HALEY ALDRICH

www.haleyaldrich.com

INTERIM REMEDIAL MEASURE WORK PLAN 2 – UNDERGROUND STORAGE TANK REMOVAL AND SOIL EXCAVATION
4001 4TH AVENUE REDEVELOPMENT SITE
NYSDEC SITE NO. C224412
4001-4011 4TH AVENUE
BROOKLYN, NEW YORK

Prepared by
H & A of New York Engineering and Geology, LLP
New York, New York

Prepared for
4 Ave Property LLC
New York, New York

File No. 0210815
November 2025

SIGNATURE PAGE

INTERIM REMEDIAL MEASURE WORK PLAN 2
UNDERGROUND STORAGE TANK REMOVAL AND SOIL EXCAVATION
4001 4TH AVENUE REDEVELOPMENT SITE
NYSDEC SITE NO. C224412
4001-4011 4TH AVENUE
BROOKLYN, NEW YORK

REVIEWED AND APPROVED BY:



Suzanne M. Bell, P.E.
Senior Associate
H & A of New York Engineering and Geology, LLP



Mari C. Conlon, P.G.
Senior Associate
H & A of New York Engineering and Geology, LLP

Certification

I, Suzanne M. Bell, certify that I am currently a New York State (NYS)-registered Professional Engineer as defined in 6NYCRR Part 375 and that this Interim Remedial Measures Work Plan was prepared in accordance with all applicable statutes and regulations and in substantial conformance with the Division of Environmental Remediation Technical Guidance for Site Investigation and Remediation (DER-10) and Green Remediation (DER-31).

I certify that all information and statements in this certification are true. I understand that a false statement made herein is punishable as a Class "A" misdemeanor, pursuant to Section 210.45 of the Penal Law.



November 4, 2025

NYS Professional Engineer No. 106301	*Date*	*Signature*

It is a violation of Article 145 of New York State Education Law for any person to alter this document in any way without the express written verification of adoption by any New York State-licensed engineer in accordance with Section 7209(2), Article 145, New York State Education Law.

Table of Contents

		Page
Certification		i
List of Tables		iii
List of Figures		iii
List of Appendices		iv
List of Acronyms		v
1.	Introduction	1
1.1	OVERVIEW	1
1.2	PURPOSE	1
2.	Background	3
2.1	SITE LOCATION AND DESCRIPTION	3
2.2	CURRENT LAND USE	3
2.3	SITE HISTORY	3
2.4	PROPOSED REDEVELOPMENT PLAN	3
2.5	SURROUNDING LAND USE	3
2.6	PREVIOUS ENVIRONMENTAL REPORTS	4
2.7	PREVIOUS REMEDIAL ACTIONS	9
3.	Interim Remedial Measure Program	10
3.1	INTERIM REMEDIAL MEASURE OBJECTIVES AND RATIONALE	10
3.2	GENERAL PROJECT INFORMATION	10
3.2.1	Remedial Engineer	10
3.2.2	Fish & Wildlife Remedial Impact Analysis	11
3.3	SUMMARY OF PROPOSED INTERIM REMEDIAL MEASURES	11
3.3.1	Site Preparation	12
3.3.2	Soil Excavation and Removal	13
3.3.3	UST Closure and Removal	20
3.3.4	Waste Management	21
3.3.5	Green and Sustainable Remediation	21
4.	Interim Remedial Performance Evaluation	23
4.1	SOIL CLEANUP OBJECTIVES	23
4.2	SOIL SAMPLING FREQUENCY	23
4.3	METHODOLOGY	23
4.4	REPORTING OF RESULTS	23
4.5	QA/QC	23
4.6	DATA VALIDATION	24
5.	Health and Safety	25

Table of Contents

		Page
5.1	HEALTH AND SAFETY PLAN	25
5.2	COMMUNITY AIR MONITORING PROGRAM	25
5.3	ODOR, DUST, AND NUISANCE CONTROL PLAN	26
5.3.1	Odor Control Plan	26
5.3.2	Dust Control Plan	26
5.3.3	Other Nuisances	27
6.	**Residual Contamination to Remain On-Site**	**28**
7.	**Reporting**	**29**
7.1	DAILY REPORTING	29
7.2	MONTHLY REPORTS	29
7.3	CONSTRUCTION COMPLETION REPORT	29
8.	**Schedule**	**31**
References		**32**

List of Tables

Table No.	Title
1	Soil Cleanup Objectives
2	Summary of Soil Quality Data
3	Summary of Water Quality Data
4	Summary of Soil Gas Quality Data

List of Figures

Figure No.	Title
1	Project Locus
2A	Partial RI Soil Analytical Data Map (VOCs)
2B	Partial RI Soil Analytical Data Map (SVOCs, Metals, Pesticides, PCBs)
3	Partial RI Groundwater Analytical Data Map
4	RI Soil Vapor Analytical Data Map
5	IRM Excavation Plan
6	Proposed Confirmation Sample Location Plan
7	Proposed Truck Route

List of Appendices

Appendix	Title
A	Previous Reports
B	Health and Safety Plan
C	Quality Assurance Project Plan
D	Excavation Work Plan
E	Resumes
F	NYSDEC Request to Import/Reuse Form
G	Environmental Footprint Analysis and Climate Screening Checklist
H	Community Air Monitoring Plan
I	Proposed Notification to I.S. 136 Charles O. Dewey Middle School

List of Acronyms

µg/L	micrograms per Liter
A	
ASP	Analytical Services Protocol
ASTM	ASTM International
AWQS	Ambient Water Quality Standards
B	
BCA	Brownfield Cleanup Agreement
BCP	Brownfield Cleanup Program
BER	Business Environmental Risk
Berninger	Berninger Environmental
bgs	below ground surface
BIC	Business Identifier Code
BTEX	benzene, toluene, ethylbenzene, xylenes
C	
C&D	construction and demolition
CAMP	Community Air Monitoring Plan
Castleton	Castleton Environmental Geologic Services DPC
CCR	Construction Completion Report
CFR	Code of Federal Regulations
CP-51	Commissioner Policy 51 – Soil Cleanup Guidance
CREC	Controlled Recognized Environmental Condition
cu yd	cubic yard(s)
CUSCO	Commercial Use Soil Cleanup Objective
D	
DER-10	Division of Environmental Remediation-10 *(specifically "May 2010 NYSDEC Technical Guidance for Site Investigation and Remediation")*
DMM	Division of Materials Management
DUSR	Data Usability Summary Report
E	
EC	Engineering Control
ECL	Environmental Conservation Law
EDD	Electronic Data Deliverable
ELAP	Environmental Laboratory Approval Program
ESA	Environmental Site Assessment

List of Acronyms (Continued)

F	
FDNY	Fire Department of the City of New York
FER	Final Engineering Report
ft	feet/foot
G	
Gal	gallon
GPR	ground-penetrating radar
H	
Haley & Aldrich of New York	H & A of New York Engineering and Geology, LLP
HASP	Health and Safety Plan
HAZWOPER	Hazardous Waste Operations and Emergency Response
HREC	Historically Recognized Environmental Concern
I	
I.S.	Intermediate School
IC	Institutional Control
IRM	Interim Remedial Measure
IRMWP	Interim Remedial Measure Work Plan
L	
LEG	Lesova Environmental Group
LNAPL	light non-aqueous phase liquid
M	
mg/kg	milligrams per kilogram
MTA	Metropolitan Transportation Authority
MTBE	methyl tert butyl ether
N	
NYCDEP	New York City Department of Environmental Protection
NYCDOB	New York City Department of Buildings
NYCDOT	New York City Department of Transportation
NYCOER	New York City Office of Environmental Remediation
NYCRR	New York Codes, Rules and Regulations
NYSDEC	New York State Department of Environmental Conservation
NYSDOH	New York State Department of Health
NYSDOT	New York State Department of Transportation

List of Acronyms (Continued)

O	
OM&M	operations, maintenance, and monitoring
OSHA	Occupational Safety and Health Administration
P	
P.E.	Professional Engineer
PBS	Petroleum Bulk Storage
PCB	polychlorinated biphenyl
PFAS	per- and polyfluoroalkyl substances
PID	photoionization detector
PPE	personal protective equipment
ppm	parts per million
PVC	polyvinyl chloride
Q	
QA/QC	Quality Assurance/Quality Control
QAPP	Quality Assurance Project Plan
R	
RAWP	Remedial Action Work Plan
RCA	Recycled Concrete Aggregate
RCRA	Resource Conservation and Recovery Act
RE	Remedial Engineer
REC	Recognized Environmental Concern
RI	Remedial Investigation
RIR	Remedial Investigation Report
RIWP	Remedial Investigation Work Plan
RRSCO	Restricted Residential Soil Cleanup Objective
RSK	RSK Environmental Group, LLC
S	
SCO	Soil Cleanup Objectives
SCL	Soil Cleanup Level
SISGR	Supplemental Investigation Soil and Groundwater Report
Site	4001 4th Avenue, Brooklyn, New York
SMP	Site Management Plan
SOE	support-of-excavation
SRIR	Supplemental Remedial Investigation Report
SSDS	Sub-Slab Depressurization System
sq ft	square feet
SVE	Soil Vapor Extraction
SVI	Soil Vapor Intrusion
SVOC	semi-volatile organic compound

List of Acronyms (Continued)

T	
TOGS 1.1.1	Technical and Operational Guidance Series 1.1.1 *(Specifically "June 1998 NYSDEC Division of Water Technical and Operational Guidance Series 1.1.1 Ambient Water Quality Standards and Guidance Values, Class GA for the protection of a source of drinking water modified per the April 2000 addendum")*
U	
USEPA	United States Environmental Protection Agency
UST	underground storage tank
UUSCOs	Unrestricted Use Soil Cleanup Objectives
V	
VEFR	vacuum-enhanced fluid recovery
VEP	vapor extraction point
VOC	Volatile Organic Compound
Volunteer	4 Ave Property LLC

1. Introduction

1.1 OVERVIEW

On behalf of 4 Ave Property LLC (the Volunteer), H & A of New York Engineering and Geology, LLP (Haley & Aldrich of New York) has prepared this Interim Remedial Measures (IRM) Work Plan (IRMWP) for the 4001 4th Avenue Redevelopment Site (New York State Department of Environmental Conservation [NYSDEC] Site No. C224412), located at 4001-4011 4th Avenue, Brooklyn, New York (Site, **Figure 1**). 4 Ave Property LLC applied to and was accepted into the NYSDEC Brownfield Cleanup Program (BCP), and a Brownfield Cleanup Agreement (BCA) was executed by the NYSDEC on October 30, 2024, with 4 Ave Property LLC. This IRMWP was prepared in accordance with applicable NYSDEC regulations and guidance, including Division of Environmental Remediation (DER)-10, which is entitled "Technical Guidance for Site Investigation and Remediation" and dated May 2010 (DER-10).

The Site, identified as Block 714, Lot 6 on the New York City Tax Map, is approximately 0.23 acres (10,018 square feet [sq ft]) and is located in the Sunset Park neighborhood of Brooklyn, New York. The Site is currently vacant and was most recently improved with a one-story structure formerly utilized as a convenience store, located in the eastern portion of the Site; an overhead canopy from the former gasoline filling station operations in the central portion of the Site; four 4,000-gallon (gal) underground storage tanks (USTs), containing gasoline/ethanol or diesel and associated fill ports, located to the southwest of the overhead canopy; and paved parking areas. The previous Site features have been demolished. The Site is bounded by 40th Street, followed by mixed-use commercial and residential buildings to the north; a commercial car wash and auto repair shop to the south, identified as the Sunset Car Care Site and site code 224244 in the State Superfund Program; residential apartment buildings to the east; and 4th Avenue, followed by the New York City Public Intermediate School (I.S.) 136 to the west. The Site location is shown on **Figure 1**.

The NYSDEC and New York State Department of Health (NYSDOH) have not yet made a significant threat determination for this Site with regard to human health and the environment.

1.2 PURPOSE

Storage and disposal of petroleum products have occurred at the Site as part of historical operations as a gasoline filling station and auto service station since at least the 1920s. The Site is registered in the NYSDEC Petroleum Bulk Storage (PBS) database with three 4,000-gal active USTs containing gasoline/ethanol, one active 4,000-gal UST containing diesel, and one closed 280-gal waste oil UST. The USTs are all listed as being installed in the mid- to late 1980s. Based on a geophysical survey and subsurface investigation field observations, an additional five USTs on the western portion of the Site appear to be abandoned-in-place. The remaining 4,000-gal USTs were to be closed-in-place under a separate IRMWP, pending site logistics, approved by NYSDEC on February 11, 2025.

Currently, one active spill case, assigned Spill No. 1811146, is associated with the Site. This spill was reported to the NYSDEC in 2019 after Castleton Environment Geologic Services DPC's (Castleton's) Phase II Environmental Site Assessment (ESA) identified several petroleum-related volatile organic compounds (VOCs) in soil above NYSDEC New York Codes, Rules, and Regulations (NYCRR) Part 375 Unrestricted Use Soil Cleanup Objectives (UUSCOs), Restricted Residential Soil Cleanup Objectives (RRSCOs), and/or Commercial Use Soil Cleanup Objectives (CUSCOs). Subsequent environmental

investigations have identified petroleum-related VOCs in soil above regulatory standards up to approximately 25 feet (ft) below ground surface (bgs).

Previous investigations conducted at the Site indicated elevated concentrations of VOCs, specifically petroleum-related VOCs, in soil and soil vapor. To date, activities completed for the Remedial Investigation (RI), completed between April 14, 2025 and July 31, 2025, include installation and sample collection from approximately 75 percent of the proposed soil borings, installation and sample collection from approximately 25 percent of the proposed groundwater monitoring wells, and 100 percent installation and sample collection of the soil vapor samples. Soil concentrations of petroleum-related VOCs, including benzene, toluene, ethylbenzene, and total xylenes (BTEX), methyl tert butyl ether (MTBE), naphthalene, n-propylbenzene, 1,3,5-trimethylbenzene, and 1,2,4-trimethylbenzene, exceed the NYSDEC NYCRR Part 375 RRSCOs. Groundwater samples were collected from two wells as part of the RI to date, which also identified elevated petroleum-related VOCs 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, benzene, ethylbenzene, MTBE, total xylenes, n-propylbenzene, and toluene above Technical and Operational Guidance Series (TOGS) 1.1.1 Ambient Water Quality Standards (AWQS).

Additionally, elevated total VOCs were identified in all soil vapor samples collected as part of the RI. Preliminary soil and soil vapor analytical results were provided to the NYSDEC Project Manager for review in the Proposed Interim Remedial Measures and Remedy Rationale Technical Memorandum prepared by Haley & Aldrich of New York, dated August 4, 2025. Groundwater results were received after submitting the technical memorandum. Available analytical results are presented in **Tables 2 through 4** and summarized in **Figures 2 through 4**. Final soil, groundwater, and soil vapor analytical results will be provided in the forthcoming Remedial Investigation Report (RIR) to be submitted after RI activities are completed.

The objectives of the IRM are to remove the four USTs and associated petroleum-impacted material (i.e., visually impacted soils, elevated photoionization detector [PID] responses). Upon removal of all accessible petroleum-impacted material, confirmation (endpoint) soil samples will be collected from the excavation to confirm that the remaining soil meets the Soil Cleanup Levels (SCLs) for Gasoline Contaminated Soils as per NYSDEC Commissioner Policy (CP)-51 Soil Cleanup Guidance. If the analytical data for soil samples collected exceed the SCLs, additional soil samples will be collected to delineate these impacts, and over-excavation may be performed to ensure that all impacted material has been removed from the Site. If over-excavation occurs, any impacted soil will be removed to the extent practical, or until the bedrock surface is encountered. Due to the location of the USTs in the southwest corner of the Site, support-of-excavation (SOE) will be installed along the western and southern boundaries abutting 4th Avenue and adjacent property building to the south.

The remaining portions of the Site and aspects of the overall Site remedy not included in this IRMWP, including additional excavation of in remainder of the Site, an in-situ groundwater remedial component (such as in-situ chemical injections), and treatment and/or containment of residual source material impacts (such as groundwater cutoff walls, soil vapor extraction [SVE], or sub-slab depressurization systems [SSDS]). These will be addressed under a forthcoming Remedial Action Work Plan (RAWP) to be submitted to NYSDEC and NYSDOH for review and approval prior to implementation of the RAWP activities.

2. Background

2.1 SITE LOCATION AND DESCRIPTION

The Site, identified as Block 714, Lot 6 on the New York City Tax Map, is approximately 0.23 acres and is located in the Sunset Park neighborhood of Brooklyn, New York. The Site is currently vacant and was most recently used as a gasoline filling station. The Project Locus is shown on **Figure 1**.

The Site is in a residential R7A zoning district with a commercial C2-4 overlay. Properties immediately surrounding the Site are zoned as the following: R7A residential with C2-4 commercial overlays for the north- and south-adjacent properties; R1-2 residential for the east-adjacent property; and C8-2 commercial/OP special purpose district (Ocean Parkway) for the west-adjacent property, across Coney Island Avenue. The Site is located within an urban area characterized by low-/mid-rising commercial and multi-family residential buildings. The proposed development is a school, which is consistent with current zoning.

2.2 CURRENT LAND USE

The Site is currently vacant and was most recently improved with a one-story structure formerly utilized as a convenience store, located in the eastern portion of the Site; an overhead canopy from the former gasoline filling station operations in the central portion of the Site; four 4,000-gal USTs, containing gasoline/ethanol or diesel and associated fill ports, located to the southwest of the overhead canopy; and paved parking areas. The previous Site features have been demolished, and the former retail petroleum station operations ceased in December 2024.

2.3 SITE HISTORY

Based on the findings of the March 2024 Phase I ESA prepared by Lesova Environmental Group (LEG), the Site was comprised of one tax lot developed with a one-story concrete structure and a gasoline filling/auto service station with one UST circa 1926 and a second lot which was vacant. The 1942 Sanborn map depicted the Site merged as one lot with previous use similar to the 1926 map, with a garage to the south of the lot. The Site was operated as an automotive service station, including lubrication and minor repair services, with office use and a parking area until at least August 1965. The configuration of the Site changed and was identified with a cement brick one-story structure with a gasoline filling station circa 1970. A historical City Directory search indicated that the Site was operated as a gasoline filling station circa 1928, as an auto service station circa 1940 to 2000, and as a gasoline filling station again circa 2010 to 2024.

2.4 PROPOSED REDEVELOPMENT PLAN

Redevelopment design is still in preliminary stages; however, the Site is proposed to be redeveloped as a school with a partial cellar extending to approximately 25 ft bgs.

2.5 SURROUNDING LAND USE

The Site is located within an urban area of the Sunset Park neighborhood of Brooklyn, New York, characterized by low-rise commercial buildings, multi-story mixed-use commercial and residential buildings, and one- and two-family homes. The Site is bounded by 40th Street, followed by mixed-use

commercial and residential buildings to the north; a commercial car wash and auto repair shop to the south, identified as the Sunset Car Care Site and site code 224244 in the State Superfund Program; residential apartment buildings to the east; and 4th Avenue, followed by the New York City Public I.S. 136 to the west. The Metropolitan Transportation Authority (MTA) underground "N, R" train line runs underneath 4th Avenue to the west of the Site.

Sensitive receptors within a 500-ft radius of the Site include New York City Public I.S. 136, located west of the Site beyond 4th Avenue; Family Day Care Graciela's Little Angels, located approximately 250 ft to the south of the Site; and Sunset Park Group Family Daycare, located approximately 475 ft to the west of the Site. A proposed notification to I.S. 136 is included as **Appendix I.**

Properties immediately surrounding the Site are zoned as the following: R7A residential with C2-4 commercial overlays for the north- and southwest-adjacent properties; R6B residential for the east, south, and southeast-adjacent properties; and R6B/R7A residential with a C2-4 commercial overlay for the northwest-adjacent property, across 4th Avenue.

2.6 PREVIOUS ENVIRONMENTAL REPORTS

To date, the following previous investigations and reports have been prepared for the Site:

- January 25, 2019, Phase II ESA, prepared by Castleton;
- June 17, 2020, Supplemental Remedial Investigation Report (SRIR), prepared by Berninger Environmental (Berninger);
- October 8, 2021, Supplemental Investigation Soil and Groundwater Report (SISGR), prepared by Berninger;
- February 27, 2024, Monitoring Report, prepared by Berninger;
- March 12, 2024, Phase I ESA, prepared by LEG; and
- April 3, 2024, Phase II Work Plan, prepared by RSK Environmental Group, LLC (RSK).

Investigation findings are included in **Appendix A**. A summary of the environmental findings of these investigations is provided below.

January 2019 Phase II ESA Prepared by Castleton

A Phase II ESA report dated January 25, 2019, prepared by Castleton, was available for review. Castleton conducted the Phase II ESA to evaluate the findings of a Phase I ESA dated January 7, 2019, prepared by Merritt Environmental Consulting Corp. (unavailable for review), with the goal of evaluating the impact of historical and current use of the Site as a gasoline filling station on subsurface conditions. The scope of work included a geophysical investigation using ground-penetrating radar (GPR) to search for subsurface anomalies indicative of USTs and to clear underground utilities and conduct soil sampling to characterize the Site soil and evaluate impacts pertaining to gasoline filling station operations.

The GPR survey indicated there were a total of nine suspected former USTs at the Site; four of which were located beneath the canopy between the dispensers and five were noted in the western portion of the Site. Currently, there are four 4,000-gal active USTs, which consist of three gasoline USTs and one

diesel UST on the Site registered under PBS ID No. 2-349399 with a registration expiration date of September 8, 2028.

Six soil borings were advanced in the potential areas of USTs identified during the GPR survey. Petroleum-related VOCs exceeding the RRSCOs were identified in three of six soil samples, all located in the southwestern portion of the Site. Elevated VOCs included:

- 1,2,4-trimethylbenzene (maximum concentration 1,200 milligrams per kilogram [mg/kg]);
- 1,3,5-trimethylbenzene (maximum concentration 860 mg/kg);
- benzene (maximum concentration 20 mg/kg);
- ethyl benzene (maximum concentration 1,100 mg/kg);
- n-propylbenzene (maximum concentration 170 mg/kg);
- toluene (maximum concentration 1,500 mg/kg); and
- total xylenes (maximum concentration 2,300 mg/kg).

Based on these findings, a spill was reported on February 5, 2019, and Spill No. 1811146 was assigned to the Site.

June 2020 SRIR Prepared by Berninger

An SRIR, dated June 25, 2020, and prepared by Berninger, was available for review. Berninger performed supplemental investigation work in April 2020 to vertically delineate the contamination discovered at previous sample locations advanced by Castleton and to attempt to locate the groundwater interface. In addition, Berninger installed test pits in the suspected UST areas to confirm the results of the 2019 GPR survey.

Berninger installed five test pits in the areas of the suspected USTs (B-1, B-2, B-3, B-6, and B-7), two soil borings at former locations from Phase II ESA (B-4, at former location SB-06, and B-5, between former locations SB-04 and SB-05), and one downgradient soil boring (B-8). While advancing the borings in the suspected UST area, consistent refusal was encountered at 2.5 ft at all the test pit locations, potentially indicating the tanks were abandoned-in-place.

Boring B-4 was installed to 30 ft bgs until refusal was encountered. PID readings from 15 to 25 ft bgs averaged approximately 4,500 parts per million (ppm) and decreased at 30 ft bgs to 190 ppm. A soil sample was collected at 27.5 to 30 ft bgs and analyzed for VOCs. BTEX were identified above the UUSCOs, but not exceeding the RRSCOs. B-5 was installed to 32.5 ft bgs until refusal was encountered. A soil sample was collected at 30 to 32.5 ft bgs and analyzed for VOCs; VOCs were not detected above the UUSCOs.

Boring B-8 was installed downgradient of B-4 and B-5 to 34 ft bgs until refusal was encountered. PID readings from 10 to 20 ft bgs ranged from 1,500 to 2,500 ppm and decreased to 25 ppm at 34 ft bgs.

Groundwater was not encountered during this investigation, and Berninger assumed the groundwater interface to be approximately 50 ft bgs or more.

Berninger concluded that the results of the supplemental investigation indicated the need for remedial actions in soils, specifically in the 10- to 25-ft bgs interval.

October 2021 SISGR Prepared by Berninger

An SISGR, prepared by Berninger and dated October 2021, was available for review. The supplemental investigation aimed to analyze groundwater conditions in the area of highest soil contamination levels at boring location B-4, in the western portion of the Site, as reported in the June 2020 SRIR. On June 10, 2021, a monitoring well (MW-1) was installed near B-4 to 50 ft bgs using an air-rotary drill rig. MW-1 was constructed with a 2-inch-diameter polyvinyl chloride (PVC) riser and screened from 25 to 50 ft bgs with a 0.02-inch slotted screen. Saturated soil from the borehole was reportedly observed from 30 to 40 ft bgs, but was dry from 40 to 65 ft bgs.

MW-1 was developed after installation and sampled for the analysis of VOCs. Multiple VOCs were detected above the TOGS 1.1.1 AWQS, including:

- 1,2,4,5-trimethylbenzene (39 micrograms per liter [µg/L]);
- 1,2,4-trimethylbenzene (790 µg/L);
- 1,2, dibromoethane (7 µg/L);
- 1,2-dichloroethane (2 µg/L);
- 1,2-dichloropropane (3 µg/L);
- 1,3,5-trimethylbenzene (240 µg/L);
- acetone (110 µg/L);
- benzene (12,000 µg/L);
- chloroform (34 µg/L);
- ethylbenzene (1,100 µg/L);
- isopropylbenzene (58 µg/L);
- m,p-xylene (4,100 µg/L);
- methyl tert-butyl ether (170 µg/L);
- methylene chloride (11 µg/L);
- n-propylbenzene (120 µg/L);
- naphthalene (160 µg/L);
- o-xylene (12,000 µg/L);
- sec-butylbenzene (11 µg/L);
- toluene (21,000 µg/L); and
- trans-1,3-dichloropropene (1 µg/L).

At this location, soil was logged to 65 ft bgs. Berninger reported that soil mainly consisted of semi-tight, brown, silty sand, with a perched water layer observed at approximately 30 ft bgs, followed by clayey soils at 30 to 35 ft bgs, silty sands from 35 to 50 ft bgs, and silty loam at 50 to 65 ft bgs. The highest PID

readings were reported from 30 to 32.5 ft bgs, reaching 1,000 ppm, and steadily decreasing until reaching 0.0 ppm from 50 to 65 ft bgs. A soil sample was collected from 45 to 50 ft bgs and analyzed for VOCs. Analytical results did not indicate VOCs detected above the UUSCOs.

February 2024 Monitoring Report Prepared by Berninger

A spill monitoring report prepared by Berninger dated February 27, 2024, was available for review. Berninger performed monthly monitoring activities of MW-1 between December 2023 and February 2024 associated with Spill No. 1811146. This consisted of measuring depth to groundwater and monitoring the presence of free-phase product. As part of the scope of work, Berninger bailed product as necessary and checked the Site for any spills from the pump island, tanks, or drains.

Product was recovered via vacuum-enhanced fluid recovery (VEFR) using a pump truck in December 2023 and using bailers in January and February 2024. Berninger reported a recharge rate of 1 to 1.5 gal per 30 minutes, but noted that the recharge rates varied between events, which impacted the volume of product/water mixture recovered each month.

For the three months included in this monitoring report (December 2023 through February 2024), Berninger reported the following measurements:

Date	Depth To Water (ft bgs)	Depth To Product (ft bgs)	Product Thickness (ft)	VEFR Total Volume Purged (gallons)
December 28, 2023	21.37	20.87	0.5	23
January 15, 2024	24.10	22.80	1.3	15
February 27, 2024	33.4	21.08	12	5

March 2024 Phase I ESA Prepared by LEG

A Phase I ESA report dated March 12, 2024, was prepared by LEG in accordance with ASTM International (ASTM) E1527-13 and E1527-21 Standards and was available for review. This Phase I ESA was completed to identify and evaluate the presence of Recognized Environmental Conditions (RECs), Historically Recognized Environmental Conditions (HRECs), Controlled Recognized Environmental Conditions (CRECs), Business Environmental Risks (BERs), and *de minimis* conditions associated with the Site.

According to Sanborn maps reviewed during the Phase I ESA, the Site was developed with a one-story concrete structure and a gasoline filling/auto service station with one gasoline tank circa 1926, and the configuration of the Site had changed and was identified with a cement-brick one-story structure with a gasoline filling station circa 1970. A historical City Directory search indicated that circa 1928, the Site was used as a gasoline filling station, circa 1940 to 2000 as an auto service station, and circa 2010 to 2024 again as a gasoline filling station. LEG identified four 4,000-gal active USTs on the lot consistent with PBS records (PBS No. 2-349399). During the Phase I ESA reconnaissance, the Site was operating as an active BP gasoline filling station with a convenience store. LEG identified the following RECs, BERs, and *de minimis* conditions for the Site:

RECs

- Information obtained from multiple historical sources revealed that the Site and multiple adjacent/surrounding properties were historically utilized as gasoline filling stations, auto repair

centers, or car washes. Previous environmental subsurface investigations have also indicated impacted subsurface conditions due to the historical uses of the Site, as well as the adjacent/surrounding properties. Thus, LEG considers the historical use of the subject property and adjacent properties to be a REC.

- During the review of the 1926 Sanborn maps, a gasoline UST was identified in the northern portion of the Site. Since the status of the UST is unknown due to the lack of documentation, LEG considers this a REC.
- A geophysical investigation conducted by Castleton identified nine suspected USTs in the western section of the Site. This study is supported by previous environmental investigations that indicated impacts to soil, soil vapor, and groundwater. As no documentation regarding the status of these suspected tanks and/or soil conditions in their vicinity was available for review, there is a potential for spills or releases from these tanks to have impacted the subsurface. Therefore, LEG considers the suspected USTs a REC.
- One open spill (Spill No. 18-11146) is recorded on the Site. This spill was recorded as a result of VOCs being detected above Soil Cleanup Objectives (SCOs) in soil during the Phase II ESA conducted by Castleton. Since the subject property was not remediated and the spill is not closed, LEG considers this a REC.
- A spill was recorded on the adjacent property identified to the southwest as Sunset Car Care along 4th Avenue, and an NYSDEC Memo suggests that no delineation or remediation was conducted; however, the spill was closed due to a lack of response from the owner. This indicated that the contamination is left in-place and LEG considers this a REC.

BERs

- A metallic anomaly non-indicative of a UST was identified in the northern portion of the Site during Castleton's geophysical investigation. Given the historical use of the Site as an auto service station with a loading area, the anomaly can possibly be a buried hydraulic lift, and LEG considers this a BER.
- The central and northwestern portions of the Site were previously developed with a service station; therefore, there is a potential for fill materials to be present. As no information regarding the nature or source of the fill materials was available for review, there is a potential for contaminated and/or structurally unsuitable fill materials to be present beneath the subject property. LEG considers the potential presence of fill materials as a BER.
- Minor water staining was observed on the ceiling of the one-story building. No active water leaks or visible mold growth were observed within the convenience store. The water-damaged areas identified should be removed from the building and properly disposed. LEG considers this a BER.

De Minimis Condition

- Solid wastes and recyclables generated on the property are stored in three dumpsters identified on the southwest of the Site. The garbage disposal service was provided by Mr. T Carting (Business Identifier Code [BIC] No. 173). No evidence of staining or liquid waste was observed around the dumpsters. Two drums were also identified near these dumpsters, one of which was damaged and needs to be disposed of legally from the Site.

April 2024 Phase II Work Plan Prepared by RSK

A Phase II Work Plan dated April 3, 2024, was prepared for the Site by RSK and was available for review. The Phase II Work Plan was drafted in response to the findings of the March 2024 Phase I ESA performed by LEG and was designed to conform with New York City Office of Environmental Remediation (NYCOER) requirements, but was never enacted at the Site. Soil, groundwater, and soil vapor sampling locations were proposed throughout the Site to provide a characterization of Site-wide conditions. The Phase II Work Plan also included summaries of previous environmental reports that included monthly groundwater monitoring reports prepared by Berninger from February 2023 through February 2024. A table was included in the summary of the monthly groundwater monitoring reports listing the observed depth to water, depth to product, product thickness, and amount of product recovered via VEFR or bailers.

2.7 PREVIOUS REMEDIAL ACTIONS

A previous IRM, overseen by Haley & Aldrich of New York, is currently partially complete at the Site in accordance with an NYSDEC-approved IRMWP, dated February 6, 2025. Site work was implemented from February to March 2025 and is planned to be continued at a future date. The IRM activities completed to date included:

- Demolition of structures associated with the former retail petroleum operations located within the IRM work area, including, but not limited to, piping, canopies, and service shop/storage areas. Demolition was limited to above-grade structures being removed to grade level;
- Well gauging and light non-aqueous phase liquid (LNAPL) recovery from on-Site groundwater monitoring well MW-1; and,
- Submission of daily reports during the IRM Site activities to document the progress of the IRM to the NYSDEC.

LNAPL recovery was completed via manual bailing, as opposed to VEFR of LNAPL as proposed in the February 2025 IRMWP, due to minimal LNAPL observed in MW-1. Measurable product was not recovered from the MW-1 during this effort. As well construction details were not known for MW-1, a recovery well (RW-1) was installed approximately 5 ft to the north. RW-1 was installed on March 24, 2025, to 45 ft and screened from 20 to 45 ft bgs as per approval from NYSDEC provided on March 18, 2025. Gauging continued at MW-1 and RW-1 on a weekly basis. Due to the lack of measurable product at the Site and minimal product recovery to date, well gauging and product recovery were discontinued with approval from NYSDEC on April 1, 2025.

Incomplete activities from this IRM include decommissioning and closure in-place of the four 4,000-gal USTs associated with the former gasoline filling station and/or associated appurtenances (e.g., fill lines, vent line, and electrical conduit); decommissioning of MW-1 in accordance with NYSDEC CP-43 policy at the completion of the IRM; and submission of a Construction Completion Report (CCR) at the completion of the IRM.

The incomplete activities, as noted above, will be completed in this IRMWP. Of note, the USTs will be closed and removed as part of the proposed work in this IRMWP instead of being closed-in-place. All work associated with the initial IRM and this subsequent IRM will be documented in one forthcoming CCR.

3. Interim Remedial Measure Program

3.1 INTERIM REMEDIAL MEASURE OBJECTIVES AND RATIONALE

The objective of this IRM is to facilitate the removal of four 4,000-gal USTs and associated impacted soils.

IRM activities will require equipment mobilization, cleaning, and removal of residual UST contents, removal of USTs and/or associated appurtenances, concrete pavement removal in the area of excavation, SOE installation to the west and south of the tank area, excavation and off-Site disposal of historic fill and hydrocarbon contaminated soil, and collection of confirmation samples. After removal of the USTs, the area will be backfilled with a 6-inch-thick temporary cover of NYSDEC-approved certified clean fill and/or gravel. The temporary cover may potentially be replaced with a DER-10-compliant final cover as part of the forthcoming final remedy. The Site will be locked and inaccessible to the public during IRM implementation and will remain locked and inaccessible until RAWP implementation is complete, and a DER-10 compliant final cover is installed. The forthcoming RAWP will be submitted to and approved by the NYSDEC prior to implementation.

3.2 GENERAL PROJECT INFORMATION

3.2.1 Remedial Engineer

The Remedial Engineer (RE) will review plans and submittals for this IRM, including contractor and subcontractor document submittals, and will confirm that plans and submittals are in compliance with this IRMWP. Remedial documents, including contractor and subcontractor document submittals, will be submitted to the NYSDEC and NYSDOH in a timely manner and prior to the start of work associated with the IRM.

The RE for this project will be Suzanne M. Bell. The RE is a registered professional engineer (P.E.) licensed by the State of New York. The RE will have primary direct responsibility for the implementation of the IRM at the Site. The RE will certify in the CCR that the IRM activities were observed by qualified environmental professionals under her supervision and that the remediation requirements set forth in this IRMWP and other relevant provisions of Environmental Conservation Law (ECL) 27-1419 have been achieved in substantial conformance with this IRMWP. Any deviations from this IRMWP will be discussed with the NYSDEC and described in monthly reporting and the CCR.

Under the direction of the RE, the work of other contractors and subcontractors involved in aspects of the IRM will be documented, including soil excavation, stockpiling, confirmation sample collection, air monitoring, emergency spill response services, import of backfill, closure and removal of the USTs, well decommissioning, and management of waste transport and disposal.

The RE will review the pre-remedial plans submitted by contractors and subcontractors for substantial conformance with this IRMWP and will certify that the work was performed in accordance with this IRMWP.

3.2.2 Fish & Wildlife Remedial Impact Analysis

NYSDEC DER-10 requires an on-Site and off-Site Fish and Wildlife Resource Impact Analysis if the stipulated criteria are met. Based on the requirements stipulated in Section 3.10 and the decision key in Appendix 3C of DER-10, there was no need to prepare a Fish and Wildlife Resource Impact Analysis for the Site. This is due to the fact that while the site is a concern for a discharge event (item 1 of the Decision Key), the contamination at the Site is not a threat to the fish and wildlife resources (item 13 of the Decision Key) as listed in Appendix 3C. Therefore as per Item 14 of the Decision Key, no FWRIA is required.

The Site, which was developed by the 1920s and most recently operated as a gasoline filling station with an associated convenience store and parking, is located in the Sunset Park neighborhood of Brooklyn, New York. The Site provides little or no wildlife habitat or food value and/or access to the detected subsurface contamination. No natural waterways are present on or directly adjacent to the Site. The proposed future use of the Site is as a school.

3.3 SUMMARY OF PROPOSED INTERIM REMEDIAL MEASURES

The proposed IRM activities are as follows:

1. Implementation of soil erosion, pollution, and sediment control measures in compliance with applicable laws and regulations.
2. Remediation/disposal of petroleum-impacted pavement and footings and removal of concrete pavement within the IRM work area.
3. Design and installation of SOE consisting of, at a minimum, sloping and/or benching as per the New York City Department of Buildings' (NYCDOB) Code along the northern and eastern UST area perimeter. Sloping of the excavation sides will be at a slope of approximately 2 horizontal to 1 vertical. If necessary, additional SOE elements may be used to reach the desired depth to the west and south of the UST area due to the proximity of the tank field to 4th Avenue and the southern adjacent property building.
4. Excavation, stockpiling, off-Site transport, and disposal of approximately 1,600 cubic yards (cu yd) of historic fill, petroleum-impacted soil, and native soil that exceeds CP-51 SCLs for Gasoline Contaminated Soil from the area of removed USTs and related equipment. Excavation is anticipated to extend to 12 ft bgs in the IRM area.
5. Screening for indications of contamination (by visual means, odor, and monitoring with PIDs) and collection of confirmation samples.
6. Although not anticipated, localized dewatering (as needed), characterization, and treatment of water accumulated in excavations prior to discharge to an NYSDEC-approved sewer/sanitary line (pending permits), or localized dewatering with containerization, classification, and disposal at an approved receiving facility.
7. Removal of residual contents of USTs and cleaning of the interior of USTs, completed by a qualified contractor. Removal of USTs and/or associated appurtenances (e.g., fill lines, vent line, and electrical conduit) and decommissioning and off-Site disposal during redevelopment in accordance with DER-10, 6 NYCRR Part 613.9, NYSDEC CP-51, and other applicable NYSDEC UST closure requirements. Removal of any petroleum-impacted soils associated with the USTs.

8. Installation of a demarcation barrier, such as orange snow fencing, along the excavation sidewalls and excavation bottom prior to backfilling. The excavation area will be backfilled with imported material that will be sampled at a frequency consistent with the recommendations of Table 5.4(e)10 in DER-10 in order to confirm CP-51 SCLs are achieved prior to placing backfill. Backfill source material will be proposed to NYSDEC prior to import to the Site.
9. Submission of daily reports to document the progress of the IRM to NYSDEC.
10. Submission of a CCR at the completion of the IRM.

3.3.1 Site Preparation

3.3.1.1 Mobilization

Prior to commencing remedial construction, the Remediation Contractor will mobilize necessary remediation personnel, equipment, and materials to the Site and prepare for remedial activities. Mobilization and Site preparation activities may include identifying the location of aboveground and underground utilities (e.g., power, gas, water, sewer, and telephone), equipment, and structures as necessary to implement the remediation work.

3.3.1.2 Site Fencing

The Site will be secured by locked entrances and inaccessible to the public during IRMWP implementation and will remain locked and inaccessible to the public until the IRMWP implementation is complete. All work conducted in accordance with this IRMWP will be conducted in compliance with the Site-specific Health and Safety Plan (HASP), included as **Appendix B**, and the Quality Assurance Project Plan (QAPP), included as **Appendix C**.

The Site will be secured with a construction fence along the northern, eastern, southern, and western Site perimeter. The gates located on 4th Avenue and/or 40th Street will be barricaded during work hours, with securely locked doors during off-hours, with appropriate signage maintained by the Contractor. No unauthorized personnel will be able to access the Site.

3.3.1.3 Monitoring Well Decommissioning

Monitoring wells within the IRM area will be decommissioned in accordance with NYSDEC CP-43 by an experienced driller with oversight from Haley & Aldrich of New York. Decommissioning documentation will be provided in the CCR.

3.3.1.4 Temporary Stabilized Construction Entrances

Temporary stabilized construction entrances will be installed at the existing curb cuts along 4th Avenue and/or 40th Street. The entrances will be covered with NYSDEC-approved gravel or recycled concrete aggregate (RCA) and graded so that runoff water will be directed on the Site. Vehicles exiting construction areas will be cleaned using clean water or dry brushing, as needed, to remove Site soil from the tires and undercarriages. The Contractor will protect and maintain the existing sidewalks and roadways at all Site access points.

3.3.1.5 Utility Mark-out and Easements Layout

4 Ave Property LLC and its contractors are solely responsible for the identification of utilities and/or easements that might be affected by work under this IRMWP and implementation of the required, appropriate, or necessary health and safety measures during performance of the work under this IRMWP. 4 Ave Property LLC and its contractors are solely responsible for the safe execution of the work performed under this IRMWP. 4 Ave Property LLC and its contractors must obtain the necessary local, state, and/or federal permits or approvals that may be required to perform the work detailed in this IRMWP. Approval of this IRMWP by the NYSDEC does not constitute satisfaction of these requirements.

3.3.1.6 Erosion and Sediment Controls

Since the planned earthwork activities will be below the adjacent sidewalk grade, full-time erosion and sedimentation measures are not anticipated. Best management practices for soil erosion will be implemented to minimize erosion and sedimentation off the Site.

3.3.1.7 Excavation Support

To accommodate the removal of soil to a depth of approximately 12 ft bgs within the IRM area, an SOE system beyond sloping will be required along the western and southern Site boundary. The SOE elements will be designed and installed as per the NYCDOB Code. Excavations are anticipated to be completed above the water table throughout the IRM area.

Appropriate management of the structural stability of on-Site or off-Site structures during Site activities is the sole responsibility of 4 Ave Property LLC and its Contractors. 4 Ave Property LLC and its Contractors are solely responsible for the safe execution of the work performed under this IRMWP. 4 Ave Property LLC and its Contractors must obtain the necessary local, state, and/or federal permits or approvals that may be required to perform the work detailed in this IRMWP. Additionally, 4 Ave Property LLC and its Contractors are solely responsible for the implementation of the required, appropriate, or necessary health and safety measures during the performance of work conducted under this IRMWP.

3.3.2 Soil Excavation and Removal

To facilitate the UST removal, soil excavation and disposal of historic fill, petroleum-impacted soil, and native soil that exceeds CP-51 SCLs for Gasoline Contaminated Soil will be required. The excavation plan is shown on **Figure 5**. The estimated volume of material requiring removal and off-site disposal during the IRM is approximately 1,600 cu yd. The soil will be screened for visual, olfactory, and instrumental evidence of environmental impacts. Due to depth to groundwater at approximately 44 ft bgs, dewatering is not anticipated. Excavation will be performed in accordance with the Excavation Work Plan included in **Appendix D**.

3.3.2.1 Waste Characterization

Waste characterization will be performed for off-Site disposal in a manner suitable to the receiving facility and in conformance with applicable permits. Sampling and analytical methods, sampling frequency, analytical results, and Quality Assurance/Quality Control (QA/QC) results will be reported. Data available for excavated material to be disposed of at a given facility will be submitted to the disposal facility with a suitable explanation prior to shipment and receipt.

Hazardous soil, if present, will be managed in accordance with applicable federal, state, and local regulations. As such, the handling, transport, and disposal of hazardous fill material is subject to United States Environmental Protection Agency (USEPA) and Occupational Safety and Health Administration (OSHA) Hazardous Waste Operations and Emergency Response (HAZWOPER) regulations. The excavated material will be segregated in the field and temporarily placed in stockpiles or direct-loaded and transported by Part 364-permitted trucks to a facility permitted by the Resource Conservation and Recovery Act (RCRA) to accept hazardous waste.

3.3.2.2 Soil Screening Methods

Visual, olfactory, and instrumental soil screening and assessment will be performed during remediation and development-related ground-intrusive activities into known or potentially contaminated material. Soil screening will be performed regardless of when the invasive work is done and will include excavation and invasive work performed during the IRM and development, such as excavations for foundations and utility work.

All primary contaminant sources (including but not limited to tanks and hot spots) identified during Site Characterization and the RI sampling completed to date will be surveyed by a surveyor licensed to practice in the state of New York. This information will be provided on maps in the CCR. Screening will be performed by qualified environmental professionals or personnel under the supervision of the RE. Resumes are provided in **Appendix E** for personnel responsible for field screening (i.e., those representing the RE) of invasive work for unknown contaminant sources during remediation and development work.

3.3.2.3 Stockpiles

While direct loading of petroleum contaminated soils will be prioritized over staging on-Site, stockpiles will be used as necessary to separate and stage excavated material pending loading or characterization sampling. Separate stockpile areas will be constructed to avoid commingling materials. Stockpile areas will meet the following minimum requirements:

- Excavated soil will be placed onto a minimum thickness of 6-mil low-permeability liner of sufficient strength and thickness to prevent puncture during use; separate stockpiles will be created where material types are different. The use of multiple layers of thinner liners is permissible.
- Efforts will be made to place and remove the soil to minimize the potential to jeopardize the integrity of the liner.
- Stockpiles will be covered at the designated times (see below) with a minimum 6-mil plastic sheeting or tarps, which will be securely anchored to the ground. Stockpiles will be routinely inspected, and broken sheeting covers will be promptly replaced.
- Stockpiles will be covered upon reaching their capacity (approximately 1,000 cu yd) until ready for loading. Stockpiles that have not reached their capacity will be covered at the end of each workday.
- Each stockpile will be encircled with silt fences and hay bales, as needed, to contain and filter particulates from rainwater that has drained off the soils and to mitigate the potential for surface water run-off.

- Stockpiles will be inspected at a minimum of once daily and after every storm event.
- If hazardous material is encountered, stockpiling on the Site will be avoided to the extent possible, in favor of live-loading into trucks permitted to transport hazardous waste.
- Stockpiled material will be appropriately graded to control run-off and will be located at least 50 feet from the property boundaries where possible.

3.3.2.4 Materials Excavation and Load Out

The RE or a qualified environmental professional under their supervision will monitor all ground-intrusive work and the excavation and load-out of excavated material. Odor suppressant will be applied during excavation and is further detailed in Section 5.3.1.

Loaded vehicles leaving the Site will be appropriately lined, securely covered, manifested, and placarded in accordance with the appropriate federal, state, and local requirements, including applicable transportation requirements (i.e., New York State Department of Transportation [NYSDOT] and New York City Department of Transportation [NYCDOT] requirements). Trucks hauling historical fill material will not be lined unless free liquids are present or the material is grossly impacted. Hazardous wastes derived from the Site will be stored, transported, and disposed of in compliance with applicable local, state, and federal regulations.

An outbound-truck inspection and wash station will be operated on the Site. Trucks will be washed, as necessary, before leaving the Site, and Site ingress and egress points will be cleaned of dirt and other materials to prevent material generated during remediation and development from being tracked off the Site. The truck inspection and wash station will be graded toward the interior of the site as detailed in Section 3.3.1.4.

The Volunteer and its contractors are solely responsible for the safe performance of all invasive and other work performed under this IRMWP and for the structural integrity of excavations and structures that may be affected by excavations (such as building foundations and bridge footings).

The Volunteers and associated parties will ensure that Site development activities will not interfere with, or otherwise impair or compromise, remedial activities proposed in this IRMWP. Development-related grading cuts and fills will not be performed without NYSDEC approval and will not interfere with, or otherwise impair or compromise, the performance of remediation required by this IRMWP. Mechanical processing of historical fill and contaminated soil on the Site is prohibited unless otherwise approved by NYSDEC.

Primary contaminant sources (including, but not limited to, tanks and hot spots) identified during Site characterization, the RI, and implementation of the IRM will be surveyed by a surveyor licensed to practice in the state of New York. The excavation will be surveyed, and survey information will be shown on maps to be included with the CCR.

3.3.2.5 Materials Transport Off-Site

Transport of materials will be performed by licensed haulers in accordance with appropriate local, state, and federal regulations, including 6 NYCRR Part 364. Haulers will be appropriately licensed, and trucks

properly placarded. Trucks heading to disposal facilities will travel northeast on 4th Avenue, southeast on 40th Street, southwest on 5th Avenue, northwest on 41st Street, southwest on 3rd Avenue, then south on the I-278/3rd Avenue ramp to 4th Avenue/Brooklyn Queens Expressway/Verrazzano Bridge, and then south onto I-278 West (or other NYSDEC-approved routes). Truck routes are shown on **Figure 7**.

Loaded trucks will exit in the vicinity of the Site using approved truck routes. These routes are the most appropriate routes to and from the Site and take into account the following:

- Limiting transport through residential areas and past sensitive Sites;
- Use of city-mapped truck routes;
- Prohibiting off-Site queuing of trucks entering the facility;
- Limiting total distance to major highways;
- Promoting safety in access to highways;
- Overall safety in transport; and,
- Community input (where necessary).

Trucks will be prohibited from excessive stopping and idling in the neighborhood outside of the Site. Egress points for truck and equipment transport from the Site will be kept clean of dirt and other materials during Site remediation and development. Queuing of trucks will be performed on the Site in order to minimize off-Site disturbance. Off-Site queuing will be prohibited. Material transported by trucks exiting the Site will be secured with tight-fitting covers. Loose-fitting canvas-type truck covers will be prohibited. If loads contain wet material capable of producing free liquid or hazardous metals-impacted material, truck liners will be used. Trucks will be washed as necessary prior to leaving the Site. Truck wash waters will be collected and disposed of off the Site in an appropriate manner. The truck inspection and wash station will be graded toward the interior of the site as detailed in Section 3.3.1.4.

3.3.2.6 Materials Disposal Off-Site

Disposal location(s) will be established at a later date and will be reported to the NYSDEC Project Manager. The total quantity of material expected to be disposed of off the Site is up to approximately 1,600 cu yd.

All soil/fill/solid waste excavated and removed from the Site will be treated as contaminated and regulated material and will be disposed of in accordance with all local, state (including 6 NYCRR Part 360), and federal regulations. If disposal of soil/fill from this Site is proposed for unregulated disposal (i.e., clean soil removed for development purposes), a formal request with an associated plan will be made to NYSDEC's Project Manager. Unregulated off-Site management of materials from this Site is prohibited without formal NYSDEC approval.

Excavated material that does not meet CP-51 SCLs for Gasoline Contaminated Soil, such as non-hazardous historical fill material, contaminated soil, and hazardous lead-impacted material, is prohibited from being taken to a New York State recycling facility (6 NYCRR Part 360.15 Registration Facility).

If hazardous soil is identified, it will be managed in accordance with applicable federal, state, and local regulations. As such, the handling, transport, and disposal of hazardous fill material is subject to USEPA

and OSHA HAZWOPER regulations. The presence of hazardous waste requires compliance with both federal and state regulations and the following requirements:

1. Hazardous waste disposal requires obtaining a USEPA RCRA generator ID number;
2. Hazardous waste must be transported to a facility permitted by the RCRA to accept hazardous waste;
3. Hazardous waste must be segregated and cannot be commingled with other Site material; and,
4. Hazardous waste must be transported and disposed of by properly permitted (Part 364) transporters and facilities.

The following documentation will be obtained and reported by the RE for each disposal location used in this project to fully demonstrate and document that the disposal of material derived from the Site conforms with all applicable laws.

- A letter from the RE or 4 Ave Property LLC to the receiving facility describing the material to be disposed of and requesting formal written acceptance of the material. This letter will state that the material to be disposed of is contaminated material generated at an environmental remediation Site in New York State. The letter will provide the project identity and the name and phone number of the RE. The letter will include, as an attachment, a summary of all chemical data for the material being transported (including Site Characterization data).
- A letter from each receiving facility stating it is in receipt of the correspondence (above) and is approved to accept the material.

These documents will be included in the CCR.

Non-hazardous historic fill and contaminated soils taken off the Site will be handled, at a minimum, as a Municipal Solid Waste per 6 NYCRR Part 360.2. The RE is responsible for assuring material is properly characterized and determining the appropriate disposal methods based on the characterization results.

Historical fill and contaminated soils from the Site are prohibited from being disposed of at Part 360.15 Registration Facilities (also known as Soil Recycling Facilities).

Soils that are contaminated but non-hazardous and are being removed from the Site are considered by the Division of Materials Management (DMM) in NYSDEC to be Construction and Demolition (C&D) materials with contamination not typical of virgin soils. These soils may be sent to a permitted Part 360 landfill. They may be sent to a permitted C&D processing facility without permit modifications only upon prior notification of NYSDEC Region 2 DMM. This material is prohibited from being sent or redirected to a Part 360-15 Registration Facility. In this case, as dictated by DMM, special procedures will include, at a minimum, a letter to the C&D facility that provides a detailed explanation that the material is derived from a DER remediation Site, that the soil material is contaminated, and that it must not be redirected to an off-Site Soil Recycling Facility. The letter will provide the project identity and the name and phone number of the RE. The letter will include, as an attachment, a summary of all chemical data for the material being transported.

The CCR will include an accounting of the destination of all material removed from the Site during this IRM, including excavated soil, contaminated soil, historic fill, solid waste, hazardous waste, non-regulated material, and fluids. Documentation associated with the disposal of all material must also

include records and approvals for receipt of the material. This information will also be presented in a tabular form in the CCR.

A bill of lading system or equivalent will be used for off-Site movement of non-hazardous wastes and contaminated soils. This information will be reported in the CCR. Hazardous wastes derived from the Site will be stored, transported, and disposed of in full compliance with applicable local, state, and federal regulations. Appropriately licensed haulers will be used for material removed from this Site and will be in full compliance with all applicable local, state, and federal regulations.

Waste characterization sampling will be performed exclusively for the purposes of off-Site soil disposal in a manner suitable to receiving facilities and in conformance with applicable federal, state, and local laws, rules, regulations, and facility-specific permits. Sampling and analytical methods, sampling frequency, analytical results, and QA/QC associated with waste characterization activities will be reported in the CCR. All data available for soil/material to be disposed of at a given facility must be submitted to the disposal facility with a suitable explanation prior to shipment and receipt. Waste characterization data will be used solely for complying with requirements for off-Site disposal. Waste characterization sampling cannot be utilized for:

- Delineating the extent of contamination required for remediation at a Site;
- Replacing or substituting data collected as part of Site Characterization and/or RI.
- Replacing or substituting confirmation or documentation sampling as described in NYSDEC DER-10, Section 5.4.
- Modifying remedial decisions as formalized in a NYSDEC-approved Decision Document or Record of Decision, as applicable.

3.3.2.7 Demarcation

After the completion of soil removal and any other invasive remedial activities and prior to backfilling, a land survey will be performed by a New York State-licensed surveyor. The survey will define the top elevation of residual contaminated soils before six inches of approved backfill material is placed on top. A physical demarcation layer, consisting of orange snow fencing material or equivalent material, will be placed on this surface to provide a visual reference. This demarcation layer will constitute the top of the "Residuals Management Zone," the zone that requires adherence to special conditions for the disturbance of contaminated residual soils defined in the forthcoming Site Management Plan (SMP). The survey will measure the grade covered by the demarcation layer before the placement of cover soils, pavement and sub-soils, structures, or other materials. This survey and the demarcation layer placed on this grade surface will constitute the physical and written record of the upper surface of the "Residuals Management Zone" in the forthcoming SMP. A map showing the survey results will be included in the CCR and the forthcoming SMP.

3.3.2.8 Import of Backfill

Materials proposed for import onto the Site are not anticipated as part of the IRM. However, if imported materials are proposed, documentation of the material will be provided to NYSDEC for approval prior to its use on the Site. Imported soil for backfill must meet the requirements of 6 NYCRR Part 375-6.7(d) and NYSDEC DER-10 Section 5.4(e), Table 5.4(e)10. Material from industrial sites, spill sites, other environmental remediation sites, or other potentially contaminated sites will not be imported to the Site. Solid waste will not be imported onto the Site.

Backfill material will consist of clean fill (as described in the following paragraph) or other acceptable fill material such as virgin stone from a quarry or RCA. If RCA is imported to the Site, it will be from a NYSDEC-registered facility in compliance with 6 NYCRR Part 360 registration and permitting requirements for the period of acquisition of RCA. RCA imported from compliant facilities will not require chemical testing unless required by the NYSDEC under the terms for operation of the facility. RCA imported to the Site must be derived from recognizable and uncontaminated concrete, with no more than 10 percent by weight passing through a No. 100 sieve. RCA is not acceptable for and will not be used as cover or drainage material.

Imported soil (i.e., clean fill) will meet the Allowable Constituent Levels of Imported Fill or Soil defined in DER-10 Appendix 5. Non-compliant soils will not be imported to the Site. Clean fill will be segregated at a source/facility that is free of environmental contaminants. Qualified environmental personnel will collect representative samples at a frequency consistent with NYSDEC CP-51. The samples will be analyzed for the Part 375 list of VOCs, SVOCs, pesticides, metals, polychlorinated biphenyls (PCBs), per- and poly-fluoroalkyl substances (PFAS), and 1,4-dioxane by an NYSDOH Environmental Laboratory Approval Program (ELAP)-certified laboratory. Upon meeting these criteria, the certified-clean fill will be transported to the Site and segregated from impacted material, as necessary, on plastic sheeting until used as backfill. Trucks entering the Site with imported soils will be secured with tight-fitting covers.

Soils that meet "general fill" requirements under 6 NYCRR Part 360.13, but do not meet backfill or cover soil objectives for this Site, will not be imported onto the Site without prior approval by NYSDEC. Nothing in this IRMWP should be construed as an approval for this purpose.

A "Request to Import/Reuse Fill Material" form will be filed with the NYSDEC Project Manager for review and approval prior to import to the Site. A copy of the form is presented in **Appendix F**. All materials proposed for import onto the Site will be approved by the RE and will be in compliance with provisions in this IRMWP prior to receipt at the Site. Material from industrial sites, spill sites, other environmental remediation sites, or other potentially contaminated sites will not be imported to the Site.

The CCR will include the following certification by the RE: "I certify that all import of soils from off-Site, including source evaluation, approval, and sampling, has been performed in a manner that is consistent with the methodology defined in the Interim Remedial Measures Work Plan."

3.3.2.9 Confirmation Sampling

Confirmation soil samples will be collected at the locations shown on **Figure 6** in accordance with the protocols outlined in Section 4, Remedial Performance Evaluation.

3.3.2.10 Fluids Management

Liquids removed from the Site, though not anticipated, including dewatering fluids, if necessary, will be handled, transported, and disposed of in accordance with applicable local, state, and federal regulations. Liquids discharged into the New York City sewer system will be addressed through approval by the New York City Department of Environmental Protection (NYCDEP).

3.3.2.11 Stormwater Pollution Prevention

A silt fence or hay bales will be installed around the perimeter of the remedial construction area, if needed. Barriers and hay bale checks will be installed and inspected once a week and after every storm event. Results of inspections will be recorded in a logbook maintained at the Site and available for inspection by the NYSDEC. Necessary repairs to the silt fence and/or hay bales will be made immediately. Accumulated sediments will be removed as required to keep the barriers and hay bale checks functional. The manufacturer's recommendations will be followed for replacing the silt fence damaged due to weathering. Erosion and sediment control measures identified in the IRMWP will be observed to ensure that they are operating correctly. Where discharge locations or points are accessible, they will be inspected to ascertain whether erosion control measures are effective in preventing significant impacts to the sewer system.

3.3.3 UST Closure and Removal

Based on the NYSDEC PBS database, there are four remaining USTs at the Site that were installed in the mid- to late 1980s, including three 4,000-gal USTs containing gasoline/ethanol and one 4,000-gal UST containing diesel. The locations of the USTs are shown on **Figure 2**.

The Remediation Contractor will provide an individual who is a Certificate of License Holder from the Fire Department of the City of New York (FDNY). The tanks and/or associated appurtenances (e.g., fill lines, vent line, and electrical conduit) will be permanently closed and removed in accordance with applicable NYSDEC tank closure requirements, including DER-10 Section 5.5, 6 NYCRR Part 613-2.6b, and NYSDEC CP-51, by submitting a modified Application for PBS Registration identifying the tanks and the date of permanent closure and removal. Petroleum-impacted soil will be excavated and disposed of off-Site at a permitted disposal facility in accordance with applicable regulations. Closure documentation, such as Contractor affidavits, bills of lading for sludge disposal, and tank disposal receipts, will be provided as appendices in the CCR.

If encountered, additional USTs and/or associated appurtenances will be decommissioned in accordance with the above procedures. USTs and/or associated appurtenances will be registered and administratively closed with the NYSDEC PBS unit.

3.3.3.1 UST Removal Methods

USTs will be removed in accordance with the procedures described under the NYSDEC Memorandum for the Permanent Abandonment of Petroleum Storage Tanks and Section 5.5 of DER-10 as follows:

- Remove all product to its lowest draw-off point.
- Drain and flush piping into the tank.
- Vacuum out the tank bottom, consisting of water product and sludge.
- Dig down to the top of the tank and expose the upper half of the tank.
- Remove the fill tube and disconnect the fill, gauge, product, and vent lines and pumps. Cap and plug open ends of lines.
- Temporarily plug all tank openings, complete the excavation, remove the tank, and place it in a secure location.

- Render the tank safe and check the tank atmosphere to ensure that petroleum vapors have been satisfactorily purged from the tank.
- Clean tank or remove to a storage yard for cleaning.
- If the tank is to be moved, it must be transported by a licensed waste transporter. Plug and cap all holes prior to transport, leaving a 1/8-inch vent hole located at the top of the tank during transport.
- After cleaning, the tank must be made acceptable for disposal at a scrap yard by cleaning the tank interior with a high-pressure rinse and cutting the tank into several pieces.

During the tank and pipeline removal, the following field observations will be made and recorded:

- A description and photographic documentation of the tank and pipeline condition (pitting, holes, staining, leak points, evidence of repairs, etc.);
- Examination of the excavation floor and sidewalls for physical evidence of contamination (odor, staining, sheen, etc.); and,
- Periodic field screening (through bucket return) of the floor and sidewalls of the excavation with a properly calibrated PID.

3.3.4 Waste Management

Waste generated during IRM activities is anticipated to include spoils generated from the installation of the cut-off wall, spent decontamination fluids, and disposable sampling equipment. The spoils will be disposed of appropriately at an approved facility. Spent decontamination fluids will be containerized on Site in NYSDOT-approved 55-gallon drums pending characterization and off-Site disposal. Incidental project wastes, such as personal protective equipment (PPE), will be disposed of as general waste unless visually impacted with contaminants, in which case the waste will be disposed of at an approved facility. Proposed facilities will be forwarded to the NYSDEC prior to off-Site disposal.

Remediation equipment may require decontamination at certain points in the project. Decontamination will take place using brushes, steam cleaners, and/or pressure washers. Residues from decontamination operations will be collected and managed with other remedial-derived waste. Decontamination water will be collected for off-Site disposal or treatment.

3.3.5 Green and Sustainable Remediation

Green remediation principles and techniques will be implemented to the extent feasible in the design, implementation, and Site management of the IRM as per DER-31. The major green remediation components are as follows:

- Considering the environmental impacts of treatment technologies and remedy stewardship over the long term;
- Reducing direct and indirect greenhouse gases and other emissions;
- Increasing energy efficiency and minimizing the use of non-renewable energy;
- Conserving and efficiently managing resources and materials;
- Reducing waste, increasing recycling, and increasing reuse of materials that would otherwise be considered waste;

- Maximizing habitat value and creating habitat when possible;
- Fostering green and healthy communities and working landscapes that balance ecological, economic, and social goals; and,
- Integrating the remedy with the end use, where possible, and encouraging green and sustainable renovation and/or redevelopment.

As part of the IRM remedial design program, to evaluate the IRM with respect to green and sustainable remediation principles, an environmental footprint analysis was completed and is included in **Appendix G**. The environmental footprint analysis was completed using the USEPA's Spreadsheets for Environmental Footprint Analysis, which is a NYSDEC-accepted tool. Water consumption, greenhouse gas emissions, renewable and non-renewable energy use, waste reduction, and material use were estimated for the IRM. Goals for the project related to these green and sustainable remediation metrics, as well as for minimizing community impacts, protecting habitats and natural and cultural resources, and promoting environmental justice, are incorporated into the IRM remedial program, as appropriate. Progress with respect to green and sustainable remediation metrics will be tracked during the implementation of the IRM and reported in the CCR, including a comparison to the goals established during the IRM remedial design program.

Additionally, the remedial design program includes a climate change vulnerability assessment to evaluate the impact of climate change on the project Site and the proposed remedy. Potential vulnerabilities associated with extreme weather events (e.g., hurricanes, lightning, heat stress, and drought), flooding, and sea level rise will be identified, and the remedial design program will incorporate measures to minimize the impact of climate change on potential identified vulnerabilities. Climate change is not expected to have a significant impact on the remedial system. The climate screening process and results will be documented in the form of a completed checklist and brief letter report. A completed climate screening checklist for the remediation phase is provided in **Appendix G**. An updated checklist will be included in the CCR to document the post-remediation status of the Site.

4. Interim Remedial Performance Evaluation

4.1 SOIL CLEANUP OBJECTIVES

SCOs for the IRM will be the CP-51 SCLs for Gasoline Contaminated Soils as listed in **Table 1**. UST closures will, at a minimum, conform to criteria defined in DER-10.

4.2 SOIL SAMPLING FREQUENCY

Confirmation samples will be collected to confirm that CP-51 SCLs have been achieved. One confirmation soil sample will be collected at the base of each tank and one from each sidewall.

Confirmation sampling locations are shown in **Figure 6**. If the analytical data for soil samples collected exceed the SCLs, additional soil samples will be collected to delineate these impacts, and over-excavation may be required to ensure that all impacted material has been removed from the Site. Impacted soil will be removed to the extent practical, or until the bedrock surface is encountered.

4.3 METHODOLOGY

Confirmation soil samples will be collected in accordance with NYSDEC DER-10 to document remedial performance and will be analyzed for the CP-51 SCLs for Gasoline Contaminated Soils. Samples will be collected into laboratory-provided bottle ware. VOCs will be collected into Terra Cores® or Encores®. Samples will be transported under chain-of-custody protocol to an ELAP-certified laboratory.

4.4 REPORTING OF RESULTS

Chemical labs used for all end-point sample results and contingency sampling will be NYSDOH ELAP-certified. Analytical Services Protocol (ASP) Category B deliverables will be prepared for remedial performance samples collected during the implementation of this IRMWP. The CCR will provide a tabular and map summary of all endpoint sample results and exceedances of SCOs.

4.5 QA/QC

QC procedures for confirmation soil sampling are included in the QAPP (refer to **Appendix C**). Confirmation analytical results will be provided in the NYSDEC's electronic data deliverable (EDD) format for EQuIS™. Guidance on the sampling frequency is presented in NYSDEC DER-10 Section 5.4.

The QA/QC procedures required by the NYSDEC ASP and SW-846 methods will be followed. This will include instrument calibration, standard compound spikes, surrogate compound spikes, and analysis of QC samples. The laboratory will provide sample bottles, which will be pre-cleaned and preserved. Where there are differences in the SW-846 and NYSDEC ASP requirements, the NYSDEC ASP will take precedence.

4.6 DATA VALIDATION

Data Usability Summary Reports (DUSRs) will be prepared by a qualified data validator, and the findings will be reported in the CCR.

5. Health and Safety

5.1 HEALTH AND SAFETY PLAN

A Site-specific HASP has been prepared in accordance with NYSDEC and NYSDOH guidelines and is provided as **Appendix B** of this work plan. The HASP includes a description of health and safety protocols to be followed by Haley & Aldrich of New York field staff during implementation of the IRM, including monitoring within the work area, along with response actions should impacts be observed. The HASP has been developed in accordance with OSHA 40 Code of Federal Regulations (CFR) Part 1910.120 regulatory requirements for use by Haley & Aldrich of New York field staff who will work at the Site during planned activities. Contractors or other personnel who perform work at the Site are required to develop their own HASP and procedures of comparable or higher content for their respective personnel in accordance with relevant OSHA regulatory requirements for work at hazardous waste sites, as well as general industry practice, as applicable, based on the nature of work being performed.

5.2 COMMUNITY AIR MONITORING PROGRAM

The Community Air Monitoring Plan (CAMP) details the monitoring for the potential presence of VOCs and particulates (i.e., dust) at the upwind and downwind perimeters of the designated work area when ground-intrusive activities are in progress outdoors at the Site during implementation of the IRMWP. The CAMP aims to provide protection for residents in the designated work area and residents of the downwind community from potential airborne releases that directly result from the invasive IRM activities conducted at the Site. Adherence to the monitoring action levels specified in the CAMP requires monitoring, and when necessary, corrective actions to abate emissions, and/or shutdown work. The CAMP also helps to confirm that work activities do not spread contamination off Site through the air. In addition, visual and olfactory observations will be made to keep dust and odors to a minimum around the work areas. VOCs will be monitored using Aeroqual® AQS1 Air Quality Monitors or other equivalent equipment. Readings will be recorded every 15 minutes at the Site by field personnel.

A public school is located west-adjacent to the Site beyond 4th Avenue with residential dwellings east of the Site and north of the Site beyond 40th Street. In accordance with the Special Requirements CAMP, when work areas are within 20 ft of potentially exposed populations or occupied structures, the continuous monitoring locations for VOCs and particulates will reflect the nearest potentially exposed individuals and the location of ventilation system intakes for nearby structures. A total of three CAMP units will be deployed (one upwind, one downwind, and one biased towards nearby sensitive receptors and occupied structures within 20 ft) during IRM activities. Copies of the CAMP and Special Requirements CAMP have been included as **Appendix H**.

In addition, the CAMP also addresses nuisance odors. Nuisance odors would be detected by on-Site personnel who are either present at the Site perimeter or working within the active investigation and remediation areas. If nuisance odors are identified, work will be halted, and the source of odors will be identified (with a PID and olfactory observation) and corrected. The remedial contractor shall procure an odor suppressant prior to work, store it at the Site, and utilize it as needed during the IRM. BioSolve™, Rusmar Foam AC645/ac-667SE, or an industry equivalent will be procured for the IRM work. The BioSolve™ and Rusmar Foam safety data sheets are provided in **Appendix H**. Should an alternative odor suppressant be proposed, the safety data sheet will be provided to NYSDEC prior to implementation for review.

Exceedances observed in the CAMP will be reported to NYSDEC and NYSDOH Project Managers within 24 hours of the exceedance and will include the reason(s) for the exceedance and steps taken to address the exceedance. CAMP exceedances will be included in the Daily Report.

5.3 ODOR, DUST, AND NUISANCE CONTROL PLAN

Dust, odor, and nuisance controls will be accomplished by the Remediation Contractor as described in this section.

The CCR will include the following certification by the RE: "I certify that all invasive work during the remediation and all invasive development work were conducted in accordance with dust and odor suppression methodology defined in the Interim Remedial Measures Work Plan."

5.3.1 Odor Control Plan

This odor control plan is capable of controlling emissions of nuisance odors off the Site. Specific odor control methods to be used, if needed, will include the application of foam suppressants or tarps over the odor or VOC source areas. If nuisance odors are identified, work will be halted, and the source of the odors will be identified and corrected. Work will not resume until nuisance odors have been abated. The NYSDEC and NYSDOH will be notified of odor events and other complaints about the project. Implementation of odor controls is the responsibility of the Contractor. Monitoring odor emission, including the halt of work, will be the responsibility of the RE or his/her designated representative.

Necessary means will be employed to prevent on- and off-Site nuisances. At a minimum, procedures will include: (a) limiting the area of open excavations; (b) shrouding open excavations with tarps and other covers; and (c) using foams to cover exposed odorous soils. If odors develop and cannot be otherwise controlled, additional means to eliminate odor nuisances will include: (a) direct load-out of soils to trucks for off-Site disposal; (b) use of chemical odorants in spray, foam, or misting systems; and (c) use of staff to monitor odors in surrounding neighborhoods. Odor control suppressant will be available on the Site during implementation of the IRMWP and will be accessible to workers who will have the knowledge and ability to operate the odor control equipment. The SDS for an odor control suppressant is provided in **Appendix H**.

Where odor nuisances have developed during remedial work and cannot be corrected, or where the release of nuisance odors cannot otherwise be avoided due to on-Site conditions or close proximity to sensitive receptors, odor control will be achieved by sheltering excavation and handling areas under tented containment structures equipped with appropriate air venting/filtering systems.

5.3.2 Dust Control Plan

A dust suppression plan that addresses dust management during ground-intrusive on-Site work will include, at a minimum: (a) the use of a dedicated water distribution system, an on-Site water truck for road wetting, or an alternate water source with suitable supply and pressure for use in dust control; (b) the use of gravel for on-Site roads to provide a clean and dust-free road surface; and (c) the limiting of the total area of on-Site roads to minimize the area required for water spraying. Dust suppression equipment will be available on-Site during implementation of the IRMWP and will be accessible to workers who will have the knowledge and ability to operate the dust suppression equipment.

5.3.3 Other Nuisances

A plan for rodent control will be developed and used by the Remediation Contractor during Site preparation (including clearing and grubbing) and during remedial work. A plan for noise control will be developed and used by the Remediation Contractor during Site preparation and remedial work and will conform, at a minimum, to the NYCDEP noise control standards.

6. Residual Contamination to Remain On-Site

Excavation associated with the IRM will remove the majority of source material at the Site, but some residual contaminated soil and groundwater will exist below 12 ft bgs and beneath the development footprint; therefore, engineering controls (ECs) and institutional controls (ICs) will be required to protect human health and the environment. Residual contamination will include petroleum-related VOC-impacted soil and groundwater with impacts to soil vapor. Residual VOC-impacted soil will likely be treated with an SVE system, to be conducted and designed as part of a forthcoming RAWP, and residual VOC-impacted groundwater will be prevented from migrating outside of the IRM area by a groundwater cutoff wall, also to be designed under a forthcoming RAWP. Residual VOC-impacted groundwater will also potentially be addressed by an in-situ remedy under a forthcoming RAWP. The potential for soil vapor intrusion (SVI) into the new building will be mitigated with an active SSDS. Upon completion of the remedial action as per this IRMWP and the forthcoming RAWP, an SVI evaluation will need to be performed prior to occupancy.

7. Reporting

7.1 DAILY REPORTING

Reports providing a summary of activities for each day of active remedial work will be emailed to the NYSDEC and NYSDOH Project Managers on a daily basis. These reports will include:

- The project number, statement of activities, an update of the progress made, locations of excavation, and other remedial work performed;
- Quantities of material imported and exported from the Site;
- Status of on-Site soil/fill stockpiles;
- A summary of citizen complaints, including relevant details (i.e., name, phone number, basis of complaint, actions taken);
- A summary of CAMP results noting exceedances; and,
- Photographs of notable Site conditions and activities.

Reports are not intended to be the primary mode of communication for notifying NYSDEC of emergencies, requests for changes to the IRMWP, or time-critical information. However, these conditions, if to occur, will be included in the daily reports. Emergency conditions and changes to the IRMWP will be directly communicated to the NYSDEC Project Manager.

Daily Reports will include a description of daily activities with a Site Map that identifies work areas. These reports will include a summary of air sampling results, odor and dust problems and corrective actions, and all complaints received from the public. The NYSDEC-assigned project number will appear on all reports.

7.2 MONTHLY REPORTS

Monthly reports will be submitted to NYSDEC and NYSDOH Project Managers by the 10th of the following month of the reporting period and will include:

- Activities relative to the Site during the previous reporting period and those anticipated for the next reporting period, including a quantitative presentation of work performed (i.e., tons of material exported and imported, etc.);
- Description of approved activity modifications, including changes in work scope and/or schedule;
- Sampling results received following internal data review and validation, as applicable; and,
- An update of the remedial schedule, including the percentage of project completion, unresolved delays encountered or anticipated that may affect the future schedule, and efforts made to mitigate such delays.

7.3 CONSTRUCTION COMPLETION REPORT

A CCR will be prepared in accordance with DER-10 guidelines to document all aspects of the IRM activities and will include:

- A summary of the removal action, including a detailed description of the extent and volume of soil excavated;
- All fully executed manifests documenting any off-Site transport of waste material;
- Well decommissioning documentation, as necessary;
- Scaled Site plan showing the location of IRM activities and confirmation samples;
- Results of all analyses, including summary tables, laboratory data sheets, and the required laboratory data deliverables;
- Information on backfill imported onto the Site, including amount, type, and origin, and copies of transport tickets from the supplier, as necessary;
- Photographic documentation; and
- Certification of the CCR by a New York State-certified P.E.

8. Schedule

The Respondent plans to implement the IRM promptly after the approval of this IRMWP.

Anticipated IRM Schedule	
IRMWP Drafting	October 2025
NYSDEC IRMWP Review, 30-Day Public Comment, and Completion of the RI	October to November 2025
NYSDEC Approval of the IRMWP	November 2025
Implementation of IRMWP	November 2025 to December 2026
RAWP Drafting	October to November 2025
NYSDEC RAWP Review and 45-Day Public Comment	November to December 2025
NYSDEC Approval of RAWP	January 2026
Implementation of RAWP	January to April 2026
Drafting CCR	January to February 2026
Drafting Final Engineering Report (FER) and SMP	March to April 2026
NYSDEC & NYSDOH Review and Approval of CCR, FER, SMP	April to May 2026
First Operations, Maintenance & Monitoring (OM&M) Report	June to July 2027

References

1. Berninger Environmental, 2020. *Supplemental Remedial Investigation Report*. June.

2. Berninger Environmental, 2021. *Supplemental Investigation Soil and Groundwater Report*. October.

3. Berninger Environmental, 2024. *Monitoring Report*. 2024.

4. Castleton Environmental, 2019. *Phase II Environmental Site Assessment*. January.

5. Guidance for Evaluating Soil Vapor Intrusion in the State of New York, October 2006 (Revised 2017 and 2024).

6. H & A of New York Engineering and Geology LLP, 2025. *Technical Memorandum*. August.

7. Lesova Environmental Group, 2024. *Phase I Environmental Site Assessment – 4001 4th Avenue, Brooklyn, New York*. March.

8. New York State Department of Environmental Conservation, 2006. Part 375 Title 6 of the New York Compilation of Codes, Rules, and Regulations. Effective December 14.

9. New York State Department of Environmental Conservation, 2010. Program Policy DER-10, Technical Guidance for Site Investigation and Remediation. May.

TABLES

Table 1. Soil Cleanup Objectives

Contaminant	CAS Registry Number	Soil Cleanup Level (ppm)
Benzene	71-43-2	0.06
n-Butylbenzene	104-51-8	12.0
sec-Butylbenzene	135-98-8	11.0
Ethylbenzene	100-41-4	1.0
Isopropylbenzene	98-82-8	2.3
p-Isopropyltoluene	99-87-6	10.0
Methyl-Tert-Butyl-Ether	1634-04-4	0.93
Naphthalene	91-20-3	12.0
n-Propylbenzene	103-65-1	3.9
Tert-Butylbenzene	98-06-6	5.9
Toluene	108-88-3	0.7
1,2,4-Trimethylbenzene	95-63-6	3.6
1,3,5-Trimethylbenzene	108-67-8	8.4
Xylene (Mixed)	1330-20-7	0.26

Notes:

1. Criteria are NYSDEC CP-51 Soil Cleanup Guidance Soil Cleanup Levels for Gasoline Contaminated Soil
2. mg/kg: milligram per kilogram

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

Location Name	Criteria			HA-SB1	HA-SB1	HA-SB1	HA-SB1	HA-SB10	HA-SB10	HA-SB10	HA-SB10	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB12	HA-SB12
Sample Name	Restricted Use Soil Cleanup Objectives - Protection of Groundwater	NY Part 375 Restricted Residential Use Soil Cleanup Objectives	NY Part 375 Unrestricted Use Soil Cleanup Objectives	HA-SB1_0-0.5	HA-SB1_6-8	HA-SB1_15-17	HA-SB1_38-40	HA-SB10_0-0.5	HA-SB10_5-7	HA-SB10_15-17	HA-SB10_43-45	HA-SB11_0-0.5	HA-SB11_4-6	HA-SB11_15-17	UP02_2025042	HA-SB11_40-42	HA-SB12_0-0.5	HA-SB12_8-10
Sample Date				04/23/2025	04/23/2025	04/23/2025	04/23/2025	07/15/2025	07/15/2025	07/15/2025	07/15/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/14/2025	04/14/2025
Lab Sample ID				L2525069-11	L2525069-12	L2525069-13	L2525069-14	460-330741-1	460-330741-2	460-330741-3	460-330741-4	L2525266-02	L2525266-03	L2525266-04	L2525266-05	L2525266-06	L2522786-07	L2522786-08
Sample Depth (bgs)				0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	38 - 40 (ft)	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	43 - 45 (ft)	0 - 0.5 (ft)	4 - 6 (ft)	15 - 17 (ft)	15 - 17 (ft)	40 - 42 (ft)	0 - 0.5 (ft)	8 - 10 (ft)
Volatile Organic Compounds (mg/kg)																		
1,1,1,2-Tetrachloroethane	NA	NA	NA	ND (0.0015)	ND (0.00058)	ND (0.25)	ND (0.032)	-	-	-	-	ND (0.034)	ND (0.033)	ND (0.096)	ND (0.096)	ND (0.32)	ND (0.00045)	ND (0.03)
1,1,1-Trichloroethane	0.68	100	0.68	ND (0.0015)	ND (0.00058)	ND (0.25)	ND (0.032)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.034)	ND (0.033)	ND (0.096)	ND (0.096)	ND (0.32)	ND (0.00045)	ND (0.03)
1,1,2,2-Tetrachloroethane	NA	NA	NA	ND (0.0015)	ND (0.00058)	ND (0.25)	ND (0.032)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.034)	ND (0.033)	ND (0.096)	ND (0.096)	ND (0.32)	ND (0.00045)	ND (0.03)
1,1,2-Trichloroethane	NA	NA	NA	ND (0.003)	ND (0.0012)	ND (0.5)	ND (0.064)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.068)	ND (0.066)	ND (0.19)	ND (0.19)	ND (0.65)	ND (0.00089)	ND (0.06)
1,1-Dichloroethane	0.27	26	0.27	ND (0.003)	ND (0.0012)	ND (0.5)	ND (0.064)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.068)	ND (0.066)	ND (0.19)	ND (0.19)	ND (0.65)	ND (0.00089)	ND (0.06)
1,1-Dichloroethene	0.33	100	0.33	ND (0.003)	ND (0.0012)	ND (0.5)	ND (0.064)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.068)	ND (0.066)	ND (0.19)	ND (0.19)	ND (0.65)	ND (0.00089)	ND (0.06)
1,1-Dichloropropene	NA	NA	NA	ND (0.0015)	ND (0.00058)	ND (0.25)	ND (0.032)	-	-	-	-	ND (0.034)	ND (0.033)	ND (0.096)	ND (0.096)	ND (0.32)	ND (0.00045)	ND (0.03)
1,2,3-Trichlorobenzene	NA	NA	NA	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	ND (0.0011)	0.11	ND (0.079)	ND (0.086)	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
1,2,3-Trichloropropane	NA	NA	NA	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	-	-	-	-	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
1,2,4,5-Tetramethylbenzene	NA	NA	NA	ND (0.006)	0.0027	24	0.19	-	-	-	-	14	6.1	12	15	12	0.001 J	3.1
1,2,4-Trichlorobenzene	NA	NA	NA	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	ND (0.0011)	0.43	ND (0.079)	ND (0.086)	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
1,2,4-Trimethylbenzene	3.6	52	3.6	0.0019 J	0.0021 J	***370***	2.5	-	-	-	-	0.38	3.5	***110***	***140***	***120***	0.0065	***33***
1,2-Dibromo-3-chloropropane (DBCP)	NA	NA	NA	ND (0.009)	ND (0.0034)	ND (1.5)	ND (0.19)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.2)	ND (0.2)	ND (0.58)	ND (0.57)	ND (1.9)	ND (0.0027)	ND (0.18)
1,2-Dibromoethane (Ethylene Dibromide)	NA	NA	NA	ND (0.003)	ND (0.0012)	ND (0.5)	ND (0.064)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.068)	ND (0.066)	ND (0.19)	ND (0.19)	ND (0.65)	ND (0.00089)	ND (0.06)
1,2-Dichlorobenzene	1.1	100	1.1	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	ND (0.0011)	0.021 J	0.03 J	ND (0.086)	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
1,2-Dichloroethane	0.02	3.1	0.02	ND (0.003)	ND (0.0012)	ND (0.5)	ND (0.064)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.068)	ND (0.066)	ND (0.19)	ND (0.19)	ND (0.65)	ND (0.00089)	ND (0.06)
1,2-Dichloroethene (total)	NA	NA	NA	ND (0.003)	ND (0.0012)	ND (0.5)	ND (0.064)	-	-	-	-	ND (0.068)	ND (0.066)	ND (0.19)	ND (0.19)	ND (0.65)	ND (0.00089)	ND (0.06)
1,2-Dichloropropane	NA	NA	NA	ND (0.003)	ND (0.0012)	ND (0.5)	ND (0.064)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.068)	ND (0.066)	ND (0.19)	ND (0.19)	ND (0.65)	ND (0.00089)	ND (0.06)
1,3,5-Trimethylbenzene	8.4	52	8.4	0.00066 J	0.00079 J	***75***	0.83	-	-	-	-	0.2	1.2	***29***	***37***	***39***	0.0021	6.1
1,3-Dichlorobenzene	2.4	49	2.4	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
1,3-Dichloropropane	NA	NA	NA	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	-	-	-	-	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
1,3-Dichloropropene	NA	NA	NA	ND (0.0015)	ND (0.00058)	ND (0.25)	ND (0.032)	-	-	-	-	ND (0.034)	ND (0.033)	ND (0.096)	ND (0.096)	ND (0.32)	ND (0.00045)	ND (0.03)
1,4-Dichlorobenzene	1.8	13	1.8	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	ND (0.0011)	0.081 J	0.056 J	ND (0.086)	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
1,4-Diethylbenzene	NA	NA	NA	ND (0.006)	0.00083 J	19	0.058 J	-	-	-	-	3.2	2.5	4.2	6.5	4.8	0.0027	ND (0.12)
1,4-Dioxane	0.1	13	0.1	ND (0.24)	ND (0.092)	ND (40)	ND (5.1)	-	-	-	-	ND (5.4)	ND (5.3)	ND (15)	ND (15)	ND (52)	ND (0.071)	ND (4.8)
2,2-Dichloropropane	NA	NA	NA	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	-	-	-	-	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
2-Butanone (Methyl Ethyl Ketone)	0.12	100	0.12	ND (0.03)	ND (0.012)	ND (5)	ND (0.64)	0.0064	ND (0.44)	ND (0.39)	ND (0.43)	ND (0.68)	ND (0.66)	ND (1.9)	ND (1.9)	ND (6.5)	ND (0.0089)	ND (0.6)
2-Chlorotoluene	NA	NA	NA	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	-	-	-	-	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
2-Hexanone (Methyl Butyl Ketone)	NA	NA	NA	ND (0.03)	ND (0.012)	ND (5)	ND (0.64)	ND (0.0055)	ND (0.44)	ND (0.39)	ND (0.43)	ND (0.68)	ND (0.66)	ND (1.9)	ND (1.9)	ND (6.5)	ND (0.0089)	ND (0.6)
2-Phenylbutane (sec-Butylbenzene)	11	100	11	ND (0.003)	0.00059 J	4.9	0.056 J	-	-	-	-	0.69	1.5	2.2	2.8	3.1	0.00031 J	0.75
4-Chlorotoluene	NA	NA	NA	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	-	-	-	-	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
4-Ethyltoluene (1-Ethyl-4-Methylbenzene)	NA	NA	NA	ND (0.006)	0.002 J	320	2.1	-	-	-	-	0.91	3.1	99	120	110	0.0018	15
4-Methyl-2-Pentanone (Methyl Isobutyl Ketone)	NA	NA	NA	ND (0.03)	ND (0.012)	ND (5)	ND (0.64)	ND (0.0055)	ND (0.44)	ND (0.39)	ND (0.43)	ND (0.68)	ND (0.66)	ND (1.9)	ND (1.9)	ND (6.5)	ND (0.0089)	ND (0.6)
Acetone	0.05	100	0.05	ND (0.03)	0.016	ND (5)	ND (0.64)	0.035	ND (0.44)	ND (0.39)	ND (0.43)	ND (0.68)	ND (0.66)	ND (1.9)	ND (1.9)	ND (6.5)	ND (0.0089)	ND (0.6)
Acrylonitrile	NA	NA	NA	ND (0.012)	ND (0.0046)	ND (2)	ND (0.26)	-	-	-	-	ND (0.27)	ND (0.26)	ND (0.77)	ND (0.76)	ND (2.6)	ND (0.0036)	ND (0.24)
Benzene	0.06	4.8	0.06	ND (0.0015)	0.0033	***0.19 J***	***0.3***	0.003	ND (0.088)	0.054 J	***1.1***	***0.77***	***0.54***	***6.3***	***8.1***	***21***	ND (0.00045)	0.042
Bromobenzene	NA	NA	NA	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	-	-	-	-	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
Bromodichloromethane	NA	NA	NA	ND (0.0015)	ND (0.00058)	ND (0.25)	ND (0.032)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.034)	ND (0.033)	ND (0.096)	ND (0.096)	ND (0.32)	ND (0.00045)	ND (0.03)
Bromoform	NA	NA	NA	ND (0.012)	ND (0.0046)	ND (2)	ND (0.26)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.27)	ND (0.26)	ND (0.77)	ND (0.76)	ND (2.6)	ND (0.0036)	ND (0.24)
Bromomethane (Methyl Bromide)	NA	NA	NA	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	ND (0.0022)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
Carbon disulfide	NA	NA	NA	ND (0.03)	ND (0.012)	ND (5)	ND (0.64)	0.0011	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.68)	ND (0.66)	ND (1.9)	ND (1.9)	ND (6.5)	ND (0.0089)	ND (0.6)
Carbon tetrachloride	0.76	2.4	0.76	ND (0.003)	ND (0.0012)	ND (0.5)	ND (0.064)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.068)	ND (0.066)	ND (0.19)	ND (0.19)	ND (0.65)	ND (0.00089)	ND (0.06)
Chlorobenzene	1.1	100	1.1	ND (0.0015)	ND (0.00058)	ND (0.25)	ND (0.032)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.034)	ND (0.033)	ND (0.096)	ND (0.096)	ND (0.32)	ND (0.00045)	ND (0.03)
Chlorobromomethane	NA	NA	NA	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	ND (0.0011)	ND (0.088) *	ND (0.079)	ND (0.086)	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
Chloroethane	NA	NA	NA	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
Chloroform (Trichloromethane)	0.37	49	0.37	ND (0.0045)	ND (0.0017)	ND (0.76)	ND (0.096)	0.0019	***10***	ND (0.079)	ND (0.086)	ND (0.1)	ND (0.099)	ND (0.29)	ND (0.29)	ND (0.97)	ND (0.0013)	ND (0.09)
Chloromethane (Methyl Chloride)	NA	NA	NA	ND (0.012)	ND (0.0046)	ND (2)	ND (0.26)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.27)	ND (0.26)	ND (0.77)	ND (0.76)	ND (2.6)	ND (0.0036)	ND (0.24)
cis-1,2-Dichloroethene	0.25	100	0.25	ND (0.003)	ND (0.0012)	ND (0.5)	ND (0.064)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.068)	ND (0.066)	ND (0.19)	ND (0.19)	ND (0.65)	ND (0.00089)	ND (0.06)
cis-1,3-Dichloropropene	NA	NA	NA	ND (0.0015)	ND (0.00058)	ND (0.25)	ND (0.032)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.034)	ND (0.033)	ND (0.096)	ND (0.096)	ND (0.32)	ND (0.00045)	ND (0.03)
Cyclohexane	NA	NA	NA	-	-	-	-	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	-	-	-	-	-	-	-
Cymene (p-Isopropyltoluene)	NA	NA	NA	ND (0.003)	0.00031 J	2.3	0.032 J	-	-	-	-	0.55	1.1	1.4	1.9	2.6	0.00013 J	0.39
Dibromochloromethane	NA	NA	NA	ND (0.003)	ND (0.0012)	ND (0.5)	ND (0.064)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.068)	ND (0.066)	ND (0.19)	ND (0.19)	ND (0.65)	ND (0.00089)	ND (0.06)
Dibromomethane	NA	NA	NA	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	-	-	-	-	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
Dichlorodifluoromethane (CFC-12)	NA	NA	NA	ND (0.03)	ND (0.012)	ND (5)	ND (0.64)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.68)	ND (0.66)	ND (1.9)	ND (1.9)	ND (6.5)	ND (0.0089)	ND (0.6)
Ethyl Ether	NA	NA	NA	ND (0.006)	ND (0.0023)	ND (1)	ND (0.13)	-	-	-	-	ND (0.14)	ND (0.13)	ND (0.38)	ND (0.38)	ND (1.3)	ND (0.0018)	ND (0.12)
Ethylbenzene	1	41	1	0.00059 J	0.001 J	***41***	0.89	ND (0.0011)	0.027 J	***6.5***	0.46	0.54	***2.6***	***32***	***40***	***48***	0.0002 J	***2***

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

Location Name	Criteria			HA-SB1	HA-SB1	HA-SB1	HA-SB1	HA-SB10	HA-SB10	HA-SB10	HA-SB10	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB12	HA-SB12
Sample Name	Restricted Use Soil Cleanup Objectives - Protection of Groundwater	NY Part 375 Restricted Residential Use Soil Cleanup Objectives	NY Part 375 Unrestricted Use Soil Cleanup Objectives	HA-SB1_0-0.5	HA-SB1_6-8	HA-SB1_15-17	HA-SB1_38-40	HA-SB10_0-0.5	HA-SB10_5-7	HA-SB10_15-17	HA-SB10_43-45	HA-SB11_0-0.5	HA-SB11_4-6	HA-SB11_15-17	UP02_20250424	HA-SB11_40-42	HA-SB12_0-0.5	HA-SB12_8-10
Sample Date				04/23/2025	04/23/2025	04/23/2025	04/23/2025	07/15/2025	07/15/2025	07/15/2025	07/15/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/14/2025	04/14/2025
Lab Sample ID				L2525069-11	L2525069-12	L2525069-13	L2525069-14	460-330741-1	460-330741-2	460-330741-3	460-330741-4	L2525266-02	L2525266-03	L2525266-04	L2525266-05	L2525266-06	L2522786-07	L2522786-08
Sample Depth (bgs)				0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	38 - 40 (ft)	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	43 - 45 (ft)	0 - 0.5 (ft)	4 - 6 (ft)	15 - 17 (ft)	15 - 17 (ft)	40 - 42 (ft)	0 - 0.5 (ft)	8 - 10 (ft)
Hexachlorobutadiene	NA	NA	NA	ND (0.012)	ND (0.0046)	ND (2)	ND (0.26)	-	-	-	-	ND (0.27)	ND (0.26)	ND (0.77)	ND (0.76)	ND (2.6)	ND (0.0036)	ND (0.24)
Isopropylbenzene (Cumene)	NA	NA	NA	ND (0.003)	0.00032 J	9.4	0.12	ND (0.0011)	ND (0.088)	1.9	0.062 J	1.2	2	4.9	6.2	6.9	0.00028 J	1
m,p-Xylenes	NA	NA	NA	0.0026 J	0.0073	150	3.8	0.0011	ND (0.088)	21	1.7	1.7	5.5	140	180	190	0.00099 J	6
Methyl acetate	NA	NA	NA	-	-	-	-	ND (0.0055)	0.98	ND (0.39)	ND (0.43)	-	-	-	-	-	-	-
Methyl Tert Butyl Ether (MTBE)	0.93	100	0.93	ND (0.006)	ND (0.0023)	ND (1)	0.015 J	ND (0.0011)	ND (0.088)	ND (0.079)	***2.1***	0.29	0.02 J	0.08 J	0.12 J	0.16 J	ND (0.0018)	ND (0.12)
Methylcyclohexane	NA	NA	NA	-	-	-	-	0.0042	ND (0.088)	24	0.33	-	-	-	-	-	-	-
Methylene chloride (Dichloromethane)	0.05	100	0.05	ND (0.015)	ND (0.0058)	ND (2.5)	ND (0.32)	ND (0.0022)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.34)	ND (0.33)	ND (0.96)	ND (0.96)	ND (3.2)	ND (0.0045)	ND (0.3)
Naphthalene	12	100	12	0.0078 J	0.0017 J	***58***	0.35	-	-	-	-	0.99	2.1	***17***	***22***	***26***	0.00091 J	3.7
n-Butylbenzene	12	100	12	ND (0.003)	0.00044 J	10	0.085	-	-	-	-	2.2	3.6	5.4	7.1	6.6	0.00023 J	1.7
n-Propylbenzene	3.9	100	3.9	ND (0.003)	0.00074 J	***39***	0.41	-	-	-	-	3.2	***6.1***	***17***	***22***	***21***	0.00043 J	***4.1***
o-Xylene	NA	NA	NA	ND (0.003)	0.0016	34	1.5	ND (0.0011)	ND (0.088)	8.4	0.67	0.42	1.4	51	65	78	0.00066 J	1.9
Styrene	NA	NA	NA	ND (0.003)	ND (0.0012)	ND (0.5)	ND (0.064)	ND (0.0011)	ND (0.088)	ND (0.079) *	ND (0.086) *	ND (0.068)	0.024 J	0.18 J	0.21	0.19 J	ND (0.00089)	ND (0.06)
tert-Butylbenzene	5.9	100	5.9	ND (0.006)	0.00024 J	ND (1)	ND (0.13)	-	-	-	-	0.086 J	0.19	ND (0.38)	ND (0.38)	0.22 J	ND (0.0018)	0.023 J
Tetrachloroethene	1.3	19	1.3	ND (0.0015)	0.00027 J	ND (0.25)	ND (0.032)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.034)	ND (0.033)	ND (0.096)	ND (0.096)	ND (0.32)	ND (0.00045)	ND (0.03)
Toluene	0.7	100	0.7	0.0016 J	0.0058	***1.2***	***13***	0.0012	ND (0.088)	***1.5***	***2.2***	***1.5***	***3.6***	***140***	***170***	***260***	ND (0.00089)	0.11
trans-1,2-Dichloroethene	0.19	100	0.19	ND (0.0045)	ND (0.0017)	ND (0.76)	ND (0.096)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.1)	ND (0.099)	ND (0.29)	ND (0.29)	ND (0.97)	ND (0.0013)	ND (0.09)
trans-1,3-Dichloropropene	NA	NA	NA	ND (0.003)	ND (0.0012)	ND (0.5)	ND (0.064)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.068)	ND (0.066)	ND (0.19)	ND (0.19)	ND (0.65)	ND (0.00089)	ND (0.06)
trans-1,4-Dichloro-2-butene	NA	NA	NA	ND (0.015)	ND (0.0058)	ND (2.5)	ND (0.32)	-	-	-	-	ND (0.34)	ND (0.33)	ND (0.96)	ND (0.96)	ND (3.2)	ND (0.0045)	ND (0.3)
Trichloroethene	0.47	21	0.47	ND (0.0015)	ND (0.00058)	ND (0.25)	ND (0.032)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.034)	ND (0.033)	ND (0.096)	ND (0.096)	ND (0.32)	ND (0.00045)	ND (0.03)
Trichlorofluoromethane (CFC-11)	NA	NA	NA	ND (0.012)	ND (0.0046)	ND (2)	ND (0.26)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.27)	ND (0.26)	ND (0.77)	ND (0.76)	ND (2.6)	ND (0.0036)	ND (0.24)
Trifluorotrichloroethane (Freon 113)	NA	NA	NA	-	-	-	-	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	-	-	-	-	-	-	-
Vinyl acetate	NA	NA	NA	ND (0.03)	ND (0.012)	ND (5)	ND (0.64)	-	-	-	-	ND (0.68)	ND (0.66)	ND (1.9)	ND (1.9)	ND (6.5)	ND (0.0089)	ND (0.6)
Vinyl chloride	0.02	0.9	0.02	ND (0.003)	ND (0.0012)	ND (0.5)	ND (0.064)	ND (0.0011)	ND (0.088)	ND (0.079)	ND (0.086)	ND (0.068)	ND (0.066)	ND (0.19)	ND (0.19)	ND (0.65)	ND (0.00089)	ND (0.06)
Xylene (Total)	1.6	100	0.26	0.0026 J	0.0089	***180***	***5.3***	-	-	-	-	***2.1***	***6.9***	***190***	***250***	***270***	0.0017 J	***7.9***
Semi-Volatile Organic Compounds (mg/kg)																		
1,2,4,5-Tetrachlorobenzene	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
1,2,4-Trichlorobenzene	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	-	-	-	-	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
1,2-Dichlorobenzene	1.1	100	1.1	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	-	-	-	-	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
1,3-Dichlorobenzene	2.4	49	2.4	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	-	-	-	-	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
1,4-Dichlorobenzene	1.8	13	1.8	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	-	-	-	-	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
1,4-Dioxane	0.1	13	0.1	ND (0.026)	ND (0.026)	ND (0.026)	ND (0.027)	ND (0.033)	ND (0.034)	ND (0.033)	ND (0.033)	ND (0.027)	ND (0.027)	ND (0.13)	ND (0.13)	ND (0.14)	ND (0.028)	ND (0.027)
2,2'-oxybis(1-Chloropropane)	NA	NA	NA	ND (0.21)	ND (0.21)	ND (0.21)	ND (0.22)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.22)	ND (0.21)	ND (1.1)	ND (1.1)	ND (1.1)	ND (0.22)	ND (0.21)
2,3,4,6-Tetrachlorophenol	NA	NA	NA	-	-	-	-	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	-	-	-	-	-	-	-
2,4,5-Trichlorophenol	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
2,4,6-Trichlorophenol	NA	NA	NA	ND (0.1)	ND (0.1)	ND (0.1)	ND (0.11)	ND (0.13)	ND (0.14)	ND (0.13)	ND (0.13)	ND (0.11)	ND (0.11)	ND (0.53)	ND (0.53)	ND (0.54)	ND (0.11)	ND (0.11)
2,4-Dichlorophenol	NA	NA	NA	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.13)	ND (0.14)	ND (0.13)	ND (0.13)	ND (0.16)	ND (0.16)	ND (0.8)	ND (0.8)	ND (0.82)	ND (0.17)	ND (0.16)
2,4-Dimethylphenol	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
2,4-Dinitrophenol	NA	NA	NA	ND (0.84)	ND (0.84)	ND (0.83)	ND (0.87)	ND (0.27)	ND (0.27)	ND (0.27)	ND (0.27)	ND (0.86)	ND (0.86)	ND (4.3)	ND (4.3)	ND (4.4)	ND (0.89)	ND (0.85)
2,4-Dinitrotoluene	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
2,6-Dinitrotoluene	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
2-Chloronaphthalene	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
2-Chlorophenol	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
2-Methylnaphthalene	NA	NA	NA	0.044 J	0.16 J	9.1	0.034 J	ND (0.33)	ND (0.34)	0.31 J	0.051 J	0.15 J	1.1	6.4	6.2	9	ND (0.22)	5.2
2-Methylphenol (o-Cresol)	0.33	100	0.33	ND (0.18)	ND (0.18)	ND (0.17)	0.19	ND (0.33)	ND (0.34)	ND (0.33)	0.017 J	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
2-Nitroaniline	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
2-Nitrophenol	NA	NA	NA	ND (0.38)	ND (0.38)	ND (0.37)	ND (0.39)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.39)	ND (0.39)	ND (1.9)	ND (1.9)	ND (2)	ND (0.4)	ND (0.38)
3&4-Methylphenol	NA	NA	NA	ND (0.25)	ND (0.25)	ND (0.25)	0.26	-	-	-	-	ND (0.26)	ND (0.26)	ND (1.3)	ND (1.3)	0.44 J	ND (0.27)	ND (0.26)
3,3'-Dichlorobenzidine	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.13)	ND (0.14)	ND (0.13)	ND (0.13)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
3-Nitroaniline	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
4,6-Dinitro-2-methylphenol	NA	NA	NA	ND (0.46)	ND (0.46)	ND (0.45)	ND (0.47)	ND (0.27)	ND (0.27)	ND (0.27)	ND (0.27)	ND (0.47)	ND (0.46)	ND (2.3)	ND (2.3)	ND (2.4)	ND (0.48)	ND (0.46)
4-Bromophenyl phenyl ether (BDE-3)	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
4-Chloro-3-methylphenol	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
4-Chloroaniline	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
4-Chlorophenyl phenyl ether	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
4-Methylphenol	0.33	100	0.33	-	-	-	-	ND (0.33)	ND (0.34)	ND (0.33)	0.022 J	-	-	-	-	-	-	-
4-Nitroaniline	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
4-Nitrophenol	NA	NA	NA	ND (0.25)	ND (0.25)	ND (0.24)	ND (0.25)	ND (0.68)	ND (0.69)	ND (0.68)	ND (0.68)	ND (0.25)	ND (0.25)	ND (1.2)	ND (1.2)	ND (1.3)	ND (0.26)	ND (0.25)

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria																
Location Name	Restricted Use	NY Part 375	NY Part 375	HA-SB1	HA-SB1	HA-SB1	HA-SB1	HA-SB10	HA-SB10	HA-SB10	HA-SB10	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB12	HA-SB12
Sample Name	Soil Cleanup	Restricted	Unrestricted	HA-SB1_0-0.5	HA-SB1_6-8	HA-SB1_15-17	HA-SB1_38-40	HA-SB10_0-0.5	HA-SB10_5-7	HA-SB10_15-17	HA-SB10_43-45	HA-SB11_0-0.5	HA-SB11_4-6	HA-SB11_15-17	UP02_2025042	HA-SB11_40-42	HA-SB12_0-0.5	HA-SB12_8-10
Sample Date	Objectives -	Residential Use	Use	04/23/2025	04/23/2025	04/23/2025	04/23/2025	07/15/2025	07/15/2025	07/15/2025	07/15/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/14/2025	04/14/2025
Lab Sample ID	Protection of	Soil Cleanup	Soil Cleanup	L2525069-11	L2525069-12	L2525069-13	L2525069-14	460-330741-1	460-330741-2	460-330741-3	460-330741-4	L2525266-02	L2525266-03	L2525266-04	L2525266-05	L2525266-06	L2522786-07	L2522786-08
Sample Depth (bgs)	Groundwater	Objectives	Objectives	0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	38 - 40 (ft)	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	43 - 45 (ft)	0 - 0.5 (ft)	4 - 6 (ft)	15 - 17 (ft)	15 - 17 (ft)	40 - 42 (ft)	0 - 0.5 (ft)	8 - 10 (ft)
Acenaphthene	98	100	20	0.028 J	ND (0.14)	1.6	ND (0.14)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.14)	0.019 J	ND (0.71)	ND (0.71)	2.4	ND (0.15)	0.034 J
Acenaphthylene	107	100	100	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.14)	ND (0.14)	ND (0.71)	ND (0.71)	ND (0.73)	ND (0.15)	ND (0.14)
Acetophenone	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
Anthracene	1000	100	100	0.095 J	0.04 J	0.35	ND (0.11)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.11)	ND (0.11)	ND (0.53)	ND (0.53)	0.7	ND (0.11)	ND (0.11)
Atrazine	NA	NA	NA	-	-	-	-	ND (0.13)	ND (0.14)	ND (0.13)	ND (0.13)	-	-	-	-	-	-	-
Benzaldehyde	NA	NA	NA	-	-	-	-	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	-	-	-	-	-	-	-
Benzo(a)anthracene	1	1	1	0.18	0.11	0.12	ND (0.11)	ND (0.033)	ND (0.034)	ND (0.033)	ND (0.033)	ND (0.11)	ND (0.11)	ND (0.53)	ND (0.53)	0.78	0.11	ND (0.11)
Benzo(a)pyrene	22	1	1	0.16	0.096 J	0.044 J	ND (0.14)	0.0099 J	ND (0.034)	ND (0.033)	ND (0.033)	ND (0.14)	ND (0.14)	ND (0.71)	ND (0.71)	0.31 J	0.13 J	ND (0.14)
Benzo(b)fluoranthene	1.7	1	1	0.22	0.13	0.066 J	ND (0.11)	0.013 J	ND (0.034)	ND (0.033)	ND (0.033)	ND (0.11)	ND (0.11)	ND (0.53)	ND (0.53)	0.51 J	0.15	ND (0.11)
Benzo(g,h,i)perylene	1000	100	100	0.1 J	0.077 J	ND (0.14)	ND (0.14)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.14)	ND (0.14)	ND (0.71)	ND (0.71)	ND (0.73)	0.099 J	ND (0.14)
Benzo(k)fluoranthene	1.7	3.9	0.8	0.058 J	0.039 J	ND (0.1)	ND (0.11)	ND (0.033)	ND (0.034)	ND (0.033)	ND (0.033)	ND (0.11)	ND (0.11)	ND (0.53)	ND (0.53)	0.14 J	0.057 J	ND (0.11)
Benzoic acid	NA	NA	NA	ND (0.57)	ND (0.57)	ND (0.56)	ND (0.59)	-	-	-	-	ND (0.58)	ND (0.58)	ND (2.9)	ND (2.9)	ND (2.9)	ND (0.6)	ND (0.58)
Benzyl Alcohol	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	-	-	-	-	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
Biphenyl	NA	NA	NA	ND (0.4)	ND (0.4)	0.44	ND (0.41)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.41)	ND (0.41)	ND (2)	ND (2)	0.52 J	ND (0.42)	0.12 J
bis(2-Chloroethoxy)methane	NA	NA	NA	ND (0.19)	ND (0.19)	ND (0.19)	ND (0.2)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.19)	ND (0.19)	ND (0.96)	ND (0.96)	ND (0.98)	ND (0.2)	ND (0.19)
bis(2-Chloroethyl)ether	NA	NA	NA	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.033)	ND (0.034)	ND (0.033)	ND (0.033)	ND (0.16)	ND (0.16)	ND (0.8)	ND (0.8)	ND (0.82)	ND (0.17)	ND (0.16)
bis(2-Ethylhexyl)phthalate	NA	NA	NA	ND (0.18)	ND (0.18)	0.064 J	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	0.42	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
Butyl benzylphthalate (BBP)	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
Caprolactam	NA	NA	NA	-	-	-	-	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	-	-	-	-	-	-	-
Carbazole	NA	NA	NA	0.052 J	ND (0.18)	0.44	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	0.38 J	0.018 J	ND (0.18)
Chrysene	1	3.9	1	0.16	0.14	0.098 J	ND (0.11)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.11)	ND (0.11)	ND (0.53)	ND (0.53)	0.41 J	0.1 J	ND (0.11)
Dibenz(a,h)anthracene	1000	0.33	0.33	0.025 J	ND (0.1)	ND (0.1)	ND (0.11)	ND (0.033)	ND (0.034)	ND (0.033)	ND (0.033)	ND (0.11)	ND (0.11)	ND (0.53)	ND (0.53)	ND (0.54)	ND (0.11)	ND (0.11)
Dibenzofuran	210	59	7	0.03 J	ND (0.18)	1.1	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	1.6	ND (0.18)	ND (0.18)
Diethyl phthalate	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
Dimethyl phthalate	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
Di-n-butylphthalate (DBP)	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
Di-n-octyl phthalate (DnOP)	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
Fluoranthene	1000	100	100	0.41	0.21	0.96	ND (0.11)	0.02 J	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.11)	0.049 J	ND (0.53)	ND (0.53)	3.6	0.17	0.022 J
Fluorene	386	100	30	0.039 J	0.027 J	1.3	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	0.023 J	ND (0.89)	ND (0.89)	1.9	ND (0.18)	0.06 J
Hexachlorobenzene	3.2	1.2	0.33	ND (0.1)	ND (0.1)	ND (0.1)	ND (0.11)	ND (0.033)	ND (0.034)	ND (0.033)	ND (0.033)	ND (0.11)	ND (0.11)	ND (0.53)	ND (0.53)	ND (0.54)	ND (0.11)	ND (0.11)
Hexachlorobutadiene	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
Hexachlorocyclopentadiene	NA	NA	NA	ND (0.5)	ND (0.5)	ND (0.49)	ND (0.52)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.51)	ND (0.51)	ND (2.5)	ND (2.5)	ND (2.6)	ND (0.53)	ND (0.51)
Hexachloroethane	NA	NA	NA	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.033)	ND (0.034)	ND (0.033)	ND (0.033)	ND (0.14)	ND (0.14)	ND (0.71)	ND (0.71)	ND (0.73)	ND (0.15)	ND (0.14)
Indeno(1,2,3-cd)pyrene	8.2	0.5	0.5	0.1 J	0.066 J	ND (0.14)	ND (0.14)	ND (0.033)	ND (0.034)	ND (0.033)	ND (0.033)	ND (0.14)	ND (0.14)	ND (0.71)	ND (0.71)	ND (0.73)	0.084 J	ND (0.14)
Isophorone	NA	NA	NA	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.13)	ND (0.14)	ND (0.13)	ND (0.13)	ND (0.16)	ND (0.16)	ND (0.8)	ND (0.8)	ND (0.82)	ND (0.17)	ND (0.16)
Naphthalene	12	100	12	0.054 J	0.21	***18***	0.055 J	ND (0.33)	ND (0.34)	0.34	0.057 J	ND (0.18)	ND (0.18)	8.8	8.5	***14***	0.039 J	4.1
Nitrobenzene	NA	NA	NA	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.033)	ND (0.034)	ND (0.033)	ND (0.033)	ND (0.16)	ND (0.16)	ND (0.8)	ND (0.8)	ND (0.82)	ND (0.17)	ND (0.16)
N-Nitrosodi-n-propylamine	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.033)	ND (0.034)	ND (0.033)	ND (0.033)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
N-Nitrosodiphenylamine	NA	NA	NA	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.14)	ND (0.14)	ND (0.71)	ND (0.71)	ND (0.73)	ND (0.15)	ND (0.14)
Pentachlorophenol	0.8	6.7	0.8	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.27)	ND (0.27)	ND (0.27)	ND (0.27)	ND (0.14)	ND (0.14)	ND (0.71)	ND (0.71)	ND (0.73)	ND (0.15)	ND (0.14)
Phenanthrene	1000	100	100	0.39	0.15	2.5	ND (0.11)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.11)	0.073 J	0.11 J	ND (0.53)	6.5	0.099 J	0.077 J
Phenol	0.33	100	0.33	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.33)	ND (0.34)	ND (0.33)	ND (0.33)	ND (0.18)	ND (0.18)	ND (0.89)	ND (0.89)	ND (0.91)	ND (0.18)	ND (0.18)
Pyrene	1000	100	100	0.33	0.23	0.62	ND (0.11)	0.019 J	ND (0.34)	ND (0.33)	ND (0.33)	0.052 J	0.046 J	ND (0.53)	ND (0.53)	2.5	0.16	0.03 J

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria																
Location Name	Restricted Use	NY Part 375	NY Part 375	HA-SB1	HA-SB1	HA-SB1	HA-SB1	HA-SB10	HA-SB10	HA-SB10	HA-SB10	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB12	HA-SB12
Sample Name	Soil Cleanup	Restricted	Unrestricted	HA-SB1_0-0.5	HA-SB1_6-8	HA-SB1_15-17	HA-SB1_38-40	HA-SB10_0-0.5	HA-SB10_5-7	HA-SB10_15-17	HA-SB10_43-45	HA-SB11_0-0.5	HA-SB11_4-6	HA-SB11_15-17	UP02_2025042	HA-SB11_40-42	HA-SB12_0-0.5	HA-SB12_8-10
Sample Date	Objectives -	Residential Use	Use	04/23/2025	04/23/2025	04/23/2025	04/23/2025	07/15/2025	07/15/2025	07/15/2025	07/15/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/14/2025	04/14/2025
Lab Sample ID	Protection of	Soil Cleanup	Soil Cleanup	L2525069-11	L2525069-12	L2525069-13	L2525069-14	460-330741-1	460-330741-2	460-330741-3	460-330741-4	L2525266-02	L2525266-03	L2525266-04	L2525266-05	L2525266-06	L2522786-07	L2522786-08
Sample Depth (bgs)	Groundwater	Objectives	Objectives	0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	38 - 40 (ft)	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	43 - 45 (ft)	0 - 0.5 (ft)	4 - 6 (ft)	15 - 17 (ft)	15 - 17 (ft)	40 - 42 (ft)	0 - 0.5 (ft)	8 - 10 (ft)
PFAS (mg/kg)																		
11-Chloroeicosafluoro-3-Oxaundecane-1-Sulfonic Acid (11Cl-PF3OUdS)	NA	NA	NA	-	-	-	-	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	-	-	-	-	-	ND (0.0008)	ND (0.000798)
2H,2H,3H,3H-Perfluorooctanoic acid (5:3 FTCA)	NA	NA	NA	ND (0.005)	ND (0.00499)	ND (0.005)	ND (0.00499)	ND (0.00102)	ND (0.00107)	ND (0.00097)	ND (0.001)	ND (0.005)	ND (0.00499)	ND (0.005)	ND (0.005)	ND (0.00499)	ND (0.005)	ND (0.00499)
3-(Perfluoroheptyl)propanoic acid (7:3 FTCA)	NA	NA	NA	ND (0.005)	ND (0.00499)	ND (0.005)	ND (0.00499)	ND (0.00102)	ND (0.00107)	ND (0.00097)	ND (0.001)	ND (0.005)	ND (0.00499)	ND (0.005)	ND (0.005)	ND (0.00499)	ND (0.005)	ND (0.00499)
3:3 Fluorotelomer carboxylic acid (3:3 FTCA)	NA	NA	NA	ND (0.001)	ND (0.000998)	ND (0.001)	ND (0.000998)	ND (0.00041)	ND (0.00043)	ND (0.00039)	ND (0.0004)	ND (0.001)	ND (0.000998)	ND (0.001)	ND (0.001)	ND (0.000999)	ND (0.001)	ND (0.000998)
4,8-Dioxa-3H-Perfluorononanoic Acid (ADONA)	NA	NA	NA	ND (0.0008)	ND (0.000798)	ND (0.0008)	ND (0.000798)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0008)	ND (0.000799)	ND (0.000801)	ND (0.0008)	ND (0.000799)	ND (0.0008)	ND (0.000798)
4:2 Fluorotelomer sulfonic acid (4:2 FTS)	NA	NA	NA	ND (0.0008)	ND (0.000798)	ND (0.0008)	ND (0.000798)	ND (0.00041)	ND (0.00043)	ND (0.00039)	ND (0.0004)	ND (0.0008)	ND (0.000799)	ND (0.000801)	ND (0.0008)	ND (0.000799)	ND (0.0008)	ND (0.000798)
6:2 Fluorotelomer sulfonic acid (6:2 FTS)	NA	NA	NA	ND (0.0008)	ND (0.000798)	ND (0.0008)	ND (0.000798)	ND (0.00041)	ND (0.00043)	ND (0.00039)	ND (0.0004)	ND (0.0008)	ND (0.000799)	ND (0.000801)	ND (0.0008)	ND (0.000799)	ND (0.0008)	ND (0.000798)
8:2 Fluorotelomer sulfonic acid (8:2 FTS)	NA	NA	NA	ND (0.0008)	ND (0.000798)	ND (0.0008)	ND (0.000798)	ND (0.00041)	ND (0.00043)	ND (0.00039)	ND (0.0004)	ND (0.0008)	ND (0.000799)	ND (0.000801)	ND (0.0008)	ND (0.000799)	ND (0.0008)	ND (0.000798)
9-Chlorohexadecafluoro-3-Oxanone-1-Sulfonic Acid (9Cl-PF3ONS)	NA	NA	NA	-	-	-	-	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	-	-	-	-	-	ND (0.0008)	ND (0.000798)
N-Ethyl Perfluorooctanesulfonamidoacetic Acid (NEtFOSAA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000074 J	ND (0.00019)	ND (0.0002)	0.000073 J	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
N-Ethylperfluorooctane sulfonamide (N-EtFOSA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
N-Ethylperfluorooctane sulfonamidoethanol (N-EtFOSE)	NA	NA	NA	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.00102)	ND (0.00107)	ND (0.00097)	ND (0.001)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)
N-Methyl Perfluorooctanesulfonamidoacetic Acid (MeFOSAA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
N-Methylperfluorooctane sulfonamide (N-MeFOSA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
N-Methylperfluorooctane sulfonamidoethanol (N-MeFOSE)	NA	NA	NA	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.00102)	ND (0.00107)	ND (0.00097)	ND (0.001)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)
Nonafluoro-3,6-dioxaheptanoic acid (NFDHA)	NA	NA	NA	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.000399)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.000399)
Perfluoro(2-ethoxyethane) sulphonic acid (PFEESA)	NA	NA	NA	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.000399)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.000399)
Perfluoro(4-methoxybutanoic) acid (PFMBA)	NA	NA	NA	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.000399)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.000399)
Perfluoro-2-propoxypropanoic acid (PFPrOPrA)(GenX) (HFPO-DA)	NA	NA	NA	ND (0.0008)	ND (0.000798)	ND (0.0008)	ND (0.000798)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0008)	ND (0.000799)	ND (0.000801)	ND (0.0008)	ND (0.000799)	ND (0.0008)	ND (0.000798)
Perfluoro-3-methoxypropanoic acid (PFMPA)	NA	NA	NA	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.000399)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.000399)
Perfluorobutanesulfonic acid (PFBS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000022 JF	ND (0.0002)
Perfluorobutanoic acid (PFBA)	NA	NA	NA	0.000032 J	ND (0.000798)	ND (0.0008)	ND (0.000798)	ND (0.00041)	ND (0.00043)	ND (0.00039)	ND (0.0004)	ND (0.0008)	0.000029 J	ND (0.000801)	ND (0.0008)	ND (0.000799)	0.000038 J	ND (0.000798)
Perfluorodecanesulfonic acid (PFDS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
Perfluorodecanoic acid (PFDA)	NA	NA	NA	0.00005 J	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
Perfluorododecane sulfonic acid (PFDoDS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
Perfluorododecanoic acid (PFDoDA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
Perfluoroheptanesulfonic acid (PFHpS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
Perfluoroheptanoic acid (PFHpA)	NA	NA	NA	0.000035 J	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000018 J	ND (0.0002)
Perfluorohexanesulfonic acid (PFHxS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
Perfluorohexanoic acid (PFHxA)	NA	NA	NA	0.000056 J	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000038 JF	ND (0.0002)
Perfluorononane sulfonic acid (PFNS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
Perfluorononanoic acid (PFNA)	NA	NA	NA	0.000048 J	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000021 J	ND (0.0002)
Perfluorooctane sulfonamide (PFOSA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
Perfluorooctanesulfonic acid (PFOS)	0.001	0.044	0.00088	0.000277	0.000153 J	ND (0.0002)	ND (0.0002)	0.000051 J	0.00017 J	ND (0.00019)	ND (0.0002)	0.000063 J	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000098 J	ND (0.0002)
Perfluorooctanoic acid (PFOA)	0.0008	0.033	0.00066	0.000102 J	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	0.000028 J	0.000038 J	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000042 J	ND (0.0002)
Perfluoropentanesulfonic acid (PFPeS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
Perfluoropentanoic acid (PFPeA)	NA	NA	NA	0.00007 J	ND (0.000399)	ND (0.0004)	ND (0.000399)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.0004)	ND (0.000399)	0.000059 J	ND (0.000399)
Perfluorotetradecanoic acid (PFTeDA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
Perfluorotridecanoic acid (PFTrDA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)
Perfluoroundecanoic acid (PFUnDA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.00021)	ND (0.00019)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria																	
Location Name	Restricted Use	NY Part 375	NY Part 375	HA-SB1	HA-SB1	HA-SB1	HA-SB1	HA-SB10	HA-SB10	HA-SB10	HA-SB10	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB12	HA-SB12
Sample Name	Soil Cleanup	Restricted	Unrestricted	HA-SB1_0-0.5	HA-SB1_6-8	HA-SB1_15-17	HA-SB1_38-40	HA-SB10_0-0.5	HA-SB10_5-7	HA-SB10_15-17	HA-SB10_43-45	HA-SB11_0-0.5	HA-SB11_4-6	HA-SB11_15-17	UP02_2025042	HA-SB11_40-42	HA-SB12_0-0.5	HA-SB12_8-10
Sample Date	Objectives -	Residential Use	Use	04/23/2025	04/23/2025	04/23/2025	04/23/2025	07/15/2025	07/15/2025	07/15/2025	07/15/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/14/2025	04/14/2025
Lab Sample ID	Protection of	Soil Cleanup	Soil Cleanup	L2525069-11	L2525069-12	L2525069-13	L2525069-14	460-330741-1	460-330741-2	460-330741-3	460-330741-4	L2525266-02	L2525266-03	L2525266-04	L2525266-05	L2525266-06	L2522786-07	L2522786-08
Sample Depth (bgs)	Groundwater	Objectives	Objectives	0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	38 - 40 (ft)	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	43 - 45 (ft)	0 - 0.5 (ft)	4 - 6 (ft)	15 - 17 (ft)	15 - 17 (ft)	40 - 42 (ft)	0 - 0.5 (ft)	8 - 10 (ft)
Pesticides (mg/kg)																		
4,4'-DDD	14	13	0.0033	ND (0.0017)	ND (0.00164)	ND (0.00161)	ND (0.0017)	ND (0.0068)	ND (0.0069)	ND (0.0068)	ND (0.0068)	ND (0.00168)	ND (0.00173)	ND (0.00168)	ND (0.00172)	ND (0.00175)	ND (0.00176)	ND (0.00171)
4,4'-DDE	17	8.9	0.0033	0.00382	ND (0.00164)	ND (0.00161)	ND (0.0017)	ND (0.0068)	ND (0.0069)	ND (0.0068)	ND (0.0068)	ND (0.00168)	ND (0.00173)	ND (0.00168)	ND (0.00172)	ND (0.00175)	ND (0.00176)	ND (0.00171)
4,4'-DDT	136	7.9	0.0033	ND (0.0017)	ND (0.00164)	ND (0.00161)	ND (0.0017)	ND (0.0068)	ND (0.0069)	ND (0.0068)	ND (0.0068)	ND (0.00168)	ND (0.00173)	ND (0.00168)	ND (0.00172)	ND (0.00175)	ND (0.00176)	ND (0.00171)
Aldrin	0.19	0.097	0.005	ND (0.0017)	ND (0.00164)	ND (0.00161)	ND (0.0017)	ND (0.0068)	ND (0.0069)	ND (0.0068)	ND (0.0068)	ND (0.00168)	ND (0.00173)	ND (0.00168)	ND (0.00172)	ND (0.00175)	ND (0.00176)	ND (0.00171)
alpha-BHC	0.02	0.48	0.02	ND (0.000708)	ND (0.000686)	ND (0.000673)	ND (0.000707)	ND (0.002)	ND (0.0021)	ND (0.002)	ND (0.002)	0.00171 P	ND (0.000722)	ND (0.000702)	ND (0.000715)	ND (0.000728)	ND (0.000734)	ND (0.000713)
alpha-Chlordane (cis)	2.9	4.2	0.094	0.00307	ND (0.00206)	ND (0.00202)	ND (0.00212)	-	-	-	-	ND (0.0021)	ND (0.00216)	ND (0.00211)	ND (0.00214) IP	ND (0.00218) IP	ND (0.0022)	ND (0.00214)
beta-BHC	0.09	0.36	0.036	ND (0.0017)	ND (0.00164)	ND (0.00161)	ND (0.0017)	ND (0.002)	ND (0.0021)	ND (0.002)	ND (0.002)	ND (0.00168)	ND (0.00173)	ND (0.00168)	ND (0.00172)	ND (0.00175)	ND (0.00176)	ND (0.00171)
Chlordane	NA	NA	NA	0.0346	ND (0.0137)	ND (0.0134)	ND (0.0141)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.014)	ND (0.0144)	ND (0.014)	ND (0.0143)	ND (0.0146)	ND (0.0147)	ND (0.0142)
delta-BHC	0.25	100	0.04	ND (0.0017)	ND (0.00164)	ND (0.00161)	ND (0.0017)	ND (0.002)	ND (0.0021)	ND (0.002)	ND (0.002)	ND (0.00168)	ND (0.00173)	ND (0.00168)	ND (0.00172)	ND (0.00175)	ND (0.00176)	ND (0.00171)
Dieldrin	0.1	0.2	0.005	ND (0.00106)	ND (0.00103)	ND (0.00101)	ND (0.00106)	ND (0.002)	ND (0.0021)	ND (0.002)	ND (0.002)	ND (0.00105)	ND (0.00108)	ND (0.00105)	ND (0.00107)	ND (0.00109)	ND (0.0011)	ND (0.00107)
Endosulfan I	102	24	2.4	ND (0.0017)	ND (0.00164)	ND (0.00161)	ND (0.0017)	ND (0.0068)	ND (0.0069)	ND (0.0068)	ND (0.0068)	ND (0.00168)	ND (0.00173)	ND (0.00168)	ND (0.00172)	ND (0.00175)	ND (0.00176)	ND (0.00171)
Endosulfan II	102	24	2.4	ND (0.0017)	ND (0.00164)	ND (0.00161)	ND (0.0017)	ND (0.0068)	ND (0.0069)	ND (0.0068)	ND (0.0068)	ND (0.00168)	ND (0.00173)	ND (0.00168)	ND (0.00172)	ND (0.00175)	ND (0.00176)	ND (0.00171)
Endosulfan sulfate	1000	24	2.4	ND (0.000708)	ND (0.000686)	ND (0.000673)	ND (0.000707)	ND (0.0068)	ND (0.0069)	ND (0.0068)	ND (0.0068)	ND (0.0007)	ND (0.000722)	ND (0.000702)	ND (0.000715)	ND (0.000728)	ND (0.000734)	ND (0.000713)
Endrin	0.06	11	0.014	ND (0.000708)	ND (0.000686)	ND (0.000673)	ND (0.000707)	ND (0.0068)	ND (0.0069)	ND (0.0068)	ND (0.0068)	ND (0.0007)	ND (0.000722)	ND (0.000702)	ND (0.000715)	ND (0.000728)	ND (0.000734)	ND (0.000713)
Endrin aldehyde	NA	NA	NA	ND (0.00212)	ND (0.00206)	ND (0.00202)	ND (0.00212)	ND (0.0068)	ND (0.0069)	ND (0.0068)	ND (0.0068)	ND (0.0021)	ND (0.00216)	ND (0.00211)	ND (0.00214)	ND (0.00218)	ND (0.0022)	ND (0.00214)
Endrin ketone	NA	NA	NA	ND (0.0017)	ND (0.00164)	ND (0.00161)	ND (0.0017)	ND (0.0068)	ND (0.0069)	ND (0.0068)	ND (0.0068)	ND (0.00168)	ND (0.00173)	ND (0.00168)	ND (0.00172)	ND (0.00175)	ND (0.00176)	ND (0.00171)
gamma-BHC (Lindane)	0.1	1.3	0.1	ND (0.000708)	ND (0.000686)	ND (0.000673)	ND (0.000707)	ND (0.002)	ND (0.0021)	ND (0.002)	ND (0.002)	0.00377 P	ND (0.000722)	ND (0.000702)	ND (0.000715)	ND (0.000728)	ND (0.000734)	ND (0.000713)
gamma-Chlordane (trans)	NA	NA	NA	0.0025 IP	ND (0.00206)	ND (0.00202)	ND (0.00212)	-	-	-	-	ND (0.0021)	ND (0.00216)	ND (0.00211)	ND (0.00214)	ND (0.00218)	ND (0.0022)	ND (0.00214)
Heptachlor	0.38	2.1	0.042	ND (0.00085)	ND (0.000823)	ND (0.000807)	ND (0.000849)	ND (0.0068)	ND (0.0069)	ND (0.0068)	ND (0.0068)	ND (0.00084)	ND (0.000866)	ND (0.000842)	ND (0.000858)	ND (0.000874)	ND (0.000881)	ND (0.000856)
Heptachlor epoxide	NA	NA	NA	ND (0.00319)	ND (0.00308)	ND (0.00303)	ND (0.00318)	ND (0.0068)	ND (0.0069)	ND (0.0068)	ND (0.0068)	ND (0.00315)	ND (0.00325)	ND (0.00316)	ND (0.00322)	ND (0.00328)	ND (0.0033)	ND (0.00321)
Methoxychlor	NA	NA	NA	ND (0.00319)	ND (0.00308)	ND (0.00303)	ND (0.00318)	ND (0.0068)	ND (0.0069)	ND (0.0068)	ND (0.0068)	ND (0.00315)	ND (0.00325)	ND (0.00316)	ND (0.00322)	ND (0.00328)	ND (0.0033)	ND (0.00321)
Toxaphene	NA	NA	NA	ND (0.0319)	ND (0.0308)	ND (0.0303)	ND (0.0318)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.0315)	ND (0.0325)	ND (0.0316)	ND (0.0322)	ND (0.0328)	ND (0.033)	ND (0.0321)
Polychlorinated Biphenyls (mg/kg)																		
Aroclor-1016 (PCB-1016)	NA	NA	NA	ND (0.0503)	ND (0.0521)	ND (0.0514)	ND (0.0545)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.0527)	ND (0.0539)	ND (0.0545)	ND (0.0518)	ND (0.0549)	ND (0.0511)	ND (0.0535)
Aroclor-1221 (PCB-1221)	NA	NA	NA	ND (0.0503)	ND (0.0521)	ND (0.0514)	ND (0.0545)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.0527)	ND (0.0539)	ND (0.0545)	ND (0.0518)	ND (0.0549)	ND (0.0511)	ND (0.0535)
Aroclor-1232 (PCB-1232)	NA	NA	NA	ND (0.0503)	ND (0.0521)	ND (0.0514)	ND (0.0545)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.0527)	ND (0.0539)	ND (0.0545)	ND (0.0518)	ND (0.0549)	ND (0.0511)	ND (0.0535)
Aroclor-1242 (PCB-1242)	NA	NA	NA	ND (0.0503)	ND (0.0521)	ND (0.0514)	ND (0.0545)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.0527)	ND (0.0539)	ND (0.0545)	ND (0.0518)	ND (0.0549)	ND (0.0511)	ND (0.0535)
Aroclor-1248 (PCB-1248)	NA	NA	NA	ND (0.0503)	ND (0.0521)	ND (0.0514)	ND (0.0545)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.0527)	ND (0.0539)	ND (0.0545)	ND (0.0518)	ND (0.0549)	ND (0.0511)	ND (0.0535)
Aroclor-1254 (PCB-1254)	NA	NA	NA	ND (0.0503)	ND (0.0521)	ND (0.0514)	ND (0.0545)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.0527)	ND (0.0539)	ND (0.0545)	ND (0.0518)	ND (0.0549)	ND (0.0511)	ND (0.0535)
Aroclor-1260 (PCB-1260)	NA	NA	NA	0.0791	0.0912	0.0152 J	ND (0.0545)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.0527)	ND (0.0539)	ND (0.0545)	ND (0.0518)	ND (0.0549)	ND (0.0511)	ND (0.0535)
Aroclor-1262 (PCB-1262)	NA	NA	NA	ND (0.0503)	ND (0.0521)	ND (0.0514)	ND (0.0545)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.0527)	ND (0.0539)	ND (0.0545)	ND (0.0518)	ND (0.0549)	ND (0.0511)	ND (0.0535)
Aroclor-1268 (PCB-1268)	NA	NA	NA	ND (0.0503)	ND (0.0521)	ND (0.0514)	ND (0.0545)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.0527)	ND (0.0539)	ND (0.0545)	ND (0.0518)	ND (0.0549)	ND (0.0511)	ND (0.0535)
Polychlorinated biphenyls (PCBs)	3.2	1	0.1	0.0791	0.0912	0.0152 J	ND (0.0545)	ND (0.068)	ND (0.069)	ND (0.068)	ND (0.068)	ND (0.0527)	ND (0.0539)	ND (0.0545)	ND (0.0518)	ND (0.0549)	ND (0.0511)	ND (0.0535)

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria																
Location Name	Restricted Use	NY Part 375	NY Part 375	HA-SB1	HA-SB1	HA-SB1	HA-SB1	HA-SB10	HA-SB10	HA-SB10	HA-SB10	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB12	HA-SB12
Sample Name	Soil Cleanup	Restricted	Unrestricted	HA-SB1_0-0.5	HA-SB1_6-8	HA-SB1_15-17	HA-SB1_38-40	HA-SB10_0-0.5	HA-SB10_5-7	HA-SB10_15-17	HA-SB10_43-45	HA-SB11_0-0.5	HA-SB11_4-6	HA-SB11_15-17	UP02_2025042	HA-SB11_40-42	HA-SB12_0-0.5	HA-SB12_8-10
Sample Date	Objectives -	Residential Use	Use	04/23/2025	04/23/2025	04/23/2025	04/23/2025	07/15/2025	07/15/2025	07/15/2025	07/15/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/14/2025	04/14/2025
Lab Sample ID	Protection of	Soil Cleanup	Soil Cleanup	L2525069-11	L2525069-12	L2525069-13	L2525069-14	460-330741-1	460-330741-2	460-330741-3	460-330741-4	L2525266-02	L2525266-03	L2525266-04	L2525266-05	L2525266-06	L2522786-07	L2522786-08
Sample Depth (bgs)	Groundwater	Objectives	Objectives	0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	38 - 40 (ft)	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	43 - 45 (ft)	0 - 0.5 (ft)	4 - 6 (ft)	15 - 17 (ft)	15 - 17 (ft)	40 - 42 (ft)	0 - 0.5 (ft)	8 - 10 (ft)
Inorganic Compounds (mg/kg)																		
Aluminum	NA	NA	NA	4360	3880	5490	3870	4920	1000	5830	4330	3580	5330	3970	3670	4210	4640	7200
Antimony	NA	NA	NA	ND (4.09)	ND (4.11)	ND (4.09)	ND (4.27)	0.91	0.16 J	0.12 J	ND (0.81)	ND (4.2)	ND (4.25)	ND (4.31)	ND (4.15)	ND (4.2)	ND (4.25)	ND (4.18)
Arsenic	16	16	13	4.63	2.38	3.33	1.87	2.8	1.2	3.2	1.6	2.18	2.49	2.11	1.91	2.33	3.99	3.13
Barium	820	400	350	86.6	72.8	45.9	37.9	153	58.6	22	34.8	22.9	40.5	43.9	35.8	48.2	59.1	62.8
Beryllium	47	72	7.2	0.535	0.383 J	0.468	0.385 J	0.33	0.049 J	0.37	0.33	0.196 J	0.518	0.429 J	0.407 J	0.411 J	0.374 J	0.443
Cadmium	7.5	4.3	2.5	0.716 J	0.202 J	0.185 J	0.086 J	0.32 J	ND (0.8)	ND (0.8)	ND (0.81)	0.047 J	0.13 J	0.131 J	0.098 J	0.392 J	0.077 J	0.187 J
Calcium	NA	NA	NA	36800	1890	5190	6440	54300	267	1010	3480	12800	8170	1230	1240	6970	36400	1700
Chromium	NA	NA	NA	12.7	9.02	21.1	11.5	12.1	40.5	32.8	18	6.66	11.9	9.99	9.07	15.4	10.7	17.3
Cobalt	NA	NA	NA	5.32	4.15	6	4.48	4.1	0.44 J	4.3	3.9	2.71	4.88	4.84	4.34	4.68	4.11	5.71
Copper	1720	270	50	38	13.9	15	10.3	19.4	1.6	12.6	10.3	9.15	12.5	11.7	9.93	12.3	22.4	14
Iron	NA	NA	NA	9300	7910	11400	8500	10200	2640	13800	9800	4980	9200	10500	8270	9820	10200	14100
Lead	450	400	63	124	55.2	23.8	7.7	81.9	2.4	9.3	6.4	20.3	12.6	18.3	17.7	16	55.3	5.98
Magnesium	NA	NA	NA	6410	2490	4040	2650	25000	274	2330	2600	2410	3150	2420	2330	2850	6620	4300
Manganese	2000	2000	1600	214	132	218	217	155	28	129	225	108	355	358	283	236	254	396
Mercury	0.73	0.81	0.18	0.111	0.095	ND (0.075)	ND (0.078)	0.1	ND (0.016)	ND (0.017)	ND (0.017)	ND (0.072)	ND (0.07)	ND (0.078)	ND (0.073)	ND (0.072)	0.084	ND (0.082)
Nickel	130	310	30	13.4	9.75	12.9	8.11	12.4	1.1 J	18.9	13.4	16.6	11.4	13.2	11.5	13.2	10.8	14.8
Potassium	NA	NA	NA	952	1040	1660	1210	967	529	1170	1100	375	1400	860	864	1120	820	2270
Selenium	4	180	3.9	ND (1.64)	ND (1.64)	ND (1.63)	ND (1.71)	0.22 J	ND (1)	ND (1)	ND (1)	ND (1.68)	ND (1.7)	ND (1.72)	ND (1.66)	ND (1.68)	ND (1.7)	ND (1.67)
Silver	8.3	180	2	ND (0.409)	ND (0.411)	ND (0.409)	ND (0.427)	0.077 J	ND (0.32)	ND (0.32)	ND (0.33)	ND (0.42)	ND (0.425)	ND (0.431)	ND (0.415)	ND (0.42)	ND (0.425)	ND (0.418)
Sodium	NA	NA	NA	879	682	878	348	206	291	458	310	219	502	376	343	478	589	808
Thallium	NA	NA	NA	ND (1.64)	ND (1.64)	ND (1.63)	ND (1.71)	0.077 J	ND (0.32)	0.072 J	0.059 J	ND (1.68)	ND (1.7)	ND (1.72)	ND (1.66)	ND (1.68)	ND (1.7)	ND (1.67)
Vanadium	NA	NA	NA	14.6	14.5	20.3	14.7	18.9	6	20	15	8.81	16.7	15.3	13.8	14.9	15.8	22.2
Zinc	2480	10000	109	257	67.5	48.1	25.2	85.4	2.4 J	26	22.6	28.8	39.4	26.9	26.1	51.4	59.8	34.7
Other																		
Total Solids (%)	NA	NA	NA	92.9	92.3	93.6	90.8	-	-	-	-	92.2	91.4	91.3	92.1	90.7	89.8	92.1

ABBREVIATIONS AND NOTES:

mg/kg: milligram per kilogram

**: LCS or LCSD is outside acceptance limits.*
-: Not Analyzed
bgs: below ground surface
F: Results are considered to be an estimated maximum concentration
ft: feet
I: The lower value for the two columns has been reported due to obvious interference.
J: Value is estimated.
NA: Not Applicable
ND (2.5): Not detected, number in parentheses is the laboratory reporting limit
P: The RPD between the results for the two columns exceeds the method-specified criteria.

- For test methods used, see the laboratory data sheets.
- Soil analytical results are compared to the New York State Department of Environmental Conservation (NYSDEC) Title 6 of the Official Compilation of New York Codes, Rules, and Regulations (NYCRR) Part 375 Unrestricted Use Soil Cleanup Objectives (SCO), Restricted-Use Residential SCOs, and Protection of Groundwater SCO's.
*- **Bold italic** values indicate an exceedance of the Protection of Groundwater Criteria.*
- Grey shading indicates an exceedance of the Unrestricted Use Soil Cleanup Objectives.
- Yellow shading indicates an exceedance of the Restricted Use Residential Soil Cleanup Objectives.

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria																	
Location Name	Restricted Use	NY Part 375	NY Part 375	HA-SB12	HA-SB12	HA-SB2	HA-SB2	HA-SB5	HA-SB5	HA-SB5	HA-SB5	HA-SB6	HA-SB6	HA-SB6	HA-SB6	HA-SB8	HA-SB8
Sample Name	Soil Cleanup	Restricted	Unrestricted	HA-SB12_15-17	HA-SB12_46-48	HA-SB2_0-0.5	HA-SB2_3-5	HA-SB5_0-0.5	HA-SB5_3-5	HA-SB5_15-17	HA-SB5_48-50	HA-SB6_0-0.5	HA-SB6_6-8	HA-SB6_15-17	HA-SB6_28-40	HA-SB8_0-0.5	HA-SB8_3-5
Sample Date	Objectives -	Residential Use	Use	04/14/2025	04/14/2025	04/24/2025	04/24/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/15/2025	04/15/2025
Lab Sample ID	Protection of	Soil Cleanup	Soil Cleanup	L2522786-09	L2522786-10	L2525266-07	L2525266-08	L2525069-03	L2525069-04	L2525069-05	L2525069-06	L2525069-07	L2525069-08	L2525069-09	L2525069-10	L2523120-01	L2523120-02
Sample Depth (bgs)	Groundwater	Objectives	Objectives	15 - 17 (ft)	46 - 48 (ft)	0 - 0.5 (ft)	3 - 5 (ft)	0 - 0.5 (ft)	3 - 5 (ft)	15 - 17 (ft)	48 - 50 (ft)	0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	28 - 40 (ft)	0 - 0.5 (ft)	3 - 5 (ft)
Volatile Organic Compounds (mg/kg)																	
1,1,1,2-Tetrachloroethane	NA	NA	NA	ND (0.028)	ND (0.00044)	ND (0.00076)	ND (0.00051) ND (0.00055)	ND (0.00048)	ND (0.00084)	ND (0.00062)	ND (0.00053)	ND (0.00071)	ND (0.00052)	ND (0.00045)	ND (0.026)	ND (0.00049)	ND (0.00046)
1,1,1-Trichloroethane	0.68	100	0.68	ND (0.028)	ND (0.00044)	ND (0.00076)	ND (0.00051) ND (0.00055)	ND (0.00048)	ND (0.00084)	ND (0.00062)	ND (0.00053)	ND (0.00071)	ND (0.00052)	ND (0.00045)	ND (0.026)	ND (0.00049)	ND (0.00046)
1,1,2,2-Tetrachloroethane	NA	NA	NA	ND (0.028)	ND (0.00044)	ND (0.00076)	ND (0.00051) ND (0.00055)	ND (0.00048)	ND (0.00084)	ND (0.00062)	ND (0.00053)	ND (0.00071)	ND (0.00052)	ND (0.00045)	ND (0.026)	ND (0.00049)	ND (0.00046)
1,1,2-Trichloroethane	NA	NA	NA	ND (0.056)	ND (0.00088)	ND (0.0015)	ND (0.001) ND (0.0011)	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	ND (0.00089)	ND (0.052)	ND (0.00098)	ND (0.00091)
1,1-Dichloroethane	0.27	26	0.27	ND (0.056)	ND (0.00088)	ND (0.0015)	ND (0.001) ND (0.0011)	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	ND (0.00089)	ND (0.052)	ND (0.00098)	ND (0.00091)
1,1-Dichloroethene	0.33	100	0.33	ND (0.056)	ND (0.00088)	ND (0.0015)	ND (0.001) ND (0.0011)	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	ND (0.00089)	ND (0.052)	ND (0.00098)	ND (0.00091)
1,1-Dichloropropene	NA	NA	NA	ND (0.028)	ND (0.00044)	ND (0.00076)	ND (0.00051) ND (0.00055)	ND (0.00048)	ND (0.00084)	ND (0.00062)	ND (0.00053)	ND (0.00071)	ND (0.00052)	ND (0.00045)	ND (0.026)	ND (0.00049)	ND (0.00046)
1,2,3-Trichlorobenzene	NA	NA	NA	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
1,2,3-Trichloropropane	NA	NA	NA	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
1,2,4,5-Tetramethylbenzene	NA	NA	NA	1.5	0.0016 J	0.033	0.0017 J 0.0035	ND (0.0019)	0.0024 J	ND (0.0025)	ND (0.0021)	0.00052 J	ND (0.0021)	0.00042 J	1.8	ND (0.002)	0.00043 J
1,2,4-Trichlorobenzene	NA	NA	NA	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
1,2,4-Trimethylbenzene	3.6	52	3.6	***12***	0.012	0.016	0.0017 J 0.0071	ND (0.0019)	ND (0.0034)	ND (0.0025)	0.0013 J	0.006	0.0008 J	ND (0.0018)	***9.8***	0.00078 J	0.0089
1,2-Dibromo-3-chloropropane (DBCP)	NA	NA	NA	ND (0.17)	ND (0.0026)	ND (0.0045)	ND (0.003) ND (0.0033)	ND (0.0028)	ND (0.005)	ND (0.0037)	ND (0.0032)	ND (0.0042)	ND (0.0031)	ND (0.0027)	ND (0.16)	ND (0.0029)	ND (0.0027)
1,2-Dibromoethane (Ethylene Dibromide)	NA	NA	NA	ND (0.056)	ND (0.00088)	ND (0.0015)	ND (0.001) ND (0.0011)	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	ND (0.00089)	ND (0.052)	ND (0.00098)	ND (0.00091)
1,2-Dichlorobenzene	1.1	100	1.1	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
1,2-Dichloroethane	0.02	3.1	0.02	ND (0.056)	ND (0.00088)	ND (0.0015)	ND (0.001) ND (0.0011)	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	ND (0.00089)	ND (0.052)	ND (0.00098)	ND (0.00091)
1,2-Dichloroethene (total)	NA	NA	NA	ND (0.056)	ND (0.00088)	ND (0.0015)	ND (0.001) ND (0.0011)	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	ND (0.00089)	ND (0.052)	ND (0.00098)	ND (0.00091)
1,2-Dichloropropane	NA	NA	NA	ND (0.056)	ND (0.00088)	ND (0.0015)	ND (0.001) ND (0.0011)	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	ND (0.00089)	ND (0.052)	ND (0.00098)	ND (0.00091)
1,3,5-Trimethylbenzene	8.4	52	8.4	3.6	0.0037	0.0063	0.00037 J 0.0017 J	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	0.0018 J	0.00033 J	ND (0.0018)	3	0.00034 J	0.0027
1,3-Dichlorobenzene	2.4	49	2.4	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
1,3-Dichloropropane	NA	NA	NA	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
1,3-Dichloropropene	NA	NA	NA	ND (0.028)	ND (0.00044)	ND (0.00076)	ND (0.00051) ND (0.00055)	ND (0.00048)	ND (0.00084)	ND (0.00062)	ND (0.00053)	ND (0.00071)	ND (0.00052)	ND (0.00045)	ND (0.026)	ND (0.00049)	ND (0.00046)
1,4-Dichlorobenzene	1.8	13	1.8	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
1,4-Diethylbenzene	NA	NA	NA	ND (0.11)	0.0056	0.0053	0.00097 J 0.003	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	0.0023 J	ND (0.0021)	0.00039 J	0.46	ND (0.002)	ND (0.0018)
1,4-Dioxane	0.1	13	0.1	ND (4.5)	ND (0.07)	ND (0.12)	ND (0.081) ND (0.088)	ND (0.076)	ND (0.13)	ND (0.1)	ND (0.085)	ND (0.11)	ND (0.084)	ND (0.071)	ND (4.1)	ND (0.078)	ND (0.073)
2,2-Dichloropropane	NA	NA	NA	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
2-Butanone (Methyl Ethyl Ketone)	0.12	100	0.12	ND (0.56)	ND (0.0088)	ND (0.015)	0.0031 J ND (0.011)	ND (0.0095)	ND (0.017)	ND (0.012)	0.0065 J	ND (0.014)	ND (0.01)	ND (0.0089)	ND (0.52)	ND (0.0098)	ND (0.0091)
2-Chlorotoluene	NA	NA	NA	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
2-Hexanone (Methyl Butyl Ketone)	NA	NA	NA	ND (0.56)	ND (0.0088)	ND (0.015)	ND (0.01) ND (0.011)	ND (0.0095)	ND (0.017)	ND (0.012)	ND (0.01)	ND (0.014)	ND (0.01)	ND (0.0089)	ND (0.52)	ND (0.0098)	ND (0.0091)
2-Phenylbutane (sec-Butylbenzene)	11	100	11	0.33	0.00045 J	0.0034	0.00027 J 0.00072 J	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	0.00078 J	0.3	ND (0.00098)	0.0002 J
4-Chlorotoluene	NA	NA	NA	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
4-Ethyltoluene (1-Ethyl-4-Methylbenzene)	NA	NA	NA	9.8	0.0094	0.0074	0.00098 J 0.0048	ND (0.0019)	ND (0.0034)	ND (0.0025)	0.00061 J	0.0039	ND (0.0021)	ND (0.0018)	7.3	0.00054 J	0.0064
4-Methyl-2-Pentanone (Methyl Isobutyl Ketone)	NA	NA	NA	ND (0.56)	ND (0.0088)	ND (0.015)	ND (0.01) ND (0.011)	ND (0.0095)	ND (0.017)	ND (0.012)	ND (0.01)	ND (0.014)	ND (0.01)	ND (0.0089)	ND (0.52)	ND (0.0098)	ND (0.0091)
Acetone	0.05	100	0.05	ND (0.56)	0.0044 J	0.03	0.019 0.023	ND (0.0095)	0.012 J	ND (0.012)	0.016	ND (0.014)	ND (0.01)	0.0062 J	ND (0.52)	ND (0.0098)	0.0057 J
Acrylonitrile	NA	NA	NA	ND (0.22)	ND (0.0035)	ND (0.0061)	ND (0.004) ND (0.0044)	ND (0.0038)	ND (0.0067)	ND (0.005)	ND (0.0042)	ND (0.0057)	ND (0.0042)	ND (0.0036)	ND (0.21)	ND (0.0039)	ND (0.0036)
Benzene	0.06	4.8	0.06	***0.082***	0.00015 J	0.0014	0.00042 J 0.00039 J	0.00075	ND (0.00084)	ND (0.00062)	0.00035 J	ND (0.00071)	ND (0.00052)	ND (0.00045)	0.013 J	0.00056	0.00044 J
Bromobenzene	NA	NA	NA	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
Bromodichloromethane	NA	NA	NA	ND (0.028)	ND (0.00044)	ND (0.00076)	ND (0.00051) ND (0.00055)	ND (0.00048)	ND (0.00084)	ND (0.00062)	ND (0.00053)	ND (0.00071)	ND (0.00052)	ND (0.00045)	ND (0.026)	ND (0.00049)	ND (0.00046)
Bromoform	NA	NA	NA	ND (0.22)	ND (0.0035)	ND (0.0061)	ND (0.004) ND (0.0044)	ND (0.0038)	ND (0.0067)	ND (0.005)	ND (0.0042)	ND (0.0057)	ND (0.0042)	ND (0.0036)	ND (0.21)	ND (0.0039)	ND (0.0036)
Bromomethane (Methyl Bromide)	NA	NA	NA	0.036 J	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
Carbon disulfide	NA	NA	NA	ND (0.56)	ND (0.0088)	ND (0.015)	ND (0.01) ND (0.011)	ND (0.0095)	ND (0.017)	ND (0.012)	ND (0.01)	ND (0.014)	ND (0.01)	ND (0.0089)	ND (0.52)	ND (0.0098)	ND (0.0091)
Carbon tetrachloride	0.76	2.4	0.76	ND (0.056)	ND (0.00088)	ND (0.0015)	ND (0.001) ND (0.0011)	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	ND (0.00089)	ND (0.052)	ND (0.00098)	ND (0.00091)
Chlorobenzene	1.1	100	1.1	ND (0.028)	ND (0.00044)	ND (0.00076)	ND (0.00051) ND (0.00055)	ND (0.00048)	ND (0.00084)	ND (0.00062)	ND (0.00053)	ND (0.00071)	ND (0.00052)	ND (0.00045)	ND (0.026)	ND (0.00049)	ND (0.00046)
Chlorobromomethane	NA	NA	NA	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
Chloroethane	NA	NA	NA	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
Chloroform (Trichloromethane)	0.37	49	0.37	ND (0.084)	ND (0.0013)	ND (0.0023)	ND (0.0015) ND (0.0016)	ND (0.0014)	ND (0.0025)	ND (0.0019)	ND (0.0016)	ND (0.0021)	ND (0.0016)	ND (0.0013)	ND (0.078)	ND (0.0015)	ND (0.0014)
Chloromethane (Methyl Chloride)	NA	NA	NA	ND (0.22)	ND (0.0035)	ND (0.0061)	ND (0.004) ND (0.0044)	ND (0.0038)	ND (0.0067)	ND (0.005)	ND (0.0042)	ND (0.0057)	ND (0.0042)	ND (0.0036)	ND (0.21)	ND (0.0039)	ND (0.0036)
cis-1,2-Dichloroethene	0.25	100	0.25	ND (0.056)	ND (0.00088)	ND (0.0015)	ND (0.001) ND (0.0011)	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	ND (0.00089)	ND (0.052)	ND (0.00098)	ND (0.00091)
cis-1,3-Dichloropropene	NA	NA	NA	ND (0.028)	ND (0.00044)	ND (0.00076)	ND (0.00051) ND (0.00055)	ND (0.00048)	ND (0.00084)	ND (0.00062)	ND (0.00053)	ND (0.00071)	ND (0.00052)	ND (0.00045)	ND (0.026)	ND (0.00049)	ND (0.00046)
Cyclohexane	NA	NA	NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Cymene (p-Isopropyltoluene)	NA	NA	NA	0.24	0.00025 J	0.0038	0.00044 J 0.0011	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	0.00023 J	0.26	ND (0.00098)	0.0003 J
Dibromochloromethane	NA	NA	NA	ND (0.056)	ND (0.00088)	ND (0.0015)	ND (0.001) ND (0.0011)	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	ND (0.00089)	ND (0.052)	ND (0.00098)	ND (0.00091)
Dibromomethane	NA	NA	NA	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
Dichlorodifluoromethane (CFC-12)	NA	NA	NA	ND (0.56)	ND (0.0088)	ND (0.015)	ND (0.01) ND (0.011)	ND (0.0095)	ND (0.017)	ND (0.012)	ND (0.01)	ND (0.014)	ND (0.01)	ND (0.0089)	ND (0.52)	ND (0.0098)	ND (0.0091)
Ethyl Ether	NA	NA	NA	ND (0.11)	ND (0.0018)	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
Ethylbenzene	1	41	1	***2.7***	0.0026	0.0021	0.00044 J 0.0016	ND (0.00095)	ND (0.0017)	ND (0.0012)	0.00068 J	0.0016	ND (0.001)	ND (0.00089)	***1.4***	0.00036 J	0.0036

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria																
Location Name	Restricted Use	NY Part 375	NY Part 375	HA-SB12	HA-SB12	HA-SB2	HA-SB2	HA-SB5	HA-SB5	HA-SB5	HA-SB5	HA-SB6	HA-SB6	HA-SB6	HA-SB6	HA-SB8	HA-SB8
Sample Name	Soil Cleanup	Restricted	Unrestricted	HA-SB12_15-17	HA-SB12_46-48	HA-SB2_0-0.5	HA-SB2_3-5	HA-SB5_0-0.5	HA-SB5_3-5	HA-SB5_15-17	HA-SB5_48-50	HA-SB6_0-0.5	HA-SB6_6-8	HA-SB6_15-17	HA-SB6_28-40	HA-SB8_0-0.5	HA-SB8_3-5
Sample Date	Objectives -	Residential Use	Use	04/14/2025	04/14/2025	04/24/2025	04/24/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/15/2025	04/15/2025
Lab Sample ID	Protection of	Soil Cleanup	Soil Cleanup	L2522786-09	L2522786-10	L2525266-07	L2525266-08	L2525069-03	L2525069-04	L2525069-05	L2525069-06	L2525069-07	L2525069-08	L2525069-09	L2525069-10	L2523120-01	L2523120-02
Sample Depth (bgs)	Groundwater	Objectives	Objectives	15 - 17 (ft)	46 - 48 (ft)	0 - 0.5 (ft)	3 - 5 (ft)	0 - 0.5 (ft)	3 - 5 (ft)	15 - 17 (ft)	48 - 50 (ft)	0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	28 - 40 (ft)	0 - 0.5 (ft)	3 - 5 (ft)
Hexachlorobutadiene	NA	NA	NA	ND (0.22)	ND (0.0035)	ND (0.0061)	ND (0.004) ND (0.0044)	ND (0.0038)	ND (0.0067)	ND (0.005)	ND (0.0042)	ND (0.0057)	ND (0.0042)	ND (0.0036)	ND (0.21)	ND (0.0039)	ND (0.0036)
Isopropylbenzene (Cumene)	NA	NA	NA	0.53	0.00059 J	0.0018	0.00012 J 0.00043 J	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	0.00029 J	ND (0.001)	0.0013	0.41	ND (0.00098)	0.00047 J
m,p-Xylenes	NA	NA	NA	11	0.0098	0.005	0.0016 J 0.0068	0.00081 J	ND (0.0034)	ND (0.0025)	0.0028	0.0062	ND (0.0021)	ND (0.0018)	6.9	0.0017 J	0.016
Methyl acetate	NA	NA	NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Methyl Tert Butyl Ether (MTBE)	0.93	100	0.93	ND (0.11)	0.00028 J	ND (0.003)	ND (0.002) ND (0.0022)	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	ND (0.0018)	ND (0.1)	ND (0.002)	ND (0.0018)
Methylcyclohexane	NA	NA	NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Methylene chloride (Dichloromethane)	0.05	100	0.05	ND (0.28)	ND (0.0044)	ND (0.0076)	ND (0.0051) ND (0.0055)	ND (0.0048)	ND (0.0084)	ND (0.0062)	ND (0.0053)	ND (0.0071)	ND (0.0052)	ND (0.0045)	ND (0.26)	ND (0.0049)	ND (0.0046)
Naphthalene	12	100	12	2.6	0.0029 J	0.037	0.0053 0.0059	ND (0.0038)	0.0016 J	ND (0.005)	ND (0.0042)	ND (0.0057)	ND (0.0042)	ND (0.0036)	3	ND (0.0039)	0.0017 J
n-Butylbenzene	12	100	12	0.83	0.00082 J	0.0028	0.00026 J 0.00052 J	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	0.00019 J	0.68	ND (0.00098)	0.0002 J
n-Propylbenzene	3.9	100	3.9	1.9	0.0019	0.0023	0.00032 J 0.0012	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	0.00092 J	ND (0.001)	0.0015	1.4	ND (0.00098)	0.001
o-Xylene	NA	NA	NA	4.5	0.0042	0.0017	0.00072 J 0.0027	ND (0.00095)	ND (0.0017)	ND (0.0012)	0.0015	0.0021	ND (0.001)	ND (0.00089)	3	0.0007 J	0.005
Styrene	NA	NA	NA	ND (0.056)	ND (0.00088)	ND (0.0015)	ND (0.001) ND (0.0011)	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	ND (0.00089)	ND (0.052)	ND (0.00098)	ND (0.00091)
tert-Butylbenzene	5.9	100	5.9	0.023 J	ND (0.0018)	0.0017 J	0.00014 J 0.00035 J	ND (0.0019)	ND (0.0034)	ND (0.0025)	ND (0.0021)	ND (0.0028)	ND (0.0021)	0.00032 J	ND (0.1)	ND (0.002)	ND (0.0018)
Tetrachloroethene	1.3	19	1.3	ND (0.028)	ND (0.00044)	ND (0.00076)	ND (0.00051) ND (0.00055)	ND (0.00048)	ND (0.00084)	ND (0.00062)	ND (0.00053)	ND (0.00071)	ND (0.00052)	ND (0.00045)	ND (0.026)	ND (0.00049)	ND (0.00046)
Toluene	0.7	100	0.7	***5.1***	0.0052	0.0082	0.0015 0.004	0.001	ND (0.0017)	ND (0.0012)	0.0034	0.0028	ND (0.001)	ND (0.00089)	***1.8***	0.0012	0.0022
trans-1,2-Dichloroethene	0.19	100	0.19	ND (0.084)	ND (0.0013)	ND (0.0023)	ND (0.0015) ND (0.0016)	ND (0.0014)	ND (0.0025)	ND (0.0019)	ND (0.0016)	ND (0.0021)	ND (0.0016)	ND (0.0013)	ND (0.078)	ND (0.0015)	ND (0.0014)
trans-1,3-Dichloropropene	NA	NA	NA	ND (0.056)	ND (0.00088)	ND (0.0015)	ND (0.001) ND (0.0011)	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	ND (0.00089)	ND (0.052)	ND (0.00098)	ND (0.00091)
trans-1,4-Dichloro-2-butene	NA	NA	NA	ND (0.28)	ND (0.0044)	ND (0.0076)	ND (0.0051) ND (0.0055)	ND (0.0048)	ND (0.0084)	ND (0.0062)	ND (0.0053)	ND (0.0071)	ND (0.0052)	ND (0.0045)	ND (0.26)	ND (0.0049)	ND (0.0046)
Trichloroethene	0.47	21	0.47	ND (0.028)	ND (0.00044)	ND (0.00076)	ND (0.00051) ND (0.00055)	ND (0.00048)	ND (0.00084)	ND (0.00062)	ND (0.00053)	ND (0.00071)	ND (0.00052)	ND (0.00045)	ND (0.026)	ND (0.00049)	ND (0.00046)
Trichlorofluoromethane (CFC-11)	NA	NA	NA	ND (0.22)	ND (0.0035)	ND (0.0061)	ND (0.004) ND (0.0044)	ND (0.0038)	ND (0.0067)	ND (0.005)	ND (0.0042)	ND (0.0057)	ND (0.0042)	ND (0.0036)	ND (0.21)	ND (0.0039)	ND (0.0036)
Trifluorotrichloroethane (Freon 113)	NA	NA	NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Vinyl acetate	NA	NA	NA	ND (0.56)	ND (0.0088)	ND (0.015)	ND (0.01) ND (0.011)	ND (0.0095)	ND (0.017)	ND (0.012)	ND (0.01)	ND (0.014)	ND (0.01)	ND (0.0089)	ND (0.52)	ND (0.0098)	ND (0.0091)
Vinyl chloride	0.02	0.9	0.02	ND (0.056)	ND (0.00088)	ND (0.0015)	ND (0.001) ND (0.0011)	ND (0.00095)	ND (0.0017)	ND (0.0012)	ND (0.001)	ND (0.0014)	ND (0.001)	ND (0.00089)	ND (0.052)	ND (0.00098)	ND (0.00091)
Xylene (Total)	1.6	100	0.26	***16***	0.014	0.0067	0.0023 J 0.0095	0.00081 J	ND (0.0017)	ND (0.0012)	0.0043	0.0083	ND (0.001)	ND (0.00089)	***9.9***	0.0024 J	0.021
Semi-Volatile Organic Compounds (mg/kg)																	
1,2,4,5-Tetrachlorobenzene	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
1,2,4-Trichlorobenzene	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
1,2-Dichlorobenzene	1.1	100	1.1	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
1,3-Dichlorobenzene	2.4	49	2.4	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
1,4-Dichlorobenzene	1.8	13	1.8	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
1,4-Dioxane	0.1	13	0.1	ND (0.027)	ND (0.026)	ND (0.027)	ND (0.026)	ND (0.026)	ND (0.027)	ND (0.027)	ND (0.027)	ND (0.027)	ND (0.026)	ND (0.028)	ND (0.026)	ND (0.026)	ND (0.027)
2,2'-oxybis(1-Chloropropane)	NA	NA	NA	ND (0.21)	ND (0.2)	ND (0.21)	ND (0.21)	ND (0.21)	ND (0.22)	ND (0.22)	ND (0.22)	ND (0.21)	ND (0.21)	ND (0.22)	ND (0.21)	ND (0.21)	ND (0.22)
2,3,4,6-Tetrachlorophenol	NA	NA	NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-
2,4,5-Trichlorophenol	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2,4,6-Trichlorophenol	NA	NA	NA	ND (0.11)	ND (0.1)	ND (0.11)	ND (0.1)	ND (0.11)	ND (0.11)	ND (0.11)	ND (0.11)	ND (0.11)	ND (0.1)	ND (0.11)	ND (0.1)	ND (0.1)	ND (0.11)
2,4-Dichlorophenol	NA	NA	NA	ND (0.16)	ND (0.15)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)
2,4-Dimethylphenol	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2,4-Dinitrophenol	NA	NA	NA	ND (0.86)	ND (0.82)	ND (0.85)	ND (0.83)	ND (0.85)	ND (0.86)	ND (0.86)	ND (0.86)	ND (0.85)	ND (0.83)	ND (0.88)	ND (0.83)	ND (0.84)	ND (0.87)
2,4-Dinitrotoluene	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2,6-Dinitrotoluene	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2-Chloronaphthalene	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2-Chlorophenol	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2-Methylnaphthalene	NA	NA	NA	1.2	ND (0.2)	0.8	0.082 J	0.042 J	ND (0.22)	ND (0.22)	ND (0.22)	0.1 J	ND (0.21)	ND (0.22)	0.76	0.038 J	0.024 J
2-Methylphenol (o-Cresol)	0.33	100	0.33	0.04 J	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	0.034 J	ND (0.17)	ND (0.18)
2-Nitroaniline	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2-Nitrophenol	NA	NA	NA	ND (0.39)	ND (0.37)	ND (0.38)	ND (0.37)	ND (0.38)	ND (0.39)	ND (0.39)	ND (0.39)	ND (0.38)	ND (0.37)	ND (0.4)	ND (0.38)	ND (0.38)	ND (0.39)
3&4-Methylphenol	NA	NA	NA	0.056 J	ND (0.24)	0.13 J	ND (0.25)	ND (0.25)	ND (0.26)	ND (0.26)	ND (0.26)	ND (0.26)	ND (0.25)	ND (0.26)	0.049 J	ND (0.25)	ND (0.26)
3,3'-Dichlorobenzidine	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
3-Nitroaniline	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
4,6-Dinitro-2-methylphenol	NA	NA	NA	ND (0.46)	ND (0.44)	ND (0.46)	ND (0.45)	ND (0.46)	ND (0.47)	ND (0.47)	ND (0.47)	ND (0.46)	ND (0.45)	ND (0.48)	ND (0.45)	ND (0.45)	ND (0.47)
4-Bromophenyl phenyl ether (BDE-3)	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
4-Chloro-3-methylphenol	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
4-Chloroaniline	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
4-Chlorophenyl phenyl ether	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
4-Methylphenol	0.33	100	0.33	-	-	-	-	-	-	-	-	-	-	-	-	-	-
4-Nitroaniline	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
4-Nitrophenol	NA	NA	NA	ND (0.25)	ND (0.24)	ND (0.25)	ND (0.24)	ND (0.25)	ND (0.25)	ND (0.25)	ND (0.25)	ND (0.25)	ND (0.24)	ND (0.26)	ND (0.24)	ND (0.24)	ND (0.25)

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria																
Location Name	Restricted Use	NY Part 375	NY Part 375	HA-SB12	HA-SB12	HA-SB2	HA-SB2	HA-SB5	HA-SB5	HA-SB5	HA-SB5	HA-SB6	HA-SB6	HA-SB6	HA-SB6	HA-SB8	HA-SB8
Sample Name	Soil Cleanup	Restricted	Unrestricted	HA-SB12_15-17	HA-SB12_46-48	HA-SB2_0-0.5	HA-SB2_3-5	HA-SB5_0-0.5	HA-SB5_3-5	HA-SB5_15-17	HA-SB5_48-50	HA-SB6_0-0.5	HA-SB6_6-8	HA-SB6_15-17	HA-SB6_28-40	HA-SB8_0-0.5	HA-SB8_3-5
Sample Date	Objectives -	Residential Use	Use	04/14/2025	04/14/2025	04/24/2025	04/24/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/15/2025	04/15/2025
Lab Sample ID	Protection of	Soil Cleanup	Soil Cleanup	L2522786-09	L2522786-10	L2525266-07	L2525266-08	L2525069-03	L2525069-04	L2525069-05	L2525069-06	L2525069-07	L2525069-08	L2525069-09	L2525069-10	L2523120-01	L2523120-02
Sample Depth (bgs)	Groundwater	Objectives	Objectives	15 - 17 (ft)	46 - 48 (ft)	0 - 0.5 (ft)	3 - 5 (ft)	0 - 0.5 (ft)	3 - 5 (ft)	15 - 17 (ft)	48 - 50 (ft)	0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	28 - 40 (ft)	0 - 0.5 (ft)	3 - 5 (ft)
Acenaphthene	98	100	20	ND (0.14)	ND (0.14)	0.2	0.091 J	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	0.034 J	ND (0.14)	ND (0.15)	ND (0.14)	ND (0.14)	ND (0.14)
Acenaphthylene	107	100	100	ND (0.14)	ND (0.14)	0.18	0.047 J	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	0.055 J	ND (0.14)	ND (0.15)	ND (0.14)	ND (0.14)	ND (0.14)
Acetophenone	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
Anthracene	1000	100	100	ND (0.11)	ND (0.1)	0.43	0.2	0.036 J	ND (0.11)	ND (0.11)	ND (0.11)	0.12	ND (0.1)	ND (0.11)	ND (0.1)	ND (0.1)	ND (0.11)
Atrazine	NA	NA	NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Benzaldehyde	NA	NA	NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Benzo(a)anthracene	1	1	1	ND (0.11)	ND (0.1)	***1.1***	0.46	0.088 J	ND (0.11)	ND (0.11)	ND (0.11)	0.47	0.026 J	ND (0.11)	ND (0.1)	0.091 J	0.065 J
Benzo(a)pyrene	22	1	1	ND (0.14)	ND (0.14)	1	0.44	0.11 J	ND (0.14)	ND (0.14)	ND (0.14)	0.46	ND (0.14)	ND (0.15)	ND (0.14)	0.11 J	0.068 J
Benzo(b)fluoranthene	1.7	1	1	ND (0.11)	ND (0.1)	1.3	0.53	0.14	ND (0.11)	ND (0.11)	ND (0.11)	0.57	ND (0.1)	ND (0.11)	ND (0.1)	0.15	0.081 J
Benzo(g,h,i)perylene	1000	100	100	ND (0.14)	ND (0.14)	0.76	0.28	0.12 J	ND (0.14)	ND (0.14)	ND (0.14)	0.26	ND (0.14)	ND (0.15)	ND (0.14)	0.12 J	0.072 J
Benzo(k)fluoranthene	1.7	3.9	0.8	ND (0.11)	ND (0.1)	0.45	0.2	0.054 J	ND (0.11)	ND (0.11)	ND (0.11)	0.16	ND (0.1)	ND (0.11)	ND (0.1)	0.038 J	ND (0.11)
Benzoic acid	NA	NA	NA	ND (0.58)	ND (0.55)	ND (0.58)	ND (0.56)	ND (0.57)	ND (0.58)	ND (0.58)	ND (0.58)	ND (0.57)	ND (0.56)	ND (0.6)	ND (0.56)	ND (0.56)	ND (0.59)
Benzyl Alcohol	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
Biphenyl	NA	NA	NA	0.029 J	ND (0.39)	0.062 J	ND (0.39)	ND (0.4)	ND (0.41)	ND (0.41)	ND (0.41)	ND (0.4)	ND (0.39)	ND (0.42)	0.022 J	ND (0.4)	ND (0.41)
bis(2-Chloroethoxy)methane	NA	NA	NA	ND (0.19)	ND (0.18)	ND (0.19)	ND (0.19)	ND (0.19)	ND (0.19)	ND (0.19)	ND (0.19)	ND (0.19)	ND (0.19)	ND (0.2)	ND (0.19)	ND (0.19)	ND (0.2)
bis(2-Chloroethyl)ether	NA	NA	NA	ND (0.16)	ND (0.15)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)
bis(2-Ethylhexyl)phthalate	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	0.13 J	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
Butyl benzylphthalate (BBP)	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	1.3	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
Caprolactam	NA	NA	NA	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Carbazole	NA	NA	NA	ND (0.18)	ND (0.17)	0.22	0.12 J	0.017 J	ND (0.18)	ND (0.18)	ND (0.18)	0.035 J	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
Chrysene	1	3.9	1	ND (0.11)	ND (0.1)	***1.1***	0.49	0.088 J	ND (0.11)	ND (0.11)	ND (0.11)	0.43	0.021 J	ND (0.11)	ND (0.1)	0.092 J	0.062 J
Dibenz(a,h)anthracene	1000	0.33	0.33	ND (0.11)	ND (0.1)	0.19	0.057 J	0.022 J	ND (0.11)	ND (0.11)	ND (0.11)	0.068 J	ND (0.1)	ND (0.11)	ND (0.1)	0.026 J	0.022 J
Dibenzofuran	210	59	7	ND (0.18)	ND (0.17)	0.13 J	0.076 J	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	0.025 J	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
Diethyl phthalate	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
Dimethyl phthalate	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
Di-n-butylphthalate (DBP)	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
Di-n-octyl phthalate (DnOP)	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
Fluoranthene	1000	100	100	ND (0.11)	ND (0.1)	2.2	1.2	0.14	0.045 J	ND (0.11)	ND (0.11)	0.81	0.054 J	ND (0.11)	ND (0.1)	0.15	0.11
Fluorene	386	100	30	ND (0.18)	ND (0.17)	0.35	0.14 J	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	0.034 J	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
Hexachlorobenzene	3.2	1.2	0.33	ND (0.11)	ND (0.1)	ND (0.11)	ND (0.1)	ND (0.11)	ND (0.11)	ND (0.11)	ND (0.11)	ND (0.11)	ND (0.1)	ND (0.11)	ND (0.1)	ND (0.1)	ND (0.11)
Hexachlorobutadiene	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
Hexachlorocyclopentadiene	NA	NA	NA	ND (0.51)	ND (0.49)	ND (0.51)	ND (0.49)	ND (0.51)	ND (0.51)	ND (0.51)	ND (0.52)	ND (0.51)	ND (0.49)	ND (0.53)	ND (0.5)	ND (0.5)	ND (0.52)
Hexachloroethane	NA	NA	NA	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.15)	ND (0.14)	ND (0.14)	ND (0.14)
Indeno(1,2,3-cd)pyrene	8.2	0.5	0.5	ND (0.14)	ND (0.14)	0.57	0.21	0.091 J	ND (0.14)	ND (0.14)	ND (0.14)	0.27	ND (0.14)	ND (0.15)	ND (0.14)	0.089 J	0.058 J
Isophorone	NA	NA	NA	ND (0.16)	ND (0.15)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)
Naphthalene	12	100	12	0.97	ND (0.17)	0.74	0.15 J	0.059 J	ND (0.18)	ND (0.18)	ND (0.18)	0.13 J	ND (0.17)	ND (0.18)	0.49	0.044 J	0.033 J
Nitrobenzene	NA	NA	NA	ND (0.16)	ND (0.15)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)
N-Nitrosodi-n-propylamine	NA	NA	NA	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
N-Nitrosodiphenylamine	NA	NA	NA	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.15)	ND (0.14)	ND (0.14)	ND (0.14)
Pentachlorophenol	0.8	6.7	0.8	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.15)	ND (0.14)	ND (0.14)	ND (0.14)
Phenanthrene	1000	100	100	ND (0.11)	ND (0.1)	1.8	1	0.092 J	ND (0.11)	ND (0.11)	ND (0.11)	0.41	0.049 J	ND (0.11)	0.035 J	0.075 J	0.089 J
Phenol	0.33	100	0.33	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
Pyrene	1000	100	100	ND (0.11)	ND (0.1)	2.2	1.1	0.13	0.036 J	ND (0.11)	ND (0.11)	0.78	0.048 J	ND (0.11)	ND (0.1)	0.14	0.1 J

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria																	
Location Name	Restricted Use	NY Part 375	NY Part 375	HA-SB12	HA-SB12	HA-SB2	HA-SB2	HA-SB5	HA-SB5	HA-SB5	HA-SB5	HA-SB6	HA-SB6	HA-SB6	HA-SB6	HA-SB8	HA-SB8
Sample Name	Soil Cleanup	Restricted	Unrestricted	HA-SB12_15-17	HA-SB12_46-48	HA-SB2_0-0.5	HA-SB2_3-5	HA-SB5_0-0.5	HA-SB5_3-5	HA-SB5_15-17	HA-SB5_48-50	HA-SB6_0-0.5	HA-SB6_6-8	HA-SB6_15-17	HA-SB6_28-40	HA-SB8_0-0.5	HA-SB8_3-5
Sample Date	Objectives -	Residential Use	Use	04/14/2025	04/14/2025	04/24/2025	04/24/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/15/2025	04/15/2025
Lab Sample ID	Protection of	Soil Cleanup	Soil Cleanup	L2522786-09	L2522786-10	L2525266-07	L2525266-08	L2525069-03	L2525069-04	L2525069-05	L2525069-06	L2525069-07	L2525069-08	L2525069-09	L2525069-10	L2523120-01	L2523120-02
Sample Depth (bgs)	Groundwater	Objectives	Objectives	15 - 17 (ft)	46 - 48 (ft)	0 - 0.5 (ft)	3 - 5 (ft)	0 - 0.5 (ft)	3 - 5 (ft)	15 - 17 (ft)	48 - 50 (ft)	0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	28 - 40 (ft)	0 - 0.5 (ft)	3 - 5 (ft)
PFAS (mg/kg)																	
11-Chloroeicosafluoro-3-Oxaundecane-1-Sulfonic Acid (11Cl-PF3OUdS)	NA	NA	NA	ND (0.000799)	ND (0.000801)	-	-	-	-	-	-	-	-	-	-	ND (0.000794)	ND (0.000798)
2H,2H,3H,3H-Perfluorooctanoic acid (5:3 FTCA)	NA	NA	NA	ND (0.00499)	ND (0.005)	ND (0.005)	ND (0.00499)	ND (0.00499)	ND (0.005)	ND (0.00498)	ND (0.005)	ND (0.00499)	ND (0.005)	ND (0.005)	ND (0.005)	ND (0.00496)	ND (0.00499)
3-(Perfluoroheptyl)propanoic acid (7:3 FTCA)	NA	NA	NA	ND (0.00499)	ND (0.005)	ND (0.005)	ND (0.00499)	ND (0.00499)	ND (0.005)	ND (0.00498)	ND (0.005)	ND (0.00499)	ND (0.005)	ND (0.005)	ND (0.005)	ND (0.00496)	ND (0.00499)
3:3 Fluorotelomer carboxylic acid (3:3 FTCA)	NA	NA	NA	ND (0.000999)	ND (0.001)	ND (0.000999)	ND (0.000998)	ND (0.000997)	ND (0.000999)	ND (0.000997)	ND (0.001)	ND (0.000999)	ND (0.001)	ND (0.001)	ND (0.001)	ND (0.000993)	ND (0.000998)
4,8-Dioxa-3H-Perfluorononanoic Acid (ADONA)	NA	NA	NA	ND (0.000799)	ND (0.000801)	ND (0.000799)	ND (0.000798)	ND (0.000798)	ND (0.0008)	ND (0.000798)	ND (0.0008)	ND (0.000799)	ND (0.000801)	ND (0.0008)	ND (0.000801)	ND (0.000794)	ND (0.000798)
4:2 Fluorotelomer sulfonic acid (4:2 FTS)	NA	NA	NA	ND (0.000799)	ND (0.000801)	ND (0.000799)	ND (0.000798)	ND (0.000798)	ND (0.0008)	ND (0.000798)	ND (0.0008)	ND (0.000799)	ND (0.000801)	ND (0.0008)	ND (0.000801)	ND (0.000794)	ND (0.000798)
6:2 Fluorotelomer sulfonic acid (6:2 FTS)	NA	NA	NA	ND (0.000799)	ND (0.000801)	ND (0.000799)	ND (0.000798)	ND (0.000798)	ND (0.0008)	ND (0.000798)	ND (0.0008)	ND (0.000799)	ND (0.000801)	ND (0.0008)	ND (0.000801)	0.00018 J	ND (0.000798)
8:2 Fluorotelomer sulfonic acid (8:2 FTS)	NA	NA	NA	ND (0.000799)	ND (0.000801)	ND (0.000799)	ND (0.000798)	ND (0.000798)	ND (0.0008)	ND (0.000798)	ND (0.0008)	ND (0.000799)	ND (0.000801)	ND (0.0008)	ND (0.000801)	ND (0.000794)	ND (0.000798)
9-Chlorohexadecafluoro-3-Oxanone-1-Sulfonic Acid (9Cl-PF3ONS)	NA	NA	NA	ND (0.000799)	ND (0.000801)	-	-	-	-	-	-	-	-	-	-	ND (0.000794)	ND (0.000798)
N-Ethyl Perfluorooctanesulfonamidoacetic Acid (NEtFOSAA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
N-Ethylperfluorooctane sulfonamide (N-EtFOSA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
N-Ethylperfluorooctane sulfonamidoethanol (N-EtFOSE)	NA	NA	NA	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.00199)	ND (0.002)	ND (0.00199)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.00199)	ND (0.002)
N-Methyl Perfluorooctanesulfonamidoacetic Acid (MeFOSAA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
N-Methylperfluorooctane sulfonamide (N-MeFOSA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
N-Methylperfluorooctane sulfonamidoethanol (N-MeFOSE)	NA	NA	NA	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.00199)	ND (0.002)	ND (0.00199)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.002)	ND (0.00199)	ND (0.002)
Nonafluoro-3,6-dioxaheptanoic acid (NFDHA)	NA	NA	NA	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.000399)	ND (0.000399)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.000397)	ND (0.000399)
Perfluoro(2-ethoxyethane) sulphonic acid (PFEESA)	NA	NA	NA	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.000399)	ND (0.000399)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.000397)	ND (0.000399)
Perfluoro(4-methoxybutanoic) acid (PFMBA)	NA	NA	NA	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.000399)	ND (0.000399)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.000397)	ND (0.000399)
Perfluoro-2-propoxypropanoic acid (PFPrOPrA)(GenX) (HFPO-DA)	NA	NA	NA	ND (0.000799)	ND (0.000801)	ND (0.000799)	ND (0.000798)	ND (0.000798)	ND (0.0008)	ND (0.000798)	ND (0.0008)	ND (0.000799)	ND (0.000801)	ND (0.0008)	ND (0.000801)	ND (0.000794)	ND (0.000798)
Perfluoro-3-methoxypropanoic acid (PFMPA)	NA	NA	NA	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.000399)	ND (0.000399)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.000397)	ND (0.000399)
Perfluorobutanesulfonic acid (PFBS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
Perfluorobutanoic acid (PFBA)	NA	NA	NA	0.000048 J	0.000032 J	0.000042 J	ND (0.000798)	ND (0.000798)	ND (0.0008)	ND (0.000798)	ND (0.0008)	ND (0.000799)	ND (0.000801)	ND (0.0008)	ND (0.000801)	ND (0.000794)	0.000034 J
Perfluorodecanesulfonic acid (PFDS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000016 J	ND (0.0002)
Perfluorodecanoic acid (PFDA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	0.000084 J	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
Perfluorododecane sulfonic acid (PFDoDS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
Perfluorododecanoic acid (PFDoDA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
Perfluoroheptanesulfonic acid (PFHpS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
Perfluoroheptanoic acid (PFHpA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000032 J	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000022 J	0.000015 J
Perfluorohexanesulfonic acid (PFHxS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
Perfluorohexanoic acid (PFHxA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.00006 J	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	0.000034 J	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000036 J	ND (0.0002)
Perfluorononane sulfonic acid (PFNS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
Perfluorononanoic acid (PFNA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000026 J	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000021 J	ND (0.0002)
Perfluorooctane sulfonamide (PFOSA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
Perfluorooctanesulfonic acid (PFOS)	0.001	0.044	0.00088	ND (0.0002)	ND (0.0002)	0.000046 J	0.000032 J	0.000179 J	0.000197 J	0.000068 J	ND (0.0002)	0.000116 J	0.000206	ND (0.0002)	ND (0.0002)	0.000223	0.000096 J
Perfluorooctanoic acid (PFOA)	0.0008	0.033	0.00066	ND (0.0002)	0.000155 J	0.000155 J	0.000168 J	0.000035 J	ND (0.0002)	ND (0.000199)	ND (0.0002)	0.000047 J	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000048 J	0.000034 J
Perfluoropentanesulfonic acid (PFPeS)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
Perfluoropentanoic acid (PFPeA)	NA	NA	NA	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.000399)	ND (0.000399)	ND (0.0004)	ND (0.000399)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.0004)	ND (0.000397)	ND (0.000399)
Perfluorotetradecanoic acid (PFTeDA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
Perfluorotridecanoic acid (PFTrDA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)
Perfluoroundecanoic acid (PFUnDA)	NA	NA	NA	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	ND (0.0002)	0.000015 J	ND (0.0002)

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

Location Name	Criteria			HA-SB12	HA-SB12	HA-SB2	HA-SB2	HA-SB5	HA-SB5	HA-SB5	HA-SB5	HA-SB6	HA-SB6	HA-SB6	HA-SB6	HA-SB8	HA-SB8
Sample Name	Restricted Use Soil Cleanup Objectives - Protection of Groundwater	NY Part 375 Restricted Residential Use Soil Cleanup Objectives	NY Part 375 Unrestricted Use Soil Cleanup Objectives	HA-SB12_15-17	HA-SB12_46-48	HA-SB2_0-0.5	HA-SB2_3-5	HA-SB5_0-0.5	HA-SB5_3-5	HA-SB5_15-17	HA-SB5_48-50	HA-SB6_0-0.5	HA-SB6_6-8	HA-SB6_15-17	HA-SB6_28-40	HA-SB8_0-0.5	HA-SB8_3-5
Sample Date				04/14/2025	04/14/2025	04/24/2025	04/24/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/15/2025	04/15/2025
Lab Sample ID				L2522786-09	L2522786-10	L2525266-07	L2525266-08	L2525069-03	L2525069-04	L2525069-05	L2525069-06	L2525069-07	L2525069-08	L2525069-09	L2525069-10	L2523120-01	L2523120-02
Sample Depth (bgs)				15 - 17 (ft)	46 - 48 (ft)	0 - 0.5 (ft)	3 - 5 (ft)	0 - 0.5 (ft)	3 - 5 (ft)	15 - 17 (ft)	48 - 50 (ft)	0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	28 - 40 (ft)	0 - 0.5 (ft)	3 - 5 (ft)
Pesticides (mg/kg)																	
4,4'-DDD	14	13	0.0033	ND (0.00171)	ND (0.00161)	ND (0.00162)	0.000795 J	ND (0.00163)	ND (0.00169)	ND (0.00174)	ND (0.00167)	ND (0.00164)	ND (0.00162)	ND (0.0017)	ND (0.00165)	ND (0.00164)	ND (0.00168)
4,4'-DDE	17	8.9	0.0033	ND (0.00171)	ND (0.00161)	0.000722 JIP	ND (0.00166)	ND (0.00163)	ND (0.00169)	ND (0.00174)	ND (0.00167)	0.000846 J	ND (0.00162)	ND (0.0017)	ND (0.00165)	ND (0.00164)	ND (0.00168)
4,4'-DDT	136	7.9	0.0033	ND (0.00171)	ND (0.00161)	ND (0.00162)	ND (0.00166)	ND (0.00163)	ND (0.00169)	ND (0.00174)	ND (0.00167)	ND (0.00164)	ND (0.00162)	ND (0.0017)	ND (0.00165)	ND (0.00164)	ND (0.00168)
Aldrin	0.19	0.097	0.005	ND (0.00171)	ND (0.00161)	ND (0.00162)	ND (0.00166)	ND (0.00163)	ND (0.00169)	ND (0.00174)	ND (0.00167)	ND (0.00164)	ND (0.00162)	ND (0.0017)	ND (0.00165)	ND (0.00164)	ND (0.00168)
alpha-BHC	0.02	0.48	0.02	ND (0.000712)	ND (0.000672)	ND (0.000677)	ND (0.000693)	ND (0.000681)	ND (0.000704)	ND (0.000726)	ND (0.000696)	ND (0.000685)	ND (0.000675)	ND (0.000708)	ND (0.000688)	ND (0.000681)	ND (0.000701)
alpha-Chlordane (cis)	2.9	4.2	0.094	ND (0.00214)	ND (0.00202)	ND (0.00203) IP	ND (0.00208)	ND (0.00204)	ND (0.00211)	ND (0.00218)	ND (0.00209)	0.00512	ND (0.00202)	ND (0.00212)	ND (0.00206)	ND (0.00204)	ND (0.0021)
beta-BHC	0.09	0.36	0.036	ND (0.00171)	ND (0.00161)	ND (0.00162)	ND (0.00166)	ND (0.00163)	ND (0.00169)	ND (0.00174)	ND (0.00167)	ND (0.00164)	ND (0.00162)	ND (0.0017)	ND (0.00165)	ND (0.00164)	ND (0.00168)
Chlordane	NA	NA	NA	ND (0.0142)	ND (0.0134)	ND (0.0135)	ND (0.0139)	ND (0.0136)	ND (0.0141)	ND (0.0145)	ND (0.0139)	ND (0.0137)	ND (0.0135)	ND (0.0142)	ND (0.0138)	ND (0.0136)	ND (0.014)
delta-BHC	0.25	100	0.04	ND (0.00171)	ND (0.00161)	ND (0.00162)	ND (0.00166)	ND (0.00163)	ND (0.00169)	ND (0.00174)	ND (0.00167)	ND (0.00164)	ND (0.00162)	ND (0.0017)	ND (0.00165)	ND (0.00164)	ND (0.00168)
Dieldrin	0.1	0.2	0.005	ND (0.00107)	ND (0.00101)	ND (0.00102)	ND (0.00104)	ND (0.00102)	ND (0.00106)	ND (0.00109)	ND (0.00104)	0.0027	ND (0.00101)	ND (0.00106)	ND (0.00103)	ND (0.00102)	ND (0.00105)
Endosulfan I	102	24	2.4	ND (0.00171)	ND (0.00161)	ND (0.00162)	ND (0.00166)	ND (0.00163)	ND (0.00169)	ND (0.00174)	ND (0.00167)	ND (0.00164)	ND (0.00162)	ND (0.0017)	ND (0.00165)	ND (0.00164)	ND (0.00168)
Endosulfan II	102	24	2.4	ND (0.00171)	ND (0.00161)	ND (0.00162)	ND (0.00166)	ND (0.00163)	ND (0.00169)	ND (0.00174)	ND (0.00167)	ND (0.00164)	ND (0.00162)	ND (0.0017)	ND (0.00165)	ND (0.00164)	ND (0.00168)
Endosulfan sulfate	1000	24	2.4	ND (0.000712)	ND (0.000672)	0.00178	0.000545 JIP	ND (0.000681)	ND (0.000704)	ND (0.000726)	ND (0.000696)	ND (0.000685)	ND (0.000675)	ND (0.000708)	ND (0.000688)	ND (0.000681)	ND (0.000701)
Endrin	0.06	11	0.014	ND (0.000712)	ND (0.000672)	ND (0.000677)	ND (0.000693)	ND (0.000681)	ND (0.000704)	ND (0.000726)	ND (0.000696)	ND (0.000685)	ND (0.000675)	ND (0.000708)	ND (0.000688)	ND (0.000681)	ND (0.000701)
Endrin aldehyde	NA	NA	NA	ND (0.00214)	ND (0.00202)	ND (0.00203)	ND (0.00208)	ND (0.00204)	ND (0.00211)	ND (0.00218)	ND (0.00209)	ND (0.00206)	ND (0.00202)	ND (0.00212)	ND (0.00206)	ND (0.00204)	ND (0.0021)
Endrin ketone	NA	NA	NA	ND (0.00171)	ND (0.00161)	ND (0.00162)	ND (0.00166)	ND (0.00163)	ND (0.00169)	ND (0.00174)	ND (0.00167)	ND (0.00164)	ND (0.00162)	ND (0.0017)	ND (0.00165)	ND (0.00164)	ND (0.00168)
gamma-BHC (Lindane)	0.1	1.3	0.1	ND (0.000712)	ND (0.000672)	ND (0.000677)	ND (0.000693)	ND (0.000681)	ND (0.000704)	ND (0.000726)	ND (0.000696)	ND (0.000685)	ND (0.000675)	ND (0.000708)	ND (0.000688)	ND (0.000681)	ND (0.000701)
gamma-Chlordane (trans)	NA	NA	NA	ND (0.00214)	ND (0.00202)	ND (0.00203)	ND (0.00208)	ND (0.00204)	ND (0.00211)	ND (0.00218)	ND (0.00209)	0.00498	ND (0.00202)	ND (0.00212)	ND (0.00206)	ND (0.00204)	ND (0.0021)
Heptachlor	0.38	2.1	0.042	ND (0.000855)	ND (0.000806)	ND (0.000812)	ND (0.000832)	ND (0.000817)	ND (0.000845)	ND (0.000871)	ND (0.000836)	ND (0.000822)	ND (0.00081)	ND (0.00085)	ND (0.000826)	ND (0.000818)	ND (0.000841)
Heptachlor epoxide	NA	NA	NA	ND (0.00321)	ND (0.00302)	ND (0.00304)	ND (0.00312)	ND (0.00306)	ND (0.00317)	ND (0.00327)	ND (0.00313)	ND (0.00308)	ND (0.00304)	ND (0.00319)	ND (0.0031)	ND (0.00306)	ND (0.00315)
Methoxychlor	NA	NA	NA	ND (0.00321)	ND (0.00302)	ND (0.00304)	ND (0.00312)	ND (0.00306)	ND (0.00317)	ND (0.00327)	ND (0.00313)	ND (0.00308)	ND (0.00304)	ND (0.00319)	ND (0.0031)	ND (0.00306)	ND (0.00315)
Toxaphene	NA	NA	NA	ND (0.0321)	ND (0.0302)	ND (0.0304)	ND (0.0312)	ND (0.0306)	ND (0.0317)	ND (0.0327)	ND (0.0313)	ND (0.0308)	ND (0.0304)	ND (0.0319)	ND (0.031)	ND (0.0306)	ND (0.0315)
Polychlorinated Biphenyls (mg/kg)																	
Aroclor-1016 (PCB-1016)	NA	NA	NA	ND (0.0532)	ND (0.0488)	ND (0.051)	ND (0.0518)	ND (0.05)	ND (0.054)	ND (0.0517)	ND (0.0526)	ND (0.0508)	ND (0.0483)	ND (0.0531)	ND (0.0522)	ND (0.0517)	ND (0.0515)
Aroclor-1221 (PCB-1221)	NA	NA	NA	ND (0.0532)	ND (0.0488)	ND (0.051)	ND (0.0518)	ND (0.05)	ND (0.054)	ND (0.0517)	ND (0.0526)	ND (0.0508)	ND (0.0483)	ND (0.0531)	ND (0.0522)	ND (0.0517)	ND (0.0515)
Aroclor-1232 (PCB-1232)	NA	NA	NA	ND (0.0532)	ND (0.0488)	ND (0.051)	ND (0.0518)	ND (0.05)	ND (0.054)	ND (0.0517)	ND (0.0526)	ND (0.0508)	ND (0.0483)	ND (0.0531)	ND (0.0522)	ND (0.0517)	ND (0.0515)
Aroclor-1242 (PCB-1242)	NA	NA	NA	ND (0.0532)	ND (0.0488)	ND (0.051)	ND (0.0518)	ND (0.05)	ND (0.054)	ND (0.0517)	ND (0.0526)	ND (0.0508)	ND (0.0483)	ND (0.0531)	ND (0.0522)	ND (0.0517)	ND (0.0515)
Aroclor-1248 (PCB-1248)	NA	NA	NA	ND (0.0532)	ND (0.0488)	ND (0.051)	ND (0.0518)	ND (0.05)	ND (0.054)	ND (0.0517)	ND (0.0526)	ND (0.0508)	ND (0.0483)	ND (0.0531)	ND (0.0522)	ND (0.0517)	ND (0.0515)
Aroclor-1254 (PCB-1254)	NA	NA	NA	ND (0.0532)	ND (0.0488)	ND (0.051)	ND (0.0518)	ND (0.05)	ND (0.054)	ND (0.0517)	ND (0.0526)	0.0177 J	ND (0.0483)	ND (0.0531)	ND (0.0522)	ND (0.0517)	ND (0.0515)
Aroclor-1260 (PCB-1260)	NA	NA	NA	ND (0.0532)	ND (0.0488)	0.051	0.02 J	0.0206 J	ND (0.054)	ND (0.0517)	ND (0.0526)	0.0184 J	ND (0.0483)	ND (0.0531)	ND (0.0522)	0.0283 J	ND (0.0515)
Aroclor-1262 (PCB-1262)	NA	NA	NA	ND (0.0532)	ND (0.0488)	ND (0.051)	ND (0.0518)	ND (0.05)	ND (0.054)	ND (0.0517)	ND (0.0526)	ND (0.0508)	ND (0.0483)	ND (0.0531)	ND (0.0522)	ND (0.0517)	ND (0.0515)
Aroclor-1268 (PCB-1268)	NA	NA	NA	ND (0.0532)	ND (0.0488)	ND (0.051)	ND (0.0518)	0.00552 J	ND (0.054)	ND (0.0517)	ND (0.0526)	ND (0.0508)	ND (0.0483)	ND (0.0531)	ND (0.0522)	ND (0.0517)	ND (0.0515)
Polychlorinated biphenyls (PCBs)	3.2	1	0.1	ND (0.0532)	ND (0.0488)	0.051	0.02 J	0.0261 J	ND (0.054)	ND (0.0517)	ND (0.0526)	0.0361 J	ND (0.0483)	ND (0.0531)	ND (0.0522)	0.0283 J	ND (0.0515)

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

Location Name	Criteria			HA-SB12	HA-SB12	HA-SB2	HA-SB2	HA-SB5	HA-SB5	HA-SB5	HA-SB5	HA-SB6	HA-SB6	HA-SB6	HA-SB6	HA-SB8	HA-SB8
Sample Name	Restricted Use Soil Cleanup Objectives - Protection of Groundwater	NY Part 375 Restricted Residential Use Soil Cleanup Objectives	NY Part 375 Unrestricted Use Soil Cleanup Objectives	HA-SB12_15-17	HA-SB12_46-48	HA-SB2_0-0.5	HA-SB2_3-5	HA-SB5_0-0.5	HA-SB5_3-5	HA-SB5_15-17	HA-SB5_48-50	HA-SB6_0-0.5	HA-SB6_6-8	HA-SB6_15-17	HA-SB6_28-40	HA-SB8_0-0.5	HA-SB8_3-5
Sample Date				04/14/2025	04/14/2025	04/24/2025	04/24/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/23/2025	04/15/2025	04/15/2025
Lab Sample ID				L2522786-09	L2522786-10	L2525266-07	L2525266-08	L2525069-03	L2525069-04	L2525069-05	L2525069-06	L2525069-07	L2525069-08	L2525069-09	L2525069-10	L2523120-01	L2523120-02
Sample Depth (bgs)				15 - 17 (ft)	46 - 48 (ft)	0 - 0.5 (ft)	3 - 5 (ft)	0 - 0.5 (ft)	3 - 5 (ft)	15 - 17 (ft)	48 - 50 (ft)	0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	28 - 40 (ft)	0 - 0.5 (ft)	3 - 5 (ft)
Inorganic Compounds (mg/kg)																	
Aluminum	NA	NA	NA	4740	2870	4680	6720	3990	5500	4330	4400	5880	6440	4900	5280	2290	3100
Antimony	NA	NA	NA	ND (4.23)	ND (4.02)	ND (4.16)	ND (4.16)	ND (4.18)	ND (4.26)	ND (4.18)	ND (4.2)	ND (4.24)	ND (4.04)	ND (4.28)	ND (4.05)	ND (4.26)	ND (21.8)
Arsenic	16	16	13	2.48	1.52	6	3.83	3.72	2.04	2.06	2.55	4.97	2.2	1.64	2.8	1.8	2.3 J
Barium	820	400	350	44.8	28.6	129	96.8	57.4	45.9	37.4	43	58.4	43.1	40.1	42.3	19.5	30.8
Beryllium	47	72	7.2	0.417 J	0.186 J	0.403 J	0.615	0.305 J	0.357 J	0.487	0.477	0.372 J	0.314 J	0.482	0.466	0.439	0.317 J
Cadmium	7.5	4.3	2.5	0.128 J	0.078 J	0.861	0.325 J	0.256 J	0.107 J	0.109 J	0.102 J	ND (0.847)	0.123 J	0.127 J	0.112 J	0.174 J	ND (4.36)
Calcium	NA	NA	NA	2630	3720	12200	8910	36900	1480	1340	7050	84000	1250	1170	12000	74200	115000
Chromium	NA	NA	NA	15.1	7.52	15.2	17.2	8.29	12.9	9.82	12.5	13.5	16.8	10.3	12.5	7.48	11.6
Cobalt	NA	NA	NA	4.99	3	4.77	5.78	3.99	4.99	4.54	4.87	3.17	5.03	5.81	4.54	2.76	3.23 J
Copper	1720	270	50	9.95	7.34	51.6	38.2	29.2	13.6	10.3	19.1	26.4	12	13	8.69	14.7	12.6
Iron	NA	NA	NA	10300	6380	12400	11400	8240	10900	8630	8300	8130	10300	10500	8860	6450	7960
Lead	450	400	63	6.63	3.54 J	***465***	38.9	105	5.2	8.86	16.2	45.1	5.28	6.55	13.8	31	38.2
Magnesium	NA	NA	NA	3300	3030	6730	5310	19800	2380	2370	3530	19700	2890	2430	3650	35000	34600
Manganese	2000	2000	1600	285	192	234	405	163	274	261	209	157	224	212	262	161	200
Mercury	0.73	0.81	0.18	ND (0.079)	ND (0.075)	0.317	ND (0.068)	0.111	ND (0.068)	ND (0.074)	ND (0.077)	0.114	ND (0.069)	ND (0.072)	ND (0.067)	0.07 J	ND (0.074)
Nickel	130	310	30	11.6	13.3	17	15.3	12.1	15.1	11.2	9.7	9.6	20.7	14.2	9.41	8.03	9.29 J
Potassium	NA	NA	NA	1210	742	1050	1560	779	1270	1000	1250	987	1280	1070	1780	476	623 J
Selenium	4	180	3.9	ND (1.69)	ND (1.61)	ND (1.66)	ND (1.66)	ND (1.67)	ND (1.71)	ND (1.67)	ND (1.68)	ND (1.69)	ND (1.62)	ND (1.71)	ND (1.62)	ND (1.7)	ND (8.71)
Silver	8.3	180	2	ND (0.423)	ND (0.402)	ND (0.416)	ND (0.416)	ND (0.418)	ND (0.426)	ND (0.418)	ND (0.42)	ND (0.424)	ND (0.404)	ND (0.428)	ND (0.405)	ND (0.426)	ND (2.18)
Sodium	NA	NA	NA	666	293	367	411	138 J	273	134 J	595	266	147 J	112 J	824	ND (170)	ND (871)
Thallium	NA	NA	NA	ND (1.69)	ND (1.61)	ND (1.66)	ND (1.66)	ND (1.67)	ND (1.71)	ND (1.67)	ND (1.68)	ND (1.69)	ND (1.62)	ND (1.71)	ND (1.62)	ND (1.7)	ND (8.71)
Vanadium	NA	NA	NA	16.8	8.82	16.8	19.6	14.9	19.4	15.1	21.6	14.5	20.6	14.3	17.8	9.57	12.2
Zinc	2480	10000	109	28.3	16.4	285	124	91.4	22.4	29.5	34.5	62.3	38.2	42.4	41.8	237	60.4
Other																	
Total Solids (%)	NA	NA	NA	91.5	97.2	93.7	94.2	93.7	91.8	91.5	90.9	92.7	94.8	89.7	94.8	92.9	91.1

ABBREVIATIONS AND NOTES:

mg/kg: milligram per kilogram

**: LCS or LCSD is outside acceptance limits.*
-: Not Analyzed
bgs: below ground surface
F: Results are considered to be an estimated maximum concentration
ft: feet
I: The lower value for the two columns has been reported due to obvious interference.
J: Value is estimated.
NA: Not Applicable
ND (2.5): Not detected, number in parentheses is the laboratory reporting limit
P: The RPD between the results for the two columns exceeds the method-specified criteria.

- For test methods used, see the laboratory data sheets.
- Soil analytical results are compared to the New York State Department of Environmental Conservation (NYSDEC) Title 6 of the Official Compilation of New York Codes, Rules, and Regulations (NYCRR) Part 375 Unrestricted Use Soil Cleanup Objectives (SCO), Restricted-Use Residential SCOs, and Protection of Groundwater SCO's.
*- **Bold italic** values indicate an exceedance of the Protection of Groundwater Criteria.*
- Grey shading indicates an exceedance of the Unrestricted Use Soil Cleanup Objectives.
- Yellow shading indicates an exceedance of the Restricted Use Residential Soil Cleanup Objectives.

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria										
Location Name	Restricted Use	NY Part 375	NY Part 375	HA-SB8	HA-SB8	HA-SB8	HA-SB9	HA-SB9	HA-SB9	HA-SB9	HA-SB9
Sample Name	Soil Cleanup	Restricted	Unrestricted	HA-SB8_15-17	DUP01_20250415	HA-SB8_48-50	HA-SB9_0-0.5	HA-SB9_5-7	HA-SB9_15-17	HA-SB9_32-34	HA-SB9_50-52
Sample Date	Objectives -	Residential Use	Use	04/15/2025	04/15/2025	04/15/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025
Lab Sample ID	Protection of	Soil Cleanup	Soil Cleanup	L2523120-03	L2523120-05	L2523120-04	L2522786-01	L2522786-02	L2522786-03	L2522786-04	L2522786-05
Sample Depth (bgs)	Groundwater	Objectives	Objectives	15 - 17 (ft)	15 - 17 (ft)	48 - 50 (ft)	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	32 - 34 (ft)	50 - 52 (ft)
Volatile Organic Compounds (mg/kg)											
1,1,1,2-Tetrachloroethane	NA	NA	NA	0.024) ND (0.00	ND (0.078)	ND (0.026)	ND (0.00044)	ND (0.00048)	ND (0.00058)	ND (0.14)	ND (0.00048) ND (0.027)
1,1,1-Trichloroethane	0.68	100	0.68	0.024) ND (0.00	ND (0.078)	ND (0.026)	ND (0.00044)	ND (0.00048)	ND (0.00058)	ND (0.14)	ND (0.00048) ND (0.027)
1,1,2,2-Tetrachloroethane	NA	NA	NA	0.024) ND (0.00	ND (0.078)	ND (0.026)	ND (0.00044)	ND (0.00048)	ND (0.00058)	ND (0.14)	ND (0.00048) ND (0.027)
1,1,2-Trichloroethane	NA	NA	NA	(0.049) ND (0.0	ND (0.16)	ND (0.052)	ND (0.00088)	ND (0.00095)	ND (0.0012)	ND (0.27)	ND (0.00096) ND (0.054)
1,1-Dichloroethane	0.27	26	0.27	(0.049) ND (0.0	ND (0.16)	ND (0.052)	ND (0.00088)	ND (0.00095)	ND (0.0012)	ND (0.27)	ND (0.00096) ND (0.054)
1,1-Dichloroethene	0.33	100	0.33	(0.049) ND (0.0	ND (0.16)	ND (0.052)	ND (0.00088)	ND (0.00095)	ND (0.0012)	ND (0.27)	ND (0.00096) ND (0.054)
1,1-Dichloropropene	NA	NA	NA	0.024) ND (0.00	ND (0.078)	ND (0.026)	ND (0.00044)	ND (0.00048)	ND (0.00058)	ND (0.14)	ND (0.00048) ND (0.027)
1,2,3-Trichlorobenzene	NA	NA	NA	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
1,2,3-Trichloropropane	NA	NA	NA	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
1,2,4,5-Tetramethylbenzene	NA	NA	NA	2.1 0.054	3.9	ND (0.1)	ND (0.0018)	0.00023 J	0.0028	14	0.092 0.045 J
1,2,4-Trichlorobenzene	NA	NA	NA	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
1,2,4-Trimethylbenzene	3.6	52	3.6	***10***	***19***	0.028 J	ND (0.0018)	0.00053 J	0.013	***110***	0.45
1,2-Dibromo-3-chloropropane (DBCP)	NA	NA	NA	(0.15) ND (0.00	ND (0.47)	ND (0.16)	ND (0.0026)	ND (0.0028)	ND (0.0035)	ND (0.82)	ND (0.0029) ND (0.16)
1,2-Dibromoethane (Ethylene Dibromide)	NA	NA	NA	(0.049) ND (0.0	ND (0.16)	ND (0.052)	ND (0.00088)	ND (0.00095)	ND (0.0012)	ND (0.27)	ND (0.00096) ND (0.054)
1,2-Dichlorobenzene	1.1	100	1.1	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
1,2-Dichloroethane	0.02	3.1	0.02	(0.049) ND (0.0	ND (0.16)	ND (0.052)	ND (0.00088)	ND (0.00095)	ND (0.0012)	ND (0.27)	ND (0.00096) ND (0.054)
1,2-Dichloroethene (total)	NA	NA	NA	(0.049) ND (0.0	ND (0.16)	ND (0.052)	ND (0.00088)	ND (0.00095)	ND (0.0012)	ND (0.27)	ND (0.00096) ND (0.054)
1,2-Dichloropropane	NA	NA	NA	(0.049) ND (0.0	ND (0.16)	ND (0.052)	ND (0.00088)	ND (0.00095)	ND (0.0012)	ND (0.27)	ND (0.00096) ND (0.054)
1,3,5-Trimethylbenzene	8.4	52	8.4	2.9 0.12	5.6	0.024 J	ND (0.0018)	0.00023 J	0.0034	***38***	0.14
1,3-Dichlorobenzene	2.4	49	2.4	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
1,3-Dichloropropane	NA	NA	NA	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
1,3-Dichloropropene	NA	NA	NA	0.024) ND (0.00	ND (0.078)	ND (0.026)	ND (0.00044)	ND (0.00048)	ND (0.00058)	ND (0.14)	ND (0.00048) ND (0.027)
1,4-Dichlorobenzene	1.8	13	1.8	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
1,4-Diethylbenzene	NA	NA	NA	1 0.02	1.6	ND (0.1)	0.00018 J	0.00032 J	0.0075	ND (0.55)	ND (0.0019) ND (0.11)
1,4-Dioxane	0.1	13	0.1	D (3.9) ND (0.08	ND (12)	ND (4.2)	ND (0.07)	ND (0.076)	ND (0.092)	ND (22)	ND (0.077) ND (4.3)
2,2-Dichloropropane	NA	NA	NA	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
2-Butanone (Methyl Ethyl Ketone)	0.12	100	0.12	) (0.49) ND (0.0	ND (1.6)	ND (0.52)	ND (0.0088)	ND (0.0095)	ND (0.012)	ND (2.7)	ND (0.0096) ND (0.54)
2-Chlorotoluene	NA	NA	NA	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
2-Hexanone (Methyl Butyl Ketone)	NA	NA	NA	) (0.49) ND (0.0	ND (1.6)	ND (0.52)	ND (0.0088)	ND (0.0095)	ND (0.012)	ND (2.7)	ND (0.0096) ND (0.54)
2-Phenylbutane (sec-Butylbenzene)	11	100	11	0.38 0.01	0.73	ND (0.052)	ND (0.00088)	ND (0.00095)	0.00038 J	3.5	0.031 0.016 J
4-Chlorotoluene	NA	NA	NA	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
4-Ethyltoluene (1-Ethyl-4-Methylbenzene)	NA	NA	NA	6.7 0.3	13	0.051 J	ND (0.0018)	0.00043 J	0.0078	91	0.38
4-Methyl-2-Pentanone (Methyl Isobutyl Ketone)	NA	NA	NA	) (0.49) ND (0.0	ND (1.6)	ND (0.52)	ND (0.0088)	ND (0.0095)	ND (0.012)	ND (2.7)	ND (0.0096) ND (0.54)
Acetone	0.05	100	0.05	ND (0.49) 0.011	ND (1.6)	ND (0.52)	ND (0.0088)	0.0072 J	ND (0.012)	ND (2.7)	ND (0.0096) ND (0.54)
Acrylonitrile	NA	NA	NA	) (0.2) ND (0.00	ND (0.62)	ND (0.21)	ND (0.0035)	ND (0.0038)	ND (0.0046)	ND (1.1)	ND (0.0038) ND (0.22)
Benzene	0.06	4.8	0.06	0.018 J 0.00085	ND (0.078)	***0.68***	ND (0.00044)	0.00018 J	0.0002 J	***0.89***	0.055 0.027
Bromobenzene	NA	NA	NA	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
Bromodichloromethane	NA	NA	NA	0.024) ND (0.00	ND (0.078)	ND (0.026)	ND (0.00044)	ND (0.00048)	ND (0.00058)	ND (0.14)	ND (0.00048) ND (0.027)
Bromoform	NA	NA	NA	) (0.2) ND (0.00	ND (0.62)	ND (0.21)	ND (0.0035)	ND (0.0038)	ND (0.0046)	ND (1.1)	ND (0.0038) ND (0.22)
Bromomethane (Methyl Bromide)	NA	NA	NA	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
Carbon disulfide	NA	NA	NA	) (0.49) ND (0.0	ND (1.6)	ND (0.52)	ND (0.0088)	ND (0.0095)	ND (0.012)	ND (2.7)	ND (0.0096) ND (0.54)
Carbon tetrachloride	0.76	2.4	0.76	(0.049) ND (0.0	ND (0.16)	ND (0.052)	ND (0.00088)	ND (0.00095)	ND (0.0012)	ND (0.27)	ND (0.00096) ND (0.054)
Chlorobenzene	1.1	100	1.1	0.024) ND (0.00	ND (0.078)	ND (0.026)	ND (0.00044)	ND (0.00048)	ND (0.00058)	ND (0.14)	ND (0.00048) ND (0.027)
Chlorobromomethane	NA	NA	NA	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
Chloroethane	NA	NA	NA	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
Chloroform (Trichloromethane)	0.37	49	0.37	(0.074) ND (0.0	ND (0.23)	ND (0.078)	ND (0.0013)	ND (0.0014)	ND (0.0017)	ND (0.41)	ND (0.0014) ND (0.081)
Chloromethane (Methyl Chloride)	NA	NA	NA	) (0.2) ND (0.00	ND (0.62)	ND (0.21)	ND (0.0035)	ND (0.0038)	ND (0.0046)	ND (1.1)	ND (0.0038) ND (0.22)
cis-1,2-Dichloroethene	0.25	100	0.25	(0.049) ND (0.0	ND (0.16)	ND (0.052)	ND (0.00088)	ND (0.00095)	ND (0.0012)	ND (0.27)	ND (0.00096) ND (0.054)
cis-1,3-Dichloropropene	NA	NA	NA	0.024) ND (0.00	ND (0.078)	ND (0.026)	ND (0.00044)	ND (0.00048)	ND (0.00058)	ND (0.14)	ND (0.00048) ND (0.027)
Cyclohexane	NA	NA	NA	-	-	-	-	-	-	-	-
Cymene (p-Isopropyltoluene)	NA	NA	NA	0.27 0.012	0.78	ND (0.052)	ND (0.00088)	ND (0.00095)	0.00031 J	2.3	0.02 0.0082 J
Dibromochloromethane	NA	NA	NA	(0.049) ND (0.0	ND (0.16)	ND (0.052)	ND (0.00088)	ND (0.00095)	ND (0.0012)	ND (0.27)	ND (0.00096) ND (0.054)
Dibromomethane	NA	NA	NA	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
Dichlorodifluoromethane (CFC-12)	NA	NA	NA	) (0.49) ND (0.0	ND (1.6)	ND (0.52)	ND (0.0088)	ND (0.0095)	ND (0.012)	ND (2.7)	ND (0.0096) ND (0.54)
Ethyl Ether	NA	NA	NA	(0.098) ND (0.0	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	ND (0.0019) ND (0.11)
Ethylbenzene	1	41	1	***1.5 0.11***	***2.3***	0.11	ND (0.00088)	0.00043 J	0.0016	***27***	0.13

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria										
Location Name	Restricted Use	NY Part 375	NY Part 375	HA-SB8	HA-SB8	HA-SB8	HA-SB9	HA-SB9	HA-SB9	HA-SB9	HA-SB9
Sample Name	Soil Cleanup	Restricted	Unrestricted	HA-SB8_15-17	DUP01_20250415	HA-SB8_48-50	HA-SB9_0-0.5	HA-SB9_5-7	HA-SB9_15-17	HA-SB9_32-34	HA-SB9_50-52
Sample Date	Objectives -	Residential Use	Use	04/15/2025	04/15/2025	04/15/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025
Lab Sample ID	Protection of	Soil Cleanup	Soil Cleanup	L2523120-03	L2523120-05	L2523120-04	L2522786-01	L2522786-02	L2522786-03	L2522786-04	L2522786-05
Sample Depth (bgs)	Groundwater	Objectives	Objectives	15 - 17 (ft)	15 - 17 (ft)	48 - 50 (ft)	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	32 - 34 (ft)	50 - 52 (ft)
Hexachlorobutadiene	NA	NA	NA	(0.2) ND (0.0	ND (0.62)	ND (0.21)	ND (0.0035)	ND (0.0038)	ND (0.0046)	ND (1.1)	ND (0.0038) ND (0.22)
Isopropylbenzene (Cumene)	NA	NA	NA	0.46 0.022	0.81	ND (0.052)	ND (0.00088)	ND (0.00095)	0.00037 J	6	0.076 0.024 J
m,p-Xylenes	NA	NA	NA	5.4 0.44	10	0.16	ND (0.0018)	0.001 J	0.0061	120	0.51
Methyl acetate	NA	NA	NA	-	-	-	-	-	-	-	-
Methyl Tert Butyl Ether (MTBE)	0.93	100	0.93	(0.098) ND (0.0	ND (0.31)	***2.5***	ND (0.0018)	ND (0.0019)	ND (0.0023)	ND (0.55)	0.0037 ND (0.11)
Methylcyclohexane	NA	NA	NA	-	-	-	-	-	-	-	-
Methylene chloride (Dichloromethane)	0.05	100	0.05	(0.24) ND (0.0	ND (0.78)	ND (0.26)	ND (0.0044)	ND (0.0048)	ND (0.0058)	ND (1.4)	ND (0.0048) ND (0.27)
Naphthalene	12	100	12	1.8 0.15	4.5	0.089 J	ND (0.0035)	0.00073 J	0.0056	***18***	0.14 0.088 J
n-Butylbenzene	12	100	12	1 0.019	1.9	ND (0.052)	ND (0.00088)	ND (0.00095)	0.00089 J	8.5	0.048 0.033 J
n-Propylbenzene	3.9	100	3.9	1.6 0.06	2.7	0.013 J	ND (0.00088)	0.00016 J	0.0014	***22***	0.22 0.085
o-Xylene	NA	NA	NA	1.4 0.13	3	0.18	ND (0.00088)	ND (0.00095)	0.0028	46	0.2
Styrene	NA	NA	NA	(0.049) 0.0002	ND (0.16)	ND (0.052)	ND (0.00088)	ND (0.00095)	ND (0.0012)	0.081 J	0.001 ND (0.054)
tert-Butylbenzene	5.9	100	5.9	017 J ND (0.002	ND (0.31)	ND (0.1)	ND (0.0018)	ND (0.0019)	ND (0.0023)	0.12 J	0.0016 J ND (0.11)
Tetrachloroethene	1.3	19	1.3	0.024) ND (0.0	ND (0.078)	ND (0.026)	0.00026 J	ND (0.00048)	ND (0.00058)	ND (0.14)	ND (0.00048) ND (0.027)
Toluene	0.7	100	0.7	0.37 0.029	0.55	0.3	ND (0.00088)	ND (0.00095)	0.0028	***47***	0.42
trans-1,2-Dichloroethene	0.19	100	0.19	(0.074) ND (0.0	ND (0.23)	ND (0.078)	ND (0.0013)	ND (0.0014)	ND (0.0017)	ND (0.41)	ND (0.0014) ND (0.081)
trans-1,3-Dichloropropene	NA	NA	NA	(0.049) ND (0.0	ND (0.16)	ND (0.052)	ND (0.00088)	ND (0.00095)	ND (0.0012)	ND (0.27)	ND (0.00096) ND (0.054)
trans-1,4-Dichloro-2-butene	NA	NA	NA	(0.24) ND (0.0	ND (0.78)	ND (0.26)	ND (0.0044)	ND (0.0048)	ND (0.0058)	ND (1.4)	ND (0.0048) ND (0.27)
Trichloroethene	0.47	21	0.47	0.024) ND (0.0	ND (0.078)	ND (0.026)	ND (0.00044)	ND (0.00048)	ND (0.00058)	ND (0.14)	ND (0.00048) ND (0.027)
Trichlorofluoromethane (CFC-11)	NA	NA	NA	(0.2) ND (0.0	ND (0.62)	ND (0.21)	ND (0.0035)	ND (0.0038)	ND (0.0046)	ND (1.1)	ND (0.0038) ND (0.22)
Trifluorotrichloroethane (Freon 113)	NA	NA	NA	-	-	-	-	-	-	-	-
Vinyl acetate	NA	NA	NA	(0.49) ND (0.0	ND (1.6)	ND (0.52)	ND (0.0088)	ND (0.0095)	ND (0.012)	ND (2.7)	ND (0.0096) ND (0.54)
Vinyl chloride	0.02	0.9	0.02	(0.049) ND (0.0	ND (0.16)	ND (0.052)	ND (0.00088)	ND (0.00095)	ND (0.0012)	ND (0.27)	ND (0.00096) ND (0.054)
Xylene (Total)	1.6	100	0.26	***6.8 0.57***	***13***	0.34	ND (0.00088)	0.001 J	0.0089	***170***	0.71
Semi-Volatile Organic Compounds (mg/kg)											
1,2,4,5-Tetrachlorobenzene	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
1,2,4-Trichlorobenzene	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
1,2-Dichlorobenzene	1.1	100	1.1	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
1,3-Dichlorobenzene	2.4	49	2.4	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
1,4-Dichlorobenzene	1.8	13	1.8	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
1,4-Dioxane	0.1	13	0.1	ND (0.027)	ND (0.026)	ND (0.027)	ND (0.027)	ND (0.027)	ND (0.026)	ND (0.026)	ND (0.027)
2,2'-oxybis(1-Chloropropane)	NA	NA	NA	ND (0.22)	ND (0.21)	ND (0.22)	ND (0.22)	ND (0.22)	ND (0.21)	ND (0.21)	ND (0.22)
2,3,4,6-Tetrachlorophenol	NA	NA	NA	-	-	-	-	-	-	-	-
2,4,5-Trichlorophenol	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2,4,6-Trichlorophenol	NA	NA	NA	ND (0.11)	ND (0.1)	ND (0.11)	ND (0.11)	ND (0.11)	ND (0.1)	ND (0.1)	ND (0.11)
2,4-Dichlorophenol	NA	NA	NA	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)
2,4-Dimethylphenol	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2,4-Dinitrophenol	NA	NA	NA	ND (0.86)	ND (0.84)	ND (0.88)	ND (0.87)	ND (0.87)	ND (0.83)	ND (0.84)	ND (0.87)
2,4-Dinitrotoluene	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2,6-Dinitrotoluene	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2-Chloronaphthalene	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2-Chlorophenol	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2-Methylnaphthalene	NA	NA	NA	0.76	0.7	ND (0.22)	0.039 J	ND (0.22)	ND (0.21)	8.8	0.086 J
2-Methylphenol (o-Cresol)	0.33	100	0.33	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2-Nitroaniline	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
2-Nitrophenol	NA	NA	NA	ND (0.39)	ND (0.38)	ND (0.4)	ND (0.39)	ND (0.39)	ND (0.37)	ND (0.38)	ND (0.39)
3&4-Methylphenol	NA	NA	NA	ND (0.26)	ND (0.25)	ND (0.26)	ND (0.26)	ND (0.26)	ND (0.25)	ND (0.25)	0.028 J
3,3'-Dichlorobenzidine	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
3-Nitroaniline	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
4,6-Dinitro-2-methylphenol	NA	NA	NA	ND (0.47)	ND (0.46)	ND (0.48)	ND (0.47)	ND (0.47)	ND (0.45)	ND (0.45)	ND (0.47)
4-Bromophenyl phenyl ether (BDE-3)	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
4-Chloro-3-methylphenol	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
4-Chloroaniline	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
4-Chlorophenyl phenyl ether	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
4-Methylphenol	0.33	100	0.33	-	-	-	-	-	-	-	-
4-Nitroaniline	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)
4-Nitrophenol	NA	NA	NA	ND (0.25)	ND (0.25)	ND (0.26)	ND (0.25)	ND (0.25)	ND (0.24)	ND (0.24)	ND (0.26)

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria											
Location Name	Restricted Use	NY Part 375	NY Part 375	HA-SB8	HA-SB8	HA-SB8	HA-SB9	HA-SB9	HA-SB9	HA-SB9	HA-SB9	
Sample Name	Soil Cleanup	Restricted	Unrestricted	HA-SB8_15-17	DUP01_20250415	HA-SB8_48-50	HA-SB9_0-0.5	HA-SB9_5-7	HA-SB9_15-17	HA-SB9_32-34	HA-SB9_50-52	
Sample Date	Objectives -	Residential Use	Use	04/15/2025	04/15/2025	04/15/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025	
Lab Sample ID	Protection of	Soil Cleanup	Soil Cleanup	L2523120-03	L2523120-05	L2523120-04	L2522786-01	L2522786-02	L2522786-03	L2522786-04	L2522786-05	
Sample Depth (bgs)	Groundwater	Objectives	Objectives	15 - 17 (ft)	15 - 17 (ft)	48 - 50 (ft)	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	32 - 34 (ft)	50 - 52 (ft)	
Acenaphthene	98	100	20	ND (0.14)	ND (0.14)	ND (0.15)	0.036 J	ND (0.14)	ND (0.14)	0.035 J	ND (0.14)	
Acenaphthylene	107	100	100	ND (0.14)	ND (0.14)	ND (0.15)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	
Acetophenone	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)	
Anthracene	1000	100	100	ND (0.11)	ND (0.1)	ND (0.11)	0.089 J	ND (0.11)	ND (0.1)	ND (0.1)	ND (0.11)	
Atrazine	NA	NA	NA	-	-	-	-	-	-	-	-	
Benzaldehyde	NA	NA	NA	-	-	-	-	-	-	-	-	
Benzo(a)anthracene	1	1	1	ND (0.11)	ND (0.1)	ND (0.11)	0.3	ND (0.11)	ND (0.1)	ND (0.1)	ND (0.11)	
Benzo(a)pyrene	22	1	1	ND (0.14)	ND (0.14)	ND (0.15)	0.37	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	
Benzo(b)fluoranthene	1.7	1	1	ND (0.11)	ND (0.1)	ND (0.11)	0.43	ND (0.11)	ND (0.1)	ND (0.1)	ND (0.11)	
Benzo(g,h,i)perylene	1000	100	100	0.044 J	0.033 J	ND (0.15)	0.25	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	
Benzo(k)fluoranthene	1.7	3.9	0.8	ND (0.11)	ND (0.1)	ND (0.11)	0.14	ND (0.11)	ND (0.1)	ND (0.1)	ND (0.11)	
Benzoic acid	NA	NA	NA	ND (0.58)	ND (0.57)	ND (0.59)	ND (0.58)	ND (0.59)	ND (0.56)	ND (0.56)	ND (0.59)	
Benzyl Alcohol	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)	
Biphenyl	NA	NA	NA	ND (0.41)	ND (0.4)	ND (0.42)	ND (0.41)	ND (0.41)	ND (0.39)	0.16 J	ND (0.42)	
bis(2-Chloroethoxy)methane	NA	NA	NA	ND (0.19)	ND (0.19)	ND (0.2)	ND (0.2)	ND (0.2)	ND (0.19)	ND (0.19)	ND (0.2)	
bis(2-Chloroethyl)ether	NA	NA	NA	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	
bis(2-Ethylhexyl)phthalate	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)	
Butyl benzylphthalate (BBP)	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)	
Caprolactam	NA	NA	NA	-	-	-	-	-	-	-	-	
Carbazole	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	0.048 J	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)	
Chrysene	1	3.9	1	0.019 J	ND (0.1)	ND (0.11)	0.32	ND (0.11)	ND (0.1)	ND (0.1)	ND (0.11)	
Dibenz(a,h)anthracene	1000	0.33	0.33	ND (0.11)	ND (0.1)	ND (0.11)	0.056 J	ND (0.11)	ND (0.1)	ND (0.1)	ND (0.11)	
Dibenzofuran	210	59	7	ND (0.18)	ND (0.18)	ND (0.18)	0.026 J	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)	
Diethyl phthalate	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)	
Dimethyl phthalate	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)	
Di-n-butylphthalate (DBP)	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)	
Di-n-octyl phthalate (DnOP)	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)	
Fluoranthene	1000	100	100	0.029 J	0.023 J	ND (0.11)	0.5	ND (0.11)	ND (0.1)	0.02 J	ND (0.11)	
Fluorene	386	100	30	ND (0.18)	ND (0.18)	ND (0.18)	0.035 J	ND (0.18)	ND (0.17)	0.068 J	ND (0.18)	
Hexachlorobenzene	3.2	1.2	0.33	ND (0.11)	ND (0.1)	ND (0.11)	ND (0.11)	ND (0.11)	ND (0.1)	ND (0.1)	ND (0.11)	
Hexachlorobutadiene	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)	
Hexachlorocyclopentadiene	NA	NA	NA	ND (0.51)	ND (0.5)	ND (0.52)	ND (0.52)	ND (0.52)	ND (0.49)	ND (0.5)	ND (0.52)	
Hexachloroethane	NA	NA	NA	ND (0.14)	ND (0.14)	ND (0.15)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	
Indeno(1,2,3-cd)pyrene	8.2	0.5	0.5	0.033 J	ND (0.14)	ND (0.15)	0.23	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	
Isophorone	NA	NA	NA	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	
Naphthalene	12	100	12	0.64	0.55	ND (0.18)	0.065 J	ND (0.18)	ND (0.17)	9.8	0.11 J	
Nitrobenzene	NA	NA	NA	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	ND (0.16)	
N-Nitrosodi-n-propylamine	NA	NA	NA	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)	
N-Nitrosodiphenylamine	NA	NA	NA	ND (0.14)	ND (0.14)	ND (0.15)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	
Pentachlorophenol	0.8	6.7	0.8	ND (0.14)	ND (0.14)	ND (0.15)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	ND (0.14)	
Phenanthrene	1000	100	100	0.026 J	0.023 J	ND (0.11)	0.32	ND (0.11)	ND (0.1)	0.083 J	ND (0.11)	
Phenol	0.33	100	0.33	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.18)	ND (0.17)	ND (0.17)	ND (0.18)	
Pyrene	1000	100	100	0.031 J	0.025 J	ND (0.11)	0.45	ND (0.11)	ND (0.1)	0.03 J	ND (0.11)	

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria										
Location Name	Restricted Use	NY Part 375	NY Part 375	HA-SB8	HA-SB8	HA-SB8	HA-SB9	HA-SB9	HA-SB9	HA-SB9	HA-SB9
Sample Name	Soil Cleanup	Restricted	Unrestricted	HA-SB8_15-17	DUP01_20250415	HA-SB8_48-50	HA-SB9_0-0.5	HA-SB9_5-7	HA-SB9_15-17	HA-SB9_32-34	HA-SB9_50-52
Sample Date	Objectives -	Residential Use	Use	04/15/2025	04/15/2025	04/15/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025
Lab Sample ID	Protection of	Soil Cleanup	Soil Cleanup	L2523120-03	L2523120-05	L2523120-04	L2522786-01	L2522786-02	L2522786-03	L2522786-04	L2522786-05
Sample Depth (bgs)	Groundwater	Objectives	Objectives	15 - 17 (ft)	15 - 17 (ft)	48 - 50 (ft)	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	32 - 34 (ft)	50 - 52 (ft)
PFAS (mg/kg)											
11-Chloroeicosafluoro-3-Oxaundecane-1-Sulfonic Acid (11Cl-PF3OUdS)	NA	NA	NA	ND (0.000795)	ND (0.000795)	ND (0.000796)	ND (0.000799)	ND (0.000798)	ND (0.000797)	ND (0.000799)	ND (0.000798)
2H,2H,3H,3H-Perfluorooctanoic acid (5:3 FTCA)	NA	NA	NA	ND (0.00497)	ND (0.00497)	ND (0.00497)	ND (0.00499)	ND (0.00499)	ND (0.00498)	ND (0.00499)	ND (0.00499)
3-(Perfluoroheptyl)propanoic acid (7:3 FTCA)	NA	NA	NA	ND (0.00497)	ND (0.00497)	ND (0.00497)	ND (0.00499)	ND (0.00499)	ND (0.00498)	ND (0.00499)	ND (0.00499)
3:3 Fluorotelomer carboxylic acid (3:3 FTCA)	NA	NA	NA	ND (0.000994)	ND (0.000994)	ND (0.000994)	ND (0.000999)	ND (0.000998)	ND (0.000996)	ND (0.000999)	ND (0.000997)
4,8-Dioxa-3H-Perfluorononanoic Acid (ADONA)	NA	NA	NA	ND (0.000795)	ND (0.000795)	ND (0.000796)	ND (0.000799)	ND (0.000798)	ND (0.000797)	ND (0.000799)	ND (0.000798)
4:2 Fluorotelomer sulfonic acid (4:2 FTS)	NA	NA	NA	ND (0.000795)	ND (0.000795)	ND (0.000796)	ND (0.000799)	ND (0.000798)	ND (0.000797)	ND (0.000799)	ND (0.000798)
6:2 Fluorotelomer sulfonic acid (6:2 FTS)	NA	NA	NA	0.00015 J	ND (0.000795)	ND (0.000796)	ND (0.000799)	ND (0.000798)	ND (0.000797)	ND (0.000799)	ND (0.000798)
8:2 Fluorotelomer sulfonic acid (8:2 FTS)	NA	NA	NA	ND (0.000795)	ND (0.000795)	ND (0.000796)	ND (0.000799)	ND (0.000798)	ND (0.000797)	ND (0.000799)	ND (0.000798)
9-Chlorohexadecafluoro-3-Oxanone-1-Sulfonic Acid (9Cl-PF3ONS)	NA	NA	NA	ND (0.000795)	ND (0.000795)	ND (0.000796)	ND (0.000799)	ND (0.000798)	ND (0.000797)	ND (0.000799)	ND (0.000798)
N-Ethyl Perfluorooctanesulfonamidoacetic Acid (NEtFOSAA)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
N-Ethylperfluorooctane sulfonamide (N-EtFOSA)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
N-Ethylperfluorooctane sulfonamidoethanol (N-EtFOSE)	NA	NA	NA	ND (0.00199)	ND (0.00199)	ND (0.00199)	ND (0.002)	ND (0.002)	ND (0.00199)	ND (0.002)	ND (0.00199)
N-Methyl Perfluorooctanesulfonamidoacetic Acid (MeFOSAA)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
N-Methylperfluorooctane sulfonamide (N-MeFOSA)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
N-Methylperfluorooctane sulfonamidoethanol (N-MeFOSE)	NA	NA	NA	ND (0.00199)	ND (0.00199)	ND (0.00199)	ND (0.002)	ND (0.002)	ND (0.00199)	ND (0.002)	ND (0.00199)
Nonafluoro-3,6-dioxaheptanoic acid (NFDHA)	NA	NA	NA	ND (0.000398)	ND (0.000398)	ND (0.000398)	ND (0.0004)	ND (0.000399)	ND (0.000398)	ND (0.0004)	ND (0.000399)
Perfluoro(2-ethoxyethane) sulphonic acid (PFEESA)	NA	NA	NA	ND (0.000398)	ND (0.000398)	ND (0.000398)	ND (0.0004)	ND (0.000399)	ND (0.000398)	ND (0.0004)	ND (0.000399)
Perfluoro(4-methoxybutanoic) acid (PFMBA)	NA	NA	NA	ND (0.000398)	ND (0.000398)	ND (0.000398)	ND (0.0004)	ND (0.000399)	ND (0.000398)	ND (0.0004)	ND (0.000399)
Perfluoro-2-propoxypropanoic acid (PFPrOPrA)(GenX) (HFPO-DA)	NA	NA	NA	ND (0.000795)	ND (0.000795)	ND (0.000796)	ND (0.000799)	ND (0.000798)	ND (0.000797)	ND (0.000799)	ND (0.000798)
Perfluoro-3-methoxypropanoic acid (PFMPA)	NA	NA	NA	ND (0.000398)	ND (0.000398)	ND (0.000398)	ND (0.0004)	ND (0.000399)	ND (0.000398)	ND (0.0004)	ND (0.000399)
Perfluorobutanesulfonic acid (PFBS)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluorobutanoic acid (PFBA)	NA	NA	NA	0.000038 J	ND (0.000795)	ND (0.000796)	ND (0.000799)	ND (0.000798)	0.000039 J	ND (0.000799)	0.000063 J
Perfluorodecanesulfonic acid (PFDS)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluorodecanoic acid (PFDA)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluorododecane sulfonic acid (PFDoDS)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluorododecanoic acid (PFDoDA)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluoroheptanesulfonic acid (PFHpS)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluoroheptanoic acid (PFHpA)	NA	NA	NA	0.000013 J	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluorohexanesulfonic acid (PFHxS)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluorohexanoic acid (PFHxA)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluorononane sulfonic acid (PFNS)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluorononanoic acid (PFNA)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluorooctane sulfonamide (PFOSA)	NA	NA	NA	ND (0.000199)	ND (0.000199)	0.000014 J	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluorooctanesulfonic acid (PFOS)	0.001	0.044	0.00088	0.000104 J	0.000059 J	ND (0.000199)	0.000085 J	0.000058 J	0.000083 J	ND (0.0002)	ND (0.000199)
Perfluorooctanoic acid (PFOA)	0.0008	0.033	0.00066	0.000029 J	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	0.000026 J
Perfluoropentanesulfonic acid (PFPeS)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluoropentanoic acid (PFPeA)	NA	NA	NA	ND (0.000398)	ND (0.000398)	ND (0.000398)	ND (0.0004)	ND (0.000399)	ND (0.000398)	ND (0.0004)	ND (0.000399)
Perfluorotetradecanoic acid (PFTeDA)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluorotridecanoic acid (PFTrDA)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	ND (0.0002)	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)
Perfluoroundecanoic acid (PFUnDA)	NA	NA	NA	ND (0.000199)	ND (0.000199)	ND (0.000199)	0.000016 J	ND (0.0002)	ND (0.000199)	ND (0.0002)	ND (0.000199)

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

Location Name	Criteria			HA-SB8	HA-SB8	HA-SB8	HA-SB9	HA-SB9	HA-SB9	HA-SB9	HA-SB9
Sample Name	Restricted Use Soil Cleanup Objectives - Protection of Groundwater	NY Part 375 Restricted Residential Use Soil Cleanup Objectives	NY Part 375 Unrestricted Use Soil Cleanup Objectives	HA-SB8_15-17	DUP01_20250415	HA-SB8_48-50	HA-SB9_0-0.5	HA-SB9_5-7	HA-SB9_15-17	HA-SB9_32-34	HA-SB9_50-52
Sample Date				04/15/2025	04/15/2025	04/15/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025
Lab Sample ID				L2523120-03	L2523120-05	L2523120-04	L2522786-01	L2522786-02	L2522786-03	L2522786-04	L2522786-05
Sample Depth (bgs)				15 - 17 (ft)	15 - 17 (ft)	48 - 50 (ft)	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	32 - 34 (ft)	50 - 52 (ft)
Pesticides (mg/kg)											
4,4'-DDD	14	13	0.0033	ND (0.00172)	ND (0.00171)	ND (0.00171)	ND (0.00169)	ND (0.0017)	ND (0.00163)	ND (0.0016)	ND (0.00169)
4,4'-DDE	17	8.9	0.0033	ND (0.00172)	ND (0.00171)	ND (0.00171)	ND (0.00169)	ND (0.0017)	ND (0.00163)	ND (0.0016)	ND (0.00169)
4,4'-DDT	136	7.9	0.0033	ND (0.00172)	ND (0.00171)	ND (0.00171)	ND (0.00169)	ND (0.0017)	ND (0.00163)	ND (0.0016)	ND (0.00169)
Aldrin	0.19	0.097	0.005	ND (0.00172)	ND (0.00171)	ND (0.00171)	ND (0.00169)	ND (0.0017)	ND (0.00163)	ND (0.0016)	ND (0.00169)
alpha-BHC	0.02	0.48	0.02	ND (0.000715)	ND (0.000713)	ND (0.000714)	ND (0.000706)	ND (0.000707)	ND (0.000681)	ND (0.000668)	ND (0.000706)
alpha-Chlordane (cis)	2.9	4.2	0.094	ND (0.00214)	ND (0.00214)	ND (0.00214)	ND (0.00212)	ND (0.00212)	ND (0.00204)	ND (0.002)	ND (0.00212)
beta-BHC	0.09	0.36	0.036	ND (0.00172)	ND (0.00171)	ND (0.00171)	ND (0.00169)	ND (0.0017)	ND (0.00163)	ND (0.0016)	ND (0.00169)
Chlordane	NA	NA	NA	ND (0.0143)	ND (0.0142)	ND (0.0143)	ND (0.0141)	ND (0.0141)	ND (0.0136)	ND (0.0134)	ND (0.0141)
delta-BHC	0.25	100	0.04	ND (0.00172)	ND (0.00171)	ND (0.00171)	ND (0.00169)	ND (0.0017)	ND (0.00163)	ND (0.0016)	ND (0.00169)
Dieldrin	0.1	0.2	0.005	ND (0.00107)	ND (0.00107)	ND (0.00107)	ND (0.00106)	ND (0.00106)	ND (0.00102)	ND (0.001)	ND (0.00106)
Endosulfan I	102	24	2.4	ND (0.00172)	ND (0.00171)	ND (0.00171)	ND (0.00169)	ND (0.0017)	ND (0.00163)	ND (0.0016)	ND (0.00169)
Endosulfan II	102	24	2.4	ND (0.00172)	ND (0.00171)	ND (0.00171)	ND (0.00169)	ND (0.0017)	ND (0.00163)	ND (0.0016)	ND (0.00169)
Endosulfan sulfate	1000	24	2.4	ND (0.000715)	ND (0.000713)	ND (0.000714)	ND (0.000706)	ND (0.000707)	ND (0.000681)	ND (0.000668)	ND (0.000706)
Endrin	0.06	11	0.014	ND (0.000715)	ND (0.000713)	ND (0.000714)	ND (0.000706)	ND (0.000707)	ND (0.000681)	ND (0.000668)	ND (0.000706)
Endrin aldehyde	NA	NA	NA	ND (0.00214)	ND (0.00214)	ND (0.00214)	ND (0.00212)	ND (0.00212)	ND (0.00204)	ND (0.002)	ND (0.00212)
Endrin ketone	NA	NA	NA	ND (0.00172)	ND (0.00171)	ND (0.00171)	ND (0.00169)	ND (0.0017)	ND (0.00163)	ND (0.0016)	ND (0.00169)
gamma-BHC (Lindane)	0.1	1.3	0.1	ND (0.000715)	ND (0.000713)	ND (0.000714)	ND (0.000706)	ND (0.000707)	ND (0.000681)	ND (0.000668)	ND (0.000706)
gamma-Chlordane (trans)	NA	NA	NA	ND (0.00214)	ND (0.00214)	ND (0.00214)	ND (0.00212)	ND (0.00212)	ND (0.00204)	ND (0.002)	ND (0.00212)
Heptachlor	0.38	2.1	0.042	ND (0.000858)	ND (0.000855)	ND (0.000857)	ND (0.000847)	ND (0.000848)	ND (0.000817)	ND (0.000802)	ND (0.000847)
Heptachlor epoxide	NA	NA	NA	ND (0.00322)	ND (0.00321)	ND (0.00321)	ND (0.00317)	ND (0.00318)	ND (0.00306)	ND (0.00301)	ND (0.00318)
Methoxychlor	NA	NA	NA	ND (0.00322)	ND (0.00321)	ND (0.00321)	ND (0.00317)	ND (0.00318)	ND (0.00306)	ND (0.00301)	ND (0.00318)
Toxaphene	NA	NA	NA	ND (0.0322)	ND (0.0321)	ND (0.0321)	ND (0.0317)	ND (0.0318)	ND (0.0306)	ND (0.0301)	ND (0.0318)
Polychlorinated Biphenyls (mg/kg)											
Aroclor-1016 (PCB-1016)	NA	NA	NA	ND (0.0519)	ND (0.0508)	ND (0.0515)	ND (0.0498)	ND (0.0534)	ND (0.0498)	ND (0.0509)	ND (0.0524)
Aroclor-1221 (PCB-1221)	NA	NA	NA	ND (0.0519)	ND (0.0508)	ND (0.0515)	ND (0.0498)	ND (0.0534)	ND (0.0498)	ND (0.0509)	ND (0.0524)
Aroclor-1232 (PCB-1232)	NA	NA	NA	ND (0.0519)	ND (0.0508)	ND (0.0515)	ND (0.0498)	ND (0.0534)	ND (0.0498)	ND (0.0509)	ND (0.0524)
Aroclor-1242 (PCB-1242)	NA	NA	NA	ND (0.0519)	ND (0.0508)	ND (0.0515)	ND (0.0498)	ND (0.0534)	ND (0.0498)	ND (0.0509)	ND (0.0524)
Aroclor-1248 (PCB-1248)	NA	NA	NA	ND (0.0519)	ND (0.0508)	ND (0.0515)	ND (0.0498)	ND (0.0534)	ND (0.0498)	ND (0.0509)	ND (0.0524)
Aroclor-1254 (PCB-1254)	NA	NA	NA	ND (0.0519)	ND (0.0508)	ND (0.0515)	ND (0.0498)	ND (0.0534)	ND (0.0498)	ND (0.0509)	ND (0.0524)
Aroclor-1260 (PCB-1260)	NA	NA	NA	ND (0.0519)	ND (0.0508)	ND (0.0515)	0.137	ND (0.0534)	ND (0.0498)	ND (0.0509)	ND (0.0524)
Aroclor-1262 (PCB-1262)	NA	NA	NA	ND (0.0519)	ND (0.0508)	ND (0.0515)	ND (0.0498)	ND (0.0534)	ND (0.0498)	ND (0.0509)	ND (0.0524)
Aroclor-1268 (PCB-1268)	NA	NA	NA	ND (0.0519)	ND (0.0508)	ND (0.0515)	ND (0.0498)	ND (0.0534)	ND (0.0498)	ND (0.0509)	ND (0.0524)
Polychlorinated biphenyls (PCBs)	3.2	1	0.1	ND (0.0519)	ND (0.0508)	ND (0.0515)	0.137	ND (0.0534)	ND (0.0498)	ND (0.0509)	ND (0.0524)

TABLE 2
SUMMARY OF SOIL QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

Location Name	Criteria			HA-SB8	HA-SB8	HA-SB8	HA-SB9	HA-SB9	HA-SB9	HA-SB9	HA-SB9
Sample Name	Restricted Use Soil Cleanup Objectives - Protection of Groundwater	NY Part 375 Restricted Residential Use Soil Cleanup Objectives	NY Part 375 Unrestricted Use Soil Cleanup Objectives	HA-SB8_15-17	DUP01_20250415	HA-SB8_48-50	HA-SB9_0-0.5	HA-SB9_5-7	HA-SB9_15-17	HA-SB9_32-34	HA-SB9_50-52
Sample Date				04/15/2025	04/15/2025	04/15/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025
Lab Sample ID				L2523120-03	L2523120-05	L2523120-04	L2522786-01	L2522786-02	L2522786-03	L2522786-04	L2522786-05
Sample Depth (bgs)				15 - 17 (ft)	15 - 17 (ft)	48 - 50 (ft)	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	32 - 34 (ft)	50 - 52 (ft)
Inorganic Compounds (mg/kg)											
Aluminum	NA	NA	NA	4130	4740	3140	3940	3570	2000	2590	2160
Antimony	NA	NA	NA	ND (4.25)	ND (4.15)	ND (4.38)	ND (4.33)	ND (4.19)	ND (3.94)	ND (4.06)	ND (4.49)
Arsenic	16	16	13	3.39	2.8	2.24	4.71	1.73	1.01	1.31	1.42
Barium	820	400	350	36.3	34	39.5	63.1	35	17.6	19.8	18.8
Beryllium	47	72	7.2	0.578	0.525	0.326 J	0.269 J	0.256 J	0.159 J	0.287 J	0.159 J
Cadmium	7.5	4.3	2.5	0.11 J	0.142 J	0.092 J	0.362 J	0.095 J	0.05 J	0.101 J	0.058 J
Calcium	NA	NA	NA	33000	7280	7310	31600	780	494	895	1380
Chromium	NA	NA	NA	25.6	17.7	8.97	8.4	7.73	4.98	7.79	5.9
Cobalt	NA	NA	NA	3.64	4.32	3.6	5.2	3.93	2.46	3.16	2.46
Copper	1720	270	50	28.7	11.1	7.23	49.8	7.05	4.75	9.3	6.04
Iron	NA	NA	NA	13300	10800	8790	11500	7440	5130	6760	5460
Lead	450	400	63	25.6	10.9	5.99	112	3.87 J	2.9 J	10.4	3.51 J
Magnesium	NA	NA	NA	13200	4770	2200	16400	1760	1140	1600	1770
Manganese	2000	2000	1600	203	206	197	179	189	92.3	142	135
Mercury	0.73	0.81	0.18	ND (0.084)	ND (0.079)	ND (0.077)	0.131	ND (0.08)	ND (0.082)	ND (0.068)	ND (0.075)
Nickel	130	310	30	14	9.76	7.28	10.4	11	8.52	9.42	9.27
Potassium	NA	NA	NA	1060	1140	990	736	900	380	579	464
Selenium	4	180	3.9	ND (1.7)	ND (1.66)	ND (1.75)	ND (1.73)	ND (1.68)	ND (1.57)	ND (1.62)	ND (1.8)
Silver	8.3	180	2	ND (0.425)	ND (0.415)	ND (0.438)	ND (0.433)	ND (0.419)	ND (0.394)	ND (0.406)	ND (0.449)
Sodium	NA	NA	NA	324	319	127 J	236	460	246	277	272
Thallium	NA	NA	NA	ND (1.7)	ND (1.66)	ND (1.75)	ND (1.73)	ND (1.68)	ND (1.57)	ND (1.62)	ND (1.8)
Vanadium	NA	NA	NA	15.9	18.9	14.4	17.8	12.5	7.51	10.3	7.42
Zinc	2480	10000	109	115	41.9	19.6	113	18.9	11.9	21	13.8
Other											
Total Solids (%)	NA	NA	NA	91.6	92.3	89.3	91.5	90.3	95.8	94.8	88.9

ABBREVIATIONS AND NOTES:

mg/kg: milligram per kilogram

**: LCS or LCSD is outside acceptance limits.*
-: Not Analyzed
bgs: below ground surface
F: Results are considered to be an estimated maximum concentration
ft: feet
I: The lower value for the two columns has been reported due to obvious interference.
J: Value is estimated.
NA: Not Applicable
ND (2.5): Not detected, number in parentheses is the laboratory reporting limit
P: The RPD between the results for the two columns exceeds the method-specified criteria.

- For test methods used, see the laboratory data sheets.
- Soil analytical results are compared to the New York State Department of Environmental Conservation (NYSDEC) Title 6 of the Official Compilation of New York Codes, Rules, and Regulations (NYCRR) Part 375 Unrestricted Use Soil Cleanup Objectives (SCO), Restricted-Use Residential SCOs, and Protection of Groundwater SCO's.
*- **Bold italic** values indicate an exceedance of the Protection of Groundwater Criteria.*
- Grey shading indicates an exceedance of the Unrestricted Use Soil Cleanup Objectives.
- Yellow shading indicates an exceedance of the Restricted Use Residential Soil Cleanup Objectives.

TABLE 3
SUMMARY OF WATER QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria		
Location Name	New York TOGS 111 Ambient Water Quality Standards	MW-02	MW-03
Sample Name		MW-02_20250731	MW-03_20250731
Sample Date		07/31/2025	07/31/2025
Lab Sample ID		460-331901-1 460-331902-1	460-331901-2 460-331902-2
Volatile Organic Compounds (ug/L)			
1,1,1-Trichloroethane	5	ND (1)	ND (10)
1,1,2,2-Tetrachloroethane	5	ND (0.2)	ND (2)
1,1,2-Trichloroethane	1	ND (0.58)	ND (5.8)
1,1-Dichloroethane	5	ND (1)	ND (10)
1,1-Dichloroethene	5	ND (1)	ND (10)
1,2,3-Trichlorobenzene	5	ND (1)	ND (10)
1,2,4-Trichlorobenzene	5	ND (1)	ND (10)
1,2,4-Trimethylbenzene	5	6	60
1,2-Dibromo-3-chloropropane (DBCP)	0.04	ND (1)	ND (10)
1,2-Dibromoethane (Ethylene Dibromide)	0.0006	ND (1)	ND (10)
1,2-Dichlorobenzene	3	ND (1)	ND (10)
1,2-Dichloroethane	0.6	ND (0.3)	ND (3)
1,2-Dichloropropane	1	ND (0.92)	ND (9.2)
1,3,5-Trimethylbenzene	5	2	21
1,3-Dichlorobenzene	3	ND (1)	ND (10)
1,4-Dichlorobenzene	3	ND (1)	ND (10)
2-Butanone (Methyl Ethyl Ketone)	50	ND (5)	ND (50)
2-Hexanone (Methyl Butyl Ketone)	50	ND (5)	ND (50)
2-Phenylbutane (sec-Butylbenzene)	5	ND (1)	ND (10)
4-Methyl-2-Pentanone (Methyl Isobutyl Ketone)	NA	ND (5)	ND (50)
Acetone	50	ND (5)	ND (50)
Benzene	1	4	320
Bromodichloromethane	50	ND (0.98)	ND (9.8)
Bromoform	50	ND (1) *	ND (10) *
Bromomethane (Methyl Bromide)	5	ND (1)	ND (10)
Carbon disulfide	60	ND (1)	ND (10)
Carbon tetrachloride	5	ND (1)	ND (10)
Chlorobenzene	5	ND (1)	ND (10)
Chlorobromomethane	5	ND (1)	ND (10)
Chloroethane	5	ND (1)	ND (10)
Chloroform (Trichloromethane)	7	ND (1)	ND (10)
Chloromethane (Methyl Chloride)	5	ND (1)	ND (10)
cis-1,2-Dichloroethene	5	ND (1)	ND (10)
cis-1,3-Dichloropropene	0.4	ND (0.45)	ND (4.5)
Cyclohexane	NA	3.3	23
Dibromochloromethane	50	ND (0.78) *	ND (7.8) *
Dichlorodifluoromethane (CFC-12)	5	ND (1)	ND (10)
Ethylbenzene	5	5	96
Isopropylbenzene (Cumene)	5	0.54 J	12
m,p-Xylenes	5	20	170
Methyl acetate	NA	ND (5)	ND (50)
Methyl Tert Butyl Ether (MTBE)	10	27	16000
Methylcyclohexane	NA	5.2	25
Methylene chloride (Dichloromethane)	5	ND (1)	ND (10)
n-Butylbenzene	5	ND (1)	ND (10)
n-Propylbenzene	5	1.4	17
o-Xylene	5	8.4	57
Styrene	5	ND (1)	ND (10)
tert-Butylbenzene	5	ND (1)	ND (10)
Tetrachloroethene	5	ND (0.4)	ND (4)
Toluene	5	39	380
trans-1,2-Dichloroethene	5	ND (1)	ND (10)
trans-1,3-Dichloropropene	0.4	ND (0.45)	ND (4.5)
Trichloroethene	5	ND (0.28)	ND (2.8)
Trichlorofluoromethane (CFC-11)	5	ND (1)	ND (10)
Trifluorotrichloroethane (Freon 113)	5	ND (1)	ND (10)
Vinyl chloride	2	ND (1)	ND (10)
Xylene (Total)	5	28	230

TABLE 3
SUMMARY OF WATER QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria		
Location Name	New York TOGS 111 Ambient Water Quality Standards	MW-02	MW-03
Sample Name		MW-02_20250731	MW-03_20250731
Sample Date		07/31/2025	07/31/2025
Lab Sample ID		460-331901-1 460-331902-1	460-331901-2 460-331902-2
Semi-Volatile Organic Compounds (ug/L)			
1,2,4,5-Tetrachlorobenzene	5	ND (10)	ND (10)
1,4-Dioxane	0.35	ND (10)	ND (10)
2,2'-oxybis(1-Chloropropane)	5	ND (10)	ND (10)
2,3,4,6-Tetrachlorophenol	NA	ND (10)	ND (10)
2,4,5-Trichlorophenol	NA	ND (10)	ND (10)
2,4,6-Trichlorophenol	NA	ND (3)	ND (3)
2,4-Dichlorophenol	5	ND (10)	ND (10)
2,4-Dimethylphenol	50	ND (10)	ND (10)
2,4-Dinitrophenol	10	ND (40)	ND (40)
2,4-Dinitrotoluene	5	ND (10)	ND (10)
2,6-Dinitrotoluene	5	ND (2)	ND (2)
2-Chloronaphthalene	10	ND (10)	ND (10)
2-Chlorophenol	NA	ND (10)	ND (10)
2-Methylnaphthalene	NA	ND (10)	3.5 J
2-Methylphenol (o-Cresol)	NA	ND (10)	ND (10)
2-Nitroaniline	5	ND (10)	ND (10)
2-Nitrophenol	NA	ND (10)	ND (10)
3&4-Methylphenol	NA	ND (10)	0.85 J
3,3'-Dichlorobenzidine	5	ND (5.2)	ND (5.2)
3-Nitroaniline	5	ND (10)	ND (10)
4,6-Dinitro-2-methylphenol	NA	ND (20)	ND (20)
4-Bromophenyl phenyl ether (BDE-3)	NA	ND (10)	ND (10)
4-Chloro-3-methylphenol	NA	ND (10)	ND (10)
4-Chloroaniline	5	ND (5)	ND (5)
4-Chlorophenyl phenyl ether	NA	ND (10)	ND (10)
4-Methylphenol	NA	ND (10)	0.86 J
4-Nitroaniline	5	ND (10)	ND (10)
4-Nitrophenol	NA	ND (20)	ND (20)
Acenaphthene	20	ND (10)	ND (10)
Acenaphthylene	NA	ND (10)	ND (10)
Acetophenone	NA	ND (10)	ND (10)
Anthracene	50	ND (10)	ND (10)
Atrazine	7.5	ND (2)	ND (2)
Benzaldehyde	NA	ND (10)	ND (10)
Benzo(a)anthracene	0.002	ND (1)	ND (1)
Benzo(a)pyrene	0	ND (1)	ND (1)
Benzo(b)fluoranthene	0.002	ND (2)	ND (2)
Benzo(g,h,i)perylene	NA	ND (10)	ND (10)
Benzo(k)fluoranthene	0.002	ND (1)	ND (1)
Biphenyl	5	ND (5)	ND (5)
bis(2-Chloroethoxy)methane	5	ND (10)	ND (10)
bis(2-Chloroethyl)ether	1	ND (1)	ND (1)
bis(2-Ethylhexyl)phthalate	5	ND (2)	ND (2)
Butyl benzylphthalate (BBP)	50	ND (10)	ND (10)
Caprolactam	NA	ND (10)	ND (10)
Carbazole	NA	ND (10)	ND (10)
Chrysene	0.002	ND (2)	ND (2)
Dibenz(a,h)anthracene	NA	ND (1)	ND (1)
Dibenzofuran	NA	ND (10)	ND (10)
Diethyl phthalate	50	ND (10)	ND (10)
Dimethyl phthalate	50	ND (10)	ND (10)
Di-n-butylphthalate (DBP)	50	ND (10)	ND (10)
Di-n-octyl phthalate (DnOP)	50	ND (10)	ND (10)
Fluoranthene	50	ND (10)	ND (10)
Fluorene	50	ND (10)	ND (10)
Hexachlorobenzene	0.04	ND (1)	ND (1)
Hexachlorobutadiene	0.5	ND (1)	ND (1)
Hexachlorocyclopentadiene	5	ND (10)	ND (10)
Hexachloroethane	5	ND (0.8)	ND (0.8)
Indeno(1,2,3-cd)pyrene	0.002	ND (2)	ND (2)
Isophorone	50	ND (10)	ND (10)
Naphthalene	10	ND (2) *	11 *
Nitrobenzene	0.4	ND (1)	ND (1)
N-Nitrosodi-n-propylamine	NA	ND (1)	ND (1)
N-Nitrosodiphenylamine	50	ND (10)	ND (10)
Pentachlorophenol	1	ND (20)	ND (20)
Phenanthrene	50	ND (10)	ND (10)
Phenol	1	ND (10)	1 J
Pyrene	50	ND (10)	ND (10)
Semi-Volatile Organic Compounds (SIM) (ug/L)			
1,4-Dioxane	0.35	0.64	1.6

TABLE 3
SUMMARY OF WATER QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria		
Location Name	New York TOGS 111 Ambient Water Quality Standards	MW-02	MW-03
Sample Name		MW-02_20250731	MW-03_20250731
Sample Date		07/31/2025	07/31/2025
Lab Sample ID		460-331901-1 460-331902-1	460-331901-2 460-331902-2
PFAS (ug/L)			
11-Chloroeicosafluoro-3-Oxaundecane-1-Sulfonic Acid (11Cl-PF3OUdS)	NA	ND (0.00156)	ND (0.00193)
2H,2H,3H,3H-Perfluorooctanoic acid (5:3 FTCA)	NA	ND (0.00782)	ND (0.00967)
3-(Perfluoroheptyl)propanoic acid (7:3 FTCA)	NA	ND (0.00782)	ND (0.00967)
3:3 Fluorotelomer carboxylic acid (3:3 FTCA)	NA	ND (0.00313)	ND (0.00387)
4,8-Dioxa-3H-Perfluorononanoic Acid (ADONA)	NA	ND (0.00156)	ND (0.00193)
4:2 Fluorotelomer sulfonic acid (4:2 FTS)	NA	ND (0.00313)	ND (0.00387)
6:2 Fluorotelomer sulfonic acid (6:2 FTS)	NA	0.0124	0.00375 J
8:2 Fluorotelomer sulfonic acid (8:2 FTS)	NA	ND (0.00313)	ND (0.00387)
9-Chlorohexadecafluoro-3-Oxanone-1-Sulfonic Acid (9Cl-PF3ONS)	NA	ND (0.00156)	ND (0.00193)
N-Ethyl Perfluorooctanesulfonamidoacetic Acid (NEtFOSAA)	NA	ND (0.00156)	ND (0.00193)
N-Ethylperfluorooctane sulfonamide (N-EtFOSA)	NA	ND (0.00156)	ND (0.00193)
N-Ethylperfluorooctane sulfonamidoethanol (N-EtFOSE)	NA	ND (0.00782)	ND (0.00967)
N-Methyl Perfluorooctanesulfonamidoacetic Acid (MeFOSAA)	NA	ND (0.00156)	ND (0.00193)
N-Methylperfluorooctane sulfonamide (N-MeFOSA)	NA	ND (0.00156)	ND (0.00193)
N-Methylperfluorooctane sulfonamidoethanol (N-MeFOSE)	NA	ND (0.00782)	ND (0.00967)
Nonafluoro-3,6-dioxaheptanoic acid (NFDHA)	NA	ND (0.00156)	ND (0.00193)
Perfluoro(2-ethoxyethane) sulphonic acid (PFEESA)	NA	ND (0.00156)	ND (0.00193)
Perfluoro(4-methoxybutanoic) acid (PFMBA)	NA	ND (0.00156)	ND (0.00193)
Perfluoro-2-propoxypropanoic acid (PFPrOPrA)(GenX) (HFPO-DA)	NA	0.00076 J	0.00055 J
Perfluoro-3-methoxypropanoic acid (PFMPA)	NA	ND (0.00156)	ND (0.00193)
Perfluorobutanesulfonic acid (PFBS)	NA	0.00968	0.0081
Perfluorobutanoic acid (PFBA)	NA	0.0174	0.0173
Perfluorodecanesulfonic acid (PFDS)	NA	ND (0.00156)	ND (0.00193)
Perfluorodecanoic acid (PFDA)	NA	ND (0.00156)	ND (0.00193)
Perfluorododecane sulfonic acid (PFDoDS)	NA	ND (0.00156)	ND (0.00193)
Perfluorododecanoic acid (PFDoDA)	NA	ND (0.00156)	ND (0.00193)
Perfluoroheptanesulfonic acid (PFHpS)	NA	ND (0.00156)	ND (0.00193)
Perfluoroheptanoic acid (PFHpA)	NA	0.00978	0.00952
Perfluorohexanesulfonic acid (PFHxS)	NA	0.00524	0.00523
Perfluorohexanoic acid (PFHxA)	NA	0.0218	0.017
Perfluorononane sulfonic acid (PFNS)	NA	ND (0.00156)	ND (0.00193)
Perfluorononanoic acid (PFNA)	NA	0.0015 J	0.0016 J
Perfluorooctane sulfonamide (PFOSA)	NA	ND (0.00156)	ND (0.00193)
Perfluorooctanesulfonic acid (PFOS)	0.0027	0.0087	0.00614
Perfluorooctanoic acid (PFOA)	0.0067	0.077	0.102
Perfluoropentanesulfonic acid (PFPeS)	NA	ND (0.00156)	0.00061 J
Perfluoropentanoic acid (PFPeA)	NA	0.0281	0.0205
Perfluorotetradecanoic acid (PFTeDA)	NA	ND (0.00156)	ND (0.00193)
Perfluorotridecanoic acid (PFTrDA)	NA	ND (0.00156)	ND (0.00193)
Perfluoroundecanoic acid (PFUnDA)	NA	ND (0.00156)	ND (0.00193)
Pesticides (ug/L)			
4,4'-DDD	0.3	ND (0.02) *	ND (0.02) *
4,4'-DDE	0.2	ND (0.02) *	ND (0.02) *
4,4'-DDT	0.2	ND (0.02) *	ND (0.02) *
Aldrin	0	ND (0.02)	ND (0.02)
alpha-BHC	0.01	ND (0.02)	ND (0.02)
alpha-Chlordane (cis)	NA	ND (0.02) *	ND (0.02) *
beta-BHC	0.04	ND (0.02)	ND (0.02)
Chlordane	0.05	ND (0.2)	ND (0.2)
delta-BHC	0.04	ND (0.02)	ND (0.02)
Dieldrin	0.004	ND (0.02) *	ND (0.02) *
Endosulfan I	NA	ND (0.02) *	ND (0.02) *
Endosulfan II	NA	ND (0.02) *	ND (0.02) *
Endosulfan sulfate	NA	ND (0.02) *	ND (0.02) *
Endrin	0	ND (0.02) *	ND (0.02) *
Endrin aldehyde	5	ND (0.02) *	ND (0.02) *
Endrin ketone	5	ND (0.02) *	ND (0.02) *
gamma-BHC (Lindane)	0.05	ND (0.02)	ND (0.02)
Heptachlor	0.04	ND (0.02)	ND (0.02)
Heptachlor epoxide	0.03	ND (0.02) *	ND (0.02) *
Methoxychlor	35	ND (0.02) *	ND (0.02) *
Toxaphene	0.06	ND (0.5)	ND (0.5)
Polychlorinated Biphenyls (ug/L)			
Aroclor-1016 (PCB-1016)	NA	ND (0.2)	ND (0.2)
Aroclor-1221 (PCB-1221)	NA	ND (0.2)	ND (0.2)
Aroclor-1232 (PCB-1232)	NA	ND (0.2)	ND (0.2)
Aroclor-1242 (PCB-1242)	NA	ND (0.2)	ND (0.2)
Aroclor-1248 (PCB-1248)	NA	ND (0.2)	ND (0.2)
Aroclor-1254 (PCB-1254)	NA	ND (0.2)	ND (0.2)
Aroclor-1260 (PCB-1260)	NA	ND (0.2)	ND (0.2)
Aroclor-1262 (PCB-1262)	NA	ND (0.2)	ND (0.2)
Aroclor-1268 (PCB-1268)	NA	ND (0.2)	ND (0.2)
Total PCBs	NA	ND (0.2)	ND (0.2)

TABLE 3
SUMMARY OF WATER QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

	Criteria		
Location Name	New York TOGS 111 Ambient Water Quality Standards	MW-02	MW-03
Sample Name		MW-02_20250731	MW-03_20250731
Sample Date		07/31/2025	07/31/2025
Lab Sample ID		460-331901-1 460-331902-1	460-331901-2 460-331902-2
Inorganic Compounds (ug/L)			
Aluminum, Dissolved	NA	ND (40)	ND (40)
Antimony, Dissolved	3	ND (2)	ND (2)
Arsenic, Dissolved	25	ND (2)	3.9
Barium, Dissolved	1000	343	699
Beryllium, Dissolved	3	ND (0.8)	ND (0.8)
Cadmium, Dissolved	5	0.32 J	ND (0.92)
Calcium, Dissolved	NA	135000	223000
Chromium, Dissolved	50	ND (4)	ND (4)
Cobalt, Dissolved	NA	5.6	2.2
Copper, Dissolved	200	ND (4)	ND (4)
Iron, Dissolved	300	ND (120)	ND (120)
Lead, Dissolved	25	ND (1.2)	ND (1.2)
Magnesium, Dissolved	35000	26900	56400
Manganese, Dissolved	300	2160	3690
Mercury, Dissolved	0.7	ND (0.2)	ND (0.2)
Nickel, Dissolved	100	22.4	28.1
Potassium, Dissolved	NA	8350	8160
Selenium, Dissolved	10	1.6 J	ND (2.5)
Silver, Dissolved	50	ND (2)	ND (2)
Sodium, Dissolved	20000	707000	489000
Thallium, Dissolved	0.5	ND (0.5)	ND (0.5)
Vanadium, Dissolved	NA	ND (4)	ND (4)
Zinc, Dissolved	2000	ND (16)	ND (16)
Aluminum, Total	NA	339	75.6
Antimony, Total	3	ND (2)	ND (2)
Arsenic, Total	25	ND (2)	9.5
Barium, Total	1000	318	723
Beryllium, Total	3	ND (0.8)	ND (0.8)
Cadmium, Total	5	0.33 J	ND (0.92)
Calcium, Total	NA	136000	230000
Chromium, Total	50	12.8	7.1
Cobalt, Total	NA	5.9	2.2
Copper, Total	200	ND (4)	ND (4)
Iron, Total	300	562	5920
Lead, Total	25	ND (1.2)	ND (1.2)
Magnesium, Total	35000	27700	59500
Manganese, Total	300	2170	3860
Mercury, Total	0.7	ND (0.2)	ND (0.2)
Nickel, Total	100	29.1	33.1
Potassium, Total	NA	8030	8140
Selenium, Total	10	1.1 J	ND (2.5)
Silver, Total	50	ND (2)	ND (2)
Sodium, Total	20000	671000	495000
Thallium, Total	0.5	ND (0.5)	ND (0.5)
Vanadium, Total	NA	1.7 J	0.71 J
Zinc, Total	2000	7.9 J	ND (16)

ABBREVIATIONS AND NOTES:

ug/L: micrograms per liter

-: Not Analyzed
**: LCS or LCSD is outside acceptance limits.*
J: Value is estimated.
NA: Not Applicable
ND (2.5): Not detected, number in parentheses is the laboratory reporting limit

- For test methods used, see the laboratory data sheets.
- Groundwater analytical results are compared to NY-AWQS: NYSDEC Technical and Operational Guidance Series (TOGS) 1.1.1 Ambient Water Quality Standards and Guidance Values (SGVs) for Class GA Water.
- Grey shading indicates an exceedance of the AWQS criteria.

TABLE 4
SUMMARY OF SOIL GAS QUALITY DATA
4001 4TH AVE
BROOKLYN, NEW YORK
FILE NO. 0210815

Location Name	SV-01	SV-02	SV-03	SV-04	SV-05	SV-06	SV-07
Sample Name	SV-01-20250701	SV-02-20250701	SV-03-20250701	SV-04-20250701	SV-05-20250701	SV-06-20250701	SV-07-20250701
Sample Date	07/01/2025	07/01/2025	07/01/2025	07/01/2025	07/01/2025	07/01/2025	07/01/2025
Lab Sample ID	L2541324-03	L2541324-02	L2541324-01	L2541324-04	L2541324-05	L2541324-06	L2541324-07
Volatile Organic Compounds (ug/m3)							
1,1,1-Trichloroethane	ND (4540)	ND (4540)	ND (3.21)	ND (15.4)	ND (6820)	ND (13600)	ND (3900)
1,1,2,2-Tetrachloroethane	ND (5720)	ND (5720)	ND (4.04)	ND (19.4)	ND (8580)	ND (17200)	ND (4900)
1,1,2-Trichloroethane	ND (4540)	ND (4540)	ND (3.21)	ND (15.4)	ND (6820)	ND (13600)	ND (3900)
1,1-Dichloroethane	ND (3370)	ND (3370)	ND (2.38)	ND (11.4)	ND (5060)	ND (10100)	ND (2890)
1,1-Dichloroethene	ND (3300)	ND (3300)	ND (2.33)	ND (11.2)	ND (4960)	ND (9910)	ND (2830)
1,2,4-Trichlorobenzene	ND (6180)	ND (6180)	ND (4.36)	ND (20.9)	ND (9280)	ND (18600)	ND (5300)
1,2,4-Trimethylbenzene	4100	ND (4100)	28.4	85.5	ND (6150)	ND (12300)	ND (3510)
1,2-Dibromoethane (Ethylene Dibromide)	ND (6400)	ND (6400)	ND (4.52)	ND (21.7)	ND (9610)	ND (19200)	ND (5490)
1,2-Dichlorobenzene	ND (5010)	ND (5010)	ND (3.54)	ND (17)	ND (7520)	ND (15000)	ND (4290)
1,2-Dichloroethane	ND (3370)	ND (3370)	ND (2.38)	ND (11.4)	ND (5060)	ND (10100)	ND (2890)
1,2-Dichloropropane	ND (3850)	ND (3850)	ND (2.72)	ND (13)	ND (5780)	ND (11600)	ND (3300)
1,2-Dichlorotetrafluoroethane (CFC 114)	ND (5820)	ND (5820)	ND (4.11)	ND (19.7)	ND (8740)	ND (17500)	ND (4990)
1,3,5-Trimethylbenzene	ND (4100)	ND (4100)	9.14	25.2	ND (6150)	ND (12300)	ND (3510)
1,3-Butadiene	ND (1840)	ND (1840)	53.1	156	ND (2770)	ND (5530)	ND (1580)
1,3-Dichlorobenzene	ND (5010)	ND (5010)	ND (3.54)	ND (17)	ND (7520)	ND (15000)	ND (4290)
1,4-Dichlorobenzene	ND (5010)	ND (5010)	ND (3.54)	ND (17)	ND (7520)	ND (15000)	ND (4290)
1,4-Dioxane	ND (3000)	ND (3000)	ND (2.12)	ND (10.2)	ND (4500)	ND (9010)	ND (2570)
2,2,4-Trimethylpentane	6540000	3810000	1000	16600	16200000	4350000	2690000
2-Butanone (Methyl Ethyl Ketone)	ND (6130)	ND (6130)	20.4	38	ND (9200)	ND (18400)	ND (5250)
2-Hexanone (Methyl Butyl Ketone)	ND (3410)	ND (3410)	ND (2.41)	ND (11.6)	ND (5120)	ND (10200)	ND (2930)
4-Ethyltoluene (1-Ethyl-4-Methylbenzene)	ND (4100)	ND (4100)	11.7	35.3	ND (6150)	ND (12300)	ND (3510)
4-Methyl-2-Pentanone (Methyl Isobutyl Ketone)	ND (8520)	ND (8520)	8.61	46.3	21500	ND (25600)	ND (7290)
Acetone	ND (9910)	ND (9910)	582	487	ND (14800)	ND (29700)	ND (8480)
Allyl chloride	ND (2610)	ND (2610)	ND (1.84)	ND (8.83)	ND (3910)	ND (7830)	ND (2230)
Benzene	19400	ND (2660)	85.9	626	6770	696000	4340
Benzyl Chloride (alpha-Chlorotoluene)	ND (4310)	ND (4310)	ND (3.04)	ND (14.6)	ND (6470)	ND (12900)	ND (3700)
Bromodichloromethane	ND (5580)	ND (5580)	ND (3.94)	ND (18.9)	ND (8370)	ND (16700)	ND (4780)
Bromoform	ND (8610)	ND (8610)	ND (6.08)	ND (29.2)	ND (12900)	ND (25800)	ND (7380)
Bromomethane (Methyl Bromide)	ND (3230)	ND (3230)	ND (2.28)	ND (11)	ND (4850)	ND (9710)	ND (2770)
Carbon disulfide	ND (2590)	ND (2590)	46.1	205	ND (3890)	ND (7790)	ND (2220)
Carbon tetrachloride	ND (5240)	ND (5240)	ND (3.7)	ND (17.7)	ND (7860)	ND (15700)	ND (4490)
Chlorobenzene	ND (3840)	ND (3840)	ND (2.71)	ND (13)	ND (5760)	ND (11500)	ND (3290)
Chloroethane	ND (2200)	ND (2200)	ND (1.55)	ND (7.44)	ND (3300)	ND (6600)	ND (1880)
Chloroform (Trichloromethane)	ND (4070)	ND (4070)	ND (2.87)	ND (13.8)	ND (6100)	ND (12200)	ND (3490)
Chloromethane (Methyl Chloride)	ND (1720)	ND (1720)	1.6	ND (5.82)	ND (2580)	ND (5160)	ND (1470)
cis-1,2-Dichloroethene	ND (3300)	ND (3300)	ND (2.33)	ND (11.2)	ND (4960)	ND (9910)	ND (2830)
cis-1,3-Dichloropropene	ND (3780)	ND (3780)	ND (2.67)	ND (12.8)	ND (5670)	ND (11300)	ND (3240)
Cyclohexane	178000	103000	170	1710	626000	1030000	465000
Dibromochloromethane	ND (7100)	ND (7100)	ND (5.01)	ND (24)	ND (10600)	ND (21300)	ND (6080)
Dichlorodifluoromethane (CFC-12)	ND (4120)	ND (4120)	3.15	ND (13.9)	ND (6180)	ND (12400)	ND (3530)
Ethanol	ND (39200)	ND (39200)	260	407	ND (58800)	ND (118000)	ND (33500)
Ethyl acetate	ND (7500)	ND (7500)	ND (5.3)	ND (25.4)	ND (11200)	ND (22500)	ND (6410)
Ethylbenzene	9990	ND (3620)	40.6	119	ND (5430)	ND (10900)	ND (3100)
Hexachlorobutadiene	ND (8890)	ND (8890)	ND (6.27)	ND (30.1)	ND (13300)	ND (26700)	ND (7620)
Hexane	592000	412000	617	7930	2010000	2220000	1150000
Isopropyl Alcohol (2-Propanol)	ND (10300)	ND (10300)	55.1	88.5	ND (15400)	ND (30700)	ND (8780)
m,p-Xylenes	27100	ND (7250)	161	452	ND (10900)	ND (21700)	ND (6210)
Methyl Tert Butyl Ether (MTBE)	ND (3000)	ND (3000)	ND (2.12)	ND (10.2)	ND (4510)	ND (9010)	ND (2570)
Methylene chloride (Dichloromethane)	ND (7230)	ND (7230)	ND (5.11)	ND (24.5)	ND (10800)	ND (21700)	ND (6180)
Naphthalene	ND (4150)	ND (4150)	ND (2.93)	ND (14.1)	ND (6240)	ND (12500)	ND (3550)
N-Heptane	184000	74600	218	1860	389000	729000	566000
o-Xylene	4950	ND (3620)	60.8	164	ND (5430)	ND (10900)	ND (3100)
Styrene	ND (3550)	ND (3550)	ND (2.5)	ND (12)	ND (5320)	ND (10600)	ND (3040)
Tert-Butyl Alcohol (tert-Butanol)	ND (6310)	ND (6310)	76.1	88.2	ND (9460)	ND (18900)	ND (5400)
Tetrachloroethene	ND (5650)	ND (5650)	572	ND (19.1)	ND (8480)	ND (17000)	ND (4840)
Tetrahydrofuran	ND (6130)	ND (6130)	13.8	24.5	ND (9200)	ND (18400)	ND (5250)
Toluene	27000	ND (3140)	254	1210	5880	243000	ND (2690)
trans-1,2-Dichloroethene	ND (3300)	ND (3300)	ND (2.33)	ND (11.2)	ND (4960)	ND (9910)	ND (2830)
trans-1,3-Dichloropropene	ND (3780)	ND (3780)	ND (2.67)	ND (12.8)	ND (5670)	ND (11300)	ND (3240)
Trichloroethene	ND (4480)	ND (4480)	19.7	ND (15.2)	ND (6720)	ND (13400)	ND (3840)
Trichlorofluoromethane (CFC-11)	ND (4680)	ND (4680)	ND (3.3)	ND (15.8)	ND (7020)	ND (14000)	ND (4010)
Trifluorotrichloroethane (Freon 113)	ND (6380)	ND (6380)	ND (4.51)	ND (21.6)	ND (9580)	ND (19200)	ND (5470)
Vinyl Bromide (Bromoethene)	ND (3640)	ND (3640)	ND (2.57)	ND (12.3)	ND (5470)	ND (10900)	ND (3120)
Vinyl chloride	ND (2130)	ND (2130)	ND (1.5)	ND (7.21)	ND (3200)	ND (6390)	ND (1830)
SUM of VOCs	7586540	4399600	4368.2	32357.5	19259150	9268000	4875340
SUM of CVOCs	ND	ND	591.7	ND	ND	ND	ND
SUM of BTEX	88440	ND	602.3	2571	12650	939000	4340


ABBREVIATIONS AND NOTES:

$\mu g/m^3$: micrograms per cubic meter

-: Not Analyzed
NA: Not Applicable
ND (2.5): Not detected, number in parentheses is the laboratory reporting limit

- For test methods used, see the laboratory data sheets.
- SUM of CVOCs includes the following compounds: carbon tetrachloride, 1,1-dichloroethene, cis-1,2-dichloroethene, trichloroethene, methylene chloride, tetrachloroethene, 1,1,1-trichloroethane, vinyl chloride

FIGURES







HALEY ALDRICH

4001 4TH AVENUE
BROOKLYN, NEW YORK


PROJECT LOCUS

MAP SOURCE: USGS
SITE COORDINATES: 40°39'06"N, 74°00'24"W

APPROXIMATE SCALE: 1 IN = 2000 FT
OCTOBER 2025

FIGURE 1

GIS: \\haleyaldrich\share\CF\Projects\0210815\GIS\210815_4TH_AVE_BROOKLYN\210815_4TH_AVE_BROOKLYN.aprx - mmjones - 4/17/2024 9:47 AM



HA-SB11

	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB11
	HA-SB11_0-0.5	HA-SB11_4-6	HA-SB11_15-17	DUP02_20250424	HA-SB11_40-42
	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025
	Primary	Primary	Primary	Duplicate	Primary
	L2525266-02	L2525266-03	L2525266-04	L2525266-05	L2525266-06
	0 - 0.5 (ft)	4 - 6 (ft)	15 - 17 (ft)	15 - 17 (ft)	40 - 42 (ft)
Volatile Organic Compounds (mg/kg)					
1,2,4-Trimethylbenzene	0.38	3.5	**110**	**140**	***120***
1,3,5-Trimethylbenzene	0.2	1.2	**29**	**37**	***39***
Benzene	**0.77**	**0.54**	**6.3**	**8.1**	***21***
Ethylbenzene	0.54	**2.6**	**32**	**40**	***48***
Naphthalene	0.99	2.1	**17**	**22**	***26***
n-Propylbenzene	3.2	**6.1**	**17**	**22**	***21***
Toluene	**1.5**	**3.6**	**140**	**170**	***260***
Xylene (Total)	**2.1**	**6.9**	**190**	**250**	***270***

HA-SB12

	HA-SB12	HA-SB12	HA-SB12	HA-SB12
	HA-SB12_0-0.5	HA-SB12_8-10	HA-SB12_15-17	HA-SB12_46-48
	04/14/2025	04/14/2025	04/14/2025	04/14/2025
	Primary	Primary	Primary	Primary
	L2522786-07	L2522786-08	L2522786-09	L2522786-10
	0 - 0.5 (ft)	8 - 10 (ft)	15 - 17 (ft)	46 - 48 (ft)
Volatile Organic Compounds (mg/kg)				
1,2,4-Trimethylbenzene	0.0065	**33**	**12**	0.012
Benzene	ND (0.00045)	0.042	**0.082**	0.00015 J
Ethylbenzene	0.0002 J	**2**	**2.7**	0.0026
n-Propylbenzene	0.00043 J	**4.1**	1.9	0.0019
Toluene	ND (0.00089)	0.11	**5.1**	0.0052
Xylene (Total)	0.0017 J	**7.9**	**16**	0.014

HA-SB1

	HA-SB1	HA-SB1	HA-SB1	HA-SB1
	HA-SB1_0-0.5	HA-SB1_6-8	HA-SB1_15-17	HA-SB1_38-40
	04/23/2025	04/23/2025	04/23/2025	04/23/2025
	Primary	Primary	Primary	Primary
	L2525069-11	L2525069-12	L2525069-13	L2525069-14
	0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	38 - 40 (ft)
Volatile Organic Compounds (mg/kg)				
1,2,4-Trimethylbenzene	0.0019 J	0.0021 J	**370**	2.5
1,3,5-Trimethylbenzene	0.00066 J	0.00079 J	**75**	0.83
Benzene	ND (0.0015)	0.0033	**0.19 J**	**0.3**
Ethylbenzene	0.00059 J	0.001 J	**41**	0.89
Naphthalene	0.0078 J	0.0017 J	**58**	0.35
n-Propylbenzene	ND (0.003)	0.00074 J	**39**	0.41
Toluene	0.0016 J	0.0058	**1.2**	**13**
Xylene (Total)	0.0026 J	0.0089	**180**	**5.3**

HA-SB10

	HA-SB10	HA-SB10	HA-SB10	HA-SB10
	HA-SB10_0-0.5	HA-SB10_5-7	HA-SB10_15-17	HA-SB10_43-45
	07/15/2025	07/15/2025	07/15/2025	07/15/2025
	Primary	Primary	Primary	Primary
	460-330741-1	460-330741-2	460-330741-3	460-330741-4
	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	43 - 45 (ft)
Volatile Organic Compounds (mg/kg)				
Benzene	0.003	ND (0.088)	0.054 J	***1.1***
Chloroform (Trichloromethane)	0.0019	***10***	ND (0.079)	ND (0.086)
Methyl Tert Butyl Ether (MTBE)	ND (0.0011)	ND (0.088)	ND (0.079)	***2.1***
Ethylbenzene	ND (0.0011)	0.027 J	***6.5***	0.46
Toluene	0.0012	ND (0.088)	***1.5***	***2.2***

HA-SB9

	HA-SB9	HA-SB9	HA-SB9	HA-SB9	HA-SB9
	HA-SB9_0-0.5	HA-SB9_5-7	HA-SB9_15-17	HA-SB9_32-34	HA-SB9_50-52
	04/14/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025
	Primary	Primary	Primary	Primary	Primary
	L2522786-01	L2522786-02	L2522786-03	L2522786-04	L2522786-05
	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	32 - 34 (ft)	50 - 52 (ft)
Volatile Organic Compounds (mg/kg)					
1,2,4-Trimethylbenzene	ND (0.0018)	0.00053 J	0.013	**110**	0.45
1,3,5-Trimethylbenzene	ND (0.0018)	0.00023 J	0.0034	**38**	0.14
Benzene	ND (0.00044)	0.00018 J	0.0002 J	**0.89**	0.055 0.027
Ethylbenzene	ND (0.00088)	0.00043 J	0.0016	**27**	0.13
Naphthalene	ND (0.0035)	0.00073 J	0.0056	**18**	0.14 0.088 J
n-Propylbenzene	ND (0.00088)	0.00016 J	0.0014	**22**	0.22 0.085
Toluene	ND (0.00088)	ND (0.00095)	0.0028	**47**	0.42
Xylene (Total)	ND (0.00088)	0.001 J	0.0089	**170**	0.71

HA-SB6

	HA-SB6	HA-SB6	HA-SB6	HA-SB6
	HA-SB6_0-0.5	HA-SB6_6-8	HA-SB6_15-17	HA-SB6_28-40
	04/23/2025	04/23/2025	04/23/2025	04/23/2025
	Primary	Primary	Primary	Primary
	L2525069-07	L2525069-08	L2525069-09	L2525069-10
	0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	28 - 40 (ft)
Volatile Organic Compounds (mg/kg)				
1,2,4-Trimethylbenzene	0.006	0.0008 J	ND (0.0018)	**9.8**
Ethylbenzene	0.0016	ND (0.001)	ND (0.00089)	**1.4**
Toluene	0.0028	ND (0.001)	ND (0.00089)	**1.8**
Xylene (Total)	0.0083	ND (0.001)	ND (0.00089)	**9.9**

HA-SB8

	HA-SB8	HA-SB8	HA-SB8	HA-SB8	HA-SB8
	HA-SB8_0-0.5	HA-SB8_3-5	HA-SB8_15-17	DUP01_20250415	HA-SB8_48-50
	04/15/2025	04/15/2025	04/15/2025	04/15/2025	04/15/2025
	Primary	Primary	Primary	Duplicate	Primary
	L2523120-01	L2523120-02	L2523120-03	L2523120-05	L2523120-04
	0 - 0.5 (ft)	3 - 5 (ft)	15 - 17 (ft)	15 - 17 (ft)	48 - 50 (ft)
Volatile Organic Compounds (mg/kg)					
1,2,4-Trimethylbenzene	0.00078 J	0.0089	**10**	**19**	0.028 J
Benzene	0.00056	0.00044 J	0.018 J 0.00085	ND (0.078)	***0.68***
Ethylbenzene	0.00036 J	0.0036	**1.5**	**2.3**	0.11
Methyl Tert Butyl Ether (MTBE)	ND (0.002)	ND (0.0018)	ND (0.098)	ND (0.31)	***2.5***
Xylene (Total)	0.0024 J	0.021	**6.8**	**13**	0.34

LEGEND

- LNAPL DELINEATION BORING
- SOIL BORING
- SOIL BORING/MONITORING WELL
- SOIL VAPOR POINT
- 4,000-GALLON UST
- SITE BOUNDARY
- PARCEL BOUNDARY

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.
2. DEFINITIONS:
LNAPL = LIGHT NON-AQUEOUS PHASE LIQUID
BTEX = BENZENE, TOLUENE, ETHYLBENZENE, XYLENES
PGWSCO = PROTECTION OF GROUNDWATER SOIL CLEANUP OBJECTIVE
UST = UNDERGROUND STORAGE TANK
BGS = BELOW GROUND SURFACE
SVE = SOIL VAPOR EXTRACTION
3. SOIL SAMPLE ANALYTICAL RESULTS ARE COMPARED TO THE NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION (NYSDEC) TITLE 6 OF THE OFFICIAL COMPILATION OF NEW YORK CODES, RULES, AND REGULATIONS (NYCRR) PART 375 PROTECTION OF GROUNDWATER SOIL CLEANUP OBJECTIVES (SCOS).
4. EXCEEDANCES OF THE PROTECTION OF GROUNDWATER SCOS ARE SHADED GRAY.
5. RESULTS ARE PRELIMINARY.
6. PARCEL DATA SOURCE: KINGS COUNTY
7. AERIAL IMAGERY SOURCE: NEARMAP, MARCH 8, 2024

N

0 30 60

SCALE IN FEET

HALEY ALDRICH

4001 4TH AVENUE
BROOKLYN, NEW YORK

PARTIAL RI SOIL ANALYTICAL DATA MAP (VOC)

OCTOBER 2025

FIGURE 2A

GIS FILE PATH: \\haleyaldrich.com\share\CF\Projects\210815\GIS\210815_4TH_AVE_BROOKLYN\210815_4TH_AVE_BROOKLYN.aprx - USER: gwilde - LAST SAVED: 7/30/2025 9:50 AM

HA-SB1	HA-SB1	HA-SB1	HA-SB1	HA-SB1
	HA-SB1_0-0.5	HA-SB1_6-8	HA-SB1_15-17	HA-SB1_38-40
	04/23/2025	04/23/2025	04/23/2025	04/23/2025
	Primary	Primary	Primary	Primary
	L2525069-11	L2525069-12	L2525069-13	L2525069-14
	0 - 0.5 (ft)	6 - 8 (ft)	15 - 17 (ft)	38 - 40 (ft)
Semi-Volatile Organic Compounds (mg/kg)				
Naphthalene	0.054 J	0.21	**18**	0.055 J
Pesticides (mg/kg)				
4,4'-DDE	0.00382	ND (0.00164)	ND (0.00161)	ND (0.0017)
Metals (mg/kg)				
Lead	124	55.2	23.8	7.7
Zinc	257	67.5	48.1	25.2

HA-SB2	HA-SB2	HA-SB2
	HA-SB2_0-0.5	HA-SB2_3-5
	04/24/2025	04/24/2025
	Primary	Primary
	L2525266-07	L2525266-08
	0 - 0.5 (ft)	3 - 5 (ft)
Semi-Volatile Organic Compounds (mg/kg)		
Benzo(a)anthracene	**1.1**	0.46
Benzo(b)fluoranthene	1.3	0.53
Indeno(1,2,3-cd)pyrene	0.57	0.21
Metals (mg/kg)		
Copper	51.6	38.2
Lead	**465**	38.9
Mercury	0.317	ND (0.068)
Zinc	285	124

HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB11	HA-SB11
	HA-SB11_0-0.5	HA-SB11_4-6	HA-SB11_15-17	DUP02_20250424	HA-SB11_40-42
	04/24/2025	04/24/2025	04/24/2025	04/24/2025	04/24/2025
	Primary	Primary	Primary	Duplicate	Primary
	L2525266-02	L2525266-03	L2525266-04	L2525266-05	L2525266-06
	0 - 0.5 (ft)	4 - 6 (ft)	15 - 17 (ft)	15 - 17 (ft)	40 - 42 (ft)
Semi-Volatile Organic Compounds (mg/kg)					
Naphthalene	ND (0.18)	ND (0.18)	8.8	8.5	***14***

HA-SB9	HA-SB9	HA-SB9	HA-SB9	HA-SB9	HA-SB9
	HA-SB9_0-0.5	HA-SB9_5-7	HA-SB9_15-17	HA-SB9_32-34	HA-SB9_50-52
	04/14/2025	04/14/2025	04/14/2025	04/14/2025	04/14/2025
	Primary	Primary	Primary	Primary	Primary
	L2522786-01	L2522786-02	L2522786-03	L2522786-04	L2522786-05
	0 - 0.5 (ft)	5 - 7 (ft)	15 - 17 (ft)	32 - 34 (ft)	50 - 52 (ft)
Polychlorinated Biphenyls (mg/kg)					
Aroclor-1260 (PCB-1260)	0.137	ND (0.0534)	ND (0.0498)	ND (0.0509)	ND (0.0524)
Metals (mg/kg)					
Lead	112	3.87 J	2.9 J	10.4	3.51 J
Zinc	113	18.9	11.9	21	13.8

HA-SB8	HA-SB8	HA-SB8	HA-SB8	HA-SB8	HA-SB8
	HA-SB8_0-0.5	HA-SB8_3-5	HA-SB8_15-17	DUP01_20250415	HA-SB8_48-50
	04/15/2025	04/15/2025	04/15/2025	04/15/2025	04/15/2025
	Primary	Primary	Primary	Duplicate	Primary
	L2523120-01	L2523120-02	L2523120-03	L2523120-05	L2523120-04
	0 - 0.5 (ft)	3 - 5 (ft)	15 - 17 (ft)	15 - 17 (ft)	48 - 50 (ft)
Metals (mg/kg)					
Zinc	237	60.4	115	41.9	19.6

HA-SB5	HA-SB5	HA-SB5	HA-SB5	HA-SB5
	HA-SB5_0-0.5	HA-SB5_3-5	HA-SB5_15-17	HA-SB5_48-50
	04/23/2025	04/23/2025	04/23/2025	04/23/2025
	Primary	Primary	Primary	Primary
	L2525069-03	L2525069-04	L2525069-05	L2525069-06
	0 - 0.5 (ft)	3 - 5 (ft)	15 - 17 (ft)	48 - 50 (ft)
Metals (mg/kg)				
Lead	105	5.2	8.86	16.2

HA-SB12/MW-8
HA-SB14/MW-8
HA-SB11
HA-SB1
MW-6
HA-SB9/MW2
HA-SB8
DB-5
HA-SB10
MW-1
HA-SB13/MW-7
DB-4
HA-SB6
DB-2
DB-1
HA-SB7
DB-3
HA-SB5/MW-5
HA-SB2
HA-SB3/MW-4
HA-SB4
SV-1
SV-2
SV-3
SV-4
SV-5
SV-6
SV-7
BLOCK 714, LOT 6
40TH STREET
Benzene

LEGEND

- LNAPL DELINEATION BORING
- SOIL BORING
- SOIL BORING/MONITORING WELL
- SOIL VAPOR POINT
- 4,000-GALLON UST
- SITE BOUNDARY
- PARCEL BOUNDARY

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.
2. DEFINITIONS:
LNAPL = LIGHT NON-AQUEOUS PHASE LIQUID
BTEX = BENZENE, TOLUENE, ETHYLBENZENE, XYLENES
PGWSCO = PROTECTION OF GROUNDWATER SOIL CLEANUP OBJECTIVE
UST = UNDERGROUND STORAGE TANK
BGS = BELOW GROUND SURFACE
SVE = SOIL VAPOR EXTRACTION
3. SOIL SAMPLE ANALYTICAL RESULTS ARE COMPARED TO THE NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION (NYSDEC) TITLE 6 OF THE OFFICIAL COMPILATION OF NEW YORK CODES, RULES, AND REGULATIONS (NYCRR) PART 375 PROTECTION OF GROUNDWATER SOIL CLEANUP OBJECTIVES (SCOS).
4. EXCEEDANCES OF THE PROTECTION OF GROUNDWATER SCOS ARE SHADED GRAY.
5. RESULTS ARE PRELIMINARY.
6. PARCEL DATA SOURCE: KINGS COUNTY
7. AERIAL IMAGERY SOURCE: NEARMAP, MARCH 8, 2024

N

0 30 60
SCALE IN FEET

HALEY ALDRICH

4001 4TH AVENUE
BROOKLYN, NEW YORK

PARTIAL RI SOIL ANALYTICAL DATA MAP (SVOC, METALS, PESTICIDES, PCBS)

OCTOBER 2025

FIGURE 2B

GIS FILE PATH: \\haleyaldrich.com\share\CF\Projects\021081\5\GIS\210815_4TH AVE_BROOKLYN\210815_4TH AVE_BROOKLYN.aprx - USER: gwilde - LAST SAVED: 7/30/2025 9:50 AM

MW-02	NY-AWQS or GV	MW-02 7/31/2025
Metals (µg/L)		
Manganese, Dissolved	300	2160
Sodium, Dissolved	20000	707000
Iron, Total	300	562
Manganese, Total	300	2170
Sodium, Total	20000	671000
Semi-Volatile Organic Compounds (µg/L)		
1,4-Dioxane	0.35	0.64
Volatile Organic Compounds (µg/L)		
1,2,4-Trimethylbenzene	5	6
Benzene	1	4
Cyclohexane	NA	3.3
Ethylbenzene	5	5
Methyl tert-butyl ether	10	27
Methylcyclohexane	NA	5.2
m-Xylene & p-Xylene	5	20
o-Xylene	5	8.4
Toluene	5	39
Xylenes, Total	NA	28
PFAS (ng/L)		
Perfluorooctanesulfonic acid (PFOS)	2.7	6.14
Perfluorooctanoic acid (PFOA)	2.6	102

MW-03	NY-AWQS or GV	MW-03 7/31/2025
Metals (µg/L)		
Magnesium, Dissolved	35000	56400
Manganese, Dissolved	300	3690
Sodium, Dissolved	20000	489000
Iron, Total	300	5920
Magnesium, Total	35000	59500
Manganese, Total	300	3860
Sodium, Total	20000	495000
Semi-Volatile Organic Compounds (µg/L)		
1,4-Dioxane	0.35	1.6
Volatile Organic Compounds (µg/L)		
1,2,4-Trimethylbenzene	5	60
1,3,5-Trimethylbenzene	5	21
Benzene	1	320
Cyclohexane	NA	23
Ethylbenzene	5	96
Methyl tert-butyl ether	10	16000
Methylcyclohexane	NA	25
m-Xylene & p-Xylene	5	170
N-Propylbenzene	5	17
o-Xylene	5	57
Toluene	5	380
Xylenes, Total	NA	230
PFAS (ng/L)		
Perfluorooctanesulfonic acid (PFOS)	2.7	8.7
Perfluorooctanoic acid (PFOA)	2.6	77

4TH AVENUE

40TH STREET

HA-SB12 / MW-3

HA-SB14/ MW-8

HA-SB9/ MW-2

HA-SB13/ MW-7

MW-1

MW-6

BLOCK 714, LOT 6

HA-SB3 / MW-4

HA-SB5 / MW-5

LEGEND

- SITE BOUNDARY
- PARCEL BOUNDARY
- APPROXIMATE LOCATION OF 4,000-GALLON UST
- SOIL BORING/MONITORING WELL

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.
2. PARCEL DATA SOURCE: KINGS COUNTY
3. AERIAL IMAGERY SOURCE: NEARMAP, 8 MARCH 2024

N

0 30 60

SCALE IN FEET

HALEY ALDRICH

4001 4TH AVENUE
BROOKLYN, NEW YORK

PARTIAL RI GROUNDWATER ANALYTICAL DATA MAP

OCTOBER 2025

FIGURE 3

GIS FILE PATH: \\haleyaldrich\share\CF Projects\0210815\GIS\210815_4TH_AVE_BROOKLYN\210815_4TH_AVE_BROOKLYN.aprx - USER: mmjones - LAST SAVED: 4/17/2024 1:31 PM

SV-02	07/01/2025 L2541324-02
Volatile Organic Compounds (ug/m3)	
2,2,4-Trimethylpentane	3810000
Cyclohexane	103000
Hexane	412000
N-Heptane	74600

SV-06	07/01/2025 L2541324-06
Volatile Organic Compounds (ug/m3)	
2,2,4-Trimethylpentane	4350000
Benzene	696000
Cyclohexane	1030000
Hexane	2220000
N-Heptane	729000
Toluene	243000

SV-01	07/01/2025 L2541324-03
Volatile Organic Compounds (ug/m3)	
1,2,4-Trimethylbenzene	4100
2,2,4-Trimethylpentane	6540000
Benzene	19400
Cyclohexane	178000
Ethylbenzene	9990
Hexane	592000
m,p-Xylenes	27100
N-Heptane	184000
o-Xylene	4950
Toluene	27000

SV-07	07/01/2025 L2541324-07
Volatile Organic Compounds (ug/m3)	
2,2,4-Trimethylpentane	2690000
Benzene	4340
Cyclohexane	465000
Hexane	1150000
N-Heptane	566000

SV-03	07/01/2025 L2541324-01
Volatile Organic Compounds (ug/m3)	
1,2,4-Trimethylbenzene	28.4
1,3,5-Trimethylbenzene	9.14
2,2,4-Trimethylpentane	1000
Benzene	85.9
Cyclohexane	170
Ethylbenzene	40.6
Hexane	617
m,p-Xylenes	161
N-Heptane	218
o-Xylene	60.8
Toluene	254

SV-05	07/01/2025 L2541324-05
Volatile Organic Compounds (ug/m3)	
2,2,4-Trimethylpentane	16200000
Benzene	6770
Cyclohexane	626000
Hexane	2010000
N-Heptane	389000
Toluene	5880

SV-04	07/01/2025 L2541324-04
Volatile Organic Compounds (ug/m3)	
1,2,4-Trimethylbenzene	85.5
1,3,5-Trimethylbenzene	25.2
2,2,4-Trimethylpentane	16600
Benzene	626
Cyclohexane	1710
Ethylbenzene	119
Hexane	7930
m,p-Xylenes	452
N-Heptane	1860
o-Xylene	164
Toluene	1210

HA-SB15
SV-2
SV-6
HA-SB12/MW-8
HA-SB2
HA-SB14/MW-8
HA-SB11
BLOCK 714, LOT 6
HA-SB1
MW-6
HA-SB3/MW-4
HA-SB9/MW2
HA-SB8
DB-5
SV-1
HA-SB10
SV-7
MW-1
DB-4
SV-3
HA-SB13/MW-7
HA-SB6
DB-2
DB-1
SV-5
HA-SB7
HA-SB4
DB-3
HA-SB5/MW-5
SV-4
4TH AVENUE
40TH STREET

LEGEND

- LNAPL DELINEATION BORING
- SOIL BORING
- SOIL BORING/MONITORING WELL
- SOIL VAPOR POINT
- 4,000-GALLON UST
- SITE BOUNDARY
- PARCEL BOUNDARY

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.

2. DEFINITIONS:
LNAPL = LIGHT NON-AQUEOUS PHASE LIQUID
BTEX = BENZENE, TOLUENE, ETHYLBENZENE, XYLENES
PGWSCO = PROTECTION OF GROUNDWATER SOIL CLEANUP OBJECTIVE
UST = UNDERGROUND STORAGE TANK
BGS = BELOW GROUND SURFACE
SVE = SOIL VAPOR EXTRACTION

3. PARCEL DATA SOURCE: KINGS COUNTY

4. AERIAL IMAGERY SOURCE: NEARMAP, MARCH 8, 2024

5. RESULTS ARE PRELIMINARY AND FOR DETECTED PETROLEUM-RELATED COMPOUNDS.

N

0 30 60
SCALE IN FEET

HALEY ALDRICH


4001 4TH AVENUE
BROOKLYN, NEW YORK

RI SOIL VAPOR ANALYTICAL DATA MAP

OCTOBER 2025

FIGURE 4

GIS FILE PATH: \\haleyaldrich.com\share\CF\Projects\0210815\GIS\210815_4TH AVE_BROOKLYN\210815_4TH AVE_BROOKLYN.aprx - USER: gwilde - LAST SAVED: 7/30/2025 9:48 AM



LEGEND

- SITE BOUNDARY
- PARCEL BOUNDARY
- APPROXIMATE UST EXCAVATION AREA (0 TO 12 FT BGS)
- APPROXIMATE SUPPORT SLOPE EXCAVATION AREA (0 TO 12 FT BGS)
- SUPPORT-OF-EXCAVATION TO WEST AND SOUTH ABUTTING 4TH AVENUE AND SOUTHERN ADJACENT PROPERTY BUILDING

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.
2. PARCEL DATA SOURCE: KINGS COUNTY
3. AERIAL IMAGERY SOURCE: NEARMAP, 8 MARCH 2024

N

0 30 60

SCALE IN FEET

HALEY ALDRICH


4001 4TH AVENUE
BROOKLYN, NEW YORK

IRM EXCAVATION PLAN

OCTOBER 2025

FIGURE 5

GIS FILE PATH: \\haleyaldrich\share\CF\Projects\0210815\GIS\210815_4TH_AVE_BROOKLYN\210815_4TH_AVE_BROOKLYN.aprx - USER: mmjones - LAST SAVED: 4/17/2024 1:31 PM



LEGEND

- SITE BOUNDARY
- PARCEL BOUNDARY
- APPROXIMATE LOCATION OF UNDERGROUND STORAGE TANK EXCAVATION
- APPROXIMATE LOCATION OF PROPOSED ENDPOINT AND SIDEWALL SAMPLES
- SUPPORT-OF-EXCAVATION

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.
2. PARCEL DATA SOURCE: KINGS COUNTY
3. AERIAL IMAGERY SOURCE: NEARMAP, 8 MARCH 2024

N

0 30 60

SCALE IN FEET

HALEY ALDRICH

4001 4TH AVENUE
BROOKLYN, NEW YORK

PROPOSED CONFIRMATION SAMPLE LOCATION PLAN

OCTOBER 2025

FIGURE 6

GIS FILE PATH: \\haleyaldrich\share\CF\Projects\0210815\GIS\210815_4TH_AVE_BROOKLYN\210815_4TH_AVE_BROOKLYN.aprx - USER: mmjones - LAST SAVED: 4/17/2024 1:31 PM



LEGEND

- TRUCK INGRESS
- TRUCK EGRESS
- CONSTRUCTION ENTRANCE
- SITE BOUNDARY
- PARCEL BOUNDARY

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.
2. PARCEL DATA SOURCE: KINGS COUNTY
3. AERIAL IMAGERY SOURCE: NEARMAP, JULY 3, 2025

N

0 20 40

SCALE IN FEET

HALEY ALDRICH

4001 4TH AVENUE
BROOKLYN, NEW YORK

PROPOSED TRUCK ROUTE

OCTOBER 2025

FIGURE 7

GIS FILE PATH: \\haleyaldrich\share\CF\Projects\021081S\GIS\210815_4TH_AVE_BROOKLYN\210815_4TH_AVE_BROOKLYN.aprx - USER: gwilde - LAST SAVED: 8/26/2025 10:23 AM

APPENDIX A
Previous Reports

CASTLETON
ENVIRONMENTAL

January 25, 2019

Donald Middleton
Middleton Environmental Inc.
54 George Street
Babylon, New York 11702

RE: Phase II Environmental Site Assessment
4001-4011 4th Avenue, Brooklyn, New York

Dear Mr. Middleton:

Please find the attached Phase II Environmental Site Assessment Report for the property located at 4001-4011 4th Avenue, Brooklyn New York.

Thank you for the opportunity. Please call with any questions or comments.

Very truly yours,
Castleton Environmental Geologic Services, DPC



Frank P. Castellano, PG
Principal

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

CASTLETON
ENVIRONMENTAL

54 George Street, Babylon Village, NY 11702
206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 OFFICE
631-482-9042 FAX
www.castletonenv.com

Phase II Environmental Site Assessment
4001-4011 4th Avenue
Brooklyn, New York



Prepared for: Donald Middleton
Middleton Environmental Inc.
54 George Street
Babylon, New York 11702

PHASE II ENVIRONMENTAL SITE ASSESSMENT
4001-4011 4TH AVENUE
BROOKLYN, NEW YORK
JANUARY 2019
CASTLETON PROJECT NUMBER: MEIN1901

Table of Contents

1.0 INTRODUCTION 1
2.0 SITE BACKGROUND 1
3.0 PHASE II ESA FIELD INVESTIGATION 1
3.1 Geophysical Survey 2
3.2 Soil Investigation 2
4.0 ANALYTICAL RESULTS AND DATA DISCUSSION 3
5.0 CONCLUSIONS AND RECOMMENDATIONS 4
6.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS 4

Figures

Figure 1 – Vicinity Map
Figure 2 – Site and Sampling Plan

Appendices

Appendix A – Soil Boring Logs
Appendix B – Laboratory Analytical Reports

1.0 INTRODUCTION

Castleton Environmental Geologic Services DPC (Castleton) has prepared the following Phase II Environmental Site Assessment (ESA) report to document the work performed at 4001-4011 4th Avenue, Brooklyn, New York (the site). The investigation was performed based upon review of the Phase I ESA by Merritt Environmental Consulting Corp. (MECC) dated January 7, 2019.

The objectives of this work were to determine if the sites historic and current usage as a gasoline station has impacted the subsurface. The objective was met through the performance of a geophysical survey and the collection and laboratory analysis of soil samples.

2.0 SITE BACKGROUND

The site is located at 4001-4011 4th Avenue, Brooklyn, New York (Figure 1). The site is located on a plot size approximately 10,017 square feet. The site is currently used as a gas station with a convenience store and parking. The building was constructed in 1965.

Castleton reviewed the Phase I ESA prepared by MECC dated January 7, 2019. The MECC Phase I ESA identified that site has been a gasoline since its first developed use. According to the historical Sanborn Maps, a gasoline tank is present at the corner of 4th Avenue and 10th Street during the years 1926-1951.

MECC recommended further evaluation to determine if any documentation is available or if additional investigation (Phase II) is warranted. Subsequent documentation regarding the gasoline tank shown on the 1926-1951 Sanborn Maps was not provided.

3.0 PHASE II ESA FIELD INVESTIGATION

The objective of this Phase II ESA was to assess subsurface quality in relation to historic and current on-site filling station operations at the site.

The following scope of work was completed to assess subsurface conditions:

Task	Objective
Geophysical Survey	Determine if any subsurface anomalies indicative of underground storage tanks (USTs) and to clear underground utilities
Soil Sampling	Characterize site soil quality for impacts related to filling station operations

On-site work was completed on January 15, 2019. Sample collection locations are depicted on Figure 2.

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

3.1 Geophysical Survey

A geophysical survey was performed to identify evidence of subsurface anomalies and to mark on-site utilities in proposed subsurface work areas. The survey was performed using a variety of remote sensing equipment/methods including a magnetometer to identify ferrous metallic objects, ground penetrating radar (GPR) to identify changes in soil density and a pipe locating device to trace piping runs. The geophysical survey was performed by Delta Geophysics, Inc. of Catasauqua, Pennsylvania.

As described in the PBS records included in the Phase I ESA, 4 4,000-gallon USTs are currently in use at the site and were identified during the geophysical survey to clear boring locations.

Nine suspect (USTs) were identified that are currently not in use. Four suspect UST anomalies are centralized under the canopy between the active dispensers. Five suspect UST anomalies are located at the western portion of the site.

A metal anomaly not indicative of a UST was identified at northern portion of the site. A suspect UST was not identified at the northern portion of the site where the gas tank was shown on the historic Sanborn Maps.

All on site utilities were cleared before intrusive activities.

3.2 Soil Investigation

Soil borings were advanced to assess soil conditions at the site. Boring locations were selected based on potential areas identified during the geophysical survey. Soil borings were advanced with direct push technology (Geoprobe®) by Coastal Environmental Solutions, Inc. of Medford, New York.

Six soil borings were advanced. Soil samples were collected continuously from each boring location, logged and field screened with a PID for the presence of VOCs. Elevated field sensory (PID), olfactory or visible evidence of impacts to soil were observed in each of the borings ranging from 22.9 ppm in SB01 to 5,285 ppm in SB04. Soil was observed to consist of silty fine and medium sand. Groundwater was not encountered during this investigation. Soil boring logs are provided as Appendix A.

The following table describes the boring location, area of concern associated with each boring, and sample collected for laboratory analysis.

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

Boring	Area of Concern	Highest Soil PID Readings (ppm)	Boring Depth (feet)	Soil Analytical Sample Interval(s)
SB01	Area of former UST (Sanborn Map) and metal anomaly	22.9	25	18-20 feet
SB02	Area of former UST (Sanborn Map) and metal anomaly	425.9	20	4-6 feet
SB03	Area of former UST (Sanborn Map) and metal anomaly	2,195	22	12-14 feet
SB04	West of the five suspect USTs	5,285	30	16-18 feet
SB05	West of the five suspect USTs	3,963	20	10-15 feet
SB06	South of the five suspect USTs and west of the currently in use USTs	4,955	24.5	18-20 feet

Soil retained for laboratory analysis was placed into laboratory supplied glassware and submitted under chain of custody to York Analytical Laboratories of Stratford, Connecticut, a New York State Department of Health (NYSDOH) ELAP certified laboratory. Soil samples were analyzed for:

- CP-51 VOCs via EPA Method 8260, and
- CP-51 SVOCs via EPA Method 8270

4.0 ANALYTICAL RESULTS AND DATA DISCUSSION

Soil analytical results were compared to NYSDEC CP-51 Soil Cleanup Levels (SCLs) for petroleum impacted soil and NYSDEC Part 375 Soil Cleanup Objectives (SCOs).

Soil analytical results reported concentrations SVOCs as non-detect or below SCLs and SCOs in the six soil sample analyzed.

VOCs above SCLs were reported in five of the six soil samples. VOCs above Commercial SCOs were reported in two of the six samples analyzed.

Analytical results and laboratory report are presented in Appendix B.

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

5.0 CONCLUSIONS AND RECOMMENDATIONS

Castleton has prepared the following Phase II ESA report to document the work performed at 4001-4011 4th Avenue, Brooklyn, New York. The investigation was performed based upon review of the Phase I ESA by MECC dated January 7, 2019.

The objectives of this work were to determine if the sites historic and current usage as a gasoline station has impacted the subsurface. The objective was met through the performance of a geophysical survey and the collection and laboratory analysis of soil samples.

The geophysical survey identified the presence of the 4 in use USTs, nine suspect USTs that are currently not in use, and one metal anomaly that is not indicative of a UST.


Six soil boring were advanced, and six soil samples collected for laboratory analysis. Analytical results reported concentrations of VOCs above applicable standards in five of the six soil samples analyzed.

Castleton recommends the following:

- Notification of these findings be made to NYSDEC
- The suspect USTs be assessed and, if are present, properly removed as per NYSDEC protocols
- Petroleum impacts to soil be delineated and remediated under the NYSDEC Spills Program

6.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS





Frank P. Castellano, PG
Principal

Jessica Ferngren, PG
Sr. Project Manager

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

CASTLETON ENVIRONMENTAL

FIGURES

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com




Figure 1 – Vicinity Map

4001-4011 4th Avenue

Brooklyn, New York

+




Figure 2 – Site Plan

4001-4011 4th Avenue

Brooklyn, New York

CASTLETON
ENVIRONMENTAL

APPENDIX A

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com



Locations are approximate

Boring # **SB01**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**25 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 9:25		DATE: 1/15/2019	
COMPLETION TIME: 9:50		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	4	Asphalt Brown silty fine SAND, trace fine gravel	PID = 0.0 ppm.	
5-10 ft	5	3	Brown silty fine SAND, trace fine gravel	PID = 8.2 ppm.	
10-15 ft	5	3.5	Brown silty fine SAND, trace fine gravel	PID = 0.8 ppm.	
15-20 ft	5	1.5	Brown silty fine SAND, trace fine gravel Perched water @ 20-21 feet	PID = 22.9 ppm.	
20-25 ft	5	3	Brown clayey SAND, trace fine gravel	PID = 0.0 ppm.	



Locations are approximate

Boring # **SB02**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**20 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 9:50		DATE: 1/15/2019	
COMPLETION TIME: 10:10		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	3	Asphalt Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 23.4 ppm.	
5-10 ft	5	2.5	Brown silty fine SAND, trace fine gravel, brick	PID = 423.4 ppm.	
10-15 ft	5	2	Brown silty fine SAND, trace fine gravel, brick	PID = 0.0 ppm.	
15-20 ft	5	3	Brown silty fine SAND, trace fine gravel, brick	PID = 0.0 ppm.	



Locations are approximate

Boring # **SB03**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**22 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 10:10		DATE: 1/15/2019	
COMPLETION TIME: 11:00		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	0.5	Asphalt Black silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 23.4 ppm.	
5-10 ft	5	3.5	Black silty fine SAND, trace fine gravel, brick - Petroleum odor Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 423.4 ppm.	
10-15 ft	5	4	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 0.0 ppm.	
15-20 ft	5	2.5	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 0.0 ppm.	
20-22 ft	2	0.5	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor Refusal @ 22'	PID = 0.0 ppm.	



Locations are approximate

Boring # **SB04**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**30 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 11:00		DATE: 1/15/2019	
COMPLETION TIME: 11:40		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	0.5	Asphalt Dark brown silty fine SAND, brick - Petroleum odor	PID = 126.7 ppm.	
5-10 ft	5	2	Brown silty fine SAND, brick - Petroleum odor	PID = 148.9 ppm.	
10-15 ft	5	2	Brown silty fine SAND, brick - Petroleum odor	PID = 3,414 ppm.	
15-20 ft	5	2.5	Brown silty fine SAND, brick - Petroleum odor	PID = 5,285 ppm.	
20-25 ft	5	3	Brown silty fine SAND, brick - Petroleum odor	PID = 4,675 ppm.	
25-30 ft	5	2.5	Brown silty fine SAND, brick - Petroleum odor	PID = 368.4 ppm.	



Locations are approximate

Boring # **SB05**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**20 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 11:40		DATE: 1/15/2019	
COMPLETION TIME: 12:00		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	1	Concrete Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 2,634 ppm.	
5-10 ft	5	2	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 2,391 ppm.	
10-15 ft	5	0.5	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 3,963 ppm.	
15-20 ft	5	0.5	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 1,516 ppm.	



Locations are approximate

Boring # **SB06**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**24.5 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 12:00		DATE: 1/15/2019	
COMPLETION TIME: 12:20		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	0.5	Concrete Tan silty fine SAND, trace fine gravel, brick	PID = 53.7 ppm.	
5-10 ft	5	0.5	Brown silty fine SAND, trace fine gravel	PID = 10.7 ppm.	
10-15 ft	5	1.5	Brown silty fine SAND, trace fine gravel	PID = 248.6 ppm.	
15-20 ft	5	2	Brown silty fine SAND, trace fine gravel	PID = 4,955 ppm.	
20-24.5 ft	4.5	0.5	Brown silty fine SAND, trace fine gravel	PID = 4,815 ppm.	

CASTLETON
ENVIRONMENTAL

APPENDIX B

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

Sample ID York ID Sampling Date Client Matrix		NYSDEC CP/SCO Table 2-Gasoline	NYSDEC CP/SCO Table 3-Fuel Oil	NYSDEC Part 375 Unrestricted Use Soil Cleanup Objectives	NYSDEC Part 375 Restricted Use Soil Cleanup Objectives - Restricted Residential	NYSDEC Part 375 Restricted Use Soil Cleanup Objectives- Commercial	SB01 19A0642-01 1/15/2019 9:50:00 AM Soil		SB02 19A0642-02 1/15/2019 10:10:00 AM Soil		SB03 19A0642-03 1/15/2019 11:00:00 AM Soil		SB04 19A0642-04 1/15/2019 11:40:00 AM Soil		SB05 19A0642-05 1/15/2019 12:00:00 PM Soil		SB06 19A0642-06 1/15/2019 12:20:00 PM Soil	
Compound	**CAS Number**						Result	Q	Result	Q	Result	Q	Result	Q	Result	Q	Result	Q
Volatile Organics, CP-51 (formerly STARS) List		mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg		mg/Kg		mg/Kg		mg/Kg		mg/Kg		mg/Kg	
Dilution Factor							1		100		200		10000		1000		5000	
1,2,4-Trimethylbenzene	95-63-6	3.6	3.6	3.6	52	190	0.00650		**4.400**	D	**22**	D	**1,200**	D	**57**	D	**360**	D
1,3,5-Trimethylbenzene	108-67-8	8.4	8.4	8.4	52	190	0.00290	J	0.170		**9.100**	D	**830**	D	**19**	D	**57**	D
Benzene	71-43-2	0.06	0.06	0.06	4.8	44	0.00680		0.00370	J	**1.200**	D	**20**	D	**2.400**	D	**3.600**	D
Ethyl Benzene	100-41-4	1	1	1	41	390	0.00310	J	0.100		**10**	D	**1,100**	D	**21**	D	**77**	D
Isopropylbenzene	98-82-8	2.3	2.3	~	~	~	0.00220	U	0.0780		**3**	D	**48**	D	**3.700**	D	**9.600**	D
Methyl tert-butyl ether (MTBE)	1634-04-4	0.93	~	0.93	100	500	0.0560		0.00350	J	0.0460		0.270	U	0.220	U	0.180	U
Naphthalene	91-20-3	12	12	12	100	500	0.00310	J	0.190		0.140		**88**	BD	6.300	BD	**23**	BD
n-Butylbenzene	104-51-8	12	12	12	100	500	0.00220	U	0.0930		0.200		**31**	D	2.700	D	6.800	D
n-Propylbenzene	103-65-1	3.9	3.9	3.9	100	500	0.00220	U	0.130		**4.800**	D	**170**	D	**11**	D	**34**	D
o-Xylene	95-47-6	~	~	~	~	~	0.00220	U	0.00250	U	3.700	D	650	D	32	D	120	D
p- & m- Xylenes	179601-23-1	~	~	~	~	~	0.00540	J	0.0130		22	D	1,600	D	82	D	350	DE
p-Isopropyltoluene	99-87-6	10	10	~	~	~	0.00220	U	0.170		2.900	D	**15**	D	1.400	D	2.300	D
sec-Butylbenzene	135-98-8	11	11	11	100	500	0.00220	U	0.110		2.100	D	**21**	D	1.600	D	3.900	D
tert-Butylbenzene	98-06-6	5.9	5.9	5.9	100	500	0.00220	U	0.0340		0.120		0.270	U	0.220	U	0.180	U
Toluene	108-88-3	0.7	0.7	0.7	100	500	0.00220	U	0.00360	J	**8.300**	D	**1,500**	D	**64**	D	**370**	D
Xylenes, Total	1330-20-7	0.26	0.26	0.26	100	500	0.00650	U	0.0130	J	**26**	D	**2,300**	D	**110**	D	**480**	DE
Semi-Volatiles, CP-51 (formerly STARS) List		mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg		mg/Kg		mg/Kg		mg/Kg		mg/Kg		mg/Kg	
Dilution Factor							2		2		2		2		2		2	
Acenaphthene	83-32-9	~	20	20	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Acenaphthylene	208-96-8	~	100	100	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Anthracene	120-12-7	~	100	100	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(a)anthracene	56-55-3	~	1	1	1	5.6	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(a)pyrene	50-32-8	~	1	1	1	1	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(b)fluoranthene	205-99-2	~	1	1	1	5.6	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(g,h,i)perylene	191-24-2	~	100	100	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(k)fluoranthene	207-08-9	~	0.8	0.8	3.9	56	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Chrysene	218-01-9	~	1	1	3.9	56	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Dibenzo(a,h)anthracene	53-70-3	~	0.33	0.33	0.33	0.56	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Fluoranthene	206-44-0	~	100	100	100	500	0.0450	U	0.0870	JD	0.0560	JD	0.0540	U	0.0450	U	0.0460	U
Fluorene	86-73-7	~	30	30	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Indeno(1,2,3-cd)pyrene	193-39-5	~	0.5	0.5	0.5	5.6	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Naphthalene	91-20-3	12	12	12	100	500	0.0450	U	0.180	D	1.600	D	1.500	D	2.900	DE	0.120	D
Phenanthrene	85-01-8	~	100	100	100	500	0.0450	U	0.100	D	0.0740	JD	0.0540	U	0.0450	U	0.0460	U
Pyrene	129-00-0	~	100	100	100	500	0.0450	U	0.0880	JD	0.0470	JD	0.0540	U	0.0450	U	0.0460	U
Total Solids							%		%		%		%		%		%	
Dilution Factor							1		1		1		1		1		1	
% Solids	solids	~	~	~	~	~	91		93.100		93.200		77.100		91.200		90.300	

NOTES:

Any Regulatory Exceedences are color coded by Regulation

Q is the Qualifier Column with definitions as follows:

D=result is from an analysis that required a dilution

J=analyte detected at or above the MDL (method detection limit) but below the RL (Reporting Limit) - data is estimated

U=analyte not detected at or above the level indicated

B=analyte found in the analysis batch blank

E=result is estimated and cannot be accurately reported due to levels encountered or interferences

P=this flag is used for pesticide and PCB (Aroclor) target compounds when there is a % difference for detected concentrations that exceed method dictated limits between the two GC columns used for analysis

NT=this indicates the analyte was not a target for this sample

~=this indicates that no regulatory limit has been established for this analyte

Technical Report

prepared for:

Castleton Environmental
54 George Street
Babylon NY, 11702
Attention: Jessica Ferngren

Report Date: 01/23/2019
Client Project ID: MEIN1901
York Project (SDG) No.: 19A0642

Report Date: 01/23/2019
Client Project ID: MEIN1901
York Project (SDG) No.: 19A0642

Castleton Environmental
54 George Street
Babylon NY, 11702
Attention: Jessica Ferngren

Purpose and Results

This report contains the analytical data for the sample(s) identified on the attached chain-of-custody received in our laboratory on January 16, 2019 with a temperature of 1.5 C. The project was identified as your project: **MEIN1901**.

The analyses were conducted utilizing appropriate EPA, Standard Methods, and ASTM methods as detailed in the data summary tables.

All samples were received in proper condition meeting the customary acceptance requirements for environmental samples except those indicated under the Sample and Analysis Qualifiers section of this report.

All analyses met the method and laboratory standard operating procedure requirements except as indicated by any data flags, the meaning of which are explained in the Sample and Data Qualifiers Relating to This Work Order section of this report and case narrative if applicable.

The results of the analyses, which are all reported on dry weight basis (soils) unless otherwise noted, are detailed in the following pages.

Please contact Client Services at 203.325.1371 with any questions regarding this report.

York Sample ID	Client Sample ID	Matrix	Date Collected	Date Received
19A0642-01	SB01	Soil	01/15/2019	01/16/2019
19A0642-02	SB02	Soil	01/15/2019	01/16/2019
19A0642-03	SB03	Soil	01/15/2019	01/16/2019
19A0642-04	SB04	Soil	01/15/2019	01/16/2019
19A0642-05	SB05	Soil	01/15/2019	01/16/2019
19A0642-06	SB06	Soil	01/15/2019	01/16/2019

General Notes for York Project (SDG) No.: 19A0642

1. The RLs and MDLs (Reporting Limit and Method Detection Limit respectively) reported are adjusted for any dilution necessary due to the levels of target and/or non-target analytes and matrix interference. The RL(REPORTING LIMIT) is based upon the lowest standard utilized for the calibration where applicable.
2. Samples are retained for a period of thirty days after submittal of report, unless other arrangements are made.
3. York's liability for the above data is limited to the dollar value paid to York for the referenced project.
4. This report shall not be reproduced without the written approval of York Analytical Laboratories, Inc.
5. All analyses conducted met method or Laboratory SOP requirements. See the Sample and Data Qualifiers Section for further information.
6. It is noted that no analyses reported herein were subcontracted to another laboratory, unless noted in the report.
7. This report reflects results that relate only to the samples submitted on the attached chain-of-custody form(s) received by York.
8. Analyses conducted at York Analytical Laboratories, Inc. Stratford, CT are indicated by NY Cert. No. 10854; those conducted at York Analytical Laboratories, Inc., Richmond Hill, NY are indicated by NY Cert. No. 12058.

Approved By: 

Date: 01/23/2019

Benjamin Gulizia
Laboratory Director

Sample Information

Client Sample ID: **SB01** **York Sample ID:** **19A0642-01**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 9:50 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**6.5**		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-67-8	**1,3,5-Trimethylbenzene**	**2.9**	J	ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
71-43-2	**Benzene**	**6.8**		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
100-41-4	**Ethyl Benzene**	**3.1**	J	ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-82-8	Isopropylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1634-04-4	**Methyl tert-butyl ether (MTBE)**	**56**		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
91-20-3	**Naphthalene**	**3.1**	J	ug/kg dry	2.2	8.6	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI			
104-51-8	n-Butylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
103-65-1	n-Propylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
95-47-6	o-Xylene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
179601-23-1	**p- & m- Xylenes**	**5.4**	J	ug/kg dry	4.3	8.6	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
99-87-6	p-Isopropyltoluene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
135-98-8	sec-Butylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-06-6	tert-Butylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-88-3	Toluene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1330-20-7	Xylenes, Total	ND		ug/kg dry	6.5	13	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,NJ			

	Surrogate Recoveries	Result	Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*102 %*	*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*102 %*	*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*109 %*	*76-130*

Sample Information

Client Sample ID: SB01 **York Sample ID:** 19A0642-01

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 9:50 am	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
208-96-8	Acenaphthylene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
120-12-7	Anthracene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
218-01-9	Chrysene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
206-44-0	Fluoranthene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
86-73-7	Fluorene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	NELAC-NY10854,NJDEP,PADEP		
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
91-20-3	Naphthalene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
85-01-8	Phenanthrene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
129-00-0	Pyrene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*54.7 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*71.8 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*66.4 %*	*24-116*

Total Solids

Log-in Notes:

Sample Notes:

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst

Sample Information

Client Sample ID: SB01 **York Sample ID:** 19A0642-01

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 9:50 am	01/16/2019

Total Solids **Log-in Notes:** **Sample Notes:**

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	* % Solids	91.0		%	0.100	1	SM 2540G Certifications: CTDOH	01/22/2019 11:58	01/22/2019 16:28	MAC

Sample Information

Client Sample ID: SB02 **York Sample ID:** 19A0642-02

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 10:10 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List **Log-in Notes:** **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	1,2,4-Trimethylbenzene	4400		ug/kg dry	250	500	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/21/2019 11:58	LLJ
108-67-8	1,3,5-Trimethylbenzene	170	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
71-43-2	Benzene	3.7	J	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
100-41-4	Ethyl Benzene	100		ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
98-82-8	Isopropylbenzene	78	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
1634-04-4	Methyl tert-butyl ether (MTBE)	3.5	J	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
91-20-3	Naphthalene	190	IS-HI	ug/kg dry	2.5	10	1	EPA 8260C Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI	01/18/2019 08:45	01/18/2019 19:56	LLJ
104-51-8	n-Butylbenzene	93	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
103-65-1	n-Propylbenzene	130	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
95-47-6	o-Xylene	ND		ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
179601-23-1	p- & m- Xylenes	13		ug/kg dry	5.0	10	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
99-87-6	p-Isopropyltoluene	170	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
135-98-8	sec-Butylbenzene	110	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
98-06-6	tert-Butylbenzene	34	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ

Sample Information

Client Sample ID: SB02 **York Sample ID:** 19A0642-02

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 10:10 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
108-88-3	**Toluene**	**3.6**	J	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications:	01/18/2019 08:45 CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 19:56	LLJ
1330-20-7	**Xylenes, Total**	**13**	J	ug/kg dry	7.5	15	1	EPA 8260C Certifications:	01/18/2019 08:45 CTDOH,NELAC-NY10854,NELAC-NY12058,NJ	01/18/2019 19:56	LLJ

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*122 %*		*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*90.5 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*246 %*	IS-HI, S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
208-96-8	Acenaphthylene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
120-12-7	Anthracene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
218-01-9	Chrysene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
206-44-0	**Fluoranthene**	**87**	J	ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
86-73-7	Fluorene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
91-20-3	**Naphthalene**	**180**		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW

Sample Information

Client Sample ID: SB02 **York Sample ID:** 19A0642-02

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 10:10 am	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
85-01-8	**Phenanthrene**	**100**		ug/kg dry	45	89	2	EPA 8270D	01/22/2019 07:32	01/22/2019 21:49	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
129-00-0	**Pyrene**	**88**	J	ug/kg dry	45	89	2	EPA 8270D	01/22/2019 07:32	01/22/2019 21:49	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*61.4 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*73.5 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*75.9 %*	*24-116*

Total Solids

Log-in Notes:

Sample Notes:

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**93.1**		%	0.100	1	SM 2540G	01/22/2019 11:58	01/22/2019 16:28	MAC
							Certifications: CTDOH			

Sample Information

Client Sample ID: SB03 **York Sample ID:** 19A0642-03

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:00 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**22000**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-67-8	**1,3,5-Trimethylbenzene**	**9100**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
71-43-2	**Benzene**	**1200**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
100-41-4	**Ethyl Benzene**	**10000**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-82-8	**Isopropylbenzene**	**3000**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1634-04-4	**Methyl tert-butyl ether (MTBE)**	**46**	IS-HI	ug/kg dry	2.6	5.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 20:23	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
91-20-3	**Naphthalene**	**140**		ug/kg dry	2.6	11	1	EPA 8260C	01/18/2019 08:45	01/18/2019 20:23	LLJ
								Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI			

Sample Information

Client Sample ID: **SB03** **York Sample ID:** **19A0642-03**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:00 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
104-51-8	**n-Butylbenzene**	**200**		ug/kg dry	2.6	5.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 20:23	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
103-65-1	**n-Propylbenzene**	**4800**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
95-47-6	**o-Xylene**	**3700**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
179601-23-1	**p- & m- Xylenes**	**22000**		ug/kg dry	1100	2100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
99-87-6	**p-Isopropyltoluene**	**2900**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
135-98-8	**sec-Butylbenzene**	**2100**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-06-6	**tert-Butylbenzene**	**120**		ug/kg dry	2.6	5.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 20:23	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-88-3	**Toluene**	**8300**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1330-20-7	**Xylenes, Total**	**26000**		ug/kg dry	1600	3200	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,NJ			

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*388 %*	IS-HI, S-03	*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*104 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*1100 %*	S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
208-96-8	Acenaphthylene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
120-12-7	Anthracene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			

Sample Information

Client Sample ID: SB03 **York Sample ID:** 19A0642-03

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:00 am	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
218-01-9	Chrysene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
206-44-0	**Fluoranthene**	**56**	J	ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
86-73-7	Fluorene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	NELAC-NY10854,NJDEP,PADEP		
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
91-20-3	**Naphthalene**	**1600**		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
85-01-8	**Phenanthrene**	**74**	J	ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
129-00-0	**Pyrene**	**47**	J	ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*78.2 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*73.7 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*83.8 %*	*24-116*

Total Solids

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**93.2**		%	0.100	1	SM 2540G	01/22/2019 11:58	01/22/2019 16:28	MAC
							Certifications:	CTDOH		

Sample Information

Client Sample ID: SB04 **York Sample ID:** 19A0642-04

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:40 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst

Sample Information

Client Sample ID: **SB04** **York Sample ID:** **19A0642-04**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:40 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**1200000**		ug/kg dry	27000	54000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-67-8	**1,3,5-Trimethylbenzene**	**830000**		ug/kg dry	14000	27000	5000	EPA 8260C	01/21/2019 09:52	01/21/2019 17:22	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
71-43-2	**Benzene**	**20000**	IS-HI	ug/kg dry	270	540	100	EPA 8260C	01/21/2019 09:52	01/21/2019 12:52	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
100-41-4	**Ethyl Benzene**	**1100000**		ug/kg dry	14000	27000	5000	EPA 8260C	01/21/2019 09:52	01/21/2019 17:22	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-82-8	**Isopropylbenzene**	**48000**		ug/kg dry	2700	5400	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1634-04-4	Methyl tert-butyl ether (MTBE)	ND	IS-HI	ug/kg dry	270	540	100	EPA 8260C	01/21/2019 09:52	01/21/2019 12:52	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
91-20-3	**Naphthalene**	**88000**	B	ug/kg dry	2700	11000	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI			
104-51-8	**n-Butylbenzene**	**31000**		ug/kg dry	2700	5400	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
103-65-1	**n-Propylbenzene**	**170000**		ug/kg dry	2700	5400	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
95-47-6	**o-Xylene**	**650000**		ug/kg dry	27000	54000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
179601-23-1	**p- & m- Xylenes**	**1600000**		ug/kg dry	54000	110000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
99-87-6	**p-Isopropyltoluene**	**15000**		ug/kg dry	270	540	100	EPA 8260C	01/21/2019 09:52	01/21/2019 12:52	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
135-98-8	**sec-Butylbenzene**	**21000**		ug/kg dry	2700	5400	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-06-6	tert-Butylbenzene	ND		ug/kg dry	270	540	100	EPA 8260C	01/21/2019 09:52	01/21/2019 12:52	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-88-3	**Toluene**	**1500000**		ug/kg dry	27000	54000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1330-20-7	**Xylenes, Total**	**2300000**		ug/kg dry	81000	160000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,NJ			

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*96.5 %*	IS-HI	*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*110 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*174 %*	S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst

Sample Information

Client Sample ID: **SB04** **York Sample ID:** **19A0642-04**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:40 am	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
208-96-8	Acenaphthylene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
120-12-7	Anthracene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
218-01-9	Chrysene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
206-44-0	Fluoranthene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
86-73-7	Fluorene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	NELAC-NY10854,NJDEP,PADEP		
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
91-20-3	**Naphthalene**	**1500**		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
85-01-8	Phenanthrene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
129-00-0	Pyrene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*53.5 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*77.7 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*82.0 %*	*24-116*

Total Solids

Log-in Notes:

Sample Notes:

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst

Sample Information

Client Sample ID: SB04 **York Sample ID:** 19A0642-04

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:40 am	01/16/2019

Total Solids **Log-in Notes:** **Sample Notes:**

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**77.1**		%	0.100	1	SM 2540G Certifications: CTDOH	01/22/2019 11:58	01/22/2019 16:28	MAC

Sample Information

Client Sample ID: SB05 **York Sample ID:** 19A0642-05

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:00 pm	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List **Log-in Notes:** **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**57000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
108-67-8	**1,3,5-Trimethylbenzene**	**19000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
71-43-2	**Benzene**	**2400**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
100-41-4	**Ethyl Benzene**	**21000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
98-82-8	**Isopropylbenzene**	**3700**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
1634-04-4	Methyl tert-butyl ether (MTBE)	ND		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
91-20-3	**Naphthalene**	**6300**	B	ug/kg dry	220	870	100	EPA 8260C Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI	01/21/2019 09:52	01/21/2019 13:46	LLJ
104-51-8	**n-Butylbenzene**	**2700**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
103-65-1	**n-Propylbenzene**	**11000**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
95-47-6	**o-Xylene**	**32000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
179601-23-1	**p- & m- Xylenes**	**82000**		ug/kg dry	4400	8700	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
99-87-6	**p-Isopropyltoluene**	**1400**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
135-98-8	**sec-Butylbenzene**	**1600**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
98-06-6	tert-Butylbenzene	ND		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ

Sample Information

Client Sample ID: **SB05** **York Sample ID:** **19A0642-05**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:00 pm	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
108-88-3	**Toluene**	**64000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications:	01/21/2019 09:52	01/21/2019 16:02 CTDOH,NELAC-NY10854,NELAC-NY12058,PA	LLJ
1330-20-7	**Xylenes, Total**	**110000**		ug/kg dry	6500	13000	1000	EPA 8260C Certifications:	01/21/2019 09:52	01/21/2019 16:02 CTDOH,NELAC-NY10854,NELAC-NY12058,NJ	LLJ

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*88.1 %*		*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*100 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*139 %*	S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
208-96-8	Acenaphthylene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
120-12-7	Anthracene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
218-01-9	Chrysene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
206-44-0	Fluoranthene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
86-73-7	Fluorene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 NELAC-NY10854,NJDEP,PADEP	OW
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
91-20-3	**Naphthalene**	**2900**		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW

Sample Information

Client Sample ID: **SB05** **York Sample ID:** **19A0642-05**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:00 pm	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
85-01-8	Phenanthrene	ND		ug/kg dry	45	90	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:11	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
129-00-0	Pyrene	ND		ug/kg dry	45	90	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:11	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*69.5 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*80.1 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*85.1 %*	*24-116*

Total Solids

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**91.2**		%	0.100	1	SM 2540G	01/22/2019 11:58	01/22/2019 16:28	MAC
							Certifications: CTDOH			

Sample Information

Client Sample ID: **SB06** **York Sample ID:** **19A0642-06**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:20 pm	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**360000**		ug/kg dry	8900	18000	5000	EPA 8260C	01/21/2019 09:52	01/21/2019 17:50	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-67-8	**1,3,5-Trimethylbenzene**	**57000**		ug/kg dry	1800	3500	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
71-43-2	**Benzene**	**3600**	IS-HI	ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
100-41-4	**Ethyl Benzene**	**77000**		ug/kg dry	1800	3500	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-82-8	**Isopropylbenzene**	**9600**		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1634-04-4	Methyl tert-butyl ether (MTBE)	ND	IS-HI	ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
91-20-3	**Naphthalene**	**23000**	B	ug/kg dry	1800	7100	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI			

Sample Information

Client Sample ID: **SB06** **York Sample ID:** **19A0642-06**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:20 pm	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
104-51-8	**n-Butylbenzene**	**6800**		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
103-65-1	**n-Propylbenzene**	**34000**		ug/kg dry	1800	3500	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
95-47-6	**o-Xylene**	**120000**		ug/kg dry	1800	3500	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
179601-23-1	**p- & m- Xylenes**	**350000**	VOA-E	ug/kg dry	3500	7100	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
99-87-6	**p-Isopropyltoluene**	**2300**		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
135-98-8	**sec-Butylbenzene**	**3900**		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-06-6	tert-Butylbenzene	ND		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-88-3	**Toluene**	**370000**		ug/kg dry	8900	18000	5000	EPA 8260C	01/21/2019 09:52	01/21/2019 17:50	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1330-20-7	**Xylenes, Total**	**480000**	VOA-E	ug/kg dry	5300	11000	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,NJ			

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*108 %*	IS-HI	*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*103 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*139 %*	S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
208-96-8	Acenaphthylene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
120-12-7	Anthracene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			

Sample Information

Client Sample ID: **SB06** **York Sample ID:** **19A0642-06**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:20 pm	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
218-01-9	Chrysene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
206-44-0	Fluoranthene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
86-73-7	Fluorene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	NELAC-NY10854,NJDEP,PADEP		
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
91-20-3	**Naphthalene**	**120**		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
85-01-8	Phenanthrene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
129-00-0	Pyrene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*55.6 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*79.8 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*77.2 %*	*24-116*

Total Solids

Log-in Notes:

Sample Notes:

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**90.3**		%	0.100	1	SM 2540G	01/22/2019 11:58	01/22/2019 16:28	MAC
							Certifications:	CTDOH		

Volatile Analysis Sample Containers

Lab ID	Client Sample ID	Volatile Sample Container
19A0642-01	SB01	40mL Vial with Stir Bar-Cool 4° C
19A0642-02	SB02	40mL Vial with Stir Bar-Cool 4° C
19A0642-03	SB03	40mL Vial with Stir Bar-Cool 4° C
19A0642-04	SB04	40mL Vial with Stir Bar-Cool 4° C
19A0642-05	SB05	40mL Vial with Stir Bar-Cool 4° C
19A0642-06	SB06	40mL Vial with Stir Bar-Cool 4° C

Sample and Data Qualifiers Relating to This Work Order

VOA-E	The concentration reported for this analyte is an estimated value above the linear range of the instrument for EPA SW846-5035/8260 (>200ppb). Re-analysis using 5035/8260 medium level prep. resulted in a detection below the reporting limit (<500ppb).
S-03	The surrogate recovery for this sample is outside of established control limits due to a sample matrix effect. This effect was confirmed by reanalysis.
J	Detected below the Reporting Limit but greater than or equal to the Method Detection Limit (MDL/LOD) or in the case of a TIC, the result is an estimated concentration.
IS-HI	The internal std associated with this target compound did not meet acceptance criteria (area >200% CCV) at the stated dilution due to matrix effects. Sample was rerun to confirm matrix effects.
CCV-E	The value reported is ESTIMATED. The value is estimated due to its behavior during continuing calibration verification (>20% Difference for average Rf or >20% Drift for quadratic fit).
B	Analyte is found in the associated analysis batch blank. For volatiles, methylene chloride and acetone are common lab contaminants.

Definitions and Other Explanations

*	Analyte is not certified or the state of the samples origination does not offer certification for the Analyte.
ND	NOT DETECTED - the analyte is not detected at the Reported to level (LOQ/RL or LOD/MDL)
RL	REPORTING LIMIT - the minimum reportable value based upon the lowest point in the analyte calibration curve.
LOQ	LIMIT OF QUANTITATION - the minimum concentration of a target analyte that can be reported within a specified degree of confidence. This is the lowest point in an analyte calibration curve that has been subjected to all steps of the processing/analysis and verified to meet defined criteria. This is based upon NELAC 2009 Standards and applies to all analyses.
LOD	LIMIT OF DETECTION - a verified estimate of the minimum concentration of a substance in a given matrix that an analytical process can reliably detect. This is based upon NELAC 2009 Standards and applies to all analyses conducted under the auspices of EPA SW-846.
MDL	METHOD DETECTION LIMIT - a statistically derived estimate of the minimum amount of a substance an analytical system can reliably detect with a 99% confidence that the concentration of the substance is greater than zero. This is based upon 40 CFR Part 136 Appendix B and applies only to EPA 600 and 200 series methods.
Reported to	This indicates that the data for a particular analysis is reported to either the LOD/MDL, or the LOQ/RL. In cases where the "Reported to" is located above the LOD/MDL, any value between this and the LOQ represents an estimated value which is "J" flagged accordingly. This applies to volatile and semi-volatile target compounds only.
NR	Not reported
RPD	Relative Percent Difference
Wet	The data has been reported on an as-received (wet weight) basis
Low Bias	Low Bias flag indicates that the recovery of the flagged analyte is below the laboratory or regulatory lower control limit. The data user should take note that this analyte may be biased low but should evaluate multiple lines of evidence including the LCS and site-specific MS/MSD data to draw bias conclusions. In cases where no site-specific MS/MSD was requested, only the LCS data can be used to evaluate such bias.
High Bias	High Bias flag indicates that the recovery of the flagged analyte is above the laboratory or regulatory upper control limit. The data user should take note that this analyte may be biased high but should evaluate multiple lines of evidence including the LCS and site-specific MS/MSD data to draw bias conclusions. In cases where no site-specific MS/MSD was requested, only the LCS data can be used to evaluate such bias.
Non-Dir.	Non-dir. flag (Non-Directional Bias) indicates that the Relative Percent Difference (RPD) (a measure of precision) among the MS and MSD data is outside the laboratory or regulatory control limit. This alerts the data user where the MS and MSD are from site-specific samples that the RPD is high due to either non-homogeneous distribution of target analyte between the MS/MSD or indicates poor reproducibility for other reasons.

If EPA SW-846 method 8270 is included herein it is noted that the target compound N-nitrosodiphenylamine (NDPA) decomposes in the gas chromatographic inlet and cannot be separated from diphenylamine (DPA). These results could actually represent 100% DPA, 100% NDPA or some combination of the two. For this reason, York reports the combined result for n-nitrosodiphenylamine and diphenylamine for either of these compounds as a combined concentration as Diphenylamine.

If Total PCBs are detected and the target aroclors reported are "Not detected", the Total PCB value is reported due to the presence of either or both Aroclors 1262 and 1268 which are non-target aroclors for some regulatory lists.

2-chloroethylvinyl ether readily breaks down under acidic conditions. Samples that are acid preserved, including standards will exhibit breakdown. The data user should take note.

Certification for pH is no longer offered by NYDOH ELAP.

Semi-Volatile and Volatile analyses are reported down to the LOD/MDL, with values between the LOD/MDL and the LOQ being "J" flagged as estimated results.

For analyses by EPA SW-846-8270D, the Limit of Quantitation (LOQ) reported for benzidine is based upon the lowest standard used for calibration and is not a verified LOQ due to this compound's propensity for oxidative losses during extraction/concentration procedures and non-reproducible chromatographic performance.

York Analytical Laboratories, Inc.
120 Research Drive, Stratford, CT 06615 | 132-02 89th Ave, Queens, NY 11418
clientservices@yorklab.com
www.yorklab.com

Field Chain-of-Custody Record

NOTE: YORK's Standard Terms & Conditions are listed on the back side of this document.
This document serves as your written authorization for YORK to proceed with the analyses requested below.
Your signature binds you to YORK's Standard Terms & Conditions.

YORK Project No.: 19A0643

Page 1 of 1

YOUR Information	Report To:	Invoice To:	YOUR Project Number	Turn-Around Time
Company: Castleton Environmental	Company:	Company:	MEIN1901	RUSH - Next Day
Address: 54 George St Babylon, NY	Address: SAME	Address: SAME	YOUR Project Name: MEIN1901	RUSH - Two Day
Phone: 631 [illegible] 1818	Phone:	Phone:		RUSH - Three Day
Contact: Jessica Terngren	Contact:	Contact:		RUSH - Four Day
E-mail: jessica@castletonenv.com	E-mail:	E-mail:	YOUR PO#:	Standard (5-7 Day) X

Please print clearly and legibly. All information must be complete. Samples will not be logged in and the turn-around-time clock will not begin until any questions by YORK are resolved.

Samples Collected by: (print your name above and sign below)
Charles Lambert

Matrix Codes
S - soil / solid
GW - groundwater
DW - drinking water
WW - wastewater
O - Oil | Other

Samples From
New York X
New Jersey
Connecticut
Pennsylvania
Other

Report / EDD Type (circle selections)
~~Summary Report~~ | CT RCP | ~~Standard Excel EDD~~
QA Report | CT RCP DQA/DUE | EQuIS (Standard)
NY ASP A Package | NJDEP Reduced Deliverables | NYSDEC EQuIS
NY ASP B Package | NJDKQP | NJDEP SRP HazSite
Other:

YORK Reg. Comp.
Compared to the following Regulation(s): (please fill in)

Sample Identification	Sample Matrix	Date/Time Sampled	Analysis Requested	Container Description
SB01	S	1/15/19 9:50	CP-51 VOCs via 8260, CP51 SVOCs via 8270	terracore 1&1, 8oz jar
SB02		10:10		
SB03		11:00		
SB04		11:40		
SB05		12:00		
SB06		12:20		

Comments:

Preservation: (check all that apply)
HCl ___ MeOH ___ HNO_3 ___ H_2SO_4 ___ NaOH ___ ZnAc ___
Ascorbic Acid ___ Other: ___

Special Instruction
Field Filtered ___
Lab to Filter ___

Samples Relinquished by / Company	Date/Time	Samples Received by / Company
[signature]	1/16/19 8:40am	[signature]
Samples Received by / Company	Date/Time	Samples Relinquished by / Company
Samples Relinquished by / Company	Date/Time	Samples Received by / Company

Date/Time	Samples Relinquished by / Company	Date/Time
1/16/19 8:40AM		
Date/Time	Samples Received by / Company	Date/Time
Date/Time	Samples Received in LAB by / Date/Time	Temp. Received at Lab
	TC Mahl 1/16/19 1647	1.5 Degrees C

BP SERVICE STATION
4001-4010 4TH AVENUE
BROOKLYN, NEW YORK
SPILL # 18-11146

Supplemental
Remedial Investigation
Report
(RIR)

NEW YORK STATE DEPARTMENT OF
ENVIRONMENTAL CONSERVATION
REGION II
LONG ISLAND CITY
NEW YORK

PREPARED BY:

BERNINGER ENVIRONMENTAL
17 OLD DOCK ROAD
YAPHANK, NEW YORK 11980

June 2020

Table of Contents

1.0 INTRODUCTION

2.0 SITE BACKGROUND

3.0 SITE HISTORY

4.0 SCOPE OF WORK

5.0 SUMMARY OF FINDINGS

6.0 REMEDIAL ALTERNATIVES

7.0 PROJECT SCHEDULE

8.0 CONCLUSION

FIGURES

Figure-1 Site Location

Figure-2 Site Map with boring/sampling locations

Figures-3 a-h Boring Logs

ATTACHMENTS

Attachment-A Current Site Layout/Schematic

Attachment-B Previous Phase II ESA

Attachment-C Lab Data Package

TABLE

Table-1 Tabulated Soil Data

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
17 Old Dock Road
Yaphank • New York • 11980
Phone: 631 • 589 • 6521
web: www.wrses.com

June 17th, 2020

Veronica Zhune
New York State Environmental Conservation
Division of Environmental Remediation, Region 2
47-40 21st Street
Long Island City, New York 11101

Re: BP Service Station
4001-4010 4th Avenue
Brooklyn, New York 11232

Remedial Investigation Work Plan
NYSDEC Spill #18-11146
(RIWP)

Dear Ms. Zhune,

1.0 INTRODUCTION

The following document is a Remedial Investigation Report (RIR) developed for the subject site based upon the approved Remedial Investigation Work Plan (RIWP), which supplemented previous Phase I and Phase II Environmental Site Assessments (ESAs) performed at the site. The previously conducted Phase II ESA identified environmental conditions above standards and warranted further supplemental investigation to further the extent of contamination. This supplemental RIR will discuss the findings from the supplemental investigation and propose remedial alternatives to address the contamination discovered within soils at the site. Included within this Report is a discussion on the following: site background, site history, summary of supplemental findings, remedial alternatives, and a conclusion on the results.

2.0 SITE BACKGROUND

The site is located at 4001-4011 4th Avenue, Brooklyn, New York- Figure 1. The site is located on a plot size approximately 10,017 square feet. The site is currently used as a gas station with a convenience store and parking. The building was constructed in 1965. Castleton reviewed the Phase I ESA prepared by Merritt Environmental Consulting Corporation (MECC) dated January 7, 2019. The MECC Phase I ESA identified that the site has been a gasoline station since its first developed use. According to the historical Sanborn Maps, a gasoline tank was present at the corner of 4th Avenue and 10th Street during the years 1926-1951. MECC recommended further evaluation to

determine if any documentation is available or if additional investigation (Phase II) is warranted. Subsequent documentation regarding the gasoline tank shown on the 1926-1951 Sanborn Maps was not provided. A Phase II was subsequently performed based on the recommendations outlined in the Phase I ESA. Please refer to Attachment-A for a survey of the current layout of the station.

3.0 SITE HISTORY

A Phase II ESA was performed by Castleton Environmental during January of 2019, which included a series of borings conducted at key locations throughout the property and a ground penetrating radar (GPR) survey to identify any potential former UST's. Six (6) soil borings were advanced on the Subject Property in the vicinity of the UST's. Soil samples were collected continuously from each boring location, logged and field screened with a PID for the presence of VOCs. Elevated field sensory (PID), olfactory or visible evidence of impacts to soil were observed in each of the borings ranging from 22.9 ppm in SB01 to 5,285 ppm in SB04. Soil analytical results were compared to NYSDEC CP-51 Soil Cleanup Levels (SCLs) for petroleum impacted soil and NYSDEC Part 375 Soil Cleanup Objectives (SCOs). Soil analytical results reported concentrations of SVOCs as non-detect or below SCLs and SCOs in all of the six (6) soil samples analyzed. VOCs above SCLs were reported in five (5) of the six (6) soil samples. VOCs above commercial-use SCOs were reported in two (2) of the six (6) samples analyzed. Based upon these findings a spill was reported and spill number # 18-11146 was assigned to the site. Please refer to Attachment-B for the previously conducted Phase II by another contractor.

4.0 SCOPE OF WORK

The previously conducted Phase II ESA concluded that the need for further investigation was necessary in order to further define the nature and extent of contamination discovered in soil. The focus was to vertically delineate the contamination discovered at previous sample locations and attempt to locate groundwater. The results of the GPR survey were also recommended to be confirmed through the performance of test pits in the former UST areas. The following summary of findings section details the results from the supplemental investigation compared to the applicable standards.

5.0 SUMMARY OF FINDINGS

The following summary of findings discusses the results from the supplemental RIR conducted on April 29, 2020. The supplemental borings conducted included: three (3) test pit borings(B-1-3) in areas of the previously identified former USTs were performed in order to confirm the results of the GPR survey. Borings B-4 and B-5 were conducted at former locations were soil contamination was discovered at depth, but never delineated. B-6 and B-7 were test pits in an additional area where the

previous GPR survey found suspected former USTs. Finally, B-8 was conducted down gradient of the suspected former USTs and B-4 and B-5. All borings were advanced until refusal was encountered preventing further vertical advancement of sample tooling.

5.1 Former UST Identification

A total of (9) suspected former UST's were identified in a GPR survey conducted during the Phase II ESA. In order to confirm this data and the existence of former USTs from past operations, a series of test pits were conducted in order to confirm the results of the GPR. Three (3) borings (B-1-3) and (B-6-7) were conducted along the string of suspected USTs discovered during the GPR as depicted on Figure-2. A rotary mason bit affixed to the boring rig was used to advance through the upper layer of concrete approximately twelve inches (12") in depth. A void of about one (1') was observed from one (1') to two and a half (2.5') feet were refusal was encountered at all three (3) test pit locations. The consistent refusal at precisely the same depth in all three (3) test pits is an indication that the previous GPR survey was accurate and most likely attributed to previous abandonment of the UST's in place. Based on the field observations at all three (3) borings, B-1-3, the tanks when abandoned were filled with concrete and left in place.

5.2 Supplemental Soil Sampling Locations and Results

A series of borings were conducted at previous sampling locations in an effort to vertically delineate contamination documented in soil. Borings B-4(former SB06) and B-5(between SB04 and former SB05) were collected at the previous Phase II locations. Boring B-8 was collected down gradient of B-4 and B-5 near the southwest corner of the property in an attempt to laterally delineate contamination discovered in the vicinity of the former USTs. Borings were collected utilizing the duel tube sampling system and continuous grab samples were extracted in five foot (5') intervals and screened in 2.5' intervals with a PID meter for the presence of VOCs. B-4 was the first delineation boring performed from 0-30' until refusal was encountered at 30' bgs. PID readings from 15-25' bgs were averaging approximately 4,500 ppm on the PID meter and subsided significantly from 25'-30' in the 500-190 ppm range with the bottom sample (B-4@ 27.5'-30'). A sample from 27.5'-30' was submitted to the lab for testing for VOCs via EPA 8260D. The results still indicated multiple BTEX petroleum constituents above unrestricted Part-375 SCOs. As mentioned above advancement beyond thirty feet (30') bgs was not feasible and most likely attributed to bedrock as rock fragments were discovered at the bottom of the last soil liner. B-5 was collected between the previous borings (SB04 and SB05) were vertical delineation was not achieved. Continuous samples were collected from grade surface to approximately 32.5' bgs. Refusal was again encountered and rock fragments were observed in the bottom sample tube at 32.5'. Again, this refusal was likely attributed to contact with bedrock. A sample at the bottom of the boring from 30-32.5' was submitted for lab analysis via VOC analysis. The lab results

indicated only minor VOC detections all significantly below the Part-375 unrestricted SCOs. B-8 was collected down gradient from the hot spot areas B-4 and B-5 and was sampled from the surface to a depth of thirty four (34') feet below grade surface. Marginal PID readings (1,500-2,500 ppm) were documented from 10'-20' bgs and subsided steadily to only 25 ppm at 34' bgs. Bedrock refusal was again encountered at 34' bgs and rock fragments were observed at the bottom of the soil sampling liner at 34' bgs. Please refer to Figure-3a-h for boring logs. Please see Table-1 for tabulated lab results compared to SCOs. The lab data package is included as Attachment-C.

6.0 REMEDIAL ALTERNATIVES

The results of the supplemental soil samples have indicated the need for remedial actions in soils with the main focus on the interval from 10'- 25' bgs. The goal is to provide in-situ remediation at areas where impacted soils have exceeded the Part-375 unrestricted-use SCOs. Please read below for remedial alternatives to treating the impacted soil discovered at the site.

5.1 Soil Vapor Extraction (SVE)

Soil Vapor Extraction (SVE) is a technology used to remove volatile organic vapors from the un-saturated zone often referred to as the vadose zone. Off-gassing of petroleum contamination emanating from the soil is extracted through a series of vertical screened pipes and exhausted to the atmosphere. This technology allows for mass removal of petroleum related contamination including sorbed contamination in the soil matrix. Soil Vapor Extraction is a reasonable in-situ alternative to remedy soil contamination at this site, especially where contamination extends beyond the capabilities of excavation. This technology would also prevent having to excavate former USTs and contaminated soil in areas where multiple underground utilities exist along with utilities associated with the operation of the active gas station. Based upon the location of the contaminated soil and the on-going operations of the current business, the SVE technology is deemed the most reasonable alternative to remediating soils to applicable levels.

5.2 Enhanced Biological Degradation

Enhance bio injections are another alternative to treating soil contamination in the vadose zone. A series of injection wells are used to deliver an oxidant solution or a microbial mixture to the contaminated vadose zone in order to promote biological degradation. This technology although practical and efficient, may not be conducive to achieve a timely clean-up based on the significant levels of contamination discovered in soil.

7.0 PROJECT SCHEDULE

Upon approval of this supplemental RIR, BEI will begin to draft a Remedial Action Plan (RAP) to address contaminated soils. The RAP will be submitted 45 days from the approval of this Report and issued to the Department for approval. The RAP will include: a remedial plan for addressing contaminated soil in the vadose zone, remedial action objectives (RAOs), operation monitoring and maintenance (OMM) and system termination.

8.0 CONCLUSION

In conclusion, the supplemental sampling data will be used to develop a Remedial Action Plan (RAP) in order to address soil contamination. No groundwater was encountered during any of the investigations conducted and is expected to be approximately 50 feet or more below grade surface. The supplemental sampling results indicated that vertical delineation was achieved at the B-5 and B-8 locations. At the B-4 location delineation was not feasible due to bedrock refusal at a depth of thirty feet (30') bgs. The majority of contamination at this boring was detected in the fifteen (15') feet to twenty five (25') horizon with PID readings as high as 4,500 ppm. Beyond this depth from 25'-30' PID readings drastically waned to levels in the 500 ppm range. Based upon the successful vertical delineation at two (2) locations B-5 and B-8, and the inability to advance beyond the refusals encountered at the surface of the bedrock at the B-6 location, a Remedial Action Plan (RAP) to address contaminated soils will be issue to the Department. Any questions or comments regarding this Report can be directed to BEI.

Sincerely,

Justin Halpin
Project Manager/Scientist

Alicia Patti
Geologist

enc: Figure-1 Site Location
Figure-2 Supplemental Boring Locations
Attachment-A Site Survey Layout
Attachment-B Previous Phase II ESA

FIGURES




Figure-1
Site Location
Brooklyn, NY



Site Map
Boring Locations
Figure-2

BP Service Station
4001-4010 4th Avenue
Brooklyn, NY

BEi Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-1

PROJECT: BP 4th Avenue Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-1	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
FT 0		GROUND SURFACE						
		First 8" concrete and an approximate 10" void of soil from 8" to 18" or 1.5'	0.0	NA	NA			
1.5'		Refusal most likely due to the former tanks backfilled with concrete; unable to advance past 2.5' Refusal at 2.5'						
2.5								
5								

Notes: Refusal at 2.5'
Sampling: No Sample Collected

FIGURE: 3-a
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-2

PROJECT: BP 4th Avenue Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

DEPTH	GRAPHIC	SUBSURFACE PROFILE BORING LOCATION: B-2	SAMPLE PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		First 8" concrete and an approximate 10" void of soil from 8" to 18" or 1.5'	0.0	NA	NA			
1.5'		Refusal most likely due to the former tanks backfilled with concrete; unable to advance past 2.5' Refusal at 2.5'	0.0	NA	NA			
2.5								
5								

Notes: Refusal at 2.5'
Sampling: No Sample Collected

FIGURE: 3-b
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-3

PROJECT: BP 4th Avenue Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-3	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		First 8" concrete and an approximate 10" void of soil from 8" to 18" or 1.5'	0.0	NA	NA			
1.5'		Refusal most likely due to the former tanks backfilled with concrete; unable to advance past 2.5' Refusal at 2.5'	0.0	NA	NA			
2.5								
5								

Notes: Refusal at 2.5'
Sampling: No Sample Collected

FIGURE: 3-c
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-4

PROJECT: BP 4th Ave Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-4	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		10YR-6/4; Light yellowish brown silty fine sand trace gravel, strong odor	38.7	80	SM			
2.5		10YR-6/4; Light yellowish brown silty fine sand trace gravel, strong odor	38.7	80	SM			
5		10YR-5/3; Brown silty fine sand, trace gravel, strong odor	25.0	80	SM			
7.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	25.0	80	SM			
10		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	199	80	SM			
12.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	199	80	SM			
15		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	4500	80	SM			
17.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	4500	80	SM			
20		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	4250	80	SM			
22.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	4250	80	SM			
25		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	900	80	SM			
27.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor; bedrock fragments	500	80	SM			Sample obtained from 27.5'-30'
30		Refusal at 30.0'						
32.5								

Notes: Refusal at 30.0'
Sampling: B-4 Collected at 27.5'-30.0'

FIGURE: 3-d
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-5

PROJECT: BP 4th Ave Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-5	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		10YR-6/4; Light yellowish brown silty fine sand trace gravel, strong odor	2350	80	SM			
2.5		10YR-6/4; Light yellowish brown silty fine sand trace gravel, strong odor	2350	80	SM			
5		10YR-5/3; Brown silty fine sand, trace gravel, strong odor	2390	80	SM			
7.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	2390	80	SM			
10		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	3875	80	SM			
12.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	3875	80	SM			
15		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	1500	80	SM			
17.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	1500	80	SM			
20		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	380	80	SM			
22.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	380	80	SM			
25		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	80	80	SM			
27.5		10YR-5/3; Brown fine sand and silt, trace gravel, odor	80	80	SM			
30		10YR-5/3; Brown fine sand and silt, trace gravel, odor; rock fragments	70	80	SM			Sample obtained from 30-32.5'
32.5		Refusal at 32.5'						

Notes: Refusal at 32.5'
Sampling: B-4 Collected at 30.0'-32.5'

FIGURE: 3-e
METHOD: Direct Push
BORING COMPANY: BEI

April 29, 2020

HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-6

PROJECT: BP 4th Avenue Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-6	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		NA	0.0	NA	SM			
2.5		Refusal at 3.0'	0.0	NA	SM			
5								
7.5								
10								
12.5								
15								
17.5								
20								
22.5								
25								
27.5								
30								

Notes: Refusal at 3.0'
Sampling: No Sample Collected

FIGURE: 3-f
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-7

PROJECT: BP 4th Avenue Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-7	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		NA	0.0	NA	SM			
2.5		Refusal at 3.0'	0.0	NA	SM			
5								
7.5								
10								
12.5								
15								
17.5								
20								
22.5								
25								
27.5								
30								

Notes: Refusal at 3.0'
Sampling: No Sample Collected

FIGURE: 3-g
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-8

PROJECT: BP 4th Avenue Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY


SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-8	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		10YR-5/3; Brown fine sand and silt trace gravel, odor	1600	80	SM			
2.5		10YR-5/3; Brown fine sand and silt trace gravel, odor	1600	80	SM			
5		10YR-5/3; Brown fine sand and silt trace gravel, odor	1870	80	SM			
7.5		10YR-5/3; Brown fine sand and silt trace gravel, odor	1870	80	SM			
10		10YR-5/3; Brown fine sand and silt trace gravel, odor	2490	80	SM			
12.5		10YR-5/3; Brown fine sand and silt trace gravel, odor	2490	80	SM			
15		10YR-5/3; Brown fine sand and silt trace gravel, odor	1430	80	SM			
17.5		10YR-5/3; Brown fine sand and silt trace gravel, odor	1430	80	SM			
20		10YR-5/3; Brown fine sand and silt trace gravel, odor	315	80	SM			
22.5		10YR-5/3; Brown fine sand and silt trace gravel, odor	315	80	SM			
25		10YR-5/3; Brown fine sand and silt trace gravel, odor	110	80	SM			
27.5		10YR-5/3; Brown fine sand and silt trace gravel, odor	90	80	SM			
30		10YR-5/3; Brown fine sand and silt trace gravel, odor	50.2	80	SM			
32.5		10YR-5/3; Brown fine sand and silt trace gravel, no odor	25.5	80	SM			
35		Refusal at 34.0'						

Notes: Refusal at 34.0'
Sampling: No Sample Collected

FIGURE: 3-h
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

ATTACHMENTS

Attachment-A
Current Site Layout Schematic



4TH AVE

0 1 2 5 10 15 20

GASOLINE SERVICE STATION

WITH ACCESSORY CONVENIENCE STORE U.G. 16 B&E
& SELF SERVE DISPENSERS

1 PUMP & TANK SITE PLAN

1" = 10'-0"

TANK MONITORING SYSTEM NOTE(S) & LEGEND :

H = ALARM HORN

L = FLASHING LIGHT

= EMERGENCY CUT OFF SWITCH

* ALARM HORN AND FLASHING LIGHT, CONNECTED TO D.E.C. APPROVED TANK MONITORING SYSTEM TO INDICATE HIGH LEVEL ALARM.

* HIGH LEVEL ALARM, BOTH AUDIBLE AND VISUAL, TO BE TRIGGERED WHEN TANK IS NO MORE THAN 90 % FULL.

* INSTALLATION MUST BE INSTALLED IN ACCORDANCE WITH FEDERAL REGULATION - 40 CFR PARTS 280 AND 281.

NOTE: WHERE INDICATED EXISTING, STEEL SINGLE WALLED UG GASO. TANK TO BE LINED (2-TOTAL), EACH TANK MUST BE LINED AS TO COMPLY WITH ALL TESTING AND REGULATIONS THAT GOVERN INCLUDING USA FEDERAL REGULATIONS (CFR), NEW YORK STATE DEPT. OF ENVIROMENT CONSERVATION, NEW YORK CODE RULES AND REGULATIONS (NYCRR) AND NEW YORK CITY FIRE DEPARTMENT. SEE NPTES "C" & "D" ON DWG. P&T-002 FO RMORE INFORMATION.

EXISTING 2-4,000 GAL. UG SINGLE WALL STEEL FUEL TANKS TO BE LINED. REPLACE CONC. MAT, FOR MORE INFO. SEE DWG P&T-004. REPLACE MANHOLE ON EA. TANK. REMOVE ALL STP & INSTALL NEW STP AS INDICATED. REMOVE ALL PIPING, VALVES, ETC. AND INSTALL NEW AS INDICATED. (C)

TANK LEVEL MONITOR (TLM) CONNECTED TO VEEDER ROOT SYSTEM (TYP. 1-EA. TANK) (4)

BSA APPR'D EXTRACTOR FLOAT VALVE (GAL. 247-83-SM) I-REQ'D IN EA. GASO. TANK EXCEPT DIESEL TANK

(4)NEW DIRECT FILL W/ 4 NEW NYC APPR'D 15 GAL SPILL CONTAINMENT DEVICE AND MECHANICAL OVERFILL PROTECTION DEVICE ON EACH FILL LINE (5)(6)

NEW STAGE-I VAPORY RECOVERY DRYBREAK

(4) NEW 2" DIA. VENT 15' ABOVE GRADE & 10' FROM THE NEAREST BLDG. OPENING & WELL BRACED IN POSITION C.A.R.B. APPROVED P/N CAPS (GASO. TANKS ONLY), GC TO INSTALL 2" DIA. VENT MANIFOLD, SEE DET. ON DWG. P&T-007 (GASO. TANKS ONLY)

NEW 2" SINGLE WALL FIBERGLASS VENT PIPING (PICH BACK TO TANK 1/8" PER FOOT, BACKFILL PER MANUFACTURER'S SPECS.

NEW ANULAR PROBE MONITOR (1 REQ'R EA. TANK) WHERE INDICATED ONLY

(4)NEW DIRECT FILL W/ 4 NEW NYC APPR'D 15 GAL SPILL CONTAINMENT DEVICE AND MECHANICAL OVERFILL PROTECTION DEVICE ON EACH FILL LINE (5)(6)

TANK LEVEL MONITOR (TLM) CONNECTED TO VEEDER ROOT SYSTEM (TYP. 1-EA. TANK) (4)

(3) NEW TOTAL SUBMERSIBLE PUMP IN A STP SUMP, PROVIDE (4) NEW 42" DIA. MANHOLE (1) REQUIRED IN EA. TANK) (4)


STICK LINE IN MANHOLE (1 REQUIRED IN EA. TANK) WHERE INDICATED

REPLACE CONC. MAT & INSTALL NEW PIPING, ETC. AS NOTED, SEE DWGS. P&T-004, P&T-005, P&T-006 FOR MORE INFO.

EXISTING 2-4,000 GAL. UG DOUBLE WALLED MOTOR FUEL TANKS TO BE LINED. REPLACE CONC. MAT, FOR MORE INFO. SEE DWG P&T-004. REPLACE MANHOLE ON EA. TANK. REMOVE ALL STP & INSTALL NEW STP AS INDICATED. REMOVE ALL PIPING, VALVES, ETC. AND INSTALL NEW AS INDICATED. (C)
NOTE: WHERE INDICATED EXISTING, DOUBLE WALLED UG GASO. TANK TO BE LINED (2-TOTAL), EACH TANK MUST BE LINED AS TO COMPLY WITH ALL TESTING AND REGULATIONS THAT GOVERN INCLUDING USA FEDERAL REGULATIONS (CFR), NEW YORK STATE DEPT. OF ENVIROMENT CONSERVATION, NEW YORK CODE RULES AND REGULATIONS (NYCRR) AND NEW YORK CITY FIRE DEPARTMENT. SEE NPTES "C" & "D" ON DWG. P&T-002 FO RMORE INFORMATION.


NOTE

1. EXACT LOCATION OF EXISTING TANK FITTINGS TO BE VERIFY IN THE FIELD.



U-BOLLARD DETAIL

N.T.S.



DRIVE MAT DETAIL

1" = 1'-0"

NOTES:

(1) REMOVE ALL EXISTING CONCRETE PUMP ISLAND, DISPENSERS, TANK STP SUMPS, FILLS, VAPOR RECOVERY MANHOLES, TOP SLAB, AND RELATED PIPING AND REPLACE WITH AMERON DUALOY 3000/L NONMETALLIC PIPING UNLESS OTHERWISE NOTED. DISPENSERS TO BE REFURBISHED AND REUSED.

(2) PIPING SHOWN IS DIAGRAMMATIC ONLY. REFER TO MANUFACTURER'S INSTALLATION MANUAL FOR PROPER INSTALLATION.

(3) GENERAL CONTRACTOR TO VERIFY IN FIELD THE EXACT NUMBER OF TANK OPENINGS AND FITTING LOCATIONS AND NOTIFY ARCHITECT OF ANY DISCREPANCIES.

(4) AT THE TIME OF COMPLETION THE CONTRACTOR SHALL FILE AN AFFIDAVIT WITH THE NEW YORK CITY FIRE DEPARTMENT STATING WORK AND REQUIRED TESTS PERFORMED ON ANY TANKS/PIPING, TESTS RESULTS SHALL BE NOTED AND A COPY SHALL BE SENT TO THE OWNER AND THE ARCHITECT.

(5) GENERAL CONTRACTOR SHALL BE RESPONSIBLE FOR ALL APPLICABLE TESTING/INSPECTIONS OF TANKS AND PIPING SYSTEM UPON COMPLETION OF PROJECT AS REQUIRED BY THE NEW YORK CITY FIRE DEPARTMENT RULES AND REGULATIONS. GENERAL CONTRACTOR TO CONTACT THE NEW YORK CITY FIRE DEPARTMENT AT (718) 644.2462 FOR THIS INFORMATION.

(6) CONTRACTOR MUST CONFORM TO THE REQUIREMENTS OF THE NEW YORK CITY ELECTRICAL CODE AND FILE A CERTIFICATE OF ELECTRICAL INSPECTION UPON COMPLETION OF THE WORK WITH THE NEW YORK CITY FIRE DEPARTMENT.

(7) LOCATION AND NUMBER OF EXISTING PUMPS AND TANKS TO BE VERIFIED BY THE NEW YORK CITY FIRE DEPARTMENT.

(8) THE BIDDING CONTRACTOR SHALL VISIT THE SITE AND BECOME FAMILIAR WITH ALL EXISTING CONDITIONS AND PROPOSED WORK ITEMS TO BE COMPLETED AS NOTED ON THE DRAWINGS PRIOR TO BIDDING.

(9) THE CONTRACTOR SHALL VERIFY THE TYPE AND EXACT LOCATION OF ALL EXISTING TANK PIPING, MPD'S PANS, AND FITTING PENETRATIONS INTO THE TANK. NOTIFY ARCHITECT OF RECORD IN WRITING OF ANY DISCREPANCIES PRIOR TO CONSTRUCTION.

(10) ANY UNDERGROUND DRAINAGE LINES, WATER LINES, SEWER LINES, ELECTRICAL LINES, ETC. THAT MAY BE ENCOUNTERED DURING THE COURSE OF CONSTRUCTION SHALL BE REMOVED AND REROUTED AS REQUIRED. GENERAL CONTRACTOR TO NOTIFY ARCHITECT AND OWNER IMMEDIATELY.

(11) PROVIDE COLOR AND SYMBOL CODES ON ALL FILLS AND GAUGE PORTS AS PER A.P.I., N.Y.S.D.E.C. AND OWNER'S STANDARDS. PRODUCT I.D. MARKERS SHALL BE INSTALLED ON ALL FILL PORTS PER N.Y.S.D.E.C. REQUIREMENTS.

(12) GENERAL CONTRACTOR TO PRECISION TEST TANKS, PIPING SYSTEM, ETC. PRIOR TO CONSTRUCTION OF PROJECT AS PER NEW YORK CITY FIRE DEPARTMENT RULES AND REGULATIONS. GENERAL CONTRACTOR SHALL SECURE THE SERVICES OF THE NEW YORK CITY FIRE DEPARTMENT FOR TESTING PURPOSES. AFTER INSTALLATION GENERAL CONTRACTOR SHALL SCHEDULE A TEST TO BE DONE BY OWNER ON TANKS, PIPING, ETC. GENERAL CONTRACTOR SHALL NOT BACK FILL UNTIL ALL TESTING HAS BEEN DONE.

(13) GENERAL CONTRACTOR SHALL BE RESPONSIBLE FOR PROVIDING A "SPARK TEST" OF THE CATHODICALLY PROTECTED PIPE WITNESSED BY A NEW YORK CITY FIRE DEPARTMENT INSPECTOR BEFORE BACK FILL INSPECTION IS SCHEDULED. (IF APPLICABLE)

(14) GENERAL CONTRACTOR TO ASSURE THAT ELECTRICAL EXPLOSION PROOF CONNECTIONS ARE PROVIDED AND IN GOOD CONDITION AT EACH TANK SUMP AS REQUIRED PER N.F.P.A. AND N.E.C. CODES.

(15) GENERAL CONTRACTOR SHALL PATCH AND REPAIR AREAS OF THE CONCRETE DRIVE MAT, SURROUNDING THE ISLANDS, DISTURBED BY CONSTRUCTION WITH A MINIMUM OF 0'-8" THICK CONCRETE, 0'-4" CRUSHED STONE AND (1) LAYER OF #5 REBARS EACH WAY.

N.Y.C. FIRE DEPARTMENT APPROVAL / EQUIPMENT LIST

EQ. NO.	EQUIPMENT	MANUFACTURER	MODEL NUMBER	C of A NUMBER
(1)	MULTI-PRODUCT BLENDER DISPENSER W/SB3	"WAYNE" OVATION	B12/B223DI/6K DOB 2-HOSE	5082
	DISPENSER PAN	ENVIRO	DEEP PAN	
(2)	NOT USED			
(3)	UNDERGROUND PIPING	SMITH FIBERCAST	RED THREAD IIA	5099
(4)	SUBMERSIBLE TURBINE PUMP	FE PETRO	1 1/2 HP W/ INTAKE FILTER SCREEN	4834
(5)	MECHANICAL OVERFILL PREVENTION DEVICE	OPW	61SO (GRAVITY FILL)	4902
(6)	SPILL CONTAINMENT DEVICE	OPW	1-2115 (15 GALLON)	4978
(7)	FLEXIBLE CONNECTOR	TITEFLEX	FIRESAFE	
(8)	EXTRACTOR FITTING - CROSS	OPW	233VM-4433	
(9)	LEAK DETECTION SYSTEM	VEEDER ROOT	TLS 350	4853
	AUTOMATIC TANK GAUGE TANK LEVEL PROBE TANK HYDROSTATIC SUMP SENSOR ELECTRONIC LINE LEAK DETECTOR STP SUMP SENSOR DISPENSER PAN SENSOR			
(10)	EXIST. DOUBLE WALLED TANKS TO BE LINED	VIF	EXIST. (2-TOTAL) 4000 GALLONS	VIF
(11)	EXIST. STEEL SINGLE WALLED TANKS TO BE LINED	VIF	EXIST. (2-TOTAL) 4000 GALLONS	VIF

AS-BUILT DRAWINGS & INSTALLER STATEMENT:

G.C./ INSTALLER SHALL PROVIDE A COMPLETE SET OF AS BUILT DRAWINGS TO SCALE DEPICTING PRECISE LOCATION OF ALL COMPONENTS INSTALLED (INCLUDING PRODUCT/ VAPOR LINE SIZES & LOCATIONS, CONDUIT SIZES & LOCATIONS, ETC.) PRIOR TO OWNER'S ACCEPTANCE.

THESE PLANS MUST INCLUDE A STATEMENT BY THE INSTALLER THAT THE SYSTEM HAS BEEN INSTALLED IN COMPLIANCE WITH THE NEW YORK STATE STANDARDS FOR NEW AND SUBSTANTIALLY MODIFIED PETROLEUM STORAGE FACILITIES, 6 NYCRR PART 614.

LICENSED INSTALLER'S FINAL STATEMENT

I, _____ COMPLETED THE INSTALLATION OF THE EQUIPMENT DESCRIBED IN THE ANNEXED PLANS ON _____. THE INSTALLATION COMPLIES FULLY WITH THE REQUIREMENTS OF THE NEW YORK STATE PETROLEUM BULK STORAGE CODE 6 NYCRR PART 614.

_____
SIGNATURE OF THE LICENSED INSTALLER

FILL BOX IDENTIFICATION REQUIREMENTS:

IDENTIFICATION REQUIREMENTS SHALL CONFORM TO AMERICAN PETROLEUM INSTITUTE STANDARDS.

AMENDED

VAPOR HOSE CONNECTION:	UNLEADED (LOWER)	UNLEADED (HIGHER)	DIESEL
ORANGE	BLACK CROSS WHITE BACKGROUND	WHITE CROSS RED BACKGROUND	YELLOW

ACCEPTABLE FOR PERMIT UNDER DIRECTIVE NO. 14/1975
DEC 28 2010
KAUSAR AHMAD

320041897
SC343628763

REGISTERED ARCHITECT JAMES P. VASSALOTTI 026076 STATE OF NEW YORK

REV	DATE	DESCRIPTION
-	6-17-09	ISSUED TO BID
-	6-24-09	ISSUED TO BLDG DEPT. FOR APPROVAL
-	8-31-09	AS BUILT CONDITIONS

DRAWING: PUMP & TANK SITE PLAN AND EQUIPMENT SCHEDULE

LOCATION: 4001 4th LLC
4001-11 4th AVE
BROOKLYN, NEW YORK

BLOCK 774 | LOT 6 | MAP --- | ZONE C-8 IN R6

VASSALOTTI ARCHITECTS, L.L.P. ASSOCIATES
3000 MARCUS AVE. LAKE SUCCESS, NY 11042

DWN. BY	CHK. BY
JEFF V.	A.D.

SCALE: AS NOTED

DATE	JOB NO.
6-17-09	08-0071

PAGE NO. DWG. 4 OF 9

DWG. NO. P&T-004.00

Attachment-B
Previous Phase II ESA

CASTLETON
ENVIRONMENTAL

January 25, 2019

Donald Middleton
Middleton Environmental Inc.
54 George Street
Babylon, New York 11702

RE: Phase II Environmental Site Assessment
4001-4011 4th Avenue, Brooklyn, New York

Dear Mr. Middleton:

Please find the attached Phase II Environmental Site Assessment Report for the property located at 4001-4011 4th Avenue, Brooklyn New York.

Thank you for the opportunity. Please call with any questions or comments.

Very truly yours,
Castleton Environmental Geologic Services, DPC



Frank P. Castellano, PG
Principal

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

CASTLETON
ENVIRONMENTAL

54 George Street, Babylon Village, NY 11702
206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 OFFICE
631-482-9042 FAX
www.castletonenv.com

Phase II Environmental Site Assessment
4001-4011 4th Avenue
Brooklyn, New York



Prepared for: Donald Middleton
Middleton Environmental Inc.
54 George Street
Babylon, New York 11702

PHASE II ENVIRONMENTAL SITE ASSESSMENT
4001-4011 4TH AVENUE
BROOKLYN, NEW YORK
JANUARY 2019
CASTLETON PROJECT NUMBER: MEIN1901

Table of Contents

1.0 INTRODUCTION 1
2.0 SITE BACKGROUND 1
3.0 PHASE II ESA FIELD INVESTIGATION 1
3.1 Geophysical Survey 2
3.2 Soil Investigation 2
4.0 ANALYTICAL RESULTS AND DATA DISCUSSION 3
5.0 CONCLUSIONS AND RECOMMENDATIONS 4
6.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS 4

Figures

Figure 1 – Vicinity Map
Figure 2 – Site and Sampling Plan

Appendices

Appendix A – Soil Boring Logs
Appendix B – Laboratory Analytical Reports

1.0 INTRODUCTION

Castleton Environmental Geologic Services DPC (Castleton) has prepared the following Phase II Environmental Site Assessment (ESA) report to document the work performed at 4001-4011 4th Avenue, Brooklyn, New York (the site). The investigation was performed based upon review of the Phase I ESA by Merritt Environmental Consulting Corp. (MECC) dated January 7, 2019.

The objectives of this work were to determine if the sites historic and current usage as a gasoline station has impacted the subsurface. The objective was met through the performance of a geophysical survey and the collection and laboratory analysis of soil samples.

2.0 SITE BACKGROUND

The site is located at 4001-4011 4th Avenue, Brooklyn, New York (Figure 1). The site is located on a plot size approximately 10,017 square feet. The site is currently used as a gas station with a convenience store and parking. The building was constructed in 1965.

Castleton reviewed the Phase I ESA prepared by MECC dated January 7, 2019. The MECC Phase I ESA identified that site has been a gasoline since its first developed use. According to the historical Sanborn Maps, a gasoline tank is present at the corner of 4th Avenue and 10th Street during the years 1926-1951.

MECC recommended further evaluation to determine if any documentation is available or if additional investigation (Phase II) is warranted. Subsequent documentation regarding the gasoline tank shown on the 1926-1951 Sanborn Maps was not provided.

3.0 PHASE II ESA FIELD INVESTIGATION

The objective of this Phase II ESA was to assess subsurface quality in relation to historic and current on-site filling station operations at the site.

The following scope of work was completed to assess subsurface conditions:

Task	Objective
Geophysical Survey	Determine if any subsurface anomalies indicative of underground storage tanks (USTs) and to clear underground utilities
Soil Sampling	Characterize site soil quality for impacts related to filling station operations

On-site work was completed on January 15, 2019. Sample collection locations are depicted on Figure 2.

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

3.1 Geophysical Survey

A geophysical survey was performed to identify evidence of subsurface anomalies and to mark on-site utilities in proposed subsurface work areas. The survey was performed using a variety of remote sensing equipment/methods including a magnetometer to identify ferrous metallic objects, ground penetrating radar (GPR) to identify changes in soil density and a pipe locating device to trace piping runs. The geophysical survey was performed by Delta Geophysics, Inc. of Catasauqua, Pennsylvania.

As described in the PBS records included in the Phase I ESA, 4 4,000-gallon USTs are currently in use at the site and were identified during the geophysical survey to clear boring locations.

Nine suspect (USTs) were identified that are currently not in use. Four suspect UST anomalies are centralized under the canopy between the active dispensers. Five suspect UST anomalies are located at the western portion of the site.

A metal anomaly not indicative of a UST was identified at northern portion of the site. A suspect UST was not identified at the northern portion of the site where the gas tank was shown on the historic Sanborn Maps.

All on site utilities were cleared before intrusive activities.

3.2 Soil Investigation

Soil borings were advanced to assess soil conditions at the site. Boring locations were selected based on potential areas identified during the geophysical survey. Soil borings were advanced with direct push technology (Geoprobe®) by Coastal Environmental Solutions, Inc. of Medford, New York.

Six soil borings were advanced. Soil samples were collected continuously from each boring location, logged and field screened with a PID for the presence of VOCs. Elevated field sensory (PID), olfactory or visible evidence of impacts to soil were observed in each of the borings ranging from 22.9 ppm in SB01 to 5,285 ppm in SB04. Soil was observed to consist of silty fine and medium sand. Groundwater was not encountered during this investigation. Soil boring logs are provided as Appendix A.

The following table describes the boring location, area of concern associated with each boring, and sample collected for laboratory analysis.

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

Boring	Area of Concern	Highest Soil PID Readings (ppm)	Boring Depth (feet)	Soil Analytical Sample Interval(s)
SB01	Area of former UST (Sanborn Map) and metal anomaly	22.9	25	18-20 feet
SB02	Area of former UST (Sanborn Map) and metal anomaly	425.9	20	4-6 feet
SB03	Area of former UST (Sanborn Map) and metal anomaly	2,195	22	12-14 feet
SB04	West of the five suspect USTs	5,285	30	16-18 feet
SB05	West of the five suspect USTs	3,963	20	10-15 feet
SB06	South of the five suspect USTs and west of the currently in use USTs	4,955	24.5	18-20 feet

Soil retained for laboratory analysis was placed into laboratory supplied glassware and submitted under chain of custody to York Analytical Laboratories of Stratford, Connecticut, a New York State Department of Health (NYSDOH) ELAP certified laboratory. Soil samples were analyzed for:

- CP-51 VOCs via EPA Method 8260, and
- CP-51 SVOCs via EPA Method 8270

4.0 ANALYTICAL RESULTS AND DATA DISCUSSION

Soil analytical results were compared to NYSDEC CP-51 Soil Cleanup Levels (SCLs) for petroleum impacted soil and NYSDEC Part 375 Soil Cleanup Objectives (SCOs).

Soil analytical results reported concentrations SVOCs as non-detect or below SCLs and SCOs in the six soil sample analyzed.

VOCs above SCLs were reported in five of the six soil samples. VOCs above Commercial SCOs were reported in two of the six samples analyzed.

Analytical results and laboratory report are presented in Appendix B.

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

5.0 CONCLUSIONS AND RECOMMENDATIONS

Castleton has prepared the following Phase II ESA report to document the work performed at 4001-4011 4th Avenue, Brooklyn, New York. The investigation was performed based upon review of the Phase I ESA by MECC dated January 7, 2019.

The objectives of this work were to determine if the sites historic and current usage as a gasoline station has impacted the subsurface. The objective was met through the performance of a geophysical survey and the collection and laboratory analysis of soil samples.

The geophysical survey identified the presence of the 4 in use USTs, nine suspect USTs that are currently not in use, and one metal anomaly that is not indicative of a UST.


Six soil boring were advanced, and six soil samples collected for laboratory analysis. Analytical results reported concentrations of VOCs above applicable standards in five of the six soil samples analyzed.

Castleton recommends the following:

- Notification of these findings be made to NYSDEC
- The suspect USTs be assessed and, if are present, properly removed as per NYSDEC protocols
- Petroleum impacts to soil be delineated and remediated under the NYSDEC Spills Program

6.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS





Frank P. Castellano, PG
Principal

Jessica Ferngren, PG
Sr. Project Manager

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

CASTLETON ENVIRONMENTAL

FIGURES

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com




Figure 1 – Vicinity Map

4001-4011 4th Avenue

Brooklyn, New York

+




Figure 2 – Site Plan

4001-4011 4th Avenue

Brooklyn, New York

CASTLETON
ENVIRONMENTAL

APPENDIX A

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com



Locations are approximate

Boring # **SB01**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**25 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 9:25		DATE: 1/15/2019	
COMPLETION TIME: 9:50		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	4	Asphalt Brown silty fine SAND, trace fine gravel	PID = 0.0 ppm.	
5-10 ft	5	3	Brown silty fine SAND, trace fine gravel	PID = 8.2 ppm.	
10-15 ft	5	3.5	Brown silty fine SAND, trace fine gravel	PID = 0.8 ppm.	
15-20 ft	5	1.5	Brown silty fine SAND, trace fine gravel Perched water @ 20-21 feet	PID = 22.9 ppm.	
20-25 ft	5	3	Brown clayey SAND, trace fine gravel	PID = 0.0 ppm.	



Locations are approximate

Boring # **SB02**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**20 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 9:50		DATE: 1/15/2019	
COMPLETION TIME: 10:10		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	3	Asphalt Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 23.4 ppm.	
5-10 ft	5	2.5	Brown silty fine SAND, trace fine gravel, brick	PID = 423.4 ppm.	
10-15 ft	5	2	Brown silty fine SAND, trace fine gravel, brick	PID = 0.0 ppm.	
15-20 ft	5	3	Brown silty fine SAND, trace fine gravel, brick	PID = 0.0 ppm.	



Locations are approximate

Boring # **SB03**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**22 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 10:10		DATE: 1/15/2019	
COMPLETION TIME: 11:00		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	0.5	Asphalt Black silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 23.4 ppm.	
5-10 ft	5	3.5	Black silty fine SAND, trace fine gravel, brick - Petroleum odor Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 423.4 ppm.	
10-15 ft	5	4	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 0.0 ppm.	
15-20 ft	5	2.5	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 0.0 ppm.	
20-22 ft	2	0.5	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor Refusal @ 22'	PID = 0.0 ppm.	



Locations are approximate

Boring # **SB04**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**30 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 11:00		DATE: 1/15/2019	
COMPLETION TIME: 11:40		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	0.5	Asphalt Dark brown silty fine SAND, brick - Petroleum odor	PID = 126.7 ppm.	
5-10 ft	5	2	Brown silty fine SAND, brick - Petroleum odor	PID = 148.9 ppm.	
10-15 ft	5	2	Brown silty fine SAND, brick - Petroleum odor	PID = 3,414 ppm.	
15-20 ft	5	2.5	Brown silty fine SAND, brick - Petroleum odor	PID = 5,285 ppm.	
20-25 ft	5	3	Brown silty fine SAND, brick - Petroleum odor	PID = 4,675 ppm.	
25-30 ft	5	2.5	Brown silty fine SAND, brick - Petroleum odor	PID = 368.4 ppm.	



Locations are approximate

Boring # **SB05**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**20 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 11:40		DATE: 1/15/2019	
COMPLETION TIME: 12:00		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	1	Concrete Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 2,634 ppm.	
5-10 ft	5	2	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 2,391 ppm.	
10-15 ft	5	0.5	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 3,963 ppm.	
15-20 ft	5	0.5	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 1,516 ppm.	



Locations are approximate

Boring # **SB06**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**24.5 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 12:00		DATE: 1/15/2019	
COMPLETION TIME: 12:20		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	0.5	Concrete Tan silty fine SAND, trace fine gravel, brick	PID = 53.7 ppm.	
5-10 ft	5	0.5	Brown silty fine SAND, trace fine gravel	PID = 10.7 ppm.	
10-15 ft	5	1.5	Brown silty fine SAND, trace fine gravel	PID = 248.6 ppm.	
15-20 ft	5	2	Brown silty fine SAND, trace fine gravel	PID = 4,955 ppm.	
20-24.5 ft	4.5	0.5	Brown silty fine SAND, trace fine gravel	PID = 4,815 ppm.	

CASTLETON
ENVIRONMENTAL

APPENDIX B

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

Sample ID York ID Sampling Date Client Matrix		NYSDEC CP/SCO Table 2-Gasoline	NYSDEC CP/SCO Table 3-Fuel Oil	NYSDEC Part 375 Unrestricted Use Soil Cleanup Objectives	NYSDEC Part 375 Restricted Use Soil Cleanup Objectives - Restricted Residential	NYSDEC Part 375 Restricted Use Soil Cleanup Objectives- Commercial	SB01 19A0642-01 1/15/2019 9:50:00 AM Soil		SB02 19A0642-02 1/15/2019 10:10:00 AM Soil		SB03 19A0642-03 1/15/2019 11:00:00 AM Soil		SB04 19A0642-04 1/15/2019 11:40:00 AM Soil		SB05 19A0642-05 1/15/2019 12:00:00 PM Soil		SB06 19A0642-06 1/15/2019 12:20:00 PM Soil	
Compound	**CAS Number**						Result	Q	Result	Q	Result	Q	Result	Q	Result	Q	Result	Q
Volatile Organics, CP-51 (formerly STARS) List		mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg		mg/Kg		mg/Kg		mg/Kg		mg/Kg		mg/Kg	
Dilution Factor							1		100		200		10000		1000		5000	
1,2,4-Trimethylbenzene	95-63-6	3.6	3.6	3.6	52	190	0.00650		**4.400**	D	**22**	D	**1,200**	D	**57**	D	**360**	D
1,3,5-Trimethylbenzene	108-67-8	8.4	8.4	8.4	52	190	0.00290	J	0.170		**9.100**	D	**830**	D	**19**	D	**57**	D
Benzene	71-43-2	0.06	0.06	0.06	4.8	44	0.00680		0.00370	J	**1.200**	D	**20**	D	**2.400**	D	**3.600**	D
Ethyl Benzene	100-41-4	1	1	1	41	390	0.00310	J	0.100		**10**	D	**1,100**	D	**21**	D	**77**	D
Isopropylbenzene	98-82-8	2.3	2.3	~	~	~	0.00220	U	0.0780		**3**	D	**48**	D	**3.700**	D	**9.600**	D
Methyl tert-butyl ether (MTBE)	1634-04-4	0.93	~	0.93	100	500	0.0560		0.00350	J	0.0460		0.270	U	0.220	U	0.180	U
Naphthalene	91-20-3	12	12	12	100	500	0.00310	J	0.190		0.140		**88**	BD	6.300	BD	**23**	BD
n-Butylbenzene	104-51-8	12	12	12	100	500	0.00220	U	0.0930		0.200		**31**	D	2.700	D	6.800	D
n-Propylbenzene	103-65-1	3.9	3.9	3.9	100	500	0.00220	U	0.130		**4.800**	D	**170**	D	**11**	D	**34**	D
o-Xylene	95-47-6	~	~	~	~	~	0.00220	U	0.00250	U	3.700	D	650	D	32	D	120	D
p- & m- Xylenes	179601-23-1	~	~	~	~	~	0.00540	J	0.0130		22	D	1,600	D	82	D	350	DE
p-Isopropyltoluene	99-87-6	10	10	~	~	~	0.00220	U	0.170		2.900	D	**15**	D	1.400	D	2.300	D
sec-Butylbenzene	135-98-8	11	11	11	100	500	0.00220	U	0.110		2.100	D	**21**	D	1.600	D	3.900	D
tert-Butylbenzene	98-06-6	5.9	5.9	5.9	100	500	0.00220	U	0.0340		0.120		0.270	U	0.220	U	0.180	U
Toluene	108-88-3	0.7	0.7	0.7	100	500	0.00220	U	0.00360	J	**8.300**	D	**1,500**	D	**64**	D	**370**	D
Xylenes, Total	1330-20-7	0.26	0.26	0.26	100	500	0.00650	U	0.0130	J	**26**	D	**2,300**	D	**110**	D	**480**	DE
Semi-Volatiles, CP-51 (formerly STARS) List		mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg		mg/Kg		mg/Kg		mg/Kg		mg/Kg		mg/Kg	
Dilution Factor							2		2		2		2		2		2	
Acenaphthene	83-32-9	~	20	20	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Acenaphthylene	208-96-8	~	100	100	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Anthracene	120-12-7	~	100	100	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(a)anthracene	56-55-3	~	1	1	1	5.6	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(a)pyrene	50-32-8	~	1	1	1	1	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(b)fluoranthene	205-99-2	~	1	1	1	5.6	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(g,h,i)perylene	191-24-2	~	100	100	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(k)fluoranthene	207-08-9	~	0.8	0.8	3.9	56	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Chrysene	218-01-9	~	1	1	3.9	56	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Dibenzo(a,h)anthracene	53-70-3	~	0.33	0.33	0.33	0.56	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Fluoranthene	206-44-0	~	100	100	100	500	0.0450	U	0.0870	JD	0.0560	JD	0.0540	U	0.0450	U	0.0460	U
Fluorene	86-73-7	~	30	30	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Indeno(1,2,3-cd)pyrene	193-39-5	~	0.5	0.5	0.5	5.6	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Naphthalene	91-20-3	12	12	12	100	500	0.0450	U	0.180	D	1.600	D	1.500	D	2.900	DE	0.120	D
Phenanthrene	85-01-8	~	100	100	100	500	0.0450	U	0.100	D	0.0740	JD	0.0540	U	0.0450	U	0.0460	U
Pyrene	129-00-0	~	100	100	100	500	0.0450	U	0.0880	JD	0.0470	JD	0.0540	U	0.0450	U	0.0460	U
Total Solids							%		%		%		%		%		%	
Dilution Factor							1		1		1		1		1		1	
% Solids	solids	~	~	~	~	~	91		93.100		93.200		77.100		91.200		90.300	

NOTES:

Any Regulatory Exceedences are color coded by Regulation

Q is the Qualifier Column with definitions as follows:

D=result is from an analysis that required a dilution

J=analyte detected at or above the MDL (method detection limit) but below the RL (Reporting Limit) - data is estimated

U=analyte not detected at or above the level indicated

B=analyte found in the analysis batch blank

E=result is estimated and cannot be accurately reported due to levels encountered or interferences

P=this flag is used for pesticide and PCB (Aroclor) target compounds when there is a % difference for detected concentrations that exceed method dictated limits between the two GC columns used for analysis

NT=this indicates the analyte was not a target for this sample

~=this indicates that no regulatory limit has been established for this analyte

Technical Report

prepared for:

Castleton Environmental
54 George Street
Babylon NY, 11702
Attention: Jessica Ferngren

Report Date: 01/23/2019
Client Project ID: MEIN1901
York Project (SDG) No.: 19A0642

Report Date: 01/23/2019
Client Project ID: MEIN1901
York Project (SDG) No.: 19A0642

Castleton Environmental
54 George Street
Babylon NY, 11702
Attention: Jessica Ferngren

Purpose and Results

This report contains the analytical data for the sample(s) identified on the attached chain-of-custody received in our laboratory on January 16, 2019 with a temperature of 1.5 C. The project was identified as your project: **MEIN1901**.

The analyses were conducted utilizing appropriate EPA, Standard Methods, and ASTM methods as detailed in the data summary tables.

All samples were received in proper condition meeting the customary acceptance requirements for environmental samples except those indicated under the Sample and Analysis Qualifiers section of this report.

All analyses met the method and laboratory standard operating procedure requirements except as indicated by any data flags, the meaning of which are explained in the Sample and Data Qualifiers Relating to This Work Order section of this report and case narrative if applicable.

The results of the analyses, which are all reported on dry weight basis (soils) unless otherwise noted, are detailed in the following pages.

Please contact Client Services at 203.325.1371 with any questions regarding this report.

York Sample ID	Client Sample ID	Matrix	Date Collected	Date Received
19A0642-01	SB01	Soil	01/15/2019	01/16/2019
19A0642-02	SB02	Soil	01/15/2019	01/16/2019
19A0642-03	SB03	Soil	01/15/2019	01/16/2019
19A0642-04	SB04	Soil	01/15/2019	01/16/2019
19A0642-05	SB05	Soil	01/15/2019	01/16/2019
19A0642-06	SB06	Soil	01/15/2019	01/16/2019

General Notes for York Project (SDG) No.: 19A0642

1. The RLs and MDLs (Reporting Limit and Method Detection Limit respectively) reported are adjusted for any dilution necessary due to the levels of target and/or non-target analytes and matrix interference. The RL(REPORTING LIMIT) is based upon the lowest standard utilized for the calibration where applicable.
2. Samples are retained for a period of thirty days after submittal of report, unless other arrangements are made.
3. York's liability for the above data is limited to the dollar value paid to York for the referenced project.
4. This report shall not be reproduced without the written approval of York Analytical Laboratories, Inc.
5. All analyses conducted met method or Laboratory SOP requirements. See the Sample and Data Qualifiers Section for further information.
6. It is noted that no analyses reported herein were subcontracted to another laboratory, unless noted in the report.
7. This report reflects results that relate only to the samples submitted on the attached chain-of-custody form(s) received by York.
8. Analyses conducted at York Analytical Laboratories, Inc. Stratford, CT are indicated by NY Cert. No. 10854; those conducted at York Analytical Laboratories, Inc., Richmond Hill, NY are indicated by NY Cert. No. 12058.

Approved By: 

Date: 01/23/2019

Benjamin Gulizia
Laboratory Director

Sample Information

Client Sample ID: **SB01** **York Sample ID:** **19A0642-01**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 9:50 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**6.5**		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-67-8	**1,3,5-Trimethylbenzene**	**2.9**	J	ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
71-43-2	**Benzene**	**6.8**		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
100-41-4	**Ethyl Benzene**	**3.1**	J	ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-82-8	Isopropylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1634-04-4	**Methyl tert-butyl ether (MTBE)**	**56**		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
91-20-3	**Naphthalene**	**3.1**	J	ug/kg dry	2.2	8.6	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI			
104-51-8	n-Butylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
103-65-1	n-Propylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
95-47-6	o-Xylene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
179601-23-1	**p- & m- Xylenes**	**5.4**	J	ug/kg dry	4.3	8.6	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
99-87-6	p-Isopropyltoluene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
135-98-8	sec-Butylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-06-6	tert-Butylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-88-3	Toluene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1330-20-7	Xylenes, Total	ND		ug/kg dry	6.5	13	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,NJ			

	Surrogate Recoveries	Result	Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*102 %*	*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*102 %*	*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*109 %*	*76-130*

Sample Information

Client Sample ID: SB01 **York Sample ID:** 19A0642-01

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 9:50 am	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
208-96-8	Acenaphthylene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
120-12-7	Anthracene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
218-01-9	Chrysene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
206-44-0	Fluoranthene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
86-73-7	Fluorene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	NELAC-NY10854,NJDEP,PADEP		
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
91-20-3	Naphthalene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
85-01-8	Phenanthrene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
129-00-0	Pyrene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*54.7 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*71.8 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*66.4 %*	*24-116*

Total Solids

Log-in Notes:

Sample Notes:

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst

Sample Information

Client Sample ID: SB01 **York Sample ID:** 19A0642-01

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 9:50 am	01/16/2019

Total Solids **Log-in Notes:** **Sample Notes:**

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	* % Solids	91.0		%	0.100	1	SM 2540G Certifications: CTDOH	01/22/2019 11:58	01/22/2019 16:28	MAC

Sample Information

Client Sample ID: SB02 **York Sample ID:** 19A0642-02

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 10:10 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List **Log-in Notes:** **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	1,2,4-Trimethylbenzene	4400		ug/kg dry	250	500	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/21/2019 11:58	LLJ
108-67-8	1,3,5-Trimethylbenzene	170	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
71-43-2	Benzene	3.7	J	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
100-41-4	Ethyl Benzene	100		ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
98-82-8	Isopropylbenzene	78	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
1634-04-4	Methyl tert-butyl ether (MTBE)	3.5	J	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
91-20-3	Naphthalene	190	IS-HI	ug/kg dry	2.5	10	1	EPA 8260C Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI	01/18/2019 08:45	01/18/2019 19:56	LLJ
104-51-8	n-Butylbenzene	93	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
103-65-1	n-Propylbenzene	130	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
95-47-6	o-Xylene	ND		ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
179601-23-1	p- & m- Xylenes	13		ug/kg dry	5.0	10	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
99-87-6	p-Isopropyltoluene	170	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
135-98-8	sec-Butylbenzene	110	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
98-06-6	tert-Butylbenzene	34	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ

Sample Information

Client Sample ID: SB02 **York Sample ID:** 19A0642-02

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 10:10 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
108-88-3	**Toluene**	**3.6**	J	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications:	01/18/2019 08:45 CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 19:56	LLJ
1330-20-7	**Xylenes, Total**	**13**	J	ug/kg dry	7.5	15	1	EPA 8260C Certifications:	01/18/2019 08:45 CTDOH,NELAC-NY10854,NELAC-NY12058,NJ	01/18/2019 19:56	LLJ

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*122 %*		*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*90.5 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*246 %*	IS-HI, S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
208-96-8	Acenaphthylene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
120-12-7	Anthracene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
218-01-9	Chrysene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
206-44-0	**Fluoranthene**	**87**	J	ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
86-73-7	Fluorene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
91-20-3	**Naphthalene**	**180**		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW

Sample Information

Client Sample ID: SB02 **York Sample ID:** 19A0642-02

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 10:10 am	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
85-01-8	**Phenanthrene**	**100**		ug/kg dry	45	89	2	EPA 8270D	01/22/2019 07:32	01/22/2019 21:49	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
129-00-0	**Pyrene**	**88**	J	ug/kg dry	45	89	2	EPA 8270D	01/22/2019 07:32	01/22/2019 21:49	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*61.4 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*73.5 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*75.9 %*	*24-116*

Total Solids

Log-in Notes:

Sample Notes:

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**93.1**		%	0.100	1	SM 2540G	01/22/2019 11:58	01/22/2019 16:28	MAC
							Certifications: CTDOH			

Sample Information

Client Sample ID: SB03 **York Sample ID:** 19A0642-03

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:00 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**22000**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-67-8	**1,3,5-Trimethylbenzene**	**9100**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
71-43-2	**Benzene**	**1200**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
100-41-4	**Ethyl Benzene**	**10000**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-82-8	**Isopropylbenzene**	**3000**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1634-04-4	**Methyl tert-butyl ether (MTBE)**	**46**	IS-HI	ug/kg dry	2.6	5.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 20:23	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
91-20-3	**Naphthalene**	**140**		ug/kg dry	2.6	11	1	EPA 8260C	01/18/2019 08:45	01/18/2019 20:23	LLJ
								Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI			

Sample Information

Client Sample ID: **SB03** **York Sample ID:** **19A0642-03**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:00 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
104-51-8	**n-Butylbenzene**	**200**		ug/kg dry	2.6	5.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 20:23	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
103-65-1	**n-Propylbenzene**	**4800**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
95-47-6	**o-Xylene**	**3700**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
179601-23-1	**p- & m- Xylenes**	**22000**		ug/kg dry	1100	2100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
99-87-6	**p-Isopropyltoluene**	**2900**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
135-98-8	**sec-Butylbenzene**	**2100**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-06-6	**tert-Butylbenzene**	**120**		ug/kg dry	2.6	5.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 20:23	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-88-3	**Toluene**	**8300**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1330-20-7	**Xylenes, Total**	**26000**		ug/kg dry	1600	3200	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,NJ			

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*388 %*	IS-HI, S-03	*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*104 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*1100 %*	S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
208-96-8	Acenaphthylene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
120-12-7	Anthracene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			

Sample Information

Client Sample ID: SB03 **York Sample ID:** 19A0642-03

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:00 am	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
218-01-9	Chrysene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
206-44-0	**Fluoranthene**	**56**	J	ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
86-73-7	Fluorene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	NELAC-NY10854,NJDEP,PADEP		
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
91-20-3	**Naphthalene**	**1600**		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
85-01-8	**Phenanthrene**	**74**	J	ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
129-00-0	**Pyrene**	**47**	J	ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*78.2 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*73.7 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*83.8 %*	*24-116*

Total Solids

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**93.2**		%	0.100	1	SM 2540G	01/22/2019 11:58	01/22/2019 16:28	MAC
							Certifications:	CTDOH		

Sample Information

Client Sample ID: SB04 **York Sample ID:** 19A0642-04

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:40 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst

Sample Information

Client Sample ID: **SB04** **York Sample ID:** **19A0642-04**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:40 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**1200000**		ug/kg dry	27000	54000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-67-8	**1,3,5-Trimethylbenzene**	**830000**		ug/kg dry	14000	27000	5000	EPA 8260C	01/21/2019 09:52	01/21/2019 17:22	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
71-43-2	**Benzene**	**20000**	IS-HI	ug/kg dry	270	540	100	EPA 8260C	01/21/2019 09:52	01/21/2019 12:52	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
100-41-4	**Ethyl Benzene**	**1100000**		ug/kg dry	14000	27000	5000	EPA 8260C	01/21/2019 09:52	01/21/2019 17:22	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-82-8	**Isopropylbenzene**	**48000**		ug/kg dry	2700	5400	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1634-04-4	Methyl tert-butyl ether (MTBE)	ND	IS-HI	ug/kg dry	270	540	100	EPA 8260C	01/21/2019 09:52	01/21/2019 12:52	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
91-20-3	**Naphthalene**	**88000**	B	ug/kg dry	2700	11000	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI			
104-51-8	**n-Butylbenzene**	**31000**		ug/kg dry	2700	5400	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
103-65-1	**n-Propylbenzene**	**170000**		ug/kg dry	2700	5400	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
95-47-6	**o-Xylene**	**650000**		ug/kg dry	27000	54000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
179601-23-1	**p- & m- Xylenes**	**1600000**		ug/kg dry	54000	110000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
99-87-6	**p-Isopropyltoluene**	**15000**		ug/kg dry	270	540	100	EPA 8260C	01/21/2019 09:52	01/21/2019 12:52	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
135-98-8	**sec-Butylbenzene**	**21000**		ug/kg dry	2700	5400	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-06-6	tert-Butylbenzene	ND		ug/kg dry	270	540	100	EPA 8260C	01/21/2019 09:52	01/21/2019 12:52	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-88-3	**Toluene**	**1500000**		ug/kg dry	27000	54000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1330-20-7	**Xylenes, Total**	**2300000**		ug/kg dry	81000	160000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,NJ			

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*96.5 %*	IS-HI	*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*110 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*174 %*	S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst

Sample Information

Client Sample ID: **SB04** **York Sample ID:** **19A0642-04**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:40 am	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
208-96-8	Acenaphthylene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
120-12-7	Anthracene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
218-01-9	Chrysene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
206-44-0	Fluoranthene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
86-73-7	Fluorene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	NELAC-NY10854,NJDEP,PADEP		
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
91-20-3	**Naphthalene**	**1500**		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
85-01-8	Phenanthrene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
129-00-0	Pyrene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*53.5 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*77.7 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*82.0 %*	*24-116*

Total Solids

Log-in Notes:

Sample Notes:

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst

Sample Information

Client Sample ID: SB04 **York Sample ID:** 19A0642-04

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:40 am	01/16/2019

Total Solids **Log-in Notes:** **Sample Notes:**

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**77.1**		%	0.100	1	SM 2540G Certifications: CTDOH	01/22/2019 11:58	01/22/2019 16:28	MAC

Sample Information

Client Sample ID: SB05 **York Sample ID:** 19A0642-05

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:00 pm	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List **Log-in Notes:** **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**57000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
108-67-8	**1,3,5-Trimethylbenzene**	**19000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
71-43-2	**Benzene**	**2400**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
100-41-4	**Ethyl Benzene**	**21000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
98-82-8	**Isopropylbenzene**	**3700**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
1634-04-4	Methyl tert-butyl ether (MTBE)	ND		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
91-20-3	**Naphthalene**	**6300**	B	ug/kg dry	220	870	100	EPA 8260C Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI	01/21/2019 09:52	01/21/2019 13:46	LLJ
104-51-8	**n-Butylbenzene**	**2700**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
103-65-1	**n-Propylbenzene**	**11000**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
95-47-6	**o-Xylene**	**32000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
179601-23-1	**p- & m- Xylenes**	**82000**		ug/kg dry	4400	8700	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
99-87-6	**p-Isopropyltoluene**	**1400**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
135-98-8	**sec-Butylbenzene**	**1600**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
98-06-6	tert-Butylbenzene	ND		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ

Sample Information

Client Sample ID: **SB05** **York Sample ID:** **19A0642-05**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:00 pm	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
108-88-3	**Toluene**	**64000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications:	01/21/2019 09:52	01/21/2019 16:02 CTDOH,NELAC-NY10854,NELAC-NY12058,PA	LLJ
1330-20-7	**Xylenes, Total**	**110000**		ug/kg dry	6500	13000	1000	EPA 8260C Certifications:	01/21/2019 09:52	01/21/2019 16:02 CTDOH,NELAC-NY10854,NELAC-NY12058,NJ	LLJ

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*88.1 %*		*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*100 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*139 %*	S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
208-96-8	Acenaphthylene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
120-12-7	Anthracene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
218-01-9	Chrysene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
206-44-0	Fluoranthene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
86-73-7	Fluorene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 NELAC-NY10854,NJDEP,PADEP	OW
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
91-20-3	**Naphthalene**	**2900**		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW

Sample Information

Client Sample ID: **SB05** **York Sample ID:** **19A0642-05**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:00 pm	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
85-01-8	Phenanthrene	ND		ug/kg dry	45	90	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:11	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
129-00-0	Pyrene	ND		ug/kg dry	45	90	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:11	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*69.5 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*80.1 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*85.1 %*	*24-116*

Total Solids

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**91.2**		%	0.100	1	SM 2540G	01/22/2019 11:58	01/22/2019 16:28	MAC
							Certifications: CTDOH			

Sample Information

Client Sample ID: **SB06** **York Sample ID:** **19A0642-06**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:20 pm	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**360000**		ug/kg dry	8900	18000	5000	EPA 8260C	01/21/2019 09:52	01/21/2019 17:50	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-67-8	**1,3,5-Trimethylbenzene**	**57000**		ug/kg dry	1800	3500	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
71-43-2	**Benzene**	**3600**	IS-HI	ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
100-41-4	**Ethyl Benzene**	**77000**		ug/kg dry	1800	3500	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-82-8	**Isopropylbenzene**	**9600**		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1634-04-4	Methyl tert-butyl ether (MTBE)	ND	IS-HI	ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
91-20-3	**Naphthalene**	**23000**	B	ug/kg dry	1800	7100	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI			

Sample Information

Client Sample ID: **SB06** **York Sample ID:** **19A0642-06**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:20 pm	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
104-51-8	**n-Butylbenzene**	**6800**		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
103-65-1	**n-Propylbenzene**	**34000**		ug/kg dry	1800	3500	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
95-47-6	**o-Xylene**	**120000**		ug/kg dry	1800	3500	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
179601-23-1	**p- & m- Xylenes**	**350000**	VOA-E	ug/kg dry	3500	7100	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
99-87-6	**p-Isopropyltoluene**	**2300**		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
135-98-8	**sec-Butylbenzene**	**3900**		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-06-6	tert-Butylbenzene	ND		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-88-3	**Toluene**	**370000**		ug/kg dry	8900	18000	5000	EPA 8260C	01/21/2019 09:52	01/21/2019 17:50	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1330-20-7	**Xylenes, Total**	**480000**	VOA-E	ug/kg dry	5300	11000	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,NJ			

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*108 %*	IS-HI	*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*103 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*139 %*	S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
208-96-8	Acenaphthylene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
120-12-7	Anthracene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			

Sample Information

Client Sample ID: **SB06** **York Sample ID:** **19A0642-06**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:20 pm	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
218-01-9	Chrysene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
206-44-0	Fluoranthene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
86-73-7	Fluorene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	NELAC-NY10854,NJDEP,PADEP		
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
91-20-3	**Naphthalene**	**120**		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
85-01-8	Phenanthrene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
129-00-0	Pyrene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*55.6 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*79.8 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*77.2 %*	*24-116*

Total Solids

Log-in Notes:

Sample Notes:

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**90.3**		%	0.100	1	SM 2540G	01/22/2019 11:58	01/22/2019 16:28	MAC
							Certifications:	CTDOH		

Volatile Analysis Sample Containers

Lab ID	Client Sample ID	Volatile Sample Container
19A0642-01	SB01	40mL Vial with Stir Bar-Cool 4° C
19A0642-02	SB02	40mL Vial with Stir Bar-Cool 4° C
19A0642-03	SB03	40mL Vial with Stir Bar-Cool 4° C
19A0642-04	SB04	40mL Vial with Stir Bar-Cool 4° C
19A0642-05	SB05	40mL Vial with Stir Bar-Cool 4° C
19A0642-06	SB06	40mL Vial with Stir Bar-Cool 4° C

Sample and Data Qualifiers Relating to This Work Order

VOA-E	The concentration reported for this analyte is an estimated value above the linear range of the instrument for EPA SW846-5035/8260 (>200ppb). Re-analysis using 5035/8260 medium level prep. resulted in a detection below the reporting limit (<500ppb).
S-03	The surrogate recovery for this sample is outside of established control limits due to a sample matrix effect. This effect was confirmed by reanalysis.
J	Detected below the Reporting Limit but greater than or equal to the Method Detection Limit (MDL/LOD) or in the case of a TIC, the result is an estimated concentration.
IS-HI	The internal std associated with this target compound did not meet acceptance criteria (area >200% CCV) at the stated dilution due to matrix effects. Sample was rerun to confirm matrix effects.
CCV-E	The value reported is ESTIMATED. The value is estimated due to its behavior during continuing calibration verification (>20% Difference for average Rf or >20% Drift for quadratic fit).
B	Analyte is found in the associated analysis batch blank. For volatiles, methylene chloride and acetone are common lab contaminants.

Definitions and Other Explanations

*	Analyte is not certified or the state of the samples origination does not offer certification for the Analyte.
ND	NOT DETECTED - the analyte is not detected at the Reported to level (LOQ/RL or LOD/MDL)
RL	REPORTING LIMIT - the minimum reportable value based upon the lowest point in the analyte calibration curve.
LOQ	LIMIT OF QUANTITATION - the minimum concentration of a target analyte that can be reported within a specified degree of confidence. This is the lowest point in an analyte calibration curve that has been subjected to all steps of the processing/analysis and verified to meet defined criteria. This is based upon NELAC 2009 Standards and applies to all analyses.
LOD	LIMIT OF DETECTION - a verified estimate of the minimum concentration of a substance in a given matrix that an analytical process can reliably detect. This is based upon NELAC 2009 Standards and applies to all analyses conducted under the auspices of EPA SW-846.
MDL	METHOD DETECTION LIMIT - a statistically derived estimate of the minimum amount of a substance an analytical system can reliably detect with a 99% confidence that the concentration of the substance is greater than zero. This is based upon 40 CFR Part 136 Appendix B and applies only to EPA 600 and 200 series methods.
Reported to	This indicates that the data for a particular analysis is reported to either the LOD/MDL, or the LOQ/RL. In cases where the "Reported to" is located above the LOD/MDL, any value between this and the LOQ represents an estimated value which is "J" flagged accordingly. This applies to volatile and semi-volatile target compounds only.
NR	Not reported
RPD	Relative Percent Difference
Wet	The data has been reported on an as-received (wet weight) basis
Low Bias	Low Bias flag indicates that the recovery of the flagged analyte is below the laboratory or regulatory lower control limit. The data user should take note that this analyte may be biased low but should evaluate multiple lines of evidence including the LCS and site-specific MS/MSD data to draw bias conclusions. In cases where no site-specific MS/MSD was requested, only the LCS data can be used to evaluate such bias.
High Bias	High Bias flag indicates that the recovery of the flagged analyte is above the laboratory or regulatory upper control limit. The data user should take note that this analyte may be biased high but should evaluate multiple lines of evidence including the LCS and site-specific MS/MSD data to draw bias conclusions. In cases where no site-specific MS/MSD was requested, only the LCS data can be used to evaluate such bias.
Non-Dir.	Non-dir. flag (Non-Directional Bias) indicates that the Relative Percent Difference (RPD) (a measure of precision) among the MS and MSD data is outside the laboratory or regulatory control limit. This alerts the data user where the MS and MSD are from site-specific samples that the RPD is high due to either non-homogeneous distribution of target analyte between the MS/MSD or indicates poor reproducibility for other reasons.

If EPA SW-846 method 8270 is included herein it is noted that the target compound N-nitrosodiphenylamine (NDPA) decomposes in the gas chromatographic inlet and cannot be separated from diphenylamine (DPA). These results could actually represent 100% DPA, 100% NDPA or some combination of the two. For this reason, York reports the combined result for n-nitrosodiphenylamine and diphenylamine for either of these compounds as a combined concentration as Diphenylamine.

If Total PCBs are detected and the target aroclors reported are "Not detected", the Total PCB value is reported due to the presence of either or both Aroclors 1262 and 1268 which are non-target aroclors for some regulatory lists.

2-chloroethylvinyl ether readily breaks down under acidic conditions. Samples that are acid preserved, including standards will exhibit breakdown. The data user should take note.

Certification for pH is no longer offered by NYDOH ELAP.

Semi-Volatile and Volatile analyses are reported down to the LOD/MDL, with values between the LOD/MDL and the LOQ being "J" flagged as estimated results.

For analyses by EPA SW-846-8270D, the Limit of Quantitation (LOQ) reported for benzidine is based upon the lowest standard used for calibration and is not a verified LOQ due to this compound's propensity for oxidative losses during extraction/concentration procedures and non-reproducible chromatographic performance.

York Analytical Laboratories, Inc.
120 Research Drive, Stratford, CT 06615 | 132-02 89th Ave, Queens, NY 11418
clientservices@yorklab.com
www.yorklab.com

Field Chain-of-Custody Record

NOTE: YORK's Standard Terms & Conditions are listed on the back side of this document.
This document serves as your written authorization for YORK to proceed with the analyses requested below.
Your signature binds you to YORK's Standard Terms & Conditions.

YORK Project No.: 19A0643

Page 1 of 1

YOUR Information	Report To:	Invoice To:	YOUR Project Number	Turn-Around Time
Company: Castleton Environmental	Company:	Company:	MEIN1901	RUSH - Next Day
Address: 54 George St Babylon, NY	Address: SAME	Address: SAME	YOUR Project Name: MEIN1901	RUSH - Two Day
Phone: 631 [illegible] 1818	Phone:	Phone:		RUSH - Three Day
Contact: Jessica Terngren	Contact:	Contact:		RUSH - Four Day
E-mail: jessica@castletonenv.com	E-mail:	E-mail:	YOUR PO#:	Standard (5-7 Day) X

Please print clearly and legibly. All information must be complete. Samples will not be logged in and the turn-around-time clock will not begin until any questions by YORK are resolved.

Samples Collected by: (print your name above and sign below)
Charles Lambert

Matrix Codes
S - soil / solid
GW - groundwater
DW - drinking water
WW - wastewater
O - Oil | Other

Samples From
New York X
New Jersey
Connecticut
Pennsylvania
Other

Report / EDD Type (circle selections)
~~Summary Report~~ | CT RCP | ~~Standard Excel EDD~~
QA Report | CT RCP DQA/DUE | EQuIS (Standard)
NY ASP A Package | NJDEP Reduced Deliverables | NYSDEC EQuIS
NY ASP B Package | NJDKQP | NJDEP SRP HazSite
Other:

YORK Reg. Comp.
Compared to the following Regulation(s): (please fill in)

Sample Identification	Sample Matrix	Date/Time Sampled	Analysis Requested	Container Description
SB01	S	1/15/19 9:50	CP-51 VOCs via 8260, CP51 SVOCs via 8270	terracore 1&1, 8oz jar
SB02		10:10		
SB03		11:00		
SB04		11:40		
SB05		12:00		
SB06		12:20		

Comments:

Preservation: (check all that apply)
HCl ___ MeOH ___ HNO_3 ___ H_2SO_4 ___ NaOH ___ ZnAc ___
Ascorbic Acid ___ Other: ___

Special Instruction
Field Filtered ___
Lab to Filter ___

Samples Relinquished by / Company	Date/Time	Samples Received by / Company
[signature]	1/16/19 8:40am	[signature]
Samples Received by / Company	Date/Time	Samples Relinquished by / Company
Samples Relinquished by / Company	Date/Time	Samples Received by / Company

Date/Time	Samples Relinquished by / Company	Date/Time
1/16/19 8:40AM		
Date/Time	Samples Received by / Company	Date/Time
Date/Time	Samples Received in LAB by / Date/Time	Temp. Received at Lab
	TC Mahl 1/16/19 1647	1.5 Degrees C

Attachment-C
Lab Data Package

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

May 13, 2020

Justin Halpin
WRS d.b.a Berninger Environmental
17 Old Dock Road
Yaphank, NY 11980
TEL: (631) 589-6521
FAX: (631) 589-6528

RE: BP Gas; 4001-4010 4th Avenue, Brooklyn, Order No.: 2005010

Dear Justin Halpin:

American Analytical Laboratories, LLC. received 2 sample(s) on 5/1/2020 for the analyses presented in the following report.

Samples were analyzed in accordance with the test procedures documented on the chain of custody and detailed throughout the text of this report. The results reported herein relate only to the items tested or to the samples as received by the laboratory. This report may not be reproduced, except in full, without the approval of American Analytical Laboratories, LLC and is not considered complete without a cover page and chain of custody documentation. The limits (LOQ) provided in the data package are analytical reporting limits and not Federal or Local mandated values to which the sample results should be compared.

There were no problems with the analyses and all data for associated QC met laboratory specifications. If there are any exceptions a Case Narrative is provided in the report or the data is qualified either on the sample results or in the QC section of the report. This package has been reviewed by American Analytical Laboratories' QA Department/Laboratory Director to comply with NELAC standards prior to report submittal.

If you have any questions regarding these tests results, please do not hesitate to call (631) 454-6100 or email me directly at lbeyer@american-analytical.com.

Sincerely,

Lori Beyer

Lori Beyer
Lab Director
American Analytical Laboratories, LLC.

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Workorder Sample Summary

WO#: **2005010**

13-May-20

CLIENT: WRS d.b.a Berninger Environmental

Project: BP Gas; 4001-4010 4th Avenue, Brooklyn, NY

Lab SampleID	Client Sample ID	Tag No	Date Collected	Date Received	Matrix
2005010-001A	B-4 @ 27.5-30'		4/29/2020 11:30:00 AM	5/1/2020 11:15:00 AM	Soil
2005010-002A	B-5 @ 30-32.5'		4/29/2020 1:00:00 PM	5/1/2020 11:15:00 AM	Soil

CHAIN OF CUSTODY

AMERICAN ANALYTICAL LABORATORIES

56 Toledo Street, Farmingdale NY 11735
(T) 631-454-6100 (F) 631-454-8027
www.american-analytical.com

CERTIFICATIONS
NY ELAP - 11418 PA DEP - 68-00573
NJ DEP - NY050 CT DOH - PH-0205

Client Information

Company Name: BEI
Address: 17 Old Dock Rd.
City: Yaphank State: NY Zip: 11980
Project Contact: Justin H.
Phone #: 631-589-6521
E-mail: jhalpin2nurses.com

Project Information

Project Name: BP Gas
Street: 4001-4010 4th Avenue
City: Brooklyn State: NY Zip:
Project # / Purchase Order #: 15487
Sampler's Name / Company: Justin H. / BEI
Sampler's Signature:

Analytical Test / Information

8260 (VOC's)

LAB SAMPLE # (LAB USE ONLY)	Sample Information: Client Sample ID	Sample Type	Matrix Code	Sample Collection: Date	Time	Glass / Plastic	Sample Containers: Total # of bottles	Number of Each Preserved Bottle: NONE	HCl	NaOH	HNO_3	H_2SO_4	DI Water (5035A)	MeOH	OTHER	8260 (VOC's)
2005010-001	B-4 @ 27.5-30'	G	S	4/29/20	11:30	G	1	X								X
002	B-5 @ 30-32.5'	G	S	↓	11:00	G	1	X								X

Turnaround Time (Business Days)

Standard
- [x] 7-10 Business Days
- [ ] 5 Day *RUSH*
- [ ] 4 Day *RUSH*
- [ ] 3 Day *RUSH*
- [ ] 2 Day *RUSH*
- [ ] 1 Day *RUSH*

Please contact laboratory for rush service availability

SAMPLE TYPE
G = Grab
C = Composite
B = Blank

MATRIX CODE
L = Liquid, PC = Paint Chip
S = Soil, SL = Sludge
O = Oil, SD = Solid
W = Wipe, M = Misc

ELECTRONIC DELIVERABLES
NYCRR Part 375 - please circle
Unres/ Comm/ Industrial/ Residential/ Res Residential/ PGW
NJ Soil Clean Up Criteria
CP 51 - Gas / Fuel
TOGS
SCDOH Action Levels
TCLP Hazardous Waste
NYSDEC EQUIS

Comments / Remarks
Rot 32/09
Cooler Temp: 2.4C

Sample custody must be documented below, each time samples change possession, with a signature, date, and time.

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME
	5/1/20 11:15	Toby Wedgwood	P Masi	5/1/20 11:15	P Masi
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Sample Log-In Check List

Client Name: Berninger Work Order Number: 2005010 RcptNo: 1

Logged by:	Lori Beyer	5/1/2020 11:15:00 AM	Lori Beyer
Completed By:	Lori Beyer	5/1/2020 11:16:32 AM	Lori Beyer
Reviewed By:	Phyllis Masi	5/4/2020	Phyllis Masi

Chain of Custody

1.	Is Chain of Custody complete?	Yes ☑	No ☐	Not Present ☐
2.	How was the sample delivered?	Client		

Log In

3.	Coolers are present?	Yes ☑	No ☐	NA ☐
4.	Shipping container/cooler in good condition?	Yes ☑	No ☐	
	Custody seals intact on shipping container/cooler?	Yes ☐	No ☐	Not Present ☑
	No. Seal Date:	Signed By:		
5.	Was an attempt made to cool the samples?	Yes ☑	No ☐	NA ☐
6.	Were all samples received at a temperature of >0° C to 6.0°C	Yes ☑	No ☐	NA ☐
7.	Sample(s) in proper container(s)?	Yes ☑	No ☐	
8.	Sufficient sample volume for indicated test(s)?	Yes ☑	No ☐	
9.	Are samples (except VOA and ONG) properly preserved?	Yes ☑	No ☐	
10.	Was preservative added to bottles?	Yes ☐	No ☑	NA ☐
11.	Is the headspace in the VOA vials less than 1/4 inch or 6 mm?	Yes ☐	No ☐	No VOA Vials ☑
12.	Were any sample containers received broken?	Yes ☐	No ☑	
13.	Does paperwork match bottle labels? (Note discrepancies on chain of custody)	Yes ☑	No ☐	
14.	Are matrices correctly identified on Chain of Custody?	Yes ☑	No ☐	
15.	Is it clear what analyses were requested?	Yes ☑	No ☐	
16.	Were all holding times able to be met? (If no, notify customer for authorization.)	Yes ☑	No ☐	

Special Handling (if applicable)

17. Was client notified of all discrepancies with this order? Yes ☐ No ☐ NA ☑

Person Notified: _____ Date: _____
By Whom: _____ Via: ☐ eMail ☐ Phone ☐ Fax ☐ In Person
Regarding: _____
Client Instructions: _____

18. Additional remarks:

Cooler Information

Cooler No	Temp ºC	Condition	Seal Intact	Seal No	Seal Date	Signed By

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Case Narrative

WO#: **2005010**
Date: **5/13/2020**

CLIENT: WRS d.b.a Berninger Environmental
Project: BP Gas; 4001-4010 4th Avenue, Brooklyn, NY

Samples were analyzed using the methods outlined in the following references:

Test Methods for Evaluating Solid Waste, Physical/Chemical Methods, SW846 and additional methods as detailed throughout the text of the report. All method blanks, laboratory spikes, and/or matrix spikes met quality assurance objectives with exceptions notated in this Narrative discussion.

Soil sample results analyzed for Volatile Organics via preparation method SW846 Method 5035A by the Low Level procedures potentially may be estimated, "J" (biased low) since the samples for this test were not collected according to the 5035A Method. Analysis was performed from intact soil jar. Volatile LCS are analyzed with preservatives - HCL/Methanol depending on level of analysis (high/low) similar to sample analysis. Outliers can be attributed to the presence of chemical preservatives. 2-Chloroethyl vinyl ether readily breaks down under acidic conditions. Samples that are acid preserved, including standards will exhibit breakdown. The data user should take note.

Sample B-4 @ 27.5-30' required reanalysis at high level due to heavy matrix interferences.

The following parameters (if included in this report) are not offered by NY ELAP: VOA 8260 Soil; 1,2,4,5-Tetramethylbenzene, Chlorodifluoromethane, Diisopropyl ether, Ethanol, Freon-114, p-Diethylbenzene, p-Ethyltoluene, Limonene. VOA 8260 Liquid; 1,2,4,5-Tetramethylbenzene, Chlorodifluoromethane, Freon-114, p-Diethylbenzene, p-Ethyltoluene, Limonene. Pesticides 8081 Soil; DBCP. Herbicides 8151 Soil; 3,5-Dichlorobenzoic Acid, 4-Nitrophenol, Acifluorfen, Bentazon, Chloramben, DCPA, Picloram, SM 2540G Total Volatile Solids, Soil TKN, Soil Organic Nitrogen, Total Phosphorus in soil, Percent Moisture, pH in non-potable water and temperature at which pH is measured, SM 4500-SO3 B Sulfite in Liquid, Total Sulfur in Soil, Acid Soluble Chloride by ASTMC1152, Water Soluble Chloride by ASTMC1218, Chlorine Demand by SM 2350 B, Total Residual Chlorine in Liquid and Reactivity to Sulfide and Reactivity to Cyanide.

The test results meet the requirements of the NYSDOH and NELAC standards, except where noted. The information contained in this analytical report is the sole property of American Analytical Laboratories, LLC. or the client for which this report was issued. The results contained in this report are only representative of the samples received. The sample receipt checklist is included as part of this lab report. Conditions can vary at different times and at different sampling conditions. American Analytical is not responsible for the use or interpretation of the data included herein.

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Definition Only

WO#: **2005010**
Date: **5/13/2020**

Definitions:

Sample Result and QC Summary Qualifiers - Level I and Level II Reports
ND - Not detected at the reporting limit/Limit of Quantitation

B - The analyte was detected in the associated method blank. For volatiles, methylene chloride and acetone are common lab contaminants. Data users should consider anything <5x the blank value as artifact.

E - The value is above the quantitation range

D - Analyte concentration was obtained from diluted analysis or from analysis using reduced sample volume.

J - The analyte was detected below the limit of quantitation but greater than the established Limit of Detection (LOD). There is greater uncertainty associated with these results and data should be considered as estimated.

U - The compound was analyzed for but not detected.

H - Holding time for preparation or analysis has been exceeded.

S - Spike recovery is outside accepted recovery limits.

R - RPD is outside accepted recovery range.

P - Secondary column exceeds 40% difference for GC test.

* - Calibration exceeds method requirement. Due to the large number of analytes for organic testing, the method allows 10% of analytes to have %RSD and/or %D to be >20%.
LOD - Limit of Detection; the lowest level the analyte can be determined to be statistically different from a blank.
LOQ - Limit of Quantitation; the lowest amount of analyte in a sample that can be quantitatively determined with suitable precision and accuracy.
PQL - Practical Quantitation Limit; the lowest level that can be reliably achieved within the specific limits of Precision and accuracy. Listed on the QC Summary Forms.
m - Analyte was manually integrated for GC/MS.
+ - Concentration exceeds regulatory level for TCLP

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-4 @ 27.5-30'
Lab Order:	2005010	**Collection Date:**	4/29/2020 11:30:00 AM
Project:	BP Gas; 4001-4010 4th Avenue, Brooklyn, NY	**Matrix:**	SOIL
Lab ID:	2005010-001A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
PERCENT MOISTURE			**D2216**				Analyst: **JaP**
Percent Moisture	10.6	0	1.00		wt%	1	5/5/2020 9:00:00 AM
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
1,1,1,2-Tetrachloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1,1-Trichloroethane	4.0	1.1	5.7	J	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1,2,2-Tetrachloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1,2-Trichloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1-Dichloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1-Dichloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1-Dichloropropene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2,3-Trichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2,3-Trichloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2,4,5-Tetramethylbenzene	5100	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
1,2,4-Trichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2,4-Trimethylbenzene	28000	280	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
1,2-Dibromo-3-chloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2-Dibromoethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2-Dichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2-Dichloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2-Dichloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,3,5-Trimethylbenzene	9600	280	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
1,3-Dichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,3-dichloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,4-Dichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,4-Dioxane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
2,2-Dichloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
2-Butanone	ND	5.7	11	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
2-Chloroethyl vinyl ether	ND	11	23	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
2-Chlorotoluene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
2-Hexanone	ND	5.7	11	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
2-Propanol	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
4-Chlorotoluene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-4 @ 27.5-30'
Lab Order:	2005010	**Collection Date:**	4/29/2020 11:30:00 AM
Project:	BP Gas; 4001-4010 4th Avenue, Brooklyn, NY	**Matrix:**	SOIL
Lab ID:	2005010-001A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
4-Isopropyltoluene	3000	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
4-Methyl-2-pentanone	ND	5.7	11	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Acetone	ND	5.7	11	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Benzene	850	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
Bromobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Bromochloromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Bromodichloromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Bromoform	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Bromomethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Carbon disulfide	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Carbon tetrachloride	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Chlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Chlorodifluoromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Chloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Chloroform	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Chloromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
cis-1,2-Dichloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
cis-1,3-Dichloropropene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Cyclohexane	8700	110	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
Dibromochloromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Dibromomethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Dichlorodifluoromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Diisopropyl ether	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Ethanol	ND	57	57	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Ethylbenzene	9500	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
Freon-114	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Hexachlorobutadiene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Isopropylbenzene	1900	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
m,p-Xylene	34000	560	2800	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
Methyl Acetate	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Methyl tert-butyl ether	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Methylene chloride	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
n-Butylbenzene	2400	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-4 @ 27.5-30'
Lab Order:	2005010	**Collection Date:**	4/29/2020 11:30:00 AM
Project:	BP Gas; 4001-4010 4th Avenue, Brooklyn, NY	**Matrix:**	SOIL
Lab ID:	2005010-001A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
n-Propylbenzene	10000	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
Naphthalene	210	1.1	5.7		µg/Kg-dry	1	5/7/2020 7:10:00 AM
o-Xylene	13000	280	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
p-Diethylbenzene	10000	280	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
p-Ethyltoluene	21000	280	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
sec-Butylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Styrene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
t-Butyl alcohol	ND	2.9	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
tert-Butylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Tetrachloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Toluene	17000	280	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
trans-1,2-Dichloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
trans-1,3-Dichloropropene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Trichloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Trichlorofluoromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Vinyl acetate	210	1.1	5.7		µg/Kg-dry	1	5/7/2020 7:10:00 AM
Vinyl chloride	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Xylenes, Total	47000	850	4200	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
Methylcyclohexane	29000	560	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
Acrolein	ND	14	29	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Acrylonitrile	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-5 @ 30-32.5'
Lab Order:	2005010	**Collection Date:**	4/29/2020 1:00:00 PM
Project:	BP Gas; 4001-4010 4th Avenue, Brooklyn, NY	**Matrix:**	SOIL
Lab ID:	2005010-002A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
PERCENT MOISTURE			**D2216**				Analyst: **JaP**
Percent Moisture	10.2	0	1.00		wt%	1	5/5/2020 9:00:00 AM
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
1,1,1,2-Tetrachloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1,1-Trichloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1,2,2-Tetrachloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1,2-Trichloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1-Dichloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1-Dichloroethene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1-Dichloropropene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2,3-Trichlorobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2,3-Trichloropropane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2,4,5-Tetramethylbenzene	1.7	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2,4-Trichlorobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2,4-Trimethylbenzene	13	1.1	5.6		µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2-Dibromo-3-chloropropane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2-Dibromoethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2-Dichlorobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2-Dichloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2-Dichloropropane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,3,5-Trimethylbenzene	2.6	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,3-Dichlorobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,3-dichloropropane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,4-Dichlorobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,4-Dioxane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
2,2-Dichloropropane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
2-Butanone	ND	5.6	11	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
2-Chloroethyl vinyl ether	ND	11	22	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
2-Chlorotoluene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
2-Hexanone	ND	5.6	11	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
2-Propanol	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
4-Chlorotoluene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM

American Analytical Laboratories, LLC.

Date: *13-May-20*

ELAP ID : 11418

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-5 @ 30-32.5'
Lab Order:	2005010	**Collection Date:**	4/29/2020 1:00:00 PM
Project:	BP Gas; 4001-4010 4th Avenue, Brooklyn, NY	**Matrix:**	SOIL
Lab ID:	2005010-002A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
4-Isopropyltoluene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
4-Methyl-2-pentanone	ND	5.6	11	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Acetone	19	5.6	11		µg/Kg-dry	1	5/7/2020 3:08:00 PM
Benzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Bromobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Bromochloromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Bromodichloromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Bromoform	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Bromomethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Carbon disulfide	2.3	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Carbon tetrachloride	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Chlorobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Chlorodifluoromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Chloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Chloroform	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Chloromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
cis-1,2-Dichloroethene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
cis-1,3-Dichloropropene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Cyclohexane	ND	2.2	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Dibromochloromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Dibromomethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Dichlorodifluoromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Diisopropyl ether	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Ethanol	ND	56	56	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Ethylbenzene	2.3	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Freon-114	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Hexachlorobutadiene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Isopropylbenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
m,p-Xylene	9.6	2.2	11	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Methyl Acetate	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Methyl tert-butyl ether	30	1.1	5.6		µg/Kg-dry	1	5/7/2020 3:08:00 PM
Methylene chloride	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
n-Butylbenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM

American Analytical Laboratories, LLC.

Date: *13-May-20*

ELAP ID : 11418

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-5 @ 30-32.5'
Lab Order:	2005010	**Collection Date:**	4/29/2020 1:00:00 PM
Project:	BP Gas; 4001-4010 4th Avenue, Brooklyn, NY	**Matrix:**	SOIL
Lab ID:	2005010-002A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
n-Propylbenzene	1.6	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Naphthalene	9.9	1.1	5.6		µg/Kg-dry	1	5/7/2020 3:08:00 PM
o-Xylene	6.0	1.1	5.6		µg/Kg-dry	1	5/7/2020 3:08:00 PM
p-Diethylbenzene	2.3	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
p-Ethyltoluene	7.7	1.1	5.6		µg/Kg-dry	1	5/7/2020 3:08:00 PM
sec-Butylbenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Styrene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
t-Butyl alcohol	ND	2.8	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
tert-Butylbenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Tetrachloroethene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Toluene	5.4	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
trans-1,2-Dichloroethene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
trans-1,3-Dichloropropene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Trichloroethene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Trichlorofluoromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Vinyl acetate	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Vinyl chloride	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Xylenes, Total	16	3.4	17	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Methylcyclohexane	ND	2.2	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Acrolein	ND	14	28	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Acrylonitrile	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM

Table-1
Tabulated Soil Data

American Analytical Laboratories, LLC. 2005010
WorkOrder: 2005010
Client: WRS d.b.a Berninger Environmental
Project: BP Gas; 4001-4010 4th Avenue, Brooklyn, NY

		Client Sample ID:		B-4 @ 27.5-30'		B-5 @ 30-32.5'		DEC Part 375	DEC Part 375
		Laboratory ID:		2005010-001		2005010-002		Unrestricted Use/	Restricted
		Sampling Date:		04/29/2020		04/29/2020		*-CP-51 Protection	Residential
Cas #:	Procedure:	Analyte:	Units:		Q		Q	of GW / Eco Res.	
E-11870	PERCENT MOISTURE	Percent Moisture	wt%	10.6		10.2		NA	NA
630-20-6	VOLATILE SW-846 METHOD 8260D	1,1,1,2-Tetrachloroethane	PPB	1.1	U	1.1	U	NA	NA
71-55-6	VOLATILE SW-846 METHOD 8260D	1,1,1-Trichloroethane	PPB	4.0	J	1.1	U	680	100,000
79-34-5	VOLATILE SW-846 METHOD 8260D	1,1,2,2-Tetrachloroethane	PPB	1.1	U	1.1	U	600*	NA
76-13-1	VOLATILE SW-846 METHOD 8260D	1,1,2-Trichloro-1,2,2-trifluoroethane	PPB	1.1	U	1.1	U	NA	NA
79-00-5	VOLATILE SW-846 METHOD 8260D	1,1,2-Trichloroethane	PPB	1.1	U	1.1	U	NA	NA
75-34-3	VOLATILE SW-846 METHOD 8260D	1,1-Dichloroethane	PPB	1.1	U	1.1	U	270	26,000
75-35-4	VOLATILE SW-846 METHOD 8260D	1,1-Dichloroethene	PPB	1.1	U	1.1	U	330	100,000
563-58-6	VOLATILE SW-846 METHOD 8260D	1,1-Dichloropropene	PPB	1.1	U	1.1	U	NA	NA
87-61-6	VOLATILE SW-846 METHOD 8260D	1,2,3-Trichlorobenzene	PPB	1.1	U	1.1	U	20,000*	NA
96-18-4	VOLATILE SW-846 METHOD 8260D	1,2,3-Trichloropropane	PPB	1.1	U	1.1	U	340*	NA
95-93-2	VOLATILE SW-846 METHOD 8260D	1,2,4,5-Tetramethylbenzene	PPB	5100	D	1.7	J	NA	NA
120-82-1	VOLATILE SW-846 METHOD 8260D	1,2,4-Trichlorobenzene	PPB	1.1	U	1.1	U	3,400*	NA
95-63-6	VOLATILE SW-846 METHOD 8260D	**1,2,4-Trimethylbenzene**	PPB	28000	D	13		*3,600*	52,000
96-12-8	VOLATILE SW-846 METHOD 8260D	1,2-Dibromo-3-chloropropane	PPB	1.1	U	1.1	U	NA	NA
106-93-4	VOLATILE SW-846 METHOD 8260D	1,2-Dibromoethane	PPB	1.1	U	1.1	U	NA	NA
95-50-1	VOLATILE SW-846 METHOD 8260D	1,2-Dichlorobenzene	PPB	1.1	U	1.1	U	1,100	100,000
107-06-2	VOLATILE SW-846 METHOD 8260D	1,2-Dichloroethane	PPB	1.1	U	1.1	U	20	3,100
78-87-5	VOLATILE SW-846 METHOD 8260D	1,2-Dichloropropane	PPB	1.1	U	1.1	U	700,000*	NA
108-67-8	VOLATILE SW-846 METHOD 8260D	**1,3,5-Trimethylbenzene**	PPB	9600	D	2.6	J	*8,400*	52,000
541-73-1	VOLATILE SW-846 METHOD 8260D	1,3-Dichlorobenzene	PPB	1.1	U	1.1	U	2,400	49,000
142-28-9	VOLATILE SW-846 METHOD 8260D	1,3-dichloropropane	PPB	1.1	U	1.1	U	300*	NA
106-46-7	VOLATILE SW-846 METHOD 8260D	1,4-Dichlorobenzene	PPB	1.1	U	1.1	U	1,800	13,000
123-91-1	VOLATILE SW-846 METHOD 8260D	1,4-Dioxane	PPB	1.1	U	1.1	U	100	13,000
594-20-7	VOLATILE SW-846 METHOD 8260D	2,2-Dichloropropane	PPB	1.1	U	1.1	U	NA	NA
78-93-3	VOLATILE SW-846 METHOD 8260D	2-Butanone	PPB	5.7	U	5.6	U	300*	NA
110-75-8	VOLATILE SW-846 METHOD 8260D	2-Chloroethyl vinyl ether	PPB	11	U	11	U	NA	NA
95-49-8	VOLATILE SW-846 METHOD 8260D	2-Chlorotoluene	PPB	1.1	U	1.1	U	NA	NA
591-78-6	VOLATILE SW-846 METHOD 8260D	2-Hexanone	PPB	5.7	U	5.6	U	NA	NA
67-63-0	VOLATILE SW-846 METHOD 8260D	2-Propanol	PPB	1.1	U	1.1	U	NA	NA
106-43-4	VOLATILE SW-846 METHOD 8260D	4-Chlorotoluene	PPB	1.1	U	1.1	U	NA	NA
99-87-6	VOLATILE SW-846 METHOD 8260D	4-Isopropyltoluene	PPB	3000	D	1.1	U	10,000	NA
108-10-1	VOLATILE SW-846 METHOD 8260D	4-Methyl-2-pentanone	PPB	5.7	U	5.6	U	100*	NA
67-64-1	VOLATILE SW-846 METHOD 8260D	Acetone	PPB	5.7	U	19		50	100,000
71-43-2	VOLATILE SW-846 METHOD 8260D	**Benzene**	PPB	850	D	1.1	U	*60*	4,800
108-86-1	VOLATILE SW-846 METHOD 8260D	Bromobenzene	PPB	1.1	U	1.1	U	NA	NA
74-97-5	VOLATILE SW-846 METHOD 8260D	Bromochloromethane	PPB	1.1	U	1.1	U	NA	NA
75-27-4	VOLATILE SW-846 METHOD 8260D	Bromodichloromethane	PPB	1.1	U	1.1	U	NA	NA
75-25-2	VOLATILE SW-846 METHOD 8260D	Bromoform	PPB	1.1	U	1.1	U	NA	NA
74-83-9	VOLATILE SW-846 METHOD 8260D	Bromomethane	PPB	1.1	U	1.1	U	NA	NA
75-15-0	VOLATILE SW-846 METHOD 8260D	Carbon disulfide	PPB	1.1	U	2.3	J	2,700*	NA
56-23-5	VOLATILE SW-846 METHOD 8260D	Carbon tetrachloride	PPB	1.1	U	1.1	U	760	2,400
108-90-7	VOLATILE SW-846 METHOD 8260D	Chlorobenzene	PPB	1.1	U	1.1	U	1,100	100,000
75-45-6	VOLATILE SW-846 METHOD 8260D	Chlorodifluoromethane	PPB	1.1	U	1.1	U	NA	NA
75-00-3	VOLATILE SW-846 METHOD 8260D	Chloroethane	PPB	1.1	U	1.1	U	NA	NA
67-66-3	VOLATILE SW-846 METHOD 8260D	Chloroform	PPB	1.1	U	1.1	U	370	49,000
74-87-3	VOLATILE SW-846 METHOD 8260D	Chloromethane	PPB	1.1	U	1.1	U	NA	NA
156-59-2	VOLATILE SW-846 METHOD 8260D	cis-1,2-Dichloroethene	PPB	1.1	U	1.1	U	250	100,000
10061-01-5	VOLATILE SW-846 METHOD 8260D	cis-1,3-Dichloropropene	PPB	1.1	U	1.1	U	NA	NA
110-82-7	VOLATILE SW-846 METHOD 8260D	Cyclohexane	PPB	8700	D	2.2	U	NA	NA
124-48-1	VOLATILE SW-846 METHOD 8260D	Dibromochloromethane	PPB	1.1	U	1.1	U	10,000*	NA
74-95-3	VOLATILE SW-846 METHOD 8260D	Dibromomethane	PPB	1.1	U	1.1	U	NA	NA
75-71-8	VOLATILE SW-846 METHOD 8260D	Dichlorodifluoromethane	PPB	1.1	U	1.1	U	NA	NA
108-20-3	VOLATILE SW-846 METHOD 8260D	Diisopropyl ether	PPB	1.1	U	1.1	U	NA	NA
64-17-5	VOLATILE SW-846 METHOD 8260D	Ethanol	PPB	57	U	56	U	NA	NA
100-41-4	VOLATILE SW-846 METHOD 8260D	**Ethylbenzene**	PPB	9500	D	2.3	J	*1,000*	41,000
76-14-2	VOLATILE SW-846 METHOD 8260D	Freon-114	PPB	1.1	U	1.1	U	NA	NA
87-68-3	VOLATILE SW-846 METHOD 8260D	Hexachlorobutadiene	PPB	1.1	U	1.1	U	NA	NA
98-82-8	VOLATILE SW-846 METHOD 8260D	Isopropylbenzene	PPB	1900	D	1.1	U	2,300	NA
179601-23-	VOLATILE SW-846 METHOD 8260D	**m,p-Xylene**	PPB	34000	D	9.6	J	*260*	100,000
79-20-9	VOLATILE SW-846 METHOD 8260D	Methyl Acetate	PPB	1.1	U	1.1	U	NA	NA
1634-04-4	VOLATILE SW-846 METHOD 8260D	Methyl tert-butyl ether	PPB	1.1	U	30		930	100,000
75-09-2	VOLATILE SW-846 METHOD 8260D	Methylene chloride	PPB	1.1	U	1.1	U	50	100,000
104-51-8	VOLATILE SW-846 METHOD 8260D	n-Butylbenzene	PPB	2400	D	1.1	U	12,000	NA
103-65-1	VOLATILE SW-846 METHOD 8260D	**n-Propylbenzene**	PPB	10000	D	1.6	J	*3,900*	100,000
91-20-3	VOLATILE SW-846 METHOD 8260D	Naphthalene	PPB	210		9.9		12,000	NA
95-47-6	VOLATILE SW-846 METHOD 8260D	**o-Xylene**	PPB	13000	D	6.0		*260*	100,000
105-05-5	VOLATILE SW-846 METHOD 8260D	p-Diethylbenzene	PPB	10000	D	2.3	J	NA	NA
622-96-8	VOLATILE SW-846 METHOD 8260D	p-Ethyltoluene	PPB	21000	D	7.7		NA	NA
135-98-8	VOLATILE SW-846 METHOD 8260D	sec-Butylbenzene	PPB	1.1	U	1.1	U	11,000	100,000
100-42-5	VOLATILE SW-846 METHOD 8260D	Styrene	PPB	1.1	U	1.1	U	300,000*	NA
75-65-0	VOLATILE SW-846 METHOD 8260D	t-Butyl alcohol	PPB	2.9	U	2.8	U	NA	NA
98-06-6	VOLATILE SW-846 METHOD 8260D	tert-Butylbenzene	PPB	1.1	U	1.1	U	5,900	100,000
127-18-4	VOLATILE SW-846 METHOD 8260D	Tetrachloroethene	PPB	1.1	U	1.1	U	1,300	19,000
108-88-3	VOLATILE SW-846 METHOD 8260D	**Toluene**	PPB	17000	D	5.4	J	*700*	100,000
156-60-5	VOLATILE SW-846 METHOD 8260D	trans-1,2-Dichloroethene	PPB	1.1	U	1.1	U	190	100,000
10061-02-6	VOLATILE SW-846 METHOD 8260D	trans-1,3-Dichloropropene	PPB	1.1	U	1.1	U	NA	NA
79-01-6	VOLATILE SW-846 METHOD 8260D	Trichloroethene	PPB	1.1	U	1.1	U	470	21,000
75-69-4	VOLATILE SW-846 METHOD 8260D	Trichlorofluoromethane	PPB	1.1	U	1.1	U	NA	NA
108-05-4	VOLATILE SW-846 METHOD 8260D	Vinyl acetate	PPB	210		1.1	U	NA	NA
75-01-4	VOLATILE SW-846 METHOD 8260D	Vinyl chloride	PPB	1.1	U	1.1	U	20	900
108-87-2	VOLATILE SW-846 METHOD 8260D	Methylcyclohexane	PPB	29000	D	2.2	U	NA	NA
107-02-8	VOLATILE SW-846 METHOD 8260D	Acrolein	PPB	14	U	14	U	NA	NA
107-13-1	VOLATILE SW-846 METHOD 8260D	Acrylonitrile	PPB	1.1	U	1.1	U	NA	NA

BP SERVICE STATION
4001-4010 4TH AVENUE
BROOKLYN, NEW YORK
SPILL # 18-11146

Supplemental Investigation
Soil and Groundwater Report

Prepared for:
NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
REGION II
LONG ISLAND CITY
NEW YORK

NEW YORK STATE OF OPPORTUNITY | Department of Environmental Conservation

PREPARED BY:

BERNINGER ENVIRONMENTAL
17 OLD DOCK ROAD
YAPHANK, NEW YORK 11980

BEi

October 2021

Table of Contents

INTRODUCTION **(1)**

SCOPE OF WORK **(1)**

SOIL PROFILING AND RESULTS **(2)**

MONITORING WELL INSTALLATION **(2)**

GROUNDWATER SAMPLING RESULTS **(2)**

CONCLUSION **(3)**

FIGURES

Figure-1 - Site Location

Figure-2 - Sampling Location Map

Figure-3a and b - Soil Lithology/Well Log

ATTACHMENTS

Attachment-A - Photo Log

Attachment-B - Lab Data Package

Attachment-C - Investigation Derived Waste (IDW) Manifest

TABLES

Table-1 - Soil Tabulated Data

Table-2 - Groundwater Tabulated Data

Berninger Environmental
groundwater consultants, geologists and scientists
17 Old Dock Road
Yaphank • New York • 11980 **Phone: 631 • 589 • 6521**
A WRS Environmental Services Company **Fax: 631 • 589 • 6528**

October 8th, 2021

Mr. Jonathan Kolleeny
Professional Geologist 1-Region 2
Division of Environmental Remediation
47-40 21st Street
Long Island City, NY 11101

Re: BP Service Station
4001 4th Avenue (and 40th St)
Brooklyn, New York

Groundwater Investigation
Soil Profiling Report
Spill # 1811146

Dear Mr. Kolleeny,

Introduction

The following is an Investigation Report for the subject site based on the approved Work Plan, which proposed soil and groundwater sampling. The purpose of the investigation was to vertically delineate soil contamination, analyze groundwater and install a monitoring well. Please read below for the results of the investigation work and monitoring well construction details. Please see Figure-1 for the site location.

Scope of Work

The proposed scope of work involved analyzing groundwater conditions in the area of the highest soil contamination based on our June 2020 Report. The Report indicated that elevated levels of VOC contamination was present at the highest concentrations at the B-4 location, which is located down gradient from the pump islands and USTs. Prior collection of groundwater was not feasible based on the multiple refusals encountered at the 30' depth with the Geoprobe direct push rig (note a possible rock strata located at this depth preventing advancement of direct push equipment). The depth to water in this area is depicted on the USGS "Depth to Water Viewer" 2013 as being in the 50' below grade surface range (bgs). The multiple refusals encountered at the 30' mark and failure to reach the target depth of 50' bgs prompted the use of an air rotary drill rig to reach the target depth. Soil profiling (vertical delineation), screening and sampling of the groundwater via a permanent monitoring well installation was the main objective of the investigation work. The investigation work was conducted on June 10, 2021. Figure-2 depicts the sampling and well location. A photo log is included as Attachment-A.

Soil Profiling and Results

Soil was collected using the duel tube sampling method and soil was screened in 2.5' intervals with a photo ionization detector (PID meter) in order to field screen for the presence of gasoline range volatile organic compounds (VOCs). Soil profiling was conducted from approximately twenty (20') bgs to sixty-five (65') as soil was never previously delineated beyond a depth of thirty (30') feet bgs. Soil mainly consisted of brown silty sand, semi tight with a perched water layer observed at approximately thirty feet (30') below grade. Clayey soils were observed at the 30-35' depth followed by silty sands past 35' with silty loam extending from 50'- 65'. PID readings were highest at the 30'-32.5' mark (1,000 ppm); steadily decreasing with depth before reaching 0.0 from 50'-65'. Soil conditions were logged for various characteristics based on the American Geologist Institute for soil classification.

A soil sample (B-6) from selected interval 45'-50' was submitted for lab analysis in an ice filled cooler to a New York State ELAP certified laboratory for testing via EPA method 8260 (VOCs). The PID reading at this location was approximately 9.0 ppm. Lab results did not indicate any levels of contamination above the New York State Part-375 SOC's. Mostly all constituents analyzed for had non-detect readings. Please see Figure-3a (initial boring conducted to 30') and Figure-3b for the soil lithology log from 30'-65'. Please refer to Table-1 for tabulated soil data and Attachment-B for the lab data package. All soil cutting and liquid was properly drummed and disposed of by Clean Earth. The waste manifest for the investigation derived waste is included as Attachment-C.

Monitoring Well Installation

In order to obtain groundwater samples from this area a permanent groundwater monitoring well (MW-1) was installed. Groundwater was originally anticipated to be in the 50' range but was encountered at approximately 35' bgs. The soil was only in fact saturated from a depth of 35'-40' and observed to be dry from 40'-65'. A permanent monitoring well was installed and includes the following specifications: twenty feet (20') of schedule 40, 2" PVC slot screen (0.02" slot) with thirty feet (30') of schedule 40, 2" PVC riser to grade surface. The total depth of the well is approximately fifty feet (50') to the bottom. The area surrounding the well screen was gravel packed extending to two feet (2') above the well screen and a bentonite grout mix was installed to seal the casing at the top of the gravel pack to one foot (1') below the top of the riser pipe. The top of the well is secured with a j-plug and finished at grade with a flush mounted, five inch (5") cast iron bolt down manhole, cement sealed at the surface. Please refer to Figure-3a and b for well construction details.

Groundwater Sampling Results

The newly installed monitoring well (MW-1) was developed days after its installation and adequately purged of 3-5 well volumes and containerized in laboratory approved glassware. The sample was procured by using the manual oscillation method with clean 3/8" poly-tubing affixed with a check valve sampling device. The samples were transported under a chain of custody to a New York State

ELAP certified laboratory for testing of Volatile Organic Compounds (VOCs) via EPA method 8260. Please see Table-2 for groundwater results compared to NYS TOGS standards.

Conclusion

The results of the soil investigation indicate that elevated contamination exists to a depth of approximately thirty five feet (35') below grade with PID readings of 700 ppm at this depth. Beyond 35' PID readings drastically decreased to 200 ppm to 0.0 from 50'-65'. No evidence of groundwater from 40'-65' with only a 10' zone of perched water from 30'-40'. Soil was delineated at a depth of 40'-45' with no constituents detected above the Part-375 SCOs'. The site has plans to be re-developed at which any suspect tanks and soil contamination can be easily excavated and transported for proper disposal. Any questions or comments regarding this Report can be directed to BEI.

Sincerely,
Berninger Environmental

Justin Halpin
Scientist/Project Manager

enc. Figure-1 site location
Figure-2 sample locations
Figure-3a and b soil lithology and monitoring well log.
Attachment-A Photo log
Attachment-B Lab Data Package
Attachment-C IDW manifest
Table-1 Soil tabulated data
Table-2 Groundwater tabulated data

FIGURES




Figure-1
Site Location
Brooklyn, NY



Site Map
Soil Sampling and Well Location
Figure-2

BP Service Station
4001-4010 4th Avenue
Brooklyn, NY

BEi Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980


LOG OF BORING: B-4

PROJECT: BP 4th Ave Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

DEPTH	GRAPHIC	BORING LOCATION: B-4 (former B-6)	PID (ppm)	Recov.%	AGI Sym		
		GROUND SURFACE					
FT 0		10YR-6/4; Light yellowish brown silty fine sand trace gravel, strong odor	38.7	80	SM		
2.5		10YR-6/4; Light yellowish brown silty fine sand trace gravel, strong odor	38.7	80	SM		
5		10YR-5/3; Brown silty fine sand, trace gravel, strong odor	25.0	80	SM		
7.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	25.0	80	SM		
10		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	199	80	SM		
12.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	199	80	SM		
15		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	4500	80	SM		
17.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	4500	80	SM		
20		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	4250	80	SM		
22.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	4250	80	SM		
25		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	900	80	SM		
27.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor; bedrock fragments	500	80	SM		
30		Refusal at 30.0'					
32.5							

SUBSURFACE PROFILE — SAMPLE

WELL DETAILS



Notes: Refusal at 30.0'
Sampling: B-4 Collected at 27.5'-30.0'

please see Figure-3b for log continued

FIGURE: 3a
METHOD: Direct Push
BORING COMPANY: BEI

April 29, 2020

HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980


LOG OF BORING: B-4

PROJECT: BP 4th Ave Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

SUBSURFACE PROFILE | SAMPLE

DEPTH	GRAPHIC	BORING LOCATION: B-4 (former B-6) cont...	PID (ppm)	Recov.%	AGI Sym		
FT 30		10YR-5/3; Brown silty fine sand, loose strong odor; wet	1000	80	SM		
32.5		10YR-5/3; Brown silty fine sand, loose strong odor; wet	700	80	SM		
35		10YR-5/3; Brown silt/ clay mix; tight mild odor; wet	200	80	CL		
37.5		10YR-5/3; Brown silt/ clay mix; tight mild odor; wet	150	80	CL		
40		10YR-5/3; Brown silty loam; tight mild odor; dry	50	80	SM		
42.5		10YR-5/3; Brown silty loam; tight mild odor; dry	45	80	SM		
45		10YR-5/3; Brown sand/silt/ clay mix; tight mild odor; dry	9	80	SM		
47.5		10YR-5/3; Brown sand/silt/ clay mix; tight mild odor; dry	5	80	SM		
50		10YR-5/3; Brown; silty loam; tight no odor; dry	0	80	SM		
52.5		10YR-5/3; Brown; silty loam; tight no odor; dry	0	80	SM		
55		10YR-5/3; Brown; silty loam; tight no odor; dry	0	80	SM		
57.5		10YR-5/3; Brown; silty loam; tight no odor; dry	0	80	SM		
60		10YR-5/3; Brown; silty loam; tight no odor; dry	0	80	SM		
62.5'		10YR-5/3; Brown sand/silt/ clay mix; tight no odor; dry	0	80	SM		
65							

WELL DETAILS



Notes:

Boring end at 65'

Sampling: B-4 (B-6) Collected at 45-50'

FIGURE: 3b
METHOD: Direct Push
BORING COMPANY: BEI

June 10, 2021

HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Attachments

Attachment-A
Photo Log


Invigorate
Save instantly
with BPme Rewards
BP diesel
3.99
IPOTLE
EXIT
NO STOP Anytime





Attachment-B
Lab Data Package

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

June 21, 2021

Justin Halpin
WRS d.b.a Berninger Environmental
17 Old Dock Road
Yaphank, NY 11980
TEL: (631) 589-6521
FAX: (631) 589-6528

RE: BP Gas Station, 4001-4010 4th Ave, Brookl Order No.: 2106083

Dear Justin Halpin:

American Analytical Laboratories, LLC. received 2 sample(s) on 6/14/2021 for the analyses presented in the following report.

Samples were analyzed in accordance with the test procedures documented on the chain of custody and detailed throughout the text of this report. The results reported herein relate only to the items tested or to the samples as received by the laboratory. This report may not be reproduced, except in full, without the approval of American Analytical Laboratories, LLC and is not considered complete without a cover page and chain of custody documentation. The limits (LOQ) provided in the data package are analytical reporting limits and not Federal or Local mandated values to which the sample results should be compared.

There were no problems with the analyses and all data for associated QC met laboratory specifications. If there are any exceptions a Case Narrative is provided in the report or the data is qualified either on the sample results or in the QC section of the report. This package has been reviewed by American Analytical Laboratories' QA Department/Laboratory Director to comply with NELAC standards prior to report submittal.

If you have any questions regarding these tests results, please do not hesitate to call (631) 454-6100 or email me directly at lbeyer@american-analytical.com.

Sincerely,

Lori Beyer

Lori Beyer
Lab Director
American Analytical Laboratories, LLC.

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Workorder Sample Summary

WO#: **2106083**

21-Jun-21

CLIENT: WRS d.b.a Berninger Environmental

Project: BP Gas Station, 4001-4010 4th Ave, Brooklyn,

Lab SampleID	Client Sample ID	Tag No	Date Collected	Date Received	Matrix
2106083-001A	B-6 @ 45'-50'		6/10/2021 11:00:00 AM	6/14/2021 1:00:00 PM	Soil
2106083-002A	MW-1		6/14/2021 10:00:00 AM	6/14/2021 1:00:00 PM	Liquid

CHAIN OF CUSTODY

AMERICAN ANALYTICAL LABORATORIES

56 Toledo Street, Farmingdale NY 11735
(T) 631-454-6100 (F) 631-454-8027
www.american-analytical.com

CERTIFICATIONS
NY ELAP - 11418 PA DEP - 68-00573
NJ DEP - NY050 CT DOH - PH-0205

Client Information

Company Name: BEi
Address: 17 Old Dock Rd.
City: Yaphank State: NY Zip: 11980
Project Contact: Justin H.
Phone #: 631-589-6521
E-mail: jhalpin@bei-ses.com

Project Information

Project Name: BP Gas Station
Street: 4001-4010 4th Ave.
City: Brooklyn State: NY Zip:
Project # / Purchase Order #: 16485
Sampler's Name / Company: Justin H / BEi
Sampler's Signature:

Analytical Test / Information

8260 (VOCs)

LAB SAMPLE # (LAB USE ONLY)	Client Sample ID	Sample Type	Matrix Code	Date	Time	Glass / Plastic	Total # of bottles	Sample Containers: Number of Each Preserved Bottle: NONE	HCl	NaOH	HNO_3	H_2SO_4	DI Water (5035A)	MeOH	OTHER	8260 (VOCs)
2106083-001A	B-6045-50'	G	S	6/10/21	11:00	G	1	X								X
002A	MW-1	G	L	6/14/21	10:00	G	2		X							X

Turnaround Time (Business Days)

- [x] Standard 7-10 Business Days
- [ ] 5 Day *RUSH*
- [ ] 4 Day *RUSH*
- [ ] 3 Day *RUSH*
- [ ] 2 Day *RUSH*
- [ ] 1 Day *RUSH*

Please contact laboratory for rush service availability

SAMPLE TYPE: G = Grab; C = Composite; B = Blank

MATRIX CODE: L = Liquid; S = Soil; O = Oil; W = Wipe; PC = Paint Chip; SL = Sludge; SD = Solid; M = Misc

ELECTRONIC DELIVERABLES

NYCRR Part 375 - please circle
Unres/ Comm/ Industrial/ Residential/ Res Residential/ PGW
NJ Soil Clean Up Criteria
CP 51 - Gas / Fuel
TOGS
SCDOH Action Levels
TCLP Hazardous Waste
NYSDEC EQUIS

Comments / Remarks

PO# 34325

Cooler Temp: 4°C

Sample custody must be documented below, each time samples change possession, with a signature, date, and time.

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME
	DATE 6-14-21 TIME 1:00 PM	Steven Polin	Phyllis Masi	DATE 6/14/21 TIME 1300	Phyllis Masi
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Sample Log-In Check List

Client Name: Berninger Work Order Number: 2106083 RcptNo: 1

Logged by:	Jenny Mullady	6/14/2021 1:00:00 PM	Jennifer Mullady
Completed By:	Jenny Mullady	6/14/2021 1:21:54 PM	Jennifer Mullady
Reviewed By:	Phyllis Masi	6/14/2021	Phyllis Masi

Chain of Custody

1.	Is Chain of Custody complete?	Yes ☑	No ☐	Not Present ☐
2.	How was the sample delivered?	Client		

Log In

3.	Coolers are present?	Yes ☑	No ☐	NA ☐
4.	Shipping container/cooler in good condition?	Yes ☑	No ☐	
	Custody seals intact on shipping container/cooler?	Yes ☐	No ☐	Not Present ☑
	No. Seal Date:	Signed By:		
5.	Was an attempt made to cool the samples?	Yes ☑	No ☐	NA ☐
6.	Were all samples received at a temperature of >0° C to 6.0°C	Yes ☑	No ☐	NA ☐
7.	Sample(s) in proper container(s)?	Yes ☑	No ☐	
8.	Sufficient sample volume for indicated test(s)?	Yes ☑	No ☐	
9.	Are samples (except VOA and ONG) properly preserved?	Yes ☑	No ☐	
10.	Was preservative added to bottles?	Yes ☐	No ☑	NA ☐
11.	Is the headspace in the VOA vials less than 1/4 inch or 6 mm?	Yes ☑	No ☐	No VOA Vials ☐
12.	Were any sample containers received broken?	Yes ☐	No ☑	
13.	Does paperwork match bottle labels? (Note discrepancies on chain of custody)	Yes ☑	No ☐	
14.	Are matrices correctly identified on Chain of Custody?	Yes ☑	No ☐	
15.	Is it clear what analyses were requested?	Yes ☑	No ☐	
16.	Were all holding times able to be met? (If no, notify customer for authorization.)	Yes ☑	No ☐	

Special Handling (if applicable)

17.	Was client notified of all discrepancies with this order?	Yes ☐	No ☐	NA ☑

Person Notified: _____ Date: _____
By Whom: _____ Via: ☐ eMail ☐ Phone ☐ Fax ☐ In Person
Regarding: _____
Client Instructions: _____

18. Additional remarks:

volatile sample collected in 4 oz jar with zero headspace

Cooler Information

Cooler No	Temp ºC	Condition	Seal Intact	Seal No	Seal Date	Signed By

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Case Narrative

WO#: **2106083**
Date: **6/21/2021**

CLIENT: WRS d.b.a Berninger Environmental
Project: BP Gas Station, 4001-4010 4th Ave, Brooklyn,

Samples were analyzed using the methods outlined in the following references:

Test Methods for Evaluating Solid Waste, Physical/Chemical Methods, SW846 and additional methods as detailed throughout the text of the report. All method blanks, laboratory spikes, and/or matrix spikes met quality assurance objectives with exceptions notated in this Narrative discussion.

Soil sample results analyzed for Volatile Organics via preparation method SW846 Method 5035A by the Low Level procedures potentially may be estimated, "J" (biased low) since the samples for this test were not collected according to the 5035A Method. Analysis was performed from intact soil jar. Volatile LCS are analyzed with preservatives - HCL/Methanol depending on level of analysis (high/low) similar to sample analysis. Outliers can be attributed to the presence of chemical preservatives. 2-Chloroethyl vinyl ether readily breaks down under acidic conditions. Samples that are acid preserved, including standards will exhibit breakdown. The data user should take note.

Samples were analyzed at the dilutions notated on the reporting forms. MW-1 was analyzed three times. Initial undiluted analysis yielded target analytes over calibration range with peak saturation. Secondary diluted reanalysis was performed at 1:20 dilution. A tertiary analysis was peformed for Benzene and Toluene. Toluene raw concentration was still slightly over range but yielded acceptable peak shape. Toluene has een qualified, "E" for tertiary analysis. Acetone detection was confirmed by reanalysis in soil sample B-6 @ 45'-50'.

The following parameters (if included in this report) are not offered by NY ELAP: VOA 8260 Soil; 1,2,4,5-Tetramethylbenzene, Chlorodifluoromethane, Diisopropyl ether, Ethanol, Freon-114, p-Diethylbenzene, p-Ethyltoluene, Limonene. VOA 8260 Liquid; 1,2,4,5-Tetramethylbenzene, Chlorodifluoromethane, Freon-114, p-Diethylbenzene, p-Ethyltoluene, Limonene. Pesticides 8081 Soil; DBCP. Herbicides 8151 Soil; 3,5-Dichlorobenzoic Acid, 4-Nitrophenol, Acifluorfen, Bentazon, Chloramben, DCPA, Picloram, SM 2540G Total Volatile Solids, Soil TKN, Soil Organic Nitrogen, Total Phosphorus in soil, Percent Moisture, pH in non-potable water and temperature at which pH is measured, SM 4500-SO3 B Sulfite in Liquid, Total Sulfur in Soil, Acid Soluble Chloride by ASTMC1152, Water Soluble Chloride by ASTMC1218, Chlorine Demand by SM 2350 B, Total Residual Chlorine in Liquid and Reactivity to Sulfide and Reactivity to Cyanide.

The test results meet the requirements of the NYSDOH and NELAC standards, except where noted. The information contained in this analytical report is the sole property of American Analytical

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Case Narrative

WO#: **2106083**
Date: **6/21/2021**

CLIENT: WRS d.b.a Berninger Environmental
Project: BP Gas Station, 4001-4010 4th Ave, Brooklyn,

Laboratories, LLC. or the client for which this report was issued. The results contained in this report are only representative of the samples received. The sample receipt checklist is included as part of this lab report. Conditions can vary at different times and at different sampling conditions. American Analytical is not responsible for the use or interpretation of the data included herein.

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Definition Only

WO#: **2106083**
Date: **6/21/2021**

Definitions:

Sample Result and QC Summary Qualifiers - Level I and Level II Reports
ND - Not detected at the reporting limit/Limit of Quantitation

B - The analyte was detected in the associated method blank. For volatiles, methylene chloride and acetone are common lab contaminants. Data users should consider anything <5x the blank value as artifact.

E - The value is above the quantitation range

D - Analyte concentration was obtained from diluted analysis or from analysis using reduced sample volume.

J - The analyte was detected below the limit of quantitation but greater than the established Limit of Detection (LOD). There is greater uncertainty associated with these results and data should be considered as estimated.

U - The compound was analyzed for but not detected.

H - Holding time for preparation or analysis has been exceeded.

S - Spike recovery is outside accepted recovery limits.

R - RPD is outside accepted recovery range.

P - Secondary column exceeds 40% difference for GC test.

* - Calibration exceeds method requirement. Due to the large number of analytes for organic testing, the method allows 10% of analytes to have %RSD and/or %D to be >20%.
LOD - Limit of Detection; the lowest level the analyte can be determined to be statistically different from a blank.
LOQ - Limit of Quantitation; the lowest amount of analyte in a sample that can be quantitatively determined with suitable precision and accuracy.
PQL - Practical Quantitation Limit; the lowest level that can be reliably achieved within the specific limits of Precision and accuracy. Listed on the QC Summary Forms.
m - Analyte was manually integrated for GC/MS.
+ - Concentration exceeds regulatory level for TCLP

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-6 @ 45'-50'
Lab Order:	2106083	**Collection Date:**	6/10/2021 11:00:00 AM
Project:	BP Gas Station, 4001-4010 4th Ave, Brooklyn,	**Matrix:**	SOIL
Lab ID:	2106083-001A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
PERCENT MOISTURE			**D2216**				Analyst: **LB**
Percent Moisture	9.90	0	1.00		wt%	1	6/15/2021 2:32:45 PM
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
1,1,1,2-Tetrachloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,1,1-Trichloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,1,2,2-Tetrachloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,1,2-Trichloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,1-Dichloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,1-Dichloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,1-Dichloropropene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,2,3-Trichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,2,3-Trichloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,2,4,5-Tetramethylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,2,4-Trichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,2,4-Trimethylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,2-Dibromo-3-chloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,2-Dibromoethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,2-Dichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,2-Dichloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,2-Dichloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,3,5-Trimethylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,3-Dichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,3-dichloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,4-Dichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
1,4-Dioxane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
2,2-Dichloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
2-Butanone	13	5.7	11		µg/Kg-dry	1	6/16/2021 4:03:00 PM
2-Chloroethyl vinyl ether	ND	11	23	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
2-Chlorotoluene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
2-Hexanone	ND	5.7	11	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
2-Propanol	ND	57	57	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
4-Chlorotoluene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-6 @ 45'-50'
Lab Order:	2106083	**Collection Date:**	6/10/2021 11:00:00 AM
Project:	BP Gas Station, 4001-4010 4th Ave, Brooklyn,	**Matrix:**	SOIL
Lab ID:	2106083-001A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
4-Isopropyltoluene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
4-Methyl-2-pentanone	ND	5.7	11	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Acetone	130	5.7	11	B	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Benzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Bromobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Bromochloromethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Bromodichloromethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Bromoform	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Bromomethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Carbon disulfide	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Carbon tetrachloride	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Chlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Chlorodifluoromethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Chloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Chloroform	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Chloromethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
cis-1,2-Dichloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
cis-1,3-Dichloropropene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Cyclohexane	ND	2.3	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Dibromochloromethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Dibromomethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Dichlorodifluoromethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Diisopropyl ether	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Ethylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Freon-114	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Hexachlorobutadiene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Isopropylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
m,p-Xylene	ND	2.3	11	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Methyl Acetate	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Methyl tert-butyl ether	74	1.1	5.7		µg/Kg-dry	1	6/16/2021 4:03:00 PM
Methylene chloride	3.4	1.1	5.7	BJ	µg/Kg-dry	1	6/16/2021 4:03:00 PM
n-Butylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
n-Propylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-6 @ 45'-50'
Lab Order:	2106083	**Collection Date:**	6/10/2021 11:00:00 AM
Project:	BP Gas Station, 4001-4010 4th Ave, Brooklyn,	**Matrix:**	SOIL
Lab ID:	2106083-001A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
Naphthalene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
o-Xylene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
p-Diethylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
p-Ethyltoluene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
sec-Butylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Styrene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
t-Butyl alcohol	130	2.9	5.7		µg/Kg-dry	1	6/16/2021 4:03:00 PM
tert-Butylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Tetrachloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Toluene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
trans-1,2-Dichloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
trans-1,3-Dichloropropene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Trichloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Trichlorofluoromethane	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Vinyl acetate	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Vinyl chloride	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Xylenes, Total	ND	3.4	17	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Methylcyclohexane	ND	2.3	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Acrolein	ND	14	29	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM
Acrylonitrile	ND	1.1	5.7	U	µg/Kg-dry	1	6/16/2021 4:03:00 PM

American Analytical Laboratories, LLC.

Date: *21-Jun-21*

ELAP ID : 11418

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	MW-1
Lab Order:	2106083	**Collection Date:**	6/14/2021 10:00:00 AM
Project:	BP Gas Station, 4001-4010 4th Ave, Brooklyn,	**Matrix:**	LIQUID
Lab ID:	2106083-002A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5030C**		Analyst: **IR**
1,1,1,2-Tetrachloroethane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,1,1-Trichloroethane	ND	0.25	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,1,2,2-Tetrachloroethane	ND	0.25	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	0.25	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,1,2-Trichloroethane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,1-Dichloroethane	2.9	0.50	2.0		µg/L	1	6/14/2021 10:25:00 PM
1,1-Dichloroethene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,1-Dichloropropene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,2,3-Trichlorobenzene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,2,3-Trichloropropane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,2,4,5-Tetramethylbenzene	39	0.50	2.0		µg/L	1	6/14/2021 10:25:00 PM
1,2,4-Trichlorobenzene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,2,4-Trimethylbenzene	790	10	40	D	µg/L	20	6/19/2021 1:53:00 AM
1,2-Dibromo-3-chloropropane	ND	1.0	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,2-Dibromoethane	7.3	0.50	2.0		µg/L	1	6/14/2021 10:25:00 PM
1,2-Dichlorobenzene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,2-Dichloroethane	1.7	0.50	2.0	J	µg/L	1	6/14/2021 10:25:00 PM
1,2-Dichloropropane	2.6	0.50	2.0		µg/L	1	6/14/2021 10:25:00 PM
1,3,5-Trimethylbenzene	240	10	40	D	µg/L	20	6/19/2021 1:53:00 AM
1,3-Dichlorobenzene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,3-dichloropropane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,4-Dichlorobenzene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
1,4-Dioxane	ND	0.50	1.0	U	µg/L	1	6/14/2021 10:25:00 PM
2,2-Dichloropropane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
2-Butanone	ND	2.0	5.0	U	µg/L	1	6/14/2021 10:25:00 PM
2-Chloroethyl vinyl ether	ND	10	20	U	µg/L	1	6/14/2021 10:25:00 PM
2-Chlorotoluene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
2-Hexanone	ND	2.0	5.0	U	µg/L	1	6/14/2021 10:25:00 PM
2-Propanol	ND	50	50	U	µg/L	1	6/14/2021 10:25:00 PM
4-Chlorotoluene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
4-Isopropyltoluene	25	0.50	2.0		µg/L	1	6/14/2021 10:25:00 PM
4-Methyl-2-pentanone	ND	2.0	5.0	U	µg/L	1	6/14/2021 10:25:00 PM
Acetone	110	5.0	10	B	µg/L	1	6/14/2021 10:25:00 PM

American Analytical Laboratories, LLC.

Date: *21-Jun-21*

ELAP ID : 11418

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	MW-1
Lab Order:	2106083	**Collection Date:**	6/14/2021 10:00:00 AM
Project:	BP Gas Station, 4001-4010 4th Ave, Brooklyn,	**Matrix:**	LIQUID
Lab ID:	2106083-002A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5030C**		Analyst: **IR**
Benzene	12000	50	200	D	µg/L	100	6/19/2021 12:50:00 AM
Bromobenzene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Bromochloromethane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Bromodichloromethane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Bromoform	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Bromomethane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Carbon disulfide	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Carbon tetrachloride	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Chlorobenzene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Chlorodifluoromethane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Chloroethane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Chloroform	34	0.50	2.0		µg/L	1	6/14/2021 10:25:00 PM
Chloromethane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
cis-1,2-Dichloroethene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
cis-1,3-Dichloropropene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Cyclohexane	780	10	40	D	µg/L	20	6/19/2021 1:53:00 AM
Dibromochloromethane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Dibromomethane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Dichlorodifluoromethane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Diisopropyl ether	ND	1.0	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Ethylbenzene	1100	10	40	D	µg/L	20	6/19/2021 1:53:00 AM
Freon-114	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Hexachlorobutadiene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Isopropylbenzene	58	0.50	2.0		µg/L	1	6/14/2021 10:25:00 PM
m,p-Xylene	4100	20	80	D	µg/L	20	6/19/2021 1:53:00 AM
Methyl Acetate	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Methyl tert-butyl ether	170	10	40	D	µg/L	20	6/19/2021 1:53:00 AM
Methylene chloride	11	0.50	2.0	B	µg/L	1	6/14/2021 10:25:00 PM
n-Butylbenzene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
n-Propylbenzene	120	0.50	2.0		µg/L	1	6/14/2021 10:25:00 PM
Naphthalene	160	0.50	2.0		µg/L	1	6/14/2021 10:25:00 PM
o-Xylene	2000	10	40	D	µg/L	20	6/19/2021 1:53:00 AM
p-Diethylbenzene	120	0.50	2.0		µg/L	1	6/14/2021 10:25:00 PM

American Analytical Laboratories, LLC.

Date: *21-Jun-21*

ELAP ID : 11418

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	MW-1
Lab Order:	2106083	**Collection Date:**	6/14/2021 10:00:00 AM
Project:	BP Gas Station, 4001-4010 4th Ave, Brooklyn,	**Matrix:**	LIQUID
Lab ID:	2106083-002A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5030C**		Analyst: **IR**
p-Ethyltoluene	650	10	40	D	µg/L	20	6/19/2021 1:53:00 AM
sec-Butylbenzene	11	0.50	2.0		µg/L	1	6/14/2021 10:25:00 PM
Styrene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
t-Butyl alcohol	ND	5.0	10	U	µg/L	1	6/14/2021 10:25:00 PM
tert-Butylbenzene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Tetrachloroethene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Toluene	21000	50	200	ED	µg/L	100	6/19/2021 12:50:00 AM
trans-1,2-Dichloroethene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
trans-1,3-Dichloropropene	1.1	0.50	2.0	J	µg/L	1	6/14/2021 10:25:00 PM
Trichloroethene	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Trichlorofluoromethane	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Vinyl acetate	ND	1.0	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Vinyl chloride	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM
Xylenes, Total	6100	30	120	D	µg/L	20	6/19/2021 1:53:00 AM
Methylcyclohexane	520	10	40	D	µg/L	20	6/19/2021 1:53:00 AM
Acrylonitrile	ND	0.50	2.0	U	µg/L	1	6/14/2021 10:25:00 PM

Attachment-C
IDW Manifest

404500-21 EPC Providers Clean Earth 3454222

NON-HAZARDOUS WASTE MANIFEST

1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Waste Tracking Number
	1		445722207 MNC

GENERATOR

5. Generator's Name and Mailing Address

The Maccaia Group
558 Central Avenue
Blackstone MA 01504

Generator's Site Address (if different than mailing address)

Generator's Phone:

6. Transporter 1 Company Name — U.S. EPA ID Number

7. Transporter 2 Company Name — U.S. EPA ID Number

8. Designated Facility Name and Site Address — U.S. EPA ID Number

225 Wilcox Avenue
Providence, RI

Facility's Phone:

	9. Waste Shipping Name and Description	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	
1.		XXX		1 320		
2.						
3.						
4.						

13. Special Handling Instructions and Additional Information

14. **GENERATOR'S CERTIFICATION:** I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Generator's/Offeror's Printed/Typed Name: Toby Wolczynski — Signature — Month: 7 — Day: 22 — Year: 21

INT'L

15. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:

Transporter Signature (for exports only): Date leaving U.S.:

TRANSPORTER

16. Transporter Acknowledgment of Receipt of Materials

Transporter 1 Printed/Typed Name — Signature — Month: 7 — Day: 22 — Year: 21

Transporter 2 Printed/Typed Name — Signature — Month — Day — Year

DESIGNATED FACILITY

17. Discrepancy

17a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

Manifest Reference Number:

17b. Alternate Facility (or Generator) — U.S. EPA ID Number

Facility's Phone:

17c. Signature of Alternate Facility (or Generator) — Month — Day — Year

18. Designated Facility Owner or Operator: Certification of receipt of materials covered by the manifest except as noted in Item 17a

Printed/Typed Name — Signature — Month — Day — Year

NHWM-5-11

GENERATOR'S/SHIPPER'S INITIAL COPY

TABLES

Table-1
Soil tabulated data

American Analytical Laboratories, LLC.						
WorkOrder: 2106083						
Client: WRS d.b.a Berninger Environmental						
Project: BP Gas Station, 4001-4010 4th Ave, Brooklyn, NY		**Client Sample ID:**		**former B-6 (B-4) @ 45'-50'**		
TABLE-1		**Laboratory ID:**		**2106083-001**		
		Sampling Date:		**06/10/2021**		
Cas #:	**Procedure:**	**Analyte:**	**Units:**		**Q**	
E-11870	PERCENT MOISTURE	Percent Moisture	wt%	9.90		
630-20-6	VOLATILE SW-846 METHOD 8260D	1,1,1,2-Tetrachloroethane	PPB	1.1	U	
71-55-6	VOLATILE SW-846 METHOD 8260D	1,1,1-Trichloroethane	PPB	1.1	U	
79-34-5	VOLATILE SW-846 METHOD 8260D	1,1,2,2-Tetrachloroethane	PPB	1.1	U	
76-13-1	VOLATILE SW-846 METHOD 8260D	1,1,2-Trichloro-1,2,2-trifluoroethane	PPB	1.1	U	
79-00-5	VOLATILE SW-846 METHOD 8260D	1,1,2-Trichloroethane	PPB	1.1	U	
75-34-3	VOLATILE SW-846 METHOD 8260D	1,1-Dichloroethane	PPB	1.1	U	
75-35-4	VOLATILE SW-846 METHOD 8260D	1,1-Dichloroethene	PPB	1.1	U	
563-58-6	VOLATILE SW-846 METHOD 8260D	1,1-Dichloropropene	PPB	1.1	U	
87-61-6	VOLATILE SW-846 METHOD 8260D	1,2,3-Trichlorobenzene	PPB	1.1	U	
96-18-4	VOLATILE SW-846 METHOD 8260D	1,2,3-Trichloropropane	PPB	1.1	U	
95-93-2	VOLATILE SW-846 METHOD 8260D	1,2,4,5-Tetramethylbenzene	PPB	1.1	U	
120-82-1	VOLATILE SW-846 METHOD 8260D	1,2,4-Trichlorobenzene	PPB	1.1	U	
95-63-6	VOLATILE SW-846 METHOD 8260D	1,2,4-Trimethylbenzene	PPB	1.1	U	
96-12-8	VOLATILE SW-846 METHOD 8260D	1,2-Dibromo-3-chloropropane	PPB	1.1	U	
106-93-4	VOLATILE SW-846 METHOD 8260D	1,2-Dibromoethane	PPB	1.1	U	
95-50-1	VOLATILE SW-846 METHOD 8260D	1,2-Dichlorobenzene	PPB	1.1	U	
107-06-2	VOLATILE SW-846 METHOD 8260D	1,2-Dichloroethane	PPB	1.1	U	
78-87-5	VOLATILE SW-846 METHOD 8260D	1,2-Dichloropropane	PPB	1.1	U	
108-67-8	VOLATILE SW-846 METHOD 8260D	1,3,5-Trimethylbenzene	PPB	1.1	U	
541-73-1	VOLATILE SW-846 METHOD 8260D	1,3-Dichlorobenzene	PPB	1.1	U	
142-28-9	VOLATILE SW-846 METHOD 8260D	1,3-dichloropropane	PPB	1.1	U	
106-46-7	VOLATILE SW-846 METHOD 8260D	1,4-Dichlorobenzene	PPB	1.1	U	
123-91-1	VOLATILE SW-846 METHOD 8260D	1,4-Dioxane	PPB	1.1	U	
594-20-7	VOLATILE SW-846 METHOD 8260D	2,2-Dichloropropane	PPB	1.1	U	
78-93-3	VOLATILE SW-846 METHOD 8260D	2-Butanone	PPB	13		
110-75-8	VOLATILE SW-846 METHOD 8260D	2-Chloroethyl vinyl ether	PPB	11	U	
95-49-8	VOLATILE SW-846 METHOD 8260D	2-Chlorotoluene	PPB	1.1	U	
591-78-6	VOLATILE SW-846 METHOD 8260D	2-Hexanone	PPB	5.7	U	
67-63-0	VOLATILE SW-846 METHOD 8260D	2-Propanol	PPB	57	U	
106-43-4	VOLATILE SW-846 METHOD 8260D	4-Chlorotoluene	PPB	1.1	U	
99-87-6	VOLATILE SW-846 METHOD 8260D	4-Isopropyltoluene	PPB	1.1	U	
108-10-1	VOLATILE SW-846 METHOD 8260D	4-Methyl-2-pentanone	PPB	5.7	U	
67-64-1	VOLATILE SW-846 METHOD 8260D	Acetone	PPB	130	B	
71-43-2	VOLATILE SW-846 METHOD 8260D	Benzene	PPB	1.1	U	
108-86-1	VOLATILE SW-846 METHOD 8260D	Bromobenzene	PPB	1.1	U	
74-97-5	VOLATILE SW-846 METHOD 8260D	Bromochloromethane	PPB	1.1	U	
75-27-4	VOLATILE SW-846 METHOD 8260D	Bromodichloromethane	PPB	1.1	U	
75-25-2	VOLATILE SW-846 METHOD 8260D	Bromoform	PPB	1.1	U	
74-83-9	VOLATILE SW-846 METHOD 8260D	Bromomethane	PPB	1.1	U	
75-15-0	VOLATILE SW-846 METHOD 8260D	Carbon disulfide	PPB	1.1	U	
56-23-5	VOLATILE SW-846 METHOD 8260D	Carbon tetrachloride	PPB	1.1	U	
108-90-7	VOLATILE SW-846 METHOD 8260D	Chlorobenzene	PPB	1.1	U	
75-45-6	VOLATILE SW-846 METHOD 8260D	Chlorodifluoromethane	PPB	1.1	U	
75-00-3	VOLATILE SW-846 METHOD 8260D	Chloroethane	PPB	1.1	U	
67-66-3	VOLATILE SW-846 METHOD 8260D	Chloroform	PPB	1.1	U	
74-87-3	VOLATILE SW-846 METHOD 8260D	Chloromethane	PPB	1.1	U	
156-59-2	VOLATILE SW-846 METHOD 8260D	cis-1,2-Dichloroethene	PPB	1.1	U	
10061-01-5	VOLATILE SW-846 METHOD 8260D	cis-1,3-Dichloropropene	PPB	1.1	U	
110-82-7	VOLATILE SW-846 METHOD 8260D	Cyclohexane	PPB	2.3	U	
124-48-1	VOLATILE SW-846 METHOD 8260D	Dibromochloromethane	PPB	1.1	U	
74-95-3	VOLATILE SW-846 METHOD 8260D	Dibromomethane	PPB	1.1	U	
75-71-8	VOLATILE SW-846 METHOD 8260D	Dichlorodifluoromethane	PPB	1.1	U	
108-20-3	VOLATILE SW-846 METHOD 8260D	Diisopropyl ether	PPB	1.1	U	
100-41-4	VOLATILE SW-846 METHOD 8260D	Ethylbenzene	PPB	1.1	U	
76-14-2	VOLATILE SW-846 METHOD 8260D	Freon-114	PPB	1.1	U	
87-68-3	VOLATILE SW-846 METHOD 8260D	Hexachlorobutadiene	PPB	1.1	U	
98-82-8	VOLATILE SW-846 METHOD 8260D	Isopropylbenzene	PPB	1.1	U	
179601-23-1	VOLATILE SW-846 METHOD 8260D	m,p-Xylene	PPB	2.3	U	
79-20-9	VOLATILE SW-846 METHOD 8260D	Methyl Acetate	PPB	1.1	U	
1634-04-4	VOLATILE SW-846 METHOD 8260D	Methyl tert-butyl ether	PPB	74		
75-09-2	VOLATILE SW-846 METHOD 8260D	Methylene chloride	PPB	3.4	BJ	
104-51-8	VOLATILE SW-846 METHOD 8260D	n-Butylbenzene	PPB	1.1	U	
103-65-1	VOLATILE SW-846 METHOD 8260D	n-Propylbenzene	PPB	1.1	U	
91-20-3	VOLATILE SW-846 METHOD 8260D	Naphthalene	PPB	1.1	U	
95-47-6	VOLATILE SW-846 METHOD 8260D	o-Xylene	PPB	1.1	U	
105-05-5	VOLATILE SW-846 METHOD 8260D	p-Diethylbenzene	PPB	1.1	U	
622-96-8	VOLATILE SW-846 METHOD 8260D	p-Ethyltoluene	PPB	1.1	U	
135-98-8	VOLATILE SW-846 METHOD 8260D	sec-Butylbenzene	PPB	1.1	U	
100-42-5	VOLATILE SW-846 METHOD 8260D	Styrene	PPB	1.1	U	
75-65-0	VOLATILE SW-846 METHOD 8260D	t-Butyl alcohol	PPB	130		
98-06-6	VOLATILE SW-846 METHOD 8260D	tert-Butylbenzene	PPB	1.1	U	
127-18-4	VOLATILE SW-846 METHOD 8260D	Tetrachloroethene	PPB	1.1	U	
108-88-3	VOLATILE SW-846 METHOD 8260D	Toluene	PPB	1.1	U	
156-60-5	VOLATILE SW-846 METHOD 8260D	trans-1,2-Dichloroethene	PPB	1.1	U	
10061-02-6	VOLATILE SW-846 METHOD 8260D	trans-1,3-Dichloropropene	PPB	1.1	U	
79-01-6	VOLATILE SW-846 METHOD 8260D	Trichloroethene	PPB	1.1	U	
75-69-4	VOLATILE SW-846 METHOD 8260D	Trichlorofluoromethane	PPB	1.1	U	
108-05-4	VOLATILE SW-846 METHOD 8260D	Vinyl acetate	PPB	1.1	U	
75-01-4	VOLATILE SW-846 METHOD 8260D	Vinyl chloride	PPB	1.1	U	
1330-20-7	VOLATILE SW-846 METHOD 8260D	Xylenes, Total	PPB	3.4	U	
108-87-2	VOLATILE SW-846 METHOD 8260D	Methylcyclohexane	PPB	2.3	U	
107-02-8	VOLATILE SW-846 METHOD 8260D	Acrolein	PPB	14	U	
107-13-1	VOLATILE SW-846 METHOD 8260D	Acrylonitrile	PPB	1.1	U	

Table-2
Groundwater tabulated data

American Analytical Laboratories, LLC.					
WorkOrder: 2106083					
Client: WRS d.b.a Berninger Environmental					
Project: BP Gas Station, 4001-4010 4th Ave, Brooklyn, NY				MW-1	
TABLE-2				2106083-002	
				06/14/2021	
Cas #:	Procedure:	Analyte:	Units:		Q
E-11870	PERCENT MOISTURE	Percent Moisture	wt%		
630-20-6	VOLATILE SW-846 METHOD 8260D	1,1,1,2-Tetrachloroethane	PPB	0.50	U
71-55-6	VOLATILE SW-846 METHOD 8260D	1,1,1-Trichloroethane	PPB	0.25	U
79-34-5	VOLATILE SW-846 METHOD 8260D	1,1,2,2-Tetrachloroethane	PPB	0.25	U
76-13-1	VOLATILE SW-846 METHOD 8260D	1,1,2-Trichloro-1,2,2-trifluoroethane	PPB	0.25	U
79-00-5	VOLATILE SW-846 METHOD 8260D	1,1,2-Trichloroethane	PPB	0.50	U
75-34-3	VOLATILE SW-846 METHOD 8260D	1,1-Dichloroethane	PPB	2.9	
75-35-4	VOLATILE SW-846 METHOD 8260D	1,1-Dichloroethene	PPB	0.50	U
563-58-6	VOLATILE SW-846 METHOD 8260D	1,1-Dichloropropene	PPB	0.50	U
87-61-6	VOLATILE SW-846 METHOD 8260D	1,2,3-Trichlorobenzene	PPB	0.50	U
96-18-4	VOLATILE SW-846 METHOD 8260D	1,2,3-Trichloropropane	PPB	0.50	U
95-93-2	VOLATILE SW-846 METHOD 8260D	1,2,4,5-Tetramethylbenzene	PPB	39	
120-82-1	VOLATILE SW-846 METHOD 8260D	1,2,4-Trichlorobenzene	PPB	0.50	U
95-63-6	VOLATILE SW-846 METHOD 8260D	1,2,4-Trimethylbenzene	PPB	790	D
96-12-8	VOLATILE SW-846 METHOD 8260D	1,2-Dibromo-3-chloropropane	PPB	1.0	U
106-93-4	VOLATILE SW-846 METHOD 8260D	1,2-Dibromoethane	PPB	7.3	
95-50-1	VOLATILE SW-846 METHOD 8260D	1,2-Dichlorobenzene	PPB	0.50	U
107-06-2	VOLATILE SW-846 METHOD 8260D	1,2-Dichloroethane	PPB	1.7	J
78-87-5	VOLATILE SW-846 METHOD 8260D	1,2-Dichloropropane	PPB	2.6	
108-67-8	VOLATILE SW-846 METHOD 8260D	1,3,5-Trimethylbenzene	PPB	240	D
541-73-1	VOLATILE SW-846 METHOD 8260D	1,3-Dichlorobenzene	PPB	0.50	U
142-28-9	VOLATILE SW-846 METHOD 8260D	1,3-dichloropropane	PPB	0.50	U
106-46-7	VOLATILE SW-846 METHOD 8260D	1,4-Dichlorobenzene	PPB	0.50	U
123-91-1	VOLATILE SW-846 METHOD 8260D	1,4-Dioxane	PPB	0.50	U
594-20-7	VOLATILE SW-846 METHOD 8260D	2,2-Dichloropropane	PPB	0.50	U
78-93-3	VOLATILE SW-846 METHOD 8260D	2-Butanone	PPB	2.0	U
110-75-8	VOLATILE SW-846 METHOD 8260D	2-Chloroethyl vinyl ether	PPB	10	U
95-49-8	VOLATILE SW-846 METHOD 8260D	2-Chlorotoluene	PPB	0.50	U
591-78-6	VOLATILE SW-846 METHOD 8260D	2-Hexanone	PPB	2.0	U
67-63-0	VOLATILE SW-846 METHOD 8260D	2-Propanol	PPB	50	U
106-43-4	VOLATILE SW-846 METHOD 8260D	4-Chlorotoluene	PPB	0.50	U
99-87-6	VOLATILE SW-846 METHOD 8260D	4-Isopropyltoluene	PPB	25	
108-10-1	VOLATILE SW-846 METHOD 8260D	4-Methyl-2-pentanone	PPB	2.0	U
67-64-1	VOLATILE SW-846 METHOD 8260D	Acetone	PPB	110	B
71-43-2	VOLATILE SW-846 METHOD 8260D	Benzene	PPB	12000	D
108-86-1	VOLATILE SW-846 METHOD 8260D	Bromobenzene	PPB	0.50	U
74-97-5	VOLATILE SW-846 METHOD 8260D	Bromochloromethane	PPB	0.50	U
75-27-4	VOLATILE SW-846 METHOD 8260D	Bromodichloromethane	PPB	0.50	U
75-25-2	VOLATILE SW-846 METHOD 8260D	Bromoform	PPB	0.50	U
74-83-9	VOLATILE SW-846 METHOD 8260D	Bromomethane	PPB	0.50	U
75-15-0	VOLATILE SW-846 METHOD 8260D	Carbon disulfide	PPB	0.50	U
56-23-5	VOLATILE SW-846 METHOD 8260D	Carbon tetrachloride	PPB	0.50	U
108-90-7	VOLATILE SW-846 METHOD 8260D	Chlorobenzene	PPB	0.50	U
75-45-6	VOLATILE SW-846 METHOD 8260D	Chlorodifluoromethane	PPB	0.50	U
75-00-3	VOLATILE SW-846 METHOD 8260D	Chloroethane	PPB	0.50	U
67-66-3	VOLATILE SW-846 METHOD 8260D	Chloroform	PPB	34	
74-87-3	VOLATILE SW-846 METHOD 8260D	Chloromethane	PPB	0.50	U
156-59-2	VOLATILE SW-846 METHOD 8260D	cis-1,2-Dichloroethene	PPB	0.50	U
10061-01-5	VOLATILE SW-846 METHOD 8260D	cis-1,3-Dichloropropene	PPB	0.50	U
110-82-7	VOLATILE SW-846 METHOD 8260D	Cyclohexane	PPB	780	D
124-48-1	VOLATILE SW-846 METHOD 8260D	Dibromochloromethane	PPB	0.50	U
74-95-3	VOLATILE SW-846 METHOD 8260D	Dibromomethane	PPB	0.50	U
75-71-8	VOLATILE SW-846 METHOD 8260D	Dichlorodifluoromethane	PPB	0.50	U
108-20-3	VOLATILE SW-846 METHOD 8260D	Diisopropyl ether	PPB	1.0	U
100-41-4	VOLATILE SW-846 METHOD 8260D	Ethylbenzene	PPB	1100	D
76-14-2	VOLATILE SW-846 METHOD 8260D	Freon-114	PPB	0.50	U
87-68-3	VOLATILE SW-846 METHOD 8260D	Hexachlorobutadiene	PPB	0.50	U
98-82-8	VOLATILE SW-846 METHOD 8260D	Isopropylbenzene	PPB	58	
179601-23-1	VOLATILE SW-846 METHOD 8260D	m,p-Xylene	PPB	4100	D
79-20-9	VOLATILE SW-846 METHOD 8260D	Methyl Acetate	PPB	0.50	U
1634-04-4	VOLATILE SW-846 METHOD 8260D	Methyl tert-butyl ether	PPB	170	D
75-09-2	VOLATILE SW-846 METHOD 8260D	Methylene chloride	PPB	11	B
104-51-8	VOLATILE SW-846 METHOD 8260D	n-Butylbenzene	PPB	0.50	U
103-65-1	VOLATILE SW-846 METHOD 8260D	n-Propylbenzene	PPB	120	
91-20-3	VOLATILE SW-846 METHOD 8260D	Naphthalene	PPB	160	
95-47-6	VOLATILE SW-846 METHOD 8260D	o-Xylene	PPB	2000	D
105-05-5	VOLATILE SW-846 METHOD 8260D	p-Diethylbenzene	PPB	120	
622-96-8	VOLATILE SW-846 METHOD 8260D	p-Ethyltoluene	PPB	650	D
135-98-8	VOLATILE SW-846 METHOD 8260D	sec-Butylbenzene	PPB	11	
100-42-5	VOLATILE SW-846 METHOD 8260D	Styrene	PPB	0.50	U
75-65-0	VOLATILE SW-846 METHOD 8260D	t-Butyl alcohol	PPB	5.0	U
98-06-6	VOLATILE SW-846 METHOD 8260D	tert-Butylbenzene	PPB	0.50	U
127-18-4	VOLATILE SW-846 METHOD 8260D	Tetrachloroethene	PPB	0.50	U
108-88-3	VOLATILE SW-846 METHOD 8260D	Toluene	PPB	21000	DE
156-60-5	VOLATILE SW-846 METHOD 8260D	trans-1,2-Dichloroethene	PPB	0.50	U
10061-02-6	VOLATILE SW-846 METHOD 8260D	trans-1,3-Dichloropropene	PPB	1.1	J
79-01-6	VOLATILE SW-846 METHOD 8260D	Trichloroethene	PPB	0.50	U
75-69-4	VOLATILE SW-846 METHOD 8260D	Trichlorofluoromethane	PPB	0.50	U
108-05-4	VOLATILE SW-846 METHOD 8260D	Vinyl acetate	PPB	1.0	U
75-01-4	VOLATILE SW-846 METHOD 8260D	Vinyl chloride	PPB	0.50	U
1330-20-7	VOLATILE SW-846 METHOD 8260D	Xylenes, Total	PPB	6100	D
108-87-2	VOLATILE SW-846 METHOD 8260D	Methylcyclohexane	PPB	520	D
107-02-8	VOLATILE SW-846 METHOD 8260D	Acrolein	PPB		
107-13-1	VOLATILE SW-846 METHOD 8260D	Acrylonitrile	PPB	0.50	U

Berninger Environmental
groundwater consultants, geologists and scientists
A Division of WRS Environmental Services
17 Old Dock Road **Phone: 631-589-6521**
Yaphank, NY 11980 **Fax: 631-924-8105**

MONITORING REPORT

February 27th, 2024

Site Location:	**Client:**
BP Service Station	The Macchia Group, Inc.
4001-4011 4th Avenue	Mr. Joseph Macchia
Brooklyn, New York	556 Central Avenue
Spill #1811146	Bethpage, NY 11714

Bailing Schedule:	**Monthly**	**Reporting Schedule**:	**Quarterly**
Last Performed:	01/15/2023	Last Performed:	11/20/2023

Objective:

Monitor site well for depth to groundwater and the presence of free phase product on a monthly basis . Bail product as necessary. Wells monitored from the north side of the well casing with a Sonic Interface Probe. Check regularly for any spills by pump islands, tanks and drains.

Recovery System:

Bailing of product until well is dry. On average recharge rate approximately 1.0-1.5 gallons every half hour, although recharge rate varies drastically per event. The varying recharge rate per event effects the amount of product/water mixture recovered.

Comments:

Floating product was detected during this monitoring period. Site monitored and product bailed on December 18th, 2023, January 15th, 2024 and February 27th, 2024. Next monitoring and bailing of product scheduled for **March 2024**.

Reported By: _____ February 29, 2024
Steven Polen/Technician

Reviewed By: _____ February 29, 2024
Justin Halpin/Project Scientist

NYS-DEC: Mr. Jonathan Kolleeny

Berninger Environmental
groundwater consultants, geologists and scientists
A Division of WRS Environmental Services, Inc.
17 Old Dock Road
Yaphank, NY 11980
Phone: 631-589-6521
Fax: 631-924-8105

MONITORING WELL MEASUREMENTS

Site Location:
BP Service Station
4001-4011 4th Avenue
Brooklyn, New York

Client:
The Macchia Group, Inc.
556 Central Avenue
Bethpage, NY 11714

Abbreviation Key

DTW - Depth to Water from Casing (ft)	**D** - Dry	**V** - Disabled Vehicle over Well
DTP - Depth to Product from Casing (ft)	**C** - Cannot Locate	**R** - Recovery Pump in Well
PT - Product Thickness (ft)	**G** - Gone / Destroyed	
T - Trace Product	**D.O.** - Dissolved Oxygen	

December 18th, 2023

Wells	DTW	DTP	PT	VEFR	D.O. (mg/L)
MW-1	**21.37'**	**20.87'**	**0.5'**	**23 gal**	**-**

Notes:
Pump truck (VEFR event) to pump water/product (~23 gallons) and on-site drum (~45 gallons)

2" pipe volume=0.16 gallons/foot

monitoring well specs: 2" PVC; 50' to bottom with 25' of screen (25'-50')
2" PVC riser pipe from grade surface to 25' (0-25').

Abbreviation Key

DTW - Depth to Water from Casing (ft)	**D** - Dry	**V** - Disabled Vehicle over Well
DTP - Depth to Product from Casing (ft)	**C** - Cannot Locate	**R** - Recovery Pump in Well
PT - Product Thickness (ft)	**G** - Gone / Destroyed	
T - Trace Product	**n/d**- non-detect	

Berninger Environmental
groundwater consultants, geologists and scientists
A Division of WRS Environmental Services, Inc.
17 Old Dock Road
Yaphank, NY 11980
Phone: 631-589-6521
Fax: 631-924-8105

MONITORING WELL MEASUREMENTS

Site Location:
BP Service Station
4001-4011 4th Avenue
Brooklyn, New York

Client:
The Macchia Group, Inc.
556 Central Avenue
Bethpage, NY 11714

Abbreviation Key

DTW - Depth to Water from Casing (ft)	**D** - Dry	**V** - Disabled Vehicle over Well
DTP - Depth to Product from Casing (ft)	**C** - Cannot Locate	**R** - Recovery Pump in Well
PT - Product Thickness (ft)	**G** - Gone / Destroyed	
T - Trace Product	**D.O.** - Dissolved Oxygen	

January 15th, 2024

Wells	DTW	DTP	PT	Bailed	D.O. (mg/L)
MW-1	**24.10'**	**22.80'**	**1.3'**	**15 gal**	**-**

Notes:
well exhibited sufficient recharge

2" pipe volume=0.16 gallons/foot

monitoring well specs: 2" PVC; 50' to bottom with 25' of screen (25'-50')
2" PVC riser pipe from grade surface to 25' (0-25').

Abbreviation Key

DTW - Depth to Water from Casing (ft)	**D** - Dry	**V** - Disabled Vehicle over Well
DTP - Depth to Product from Casing (ft)	**C** - Cannot Locate	**R** - Recovery Pump in Well
PT - Product Thickness (ft)	**G** - Gone / Destroyed	
T - Trace Product	**n/d**- non-detect	

Berninger Environmental
groundwater consultants, geologists and scientists
A Division of WRS Environmental Services, Inc.
17 Old Dock Road
Yaphank, NY 11980
Phone: 631-589-6521
Fax: 631-924-8105

MONITORING WELL MEASUREMENTS

Site Location:
BP Service Station
4001-4011 4th Avenue
Brooklyn, New York

Client:
The Macchia Group, Inc.
556 Central Avenue
Bethpage, NY 11714

Abbreviation Key

DTW - Depth to Water from Casing (ft)	**D** - Dry	**V** - Disabled Vehicle over Well
DTP - Depth to Product from Casing (ft)	**C** - Cannot Locate	**R** - Recovery Pump in Well
PT - Product Thickness (ft)	**G** - Gone / Destroyed	
T - Trace Product	**D.O.** - Dissolved Oxygen	

February 27th, 2024

Wells	DTW	DTP	PT	Bailed	D.O. (mg/L)
MW-1	**33.4'**	**21.08'**	**12'**	**5 gal**	**-**


Notes:
11 bails of product/water mixture and well went dry.

2" pipe volume=0.16 gallons/foot

monitoring well specs: 2" PVC; 50' to bottom with 25' of screen (25'-50')
2" PVC riser pipe from grade surface to 25' (0-25').

Abbreviation Key

DTW - Depth to Water from Casing (ft)	**D** - Dry	**V** - Disabled Vehicle over Well
DTP - Depth to Product from Casing (ft)	**C** - Cannot Locate	**R** - Recovery Pump in Well
PT - Product Thickness (ft)	**G** - Gone / Destroyed	
T - Trace Product	**n/d**- non-detect	



Site Map
Proposed Sampling Locations
Figure-1

BP Service Station
4001-4010 4th Avenue
Brooklyn, NY

BEi Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

Lesova
ENVIRONMENTAL GROUP

PHASE-I
ENVIRONMENTAL SITE ASSESSMENT
For



4001 4th Avenue (a.k.a. 410 40th Street)
Brooklyn, NY 11232

(Block 714, Lot 6)

March 12, 2024

718.436.5500
office@lesovaenv.com
3611 14Tth Ave Suite #551
Brooklyn NY 1121
132-02 89th Ave Suite #222
Richmond Hill NY 11418

PHASE I
ENVIRONMENTAL SITE ASSESSMENT

ASTM E 1527-21

SITE ADDRESS: 4001 4th Avenue (a.k.a. 410 40th Street)
Brooklyn, NY 11232

PREPARED FOR: SLJ Management Group LLC
331 Rutledge Street, Suite #207
Brooklyn, NY 11211
Attn.: Mr. Solomon Jacobs

PREPARED BY: Lesova Environmental Group, LLC
132-02 89th Avenue, Ste. 222
Richmond Hill, NY 11418
Tel: (718) 436-5500

DATE: March 12, 2024

TABLE OF CONTENTS

EXECUTIVE SUMMARY **4**

1.0 INTRODUCTION **1**

1.1 Purpose 1

1.2 Detailed Scope of Services 1

1.3 Significant Assumptions 3

1.4 Limitations and Exceptions 3

1.5 User Reliance 4

2.0 SITE DESCRIPTION **5**

2.1 Property and Address Location 5
2.1.1 Tax Map Number 5
2.1.2 Acreage and Building Size 5
2.1.3 Ownership 5
2.1.4 Zoning 5

2.2 Current Occupancy and Property Use 5

3.0 USER PROVIDED INFORMATION **7**

3.1 Title Records 7

3.2 Environmental Liens 7

3.3 Specialized Knowledge 7

3.4 Commonly Known or Reasonably Ascertainable Information 7

3.5 Valuation Reduction for Environmental Issues 7

3.6 Reason for Performing Phase I ESA 7

4.0 SITE GEOLOGY AND HYDROGEOLOGY **8**

4.1 Topography and Site Characteristics 8
4.1.1 Elevation 8
4.1.2 Surface Water Bodies 8
4.1.3 Soils 8
4.1.4 Historic Fill Materials 8

4.2 Groundwater Characteristics 9

4.2.1 Depth to the Water and Groundwater Flow Direction 9

4.3 Geology 9

5.0 SITE HISTORY **11**

5.1 Municipal Records Review 11
5.1.1 EDR Building Department Permit Report 12

5.2 Historical Resources Review 12

5.2.1 Sanborn Fire Insurance Map Review 12
5.2.2 Historic Aerial Photograph Review 13
5.2.3 Historic Topographic Map Review 15
5.2.4 Historical City Directory Search 16
5.2.5 Previous Environmental Site Assessments 16
5.2.6 Environmental Liens or Activity and Use Limitations 18
5.3 Summary of Site History 19

6.0 REGULATORY AGENCY DATABASE SEARCH 21
6.1 Federal Databases 21
6.2 State Databases 23
6.3 Orphan Site Summary 30

7.0 SITE RECONNAISSANCE 31
7.1 Site Inspection 31
7.2 Methodology and Limiting Conditions 31
7.3 Site Description 31
7.4 Utilities 32
7.5 Surrounding Land Use 32
7.6 Interviews 33
7.7 Summary of Environmental Site Features 33
7.7.1 Chemical Use and Storage 33
7.7.2 Hazardous and Non-Hazardous Waste Storage and Disposal 33
7.7.3 Underground and Aboveground Storage Tanks 33
7.7.4 Sanitary and Stormwater Disposal 34
7.7.5 Polychlorinated Biphenyls 34
7.7.6 Debris, Dumping and Surficial Staining 34
7.7.7 Stressed Vegetation 35
7.7.8 Other Environmental Concerns 35

8.0 NON-SCOPE CONSIDERATIONS 36
8.1 Radon 36
8.2 Lead-Based Paint 36
8.3 Asbestos-Containing Materials 36
8.4 Wetlands 37
8.5 Mold and Water Damage 38
8.6 Vapor Encroachment 38

9.0 CONCLUSIONS AND RECOMMENDATIONS 40

10.0 ENVIRONMENTAL PROFESSIONAL STATEMENT 43

11.0 REFERENCES 44

FIGURES

No.	Description
1	Property Location Map
2	Property Tax Map
3	Property Zoning Map

PHOTOS

APPENDICES

APPENDIX A - EDR Radius Map
APPENDIX B - Property Profile Overview
APPENDIX C - EDR Building Permit Report
APPENDIX D - Historic Information (Sanborn Maps, Aerial Photographs, Topography Maps)
APPENDIX E - EDR City Directory Listings
APPENDIX F - Previous Environmental Reports
APPENDIX G - EDR Environmental Liens and AUL
APPENDIX H - User Questionnaire

EXECUTIVE SUMMARY

Lesova Environmental Group, LLC (LEG) prepared this Phase I Environmental Site Assessment (ESA) report for the commercial property known as 4001 4th Avenue, Brooklyn, NY 11232 which is situated east of 4th Avenue, west of 5th Avenue, between 40th Street to the north, and 41st Street to the south in the Sunset Park section of the borough of Brooklyn in the City of New York (hereinafter the "subject property"). The subject property is identified as Block 714 – Lot No. 6 on the New York City (NYC) tax maps.

The purpose of the Phase I ESA was to identify and evaluate the presence of recognized environmental conditions (RECs). Recognized environmental conditions (RECs) are defined as (1) the presence of hazardous substances or petroleum products in, on or at the property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on or at the property due to a release to the environment; or (3) the presence of hazardous substances or petroleum products in, on or at the property under conditions that pose a material threat of a future release to the environment. De minimis conditions are not recognized environmental conditions. The work was conducted in accordance with the American Society for Testing and Materials (ASTM) Standard E 1527-21 (Standard Practices for Environmental Site Assessment: Phase I Environmental Site Assessment Process), 40 CFR Part 312 (Standards and Practices for All Appropriate Inquiry; Final Rule), and LEG's proposal for services.

LEG was able to establish a history for the subject property dating back to 1888. According to a review of NYC records, Sanborn maps, aerial photographs, historic city directory listings, and historic topographic maps, as well as personal interviews, the subject property was identified with an L-shaped one-story concrete store and service station constructed circa 1925, and the second lot was vacant. A gasoline Underground Storage Tank (UST) was also depicted on the northern section of the lot as depicted on the 1926 Sanborn map. The 1942 Sanborn map depicted the subject property merged as one (1) lot with previous use as 1926 map and a one (1) story car garage to the south of the lot. The subject property was used as an automotive service station, lubrication, minor repair and office use with parking area until at least August 1965. The subject property was redeveloped with a one-story cement brick construction in the northwest portion which was used as a store with a gasoline filling station since at least 1970. However, the gasoline tank north of the lot was not depicted in the 1970 map. The subject property has remained in a similar configuration till date, and it is currently operating as a BP Gas Station with a convenience store. Currently, there are four (4) 4,000-gallon active USTs which consist of three (3) gasoline USTs and one (1) diesel UST on the subject property, registered as PBS #2-349399 with registration expiration date of September 08, 2028. The tanks are registered as equipped with an automatic overfill monitoring system, secondary spill containment and interstitial leak detection system.

LEG reviewed previous environmental investigations/reports for the subject property where a Phase-II Environmental Site Assessment prepared by Castleton Environmental Geologic Services DPC (Castleton) dated January 25, 2019, indicated that the geophysical investigation suspected the presence of nine (9) out-of-service USTs, of which four (4) were centralized under the canopy between the active dispensers and five (5) were in the western portion of the subject property. Additionally, a metallic anomaly non-indicative of a UST was detected on the northern portion of the subject property. This was followed by assessment of soil conditions which suggested that Volatile Organic Compounds (VOCs) exceeding Soil Cleanup Objectives (SCOs) were detected in five (5) out of six (6) samples. Also, certain VOCs exceeded commercial SCOs in two (2) samples that were collected from the west and south of the five (5) suspected USTs. No Semi-Volatile Organic Compounds (SVOCs) were detected in the samples analyzed. Based on these findings, a spill was reported on February 05, 2019 and spill # 18-11146 was assigned to the subject property. A supplemental remedial investigation (RI) prepared by Berninger Environmental dated August 29, 2020, was reviewed, where three (3) supplemental test pit borings in the area of five (5) suspected USTs, two (2) borings at the location of previously reported soil contamination, which was not delineated, and two (2) borings in the area of four (4) suspected USTs in the central portion of the property were installed. While advancing the borings in the suspected USTs area, a consistent refusal was achieved at 2.5-feet at all the three (3) test pit locations. This precisely consistent refusal indicated that the results of geophysical investigation were accurate and attributed to the abandonment of USTs in place. Vertical delineation was successfully achieved in the two (2) samples collected from the location of previously reported soil contamination while refusal was achieved in all the other samples. The analytical results for the supplemental soil samples indicated that Benzene, Toluene, Ethylbenzene, Xylenes (BTEX) was encountered in two (2) samples collected from the area of previously reported soil contamination. Furthermore, the Photo Ionization Detector (PID) readings as high as 4,500-ppm from the area near suspected USTs suggested majority contamination between 15-feet to 25-feet and drastic reduction (500 ppm) thereafter. No groundwater was encountered during this investigation, and it was assumed to be approximately 50-feet or more below grade surface (bgs). Based on the findings of these investigations, Berninger recommended Soil Vapor Extraction (SVE) and enhanced biological degradation as remedial alternatives and further proposed to prepare a Remedial Action Plan (RAP) to address soil contamination.

Based on the results of LEG's site inspection and records review, it was determined that the following RECs were identified for the subject property, which are summarized as follows:

- Information obtained from multiple historic sources revealed that the subject and multiple adjacent/surrounding properties were historically utilized as gasoline filling stations, auto repair and

car wash. The previous environmental subsurface investigations have also indicated impacted subsurface conditions due to the historic uses of the subject property as well as the adjacent/surrounding properties. Thus, LEG considers the historic use of the subject property and adjacent properties to be a REC.

- During the review of 1926 Sanborn maps, a gasoline UST was identified in the northern portion of the subject property. Since the status of the UST is unknown because of lack of documentation, LEG considers this as a REC.
- A geophysical investigation conducted by Castleton identified nine (9) suspected USTs in the western section of the subject property. This study is supported by previous environmental investigations that indicated impact on soil, soil vapor and groundwater. As no documentation regarding the status of these suspected tanks and/or soil conditions in its vicinity were available for review, there is a potential for spills or releases from these tanks to have impacted the subsurface. Therefore, the suspected USTs are considered a REC.
- One (1) open spill (Spill #18-11146) is recorded on the subject property. This spill was recorded as a result of VOCs being detected above SCOs in soil during Phase-II Environmental Site Assessment conducted by Castleton. Since the subject property was not remediated and the spill is not closed, LEG considers this a REC.
- A spill was recorded on the adjacent property identified to the southwest as Sunset Car Care along 4th Avenue and the DEC Memo suggests that no delineation or remediation was conducted, however, the spill was closed due to lack of response from the owner. This indicated that the contamination is left is place and LEG considers this a REC.

LEG identified the following environmental concerns/Business Environmental Risks (BER) and a De Minimis condition that are summarized as follows:

- A metallic anomaly non-indicative of a UST was identified in the northern portion of the subject property during Castleton's geophysical investigation. Given the historic use of the subject property as an auto service station with a loading area, the anomaly can possibly be a buried hydraulic lift and LEG considers this as a BER.
- The central and northwestern portions of the property were previously developed with a service station, so there is a potential for fill materials to be present. As no information regarding the nature or source of the fill materials was available for review, there is a potential for contaminated and/or structurally unsuitable fill materials to be present beneath the subject property. The potential presence of fill materials is considered a BER.

- Minor water staining was observed on the ceiling of the one-story building. No active water leaks or visible mold growth were observed within convenience store. The water-damaged areas identified should be removed from the building and properly disposed. LEG considers this a BER.
- Solid wastes and recyclables generated on the property are stored in three (3) dumpsters identified on the southwest of the subject property. The garbage disposal service was provided by Mr. T Carting (BIC #173). No evidence of staining or liquid waste was observed around the dumpsters. Two (2) drums were also identified near these dumpsters, of which one (1) was damaged and needs to be disposed of legally from the subject property. This damaged drum represents a De Minimis condition.

Based upon the above findings and conclusions, LEG recommends the following:

- The unregistered nine (9) USTs should be officially registered with New York State Department of Environmental Conservation (NYSDEC) Petroleum Bul Storage (PBS) Unit and closed with proper tank closure procedures as promulgated by the NYSDEC and New York City Fire Department (FDNY).
- To further evaluate the potential impacts related to the historic uses of the subject property and the spill on the subject property and from adjacent property, a subsurface investigation should be conducted by installation of soil borings and collection of representative soil, groundwater, and soil vapor samples. Further subsurface assessments are warranted to include laboratory analysis of the samples to determine the nature and extent of subsurface contamination.
- The contaminated areas should be further remediated to achieve acceptable Soil Cleanup Objectives.

The site reconnaissance, interviews and review of records have identified the presence or possible presence of hazardous substances or petroleum related products in, on, or at the Subject Property due to onsite and offsite release to the environment. Additionally, the subject property is identified as an E-Designation site requiring further evaluation of air quality and Hazardous Materials Phase I and Phase II Testing Protocol. LEG recommends that any future redevelopment of the subject property to be done must comply under the oversight of the NYC Office of Environmental Remediation (OER) to ensure that the E-Designation listing is properly addressed.

INTRODUCTION

1.1 Purpose

This document is a Phase I Environmental Site Assessment (ESA) prepared to determine recognized environmental conditions (RECs) and/or potential environmental concerns (PECs) in connection with the commercial property located at 4001 4th Avenue, Brooklyn NY 11232 (**Figure 1**). Lesova Environmental Group, LLC (LEG) prepared this Phase I Environmental Site Assessment (ESA) report for the commercial property which is situated east of 4th Avenue, west of 5th Avenue, between 40th Street to the north, and 41st Street to the south in the Sunset Park section of the borough of Brooklyn in the City of New York (hereinafter the "subject property"). The subject property is identified as Block 714 – Lot No. 6 on the New York City (NYC) tax maps. Representative site photographs are included in the **PHOTOS** section of the report.

1.2 Detailed Scope of Services

This Phase I ESA has been prepared in accordance with procedures established by environmental professionals and in concert with the guidance of regulatory agencies and funding institutions and American Society of Testing and Materials (ASTM) Practice E1527-21, inclusive of the United States Environmental Protection Agency (USEPA) "all appropriate inquiry" requirement published in the Federal Register on November 1, 2005. The USEPA "all appropriate inquiry" requirement establishes specific regulatory requirements for conducting all appropriate inquiries into the previous ownership, uses, and environmental conditions of a property for the purposes of qualifying for certain landowner liability protections under Comprehensive Environmental Response, Compensation and Liability Act (CERCLA).

The purpose of ASTM Practice E1527-21 is to define good commercial and customary practice in the United States of America for conducting an environmental site assessment of a parcel of commercial real estate with respect to the range of contaminants within the scope of CERCLA and petroleum products. As such, the practice is intended to permit a user to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on CERCLA liability; that is, the practices that constitute "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" as defined in 42 U.S.C. §9601 (35)(B).

As stated in ASTM Practice E1527-21, the purpose of the Phase I ESA is to identify, to the extent feasible pursuant to the process established by ASTM Practice E1527-21, *"recognized environmental conditions in connection with the subject commercial parcel."*

The term *recognized environmental conditions*, as defined by ASTM Practice E1527-21 means *"...the (1) the presence of hazardous substances or petroleum products in, on or at the property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on or at the property due to a release to the environment; or (3) the presence of hazardous substances or petroleum products in, on or at the property under conditions that pose a material threat of a future release to the environment. De minimis conditions are not recognized environmental conditions."*

"The term is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be subject of an enforcement action if brought to the attention of appropriate government agencies. Conditions determined to be de minimis are not recognized environmental conditions. A material threat is a physically observable or obvious threat which is reasonably likely to lead to a release that is threatening and might result in impact to human health and the environment."

This Phase I Environmental Site Assessment, as required by ASTM Practice E1527-21, specifically consists of the following four components:

1. Records Review;
    a. Physical settings document review;
    b. Regulatory database records search;
    c. Local municipal agency records search; and
    d. Historic use records search.
2. Site Reconnaissance;
3. Interviews with Past and Present Owners and Occupants; and
4. Evaluation and Reporting.

As stated in Practice E1527-21, there may be environmental issues or conditions at the property, which may be requested by the user to be addressed as part of the Phase I ESA, which are not covered within the scope of ASTM Practice E1527-21. The issues are referred to as non-scope considerations. The following is a list of non-scope considerations, which may be addressed, in a limited capacity within this Phase I Environmental Site Assessment:

- Radon;
- Lead-Based Paint;
- Asbestos-Containing Materials;

- Emerging Contaminants (PFOA and PFOS);
- Wetlands; and
- Mold and Water Damage.

1.3 Significant Assumptions

In preparation of the Phase I Environmental Site Assessment, it is assumed that information provided within the Environmental Database, regulatory agency records, municipal agency records, as well as information obtained from the user is accurate.

1.4 Limitations and Exceptions

The conclusions presented in this report are professional opinions based on the data described in this report. These opinions have been arrived at in accordance with currently accepted engineering and hydrogeologic standards and practices applicable to this location, and are subject to the following inherent limitations:

1. The data presented in this report are from visual inspections, examination of records in the public domain, and interviews with individuals having information about the subject property. The passage of time, manifestation of latent conditions, or occurrence of future events may require further exploration of the subject property, analysis of data, and re-evaluation of the findings, observations, and conclusions presented in this report;

2. The data reported and the findings, observations, and conclusions expressed are limited by the scope of work and defined in ASTM Practice E1527-21. Any deviations from this scope are defined below. Furthermore, the scope of work was defined and developed pursuant to the request of the Client;

3. No warranty or guarantee, whether expressed or implied, is made with respect to the data reported, findings, observations, or conclusions. These are based solely upon site conditions in existence at the time of the investigation, and other information obtained and reviewed by LEG;

4. LEG's Phase I ESA report presents professional opinions and findings of a scientific and technical nature. While attempts were made to relate the data and findings to applicable environmental laws and regulations, the report will not be construed to offer legal opinion or representations as to the requirements of, or compliance with, environmental laws, rules, or regulations, or policies of federal, state, or local government agencies. LEG does not assume liability for financial or other losses or subsequent damage caused by or related to any use of this document;

5. The conclusions presented in this report are professional opinions based on data described in this report. They are intended only for the purpose, site location, and project indicated. This report is not a definitive study of contamination at the subject property and should not be interpreted as such. An evaluation of subsurface soil and groundwater conditions was not performed as part of this investigation. As at any site, the actual condition of the groundwater and sub-surface soil cannot be determined without further investigation;

6. This report is based, in part, on information supplied to LEG by third-party sources. While efforts have been made to substantiate this third-party information, LEG cannot attest to the completeness or accuracy of information provided by others; and

7. The Phase I ESA practice does not include any testing or sampling of materials (e.g., soil, water, air, building materials).

1.5 User Reliance

This report was prepared in February 2024 by LEG at the request of Mr. Solomon Jacobs, representing JLH Holdings LLC, for use by JLH Holdings LLC, their legal and consulting representatives and other agents authorized to act on their behalf, in conjunction with the sale or lease of the subject property. LEG assumes no liability for use of this report by any person or entity other than those, for which it was prepared.

2.0 SITE DESCRIPTION

2.1 Property and Address Location

The subject property consists of a single tax parcel located with located east of 4th Avenue, west of 5th Avenue, between 40th Street to the north, and 41st Street to the south in the Sunset Park section of the borough of Brooklyn in the City of New York. The subject property is identified as Block 714 – Lot No. 6 on the New York City (NYC) tax maps. **(Figure 2)**.

2.1.1 Tax Map Number

The subject property is designated in the Brooklyn Borough as Block 714 – Lot No. 6 on the NYC tax maps.

2.1.2 Acreage and Building Size

According to the New York City Department of Finance, the subject property consists of a single 10,017-square feet tax parcel. The property is currently developed with a gasoline filling station with a one-story convenience store and parking. The gross floor area of the building is 1,860-square feet. The building occupies approximately 20% of the site footprint, and the remaining area is utilized as an asphalt-paved gasoline filling station and parking lot. The subject property is accessible from the western side of 4th Avenue and southern side of 40th Street. Street sidewalks are identified to the west along 4th Avenue and east along 40th Street of the property.

2.1.3 Ownership

According to information maintained by the New York City Department of Finance, the current property is owned by 4001 4th LLC.

2.1.4 Zoning

According to the City of New York Zoning Maps, the subject property is zoned for residential (R7A) with a commercial overlay (C4-2) (**Figure 3**).

2.2 Current Occupancy and Property Use

The building is currently operated by BP Gas Station and is developed with a gasoline filling station with a one-story convenience store (1,860 SF) and parking lot. The building was constructed circa 1928 with a concrete brick one-story convenience store, service station, auto garage and gasoline filling station, and was altered in at least 1970 with a one-story store and gasoline filling station with similar configuration till date. During the site inspection, the convenience store was identified to be constructed with a concrete masonry unit (c.m.u) with a cold storage room, a kitchen, storage racks and restrooms. The exhaust units for HVAC and compressor are located on the roof. All open areas on the lot were asphalt-paved and utilized for gas

filling and parking. Currently, there are four (4) 4,000-gallon active USTs which includes three (3) gasoline USTs and one (1) diesel UST on the subject property, registered as PBS #2-349399 with registration expiration date of September 08, 2028. The tanks are equipped with an automatic overfill monitoring system, secondary spill containment and interstitial leak detection system.

3.0 USER PROVIDED INFORMATION

3.1 Title Records

As of the date of this report the Client did not engage LEG to perform a Chain of Title review nor was a Chain of Title provided for review.

3.2 Environmental Liens

An environmental lien is a charge, security, or encumbrance upon title to a property to secure the payment of a cost, damage, debt, obligation, or duty arising out of response actions, cleanup or other remediation of hazardous substances or petroleum products upon a property, including, but not limited to, liens imposed pursuant to CERCLA 42 USC § 9607 (1) & 9607(r) and similar state and local laws. The user has not made LEG aware of any environmental liens against the subject property. According to Environmental data Resources, Inc. (EDR) data search, no environmental Lien and AUL were found for the subject property.

3.3 Specialized Knowledge

The user has not made LEG aware of any specialized knowledge regarding the chemicals or processes formerly in use at the subject or surrounding properties.

3.4 Commonly Known or Reasonably Ascertainable Information

The user has not made LEG aware of any commonly known or reasonably ascertainable information regarding the past uses of the subject property, specific chemicals in use at the subject property or any spills, chemical releases, or environmental cleanups at the subject property.

3.5 Valuation Reduction for Environmental Issues

The user has not made LEG aware of any valuation reduction regarding the sale price of the property.

3.6 Reason for Performing Phase I ESA

The Phase I ESA was performed to identify recognized environmental conditions at the subject property as part of the due diligence to support the acquisition of the property by 4001 4th LLC.

4.0 SITE GEOLOGY AND HYDROGEOLOGY

4.1 Topography and Site Characteristics

4.1.1 Elevation

The topography of the property and surrounding area was reviewed from the United States Geological Survey (USGS) 7.5-minute series topographic map for the Brooklyn, NY. The elevation of the subject property is approximately 51-feet above mean sea level (amsl). The subject property is relatively flat with the general topographic gradient sloping downward to the north-northwest direction.

4.1.2 Surface Water Bodies

There are no surface water bodies on or adjacent to the subject property. Surface water bodies near the subject property include Sylvan Water Lake located approximately 0.4-mile to the northeast and Gowanus Bay located approximately 0.6-mile to the north at their closest points.

4.1.3 Soils

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. Soil maps, based on the State Soil Geographic (STATSGO) Database, are compiled by generalizing more detailed Soil Survey Geographic (SSURGO) database maps.

According to the STATSGO data, the soil component in the vicinity of the subject property is identified as Urban Land and is described as having a variable surface texture. The STATSGO database states that additional subordinate soil types may be present in the general vicinity of the subject property. These soil types are described as mainly silt loam and sandy loam. Deeper soil types consist of very gravelly, loamy sand, non-weathered bedrock and stratified sandy loam.

Additional information regarding the soil classification is also included in on Page A-4 of the EDR Radius Map report which is attached as **Appendix A**.

4.1.4 Historic Fill Materials

Information obtained from the US Department of Agriculture’s Web Soil Survey indicates that the soil profile beneath the subject property consists of Urban Land Greenbelt substratum (cemented material up till 15-inches, followed by gravelly sandy loam.

As such, there is a potential for fill materials to be present, given the historical development of the on-site and surrounding properties. However, this is not a concern at this time as the subject property is maintained with a solid cap with no direct contact or exposure to affect human health. In the event the urban fill material is disturbed during any future construction/redevelopment project, sampling for proper disposal and handling is recommended.

4.2 Groundwater Characteristics

4.2.1 Depth to the Water and Groundwater Flow Direction

Estimated groundwater levels and flow directions may vary due to seasonal fluctuations in precipitation, local usage demands, geology, underground structures, or de-watering operations. Generally, groundwater flow typically mimics surface topography and will also tend to flow towards nearby bodies of water. Information contained in the EDR database report, the USGS Water-Table and Potentiometric-Surface Altitudes in the Magothy Aquifer Beneath Long Island, March-April 2013, the USGS web site and topographic map were used to estimate groundwater depth and flow direction.

Based upon a surface elevation of 51-feet amsl, the depth to groundwater in the vicinity of the subject property is approximately 51-feet to 75-feet below grade surface (bgs) (USGS Long Island Depth to Water, 2013). Groundwater is expected to flow to the north-northwest, towards Upper New York Bay, and consistent with the regional trend.

A review of USGS well data indicates that the nearest USGS monitoring well (USGS ID – USGS403841074005101) with available water level data is located approximately 1/8-1/4 mile east-southeast of the subject property at a lower elevation. The well is completed in the Northern Atlantic Coastal Plain aquifer at a depth of 236-feet bgs. Seventy-one (71) groundwater measurements were collected from this well and the latest collected on December 28, 1984 at a level of 1.35-feet to sea level.

4.3 Geology

According to the USGS Groundwater Atlas of the United States, New York region (1995) and USGS Hydrogeologic Framework of Long Island, New York, the property is located within the Atlantic Coastal Plain physiographic province. Overlaying the Atlantic Coastal Plain, the property is underlain by a small section of the Manhattan prong bedrock, exhibiting metamorphic rocks such as schist and gneiss. Additionally, the property features Cretaceous sediments, which contribute to the formation of specific soil types such as sandy and clayey soils. Moreover, the presence of Terminal Moraines provides evidence of past glaciation, marking the extent of glacial advance and retreat during the Quaternary period. These glacial

deposits overlay Cretaceous sediments, further shaping the property's soil composition. Within the terminal moraines, soils may exhibit a mixture of gravel, sand and till.

5.0 SITE HISTORY

5.1 Municipal Records Review

As the subject property is located in the Borough of Brooklyn, New York City, Kings County, on-line records searches were conducted or Freedom of Information Law (FOIL) requests were sent to the following agencies: New York City Department of Buildings (NYCDOB) and the New York City Department of Environmental Protection (NYCDEP), and NYSDEC requesting available regulatory information regarding the subject property. Regulatory agencies usually take six to eight (6-8) weeks to process FOIL requests. Any additional responses will be reviewed and forwarded upon receipt. As of the date of this report, the following information has been received:

New York City Department of Finance

The following is a summary of pertinent information obtained:

Tax Lot:	Block 714 – Lot No. 6
Address:	4001 4th Avenue, Brooklyn NY 11232
Owner:	4001 4th LLC
Lot Size:	10,017-square
Building Class:	G3-Gas Station with Retail Store
Zoning:	Residential (R7A) with Commercial overlay (C2-4)

New York City Department Buildings

Computerized Property Profile Overviews (PPOs) available from the NYCDOB Building Information System (BIS) website were reviewed for information regarding the subject property. Pertinent information regarding the subject property is summarized below:

BIN No. 3010582

Per the NYCDOB Building Information Search (NYCDOB BIS) conducted on February 26, 2024, the subject property was registered with BIN #3010582. The following Certificate of Occupancy (CO) were identified:

- CO # 34595 dated 1925, was identified and stated that the new building had been completed substantially on the subject property for the purpose of its use as an office.
- CO # 192481 dated August 10, 1965, was identified and stated the subject property was used as automotive service station, lubrication, minor repair and office use with parking area. According to the Fire Department, gasoline storage tanks were installed on July 23, 1965.

The profile was identified with one (1) complaint, no violations, and ten (10) jobs/filings. One (1) ARA/LAA Job was identified pertaining to the installation of a gas fired Modine heater. Additionally, a property profile overview including the CO is provided in the **Appendix B**.

New York City Department of Environmental Protection

A FOIL application was forwarded to the NYCDEP on February 23, 2024. A response from this agency is pending.

New York State Department of Environmental Conservation

A FOIL application was forwarded to the NYSDEC on February 26, 2024, for information regarding the open/active spill incident associated with the southern adjacent property.

5.1.1 EDR Building Department Permit Report

EDR conducted a search of available Building Department Permits for the subject and adjacent properties. The search was provided for the years 1974 through 2023. LEG identified seven (7) Alt 2 alteration/renovation work permits and eight (8) electrical permits. Selective permits are explained as follows:

- Permit #301864515-01-EW-OT, dated August 18, 2009, was filed and issued for the renovation of the existing store for installation of new aluminum doors and windows, no change in occupancy, use or egress.
- Permit #320041897-01-EW-OT, dated July 9, 2009, was filed and issued to line the existing motor fuel tanks, install new piping and dispensers, no change in occupancy, use or egress.
- Permit #310155667-01-EW-FP, dated July 30, 2008, was filed and issued for installation of fire suppression system over existing pump islands, no change in occupancy, use or egress.

A copy of the EDR Building Permit Search is included in **Appendix C.**

5.2 Historical Resources Review

5.2.1 Sanborn Fire Insurance Map Review

EDR conducted a search of available Sanborn Fire Insurance Maps for the subject property and immediate surrounding area. Fire Insurance Maps were provided for the years 1888, 1906, 1926, 1942, 1951, 1970, 1976, 1978, 1979, 1980, 1982, 1987, 1988, 1990, 1991, 1992, 1993, 1994, 1995, 2001, 2002, 2003, 2004, 2005, 2006 and 2007. A copy of the EDR Sanborn Maps is attached as **Appendix D**. LEG's review of the Sanborn Maps is provided on the following table:

YEAR	OBSERVATIONS for *Subject property*	OBSERVATIONS for *Surrounding properties*
1888	*The subject property is identified as a vacant lot.*	*4th Avenue and 40th Street appear in their current approximate configurations. No significant development appears to the north, west, or south of the subject property. Limited, multistory residential development appears to the east of the subject property.*
1906	*The subject property is identified as a vacant lot.*	*The surrounding properties were further developed with multi-storied row of residential building to the south, a school at the northwest and multi-storied stores at the northeast. Identified 4th Avenue to the north, 40th Street to the northeast and 41st Street to the southeast of the subject property.*
1926	*The subject property appears to be developed with a one-story concrete store and service station with one (1) gasoline tank at the north of the property.*	*The surrounding properties were further developed with a row of residential flats to the southeast. A store with two (2) gasoline tanks is also identified at the southwest of the subject property.*
1942-1951	*The subject property was identified in the similar configuration as the 1926 map with the addition of an auto parking lot identified on the southern corner.*	*The surrounding properties were further developed with an auto parking to the north and an auto service station and auto laundry adjacent to the subject property to the south. Three (3) gasoline tanks at the front of the auto laundry to the south were identified.*
1970-1982	*The subject property has been reconfigured and is now improved with a one-story masonry building along the southeast portion of the property, identified as a filling station. The gasoline tank identified on the 1926-1951 Sanborn Maps is no longer present.*	*The surrounding properties were mostly identified in a similar configuration as the 1942-1951 maps. An auto repair shop was identified to the north of the subject property. An auto body shop was also identified at the northeast to the subject property. A filling station is also identified at the corner of 39th Street and 4th Avenue at the northeast of the subject property.*
1987-2007	*The subject property was identified in the similar configuration as the 1970-1982 maps with an addition of a canopy.*	*The surrounding properties were identified in a similar configuration as the 1970-1982 maps. In 1994, the filling station was not identified, instead a commercial building was developed.*

The Sanborn maps identified presence of a gasoline UST from 1926 to 1951 on the subject property, two (2) gasoline USTs on the property to southwest along 4th Avenue in 1926, and three (3) gasoline USTs on the property to southwest along 41st street from 1942 to 2007.

5.2.2 Historic Aerial Photograph Review

EDR conducted a search and provided copies of available historical aerial photographs showing the subject and surrounding properties. Aerial photographs were provided for the years 1924, 1940, 1943, 1951, 1954, 1961, 1966, 1976, 1980, 1985, 1995, 2008, 2011, 2015, and 2019 (**Appendix D**).

YEAR	*OBSERVATIONS for Subject property*	*OBSERVATIONS for Surrounding property*
1924	*The subject property was identified as a vacant land.*	*The surrounding properties were identified as either developed lands or lands that were in the process of being cleared for development. Adjacent structure to the southwest was identified with a single structure. A multi-story structure was identified occupying the lot across the street on 4th Avenue.*
1940-1954	*The subject property was identified as developed with multiple structures in the center and towards the north of the property.*	*The surrounding properties were identified as densely developed with muti-storied residential buildings. The properties to the south and west were scarcely developed with structures.*
1961-1985	*The subject property was identified in a different configuration with only one structure on the southeast corner of the property.*	*The surrounding properties were identified in a similar configuration as the 1940-1954 maps.*
1995-2019	*The subject property was identified in the similar configuration as the 1961-1985 maps with an addition of a canopy.*	*The surrounding properties were identified in a similar configuration as the 1961-1985 maps.*

The photographs do not show any evidence of historic water bodies, significant re-grading, mining or historic dumping activities, which would indicate a potential environmental risk to the property.

5.2.3 Historic Topographic Map Review

LEG reviewed the 2019 Brooklyn, NY USGS topographic quadrangle map, as well as available historic topographic quadrangle maps provided by EDR (**Appendix D**).

LEG's review of the topographic maps is provided on the following table:

YEAR	*OBSERVATIONS for Subject property*	*OBSERVATIONS for Surrounding property*
1891	*The subject property is not depicted on the map.*	*Areas on north and northwest of the properties were depicted scarce development. The land around the subject property indicated higher elevation which gradually decreased moving towards Gowanus Bay, indicating sloping towards north-northwest.*
1897	*The subject property is not depicted on the map.*	*The surrounding properties are not depicted on the map.*
1898-1905	*The subject property is not depicted on the map.*	*The Greenwood Cemetery is depicted on the northwest of the subject property. Sparse development is identified around the subject property with development of rail road on the south and southeast.*
1925	*The subject property is identified on the map.*	*Areas around the property indicate development of more than one structure consistent to multi-storied buildings.*
1947	*The subject property does not depict any improvements.*	*Areas surrounding the property depict dense development. Landmarks and the avenues are also identified.*
1955-1981	*The subject property does not depict any improvements.*	*Areas surrounding the property showed no improvement. Express ways on west and east of the subject property were identified.*
1995	*The subject property is not depicted on the map.*	*The surrounding properties are not depicted on the map.*
2013-2019	*The 2013-2019 maps do not depict any buildings or other structures.*	*Surrounding roads are visible, consistent with their current configuration. Bay Ridge Channel on the West and Gowanus Bay on the north to the subject property are identified. Perennial lakes in the Greenwood Cemetery are also identified.*

LEG's historic topographic map review did not reveal evidence of recognized environmental conditions in connection with the site or adjoining properties.

5.2.4 Historical City Directory Search

EDR conducted a search and provided copies of available historical city directory listings for the subject and adjacent properties. The historical city directory listings (**Appendix E**) were reviewed, to identify information regarding past uses of the subject and surrounding properties to determine if historical usage represented a REC to the subject property.

The listings are summarized in the following table:

YEAR	**OBSERVATIONS FOR *Subject Property – 4001 4th Avenue***
1928-1934	*TYDOL CHAIN INC GAS STATION*
1940-1949	*LAMBNETS SERVICE STATION*
1960-1970	*ELWOOD SERVICE STATION*
1973	*TENANT* *STAGE AUTO SERVICE STATION*
1976	*ALLAN BROS SERVICE STATION*
1985-1997	*H&S SERVICE CENTER*
2000	*JOHNNYS AUTO REPAIR AND BODY WORK* *BROOKLYN SERVICE STATION INC* *NOR GLENN SERVICE STATION*
2010-2017	*B&L GAS STATION ENTERPRISES INC*
2020	*TENANTS*

The historical uses of the property as a service station and gas station represents REC to the subject property.

5.2.5 Previous Environmental Site Assessments

LEG was provided with the following previous investigations/reports for the subject property for review by the property owner:

- *Phase-II Environmental Site Assessment prepared by Castleton Environmental Geologic Services DPC dated January 25, 2019*

  Castleton conducted a Phase-II Environmental Site Assessment (ESA) based on the Phase-I ESA prepared by Merritt Environmental Consulting Corp. (MECC) dated January 7, 2019, to determine the impact of historic and current usages of the subject property as a gasoline filling station on subsurface. The scope of work included (a) geophysical investigation using Ground Penetrating Radar (GPR) to determine the presence/absence of any subsurface anomalies indicative of USTs and to clear underground utilities; and (b) soil sampling to characterize the site soil quality for impacts pertaining to gasoline filling station operations.

  During the geophysical investigation, Castleton identified four (4) 4,000-gallons active USTs on the subject property consistent with the Petroleum Bulk Storage (PBS) records. Additionally, nine (9) suspected USTs were identified, of which four (4) were centralized under the canopy between the active dispensers and five (5) were located in the western portion of the subject property. A metal anomaly non-

indicative of a UST was also identified on the northern portion of the subject property. The gasoline tank identified on the historic Sanborn Maps on the northern portion was also not identified.

To assess the soil conditions at the subject property, Castleton advanced six (6) soil borings in the potential areas identified during the geophysical investigation. Elevated Photo Ionization Detector (PID) readings (ranging from 22.9 ppm to 5,285 ppm) and visible olfactory or visible evidence of contamination were observed and recorded. The analytical results for soil samples reported VOCs above SCOs in five (5) out of six (6) samples. Also, certain VOCs exceeded commercial SCOs in two (2) samples that were collected from the west and south of the five (5) suspect USTs. No SVOCs were detected in the samples.

Based on these findings, a spill was reported on February 05, 2019 and spill # 18-11146 was assigned to the subject property. Furthermore, Castleton recommended notifying NYSDEC about the findings, assessment and legal removal of suspected USTs, and delineation and remediation of petroleum VOCs under NYSDEC Spills Program. A copy of this report is compiled and attached as **Appendix F**.

- *Supplemental Remedial Investigation report (RIR) prepared by Berninger Environmental dated June 2020*

  A supplemental remedial investigation (RI) was conducted by Berninger on August 29, 2020, to further define the nature and extent of contamination by vertically delineating the contamination discovered on previous sample locations identified by Castleton and confirm the results of geophysical investigation by Castleton by performing test pits in the suspected UST area.

  To do this, Berninger installed three (3) supplemental test pit borings in the area of suspected USTs and two (2) borings at the location of previously reported soil contamination which was not delineated. Two (2) borings were also installed in the suspected USTs area in the central portion of the property. While advancing the borings in the suspected UST area, a consistent refusal was achieved at 2.5-feet at all the three (3) test pit locations. This precisely consistent refusal indicated that the results of geophysical investigation were accurate and attributed to the abandonment of USTs in place.

  Vertical delineation was successfully achieved in the two (2) samples collected from the location of previously reported soil contamination while refusal was achieved in all the other samples. The analytical results for the supplemental soil samples indicated that Benzene, Toluene, Ethylbenzene, Xylenes (BTEX) was encountered in two (2) samples collected from the area of previously reported soil contamination. Furthermore, the PID readings as high as 4,500-ppm from the area near UST suggested majority contamination between 15-feet to 25-feet and drastic reduction (500 ppm) thereafter. No groundwater was encountered during this investigation, and it is assumed to be approximately 50-feet or more below grade surface (bgs). Based on these findings, Berninger recommended Soil Vapor Extraction (SVE) and enhanced biological degradation as remedial alternatives, and further proposed to prepare a

Remedial Action Plan (RAP) to address soil contamination. A copy of this report is compiled and attached as **Appendix F**.

- *Remedial Action Plan (RAP) prepared by Berninger Environmental dated August 2020*
  Following the conclusion and recommendations of the RIR, Berninger proposed SVE as a remedy for removal the VOCs from the soil by off gassing them into the atmosphere. For the same, four (4) SVE wells were proposed in the area of former USTs on the subject property. A copy of this report is compiled and attached as **Appendix F**.

- *Supplemental Remedial Investigation Pilot Study Work Plan prepared by Berninger Environmental dated December 2021*
  The findings of supplemental RIR by Berninger dated June 2020 concluded requirement of additional investigation to determine the lateral extent of contamination. To address this, installation of three (3) groundwater monitoring wells was proposed near the 4th Avenue Subway line to determine potential impacts to sensitive receptors. The study of depth of the subway tunnel was also proposed to evaluate potential impacts. Additionally, a SVE Pilot Test was also proposed to confirm the Radius of Influence (ROI) by installing one (1) pilot well (SVE-PW) within the plume. Berninger concluded by adding that a remedial plan will be developed to treat the contaminated media on site based on the pilot test results. A copy of this report is compiled and attached as **Appendix F**.

- *Supplemental Remedial Investigation Work Plan prepared by Berninger Environmental dated March 2022 (revised 1)*
  Consequent to the findings and conclusion of supplemental RIR, Berninger proposed installation of three (3) groundwater monitoring wells where two (2) are located at the location of two (2) soil borings that were installed in the area of previously reported soil contamination. A copy of this report is compiled and attached as **Appendix F**.

5.2.6 Environmental Liens or Activity and Use Limitations

No Title Reports were available for review from the Client of the Property Owner. However, at the request of the Client, LEG obtained an Environmental Lien and Activity Use Limitation Search from EDR. The search did not identify any environmental liens or AULs based upon a review of New York City, NYSDEC and USEPA records. However, ownership information was also provided with the lien and AUL search, which is summarized as follows:

An Environmental Liens and AUL search conducted by EDR and dated February 20, 2024, resulted as follows: A Deed (ID: 2008091800252001) was found for the subject property, dated September 22, 2008, that stated that the title was vested in 4001 4th LLC, from Estron Oil Corp, for Block 714 and Lot 6 in the Borough of Kings. A RP-5217 real property transfer report was also found. No Environmental Liens or AUL were identified. A copy of the Environmental Lien and Activity Use Limitation Search is included in **Appendix G**.

Additionally, a search was conducted for Activity and Use Limitations (AULs) associated with the subject property, more specifically Institutional Controls (ICs) and/or Engineering Controls (ECs), which have been placed upon the property as a result of environmental issues identified at the property. In the City of New York, information on such AULs is maintained by the City of New York Department of City Planning (NYCDCP) and is commonly depicted on zoning maps with an "E" designation, as well as maintained within Chain of Title Records. For a site to be designated with an "E" restriction, several criteria must be met. First, a property must be included within a designated re-zoning area, then the property must be identified as a "Potential" or "Projected" re-development property, and finally, the site must be listed on one or more environmental regulatory databases as listed in the ASTM standard, be adjacent to such a site, and/or have historical usage associated with hazardous materials with the potential to impact human health and/or the environment should a release have occurred. Sites with an "E" designation require additional investigation and/or remediation be performed in order to determine if the historical use of a property, typically manufacturing or chemical usage, have impacted the site. No change of use or development requiring a building permit will be issued for an "E" designated site without approval from the New York City of Office of Environmental Remediation (NYCOER).

5.3 Summary of Site History

LEG was able to establish a history for the property dating back to 1925. According to a review of NYC records, Sanborn maps, aerial photographs, historic city directory listings, and historic topographic maps, as well as personal interviews, the subject property was identified as a square shaped lot developed with an L-shaped one-story concrete store and service station constructed circa 1925 in the central and northern portion of the subject property. A gasoline UST was also depicted along 40th Street during this time. The subject property was used as an automotive service station, lubrication, minor repair and office use with parking area until at least August 1965. The subject property was redeveloped with a one-story cement brick construction in the northwest portion which was used as a store with a gasoline filling station since at least 1970. However, the tank along 40th Street was not identified on the subject property anymore. The subject property has

remained in a similar configuration till date, and it is currently operated as a BP Gas Station with a convenience store.

6.0 REGULATORY AGENCY DATABASE SEARCH

EDR was retained to provide a computerized database search of the project area within an ASTM-standard radius of the subject property. A list of the databases searched and the search radius is shown on the summary table below. LEG reviewed the database output to determine if the property appears on any of the regulatory agency lists.

6.1 Federal Databases

Listing Name or Database Searched	Abbreviation	Search Distance	Subject Property Listed?	No. of Sites within the Search Radius
National Priorities List Sites, including Proposed and Delisted Sites	NPL	1.0 mile	No	0 NPL 0 Proposed 0 Delisted
Superfund Enterprise Management System (SEMS) and SEMS Archive Sites	SEMS and SEMS-ARCHIVE	0.5 mile	No	0 SEMS 1 SEMS-ARCHIVE
Corrective Action Reports	CORRACTS	1.0 mile	No	0
Federal Facility Site Information	FFSI	1.0 mile	No	0
Resource Conservation and Recovery Act - Treatment, Storage and Disposal Facilities	RCRA-TSD	0.5 mile	No	0
Resource Conservation and Recovery Act – Active and Former Hazardous Waste Generators	RCRA LQG/SQG/VSQG/ NonGen	Site & Adjoining	Yes - NonGen	11 LQG 5 SQG 2 VSQG 79 NonGen
Land Use Control Information System	LUCIS	0.5 mile	No	0
Engineering Control Sites	USEC	Site	No	0
Institutional Control Sites	USIC	Site	No	0
Emergency Response Notification System	ERNS	Site	No	0
Federal Brownfields Sites	US Brownfields	0.5 mile	No	0

In addition to the federal databases included on the table above, over 30 additional federal databases were searched to determine if the subject and/or surrounding properties were listed. The subject property was not listed on the additional federal databases included in the EDR search report and no adjacent or surrounding listings were identified with the potential to represent an environmental concern to the subject property.

The database search generated information on the following listings for the surrounding properties within ASTM radius guidelines that could potentially impact the subject property:

Superfund Enterprise Management System Archive (SEMS Archive): SEMS Archive (formally known as CERCLIS-NFRAP) listings are for properties removed from the SEMS list following an initial investigation because either no contamination was found, or contamination was not serious enough to warrant Superfund Action or NPL consideration. A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 09/19/2023 has revealed that there is 1 SEMS-ARCHIVE site within approximately 0.5 miles of the target property:

- Blatchford Base Plan, Site ID: 0201944 (EPA ID: NYD980531644). The site was identified as 32 33rd Street, approximately 2,279-feet (0.432 mile) north of the subject property at a lower elevation. The USPEA conducted a Preliminary Assessment, a Site Inspection and Removal Assessment for this site, and the site was subsequently archived. Based on the information provided in the database, its distance and the presumed hydraulic gradient, this listing is unlikely to present a significant environmental concern to the subject property.

Based on the information in the database report, its distance, and the presumed hydraulic gradient, it is unlikely that this listing represents a significant environmental concern to the subject property.

RCRA NonGen/NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste. A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/04/2023 has revealed that the target property was listed as a RCRA NonGen / NLR site:

- H&S Amoco, 4001 4th Avenue, EPA ID NY0000017582: The subject property was historically identified as a large quantity generator on January 1, 2007, and before that it was identified as a conditionally exempt small quantity generator on October 10, 1993. Hazardous waste codes D001 (Ignitable Waste), D018 (Benzene) and D039 (Tetrachloroethylene) were also identified.

RCRA Generators: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and

Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, dated 12/04/2023 has revealed that there is one (1) RCRA-LQG site within approximately 100-ft. of the target property.

- Consolidated Edison Inc – Service Box, 415 40th Street, EPA ID NYP004404968: The site is located approximately 97-feet east-northeast of the subject property at a higher elevation. The site was historically identified as a large quantity generator on March 23, 2014. NAICS Code 221122 (Electric power distribution) was found. No violations or evaluations were found for the site.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/04/2023 has revealed that there is one (1) RCRA-SQG sites within approximately 100-feet of the target property.

- NYC Department of Education, 4004 4th Avenue, EPA ID NYR000205674: The site is located approximately 46-feet north-northwest of the subject property at a lower elevation. The site was historically identified as a small quantity generator on November 26, 2013. NAICS Code 61111 (Elementary and Secondary Schools) was found. No violations or evaluations were found for the site.

A review of the RCRA-VSQG list, as provided by EDR, and dated 12/04/2023 has revealed that there are two (2) RCRA-VSQG sites within approximately 100-feet of the target property.

Based on the information in the database report, its distance, and the presumed hydraulic gradient, it is unlikely that this listing represents a significant environmental concern to the subject property.

6.2 State Databases

Listing Name or Database Searched	Abbreviation	Search Distance	Subject Property Listed?	No. of Sites within the Search Radius
Inactive Hazardous Waste Disposal Sites, including De-listed Sites	SHWS	1.0 mile	No	7 SHWS 0 Delisted SHWS
Vapor Intrusion Legacy Site List	VAPOR	1.0 mile	No	0
Hazardous Substance Waste Disposal Site	HSWDS	0.5 mile	No	2
Solid Waste Facilities/Landfill Sites	SWF/LF	0.5 mile	No	1
Registered Recycling Facility	SWRCY	0.5 mile	No	0

List				
Registered Waste Tire Storage Facility List	SWTIRE	0.5 mile	No	0
Leaking Underground Storage Tanks	LTANKS	0.5 mile	No	28 LTANKS
Petroleum Bulk Storage - Underground and Aboveground Storage Tank Databases	PBS UST/AST	Site & Adjoining	No	11 UST 25 AST 0 TANKS
Chemical Bulk Storage - Underground and Aboveground Storage Tank Databases	CBS UST/AST	0.25 mile	No	1 UST 1 AST
Major Oil Storage Facility - Underground and Aboveground Storage Tank Databases	MOSF UST/AST	Site & Adjoining	No	0
Registry of Engineering Controls	NYEC	Site	No	NA
Registry of Institutional Controls	NYEC	Site	No	NA
Voluntary Cleanup Agreements	VCP	0.5 mile	No	2
NY State Manifest	NY MANIFEST	0.25 mile	No	110
NJ State Manifest	NJ MANIFEST	0.25 mile	No	23
State Brownfields Site List	Brownfields	0.5 mile	No	2
US AIRS	Clean Air Act	TP	Yes	1
E-Designation Site List	E-Des	0.125 mile	1	5
Spills Information Database	NYSPILLS	0.125 mile	2	27
PFOA/PFOS Database	PFAS	0.25 mile	0	0
Registered Drycleaning Facilities	DRYCLEANERS	0.25 mile	No	0
EDR Historic Auto	Historic Auto repair Shop	0.125 mile	Yes	4

**LEG notes that according to ASTM E 1527-21, Section 8.1.2.1, the search distance may be reduced at the discretion of the environmental professional. The potential to impact the site, including LEG's decision to reduce the search distances, was based on several factors including, but not limited to: regulatory status by applicable agencies, medium impacted, distance from the site, historical use of the site and surrounding properties, estimated direction of groundwater flow, soil/geologic factors, urban setting, and other factors. In this case, there were no databases with reduced search distances.*

In addition to the New York State (NYS) databases included on the table above, over, ten additional NYS databases were searched to determine if the subject and/or surrounding properties were listed. The database search generated information on the following listings for the surrounding properties within ASTM radius guidelines that could potentially impact the subject property:

State Hazardous Waste Sites (SHWS): SHWS records are New York State's equivalent to the CERCLIS. These properties may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. These records come from the NYSDEC. One (1) SHWS listing was identified within a 100-feet radius:

- Sunset Car Care Site (ID No. 532551), 4013 4th Avenue, approximately 49-feet southwest and hydraulically cross-to upgradient of the subject property. This property has historically operated as an automobile garage, gas station, and car wash since 1926. Three (3) USTs were identified on the Sanborn maps and two (2) USTs (possibly removed) were identified on the 1926 Sanborn Map. A petroleum spill was recorded on August 9, 2015, during a Phase II Environmental Site Assessment through NYCOER Brownfield Program. VOCs were detected in both shallow and deep soil in the location of the two (2) former USTs identified on the 1926 Sanborn Map. The groundwater results indicated exceedances in petroleum constituents and metals, while tetrachloroethylene (PCE) was detected in soil vapor. A supplemental soil investigation was also conducted which did not identify any off-site impacts that would require monitoring or mitigation as per the NYSDOH guidance. The site designation was then changed from Class P (Potential) to Class N (No further action at this time).

Based on this information, its distance, the presumed hydraulic gradient, and the historical uses of this property, it is likely that this facility represents an environmental concern to the subject property and can be identified as a Recognized Environmental Condition (REC).

NY Hazardous Substance Waste Disposal Site (HSWDS): The List includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that

the study inventory has served its purpose and will no longer be maintained as a separate entity. The latest version of the study is frozen in time. The sites on the study will not automatically be made superfund sites, rather each site will be further evaluated for listing in the registry. So, overtime will be added to the registry or not. A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there are two (2) NY HSWDS site within approximately 0.25 miles of the target property:

- G&L Eyes Inc. (EPA ID: NYD042777128): the site was identified approximately 544-feet north of the subject property at a lower elevation, however, it stated that the site is not on the NYS Registry of Inactive Hazardous Waste Disposal Sites. No other details were reported.

Based on the information provided in the database report, their distance, and/or the presumed hydraulic gradient, this facility is unlikely to represent a significant environmental concern to the subject property.

Solid Waste Facilities/ Landfill Sites (SWF/LF): This database is an inventory of solid waste disposal facilities or landfills in New York State. One (1) SWF/LF listings was identified within a 0.5-mile radius of the subject property. These listing is summarized as follows:

- Big L Excavating & Demolition: This site is approximately 2,269-feet east-southeast and hydraulically upgradient of the target property. This facility is identified as a retired C&D (construction and demolition) processing facility with no violations.

Leaking Underground Storage Tanks (LTANKS): These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills A review of the NY LTANKS list, as provided by EDR, and dated 01/24/2024 has revealed that there are twenty (28) NY LTANKS sites within approximately 0.5 miles of the target property. Each of the twenty-eight (28) LTANKS sites listed in the database were issued letters of no further action by the NYSDEC, and there is no reported evidence in the database search which suggests that these sites are a significant environmental concern to the subject property. In addition, none of the properties with a listed closed LTANKS incident is located adjacent to the target property.

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data comes from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database. A review of the NY UST list, as provided by EDR, has revealed that there are eleven (11) NY UST sites within approximately 0.25 miles of the target property. the target property is also listed as a NY UST Site and the listing is summarized as follows:

- B&L Gas Station Enterprises, Inc., Site # 2-349399: The target property is listed with active UST status and has included tank information for four (4) 4,000-gallon USTs, which includes three (3) gasoline USTs and one (1) diesel UST. Two (2) gasoline USTs were installed on April 01, 1985, and one (1) gasoline UST and one (1) diesel UST were installed on April 01, 1989. Additionally, one (1) 280-gallon Aboveground Storage Tank (AST) used to store waste oil/used oil is also listed which was installed on April 01, 1989, and closed on October 06, 2008.

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data comes from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database. A review of the NY AST list, as provided by EDR, has revealed that there are twenty-five (25) NY AST sites within approximately 0.25 miles of the target property.

NY CBS UST: The Chemical Bulk Storage Database includes facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size A review of the NY CBS list, as provided by EDR, and dated 09/06/2023 has revealed that there is one (1) NY CBS site within approximately 0.25 miles of the target property.

NY CBS UST: The Chemical Bulk Storage Database includes registration data collected as required by 6 NYCRR Part 596. It includes facilities that store hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed. A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is one (1) NY CBS AST site within approximately 0.25 miles of the target property.

Voluntary Cleanup Program (VCP) Sites: VCP sites are those facilities where the property owner has to investigate and remediate the site. New York's VCP is a cooperative program for lenders, developers and prospective purchasers to investigate and/or remediate contaminated sites and return them to productive use. Under the VCP, a volunteer performs remedial activities pursuant to one or more NYSDEC approved work plans and agrees to remediate the site to a level that is protective of public health and the environment for the present or intended use of the property. Investigation and remediation are carried out under oversight of the NYSDEC, and the New York State Department of Health (NYSDOH) and the volunteer pays the State's oversight costs. Additionally, this database also includes NYCOER E-Designated sites that are investigated/remediated under the NYC VCP program. When the volunteer completes work, a release from liability from the NYSDEC/NYCOER is provided with standard reservations. A review of the NY VCP list, as provided by EDR, has revealed that there are two (2) NY VCP sites within approximately 0.5 miles of the

target property where one (1) site is in the Completed phase and one (1) site in the Closure Phase of the remediation program.

NYCDCP Environmental Designation Sites (E-DES): Environmental "E" designation sites are those sites identified by the NYC Department of City Planning (DCP), which need to be evaluated to address potential issues related to hazardous materials, air quality and/or noise. This designation is typically associated with areas NYC has designated for re-development and/or re-zoning, and ensure that sampling and remediation (if warranted) or other measures implemented at the property if demolition, excavation and construction are proposed to be conducted. A review of the NY E DESIGNATION list, as provided by EDR, and dated 07/26/2023 has revealed that there are three (3) NY E DESIGNATION sites within approximately 0.125 miles of the target property.

The adjoining property located at 4013 4th Avenue (Block 714 and Lot 1) at 49-feet southwest of the subject and hydraulically upgradient, has E-designation requirements for Hazardous Materials, Air Quality and Noise. The facility is currently used as a garage, gasoline filling station and carwash.

Based on the information in the database report, the distance of this property and the presumed hydraulic gradient, it is likely that this facility represents a significant environmental risk to the subject property.

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility. A review of the NY MANIFEST list, as provided by EDR, and dated 12/31/2019 has revealed that there are one hundred ten (110) NY MANIFEST sites within approximately 0.25 miles of the target property.

NJ MANIFEST: Hazardous waste manifest information. A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are twenty-three (23) NJ MANIFEST sites within approximately 0.25 miles of the target property.

New York Spills Information Database (NYSPILLS): NY Spills: Data collected on spills reported to NYSDEC is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date. A review of the NY Spills list, as provided by EDR, and dated 08/07/2023 has revealed that there are two (2) spills recorded on the target property and one (1) NY Spills site within approximately 100-feet of the target property:

- BP Gas Station, Site ID: 645074, NYSDEC Spill #2206825: According to the DEC notes, a spill was recorded on the target property on November 09, 2022, where a car ran over the equipment while

making delivery and approximately 5-gallon of gasoline was cleaned by the driver and attendant from asphalt. The spill was closed on November 16, 2022.

- Commercial facility at 4001-4011 4th Ave, Site ID: 582069, NYSDEC Spill #1811146: A spill was recorded on site on February 05, 2019, when contaminated soil was observed between 5 and 25 feet below grade during Phase-II investigation conducted by Castleton. The spill is not closed.
- Sunset Car Care Site, Site ID: 513543, NYSDEC Spill #1506140. The site is located approximately 49-feet southwest and hydraulically upgradient of the subject property. A Phase-II investigation test results depicted impacted soil, soil vapor and groundwater. Per the DEC Memo, a contaminated soil letter was sent to the owner of this property, but upon no response, the site was redesignated from Class P to Class N and the spill was closed on May 27, 2021.

A review of the information provided regarding the NYSPILLS listing, including the nature of the release, its distance, the presumed hydraulic gradient, and impact to groundwater, this spill is likely to represent an environmental concern to the subject property.

New York Brownfields List: In New York State, a Brownfields site is any real property in the State, whose redevelopment or reuse may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant, except those properties which are listed as Class 1 or 2 in the Registry of Inactive Hazardous Waste Disposal Sites (Class 2 sites owned by a Volunteer are eligible until July, 1, 2005); sites on the USEPA NPL; hazardous waste treatment, storage, or disposal facilities (TSDFs) permitted under ECL §27-0901 ("interim status" facilities are eligible); sites subject to a cleanup order or Stipulation under Article 12 of the Navigation Law (oil spill prevention, control, and compensation) or under Title 10 of ECL Article 17 (control of the bulk storage of petroleum); or sites subject to any on-going state or federal enforcement actions regarding solid/hazardous waste or petroleum. One (1) BROWNFIELDS sites were identified within a 0.25-mile radius of the subject property. This site is summarized as follows:

- NYC Department of Education – Public School 671K, 840 5th Avenue (NY Brownfields ID: S123159079): The site is located 1,182-feet east-northeast and hydraulically upgradient from the subject property. The historic uses of the site suggest presence of elevated train tracks and a train car repair shop, and after reconstruction, the current facility was used as a jewelry fabrication, garment assembly facility, night club, church and automobile sales and automobiles parts scrapping operations. The property was then developed as a school. The property is also listed in the PBS database, and given its historic uses, it was remediated. Prior to remediation, the primary contaminants of concern were SVOCs, VOCs, and metals in soil and groundwater, and chlorinated VOCs in soil vapor. The remedial actions successfully achieved Soil Cleanup

Objectives (SCOs) for Restricted Residential Use and the residual contamination is now managed under a Site Management Plan.

A review of the information provided regarding the NY BROWNFIELDS listing, including its distance, the presumed hydraulic gradient, and the remedial actions taken, this site is unlikely to represent an environmental concern to the subject property.

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns but may not show up in current government records searches.

- A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are three (3) EDR Hist Auto sites within approximately 0.125 miles of the target property. According to EDR data search, the subject property was occupied by an auto repair shop and auto body shop from 1971 through 2014. No further information is available.

6.3 Orphan Site Summary

The database report also includes nine (9)"orphan" sites, which are properties where due to poor or inadequate address information the location of the property cannot be determined sufficiently for it to be included on the radius map. However, sites with similar street names or zip codes are summarized in the database report as these sites may present environmental risks to the subject property. LEG reviewed additional information available from EDR regarding this site, as well as available USEPA and NYS data and maps to determine if the orphan sites present a significant environmental risk to the subject property. None of the listed Orphan sites appear to represent an environmental concern to the subject property.

7.0 SITE RECONNAISSANCE

7.1 Site Inspection

LEG representatives Dhanraj Singh, Katherine Espinoza and Dhruvi Patel inspected the subject property on February 21, 2024.

7.2 Methodology and Limiting Conditions

Site reconnaissance included a visual inspection of the building interior, exterior areas, cold storage room, the sidewalk area along 4th Avenue and 40th Street, and the exteriors of adjacent properties. However, the roof could not be accessed.

7.3 Site Description

The subject property consists of a single tax parcel located east of 4th Avenue, west of 5th Avenue, between 40th Street to the north, and 41st Street to the south in the Sunset Park section of the borough of Brooklyn in the City of New York. The subject property is identified as Block 714 – Lot No. 6 on the New York City (NYC) tax maps.

The subject property is a single 10,017-square feet tax parcel that is currently developed with a gasoline filling station with a 1-story convenience store and parking. The gross floor area of the building is 1,860-square feet. The building occupies approximately 20% of the site footprint, and the remaining area is utilized as an asphalt-paved gasoline filling station and parking lot. The subject property is accessible from the western side of 4th Avenue and southern side of 40th Street. Street sidewalks are identified to the west along 4th Avenue and east along 40th Street of the property.

The building is currently operated by BP Gas Station and is developed with a gasoline filling station with a one-story convenience store and parking lot. The building was constructed in at least 1970 with a concrete brick structure and was altered in 1985. The current building was found to be constructed with concrete masonry unit (c.m.u.) and concrete columns during site inspection. All the areas of the property were accessed; however, the roof could not be accessed. Currently, there are four (4) 4,000-gallon active USTs which includes three (3) gasoline USTs and one (1) diesel UST on the subject property, registered as PBS #2-349399 with registration expiration date of September 08, 2028. The tanks are equipped with an automatic overfill monitoring system, secondary spill containment and interstitial leak detection system.

Upon inspecting the property, an electric box was identified at the south of the property on the exterior wall and a Consolidated Edison Inc manhole was also found on the sidewalk near the entrance of the property along 40th Street. Three (3) pump islands were located in the center of the property, with two (2) of them

closer to 4th Avenue and one (1) closer to the convenience store. Access with manholes for four (4) active USTs, interstitial monitoring and monitoring wells were located on the southwest of the property between pump islands the adjacent property. Three (3) gasoline and one (1) diesel vent lines for these USTs were located adjacent to the USTs, fixated on the wall of the adjoining property. No signs of spills or stains were identified. Three (3) waste dumpsters and two (2) drums, of which one (1) was damaged were identified on the southwest of the property near vent lines. A 95-gallon secondary containment drum was identified in the parking lot closer to the wall of the convenience store. Three (3) used tires were also identified in the parking lot.

Upon inspecting the convenience store, a cold storage room, a kitchen, racks and restrooms were identified. The exhaust units for HVAC and compressor were located on the roof.

7.4 Utilities

Based upon information provide to LEG and/or obtained during the site inspection, the following is a table of utilities supplied to the subject property and the names of the suppliers:

Utility	Provider
Domestic Water	New York City Department of Environmental Protection (NYCDEP)
Sanitary Sewer	NYCDEP
Storm Sewer	NYCDEP
Electricity	Con Edison
Natural Gas	Natural Grid

7.5 Surrounding Land Use

The subject property is located in a densely developed, mixed-use urban area of Sunset Park, Brooklyn. The following surrounding land uses were observed during the Phase I ESA site inspection:

DIRECTION	ADJOINING USE(S)	VICINITY USE(S)
North	Attached commercial and residential buildings. • Along 4th Avenue	Residential
South	Attached commercial and residential buildings, and a School. • Along 41st Street	Mixed-use
East	Attached residential buildings. • Along 40th Street	Residential
West	Attached residential and commercial buildings. • Along 41st Street	Mixed-use

Surrounding properties are used for mainly commercial and residential purposes; industrial properties were identified within a one-mile radius.

7.6 Interviews

A User Questionnaire was sent and Shia Lefkowitz, the owner of the property filled it and provided with the information.

7.7 Summary of Environmental Site Features

7.7.1 Chemical Use and Storage

Typical household cleaning and maintenance chemicals were observed within the restroom in the convenience store. Unopened cleaning agents, anti-freeze, automobile oils and other typical products were identified on the racks within the convenience store which is normal for a store near a gas station. The on-site storage of these substances is not a REC. No evidence of oil spills/staining was observed.

7.7.2 Hazardous and Non-Hazardous Waste Storage and Disposal

No evidence that regulated hazardous materials and/or hazardous wastes are generated, treated, stored, or disposed of at the site was observed on the date of the survey.

- Solid wastes and recyclables generated on the property are stored in three (3) dumpsters identified on the southwest of the subject property. The garbage disposal service was provided by Mr. T Carting (BIC #173). No evidence of staining or liquid waste was observed around the dumpsters. Two (2) drums were also identified near these dumpsters, of which one (1) was damaged and needs to be disposed of legally from the subject property. This damaged drum represents a De Minimis condition.

No other environmental conditions, associated with solid waste generation, storage, and disposal were identified on the subject property during the reconnaissance.

7.7.3 Underground and Aboveground Storage Tanks

The site building was heated and supplied with electricity. Heating, ventilation, and air conditioning (HVAC) equipment was located atop the building roof.

Four (4) 4,000-gallon USTs including three (3) gasoline USTs and one (1) diesel UST were identified on the subject property. These tanks are registered as PBS #2-349399 with registration expiration date of September 08, 2028. The tanks were equipped with an automatic overfill monitoring system, secondary spill containment and interstitial leak detection system. No spills/leaks were identified in the vicinity of the UST. No RECs are associated with the on-site USTs due to proper condition and maintenance.

Additional information may be available in files maintained by the FDNY, NYCDEP and/or NYCOER, however, no responses to LEG's FOIL requests have been received to date. Any information received from these agencies will be reviewed upon receipt and pertinent information forwarded to the client.

7.7.4 Sanitary and Stormwater Disposal

The subject property is serviced by the NYC municipal sewer system. Storm drains and floor drains that discharge directly to subsurface soils pose a potential environmental concern because they provide a pathway for impacts to the subsurface and are classified as Class V injection wells under the USEPA's Underground Injection Control (UIC) program. These structures are required to be properly closed or permitted to stay open.

- One (1) floor drain leading to the storm drain was identified near the parking lot. Curbside drains reportedly discharge to the municipal sewer system and were identified along 40th Street. The floor drains reportedly discharge to the New York City municipal sewer system, which is consistent with the presence of subgrade piping observed during the site inspection. As such, the drains would be exempt from UIC Program regulations. No chemicals are stored near the floor/trench drains. No significant staining, corrosion, odors or other evidence of potential environmental impairment was observed around the floor/trench drains.

7.7.5 Polychlorinated Biphenyls

Polychlorinated biphenyls (PCBs) were used until 1978 and are a group of compounds formed by the chlorination of biphenyl. PCBs have extremely high physical and chemical stabilities which led to their being used in many applications, including heat transfer fluids, hydraulic fluids, and dielectrics. PCBs are often found in transformers, capacitors and hydraulic systems.

Electrical equipment containing PCBs are still in use and can pose a serious health hazard if fluids come in direct contact with humans, soil or groundwater. Fires involving electrical equipment containing PCBs can cause the material to be dispersed over a large area and potentially expose many people to a health risk. Because of the health hazard associated with PCBs, they are regulated under the Toxic Substances Control Act (TSCA).

No hydraulic automotive lifts, electrical transformers, hydraulic elevators, or other equipment suspected to contain PCBs were identified within the building on the subject property at the time of the site inspection.

7.7.6 Debris, Dumping and Surficial Staining

No evidence of chemical spills or stains was observed on the property at the time of the site inspection, except for de minimis strong odors associated with oil and asphalt burning were observed in the area, consistent with the traffic and road construction. Based on the review of historical and regulatory records, no evidence of landfills, and/or direct burial activities was observed on or proximate to the subject property. However, as the central and northwestern portions of the property were previously developed with a service station, there is a

potential for fill materials to be present. As no information regarding the nature or source of the fill materials was available for review, there is a potential for contaminated and/or structurally unsuitable fill materials to be present on site. The potential presence of fill materials is considered a BER.

7.7.7 Stressed Vegetation

No stressed vegetation was present at the time of inspection.

7.7.8 Other Environmental Concerns

LEG also inspected the subject property for evidence of the following potential environmental concerns:

OTHER AREAS OF CONCERN		
Area of Concern	**Not Observed**	**Observed**
Chemical/Petroleum Odors		X
Pools of Liquid	X	
Stains or Corrosion	X	
Unidentified Containers	X	
Pits, Ponds, or Lagoons	X	
Monitoring or Other Wells		X
Stained Soil or Pavement	X	
Air Quality	X	
Stressed Vegetation	X	

Monitoring or Other Wells

The site inspection identified monitoring wells surrounding the USTs that are usually installed for monitoring of subsurface conditions around the USTs for presence of gasoline or diesel contamination. Two (2) monitoring wells, potentially from previous investigations were also found in the west and northwest of the property along 4th Avenue.

8.0 NON-SCOPE CONSIDERATIONS

8.1 Radon

Radon is a colorless, radioactive, inert gas formed by the decay of radium and may be present in soils and rocks containing granite, shale, phosphate and pitchblende. The USEPA's Map of Radon Zones for New York State, September 1993, indicates that the Queens area is not a radon risk area. The EDR report provides information from the New York State Department of Health (NYSDOH) radon survey which indicates that 81 radon tests have been conducted in Kings County. Test results indicate average radon concentrations of 0.620 pCi/L (living area) and 0.970 pCi/L (basements). Data indicate that approximately 6% of basements tested showed results in excess of the 4.0 pCi/L USEPA action level.

The Federal EPA Radon Zone for Kings County is 3, which indicates that the indoor average level of Radon is likely to be less than 2 pCi/L. Based on the data, radon is not likely to represent an environmental concern for the subject property.

8.2 Lead-Based Paint

In 1978, the U.S. Product Safety Commission issued a ban on paints or surface coatings that contain greater than 0.06 percent lead. A visual inspection of painted surfaces conducted during the site inspection indicated that interior paint within the building was in fair to good condition Paint within the office spaces were generally in good condition. The building exterior walls were finished with paint and appeared to be in good condition. The lead content of the paints is unknown, hence, possible presence of lead-based paint is not a business environmental risk (BER). The disposal of lead paint waste resulting from renovation or demolition activities may be subject to federal and State regulations.

8.3 Asbestos-Containing Materials

Asbestos is the name given to a group of fibrous silicate minerals, typically those of the serpentine group. The tensile strength, flexibility, and non-flammability of asbestos have led to many uses including structural materials, brake linings, insulation, and pipe manufacture. Asbestos is of concern as an air pollutant because when inhaled it may cause asbestosis, mesothelioma, and bronchogenic carcinoma. In 1989, the USEPA announced regulations that would phase out most uses of asbestos by 1996.

As part of the site inspection, a visual survey was conducted of accessible areas for the presence of suspect asbestos-containing materials (ACM). Suspected asbestos-containing non-friable pipe insulation (approx. 5-feet in length) was identified in the basement hallway ceiling (near the electrical room) and within the emergency generator panel room. These materials were generally in good to fair condition and the materials were not sampled to avoid needlessly damaging them. Additionally, due to the age of the building, it is

possible that roofing, roof flashing, caulking putties, construction mastics, and other (inaccessible) building materials contain asbestos. No sampling of suspect ACMs was conducted in coordination with this Phase I ESA.

As part of the site inspection, a visual survey was conducted of accessible areas for the presence of suspect ACMs. No friable asbestos-containing surfacing, spray-on or thermal system insulation materials were observed in the areas inspected on site. LEG observed non-friable vinyl floor tile and ceilings. These materials were in generally good to fair conditions, except for a few water-stained ceiling tiles. No sampling was conducted of any materials in coordination with this Phase-I ESA.

Thermal insulation, surfacing materials, and vinyl/asphalt floor materials installed before 1981 are presumed to contain asbestos. The Occupational Safety and Health Administration (OSHA) asbestos standards (effective October 1995) require owners of commercial or industrial buildings (constructed before 1981) to identify potential asbestos hazards, keep records about potential asbestos hazards, post signs to warn of asbestos hazards, and communicate information about the hazards.

8.4 Wetlands

A review of the NYSDEC Freshwater Wetland Map, Brooklyn, NY Quadrangle, indicated that there are no NYS freshwater wetlands located within a one-mile radius of the subject property.

Tidal wetlands line much of the saltwater shore, bays, inlets, canals, and estuaries of Long Island and New York City, and Westchester County. The tidal wetlands regulations apply anywhere tidal inundation occurs on a daily, monthly or intermittent basis, including but not exclusively within the salt wedge. Vegetation in intertidal areas beyond the range of the salt wedge is classified as coastal fresh marsh. In accordance with the New York State Tidal Wetlands Land Use Regulations (6 NYCRR Part 661), sixteen wetland categories are defined in the regulations. Coastal and tidal freshwater wetlands categories are identified by the presence of a tide and the types of vegetation present. The categories of wetlands and the restrictions placed on activities in and around them are defined in detail in 6 NYCRR Part 661.

LEG also reviewed NYSDEC Tidal Wetlands Maps available online via the NYS GIS website. The tidal wetlands map (No. 582-500) showing the subject and surrounding properties indicates that Upper New York Bay located approximately one-quarter mile west-northwest of the subject property is classified as Littoral Zone (LZ) tidal wetlands. LZ wetlands are defined as the tidal wetland zone that includes all lands under tidal waters which are not included in any other category. There shall be no LZ under waters deeper than six (6) feet at mean low water.

Potential federal wetlands were identified from the U.S. Fish and Wildlife Service (FWS) Wetlands Mapper software, which indicates that the nearest potential federal wetlands are located approximately 0.5-mile to the northwest and 0.5-mile to the north of the subject property.

Federal Emergency Management Agency (FEMA) Flood Insurance Rate Maps (FIRMs) were reviewed to determine if the subject properties are located within the 100-year or 500-year flood zones. The FIRM depicted the property on No. 3604970194F section and are not located within the 100-year flood zone.

8.5 Mold and Water Damage

Concern about indoor exposure to mold has been increasing as the public becomes aware that exposure to mold can cause a variety of health effects and symptoms, including allergic reactions. Molds can be found almost anywhere; they can grow on virtually any organic substance, as long as moisture and oxygen are present. There are molds that can grow on wood, paper, carpet, foods, sheetrock, plaster and insulation. When excessive moisture accumulates in buildings or on building materials, mold growth will often occur, particularly if the moisture problem remains undiscovered or unaddressed.

As part of this assessment, a visual inspection was conducted for the presence of water damage and odors, indicative of the potential for mold growth. Minor water stains were identified on the ceiling within the convenience store; and no active water leaks or visible mold growth were observed within the convenience store on the subject property.

8.6 Vapor Encroachment

As part of this assessment, LEG evaluated the potential for vapor encroachment into onsite structures following the general methodology outlined in ASTM E-2600-15 utilizing professional judgment. The Tier 1 screening assessment was employed to determine if a potential vapor encroachment condition (VEC) exists at the site. The site, adjoining properties and hydraulically upgradient properties were assessed for known or suspected contaminated facilities within approximate minimum search distances. A Tier 1 screening assessment generally consists of the following: a search distance test to identify if there are any known or suspected contaminated sites within the area of concern (AOC); a chemicals of concern (COC) test to determine if chemicals of concern exist at the known or suspected contaminated facilities and a plume test to determine whether or not COC in the contaminated plume may be within the critical distance (or AOC). The critical distance is defined as the linear distance in any direction from the nearest edge of the plume to the site. If the critical distance from the site to the nearest edge of a petroleum hydrocarbon plume is within 528 feet (1/10-mile) or within 1,760 feet (1/3-mile) for nonpetroleum COC (e.g., trichloroethylene, perchloroethylene, etc.), then it is assumed that COC are within the AOC and a potential VEC exists, and additional screening

may be necessary. The critical distance and AOC may be modified using professional judgment based on hydraulic gradient direction and contaminant plume width.

The decision to recommend additional screening, even if a potential VEC is determined by distance, is based on other criteria including existing and planned use of the property, type of structures potentially impacted, physical setting, hydraulic gradient, depth to groundwater, soil characteristics, activities in the surrounding area and the presence of natural or manmade conduits.

- Based on an evaluation of this collective criteria, the potential for a VEC from current and historic land use activities at the subject and surrounding properties is considered moderate to high due to long term use of the site and adjacent properties as gasoline filling station, auto repair and car wash. As well as the documented soil, groundwater and soil vapor impacts on the subject property and adjacent property (at southwest on 4th Avenue). Although the site building is utilized for commercial purposes, the subsurface conditions of the subject should be further evaluated.

9.0 CONCLUSIONS AND RECOMMENDATIONS

This Phase I ESA has been prepared in conformance with the scope and limitations of ASTM Practice E1527-21 (inclusive of the USEPA all appropriate inquiry requirements) for the commercial property located with 4th Avenue on the northwest and 5th Avenue on the southeast, between 40th Street to the northeast, and 41st Street to the southwest in the Sunset Park section of the Brooklyn borough, New York City, New York. The subject property is identified by the street address of 4001 4th Avenue, , and as Block 714 – Lot No. 6 on the New York City (NYC) tax maps. Any exceptions to, or deletions from, this practice are described in the section of the report entitled Limitations and Exceptions.

Based on the results of LEG's site inspection and records review, it was determined that the following RECs were identified for the subject property, which are summarized as follows:

- Information obtained from multiple historic sources revealed that the subject and multiple adjacent/surrounding properties were historically utilized as gasoline filling stations, auto repair and car wash. The previous environmental subsurface investigations have also indicated impacted subsurface conditions due to the historic uses of the subject property as well as the adjacent/surrounding properties. Thus, LEG considers the historic use of the subject property and adjacent properties to be a REC.
- During the review of 1926 Sanborn maps, a gasoline UST was identified in the northern portion of the subject property. Since the status of the UST is unknown because of lack of documentation, LEG considers this as a REC.
- A geophysical investigation conducted by Castleton identified nine (9) suspected USTs in the western section of the subject property. This study is supported by previous environmental investigations that indicated impact on soil, soil vapor and groundwater. As no documentation regarding the status of these suspected tanks and/or soil conditions in its vicinity were available for review, there is a potential for spills or releases from these tanks to have impacted the subsurface. Therefore, the suspected USTs are considered a REC.
- One (1) open spill (Spill #18-11146) is recorded on the subject property. This spill was recorded as a result of VOCs being detected above SCOs in soil during Phase-II Environmental Site Assessment conducted by Castleton. Since the subject property was not remediated and the spill is not closed, LEG considers this a REC.
- A spill was recorded on the adjacent property identified to the southwest as Sunset Car Care along 4th Avenue and the DEC Memo suggests that no delineation or remediation was conducted, however, the

spill was closed due to lack of response from the owner. This indicated that the contamination is left is place and LEG considers this a REC.

LEG identified the following environmental concerns/Business Environmental Risks (BER) and a De Minimis condition that are summarized as follows:

- A metallic anomaly non-indicative of a UST was identified in the northern portion of the subject property during Castleton's geophysical investigation. Given the historic use of the subject property as an auto service station with a loading area, the anomaly can possibly be a buried hydraulic lift and LEG considers this as a BER.
- The central and northwestern portions of the property were previously developed with a service station, so there is a potential for fill materials to be present. As no information regarding the nature or source of the fill materials was available for review, there is a potential for contaminated and/or structurally unsuitable fill materials to be present beneath the subject property. The potential presence of fill materials is considered a BER.
- Minor water staining was observed on the ceiling of the one-story building. No active water leaks or visible mold growth were observed within convenience store. The water-damaged areas identified should be removed from the building and properly disposed. LEG considers this a BER.
- Solid wastes and recyclables generated on the property are stored in three (3) dumpsters identified on the southwest of the subject property. The garbage disposal service was provided by Mr. T Carting (BIC #173). No evidence of staining or liquid waste was observed around the dumpsters. Two (2) drums were also identified near these dumpsters, of which one (1) was damaged and needs to be disposed of legally from the subject property. This damaged drum represents a De Minimis condition.

Based upon the above findings and conclusions, LEG recommends the following:

- The unregistered nine (9) USTs should be officially registered with New York State Department of Environmental Conservation (NYSDEC) Petroleum Bul Storage (PBS) Unit and closed with proper tank closure procedures as promulgated by the NYSDEC and New York City Fire Department (FDNY).
- To further evaluate the potential impacts related to the historic uses of the subject property and the spill on the subject property and from adjacent property, a subsurface investigation should be conducted by installation of soil borings and collection of representative soil, groundwater, and soil vapor samples. Further subsurface assessments are warranted to include laboratory analysis of the samples to determine the nature and extent of subsurface contamination.
- The contaminated areas should be further remediated to achieve acceptable Soil Cleanup Objectives.

The site reconnaissance, interviews and review of records have identified the presence or possible presence of hazardous substances or petroleum related products in, on, or at the Subject Property due to onsite and offsite release to the environment. Additionally, the subject property is identified as an E-Designation site requiring further evaluation of air quality and Hazardous Materials Phase I and Phase II Testing Protocol. LEG recommends that any future redevelopment of the subject property to be done must comply under the oversight of the NYC Office of Environmental Remediation (OER) to ensure that the E-Designation listing is properly addressed.


10.0 ENVIRONMENTAL PROFESSIONAL STATEMENT

This Phase I ESA has been prepared in accordance with procedures established by environmental professionals and in concert with the guidance of regulatory agencies and funding institutions, ASTM Practice E1527-21, inclusive of the USEPA "All Appropriate Inquiry" requirement published in the Federal Register on November 1, 2005. The USEPA "All Appropriate Inquiry" requirement establishes specific regulatory requirements for conducting all appropriate inquiries into the previous ownership, uses, and environmental conditions of a property for the purposes of qualifying for certain landowner liability protections under CERCLA.

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in § 312.10 part of 40 CFR 312. I have the specific qualifications based on education, training, and experience to assess a property of the nature, history and setting of the site referenced above. LEG has developed and performed the "All Appropriate Inquiries" in conformance with the standards and practices set forth in 40 CFR Part 312.

Section 11.0 contains the data gaps and deficiencies of the research data encountered during LEG's preparation of this report.

Prepared by,



Dhruvi Patel
Project Manager

Reviewed by,



Theodore Yen, P.E.
Sr. Project Manager

Reviewed by,



Danny Singh
Sr. Project Manager

Submitted by,



Sam Rosenbaum
Managing Director

11.0 REFERENCES

Environmental Data Resources, Inc. Radius Map (No. 7526965.2s), February 16, 2024.

Environmental Data Resources, Inc. Sanborn Map Report (7526965.3), February 18, 2024.

Environmental Data Resources, Inc. City Directory Search (7526965.5), February 16, 2024.

Environmental Data Resources, Inc. Topographic Map Search (7526965.4), February 16, 2024.

Environmental Data Resources, Inc. Aerial Photograph (7526965.11), February 20, 2024.

Environmental Data Resources, Inc. Property Tax Map Report (7526965.6), February 16, 2024.

Environmental Data Resources, Inc. Environmental Lien and AUL Search (7526965.7), February 20, 2024.

Environmental Data Resources, Inc. Building Permit Report (7526965.8), February 16, 2024.

New York City Department of Environmental Protection, Freedom of Information request forwarded February 2024.

New York City Office of Environmental Remediation, Freedom of Information request forwarded December 2023.

New York City Building Department records on-line review February 2024.

U.S.G.S. Topographic Map, Brooklyn, NY Quadrangle.

U.S. Department of the Interior, Fish and Wildlife Service. National Wetlands Inventory Maps.

United States Department of Agriculture, Web Soil Survey.

NYSDEC Tidal Wetlands Maps (No. 582-500) on-line review February 2024.

USFWS Wetlands Mapper on-line review February 2024.

Federal Emergency Management Agency (FEMA) Flood Insurance rate Maps No. 3604970194F

FIGURES




FIGURE 1 – PROPERTY LOCATION MAP

N

SITE NAME: Commercial Property

STREET ADDRESS: 4001 4th Avenue (a.k.a., 410 40th Street)

MUNICIPALITY, STATE, ZIP: Brooklyn, NY 11232

Lesova




FIGURE 3 – PROPERTY ZONING MAP

N

SITE NAME: Commercial Property

STREET ADDRESS: 4001 4th Avenue (a.k.a., 410 40th Street)

MUNICIPALITY, STATE, ZIP: Brooklyn, NY 11232

Lesova



FIGURE 2 – PROPERTY TAX MAP

N

SITE NAME: Commercial Property

STREET ADDRESS: 4001 4th Avenue (a.k.a., 410 40th Street)

MUNICIPALITY, STATE, ZIP: Brooklyn, NY 11232

Lesova

PHOTOS

PHOTO LOCATION: Depicts the gasoline filling station on the subject property with a one-story convenience store.



PHOTO LOCATION: Depicts adjacent property to the south identified as Sunset Auto repair & Car wash.



PHOTO LOCATION: Depicts the surrounding properties at the northeast to the subject property.



PHOTO LOCATION: Depicts the adjacent property to the east on 40th Street.



PHOTO LOCATION: Depicts the residential buildings along 40th Street.



PHOTO LOCATION: Depicts the public school across from the subject property on 4th Avenue.



PHOTO LOCATION: Depicts the paved parking area adjacent to the convenience store on the subject property.




PHOTO LOCATION: Depicts the manhole covers of the four (4) USTs.



PHOTO LOCATION: Depicts three (3) pump islands on the subject property.



PHOTO LOCATION: Depicts electric maintenance manhole cover near the northern entrance of the subject property on the sidewalk along 40th Street.



PHOTO LOCATION: Depicts locations of four (4) USTs, two (2) 55-gallon drums, three (3) dumpsters, four (4) gasoline vent pipes and



LOCATION: Depicts two (2) 55-gallon drums of non-hazardous waste including one (1) damaged drum.



LOCATION: Depicts a monitoring well from previous investigation on the subject property along 4th Avenue.



LOCATION: Depicts a monitoring well from previous investigation on the subject property near the adjacent property line.



LOCATION: Depicts containers of automotive oil, antifreeze and other products related to automotive maintenance on the racks within the convenience store.




PHOTO LOCATION: Depicts minor water staining within the convenience store.



PHOTO LOCATION: Depicts storm trough in the parking lot within the subject property.



PHOTO LOCATION: Depicts used tires in the parking lot within the subject property.



PHOTO LOCATION: Depicts H-5067 overpack drum in the parking lot within the subject property.



PHOTO LOCATION: Depicts electricity box on the wall of the convenience store along 40th Street.



APPENDIX A - EDR Radius Map

4001 4th Avenue
4001 4th Avenue
Brooklyn, NY 11232

Inquiry Number: 7571432.2s
February 16, 2024

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	9
Orphan Summary	1053
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings	A-8
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2024 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

4001 4TH AVENUE
BROOKLYN, NY 11232

COORDINATES

Latitude (North):	40.6517170 - 40° 39' 6.18''
Longitude (West):	74.0066180 - 74° 0' 23.82''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	583986.1
UTM Y (Meters):	4500358.5
Elevation:	51 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14317809 JERSEY CITY, NJ
Version Date:	2019
Northeast Map:	14115940 BROOKLYN, NY
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20190830
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
4001 4TH AVENUE
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	B & L GAS STATION EN	4001 4TH AVENUE	FINDS		TP
A2	B & L GAS STATION EN	4001 4TH AVENUE	NY AST		TP
A3	BP GAS STATION	4001 4TH AVE	NY Spills		TP
A4	AMOCO-FOURTH AVE	4001-4011 FOURTH AVE	FINDS, ECHO		TP
A5	AMOCO-FOURTH AVE	4001-4011 4TH AVE	US AIRS		TP
A6	ALMANZAR INC	4001 4TH AVE	EDR Hist Auto		TP
A7	B & L GAS STATION EN	4001 4TH AVENUE	UST FINDER		TP
A8	COMMERICAL	4001-4011 4TH AVE	NY Spills		TP
A9	LOT 6,TAXBLOCK 714	4001 4 AVENUE	NY E DESIGNATION, NY NYC LAND USE		TP
A10	H & S AMOCO	4001 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO		TP
A11	B & L GAS STATION EN	4001 4TH AVENUE	NY UST		TP
A12	CON EDISON - SERVICE	412 40 ST	NY MANIFEST	Higher	1 ft.
A13	MANHOLE 4084	40TH ST/4TH AVE	NY Spills	Lower	48, 0.009, NNW
A14	SUNSET CAR CARE SITE	4013 4TH AVENUE	NY SHWS, NY Spills	Higher	49, 0.009, SW
A15	4013 CAR CARE	4013 4TH AVENUE	NY AST	Higher	49, 0.009, SW
A16	BORIS AUTO REPAIR	4013 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	49, 0.009, SW
A17	BATAN TOWING SERVICE	4013 4TH AVE	EDR Hist Auto	Higher	49, 0.009, SW
A18	LOT 1,TAXBLOCK 714		NY E DESIGNATION	Higher	49, 0.009, SW
A19	LOT 1,TAXBLOCK 714	4013 4 AVENUE	NY E DESIGNATION, NY NYC LAND USE	Higher	49, 0.009, SW
A20	CON EDISON SERVICE B	420 40TH ST	RCRA NonGen / NLR, FINDS	Higher	60, 0.011, ESE
A21	CON EDISON	420 40TH ST	NY MANIFEST	Higher	60, 0.011, ESE
A22	VM REALTY 8 LLC	417-441 40 STREET	NY AST	Higher	87, 0.016, ENE
A23	I.S. 136 - BROOKLYN	4004 4TH AVE	NY AST	Lower	96, 0.018, NW
A24	CON EDISON	415 40TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	97, 0.018, ENE
A25	CON EDISON - SERVICE	415 40 ST	RCRA-LQG, NY MANIFEST	Higher	97, 0.018, ENE
A26	CON EDISON	415 40TH ST	NY MANIFEST	Higher	97, 0.018, ENE
A27	CON EDISON	415 40TH ST	NJ MANIFEST	Higher	97, 0.018, ENE
A28	NYC DEPT OF EDUCATIO	4004 4TH AVE	RCRA-SQG, FINDS, ECHO	Lower	100, 0.019, NNW
A29	ROADWAY	4TH AVE & 41ST STREE	NY Spills	Higher	141, 0.027, WSW
A30	MANHOLE 45501	4TH AVE/41ST ST	NY Spills	Higher	141, 0.027, WSW
A31	MANHOLE #4049	SW CORN. 41ST & 4TH	NY Spills	Higher	141, 0.027, WSW
A32	MANHOLE 73170	4TH AVE AND 41ST ST	NY Spills	Higher	141, 0.027, WSW
A33		444 40 STREET	NY Spills, NY NYC LAND USE	Higher	173, 0.033, SE
A34	CON EDISON	F/O 3907 4TH AVE	NY MANIFEST	Lower	182, 0.034, NE
A35	LOT 42,TAXBLOCK 708	3918 4 AVENUE	NY E DESIGNATION, NY NYC LAND USE	Lower	188, 0.036, NNW
A36	LOT 6,TAXBLOCK 719	4111 4 AVENUE	NY E DESIGNATION, NY NYC LAND USE	Higher	208, 0.039, SW
B37	CON EDISON	424 41ST ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	208, 0.039, South
B38	CON EDISON	424 41ST ST	NY MANIFEST	Higher	208, 0.039, South
B39	CON EDISON	424 41ST ST	NJ MANIFEST	Higher	208, 0.039, South

MAPPED SITES SUMMARY

Target Property Address:
4001 4TH AVENUE
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
C40	CONSOLIDATED EDISON	MH49287-444 40TH ST	NY MANIFEST	Higher	219, 0.041, ESE
D41	366 41ST ST	366 41ST ST	NY AST	Lower	254, 0.048, West
E42	MANHOLE 73167	39TH STREET & 4TH AV	NY Spills	Lower	264, 0.050, NNE
E43	VAULT 6035	39TH STREET & 4TH AV	NY Spills	Lower	264, 0.050, NNE
E44	SERVICE VAULT 6035	39TH ST/4TH AVE	NY Spills	Lower	264, 0.050, NNE
E45	V# VS6058	39TH STREET & 4TH AV	NY Spills	Lower	289, 0.055, NNE
F46	FRED ALIMONDA	357 40TH STREET	UST FINDER	Lower	300, 0.057, NNW
F47	FRED ALIMONDA	357 40TH STREET	NY UST	Lower	300, 0.057, NNW
F48	FRED ALIMONDA	357 40TH STREET	NY LTANKS	Lower	300, 0.057, NNW
E49	366 39 REALTY LLC	366 39TH STREET	NY AST	Lower	308, 0.058, North
B50	444 41ST STREET	444 41ST STREET	NY Spills	Higher	321, 0.061, SSE
C51	CON EDISON	454 40TH ST	NY MANIFEST	Higher	338, 0.064, SE
C52	CON EDISON	454 40TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	338, 0.064, SE
D53	APARTMENT BUILDING	358 41ST STREET	NY AST	Lower	354, 0.067, West
E54	MOBIL S/S F7FYG C&M	987-993 4TH AVENUE	NY UST	Lower	362, 0.069, NE
E55	DLJ ENTERPRISES	987 4TH AVENUE	EDR Hist Auto	Lower	362, 0.069, NE
E56	MOBIL S/S	987 4TH AVE	NY LTANKS	Lower	362, 0.069, NE
E57	MOBIL S/S F7FYG C&M	987-993 4TH AVENUE	UST FINDER	Lower	362, 0.069, NE
E58	MOBIL S/S	987 4TH AVE	UST FINDER RELEASE	Lower	362, 0.069, NE
E59	CON EDISON	423 39 ST	NY MANIFEST	Higher	364, 0.069, ENE
D60	CON EDISON SERVICE B	354 41ST ST FRONT OF	RCRA NonGen / NLR, NY MANIFEST	Lower	388, 0.073, West
D61	CON EDISON	OPP 354 41 ST	NY MANIFEST	Lower	388, 0.073, West
D62	SUNSET HEIGHTS, L.P.	354 41ST STREET	NY AST	Lower	388, 0.073, West
D63	4201 4TH AVE/B'KLYN/	4201 4TH AVE	NY Spills	Higher	390, 0.074, SW
C64	SERVICE BOX 48297	459 41ST ST	NY Spills	Higher	393, 0.074, SE
D65	MANHOLE 4045	4TH AVE/42ND ST	NY Spills	Higher	399, 0.076, SW
D66	4112 4TH AVE LLC	375 42ND STREET	NY AST	Higher	406, 0.077, WSW
C67	CLEAN RITE CLEANERS	442 39TH ST	EDR Hist Cleaner	Higher	407, 0.077, East
E68	USPS	1050 FOUR BELL ST	NY Spills	Lower	410, 0.078, NNE
G69	J. KEVIN O'CONNOR	460 41 STREET	NY AST	Higher	444, 0.084, SSE
F70	CON EDISON MANHOLE:	346 39TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	446, 0.084, NNW
F71	CON EDISON MANHOLE:	346 39TH ST	NJ MANIFEST	Lower	446, 0.084, NNW
D72	NYC DEPT OF ED - PS	4222 4TH AVE	RCRA-SQG, NY LEAD, NY MANIFEST, NJ MANIFEST	Higher	459, 0.087, SW
C73	CON EDISON	467 40TH ST	NY MANIFEST	Higher	470, 0.089, ESE
H74	CON EDISON	449 39 ST	NY MANIFEST	Higher	470, 0.089, East
I75	CON EDISON - MANHOLE	476 40TH ST	RCRA-LQG	Higher	505, 0.096, SE
I76	CON EDISON	476 40TH ST	NY MANIFEST	Higher	505, 0.096, SE
J77	PS # 24	38TH STREET AND 4TH	NY Spills	Lower	536, 0.102, NE
F78	341 39TH ST/BKLYN	341 39TH STREET	NY Spills	Lower	544, 0.103, NNW

MAPPED SITES SUMMARY

Target Property Address:
4001 4TH AVENUE
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
K79	341 39TH ST	341 39TH ST	NY LTANKS	Lower	544, 0.103, North
K80	G & L EYES INC.	341 39TH ST.	NY LTANKS, NY Spills, NY HSWDS	Lower	544, 0.103, North
K81	COMMERCIAL BUILDING	341 39TH STREET	NY Spills	Lower	544, 0.103, North
K82	341 39TH ST	341 39TH ST	NY AST	Lower	544, 0.103, North
J83	PAVEMENT	38TH ST AND 4TH AVE	NY Spills	Lower	550, 0.104, NNE
I84	CON EDISON - MANHOLE	4002 5TH AVE	RCRA-LQG	Higher	553, 0.105, SE
I85	CON EDISON - MANHOLE	4002 5TH AVE	NY MANIFEST	Higher	553, 0.105, SE
J86	BIG APPLE MOBIL	984-4TH AVENUE	EDR Hist Auto	Lower	556, 0.105, NNE
I87	CON EDISON	4008 5TH AVE	NJ MANIFEST	Higher	568, 0.108, SE
I88	CON EDISON	4008 5TH AVE	RCRA NonGen / NLR	Higher	568, 0.108, SE
I89	CON EDISON	4008 5TH AVE	NY MANIFEST	Higher	568, 0.108, SE
I90	CARLINO BROS FINST F	3916 5TH AVENUE	EDR Hist Cleaner	Higher	575, 0.109, ESE
L91	CON EDISON SERVICE B	335 42ND ST	RCRA NonGen / NLR, NY MANIFEST	Lower	581, 0.110, West
M92	CON EDISON	417 43RD ST	NY MANIFEST	Higher	585, 0.111, SSW
M93	CON EDISON SERVICE B	417 43RD ST	RCRA NonGen / NLR, FINDS	Higher	585, 0.111, SSW
G94	4018 5TH AVE	4018 5TH AVENUE	NY AST	Higher	586, 0.111, SE
M95	CON EDISON	421 43RD ST	NJ MANIFEST	Higher	588, 0.111, SSW
M96	CON EDISON	421 43RD ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	588, 0.111, SSW
M97	CON EDISON	421 43RD ST	NY MANIFEST	Higher	588, 0.111, SSW
K98	DAVIDSON PIPE SUPPLY	39TH STREET/THIRD AV	NY AST	Lower	589, 0.112, NNW
G99	CON EDISON	4108 5TH AVE	NY MANIFEST	Higher	618, 0.117, SSE
G100	CON EDISON	4108 5TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	618, 0.117, SSE
G101	CON EDISON	4108 5TH AVE	NJ MANIFEST	Higher	618, 0.117, SSE
M102	CON EDISON	437 43RD ST	RCRA NonGen / NLR, FINDS	Higher	621, 0.118, SSW
M103	CON EDISON	437 43RD ST	NY MANIFEST	Higher	621, 0.118, SSW
J104	PUBLIC SCHOOL 24 - B	427 38TH STREET	NY AST	Lower	626, 0.119, NE
J105	971-975 4TH AVE.	971 4TH AVE	UST FINDER RELEASE	Lower	628, 0.119, NNE
J106	971-975 4TH AVE.	971 4TH AVE	NY LTANKS	Lower	628, 0.119, NNE
K107	CON EDISON SERVICE B	331 39TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	636, 0.120, NNW
L108	2- FAMILY HOME	324 41ST STREET	NY Spills	Lower	637, 0.121, WNW
N109	CON EDISION	317 40TH ST	NY MANIFEST	Lower	640, 0.121, NW
N110	CON EDISON	317 40TH ST	RCRA NonGen / NLR, FINDS	Lower	640, 0.121, NW
I111	CON EDISON SERVICE B	E 40TH ST & 5TH AVE	RCRA NonGen / NLR, FINDS	Higher	640, 0.121, ESE
J112	VAULT 3225	38TH ST/4TH AVE	NY Spills	Lower	647, 0.123, NE
J113	4TH AVE.AND 38TH ST.	4TH AVE AND 38THST.	NY LTANKS	Lower	647, 0.123, NE
G114	BELCHER SPILL INTO H	4095 5TH AVE	NY Spills	Higher	648, 0.123, SE
L115	JOKHAN RESIDENCE	322 41ST STREET	NY Spills	Lower	656, 0.124, WNW
J116	MERIT FOURTH	969 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	662, 0.125, NNE
O117	CON EDISON SERVICE B	361 43RD ST	RCRA NonGen / NLR, NY MANIFEST	Higher	669, 0.127, WSW

MAPPED SITES SUMMARY

Target Property Address:
4001 4TH AVENUE
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
O118	CON EDISON	359 43 ST	NY MANIFEST	Higher	671, 0.127, WSW
O119	CON EDISON	365 43RD ST	NY MANIFEST	Higher	675, 0.128, WSW
O120	CON EDISON SERVICE B	365 43RD ST	RCRA NonGen / NLR, FINDS	Higher	675, 0.128, WSW
P121	CON EDISON SERVICE B	453 43RD ST	RCRA NonGen / NLR, NY MANIFEST	Higher	681, 0.129, South
L122	CON EDISON SERVICE B	319 42ND ST	RCRA NonGen / NLR, NY MANIFEST	Lower	683, 0.129, West
H123	884 FIFTH AVENUE	884 FIFTH AVENUE	NY AST	Higher	683, 0.129, East
Q124	CON EDISON SERVICE B	16-18 E 39TH ST & 5T	RCRA NonGen / NLR, FINDS	Higher	705, 0.134, ESE
M125	CON EDISON	418 43RD ST	NY MANIFEST	Higher	716, 0.136, SSW
M126	CON EDISON	FRONT OF 418 43 ST	NY MANIFEST	Higher	716, 0.136, SSW
M127	CON EDISON	418 43RD ST	NY MANIFEST	Higher	716, 0.136, SSW
M128	CON EDISON SERVICE B	418 43RD ST	RCRA NonGen / NLR	Higher	716, 0.136, SSW
R129	CON EDISON SERVICE B	4023 5TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	720, 0.136, SE
K130	CON EDISON SERVICE B	313 39TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	732, 0.139, NNW
L131	CON EDISON SERVICE B	313 42 ST	RCRA NonGen / NLR, NY MANIFEST	Lower	736, 0.139, WNW
O132	NYC DOE - PS 557K	4302 4TH AVE	RCRA-LQG	Higher	743, 0.141, SW
O133	NYC DOE - PS 557K	4302 4TH AVE	NY MANIFEST	Higher	743, 0.141, SW
J134	P.S. 24 (OLD MERIT F	969-75 FOURTH AVE	NY UST	Lower	749, 0.142, NE
R135	CON EDISON - MANHOLE	507 41ST ST	NY MANIFEST	Higher	759, 0.144, SE
P136	CON EDISON SERVICE B	471 43RD ST	RCRA NonGen / NLR, NY MANIFEST	Higher	762, 0.144, South
S137	NYCT	481 38TH ST IN FRONT	NY MANIFEST	Higher	762, 0.144, ENE
S138	MTA NYCT	481 38TH ST IN FRONT	RCRA NonGen / NLR, FINDS, ECHO	Higher	762, 0.144, ENE
P139	CON EDISON	446 43RD ST	NY MANIFEST	Higher	772, 0.146, SSW
P140	CON EDISON	446 43RD ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	772, 0.146, SSW
P141	CON EDISON	446 43RD ST	NJ MANIFEST	Higher	772, 0.146, SSW
O142	CON EDISON SERVICE B	358 43RD ST	RCRA NonGen / NLR, NY MANIFEST	Higher	777, 0.147, WSW
O143	CON EDISON SERVICE B	358 43RD ST FRONT OF	RCRA NonGen / NLR, NY MANIFEST	Higher	777, 0.147, WSW
P144	CON EDISON	452 43RD ST	NY MANIFEST	Higher	788, 0.149, SSW
P145	CON EDISON SERVICE B	452 43RD ST	RCRA NonGen / NLR	Higher	788, 0.149, SSW
P146	CON EDISON SERVICE B	4214 5TH AVE	RCRA NonGen / NLR, FINDS	Higher	788, 0.149, South
P147	CON EDISON	4214 5TH AVE	NY MANIFEST	Higher	788, 0.149, South
O148	CON EDISON SERVICE B	352 352 43RD ST	RCRA NonGen / NLR, NY MANIFEST	Higher	794, 0.150, WSW
P149	CON EDISON SERVICE B	454 43RD ST	RCRA NonGen / NLR, NY MANIFEST	Higher	796, 0.151, South
L150	CROWN HOLDINGS USA	327 43RD STREET	NY AST	Lower	797, 0.151, West
Q151	CONSOLIDATED EDISON	879 FIFTH AVE	PA MANIFEST	Higher	797, 0.151, East
T152	CON EDISON	4TH AVE & 37TH ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	800, 0.152, NNE
Q153	JACKIE GLEASON BUS D	875 5TH AVE	NY AST, NY Spills	Higher	806, 0.153, East
T154	METRO 1 AMBULANCE SE	350 37TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	809, 0.153, NNE
Q155	JACKIE GLEASON (FIFT	871 FIFTH AVENUE	NY LTANKS, NY CBS AST, NY Spills	Higher	814, 0.154, East
Q156	NYCTA JACKIE GLEASON	871 5TH AVE	RCRA NonGen / NLR, US AIRS, NJ MANIFEST	Higher	814, 0.154, East

MAPPED SITES SUMMARY

Target Property Address:
4001 4TH AVENUE
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Q157	871 5TH AV/JACKIE GL	871 5TH AVE	UST FINDER RELEASE	Higher	814, 0.154, East
M158	SUNSET GARDENS SENIO	405 44TH STREET	UST FINDER	Higher	843, 0.160, SW
M159	SUNSET GARDENS SENIO	405 44TH STREET	NY UST	Higher	843, 0.160, SW
R160	CON EDISON SERVICE B	519 41ST ST	RCRA NonGen / NLR, NY MANIFEST	Higher	843, 0.160, SE
Q161	CON EDISON SERVICE B	518 39TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	846, 0.160, ESE
U162	CON EDISON SERVICE B	4018 3RD AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	889, 0.168, WNW
V163	CON EDISON	38TH ST & 3RD AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	898, 0.170, NNW
T164	NYC DEPT OF EDUCATIO	355 37TH ST	NY MANIFEST	Lower	898, 0.170, NNE
T165	P.S. 371 (OLD 615) -	355 37TH STREET	NY AST	Lower	898, 0.170, NNE
T166	PUBLIC SCHOOL 371K	355 37TH ST	RCRA-LQG	Lower	898, 0.170, NNE
R167	PARK SLOPE HOMES, IN	521-531 41ST STREET	NY AST	Higher	905, 0.171, SE
Q168	CON EDISON	523 39TH ST	NY MANIFEST	Higher	933, 0.177, ESE
Q169	CON EDISON SERVICE B	523 39TH ST	RCRA NonGen / NLR	Higher	933, 0.177, ESE
W170	CON EDISON	457 37TH ST	NY MANIFEST	Higher	953, 0.180, ENE
X171	CON EDISON SERVICE B	43RD AVE & 3RD ST N	RCRA NonGen / NLR, FINDS	Lower	958, 0.181, West
Y172	CON EDISON	532 39TH ST SB49212	NJ MANIFEST	Higher	967, 0.183, ESE
Y173	CON EDISON	532 39TH ST SB49212	NY MANIFEST	Higher	967, 0.183, ESE
Y174	CON EDISON	532 39TH ST SB49215	RCRA NonGen / NLR, FINDS, ECHO	Higher	967, 0.183, ESE
Y175	CON EDISON	532 39TH ST SB49215	NJ MANIFEST	Higher	967, 0.183, ESE
Y176	CON EDISON	532 39 ST	NY MANIFEST	Higher	967, 0.183, ESE
Y177	CON EDISON	532 39TH ST SB49212	RCRA NonGen / NLR	Higher	967, 0.183, ESE
X178	CON EDISON SERVICE B	4317 3RD AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	980, 0.186, West
Z179	533 41 ST	533 41ST STREET	NY UST	Higher	980, 0.186, SE
Z180	533 41 ST	533 41ST STREET	UST FINDER	Higher	980, 0.186, SE
Y181	ORTIZ PROPERTIES	535 40TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	981, 0.186, ESE
U182	CON EDISON SERVICE B	268 40TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	993, 0.188, NW
Z183	540-40 STREET	540 40TH STREET	NY UST	Higher	1004, 0.190, SE
Z184	CLOSED-LACKOF RECENT	540 40TH ST	NY LTANKS	Higher	1004, 0.190, SE
Z185	540-40 STREET	540 40TH STREET	UST FINDER	Higher	1004, 0.190, SE
AA186	CON EDISON - MANHOLE	OPP 4202 3RD AVE & 4	RCRA-LQG, NY MANIFEST, NJ MANIFEST	Lower	1004, 0.190, WNW
W187	CON EDISON SERVICE B	461 37TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1009, 0.191, ENE
AB188	CORNER VIEW ASSOCIAT	4407 4TH AVE	NY AST	Higher	1015, 0.192, SW
T189	CON EDISON - MANHOLE	941 4TH AVE	NY MANIFEST	Lower	1026, 0.194, NE
T190	CON EDISON - MANHOLE	941 4TH AVE	RCRA-LQG	Lower	1026, 0.194, NE
AC191	CON EDISON - MANHOLE	37TH ST & 5TH AVE	NY MANIFEST	Higher	1029, 0.195, ENE
AC192	CON EDISON	37TH ST & 5TH AVE	NY MANIFEST	Higher	1029, 0.195, ENE
AC193	CON EDISON - MANHOLE	EAST 5TH AVE AND 37T	RCRA-LQG, NY MANIFEST	Higher	1029, 0.195, ENE
AC194	CON EDISON SERVICE B	37TH ST & 5TH AVE	RCRA NonGen / NLR	Higher	1029, 0.195, ENE
X195	321 REALTY LLC	321 44TH STREET	NY AST	Lower	1037, 0.196, WSW

MAPPED SITES SUMMARY

Target Property Address:
4001 4TH AVENUE
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
X196	EAST END WOOD STRIPP	4218 3RD AVE	RCRA-SQG, NY MANIFEST, NJ MANIFEST	Lower	1049, 0.199, West
AD197	CON EDISON - CUSTOME	348 44 ST	NY MANIFEST	Higher	1051, 0.199, WSW
AE198	NYC DEPT OF EDUCATIO	360 36TH ST	NY MANIFEST	Lower	1065, 0.202, NNE
AE199	NYC DEPT OF EDUCATIO	360 36TH ST	RCRA-SQG	Lower	1065, 0.202, NNE
AF200	CON EDISON	319 37 ST	NY MANIFEST	Lower	1066, 0.202, North
Y201	CON EDISON	541 39TH ST	NY Spills, NY MANIFEST	Higher	1076, 0.204, ESE
Y202	CON EDISON - MANHOLE	541 39 ST	RCRA-LQG	Higher	1076, 0.204, ESE
AG203	DLJ ENTERPRISES, LTD	260 39TH STREET	NY AST	Lower	1080, 0.205, NW
V204	COSTCO WHOLESALE #03	976 3RD AVE	RCRA-VSQG, NY MANIFEST	Lower	1089, 0.206, NNW
V205	COSTCO # 318	976 THIRD AVE	PA MANIFEST	Lower	1089, 0.206, NNW
AH206	CON EDISON SERVICE B	4402 5TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1100, 0.208, South
AB207	CON EDISON SERVICE B	423 45TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1107, 0.210, SSW
AB208	CON EDISON	425 45TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1108, 0.210, SSW
AH209	NYNEX	44TH ST & 5TH AVE	NY MANIFEST	Higher	1111, 0.210, South
AC210	JACKIE GLEASON BUS D	845 5TH AVENUE	UST FINDER	Higher	1114, 0.211, ENE
AC211	JACKIE GLEASON BUS D	845 5TH AVENUE	NY CBS	Higher	1114, 0.211, ENE
AC212	JACKIE GLEASON BUS D	845 5TH AVENUE	NY UST	Higher	1114, 0.211, ENE
AC213	NYCTA - JACKIE GLEAS	845 5TH AVE	NY Spills, NY MANIFEST	Higher	1114, 0.211, ENE
AE214	CON EDISON	334 36TH STREET	NY MANIFEST	Lower	1123, 0.213, North
AE215	CON EDISON - MANHOLE	334 36TH STREET	RCRA-LQG	Lower	1123, 0.213, North
W216	SHELL SERVICE STATIO	842 FIFTH AVENUE	UST FINDER	Higher	1139, 0.216, ENE
W217	AMOCO SERVICE STATIO	842 5TH AVE	NY AST, NY Spills, RCRA NonGen / NLR, NY MANIFEST	Higher	1139, 0.216, ENE
W218	SHELL SERVICE STATIO	842 FIFTH AVENUE	NY UST	Higher	1139, 0.216, ENE
Z219	CON EDISON SERVICE B	556 40TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1140, 0.216, SE
W220	CON EDISON	472 36TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1141, 0.216, ENE
W221	CON EDISON	472 36TH ST	NJ MANIFEST	Higher	1141, 0.216, ENE
AC222	CON EDISON SERVICE B	845 5TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1148, 0.217, ENE
AA223	NYSDOT D254608 GOWAN	255 42ND ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1149, 0.218, WNW
AA224	CON EDISON	258 42ND ST	NY MANIFEST	Lower	1160, 0.220, WNW
AA225	CON EDISON	258 42ND ST	NJ MANIFEST	Lower	1160, 0.220, WNW
AA226	CON EDISON	258 42ND ST MH48383	NY MANIFEST	Lower	1160, 0.220, WNW
AA227	CON EDISON	258 42ND ST MH48386	RCRA NonGen / NLR, FINDS, ECHO	Lower	1160, 0.220, WNW
AA228	CON EDISON	258 42ND ST MH48383	RCRA NonGen / NLR	Lower	1160, 0.220, WNW
AA229	CON EDISON	258 42ND ST MH48383	NJ MANIFEST	Lower	1160, 0.220, WNW
AI230	CON EDISON SERVICE B	4409 3RD AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1162, 0.220, WSW
AD231	CON EDISON	347 45 ST	NY MANIFEST	Higher	1167, 0.221, WSW
AB232	CON EDISON	45TH ST & 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	1172, 0.222, SW
AI233	CON EDISON SERVICE B	4417 3RD AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1178, 0.223, WSW
AC234	DELIZZA REALTY INC	840 5TH AVENUE	UST FINDER	Higher	1182, 0.224, ENE

MAPPED SITES SUMMARY

Target Property Address:
4001 4TH AVENUE
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AC235	NYC DEPT OF EDUCATIO	840 5TH AVE	RCRA-SQG	Higher	1182, 0.224, ENE
AC236	NYC DEPT OF EDUCATIO	840 5TH AVE	NY BROWNFIELDS, NY Spills, NY MANIFEST	Higher	1182, 0.224, ENE
AC237	PS 671	840 5TH AVENUE	NY UST	Higher	1182, 0.224, ENE
X238	LOUIS BRESSOUD INC	270 43RD ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1192, 0.226, West
AD239	CON EDISON	337 45TH ST	NJ MANIFEST	Higher	1195, 0.226, WSW
AD240	CON EDISON	337 45TH ST	NY MANIFEST	Higher	1195, 0.226, WSW
AD241	CON EDISON	337 45TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1195, 0.226, WSW
AH242	BAYRIDGE FRENCH CLEA	4414 5TH AVENUE	RCRA-VSQG, ICIS, US AIRS, FINDS, ECHO, NY...	Higher	1197, 0.227, South
AB243	CON EDISON	4511 4TH AVE SB45506	RCRA NonGen / NLR	Higher	1198, 0.227, SW
AB244	CON EDISON	4511 4TH AVE SB45506	NJ MANIFEST	Higher	1198, 0.227, SW
AB245	CON EDISON	4511 4 AVE	NJ MANIFEST	Higher	1198, 0.227, SW
AB246	CON EDISON	4511 4TH AVE SB45506	NY MANIFEST	Higher	1198, 0.227, SW
AB247	CON EDISON	4511 4TH AVE MH5826	NY MANIFEST	Higher	1198, 0.227, SW
AB248	CON EDISON	4511 4TH AVE MH5827	RCRA NonGen / NLR	Higher	1198, 0.227, SW
AB249	CON EDISON	4511 4TH AVE MH5827	NY MANIFEST	Higher	1198, 0.227, SW
AB250	CON EDISON	4511 4TH AVE MH5826	NJ MANIFEST	Higher	1198, 0.227, SW
AB251	CON EDISON	4511 4TH AVE MH5826	RCRA NonGen / NLR	Higher	1198, 0.227, SW
AE252	CON EDISON SERVICE B	337 36TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1199, 0.227, NNE
W253	CON EDISON	461 36TH ST	NY MANIFEST	Lower	1205, 0.228, ENE
AB254	CON EDISON	46TH ST & 4TH AVE	NY MANIFEST	Higher	1211, 0.229, SW
AD255	CON EDISON	333 45TH ST	NY MANIFEST	Higher	1212, 0.230, WSW
AD256	CON EDISON	333 45TH ST	NJ MANIFEST	Higher	1212, 0.230, WSW
AD257	CON EDISON	333 45TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1212, 0.230, WSW
Z258	CON EDISON	563 41ST ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1215, 0.230, SE
Z259	CON EDISON	563 41ST ST	NY MANIFEST	Higher	1215, 0.230, SE
Z260	CON EDISON	563 41ST ST	NJ MANIFEST	Higher	1215, 0.230, SE
AJ261	CON EDISON	566 40TH ST	NY MANIFEST	Higher	1231, 0.233, SE
AJ262	CON EDISON	566 40TH ST	NJ MANIFEST	Higher	1231, 0.233, SE
AJ263	CON EDISON	566 40TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1231, 0.233, SE
AE264	CON EDISON MANHOLE:	940 4TH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1233, 0.234, NNE
AC265	CONSOLIDATED EDISON	36 ST & 5 AVE MH7606	NY MANIFEST	Higher	1245, 0.236, ENE
AK266	CON EDISON - MANHOLE	36TH ST & 5TH AVE	NY MANIFEST	Higher	1250, 0.237, ENE
AK267	CON EDISON MANHOLE 3	5 AVE & 36 ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1250, 0.237, ENE
AK268	CON EDISON MANHOLE 6	36 ST & 5TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1250, 0.237, ENE
AG269	CONSOLIDATED EDISON	257 W 39TH ST	NY MANIFEST	Lower	1255, 0.238, NW
AC270	CON EDISON SERVICE B	502 36TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	1256, 0.238, ENE
AL271	CON EDISON - MANHOLE	442 45 ST	RCRA-LQG, NY MANIFEST	Higher	1259, 0.238, SSW
AG272	CON EDISON - MANHOLE	230 39 ST	NY MANIFEST	Lower	1286, 0.244, NW
AM273	INDUSTRY CITY ASSOCI	241 37TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1296, 0.245, NNW

MAPPED SITES SUMMARY

Target Property Address:
4001 4TH AVENUE
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AF274	CON EDISON SERVICE B	315 36TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1298, 0.246, North
275	MARIEN-HEIM OF SUNSE	4520 4TH AVENUE	NY AST	Higher	1306, 0.247, SW
AM276	CON EDISON - VAULT S	233 37TH ST	NY MANIFEST	Lower	1312, 0.248, NNW
AM277	CON EDISON - VAULT S	233 37TH ST	NY MANIFEST	Lower	1312, 0.248, NNW
AN278	GREENWOOD CEMETERY	921 4TH AVENUE	NY LTANKS	Lower	1318, 0.250, NE
AN279	THE GREEN-WOOD CEMET	921 FOURTH AVENUE	NY UST	Lower	1318, 0.250, NE
AN280	GREENWOOD CEMETERY	921 4TH AVENUE	UST FINDER RELEASE	Lower	1318, 0.250, NE
AN281	THE GREEN-WOOD CEMET	921 FOURTH AVENUE	UST FINDER	Lower	1318, 0.250, NE
AN282	THE GREEN-WOOD CEMET	921 FOURTH AVENUE	NY AST	Lower	1318, 0.250, NE
AN283	4TH AVE & 34TH / 35T	4TH AVE & 34TH/35TH	NY LTANKS	Lower	1324, 0.251, NNE
284	DAVIDSON PIPE SUPPLY	990 3RD AVE	NY LTANKS, NY MANIFEST	Lower	1349, 0.255, NNW
AI285	OHANNA APARTMENT BUI	4420 3RD AVE	NY LTANKS	Lower	1396, 0.264, WSW
AL286	APRT	461 46TH STREET	NY LTANKS	Higher	1431, 0.271, SSW
AN287	CLOSED-LACKOF RECENT	34TH ST / 4TH AVE	NY LTANKS	Lower	1453, 0.275, NNE
AO288	SHOW AUTO SALES -MTB	4001 SECOND AVE	UST FINDER RELEASE	Lower	1531, 0.290, NW
AO289	COMADORE MANUFAC	3913 2ND AVE	NY LTANKS	Lower	1536, 0.291, NW
290	BELL ATLANTIC	230 43RD ST	UST FINDER RELEASE	Lower	1552, 0.294, West
AP291	156-170 34TH STREET	156-170 34TH STREET	NY LTANKS	Lower	1554, 0.294, NNE
AP292	NABISCO CO - LIFESAV	170 34TH ST	RCRA-VSQG, NY LTANKS, NY Spills, FINDS, ECHO, NY...	Lower	1555, 0.295, NNE
AP293	34TH ST & 4TH AVE/BK	34TH ST & 4TH AVE	NY LTANKS	Lower	1583, 0.300, NE
AP294	CLOSED-LACKOF RECENT	34TH ST / 4TH AVE	NY LTANKS	Lower	1583, 0.300, NE
295	FORMER GETTY S/S #98	602 39TH ST	UST FINDER RELEASE	Higher	1586, 0.300, ESE
AO296	22-36 SECOND AVENUE	22-36 SECOND AVENUE	NY BROWNFIELDS	Lower	1627, 0.308, NW
AQ297	875 4TH AVENUE	875 4TH AVENUE	NY VCP	Lower	1924, 0.364, NE
AQ298	875 4TH AVENUE	875 4TH AVENUE	NY Spills, NY NYC OER	Lower	1924, 0.364, NE
AR299	FGP BUSH TERMINALS	148 39TH STREET	NY LTANKS	Lower	1987, 0.376, NW
AS300	114 32ND ST AT 3RD A	114 32ND ST AT 3RD A	NY LTANKS	Lower	2139, 0.405, NNE
301	COMMODORE MANUFACTUR	140 43RD STREET	NY LTANKS	Lower	2160, 0.409, WNW
AS302	882 3RD AVE	882 3RD AVENUE	NY LTANKS, NY Spills	Lower	2169, 0.411, NNE
AR303	116 39TH ST/MAGNOLIA	116 39TH ST/MAGNOLIA	NY LTANKS	Lower	2190, 0.415, NW
AR304	116 39TH ST	116 39TH ST	NY LTANKS	Lower	2190, 0.415, NW
305	BIG L EXCAVATING & D	701 39 STREET	NY SWF/LF, NY NYC LAND USE	Higher	2269, 0.430, ESE
AT306	BLATCHFORD BASE PLAN	32 33RD ST	SEMS-ARCHIVE	Lower	2279, 0.432, North
AT307	BLATCHFORD BASE PLAN	32 33RD ST.	NY HSWDS	Lower	2279, 0.432, North
308	SUNSET PARK 7TH AVE/	7TH AVE/43RD ST	NY LTANKS	Higher	2292, 0.434, SE
AU309	4907-4709 4TH AVENUE	4907 4TH AVENUE	NY VCP	Higher	2316, 0.439, SW
AU310	4907-4709 4TH AVENUE	4907 4TH AVENUE	NY NYC OER	Higher	2316, 0.439, SW
311	BUSH TERMINAL EDC -D	4104 FIRST AVENUE	UST FINDER RELEASE	Lower	2425, 0.459, WNW
312	LUTHERAN MEDICAL CTR	514 49TH ST	NY LTANKS, NY Spills	Higher	2430, 0.460, SSW

MAPPED SITES SUMMARY

Target Property Address:
4001 4TH AVENUE
BROOKLYN, NY 11232

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
313	VIDINHA RESIDENCE	442 50TH STREET	NY LTANKS	Higher	2547, 0.482, SSW
314	RED HOOK MARINE/PT A	RED HOOK MARINE TERM	UST FINDER RELEASE	Lower	2589, 0.490, North
315	PIER 6 BUSH TERMINAL		FUDS	Lower	2646, 0.501, WNW
316	5111 4TH AVENUE	5111 4TH AVENUE	NY NYC OER	Higher	2758, 0.522, SW
317	MIL MED SUPPLY NO. 1		FUDS	Lower	2867, 0.543, NNE
318	REAR OF BUSH TERMINA	END OF 47 THRU 52ND	NY SHWS	Lower	3161, 0.599, West
319	US ARMED GUARD CENTE		FUDS	Lower	3521, 0.667, West
320	NYSDEC EMPIRE ELECTR	5200 1ST AVE	RCRA-LQG, NY SHWS, NY MANIFEST	Lower	3922, 0.743, WSW
321	AMERICAN MACHINE AND	SECOND AVENUE AND 56	FUSRAP	Lower	4339, 0.822, WSW
AV322	KINGS COUNTY WORKS	55TH ST. AND 1ST AVE	EDR MGP	Lower	4368, 0.827, WSW
AV323	K - KINGS COUNTY WOR	55TH ST & 1ST AVE	NY SHWS, NY BROWNFIELDS, NY MGP	Lower	4448, 0.842, WSW
324	FORMER E.W. BLISS PR	29 53RD STREET	NY SHWS, NY Spills	Lower	4466, 0.846, West
325	FORMER MOORE MCCORMA	730 3RD AVENUE	NY SHWS, NY Spills	Lower	4467, 0.846, NNE
326	GENERAL TIRE	602 WEST 57TH ST	NY SHWS	Higher	4588, 0.869, SSW
AW327	179 22ND STREET	691 4TH AVENUE	NY NYC OER	Lower	4746, 0.899, NE
AW328	CON EDISON SERVICE B	683 4TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST, NY...	Lower	4853, 0.919, NE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 9 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
B & L GAS STATION EN 4001 4TH AVENUE BROOKLYN, NY 11232	FINDS Registry ID:: 110054924917	N/A
B & L GAS STATION EN 4001 4TH AVENUE BROOKLYN, NY 11232	NY AST Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-349399	N/A
BP GAS STATION 4001 4TH AVE BROOKLYN, NY	NY Spills Spill Number/Closed Date: 2206825 / 2022-11-16 Site ID: 645074 Spill Date: 2022-11-09	N/A
AMOCO-FOURTH AVE 4001-4011 FOURTH AVE BROOKLYN, NY 11232	FINDS Registry ID:: 110005986790 ECHO Registry ID: 110005986790	N/A
AMOCO-FOURTH AVE 4001-4011 4TH AVE BROOKLYN, NY 11232	US AIRS Database: US AIRS MINOR, Date of Government Version: 10/12/2016 EPA plant ID:: 110005986790	N/A
ALMANZAR INC 4001 4TH AVE BROOKLYN, NY 11232	EDR Hist Auto	N/A
B & L GAS STATION EN 4001 4TH AVENUE BROOKLYN, NY 11232	UST FINDER	N/A
COMMERICAL 4001-4011 4TH AVE BROOKLYN, NY	NY Spills Spill Number/Closed Date: 1811146 / Not Reported Site ID: 582069 Spill Date: 2019-02-05	N/A
LOT 6,TAXBLOCK 714 4001 4 AVENUE BROOKLYN, NY 11232	NY E DESIGNATION NY NYC LAND USE	N/A

EXECUTIVE SUMMARY

H & S AMOCO 4001 4TH AVE BROOKLYN, NY 11232	RCRA NonGen / NLR EPA ID:: NY0000017582 FINDS Registry ID:: 110004307919 ECHO Registry ID: 110004307919	NY0000017582
B & L GAS STATION EN 4001 4TH AVENUE BROOKLYN, NY 11232	NY UST Database: UST, Date of Government Version: 09/06/2023	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---------- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

EXECUTIVE SUMMARY

Federal ERNS list

ERNS ---------- Emergency Response Notification System

Lists of state and tribal leaking storage tanks

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---------- Listing of Leaking Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST ---------- Underground Storage Tank Listing
NY CBS UST ---------- Chemical Bulk Storage Database
NY MOSF UST ---------- Major Oil Storage Facilities Database
NY MOSF ---------- Major Oil Storage Facility Site Listing
NY MOSF AST ---------- Major Oil Storage Facilities Database
INDIAN UST ---------- Underground Storage Tanks on Indian Land
NY TANKS ---------- Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL ---------- Restrictive Declarations Listing
NY ENG CONTROLS ---------- Registry of Engineering Controls
NY INST CONTROL ---------- Registry of Institutional Controls

Lists of state and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

NY ERP ---------- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE ---------- Registered Waste Tire Storage & Facility List
NY SWRCY ---------- Registered Recycling Facility List
INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
ODI ---------- Open Dump Inventory
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---------- Delisted National Clandestine Laboratory Register
NY DEL SHWS ---------- Delisted Registry Sites
US CDL ---------- National Clandestine Laboratory Register

EXECUTIVE SUMMARY

Local Lists of Registered Storage Tanks

NY HIST UST	Historical Petroleum Bulk Storage Database
NY HIST AST	Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS	Spill Liens Information
LIENS 2	CERCLA Lien Information

Records of Emergency Release Reports

HMIRS	Hazardous Materials Information Reporting System
NY Hist Spills	SPILLS Database
NY SPILLS 90	SPILLS 90 data from FirstSearch
NY SPILLS 80	SPILLS 80 data from FirstSearch

Other Ascertainable Records

DOD	Department of Defense Sites
SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR	Financial Assurance Information
EPA WATCH LIST	EPA WATCH LIST
2020 COR ACTION	2020 Corrective Action Program List
TSCA	Toxic Substances Control Act
TRIS	Toxic Chemical Release Inventory System
SSTS	Section 7 Tracking Systems
ROD	Records Of Decision
RMP	Risk Management Plans
RAATS	RCRA Administrative Action Tracking System
PRP	Potentially Responsible Parties
PADS	PCB Activity Database System
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS	Material Licensing Tracking System
COAL ASH DOE	Steam-Electric Plant Operation Data
COAL ASH EPA	Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER	PCB Transformer Registration Database
RADINFO	Radiation Information Database
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS	Incident and Accident Data
CONSENT	Superfund (CERCLA) Consent Decrees
INDIAN RESERV	Indian Reservations
UMTRA	Uranium Mill Tailings Sites
LEAD SMELTERS	Lead Smelter Sites
US MINES	Mines Master Index File
MINES MRDS	Mineral Resources Data System
ABANDONED MINES	Abandoned Mines
DOCKET HWC	Hazardous Waste Compliance Docket Listing
UXO	Unexploded Ordnance Sites
FUELS PROGRAM	EPA Fuels Program Registered Listing
PFAS NPL	Superfund Sites with PFAS Detections Information
PFAS FEDERAL SITES	Federal Sites PFAS Information
PFAS TRIS	List of PFAS Added to the TRI

PFAS TSCA ---- PFAS Manufacture and Imports Information
PFAS RCRA MANIFEST ---- PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR ---- PFAS Contamination Site Location Listing
PFAS WQP ---- Ambient Environmental Sampling for PFAS
PFAS NPDES ---- Clean Water Act Discharge Monitoring Information
PFAS ECHO ---- Facilities in Industries that May Be Handling PFAS Listing
PFAS ECHO FIRE TRAINING Facilities in Industries that May Be Handling PFAS Listing
PFAS PART 139 AIRPORT ---- All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC ---- Aqueous Foam Related Incidents Listing
BIOSOLIDS ---- ICIS-NPDES Biosolids Facility Data
NY PFAS ---- PFAS Contamination Site Location Listing
NY AIRS ---- Air Emissions Data
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY Financial Assurance ---- Financial Assurance Information Listing
NY SPDES ---- State Pollutant Discharge Elimination System
NY VAPOR REOPENED ---- Vapor Intrusion Legacy Site List
NY UIC ---- Underground Injection Control Wells
NY COOLING TOWERS ---- Registered Cooling Towers
NY ILI ---- New York State Inactive Landfill Initiative

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---- Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF ---- Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless

information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 09/19/2023 has revealed that there is 1 SEMS-ARCHIVE site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BLATCHFORD BASE PLAN Site ID: 0201944 EPA Id: NYD980531644	32 33RD ST	N 1/4 - 1/2 (0.432 mi.)	AT306	995

Lists of Federal RCRA generators

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/04/2023 has revealed that there are 11 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - SERVICE EPA ID:: NYP004404968	***415 40 ST***	***ENE 0 - 1/8 (0.018 mi.)***	***A25***	***65***
CON EDISON - MANHOLE EPA ID:: NYP005087527	476 40TH ST	SE 0 - 1/8 (0.096 mi.)	I75	172
CON EDISON - MANHOLE EPA ID:: NYP005089741	4002 5TH AVE	SE 0 - 1/8 (0.105 mi.)	I84	191
NYC DOE - PS 557K EPA ID:: NYR000251066	4302 4TH AVE	SW 1/8 - 1/4 (0.141 mi.)	O132	288
CON EDISON - MANHOLE EPA ID:: NYP004197851	***EAST 5TH AVE AND 37T***	***ENE 1/8 - 1/4 (0.195 mi.)***	***AC193***	***508***
CON EDISON - MANHOLE EPA ID:: NYP004391280	541 39 ST	ESE 1/8 - 1/4 (0.204 mi.)	Y202	650
CON EDISON - MANHOLE EPA ID:: NYP004392056	***442 45 ST***	***SSW 1/8 - 1/4 (0.238 mi.)***	***AL271***	***898***

Lower Elevation	Address	Direction / Distance	Map ID	Page
PUBLIC SCHOOL 371K EPA ID:: NYR000214080	355 37TH ST	NNE 1/8 - 1/4 (0.170 mi.)	T166	447
CON EDISON - MANHOLE EPA ID:: NYP004190732	***OPP 4202 3RD AVE & 4***	***WNW 1/8 - 1/4 (0.190 mi.)***	***AA186***	***492***
CON EDISON - MANHOLE EPA ID:: NYP005032164	941 4TH AVE	NE 1/8 - 1/4 (0.194 mi.)	T190	503
CON EDISON - MANHOLE	334 36TH STREET	N 1/8 - 1/4 (0.213 mi.)	AE215	722

EPA ID:: NYP004383519

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/04/2023 has revealed that there are 5 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYC DEPT OF ED - PS EPA ID:: NYR000134783	***4222 4TH AVE***	***SW 0 - 1/8 (0.087 mi.)***	***D72***	***155***
NYC DEPT OF EDUCATIO EPA ID:: NYR000238626	840 5TH AVE	ENE 1/8 - 1/4 (0.224 mi.)	AC235	793

Lower Elevation	Address	Direction / Distance	Map ID	Page
NYC DEPT OF EDUCATIO EPA ID:: NYR000205674	***4004 4TH AVE***	***NNW 0 - 1/8 (0.019 mi.)***	***A28***	***71***
EAST END WOOD STRIPP EPA ID:: NYR000147389	***4218 3RD AVE***	***W 1/8 - 1/4 (0.199 mi.)***	***X196***	***516***
NYC DEPT OF EDUCATIO EPA ID:: NYR000242230	360 36TH ST	NNE 1/8 - 1/4 (0.202 mi.)	AE199	644

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 12/04/2023 has revealed that there are 2 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BAYRIDGE FRENCH CLEA EPA ID:: NY0000359703	***4414 5TH AVENUE***	***S 1/8 - 1/4 (0.227 mi.)***	***AH242***	***814***

Lower Elevation	Address	Direction / Distance	Map ID	Page
COSTCO WHOLESALE #03 EPA ID:: NYR000030353	***976 3RD AVE***	***NNW 1/8 - 1/4 (0.206 mi.)***	***V204***	***655***

EXECUTIVE SUMMARY

Lists of state- and tribal hazardous waste facilities

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 11/06/2023 has revealed that there are 7 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SUNSET CAR CARE SITE Site Code: 532551	***4013 4TH AVENUE***	***SW 0 - 1/8 (0.009 mi.)***	***A14***	***39***
GENERAL TIRE Site Code: 338762	602 WEST 57TH ST	SSW 1/2 - 1 (0.869 mi.)	326	1047

Lower Elevation	Address	Direction / Distance	Map ID	Page
REAR OF BUSH TERMINA Site Code: 58024 Class Code: Does not present a significant threat to the public health or the environment - action may be deferred.	END OF 47 THRU 52ND	W 1/2 - 1 (0.599 mi.)	318	1010
NYSDEC EMPIRE ELECTR Site Code: 57687 Class Code: Significant threat to the public health or environment - action required.	***5200 1ST AVE***	***WSW 1/2 - 1 (0.743 mi.)***	***320***	***1014***
K - KINGS COUNTY WOR Site Code: 378989	***55TH ST & 1ST AVE***	***WSW 1/2 - 1 (0.842 mi.)***	***AV323***	***1034***
FORMER E.W. BLISS PR Site Code: 535697	***29 53RD STREET***	***W 1/2 - 1 (0.846 mi.)***	***324***	***1038***
FORMER MOORE MCCORMA Site Code: 439096	***730 3RD AVENUE***	***NNE 1/2 - 1 (0.846 mi.)***	***325***	***1040***

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 09/27/2023 has revealed that there is 1 NY SWF/LF site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BIG L EXCAVATING & D	***701 39 STREET***	***ESE 1/4 - 1/2 (0.430 mi.)***	***305***	***993***

EXECUTIVE SUMMARY

Lists of state and tribal leaking storage tanks

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 01/24/2024 has revealed that there are 28 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
JACKIE GLEASON (FIFT	***871 FIFTH AVENUE***	***E 1/8 - 1/4 (0.154 mi.)***	***Q155***	***387***
Spill Number/Closed Date: 9106350 / 2002-02-07				
Spill Number/Closed Date: 9510771 / 1995-12-11				
Spill Date: 1991-09-12				
Spill Date: 1995-11-27				
Site ID: 137663				
Site ID: 137664				
CLOSED-LACKOF RECENT	540 40TH ST	SE 1/8 - 1/4 (0.190 mi.)	Z184	487
Spill Number/Closed Date: 1104703 / 2011-08-17				
Spill Number/Closed Date: 9813577 / 2003-03-10				
Spill Date: 2011-07-25				
Spill Date: 1999-02-04				
Site ID: 452314				
Site ID: 280559				
APRT	461 46TH STREET	SSW 1/4 - 1/2 (0.271 mi.)	AL286	943
Spill Number/Closed Date: 0711703 / 2008-06-03				
Spill Date: 2008-02-06				
Site ID: 393223				
SUNSET PARK 7TH AVE/	7TH AVE/43RD ST	SE 1/4 - 1/2 (0.434 mi.)	308	998
Spill Number/Closed Date: 0100864 / 2006-11-01				
Spill Date: 2001-04-23				
Site ID: 108017				
LUTHERAN MEDICAL CTR	***514 49TH ST***	***SSW 1/4 - 1/2 (0.460 mi.)***	***312***	***1001***
Spill Number/Closed Date: 1600912 / 2019-12-03				
Spill Number/Closed Date: 1305012 / 2013-10-31				
Spill Date: 2016-04-27				
Spill Date: 2013-08-08				
Site ID: 526211				
Site ID: 485566				
VIDINHA RESIDENCE	442 50TH STREET	SSW 1/4 - 1/2 (0.482 mi.)	313	1005
Spill Number/Closed Date: 0314286 / 2004-03-31				
Spill Number/Closed Date: 0312507 / 2004-07-12				
Spill Date: 2004-02-10				
Site ID: 125672				
Site ID: 99378				

Lower Elevation	Address	Direction / Distance	Map ID	Page
FRED ALIMONDA	357 40TH STREET	NNW 0 - 1/8 (0.057 mi.)	F48	104
Spill Number/Closed Date: 9803014 / 2003-03-03				
Spill Number/Closed Date: 0301684 / 2009-09-02				

Spill Date: 1998-06-01
Spill Date: 2003-05-16
Site ID: 79043
Site ID: 288656

MOBIL S/S Spill Number/Closed Date: 8706481 / 2013-05-23 Spill Date: 1987-10-30 Site ID: 192011	987 4TH AVE	NE 0 - 1/8 (0.069 mi.)	E56	125
341 39TH ST Spill Number/Closed Date: 9200366 / 1992-04-10 Spill Date: 1992-04-09 Site ID: 103132	341 39TH ST	N 0 - 1/8 (0.103 mi.)	K79	178
G & L EYES INC. Spill Number/Closed Date: 9313271 / 1994-04-25 Spill Number/Closed Date: 9313394 / 1994-02-14 Spill Date: 1994-02-09 Spill Date: 1994-02-14 Site ID: 201123 Site ID: 201124	***341 39TH ST.***	***N 0 - 1/8 (0.103 mi.)***	***K80***	***180***
971-975 4TH AVE. Spill Number/Closed Date: 9207015 / 2006-07-13 Spill Date: 1992-09-17 Site ID: 115646	971 4TH AVE	NNE 0 - 1/8 (0.119 mi.)	J106	231
4TH AVE.AND 38TH ST. Spill Number/Closed Date: 8606188 / 1987-01-04 Spill Date: 1987-01-04 Site ID: 214911	4TH AVE AND 38THST.	NE 0 - 1/8 (0.123 mi.)	J113	245
GREENWOOD CEMETERY Spill Number/Closed Date: 9413808 / 2005-11-16 Spill Date: 1995-01-17 Site ID: 150406	921 4TH AVENUE	NE 1/8 - 1/4 (0.250 mi.)	AN278	915
4TH AVE & 34TH / 35T Spill Number/Closed Date: 8901237 / 1992-09-30 Spill Date: 1989-05-08 Site ID: 117733	4TH AVE & 34TH/35TH	NNE 1/4 - 1/2 (0.251 mi.)	AN283	929
DAVIDSON PIPE SUPPLY Spill Number/Closed Date: 9510315 / 2006-02-15 Spill Date: 1995-11-16 Site ID: 175589	***990 3RD AVE***	***NNW 1/4 - 1/2 (0.255 mi.)***	***284***	***930***
OHANNA APARTMENT BUI Spill Number/Closed Date: 0514696 / 2006-07-26 Spill Date: 2006-03-22 Site ID: 361487	4420 3RD AVE	WSW 1/4 - 1/2 (0.264 mi.)	AI285	940
CLOSED-LACKOF RECENT Spill Number/Closed Date: 8710694 / 2003-03-13 Spill Date: 1988-03-11 Site ID: 175406	34TH ST / 4TH AVE	NNE 1/4 - 1/2 (0.275 mi.)	AN287	944
COMADORE MANUFAC Spill Number/Closed Date: 0713359 / 2008-09-08 Spill Date: 2008-03-18 Site ID: 395096	3913 2ND AVE	NW 1/4 - 1/2 (0.291 mi.)	AO289	946
156-170 34TH STREET	156-170 34TH STREET	NNE 1/4 - 1/2 (0.294 mi.)	AP291	949

Spill Number/Closed Date: 9210902 / 1993-02-25 Spill Date: 1992-12-21 Site ID: 114462				
NABISCO CO - LIFESAV Spill Number/Closed Date: 9211737 / 1993-02-01 Spill Date: 1992-12-10 Site ID: 171962	***170 34TH ST***	***NNE 1/4 - 1/2 (0.295 mi.)***	***AP292***	***950***
34TH ST & 4TH AVE/BK Spill Number/Closed Date: 8710384 / 1992-09-30 Spill Date: 1988-03-11 Site ID: 151245	34TH ST & 4TH AVE	NE 1/4 - 1/2 (0.300 mi.)	AP293	976
CLOSED-LACKOF RECENT Spill Number/Closed Date: 8902953 / 2003-03-04 Spill Date: 1989-06-21 Site ID: 175407	34TH ST / 4TH AVE	NE 1/4 - 1/2 (0.300 mi.)	AP294	977
FGP BUSH TERMINALS Spill Number/Closed Date: 9514887 / 2003-02-24 Spill Date: 1996-02-20 Site ID: 160744	148 39TH STREET	NW 1/4 - 1/2 (0.376 mi.)	AR299	985
114 32ND ST AT 3RD A Spill Number/Closed Date: 9305702 / 2003-10-27 Spill Date: 1993-08-09 Site ID: 167598	114 32ND ST AT 3RD A	NNE 1/4 - 1/2 (0.405 mi.)	AS300	986
COMMODORE MANUFACTUR Spill Number/Closed Date: 8910578 / 2014-09-19 Spill Date: 1990-01-29 Site ID: 203368	140 43RD STREET	WNW 1/4 - 1/2 (0.409 mi.)	301	987
882 3RD AVE Spill Number/Closed Date: 9614424 / 1997-03-13 Spill Date: 1997-03-13 Site ID: 124122	***882 3RD AVENUE***	***NNE 1/4 - 1/2 (0.411 mi.)***	***AS302***	***989***
116 39TH ST/MAGNOLIA Spill Number/Closed Date: 9201695 / 1992-05-12 Spill Date: 1992-05-11 Site ID: 288856	116 39TH ST/MAGNOLIA	NW 1/4 - 1/2 (0.415 mi.)	AR303	991
116 39TH ST Spill Number/Closed Date: 9411889 / 1994-12-06 Spill Date: 1994-12-06 Site ID: 195660	116 39TH ST	NW 1/4 - 1/2 (0.415 mi.)	AR304	992

Lists of state and tribal registered storage tanks

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 10 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SUNSET GARDENS SENIO Database: UST, Date of Government Version: 09/06/2023	405 44TH STREET	SW 1/8 - 1/4 (0.160 mi.)	M159	426
533 41 ST Database: UST, Date of Government Version: 09/06/2023	533 41ST STREET	SE 1/8 - 1/4 (0.186 mi.)	Z179	473
540-40 STREET Database: UST, Date of Government Version: 09/06/2023	540 40TH STREET	SE 1/8 - 1/4 (0.190 mi.)	Z183	485
JACKIE GLEASON BUS D Database: UST, Date of Government Version: 09/06/2023	845 5TH AVENUE	ENE 1/8 - 1/4 (0.211 mi.)	AC212	693
SHELL SERVICE STATIO Database: UST, Date of Government Version: 09/06/2023	842 FIFTH AVENUE	ENE 1/8 - 1/4 (0.216 mi.)	W218	736
PS 671 Database: UST, Date of Government Version: 09/06/2023	840 5TH AVENUE	ENE 1/8 - 1/4 (0.224 mi.)	AC237	803

Lower Elevation	Address	Direction / Distance	Map ID	Page
FRED ALIMONDA Database: UST, Date of Government Version: 09/06/2023	357 40TH STREET	NNW 0 - 1/8 (0.057 mi.)	F47	102
MOBIL S/S F7FYG C&M Database: UST, Date of Government Version: 09/06/2023	987-993 4TH AVENUE	NE 0 - 1/8 (0.069 mi.)	E54	116
P.S. 24 (OLD MERIT F Database: UST, Date of Government Version: 09/06/2023	969-75 FOURTH AVE	NE 1/8 - 1/4 (0.142 mi.)	J134	292
THE GREEN-WOOD CEMET Database: UST, Date of Government Version: 09/06/2023	921 FOURTH AVENUE	NE 1/8 - 1/4 (0.250 mi.)	AN279	916

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 09/06/2023 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
JACKIE GLEASON BUS D Facility Status: Active CBS Number: 2-000283	845 5TH AVENUE	ENE 1/8 - 1/4 (0.211 mi.)	AC211	692

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 24 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
4013 CAR CARE Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-611076	4013 4TH AVENUE	SW 0 - 1/8 (0.009 mi.)	A15	45
VM REALTY 8 LLC Database: AST, Date of Government Version: 09/06/2023	417-441 40 STREET	ENE 0 - 1/8 (0.016 mi.)	A22	57

Facility Id: 2-608147				
4112 4TH AVE LLC Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-406333	375 42ND STREET	WSW 0 - 1/8 (0.077 mi.)	D66	144
J. KEVIN O'CONNOR Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-602384	460 41 STREET	SSE 0 - 1/8 (0.084 mi.)	G69	148
4018 5TH AVE Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-327697	4018 5TH AVENUE	SE 0 - 1/8 (0.111 mi.)	G94	207
884 FIFTH AVENUE Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-608715	884 FIFTH AVENUE	E 1/8 - 1/4 (0.129 mi.)	H123	267
JACKIE GLEASON BUS D Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-190233	***875 5TH AVE***	***E 1/8 - 1/4 (0.153 mi.)***	***Q153***	***359***
PARK SLOPE HOMES, IN Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-600242	521-531 41ST STREET	SE 1/8 - 1/4 (0.171 mi.)	R167	451
CORNER VIEW ASSOCIAT Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-095230	4407 4TH AVE	SW 1/8 - 1/4 (0.192 mi.)	AB188	500
AMOCO SERVICE STATIO Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-509108	***842 5TH AVE***	***ENE 1/8 - 1/4 (0.216 mi.)***	***W217***	***728***
MARIEN-HEIM OF SUNSE Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-216046	4520 4TH AVENUE	SW 1/8 - 1/4 (0.247 mi.)	275	912

Lower Elevation	Address	Direction / Distance	Map ID	Page
I.S. 136 - BROOKLYN Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-606291	4004 4TH AVE	NW 0 - 1/8 (0.018 mi.)	A23	59
366 41ST ST Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-360007	366 41ST ST	W 0 - 1/8 (0.048 mi.)	D41	94
366 39 REALTY LLC Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-602835	366 39TH STREET	N 0 - 1/8 (0.058 mi.)	E49	107
APARTMENT BUILDING Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-406112	358 41ST STREET	W 0 - 1/8 (0.067 mi.)	D53	114
SUNSET HEIGHTS, L.P. Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-406120	354 41ST STREET	W 0 - 1/8 (0.073 mi.)	D62	139
341 39TH ST Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-320617	341 39TH ST	N 0 - 1/8 (0.103 mi.)	K82	187
DAVIDSON PIPE SUPPLY Database: AST, Date of Government Version: 09/06/2023	39TH STREET/THIRD AV	NNW 0 - 1/8 (0.112 mi.)	K98	214

Facility Id: 2-000787

PUBLIC SCHOOL 24 - B Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-604352	427 38TH STREET	NE 0 - 1/8 (0.119 mi.)	J104	228
CROWN HOLDINGS USA Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-608168	327 43RD STREET	W 1/8 - 1/4 (0.151 mi.)	L150	353
P.S. 371 (OLD 615) - Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-355798	355 37TH STREET	NNE 1/8 - 1/4 (0.170 mi.)	T165	445
321 REALTY LLC Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-467006	321 44TH STREET	WSW 1/8 - 1/4 (0.196 mi.)	X195	514
DLJ ENTERPRISES, LTD Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-610119	260 39TH STREET	NW 1/8 - 1/4 (0.205 mi.)	AG203	653
THE GREEN-WOOD CEMET Database: AST, Date of Government Version: 09/06/2023 Facility Id: 2-004472	921 FOURTH AVENUE	NE 1/8 - 1/4 (0.250 mi.)	AN282	925

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
JACKIE GLEASON (FIFT Facility Status: 1 Facility Status: 1 CBS Number: 2-000283	***871 FIFTH AVENUE***	***E 1/8 - 1/4 (0.154 mi.)***	***Q155***	***387***

Lists of state and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 2 NY VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
4907-4709 4TH AVENUE Database: VCP NYC, Date of Government Version: 09/05/2023	4907 4TH AVENUE	SW 1/4 - 1/2 (0.439 mi.)	AU309	1000

Lower Elevation	Address	Direction / Distance	Map ID	Page
875 4TH AVENUE Database: VCP NYC, Date of Government Version: 09/05/2023	875 4TH AVENUE	NE 1/4 - 1/2 (0.364 mi.)	AQ297	982

EXECUTIVE SUMMARY

Lists of state and tribal brownfield sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 11/06/2023 has revealed that there are 2 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYC DEPT OF EDUCATIO	***840 5TH AVE***	***ENE 1/8 - 1/4 (0.224 mi.)***	***AC236***	***796***
Site Code: 567010				

Lower Elevation	Address	Direction / Distance	Map ID	Page
22-36 SECOND AVENUE	22-36 SECOND AVENUE	NW 1/4 - 1/2 (0.308 mi.)	AO296	979
Site Code: 507964				

ADDITIONAL ENVIRONMENTAL RECORDS

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 01/24/2024 has revealed that there are 25 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SUNSET CAR CARE SITE	***4013 4TH AVENUE***	***SW 0 - 1/8 (0.009 mi.)***	***A14***	***39***
Spill Number/Closed Date: 1506140 / 2021-05-27				
Site ID: 513543				
Spill Date: 2015-08-09				
ROADWAY	4TH AVE & 41ST STREE	WSW 0 - 1/8 (0.027 mi.)	A29	74
Spill Number/Closed Date: 0709105 / 2007-11-21				
Site ID: 390128				
Spill Date: 2007-11-21				
MANHOLE 45501	4TH AVE/41ST ST	WSW 0 - 1/8 (0.027 mi.)	A30	75
Spill Number/Closed Date: 0009003 / 2001-12-21				
Site ID: 273030				
Spill Date: 2000-11-03				
MANHOLE #4049	SW CORN. 41ST & 4TH	WSW 0 - 1/8 (0.027 mi.)	A31	76
Spill Number/Closed Date: 0401833 / 2004-09-07				
Site ID: 92945				
Spill Date: 2004-05-18				
MANHOLE 73170	4TH AVE AND 41ST ST	WSW 0 - 1/8 (0.027 mi.)	A32	77
Spill Number/Closed Date: 0602997 / 2006-10-05				
Site ID: 365592				
Spill Date: 2006-06-18				
Not reported	***444 40 STREET***	***SE 0 - 1/8 (0.033 mi.)***	***A33***	***78***

Spill Number/Closed Date: 0504791 / 2005-09-26
Site ID: 349701
Spill Date: 2005-07-20

444 41ST STREET — 444 41ST STREET — SSE 0 - 1/8 (0.061 mi.) — B50 — 109
Spill Number/Closed Date: 9414357 / 2005-07-13
Site ID: 267140
Spill Date: 1995-01-30

4201 4TH AVE/B'KLYN/ — 4201 4TH AVE — SW 0 - 1/8 (0.074 mi.) — D63 — 141
Spill Number/Closed Date: 8707375 / 1987-12-01
Site ID: 267121
Spill Date: 1987-11-01

SERVICE BOX 48297 — 459 41ST ST — SE 0 - 1/8 (0.074 mi.) — C64 — 142
Spill Number/Closed Date: 9900540 / 2002-06-10
Site ID: 137908
Spill Date: 1999-04-15

MANHOLE 4045 — 4TH AVE/42ND ST — SW 0 - 1/8 (0.076 mi.) — D65 — 143
Spill Number/Closed Date: 0010159 / 2001-12-28
Site ID: 149544
Spill Date: 2000-12-09

BELCHER SPILL INTO H — 4095 5TH AVE — SE 0 - 1/8 (0.123 mi.) — G114 — 246
Spill Number/Closed Date: 8605453 / 1986-11-28
Site ID: 201860
Spill Date: 1986-11-28

Lower Elevation	Address	Direction / Distance	Map ID	Page

MANHOLE 4084 — 40TH ST/4TH AVE — NNW 0 - 1/8 (0.009 mi.) — A13 — 38
Spill Number/Closed Date: 0003749 / 2009-09-10
Site ID: 190436
Spill Date: 2000-06-27

MANHOLE 73167 — 39TH STREET & 4TH AV — NNE 0 - 1/8 (0.050 mi.) — E42 — 97
Spill Number/Closed Date: 0406654 / 2004-09-21
Site ID: 101225
Spill Date: 2004-09-16

VAULT 6035 — 39TH STREET & 4TH AV — NNE 0 - 1/8 (0.050 mi.) — E43 — 98
Spill Number/Closed Date: 0011492 / 2001-06-01
Site ID: 141214
Spill Date: 2001-01-24

SERVICE VAULT 6035 — 39TH ST/4TH AVE — NNE 0 - 1/8 (0.050 mi.) — E44 — 99
Spill Number/Closed Date: 0011269 / 2001-04-18
Site ID: 222736
Spill Date: 2001-01-16

V# VS6058 — 39TH STREET & 4TH AV — NNE 0 - 1/8 (0.055 mi.) — E45 — 100
Spill Number/Closed Date: 9901850 / 1999-10-26
Site ID: 299331
Spill Date: 1999-05-17

USPS — 1050 FOUR BELL ST — NNE 0 - 1/8 (0.078 mi.) — E68 — 147
Spill Number/Closed Date: 1800585 / 2018-04-17
Site ID: 569088
Spill Date: 2018-04-17

PS # 24 — 38TH STREET AND 4TH — NE 0 - 1/8 (0.102 mi.) — J77 — 175

Spill Number/Closed Date: 0603862 / 2006-09-13 Site ID: 366701 Spill Date: 2006-07-07				
341 39TH ST/BKLYN Spill Number/Closed Date: 8809138 / 2004-01-12 Site ID: 201122 Spill Date: 1989-02-24	341 39TH STREET	NNW 0 - 1/8 (0.103 mi.)	F78	177
G & L EYES INC. Spill Number/Closed Date: 0413302 / 2006-11-09 Site ID: 342368 Spill Date: 2005-03-22	***341 39TH ST.***	***N 0 - 1/8 (0.103 mi.)***	***K80***	***180***
COMMERCIAL BUILDING Spill Number/Closed Date: 1512257 / 2016-04-20 Site ID: 525066 Spill Date: 2016-03-26	341 39TH STREET	N 0 - 1/8 (0.103 mi.)	K81	185
PAVEMENT Spill Number/Closed Date: 1004336 / 2010-07-19 Site ID: 437606 Spill Date: 2010-07-19	38TH ST AND 4TH AVE	NNE 0 - 1/8 (0.104 mi.)	J83	190
2- FAMILY HOME Spill Number/Closed Date: 0611029 / 2007-06-27 Site ID: 375595 Spill Date: 2007-01-03	324 41ST STREET	WNW 0 - 1/8 (0.121 mi.)	L108	236
VAULT 3225 Spill Number/Closed Date: 9908076 / 2002-02-20 Site ID: 219409 Spill Date: 1999-10-03	38TH ST/4TH AVE	NE 0 - 1/8 (0.123 mi.)	J112	244
JOKHAN RESIDENCE Spill Number/Closed Date: 0510380 / 2005-12-06 Site ID: 356347 Spill Date: 2005-12-03	322 41ST STREET	WNW 0 - 1/8 (0.124 mi.)	L115	247

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/04/2023 has revealed that there are 79 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BORIS AUTO REPAIR EPA ID:: NYD986985471	***4013 4TH AVE***	***SW 0 - 1/8 (0.009 mi.)***	***A16***	***47***
CON EDISON SERVICE B EPA ID:: NYP004529541	***420 40TH ST***	***ESE 0 - 1/8 (0.011 mi.)***	***A20***	***53***
CON EDISON	***415 40TH ST***	***ENE 0 - 1/8 (0.018 mi.)***	***A24***	***62***

EPA ID:: NYP004754115				
CON EDISON EPA ID:: NYP004793634	***424 41ST ST***	***S 0 - 1/8 (0.039 mi.)***	***B37***	***87***
CON EDISON EPA ID:: NYP004399069	***454 40TH ST***	***SE 0 - 1/8 (0.064 mi.)***	***C52***	***111***
CON EDISON EPA ID:: NYP004818763	4008 5TH AVE	SE 0 - 1/8 (0.108 mi.)	I88	196
CON EDISON SERVICE B EPA ID:: NYP004542809	***417 43RD ST***	***SSW 0 - 1/8 (0.111 mi.)***	***M93***	***204***
CON EDISON EPA ID:: NYP004809616	***421 43RD ST***	***SSW 0 - 1/8 (0.111 mi.)***	***M96***	***210***
CON EDISON EPA ID:: NYP004765558	***4108 5TH AVE***	***SSE 0 - 1/8 (0.117 mi.)***	***G100***	***219***
CON EDISON EPA ID:: NYP004549721	***437 43RD ST***	***SSW 0 - 1/8 (0.118 mi.)***	***M102***	***222***
CON EDISON SERVICE B EPA ID:: NYP004526406	***E 40TH ST & 5TH AVE***	***ESE 0 - 1/8 (0.121 mi.)***	***I111***	***242***
CON EDISON SERVICE B EPA ID:: NYP004454187	***361 43RD ST***	***WSW 1/8 - 1/4 (0.127 mi.)***	***O117***	***252***
CON EDISON SERVICE B EPA ID:: NYP004561239	***365 43RD ST***	***WSW 1/8 - 1/4 (0.128 mi.)***	***O120***	***258***
CON EDISON SERVICE B EPA ID:: NYP004373429	***453 43RD ST***	***S 1/8 - 1/4 (0.129 mi.)***	***P121***	***260***
CON EDISON SERVICE B EPA ID:: NYP004525010	***16-18 E 39TH ST & 5T***	***ESE 1/8 - 1/4 (0.134 mi.)***	***Q124***	***269***
CON EDISON SERVICE B EPA ID:: NYP004571279	418 43RD ST	SSW 1/8 - 1/4 (0.136 mi.)	M128	276
CON EDISON SERVICE B EPA ID:: NYP004378881	***4023 5TH AVE***	***SE 1/8 - 1/4 (0.136 mi.)***	***R129***	***278***
CON EDISON SERVICE B EPA ID:: NYP004384335	***471 43RD ST***	***S 1/8 - 1/4 (0.144 mi.)***	***P136***	***320***
MTA NYCT EPA ID:: NYP000970509	***481 38TH ST IN FRONT***	***ENE 1/8 - 1/4 (0.144 mi.)***	***S138***	***325***
CON EDISON EPA ID:: NYP004831455	***446 43RD ST***	***SSW 1/8 - 1/4 (0.146 mi.)***	***P140***	***329***
CON EDISON SERVICE B EPA ID:: NYP004454146	***358 43RD ST***	***WSW 1/8 - 1/4 (0.147 mi.)***	***O142***	***333***
CON EDISON SERVICE B EPA ID:: NYP004389649	***358 43RD ST FRONT OF***	***WSW 1/8 - 1/4 (0.147 mi.)***	***O143***	***336***
CON EDISON SERVICE B EPA ID:: NYP004489993	452 43RD ST	SSW 1/8 - 1/4 (0.149 mi.)	P145	341
CON EDISON SERVICE B EPA ID:: NYP004549499	***4214 5TH AVE***	***S 1/8 - 1/4 (0.149 mi.)***	***P146***	***343***
CON EDISON SERVICE B EPA ID:: NYP004379012	***352 352 43RD ST***	***WSW 1/8 - 1/4 (0.150 mi.)***	***O148***	***347***
CON EDISON SERVICE B	***454 43RD ST***	***S 1/8 - 1/4 (0.151 mi.)***	***P149***	***350***

EPA ID:: NYP004397154				
NYCTA JACKIE GLEASON EPA ID:: NYD980642300	***871 5TH AVE***	***E 1/8 - 1/4 (0.154 mi.)***	***Q156***	***401***
CON EDISON SERVICE B EPA ID:: NYP004392940	***519 41ST ST***	***SE 1/8 - 1/4 (0.160 mi.)***	***R160***	***431***
CON EDISON SERVICE B EPA ID:: NYP004368056	***518 39TH ST***	***ESE 1/8 - 1/4 (0.160 mi.)***	***Q161***	***434***
CON EDISON SERVICE B EPA ID:: NYP004575841	523 39TH ST	ESE 1/8 - 1/4 (0.177 mi.)	Q169	454
CON EDISON EPA ID:: NYP004735510	***532 39TH ST SB49215***	***ESE 1/8 - 1/4 (0.183 mi.)***	***Y174***	***463***
CON EDISON EPA ID:: NYP004735528	532 39TH ST SB49212	ESE 1/8 - 1/4 (0.183 mi.)	Y177	468
ORTIZ PROPERTIES EPA ID:: NY0001000157	***535 40TH ST***	***ESE 1/8 - 1/4 (0.186 mi.)***	***Y181***	***477***
CON EDISON SERVICE B EPA ID:: NYP004391066	***461 37TH ST***	***ENE 1/8 - 1/4 (0.191 mi.)***	***W187***	***497***
CON EDISON SERVICE B EPA ID:: NYP004569703	37TH ST & 5TH AVE	ENE 1/8 - 1/4 (0.195 mi.)	AC194	512
CON EDISON SERVICE B EPA ID:: NYP004374120	***4402 5TH AVE***	***S 1/8 - 1/4 (0.208 mi.)***	***AH206***	***677***
CON EDISON SERVICE B EPA ID:: NYP004394052	***423 45TH ST***	***SSW 1/8 - 1/4 (0.210 mi.)***	***AB207***	***680***
CON EDISON EPA ID:: NYP004731477	***425 45TH ST***	***SSW 1/8 - 1/4 (0.210 mi.)***	***AB208***	***683***
AMOCO SERVICE STATIO EPA ID:: NY0000562025	***842 5TH AVE***	***ENE 1/8 - 1/4 (0.216 mi.)***	***W217***	***728***
CON EDISON SERVICE B EPA ID:: NYP004394862	***556 40TH ST***	***SE 1/8 - 1/4 (0.216 mi.)***	***Z219***	***747***
CON EDISON EPA ID:: NYP004885105	***472 36TH ST***	***ENE 1/8 - 1/4 (0.216 mi.)***	***W220***	***750***
CON EDISON SERVICE B EPA ID:: NYP004317111	***845 5TH AVE***	***ENE 1/8 - 1/4 (0.217 mi.)***	***AC222***	***754***
CON EDISON EPA ID:: NYP004785812	***45TH ST & 4TH AVE***	***SW 1/8 - 1/4 (0.222 mi.)***	***AB232***	***787***
CON EDISON EPA ID:: NYP004735239	***337 45TH ST***	***WSW 1/8 - 1/4 (0.226 mi.)***	***AD241***	***811***
CON EDISON EPA ID:: NYP004762985	4511 4TH AVE SB45506	SW 1/8 - 1/4 (0.227 mi.)	AB243	843
CON EDISON EPA ID:: NYP004762993	4511 4TH AVE MH5827	SW 1/8 - 1/4 (0.227 mi.)	AB248	850
CON EDISON EPA ID:: NYP004763009	4511 4TH AVE MH5826	SW 1/8 - 1/4 (0.227 mi.)	AB251	856
CON EDISON EPA ID:: NYP004727517	***333 45TH ST***	***WSW 1/8 - 1/4 (0.230 mi.)***	***AD257***	***866***
CON EDISON	***563 41ST ST***	***SE 1/8 - 1/4 (0.230 mi.)***	***Z258***	***869***

EPA ID:: NYP004841421

CON EDISON	***566 40TH ST***	***SE 1/8 - 1/4 (0.233 mi.)***	***AJ263***	***876***
EPA ID:: NYP004760906				
CON EDISON MANHOLE 3	***5 AVE & 36 ST***	***ENE 1/8 - 1/4 (0.237 mi.)***	***AK267***	***884***
EPA ID:: NYP004142600				
CON EDISON MANHOLE 6	***36 ST & 5TH AVE***	***ENE 1/8 - 1/4 (0.237 mi.)***	***AK268***	***889***
EPA ID:: NYP004148185				
CON EDISON SERVICE B	***502 36TH ST***	***ENE 1/8 - 1/4 (0.238 mi.)***	***AC270***	***894***
EPA ID:: NYP004374211				

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE B	***354 41ST ST FRONT OF***	***W 0 - 1/8 (0.073 mi.)***	***D60***	***134***
EPA ID:: NYP004391520				
CON EDISON MANHOLE:	***346 39TH ST***	***NNW 0 - 1/8 (0.084 mi.)***	***F70***	***150***
EPA ID:: NYP004272829				
CON EDISON SERVICE B	***335 42ND ST***	***W 0 - 1/8 (0.110 mi.)***	***L91***	***200***
EPA ID:: NYP004383865				
CON EDISON SERVICE B	***331 39TH ST***	***NNW 0 - 1/8 (0.120 mi.)***	***K107***	***233***
EPA ID:: NYP004392395				
CON EDISON	***317 40TH ST***	***NW 0 - 1/8 (0.121 mi.)***	***N110***	***239***
EPA ID:: NYP004486973				
MERIT FOURTH	***969 4TH AVE***	***NNE 1/8 - 1/4 (0.125 mi.)***	***J116***	***249***
EPA ID:: NYD982185910				
CON EDISON SERVICE B	***319 42ND ST***	***W 1/8 - 1/4 (0.129 mi.)***	***L122***	***264***
EPA ID:: NYP004383857				
CON EDISON SERVICE B	***313 39TH ST***	***NNW 1/8 - 1/4 (0.139 mi.)***	***K130***	***281***
EPA ID:: NYP004414272				
CON EDISON SERVICE B	***313 42 ST***	***WNW 1/8 - 1/4 (0.139 mi.)***	***L131***	***285***
EPA ID:: NYP004384251				
CON EDISON	***4TH AVE & 37TH ST***	***NNE 1/8 - 1/4 (0.152 mi.)***	***T152***	***356***
EPA ID:: NYP004729158				
METRO 1 AMBULANCE SE	***350 37TH ST***	***NNE 1/8 - 1/4 (0.153 mi.)***	***T154***	***381***
EPA ID:: NYR000062257				
CON EDISON SERVICE B	***4018 3RD AVE***	***WNW 1/8 - 1/4 (0.168 mi.)***	***U162***	***437***
EPA ID:: NYP004327599				
CON EDISON	***38TH ST & 3RD AVE***	***NNW 1/8 - 1/4 (0.170 mi.)***	***V163***	***441***
EPA ID:: NYP004843781				
CON EDISON SERVICE B	***43RD AVE & 3RD ST N***	***W 1/8 - 1/4 (0.181 mi.)***	***X171***	***458***
EPA ID:: NYP004484671				
CON EDISON SERVICE B	***4317 3RD AVE***	***W 1/8 - 1/4 (0.186 mi.)***	***X178***	***470***
EPA ID:: NYP004325569				
CON EDISON SERVICE B	***268 40TH ST***	***NW 1/8 - 1/4 (0.188 mi.)***	***U182***	***481***
EPA ID:: NYP004376687				
NYSDOT D254608 GOWAN	***255 42ND ST***	***WNW 1/8 - 1/4 (0.218 mi.)***	***AA223***	***759***
EPA ID:: NY0000045005				
CON EDISON	***258 42ND ST MH48386***	***WNW 1/8 - 1/4 (0.220 mi.)***	***AA227***	***775***

EPA ID:: NYP004744884				
CON EDISON EPA ID:: NYP004744892	258 42ND ST MH48383	WNW 1/8 - 1/4 (0.220 mi.)	AA228	779
CON EDISON SERVICE B EPA ID:: NYP004325452	***4409 3RD AVE***	***WSW 1/8 - 1/4 (0.220 mi.)***	***AI230***	***782***
CON EDISON SERVICE B EPA ID:: NYP004325460	***4417 3RD AVE***	***WSW 1/8 - 1/4 (0.223 mi.)***	***AI233***	***789***
LOUIS BRESSOUD INC EPA ID:: NYR000092171	***270 43RD ST***	***W 1/8 - 1/4 (0.226 mi.)***	***X238***	***805***
CON EDISON SERVICE B EPA ID:: NYP004379061	***337 36TH ST***	***NNE 1/8 - 1/4 (0.227 mi.)***	***AE252***	***858***
CON EDISON MANHOLE: EPA ID:: NYP004412581	***940 4TH AVE***	***NNE 1/8 - 1/4 (0.234 mi.)***	***AE264***	***879***
INDUSTRY CITY ASSOCI EPA ID:: NY0000882027	***241 37TH ST***	***NNW 1/8 - 1/4 (0.245 mi.)***	***AM273***	***902***
CON EDISON SERVICE B EPA ID:: NYP004379053	***315 36TH ST***	***N 1/8 - 1/4 (0.246 mi.)***	***AF274***	***908***

FUDS: The Listing includes locations of Formerly Used Defense Sites Properties where the US Army Corps Of Engineers is actively working or will take necessary cleanup actions.

A review of the FUDS list, as provided by EDR, and dated 09/28/2023 has revealed that there are 3 FUDS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PIER 6 BUSH TERMINAL		WNW 1/2 - 1 (0.501 mi.)	315	1009
MIL MED SUPPLY NO. 1		NNE 1/2 - 1 (0.543 mi.)	317	1010
US ARMED GUARD CENTE		W 1/2 - 1 (0.667 mi.)	319	1013

FUSRAP: DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

A review of the FUSRAP list, as provided by EDR, and dated 03/03/2023 has revealed that there is 1 FUSRAP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
AMERICAN MACHINE AND Site Status: Eliminated from consideration under FUSRAP Site ID: NY 26	SECOND AVENUE AND 56	WSW 1/2 - 1 (0.822 mi.)	321	1033

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 11/29/2023 has revealed that there is 1 NY DRYCLEANERS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BAYRIDGE FRENCH CLEA	***4414 5TH AVENUE***	***S 1/8 - 1/4 (0.227 mi.)***	***AH242***	***814***

EXECUTIVE SUMMARY

Facility Id: 2-6102-00380

NY E DESIGNATION: Lots designation with an ?E? on the Zoning Maps of the City of New York for potential hazardous material contamination, air and/or noise quality impacts.

A review of the NY E DESIGNATION list, as provided by EDR, and dated 07/26/2023 has revealed that there are 4 NY E DESIGNATION sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LOT 1,TAXBLOCK 714		SW 0 - 1/8 (0.009 mi.)	A18	51
LOT 1,TAXBLOCK 714	***4013 4 AVENUE***	***SW 0 - 1/8 (0.009 mi.)***	***A19***	***51***
LOT 6,TAXBLOCK 719	***4111 4 AVENUE***	***SW 0 - 1/8 (0.039 mi.)***	***A36***	***85***

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 42,TAXBLOCK 708	***3918 4 AVENUE***	***NNW 0 - 1/8 (0.036 mi.)***	***A35***	***83***

NY HSWDS: The List includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity The latest version of the study is frozen in time. The sites on the study will not automatically be made superfund sites, rather each site will be further evaluated for listing in the registry. So overtime they will be added to the registry or not.

A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there are 2 NY HSWDS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
G & L EYES INC.	***341 39TH ST.***	***N 0 - 1/8 (0.103 mi.)***	***K80***	***180***
BLATCHFORD BASE PLAN	32 33RD ST.	N 1/4 - 1/2 (0.432 mi.)	AT307	997

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 12/31/2019 has revealed that there are 110 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - SERVICE EPA ID: NYP004951388	412 40 ST	0 - 1/8 (0.000 mi.)	A12	38
CON EDISON EPA ID: NYP004529541	420 40TH ST	ESE 0 - 1/8 (0.011 mi.)	A21	56
CON EDISON - SERVICE EPA ID: NYP004404968	***415 40 ST***	***ENE 0 - 1/8 (0.018 mi.)***	***A25***	***65***
CON EDISON EPA ID: NYP004754115	415 40TH ST	ENE 0 - 1/8 (0.018 mi.)	A26	68
CON EDISON	424 41ST ST	S 0 - 1/8 (0.039 mi.)	B38	90

EPA ID: NYP004793634				
CONSOLIDATED EDISON EPA ID: NYP004133674	MH49287-444 40TH ST	ESE 0 - 1/8 (0.041 mi.)	C40	92
CON EDISON EPA ID: NYP004399069	454 40TH ST	SE 0 - 1/8 (0.064 mi.)	C51	110
CON EDISON EPA ID: NYP004612933	423 39 ST	ENE 0 - 1/8 (0.069 mi.)	E59	133
NYC DEPT OF ED - PS EPA ID: NYR000134783	***4222 4TH AVE***	***SW 0 - 1/8 (0.087 mi.)***	***D72***	***155***
CON EDISON EPA ID: NYP004400784	467 40TH ST	ESE 0 - 1/8 (0.089 mi.)	C73	169
CON EDISON EPA ID: NYP004719068	449 39 ST	E 0 - 1/8 (0.089 mi.)	H74	171
CON EDISON EPA ID: NYP005087527	476 40TH ST	SE 0 - 1/8 (0.096 mi.)	I76	174
CON EDISON - MANHOLE EPA ID: NYP005089741	4002 5TH AVE	SE 0 - 1/8 (0.105 mi.)	I85	194
CON EDISON EPA ID: NYP004818763	4008 5TH AVE	SE 0 - 1/8 (0.108 mi.)	I89	198
CON EDISON EPA ID: NYP004542809	417 43RD ST	SSW 0 - 1/8 (0.111 mi.)	M92	203
CON EDISON EPA ID: NYP004809616	421 43RD ST	SSW 0 - 1/8 (0.111 mi.)	M97	213
CON EDISON EPA ID: NYP004765558	4108 5TH AVE	SSE 0 - 1/8 (0.117 mi.)	G99	217
CON EDISON EPA ID: NYP004549721 EPA ID: NYP004794343	437 43RD ST	SSW 0 - 1/8 (0.118 mi.)	M103	225
CON EDISON SERVICE B EPA ID: NYP004454187	***361 43RD ST***	***WSW 1/8 - 1/4 (0.127 mi.)***	***O117***	***252***
CON EDISON EPA ID: NYP004586993	359 43 ST	WSW 1/8 - 1/4 (0.127 mi.)	O118	256
CON EDISON EPA ID: NYP004561239	365 43RD ST	WSW 1/8 - 1/4 (0.128 mi.)	O119	256
CON EDISON SERVICE B EPA ID: NYP004373429	***453 43RD ST***	***S 1/8 - 1/4 (0.129 mi.)***	***P121***	***260***
CON EDISON EPA ID: NYP004691838	418 43RD ST	SSW 1/8 - 1/4 (0.136 mi.)	M125	272
CON EDISON EPA ID: NYP004698379	FRONT OF 418 43 ST	SSW 1/8 - 1/4 (0.136 mi.)	M126	273
CON EDISON EPA ID: NYP004571279	418 43RD ST	SSW 1/8 - 1/4 (0.136 mi.)	M127	274
CON EDISON SERVICE B EPA ID: NYP004378881	***4023 5TH AVE***	***SE 1/8 - 1/4 (0.136 mi.)***	***R129***	***278***
NYC DOE - PS 557K EPA ID: NYR000251066	4302 4TH AVE	SW 1/8 - 1/4 (0.141 mi.)	O133	291
CON EDISON - MANHOLE	507 41ST ST	SE 1/8 - 1/4 (0.144 mi.)	R135	320

EPA ID: NYP004954705				
CON EDISON SERVICE B EPA ID: NYP004384335	***471 43RD ST***	***S 1/8 - 1/4 (0.144 mi.)***	***P136***	***320***
NYCT EPA ID: NYP000970509	481 38TH ST IN FRONT	ENE 1/8 - 1/4 (0.144 mi.)	S137	324
CON EDISON EPA ID: NYP004831455	446 43RD ST	SSW 1/8 - 1/4 (0.146 mi.)	P139	328
CON EDISON SERVICE B EPA ID: NYP004454146	***358 43RD ST***	***WSW 1/8 - 1/4 (0.147 mi.)***	***O142***	***333***
CON EDISON SERVICE B EPA ID: NYP004389649	***358 43RD ST FRONT OF***	***WSW 1/8 - 1/4 (0.147 mi.)***	***O143***	***336***
CON EDISON EPA ID: NYP004489993	452 43RD ST	SSW 1/8 - 1/4 (0.149 mi.)	P144	339
CON EDISON EPA ID: NYP004549499	4214 5TH AVE	S 1/8 - 1/4 (0.149 mi.)	P147	345
CON EDISON SERVICE B EPA ID: NYP004379012	***352 352 43RD ST***	***WSW 1/8 - 1/4 (0.150 mi.)***	***O148***	***347***
CON EDISON SERVICE B EPA ID: NYP004397154	***454 43RD ST***	***S 1/8 - 1/4 (0.151 mi.)***	***P149***	***350***
CON EDISON SERVICE B EPA ID: NYP004392940	***519 41ST ST***	***SE 1/8 - 1/4 (0.160 mi.)***	***R160***	***431***
CON EDISON SERVICE B EPA ID: NYP004368056	***518 39TH ST***	***ESE 1/8 - 1/4 (0.160 mi.)***	***Q161***	***434***
CON EDISON EPA ID: NYP004575841	523 39TH ST	ESE 1/8 - 1/4 (0.177 mi.)	Q168	453
CON EDISON EPA ID: NYP004400586	457 37TH ST	ENE 1/8 - 1/4 (0.180 mi.)	W170	456
CON EDISON EPA ID: NYP004735528	532 39TH ST SB49212	ESE 1/8 - 1/4 (0.183 mi.)	Y173	461
CON EDISON EPA ID: NYP000473510	532 39 ST	ESE 1/8 - 1/4 (0.183 mi.)	Y176	467
ORTIZ PROPERTIES EPA ID: NY0001000157	***535 40TH ST***	***ESE 1/8 - 1/4 (0.186 mi.)***	***Y181***	***477***
CON EDISON SERVICE B EPA ID: NYP004391066	***461 37TH ST***	***ENE 1/8 - 1/4 (0.191 mi.)***	***W187***	***497***
CON EDISON - MANHOLE EPA ID: NYP004993034	37TH ST & 5TH AVE	ENE 1/8 - 1/4 (0.195 mi.)	AC191	506
CON EDISON EPA ID: NYP004569703	37TH ST & 5TH AVE	ENE 1/8 - 1/4 (0.195 mi.)	AC192	506
CON EDISON - MANHOLE EPA ID: NYP004197851	***EAST 5TH AVE AND 37T***	***ENE 1/8 - 1/4 (0.195 mi.)***	***AC193***	***508***
CON EDISON - CUSTOME EPA ID: NYP005012612	348 44 ST	WSW 1/8 - 1/4 (0.199 mi.)	AD197	642
CON EDISON EPA ID: NYP004391280	***541 39TH ST***	***ESE 1/8 - 1/4 (0.204 mi.)***	***Y201***	***647***
CON EDISON SERVICE B	***4402 5TH AVE***	***S 1/8 - 1/4 (0.208 mi.)***	***AH206***	***677***

EPA ID: NYP004374120				
CON EDISON SERVICE B EPA ID: NYP004394052	***423 45TH ST***	***SSW 1/8 - 1/4 (0.210 mi.)***	***AB207***	***680***
NYNEX EPA ID: NYP000917336	44TH ST & 5TH AVE	S 1/8 - 1/4 (0.210 mi.)	AH209	686
NYCTA - JACKIE GLEAS EPA ID: NYD980642300	***845 5TH AVE***	***ENE 1/8 - 1/4 (0.211 mi.)***	***AC213***	***710***
AMOCO SERVICE STATIO EPA ID: NY0000562025	***842 5TH AVE***	***ENE 1/8 - 1/4 (0.216 mi.)***	***W217***	***728***
CON EDISON SERVICE B EPA ID: NYP004394862	***556 40TH ST***	***SE 1/8 - 1/4 (0.216 mi.)***	***Z219***	***747***
CON EDISON SERVICE B EPA ID: NYP004317111 EPA ID: NYP004168969	***845 5TH AVE***	***ENE 1/8 - 1/4 (0.217 mi.)***	***AC222***	***754***
CON EDISON EPA ID: NYP004585253	347 45 ST	WSW 1/8 - 1/4 (0.221 mi.)	AD231	785
NYC DEPT OF EDUCATIO EPA ID: NYR000238626	***840 5TH AVE***	***ENE 1/8 - 1/4 (0.224 mi.)***	***AC236***	***796***
CON EDISON EPA ID: NYP004735239	337 45TH ST	WSW 1/8 - 1/4 (0.226 mi.)	AD240	810
BAYRIDGE FRENCH CLEA EPA ID: NY0000359703	***4414 5TH AVENUE***	***S 1/8 - 1/4 (0.227 mi.)***	***AH242***	***814***
CON EDISON EPA ID: NYP004762985	4511 4TH AVE SB45506	SW 1/8 - 1/4 (0.227 mi.)	AB246	847
CON EDISON EPA ID: NYP004763009	4511 4TH AVE MH5826	SW 1/8 - 1/4 (0.227 mi.)	AB247	849
CON EDISON EPA ID: NYP004762993	4511 4TH AVE MH5827	SW 1/8 - 1/4 (0.227 mi.)	AB249	853
CON EDISON EPA ID: NYP004741070	46TH ST & 4TH AVE	SW 1/8 - 1/4 (0.229 mi.)	AB254	862
CON EDISON EPA ID: NYP004727517	333 45TH ST	WSW 1/8 - 1/4 (0.230 mi.)	AD255	864
CON EDISON EPA ID: NYP004841421	563 41ST ST	SE 1/8 - 1/4 (0.230 mi.)	Z259	871
CON EDISON EPA ID: NYP004760906	566 40TH ST	SE 1/8 - 1/4 (0.233 mi.)	AJ261	874
CONSOLIDATED EDISON EPA ID: NYP004129136	36 ST & 5 AVE MH7606	ENE 1/8 - 1/4 (0.236 mi.)	AC265	882
CON EDISON - MANHOLE EPA ID: NYP004993026	36TH ST & 5TH AVE	ENE 1/8 - 1/4 (0.237 mi.)	AK266	884
CON EDISON MANHOLE 3 EPA ID: NYP004142600	***5 AVE & 36 ST***	***ENE 1/8 - 1/4 (0.237 mi.)***	***AK267***	***884***
CON EDISON MANHOLE 6 EPA ID: NYP004148185	***36 ST & 5TH AVE***	***ENE 1/8 - 1/4 (0.237 mi.)***	***AK268***	***889***
CON EDISON SERVICE B EPA ID: NYP004374211	***502 36TH ST***	***ENE 1/8 - 1/4 (0.238 mi.)***	***AC270***	***894***
CON EDISON - MANHOLE	***442 45 ST***	***SSW 1/8 - 1/4 (0.238 mi.)***	***AL271***	***898***

EPA ID: NYP004392056

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID: NYP004718946	F/O 3907 4TH AVE	NE 0 - 1/8 (0.034 mi.)	A34	82
CON EDISON SERVICE B EPA ID: NYP004391520	***354 41ST ST FRONT OF***	***W 0 - 1/8 (0.073 mi.)***	***D60***	***134***
CON EDISON EPA ID: NYP004635439	OPP 354 41 ST	W 0 - 1/8 (0.073 mi.)	D61	138
CON EDISON MANHOLE: EPA ID: NYP004272829	***346 39TH ST***	***NNW 0 - 1/8 (0.084 mi.)***	***F70***	***150***
CON EDISON SERVICE B EPA ID: NYP004383865	***335 42ND ST***	***W 0 - 1/8 (0.110 mi.)***	***L91***	***200***
CON EDISON SERVICE B EPA ID: NYP004392395	***331 39TH ST***	***NNW 0 - 1/8 (0.120 mi.)***	***K107***	***233***
CON EDISION EPA ID: NYP004486973	317 40TH ST	NW 0 - 1/8 (0.121 mi.)	N109	238
CON EDISON SERVICE B EPA ID: NYP004383857	***319 42ND ST***	***W 1/8 - 1/4 (0.129 mi.)***	***L122***	***264***
CON EDISON SERVICE B EPA ID: NYP004414272	***313 39TH ST***	***NNW 1/8 - 1/4 (0.139 mi.)***	***K130***	***281***
CON EDISON SERVICE B EPA ID: NYP004384251	***313 42 ST***	***WNW 1/8 - 1/4 (0.139 mi.)***	***L131***	***285***
METRO 1 AMBULANCE SE EPA ID: NYR000062257	***350 37TH ST***	***NNE 1/8 - 1/4 (0.153 mi.)***	***T154***	***381***
CON EDISON SERVICE B EPA ID: NYP004327599	***4018 3RD AVE***	***WNW 1/8 - 1/4 (0.168 mi.)***	***U162***	***437***
NYC DEPT OF EDUCATIO EPA ID: NYR000214080	355 37TH ST	NNE 1/8 - 1/4 (0.170 mi.)	T164	443
CON EDISON SERVICE B EPA ID: NYP004325569	***4317 3RD AVE***	***W 1/8 - 1/4 (0.186 mi.)***	***X178***	***470***
CON EDISON SERVICE B EPA ID: NYP004376687	***268 40TH ST***	***NW 1/8 - 1/4 (0.188 mi.)***	***U182***	***481***
CON EDISON - MANHOLE EPA ID: NYP004190732	***OPP 4202 3RD AVE & 4***	***WNW 1/8 - 1/4 (0.190 mi.)***	***AA186***	***492***
CON EDISON - MANHOLE EPA ID: NYP004977114 EPA ID: NYP005032164	941 4TH AVE	NE 1/8 - 1/4 (0.194 mi.)	T189	502
EAST END WOOD STRIPP EPA ID: NYR000147389	***4218 3RD AVE***	***W 1/8 - 1/4 (0.199 mi.)***	***X196***	***516***
NYC DEPT OF EDUCATIO EPA ID: NYR000242230	360 36TH ST	NNE 1/8 - 1/4 (0.202 mi.)	AE198	643
CON EDISON EPA ID: NYP004617189	319 37 ST	N 1/8 - 1/4 (0.202 mi.)	AF200	646
COSTCO WHOLESALE #03 EPA ID: NYR000030353	***976 3RD AVE***	***NNW 1/8 - 1/4 (0.206 mi.)***	***V204***	***655***
CON EDISON	334 36TH STREET	N 1/8 - 1/4 (0.213 mi.)	AE214	721

EPA ID: NYP004383519				
NYSDOT D254608 GOWAN EPA ID: NY0000045005	***255 42ND ST***	***WNW 1/8 - 1/4 (0.218 mi.)***	***AA223***	***759***
CON EDISON EPA ID: NYP004744884	258 42ND ST	WNW 1/8 - 1/4 (0.220 mi.)	AA224	771
CON EDISON EPA ID: NYP004744892	258 42ND ST MH48383	WNW 1/8 - 1/4 (0.220 mi.)	AA226	774
CON EDISON SERVICE B EPA ID: NYP004325452	***4409 3RD AVE***	***WSW 1/8 - 1/4 (0.220 mi.)***	***AI230***	***782***
CON EDISON SERVICE B EPA ID: NYP004325460	***4417 3RD AVE***	***WSW 1/8 - 1/4 (0.223 mi.)***	***AI233***	***789***
CON EDISON SERVICE B EPA ID: NYP004379061	***337 36TH ST***	***NNE 1/8 - 1/4 (0.227 mi.)***	***AE252***	***858***
CON EDISON EPA ID: NYP004400792	461 36TH ST	ENE 1/8 - 1/4 (0.228 mi.)	W253	861
CON EDISON MANHOLE: EPA ID: NYP004412581	***940 4TH AVE***	***NNE 1/8 - 1/4 (0.234 mi.)***	***AE264***	***879***
CONSOLIDATED EDISON EPA ID: NYP000928200	257 W 39TH ST	NW 1/8 - 1/4 (0.238 mi.)	AG269	892
CON EDISON - MANHOLE EPA ID: NYP004904387	230 39 ST	NW 1/8 - 1/4 (0.244 mi.)	AG272	902
INDUSTRY CITY ASSOCI EPA ID: NY0000882027	***241 37TH ST***	***NNW 1/8 - 1/4 (0.245 mi.)***	***AM273***	***902***
CON EDISON SERVICE B EPA ID: NYP004379053	***315 36TH ST***	***N 1/8 - 1/4 (0.246 mi.)***	***AF274***	***908***
CON EDISON - VAULT S EPA ID: NYP005194444	233 37TH ST	NNW 1/8 - 1/4 (0.248 mi.)	AM276	914
CON EDISON - VAULT S EPA ID: NYP005194451	233 37TH ST	NNW 1/8 - 1/4 (0.248 mi.)	AM277	914

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there are 2 PA MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED EDISON Generator EPA Id: NYP005046067	879 FIFTH AVE	E 1/8 - 1/4 (0.151 mi.)	Q151	356

Lower Elevation	Address	Direction / Distance	Map ID	Page
COSTCO # 318 Generator EPA Id: NYR000030353	976 THIRD AVE	NNW 1/8 - 1/4 (0.206 mi.)	V205	675

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 23 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004754115	415 40TH ST	ENE 0 - 1/8 (0.018 mi.)	A27	70
CON EDISON EPA Id: NYP004793634	424 41ST ST	S 0 - 1/8 (0.039 mi.)	B39	91
NYC DEPT OF ED - PS EPA Id: NYR000134783	***4222 4TH AVE***	***SW 0 - 1/8 (0.087 mi.)***	***D72***	***155***
CON EDISON EPA Id: NYP004818763	4008 5TH AVE	SE 0 - 1/8 (0.108 mi.)	I87	194
CON EDISON EPA Id: NYP004809616	421 43RD ST	SSW 0 - 1/8 (0.111 mi.)	M95	209
CON EDISON EPA Id: NYP004765558	4108 5TH AVE	SSE 0 - 1/8 (0.117 mi.)	G101	221
CON EDISON EPA Id: NYP004831455	446 43RD ST	SSW 1/8 - 1/4 (0.146 mi.)	P141	331
NYCTA JACKIE GLEASON EPA Id: NYD980642300	***871 5TH AVE***	***E 1/8 - 1/4 (0.154 mi.)***	***Q156***	***401***
CON EDISON EPA Id: NYP004735528	532 39TH ST SB49212	ESE 1/8 - 1/4 (0.183 mi.)	Y172	460
CON EDISON EPA Id: NYP004735510	532 39TH ST SB49215	ESE 1/8 - 1/4 (0.183 mi.)	Y175	465
CON EDISON EPA Id: NYP004885105	472 36TH ST	ENE 1/8 - 1/4 (0.216 mi.)	W221	753
CON EDISON EPA Id: NYP004735239	337 45TH ST	WSW 1/8 - 1/4 (0.226 mi.)	AD239	809
CON EDISON EPA Id: NYP004762985	4511 4TH AVE SB45506	SW 1/8 - 1/4 (0.227 mi.)	AB244	845
CON EDISON EPA Id: NYP004762993	4511 4 AVE	SW 1/8 - 1/4 (0.227 mi.)	AB245	846
CON EDISON EPA Id: NYP004763009	4511 4TH AVE MH5826	SW 1/8 - 1/4 (0.227 mi.)	AB250	854
CON EDISON EPA Id: NYP004727517	333 45TH ST	WSW 1/8 - 1/4 (0.230 mi.)	AD256	865
CON EDISON EPA Id: NYP004841421	563 41ST ST	SE 1/8 - 1/4 (0.230 mi.)	Z260	873
CON EDISON EPA Id: NYP004760906	566 40TH ST	SE 1/8 - 1/4 (0.233 mi.)	AJ262	875

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE: EPA Id: NYP004272829	346 39TH ST	NNW 0 - 1/8 (0.084 mi.)	F71	154
CON EDISON - MANHOLE	***OPP 4202 3RD AVE & 4***	***WNW 1/8 - 1/4 (0.190 mi.)***	***AA186***	***492***

EPA Id: NYP004190732				
EAST END WOOD STRIPP	***4218 3RD AVE***	***W 1/8 - 1/4 (0.199 mi.)***	***X196***	***516***
EPA Id: NYR000147389				
CON EDISON	258 42ND ST	WNW 1/8 - 1/4 (0.220 mi.)	AA225	773
EPA Id: NYP004744884				
CON EDISON	258 42ND ST MH48383	WNW 1/8 - 1/4 (0.220 mi.)	AA229	781
EPA Id: NYP004744892				

NY NYC OER: Properties remediated under OER's oversight, both in the E-Designation program and the NYC Voluntary Cleanup Program. Includes sites completed and in progress.

A review of the NY NYC OER list, as provided by EDR, and dated 06/04/2023 has revealed that there are 5 NY NYC OER sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
4907-4709 4TH AVENUE	4907 4TH AVENUE	SW 1/4 - 1/2 (0.439 mi.)	AU310	1000
5111 4TH AVENUE	5111 4TH AVENUE	SW 1/2 - 1 (0.522 mi.)	316	1009
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
875 4TH AVENUE	***875 4TH AVENUE***	***NE 1/4 - 1/2 (0.364 mi.)***	***AQ298***	***982***
179 22ND STREET	691 4TH AVENUE	NE 1/2 - 1 (0.899 mi.)	AW327	1048
CON EDISON SERVICE B	***683 4TH AVE***	***NE 1/2 - 1 (0.919 mi.)***	***AW328***	***1048***

NY MGP: From the late 1800's to the mid 1900's, hundreds of manufactured gas plants across New York State supplied homes and industry with fuel for heating, cooking, and lighting. Today, the New York State DEC is overseeing the investigation and cleanup of contamination left behind from these plants.

A review of the NY MGP list, as provided by EDR, and dated 11/15/2021 has revealed that there is 1 NY MGP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
K - KINGS COUNTY WOR	***55TH ST & 1ST AVE***	***WSW 1/2 - 1 (0.842 mi.)***	***AV323***	***1034***

UST FINDER RELEASE: US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

A review of the UST FINDER RELEASE list, as provided by EDR, and dated 06/08/2023 has revealed that there are 9 UST FINDER RELEASE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
871 5TH AV/JACKIE GL	871 5TH AVE	E 1/8 - 1/4 (0.154 mi.)	Q157	424
FORMER GETTY S/S #98	602 39TH ST	ESE 1/4 - 1/2 (0.300 mi.)	295	978
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
MOBIL S/S	987 4TH AVE	NE 0 - 1/8 (0.069 mi.)	E58	132
971-975 4TH AVE.	971 4TH AVE	NNE 0 - 1/8 (0.119 mi.)	J105	231

Lower Elevation	Address	Direction / Distance	Map ID	Page
GREENWOOD CEMETERY	921 4TH AVENUE	NE 1/8 - 1/4 (0.250 mi.)	AN280	922
SHOW AUTO SALES -MTB	4001 SECOND AVE	NW 1/4 - 1/2 (0.290 mi.)	AO288	946
BELL ATLANTIC	230 43RD ST	W 1/4 - 1/2 (0.294 mi.)	290	948
BUSH TERMINAL EDC -D	4104 FIRST AVENUE	WNW 1/4 - 1/2 (0.459 mi.)	311	1001
RED HOOK MARINE/PT A	RED HOOK MARINE TERM	N 1/4 - 1/2 (0.490 mi.)	314	1008

UST FINDER: EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

A review of the UST FINDER list, as provided by EDR, and dated 06/08/2023 has revealed that there are 9 UST FINDER sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SUNSET GARDENS SENIO	405 44TH STREET	SW 1/8 - 1/4 (0.160 mi.)	M158	425
533 41 ST	533 41ST STREET	SE 1/8 - 1/4 (0.186 mi.)	Z180	476
540-40 STREET	540 40TH STREET	SE 1/8 - 1/4 (0.190 mi.)	Z185	491
JACKIE GLEASON BUS D	845 5TH AVENUE	ENE 1/8 - 1/4 (0.211 mi.)	AC210	687
SHELL SERVICE STATIO	842 FIFTH AVENUE	ENE 1/8 - 1/4 (0.216 mi.)	W216	725
DELIZZA REALTY INC	840 5TH AVENUE	ENE 1/8 - 1/4 (0.224 mi.)	AC234	792

Lower Elevation	Address	Direction / Distance	Map ID	Page
FRED ALIMONDA	357 40TH STREET	NNW 0 - 1/8 (0.057 mi.)	F46	101
MOBIL S/S F7FYG C&M	987-993 4TH AVENUE	NE 0 - 1/8 (0.069 mi.)	E57	129
THE GREEN-WOOD CEMET	921 FOURTH AVENUE	NE 1/8 - 1/4 (0.250 mi.)	AN281	923

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
KINGS COUNTY WORKS	55TH ST. AND 1ST AVE	WSW 1/2 - 1 (0.827 mi.)	AV322	1034

EXECUTIVE SUMMARY

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 3 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BATAN TOWING SERVICE	4013 4TH AVE	SW 0 - 1/8 (0.009 mi.)	A17	50

Lower Elevation	Address	Direction / Distance	Map ID	Page
DLJ ENTERPRISES	987 4TH AVENUE	NE 0 - 1/8 (0.069 mi.)	E55	125
BIG APPLE MOBIL	984-4TH AVENUE	NNE 0 - 1/8 (0.105 mi.)	J86	194

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 2 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.


Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CLEAN RITE CLEANERS	442 39TH ST	E 0 - 1/8 (0.077 mi.)	C67	147
CARLINO BROS FINST F	3916 5TH AVENUE	ESE 0 - 1/8 (0.109 mi.)	I90	199

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 9 records.

Site Name	Database(s)
BROOKLYN MILITARY OCEAN TERMINAL	NY SHWS
DAVIDSON PIPE SUPPLY COMPANY	NY SHWS
CARROL GARDEN	SEMS-ARCHIVE
REAR BUSH TERMINAL BUILDING	SEMS-ARCHIVE
NORTHEAST MARINE TERMINAL CO INC	CORRACTS, RCRA NonGen / NLR
25 ST & 4TH AVENUE	NY Spills
USPS GOWANUS SITE, FORMER MGP METR	NY VCP, NY MGP
455 SMITH STREET (VICHAR, INC.)	NY VCP
DANGMAN PARK	NY VCP

OVERVIEW MAP - 7571432.2S



0 1/4 1/2 1 Miles


- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	4001 4th Avenue	CLIENT:	Lesova Environmental Group
ADDRESS:	4001 4th Avenue Brooklyn NY 11232	CONTACT:	Dhruvi Patel
		INQUIRY #:	7571432.2s
LAT/LONG:	40.651717 / 74.006618	DATE:	February 16, 2024 4:05 pm

Copyright © 2024 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 7571432.2S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 4001 4th Avenue	CLIENT: Lesova Environmental Group
ADDRESS: 4001 4th Avenue Brooklyn NY 11232	CONTACT: Dhruvi Patel
LAT/LONG: 40.651717 / 74.006618	INQUIRY #: 7571432.2s DATE: February 16, 2024 4:07 pm

Copyright © 2024 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	1	NR	NR	1
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		3	8	NR	NR	NR	11
RCRA-SQG	0.250		2	3	NR	NR	NR	5
RCRA-VSQG	0.250		0	2	NR	NR	NR	2
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		1	0	0	6	NR	7
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500		0	0	1	NR	NR	1
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		6	3	19	NR	NR	28
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250	1	2	8	NR	NR	NR	11
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	1	NR	NR	NR	1
NY AST	0.250	1	13	11	NR	NR	NR	25
NY CBS AST	0.250		0	1	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	0	NR	NR	0
NY INST CONTROL	0.500		0	0	0	NR	NR	0
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	2	NR	NR	2
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		0	1	1	NR	NR	2
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125	2	25	NR	NR	NR	NR	27
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250	1	16	63	NR	NR	NR	80
FUDS	1.000		0	0	0	3	NR	3
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	1	NR	1
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP	1	NR	NR	NR	NR	NR	1
US MINES	0.250		0	0	NR	NR	NR	0
MINES MRDS	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP	3	NR	NR	NR	NR	NR	3
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
ECHO	TP	2	NR	NR	NR	NR	NR	2
UXO	1.000		0	0	0	0	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		0	0	NR	NR	NR	0
PFAS ECHO FIRE TRAINING	0.250		0	0	NR	NR	NR	0
PFAS PART 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
BIOSOLIDS	TP		NR	NR	NR	NR	NR	0
NY PFAS	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	1	NR	NR	NR	1
NY E DESIGNATION	0.125	1	4	NR	NR	NR	NR	5
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		1	0	1	NR	NR	2
NY LEAD	TP		NR	NR	NR	NR	NR	0
NY MANIFEST	0.250		25	85	NR	NR	NR	110
PA MANIFEST	0.250		0	2	NR	NR	NR	2
NJ MANIFEST	0.250		7	16	NR	NR	NR	23
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY COOLING TOWERS	TP		NR	NR	NR	NR	NR	0
NY NYC OER	1.000		0	0	2	3	NR	5
NY NYC LAND USE	TP	1	NR	NR	NR	NR	NR	1
NY MGP	1.000		0	0	0	1	NR	1
NY ILI	0.500		0	0	0	NR	NR	0
UST FINDER RELEASE	0.500		2	2	5	NR	NR	9
UST FINDER	0.250	1	2	7	NR	NR	NR	10
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	1	NR	1
EDR Hist Auto	0.125	1	3	NR	NR	NR	NR	4
EDR Hist Cleaner	0.125		2	NR	NR	NR	NR	2
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		15	114	214	32	15	0	390

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
Target Property
B & L GAS STATION ENTERPRISES
4001 4TH AVENUE
BROOKLYN, NY 11232

FINDS **1016008562**
N/A

Site 1 of 36 in cluster A

Actual: 51 ft.

FINDS:
Registry ID: 110054924917

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Integrated Compliance Information System (ICIS) provides a database that, when complete, will contain integrated enforcement and compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained in ICIS by EPA in the Regional offices and it at Headquarters. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A2
Target Property
B & L GAS STATION ENTERPRISES, I NC.
4001 4TH AVENUE
BROOKLYN, NY 11232

NY AST **A100294289**
N/A

Site 2 of 36 in cluster A

Actual: 51 ft.

AST:

Name:	B & L GAS STATION ENTERPRISES, I NC.
Address:	4001 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-349399
Program Type:	PBS
UTM X:	583995.39504
UTM Y:	4500573.49218
Expiration Date:	09/09/2023
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	17199
Affiliation Type:	Facility Owner
Company Name:	4001 4TH LLC
Contact Type:	MEMBER
Contact Name:	JOSEPH MACCHIA
Address1:	556 CENTRAL AVENUE
Address2:	Not reported
City:	BETHPAGE
State:	NY
Zip Code:	11714

B & L GAS STATION ENTERPRISES, I NC. (Continued) **A100294289**

Country Code:	001
Phone:	(516) 933-0700
EMail:	JOSEPH@THEMACCHIAGROUP.NET
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-07-09

Site Id:	17199
Affiliation Type:	Mail Contact
Company Name:	4001 4TH LLC
Contact Type:	MEMBER
Contact Name:	JOSEPH MACCHIA
Address1:	556 CENTRAL AVENUE
Address2:	Not reported
City:	BETHPAGE
State:	NY
Zip Code:	11714
Country Code:	001
Phone:	(516) 933-0700
EMail:	JOSEPH@THEMACCHIAGROUP.NET
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-07-09

Site Id:	17199
Affiliation Type:	Facility Operator
Company Name:	B & L GAS STATION ENTERPRISES, I NC.
Contact Type:	Not reported
Contact Name:	JOSEPH MACCHIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 851-0006
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AYLAGATI
Date Last Modified:	2016-11-08

Site Id:	17199
Affiliation Type:	Emergency Contact
Company Name:	4001 4TH LLC
Contact Type:	Not reported
Contact Name:	JOSEPH MACCHIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 933-0700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-10-15

B & L GAS STATION ENTERPRISES, I NC. (Continued) **A100294289**

Tank Info:

Tank Number:	105
Tank Id:	66130
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
C01 - Pipe Location - Aboveground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/1989
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/06/2008
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

A3 **BP GAS STATION** **NY Spills** **S129127665**
Target **4001 4TH AVE** **N/A**
Property **BROOKLYN, NY**

Site 3 of 36 in cluster A

Actual: **51 ft.**

SPILLS:

Name:	BP GAS STATION
Address:	4001 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2206825 / 2022-11-16
Facility ID:	2206825
Facility Type:	ER
DER Facility ID:	591376
Site ID:	645074
DEC Region:	2
Spill Cause:	Traffic Accident
Spill Class:	C4
SWIS:	2401
Spill Date:	2022-11-09
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2022-11-09
CID:	Not reported
Water Affected:	Not reported

BP GAS STATION (Continued) **S129127665**

Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2022-11-09
Spill Record Last Update:	2022-11-16
Spiller Name:	Not reported
Spiller Company:	UNKNOWN MOTORIST
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MEARY KING
DEC Memo:	car ran over equipment while making delivery - cleanup in progress
Remarks:	DEC Piper spoke with caller. While making delivery, hose was run over by a motorist. The hose began leaking and the delivery was stopped. Approx 5 gal to asphalt cleaned by driver and attendant. spill cleaned. spill closed.

All Materials:

Site ID:	645074
Operable Unit ID:	1392069
Operable Unit:	01
Material ID:	2407375
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

A4 **AMOCO-FOURTH AVE** **FINDS** **1016210181**
Target **4001-4011 FOURTH AVENUE** **ECHO** **N/A**
Property **BROOKLYN, NY 11232**

Site 4 of 36 in cluster A

Actual:
51 ft.

FINDS:
Registry ID: 110005986790

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Air Facility System (AFS) contains compliance and permit data for

AMOCO-FOURTH AVE (Continued) **1016210181**

stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016210181
Registry ID:	110005986790
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110005986790
Name:	AMOCO-FOURTH AVE
Address:	4001-4011 FOURTH AVENUE
City,State,Zip:	BROOKLYN, NY 11232

A5 **AMOCO-FOURTH AVE** **US AIRS** **1004567261**
Target **4001-4011 4TH AVE** **N/A**
Property **BROOKLYN, NY 11232**

Site 5 of 36 in cluster A

Actual: **51 ft.**

US AIRS MINOR:

Envid:	1004567261
Region Code:	02
Programmatic ID:	AIR NY0000002610200069
Facility Registry ID:	110005986790
D and B Number:	Not reported
Primary SIC Code:	5541
NAICS Code:	999999
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000002610200069
Facility Registry ID:	110005986790
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1988-08-09 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

A6 **ALMANZAR INC** **EDR Hist Auto** **1020918557**
Target **4001 4TH AVE** **N/A**
Property **BROOKLYN, NY 11232**

Site 6 of 36 in cluster A

Actual: **51 ft.**

EDR Hist Auto

Year:	Name:	Type:
1971	STAGE AUTO SERVICE INC	Gasoline Service Stations

ALMANZAR INC (Continued) **1020918557**

1972	STAGE AUTO SERVICE INC	Gasoline Service Stations
1982	ALMANZAR INC	Gasoline Service Stations
1983	ALMANZAR INC	Gasoline Service Stations
1985	ALMANZAR INC	Gasoline Service Stations
1986	ALMANZAR INC	Gasoline Service Stations
1986	H & S SERVICE CENTER	Gasoline Service Stations
1987	H & S SERVICE CENTER	Gasoline Service Stations
1987	ALMANZAR INC	Gasoline Service Stations
1988	H & S SERVICE CENTER	Gasoline Service Stations
1988	ALMANZAR INC	Gasoline Service Stations
1989	ALMANZAR INC	Gasoline Service Stations
1989	H & S SERVICE STATION INC	Gasoline Service Stations
1990	ALMANZAR INC	Gasoline Service Stations
1991	ALMANZAR INC	Gasoline Service Stations
1992	L & V SVCE STA	Gasoline Service Stations
1992	H&S SVCE CTR	Gasoline Service Stations
1992	ALMANZAR INC	Gasoline Service Stations
1993	L & V SVCE STA	Gasoline Service Stations
1993	H&S SVCE CTR	Gasoline Service Stations
1993	ALMANZAR INC	Gasoline Service Stations
1994	L & V SVCE STA	Gasoline Service Stations
1994	H&S SVCE CTR	Gasoline Service Stations
1995	L & V SVCE STA	Gasoline Service Stations
1995	H&S SVCE CTR	Gasoline Service Stations
1996	H&S SVCE CTR	Gasoline Service Stations
2001	JOHNNYS AUTO REPAIR & BDY WORK	General Automotive Repair Shops
2001	4TH AVENUE AUTO REPAIR INC	General Automotive Repair Shops
2002	4TH AVENUE AUTO REPAIR INC	General Automotive Repair Shops
2002	JOHNNYS AUTO REPAIR & BDY WORK	General Automotive Repair Shops
2003	4TH AVENUE AUTO REPAIR INC	General Automotive Repair Shops
2003	JOHNNYS AUTO REPAIR & BDY WORK	General Automotive Repair Shops
2004	JOHNNYS AUTO REPAIR & BDY WORK	General Automotive Repair Shops
2004	4TH AVENUE AUTO REPAIR INC	General Automotive Repair Shops
2005	4TH AVENUE AUTO REPAIR INC	General Automotive Repair Shops
2005	JOHNNYS AUTO REPAIR & BDY WORK	General Automotive Repair Shops
2006	4TH AVENUE AUTO REPAIR INC	General Automotive Repair Shops
2006	JOHNNYS AUTO REPAIR & BDY WORK	General Automotive Repair Shops
2007	JOHNNYS AUTO REPAIR & BDY WORK	General Automotive Repair Shops
2007	4TH AVENUE AUTO REPAIR INC	General Automotive Repair Shops
2008	DAX AUTO INC	General Automotive Repair Shops
2008	JOHNNYS AUTO REPAIR & BDY WORK	General Automotive Repair Shops
2008	4TH AVENUE AUTO REPAIR INC	General Automotive Repair Shops
2008	B & L GAS STATION ENTERPRISES	Gasoline Service Stations
2008	H & S SERVICE STATION INC	Gasoline Service Stations, NEC
2009	B & L GAS STATION ENTERPRISES	Gasoline Service Stations
2010	H & S SERVICE STATION INC	Gasoline Service Stations, NEC
2010	B & L GAS STATION ENTERPRISES	Gasoline Service Stations
2011	B & L GAS STATION ENTERPRISES	Gasoline Service Stations
2011	H & S SERVICE STATION INC	Gasoline Service Stations, NEC
2012	B & L GAS STATION ENTERPRISES	Gasoline Service Stations
2012	H & S SERVICE STATION INC	Gasoline Service Stations, NEC
2013	H & S SERVICE STATION INC	Gasoline Service Stations, NEC
2013	B & L GAS STATION ENTERPRISES	Gasoline Service Stations
2014	H & S SERVICE STATION INC	Gasoline Service Stations, NEC
2014	B & L GAS STATION ENTERPRISES	Gasoline Service Stations

A7 **B & L GAS STATION ENTERPRISES, I NC.** **UST FINDER** **1028569570**
Target **4001 4TH AVENUE** **N/A**
Property **BROOKLYN, NY 11232**

Site 7 of 36 in cluster A

Actual:
51 ft.

UST FINDER:

Object ID:	294939
Facility ID:	NY17199
Name:	B & L GAS STATION ENTERPRISES, I NC.
Address:	4001 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Address Match Type:	Not reported
Open USTs:	4
Closed USTs:	0
TOS USTs:	0
Population 1500ft:	10796
Private Wells 1500ft:	7
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-74.006481
Y Coord:	40.6517490000001
Latitude:	40.651749
Longitude:	-74.006481

UST FINDER:

Object ID:	1208797
Facility ID:	NY17199
Tank ID:	NY18488
Tank Status:	Open
Installation Date:	1985/04/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1208798
Facility ID:	NY17199
Tank ID:	NY18489
Tank Status:	Open
Installation Date:	1985/04/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

B & L GAS STATION ENTERPRISES, I NC. (Continued) **1028569570**

Object ID:	1208799
Facility ID:	NY17199
Tank ID:	NY19296
Tank Status:	Open
Installation Date:	1989/04/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1208800
Facility ID:	NY17199
Tank ID:	NY19334
Tank Status:	Open
Installation Date:	1989/04/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

A8 **COMMERICAL** **NY Spills** **S123660794**
Target **4001-4011 4TH AVE** **N/A**
Property **BROOKLYN, NY**

Site 8 of 36 in cluster A

Actual:
51 ft.

SPILLS:

Name:	COMMERICAL
Address:	4001-4011 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1811146 / Not Reported
Facility ID:	1811146
Facility Type:	ER
DER Facility ID:	534572
Site ID:	582069
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2019-02-05
Investigator:	JAKOLLEE
Referred To:	MONTHLY GAUGING & BAILING OF PRODUCT
Reported to Dept:	2019-02-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2019-02-05
Spill Record Last Update:	2024-01-02
Spiller Name:	JUSTIN HALPIN
Spiller Company:	GAS STATION BP

COMMERICAL (Continued) **S123660794**

Spiller Address: 4001-4011 4TH AVE
Spiller Company: 999
Contact Name: 4001 4TH AVE LLC
DEC Memo: shallow in pack to soil clean up pending insurance
Remarks: DEC Piper spoke with Justin at WRS. While performing borings for a phase II, contaminated soil was observed between 5 and 25 feet below grade. A full Phase II report will be sent to DEC Zhune upon completion. Site is currently an active gas station. PBS 2-349399 1/25/19 Castleton Environmental prepared the phase II Environmental Site Assessment dated January 25, 2019. Catleston has prepared the following Phase II report to document the work performed at 4001-4011 4th Avenue, Brooklyn, New York. The investigation was performed based upon review of the phase I ESA by MECC dated January 7, 2019. The objectives of this work were to determine if the sites historic and current usages as a gasoline station has impacted the subsurface. The objectives was met through the performance of a geophysical survey and the collection and laboratory analysis of soil samples. The geophysical survey identified the presence of the 4 in-use USTs, nine suspect USTs that are currently not in use, and one metal anomaly that is not indicative of a UST. Six soil borings were advanced, and six soil samples collected for laboratory analysis. Analytical results reported concentrations of VOCs above applicable standards in five of the six soil samples analyzed. Castleton recommends the following: . Notification of these findings be made to NYSDEC . The suspected USTs be assessed and, if are present, properly removed as per NYSDEC protocols . Petroleum impacts to soil be delineated and remediated under the NYSDEC Spills Program 2/20/19-Justin, The DEC require the work plan from this site. 2/2/19-Thank you Veronica, as soon as we confirm if there any old USTs, we will prepare a Work Plan for further investigation and possible UST removal and soil disposal. 2/21/19-Please send the revise report with the following: 1. Correct boring logs. Log #2 and # 3 are duplicate. 2. Scale site plan including piping, active tanks, dispensers, remote fill port if any 3. Complete delineation of soil contamination and investigation for groundwater with site specific groundwater flow direction. 4/3/19-I received the corrected boring log from Castleton Environmental. As I mentioned we did not do the Phase II Report or the Phase I. Im working on getting scaled site plan, and as soon as we know the status of the suspected former USTs , I will be drafting a Work Plan. I asked Castleton why they did not go deeper on borings B-4, B-5 and 6 and they mentioned they hit refusal at 30 , 20 and 24.5 at 4, 5 and 6. If that s the case we will not reach groundwater at 60 feet. 2/24/20-Would you be able to issue a letter with the requirements of the work Plan? We are having a little trouble with the current tenant getting access to the site and I think a letter from DEC would help us explain to them that we need access to the site. 2/25/20-A CSL letter was sent to: LiIla LOmanov B&L Gas Station Enterprises Inc. 4001 4th AV Brooklyn NY 11232 3/23/20- Veronica may I request a 2 week extension on the RIWP due March 25th, given all that s going on with the COVID-19 crisis I need a little extra time. 3/23/20Justin, You can take the two week extension. 4/7/20-Hi Veronica, I hope you are safe and well. Just an update: Im currently working on the Remedial Investigation Work Plan for delineation of soil and excavation of former USTs (if present). I ll have the Work Plan to you by close of business on Friday April 10th. Is this ok? 4/8/20-Veronica I hope you are well. Are you available to breifly speak? Also wondering if you are ok with my request to submit work

COMMERICAL (Continued) **S123660794**

plan Friday?. Thank you Justin 631 774 6682 4/9/20-Veronica thank you for speaking with me before. Please see the attached RIWP for spill 18-11146- 4th Ave Brooklyn site. 4/9/20 Justin Halpin emailed the Remedial Investigation Work Plan dated April 9,20. The Remedial Investigation Work Plan includes: confirmation of the presence of suspect USTs identified during Phase II; supplemental vertical delineation of soil contamination; attempt to collect and analyze groundwater samples; provisions to remove the suspect USTs; excavation of contaminated soils if excavation of historic USTs is warranted; and reasonable altenatives to an in-situ approach for remediating contaminated soils. 4/17/20-The Remedial Investigation work plan was approves. An approval letter was sent to Joseph Machia dated April 17, 20. Justin Halpin emailed The supplemental Remedial Investigation Report dated April 17, 20. In Conclusion, the supplemental sampling data will be used to develop a Remedail ActionPlan (RAP) in Oreder to address soil contamination. No groundwater was encountered during any of the investigation conducted and is expected to be approximately 50 feet or more below grade surface. The supplemental sampling results indicated that vertical delineation was achieved at the B-5 and B-8 locations. At the B-4 location delineation was not feasible due to bedrock refusal at a depth of thirty feet (30'). The majority of contamination at this boring was detected in the fifteen (15') feet to twenty five (25') horizon with PID reading as high as 4,500ppm. Beyond this depth from 25'-30'PID readings drastically waned to levels in the 500 ppm range. Based upon the successful vertical delineation at two (2) locations B-5 and B-8 and the inability to advance beyond the refusals encountered at the surface of the bedrock at the B-6 location, a Remedial Action Plan (RAP)to to address contaminated soils will be issue to the Department. 8/31/20 - Obligado - As per Randall Austin, this long-term remediation Spill case is transferred to Jon Kolleeny. 03/30/21: I sent email to Justin Halpin of Berninger Envt'l: Justin, Going thru my open spills, I came across this case, which was assigned to me in August 2020. Comments in spills database indicate you were communicating with previous DEC case manager, Veronica Zhune, and that a RAP to address contaminated soil was to be prepared. Can you update me on this site? Is Berninger Envt'l still involved as consultant? Has a RAP been prepared? Is Joseph Macchia spill Responsible Party? Please let me know, and if any rpts have been submitted to DEC since last August, please forward them again to my attention. Received reply from Justin: Let me look into this with owner. I believe it is still owned by Macchia group. We did do an investigation and proposed a remedial plan and that s when I was informed case was being transferred. I'll get back to you ASAP. - JK 04/01/21: Found Remedial Action Plan by Berninger Envt'l, Inc. dated August 2020 in DecDocs. RAP proposes install'n of an SVE system to address contaminated soil at site. Proposed system would include four vapor extraction wells installed to a depth of 30 ft, with 5 ft of riser and 25 ft of screen. Below-grade piping will connect SVE wells to an equipment shed with a blower and moisture separator (water knock-out drum). A fresh-air inlet will be installed on main influent piping leg prior to blower to reduce exhaust stack emissions by dilution. Air emission control equipment (carbon drum) will be installed if necessary, based on results of first air discharge sampling event, to reduce or eliminate VOCs in system exhaust prior to exiting stack. Height of exhaust stack will be 15 ft, with 5 ft projecting above equipment shed. RAP states that during 1st month of

COMMERICAL (Continued) **S123660794**

operation, weekly O&M inspections will be conducted, with vapor influent screening and lab sampling to establish a baseline for future calculation of contaminant mass removal. Vapor effluent sampling will be performed quarterly with a summa canister. Quarterly rpts will be submitted to DEC documenting O&M activities and vapor effluent sampling results. RAP states that BEI will be prepared to mobilize within 60 days of RAP approval, and system install'n fieldwork is anticipated to take 7-10 days. A Construction Completion Rpt will be submitted to document layout of constructed system, with as-built drawings, baseline effluent levels, etc., plus discussion of post-mitigation testing results and protocol for system termination procedures. - J. Kolleeny 04/02/21: I sent email to Justin Halpin of BEI: Justin, I checked documents in our database related to this spill and found that Berninger Envt'l submitted a RAP in August 2020. However, RAP was not formally reviewed or approved. I looked over plan, which proposes install'n of an SVE system with 4 extraction wells to address soil contamination at site. Plan looks good, but I would like to request some revisions & additions to RAP. First, please complete attached SVE Data Sheets and add them to RAP. You should use existing soil data with highest benzene result to calculate benzene influent vapor concentration. One of Phase II soil samples had 20 mg/kg (PPM) of benzene, which is pretty high, so I believe system should incorporate vapor treatment. If you don t agree that vapor treatment is necessary, you can go with current system design without vapor-phase carbon treatment units, but I ll require that a system off-gas sample be collected shortly after system startup and submitted for lab analysis. System should be shut off while awaiting lab results to see if they confirm that benzene doesn t exceed DEC discharge standard. Even if system s air discharge meets benzene limit, system may need vapor treatment if there are any nuisance odor complaints from local residents. Also, I ve attached an example of an OM&M Table listing basic monitoring & maintenance requirements for an SVE system. Please modify this table as necessary to be site specific and include it in revised RAP. RAP does not discuss how SVE radius of influence (shown around extraction wells on Fig. 2) was determined; revised RAP should specify vapor extraction ROI and discuss how it was determined. Also, RAP should include a short section on physical setting of site, with geological & hydrogeological information. In other words, it should state elevation of site above sea level, and should include estimates of depth to bedrock and depth to GW at site based on documents by USGS, NYCDEP, and/or other sources. I know that both Phase II rpt by previous consultant and rpts by BEI state that borings met refusal on bedrock at about 30 ft below grade, but I am skeptical that it was truly bedrock, as it s my understanding that this area of Brooklyn is composed of glacial moraine deposits which may include large boulders that could give impression of hitting bedrock. If it turns out that your sources indicate bedrock at site is much deeper than 30 ft, so refusals were not on actual bedrock but on boulders in glacial till, then I may require an attempt to install a well at site to evaluate whether GW has been impacted by fuel release(s). Finally, Responsible Party (Joseph Macchia) will need to sign a Stipulation Agreement for this spill in order to run SVE system. Stipulation Agreement will authorize system s vapor discharges without having to obtain a permit from our Air Division. I am putting together Stipulation Agreement now and will be sending it to Mr. Macchia soon. Please let me know if you have any questions about any of this, and feel free to call to

COMMERICAL (Continued) **S123660794**

discuss. - JK 04/02/21: I sent Stipulation Agreement with Corrective Action Plan (CAP) to Mr. Joseph Macchia of The Macchia Group, plus cover letter (cc'ing DEC atty James Simpson). Due date for return of signed Stip is 4/30/21. CAP indicates that a revised RAP addressing comments in my 4/2/21 email to BEI must be submitted to DEC within 30 days of execution of Stip. - J. Kolleeny 05/06/21: In discussions with Justin Halpin of Berninger Envt'l, we agreed to temporarily put RAP on hold and suspend deadline for return of signed Stip by RP Joseph Macchia and to conduct a GW investigation to evaluate potential impacts to GW, which could affect remedial plan. - J. Kolleeny 05/17/21: Reviewed GW Investigation & Soil Profiling plan by Berninger Envt'l Inc., dated 5/17/21. Plan proposes to investigate whether soil contamination at site has impacted GW by installing a permanent 2-inch well at location of hottest soil sample during earlier site investigation by BEI (Boring B-4). Plan proposes to use air rotary drilling to penetrate later of rock(s) at which earlier borings met refusal. To characterize soil conditions below 30 ft bgs, soil profiling will be conducted from ~30 ft bgs down to GW interface, expected to be at ~50 ft bgs. Soil samples will be collected using dual-tube sampling method, screening soil at 2.5 ft intervals with a PID, and sending samples with highest PID readings and from just above water table to lab for analysis. Lab results will be compared to DEC Part 375 Unrestricted Use SCOs. I sent approval letter to RP Joseph Macchia, cc's to Justin Halpin & Alicia Patti of BEI. - J. Kolleeny 10/27/21: Reviewed Supplemental Investigation Soil & GW Rpt aka GW Investigation Soil Profiling Rpt by Berninger Envt'l dated 10/8/21. Rpt summarizes drilling of a boring and install'n of a well at location of former boring B-4, where highest levels of soil contamination were found in a previous site investigation. Using an air rotary drill rig, BEI was able to penetrate thru rocky stratum at ~30 ft bgs. Boring was drilled to depth of 65 ft; soil screening starting at 30 ft showed highest PID reading of 1,000 ppm in interval from 30-32.5 ft, PID readings decreased steadily from 32.5 to 50 ft, and no PID hits were detected from 50-65 ft. A soil sample was collect from 45-50 ft interval, with PID reading of 9 ppm; analytical results showed almost no detections of VOCs, and no compounds exceeding Part 375 cleanup objectives. A 2-inch well was set at 50 ft, with screen extending from 50 ft up to 25 ft (according to boring log; text says screen is 20 ft long, extending from 50 ft to 30 ft bgs). Rpt states that soil was only saturated from 35 to 40 ft bgs, with dry soil below 40 ft, indicating a perched groundwater condition. GW sample from well had highly elevated levels of BTEX compounds (~40 mg/L total BTEX). Rpt's Conclusion states that highly elevated levels of soil contamination extend to a depth of ~35 ft, with contamination ending at 50 ft bgs so soil impacts have been vertically delineated; soil was dry from 40' to 65', with a 10 ft zone of perched water from 30 to 40 ft (contradicts earlier statement in text). Rpt states that there are plans to redevelop property, at which time any suspect tanks and contaminated soil can be easily excavated. - J. Kolleeny 10/27/21: I sent email to Justin Halpin of Berninger Envt'l: Justin, I ve looked at October 2021 Soil and GW Rpt for this spill site, and have some thoughts and questions. First, fact that you found very contaminated perched GW (~40 ppm total BTEX!) concerns me because there is a nearby sensitive receptor subway lines that run along 4th Ave (D, N & R Trains). We have a number of spill sites where free product and/or contaminated GW migrated into subway stations, causing odor problems and other

COMMERICAL (Continued) **S123660794**

headaches. Can you try to find out depth of subway lines where they pass in front of this site, and maybe put together a cross-section diagram of subsurface showing subway tunnel in relation to soil stratigraphy and perched GW zone? Along these lines, I will probably be requesting install'n of another well to delineate perched water zone and see if it extends towards 4th Avenue and subway lines. Former borings B-8 & B-5 are potential locations for addt'l wells. I m also concerned about potential presence of free product on perched water, and I think it s possible that well already installed was constructed in so that it could ve missed floating product. Rpt describes saturated zone as extending from 30 to 40 ft bgs. Well was installed to a depth of 50 ft, and screened section extends from 50 ft up to 30 ft, i.e., just about to top of saturated zone. If I request one or more addt'l wells to delineate extent of perched water, they should probably be installed to 40-ft depth, with 15 ft of screen (i.e., from 40 to 25 ft bgs). Have you gone back to site and checked existing well (I m assuming it s still there?) for free product? Is it possible to determine if screen is submerged or if there is daylight above water level in well? I'm also considering whether to require another attempt to reach regional aquifer, to see if GW there has been impacted. Regarding request to put RAP on hold: fact that there are plans (tentative?) to decommission gas station in late 2024 means that if an SVE system is installed in next couple of months, it could operate for almost 3 years, which in my experience is enough time to recover most volatile contaminants. And decommissioning could easily be delayed. Even if it does occur in 2024, RAP hold request letter says that station will likely be excavated to a depth of ~15 ft, while contaminated soil extends to depths of ~35 ft at site, so a lot of contamination would be left behind by excavation. If soil remediation is required, it would be a good idea to conduct an SVE pilot test by installing a vapor extraction test well down to end of unsaturated zone (~30 ft bgs), with 20 ft of screen, and attaching a blower to extract soil vapors and collect a vapor sample(s) for PID screening and lab analysis. I will continue to think about rpt and these issues, but I d like to get your feedback before I issue a formal response to your client. Please feel free to call to discuss. - J. Kolleeny 11/02/21: Received email reply from Justin Halpin of BEI: Jon, Yes we can see what s going on out there and get depths on subways. We may be able to screen ambient air with a PID in subway to see if there are any significant volatile levels from spill, but I think subway stations are at 45th St & 36th St, quite a ways from our site and not in down-gradient of anticipated GW flow. We can investigate this when we gauge new MW-1 well. We will check well (still intact and secured with a manhole cover), but I believe we had a DTW at ~30 . I also made a typo in Rpt on screened interval stating 20 of screen when it's actually 25 . Well log depicts this interval so I will revise text to match log, Figures 3a & b. So we definitely have about 5 ft of daylight above water table. We will also gauge well for floating product. When we initially purged and sampled there was a sheen but no free phase product. As far as regional aquifer, we actually hit dry soil from 40-65 , and delineated to 0.0 on PID at 50 all way to 65 , so I would believe based on this that regional aquifer has not been impacted. Regarding RAP, we can excavate deeper if we had to, probably to 20-25 . We can also do a pilot test to see what kind of VOC concentrations we extract. I wouldn t be surprised if soil from 25 -45 was within unrestricted SCOs as a majority of contamination

COMMERICAL (Continued) **S123660794**

looked like it was from 15-25 , after that PID readings significantly dropped. I will send a revised Rpt for record with revision of screened interval in text to match well log. - J. Kolleeny 11/04/21: I sent reply to Justin Halpin of BEI: Justin, I don t think there s a need to screen subway stations with a PID at this time, since we have not received any rpts of petroleum odors. I realize site is midway between two subway stations which are a few blocks away, but there s still a possibility that if perched water body extends far enough, contaminated GW could eventually impact subway tunnel and from there impact one or both stations, so I think it s worth installing another well in perched water body, down-gradient of first well, to see if perched water extends in that direction. Once addt'l well has been installed, both wells should be gauged and sampled (assuming you find sufficient water for sampling in newer well). I did notice that boring log for first well indicates that screen extends from a depth of 50 ft up to 25 ft, so if that s accurate and text is incorrect, then I agree there should be sufficient screen to extend above water level and allow any free product, if present, to enter well. Regarding need for a well drilled to regional aquifer, it s good that you had clean soil from 50 ft to 65 ft in that boring; however, petroleum and/or contaminated precipitation water may follow tortuous pathways as they travel downward thru soil, so I wouldn t say a single boring ending with 15 ft of clean soil conclusively proves that contamination has not traveled down to regional aquifer. I need to think about this a little more though. Can you let me know elevation of site above sea level? Finally, I appreciate that soil excavation during decommissioning of gas station and removal of all tanks & piping could be extended to 20-25 ft, but I discussed request to postpone remediation until station is decommissioned with my supervisor, and he was not receptive to idea of waiting 3 years (at a minimum, with potential delays) to remediate spill. And in fact, NYS envt'l regs require that petroleum releases be contained immediately, and that a cleanup should be performed to rapidly remove discharge. So I d still like you to install a dedicated SVE well screened entirely in unsaturated soil zone and perform an SVE pilot test to see if hydrocarbon vapors can be recovered and determine an ROI. In my experience, three years is enough time to design and install an SVE system and operate system to remove a major amount of recoverable volatile gasoline-related compounds from soil. But let s first see if SVE would be effective at this site. I will prepare a letter to your client requesting a work plan for install'n of a well to delineate perched water zone, install'n of an SVE test well, and performance of an SVE pilot test. Please let me know about site s elevation above sea level. - J. Kolleeny 11/04/21: Received email reply from Justin Halpin of BEI: Ok thank you Jon. Ground elevation above sea level is 55 where we conducted boring. I'm thinking we are in actual aquifer given this elevation, it was just perplexing how it went dry. It is possible there is just slow recharge at 50' + and we just didn t notice that it was only slightly saturated. Either way we can install an SVE pilot well and run a pilot test. I'll work on prepping an SVE Pilot Test Work Plan in order to determine VOC recovery and ROI. I sent reply: Justin, That s interesting that you say you may already have reached regional aquifer. If site is 55 ft above sea level and depth to water is about 30 ft, that would mean water table is at 25 ft above sea level, which seems a little high considering site is fairly close to bay. On other hand, if you haven t hit regional aquifer by 65 ft below grade, that would suggest regional water table

COMMERICAL (Continued) **S123660794**

is located far below sea level, which also doesn t seem right! But of course it s very odd that you only had saturated soil from 30 to 40 ft, and that soil from 40 to 65 ft seemed completely dry! If well is in fact installed into regional aquifer, it would mean regional GW (not just a perched water body) is very contaminated, in which case you'll have to devise a remedial plan to address both soil & GW contamination even if there is no threat to subway tunnel. Maybe you should develop a work plan for a pilot test of AS/SVE instead of just SVE? Or come up with other ideas to treat both soil & GW? In light of this, I will have to ask for more than one delineation well at site. 11/05/21: I sent letter to RP Joseph Macchia, cc's to Justin Halpin & Alicia Patti of BEI, responding to BEI's 10/8/21 Supplt'l Investigation Soil & GW Rpt, aka GW Investig Soil Profiling Rpt. Letter stated that GW at site, whether a perched GW zone or regional aquifer, constitutes waters of NY State, protected by envt'l regs and subject to spill cleanup requirements. Letter also noted that site is very close to 4th Ave subway line, a potential sensitive receptor, and that contaminated GW identified at site could pose a threat to subway line. Then stated that site redevelopment, which BEI rpt suggested as way to address contamination, is not scheduled until at least late 2024, and that delaying remediation until then is unacceptable. Letter said GW impacts at site must be delineated and characterized, and remedial strategies to address both soil & GW contamination must be evaluated. Therefore, DEC requires that at least two addt'l monitoring wells be installed at site to delineate GW contamination, esp in direction of subway line, and to accurately determine local GW flow direction. In addition, pilot testing of one or more remedial technologies appropriate to address site conditions should be conducted. Letter required that a work plan proposing install'n of addt'l monitoring wells and performance of remedial pilot testing at site be prepared & submitted by 12/3/21. Finally, letter noted that care should be taken to ensure proposed well borings are not located too close to 4th Avenue subway tunnel. - J. Kolleeny On 12/21/21: Reviewed Supplemental Remedial Investigation and Pilot Study Work Plan by BEI dated Dec. 2021, submitted by email on 12/3/21. Work plan proposes collection of GW samples via install'n of two new monitoring wells, down-gradient (i.e., NW) of existing well MW-1 in direction of 4th Ave. subway lines. Work plan states that depth of subway tunnel will be investigated to evaluate potential impacts to this sensitive receptor. Wells will be 1 internal diameter, with 10 ft of screen (25-35 ft bgs) and 25 ft of PVC riser. Work plan also proposes performing an SVE pilot test by installing a 2-inch diameter SVE well screened in vadose zone (10 ft of screen from 15' to 25', and 15 ft of riser). BEI anticipates SVE ROI to be 5-10 ft; new and existing monitoring wells will be used to measure vacuum influence. A rpt of findings will be issued after lab results for GW samples and SVE pilot test are received and evaluated. - J. Kolleeny 12/22/21: On 12/21/21, I sent email to Justin Halpin of BEI: Justin, I m reviewing Supplemental Remedial Investigation Pilot Study Work Plan, and have questions. Plan proposes two addt'l monitoring wells (MW-2 & MW-3) to delineate GW impacts found in first well, but text says new wells will be 1-inch internal diameter. To add further confusion, top section of Fig. 3, Proposed Monitoring Well Log, indicates that casing & screen for each new well will be 2-inch diameter, but Well Design Drawing further down page has arrows pointing at well drawing with labels, (25) of 1 PVC riser and (10) of 1 PVC 0.02 slot screen. I believe first well installed, MW-1, is a

COMMERICAL (Continued) **S123660794**

2-inch diameter well; why is BEI now proposing to install 1-inch wells? I understand site has difficult drilling conditions, but I think it makes more sense to put in 2-inch wells which, altho not as useful as 4-inch wells for remediation, have some ability to be used for remediation if significant petroleum impacts (e.g., free product) are found at proposed locations. I m also not sure I agree with proposed location of one of new wells, way to the NE closer to 40th Street. Can that well be installed in front of dispenser islands, closer to earlier soil borings done at site? Finally, it s not entirely clear if BEI is proposing to sample soil during install'n of new wells. In Section 4.0 Scope of Work, on page 2, second paragraph states, All soil & GW samples will be placed in laboratory approved glassware , but that s only mention of soil sampling. Will soil samples be collected & screened during well install'n? Unless new wells will be drilled at locations of earlier soil borings, soil sampling should be performed to further delineate lateral extent of soil impacts. Please let me know your thoughts, and feel free to call to discuss. On 12/22/21, Justin replied, Ok thank you, I will revise Work Plan based on comments. - J. Kolleeny 04/01/22: Reviewed Supplemental Remedial Investigation Work Plan by BEI, dated 3/28/22. Work plan proposes install'n of two addt;l monitoring wells (MW-2 & MW-3) at site down-gradient of existing well MW-1, to delineate and further characterize GW contamination identified in that well. New wells will be installed at approx locations of former soil borings B-5 & B-8. Rpt notes that soil screening & sampling were performed while advancing those borings (w/preparation of boring logs), so soil at these borings has been characterized and significant VOC levels were found at these locations. Therefore, no addt'l soil sampling is proposed for this investigation. New wells will be constructed of 2-inch internal diameter PVC casing & screen. Work plan states that based on results of GW samples from new wells, BEI will develop a pilot study work plan to evaluate remedial strategies to address subsurface petroleum impacts at site, including SVE, AS, and ISCO. BEI will also investigate location of nearby MTA subway lines in relation to site and wells and will issue a Rpt of Findings with results of this investigation. I sent letter to Joseph Macchia (RP), cc's to Justin Halpin & Alicia Patti of BEI, approving work plan but stating: (1) once new wells have been installed, new wells plus existing well MW-1 should be sampled to provide up-to-date data; and (2) fieldwork should be scheduled asap, and by no later than 4/29/22. - J. Kolleeny 12/19/22: Reviewed Supplemental Remedial Investigation Rpt and Pilot Study Work Plan by Berninger Envt'l, Inc. (BEI), dated Nov. 2022. Rpt states that altho two addt'l monitoring wells were proposed to delineate GW impacts, only one boring (B-9) was drilled, to a depth of ~50 ft, and no GW was encountered. Boring log shows PID detections beginning in 2.5 to 5 ft interval, with strong odor and 5 ppm on PID; readings increased to 190 ppm in 12.5-15 ft interval, then increased to 1,500 ppm in 15-17.5 ft interval and to highest reading of 1,800 ppm in 17.5 to 20 ft interval. PID readings gradually decreased to 50 ppm in 40-42.5 ft interval, then were ND from 42.5 to 50 ft. From 45 to 50 ft, log indicates soil was tight brown clay with mild odor and was moist/wet. Log also shows tight soils from 35 to 40 ft (brown silt/clay mix). Text notes that soil tightened up at ~35 ft bgs, and states that a 1-inch temporary well was set in boring, but no GW entered well after 2 hours. Text states that mainly clay was encountered at 45 ft, where moisture and minimal water were observed. Boring was discontinued at 50 ft due to

COMMERICAL (Continued) **S123660794**

difficulty advancing tool and risk of puncturing confining clay unit. Pilot test plan portion of rpt proposes install'n of one SVE test well, a short distance from existing GW well MW-1, which will be used to measure induced vacuum during pilot test to help calculate ROI (expected to be 5 to 10 ft). Recovered soil vapors will be screened with a PID during pilot test, and a sample of vapor will be collected with a summa canister for lab analysis (TO-15). Test well will be 2-inch diameter, installed to depth of 25 ft, with 10 ft of screen (15-25 ft bgs) and 15 ft of riser (0-15 ft bgs). Results will be presented in a Pilot Test Rpt. - J. Kolleeny 12/19/22: I sent email to Justin Halpin of BEI: Justin, I m reviewing Supplemental Remedial Investigation Rpt and Pilot Study Work Plan for this site, prepared by BEI and dated November 2022. Rpt mentions that only one of two proposed borings/wells were installed (well was dry), and rpt doesn t mention anything about status of earlier site well MW-1. My supplemental remedial investigation work plan approval letter dated 4/1/22 required that two new wells and one existing well be sampled as part of this investigation. I know you couldn t sample new well because it was dry, but has existing well been re-sampled, or gauged for presence of free product? Also, please let me know why second proposed boring/well wasn t drilled? Rpt indicates that a temporary 1-inch well was installed in new well borehole; according to my approval letter, investigation work plan proposed install'n of two 2-inch diameter permanent PVC wells. Why was work plan deviated from? I m assuming BEI was aware of difficult drilling conditions at this site, so a suitably heavy-duty drill rig should have been used. Please let me know. - J. Kolleeny 12/20/22: Justin Halpin of BEI sent email reply: Original well MW-1 still has product in well but when pumping it out we recovered about a gal and it takes 1 hour to re-charge. Second well we profiled and took PID readings then when installing well had a lot of trouble pushing 3.25 rods for 2 well, so we switched over to narrower rods for 1 well. We advanced well past product/water level at MW-1, and it was dry. I really believe that there is a confining aquifer somewhere at 50-65 and its basically clay at this depth. Also, I just got news that site is going to go under construction and gas station will no longer be in service (proposed plans to build a charter school). I think we should discuss this proposal and also remedial actions moving forward. I can talk tomorrow or Thursday if you're available. - J. Kolleeny 12/21/22: Spoke with Justin Halpin of BEI. He stated that it looks like gas station will be abandoned and site may be redeveloped with a charter school. I asked when this will take place, and Justin said possibly in 2024. I said that since this is not definite, we should proceed with further investigation and remediation of impacts at site, especially since impacts extend to significant depth that would not be addressed during site redevelopment. I mentioned that if a school is built on site, it must have not only a vapor barrier but also a SSDS. I asked about free product in well MW-1, stating that I have nothing in writing (emails, rpts) mentioning LNAPL in this well. Justin stated that LNAPL thickness is about 6 inches and when well is pumped it goes dry right away and takes at least an hour to recharge. I said that LNAPL should be addressed on a regular, at least monthly basis, and details provided in writing. I also stated that in light of presence of LNAPL, it is still necessary to install two wells to delineate GW impacts, and BEI must return to site with a heavier rig (sonic rig?) to reach greater depth. He noted that after reaching 60 ft with well MW-1, water came into well and rose to ~30 ft bgs,

COMMERICAL (Continued) **S123660794**

suggesting aquifer is confined by a clay layer and under pressure. I also said that SVE pilot test well should be drilled deeper than 25 ft, since soil impacts extend much deeper. Justin agreed to revise Supplemental Remedial Investigation Rpt and Pilot Test Work Plan to propose two new, deeper wells and make changes to SVE pilot test, and to include data on LNAPL and proposed interim remedial measures for well MW-1. - J. Kolleeny 03/16/23: Received email from Alicia Patti of Berninger Envt'l, with attached rpt. Email states: Jon, Justin finished this rpt today, please see attached. Also, would you like us to visit site monthly or quarterly? I looked quickly at rpt, Monitoring Rpt, February 2023. Rpt states Objective as Monitor site well for depth to GW and presence of free phase product on a monthly basis. Bail product as necessary. Under Recovery System, rpt states Bailing of product, approx 1.5 gals until well is dry. Recharge rate approx. 1.0 - 1.5 gals every half hour. Under Comments, rpt states that floating product was detected this monitoring period, site monitored and product bailed on 2/20/23, next monitoring and bailing of product scheduled for May 2023 (i.e., 3 months from Feb. 2023 event). Well gauging data table in rpt indicates that on 2/20/23, well MW-1 (only existing site well) had no water, but had 12.66 ft of product; 6.44 gals were bailed. I sent email response to Ms. Patti, cc to Justin Halpin of BEI: Alicia, am I reading table in rpt correctly, was Product Thickness in well on February 20th 12.66 feet?! If that is case, and product recharges into well at a rate of 1 to 1.5 gals every half hour as stated in rpt, then BEI should be visiting site to perform product recovery on a monthly basis at a minimum! Twice a month would be better, or even weekly until product thicknesses and recharge rate decrease significantly. Thanks for asking! I ll review rpt in more detail soon and will get back to you and Justin if I have any questions or addt'l comments. I later sent follow-up email: I noticed that rpt states project objective is to monitor site well on a monthly basis for depth to water and presence of free product (and bail well as necessary), but also states that next monitoring and bailing event (after February 2023 event) is scheduled for May 2023; this is an inconsistency. As mentioned before, monitoring & product recovery should be performed monthly at a minimum, with weekly or twice/month preferred. - J. Kolleeny 04/06/23: I sent email to Alicia Patti and Justin Halpin of Berninger Envt'l: Justin and Alicia, I wanted to follow up on this site, regarding free product monitoring & recovery events. Has site been visited since February 20, 2023 monitoring event? If so, can you let me know how often you are visiting site, product thickness measured during any visits, and amount of product bailed from on-site well? (Have you tried VEFR for product recovery, to increase recovery amounts?) If BEI has not been back to site since February, a site visit must be scheduled immediately for month of April 2023, and product monitoring & recovery events must continue on a monthly basis at a minimum. Please let me know status of product monitoring and recovery at this site. Received reply from Justin Halpin: We did another visit in March and just went yesterday to bail as much as possible, given slow recharge rate. VEFR would be difficult here and costly to mobilize, but once we get other viable wells in ground maybe at that time we can attempt VEFR. We will document all visits and data (DTP, DTW if present, product thickness, amount recovered) in next quarterly Rpt (unless you want monthly Rpts?) Also working with MTA to try and get subway permit for delineation borings it's going to take some time, it's quite a process but we definitely can't

COMMERICAL (Continued) **S123660794**

drill without it, being that we are within 200 ft of subway line. Will keep you posted. I sent reply: Justin, thanks for getting back to me about this site. I think quarterly rpts will be adequate, as long as you re doing monitoring & recovery events on at least a monthly basis. If recharge is slow, you can certainly hold off on VEFR for product recovery, for now. I was under impression recharge rate was pretty high, with 1 to 1.5 gals every 1/2 hour. Question: February 2023 rpt indicates that there was no GW in well, only product, so when you re talking about recharge, is it GW coming into well, or only pure free product? If it s all product, how many inches in well does that 1 to 1.5 gals per half-hour translate to? I understand that it s slow to get MTA permit to drill addt'l borings, and that you cannot drill without it. Can you let me know product thickness and recovery amounts for March visit and yesterday s visit? Thanks. - J. Kolleeny 04/12/23: Received email response from Justin Halpin of BEI: Jon, we recovered 5 gals on March 23rd with a product thickness (PT) of 6 inches (DTW =37.52 , DTP=37.02). April 6th first 2 bailers all gas DTW 40.57 and DTP = 37.27; PT = 3.3 ft - recovered 3 full bailers (~ 1 gal). - J. Kolleeny 06/21/23: Reviewed Monitoring Rpt for May 2023 by Berninger Envt'l. Rpt presents results of monthly gauging of one on-site well for March, April, and May 2023. On March 23rd, depth to water in well MW-1 was 37.52 ft, well had 6 inches of free product, 5 gals were bailed from well (table doesn't specify if this was pure product or mix of product and water). On April 5th, depth to water in well MW-1 was 40.57 ft, well had 3.30 ft of product; 5 gals were bailed from well. On May 11th, depth to water in well MW-1 was only 26.65 ft, no free product was detected (maybe buried beneath water table?), 7 gals of contaminated petroleum-impacted water were bailed. Rpt lists Recovery System as Bailing of product, approx 1.5 gals until well is dry, recharge rate approx 1.0 to 1.5 gals per half hour, total amount of product/water bailed on average per event is 5 to 10 gals. Next monitoring event and bailing of product is scheduled for June 2023. - J. Kolleeny 10/03/23: Reviewed Monitoring Rpt for August 2023 by Berninger Envt'l. Rpt presents results of monthly gauging and bailing of one on-site well (MW-1) in June, July and August 2023. On 6/27/23, well MW-1 had 13 ft (!) of free product; 2 gals were bailed. On 7/24/23, MW-1 had 16.9 ft (!) of free product; 5 gals were bailed. On 8/11/23, MW-1 had 4.14 ft of free product; 5 gals were bailed. Notes for 8/11/23 state that well showed good recharge during this event. Rpt lists Objective as monitoring for product monthly, bailing as necessary; lists Recovery System as bailing of product, approx. 1.5 gals until well is dry, recharge rate approx. 1.0 to 1.5 gals per half hour. Comments state that free product was detected this monitoring period, site was monitored and product bailed on 8/11/23; next monitoring & bailing of product scheduled for September 2023. - J. Kolleeny 01/02/24: Reviewed Monitoring Rpt for November 2023 by Berninger Envt'l, received on 12/14/23. Rpt presents results of monthly gauging & bailing of on-site well MW-1 in Sept., Oct., and Nov. 2023. On 9/13/23, well MW-1 had 0.65 ft of LNAPL, 5 gals of liquid (product + water) were bailed. On 10/12/23, MW-1 had 1/4 inch of LNAPL, 5 gals of liquid were bailed. On 11/20/23, MW-1 had 1.38 ft of LNAPL, 5 gals of liquid were bailed. Next monitoring & bailing scheduled for December 2023. - JK

All Materials:
Site ID: 582069
Operable Unit ID: 1329759

COMMERICAL (Continued) **S123660794**

Operable Unit:	01
Material ID:	2338899
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

A9 **LOT 6,TAXBLOCK 714** **NY E DESIGNATION** **S110092265**
Target **4001 4 AVENUE** **NY NYC LAND USE** **N/A**
Property **BROOKLYN, NY 11232**

Site 9 of 36 in cluster A

Actual: 51 ft.

E DESIGNATION:

Name:	LOT 6,TAXBLOCK 714
Address:	4001 4 AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Tax Lot(s):	6
Tax Block:	714
Borough Code:	BK
E-No:	E-236
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	09DCP075K
Ulurp Number:	090387ZMK
Zoning Map No:	16b 16d 22a 22c
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems;Exhaust stack location limitations;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	4001 4 AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Latitude:	40.6517156
Longitude:	-74.0066203
Type Of Ownership Code:	Not reported
Owner Name:	4001 4TH LLC
Borough:	BK
Tax Block:	714
Tax Lot:	6
Community District:	307
Census Tract 2020:	3008200
Census Block 2020:	30082001000
Census Tract 2010:	82
Census Block 2010:	1000
School District:	15
City Council District:	38
Fire Company:	E228

LOT 6,TAXBLOCK 714 (Continued) **S110092265**

Police Precinct:	72
Health Center District:	39
Health Area:	6600
Sanitation District Boro:	3
Sanitation District Number:	07
Sanitation Subsection:	2E
Zoning District 1:	R7A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	G3: GARAGES AND GASOLINE STATIONS - Gas Station with Retail Store
Land Use Category:	Transportation & Utility
Number Of Easements:	0
Lot Area:	10017
Total Building Floor Area:	1860
Commercial Floor Area:	1860
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	1860
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	100.1700000
Lot Depth:	100.0000000
Building Frontage:	60.0000000
Building Depth:	31.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	72000.00000
Assessed Total Value:	316350.00000
Exempt Total Value:	0.00000
Year Built:	1965
Year Altered 1:	1986
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.19000000000
Maximum Allowable Residential Far:	4.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.00000000000
Boro Code:	3

LOT 6,TAXBLOCK 714 (Continued) **S110092265**

Borough, Tax Block and Lot:	3007140006.00000000
Condominium Number:	Not reported
Census Tract 2:	0082
X Coordinate:	982413
Y Coordinate:	176714
Zoning Map #:	16b
Zoning Map Code:	Not reported
Sanborn Map #:	306A021
Tax Map #:	30303
E-designation Number:	E-236
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	23v1.1
Changed By DCP:	Not reported

A10 **H & S AMOCO** **RCRA NonGen / NLR** **1004755472**
Target **4001 4TH AVE** **FINDS** **NY0000017582**
Property **BROOKLYN, NY 11232** **ECHO**

Site 10 of 36 in cluster A

Actual: **51 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	H & S Amoco
Handler Address:	4TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NY0000017582
Contact Name:	SAM PAREDA
Contact Address:	4TH AVE
Contact City,State,Zip:	BROOKLYN, NY 11232
Contact Telephone:	718-851-3008
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	4TH AVE
Mailing City,State,Zip:	BROOKLYN, NY 11232
Owner Name:	Sam Pareda
Owner Type:	Private
Operator Name:	Sam Pareda
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

H & S AMOCO (Continued) **1004755472**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D039
Waste Description:	Tetrachloroethylene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SAM PAREDA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	4001 4TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11232
Owner/Operator Telephone:	718-851-3008
Owner/Operator Telephone Ext:	Not reported

H & S AMOCO (Continued) **1004755472**

Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: SAM PAREDA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	4001 4TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11232
Owner/Operator Telephone:	718-851-3008
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: SAM PAREDA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	4001 4TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11232
Owner/Operator Telephone:	718-851-3008
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: H & S AMOCO	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: H & S AMOCO	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19931004
Handler Name: H & S AMOCO	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator

H & S AMOCO (Continued) **1004755472**

State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004307919

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004755472
Registry ID:	110004307919
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004307919
Name:	H & S AMOCO
Address:	4001 4TH AVE
City,State,Zip:	BROOKLYN, NY 11232

A11 **B & L GAS STATION ENTERPRISES, I NC.** **NY UST** **U004063031**
Target **4001 4TH AVENUE** **N/A**
Property **BROOKLYN, NY 11232**

Site 11 of 36 in cluster A

Actual: **51 ft.**

UST:

Name:	B & L GAS STATION ENTERPRISES, I NC.
Address:	4001 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Id/Status:	2-349399 / Active
Program Type:	PBS
Region:	STATE

B & L GAS STATION ENTERPRISES, I NC. (Continued) **U004063031**

DEC Region: 2
Expiration Date: 09/09/2023
UTM X: 583995.39504
UTM Y: 4500573.49218
Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 17199
Affiliation Type: Facility Owner
Company Name: 4001 4TH LLC
Contact Type: MEMBER
Contact Name: JOSEPH MACCHIA
Address1: 556 CENTRAL AVENUE
Address2: Not reported
City: BETHPAGE
State: NY
Zip Code: 11714
Country Code: 001
Phone: (516) 933-0700
EMail: JOSEPH@THEMACCHIAGROUP.NET
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2018-07-09

Site Id: 17199
Affiliation Type: Mail Contact
Company Name: 4001 4TH LLC
Contact Type: MEMBER
Contact Name: JOSEPH MACCHIA
Address1: 556 CENTRAL AVENUE
Address2: Not reported
City: BETHPAGE
State: NY
Zip Code: 11714
Country Code: 001
Phone: (516) 933-0700
EMail: JOSEPH@THEMACCHIAGROUP.NET
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2018-07-09

Site Id: 17199
Affiliation Type: Facility Operator
Company Name: B & L GAS STATION ENTERPRISES, I NC.
Contact Type: Not reported
Contact Name: JOSEPH MACCHIA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 851-0006
EMail: Not reported
Fax Number: Not reported
Modified By: AYLAGATI
Date Last Modified: 2016-11-08

B & L GAS STATION ENTERPRISES, I NC. (Continued) **U004063031**

Site Id:	17199
Affiliation Type:	Emergency Contact
Company Name:	4001 4TH LLC
Contact Type:	Not reported
Contact Name:	JOSEPH MACCHIA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 933-0700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	dxliving
Date Last Modified:	2008-10-15

Tank Info:

Tank Number:	101
Tank ID:	33491
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	04/01/1985
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	34
Date Test:	05/03/2021
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	LABATIST
Last Modified:	05/03/2023

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A01 - Tank Internal Protection - Epoxy Liner
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
I03 - Overfill - Automatic Shut-Off
H05 - Tank Leak Detection - In-Tank System (ATG)
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring

Tank Number:	102

B & L GAS STATION ENTERPRISES, I NC. (Continued) **U004063031**

Tank ID: 33492
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 04/01/1985
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 34
Date Test: 05/03/2021
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: LABATIST
Last Modified: 05/03/2023

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
I03 - Overfill - Automatic Shut-Off
A01 - Tank Internal Protection - Epoxy Liner
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 103
Tank ID: 33493
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 04/01/1989
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: 0
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 34
Date Test: 05/03/2021
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: LABATIST
Last Modified: 05/03/2023

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)

B & L GAS STATION ENTERPRISES, I NC. (Continued) **U004063031**

G04 - Tank Secondary Containment - Double-Walled (Underground)
B05 - Tank External Protection - Jacketed
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
I03 - Overfill - Automatic Shut-Off
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
B07 - Tank External Protection - Retrofitted Sacrificial Anode

Tank Number:	104
Tank ID:	33494
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	04/01/1989
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	0
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	34
Date Test:	05/03/2021
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	LABATIST
Last Modified:	05/03/2023

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
H05 - Tank Leak Detection - In-Tank System (ATG)
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)

A12 **CON EDISON - SERVICE BOX** **NY MANIFEST** **S120958610**
412 40 ST **N/A**
< 1/8 **BROOKLYN, NY 11232**
1 ft.

Site 12 of 36 in cluster A

Relative: NY MANIFEST:
Higher

Actual: EPA ID:	NYP004951388
54 ft. Country:	USA
Name:	CON EDISON - SERVICE BOX
Address:	412 40 ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	412 40 ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON - SERVICE BOX
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

A13 **MANHOLE 4084** **NY Spills** **S104654056**
NNW **40TH ST/4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.009 mi.
48 ft.

Site 13 of 36 in cluster A

Relative: SPILLS:
Lower

Actual: Name:	MANHOLE 4084
47 ft. Address:	40TH ST/4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0003749 / 2009-09-10
Facility ID:	0003749
Facility Type:	ER
DER Facility ID:	158861
Site ID:	190436
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-06-27
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2000-06-27
CID:	382
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party

MANHOLE 4084 (Continued) **S104654056**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-06-27
Spill Record Last Update:	2009-09-10
Spiller Name:	MARK SCHLAGEL
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MARK SCHLAGEL
DEC Memo:	1PT OIL IN MANHOLE. CLEAN UP PENDING INSPECTION. CON ED 132-058
Remarks:	09/10/09 - See eDocs for Con Ed report detailing cleanup and closure. Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL

All Materials:

Site ID:	190436
Operable Unit ID:	825058
Operable Unit:	01
Material ID:	548499
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A14 **SUNSET CAR CARE SITE** **NY SHWS S118261357**
SW **4013 4TH AVENUE** **NY Spills N/A**
< 1/8 **BROOKLYN, NY 11232**
0.009 mi.
49 ft. **Site 14 of 36 in cluster A**

Relative:
Higher

Actual:
56 ft.

SHWS:

Name:	SUNSET CAR CARE SITE
Address:	4013 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Program:	HW
Site Code:	532551
Classification:	N
Region:	2
Acres:	0.230
HW Code:	224244
Record Add:	09/14/2016
Record Upd:	07/08/2020
Updated By:	JCGRATHW
Site Description:	Location: The Site is located at the corner of 41st Street and 4th Avenue in the northwestern portion of Brooklyn. The site is bounded on the north by an active gasoline station, on the south by a fast food restaurant and on the east by a 3-story residential building. West of the site is 4th Avenue, the MTA Subway tunnel and the PS 136

SUNSET CAR CARE SITE (Continued) **S118261357**

Charles O'Dewey Elementary School. Site Features: The site is a vacant one-story building with no basement. The building covers approximately half of the 10,017 square-foot lot (0.23 acres) and was recently used as an auto repair business, a car wash and a small store. In addition to the existing building, there are tire racks, an oil change area, oil traps to a waste oil tank, car wash dry well, an office area, a car wash, hydraulic lifts, a 1,040 waste oil tank, a 1,040 gallon motor oil tank, an asphalt parking lot, and 6 potential underground storage tanks (USTs) identified on Sanborn Maps. Current Zoning/Use(s): The area is zoned C2-4. C2-4 districts serve the immediate needs of surrounding lower- and medium-density residential neighborhoods along streets that provide small local retail and service shops. Typical retail uses include neighborhood grocery stores, restaurants, beauty parlors, funeral homes and repair services. The Community Facility Use for C2-4 districts provides educational, health, recreational, religious or other essential services. Historical Use(s): The site has been an automobile garage, gas station, and car wash since 1926. From 1942-1995, three USTs were noted on Sanborn maps and two USTs (possibly removed) were identified on the 1926 Sanborn Map. Other uses are listed as an office/warehouse space for various tenants, taxi/limo parking and repair services. A Phase I Environmental Assessment was performed in July 2015 and a Phase II Environmental Assessment was performed in August 2015. Site Geology and Hydrogeology: The elevation of the property is approximately 55 feet above mean sea level. The general soil type consists of fine to coarse-grained sand and silty sand with gravel. Historic fill was encountered from grade to 15 feet below grade (deepest soil boring depth). The depth to water ranges from 18 feet (MW-3) to 44 feet (MW-1). The depth to water observed in MW-3 may be attributed to influence from the car washing operations (dry well), which may be contributing water to the aquifer. The groundwater flow direction is northwest towards the Upper Bay/Gowanus Bay three blocks away. The site did not qualify for addition to the Registry of Inactive Hazardous Disposal Sites.

Env Problem: This spill was originally reported on August 9, 2015 during a Phase II Environmental Site Assessment (Phase II) through the New York City Office of Environmental Remediation Brownfield Program. The Phase II included the installation and sampling of a series of soil probes, monitoring wells and soil vapor sampling points that showed impacted soil and groundwater. Nature of Contamination: Petroleum spill with soil and groundwater impacts, and elevated tetrachloroethylene (PCE) in soil vapor. Volatile Organic Compounds (VOCs) associated with gasoline constituents and chlorinated compounds are present beneath the northern portions of the Site. VOCs indicative of petroleum were identified in both shallow and deep soil in the northwest portion of the property. This impacted soil is located at the former location of two (2) underground storage tanks (USTs) identified on the 1926 Sanborn Map. Results of the groundwater evaluation completed did not identify any exceedances of PCE in groundwater above the groundwater standard of 5 ppb. However, investigation results showed impacts of petroleum constituents and metals above their respective groundwater standards. A soil vapor evaluation was completed as part of the Phase II investigation and a supplemental soil vapor investigation did not identify any off-site impacts that would require monitoring or mitigation per the NYSDOH guidance values. Significant Threat Determination: Based on investigations performed to date, the site did not qualify for addition to the Registry of Inactive Hazardous

SUNSET CAR CARE SITE (Continued) **S118261357**

Waste Sites. The site was referred back for investigation and remediation under Spill No. 15-06140. Site designation was changed from P to N.

Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	4
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Sunset Car Care (aka 4013 Car Care)
Owner Address:	125 42nd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11232
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Elsaun Inc.
Owner Address:	125 42nd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11232
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	FORMER GAS STATION/CURRENT AUTO REPAI
Address:	4013 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1506140 / 2021-05-27
Facility ID:	1506140
Facility Type:	ER
DER Facility ID:	468053
Site ID:	513543
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	2015-08-09

SUNSET CAR CARE SITE (Continued) **S118261357**

Investigator:	JXPEREZM
Referred To:	Not reported
Reported to Dept:	2015-09-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-09-09
Spill Record Last Update:	2021-05-27
Spiller Name:	CARLOS QUINONEZ
Spiller Company:	FORMER GAS STATION
Spiller Address:	4013 4TH AVE
Spiller Company:	999
Contact Name:	CARLOS QUINONEZ
DEC Memo:	Phase II investigation test results showed impacted soil & ground water. Cleanup is pending.
Remarks:	9/11/15-Zhune called Carlos Quinonez from Hydro Tech (631) 462-5866. Mary said he is not available and he will call me back. 1/14/16-Vought-This spill transferred from DEC Zhune to DEC Omar as per DEC Demeo. 1/15/2016: Rashad 4013 4th Avenue has an alternate address of 401 41st Street. No additional spills found for site. 4013 4th Avenue has PBS#2-611076 for a 1,000 gallon waste/used oil AST. No documents found in D2. 1/19/2016: Rashad Sent email to Carlos: I have been reassigned 2 spills that list you as a contact, they are as follows: Spill#1305487 822 4th Ave, Brooklyn 11232, date received was 8/21/2013, Spill#1506140 4013 4th Ave, Brooklyn 11232, date received was 9/9/2015. I would appreciate any documentation/information you have on either of these sites. 1/20/2016: Rashad Carlos responded on 1/19 saying he will call me and give me an update on both sites. 3/10/2016: Rashad Sent email to Carlos: Can you please send me the Phase 2 investigation as well as any other reports you have for this site. 3/11/2016: Rashad Carlos responded on 3/10: Please see attached the report for the Phase II we performed. Any questions pelase let me know. thanks Phase 2 report was attached and uploaded to D2. Review of Phase 2 report: Depth to groundwater has been identified to range from 18 feet to 45 feet and the groundwater flow direction was identified to be northwest. No free product was identified on the water table. Dissolved VOCs indicative of petroleum were identified in groundwater beneath the southern and northern portions of the site at concentrations exceeding standards. Dissolved metals were also detected in groundwater. VOCs associated with gasoline constituents and chlorinated compounds are both present beneath the southern and northern portions of the site. The site is occupied by a 1 story building that consists of an auto repair business, car wash and a small store. The building does not have a basement. Building is heated with natural gas. A GPR, 7 soil probes, 3 groundwater monitoring wells and 4 soil vapor probes were taken. The GPR detected one anomaly in the western portion of the Site and one anomaly was detected in the northwestern portion of the site. According to historic sanborn maps there are 3 gasoline tanks located in the northwestern portion of the site. Soil probes SP-1 and SP-2 were

SUNSET CAR CARE SITE (Continued) **S118261357**

installed in the approximate locations of 2 gasoline tanks in the northwestern portion of site. SP-3 and SP-6 were also installed near these tanks. SP-4 was installed in the approximate location of 3 gasoline tanks in the southwest portion of the site. SP-5 and SP-7 were installed in the easten portion of the site in the vicinity of the former auto repair shop and active car wash. SP-1, SP-4, and SP-7 were installed to a depth of 12 feet. SP-2, SP-3, and SP-5 were installed to a depth of 14feet, SP-6 was installed to depth of 16 feet. Three monitoring wells MW1-MW3 were installed in the same locations as SP-1, SP-4, and SP-7 respectively. They were installed to a depth of 55ft, 60 ft and 55 ft. None of the wells contained free product. Depth to water ranged from 18.4 feet in MW3 to 44.5ft in MW1. Soil sample SP-2 taken 4-6ft had contamination as follows: 1,2,4 Trimethylbenzene - 95ppm, 1,3,5 Trimethylbenzene - 42ppm, Ethylbenzene - 3.2ppm, Naphthalene - 19ppm, Xylene - 17ppm, At 12- 14 ft: 1,2,4 Trimethylbenzene - 180ppm, 1,3,5 Trimethylbenzene - 71ppm, Ethylbenzene - 42ppm, Naphthalene - 32ppm, n-Butylbenzene - 26ppm, n-Propylbenzene-33ppm, Xylene-180ppm, Toluene-5.90ppm. Other soil locations did not have elevated concentrations. MW1 has a groundwater elevation of 51ft, contamination found in MW1 is as follows: 1,2,4 Trimethylbenzene-1500ppb, 1,3,5 Trimethylbenzene-1300ppb, Acetone-57ppb, Benzene-1100ppb, Ethylbenzene-2700ppb, Isopropylbenzene-82ppb, Naphthalene-180ppb, xylene-13,000ppb, Toluene-1800ppb. MW2 had a groundwater elevation of 53ft, contaminates found in MW2 are as follows: 2-butanone-15ppb, acetone-32ppb, benzene-8ppb, xylene-4ppb. MW3 had a groundwater elevation of 78ft, the following contaminats were found in MW3: 1,2,4 Trimethylbenzene-510ppb, 1,3,5 Trimethylbenzene-100ppb, ethylbenzene-280ppb, isopropylbenzene-68ppb, Naphthalene-60ppb, xylene-1200ppb, toluene-96ppb. Soil Vapor samples were taken and are as follows for SV1: 1,2,4 Trimethylbenzene - 20ug/m3, 1,3 Butadiene-50, 2-butanoe-62, 2-hexanone-20, acetone-230, benzene-18, chloroform-16, cyclohexane-3, dichlorofluromethane-7.7, ethylbenzene-14, methylene chloride-1.5, n-heptane-30, n-hexane-49, xylene-46, p-ethlytoluene-70, tetrachlorethylene-70, toluene-54. SV2 has similar readings to SV1. SV3 had tetrachloroethylene-1400 and SV4 had tetrachloroethylene-3800. According to the Phase 2: Depth of water in MW3 may be attributed to influence from the car washing operations, which may be contributing water to the aquifer Soil sample SP5 (4-6ft) - Tetrachloroethylene - 0.047ppm. MW3 has Tetrachloroethylene-4ppb. Sent email to Carlos: Thank you for the report, is this site a BCP or OER site? Also has a Remedial Action Work Plan been made yet and are there any plans for redevelopment? Brief review of the Phase 1 has subject property of one story auto laundry located in southern portion since 1926 and auto repair shop which contains the discussed tanks. 8/10/2016: Rashad Sent email to Carlos: See below questions, also is any work occurring on this site currently? Carlos responded: Yes indeed this site is an OER site. no further work has taken place to our knowledge since our submittal of the report. We did provide the client with a cost estimate letter but he didn t want to proceed after that. I will reach out to him and will try to get more information for you. 8/12/2016: Rashad Spoke to DEC Vought and I sent email to Shaminder from OER to see if he has any further info on site. Report receipt review letter should include - delineation of soil and groundwater, development plans, RAP approval warning before redevelopment. Shaminder responded that site was previously discussed with DEC O'Connell to enter BCP, I will

SUNSET CAR CARE SITE (Continued) **S118261357**

email Jane to discuss case. 8/22/2016: Rashad Letter was prepared and will be sent to property owner as well as emailed to Carlos of Hydrotech to address petroleum contamination. Letter was uploaded to D2. 8/25/2016: Rashad Received call from Sam, who is property owners son. He wanted to discuss contaminated soil letter that was sent to him. At this time the car wash and lube center is still in service and they are planning to close the last day of this year and either redevelop or sell property. His email is samson414@gmail.com, phone number is 917-656-4676. DEC Potentially Requires: 1-BCP or OER 2-Future use - CAMP, depth of basement piping locations, vapor barrier, ssds with doh review 3-Possible delineation across 4th Ave and its affect with groundwater 4-RAP 5-BP station spills 6-Review Phase 1 for previous source of chlorinated solvent 7-Owner: Elsaun Inc, 125 42nd Street Brooklyn NY 11232 1/17/17 - Obligado - Spill assigned to Obligado from Omar as per Austin. 1/10/18 - Obligado - Spill transferred to from Obligado to Feng. 3/16/2018 - Durnin - DER mailed a P site Notification letter to the property owner on March 16, 2018. Environmental Assessment: Volatile organic compounds (VOCs) associated with gasoline constituents: Benzene (1,100 ppb), Ethyl Benzene (2,700 ppb), o?Xylene (5,800 ppb), p & m? Xylenes (13,000 ppb), and Toluene (1,800 ppb), were found in groundwater (groundwater standard of 5 ppb). Chlorinated compound tetrachloroethylene (PCE) was detected in on-site soil vapor throughout much of the site between 66 ug/m3 and 3,800 ug/m3. (Durnin 3/29/2018) March 2017 - March 2018: After over a year nothing was done and apparently the owner was trying to sell the site. DER mailed a second P Site notification letter to the owner on March 16, 2018 but it was returned as undeliverable. It was resent to the site address (not the owner address) later in March 2016. On August 2018, DEC staff visited the site and provide copy of contact information to the receptionist. The Owner was not available at the time. On August 2019, access request letters (English and Spanish version) were resent to property owner. As of today, we haven't received any verbal or written communication from the property owner. (Grathwol - 6/24/20) 5/27/21 - Site Characterization completed under site no. 224244. No further action needed. Spill closed. (JHO)

All Materials:

Site ID:	513543
Operable Unit ID:	1262763
Operable Unit:	01
Material ID:	2266364
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil, Groundwater
Oxygenate:	Not reported

A15
SW
< 1/8
0.009 mi.
49 ft.

4013 CAR CARE
4013 4TH AVENUE
BROOKLYN, NY 11232

Site 15 of 36 in cluster A

NY AST **A100343970**
N/A

Relative:
Higher

Actual:
56 ft.

AST:

Name:	4013 CAR CARE
Address:	4013 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611076
Program Type:	PBS
UTM X:	583966.09041
UTM Y:	4500556.33399
Expiration Date:	05/08/2024
Site Type:	Other

Affiliation Records:

Site Id:	413589
Affiliation Type:	Mail Contact
Company Name:	4013 CAR CARE
Contact Type:	Not reported
Contact Name:	SAMUEL PARADA
Address1:	125 42ND STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(718) 437-7593
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-11-07

Site Id:	413589
Affiliation Type:	Facility Operator
Company Name:	SUPERIOR CAR WASH
Contact Type:	Not reported
Contact Name:	SAM PARADA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 437-7593
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-05-08

Site Id:	413589
Affiliation Type:	Emergency Contact
Company Name:	SAM PARADA
Contact Type:	Not reported
Contact Name:	SAM PARADA

4013 CAR CARE (Continued) **A100343970**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 704-0251
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-05-08

Site Id:	413589
Affiliation Type:	Facility Owner
Company Name:	ELSAUN INC.
Contact Type:	OFFICER
Contact Name:	SAMUEL PARADA
Address1:	125 42ND STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(917) 656-4676
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-03-19

Tank Info:

Tank Number:	01
Tank Id:	228357
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	L02 - Piping Leak Detection - Interstitial - Manual Monitoring E00 - Piping Secondary Containment - None H00 - Tank Leak Detection - None D01 - Pipe Type - Steel/Carbon Steel/Iron A00 - Tank Internal Protection - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1995
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

4013 CAR CARE (Continued) **A100343970**

Material Name: waste oil/used oil

A16 **BORIS AUTO REPAIR** **RCRA NonGen / NLR** **1000555998**
SW **4013 4TH AVE** **FINDS** **NYD986985471**
< 1/8 **BROOKLYN, NY 11232** **ECHO**
0.009 mi.
49 ft. **Site 16 of 36 in cluster A**

Relative:
Higher

Actual:
56 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Boris Auto Repair
Handler Address:	4TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232-3401
EPA ID:	NYD986985471
Contact Name:	Not reported
Contact Address:	4TH AVE
Contact City,State,Zip:	BROOKLYN, NY 11232
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	4TH AVE
Mailing City,State,Zip:	BROOKLYN, NY 11232
Owner Name:	Boris Jairala
Owner Type:	Private
Operator Name:	Boris Jairala
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No

BORIS AUTO REPAIR (Continued) **1000555998**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: BORIS JAIRALA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	4013 4TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11232
Owner/Operator Telephone:	718-633-0373
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: BORIS JAIRALA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	4013 4TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11232
Owner/Operator Telephone:	718-633-0373
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner

BORIS AUTO REPAIR (Continued) **1000555998**

Owner/Operator Name: BORIS JAIRALA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4013 4TH AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11232
Owner/Operator Telephone: 718-633-0373
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990708
Handler Name: BORIS AUTO REPAIR
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: BORIS AUTO REPAIR
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: BORIS AUTO REPAIR
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19911224
Handler Name: BORIS AUTO REPAIR
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

BORIS AUTO REPAIR (Continued) **1000555998**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004482382

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000555998
Registry ID:	110004482382
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004482382
Name:	BORIS AUTO REPAIR
Address:	4013 4TH AVE
City,State,Zip:	BROOKLYN, NY 11232

A17 **BATAN TOWING SERVICE INC** **EDR Hist Auto** **1021979215**
SW **4013 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.009 mi.
49 ft. **Site 17 of 36 in cluster A**

Relative: EDR Hist Auto
Higher

Actual: **56 ft.**

Year:	Name:	Type:
1980	ECUADOR SERVICE STATION INC	General Automotive Repair Shops
1982	ECUADOR SERVICE STATION INC	General Automotive Repair Shops
1983	ECUADOR SERVICE STATION	General Automotive Repair Shops
1985	ECUADOR SERVICE STATION	General Automotive Repair Shops
1986	ECUADOR SERVICE STATION	General Automotive Repair Shops
1987	ECUADOR SERVICE STATION	General Automotive Repair Shops
1988	ECUADOR SERVICE STATION	General Automotive Repair Shops

BATAN TOWING SERVICE INC (Continued) **1021979215**

1989	EQUADOR SERVICE STATION	Gasoline Service Stations
1990	EQUADOR SERVICE STATION	Gasoline Service Stations
1991	EQUADOR SERVICE STATION	Gasoline Service Stations
2010	4013 CAR CARE INC	General Automotive Repair Shops

A18 **LOT 1,TAXBLOCK 714** **NY E DESIGNATION** **S117675785**
SW **N/A**
< 1/8 **MANHATTAN, NY**
0.009 mi.
49 ft. **Site 18 of 36 in cluster A**

Relative:
Higher

Actual:
56 ft.

E DESIGNATION:

Name:	LOT 1,TAXBLOCK 714
Address:	Not reported
City,State,Zip:	MANHATTAN, NY
Tax Lot(s):	1
Tax Block:	714
Borough Code:	Not reported
E-No:	E-142
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	03DCP069M
Ulurp Number:	050161 ZRM
Zoning Map No:	8b
Description:	Underground Gasoline Storage Tanks* Testing Protocol.;Window Wall Attenuation & Alternate Ventilation
Lot Remediation Date:	Not reported

A19 **LOT 1,TAXBLOCK 714** **NY E DESIGNATION** **S110092209**
SW **4013 4 AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.009 mi.
49 ft. **Site 19 of 36 in cluster A**

Relative:
Higher

Actual:
56 ft.

E DESIGNATION:

Name:	LOT 1,TAXBLOCK 714
Address:	4013 4 AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	1
Tax Block:	714
Borough Code:	Not reported
E-No:	E-236
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	09DCP075K
Ulurp Number:	090387ZMK
Zoning Map No:	16b 16d 22a 22c
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems;Exhaust stack location limitations;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported

LOT 1,TAXBLOCK 714 (Continued) **S110092209**

Address:	4013 4 AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Latitude:	40.6514960
Longitude:	-74.0068509
Type Of Ownership Code:	Not reported
Owner Name:	ELSAUM INC
Borough:	BK
Tax Block:	714
Tax Lot:	1
Community District:	307
Census Tract 2020:	3008200
Census Block 2020:	30082001000
Census Tract 2010:	82
Census Block 2010:	1000
School District:	15
City Council District:	38
Fire Company:	E228
Police Precinct:	72
Health Center District:	39
Health Area:	6600
Sanitation District Boro:	3
Sanitation District Number:	07
Sanitation Subsection:	2E
Zoning District 1:	R7A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	GW: GARAGES AND GASOLINE STATIONS - Car Wash or Lubritorium Facility
Land Use Category:	Commercial & Office Buildings
Number Of Easements:	0
Lot Area:	10017
Total Building Floor Area:	6500
Commercial Floor Area:	6500
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	6500
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	100.1700000
Lot Depth:	100.0000000
Building Frontage:	100.0000000
Building Depth:	84.0000000
Extension Code:	E

LOT 1,TAXBLOCK 714 (Continued) **S110092209**

Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	157950.00000
Assessed Total Value:	500850.00000
Exempt Total Value:	0.00000
Year Built:	1950
Year Altered 1:	1996
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.65000000000
Maximum Allowable Residential Far:	4.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3007140001.00000000
Condominium Number:	Not reported
Census Tract 2:	0082
X Coordinate:	982349
Y Coordinate:	176634
Zoning Map #:	16b
Zoning Map Code:	Not reported
Sanborn Map #:	306A021
Tax Map #:	30303
E-designation Number:	E-236
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	23v1.1
Changed By DCP:	Not reported

A20 **CON EDISON SERVICE BOX: 49286** **RCRA NonGen / NLR** **1017775129**
ESE **420 40TH ST** **FINDS** **NYP004529541**
< 1/8 **BROOKLYN, NY 11232**
0.011 mi.
60 ft. **Site 20 of 36 in cluster A**

Relative: RCRA Listings:
Higher

Actual: Date Form Received by Agency:	20140613
59 ft. Handler Name:	Con Edison Service Box: 49286
Handler Address:	40TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004529541
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CON EDISON SERVICE BOX: 49286 (Continued) **1017775129**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140513
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator

CON EDISON SERVICE BOX: 49286 (Continued) **1017775129**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140513
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140613
Handler Name: CON EDISON SERVICE BOX: 49286
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063808116

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many

CON EDISON SERVICE BOX: 49286 (Continued) **1017775129**

types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A21 **CON EDISON** **NY MANIFEST** **S117060715**
ESE **420 40TH ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.011 mi.
60 ft. **Site 21 of 36 in cluster A**

Relative:
Higher

Actual:
59 ft.

NY MANIFEST:

EPA ID:	NYP004529541
Country:	USA
Name:	CON EDISON
Address:	420 40TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	420 40TH ST
Location Address 2:	SB 49286
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/2014
Trans1 Recv Date:	05/13/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004529541
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013246313JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

CON EDISON (Continued) **S117060715**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	75
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

A22 **VM REALTY 8 LLC** **NY AST** **A100293072**
ENE **417-441 40 STREET** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.016 mi.
87 ft. **Site 22 of 36 in cluster A**

Relative:
Higher

Actual:
54 ft.

AST:

Name:	VM REALTY 8 LLC
Address:	417-441 40 STREET
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608147
Program Type:	PBS
UTM X:	584015.12212
UTM Y:	4500583.31890
Expiration Date:	06/11/2025
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	29999
Affiliation Type:	Facility Owner
Company Name:	VM REALTY 8, LLC
Contact Type:	PROPERTY MGR
Contact Name:	JOHN CALISE
Address1:	6717 4TH AVENUE
Address2:	Not reported
City:	BROOKYLN
State:	NY

VM REALTY 8 LLC (Continued) **A100293072**

Zip Code:	11220
Country Code:	001
Phone:	(718) 672-8106
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-02-19

Site Id:	29999
Affiliation Type:	Facility Operator
Company Name:	VM REALTY 8 LLC
Contact Type:	Not reported
Contact Name:	JOHN CALISE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 438-7538
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-02-19

Site Id:	29999
Affiliation Type:	Mail Contact
Company Name:	VM REALTY 8, LLC
Contact Type:	Not reported
Contact Name:	JOHN CALISE
Address1:	6717 4TH AVENUE
Address2:	Not reported
City:	BROOKYLN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 628-8106
EMail:	JCALISE@APPROVEDOIL.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2021-02-19

Site Id:	29999
Affiliation Type:	Emergency Contact
Company Name:	VM REALTY 8, LLC
Contact Type:	Not reported
Contact Name:	JOHN CALISE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 628-8106
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL

VM REALTY 8 LLC (Continued) **A100293072**

Date Last Modified: 2021-02-19

Tank Info:

Tank Number: 001
Tank Id: 64673
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
J05 - Dispenser - On Site Heating System (Supply/Return)
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/01/1987
Capacity Gallons: 3000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

A23 **I.S. 136 - BROOKLYN K136** **NY AST** **A100178469**
NW **4004 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.018 mi.
96 ft. **Site 23 of 36 in cluster A**

Relative: AST:
Lower
Actual: Name: I.S. 136 - BROOKLYN K136
48 ft. Address: 4004 4TH AVE
City,State,Zip: BROOKLYN, NY 11232
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-606291
Program Type: PBS
UTM X: 583986.14218
UTM Y: 4500584.87580
Expiration Date: 07/11/2026

I.S. 136 - BROOKLYN K136 (Continued) **A100178469**

Site Type: School

Affiliation Records:

Site Id: 28155
Affiliation Type: Mail Contact
Company Name: NYC DEPARTMENT OF EDUCATION
Contact Type: MANAGER, FUEL DIVISION
Contact Name: JOSEPH YOUNGHESE
Address1: FIELD OPERATIONS-FUEL DIVISION
Address2: 44-36 VERNON BOULEVARD
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5751
EMail: JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number: Not reported
Modified By: KXLIU
Date Last Modified: 2023-06-16

Site Id: 28155
Affiliation Type: Emergency Contact
Company Name: NYC DEPARTMENT OF EDUCATION
Contact Type: Not reported
Contact Name: KEN MAHADEO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 210-7918
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2020-02-04

Site Id: 28155
Affiliation Type: Facility Owner
Company Name: NYC DEPARTMENT OF EDUCATION
Contact Type: MANAGER. FUEL DIVISION
Contact Name: JOSEPH YOUNGHESE
Address1: 44-36 VERNON BLVD.
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5751
EMail: MSHARMA@SCHOOLS.NYC.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2022-08-03

Site Id: 28155
Affiliation Type: Facility Operator
Company Name: PUBLIC SCHOOL 136-BROOKLYN
Contact Type: Not reported

I.S. 136 - BROOKLYN K136 (Continued) **A100178469**

Contact Name:	DAVID GRONOCK, JR.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 499-3504
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-12-15

Tank Info:

Tank Number:	001
Tank Id:	61221
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	K01 - Spill Prevention - Catch Basin
	E00 - Piping Secondary Containment - None
	H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	F01 - Pipe External Protection - Painted/Asphalt Coating
	A00 - Tank Internal Protection - None
	L00 - Piping Leak Detection - None
	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	J02 - Dispenser - Suction Dispenser
	C03 - Pipe Location - Aboveground/Underground Combination
	I04 - Overfill - Product Level Gauge (A/G)
	I05 - Overfill - Vent Whistle
	G02 - Tank Secondary Containment - Vault (w/access)
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1992
Capacity Gallons:	7500
Tightness Test Method:	34
Date Test:	07/06/2023
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	LABATIST
Last Modified:	08/29/2023
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	61222
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

I.S. 136 - BROOKLYN K136 (Continued) **A100178469**

Equipment Records:

K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
F01 - Pipe External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
I04 - Overfill - Product Level Gauge (A/G)
I05 - Overfill - Vent Whistle
G02 - Tank Secondary Containment - Vault (w/access)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1992
Capacity Gallons:	7500
Tightness Test Method:	34
Date Test:	07/06/2023
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	LABATIST
Last Modified:	08/29/2023
Material Name:	#2 fuel oil (on-site consumption)

A24 **CON EDISON** **RCRA NonGen / NLR** **1018280524**
ENE **415 40TH ST** **FINDS** **NYP004754115**
< 1/8 **BROOKLYN, NY 11232** **ECHO**
0.018 mi.
97 ft. **Site 24 of 36 in cluster A**

Relative:
Higher

Actual:
53 ft.

RCRA Listings:

Date Form Received by Agency:	20150319
Handler Name:	Con Edison
Handler Address:	40TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004754115
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported

CON EDISON (Continued) **1018280524**

State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150319
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON (Continued) **1018280524**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150319
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067708109

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280524
Registry ID:	110067708109
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067708109
Name:	CON EDISON
Address:	415 40TH ST
City,State,Zip:	BROOKLYN, NY 11232

A25 **CON EDISON - SERVICE BOX 49283** **RCRA-LQG** **1016967090**
ENE **415 40 ST** **NY MANIFEST** **NYP004404968**
< 1/8 **BROOKLYN, NY 11232**
0.018 mi.
97 ft. **Site 25 of 36 in cluster A**

Relative: **Higher**

Actual: **53 ft.**

RCRA Listings:

Date Form Received by Agency:	20140327
Handler Name:	Con Edison - Service Box 49283
Handler Address:	40 ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004404968
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	518-473-8034
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON - SERVICE BOX 49283 (Continued) **1016967090**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20131212
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20131212
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140327
Handler Name:	CON EDISON - SERVICE BOX 49283
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny

CON EDISON - SERVICE BOX 49283 (Continued) **1016967090**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004404968
Country:	USA
Name:	CON EDISON
Address:	415 40 ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	415 40TH ST
Location Address 2:	SB49283
Location City,State,Zip:	BROOKLYN, NY 11221
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	12/12/2013
Trans1 Recv Date:	12/12/2013
Trans2 Recv Date:	Not reported

CON EDISON - SERVICE BOX 49283 (Continued) **1016967090**

TSD Site Recv Date:	12/12/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004404968
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002300780GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	300
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

A26 **CON EDISON** **NY MANIFEST** **S117742122**
ENE **415 40TH ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.018 mi.
97 ft. **Site 26 of 36 in cluster A**

Relative: NY MANIFEST:
Higher

Actual: EPA ID:	NYP004754115
53 ft. Country:	USA
Name:	CON EDISON
Address:	415 40TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	F/O 415 40 ST
Location Address 2:	SB49283
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported

CON EDISON (Continued) **S117742122**

Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 03/19/2015
Trans1 Recv Date: 03/19/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/19/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004754115
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014091096JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 500
Units: Pounds

CON EDISON (Continued) **S117742122**

Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

A27 **CON EDISON** **NJ MANIFEST** **S120669260**
ENE **415 40TH ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.018 mi.
97 ft. **Site 27 of 36 in cluster A**

Relative:
Higher

Actual:
53 ft.

NJ MANIFEST:

EPA ID:	NYP004754115
Name:	CON EDISON
Address:	415 40TH ST
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004754115
Manifest Number:	014091096JJK
Date Shipped:	3/19/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

CON EDISON (Continued) **S120669260**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

A28 **NYC DEPT OF EDUCATION - I S 136K** **RCRA-SQG** **1016455464**
NNW **4004 4TH AVE** **FINDS** **NYR000205674**
< 1/8 **BROOKLYN, NY 11232** **ECHO**
0.019 mi.
100 ft. **Site 28 of 36 in cluster A**

Relative:
Lower

Actual:
46 ft.

RCRA Listings:

Date Form Received by Agency:	20131126
Handler Name:	Nyc Dept Of Education - I S 136k
Handler Address:	4TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYR000205674
Contact Name:	ALEXANDER LEMPERT
Contact Address:	THOMSON AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-472-8501
Contact Fax:	718-472-8500
Contact Email:	ALEMPERT@NYCSCA.ORG
Contact Title:	DIRECTOR
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	THOMSON AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Nyc Dept Of Education
Owner Type:	Municipal
Operator Name:	Nyc Dept Of School Facilities
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No

NYC DEPT OF EDUCATION - I S 136K (Continued) **1016455464**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150324
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYC DEPT OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	19010115
Date Ended Current:	Not reported
Owner/Operator Address:	30-30 THOMSON AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-472-8501
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NYC DEPT OF SCHOOL FACILITIES	
Legal Status:	Municipal
Date Became Current:	19010115
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported

NYC DEPT OF EDUCATION - I S 136K (Continued) **1016455464**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20131126
Handler Name: NYC DEPT OF EDUCATION - I S 136K
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 61111
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110056505857

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016455464
Registry ID: 110056505857
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110056505857
Name: NYC DEPT OF EDUCATION - I S 136K
Address: 4004 4TH AVE
City,State,Zip: BROOKLYN, NY 11232

A29
WSW
< 1/8
0.027 mi.
141 ft.

ROADWAY
4TH AVE & 41ST STREET
BROOKLYN, NY

Site 29 of 36 in cluster A

NY Spills **S108956927**
N/A

Relative:
Higher

Actual:
53 ft.

SPILLS:

Name:	ROADWAY
Address:	4TH AVE & 41ST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0709105 / 2007-11-21
Facility ID:	0709105
Facility Type:	ER
DER Facility ID:	339733
Site ID:	390128
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2007-11-21
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	2007-11-21
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-11-21
Spill Record Last Update:	2007-11-21
Spiller Name:	VINCENT MORREALE
Spiller Company:	MAINES PAPER AND FOODS TR
Spiller Address:	4TH AVE
Spiller Company:	001
Contact Name:	VINCENT MORREALE
DEC Memo:	AMOUNT IS BETWEEN 75-100 GALLONS IN ESTIMATION; IN FRONT OF THE BURGER KING ON 4TH; DRIVER SAYS IT JUST STARTED LEAKING BUT REPAIR TEAM SAID IT APPEARS THAT HE HIT SOMETHING SO CAUSE IS UNKOWN AT THIS TIME; CLEAN UP CREW IN ROUTE; SPILL KIT WAS USED AS WELL AS BUCKETS TO CONTAIN - UNSURE IF SPILL IS FULLY CONTAINED;
Remarks:	11/21/07-Hiralkumar Patel. visited site. met Vincent Morreale from Maines paper & Food service. also met truck driver. as per driver, he arrived at Burger King for delivery at around 4 AM. and after delivery while coming out from parking lot, customer noticed leak from one of the saddle tank. driver stopped truck and collected remaining oil from tank into garbage cans/buckets. some oil reached to sewer drain at intersection of 4th ave and 41st street. as per Vincent, NYC DEP has been notified. asked Vincent to clean asphalt surface in parking lot as well as roadways. also asked him to clean sewer as had odor inside it. Vincent will contact DEP regarding sewer cleanup. Vincent Morreale Maines Paper & Food Service - NY Metro, Inc. 105 Sea Lane Farmingdale, NY 11735 PH. (631) 501-8307 Fax (631)

ROADWAY (Continued) **S108956927**

753-6613 email: vincent.morreale@maines.net no soil/groundwater affected. case closed.

All Materials:

Site ID:	390128
Operable Unit ID:	1147241
Operable Unit:	01
Material ID:	2137642
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A30 **MANHOLE 45501** **NY Spills** **S104880204**
WSW **4TH AVE/41ST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
141 ft. **Site 30 of 36 in cluster A**

Relative:
Higher

Actual:
53 ft.

SPILLS:

Name:	MANHOLE 45501
Address:	4TH AVE/41ST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0009003 / 2001-12-21
Facility ID:	0009003
Facility Type:	ER
DER Facility ID:	222190
Site ID:	273030
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-11-03
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2000-11-03
CID:	389
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-03
Spill Record Last Update:	2001-12-21
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001

MANHOLE 45501 (Continued) **S104880204**

Contact Name: CALLER
DEC Memo: caller reporting a spill due to equipment failure coned#134234 samples taken clean up pending lab
results no sewers or waterways effected
Remarks: Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY Con Ed e2mis #134234 Notes: 11-3-00 1/2gal dielectric fluid in manhole 45501. Leaked from uncapped feeder onto dirt. Also in structure there are two other uncapped feeders. Solid sample taken. Env Ops says truck may be contaminated with what first appeared to be asphalt residue. Quarantined truck at 3rd Ave Yard. 11-3-00 1700hrs Found uncapped end on north wall by floor. Took liquid sample. 11-4-00 LSN 00-10563 <1ppm PCB 11-9-00 No sump in structure. Cleanup complete. 11-9-00 Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. Source of leak was cut cable that was repaire by Underground.

All Materials:
Site ID: 273030
Operable Unit ID: 829603
Operable Unit: 01
Material ID: 546507
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

A31 **MANHOLE #4049** **NY Spills** **S106469195**
WSW **SW CORN. 41ST & 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
141 ft. **Site 31 of 36 in cluster A**

Relative: Higher
Actual: 53 ft.

SPILLS:
Name: MANHOLE #4049
Address: SW CORN. 41ST & 4TH AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0401833 / 2004-09-07
Facility ID: 0401833
Facility Type: ER
DER Facility ID: 83347
Site ID: 92945
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2004-05-18
Investigator: SKARAKHA
Referred To: Not reported
Reported to Dept: 2004-05-19
CID: 407
Water Affected: Not reported
Spill Source: Commercial/Industrial

MANHOLE #4049 (Continued) **S106469195**

Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-05-19
Spill Record Last Update:	2004-09-07
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	999
Contact Name:	ERT DESK
DEC Memo:	Amount: 1 pint Coming off 24 hour program, due to traffic unable to clean up at this time.
Remarks:	e2mis 153458 DELAROSA # 1955 FLUSH DEPT REPORTS FOUND 1 PINT DILECTRIC FLUID LEAKED FROM CABLE IN M- 4049. NO WATER IN STRUCTURE. SAW A 3C CABLE LEAKING FROM CAP. #9 ON LOCATION AND WILL CAP CABLE. NO FIRE OR SMOKE. IT APPEARS TO BE CONTAINED TO STRUCTURE. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. TOOK SAMPLE ON A 4 TO 6 HOUR PRIORITY TURNAROUND. CLEANUP PENDING RESULTS. PLACED ENVIROMENTAL STOP TAG #38217. CHAIN OF CUSTODY # IS DD09131. UPDATE: THIS WAS FIRST PUT INTO QUEENS SITE #15345 VOIDED OUT. LAB SEQ NO. 04-03836-001 PCB RESULTS < 1.0 PPM Update 5/20/04 0215hrs Kevin Hufford. env ops mech reports double washed structure with biogen 760. No leaking co. equipment found. No earthen sump. Removed env. stop tag. Cleanup completed.

All Materials:

Site ID:	92945
Operable Unit ID:	885719
Operable Unit:	01
Material ID:	493027
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

A32 **MANHOLE 73170** **NY Spills** **S108057543**
WSW **4TH AVE AND 41ST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.027 mi.
141 ft. **Site 32 of 36 in cluster A**

Relative: **Higher**

Actual: **53 ft.**

SPILLS:

Name:	MANHOLE 73170
Address:	4TH AVE AND 41ST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0602997 / 2006-10-05
Facility ID:	0602997
Facility Type:	ER

MANHOLE 73170 (Continued) **S108057543**

DER Facility ID:	315717
Site ID:	365592
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-06-18
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2006-06-18
CID:	62
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-18
Spill Record Last Update:	2006-10-05
Spiller Name:	ERTS
Spiller Company:	MANHOLE 73170
Spiller Address:	4TH AVE AND 41ST ST
Spiller Company:	001
Contact Name:	ERTS
DEC Memo:	6 oz unknown oil, clean up pending test results.
Remarks:	10/05/06 - See e-docs for Con Ed report detailing cleanup and closure. Con Ed Emis no. 200641 - see eDocs. (JHO)

All Materials:

Site ID:	365592
Operable Unit ID:	1123606
Operable Unit:	01
Material ID:	2113073
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A33 **NY Spills** **S106969908**
SE **444 40 STREET** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.033 mi.
173 ft. **Site 33 of 36 in cluster A**

Relative:
Higher

Actual:
64 ft.

SPILLS:

Name:	MANHOLE #49287
Address:	444 40 STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0504791 / 2005-09-26

(Continued) **S106969908**

Facility ID:	0504791
Facility Type:	ER
DER Facility ID:	296134
Site ID:	349701
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-07-20
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2005-07-21
CID:	444
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-21
Spill Record Last Update:	2005-09-26
Spiller Name:	ERT DESK'
Spiller Company:	MANHOLE #49287
Spiller Address:	444/40TH STREET
Spiller Company:	001
Contact Name:	ERT DESK'
DEC Memo:	1 QUART ON 100 GALLONS OF WATER: CANT FINISH CLEANUP DUE TO A CAR PARKED ON MANHOLE: NO TO 5 QUESTIONS; CONED # 159877
Remarks:	e2mis no 159877 J. DELAROSA #19655 MECH A ENV OPS REPORTS FINDING APPROX 1 QT OF UNKNOWN OIL ON APPROX 100 GALS OF WATER IN M49287. NO SEWERS, WATERWAYS, OR PRIVATE PROPERTY AFFECTED. THE SOURCE AND CAUSE OF THE SPILL IS UNKNOWN, HOWEVER THERE IS A BLOWN JOINT IN THE STRUCTURE. THERE WERE NO SUBSTANTIAL CRACKS IN THE STRUCTURE AND THE STANDING WATER HAD NO MOVEMENT. THE EXISTENCE OF ANY SEWER CONNECTIONS, SUMPS, OR DRAINS COULD NOT BE VERIFIED AT THIS TIME. ENV STOP TAG# 46866 WAS PLACED AND ONE LIQUID SAMPLE TAKEN CLEANUP WILL BEGIN USING THE VACTOR AND THEN WAITING FOR LAB RESULTS. UPDATE 7-20-05 14:15HRS AS PER A. WALKER, J. DELAROSA ENV OPS CONTAMINATED VACTOR TRUCK 60571, REMOVED BOTH SOLID DEBRIS. DOUBLE WASHED STRUCTURE, WILL CHECK DIRT SUMP AT ANOTHER TIME. ALSO ALL LIQUIDS WERE REMOVED. VACTOR WILL REMAIN ON LOCATION UNTIL RESULTS COME BACK. 7/20/05 2100HRS LAB RESULT RETURNED < 1.PPM LSN-05-07437-001 7/21/05 0200HRS Update for F/O 444 40 St. (Inc #159877): MH 49287 made water prior to UG working in the hole. 100 gals. of water were taken out of the structure by Astoria Tanker. Results of the structure came back as < 1 PPM PCB, and as a Water Grab. Because this result came back as a Water result, the directive was made to take another sample of the sludge in the vactor for PCB and a note was made on the sample request to sample as a solid, do not extract oil. Because this incident is pending sample results, MH 49287 and Vactor 60571 will be treated as 50-499 until results of this last sample is received. Vactor 60571 will remain on location until these final sample results are received. 7/21/2005 07:52 HRS. -- RECEIVED PCB RESULTS < 1.0 PPM,

(Continued) **S106969908**

LAB SEQ # 05-07472-001, MATRIX: SOLID GRAB, DESCRIPTION: SLUDGE FROM VACTOR 60571. 7/21/2005 10:55 HRS. -- BROOKLYN ENV OPS. O/S A. WALKER REPORTS HE INSPECTED VACTOR 60571 AND FOUND NO FREE FLOWING OIL IN VEHICLE. TRUCK WILL BE DUMPED. -- W.W. #17344 -- 8/02/2005 13:13 HRS.
-- D. BANKHEAD OF BROOKLYN ENV OPS REPORTS HE & J. CUADRADO DOUBLE WASHED STRUCTURE, FOUND SUMP SEALED AND REMOVED ENV STOP TAG 46866. CLEANUP COMPLETE AS OF THIS TIME. BKLYN ENV OPS O/S E. WILLIAMS WAS NOTIFIED. -- W.W. #17344 -- Closed. 9-26-05. GB.

All Materials:

Site ID:	349701
Operable Unit ID:	1107290
Operable Unit:	01
Material ID:	2097182
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	444 40 STREET
City,State,Zip:	BROOKLYN, NY 11232
Latitude:	40.6513313
Longitude:	-74.0059823
Type Of Ownership Code:	Not reported
Owner Name:	THERMOS, JOHN
Borough:	BK
Tax Block:	714
Tax Lot:	19
Community District:	307
Census Tract 2020:	3008200
Census Block 2020:	30082001000
Census Tract 2010:	82
Census Block 2010:	1000
School District:	15
City Council District:	38
Fire Company:	E228
Police Precinct:	72
Health Center District:	39
Health Area:	6600
Sanitation District Boro:	3
Sanitation District Number:	07
Sanitation Subsection:	2E
Zoning District 1:	R6B: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported

(Continued) **S106969908**

Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	C2: WALK UP APARTMENTS - Five to Six Families
Land Use Category:	Multi-Family Walk-Up Buildings
Number Of Easements:	0
Lot Area:	3339
Total Building Floor Area:	5541
Commercial Floor Area:	0
Residential Floor Area:	5541
Office Floor Area:	0
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	3.0000000
Residential Units:	6
Total Units:	6
Lot Frontage:	33.3300000
Lot Depth:	100.1700000
Building Frontage:	33.3300000
Building Depth:	68.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	5
Assessed Land Value:	7650.00000
Assessed Total Value:	555300.00000
Exempt Total Value:	0.00000
Year Built:	1914
Year Altered 1:	0
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.66000000000
Maximum Allowable Residential Far:	2.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	2.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3007140019.00000000
Condominium Number:	Not reported
Census Tract 2:	0082
X Coordinate:	982590
Y Coordinate:	176574
Zoning Map #:	16b
Zoning Map Code:	Not reported
Sanborn Map #:	306A021
Tax Map #:	30303
E-designation Number:	Not reported
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1

(Continued) **S106969908**

2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	23v1.1
Changed By DCP:	Not reported

A34 **CON EDISON** **NY MANIFEST** **S117738817**
NE **F/O 3907 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11234**
0.034 mi.
182 ft. **Site 34 of 36 in cluster A**

Relative: **Lower**
Actual: **48 ft.**

NY MANIFEST:

EPA ID:	NYP004718946
Country:	USA
Name:	CON EDISON
Address:	F/O 3907 4TH AVE
Address 2:	SB 62424
City,State,Zip:	BROOKLYN, NY 11234
Zip 4:	Not reported
Location Address 1:	F/O 3907 4TH AVE
Location Address 2:	SB 62424
Location City,State,Zip:	BROOKLYN, NY 11234
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	01/26/2015
Trans1 Recv Date:	01/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004718946
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620805GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

CON EDISON (Continued) **S117738817**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	40
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

A35 **LOT 42,TAXBLOCK 708** **NY E DESIGNATION S110092243**
NNW **3918 4 AVENUE** **NY NYC LAND USE N/A**
< 1/8 **BROOKLYN, NY**
0.036 mi.
188 ft. **Site 35 of 36 in cluster A**

Relative: **Lower**
Actual: **42 ft.**

E DESIGNATION:

Name:	LOT 42,TAXBLOCK 708
Address:	3918 4 AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	42
Tax Block:	708
Borough Code:	Not reported
E-No:	E-236
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	09DCP075K
Ulurp Number:	090387ZMK
Zoning Map No:	16b 16d 22a 22c
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

Name:	Not reported
Address:	3918 4 AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Latitude:	40.6523990
Longitude:	-74.0069050

LOT 42,TAXBLOCK 708 (Continued) **S110092243**

Type Of Ownership Code:	Not reported
Owner Name:	PIZZO 3918 LLC
Borough:	BK
Tax Block:	708
Tax Lot:	42
Community District:	307
Census Tract 2020:	3008400
Census Block 2020:	30084002003
Census Tract 2010:	84
Census Block 2010:	2003
School District:	15
City Council District:	38
Fire Company:	E228
Police Precinct:	72
Health Center District:	39
Health Area:	4400
Sanitation District Boro:	3
Sanitation District Number:	07
Sanitation Subsection:	2E
Zoning District 1:	R7A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	K1: STORE BUILDINGS (TAXPAYERS INCLUDED) - One Story Retail Building
Land Use Category:	Commercial & Office Buildings
Number Of Easements:	0
Lot Area:	7517
Total Building Floor Area:	5250
Commercial Floor Area:	640
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	640
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	75.1700000
Lot Depth:	100.0000000
Building Frontage:	75.0000000
Building Depth:	70.0000000
Extension Code:	N
Proximity Code:	0
Irregular Lot Code:	N
Lot Type:	5
Basement Type/Grade:	0

LOT 42,TAXBLOCK 708 (Continued) **S110092243**

Assessed Land Value:	152100.00000
Assessed Total Value:	335250.00000
Exempt Total Value:	0.00000
Year Built:	1954
Year Altered 1:	1976
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.70000000000
Maximum Allowable Residential Far:	4.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3007080042.00000000
Condominium Number:	Not reported
Census Tract 2:	0084
X Coordinate:	982334
Y Coordinate:	176963
Zoning Map #:	16b
Zoning Map Code:	Not reported
Sanborn Map #:	306A022
Tax Map #:	30303
E-designation Number:	E-236
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	23v1.1
Changed By DCP:	Not reported

A36 **LOT 6,TAXBLOCK 719** **NY E DESIGNATION** **S110092266**
SW **4111 4 AVENUE** **NY NYC LAND USE** **N/A**
< 1/8 **BROOKLYN, NY**
0.039 mi.
208 ft. **Site 36 of 36 in cluster A**

Relative:
Higher

Actual:
59 ft.

E DESIGNATION:

Name:	LOT 6,TAXBLOCK 719
Address:	4111 4 AVENUE
City,State,Zip:	BROOKLYN, NY
Tax Lot(s):	6
Tax Block:	719
Borough Code:	Not reported
E-No:	E-236
Effective Date:	Not reported
Satisfaction Date:	Not reported
Ceqr Number:	09DCP075K
Ulurp Number:	090387ZMK
Zoning Map No:	16b 16d 22a 22c
Description:	Air Quality - #2 Fuel Oil or Natural Gas for heating, ventilating and air conditioning systems;Exhaust stack location limitations;Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

NYC LAND USE:

LOT 6,TAXBLOCK 719 (Continued) **S110092266**

Name:	Not reported
Address:	4111 4 AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Latitude:	40.6511556
Longitude:	-74.0072076
Type Of Ownership Code:	Not reported
Owner Name:	41ST STREET REALTY LLC
Borough:	BK
Tax Block:	719
Tax Lot:	6
Community District:	307
Census Tract 2020:	3008200
Census Block 2020:	30082001001
Census Tract 2010:	82
Census Block 2010:	1001
School District:	15
City Council District:	38
Fire Company:	E228
Police Precinct:	72
Health Center District:	39
Health Area:	6600
Sanitation District Boro:	3
Sanitation District Number:	07
Sanitation Subsection:	2E
Zoning District 1:	R7A: Residential Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	C2-4
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	K5: STORE BUILDINGS (TAXPAYERS INCLUDED) - Stand Alone Food Establishment
Land Use Category:	Commercial & Office Buildings
Number Of Easements:	0
Lot Area:	10017
Total Building Floor Area:	2200
Commercial Floor Area:	2200
Residential Floor Area:	0
Office Floor Area:	0
Retail Floor Area:	2200
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1
Number Of Floors:	1.0000000
Residential Units:	0
Total Units:	1
Lot Frontage:	100.1700000
Lot Depth:	100.0000000
Building Frontage:	26.0000000

LOT 6,TAXBLOCK 719 (Continued) **S110092266**

Building Depth:	76.0000000
Extension Code:	N
Proximity Code:	1
Irregular Lot Code:	N
Lot Type:	3
Basement Type/Grade:	0
Assessed Land Value:	135450.00000
Assessed Total Value:	817200.00000
Exempt Total Value:	45000.00000
Year Built:	1999
Year Altered 1:	2020
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	0.22000000000
Maximum Allowable Residential Far:	4.00000000000
Maximum Allowable Commercial Far:	0.00000000000
Maximum Allowable Community Facility Far:	4.00000000000
Boro Code:	3
Borough, Tax Block and Lot:	3007190006.00000000
Condominium Number:	Not reported
Census Tract 2:	0082
X Coordinate:	982250
Y Coordinate:	176510
Zoning Map #:	16b
Zoning Map Code:	Not reported
Sanborn Map #:	306A021
Tax Map #:	30303
E-designation Number:	E-236
Apportionment BBL:	Not reported
Apportionment Date:	Not reported
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	23v1.1
Changed By DCP:	Not reported

B37 **CON EDISON** **RCRA NonGen / NLR** **1019904094**
South **424 41ST ST** **FINDS** **NYP004793634**
< 1/8 **BROOKLYN, NY 11232** **ECHO**
0.039 mi.
208 ft. **Site 1 of 4 in cluster B**

Relative:
Higher

Actual:
67 ft.

RCRA Listings:

Date Form Received by Agency:	20150612
Handler Name:	Con Edison
Handler Address:	41ST ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004793634
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private

CON EDISON (Continued) **1019904094**

Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150612

CON EDISON (Continued) **1019904094**

Handler Name:	CON EDISON
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150612
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069689046

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019904094
Registry ID:	110069689046
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069689046
Name:	CON EDISON

CON EDISON (Continued) **1019904094**

Address: 424 41ST ST
City,State,Zip: BROOKLYN, NY 11232

B38 **CON EDISON** **NY MANIFEST** **S119075848**
South **424 41ST ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.039 mi.
208 ft. **Site 2 of 4 in cluster B**

Relative:
Higher

Actual:
67 ft.

NY MANIFEST:

EPA ID:	NYP004793634
Country:	USA
Name:	CON EDISON
Address:	424 41ST ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	424 41 ST
Location Address 2:	SB 48253
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	06/12/2015
Trans1 Recv Date:	06/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/15/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004793634
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620010GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S119075848**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	200
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

B39 **CON EDISON** **NJ MANIFEST** **S120672736**
South **424 41ST ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.039 mi.
208 ft. **Site 3 of 4 in cluster B**

Relative:
Higher

Actual:
67 ft.

NJ MANIFEST:

EPA ID:	NYP004793634
Name:	CON EDISON
Address:	424 41ST ST
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004793634
Manifest Number:	002620010GBF
Date Shipped:	6/12/2015

CON EDISON (Continued) **S120672736**

TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

C40 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243790**
ESE **MH49287-444 40TH ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.041 mi.
219 ft. **Site 1 of 6 in cluster C**

Relative: NY MANIFEST:
Higher

Actual: EPA ID:	NYP004133674
65 ft. Country:	USA
Name:	CONSOLIDATED EDISON
Address:	MH49287-444 40TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY
Zip 4:	Not reported
Location Address 1:	MH49287-444 40TH ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY
Location Zip 4:	Not reported
Facility Status:	Not reported

CONSOLIDATED EDISON (Continued) **1009243790**

Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: NYE0629586
Manifest Status: Not reported
Trans1 State ID: 86110JM
Year: 2005
Trans2 State ID: Not reported
Generator Ship Date: 07/20/2005
Trans1 Recv Date: 07/20/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/21/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004133674
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B002
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00409
Units: Kilograms
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 01.00

Document ID: NYE0591012
Manifest Status: Not reported

CONSOLIDATED EDISON (Continued) **1009243790**

Trans1 State ID:	12446JT
Year:	2005
Trans2 State ID:	Not reported
Generator Ship Date:	07/20/2005
Trans1 Recv Date:	07/20/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/22/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004133674
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00030
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

D41 **366 41ST ST** **NY AST** **U004077929**
West **366 41ST ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.048 mi.
254 ft. **Site 1 of 9 in cluster D**

Relative: AST:
Lower

Name:	366 41ST ST
Address:	366 41ST ST
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-360007
Program Type:	PBS
UTM X:	583891.44224
UTM Y:	4500558.26802
Expiration Date:	12/14/2024

Actual:
50 ft.

366 41ST ST (Continued) **U004077929**

Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 18120
Affiliation Type: Facility Owner
Company Name: GIA PROPERTY LLC
Contact Type: OFFICER
Contact Name: ALESSANDRO PIROZZI
Address1: 122 76TH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11209
Country Code: 001
Phone: (718) 857-7920
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2006-03-28

Site Id: 18120
Affiliation Type: Mail Contact
Company Name: GIA PROPERTY LLC
Contact Type: Not reported
Contact Name: ALEX PIROZZI
Address1: 122 76TH STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11209
Country Code: 001
Phone: (718) 857-7920
EMail: ALEXXPIROZZI@GMAIL.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2019-10-03

Site Id: 18120
Affiliation Type: Facility Operator
Company Name: 366 41ST ST
Contact Type: Not reported
Contact Name: ALEX PIROZZI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 294-0244
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2006-03-28

Site Id: 18120
Affiliation Type: Emergency Contact
Company Name: GIA PROPERTY LLC
Contact Type: Not reported

366 41ST ST (Continued) **U004077929**

Contact Name:	ALEX PRIOZZI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 294-0244
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2006-03-28

Tank Info:

Tank Number:	001
Tank Id:	20531
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	I04 - Overfill - Product Level Gauge (A/G)
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1980
Capacity Gallons:	5000
Tightness Test Method:	03
Date Test:	11/01/1998
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

E42 **MANHOLE 73167** **NY Spills** **S106699316**
NNE **39TH STREET & 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.050 mi.
264 ft. **Site 1 of 12 in cluster E**

Relative: **Lower**

Actual: **46 ft.**

SPILLS:

Name:	MANHOLE 73167
Address:	39TH STREET & 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0406654 / 2004-09-21
Facility ID:	0406654
Facility Type:	ER
DER Facility ID:	89704
Site ID:	101225
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-09-16
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2004-09-16
CID:	74
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-09-16
Spill Record Last Update:	2004-09-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT DESK
DEC Memo:	1/2 pint of unknown oil on 20 gallons of water. Cleanup pending - found an earthen sump. Ref. 155404
	Not reported
Remarks:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis no. 155404: APPROX. 1/2 pt OF UNKNOWN OIL ON APPROX. 20 GAL'S OF WATER. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. 1 LIQ. SAMPLE TAKEN FROM SPILL. Lab Sequence Number: 04-07355-001 PCB <1 ppm. UPDATE: 16-SEP-2004 2300HRS BREAKENRIDGE REPORTS FOUND EATHREN SUMP IN STRUCTURE. UPDATE: 16-SEP-2004 2310HRS BREAKENRIDGE REPORTS DOUBLE WASHED STRUCTURE WITH BIO GEN 760. REMOVED ALL LIQUIDS. CEMENTED SUMP.

All Materials:

Site ID:	101225
Operable Unit ID:	889282
Operable Unit:	01
Material ID:	487847
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported

MANHOLE 73167 (Continued) **S106699316**

Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

E43 **VAULT 6035** **NY Spills** **S104952324**
NNE **39TH STREET & 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.050 mi.
264 ft. **Site 2 of 12 in cluster E**

Relative:
Lower

Actual:
46 ft.

SPILLS:

Name:	VAULT 6035
Address:	39TH STREET & 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0011492 / 2001-06-01
Facility ID:	0011492
Facility Type:	ER
DER Facility ID:	89704
Site ID:	141214
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-01-24
Investigator:	OKWUOHA
Referred To:	Not reported
Reported to Dept:	2001-01-24
CID:	270
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-24
Spill Record Last Update:	2003-11-10
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CALLER
DEC Memo:	sample taken clean up pending 135204
Remarks:	Not reported

All Materials:

Site ID:	141214
Operable Unit ID:	832996
Operable Unit:	01
Material ID:	541801
Material Code:	0066A
Material Name:	unknown petroleum

VAULT 6035 (Continued) **S104952324**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

E44 **SERVICE VAULT 6035** **NY Spills** **S104952173**
NNE **39TH ST/4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.050 mi.
264 ft. **Site 3 of 12 in cluster E**

Relative: SPILLS:
Lower

Actual:
46 ft.

Name:	SERVICE VAULT 6035
Address:	39TH ST/4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0011269 / 2001-04-18
Facility ID:	0011269
Facility Type:	ER
DER Facility ID:	184179
Site ID:	222736
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-01-16
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2001-01-16
CID:	382
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-16
Spill Record Last Update:	2001-08-13
Spiller Name:	SAME
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	PETER MCQUIRE
DEC Memo:	INVESTIGATION OF SPILL UNDERWAY. OIL POSSIBLY ON FLOOR OF VAULT. CLEAN UP PENDING. CON ED 135-122
Remarks:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL DEC INSPECTOR'S NOTES No sump or sewer connection found, all oil in debris. 1-18-01 Spoke with Steve Zalloughi 100 gals. drained from transformer amount released down to 165gals. CON ED E2MIS REPORT 1-16-01 When dip stick was checked no oil was found, at the time a samll stream is flowing from rust hole in unit onto soil. No water in VS. No known sewer connection also no historical record

SERVICE VAULT 6035 (Continued) **S104952173**

of sewer connection. 1 liquid sample taken from source. Equipment history- Fluid capacity 265gals, 10ppm PCB. 12:43 Need to check if soil bottom sump in VS Transformer drained and removed from structure 100gals. of oil removed from transformer. 165 gals. not accounted for. 20:40hrs. 4 barrels of solid waste were removed. Sump was found cemented, no other drains found in vault. Vault double washed with Bio Gen 760 wash water was pumped into tanker. Cleanup is complete. 1-17-01 0630hrs. Lab Seq# 01-00451 6ppm

All Materials:

Site ID:	222736
Operable Unit ID:	832658
Operable Unit:	01
Material ID:	541591
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	265.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

E45 **V# VS6058** **NY Spills** **S103937373**
NNE **39TH STREET & 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.055 mi.
289 ft. **Site 4 of 12 in cluster E**

Relative: **Lower**

Actual: **44 ft.**

SPILLS:

Name:	V# VS6058
Address:	39TH STREET & 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9901850 / 1999-10-26
Facility ID:	9901850
Facility Type:	ER
DER Facility ID:	89704
Site ID:	299331
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1999-05-17
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1999-05-17
CID:	366
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

V# VS6058 (Continued) **S103937373**

Date Entered In Computer:	1999-05-17
Spill Record Last Update:	2000-06-13
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	CALLER REPORTING THAT PRODUCT FOUND IN VAULT. FEEDER NEEDS TO BE DISCONNECTED BEFORE SAMPLES CAN BE TAKEN. CON ED #124937.
Remarks:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT Con ed e2mis notes: Approx 5 gallons of oil leaking from bottom of VS6058, onto 4 of dirt on concrete floor, records shows 10ppm. Loss of 15 gallons of transf. oil. Also taken sample with 4-6 hr. priority. Partial cleanup completed pending. Reports 9ppm cleanup complete. DEC Inspector Notes: 8/26/99: emailed ERT's for more infor on cleanup and transformer.

All Materials:

Site ID:	299331
Operable Unit ID:	1076629
Operable Unit:	01
Material ID:	305376
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

F46 **FRED ALIMONDA** **UST FINDER** **1028573257**
NNW **357 40TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.057 mi.
300 ft. **Site 1 of 6 in cluster F**

Relative: **Lower**
Actual: **38 ft.**

UST FINDER:

Object ID:	294958
Facility ID:	NY25500
Name:	FRED ALIMONDA
Address:	357 40TH STREET
City,State,Zip:	BROOKLYN, NY 11233
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	9835
Private Wells 1500ft:	7
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported

FRED ALIMONDA (Continued) **1028573257**

SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-74.0072959999999
Y Coord:	40.6523120000001
Latitude:	40.652312
Longitude:	-74.007296

UST FINDER:

Object ID:	1223902
Facility ID:	NY25500
Tank ID:	NY32647
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	1500
Substances:	Not reported
Tank Wall Type:	Not reported

F47 **FRED ALIMONDA** **NY UST** **U003397274**
NNW **357 40TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.057 mi.
300 ft. **Site 2 of 6 in cluster F**

Relative: **Lower**

Actual: **38 ft.**

UST:

Name:	FRED ALIMONDA
Address:	357 40TH STREET
City,State,Zip:	BROOKLYN, NY 11232
Id/Status:	2-603586 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583923.21568
UTM Y:	4500661.48832
Site Type:	Private Residence

Affiliation Records:

Site Id:	25500
Affiliation Type:	Facility Owner
Company Name:	ANNA ALIMONDA
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	357 40TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001

FRED ALIMONDA (Continued) **U003397274**

Phone:	(718) 768-2240
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2016-11-14

Site Id:	25500
Affiliation Type:	Mail Contact
Company Name:	MARGIE ALIMONDA
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	357 40TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11233
Country Code:	001
Phone:	(718) 768-2240
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25500
Affiliation Type:	Facility Operator
Company Name:	FRED ALIMONDA
Contact Type:	Not reported
Contact Name:	MARGIE ALIMONDA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 768-2240
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25500
Affiliation Type:	Emergency Contact
Company Name:	ANNA ALIMONDA
Contact Type:	Not reported
Contact Name:	MARGIE ALIMONDA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 768-2240
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

FRED ALIMONDA (Continued) **U003397274**

Tank Info:

Tank Number:	001
Tank ID:	54881
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1500
Install Date:	Not reported
Date Tank Closed:	06/23/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	03
Date Test:	09/01/1998
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

F48 **FRED ALIMONDA** **NY LTANKS** **S104619550**
NNW **357 40TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11233**
0.057 mi.
300 ft. **Site 3 of 6 in cluster F**

Relative: **Lower**

Actual: **38 ft.**

LTANKS:

Name:	SPILL NUMBER 9803014
Address:	357 40TH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9803014 / 2003-03-03
Facility ID:	9803014
Site ID:	79043
Spill Date:	1998-06-01
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1998-06-08
CID:	369
Water Affected:	Not reported
Spill Notifier:	Other

FRED ALIMONDA (Continued) **S104619550**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-06-08
Spill Record Last Update:	2003-03-03
Spiller Name:	ANNA ALIMONDA
Spiller Company:	Not reported
Spiller Address:	357 40TH ST
Spiller County:	001
Spiller Contact:	ANNA ALIMONDA
Spiller Phone:	(718) 768-2240
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	73493
DEC Memo:	Not reported
Remarks:	tank failure.

All Materials:

Site ID:	79043
Operable Unit ID:	1063671
Operable Unit:	01
Material ID:	321334
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	FRED ALIMONDA
Address:	357 40TH STREET
City,State,Zip:	BROOKLYN, NY 11233
Spill Number/Closed Date:	0301684 / 2009-09-02
Facility ID:	0301684
Site ID:	288656
Spill Date:	2003-05-16
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	VSZHUNE
Referred To:	Not reported
Reported to Dept:	2003-05-16
CID:	422
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0

FRED ALIMONDA (Continued) **S104619550**

Date Entered In Computer:	2003-05-16
Spill Record Last Update:	2009-09-02
Spiller Name:	MARGIE ALIMONDA
Spiller Company:	MARGIE ALIMONDA
Spiller Address:	357 40TH STREET
Spiller County:	001
Spiller Contact:	ANNA ALIMONDA
Spiller Phone:	(718) 768-2240
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	25407
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE Site is a 2 Family house in Brooklyn. DEC Sigona sent notice regarding the tank test failure on May 16, 2003. 4/23/2004 Sangesland -another TTF letter sent today 4/30/2004 Sangesland spoke to property owner Margie Alimonda. She said Bayside was hired to close out the buried 1500 gal tank and install a 550 in her garage. Sangesland spoke to Fred Caputo at Bayside (718-946-4000). He said the whole job was contracted out to AL Eastmond. Eastmond was to close out the tank, install the new tank and take care of the PBS paperwork. 11/8/05 Spoke to Margie Alimonda she said Bayside filled in the below ground tank and installed several above ground tanks. She said Bayside was to send in the paperwork. Spoke with a Margie at Bayside now Petco she had no record of work. Gave me name of Phil Tanella their installer in the area of the spill. I callled Tanella and left a message. J Lister 11/9/05 Spoke to employee of Al Eastmond (718-378-7000)who left a message for Renee. JL Open Issues: 1) Review of DEC database shows no PBS was ever filed (for a 1500 gal tank). - Question if this really was a 1500 gal tank on a 2 Family house in Brooklyn. 2) Apparently no soil boring samples were taken. Tank was just closed out and left. 09/6/06- Zhune sent TTF letter to: Fred Alimonda 357 40th Street Brooklyn, NY 11233 Margie Alimonda called to say that she will fax a copy of letter from Eastmond & Sons, Fuel Oil Tank Cleaning. Zhune got the fax but it was not visible. She will send it by mail. Zhune. Margie sent a visible job ticket from A.L.Eastmond. Eastmond close the underground tank. They filled it with sand. They installed 2(275) gallons AST in the basement. Petro tested the tank and failed. 09/02/09-Randy Austin and Zhune review the case and found no evidence that will indicate of petroleum release. Other than that tank test failure. Since tank fail test are no presumption not prove of spill. Therefore spil has been closed.
Remarks:	TANK TEST FAILURE ON 1,500 GALLON UST

All Materials:

Site ID:	288656
Operable Unit ID:	868229
Operable Unit:	01
Material ID:	506175
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

E49 **366 39 REALTY LLC** **NY AST** **A100157633**
North **366 39TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.058 mi.
308 ft. **Site 5 of 12 in cluster E**

Relative:
Lower

Actual:
38 ft.

AST:

Name:	366 39 REALTY LLC
Address:	366 39TH STREET
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-602835
Program Type:	PBS
UTM X:	583975.48829
UTM Y:	4500694.20809
Expiration Date:	12/15/2024
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	24790
Affiliation Type:	Facility Operator
Company Name:	366 39 REALTY LLC
Contact Type:	Not reported
Contact Name:	JOSE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 841-1273
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-01-16

Site Id:	24790
Affiliation Type:	Emergency Contact
Company Name:	366 39 REALTY LLC
Contact Type:	Not reported
Contact Name:	TOMMY MANOUNAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 609-8348
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-01-16

Site Id:	24790
Affiliation Type:	Mail Contact
Company Name:	366 39TH REALTY LLC
Contact Type:	Not reported
Contact Name:	TOMMY MANOUNAS

366 39 REALTY LLC (Continued) **A100157633**

Address1:	509B 39TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(917) 609-8348
EMail:	OFFICE@MANASNY.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-10-22

Site Id:	24790
Affiliation Type:	Facility Owner
Company Name:	366 39 REALTY LLC
Contact Type:	LLC MEMBER
Contact Name:	TOMMY MANOUNAS
Address1:	509B 39TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(917) 609-8348
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-10-22

Tank Info:

Tank Number:	001
Tank Id:	51783
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	F
Install Date:	01/01/1986
Capacity Gallons:	3000

366 39 REALTY LLC (Continued) **A100157633**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

B50 **444 41ST STREET** **NY Spills** **S104495920**
SSE **444 41ST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.061 mi.
321 ft. **Site 4 of 4 in cluster B**

Relative:
Higher

Actual:
78 ft.

SPILLS:

Name:	444 41ST STREET
Address:	444 41ST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9414357 / 2005-07-13
Facility ID:	9414357
Facility Type:	ER
DER Facility ID:	217619
Site ID:	267140
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C1
SWIS:	2401
Spill Date:	1995-01-30
Investigator:	TLDiaz
Referred To:	Not reported
Reported to Dept:	1995-01-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-15
Spill Record Last Update:	2006-02-10
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	UNKNOWN PETROL OOZING OUT OF THE GROUND AT ABOVE LOCATION
Remarks:	7/13/05 - Diaz - Site inspection conducted. Nothing unusual observed other than utility mark outs. It appears that the concrete from the sidewalk up to the residence has been replaced within the last 5 years. All listed phone numbers on spill report are no longer valid.

All Materials:

Site ID:	267140
Operable Unit ID:	1011765

444 41ST STREET (Continued) **S104495920**

Operable Unit:	01
Material ID:	373099
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

C51 **CON EDISON** **NY MANIFEST** **S116043545**
SE **454 40TH ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.064 mi.
338 ft. **Site 2 of 6 in cluster C**

Relative:
Higher

Actual:
73 ft.

NY MANIFEST:

EPA ID:	NYP004399069
Country:	USA
Name:	CON EDISON
Address:	454 40TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	454 40TH ST
Location Address 2:	SB49288
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	12/03/2013
Trans1 Recv Date:	12/03/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004399069

CON EDISON (Continued) **S116043545**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299995GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	40
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

C52 **CON EDISON** **RCRA NonGen / NLR** **1018277465**
SE **454 40TH ST** **FINDS** **NYP004399069**
< 1/8 **BROOKLYN, NY 11232** **ECHO**
0.064 mi.
338 ft. **Site 3 of 6 in cluster C**

Relative:
Higher

Actual:
73 ft.

RCRA Listings:

Date Form Received by Agency:	20131203
Handler Name:	Con Edison
Handler Address:	40TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004399069
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1018277465**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131203
Handler Name:	CON EDISON

CON EDISON (Continued) **1018277465**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131203
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067680389

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018277465
Registry ID:	110067680389
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067680389
Name:	CON EDISON
Address:	454 40TH ST

CON EDISON (Continued) **1018277465**

City,State,Zip: BROOKLYN, NY 11232

D53 **APARTMENT BUILDING** **NY AST** **U003392455**
West **358 41ST STREET** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.067 mi.
354 ft. **Site 2 of 9 in cluster D**

Relative:
Lower

Actual:
45 ft.

AST:

Name:	APARTMENT BUILDING
Address:	358 41ST STREET
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-406112
Program Type:	PBS
UTM X:	583881.15768
UTM Y:	4500571.46540
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	19605
Affiliation Type:	Facility Owner
Company Name:	BEC NEW COMMUNITIES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	541 ATLANTIC AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11217
Country Code:	001
Phone:	(718) 858-8803
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19605
Affiliation Type:	Mail Contact
Company Name:	BEC NEW COMMUNITIES
Contact Type:	Not reported
Contact Name:	WILLIS MCCARTNEY
Address1:	1448 BEDFORD AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11216
Country Code:	001
Phone:	(718) 622-2150
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id: 19605

APARTMENT BUILDING (Continued) **U003392455**

Affiliation Type:	Facility Operator
Company Name:	APARTMENT BUILDING
Contact Type:	Not reported
Contact Name:	MICHAEL SWINT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 858-8802
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	19605
Affiliation Type:	Emergency Contact
Company Name:	BEC NEW COMMUNITIES
Contact Type:	Not reported
Contact Name:	MICHAEL SWINT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 858-8802
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	24641
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	B99 - Tank External Protection - Other
	C01 - Pipe Location - Aboveground
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	F01 - Pipe External Protection - Painted/Asphalt Coating
	I01 - Overfill - Float Vent Valve
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported

APARTMENT BUILDING (Continued) **U003392455**

Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/31/1997
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

E54 **MOBIL S/S F7FYG C&M SERVICE ST** **NY UST** **U001839140**
NE **987-993 4TH AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.069 mi.
362 ft. **Site 6 of 12 in cluster E**

Relative: **Lower**
Actual: **42 ft.**

UST:

Name:	MOBIL S/S F7FYG C&M SERVICE ST
Address:	987-993 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Id/Status:	2-157236 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584056.35844
UTM Y:	4500676.14736
Site Type:	Unknown

Affiliation Records:

Site Id:	5194
Affiliation Type:	Facility Operator
Company Name:	MOBIL S/S F7FYG C&M SERVICE ST
Contact Type:	Not reported
Contact Name:	C MAURIELLO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 438-9583
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	5194
Affiliation Type:	Emergency Contact
Company Name:	MOBIL OIL CORP;ATT:A.J.PRINGLE
Contact Type:	Not reported
Contact Name:	C MAURIELLO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

MOBIL S/S F7FYG C&M SERVICE ST (Continued) **U001839140**

Country Code:	001
Phone:	(718) 438-9583
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	5194
Affiliation Type:	Facility Owner
Company Name:	MOBIL OIL CORP;ATT:A.J.PRINGLE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	3225 GALLOWS RD.; ENV.ENGINEER
Address2:	Not reported
City:	FAIRFAX
State:	VA
Zip Code:	22037
Country Code:	001
Phone:	(703) 849-5862
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-03-10

Site Id:	5194
Affiliation Type:	Mail Contact
Company Name:	MOBIL OIL CORP;ATT:A.J.PRINGLE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	3225 GALLOWS RD.; ENV.ENGINEER
Address2:	Not reported
City:	FAIRFAX
State:	VA
Zip Code:	22037
Country Code:	001
Phone:	(703) 849-5862
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-03-10

Tank Info:

Tank Number:	001
Tank ID:	29791
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1969
Date Tank Closed:	04/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN

MOBIL S/S F7FYG C&M SERVICE ST (Continued) **U001839140**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

Tank Number: 002
Tank ID: 29792
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 04/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 29793
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 04/01/1990
Registered: True

MOBIL S/S F7FYG C&M SERVICE ST (Continued) **U001839140**

Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 004
Tank ID: 29794
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 04/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 005
Tank ID: 29795

MOBIL S/S F7FYG C&M SERVICE ST (Continued) **U001839140**

Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 04/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 006
Tank ID: 29796
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 04/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

MOBIL S/S F7FYG C&M SERVICE ST (Continued) **U001839140**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 007
Tank ID: 29797
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 04/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 008
Tank ID: 29798
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 04/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I00 - Overfill - None

MOBIL S/S F7FYG C&M SERVICE ST (Continued) **U001839140**

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 009
Tank ID: 29799
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 04/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 010
Tank ID: 29800
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 04/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

MOBIL S/S F7FYG C&M SERVICE ST (Continued) **U001839140**

Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 011
Tank ID: 29801
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 04/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 012
Tank ID: 29802
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 04/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

MOBIL S/S F7FYG C&M SERVICE ST (Continued) **U001839140**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 013
Tank ID: 29803
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1969
Date Tank Closed: 04/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number: 014
Tank ID: 29804
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550

MOBIL S/S F7FYG C&M SERVICE ST (Continued) **U001839140**

Install Date:	12/01/1969
Date Tank Closed:	04/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

E55 **DLJ ENTERPRISES** **EDR Hist Auto** **1021563462**
NE **987 4TH AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.069 mi.
362 ft. **Site 7 of 12 in cluster E**

Relative: EDR Hist Auto
Lower

Actual:
42 ft.

Year:	Name:	Type:
1989	DLJ ENTERPRISES	Gasoline Service Stations, NEC
1990	DLJ ENTERPRISES	Gasoline Service Stations, NEC

E56 **MOBIL S/S** **NY LTANKS** **S106719530**
NE **987 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.069 mi.
362 ft. **Site 8 of 12 in cluster E**

Relative: LTANKS:
Lower

Actual:
42 ft.

Name:	MOBIL S/S
Address:	987 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8706481 / 2013-05-23
Facility ID:	8706481
Site ID:	192011
Spill Date:	1987-10-30
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	MDMACCAB

MOBIL S/S (Continued) **S106719530**

Referred To:	P2
Reported to Dept:	1987-10-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-11-02
Spill Record Last Update:	2013-05-23
Spiller Name:	MIKE MEOLA
Spiller Company:	EXXONMOBIL
Spiller Address:	464 DOUGHTY BLVD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	160128
DEC Memo:	On June 29, 2000, DEC (Sigona) along with Handex (Hoashi, Tonn, and DeVoe) conducted a site visit at Former Mobil S/S, 987 4th Avenue, Brooklyn, which is currently occupied by a Taco Bell. According toe Handex (Tonn) Mobil delivered a shipment of gasoline to the USTs which were partially decommissioned in 1988. Fenely & Nicol performed an investigation in 1988, and prepared a report in December 1989. Fenely and Nicol recovered approximately 250 gallons using a pump and treatment system. GTI became involved in 1992, and installed a groundwater sparging system to treat the remaining dissolved phased at the site. There were however, sporadic signs of free product over the years. There were at least 10-12 wells at the site in the previous investigations. Currently, there are only four groundwater monitoring wells, and four sparging wells. There is also a vapor extraction system at the site. A Stipulation Agreement was issued by DEC on July 7, 1995. The site is directly adjacent to a Subway which runs underneath 4th Avenue. There was no indications from Handex that the subway lines have ever been impacted. The vapor from the SVES was shut down in 1998, and was teated with carbon. DEC (O'Dowd) requested a test of the vapor from the sparge wells. In September 1999, Handex found 11,000 ppb total BTEX in SP-2 and 2,900 ppb BTEX in SP-3 and nd in SP1 and SP4. MTBE was relatively low. In November 1999, Handex found 3 feet of floating product in MW21 and has monitored on semi-annual basis only. The wells were last sampled in June 2000. Since November 1999 performed 3 vacuum truck visits and recovered free product, gaged for free product before and after each visit. Handex is not sure what the source of the free product in Well No. 21. Handex will continue to submit a semi-annual report which will be due in August 2000. Handex plans to conduct a soil investigation in Sept 2000. Handex will send the plan to DEC for review and approval. Meanwhile, the system will be shut down until Handex can determine the proximity of the contamination. The depth of groundwater is 38 feet below grade. 4/27/10 - M. MacCabe - Reinstallation of AS/SVE system has been completed except for connection to the power grid. Soil and GW were sampled when AS/SVE wells were constructed. Soil and GW contamination remain on-site. 5/21/10 - no activities this month. 6/23/10 - No activities this month. 7/26/10 - The quarterly site

MOBIL S/S (Continued) **S106719530**

status update report was received. 9/29/10 - The quarterly site status update report showed no changes in groundwater concentrations. 10/27/10 - Electrical work was conducted on the AS/SVE system in preparation for hook up to the power grid. 11/24/10 - The quarterly site status update report was received. Groundwater concentrations generally remain constant. 3/01/11 - The SVE component of the on-site remedial system was placed on-line on 12/29/10 then back off line on 1/10/11. The quarterly site status update report was received. Groundwater concentrations generally remain constant. 3/28/11 - The AS/SVE system is expected to go back on line in early April. 4/25/11 - Maintenance of the AS/SVE system was conducted in late April. This included change out of the carbon filter for the SVE effluent stack. 6/28/11 - The quarterly site status update report was received. The consultant estimates that four pounds of total BTEX and 26 pounds of total volatile petroleum hydrocarbons were removed with the SVE/AS system by the end of 2010. 7/05/11 - Periodic O&M was conducted and carbon filter was changed. 8/29/11 - Periodic O&M was conducted and the carbon filter was changed in August. The August site status update report states that approximately 10.6 lbs of BTEX and 64.9 lbs of total volatile petroleum hydrocarbons have been removed from the subsurface since the rebuilt AS/SVE system went on line in December 2010. The AS/SVE system was temporarily shut down in anticipation of hurricane Irene. 9/12/11 - Periodic O&M was conducted and the carbon filter was changed in September. 12/20/11 - The quarterly report was received. The consultant states that approximately 18.72 pounds of total BTEX and approximately 93.77 pounds of total volatile petroleum hydrocarbons (TVPH) were recovered by the SVE/AS system during the entire operation period. However, the groundwater data are inconclusive. 12/27/11 - Effective January 1, 2012, the consultant working for ExxonMobil on this project will change from Kleinfelder to Groundwater and Environmental Services (GES). 2/29/12 - Staff met with representatives of ExxonMobil and GES on February 28 to discuss modifications to the AS/SVE system to improve its efficiency. Modifications of the system consist of installing a larger compressor and cycling the system to just two of the seven vapor extraction points at one time. 5/11/12 - The quarterly site status update report covering the last quarter of 2011 and the first quarter of 2012 saw received. Weekly O&M was conducted about once every two weeks. The AS and SVE points have been cycled to allow for larger flow rates in different areas. The data show continued decreases in BTEX concentration in on-site groundwater. 8/3/12 - The quarterly site status update report saw received. Periodic OM&M was conducted twice a month. Based on the sampling results from the June 15, 2012 groundwater sampling event, extraction wells SVE-3 and SVE-5 are the only wells on-site with dissolved-phase BTEX concentrations over 1,000 ug/L. Therefore, during the third quarter of 2012, sparging efforts will be focused on these areas, specifically utilizing sparge wells AS-1 & AS-2. Quarterly groundwater sampling is scheduled for September 2012. Semi-monthly O&M will continue. 10/23/12 - The quarterly site status update report saw received. Periodic OM&M was conducted twice a month. The data continue to show decreases in BTEX concentrations in groundwater. The SSUR also contained a request to to pulse the AS/SVE system (alternating one month of system operation and one month of system inactivity). The request was accepted. 01/28/13 - The quarterly site status update report was received. Periodic OM&M was conducted twice a month. The SVE system is now operated with periodic pulsing. The pulsing consists of extracting

MOBIL S/S (Continued) **S106719530**

from different points with others dormant and changing monthly. 4/12/13 - The quarterly site status update report was received. System O&M activities were conducted twice per month during system operation in the first quarter of 2013. The system was temporarily shut down between January 2 and February 6, 2013 as part of system pulsing activities and to observe any changes in hydrocarbon recovery. The data show continued decreases in contaminant concentrations in groundwater The consultant states the approximately 147 lbs of hydrocarbons were recovered during this monitoring period and approximately 2,010 lbs of hydrocarbons have been recovered since system startup in December 2010. 5/23/13 - The groundwater data presented in the May 20, 2013 Groundwater & Environmental Services (GES) quarterly report and proceeding quarterly reports have shown consistent and significant decreases in BTEX concentrations throughout the operation of the existing AS/SVE system. Current BTEX concentrations in groundwater range from non-detect to 46 ppb. SVE system effluent has shown limited recovery in the last three quarters; presumably due to the lower contaminant concentrations in groundwater. Based on the findings, discontinuation of the AS/SVE system was deemed acceptable and the spill was closed.

Remarks: (4) 550 GAL. TANKS WOULDNT HOLD PRESSURE, WILL EXCAVATE, ISOLATE, AND RETEST. CONTACT: STEVE TRIFFOLOTTI (516 371-0286.)

All TTF:

Facility ID:	8706481
Spill Number:	8706481
Spill Tank Test:	1532110
Site ID:	192011
Tank Number:	Not reported
Tank Size:	0
Material:	1213A
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	192011
Operable Unit ID:	910196
Operable Unit:	01
Material ID:	2096468
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	True

MOBIL S/S (Continued) **S106719530**

Site ID:	192011
Operable Unit ID:	910196
Operable Unit:	01
Material ID:	465494
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	True

E57 **MOBIL S/S F7FYG C&M SERVICE ST** **UST FINDER** **1028595351**
NE **987-993 4TH AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.069 mi.
362 ft. **Site 9 of 12 in cluster E**

Relative: **Lower**
Actual: **42 ft.**

UST FINDER:

Object ID:	294973
Facility ID:	NY5194
Name:	MOBIL S/S F7FYG C&M SERVICE ST
Address:	987-993 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	14
TOS USTs:	0
Population 1500ft:	9723
Private Wells 1500ft:	15
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-74.005746
Y Coord:	40.6526670000001
Latitude:	40.652667
Longitude:	-74.005746

UST FINDER:

Object ID:	1301894
Facility ID:	NY5194

MOBIL S/S F7FYG C&M SERVICE ST (Continued) **1028595351**

Tank ID: NY4952
Tank Status: Closed
Installation Date: 1969/12/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1301895
Facility ID: NY5194
Tank ID: NY4953
Tank Status: Closed
Installation Date: 1969/12/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1301896
Facility ID: NY5194
Tank ID: NY4954
Tank Status: Closed
Installation Date: 1969/12/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1301897
Facility ID: NY5194
Tank ID: NY5593
Tank Status: Closed
Installation Date: 1969/12/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1301898
Facility ID: NY5194
Tank ID: NY5723
Tank Status: Closed
Installation Date: 1969/12/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1301899
Facility ID: NY5194
Tank ID: NY5724
Tank Status: Closed
Installation Date: 1969/12/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

MOBIL S/S F7FYG C&M SERVICE ST (Continued) **1028595351**

Object ID:	1301900
Facility ID:	NY5194
Tank ID:	NY5725
Tank Status:	Closed
Installation Date:	1969/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1301901
Facility ID:	NY5194
Tank ID:	NY6167
Tank Status:	Closed
Installation Date:	1969/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1301902
Facility ID:	NY5194
Tank ID:	NY6168
Tank Status:	Closed
Installation Date:	1969/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1301903
Facility ID:	NY5194
Tank ID:	NY6293
Tank Status:	Closed
Installation Date:	1969/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1301904
Facility ID:	NY5194
Tank ID:	NY6294
Tank Status:	Closed
Installation Date:	1969/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1301905
Facility ID:	NY5194
Tank ID:	NY6295
Tank Status:	Closed
Installation Date:	1969/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	550

MOBIL S/S F7FYG C&M SERVICE ST (Continued) **1028595351**

Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1301906
Facility ID:	NY5194
Tank ID:	NY6296
Tank Status:	Closed
Installation Date:	1969/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1301907
Facility ID:	NY5194
Tank ID:	NY6297
Tank Status:	Closed
Installation Date:	1969/12/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

E58 **MOBIL S/S** **UST FINDER RELEASE** **1029061388**
NE **987 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 0**
0.069 mi.
362 ft. **Site 10 of 12 in cluster E**

Relative: **Lower**
Actual: **42 ft.**

UST FINDER RELEASE:

Object ID:	255869
Facility ID:	NY160128
Lust ID:	NY8706481
Name:	MOBIL S/S
Address:	987 4TH AVE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1987/10/30 16:00:00+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	9418
Domestic Wells within 1500ft:	16
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported

MOBIL S/S (Continued) **1029061388**

NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-74.00564
Y Coord:	40.65295
Latitude:	40.6529499999999
Longitude:	-74.00564

E59 **CON EDISON** **NY MANIFEST** **S117314248**
ENE **423 39 ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.069 mi.
364 ft. **Site 11 of 12 in cluster E**

Relative:
Higher

Actual:
51 ft.

NY MANIFEST:

EPA ID:	NYP004612933
Country:	USA
Name:	CON EDISON
Address:	423 39 ST
Address 2:	STRUCTURE 49206
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	423 39 ST
Location Address 2:	STRUCTURE 49206
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/30/2014
Trans1 Recv Date:	07/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004612933
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105

CON EDISON (Continued) **S117314248**

TSDF ID 2:	Not reported
Manifest Tracking Number:	002615667GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	150
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

D60 **CON EDISON SERVICE BOX: 48292** **RCRA NonGen / NLR** **1016966301**
West **354 41ST ST FRONT OF** **NY MANIFEST** **NYP004391520**
< 1/8 **BROOKLYN, NY 11232**
0.073 mi.
388 ft. **Site 3 of 9 in cluster D**

Relative: RCRA Listings:
Lower

Actual: Date Form Received by Agency:	20131214
43 ft. Handler Name:	Con Edison Service Box: 48292
Handler Address:	41ST ST FRONT OF
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004391520
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

CON EDISON SERVICE BOX: 48292 (Continued) **1016966301**

Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131114
Handler Name: CON EDISON SERVICE BOX:	48292
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No

CON EDISON SERVICE BOX: 48292 (Continued) **1016966301**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131214
Handler Name: CON EDISON SERVICE BOX:	48292
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004391520
Country:	USA
Name:	CON EDISON
Address:	354 41ST ST FRONT OF
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	OPP 354 41 ST
Location Address 2:	SB 48292
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON SERVICE BOX: 48292 (Continued) **1016966301**

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	NJD003812047
Generator Ship Date:	11/14/2013
Trans1 Recv Date:	11/14/2013
Trans2 Recv Date:	11/18/2013
TSD Site Recv Date:	11/18/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004391520
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002298781GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	150
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

D61 **CON EDISON** **NY MANIFEST** **S116042820**
West **OPP 354 41 ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.073 mi.
388 ft. **Site 4 of 9 in cluster D**

Relative:
Lower

Actual:
43 ft.

NY MANIFEST:

EPA ID:	NYP004635439
Country:	USA
Name:	CON EDISON
Address:	OPP 354 41 ST
Address 2:	SB 48292
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	OPP 354 41 ST
Location Address 2:	SB 48292
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	08/21/2014
Trans1 Recv Date:	08/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/22/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004635439
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002616594GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **S116042820**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

D62 **SUNSET HEIGHTS, L.P.** **NY AST** **A100360379**
West **354 41ST STREET** **N/A**
< 1/8 **BROOKLYN, NY 11214**
0.073 mi.
388 ft. **Site 5 of 9 in cluster D**

Relative: **Lower**

Actual: **43 ft.**

AST:

Name:	SUNSET HEIGHTS, L.P.
Address:	354 41ST STREET
City,State,Zip:	BROOKLYN, NY 11214
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-406120
Program Type:	PBS
UTM X:	583875.59468
UTM Y:	4500576.03465
Expiration Date:	N/A
Site Type:	Unknown

Affiliation Records:

Site Id:	19606
Affiliation Type:	Facility Owner
Company Name:	SUNSET HEIGHTS, L.P.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	354 41ST STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11214
Country Code:	001
Phone:	(718) 221-5464
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT

SUNSET HEIGHTS, L.P. (Continued) **A100360379**

Date Last Modified: 2004-03-04

Site Id: 19606
Affiliation Type: Mail Contact
Company Name: SUNSET HEIGHTS, L.P.
Contact Type: Not reported
Contact Name: Not reported
Address1: % SHINDA MANAGEMENT CORP.
Address2: 217-02 JAMAICA AVENUE
City: QUEENS VILLAGE
State: NY
Zip Code: 11428
Country Code: 001
Phone: (718) 740-0416
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 19606
Affiliation Type: Facility Operator
Company Name: SUNSET HEIGHTS, L.P.
Contact Type: Not reported
Contact Name: MICHAEL SWINT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 221-5464
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 19606
Affiliation Type: Emergency Contact
Company Name: SUNSET HEIGHTS, L.P.
Contact Type: Not reported
Contact Name: MICHAEL SWINT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 221-5464
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank Id: 24642

SUNSET HEIGHTS, L.P. (Continued) **A100360379**

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 2000
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/15/2013
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

D63 **4201 4TH AVE/B'KLYN/OLD C** **NY Spills** **S103560235**
SW **4201 4TH AVE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.074 mi.
390 ft. **Site 6 of 9 in cluster D**

Relative: Higher
Actual: 57 ft.

SPILLS:
Name: 4201 4TH AVE/B'KLYN/OLD C
Address: 4201 4TH AVE
City,State,Zip: NEW YORK CITY, NY
Spill Number/Closed Date: 8707375 / 1987-12-01
Facility ID: 8707375
Facility Type: ER
DER Facility ID: 217602
Site ID: 267121
DEC Region: 2
Spill Cause: Other
Spill Class: Not reported
SWIS: 2401
Spill Date: 1987-11-01
Investigator: UNASSIGNED
Referred To: Not reported
Reported to Dept: 1987-11-27
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Affected Persons

4201 4TH AVE/B'KLYN/OLD C (Continued) **S103560235**

Cleanup Ceased:	1987-12-01
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-12-01
Spill Record Last Update:	1988-10-14
Spiller Name:	Not reported
Spiller Company:	BOARD OF EDUCATION
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	CALLER WAS SECURITY GUARD FOR PRIVATE COMP. SAID ASBESTOS WAS FALLINGFROM CEILING, WANTS SOMEONE TO INVESTIGATE.
Remarks:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was

All Materials:

Site ID:	267121
Operable Unit ID:	913081
Operable Unit:	01
Material ID:	466331
Material Code:	0026A
Material Name:	asbestos
Case No.:	01332214
Material FA:	Hazardous Material
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Air
Oxygenate:	Not reported

C64 **SERVICE BOX 48297** **NY Spills** **S103936246**
SE **459 41ST ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.074 mi.
393 ft. **Site 4 of 6 in cluster C**

Relative:
Higher

Actual:
80 ft.

SPILLS:

Name:	SERVICE BOX 48297
Address:	459 41ST ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9900540 / 2002-06-10
Facility ID:	9900540
Facility Type:	ER
DER Facility ID:	117926
Site ID:	137908
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1999-04-15
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1999-04-15
CID:	257

SERVICE BOX 48297 (Continued) **S103936246**

Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-15
Spill Record Last Update:	2002-06-11
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	STEVE ROMERO
DEC Memo:	1 quart on 1 gal on water - cleanup pending test results ref #124249
Remarks:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL CON ED E2MIS NOTES 4-21-99 1qt of oil found on 1 gal. of water in SB-48297 no sewers or waterways affected, it is contained. Sample taken on a 4-6hr. turnaround and sign hung. 4-15-99 Update Lab Seq#99-03869 PCB <1ppm. UPDATE: 4/22/99 - 1000 K. QUEST - 55475 - ENV. OPS., REPORTS <1.0 PPM CLEANUP COMPLETE AND TAG # 07808 REMOVED.

All Materials:

Site ID:	137908
Operable Unit ID:	1075310
Operable Unit:	01
Material ID:	307669
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

D65 **MANHOLE 4045** **NY Spills** **S104880956**
SW **4TH AVE/42ND ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.076 mi.
399 ft. **Site 7 of 9 in cluster D**

Relative: **Higher**
Actual: **57 ft.**

SPILLS:

Name:	MANHOLE 4045
Address:	4TH AVE/42ND ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0010159 / 2001-12-28
Facility ID:	0010159
Facility Type:	ER
DER Facility ID:	127203
Site ID:	149544
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4

MANHOLE 4045 (Continued) **S104880956**

SWIS:	2401
Spill Date:	2000-12-09
Investigator:	OKWUOHA
Referred To:	Not reported
Reported to Dept:	2000-12-09
CID:	382
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-12-09
Spill Record Last Update:	2002-01-02
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JIMMY FOX
DEC Memo:	1/2 pt oil on floor of manhole. clean up pending. con ed 134-697
Remarks:	Not reported

All Materials:

Site ID:	149544
Operable Unit ID:	832243
Operable Unit:	01
Material ID:	563264
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

D66 **4112 4TH AVE LLC** **NY AST** **U003392469**
WSW **375 42ND STREET** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.077 mi.
406 ft. **Site 8 of 9 in cluster D**

Relative:
Higher

Actual:
53 ft.

AST:

Name:	4112 4TH AVE LLC
Address:	375 42ND STREET
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-406333
Program Type:	PBS
UTM X:	583871.00062
UTM Y:	4500532.53493

4112 4TH AVE LLC (Continued) **U003392469**

Expiration Date: 11/15/2027
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 19625
Affiliation Type: Mail Contact
Company Name: 4112 REALTY LLC
Contact Type: Not reported
Contact Name: IRA EPSTEIN
Address1: 2167 EAST 21 STREET
Address2: #149
City: BROOKLYN
State: NY
Zip Code: 11229
Country Code: 001
Phone: (718) 258-1936
EMail: REMGMT149@OPTONLINE.COM
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2018-07-25

Site Id: 19625
Affiliation Type: Facility Operator
Company Name: 4112 4TH AVE LLC
Contact Type: Not reported
Contact Name: IRA EPSTEIN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 258-1936
EMail: Not reported
Fax Number: Not reported
Modified By: DMMOLOUG
Date Last Modified: 2013-11-05

Site Id: 19625
Affiliation Type: Facility Owner
Company Name: 4112 REALTY LLC
Contact Type: OWNER
Contact Name: IRA EPSTEIN
Address1: 2167 EAST 21 ST, PMB 149
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11229
Country Code: 001
Phone: (718) 258-1936
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2018-07-25

Site Id: 19625
Affiliation Type: Emergency Contact
Company Name: 4112 REALTY LLC

4112 4TH AVE LLC (Continued) **U003392469**

Contact Type:	Not reported
Contact Name:	IRA EPSTEIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 258-1936
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2023-04-20

Tank Info:

Tank Number:	001
Tank Id:	24662
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	J02 - Dispenser - Suction Dispenser
	F04 - Pipe External Protection - Fiberglass
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	B04 - Tank External Protection - Fiberglass
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	I04 - Overfill - Product Level Gauge (A/G)
	C01 - Pipe Location - Aboveground
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/1963
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

C67 **CLEAN RITE CLEANERS** **EDR Hist Cleaner** **1019957092**
East **442 39TH ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.077 mi.
407 ft. **Site 5 of 6 in cluster C**

Relative: EDR Hist Cleaner
Higher

Actual: Year: Name: Type:
67 ft. 2006 CLEAN RITE CLEANERS Drycleaning Plants, Except Rugs, NEC
2010 CLEAN RITE CLEANERS Drycleaning Plants, Except Rugs, NEC

E68 **USPS** **NY Spills** **S121985097**
NNE **1050 FOUR BELL ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.078 mi.
410 ft. **Site 12 of 12 in cluster E**

Relative: SPILLS:
Lower

Actual:
40 ft.

Name:	USPS
Address:	1050 FOUR BELL ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1800585 / 2018-04-17
Facility ID:	1800585
Facility Type:	ER
DER Facility ID:	514571
Site ID:	569088
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2018-04-17
Investigator:	AAOBLIGA
Referred To:	Not reported
Reported to Dept:	2018-04-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2018-04-17
Spill Record Last Update:	2018-04-25
Spiller Name:	SAL SAIEVA
Spiller Company:	USPS
Spiller Address:	1050 FOUR BELL ST
Spiller Company:	999
Contact Name:	SAL SAIEVA
DEC Memo:	LOSS FROM COMPACTOR ON SITE. CONTAINED. MILLER ENVIRO ON SITE FOR CLEAN UP
Remarks:	4-17-18 - Obligado - I called Sal. Left a message to call back the NYSDEC. Last night one of the recyclying units went down. Control for recycler are in a pit. Called in a vendor and opened the pit. There is oil in the pit. Miller Environmental went in the pit. Estimated 30 gallons of oil. Broken high pressure hose. Miller did the remediation. Contained. Cleaned up, and doing a final steam clean.

USPS (Continued) **S121985097**

4/19/18 - Obligado - I received photo documentation of the clean up. Spill closed.

All Materials:

Site ID:	569088
Operable Unit ID:	1316958
Operable Unit:	01
Material ID:	2324727
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

G69 **J. KEVIN O'CONNOR** **NY AST** **U003396617**
SSE **460 41 STREET** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.084 mi.
444 ft. **Site 1 of 6 in cluster G**

Relative:
Higher

Actual:
83 ft.

AST:

Name:	J. KEVIN O'CONNOR
Address:	460 41 STREET
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-602384
Program Type:	PBS
UTM X:	584051.55192
UTM Y:	4500434.23552
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	24341
Affiliation Type:	Mail Contact
Company Name:	PATKEY, LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	PO BOX 2518, CHURCH STREET STATION
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10008
Country Code:	001
Phone:	(718) 344-3096
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-07-26

Site Id:	24341
Affiliation Type:	Facility Operator

J. KEVIN O'CONNOR (Continued) **U003396617**

Company Name:	J. KEVIN OCONNOR
Contact Type:	Not reported
Contact Name:	F. CABRERA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 436-4540
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-07-26

Site Id:	24341
Affiliation Type:	Emergency Contact
Company Name:	PATKEY, LLC
Contact Type:	Not reported
Contact Name:	F. CABRERA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 436-4540
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-07-26

Site Id:	24341
Affiliation Type:	Facility Owner
Company Name:	PATKEY, LLC
Contact Type:	MANAGING MEMBER
Contact Name:	JOHN K. O'CONNOR
Address1:	PO BOX 2518, CHURCH STREET STATION
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10008
Country Code:	001
Phone:	(718) 344-3096
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-07-26

Tank Info:

Tank Number:	1
Tank Id:	49932
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

J. KEVIN O'CONNOR (Continued) **U003396617**

Equipment Records:

	B00 - Tank External Protection - None
	F00 - Pipe External Protection - None
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	G03 - Tank Secondary Containment - Vault (w/o access)
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	C01 - Pipe Location - Aboveground
	J02 - Dispenser - Suction Dispenser
	I05 - Overfill - Vent Whistle
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1080
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/03/2012
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

F70 **CON EDISON MANHOLE: 49204** **RCRA NonGen / NLR** **1016148702**
NNW **346 39TH ST** **FINDS** **NYP004272829**
< 1/8 **BROOKLYN, NY 11232** **ECHO**
0.084 mi. **NY MANIFEST**
446 ft. **Site 4 of 6 in cluster F**

Relative: **Lower**
Actual: **32 ft.**

RCRA Listings:

Date Form Received by Agency:	20170728
Handler Name:	Con Edison Manhole: 49204
Handler Address:	39TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004272829
Contact Name:	MICHAEL STAMPFEL
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-666-4550
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003

CON EDISON MANHOLE: 49204 (Continued) **1016148702**

Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20171101
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20121009
Handler Name:	CON EDISON MANHOLE: 49204
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CON EDISON MANHOLE: 49204 (Continued) **1016148702**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20170728
Handler Name: CON EDISON MANHOLE: 49204
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055453824

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016148702
Registry ID: 110055453824
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055453824
Name: CON EDISON MANHOLE: 49204
Address: 346 39TH ST
City,State,Zip: BROOKLYN, NY 11232

NY MANIFEST:
EPA ID: NYP004272829
Country: USA
Name: CON EDISON
Address: 346 39TH ST
Address 2: Not reported

CON EDISON MANHOLE: 49204 (Continued) **1016148702**

City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: 346 39TH ST
Location Address 2: MH 49204
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 10/09/2012
Trans1 Recv Date: 10/09/2012
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/11/2012
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004272829
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 001675128GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported

CON EDISON MANHOLE: 49204 (Continued) **1016148702**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	200
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

F71 **CON EDISON MANHOLE: 49204** **NJ MANIFEST** **S117986660**
NNW **346 39TH ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.084 mi.
446 ft. **Site 5 of 6 in cluster F**

Relative:
Lower

Actual:
32 ft.

NJ MANIFEST:

EPA ID:	NYP004272829
Name:	CON EDISON MANHOLE: 49204
Address:	346 39TH ST
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	MICHAEL STAMPFEL
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004272829
Manifest Number:	001675128GBF
Date Shipped:	10/9/2012
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

CON EDISON MANHOLE: 49204 (Continued) **S117986660**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	Not reported
Quantity:	200.00
Unit:	gallons

D72 **NYC DEPT OF ED - PS 333K** **RCRA-SQG** **1008404481**
SW **4222 4TH AVE** **NY LEAD** **NYR000134783**
< 1/8 **BROOKLYN, NY 11232** **NY MANIFEST**
0.087 mi. **NJ MANIFEST**
459 ft. **Site 9 of 9 in cluster D**

Relative: Higher
Actual: 58 ft.

RCRA Listings:

Date Form Received by Agency:	20121018
Handler Name:	Nyc Dept Of Ed - Ps 333k
Handler Address:	4TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYR000134783
Contact Name:	ALEXANDER LEMPERT
Contact Address:	THOMSON AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-472-8501
Contact Fax:	718-472-8500
Contact Email:	ALEMPERT@NYCSCA.ORG
Contact Title:	DIRECTOR
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	THOMSON AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	St Michaels Roman Catholic Church
Owner Type:	Private
Operator Name:	St Michaels Roman Catholic Church
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

Owner/Operator Indicator:	Operator
Owner/Operator Name: NO NAME FOUND	
Legal Status:	Municipal
Date Became Current:	19900101
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ST MICHAELS ROMAN CATHOLIC CHURCH	
Legal Status:	Private
Date Became Current:	19241101
Date Ended Current:	Not reported
Owner/Operator Address:	352 42ND ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11232
Owner/Operator Telephone:	718-768-6065
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NO NAME FOUND	
Legal Status:	Municipal
Date Became Current:	19300101
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: HEAD START	
Legal Status:	Municipal
Date Became Current:	19900101
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CATHOLIC CHARITIES	
Legal Status:	Municipal
Date Became Current:	19300101
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ST MICHAELS ROMAN CATHOLIC CHURCH
Legal Status: Private
Date Became Current: 19241101
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: SUNSET PARK DAY CARE CENTER
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SUNSET PARK DAY CARE CENTER
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20050929
Handler Name: SUNSET PARK DAY CARE CENTER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20121018
Handler Name: NYC DEPT OF ED - PS 333K

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	61111
NAICS Description:	ELEMENTARY AND SECONDARY SCHOOLS

NAICS Code:	61169
NAICS Description:	ALL OTHER SCHOOLS AND INSTRUCTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NYC LEAD 2:

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K333
Room:	101B BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K333
Room:	103B BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K333
Room:	110 BR
Deteriorated Paint:	NO

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: 112 BR
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: 129A BR
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: 202C BR
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: 203B BR
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: 204C BR
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: 206B BR
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: 208B BR
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: 209 BR
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: 225A BR
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: 229A BR
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K333
Room:	302C BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K333
Room:	304B BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K333
Room:	306B BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K333
Room:	308B BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K333
Room:	311 BR
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: C06 BR
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: C07 BR
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: 101
Deteriorated Paint: YES
Presence of LBP: YES
Stabilization Required: YES
Stabilization Complete: YES

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: 103
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: 129
Deteriorated Paint: NO
Presence of LBP: NA
Stabilization Required: NA
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

Building Code:	K333
Room:	202
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K333
Room:	204
Deteriorated Paint:	YES
Presence of LBP:	NO
Stabilization Required:	NO
Stabilization Complete:	NA

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K333
Room:	208
Deteriorated Paint:	YES
Presence of LBP:	NO
Stabilization Required:	NO
Stabilization Complete:	NA

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K333
Room:	225
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K333
Room:	229
Deteriorated Paint:	NO
Presence of LBP:	NA
Stabilization Required:	NA
Stabilization Complete:	NA

Name:	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address:	4222 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Geographical District:	15
Building Code:	K333
Room:	114 Gym

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

Deteriorated Paint: YES
Presence of LBP: YES
Stabilization Required: YES
Stabilization Complete: YES

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: CAFT
Deteriorated Paint: YES
Presence of LBP: NO
Stabilization Required: NO
Stabilization Complete: NA

Name: P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL - B
Address: 4222 4TH AVENUE
City,State,Zip: BROOKLYN, NY
Geographical District: 15
Building Code: K333
Room: SCAF
Deteriorated Paint: YES
Presence of LBP: NO
Stabilization Required: NO
Stabilization Complete: NA

NY MANIFEST:
EPA ID: NYR000134783
Country: USA
Name: SUNSET PARK DAYCARE CENTER
Address: 4222 4TH AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: 4222 4TH AVENUE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: SUNSET PARK DAYCARE CENTER
Mailing Contact: EDWARD FAISON
Mailing Address 1: 150 WILLIAM ST
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10038
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2123410900

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYR000081661

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	11/30/2012
Trans1 Recv Date:	11/30/2012
Trans2 Recv Date:	12/06/2012
TSD Site Recv Date:	12/07/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134783
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000097262JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	B004
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	45
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000081661
Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	11/30/2012
Trans1 Recv Date:	11/30/2012
Trans2 Recv Date:	12/06/2012
TSD Site Recv Date:	12/07/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134783
Trans1 EPA ID:	Not reported

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000097262JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	B004
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	675
Units:	Kilograms
Number of Containers:	3
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Document ID:	NJA5300359
Manifest Status:	Not reported
Trans1 State ID:	S8424
Year:	2005
Trans2 State ID:	Not reported
Generator Ship Date:	10/07/2005
Trans1 Recv Date:	10/07/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/07/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134783
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00800
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

NJ MANIFEST:

EPA ID:	NYR000134783
Name:	NYC ADMIN FOR CHILDRENS SVCS
Address:	4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11201
County:	Not reported
Mailing Address:	66 JOHNS STREET
Mailing City,State,Zip:	NEW YORK 10038
Telephone:	2123615873
Emergency Telephone:	Not reported
Contact:	EDWARD FAISON
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPAID:	Not reported
Generator Flag:	X
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYR000134783
Manifest Number:	NJA5300359
Date Shipped:	10/07/2005
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/07/2005

NYC DEPT OF ED - PS 333K (Continued) **1008404481**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/07/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01300621
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

C73 **CON EDISON** **NY MANIFEST** **S116043714**
ESE **467 40TH ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.089 mi.
470 ft. **Site 6 of 6 in cluster C**

Relative:
Higher

Actual:
77 ft.

NY MANIFEST:

EPA ID:	NYP004400784
Country:	USA
Name:	CON EDISON
Address:	467 40TH ST
Address 2:	SB49285
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	467 40TH ST
Location Address 2:	SB49285
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S116043714**

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	12/05/2013
Trans1 Recv Date:	12/05/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004400784
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002300215GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	40
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

H74 **CON EDISON** **NY MANIFEST** **S117738828**
East **449 39 ST** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.089 mi.
470 ft. **Site 1 of 2 in cluster H**

Relative:
Higher

Actual:
63 ft.

NY MANIFEST:

EPA ID:	NYP004719068
Country:	USA
Name:	CON EDISON
Address:	449 39 ST
Address 2:	SB49207
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	449 39 ST
Location Address 2:	SB49207
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	NJD003812047
Generator Ship Date:	01/26/2015
Trans1 Recv Date:	01/26/2015
Trans2 Recv Date:	02/05/2015
TSD Site Recv Date:	02/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004719068
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620689GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **S117738828**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

I75 **CON EDISON - MANHOLE 49290** **RCRA-LQG** **1024891224**
SE **476 40TH ST** **NYP005087527**
< 1/8 **BROOKLYN, NY 11232**
0.096 mi.
505 ft. **Site 1 of 9 in cluster I**

Relative: **Higher**

Actual: **81 ft.**

RCRA Listings:

Date Form Received by Agency:	20180410
Handler Name:	Con Edison - Manhole 49290
Handler Address:	40TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP005087527
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No

CON EDISON - MANHOLE 49290 (Continued) **1024891224**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170525
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003

CON EDISON - MANHOLE 49290 (Continued) **1024891224**

Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170525
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - MANHOLE 49290
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

I76 **CON EDISON** **NY MANIFEST** **S121968144**
SE **476 40TH ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.096 mi.
505 ft. **Site 2 of 9 in cluster I**

Relative: NY MANIFEST:
Higher
EPA ID: NYP005087527
Actual: Country: USA
81 ft. Name: CON EDISON
Address: 476 40TH ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported

CON EDISON (Continued) **S121968144**

Location Address 1:	476 40TH ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

J77 **PS # 24** **NY Spills** **S108058233**
NE **38TH STREET AND 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.102 mi.
536 ft. **Site 1 of 10 in cluster J**

Relative: **Lower**

Actual: **36 ft.**

SPILLS:

Name:	PS # 24
Address:	38TH STREET AND 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0603862 / 2006-09-13
Facility ID:	0603862
Facility Type:	ER
DER Facility ID:	316745
Site ID:	366701
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-07-07
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2006-07-07
CID:	410
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-07-07
Spill Record Last Update:	2006-09-13
Spiller Name:	ALAN WEINER
Spiller Company:	LAWRENCE CARR
Spiller Address:	38TH STREET AND 4TH AVE
Spiller Company:	001

PS # 24 (Continued) **S108058233**

Contact Name: ALAN WEINER
DEC Memo: LAWRENCE CARR AMUSEMENT COMPANY PH# 917-653-3168 LARRY CARR CALLER REPORTS ONLY A STAIN LEFT ON
PAVEMENT AT PUBLIC SCHOOL #24 UPON ARRIVAL TO SPILL.
Remarks: 7/7/2006 Sangeland spoke w/ Ray Lara of PTC. Ray stated that one 20' diameter and one 10' diameter stian that is sheening was present. PTC gave estimate though was not hired and was told by Alan Weiner that they were going to hire a guy with a power washer and wash it into the drain. Piper spoke w/ Don Iaccarino from the school. 917.440.7067 office- 718.832.8720. As per him approximately 50 gal of hydraulic oil was left on the asphalt when they left in one location. There are other areas also affected with up to 20 gal in that location. They didn't do much to clean it. DEC Piper called Alan 347.671.2482 who is director of amusement company. Owner, Larry Carr 917.653.3168. PO Box 83, Wintersville, GA 30683-0083 Piper asked what is being done. Al stated that PTC bid was very high and that he was going w/ AJ Pressure Washing. 718.256.1214. to clean it up. Piper called Anthony at AJ Press. He stated that he was asked to provide an estimate to provide pressure washing of area. Piper explained that the water generated would have to be vacced up and disposed of properly. Anthony stated that he will use a shop vac to collect the water and dispose of it properly. It might take a while for him to figure out how. Piper thanked him and ended conversation. Piper called Alan Weiner and stated that AJ PW is unacceptable for the cleanup requirements. Piper stated that he could fax a list of contractors to him for his use in finding a contractor who can do this other than PTC. Alan stated he will call me back with a fax number. 7/10/06- DEC Piper left message for Alan to call back. DEC Piper spoke w/ Don at school. There was nothing done over the weekend. DEC Piper responded to site. Upon arrival, Piper met w/ Robert (custodial)and its was observed that multiple large stains were present on basket ball court area. Tire marks smeared throughout court. Some staining observed entering storm drain on northwest side of property. Piper photodocumented site. Piper spoke w/ Principal of School Christina Fuentes in her office regarding spill. As per her, the canival lasted from June 212 to July 3. During their stay the carnival was very dirty, un responsive and un professional. (blocked fire exits, sidewalk and harrassed women.) Principal Fuentes #.718.832.9366. Alan Weiner has been uncooperative w/ School and has given them runaround since they left. Spill was called in by PTC 4 days after they had left. DEC Piper mailed letter to LAwrence Carr Amusements adn faxed copy to Alan Weiner at 718.642.2861 7/12/06- DEC Piper spoke w/ Al;an Weiner regarding cleanup. As per him, he will be receiving estimates today and will inform me as to whne work will commence. DECP iper phoned Joe gallager w/ NYS Dept of LAbor, Health and Safety Div. 518.457.2131, regarding Amusement CO. HE is well aware of the type of Operation and has discontinued permitting for this Company. Joe stated He is one of the worst operators on record . However since city is not state juristiction, he operates within city limits. Joe forwarded me to City Ride Inspector, Jim Waters, 212.566.5539. Piper left message requesting callback and info. 07/13/06-Vought-Called Weiner for udpate on contractor as per DEC Piper. Vought called Weiner and he contacted four companies and only one returned call with high price as per Weiner. Weiner told Vought that he would call back by the end of the day with a contractor. Vought explained that if call was not received and ECO would be sent to the Carnival's current location(Northern Blvd and Junction Blvd).

PS # 24 (Continued) **S108058233**

07/14/06-Vought-Received message from Weiner and returned call and left message to return call. Vought received call from Weiner and he nobody has called him back, he will call back this morning with name of contractor. 07/17/06-Vought-Received message from Weiner on 7/14 that he had received estimates from PTC, Eastmond and ABC and was awaiting estimate from Tradewinds. Weiner willing to fax DEC copy of estimates. Vought referred case back to DEC Piper. Piper spoke w/ Alan weiner, he will have Eastmond come and power wash affected area. Piper confirmed w. Eastmond that pwer washing was done. Piper spoke w. Principal Fuentes to confirm. As per her, work was done though it is still bad. Piper resonded to site to inspect. Heavy stains still existed. DEC Piper required Carr AMusemnets to deal affected area. DEC Piper made numerous attemts to caontact ALan to perform sealing. 9/13/06- DEC Piper spoke w. Don from school. aS per him, Don Merlo of Fuel Division inspercted and had PTC cleaners perform additional cleaning of area w/ more effective eqipment. As per son it is much better and school is more pleased. School may resurface in short while. Fuel spill is cleaned. Closed.

All Materials:

Site ID:	366701
Operable Unit ID:	1124633
Operable Unit:	01
Material ID:	2114128
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

F78 **341 39TH ST/BKLYN** **NY Spills** **S102142402**
NNW **341 39TH STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.103 mi.
544 ft. **Site 6 of 6 in cluster F**

Relative: **Lower**

Actual: **28 ft.**

SPILLS:

Name:	341 39TH ST/BKLYN
Address:	341 39TH STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8809138 / 2004-01-12
Facility ID:	8809138
Facility Type:	ER
DER Facility ID:	167330
Site ID:	201122
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1989-02-24
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1989-02-24

341 39TH ST/BKLYN (Continued) **S102142402**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-03-02
Spill Record Last Update:	2004-01-12
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	SETTING UP VAC TRUCK TO CLEAN, WERE USING PRESSURE PUMP ON TANK, VIBRATION LOOSENED CONNECTION IN RETURN LINE RELEASING 1000 GALLONS OF OIL IN TANK ROOM.
Remarks:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 1/12/o4 - AUSTIN - SURF. SPILL FROM 15 YRS. AGO - CLOSED - ORIG. ASSIGNED TO FINGER - END

All Materials:

Site ID:	201122
Operable Unit ID:	925035
Operable Unit:	01
Material ID:	453902
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1000.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

K79 **341 39TH ST** **NY LTANKS** **S100493383**
North **341 39TH ST** **N/A**
< 1/8 **SUNSET PARK, NY**
0.103 mi.
544 ft. **Site 1 of 7 in cluster K**

Relative: LTANKS:
Lower

Actual: Name:	341 39TH ST
29 ft. Address:	341 39TH ST
City,State,Zip:	SUNSET PARK, NY
Spill Number/Closed Date:	9200366 / 1992-04-10
Facility ID:	9200366
Site ID:	103132
Spill Date:	1992-04-09
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1992-04-10

341 39TH ST (Continued) **S100493383**

SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1992-04-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-04-16
Spill Record Last Update:	2002-11-29
Spiller Name:	Not reported
Spiller Company:	JERRY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	91242
DEC Memo:	Not reported
Remarks:	PETRO TANK CLEANERS TO PUMP & CLEAN

All TTF:

Facility ID:	9200366
Spill Number:	9200366
Spill Tank Test:	1539849
Site ID:	103132
Tank Number:	Not reported
Tank Size:	0
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	103132
Operable Unit ID:	964303
Operable Unit:	01
Material ID:	415171
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	300.00
Units:	G
Recovered:	.00

341 39TH ST (Continued) **S100493383**

Resource Affected: Soil
Oxygenate: Not reported

K80 **G & L EYES INC.** **NY LTANKS** **S108146492**
North **341 39TH ST.** **NY Spills** **N/A**
< 1/8 **BROOKLYN, NY 11232** **NY HSWDS**
0.103 mi.
544 ft. **Site 2 of 7 in cluster K**

Relative:
Lower

Actual:
29 ft.

LTANKS:

Name:	341 39TH STREET
Address:	341 39TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9313271 / 1994-04-25
Facility ID:	9313271
Site ID:	201123
Spill Date:	1994-02-09
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1994-04-25
SWIS:	2401
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1994-02-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-02-10
Spill Record Last Update:	1994-05-25
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	288717
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was GENE SULLIVAN
Remarks:	FILLED WRONG TANK - BAYSIDE - FILLED TANK IN BROOKLYN - VACUUMED UP - WILL DISPOSE OF - TALKED WITH BOB DECK OIL CAME OUT VENT - SPILL OUTSIDE 25'-25' AND MOST SIDE TANK - NO DRAINS INVOLVED.

All Materials:

Site ID:	201123
Operable Unit ID:	991727
Operable Unit:	01
Material ID:	388656
Material Code:	0003A
Material Name:	#6 fuel oil

G & L EYES INC. (Continued) **S108146492**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1400.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	341 39TH ST.
Address:	341 39TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9313394 / 1994-02-14
Facility ID:	9313394
Site ID:	201124
Spill Date:	1994-02-14
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1994-02-14
SWIS:	2401
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1994-02-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Federal Government
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-02-15
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	288717
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG 10/10/95: This is additional information about material spilled from the translation of the old spill file: UNDERGR. STAR TANK.
Remarks:	USCG WILL BE THERE - WILL INVEST. CALLED USCG, THEY TOLD ME THAT SPILL HAD BEEN CLEANED UP LAST FRIDAY.

All Materials:

Site ID:	201124
Operable Unit ID:	991852
Operable Unit:	01
Material ID:	388778
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

G & L EYES INC. (Continued) **S108146492**

Quantity: 2000.00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

SPILLS:
Name: WAREHOUSE - MISC
Address: 341 39TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0413302 / 2006-11-09
Facility ID: 0413302
Facility Type: ER
DER Facility ID: 288717
Site ID: 342368
DEC Region: 2
Spill Cause: Unknown
Spill Class: B3
SWIS: 2401
Spill Date: 2005-03-22
Investigator: KSTANG
Referred To: Not reported
Reported to Dept: 2005-03-22
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2005-03-22
Spill Record Last Update: 2006-11-09
Spiller Name: Not reported
Spiller Company: UNKNOWN AT THIS TIME
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ANTONY
DEC Memo: CALLER STATES THAT THEY ARE STILL INVESTIGATING WHAT HAPPENED: ANTHONY IS TEH CONTACT ON THE SCENE,
FROM PERTOLUEM TANK : IT IS INSIDE AND OUTSIDE THE BUILDING:
Remarks: 03/22/05-Sharif// Sharif and Mr. Sawyer responded to the site.About 4000 gallons of #6 oil came out of vent line and top of the tank while the pump to the boiler was replaced and being tested.Oil had been contained in the secondary container(vault). Vent is located out of the building at the backside where about 20'by 20' open area adjacent to couple of abandoned railroad track line is impacted by the oil. Oil spreaded over one of the track of about 10 ft in length.Petrolium Tank Cleaners(PTC) has been called in to do the clean up. NYC Transit, Office of System Safety(Josephina Volyn/Richel Kron, 718-243-4581, Fax: 718-243-4309) has been notified of their property impact. 04/06/05-SR// PTC excavated the rail track, took sample, backfill soon with supervision from NYC Transit. Open lot between building and the track has been field screened.

G & L EYES INC. (Continued) **S108146492**

Contamination found.Property owner Mr. Merhige was contacted for revised work plan including tank vault and open lot. 9/8/05-Vought-File review as per DEC Austin due to inquiry by Rachel Kron (NYC Transit 646-252-5773). Spill out of vent pipe and also into tank room. Letter from DEC Rahman to Commercial Realty Co (11 East 26th Street, 11th Floor attn: Richard Merhige)-3/23/05. Letter sent requiring: 1)excavation of all oil impacted soil and debris including railroad track area 2)removal of oil from secondary containment vault 3)submission of soil sampling results. Scope of Work from Petroleum Tank Cleaners PTC(Anthony Lara 718-624-4842)-4/5/05. Scope of work includes: 1)product removal from vaults. Soil analyticals from PTC-5/24/05. Water analyticals show no TAGM Soil Cleanup Objective exceedences except for minor PAH's attributable to fill material. Letter from PTC (Lara) to DEC Rahman-6/27/05. PTC has removed all contaminated soil and debris from the vault, and as you agreed what was acceptable PTC has addressed any remaining contamination via the application of Biosolve biormediation accelerant to the soil beneath the existing vault floor . PTC plans to begin installing a new concrete floor as early as 7/6/05. 9/8/05-Vought-Called Rachel (646-252-5773) and left message with outstanding requirements: 1)endpoint soil samples from track excavation 2)site plan and locations of endpoint sampling. Vought called Commercial Realty (Richard Merhige 212-947-7500) and he tried to call Rachel who has not returned call. PTC still cleaning out second tank room. PTC collected soil samples from outside and two 20' foot containers were generated from soil excavation. Jerry Sobel will be contact for next seven weeks as Richard will be going on vacation. Vought left message for PTC to return call with status of soil excavation and endpoint sampling. 10.19.05 Sharif- I spoke with Anthony of PTC, 646-772-7180 who informed me they made formal request to NYCT's property to do geoprobe investigation. NYCT holding them regarding some insurance coverage issues which will possibly be simplified as they are working on it. NYCT is supposed to getback to PTC by this week. I'll call NYCT next week about their approval. 12/15/05 Sun reassigned from Rahman to Foley. 1/3/2005 - Feng - File reviewed by Feng and summarized: 1) some samples were collected the boiler room with site plan provided, but did not indicated out whether soil or groundwater samples. High SVOCs. 2) Track area inpacted, and removed the contaminated soil. DEC has been requested 1)endpoint soil samples from track excavation 2)site plan and locations of endpoint sampling. Nono were submitted on file. 3) DEC Rahman has assisted PTC to access the NYCT property and do the sampling. Wait for sampling result report. 05/09/06 - spoke to Mr. Bob Lamirata of PTC, 718-624-2185. He said he will take care of disposing the contaminated soil pile at the site in a few days. I will find out more of the subsurface contamination. - KST 6/15/06 - Bob Lamirata of PTC called and advised that contaminated soil pile has been removed. Will fax end-point sampling results. - KST 6/26/06 - PTC sent in the report which only has the lab results, no write-up. The results look clean. Called Bob Lamirta and told him that DEC needs a report summarizing the contamination and the actions taken by the RP OR PTC in cleaning up the spill. Liz Deluca called and will be at the site on June 27, assessing the spill. She will call me to report if additional work is needed. - KST 11/9/06 - NYCT has not call to request additional cleanup work. Spill closed. - KST

All Materials:
Site ID: 342368

G & L EYES INC. (Continued) **S108146492**

Operable Unit ID: 1101098
Operable Unit: 01
Material ID: 581232
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 500.00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

HSWDS:
Facility ID: Not reported
Region: 2
Facility Status: None
Owner Type: Puplic
Owner: G & L Eyes, Inc.
Owner Address: 341 39th St.
Owner Phone: (718)768-9690
Operator Type: Same
Operator: Unknown
Operator: Unknown
Operator Phone: Unknown
EPA ID: NYD042777128
Registry: Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID: None
RCRA Permitted: Unknown
Site Code: Industrial Site
Owner City State: Brooklyn, NY 11232
Operator City State: Not reported
Quadrange: Unknown
Latitude: 40 39'22"N
Longitude: 74 00'27"W
Acres: 0.00
Operator Date: 1962
Close Date: Unknown
Completed: PA
Active: Unknown
PCB's Disposed: No
Pesticides Disposed: No
Metals Disposed: No
Asbestos Disposed: No
Volatile Organic Compounds Disposed: No
Semi Volatile Organic Compounds Disposed: No
Analytical Info Exists for Air: Not reported
Analytical Info Exists for Ground: None
Analytical Info Exists for Surface: Not reported
Analytical Info Exists for Sediments: Not reported
Analytical Info Exists for Surface: Not reported
Analytical Info Exists for Substance: Not reported
Analytical Info Exists for Waste: Not reported
Analytical Info Exists for Leachate: Not reported
Analytical Info Exists for EP Toxicity: Not reported
Analytical Info Exists for TCLP: Not reported

G & L EYES INC. (Continued) **S108146492**

Threat to Environment/Public Health:	None
Surface Water Contamination:	No
Surface Water Body Class:	Unknown
Groundwater Contamination:	No
Groundwater Classification:	Unknown
Drinking Water Contamination:	No
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	No
Hazardous Exposure:	No
Site Has Controlled Acess:	Unknown
Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

K81 **COMMERCIAL BUILDING** **NY Spills** **S118637127**
North **341 39TH STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.103 mi.
544 ft. **Site 3 of 7 in cluster K**

Relative: **Lower**
Actual: **29 ft.**

SPILLS:

Name:	COMMERCIAL BUILDING
Address:	341 39TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1512257 / 2016-04-20
Facility ID:	1512257
Facility Type:	ER
DER Facility ID:	288717
Site ID:	525066
DEC Region:	2
Spill Cause:	Human Error

COMMERCIAL BUILDING (Continued) **S118637127**

Spill Class:	C3
SWIS:	2401
Spill Date:	2016-03-26
Investigator:	SXMAHAT
Referred To:	Not reported
Reported to Dept:	2016-03-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-03-26
Spill Record Last Update:	2016-04-20
Spiller Name:	JANET MCANDRIS
Spiller Company:	HAMPSHIRE COMPANIES
Spiller Address:	341 39TH STREET
Spiller Company:	999
Contact Name:	JANET MCANDRIS
DEC Memo:	Contained to inside the building. All boroughs is cleaning up spill right now. Approved oil's electrician accidentally activated pump during a service call.
Remarks:	3/28/16: Mahat Response: On 3/26/16, DEC Spills staff responded to a reported 1,000 gallon #4 fuel oil. Field Report: Field update on the spill at 341 39th Ave., Brooklyn : The spill area is on the basement of the industrial/commercial building in Brooklyn. The building has two 5,000 gallon ASTs. The PBS registration of the tanks is 2 320617. The building use a transfer pump to transfer oil from tank #1 (4,850 gallons- 68) to tank # 2(1,465 gallons- 25) and vice versa. During the transfer, the tank #1 was overfilled causing the spill from the manhole gasket. Approximately 1,000 gallon of oil was spilled. The spill is contained within the secondary containment. Super of the building was advised to monitor the Petro meter level to insure the tank is not leaking other than from the man way gasket. All Boro (retained by Approved oil) is pumping out the oil from the secondary containment. Once the oil is pumped out, an inspection on the tank will be performed. The gasket on the tank will be replaced followed by the pressure test. No vapor and other resources were impacted. Spill is Contain within the secondary containment. PBS : 2-320617 [Crossed Referenced] Mail: THE HAMPSHIRE COMPANIES 906 MOUNT KEMBLE AVE MORRISTOWN, NJ 07960 Point Of Contact: Eric Supthen [Approved Oil] All Boro [Contractor] JANET MCANDRIS [Management] *** 973.224.6929 jmcandris@hampshireco.com 3/28/16: Mahat Total 500 gallons of oil and wash water was collected from the secondary containment. 3/29/16: Mahat A SCL was sent out. The letter is uploaded on D2 for reference. 4/11/16: Mahat e/c: DEC Mahat received an email update from the contractor: Email: Mr. Mahat, It was a pleasure speaking with you last week regarding 341 39th Street in Brooklyn. I am awaiting the report and disposal documentation from the response contractor (All Borough Testing), although I was provided photographs showing the tank vault was thoroughly steam cleaned. I am also waiting for some additional information from the current building owner, who is under contract to sell the property

COMMERCIAL BUILDING (Continued) **S118637127**

later this month. The owner is requesting information from the purchaser regarding their plans for the heating system and heating oil tanks at the site. Please feel free to contact me with any questions regarding this case. Adam Mickley DEC is waiting a report. 3/12/16: Mahat e/c: DEC Mahat received an email update on the spill case: Email: Mr. Mahat, It was a pleasure speaking with you last week regarding 341 39th Street in Brooklyn. I am awaiting the report and disposal documentation from the response contractor (All Borough Testing), although I was provided photographs showing the tank vault was thoroughly steam cleaned. I am also waiting for some additional information from the current building owner, who is under contract to sell the property later this month. The owner is requesting information from the purchaser regarding their plans for the heating system and heating oil tanks at the site. Please feel free to contact me with any questions regarding this case. Adam Mickley 4/20/16 : Mahat DEC Mahat received an closure report on the spill case. The report consist of Narrative description, manifest, pictures and PBS Application confirmation. A complete report has been uploaded on D2 for reference. Based on the report, site visit and email, the Department does not warrant any further investigation on the spill case.

All Materials:

Site ID:	525066
Operable Unit ID:	1274030
Operable Unit:	01
Material ID:	2278568
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1000.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

K82 **341 39TH ST** **NY AST** **U004077511**
North **341 39TH ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.103 mi.
544 ft. **Site 4 of 7 in cluster K**

Relative: **Lower**

Actual: **29 ft.**

AST:

Name:	341 39TH ST
Address:	341 39TH ST
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-320617
Program Type:	PBS
UTM X:	583940.77705
UTM Y:	4500749.09764
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

341 39TH ST (Continued) **U004077511**

Affiliation Records:

Site Id:	14863
Affiliation Type:	Facility Operator
Company Name:	THE MERHIGE BUILDING
Contact Type:	Not reported
Contact Name:	JERRY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 788-1155
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-07-01

Site Id:	14863
Affiliation Type:	Emergency Contact
Company Name:	341-353 39TH STREET LLC
Contact Type:	Not reported
Contact Name:	JARASLOV JUSACK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 786-8000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-04-06

Site Id:	14863
Affiliation Type:	Facility Owner
Company Name:	341-353 39TH STREET LLC
Contact Type:	MANAGING DIRECTOR
Contact Name:	PHIL LAVOIE
Address1:	825 THIRD AVE 36TH FLOOR
Address2:	Not reported
City:	NY
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(646) 786-8000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-04-06

Site Id:	14863
Affiliation Type:	Mail Contact
Company Name:	SILVERSTONE PROPERTY GROUP
Contact Type:	Not reported
Contact Name:	PHIL LAVOIE

341 39TH ST (Continued) **U004077511**

Address1:	825 THIRD AVE 36TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(646) 786-8000
EMail:	PLAVOIE@SILVERSTONEPG.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-05-18

Tank Info:

Tank Number:	001
Tank Id:	26314
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
H99 - Tank Leak Detection - Other

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1926
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/20/2017
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#6 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	26315
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser

341 39TH ST (Continued) **U004077511**

C03 - Pipe Location - Aboveground/Underground Combination
E02 - Piping Secondary Containment - Vault (with Access)
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G03 - Tank Secondary Containment - Vault (w/o access)
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H99 - Tank Leak Detection - Other

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1926
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/20/2017
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#6 fuel oil (on-site consumption)

J83 **PAVEMENT** **NY Spills** **S110489383**
NNE **38TH ST AND 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.104 mi.
550 ft. **Site 2 of 10 in cluster J**

Relative: SPILLS:
Lower

Actual:
33 ft.

Name:	PAVEMENT
Address:	38TH ST AND 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1004336 / 2010-07-19
Facility ID:	1004336
Facility Type:	ER
DER Facility ID:	392577
Site ID:	437606
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2010-07-19
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2010-07-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

PAVEMENT (Continued) **S110489383**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-07-19
Spill Record Last Update:	2010-07-19
Spiller Name:	Not reported
Spiller Company:	TRACTOR TRAILER TRUCK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	SAME AS ABOVE
DEC Memo:	approx. 20 gallons of diesel spilled onto pavement. Unk how tank was punctured. Clean up is being done at this time.
Remarks:	7/19/10-Vought-Primary off-hours responder. Diesel spill to pavement (concrete) and effects to sewers or drains to be reported to DEP as per procedure. Spill cleaned with absorbent material and closed by Vought.

All Materials:

Site ID:	437606
Operable Unit ID:	1188277
Operable Unit:	01
Material ID:	2183193
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

I84 **CON EDISON - MANHOLE M4101** **RCRA-LQG** **1024891258**
SE **4002 5TH AVE** **NYP005089741**
< 1/8 **BROOKLYN, NY 11232**
0.105 mi.
553 ft. **Site 3 of 9 in cluster I**

Relative: **Higher**
Actual: **85 ft.**

RCRA Listings:

Date Form Received by Agency:	20180410
Handler Name:	Con Edison - Manhole M4101
Handler Address:	5TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP005089741
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported

CON EDISON - MANHOLE M4101 (Continued) **1024891258**

Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years

Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

CON EDISON - MANHOLE M4101 (Continued) **1024891258**

Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170531
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170531
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - MANHOLE M4101
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

I85 **CON EDISON - MANHOLE M4101** **NY MANIFEST** **S121968178**
SE **4002 5TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.105 mi.
553 ft. **Site 4 of 9 in cluster I**

Relative: **Higher**
Actual: **85 ft.**

NY MANIFEST:

EPA ID:	NYP005089741
Country:	USA
Name:	CON EDISON - MANHOLE M4101
Address:	4002 5TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	4002 5TH AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON - MANHOLE M4101
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

J86 **BIG APPLE MOBIL** **EDR Hist Auto** **1021302790**
NNE **984-4TH AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.105 mi.
556 ft. **Site 3 of 10 in cluster J**

Relative: **Lower**
Actual: **31 ft.**

EDR Hist Auto

Year:	Name:	Type:
1986	BIG APPLE MOBIL	Gasoline Service Stations
1987	BIG APPLE MOBIL	Gasoline Service Stations
1988	BIG APPLE MOBIL	Gasoline Service Stations
1989	BIG APPLE MOBIL	Gasoline Service Stations

I87 **CON EDISON** **NJ MANIFEST** **S120674994**
SE **4008 5TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.108 mi.
568 ft. **Site 5 of 9 in cluster I**

Relative: **Higher**
Actual: **89 ft.**

NJ MANIFEST:

EPA ID:	NYP004818763
Name:	CON EDISON
Address:	4008 5TH AVE
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported

CON EDISON (Continued) **S120674994**

Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004818763
Manifest Number:	002619427GBF
Date Shipped:	8/5/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

I88
SE
< 1/8
0.108 mi.
568 ft.

CON EDISON
4008 5TH AVE
BROOKLYN, NY 11232

Site 6 of 9 in cluster I

RCRA NonGen / NLR | **1019906234** | **NYP004818763**

Relative:
Higher

Actual:
89 ft.

RCRA Listings:

Date Form Received by Agency:	20150805
Handler Name:	Con Edison
Handler Address:	5TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004818763
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1019906234**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150805
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150805
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

I89 **CON EDISON** **NY MANIFEST** **S118258630**
SE **4008 5TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.108 mi.
568 ft. **Site 7 of 9 in cluster I**

Relative:
Higher

Actual:
89 ft.

NY MANIFEST:

EPA ID:	NYP004818763
Country:	USA
Name:	CON EDISON
Address:	4008 5TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	4008 5TH AVE
Location Address 2:	SB 45837
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	08/05/2015
Trans1 Recv Date:	08/05/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/08/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004818763
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619427GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **S118258630**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

I90 **CARLINO BROS FINST FRNCH CLRS*** **EDR Hist Cleaner** **1018414690**
ESE **3916 5TH AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.109 mi.
575 ft. **Site 8 of 9 in cluster I**

Relative: EDR Hist Cleaner
Higher

Actual: **82 ft.**

Year:	Name:	Type:
1986	CARLINO BROS CLEANERS	Garment Pressing And Cleaners' Agents
1987	CARLINO BROS CLEANERS	Garment Pressing And Cleaners' Agents
1989	CARLINO BROS FNEST FRENCH CLRS	Drycleaning Plants, Except Rugs
1990	CARLINO BROS FNEST FRENCH CLRS	Drycleaning Plants, Except Rugs
1991	CARLINO BROS FNEST FRENCH CLRS	Drycleaning Plants, Except Rugs
1992	CARLINO BROS FNEST FRENCH CLRS	Drycleaning Plants, Except Rugs
1995	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
1996	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
1997	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
1998	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
1999	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2000	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2001	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2001	CARLINO BROS DNEST FRENCH CLRS	Drycleaning Plants, Except Rugs, NEC
2002	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2002	CARLINO BROS DNEST FRENCH CLRS	Drycleaning Plants, Except Rugs, NEC
2003	CARLINO BROS DNEST FRENCH CLRS	Drycleaning Plants, Except Rugs, NEC
2003	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2004	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2005	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2006	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2007	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2008	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2009	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2010	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2011	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2012	KB DRY CLEANERS	Drycleaning Plants, Except Rugs

CARLINO BROS FINST FRNCH CLRS* (Continued) **1018414690**

2013	KB DRY CLEANERS	Drycleaning Plants, Except Rugs
2014	KB DRY CLEANERS	Drycleaning Plants, Except Rugs

L91 **CON EDISON SERVICE BOX: 48390** **RCRA NonGen / NLR** **1016965509**
West **335 42ND ST** **NY MANIFEST** **NYP004383865**
< 1/8 **BROOKLYN, NY 11232**
0.110 mi.
581 ft. **Site 1 of 6 in cluster L**

Relative: **Lower**
Actual: **41 ft.**

RCRA Listings:

Date Form Received by Agency:	20131130
Handler Name:	Con Edison Service Box: 48390
Handler Address:	42ND ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004383865
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

CON EDISON SERVICE BOX: 48390 (Continued) **1016965509**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131031
Handler Name: CON EDISON SERVICE BOX:	48390
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131130
Handler Name: CON EDISON SERVICE BOX:	48390
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CON EDISON SERVICE BOX: 48390 (Continued) **1016965509**

Evaluations: No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004383865
Country:	USA
Name:	CON EDISON
Address:	335 42ND ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	335 42ND ST
Location Address 2:	MH48390
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/31/2013
Trans1 Recv Date:	10/31/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/31/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004383865
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237267GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

CON EDISON SERVICE BOX: 48390 (Continued) **1016965509**

MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	30
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

M92 **CON EDISON** **NY MANIFEST** **S117061951**
SSW **417 43RD ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.111 mi.
585 ft. **Site 1 of 13 in cluster M**

Relative:
Higher

Actual:
78 ft.

NY MANIFEST:

EPA ID:	NYP004542809
Country:	USA
Name:	CON EDISON
Address:	417 43RD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	FO 417 43RD ST
Location Address 2:	SB 48498
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018

CON EDISON (Continued) **S117061951**

Trans2 State ID:	Not reported
Generator Ship Date:	05/24/2014
Trans1 Recv Date:	05/24/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004542809
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002422011GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

M93 **CON EDISON SERVICE BOX: 48498** **RCRA NonGen / NLR** **1017776422**
SSW **417 43RD ST** **FINDS** **NYP004542809**
< 1/8 **BROOKLYN, NY 11232**
0.111 mi.
585 ft. **Site 2 of 13 in cluster M**

Relative: **Higher**
Actual: **78 ft.**

RCRA Listings:

Date Form Received by Agency:	20140624
Handler Name:	Con Edison Service Box: 48498
Handler Address:	43RD ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004542809
Contact Name:	THOMAS TEELING
Contact Address:	Not reported

CON EDISON SERVICE BOX: 48498 (Continued) **1017776422**

Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

CON EDISON SERVICE BOX: 48498 (Continued) **1017776422**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20140524
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140524
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140624
Handler Name: CON EDISON SERVICE BOX: 48498
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

CON EDISON SERVICE BOX: 48498 (Continued) **1017776422**

FINDS:
Registry ID: 110063768891

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

G94 **4018 5TH AVE** **NY AST** **U003390801**
SE **4018 5TH AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.111 mi.
586 ft. **Site 2 of 6 in cluster G**

Relative: Higher
Actual: 91 ft.

AST:

Name:	4018 5TH AVE
Address:	4018 5TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-327697
Program Type:	PBS
UTM X:	584123.60786
UTM Y:	4500430.39229
Expiration Date:	09/06/2026
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	15316
Affiliation Type:	Mail Contact
Company Name:	5 SUNDET PARK HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	JACK GEULA
Address1:	1 HORIZON WAY
Address2:	Not reported
City:	GREAT NECK
State:	NY
Zip Code:	11024
Country Code:	001
Phone:	(917) 583-4559
EMail:	JGEULA@AOL.COM
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-12-07

Site Id:	15316
Affiliation Type:	Facility Operator
Company Name:	4018 5TH AVE
Contact Type:	Not reported
Contact Name:	FRANK HODGE

4018 5TH AVE (Continued) **U003390801**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 971-5591
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2011-07-05

Site Id:	15316
Affiliation Type:	Emergency Contact
Company Name:	5 SUNSET PARK HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	JACK GEULA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 583-4559
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-12-07

Site Id:	15316
Affiliation Type:	Facility Owner
Company Name:	5 SUNSET PARK HOLDINGS LLC
Contact Type:	MEMBER
Contact Name:	JACK GEULA
Address1:	P.O. BOX 320671
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(917) 583-4559
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2016-04-13

Tank Info:

Tank Number:	001
Tank Id:	20097
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
B00 - Tank External Protection - None

4018 5TH AVE (Continued) **U003390801**

C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1906
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

M95 **CON EDISON** **NJ MANIFEST** **S120674150**
SSW **421 43RD ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.111 mi.
588 ft. **Site 3 of 13 in cluster M**

Relative: **Higher**
Actual: **79 ft.**

NJ MANIFEST:

EPA ID:	NYP004809616
Name:	CON EDISON
Address:	421 43RD ST
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004809616
Manifest Number:	002619692GBF
Date Shipped:	7/20/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047

CON EDISON (Continued) **S120674150**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

M96 **CON EDISON** **RCRA NonGen / NLR** **1019905434**
SSW **421 43RD ST** **FINDS** **NYP004809616**
< 1/8 **BROOKLYN, NY 11232** **ECHO**
0.111 mi.
588 ft. **Site 4 of 13 in cluster M**

Relative:
Higher

Actual:
79 ft.

RCRA Listings:

Date Form Received by Agency:	20150720
Handler Name:	Con Edison
Handler Address:	43RD ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004809616
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private

CON EDISON (Continued) **1019905434**

Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150720

CON EDISON (Continued) **1019905434**

Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150720
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069679137

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019905434
Registry ID: 110069679137
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069679137
Name: CON EDISON

CON EDISON (Continued) **1019905434**

Address: 421 43RD ST
City,State,Zip: BROOKLYN, NY 11232

M97 **CON EDISON** **NY MANIFEST** **S118258049**
SSW **421 43RD ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.111 mi.
588 ft. **Site 5 of 13 in cluster M**

Relative:
Higher

Actual:
79 ft.

NY MANIFEST:

EPA ID:	NYP004809616
Country:	USA
Name:	CON EDISON
Address:	421 43RD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	421 43RD ST
Location Address 2:	SB 48498
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/20/2015
Trans1 Recv Date:	07/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/22/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004809616
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619692GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118258049**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

K98 **DAVIDSON PIPE SUPPLY CO INC** **NY AST** **U003383286**
NNW **39TH STREET/THIRD AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.112 mi.
589 ft. **Site 5 of 7 in cluster K**

Relative: **Lower**

Actual: **25 ft.**

AST:

Name:	DAVIDSON PIPE SUPPLY CO INC
Address:	39TH STREET/THIRD AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000787
Program Type:	PBS
UTM X:	583903.93414
UTM Y:	4500754.77937
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	9
Affiliation Type:	Facility Owner
Company Name:	DAVIDSON PIPE SUPPLY CO INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	5002 SECOND AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001

DAVIDSON PIPE SUPPLY CO INC (Continued) **U003383286**

Phone:	(718) 439-6300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9
Affiliation Type:	Mail Contact
Company Name:	DAVIDSON PIPE SUPPLY CO INC
Contact Type:	Not reported
Contact Name:	STUART L. KRUEGER
Address1:	5002 SECOND AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(718) 439-6300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9
Affiliation Type:	Facility Operator
Company Name:	DAVIDSON PIPE SUPPLY CO INC
Contact Type:	Not reported
Contact Name:	DAVIDSON PIPE SUPPLY CO INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 439-6300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9
Affiliation Type:	Emergency Contact
Company Name:	DAVIDSON PIPE SUPPLY CO INC
Contact Type:	Not reported
Contact Name:	DAN SPECTOR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 678-4450
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

DAVIDSON PIPE SUPPLY CO INC (Continued) **U003383286**

Tank Info:

Tank Number:	101
Tank Id:	694
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	J02 - Dispenser - Suction Dispenser
	C03 - Pipe Location - Aboveground/Underground Combination
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	G99 - Tank Secondary Containment - Other
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	H99 - Tank Leak Detection - Other
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed Prior to Micro Conversion, 03/91
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	102
Tank Id:	695
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

	I04 - Overfill - Product Level Gauge (A/G)
	C03 - Pipe Location - Aboveground/Underground Combination
	J02 - Dispenser - Suction Dispenser
	B00 - Tank External Protection - None
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	G99 - Tank Secondary Containment - Other
	H99 - Tank Leak Detection - Other
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed Prior to Micro Conversion, 03/91
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550

DAVIDSON PIPE SUPPLY CO INC (Continued) **U003383286**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	103
Tank Id:	696
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed Prior to Micro Conversion, 03/91
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

G99 **CON EDISON** **NY MANIFEST** **S118088967**
SSE **4108 5TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.117 mi.
618 ft. **Site 3 of 6 in cluster G**

Relative:
Higher

Actual:
92 ft.

NY MANIFEST:

EPA ID:	NYP004765558
Country:	USA
Name:	CON EDISON
Address:	4108 5TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	4108 5TH AVE
Location Address 2:	SB 45840

CON EDISON (Continued) **S118088967**

Location City,State,Zip: BROOKLYN, NY 11201
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 04/09/2015
Trans1 Recv Date: 04/09/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/13/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004765558
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002619181GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported

CON EDISON (Continued) **S118088967**

Quantity:	1000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

G100 **CON EDISON** **RCRA NonGen / NLR** **1019901746**
SSE **4108 5TH AVE** **FINDS** **NYP004765558**
< 1/8 **BROOKLYN, NY 11232** **ECHO**
0.117 mi.
618 ft. **Site 4 of 6 in cluster G**

Relative: **Higher**
Actual: **92 ft.**

RCRA Listings:

Date Form Received by Agency:	20150409
Handler Name:	Con Edison
Handler Address:	5TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004765558
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN

CON EDISON (Continued) **1019901746**

Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150409
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150409
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

CON EDISON (Continued) **1019901746**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069656562

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019901746
Registry ID:	110069656562
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069656562
Name:	CON EDISON
Address:	4108 5TH AVE
City,State,Zip:	BROOKLYN, NY 11232

G101 **CON EDISON** **NJ MANIFEST** **S120670269**
SSE **4108 5TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.117 mi.
618 ft. **Site 5 of 6 in cluster G**

Relative: Higher
Actual: 92 ft.

NJ MANIFEST:

EPA ID:	NYP004765558
Name:	CON EDISON
Address:	4108 5TH AVE
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported

CON EDISON (Continued) **S120670269**

Date Change:	Not reported
Manifest Data:	
EPA ID:	NYP004765558
Manifest Number:	002619181GBF
Date Shipped:	4/9/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

M102 **CON EDISON** **RCRA NonGen / NLR** **1017777086**
SSW **437 43RD ST** **FINDS** **NYP004549721**
< 1/8 **BROOKLYN, NY 11232**
0.118 mi.
621 ft. **Site 6 of 13 in cluster M**

Relative:
Higher

Actual:
87 ft.

RCRA Listings:

Date Form Received by Agency:	20150615
Handler Name:	Con Edison
Handler Address:	43RD ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004549721
Contact Name:	THOMAS TEELING

CON EDISON (Continued) **1017777086**

Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

CON EDISON (Continued) **1017777086**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20150615
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150615
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140702
Handler Name: CON EDISON SERVICE BOX: 48500
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

CON EDISON (Continued) **1017777086**

FINDS:
Registry ID: 110063819532

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

M103 **CON EDISON** **NY MANIFEST** **S117062604**
SSW **437 43RD ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.118 mi.
621 ft. **Site 7 of 13 in cluster M**

Relative: **Higher**
Actual: **87 ft.**

NY MANIFEST:

EPA ID:	NYP004549721
Country:	USA
Name:	CON EDISON
Address:	437 43RD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	437 43 ST
Location Address 2:	SB 48500
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	06/02/2014
Trans1 Recv Date:	06/02/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/03/2014
Part A Recv Date:	Not reported

CON EDISON (Continued) **S117062604**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004549721
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245932JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

EPA ID:	NYP004794343
Country:	USA
Name:	CON EDISON
Address:	437 43RD ST
Address 2:	SB 48500
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	437 43RD ST
Location Address 2:	SB 48500
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported

CON EDISON (Continued) **S117062604**

Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	06/15/2015
Trans1 Recv Date:	06/15/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/15/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004794343
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624511GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	200
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

J104 **PUBLIC SCHOOL 24 - BROOKLYN (K024)** **NY AST** **A100157707**
NE **427 38TH STREET** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.119 mi.
626 ft. **Site 4 of 10 in cluster J**

Relative:
Lower

Actual:
48 ft.

AST:

Name:	PUBLIC SCHOOL 24 - BROOKLYN (K024)
Address:	427 38TH STREET
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-604352
Program Type:	PBS
UTM X:	584147.54694
UTM Y:	4500689.91211
Expiration Date:	12/13/2024
Site Type:	School

Affiliation Records:

Site Id:	26227
Affiliation Type:	Facility Operator
Company Name:	PUBLIC SCHOOL 24 - BROOKLYN (K024)
Contact Type:	Not reported
Contact Name:	RICHARD AFFITO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 788-0860
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-01-22

Site Id:	26227
Affiliation Type:	Mail Contact
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	JOSEPH YOUNGHESE
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5779
EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-01-25

Site Id:	26227
Affiliation Type:	Facility Owner
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	YOGESHWAR NARINE

PUBLIC SCHOOL 24 - BROOKLYN (K024) (Continued) **A100157707**

Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 610-0118
EMail:	YNARINE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-08-13

Site Id:	26227
Affiliation Type:	Emergency Contact
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	KEN MAHADEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-02-04

Tank Info:

Tank Number:	001
Tank Id:	57436
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
I02 - Overfill - High Level Alarm
E00 - Piping Secondary Containment - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
G02 - Tank Secondary Containment - Vault (w/access)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported

PUBLIC SCHOOL 24 - BROOKLYN (K024) (Continued) **A100157707**

Install Date:	05/07/1993
Capacity Gallons:	10000
Tightness Test Method:	34
Date Test:	07/06/2023
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	LABATIST
Last Modified:	08/22/2023
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	57437
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
J02 - Dispenser - Suction Dispenser
I02 - Overfill - High Level Alarm
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
G02 - Tank Secondary Containment - Vault (w/access)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/07/1993
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

J105 **971-975 4TH AVE.** **UST FINDER RELEASE** **1029056564**
NNE **971 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY 0**
0.119 mi.
628 ft. **Site 5 of 10 in cluster J**

Relative: **Lower**
Actual: **37 ft.**

UST FINDER RELEASE:

Object ID:	255880
Facility ID:	NY100751
Lust ID:	NY9207015
Name:	971-975 4TH AVE.
Address:	971 4TH AVE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1992/09/17 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	8773
Domestic Wells within 1500ft:	16
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-74.00512
Y Coord:	40.6534500000001
Latitude:	40.6534499999999
Longitude:	-74.00512

J106 **971-975 4TH AVE.** **NY LTANKS** **S100494031**
NNE **971 4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.119 mi.
628 ft. **Site 6 of 10 in cluster J**

Relative: **Lower**
Actual: **37 ft.**

LTANKS:

Name:	971-975 4TH AVE.
Address:	971 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9207015 / 2006-07-13
Facility ID:	9207015
Site ID:	115646
Spill Date:	1992-09-17
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility

971-975 4TH AVE. (Continued) **S100494031**

Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JAQUINN
Referred To:	Not reported
Reported to Dept:	1992-09-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-09-18
Spill Record Last Update:	2006-07-13
Spiller Name:	Not reported
Spiller Company:	SCA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	100751
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL C 3/11/03 - SAMUEL- File available in active unassigned spill files. 04/12/04 TRANSFERRD FROM ODOWD TO ROMMEL. 1/10/2006 - Haggerty - Leigh Gutterman from NYC School Construction (718-472-8502) is locating necessary reports. She is requesting another week to find them 7/13/2006 - Haggerty - Leigh Gutterman from NYC School Construction mailed closure report on June 7, 2006. The report essentially is the original from 13 years ago. NYC School Construction included new groundwater samples (March 2006) to hopefully provide proof the site has been remediated. In 1993, 44 UST's were removed along with 15,000 cubic yards of petroleum contaminated soil which were properly disposed of. Due to the N,R subway running underneath 4th Avenue to the west of the property, excavation was restricted. All accessible soil was excavated. Post-excavation soil samples contain VOC's and SVOC's above TAGM mostly in the area adjacent to 4th Avenue. However, the time passed since the soil samples were taken as well as the fact that the recent groundwater samples are below TAGM, DEC has decided to close the spill.
Remarks:	SUSPECT ABOUT 35 YRS OLD GASOLINE TANKS AT SITE RANDY AUSTIN IS AWARE OF SITE.

All Materials:

Site ID:	115646
Operable Unit ID:	974037
Operable Unit:	01
Material ID:	407689
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L

971-975 4TH AVE. (Continued) **S100494031**

Recovered: .00
Resource Affected: Groundwater
Oxygenate: Not reported

K107 **CON EDISON SERVICE BOX: 49200** **RCRA NonGen / NLR** **1016966389**
NNW **331 39TH ST** **NY MANIFEST** **NYP004392395**
< 1/8 **BROOKLYN, NY 11232**
0.120 mi.
636 ft. **Site 6 of 7 in cluster K**

Relative: **Lower**
Actual: **22 ft.**

RCRA Listings:

Date Form Received by Agency:	20131215
Handler Name:	Con Edison Service Box: 49200
Handler Address:	39TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004392395
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline

CON EDISON SERVICE BOX: 49200 (Continued) **1016966389**

202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131115
Handler Name: CON EDISON SERVICE BOX:	49200
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131215
Handler Name: CON EDISON SERVICE BOX:	49200
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON SERVICE BOX: 49200 (Continued) **1016966389**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004392395
Country:	USA
Name:	CON EDISON
Address:	331 39TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	331 39TH ST
Location Address 2:	SB49200
Location City,State,Zip:	BROOKLYN, NY 11215
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/15/2013
Trans1 Recv Date:	11/15/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004392395
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299030GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON SERVICE BOX: 49200 (Continued) **1016966389**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	150
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

L108 **2- FAMILY HOME** **NY Spills** **S108297211**
WNW **324 41ST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.121 mi.
637 ft. **Site 2 of 6 in cluster L**

Relative: **Lower**
Actual: **32 ft.**

SPILLS:

Name:	2- FAMILY HOME
Address:	324 41ST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0611029 / 2007-06-27
Facility ID:	0611029
Facility Type:	ER
DER Facility ID:	325217
Site ID:	375595
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2007-01-03
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2007-01-03
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-03
Spill Record Last Update:	2007-06-27

2- FAMILY HOME (Continued) **S108297211**

Spiller Name: BOB SNYDER
Spiller Company: 2- FAMILY HOME
Spiller Address: 324 41ST STREET
Spiller Company: 001
Contact Name: BOB SNYDER
DEC Memo: CLEANED UP FROM GAUGE MALFUNCTION
Remarks: Piper contacted blue diamond and spoke w/ Bob Sntder. Bob stated that 15 gallons spilled to due a broken gauge. He then stated that he has a crew there now. Piper asked for homowners #, 718-499-2203. Piper called though no one answered. Piper responded to the site due to major discrepancies in Bob's story. Upon arrival 3 Blue Diamond work vans outside residence and 12' diameter oil soaked speedy dry present in roadway. Piper entered basement residence to discover Diamond Oil personell removing carpeting in bedroom. Major spill across the basement level floor. The tech was sqeegeeing oil from carpet in 5 gallon pails. Tech stated that what was spilled outside as well and a representative will be arriving shortly. Piper entered though another room where carpet was removed though old tile and wood was present that was broken and soaked in oil. The floor may be a raised floor. Requirements to follow notes. Speedy dry covered the remainder of the room. Piper inspected tank area which was behind concrete block and sheet rock. Blue diamond had already opened hole with a sledge hammer in boiler room where it was cemented painted and unaffected. Spill was behind walls of basement apartment. Piper observed where gauge was blown off due to overfill. Tech stated the construction noise was high and could not hear whistle. Oil soaked speedy dry was dumped around tank and ample amounts of sweet air was spread as well. Bob Snyner arrived on site as rep for Blue diamond. He has not seen the spill scene though he had certified tech out her that said it was 15 gallons. Piper stated he was misinformed and that a professional contractor needs to be hired. Bob hired PTC to respond for demo of basement. Bob stated that he was not going to deal with 3rd party damages because it is an illegal apartment. Piper stated it is not my concern weather it is or not my concern is that the oil is cleaned and the owners house is restored. Requirements are to remove all contaminated debris, relocate tenants, restore property. PTC arrived on site and removed 17 drums by 400. They wil return tomorrow. 1/4/06- DEC Piper received call from Firemans Fund (Insurer)Ray Bootin 732-477-0084, they are taking full responsibilty for spill and will clean. Cooperation is expected. Piper agreed. Firemans fund hired action Env as consultant. Steve Bouton 518- 441-7130. He will meet Piper on site at 2pm. 6/20/07- DEC Piper spoke w. Steve Bouton and he will send closure report. SOils have been excavated, sampled, backfilled and a new slab has been poured and sealed. 6/27/07- DEC Piper recieved and reviewed closure request. Based on remedial efforts and analytical endpoint results to date, no further action is granted. This spill is closed. See e-docs if warranted/

All Materials:
Site ID: 375595
Operable Unit ID: 1133216
Operable Unit: 01
Material ID: 2123020
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 15.00

2- FAMILY HOME (Continued) **S108297211**

Units: G
Recovered: 15.00
Resource Affected: Soil
Oxygenate: Not reported

N109 **CON EDISION** **NY MANIFEST** **S116550329**
NW **317 40TH ST** **N/A**
< 1/8 **BROOKLYN, NY 11232**
0.121 mi.
640 ft. **Site 1 of 2 in cluster N**

Relative:
Lower

Actual:
27 ft.

NY MANIFEST:
EPA ID: NYP004486973
Country: USA
Name: CON EDISION
Address: 317 40TH ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: 317 40 ST
Location Address 2: SB49278
Location City,State,Zip: BROOKLYN, NY 11201
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISION
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 04/02/2014
Trans1 Recv Date: 04/02/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/07/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004486973
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012354187JJK
Import Indicator: N
Export Indicator: N

CON EDISION (Continued) **S116550329**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

N110 **CON EDISON** **RCRA NonGen / NLR** **1017771752**
NW **317 40TH ST** **FINDS** **NYP004486973**
< 1/8 **BROOKLYN, NY 11232**
0.121 mi.
640 ft. **Site 2 of 2 in cluster N**

Relative: **Lower**
Actual: **27 ft.**

RCRA Listings:

Date Form Received by Agency:	20151230
Handler Name:	Con Edison
Handler Address:	40TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004486973
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE

CON EDISON (Continued) **1017771752**

Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151230
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON (Continued) **1017771752**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20151230
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140502
Handler Name: CON EDISON SERVICE BOX: 49278
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063796343

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

I111 **CON EDISON SERVICE BOX: 7759** **RCRA NonGen / NLR** **1017774822**
ESE **E 40TH ST & 5TH AVE E OF** **FINDS** **NYP004526406**
< 1/8 **NEW YORK, NY 10016**
0.121 mi.
640 ft. **Site 9 of 9 in cluster I**

Relative:
Higher

Actual:
87 ft.

RCRA Listings:

Date Form Received by Agency:	20140608
Handler Name:	Con Edison Service Box: 7759
Handler Address:	E 40TH ST & 5TH AVE E OF
Handler City,State,Zip:	NEW YORK, NY 10016
EPA ID:	NYP004526406
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 7759 (Continued) **1017774822**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140508
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140508
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140608
Handler Name: CON EDISON SERVICE BOX: 7759	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 7759 (Continued) **1017774822**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063794988

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

J112 **VAULT 3225** **NY Spills** **S104195919**
NE **38TH ST/4TH AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.123 mi.
647 ft. **Site 7 of 10 in cluster J**

Relative:
Lower

Actual:
42 ft.

SPILLS:

Name:	VAULT 3225
Address:	38TH ST/4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9908076 / 2002-02-20
Facility ID:	9908076
Facility Type:	ER
DER Facility ID:	181446
Site ID:	219409
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D3
SWIS:	2401
Spill Date:	1999-10-03
Investigator:	COMENALE
Referred To:	Not reported
Reported to Dept:	1999-10-03
CID:	323
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

VAULT 3225 (Continued) **S104195919**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-03
Spill Record Last Update:	2002-02-20
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	FRANK MESSERIA
DEC Memo:	ON 2500 GALLONS OF WATER, THERE IS A SHEEN OF UNDIAPERABLE PRODUCT. SAMPLE TAKEN, CLEAN UP PENDING. CON ED# 128211
Remarks:	Not reported

All Materials:

Site ID:	219409
Operable Unit ID:	1082353
Operable Unit:	01
Material ID:	300759
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

J113 **4TH AVE.AND 38TH ST./ GAS** **NY LTANKS** **S102671137**
NE **4TH AVE AND 38THST.** **N/A**
< 1/8 **NYC, NY**
0.123 mi.
647 ft. **Site 8 of 10 in cluster J**

Relative:
Lower

Actual:
42 ft.

LTANKS:

Name:	4TH AVE.AND 38TH ST./ GAS
Address:	4TH AVE AND 38THST.
City,State,Zip:	NYC, NY
Spill Number/Closed Date:	8606188 / 1987-01-04
Facility ID:	8606188
Site ID:	214911
Spill Date:	1987-01-04
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1987-01-04
SWIS:	2401
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1987-01-04
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

4TH AVE.AND 38TH ST./ GAS (Continued) **S102671137**

UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-02-10
Spill Record Last Update:	1988-02-17
Spiller Name:	Not reported
Spiller Company:	ISLAND TRANSPORTATION
Spiller Address:	AT MERRIT A
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	178048
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN
Remarks:	SPILL WENT INTO DRY WELL, CLEAN UP BY SPILLER

All Materials:

Site ID:	214911
Operable Unit ID:	902983
Operable Unit:	01
Material ID:	475321
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	55.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

G114 **BELCHER SPILL INTO HARLEM** **NY Spills** **S102144230**
SE **4095 5TH AVE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.123 mi.
648 ft. **Site 6 of 6 in cluster G**

Relative:
Higher

Actual:
94 ft.

SPILLS:

Name:	BELCHER SPILL INTO HARLEM
Address:	4095 5TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8605453 / 1986-11-28
Facility ID:	8605453
Facility Type:	ER
DER Facility ID:	167957
Site ID:	201860
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3101
Spill Date:	1986-11-28
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1986-11-28
CID:	Not reported
Water Affected:	HARLEM RIVER

BELCHER SPILL INTO HARLEM (Continued) **S102144230**

Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	1986-11-28
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-12-08
Spill Record Last Update:	2006-10-13
Spiller Name:	Not reported
Spiller Company:	BELCHER OIL CO.
Spiller Address:	SAME
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	BOOM WAS PLACED AROUND THE SPILL
Remarks:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was 10/13/06 - Austin - This spill was originally managed by Anthony Sigona. Files for this are in the MOSF file archives, in the old storage room in the basement of Region 2 office. - end

All Materials:

Site ID:	201860
Operable Unit ID:	902423
Operable Unit:	01
Material ID:	571062
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	-1.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

L115 **JOKHAN RESIDENCE** **NY Spills** **S107488831**
WNW **322 41ST STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.124 mi.
656 ft. **Site 3 of 6 in cluster L**

Relative: **Lower**
Actual: **31 ft.**

SPILLS:

Name:	JOKHAN RESIDENCE
Address:	322 41ST STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0510380 / 2005-12-06
Facility ID:	0510380
Facility Type:	ER
DER Facility ID:	306406
Site ID:	356347
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2005-12-03
Investigator:	JBVOUGHT

JOKHAN RESIDENCE (Continued) **S107488831**

Referred To:	Not reported
Reported to Dept:	2005-12-03
CID:	72
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-03
Spill Record Last Update:	2005-12-06
Spiller Name:	RAWATEE JOKHAN
Spiller Company:	JOKHAN RESIDENCE
Spiller Address:	322 41ST STREET
Spiller Company:	001
Contact Name:	RAWATEE JOKHAN
DEC Memo:	Not reported
Remarks:	12/05/05-Vought-Off hours duty responder. Vought called and spoke to Badsi Jokhan and spill to store and occurred on 11/31/05. Vought called Billy Romanello and spoke to Joey and site visit was performed on 12/4/05 and film of oil in sewer. DEP contacted with respect to sewer. Joe hadnt heard of vapor complaint or indoor spill so he will call Billy and return call to DEC. Vought called Badsi and left message to return call to DEC. Vought called Joey again who will return call with spill status. 12/06/05-Vought-Received call from Billy Romanello and he had crew who visited site and found oil in sewer. No oil around tank and no oil from vent pipe. No spill inside residence. Spill closed by Vought. Spill will be reopened if second call from owner complaining of vapors.

All Materials:

Site ID:	356347
Operable Unit ID:	1113654
Operable Unit:	01
Material ID:	2103720
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

J116 **MERIT FOURTH** **RCRA NonGen / NLR** **1000263796**
NNE **969 4TH AVE** **FINDS** **NYD982185910**
1/8-1/4 **BROOKLYN, NY 11232** **ECHO**
0.125 mi.
662 ft. **Site 9 of 10 in cluster J**

Relative: **Lower**
Actual: **37 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Merit Oil Corp
Handler Address:	4TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYD982185910
Contact Name:	Not reported
Contact Address:	W LANCASTER AVE
Contact City,State,Zip:	HAVERFORD, NY 19041
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	W LANCASTER AVE
Mailing City,State,Zip:	HAVERFORD, NY 19041
Owner Name:	Merit Oil Corp
Owner Type:	Private
Operator Name:	Merit Oil Corp
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

MERIT FOURTH (Continued) **1000263796**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	NONE
Waste Description:	None

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

MERIT FOURTH (Continued) **1000263796**

Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19951005
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19870511
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

MERIT FOURTH (Continued) **1000263796**

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004416070

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000263796
Registry ID: 110004416070
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004416070
Name: MERIT FOURTH
Address: 969 4TH AVE
City,State,Zip: BROOKLYN, NY 11232

O117 **CON EDISON SERVICE BOX: 70349** **RCRA NonGen / NLR** **1016971675**
WSW **361 43RD ST** **NY MANIFEST** **NYP004454187**
1/8-1/4 **BROOKLYN, NY 11232**
0.127 mi.
669 ft. **Site 1 of 9 in cluster O**

Relative:
Higher

Actual:
54 ft.

RCRA Listings:
Date Form Received by Agency: 20140327
Handler Name: Con Edison Service Box: 70349
Handler Address: 43RD ST
Handler City,State,Zip: BROOKLYN, NY 11232
EPA ID: NYP004454187

CON EDISON SERVICE BOX: 70349 (Continued) **1016971675**

Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

CON EDISON SERVICE BOX: 70349 (Continued) **1016971675**

Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20140227
Handler Name: CON EDISON SERVICE BOX: 70349
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140327
Handler Name: CON EDISON SERVICE BOX: 70349
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004454187
Country: USA
Name: CON EDISON
Address: 361 43RD ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: 362 43RD & 3RD AVE
Location Address 2: SB70349
Location City,State,Zip: BROOKLYN, NY 11201

CON EDISON SERVICE BOX: 70349 (Continued) **1016971675**

Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/27/2014
Trans1 Recv Date:	02/27/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004454187
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694373JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50

CON EDISON SERVICE BOX: 70349 (Continued) **1016971675**

Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

O118 **CON EDISON** **NY MANIFEST** **S117066081**
WSW **359 43 ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.127 mi.
671 ft. **Site 2 of 9 in cluster O**

Relative:
Higher

Actual:
54 ft.

NY MANIFEST:

EPA ID:	NYP004586993
Country:	USA
Name:	CON EDISON
Address:	359 43 ST
Address 2:	SB48931
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	359 43 ST
Location Address 2:	SB48931
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

O119 **CON EDISON** **NY MANIFEST** **S117063685**
WSW **365 43RD ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.128 mi.
675 ft. **Site 3 of 9 in cluster O**

Relative:
Higher

Actual:
58 ft.

NY MANIFEST:

EPA ID:	NYP004561239
Country:	USA
Name:	CON EDISON
Address:	365 43RD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11220
Zip 4:	Not reported
Location Address 1:	OPP 365 43 ST
Location Address 2:	SB 70349
Location City,State,Zip:	BROOKLYN, NY 11232

CON EDISON (Continued) **S117063685**

Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 06/11/2014
Trans1 Recv Date: 06/11/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/11/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004561239
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002424490GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 50

CON EDISON (Continued) **S117063685**

Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

O120 **CON EDISON SERVICE BOX: 70349** **RCRA NonGen / NLR** **1017778200**
WSW **365 43RD ST** **FINDS** **NYP004561239**
1/8-1/4 **BROOKLYN, NY 11220**
0.128 mi.
675 ft. **Site 4 of 9 in cluster O**

Relative: **Higher**

Actual: **58 ft.**

RCRA Listings:

Date Form Received by Agency:	20140711
Handler Name:	Con Edison Service Box: 70349
Handler Address:	43RD ST
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NYP004561239
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported

CON EDISON SERVICE BOX: 70349 (Continued) **1017778200**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140611
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140611
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140711
Handler Name: CON EDISON SERVICE BOX:	70349
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No

CON EDISON SERVICE BOX: 70349 (Continued) **1017778200**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063833044

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

P121 **CON EDISON SERVICE BOX: 48503** **RCRA NonGen / NLR** **1016964416**
South **453 43RD ST** **NY MANIFEST** **NYP004373429**
1/8-1/4 **BROOKLYN, NY 11229**
0.129 mi.
681 ft. **Site 1 of 10 in cluster P**

Relative: **Higher**
Actual: **95 ft.**

RCRA Listings:

Date Form Received by Agency:	20131111
Handler Name:	Con Edison Service Box: 48503
Handler Address:	43RD ST
Handler City,State,Zip:	BROOKLYN, NY 11229
EPA ID:	NYP004373429
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CON EDISON SERVICE BOX: 48503 (Continued) **1016964416**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131011
Handler Name: CON EDISON SERVICE BOX:	48503
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator

CON EDISON SERVICE BOX: 48503 (Continued) **1016964416**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131111
Handler Name: CON EDISON SERVICE BOX: 48503
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004373429
Country: USA
Name: CON EDISON
Address: 453 43RD ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11229
Zip 4: Not reported
Location Address 1: 453 43 ST
Location Address 2: SERVICE BOX # 48503
Location City,State,Zip: BROOKLYN, NY 11209
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported

CON EDISON SERVICE BOX: 48503 (Continued) **1016964416**

Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/11/2013
Trans1 Recv Date:	10/11/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004373429
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002236533GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

L122 **CON EDISON SERVICE BOX: 48289** **RCRA NonGen / NLR** **1016965508**
West **319 42ND ST** **NY MANIFEST** **NYP004383857**
1/8-1/4 **BROOKLYN, NY 11232**
0.129 mi.
683 ft. **Site 4 of 6 in cluster L**

Relative: **Lower**
Actual: **34 ft.**

RCRA Listings:

Date Form Received by Agency:	20131130
Handler Name:	Con Edison Service Box: 48289
Handler Address:	42ND ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004383857
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 48289 (Continued) **1016965508**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131031
Handler Name: CON EDISON SERVICE BOX:	48289
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131130
Handler Name: CON EDISON SERVICE BOX:	48289
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 48289 (Continued) **1016965508**

NY MANIFEST:

EPA ID:	NYP004383857
Country:	USA
Name:	CON EDISON
Address:	319 42ND ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	319 42ND ST
Location Address 2:	SB483389
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/31/2013
Trans1 Recv Date:	10/31/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/31/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004383857
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237207GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported

CON EDISON SERVICE BOX: 48289 (Continued) **1016965508**

Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	30
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

H123 **884 FIFTH AVENUE** **NY AST** **A100301004**
East **884 FIFTH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.129 mi.
683 ft. **Site 2 of 2 in cluster H**

Relative:
Higher

Actual:
74 ft.

AST:

Name:	884 FIFTH AVENUE
Address:	884 FIFTH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-608715
Program Type:	PBS
UTM X:	584220.12162
UTM Y:	4500552.69251
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30567
Affiliation Type:	Facility Owner
Company Name:	884 FIFTH REALTY, LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	114 BROWN ROAD
Address2:	Not reported
City:	SCARSDALE
State:	NY
Zip Code:	10583
Country Code:	001
Phone:	(212) 908-0688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	30567
Affiliation Type:	Mail Contact

884 FIFTH AVENUE (Continued) **A100301004**

Company Name:	884 FIFTH REALTY, LLC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	114 BROWN ROAD
Address2:	Not reported
City:	SCARSDALE
State:	NY
Zip Code:	10583
Country Code:	001
Phone:	(212) 908-0688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	30567
Affiliation Type:	Facility Operator
Company Name:	884 FIFTH AVENUE
Contact Type:	Not reported
Contact Name:	ELIDIO SANTIAGO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 686-0459
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	30567
Affiliation Type:	Emergency Contact
Company Name:	884 FIFTH REALTY, LLC
Contact Type:	Not reported
Contact Name:	VIOLA FONG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 908-0688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank Id:	65558
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

884 FIFTH AVENUE (Continued) **A100301004**

Equipment Records:

D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/20/2003
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Q124 **CON EDISON SERVICE BOX: 7520** **RCRA NonGen / NLR** **1017774687**
ESE **16-18 E 39TH ST & 5TH AVE E OF** **FINDS** **NYP004525010**
1/8-1/4 **NEW YORK, NY 10016**
0.134 mi.
705 ft. **Site 1 of 9 in cluster Q**

Relative: **Higher**

Actual: **77 ft.**

RCRA Listings:

Date Form Received by Agency:	20140607
Handler Name:	Con Edison Service Box: 7520
Handler Address:	E 39TH ST & 5TH AVE E OF
Handler City,State,Zip:	NEW YORK, NY 10016
EPA ID:	NYP004525010
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported

CON EDISON SERVICE BOX: 7520 (Continued) **1017774687**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140507
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 7520 (Continued) **1017774687**

Electronic Manifest Broker: Not reported

Receive Date: 20140507
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140607
Handler Name: CON EDISON SERVICE BOX: 7520
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063785523

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

M125
SSW
1/8-1/4
0.136 mi.
716 ft.

CON EDISON
418 43RD ST
BROOKLYN, NY 11232

Site 8 of 13 in cluster M

NY MANIFEST **S117536695**
N/A

Relative:
Higher

Actual:
79 ft.

NY MANIFEST:

EPA ID:	NYP004691838
Country:	USA
Name:	CON EDISON
Address:	418 43RD ST
Address 2:	SB 48499
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	418 43RD ST
Location Address 2:	SB 48499
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/07/2014
Trans1 Recv Date:	11/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/18/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004691838
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416938GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **S117536695**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

M126 **CON EDISON** **NY MANIFEST** **S117537293**
SSW **FRONT OF 418 43 ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.136 mi.
716 ft. **Site 9 of 13 in cluster M**

Relative: **Higher**

Actual: **79 ft.**

NY MANIFEST:

EPA ID:	NYP004698379
Country:	USA
Name:	CON EDISON
Address:	FRONT OF 418 43 ST
Address 2:	SB48499
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	FRONT OF 418 43 ST
Location Address 2:	SB48499
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047

CON EDISON (Continued) **S117537293**

Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/21/2014
Trans1 Recv Date:	11/21/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004698379
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002618321GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

M127 **CON EDISON** **NY MANIFEST** **S117064629**
SSW **418 43RD ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.136 mi.
716 ft. **Site 10 of 13 in cluster M**

Relative: NY MANIFEST:
Higher

EPA ID:	NYP004571279
Country:	USA
Name:	CON EDISON
Address:	418 43RD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232

Actual:
79 ft.

CON EDISON (Continued) **S117064629**

Zip 4: Not reported
Location Address 1: 418 43 ST
Location Address 2: STRUCTURE 48499
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 06/20/2014
Trans1 Recv Date: 06/20/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/24/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004571279
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002424344GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported

CON EDISON (Continued) **S117064629**

Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

M128 **CON EDISON SERVICE BOX: 48499** **RCRA NonGen / NLR** **1017779149**
SSW **418 43RD ST** **NYP004571279**
1/8-1/4 **BROOKLYN, NY 11232**
0.136 mi.
716 ft. **Site 11 of 13 in cluster M**

Relative: **Higher**
Actual: **79 ft.**

RCRA Listings:

Date Form Received by Agency:	20140720
Handler Name:	Con Edison Service Box: 48499
Handler Address:	43RD ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004571279
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

CON EDISON SERVICE BOX: 48499 (Continued) **1017779149**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140620
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140620
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140720

CON EDISON SERVICE BOX: 48499 (Continued) **1017779149**

Handler Name:	CON EDISON SERVICE BOX: 48499
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

R129 **CON EDISON SERVICE BOX: 45835** **RCRA NonGen / NLR** **1016964991**
SE **4023 5TH AVE** **NY MANIFEST** **NYP004378881**
1/8-1/4 **BROOKLYN, NY 11232**
0.136 mi.
720 ft. **Site 1 of 4 in cluster R**

Relative: **Higher**

Actual: **99 ft.**

RCRA Listings:

Date Form Received by Agency:	20131123
Handler Name:	Con Edison Service Box: 45835
Handler Address:	5TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004378881
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported

CON EDISON SERVICE BOX: 45835 (Continued) **1016964991**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131023
Handler Name: CON EDISON SERVICE BOX:	45835
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131123

CON EDISON SERVICE BOX: 45835 (Continued) **1016964991**

Handler Name: CON EDISON SERVICE BOX: 45835
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004378881
Country: USA
Name: CON EDISON
Address: 4023 5TH AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: 4023 5TH AVE
Location Address 2: SB45835
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 10/23/2013

CON EDISON SERVICE BOX: 45835 (Continued) **1016964991**

Trans1 Recv Date:	10/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/24/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004378881
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237490GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

K130 **CON EDISON SERVICE BOX: 49198** **RCRA NonGen / NLR** **1016967829**
NNW **313 39TH ST** **NY MANIFEST** **NYP004414272**
1/8-1/4 **BROOKLYN, NY 11232**
0.139 mi.
732 ft. **Site 7 of 7 in cluster K**

Relative: **Lower**
Actual: **19 ft.**

RCRA Listings:

Date Form Received by Agency:	20140208
Handler Name:	Con Edison Service Box: 49198
Handler Address:	39TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004414272
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770

CON EDISON SERVICE BOX: 49198 (Continued) **1016967829**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 49198 (Continued) **1016967829**

Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20140108
Handler Name: CON EDISON SERVICE BOX:	49198
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140208
Handler Name: CON EDISON SERVICE BOX:	49198
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004414272
Country:	USA
Name:	CON EDISON
Address:	313 39TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	313 39 ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

CON EDISON SERVICE BOX: 49198 (Continued) **1016967829**

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	01/08/2014
Trans1 Recv Date:	01/08/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/09/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004414272
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011695526JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	5000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat

CON EDISON SERVICE BOX: 49198 (Continued) **1016967829**

Specific Gravity: 1

L131 **CON EDISON SERVICE BOX: 48388** **RCRA NonGen / NLR** **1016965555**
WNW **313 42 ST** **NY MANIFEST** **NYP004384251**
1/8-1/4 **BROOKLYN, NY 11232**
0.139 mi.
736 ft. **Site 5 of 6 in cluster L**

Relative: **Lower**

Actual: **29 ft.**

RCRA Listings:

Date Form Received by Agency:	20131201
Handler Name:	Con Edison Service Box: 48388
Handler Address:	42 ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004384251
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

CON EDISON SERVICE BOX: 48388 (Continued) **1016965555**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131101
Handler Name: CON EDISON SERVICE BOX:	48388
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131201
Handler Name: CON EDISON SERVICE BOX:	48388
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CON EDISON SERVICE BOX: 48388 (Continued) **1016965555**

Evaluations: No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004384251
Country:	USA
Name:	CON EDISON
Address:	313 42 ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	42ND 5 20PT SOUTH OF 2ND AVE
Location Address 2:	SB43888
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/01/2013
Trans1 Recv Date:	11/01/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/04/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004384251
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002086531GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

CON EDISON SERVICE BOX: 48388 (Continued) **1016965555**

MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

O132 **NYC DOE - PS 557K** **RCRA-LQG** **1026834123**
SW **4302 4TH AVE** **NYR000251066**
1/8-1/4 **BROOKLYN, NY 11232**
0.141 mi.
743 ft. **Site 5 of 9 in cluster O**

Relative: **Higher**

Actual: **63 ft.**

RCRA Listings:

Date Form Received by Agency:	20230316
Handler Name:	Nyc Doe - Ps 557k
Handler Address:	4TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYR000251066
Contact Name:	CHAD J ONDRUSEK
Contact Address:	THOMSON AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-752-5249
Contact Fax:	Not reported
Contact Email:	CONDRUSEK@NYCSCA.ORG
Contact Title:	SR. DIRECTOR, NYC SCA IEH DIVISION
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2022
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	THOMSON AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Nyc Dept Of Education
Owner Type:	Municipal
Operator Name:	Nyc Dept Of Education
Operator Type:	Municipal
Short-Term Generator Activity:	Yes
Importer Activity:	No
Mixed Waste Generator:	No

NYC DOE - PS 557K (Continued) **1026834123**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230316
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYC DEPT OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	20210709
Date Ended Current:	Not reported
Owner/Operator Address:	44-36 VERNON BOULEVARD
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

NYC DOE - PS 557K (Continued) **1026834123**

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC DEPT OF EDUCATION
Legal Status: Municipal
Date Became Current: 20210709
Date Ended Current: Not reported
Owner/Operator Address: 44-36 VERNON BOULEVARD
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC DEPT OF SCHOOL FACILITIES
Legal Status: Municipal
Date Became Current: 20210709
Date Ended Current: Not reported
Owner/Operator Address: 30-30 THOMSON AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-752-5496
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: 718-472-8500
Owner/Operator Email: TBROWN@NYCSCA.ORG

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC DEPT OF EDUCATION
Legal Status: Municipal
Date Became Current: 20210709
Date Ended Current: Not reported
Owner/Operator Address: 30-30 THOMSON AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-752-5496
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: 718-472-8500
Owner/Operator Email: TBROWN@NYCSCA.ORG

Historic Generators:
Receive Date: 20230316
Handler Name: NYC DOE - PS 557K
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20210713
Handler Name: NYC DOE - PS 557K
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

NYC DOE - PS 557K (Continued) **1026834123**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 611110
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

O133 **NYC DOE - PS 557K** **NY MANIFEST** **S130582695**
SW **4302 4TH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.141 mi.
743 ft. **Site 6 of 9 in cluster O**

Relative:
Higher

Actual:
63 ft.

NY MANIFEST:
EPA ID: NYR000251066
Country: USA
Name: NYC DOE - PS 557K
Address: 4302 4TH AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: 4302 4TH AVE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: NYC DOE - PS 557K
Mailing Contact: NYC DEPT. OF EDUCATION
Mailing Address 1: 30-30 THOMSON AVE
Mailing Address 2: Not reported
Mailing City,State,Zip: LONG ISLAND CITY, NY 11101
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7187525496

J134 **P.S. 24 (OLD MERIT FOURTH STATION)** **NY UST** **U001835728**
NE **969-75 FOURTH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.142 mi.
749 ft. **Site 10 of 10 in cluster J**

Relative:
Lower

Actual:
38 ft.

UST:

Name:	P.S. 24 (OLD MERIT FOURTH STATION)
Address:	969-75 FOURTH AVE
City,State,Zip:	BROOKLYN, NY 11232
Id/Status:	2-297291 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583343.80631
UTM Y:	4497578.41105
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	13723
Affiliation Type:	Facility Owner
Company Name:	NYC SCHOOL CONSTRUCTION AUTHORITY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	30-30 THOMPSON AVE
Address2:	Not reported
City:	L.I.C.
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 472-8638
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	13723
Affiliation Type:	Mail Contact
Company Name:	VAN SAN CONSTRUCTION CORP.
Contact Type:	Not reported
Contact Name:	YVONNE DESOTO
Address1:	71-26 164TH ST
Address2:	Not reported
City:	FRESH MEADOWS
State:	NY
Zip Code:	11365
Country Code:	001
Phone:	(718) 969-2588
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	13723
Affiliation Type:	Facility Operator
Company Name:	P.S. 24 (OLD MERIT FOURTH STATION)
Contact Type:	Not reported
Contact Name:	NYC SCA
Address1:	Not reported

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 969-2588
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	13723
Affiliation Type:	Emergency Contact
Company Name:	NYC SCHOOL CONSTRUCTION AUTHORITY
Contact Type:	Not reported
Contact Name:	NYC SCA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 969-2588
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	15495
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	01/01/1989
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
H03 - Tank Leak Detection - Vapor Well
I01 - Overfill - Float Vent Valve
B04 - Tank External Protection - Fiberglass

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G03 - Tank Secondary Containment - Vault (w/o access)
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 002
Tank ID: 15496
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 01/01/1989
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 003
Tank ID: 15497
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 01/01/1989
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
G03 - Tank Secondary Containment - Vault (w/o access)
B04 - Tank External Protection - Fiberglass
H03 - Tank Leak Detection - Vapor Well
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 004
Tank ID: 15498
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 01/01/1989
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 005
Tank ID: 15499
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Install Date: 01/01/1989
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin

Tank Number: 006
Tank ID: 15500
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1989
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

D00 - Pipe Type - No Piping

Tank Number: 007
Tank ID: 43896
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 008
Tank ID: 43897
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	009
Tank ID:	43898
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	010
Tank ID:	43899
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

Tank Number: 011
Tank ID: 43900
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 012
Tank ID: 43901
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 013
Tank ID: 43902
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 014
Tank ID: 43903
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

Tank Number:	015
Tank ID:	43904
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Tank Number: 016
Tank ID: 43905
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 017
Tank ID: 43906
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

A00 - Tank Internal Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	018
Tank ID:	43907
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	019
Tank ID:	43908
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	020
Tank ID:	43909
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	021
Tank ID:	43910
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 022
Tank ID: 43911
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 023
Tank ID: 43912
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 024
Tank ID: 43913
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 025

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Tank ID:	43914
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	026
Tank ID:	43915
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	027
Tank ID:	43916
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	028
Tank ID:	43917
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None

Tank Number:	029
Tank ID:	43918
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number:	030
Tank ID:	43919
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 031
Tank ID: 43920
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 032
Tank ID: 43921
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 033
Tank ID: 43922
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 034
Tank ID: 43923
Tank Status: Closed - Removed

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	035
Tank ID:	43924
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

G00 - Tank Secondary Containment - None

Tank Number: 036
Tank ID: 43925
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 037
Tank ID: 43926
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

Tank Number:	038
Tank ID:	43927
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	039
Tank ID:	43928
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1970
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J00 - Dispenser - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 040
Tank ID: 43929
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 041
Tank ID: 43930
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 042
Tank ID: 43931
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1970
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 043
Tank ID: 48416
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Install Date:	Not reported
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number:	044
Tank ID:	48417
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1974
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J00 - Dispenser - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Tank Number: 045
Tank ID: 48418
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1974
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number: 046
Tank ID: 48419
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 275
Install Date: 12/01/1974
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

F00 - Pipe External Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

Tank Number:	047
Tank ID:	48420
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	275
Install Date:	12/01/1974
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	048
Tank ID:	48421
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1080
Install Date:	12/01/1974
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

P.S. 24 (OLD MERIT FOURTH STATION) (Continued) **U001835728**

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None

R135 **CON EDISON - MANHOLE 71516** **NY MANIFEST** **S120958654**
SE **507 41ST ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.144 mi.
759 ft. **Site 2 of 4 in cluster R**

Relative: **Higher**
Actual: **102 ft.**

NY MANIFEST:

EPA ID:	NYP004954705
Country:	USA
Name:	CON EDISON - MANHOLE 71516
Address:	507 41ST ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	507 41ST ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON - MANHOLE 71516
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

P136 **CON EDISON SERVICE BOX: 48505** **RCRA NonGen / NLR** **1016965563**
South **471 43RD ST** **NY MANIFEST** **NYP004384335**
1/8-1/4 **BROOKLYN, NY 11232**
0.144 mi.
762 ft. **Site 2 of 10 in cluster P**

Relative: **Higher**
Actual: **102 ft.**

RCRA Listings:

Date Form Received by Agency:	20131201
Handler Name:	Con Edison Service Box: 48505
Handler Address:	43RD ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004384335

CON EDISON SERVICE BOX: 48505 (Continued) **1016965563**

Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

CON EDISON SERVICE BOX: 48505 (Continued) **1016965563**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131101
Handler Name: CON EDISON SERVICE BOX:	48505
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131201
Handler Name: CON EDISON SERVICE BOX:	48505
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004384335
Country:	USA
Name:	CON EDISON
Address:	471 43RD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	471 43RD ST
Location Address 2:	SB40518
Location City,State,Zip:	BROOKLYN, NY 11232

CON EDISON SERVICE BOX: 48505 (Continued) **1016965563**

Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/01/2013
Trans1 Recv Date:	11/01/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/04/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004384335
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002086532GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	75

CON EDISON SERVICE BOX: 48505 (Continued) **1016965563**

Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

S137 **NYCT** **NY MANIFEST** **S117736021**
ENE **481 38TH ST IN FRONT OF** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.144 mi.
762 ft. **Site 1 of 2 in cluster S**

Relative:
Higher

Actual:
64 ft.

NY MANIFEST:

EPA ID:	NYP000970509
Country:	USA
Name:	NYCT
Address:	481 38TH ST IN FRONT OF
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	481 38TH STREET
Location Address 2:	IN FRONT E SIDE 38TH NORTH 5T
Location City,State,Zip:	BROOKLYN, NY 11231
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	NYCT
Mailing Contact:	NYCT
Mailing Address 1:	2 BROADWAY - RM A27.72
Mailing Address 2:	27TH FLOOR
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462525777

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	04/03/2014
Trans1 Recv Date:	04/03/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/03/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP000970509
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012352861JJK
Import Indicator:	N

NYCT (Continued) **S117736021**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	400
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

S138 **MTA NYCT** **RCRA NonGen / NLR** **1016677148**
ENE **481 38TH ST IN FRONT OF** **FINDS** **NYP000970509**
1/8-1/4 **BROOKLYN, NY 11232** **ECHO**
0.144 mi.
762 ft. **Site 2 of 2 in cluster S**

Relative:
Higher

Actual:
64 ft.

RCRA Listings:

Date Form Received by Agency:	20140522
Handler Name:	Mta Nyct
Handler Address:	38TH ST IN FRONT OF
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP000970509
Contact Name:	SHERRY BULKLEY
Contact Address:	BROADWAY RM A27.63
Contact City,State,Zip:	NEW YORK, NY 10004
Contact Telephone:	646-252-5774 5777
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SYS SAFETY SPECIALIST
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2

MTA NYCT (Continued) **1016677148**

Mailing Address:	BROADWAY RM A27.63
Mailing City,State,Zip:	NEW YORK, NY 10004
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170427
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140402
Handler Name: MTA NYCT	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

MTA NYCT (Continued) **1016677148**

Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20140522
Handler Name: MTA NYCT	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058870510

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016677148
Registry ID:	110058870510
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058870510
Name:	MTA NYCT
Address:	481 38TH ST IN FRONT OF
City,State,Zip:	BROOKLYN, NY 11232

P139 **CON EDISON** **NY MANIFEST** **S118259412**
SSW **446 43RD ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.146 mi.
772 ft. **Site 3 of 10 in cluster P**

Relative:
Higher

Actual:
94 ft.

NY MANIFEST:

EPA ID:	NYP004831455
Country:	USA
Name:	CON EDISON
Address:	446 43RD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	446 43RD ST
Location Address 2:	SB 48801
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/2015
Trans1 Recv Date:	08/28/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004831455
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624764GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **S118259412**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

P140 **CON EDISON** **RCRA NonGen / NLR** **1019907213**
SSW **446 43RD ST** **FINDS** **NYP004831455**
1/8-1/4 **BROOKLYN, NY 11232** **ECHO**
0.146 mi.
772 ft. **Site 4 of 10 in cluster P**

Relative: **Higher**
Actual: **94 ft.**

RCRA Listings:

Date Form Received by Agency:	20150828
Handler Name:	Con Edison
Handler Address:	43RD ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004831455
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No

CON EDISON (Continued) **1019907213**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150828
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150828
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1019907213**

State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069687583

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019907213
Registry ID:	110069687583
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069687583
Name:	CON EDISON
Address:	446 43RD ST
City,State,Zip:	BROOKLYN, NY 11232

P141 **CON EDISON** **NJ MANIFEST** **S120676061**
SSW **446 43RD ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.146 mi.
772 ft. **Site 5 of 10 in cluster P**

Relative: **Higher**
Actual: **94 ft.**

NJ MANIFEST:

EPA ID:	NYP004831455
Name:	CON EDISON
Address:	446 43RD ST
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE

CON EDISON (Continued) **S120676061**

Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004831455
Manifest Number:	002624764GBF
Date Shipped:	8/28/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

O142 **CON EDISON SERVICE BOX: 48497** **RCRA NonGen / NLR** **1016971671**
WSW **358 43RD ST** **NY MANIFEST** **NYP004454146**
1/8-1/4 **BROOKLYN, NY 11232**
0.147 mi.
777 ft. **Site 7 of 9 in cluster O**

Relative: **Higher**
Actual: **56 ft.**

RCRA Listings:

Date Form Received by Agency:	20140327
Handler Name:	Con Edison Service Box: 48497
Handler Address:	43RD ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004454146
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 48497 (Continued) **1016971671**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140227
Handler Name: CON EDISON SERVICE BOX:	48497
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140327
Handler Name: CON EDISON SERVICE BOX:	48497
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 48497 (Continued) **1016971671**

NY MANIFEST:

EPA ID:	NYP004454146
Country:	USA
Name:	CON EDISON
Address:	358 43RD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	358 43 ST & 3RD AVE
Location Address 2:	SB48897
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/27/2014
Trans1 Recv Date:	02/27/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/28/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004454146
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772991JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported

CON EDISON SERVICE BOX: 48497 (Continued) **1016971671**

Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

O143 **CON EDISON SERVICE BOX: 48495** **RCRA NonGen / NLR** **1016966108**
WSW **358 43RD ST FRONT OF** **NY MANIFEST** **NYP004389649**
1/8-1/4 **BROOKLYN, NY 11232**
0.147 mi.
777 ft. **Site 8 of 9 in cluster O**

Relative: **Higher**

Actual: **56 ft.**

RCRA Listings:

Date Form Received by Agency:	20131212
Handler Name:	Con Edison Service Box: 48495
Handler Address:	43RD ST FRONT OF
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004389649
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

CON EDISON SERVICE BOX: 48495 (Continued) **1016966108**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131112
Handler Name: CON EDISON SERVICE BOX:	48495
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131212
Handler Name: CON EDISON SERVICE BOX:	48495
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON SERVICE BOX: 48495 (Continued) **1016966108**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004389649
Country: USA
Name: CON EDISON
Address: 358 43RD ST FRONT OF
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: OP 358 43RD ST
Location Address 2: SB48495
Location City,State,Zip: BROOKLYN, NY 11220
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 11/12/2013
Trans1 Recv Date: 11/12/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/14/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004389649

CON EDISON SERVICE BOX: 48495 (Continued) **1016966108**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002298875GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	80
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

P144 **CON EDISON** **NY MANIFEST** **S116550606**
SSW **452 43RD ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11231**
0.149 mi.
788 ft. **Site 6 of 10 in cluster P**

Relative: NY MANIFEST:
Higher

Actual:
97 ft.

EPA ID:	NYP004489993
Country:	USA
Name:	CON EDISON
Address:	452 43RD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11231
Zip 4:	Not reported
Location Address 1:	452 43RD ST
Location Address 2:	SB 48502
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

CON EDISON (Continued) **S116550606**

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	04/04/2014
Trans1 Recv Date:	04/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004489993
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002407750GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	60
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat

CON EDISON (Continued) **S116550606**

Specific Gravity: 1

P145 **CON EDISON SERVICE BOX: 48502** **RCRA NonGen / NLR** **1017772051**
SSW **452 43RD ST** **NYP004489993**
1/8-1/4 **BROOKLYN, NY 11231**
0.149 mi.
788 ft. **Site 7 of 10 in cluster P**

Relative:
Higher

Actual:
97 ft.

RCRA Listings:

Date Form Received by Agency:	20140504
Handler Name:	Con Edison Service Box: 48502
Handler Address:	43RD ST
Handler City,State,Zip:	BROOKLYN, NY 11231
EPA ID:	NYP004489993
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

CON EDISON SERVICE BOX: 48502 (Continued) **1017772051**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140404
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140404
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140504
Handler Name: CON EDISON SERVICE BOX:	48502
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON SERVICE BOX: 48502 (Continued) **1017772051**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

P146 **CON EDISON SERVICE BOX: 45842** **RCRA NonGen / NLR** **1017777064**
South **4214 5TH AVE** **FINDS** **NYP004549499**
1/8-1/4 **BROOKLYN, NY 11220**
0.149 mi.
788 ft. **Site 8 of 10 in cluster P**

Relative: **Higher**
Actual: **104 ft.**

RCRA Listings:

Date Form Received by Agency:	20140702
Handler Name:	Con Edison Service Box: 45842
Handler Address:	5TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NYP004549499
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No

CON EDISON SERVICE BOX: 45842 (Continued) **1017777064**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140602
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140602
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON SERVICE BOX: 45842 (Continued) **1017777064**

Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20140702
Handler Name: CON EDISON SERVICE BOX:	45842
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063818846

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

P147 **CON EDISON** **NY MANIFEST** **S117062588**
South **4214 5TH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.149 mi.
788 ft. **Site 9 of 10 in cluster P**

Relative:
Higher

Actual:
104 ft.

NY MANIFEST:

EPA ID:	NYP004549499
Country:	USA
Name:	CON EDISON
Address:	4214 5TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11220
Zip 4:	Not reported

CON EDISON (Continued) **S117062588**

Location Address 1: 4214 5 AVE
Location Address 2: SB 45842
Location City,State,Zip: BROOKLYN, NY 11220
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 06/02/2014
Trans1 Recv Date: 06/02/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/03/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004549499
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 013245931JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported

CON EDISON (Continued) **S117062588**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

O148 **CON EDISON SERVICE BOX: 48497** **RCRA NonGen / NLR** **1016965005**
WSW **352 352 43RD ST** **NY MANIFEST** **NYP004379012**
1/8-1/4 **BROOKLYN, NY 11232**
0.150 mi.
794 ft. **Site 9 of 9 in cluster O**

Relative: **Higher**

Actual: **54 ft.**

RCRA Listings:

Date Form Received by Agency:	20131123
Handler Name:	Con Edison Service Box: 48497
Handler Address:	352 43RD ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004379012
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---

CON EDISON SERVICE BOX: 48497 (Continued) **1016965005**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131023
Handler Name: CON EDISON SERVICE BOX:	48497
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131123
Handler Name: CON EDISON SERVICE BOX:	48497
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

CON EDISON SERVICE BOX: 48497 (Continued) **1016965005**

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004379012
Country:	USA
Name:	CON EDISON
Address:	352 352 43RD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	352 43ST
Location Address 2:	SB48497
Location City,State,Zip:	BROOKLYN, NY 11220
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2013
Trans1 Recv Date:	10/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004379012
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002236699GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

CON EDISON SERVICE BOX: 48497 (Continued) **1016965005**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	200
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

P149 **CON EDISON SERVICE BOX: 48501** **RCRA NonGen / NLR** **1016966876**
South **454 43RD ST** **NY MANIFEST** **NYP004397154**
1/8-1/4 **BROOKLYN, NY 11232**
0.151 mi.
796 ft. **Site 10 of 10 in cluster P**

Relative: **Higher**

Actual: **98 ft.**

RCRA Listings:

Date Form Received by Agency:	20131222
Handler Name:	Con Edison Service Box: 48501
Handler Address:	43RD ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004397154
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003

CON EDISON SERVICE BOX: 48501 (Continued) **1016966876**

Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131122
Handler Name: CON EDISON SERVICE BOX:	48501
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CON EDISON SERVICE BOX: 48501 (Continued) **1016966876**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131222
Handler Name: CON EDISON SERVICE BOX: 48501
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004397154
Country: USA
Name: CON EDISON
Address: 454 43RD ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: 454 43RD ST
Location Address 2: SB 48501
Location City,State,Zip: BROOKLYN, NY 11220
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported

CON EDISON SERVICE BOX: 48501 (Continued) **1016966876**

Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/22/2013
Trans1 Recv Date:	11/22/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/22/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004397154
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299249GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

L150 **CROWN HOLDINGS USA** **NY AST** **A100293682**
West **327 43RD STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.151 mi.
797 ft. **Site 6 of 6 in cluster L**

Relative: AST:
Lower

Name:	CROWN HOLDINGS USA
Address:	327 43RD STREET
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2

Actual:
43 ft.

CROWN HOLDINGS USA (Continued) **A100293682**

Site Status:	Active
Facility Id:	2-608168
Program Type:	PBS
UTM X:	583715.45001
UTM Y:	4500521.54080
Expiration Date:	01/10/2023
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	30020
Affiliation Type:	Facility Owner
Company Name:	PLAZA MANAGEMENT USA
Contact Type:	PROPERTY MANAGER
Contact Name:	JOCOB BERNAT
Address1:	543 BEDFORD AVE. PMB 114
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 243-2889
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-02

Site Id:	30020
Affiliation Type:	Mail Contact
Company Name:	PLAZA MANAGEMENT USA
Contact Type:	Not reported
Contact Name:	JACOB BERNAT
Address1:	543 BEDFORD AVENUE
Address2:	PMB 114
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 243-2889
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-02

Site Id:	30020
Affiliation Type:	Emergency Contact
Company Name:	PLAZA MANAGEMENT USA
Contact Type:	Not reported
Contact Name:	PLAZA MANAGEMENT USA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 243-2889
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR

CROWN HOLDINGS USA (Continued) **A100293682**

Date Last Modified: 2018-01-02

Site Id: 30020
Affiliation Type: Facility Operator
Company Name: CROWN HOLDINGS USA
Contact Type: Not reported
Contact Name: SUPER - ISREAL SOTO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 288-9230
EMail: Not reported
Fax Number: Not reported
Modified By: KAKYER
Date Last Modified: 2013-01-29

Tank Info:

Tank Number: 001
Tank Id: 64786
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/2001
Capacity Gallons: 1200
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

Q151 **CONSOLIDATED EDISON** **PA MANIFEST** **S123093158**
East **879 FIFTH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.151 mi.
797 ft. **Site 2 of 9 in cluster Q**

Relative: **Higher**
Actual: **78 ft.**

PA MANIFEST:

Year:	2017
Manifest Number:	009794829FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYP005046067
Generator Date:	03/12/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	1000
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

T152 **CON EDISON** **RCRA NonGen / NLR** **1018278159**
NNE **4TH AVE & 37TH ST** **FINDS** **NYP004729158**
1/8-1/4 **BROOKLYN, NY 11232** **ECHO**
0.152 mi.
800 ft. **Site 1 of 7 in cluster T**

Relative: **Lower**
Actual: **35 ft.**

RCRA Listings:

Date Form Received by Agency:	20150209
Handler Name:	Con Edison
Handler Address:	4TH AVE & 37TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004729158
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported

CON EDISON (Continued) **1018278159**

State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150209
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON (Continued) **1018278159**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150209
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067700544

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018278159
Registry ID: 110067700544
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067700544
Name: CON EDISON
Address: 4TH AVE & 37TH ST
City,State,Zip: BROOKLYN, NY 11232

Q153 **JACKIE GLEASON BUS DEPOT** **NY AST** **U003080331**
East **875 5TH AVE** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.153 mi.
806 ft. **Site 3 of 9 in cluster Q**

Relative:
Higher

Actual:
78 ft.

AST:

Name:	JACKIE GLEASON BUS DEPOT
Address:	845 5TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-190233
Program Type:	PBS
UTM X:	584339.50683
UTM Y:	4500633.77354
Expiration Date:	06/05/2027
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	5859
Affiliation Type:	Mail Contact
Company Name:	NYC TRANSIT AUTHORITY
Contact Type:	DIRECTOR, EPIH
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY
Address2:	27TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	DOREEN.BOATSWAIN@NYCT.COM
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-01-27

Site Id:	5859
Affiliation Type:	Facility Owner
Company Name:	NYC TRANSIT AUTHORITY
Contact Type:	DIRECTOR, EPIH
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-06-09

Site Id:	5859
Affiliation Type:	Facility Operator
Company Name:	ROGER MIGNOTT
Contact Type:	Not reported
Contact Name:	ROGER MIGNOTT

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Address1:	845 5TH AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(347) 682-0124
EMail:	ROGER.MIGNOTT@NYCT.COM
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-01-27

Site Id:	5859
Affiliation Type:	Emergency Contact
Company Name:	NYC TRANSIT AUTHORITY
Contact Type:	Not reported
Contact Name:	BUS COMMAND CENTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 927-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-01-27

Tank Info:

Tank Number:	002
Tank Id:	6689
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

	B00 - Tank External Protection - None
	D02 - Pipe Type - Galvanized Steel
	F00 - Pipe External Protection - None
	I00 - Overfill - None
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	A00 - Tank Internal Protection - None
	J02 - Dispenser - Suction Dispenser
	C02 - Pipe Location - Underground/On-ground
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	12/01/1984
Capacity Gallons:	4000
Tightness Test Method:	ZZ
Date Test:	09/01/1991
Next Test Date:	Not reported

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Date Tank Closed:	09/01/1994
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel
Tank Number:	003
Tank Id:	6690
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H03 - Tank Leak Detection - Vapor Well

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	12/01/1984
Capacity Gallons:	4000
Tightness Test Method:	ZZ
Date Test:	09/01/1991
Next Test Date:	Not reported
Date Tank Closed:	09/01/1994
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel
Tank Number:	004
Tank Id:	6691
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
H03 - Tank Leak Detection - Vapor Well
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	12/01/1984
Capacity Gallons:	4000
Tightness Test Method:	ZZ
Date Test:	09/01/1991
Next Test Date:	Not reported
Date Tank Closed:	09/01/1994
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	005
Tank Id:	6692
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H03 - Tank Leak Detection - Vapor Well
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	12/01/1984
Capacity Gallons:	4000
Tightness Test Method:	ZZ
Date Test:	09/01/1991
Next Test Date:	Not reported
Date Tank Closed:	09/01/1994
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	006
Tank Id:	6693
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

H03 - Tank Leak Detection - Vapor Well
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	12/01/1984
Capacity Gallons:	4000
Tightness Test Method:	ZZ
Date Test:	09/01/1991
Next Test Date:	Not reported
Date Tank Closed:	09/01/1994
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	007
Tank Id:	6694
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
H03 - Tank Leak Detection - Vapor Well
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	12/01/1984
Capacity Gallons:	4000
Tightness Test Method:	ZZ
Date Test:	09/01/1991
Next Test Date:	Not reported
Date Tank Closed:	09/01/1994
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	008
Tank Id:	6695

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H03 - Tank Leak Detection - Vapor Well
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: 12/01/1984
Capacity Gallons: 4000
Tightness Test Method: ZZ
Date Test: 09/01/1991
Next Test Date: Not reported
Date Tank Closed: 09/01/1994
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: diesel

Tank Number: 009
Tank Id: 6696
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
H03 - Tank Leak Detection - Vapor Well
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: 12/01/1984
Capacity Gallons: 4000
Tightness Test Method: ZZ
Date Test: 09/01/1991
Next Test Date: Not reported
Date Tank Closed: 09/01/1994

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: diesel

Tank Number: 010
Tank Id: 6697
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
H03 - Tank Leak Detection - Vapor Well
G03 - Tank Secondary Containment - Vault (w/o access)

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place
Pipe Model: Not reported
Install Date: 12/01/1984
Capacity Gallons: 4000
Tightness Test Method: ZZ
Date Test: 09/01/1991
Next Test Date: Not reported
Date Tank Closed: 09/01/1994
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: diesel

Tank Number: 011
Tank Id: 6698
Material Code: 0008
Common Name of Substance: Diesel

Equipment Records:
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H03 - Tank Leak Detection - Vapor Well
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - In Place

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Pipe Model:	Not reported
Install Date:	12/01/1984
Capacity Gallons:	4000
Tightness Test Method:	ZZ
Date Test:	09/01/1991
Next Test Date:	Not reported
Date Tank Closed:	09/01/1994
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	ATF-1
Tank Id:	66210
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
J02 - Dispenser - Suction Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)
D00 - Pipe Type - No Piping
C01 - Pipe Location - Aboveground
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	08/01/2000
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/2004
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	ATF-2
Tank Id:	66211
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

D00 - Pipe Type - No Piping
H05 - Tank Leak Detection - In-Tank System (ATG)
C01 - Pipe Location - Aboveground

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
J02 - Dispenser - Suction Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	08/01/2000
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/04/2004
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	ATF-3
Tank Id:	66212
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
H05 - Tank Leak Detection - In-Tank System (ATG)
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	08/01/2000
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/2004
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Tank Number: DSL-11
Tank Id: 277766

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C01 - Pipe Location - Aboveground
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
I03 - Overfill - Automatic Shut-Off
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
G12 - Tank Secondary Containment - Double-Walled (AG only)

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel Tank in Concrete
Tank Status: In Service
Pipe Model: Not reported
Install Date: 05/31/2018
Capacity Gallons: 8012
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: diesel

Tank Number: EMGEN-2
Tank Id: 48623
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
J02 - Dispenser - Suction Dispenser
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/01/1994
Capacity Gallons:	100
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	EMGEN-3
Tank Id:	251725

Equipment Records:

C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
G12 - Tank Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2000
Capacity Gallons:	200
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Tank Number:	HYDLIF10
Tank Id:	66222
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I99 - Overfill - Other

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	09/01/1987
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	HYDLIF11
Tank Id:	66223
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I99 - Overfill - Other
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	09/01/1987
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Tank Number:	HYDLIF12
Tank Id:	66224
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

I99 - Overfill - Other
D02 - Pipe Type - Galvanized Steel
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	09/01/1987
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	HYDLIF13
Tank Id:	66225
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

D02 - Pipe Type - Galvanized Steel
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
I99 - Overfill - Other

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	09/01/1987
Capacity Gallons:	275

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	HYDLIF14
Tank Id:	66226
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
I99 - Overfill - Other
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	09/01/1987
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	HYDLIF15
Tank Id:	66227
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I99 - Overfill - Other

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	09/01/1987
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	HYDLIFT1
Tank Id:	66213
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

D02 - Pipe Type - Galvanized Steel
E04 - Piping Secondary Containment - Double walled UG
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I99 - Overfill - Other
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	09/01/1987
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	HYDLIFT2
Tank Id:	66214
Material Code:	9999

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Common Name of Substance: Other

Equipment Records:

D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I99 - Overfill - Other

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 09/01/1987
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: other

Tank Number: HYDLIFT3
Tank Id: 66215
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I99 - Overfill - Other
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 09/01/1987
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: other

Tank Number: HYDLIFT4
Tank Id: 66216
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

D02 - Pipe Type - Galvanized Steel
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I99 - Overfill - Other

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 09/01/1987
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: other

Tank Number: HYDLIFT5
Tank Id: 66217
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

D02 - Pipe Type - Galvanized Steel
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I99 - Overfill - Other

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	09/01/1987
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	HYDLIFT6
Tank Id:	66218
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

I99 - Overfill - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
D02 - Pipe Type - Galvanized Steel

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	09/01/1987
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

Tank Number:	HYDLIFT7
Tank Id:	66219
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

D02 - Pipe Type - Galvanized Steel
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
I99 - Overfill - Other

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 09/01/1987
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: other

Tank Number: HYDLIFT8
Tank Id: 66220
Material Code: 9999
Common Name of Substance: Other

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I99 - Overfill - Other
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 09/01/1987
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Material Name: other

Tank Number: HYDLIFT9
Tank Id: 66221
Material Code: 9999
Common Name of Substance: Other

Equipment Records:
I99 - Overfill - Other
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 09/01/1987
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: other

Tank Number: JAC-18
Tank Id: 48113
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:
C01 - Pipe Location - Aboveground
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

Install Date:	12/01/1984
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/2000
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil

Tank Number:	JAC-19
Tank Id:	48114
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

D02 - Pipe Type - Galvanized Steel
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
I00 - Overfill - None
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1984
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/2000
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil

Tank Number:	JAC-20
Tank Id:	48115
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1984
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/2000
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil

SPILLS:

Name:	JACKIE GLEASON BUS DEPOT
Address:	875 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0012211 / 2002-07-11
Facility ID:	0012211
Facility Type:	ER
DER Facility ID:	173261
Site ID:	208851
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-02-13
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2001-02-13
CID:	205
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-02-13
Spill Record Last Update:	2002-07-11
Spiller Name:	CALLER
Spiller Company:	JACKIE GLEASON BUS DEPOT
Spiller Address:	875 5TH AVE
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	emergency generator colling system faliure. spill stopped. contained and cleaned.
Remarks:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE CLEANED BY NYCT.

JACKIE GLEASON BUS DEPOT (Continued) **U003080331**

All Materials:

Site ID:	208851
Operable Unit ID:	834111
Operable Unit:	01
Material ID:	542492
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	10.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

T154 **METRO 1 AMBULANCE SERVICE INC** **RCRA NonGen / NLR** **1001233115**
NNE **350 37TH ST** **FINDS** **NYR000062257**
1/8-1/4 **BROOKLYN, NY 11232** **ECHO**
0.153 mi. **NY MANIFEST**
809 ft. **Site 2 of 7 in cluster T**

Relative: **Lower**
Actual: **29 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Metro 1 Ambulance Service Inc
Handler Address:	37TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYR000062257
Contact Name:	JEAN RAYMOND SAINT JUSTZ
Contact Address:	37TH ST
Contact City,State,Zip:	BROOKLYN, NY 11232
Contact Telephone:	718-832-4700
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	37TH ST
Mailing City,State,Zip:	BROOKLYN, NY 11232
Owner Name:	Metro 1 Ambulance Service Inc
Owner Type:	Private
Operator Name:	Metro 1 Ambulance Service Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No

METRO 1 AMBULANCE SERVICE INC (Continued) **1001233115**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	D040
Waste Description:	Trichlorethylene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	METRO 1 AMBULANCE SERVICE INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	350 37TH ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11232
Owner/Operator Telephone:	718-832-4700
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner

METRO 1 AMBULANCE SERVICE INC (Continued) **1001233115**

Owner/Operator Name: METRO 1 AMBULANCE SERVICE INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 350 37TH ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11232
Owner/Operator Telephone: 718-832-4700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: METRO 1 AMBULANCE SERVICE INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 350 37TH ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11232
Owner/Operator Telephone: 718-832-4700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: METRO 1 AMBULANCE SERVICE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: METRO 1 AMBULANCE SERVICE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19981020
Handler Name: METRO 1 AMBULANCE SERVICE INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

METRO 1 AMBULANCE SERVICE INC (Continued) **1001233115**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004547946

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001233115
Registry ID: 110004547946
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004547946
Name: METRO 1 AMBULANCE SERVICE INC
Address: 350 37TH ST
City,State,Zip: BROOKLYN, NY 11232

NY MANIFEST:
EPA ID: NYR000062257
Country: USA
Name: METRO 1 AMBULANCE SVC
Address: 350 37TH ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: 350 37TH ST
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

METRO 1 AMBULANCE SERVICE INC (Continued) **1001233115**

Mailing:

Mailing Name:	METRO 1 AMBULANCE SVC
Mailing Contact:	N/S
Mailing Address 1:	350 37TH ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11232
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7188320100

Manifest Data:

Document ID:	NYC5892748
Manifest Status:	Not reported
Trans1 State ID:	NYCD67754
Year:	1999
Trans2 State ID:	817TZC
Generator Ship Date:	08/30/1999
Trans1 Recv Date:	08/30/1999
Trans2 Recv Date:	09/02/1999
TSD Site Recv Date:	09/03/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000062257
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID 1:	NYD000708198
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	TETRACHLOROETHYLENE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00005
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NYC5852867
Manifest Status:	Not reported
Trans1 State ID:	NYCDL7754
Year:	1999

METRO 1 AMBULANCE SERVICE INC (Continued) **1001233115**

Trans2 State ID:	817TZC
Generator Ship Date:	07/13/1999
Trans1 Recv Date:	07/13/1999
Trans2 Recv Date:	07/15/1999
TSD Site Recv Date:	07/15/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000062257
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID 1:	NYD000708198
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	IGNITABLE WASTE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00008
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	IGNITABLE WASTE
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00015
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Q155
East
1/8-1/4
0.154 mi.
814 ft.

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT
871 FIFTH AVENUE
BROOKLYN, NY 11232

Site 4 of 9 in cluster Q

NY LTANKS
NY CBS AST
NY Spills

S102234408
N/A

Relative:
Higher

Actual:
77 ft.

LTANKS:

Name:	871 5TH AV/JACKIE GLEASON
Address:	871 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9106350 / 2002-02-07
Facility ID:	9106350
Site ID:	137663
Spill Date:	1991-09-12
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	1994-11-18
SWIS:	2401
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1991-09-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-09-13
Spill Record Last Update:	2002-02-07
Spiller Name:	Not reported
Spiller Company:	NYCTA/URS CONSULTANTS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	117753
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 11/18/94: REASSIGNED FROM SIGONA TO ZHITOMIRSKY ON 11/18/94. TRANSFERED FROM HALE TO TIBBE ON 12/28/00. INVESTIGATION ONGOING. TANKS CLOSED AND REPLACED. No contamination found during investigation.
Remarks:	Not reported

All TTF:

Facility ID:	9106350
Spill Number:	9106350
Spill Tank Test:	1539042
Site ID:	137663
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	137663
Operable Unit ID:	956797
Operable Unit:	01
Material ID:	422064
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Name:	JACKIE GLEASON DEPOT
Address:	871 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9510771 / 1995-12-11
Facility ID:	9510771
Site ID:	137664
Spill Date:	1995-11-27
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	1995-11-27
CID:	282
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-11-27
Spill Record Last Update:	1996-01-04
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	DONALD BORNKAMP
Spiller Phone:	(718) 927-8209
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	117753

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY
Remarks: TANK OVERFILL IN A UNDERGROUND TANK AT THAT SITE.IT WAS ALL CLEANED UP.

All Materials:
Site ID: 137664
Operable Unit ID: 1025210
Operable Unit: 01
Material ID: 358123
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 15.00
Units: G
Recovered: 15.00
Resource Affected: Soil
Oxygenate: Not reported

CBS AST:
CBS Number: 2-000283
ICS Number: Not reported
PBS Number: 2-190233
MOSF Number: Not reported
SPDES Number: Not reported
Facility Status: IN SERVICE
Facility Type: F
Telephone: (212) 690-9602
Facility Town: NEW YORK CITY
Region: STATE
Expiration Date: 08/11/2003
Total Capacity of All Active Tanks(gal): 2000
Operator: NEW YORK CITY TRANSIT
Emergency Contact: HOWARD MATZA
Emergency Phone: (718) 243-4581
Owner Name: NEW YORK CITY TRANSIT
Owner Address: 370 JAY STREET ROOM 819
Owner City,St,Zip: BROOKLYN, NY 11201
Owner Telephone: (718) 243-4581
Owner Type: State Government
Owner Sub Type: None
Mail Name: NEW YORK CITY TRANSIT
Mail Contact Addr: 370 JAY STREET
Mail Contact Addr2: ROOM 819
Mail Contact Contact: JOSEPHINE BROWN
Mail Contact City,St,Zip: BROOKLYN, NY 11201
Mail Phone: (718) 243-4581

Tank Id: CBS-JAC-1
CAS Number: 107211
Federal ID: Not reported
Tank Status: In Service
Install Date: 12/99
Tank Closed: Not reported
Capacity (Gal): 1000

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

Chemical:	Ethylene glycol
Tank Location:	Indoors, Belowground
Tank Type:	Fiberglass coated steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	08/10/1995
Certified Date:	06/06/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Cathodically Protected
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	In_Tank System
Overfill Protection:	23
Haz Percent:	100
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	04/30/2001

Tank Id:	CBS-JAC-2
CAS Number:	107211
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/84
Tank Closed:	Not reported
Capacity (Gal):	1000
Chemical:	Ethylene glycol
Tank Location:	Indoors, Belowground
Tank Type:	Steel/carbon steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Double-Walled Tank
Tank Error Status:	No Missing Data
Date Entered:	08/10/1995
Certified Date:	06/06/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Galvanized Steel

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	49
Overfill Protection:	23
Haz Percent:	100
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	04/30/2001

SPILLS:

Name:	JACKIE GLEASON DEPOT
Address:	871 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0413523 / 2005-06-27
Facility ID:	0413523
Facility Type:	ER
DER Facility ID:	117753
Site ID:	342651
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-03-21
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2005-03-29
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-29
Spill Record Last Update:	2005-06-27
Spiller Name:	RACHEAL KROWN
Spiller Company:	JACKIE GLEASON DEPOT
Spiller Address:	871 5TH AVE
Spiller Company:	001
Contact Name:	RACHEAL KROWN
DEC Memo:	HYDRALIC LIFT FAILED AND WENT INTO CONFINMENT PIT AND WAS PUMPED OUT THAT DAY:

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

Remarks: 06-27-05: Hydraulic lift failure into secondary contaminment pit. Product discovered in 4 other pits. Pits cleaned by inhouse staff. Standing water test performed on all pits. They held.

All Materials:
Site ID: 342651
Operable Unit ID: 1101372
Operable Unit: 01
Material ID: 581531
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 100.00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

Name: JACKIE GLEASON BUS DEPOT
Address: 871 5TH AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0708260 / 2007-11-02
Facility ID: 0708260
Facility Type: ER
DER Facility ID: 117753
Site ID: 389114
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2007-10-29
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 2007-10-29
CID: 444
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: Not reported
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2007-10-29
Spill Record Last Update: 2007-11-02
Spiller Name: GEORGE CUNNINGHAM
Spiller Company: JACKIE GLEASON BUS DEPOT
Spiller Address: 871 5TH AVE
Spiller Company: 001
Contact Name: GEORGE CUNNINGHAM
DEC Memo: still investigating what caused spill, and is all cleaned up :
Remarks: Spill at Depot onto cement/pavement. All cleaned up.

All Materials:
Site ID: 389114

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

Operable Unit ID:	1146265
Operable Unit:	01
Material ID:	2136634
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Resource Affected:	Soil
Oxygenate:	Not reported

Site ID:	389114
Operable Unit ID:	1146265
Operable Unit:	01
Material ID:	2136655
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	JACKIE GLEASON BUS DEPOT
Address:	871 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0702197 / 2007-05-29
Facility ID:	0702197
Facility Type:	ER
DER Facility ID:	117753
Site ID:	381875
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	2007-05-23
Investigator:	jbvought
Referred To:	Not reported
Reported to Dept:	2007-05-23
CID:	444
Water Affected:	CATCH BASIN
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-05-23
Spill Record Last Update:	2007-05-29
Spiller Name:	JOSEPHINE BROWNE

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

Spiller Company:	JACKIE GLEASON BUS DEPOT
Spiller Address:	871 5TH AVE
Spiller Company:	001
Contact Name:	JOSEPHINE BROWNE
DEC Memo:	OVERFILL OF A GENERATER AND IS CLEANED UP: 1-2 GALLONS WENT INTO A CATCH BASIN
Remarks:	Need to call system safety dept.to follow up on that. 05/25/07 Rahman- Left a messege for Jim Houser to follow up on clean up. 05/29/07-Vought-Spill transferred from Rahman to Vought. Spoke to Josephine Brown and spill on concrete and no sewers or drains affected. Spill cleaned using absorbent material. Spill closed by Vought.

All Materials:

Site ID:	381875
Operable Unit ID:	1139301
Operable Unit:	01
Material ID:	2129331
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	JACKIE GLEASON DEPOT
Address:	871 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9705882 / 2004-10-07
Facility ID:	9705882
Facility Type:	ER
DER Facility ID:	117753
Site ID:	137665
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	2401
Spill Date:	1997-08-14
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1997-08-14
CID:	371
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-08-14
Spill Record Last Update:	2004-10-07
Spiller Name:	CLAIRE SPEILBERG

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

Spiller Company:	NYCT
Spiller Address:	871 5TH AVE
Spiller Company:	001
Contact Name:	CLAIRE SPEILBERG
DEC Memo:	DRUM OF WAST OIL BEING LIFTED BY FORKLIFT AND WAS ACCIDENTALLY SPEARED CAUSING SPILL - SPILL GOES INTO DRAIN WITH OIL/WATER SEPARATER - CLEANUP IN PROGRESS.UPDATE-SPILL WENT INTO STORM BASIN AND IS BEING CLEANED UP.
Remarks:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 10/9/03 - AUSTIN - TRANS. FROM HALE TO TIBBE - END 10/07/04: As per NYCT's e-mail dated 10/05/04, a 55 gallon drum of motor oil was overturned while being transported by a forklift. Most of the oil was contained and cleaned by NYCT but some entered a nearby sewer catch basin. Allstate Power Vac was hired to clean the catch basin. Neither OSS nor DOB has any further information about this spill.

All Materials:

Site ID:	137665
Operable Unit ID:	1049142
Operable Unit:	01
Material ID:	331495
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	55.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	871 5TH AVE
Address:	871 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9803068 / 2003-11-12
Facility ID:	9803068
Facility Type:	ER
DER Facility ID:	117753
Site ID:	137666
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	2401
Spill Date:	1998-06-09
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1998-06-09
CID:	205
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

Remediation Phase:	0
Date Entered In Computer:	1998-06-09
Spill Record Last Update:	2003-11-12
Spiller Name:	JIMMY CORTNEY
Spiller Company:	NYC TRANSIT
Spiller Address:	370 JAY STREET
Spiller Company:	001
Contact Name:	JIMMY CORTNEY
DEC Memo:	WORKER TRANSFERING FLUIDS, SPILLED 5 GAL TO GROUND. CLEANUP IN PROGRESS. SOME SPILLED TO SEWER DRAIN.
Remarks:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE transfered from Hale to Tibbe on 3/18/03. Spill during trasnfer. No impact to sewer. Contained and cleaned by NYCT.

All Materials:

Site ID:	137666
Operable Unit ID:	1060891
Operable Unit:	01
Material ID:	321394
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	5.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	JACKIE GLEASON DEPOT
Address:	871 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9902851 / 2003-03-03
Facility ID:	9902851
Facility Type:	ER
DER Facility ID:	117753
Site ID:	137667
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	1999-06-11
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1999-06-11
CID:	371
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-06-11

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

Spill Record Last Update:	2003-03-03
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	product may by lube oil -- drums that were supposed to be empty had some left in them..spill occurred when the drums were being disposed of...some went into a drain which may have connected to sewer... further investigation in progress. chris thomasello was on scene.
Remarks:	Not reported

All Materials:

Site ID:	137667
Operable Unit ID:	1077458
Operable Unit:	01
Material ID:	302782
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

Name:	JACKIE GLEASON DEPOT - NYCT
Address:	871 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9908589 / 2005-06-13
Facility ID:	9908589
Facility Type:	ER
DER Facility ID:	117753
Site ID:	137668
DEC Region:	2
Spill Cause:	Other
Spill Class:	B3
SWIS:	2401
Spill Date:	1999-10-13
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1999-10-14
CID:	390
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-14
Spill Record Last Update:	2005-06-13

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	GEORGE MANDUINA
DEC Memo:	tank was being filled - is a roof unit and 100 - 150 gals of oil were spilled in the filling process Not reported
Remarks:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 06/13/05: A heating contractor, Roy Kay, Inc., was modifying the roof top heating units to operate on duel fuel. While bleeding the lines of air, the operation was left unattended and an unknown amount of heating oil was released to the roof and apparently impacted a roof drain leading to a NYCDEP sewer. It is unsure how much was lost because of an unexplained inventory descrepency. At the time of the spill, both boilers were turned off but the facilities Dravo unit (another type of heating unit) and water heater were still active. Also, in order to bleed the roof top lines, an unknown amount of product was pumped off and most likely removed by the contractor; yet there was a descrepency of 242 gallons. Also, the contractor did not inform NYCT or make notification to DEC of the spill at the time it happened. The contractor attempted to perform the cleanup without telling anyone. Once discovered, NYCT hired an emergency response contractor to remove all of the contaminated debris already generated by the heating contractor and to finish the remaining cleanup. This did not allow NYCT to accurately determine the extent of the spill, nor the possible amount lost. The tank is and was at that time, a double walled fiberglass tank with interstitial monitoring and double walled piping with leak monitoring sump sensors. There is no record of any alarms from the intersttial or sumps sensors and no report of a loss of product in any of the log books. It would appear that the tank was not leaking but that product was being with drawn from the tank for several reason and that the product was no accounted for.

All Materials:

Site ID:	137668
Operable Unit ID:	1082861
Operable Unit:	01
Material ID:	297699
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	150.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

Name:	JACKIE GLEASON DEPOT
Address:	871 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0211807 / 2004-03-17
Facility ID:	0211807
Facility Type:	ER
DER Facility ID:	117753
Site ID:	137661

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2003-02-26
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2003-02-28
CID:	199
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-28
Spill Record Last Update:	2004-03-19
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JOSEPHINE BROWN
DEC Memo:	product found in three sumps at location - product found while doing routine inspections - no further materal found unk where it came from
Remarks:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE Product discovered in sumps of diesel tanks. Check valve gaskets were leaking into sumps. Product contained in sumps as confirmed by testing. Check valve gaskets were replaced for all diesel tanks. Product was also discovered in fill spill buckets due to clogged valves. Spill buckets were cleaned and valves unclogged. Product was also found around the waste oil catch basin. Sloppy housekeeping. Area was cleaned by NYCT personnel.

All Materials:

Site ID:	137661
Operable Unit ID:	865254
Operable Unit:	01
Material ID:	511592
Material Code:	0013
Material Name:	lube oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

Site ID:	137661
Operable Unit ID:	865254
Operable Unit:	01
Material ID:	511593
Material Code:	0022
Material Name:	waste oil/used oil

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

Site ID:	137661
Operable Unit ID:	865254
Operable Unit:	01
Material ID:	511590
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	JACKIE GLEASON DEPOT
Address:	871 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0402205 / 2004-06-08
Facility ID:	0402205
Facility Type:	ER
DER Facility ID:	117753
Site ID:	137662
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-05-28
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2004-05-28
CID:	403
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-05-28
Spill Record Last Update:	2004-06-08
Spiller Name:	Not reported
Spiller Company:	CIRCLE LUBRICANTS
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	CLAIRE SANNON
DEC Memo:	250 gallons of motor spilled. the vendor was delivering motor oil and

JACKIE GLEASON (FIFTH AVENUE) BUS DEPOT (Continued) **S102234408**

it spilled in the depot. the
spill is being cleaned up right now

Remarks: Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 180 gallons of motor oil spilled during delivery of drums from Circle Libricants. Contractor dropped 9 drums from truck. Contained and cleaned by NYCT.

All Materials:

Site ID:	137662
Operable Unit ID:	885990
Operable Unit:	01
Material ID:	489838
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	500.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Q156 **NYCTA JACKIE GLEASON DEPOT** **RCRA NonGen / NLR** **1000140968**
East **871 5TH AVE** **US AIRS** **NYD980642300**
1/8-1/4 **BROOKLYN, NY 11201** **NJ MANIFEST**
0.154 mi.
814 ft. **Site 5 of 9 in cluster Q**

Relative: **Higher**

Actual: **77 ft.**

RCRA Listings:

Date Form Received by Agency:	20221109
Handler Name:	Nycta Jackie Gleason Depot
Handler Address:	5TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11201
EPA ID:	NYD980642300
Contact Name:	ISABEL POTTER
Contact Address:	BROADWAY 27TH FL
Contact City,State,Zip:	NEW YORK, NY 10004
Contact Telephone:	646-252-5777
Contact Fax:	Not reported
Contact Email:	ENVIRONMENTALPROTECTIONNYCT@NYCT.COM
Contact Title:	SYSTEM SAFETY SPECIALIST
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	BROADWAY 27TH FL
Mailing City,State,Zip:	NEW YORK, NY 10004
Owner Name:	Nycta
Owner Type:	State
Operator Name:	Nycta
Operator Type:	State
Short-Term Generator Activity:	No

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20221109
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D006
Waste Description: Cadmium

Waste Code: D008
Waste Description: Lead

Waste Code: X001
Waste Description: Not Defined

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: NYCTA	
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 27TH FL
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CITY OF NEW YORK	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CITY OF NEW YORK	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NYCTA	
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 27TH FL
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYCTA	
Legal Status:	State
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 27TH FL
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	Not reported

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYCTA
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2 BROADWAY 27TH FL
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF NEW YORK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20221109
Handler Name: NYCTA JACKIE GLEASON DEPOT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20060101
Handler Name: NYCTA-JACKIE GLEASON DEPOT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCTA-JACKIE GLEASON DEPOT

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19820521
Handler Name: NYCTA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20210822
Handler Name: NYCTA JACKIE GLEASON DEPOT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19900301
Handler Name: NEW YORK CITY TRANSIT AUTHORITY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980204
Handler Name: NYCTA - JACKSON GLENON DEPOT
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020220
Handler Name: NYCTA-JACKIE GLEASON DEPOT
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 485111
NAICS Description: MIXED MODE TRANSIT SYSTEMS

NAICS Code: 485999
NAICS Description: ALL OTHER TRANSIT AND GROUND PASSENGER TRANSPORTATION

NAICS Code: 561599
NAICS Description: ALL OTHER TRAVEL ARRANGEMENT AND RESERVATION SERVICES

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20031231
Actual Return to Compliance Date: 20040304
Return to Compliance Qualifier: Documented
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20040202
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2AHJ
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20031231
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: R2AHJ
Evaluation Responsible Sub-Organization: RCB

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Actual Return to Compliance Date:	20040304
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20160713
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

US AIRS (AFS):

Region Code:	02
County Code:	NY047
Programmatic ID:	AIR NY0000002610200079
Facility Registry ID:	110000808788
D and B Number:	Not reported
Facility Site Name:	NYC-TA JACKIE GLEASON BUS DEPOT & 38TH ST YARD
Primary SIC Code:	4173
NAICS Code:	221112
Default Air Classification Code:	SMI
Facility Type of Ownership Code:	Not reported
Air CMS Category Code:	SMI
HPV Status:	Not reported
Region Code:	02
County Code:	NY047
Programmatic ID:	AIR NY0000002610200079
Facility Registry ID:	110000808788
D and B Number:	Not reported
Facility Site Name:	NYC-TA JACKIE GLEASON BUS DEPOT & 38TH ST YARD
Primary SIC Code:	4173
NAICS Code:	488490
Default Air Classification Code:	SMI
Facility Type of Ownership Code:	Not reported
Air CMS Category Code:	SMI
HPV Status:	Not reported

US AIRS (AFS):

Region Code:	02
Programmatic ID:	AIR NY0000002610200079
Facility Registry ID:	110000808788
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2016-02-02 00:00:00
Activity Status Date:	2016-06-09 07:01:18

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2016-02-02 00:00:00
Activity Status Date: 2016-06-09 07:01:18
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: New Source Review Permit Requirements
Activity Date: 2016-02-02 00:00:00
Activity Status Date: 2016-06-09 07:01:18
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 13:07:40
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 13:07:40
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: New Source Review Permit Requirements
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-05-02 13:07:40
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Air Program: National Emission Standards for Hazardous Air Pollutants (40 CFR Part 61)
Activity Date: 2014-06-11 00:00:00
Activity Status Date: 2014-06-11 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Closed

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-02-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Review Permit Requirements
Activity Date: 2014-02-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2014-02-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-05-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Review Permit Requirements
Activity Date: 2013-05-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-05-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-05-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-05-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Review Permit Requirements
Activity Date: 2013-05-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Review Permit Requirements
Activity Date: 2013-02-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-02-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-02-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2012-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Review Permit Requirements
Activity Date: 2012-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-02-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Review Permit Requirements
Activity Date: 2011-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Air Program: New Source Review Permit Requirements
Activity Date: 2010-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Review Permit Requirements
Activity Date: 2009-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2009-02-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Review Permit Requirements
Activity Date: 2008-07-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-07-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Activity Date: 2008-07-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-07-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Review Permit Requirements
Activity Date: 2008-07-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-07-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Review Permit Requirements
Activity Date: 2008-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-12-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-12-11 00:00:00

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Review Permit Requirements
Activity Date: 2007-12-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-08-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Review Permit Requirements
Activity Date: 2005-08-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-08-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: New Source Review Permit Requirements
Activity Date: 2000-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-02-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NJ MANIFEST:
EPA ID: NYD980642300

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Name:	NYC TRANSIT AUTHORITY
Address:	845 5TH AVE
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPAID:	Not reported
Generator Flag:	D
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYD980642300
Manifest Number:	001031962JJK
Date Shipped:	05/14/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/14/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/14/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	55
Unit:	G

EPA ID:	NYD980642300
Manifest Number:	001029930JJK
Date Shipped:	03/01/2007
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/01/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/01/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H06
Quantity:	55

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Unit: G

EPA ID: NYD980642300
Manifest Number: 001085703GBF
Date Shipped: 08/20/2009
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 08/20/2009
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 08/20/2009
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: N
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D003
Hand Code: H061
Quantity: 55
Unit: G

EPA ID: NYD980642300
Manifest Number: 000959472GBF
Date Shipped: 03/17/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NJ0000027193
Transporter 2 EPA ID: Not reported

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/17/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/17/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	55
Unit:	G

EPA ID:	NYD980642300
Manifest Number:	NJA5209281
Date Shipped:	09/07/2004
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/07/2004

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/07/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	10130422
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

EPA ID:	NYD980642300
Manifest Number:	000959817GBF
Date Shipped:	3/26/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported
EPA ID:	NYD980642300
Manifest Number:	015626088JJK
Date Shipped:	3/30/2016
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported
EPA ID:	NYD980642300
Manifest Number:	015626088JJK
Date Shipped:	3/30/2016
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

EPA ID:	NYD980642300
Manifest Number:	003535038JJK
Date Shipped:	10/09/2007
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/09/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/09/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H06
Quantity:	55
Unit:	G

EPA ID:	NYD980642300
Manifest Number:	010407125JJK
Date Shipped:	6/7/2013
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001 F003 D035
Hand Code:	Not reported
Quantity:	55.00
Unit:	gallons

EPA ID:	NYD980642300
Manifest Number:	003535289JJK
Date Shipped:	01/25/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD063147797
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/25/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/25/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

NYCTA JACKIE GLEASON DEPOT (Continued) **1000140968**

Waste:
- Manifest Year: Not reported
- Waste Code: D008
- Hand Code: H111
- Quantity: 425
- Unit: G

Click this hyperlink while viewing on your computer to access
41 additional NJ MANIFEST: record(s) in the EDR Site Report.

Q157 **871 5TH AV/JACKIE GLEASON** **UST FINDER RELEASE** **1029057923**
East **871 5TH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 0**
0.154 mi.
814 ft. **Site 6 of 9 in cluster Q**

Relative: **Higher**
Actual: **77 ft.**

UST FINDER RELEASE:
- Object ID: 255952
- Facility ID: NY117753
- Lust ID: NY9106350
- Name: 871 5TH AV/JACKIE GLEASON
- Address: 871 5TH AVE
- City,State,Zip: BROOKLYN, NY 0
- Address Match Type: Not reported
- Reported Date: 1991/09/12 15:59:59+00
- Status: No Further Action
- Substance: Not reported
- Population within 1500ft: 8765
- Domestic Wells within 1500ft: 13
- Land Use: Developed, High Intensity
- Within SPA: No
- SPA PWS Facility ID: Not reported
- SPA Water Type: Not reported
- SPA Facility Type: Not reported
- SPA HUC12: Not reported
- Within WHPA: No
- WHPA PWS Facility ID: Not reported
- WHPA Water Type: Not reported
- WHPA Facility Type: Not reported
- WHPA HUC12: Not reported
- Within 100yr Floodplain: No
- Tribe: Not reported
- EPA Region: 2
- NFA Letter 1: Not reported
- NFA Letter 2: Not reported
- NFA Letter 3: Not reported
- NFA Letter 4: Not reported
- Closed With Residual Contaminate: Not reported
- Coordinate Source: State
- X Coord: -74.00312
- Y Coord: 40.6519200000001
- Latitude: 40.6519199999999
- Longitude: -74.0031199999999

M158 **SUNSET GARDENS SENIOR HOUSING** **UST FINDER** **1028582027**
SW **405 44TH STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.160 mi.
843 ft. **Site 12 of 13 in cluster M**

Relative:
Higher

Actual:
81 ft.

UST FINDER:

Object ID:	294879
Facility ID:	NY383420
Name:	SUNSET GARDENS SENIOR HOUSING
Address:	405 44TH STREET
City,State,Zip:	BROOKLYN, NY 11220
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	5
TOS USTs:	0
Population 1500ft:	16192
Private Wells 1500ft:	39
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-74.0088279999999
Y Coord:	40.649725
Latitude:	40.649725
Longitude:	-74.008828

UST FINDER:

Object ID:	1254306
Facility ID:	NY383420
Tank ID:	NY100764
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1254307
Facility ID:	NY383420
Tank ID:	NY100765
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported

SUNSET GARDENS SENIOR HOUSING (Continued) **1028582027**

Object ID:	1254308
Facility ID:	NY383420
Tank ID:	NY100774
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	2000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1254309
Facility ID:	NY383420
Tank ID:	NY102821
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1254310
Facility ID:	NY383420
Tank ID:	NY122091
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

M159 **SUNSET GARDENS SENIOR HOUSING** **NY UST** **U004107540**
SW **405 44TH STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.160 mi.
843 ft. **Site 13 of 13 in cluster M**

Relative:
Higher

Actual:
81 ft.

UST:

Name:	SUNSET GARDENS SENIOR HOUSING
Address:	405 44TH STREET
City,State,Zip:	BROOKLYN, NY 11220
Id/Status:	2-610597 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	583799.46093
UTM Y:	4500346.60389
Site Type:	Hospital/Nursing Home/Health Care

Affiliation Records:

Site Id:	383420
Affiliation Type:	Facility Owner
Company Name:	LUTHERAN MEDICAL CENTER
Contact Type:	SENIOR VICE-PRESIDENT
Contact Name:	MILES DAVIS
Address1:	EXEC.OFFICES, 150 55TH ST. 3RD FL
Address2:	Not reported

SUNSET GARDENS SENIOR HOUSING (Continued) **U004107540**

City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 630-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-06-26

Site Id:	383420
Affiliation Type:	Mail Contact
Company Name:	LUTHERAN MEDICAL CENTER
Contact Type:	Not reported
Contact Name:	MILES DAVIS
Address1:	EXECUTIVE OFFICES
Address2:	150 55TH STREET, 3RD FLOOR
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 630-7000
EMail:	MDAVIS@IMCMC.COM
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-06-26

Site Id:	383420
Affiliation Type:	Facility Operator
Company Name:	SUNSET GARDENS SENIOR HOUSING
Contact Type:	Not reported
Contact Name:	MYLES DAVIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 630-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-06-26

Site Id:	383420
Affiliation Type:	Emergency Contact
Company Name:	LUTHERAN MEDICAL CENTER
Contact Type:	Not reported
Contact Name:	MYLES DAVIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 630-7000
EMail:	Not reported

SUNSET GARDENS SENIOR HOUSING (Continued) **U004107540**

Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2007-06-26

Tank Info:

Tank Number: 1
Tank ID: 217958
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 10/04/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0002
Common Name of Substance: #4 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None

Tank Number: 2
Tank ID: 217959
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 09/29/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported

SUNSET GARDENS SENIOR HOUSING (Continued) **U004107540**

Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None

Tank Number: 3
Tank ID: 217960
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 10/24/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
J00 - Dispenser - None
G00 - Tank Secondary Containment - None

Tank Number: 4
Tank ID: 217961
Tank Status: Closed - Removed
Material Name: Closed - Removed

SUNSET GARDENS SENIOR HOUSING (Continued) **U004107540**

Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 10/24/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None

Tank Number: 5
Tank ID: 217962
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 10/24/2006
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None

SUNSET GARDENS SENIOR HOUSING (Continued) **U004107540**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
J00 - Dispenser - None

R160 **CON EDISON SERVICE BOX: 48298** **RCRA NonGen / NLR** **1016966445**
SE **519 41ST ST** **NY MANIFEST** **NYP004392940**
1/8-1/4 **BROOKLYN, NY 11231**
0.160 mi.
843 ft. **Site 3 of 4 in cluster R**

Relative: **Higher**
Actual: **110 ft.**

RCRA Listings:

Date Form Received by Agency:	20131218
Handler Name:	Con Edison Service Box: 48298
Handler Address:	41ST ST
Handler City,State,Zip:	BROOKLYN, NY 11231
EPA ID:	NYP004392940
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported

CON EDISON SERVICE BOX: 48298 (Continued) **1016966445**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131118
Handler Name: CON EDISON SERVICE BOX:	48298
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131218
Handler Name: CON EDISON SERVICE BOX:	48298
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

CON EDISON SERVICE BOX: 48298 (Continued) **1016966445**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004392940
Country:	USA
Name:	CON EDISON
Address:	519 41ST ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11231
Zip 4:	Not reported
Location Address 1:	519 41ST ST
Location Address 2:	SB48298
Location City,State,Zip:	BROOKLYN, NY 11215
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/18/2013
Trans1 Recv Date:	11/18/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/20/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004392940
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299105GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON SERVICE BOX: 48298 (Continued) **1016966445**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Q161 **CON EDISON SERVICE BOX: 49215** **RCRA NonGen / NLR** **1016963837**
ESE **518 39TH ST** **NY MANIFEST** **NYP004368056**
1/8-1/4 **BROOKLYN, NY 11229**
0.160 mi.
846 ft. **Site 7 of 9 in cluster Q**

Relative: **Higher**
Actual: **89 ft.**

RCRA Listings:

Date Form Received by Agency:	20131030
Handler Name:	Con Edison Service Box: 49215
Handler Address:	39TH ST
Handler City,State,Zip:	BROOKLYN, NY 11229
EPA ID:	NYP004368056
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON SERVICE BOX: 49215 (Continued) **1016963837**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130930
Handler Name: CON EDISON SERVICE BOX:	49215
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 49215 (Continued) **1016963837**

Receive Date:	20131030
Handler Name: CON EDISON SERVICE BOX:	49215
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004368056
Country:	USA
Name:	CON EDISON
Address:	518 39TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11229
Zip 4:	Not reported
Location Address 1:	518-39TH ST
Location Address 2:	SB49215
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported

CON EDISON SERVICE BOX: 49215 (Continued) **1016963837**

Generator Ship Date:	09/30/2013
Trans1 Recv Date:	09/30/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004368056
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002290938GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	150
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

U162 **CON EDISON SERVICE BOX: 45061** **RCRA NonGen / NLR** **1016960661**
WNW **4018 3RD AVE** **NY MANIFEST** **NYP004327599**
1/8-1/4 **BROOKLYN, NY 11220**
0.168 mi.
889 ft. **Site 1 of 2 in cluster U**

Relative: RCRA Listings:
Lower

Date Form Received by Agency:	20130811
Handler Name:	Con Edison Service Box: 45061
Handler Address:	3RD AVE
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NYP004327599
Contact Name:	ANTHONY SIGNORE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported

Actual:
24 ft.

CON EDISON SERVICE BOX: 45061 (Continued) **1016960661**

Contact Telephone:	718-666-4714
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	GENERAL UTILITY WORKER L1-2
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported

CON EDISON SERVICE BOX: 45061 (Continued) **1016960661**

Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20130711
Handler Name: CON EDISON SERVICE BOX: 45061
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130811
Handler Name: CON EDISON SERVICE BOX: 45061
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004327599
Country: USA
Name: CON EDISON
Address: 4018 3RD AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11220
Zip 4: Not reported
Location Address 1: 4018 3 AVE
Location Address 2: SB #45061
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported

CON EDISON SERVICE BOX: 45061 (Continued) **1016960661**

Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 07/11/2013
Trans1 Recv Date: 07/11/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/16/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004327599
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002084615GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 60
Units: Gallons (liquids only)
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)

CON EDISON SERVICE BOX: 45061 (Continued) **1016960661**

Handling Method: Treat
Specific Gravity: 1

V163 **CON EDISON** **RCRA NonGen / NLR** **1019908258**
NNW **38TH ST & 3RD AVE** **FINDS** **NYP004843781**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.170 mi.
898 ft. **Site 1 of 3 in cluster V**

Relative: **Lower**
Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	20150924
Handler Name:	Con Edison
Handler Address:	38TH ST & 3RD AVE
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYP004843781
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No

CON EDISON (Continued) **1019908258**

Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150924
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150924
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON (Continued) **1019908258**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069664492

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019908258
Registry ID:	110069664492
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069664492
Name:	CON EDISON
Address:	38TH ST & 3RD AVE
City,State,Zip:	BROOKLYN, NY 11215

T164 **NYC DEPT OF EDUCATION - PUBLIC SCHOOL 371K** **NY MANIFEST** **S118091626**
NNE **355 37TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.170 mi.
898 ft. **Site 3 of 7 in cluster T**

Relative:
Lower

Actual:
28 ft.

NY MANIFEST:

EPA ID:	NYR000214080
Country:	USA
Name:	NYC DEPT OF EDUCATION - PUBLIC SCHOOL 371K
Address:	355 37TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	355 37TH STREET
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	NYC DEPT OF EDUCATION - PUBLIC SCHOOL 371K
Mailing Contact:	NYC SCHOOL CONSTRUCTION AUTHORITY - PS 371K &PS 231K
Mailing Address 1:	355 37TH ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11232
Mailing Zip 4:	Not reported
Mailing Country:	USA

NYC DEPT OF EDUCATION - PUBLIC SCHOOL 371K (Continued) **S118091626**

Mailing Phone: 9178076744

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/26/2015
Trans1 Recv Date:	05/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/03/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000214080
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAC300017498
TSDF ID 2:	Not reported
Manifest Tracking Number:	000787741VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H039
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1600
Units:	Kilograms
Number of Containers:	6
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	1

T165 **P.S. 371 (OLD 615) - BROOKLYN K371** **NY AST** **U003394317**
NNE **355 37TH STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.170 mi.
898 ft. **Site 4 of 7 in cluster T**

Relative:
Lower

Actual:
28 ft.

AST:

Name:	P.S. 371 (OLD 615) - BROOKLYN K371
Address:	355 37TH STREET
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-355798
Program Type:	PBS
UTM X:	584085.89282
UTM Y:	4500836.83023
Expiration Date:	06/28/2023
Site Type:	School

Affiliation Records:

Site Id:	17746
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	MUNENDRA SHARMA
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-07-17

Site Id:	17746
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	JOSEPH YOUNGHESE
Address1:	FIELD OPERATIONS - FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5779
EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-11-14

Site Id:	17746
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	KEN MAHADEO

P.S. 371 (OLD 615) - BROOKLYN K371 (Continued) **U003394317**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-03

Site Id:	17746
Affiliation Type:	Facility Operator
Company Name:	P.S. 371 (OLD 615) - BROOKLYN K371
Contact Type:	Not reported
Contact Name:	SALVATORE CALDERONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 788-7608
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-28

Tank Info:

Tank Number:	001
Tank Id:	34748
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	L00 - Piping Leak Detection - None
	J02 - Dispenser - Suction Dispenser
	C03 - Pipe Location - Aboveground/Underground Combination
	I05 - Overfill - Vent Whistle
	G02 - Tank Secondary Containment - Vault (w/access)
	I04 - Overfill - Product Level Gauge (A/G)
	E00 - Piping Secondary Containment - None
	K00 - Spill Prevention - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	F01 - Pipe External Protection - Painted/Asphalt Coating
	A00 - Tank Internal Protection - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1966

P.S. 371 (OLD 615) - BROOKLYN K371 (Continued) **U003394317**

Capacity Gallons:	6000
Tightness Test Method:	34
Date Test:	07/06/2023
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	LABATIST
Last Modified:	08/29/2023
Material Name:	#4 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	34749
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
C03 - Pipe Location - Aboveground/Underground Combination
J02 - Dispenser - Suction Dispenser
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
I04 - Overfill - Product Level Gauge (A/G)
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1966
Capacity Gallons:	6000
Tightness Test Method:	34
Date Test:	07/06/2023
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	LABATIST
Last Modified:	08/29/2023
Material Name:	#4 fuel oil (on-site consumption)

T166 **PUBLIC SCHOOL 371K** **RCRA-LQG** **1016974947**
NNE **355 37TH ST** **NYR000214080**
1/8-1/4 **BROOKLYN, NY 11232**
0.170 mi.
898 ft. **Site 5 of 7 in cluster T**

Relative: RCRA Listings:
Lower

Date Form Received by Agency:	20160222
Handler Name:	Public School 371k
Handler Address:	37TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232

Actual:
28 ft.

PUBLIC SCHOOL 371K (Continued) **1016974947**

EPA ID:	NYR000214080
Contact Name:	ALEXANDER LEMPERT
Contact Address:	THOMSON AVENUE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-472-8501
Contact Fax:	518-402-9767
Contact Email:	ALEMPERT@NYCSCA.ORG
Contact Title:	SCAIEH SR. DIRECTOR
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	THOMSON AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Nyc Department Of Education
Owner Type:	Municipal
Operator Name:	Nyc Department Of Education
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No

PUBLIC SCHOOL 371K (Continued) **1016974947**

Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: NYC DEPARTMENT OF EDUCATION
Legal Status: Municipal
Date Became Current: 19000101
Date Ended Current: Not reported
Owner/Operator Address: 44-36 VERNON BLVD
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC DEPARTMENT OF EDUCATION
Legal Status: Municipal
Date Became Current: 19000101
Date Ended Current: Not reported
Owner/Operator Address: 44-36 VERNON BLVD
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYC DEPT OF SCHOOL FACILITIES
Legal Status: Municipal
Date Became Current: 19661121
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC DEPT OF EDUCATION
Legal Status: Municipal
Date Became Current: 19661121
Date Ended Current: Not reported
Owner/Operator Address: 30-30 THOMSON AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101

PUBLIC SCHOOL 371K (Continued) **1016974947**

Owner/Operator Telephone: 718-742-8501
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160222
Handler Name: PUBLIC SCHOOL 371K
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20141021
Handler Name: NYC DEPT OF EDUCATION - PS 371K
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 61111
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

NAICS Code: 611110
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

R167
SE
1/8-1/4
0.171 mi.
905 ft.

PARK SLOPE HOMES, INC.
521-531 41ST STREET
BROOKLYN, NY 11232

Site 4 of 4 in cluster R

NY AST **S107782632**
N/A

Relative:
Higher

Actual:
114 ft.

AST:

Name:	PARK SLOPE HOMES, INC.
Address:	521-531 41ST STREET
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-600242
Program Type:	PBS
UTM X:	584162.11518
UTM Y:	4500371.06088
Expiration Date:	N/A
Site Type:	Private Residence

Affiliation Records:

Site Id:	22225
Affiliation Type:	Facility Owner
Company Name:	PARK SLOPE HOMES, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	521-531 41ST STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(718) 437-4057
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22225
Affiliation Type:	Mail Contact
Company Name:	PARK SLOPE HOMES, INC.
Contact Type:	Not reported
Contact Name:	PRES., BOARD OF DIRECTORS
Address1:	521-531 41ST STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(718) 437-4057
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22225
Affiliation Type:	Facility Operator
Company Name:	PARK SLOPE HOMES, INC.
Contact Type:	Not reported
Contact Name:	GREGORY LOUIS

PARK SLOPE HOMES, INC. (Continued) **S107782632**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 437-4057
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22225
Affiliation Type:	Emergency Contact
Company Name:	PARK SLOPE HOMES, INC.
Contact Type:	Not reported
Contact Name:	GAIL ALI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 853-7021
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	41662
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	B00 - Tank External Protection - None
	F00 - Pipe External Protection - None
	C01 - Pipe Location - Aboveground
	G01 - Tank Secondary Containment - Diking (Aboveground)
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/01/2000

PARK SLOPE HOMES, INC. (Continued) **S107782632**

Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

Q168 **CON EDISON** **NY MANIFEST** **S117065058**
ESE **523 39TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.177 mi.
933 ft. **Site 8 of 9 in cluster Q**

Relative: **Higher**
Actual: **90 ft.**

NY MANIFEST:
EPA ID: NYP004575841
Country: USA
Name: CON EDISON
Address: 523 39TH ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: 523 39 ST
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 06/25/2014
Trans1 Recv Date: 06/25/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/26/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004575841
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002502933GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N

CON EDISON (Continued) **S117065058**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	300
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Q169 **CON EDISON SERVICE BOX: 49212** **RCRA NonGen / NLR** **1017779581**
ESE **523 39TH ST** **NYP004575841**
1/8-1/4 **BROOKLYN, NY 11232**
0.177 mi.
933 ft. **Site 9 of 9 in cluster Q**

Relative: **Higher**

Actual: **90 ft.**

RCRA Listings:

Date Form Received by Agency:	20140725
Handler Name:	Con Edison Service Box: 49212
Handler Address:	39TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004575841
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003

CON EDISON SERVICE BOX: 49212 (Continued) **1017779581**

Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140625
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CON EDISON SERVICE BOX: 49212 (Continued) **1017779581**

Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20140625
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20140725
Handler Name: CON EDISON SERVICE BOX:	49212
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

W170 **CON EDISON** **NY MANIFEST** **S116043694**
ENE **457 37TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.180 mi.
953 ft. **Site 1 of 8 in cluster W**

Relative:
Higher

Actual:
53 ft.

NY MANIFEST:

EPA ID:	NYP004400586
Country:	USA
Name:	CON EDISON
Address:	457 37TH ST
Address 2:	SB49125
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	457 37TH ST
Location Address 2:	SB49125
Location City,State,Zip:	BROOKLYN, NY 11232

CON EDISON (Continued) **S116043694**

Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 12/05/2013
Trans1 Recv Date: 12/05/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/09/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004400586
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002300217GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 40

CON EDISON (Continued) **S116043694**

Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

X171 **CON EDISON SERVICE BOX: 25996** **RCRA NonGen / NLR** **1017771527**
West **43RD AVE & 3RD ST N OF** **FINDS** **NYP004484671**
1/8-1/4 **NEW YORK, NY 10009**
0.181 mi.
958 ft. **Site 1 of 5 in cluster X**

Relative: **Lower**
Actual: **35 ft.**

RCRA Listings:

Date Form Received by Agency:	20140430
Handler Name:	Con Edison Service Box: 25996
Handler Address:	43RD AVE & 3RD ST N OF
Handler City,State,Zip:	NEW YORK, NY 10009
EPA ID:	NYP004484671
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported

CON EDISON SERVICE BOX: 25996 (Continued) **1017771527**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140331
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140331
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140430
Handler Name: CON EDISON SERVICE BOX:	25996
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No

CON EDISON SERVICE BOX: 25996 (Continued) **1017771527**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063783035

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Y172 **CON EDISON** **NJ MANIFEST** **S120667623**
ESE **532 39TH ST SB49212** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.183 mi.
967 ft. **Site 1 of 9 in cluster Y**

Relative:
Higher

Actual:
97 ft.

NJ MANIFEST:

EPA ID:	NYP004735528
Name:	CON EDISON
Address:	532 39TH ST SB49212
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported

CON EDISON (Continued) **S120667623**

Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004735528
Manifest Number:	014091581JJK
Date Shipped:	2/22/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Y173 **CON EDISON** **NY MANIFEST** **S117740387**
ESE **532 39TH ST SB49212** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.183 mi.
967 ft. **Site 2 of 9 in cluster Y**

Relative:
Higher

Actual:
97 ft.

NY MANIFEST:

EPA ID:	NYP004735528
Country:	USA
Name:	CON EDISON

CON EDISON (Continued) **S117740387**

Address:	532 39TH ST SB49212
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	517 39 ST
Location Address 2:	SB49212
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/22/2015
Trans1 Recv Date:	02/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004735528
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091581JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported

CON EDISON (Continued) **S117740387**

Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Y174 **CON EDISON** **RCRA NonGen / NLR** **1018278770**
ESE **532 39TH ST SB49215** **FINDS** **NYP004735510**
1/8-1/4 **BROOKLYN, NY 11232** **ECHO**
0.183 mi.
967 ft. **Site 3 of 9 in cluster Y**

Relative: **Higher**
Actual: **97 ft.**

RCRA Listings:

Date Form Received by Agency:	20150222
Handler Name:	Con Edison
Handler Address:	39TH ST SB49215
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004735510
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

CON EDISON (Continued) **1018278770**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150222
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150222
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1018278770**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067680995

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018278770
Registry ID:	110067680995
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067680995
Name:	CON EDISON
Address:	532 39TH ST SB49212
City,State,Zip:	BROOKLYN, NY 11232

Y175 **CON EDISON** **NJ MANIFEST** **S120667622**
ESE **532 39TH ST SB49215** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.183 mi.
967 ft. **Site 4 of 9 in cluster Y**

Relative:
Higher

Actual:
97 ft.

NJ MANIFEST:

EPA ID:	NYP004735510
Name:	CON EDISON
Address:	532 39TH ST SB49215
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported

CON EDISON (Continued) **S120667622**

Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004735510
Manifest Number:	014088728JJK
Date Shipped:	2/22/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Y176 **CON EDISON** **NY MANIFEST** **S117735989**
ESE **532 39 ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.183 mi.
967 ft. **Site 5 of 9 in cluster Y**

Relative:
Higher

Actual:
97 ft.

NY MANIFEST:

EPA ID:	NYP000473510
Country:	USA
Name:	CON EDISON
Address:	532 39 ST
Address 2:	SB49215
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	532 39 ST
Location Address 2:	SB49215
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/22/2015
Trans1 Recv Date:	02/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP000473510
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014088728JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **S117735989**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Y177 **CON EDISON** **RCRA NonGen / NLR** **1018278771**
ESE **532 39TH ST SB49212** **NYP004735528**
1/8-1/4 **BROOKLYN, NY 11232**
0.183 mi.
967 ft. **Site 6 of 9 in cluster Y**

Relative: **Higher**

Actual: **97 ft.**

RCRA Listings:

Date Form Received by Agency:	20150222
Handler Name:	Con Edison
Handler Address:	39TH ST SB49212
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004735528
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No

CON EDISON (Continued) **1018278771**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150222
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150222
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1018278771**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

X178 **CON EDISON SERVICE BOX: 45068** **RCRA NonGen / NLR 1016960545**
West **4317 3RD AVE** **NY MANIFEST NYP004325569**
1/8-1/4 **BROOKLYN, NY 11220**
0.186 mi.
980 ft. **Site 2 of 5 in cluster X**

Relative: **Lower**
Actual: **37 ft.**

RCRA Listings:
Date Form Received by Agency: 20130808
Handler Name: Con Edison Service Box: 45068
Handler Address: 3RD AVE
Handler City,State,Zip: BROOKLYN, NY 11220
EPA ID: NYP004325569
Contact Name: ANTHONY SIGNORE
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 718-666-4714
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: GENERAL UTILITY WORKER L1-2
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Ny
State District: NYSDEC R2
Mailing Address: IRVING PL, RM 828
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported
Owner Type: Not reported
Operator Name: Not reported
Operator Type: Not reported
Short-Term Generator Activity: No
Importer Activity: No

CON EDISON SERVICE BOX: 45068 (Continued) **1016960545**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130708
Handler Name: CON EDISON SERVICE BOX:	45068
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130808
Handler Name: CON EDISON SERVICE BOX:	45068
Federal Waste Generator Description:	Not a generator, verified

CON EDISON SERVICE BOX: 45068 (Continued) **1016960545**

State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004325569
Country:	USA
Name:	CON EDISON
Address:	4317 3RD AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11220
Zip 4:	Not reported
Location Address 1:	4311 3 AVENUE
Location Address 2:	SB 45068
Location City,State,Zip:	BROOKLYN, NY 11220
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/08/2013
Trans1 Recv Date:	07/08/2013
Trans2 Recv Date:	Not reported

CON EDISON SERVICE BOX: 45068 (Continued) **1016960545**

TSD Site Recv Date:	09/11/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004325569
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002084311GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	70
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Z179 **533 41 ST** **NY UST** **U004222821**
SE **533 41ST STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.186 mi.
980 ft. **Site 1 of 9 in cluster Z**

Relative: **Higher**
Actual: **119 ft.**

UST:

Name:	533 41 ST
Address:	533 41ST STREET
City,State,Zip:	BROOKLYN, NY 11232
Id/Status:	2-297232 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584197.62262
UTM Y:	4500330.13403
Site Type:	Apartment Building/Office Building

533 41 ST (Continued) **U004222821**

Affiliation Records:

Site Id:	13718
Affiliation Type:	Mail Contact
Company Name:	A HEATING INC.
Contact Type:	Not reported
Contact Name:	EDITH FRIED
Address1:	P.O. BOX 190-147
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(718) 234-8441 301
EMail:	FAIGY@AHEATINGINC.COM
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2014-04-04

Site Id:	13718
Affiliation Type:	Facility Operator
Company Name:	533 41 STREET
Contact Type:	Not reported
Contact Name:	ALEX PIROZZI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 294-0244
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-12-28

Site Id:	13718
Affiliation Type:	Emergency Contact
Company Name:	533 PROPERTIES LLC
Contact Type:	Not reported
Contact Name:	ALEX PIROZZI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 857-7920
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-03-14

Site Id:	13718
Affiliation Type:	Facility Owner
Company Name:	533 PROPERTIES LLC
Contact Type:	Not reported
Contact Name:	Not reported

533 41 ST (Continued) **U004222821**

Address1:	122 76TH ST.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11209
Country Code:	001
Phone:	(718) 857-7920
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-03-14

Tank Info:

Tank Number:	001
Tank ID:	26049
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	3000
Install Date:	05/10/1960
Date Tank Closed:	12/24/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	10/18/2011
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
G02 - Tank Secondary Containment - Vault (w/access)
I05 - Overfill - Vent Whistle
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser

Z180 **533 41 ST** **UST FINDER** **1028568234**
SE **533 41ST STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.186 mi.
980 ft. **Site 2 of 9 in cluster Z**

Relative: **Higher**

Actual: **119 ft.**

UST FINDER:

Object ID:	294873
Facility ID:	NY13718
Name:	533 41 ST
Address:	533 41ST STREET
City,State,Zip:	BROOKLYN, NY 11232
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	13717
Private Wells 1500ft:	5
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-74.0041209999999
Y Coord:	40.6495360000001
Latitude:	40.649536
Longitude:	-74.004121

UST FINDER:

Object ID:	1202304
Facility ID:	NY13718
Tank ID:	NY15349
Tank Status:	Closed
Installation Date:	1960/05/10 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	3000
Substances:	Not reported
Tank Wall Type:	Not reported

Y181 **ORTIZ PROPERTIES** **RCRA NonGen / NLR** **1000981465**
ESE **535 40TH ST** **FINDS** **NY0001000157**
1/8-1/4 **BROOKLYN, NY 11232** **ECHO**
0.186 mi. **NY MANIFEST**
981 ft. **Site 7 of 9 in cluster Y**

Relative: **Higher**
Actual: **107 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Ortiz Properties
Handler Address:	40TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232-3003
EPA ID:	NY0001000157
Contact Name:	Not reported
Contact Address:	LIBERTY AVE
Contact City,State,Zip:	RICHMOND HILL, NY 11419
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	LIBERTY AVE
Mailing City,State,Zip:	RICHMOND HILL, NY 11419
Owner Name:	Rafael Cepeda
Owner Type:	Private
Operator Name:	Rafael Cepeda
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

ORTIZ PROPERTIES (Continued) **1000981465**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: RAFAEL CEPEDA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125-09 LIBERTY AVE
Owner/Operator City,State,Zip:	RICHMOND HILL, NY 11419
Owner/Operator Telephone:	718-835-7171
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: RAFAEL CEPEDA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125-09 LIBERTY AVE
Owner/Operator City,State,Zip:	RICHMOND HILL, NY 11419
Owner/Operator Telephone:	718-835-7171
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: RAFAEL CEPEDA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125-09 LIBERTY AVE
Owner/Operator City,State,Zip:	RICHMOND HILL, NY 11419
Owner/Operator Telephone:	718-835-7171
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

ORTIZ PROPERTIES (Continued) **1000981465**

Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990708
Handler Name: ORTIZ PROPERTIES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: ORTIZ PROPERTIES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ORTIZ PROPERTIES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19950105
Handler Name: ORTIZ PROPERTIES
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

ORTIZ PROPERTIES (Continued) **1000981465**

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004323599

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000981465
Registry ID:	110004323599
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004323599
Name:	ORTIZ PROPERTIES
Address:	535 40TH ST
City,State,Zip:	BROOKLYN, NY 11232

NY MANIFEST:

EPA ID:	NY0001000157
Country:	USA
Name:	RAFAEL CEPEDA
Address:	535 40TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232-3003
Zip 4:	Not reported
Location Address 1:	535 40TH ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	RAFAEL CEPEDA
Mailing Contact:	MARC GOLDSTEIN
Mailing Address 1:	535 40TH ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11232
Mailing Zip 4:	Not reported
Mailing Country:	USA

ORTIZ PROPERTIES (Continued) **1000981465**

Mailing Phone: 7188322300

Manifest Data:

Document ID:	NYB2122200
Manifest Status:	Not reported
Trans1 State ID:	98113FNY
Year:	1995
Trans2 State ID:	Not reported
Generator Ship Date:	01/09/1995
Trans1 Recv Date:	01/09/1995
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/10/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0001000157
Trans1 EPA ID:	NYD982792814
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980681571
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00120
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

U182 **CON EDISON SERVICE BOX: 49277** **RCRA NonGen / NLR** **1016964759**
NW **268 40TH ST** **NY MANIFEST** **NYP004376687**
1/8-1/4 **BROOKLYN, NY 11232**
0.188 mi.
993 ft. **Site 2 of 2 in cluster U**

Relative: RCRA Listings:
Lower

Actual: Date Form Received by Agency:	20131118
20 ft. Handler Name:	Con Edison Service Box: 49277
Handler Address:	40TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004376687

CON EDISON SERVICE BOX: 49277 (Continued) **1016964759**

Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

CON EDISON SERVICE BOX: 49277 (Continued) **1016964759**

Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20131018
Handler Name: CON EDISON SERVICE BOX: 49277
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131118
Handler Name: CON EDISON SERVICE BOX: 49277
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004376687
Country: USA
Name: CON EDISON
Address: 268 40TH ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: F/O 268 40TH ST
Location Address 2: SB49277
Location City,State,Zip: BROOKLYN, NY 11232

CON EDISON SERVICE BOX: 49277 (Continued) **1016964759**

Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 10/18/2013
Trans1 Recv Date: 10/18/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/21/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004376687
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002236753GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 250

CON EDISON SERVICE BOX: 49277 (Continued) **1016964759**

Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Z183 **540-40 STREET** **NY UST** **U003127811**
SE **540 40TH STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.190 mi.
1004 ft. **Site 3 of 9 in cluster Z**

Relative:
Higher

Actual:
114 ft.

UST:

Name:	540-40 STREET
Address:	540 40TH STREET
City,State,Zip:	BROOKLYN, NY 11232
Id/Status:	2-253006 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584246.07662
UTM Y:	4500383.76481
Site Type:	School

Affiliation Records:

Site Id:	10222
Affiliation Type:	Facility Owner
Company Name:	YMS REALTY CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1312-44 STREET PMB 111
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(917) 622-3820
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-08-25

Site Id:	10222
Affiliation Type:	Mail Contact
Company Name:	YMS REALTY CORP
Contact Type:	Not reported
Contact Name:	DANIEL SCHWIMMER
Address1:	1312 44TH STREET
Address2:	PMB 111
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(917) 622-3820
EMail:	YMS540@GMAIL.COM
Fax Number:	Not reported

540-40 STREET (Continued) **U003127811**

Modified By:	NRLOMBAR
Date Last Modified:	2011-08-25

Site Id:	10222
Affiliation Type:	Facility Operator
Company Name:	540-40 STREET
Contact Type:	Not reported
Contact Name:	DANIEL SCHWIMMER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 622-3820
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-08-25

Site Id:	10222
Affiliation Type:	Emergency Contact
Company Name:	YMS REALTY CORP
Contact Type:	Not reported
Contact Name:	DANIEL SCHWIMMER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 951-2248
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-08-25

Tank Info:

Tank Number:	001
Tank ID:	14188
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	05/03/1990
Date Tank Closed:	08/18/2011
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	21
Date Test:	10/21/2009
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI

540-40 STREET (Continued) **U003127811**

Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
D10 - Pipe Type - Copper
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle

Z184 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S104619963**
SE **540 40TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.190 mi.
1004 ft. **Site 4 of 9 in cluster Z**

Relative: LTANKS:
Higher

Actual: Name: APARTMENT BUILDING
114 ft. Address: 540 40TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1104703 / 2011-08-17
Facility ID: 1104703
Site ID: 452314
Spill Date: 2011-07-25
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: Not reported
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: HRPATEL
Referred To: Not reported
Reported to Dept: 2011-07-25
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2011-07-25
Spill Record Last Update: 2011-08-19
Spiller Name: CALLER
Spiller Company: UNKNOWN
Spiller Address: 540 40TH STREET
Spiller County: 999
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 406904
DEC Memo: 07/25/11-Hiralkumar Patel. 5:05 PM:- spoke with Chris. he mentioned that they tested tank system around 3 PM and found wet leak. he spoke with property owner and informed him about product removal from the

CLOSED-LACKOF RECENT INFO (Continued) **S104619963**

tank. as owner is working to get gas line, he refused to pump out tank. site has 2,000 gal UST in courtyard, on right side of the building. Chris mentioned that tank had about 600 gal in it during testing. 5:11 PM:- spoke with Mr. Schwimmer, property owner. informed him that the tank must be pumped out tonight. he will talk to ABC tank. 6:42 PM:- received call from Chris. he mentioned that tank has been pumped out. they will install temp tank tomorrow. 07/26/11-Hiralkumar Patel. 11:38 AM:- spoke with Chris. asked him about current status. he mentioned that fill port was plugged with red cloth. he mentioned that tank is located in courtyard on right side of the building and tank top is about 5-6 ft below courtyard surface. courtyard is about 12 ft wide. he will send proposal for tank cleanout and investigation. he mentioned that owner refused to install temp tank as he applied for emergency permit to install natural gas line. 1:30 PM:- spoke with Mr. Schwimmer. informed him that the department requires soil (and groundwater, if applicable) investigation around the tank system. asked him about status of temp tank. he mentioned that he got all permits and will have gas supply availabe tomorrow morning. suggest him to have temporary tank installed to provide hot water to buiding residents. he mentioned that he has informed his tenants about new gas line installation tomorrow morning and he doesn't want to spend money for temporary tank. asked him to seal the fill port to prevent misdelivery. informed him that the tank must not be abandoned until approved by the department. YMS Realty Corp. c/o Daniel Schwimmer 1312 44th Street, Suite 111 Brooklyn, NY 11219 Ph. (718) 951-2248 (O) (917) 622-3820 (C) email: yms2047@aol.com alternate addresses: none PBS #: 2-253006. as per PBS record, the site has 2,000 gal #2 oil UST. the PBS registration expired on 08/06/2007. other spill #: 9813577. spill was reported on 02/05/1999 due to tank test failure. case was closed in Mar. 2003 due to nature/extent of spill report. 3:50 PM:- sent CSL to Mr. Schwimmer requiring PBS renewal (form submitted by 08/10/11) and soil delineation around the tank system (report due on 08/31/11). letter emailed to Mr. Schwimmer and Donna (ABC Tank). 08/04/11-Hiralkumar Patel. 3:41 PM:- received call from Chris. they were hired for tank cleaning/inspection and investigation. ABC tank will clean the tank and will do visual inspection to find out leak area. he also mentioned that owner has decided to abandone the tank. as tank will be abandoned, asked him to drill through tank bottom and sidewalls to collect soil samples at least three feet beyond the tank surface. informed him that tank must not be abandoned until the department reviews the soil samples results. asked Chris to call to schedule a site inspection, once they expose the tank. 08/09/11-Hiralkumar Patel. 11:03 AM:- received call from Chris. they cleaned the tank. he requested a site visit. scheduled a site visit at 3:30 PM on 08/11/11. 08/11/11-Hiralkumar Patel. 3:35 PM:- visited site. met ABC crew at the site. inspected tank area. tank is located in 12 ft wide courtyard between the subject site and adjacent building at 536 40th street. fill port is located in 4 ft wide alleway and it is located behind the locked gate. found stockpile of contaminated soil in courtyard. this soil was removed from top of tank. found water in tank (half full). no sheen or oil droplets found on water. tank top is about 2 ft below grade. found old abandoned fill port on sidewalk. 3:51 PM:- spoke with Chris. he mentioned that tank is 12 ft long and 64 inch in diameter. based on observation during the site visit, asked him for following: - removal of stockpiled soil in courtyard - further excavation of soil from tank

CLOSED-LACKOF RECENT INFO (Continued) **S104619963**

top until expose the tank sides (as suspecting more contamination on tank top) - total of six soil samples via borings through tank: two borings through each side of tank and two borings through tank bottom - collection (and analysis) of soil samples at least two ft beyond tank wall and two ft below tank bottom 08/17/11-Hiralkumar Patel. 12:56 PM:- received call from Chris. they finished removing soil from tank top. he mentioned that entire tank is full of rain water and no oil sheen or droplets observed on water. he suspect that wet leak noticed during tank test could be water bubbles from pipe joints on tank top. he requested a site visit. scheduled a site visit at 3:30 PM today. 3:35 PM:- visited site. met Chris and Mr. Schwimmer. inspected tank area. entire tank and 6 inches above tank was filled with water. no sheen or product observed on water. tank was holding water. Chris mentioned that no holes were found during tank cleaning. based on available information and observations during site visits, case closed. **refer to spill # 9813577 also.**

Remarks: CATCHING BUBBLES DURING TEST WHICH INDICATED A WET LEAK

All Materials:

Site ID:	452314
Operable Unit ID:	1202492
Operable Unit:	01
Material ID:	2199078
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	CLOSED-LACKOF RECENT INFO
Address:	540 40TH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9813577 / 2003-03-10
Facility ID:	9813577
Site ID:	280559
Spill Date:	1999-02-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1999-02-05
CID:	382
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-02-05

CLOSED-LACKOF RECENT INFO (Continued) **S104619963**

Spill Record Last Update:	2011-07-26
Spiller Name:	DAVID NOCERA
Spiller Company:	Not reported
Spiller Address:	540 40TH ST
Spiller County:	001
Spiller Contact:	DAVID NOCERA
Spiller Phone:	(718) 435-4849
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	227805
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was ADMIN.CLOSED 03/10/2003 - Closed Due To The Nature / Extent Of The Spill Report. 07/26/11-Hiralkumar Patel. the case was closed in 2003 due to lack of information. a new tank test failure reported at the site (spill # 1104703). the subject spill will stay closed but will be investigated under the new spill #: 1104703. refer to spill #: 1104703.
Remarks:	GROSS FAILURE. EXCAVATE ISOLATE AND RETEST. CLOSED DUE TO LACK OF ANY RECENT INFO-DOES NOT MEET ANY CLEANUP REQUIREMENTS.

All TTF:

Facility ID:	9813577
Spill Number:	9813577
Spill Tank Test:	1546823
Site ID:	280559
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	280559
Operable Unit ID:	1074018
Operable Unit:	01
Material ID:	310291
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Z185 **540-40 STREET** **UST FINDER** **1028567159**
SE **540 40TH STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.190 mi.
1004 ft. **Site 5 of 9 in cluster Z**

Relative:
Higher

Actual:
114 ft.

UST FINDER:

Object ID:	294889
Facility ID:	NY10222
Name:	540-40 STREET
Address:	540 40TH STREET
City,State,Zip:	BROOKLYN, NY 11232
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	11363
Private Wells 1500ft:	5
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-74.0033749999999
Y Coord:	40.649996
Latitude:	40.649996
Longitude:	-74.003375

UST FINDER:

Object ID:	1199272
Facility ID:	NY10222
Tank ID:	NY12517
Tank Status:	Closed
Installation Date:	1990/05/03 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	2000
Substances:	Not reported
Tank Wall Type:	Not reported

AA186 **CON EDISON - MANHOLE 4040** **RCRA-LQG** **1014396758**
WNW **OPP 4202 3RD AVE & 43RD STREET** **NY MANIFEST** **NYP004190732**
1/8-1/4 **BROOKLYN, NY 11232** **NJ MANIFEST**
0.190 mi.
1004 ft. **Site 1 of 8 in cluster AA**

Relative:
Lower

Actual:
26 ft.

RCRA Listings:

Date Form Received by Agency:	20100323
Handler Name:	Con Edison - Manhole 4040
Handler Address:	OPP 4202 3RD AVE & 43RD STREET
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004190732
Contact Name:	FRANKLYN MURRAY
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2009
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON - MANHOLE 4040 (Continued) **1014396758**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20090813
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20090813
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20100323
Handler Name:	CON EDISON - MANHOLE 4040
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported

CON EDISON - MANHOLE 4040 (Continued) **1014396758**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20090813
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004190732
Country:	USA
Name:	CONSOLIDATED EDISON MH4040
Address:	4202 3RD AVE & 43RD ST OPP
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	OPP 4202 3RD AVE & 43RD STREET
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CONSOLIDATED EDISON MH4040
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported

CON EDISON - MANHOLE 4040 (Continued) **1014396758**

Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	08/18/2009
Trans1 Recv Date:	08/18/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/28/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004190732
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000894663GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	450
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

NJ MANIFEST:

EPA ID:	NYP004190732
Name:	CON EDISON - MANHOLE 4040
Address:	4202 3RD AVE & 43RD ST OPP

CON EDISON - MANHOLE 4040 (Continued) **1014396758**

City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	CAROLINE ISKANDER
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004190732
Manifest Number:	000894663GBF
Date Shipped:	08/18/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/18/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/21/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N

CON EDISON - MANHOLE 4040 (Continued) **1014396758**

Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H141
Quantity: 450
Unit: G

W187 **CON EDISON SERVICE BOX: 62383** **RCRA NonGen / NLR** **1016966253**
ENE **461 37TH ST** **NY MANIFEST** **NYP004391066**
1/8-1/4 **BROOKLYN, NY 11232**
0.191 mi.
1009 ft. **Site 2 of 8 in cluster W**

Relative:
Higher

Actual:
58 ft.

RCRA Listings:

Date Form Received by Agency:	20131214
Handler Name:	Con Edison Service Box: 62383
Handler Address:	37TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004391066
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

CON EDISON SERVICE BOX: 62383 (Continued) **1016966253**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131114
Handler Name: CON EDISON SERVICE BOX:	62383
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131214
Handler Name: CON EDISON SERVICE BOX:	62383
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 62383 (Continued) **1016966253**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004391066
Country:	USA
Name:	CON EDISON
Address:	461 37TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	461 37TH ST
Location Address 2:	STRUCTURE 62383
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/14/2013
Trans1 Recv Date:	11/14/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/18/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004391066
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002298783GBF
Import Indicator:	N

CON EDISON SERVICE BOX: 62383 (Continued) **1016966253**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AB188 **CORNER VIEW ASSOCIATION** **NY AST** **U003384811**
SW **4407 4TH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.192 mi.
1015 ft. **Site 1 of 14 in cluster AB**

Relative:
Higher

Actual:
80 ft.

AST:

Name:	CORNER VIEW ASSOCIATION
Address:	4407 4TH AVE
City,State,Zip:	BROOKLYN, NY 11220
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-095230
Program Type:	PBS
UTM X:	583771.12963
UTM Y:	4500318.77849
Expiration Date:	05/07/2027
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	2626
Affiliation Type:	Facility Operator
Company Name:	CORNER VIEW ASSOCIATION
Contact Type:	Not reported
Contact Name:	EDIE BELLOCCHIO
Address1:	Not reported
Address2:	Not reported

CORNER VIEW ASSOCIATION (Continued) **U003384811**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 781-8427
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2012-11-30

Site Id:	2626
Affiliation Type:	Facility Owner
Company Name:	CORNER VIEW ASSOCIATION INC
Contact Type:	MANAGER
Contact Name:	JOHN KEATING
Address1:	4401-4407 4TH AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 781-8427
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-19

Site Id:	2626
Affiliation Type:	Emergency Contact
Company Name:	CORNER VIEW ASSOCIATION INC
Contact Type:	Not reported
Contact Name:	JOHN KEATING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 781-8427
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-19

Site Id:	2626
Affiliation Type:	Mail Contact
Company Name:	CORNER VIEW ASSOCIATION INC
Contact Type:	Not reported
Contact Name:	JOHN KEATING
Address1:	4401-4407 4TH AVE
Address2:	B2
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(617) 810-9520
EMail:	CVABOARD@GMAIL.COM

CORNER VIEW ASSOCIATION (Continued) **U003384811**

Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-19

Tank Info:

Tank Number:	001
Tank Id:	4510
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/12/1953
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	08/19/2022
Material Name:	#2 fuel oil (on-site consumption)

T189 **CON EDISON - MANHOLE 4091** **NY MANIFEST** **S120958935**
NE **941 4TH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.194 mi.
1026 ft. **Site 6 of 7 in cluster T**

Relative: **Lower**
Actual: **34 ft.**

NY MANIFEST:

EPA ID:	NYP004977114
Country:	USA
Name:	CON EDISON - MANHOLE 4091
Address:	941 4TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11230
Zip 4:	Not reported
Location Address 1:	941 4TH AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11230
Location Zip 4:	Not reported

CON EDISON - MANHOLE 4091 (Continued) **S120958935**

Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON - MANHOLE 4091
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL NE
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

EPA ID: NYP005032164
Country: USA
Name: CON EDISON - MANHOLE 4091
Address: 941 4TH AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: 941 4TH AVE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON - MANHOLE 4091
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

T190 **CON EDISON - MANHOLE 4091** **RCRA-LQG** **1024890753**
NE **941 4TH AVE** **NYP005032164**
1/8-1/4 **BROOKLYN, NY 11232**
0.194 mi.
1026 ft. **Site 7 of 7 in cluster T**

Relative:
Lower

Actual:
34 ft.

RCRA Listings:
Date Form Received by Agency: 20180410
Handler Name: Con Edison - Manhole 4091
Handler Address: 4TH AVE
Handler City,State,Zip: BROOKLYN, NY 11232
EPA ID: NYP005032164
Contact Name: ALYSSA SOTTO
Contact Address: IRVING PLACE, 15TH FL NE
Contact City,State,Zip: NEW YORK, NY 10003
Contact Telephone: 212-460-2757
Contact Fax: Not reported
Contact Email: SOTTOA@CONED.COM

CON EDISON - MANHOLE 4091 (Continued) **1024890753**

Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

CON EDISON - MANHOLE 4091 (Continued) **1024890753**

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170212
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170212
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - MANHOLE 4091
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

CON EDISON - MANHOLE 4091 (Continued) **1024890753**

Evaluation Action Summary:
Evaluations: No Evaluations Found

AC191 **CON EDISON - MANHOLE 71512** **NY MANIFEST** **S120959112**
ENE **37TH ST & 5TH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.195 mi.
1029 ft. **Site 1 of 15 in cluster AC**

Relative:
Higher

Actual:
65 ft.

NY MANIFEST:

EPA ID:	NYP004993034
Country:	USA
Name:	CON EDISON - MANHOLE 71512
Address:	37TH ST & 5TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	37TH ST & 5TH AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON - MANHOLE 71512
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AC192 **CON EDISON** **NY MANIFEST** **S117064480**
ENE **37TH ST & 5TH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.195 mi.
1029 ft. **Site 2 of 15 in cluster AC**

Relative:
Higher

Actual:
65 ft.

NY MANIFEST:

EPA ID:	NYP004569703
Country:	USA
Name:	CON EDISON
Address:	37TH ST & 5TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	37 ST & 5 AVE
Location Address 2:	STRUCTURE 62383
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported

CON EDISON (Continued) **S117064480**

Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 06/19/2014
Trans1 Recv Date: 06/19/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/19/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004569703
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002502748GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 50
Units: Gallons (liquids only)
Number of Containers: 1

CON EDISON (Continued) **S117064480**

Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AC193 **CON EDISON - MANHOLE 3980** **RCRA-LQG** **1014397463**
ENE **EAST 5TH AVE AND 37TH ST** **NY MANIFEST** **NYP004197851**
1/8-1/4 **BROOKLYN, NY 11232**
0.195 mi.
1029 ft. **Site 3 of 15 in cluster AC**

Relative: **Higher**
Actual: **65 ft.**

RCRA Listings:

Date Form Received by Agency:	20100323
Handler Name:	Con Edison - Manhole 3980
Handler Address:	EAST 5TH AVE AND 37TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004197851
Contact Name:	FRANKLYN MURRAY
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2009
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline

CON EDISON - MANHOLE 3980 (Continued) **1014397463**

202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20091009
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20091009
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CON EDISON - MANHOLE 3980 (Continued) **1014397463**

Historic Generators:
Receive Date: 20100323
Handler Name: CON EDISON - MANHOLE 3980
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20091009
Handler Name: CON EDISON
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004197851
Country: USA
Name: CONSOLIDATED EDISON
Address: E 5TH AVE & 37TH ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: EAST 5TH AVE AND 37TH ST
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:

CON EDISON - MANHOLE 3980 (Continued) **1014397463**

Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/09/2009
Trans1 Recv Date:	10/09/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/09/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004197851
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000893918GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1200
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AC194 **CON EDISON SERVICE BOX: 62383** **RCRA NonGen / NLR** **1017779007**
ENE **37TH ST & 5TH AVE** **NYP004569703**
1/8-1/4 **BROOKLYN, NY 11232**
0.195 mi.
1029 ft. **Site 4 of 15 in cluster AC**

Relative: **Higher**
Actual: **65 ft.**

RCRA Listings:

Date Form Received by Agency:	20140719
Handler Name:	Con Edison Service Box: 62383
Handler Address:	37TH ST & 5TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004569703
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 62383 (Continued) **1017779007**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140619
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140619
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140719
Handler Name: CON EDISON SERVICE BOX:	62383
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 62383 (Continued) **1017779007**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

X195 **321 REALTY LLC** **NY AST** **U003394655**
WSW **321 44TH STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.196 mi.
1037 ft. **Site 3 of 5 in cluster X**

Relative:
Lower

Actual:
42 ft.

AST:

Name:	321 REALTY LLC
Address:	321 44TH STREET
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-467006
Program Type:	PBS
UTM X:	583653.03068
UTM Y:	4500469.36698
Expiration Date:	02/15/2024
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	20293
Affiliation Type:	Facility Owner
Company Name:	321 REALTY LLC
Contact Type:	MEMBER
Contact Name:	WOLF SICHERMAN
Address1:	1451 52ND STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11219
Country Code:	001
Phone:	(718) 851-4441
EMail:	sichermanmgmt@aol.com
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-11-28

Site Id:	20293
Affiliation Type:	Mail Contact
Company Name:	321 REALTY LLC
Contact Type:	Not reported
Contact Name:	WOLF SICHERMAN
Address1:	1451 52ND STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY

321 REALTY LLC (Continued) **U003394655**

Zip Code:	11219
Country Code:	001
Phone:	(718) 851-4441
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-12-16

Site Id:	20293
Affiliation Type:	Facility Operator
Company Name:	321 REALTY LLC
Contact Type:	Not reported
Contact Name:	CARLOS ALEMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 307-1529
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-11-28

Site Id:	20293
Affiliation Type:	Emergency Contact
Company Name:	321 REALTY LLC
Contact Type:	Not reported
Contact Name:	WOLF SICHERMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 851-4441
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	36970
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

321 REALTY LLC (Continued) **U003394655**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1980
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

X196 **EAST END WOOD STRIPPERS INC** **RCRA-SQG** **1010329115**
West **4218 3RD AVE** **NY MANIFEST** **NYR000147389**
1/8-1/4 **BROOKLYN, NY 11232** **NJ MANIFEST**
0.199 mi.
1049 ft. **Site 4 of 5 in cluster X**

Relative: **Lower**
Actual: **28 ft.**

RCRA Listings:

Date Form Received by Agency:	20070521
Handler Name:	East End Wood Strippers Inc
Handler Address:	3RD AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYR000147389
Contact Name:	DEAN CAMENARES
Contact Address:	GLENMERE WAY
Contact City,State,Zip:	HOLBROOK, NY 11741
Contact Telephone:	718-788-1375
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	GLENMERE WAY
Mailing City,State,Zip:	HOLBROOK, NY 11741
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: DEAN CAMENARES	
Legal Status:	Private
Date Became Current:	20070131
Date Ended Current:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: 4218 THIRD AVE LLC
Legal Status: Private
Date Became Current: 20070131
Date Ended Current: Not reported
Owner/Operator Address: 4214 THIRD AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11232
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20070521
Handler Name: EAST END WOOD STRIPPERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070522
Handler Name: EAST END WOOD STRIPPERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 54131
NAICS Description: ARCHITECTURAL SERVICES

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: LDR - General
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Manifest
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Manifest
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Records/Reporting
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Records/Reporting
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Manifest
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Manifest
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Manifest
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Records/Reporting
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Records/Reporting
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Records/Reporting
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Records/Reporting
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Records/Reporting
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Records/Reporting
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Manifest
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	LDR - General
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	LDR - General
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	LDR - General
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Records/Reporting
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Records/Reporting
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Records/Reporting
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: LDR - General
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	LDR - General
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	LDR - General
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090107
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-20090107-2
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 53997
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Manifest
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Manifest
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Tank System Standards
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Records/Reporting
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: 2-200901072
Enforcement Attorney: MN
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 3000
Paid Amount: 3000
Final Count: 1
Final Amount: 3000

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Tank System Standards
Date Violation was Determined: 20080411
Actual Return to Compliance Date: 20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-200901072
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	3000
Paid Amount:	3000
Final Count:	1
Final Amount:	3000

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	LDR - General
Date Violation was Determined:	20080411
Actual Return to Compliance Date:	20090723
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090107
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20090107-2
Enforcement Attorney:	MN
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	53997
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20090618
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NO LONGER A SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	CO
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20080411
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYHHN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20090723
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20081121
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier: NYJRI
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20090723
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20081121
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier: NYJRI
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20090723
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20080411
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYHHN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20090723
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20081121
Evaluation Responsible Agency: State

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20090723
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20080411
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYHHN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20090723
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20081121
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier: NYJRI
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20090723
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20081121
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier: NYJRI
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20090723
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20080411
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYHHN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20090723
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20081121
Evaluation Responsible Agency: State

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20081121
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090723
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NY MANIFEST:

EPA ID:	NYR000147389
Country:	USA
Name:	EAST END WOOD STRIPPERS INC
Address:	4218 3RD AVE
Address 2:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: 4218 3RD AVE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: EAST END WOOD STRIPPERS INC
Mailing Contact: EAST END WOOD STRIPPERS INC
Mailing Address 1: 4218 3RD AVE
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11232
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD064748304
Year: 2018
Trans2 State ID: NJD080631369
Generator Ship Date: 07/07/2009
Trans1 Recv Date: 07/07/2009
Trans2 Recv Date: 07/08/2009
TSD Site Recv Date: 07/10/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000147389
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD980536593
TSDF ID 2: Not reported
Manifest Tracking Number: 004718001JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code a: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

	SPENT SOLVENT MIXTURES.
Waste Code b:	IGNITABLE WASTE
Waste Code c:	LEAD
Waste Code e:	SELENIUM
Waste Code f:	Not reported
Waste Code g:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	900
Units:	Pounds
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	09/03/2008
Trans1 Recv Date:	09/03/2008
Trans2 Recv Date:	09/05/2008
TSD Site Recv Date:	09/05/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000147389
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004072002JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2,

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code b:	IGNITABLE WASTE
Waste Code c:	LEAD
Waste Code e:	ARSENIC
Waste Code f:	Not reported
Waste Code g:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1200
Units:	Pounds
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	06/27/2008
Trans1 Recv Date:	06/27/2008
Trans2 Recv Date:	07/03/2008
TSD Site Recv Date:	07/03/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000147389
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004072348JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Waste Code a:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code b:	IGNITABLE WASTE
Waste Code c:	LEAD
Waste Code e:	SELENIUM
Waste Code f:	METHYL ETHYL KETONE
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	900
Units:	Pounds
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	03/07/2008
Trans1 Recv Date:	03/07/2008
Trans2 Recv Date:	03/14/2008
TSD Site Recv Date:	03/14/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000147389
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	001417972JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE,

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

	CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code b:	IGNITABLE WASTE
Waste Code c:	LEAD
Waste Code e:	METHYL ETHYL KETONE
Waste Code f:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1200
Units:	Pounds
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Year:	2018
Trans2 State ID:	NJD002454544
Generator Ship Date:	08/21/2007
Trans1 Recv Date:	08/21/2007
Trans2 Recv Date:	08/31/2007
TSD Site Recv Date:	08/31/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000147389
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	001417603JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code b:	IGNITABLE WASTE
Waste Code c:	LEAD
Waste Code e:	SELENIUM
Waste Code f:	METHYL ETHYL KETONE
Waste Code g:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1000
Units:	Pounds
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	07/21/2009
Trans1 Recv Date:	07/21/2009
Trans2 Recv Date:	07/28/2009
TSD Site Recv Date:	07/29/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000147389
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004718914JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code b:	IGNITABLE WASTE
Waste Code c:	LEAD
Waste Code e:	SELENIUM
Waste Code f:	METHYL ETHYL KETONE
Waste Code g:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1200
Units:	Pounds
Number of Containers:	3
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	07/21/2009
Trans1 Recv Date:	07/21/2009
Trans2 Recv Date:	07/28/2009
TSD Site Recv Date:	07/29/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000147389
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004718914JJK
Import Indicator:	N

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code b:	IGNITABLE WASTE
Waste Code c:	LEAD
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	5
Units:	Pounds
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	04/29/2008
Trans1 Recv Date:	04/29/2008
Trans2 Recv Date:	05/02/2008
TSD Site Recv Date:	05/02/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000147389
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004072384JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code b:	IGNITABLE WASTE
Waste Code c:	LEAD
Waste Code e:	SELENIUM
Waste Code f:	METHYL ETHYL KETONE
Waste Code g:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	900
Units:	Pounds
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	04/06/2009
Trans1 Recv Date:	04/06/2009
Trans2 Recv Date:	04/06/2009
TSD Site Recv Date:	04/09/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000147389
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Manifest Tracking Number:	004718731JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code b:	IGNITABLE WASTE
Waste Code c:	LEAD
Waste Code e:	SELENIUM
Waste Code f:	METHYL ETHYL KETONE
Waste Code g:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1900
Units:	Pounds
Number of Containers:	4
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	03/31/2009
Trans1 Recv Date:	03/31/2009
Trans2 Recv Date:	03/31/2009
TSD Site Recv Date:	04/02/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000147389

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	004718705JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	METHYL ETHYL KETONE
Waste Code b:	LEAD
Waste Code c:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD064748304
Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	03/31/2009
Trans1 Recv Date:	03/31/2009
Trans2 Recv Date:	03/31/2009
TSD Site Recv Date:	04/02/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000147389
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Manifest Tracking Number:	004718705JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code b:	IGNITABLE WASTE
Waste Code c:	LEAD
Waste Code e:	SELENIUM
Waste Code f:	Not reported
Waste Code g:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Click this hyperlink while viewing on your computer to access
5 additional NY MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

EPA ID:	NYR000147389
Name:	EAST END WOOD STRIPPERS INC
Address:	4218 3RD AVE
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	GLENMERE WAY
Mailing City,State,Zip:	HOLBROOK, NY 11741

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	DEAN CAMENARES
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYR000147389
Manifest Number:	001717972JJK
Date Shipped:	03/07/2008
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/07/2008
Date Trans2 Transported Waste:	03/14/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/14/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Waste Code:	F002
Hand Code:	H141
Quantity:	1200
Unit:	P
EPA ID:	NYR000147389
Manifest Number:	004718998JJK
Date Shipped:	08/31/2009
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/31/2009
Date Trans2 Transported Waste:	09/04/2009
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/04/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	750
Unit:	P
EPA ID:	NYR000147389
Manifest Number:	004718914JJK
Date Shipped:	07/21/2009

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/21/2009
Date Trans2 Transported Waste:	07/28/2009
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/29/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	5
Unit:	P

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	1200
Unit:	P

EPA ID:	NYR000147389
Manifest Number:	004072002JJK
Date Shipped:	09/03/2008
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/03/2008
Date Trans2 Transported Waste:	09/05/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/05/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	1200
Unit:	P

EPA ID:	NYR000147389
Manifest Number:	004072384JJK
Date Shipped:	04/29/2008
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/29/2008

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Date Trans2 Transported Waste:	05/02/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/02/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	900
Unit:	P

EPA ID:	NYR000147389
Manifest Number:	004072348JJK
Date Shipped:	06/27/2008
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/27/2008
Date Trans2 Transported Waste:	07/03/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Date TSDF Received Waste:	07/03/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	900
Unit:	P

EPA ID:	NYR000147389
Manifest Number:	004718040JJK
Date Shipped:	09/23/2009
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/23/2009
Date Trans2 Transported Waste:	09/24/2009
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/25/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	1350
Unit:	P

EPA ID:	NYR000147389
Manifest Number:	001418731JJK
Date Shipped:	04/06/2009
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/06/2009
Date Trans2 Transported Waste:	04/06/2009
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/09/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	1900
Unit:	P

EPA ID:	NYR000147389
Manifest Number:	004718001JJK
Date Shipped:	07/07/2009
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/07/2009
Date Trans2 Transported Waste:	07/08/2009
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/10/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	900
Unit:	P

EPA ID:	NYR000147389
Manifest Number:	004072122JJK

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Date Shipped:	11/06/2008
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/06/2008
Date Trans2 Transported Waste:	11/14/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/14/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	1200
Unit:	P

EPA ID:	NYR000147389
Manifest Number:	004718705JJK
Date Shipped:	03/31/2009
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD080631369
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

EAST END WOOD STRIPPERS INC (Continued) **1010329115**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/31/2009
Date Trans2 Transported Waste:	03/31/2009
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/02/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	100
Unit:	P

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	500
Unit:	P

Click this hyperlink while viewing on your computer to access
2 additional NJ MANIFEST: record(s) in the EDR Site Report.

AD197 **CON EDISON - CUSTOMER MANHOLE 5790** **NY MANIFEST** **S120959306**
WSW **348 44 ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.199 mi.
1051 ft. **Site 1 of 8 in cluster AD**

Relative: NY MANIFEST:
Higher

EPA ID:	NYP005012612
Country:	USA
Name:	CON EDISON - CUSTOMER MANHOLE 5790

Actual:
55 ft.

CON EDISON - CUSTOMER MANHOLE 5790 (Continued) **S120959306**

Address:	348 44 ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11220
Zip 4:	Not reported
Location Address 1:	348 44 ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11220
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON - CUSTOMER MANHOLE 5790
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AE198 **NYC DEPT OF EDUCATION - PS 231K** **NY MANIFEST** **S130582388**
NNE **360 36TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.202 mi.
1065 ft. **Site 1 of 6 in cluster AE**

Relative:
Lower

Actual:
23 ft.

NY MANIFEST:

EPA ID:	NYR000242230
Country:	USA
Name:	NYC DEPT OF EDUCATION - PS 231K
Address:	360 36TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	360 36TH ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	NYC DEPT OF EDUCATION - PS 231K
Mailing Contact:	NYC DEPT OF EDUCATION - PS 231K
Mailing Address 1:	360 36TH ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11232
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3478850108

AE199 **NYC DEPT OF EDUCATION - PS 231K** **RCRA-SQG** **1025887655**
NNE **360 36TH ST** **NYR000242230**
1/8-1/4 **BROOKLYN, NY 11232**
0.202 mi.
1065 ft. **Site 2 of 6 in cluster AE**

Relative: **Lower**

Actual: **23 ft.**

RCRA Listings:

Date Form Received by Agency:	20190729
Handler Name:	Nyc Dept Of Education - Ps 231k
Handler Address:	36TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYR000242230
Contact Name:	TRENTON BROWN
Contact Address:	THOMSON AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-752-5496
Contact Fax:	718-472-8500
Contact Email:	TBROWN2@NYCSA.ORG
Contact Title:	MANAGER, OPERATIONS
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	THOMSON AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Nyc Dept Of Education
Owner Type:	Municipal
Operator Name:	Nyc Dept Of School Facilities
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

NYC DEPT OF EDUCATION - PS 231K (Continued) **1025887655**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190806
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYC DEPT OF SCHOOL FACILITIES
Legal Status:	Municipal
Date Became Current:	19660224
Date Ended Current:	Not reported
Owner/Operator Address:	30-30 THOMSON AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-752-5296
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	718-472-8500
Owner/Operator Email:	TBROWN2@NYCSA.ORG

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYC DEPT OF EDUCATION
Legal Status:	Municipal
Date Became Current:	19660224
Date Ended Current:	Not reported
Owner/Operator Address:	30-30 THOMSON AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-752-5296
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	718-472-8500
Owner/Operator Email:	TBROWN2@NYCSA.ORG

Historic Generators:

Receive Date:	20190729
Handler Name:	NYC DEPT OF EDUCATION - PS 231K
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

NYC DEPT OF EDUCATION - PS 231K (Continued) **1025887655**

Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 611110
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AF200 **CON EDISON** **NY MANIFEST** **S117314647**
North **319 37 ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.202 mi.
1066 ft. **Site 1 of 2 in cluster AF**

Relative: **Lower**
Actual: **18 ft.**

NY MANIFEST:
EPA ID: NYP004617189
Country: USA
Name: CON EDISON
Address: 319 37 ST
Address 2: SB 49116
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: 319 37 ST
Location Address 2: SB 49116
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 08/04/2014
Trans1 Recv Date: 08/04/2014
Trans2 Recv Date: Not reported

CON EDISON (Continued) **S117314647**

TSD Site Recv Date:	08/05/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004617189
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002615676GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Y201 **CON EDISON** **NY Spills** **S103575702**
ESE **541 39TH ST** **NY MANIFEST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.204 mi.
1076 ft. **Site 8 of 9 in cluster Y**

Relative:
Higher

Actual:
100 ft.

SPILLS:

Name:	MANHOLE 56710
Address:	541 39TH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9811868 / 2003-02-20
Facility ID:	9811868
Facility Type:	ER
DER Facility ID:	96739
Site ID:	110368
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4

CON EDISON (Continued) **S103575702**

SWIS:	2401
Spill Date:	1998-12-21
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1998-12-21
CID:	371
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-12-21
Spill Record Last Update:	2003-02-24
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	contained - sample taken - spill 122073. clean up pending lab results.
Remarks:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 122073 MR MISISCHIA#56932 SPLICER I&A REPORTS FOUND APPROXIMATELY 1 GALLON OIL ON 623 GALLONS OF WATER IN MH56710 F/O 541 39 ST. NO SEWERS OR WATERWAYS AFFECTED. SAMPLE TAKEN -- MR MISISCHIA WILL CALL BACK WITH E.S.TAG#. FOUND OIL WHILE PERFORMING A SERVICE REPLACEMENT. D.HERBST 27461 F.MISISCHIA REPORTS INSTALLED E.S.TAG#07876 AT 1130HRS. D.HERBST UPDATE: 12/22/98-LAB SEQ#98-14199-LAB RESULTS <1.00PPM UPDATE: 12/23/98 - 1245 D. LICHTENSTEIN - 08078 - ENV. OPS., REPORTS <1.0 PPM CLEANUP COMPLETE WITH SLIX AND TAG #07876 REMOVED. INCIDENT IS CLOSED.

All Materials:

Site ID:	110368
Operable Unit ID:	1069131
Operable Unit:	01
Material ID:	312150
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

NY MANIFEST:

EPA ID:	NYP004391280
Country:	USA
Name:	CON EDISON
Address:	541 39TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232

CON EDISON (Continued) **S103575702**

Zip 4:	Not reported
Location Address 1:	541 39TH ST
Location Address 2:	SB56710
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/14/2013
Trans1 Recv Date:	11/14/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/14/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004391280
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002298874GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported

CON EDISON (Continued) **S103575702**

Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	400
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Y202 **CON EDISON - MANHOLE 56710** **RCRA-LQG** **1016966275**
ESE **541 39 ST** **NYP004391280**
1/8-1/4 **BROOKLYN, NY 11232**
0.204 mi.
1076 ft. **Site 9 of 9 in cluster Y**

Relative: **Higher**
Actual: **100 ft.**

RCRA Listings:

Date Form Received by Agency:	20140327
Handler Name:	Con Edison - Manhole 56710
Handler Address:	39 ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004391280
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	518-473-8034
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

CON EDISON - MANHOLE 56710 (Continued) **1016966275**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20131114
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20131114
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE

CON EDISON - MANHOLE 56710 (Continued) **1016966275**

Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140327
Handler Name: CON EDISON - MANHOLE 56710
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131114
Handler Name: CON EDISON MANHOLE: 56710
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131214
Handler Name: CON EDISON MANHOLE: 56710
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AG203 **DLJ ENTERPRISES, LTD** **NY AST** **A100293775**
NW **260 39TH STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.205 mi.
1080 ft. **Site 1 of 3 in cluster AG**

Relative:
Lower

Actual:
17 ft.

AST:

Name:	DLJ ENTERPRISES, LTD
Address:	260 39TH STREET
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610119
Program Type:	PBS
UTM X:	583773.72519
UTM Y:	4500859.55661
Expiration Date:	02/08/2026
Site Type:	Other

Affiliation Records:

Site Id:	359352
Affiliation Type:	Facility Owner
Company Name:	DAVID JARON
Contact Type:	OWNER
Contact Name:	DAVID JARON
Address1:	19 GLENWOOD DRIVE
Address2:	Not reported
City:	GREAT NECK
State:	NY
Zip Code:	11021
Country Code:	001
Phone:	(516) 315-9733
EMail:	RONITJARON@OPTONLINE.NET
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-01-07

Site Id:	359352
Affiliation Type:	Mail Contact
Company Name:	DLJ ENTERPRISES
Contact Type:	Not reported
Contact Name:	DAVID JARON
Address1:	260 39TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(718) 499-6793
EMail:	RONITJARON@OPTONLINE.NET
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2013-01-04

Site Id:	359352
Affiliation Type:	Facility Operator
Company Name:	DLJ ENTERPRISES LTD
Contact Type:	Not reported
Contact Name:	DAVID JARON

DLJ ENTERPRISES, LTD (Continued) **A100293775**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 499-6793
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-01-07

Site Id:	359352
Affiliation Type:	Emergency Contact
Company Name:	DAVID JARON
Contact Type:	Not reported
Contact Name:	RONIT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 315-9733
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-02-08

Tank Info:

Tank Number:	001
Tank Id:	209976
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J03 - Dispenser - Gravity
E07 - Piping Secondary Containment - Trench Liner
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel Tank in Concrete
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1989
Capacity Gallons:	250

DLJ ENTERPRISES, LTD (Continued) **A100293775**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

V204 **COSTCO WHOLESALE #0318** **RCRA-VSQG 1001124762**
NNW **976 3RD AVE** **NY MANIFEST NYR000030353**
1/8-1/4 **BROOKLYN, NY 11232**
0.206 mi.
1089 ft. **Site 2 of 3 in cluster V**

Relative: **Lower**

Actual: **16 ft.**

RCRA Listings:

Date Form Received by Agency:	20230612
Handler Name:	Costco Wholesale #0318
Handler Address:	3RD AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYR000030353
Contact Name:	GAVIN PENDLETON
Contact Address:	LAKE DR
Contact City,State,Zip:	ISSAQUAH, WA 98027
Contact Telephone:	425-427-7862
Contact Fax:	Not reported
Contact Email:	ENVIRONMENTALCOMPLIANCE@COSTCO.COM
Contact Title:	MANAGER GLOBAL ENV COMPLIANCE
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	GREY HAWK CT STE 200
Mailing City,State,Zip:	CARLSBAD, CA 92010
Owner Name:	Costco Wholesale Corp
Owner Type:	Private
Operator Name:	Costco Wholesale Corp
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230613
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2019

Click Here for Biennial Reporting System Data:
Year: 2017

Click Here for Biennial Reporting System Data:
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D006
Waste Description:	Cadmium

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D016
Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D018
Waste Description: Benzene

Waste Code: D024
Waste Description: M-Cresol

Waste Code: D026
Waste Description: Cresol

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: P001
Waste Description: 2h-1-Benzopyran-2-One, 4-Hydroxy-3-(3-Oxo-1-Phenylbutyl)-, & Salts, When Present At Concentrations Greater Than 0.3% (Or) Warfarin, & Salts, When Present At Concentrations Greater Than 0.3%

Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Waste Code: U034
Waste Description: Acetaldehyde, Trichloro- (Or) Chloral

Waste Code: U057
Waste Description: Cyclohexanone (I)

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Waste Code: U279
Waste Description: U279

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: COSTCO WHOLESALE CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 999 LAKE DR
Owner/Operator City,State,Zip: ISSAQUAH, WA 98027-5366
Owner/Operator Telephone: 206-313-8100
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COSTCO WHOLESALE CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 999 LAKE DR
Owner/Operator City,State,Zip: ISSAQUAH, WA 98027-5366
Owner/Operator Telephone: 206-313-8100
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COSTCO WHOLESALE CORP
Legal Status: Private
Date Became Current: 19961121
Date Ended Current: Not reported
Owner/Operator Address: 999 LAKE DR
Owner/Operator City,State,Zip: ISSAQUAH, WA 98027
Owner/Operator Telephone: 425-313-6674
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: RTHOMPSON@COSTCO.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: COSTCO WHOLESALE CORPORATION
Legal Status: Private
Date Became Current: 19961121
Date Ended Current: Not reported
Owner/Operator Address: 999 LAKE DR
Owner/Operator City,State,Zip: ISSAQUAH, WA 98027
Owner/Operator Telephone: 425-313-8100
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COSTCO WHOLESALE CORP
Legal Status: Private
Date Became Current: 19961121
Date Ended Current: Not reported

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Owner/Operator Address: 999 LAKE DR
Owner/Operator City,State,Zip: ISSAQUAH, WA 98027
Owner/Operator Telephone: 425-313-8100
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COSTCO WHOLESALE CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 999 LAKE DR
Owner/Operator City,State,Zip: ISSAQUAH, WA 98027-5366
Owner/Operator Telephone: 206-313-8100
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: KARIM ZEFFOUNI
Legal Status: Private
Date Became Current: 20090701
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COSTCO WHOLESALE CORPORATION
Legal Status: Private
Date Became Current: 19961121
Date Ended Current: Not reported
Owner/Operator Address: 999 LAKE DR
Owner/Operator City,State,Zip: ISSAQUAH, WA 98027
Owner/Operator Telephone: 425-313-8100
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COSTCO WHOLESALE CORPORATION
Legal Status: Private
Date Became Current: 19961121
Date Ended Current: Not reported
Owner/Operator Address: 999 LAKE DR
Owner/Operator City,State,Zip: ISSAQUAH, WA 98027
Owner/Operator Telephone: 425-313-8100
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COSTCO WHOLESALE CORP

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Legal Status:	Private
Date Became Current:	19961121
Date Ended Current:	Not reported
Owner/Operator Address:	999 LAKE DR
Owner/Operator City,State,Zip:	ISSAQUAH, WA 98027
Owner/Operator Telephone:	425-313-8110
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	RTHOMPSON@COSTCO.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COSTCO WHOLESALE CORP
Legal Status:	Private
Date Became Current:	19961121
Date Ended Current:	Not reported
Owner/Operator Address:	999 LAKE DR
Owner/Operator City,State,Zip:	ISSAQUAH, WA 98027
Owner/Operator Telephone:	425-313-8100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COSTCO WHOLESALE CORP
Legal Status:	Private
Date Became Current:	19961121
Date Ended Current:	Not reported
Owner/Operator Address:	999 LAKE DR
Owner/Operator City,State,Zip:	ISSAQUAH, WA 98027
Owner/Operator Telephone:	425-313-8100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COSTCO WHOLESALE CORPORATION
Legal Status:	Private
Date Became Current:	19961121
Date Ended Current:	Not reported
Owner/Operator Address:	999 LAKE DR
Owner/Operator City,State,Zip:	ISSAQUAH, WA 98027
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COSTCO WHOLESALE CORP
Legal Status:	Private
Date Became Current:	19961121
Date Ended Current:	Not reported
Owner/Operator Address:	999 LAKE DR
Owner/Operator City,State,Zip:	ISSAQUAH, WA 98027
Owner/Operator Telephone:	425-313-8100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Owner/Operator Indicator: Owner
Owner/Operator Name: COSTCO WHOLESALE CORP
Legal Status: Private
Date Became Current: 19961121
Date Ended Current: Not reported
Owner/Operator Address: 999 LAKE DR
Owner/Operator City,State,Zip: ISSAQUAH, WA 98027
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160317
Handler Name: COSTCO WHOLESALE # 318
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180131
Handler Name: COSTCO WHOLESALE #0318
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20200226
Handler Name: COSTCO WHOLESALE #0318
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19990708
Handler Name: COSTCO WHOLESALE #318
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: COSTCO WHOLESALE #318
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: COSTCO WHOLESALE #318
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19961007
Handler Name: COSTCO WHOLESALE #318
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130917
Handler Name: COSTCO WHOLESALE #318
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20171016
Handler Name: COSTCO WHOLESALE #318
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20230612
Handler Name: COSTCO WHOLESALE #0318
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 445291
NAICS Description: BAKED GOODS RETAILERS

NAICS Code: 44611
NAICS Description: PHARMACIES AND DRUG STORES

NAICS Code: 446110
NAICS Description: PHARMACIES AND DRUG STORES

NAICS Code: 44719
NAICS Description: OTHER GASOLINE STATIONS

NAICS Code: 447190
NAICS Description: OTHER GASOLINE STATIONS

NAICS Code: 452311
NAICS Description: WAREHOUSE CLUBS AND SUPERCENTERS

NAICS Code: 45291
NAICS Description: WAREHOUSE CLUBS AND SUPERCENTERS

NAICS Code: 45521
NAICS Description: WAREHOUSE CLUBS, SUPERCENTERS, AND OTHER GENERAL MERCHANDISE RETAILERS

NAICS Code: 812922
NAICS Description: ONE-HOUR PHOTOFINISHING

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Has the Facility Received Notices of Violations:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20160531
Actual Return to Compliance Date:	20160701
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20160614
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20160728
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYSR
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20160531
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYSR
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20160701
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20210720
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYCMK
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

NY MANIFEST:
EPA ID: NYR000030353
Country: USA
Name: COSTCO WHOLESALE #318
Address: 976 3RD AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232-2400
Zip 4: Not reported

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Location Address 1: 976 3RD AVENUE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: COSTCO WHOLESALE #318
Mailing Contact: COSTCO WHOLESALE #318
Mailing Address 1: 976 3RD AVE
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11232
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: CTD983872698
Year: 2018
Trans2 State ID: NJR000063677
Generator Ship Date: 03/25/2015
Trans1 Recv Date: 03/25/2015
Trans2 Recv Date: 03/27/2015
TSD Site Recv Date: 03/31/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000030353
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: RID040098352
TSDF ID 2: Not reported
Manifest Tracking Number: 007387496FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code a: Not reported
Waste Code b: IGNITABLE WASTE
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	44
Units:	Pounds
Number of Containers:	2
Container Type:	Burlap, cloth, paper or plastic bags
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Year:	2018
Trans2 State ID:	NJR000063677
Generator Ship Date:	03/25/2015
Trans1 Recv Date:	03/25/2015
Trans2 Recv Date:	03/27/2015
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000030353
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	007387496FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1
Units:	Pounds
Number of Containers:	1
Container Type:	Burlap, cloth, paper or plastic bags
Handling Method:	Landfill
Specific Gravity:	1

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Year:	2018
Trans2 State ID:	NJR000063677
Generator Ship Date:	10/01/2012
Trans1 Recv Date:	10/01/2012
Trans2 Recv Date:	10/16/2012
TSD Site Recv Date:	10/19/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000030353
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	INR000110197
TSDF ID 2:	Not reported
Manifest Tracking Number:	005429004FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1
Units:	Pounds
Number of Containers:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	CTD983872698
Year:	2018
Trans2 State ID:	NJR000063677
Generator Ship Date:	10/01/2012
Trans1 Recv Date:	10/01/2012
Trans2 Recv Date:	10/16/2012

COSTCO WHOLESALE #0318 (Continued) **1001124762**

TSD Site Recv Date:	10/19/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000030353
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	INR000110197
TSDF ID 2:	Not reported
Manifest Tracking Number:	005429004FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	IGNITABLE WASTE
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	85
Units:	Pounds
Number of Containers:	3
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Year:	2018
Trans2 State ID:	NJD071629976
Generator Ship Date:	11/10/2017
Trans1 Recv Date:	11/10/2017
Trans2 Recv Date:	11/21/2017
TSD Site Recv Date:	11/21/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000030353
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	010841356FLE
Import Indicator:	N

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	IGNITABLE WASTE
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	39
Units:	Pounds
Number of Containers:	1
Container Type:	Burlap, cloth, paper or plastic bags
Handling Method:	Burn
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Year:	2018
Trans2 State ID:	NJD071629976
Generator Ship Date:	11/10/2017
Trans1 Recv Date:	11/10/2017
Trans2 Recv Date:	11/21/2017
TSD Site Recv Date:	11/21/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000030353
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	010841356FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Waste Code a:	Not reported
Waste Code b:	CORROSIVE WASTE
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	42
Units:	Pounds
Number of Containers:	2
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Treat
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Year:	2018
Trans2 State ID:	NJD071629976
Generator Ship Date:	11/10/2017
Trans1 Recv Date:	11/10/2017
Trans2 Recv Date:	11/21/2017
TSD Site Recv Date:	11/21/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000030353
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	010841356FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1
Units:	Pounds
Number of Containers:	1
Container Type:	Burlap, cloth, paper or plastic bags
Handling Method:	Burn
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Year:	2018
Trans2 State ID:	NJD071629976
Generator Ship Date:	05/11/2018
Trans1 Recv Date:	05/11/2018
Trans2 Recv Date:	05/25/2018
TSD Site Recv Date:	05/29/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000030353
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	011380606FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	CORROSIVE WASTE
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	56
Units:	Pounds
Number of Containers:	2
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	1

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Year:	2018
Trans2 State ID:	NJD071629976
Generator Ship Date:	05/11/2018
Trans1 Recv Date:	05/11/2018
Trans2 Recv Date:	05/25/2018
TSD Site Recv Date:	05/29/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000030353
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	011380606FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	IGNITABLE WASTE
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	56
Units:	Pounds
Number of Containers:	2
Container Type:	Burlap, cloth, paper or plastic bags
Handling Method:	Burn
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Year:	2018
Trans2 State ID:	NJD071629976
Generator Ship Date:	05/11/2018
Trans1 Recv Date:	05/11/2018
Trans2 Recv Date:	05/25/2018
TSD Site Recv Date:	05/29/2018
Part A Recv Date:	Not reported

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000030353
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	011380606FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1
Units:	Pounds
Number of Containers:	1
Container Type:	Burlap, cloth, paper or plastic bags
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Year:	2018
Trans2 State ID:	NJD071629976
Generator Ship Date:	05/11/2018
Trans1 Recv Date:	05/11/2018
Trans2 Recv Date:	05/25/2018
TSD Site Recv Date:	05/29/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000030353
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	011380606FLE
Import Indicator:	N

COSTCO WHOLESALE #0318 (Continued) **1001124762**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	IGNITABLE WASTE
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	25
Units:	Pounds
Number of Containers:	1
Container Type:	Burlap, cloth, paper or plastic bags
Handling Method:	Burn
Specific Gravity:	1

Click this hyperlink while viewing on your computer to access
163 additional NY MANIFEST: record(s) in the EDR Site Report.

V205 **COSTCO # 318** **PA MANIFEST** **S118889197**
NNW **976 THIRD AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.206 mi.
1089 ft. **Site 3 of 3 in cluster V**

Relative: PA MANIFEST:
Lower

Actual: Year:	2015
16 ft. Manifest Number:	007395250FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000030353
Generator Date:	04/22/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2

COSTCO # 318 (Continued) **S118889197**

Waste Number:	P001
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	007395250FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000030353
Generator Date:	04/22/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	4
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	75
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	007395250FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000030353
Generator Date:	04/22/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D009
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases

COSTCO # 318 (Continued) **S118889197**

Waste Quantity:	5
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

AH206 **CON EDISON SERVICE BOX: 45846** **RCRA NonGen / NLR** **1016964493**
South **4402 5TH AVE** **NY MANIFEST** **NYP004374120**
1/8-1/4 **BROOKLYN, NY 11232**
0.208 mi.
1100 ft. **Site 1 of 3 in cluster AH**

Relative: **Higher**

Actual: **111 ft.**

RCRA Listings:

Date Form Received by Agency:	20131115
Handler Name:	Con Edison Service Box: 45846
Handler Address:	5TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004374120
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline

CON EDISON SERVICE BOX: 45846 (Continued) **1016964493**

2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131015
Handler Name: CON EDISON SERVICE BOX:	45846
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131115
Handler Name: CON EDISON SERVICE BOX:	45846
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON SERVICE BOX: 45846 (Continued) **1016964493**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004374120
Country:	USA
Name:	CON EDISON
Address:	4402 5TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	F/O 4402 5TH AVE
Location Address 2:	SB454846
Location City,State,Zip:	BROOKLYN, NY 11220
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2013
Trans1 Recv Date:	10/15/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004374120
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002291249GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON SERVICE BOX: 45846 (Continued) **1016964493**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	30
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AB207 **CON EDISON SERVICE BOX: 48662** **RCRA NonGen / NLR** **1016966558**
SSW **423 45TH ST** **NY MANIFEST** **NYP004394052**
1/8-1/4 **BROOKLYN, NY 11220**
0.210 mi.
1107 ft. **Site 2 of 14 in cluster AB**

Relative: **Higher**
Actual: **88 ft.**

RCRA Listings:

Date Form Received by Agency:	20131219
Handler Name:	Con Edison Service Box: 48662
Handler Address:	45TH ST
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NYP004394052
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No

CON EDISON SERVICE BOX: 48662 (Continued) **1016966558**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131119
Handler Name: CON EDISON SERVICE BOX:	48662
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131219
Handler Name: CON EDISON SERVICE BOX:	48662

CON EDISON SERVICE BOX: 48662 (Continued) **1016966558**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004394052
Country:	USA
Name:	CON EDISON
Address:	423 45TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11220
Zip 4:	Not reported
Location Address 1:	423 45TH ST
Location Address 2:	SB48662
Location City,State,Zip:	BROOKLYN, NY 11220
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/19/2013
Trans1 Recv Date:	11/19/2013

CON EDISON SERVICE BOX: 48662 (Continued) **1016966558**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004394052
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299166GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	100
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AB208 **CON EDISON** **RCRA NonGen / NLR** **1018278378**
SSW **425 45TH ST** **FINDS** **NYP004731477**
1/8-1/4 **BROOKLYN, NY 11220** **ECHO**
0.210 mi.
1108 ft. **Site 3 of 14 in cluster AB**

Relative: **Higher**
Actual: **89 ft.**

RCRA Listings:

Date Form Received by Agency:	20150212
Handler Name:	Con Edison
Handler Address:	45TH ST
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NYP004731477
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported

CON EDISON (Continued) **1018278378**

Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON (Continued) **1018278378**

Historic Generators:
Receive Date: 20150212
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150212
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067704121

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018278378
Registry ID: 110067704121

CON EDISON (Continued) **1018278378**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067704121
Name: CON EDISON
Address: 425 45TH ST
City,State,Zip: BROOKLYN, NY 11220

AH209 **NYNEX** **NY MANIFEST** **1009233577**
South **44TH ST & 5TH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 10016**
0.210 mi.
1111 ft. **Site 2 of 3 in cluster AH**

Relative: **Higher**
Actual: **116 ft.**

NY MANIFEST:
EPA ID: NYP000917336
Country: USA
Name: NYNEX
Address: 44TH ST & 5TH AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 10016
Zip 4: Not reported
Location Address 1: 44TH ST & 5TH AVE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 10016
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: NYNEX
Mailing Contact: DAN DEGUZMAN
Mailing Address 1: 221 EAST 37TH STREET
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10016
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2123387126

Manifest Data:
Document ID: MIA3014144
Manifest Status: Not reported
Trans1 State ID: Not reported
Year: 1994
Trans2 State ID: Not reported
Generator Ship Date: 10/14/1994
Trans1 Recv Date: 10/14/1994
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/25/1994
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP000917336
Trans1 EPA ID: NJD986576031
Trans2 EPA ID: Not reported
TSDF ID 1: MID096963194
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported

NYNEX (Continued) **1009233577**

Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	03000
Units:	Pounds
Number of Containers:	008
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

AC210 **JACKIE GLEASON BUS DEPOT** **UST FINDER** **1028599262**
ENE **845 5TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.211 mi.
1114 ft. **Site 5 of 15 in cluster AC**

Relative: **Higher**
Actual: **62 ft.**

UST FINDER:

Object ID:	294957
Facility ID:	NY5859
Name:	JACKIE GLEASON BUS DEPOT
Address:	845 5TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Address Match Type:	Not reported
Open USTs:	8
Closed USTs:	18
TOS USTs:	0
Population 1500ft:	8083
Private Wells 1500ft:	14
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-74.002403

JACKIE GLEASON BUS DEPOT (Continued) **1028599262**

Y Coord: 40.6522570000001
Latitude: 40.652257
Longitude: -74.002403

UST FINDER:
Object ID: 1316132
Facility ID: NY5859
Tank ID: NY108513
Tank Status: Open
Installation Date: 1994/08/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 1000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316133
Facility ID: NY5859
Tank ID: NY108512
Tank Status: Closed
Installation Date: 1994/08/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316134
Facility ID: NY5859
Tank ID: NY108511
Tank Status: Closed
Installation Date: 1994/08/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316135
Facility ID: NY5859
Tank ID: NY108510
Tank Status: Closed
Installation Date: 1994/08/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316136
Facility ID: NY5859
Tank ID: NY9477
Tank Status: Open
Installation Date: 1994/08/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 1000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316137
Facility ID: NY5859
Tank ID: NY9476

JACKIE GLEASON BUS DEPOT (Continued) **1028599262**

Tank Status: Closed
Installation Date: 1994/08/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316138
Facility ID: NY5859
Tank ID: NY9474
Tank Status: Closed
Installation Date: 1984/12/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 1000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316139
Facility ID: NY5859
Tank ID: NY8500
Tank Status: Closed
Installation Date: 1994/08/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316140
Facility ID: NY5859
Tank ID: NY8304
Tank Status: Open
Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 275
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316141
Facility ID: NY5859
Tank ID: NY8303
Tank Status: Open
Installation Date: 1994/09/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 20000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316142
Facility ID: NY5859
Tank ID: NY8302
Tank Status: Open
Installation Date: 1994/08/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 1000
Substances: Not reported
Tank Wall Type: Not reported

JACKIE GLEASON BUS DEPOT (Continued) **1028599262**

Object ID:	1316143
Facility ID:	NY5859
Tank ID:	NY8301
Tank Status:	Closed
Installation Date:	1994/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1316144
Facility ID:	NY5859
Tank ID:	NY8300
Tank Status:	Closed
Installation Date:	1994/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1316145
Facility ID:	NY5859
Tank ID:	NY8282
Tank Status:	Open
Installation Date:	1994/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1316146
Facility ID:	NY5859
Tank ID:	NY8281
Tank Status:	Closed
Installation Date:	1994/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1316147
Facility ID:	NY5859
Tank ID:	NY8280
Tank Status:	Closed
Installation Date:	1994/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1316148
Facility ID:	NY5859
Tank ID:	NY8023
Tank Status:	Closed
Installation Date:	1994/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	1000

JACKIE GLEASON BUS DEPOT (Continued) **1028599262**

Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316149
Facility ID: NY5859
Tank ID: NY8022
Tank Status: Open
Installation Date: 1994/08/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 600
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316150
Facility ID: NY5859
Tank ID: NY8021
Tank Status: Closed
Installation Date: 1994/08/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316151
Facility ID: NY5859
Tank ID: NY7399
Tank Status: Open
Installation Date: Not reported
Removal Date: Not reported
Tank Capacity: 275
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316152
Facility ID: NY5859
Tank ID: NY108509
Tank Status: Closed
Installation Date: 1984/12/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316153
Facility ID: NY5859
Tank ID: NY9475
Tank Status: Closed
Installation Date: 1984/12/01 16:00:00+00
Removal Date: Not reported
Tank Capacity: 1000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1316154
Facility ID: NY5859
Tank ID: NY8499
Tank Status: Closed

JACKIE GLEASON BUS DEPOT (Continued) **1028599262**

Installation Date:	1984/12/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	10000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316155
Facility ID:	NY5859
Tank ID:	NY8299
Tank Status:	Closed
Installation Date:	1984/12/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316156
Facility ID:	NY5859
Tank ID:	NY8298
Tank Status:	Closed
Installation Date:	1984/12/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1316157
Facility ID:	NY5859
Tank ID:	NY8020
Tank Status:	Closed
Installation Date:	1984/12/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported

AC211 **JACKIE GLEASON BUS DEPOT** **NY CBS** **S120838864**
ENE **845 5TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.211 mi.
1114 ft. **Site 6 of 15 in cluster AC**

Relative: **Higher**

Actual: **62 ft.**

CBS:

Name:	JACKIE GLEASON BUS DEPOT
Address:	845 5TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
CBS Number:	2-000283
Program Type:	CBS
Facility Status:	Active
Expiration Date:	08/11/2023
Dec Region:	2
UTMX:	584357.28405
UTMY:	4500698.36145

AC212 **JACKIE GLEASON BUS DEPOT** **NY UST** **U004063208**
ENE **845 5TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.211 mi.
1114 ft. **Site 7 of 15 in cluster AC**

Relative:
Higher

Actual:
62 ft.

UST:

Name:	JACKIE GLEASON BUS DEPOT
Address:	845 5TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Id/Status:	2-190233 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	06/05/2027
UTM X:	584339.50683
UTM Y:	4500633.77354
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	5859
Affiliation Type:	Mail Contact
Company Name:	NYC TRANSIT AUTHORITY
Contact Type:	DIRECTOR, EPIH
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY
Address2:	27TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	DOREEN.BOATSWAIN@NYCT.COM
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-01-27

Site Id:	5859
Affiliation Type:	Facility Owner
Company Name:	NYC TRANSIT AUTHORITY
Contact Type:	DIRECTOR, EPIH
Contact Name:	DOREEN BOATSWAIN
Address1:	2 BROADWAY
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10004
Country Code:	001
Phone:	(646) 252-5777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-06-09

Site Id:	5859
Affiliation Type:	Facility Operator
Company Name:	ROGER MIGNOTT
Contact Type:	Not reported
Contact Name:	ROGER MIGNOTT
Address1:	845 5TH AVE

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(347) 682-0124
EMail:	ROGER.MIGNOTT@NYCT.COM
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-01-27

Site Id:	5859
Affiliation Type:	Emergency Contact
Company Name:	NYC TRANSIT AUTHORITY
Contact Type:	Not reported
Contact Name:	BUS COMMAND CENTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 927-7777
EMail:	Not reported
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-01-27

Tank Info:

Tank Number:	#7
Tank ID:	67161
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	275
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0013
Common Name of Substance:	Lube Oil

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
G08 - Tank Secondary Containment - Flexible Internal Lining (Bladder)
A00 - Tank Internal Protection - None

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
I05 - Overfill - Vent Whistle

Tank Number:	#8
Tank ID:	67162
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	275
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0013
Common Name of Substance:	Lube Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I05 - Overfill - Vent Whistle
G08 - Tank Secondary Containment - Flexible Internal Lining (Bladder)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Number:	001
Tank ID:	6688
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	12/01/1984
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	ZZ
Date Test:	09/01/1991
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

Equipment Records:

A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B04 - Tank External Protection - Fiberglass
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	012
Tank ID:	6699
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	12/01/1984
Date Tank Closed:	09/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	ZZ
Date Test:	10/01/1991
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B04 - Tank External Protection - Fiberglass
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)

Tank Number:	013
Tank ID:	6700
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	12/01/1984
Date Tank Closed:	09/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	ZZ

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

Date Test: 10/01/1991
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
H00 - Tank Leak Detection - None
I00 - Overfill - None
B04 - Tank External Protection - Fiberglass
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground

Tank Number: 014
Tank ID: 6701
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1000
Install Date: 12/01/1984
Date Tank Closed: 09/01/1994
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: ZZ
Date Test: 10/01/1991
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B04 - Tank External Protection - Fiberglass
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: 015
Tank ID: 6702
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 12/01/1984
Date Tank Closed: 09/01/1994
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

Material Code: 0013
Common Name of Substance: Lube Oil

Tightness Test Method: ZZ
Date Test: 09/01/1991
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B04 - Tank External Protection - Fiberglass
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A03 - Tank Internal Protection - Fiberglass Liner (FRP)

Tank Number: 016
Tank ID: 45257
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 12/01/1984
Date Tank Closed: 09/01/1994
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0013
Common Name of Substance: Lube Oil

Tightness Test Method: ZZ
Date Test: 09/01/1991
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B04 - Tank External Protection - Fiberglass
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 017
Tank ID: 45258
Tank Status: Closed - Removed
Material Name: Closed - Removed

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

Capacity Gallons:	550
Install Date:	12/01/1984
Date Tank Closed:	09/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	ZZ
Date Test:	09/01/1991
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	DSL-1
Tank ID:	48612
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	08/01/1994
Date Tank Closed:	06/02/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
I03 - Overfill - Automatic Shut-Off

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	DSL-10
Tank ID:	48621
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	08/01/1994
Date Tank Closed:	06/02/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	DSL-2
Tank ID:	48613
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	08/01/1994
Date Tank Closed:	06/02/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
I03 - Overfill - Automatic Shut-Off
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: DSL-3
Tank ID: 48614
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 4000
Install Date: 08/01/1994
Date Tank Closed: 06/02/2017
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

Tank Number:	DSL-4
Tank ID:	48615
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	08/01/1994
Date Tank Closed:	06/02/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	DSL-5
Tank ID:	48616
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	08/01/1994
Date Tank Closed:	06/02/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin

Tank Number:	DSL-6
Tank ID:	48617
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	08/01/1994
Date Tank Closed:	06/02/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin

Tank Number:	DSL-7
Tank ID:	48618
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

Install Date:	08/01/1994
Date Tank Closed:	06/02/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	DSL-8
Tank ID:	48619
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	08/01/1994
Date Tank Closed:	06/02/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
C02 - Pipe Location - Underground/On-ground

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off

Tank Number:	DSL-9
Tank ID:	48620
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	08/01/1994
Date Tank Closed:	06/02/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser

Tank Number:	EMGEN-1
Tank ID:	48622
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	600
Install Date:	08/01/1994
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 14
Date Test: 02/11/2000
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: nFormUpd
Last Modified: 01/27/2023

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: H/O-1
Tank ID: 48629
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 20000
Install Date: 09/01/1994
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 14
Date Test: 02/11/2000
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J05 - Dispenser - On Site Heating System (Supply/Return)

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	JAC-17
Tank ID:	48628
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	1000
Install Date:	08/01/1994
Date Tank Closed:	05/04/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	M/O-1
Tank ID:	48626
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1000
Install Date:	08/01/1994
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0013
Common Name of Substance:	Lube Oil
Tightness Test Method:	14
Date Test:	02/11/2000
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	nFormUpd
Last Modified:	01/27/2023

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Number:	M/O-2
Tank ID:	48627
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1000
Install Date:	08/01/1994
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0013
Common Name of Substance:	Lube Oil
Tightness Test Method:	19
Date Test:	02/28/2000
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	nFormUpd
Last Modified:	01/27/2023

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B04 - Tank External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	W/O-1
Tank ID:	48624
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1000

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

Install Date:	08/01/1994
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	14
Date Test:	02/28/2000
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	nFormUpd
Last Modified:	01/27/2023

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
J00 - Dispenser - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	W/O-2
Tank ID:	48625
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1000
Install Date:	08/01/1994
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	nFormUpd
Last Modified:	01/27/2023

Equipment Records:

A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
J00 - Dispenser - None

JACKIE GLEASON BUS DEPOT (Continued) **U004063208**

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
G04 - Tank Secondary Containment - Double-Walled (Underground)

AC213 **NYCTA - JACKIE GLEASON DEPOT - NYCTA** **NY Spills** **S122480165**
ENE **845 5TH AVE** **NY MANIFEST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.211 mi.
1114 ft. **Site 8 of 15 in cluster AC**

Relative: **Higher**
Actual: **62 ft.**

SPILLS:

Name:	NYC TRANSIT
Address:	845 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1803302 / 2018-08-08
Facility ID:	1803302
Facility Type:	ER
DER Facility ID:	525022
Site ID:	571933
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	D4
SWIS:	2401
Spill Date:	2018-06-21
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2018-06-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2018-06-26
Spill Record Last Update:	2018-08-08
Spiller Name:	MICHAEL MANDAC
Spiller Company:	NYC TRANSIT
Spiller Address:	845 5TH AVE
Spiller Company:	999
Contact Name:	MICHAEL MANDAC
DEC Memo:	valve left open during service, c/u pending
Remarks:	6/26/18-Lin- PBS 2-190233. While doing excavation work at the bus depot, the construction crew discovered a buried hydraulic oil tank filled with water/oil. The tank is improperly abandoned. Piping was discovered that is suspected to be related to the hydraulic oil tank found. Close to a drum of water/oil mixture was pumped. The tank is estimated to be approximately 50 gallons. Plan to either remove tank and collect endpoint samples or installed soil borings. Pending investigation. Will send all documentations and plan to Demeo. 8/8/18 TJD File review. Email from NYCTA System Safety (Mandac) received detailing history of location and misreporting of spill. No discharge occurred as per below info received from NYCTA: Sorry for the late

NYCTA - JACKIE GLEASON DEPOT - NYCTA (Continued) **S122480165**

follow up. I have been grossly misinformed about this issue. First and foremost, there was never any sheen in either the remaining piston cylinder or the pumped out liquid sitting in a drum. The project engineer did not seem to understand what sheen meant, not did the Buses compliance group step in and intervene. The attached pictures show just water. No odor. No PID readings in the construction zone, in the drum, or in the in-ground piston cylinder. The hydraulic oil tank reservoir was an aboveground tank that was removed back in 2009. Photographic documentation includes removal of the tank, pump, and associated piping, as well as proof of removal of the other hydraulic piston. The PM of that project is still with Buses and stated that the contractor cleaned and removed all piping. It looks like the piston was left in place because it was just too costly to remove both pistons ten years ago. The hydraulic oil was not an unknown product. Since 1992 (and this applies to Jackie Gleason per the paperwork but probably is systemwide), stock number 69-12-1510 has been used as hydraulic oil for the bus chassis wash lifts. That stock number represents several products which are all similar in composition. Given that there was no initial contamination of water (misreported) and no source of contamination exists, OSS is requesting that DEC administratively close out the spill which should have been reported in the first place. Based upon the documentation provided - spill is administratively closed.

All Materials:

Site ID:	571933
Operable Unit ID:	1319750
Operable Unit:	01
Material ID:	2327793
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

NY MANIFEST:

EPA ID:	NYD980642300
Country:	USA
Name:	NYCTA - JACKIE GLEASON DEPOT - NYCTA
Address:	845 5TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	871 5TH AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	NYCTA - JACKIE GLEASON DEPOT - NYCTA

NYCTA - JACKIE GLEASON DEPOT - NYCTA (Continued) **S122480165**

Mailing Contact:	DANIEL YU
Mailing Address 1:	2 BROADWAY
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462525777

Manifest Data:

Document ID:	NYA9060039
Manifest Status:	C - Completed copy
Trans1 State ID:	MU4522
Year:	1988
Trans2 State ID:	Not reported
Generator Ship Date:	881006
Trans1 Recv Date:	881006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	881006
Part A Recv Date:	881013
Part B Recv Date:	881012
Generator EPA ID:	NYD980642300
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	IGNITABLE WASTE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00400
Units:	Pounds
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100

Document ID:	NYC3142416
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/1994
Trans1 Recv Date:	07/22/1994

NYCTA - JACKIE GLEASON DEPOT - NYCTA (Continued) **S122480165**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/22/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980642300
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	IGNITABLE WASTE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00075
Units:	Gallons (liquids only)
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	ILA8347483
Manifest Status:	Not reported
Trans1 State ID:	UPW151288
Year:	1999
Trans2 State ID:	UPW203954
Generator Ship Date:	06/25/1999
Trans1 Recv Date:	06/25/1999
Trans2 Recv Date:	06/30/1999
TSD Site Recv Date:	07/02/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980642300
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID 1:	ILD980613913
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

NYCTA - JACKIE GLEASON DEPOT - NYCTA (Continued) **S122480165**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00036
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC1095974
Manifest Status:	Not reported
Trans1 State ID:	DL7754
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	07/25/1991
Trans1 Recv Date:	07/25/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/25/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980642300
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	IGNITABLE WASTE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported

NYCTA - JACKIE GLEASON DEPOT - NYCTA (Continued) **S122480165**

Waste Code 6:	Not reported
Quantity:	00430
Units:	Pounds
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC1819776
Manifest Status:	Not reported
Trans1 State ID:	GF4332
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	08/18/1992
Trans1 Recv Date:	08/18/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/18/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980642300
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	IGNITABLE WASTE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00430
Units:	Pounds
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NJA1968263
Manifest Status:	Not reported
Trans1 State ID:	S5811
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	12/29/1994
Trans1 Recv Date:	12/29/1994
Trans2 Recv Date:	Not reported

NYCTA - JACKIE GLEASON DEPOT - NYCTA (Continued) **S122480165**

TSD Site Recv Date:	12/29/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980642300
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC1546479
Manifest Status:	Not reported
Trans1 State ID:	GF4332
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	03/25/1992
Trans1 Recv Date:	03/25/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/25/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980642300
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980785760
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported

NYCTA - JACKIE GLEASON DEPOT - NYCTA (Continued) **S122480165**

Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	IGNITABLE WASTE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00430
Units:	Pounds
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NJA3126477
Manifest Status:	Not reported
Trans1 State ID:	S5811
Year:	1999
Trans2 State ID:	Not reported
Generator Ship Date:	09/16/1999
Trans1 Recv Date:	09/16/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/16/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980642300
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED

NYCTA - JACKIE GLEASON DEPOT - NYCTA (Continued) **S122480165**

SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NJA2786208
Manifest Status:	Not reported
Trans1 State ID:	NJDEPES58
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	12/05/1997
Trans1 Recv Date:	12/05/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/05/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980642300
Trans1 EPA ID:	NJ0000027193
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	CORROSIVE WASTE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00220
Units:	Gallons (liquids only)
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL

NYCTA - JACKIE GLEASON DEPOT - NYCTA (Continued) **S122480165**

KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code 8: Not reported
Waste Code: Not reported
Waste Code 10: Not reported
Waste Code 11: Not reported
Quantity: 00055
Units: Gallons (liquids only)
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NJA2785761
Manifest Status: Not reported
Trans1 State ID: NY1123200
Year: 1998
Trans2 State ID: Not reported
Generator Ship Date: 02/05/1998
Trans1 Recv Date: 02/05/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/05/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980642300
Trans1 EPA ID: NJ0000027193
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2: Not reported
Waste Code 3: Not reported

NYCTA - JACKIE GLEASON DEPOT - NYCTA (Continued) **S122480165**

Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NJA1967514
Manifest Status:	Not reported
Trans1 State ID:	S5811
Year:	1995
Trans2 State ID:	Not reported
Generator Ship Date:	04/04/1995
Trans1 Recv Date:	04/04/1995
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/04/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980642300
Trans1 EPA ID:	NJD982281016
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	IGNITABLE WASTE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
280 additional NY MANIFEST: record(s) in the EDR Site Report.

AE214 **CON EDISON** **NY MANIFEST** **1016965472**
North **334 36TH STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.213 mi.
1123 ft. **Site 3 of 6 in cluster AE**

Relative: **Lower**

Actual: **18 ft.**

NY MANIFEST:

EPA ID:	NYP004383519
Country:	USA
Name:	CON EDISON
Address:	334 36TH STREET
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	334 36TH ST
Location Address 2:	MH49083
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/31/2013
Trans1 Recv Date:	10/31/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/31/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004383519
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002298419GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON (Continued) **1016965472**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	400
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AE215 **CON EDISON - MANHOLE 49083** **RCRA-LQG** **1016965473**
North **334 36TH STREET** **NYP004383519**
1/8-1/4 **BROOKLYN, NY 11232**
0.213 mi.
1123 ft. **Site 4 of 6 in cluster AE**

Relative: **Lower**

Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	20140327
Handler Name:	Con Edison - Manhole 49083
Handler Address:	36TH STREET
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004383519
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	518-473-8034
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No

CON EDISON - MANHOLE 49083 (Continued) **1016965473**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20131031
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003

CON EDISON - MANHOLE 49083 (Continued) **1016965473**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20131031
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140327
Handler Name: CON EDISON - MANHOLE 49083
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131031
Handler Name: CON EDISON MANHOLE: 49083
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131130
Handler Name: CON EDISON MANHOLE: 49083
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

CON EDISON - MANHOLE 49083 (Continued) **1016965473**

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

W216 **SHELL SERVICE STATION** **UST FINDER** **1028571456**
ENE **842 FIFTH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.216 mi.
1139 ft. **Site 3 of 8 in cluster W**

Relative:
Higher

Actual:
56 ft.

UST FINDER:
Object ID: 294978
Facility ID: NY21739
Name: SHELL SERVICE STATION
Address: 842 FIFTH AVENUE
City,State,Zip: BROOKLYN, NY 11232
Address Match Type: Not reported
Open USTs: 4
Closed USTs: 12
TOS USTs: 0
Population 1500ft: 7578
Private Wells 1500ft: 15
Within 100yr Floodplain: No
Land Use: Developed, High Intensity
Within SPA: No
SPA PWS Facility ID: Not reported
SPA Water Type: Not reported
SPA Facility Type: Not reported
SPA HUC12: Not reported
Within WHPA: No
WHPA PWS Facility ID: Not reported
WHPA Water Type: Not reported
WHPA Facility Type: Not reported
WHPA HUC12: Not reported
Facility Status: Open UST(s)
Date of Last Inspection: Not reported
EPA Region: 2
Tribe: Not reported
Coordinate Source: State
X Coord: -74.0018889999999
Y Coord: 40.6527770000001
Latitude: 40.652777
Longitude: -74.001889

UST FINDER:
Object ID: 1216657
Facility ID: NY21739
Tank ID: NY25661
Tank Status: Closed
Installation Date: 1994/08/01 15:59:59+00

SHELL SERVICE STATION (Continued) **1028571456**

Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1216658
Facility ID: NY21739
Tank ID: NY25781
Tank Status: Closed
Installation Date: 1994/08/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1216659
Facility ID: NY21739
Tank ID: NY25782
Tank Status: Closed
Installation Date: 1994/08/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1216660
Facility ID: NY21739
Tank ID: NY25783
Tank Status: Closed
Installation Date: 1964/01/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1216661
Facility ID: NY21739
Tank ID: NY26876
Tank Status: Closed
Installation Date: 1964/01/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1216662
Facility ID: NY21739
Tank ID: NY26877
Tank Status: Closed
Installation Date: 1964/01/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1216663
Facility ID: NY21739

SHELL SERVICE STATION (Continued) **1028571456**

Tank ID: NY26878
Tank Status: Closed
Installation Date: 1964/01/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1216664
Facility ID: NY21739
Tank ID: NY26879
Tank Status: Closed
Installation Date: 1964/01/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1216665
Facility ID: NY21739
Tank ID: NY29447
Tank Status: Closed
Installation Date: 1964/01/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1216666
Facility ID: NY21739
Tank ID: NY29448
Tank Status: Closed
Installation Date: 1964/01/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1216667
Facility ID: NY21739
Tank ID: NY111126
Tank Status: Closed
Installation Date: 1964/01/01 16:00:01+00
Removal Date: Not reported
Tank Capacity: 550
Substances: Not reported
Tank Wall Type: Not reported

Object ID: 1216668
Facility ID: NY21739
Tank ID: NY26880
Tank Status: Open
Installation Date: 1994/08/01 15:59:59+00
Removal Date: Not reported
Tank Capacity: 4000
Substances: Not reported
Tank Wall Type: Not reported

SHELL SERVICE STATION (Continued) **1028571456**

Object ID:	1216669
Facility ID:	NY21739
Tank ID:	NY29446
Tank Status:	Closed
Installation Date:	1994/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1216670
Facility ID:	NY21739
Tank ID:	NY29449
Tank Status:	Open
Installation Date:	1994/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1216671
Facility ID:	NY21739
Tank ID:	NY29450
Tank Status:	Open
Installation Date:	1994/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1216672
Facility ID:	NY21739
Tank ID:	NY29451
Tank Status:	Open
Installation Date:	1994/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

W217 **AMOCO SERVICE STATION** **NY AST** **1000912233**
ENE **842 5TH AVE** **NY Spills** **NY0000562025**
1/8-1/4 **BROOKLYN, NY 11232** **RCRA NonGen / NLR**
0.216 mi. **NY MANIFEST**
1139 ft. **Site 4 of 8 in cluster W**

Relative:
Higher

Actual:
56 ft.

AST:

Name:	SHELL SERVICE STATION
Address:	842 FIFTH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-509108
Program Type:	PBS
UTM X:	584310.27345
UTM Y:	4500704.32967

AMOCO SERVICE STATION (Continued) **1000912233**

Expiration Date: 01/25/2026
Site Type: Retail Gasoline Sales

Affiliation Records:
Site Id: 21739
Affiliation Type: Emergency Contact
Company Name: 3072 CROPSEY AVENUE CORP.
Contact Type: Not reported
Contact Name: CARY WOLF
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (516) 997-9300
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-03-06

Site Id: 21739
Affiliation Type: Facility Owner
Company Name: BILL WOLF PETROLEUM
Contact Type: PRESIDENT
Contact Name: ADAM WOLF
Address1: 100 JERICHO QUADRANGLE SUITE 209
Address2: Not reported
City: JERICHO
State: NY
Zip Code: 11753
Country Code: 001
Phone: (516) 997-9300
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-07-07

Site Id: 21739
Affiliation Type: Facility Operator
Company Name: SHELL SERVICE STATION
Contact Type: Not reported
Contact Name: MOHAMMED ALAM
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 499-6290
EMail: Not reported
Fax Number: Not reported
Modified By: LXZIELIN
Date Last Modified: 2016-12-21

Site Id: 21739
Affiliation Type: Mail Contact
Company Name: BILL WOLF PETROLEUM

AMOCO SERVICE STATION (Continued) **1000912233**

Contact Type:	Not reported
Contact Name:	CARY WOLF
Address1:	100 JERICHO QUADRANGLE
Address2:	SUITE 209
City:	JERICHO
State:	NY
Zip Code:	11753
Country Code:	001
Phone:	(516) 997-9300
EMail:	CWOLF@BWPETROLEUM.COM
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2016-12-21

Tank Info:

Tank Number:	005
Tank Id:	39599
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

H00 - Tank Leak Detection - None
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	08/01/1994
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1994
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	105
Tank Id:	47936
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None

AMOCO SERVICE STATION (Continued) **1000912233**

I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
L00 - Piping Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
D00 - Pipe Type - No Piping

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/01/1994
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

SPILLS:

Name:	842 FIFTH AVE/BKLYN/AMOCO
Address:	842 5TH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8901960 / 2003-02-12
Facility ID:	8901960
Facility Type:	ER
DER Facility ID:	125953
Site ID:	147964
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	A3
SWIS:	2401
Spill Date:	1989-05-26
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	1989-05-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-06-02
Spill Record Last Update:	2003-11-13
Spiller Name:	Not reported
Spiller Company:	AMOCO GAS STATION
Spiller Address:	842 FIFTH AVENUE

AMOCO SERVICE STATION (Continued) **1000912233**

Spiller Company: 001
Contact Name: Not reported
DEC Memo: ON GOING FOR 2 YEARS, TANKS OVERFILL & RUN ON STREET.
Remarks: Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 2/12/03. Closed Due To The Nature / Extent Of The Spill Report. 3/14/03 Reassigned From Sullivan To Vought.

All Materials:
Site ID: 147964
Operable Unit ID: 927868
Operable Unit: 01
Material ID: 449679
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

RCRA Listings:
Date Form Received by Agency: 20070101
Handler Name: Amoco Service Station
Handler Address: 5TH AVE
Handler City,State,Zip: BROOKLYN, NY 11232-2522
EPA ID: NY0000562025
Contact Name: Not reported
Contact Address: JERICHO TNPK
Contact City,State,Zip: JERICHO, NY 11753
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Ny
State District: NYSDEC R2
Mailing Address: JERICHO TNPK
Mailing City,State,Zip: JERICHO, NY 11753
Owner Name: 3072 Cropsey Ave Corp
Owner Type: Private
Operator Name: 3072 Cropsey Ave Corp
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No

AMOCO SERVICE STATION (Continued) **1000912233**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200527
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: 3072 CROPSEY AVE CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	55 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11753
Owner/Operator Telephone:	516-987-9300
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: 3072 CROPSEY AVE CORP	
Legal Status:	Private

AMOCO SERVICE STATION (Continued) **1000912233**

Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	55 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11753
Owner/Operator Telephone:	516-987-9300
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: 3072 CROPSEY AVE CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	55 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11753
Owner/Operator Telephone:	516-987-9300
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: AMOCO SERVICE STATION	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: AMOCO SERVICE STATION	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: AMOCO SERVICE STATION	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported

AMOCO SERVICE STATION (Continued) **1000912233**

Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19940808
Handler Name: AMOCO SERVICE STATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NY0000562025
Country: USA
Name: AMOCO
Address: 842 FIFTH AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232-2522
Zip 4: Not reported
Location Address 1: 842 5TH AVE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: AMOCO
Mailing Contact: JED MEYERS
Mailing Address 1: MORRIS CORPORATE CTR 1 BLD C
Mailing Address 2: Not reported
Mailing City,State,Zip: PARSIPPANY, NJ 07054
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2013317000

Manifest Data:
Document ID: NYB4126806

AMOCO SERVICE STATION (Continued) **1000912233**

Manifest Status:	Not reported
Trans1 State ID:	PP1378
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	11/08/1994
Trans1 Recv Date:	11/08/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/08/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000562025
Trans1 EPA ID:	NYD986910222
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	IGNITABLE WASTE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00165
Units:	Gallons (liquids only)
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

W218 **SHELL SERVICE STATION** **NY UST** **U004062094**
ENE **842 FIFTH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.216 mi.
1139 ft. **Site 5 of 8 in cluster W**

Relative: **Higher**
Actual: **56 ft.**

UST:

Name:	SHELL SERVICE STATION
Address:	842 FIFTH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Id/Status:	2-509108 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	01/25/2026
UTM X:	584310.27345
UTM Y:	4500704.32967

SHELL SERVICE STATION (Continued) **U004062094**

Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 21739
Affiliation Type: Emergency Contact
Company Name: 3072 CROPSEY AVENUE CORP.
Contact Type: Not reported
Contact Name: CARY WOLF
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (516) 997-9300
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2007-03-06

Site Id: 21739
Affiliation Type: Facility Owner
Company Name: BILL WOLF PETROLEUM
Contact Type: PRESIDENT
Contact Name: ADAM WOLF
Address1: 100 JERICHO QUADRANGLE SUITE 209
Address2: Not reported
City: JERICHO
State: NY
Zip Code: 11753
Country Code: 001
Phone: (516) 997-9300
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-07-07

Site Id: 21739
Affiliation Type: Facility Operator
Company Name: SHELL SERVICE STATION
Contact Type: Not reported
Contact Name: MOHAMMED ALAM
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 499-6290
EMail: Not reported
Fax Number: Not reported
Modified By: LXZIELIN
Date Last Modified: 2016-12-21

Site Id: 21739
Affiliation Type: Mail Contact
Company Name: BILL WOLF PETROLEUM
Contact Type: Not reported

SHELL SERVICE STATION (Continued) **U004062094**

Contact Name:	CARY WOLF
Address1:	100 JERICHO QUADRANGLE
Address2:	SUITE 209
City:	JERICHO
State:	NY
Zip Code:	11753
Country Code:	001
Phone:	(516) 997-9300
EMail:	CWOLF@BWPETROLEUM.COM
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2016-12-21

Tank Info:

Tank Number:	001
Tank ID:	39595
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	08/01/1994
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	ZZ
Date Test:	09/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	002
Tank ID:	39596
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	08/01/1994
Date Tank Closed:	08/01/1994
Registered:	True

SHELL SERVICE STATION (Continued) **U004062094**

Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: ZZ
Date Test: 09/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B01 - Tank External Protection - Painted/Asphalt Coating
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 003
Tank ID: 39597
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 08/01/1994
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: ZZ
Date Test: 09/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B04 - Tank External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)

SHELL SERVICE STATION (Continued) **U004062094**

Tank Number:	004
Tank ID:	39598
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	08/01/1994
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	ZZ
Date Test:	09/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
J01 - Dispenser - Pressurized Dispenser
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	006
Tank ID:	39600
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	01/01/1964
Date Tank Closed:	08/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None

SHELL SERVICE STATION (Continued) **U004062094**

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser

Tank Number: 007
Tank ID: 39601
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1964
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
J02 - Dispenser - Suction Dispenser

Tank Number: 008
Tank ID: 39602
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1964
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI

SHELL SERVICE STATION (Continued) **U004062094**

Last Modified: 05/09/2022

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser

Tank Number: 009
Tank ID: 39603
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1964
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser

Tank Number: 010
Tank ID: 39604
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1964
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

SHELL SERVICE STATION (Continued) **U004062094**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser

Tank Number: 011
Tank ID: 39605
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1964
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
J02 - Dispenser - Suction Dispenser

Tank Number: 012
Tank ID: 39606
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1964
Date Tank Closed: 08/01/1994

SHELL SERVICE STATION (Continued) **U004062094**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser

Tank Number: 013
Tank ID: 39607
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 01/01/1964
Date Tank Closed: 08/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I00 - Overfill - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser

Tank Number: 101

SHELL SERVICE STATION (Continued) **U004062094**

Tank ID: 47932
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 08/01/1994
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 34
Date Test: 08/09/2022
Next Test Date: Not reported
Pipe Model: D
Modified By: LABATIST
Last Modified: 10/11/2022

Equipment Records:

K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
E04 - Piping Secondary Containment - Double walled UG
J02 - Dispenser - Suction Dispenser
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 102
Tank ID: 47933
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 08/01/1994
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 34
Date Test: 08/09/2022
Next Test Date: Not reported
Pipe Model: D
Modified By: TankSys
Last Modified: 05/15/2023

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass

SHELL SERVICE STATION (Continued) **U004062094**

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
L99 - Piping Leak Detection - Other
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	103
Tank ID:	47934
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	08/01/1994
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	34
Date Test:	08/09/2022
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	TankSys
Last Modified:	05/15/2023

Equipment Records:

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
L99 - Piping Leak Detection - Other
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number:	104
Tank ID:	47935
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	08/01/1994
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology

SHELL SERVICE STATION (Continued) **U004062094**

Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 34
Date Test: 08/09/2022
Next Test Date: Not reported
Pipe Model: D
Modified By: TankSys
Last Modified: 05/15/2023

Equipment Records:

K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
L99 - Piping Leak Detection - Other
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

---

Z219 **CON EDISON SERVICE BOX: 49296** **RCRA NonGen / NLR 1016966639**
SE **556 40TH ST** **NY MANIFEST NYP004394862**
1/8-1/4 **BROOKLYN, NY 11232**
0.216 mi.
1140 ft. **Site 6 of 9 in cluster Z**

Relative: **Higher**
Actual: **125 ft.**

RCRA Listings:

Date Form Received by Agency: 20131220
Handler Name: Con Edison Service Box: 49296
Handler Address: 40TH ST
Handler City,State,Zip: BROOKLYN, NY 11232
EPA ID: NYP004394862
Contact Name: THOMAS TEELING
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 212-460-3770
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: SENIOR SCIENTIST
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Ny
State District: NYSDEC R2
Mailing Address: IRVING PL, 15TH FL NE
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported
Owner Type: Not reported
Operator Name: Not reported

CON EDISON SERVICE BOX: 49296 (Continued) **1016966639**

Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131120
Handler Name: CON EDISON SERVICE BOX:	49296
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 49296 (Continued) **1016966639**

Receive Date:	20131220
Handler Name: CON EDISON SERVICE BOX:	49296
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004394862
Country:	USA
Name:	CON EDISON
Address:	556 40TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	556 40 ST
Location Address 2:	SERVICE BOX # 49296
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported

CON EDISON SERVICE BOX: 49296 (Continued) **1016966639**

Generator Ship Date:	11/20/2013
Trans1 Recv Date:	11/20/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/21/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004394862
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002299086GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

W220 **CON EDISON** **RCRA NonGen / NLR** **1019909462**
ENE **472 36TH ST** **FINDS** **NYP004885105**
1/8-1/4 **BROOKLYN, NY 11232** **ECHO**
0.216 mi.
1141 ft. **Site 6 of 8 in cluster W**

Relative:
Higher

Actual:
52 ft.

RCRA Listings:

Date Form Received by Agency:	20151230
Handler Name:	Con Edison
Handler Address:	36TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004885105
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported

CON EDISON (Continued) **1019909462**

Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported

CON EDISON (Continued) **1019909462**

Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:

Receive Date:	20151230
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151230
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069665311

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

CON EDISON (Continued) **1019909462**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019909462
Registry ID:	110069665311
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069665311
Name:	CON EDISON
Address:	472 36TH ST
City,State,Zip:	BROOKLYN, NY 11232

W221 **CON EDISON** **NJ MANIFEST** **S120678607**
ENE **472 36TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.216 mi.
1141 ft. **Site 7 of 8 in cluster W**

Relative:
Higher

Actual:
52 ft.

NJ MANIFEST:

EPA ID:	NYP004885105
Name:	CON EDISON
Address:	472 36TH ST
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004885105
Manifest Number:	015320393JJK
Date Shipped:	12/30/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

CON EDISON (Continued) **S120678607**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

AC222 **CON EDISON SERVICE BOX: 33952** **RCRA NonGen / NLR** **1016678027**
ENE **845 5TH AVE** **FINDS** **NYP004317111**
1/8-1/4 **NEW YORK, NY 10060** **ECHO**
0.217 mi. **NY MANIFEST**
1148 ft. **Site 9 of 15 in cluster AC**

Relative: **Higher**
Actual: **59 ft.**

RCRA Listings:

Date Form Received by Agency:	20130630
Handler Name:	Con Edison Service Box: 33952
Handler Address:	5TH AVE
Handler City,State,Zip:	NEW YORK, NY 10060
EPA ID:	NYP004317111
Contact Name:	BENJAMIN BAMONTE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-894-9549
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	VING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported

CON EDISON SERVICE BOX: 33952 (Continued) **1016678027**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140402
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130530
Handler Name: CON EDISON SERVICE BOX:	33952
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130630

CON EDISON SERVICE BOX: 33952 (Continued) **1016678027**

Handler Name: CON EDISON SERVICE BOX: 33952
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058874696

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016678027
Registry ID: 110058874696
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058874696
Name: CON EDISON SERVICE BOX: 33952
Address: 845 5TH AVE
City,State,Zip: NEW YORK, NY 10060

NY MANIFEST:
EPA ID: NYP004317111
Country: USA
Name: CON EDISON
Address: 845 5TH AVE
Address 2: Not reported
City,State,Zip: NEW YORK, NY 10060
Zip 4: Not reported
Location Address 1: FO 845 5TH AVE
Location Address 2: Not reported

CON EDISON SERVICE BOX: 33952 (Continued) **1016678027**

Location City,State,Zip: NEW YORK, NY 10065
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 05/29/2013
Trans1 Recv Date: 05/29/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/03/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004317111
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 010917916JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported

CON EDISON SERVICE BOX: 33952 (Continued) **1016678027**

Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1
EPA ID:	NYP004168969
Country:	USA
Name:	CONSOLIDATED EDISON
Address:	845 5TH AVE & E 66TH ST OPP OF
Address 2:	Not reported
City,State,Zip:	NEW YORK, NY 10022
Zip 4:	Not reported
Location Address 1:	OPP 845 5TH AVE & E. 66TH ST
Location Address 2:	Not reported
Location City,State,Zip:	NEW YORK, NY 10022
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/2009
Trans1 Recv Date:	05/06/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/07/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004168969
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003534014JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

CON EDISON SERVICE BOX: 33952 (Continued) **1016678027**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	4900
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AA223 **NYSDOT D254608 GOWANUS VIADUCT** **RCRA NonGen / NLR** **1000871437**
WNW **255 42ND ST** **FINDS** **NY0000045005**
1/8-1/4 **BROOKLYN, NY 11220** **ECHO**
0.218 mi. **NY MANIFEST**
1149 ft. **Site 2 of 8 in cluster AA**

Relative: **Lower**
Actual: **23 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Nysdot D254608 Gowanus Viaduct
Handler Address:	42ND ST
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NY0000045005
Contact Name:	PIETRO CALCARA
Contact Address:	HUNTERS POINT PLZ
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-439-8485
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	HUNTERS POINT PLZ
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Nysdot Region 2
Owner Type:	Municipal
Operator Name:	Nysdot Region 2

NYSDOT D254608 GOWANUS VIADUCT (Continued) **1000871437**

Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYSDOT REGION 2	
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported

NYSDOT D254608 GOWANUS VIADUCT (Continued) **1000871437**

Owner/Operator Address: 1 HUNTERS POINT PLZ
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-439-8485
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYSDOT REGION 2
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1 HUNTERS POINT PLZ
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-439-8485
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYSDOT REGION 2
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1 HUNTERS POINT PLZ
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-439-8485
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYSDOT D254608 GOWANUS VIADUCT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYSDOT D254608 GOWANUS VIADUCT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

NYSDOT D254608 GOWANUS VIADUCT (Continued) **1000871437**

Receive Date: 19931124
Handler Name: NYSDOT D254608 GOWANUS VIADUCT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940216
Handler Name: N.Y.S.D.O.T. CONSTRUCTION FIELD OFFICE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 92119
NAICS Description: OTHER GENERAL GOVERNMENT SUPPORT

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004309061

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000871437
Registry ID: 110004309061

NYSDOT D254608 GOWANUS VIADUCT (Continued) **1000871437**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004309061
Name: NYSDOT D254608 GOWANUS VIADUCT
Address: 255 42ND ST
City,State,Zip: BROOKLYN, NY 11220

NY MANIFEST:
EPA ID: NY0000045005
Country: USA
Name: NYSDOT
Address: 255 42ND ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11220
Zip 4: Not reported
Location Address 1: 255 42ND ST(BTWN 2ND & 3RD)
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11220
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: NYSDOT
Mailing Contact: D BERKHOFER
Mailing Address 1: 420 64TH ST APT 4D
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11220
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7184398485

Manifest Data:
Document ID: NJA2024106
Manifest Status: Not reported
Trans1 State ID: S6993
Year: 1994
Trans2 State ID: Not reported
Generator Ship Date: 11/09/1994
Trans1 Recv Date: 11/09/1994
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/09/1994
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NY0000045005
Trans1 EPA ID: NJD980772768
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported

NYSDOT D254608 GOWANUS VIADUCT (Continued) **1000871437**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00013
Units:	Cubic Yards
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NJA2024111
Manifest Status:	Not reported
Trans1 State ID:	S6993
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	10/31/1994
Trans1 Recv Date:	10/31/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/31/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000045005
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00014
Units:	Cubic Yards
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	01.00

NYSDOT D254608 GOWANUS VIADUCT (Continued) **1000871437**

Document ID:	NJA2022908
Manifest Status:	Not reported
Trans1 State ID:	S6993
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	11/16/1994
Trans1 Recv Date:	11/16/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/16/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000045005
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00011
Units:	Cubic Yards
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NJA1972409
Manifest Status:	Not reported
Trans1 State ID:	NJDEPES69
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	06/10/1994
Trans1 Recv Date:	06/10/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/10/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000045005
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported

NYSDOT D254608 GOWANUS VIADUCT (Continued) **1000871437**

Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00014
Units:	Cubic Yards
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	01.00
Document ID:	NJA1978709
Manifest Status:	Not reported
Trans1 State ID:	S6993
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	10/07/1994
Trans1 Recv Date:	10/07/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/07/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000045005
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported

NYSDOT D254608 GOWANUS VIADUCT (Continued) **1000871437**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00017
Units:	Cubic Yards
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NJA1978714
Manifest Status:	Not reported
Trans1 State ID:	S6993
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	10/11/1994
Trans1 Recv Date:	10/11/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/11/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000045005
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00017
Units:	Cubic Yards
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NJA1978724
Manifest Status:	Not reported
Trans1 State ID:	S6993
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	10/12/1994
Trans1 Recv Date:	10/12/1994

NYSDOT D254608 GOWANUS VIADUCT (Continued) **1000871437**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/12/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000045005
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00019
Units:	Cubic Yards
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NJA1978759
Manifest Status:	Not reported
Trans1 State ID:	S6993
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/1994
Trans1 Recv Date:	10/14/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000045005
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

NYSDOT D254608 GOWANUS VIADUCT (Continued) **1000871437**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00018
Units:	Cubic Yards
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NJA1978764
Manifest Status:	Not reported
Trans1 State ID:	S6993
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	10/17/1994
Trans1 Recv Date:	10/17/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000045005
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00015
Units:	Cubic Yards
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill

NYSDOT D254608 GOWANUS VIADUCT (Continued) **1000871437**

Specific Gravity:	01.00
Document ID:	NJA1978779
Manifest Status:	Not reported
Trans1 State ID:	63095
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/1994
Trans1 Recv Date:	10/19/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/19/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000045005
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00017
Units:	Cubic Yards
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	01.00
Document ID:	NJA1978801
Manifest Status:	Not reported
Trans1 State ID:	S6993
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	10/21/1994
Trans1 Recv Date:	10/21/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000045005
Trans1 EPA ID:	NJD980772768
Trans2 EPA ID:	Not reported

NYSDOT D254608 GOWANUS VIADUCT (Continued) **1000871437**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00017
Units:	Cubic Yards
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
69 additional NY MANIFEST: record(s) in the EDR Site Report.

AA224 **CON EDISON** **NY MANIFEST** **S117741269**
WNW **258 42ND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.220 mi.
1160 ft. **Site 3 of 8 in cluster AA**

Relative:
Lower

Actual:
24 ft.

NY MANIFEST:

EPA ID:	NYP004744884
Country:	USA
Name:	CON EDISON
Address:	258 42ND ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	258 42ND ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL

CON EDISON (Continued) **S117741269**

Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 03/06/2015
Trans1 Recv Date: 03/06/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/09/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004744884
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002610841GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 5000
Units: Pounds
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 1

AA225 **CON EDISON** **NJ MANIFEST** **S120668454**
WNW **258 42ND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.220 mi.
1160 ft. **Site 4 of 8 in cluster AA**

Relative: **Lower**

Actual: **24 ft.**

NJ MANIFEST:

EPA ID:	NYP004744884
Name:	CON EDISON
Address:	258 42ND ST
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	IRVING PL15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004744884
Manifest Number:	002610841GBF
Date Shipped:	3/6/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

CON EDISON (Continued) **S120668454**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

AA226 **CON EDISON** **NY MANIFEST** **S118256548**
WNW **258 42ND ST MH48383** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.220 mi.
1160 ft. **Site 5 of 8 in cluster AA**

Relative: **Lower**
Actual: **24 ft.**

NY MANIFEST:

EPA ID:	NYP004744892
Country:	USA
Name:	CON EDISON
Address:	258 42ND ST MH48383
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	F/O 258 42ND ST
Location Address 2:	MH 48383
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/06/2015
Trans1 Recv Date:	03/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004744892
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S118256548**

TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610990GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AA227 **CON EDISON** **RCRA NonGen / NLR** **1018279648**
WNW **258 42ND ST MH48386** **FINDS** **NYP004744884**
1/8-1/4 **BROOKLYN, NY 11232** **ECHO**
0.220 mi.
1160 ft. **Site 6 of 8 in cluster AA**

Relative: **Lower**

Actual: **24 ft.**

RCRA Listings:

Date Form Received by Agency:	20150306
Handler Name:	Con Edison
Handler Address:	42ND ST MH48386
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004744884
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

CON EDISON (Continued) **1018279648**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

CON EDISON (Continued) **1018279648**

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON CO OF NY INC
Legal Status: Private
Date Became Current: 20150306
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON CO OF NY INC
Legal Status: Private
Date Became Current: 20150306
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - MANHOLE 48386
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150306
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

CON EDISON (Continued) **1018279648**

Receive Date: 20150306
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067693641

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018279648
Registry ID: 110067693641
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067693641
Name: CON EDISON
Address: 258 42ND ST MH48386
City,State,Zip: BROOKLYN, NY 11232

AA228 **CON EDISON** **RCRA NonGen / NLR** **1018279649**
WNW **258 42ND ST MH48383** **NYP004744892**
1/8-1/4 **BROOKLYN, NY 11232**
0.220 mi.
1160 ft. **Site 7 of 8 in cluster AA**

Relative: **Lower**
Actual: **24 ft.**

RCRA Listings:

Date Form Received by Agency:	20150306
Handler Name:	Con Edison
Handler Address:	42ND ST MH48383
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004744892
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1018279649**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150306
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150306
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AA229 **CON EDISON** **NJ MANIFEST** **S120668455**
WNW **258 42ND ST MH48383** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.220 mi.
1160 ft. **Site 8 of 8 in cluster AA**

Relative:
Lower

Actual:
24 ft.

NJ MANIFEST:

EPA ID:	NYP004744892
Name:	CON EDISON
Address:	258 42ND ST MH48383
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004744892
Manifest Number:	002610990GBF
Date Shipped:	3/6/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

CON EDISON (Continued) **S120668455**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

AI230 **CON EDISON SERVICE BOX: 45070** **RCRA NonGen / NLR** **1016960540**
WSW **4409 3RD AVE** **NY MANIFEST** **NYP004325452**
1/8-1/4 **BROOKLYN, NY 11220**
0.220 mi.
1162 ft. **Site 1 of 3 in cluster AI**

Relative: **Lower**
Actual: **38 ft.**

RCRA Listings:

Date Form Received by Agency:	20130808
Handler Name:	Con Edison Service Box: 45070
Handler Address:	3RD AVE
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NYP004325452
Contact Name:	ANTHONY SIGNORE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-666-4714
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	GENERAL UTILITY WORKER L1-2
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

CON EDISON SERVICE BOX: 45070 (Continued) **1016960540**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130708
Handler Name: CON EDISON SERVICE BOX:	45070
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130808
Handler Name: CON EDISON SERVICE BOX:	45070
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 45070 (Continued) **1016960540**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004325452
Country:	USA
Name:	CON EDISON
Address:	4409 3RD AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11220
Zip 4:	Not reported
Location Address 1:	4409 3 AVENUE
Location Address 2:	SB 45070
Location City,State,Zip:	BROOKLYN, NY 11220
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/08/2013
Trans1 Recv Date:	07/08/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/11/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004325452
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002084324GBF
Import Indicator:	N

CON EDISON SERVICE BOX: 45070 (Continued) **1016960540**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	70
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AD231 **CON EDISON** **NY MANIFEST** **S117065924**
WSW **347 45 ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.221 mi.
1167 ft. **Site 2 of 8 in cluster AD**

Relative:
Higher

Actual:
57 ft.

NY MANIFEST:

EPA ID:	NYP004585253
Country:	USA
Name:	CON EDISON
Address:	347 45 ST
Address 2:	SB 48658
City,State,Zip:	BROOKLYN, NY 11220
Zip 4:	Not reported
Location Address 1:	347 45 ST
Location Address 2:	SB 48658
Location City,State,Zip:	BROOKLYN, NY 11220
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003

CON EDISON (Continued) **S117065924**

Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 07/03/2014
Trans1 Recv Date: 07/03/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/03/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004585253
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002503887GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 40
Units: Gallons (liquids only)
Number of Containers: 1
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 1

AB232 **CON EDISON** **RCRA NonGen / NLR** **1019903457**
SW **45TH ST & 4TH AVE** **FINDS** **NYP004785812**
1/8-1/4 **BROOKLYN, NY 11215** **ECHO**
0.222 mi.
1172 ft. **Site 4 of 14 in cluster AB**

Relative: **Higher**

Actual: **75 ft.**

RCRA Listings:

Date Form Received by Agency:	20150522
Handler Name:	Con Edison
Handler Address:	45TH ST & 4TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYP004785812
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1019903457**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150522
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150522
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1019903457**

FINDS:
Registry ID: 110069663171

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019903457
Registry ID:	110069663171
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069663171
Name:	CON EDISON
Address:	45TH ST & 4TH AVE
City,State,Zip:	BROOKLYN, NY 11215

AI233 **CON EDISON SERVICE BOX: 45077** **RCRA NonGen / NLR** **1016960541**
WSW **4417 3RD AVE** **NY MANIFEST** **NYP004325460**
1/8-1/4 **BROOKLYN, NY 11220**
0.223 mi.
1178 ft. **Site 2 of 3 in cluster AI**

Relative: **Lower**

Actual: **38 ft.**

RCRA Listings:

Date Form Received by Agency:	20130808
Handler Name:	Con Edison Service Box: 45077
Handler Address:	3RD AVE
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NYP004325460
Contact Name:	ANTHONY SIGNORE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-666-4714
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	GENERAL UTILITY WORKER L1-2
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported

CON EDISON SERVICE BOX: 45077 (Continued) **1016960541**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130708
Handler Name: CON EDISON SERVICE BOX:	45077
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130808

CON EDISON SERVICE BOX: 45077 (Continued) **1016960541**

Handler Name: CON EDISON SERVICE BOX: 45077
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004325460
Country: USA
Name: CON EDISON
Address: 4417 3RD AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11220
Zip 4: Not reported
Location Address 1: 4417 3 AVENUE
Location Address 2: SB 45077
Location City,State,Zip: BROOKLYN, NY 11220
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 07/08/2013

CON EDISON SERVICE BOX: 45077 (Continued) **1016960541**

Trans1 Recv Date:	07/08/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/11/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004325460
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002084342GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	60
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AC234 **DELIZZA REALTY INC** **UST FINDER** **1028567301**
ENE **840 5TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11222**
0.224 mi.
1182 ft. **Site 10 of 15 in cluster AC**

Relative:
Higher

Actual:
55 ft.

UST FINDER:

Object ID:	294989
Facility ID:	NY10712
Name:	DELIZZA REALTY INC
Address:	840 5TH AVENUE
City,State,Zip:	BROOKLYN, NY 11222
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0

DELIZZA REALTY INC (Continued) **1028567301**

Population 1500ft:	7686
Private Wells 1500ft:	16
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-74.002155
Y Coord:	40.6531640000001
Latitude:	40.653164
Longitude:	-74.002155

UST FINDER:

Object ID:	1199578
Facility ID:	NY10712
Tank ID:	NY109137
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	1500
Substances:	Not reported
Tank Wall Type:	Not reported

AC235 **NYC DEPT OF EDUCATION - PS 671K SCHOOL** **RCRA-SQG** **1024892262**
ENE **840 5TH AVE** **NYR000238626**
1/8-1/4 **BROOKLYN, NY 11232**
0.224 mi.
1182 ft. **Site 11 of 15 in cluster AC**

Relative: **Higher**
Actual: **55 ft.**

RCRA Listings:

Date Form Received by Agency:	20220512
Handler Name:	Nyc Dept Of Education - Ps 671k School
Handler Address:	5TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYR000238626
Contact Name:	TRENTON BROWN
Contact Address:	THOMSON AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-752-5496
Contact Fax:	718-472-8500
Contact Email:	TBROWN2@NYCSCA.ORG
Contact Title:	DIRECTOR OF OPERATIONS
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Small Quantity Generator

NYC DEPT OF EDUCATION - PS 671K SCHOOL (Continued) **1024892262**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	THOMSON AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Nyc Dept Of Education
Owner Type:	Municipal
Operator Name:	Nyc Dept Of Education
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220512
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

NYC DEPT OF EDUCATION - PS 671K SCHOOL (Continued) **1024892262**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: NYC DEPT PF SCHOOL FACILITIES	
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	30-30 THOMSON AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-472-8501
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	718-472-8501
Owner/Operator Email:	ALEMPERT@NYCSCA.ORG

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYC DEPT OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	20180216
Date Ended Current:	Not reported
Owner/Operator Address:	30-30 THOMSON AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-472-8501
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	718-472-8500
Owner/Operator Email:	ALEMPERT@NYCSCA.ORG

Owner/Operator Indicator:	Owner
Owner/Operator Name: NYC DEPT OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	20180216
Date Ended Current:	Not reported
Owner/Operator Address:	30-30 THOMSON AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-752-5496
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	718-472-8500
Owner/Operator Email:	TBROWN2@NYCSCA.ORG

Owner/Operator Indicator:	Operator
Owner/Operator Name: NYC DEPT OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	20180216
Date Ended Current:	Not reported
Owner/Operator Address:	30-30 THOMSON AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-752-5496
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	718-472-8500
Owner/Operator Email:	TBROWN2@NYCSCA.ORG

Historic Generators:

Receive Date:	20190503
Handler Name:	NYC DEPT OF EDUCATION - PS 671K SCHOOL
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

NYC DEPT OF EDUCATION - PS 671K SCHOOL (Continued) **1024892262**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20220512
Handler Name: NYC DEPT OF EDUCATION - PS 671K SCHOOL
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20181024
Handler Name: NYC DEPT OF EDUCATION - PS 671K
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 611110
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AC236 **NYC DEPT OF EDUCATION - PS 671K** **NY BROWNFIELDS S123159079**
ENE **840 5TH AVE** **NY Spills N/A**
1/8-1/4 **BROOKLYN, NY 11232** **NY MANIFEST**
0.224 mi.
1182 ft. **Site 12 of 15 in cluster AC**

Relative: BROWNFIELDS:
Higher
Name: 840 5TH AVENUE
Actual: Address: 840 5TH AVENUE
55 ft. City,State,Zip: BROOKLYN, NY 11232
Program: BCP
Site Code: 567010

NYC DEPT OF EDUCATION - PS 671K (Continued) **S123159079**

Acres:	0.450
HW Code:	C224271
SWIS:	2401
Town:	New York City
Record Added Date:	02/21/2018
Record Updated Date:	07/24/2023
Update By:	SMQUANDT
Site Description:	Location: The site is located in Sunset Park, a mixed-use urban area of Brooklyn, New York, which includes residential, commercial, and industrial areas. The site consists of one lot (Lot 39) totaling approximately 19,605 square feet (sf). Site Features: The site is bounded to the north and northwest by Greenwood Cemetery maintenance facility; to the east and northeast by 5th Avenue followed by Greenwood Cemetery; to the south and southeast by 5th Avenue followed by the MTAs Jackie Gleason Bus Depot; to the south and southwest by 36th Street followed by a gasoline station, car wash and commercial offices; and to the west by a three-story residential building with a first floor church occupant. Surrounding property uses are commercial, residential, and institutional. Current Zoning and Land Use: According to the New York City Department of City Planning (NYCDCP) Zoning Map 16B, the site is zoned for manufacturing use (M1-2) and is improved with a two-story building. The site is currently vacant. Use of the Site as a community facility (i.e., a school facility) is permitted by a special permit in M1 districts. NYCSCA is seeking and anticipates issuance of a special permit for the proposed use of the Site as a public school facility. Past Use of the Site: The eastern portion of the site was first known to be developed in 1903 with elevated train tracks and an elevated train car repair shop. By 1926, the train car repair shop was demolished and the lot was vacant with the exception of the elevated train tracks (on a platform). The current site building was constructed in approximately 1953, and used for manufacturing purposes including jewelry fabrication. By 1997, the second floor was utilized as a garment assembly facility and by 1998, the first floor was used as a nightclub. Since at least 2004 through 2017, the building has been used as a church. The paved area is fenced-in and was used for automobile sales and automobile parts scrapping operations until the New York City School Construction Authority (NYCSCA) purchased the property. The western portion of the site was developed with a four-story residential building from at least 1903 until 1951, when it was razed. Since approximately 1999 to 2017, a trailer has been present on the western portion of the lot and the unpaved area has been utilized for storage of automobiles. The site is listed in the Department s Petroleum Bulk Storage (PBS) tank database for one 1,500 gallon underground storage tank with a status of closed prior to 03/1991 . The PBS records indicate the tank is vaulted with no access for inspection. Site Geology and Hydrogeology: Geological data obtained as part of the Remedial Investigation (RI) and from previous reports indicates the principal geological units, from top to bottom, are: 1) fill material consisting of reddish brown sand, silt, gravel, and miscellaneous debris (i.e., metal, glass, asphalt, slag, coal ash/ash, concrete, red brick, and wood) from the ground surface to depths ranging from 11.5 feet below ground surface (bgs) to 48 feet bgs and 2) reddish brown, dark brown, and light brown fine to medium sand, silt, and fine gravel beneath the fill to the terminal depths of the borings, which ranged up to 70 feet bgs. Bedrock is expected to be at greater than 200 feet bgs. Based on the two rounds of

NYC DEPT OF EDUCATION - PS 671K (Continued) **S123159079**

groundwater surface elevation measurements, the depth to groundwater ranges from 46 feet bgs to 53 feet bgs and the predominant direction of groundwater flow in the eastern portion of the site is towards the northeast. A site location map is attached as Figure 1.

Env Problem:

Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were semi-volatile organic compounds (SVOCs) and metals in soil, volatile organic compounds (VOCs), SVOCs, and metals (in filtered samples) in groundwater; and, chlorinated VOCs in sub slab vapor/soil vapor. Remedial actions have successfully achieved soil cleanup objectives for Restricted Residential use. Residual contamination in the soil, groundwater is being managed under a Site Management Plan. Prior to Completion of Remediation: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Soil: The primary contaminants found in subsurface soils are polycyclic aromatic hydrocarbons (PAHs) and metals typically found in historic fill, which is generally present in the top 12 feet of the site. Eleven PAHs were detected in soils down to 12 feet below ground surface (bgs) during the RI, included but not limited to, anthracene at 150 parts per million (ppm) (restricted residential soil cleanup objective (RRSCO) is 100 ppm), benzo(a)anthracene at 200 ppm (RRSCO is 1 ppm), benzo(a)pyrene at 180 ppm (RRSCO is 1 ppm), benzo(b)fluoranthene at 210 ppm (RRSCO is 1 ppm), benzo (k) fluoranthene at 85 ppm (RRSCO is 3.9 ppm), chrysene at 190 ppm (RRSCO is 3.9 ppm), dibenzo(a,h)anthracene at 98 ppm (RRSCO is 0.33 ppm), fluoranthene at 490 ppm (RRSCO is 100 ppm), indeno(1,2,3-cd)pyrene at 98 ppm (RRSCO is 0.5 ppm), phenanthrene at 560 ppm (RRSCO is 100 ppm) and pyrene at 590 ppm (RRSCO is 100 ppm). Metals, including arsenic, copper, lead and mercury were found in site soils down to 12 feet bgs. Arsenic at 21 ppm (RRSCO is 16 ppm), copper at 1,300 ppm (RRSCO is 270 ppm), lead at 1,200 ppm (RRSCO is 400 ppm) and mercury at 1.5 ppm (RRSCO is 0.81 ppm). Two soil samples collected from the northeast portion of the site were characterized as hazardous waste for lead, exceeding the regulatory limit of 5 milligrams per liter (mg/L). It is currently unknown if the elevated lead in soil extends off-site. There were no VOCs, PCBs, pesticides or herbicides detected at concentrations exceeding the RRSCOs. Three surface soil samples collected from the northern portion of the site contained PAHs and metals slightly above their respective RRSCOs. Groundwater: Six VOCs were detected in groundwater including 1,1,1-trichloroethane (TCA) at 7.9 parts per billion (ppb), (class GA standard of 5 ppb), chloroform at 25.9 ppb (class GA standard of 7 ppb), cis-1,2-DCE at 7.9 ppb (class GA standard of 5 ppb), MTBE at 2,200 ppb (class GA standard of 10 ppb), toluene at 9.1 ppb (class GA standard of 5 ppb) and formaldehyde at 2,700 ppb (class GA standard of 8 ppb). Three SVOCs were detected above standards as follows: benzo(a)anthracene at 3.7 ppb (class GA standard 0.002), bis(2-ehylhexyl)phthalate at 10 ppb (class GA standard 5 ppb) and chrysene at 3.4 ppb (class GA standard 0.002 ppb). No PCBs or metals of concern were detected in groundwater over standards. Soil Vapor: Several VOCs, including petroleum-related and chlorinated, were detected in soil vapor. Chlorinated VOC detections included TCA at 6,200 micrograms per cubic meter (ug/m^3), 1,1-dichloroethene at 28 ug/m^3 and vinyl chloride at 400 ug/m^3. Petroleum-related VOC detections included benzene at 4,000 ug/m^3, ethylbenzene at 500 ug/m^3, p/m-xylene at 330 ug/m^3, o-xylene at 370 ug/m^3 and toluene at 2,700 ug/m^3. The VOCs detected in soil vapor

NYC DEPT OF EDUCATION - PS 671K (Continued) **S123159079**

	are likely site-related from historical site activities or from the historic fill present beneath the site. Based on these results, more information is necessary to assess the potential for off-site soil vapor intrusion. Off-site soil vapor intrusion sampling will be performed during this coming heating season.
Health Problem:	Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2018-07-13 11:43:00
Record Upd:	2022-08-24 14:08:00
Updated By:	MDSOLLEC
Own Op:	1
Sub Type:	P03
Owner Name:	Saritha Thumma
Owner Company:	New York City Department of Education
Owner Address:	44-36 Vernon Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Lee Guterman
Owner Company:	New York City School Construction Authority
Owner Address:	30-30 Thomson Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Sunset Libary branch
Owner Address:	5108 4th Ave.
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11220
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Daniel Murphy
Owner Company:	Brooklyn Community Board 7
Owner Address:	4201 4th Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11232
Owner Country:	United States of America
HW Code:	C224271
Waste Type:	pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271

NYC DEPT OF EDUCATION - PS 671K (Continued) **S123159079**

Waste Type:	1,1,1-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	phenanthrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	chloroform
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	methyl-tert-butyl ether (MTBE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	benzo[k]fluoranthene

NYC DEPT OF EDUCATION - PS 671K (Continued) **S123159079**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	formaldehyde
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	1,1-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	1,1,1-Trichloroethane(TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224271
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C224271-05-18
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2022-08-25 15:00:00
Record Updated:	2022-08-25 15:00:00
Updated By:	AMSERVIS
Crossref ID:	2022000381450
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2022-10-18 09:48:00
Record Updated:	2022-10-18 09:48:00
Updated By:	MDSOLLEC

SPILLS:

Name:	CONTRUCTION SITE
Address:	840 5TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2204057 / 2022-11-21
Facility ID:	2204057

NYC DEPT OF EDUCATION - PS 671K (Continued) **S123159079**

Facility Type:	ER
DER Facility ID:	586702
Site ID:	640183
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2022-08-04
Investigator:	MDSOLLEC
Referred To:	Not reported
Reported to Dept:	2022-08-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2022-08-08
Spill Record Last Update:	2023-03-07
Spiller Name:	PHIL
Spiller Company:	TRC ENGINEER
Spiller Address:	840 5TH AVE
Spiller Company:	999
Contact Name:	PHIL
DEC Memo:	Clean up completed.
Remarks:	8/8/22-Lin-Spill from hydraulic line due to a boom truck accident. Spill onto gravel only. The impacted gravels were removed and place into five (5) drums for disposal. The site owner is the school construction authority and this is a BCP site. DEC BCP project manager: Michael Sollecito TRC Engineers: pcastellano@trccompanies.com 8/8/22-Zhune- Spill transferred to Michael Sollecito project manager of the Brownfields program

All Materials:

Site ID:	640183
Operable Unit ID:	1387237
Operable Unit:	01
Material ID:	2402134
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

NY MANIFEST:

EPA ID:	NYR000238626
Country:	USA
Name:	NYC DEPT OF EDUCATION - PS 671K

NYC DEPT OF EDUCATION - PS 671K (Continued) **S123159079**

Address:	840 5TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	840 5TH AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	NYC DEPT OF EDUCATION - PS 671K
Mailing Contact:	NYC DEPT OF EDUCATION - PS 671K
Mailing Address 1:	840 5TH AVE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11232
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AC237 **PS 671** **NY UST** **U000400181**
ENE **840 5TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.224 mi.
1182 ft. **Site 13 of 15 in cluster AC**

Relative:
Higher

Actual:
55 ft.

UST:

Name:	PS 671
Address:	840 5TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Id/Status:	2-258520 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	584359.32846
UTM Y:	4500734.71228
Site Type:	Other

Affiliation Records:

Site Id:	10712
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY SCHOOL CONSTRUCTION AUTHORITY
Contact Type:	Not reported
Contact Name:	PETER LEVI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 939-1980
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-10-02

PS 671 (Continued) **U000400181**

Site Id:	10712
Affiliation Type:	Facility Operator
Company Name:	PS 671
Contact Type:	Not reported
Contact Name:	NEW YORK CITY SCHOOL CONSTRUCTION AUTH.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 472-8000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-10-02

Site Id:	10712
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY SCHOOL CONSTRUCTION AUTHORITY
Contact Type:	SENIOR DIRECTOR, IEH DIVISION
Contact Name:	ALEXANDER LEMPERT
Address1:	30-30 THOMSON AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 472-8000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-10-02

Site Id:	10712
Affiliation Type:	Mail Contact
Company Name:	NYC SCHOOL CONSTRUCTION AUTHORITY
Contact Type:	Not reported
Contact Name:	ALEXANDER LEMPERT
Address1:	30-30 THOMSON AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 472-8000
EMail:	ALEMPERT@NYCSCA.ORG
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-10-02

Tank Info:

Tank Number:	001
Tank ID:	40493
Tank Status:	Closed - Removed
Material Name:	Closed - Removed

PS 671 (Continued) **U000400181**

Capacity Gallons:	1500
Install Date:	09/02/2018
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None

X238 **LOUIS BRESSOUD INC** **RCRA NonGen / NLR** **1004761964**
West **270 43RD ST** **FINDS** **NYR000092171**
1/8-1/4 **BROOKLYN, NY 11232** **ECHO**
0.226 mi.
1192 ft. **Site 5 of 5 in cluster X**

Relative:
Lower

Actual:
28 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Louis Bressoud Inc
Handler Address:	43RD ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYR000092171
Contact Name:	PHILIP PRESTINO
Contact Address:	43RD ST
Contact City,State,Zip:	BROOKLYN, NY 11232
Contact Telephone:	718-499-2323
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2

LOUIS BRESSOUD INC (Continued) **1004761964**

Mailing Address:	43RD ST
Mailing City,State,Zip:	BROOKLYN, NY 11232
Owner Name:	Joseph Prestino
Owner Type:	Private
Operator Name:	Joseph Prestino
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing

LOUIS BRESSOUD INC (Continued) **1004761964**

Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: JOSEPH PRESTINO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	270 43RD ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11232
Owner/Operator Telephone:	718-499-2323
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JOSEPH PRESTINO	
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	270 43RD ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11232
Owner/Operator Telephone:	718-499-2323
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: JOSEPH PRESTINO	
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	270 43RD ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11232
Owner/Operator Telephone:	718-499-2323
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: LOUIS BRESSOUD INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

LOUIS BRESSOUD INC (Continued) **1004761964**

Receive Date:	20070101
Handler Name: LOUIS BRESSOUD INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20001212
Handler Name: LOUIS BRESSOUD INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004566121

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

LOUIS BRESSOUD INC (Continued) **1004761964**

ECHO:
- Envid: 1004761964
- Registry ID: 110004566121
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004566121
- Name: LOUIS BRESSOUD INC
- Address: 270 43RD ST
- City,State,Zip: BROOKLYN, NY 11232

AD239 **CON EDISON** **NJ MANIFEST** **S120667595**
WSW **337 45TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.226 mi.
1195 ft. **Site 3 of 8 in cluster AD**

Relative:
Higher

Actual:
53 ft.

NJ MANIFEST:
- EPA ID: NYP004735239
- Name: CON EDISON
- Address: 337 45TH ST
- City,State,Zip: BROOKLYN, NY 11220
- County: Not reported
- Mailing Address: IRVING PL, 15TH FL NE
- Mailing City,State,Zip: NEW YORK, NY 10003
- Telephone: Not reported
- Emergency Telephone: Not reported
- Contact: THOMAS TEELING
- Comments: Not reported
- SIC Code: Not reported
- County: NY047
- Municipal: Not reported
- Previous EPAID: Not reported
- Generator Flag: Not reported
- Transporter Flag: Not reported
- TSDF Flag: Not reported
- Name Change: Not reported
- Date Change: Not reported

Manifest Data:
- EPA ID: NYP004735239
- Manifest Number: 002620980GBF
- Date Shipped: 2/22/2015
- TSDF EPA ID: NJD991291105
- Transporter EPA ID: NJD003812047
- Transporter 2 EPA ID: Not reported
- Transporter 3 EPA ID: Not reported
- Transporter 4 EPA ID: Not reported
- Transporter 5 EPA ID: Not reported
- Transporter 6 EPA ID: Not reported
- Transporter 7 EPA ID: Not reported
- Transporter 8 EPA ID: Not reported
- Transporter 9 EPA ID: Not reported
- Transporter 10 EPA ID: Not reported
- Date Trans1 Transported Waste: Not reported
- Date Trans2 Transported Waste: Not reported
- Date Trans3 Transported Waste: Not reported
- Date Trans4 Transported Waste: Not reported
- Date Trans5 Transported Waste: Not reported
- Date Trans6 Transported Waste: Not reported
- Date Trans7 Transported Waste: Not reported

CON EDISON (Continued) **S120667595**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

AD240 **CON EDISON** **NY MANIFEST** **S117740359**
WSW **337 45TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.226 mi.
1195 ft. **Site 4 of 8 in cluster AD**

Relative:
Higher

Actual:
53 ft.

NY MANIFEST:

EPA ID:	NYP004735239
Country:	USA
Name:	CON EDISON
Address:	337 45TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11220
Zip 4:	Not reported
Location Address 1:	337 45TH ST
Location Address 2:	STRUCTURE 48656
Location City,State,Zip:	BROOKLYN, NY 11220
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018

CON EDISON (Continued) **S117740359**

Trans2 State ID:	NJD003812047
Generator Ship Date:	02/22/2015
Trans1 Recv Date:	02/22/2015
Trans2 Recv Date:	03/03/2015
TSD Site Recv Date:	03/03/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004735239
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620980GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AD241 **CON EDISON** **RCRA NonGen / NLR** **1018278742**
WSW **337 45TH ST** **FINDS** **NYP004735239**
1/8-1/4 **BROOKLYN, NY 11220** **ECHO**
0.226 mi.
1195 ft. **Site 5 of 8 in cluster AD**

Relative: **Higher**
Actual: **53 ft.**

RCRA Listings:

Date Form Received by Agency:	20150222
Handler Name:	Con Edison
Handler Address:	45TH ST
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NYP004735239
Contact Name:	THOMAS TEELING
Contact Address:	Not reported

CON EDISON (Continued) **1018278742**

Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

CON EDISON (Continued) **1018278742**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20150222
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150222
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067680744

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

CON EDISON (Continued) **1018278742**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018278742
Registry ID:	110067680744
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067680744
Name:	CON EDISON
Address:	337 45TH ST
City,State,Zip:	BROOKLYN, NY 11220

AH242 **BAYRIDGE FRENCH CLEANERS** **RCRA-VSQG** **1000890387**
South **4414 5TH AVENUE** **ICIS** **NY0000359703**
1/8-1/4 **BROOKLYN, NY 11220** **US AIRS**
0.227 mi. **FINDS**
1197 ft. **Site 3 of 3 in cluster AH** **ECHO**
NY DRYCLEANERS
Relative: Higher **NY MANIFEST**

Actual: 113 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Bay Ridge French Cleaners
Handler Address:	5TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NY0000359703
Contact Name:	ARMANDO ALVAREZ
Contact Address:	5TH AVE
Contact City,State,Zip:	BROOKLYN, NY 11220
Contact Telephone:	718-438-4406
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	5TH AVE
Mailing City,State,Zip:	BROOKLYN, NY 11220
Owner Name:	Bay Ridge French Cleaners
Owner Type:	Private
Operator Name:	Bay Ridge French Cleaners
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BAY RIDGE FRENCH CLEANERS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	4414 5TH AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11220
Owner/Operator Telephone:	718-438-4406
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Owner/Operator Indicator: Owner
Owner/Operator Name: BAY RIDGE FRENCH CLEANERS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4414 5TH AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11220
Owner/Operator Telephone: 718-438-4406
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: BAY RIDGE FRENCH CLEANERS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4414 5TH AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11220
Owner/Operator Telephone: 718-438-4406
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: BAY RIDGE FRENCH CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: BAY RIDGE FRENCH CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940608
Handler Name: BAY RIDGE FRENCH CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ICIS:
Enforcement Action ID: NY000A0000261020038000314
FRS ID: 110004316026
Action Name: BAYRIDGE FRENCH CLEANERS 36047R271100314
Facility Name: BAYRIDGE FRENCH CLEANERS
Facility Address: 4414 5TH AVE
BROOKLYN, NY 112201204
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.64814
Longitude in Decimal Degrees: -74.00715
Permit Type Desc: Not reported
Program System Acronym: NY0000002610200380
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261020038000307
FRS ID: 110004316026
Action Name: BAYRIDGE FRENCH CLEANERS 36047R271100307
Facility Name: BAYRIDGE FRENCH CLEANERS
Facility Address: 4414 5TH AVE
BROOKLYN, NY 112201204
Enforcement Action Type: Administrative Order
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.64814
Longitude in Decimal Degrees: -74.00715
Permit Type Desc: Not reported
Program System Acronym: NY0000002610200380

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261020038000304
FRS ID: 110004316026
Action Name: BAYRIDGE FRENCH CLEANERS 36047R271100304
Facility Name: BAYRIDGE FRENCH CLEANERS
Facility Address: 4414 5TH AVE
BROOKLYN, NY 112201204
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.64814
Longitude in Decimal Degrees: -74.00715
Permit Type Desc: Not reported
Program System Acronym: NY0000002610200380
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261020038000301
FRS ID: 110004316026
Action Name: BAYRIDGE FRENCH CLEANERS 36047R271100301
Facility Name: BAYRIDGE FRENCH CLEANERS
Facility Address: 4414 5TH AVE
BROOKLYN, NY 112201204
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.64814
Longitude in Decimal Degrees: -74.00715
Permit Type Desc: Not reported
Program System Acronym: NY0000002610200380
Facility NAICS Code: 812320
Tribal Land Code: Not reported

US AIRS MINOR:
Envid: 1000890387
Region Code: 02
Programmatic ID: AIR NY0000002610200380
Facility Registry ID: 110004316026
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000002610200380
Facility Registry ID:	110004316026
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2001-12-16 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000002610200380
Facility Registry ID:	110004316026
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2002-12-04 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000002610200380
Facility Registry ID:	110004316026
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2003-05-27 00:00:00
Activity Status Date:	2003-05-27 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Formal
Activity Status:	Final Order Issued

Region Code:	02
Programmatic ID:	AIR NY0000002610200380
Facility Registry ID:	110004316026
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2003-03-11 00:00:00
Activity Status Date:	2003-03-11 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

Region Code:	02
Programmatic ID:	AIR NY0000002610200380
Facility Registry ID:	110004316026
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2005-04-13 00:00:00
Activity Status Date:	2005-04-13 00:00:00

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610200380
Facility Registry ID: 110004316026
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-12-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610200380
Facility Registry ID: 110004316026
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-12-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610200380
Facility Registry ID: 110004316026
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-05-27 00:00:00
Activity Status Date: 2003-05-27 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 02
Programmatic ID: AIR NY0000002610200380
Facility Registry ID: 110004316026
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-03-11 00:00:00
Activity Status Date: 2003-03-11 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

FINDS:
Registry ID: 110004316026

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000890387
Registry ID:	110004316026
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004316026
Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVENUE
City,State,Zip:	BROOKLYN, NY 11220

DRYCLEANERS:

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	05/28/2003
Inspection Date:	12/12/2019
Install Date:	Not reported
Expiration Date:	01/17/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	01/25/2008

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Inspection Date:	12/16/2001
Install Date:	Not reported
Expiration Date:	09/23/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	01/25/2008
Inspection Date:	12/04/2002
Install Date:	Not reported
Expiration Date:	09/23/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	01/25/2008
Inspection Date:	12/09/2003
Install Date:	Not reported
Expiration Date:	09/23/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	01/25/2008
Inspection Date:	12/07/2004
Install Date:	Not reported
Expiration Date:	09/23/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	01/25/2008
Inspection Date:	12/08/2005
Install Date:	Not reported
Expiration Date:	09/23/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	01/25/2008
Inspection Date:	12/14/2006
Install Date:	Not reported
Expiration Date:	09/23/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	01/25/2008
Inspection Date:	12/17/2007
Install Date:	Not reported
Expiration Date:	09/23/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	01/25/2008
Inspection Date:	12/15/2008
Install Date:	Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Expiration Date:	09/23/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	01/25/2008
Inspection Date:	12/17/2009
Install Date:	Not reported
Expiration Date:	09/23/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	01/25/2008
Inspection Date:	12/22/2010
Install Date:	Not reported
Expiration Date:	09/23/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	01/25/2008
Inspection Date:	12/20/2012
Install Date:	Not reported
Expiration Date:	09/23/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 01/25/2008
Inspection Date: 12/21/2011
Install Date: Not reported
Expiration Date: 09/23/2021
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 01/25/2008
Inspection Date: 12/26/2013
Install Date: Not reported
Expiration Date: 09/23/2021
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 01/25/2008
Inspection Date: 12/18/2014
Install Date: Not reported
Expiration Date: 09/23/2021
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 01/25/2008
Inspection Date: 12/17/2015
Install Date: Not reported
Expiration Date: 09/23/2021
Removal Date: Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 01/25/2008
Inspection Date: 12/13/2016
Install Date: Not reported
Expiration Date: 09/23/2021
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 01/25/2008
Inspection Date: 12/13/2018
Install Date: Not reported
Expiration Date: 09/23/2021
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 01/25/2008
Inspection Date: 12/13/2017
Install Date: Not reported
Expiration Date: 09/23/2021
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	01/25/2008
Inspection Date:	12/12/2019
Install Date:	Not reported
Expiration Date:	09/23/2021
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	05/28/2003
Inspection Date:	12/16/2001
Install Date:	Not reported
Expiration Date:	01/17/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	05/28/2003
Inspection Date:	12/04/2002
Install Date:	Not reported
Expiration Date:	01/17/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	05/28/2003
Inspection Date:	12/09/2003
Install Date:	Not reported
Expiration Date:	01/17/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 05/28/2003
Inspection Date: 12/07/2004
Install Date: Not reported
Expiration Date: 01/17/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 05/28/2003
Inspection Date: 12/08/2005
Install Date: Not reported
Expiration Date: 01/17/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 05/28/2003
Inspection Date: 12/14/2006
Install Date: Not reported
Expiration Date: 01/17/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Registration Effective Date: 05/28/2003
Inspection Date: 12/17/2007
Install Date: Not reported
Expiration Date: 01/17/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 05/28/2003
Inspection Date: 12/15/2008
Install Date: Not reported
Expiration Date: 01/17/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 05/28/2003
Inspection Date: 12/17/2009
Install Date: Not reported
Expiration Date: 01/17/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 05/28/2003
Inspection Date: 12/22/2010
Install Date: Not reported
Expiration Date: 01/17/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	05/28/2003
Inspection Date:	12/20/2012
Install Date:	Not reported
Expiration Date:	01/17/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	05/28/2003
Inspection Date:	12/21/2011
Install Date:	Not reported
Expiration Date:	01/17/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	05/28/2003
Inspection Date:	12/26/2013
Install Date:	Not reported
Expiration Date:	01/17/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

Name:	BAYRIDGE FRENCH CLEANERS
Address:	4414 5TH AVE
City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	05/28/2003
Inspection Date:	12/18/2014
Install Date:	Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Expiration Date: 01/17/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 05/28/2003
Inspection Date: 12/17/2015
Install Date: Not reported
Expiration Date: 01/17/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 05/28/2003
Inspection Date: 12/13/2016
Install Date: Not reported
Expiration Date: 01/17/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE
City,State,Zip: BROOKLYN, NY 11220 1204
Facility ID: 2-6102-00380
Phone Number: 7184384406
Region: Not reported
Registration Effective Date: 05/28/2003
Inspection Date: 12/13/2018
Install Date: Not reported
Expiration Date: 01/17/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: (null)
Current Business: Not reported

Name: BAYRIDGE FRENCH CLEANERS
Address: 4414 5TH AVE

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

City,State,Zip:	BROOKLYN, NY 11220 1204
Facility ID:	2-6102-00380
Phone Number:	7184384406
Region:	Not reported
Registration Effective Date:	05/28/2003
Inspection Date:	12/13/2017
Install Date:	Not reported
Expiration Date:	01/17/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	(null)
Current Business:	Not reported

NY MANIFEST:

EPA ID:	NY0000359703
Country:	USA
Name:	BAY RIDGE FRENCH CLNRS
Address:	4414 5TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11220
Zip 4:	Not reported
Location Address 1:	4414 5TH AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11220
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	BAY RIDGE FRENCH CLNRS
Mailing Contact:	ALESANDRO ESTRELLA
Mailing Address 1:	4414 5TH AVE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11220
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184384406

Manifest Data:

Document ID:	NYC7132724
Manifest Status:	Not reported
Trans1 State ID:	NYAT8305
Year:	2003
Trans2 State ID:	CAFT97544
Generator Ship Date:	05/22/2003
Trans1 Recv Date:	05/22/2003
Trans2 Recv Date:	05/29/2003
TSD Site Recv Date:	06/02/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000359703
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	MOR000505347
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00133
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00195
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC5619205
Manifest Status:	Not reported
Trans1 State ID:	NYGF2859
Year:	1999
Trans2 State ID:	NJT486J2

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Generator Ship Date:	04/30/1999
Trans1 Recv Date:	04/30/1999
Trans2 Recv Date:	05/04/1999
TSD Site Recv Date:	05/07/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000359703
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00195
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC7210620
Manifest Status:	Not reported
Trans1 State ID:	NYAT8011
Year:	2004
Trans2 State ID:	T39K7HNJ
Generator Ship Date:	05/26/2004
Trans1 Recv Date:	05/26/2004
Trans2 Recv Date:	05/28/2004
TSD Site Recv Date:	06/01/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000359703
Trans1 EPA ID:	TXR000050930

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Trans2 EPA ID:	NJD071629976
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00133
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC5751696
Manifest Status:	Not reported
Trans1 State ID:	NYGF2859
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	04/26/2001
Trans1 Recv Date:	04/26/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/03/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000359703
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00195
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC5756736
Manifest Status:	Not reported
Trans1 State ID:	NYGF2859
Year:	2001
Trans2 State ID:	T162VWNJ
Generator Ship Date:	01/25/2001
Trans1 Recv Date:	01/25/2001
Trans2 Recv Date:	01/30/2001
TSD Site Recv Date:	02/02/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000359703
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE,

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00195
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC7552798
Manifest Status:	Not reported
Trans1 State ID:	NYCAP6277
Year:	2005
Trans2 State ID:	T471GLNJ
Generator Ship Date:	01/13/2005
Trans1 Recv Date:	01/13/2005
Trans2 Recv Date:	01/21/2005
TSD Site Recv Date:	01/24/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000359703
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00195
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00133
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC6981287
Manifest Status:	Not reported
Trans1 State ID:	NYAT8305
Year:	2003
Trans2 State ID:	T473GLNJ
Generator Ship Date:	03/11/2003
Trans1 Recv Date:	03/11/2003
Trans2 Recv Date:	03/14/2003
TSD Site Recv Date:	03/17/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000359703
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00133
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC6588696
Manifest Status:	Not reported
Trans1 State ID:	NYAT8605
Year:	2002
Trans2 State ID:	NJT24280
Generator Ship Date:	11/18/2002
Trans1 Recv Date:	11/18/2002
Trans2 Recv Date:	11/22/2002
TSD Site Recv Date:	11/25/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000359703
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00195
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00133
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC7005598
Manifest Status:	Not reported
Trans1 State ID:	NYAT8305
Year:	2003
Trans2 State ID:	MO013
Generator Ship Date:	08/13/2003
Trans1 Recv Date:	08/13/2003
Trans2 Recv Date:	08/18/2003
TSD Site Recv Date:	08/19/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000359703
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	MOR000505347
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00133
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC6713954
Manifest Status:	Not reported
Trans1 State ID:	NYCAT8305
Year:	2002
Trans2 State ID:	0172
Generator Ship Date:	05/09/2002
Trans1 Recv Date:	05/09/2002
Trans2 Recv Date:	05/17/2002
TSD Site Recv Date:	05/17/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000359703
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE,

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00133
Units: Pounds
Number of Containers: 001
Container Type: Fiberboard or plastic drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYC3298048
Manifest Status: Not reported
Trans1 State ID: DF2859NY
Year: 1994
Trans2 State ID: Not reported
Generator Ship Date: 10/20/1994
Trans1 Recv Date: 10/20/1994
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/20/1994
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NY0000359703
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980785760
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2: Not reported
Waste Code 3: Not reported

BAYRIDGE FRENCH CLEANERS (Continued) **1000890387**

Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00120
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
31 additional NY MANIFEST: record(s) in the EDR Site Report.

AB243 **CON EDISON** **RCRA NonGen / NLR** **1019901528**
SW **4511 4TH AVE SB45506** **NYP004762985**
1/8-1/4 **BROOKLYN, NY 11220**
0.227 mi.
1198 ft. **Site 5 of 14 in cluster AB**

Relative: **Higher**
Actual: **77 ft.**

RCRA Listings:

Date Form Received by Agency:	20150403
Handler Name:	Con Edison
Handler Address:	4TH AVE SB45506
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NYP004762985
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

CON EDISON (Continued) **1019901528**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150403
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150403
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1019901528**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AB244 **CON EDISON** **NJ MANIFEST** **S120670047**
SW **4511 4TH AVE SB45506** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.227 mi.
1198 ft. **Site 6 of 14 in cluster AB**

Relative:
Higher

Actual:
77 ft.

NJ MANIFEST:

EPA ID:	NYP004762985
Name:	CON EDISON
Address:	4511 4TH AVE SB45506
City,State,Zip:	BROOKLYN, NY 11220
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004762985
Manifest Number:	014091199JJK
Date Shipped:	4/3/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported

CON EDISON (Continued) **S120670047**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

AB245 **CON EDISON** **NJ MANIFEST** **S120670048**
SW **4511 4 AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.227 mi.
1198 ft. **Site 7 of 14 in cluster AB**

Relative:
Higher

Actual:
77 ft.

NJ MANIFEST:

EPA ID:	NYP004762993
Name:	CON EDISON
Address:	4511 4 AVE
City,State,Zip:	BROOKLYN, NY 11220
County:	Not reported
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004762993
Manifest Number:	014091200JJK
Date Shipped:	4/3/2015

CON EDISON (Continued) **S120670048**

TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

AB246 **CON EDISON** **NY MANIFEST** **S119074155**
SW **4511 4TH AVE SB45506** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.227 mi.
1198 ft. **Site 8 of 14 in cluster AB**

Relative: **Higher**

Actual: **77 ft.**

NY MANIFEST:

EPA ID:	NYP004762985
Country:	USA
Name:	CON EDISON
Address:	4511 4TH AVE SB45506
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11220
Zip 4:	Not reported
Location Address 1:	4511 4TH AVE
Location Address 2:	SB 45506
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported

CON EDISON (Continued) **S119074155**

Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 04/03/2015
Trans1 Recv Date: 04/03/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/08/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004762985
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014091199JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 1500
Units: Pounds
Number of Containers: 1

CON EDISON (Continued) **S119074155**

Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AB247 **CON EDISON** **NY MANIFEST** **S119074157**
SW **4511 4TH AVE MH5826** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.227 mi.
1198 ft. **Site 9 of 14 in cluster AB**

Relative:
Higher

Actual:
77 ft.

NY MANIFEST:

EPA ID:	NYP004763009
Country:	USA
Name:	CON EDISON
Address:	4511 4TH AVE MH5826
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11220
Zip 4:	Not reported
Location Address 1:	4601 4TH AVE
Location Address 2:	MH 5826
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	04/03/2015
Trans1 Recv Date:	04/03/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/08/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004763009
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091201JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N

CON EDISON (Continued) **S119074157**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	2000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AB248 **CON EDISON** **RCRA NonGen / NLR** **1019324799**
SW **4511 4TH AVE MH5827** **NYP004762993**
1/8-1/4 **BROOKLYN, NY 11220**
0.227 mi.
1198 ft. **Site 10 of 14 in cluster AB**

Relative: **Higher**
Actual: **77 ft.**

RCRA Listings:

Date Form Received by Agency:	20150403
Handler Name:	Con Edison
Handler Address:	4TH AVE MH5827
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NYP004762993
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003

CON EDISON (Continued) **1019324799**

Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner

CON EDISON (Continued) **1019324799**

Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150403
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150403
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - MANHOLE 5827
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150403
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150403
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

CON EDISON (Continued) **1019324799**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AB249 **CON EDISON** **NY MANIFEST** **S119074156**
SW **4511 4TH AVE MH5827** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.227 mi.
1198 ft. **Site 11 of 14 in cluster AB**

Relative:
Higher

Actual:
77 ft.

NY MANIFEST:
EPA ID: NYP004762993
Country: USA
Name: CON EDISON
Address: 4511 4TH AVE MH5827
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11220
Zip 4: Not reported
Location Address 1: 4511 4 AVE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11220
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 04/03/2015

CON EDISON (Continued) **S119074156**

Trans1 Recv Date:	04/03/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/08/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004762993
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091200JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	5000
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AB250 **CON EDISON** **NJ MANIFEST** **S120670049**
SW **4511 4TH AVE MH5826** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.227 mi.
1198 ft. **Site 12 of 14 in cluster AB**

Relative: **Higher**
Actual: **77 ft.**

NJ MANIFEST:

EPA ID:	NYP004763009
Name:	CON EDISON
Address:	4511 4TH AVE MH5826
City,State,Zip:	BROOKLYN, NY 11220
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported

CON EDISON (Continued) **S120670049**

Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004763009
Manifest Number:	014091201JJK
Date Shipped:	4/3/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

AB251 **CON EDISON** **RCRA NonGen / NLR** **1019901529**
SW **4511 4TH AVE MH5826** **NYP004763009**
1/8-1/4 **BROOKLYN, NY 11220**
0.227 mi.
1198 ft. **Site 13 of 14 in cluster AB**

Relative: **Higher**

Actual: **77 ft.**

RCRA Listings:

Date Form Received by Agency:	20150403
Handler Name:	Con Edison
Handler Address:	4TH AVE MH5826
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NYP004763009
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1019901529**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150403
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150403
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AE252 **CON EDISON SERVICE BOX: 49080** **RCRA NonGen / NLR** **1016965010**
NNE **337 36TH ST** **NY MANIFEST** **NYP004379061**
1/8-1/4 **BROOKLYN, NY 11232**
0.227 mi.
1199 ft. **Site 5 of 6 in cluster AE**

Relative: **Lower**
Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	20131123
Handler Name:	Con Edison Service Box: 49080
Handler Address:	36TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004379061
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 49080 (Continued) **1016965010**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131023
Handler Name: CON EDISON SERVICE BOX:	49080
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131123
Handler Name: CON EDISON SERVICE BOX:	49080
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 49080 (Continued) **1016965010**

NY MANIFEST:

EPA ID:	NYP004379061
Country:	USA
Name:	CON EDISON
Address:	337 36TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	337-36TH ST
Location Address 2:	SB49080
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2013
Trans1 Recv Date:	10/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/24/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004379061
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237493GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported

CON EDISON SERVICE BOX: 49080 (Continued) **1016965010**

Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

W253 **CON EDISON** **NY MANIFEST** **S116043715**
ENE **461 36TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.228 mi.
1205 ft. **Site 8 of 8 in cluster W**

Relative: **Lower**

Actual: **38 ft.**

NY MANIFEST:

EPA ID:	NYP004400792
Country:	USA
Name:	CON EDISON
Address:	461 36TH ST
Address 2:	SB49090
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	461 36TH ST
Location Address 2:	SB49090
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	12/05/2013
Trans1 Recv Date:	12/05/2013

CON EDISON (Continued) **S116043715**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004400792
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002300216GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AB254 **CON EDISON** **NY MANIFEST** **S117740917**
SW **46TH ST & 4TH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.229 mi.
1211 ft. **Site 14 of 14 in cluster AB**

Relative: NY MANIFEST:
Higher

Actual: EPA ID:	NYP004741070
81 ft. Country:	USA
Name:	CON EDISON
Address:	46TH ST & 4TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11220
Zip 4:	Not reported
Location Address 1:	4501 4TH AVE
Location Address 2:	MH 5827
Location City,State,Zip:	BROOKLYN, NY 11220

CON EDISON (Continued) **S117740917**

Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 03/02/2015
Trans1 Recv Date: 03/02/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/05/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004741070
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014088822JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 2000

CON EDISON (Continued) **S117740917**

Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AD255 **CON EDISON** **NY MANIFEST** **S117739618**
WSW **333 45TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.230 mi.
1212 ft. **Site 6 of 8 in cluster AD**

Relative:
Higher

Actual:
51 ft.

NY MANIFEST:

EPA ID:	NYP004727517
Country:	USA
Name:	CON EDISON
Address:	333 45TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11220
Zip 4:	Not reported
Location Address 1:	F/O 333 45 ST
Location Address 2:	SB48656
Location City,State,Zip:	BROOKLYN, NY 11220
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/06/2015
Trans1 Recv Date:	02/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/11/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004727517
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610589GBF
Import Indicator:	N

CON EDISON (Continued) **S117739618**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	150
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AD256 **CON EDISON** **NJ MANIFEST** **S120666904**
WSW **333 45TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11220**
0.230 mi.
1212 ft. **Site 7 of 8 in cluster AD**

Relative: **Higher**

Actual: **51 ft.**

NJ MANIFEST:

EPA ID:	NYP004727517
Name:	CON EDISON
Address:	333 45TH ST
City,State,Zip:	BROOKLYN, NY 11220
County:	Not reported
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

CON EDISON (Continued) **S120666904**

Manifest Data:

EPA ID:	NYP004727517
Manifest Number:	002610589GBF
Date Shipped:	2/6/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

AD257 **CON EDISON** **RCRA NonGen / NLR** **1018278003**
WSW **333 45TH ST** **FINDS** **NYP004727517**
1/8-1/4 **BROOKLYN, NY 11220** **ECHO**
0.230 mi.
1212 ft. **Site 8 of 8 in cluster AD**

Relative:
Higher

Actual:
51 ft.

RCRA Listings:

Date Form Received by Agency:	20150206
Handler Name:	Con Edison
Handler Address:	45TH ST
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NYP004727517
Contact Name:	THOMAS TEELING
Contact Address:	Not reported

CON EDISON (Continued) **1018278003**

Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

CON EDISON (Continued) **1018278003**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20150206
Handler Name: CON EDISON
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150206
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067698129

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

CON EDISON (Continued) **1018278003**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018278003
Registry ID:	110067698129
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067698129
Name:	CON EDISON
Address:	333 45TH ST
City,State,Zip:	BROOKLYN, NY 11220

Z258 **CON EDISON** **RCRA NonGen / NLR** **1019908050**
SE **563 41ST ST** **FINDS** **NYP004841421**
1/8-1/4 **BROOKLYN, NY 11232** **ECHO**
0.230 mi.
1215 ft. **Site 7 of 9 in cluster Z**

Relative: **Higher**
Actual: **133 ft.**

RCRA Listings:

Date Form Received by Agency:	20150921
Handler Name:	Con Edison
Handler Address:	41ST ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004841421
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No

CON EDISON (Continued) **1019908050**

Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150921
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150921
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON (Continued) **1019908050**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069654261

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019908050
Registry ID:	110069654261
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069654261
Name:	CON EDISON
Address:	563 41ST ST
City,State,Zip:	BROOKLYN, NY 11232

Z259 **CON EDISON** **NY MANIFEST** **S118259934**
SE **563 41ST ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.230 mi.
1215 ft. **Site 8 of 9 in cluster Z**

Relative:
Higher

Actual:
133 ft.

NY MANIFEST:

EPA ID:	NYP004841421
Country:	USA
Name:	CON EDISON
Address:	563 41ST ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	563 41ST ST
Location Address 2:	SB 48300
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

CON EDISON (Continued) **S118259934**

Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	09/21/2015
Trans1 Recv Date:	09/21/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/21/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004841421
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002625043GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

Z260 **CON EDISON** **NJ MANIFEST** **S120676960**
SE **563 41ST ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.230 mi.
1215 ft. **Site 9 of 9 in cluster Z**

Relative:
Higher

Actual:
133 ft.

NJ MANIFEST:

EPA ID:	NYP004841421
Name:	CON EDISON
Address:	563 41ST ST
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYP004841421
Manifest Number:	002625043GBF
Date Shipped:	9/21/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

CON EDISON (Continued) **S120676960**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

AJ261 **CON EDISON** **NY MANIFEST** **S118088519**
SE **566 40TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.233 mi.
1231 ft. **Site 1 of 3 in cluster AJ**

Relative:
Higher

Actual:
129 ft.

NY MANIFEST:

EPA ID:	NYP004760906
Country:	USA
Name:	CON EDISON
Address:	566 40TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	566 40TH ST
Location Address 2:	SB 49296
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJ0000027193
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/2015
Trans1 Recv Date:	03/31/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004760906
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S118088519**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014088380JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AJ262 **CON EDISON** **NJ MANIFEST** **S120669857**
SE **566 40TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.233 mi.
1231 ft. **Site 2 of 3 in cluster AJ**

Relative: **Higher**

Actual: **129 ft.**

NJ MANIFEST:

EPA ID:	NYP004760906
Name:	CON EDISON
Address:	566 40TH ST
City,State,Zip:	BROOKLYN, NY 11232
County:	Not reported
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported
Transporter Flag:	Not reported

CON EDISON (Continued) **S120669857**

TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported
Manifest Data:	
EPA ID:	NYP004760906
Manifest Number:	014088380JJK
Date Shipped:	3/31/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

AJ263 **CON EDISON** **RCRA NonGen / NLR** **1019901346**
SE **566 40TH ST** **FINDS** **NYP004760906**
1/8-1/4 **BROOKLYN, NY 11232** **ECHO**
0.233 mi.
1231 ft. **Site 3 of 3 in cluster AJ**

Relative:
Higher

Actual:
129 ft.

RCRA Listings:

Date Form Received by Agency:	20150331
Handler Name:	Con Edison
Handler Address:	40TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232

CON EDISON (Continued) **1019901346**

EPA ID:	NYP004760906
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No

CON EDISON (Continued) **1019901346**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150331
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150331
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID:	110069701594

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many

CON EDISON (Continued) **1019901346**

types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019901346
Registry ID:	110069701594
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069701594
Name:	CON EDISON
Address:	566 40TH ST
City,State,Zip:	BROOKLYN, NY 11232

AE264 **CON EDISON MANHOLE: 45483** **RCRA NonGen / NLR** **1016967660**
NNE **940 4TH AVE** **NY MANIFEST** **NYP004412581**
1/8-1/4 **BROOKLYN, NY 11232**
0.234 mi.
1233 ft. **Site 6 of 6 in cluster AE**

Relative: **Lower**

Actual: **23 ft.**

RCRA Listings:

Date Form Received by Agency:	20140205
Handler Name:	Con Edison Manhole: 45483
Handler Address:	4TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004412581
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

CON EDISON MANHOLE: 45483 (Continued) **1016967660**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140105
Handler Name:	CON EDISON MANHOLE: 45483
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140205
Handler Name:	CON EDISON MANHOLE: 45483
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON MANHOLE: 45483 (Continued) **1016967660**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004412581
Country: USA
Name: CON EDISON
Address: 940 4TH AVE
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: FP 940 4TH AVE
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11232
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJ0000027193
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 01/06/2014
Trans1 Recv Date: 01/06/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/09/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004412581
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported

CON EDISON MANHOLE: 45483 (Continued) **1016967660**

Manifest Tracking Number:	011696272JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AC265 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243447**
ENE **36 ST & 5 AVE MH76063** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.236 mi.
1245 ft. **Site 14 of 15 in cluster AC**

Relative: **Higher**
Actual: **55 ft.**

NY MANIFEST:

EPA ID:	NYP004129136
Country:	USA
Name:	CONSOLIDATED EDISON
Address:	36 ST & 5 AVE MH76063
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	36 ST & 5 AVE MH76063
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828

CONSOLIDATED EDISON (Continued) **1009243447**

Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	NYE1553967
Manifest Status:	Not reported
Trans1 State ID:	69526JR
Year:	2005
Trans2 State ID:	Not reported
Generator Ship Date:	02/25/2005
Trans1 Recv Date:	02/25/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/28/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004129136
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00050
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

AK266 **CON EDISON - MANHOLE 63187** **NY MANIFEST** **S120959111**
ENE **36TH ST & 5TH AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.237 mi.
1250 ft. **Site 1 of 3 in cluster AK**

Relative:
Higher

Actual:
55 ft.

NY MANIFEST:

EPA ID:	NYP004993026
Country:	USA
Name:	CON EDISON - MANHOLE 63187
Address:	36TH ST & 5TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	36TH ST & 5TH AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON - MANHOLE 63187
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AK267 **CON EDISON MANHOLE 3992** **RCRA NonGen / NLR** **1010326702**
ENE **5 AVE & 36 ST** **NY MANIFEST** **NYP004142600**
1/8-1/4 **BROOKLYN, NY 11232**
0.237 mi.
1250 ft. **Site 2 of 3 in cluster AK**

Relative:
Higher

Actual:
55 ft.

RCRA Listings:

Date Form Received by Agency:	20061117
Handler Name:	Con Edison Manhole 3992
Handler Address:	5 AVE & 36 ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004142600
Contact Name:	TIMOTHY REGAN
Contact Address:	4 IRVING PL, RM 828
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	718-204-4221
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny

CON EDISON MANHOLE 3992 (Continued) **1010326702**

State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20061115
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not reported
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON MANHOLE 3992 (Continued) **1010326702**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20061116
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20061117
Handler Name: CON EDISON MANHOLE 3992
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004142600
Country: USA
Name: CONSOLIDATED EDISON
Address: 5 AVE & 36 ST
Address 2: E OF & 213 FT N OF 36 ST
City,State,Zip: BROOKLYN, NY 11232
Zip 4: Not reported
Location Address 1: 5 AVE & 36 ST MH3992
Location Address 2: Not reported
Location City,State,Zip: BROOKLYN, NY 11201
Location Zip 4: Not reported
Facility Status: Not reported

CON EDISON MANHOLE 3992 (Continued) **1010326702**

Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD006982359
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 06/03/2006
Trans1 Recv Date: 06/03/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/05/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004142600
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: NYE1321812
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code a: B007
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 140
Units: Kilograms
Number of Containers: 1

CON EDISON MANHOLE 3992 (Continued) **1010326702**

Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	0.08
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	06/03/2006
Trans1 Recv Date:	06/03/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/05/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004142600
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	NYE1321812
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	357
Units:	Kilograms
Number of Containers:	3
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

AK268 **CON EDISON MANHOLE 66063** **RCRA NonGen / NLR** **1010327688**
ENE **36 ST & 5TH AVE** **NY MANIFEST** **NYP004148185**
1/8-1/4 **BROOKLYN, NY 11215**
0.237 mi.
1250 ft. **Site 3 of 3 in cluster AK**

Relative: **Higher**

Actual: **55 ft.**

RCRA Listings:

Date Form Received by Agency:	20070411
Handler Name:	Con Edison Manhole 66063
Handler Address:	36 ST & 5TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11215
EPA ID:	NYP004148185
Contact Name:	PATRICK HANLEY
Contact Address:	4 IRVING PL, RM 828
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	718-204-4234
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON MANHOLE 66063 (Continued) **1010327688**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20070409
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not reported
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070410
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070411
Handler Name: CON EDISON MANHOLE 66063	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON MANHOLE 66063 (Continued) **1010327688**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004148185
Country:	USA
Name:	CONSOLIDATED EDISON
Address:	36 ST & 5TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11215
Zip 4:	Not reported
Location Address 1:	36th STREET & 6th AVENUE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYB, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD006982359
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/16/2007
Trans1 Recv Date:	02/16/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004148185
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001450468FLE
Import Indicator:	N

CON EDISON MANHOLE 66063 (Continued) **1010327688**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	CADMIUM
Waste Code b:	CHROMIUM
Waste Code c:	LEAD
Waste Code e:	B007
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	200
Units:	Kilograms
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

AG269 **CONSOLIDATED EDISON** **NY MANIFEST** **1009234307**
NW **257 W 39TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11201**
0.238 mi.
1255 ft. **Site 2 of 3 in cluster AG**

Relative:
Lower

Actual:
15 ft.

NY MANIFEST:

EPA ID:	NYP000928200
Country:	USA
Name:	CONSOLIDATED EDISON
Address:	257 W 39TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11201
Zip 4:	Not reported
Location Address 1:	257 W 39TH ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11201
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003

CONSOLIDATED EDISON (Continued) **1009234307**

Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

Manifest Data:
Document ID: NYB7236162
Manifest Status: Not reported
Trans1 State ID: SM1708
Year: 1996
Trans2 State ID: Not reported
Generator Ship Date: 09/03/1996
Trans1 Recv Date: 09/03/1996
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/04/1996
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP000928200
Trans1 EPA ID: NYD006982359
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: B003
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 01273
Units: Kilograms
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 01.00

Document ID: NYG0123966
Manifest Status: Not reported
Trans1 State ID: GX3213
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 03/20/1997
Trans1 Recv Date: 03/20/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/21/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported

CONSOLIDATED EDISON (Continued) **1009234307**

Generator EPA ID:		NYP000928200
Trans1 EPA ID:		NYD006982359
Trans2 EPA ID:		Not reported
TSDF ID 1:		NYD980593636
TSDF ID 2:		Not reported
Manifest Tracking Number:		Not reported
Import Indicator:		Not reported
Export Indicator:		Not reported
Discr Quantity Indicator:		Not reported
Discr Type Indicator:		Not reported
Discr Residue Indicator:		Not reported
Discr Partial Reject Indicator:		Not reported
Discr Full Reject Indicator:		Not reported
Manifest Ref Number:		Not reported
Alt Facility RCRA ID:		Not reported
Alt Facility Sign Date:		Not reported
MGMT Method Type Code:		Not reported
Waste Code 1:	B003	
Waste Code 2:		Not reported
Waste Code 3:		Not reported
Waste Code 4:		Not reported
Waste Code 5:		Not reported
Waste Code 6:		Not reported
Quantity:		00818
Units:		Kilograms
Number of Containers:		001
Container Type:		Cargo tanks (tank trucks)
Handling Method:		Treat
Specific Gravity:		01.00

AC270 **CON EDISON SERVICE BOX: 63190** **RCRA NonGen / NLR** **1016964501**
ENE **502 36TH ST** **NY MANIFEST** **NYP004374211**
1/8-1/4 **BROOKLYN, NY 11232**
0.238 mi.
1256 ft. **Site 15 of 15 in cluster AC**

Relative:
Higher

Actual:
55 ft.

RCRA Listings:

Date Form Received by Agency:	20131115
Handler Name:	Con Edison Service Box: 63190
Handler Address:	36TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004374211
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny

CON EDISON SERVICE BOX: 63190 (Continued) **1016964501**

State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131015
Handler Name: CON EDISON SERVICE BOX:	63190
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON SERVICE BOX: 63190 (Continued) **1016964501**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131115
Handler Name: CON EDISON SERVICE BOX:	63190
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004374211
Country:	USA
Name:	CON EDISON
Address:	502 36TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	F/O 502 36TH ST
Location Address 2:	SB63190
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON SERVICE BOX: 63190 (Continued) **1016964501**

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2013
Trans1 Recv Date:	10/15/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004374211
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002291248GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	75
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AL271 **CON EDISON - MANHOLE 71492** **RCRA-LQG** **1016966354**
SSW **442 45 ST** **NY MANIFEST** **NYP004392056**
1/8-1/4 **BROOKLYN, NY 11220**
0.238 mi.
1259 ft. **Site 1 of 2 in cluster AL**

Relative: **Higher**
Actual: **96 ft.**

RCRA Listings:

Date Form Received by Agency:	20140327
Handler Name:	Con Edison - Manhole 71492
Handler Address:	45 ST
Handler City,State,Zip:	BROOKLYN, NY 11220
EPA ID:	NYP004392056
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	518-473-8034
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON - MANHOLE 71492 (Continued) **1016966354**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20131115
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20131115
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140327
Handler Name:	CON EDISON - MANHOLE 71492
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny

CON EDISON - MANHOLE 71492 (Continued) **1016966354**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131115
Handler Name: CON EDISON MANHOLE: 71492
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131215
Handler Name: CON EDISON MANHOLE: 71492
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYP004392056
Country: USA
Name: CON EDISON
Address: 442 45TH ST
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11220
Zip 4: Not reported
Location Address 1: 442 45TH ST

CON EDISON - MANHOLE 71492 (Continued) **1016966354**

Location Address 2: SB71492
Location City,State,Zip: BROOKLYN, NY 11220
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City,State,Zip: NEW YORK, NY 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD003812047
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 11/15/2013
Trans1 Recv Date: 11/15/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/18/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004392056
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002299010GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code a: LEAD
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported

CON EDISON - MANHOLE 71492 (Continued) **1016966354**

Waste Code 6:	Not reported
Quantity:	600
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

AG272 **CON EDISON - MANHOLE M49195** **NY MANIFEST** **S120958023**
NW **230 39 ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.244 mi.
1286 ft. **Site 3 of 3 in cluster AG**

Relative:
Lower

Actual:
15 ft.

NY MANIFEST:

EPA ID:	NYP004904387
Country:	USA
Name:	CON EDISON - MANHOLE M49195
Address:	230 39 ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	230 39 ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON - MANHOLE M49195
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AM273 **INDUSTRY CITY ASSOCIATION** **RCRA NonGen / NLR** **1000912611**
NNW **241 37TH ST** **FINDS** **NY0000882027**
1/8-1/4 **BROOKLYN, NY 11232** **ECHO**
0.245 mi. **NY MANIFEST**
1296 ft. **Site 1 of 3 in cluster AM**

Relative:
Lower

Actual:
13 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Industry City Association
Handler Address:	37TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232-2409
EPA ID:	NY0000882027
Contact Name:	Not reported
Contact Address:	37TH ST
Contact City,State,Zip:	BROOKLYN, NY 11232

INDUSTRY CITY ASSOCIATION (Continued) **1000912611**

Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	37TH ST
Mailing City,State,Zip:	BROOKLYN, NY 11232
Owner Name:	Industry City Association
Owner Type:	Private
Operator Name:	Industry City Association
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No

INDUSTRY CITY ASSOCIATION (Continued) **1000912611**

Manifest Broker: No
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: INDUSTRY CITY ASSOCIATION
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 141 37TH ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11232
Owner/Operator Telephone: 718-965-6450
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: INDUSTRY CITY ASSOCIATION
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 141 37TH ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11232
Owner/Operator Telephone: 718-965-6450
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: INDUSTRY CITY ASSOCIATION
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 141 37TH ST
Owner/Operator City,State,Zip: BROOKLYN, NY 11232
Owner/Operator Telephone: 718-965-6450
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: INDUSTRY CITY ASSOCIATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

INDUSTRY CITY ASSOCIATION (Continued) **1000912611**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: INDUSTRY CITY ASSOCIATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: INDUSTRY CITY ASSOCIATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19941013
Handler Name: INDUSTRY CITY ASSOCIATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004320477

INDUSTRY CITY ASSOCIATION (Continued) **1000912611**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000912611
Registry ID:	110004320477
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004320477
Name:	INDUSTRY CITY ASSOCIATION
Address:	241 37TH ST
City,State,Zip:	BROOKLYN, NY 11232

NY MANIFEST:

EPA ID:	NY0000882027
Country:	USA
Name:	INDUSTRY CITY ASSOCIATION
Address:	241 37TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232-2409
Zip 4:	Not reported
Location Address 1:	241 37TH ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	INDUSTRY CITY ASSOCIATION
Mailing Contact:	DENNIS HOVANEC
Mailing Address 1:	241 37TH STREET
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11232
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7189656450

Manifest Data:

Document ID:	NJA2009107
Manifest Status:	Not reported
Trans1 State ID:	50060
Year:	1994
Trans2 State ID:	S50060

INDUSTRY CITY ASSOCIATION (Continued) **1000912611**

Generator Ship Date:	10/20/1994
Trans1 Recv Date:	10/20/1994
Trans2 Recv Date:	10/25/1994
TSD Site Recv Date:	10/26/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000882027
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	NYD980761191
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	IGNITABLE WASTE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00002
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	CTF0360830
Manifest Status:	Not reported
Trans1 State ID:	16788ACT
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/1994
Trans1 Recv Date:	10/20/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/21/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000882027
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD072138969
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported

INDUSTRY CITY ASSOCIATION (Continued) **1000912611**

Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	IGNITABLE WASTE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00020
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	CORROSIVE WASTE
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00005
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

AF274 **CON EDISON SERVICE BOX: 49079** **RCRA NonGen / NLR** **1016965009**
North **315 36TH ST** **NY MANIFEST** **NYP004379053**
1/8-1/4 **BROOKLYN, NY 11232**
0.246 mi.
1298 ft. **Site 2 of 2 in cluster AF**

Relative: **Lower**
Actual: **16 ft.**

RCRA Listings:

Date Form Received by Agency:	20131123
Handler Name:	Con Edison Service Box: 49079
Handler Address:	36TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYP004379053
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported

CON EDISON SERVICE BOX: 49079 (Continued) **1016965009**

State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20131023
Handler Name: CON EDISON SERVICE BOX:	49079
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON SERVICE BOX: 49079 (Continued) **1016965009**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131123
Handler Name: CON EDISON SERVICE BOX:	49079
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

EPA ID:	NYP004379053
Country:	USA
Name:	CON EDISON
Address:	315 36TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	315 36TH ST
Location Address 2:	SB49079
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON SERVICE BOX: 49079 (Continued) **1016965009**

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2013
Trans1 Recv Date:	10/23/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/24/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004379053
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002237494GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

275
SW
1/8-1/4
0.247 mi.
1306 ft.

MARIEN-HEIM OF SUNSET PARK
4520 4TH AVENUE
BROOKLYN, NY 11220

NY AST **U003391812**
N/A

Relative:
Higher

Actual:
70 ft.

AST:

Name:	MARIEN-HEIM OF SUNSET PARK
Address:	4520 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11220
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-216046
Program Type:	PBS
UTM X:	583678.57444
UTM Y:	4500291.34213
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	8104
Affiliation Type:	Mail Contact
Company Name:	MARIEN-HEIM OF SUNSET PARK
Contact Type:	ADMINISTRATOR
Contact Name:	BARBARA MIKOLAJCZAK
Address1:	4520-4 AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 492-6833
EMail:	MHSP@VERIZON.NET
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2012-12-21

Site Id:	8104
Affiliation Type:	Facility Operator
Company Name:	MARIEN-HEIM OF SUNSET PARK
Contact Type:	Not reported
Contact Name:	DRITAN IBRAHIMI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 492-6833
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2012-12-21

Site Id:	8104
Affiliation Type:	Emergency Contact
Company Name:	MARIEN-HEIM OF SUNSET PARK
Contact Type:	Not reported
Contact Name:	BARBARA MIKOLAJCZAK

MARIEN-HEIM OF SUNSET PARK (Continued) **U003391812**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 833-8670
EMail:	Not reported
Fax Number:	Not reported
Modified By:	kakyer
Date Last Modified:	2007-09-11

Site Id:	8104
Affiliation Type:	Facility Owner
Company Name:	MARIEN-HEIM OF SUNSET PARK HDFC
Contact Type:	AUTHORIZED REP.
Contact Name:	DAVID CHAN
Address1:	4520-4 AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11220
Country Code:	001
Phone:	(718) 492-6833
EMail:	MHSP@VERIZON.NET
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2022-04-20

Tank Info:

Tank Number:	120
Tank Id:	22336
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G00 - Tank Secondary Containment - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	K01 - Spill Prevention - Catch Basin
	L09 - Piping Leak Detection - Exempt Suction Piping
	E00 - Piping Secondary Containment - None
	J01 - Dispenser - Pressurized Dispenser
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	H99 - Tank Leak Detection - Other
	I04 - Overfill - Product Level Gauge (A/G)
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/01/1980
Capacity Gallons:	9698

MARIEN-HEIM OF SUNSET PARK (Continued) **U003391812**

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/24/2022
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AM276 **CON EDISON - VAULT SUBMERSIBLE VS7560** **NY MANIFEST** **S123692369**
NNW **233 37TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.248 mi.
1312 ft. **Site 2 of 3 in cluster AM**

Relative: **Lower**
Actual: **13 ft.**

NY MANIFEST:

EPA ID:	NYP005194444
Country:	USA
Name:	CON EDISON - VAULT SUBMERSIBLE VS7560
Address:	233 37TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	233 37TH ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON - VAULT SUBMERSIBLE VS7560
Mailing Contact:	ANNAMARIE MOYLAN
Mailing Address 1:	4 IRVING PLACE 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602278

AM277 **CON EDISON - VAULT SUBMERSIBLE VS7497** **NY MANIFEST** **S123692370**
NNW **233 37TH ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.248 mi.
1312 ft. **Site 3 of 3 in cluster AM**

Relative: **Lower**
Actual: **13 ft.**

NY MANIFEST:

EPA ID:	NYP005194451
Country:	USA
Name:	CON EDISON - VAULT SUBMERSIBLE VS7497
Address:	233 37TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	233 37TH ST

CON EDISON - VAULT SUBMERSIBLE VS7497 (Continued) **S123692370**

Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON - VAULT SUBMERSIBLE VS7497
Mailing Contact:	ANNAMARIE MOYLAN
Mailing Address 1:	4 IRVING PLACE 15TH FL NE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602278

AN278 **GREENWOOD CEMETERY** **NY LTANKS** **S102619671**
NE **921 4TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.250 mi.
1318 ft. **Site 1 of 7 in cluster AN**

Relative: **Lower**

Actual: **24 ft.**

LTANKS:

Name:	GREENWOOD CEMETERY
Address:	921 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 11232-2317
Spill Number/Closed Date:	9413808 / 2005-11-16
Facility ID:	9413808
Site ID:	150406
Spill Date:	1995-01-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JEDURNIN
Referred To:	Not reported
Reported to Dept:	1995-01-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1995-03-21
Spill Record Last Update:	2005-11-16
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	NICHOLAS VISLOCKY
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2

GREENWOOD CEMETERY (Continued) **S102619671**

DER Facility ID: 127896
DEC Memo: November 16, 2005, Durnin: On about January 17, 1995, the Greenwood Cemetery removed 3 existing 550 gallon & 1 existing 4000 gallon motor fuel storage tanks & related pumps. They were replaced with 1 new 1000 gallon & 1 new 4000 gallon motor fuel storage tanks and 2 new BSA approved pumps on a concrete island with related piping and controls. Both tanks are Double-Walled Fiberglass. The 1000 gallon tank is for diesel. Nicholas Vislocky obtained a permit to do this work on July 25, 1994. Based on this information and that less than a liter of petroleum was apparently spilled, this spill is closed.
Remarks: CONTAMINATION FOUND WHEN REMOVING TANKS ABOVE TANKS. 3 550 GAL TANKS

All Materials:
Site ID: 150406
Operable Unit ID: 1011366
Operable Unit: 01
Material ID: 372555
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

AN279 **THE GREEN-WOOD CEMETERY** **NY UST** **U004063009**
NE **921 FOURTH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.250 mi.
1318 ft. **Site 2 of 7 in cluster AN**

Relative: **Lower**
Actual: **24 ft.**

UST:
Name: THE GREEN-WOOD CEMETERY
Address: 921 FOURTH AVENUE
City,State,Zip: BROOKLYN, NY 11232
Id/Status: 2-004472 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 10/23/2027
UTM X: 584259.46568
UTM Y: 4500860.81843
Site Type: Cemeteries/Memorials

Affiliation Records:
Site Id: 42
Affiliation Type: Emergency Contact
Company Name: THE GREEN-WOOD CEMETERY
Contact Type: Not reported
Contact Name: LUIGI ARNONE
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999

THE GREEN-WOOD CEMETERY (Continued) **U004063009**

Phone:	(718) 679-8692
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-03-22

Site Id:	42
Affiliation Type:	Mail Contact
Company Name:	THE GREEN-WOOD CEMETERY
Contact Type:	VICE PRESIDENT
Contact Name:	ERIC BARNA
Address1:	500 25TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(718) 768-7300
EMail:	LUIGIARNONE@GREEN-WOOD.COM
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2019-08-19

Site Id:	42
Affiliation Type:	Facility Owner
Company Name:	THE GREEN-WOOD CEMETERY
Contact Type:	VICE PRESIDENT
Contact Name:	ERIC BARNA
Address1:	500 25TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(718) 768-7300
EMail:	LUIGIARNONE@GREEN-WOOD.COM
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2019-08-19

Site Id:	42
Affiliation Type:	Facility Operator
Company Name:	THE GREEN-WOOD CEMETERY
Contact Type:	Not reported
Contact Name:	ERIC BARNA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 768-7300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2019-08-19

THE GREEN-WOOD CEMETERY (Continued) **U004063009**

Tank Info:

Tank Number:	001
Tank ID:	26773
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	11/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	002
Tank ID:	26774
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	09/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	12/01/1989
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
I00 - Overfill - None
H00 - Tank Leak Detection - None

THE GREEN-WOOD CEMETERY (Continued) **U004063009**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 003
Tank ID: 26775
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: Not reported
Date Tank Closed: 09/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 05/01/1989
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 004
Tank ID: 26776
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 06/01/1973
Date Tank Closed: 09/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI

THE GREEN-WOOD CEMETERY (Continued) **U004063009**

Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 26777
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 5000
Install Date: 01/01/1964
Date Tank Closed: 01/31/2009
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 08/11/2004
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J03 - Dispenser - Gravity
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
I04 - Overfill - Product Level Gauge (A/G)
I05 - Overfill - Vent Whistle

Tank Number: 006
Tank ID: 48349
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 09/01/1994
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground

THE GREEN-WOOD CEMETERY (Continued) **U004063009**

Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
E04 - Piping Secondary Containment - Double walled UG
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
J02 - Dispenser - Suction Dispenser
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 007
Tank ID: 48350
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 1000
Install Date: 09/01/1994
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double walled UG
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
D07 - Pipe Type - Plastic
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped

THE GREEN-WOOD CEMETERY (Continued) **U004063009**

A03 - Tank Internal Protection - Fiberglass Liner (FRP)
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

AN280 **GREENWOOD CEMETERY** **UST FINDER RELEASE** **1029058706**
NE **921 4TH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 0**
0.250 mi.
1318 ft. **Site 3 of 7 in cluster AN**

Relative: **Lower**
Actual: **24 ft.**

UST FINDER RELEASE:

Object ID:	255934
Facility ID:	NY127896
Lust ID:	NY9413808
Name:	GREENWOOD CEMETERY
Address:	921 4TH AVENUE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1995/01/17 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	6281
Domestic Wells within 1500ft:	16
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-74.00354
Y Coord:	40.65497
Latitude:	40.6549699999999
Longitude:	-74.00354

AN281 **THE GREEN-WOOD CEMETERY** **UST FINDER** **1028586904**
NE **921 FOURTH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.250 mi.
1318 ft. **Site 4 of 7 in cluster AN**

Relative:
Lower

Actual:
24 ft.

UST FINDER:

Object ID:	295030
Facility ID:	NY42
Name:	THE GREEN-WOOD CEMETERY
Address:	921 FOURTH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Address Match Type:	Not reported
Open USTs:	2
Closed USTs:	5
TOS USTs:	0
Population 1500ft:	6860
Private Wells 1500ft:	16
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-74.003319
Y Coord:	40.6543100000001
Latitude:	40.65431
Longitude:	-74.003319

UST FINDER:

Object ID:	1268521
Facility ID:	NY42
Tank ID:	NY37
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1268522
Facility ID:	NY42
Tank ID:	NY114
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

THE GREEN-WOOD CEMETERY (Continued) **1028586904**

Object ID:	1268523
Facility ID:	NY42
Tank ID:	NY149
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1268524
Facility ID:	NY42
Tank ID:	NY204
Tank Status:	Closed
Installation Date:	1973/06/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	550
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1268525
Facility ID:	NY42
Tank ID:	NY38
Tank Status:	Open
Installation Date:	1994/09/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1268526
Facility ID:	NY42
Tank ID:	NY99
Tank Status:	Open
Installation Date:	1994/09/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1268527
Facility ID:	NY42
Tank ID:	NY175
Tank Status:	Closed
Installation Date:	1964/01/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	5000
Substances:	Not reported
Tank Wall Type:	Not reported

AN282 **THE GREEN-WOOD CEMETERY** **NY AST** **U001838840**
NE **921 FOURTH AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11232**
0.250 mi.
1318 ft. **Site 5 of 7 in cluster AN**

Relative:
Lower

Actual:
24 ft.

AST:

Name:	THE GREEN-WOOD CEMETERY
Address:	921 FOURTH AVENUE
City,State,Zip:	BROOKLYN, NY 11232
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-004472
Program Type:	PBS
UTM X:	584259.46568
UTM Y:	4500860.81843
Expiration Date:	10/23/2027
Site Type:	Cemeteries/Memorials

Affiliation Records:

Site Id:	42
Affiliation Type:	Emergency Contact
Company Name:	THE GREEN-WOOD CEMETERY
Contact Type:	Not reported
Contact Name:	LUIGI ARNONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 679-8692
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-03-22

Site Id:	42
Affiliation Type:	Mail Contact
Company Name:	THE GREEN-WOOD CEMETERY
Contact Type:	VICE PRESIDENT
Contact Name:	ERIC BARNA
Address1:	500 25TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(718) 768-7300
EMail:	LUIGIARNONE@GREEN-WOOD.COM
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2019-08-19

Site Id:	42
Affiliation Type:	Facility Owner
Company Name:	THE GREEN-WOOD CEMETERY
Contact Type:	VICE PRESIDENT
Contact Name:	ERIC BARNA

THE GREEN-WOOD CEMETERY (Continued) **U001838840**

Address1:	500 25TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11232
Country Code:	001
Phone:	(718) 768-7300
EMail:	LUIGIARNONE@GREEN-WOOD.COM
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2019-08-19

Site Id:	42
Affiliation Type:	Facility Operator
Company Name:	THE GREEN-WOOD CEMETERY
Contact Type:	Not reported
Contact Name:	ERIC BARNA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 768-7300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2019-08-19

Tank Info:

Tank Number:	0001
Tank Id:	229070
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
G10 - Tank Secondary Containment - Impervious Underlayment
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported

THE GREEN-WOOD CEMETERY (Continued) **U001838840**

Install Date:	01/31/2009
Capacity Gallons:	1000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	0002
Tank Id:	229071
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
D00 - Pipe Type - No Piping
E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
J00 - Dispenser - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/31/2009
Capacity Gallons:	250
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	008
Tank Id:	53444
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

D00 - Pipe Type - No Piping

THE GREEN-WOOD CEMETERY (Continued) **U001838840**

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/2000
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/31/2009
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	009
Tank Id:	53445
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/2000
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/31/2009
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

AN283 **4TH AVE & 34TH / 35TH ST.** **NY LTANKS** **S105053969**
NNE **4TH AVE & 34TH/35TH STREE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.251 mi.
1324 ft. **Site 6 of 7 in cluster AN**

Relative:
Lower

Actual:
21 ft.

LTANKS:

Name:	4TH AVE & 34TH / 35TH ST.
Address:	4TH AVE & 34TH/35TH STREE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8901237 / 1992-09-30
Facility ID:	8901237
Site ID:	117733
Spill Date:	1989-05-08
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1992-09-30
SWIS:	2401
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1989-05-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-05-09
Spill Record Last Update:	1994-05-12
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	102373
DEC Memo:	Not reported
Remarks:	5K TANK FAILED A SYSTEMS TEST, HORNER EZY CHECK, GROSS LEAK, WILL ISOLATE LINES & TEST TANKS.

All TTF:

Facility ID:	8901237
Spill Number:	8901237
Spill Tank Test:	1535433
Site ID:	117733
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

4TH AVE & 34TH / 35TH ST. (Continued) **S105053969**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 117733
Operable Unit ID: 927378
Operable Unit: 01
Material ID: 448991
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Resource Affected: Groundwater
Oxygenate: Not reported

284
NNW
1/4-1/2
0.255 mi.
1349 ft.

DAVIDSON PIPE SUPPLY CO INC **NY LTANKS** **S103238598**
990 3RD AVE **NY MANIFEST** **N/A**
BROOKLYN, NY 11232

Relative:
Lower

Actual:
12 ft.

LTANKS:
Name: 990 THIRD AVE
Address: 990 THIRD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9510315 / 2006-02-15
Facility ID: 9510315
Site ID: 175589
Spill Date: 1995-11-16
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: JCGRATHW
Referred To: Not reported
Reported to Dept: 1995-11-16
CID: 297
Water Affected: Not reported
Spill Notifier: Local Agency
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1995-11-16
Spill Record Last Update: 2006-02-24
Spiller Name: PETER DAVIDSON
Spiller Company: DAVIDSON PIPE SUPPLY
Spiller Address: 5002 2D AVE
Spiller County: 001
Spiller Contact: AL GULUM

DAVIDSON PIPE SUPPLY CO INC (Continued) **S103238598**

Spiller Phone:	(516) 221-7500
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	147618
DEC Memo:	8/15/05 - Haggerty - spoke with Kathy from Soil Mechanics (516)-221-7500 on 7/15/05. She is trying to locate the file and will call back when and if she does. All other contact info is outdated. ----requires additional info, site visit 11/22/05, SA: No PBS record found. Can not find the property records in the property shark. Address found on google. Talked to Kathy, she told me that as far she remember this spill has been closed by DEC. She will fax me a copy if found. 12/19/2005: No record found in remediation database. Spill remains open. Need to find the owner. (Sadique) 01/04/2006: As per property shark present owner is Costco Wholesale Corp. The property have multiple alternate address. (Sadique) 02/15/06 - DEC lead changed to Grathwol. Performed site visit. Davidson Pipe Supply is no longer at this address. Tenant spoke to me on the phone and gave me permission to inspect the basement of his new business. No oil fumes, basement refinished. Business is on gas heat. New slab floor, no oil stains on walls or floor. Floor drain had water in it, no oil product or sheen. New business: K.C. Products, Ltd. (Kitchen counters, moulding, etc.)
Remarks:	COMPLAINANTS COMPANY WAS CONTRACTED TO REMOVED THREE TANKS OUT OF THE GROUND AND TWO TANKS WERE DISCOVERED TO HAVE BEEN LEAKING FOR AN UNDETERMINED AMOUNT OF TIME,BOTH TANKS HELD 4,000 GALS - TANKS HAVE BEEN REMOVED FROM THE GROUND AND CLEAN UP WILL BEGIN TOMORROW

All Materials:

Site ID:	175589
Operable Unit ID:	1020837
Operable Unit:	01
Material ID:	361240
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

NY MANIFEST:

EPA ID:	NYR000011544
Country:	USA
Name:	DAVIDSON PIPE SUPPLY CO INC
Address:	990 3RD AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232-2400
Zip 4:	Not reported
Location Address 1:	990 THIRD AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported

DAVIDSON PIPE SUPPLY CO INC (Continued) **S103238598**

Code: BP

Mailing:
Mailing Name: DAVIDSON PIPE SUPPLY CO INC
Mailing Contact: HAROLD PIGARO
Mailing Address 1: 990 THIRD AVE
Mailing Address 2: Not reported
Mailing City,State,Zip: BROOKLYN, NY 11232
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7184396300

Manifest Data:
Document ID: PAE6008100
Manifest Status: Not reported
Trans1 State ID: PAAH0317
Year: 1996
Trans2 State ID: Not reported
Generator Ship Date: 05/14/1996
Trans1 Recv Date: 05/14/1996
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/16/1996
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000011544
Trans1 EPA ID: PAD982661381
Trans2 EPA ID: Not reported
TSDF ID 1: PAD085690592
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: LEAD
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 46880
Units: Pounds
Number of Containers: 001
Container Type: Dump truck
Handling Method: Landfill
Specific Gravity: 01.00

Document ID: PAE6008111
Manifest Status: Not reported
Trans1 State ID: PAAH0338

DAVIDSON PIPE SUPPLY CO INC (Continued) **S103238598**

Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/1996
Trans1 Recv Date:	05/14/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000011544
Trans1 EPA ID:	NYD986969947
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	44280
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00
Document ID:	PAE6008203
Manifest Status:	Not reported
Trans1 State ID:	PAAH0338
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/1996
Trans1 Recv Date:	05/14/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000011544
Trans1 EPA ID:	NYD986969947
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

DAVIDSON PIPE SUPPLY CO INC (Continued) **S103238598**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	50420
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	PAE6007691
Manifest Status:	Not reported
Trans1 State ID:	PAAH0317
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/1996
Trans1 Recv Date:	05/13/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000011544
Trans1 EPA ID:	PAD982661381
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	30040

DAVIDSON PIPE SUPPLY CO INC (Continued) **S103238598**

Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00
Document ID:	PAE6007702
Manifest Status:	Not reported
Trans1 State ID:	PAAH0317
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/1996
Trans1 Recv Date:	05/13/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000011544
Trans1 EPA ID:	PAD982661381
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	43360
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00
Document ID:	PAE6007713
Manifest Status:	Not reported
Trans1 State ID:	PAAH0317
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/1996
Trans1 Recv Date:	05/13/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/1996
Part A Recv Date:	Not reported

DAVIDSON PIPE SUPPLY CO INC (Continued) **S103238598**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000011544
Trans1 EPA ID:	PAD982661381
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	45960
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	PAE6007724
Manifest Status:	Not reported
Trans1 State ID:	PAAH0317
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/1996
Trans1 Recv Date:	05/13/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000011544
Trans1 EPA ID:	PAD982661381
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

DAVIDSON PIPE SUPPLY CO INC (Continued) **S103238598**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	44620
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	PAE6007735
Manifest Status:	Not reported
Trans1 State ID:	PAAH0317
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/1996
Trans1 Recv Date:	05/13/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000011544
Trans1 EPA ID:	PAD982661381
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	43280
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	PAE6007746

DAVIDSON PIPE SUPPLY CO INC (Continued) **S103238598**

Manifest Status:	Not reported
Trans1 State ID:	PAAH0317
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/1996
Trans1 Recv Date:	05/13/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000011544
Trans1 EPA ID:	PAD982661381
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	45180
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	PAE6008085
Manifest Status:	Not reported
Trans1 State ID:	PAAH0317
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/1996
Trans1 Recv Date:	05/14/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000011544
Trans1 EPA ID:	PAD982661381
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported

DAVIDSON PIPE SUPPLY CO INC (Continued) **S103238598**

Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	44860
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	PAE6008096
Manifest Status:	Not reported
Trans1 State ID:	PAAH0317
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/1996
Trans1 Recv Date:	05/14/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000011544
Trans1 EPA ID:	PAD982661381
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	LEAD
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported

DAVIDSON PIPE SUPPLY CO INC (Continued) **S103238598**

Waste Code 6:	Not reported
Quantity:	44240
Units:	Pounds
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
21 additional NY MANIFEST: record(s) in the EDR Site Report.

AI285 **OHANNA APARTMENT BUILDING** **NY LTANKS** **S107658846**
WSW **4420 3RD AVE** **N/A**
1/4-1/2 **BROOKLYN, NY 11220**
0.264 mi.
1396 ft. **Site 3 of 3 in cluster AI**

Relative:
Lower

Actual:
33 ft.

LTANKS:

Name:	OHANNA APARTMENT BUILDING
Address:	4420 3RD AVE
City,State,Zip:	BROOKLYN, NY 11220
Spill Number/Closed Date:	0514696 / 2006-07-26
Facility ID:	0514696
Site ID:	361487
Spill Date:	2006-03-22
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2006-03-23
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-23
Spill Record Last Update:	2006-08-17
Spiller Name:	ALICE OHANNA
Spiller Company:	OHANNA HOME
Spiller Address:	4420 3RD AVE
Spiller County:	001
Spiller Contact:	ALICE OHANNA
Spiller Phone:	(718) 851-1328
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	311708
DEC Memo:	3/24/06 - Raphael Ketani. I finally made contact with someone at the super's phone at (718) 851-1328. I had been trying since yesterday. Maria, a maintenance worker there, answered and said that Ms. Ohanna wasn't in, but would be back in the afternoon. I asked her if there were any odors in the building and she said she didn't smell

OHANNA APARTMENT BUILDING (Continued) **S107658846**

anything. I asked her about the oil spill and she said she wasn't aware of any oil spill or any problems with the heat. I asked Maria where I can send a letter that would reach Ms. Ohanna. She said to send it to P.O. Box 200289, Brooklyn, 11220. I told her that I will make a site visit at 2PM and that I wanted access to the basement. She said that she will let Ms. Ohanna know. I made the site visit. The odors were very strong (22 ppm) in the area of the twin 275 gallon tanks. However, there was only a slight indication that anything had ever spilled due to the absorbent sand on the floor below the front of the tanks. Ms. Ohana said that the service guy from Edward T. Miner Fuel Co. had stepped on a valve to one of the tanks and broke it. Later, I spoke to Mr. Chris Paulsen of the E.T. Miner Fuel Co. He said that there had been a leak from a broken cross over pipe and his crew had been over to repair it. He added that two days before, the tanks had held a large quantity of oil, but later they were dry. He suspected a 300 gal. loss. 4/24/06 - Raphael Ketani. I contacted Ms. Ohanna. I asked her what was the status of the cleanup. She said that her husband cleaned up all of the absorbent material and there is no odor. I told her I wanted to check and see for myself. She said that would be alright and she will call me with a date and time this week that would be good for her for a site visit. 5/17/06 - Raphael Ketani. I called Ms. Ohana and made an appointment for a site visit on 5/22 at 10:30AM. 5/22/06 - Raphael Ketani. I made a site visit at 10:15AM today. Ms. Ohana showed me that the oil company had come to her basement, cleaned up the spent Speedi Dri and had cemented over the floor under and around the tanks. I still detected 3900 ppb of volatiles with the PID. I told her that, to start, at least several soil borings and soil samplings have to be done around the tanks - and then maybe bioremediation. She said she has no money to do the work. I explained to her to contact either the oil company's or her own insurance to possibly get them to hire someone. She said she will try. 5/23/06 - Raphael Ketani. I received a call from Ms. Ohana. She said that she had all of the oil system piping replaced because her new oil company told her that E.T. Miner Fuel didn't do the job right and that the oil was still leaking out. She asked me to take a look at the pipes and close the case. She said she has no money to do the borings. I told her that the issue wasn't the pipes, but the estimated 300 gals. of oil that leaked into the ground below the tanks. I asked her for the phone number of E.T. Miner Fuel (718) 439-5066 and spoke to Karen at Miner Fuel. She passed me to Christopher of Miner Fuel. He explained that he tried to work with her, but she didn't want to pay for an investigation and remediation. 5/24/06 - Raphael Ketani. I called Ms. Ohana and talked to her about having one soil sample taken above the water table, instead of a series of borings and samples. I told her the sample needs to be taken to find out if her oil spill reached the water table. I gave her a list of contractors over the phone without prefering anyone. She said she was willing to do this and that she will get back to me when she finds a contractor. 5/25/06 - Raphael Ketani. I received a message from Ms. Ohana and returned her call. She said she contacted an environmental company from the list I had given her regarding doing one soil boring and taking one soil sample. She said they wanted $3000. She said she doesn't have that kind of money and that I am driving her out of business. She claimed she may have to take out a loan and she needs the money to fix up her building. She asked that I come to her building one more time with the PID. She said I will not find any odors now as she and her

OHANNA APARTMENT BUILDING (Continued) **S107658846**

husband have used ammonia and the deoderant powder and have cleaned everything up. I tried to explain to her, though she didn't seem to grasp the idea, that the issue is oil in the ground, not vapors. I told her I still needed one soil sample and to call Eastmond & Son who, I told her, were willing to give her a good price. I asked her whether she will call Eastmond, but she didn't respond to my question. She asked whether she can have her husband do the drilling and take the sample themselves to a laboratory. I told her that wouldn't be satisfactory as it has to be a sample taken with clean sampling equipment. I told her to call Eastmond, but she seemed to be more agitated. With that, she hung up the phone. 5/26/06 - Raphael Ketani. I sent a letter to Ms. Ohana explaining what she needs to do as the next step in the spill investigation and that the state will do the work if she doesn't and back bill her. 6/5/06 - Raphael Ketani. Received a call from Dennis Femia of NYC HPD (718) 802-4506. He asked what the situation in the building's basement was and what happened with the oil. I told him and he said Ms. Ohana takes his Section 8 clients so he will try to help her. I spoke to Mr. Mungra of Eastmond after this. He said he will do one boring tomorrow in her basement. He will go down 4 feet and take a sample. If it's clean he'll stop if it's dirty he'll try at 6 feet down and then maybe 8 feet. 7/5/06 - Raphael Ketani. I left a message for Isaac of Eastmond (718) 378-3000 to call me regarding the results of the soil boring. 7/18/06 - Raphael Ketani. I spoke to Isaac of Eastmond. He said that he has the soil sample analytical results. He said he will FAC them to me. 7/20/06 - Raphael Ketani. I tried calling Isaac, but could only leave a message on his cell phone (646) 879-6703. 7/26/06 - Raphael Ketani. I received a FAX today from Isaac of Eastmond with the analytical results for the one soil boring that was taken. There were no VOC hits, and the SVOC hits were either below TAGM or just slightly above it. Based upon this document and the documents in the record, I am closing this case. 8/17/06 - Raphael Ketani. Ms. Ohanna called up to inquire as to whether the spill case was closed. I told her it was. She asked for a DEC letter stating that the spill case is closed. I sent her one today.

Remarks: oil company deleivered fuel here two days ago and then customer called last night abnd said they were out of fuel: cross over split:

All Materials:

Site ID:	361487
Operable Unit ID:	1119621
Operable Unit:	01
Material ID:	2109065
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	300.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AL286
SSW
1/4-1/2
0.271 mi.
1431 ft.

APRT
461 46TH STREET
BROOKLYN, NY 11220

Site 2 of 2 in cluster AL

NY LTANKS **S109064111**
N/A

Relative:
Higher

Actual:
105 ft.

LTANKS:

Name:	APRT
Address:	461 46TH STREET
City,State,Zip:	BROOKLYN, NY 11220
Spill Number/Closed Date:	0711703 / 2008-06-03
Facility ID:	0711703
Site ID:	393223
Spill Date:	2008-02-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2008-02-06
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-02-06
Spill Record Last Update:	2008-06-03
Spiller Name:	CARMEN SANDATAGO
Spiller Company:	APRT
Spiller Address:	461 46TH STREET
Spiller County:	001
Spiller Contact:	CARMEN SANDATAGO
Spiller Phone:	(646) 673-6714
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	342839
DEC Memo:	2/13/08 Called Ms. Carmen Santiago (646)673-6714. Left message on machine to call me back. Sent ttf letter to: Carmen Santiago The Dermot Company Inc. 320 West 57th Street, 5th Floor New York, NY 10019 Spoke with Bob Urban of Pro Test. Proposal sent to repair. Believes failure is due to vent line. bf 3/27/08 Recieved fax on 3/18/08 from Ted Dros of Protest. They have been hired as the contractor to make repairs. bf 6/3/08 Received letter from Robert Urban of Pro Test. Re-gasketed and re-bolted manhole cover. Tank passed test 4/10/08 (test report attached). No contamination found. NFA. bf
Remarks:	DRY LEAK

All TTF:

Facility ID:	0711703
Spill Number:	0711703
Spill Tank Test:	2384629
Site ID:	393223
Tank Number:	Not reported
Tank Size:	5000

APRT (Continued) **S109064111**

Material:	Not reported
EPA UST:	Not reported
UST:	False
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	393223
Operable Unit ID:	1150191
Operable Unit:	01
Material ID:	2140778
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AN287 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S100145020**
NNE **34TH ST / 4TH AVE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.275 mi.
1453 ft. **Site 7 of 7 in cluster AN**

Relative:
Lower

Actual:
21 ft.

LTANKS:

Name:	CLOSED-LACKOF RECENT INFO
Address:	34TH ST / 4TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8710694 / 2003-03-13
Facility ID:	8710694
Site ID:	175406
Spill Date:	1988-03-11
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1988-03-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False

CLOSED-LACKOF RECENT INFO (Continued) **S100145020**

Remediation Phase:	0
Date Entered In Computer:	1988-03-24
Spill Record Last Update:	2003-03-13
Spiller Name:	Not reported
Spiller Company:	GREENWOOD CEMETERY CO.
Spiller Address:	34TH & 4TH AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	147459
DEC Memo:	Not reported
Remarks:	LEAKING AT UNKNOWN RATE-33YEAR OLD TANK -5,000 GALLON TANK TO REMOVE FUEL AND TANK-ARE PUTTING IN GAS LINE. CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS.

All TTF:

Facility ID:	8710694
Spill Number:	8710694
Spill Tank Test:	1533479
Site ID:	175406
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	175406
Operable Unit ID:	915533
Operable Unit:	01
Material ID:	462454
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

AO288 **SHOW AUTO SALES -MTBE** **UST FINDER RELEASE** **1029060390**
NW **4001 SECOND AVE** **N/A**
1/4-1/2 **BROOKLYN, NY 0**
0.290 mi.
1531 ft. **Site 1 of 3 in cluster AO**

Relative: **Lower**
Actual: **16 ft.**

UST FINDER RELEASE:

Object ID:	255765
Facility ID:	NY148744
Lust ID:	NY102446
Name:	SHOW AUTO SALES -MTBE
Address:	4001 SECOND AVE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	2001/06/04 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	2877
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-74.01107
Y Coord:	40.6546200000001
Latitude:	40.65462
Longitude:	-74.01107

AO289 **COMADORE MANUFAC** **NY LTANKS** **S109064189**
NW **3913 2ND AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.291 mi.
1536 ft. **Site 2 of 3 in cluster AO**

Relative: **Lower**
Actual: **14 ft.**

LTANKS:

Name:	COMADORE MANUFAC
Address:	3913 2ND AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0713359 / 2008-09-08
Facility ID:	0713359
Site ID:	395096
Spill Date:	2008-03-18
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial

COMADORE MANUFAC (Continued) **S109064189**

Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2008-03-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-03-18
Spill Record Last Update:	2008-09-08
Spiller Name:	HARRY GELB
Spiller Company:	COMADORE MANUFAC
Spiller Address:	3913 2ND AVE
Spiller County:	001
Spiller Contact:	HARRY GELB
Spiller Phone:	(718) 788-2600
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	344636
DEC Memo:	4/1/08 bf: Called Harry Gelb (718)788-2600. He is not sure of why tank failed. he believes it may have been caused when the driveway was repaved. I confirmed mailing contact and address. Mr. Damast is owner of the building. Told him he can register both tanks for 2-608583 and 2-608582 under one registration since they are on same property. Address for site location for 2-608582 is incorrect and is the mailing address. I told him this needs to be corrected. Sent ttf letter to: Abraham Damast 3913 2nd Ave. Realty LLC 4312 2nd Avenue Brooklyn, NY 11232 09/05/08-Hiralkumar Patel. received call from Isaac from Eastmond. he mentioned that they did isolation test and found tank, fill line and supply/return lines tight. they found problem in vent pipe. asked Isaac to submit isolation test result. 9/8/2008 Isaac submitted a writeup listing the work done and there was no contamination found. Tank was closed in place. See attached eDocs report.
Remarks:	Not reported

All TTF:

Facility ID:	0713359
Spill Number:	0713359
Spill Tank Test:	2384858
Site ID:	395096
Tank Number:	Not reported
Tank Size:	5000
Material:	Not reported
EPA UST:	Not reported
UST:	True
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported

COMADORE MANUFAC (Continued) **S109064189**

Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 395096
Operable Unit ID: 1152038
Operable Unit: 01
Material ID: 2142811
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

---

290 West 1/4-1/2 0.294 mi. 1552 ft. **BELL ATLANTIC** **UST FINDER RELEASE** **1029056804**
230 43RD ST **N/A**
BROOKLYN, NY 0

Relative: Lower
Actual: 20 ft.

UST FINDER RELEASE:
Object ID: 255737
Facility ID: NY103564
Lust ID: NY9108899
Name: BELL ATLANTIC
Address: 230 43RD ST
City,State,Zip: BROOKLYN, NY 0
Address Match Type: Not reported
Reported Date: 1991/11/19 15:59:59+00
Status: No Further Action
Substance: Not reported
Population within 1500ft: 5116
Domestic Wells within 1500ft: 0
Land Use: Developed, High Intensity
Within SPA: No
SPA PWS Facility ID: Not reported
SPA Water Type: Not reported
SPA Facility Type: Not reported
SPA HUC12: Not reported
Within WHPA: No
WHPA PWS Facility ID: Not reported
WHPA Water Type: Not reported
WHPA Facility Type: Not reported
WHPA HUC12: Not reported
Within 100yr Floodplain: No
Tribe: Not reported
EPA Region: 2
NFA Letter 1: Not reported
NFA Letter 2: Not reported
NFA Letter 3: Not reported
NFA Letter 4: Not reported
Closed With Residual Contaminate: Not reported

BELL ATLANTIC (Continued) **1029056804**

Coordinate Source:	State
X Coord:	-74.0121799999999
Y Coord:	40.65254
Latitude:	40.65254
Longitude:	-74.01218

AP291 **156-170 34TH STREET** **NY LTANKS** **S104275685**
NNE **156-170 34TH STREET** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.294 mi.
1554 ft. **Site 1 of 4 in cluster AP**

Relative: **Lower**

Actual: **17 ft.**

LTANKS:

Name:	156-170 34TH STREET
Address:	156-170 34TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9210902 / 1993-02-25
Facility ID:	9210902
Site ID:	114462
Spill Date:	1992-12-21
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1993-02-25
SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1992-12-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-12-22
Spill Record Last Update:	2003-12-23
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	99823
DEC Memo:	Not reported
Remarks:	TANK BENEATH BUILDING-POST-=SALE SITE ASSESSMENT DONE-DISCOVERED CONTAMINATED BETWEEN 1 1/2 -13 FEET SAMPLES TAKEN AND TESTED RESULTS JUST OBTAINED REQUEST CALLBACK ASAP

All Materials:

Site ID:	114462
Operable Unit ID:	975074
Operable Unit:	01
Material ID:	404339
Material Code:	0001A

156-170 34TH STREET (Continued) **S104275685**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AP292 **NABISCO CO - LIFESAVERS BROOKLYN** **RCRA-VSQG** **1001113387**
NNE **170 34TH ST** **NY LTANKS** **NYR000023770**
1/4-1/2 **BROOKLYN, NY 11232** **NY Spills**
0.295 mi. **FINDS**
1555 ft. **Site 2 of 4 in cluster AP** **ECHO**
NY MANIFEST

Relative:
Lower

Actual:
18 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Nabisco Co - Lifesavers Brooklyn
Handler Address:	34TH ST
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYR000023770
Contact Name:	KEN MILMAN
Contact Address:	34TH ST
Contact City,State,Zip:	BROOKLYN, NY 11232
Contact Telephone:	718-768-7900
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	34TH ST
Mailing City,State,Zip:	BROOKLYN, NY 11232
Owner Name:	Nabisco Inc
Owner Type:	Private
Operator Name:	Nabisco Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NABISCO INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	7 CAMPUS DR
Owner/Operator City,State,Zip:	PARSIPPANY, NJ 07054-0311
Owner/Operator Telephone:	201-682-5000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: NABISCO INC	
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	7 CAMPUS DR
Owner/Operator City,State,Zip:	PARSIPPANY, NJ 07054-0311

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

Owner/Operator Telephone: 201-682-5000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NABISCO INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 7 CAMPUS DR
Owner/Operator City,State,Zip: PARSIPPANY, NJ 07054-0311
Owner/Operator Telephone: 201-682-5000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NABISCO INC
Legal Status: Private
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 7 CAMPUS DR
Owner/Operator City,State,Zip: PARSIPPANY, NJ 07054-0311
Owner/Operator Telephone: 201-682-5000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20030109
Handler Name: NABISCO CO - LIFESAVERS BROOKLYN
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NABISCO CO - LIFESAVERS BROOKLYN
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

Handler Name: NABISCO CO - LIFESAVERS BROOKLYN
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960511
Handler Name: NABISCO CO - LIFESAVERS BROOKLYN
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20040708
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYYWG
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

LTANKS:

Name:	170 34TH STREET
Address:	170 34TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9211737 / 1993-02-01
Facility ID:	9211737
Site ID:	171962
Spill Date:	1992-12-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1993-02-01
SWIS:	2401
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1993-01-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-01-14
Spill Record Last Update:	1994-03-18
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	144730
DEC Memo:	Not reported
Remarks:	AT TIME SUSPECTED TILTED TANK ANOTHER COMPANY DID TEST AND FOUND CONATAMINATED SOIL-NO FURTHER TANK TEST DONE BY CALLER EXPECT TO PULL TANK

All TTF:

Facility ID:	9211737
Spill Number:	9211737
Spill Tank Test:	1541058
Site ID:	171962
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	171962
Operable Unit ID:	976183
Operable Unit:	01
Material ID:	405119
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

SPILLS:

Name:	NYC HIGH SCHOOL
Address:	170 34TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0703584 / 2007-06-27
Facility ID:	0703584
Facility Type:	ER
DER Facility ID:	144730
Site ID:	383556
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

SWIS:	2401
Spill Date:	2007-06-27
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	2007-06-27
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-06-27
Spill Record Last Update:	2007-07-05
Spiller Name:	SANJAY SHARMA
Spiller Company:	NYC HIGH SCHOOL
Spiller Address:	170 34TH STREET
Spiller Company:	999
Contact Name:	SANJAY SHARMA
DEC Memo:	SOIL BORINGS SHOWED CONTAMINATION:
Remarks:	06/27/07-Hiralkumar Patel. spoke with Mr. Sharma. this is same site which he reported earlier (old spill #: 0613263). they did borings on property along 34ths street and found soil and groundwater contamination. asked Mr. Sharma to send all analytical data (for all samples done on-site till date) and detailed scaled site map with all sampling locations, tank locations and associated lines. also asked Mr. Sharma to send copy of phase I and phase II reports. case closed. refer to Spill #: 0613263.

All Materials:

Site ID:	383556
Operable Unit ID:	1140897
Operable Unit:	01
Material ID:	2131009
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	SUNSET PARK HIGH SCHOOL
Address:	170 34TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0613263 / 2008-07-09
Facility ID:	0613263
Facility Type:	ER
DER Facility ID:	333284
Site ID:	378267
DEC Region:	2
Spill Cause:	Human Error

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

Spill Class:	C4
SWIS:	2401
Spill Date:	2007-03-10
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	2007-03-10
CID:	72
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-03-12
Spill Record Last Update:	2008-07-11
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MIKE SHERWOOD
DEC Memo:	School under construction; underground tank was hit. Tank was emptied and removed, as well as contaminated soil. Area was backfilled and end point sample was taken from excavation.
Remarks:	03/12/07-Hiralkumar Patel. spoke with Mr. Sharma. they were hired by contractor who is working at school construction site. site owned by NYC shcool authority. during construction activities, they hit underground tank and punched hole in it. as per Mr. Sharma, tank was about 1000 gal capacity and had about 800 gal diesel in it. spill started about 7:30 am and Mr. Sharma reached with crew for cleanup about 10 am. they have removed underground diesel tank and removed associated contaminated soil. they dug about two ft below tank invert. excavation was backfilled with five endpoint sample taken. asked Mr. Sharma to submit site plan with sampling locations, disposal manifests and sample analyticals. 03/27/07-Hiralkumar Patel. received call from Amy Fonpana (845-492-3178). they are preaparing closure report and will send by 04/15/07. 04/24/07-Hiralkumar Patel. spoke with Ms. Fonpana. they are still waiting for some disposal manifests and other documents. she will send report soon. 06/19/07-Hiralkumar Patel. left message for Ms. Fonpana. 06/26/07-Hiralkumar Patel. received message from Ms. Fonpana. they are still working on-site and waiting for some documents. will send report once they get all documents. 06/27/07-Hiralkumar Patel. Mr. Sharma reported another spill at same site. (new spill #: 0703584). they did borings on property along 34th street and found soil and groundwater contamination. Mr. Sharma mentioned that site had multiple tanks. asked Mr. Sharma to send all analytical data (for all samples done on-site till date) and detailed scaled site map with all sampling locations, tank locations and associated lines. also asked Mr. Sharma to send copy of phase I and phase II reports. 06/28/07-Hiralkumar Patel. meet Bob Kanaparthi and Drew Pardus from NYC SCA and Michael Sherwood from Shaw environmental. Mr. Sherwood mentioned that school construction site is combination of two sites known as large parcel and small parcel. received phase I and Phase II

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

reports from Mr. Sherwood. abstract of Phase I: - the site is located in mixed commercial/residential area on the corner of 4th ave and 35th street - previous occupants of the site included private residences, a stationer, tool manufacturing facility, a garage and candy manufacturing. - large parcel of site had 5000 gal tank and history of spills (9210902, 9605304, 9211737) - site is approx. 20 ft above mean sea level - BASED ON phase II investigations conducted by Weston for the McDonalds restaurant site located at 968 4th ave, the depth of groundwater is approx. 37 ft bg and groundwater flow direction is to the northeast. <---------- - major spill sites in neighbourhood: 1. Greenwood Cemetery (Spill #s: 8710384, 8710694, 8902953, 9413808). all spill closed 2. Jackie Gleason Bus Depot (Spill #s: 9106350, 9507015, 9705882, 9803068, 9902851, 9908589, 0211807, 0402205, 0413523, 0702197) 3. 971-975 4th ave (spill #: 9207015). groundwater contamination reported <------ 4. Mobile service station, 89-14 4th ave (Spill #s: 0430002, 0330037, 8302631) reported groundwater contamination <---------- 5. 987 4th AVe (spill #: 8706481). found groundwater contamination. abstract of Phase II report: - proposed design for school includes construction to a depth of approx. 18 ft bg - depth of groundwater was found to range from between 14 and 24 ft bg - total of 13 soil samples (LPB-1 to LPB-8, SPB-2,5,6,7 and 8) and 7 groundwater samples (LPB-1W, 5W and 8W, SPB-5,6,7 and 8)were collected for analysis - found heavy Tricholorethene (160,000 ppb) contamination in groundwater sample SPB-5 <------ - as found heavy TCE contamination in groundwater sample, did suplemental phase II - collected two soil sample from two borings (close to previous boring location SPB-5) and three groundwater sample from same two borings on-site and four groundwater sample from two off-site borings - also took 6 sub-slab soil-gas samples, because of heavy TCE contamination - found no contamination in any soil, groundwater or soil-gas samples during supplemental phase II investigation Michael Sherwood Shaw environemtal PH. (914) 633-9324 (O) (516) 650-5290 (C) Fax (845) 492-3101 email: michael.sherwood@shawgrp.com Bob Kanaparthi NYC SCA Ph. (718) 472-8620 Drew Pardus NYC SCA Ph. (718) 752-5036 (O) (646) 577-8280 (C) during meeting Mr. Kanaparthi mentioned following: - entire site has been excavated to depth of 16 ft and groundwater is about two more feet deeper than existing excavation bottom. - during excavation, they removed total of five USTs (one 2000 gal fuel oil/diesel tank, one 1000 gal sugary mix tank, one 5000 gal tank, one 100 gal tank and one 1000 gal tank). - found contaminated soil around some tanks and has been removed - endpoint samples taken from contaminated zones - currently footing work for proposed building is going on at site - during construction found sheen on groundwater and gasoline odor - took groundwater samples from two different locations - found minor benzene (58 ppb) contamination in groundwate sample GW-1, along 35th street <--- - there will be two elevator pits, partially merged in groundwater - to work on elevator pit, they need to dewater those areas - due to high concentration of TCE in groundwater sample during first set of sampling, they will put vapor barrier and active SSDS under BASEMENT floor asked Mr. Pardus to do following: - installation of atleast three monitoring wells to define site specific groundwater flow direction and sampling soil and groundwater during this monitoring well installation. - samples must be analyzed for STARS 8260 & 8270 methods & report must include chlorinated compounds - no dewatering events until site-specific groundwater flow direction has defined (to prevent spreading

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

contamination if dewatering points are downgradient to source of contamination) - no concrete/foundation work till full investigation completed - installation of one more monitoring well upgradient (once groundwater flow direction defined) to check any off-site migration - submission of soft copy of vapor barrier & SSDS design - monitoring wells atleast 5 ft below groundwater table - samples from monitoring wells must be taken using Low Sress (low flow) Purging and Sampling procedure (EPA guidance)
--*-

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

data). also asked Mr. Pardus to install a permanent monitoring well on sidewalk along 34th street (close to property line between subject site and park) as subject site is exactly downgradient from contamianted site at 129 34th street. this well will be used as monitoring point to see any oil from 129 34th street site hit construction site or not. Mr. Pardus mentioned that they will install vapor barrier and sub-slab system. Mr. Pardus will schedule installation of one well on sidewalk along 34th street. 03/20/08-Hiralkumar Patel. received tank closure report from Shaw environmental. abstract: - site groundwater was encountered between 16 to 18 ft bg - installed four wells (MW-1, MW-2, MW-4 and MW-5) - no tidal influence noticed in wells MW-1, MW-2 and MW-5, via automatic data logger - groundwater level data from MW-4 shows rise in the water level; cause o fthis water level rise is unknown (no preceipitation or on-site dewatering during or before water level measurement) - direction of groundwater flow from north toward the south and away from the Upper New York Bay; this is opposite of the anticipated direction of groundwater flow based upon the surface topography of the area and the proximity to the Upper New York Bay (0.3 miles northwest) - removed four regulated (petroleum) USTs and one non-regulated (sugar) UST in Mar.-Apr. 2007 - four petroleum tanks removed: one 2000 gal, one 1000 gal, one 5000 gal and one 100 gal - one 1000 gal sugar tank removed - 2000 gal tank was punctured during excvation and then spill reported - 2000 gal UST found to be in fairly good condition with no significant evidence of corrosion - final dimensions of excavation for 2000 gal UST measured approx. 15 ft wide by 20 ft long by 20 ft deep; after collection of endpoint samples, excavation backfilled - 100 gal UST was dicovered immeidately beneath the concrete slab of the former site building - 100 gal UST was found to be old and rusted with large openings - following removal of 100 gal UST, no evidence of release was observed; no impacted material was excavated; one bottom endpoint sample collected after tank removal - 5000 gal UST was abandoned-in-place with concrete - 5000 gal UST found to be slightly corroded but no holes were observed - final dimensions of excavation for 5000 gal UST measured approx. 30 ft wide by 50 ft long by 35 ft deep; after collection of endpoint sidewall samples, excavation backfilled - no endpoint bottom samples collected after 5000 gal tank removal <---------- - 1000 gal UST was discovered about 5 ft bg and found to be rusted with a large hole where it appears that the weld seperated <------- - final dimensions of excavation for 1000 gal UST measured approx. 10 ft wide by 15 ft long by 15 ft deep; after collection of endpoint samples, excavation backfilled - groundwater samples collected from one geoprobe GW-1 and four monitoring wells (MW-1, MW-2, MW-4 and MW-5) - found some SVOC contamination in endpoint soil samples and some VOC contamination in groundwater samples - school design includes a vapor barrier and an active SSDS 06/03/08-Hiralkumar Patel. spoke with Mr. Pardus. he doesn't know about construction status. asked him to submit soft copy of vapor barrier and SSDS design for review by NYS DOH, prior to installation of such. 06/06/08-Hiralkumar Patel. during site visit in neighbourhood, pass through subject site and found few floors already developed at the site. no information available whether vapor barrier and active SSDS were installed or not. 06/17/08-Hiralkumar patel. spoke with Mr. Sherwood. asked him about endpoint bottom sample after removal of 5000 gal tank and design specification of vapor barrier and SSDS. left message for Mr. Pardus for following: - submission of

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

design specs of vapor barrier and SSDS - confirmation about installation of vapor barrier and SSDS - clarification for not taking endpoint bottom sample after 5000 gal tank removed 06/23/08-Hiralkumar Patel. left message for Mr. Pardus. 07/09/08-Hiralkuamr Patel. received email from Mr. Sherwood with vapor barrier and SSDS design and clarification about not taking endpoint bottom samples after 5000 gal tank removal. as per Mr. Sherwood, Shaw environmental was not on site to witness the removal of the 5,000 gal UST as this work was overseen by GZA Environmental, the consultant to the general contractor. as per GZA, they have indicated that they initially removed the UST but did not collect confirmatory soil samples because they felt that there were some minor impacted soils that needed to be excavated and knew that the Contractor was coming back to this area to excavate for the building foundation. when contractor returned to the area to excavate for the building foundation, they indicated that they excavated contaminated soils down to the watertable at approximately 18 feet below grade, and therefore could not collect bottom soil samples. in June 2007, Shaw conducted a soil and groundwater investigation at the site. during that investigation, collected two water samples in the southwest corner of the building foundation excavation, immediately below the former location of the 5,000 gallon UST. one sample was collected from a temporary geotechnical well (GW-2) already in place at the Site and the other was collected from standing water (SGW-1) that had pooled in that corner of the Site. no contamiantion found in groundwater samples. 5000 gal UST was removed in Apr. 2007 and groundwater samples were taken in June 2007 after contractor removed soil under water table as part of foundation work. based on submitted documents till date, case closed. **see Spill #: 0703584 & 0700836 also as reported to same site.**

All Materials:

Site ID:	378267
Operable Unit ID:	1135769
Operable Unit:	01
Material ID:	2125687
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	NABISCO
Address:	170 34TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9605304 / 1998-03-04
Facility ID:	9605304
Facility Type:	ER
DER Facility ID:	144730
Site ID:	171963
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

SWIS:	2401
Spill Date:	1996-07-24
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1996-07-24
CID:	252
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-07-24
Spill Record Last Update:	1998-03-04
Spiller Name:	ASSIM HANNA
Spiller Company:	NABISCO
Spiller Address:	170 34TH STREET
Spiller Company:	001
Contact Name:	ASSIM HANNA
DEC Memo:	under gound tank that has not been in use was found to have contaminated soil after samples were taken by consultant tank will be closed and left in place
Remarks:	Not reported

All Materials:

Site ID:	171963
Operable Unit ID:	1036181
Operable Unit:	01
Material ID:	348051
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

FINDS:

Registry ID: 110004524907

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters,

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

storers, and disposers of hazardous waste.

~~Click this hyperlink~~ while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001113387
Registry ID:	110004524907
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004524907
Name:	NABISCO INC
Address:	170 34TH ST
City,State,Zip:	BROOKLYN, NY 11232

NY MANIFEST:

EPA ID:	NYR000023770
Country:	USA
Name:	NABISCO CO - LIFESAVERS
Address:	170 34TH ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Zip 4:	Not reported
Location Address 1:	170 34TH ST
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	NABISCO CO - LIFESAVERS
Mailing Contact:	KEN MILMAN
Mailing Address 1:	170 34TH ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11232
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7187687900

Manifest Data:

Document ID:	NJA2782915
Manifest Status:	Not reported
Trans1 State ID:	NJDEP5016
Year:	1998
Trans2 State ID:	Not reported
Generator Ship Date:	04/28/1998
Trans1 Recv Date:	04/28/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/01/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000023770
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	IGNITABLE WASTE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00135
Units:	Pounds
Number of Containers:	003
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	IGNITABLE WASTE
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00335
Units:	Pounds
Number of Containers:	008
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	CORROSIVE WASTE
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00010
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	MERCURY
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00520
Units:	Pounds
Number of Containers:	022
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Recycle
Specific Gravity:	01.00

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

Document ID:	NJA2782915
Manifest Status:	Not reported
Trans1 State ID:	NJDEP5016
Year:	1998
Trans2 State ID:	Not reported
Generator Ship Date:	04/28/1998
Trans1 Recv Date:	04/28/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/01/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000023770
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	MERCURY
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00020
Units:	Pounds
Number of Containers:	001
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	CORROSIVE WASTE
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00010
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 12:	CORROSIVE WASTE
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00025

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 17:	MERCURY
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00005
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NJA3249838
Manifest Status:	Not reported
Trans1 State ID:	NJDEP5016
Year:	2002
Trans2 State ID:	Not reported
Generator Ship Date:	01/08/2002
Trans1 Recv Date:	01/08/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/08/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000023770
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2:	Not reported
Waste Code 3:	Not reported

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00200
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NJA3214732
Manifest Status:	Not reported
Trans1 State ID:	NJDEP5016
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	02/08/2001
Trans1 Recv Date:	02/08/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/08/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000023770
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	IGNITABLE WASTE
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00080
Units:	Pounds
Number of Containers:	002
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	IGNITABLE WASTE
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00050
Units:	Pounds

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	IGNITABLE WASTE
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00150
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00045
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC6937492
Manifest Status:	Not reported
Trans1 State ID:	NY55817JL
Year:	2003
Trans2 State ID:	T854MW
Generator Ship Date:	03/19/2003
Trans1 Recv Date:	03/19/2003
Trans2 Recv Date:	03/21/2003
TSD Site Recv Date:	03/24/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000023770
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00600
Units: Pounds
Number of Containers: 002
Container Type: Fiberboard or plastic drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYC6935433
Manifest Status: Not reported
Trans1 State ID: Not reported
Year: 2003
Trans2 State ID: T473CLNJ
Generator Ship Date: 04/10/2003
Trans1 Recv Date: 04/10/2003
Trans2 Recv Date: 04/15/2003
TSD Site Recv Date: 04/17/2003
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000023770
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: NJD071629976
TSDF ID 1: KYD053348108
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: IGNITABLE WASTE
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 02760
Units: Pounds
Number of Containers: 006

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	IGNITABLE WASTE
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00150
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NJA2966628
Manifest Status:	Not reported
Trans1 State ID:	NJDEP5016
Year:	1998
Trans2 State ID:	Not reported
Generator Ship Date:	10/02/1998
Trans1 Recv Date:	10/02/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/02/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000023770
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

Waste Code 6:	Not reported
Quantity:	00095
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	MERCURY
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00175
Units:	Pounds
Number of Containers:	007
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 12:	MERCURY
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00050
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NJA3065809
Manifest Status:	Not reported
Trans1 State ID:	NJDEP5016
Year:	1999
Trans2 State ID:	Not reported
Generator Ship Date:	10/06/1999
Trans1 Recv Date:	10/06/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/06/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000023770
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00400
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	MERCURY
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00210
Units:	Pounds
Number of Containers:	002
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Document ID:	NJA3096949
Manifest Status:	Not reported
Trans1 State ID:	NJDEP5016
Year:	2000
Trans2 State ID:	Not reported
Generator Ship Date:	10/20/2000
Trans1 Recv Date:	10/20/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/20/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000023770
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00320
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC6829446
Manifest Status:	Not reported
Trans1 State ID:	NJX9693L
Year:	2002
Trans2 State ID:	Not reported
Generator Ship Date:	06/18/2002
Trans1 Recv Date:	06/18/2002
Trans2 Recv Date:	06/20/2002
TSD Site Recv Date:	06/25/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000023770
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00460
Units: Pounds
Number of Containers: 001
Container Type: Fiberboard or plastic drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NJA3065772
Manifest Status: Not reported
Trans1 State ID: NJDEP5016
Year: 2000
Trans2 State ID: Not reported
Generator Ship Date: 06/08/2000
Trans1 Recv Date: 06/08/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/08/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000023770
Trans1 EPA ID: NJD080631369
Trans2 EPA ID: Not reported
TSDF ID 1: NJD980536593
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT

NABISCO CO - LIFESAVERS BROOKLYN (Continued) **1001113387**

MIXTURES.

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00200
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	MERCURY
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00075
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 12:	MERCURY
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00050
Units:	Pounds
Number of Containers:	002
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 17:	LEAD
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00150
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
10 additional NY MANIFEST: record(s) in the EDR Site Report.

AP293 **34TH ST & 4TH AVE/BKLYN** **NY LTANKS** **S100145009**
NE **34TH ST & 4TH AVE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.300 mi.
1583 ft. **Site 3 of 4 in cluster AP**

Relative:
Lower

Actual:
20 ft.

LTANKS:

Name:	34TH ST & 4TH AVE/BKLYN
Address:	34TH ST & 4TH AVE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8710384 / 1992-09-30
Facility ID:	8710384
Site ID:	151245
Spill Date:	1988-03-11
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B4
Cleanup Ceased:	1992-09-30
SWIS:	2401
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1988-03-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-03-14
Spill Record Last Update:	1994-05-12
Spiller Name:	Not reported
Spiller Company:	GREENWOOD CEMETERY
Spiller Address:	34TH ST & 4TH AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	128548
DEC Memo:	Not reported
Remarks:	5K TANK FAILED TEST WITH UNREADABLE RATE, TO EXCAVATE, ISOLATE AND RETEST.

All TTF:

Facility ID:	8710384
Spill Number:	8710384
Spill Tank Test:	1533421
Site ID:	151245
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

34TH ST & 4TH AVE/BKLYN (Continued) **S100145009**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 151245
Operable Unit ID: 916090
Operable Unit: 01
Material ID: 462153
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Resource Affected: Groundwater
Oxygenate: Not reported

AP294 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S100145469**
NE **34TH ST / 4TH AVE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.300 mi.
1583 ft. **Site 4 of 4 in cluster AP**

Relative:
Lower

Actual:
20 ft.

LTANKS:
Name: CLOSED-LACKOF RECENT INFO
Address: 34TH ST / 4TH AVE
City,State,Zip: NEW YORK CITY, NY
Spill Number/Closed Date: 8902953 / 2003-03-04
Facility ID: 8902953
Site ID: 175407
Spill Date: 1989-06-21
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: A3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: ADMIN. CLOSED
Referred To: Not reported
Reported to Dept: 1989-06-21
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1989-06-23
Spill Record Last Update: 2003-03-04
Spiller Name: Not reported
Spiller Company: GREENWOOD CEMETERY
Spiller Address: 34TH ST & 4TH AVENUE
Spiller County: 001
Spiller Contact: Not reported

CLOSED-LACKOF RECENT INFO (Continued) **S100145469**

Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 279765
DEC Memo: Not reported
Remarks: (2) 550 GALLON TANKS FAILED HORNER EZY CHECK WITH A LEAK RATE OF -.062GPH CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS.

All TTF:
Facility ID: 8902953
Spill Number: 8902953
Spill Tank Test: 1535617
Site ID: 175407
Tank Number: Not reported
Tank Size: 0
Material: 0009
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 175407
Operable Unit ID: 930363
Operable Unit: 01
Material ID: 450625
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Resource Affected: Groundwater
Oxygenate: Not reported

---

295 ESE 1/4-1/2 0.300 mi. 1586 ft. **FORMER GETTY S/S #98502 - GETTY MARKETING** **UST FINDER RELEASE** **1029058185**
602 39TH ST **N/A**
BROOKLYN, NY 0

Relative: Higher
Actual: 128 ft.

UST FINDER RELEASE:
Object ID: 255991
Facility ID: NY121263
Lust ID: NY9905769
Name: FORMER GETTY S/S #98502 - GETTY MARKETING
Address: 602 39TH ST
City,State,Zip: BROOKLYN, NY 0
Address Match Type: Not reported

FORMER GETTY S/S #98502 - GETTY MARKETING (Continued) **1029058185**

Reported Date:	1999/08/13 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	8922
Domestic Wells within 1500ft:	3
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-74.0015799999999
Y Coord:	40.6498
Latitude:	40.6497999999999
Longitude:	-74.00158

AO296 **22-36 SECOND AVENUE** **NY BROWNFIELDS** **S117936671**
NW **22-36 SECOND AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11215**
0.308 mi.
1627 ft. **Site 3 of 3 in cluster AO**

Relative:
Lower

Actual:
12 ft.

BROWNFIELDS:

Name:	22-36 SECOND AVENUE
Address:	22-36 SECOND AVENUE
City,State,Zip:	BROOKLYN, NY 11215
Program:	BCP
Site Code:	507964
Acres:	1.090
HW Code:	C224227
SWIS:	2401
Town:	New York City
Record Added Date:	05/15/2015
Record Updated Date:	09/27/2023
Update By:	HMDUDEK
Site Description:	Location: The 22-36 Second Avenue site is a one-acre site located in an urban area, in the Gowanus area of Brooklyn, New York (Kings County). The site is bounded by 5th Street to the North, Second Avenue to the east, and the Gowanus Canal to the south and west. Site Features: The site is flat and has four one-story buildings which cover most of the site. Current Zoning and Land Use(s): The site is located in an M2-1 manufacturing district. The site is currently occupied by a metal shop, a wood shop, a food distributer and a clothing distributer. Past Use of the Site: Past uses of the site

22-36 SECOND AVENUE (Continued) **S117936671**

include sulfur works; manure dump; operations and storage of various materials, including cement, asphalt, paint, cork materials, finishing and cutting; cork slab plant; iron oven; and a switch house. Five petroleum spills were reported on the site between 1994 and 2015. One spill, reporting gross soil contamination and free-phase petroleum-like material in soils, is currently open. Site Geology and Hydrogeology: Historic fill extends from the surface cover to depths ranging from 11 to 15 feet below ground surface. The fill generally consists of brown coarse- to fine-grained sand with variable amounts of wood and brick. Below the fill, a layer of native organic clay extends to a depth of 25 to 35 feet below ground surface. The clay is underlain by glacial till. Bedrock occurs at approximately 140 feet below ground surface. Groundwater was observed at about 7 feet below ground surface and is inferred to flow northwest towards the Gowanus Canal.

Env Problem: Soil samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals and pesticides. Based on investigations conducted to date, the primary contaminants of concern include polyaromatic hydrocarbons (PAHs), 4,4-DDT, acetone, trivalent chromium, copper, lead, mercury and zinc. Soils - Soil borings were advanced to a depth of 12 feet below ground surface at three on-site locations. Two samples were taken from each boring. Acetone was found at concentrations up to 1.6 mg/kg (the unrestricted use Soil Cleanup Objective (SCO) is 0.05 mg/kg). The SVOC found at the highest concentration was Benzo(b)fluoranthene at 44 mg/kg (the SCO is 1 mg/kg). Six additional SVOCs were found at maximum concentrations ranging from 4.9 mg/kg to 38 mg/kg. The SCOs for these SVOCs range from 0.33 mg/kg to 1 mg/kg. The pesticide 4,4-DDT was found at concentrations up to 0.018 mg/kg (the SCO is 0.0033 mg/kg). Trivalent Chromium was found at concentrations up to 34 mg/kg (the SCO is 30mg/kg). Copper was found at concentrations up to 2,200 mg/kg (the SCO is 50 mg/kg). Lead was found at concentrations up to 540 mg/kg (the SCO is 63 mg/kg). Mercury was found at concentrations up to 19 mg/kg (the SCO is 0.18 mg/kg). Zinc was found in concentrations up to 710 mg/kg (the SCO is 109 mg/kg).

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Additional investigation is needed to determine whether actions are needed to address soil vapor intrusion on and off-site.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2015-06-02 10:31:00

22-36 SECOND AVENUE (Continued) **S117936671**

Record Upd:	2018-11-29 10:08:00
Updated By:	JXGRECO
Own Op:	6
Sub Type:	P03
Owner Name:	Carter Gray
Owner Company:	Pelagic Capital Advisory, LLC
Owner Address:	c/o Wiggin and Dana LLP
Owner Addr2:	437 Madison Avenue, 35th Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Carroll Gardens Library
Owner Address:	396 Clinton Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	1
Sub Type:	A
Owner Name:	Not reported
Owner Company:	Richard Ribellino
Owner Address:	313 Butler Street
Owner Addr2:	Brooklyn, NY 11217
Owner City,St,Zip:	Brooklyn, NY 11217
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Joseph Jones
Owner Company:	New York State Department of Environmental Conservation
Owner Address:	12th Floor, 625 Broadway,
Owner Addr2:	Not reported
Owner City,St,Zip:	Albany, NY 12233-7015
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Craig Hammerman
Owner Company:	Brooklyn Community Board 6
Owner Address:	250 Baltic Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11201
Owner Country:	United States of America
HW Code:	C224227
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224227
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224227
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224227
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN

22-36 SECOND AVENUE (Continued) **S117936671**

Waste Code:	Not reported
HW Code:	C224227
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224227
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224227
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AQ297 **875 4TH AVENUE** **NY VCP** **S121796985**
NE **875 4TH AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.364 mi.
1924 ft. **Site 1 of 2 in cluster AQ**

Relative: **Lower**
Actual: **22 ft.**

VCP NYC:

Project ID:	16TMP0330K,16EH-A242K,18CVCP013K
Name:	875 4TH AVENUE
Address:	875 4TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	30,068,100,013,006,800,000
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Closure
Latitude:	40.656237
Longitude:	-74.002408
Postcode:	7
Community Board:	38
Council District:	101
Census Tract:	3010094
BIN:	3006810001
NTA:	Sunset Park West

AQ298 **875 4TH AVENUE** **NY Spills** **S110139776**
NE **875 4TH AVENUE** **NY NYC OER** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.364 mi.
1924 ft. **Site 2 of 2 in cluster AQ**

Relative: **Lower**
Actual: **22 ft.**

SPILLS:

Name:	EXXONMOBIL 10019
Address:	875 4TH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0911335 / 2011-04-29
Facility ID:	0911335

875 4TH AVENUE (Continued) **S110139776**

Facility Type:	ER
DER Facility ID:	373087
Site ID:	424135
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2010-01-04
Investigator:	MDMACCAB
Referred To:	Not reported
Reported to Dept:	2010-01-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-01-21
Spill Record Last Update:	2016-06-20
Spiller Name:	KEN DRAKE
Spiller Company:	EXXON 10019
Spiller Address:	875 4TH AVE
Spiller Company:	999
Contact Name:	KEN DRAKE
DEC Memo:	GROUNDWATER SHOWN TO BE EEFECTED BY RELEASE. CLEAN UP UNSURE.
Remarks:	Sangesland spoke to Wendy at Roux Assoc. She said they have been doing Phase 2 investigations at a number of Exxon-Mobil sites in the New York Area. They did soil borings and installed monitoring wells and found contamination. 08/6/10-Farrell-Report review requested by S. Rahman. Spill closure request for Spill #09-11335 by (Kleinfelder East, Inc.-Joel Adrian/Alex Wirth-(845)-567-6530) April 6, 2010 SAR prepared by (Roux Associates, Inc.-Scott Glash/Daren Moss-(800)-322-7689) February 12, 2010 for ExxonMobil Environmental Services Company, Fairfax, VA. Location of interest: ExxonMobil Station No.10019 875 4th Avenue Brooklyn, NY RAI (listed above) evaluated recognized environmental conditions (REC) conducted in 12/08 by Kleinfelder East, Inc. The property consists of an active retail petroleum filling station & convenience store. Residential use structures (east), 33rd Street and further residential and commercial use structures (south), 32nd Street and further residential and commercial use structures (north), & 4th Avenue followed by an automotive repair shop and a drycleaner (west). Ground surface elevation is about 23 above sea level, groundwater found at depths of 24.05-32.19 bgs, southward flow determined. One (1) tank field observation well is a monitoring point at the southwestern side of the tank field. KEI (above) reported no public water-supply wells within 1 mile of the property. REC s include (3) current 12,000 gal gasoline USTs with piping and dispensing units. No former USTs were noted. No previous spill cases associated with the property. RAI began Phase II ESA on 10/13/09 with site-wide GPR survey. One (1) soil boring was advanced & (7) monitoring wells were installed; soil & groundwater samples were taken and analyzed. Results of soil sample analysis included: No VOC or SVOC detect above NYSDEC RSCO. Heavy

875 4TH AVENUE (Continued) **S110139776**

metal detect only. On 12/23/2009 groundwater samples were collected and analyzed, no free-phase product was observed. Field tank observation well (TF-1) was gauged on 10/13/2009. The well was dry with no presence of LPH. Results of groundwater sample analysis included: MTBE detect above its NYSDEC groundwater standard in MW-2 at 876 ppb (12/09) 360 ppb in June 2010. Tetrachloroethene detect above NYSDEC groundwater standard in MW-6: (12.7 ppb) Trichloroethene detect above NYSDEC groundwater standard in MW-5,6 & 7: (22.1 ppb high in MW-6) SVOCs detect in MW-4 & MW-6: Acenaphthene(78ppb) & Bis(2-ethylhexyl) phthalate(10.8 ppb) 10/26/10 - This spill has been assigned to M. MacCabe. 1/25/11 - M. MacCabe - Bolla EM Realty has taken responsibility for site remediation. Arcacis is the new consultant. 4/29/11 - spill closed

All Materials:

Site ID:	424135
Operable Unit ID:	1179929
Operable Unit:	01
Material ID:	2173764
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil, Groundwater
Oxygenate:	Not reported

NYC OER:

Name:	875 4TH AVENUE
Address:	875 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.656237
Longitude:	-74.002408
OER Project Numbers:	16TMP0330K,16EH-A242K,18CVCP013K
BBL:	3.0068100013006799E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Active (A)
Phase:	Closure
URL:	https://a002-epic.nyc.gov/app/workspace/3250/docrepository
Postcode:	7
Community Board:	38
Council District:	101
Census Tract:	3010094
BIN:	3006810001
NTA:	Sunset Park West

AR299 **FGP BUSH TERMINALS** **NY LTANKS** **S102673281**
NW **148 39TH STREET** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.376 mi.
1987 ft. **Site 1 of 3 in cluster AR**

Relative:
Lower

Actual:
10 ft.

LTANKS:

Name:	FGP BUSH TERMINALS
Address:	148 39TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9514887 / 2003-02-24
Facility ID:	9514887
Site ID:	160744
Spill Date:	1996-02-20
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1996-02-21
CID:	205
Water Affected:	Not reported
Spill Notifier:	Federal Government
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-21
Spill Record Last Update:	2003-02-24
Spiller Name:	Not reported
Spiller Company:	FGP BUSH TERMINALS
Spiller Address:	148 39TH STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	135721
DEC Memo:	Not reported
Remarks:	transfer of fuel from one tank to another, overfilled.annon caller.

All Materials:

Site ID:	160744
Operable Unit ID:	1025985
Operable Unit:	01
Material ID:	355005
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AS300 **114 32ND ST AT 3RD AVE.** **NY LTANKS** **S102662567**
NNE **114 32ND ST AT 3RD AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.405 mi.
2139 ft. **Site 1 of 2 in cluster AS**

Relative:
Lower

Actual:
15 ft.

LTANKS:

Name:	114 32ND ST AT 3RD AVE.
Address:	114 32ND ST AT 3RD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9305702 / 2003-10-27
Facility ID:	9305702
Site ID:	167598
Spill Date:	1993-08-09
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	1993-08-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-08-11
Spill Record Last Update:	2003-10-27
Spiller Name:	Not reported
Spiller Company:	DIDA'S SERVICE STATION
Spiller Address:	339 3RD AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	141217
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY Closed 10/27/03 by A.Zhitomirsky
Remarks:	THE RESIDENT COMPLAINED ABOUT PETROLEUM FROM GAS STATION VENTS GETTING INTO HER BACK YARD

All Materials:

Site ID:	167598
Operable Unit ID:	987218
Operable Unit:	01
Material ID:	561690
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

301
WNW
1/4-1/2
0.409 mi.
2160 ft.

COMMODORE MANUFACTURING
140 43RD STREET
BROOKLYN, NY 11232

NY LTANKS **S106703419**
N/A

Relative:
Lower

Actual:
13 ft.

LTANKS:

Name:	COMMODORE MANUFACTURING
Address:	140 43RD STREET
City,State,Zip:	BROOKLYN, NY 11232
Spill Number/Closed Date:	8910578 / 2014-09-19
Facility ID:	8910578
Site ID:	203368
Spill Date:	1990-01-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RVKETANI
Referred To:	091714 REVEIWED INVESTIG TANK CLOSURE REPORT
Reported to Dept:	1990-02-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1990-02-07
Spill Record Last Update:	2014-09-19
Spiller Name:	Not reported
Spiller Company:	SEA JET INC
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	25417
DEC Memo:	3/4/2003: CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS. 5/18/06: Case reopened because high napthalene found in downgradient MW8 on Verizon property. Assessment required letter sent, due back 7/18/06. PBS # 2-603597 5/31/06: Spoke to Commodore Manufacturing. He will send documents regarding legal closure of tanks three years ago. 6/5/06: Received letter with documentation that Action Environmental closed in place a 35,000 gallon heating oil tank that was previously abandoned in place. The tank was noted to have been properly abandoned in the late 1940's. 8/11/06: Spoke with Kevin O'Connor. Two 35,000 gallon USTs were abandoned in place. A third tank was found to be formerly abandoned in place with sand. All three tanks were in parrallel. Soil testing may have been completed by a different company. Contact owner for additional information. Called Abraham Damast (718-788-2600), he was not in the office. 8/21/06: Called Abraham Damast, the line was busy. 8/25/06: Left message with Abraham Damast's secretary to see if he has additional information regarding the tank removal/abandonment. 9/27/06: Sent letter to Abraham Damast requiring sampling results

COMMODORE MANUFACTURING (Continued) **S106703419**

from the abandonment which occurred in September 2004. 10/11/06: Downgradient Verizon site Spill 9108899, located directly downgradient of Commodore manufacturing, was closed, although their upgradient well MW8 still shows high napthalene contamination from an unknown upgradient source. Include Verizon's well MW8 in possible future sampling of this plume. 9/16/14 - Raphael Ketani. The spill was opened on 2/6/90 as a result of an integrity test failure for a two tank system. According to the spill report, these were two 550 gal. gasoline USTs. However, there is no documentation indicating that gasoline USTs were ever at the site. The site is owned by 4312 2nd Avenue Realty, LLC (zip code for site address is 11232). The contact is Abraham Damast at 19 Mitchell Drive, Kings Point, NY, 11024. The township for his home is North Hempstead. The general area of Nassau County is Great Neck. The block and lot for the site are 726 and 1. The information above came from a deed dated 12/31/2000 which was found in ACRIS. The PBS registration is #2-603597. It shows three 35,000 gal. USTs. Two had #2 heating oil and one had #6 heating oil. The tanks were closed in place. An investigation and tank closure report was sent on 5/12/99 by Action Remediation Co. It was produced for Action by Advanced Cleanup Technologies and is dated 5/11/99. According to the report, 5 soil borings were performed. There were no PID detections. These borings were turned into wells TW-01 to TW-05. Groundwater samples were collected and analyzed (received by the lab on 4/19/99). All of the results were non-detect. The tanks were cleaned out and abandoned in place. 9/19/14 - Raphael Ketani. I presented the case for closure to Hassan Hussein, EE III and head of Unit C Remediation. He approved the closure. The closure was based on the lack of evidence of soil and groundwater contamination as the PID results were all 0 ppm and the groundwater results were all non-detect for VOCs and SVOCs. The closure was also based upon the letter from Action Remediation Co. indicating that they had abandoned the tanks by cleaning out the tanks and filling them with sand. Considering the information in the case file, it was determined that the spill was not a threat to the public or the environment. The spill case was closed today.

Remarks: (2) 550 GALLON SYSTEM FAILED AIR PRESSURE TEST, NYCFD & OWNER NOTIIFED
Not reported

All TTF:

Facility ID:	8910578
Spill Number:	8910578
Spill Tank Test:	1536749
Site ID:	203368
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

COMMODORE MANUFACTURING (Continued) **S106703419**

All Materials:

Site ID:	203368
Operable Unit ID:	937471
Operable Unit:	01
Material ID:	440149
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

AS302 **882 3RD AVE** **NY LTANKS** **S102402021**
NNE **882 3RD AVENUE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.411 mi.
2169 ft. **Site 2 of 2 in cluster AS**

Relative: **Lower**
Actual: **12 ft.**

LTANKS:

Name:	VIRGINIA DARE EXTRACT COM
Address:	882 3RD AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9614424 / 1997-03-13
Facility ID:	9614424
Site ID:	124122
Spill Date:	1997-03-13
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1997-03-13
CID:	266
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-03-13
Spill Record Last Update:	1997-05-06
Spiller Name:	DONALD KENNEDY
Spiller Company:	VIRGINIA DARE EXTRACT COM
Spiller Address:	882 3RD AVENUE
Spiller County:	001
Spiller Contact:	DONALD KENNEDY
Spiller Phone:	(718) 788-1776
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	107542

882 3RD AVE (Continued) **S102402021**

DEC Memo: Not reported
Remarks: DOMINION BROMINATED VEGETABLE OIL #171. CAS NUMBER 8016-94-2. MATERIAL OVERFLOWED FROM TANK WHILE ADDING BROMINE TO OIL. ONTO CONCRETE FLOOR. BEING CLEANED UP.

All Materials:
Site ID: 124122
Operable Unit ID: 1045814
Operable Unit: 01
Material ID: 339531
Material Code: 0968A
Material Name: bromine
Case No.: 07726956
Material FA: Hazardous Material
Quantity: 5.00
Units: G
Recovered: 5.00
Resource Affected: Soil
Oxygenate: Not reported

SPILLS:
Name: 882 3RD AVE
Address: 882 3RD AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9607381 / 1996-09-11
Facility ID: 9607381
Facility Type: ER
DER Facility ID: 107542
Site ID: 65281
DEC Region: 2
Spill Cause: Unknown
Spill Class: B3
SWIS: 2401
Spill Date: 1996-09-11
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1996-09-11
CID: 349
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1996-09-11
Spill Record Last Update: 1996-09-24
Spiller Name: KEHLER
Spiller Company: VIRGINIA DARE
Spiller Address: 882 3RD AV
Spiller Company: 001
Contact Name: Not reported
DEC Memo: FD ON SCENE - SPILL INSIDE BUILDING - NO OTHER INFO
Remarks: Not reported

882 3RD AVE (Continued) **S102402021**

All Materials:

Site ID:	65281
Operable Unit ID:	1035339
Operable Unit:	01
Material ID:	346647
Material Code:	0968A
Material Name:	bromine
Case No.:	07726956
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AR303 **116 39TH ST/MAGNOLIA IND.** **NY LTANKS** **S102671889**
NW **116 39TH ST/MAGNOLIA IND.** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.415 mi.
2190 ft. **Site 2 of 3 in cluster AR**

Relative: **Lower**
Actual: **9 ft.**

LTANKS:

Name:	116 39TH ST/MAGNOLIA IND.
Address:	116 39TH ST/MAGNOLIA IND.
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9201695 / 1992-05-12
Facility ID:	9201695
Site ID:	288856
Spill Date:	1992-05-11
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1992-05-12
SWIS:	2401
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1992-05-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-12
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	233968

116 39TH ST/MAGNOLIA IND. (Continued) **S102671889**

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG
Remarks: SORBENT APPLIED, PICKED UP & DISPOSED.

All Materials:
Site ID: 288856
Operable Unit ID: 968959
Operable Unit: 01
Material ID: 412994
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

AR304 **116 39TH ST** **NY LTANKS** **S102672710**
NW **116 39TH ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.415 mi.
2190 ft. **Site 3 of 3 in cluster AR**

Relative: **Lower**
Actual: **9 ft.**

LTANKS:
Name: 116 39TH ST
Address: 116 39TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9411889 / 1994-12-06
Facility ID: 9411889
Site ID: 195660
Spill Date: 1994-12-06
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: 1994-12-06
SWIS: 2401
Investigator: KSTANG
Referred To: Not reported
Reported to Dept: 1994-12-06
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1995-01-23
Spill Record Last Update: 2003-08-20
Spiller Name: Not reported
Spiller Company: BUS.
Spiller Address: 116 39TH ST
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported

116 39TH ST (Continued) **S102672710**

Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	163010
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG
Remarks:	OVER ORDER-SPEEDY DRY USED

All Materials:

Site ID:	195660
Operable Unit ID:	1005512
Operable Unit:	01
Material ID:	374229
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

---

305 ESE 1/4-1/2 0.430 mi. 2269 ft. **BIG L EXCAVATING & DEMOLITION** **NY SWF/LF** **S105841895**
701 39 STREET **NY NYC LAND USE** **N/A**
BROOKLYN, NY 11232

Relative: Higher

Actual: 123 ft.

SWF/LF:

Name:	BIG L EXCAVATING & DEMOLITION
Address:	701 39 STREET
City,State,Zip:	BROOKLYN, NY 11232
Flag:	INACTIVE
Region Code:	2
Phone Number:	5162953858
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	BIAGIO LAMBERTI; PRESIDENT
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	z Retired - C&D processing - registration
Activity Number:	[24W16]
Active:	No
East Coordinate:	Not reported
North Coordinate:	Not reported
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported

BIG L EXCAVATING & DEMOLITION (Continued) **S105841895**

Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Not reported
Operator Type: Not reported
Laste Date: Not reported

NYC LAND USE:

Name:	Not reported
Address:	701 39 STREET
City,State,Zip:	BROOKLYN, NY 11232
Latitude:	40.6486937
Longitude:	-73.9991567
Type Of Ownership Code:	Not reported
Owner Name:	BIAGIO LAMBERTI
Borough:	BK
Tax Block:	903
Tax Lot:	77
Community District:	307
Census Tract 2020:	3009001
Census Block 2020:	30090011001
Census Tract 2010:	90
Census Block 2010:	1001
School District:	15
City Council District:	38
Fire Company:	E228
Police Precinct:	72
Health Center District:	39
Health Area:	6600
Sanitation District Boro:	3
Sanitation District Number:	07
Sanitation Subsection:	2D
Zoning District 1:	M1-2: Manufacturing Districts
Zoning District 2:	Not reported
Zoning District 3:	Not reported
Zoning District 4:	Not reported
Commercial Overlay 1:	Not reported
Commercial Overlay 2:	Not reported
Special Purpose District 1:	Not reported
Special Purpose District 2:	Not reported
Special Purpose District 3:	Not reported
Limited Height District:	Not reported
Spill Boundary Indicator:	N
Building Class:	E2: WAREHOUSES - Contractor?s Warehouse
Land Use Category:	Industrial & Manufacturing
Number Of Easements:	0
Lot Area:	8409
Total Building Floor Area:	10496
Commercial Floor Area:	5000
Residential Floor Area:	0
Office Floor Area:	5000
Retail Floor Area:	0
Garage Floor Area:	0
Storage Floor Area:	0
Factory Floor Area:	0
Other Floor Area:	0
Total Building Floor Area Source Code:	2
Number Of Buildings:	1

BIG L EXCAVATING & DEMOLITION (Continued) **S105841895**

Number Of Floors:	2.0000000
Residential Units:	0
Total Units:	2
Lot Frontage:	60.0000000
Lot Depth:	100.1700000
Building Frontage:	50.0000000
Building Depth:	100.0000000
Extension Code:	N
Proximity Code:	2
Irregular Lot Code:	Y
Lot Type:	3
Basement Type/Grade:	1
Assessed Land Value:	140400.00000
Assessed Total Value:	479250.00000
Exempt Total Value:	167760.00000
Year Built:	2004
Year Altered 1:	2009
Year Altered 2:	0
Historic District Name:	Not reported
Landmark Status:	Not reported
Built Floor Area Ratio:	1.25000000000
Maximum Allowable Residential Far:	0.00000000000
Maximum Allowable Commercial Far:	2.00000000000
Maximum Allowable Community Facility Far:	4.80000000000
Boro Code:	3
Borough, Tax Block and Lot:	3009030077.00000000
Condominium Number:	Not reported
Census Tract 2:	0090
X Coordinate:	984484
Y Coordinate:	175613
Zoning Map #:	22c
Zoning Map Code:	Not reported
Sanborn Map #:	306A038
Tax Map #:	30310
E-designation Number:	Not reported
Apportionment BBL:	3009030077.00000000
Apportionment Date:	09/15/1997
Pluto ??? Dtm Base Map Indicator:	1
2007 Flood Insurance Rate Map Indicator:	Not reported
2015 Preliminary Flood Insurance Rate Map Indicator:	Not reported
Version Number:	23v1.1
Changed By DCP:	Not reported

AT306 **BLATCHFORD BASE PLANT** **SEMS-ARCHIVE** **1003863825**
North **32 33RD ST** **NYD980531644**
1/4-1/2 **BROOKLYN, NY 11232**
0.432 mi.
2279 ft. **Site 1 of 2 in cluster AT**

Relative: **Lower**
Actual: **8 ft.**

SEMS Archive:

Site ID:	0201944
EPA ID:	NYD980531644
Name:	BLATCHFORD BASE PLANT
Address:	32 33RD ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232
Cong District:	15
FIPS Code:	36047

BLATCHFORD BASE PLANT (Continued) **1003863825**

FF: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region: 02
Site ID: 0201944
EPA ID: NYD980531644
Site Name: BLATCHFORD BASE PLANT
NPL: N
FF: N
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 1987-09-22 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 02
Site ID: 0201944
EPA ID: NYD980531644
Site Name: BLATCHFORD BASE PLANT
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1981-06-01 04:00:00
Finish Date: 1981-06-01 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0201944
EPA ID: NYD980531644
Site Name: BLATCHFORD BASE PLANT
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: Not reported
Finish Date: 1987-09-22 04:00:00
Qual: N
Current Action Lead: EPA Perf

AT307 **BLATCHFORD BASE PLANT** **NY HSWDS** **S108146438**
North **32 33RD ST.** **N/A**
1/4-1/2 **BROOKLYN, NY 11232**
0.432 mi.
2279 ft. **Site 2 of 2 in cluster AT**

Relative: **Lower**

Actual: **8 ft.**

HSWDS:

Facility ID:	Not reported
Region:	2
Facility Status:	Unknown
Owner Type:	U
Owner:	Unknown
Owner Address:	Unknown
Owner Phone:	Unknown
Operator Type:	Puplic
Operator:	Blatchford Base Plant
Operator:	Blatchford Base Plant
Operator Phone:	Unknown
EPA ID:	NYD980531644
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	None
RCRA Permitted:	Unknown
Site Code:	Industrial Site
Owner City State:	Not reported
Operator City State:	Brooklyn, NY 11232
Quadrange:	Unknown
Latitude:	40 39'20"N
Longitude:	74 00'10"w
Acres:	0.00
Operator Date:	Unknown
Close Date:	Unknown
Completed:	PA
Active:	No
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	No
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	None
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown
Groundwater Contamination:	Unknown
Groundwater Classification:	Unknown
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	Unknown

BLATCHFORD BASE PLANT (Continued) **S108146438**

Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

308
SE
1/4-1/2
0.434 mi.
2292 ft.

SUNSET PARK 7TH AVE/43RD ST **NY LTANKS** **S105054705**
7TH AVE/43RD ST **N/A**
BROOKLYN, NY

Relative:
Higher

Actual:
157 ft.

LTANKS:

Name:	SUNSET PARK 7TH AVE/43RD ST
Address:	7TH AVE/43RD ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0100864 / 2006-11-01
Facility ID:	0100864
Site ID:	108017
Spill Date:	2001-04-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2001-04-23
CID:	382
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False

SUNSET PARK 7TH AVE/43RD ST (Continued) **S105054705**

Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-04-23
Spill Record Last Update:	2008-05-12
Spiller Name:	TED MAFFEI
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	MICHAEL COLLINS
Spiller Phone:	(631) 586-4900
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	94953
DEC Memo:	10/01/06. Unable to locate address and owner. NFA. JK. Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO
Remarks:	ULAGE FAILURE

All TTF:

Facility ID:	0100864
Spill Number:	0100864
Spill Tank Test:	1526242
Site ID:	108017
Tank Number:	Not reported
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	108017
Operable Unit ID:	839713
Operable Unit:	01
Material ID:	536580
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AU309 **4907-4709 4TH AVENUE** **NY VCP** **S125317115**
SW **4907 4TH AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.439 mi.
2316 ft. **Site 1 of 2 in cluster AU**

Relative:
Higher

Actual:
79 ft.

VCP NYC:

Project ID:	14TMP0405K,14EHAZ405K,14CVCP256K
Name:	4907-4709 4TH AVENUE
Address:	4907 4TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Brooklyn
BBL:	3007830006
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.646918
Longitude:	-74.012101
Postcode:	7
Community Board:	38
Council District:	78
Census Tract:	3012911
BIN:	3007837502
NTA:	Sunset Park West

AU310 **4907-4709 4TH AVENUE** **NY NYC OER** **S129932481**
SW **4907 4TH AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.439 mi.
2316 ft. **Site 2 of 2 in cluster AU**

Relative:
Higher

Actual:
79 ft.

NYC OER:

Name:	4907-4709 4TH AVENUE
Address:	4907 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.646918
Longitude:	-74.012101
OER Project Numbers:	14TMP0405K,14EHAZ405K,14CVCP256K
BBL:	3007830006
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Completed
URL:	https://a002-epic.nyc.gov/app/workspace/2229/docrepository
Postcode:	7
Community Board:	38
Council District:	78
Census Tract:	3012911
BIN:	3007837502
NTA:	Sunset Park West

311
WNW
1/4-1/2
0.459 mi.
2425 ft.

BUSH TERMINAL EDC -DDC
4104 FIRST AVENUE
BROOKLYN, NY 0

UST FINDER RELEASE **1029057100**
N/A

Relative:
Lower

Actual:
11 ft.

UST FINDER RELEASE:

Object ID:	255697
Facility ID:	NY107237
Lust ID:	NY9701133
Name:	BUSH TERMINAL EDC -DDC
Address:	4104 FIRST AVENUE
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	Not reported
Reported Date:	1997/04/18 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	480
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-74.01404
Y Coord:	40.6554400000001
Latitude:	40.6554399999999
Longitude:	-74.0140399999999

312
SSW
1/4-1/2
0.460 mi.
2430 ft.

LUTHERAN MEDICAL CTR
514 49TH ST
BROOKLYN, NY

NY LTANKS **S104510039**
NY Spills **N/A**

Relative:
Higher

Actual:
127 ft.

LTANKS:

Name:	SUNSET TERRACE FAMILY HEALTH CTR
Address:	514 49TH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1600912 / 2019-12-03
Facility ID:	1600912
Site ID:	526211
Spill Date:	2016-04-27
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other

LUTHERAN MEDICAL CTR (Continued) **S104510039**

Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2016-04-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2016-04-27
Spill Record Last Update:	2019-12-03
Spiller Name:	RENE ALEX MEDAS
Spiller Company:	SUNSET TERRACE FAMILY HEALTH CTR
Spiller Address:	514 49TH ST
Spiller County:	999
Spiller Contact:	RENE ALEX MEDAS
Spiller Phone:	(718) 630-7520
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	215860
DEC Memo:	4/27/2016: Rashad 514 49th Street does not have an alternate address. Previous spill#1305012 found for site, tank test failure on 5000 gallon tank, dry leak, case closed after passing tank test. PBS#2-218979 found for site, there is a 5000 gallon #2 fuel oil UST with no access to inspection. Talked to Victoria she said tank test failed, and it is hard to tell if it is wet leak due to manway top accumulating groundwater. Water ontop of manway is being pumped out and protest will be retesting next week. 4/28/2016: Rashad TTF letter emailed to Victoria from Protest and mailed to site owner as per PBS registration, letter was also uploaded to D2. Spill will be reassigned to DEC Piper as he was day time runner on 4/27/16. 7/11/16- DEC Piper received email from Victoria from Protest. they were investigating the source the failure, but they are exploring the possibility of decommissioning this tank rather than repairing. This tank is located in a courtyard with no access for a machine for removal. Ultimately DEC would like to see three samples through the bottom of the tank, once it s cleaned, or four samples on each side adjacent to the tank. Samples must be collected at least 2 below the bottom of the tank if taken through, and at least 4 below the bottom if taken adjacent to. If contamination is found, it may be necessary to install monitoring/ recovery wells and/ or perform an ORC type injection to enhance bioremediation. 2/27/17- DEC Piper spoke with Gerry Nichols at Langan. Bldg is looking to replace tank in summer. Samples will be taken through bottom. Gerry will provide update when closer to start of project. 10/1/19- DEC Piper emailed Gerry Nicols for update. 12/10/19- DEC Piper received and reviewed tank closure report. Based on work to date, this spill is closed. See report in DEC Docs if warranted.
Remarks:	RETEST PENDING

All Materials:

Site ID:	526211
Operable Unit ID:	1275142

LUTHERAN MEDICAL CTR (Continued) **S104510039**

Operable Unit:	01
Material ID:	2279849
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	LUTHERAN MEDICAL CTR
Address:	514 49TH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1305012 / 2013-10-31
Facility ID:	1305012
Site ID:	485566
Spill Date:	2013-08-08
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2013-08-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-08-08
Spill Record Last Update:	2013-10-31
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	GEORGE SULTANA
Spiller Phone:	(718) 630-7520
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	215860
DEC Memo:	08/8/12-Zhune called Bob Urban from Protest but could not get him. Bob will call me back. 08/21/13- Zhune spoke to Bob. Bob said the tank system was tested and failed the test with a dry leak. The proposal for the isolation test was sent to the owner to be signed. As per Bob the fill line caused the test to fail. 10/30/13- Pro Test Environmental sent the closure letter report, including the tightness test results. As per Report on August 8th 2013 Pro Test performed a tightness test on 514 49th Street the tank system failed the test with a dry leak. On September 9th Pro Test returned to isolate the tank from its associated lines. Isolation was first attempted from

LUTHERAN MEDICAL CTR (Continued) **S104510039**

inside the tank, but it was discovered that several lines could not be isolated. Protest returned the next day to excavate, isolate and retest. The tank with only the supply, return and remote fill line attached passed a tightness test. Both the vent line and direct fill line were isolated at the time of the test. Technichians returned on September 11th, 2013 to make repairs. Technicians installed new vemt line and vent riser as well as new direct fill line with spill container. The tank system passed a restest. There was mo evidence of visible contamination within the escavation. Report added to E-docs. Spill closed.

Remarks: 5000 gal ust - dry leak - repair/retest pending

All Materials:

Site ID: 485566
Operable Unit ID: 1235224
Operable Unit: 01
Material ID: 2234415
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

Site ID: 485566
Operable Unit ID: 1235224
Operable Unit: 01
Material ID: 2234416
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

SPILLS:

Name: 514 49TH STREET
Address: 514 49TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9913127 / 2000-03-07
Facility ID: 9913127
Facility Type: ER
DER Facility ID: 215860
Site ID: 264907
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 2401
Spill Date: 2000-02-18
Investigator: SIGONA

LUTHERAN MEDICAL CTR (Continued) **S104510039**

Referred To:	Not reported
Reported to Dept:	2000-02-18
CID:	388
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-02-18
Spill Record Last Update:	2000-03-07
Spiller Name:	Not reported
Spiller Company:	LUTHEREN HOSPITAL
Spiller Address:	514 49TH ST
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	caller reports spill of 50 gallons diesel to sewer. oil co en route to scene to access. unk cause at this time.
Remarks:	Not reported

All Materials:

Site ID:	264907
Operable Unit ID:	1091838
Operable Unit:	01
Material ID:	294985
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	150.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

313
SSW
1/4-1/2
0.482 mi.
2547 ft.

VIDINHA RESIDENCE **NY LTANKS** **S106385726**
442 50TH STREET **N/A**
BROOKLYN, NY

Relative:
Higher

Actual:
95 ft.

LTANKS:

Name:	VIDINHA RESIDENCE
Address:	442 50TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0314286 / 2004-03-31
Facility ID:	0314286
Site ID:	125672
Spill Date:	2004-02-10
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported

VIDINHA RESIDENCE (Continued) **S106385726**

SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2004-03-31
CID:	444
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-31
Spill Record Last Update:	2004-03-31
Spiller Name:	JEFF COHEN
Spiller Company:	BORROW FUEL CO.
Spiller Address:	2 CHURCH AVE
Spiller County:	001
Spiller Contact:	LINDA VIDINHA
Spiller Phone:	(718) 492-0006
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	108697
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND duplicate spill number - closed cross ref #0312507
Remarks:	caller states she does not oil heat and oil co. tried to delivery to her house and her nieghbor stopped them. she didi not think anyone reported it:

All Materials:

Site ID:	125672
Operable Unit ID:	879730
Operable Unit:	01
Material ID:	495860
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	PRIVATE RESIDENCE
Address:	442 50TH STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0312507 / 2004-07-12
Facility ID:	0312507
Site ID:	99378
Spill Date:	2004-02-10
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	TJDEMEO

VIDINHA RESIDENCE (Continued) **S106385726**

Referred To:	Not reported
Reported to Dept:	2004-02-10
CID:	406
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-10
Spill Record Last Update:	2004-07-12
Spiller Name:	JEFF COHEN
Spiller Company:	BORO FUEL
Spiller Address:	2 CHURCH AVE
Spiller County:	001
Spiller Contact:	LINDA VIDINHA (HOMEOWNER)
Spiller Phone:	(718) 492-0006
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	108697
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO Sangesland spoke with Ray Lara. He said there was a spill in a basement of the house. He says they switched to gas heat and forgot to cancel the automatic delivery. Spill was minor. Stained an area approx 8' x 10' on the cement floor. PTC is laying speedie dry and will cleanup when absorbed. 3/26/2004 Sangesland spoke with Ray Lara of PTC. PTC did a basement digout, clean fill and repoured a cement floor. The homeowner said there was still an oil problem. PTC has reopened the floor and drilled several borings throughout the basement. When results come back PTC will forward them on to the DEC for closure. 3/31/2004 DeMeo spoke to Linda Vidinha (homeowner) who says there is still an oil problem at the house. She says PTC did an initial digout and then poured a new cement floor over a contaminated area. PTC came back and did some additional work, but she says there is still an oil smell. She would like the area properly excavated and cleaned. 3/31/2004 Sangesland spoke with Ray Lara at PTC. He said he over excavated the basement and pulled out clean soil. He took two soil samples that came back clean. He says the excavation is still open and he's waiting for word from DEC before he closes it up. Sangesland suggested that Ray speak with DeMeo to set up a time to visit the house to discuss what would be required to close the case out. 4/7/04 TJD Site inspection. Basement excavation complete. No contaminated soils identified via olfactory or visual inspection. Strong residual vapors still present inside residence, vapors are attributable to the use of sweet air by oil company/contractor. Endpoint sample analysis all below TAGM. Oil company & contractor have been directed to backfill excavation and restore concrete floor in basement. Upon completion the new floor must be coated with 2-part epoxy. 7/12/04 TJD Homeowner contacted DeMeo, All work has been completed to her satisfaction and she has requested a NFA letter for her files. Spill closed. Letter mailed.
Remarks:	Tank Overfill. Approx 10 gal. was spilled on land. Working on cleaning it up.

All Materials:

Site ID:	99378
Operable Unit ID:	877750

VIDINHA RESIDENCE (Continued) **S106385726**

Operable Unit:	01
Material ID:	497710
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

314
North
1/4-1/2
0.490 mi.
2589 ft.

RED HOOK MARINE/PT AUTH **UST FINDER RELEASE** **1029078802**
RED HOOK MARINE TERMINAL **N/A**
BROOKLYN, NY 0

Relative:
Lower

Actual:
4 ft.

UST FINDER RELEASE:

Object ID:	255831
Facility ID:	NY84310
Lust ID:	NY8806372
Name:	RED HOOK MARINE/PT AUTH
Address:	RED HOOK MARINE TERMINAL
City,State,Zip:	BROOKLYN, NY 0
Address Match Type:	POI
Reported Date:	1988/10/30 16:00:00+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	Not reported
Domestic Wells within 1500ft:	Not reported
Land Use:	Not reported
Within SPA:	Not reported
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Not reported
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	Not reported
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-74.00708
Y Coord:	40.6590200000001
Latitude:	40.6590199999999
Longitude:	-74.00708

315
WNW
1/2-1
0.501 mi.
2646 ft.

PIER 6 BUSH TERMINAL
NO CITY, NY

FUDS **1024899361**
N/A

Relative:
Lower

Actual:
8 ft.

FUDS:

EPA Region:	02
Installation ID:	NY29799F956100
Congressional District Number:	10
Name:	PIER 6 BUSH TERMINAL
FUDS Number:	C02NY1100
City:	NO CITY
State:	NY
County:	KINGS
Object ID:	4474
USACE Division:	NAD
USACE District:	New England District (NAE)
Status:	Properties without projects
Current Owner:	LOCAL: CITY NEW YORK CITY
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map?id=54340
Eligibility:	Eligible
Has Projects:	No
NPL Status:	Not reported
Project Required:	No
Feature Description:	The Navy used Pier 6 as a shipping and receiving port for transporting of Naval equipment and ammunition along the Gowanus Bay.
Latitude:	40.65472222
Longitude:	-74.01555556

316
SW
1/2-1
0.522 mi.
2758 ft.

5111 4TH AVENUE
5111 4TH AVENUE
BROOKLYN, NY

NY NYC OER **S129932508**
N/A

Relative:
Higher

Actual:
76 ft.

NYC OER:

Name:	5111 4TH AVENUE
Address:	5111 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.645781
Longitude:	-74.013279
OER Project Numbers:	15TMP0376K,15EHAZ376K,15CVCP115K
BBL:	3007990006
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Completed (C)
Phase:	Site Management
URL:	https://a002-epic.nyc.gov/app/workspace/2791/docrepository
Postcode:	7
Community Board:	38
Council District:	78
Census Tract:	3013536
BIN:	3007990006
NTA:	Sunset Park West

317
NNE
1/2-1
0.543 mi.
2867 ft.

MIL MED SUPPLY NO. 1
NO CITY, NY

FUDS **1024899196**
N/A

Relative:
Lower

Actual:
10 ft.

FUDS:

EPA Region:	02
Installation ID:	NY29799F760000
Congressional District Number:	10
Name:	MIL MED SUPPLY NO. 1
FUDS Number:	C02NY0041
City:	NO CITY
State:	NY
County:	KINGS
Object ID:	4591
USACE Division:	NAD
USACE District:	New England District (NAE)
Status:	Properties without projects
Current Owner:	FED: FEDERAL GSA AND SEVERAL OTHER GOVERNMENT AGENCIES.
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map?id=62684
Eligibility:	Eligible
Has Projects:	No
NPL Status:	Not reported
Project Required:	No
Feature Description:	As per Deeds dated 29 October 1918 and 3 December 1926, the Government did obtain from the Bush Terminal Corporation: 83 0 3d Avenue, 850 3d Avenue and 870 3d Avenue. In 1961, the Department of the Navy conveyed the site to the General Services Administration (GSA). As per Assessor?s Office of Kings County, GSA is still the owner of record. The former Military Medical Supply Agency is shown on the Kings County Tax Map as: a. Block 667, Lot 1 (83 0 34 Avenue) b. Block 671, Lot 1 (850 3d Avenue) c. Block 675, Lot 1 (870 3d Avenue)
Latitude:	40.65944444
Longitude:	-74.00361111

318
West
1/2-1
0.599 mi.
3161 ft.

REAR OF BUSH TERMINAL BUILDING
END OF 47 THRU 52ND STREETS
BROOKLYN, NY 11220

NY SHWS **S101008336**
N/A

Relative:
Lower

Actual:
11 ft.

SHWS:

Name:	REAR OF BUSH TERMINAL BUILDING
Address:	END OF 47 THRU 52ND STREETS
City,State,Zip:	BROOKLYN, NY 11220
Program:	HW
Site Code:	58024
Classification:	Does not present a significant threat to the public health or the environment - action may be deferred.
Region:	2
Acres:	11.000
HW Code:	224011
Record Add:	11/18/1999
Record Upd:	05/22/2008
Updated By:	JHOCONNE
Site Description:	The site is located along the Upper New York Bay, in the Sunset Park Section of Brooklyn, in the western part of Kings County, New York. The site borders an access road referred to as Marginal Street (which parallels 1st Avenue), between 45th and 50th Street. The land

REAR OF BUSH TERMINAL BUILDING (Continued) **S101008336**

immediately adjacent to the site is used for commercial and industrial purposes, although residential housing areas are present within approximately 1,500 to 2,000 feet of the site. The 17.3-acre site includes approximately 14 acres of urban land that was created by landfilling between four piers that were part of the former Bush Terminal warehouse complex. The remaining pier structures are dilapidated and extend 600 to 800 feet into the Bay from the existing fill areas. The site is currently fenced to prevent public access. The total landfill area is approximately 14 acres in size. Partial filling between two piers (Piers 3 and 4) has resulted in the presence of two ponded areas in the northeastern portion of the site. While most of the landfilled areas are covered with grasses or barren soils, the westernmost fill area between Piers 2 and 3 supports an area of mature trees (referred to as the existing wooded area). Debris piles are present in some areas, especially along the edge of the site bordering Marginal Road. The Site Investigation (SI)was conducted between May 1999 and May 2001. The field activities and findings of the investigation are described in the SI report. Additional studies were conducted between March and July 2002 to support the evaluation of remedial alternatives and are described in the Remedial Alternatives Report (RAR). This site is being tracked under the Environmental Restoration Program (ERP) as site number B00031-2.

Env Problem: The primary contaminants of concern at the site (in groundwater, soils and sediments) that exceed their SCGs are semivolatile organic compounds (SVOCs) and inorganics (metals). VOCs, the pesticide 4,4-DDT, and PCBs were also detected at levels exceeding SCGs, but to a much lesser extent than the SVOCs and metals. Sampling has revealed contravention of groundwater standards by 23 organic chemicals and 12 metals. It has been determined that no significant threat exists to the environment. While groundwater quality at the site has been impacted, it is unlikely that surface water quality criteria will be exceeded when groundwater discharges to the Bay, due to the low rates of groundwater discharge and the relatively low concentrations of contaminants in groundwater. Therefore, groundwater is not expected to present a potential environmental impact.

Health Problem: The area is served by public water, therefore, exposure to contaminated groundwater is unlikely. There is a potential for direct contact expsoure with contaminated surface soil. However, a clean soil cover over the site and landfill gas control measures will minimize the potential for exposures to future park users. Site access is currently restricted by a fence minimizing the potential for exposure.

Dump: True
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: mid 1974
Disp Term: 1978
Lat/Long: 40:39:06:0 / 74:01:12:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2004-12-23 08:50:00
Updated By: JMOCONNE
Own Op: 1
Sub Type: C01

REAR OF BUSH TERMINAL BUILDING (Continued) **S101008336**

Owner Name:	PATRICIA ZEDALIS
Owner Company:	UNKNOWN
Owner Address:	BATTERY MARITIME BOARD, WHITEHALL ST
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10004
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	UNKNOWN3
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	1
Sub Type:	D
Owner Name:	Not reported
Owner Company:	United States Coast Guard
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	1
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	NYC DEPT. OF PORTS AND TRADE
Owner Address:	BATTERY MARITIME BOARD, WHITEHALL ST
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10004
Owner Country:	United States of America
Own Op:	1
Sub Type:	C01
Owner Name:	PATRICIA ZEDALIS
Owner Company:	NYC Dept. of Ports and Trade
Owner Address:	BATTERY MARITIME BOARD, WHITEHALL ST
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10004
Owner Country:	United States of America
HW Code:	224011
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224011
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224011
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224011
Waste Type:	PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224011
Waste Type:	ANTHRACENE
Waste Quantity:	UNKNOWN

REAR OF BUSH TERMINAL BUILDING (Continued) **S101008336**

Waste Code:	Not reported
HW Code:	224011
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224011
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224011
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD982181059
Cross Ref Type Code:	05
Cross Ref Type:	EPA Site ID
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2001-05-10 16:31:00
Updated By:	REGTRANS
Crossref ID:	023
Cross Ref Type Code:	13
Cross Ref Type:	Senate District
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2005-02-24 15:54:00
Updated By:	INITIAL

---

319 **US ARMED GUARD CENTER** **FUDS** **1024899356**
West **N/A**
1/2-1 **NO CITY, NY**
0.667 mi.
3521 ft.

Relative: **Lower**

Actual: **17 ft.**

FUDS:

EPA Region:	02
Installation ID:	NY29799F955000
Congressional District Number:	10
Name:	US ARMED GUARD CENTER
FUDS Number:	C02NY1089
City:	NO CITY
State:	NY
County:	KINGS
Object ID:	10113
USACE Division:	NAD
USACE District:	New England District (NAE)
Status:	Properties without projects
Current Owner:	LOCAL: CITY ; PRIV: PRIVATE
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map?id=54798
Eligibility:	Eligible
Has Projects:	No
NPL Status:	Not reported
Project Required:	No
Feature Description:	Between 1904 and 1941, the site was used as a training center for members of the New York State Naval Militia and from 1942 to 1946, the Navy utilized the site as a detention center.
Latitude:	40.65027778
Longitude:	-74.01944444

320 WSW 1/2-1 0.743 mi. 3922 ft.

NYSDEC EMPIRE ELECTRIC SITE #2-24-075
5200 1ST AVE
BROOKLYN, NY 11232

RCRA-LQG 1000261156
NY SHWS NYD003907045
NY MANIFEST

Relative: Lower

Actual: 22 ft.

RCRA Listings:

Date Form Received by Agency:	20180209
Handler Name:	Nysdec Empire Electric Site #2-24-075
Handler Address:	1ST AVE
Handler City,State,Zip:	BROOKLYN, NY 11232
EPA ID:	NYD003907045
Contact Name:	DAVID J CHIUSANO
Contact Address:	BROADWAY - 12TH FLOOR
Contact City,State,Zip:	ALBANY, NY 12233
Contact Telephone:	518-402-9813
Contact Fax:	518-402-9819
Contact Email:	DAVID.CHIUSANO@DEC.NY.GOV
Contact Title:	ENVIRONMENTAL ENGINEER - PROJECT MANAGER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	BROADWAY - 12TH FLOOR
Mailing City,State,Zip:	ALBANY, NY 12233
Owner Name:	5200 Enterproses Limited
Owner Type:	Private
Operator Name:	Nysdec
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Waste Code: NONE
Waste Description: None

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: ZAFAR ULLAH	
Legal Status:	Private
Date Became Current:	19931119
Date Ended Current:	Not reported
Owner/Operator Address:	5200 FIRST AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11232
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: 5200 ENTERPRISES LTD	
Legal Status:	Private
Date Became Current:	19931119
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Owner/Operator Indicator:	Operator
Owner/Operator Name: NYSDEC	
Legal Status:	State
Date Became Current:	20081007
Date Ended Current:	Not reported
Owner/Operator Address:	625 BROADWAY
Owner/Operator City,State,Zip:	ALBANY, NY 12233
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: OWNERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: OWNERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: 5200 ENTERPROSES LIMITED	
Legal Status:	Private
Date Became Current:	19000101
Date Ended Current:	Not reported
Owner/Operator Address:	1 BUSH PLAZA
Owner/Operator City,State,Zip:	BROAKLYN, NY 11232
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NYSDEC	
Legal Status:	State
Date Became Current:	20140612
Date Ended Current:	Not reported
Owner/Operator Address:	625 BROADWAY - 12TH FLOOR
Owner/Operator City,State,Zip:	ALBANY, NY 12233
Owner/Operator Telephone:	518-402-9813
Owner/Operator Telephone Ext:	Not reported

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ZAFAR ULLAH
Legal Status: Private
Date Became Current: 19931119
Date Ended Current: Not reported
Owner/Operator Address: 5202 FIRST AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11232
Owner/Operator Telephone: 917-361-0104
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160422
Handler Name: NYSDEC EMPIRE ELECTRIC SITE #2-24-015 CO INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180209
Handler Name: NYSDEC EMPIRE ELECTRIC SITE #2-24-075
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19990708
Handler Name: EMPIRE ELECTRIC CO INC
Federal Waste Generator Description: Not a generator, verified

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: EMPIRE ELECTRIC CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: EMPIRE ELECTRIC CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19850716
Handler Name: EMPIRE ELECTRIC CO INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20081007
Handler Name: NYSDEC EMPIRE ELECTRIC SITE #2-24-015
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 562211
NAICS Description: HAZARDOUS WASTE TREATMENT AND DISPOSAL

NAICS Code: 56291
NAICS Description: REMEDIATION SERVICES

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19880721
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19860225
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Request Agency: Not reported
Former Citation: Not reported

SHWS:
Name: EMPIRE ELECTRIC COMPANY
Address: 5200 1ST AVENUE
City,State,Zip: BROOKLYN, NY 11232
Program: HW
Site Code: 57687
Classification: Significant threat to the public health or environment - action required.
Region: 2
Acres: 0.500
HW Code: 224015
Record Add: 11/18/1999
Record Upd: 02/07/2023
Updated By: SMQUANDT
Site Description: Location: The 0.5-acre Empire Electric Company site is located at 5200 1st Avenue in Brooklyn, New York on the southwest corner of 52nd Street and 1st Avenue. Site Features: The site previously contained a deteriorated, vacant, red brick building that had covered the entire site. This building was razed by NYSDEC during an interim remedial measure (IRM) in 2017 in order to make the site safe to perform the Remedial Investigation and excavation of contaminated soil. Currently, the entire site has a gravel cover system and is presently used as a parking lot. Current Zoning and Land Use: The area is primarily industrial (zoned 3, heavy industries), with a potato chip manufacturing plant, a New York City Department of Sanitation vehicle maintenance and storage building, an DHL courier company, the former BUG Kings County Works manufactured gas plant site, and the waterfront (Bush Terminal docks) in the general vicinity of the site. Past Use of the Site: The building was constructed in 1892 by the Brooklyn City Railroad Company for use as a power plant for the municipally owned trolley system. The building was used for electrical generation until the 1930s when the trolley system was abandoned. The facility was conveyed to the city of New York in 1940. The City sold the property in 1951. The new owner subdivided the parcel into two lots (Lot 6 and Lot 9). Empire Electric operated on Lot 9 from 1951 to December 1986 when the property was sold. Empire Electric s operations consisted of reconditioning and salvaging electrical apparatus, including PCB-containing transformers. The site was sold again in 1986, but the building remained unused until it was demolished. Site Geology and Hydrogeology: The site is situated approximately 1,200 feet from the Upper New York Bay at the western end of Brooklyn. The site is approximately 16 feet above mean sea level (msl), sloping gradually toward the bay. Prior to the IRM, site soil directly beneath the building consisted primarily large granite slabs that had supported the generators and historic fill and debris materials, underlain by sand and gravel under the basement slab. The water table beneath the site occurs at approximately 17 to 21 feet below ground surface (bgs). Regional groundwater flow direction is to the west, toward the bay. The depth to bedrock is unknown but is likely greater than 100 feet bgs. Surface drainage generally follows the topography, and flow is northwest along 52nd Street toward the Upper New York Bay. Storm water drains are present along 52nd Street and First Avenue. Surface runoff collects in these drains and then

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

	flows directly into the Upper New York Bay.
Env Problem:	Nature and Extent of Contamination: Based upon investigations conducted to date and findings observed during the 2017 interim remedial measure (IRM), the primary contaminant of concern are PCBs and trichlorobenzene. Post-excavation soil samples from beneath the former basement floor exceeded the 1 ppm surface and 10 ppm subsurface criteria historically used to assess PCB contamination in soil. Two soil samples also exceeded the TSCA definition of hazardous waste. The site presents a significant environmental threat due to the presence of high concentrations of PCBs at and below the water table.
Health Problem:	The site is completely fenced, and contaminated soil is at depth below clean backfill, stone and concrete. Therefore, contact with contaminated soil is unlikely. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil), may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants due to soil vapor intrusion does not represent a current concern. However, there is a potential for soil vapor intrusion in future on-site buildings and off-site buildings.
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1950
Disp Term:	1985
Lat/Long:	40:38:58:0 / 74:01:11:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2013-09-20 14:06:00
Updated By:	ldennist
Own Op:	3
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	5200 ENTERPRISES LIMITED CORP.
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	John Luhrs
Owner Company:	5200 Enterprises Limited
Owner Address:	4453 St. Johns Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Jacksonville, FL 32210
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Not reported
Owner Company:	5200 ENTERPRISES LIMITED CORP.

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Owner Address:	5200 1ST AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Empire Electric Company
Owner Address:	5200 1st Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11232
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	5200 Enterprises Limited
Owner Address:	1 Bush Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11232
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Ms. Roxana Benavides
Owner Company:	Brooklyn Public Library - Sunset Park Branch
Owner Address:	5108 4th Ave. at 51st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11220
Owner Country:	United States of America
HW Code:	224015
Waste Type:	PCB aroclor 1260
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224015
Waste Type:	1,2,4-trichlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224015
Waste Type:	PCBS
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224015
Waste Type:	1,3-dichlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224015
Waste Type:	1,4-dichlorobenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD003907045
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	2016-04-11 14:20:00
Record Updated:	2016-04-11 14:20:00
Updated By:	SMWITHER
Crossref ID:	1900873
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Record Added Date: 2019-08-09 10:40:00
Record Updated: 2019-08-09 10:40:00
Updated By: CHPOST

NY MANIFEST:

EPA ID:	NYD003907045
Country:	USA
Name:	NYSDEC EMPIRE ELECTRIC SITE #2-24-015 CO INC
Address:	5200 1ST AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11232-4306
Zip 4:	Not reported
Location Address 1:	5200 1ST AVE
Location Address 2:	Not reported
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	NYSDEC EMPIRE ELECTRIC SITE #2-24-015 CO INC
Mailing Contact:	IRVING HASNAS
Mailing Address 1:	1613 63RD ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BROOKLYN, NY 11204
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184925555

Manifest Data:

Document ID:	NYA2625696
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	MN-004PTA
Year:	1986
Trans2 State ID:	Not reported
Generator Ship Date:	861124
Trans1 Recv Date:	861124
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	861202
Part A Recv Date:	861202
Part B Recv Date:	861226
Generator EPA ID:	NYD003907045
Trans1 EPA ID:	MND980791321
Trans2 EPA ID:	Not reported
TSDF ID 1:	KSD980964993
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B006
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	43390
Units:	Pounds
Number of Containers:	005
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	100

Document ID:	NYA3293166
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	MN-004PRA
Year:	1986
Trans2 State ID:	Not reported
Generator Ship Date:	861124
Trans1 Recv Date:	861124
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	861203
Part A Recv Date:	861202
Part B Recv Date:	861226
Generator EPA ID:	NYD003907045
Trans1 EPA ID:	MND980791321
Trans2 EPA ID:	Not reported
TSDF ID 1:	KSD980964993
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B006
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	42800
Units:	Pounds
Number of Containers:	003
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	100

Document ID:	NYA3183726

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Manifest Status:	C - Completed copy
Trans1 State ID:	MN-004
Year:	1986
Trans2 State ID:	Not reported
Generator Ship Date:	860923
Trans1 Recv Date:	860923
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860930
Part A Recv Date:	860930
Part B Recv Date:	861007
Generator EPA ID:	NYD003907045
Trans1 EPA ID:	MND980791321
Trans2 EPA ID:	Not reported
TSDF ID 1:	KSD980964993
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B006
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	11300
Units:	Pounds
Number of Containers:	003
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	100
Waste Code 7:	B006
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00350
Units:	Pounds
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	100

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	NYD148612922
Generator Ship Date:	11/03/2015

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Trans1 Recv Date:	11/03/2015
Trans2 Recv Date:	11/03/2015
TSD Site Recv Date:	11/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD003907045
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID048090633
TSDF ID 2:	Not reported
Manifest Tracking Number:	015169780JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	B007
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	11158
Units:	Kilograms
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	NYD148612922
Generator Ship Date:	11/03/2015
Trans1 Recv Date:	11/03/2015
Trans2 Recv Date:	11/03/2015
TSD Site Recv Date:	11/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD003907045
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID048090633
TSDF ID 2:	Not reported

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Manifest Tracking Number:	015169782JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	B007
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	12646
Units:	Kilograms
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	NYD148612922
Generator Ship Date:	11/03/2015
Trans1 Recv Date:	11/03/2015
Trans2 Recv Date:	11/03/2015
TSD Site Recv Date:	11/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD003907045
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID048090633
TSDF ID 2:	Not reported
Manifest Tracking Number:	015169783JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	B007
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	2994
Units:	Kilograms
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	NYD148612922
Generator Ship Date:	10/29/2015
Trans1 Recv Date:	10/29/2015
Trans2 Recv Date:	10/29/2015
TSD Site Recv Date:	11/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD003907045
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID048090633
TSDF ID 2:	Not reported
Manifest Tracking Number:	015169766JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	B007
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	18.15
Units:	Tons (2000 Pounds)
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	NYD148612922
Generator Ship Date:	10/29/2015
Trans1 Recv Date:	10/29/2015
Trans2 Recv Date:	10/29/2015
TSD Site Recv Date:	11/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD003907045
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID048090633
TSDF ID 2:	Not reported
Manifest Tracking Number:	015169789JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	B007
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	17.45
Units:	Tons (2000 Pounds)
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	NYD148612922
Generator Ship Date:	10/30/2015
Trans1 Recv Date:	10/30/2015
Trans2 Recv Date:	10/30/2015
TSD Site Recv Date:	11/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD003907045
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID048090633
TSDF ID 2:	Not reported
Manifest Tracking Number:	015169765JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	B007
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	34460
Units:	Kilograms
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	NYD148612922
Generator Ship Date:	10/30/2015
Trans1 Recv Date:	10/30/2015
Trans2 Recv Date:	10/30/2015
TSD Site Recv Date:	11/13/2015
Part A Recv Date:	Not reported

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Part B Recv Date:	Not reported
Generator EPA ID:	NYD003907045
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID048090633
TSDF ID 2:	Not reported
Manifest Tracking Number:	015169768JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	B007
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	30040
Units:	Kilograms
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR000029967
Year:	2018
Trans2 State ID:	NYD148612922
Generator Ship Date:	10/30/2015
Trans1 Recv Date:	10/30/2015
Trans2 Recv Date:	10/30/2015
TSD Site Recv Date:	11/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD003907045
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID048090633
TSDF ID 2:	Not reported
Manifest Tracking Number:	015169770JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y

NYSDEC EMPIRE ELECTRIC SITE #2-24-075 (Continued) **1000261156**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	B007
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	31000
Units:	Kilograms
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1

Click this hyperlink while viewing on your computer to access
322 additional NY MANIFEST: record(s) in the EDR Site Report.

321
WSW
1/2-1
0.822 mi.
4339 ft.

AMERICAN MACHINE AND FOUNDRY CO SITE **FUSRAP** **1016603370**
SECOND AVENUE AND 56TH STREET **N/A**
BROOKLYN, NY

Relative:
Lower

Actual:
36 ft.

FUSRAP:

Site Name:	AMERICAN MACHINE AND FOUNDRY CO SITE
Site Id:	NY 26
Site Status:	Eliminated from consideration under FUSRAP
Designated Name:	Not Designated
Alternate Name:	American Machine and Foundry Co - NY 26; Lutheran Medical Center; AMF; AMF Atomics
Location Street Address:	SECOND AVENUE AND 56TH STREET
Location City:	BROOKLYN
Location State:	NY
Location County:	Not reported
Site Oprerations:	1951 - 1954 conducted metal fabrication operation on uranium and thorium metals.
Site Disposition:	Eliminated - Potential for contamination considered remote based on results of radiological monitoring and sampling and extensive renovation of the site
Radioactice Materials Handled:	Yes
Primary Radioactivce Materials Handled:	Uranium and Thorium metal
Radiological Survey(S):	Yes
LM Site:	Not reported
Considered Name:	American Machine and Foundry Co
Site Summary:	Not reported

AMERICAN MACHINE AND FOUNDRY CO SITE (Continued) **1016603370**

Website URL: https://lmpublicsearch.lm.doe.gov/SitePages/ConsideredSites.aspx?sitename=American%20Machine%20and%20Foundry%20Co

---

AV322 **KINGS COUNTY WORKS** **EDR MGP** **1008407894**
WSW **55TH ST. AND 1ST AVE** **N/A**
1/2-1 **BROOKLYN, NY 11220**
0.827 mi.
4368 ft. **Site 1 of 2 in cluster AV**

Relative: **Lower**
Actual: **24 ft.**

EDR MGP:
No additional information available

AV323 **K - KINGS COUNTY WORKS** **NY SHWS** **S110748428**
WSW **55TH ST & 1ST AVE** **NY BROWNFIELDS** **N/A**
1/2-1 **BROOKLYN, NY 11220** **NY MGP**
0.842 mi.
4448 ft. **Site 2 of 2 in cluster AV**

Relative: **Lower**
Actual: **24 ft.**

SHWS:
Name: K - KINGS COUNTY WORKS
Address: 55TH ST & 1ST AVE
City,State,Zip: BROOKLYN, NY 11220
Program: HW
Site Code: 378989
Classification: A
Region: 2
Acres: 7.500
HW Code: 224056
Record Add: 03/27/2007
Record Upd: 06/30/2023
Updated By: SXDEYETT
Site Description: Location - The Kings County Manufactured Gas Plant (MGP) site is comprised of two contiguous parcels of land located on the east bank of the Bay Ridge Channel of the Upper New York Bay in Brooklyn, Kings County. The parcels are identified as 5400 1st Avenue and 5600 1st Avenue. The site is on the west side of 1st Avenue, near 54th Street. Site Features - The site is currently used for commercial/industrial purposes with warehouse buildings, a fuel oil storage facility and a power-generating station. The area between the buildings and other infrastructure is paved. Current Zoning/Use - The site is currently active and is zoned for industrial use. The surrounding parcels are currently used for a combination of both commercial and industrial uses. Past Use of the Site - The former MGP operated from 1904 until 1951. By 1970 all former MGP structures had been removed except for four fuel oil tanks and one gas holder that was converted into a fuel oil tank. In 1976 three meat distribution buildings were added to the property, which still exist today. At this time the fuel oil tanks and a power generating station were being operated by Con Edison. There are numerous spills relating to this activity on the site. One of the results of these spills was the installation of recovery wells for the collection of light non-aqueous phase liquid (LNAPL). These wells are currently being sampled on an annual basis. Site Geology and Hydrogeology - Fill material was encountered up to approximately 18 feet below ground surface. Fill material consists of fine to

K - KINGS COUNTY WORKS (Continued) **S110748428**

coarse sand with some silt, brick, metal fragments, concrete, cobbles and some clay. Underlying the fill was glacial outwash, fine to coarse gravel. Bedrock in the area is expected to be approximately 225 feet below ground surface. Groundwater is found at depths of 8 to 25 feet below ground surface and is tidally influenced. The groundwater flow direction is to the west.

Env Problem:	Prior to Remediation- Based on previous investigations, there are both VOCs (BTEX) and SVOCs (PAHs) from numerous petroleum spills at the property, as well as from past MGP operations. These contaminants are present in both soil and groundwater. In 2018, several monitoring wells were sampled for PFAS and 1,4-dioxane as part of the Department's Emerging Contaminants initiative. Perfluorooctanoic acid (PFOA) was reported at concentrations up to 155 parts per trillion (ppt), exceeding the 10 ppt screening level for groundwater. Individual PFAS exceeding the 100 ppt screening level included Perfluorobutanoic Acid (PFBA) at a concentration of 2,940 ppt. Total PFAS, including PFOA and PFOS, were reported at concentrations up to 3,521 ppt, which is above the 500 ppt screening level for total PFAS in groundwater.
Health Problem:	The NYSDOH will evaluate the potential for impacts to public health from exposure to site contaminants once sufficient information from the investigation of the site becomes available for review.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-09-20 14:12:00
Record Upd:	2013-09-20 14:12:00
Updated By:	ldennist
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	224056
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1511770
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2016-04-14 10:22:00
Record Updated:	2016-04-14 10:22:00
Updated By:	HRAHMED

BROWNFIELDS:

Name:	K - KINGS COUNTY WORKS
Address:	55TH ST & 1ST AVE
City,State,Zip:	BROOKLYN, NY 11220

K - KINGS COUNTY WORKS (Continued) **S110748428**

Program:	BCP
Site Code:	58953
Acres:	7.500
HW Code:	C224056
SWIS:	2401
Town:	New York City
Record Added Date:	04/30/2004
Record Updated Date:	12/07/2009
Update By:	MOBARRIE
Site Description:	See Site 224056
Env Problem:	Not reported
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	KEYSPAN
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	Unknown
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

MGP:

Site ID:	224056
Name:	K - KINGS COUNTY WORKS
Address:	55TH ST & 1ST AVE
City,State,Zip:	BROOKLYN, NY 11220
Region:	2
Class:	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Swis Code:	2401
Town:	New York City

K - KINGS COUNTY WORKS (Continued) **S110748428**

Disp Start:	Not reported
Disp Term:	Not reported
Acres:	7.5
Fuse:	Not Identified
Description:	Location - The Kings County Manufactured Gas Plant (MGP) site is comprised of two contiguous parcels of land located on the east bank of the Bay Ridge Channel of the Upper New York Bay in Brooklyn, Kings County. The parcels are identified as 5400 1st Avenue and 5600 1st Avenue. The site is on the west side of 1st Avenue, near 54th Street. Site Features - The site is currently used for commercial/industrial purposes with warehouse buildings, a fuel oil storage facility and a power-generating station. The area between the buildings and other infrastructure is paved. Current Zoning/Use - The site is currently active and is zoned for industrial use. The surrounding parcels are currently used for a combination of both commercial and industrial uses. Past Use of the Site - The former MGP operated from 1904 until 1951. By 1970 all former MGP structures had been removed except for four fuel oil tanks and one gas holder that was converted into a fuel oil tank. In 1976 three meat distribution buildings were added to the property, which still exist today. At this time the fuel oil tanks and a power generating station were being operated by Con Edison. There are numerous spills relating to this activity on the site. One of the results of these spills was the installation of recovery wells for the collection of light non-aqueous phase liquid (LNAPL). These wells are currently being sampled on an annual basis. Site Geology and Hydrogeology - Fill material was encountered up to approximately 18 feet below ground surface. Fill material consists of fine to coarse sand with some silt, brick, metal fragments, concrete, cobbles and some clay. Underlying the fill was glacial outwash, fine to coarse gravel. Bedrock in the area is expected to be approximately 225 feet below ground surface. Groundwater is found at depths of 8 to 25 feet below ground surface and is tidally influenced. The groundwater flow direction is to the west.
Assess Env:	Prior to Remediation- Based on previous investigations, there are both VOCs (BTEX) and SVOCs (PAHs) from numerous petroleum spills at the property, as well as from past MGP operations. These contaminants are present in both soil and groundwater. In 2018, several monitoring wells were sampled for PFAS and 1,4-dioxane as part of the Department’s Emerging Contaminants initiative. Perfluorooctanoic acid (PFOA) was reported at concentrations up to 155 parts per trillion (ppt), exceeding the 10 ppt screening level for groundwater. Individual PFAS exceeding the 100 ppt screening level included Perfluorobutanoic Acid (PFBA) at a concentration of 2,940 ppt. Total PFAS, including PFOA and PFOS, were reported at concentrations up to 3,521 ppt, which is above the 500 ppt screening level for total PFAS in groundwater.
Assess Doh:	The NYSDOH will evaluate the potential for impacts to public health from exposure to site contaminants once sufficient information from the investigation of the site becomes available for review.
Latitude:	40.648888889
Longitude:	-74.022222222

324 West 1/2-1 0.846 mi. 4466 ft. | **FORMER E.W. BLISS PROJECTILES**
29 53RD STREET
BROOKLYN, NY 11232 | **NY SHWS** **S112809371**
NY Spills **N/A**

Relative: Lower

Actual: 7 ft.

SHWS:

Name:	FORMER E.W. BLISS PROJECTILES
Address:	29 53RD STREET
City,State,Zip:	BROOKLYN, NY 11232
Program:	HW
Site Code:	535697
Classification:	P
Region:	2
Acres:	0.700
HW Code:	224249
Record Add:	11/16/2016
Record Upd:	09/26/2017
Updated By:	JHOCONNE
Site Description:	Location: The subject property is located at 29 53rd Street in the Borough of Brooklyn, Kings County, NY in an urban area. The subject property consists of about 0.7 acres designated as tax block 803, Lot 41. Site Features: The site currently contains a one-story warehouse-style building which occupies the entire property. Current Zoning/Use(s): The site is currently zoned as M3-1 (industrial and manufacturing district) and is used as a storage and distribution facility for packaged dry snacks. Historical Use(s): Since 1977 the Site has been occupied by Clem Snacks. A mechanic shop containing hydraulic lifts was noted to be located in the southeastern portion of the building from 1977 to 2004. Historically the site was utilized mainly for industrial purposes, including the E.W. Bliss projectile Department, paper warehouse and metal product manufacture from 1906 to 1977. Two crude oil tanks were depicted adjoining the southwestern side of the subject building on the 1926 to 1942 Sanborn maps. Site Geology and Hydrogeology: Soil borings conducted in 2013 identified sand and silt beneath the one-foot thick concrete building slab. Some gravel, brick and concrete fragments were observed in the boring down to 20 feet below grade; this debris represents fill material. Groundwater is present at a depth of approximately 12 feet below grade. The groundwater beneath the subject property is expected to be tidally influenced, and generally flowing to the west towards Gowanus Bay, which is located approximately 400 feet west of the site.
Env Problem:	Nature and Extent of Contamination: The following information was obtained from two separate Phase II reports prepared for the site in 2012 and 2013. Soil Borings identified evidence of petroleum non-aqueous phase liquid (NAPL) at the water table in at least 6 on-site boring locations. Volatile organic compounds (VOCs) were found including tetrachloroethylene (PCE) at a maximum concentration of 7.7 parts per million (ppm), trichloroethylene (TCE) at a maximum concentration of 12 ppm, and cis-1,2-dichloroethene (cis-1,2-DCE) at a maximum concentration of 18.2 ppm. Groundwater VOCs were detected in temporary wells on-site, including: PCE at a maximum concentration of 62 parts per billion (ppb); TCE up to 78 ppb; and cis-1,2-DCE up to 33 ppb. Soil Vapor No soil vapor data has been collected to date.
Health Problem:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Dump:	Not reported
Structure:	Not reported

FORMER E.W. BLISS PROJECTILES (Continued) **S112809371**

Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	E
Owner Name:	Frank Clemente
Owner Company:	Clem Properties Inc.
Owner Address:	29 53rd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11232
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Clem Properties Inc.
Owner Address:	29 53rd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11232
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	CLEM SNACKS WAREHOUSE
Address:	29 53RD ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1214682 / Not Reported
Facility ID:	1214682
Facility Type:	ER
DER Facility ID:	433236
Site ID:	477938
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2013-01-16
Investigator:	YYWONG
Referred To:	Not reported
Reported to Dept:	2013-01-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial

FORMER E.W. BLISS PROJECTILES (Continued) **S112809371**

Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2013-01-16
Spill Record Last Update:	2020-02-13
Spiller Name:	CLEM SNACKS INC
Spiller Company:	CLEM SNACKS WAREHOUSE
Spiller Address:	29 53RD ST
Spiller Company:	999
Contact Name:	EDWARD SHEY
DEC Memo:	Drill samples done as per refinacing company showed impacted soil at approx. 14 feet. Cleanup or further action is pending DEC requirements.
Remarks:	1/18/13: Jane O'Connell received email from Joe Crua (NYSDOH) transmitting a copy of the NRC notification (see eDocs). Contacted Edward Shea, attorney for property owner. He stated that Phase II was performed on behalf of TD Bank for loan refinance purposes. Found solvent contamination in soil at 14 feet below floor slab (above water table). Mr. Shea characterized the concentrations as slightly above standards , but did not know the actual concentrations or to which standards the results were compared. I requested that he send me a copy of the report. (JHO) 2/13/20 - Spill transferred to Bryan Wong - site is managed under Consent Order, site no. 224249 (JHO)

All Materials:

Site ID:	477938
Operable Unit ID:	1227731
Operable Unit:	01
Material ID:	2225221
Material Code:	0776A
Material Name:	chlorinated solvents
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

---

325 NNE 1/2-1 0.846 mi. 4467 ft.

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS **NY SHWS S110751210**
730 3RD AVENUE **NY Spills N/A**
BROOKLYN, NY 12201

Relative: Lower

Actual: 6 ft.

SHWS:

Name:	FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS
Address:	730 3RD AVENUE
City,State,Zip:	BROOKLYN, NY 12201
Program:	HW
Site Code:	439096
Classification:	N
Region:	2

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS (Continued) **S110751210**

Acres: 18.540
HW Code: 224143
Record Add: 08/24/2010
Record Upd: 11/12/2010
Updated By: MOBARRIE
Site Description: The Site is located in the Gowanus section of Brooklyn in a zoned manufacturing area. The site was formerly used by Moore McCormack Lines, a steamship company (dates of occupancy unknown). Subsequently, Continental Terminals used the pier shed to store and distribute cocoa beans into the late 1990s. The shed was removed and the pier was then used by American Warehousing for vehicle storage. The Site also contains a garage that was used for vehicle maintenance. The Site was recently paved. The northern portion of the Site is used for storage of sea containers by the New York City Police Department, and a small electric power generating station operated by the New York Power Authority occupies the south part of the Site. Immediately northwest of the Site is Upper New York Bay/Gowanus Canal, immediately northeast is industrial/manufacturing, and immediately southeast are commercial and office buildings. The Site is approximately 98,010 square feet (2.2 acres) in size and is occupied by the NY Power Authority as well as the storage area for sea containers for NYPD. The nearest residential units are 0.12 miles (approx. 650 feet) to the east-southeast. There are no records of Petroleum Bulk Storage or Chemical Bulk Storage on the site. The site did not qualify for addition to the Registry of Inactive Hazardous Waste Disposal Sites.
Env Problem: Based upon investigations conducted to date, the primary contaminants of concern at the site include mercury, lead and copper. In July 2009, following discovery of petroleum contaminated soil during excavation to support repairs to the Site?s bulkhead, three test pits were excavated to determine the extent of the petroleum impacts. A total of seven sidewall soil samples and one grab groundwater sample were collected from the test pits. One sample was also collected for waste classification from the stockpiled soil excavated from the initial excavation and the test pits. Sidewall samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, PCBs, pesticides and Total Petroleum Hydrocarbons. The composite waste classification sample was analyzed for TCLP parameters as well. The following contaminants with maximum concentrations were observed in soil: 17 ppm mercury; 1,100 ppm lead; and 330 ppm copper. The Part 375 Industrial Use Soil Cleanup Objectives (SCOs) have been exceeded for mercury, and the Part 375 Commercial Use SCOs have been exceeded for lead and copper. Groundwater samples were all below applicable Groundwater Standards for VOCs and SVOCs, but were not analyzed for metals. Depth to groundwater is approximately 9-15' below grade and is likely influenced by tidal action due to the immediately adjacent Gowanus Bay. Site characterization is required to evaluate the presence or absence of hazardous waste on the site, and to collect data sufficient to determine if the site poses a significant threat to public health or the environment. The site did not qualify for addition to the Registry of Inactive Hazardous Waste Disposal Sites.
Health Problem: Not reported
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS (Continued) **S110751210**

Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	Attn: Kay Zias
Owner Company:	NYC Economic Development Corp.
Owner Address:	110 William Street, 16th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10038-3940
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	NYPA
Address:	730 3RD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1010704 / 2011-01-21
Facility ID:	1010704
Facility Type:	ER
DER Facility ID:	398537
Site ID:	444318
DEC Region:	2
Spill Cause:	Other
Spill Class:	D5
SWIS:	2401
Spill Date:	2011-01-14
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2011-01-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-01-18
Spill Record Last Update:	2011-01-21
Spiller Name:	JOSHUA RAMAS

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS (Continued) **S110751210**

Spiller Company:	NYPA
Spiller Address:	730 3RD AVE
Spiller Company:	999
Contact Name:	JOSHUA RAMAS
DEC Memo:	Caller reporting a release
Remarks:	Not reported

All Materials:

Site ID:	444318
Operable Unit ID:	1194763
Operable Unit:	01
Material ID:	2190630
Material Code:	0025A
Material Name:	ammonia
Case No.:	07664417
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Air
Oxygenate:	Not reported

Site ID:	444318
Operable Unit ID:	1194763
Operable Unit:	01
Material ID:	2190629
Material Code:	0283A
Material Name:	carbon monoxide
Case No.:	00630080
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Air
Oxygenate:	Not reported

Name:	NY POWER AUTHORITY POWER PLANT
Address:	730 3RD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1010412 / 2011-01-06
Facility ID:	1010412
Facility Type:	ER
DER Facility ID:	398537
Site ID:	444015
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2011-01-05
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2011-01-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS (Continued) **S110751210**

Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-01-06
Spill Record Last Update: 2011-01-06
Spiller Name: JOSH RAMOS
Spiller Company: NY POWER AUTHORITY
Spiller Address: 730 3RD AVE
Spiller Company: 999
Contact Name: JOSH RAMOS
DEC Memo: equip failaure, immediate correction.
Remarks: minor issue.

All Materials:
Site ID: 444015
Operable Unit ID: 1194460
Operable Unit: 01
Material ID: 2190286
Material Code: 0243A
Material Name: nitrogen dioxide
Case No.: 10544726
Material FA: Hazardous Material
Quantity: 3.80
Units: G
Recovered: Not reported
Resource Affected: Air
Oxygenate: Not reported

Name: AIR
Address: 730 3RD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1101207 / 2011-05-03
Facility ID: 1101207
Facility Type: ER
DER Facility ID: 398537
Site ID: 448654
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: D5
SWIS: 2401
Spill Date: 2011-05-02
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 2011-05-03
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-05-03

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS (Continued) **S110751210**

Spill Record Last Update:	2011-05-03
Spiller Name:	JOSHUA
Spiller Company:	NY POWER AUTHORITY
Spiller Address:	730 3RD AVE
Spiller Company:	999
Contact Name:	JOSHUA
DEC Memo:	Not reported
Remarks:	NOx exceedance - copy forwarded to DEC Air Group

All Materials:

Site ID:	448654
Operable Unit ID:	1198884
Operable Unit:	01
Material ID:	2195216
Material Code:	0243A
Material Name:	nitrogen dioxide
Case No.:	10544726
Material FA:	Hazardous Material
Quantity:	.10
Units:	L
Recovered:	Not reported
Resource Affected:	Air
Oxygenate:	Not reported

Name:	NY POWER AUTHORITY/ GOWNAS POWER PLANT
Address:	730 3RD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1010032 / 2010-12-29
Facility ID:	1010032
Facility Type:	ER
DER Facility ID:	398537
Site ID:	443615
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	2010-12-20
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2010-12-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-12-21
Spill Record Last Update:	2010-12-29
Spiller Name:	JOSH RAMOS
Spiller Company:	NY POWER AUTHORITY/ GOWNAS POWER PLANT
Spiller Address:	730 3RD AVE
Spiller Company:	999
Contact Name:	JOSH RAMOS

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS (Continued) **S110751210**

DEC Memo:	exceeded emissions, operator error- corrected
Remarks:	Not reported

All Materials:

Site ID:	443615
Operable Unit ID:	1194068
Operable Unit:	01
Material ID:	2189706
Material Code:	0025A
Material Name:	ammonia
Case No.:	07664417
Material FA:	Hazardous Material
Quantity:	.05
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Air
Oxygenate:	Not reported

Name:	NY POWER AUTHORITY
Address:	730 3RD AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1011757 / 2011-02-25
Facility ID:	1011757
Facility Type:	ER
DER Facility ID:	398537
Site ID:	445647
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2011-02-24
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2011-02-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-02-25
Spill Record Last Update:	2011-02-25
Spiller Name:	Not reported
Spiller Company:	NY POWER AUTHORITY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JOSH RAMOS
DEC Memo:	0903 THE CALLER ADVISED DISPATCH THE SPILL WAS DUE TO AN ERROR INLET HEATER. THE AIR WAS IMPACTED. CLEAN UP NOT NECESSARY. NO CALL BACK IS NEEDED BY SPILLS REPRESENTATIVE.
Remarks:	Forwarded to DEC Air Unit

FORMER MOORE MCCORMACK LINES-CONTINENTAL TERMINALS (Continued) **S110751210**

All Materials:

Site ID:	445647
Operable Unit ID:	1196029
Operable Unit:	01
Material ID:	2192217
Material Code:	0243A
Material Name:	nitrogen dioxide
Case No.:	10544726
Material FA:	Hazardous Material
Quantity:	.10
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

326
SSW
1/2-1
0.869 mi.
4588 ft.

GENERAL TIRE
602 WEST 57TH ST
KINGS (County), NY 11220

NY SHWS **S113916584**
N/A

Relative:
Higher

Actual:
128 ft.

SHWS:

Name:	GENERAL TIRE
Address:	602 WEST 57TH ST
City,State,Zip:	NY 11220
Program:	HW
Site Code:	338762
Classification:	N
Region:	2
Acres:	Not reported
HW Code:	224022
Record Add:	11/18/1999
Record Upd:	12/16/2003
Updated By:	kstang
Site Description:	The site did not qualify for addition to the Registry of Inactive Hazardous Disposal Sites
Env Problem:	Not reported
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported

GENERAL TIRE (Continued) **S113916584**

Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AW327 **179 22ND STREET** **NY NYC OER** **S129932115**
NE **691 4TH AVENUE** **N/A**
1/2-1 **BROOKLYN, NY**
0.899 mi.
4746 ft. **Site 1 of 2 in cluster AW**

Relative: **Lower**
Actual: **42 ft.**

NYC OER:

Name:	179 22ND STREET
Address:	691 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.66222
Longitude:	-73.996179
OER Project Numbers:	18TMP0017K,18EHAZ047K,23CVCP038K
BBL:	3.00643000230064E+49
OER Program:	VCP (Enrolled), E/RD (Review)
Class:	Active (A)
Phase:	Approved Remedial Plan
URL:	https://a002-epic.nyc.gov/app/workspace/4595/docrepository
Postcode:	7
Community Board:	38
Council District:	145
Census Tract:	3000000
BIN:	3006430001
NTA:	Sunset Park West

AW328 **CON EDISON SERVICE BOX: S/B~45448** **RCRA NonGen / NLR** **1016677670**
NE **683 4TH AVE** **FINDS** **NYP004313391**
1/2-1 **BROOKLYN, NY 11217** **ECHO**
0.919 mi. **NY MANIFEST**
4853 ft. **Site 2 of 2 in cluster AW** **NY NYC OER**

Relative: **Lower**
Actual: **44 ft.**

RCRA Listings:

Date Form Received by Agency:	20130615
Handler Name:	Con Edison Service Box: S/B~45448
Handler Address:	4TH AVE
Handler City,State,Zip:	BROOKLYN, NY 11217
EPA ID:	NYP004313391
Contact Name:	KYLE ANDERSON
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-666-4596
Contact Fax:	Not reported
Contact Email:	Not reported

CON EDISON SERVICE BOX: S/B~45448 (Continued) **1016677670**

Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	VING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140402
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON SERVICE BOX: S/B~45448 (Continued) **1016677670**

Historic Generators:

Receive Date:		20130515
Handler Name:	CON EDISON SERVICE BOX:	S/B~45448
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
State District Owner:		Ny
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		No
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

Receive Date:		20130615
Handler Name:	CON EDISON SERVICE BOX:	S/B~45448
Federal Waste Generator Description:		Not a generator, verified
State District Owner:		Ny
Large Quantity Handler of Universal Waste:		No
Recognized Trader Importer:		No
Recognized Trader Exporter:		No
Spent Lead Acid Battery Importer:		No
Spent Lead Acid Battery Exporter:		No
Current Record:		Yes
Non Storage Recycler Activity:		Not reported
Electronic Manifest Broker:		Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058877256

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016677670
Registry ID: 110058877256

CON EDISON SERVICE BOX: S/B~45448 (Continued) **1016677670**

DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058877256
Name:	CON EDISON SERVICE BOX: S/B~45448
Address:	683 4TH AVE
City,State,Zip:	BROOKLYN, NY 11217

NY MANIFEST:

EPA ID:	NYP004313391
Country:	USA
Name:	CON EDISON
Address:	683 4TH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11217
Zip 4:	Not reported
Location Address 1:	683 4TH AVE
Location Address 2:	SERVICE BOX # 45448
Location City,State,Zip:	BROOKLYN, NY 11232
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD003812047
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/15/2013
Trans1 Recv Date:	05/15/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004313391
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002017481GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON SERVICE BOX: S/B~45448 (Continued) **1016677670**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	LEAD
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	150
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1

NYC OER:

Name:	683 4TH AVENUE
Address:	683 4TH AVENUE
City,State,Zip:	BROOKLYN, NY
Latitude:	40.66244
Longitude:	-73.995949
OER Project Numbers:	12TMP0131K,12EHAZ131K
BBL:	3006430005
OER Program:	E/RD (Review)
Class:	Completed (C)
Phase:	Site Management
URL:	https://a002-epic.nyc.gov/app/workspace/1107/docrepository
Postcode:	7
Community Board:	38
Council District:	145
Census Tract:	3420408
BIN:	3006430005
NTA:	Sunset Park West

Count: 9 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S121986656	25 ST & 4TH AVENUE	25 ST & 4TH AVENUE		NY Spills
BROOKLYN	S113917066	BROOKLYN MILITARY OCEAN TERMINAL	2ND AVE BTWN 57TH, 65TH STREET	11232	NY SHWS
BROOKLYN	S105003695	USPS GOWANUS SITE, FORMER MGP METR	2ND AVENUE AND 12TH STREET	11215	NY VCP, NY MGP
BROOKLYN	S113916585	DAVIDSON PIPE SUPPLY COMPANY	3RD AVE & 37TH STREET		NY SHWS
BROOKLYN	S113922111	455 SMITH STREET (VICHAR, INC.)	5TH STREET & SMITH STREET TO G	11231	NY VCP
BROOKLYN	1003864070	CARROL GARDEN	CORNER OF 5TH AND SMITH STREET	11231	SEMS-ARCHIVE
BROOKLYN	1003864120	REAR BUSH TERMINAL BUILDING	END OF 47TH THRU 52ND STREET	11232	SEMS-ARCHIVE
BROOKLYN	1000407436	NORTHEAST MARINE TERMINAL CO INC	FOOT OF 39TH ST	11232	CORRACTS, RCRA NonGen / NLR
BROOKLYN	S113922162	DANGMAN PARK	SHEEPSHEAD BAY ROAD & WEST 5TH	11215	NY VCP

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 12/26/2023
Date Data Arrived at EDR: 01/02/2024
Date Made Active in Reports: 01/24/2024
Number of Days to Update: 22

Source: EPA
Telephone: N/A
Last EDR Contact: 02/01/2024
Next Scheduled EDR Contact: 04/08/2024
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 12/26/2023
Date Data Arrived at EDR: 01/02/2024
Date Made Active in Reports: 01/24/2024
Number of Days to Update: 22

Source: EPA
Telephone: N/A
Last EDR Contact: 02/01/2024
Next Scheduled EDR Contact: 04/08/2024
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 12/26/2023
Date Data Arrived at EDR: 01/02/2024
Date Made Active in Reports: 01/24/2024
Number of Days to Update: 22

Source: EPA
Telephone: N/A
Last EDR Contact: 02/01/2024
Next Scheduled EDR Contact: 04/08/2024
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 12/20/2023
Date Data Arrived at EDR: 12/20/2023
Date Made Active in Reports: 01/24/2024
Number of Days to Update: 35

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 12/20/2023
Next Scheduled EDR Contact: 04/08/2024
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 09/19/2023
Date Data Arrived at EDR: 10/03/2023
Date Made Active in Reports: 10/19/2023
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 02/01/2024
Next Scheduled EDR Contact: 04/22/2024
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 09/19/2023
Date Data Arrived at EDR: 10/03/2023
Date Made Active in Reports: 10/19/2023
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 02/01/2024
Next Scheduled EDR Contact: 04/22/2024
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/04/2023
Date Data Arrived at EDR: 12/06/2023
Date Made Active in Reports: 12/12/2023
Number of Days to Update: 6

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 12/06/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 12/04/2023
Date Data Arrived at EDR: 12/06/2023
Date Made Active in Reports: 12/12/2023
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/06/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/04/2023
Date Data Arrived at EDR: 12/06/2023
Date Made Active in Reports: 12/12/2023
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/06/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 12/04/2023
Date Data Arrived at EDR: 12/06/2023
Date Made Active in Reports: 12/12/2023
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/06/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/04/2023
Date Data Arrived at EDR: 12/06/2023
Date Made Active in Reports: 12/12/2023
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/06/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 08/03/2023
Date Data Arrived at EDR: 08/07/2023
Date Made Active in Reports: 10/10/2023
Number of Days to Update: 64

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 02/02/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 10/26/2023
Date Data Arrived at EDR: 11/17/2023
Date Made Active in Reports: 02/13/2024
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/17/2023
Next Scheduled EDR Contact: 03/04/2024
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 10/26/2023
Date Data Arrived at EDR: 11/17/2023
Date Made Active in Reports: 02/13/2024
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/17/2023
Next Scheduled EDR Contact: 03/04/2024
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 09/18/2023
Date Data Arrived at EDR: 09/20/2023
Date Made Active in Reports: 12/11/2023
Number of Days to Update: 82

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 12/13/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 11/06/2023
Date Data Arrived at EDR: 11/07/2023
Date Made Active in Reports: 02/05/2024
Number of Days to Update: 90

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/07/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 09/27/2023
Date Data Arrived at EDR: 09/28/2023
Date Made Active in Reports: 12/19/2023
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 12/19/2023
Next Scheduled EDR Contact: 04/08/2024
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/25/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/14/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 01/24/2024
Date Data Arrived at EDR: 01/24/2024
Date Made Active in Reports: 01/25/2024
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/07/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 11/16/2023
Date Data Arrived at EDR: 11/16/2023
Date Made Active in Reports: 02/13/2024
Number of Days to Update: 89

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 01/11/2024
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 09/06/2023
Date Data Arrived at EDR: 09/06/2023
Date Made Active in Reports: 09/07/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/14/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 09/06/2023
Date Data Arrived at EDR: 09/06/2023
Date Made Active in Reports: 09/07/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/14/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 09/06/2023
Date Data Arrived at EDR: 09/06/2023
Date Made Active in Reports: 09/07/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/14/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 09/06/2023
Date Data Arrived at EDR: 09/06/2023
Date Made Active in Reports: 09/07/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/14/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/25/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/14/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 09/06/2023
Date Data Arrived at EDR: 09/06/2023
Date Made Active in Reports: 09/07/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 12/14/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 03/21/2023
Date Data Arrived at EDR: 06/20/2023
Date Made Active in Reports: 09/12/2023
Number of Days to Update: 84

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 12/14/2023
Next Scheduled EDR Contact: 03/25/2024
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 03/21/2023
Date Data Arrived at EDR: 06/14/2023
Date Made Active in Reports: 08/31/2023
Number of Days to Update: 78

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 12/11/2023
Next Scheduled EDR Contact: 03/25/2024
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 11/06/2023
Date Data Arrived at EDR: 11/07/2023
Date Made Active in Reports: 02/05/2024
Number of Days to Update: 90

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 02/07/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 11/06/2023
Date Data Arrived at EDR: 11/07/2023
Date Made Active in Reports: 02/05/2024
Number of Days to Update: 90

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 02/07/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Quarterly

Lists of state and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 11/06/2023
Date Data Arrived at EDR: 11/07/2023
Date Made Active in Reports: 02/05/2024
Number of Days to Update: 90

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 02/07/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Semi-Annually

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 12/12/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 09/05/2023
Date Data Arrived at EDR: 09/07/2023
Date Made Active in Reports: 11/28/2023
Number of Days to Update: 82

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 12/05/2023
Next Scheduled EDR Contact: 03/18/2024
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 11/06/2023
Date Data Arrived at EDR: 11/07/2023
Date Made Active in Reports: 02/05/2024
Number of Days to Update: 90

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 02/07/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 11/06/2023
Date Data Arrived at EDR: 11/07/2023
Date Made Active in Reports: 02/05/2024
Number of Days to Update: 90

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/07/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 08/15/2023
Date Data Arrived at EDR: 08/30/2023
Date Made Active in Reports: 12/01/2023
Number of Days to Update: 93

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 12/14/2023
Next Scheduled EDR Contact: 03/25/2024
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 11/28/2023
Next Scheduled EDR Contact: 03/18/2024
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 09/27/2023
Date Data Arrived at EDR: 09/28/2023
Date Made Active in Reports: 12/19/2023
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 12/19/2023
Next Scheduled EDR Contact: 04/08/2024
Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 01/26/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 01/11/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 11/17/2023
Date Data Arrived at EDR: 11/17/2023
Date Made Active in Reports: 02/07/2024
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/17/2023
Next Scheduled EDR Contact: 03/04/2024
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 11/06/2023
Date Data Arrived at EDR: 11/07/2023
Date Made Active in Reports: 02/05/2024
Number of Days to Update: 90

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/07/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 11/17/2023
Date Data Arrived at EDR: 11/17/2023
Date Made Active in Reports: 02/07/2024
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/17/2023
Next Scheduled EDR Contact: 03/04/2024
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 10/30/2023
Date Data Arrived at EDR: 11/01/2023
Date Made Active in Reports: 01/29/2024
Number of Days to Update: 89

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 01/29/2024
Next Scheduled EDR Contact: 05/13/2024
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 11/14/2023
Date Data Arrived at EDR: 12/22/2023
Date Made Active in Reports: 01/24/2024
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 02/01/2024
Next Scheduled EDR Contact: 04/08/2024
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 09/18/2023
Date Data Arrived at EDR: 09/20/2023
Date Made Active in Reports: 11/14/2023
Number of Days to Update: 55

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 12/13/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Quarterly

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 01/24/2024
Date Data Arrived at EDR: 01/24/2024
Date Made Active in Reports: 01/25/2024
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/07/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 12/04/2023
Date Data Arrived at EDR: 12/06/2023
Date Made Active in Reports: 12/12/2023
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/06/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 09/28/2023
Date Data Arrived at EDR: 11/10/2023
Date Made Active in Reports: 02/07/2024
Number of Days to Update: 89

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 02/13/2024
Next Scheduled EDR Contact: 05/27/2024
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 01/10/2024
Next Scheduled EDR Contact: 04/22/2024
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 01/05/2024
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 02/06/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 09/18/2023
Date Data Arrived at EDR: 09/20/2023
Date Made Active in Reports: 12/12/2023
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 12/13/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 01/29/2024
Next Scheduled EDR Contact: 05/13/2024
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 02/02/2024
Next Scheduled EDR Contact: 05/13/2024
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 12/14/2023
Next Scheduled EDR Contact: 03/25/2024
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2022
Date Data Arrived at EDR: 11/13/2023
Date Made Active in Reports: 02/07/2024
Number of Days to Update: 86

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 02/15/2024
Next Scheduled EDR Contact: 05/27/2024
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 10/19/2023
Date Data Arrived at EDR: 10/20/2023
Date Made Active in Reports: 01/16/2024
Number of Days to Update: 88

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 01/17/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 12/26/2023
Date Data Arrived at EDR: 01/02/2024
Date Made Active in Reports: 01/24/2024
Number of Days to Update: 22

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 02/01/2024
Next Scheduled EDR Contact: 03/11/2024
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 09/01/2023
Date Data Arrived at EDR: 09/27/2023
Date Made Active in Reports: 12/21/2023
Number of Days to Update: 85

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 01/12/2024
Next Scheduled EDR Contact: 04/19/2024
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 09/19/2023
Date Data Arrived at EDR: 10/03/2023
Date Made Active in Reports: 10/19/2023
Number of Days to Update: 16

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 02/01/2024
Next Scheduled EDR Contact: 05/13/2024
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 03/20/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 66

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 01/05/2024
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/26/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 07/20/2023
Date Data Arrived at EDR: 09/01/2023
Date Made Active in Reports: 09/20/2023
Number of Days to Update: 19
Source: Nuclear Regulatory Commission
Telephone: 301-415-0717
Last EDR Contact: 01/11/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 04/14/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 87
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 11/27/2023
Next Scheduled EDR Contact: 03/11/2024
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 11/27/2023
Next Scheduled EDR Contact: 03/11/2024
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 02/02/2024
Next Scheduled EDR Contact: 05/13/2024
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 12/19/2023
Next Scheduled EDR Contact: 04/08/2024
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 01/05/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 01/11/2024
Date Made Active in Reports: 01/16/2024
Number of Days to Update: 5

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 01/03/2024
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 12/06/2023
Next Scheduled EDR Contact: 04/01/2024
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 01/02/2024
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 01/29/2024
Next Scheduled EDR Contact: 05/13/2024
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 02/15/2024
Next Scheduled EDR Contact: 05/27/2024
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 12/26/2024
Date Data Arrived at EDR: 01/02/2024
Date Made Active in Reports: 01/24/2024
Number of Days to Update: 22

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 02/01/2024
Next Scheduled EDR Contact: 04/08/2024
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File
Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 11/01/2023
Date Data Arrived at EDR: 11/17/2023
Date Made Active in Reports: 02/13/2024
Number of Days to Update: 88

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 11/17/2023
Next Scheduled EDR Contact: 03/04/2024
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data
Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 01/02/2024
Date Data Arrived at EDR: 01/03/2024
Date Made Active in Reports: 01/04/2024
Number of Days to Update: 1

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 01/03/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing
This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 01/07/2022
Date Data Arrived at EDR: 02/24/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 82

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/20/2023
Next Scheduled EDR Contact: 03/04/2024
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing
Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/20/2023
Next Scheduled EDR Contact: 03/04/2024
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 08/23/2022
Date Data Arrived at EDR: 11/22/2022
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 98

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 11/20/2023
Next Scheduled EDR Contact: 03/04/2024
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 11/28/2023
Date Data Arrived at EDR: 11/29/2023
Date Made Active in Reports: 12/11/2023
Number of Days to Update: 12

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 11/28/2023
Next Scheduled EDR Contact: 03/18/2024
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 11/03/2023
Date Data Arrived at EDR: 11/08/2023
Date Made Active in Reports: 11/20/2023
Number of Days to Update: 12

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 11/08/2023
Next Scheduled EDR Contact: 03/11/2024
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 11/15/2023
Next Scheduled EDR Contact: 03/04/2024
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 09/23/2023
Date Data Arrived at EDR: 10/03/2023
Date Made Active in Reports: 01/04/2024
Number of Days to Update: 93

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 12/28/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 09/06/2023
Date Data Arrived at EDR: 09/13/2023
Date Made Active in Reports: 12/11/2023
Number of Days to Update: 89

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 01/05/2024
Next Scheduled EDR Contact: 04/22/2024
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 11/10/2023
Date Data Arrived at EDR: 11/10/2023
Date Made Active in Reports: 02/07/2024
Number of Days to Update: 89

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 02/13/2024
Next Scheduled EDR Contact: 05/27/2024
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 09/23/2023
Date Data Arrived at EDR: 10/03/2023
Date Made Active in Reports: 12/21/2023
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 12/28/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 09/23/2023
Date Data Arrived at EDR: 10/03/2023
Date Made Active in Reports: 12/21/2023
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/28/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

PFAS TRIS: List of PFAS Added to the TRI

Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 12/28/2023
Date Data Arrived at EDR: 12/28/2023
Date Made Active in Reports: 01/04/2024
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 12/28/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 12/28/2023
Date Data Arrived at EDR: 12/28/2023
Date Made Active in Reports: 01/04/2024
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/28/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 12/28/2023
Date Data Arrived at EDR: 12/28/2023
Date Made Active in Reports: 01/04/2024
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/28/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 06/24/2020
Date Data Arrived at EDR: 03/17/2021
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 601

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 01/22/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 09/23/2023
Date Data Arrived at EDR: 10/03/2023
Date Made Active in Reports: 10/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/28/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits. Caveats and Limitations: Less than half of states have required PFAS monitoring for at least one of their permittees and fewer states have established PFAS effluent limits for permittees. New rulemakings have been initiated that may increase the number of facilities monitoring for PFAS in the future.

Date of Government Version: 09/23/2023
Date Data Arrived at EDR: 10/03/2023
Date Made Active in Reports: 01/04/2024
Number of Days to Update: 93

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/28/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 09/23/2023
Date Data Arrived at EDR: 10/03/2023
Date Made Active in Reports: 12/21/2023
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/28/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

PFAS ECHO FIRE TRAINING: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 09/23/2023
Date Data Arrived at EDR: 10/03/2023
Date Made Active in Reports: 12/21/2023
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/28/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

PFAS PART 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 09/23/2023
Date Data Arrived at EDR: 10/03/2023
Date Made Active in Reports: 12/21/2023
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/28/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 09/23/2023
Date Data Arrived at EDR: 10/03/2023
Date Made Active in Reports: 12/21/2023
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-267-2675
Last EDR Contact: 12/28/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 12/16/2016
Date Data Arrived at EDR: 01/06/2017
Date Made Active in Reports: 03/10/2017
Number of Days to Update: 63

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 12/27/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: No Update Planned

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 12/27/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Varies

BIOSOLIDS: ICIS-NPDES Biosolids Facility Data

The data reflects compliance information about facilities in the biosolids program.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 01/03/2024
Date Made Active in Reports: 01/16/2024
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 202-564-4700
Last EDR Contact: 01/03/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 02/02/2024
Next Scheduled EDR Contact: 05/13/2024
Data Release Frequency: Varies

PFAS 3: PFAS Environmental Site Remediation List

Per- and Polyfluoroalkyl Substances (PFAS) are a group of chemicals used to make fluoropolymer coatings and products that resist heat, oil, stains, grease, and water. Fluoropolymer coatings are blends of resins and lubricants used in products such as water-repellent clothing, furniture, adhesives, paint and varnish, food packaging, heat-resistant non-stick cooking surfaces and insulation of electrical wires. Chemicals in this group include perfluorooctanoic acid (PFOA) and perfluorooctane sulfonic acid (PFOS).

Date of Government Version: 11/06/2023
Date Data Arrived at EDR: 11/07/2023
Date Made Active in Reports: 02/05/2024
Number of Days to Update: 90

Source: Department of Environmental Conservation
Telephone: 518-402-9759
Last EDR Contact: 02/07/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Varies

PFAS 2: New York State Inactive Landfill Initiative

A list of landfills that were investigated and the analytical results for PFOA and PFOS for those landfills. These data represent the landfills from the ILI database that were investigated.

Date of Government Version: 12/12/2022
Date Data Arrived at EDR: 08/10/2023
Date Made Active in Reports: 10/25/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 01/29/2024
Next Scheduled EDR Contact: 05/13/2024
Data Release Frequency: Varies

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 10/11/2023
Date Data Arrived at EDR: 10/26/2023
Date Made Active in Reports: 01/23/2024
Number of Days to Update: 89

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 01/12/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 09/08/2023
Date Data Arrived at EDR: 09/27/2023
Date Made Active in Reports: 12/18/2023
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 12/19/2023
Next Scheduled EDR Contact: 04/08/2024
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 11/29/2023
Date Data Arrived at EDR: 12/12/2023
Date Made Active in Reports: 12/19/2023
Number of Days to Update: 7

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 11/29/2023
Next Scheduled EDR Contact: 03/18/2024
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 07/26/2023
Date Data Arrived at EDR: 09/13/2023
Date Made Active in Reports: 12/07/2023
Number of Days to Update: 85

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 12/11/2023
Next Scheduled EDR Contact: 03/25/2024
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 10/01/2023
Date Data Arrived at EDR: 10/05/2023
Date Made Active in Reports: 12/21/2023
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 12/19/2023
Next Scheduled EDR Contact: 04/08/2024
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 07/31/2021
Date Data Arrived at EDR: 01/05/2023
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 11/29/2023
Next Scheduled EDR Contact: 03/18/2024
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 09/19/2023
Date Data Arrived at EDR: 11/02/2023
Date Made Active in Reports: 01/29/2024
Number of Days to Update: 88

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 01/31/2024
Next Scheduled EDR Contact: 05/13/2024
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 10/31/2023
Date Data Arrived at EDR: 11/02/2023
Date Made Active in Reports: 01/29/2024
Number of Days to Update: 88

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 01/31/2024
Next Scheduled EDR Contact: 05/13/2024
Data Release Frequency: Varies

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 11/30/2023
Date Made Active in Reports: 12/01/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 01/26/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 10/19/2023
Date Data Arrived at EDR: 11/09/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 89

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 01/12/2024
Next Scheduled EDR Contact: 04/29/2024
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 02/09/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 08/27/2023
Date Data Arrived at EDR: 08/30/2023
Date Made Active in Reports: 11/16/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 11/22/2023
Next Scheduled EDR Contact: 03/11/2024
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 10/03/2023
Date Data Arrived at EDR: 10/10/2023
Date Made Active in Reports: 01/04/2024
Number of Days to Update: 86

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 01/10/2024
Next Scheduled EDR Contact: 04/22/2024
Data Release Frequency: Varies

ILI: New York State Inactive Landfill Initiative

A solid waste site priority list of mitigation and remedial activities to address sites causing, or substantially contributing to, impairments of drinking water quality. Inactive solid waste disposal sites, primarily landfills, and their potential impact on New York?s drinking water resources from site-related contaminants, with a focus on emerging contaminants.

Date of Government Version: 06/24/2022
Date Data Arrived at EDR: 10/04/2023
Date Made Active in Reports: 12/21/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8671
Last EDR Contact: 01/29/2024
Next Scheduled EDR Contact: 05/13/2024
Data Release Frequency: Varies

NYC OER: OER Cleanup Sites Listing

Properties remediated under OER's oversight, both in the E-Designation program and the NYC Voluntary Cleanup Program. Includes sites completed and in progress.

Date of Government Version: 06/04/2023
Date Data Arrived at EDR: 06/06/2023
Date Made Active in Reports: 12/04/2023
Number of Days to Update: 181

Source: Office of Environmental Remediation
Telephone: 212-788-8841
Last EDR Contact: 12/05/2023
Next Scheduled EDR Contact: 03/18/2024
Data Release Frequency: Varies

NYC LAND USE: New York City Land Use Information

Land use colors

Date of Government Version: 05/15/2023
Date Data Arrived at EDR: 06/13/2023
Date Made Active in Reports: 01/03/2024
Number of Days to Update: 204

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 12/11/2023
Next Scheduled EDR Contact: 03/25/2024
Data Release Frequency: Varies

MGP: Manufactured Gas Plants Listing

From the late 1800's to the mid 1900's, hundreds of manufactured gas plants across New York State supplied homes and industry with fuel for heating, cooking, and lighting. Today, the New York State DEC is overseeing the investigation and cleanup of contamination left behind from these plants.

Date of Government Version: 11/15/2021
Date Data Arrived at EDR: 11/19/2021
Date Made Active in Reports: 12/12/2023
Number of Days to Update: 753

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 11/29/2023
Next Scheduled EDR Contact: 03/18/2024
Data Release Frequency: Varies

UST FINDER RELEASE: UST Finder Releases Database

US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/31/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 79

Source: Environmental Protecton Agency
Telephone: 202-564-0394
Last EDR Contact: 02/09/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Semi-Annually

UST FINDER: UST Finder Database

EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/04/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 106

Source: Environmental Protection Agency
Telephone: 202-564-0394
Last EDR Contact: 02/09/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List
The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List
The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 02/07/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 02/07/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/22/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 01/22/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 01/22/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: No Update Planned

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/22/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 01/22/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 11/21/2023
Next Scheduled EDR Contact: 03/11/2024
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 11/21/2023
Next Scheduled EDR Contact: 03/11/2024
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 01/22/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database
This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 01/22/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 01/22/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 07/03/2023
Date Data Arrived at EDR: 08/18/2023
Date Made Active in Reports: 11/03/2023
Number of Days to Update: 77

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 01/22/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 07/03/2023
Date Data Arrived at EDR: 08/18/2023
Date Made Active in Reports: 11/03/2023
Number of Days to Update: 77

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 01/22/2024
Next Scheduled EDR Contact: 05/06/2024
Data Release Frequency: Semi-Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 11/06/2023
Date Data Arrived at EDR: 11/07/2023
Date Made Active in Reports: 01/31/2024
Number of Days to Update: 85

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 02/06/2024
Next Scheduled EDR Contact: 05/20/2024
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 12/27/2023
Next Scheduled EDR Contact: 04/15/2024
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 01/05/2024
Next Scheduled EDR Contact: 04/22/2024
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 02/12/2024
Next Scheduled EDR Contact: 05/27/2024
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 01/05/2024
Next Scheduled EDR Contact: 04/22/2024
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 11/29/2023
Next Scheduled EDR Contact: 03/18/2024
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

4001 4TH AVENUE
4001 4TH AVENUE
BROOKLYN, NY 11232

TARGET PROPERTY COORDINATES

Latitude (North):	40.651717 - 40° 39' 6.18''
Longitude (West):	74.006618 - 74° 0' 23.82''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	583986.1
UTM Y (Meters):	4500358.5
Elevation:	51 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14317809 JERSEY CITY, NJ
Version Date:	2019
Northeast Map:	14115940 BROOKLYN, NY
Version Date:	2019

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NNW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 51 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3604970194F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
3604970192F	FEMA FIRM Flood data
3604970211F	FEMA FIRM Flood data
3604970073B	FEMA Q3 Flood data
3604970085B	FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
JERSEY CITY	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Mesozoic
System:	Cretaceous
Series:	Upper Cretaceous
Code:	uK *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	USGS40000827028	1/8 - 1/4 Mile NW
2	USGS40000827039	1/4 - 1/2 Mile North
A3	USGS40000827036	1/4 - 1/2 Mile NW
4	USGS40000827037	1/4 - 1/2 Mile NW
B5	USGS40000827003	1/4 - 1/2 Mile WNW
B6	USGS40000827004	1/4 - 1/2 Mile WNW
B8	USGS40000827016	1/4 - 1/2 Mile WNW
C9	USGS40000827051	1/4 - 1/2 Mile NW
10	USGS40000826538	1/2 - 1 Mile SW
11	USGS40000826496	1/2 - 1 Mile SSE
12	USGS40000827412	1/2 - 1 Mile NNW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
C7	NYREG1000000255	1/4 - 1/2 Mile NW
13	NYREG1000000181	1/2 - 1 Mile NE

PHYSICAL SETTING SOURCE MAP - 7571432.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons

- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

N

SITE NAME:	4001 4th Avenue	CLIENT:	Lesova Environmental Group
ADDRESS:	4001 4th Avenue Brooklyn NY 11232	CONTACT:	Dhruvi Patel
		INQUIRY #:	7571432.2s
LAT/LONG:	40.651717 / 74.006618	DATE:	February 16, 2024 4:08 pm

Copyright © 2024 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A1
NW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000827028**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1148. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	150	Well Hole Depth Units:	ft

2
North
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000827039**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 922. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Jameco Aquifer	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	150
Well Hole Depth Units:	ft		

A3
NW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000827036**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 167. 1	Type:	Well
Description:	3801	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	150	Well Hole Depth Units:	ft

4
NW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000827037**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1189. 1	Type:	Well
Description:	Not Reported	HUC:	02030201

Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Jameco Aquifer	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	144
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

B5
WNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000827003**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 944. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	157	Well Hole Depth Units:	ft

B6
WNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000827004**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1012. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	175	Well Hole Depth Units:	ft

C7
NW
1/4 - 1/2 Mile
Lower

NY WELLS **NYREG1000000255**

Well Number:	K003603D	Owner:	Paradise Plastics
Well Depth:	50	Diameter:	6
Casing Length:	0	Screen Diameter:	6
Screen Length:	20		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B8
WNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000827016**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2070. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	169	Well Hole Depth Units:	ft

C9
NW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000827051**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1271. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	1503	Well Hole Depth Units:	ft

10
SW
1/2 - 1 Mile
Higher

FED USGS **USGS40000826538**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1494. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	236
Well Depth Units:	ft	Well Hole Depth:	244
Well Hole Depth Units:	ft		

11
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS40000826496**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 245. 1	Type:	Well
Description:	0501	HUC:	02030201

Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	174
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

12
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000827412**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 698. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	100	Well Hole Depth Units:	ft

13
NE
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000000181**

Well Number:	K003532	Owner:	Greenwood Cemetary
Well Depth:	120	Diameter:	4
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.750 pCi/L	100%	0%	0%
Basement	1.370 pCi/L	88%	10%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX B - PROPERTY PROFILE OVERVIEW

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

4001 4 AVENUE **BROOKLYN 11232** **BIN# 3010582**

4 AVENUE	4001 - 4011	**Health Area**	: 6600	**Tax Block**	: 714
40 STREET	402 - 412	**Census Tract**	: 82	**Tax Lot**	: 6
		Community Board	: 307	**Condo**	: NO
		Buildings on Lot	: 2	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	40 STREET, 41 STREET		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	HAZMAT/AIR	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	NO
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: G3-GARAGE/GAS STAT'N

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	1	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	10	
ARA / LAA Jobs	1	
Total Jobs	11	
Actions	73	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

APPENDIX C - BUILDING PERMIT REPORT

4001 4th Avenue
4001 4th Avenue
Brooklyn, NY 11232

Inquiry Number: 7571432.8
February 16, 2024

EDR Building Permit Report

Target Property and Adjoining Properties

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

About This Report

Executive Summary

Findings

Glossary

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR BUILDING PERMIT REPORT

About This Report

The EDR Building Permit Report provides a practical and efficient method to search building department records for indications of environmental conditions. Generated via a search of municipal building permit records gathered from more than 1,600 cities nationwide, this report will assist you in meeting the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

Building permit data can be used to identify current and/or former operations and structures/features of environmental concern. The data can provide information on a target property and adjoining properties such as the presence of underground storage tanks, pump islands, sumps, drywells, etc., as well as information regarding water, sewer, natural gas, electrical connection dates, and current/former septic tanks.

Methodology

EDR has developed the EDR Building Permit Report through our partnership with BuildFax, the nation's largest repository of building department records. BuildFax collects, updates, and manages building department records from local municipal governments. The database now includes 30 million permits, on more than 10 million properties across 1,600 cities in the United States.

The EDR Building Permit Report comprises local municipal building permit records, gathered directly from local jurisdictions, including both target property and adjoining properties. Years of coverage vary by municipality. Data reported includes (where available): date of permit, permit type, permit number, status, valuation, contractor company, contractor name, and description.

Incoming permit data is checked at seven stages in a regimented quality control process, from initial data source interview, to data preparation, through final auditing. To ensure the building department is accurate, each of the seven quality control stages contains, on average, 15 additional quality checks, resulting in a process of approximately 105 quality control "touch points."

For more information about the EDR Building Permit Report, please contact your EDR Account Executive at (800) 352-0050.

EDR® Environmental Data Resources Inc

BUILD FAX PROPERTY HISTORY

EXECUTIVE SUMMARY: SEARCH DOCUMENTATION

A search of building department records was conducted by Environmental Data Resources, Inc (EDR) on behalf of Lesova Environmental Group on Feb 16, 2024.

TARGET PROPERTY

4001 4th Avenue
Brooklyn, NY 11232

SEARCH METHODS

EDR searches available lists for both the Target Property and Surrounding Properties.

RESEARCH SUMMARY

Building permits identified: **YES**

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

P//New York City, NY

Year	*Source*	*TP*	*Adjoining*
2023	New York City, Department of Buildings		X
2022	New York City, Department of Buildings		X
2021	New York City, Department of Buildings		X
2020	New York City, Department of Buildings		X
2019	New York City, Department of Buildings		X
2018	New York City, Department of Buildings		X
2017	New York City, Department of Buildings		X
2016	New York City, Department of Buildings		X
2015	New York City, Department of Buildings		X
	New York City, Department of Buildings	X	
2014	New York City, Department of Buildings		X
2013	New York City, Department of Buildings		X
2012	New York City, Department of Buildings		X
2011	New York City, Department of Buildings		X
	New York City, Department of Buildings	X	
2010	New York City, Department of Buildings		X
2009	New York City, Department of Buildings		X
	New York City, Department of Buildings	X	
2008	New York City, Department of Buildings		X
	New York City, Department of Buildings	X	
2007	New York City, Department of Buildings		X
2006	New York City, Department of Buildings		X
2005	New York City, Department of Buildings		X
2004	New York City, Department of Buildings		X
	New York City, Department of Buildings	X	
2003	New York City, Department of Buildings		X
2002	New York City, Department of Buildings		X
2001	New York City, Department of Buildings		X

EXECUTIVE SUMMARY: SEARCH DOCUMENTATION

Year	Source	TP	Adjoining
2000	New York City, Department of Buildings		X
1999	New York City, Department of Buildings		X
1998	New York City, Department of Buildings		X
1997	New York City, Department of Buildings		X
1996	New York City, Department of Buildings		X
1995	New York City, Department of Buildings		X
	New York City, Department of Buildings	X	
1994	New York City, Department of Buildings		X
	New York City, Department of Buildings	X	
1993	New York City, Department of Buildings		X
1992	New York City, Department of Buildings		X
1991	New York City, Department of Buildings		X
1990	New York City, Department of Buildings		X
1989	New York City, Department of Buildings		X
	New York City, Department of Buildings	X	
1988	New York City, Department of Buildings		X
1987	New York City, Department of Buildings		X
1986	New York City, Department of Buildings		X
1985	New York City, Department of Buildings		X
	New York City, Department of Buildings	X	
1984	New York City, Department of Buildings		X
1983	New York City, Department of Buildings		X
1982	New York City, Department of Buildings		X
1981	New York City, Department of Buildings		
1980	New York City, Department of Buildings		
1979	New York City, Department of Buildings		
1978	New York City, Department of Buildings		
1977	New York City, Department of Buildings		
1976	New York City, Department of Buildings		
1975	New York City, Department of Buildings		
1974	New York City, Department of Buildings		

Name: JurisdictionName
Years: Years
Source: Source
Phone: Phone

BUILDING DEPARTMENT RECORDS SEARCHED

Name: P//New York City, NY
Years: 1974-2023
Source: New York City, Department of Buildings, BROOKLYN, NY
Phone: (212) 566-5000

TARGET PROPERTY FINDINGS

TARGET PROPERTY DETAIL

4001 4th Avenue
Brooklyn, NY 11232

4001 4TH AVE

Date:	**8/4/2015**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	
Proposed Use:	
Permit Number:	B399207
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

Date:	**1/11/2011**
Permit Type:	**PL**
Description:	**PROPOSE TO INSTALL PLUMBING AND MECHANICAL AS PER PLANS FILED HEREWITH AND IN CONJUCTION WITH ALT II 301864515. NO CHANGE IN USE EGRESS OR OCCUPANCY IS PROPOSED UNDER THIS APPLICATION.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320042654-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MPC PLUMBING & HEATING IN

TARGET PROPERTY FINDINGS

Date:	**8/18/2009**
Permit Type:	**EW**
Description:	**RENOVATE EXISTING STORE INSTALL NEW ALLUMINUM DOORS AND WINDOWS AS SHOWN ON PLAN. NO CHANGE IN USE OCCUPANCY OR EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301864515-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	GEMSTAR CONSTRUCTION CORP

Date:	**8/18/2009**
Permit Type:	**EW**
Description:	**PROPOSE TO INSTALL PLUMBING AND MECHANICAL AS PER PLANS FILED HEREWITH AND IN CONJUCTION WITH ALT II 301864515. NO CHANGE IN USE EGRESS OR OCCUPANCY IS PROPOSED UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	320042654-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	GEMSTAR CONSTRUCTION CORP

Date:	**8/11/2009**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B319281
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AD ELECTRIC

TARGET PROPERTY FINDINGS

Date:	**7/9/2009**
Permit Type:	**EW**
Description:	**PROPOSE TO LINE EXISTING MOTOR FUELS TANKS, INSTALL NEW PIPING AND INSTALL NEW DISPENSERS ALL AS PER PLANS FILED HEREWITH. NO CHANGE IN USE EGRESS OR OCCUPANCY IS PROPOSED UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320041897-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALVIN PETROLEUM

Date:	**7/30/2008**
Permit Type:	**EW**
Description:	**INSTALL FIRE SUPPRESSION SYSTEM OVER EXISTING PUMP ISLANDS AS PER PLAN. THERE IS NO CHANGE TO USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FIRE SUPPRESSION
Permit Number:	310155667-01-EW-FP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ACTION FIRE SERVICES CO., INC.

Date:	**7/10/2008**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B306248
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JAM ELECTRICAL CORP

TARGET PROPERTY FINDINGS

Date: **3/31/2004**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B251579
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: M.B.S. ELECTRIC INC.

Date: **7/10/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FIRE SUPPRESSION
Permit Number: 300406022-01-EW-FP
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: FIRE GUARD OF LONG ISLAND, INC.

Date: **7/10/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300406022-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: GASOLINE INSTALLATIONS INC,.

TARGET PROPERTY FINDINGS

Date: **12/19/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B136104
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: THE FRANKLIN CO.

Date: **12/19/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B136105
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: THE FRANKLIN CO.

Date: **4/10/1989**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B051793
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: M.B.S. ELECTRIC INC.

TARGET PROPERTY FINDINGS

Date:	**8/20/1985**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	K23316
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	GASOLINE INSTALLATIONS, I

ADJOINING PROPERTY FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

38 ST

357 38 ST

Date:	**10/15/1999**
Permit Type:	**PL**
Description:	
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	300931838-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	KOMFORT HTG & PL INC

Date:	**10/8/1999**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	300931838-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	KOMFORT HTG & PL

ADJOINING PROPERTY FINDINGS

Date: **10/8/1999**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300931838-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: KOMFORT HTG & PL

411 38 ST

Date: **12/11/1991**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B093229
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: RAMDEEN'S ELEC. CONTR.COR

Date: **9/8/1987**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B027248
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: INTERPHASE ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

421 38 ST

Date:	**9/11/1995**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B144795
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EMPIRE ELEVATOR CORP.

38TH ST

427 38TH ST

Date:	**8/28/2023**
Permit Type:	**EW**
Description:	**ROOF #7 REPLACEMENT, PARAPET COPING AND RAILING & MISC. ROOF REPAIRS. REPLACEMENT OF TWO (2) VESTIBULES.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	322048609-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SKY HEIGHTS CONSTRUCTION

ADJOINING PROPERTY FINDINGS

Date:	**8/28/2023**
Permit Type:	**EW**
Description:	**STRUCTURAL FOUNDATION AND SUPPORTS FOR TWO (2) VESTIBULE REPLACEMENTS**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	322048609-02-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SKY HEIGHTS CONSTRUCTION

Date:	**10/5/2022**
Permit Type:	**EW**
Description:	**PROVIDE DRAIN FROM TWO (2) VESTIBULE ROOF LEADERS. REPLACE ONE ROOF DRAIN AT ROOF #7. REPLACE FIN TUBE AND UNIT HEATERS (2) AT EACH VESTIBULE. REPLACE LIGHTS AT TWO (2) VESTIBULES**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	322048609-03-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HEXAGON CONSTRUCTION & EL

ADJOINING PROPERTY FINDINGS

Date:	**10/4/2022**
Permit Type:	**EW**
Description:	**PROVIDE DRAIN FROM TWO (2) VESTIBULE ROOF LEADERS. REPLACE ONE ROOF DRAIN AT ROOF #7. REPLACE FIN TUBE AND UNIT HEATERS (2) AT EACH VESTIBULE. REPLACE LIGHTS AT TWO (2) VESTIBULES**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	322048609-03-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	THERMO TECH MECHANICAL I*

Date:	**10/4/2022**
Permit Type:	**PL**
Description:	**PROVIDE DRAIN FROM TWO (2) VESTIBULE ROOF LEADERS. REPLACE ONE ROOF DRAIN AT ROOF #7. REPLACE FIN TUBE AND UNIT HEATERS (2) AT EACH VESTIBULE. REPLACE LIGHTS AT TWO (2) VESTIBULES**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	322048609-03-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MAR-SAL PLBG & HTG, INC

ADJOINING PROPERTY FINDINGS

Date:	**3/6/2020**
Permit Type:	**EW**
Description:	**EXCAVATE FOR PLAYGROUND FOOTINGS, DISPOSE OF UNSUITABLE MATERIAL, INSTALL NEW CONCRETE FOOTING AND PLAY STRUCTURE**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	302586146-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SHAHEEN CONSTRUCTION CORP

Date:	**5/25/2018**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00047673I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	LASER ELECTRICAL CONTRACTING INC.

Date:	**12/11/2015**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	
Proposed Use:	
Permit Number:	B404680
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date: **9/15/2011**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B342578
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CHARAN ELEC'L ENTERP'S IN

Date: **7/16/2010**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B329152
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: PULSAR ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

39 ST

415 39 ST

Date:	**6/21/1994**
Permit Type:	**DM**
Description:	
Permit Description:	**DEMOLITION & REMOVAL**
Work Class:	DM - FULL DEMOLITION
Proposed Use:	
Permit Number:	300350732-01-DM
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	TESTA & WIRTH INC

Date:	**6/21/1994**
Permit Type:	**EQ**
Description:	
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	DM - FULL DEMOLITION
Proposed Use:	FENCE
Permit Number:	300350732-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	TESTA & WIRTH INC

ADJOINING PROPERTY FINDINGS

39TH ST

314 39TH ST

Date:	**8/19/2019**
Permit Type:	**EW**
Description:	**JOB FILED TO INSTALL (2) BOILER, HWH FOR 2ND, 3RD FLOOR. REMOVE REAR EXTENSION WITH TIMER WALL & ROOF AS GAME ROOM. RESOLVE ECB VIOLATION #34754194J & 34431926J. NO CHANGE OF USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	321757899-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALMA PLUMBING INC

Date:	**5/18/2019**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00169158I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WCK ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

Date:	**5/16/2019**
Permit Type:	**PL**
Description:	**JOB FILED TO INSTALL COOKING EQUIPMENT, MH HOOD AT 1ST FLOOR. NO CHANGE OF USE, EGRESS OR OCCUPANCY.**

Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321931683-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALMA PLUMBING INC

Date:	**4/16/2019**
Permit Type:	**EW**
Description:	**JOB FILED TO INSTALL COOKING EQUIPMENT, MH HOOD AT 1ST FLOOR. NO CHANGE OF USE, EGRESS OR OCCUPANCY.**

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	321931683-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	J'S CUSTOM CONTRACTING IN

ADJOINING PROPERTY FINDINGS

Date:	**4/16/2019**
Permit Type:	**EW**
Description:	**JOB FILED TO INSTALL COOKING EQUIPMENT, MH HOOD AT 1ST FLOOR. NO CHANGE OF USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321931683-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	J'S CUSTOM CONTRACTING IN

Date:	**4/16/2019**
Permit Type:	**PL**
Description:	**JOB FILED TO INSTALL (2) BOILER, HWH FOR 2ND, 3RD FLOOR. REMOVE REAR EXTENSION WITH TIMER WALL & ROOF AS GAME ROOM. RESOLVE ECB VIOLATION #34754194J & 34431926J. NO CHANGE OF USE, EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321757899-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALMA PLUMBING INC

ADJOINING PROPERTY FINDINGS

Date:	**2/4/2019**
Permit Type:	**EW**
Description:	**JOB FILED TO INSTALL (2) BOILER, HWH FOR 2ND, 3RD FLOOR. REMOVE REAR EXTENSION WITH TIMER WALL & ROOF AS GAME ROOM. RESOLVE ECB VIOLATION #34754194J & 34431926J. NO CHANGE OF USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321757899-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALMA DESIGN INC

Date:	**8/28/2018**
Permit Type:	
Description:	
Permit Description:	**Sign Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00028465I1SG
Status:	Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RED HOOK SIGN AND ELECTRIC CORP

ADJOINING PROPERTY FINDINGS

Date:	**8/23/2018**
Permit Type:	**EW**
Description:	**TO INSTALL A STRUCTURE FOR A NON ILLUMINATED ADVERTISING WALL SIGN**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321756532-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RED HOOK SIGN AND ELECTRI

Date:	**7/14/2014**
Permit Type:	**EQ**
Description:	**PROPOSED INSTALLATION OF HEAVY DUTY SIDEWALK SHED FILED FOR REMEDIAL REPAIRS AS PER PLANS. LIVE LOAD 300 PER SQUARE FEET. SIDEWALK SHED SHALL COMPLY WITH CHAPTER # 33 OF THE 2008 CODE. NO CHANGE IN USE OCCUPANCY OR EGRESS UNDER THIS APPLICATION**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	340163922-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SHAH BUILDERS INC

ADJOINING PROPERTY FINDINGS

Date: **7/10/2014**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B383248
Status: Open
Valuation: $0.00
Contractor Company:
Contractor Name: RPJ ELECTRIC CORP

Date: **3/5/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B109708
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: EMPIRE ELECT. CONTR'G INC

ADJOINING PROPERTY FINDINGS

318 39TH ST

Date:	**10/29/2010**
Permit Type:	**PL**
Description:	**CONSTRUCTION OF BOILER ROOM ENCLOSURE/PARTITIONS, AND INSTALLATION OF THREE (3) NEW BOILERS AS PER PLANS FILED HEREWITH. NO CHANGE TO USE, OCCUPANCY, OR EGRESS.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320175877-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JFR CONSTRUCTION CORP

Date:	**9/22/2010**
Permit Type:	**EW**
Description:	**CONSTRUCTION OF BOILER ROOM ENCLOSURE/PARTITIONS, AND INSTALLATION OF THREE (3) NEW BOILERS AS PER PLANS FILED HEREWITH. NO CHANGE TO USE, OCCUPANCY, OR EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320175877-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AGRAS CONSTRUCTION CORP

ADJOINING PROPERTY FINDINGS

Date:	**4/20/2007**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION OF EXISTING COMMERCIAL SPACE. NO CHANGE OF USE OF EGRESS USE OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	302275035-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

319 39TH ST

Date:	**11/16/2001**
Permit Type:	**AL**
Description:	**To install ground sign structure within property line located within 200' of an arterial highway. No change in use, occupancy or egress.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	301101242-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NORTH SHORE NEON SIGN CO INC

ADJOINING PROPERTY FINDINGS

Date: **10/2/2001**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 301101224-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTH SHORE NEON SIGN CO INC

Date: **10/2/2001**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 301101233-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTH SHORE NEON SIGN CO INC

320 39TH ST

Date: **10/12/1990**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B075338
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ACG ELEC'L CONTR'S

ADJOINING PROPERTY FINDINGS

321 39TH ST

Date:	**1/16/2004**
Permit Type:	**SG**
Description:	
Permit Description:	**SIGN**
Work Class:	SG - SIGN
Proposed Use:	
Permit Number:	301677068-01-SG
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PAUL SIGNS

Date:	**10/28/2003**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B247466
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AMPCO TECH ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

Date:	**6/20/2003**
Permit Type:	**EQ**
Description:	**INSTALLATION OF A HEAVY DUTY SIDEWALK SHED 50' DURING MASONRY REPAIR. (NO DOB REQUIRED). SHED TO COMPLY WITH LL33/91 AND TPPN 9/99. NO CHANGE IN USE, EGRESS OR OCCUPANCY**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	301555074-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PERIMETER BRIDGE & SCAFFOLD CO I

Date:	**6/16/2003**
Permit Type:	**EQ**
Description:	**Enlargement of accessory office at 2nd floor as well as new brick and stucco facade at street elevation. No change in egress use or occupancy,**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FENCE
Permit Number:	301516857-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MASTER BUILDERS

ADJOINING PROPERTY FINDINGS

Date:	**6/16/2003**
Permit Type:	**EW**
Description:	**Enlargement of accessory office at 2nd floor as well as new brick and stucco facade at street elevation. No change in egress use or occupancy,**

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	301516857-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MASTER BUILDERS

Date:	**6/16/2003**
Permit Type:	**EW**
Description:	**Enlargement of accessory office at 2nd floor as well as new brick and stucco facade at street elevation. No change in egress use or occupancy,**

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301516857-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MASTER BUILDERS

Date:	**4/4/1997**
Permit Type:	**EW**
Description:	

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	300623975-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	C.D.E.AIR CONDITIONING CO INC

ADJOINING PROPERTY FINDINGS

Date: **4/4/1997**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300623975-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: C.D.E.AIR CONDITIONING CO INC

324 39TH ST

Date: **12/28/1988**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B047451
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ALWON ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

326 39TH ST

Date: **10/14/1999**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B194821
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: AL FOY ELECTRIC

Date: **11/5/1998**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B184207
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: VINTAGE ELEC. SERVICE INC

ADJOINING PROPERTY FINDINGS

328 39TH ST

Date: **10/2/2013**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: MINOR WORK
Proposed Use:
Permit Number: B373056
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: RIVIERA ELECTRIC CORP

Date: **9/17/2007**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B295383
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: HABER ELECTRIC CO. INC.

Date: **3/10/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B110724
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ALWON ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

330 39TH ST

Date:	**6/16/2017**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B430129
Status:	OBJECTN PENDING AT CONTRACTOR
Valuation:	$0.00
Contractor Company:	
Contractor Name:	KJK ELECTRIC INC

332 39TH ST

Date:	**8/27/1990**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B073250
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MANDA ELECTRIC CO.

ADJOINING PROPERTY FINDINGS

334 39TH ST

Date:	**4/6/1998**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B176171
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AL-ARM ELEC'L CONST.CORP

Date:	**8/14/1997**
Permit Type:	**AL**
Description:	
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	300651346-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SUNSHINE QUALITY CONSTRUCTION IN

ADJOINING PROPERTY FINDINGS

340 39TH ST

Date:	**11/1/1996**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B159123
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EMPIRE ELECT. CONTR'G INC

341 39TH ST

Date:	**8/1/2023**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00911938I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	LUNA NYC ELECTRIC CORP

ADJOINING PROPERTY FINDINGS

Date: **7/19/2023**
Permit Type:
Description:

Permit Description: **Sign Permit**
Work Class:
Proposed Use:
Permit Number: B00832501I1SG
Status: Issued
Valuation: $0.00
Contractor Company:
Contractor Name: SIGNS CAD CORP

Date: **10/26/2022**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B08026894I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: A&E ELECTRICAL SYSTEMS CO

Date: **5/21/2022**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00742519I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: CAPONE ELECL CONTRS CORP

ADJOINING PROPERTY FINDINGS

Date: **5/21/2022**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00742591I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: CAPONE ELECL CONTRS CORP

Date: **5/21/2022**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00742656I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: CAPONE ELECL CONTRS CORP

Date: **5/21/2022**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00742676I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: CAPONE ELECL CONTRS CORP

ADJOINING PROPERTY FINDINGS

Date: **5/20/2022**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00741509I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: CAPONE ELECL CONTRS CORP

Date: **6/11/2020**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00356635I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: PREMIUM ELECTRIC INC

Date: **8/13/2019**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 321432972-01-AL
Status: RE-ISSUED, ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: MEGA CONTRACTING GP LLC

ADJOINING PROPERTY FINDINGS

Date:	**4/27/2019**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00159770I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ELITE ELECTRICAL & WIRING

Date:	**9/20/2018**
Permit Type:	**EW**
Description:	**INSTALLATION OF NEW EMERGENCY GENERATOR ON THE 8TH FLOOR WITH RELATED FUEL-OIL TANK AND FUEL-OIL PUMP ON THE CELLAR LEVEL; RELATED WORK AS PER PLANS SUBMITTED HEREWITH. NO CHANGE IN BUILDING USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	321581427-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MEGA CONTRACTING GP LLC

ADJOINING PROPERTY FINDINGS

Date:	**6/8/2018**
Permit Type:	**EQ**
Description:	**PROPOSED INSTALLATION OF PLYWOOD FENCE AS PER PLANS. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	340512341-01-EQ-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EVEREST SCAFFOLDING INC

Date:	**6/8/2018**
Permit Type:	**EW**
Description:	**INTERIOR ARCHITECTURAL CHANGES ON THE PART OF THE 1ST THRU 10TH FLOORS, CELLAR, AND ROOF WITH RELATED WORK AS PER PLANS SUBMITTED HEREWITH. NO CHANGE IN BUILDING USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321546608-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MEGA CONTRACTING GP LLC

ADJOINING PROPERTY FINDINGS

Date:	**6/8/2018**
Permit Type:	**EW**
Description:	**STRUCTURAL MODIFICATIONS ON PART OF THE 1ST THRU 10TH FLOORS, CELLAR, AND ROOF LEVEL WITH RELATED WORK AS PER PLANS SUBMITTED HEREWITH. NO CHANGE IN BUILDING USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321546608-02-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MEGA CONTRACTING GP LLC

Date:	**6/4/2018**
Permit Type:	**EW**
Description:	**SPRINKLER AND STANDPIPE SYSTEM MODIFICATIONS ON THE 1ST THRU 10TH FLOORS, CELLAR, AND ROOF LEVELS AS PER PLANS SUBMITTED HEREWITH. NO CHANGE IN BUILDING USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	STAND PIPE
Permit Number:	321444807-01-EW-SD
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ARISTA PLBG. & HTG. CORP

ADJOINING PROPERTY FINDINGS

Date:	**6/4/2018**
Permit Type:	**EW**
Description:	**SPRINKLER AND STANDPIPE SYSTEM MODIFICATIONS ON THE 1ST THRU 10TH FLOORS, CELLAR, AND ROOF LEVELS AS PER PLANS SUBMITTED HEREWITH. NO CHANGE IN BUILDING USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	SPRINKLER
Permit Number:	321444807-01-EW-SP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ARISTA PLBG. & HTG. CORP

Date:	**5/25/2018**
Permit Type:	**PL**
Description:	**MECHANICAL AND PLUMBING ALTERATIONS RELATED TO THE MERGE OF TWO PROPERTIES (341 & 351 39TH STREET; LOTS 54 AND 51, RESPECTIVELY) UNDER A SINGLE ZONING LOT AND CHANGE OF PRIMARY USE/OCCUPANCY OF BUILDING AS PER PLANS SUBMITTED HEREWITH.**
Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	321432972-03-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	D.D.S. MECH PBG&HTG CORP

ADJOINING PROPERTY FINDINGS

Date:	**4/20/2018**
Permit Type:	**EQ**
Description:	**PROPOSED INSTALLATION OF PIPE SCAFFOLD AS PER PLANS. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SCAFFOLD
Permit Number:	340381090-01-EQ-SF
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EVEREST SCAFFOLDING INC

Date:	**4/11/2018**
Permit Type:	**EW**
Description:	**INSTALLATION OF NEW EMERGENCY GENERATOR ON THE 8TH FLOOR WITH RELATED FUEL-OIL TANK AND FUEL-OIL PUMP ON THE CELLAR LEVEL; RELATED WORK AS PER PLANS SUBMITTED HEREWITH. NO CHANGE IN BUILDING USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FUEL STORAGE
Permit Number:	321581427-01-EW-FS
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BONDEE ENTERPRISES INC

ADJOINING PROPERTY FINDINGS

Date:	**4/9/2018**
Permit Type:	**EQ**
Description:	**PROPOSED INSTALLATION OF HEAVY DUTY SIDEWALK SHED AS PER PLANS. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	340380689-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EVEREST SCAFFOLDING INC

Date:	**3/28/2018**
Permit Type:	**EQ**
Description:	**INSTALLATION OF PERSONNEL/MATERIAL HOIST AS PER PLANS IN CONJUNCTION WITH STRUCTURAL WORK. NO CHANGE IN USE, EGRESS OR OCCUPANCY. HOIST TO COMPLY WITH CHAPTER 33 OF NYC BUILDING CODE OF 2014.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321496207-01-EQ-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	REPUBLIC SCAFFOLD&HOIST C

ADJOINING PROPERTY FINDINGS

Date:	**2/23/2018**
Permit Type:	**EW**
Description:	**RENOVATION AND MAINTENANCE WORK ON THE SOUTH, EAST, AND WEST BUILDING FACADES (NORTH FACADE N.I.C.) WITH RELATED WORK AS PER PLANS SUBMITTED HEREWITH. NO CHANGE IN BUILDING USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321449526-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SKYLINE RESTORATION INC

Date:	**10/11/2017**
Permit Type:	**EQ**
Description:	**INSTALLATION OF A TEMPORARY SCAFFOLD AS PER PLANS DURING GENERAL CONSTRUCTION WORK. NO CHANGE IN USE, EGRESS OR OCCUPANCY. SCAFFOLD TO COMPLY WITH CHAPTER 33 OF NYC BUILDING CODE OF 2014.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SCAFFOLD
Permit Number:	321667692-01-EQ-SF
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JJ MATTHEWS INC

ADJOINING PROPERTY FINDINGS

Date: **3/20/2017**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B425686
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: V. VASS ELECTRIC CORP

Date: **2/15/2017**
Permit Type: **EW**
Description: **INTERIOR DEMOLITION OF NONLOADBEARING PARTITIONS ON THE 1ST THRU 10TH FLOORS AND CELLAR LEVEL, RELATED WORK AS PER PLANS SUBMITTED HEREWITH. NO CHANGE IN BUILDING USE, EGRESS, OR OCCUPANCY.**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 321449517-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WORLD CLASS CONTRACTING

Date: **1/24/2017**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B422902
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: CSI SEC & ELECTRIC INC

ADJOINING PROPERTY FINDINGS

Date:	**5/7/2016**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B411160
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BOROWIDE ELECT'L CONTR'S

Date:	**1/11/2016**
Permit Type:	**EQ**
Description:	**INSTALLATION OF SIDEWALK SHED AS PER PLANS. WORK SHALL COMPLY WITH 2008 BUILDING CODE, CHAPTER 33. NO CHANGE IN USE EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	320855829-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	COLGATE ENTERPRISE CORP

ADJOINING PROPERTY FINDINGS

Date:	**6/5/2014**
Permit Type:	**AL**
Description:	**INSTALLATION OF EQUIPMENT CABINET ON ROOF WITH RELATED ANTENNAS ON ROOF.ALL IN CONFORMANCE WITH TPPN#5/98.NO CHANGE IN USE,EGRESS OR OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	321005327-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HPC WIRELESS SERVICES LLC

Date:	**8/27/2013**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B371780
Status:	Open
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NASH ELECTRIC SERVICES IN

Date:	**8/19/2013**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B371413
Status:	Open
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JAY UNITED ELECL CONTNG

ADJOINING PROPERTY FINDINGS

Date:	**8/13/2012**
Permit Type:	**EW**
Description:	**INSTALL TWO (2) HIGH PRESSURE BOILERS PER PLANS ON 10TH FLOOR. CONSTRUCT NEW BOILER ROOM ENCLOSURE.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	320518221-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SEICKEL & SONS PLBG. INC

Date:	**8/13/2012**
Permit Type:	**EW**
Description:	**INSTALL TWO (2) HIGH PRESSURE BOILERS PER PLANS ON 10TH FLOOR. CONSTRUCT NEW BOILER ROOM ENCLOSURE.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320518221-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SEICKEL AND SONS PLUMB IN

ADJOINING PROPERTY FINDINGS

Date:	**8/13/2012**
Permit Type:	**PL**
Description:	**INSTALL TWO (2) HIGH PRESSURE BOILERS PER PLANS ON 10TH FLOOR. CONSTRUCT NEW BOILER ROOM ENCLOSURE.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320518221-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SEICKEL & SONS PLBG. INC

Date:	**1/9/2012**
Permit Type:	**EW**
Description:	**REPLACE GAS BOILER.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	320417303-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	STUART ISER INC

Date:	**1/9/2012**
Permit Type:	**PL**
Description:	**REPLACE GAS BOILER.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320417303-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	STUART ISER INC

ADJOINING PROPERTY FINDINGS

Date:	**9/18/2009**
Permit Type:	**EW**
Description:	**LEGALIZE GAS HIGH PRESSURE BOILER. PENALTY FEE PAID UNDER APPLICATION # 310301599**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	320070294-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SEICKEL & SONS PLBG. INC

Date:	**9/18/2009**
Permit Type:	**PL**
Description:	**LEGALIZE GAS HIGH PRESSURE BOILER. PENALTY FEE PAID UNDER APPLICATION # 310301599**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320070294-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SEICKEL & SONS PLBG. INC

Date:	**8/24/2009**
Permit Type:	**EW**
Description:	**REPLACE GAS HIGH PRESSURE BOILER.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	310301599-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SEICKEL & SONS PLBG. INC

ADJOINING PROPERTY FINDINGS

Date:	**8/24/2009**
Permit Type:	**PL**
Description:	**REPLACE GAS HIGH PRESSURE BOILER.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	310301599-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SEICKEL & SONS PLBG. INC

Date:	**8/29/2006**
Permit Type:	**EW**
Description:	**Installation of reconditioned natural gas process boiler. No change in use, occupancy or egress.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	302182055-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	METROPOLITAN HT & PWR CO INC

Date:	**8/29/2006**
Permit Type:	**PL**
Description:	**Installation of reconditioned natural gas process boiler. No change in use, occupancy or egress.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	302182055-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	METROPOLITAN HT & PWR CO INC

ADJOINING PROPERTY FINDINGS

Date:	**9/29/2005**
Permit Type:	**EW**
Description:	**INSTALLING TELECOMUNICATIONS SHELTER WIT H HVAC RELATED DUNNAGE & RELATE ANTENNAS ON ROOF IN CONFORMANCE WITH TP PN #5/98 NO CHANGE IN USE EGRESS OR OCCUPANCY**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	301932201-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ARETE DEVELOPMT INC

Date:	**9/29/2005**
Permit Type:	**EW**
Description:	**INSTALLING TELECOMUNICATIONS SHELTER WIT H HVAC RELATED DUNNAGE & RELATE ANTENNAS ON ROOF IN CONFORMANCE WITH TP PN #5/98 NO CHANGE IN USE EGRESS OR OCCUPANCY**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301932201-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ARETE DEVELOPMT INC

ADJOINING PROPERTY FINDINGS

Date:	**4/29/2004**
Permit Type:	**EW**
Description:	**INSTALL GAS FIRED HIGH PRESSURE BOILER AND BOILER ROOM ENCLOSURE. NO CHANGE IN EGRESS, OCCUPANCY, OR USE UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	301696591-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	STUART ISER INC.

Date:	**4/29/2004**
Permit Type:	**EW**
Description:	**INSTALL GAS FIRED HIGH PRESSURE BOILER AND BOILER ROOM ENCLOSURE. NO CHANGE IN EGRESS, OCCUPANCY, OR USE UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301696591-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	STUART ISER INC.

ADJOINING PROPERTY FINDINGS

Date:	**4/29/2004**
Permit Type:	**PL**
Description:	**INSTALL GAS FIRED HIGH PRESSURE BOILER AND BOILER ROOM ENCLOSURE. NO CHANGE IN EGRESS, OCCUPANCY, OR USE UNDER THIS APPLICATION.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	301696591-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	STUART ISER INC.

Date:	**2/25/2002**
Permit Type:	**EW**
Description:	**INSTALL (2) HIGH PRESSURE GAS BOILERS, (2) GAS METERS AND (1) BOILER EN CLOSURE. NO CHANGE IN EGRESS, OCCUPANCY OR USE UNDER THIS APPLICATION. LOCAL LAW 17/95 DOES NOT APPLY TO THIS APPLILCATI ON.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	301296675-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SEICKEL & SONS PLBG

ADJOINING PROPERTY FINDINGS

Date:	**2/25/2002**
Permit Type:	**EW**
Description:	**INSTALL (2) HIGH PRESSURE GAS BOILERS, (2) GAS METERS AND (1) BOILER EN CLOSURE. NO CHANGE IN EGRESS, OCCUPANCY OR USE UNDER THIS APPLICATION. LOCAL LAW 17/95 DOES NOT APPLY TO THIS APPLILCATI ON.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301296675-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SEICKEL & SONS PLBG

Date:	**2/25/2002**
Permit Type:	**PL**
Description:	**INSTALL (2) HIGH PRESSURE GAS BOILERS, (2) GAS METERS AND (1) BOILER EN CLOSURE. NO CHANGE IN EGRESS, OCCUPANCY OR USE UNDER THIS APPLICATION. LOCAL LAW 17/95 DOES NOT APPLY TO THIS APPLILCATI ON.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	301296675-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SEICKEL & SONS PLBG

ADJOINING PROPERTY FINDINGS

Date:	**9/5/2001**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B217814
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HEWS ELECTRIC INC.

Date:	**7/12/2001**
Permit Type:	**EW**
Description:	**INSTALL RADIO ANTENNAE ON ROOF NO CHANGE IN USE OCCUPANCY OR EGRESS**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301189176-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AMERICAN TOWER CORP.

ADJOINING PROPERTY FINDINGS

Date:	**3/6/2000**
Permit Type:	**EW**
Description:	**REPLACE (2)GAS FIRED PACKAGE BOILERS AND CONNECT TO EXISTING GAS SERVIC .INSTALL (1)BOILER ROOM ENCLOSURE.NO CHANGE IN EGRESS,OCCUPANCY OR USE UNDER THIS APPLICATION.LOCAL LAW 17/95 DOES NO T APPLY TO THIS APPLICATION**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	300995706-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	STUART ISERR INC

Date:	**3/6/2000**
Permit Type:	**EW**
Description:	**REPLACE (2)GAS FIRED PACKAGE BOILERS AND CONNECT TO EXISTING GAS SERVIC .INSTALL (1)BOILER ROOM ENCLOSURE.NO CHANGE IN EGRESS,OCCUPANCY OR USE UNDER THIS APPLICATION.LOCAL LAW 17/95 DOES NO T APPLY TO THIS APPLICATION**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	300995706-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	STUART ISERR INC

ADJOINING PROPERTY FINDINGS

Date:	**3/6/2000**
Permit Type:	**PL**
Description:	**REPLACE (2)GAS FIRED PACKAGE BOILERS AND CONNECT TO EXISTING GAS SERVIC .INSTALL (1)BOILER ROOM ENCLOSURE.NO CHANGE IN EGRESS,OCCUPANCY OR USE UNDER THIS APPLICATION.LOCAL LAW 17/95 DOES NO T APPLY TO THIS APPLICATION**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	300995706-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	STUART ISERR INC

Date:	**11/8/1999**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	300947509-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	STUART_ISER INC

ADJOINING PROPERTY FINDINGS

Date: **11/8/1999**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300947509-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: STUART_ISER INC

Date: **6/29/1998**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use: SIDEWALK SHED
Permit Number: 300740875-01-EQ-SH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: YORK SCAFFOLDING

Date: **6/18/1998**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B179499
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: E. FITZGERALD ELEC CO

ADJOINING PROPERTY FINDINGS

Date: **4/10/1998**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FUEL BURNING
Permit Number: 300707714-01-EW-FB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: A-C COMBUSTION SERVICE

Date: **2/9/1998**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B174428
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: WINKLER ELECTRICIANS INC.

Date: **3/8/1996**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300473002-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: MAINLAND PLUMBING AND HEATING

ADJOINING PROPERTY FINDINGS

Date: **3/6/1996**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300473002-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: MAINLAND PLUMBING AND HEATING

Date: **3/1/1996**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300493268-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL & SONS PLMB.INC.

Date: **3/1/1996**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300493268-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL & SONS PLMB.INC.

ADJOINING PROPERTY FINDINGS

Date: **3/1/1996**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300493268-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL & SONS PLMB.INC.

Date: **9/8/1995**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300461122-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL & SONS PLUMBING INC

Date: **9/7/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300458582-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL & SONS PLUMBING INC

ADJOINING PROPERTY FINDINGS

Date: **9/7/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300458582-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL & SONS PLUMBING INC

Date: **9/7/1995**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300458582-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL & SONS PLUMBING

Date: **9/7/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300461122-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL & SONS PLUMBING INC

ADJOINING PROPERTY FINDINGS

Date: **9/7/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300461122-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL & SONS PLUMBING INC

Date: **3/22/1994**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300324995-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WASOFF PLUMBING & UTILITY CO.INC

Date: **3/22/1994**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300324995-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WASOFF PLUMBING & UTILITY CO.INC

ADJOINING PROPERTY FINDINGS

Date: **3/22/1994**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300324995-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WASOFF PLUMBING & UTILITY CO.INC

Date: **12/27/1993**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300312686-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: STUART ISER INC.

Date: **12/27/1993**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300312686-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: STUART ISER INC.

ADJOINING PROPERTY FINDINGS

Date: **12/27/1993**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300312686-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: STUART ISER INC.

Date: **5/26/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B113256
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A.S.M. ELEC. & MACH. CORP

Date: **3/3/1993**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300224754-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL AND SONS PLUMBING INC.

ADJOINING PROPERTY FINDINGS

Date: **3/3/1993**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300224754-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL AND SONS PLUMBING INC.

Date: **9/16/1992**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300197935-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL AND SONS PLUMBING INC.

Date: **9/16/1992**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300197935-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL AND SONS PLUMBING INC.

ADJOINING PROPERTY FINDINGS

Date: **9/8/1992**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use:
Permit Number: 300195937-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEUNG YUNG

Date: **8/31/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B102751
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A.S.M. ELEC. & MACH. CORP

Date: **7/27/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B102232
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ROTHSTEIN & HOFFMAN ELEC.

ADJOINING PROPERTY FINDINGS

Date: **7/15/1992**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300183780-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL AND SONS PLUMBING INC.

Date: **7/15/1992**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300183780-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL AND SONS PLUMBING INC.

Date: **5/1/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B098798
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A.S.M. ELEC. & MACH. CORP

ADJOINING PROPERTY FINDINGS

Date: **3/2/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B096282
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A.S.M. ELEC. & MACH. CORP

Date: **12/31/1991**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300143958-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: A & H EQUIPMENT INC

Date: **12/31/1991**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300143958-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WASOFF PLUMBING & UTILITY CO

ADJOINING PROPERTY FINDINGS

Date: **12/12/1991**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300140826-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: STUART ISER INC.

Date: **12/12/1991**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300140826-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL & SONS INC.

Date: **12/12/1991**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300140826-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SEICKEL & SONS INC.

ADJOINING PROPERTY FINDINGS

Date: **11/26/1991**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B092643
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A.S.M. ELEC. & MACH. CORP

Date: **2/21/1991**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B080472
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A.S.M. ELEC. & MACH. CORP

Date: **11/12/1990**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B076837
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: A.S.M. ELEC. & MACH. CORP

ADJOINING PROPERTY FINDINGS

Date: **1/26/1987**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B015310
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A.S.M. ELEC. & MACH. CORP

Date: **11/25/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B012767
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A.S.M. ELEC. & MACH. CORP

Date: **11/25/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B012768
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A.S.M. ELEC. & MACH. CORP

ADJOINING PROPERTY FINDINGS

342 39TH ST

Date: **2/28/1989**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B049600
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: R & J MECHANICAL CORP.

Date: **5/9/1984**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K04733
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: R & J MECHANICAL CORP.

ADJOINING PROPERTY FINDINGS

344 39TH ST

Date:	**7/19/2000**
Permit Type:	**PL**
Description:	**LEGALIZE THE RENOVATION OF EXISTING 2 FAMILY HOUSE. PLUMBING AND PARTITION CHANGES, NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	301034379-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SCARPONI & SON PLBG & HTG

Date:	**6/28/2000**
Permit Type:	**EW**
Description:	**LEGALIZE THE RENOVATION OF EXISTING 2 FAMILY HOUSE. PLUMBING AND PARTITION CHANGES, NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301034379-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MAERS HOME IMPROVEMENT

ADJOINING PROPERTY FINDINGS

Date: **3/13/2000**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B199439
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: VINTAGE ELEC. SERVICE INC

346 39TH ST

Date: **7/13/2023**
Permit Type: **NB**
Description: **CONSTRUCTION OF 3 STORY COMMERICAL BUILDING TO FULLY SPRINKLERED.**

Permit Description: **NEW BUILDING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 301515849-01-NB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SKY TEAM CONTRACTING

Date: **5/11/2023**
Permit Type: **PL**
Description: **CONSTRUCTION OF 3 STORY COMMERICAL BUILDING TO FULLY SPRINKLERED.**

Permit Description: **PLUMBING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 301515849-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: L & G PLUMBERS, INC

ADJOINING PROPERTY FINDINGS

Date:	**4/28/2023**
Permit Type:	**EW**
Description:	**FILING THIS JOB TO INSTALL SPRINKLER SYSTEM IN-CONJUNCTION WITH 301515849. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	SPRINKLER
Permit Number:	320733239-01-EW-SP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AAA TOTAL PLUMBING INC

Date:	**10/11/2022**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00772044I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RICHARD NEU

Date:	**8/23/2022**
Permit Type:	**EQ**
Description:	**CONSTRUCTION OF 3 STORY COMMERICAL BUILDING TO FULLY SPRINKLERED.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	NB - NEW BUILDING
Proposed Use:	FENCE
Permit Number:	301515849-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SKY TEAM CONTRACTING GROUP

ADJOINING PROPERTY FINDINGS

Date: **6/5/2019**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00173536I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RICHARD NEU

Date: **12/11/2018**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00108451I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: KWONG MING ELECTRIC INC

Date: **7/17/2018**
Permit Type: **EQ**
Description: **INSTALLATION OF HEAVY DUTY 300PSF SIDEWALK SHED AS PER PLANS. NO CHANGE IN USE, EGRESS OR OCCUPANCY. SIDEWALK SHED SHALL COMPLY WITH CHAPTER #33 OF THE NYC BUILDING CODE.**

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use: SIDEWALK SHED
Permit Number: 340423287-01-EQ-SH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BILLY ENTERPRISES INC

ADJOINING PROPERTY FINDINGS

Date: **9/1/2016**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B416622
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: WCK ELECTRIC CORP.

Date: **11/14/2003**
Permit Type: **DM**
Description:

Permit Description: **DEMOLITION & REMOVAL**
Work Class: DM - FULL DEMOLITION
Proposed Use:
Permit Number: 301665650-01-DM
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: R MOEZINIA'S CONTRACTING CORP

352 39TH ST

Date: **5/5/2014**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B380643
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: RIVIERA ELECTRIC CORP

ADJOINING PROPERTY FINDINGS

Date: **10/16/1985**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K25611
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ROBERT DURST

353 39TH ST

Date: **2/5/2018**
Permit Type: **EQ**
Description: **PROPOSED INSTALLATION OF PIPE SCAFFOLD AS PER PLANS. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use: SCAFFOLD
Permit Number: 340435924-01-EQ-SF
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: EVEREST SCAFFOLDING INC

ADJOINING PROPERTY FINDINGS

Date:	**10/23/2017**
Permit Type:	**EQ**
Description:	**PROPOSED INSTALLATION OF HEAVY DUTY SIDEWALK SHED AS PER PLANS. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	340435915-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EVEREST SCAFFOLDING INC

Date:	**11/16/2016**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B420111
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	R.C.M. ELECTRIC CORP.

Date:	**10/14/2016**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B418607
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BOROWIDE ELECT'L CONTR'S

ADJOINING PROPERTY FINDINGS

Date:	**2/4/2015**
Permit Type:	**EQ**
Description:	**INSTALLATION OF SIDEWALK SHED AS PER PLANS. WORK SHALL COMPLY WITH 2014 BUILDING CODE CHAPTER 33. NO CHANGE IN USE EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	340226240-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ARSENAL SCAFFOLD INC

Date:	**2/3/2015**
Permit Type:	**EQ**
Description:	**INSTALLATION OF PIPE SCAFFOLD AS PER PLANS. WORK SHALL COMPLY WITH 2014 BUILDING CODE CHAPTER 33. NO CHANGE IN USE EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SCAFFOLD
Permit Number:	340226179-01-EQ-SF
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ARSENAL SCAFFOLD INC

ADJOINING PROPERTY FINDINGS

Date:	**2/3/2015**
Permit Type:	**EQ**
Description:	**INSTALLATION OF FENCE AS PER PLANS. WORK SHALL COMPLY WITH 2014 BUILDING CODE CHAPTER 33. NO CHANGE IN USE EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	FENCE
Permit Number:	340226231-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ARSENAL SCAFFOLD INC

Date:	**1/26/2015**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B391339
Status:	AWAITING INSPECTION REQUEST, Open
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NASH ELECTRIC SERVICES IN

ADJOINING PROPERTY FINDINGS

Date:	**11/30/2012**
Permit Type:	**EQ**
Description:	**REPLACE DETERIORATED OR RUSTY WINDOW LINTELS/SILLS, REPAIR CRACKED BRICK WALL, AS PER PLANS. NO CHANGE OF USES,EGRESS OR OCCUPANCY**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	SIDEWALK SHED
Permit Number:	320541115-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	N & J HOME IMPROVEMNT COR

Date:	**10/16/2012**
Permit Type:	**EW**
Description:	**REPLACE DETERIORATED OR RUSTY WINDOW LINTELS/SILLS, REPAIR CRACKED BRICK WALL, AS PER PLANS. NO CHANGE OF USES,EGRESS OR OCCUPANCY**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320541115-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NEW REGAL CONSTRUCTION IN

ADJOINING PROPERTY FINDINGS

Date:	**2/7/2007**
Permit Type:	**EW**
Description:	**To register a high pressure steam boiler. There will be no change in use, egress and occupancy.**

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	302292560-01-EW-BL
Status:	IN PROCESS
Valuation:	$0.00
Contractor Company:	
Contractor Name:	GLOBE PLUMBINT & HTG

Date:	**3/6/2006**
Permit Type:	**EW**
Description:	**REPLACE GAS FIRED PACKAGE HIGH PRESSURE BOILER. NO CHANGE IN EGRESS, OCCUPANCY OR USE UNDER THIS APPLICATION.**

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	302086034-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SEICKEL & SONS PLBG

ADJOINING PROPERTY FINDINGS

Date:	**3/6/2006**
Permit Type:	**PL**
Description:	**REPLACE GAS FIRED PACKAGE HIGH PRESSURE BOILER. NO CHANGE IN EGRESS, OCCUPANCY OR USE UNDER THIS APPLICATION.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	302086034-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SEICKEL & SONS PLBG

Date:	**10/11/2005**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B272561
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ARNOLD FINKELSTEIN

Date:	**4/11/1997**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	300623840-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	STUART ISER INC

ADJOINING PROPERTY FINDINGS

Date: **4/11/1997**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300623840-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: STUART ISER INC

Date: **4/11/1997**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300623840-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: STUART ISER INC

Date: **11/14/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B133917
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A.S.M. ELEC. & MACH. CORP

ADJOINING PROPERTY FINDINGS

Date: **7/23/1992**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300187241-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WASOFF PLUMBING & UTILITY CO

Date: **7/22/1992**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300187241-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WASOFF PLUMBING & UTILITY CO

Date: **5/1/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B098797
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A.S.M. ELEC. & MACH. CORP

ADJOINING PROPERTY FINDINGS

358 39TH ST

Date:	**8/10/2009**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B319224
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	J. STAR ELECTRIC INC

364 39TH ST

Date:	**5/2/2016**
Permit Type:	**EW**
Description:	**PROPOSED NEW STEAM BOILER IN CELLAR LEVEL AND MINOR CONSTRUCTION WORK.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	321099173-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ARANDA PLBG & HTG CORP

ADJOINING PROPERTY FINDINGS

Date:	**5/2/2016**
Permit Type:	**PL**
Description:	**PROPOSED NEW STEAM BOILER IN CELLAR LEVEL AND MINOR CONSTRUCTION WORK.**

Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321099173-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ARANDA PLBG & HTG CORP

Date:	**10/1/2015**
Permit Type:	**EW**
Description:	**PROPOSED NEW STEAM BOILER IN CELLAR LEVEL AND MINOR CONSTRUCTION WORK.**

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	321099173-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NORTH STAR GENERAL CONTR

ADJOINING PROPERTY FINDINGS

Date:	**10/1/2015**
Permit Type:	**EW**
Description:	**PROPOSED NEW STEAM BOILER IN CELLAR LEVEL AND MINOR CONSTRUCTION WORK.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321099173-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NORTH STAR GENERAL CONTR

366 39TH ST

Date:	**12/18/2012**
Permit Type:	**SG**
Description:	
Permit Description:	**SIGN**
Work Class:	SG - SIGN
Proposed Use:	
Permit Number:	320398495-01-SG
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	INTERBORO SIGN & MNTNCE

ADJOINING PROPERTY FINDINGS

Date:	**3/29/2012**
Permit Type:	**EW**
Description:	**STRUCTURE DESIGN FOR ADVERTISING WALL FACE SIGN (10.5'X 22.8'). ALL AS PER PLANS FILE HEREWITH.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320398501-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	INTERBORO SIGN & MAINTENA

Date:	**9/17/2009**
Permit Type:	**EW**
Description:	**REPLACE BOILER SECTIONS ONLY. BOILER JACKET AND ALL CONTROLS TO BE REUSED. REINSTALL EXISTING OIL BURNER**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	320073013-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MICHAEL S. KAPLAN

ADJOINING PROPERTY FINDINGS

Date:	**9/17/2009**
Permit Type:	**EW**
Description:	**REPLACE BOILER SECTIONS ONLY. BOILER JACKET AND ALL CONTROLS TO BE REUSED. REINSTALL EXISTING OIL BURNER**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FUEL BURNING
Permit Number:	320073013-01-EW-FB
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MICHAEL S. KAPLAN

Date:	**3/28/2001**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B211665
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WINKLER ELECTRICIANS INC.

Date:	**11/8/1999**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FUEL BURNING
Permit Number:	300950996-01-EW-FB
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JACK PICCININNI INC

ADJOINING PROPERTY FINDINGS

Date: **11/4/1999**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300950996-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: JACK PICCININNI INC

Date: **11/1/1999**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B195656
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: PROTON ELEC & SEC SYS INC

Date: **1/25/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300333253-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: JNG CONSTRUCTION LTD

ADJOINING PROPERTY FINDINGS

369 39TH ST

Date:	**2/8/2007**
Permit Type:	**PL**
Description:	**THIS APPLICATION IS FILED TO PROPOSE AN EXTENSION AT REAR OF EXISTING COMMERCIAL BUILDING, TO DIVIDE EXISTING COMMERCIAL BUILDING INTO SIX INDIVIDUAL BUILDINGS AND TAX LOTS, AND TO OBTAIN A NEW CERTIFICATE OF OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	302158331-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	VALUE PLBG INC

Date:	**1/26/2007**
Permit Type:	**AL**
Description:	**THIS APPLICATION IS FILED TO PROPOSE AN EXTENSION AT REAR OF EXISTING COMMERCIAL BUILDING, TO DIVIDE EXISTING COMMERCIAL BUILDING INTO SIX INDIVIDUAL BUILDINGS AND TAX LOTS, AND TO OBTAIN A NEW CERTIFICATE OF OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	302158331-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	UNIVERSAL CONSTRUCTION & BUILDER

ADJOINING PROPERTY FINDINGS

420 39TH ST

Date:	**9/29/2000**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B206328
Status:	VIOLATN PENDING AT CONTRACTOR
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CRAFTSMEN ELEC'L CO. INC

421 39TH ST

Date:	**7/10/2012**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION FOR EXISTING 2 FAMILY. PLUMBING WORK AND PARTITION WALL WILL BE INVOLVED. NO CHANGE TO USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320432652-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BEST CALL SERVICE INC

ADJOINING PROPERTY FINDINGS

Date:	**3/9/2012**
Permit Type:	**PL**
Description:	**INTERIOR RENOVATION FOR EXISTING 2 FAMILY. PLUMBING WORK AND PARTITION WALL WILL BE INVOLVED. NO CHANGE TO USE, EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320432652-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	OJ PLUMBING & HEATING INC

422 39TH ST

Date:	**11/30/1988**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B046168
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	INTERPHASE ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

Date: **11/16/1988**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B046161
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: INTERPHASE ELECTRIC CORP.

423 39TH ST

Date: **6/16/2017**
Permit Type: **EQ**
Description: **INSTALLATION OF 38 LINEAR FEET OF HEAVY DUTY SIDEWALK SHED FOR REMEDIAL REPAIRS. SIDEWALK SHED SHALL COMPLY WITH LL33/91 AND TPPN 9/1999. NO CHANGE IN USE, OCCUPANCY OR EGRESS UNDER THIS APPLICATION. LIVE LOAD 300 PSF.**

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use: SIDEWALK SHED
Permit Number: 310277875-01-EQ-SH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: OUTDOOR INSTALLATIONS LLC

ADJOINING PROPERTY FINDINGS

Date: **1/4/2016**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B405502
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: AMERICAN STANDARD ELECTRIC CORP

Date: **12/31/2015**
Permit Type: **AL**
Description: **CONVERT EXISTING FIRST AND SECOND FLOOR INTO A COMMUNITY FACILITY.**

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 321129355-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: OVERTONE CONSULTING & CON

Date: **8/4/2009**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B319039
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CORPORATE ELEC. GROUP INC

ADJOINING PROPERTY FINDINGS

Date: **4/22/2009**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 302384989-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: GO PRO PLBG. & HGT. CO., INC.

Date: **4/3/2009**
Permit Type: **NB**
Description:

Permit Description: **NEW BUILDING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 302384989-01-NB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: POWERHOUSE CONST

Date: **7/5/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B306239
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: MARI ELEC. CONTR'S INC.

ADJOINING PROPERTY FINDINGS

Date: **7/3/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B306154
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: MARI ELEC. CONTR'S INC.

Date: **4/16/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B303223
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: TMF ELEC'L CONTR. INC.

Date: **3/13/2008**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: NB - NEW BUILDING
Proposed Use: FENCE
Permit Number: 302384989-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: POWERHOUSE CONST

ADJOINING PROPERTY FINDINGS

Date: **5/4/2007**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: DM - FULL DEMOLITION
Proposed Use: FENCE
Permit Number: 302333375-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: POWERHOUSE

Date: **5/4/2007**
Permit Type: **DM**
Description:

Permit Description: **DEMOLITION & REMOVAL**
Work Class: DM - FULL DEMOLITION
Proposed Use:
Permit Number: 302333375-01-DM
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: POWERHOUSE

Date: **4/11/2007**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B290255
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: P VERARDI CONSTRUCTION CO

ADJOINING PROPERTY FINDINGS

Date: **7/12/1997**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B167633
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: BDS ELECTRIC CORP.

424 39TH ST

Date: **6/5/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B305022
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: SCHLESINGER ELECT'L CONTR

Date: **8/7/2007**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B294188
Status: ADMINISTRATIVELY CLOSED (MINOR WORK)
Valuation: $0.00
Contractor Company:
Contractor Name: DELTEX ELECTRICAL CONT.

ADJOINING PROPERTY FINDINGS

425 39TH ST

Date: **11/10/2003**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B246464
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: UNITED ELEC'L CONT'G CORP

Date: **9/19/2003**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 301524688-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WAGNER ZIV PLUMBING & HEATING

Date: **7/17/2003**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: NB - NEW BUILDING
Proposed Use: FENCE
Permit Number: 301524688-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: JWC CONST CORP

ADJOINING PROPERTY FINDINGS

Date: **7/17/2003**
Permit Type: **NB**
Description:

Permit Description: **NEW BUILDING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 301524688-01-NB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: JWC CONST CORP

426 39TH ST

Date: **10/30/2004**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B259925
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: NEW GRAND ELECTRIC INC.

Date: **11/16/1988**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B045338
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: SCHWARTZ ELEC. & RADIO SV

ADJOINING PROPERTY FINDINGS

427 39TH ST

Date:	**1/29/2004**
Permit Type:	**EW**
Description:	**HEREAFTER SUBMIT AN APPLICATION FOR AUTO SALE AND REPAIR ESTABLISHMENT. NO WORK TO BE DONE. NO CHANGE IN USE, EGRESS AND OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301684158-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	J W C CONSTRUCTION CORP

430 39TH ST

Date:	**3/19/2019**
Permit Type:	**PL**
Description:	**RENOVATION OF EXISTING 2 FAMILY BUILDING. PARTITION AND PLUMBING WORK AS PER PLAN. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321668496-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RICHMOND CONSTR ASSOC INC

ADJOINING PROPERTY FINDINGS

Date:	**5/30/2018**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00048381I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	KWONG MING ELECTRIC INC.

Date:	**4/3/2018**
Permit Type:	**EW**
Description:	**RENOVATION OF EXISTING 2 FAMILY BUILDING. PARTITION AND PLUMBING WORK AS PER PLAN. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	321668496-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NIC DESIGN MGMT INC

Date:	**4/3/2018**
Permit Type:	**EW**
Description:	**RENOVATION OF EXISTING 2 FAMILY BUILDING. PARTITION AND PLUMBING WORK AS PER PLAN. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321668496-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NIC DESIGN MGMT INC

ADJOINING PROPERTY FINDINGS

432 39TH ST

Date:	**10/5/2007**
Permit Type:	**PL**
Description:	**Partition and plumbing modifications on the cellar, 1st, 2nd and 3rd floors. No change in use, egress, or occupancy.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	301947099-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	S L HUNSDORFER PLBG

Date:	**1/5/2006**
Permit Type:	**EW**
Description:	**Partition and plumbing modifications on the cellar, 1st, 2nd and 3rd floors. No change in use, egress, or occupancy.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301947099-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	POWERHOUSE CONST INC

ADJOINING PROPERTY FINDINGS

Date: **9/26/2005**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B272442
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: P VERARDI CONSTRUCTION CO

434 39TH ST

Date: **2/10/2020**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00312495I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: WEBSTAR ELECL CONTRS INC

ADJOINING PROPERTY FINDINGS

Date:	**3/16/2016**
Permit Type:	**EW**
Description:	**APPLICATION FILED TO RENOVATE INTERIOR AS FOLLOWS: INSTALL NEW INTERIOR NON-BEARING PARTITIONS AND REPLACE STOREFRONT. NO CHANGE TO USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321284882-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	GUNDERSEN CONSTRUCTION CO

Date:	**3/16/2016**
Permit Type:	**EQ**
Description:	**APPLICATION FILED TO RENOVATE INTERIOR AS FOLLOWS: INSTALL NEW INTERIOR NON-BEARING PARTITIONS AND REPLACE STOREFRONT. NO CHANGE TO USE, EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FENCE
Permit Number:	321284882-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	GUNDERSEN CONSTRUCTION CO

ADJOINING PROPERTY FINDINGS

436 39TH ST

Date:	**12/15/2020**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00439724I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HUNTER ELECTRIC, INC.

Date:	**9/15/2020**
Permit Type:	**EW**
Description:	**HEREWITH FILING TO EMPTY,PURGE,CLEAN,REMOVE & DISPOSE OF ONE(1) 550-GALLON DIESEL MOTOR FUEL AST & ALL ASSOCIATED PIPING.REMOVE & DISPOSE OF (1)FUEL DISPENSER,CONCRETE ISLAND & VEEDER ROOT TLS-350R.INSTALL ONE(1)NEW 550-GALLON FIELDFABRICATED SINGLE-WALL STEEL DIESEL MOTOR FUEL AST,(1)FUEL DISPENSER,CONCRETE ISLAND,VEEDER ROOT TLS-450 AS PER PLANS**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321848738-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PAPITTO CONSTRUCTION CO I

ADJOINING PROPERTY FINDINGS

Date: **9/2/2016**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B416650
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: APPROVED ELEC CONT'G INC

Date: **9/10/1999**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300935941-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: DELPHI PLUMBING & HEATING, INC.

Date: **9/10/1999**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300935941-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: DELPHI PLUMBING & HEATING

ADJOINING PROPERTY FINDINGS

Date: **11/13/1998**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use: SIDEWALK SHED
Permit Number: 300791490-01-EQ-SH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SPSING SCAFFOLDING INC

Date: **12/24/1997**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B173172
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: RAPID ELECTRIC

Date: **5/29/1996**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B153627
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: HUNTER ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

Date: **7/26/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300073630-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: TECH-BUILDERS INC.

Date: **11/23/1994**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300148230-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: FOUNDATION CONSTR. CONS.

Date: **4/18/1994**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300073630-02-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: ACE CONTRACTING CORP

ADJOINING PROPERTY FINDINGS

Date: **9/1/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B121925
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: JOHNSON BROS. INC.

Date: **12/7/1984**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K13850
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: MICHAEL A. LLADO

437 39TH ST

Date: **12/29/2016**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 321502272-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: MAUCERI SIGN CO.,INC

ADJOINING PROPERTY FINDINGS

Date: **12/29/2016**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 321502281-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: MAUCERI SIGN CO.,INC

Date: **12/28/2016**
Permit Type:
Description:

Permit Description: **Sign Permit**
Work Class:
Proposed Use:
Permit Number: 32150227201SG
Status: Issued
Valuation: $0.00
Contractor Company:
Contractor Name: MAUCERI SIGN CO.,INC

Date: **12/28/2016**
Permit Type:
Description:

Permit Description: **Sign Permit**
Work Class:
Proposed Use:
Permit Number: 32150228101SG
Status: Issued
Valuation: $0.00
Contractor Company:
Contractor Name: MAUCERI SIGN CO.,INC

ADJOINING PROPERTY FINDINGS

Date: **10/6/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B309658
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: UNITED ELEC'L CONT'G CORP

Date: **5/30/2008**
Permit Type: **PL**
Description: **PROPOSE HORIZONTAL AND VERTICAL EXTENSION 4-STORIES AT THE SIDE OF THE EXISTING BUILDING. PLUMBING FIXTURE INVOLVED. OBTAIN NEW C.O.**

Permit Description: **PLUMBING**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 302295969-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: C2 PLUMBING CORP.

Date: **3/24/2008**
Permit Type: **AL**
Description: **PROPOSE HORIZONTAL AND VERTICAL EXTENSION 4-STORIES AT THE SIDE OF THE EXISTING BUILDING. PLUMBING FIXTURE INVOLVED. OBTAIN NEW C.O.**

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 302295969-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: MILESTONE CONSTRUCTION CORP.

ADJOINING PROPERTY FINDINGS

Date:	**3/24/2008**
Permit Type:	**EQ**
Description:	**PROPOSE HORIZONTAL AND VERTICAL EXTENSION 4-STORIES AT THE SIDE OF THE EXISTING BUILDING. PLUMBING FIXTURE INVOLVED. OBTAIN NEW C.O.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	FENCE
Permit Number:	302295969-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MILESTONE CONSTRUCTION CORP.

Date:	**4/28/2005**
Permit Type:	**AL**
Description:	**Fire Protection Plan filed in conjunction with NB 301546138. No change to use, occupancy or egress.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	301788297-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MIKEESAM

ADJOINING PROPERTY FINDINGS

Date:	**9/29/2004**
Permit Type:	**EW**
Description:	**File fuel storage work type for emergency generator in conjunction with NB 301546138. No change to use, occupancy or egress.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FUEL STORAGE
Permit Number:	301826362-01-EW-FS
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JACK PICCINNI INC

Date:	**3/2/2004**
Permit Type:	**NB**
Description:	
Permit Description:	**NEW BUILDING**
Work Class:	NB - NEW BUILDING
Proposed Use:	
Permit Number:	301546138-01-NB
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	IKESAM CONSTRUCTION CORP.

Date:	**3/2/2004**
Permit Type:	**EQ**
Description:	
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	NB - NEW BUILDING
Proposed Use:	FENCE
Permit Number:	301546138-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MIKESAM CONSTRUC CORP.

ADJOINING PROPERTY FINDINGS

Date: **12/15/2003**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B247503
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: OTIS ELEVATOR COMPANY

Date: **11/17/2003**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B246871
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: UNITED ELEC'L CONT'G CORP

Date: **7/31/2003**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 301546138-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WASOFF PLBG & UTILITY CO INC

ADJOINING PROPERTY FINDINGS

Date: **5/13/2003**
Permit Type: **DM**
Description:

Permit Description: **DEMOLITION & REMOVAL**
Work Class: DM - FULL DEMOLITION
Proposed Use:
Permit Number: 301535881-01-DM
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: FIRST CLASS WRECKING INC

438 39TH ST

Date: **12/4/2000**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B209836
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ACCURATE ELEC'L CORP.

ADJOINING PROPERTY FINDINGS

441 39TH ST

Date: **5/3/1995**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B140099
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: M & W ELECTRIC CORP.

Date: **2/16/1984**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K01505
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: D. RYAN LIC. ELEC'L CONTR

ADJOINING PROPERTY FINDINGS

442 39TH ST

Date:	**8/20/2018**
Permit Type:	**PL**
Description:	**REPLACEMENT EXISTING BOILER WITH NEW HOT WATER HEATER. NO CHANGE IN USE, OCCUPANCY OR EGRESS.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321039782-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	J.D. MASTERS PLBG & HTG

Date:	**8/17/2018**
Permit Type:	**EW**
Description:	**REPLACEMENT EXISTING BOILER WITH NEW HOT WATER HEATER. NO CHANGE IN USE, OCCUPANCY OR EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	321039782-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	J.D. MASTERS PLUMBING & H

ADJOINING PROPERTY FINDINGS

Date: **10/30/2016**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: MINOR WORK
Proposed Use:
Permit Number: B419386
Status: ADMINISTRATIVELY CLOSED (MINOR WORK)
Valuation: $0.00
Contractor Company:
Contractor Name: THREE SON'S ELECTRICAL CO

Date: **8/19/2011**
Permit Type: **EW**
Description: **INSTALL PARTITIONS AND REPLACE FLOORING WITH CONJUNCTION IN ALT #310223120, NO CHANGE IN USE, EGRESS OR OCCUPANCY**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: MECHANICAL/HVAC
Permit Number: 320345088-01-EW-MH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: DAL H CHUN ENGINEER

Date: **8/19/2011**
Permit Type: **EW**
Description: **INSTALL PARTITIONS AND REPLACE FLOORING WITH CONJUNCTION IN ALT #310223120, NO CHANGE IN USE, EGRESS OR OCCUPANCY**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 320345088-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: DAL H CHUN ENGINEER

ADJOINING PROPERTY FINDINGS

Date:	**3/2/2011**
Permit Type:	**PL**
Description:	**INTERIOR RENOVATION OF EXISTING COMMERCIAL LAUNDRY. WORK INCLUDES INSTALLATIION OF ADDITIONAL WASHERS, DRYERS AND SPRINKLER HEADS. NO CHANGE IN USE, EGRESS OR OCCUPANCY**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	310223120-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ACR PLUMBING INC

Date:	**3/2/2011**
Permit Type:	**EW**
Description:	**INSTALL (6) SPRINKLER HEADS. THIS APPLICATION IS FILED IN CONJUNCTION WITH # 310223120. NO CHANGE IN USE, EGRESS OR OCCUPANCY**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	SPRINKLER
Permit Number:	310304051-01-EW-SP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ACR PLUMBING INC

ADJOINING PROPERTY FINDINGS

Date:	**12/23/2008**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION OF EXISTING COMMERCIAL LAUNDRY. WORK INCLUDES INSTALLATIION OF ADDITIONAL WASHERS, DRYERS AND SPRINKLER HEADS. NO CHANGE IN USE, EGRESS OR OCCUPANCY**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	310223120-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NEW WAVE ELECTR CONTR INC

Date:	**12/23/2008**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION OF EXISTING COMMERCIAL LAUNDRY. WORK INCLUDES INSTALLATIION OF ADDITIONAL WASHERS, DRYERS AND SPRINKLER HEADS. NO CHANGE IN USE, EGRESS OR OCCUPANCY**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	310223120-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NEW WAVE ELECTR CONTR INC

ADJOINING PROPERTY FINDINGS

Date: **9/8/1998**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B182205
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: FAS ELECTRIC INC.

Date: **7/28/1997**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300646488-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: R&R STEAM INC.

Date: **7/28/1997**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300646488-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: ALL-RITE PLUMBING

ADJOINING PROPERTY FINDINGS

Date: **7/28/1997**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300646488-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: ALL-RITE PLUMBING

Date: **12/29/1994**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: MECHANICAL/HVAC
Permit Number: 300410124-01-EW-MH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: RZM HEATING & COOLING, INC.

443 39TH ST

Date: **10/11/2019**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00243944I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: STAR ELEC'L CONTRACTORS C

ADJOINING PROPERTY FINDINGS

Date:	**5/31/2018**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00047421I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WCK ELECTRIC CORP.

Date:	**10/5/2015**
Permit Type:	**AL**
Description:	**PROPOSED NEW RAMP AT THE EXISTING NORTH ENTRANCE OF THE BUILDING AS PER SUBMITTED PLANS. NO CHANGE IN USE, EGRESS OR OCCUPANCY UNDER THIS FILING.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	340308759-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HIGH RISE BUILD & DES INC

ADJOINING PROPERTY FINDINGS

Date:	**5/12/2014**
Permit Type:	**EW**
Description:	**FILING TO INSTALL NEW CEILING HUNG MECHANICAL UNIT ON 3RD FLOOR AND 2 NEW CONDENSING UNITS ON THE ROOF AS WELL AS NEW DUCTWORK AS PER PLANS FILED HEREWITH. NO CHANGE IN USE, EGRESS, OR OCCUPANCY UNDER THIS APPLICATION. THANK YOU.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	340136178-01-EW-MH
Status:	RE-ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BARTEL CONSTRUCTION CO

Date:	**5/5/2014**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B380672
Status:	Closed
Valuation:	$0.00
Contractor Company:	
Contractor Name:	COBRA ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

Date:	**12/30/2013**
Permit Type:	**PL**
Description:	**PROPOSE TO REMOVE EXISTING NON BEARING PARTITIONS, INSTALL NEW NON BEARING PARTITIONS AND REMOVE PLUMBING FIXTURES AS PER PLANS FILED HEREWITH.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320846386-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	LLG P

Date:	**10/25/2013**
Permit Type:	**EW**
Description:	**PROPOSE TO REMOVE EXISTING NON BEARING PARTITIONS, INSTALL NEW NON BEARING PARTITIONS AND REMOVE PLUMBING FIXTURES AS PER PLANS FILED HEREWITH.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320846386-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BARTEL CONSTRUCTION CO

ADJOINING PROPERTY FINDINGS

Date:	**1/18/2013**
Permit Type:	**PL**
Description:	**PROPOSE TO ADD WORK TYPE PL PLUMBING AND MH MECHANICAL FOR THIS APPLICATION.**
Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	302325936-02-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ANGELO ANDREW INC

Date:	**11/8/2012**
Permit Type:	**AL**
Description:	
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	302325936-01-AL
Status:	RE-ISSUED, ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BARTEL CONSTRUCTION CO

Date:	**9/8/2011**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B342298
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date:	**8/28/2001**
Permit Type:	**EW**
Description:	**Installation of HVAC unit at the Roof**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	301223744-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	POWERHOUSE CONSTRUCTION INC

Date:	**3/5/2001**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B211420
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	P VERARDI CONSTRUCTION CO

Date:	**10/30/2000**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B207833
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	P VERARDI CONSTRUCTION CO

ADJOINING PROPERTY FINDINGS

Date: **10/18/2000**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 301043877-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BAY RIDGE INC

Date: **6/26/2000**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: NB - NEW BUILDING
Proposed Use: FENCE
Permit Number: 301043877-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: POWER HOUSE CONSTRUCTION

Date: **6/26/2000**
Permit Type: **NB**
Description:

Permit Description: **NEW BUILDING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 301043877-01-NB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: POWER HOUSE CONSTRUCTION

ADJOINING PROPERTY FINDINGS

Date: **5/19/2000**
Permit Type: **AL**
Description: **EXCAVATION AND FOUNDATION**

Permit Description: **ALTERATION**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use:
Permit Number: 301030532-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: POWER HOUSE CONSTRUCTION

444 39TH ST

Date: **12/21/1998**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300781205-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WARD MECH CORP

Date: **11/19/1998**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: MECHANICAL/HVAC
Permit Number: 300781205-01-EW-MH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: B O SS CONST & MGMT

ADJOINING PROPERTY FINDINGS

Date: **9/3/1998**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300781205-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WARD MECH CORP

Date: **8/26/1998**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300781205-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: B O SS CONST & MGMT

ADJOINING PROPERTY FINDINGS

449 39TH ST

Date:	**12/8/2023**
Permit Type:	**AL**
Description:	**ADDITION OF NEW FLOOR WITHIN THE EXISTING ENVELOPE OF THE BUILDING AND EXTENSION OF EXISTING 5TH FLOOR VERTICAL EXTENSION TO CREATE NEW 6TH FLOOR. ALL AS PER PLANS AND APPLICATION HEREWITH FILED.**
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	320375447-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	KC EXPEDITING INC

Date:	**5/28/2019**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00172716I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RC3 ELECTRIC, LLC

ADJOINING PROPERTY FINDINGS

Date:	**8/14/2018**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B372997
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PAUL VERARDI

Date:	**2/28/2017**
Permit Type:	**EW**
Description:	**MODIFICATION OF EXISTING SPRINKLER SYSTEM FOR THE 5TH AND 6TH FLOORS ONLY IN CONJUNCTION WITH ALT 1 APPLICATION # 320375447. NO CHANGE IN USE, EGRESS, OR OCCUPANCY UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	SPRINKLER
Permit Number:	340463705-01-EW-SP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A. AUTOMATIC SPRINKLER

ADJOINING PROPERTY FINDINGS

Date:	**12/20/2016**
Permit Type:	**PL**
Description:	**ALT-2 FILED TO INCLUDE FIXTURES ONLY FOR AN EXT'G ALTERATION WHERE PLUMBING IS SIGNED OFF. ALL CONSTRUCTION FILED UNDER ALT-1 D.O.B APPLICATION #320375447.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321446299-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PRECISION PLBG SVCS.,INC

Date:	**12/14/2016**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B421420
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	P VERARDI CONSTRUCTION CO

Date:	**12/28/2015**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	
Proposed Use:	
Permit Number:	B405317
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date:	**10/17/2014**
Permit Type:	**EW**
Description:	**INSTALLATION OF SPRINKLER SYSTEM IN CONJUNCTION WITH ALT 320375447**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	SPRINKLER
Permit Number:	320697910-01-EW-SP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A. AUTOMATIC SPRINKLER

Date:	**10/1/2013**
Permit Type:	**PL**
Description:	**ADDITION OF NEW FLOOR WITHIN THE EXISTING ENVELOPE OF THE BUILDING AND EXTENSION OF EXISTING 5TH FLOOR VERTICAL EXTENSION TO CREATE NEW 6TH FLOOR. ALL AS PER PLANS AND APPLICATION HEREWITH FILED.**
Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	320375447-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PRECISION PLBG SVCS.,INC

Date:	**9/27/2011**
Permit Type:	**PL**
Description:	
Permit Description:	**PLUMBING**
Work Class:	NB - NEW BUILDING
Proposed Use:	
Permit Number:	320088846-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	GO PRO PLBNG AND HTG CO I

ADJOINING PROPERTY FINDINGS

Date: **5/26/2011**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: NB - NEW BUILDING
Proposed Use: FENCE
Permit Number: 320088846-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: POWER HOUSE CONSTRUCTION

Date: **5/26/2011**
Permit Type: **NB**
Description:

Permit Description: **NEW BUILDING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 320088846-01-NB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: POWER HOUSE CONSTRUCTION

ADJOINING PROPERTY FINDINGS

Date:	**4/22/2011**
Permit Type:	**AL**
Description:	**PROVIDE 14' CURB CUT INCLUDING (2) 18' SPLAYS LOCATED ON 39TH STREET 390' WEST OF 4TH AVENUE. FILING IN CONJUNCTION WITH BPP DOB APPLICATION# 320139881 BNP# 10-071. NO CHANGE TO EGRESS BULK, USE OR OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	320294007-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	POWER HOUSE CONSTRUCTION

Date:	**3/29/2011**
Permit Type:	**EW**
Description:	**FILING SPRINKLER APPLICATION FOR A NEW BUILDING**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	SPRINKLER
Permit Number:	320169465-01-EW-SP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A. AUTOMATIC SPRINKLER

ADJOINING PROPERTY FINDINGS

Date:	**3/7/2011**
Permit Type:	**PL**
Description:	**FILING SPRINKLER APPLICATION FOR A NEW BUILDING**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320169465-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SMILEYS WATERWORKS INC

Date:	**1/12/2011**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	NEW BUILDING
Proposed Use:	
Permit Number:	B335039
Status:	ASSIGNED TO INSPECTOR, COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	P VERARDI CONSTRUCTION CO

ADJOINING PROPERTY FINDINGS

Date:	**6/1/2010**
Permit Type:	**EQ**
Description:	**INSTALLATION OF 52 LINEAR FEET OF HEAVY DUTY SIDEWALK SHED FOR REMEDIAL REPAIRS. SIDEWALK SHED SHALL COMPLY WITH LL33/91 AND TPPN 9/1999. NO CHANGE IN USE, OCCUPANCY OR EGRESS UNDER THIS APPLICATION. LIVE LOAD 300 PSF.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	310277884-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	OUTDOOR INSTALLATIONS LLC

Date:	**2/1/2010**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B324142
Status:	CLOSED/CANCELLED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	P VERARDI CONSTRUCTION CO

ADJOINING PROPERTY FINDINGS

Date: **7/4/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B306238
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: MARI ELEC. CONTR'S INC.

Date: **7/3/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B306155
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: MARI ELEC. CONTR'S INC.

Date: **4/5/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B302813
Status: ASSIGNED TO INSPECTOR
Valuation: $0.00
Contractor Company:
Contractor Name: CORPORATE ELEC. GROUP INC

ADJOINING PROPERTY FINDINGS

Date: **3/13/2008**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use: FENCE
Permit Number: 301290430-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: POWERHOUSE CONSTRUCTION, INC.

Date: **3/13/2008**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 301290430-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: POWERHOUSE CONSTRUCTION

Date: **6/1/2007**
Permit Type: **DM**
Description:

Permit Description: **DEMOLITION & REMOVAL**
Work Class: DM - FULL DEMOLITION
Proposed Use:
Permit Number: 302340250-01-DM
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: POWERHOUSE

ADJOINING PROPERTY FINDINGS

Date: **5/30/2007**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: DM - FULL DEMOLITION
Proposed Use: FENCE
Permit Number: 302340250-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: POWERHOUSE

Date: **5/4/2007**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B290929
Status: ASSIGNED TO INSPECTOR
Valuation: $0.00
Contractor Company:
Contractor Name: P VERARDI CONSTRUCTION CO

Date: **12/19/2000**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B210252
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: SPIELER & RICCA ELEC'L CO

ADJOINING PROPERTY FINDINGS

Date: **5/16/1997**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use:
Permit Number: 300623626-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: IRA J BENLEVI ARCHITECT

Date: **11/4/1996**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B159731
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: JECO ELEC'L SERVICE CORP.

457 39TH ST

Date: **7/15/2015**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: B398347
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date:	**7/13/2015**
Permit Type:	**AL**
Description:	**FIRE PROTECTION PLAN IN CONJUNCTION WITH NB 320724221. NO CHANGE TO USE, OCCUPANCY OR EGRESS.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	340202514-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	W & L GROUP CONSTRUCTION

Date:	**6/8/2015**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	
Proposed Use:	
Permit Number:	B396801
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date:	**6/5/2015**
Permit Type:	**AL**
Description:	**INSTALL 13' CURB CUT INCLUDING 2 X 2.5' SPLAY AREA AT NORTH SIDE OF 39TH STREET 259.50' FROM CORNER OF 39TH STREET AND 5TH AVENUE IN CONJUNCTION WITH NB 320724221. NO CHANGE TO USE, OCCUPANCY OR EGRESS.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	321120924-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	W & L GROUP CONSTRUCTION

Date:	**4/21/2015**
Permit Type:	**EQ**
Description:	**INSTALLATION OF SIDEWALK SHED AS PER PLANS. WORK SHALL COMPLY WITH 2008 BUILDING CODE CHAPTER 33. NO CHANGE IN USE EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	340138906-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	TRI BOROUGH SCAFFOLDING

ADJOINING PROPERTY FINDINGS

Date: **2/25/2015**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 321085785-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: PAUL SIGNS, INC

Date: **2/18/2015**
Permit Type: **EW**
Description: **INSTALL EMERGENCY GENERATOR AT OPEN SPACE IN CONJUNCTION WITH NB 320724221. NO CHANGE TO USE, OCCUPANCY OR EGRESS.**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FUEL STORAGE
Permit Number: 340152667-01-EW-FS
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: JACK PICCINI, INC

Date: **12/3/2014**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 320724221-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: H & F PLUMBING INC

ADJOINING PROPERTY FINDINGS

Date:	**11/28/2014**
Permit Type:	**EW**
Description:	**INSTALL AUTOMATIC FIRE SUPPRESSION SYSTEM IN CONJUNCTION WITH JOB#320724221 . NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FIRE SUPPRESSION
Permit Number:	321162317-01-EW-FP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NY FIRE LLC

Date:	**7/24/2014**
Permit Type:	**EQ**
Description:	**INSTALLATION OF PIPE SCAFFOLD AS PER PLAN IN CONJUNCTION WITH NB 320724221. WORK SHALL COMPLY WITH 2008 BUILDING CODE CHAPTER 33. NO CHANGE IN USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SCAFFOLD
Permit Number:	340168115-01-EQ-SF
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	W & L GROUP CONSTRUCTION

ADJOINING PROPERTY FINDINGS

Date: **7/21/2014**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B383588
Status: Open
Valuation: $0.00
Contractor Company:
Contractor Name: TITAN ELEC'L & ELEV CONTR

Date: **6/20/2014**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: NB - NEW BUILDING
Proposed Use: FENCE
Permit Number: 320724221-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: W & L GROUP CONSTRUCTION

Date: **6/20/2014**
Permit Type: **FO**
Description:

Permit Description: **FOUNDATION/EARTHWORK**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 320724221-01-FO
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: W & L GROUP CONSTRUCTION

ADJOINING PROPERTY FINDINGS

Date: **6/20/2014**
Permit Type: **FO**
Description:

Permit Description: **FOUNDATION/EARTHWORK**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 320724221-01-FO-EA
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: W & L GROUP CONSTRUCTION

Date: **6/20/2014**
Permit Type: **NB**
Description:

Permit Description: **NEW BUILDING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 320724221-01-NB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: W & L GROUP CONSTRUCTION

Date: **4/25/2014**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B380306
Status: Open
Valuation: $0.00
Contractor Company:
Contractor Name: NASH ELECTRIC SERVICES IN

ADJOINING PROPERTY FINDINGS

Date: **3/24/2014**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: NEW BUILDING
Proposed Use:
Permit Number: B379019
Status: Open
Valuation: $0.00
Contractor Company:
Contractor Name: RIGHTWAY ELECTRICAL INC

Date: **3/24/2014**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: NEW BUILDING
Proposed Use:
Permit Number: B379022
Status: Open
Valuation: $0.00
Contractor Company:
Contractor Name: RIGHTWAY ELECTRICAL INC

459 39TH ST

Date: **7/10/2013**
Permit Type: **EQ**
Description: **FULL DEMOLITION OF 2 STORY BUILDING WITH BASEMENT.**

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: DM - FULL DEMOLITION
Proposed Use: FENCE
Permit Number: 320699703-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: 98 CONSTRUCTION INC

ADJOINING PROPERTY FINDINGS

Date: **5/7/2013**
Permit Type: **DM**
Description: **FULL DEMOLITION OF 2 STORY BUILDING WITH BASEMENT.**

Permit Description: **DEMOLITION & REMOVAL**
Work Class: DM - FULL DEMOLITION
Proposed Use:
Permit Number: 320699703-01-DM
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: 98 CONSTRUCTION INC

Date: **5/7/2013**
Permit Type: **DM**
Description: **FULL DEMOLITION OF 1 STORY GARAGE.**

Permit Description: **DEMOLITION & REMOVAL**
Work Class: DM - FULL DEMOLITION
Proposed Use:
Permit Number: 320699712-01-DM
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: 98 CONSTRUCTION INC

Date: **5/17/1998**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B176967
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: EMPIRE ELECT. CONTR'G INC

ADJOINING PROPERTY FINDINGS

4 AVE

4002 4 AVE

Date:	**5/16/2011**
Permit Type:	**EQ**
Description:	**INSTALLATION OF DEBRIS NETTING AROUND EXISTING FENCE AS INDICATED ON PLANS. THERE WILL BE NO CHANGE IN THE USE, EGRESS, OR OCCUPANCY UNDER THIS APPLICATION.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	FENCE
Permit Number:	302561190-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PMY CONSTRUCTION CORP

4009 4 AVE

Date:	**2/16/2000**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B198585
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CITYWIDE ELEC'L CONTR'G

ADJOINING PROPERTY FINDINGS

993 4 AVE

Date: **1/18/1995**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 300402080-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTH SHORE NEON SIGN CO.

Date: **1/18/1995**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 300402295-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTH SHORE NEON SIGN CO.

Date: **1/18/1995**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 300402972-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTH SHORE NEON SIGN CO.

ADJOINING PROPERTY FINDINGS

Date: **1/18/1995**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 300403472-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTH SHORE NEON SIGN CO.

Date: **1/18/1995**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 300403481-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTH SHORE NEON SIGN CO.

Date: **10/7/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B131940
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

ADJOINING PROPERTY FINDINGS

Date: **10/7/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B131941
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

Date: **10/7/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B131942
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

Date: **10/7/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B131943
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

ADJOINING PROPERTY FINDINGS

Date: **10/7/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B131944
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

Date: **10/7/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B131945
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

Date: **10/7/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B131946
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

ADJOINING PROPERTY FINDINGS

Date: **10/7/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B131947
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

Date: **10/7/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B131948
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

Date: **10/7/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B131949
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

ADJOINING PROPERTY FINDINGS

Date: **10/7/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B131950
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

40 ST

459-461 40 ST

Date: **8/10/2005**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B270425
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: KJK ELECTRIC INC

ADJOINING PROPERTY FINDINGS

40TH ST

313 40TH ST

Date:	**1/29/2019**
Permit Type:	**EW**
Description:	**EXISTING TWO-FAMILY HOUSE INTERIOR RENOVATION PER PLANS, NO CHANGE IN USE, EGRESS, AND OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	340644360-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SUPER POWER CONSTRUCTION

Date:	**1/29/2019**
Permit Type:	**EW**
Description:	**EXISTING TWO-FAMILY HOUSE INTERIOR RENOVATION PER PLANS, NO CHANGE IN USE, EGRESS, AND OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	340644360-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SUPER POWER CONSTRUCTION

ADJOINING PROPERTY FINDINGS

Date:	**12/20/2018**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00112500I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	KWONG MING ELECTRIC INC

Date:	**12/5/2018**
Permit Type:	**PL**
Description:	**EXISTING TWO-FAMILY HOUSE INTERIOR RENOVATION PER PLANS, NO CHANGE IN USE, EGRESS, AND OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	340644360-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	TRI STATE PLBG & HTG INC

ADJOINING PROPERTY FINDINGS

315 40TH ST

Date:	**9/24/2002**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B233524
Status:	VIOLATN PENDING AT CONTRACTOR
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RAINBOW ELECTRIC CO. INC

323 40TH ST

Date:	**7/6/1993**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B114188
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	TANG ELEC'L CO. INC.

ADJOINING PROPERTY FINDINGS

325 40TH ST

Date: **11/30/2002**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B233535
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: Y.E.A.S. ELECTRIC INC.

Date: **2/26/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B109873
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: TRINITY ELECTRIC

ADJOINING PROPERTY FINDINGS

327 40TH ST

Date:	**7/20/1994**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B130241
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HEAVEN INDUSTRIAL ELEC IN

333 40TH ST

Date:	**5/13/1997**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B165558
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	F & F ELECTRICAL CORP.

ADJOINING PROPERTY FINDINGS

Date: **10/24/1988**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B044874
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: NORWAY ELECTRIC CORP.

339 40TH ST

Date: **6/8/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B099882
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: L & D ELECTRIC CO.

Date: **2/3/1987**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B015646
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: MAOR ELECTR'L SERV. INC.

ADJOINING PROPERTY FINDINGS

341 40TH ST

Date:	**8/3/2000**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B204525
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	GENERAL ELEC'L CONTR'G CO

345 40TH ST

Date:	**12/5/1985**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	K30554
Status:	CLOSED/CANCELLED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	REILLY ELECTRICAL INC.

ADJOINING PROPERTY FINDINGS

347 40TH ST

Date:	**1/11/2023**
Permit Type:	**PL**
Description:	**ENLARGEMENT AND RENOVATION OF 3 STORY WOOD FRAME 2 FAMILY STRUCTURE**
Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	321732746-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EZ RUNER CONSTRUCTION COR

Date:	**8/25/2022**
Permit Type:	**FO**
Description:	**ENLARGEMENT AND RENOVATION OF 3 STORY WOOD FRAME 2 FAMILY STRUCTURE**
Permit Description:	**FOUNDATION/EARTHWORK**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	321732746-01-FO
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A & S SCULLARI CONSTRUCTI

ADJOINING PROPERTY FINDINGS

Date:	**8/25/2022**
Permit Type:	**FO**
Description:	**ENLARGEMENT AND RENOVATION OF 3 STORY WOOD FRAME 2 FAMILY STRUCTURE**
Permit Description:	**FOUNDATION/EARTHWORK**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	321732746-01-FO-EA
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A & S SCULLARI CONSTRUCTI

Date:	**5/3/2022**
Permit Type:	**AL**
Description:	**ENLARGEMENT AND RENOVATION OF 3 STORY WOOD FRAME 2 FAMILY STRUCTURE**
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	321732746-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A & S SCULLARI CONSTRUCTI

Date:	**9/29/1995**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B145692
Status:	NO ACCESS
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HEAVEN INDUSTRIAL ELEC IN

ADJOINING PROPERTY FINDINGS

355 40TH ST

Date:	**5/20/2004**
Permit Type:	**PL**
Description:	**Install new partitions and bathroom on first floor. No change in use, occupancy, or egress.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	301798053-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	LI SHING LAM CORP

Date:	**5/10/2004**
Permit Type:	**EW**
Description:	**Install new partitions and bathroom on first floor. No change in use, occupancy, or egress.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	301798053-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	URBAN COTTAGES INC

ADJOINING PROPERTY FINDINGS

Date:	**5/10/2004**
Permit Type:	**EW**
Description:	**Install new partitions and bathroom on first floor. No change in use, occupancy, or egress.**

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301798053-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	URBAN COTTAGES INC

Date:	**2/15/1997**
Permit Type:	
Description:	

Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B162601
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	UNITED ELEC'L CONT'G CORP

ADJOINING PROPERTY FINDINGS

359 40TH ST

Date: **8/31/2007**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B295006
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ERIC & NG ELEC'L INC.

Date: **6/29/2007**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B292551
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ERIC & NG ELEC'L INC.

ADJOINING PROPERTY FINDINGS

Date:	**6/19/2007**
Permit Type:	**PL**
Description:	**RENOVATE EXISTING TWO FAMILY HOUSE INTO A THREE FAMILY HOUSE. NEW C OF O REQUIRED FOR CHANGE TO NUMBER OF DWELLING UNITS. NO CHANGE TO USE, EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	302339789-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	DYCKMAN

Date:	**6/6/2007**
Permit Type:	**AL**
Description:	**RENOVATE EXISTING TWO FAMILY HOUSE INTO A THREE FAMILY HOUSE. NEW C OF O REQUIRED FOR CHANGE TO NUMBER OF DWELLING UNITS. NO CHANGE TO USE, EGRESS OR OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	302339789-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	LINDEN GROUP CONST CORP

ADJOINING PROPERTY FINDINGS

Date:	**5/14/2007**
Permit Type:	**EW**
Description:	**REMOVE INTERIOR PARTITIONS AT FIRST FLOOR, REMOVE KITCHEN CABINETS AT 002 AND 003. MINOR PARTITION WORK AT 002 AND 003. NO CHANGE TO USE OCCUPANCY OR EGRESS UNDER THIS APPLICATION. JOB FILED IN CONJUNCTION WITH ALT. 1 JOB NUMBER 302339789.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	302347306-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	LINDEN GROUP CONSTRUCTION CORP.

Date:	**8/26/1996**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B157138
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ROTHSTEIN & HOFFMAN ELEC.

ADJOINING PROPERTY FINDINGS

365 40TH ST

Date:	**7/18/2014**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B383597
Status:	Open
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ELECTROTEC OF NY ELECL IN

Date:	**1/20/2003**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B235244
Status:	VIOLATN PENDING AT CONTRACTOR
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALPINE ELEC'L CONTRACTOR

ADJOINING PROPERTY FINDINGS

409 40TH ST

Date:	**1/9/2018**
Permit Type:	**PL**
Description:	**HEREWITH TO PROPOSE REPLACEMENT OF EXIST. GAS METERS MANIFOLD AND SECURE TO WALL AT CELLAR FLOOR. NO CHANGES IN OCCUPANCY,USE,GROUP OR EGRESS UNDER THIS APPLICATION**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321480385-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	2M MECHANICAL LLC

Date:	**12/11/2013**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	MINOR WORK
Proposed Use:	
Permit Number:	B375552
Status:	Closed
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ELECTROTEC OF NY ELECL IN

ADJOINING PROPERTY FINDINGS

Date: **3/6/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B276594
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: EMERGENCY ELEC'L CONTR'G

Date: **2/16/2000**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B200857
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITYWIDE ELEC'L CONTR'G

411 40TH ST

Date: **10/30/2015**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: B402944
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date:	**3/10/2015**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	MINOR WORK
Proposed Use:	
Permit Number:	B392821
Status:	ADMINISTRATIVELY CLOSED (MINOR WORK), Closed
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RIVIERA ELECTRIC CORP

Date:	**9/30/2003**
Permit Type:	**PL**
Description:	**First floor and cellar interior renovation, new plumbing as per plan, repair ceiling of 2nd floor rear as per plan, no change to use, egress, or occupancy.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	301496842-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ADVANCED PLBG,HTG & SPRINKLER

Date:	**8/4/2003**
Permit Type:	**EW**
Description:	**First floor and cellar interior renovation, new plumbing as per plan, repair ceiling of 2nd floor rear as per plan, no change to use, egress, or occupancy.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301496842-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MK BUILDERS CORP

ADJOINING PROPERTY FINDINGS

Date: **6/5/2003**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B240595
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: ALEF ELEC'L CONTR'G INC

414 40TH ST

Date: **12/15/2014**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B389884
Status: Open
Valuation: $0.00
Contractor Company:
Contractor Name: JAMES WALTERS ELECTL

ADJOINING PROPERTY FINDINGS

415 40TH ST

Date:	**5/18/2001**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B213827
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALBERT DEWDNEY

417 40TH ST

Date:	**9/3/2009**
Permit Type:	**AL**
Description:	**WINDOW LINTELS CHANGE AS PER PLANS, NO CHANGE IN USE OCCUPANY OR EGRESS UNDER THIS APPLICATION. SIDEWALK SHED FILED UNDER SEPARATE APPLICATION.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	320069983-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ROYAL B CONSTRUCTION CORP

ADJOINING PROPERTY FINDINGS

Date: **10/9/1996**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B158492
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: P & M ELECT'L CONTR. CORP

Date: **7/12/1988**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B040277
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: BERNARDO ELECTRIC CO.

Date: **12/4/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B012899
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: PRECISION ELEC'L CONTR'G

ADJOINING PROPERTY FINDINGS

418 40TH ST

Date:	**1/17/2001**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B209847
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BERNARDO ELECTRIC CO.

420 40TH ST

Date:	**4/5/2004**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B251878
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BERNARDO ELECTRIC CO.

ADJOINING PROPERTY FINDINGS

Date:	**4/24/2003**
Permit Type:	**EW**
Description:	**REPLACE LOW PRESSURE BOILER. INSTALL NEW GAS SERVICE, METER AND PIPING, GAS BURNER AND (2) GAS FIRED HOT WATER HEATERS. DISCONTINUE FUEL OIL STORAGE TANKS. NO CHANGE IN USE, EGRESS OR OCCUPANCY IS INVOLVED UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301523947-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EMPIRE STATE FUEL CORP

Date:	**4/24/2003**
Permit Type:	**EW**
Description:	**REPLACE LOW PRESSURE BOILER. INSTALL NEW GAS SERVICE, METER AND PIPING, GAS BURNER AND (2) GAS FIRED HOT WATER HEATERS. DISCONTINUE FUEL OIL STORAGE TANKS. NO CHANGE IN USE, EGRESS OR OCCUPANCY IS INVOLVED UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	301523947-01-EW-BL
Status:	RE-ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ELITE PLBG & HTG INC.

ADJOINING PROPERTY FINDINGS

Date:	**4/24/2003**
Permit Type:	**PL**
Description:	**REPLACE LOW PRESSURE BOILER. INSTALL NEW GAS SERVICE, METER AND PIPING, GAS BURNER AND (2) GAS FIRED HOT WATER HEATERS. DISCONTINUE FUEL OIL STORAGE TANKS. NO CHANGE IN USE, EGRESS OR OCCUPANCY IS INVOLVED UNDER THIS APPLICATION.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	301523947-01-PL
Status:	RE-ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ELITE PLBG & HTG INC.

441 40TH ST

Date:	**10/15/1986**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B010196
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	INTERCITY ELEC'L CONTR'G

ADJOINING PROPERTY FINDINGS

Date: **8/19/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B007783
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CARMELO TRAPANI

442 40TH ST

Date: **3/20/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B276797
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: AL-ARM ELEC'L CONST.CORP

Date: **9/27/1989**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B058276
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: GILSON ELEC'L CO. INC.

ADJOINING PROPERTY FINDINGS

444 40TH ST

Date: **4/26/2016**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B410630
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: PETER J. CATANZARO,INC.

Date: **8/22/2002**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B232180
Status: HPD JOB AWAIT INSP REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: NORWAY ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

446 40TH ST

Date:	**10/21/2005**
Permit Type:	**EW**
Description:	**Replace existing boiler with a new Boiler This application is filed in cunjuction with application # 301492212 No change to occupancy, use, egress or bulk.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	301960215-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ABR PLUMBING & HEATING CONTRACTO

Date:	**10/7/2003**
Permit Type:	**AL**
Description:	**EXISTING SIX FAMILY MULTIPLE DWELLING TO BE CONVERTED TO AN 8 FAMILY MUL IPLE DWELLING AND OBTAIN A NEW CERTIFICA TE OF OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	301492212-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ABR PLUMBING & HEATING CONTRACT

ADJOINING PROPERTY FINDINGS

Date:	**10/7/2003**
Permit Type:	**PL**
Description:	**EXISTING SIX FAMILY MULTIPLE DWELLING TO BE CONVERTED TO AN 8 FAMILY MUL IPLE DWELLING AND OBTAIN A NEW CERTIFICA TE OF OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	301492212-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ABR PLUMBING & HEATING CONTRACT

Date:	**9/14/2003**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B244434
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BLUE RIBBON ELEC'L CONTRS

ADJOINING PROPERTY FINDINGS

448 40TH ST

Date: **10/12/1999**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B194917
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: CITI-WIDE ELECTRIC INC.

Date: **1/9/1992**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300122677-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: KOMFORT PLUMBING AND HEATING

Date: **1/9/1992**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300122677-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: KOMFORT PLUMBING AND HEATING

ADJOINING PROPERTY FINDINGS

Date: **8/21/1990**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B073114
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: MEDCO ELECL CONTRNG INC

451 40TH ST

Date: **2/6/2014**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B041198
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: RIVIERA ELECTRIC CORP

Date: **7/10/2013**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B369556
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: RIVIERA ELECTRIC CORP

ADJOINING PROPERTY FINDINGS

Date: **7/8/2013**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 320716757-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: TREVI PLUMBING INC

Date: **6/19/2013**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 320716757-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: LXS REALTY CORP

Date: **6/26/2000**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B203362
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: EMPIRE ELECT. CONTR'G INC

ADJOINING PROPERTY FINDINGS

Date: **12/20/1999**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300927709-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: THEODORE WAGNER PLG HTNG CORP

Date: **8/27/1999**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300927709-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name:

Date: **3/1/1999**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B186789
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: EMPIRE ELECT. CONTR'G INC

ADJOINING PROPERTY FINDINGS

452 40TH ST

Date: **3/24/2019**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00145746I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: PROSCIA ELECTL CONTRNG IN

Date: **3/2/2019**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00137162I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: PROSCIA ELECTL CONTRNG IN

ADJOINING PROPERTY FINDINGS

Date:	**3/8/2018**
Permit Type:	**EW**
Description:	**THIS APPLICATION IS FILED TO LEGALIZE METAL DECK @ BACK OF THE HOUSE. NO CHANGE OF EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321553760-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	452 40 STREET LLC

Date:	**6/26/1991**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	300098490-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	OIL SAVE CORP

Date:	**6/26/1991**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FUEL BURNING
Permit Number:	300098490-01-EW-FB
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	OIL SAVE CORP

ADJOINING PROPERTY FINDINGS

453 40TH ST

Date:	**12/7/2022**
Permit Type:	**PL**
Description:	**RENOVATION OF EXISTING APARTMENTS #1,#2 1ST FLOOR, NEW ACCESSORY SPACE IN CELLAR USED IN CONJUNCTION WITH THESE APARTMENTS.RENOVATION OF APT#6 3RD FLOOR,PARTITION AND PLUMBING WORK AS PER PLANS.NO CHANGE IN USE,EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321946249-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	P.S.I. MECHANICAL

Date:	**3/26/2020**
Permit Type:	**EW**
Description:	**RENOVATION OF EXISTING APARTMENTS #1,#2 1ST FLOOR, NEW ACCESSORY SPACE IN CELLAR USED IN CONJUNCTION WITH THESE APARTMENTS.RENOVATION OF APT#6 3RD FLOOR,PARTITION AND PLUMBING WORK AS PER PLANS.NO CHANGE IN USE,EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321946249-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	OZ BOSPH CONSTRUCTION COR

ADJOINING PROPERTY FINDINGS

Date: **1/21/2020**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00300015I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RIVIERA ELECTRIC CORP

Date: **12/26/2003**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B248121
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A#1 UNIVERSAL ELEC'L INC

ADJOINING PROPERTY FINDINGS

454 40TH ST

Date:	**6/28/2012**
Permit Type:	**EQ**
Description:	**PROPOSED INSTALLATION OF HEAVY DUTY SIDEWALK SHED FILED FOR REMEDIAL REPAIRS AS PER PLANS. NO CHANGE IN USE OCCUPANCY OR EGRESS UNDER THIS APPLICATION. LIVE LOAD 300 PER SQUARE FEET. SIDEWALK SHED SHALL COMPLY WITH CHAPTER # 33 OF THE 2008 CODE. NO STORAGE ON SIDEWALK SHED.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	320448878-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	LAND HOME IMPRO MATERIAL

Date:	**10/18/2010**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B332508
Status:	ASSIGNED TO INSPECTOR
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AA ELEC. CONTRACTOR INC

ADJOINING PROPERTY FINDINGS

Date: **5/19/2009**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B316541
Status: ADMINISTRATIVELY CLOSED (MINOR WORK)
Valuation: $0.00
Contractor Company:
Contractor Name: PHASOR ELEC. CO. INC.

Date: **7/9/1996**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300532895-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: HENRY TRAKTMAN

Date: **7/9/1996**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300532895-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: HENRY TRAKTMAN

ADJOINING PROPERTY FINDINGS

Date: **12/15/1995**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B147894
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: SPIRO ELECTRIC INC.

Date: **9/23/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B117736
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: LLEWELLYN ELECTRIC CORP.

Date: **2/15/1989**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B049389
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: JRC ELECTRIC CONTROL SERV

ADJOINING PROPERTY FINDINGS

455 40TH ST

Date: **7/30/2013**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B370261
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: RIVIERA ELECTRIC CORP

Date: **7/22/2013**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 320716739-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: FOUNTAIN OF TREVI, INC

Date: **7/11/2013**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 320716739-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: LXS REALTY CORP

ADJOINING PROPERTY FINDINGS

Date: **5/2/2002**
Permit Type: **EW**
Description: **REPLACE BOILER AND OIL BURNER**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 301341322-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BORO FUEL OIL CO INC

Date: **5/2/2002**
Permit Type: **EW**
Description: **REPLACE BOILER AND OIL BURNER**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FUEL BURNING
Permit Number: 301341322-01-EW-FB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BORO FUEL OIL CO INC

Date: **8/27/1999**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300927718-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

456 40TH ST

Date:	**2/28/2019**
Permit Type:	**EW**
Description:	**APPLICATION FILE TO REGISTER EXIST. BOILER, HWH AND INSTALL ONE GAS METER FOR BASEMENT. NO CHANGE IN USE, EGRESS OR OCCUPANCY UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	321912089-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JOHNNY'S P&H CONTRAC INC

Date:	**2/28/2019**
Permit Type:	**PL**
Description:	**APPLICATION FILE TO REGISTER EXIST. BOILER, HWH AND INSTALL ONE GAS METER FOR BASEMENT. NO CHANGE IN USE, EGRESS OR OCCUPANCY UNDER THIS APPLICATION.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321912089-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JOHNNY'S P&H CONTRAC INC

ADJOINING PROPERTY FINDINGS

Date:	**4/1/2006**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B277679
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A#1 UNIVERSAL ELEC'L INC

Date:	**5/14/2001**
Permit Type:	**EW**
Description:	**REPLACE BOILER AND OIL BURNER. NO CHANGE IN EGRESS, OCCUPANCY OR USE UNDER THIS APPLICATION. LOCAL LAW 17/95 DOES NOT APPLY TO THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	301152375-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALFRED F. CACCAMO

ADJOINING PROPERTY FINDINGS

Date:	**5/14/2001**
Permit Type:	**EW**
Description:	**REPLACE BOILER AND OIL BURNER. NO CHANGE IN EGRESS, OCCUPANCY OR USE UNDER THIS APPLICATION. LOCAL LAW 17/95 DOES NOT APPLY TO THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FUEL BURNING
Permit Number:	301152375-01-EW-FB
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALFRED F. CACCAMO

457 40TH ST

Date:	**12/10/2001**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B221738
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NEW GRAND ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

459 40TH ST

Date:	**8/10/2005**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B270425
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	KJK ELECTRIC INC

460 40TH ST

Date:	**8/2/1990**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B072132
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	S.N.S. ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

463 40TH ST

Date:	**6/29/2019**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00186626I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RIVIERA ELECTRIC CORP

Date:	**5/10/2013**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B367132
Status:	Closed
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RIVIERA ELECTRIC CORP

ADJOINING PROPERTY FINDINGS

Date:	**5/8/2013**
Permit Type:	**EW**
Description:	**INSTALLATION OF NEW GAS BOILER AS PER PLAN, PLUMBING WORK IS DONE UNDER ALT I APPLICATION.NO CHANGE IN USE,EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	320737413-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	TREVI PLUMBING INC

Date:	**4/15/2013**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B174494
Status:	Closed
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RIVIERA ELECTRIC CORP

Date:	**3/15/2013**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B363404
Status:	Closed
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RIVIERA ELECTRIC CORP

ADJOINING PROPERTY FINDINGS

Date: **1/18/2013**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B360199
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: RIVIERA ELECTRIC CORP

Date: **1/18/2013**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 320509099-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: TREVI PLUMBING INC

Date: **12/12/2012**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 320509099-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: LXS REALTY CORP

ADJOINING PROPERTY FINDINGS

Date: **6/26/2000**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B203363
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: EMPIRE ELECT. CONTR'G INC

Date: **12/29/1999**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300927727-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: THEODORE WAGNER PLUMBING AND HEA

Date: **11/23/1999**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300927727-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **1/3/1998**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B175083
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: EMPIRE ELECT. CONTR'G INC

464 40TH ST

Date: **8/21/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B281716
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: A#1 UNIVERSAL ELEC'L INC

ADJOINING PROPERTY FINDINGS

467 40TH ST

Date:	**2/27/2022**
Permit Type:	**EW**
Description:	**NEW STORAGE AREA FOR CAMERA ROOM ON CELLAR AT 43 SQ FT**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	322031467-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AM EXPEDITING DRAFTING &

Date:	**11/4/1996**
Permit Type:	**PL**
Description:	
Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	300094083-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	OLYMPIA MECHANICAL PIPING & HTG

Date:	**10/25/1996**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B158955
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AJS ELECTRICAL CORP.

ADJOINING PROPERTY FINDINGS

Date: **9/19/1996**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300094083-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name:

Date: **1/29/1990**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B063888
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: S.E.S. ELEC'L CORP.

468 40TH ST

Date: **9/22/1993**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300291048-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BAYSIDE FUEL OIL CORP.

ADJOINING PROPERTY FINDINGS

Date: **9/22/1993**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FUEL BURNING
Permit Number: 300291048-01-EW-FB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BAYSIDE FUEL OIL CORP.

Date: **8/7/1987**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B025622
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: FOSTER ELEC'L SVC. INC.

471 40TH ST

Date: **11/7/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B012124
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: FOSTER ELEC'L SVC. INC.

ADJOINING PROPERTY FINDINGS

472 40TH ST

Date: **12/15/2011**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B345422
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: KEVIN KEAVENY ELEC CO INC

Date: **4/22/2004**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B253631
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: K.J. MCGINLEY ELEC'L CONT

Date: **5/1/1995**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B140464
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: FROEDER ELECTRIC

ADJOINING PROPERTY FINDINGS

Date: **3/22/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300423110-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: D.J.F. SERVICE & INSTALLATION

Date: **3/22/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FUEL BURNING
Permit Number: 300423110-01-EW-FB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: D.J.F. SERVICE & INSTALLATION

ADJOINING PROPERTY FINDINGS

476 40TH ST

Date:	**11/30/2012**
Permit Type:	**AL**
Description:	**INSTALLATION OF A BUSINESS AWNING WORDING 'KAIROS CENTER CORP. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	320750380-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JRS CONSTRUCTION & EXPEDI

478 40TH ST

Date:	**2/25/2011**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B336284
Status:	AWAITING INSPECTION REQUEST, COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A#1 UNIVERSAL ELEC'L INC

ADJOINING PROPERTY FINDINGS

Date: **12/13/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B311799
Status: ASSIGNED TO INSPECTOR
Valuation: $0.00
Contractor Company:
Contractor Name: A#1 UNIVERSAL ELEC'L INC

Date: **4/15/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B303135
Status: ASSIGNED TO INSPECTOR
Valuation: $0.00
Contractor Company:
Contractor Name: A#1 UNIVERSAL ELEC'L INC

Date: **12/4/1996**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B160313
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A#1 UNIVERSAL ELEC'L INC

ADJOINING PROPERTY FINDINGS

Date: **5/22/1985**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K19926
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: MONTE ELECTRIC CO.

41ST ST

330 41ST ST

Date: **10/25/2005**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B273022
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A#1 UNIVERSAL ELEC'L INC

ADJOINING PROPERTY FINDINGS

Date: **7/15/2005**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B270304
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: GUIDA ELECTRIC INC.

334 41ST ST

Date: **2/24/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K30685
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: INTERPHASE ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

336 41ST ST

Date:	**4/30/2007**
Permit Type:	**PL**
Description:	**REVISE BASEMENT LAYOUT TO CONVERT EXISTING TWO FAMILY TO A THREE FAMILY DWELLING**
Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	302055264-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AUSTIN PLBG & HTG CO INC

Date:	**4/25/2007**
Permit Type:	**AL**
Description:	**REVISE BASEMENT LAYOUT TO CONVERT EXISTING TWO FAMILY TO A THREE FAMILY DWELLING**
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	302055264-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	GUERRERO'S

ADJOINING PROPERTY FINDINGS

338 41ST ST

Date:	**2/14/2014**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B378060
Status:	Closed
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HI-RITE ELECTRIC CORP.

340 41ST ST

Date:	**3/7/2023**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00839326I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ISLAND ELECTRIC CORP

ADJOINING PROPERTY FINDINGS

Date: **1/25/2023**
Permit Type: **EW**
Description: **INSTALLATION OF A ROOFTOP SOLAR PANEL PV SYSTEM**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 340876715-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: PRO CUSTOM SOLAR LLC

Date: **12/15/2017**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00005735I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: R.J.ELECTRIC&MAINTENANCE CONTRACTOR

346 41ST ST

Date: **5/23/1998**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B178136
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: TMF ELEC'L CONTR. INC.

ADJOINING PROPERTY FINDINGS

354 41ST ST

Date:	**2/23/2022**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00685463I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	DEMAND ELECTRIC INC

Date:	**3/29/2019**
Permit Type:	**EW**
Description:	**HEREWITH FILING FOR GENERAL CONSTRUCTION WORK AS PER PLANS. NO CHANGE IN USE, OCCUPANCY OR EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321485834-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NOTIAS CONSTRUCTION INC

ADJOINING PROPERTY FINDINGS

Date:	**9/5/2017**
Permit Type:	**EQ**
Description:	**INSTALLATION OF LIGHT DUTY SIDEWALK SHED DURING BUILDING ALTERATION, FILED SEPARATELY. SIDEWALK SHED SHALL COMPLY WITH CHAPTER #33 OF THE NYC BUILDING CODE. NO CHANGE IN USE, OCCUPANCY OR EGRESS UNDER THIS APPLICATION.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	340540114-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ADVANCED CONSTRUCTION EQU

Date:	**8/31/2017**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B433600
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NASH ELECTRIC SERVICES IN

ADJOINING PROPERTY FINDINGS

Date: **12/30/2014**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B389930
Status: Open
Valuation: $0.00
Contractor Company:
Contractor Name: ALSON ELEC'L CONTR. INC

Date: **5/17/2013**
Permit Type: **EW**
Description: **REPLACE BOILER AND OIL BURNER WITH BOILER AND GAS BURNER. REMOVE EXISTING FUEL STORAGE TANK. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 320759826-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: HI-TECH HEATING CORP

Date: **5/17/2013**
Permit Type: **EW**
Description: **REPLACE BOILER AND OIL BURNER WITH BOILER AND GAS BURNER. REMOVE EXISTING FUEL STORAGE TANK. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 320759826-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: HI-TECH HTG SPEC INC

ADJOINING PROPERTY FINDINGS

Date:	**5/17/2013**
Permit Type:	**PL**
Description:	**REPLACE BOILER AND OIL BURNER WITH BOILER AND GAS BURNER. REMOVE EXISTING FUEL STORAGE TANK. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320759826-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HI-TECH HTG SPEC INC

Date:	**12/17/1996**
Permit Type:	**PL**
Description:	
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	300424636-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MAINLAND PLUMBING & HEATING INC.

Date:	**6/6/1996**
Permit Type:	**EQ**
Description:	
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	300522664-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PORTCHESTER SCAFFOLDING

ADJOINING PROPERTY FINDINGS

Date: **5/17/1996**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300424636-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BLAKEL CONSTR CORP

Date: **1/17/1996**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B149132
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: E & M ELECT CONTRS CORP

Date: **8/31/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B135946
Status: LOCATION PROBLEM
Valuation: $0.00
Contractor Company:
Contractor Name: DEPT OF HOUS PRES & DEVEL

ADJOINING PROPERTY FINDINGS

Date: **8/16/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B116185
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: APPROVED ELEC CONT'G INC

Date: **3/31/1993**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FUEL BURNING
Permit Number: 300233478-01-EW-FB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CAPITOL FUEL OIL TRANSPORTATION

Date: **3/29/1993**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300233478-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CAPITOL FUEL OIL TRANSPORTATION

ADJOINING PROPERTY FINDINGS

Date: **12/12/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B107939
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: THOMAS ELECTRIC INC.

Date: **7/24/1991**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B086572
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: APPROVED ELEC CONT'G INC

Date: **10/16/1990**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B075537
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: OLYMPIC ELECT WIRING CORP

ADJOINING PROPERTY FINDINGS

Date: **9/4/1990**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B073849
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: OLYMPIC ELECT WIRING CORP

Date: **5/1/1984**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K04440
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: BLUE RIBBON ELEC'L CONTRS

ADJOINING PROPERTY FINDINGS

358 41ST ST

Date:	**3/29/2019**
Permit Type:	**EW**
Description:	**HEREWITH FILING FOR GENERAL CONSTRUCTION WORK AS PER PLANS. NO CHANGE IN USE, OCCUPANCY, OR EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321485861-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NOTIAS CONSTRUCTION INC

Date:	**9/5/2017**
Permit Type:	**EQ**
Description:	**INSTALLATION OF LIGHT DUTY SIDEWALK SHED DURING BUILDING ALTERATION, FILED SEPARATELY. SIDEWALK SHED SHALL COMPLY WITH CHAPTER #33 OF THE NYC BUILDING CODE. NO CHANGE IN USE, OCCUPANCY OR EGRESS UNDER THIS APPLICATION.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	340540105-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ADVANCED CONSTRUCTION EQU

ADJOINING PROPERTY FINDINGS

Date:	**8/31/2017**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B433601
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NASH ELECTRIC SERVICES IN

Date:	**7/2/2015**
Permit Type:	**PL**
Description:	**REPLACE BOILER AND OIL BURNER WITH BOILER AND GAS BURNER. REMOVE EXISTING FUEL STORAGE TANK. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320846992-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HI-TECH HTG SPEC INC

Date:	**8/21/2013**
Permit Type:	**EW**
Description:	**REPLACE BOILER AND OIL BURNER WITH BOILER AND GAS BURNER. REMOVE EXISTING FUEL STORAGE TANK. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	320846992-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HI-TECH HTG SPEC INC

ADJOINING PROPERTY FINDINGS

Date:	**8/15/2013**
Permit Type:	**EW**
Description:	**REPLACE BOILER AND OIL BURNER WITH BOILER AND GAS BURNER. REMOVE EXISTING FUEL STORAGE TANK. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320846992-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HI-TECH HEATING CORP

Date:	**7/8/2011**
Permit Type:	**EW**
Description:	**THE REPLACEMENT OF THE EXISTING GAS FIRED BOILER WITH TANKLESS COIL UTILIZING EXISTING CHIMNEY FOR VENTING**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	320303612-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CENTRAL PLBG&HTG SVC CORP

Date:	**5/17/1996**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	300424645-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BLAKEL CONSTR CORP

ADJOINING PROPERTY FINDINGS

Date: **1/19/1996**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300424645-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: TOTAL PLUMBING AND HEATING INC.

Date: **1/19/1996**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B149444
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: E & M ELECT CONTRS CORP

Date: **10/5/1995**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use: SIDEWALK SHED
Permit Number: 300469286-01-EQ-SH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: PORTCHESTER SCAFFOLDING

ADJOINING PROPERTY FINDINGS

Date: **9/12/1994**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300384849-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: EASTERN EMPIRE CONT CORP

Date: **5/30/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B127926
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: OLYMPIC ELECT WIRING CORP

Date: **3/9/1994**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300329099-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CAPITOL FUEL OIL TRANSPORT CORP.

ADJOINING PROPERTY FINDINGS

Date: **3/9/1994**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FUEL BURNING
Permit Number: 300329099-01-EW-FB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CAPITOL FUEL OIL TRANSPORT CORP.

Date: **10/25/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B118895
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: NUNEZ ELECTRIC INC.

Date: **10/7/1993**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use: SIDEWALK SHED
Permit Number: 300299406-01-EQ-SH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: LAKHI GENERAL CONTRACTOR INC.

ADJOINING PROPERTY FINDINGS

Date: **10/5/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B119967
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: P & M ELECT'L CONTR. CORP

Date: **9/28/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B117819
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: THORN ELECTRIC INC.

Date: **9/1/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B117278
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: DA-WILL ELECTRIC CO.INC.

ADJOINING PROPERTY FINDINGS

Date: **6/7/1993**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300243412-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CAPITOL FO TRANSP. CORP

Date: **6/7/1993**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FUEL BURNING
Permit Number: 300243412-01-EW-FB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CAPITOL FO TRANSP. CORP

Date: **5/17/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B116264
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: DELTEX ELECTRICAL CONT.

ADJOINING PROPERTY FINDINGS

Date: **3/15/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B109967
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: ROBIN ELECTRICAL CO. INC

Date: **3/3/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B110027
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: PHASOR ELEC. CO. INC.

Date: **2/22/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B109429
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: OLYMPIC ELECT WIRING CORP

ADJOINING PROPERTY FINDINGS

Date: **2/12/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B109399
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: OLYMPIC ELECT WIRING CORP

Date: **2/11/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B109544
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: THOMAS ELECTRIC INC.

Date: **5/20/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B099524
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: DELTEX ELECTRICAL CONT.

ADJOINING PROPERTY FINDINGS

Date: **12/2/1991**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B093149
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: KONSKER ELECTRIC CORP.

Date: **11/11/1991**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B092118
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: OLYMPIC ELECT WIRING CORP

Date: **9/25/1991**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B091353
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: OLYMPIC ELECT WIRING CORP

ADJOINING PROPERTY FINDINGS

Date:	**9/4/1991**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B090060
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	OLYMPIC ELECT WIRING CORP

360 41ST ST

Date:	**5/10/2017**
Permit Type:	**PL**
Description:	**INSTALL BOILERS AND H.W. HEATERS. NO CHANGE TO USE,EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321446985-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NEW YORK STANDARD MECH CO

ADJOINING PROPERTY FINDINGS

Date: **4/26/2017**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B427577
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: ACCURATE ELEC'L CORP.

Date: **12/20/2003**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B248018
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ERIC & NG ELEC'L INC.

Date: **6/5/2003**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B244771
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: AAR/CO ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

362 41ST ST

Date:	**2/7/2013**
Permit Type:	**EQ**
Description:	**FILING HEREWITH FACADE REPAIR - REPLACING DEFECTIVE WINDOW LINTELS & BRICK REPOINTING WHERE REQUIRED AND WINDOW REPLACEMENT. DIRECTIVE II FILING IS HEREWITH REQUESTED; NO CHANGE IN EGRESS, USE, OR OCCUPANCY. SHED FILED UNDER SEPARATE APPLICATION AS SHOWN.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	SCAFFOLD
Permit Number:	320702655-01-EQ-SF
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MARTAN PROPERTIES LLC

Date:	**2/7/2013**
Permit Type:	**EW**
Description:	**FILING HEREWITH FACADE REPAIR - REPLACING DEFECTIVE WINDOW LINTELS & BRICK REPOINTING WHERE REQUIRED AND WINDOW REPLACEMENT. DIRECTIVE II FILING IS HEREWITH REQUESTED; NO CHANGE IN EGRESS, USE, OR OCCUPANCY. SHED FILED UNDER SEPARATE APPLICATION AS SHOWN.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320702655-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MARTAN PROPERTIES LLC

ADJOINING PROPERTY FINDINGS

Date:	**12/26/2012**
Permit Type:	**EQ**
Description:	**INSTALLATION OF HEAVY DUTY SIDEWALK SHED AS PER PLANS. NO CHANGE IN USE, EGRESS, OR OCUUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	320691783-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PILKU CONSTRUCTION SERVIC

Date:	**9/18/2008**
Permit Type:	**PL**
Description:	**RENOVATION OF CELLAR TO ACCOMMODATE SUPERINTENDENT'S MEETING ROOM AS PER PLANS SUBMITTED. NO CHANGE IN EGRESS, USE, OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	310195179-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AMERICAN NATIONAL PLG & HTG INC

ADJOINING PROPERTY FINDINGS

Date:	**8/28/2008**
Permit Type:	**EW**
Description:	**RENOVATION OF CELLAR TO ACCOMMODATE SUPERINTENDENT'S MEETING ROOM AS PER PLANS SUBMITTED. NO CHANGE IN EGRESS, USE, OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	310195179-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

Date:	**5/15/2007**
Permit Type:	**AL**
Description:	**INTERIOR RENOVATION OF EXISTING APARTMENT NUMBER 44 AT FOURTH FLOOR OF EXISTING BUILDING. NO CHANGE IN EGRESS, USE, OR OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	302339306-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	DBA PRICEBUSTER CORNER

ADJOINING PROPERTY FINDINGS

Date: **2/21/2004**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: NB - NEW BUILDING
Proposed Use: FENCE
Permit Number: 301501266-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: KHORSANDI

Date: **2/21/2004**
Permit Type: **NB**
Description:

Permit Description: **NEW BUILDING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 301501266-01-NB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: KHORSANDI

Date: **7/10/2003**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 301501266-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WAGNER ZIV PLBG & HTG CORP

ADJOINING PROPERTY FINDINGS

Date: **8/28/1989**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B056915
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: JRC ELECTRIC CONTROL SERV

366 41ST ST

Date: **8/17/2019**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00212339I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: J.A. LEE ELEC SVCS LLC

ADJOINING PROPERTY FINDINGS

Date:	**9/12/2017**
Permit Type:	**AL**
Description:	**INTERIOR RENOVATION OF THIRD FLOOR APARTMENT #5 INCLUDING CEILING, WALLS, FLOORS, AND REPLACE KITCHEN, & BATH FIXTURES ON EXISTING ROUGHING. NO CHANGE IN EGRESS,USE, OR OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	321526675-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BESCO BUILDERS LLC

Date:	**8/16/2016**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B415803
Status:	NO ACCESS
Valuation:	$0.00
Contractor Company:	
Contractor Name:	DNR ELECTRIC INCORPORATE

ADJOINING PROPERTY FINDINGS

Date:	**2/23/2016**
Permit Type:	**EW**
Description:	**GENERAL RENOVATION OF APARTMENT 1L AT FIRST FLOOR. PATCH, PAINT, REPAIR WALLS AND FLOORS, REPLACE KITCHEN AND BATH FIXTURES AS NEEDED. NO CHANGE IN EGRESS, USE, OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321137159-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MARTAN PROPERTIES LLC

Date:	**3/10/2015**
Permit Type:	**AL**
Description:	**INSTALLATION OF TELECOMMUNICATIONS ANTENNAS AND RELATED EQUIPMENT ON THE ROOF. ALL IN CONFORMANCE WITH TPPN 5/98. NO CHANGE IN USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	321065501-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	COMMUNICATION COMPONENT S

ADJOINING PROPERTY FINDINGS

Date:	**4/2/2014**
Permit Type:	**EW**
Description:	**FILING HEREWITH FACADE REPAIR - RENOVATE BUILDING FACADE INCLUDING REPAIR/REPLACING OF PARAPET WALL,WHERE REQUIRED: DEFECTIVE WINDOW LINTELS, WINDOW REPLACEMENT, PARAPET WALL, & BRICK POINTING. DIRECTIVE II FILING IS HEREWITH REQUESTED. SHED TO BE FILED UNDER SEPERATE APPLICATION. NO CHANGE IN EGRESS, USE, OR OCCUPANC**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320760020-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MARTAN PROPERTIES LLC

Date:	**4/2/2014**
Permit Type:	**EQ**
Description:	**FILING HEREWITH FACADE REPAIR - RENOVATE BUILDING FACADE INCLUDING REPAIR/REPLACING OF PARAPET WALL,WHERE REQUIRED: DEFECTIVE WINDOW LINTELS, WINDOW REPLACEMENT, PARAPET WALL, & BRICK POINTING. DIRECTIVE II FILING IS HEREWITH REQUESTED. SHED TO BE FILED UNDER SEPERATE APPLICATION. NO CHANGE IN EGRESS, USE, OR OCCUPANC**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	SCAFFOLD
Permit Number:	320760020-01-EQ-SF
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MARTAN PROPERTIES LLC

ADJOINING PROPERTY FINDINGS

Date:	**1/8/2014**
Permit Type:	**EQ**
Description:	**INSTALLATION OF HEAVY DUTY SIDEWALK SHED AS PER PLANS. NO CHANGE IN USE, EGRESS, OR OCCUPANCY**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	320757490-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PILKU CONSTRUCTION SERVIC

Date:	**10/11/2013**
Permit Type:	**EQ**
Description:	**INSTALLATION OF PIPE SCAFFOLD AS PER PLANS. NO CHANGE IN USE, EGRESS, OR OCCUPANCY**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SCAFFOLD
Permit Number:	340090109-01-EQ-SF
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MARTAN PROPERTIES LLC

Date:	**7/9/2013**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B369939
Status:	Closed
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NASH ELECTRIC SERVICES IN

ADJOINING PROPERTY FINDINGS

Date:	**8/12/2009**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION OF EXISTING APARTMENT #43 @ 4TH FLOOR. NO CHANGE IN EGRESS, USE, OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320055079-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALESSANDRO PIROZZI

Date:	**5/15/2007**
Permit Type:	**AL**
Description:	**INTERIOR RENOVATION OF EXISTING APARTMENTS NUMBER 44 AND 45 AT FOURTH FLOOR OF EXISTING BUILDING. NO CHANGE IN EGRESS, USE, OR OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	302338691-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	DBA PRICEBUSTER CORNER

ADJOINING PROPERTY FINDINGS

Date: **5/3/1995**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B140463
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: FROEDER ELECTRIC

Date: **10/31/1994**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300395944-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: ROBERT LEONARD, INC

Date: **10/13/1994**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300392448-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: D.J.F. SERV. & INSTALL SYS. INC.

ADJOINING PROPERTY FINDINGS

Date: **10/13/1994**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FUEL BURNING
Permit Number: 300392448-01-EW-FB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: D.J.F. SERV. & INSTALL SYS. INC.

Date: **10/13/1994**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300392448-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: DURR PLUMBING, INC.

413 41ST ST

Date: **6/7/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B113121
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: S C ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

414 41ST ST

Date:	**9/5/2002**
Permit Type:	**EW**
Description:	**Legalization of cellar condition to be use as an accessory room with first floor dwelling and metal deck at rear of building.**

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301409107-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

Date:	**9/5/2002**
Permit Type:	**PL**
Description:	**Legalization of cellar condition to be use as an accessory room with first floor dwelling and metal deck at rear of building.**

Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	301409107-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JOE TRUCE PLUMBING, INC.

ADJOINING PROPERTY FINDINGS

Date: **5/13/1987**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B021121
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: DEAN ELECTRIC CO. INC.

415 41ST ST

Date: **4/9/1989**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B051522
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ALWON ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

417 41ST ST

Date:	**8/4/2011**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B341352
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Q.Y. ELECTRIC INC

Date:	**8/22/2002**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B230305
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALBERT DEWDNEY

ADJOINING PROPERTY FINDINGS

418 41ST ST

Date: **10/14/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B009918
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ALWON ELECTRIC CORP.

Date: **9/10/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B010441
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: ABRAHAM STERN

ADJOINING PROPERTY FINDINGS

421 41ST ST

Date:	**10/7/2019**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00241172I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A#1 UNIVERSAL ELEC'L INC

422 41ST ST

Date:	**5/29/2008**
Permit Type:	**EW**
Description:	**RENOVATE EXISTING 2-FAMILY DWELLING BY RELOCATING BATHROOM AND KITCHENS. CREATE A 1-STORY EXTENSION AT REAR OF BASEMENT. MAKE BASEMENT ACCESSORY USE TO 1ST FLOOR DWELLING UNIT WITH 2-PIECE BATHROOM.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	310071034-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AIMELITE CONST CORP

ADJOINING PROPERTY FINDINGS

Date:	**2/19/2008**
Permit Type:	**PL**
Description:	**RENOVATE EXISTING 2-FAMILY DWELLING BY RELOCATING BATHROOM AND KITCHENS. CREATE A 1-STORY EXTENSION AT REAR OF BASEMENT. MAKE BASEMENT ACCESSORY USE TO 1ST FLOOR DWELLING UNIT WITH 2-PIECE BATHROOM.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	310071034-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RIGID PLUMBING CONTRACTOR'S INC.

Date:	**2/4/2008**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B300270
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ACCURATE ELEC'L CORP.

ADJOINING PROPERTY FINDINGS

423 41ST ST

Date:	**1/3/2019**
Permit Type:	**PL**
Description:	**RENOVATE EXISTING TWO FAMILY RESIDENCE. NO CHANGE TO USE,EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321518871-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JMW PLUMBING, INC

Date:	**10/28/2018**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00093415I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	OMD ELECTRICAL CORP

ADJOINING PROPERTY FINDINGS

Date:	**7/10/2018**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00060068I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BROOKLYN SOLARWORKS, LLC

Date:	**4/27/2018**
Permit Type:	**EW**
Description:	**INSTALL SOLAR PV SYSTEM ON THE EXISTING ROOFTOP. NO CHANGES TO USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	340597090-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BROOKLYN SOLARWORKS LLC

Date:	**4/6/2018**
Permit Type:	**EW**
Description:	**RENOVATE EXISTING TWO FAMILY RESIDENCE. NO CHANGE TO USE,EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321518871-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	DALEY SHELCO CONSTRUCTION

ADJOINING PROPERTY FINDINGS

424 41ST ST

Date:	**2/16/1988**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B033799
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BROWN ELECTRIC SHOP INC.

427 41ST ST

Date:	**12/10/2020**
Permit Type:	**EW**
Description:	**PROPOSED INTERIOR RENOVATION AT CELLAR, 001 THRU 003. REMOVE PARTITION WALL AND DOORS AS PER PLAN. REMOVE A EXISTING STAIR AS PER PLAN. REPAIR OF EXISTING FLOORING AND CEILING. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	322039370-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WINWAY DEVELOPMENT LLC

ADJOINING PROPERTY FINDINGS

Date:	**9/20/2007**
Permit Type:	**PL**
Description:	**INSTALL TWO GAS BOILERS AND GAS H.W.HEATERS @ CELLAR FOR 1ST AND 2ND FL. APTS. NO CHANGE IN USE, OCCUPANCY OR EGRESS.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	310020884-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	LI SHING LAM CORP.

Date:	**7/5/2007**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B293252
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AEC ELECTRICAL CO INC

Date:	**5/9/2005**
Permit Type:	**AL**
Description:	**CONVERT EXISTING 2 FAMILY DWELLING TO 3 FAMILY DWELLING. PARTITION & PLUMBING WORK AS PER PLAN.**
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	301795573-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A-1 WATER MAIN & SEWER CO

ADJOINING PROPERTY FINDINGS

Date:	**9/16/2004**
Permit Type:	**PL**
Description:	**CONVERT EXISTING 2 FAMILY DWELLING TO 3 FAMILY DWELLING. PARTITION & PLUMBING WORK AS PER PLAN.**
Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	301795573-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A-1 WATER MAIN & SEWER CR

Date:	**8/19/2004**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B257212
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SCHORR'S ELECTRIC CO. INC

Date:	**10/16/1986**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B010322
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NELSON&TOM MAINTDBA TOMCO LAWRENCE NELSON

ADJOINING PROPERTY FINDINGS

429 41ST ST

Date:	**6/13/1988**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B042237
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	FOSTER ELEC'L SVC. INC.

432 41ST ST

Date:	**10/8/1997**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B170362
Status:	NO ACCESS
Valuation:	$0.00
Contractor Company:	
Contractor Name:	FISKE ELEC'L CONSTR. CORP

ADJOINING PROPERTY FINDINGS

433 41ST ST

Date:	**3/15/2002**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B224070
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A#1 UNIVERSAL ELEC'L INC

434 41ST ST

Date:	**4/20/1996**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B152259
Status:	CLOSED/CANCELLED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	TMF ELEC'L CONTR. INC.

ADJOINING PROPERTY FINDINGS

Date: **4/4/1996**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B151736
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: TMF ELEC'L CONTR. INC.

435 41ST ST

Date: **9/28/2007**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B296110
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: KJK ELECTRIC INC

ADJOINING PROPERTY FINDINGS

436 41ST ST

Date:	**9/19/1994**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B130843
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NELSON&TOM MAINTDBA TOMCO LAWRENCE NELSON

437 41ST ST

Date:	**6/29/1989**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B054652
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALL-NITE ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

438 41ST ST

Date:	**7/26/2013**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B370733
Status:	Closed
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RIVIERA ELECTRIC CORP

442 41ST ST

Date:	**2/10/1987**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B017555
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	1150 ELEC. DBA NOVA ELECT IVAN DUBBS

ADJOINING PROPERTY FINDINGS

444 41ST ST

Date:	**11/5/2021**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B006256021I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BERGER QUALITY ELEC'L CON

Date:	**11/2/2021**
Permit Type:	**EW**
Description:	**ROOFTOP SOLAR INSTALLATION. NO CHANGE TO USE, OCCUPANCY OR EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	340826002-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	KAMTECH RESTORATION CORP

ADJOINING PROPERTY FINDINGS

447 41ST ST

Date:	**8/6/2020**
Permit Type:	**EW**
Description:	**THIS PROJECT INCLUDES INSTALLING AN ELEVATED STEEL DECK AND STAIRS IN THE REAR YARD IN AN EXISTING 2 FAMILY BROWNSTONE HOUSE, AND ENLARGING AN EXISTING 1ST FLOOR WINDOW TO ACCESS THE DECK (STRUCTURAL WORK FOR DECK). NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	322001276-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CENTURY GENERAL CONTRACTI

Date:	**9/17/2009**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B320409
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RAINBOW ELECTRIC CO. INC

ADJOINING PROPERTY FINDINGS

449 41ST ST

Date:	**9/10/2006**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B282822
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A#1 UNIVERSAL ELEC'L INC

450 41ST ST

Date:	**8/8/2023**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00915551I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NAPSTAR ELECTRIC INC

ADJOINING PROPERTY FINDINGS

Date:	**4/9/2009**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B315226
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	GRAND ELECTRIC INC.

451 41ST ST

Date:	**11/12/2014**
Permit Type:	**EW**
Description:	**MINOR RENOVATION TO AN EXISTING THREE FAMILY. SKIM COATING AND PAINTING ALL WALLS, NEW FLOORING, NEW INTERIOR DOORS, AND NEW BASEBOARD MOLDINGS. NO CHANGE IN USE EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320834488-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BOUBACAR SOW

ADJOINING PROPERTY FINDINGS

452 41ST ST

Date: **12/11/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B311757
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: AL-ARM ELEC'L CONST.CORP

Date: **8/3/2007**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B293947
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: AL-ARM ELEC'L CONST.CORP

Date: **1/14/2004**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B248926
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: AL-ARM ELEC'L CONST.CORP

ADJOINING PROPERTY FINDINGS

Date: **1/31/1989**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B047969
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ENTERPRISE ELECT. CONTR

456 41ST ST

Date: **9/10/2016**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B416943
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: KNC ELECTRIC INC

Date: **4/20/2000**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B200568
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: NELSON&TOM MAINTDBA TOMCO LAWRENCE NELSON

ADJOINING PROPERTY FINDINGS

Date: **12/30/1999**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300859970-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CENTRAL DEVELOPMENT, CORP

Date: **12/30/1999**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300859970-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: MAGOR PLUMBING AND HEATING

Date: **1/10/1997**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B161556
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: AL-LECTRIC ELECT'L CONTRG

ADJOINING PROPERTY FINDINGS

Date: **2/28/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B096326
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: NU-WAY ELEC. CONTR'G

Date: **2/26/1992**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300153679-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: A R FUELS INC

Date: **2/26/1992**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FUEL BURNING
Permit Number: 300153679-01-EW-FB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: A R FUELS INC

ADJOINING PROPERTY FINDINGS

457 41ST ST

Date: **6/24/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B127882
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: MONTE ELECTRIC CO.

Date: **10/24/1988**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B044709
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: GSA ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

459 41ST ST

Date:	**6/24/2014**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	MINOR WORK
Proposed Use:	
Permit Number:	B382632
Status:	Closed
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RIVIERA ELECTRIC CORP

Date:	**10/28/2011**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320333144-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BOLTECH BLDG SOLUTIONS CO

Date:	**10/28/2011**
Permit Type:	**PL**
Description:	
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320333144-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ORION PLUMBING & HTG CORP

ADJOINING PROPERTY FINDINGS

Date: **1/15/1999**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B186251
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: RANDO ELEC'L CONTR'G INC

Date: **3/1/1990**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B065578
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: KEYSTONE ELECTRIC INC.

460 41ST ST

Date: **2/22/2013**
Permit Type: **PL**
Description: **REPLACE BOILER AND GAS/OIL BURNER (NYC BOILER NO. MD 22850-01).**

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 320121989-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: PAT SEMENTA P & H CO INC

ADJOINING PROPERTY FINDINGS

Date: **1/22/2010**
Permit Type: **EW**
Description: **REPLACE BOILER AND GAS/OIL BURNER (NYC BOILER NO. MD 22850-01).**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 320121989-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: DUOCOLONY FUEL CORP

Date: **1/22/2010**
Permit Type: **EW**
Description: **REPLACE BOILER AND GAS/OIL BURNER (NYC BOILER NO. MD 22850-01).**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FUEL BURNING
Permit Number: 320121989-01-EW-FB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: DUOCOLONY FUEL CORP

Date: **10/30/2009**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B321594
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: FIVE STAR ELEC'L CONTR'G

ADJOINING PROPERTY FINDINGS

Date:	**10/9/2008**
Permit Type:	**PL**
Description:	**INSTALL WEBSTER JB-1C-03 GAS/OIL BURNER AND CONNECT TO EXISTING CHIMNEY. NO CHANGE IN EGRESS USE OR OCCUPANCY IS INVOLVED UNDER THIS APPLICATION.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	310207503-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	DYNAMIC CONTRACTING CORP.

Date:	**10/8/2008**
Permit Type:	**EW**
Description:	**INSTALL WEBSTER JB-1C-03 GAS/OIL BURNER AND CONNECT TO EXISTING CHIMNEY. NO CHANGE IN EGRESS USE OR OCCUPANCY IS INVOLVED UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FUEL BURNING
Permit Number:	310207503-01-EW-FB
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BORO FUEL OIL CORP.

ADJOINING PROPERTY FINDINGS

Date: **3/15/2007**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B289658
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: NELSON&TOM MAINTDBA TOMCO LAWRENCE NELSON

Date: **2/23/2007**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B288217
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: DELTEX ELECTRICAL CONT.

Date: **11/6/2006**
Permit Type: **EW**
Description: **Filing to renovate apartments with partition work, doors, patchwork, and finishes as well as direct replacement of plumbing fixtures as per plans filed herewith. No change to use, egress, or occupancy under this application.**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 302243588-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: YUCO CONST CORP

ADJOINING PROPERTY FINDINGS

Date:	**6/7/2006**
Permit Type:	**EW**
Description:	**Masonry repairs repointing and replacment on front and rear facade as indicated on the drawings.No chage in use egress or occupancy**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	302163049-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	YUCO CONST CORP

Date:	**5/16/2006**
Permit Type:	**EQ**
Description:	**INSTALLATION OF 40 L.F. TEMPORARY SIDEWALK SHED FOR FACDAE REPAIR. NO CHANGE IN USES, EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	302160943-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MBR CONT INC

Date:	**6/1/1998**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B178643
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ATN ELECTRIC CORP

ADJOINING PROPERTY FINDINGS

Date: **5/22/1998**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B177843
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: ATN ELECTRIC CORP

Date: **5/27/1992**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300170669-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: EXPERT BOILER REPAIR & WELDING

Date: **5/27/1992**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FUEL BURNING
Permit Number: 300170669-01-EW-FB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: EXPERT BOILER REPAIR & WELDING

ADJOINING PROPERTY FINDINGS

461 41ST ST

Date:	**1/13/1992**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B094408
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	DIADEM ELECTRIC CORP.

463 41ST ST

Date:	**11/22/1983**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	K11316B
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	KAYAR ELEC'L CORP.

ADJOINING PROPERTY FINDINGS

464 41ST ST

Date:	**6/20/2017**
Permit Type:	**PL**
Description:	**INTERIOR RENOVATION OF APARTMENT 3R INCLUDING REMOVAL OF NON LOAD BEARING WALL SEPARATING THE KITCHEN AND LIVING ROOM. RELOCATION OF BEDROOM WALL AS PER PLANS. REPLACEMENT OF KITCHEN CABINETS, APPLIANCES AND PLUMBING FIXTURES. NO CHANGE TO USE, EGRESS AND OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321586164-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WNW & SONS PLUMBING & HTG

Date:	**5/31/2017**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION OF APARTMENT 3R INCLUDING REMOVAL OF NON LOAD BEARING WALL SEPARATING THE KITCHEN AND LIVING ROOM. RELOCATION OF BEDROOM WALL AS PER PLANS. REPLACEMENT OF KITCHEN CABINETS, APPLIANCES AND PLUMBING FIXTURES. NO CHANGE TO USE, EGRESS AND OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321586164-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	TIGER GENERAL CONTRACTOR

ADJOINING PROPERTY FINDINGS

Date: **3/24/2016**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B409120
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: B & S ELEC'L CONTR CO INC

Date: **3/16/2016**
Permit Type: **PL**
Description: **INTERIOR RENOVATION OF APARTMENTS R1, R2 & R3 APARTMENTS**

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 320522788-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WNW & SONS PLUMBING & HTG

Date: **7/6/2015**
Permit Type: **EW**
Description: **RENOVATION OF APARTMENT F1 AND THE BATHROOMS IN APARTMENT F2 & F3**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: MECHANICAL/HVAC
Permit Number: 320997579-01-EW-MH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: TIGER GENERAL CONTRACTOR

ADJOINING PROPERTY FINDINGS

Date:	**7/6/2015**
Permit Type:	**EW**
Description:	**RENOVATION OF APARTMENT F1 AND THE BATHROOMS IN APARTMENT F2 & F3**

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320997579-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	TIGER GENERAL CONTRACTOR

Date:	**7/6/2015**
Permit Type:	**PL**
Description:	**RENOVATION OF APARTMENT F1 AND THE BATHROOMS IN APARTMENT F2 & F3**

Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320997579-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WNW & SONS PLUMBING & HTG

Date:	**9/6/2012**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION OF APARTMENTS R1, R2 & R3 APARTMENTS**

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	320522788-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WNW & SONS PLUMBING & HEA

ADJOINING PROPERTY FINDINGS

Date:	**9/6/2012**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION OF APARTMENTS R1, R2 & R3 APARTMENTS**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320522788-01-EW-OT
Status:	RE-ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WNW & SONS PLUMBING & HEA

Date:	**10/10/2005**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B273308
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MAC ELECT'L CONTR. INC.

465 41ST ST

Date:	**9/20/2012**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B351370
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RENAISSANCE ELECTRIC CORP

ADJOINING PROPERTY FINDINGS

468 41ST ST

Date:	**7/27/2017**
Permit Type:	**PL**
Description:	**INTERIOR RENOVATION OF APARTMENT 1F INCLUDING REMOVAL OF NON LOAD BEARING WALL SEPARATING THE KITCHEN AND LIVING ROOM. RENOVATION OF DWELLING AS PER PLANS. REPLACEMENT OF KITCHEN CABINETS, RELOCATION OF APPLIANCES AND PLUMBING FIXTURES. NO CHANGE TO USE, EGRESS AND OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321587877-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WNW & SONS PLUMBING & HTG

Date:	**7/14/2017**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION OF APARTMENT 1F INCLUDING REMOVAL OF NON LOAD BEARING WALL SEPARATING THE KITCHEN AND LIVING ROOM. RENOVATION OF DWELLING AS PER PLANS. REPLACEMENT OF KITCHEN CABINETS, RELOCATION OF APPLIANCES AND PLUMBING FIXTURES. NO CHANGE TO USE, EGRESS AND OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321587877-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	TIGER GENERAL CONTRACTOR

ADJOINING PROPERTY FINDINGS

Date:	**3/24/2016**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B409125
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	B & S ELEC'L CONTR CO INC

Date:	**7/31/2014**
Permit Type:	**EW**
Description:	**THIS APPLICATION IS BEING PROFESSIONALLY CERTIFIED AND THIS APPLICATION IS BEING FILED FOR THE RENOVATION OF THE EXISTING SIX (6) BATHROOMS IN A SIX FAMILY DWELLING/ONE PER UNIT.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	320125967-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MODERN CONCEPTS RENOV INC

ADJOINING PROPERTY FINDINGS

Date:	**7/31/2014**
Permit Type:	**EW**
Description:	**THIS APPLICATION IS BEING PROFESSIONALLY CERTIFIED AND THIS APPLICATION IS BEING FILED FOR THE RENOVATION OF THE EXISTING SIX (6) BATHROOMS IN A SIX FAMILY DWELLING/ONE PER UNIT.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320125967-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MODERN CONCEPTS RENOV INC

Date:	**3/10/2010**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B324872
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	B & S ELEC'L CONTR

ADJOINING PROPERTY FINDINGS

Date:	**3/2/2010**
Permit Type:	**PL**
Description:	**THIS APPLICATION IS BEING PROFESSIONALLY CERTIFIED AND THIS APPLICATION IS BEING FILED FOR THE RENOVATION OF THE EXISTING SIX (6) BATHROOMS IN A SIX FAMILY DWELLING/ONE PER UNIT.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320125967-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WNW & SONS PLUMBING & HTG

Date:	**10/10/2005**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B273309
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MAC ELECT'L CONTR. INC.

ADJOINING PROPERTY FINDINGS

469 41ST ST

Date: **6/28/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B128140
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: S C ELECTRIC CORP.

Date: **6/6/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B128235
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: S C ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

471 41ST ST

Date:	**1/9/2014**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION ON CELLAR, BASEMENT, 1ST & 2ND FLOOR. FOR EXIST. TWO FAMILY DWELLING. NEW PARTITION WALL AND PLUMBING WORK INVOLVED. NO CHANGE TO USE, OCCUPANCY OR EGRESS.**

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320808667-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	FIRST STAR CONSTRUCTION I

Date:	**12/11/2013**
Permit Type:	
Description:	

Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B375563
Status:	Closed
Valuation:	$0.00
Contractor Company:	
Contractor Name:	POWER SURGE ELECTRIC INC

ADJOINING PROPERTY FINDINGS

Date:	**12/4/2013**
Permit Type:	**PL**
Description:	**INTERIOR RENOVATION ON CELLAR, BASEMENT, 1ST & 2ND FLOOR. FOR EXIST. TWO FAMILY DWELLING. NEW PARTITION WALL AND PLUMBING WORK INVOLVED. NO CHANGE TO USE, OCCUPANCY OR EGRESS.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320808667-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	C & T PLUMBING & HTG INC

472 41ST ST

Date:	**8/25/1989**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B056817
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WALSH ELEC'L CONTR'G INC

ADJOINING PROPERTY FINDINGS

Date: **5/2/1983**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K04200B
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: WALSH ELEC'L CONTR'G INC

475 41ST ST

Date: **9/21/2007**
Permit Type: **PL**
Description: **REPLACE OIL BURNER WITH GAS/OIL BURNER ON EXISTING LOW PRESSURE BOILER. INSTALL NEW GAS SERVICE. NO CHANGE IN EGRESS, OCCUPANCY OR USE UNDER THIS APPLICATION.**

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 310009424-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: AURORA P & H CONT INC

ADJOINING PROPERTY FINDINGS

Date:	**9/12/2007**
Permit Type:	**EW**
Description:	**REPLACE OIL BURNER WITH GAS/OIL BURNER ON EXISTING LOW PRESSURE BOILER. INSTALL NEW GAS SERVICE. NO CHANGE IN EGRESS, OCCUPANCY OR USE UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FUEL BURNING
Permit Number:	310009424-01-EW-FB
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	STUART N SCHWARTZ

Date:	**1/28/2002**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B222002
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALCO ELEC. CO. INC.

ADJOINING PROPERTY FINDINGS

42ND ST

339 42ND ST

Date: **6/16/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B003856
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ABRAHAM STERN

345 42ND ST

Date: **9/3/1985**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K22743
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: SUPERIOR ELEC. CONTR. LTD

ADJOINING PROPERTY FINDINGS

Date: **7/16/1984**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K07706
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: SUPERIOR ELEC. CONTR. LTD

347 42ND ST

Date: **9/28/2017**
Permit Type: **AL**
Description: **POINTING & PATCH WORK AS PER PLAN .NO CHANGE IN USE OCCUPANCY OR EGRESS UNDER THIS APPLICATION**

Permit Description: **ALTERATION**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use:
Permit Number: 340548679-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SHAH GROUP ENTERPRISES IN

ADJOINING PROPERTY FINDINGS

Date: **10/22/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B010357
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ALWON ELECTRIC CORP.

349 42ND ST

Date: **8/23/1990**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B072920
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: DONALD MCGEACHY INC.

ADJOINING PROPERTY FINDINGS

351 42ND ST

Date:	**5/17/2006**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B279234
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BLUE RIBBON ELEC'L CONTRS

356 42ND ST

Date:	**7/21/2017**
Permit Type:	**EW**
Description:	**INSTALL NEW LOW PRESS. HEATING BOILER & GAS BURNER FOR CHURCH. EXIST. BOILER SERVING CHURCH IN ADJOINING SCHOOL TO BE DISCONTINUED. REPLACE EXIST. GAS BOILER SERVING ADJOINING RECTORY. INSTALL NEW GAS METER AND PIPING. INSTALL NEW INDIRECT FIRED DOMESTIC HW HEATER/STORAGE TANK. NO CHANGE IN USE, EGRESS OR OCCUPANCY UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	321586002-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BONDEE ENTERPRISES INC

ADJOINING PROPERTY FINDINGS

Date:	**5/31/2017**
Permit Type:	**PL**
Description:	**INSTALL NEW LOW PRESS. HEATING BOILER & GAS BURNER FOR CHURCH. EXIST. BOILER SERVING CHURCH IN ADJOINING SCHOOL TO BE DISCONTINUED. REPLACE EXIST. GAS BOILER SERVING ADJOINING RECTORY. INSTALL NEW GAS METER AND PIPING. INSTALL NEW INDIRECT FIRED DOMESTIC HW HEATER/STORAGE TANK. NO CHANGE IN USE, EGRESS OR OCCUPANCY UNDER THIS APPLICATION.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321586002-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BONDEE ENTERPRISES INC

357 42ND ST

Date:	**7/29/2005**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B269981
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BLUE RIBBON ELEC'L CONTRS

ADJOINING PROPERTY FINDINGS

359 42ND ST

Date:	**3/22/1989**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B050765
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALWON ELECTRIC CORP.

361 42ND ST

Date:	**4/23/2016**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B410517
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RIVIERA ELECTRIC CORP

ADJOINING PROPERTY FINDINGS

363 42ND ST

Date:	**2/21/1986**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	K30741
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	KELLEHER ELECTRICIANS

365 42ND ST

Date:	**10/12/2016**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B418514
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RIVIERA ELECTRIC CORP

ADJOINING PROPERTY FINDINGS

Date: **8/15/2016**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B415692
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: RIVIERA ELECTRIC CORP

373 42ND ST

Date: **4/27/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00510903I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

Date: **8/28/2020**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00391136I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

ADJOINING PROPERTY FINDINGS

Date: **1/30/1998**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B174491
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: CITYWIDE ELEC'L CONTR'G

Date: **11/25/1996**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B160097
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: OLYMPIC ELECT WIRING CORP

Date: **12/4/1995**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B147625
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: OLYMPIC ELECT WIRING CORP

ADJOINING PROPERTY FINDINGS

375 42ND ST

Date: **3/2/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00464009S1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

Date: **2/26/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00476030I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

Date: **2/26/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00476032I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

ADJOINING PROPERTY FINDINGS

Date: **2/26/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00476033I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

Date: **2/3/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00464006I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

Date: **2/3/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00464008I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

ADJOINING PROPERTY FINDINGS

Date: **2/3/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00464009I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

Date: **2/2/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00463993I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

Date: **8/28/2020**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00391138I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

ADJOINING PROPERTY FINDINGS

Date:	**6/20/2016**
Permit Type:	**AL**
Description:	**FILING TO REMOVE AN ILLEGAL INTERIOR NON-BEARING PARTITION IN APT. 4H SO AS TO REMOVE VIOLATION. NO CHANGE TO OCCUPANCY, EGRESS OR OCCUPANCY UNDER THIS APPLICATION**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	340344924-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	METROTECH DEVELOPMENT COR

Date:	**10/19/2015**
Permit Type:	**AL**
Description:	**INSTALLATION OF TELECOMMUNICATION ANTENNA COMPONENTS ON THE ROOF. RETROFIT EXISTING EQUIPMENT CABINET ON THE ROOF. ALL WORK IS IN COMPLIANCE WITH TPPN 5/98. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	321122361-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SQUAN CONSTRUCTION SERVIC

ADJOINING PROPERTY FINDINGS

Date: **5/17/2013**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: MINOR WORK
Proposed Use:
Permit Number: B367687
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: J.A. LEE ELECTRIC INC.

Date: **5/16/2013**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: MINOR WORK
Proposed Use:
Permit Number: B367578
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: J.A. LEE ELECTRIC INC.

Date: **5/1/2013**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: MINOR WORK
Proposed Use:
Permit Number: B366971
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: J.A. LEE ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

Date: **1/5/2013**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B358614
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: J.A. LEE ELECTRIC INC.

Date: **5/12/2010**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B327160
Status: ASSIGNED TO INSPECTOR
Valuation: $0.00
Contractor Company:
Contractor Name: ASSOCIATED ELEC CONT

Date: **5/1/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B278039
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: TESTA ELECTRIC CO. INC

ADJOINING PROPERTY FINDINGS

Date: **4/27/2006**
Permit Type: **AL**
Description: **EST COST $25,000 INSTALLING TELECOMMUNICATIONS CABINETS WITH RELATED DUN NAGE & ANTENNAS ON ROOF IN CONFORMANCE WITH TPPN #5/98.NO CHANGE IN USE,EGRES OR OCC**

Permit Description: **ALTERATION**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use:
Permit Number: 302140975-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: DAVRIAL ENT INC

Date: **11/9/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B105914
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: IRWIN ELECTR'L CONTR'S

Date: **10/1/1989**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B058938
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: IRWIN ELECTR'L CONTR'S

ADJOINING PROPERTY FINDINGS

377 42ND ST

Date: **3/15/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00485127I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

Date: **3/15/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00485129I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

Date: **3/6/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00391140S1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

ADJOINING PROPERTY FINDINGS

Date: **8/28/2020**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00391140I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO., INC.

415 42ND ST

Date: **1/5/1990**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B062154
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: SRB ELEC'L CONTR'S INC.

Date: **11/29/1989**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B060857
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: SRB ELEC'L CONTR'S INC.

ADJOINING PROPERTY FINDINGS

417 42ND ST

Date: **1/12/2022**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00660326I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: BROOKYLN SOLARWORKS, LLC

Date: **12/4/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00641878I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: BROOKYLN SOLARWORKS, LLC

ADJOINING PROPERTY FINDINGS

Date:	**4/14/2021**
Permit Type:	**EW**
Description:	**INSTALL SOLAR PV SYSTEM ON THE EXISTING ROOFTOP. NO CHANGES TO USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	340809502-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BROOKLYN SOLARWORKS LLC

Date:	**6/15/2005**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B268268
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RELIANT ELEC'L CONT'G INC

ADJOINING PROPERTY FINDINGS

420 42ND ST

Date:	**11/13/2020**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	340699042-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	GOLDEN CONSTRUCTION NY CO

Date:	**5/8/2017**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION; NO CHANGE OF USE GROUP,EGRESS AND OCCUPANCY**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	340501059-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PONDOSA INC

ADJOINING PROPERTY FINDINGS

Date:	**10/29/2009**
Permit Type:	**AL**
Description:	**CORRECT EXISTING CURB CUT SIZE IN DOB RECORD TO MATCH AS BUILT. CHANGE THE CURB CUT WIDTH FROM 17 FEET TO 25 FEET. NO CHANGE IN USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	320053419-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	55C GROUP INC

Date:	**9/30/2009**
Permit Type:	**AL**
Description:	**CHANGE ACCESSORY 21 ATTENDANT PARKING SPACES TO 15 PARKING SPACES AT CELLAR. NO WORK TO BE DONE UNDER THIS APPLICATION.**
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	320046017-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	55C GROUP INC

ADJOINING PROPERTY FINDINGS

Date:	**5/8/2008**
Permit Type:	**EW**
Description:	**FILING FOR HVAC SYSTEM FRO TREATMENT HEALTH CARE IN CONJUNCTION WITH NB APPLICATION # 302245853. NO CHANGE IN USE, EGRESS OROCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	310136322-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	UNIVERSAL CONST. CONSULT. INC.

Date:	**1/7/2008**
Permit Type:	**NB**
Description:	
Permit Description:	**NEW BUILDING**
Work Class:	NB - NEW BUILDING
Proposed Use:	
Permit Number:	302245853-01-NB
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	UNIVERSAL CONSTR CONS INCNC

Date:	**12/28/2007**
Permit Type:	**EQ**
Description:	
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	NB - NEW BUILDING
Proposed Use:	FENCE
Permit Number:	302245853-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	UNIVERSAL CONSTR CONS INCNC

ADJOINING PROPERTY FINDINGS

Date:	**11/29/2007**
Permit Type:	**EW**
Description:	**Install sprinkler system in conjunction with NB application 302245853. No change in use, egress, or occupancy.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	SPRINKLER
Permit Number:	302377372-01-EW-SP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ORION PLUMBING & HEATING CORP.

Date:	**10/22/2007**
Permit Type:	**PL**
Description:	
Permit Description:	**PLUMBING**
Work Class:	NB - NEW BUILDING
Proposed Use:	
Permit Number:	302245853-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ORION

Date:	**10/9/2007**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B296315
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HI-RITE ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

Date: **2/5/2007**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B287408
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: HI-RITE ELECTRIC CORP.

421 42ND ST

Date: **11/4/2021**
Permit Type: **PL**
Description: **CONVERT EXISTING TWO FAMILY DWELLING TO THREE FAMILY DWELLING.**

Permit Description: **PLUMBING**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 310078974-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BIG APPLE SEWER & DRAIN I

Date: **4/28/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00511371I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: BLAZE ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

Date: **12/12/2008**
Permit Type: **AL**
Description: **CONVERT EXISTING TWO FAMILY DWELLING TO THREE FAMILY DWELLING.**

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 310078974-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: MINNOW ASSOCIATES LLC

Date: **12/12/2008**
Permit Type: **EQ**
Description: **CONVERT EXISTING TWO FAMILY DWELLING TO THREE FAMILY DWELLING.**

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use: FENCE
Permit Number: 310078974-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: MINNOW ASSOCIATES LLC

Date: **4/28/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B303574
Status: VIOLATN PENDING AT CONTRACTOR
Valuation: $0.00
Contractor Company:
Contractor Name: RM ELECTRIC CO. INC.

ADJOINING PROPERTY FINDINGS

Date: **2/25/1985**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K16208
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: THOMAS STANCO

425 42ND ST

Date: **3/9/2002**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B224602
Status: VIOLATN PENDING AT CONTRACTOR
Valuation: $0.00
Contractor Company:
Contractor Name: M.J. BARRAL ELECT. CO

ADJOINING PROPERTY FINDINGS

426 42ND ST

Date:	**12/28/2011**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B345817
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HI-RITE ELECTRIC CORP.

Date:	**12/5/2011**
Permit Type:	**EW**
Description:	**RENOVATION OF EXISTING 2 FAMILY BUILDING AT CEL, 1ST, 2ND AND ROOF FLOOR. REPLACE AND RELOCATE PLUMBING FIXTURES AT 1ST AND 2ND FLOOR. NO CHANGE IN USE EGRESS, AND OCCUPANCY UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320392197-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HIGH QUALITY CONSTRUCTION

ADJOINING PROPERTY FINDINGS

Date:	**12/5/2011**
Permit Type:	**PL**
Description:	**RENOVATION OF EXISTING 2 FAMILY BUILDING AT CEL, 1ST, 2ND AND ROOF FLOOR. REPLACE AND RELOCATE PLUMBING FIXTURES AT 1ST AND 2ND FLOOR. NO CHANGE IN USE EGRESS, AND OCCUPANCY UNDER THIS APPLICATION.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320392197-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	M. SPINELLI PLB & HTG INC

Date:	**10/4/1996**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B158411
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EMPIRE ELECT. CONTR'G INC

ADJOINING PROPERTY FINDINGS

Date: **10/31/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B011163
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CABIN ELECTRIC INC.

428 42ND ST

Date: **6/23/2014**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B382112
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: P.L. ELEC'L CONTR'G CORP

ADJOINING PROPERTY FINDINGS

429 42ND ST

Date:	**12/21/2010**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B334591
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	POWER SURGE ELECTRIC INC

Date:	**11/5/2010**
Permit Type:	**PL**
Description:	**REFURBISH EXISTING DWELLING UNITS. REPLACE PLUMBING FIXTURES ON EACH FLOOR, POLISH EXISTING WOOD FLOORING. REPLACE NEW TILES IN KITCHEN AREA ON FIRST (1ST) AND SECOND (2ND) FLOOR REPLACE ONE (1) BOILER AND TWO (2) HOT WATER HEATER. NO CHANGE IN USE, OCCUPANCY AND EGRESS.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320227875-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CREO MECHANICAL INC

ADJOINING PROPERTY FINDINGS

Date:	**10/15/2010**
Permit Type:	**EQ**
Description:	**REFURBISH EXISTING DWELLING UNITS. REPLACE PLUMBING FIXTURES ON EACH FLOOR, POLISH EXISTING WOOD FLOORING. REPLACE NEW TILES IN KITCHEN AREA ON FIRST (1ST) AND SECOND (2ND) FLOOR REPLACE ONE (1) BOILER AND TWO (2) HOT WATER HEATER. NO CHANGE IN USE, OCCUPANCY AND EGRESS.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FENCE
Permit Number:	320227875-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EMPRISE CONSTRUCTION INC

Date:	**10/15/2010**
Permit Type:	**EW**
Description:	**REFURBISH EXISTING DWELLING UNITS. REPLACE PLUMBING FIXTURES ON EACH FLOOR, POLISH EXISTING WOOD FLOORING. REPLACE NEW TILES IN KITCHEN AREA ON FIRST (1ST) AND SECOND (2ND) FLOOR REPLACE ONE (1) BOILER AND TWO (2) HOT WATER HEATER. NO CHANGE IN USE, OCCUPANCY AND EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320227875-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EMPRISE CONSTRUCTION INC

ADJOINING PROPERTY FINDINGS

430 42ND ST

Date:	**6/13/2005**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B268521
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	THROOP ELECTRIC CO. INC.

Date:	**6/1/2005**
Permit Type:	**PL**
Description:	**Proposed minor partition work and new plumbing fixtures in basement floor as indicated on plans. New windows and doors as per plans. No change in bulk, occupancy or egress.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	301920713-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	E.Z. RUNNER CONSTRUCTION CORP.

ADJOINING PROPERTY FINDINGS

Date:	**4/19/2005**
Permit Type:	**EW**
Description:	**Proposed minor partition work and new plumbing fixtures in basement floor as indicated on plans. New windows and doors as per plans. No change in bulk, occupancy or egress.**

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301920713-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EUROPEAN BUILDERS & CONT

441 42ND ST

Date:	**9/12/2012**
Permit Type:	**PL**
Description:	**LEGALIZATION OF THE CONVERSION OF A TWO FAMILY DWELLING INTO A THREE FAMILY DWELLING.**

Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	310002092-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	FIRST CHOICE PL CORP

ADJOINING PROPERTY FINDINGS

Date: **11/28/2011**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B344795
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: TMF ELEC'L CONTR. INC.

Date: **12/10/2009**
Permit Type: **AL**
Description: **LEGALIZATION OF THE CONVERSION OF A TWO FAMILY DWELLING INTO A THREE FAMILY DWELLING.**

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 310002092-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: N Y GENESIS BUILDERS CORP

Date: **11/16/2009**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B322109
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: WOODLAND ELEC'L CONTG COR

ADJOINING PROPERTY FINDINGS

449 42ND ST

Date: **9/19/1991**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300106579-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: DURNEY MECHANICAL

Date: **9/19/1991**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300106579-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: DURNEY MECHANICAL

Date: **1/25/1988**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B032443
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ALWON ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

4TH AVE

1004 4TH AVE

Date:	**5/20/2022**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00741689I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	TRIPLE D ELECTRIC INC

Date:	**3/23/2009**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B314624
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NEW GRAND ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

Date: **3/9/2009**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B314146
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: NEW GRAND ELECTRIC INC.

Date: **3/9/2009**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B314147
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: NEW GRAND ELECTRIC INC.

Date: **8/30/2007**
Permit Type: **PL**
Description: **APPLICATION FILED TO MODIFY EXISTING SPRINKLER SYSTEM APPROVED UNDER JOB # SPR 549-88, TO WORK IN CONJUNCTION WITH APPLICATION #302158359. NO CHANGE IN USE, OCCUPANCY OR EGRESS.**

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 302377906-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: THE PLUMBING COMPANY INC

ADJOINING PROPERTY FINDINGS

Date:	**8/15/2007**
Permit Type:	**EW**
Description:	**TO INSTALL NEW FIRE SUPPRESSION SYSTEM SHOT-OFF VALVE FILED IN A SEPATATED APPLICATION. NO CHANGE IN USE, OCCUPANCY OR EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FIRE SUPPRESSION
Permit Number:	302384961-01-EW-FP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NEW YORK BUSINESS FIRE SYSTEM IN

Date:	**7/24/2007**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B293684
Status:	CLOSED/CANCELLED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	UL ELECTRICAL CORP.

ADJOINING PROPERTY FINDINGS

3901 4TH AVE

Date:	**7/2/2015**
Permit Type:	**EW**
Description:	**FILING FOR REPLACING CONDENSER UNITS ON ROOF FOR 1ST FLOOR COMMERCIAL SPACE.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	321153746-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HASSAN CHANNAOUI

Date:	**5/21/2015**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	
Proposed Use:	
Permit Number:	B396065
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date: **5/21/2015**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: B396067
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name:

Date: **12/16/2014**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 321046113-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SIGNSTAR NYC

Date: **12/15/2014**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 321046122-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SIGNSTAR NYC

ADJOINING PROPERTY FINDINGS

Date: **11/26/2013**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: MINOR WORK
Proposed Use:
Permit Number: B375120
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: ELECTROTEC OF NY ELECL IN

Date: **10/4/1999**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 300940720-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTH SHORE NEON SIGN CO., INC.

Date: **10/4/1999**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 300940739-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTH SHORE NEON SIGN CO., INC.

ADJOINING PROPERTY FINDINGS

Date: **9/27/1999**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300930269-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: STELLMAR PLUMBING & MECHANICAL C

Date: **9/9/1999**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B193036
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

Date: **9/9/1999**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B193037
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

ADJOINING PROPERTY FINDINGS

Date: **9/9/1999**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B193038
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: CITY ELEC'L SIGN ERECTORS

Date: **9/1/1999**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: MECHANICAL/HVAC
Permit Number: 300930269-01-EW-MH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: HI-TECH CONST GC

Date: **9/1/1999**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300930269-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: HI-TECH CONST GC

ADJOINING PROPERTY FINDINGS

Date: **9/12/1996**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B157531
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A#1 UNIVERSAL ELEC'L INC

Date: **3/3/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FIRE SUPPRESSION
Permit Number: 300418787-01-EW-FP
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: MASTER FIRE PREVENTION INC.

Date: **10/24/1991**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FIRE SUPPRESSION
Permit Number: 300124238-01-EW-FP
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: ACTIVE FIRE EXTING.CO

ADJOINING PROPERTY FINDINGS

3902 4TH AVE

Date: **11/2/2020**
Permit Type:
Description:

Permit Description: **Sign Permit**
Work Class:
Proposed Use:
Permit Number: B00386304I1SG
Status: Signed Off
Valuation: $0.00
Contractor Company:
Contractor Name: AMA SIGN AND ELECTRIC CO

Date: **1/28/2011**
Permit Type: **NB**
Description:

Permit Description: **NEW BUILDING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 301440251-01-NB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CHINA PEFECT CONSTR CORP

Date: **9/2/2010**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 301440251-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CREO MECHANICAL INC

ADJOINING PROPERTY FINDINGS

Date: **6/2/2010**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B327619
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: A.T. ELEC'L CONTR'G INC

Date: **1/28/2010**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: NB - NEW BUILDING
Proposed Use: FENCE
Permit Number: 301440251-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CHINA PEFECT CONSTR CORP

Date: **3/19/2004**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: DM - FULL DEMOLITION
Proposed Use: FENCE
Permit Number: 301773515-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SAL ANDREW CONTRACTING CO

ADJOINING PROPERTY FINDINGS

Date: **3/19/2004**
Permit Type: **DM**
Description:

Permit Description: **DEMOLITION & REMOVAL**
Work Class: DM - FULL DEMOLITION
Proposed Use:
Permit Number: 301773515-01-DM
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SAL ANDREW CONTRACTING CO

Date: **1/22/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K29464
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: S. BROWN & SON INC.

ADJOINING PROPERTY FINDINGS

3907 4TH AVE

Date:	**3/14/2018**
Permit Type:	**EW**
Description:	**DIRECT REPLACEMENT OF EXISTING AIR CONDITIONING UNIT ON ROOF ON EXISTING DUNNAGE. NO CHANGE IN EGRESS, USE OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	321734548-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BLIZZARD COOLING INC

Date:	**11/3/2004**
Permit Type:	**PL**
Description:	**Renovate existing commercial building for new physical therapy clinic. Install new gypsum partitions, plumbing fixtures for h/c accessible bathroom and finishes throughout. Obtain new C/O at conclusion of work. No change to fire-protection under this application. Change to egress, occupancy, and use. Mechanical work to be filed under seperate application**
Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	301744094-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JOHN BRETONE PLUMBING HEATING

ADJOINING PROPERTY FINDINGS

Date:	**10/25/2004**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B261605
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EUGENE IOVINE INC.

Date:	**9/9/2004**
Permit Type:	**AL**
Description:	**Renovate existing commercial building for new physical therapy clinic. Install new gypsum partitions, plumbing fixtures for h/c accessible bathroom and finishes throughout. Obtain new C/O at conclusion of work. No change to fire-protection under this application. Change to egress, occupancy, and use. Mechanical work to be filed under seperate application**
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	301744094-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ARIS CONSTRUCTION COMPANY

ADJOINING PROPERTY FINDINGS

Date:	**7/28/2004**
Permit Type:	**EW**
Description:	**INSTALLATION OF AIR CONDITIONING UNIT IN CONJUNCTION WITH ALTERATION APPLICATION #301744094. NO CHANGE IN USE, EGRESS OR OCCUPANCY UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	301781793-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CONSOLIDATED COMFORT INC

Date:	**6/2/1989**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B053829
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	OLYMPIC ELECT WIRING CORP

ADJOINING PROPERTY FINDINGS

3908 4TH AVE

Date: **3/20/2013**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B364757
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: HECMAR ELECTRIC

Date: **8/27/2012**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300722350-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: PFEIFFER P,HTG,SPKL CONT

Date: **3/1/2011**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300722350-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CONSTR. POPULAR

ADJOINING PROPERTY FINDINGS

Date:	**8/2/2001**
Permit Type:	**EQ**
Description:	**New tiling of Street facade. No change in use, egress or occupancy.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FENCE
Permit Number:	301221808-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	LICKY K CONTRACTING CO

Date:	**8/2/2001**
Permit Type:	**EW**
Description:	**New tiling of Street facade. No change in use, egress or occupancy.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301221808-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	LICKY K CONTRACTING CO

Date:	**1/13/1999**
Permit Type:	**PL**
Description:	
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	300819434-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MAINLAND PLUMBING & HEATING

ADJOINING PROPERTY FINDINGS

Date: **12/21/1998**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: MECHANICAL/HVAC
Permit Number: 300819434-01-EW-MH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: ALL TECHNICAL ART

Date: **12/21/1998**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300819434-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: ALL TECHNICAL ART

Date: **12/29/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B121257
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: JIM ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

Date: **5/21/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B113067
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: JIM ELECTRIC CORP.

Date: **12/15/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B106984
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: JIM ELECTRIC CORP.

Date: **5/27/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B099612
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: JIM ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

Date:	**12/30/1991**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B093824
Status:	ADMINISTRATIVELY CLOSED (MINOR WORK)
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JIM ELECTRIC CORP.

3910 4TH AVE

Date:	**10/4/2004**
Permit Type:	**EW**
Description:	**INSTALL PLUMBING FIXTURES, COOKING EQUITMENTS AND FINISHES FOR AND EXISTING STORE ON FIRST FLOOR. NO CHANGE IN USE, EGRESS OR OCCUPANCY UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FIRE SUPPRESSION
Permit Number:	301779127-01-EW-FP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	N Y BUSINESS FIRE SYSTEM INC

ADJOINING PROPERTY FINDINGS

Date:	**9/9/2004**
Permit Type:	**PL**
Description:	**INSTALL PLUMBING FIXTURES, COOKING EQUITMENTS AND FINISHES FOR AND EXISTING STORE ON FIRST FLOOR. NO CHANGE IN USE, EGRESS OR OCCUPANCY UNDER THIS APPLICATION.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	301779127-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	C2 PLBG CORP

Date:	**8/11/2004**
Permit Type:	**EW**
Description:	**INSTALL PLUMBING FIXTURES, COOKING EQUITMENTS AND FINISHES FOR AND EXISTING STORE ON FIRST FLOOR. NO CHANGE IN USE, EGRESS OR OCCUPANCY UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	301779127-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NEW EMPIRE CONSTRUCTION

ADJOINING PROPERTY FINDINGS

Date:	**8/11/2004**
Permit Type:	**EW**
Description:	**INSTALL PLUMBING FIXTURES, COOKING EQUITMENTS AND FINISHES FOR AND EXISTING STORE ON FIRST FLOOR. NO CHANGE IN USE, EGRESS OR OCCUPANCY UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301779127-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NEW EMPIRE CONSTRUCTION

Date:	**4/22/2004**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B252072
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A.T. ELEC'L CONTR'G INC

Date:	**7/27/1998**
Permit Type:	**PL**
Description:	
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	300693195-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ALL ABOVE PLUMBING & HAETING

ADJOINING PROPERTY FINDINGS

Date: **3/10/1998**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300693195-01-EW-BL
Status: RE-ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: ALL ABOUT PLUMBING & HEATING

Date: **1/6/1984**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K00395
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: S. A. RANKIN ELEC. CO.

3913 4TH AVE

Date: **8/31/2015**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: B400366
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

3914 4TH AVE

Date:	**11/30/2006**
Permit Type:	**AL**
Description:	**ERECT A STEEL CANOPY IN REAR YARD. NO CHANGE TO USE,EGRESS OR OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	302246399-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HW CONST CORP

3917 4TH AVE

Date:	**4/22/2013**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FIRE SUPPRESSION
Permit Number:	320448734-01-EW-FP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ACTIVE FIRE CONTROL, INC

ADJOINING PROPERTY FINDINGS

Date:	**11/7/2012**
Permit Type:	**PL**
Description:	**REFURBISH EXISTING COMM SPACE U.G. # 6 AS PER PLANS; MINOR PARTITION WORK, INSTALL COOKING EQUIPMENT, HOOD AND DUCT, FIRE SUPPRESSION SYSTEM TO BE FILED UNDER SEPARATE APPLICATION, PLASTER AND PAINT TO MATCH EXISTING. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320450677-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	R. BARONE PLUMBING

Date:	**5/1/2012**
Permit Type:	**EW**
Description:	**REFURBISH EXISTING COMM SPACE U.G. # 6 AS PER PLANS; MINOR PARTITION WORK, INSTALL COOKING EQUIPMENT, HOOD AND DUCT, FIRE SUPPRESSION SYSTEM TO BE FILED UNDER SEPARATE APPLICATION, PLASTER AND PAINT TO MATCH EXISTING. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	320450677-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AIR EXTREME INC

ADJOINING PROPERTY FINDINGS

Date:	**5/1/2012**
Permit Type:	**EW**
Description:	**REFURBISH EXISTING COMM SPACE U.G. # 6 AS PER PLANS; MINOR PARTITION WORK, INSTALL COOKING EQUIPMENT, HOOD AND DUCT, FIRE SUPPRESSION SYSTEM TO BE FILED UNDER SEPARATE APPLICATION, PLASTER AND PAINT TO MATCH EXISTING. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320450677-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AIR EXTREME INC

Date:	**6/1/2007**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B291202
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SCHWIMMER ELEC'L SVC CORP

ADJOINING PROPERTY FINDINGS

Date:	**1/16/2007**
Permit Type:	**PL**
Description:	**THIS APPLICATION IS FILED TO PROPOSE INTERIOR RENOVATION AND PLUMBING WORK TO EXISTING THREE STORY BUILDING. NO CHANGE TO USE, EGRESS, OR OCCUPANCY FILED UNDER THIS APPLICAITON.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	302272332-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	VALUE PLUMBING, INC.

Date:	**1/12/2007**
Permit Type:	**EW**
Description:	**THIS APPLICATION IS FILED TO PROPOSE INTERIOR RENOVATION AND PLUMBING WORK TO EXISTING THREE STORY BUILDING. NO CHANGE TO USE, EGRESS, OR OCCUPANCY FILED UNDER THIS APPLICAITON.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	302272332-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	UNIVERSAL CONST & BUILDERS INC

ADJOINING PROPERTY FINDINGS

3918 4TH AVE

Date:	**2/18/2021**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	340760876-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EG ENTERPRISES NY INC

Date:	**7/16/2013**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	UN-TAGGED SIGN
Proposed Use:	
Permit Number:	B369808
Status:	Open
Valuation:	$0.00
Contractor Company:	
Contractor Name:	P.L. ELEC'L CONTR'G CORP

Date:	**7/16/2013**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	UN-TAGGED SIGN
Proposed Use:	
Permit Number:	B369811
Status:	Open
Valuation:	$0.00
Contractor Company:	
Contractor Name:	P.L. ELEC'L CONTR'G CORP

ADJOINING PROPERTY FINDINGS

Date: **5/24/2013**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 320757310-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NEPTUNE SIGNS&AWNINGS INC

Date: **5/24/2013**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 320757338-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NEPTUNE SIGNS&AWNINGS INC

Date: **7/7/2009**
Permit Type: **EW**
Description: **FIRST FLOOR: REMOVE NON-LOAD BEARING PARTITIONS AND RELOCATE EXISTING TOILET INSTALL NON LOAD BEARING PARTITIONS AND HEATING/COOLING EQUIPMENT. NO CHANGE TO USE, EGRESS OR OCCUPANCY.**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: MECHANICAL/HVAC
Permit Number: 310162454-01-EW-MH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: AIR MASTERS INC

ADJOINING PROPERTY FINDINGS

Date:	**2/12/2009**
Permit Type:	**PL**
Description:	**FIRST FLOOR: REMOVE NON-LOAD BEARING PARTITIONS AND RELOCATE EXISTING TOILET INSTALL NON LOAD BEARING PARTITIONS AND HEATING/COOLING EQUIPMENT. NO CHANGE TO USE, EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	310162454-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WATER WORKS MECH'LS LTD

Date:	**2/4/2009**
Permit Type:	**EW**
Description:	**FIRST FLOOR: REMOVE NON-LOAD BEARING PARTITIONS AND RELOCATE EXISTING TOILET INSTALL NON LOAD BEARING PARTITIONS AND HEATING/COOLING EQUIPMENT. NO CHANGE TO USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	310162454-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RITE WAY WOODCRAFTS, INC

ADJOINING PROPERTY FINDINGS

Date: **1/6/2009**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B312382
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: MAC ELECT'L CONTR. INC.

Date: **4/18/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B001807
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: PRO ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

3919 4TH AVE

Date:	**7/25/2017**
Permit Type:	**EW**
Description:	**RENOVATE EXISTING APARTMENT WITH REMOVAL OF PARTITION WALLS, REFINISHING WALLS, FLOOR, CEILING AND REPLACE PLUMBING FIXTURES AS PER PLAN. NO CHANGE IN EGRESS, OCCUPANCY OR USE IS INVOLVED UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321521938-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	360 INTERIOR CONCEPT HOLD

Date:	**4/17/2017**
Permit Type:	**PL**
Description:	**RENOVATE EXISTING APARTMENT WITH REMOVAL OF PARTITION WALLS, REFINISHING WALLS, FLOOR, CEILING AND REPLACE PLUMBING FIXTURES AS PER PLAN. NO CHANGE IN EGRESS, OCCUPANCY OR USE IS INVOLVED UNDER THIS APPLICATION.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321521938-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	KIN CHI PLBG AND HTG CORP

ADJOINING PROPERTY FINDINGS

Date:	**3/16/2006**
Permit Type:	**EW**
Description:	**INSTAL NEW ANSUL SYSTEM (THE PLUMBING IS FILED UNDER APPLICATION 302055433). NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FIRE SUPPRESSION
Permit Number:	302091643-01-EW-FP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NEW YORK BUSINESS FIRE SYS INC

Date:	**1/6/2006**
Permit Type:	**PL**
Description:	**INSTALLATION OF COOKING EQUIPMENTS AND ONE NEW GAS METER. THIS APPLICATION IS FILED IN CONJUNCTION WITH JOB#301954035. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	302055433-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	B.H.PLBG & HTG CORP

ADJOINING PROPERTY FINDINGS

Date:	**6/27/2005**
Permit Type:	**EW**
Description:	**RENOVATION OF AN EXISTING STORE. INSTALL FLOOR TILES AND REPLACE SUSPENDED CEILING TILES. THERE IS NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	301954035-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BIZENTI CONST CORP

3921 4TH AVE

Date:	**3/10/2000**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B199863
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CITYWIDE ELEC'L CONTR'G

ADJOINING PROPERTY FINDINGS

4004 4TH AVE

Date:	**10/19/2023**
Permit Type:	**PL**
Description:	
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	302585600-02-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	FORSYTHE P&H CORP

Date:	**9/28/2023**
Permit Type:	**EW**
Description:	**K136 - FILING HEREWITH ARCHITECTURAL MODIFICATIONS FOR PARAPET, FACE BRICK, LINTELS AND ROOF REPLACEMENT; REPAIR OF ENTRANCE STEPS, SPANDRELS AND COLUMNS; REPOINTING; WINDOW GUARD INSTALLATION; INJECTION GROUTING; WATERPROOFING; VARIOUS COATINGS AND INTERIOR FINISHES. NO CHANGE OF USE, OCCUPANCY OR EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	302585600-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	J & N CONSTRUCTION GROUP

ADJOINING PROPERTY FINDINGS

Date:	**12/8/2022**
Permit Type:	**EQ**
Description:	**SH/IS136K - FOR TEMPORARY CONSTRUCTION EQUIPMENT (1,207 FEET OF SHED) SUBMITTING ON BEHALF OF CONTRACTOR, IN CONJUNCTION WITH DOB JOB #302585600. NO CHANGE IN USE, OCCUPANCY OR EGRESS.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	322048592-01-EQ-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	J & N CONSTRUCTION GROUP

Date:	**11/28/2022**
Permit Type:	**EW**
Description:	**THE WORK CONSISTS OF REPLACING IN KIND (2)VENT PIPES, REPAIRING JOINTS IN STAIR, INSTALLING A PROPERTY LINE BOX, INSTALL A CONCRETE HOUSEKEEPING PADS, AND REMOVING (2) SPRINKLER HEADS IN ELECTRIC ROOM.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	SPRINKLER
Permit Number:	302578173-01-EW-SP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EAGLE MECHANICAL INC

ADJOINING PROPERTY FINDINGS

Date:	**7/29/2022**
Permit Type:	**EW**
Description:	**THE WORK CONSISTS OF REPLACING IN KIND (2)VENT PIPES, REPAIRING JOINTS IN STAIR, INSTALLING A PROPERTY LINE BOX, INSTALL A CONCRETE HOUSEKEEPING PADS, AND REMOVING (2) SPRINKLER HEADS IN ELECTRIC ROOM.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	302578173-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RODEL ELECTRICAL CONTR IN

Date:	**7/29/2022**
Permit Type:	**EW**
Description:	**SOE/IS136K - FILING ON BEHALF OF CONTRACTOR FOR INSTALLATION OF TEMPORARY SHORING OF EXCAVATION. IN CONJUNCTION WITH DOB 302585600. NO CHANGE IN USE, OCCUPANCY OR EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	322048618-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	J & N CONSTRUCTION GROUP

ADJOINING PROPERTY FINDINGS

Date:	**7/28/2022**
Permit Type:	**EQ**
Description:	**FN/PS136K - FOR TEMPORARY CONSTRUCTION EQUIPMENT (FENCE) SUBMITTING ON BEHALF OF CONTRACTOR, IN CONJUNCTION WITH DOB JOB #302578173 (REPLACE VENT PIPING & CONCRETE REPAIR). NO CHANGE IN USE, OCCUPANCY OR EGRESS**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	302584898-01-EQ-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RODEL ELECTRICAL CONTR IN

Date:	**7/19/2022**
Permit Type:	**EW**
Description:	**THE WORK CONSISTS OF REPLACING IN KIND (2)VENT PIPES, REPAIRING JOINTS IN STAIR, INSTALLING A PROPERTY LINE BOX, INSTALL A CONCRETE HOUSEKEEPING PADS, AND REMOVING (2) SPRINKLER HEADS IN ELECTRIC ROOM.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	302578173-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CHAPMAN & EVANS INC

ADJOINING PROPERTY FINDINGS

Date:	**11/12/2021**
Permit Type:	**EQ**
Description:	**FN/IS136K - FOR TEMPORARY CONSTRUCTION EQUIPMENT (FENCE) SUBMITTING ON BEHALF OF CONTRACTOR, IN CONJUNCTION WITH DOB JOB #302585600 & DOB JOB#322048618. NO CHANGE IN USE, OCCUPANCY OR EGRESS**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	322048645-01-EQ-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	J & N CONSTRUCTION GROUP

Date:	**11/12/2021**
Permit Type:	**EQ**
Description:	**SF/IS136K - FOR TEMPORARY CONSTRUCTION EQUIPMENT (SCAFFOLD) SUBMITTING ON BEHALF OF CONTRACTOR, IN CONJUNCTION WITH DOB JOB #302585600. NO CHANGE IN USE, OCCUPANCY OR EGRESS**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	322048583-01-EQ-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	J & N CONSTRUCTION GROUP

ADJOINING PROPERTY FINDINGS

Date:	**11/10/2021**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	302585600-03-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CHAPMAN & EVANS INC

Date:	**12/10/2020**
Permit Type:	**EW**
Description:	**REPLACING 2 EXISTING BLEACHERS, 1 EXISTING DF AND 1 CUSPIDOR W/ 2 BI-LEVEL DF (ONE WITH BOTTLE FILLER), A PART OF EXISTING HARDWOOD FLOORING, REFINISHING ENTIRE EXISTING HARDWOOD FLOOR, AND REPAIRING EXISTING WALL AT GYMNASIUM.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	302579458-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	LAWRENCE'S CONTRACTOR,INC

ADJOINING PROPERTY FINDINGS

Date:	**7/29/2019**
Permit Type:	**EQ**
Description:	**SH/IS136K - FOR TEMPORARY CONSTRUCTION EQUIPMENT (574 FT OF SHED) SUBMITTING ON BEHALF OF CONTRACTOR, IN CONJUNCTION WITH LLW # 114692 (EMERGENCY PROTECTION). NO CHANGE IN USE, OCCUPANCY OR EGRESS**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321068376-01-EQ-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ADAM'S EUROPEAN CONTRACTI

Date:	**1/4/2019**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00115709I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HIGH VOLT ELEC CORP. OF

ADJOINING PROPERTY FINDINGS

Date: **11/14/2018**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00099744I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: SAMCO ELECTRIC CORPORATION

Date: **8/27/2018**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00074445I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: RODEL ELECTRICAL CONTRACTORS, INC

Date: **6/22/2018**
Permit Type: **PL**
Description: **REMOVE AND REPLACE (4) EXISTING DOMESTIC WATER AND INSTALL (3) NEW DOMESTIC WATER SERVICES. REMOVE AND REPLACE (1) FIRE/SPRINKLER SERVICE. PROVIDE (3) NEW RPZ,**

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 302570858-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: VITAL PLUMBING,INC

ADJOINING PROPERTY FINDINGS

Date:	**12/6/2016**
Permit Type:	**PL**
Description:	**REPLACING 2 EXISTING BLEACHERS, 1 EXISTING DF AND 1 CUSPIDOR W/ 2 BI-LEVEL DF (ONE WITH BOTTLE FILLER), A PART OF EXISTING HARDWOOD FLOORING, REFINISHING ENTIRE EXISTING HARDWOOD FLOOR, AND REPAIRING EXISTING WALL AT GYMNASIUM.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	302579458-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ROBERT PARCHMENT P&H.INC

Date:	**9/26/2016**
Permit Type:	**EW**
Description:	**PS 136K- PROVIDE CONCRETE PADS FOR EQUIPMENT. PROVIDE CONCRETE WORK FOR FENCE. PROVIDE LADDER AND FENCE.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	302570858-02-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	UNISYS ELECTRIC, INC

ADJOINING PROPERTY FINDINGS

Date:	**6/22/2012**
Permit Type:	**EW**
Description:	**IS136K: REPLACEMENT OF ASPHALTIC CONCRETE AND CONCRETE WALKWAYS, REPAIR TO CONCRETE STEPS, WALLS AND CURBS, INSTALLATION OF BASKETBALL COURT AND HOOPS,**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	302560155-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PMY CONSTRUCTION CORP

Date:	**5/16/2012**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B350060
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A & S ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

Date:	**4/19/2012**
Permit Type:	**EQ**
Description:	**INSTALLATION OF TEMP. CONSTRUCTION FENCE TO FACILITATE THE ONGOING RENOVATION WORK. NO CHANGE IN USE, EGRESS AND OCCUPANCY**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	FENCE
Permit Number:	302565105-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PMY CONSTRUCTION CORP

Date:	**1/26/2011**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B335450
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A & S ELECTRIC INC.

Date:	**2/4/2010**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B324244
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A & S ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

Date: **1/14/2010**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B323596
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: E.N.E.L. ELECTRICAL CORP

Date: **1/13/2010**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B323629
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: A & S ELECTRIC INC.

Date: **11/25/2009**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B322488
Status: ASSIGNED TO INSPECTOR
Valuation: $0.00
Contractor Company:
Contractor Name: BOBTEK ELECTRICAL CORP.

ADJOINING PROPERTY FINDINGS

Date: **9/1/2004**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B258053
Status: ADMINISTRATIVELY CLOSED (MINOR WORK)
Valuation: $0.00
Contractor Company:
Contractor Name: PEGASUS ELECTRICAL CORP.

Date: **10/20/1999**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 301060063-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: STONEWALL CONTRACTING CORP.

Date: **10/21/1988**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B044820
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: KELLEHER ELECTRICIANS

ADJOINING PROPERTY FINDINGS

4013 4TH AVE

Date: **7/28/2015**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: B170237
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name:

Date: **7/14/2015**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300508065-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: VC CONSTRUCTION CO

Date: **12/9/2014**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B389657
Status: Open
Valuation: $0.00
Contractor Company:
Contractor Name: ELECTROTEC OF NY ELECL IN

ADJOINING PROPERTY FINDINGS

Date: **6/13/2014**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300541297-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: PROFESSIONAL PLBG & HTG CORP

Date: **6/4/2013**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: UN-TAGGED SIGN
Proposed Use:
Permit Number: B368992
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: STAT ELECTRIC INC.

Date: **6/4/2013**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: UN-TAGGED SIGN
Proposed Use:
Permit Number: B368993
Status: Closed
Valuation: $0.00
Contractor Company:
Contractor Name: STAT ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

Date: **4/24/2013**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 320739652-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: PAUL SIGNS, INC

Date: **4/24/2013**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 320739661-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: PAUL SIGNS, INC

Date: **9/4/2012**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300541297-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SPINNER INDUSTRIAL

ADJOINING PROPERTY FINDINGS

Date: **1/26/2012**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300508065-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SILVER STAR PLBG & HTG IN

Date: **1/24/2005**
Permit Type: **EW**
Description: **OBTAIN EQUIPMENT USE PERMIT FOR ROOFTOP UNIT.**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: MECHANICAL/HVAC
Permit Number: 301870232-01-EW-MH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name:

Date: **7/15/1997**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B167724
Status: VIOLATN PENDING AT CONTRACTOR
Valuation: $0.00
Contractor Company:
Contractor Name: TESTA ELECTRIC CO. INC

ADJOINING PROPERTY FINDINGS

Date: **9/6/1996**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: MECHANICAL/HVAC
Permit Number: 300541297-01-EW-MH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: SPINNER INDUSTRIAL

4101 4TH AVE

Date: **1/22/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00457900I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: SIGNS CAD CORP

Date: **1/22/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00457988I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: SIGNS CAD CORP

ADJOINING PROPERTY FINDINGS

Date: **1/21/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00457564I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: SIGNS CAD CORP

Date: **9/15/2020**
Permit Type:
Description:

Permit Description: **Sign Permit**
Work Class:
Proposed Use:
Permit Number: B00382213I1SG
Status: Signed Off
Valuation: $0.00
Contractor Company:
Contractor Name: SIGNS CAD CORP

Date: **9/15/2020**
Permit Type:
Description:

Permit Description: **Sign Permit**
Work Class:
Proposed Use:
Permit Number: B00382217I1SG
Status: Signed Off
Valuation: $0.00
Contractor Company:
Contractor Name: SIGNS CAD CORP

ADJOINING PROPERTY FINDINGS

Date: **9/11/2020**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00397627I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: HANISON ELECTRIC INC

Date: **9/10/2020**
Permit Type:
Description:

Permit Description: **Sign Permit**
Work Class:
Proposed Use:
Permit Number: B00382230I1SG
Status: Signed Off
Valuation: $0.00
Contractor Company:
Contractor Name: SIGNS CAD CORP

ADJOINING PROPERTY FINDINGS

Date:	**9/3/2020**
Permit Type:	**EW**
Description:	**HEREBY FILING FOR STRUCTURAL WORK IN CONJUNCTION WITH TENANT INTERIOR AND EXTERIOR ALTERATION IN CONJUNCTION WITH ARCHITECTURAL APPLICATION #340750565, MH- B00368321-I1,PL- B00368342-I1,. NO CHANGE TO USE EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	340750583-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CUSTOM COMMERCIAL CONSTRU

Date:	**8/13/2020**
Permit Type:	**EW**
Description:	**HEREBY FILING FOR TENANT INTERIOR AND EXTERIOR ALTERATION TO EXISTING SHELL SPACE. NO CHANGE TO USE EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	340750565-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CUSTOM COMMERCIAL CONSTRU

ADJOINING PROPERTY FINDINGS

Date: **8/12/2020**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00383447I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: NASH ELECTRIC SERVICES IN

Date: **4/15/2020**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00341759I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: TOP SHELF ELECTRIC CORP

Date: **3/3/2000**
Permit Type: **AL**
Description: **GROUND STRUCTURE FOR ILLUMINATED NON ADVERTISING ACCESSORY SIGN**

Permit Description: **ALTERATION**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use:
Permit Number: 300996929-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BERGER SIGN FAB INC

ADJOINING PROPERTY FINDINGS

Date: **3/2/2000**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 300996750-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BERGER SIGN FAB INC

Date: **3/2/2000**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 300996769-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BERGER SIGN FAB INC

Date: **3/2/2000**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 300996938-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BERGER SIGN FAB INC

ADJOINING PROPERTY FINDINGS

Date: **3/1/2000**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 300996778-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BERGER SIGN FAB INC

Date: **2/18/2000**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300957846-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name:

Date: **2/1/2000**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B197934
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: STAT ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

Date: **2/1/2000**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B197936
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: STAT ELECTRIC INC.

Date: **2/1/2000**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B197938
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: STAT ELECTRIC INC.

Date: **2/1/2000**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B197940
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: STAT ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

Date: **2/1/2000**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B197941
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: STAT ELECTRIC INC.

Date: **1/5/2000**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300939377-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: VIP SEWER CLEANING SERV

Date: **12/15/1999**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B196672
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: LTC ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

Date: **10/12/1999**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FENCE
Permit Number: 300939377-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: FATHER & SON CONTR INC

Date: **10/12/1999**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: MECHANICAL/HVAC
Permit Number: 300939377-01-EW-MH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: FATHER & SON CONTR INC

Date: **10/12/1999**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300939377-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: FATHER & SON CONTR INC

ADJOINING PROPERTY FINDINGS

4110 4TH AVE

Date:	**4/26/2017**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B427493
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	E & M ELECTRICAL NY CORP

Date:	**3/31/2017**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	321298252-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MASTER FIRE MECH CORP

Date:	**3/31/2017**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FIRE SUPPRESSION
Permit Number:	321298252-01-EW-FP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MASTER FIRE SYSTEMS, INC

ADJOINING PROPERTY FINDINGS

Date:	**2/18/2017**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B424227
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	E & M ELECTRICAL NY CORP

Date:	**11/23/2016**
Permit Type:	**EW**
Description:	**HEREWITH FILE TO RENOVATE RESTAURANT INCLUDES NEW NON-LOAD PARTITION WALL, NEW PLUMBING FIXTURES, NEW CARPENTRY/MILLWORK, MODIFY STORE-FRONT, AND GENERAL CONSTRUCTION. NO CHANGE IN USE, EGRESS, AND OCCUPANCY**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	321379405-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MICHAEL DEFINIS ALL PRO C

ADJOINING PROPERTY FINDINGS

Date:	**11/23/2016**
Permit Type:	**EW**
Description:	**HEREWITH FILE TO RENOVATE RESTAURANT INCLUDES NEW NON-LOAD PARTITION WALL, NEW PLUMBING FIXTURES, NEW CARPENTRY/MILLWORK, MODIFY STORE-FRONT, AND GENERAL CONSTRUCTION. NO CHANGE IN USE, EGRESS, AND OCCUPANCY**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321379405-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MICHAEL DEFINIS ALL PRO C

Date:	**11/23/2016**
Permit Type:	**EQ**
Description:	**HEREWITH FILE TO RENOVATE RESTAURANT INCLUDES NEW NON-LOAD PARTITION WALL, NEW PLUMBING FIXTURES, NEW CARPENTRY/MILLWORK, MODIFY STORE-FRONT, AND GENERAL CONSTRUCTION. NO CHANGE IN USE, EGRESS, AND OCCUPANCY**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FENCE
Permit Number:	321379405-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MICHAEL DEFINIS ALL PRO C

ADJOINING PROPERTY FINDINGS

Date:	**11/22/2016**
Permit Type:	**PL**
Description:	**HEREWITH FILE TO RENOVATE RESTAURANT INCLUDES NEW NON-LOAD PARTITION WALL, NEW PLUMBING FIXTURES, NEW CARPENTRY/MILLWORK, MODIFY STORE-FRONT, AND GENERAL CONSTRUCTION. NO CHANGE IN USE, EGRESS, AND OCCUPANCY**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321379405-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	GO PRO PLBNG AND HTG CO I

Date:	**2/11/2011**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B335858
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PRO ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

Date:	**2/2/2011**
Permit Type:	**EW**
Description:	**APPLICATION IS HEREWITH FILED TO REMOVE EXISTING PLANSTER FROM EXIST'G INTERIOR PARTITIONS ON APT.2F.PROVIDE NEW 5/8' GYP. BD.OVER THE EXISTING WALLS AND CEILING.REMOVE EXISTING TILES FROM THE EXISTING BATH ROOM AND INSTALL NEW TILES.ON THE WAALLS AND FLOOR.NO CHANGE OF USE OCCUPANCY OR MEANS OF EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320263996-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	UNITED INDUSTRIES & CONST

Date:	**1/4/2008**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B299482
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	KEVIN KEAVENY ELEC CO INC

ADJOINING PROPERTY FINDINGS

Date:	**11/14/2007**
Permit Type:	**EW**
Description:	**REPLACE BOILER AND OIL BURNER. NO CHANGE IN EGRESS, OCCUPANCY OR USE UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	310047785-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BLUE DIAMOND FUEL OIL CORP

Date:	**11/14/2007**
Permit Type:	**EW**
Description:	**REPLACE BOILER AND OIL BURNER. NO CHANGE IN EGRESS, OCCUPANCY OR USE UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FUEL BURNING
Permit Number:	310047785-01-EW-FB
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BLUE DIAMOND FUEL OIL CORP

ADJOINING PROPERTY FINDINGS

Date:	**4/14/2004**
Permit Type:	**EW**
Description:	**Modify Existing Fire Suppression System and shut off valve. All work to be conceiled within existing steel rangehood. No change in use, egrees or occupancy.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FIRE SUPPRESSION
Permit Number:	301800825-01-EW-FP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JEM FIRE PREVENTION INC

Date:	**7/6/1992**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B101270
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MAC ELECT'L CONTR. INC.

ADJOINING PROPERTY FINDINGS

4112 4TH AVE

Date: **8/26/2021**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00583603I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: WIRE UP ELEC'L CONT'G COR

Date: **9/3/2020**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00394100I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: WIRE UP ELEC'L CONT'G COR

ADJOINING PROPERTY FINDINGS

Date:	**1/12/2019**
Permit Type:	**EW**
Description:	**MINOR INTERIOR NON-BEARING PARTITION REMOVALS, CONVENIENCE STEPS AND RELOCATED 2 PIECE H.C. TOILET AT 1ST FLOOR STORE. THERE IS NO CHANGE TO OCCUPANCY GROUP, EGRESS OR USE UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	340653297-01-EW-OT
Status:	IN PROCESS, ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AMERICAN PRO BUILDERS*

Date:	**11/21/2018**
Permit Type:	**EW**
Description:	**FILING TO PROVIDE NEW INTERIOR FINISHES AND DIRECT REPLACEMENT OF PLUMBING FIXTURES SO AS TO MEET PARTIAL VACATE ORDER #146077. THERE IS NO CHANGE TO OCCUPANCY GROUP, EGRESS OR USE UNDER THIS APPLICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	340645555-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AMERICAN PRO BUILDERS*

ADJOINING PROPERTY FINDINGS

Date: **7/9/1998**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B179810
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: FALLON ELECTRIC

Date: **2/14/1991**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FIRE SUPPRESSION
Permit Number: 300053199-01-EW-FP
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: IDEAL FIRE CONTROL INC

Date: **4/19/1990**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B066721
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: IRWIN ELECTR'L CONTR'S

ADJOINING PROPERTY FINDINGS

4113 4TH AVE

Date: **2/28/1996**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B150510
Status: VIOLATN PENDING AT CONTRACTOR
Valuation: $0.00
Contractor Company:
Contractor Name: PHILIP A. ROBINSON

Date: **10/25/1989**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B059107
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: D. RYAN LIC. ELEC'L CONTR

Date: **1/17/1989**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B047904
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: D. RYAN LIC. ELEC'L CONTR

ADJOINING PROPERTY FINDINGS

4115 4TH AVE

Date:	**3/2/1992**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B095978
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	LOUIS DEM ELECTRICAL INC.

4117 4TH AVE

Date:	**1/21/2013**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B359432
Status:	Open
Valuation:	$0.00
Contractor Company:	
Contractor Name:	PRO ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

Date: **4/23/2012**
Permit Type: **EQ**
Description: **WINDOWS REPLACEMENT AT BOTH FACADES.**

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FENCE
Permit Number: 320394444-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: TRI-STATE KITCHEN AND BAT

Date: **4/23/2012**
Permit Type: **EW**
Description: **WINDOWS REPLACEMENT AT BOTH FACADES.**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 320394444-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: TRI-STATE KITCHEN AND BAT

Date: **1/10/1992**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use:
Permit Number: 300136403-01-AL
Status: RE-ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **10/25/1984**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K12512
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: NEAL ELECTRIC CORP.

4122 4TH AVE

Date: **8/3/2010**
Permit Type: **EW**
Description: **INSTALL FIRE SUPPRESSION SYSTEM FOR RESTAURANT IN ASSOCIATED WITH APPLICATION # 320135634. NO CHANGE IN USE, EGRESS, OR OCCUPANCY.**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FIRE SUPPRESSION
Permit Number: 320183350-01-EW-FP
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NY FIRE LLC

ADJOINING PROPERTY FINDINGS

Date:	**6/9/2010**
Permit Type:	**PL**
Description:	**RENOVATION OF TAKEOUT STORE. INSTALL COOKING EQUIPMENT, PLUMBING FIXTURES, RANGE HOOD, FLOOR, CEILING, AND STOREFRONT. NO CHANGE IN USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320135634-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CATMAN PLUMBING INC

Date:	**6/3/2010**
Permit Type:	**EW**
Description:	**RENOVATION OF TAKEOUT STORE. INSTALL COOKING EQUIPMENT, PLUMBING FIXTURES, RANGE HOOD, FLOOR, CEILING, AND STOREFRONT. NO CHANGE IN USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	320135634-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	55C CONSTRUCTION CORP

ADJOINING PROPERTY FINDINGS

Date:	**6/3/2010**
Permit Type:	**EW**
Description:	**RENOVATION OF TAKEOUT STORE. INSTALL COOKING EQUIPMENT, PLUMBING FIXTURES, RANGE HOOD, FLOOR, CEILING, AND STOREFRONT. NO CHANGE IN USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320135634-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	55C CONSTRUCTION CORP

Date:	**6/2/2010**
Permit Type:	**EQ**
Description:	**RENOVATION OF TAKEOUT STORE. INSTALL COOKING EQUIPMENT, PLUMBING FIXTURES, RANGE HOOD, FLOOR, CEILING, AND STOREFRONT. NO CHANGE IN USE, EGRESS, OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FENCE
Permit Number:	320135634-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	55C CONSTRUCTION CORP

ADJOINING PROPERTY FINDINGS

Date: **11/1/1989**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B059837
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: 3 L & J ELECT'L MAINT. L HERNANDEZ

4123 4TH AVE

Date: **3/1/2000**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B198892
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: JOHN PASTORE

ADJOINING PROPERTY FINDINGS

Date:	**2/18/2000**
Permit Type:	**EW**
Description:	**REPLACE BOILER, INSTALL GAS BURNER, NEW GAS SERVICE, METER AND PIPING NO CHANGE IN EGRESS, OCCUPANCY OR USE UNDER THIS APPLICATION. EMERGENCY HEAR REPAIR PER P.P.N. 7/99 FILED UNDER APPLICATION #300884737.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	300986379-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	COOPER MECHNICAL CORP.

Date:	**2/18/2000**
Permit Type:	**PL**
Description:	**REPLACE BOILER, INSTALL GAS BURNER, NEW GAS SERVICE, METER AND PIPING NO CHANGE IN EGRESS, OCCUPANCY OR USE UNDER THIS APPLICATION. EMERGENCY HEAR REPAIR PER P.P.N. 7/99 FILED UNDER APPLICATION #300884737.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	300986379-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	COOPER MECHNICAL CORP.

ADJOINING PROPERTY FINDINGS

Date: **7/3/1996**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B155300
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: VOLVIE HERMAN CONTRG CORP

Date: **10/13/1988**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B044259
Status: NO ACCESS
Valuation: $0.00
Contractor Company:
Contractor Name: E. CONTI ELECTRIC INC.

4201 4TH AVE

Date: **1/19/2018**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00005745I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: FREEDOM ELECTRIC & DATA,INC

ADJOINING PROPERTY FINDINGS

Date:	**9/7/2017**
Permit Type:	**EW**
Description:	**FILING HEREWITH FOR GENERAL CONSTRUCTION AS SHOWN ON DRAWINGS FILED HEREWITH. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321587797-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	F.J. SCIAME CONSTRUC CO I

Date:	**5/10/2011**
Permit Type:	**PL**
Description:	**REPLACEMENT OF COOLING TOWERE ON GROUND LEVEL AND CHILLERS IN THE BASEMENT. RE LATED MECHANICAL IN THE BASEMENT. NO CHANGE IN USE, EGRESS OR OCCUPANCY. RELAT ED PLUMBING IN THE BASEMENT.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320094964-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	SENID PL & HTG CORP

ADJOINING PROPERTY FINDINGS

Date:	**11/19/2010**
Permit Type:	**EW**
Description:	**REPLACEMENT OF COOLING TOWERE ON GROUND LEVEL AND CHILLERS IN THE BASEMENT. RE LATED MECHANICAL IN THE BASEMENT. NO CHANGE IN USE, EGRESS OR OCCUPANCY. RELAT ED PLUMBING IN THE BASEMENT.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	320094964-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ULTIMATE POWER INC

Date:	**11/19/2010**
Permit Type:	**EW**
Description:	**RELATED STRUCTURAL IN BASEMENT AND GRADE.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320094964-02-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ULTIMATE POWER INC

ADJOINING PROPERTY FINDINGS

Date:	**3/26/2010**
Permit Type:	**EQ**
Description:	**INSTALLATION OF HEAVY DUTY SIDEWALK SHED A TOTAL OF 446 LF AS PER PLAN AT 4201 4 AVENUE. WORK SHALL COMPLY WITH 2008 BUILDING CODE CHAPTER 33. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	320013597-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EVEREST SCAFFOLDING INC

Date:	**3/20/2010**
Permit Type:	**EQ**
Description:	**ERECT PIPE SCAFFOLD AS PER PLAN AT 4201 4 AVENUE. WORK SHALL COMPLY WITH 2008 BUILDING CODE CHAPTER 33. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SCAFFOLD
Permit Number:	320013604-01-EQ-SF
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EVEREST SCAFFOLDING INC

ADJOINING PROPERTY FINDINGS

Date:	**3/20/2010**
Permit Type:	**EQ**
Description:	**INSTALLATION OF PLYWOOD FENCE AS PER PLAN AT 4201 4 AVENUE. WORK SHALL COMPLY WITH 2008 BUILDING CODE CHAPTER 33. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	FENCE
Permit Number:	320013613-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EVEREST SCAFFOLDING INC

Date:	**4/14/2009**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B315360
Status:	CLOSED/CANCELLED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BOROWIDE ELECT'L CONTR'S

Date:	**3/16/2003**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B237925
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	N.Y.C. POLICE DEPT.

ADJOINING PROPERTY FINDINGS

Date: **1/27/2000**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: STAND PIPE
Permit Number: 300309869-01-EW-SD
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: PACE PLG CORP

Date: **1/27/2000**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300309869-02-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: PACE PLG CORP

Date: **11/8/1996**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: SPRINKLER
Permit Number: 300309869-01-EW-SP
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: THE PACE COMPANIES NY INC

ADJOINING PROPERTY FINDINGS

Date: **7/8/1996**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300286704-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: YORK/HUNTER CITY SERVICE,INC

Date: **1/25/1996**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B149049
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTHGATE ELECTRIC CORP.

Date: **12/22/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FUEL STORAGE
Permit Number: 300490289-01-EW-FS
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BERGEN FUEL OIL

ADJOINING PROPERTY FINDINGS

Date: **12/22/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: MECHANICAL/HVAC
Permit Number: 300490289-01-EW-MH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BERGEN FUEL OIL

Date: **12/22/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300490289-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BERGEN FUEL OIL

Date: **3/28/1995**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B138931
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTHGATE ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

Date: **3/28/1995**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B138934
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTHGATE ELECTRIC CORP.

Date: **3/28/1995**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B138937
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTHGATE ELECTRIC CORP.

Date: **1/31/1995**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300286704-03-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: THE PACE COMPANIES NY INC

ADJOINING PROPERTY FINDINGS

Date: **1/4/1995**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B144885
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTHGATE ELECTRIC CORP.

Date: **10/10/1986**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B011201
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: B & Q COMPANY INC.

Date: **5/20/1982**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: K03377C
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: APPLIED ELEC. CORP.

ADJOINING PROPERTY FINDINGS

4222 4TH AVE

Date:	**2/14/2023**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	STAND PIPE
Permit Number:	320702003-01-EW-SD
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	FORSYTHE PLBG & HTG. CORP

Date:	**4/11/2017**
Permit Type:	**EW**
Description:	**PROPOSED SELECTIVE DEMOLITION, NEW PARTITIONS, DOORS, STAIRS AND FINISHES. ALL AS PER PLANS FILED HEREWITH.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320991520-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NORTHEAST RESTOR. CORP

ADJOINING PROPERTY FINDINGS

Date:	**4/11/2017**
Permit Type:	**EW**
Description:	**SUBSEQUENT FILING OF PROPOSED STRUCTURAL WORK INVOLVING SELECTIVE DEMOLITION, AND STRUCTURAL MODIFICATIONS, INCLUDING REMOVAL OF LOAD BEARING WALLS, FLOOR REPLACEMENT, NEW STAIR AND SHAFT OPENINGS AND ROOF TOP DUNNAGE. ALL AS PER PLANS FILED HEREWITH.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320991520-02-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NORTHEAST RESTOR. CORP

Date:	**3/13/2017**
Permit Type:	**PL**
Description:	**SUBSEQUENT MECHANICAL & PLUMBING FILING OF PROPOSED WORK FOR SELECTIVE DEMOLITION, INSTALLATION OF NEW MECHANICAL AND PLUMBING SYSTEMS . ALL AS PER PLANS FILED HEREWITH.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320991520-03-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	FORSYTHE P&H CORP

ADJOINING PROPERTY FINDINGS

Date: **9/13/2016**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B417062
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: HIGH VOLT ELEC CORP. OF

Date: **7/15/2016**
Permit Type: **AL**
Description: **PROPOSED FIRE PROTECTION PLAN APPLICATION.**

Permit Description: **ALTERATION**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use:
Permit Number: 321145872-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NORTHEAST RESTOR. CORP

Date: **6/29/2016**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: MINOR WORK
Proposed Use:
Permit Number: B413653
Status: ADMINISTRATIVELY CLOSED (MINOR WORK)
Valuation: $0.00
Contractor Company:
Contractor Name: CHARAN ELEC'L ENTERP'S IN

ADJOINING PROPERTY FINDINGS

Date:	**6/20/2016**
Permit Type:	**EW**
Description:	**SUBSEQUENT DOCUMENT FOR INSTALLATION OF SPRINKLER SYSTEM. ALL AS PER PLANS FILED HEREWITH.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	SPRINKLER
Permit Number:	320991520-04-EW-SP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EAGLE MECHANICAL INC

Date:	**6/20/2016**
Permit Type:	**EW**
Description:	**SUBSEQUENT DOCUMENT FOR INSTALLATION OF STANDPIPE SYSTEM. ALL AS PER PLANS FILED HEREWITH.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	STAND PIPE
Permit Number:	320991520-05-EW-SD
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	EAGLE MECHANICAL INC

Date:	**5/16/2016**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	MINOR WORK
Proposed Use:	
Permit Number:	B411550
Status:	ADMINISTRATIVELY CLOSED (MINOR WORK)
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CHARAN ELEC'L ENTERP'S IN

ADJOINING PROPERTY FINDINGS

Date:	**5/5/2016**
Permit Type:	**EW**
Description:	**SUBSEQUENT FILING OF MECHANICAL & PLUMBING WORK TYPES. PROVIDING VENTILATION FOR TOILETS AND HVAC IN CAFETERIA AND KITCHEN AREA. SELECTIVE DEMOLITION OF RADIATORS AND ASSOCIATED PIPING. NEW ROOFTOP UNITS. SELECTIVE DEMOLITION OF PLUMBING FIXTURES AND PIPING. NEW PLUMBING FIXTURES AND PIPING. ALL AS PER PLANS FILED HEREWITH.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	320415662-03-EW-MH
Status:	ISSUED, RE-ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	MIDTOWN HVAC ENTERPRISES

Date:	**5/4/2016**
Permit Type:	**EW**
Description:	**PROPOSED INTERIOR RENOVATION, INCLUDING INTERIOR DEMOLITION, NEW PARTITIONS AND FINISHES. ALL AS PER PLANS FILED HEREWITH.NO CHANGE IN USE, EGRESS OR OCCUPANCY CLASSIFICATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320415662-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	INNOVAX PILLAR INC

ADJOINING PROPERTY FINDINGS

Date:	**5/4/2016**
Permit Type:	**EW**
Description:	**SUBSEQUENT FILING OF STRUCTURAL WORK TYPE. PROPOSED SLAB ON GRADE TRENCHING, NEW SLAB AND WALLS OPENINGS, STAIR ALTERATION.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320415662-02-EW-OT
Status:	ISSUED, RE-ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	INNOVAX PILLAR INC

Date:	**2/12/2016**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B407153
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HIGH VOLT ELEC CORP. OF

ADJOINING PROPERTY FINDINGS

Date:	**1/12/2016**
Permit Type:	**AL**
Description:	**PROPOSED CHANGE OF CONSTRUCTION CLASSIFICATION OF CLASS 2-FIRE PROTECTED WHICH IS INCONSISTENT WITH THE EXISTING WOOD STRUCTURE BASED ON PROBES. WE ARE FILING APPLICATION HEREWITH TO CLASSIFY THE EXISTING STRUCTURE AS CONSTRUCTION CLASSIFICATION 3A IN ACCORDANCE TO 2008 BUILDING CODE. NO WORK TO BE DONE.**
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	320858327-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NORTHEAST RESTORATION CORP

Date:	**10/15/2015**
Permit Type:	**PL**
Description:	**SUBSEQUENT FILING OF MECHANICAL & PLUMBING WORK TYPES. PROVIDING VENTILATION FOR TOILETS AND HVAC IN CAFETERIA AND KITCHEN AREA. SELECTIVE DEMOLITION OF RADIATORS AND ASSOCIATED PIPING. NEW ROOFTOP UNITS. SELECTIVE DEMOLITION OF PLUMBING FIXTURES AND PIPING. NEW PLUMBING FIXTURES AND PIPING. ALL AS PER PLANS FILED HEREWITH.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320415662-03-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	FORSYTHE P&H CORP

ADJOINING PROPERTY FINDINGS

Date:	**8/6/2015**
Permit Type:	**EQ**
Description:	**SH/PS333K - SUBMITTING ON BEHALF OF CONTRACTOR FOR THE INSTALLATION OF TEMPORARY CONSTRUCTION EQUIPMENT (SHED). NO CHANGE IN USE, OCCUPANCY OR EGRESS**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	340289137-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NORTHEAST RESTOR. CORP

Date:	**8/6/2015**
Permit Type:	**EQ**
Description:	**SF/PS333K - SUBMITTING ON BEHALF OF CONTRACTOR FOR THE INSTALLATION OF TEMPORARY CONSTRUCTION EQUIPMENT (SCAFFOLD). NO CHANGE IN USE, OCCUPANCY OR EGRESS**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SCAFFOLD
Permit Number:	340289146-01-EQ-SF
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NORTHEAST RESTOR. CORP

ADJOINING PROPERTY FINDINGS

Date: **8/3/2015**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: B399146
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name:

Date: **5/26/2015**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: B396220
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name:

Date: **4/30/2015**
Permit Type: **EW**
Description: **APPLICATION FILED HEREWITH PROVIDE NEW AUTOMATIC SPRINKLER SYSTEM TO SERVE STORAGE, CAFETERIA, OFFICES, TOILETS & KITCHEN SPACES IN THE CELLAR.**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: SPRINKLER
Permit Number: 320824006-01-EW-SP
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: FORSYTHE PLBG & HTG. CORP

ADJOINING PROPERTY FINDINGS

Date:	**3/31/2015**
Permit Type:	**EW**
Description:	**SUBSEQUENT MECHANICAL & PLUMBING FILING OF PROPOSED WORK FOR SELECTIVE DEMOLITION, INSTALLATION OF NEW MECHANICAL AND PLUMBING SYSTEMS . ALL AS PER PLANS FILED HEREWITH.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	320991520-03-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CHAPMAN & EVANS INC

Date:	**1/8/2015**
Permit Type:	**EW**
Description:	**PROPOSED WORK FOR SELECTIVE DEMOLITION OF INTERIOR NON-STRUCTURAL ELEMENTS AND FINISHES. PARTIAL DEMOLITION WORK AS DEFINED BY AC 28-101.5 INVOLVING STRUCTURAL MODIFICATIONS (INCLUDING NEW OPENINGS, REPLACEMENT OF STRUCTURAL MEMBERS, AND REMOVAL OF LOAD BEARING WALLS) HAVE BEEN FILED UNDER ALTERATION TYPE 2, JOB NO 320991520.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321011720-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NORTHEAST RESTOR. CORP

ADJOINING PROPERTY FINDINGS

Date:	**10/28/2014**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B387955
Status:	Open
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HIGH VOLT ELEC CORP.

Date:	**10/16/2014**
Permit Type:	**EW**
Description:	**SUBSEQUENT FILING OF STANDPIPE WORK TYPE.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	STAND PIPE
Permit Number:	320415662-04-EW-SD
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	FORSYTHE P&H CORP

ADJOINING PROPERTY FINDINGS

Date:	**2/5/2014**
Permit Type:	**PL**
Description:	**PLUMBING - ALTERATION TYPE 2** **SUBSEQUENT FILING OF MECHANICAL & PLUMBING WORK TYPES. PROVIDING VENTILATION** **FOR TOILETS AND HVAC IN CAFETERIA AND KITCHEN AREA. SELECTIVE DEMOLITION OF** **RADIATORS AND ASSOCIATED PIPING. NEW ROOFTOP UNITS. SELECTIVE DEMOLITION OF** **PLUMBING FIXTURES AND PIPING. NEW PLUMBING FIXTURES AND PIPING. ALL AS PER** **PLANS FILED HEREWITH.** **Limited scope of work: INSTALLATION OF WATER SERVICE**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	PLUMBING
Permit Number:	3PL005394-03-PL-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JULIAN PLBG & HTG CORP

Date:	**3/2/2010**
Permit Type:	**EW**
Description:	**INSTALLATION OF FIRE SUPPRESSIION SYSTEM ONLY. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FIRE SUPPRESSION
Permit Number:	320116414-01-EW-FP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	FIRE COMMAND CO,INC

ADJOINING PROPERTY FINDINGS

Date: **2/28/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B300677
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: TESTA ELECTRIC CO. INC

Date: **3/15/2007**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B288165
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: JAM ELECTRICAL CORP

Date: **7/24/2006**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 301420362-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: S.M CONST CO

ADJOINING PROPERTY FINDINGS

Date:	**3/10/2004**
Permit Type:	**EW**
Description:	**REPLACE (2) LOW PRESSURE BOILER + (2) GAS BURNER WITH ONE BOILER AND G AS BURNER MODIFY EXISTING GAS PIPING NO CHANGE IN USE EGRESS OR OCCUPANCY IS INVOLVED UNDER THIS APPLICATION**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	301809764-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RANSHAW FUEL, PLG & HTG

Date:	**3/10/2004**
Permit Type:	**PL**
Description:	**REPLACE (2) LOW PRESSURE BOILER + (2) GAS BURNER WITH ONE BOILER AND G AS BURNER MODIFY EXISTING GAS PIPING NO CHANGE IN USE EGRESS OR OCCUPANCY IS INVOLVED UNDER THIS APPLICATION**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	301809764-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	RANSHAW FUEL, PLG & HTG

ADJOINING PROPERTY FINDINGS

Date: **8/9/1996**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use:
Permit Number: 300535927-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: C N PLUMBING, INC.

Date: **8/5/1996**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300535927-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: G.FAZIO CONTRACTING CORP

Date: **5/30/1993**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B112496
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: HI-TECH ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

Date: **11/3/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B118140
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: DIBARTOLOMEO ELEC CONTR

Date: **5/6/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B097306
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: BEMUS ELEC'L CONTRS.

Date: **4/27/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B098774
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: BEMUS ELEC'L CONTRS.

ADJOINING PROPERTY FINDINGS

Date: **1/27/1992**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B094612
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: BEMUS ELEC'L CONTRS.

980 4TH AVE

Date: **2/14/2019**
Permit Type: **EW**
Description: **APPLICATION FILED HEREWITH ONLY TO OBTAIN EQUIPMENT USE CARDS**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: MECHANICAL/HVAC
Permit Number: 321923111-01-EW-MH
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CAVALRY LLC

ADJOINING PROPERTY FINDINGS

987 4TH AVE

Date:	**9/13/2019**
Permit Type:	**EW**
Description:	**PROPOSED RENOVATION TO EXISTING ATM DRIVE-THRU AS PER PLANS FILED HEREWITH. NO CHANGES TO OCCUPANCY USE OR EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321980193-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ICS BUILDERS, INC

Date:	**8/23/2019**
Permit Type:	
Description:	
Permit Description:	**Sign Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00158101I1SG
Status:	Signed Off
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NATIONAL MAINTENANCE, INC

ADJOINING PROPERTY FINDINGS

Date: **8/20/2019**
Permit Type:
Description:

Permit Description: **Sign Permit**
Work Class:
Proposed Use:
Permit Number: B00158136I1SG
Status: Signed Off
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINTENANCE, INC

Date: **8/2/2019**
Permit Type:
Description:

Permit Description: **Sign Permit**
Work Class:
Proposed Use:
Permit Number: B00158129I1SG
Status: Signed Off
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINTENANCE, INC

Date: **8/2/2019**
Permit Type:
Description:

Permit Description: **Sign Permit**
Work Class:
Proposed Use:
Permit Number: B00158141I1SG
Status: Signed Off
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINTENANCE, INC

ADJOINING PROPERTY FINDINGS

Date: **8/2/2019**
Permit Type:
Description:

Permit Description: **Sign Permit**
Work Class:
Proposed Use:
Permit Number: B00158149I1SG
Status: Signed Off
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINTENANCE, INC

Date: **8/2/2019**
Permit Type:
Description:

Permit Description: **Sign Permit**
Work Class:
Proposed Use:
Permit Number: B00158195I1SG
Status: Signed Off
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINTENANCE, INC

Date: **8/2/2019**
Permit Type:
Description:

Permit Description: **Sign Permit**
Work Class:
Proposed Use:
Permit Number: B00158207I1SG
Status: Signed Off
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINTENANCE, INC

ADJOINING PROPERTY FINDINGS

Date:	**8/7/2015**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION AND GENERAL SITE MAINTENANCE TO EXISTING TD BANK SPACE. NO CHANGE IN USE, OCCUPANCY, OR EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321180976-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CUSTOM COMMERCIAL CONSTRU

Date:	**4/20/2010**
Permit Type:	**EW**
Description:	**PROPOSE TO INSTALL WELLS, PIPING CONNECTIONS AND RESTORE ASPHALT. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	310232325-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	KLEINFELDER EAST,INC

Date:	**2/23/2010**
Permit Type:	**AL**
Description:	**GROUND STRUCTURE FOR ACCESSORY SIGN IPL**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	320122247-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ULTIMATE SIGNS & DESIGNS

ADJOINING PROPERTY FINDINGS

Date: **2/23/2010**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 320122256-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: ULTIMATE SIGNS&DESIGNS CO

Date: **11/11/2009**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B322467
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: BESTCO GENERAL ELEC. MAIN

Date: **11/5/2009**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B321721
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: WIRE TO WATER ELEC.

ADJOINING PROPERTY FINDINGS

Date: **9/29/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B309002
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: SCIENTIFIC ELEC. CO.

Date: **9/29/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B309003
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: SCIENTIFIC ELEC. CO.

Date: **9/29/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B309004
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: SCIENTIFIC ELEC. CO.

ADJOINING PROPERTY FINDINGS

Date: **9/29/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B309006
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: SCIENTIFIC ELEC. CO.

Date: **9/29/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B309008
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: SCIENTIFIC ELEC. CO.

Date: **9/29/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B309010
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: SCIENTIFIC ELEC. CO.

ADJOINING PROPERTY FINDINGS

Date: **9/29/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B309012
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: SCIENTIFIC ELEC. CO.

Date: **9/22/2008**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 310201867-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **9/22/2008**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 310201876-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

ADJOINING PROPERTY FINDINGS

Date: **9/22/2008**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 310201885-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **9/22/2008**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 310201894-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **9/22/2008**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 310201901-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

ADJOINING PROPERTY FINDINGS

Date: **9/22/2008**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 310201910-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **9/22/2008**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 310201929-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **4/6/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B302358
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: SCIENTIFIC ELEC. CO.

ADJOINING PROPERTY FINDINGS

Date: **1/26/2007**
Permit Type: **AL**
Description: **Erect accessory business banner on pole. Banner filed under seperate applications. No change in use, egress or occupancy.**

Permit Description: **ALTERATION**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use:
Permit Number: 302271271-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT

Date: **12/28/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302271137-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **12/28/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302271324-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

ADJOINING PROPERTY FINDINGS

Date: **12/28/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302274072-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **12/28/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302274081-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **12/28/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302274090-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

ADJOINING PROPERTY FINDINGS

Date: **12/28/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302274312-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **12/28/2006**
Permit Type: **AL**
Description: **Erect accessory business banner on pole. Banner filed under seperate applications. No change in use, egress or occupancy.**

Permit Description: **ALTERATION**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use:
Permit Number: 302271146-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **12/28/2006**
Permit Type: **AL**
Description: **Erect accessory business banner on pole. Banner filed under seperate applications. No change in use, egress or occupancy.**

Permit Description: **ALTERATION**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use:
Permit Number: 302271155-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

ADJOINING PROPERTY FINDINGS

Date:	**12/28/2006**
Permit Type:	**AL**
Description:	**Erect accessory business banner on pole. Banner filed under seperate applications. No change in use, egress or occupancy.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	302271360-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NATIONAL MAINT. INC

Date:	**12/28/2006**
Permit Type:	**SG**
Description:	
Permit Description:	**SIGN**
Work Class:	SG - SIGN
Proposed Use:	
Permit Number:	302274116-01-SG
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NATIONAL MAINT. INC

Date:	**12/28/2006**
Permit Type:	**SG**
Description:	
Permit Description:	**SIGN**
Work Class:	SG - SIGN
Proposed Use:	
Permit Number:	302274134-01-SG
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NATIONAL MAINT. INC

ADJOINING PROPERTY FINDINGS

Date: **12/28/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302274152-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **12/28/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302274161-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **12/27/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302271280-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

ADJOINING PROPERTY FINDINGS

Date: **12/27/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302271333-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **12/27/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302274063-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **12/27/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302274269-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

ADJOINING PROPERTY FINDINGS

Date:	**12/27/2006**
Permit Type:	**AL**
Description:	**Erect accessory business banner on pole. Banner filed under seperate applications. No change in use, egress or occupancy.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	302271262-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NATIONAL MAINT. INC

Date:	**12/27/2006**
Permit Type:	**AL**
Description:	**Erect accessory business banner on pole. Banner filed under seperate applications. No change in use, egress or occupancy.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	302271306-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NATIONAL MAINT. INC

ADJOINING PROPERTY FINDINGS

Date:	**12/27/2006**
Permit Type:	**AL**
Description:	**Erect accessory business banner on pole. Banner filed under seperate applications. No change in use, egress or occupancy.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	302271315-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NATIONAL MAINT. INC

Date:	**12/27/2006**
Permit Type:	**AL**
Description:	**Erect accessory business banner on pole. Banner filed under seperate applications. No change in use, egress or occupancy.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	302271342-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NATIONAL MAINT. INC

ADJOINING PROPERTY FINDINGS

Date:	**12/27/2006**
Permit Type:	**AL**
Description:	**Erect accessory business banner on pole. Banner filed under seperate applications. No change in use, egress or occupancy.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	302271351-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NATIONAL MAINT. INC

Date:	**12/27/2006**
Permit Type:	**SG**
Description:	
Permit Description:	**SIGN**
Work Class:	SG - SIGN
Proposed Use:	
Permit Number:	302274045-01-SG
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NATIONAL MAINT. INC

Date:	**12/27/2006**
Permit Type:	**AL**
Description:	**Erect accessory business banner on pole. Banner filed under seperate applications. No change in use, egress or occupancy.**
Permit Description:	**ALTERATION**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	
Permit Number:	302274054-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NATIONAL MAINT. INC

ADJOINING PROPERTY FINDINGS

Date: **12/27/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302274125-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **12/27/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302274143-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **12/27/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302274170-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

ADJOINING PROPERTY FINDINGS

Date: **12/26/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302271253-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **12/26/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302271299-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

Date: **12/26/2006**
Permit Type: **SG**
Description:

Permit Description: **SIGN**
Work Class: SG - SIGN
Proposed Use:
Permit Number: 302274107-01-SG
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NATIONAL MAINT. INC

ADJOINING PROPERTY FINDINGS

Date: **12/22/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B286096
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ELEMCO TESTING CO

Date: **12/22/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B286097
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ELEMCO TESTING CO

Date: **12/22/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B286098
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ELEMCO TESTING CO

ADJOINING PROPERTY FINDINGS

Date: **12/22/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B286099
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ELEMCO TESTING CO

Date: **12/22/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B286100
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ELEMCO TESTING CO

Date: **12/22/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B286101
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ELEMCO TESTING CO

ADJOINING PROPERTY FINDINGS

Date: **12/22/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B286102
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ELEMCO TESTING CO

Date: **12/22/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B286103
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ELEMCO TESTING CO

Date: **12/22/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B286105
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ELEMCO TESTING CO

ADJOINING PROPERTY FINDINGS

Date: **12/22/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B286106
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ELEMCO TESTING CO

Date: **12/22/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B286107
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ELEMCO TESTING CO

Date: **11/1/2006**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B284679
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: LAN UTILITIES ELEC. INC.

ADJOINING PROPERTY FINDINGS

Date: **10/20/2006**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 302086285-04-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: DUO PL & HTG CORP

Date: **10/17/2006**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: NB - NEW BUILDING
Proposed Use: FENCE
Permit Number: 302086285-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CUSTOM COMMERCIAL CONSTRUCTION

Date: **10/17/2006**
Permit Type: **NB**
Description:

Permit Description: **NEW BUILDING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 302086285-01-NB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CUSTOM COMMERCIAL CONSTRUCTION

ADJOINING PROPERTY FINDINGS

Date: **9/15/2006**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: DM - FULL DEMOLITION
Proposed Use: FENCE
Permit Number: 302216536-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CUSTOM COMMERCIAL CONST CORP

Date: **9/15/2006**
Permit Type: **DM**
Description:

Permit Description: **DEMOLITION & REMOVAL**
Work Class: DM - FULL DEMOLITION
Proposed Use:
Permit Number: 302216536-01-DM
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CUSTOM COMMERCIAL CONST CORP

Date: **6/6/2006**
Permit Type: **EQ**
Description: **Filing herewith proposed 8' high wood construction fence. No change in use, egress or occupancy.**

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use: FENCE
Permit Number: 302170576-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: LORICH CONST MNGMNT LLC

ADJOINING PROPERTY FINDINGS

Date:	**3/21/2002**
Permit Type:	**EW**
Description:	**REPLACE A.C.UNITS ON ROOF TOP ON EXISTIN G DUNNAGE.NO CHANGE IN USE,EGRE S OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	301223959-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WEATHER WISE CONDITIONING CORP

Date:	**9/15/1995**
Permit Type:	**PL**
Description:	
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	300411356-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	G M PLUMBING & HEATING

Date:	**1/11/1995**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FIRE SUPPRESSION
Permit Number:	300411356-01-EW-FP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	FIRE COMMAND CO., INC.

ADJOINING PROPERTY FINDINGS

Date: **11/2/1994**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A3 - ALTERATION TYPE 3
Proposed Use:
Permit Number: 300327885-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: TESTA & WIRTH, INC

Date: **10/10/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B133221
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: ARCADIA ELECT'L CO. INC.

Date: **8/1/1994**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 300251796-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: G M PLG & HTG

ADJOINING PROPERTY FINDINGS

Date: **7/18/1994**
Permit Type: **NB**
Description:

Permit Description: **NEW BUILDING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 300251796-01-NB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: TESTA & WIRTH INC

Date: **7/18/1994**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: NB - NEW BUILDING
Proposed Use: FENCE
Permit Number: 300251796-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: TESTA & WIRTH INC

Date: **7/18/1994**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FENCE
Permit Number: 300356353-01-EQ-FN
Status: RE-ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: TESTA & WIRTH INC

ADJOINING PROPERTY FINDINGS

Date: **6/10/1994**
Permit Type: **DM**
Description:

Permit Description: **DEMOLITION & REMOVAL**
Work Class: DM - FULL DEMOLITION
Proposed Use:
Permit Number: 300341761-01-DM
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: TESTA & WIRTH INC

Date: **5/10/1994**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: DM - FULL DEMOLITION
Proposed Use: FENCE
Permit Number: 300341761-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: TESTA & WIRTH INC

Date: **5/9/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B128249
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: HOMESTEAD ELEC & SECURITY

ADJOINING PROPERTY FINDINGS

Date: **12/29/1993**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300281237-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: GROUNDWATER TECHNOLOGY INC

Date: **12/23/1993**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 300279954-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: GROUNDWATER TECHNOLOGY INC.

ADJOINING PROPERTY FINDINGS

992 4TH AVE

Date:	**5/23/2016**
Permit Type:	**EQ**
Description:	**PROPOSED INSTALLATION OF HEAVY DUTY SIDEWALK SHED FILED FOR REMEDIAL REPAIRS AS PER PLANS. NO CHANGE IN USE OCCUPANCY OR EGRESS UNDER THIS APPLICATION. LIVE LOAD 300 PER SQUARE FEET. SIDEWALK SHED SHALL COMPLY WITH CHAPTER # 33 OF THE 2014 CODE.**
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A3 - ALTERATION TYPE 3
Proposed Use:	SIDEWALK SHED
Permit Number:	340382570-01-EQ-SH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HKSCONSTRUCTION CORP

Date:	**5/18/2016**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B411647
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	4000 ELECTRIC CORP

ADJOINING PROPERTY FINDINGS

Date:	**5/21/2013**
Permit Type:	
Description:	
Permit Description:	**ELECTRICAL**
Work Class:	REHABILITATION
Proposed Use:	
Permit Number:	B367757
Status:	Closed
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BLAZE ELECTRIC INC.

Date:	**3/6/2007**
Permit Type:	**PL**
Description:	**LEGALIZE CONSTRUCTION PLUMBING WORK ANDREPLACEMENT OF MECHANICAL VENTS AT 1ST FLOOR INDICATED ON DRAWINGS FILEDHEREWITH NO WORK TO BE DONE UNDER THIS APPLICATION NO CHANGE IN USE EGRESS OROCCUPANCY UNDER THIS APPLIACATION**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	302193659-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	THE PLUMBING COMPANY, INC.

ADJOINING PROPERTY FINDINGS

Date:	**11/6/2006**
Permit Type:	**EW**
Description:	**LEGALIZE CONSTRUCTION PLUMBING WORK ANDREPLACEMENT OF MECHANICAL VENTS AT 1ST FLOOR INDICATED ON DRAWINGS FILEDHEREWITH NO WORK TO BE DONE UNDER THIS APPLICATION NO CHANGE IN USE EGRESS OROCCUPANCY UNDER THIS APPLIACATION**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	302193659-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

Date:	**11/6/2006**
Permit Type:	**EW**
Description:	**LEGALIZE CONSTRUCTION PLUMBING WORK ANDREPLACEMENT OF MECHANICAL VENTS AT 1ST FLOOR INDICATED ON DRAWINGS FILEDHEREWITH NO WORK TO BE DONE UNDER THIS APPLICATION NO CHANGE IN USE EGRESS OROCCUPANCY UNDER THIS APPLIACATION**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	302193659-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date: **8/30/1996**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B157038
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: BLAZE ELECTRIC INC.

Date: **4/10/1995**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B139454
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: BLAZE ELECTRIC INC.

994 4TH AVE

Date: **5/20/2022**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B00741490I1EL
Status: Permit Issued
Valuation: $0.00
Contractor Company:
Contractor Name: TRIPLE D ELECTRIC INC

ADJOINING PROPERTY FINDINGS

Date: **1/4/2017**
Permit Type:
Description:

Permit Description: **Electrical Permit**
Work Class:
Proposed Use:
Permit Number: B421666
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: APPROVED ELECTRIC CORP.

Date: **7/21/2011**
Permit Type: **EW**
Description: **INSTALL FIRE SUPPRESSION SYSTEM ONLY. FIRE SUPPRESSION GAS SHUT OFF VALVE FILED UNDER APPLICATION #302287987. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: FIRE SUPPRESSION
Permit Number: 320333242-01-EW-FP
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: FIRE COMMAND CO,INC

Date: **4/6/2007**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B289972
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: AEC ELECTRICAL CO INC

ADJOINING PROPERTY FINDINGS

Date:	**2/23/2007**
Permit Type:	**PL**
Description:	**Renovate existing store for eating and drinking establishment. Install fire suppression system under kitchen hood. U.G. # 6. No change in egress, occupancy or use is involved under this application.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	302287987-01-PL
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	VALUE PLG. INC.

Date:	**1/5/2007**
Permit Type:	**EW**
Description:	**Renovate existing store for eating and drinking establishment. Install fire suppression system under kitchen hood. U.G. # 6. No change in egress, occupancy or use is involved under this application.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FIRE SUPPRESSION
Permit Number:	302287987-01-EW-FP
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	NEW YORK BUSINESSZ FIRE SYST

ADJOINING PROPERTY FINDINGS

Date:	**1/5/2007**
Permit Type:	**EW**
Description:	**Renovate existing store for eating and drinking establishment. Install fire suppression system under kitchen hood. U.G. # 6. No change in egress, occupancy or use is involved under this application.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	302287987-01-EW-MH
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JNL CONST INC

Date:	**1/5/2007**
Permit Type:	**EW**
Description:	**Renovate existing store for eating and drinking establishment. Install fire suppression system under kitchen hood. U.G. # 6. No change in egress, occupancy or use is involved under this application.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	302287987-01-EW-OT
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	JNL CONST INC

ADJOINING PROPERTY FINDINGS

Date: **8/9/1994**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B129943
Status: CLOSED/CANCELLED
Valuation: $0.00
Contractor Company:
Contractor Name: ABCO ELEC'L CONTR'G CORP.

996 4TH AVE

Date: **2/25/2008**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B301198
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: A.T. ELEC'L CONTR'G INC

ADJOINING PROPERTY FINDINGS

Date:	**2/11/2008**
Permit Type:	**EW**
Description:	**INTERIOR RENOVATION OF EXISTING 2-FAMILY HOUSE WITH RELAMINATING INTERIOR PARTITIONS, NO PLUMBING WORK. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	310087009-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CHINA PERFECT CONSTRUCTION CORP.

Date:	**1/20/1999**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B187296
Status:	AWAITING INSPECTION REQUEST
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BLAZE ELECTRIC INC.

ADJOINING PROPERTY FINDINGS

998 4TH AVE

Date:	**3/4/2009**
Permit Type:	**AL**
Description:	**THIS APPLICATION IS FILED TO PROPOSE AN INTERIOR RENOVATION OF EXISTING COMMERCIAL BUILDING. THIS APPLICATION IS FILED TO PROPOSE AN EXTENSION AT REAR OF EXISTING COMMERCIAL BUILDING. TO OOBTAIN A NEW CERTIFICATE OF OCCUPANCY.**
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	302158359-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	UNIVERSAL. CONST & BUILD. INC

Date:	**7/11/2007**
Permit Type:	**PL**
Description:	**THIS APPLICATION IS FILED TO PROPOSE AN INTERIOR RENOVATION OF EXISTING COMMERCIAL BUILDING. THIS APPLICATION IS FILED TO PROPOSE AN EXTENSION AT REAR OF EXISTING COMMERCIAL BUILDING. TO OOBTAIN A NEW CERTIFICATE OF OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	302158359-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	VALUE PLBG INC

ADJOINING PROPERTY FINDINGS

Date: **2/8/2007**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 302158313-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: VALUE PLUMBING., INC.

Date: **1/26/2007**
Permit Type: **EQ**
Description:

Permit Description: **CONSTRUCTION EQUIPMENT**
Work Class: NB - NEW BUILDING
Proposed Use: FENCE
Permit Number: 302158313-01-EQ-FN
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: UNIVERSAL CONSTRUCTION & BUILDER

Date: **1/26/2007**
Permit Type: **NB**
Description:

Permit Description: **NEW BUILDING**
Work Class: NB - NEW BUILDING
Proposed Use:
Permit Number: 302158313-01-NB
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: UNIVERSAL CONSTRUCTION & BUILDER

ADJOINING PROPERTY FINDINGS

5TH AVE

3918 5TH AVE

Date:	**12/11/2018**
Permit Type:	**EW**
Description:	**INSTALL NEW AWNING AT STOREFRONT READING AS '5TH AVE DISCOUNT STORE'. NO CHANGE IN USE, EGRESS, AND OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	321737803-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	C & I PLUMBING CONSTRUCTI

Date:	**11/15/2018**
Permit Type:	
Description:	
Permit Description:	**Electrical Permit**
Work Class:	
Proposed Use:	
Permit Number:	B00100109I1EL
Status:	Permit Issued
Valuation:	$0.00
Contractor Company:	
Contractor Name:	HI- RITE ELECTRIC CORP.

ADJOINING PROPERTY FINDINGS

Date:	**1/15/2016**
Permit Type:	**EW**
Description:	**FILE BOILER WORK IN CONJUNCTION WITH A2# 320955123 AS PER PLAN. NO CHANGE IN USE, EGRESS & OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	321292338-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ORION PLUMBING & HTG CORP

Date:	**11/4/2015**
Permit Type:	**EW**
Description:	**PROPOSE INTERIOR RENOVATION WITH MINOR PARTITION, FLOOR FINISH AND PLUMBING WORK AS PER PLAN. NO CHANGE IN USE, EGRESS & OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	OTHER CONSTRUCTION EQUIPMENT
Permit Number:	320955123-01-EW-OT
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	C & I PLUMBING CONSTRUCTI

ADJOINING PROPERTY FINDINGS

Date:	**11/4/2015**
Permit Type:	**EW**
Description:	**PROPOSE INTERIOR RENOVATION WITH MINOR PARTITION, FLOOR FINISH AND PLUMBING WORK AS PER PLAN. NO CHANGE IN USE, EGRESS & OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	320955123-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	C & I PLUMBING CONSTRUCTI

Date:	**7/15/2015**
Permit Type:	**PL**
Description:	**PROPOSE INTERIOR RENOVATION WITH MINOR PARTITION, FLOOR FINISH AND PLUMBING WORK AS PER PLAN. NO CHANGE IN USE, EGRESS & OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320955123-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ORION PLUMBING & HTG CORP

ADJOINING PROPERTY FINDINGS

Date: **4/16/2015**
Permit Type:
Description:

Permit Description: **ELECTRICAL**
Work Class: REHABILITATION
Proposed Use:
Permit Number: B394401
Status: COMPLETED, Closed
Valuation: $0.00
Contractor Company:
Contractor Name: HI-RITE ELECTRIC CORP.

3920 5TH AVE

Date: **11/14/2019**
Permit Type: **EW**
Description: **LEGALIZE EXISTING BOILER IN CELLAR AS PER PLAN FILED HEREWITH TO REMOVE VIOLATION #32053706J, #32053705H, #32053704X & #32053703Y. NO CHANGE IN USE, OCCUPANCY & EGRESS.**

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 321369871-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: WATSON'S PLBG, HTG, & BDG

ADJOINING PROPERTY FINDINGS

Date:	**11/14/2019**
Permit Type:	**PL**
Description:	**LEGALIZE EXISTING BOILER IN CELLAR AS PER PLAN FILED HEREWITH TO REMOVE VIOLATION #32053706J, #32053705H, #32053704X & #32053703Y. NO CHANGE IN USE, OCCUPANCY & EGRESS.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321369871-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WATSON'S PLBG, HTG, & BDG

Date:	**8/8/2019**
Permit Type:	**PL**
Description:	**INSTALLATION OF NEW SPRINKLER SYSTEM AS PER PLAN FILED HEREWITH TO REMOVE VILA TION #35140120R, #35140121Z. NO CHANGE IN USE, OCCUPANCY & EGRESS.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	321369880-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	WATSON'S PLBG, HTG, & BDG

ADJOINING PROPERTY FINDINGS

Date:	**7/23/2018**
Permit Type:	**EW**
Description:	**FILE SPRINKLER WORK TYPE IN CONJUNCTION W/ JOB #321369880. NO CHANGE IN USE, OCCUPANCY & EGRESS.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	SPRINKLER
Permit Number:	321675674-01-EW-SP
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	QMB PLUMBING & HTG INC

Date:	**7/3/2018**
Permit Type:	**AL**
Description:	
Permit Description:	**ALTERATION**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	321396217-01-AL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	TGC CONSTRUCTION INC

Date:	**9/7/2017**
Permit Type:	**PL**
Description:	
Permit Description:	**PLUMBING**
Work Class:	A1 - ALTERATION TYPE 1
Proposed Use:	
Permit Number:	321396217-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	TOP PLUMBING GROUP,INC

ADJOINING PROPERTY FINDINGS

Date:	**9/19/2006**
Permit Type:	**EW**
Description:	**INSTALL ONE NEW HYDRONIC BOILER IN CELLAR. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	BOILER
Permit Number:	302179639-01-EW-BL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ATTACK PLUMBING

Date:	**6/29/2006**
Permit Type:	**PL**
Description:	**INSTALL ONE NEW HYDRONIC BOILER IN CELLAR. NO CHANGE IN USE, EGRESS OR OCCUPANCY.**
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	302179639-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	ATTACK PLUMBING

Date:	**3/30/2000**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	B199824
Status:	COMPLETED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AL-LECTRIC ELECT'L CONTRG

ADJOINING PROPERTY FINDINGS

Date: **3/27/2000**
Permit Type: **PL**
Description:

Permit Description: **PLUMBING**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300957800-01-PL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: K C PLG HTNG CONTR CO

Date: **2/11/2000**
Permit Type: **AL**
Description:

Permit Description: **ALTERATION**
Work Class: A1 - ALTERATION TYPE 1
Proposed Use:
Permit Number: 300957800-01-AL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: NYC CORP BUILDERS

Date: **11/8/1990**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B076784
Status: COMPLETED
Valuation: $0.00
Contractor Company:
Contractor Name: E & M ELECT CONTRS CORP

ADJOINING PROPERTY FINDINGS

4002 5TH AVE

Date:	**4/15/2011**
Permit Type:	**PL**
Description:	
Permit Description:	**PLUMBING**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	
Permit Number:	320188596-01-PL
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	AUSTIN PLBG & HTG CO.INC

Date:	**3/1/2011**
Permit Type:	**EQ**
Description:	
Permit Description:	**CONSTRUCTION EQUIPMENT**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FENCE
Permit Number:	320188596-01-EQ-FN
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CAPPEZZANO CONSTRUCTION

Date:	**3/1/2011**
Permit Type:	**EW**
Description:	
Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	MECHANICAL/HVAC
Permit Number:	320188596-01-EW-MH
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	CAPPEZZANO CONSTRUCTION

ADJOINING PROPERTY FINDINGS

Date: **3/1/2011**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: OTHER CONSTRUCTION EQUIPMENT
Permit Number: 320188596-01-EW-OT
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: CAPPEZZANO CONSTRUCTION

Date: **11/21/2010**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: B333766
Status: AWAITING INSPECTION REQUEST
Valuation: $0.00
Contractor Company:
Contractor Name: A#1 UNIVERSAL ELEC'L INC

Date: **12/6/1995**
Permit Type: **EW**
Description:

Permit Description: **EQUIPMENT WORK**
Work Class: A2 - ALTERATION TYPE 2
Proposed Use: BOILER
Permit Number: 300473404-01-EW-BL
Status: ISSUED
Valuation: $0.00
Contractor Company:
Contractor Name: BLUE DIAMOND FUEL OIL CORP.

ADJOINING PROPERTY FINDINGS

Date:	**12/6/1995**
Permit Type:	**EW**
Description:	

Permit Description:	**EQUIPMENT WORK**
Work Class:	A2 - ALTERATION TYPE 2
Proposed Use:	FUEL BURNING
Permit Number:	300473404-01-EW-FB
Status:	ISSUED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	BLUE DIAMOND FUEL OIL CORP.

GLOSSARY

General Building Department concepts

- **ICC:** The International Code Council. The governing body for the building/development codes used by all jurisdictions who've adopted the ICC guidelines. MOST of the US has done this. Canada, Mexico, and other countries use ICC codes books and guides as well. There are a few states who have added guidelines to the ICC codes to better fit their needs. For example, California has added seismic retrofit requirements for most commercial structures.
- **Building Department (Permitting Authority, Building Codes, Inspections Department, Building and Inspections):** This is the department in a jurisdiction where an owner or contractor goes to obtain permits and inspections for building, tearing down, remodeling, adding to, re-roofing, moving or otherwise making changes to any structure, Residential or Commercial.
- **Jurisdiction:** This is the geographic area representing the properties over which a Permitting Authority has responsibility.
- **GC:** General Contractor. Usually the primary contractor hired for any Residential or Commercial construction work.
- **Sub:** Subordinate contracting companies or subcontractors. Usually a "trades" contractor working for the GC. These contractors generally have an area of expertise in which they are licensed like Plumbing, Electrical, Heating and Air systems, Gas Systems, Pools etc. (called "trades").
- **Journeymen:** Sub contractors who have their own personal licenses in one or more trades and work for different contracting companies, wherever they are needed or there is work.
- **HVAC (Mechanical, Heating & Air companies):** HVAC = Heating, Ventilation, and Air Conditioning.
- **ELEC (Electrical, TempPole, TPole, TPower, Temporary Power, Panel, AMP Change, Power Release):** Electrical permits can be pulled for many reasons. The most common reason is to increase the AMPs of power in an electrical power panel. This requires a permit in almost every jurisdiction. Other commons reason for Electrical permits is to insert a temporary power pole at a new construction site. Construction requires electricity, and in a new development, power has yet to be run to the lot. The temporary power pole is usually the very first permit pulled for new development. The power is released to the home owner when construction is complete and this sometimes takes the form of a Power Release permit or inspection.
- **"Pull" a permit:** To obtain and pay for a building permit.
- **CBO:** Chief Building Official
- **Planning Department:** The department in the development process where the building /structural plans are reviewed for their completeness and compliance with building codes
- **Zoning Department:** The department in the development process where the site plans are reviewed for their compliance with the regulations associated with the zoning district in which they are situated.
- **Zoning District:** A pre-determined geographic boundary within a jurisdiction where certain types of structures are permitted / prohibited. Examples are Residential structure, Commercial/Retail structures, Industrial/Manufacturing structures etc. Each zoning district has regulations associated with it like the sizes of the lots, the density of the structures on the lots, the number of parking spaces required for certain types of structures on the lots etc.
- **PIN (TMS, GIS ID, Parcel#):** Property Identification Number and Tax Map System number.
- **State Card (Business license):** A license card issued to a contractor to conduct business.
- **Building Inspector (Inspector):** The inspector is a building department employee that inspects building construction for compliance to codes.
- **C.O.:** Certificate of Occupancy. This is the end of the construction process and designates that the owners now have permission to occupy a structure after its building is complete. Sometimes also referred to as a Certificate of Compliance.

GLOSSARY

Permit Content Definitions

- Permit Number: The alphanumerical designation assigned to a permit for tracking within the building department system. Sometimes the permit number gives clues to its role, e.g. a "PL" prefix may designate a plumbing permit.
- Description: A field on the permit form that allows the building department to give a brief description of the work being done. More often than not, this is the most important field for EP's to find clues to the prior use (s) of the property.
- Permit Type: Generally a brief designation of the type of job being done. For example BLDG-RES, BLDG-COM, ELEC, MECH etc.

Sample Building Permit Data

Date: Nov 09, 2000
Permit Type: Bldg -
New Permit Number: 101000000405
Status: Valuation: $1,000,000.00
Contractor Company: OWNER-BUILDER
Contractor Name:

Description: New one store retail (SAV-ON) with drive-thru pharmacy. Certificate of Occupancy.

APPENDIX D - Historic Information (Sanborn Maps, Aerial Photographs, Topography Maps)

4001 4th Avenue

4001 4th Avenue

Brooklyn, NY 11232

Inquiry Number: 7571432.3

February 18, 2024

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

02/18/24

Site Name:

4001 4th Avenue
4001 4th Avenue
Brooklyn, NY 11232
EDR Inquiry # 7571432.3

Client Name:

Lesova Environmental Group
3611 14th Avenue, Suite 551
Brooklyn, NY 11218
Contact: Dhruvi Patel

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Lesova Environmental Group were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 37D8-4991-ACD5

PO # NA

Project NA

Maps Provided:

2007	1994	1980	1906
2006	1993	1979	1888
2005	1992	1978	
2004	1991	1976	
2003	1990	1970	
2002	1988	1951	
2001	1987	1942	
1995	1982	1926	

Sanborn® Library search results

Certification #: 37D8-4991-ACD5

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Lesova Environmental Group (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.


Copyright 2024 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2007 Source Sheets



Volume 6A, Sheet 21
2007




Volume 6A, Sheet 22
2007

2006 Source Sheets




Volume 6A, Sheet 22
2006



Volume 6A, Sheet 21
2006

2005 Source Sheets




Volume 6A, Sheet 21
2005




Volume 6A, Sheet 22
2005

2004 Source Sheets



Volume 6A, Sheet 22
2004



Volume 6A, Sheet 21
2004


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2003 Source Sheets



Volume 6A, Sheet 21
2003




Volume 6A, Sheet 22
2003

2002 Source Sheets




Volume 6A, Sheet 21
2002



Volume 6A, Sheet 22
2002

2001 Source Sheets



Volume 6A, Sheet 22
2001



Volume 6A, Sheet 21
2001

1995 Source Sheets



Volume 6A, Sheet 21
1995



Volume 6A, Sheet 22
1995

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1994 Source Sheets




Volume 6A, Sheet 22
1994



Volume 6A, Sheet 21
1994

1993 Source Sheets



Volume 6A, Sheet 21
1993



Volume 6A, Sheet 22
1993

1992 Source Sheets



Volume 6A, Sheet 22
1992



Volume 6A, Sheet 21
1992

1991 Source Sheets



Volume 6A, Sheet 21
1991




Volume 6A, Sheet 22
1991


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1990 Source Sheets




Volume 6A, Sheet 21
1990



Volume 6A, Sheet 22
1990

1988 Source Sheets



Volume 6A, Sheet 22
1988




Volume 6A, Sheet 21
1988

1987 Source Sheets




Volume 6A, Sheet 21
1987




Volume 6A, Sheet 22
1987

1982 Source Sheets



Volume 6A, Sheet 21
1982




Volume 6A, Sheet 22
1982

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1980 Source Sheets




Volume 6A, Sheet 21
1980




Volume 6A, Sheet 22
1980

1979 Source Sheets



Volume 6A, Sheet 21
1979



Volume 6A, Sheet 22
1979

1978 Source Sheets




Volume 6A, Sheet 21
1978




Volume 6A, Sheet 22
1978

1976 Source Sheets



Volume 6A, Sheet 21
1976




Volume 6A, Sheet 22
1976


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1970 Source Sheets




Volume 6A, Sheet 21
1970



Volume 6A, Sheet 22
1970

1951 Source Sheets




Volume 6A, Sheet 22
1951



Volume 6A, Sheet 21
1951

1942 Source Sheets




Volume 6A, Sheet 21
1942




Volume 6A, Sheet 22
1942

1926 Source Sheets



Volume 6A, Sheet 22
1926




Volume 6A, Sheet 21
1926


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1906 Source Sheets



Volume 6, Sheet 28
1906




Volume 6, Sheet 29
1906


1888 Source Sheets



Volume 6, Sheet 142
1888





Volume 6, Sheet 142a
1888



Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #:	37D8-4991-ACD5
Copyright	2007

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 22
Volume 6A, Sheet 21


0 Feet 150 300 600


N



Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #:	37D8-4991-ACD5
Copyright	2006

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.







Volume 6A, Sheet 21
Volume 6A, Sheet 22

0 Feet 150 300 600


N



708
713
709
714
719
4TH
4ST
4TH
4TH
4TH



Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #:	37D8-4991-ACD5
Copyright	2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 21
Volume 6A, Sheet 22

0 Feet 150 300 600


N




Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #:	37D8-4991-ACD5
Copyright	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600






Volume 6A, Sheet 22
Volume 6A, Sheet 21


N



Site Name: 4001 4th Avenue
Address: 4001 4th Avenue
City, ST, ZIP: Brooklyn, NY 11232
Client: Lesova Environmental Group
EDR Inquiry: 7571432.3
Order Date: 02/18/2024
Certification #: 37D8-4991-ACD5
Copyright: 2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 22
Volume 6A, Sheet 21


0 Feet 150 300 600


N



Site Name: 4001 4th Avenue
Address: 4001 4th Avenue
City, ST, ZIP: Brooklyn, NY 11232
Client: Lesova Environmental Group
EDR Inquiry: 7571432.3
Order Date: 02/18/2024
Certification #: 37D8-4991-ACD5
Copyright 2001

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 21
Volume 6A, Sheet 22

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #:	37D8-4991-ACD5
Copyright	1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 22
Volume 6A, Sheet 21

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #37D8-4991-ACD5

Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #:	37D8-4991-ACD5
Copyright	1994

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 21
Volume 6A, Sheet 22

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #37D8-4991-ACD5

Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #	37D8-4991-ACD5
Copyright	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 22
Volume 6A, Sheet 21

0 Feet 150 300 600

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #37D8-4991-ACD5

Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #:	37D8-4991-ACD5
Copyright	1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 21
Volume 6A, Sheet 22


0 Feet 150 300 600


N



Site Name: 4001 4th Avenue
Address: 4001 4th Avenue
City, ST, ZIP: Brooklyn, NY 11232
Client: Lesova Environmental Group
EDR Inquiry: 7571432.3
Order Date: 02/18/2024
Certification #: 37D8-4991-ACD5
Copyright: 1991

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 22
Volume 6A, Sheet 21


0 Feet 150 300 600


N



Site Name: 4001 4th Avenue
Address: 4001 4th Avenue
City, ST, ZIP: Brooklyn, NY 11232
Client: Lesova Environmental Group
EDR Inquiry: 7571432.3
Order Date: 02/18/2024
Certification #: 37D8-4991-ACD5
Copyright: 1990

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 22
Volume 6A, Sheet 21

0 Feet 150 300 600

N


Certified Sanborn® Map


1988



Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #:	37D8-4991-ACD5
Copyright	1988

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 21
Volume 6A, Sheet 22

0 Feet 150 300 600


N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #:	37D8-4991-ACD5
Copyright	1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 22
Volume 6A, Sheet 21

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #	37D8-4991-ACD5
Copyright	1982

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 22
Volume 6A, Sheet 21

0 Feet 150 300 600

N




Site Name: 4001 4th Avenue
Address: 4001 4th Avenue
City, ST, ZIP: Brooklyn, NY 11232
Client: Lesova Environmental Group
EDR Inquiry: 7571432.3
Order Date: 02/18/2024
Certification #: 37D8-4991-ACD5
Copyright 1980

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 6A, Sheet 22
Volume 6A, Sheet 21


N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #	37D8-4991-ACD5
Copyright	1979

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 22
Volume 6A, Sheet 21

0 Feet 150 300 600


N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #:	37D8-4991-ACD5
Copyright	1978

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 22
Volume 6A, Sheet 21


0 Feet 150 300 600


N



Site Name: 4001 4th Avenue
Address: 4001 4th Avenue
City, ST, ZIP: Brooklyn, NY 11232
Client: Lesova Environmental Group
EDR Inquiry: 7571432.3
Order Date: 02/18/2024
Certification #: 37D8-4991-ACD5
Copyright: 1976

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 22
Volume 6A, Sheet 21

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #37D8-4991-ACD5

Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #	37D8-4991-ACD5
Copyright	1970

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 6A, Sheet 22
Volume 6A, Sheet 21

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #37D8-4991-ACD5

Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #	37D8-4991-ACD5
Copyright	1951

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 6A, Sheet 21
Volume 6A, Sheet 22

N





The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #37D8-4991-ACD5

Site Name:	4001 4th Avenue
Address:	4001 4th Avenue
City, ST, ZIP:	Brooklyn, NY 11232
Client:	Lesova Environmental Group
EDR Inquiry:	7571432.3
Order Date:	02/18/2024
Certification #:	37D8-4991-ACD5
Copyright	1942

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 22
Volume 6A, Sheet 21

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: 4001 4th Avenue
Address: 4001 4th Avenue
City, ST, ZIP: Brooklyn, NY 11232
Client: Lesova Environmental Group
EDR Inquiry: 7571432.3
Order Date: 02/18/2024
Certification #: 37D8-4991-ACD5
Copyright: 1926

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 6A, Sheet 21
Volume 6A, Sheet 22

0 Feet 150 300 600


N




Site Name: 4001 4th Avenue
Address: 4001 4th Avenue
City, ST, ZIP: Brooklyn, NY 11232
Client: Lesova Environmental Group
EDR Inquiry: 7571432.3
Order Date: 02/18/2024
Certification #: 37D8-4991-ACD5
Copyright: 1906

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 6, Sheet 29
Volume 6, Sheet 28


N




Site Name: 4001 4th Avenue
Address: 4001 4th Avenue
City, ST, ZIP: Brooklyn, NY 11232
Client: Lesova Environmental Group
EDR Inquiry: 7571432.3
Order Date: 02/18/2024
Certification #: 37D8-4991-ACD5
Copyright: 1888

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 6, Sheet 142a
Volume 6, Sheet 142

N

4001 4th Avenue

4001 4th Avenue

Brooklyn, NY 11232

Inquiry Number: 7571432.11

February 20, 2024

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

02/20/24

Site Name:

4001 4th Avenue
4001 4th Avenue
Brooklyn, NY 11232
EDR Inquiry # 7571432.11

Client Name:

Lesova Environmental Group
3611 14th Avenue, Suite 551
Brooklyn, NY 11218
Contact: Dhruvi Patel

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2019	1"=500'	Flight Year: 2019	USDA/NAIP
2015	1"=500'	Flight Year: 2015	USDA/NAIP
2011	1"=500'	Flight Year: 2011	USDA/NAIP
2008	1"=500'	Flight Year: 2008	USDA/NAIP
1995	1"=500'	Acquisition Date: January 01, 1995	USGS/DOQQ
1985	1"=500'	Flight Date: March 16, 1985	USDA
1980	1"=500'	Flight Date: July 25, 1980	NOAA
1976	1"=500'	Flight Date: October 29, 1976	USGS
1966	1"=500'	Flight Date: February 23, 1966	USGS
1961	1"=500'	Flight Date: April 12, 1961	EDR Proprietary Aerial Viewpoint
1954	1"=500'	Flight Date: February 27, 1954	USGS
1951	1"=500'	Flight Date: April 07, 1951	EDR Proprietary Aerial Viewpoint
1943	1"=500'	Flight Date: December 23, 1943	USC&GS
1940	1"=500'	Flight Date: April 06, 1940	EDR Proprietary Aerial Viewpoint
1924	1"=500'	Flight Date: July 01, 1924	FAIR

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.


Disclaimer - Copyright and Trademark Notice


This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.

Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.


Copyright 2024 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.


EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.



INQUIRY #: 7571432.11
YEAR: 2019
= 500'
N
EDR


INQUIRY #: 7571432.11
YEAR: 2015
= 500'
N
EDR


INQUIRY #: 7571432.11
YEAR: 2011
= 500'
N
EDR


INQUIRY #: 7571432.11
YEAR: 2008
= 500'
N
EDR


INQUIRY #: 7571432.11
YEAR: 1995
= 500'
N
EDR


INQUIRY #: 7571432.11
YEAR: 1985
= 500'
N
EDR


INQUIRY #: 7571432.11
YEAR: 1980
= 500'
N
EDR


INQUIRY #: 7571432.11
YEAR: 1976
= 500'
N
EDR



INQUIRY #: 7571432.11
YEAR: 1966
= 500'
N
EDR



INQUIRY #: 7571432.11
YEAR: 1961
= 500'
N
EDR


INQUIRY #: 7571432.11
YEAR: 1954
= 500'
N
EDR


INQUIRY #: 7571432.11
YEAR: 1951
= 500'
N
EDR


INQUIRY #: 7571432.11
YEAR: 1943
= 500'
N
EDR


INQUIRY #: 7571432.11
YEAR: 1940
= 500'
N
EDR


INQUIRY #: 7571432.11
YEAR: 1924
= 500'
N
EDR

4001 4th Avenue

4001 4th Avenue

Brooklyn, NY 11232

Inquiry Number: 7571432.4

February 16, 2024

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

02/16/24

Site Name:

4001 4th Avenue
4001 4th Avenue
Brooklyn, NY 11232
EDR Inquiry # 7571432.4

Client Name:

Lesova Environmental Group
3611 14th Avenue, Suite 551
Brooklyn, NY 11218
Contact: Dhruvi Patel

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Lesova Environmental Group were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# NA
Project: NA

Coordinates:

Latitude:	40.651717 40° 39' 6" North
Longitude:	-74.006618 -74° 0' 24" West
UTM Zone:	Zone 18 North
UTM X Meters:	583983.81
UTM Y Meters:	4500569.83
Elevation:	50.61' above sea level

Maps Provided:

2019	1925
2016	1905
2014, 2013	1900
1995	1898
1979, 1981	1897
1967	1891
1955, 1956	
1947	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2024 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2019 Source Sheets



Jersey City
2019
7.5-minute, 24000



Brooklyn
2019
7.5-minute, 24000

2016 Source Sheets



Jersey City
2016
7.5-minute, 24000



Brooklyn
2016
7.5-minute, 24000

2014, 2013 Source Sheets



Jersey City
2014
7.5-minute, 24000



Brooklyn
2013
7.5-minute, 24000

1995 Source Sheets



Brooklyn
1995
7.5-minute, 24000
Aerial Photo Revised 1977

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1979, 1981 Source Sheets



Brooklyn
1979
7.5-minute, 24000
Aerial Photo Revised 1977



Jersey City
1981
7.5-minute, 24000
Aerial Photo Revised 1976

1967 Source Sheets



Brooklyn
1967
7.5-minute, 24000
Aerial Photo Revised 1966



Jersey City
1967
7.5-minute, 24000
Aerial Photo Revised 1966

1955, 1956 Source Sheets



Jersey City
1955
7.5-minute, 24000
Aerial Photo Revised 1954



Brooklyn
1956
7.5-minute, 24000

1947 Source Sheets



Brooklyn
1947
7.5-minute, 24000
Aerial Photo Revised 1940



Jersey City
1947
7.5-minute, 24000
Aerial Photo Revised 1940

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1925 Source Sheets



Staten Island
1925
15-minute, 62500

1905 Source Sheets



Passaic
1905
30-minute, 125000

1900 Source Sheets



Brooklyn
1900
15-minute, 62500



Staten Island
1900
15-minute, 62500

1898 Source Sheets



Brooklyn
1898
15-minute, 62500



Staten Island
1898
15-minute, 62500

Topo Sheet Key


This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1897 Source Sheets



Brooklyn
1897
15-minute, 62500


1891 Source Sheets



STATEN ISLAND
1891
15-minute, 62500

Historical Topo Map

2019



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Jersey City, 2019, 7.5-minute
NE, Brooklyn, 2019, 7.5-minute

SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group

N

Historical Topo Map

2016



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Jersey City, 2016, 7.5-minute
NE, Brooklyn, 2016, 7.5-minute

SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group

N

Historical Topo Map

2014, 2013



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Jersey City, 2014, 7.5-minute
NE, Brooklyn, 2013, 7.5-minute

SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

NE, Brooklyn, 1995, 7.5-minute

SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Jersey City, 1981, 7.5-minute
NE, Brooklyn, 1979, 7.5-minute


SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group

N



This report includes information from the following map sheet(s).






TP, Jersey City, 1967, 7.5-minute
NE, Brooklyn, 1967, 7.5-minute

SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group





This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Jersey City, 1955, 7.5-minute
NE, Brooklyn, 1956, 7.5-minute

SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group

N

Historical Topo Map

1947



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Jersey City, 1947, 7.5-minute
NE, Brooklyn, 1947, 7.5-minute

SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group

N



UNMAPPED

This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Staten Island, 1925, 15-minute

SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group


N



UNMAPPED

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5



TP, Passaic, 1905, 30-minute

SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Staten Island, 1900, 15-minute
E, Brooklyn, 1900, 15-minute

SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Staten Island, 1898, 15-minute
E, Brooklyn, 1898, 15-minute

SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

E, Brooklyn, 1897, 15-minute

SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, STATEN ISLAND, 1891, 15-minute

SITE NAME: 4001 4th Avenue
ADDRESS: 4001 4th Avenue
Brooklyn, NY 11232
CLIENT: Lesova Environmental Group

N

APPENDIX E - EDR City Directory Listings

4001 4th Avenue
4001 4th Avenue
Brooklyn, NY 11232

Inquiry Number: 7571432.5
February 16, 2024

The EDR-City Directory Abstract

Environmental Data Resources Inc
6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at approximately five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1928 through current. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 200 feet of the target property.

Summary information obtained is provided in the text of this report.

RECORD SOURCES

The EDR City Directory Report accesses a variety of business directory sources, including Haines, InfoUSA, Polk, Cole, Bresser, and Stewart. Listings marked as EDR Digital Archive access Cole and InfoUSA records. The various directory sources enhance and complement each other to provide a more thorough and accurate report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	*Source*	*TP*	*Adjoining*	*Text Abstract*	*Source Image*
2020	EDR Digital Archive	X	X	X	-
2017	Cole Information	X	X	X	-
2014	Cole Information	X	X	X	-
2010	Cole Information	X	X	X	-
2005	Cole Information	X	X	X	-
	Hill-Donnelly Corporation	X	X	X	-
2000	Cole Information	X	X	X	-
1997	NYNEX	X	X	X	-
1995	Cole Information	X	X	X	-
1992	Cole Information	X	X	X	-
	NYNEX Informantion Resource Co.	X	X	X	-
1985	NYNEX Information Resources Company	X	X	X	-
1980	New York Telephone	-	X	X	-
1976	New York Telephone	X	X	X	-
1973	New York Telephone	X	X	X	-
1970	New York Telephone	X	X	X	-

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1965	New York Telephone	X	X	X	-
1960	New York Telephone	X	X	X	-
	New York Telephone Company	X	X	X	-
1949	New York Telephone Company	X	X	X	-
1945	New York Telephone	X	X	X	-
1940	New York Telephone	X	X	X	-
1934	R. L. Polk & Co.	X	X	X	-
1928	New York Telephone	X	X	X	-

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

4001 4th Avenue
Brooklyn, NY 11232

FINDINGS DETAIL

Target Property research detail.

4 AVE

4001 4 AVE

Year	Uses	Source
1997	Johnnys Auto Repair & Body Work	NYNEX

4TH AVE

4001 4TH AVE

Year	Uses	Source
2020	CHARLIE INC	EDR Digital Archive
	DANIEL RAY	EDR Digital Archive
2017	B & L GAS STATION ENTERPRISES INC	Cole Information
2014	B & L GAS STATION ENTERPRISES INC	Cole Information
2010	B & L GAS STATION ENTERPRISES	Cole Information
2005	BROOKLYN SERVICE STATION INC	Cole Information
	JOHNNYS AUTO REPAIR & BODY WORK	Cole Information
	Nor Glenn Svc Station	Hill-Donnelly Corporation
2000	JOHNNYS AUTO REPAIR & BODY WORK	Cole Information
	MY 4 CAB COMPANY	Cole Information
	SHIELA HACKIN CORPORATION	Cole Information
1997	H & S Service Ctr	NYNEX
1995	H & S SERVICE CTR	Cole Information
	H & S SVCE CTR	Cole Information
1992	H & S SERVICE CTR	Cole Information
	H & S SVCE CTR	Cole Information
	H & S SERVICE CTR BROOKLYN	NYNEX Informantion Resource Co.

FINDINGS

Year	Uses	Source
1992	H & S SVCE CTR	NYNEX Informantion Resource Co.
1985	H & S SVCE CTR	NYNEX Information Resources Company
1976	ALLAN BROS SVCE STA	New York Telephone
1973	Murray John	New York Telephone
	Stage Auto Svce	New York Telephone
1970	Elwood Svce Sta	New York Telephone
1965	Elwood Svce Sta	New York Telephone
1960	ELWOOD SVCE STA	New York Telephone
	Elwood Svce sta	New York Telephone Company
1949	Lambert Svce Sta	New York Telephone Company
1945	Lambert Svce Sta	New York Telephone
1940	Lambnets Svce Sta	New York Telephone
1934	TYDOL CHAIN INC GAS	R. L. Polk & Co.
1928	TYDOL CHAIN INC GAS STA	New York Telephone

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

40 972

415 40 972

Year	Uses	Source
1997	TEJADA Seferino	NYNEX

40 J

420 40 J

Year	Uses	Source
1960	KESSLER JOHN	New York Telephone
	Kessler John	New York Telephone Company

40TH

369 40TH

Year	Uses	Source
1934	BERINGER ALBIN H	R. L. Polk & Co.

382 40TH

Year	Uses	Source
1934	DEERY JOHN H	R. L. Polk & Co.

383 40TH

Year	Uses	Source
1934	OLSEN JUDITH HAIRDRSR R	R. L. Polk & Co.

385 40TH

Year	Uses	Source
1934	PAGE HANNAH H	R. L. Polk & Co.

403 40TH

Year	Uses	Source
1928	MONTANA JOS R	New York Telephone

FINDINGS

408 40TH

Year	Uses	Source
1928	CARBOY SADIE MRS R	New York Telephone

409 40TH

Year	Uses	Source
1985	HERNANDEZ S	NYNEX Information Resources Company
1980	TORRES JOYCE	New York Telephone
1976	HERNANDEZ M	New York Telephone
1960	GARLAND JOHN MRS	New York Telephone
	KENT RESINA V	New York Telephone
	MCLAUGHLIN M MRS	New York Telephone
1934	ANDERSON ALEX CARP H	R. L. Polk & Co.
	ANDERSON DAGMAR CLK R	R. L. Polk & Co.
	ANDERSON ELSINOR R	R. L. Polk & Co.
	ANDERSON OTTO LAB R	R. L. Polk & Co.
	CARBOY SADIE MRS H	R. L. Polk & Co.
	CARBOY WM CLK R	R. L. Polk & Co.
	NELSON FRED PNTR H	R. L. Polk & Co.
	PROSPECT POLING CO	R. L. Polk & Co.
	RICHTER A H	R. L. Polk & Co.
	SANANTONIO ROSE H	R. L. Polk & Co.
	THOMPSON DAVID	R. L. Polk & Co.
1928	LAMBERT E MRS STATNY	New York Telephone

411 40TH

Year	Uses	Source
1992	BALDWIN EDUARDO	NYNEX Informantion Resource Co.
	KHAKISADIGH FENDOON	NYNEX Informantion Resource Co.
1985	LANGLOIS I	NYNEX Information Resources Company
	MAGRO JACINTA	NYNEX Information Resources Company
	RIVERA LYDIA	NYNEX Information Resources Company
1976	CARBOY WM F	New York Telephone
1960	CARBOY SADIE MRS	New York Telephone
	CASSIDY ELIZ MRS	New York Telephone

FINDINGS

Year	Uses	Source
1960	FAHEY ELIZ	New York Telephone
	HARTMAN CHAS MRS	New York Telephone
1934	DORNIAK JOHN LAB R	R. L. Polk & Co.
	ELLIOTT ELLIAH LAN R	R. L. Polk & Co.
	GIBSON WM LAB H	R. L. Polk & Co.
	IVANY ROBT LAB H	R. L. Polk & Co.
	MACEY PHILIP LAB H	R. L. Polk & Co.
	SANKOFSKY JACOB LAB H	R. L. Polk & Co.
	SANKONLS ANTHONY LAB H	R. L. Polk & Co.
	SNOWDEN JOHN H	R. L. Polk & Co.
	WISEMAN GIDEON LAB H	R. L. Polk & Co.

412 40TH

Year	Uses	Source
1928	BERNTSEN LAURITS R	New York Telephone

413 40TH

Year	Uses	Source
1992	EGAN STEPHEN J	NYNEX Informantion Resource Co.
	LOGOZO CORINNE	NYNEX Informantion Resource Co.
	PHELAN NOREEN	NYNEX Informantion Resource Co.
1985	EGAN STEPHEN J	NYNEX Information Resources Company
1980	EGAN STEPHEN J	New York Telephone
1976	EGAN STEPHEN J	New York Telephone
1960	EGAN STEPHEN J	New York Telephone
	GERLACH ANDREW C JR	New York Telephone
	ROMANELLI ANNETTE	New York Telephone
1934	CONBOY DAVID COND H	R. L. Polk & Co.
	CONBOY WALTER CLK R	R. L. Polk & Co.
	CONBOY WM CLK R	R. L. Polk & Co.
	MAETRICH GEO LAB H	R. L. Polk & Co.
	PARIS EMBROIDERY AND MONOGRAM CO	R. L. Polk & Co.
	SKELLY PETER LAB H	R. L. Polk & Co.

FINDINGS

414 40TH

Year	*Uses*	*Source*
1992	LEON SERGIO	NYNEX Informantion Resource Co.
1985	ACEVEDO SUSANNA	NYNEX Information Resources Company
	LEON SERGIO	NYNEX Information Resources Company
1960	D ONOFRIO EDW	New York Telephone
1934	DEFELICE ARNOLD R	R. L. Polk & Co.
	DEFELICE CARMELA INSPR BEMIS BRO BAG CO R	R. L. Polk & Co.
	DEFELICE JOS CHAUF H	R. L. Polk & Co.
	DEFELICE LUCILLE R	R. L. Polk & Co.
	DEFELICE LULN CLIPPER BEMIS BROS BAG CO H	R. L. Polk & Co.
	MCDOWELL MARGT TEL OPR R	R. L. Polk & Co.
	POULSTON ETHEL V OPR R	R. L. Polk & Co.
	POULSTON WALTER CLK H	R. L. Polk & Co.
	POULSTON WM R	R. L. Polk & Co.

415 40TH

Year	*Uses*	*Source*
1992	PENA MANUEL	NYNEX Informantion Resource Co.
1980	BARTUCCELLI JAS	New York Telephone
1976	BARTUCCELLI JAS	New York Telephone
	SAVAIA R	New York Telephone
1960	PARIS EMBROIDERY & MONGRM CO	New York Telephone
	SAVAIA CHAS J	New York Telephone
	SAVAIA R EMBROIDERY	New York Telephone
1934	MELONE MARIO LAB R	R. L. Polk & Co.
1928	GIUFFRIDA C	New York Telephone
	PARIS EMBROIDERY MONOGRAM	New York Telephone

416 40TH

Year	*Uses*	*Source*
1934	JACOBSEN LILLIAN CLK R	R. L. Polk & Co.

FINDINGS

418 40TH

Year	Uses	Source
1960	GASPARINI ROSE T	New York Telephone
1934	ANDERSON WM H	R. L. Polk & Co.
	MCFARLAND ELLEN H	R. L. Polk & Co.
	SULLIVAN GERTUDE STUDENT R	R. L. Polk & Co.
	SULLIVAN JOHN R	R. L. Polk & Co.
	SULLIVAN JOHN W R	R. L. Polk & Co.
1928	MCFARLAND E E MRS R	New York Telephone

420 40TH

Year	Uses	Source
1992	KEHOE ANN MARIE	NYNEX Informantion Resource Co.
	SARKER SHAHJAHAN	NYNEX Informantion Resource Co.
	SCHREIBER FLORENCE	NYNEX Informantion Resource Co.
	SMALL F	NYNEX Informantion Resource Co.
1985	BOCHENSKI E	NYNEX Information Resources Company
	SCHREIBER FLORENCE	NYNEX Information Resources Company
1976	ENRIQUEZ CARL	New York Telephone
	GOLDSBURY MARGARET V	New York Telephone
	PAGAN P	New York Telephone
	SCHREIBER HENRY	New York Telephone
1960	BERGAMINI R M	New York Telephone
	CARINI ANTHONY	New York Telephone
	FARRIS PASQUALE	New York Telephone
	GAVASSINO ANGELO	New York Telephone
	SANTURRO ADA	New York Telephone
1934	BARBIERI JOHN CLK R	R. L. Polk & Co.
	BARBIERI LINDA R	R. L. Polk & Co.
	BARBIERI LOUISE CASH R	R. L. Polk & Co.
	BIRGAMINI PETER JANITOR H	R. L. Polk & Co.
	BONDONO ALPHONSE P H	R. L. Polk & Co.
	CARMONA JOS R CLK H	R. L. Polk & Co.
	COSTELLI HENRY COOK H	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	FOSSA ALPHONSE R	R. L. Polk & Co.
	HELEN H	R. L. Polk & Co.
	JAS LAB R	R. L. Polk & Co.
	VINCENZA STUDENT R	R. L. Polk & Co.
	MACELLARI HENRIETTA FCTYWKR R	R. L. Polk & Co.
	MACELLARI LOUIS FCTYWKR R	R. L. Polk & Co.
	ANGELO LAB H	R. L. Polk & Co.
	RAVERA SILVLO MECH R	R. L. Polk & Co.
1928	MANNING J A R	New York Telephone

422 40TH

Year	Uses	Source
1985	SADA J P	NYNEX Information Resources Company
1976	SADA M	New York Telephone
1960	SADA EDW A	New York Telephone

424 40TH

Year	Uses	Source
1992	CARMELLO C	NYNEX Informantion Resource Co.
1985	CARMELLO C	NYNEX Information Resources Company
1976	DE VITO WM N	New York Telephone
	MATERA MICHAEL JR	New York Telephone
1960	DE VITO WM N	New York Telephone
1934	BASSILIA PERITZ R	R. L. Polk & Co.
	FERBONIA MARIA H	R. L. Polk & Co.
	KIRSCHHOFF EDW K CLK R	R. L. Polk & Co.
	KIRSCHHOFF FREDK JR CHAUF R	R. L. Polk & Co.
	VINCE LINA H	R. L. Polk & Co.
	VINCI LENA CROCHET WKR R	R. L. Polk & Co.

40TH AVE

400 40TH AVE

Year	Uses	Source
1965	Moore Pal	New York Telephone

FINDINGS

40TH ST

391 40TH ST

Year	Uses	Source
2005	Carty Raphael	Hill-Donnelly Corporation

409 40TH ST

Year	Uses	Source
2020	FAUSTO & CHARLY BARBER	EDR Digital Archive
	YARILENY DELAROSA	EDR Digital Archive
	ALEYDA PARRA	EDR Digital Archive
	FABIO GONZALEZ	EDR Digital Archive
2017	ELIZABETH NAZARIO	Cole Information
	GLENNYS REYES	Cole Information
	ERIKA FERREDINO	Cole Information
	JOHANNA PINOS	Cole Information
	DARION ENCARNACION	Cole Information
2014	YARILENY DELAROSA	Cole Information
	JUANA PARRA	Cole Information
	MYRNA SANTIAGO	Cole Information
	JOSE RODRIGUEZ	Cole Information
	FABIO GONZALEZ	Cole Information
2010	ASTACIA CABAN	Cole Information
	JUANA PARRA	Cole Information
	MYRNA SANTIAGO	Cole Information
2005	Astacia Caban is	Hill-Donnelly Corporation
	Fausto & Charly Barber is	Hill-Donnelly Corporation
	h Parra A	Hill-Donnelly Corporation
	Parra Juanao	Hill-Donnelly Corporation
	AB 99 CENT STORE	Cole Information
	A PARRA	Cole Information
	CHARLES TORIBIO	Cole Information
	VINCENT SHARP	Cole Information
2000	ROSEMARY HERNANDEZ	Cole Information

FINDINGS

Year	Uses	Source
2000	JUNIOR CLNRS & TLRS	Cole Information
	JUNIOR HOS CLEANERS & TAILORS	Cole Information
	F NIEVES	Cole Information
	R HERNANDEZ	Cole Information
1997	ALBAN Maria	NYNEX
	SALAZAR Ulbio	NYNEX
1973	Goldy M	New York Telephone
	Talavera Pedro	New York Telephone
1949	Di Serio Pasquale	New York Telephone Company
	Faulkner Alice Mrs	New York Telephone Company
	Rossi Michl	New York Telephone Company
1940	Carboy Sadie Mrs	New York Telephone
	Kirkham W Mrs statnry	New York Telephone

411 40TH ST

Year	Uses	Source
2020	YVETTE SADIGH	EDR Digital Archive
	NISAN LESSANE	EDR Digital Archive
	FERIDOON SADIGH	EDR Digital Archive
	ATESH KHAKISADIGH	EDR Digital Archive
	JIMMY VELEZ	EDR Digital Archive
	NANCY CONTRERAS	EDR Digital Archive
	EDWARD BELLIARD	EDR Digital Archive
	MARCOS RAMOS	EDR Digital Archive
2017	FERIDOON SADIGH	Cole Information
	EDWARD BELLIARD	Cole Information
	NANCY CONTRERAS	Cole Information
2014	FERIDOON SADIGH	Cole Information
	NICHOLAS PONCE	Cole Information
	EDWARD BELLIARD	Cole Information
	STARSHA GILL	Cole Information
	JIMMY VELEZ	Cole Information
2010	ALEXANDRA GARCIA	Cole Information

FINDINGS

Year	Uses	Source
2010	FERIDOON SADIGH	Cole Information
	JORGE NAVARRETE	Cole Information
	JIMMY VELEZ	Cole Information
2005	h Khakisadlgh Feridoon AV 718 854 557 C	Hill-Donnelly Corporation
	FERIDOON SADIGH	Cole Information
	JESSICA WANKA	Cole Information
	FERIDOON KHAKISADIGH	Cole Information
	JIMMY VELEZ	Cole Information
2000	F KHAKISADIGH	Cole Information
	EDGAR LORIA	Cole Information
1997	KHAKISADIGH Feridoon	NYNEX
1992	KHAKISADIGH, FERIDOON	Cole Information
	BALDWIN, EDUARDO	Cole Information
	MATOS, MARIA	Cole Information
1973	Carboy Wm F	New York Telephone
	Mieles John	New York Telephone
1970	Hartman Chas Mrs	New York Telephone
1965	Carboy Sadie Mrs	New York Telephone
	Hartman Chas Mrs	New York Telephone
1960	Carboy Sadie Mrs	New York Telephone Company
	Hartman Chas Mrs	New York Telephone Company
1949	Carboy Sadie Mrs	New York Telephone Company
	Fahey Eliz	New York Telephone Company
	Hartman Chas Mrs	New York Telephone Company
	Koop Irene Mrs	New York Telephone Company
1945	Hartman Chas Mrs	New York Telephone

413 40TH ST

Year	Uses	Source
2020	STEPHANIE LOGOZO	EDR Digital Archive
	CORINNE PHELAN	EDR Digital Archive
	THOMAS PHELAN	EDR Digital Archive
	PATRICIA PHELAN	EDR Digital Archive

FINDINGS

Year	Uses	Source
2020	DANIELLE LOGOZO	EDR Digital Archive
	THOMAS LOGOZO	EDR Digital Archive
2017	TAYLOR LOGOZO	Cole Information
	STEPHANIE LOGOZO	Cole Information
	THOMAS PHELAN	Cole Information
2014	CORINNE LOGOZO	Cole Information
	JAMES PHELAN	Cole Information
2010	JAMES PHELAN	Cole Information
2005	h Egan Stephen 3 AV	Hill-Donnelly Corporation
	h Phelan Corinne AO	Hill-Donnelly Corporation
	Phelan James	Hill-Donnelly Corporation
	Phelan Thomas	Hill-Donnelly Corporation
	CORINNE PHELAN	Cole Information
	STEPHEN EGAN	Cole Information
	JAMES PHELAN	Cole Information
2000	STEPHEN J EGAN	Cole Information
	CORINNE PHELAN	Cole Information
	THOMAS PHELAN	Cole Information
	STEPHEN EGAN	Cole Information
	THOMAS PHELAN	Cole Information
1997	EGAN Stephen J	NYNEX
	LOGOZO Corinne	NYNEX
	PHELENA Thomas	NYNEX
1992	PHELAN, NOREEN	Cole Information
	LOGOZO, CORINNE	Cole Information
	EGAN, STEPHEN J	Cole Information
1973	Egan Stephen J	New York Telephone
	Gerlach Andrew C Jr	New York Telephone

414 40TH ST

Year	Uses	Source
2020	JUAN SANCHEZ	EDR Digital Archive
	KENNY SANCHEZ	EDR Digital Archive

FINDINGS

Year	Uses	Source
2020	GETZEMANI RENDON	EDR Digital Archive
	LOIDA JIMENEZ	EDR Digital Archive
	GABRIELA NORIEGA	EDR Digital Archive
	EDWIN SANCHEZ	EDR Digital Archive
2017	FRANCISCO LOPEZ	Cole Information
	GETZEMANI RENDON	Cole Information
	GABRIELA NORIEGA	Cole Information
	EDWIN SANCHEZ	Cole Information
2014	JUAN SANCHEZ	Cole Information
2010	JUAN SANCHEZ	Cole Information
	FREDDY AGUILAR	Cole Information
	ANGEL RIVERA	Cole Information
2005	h Rivera Angel	Hill-Donnelly Corporation
	H Sanchez Juan v 718 437 255 C	Hill-Donnelly Corporation
	JUAN SANCHEZ	Cole Information
	LOIDA RIVERA	Cole Information
	HAYLIE CORREA	Cole Information
2000	ANGEL RIVERA	Cole Information
	JUAN SANCHEZ	Cole Information
	JUAN SANCHEZ	Cole Information
	ANGEL RIVERA	Cole Information
1997	PYRDOL Joanne	NYNEX
1992	LEON, SERGIO	Cole Information
1945	Savaia R embrol Irry	New York Telephone

415 40TH ST

Year	Uses	Source
2020	ARSENIO AYBAR	EDR Digital Archive
	NATIVIDAD BRITO	EDR Digital Archive
	LUIS BRITO	EDR Digital Archive
	HENRY AYBAR	EDR Digital Archive
2017	NATIVIDAD BRITO	Cole Information
	HENRY AYBAR	Cole Information

FINDINGS

Year	*Uses*	*Source*
2017	LUIS BRITO	Cole Information
2014	NATIVIDAD BRITO	Cole Information
	HENRY AYBAR	Cole Information
	VIRGINIA GOMEZ	Cole Information
2010	ARSENIO AYBAR	Cole Information
	NATIVIDAD BRITO	Cole Information
2005	h Aybar Arsenio v	Hill-Donnelly Corporation
	H Brito Natividad AO	Hill-Donnelly Corporation
	ARSENIO AYBAR	Cole Information
	CLARA MERCEDEZ	Cole Information
	NATIVIDAD BRITO	Cole Information
	SASHA LONGO	Cole Information
	FRANCISCO CEPEDA	Cole Information
2000	DYHALMA ANAYA	Cole Information
	NURYS AYBAR	Cole Information
	STANLEY JEANFRANCOIS	Cole Information
	DYHALMA ANAYA	Cole Information
	CLARA MERCEDES	Cole Information
1997	ANAYA Dyhalma	NYNEX
1992	PENA, MANUEL	Cole Information
1973	Bartuccelli Jas	New York Telephone
	Paris Embroidery & Mongrm CO	New York Telephone
	Savaia R embroldery	New York Telephone
1970	Savaia R embroidery	New York Telephone
1965	Savaia R embroidery	New York Telephone
1960	Paris Embroidery & Mongrm Co	New York Telephone Company
	Savaia R embroidery	New York Telephone Company
1949	Paris Erabroidery & Mongrm Co	New York Telephone Company
	Savaia R embroidery	New York Telephone Company
1945	Paris Embroidery & Mongrm Co	New York Telephone
1940	Paris Embroidery & Wongrm Co	New York Telephone
	Savata R embroidery	New York Telephone

FINDINGS

418 40TH ST

Year	Uses	Source
2020	ROBERT HANSEN	EDR Digital Archive
	BRETT GRENNAN	EDR Digital Archive
	TODD GRENNAN	EDR Digital Archive
	SARAH BIRIA	EDR Digital Archive
2017	TODD GRENNAN	Cole Information
	CHRISTINE BELL	Cole Information
2014	GEORGIA SIEGCHRIST	Cole Information
2010	DOREEN MIRANDA	Cole Information
2005	Hn Mccoy SR R	Hill-Donnelly Corporation
	DOREEN MIRANDA	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information
1997	ESCOBAR J	NYNEX

420 40TH ST

Year	Uses	Source
2020	NANCY OSHAUGHNESSY	EDR Digital Archive
	ELIZABETH CALIXTO	EDR Digital Archive
	RYAN HOLMES	EDR Digital Archive
	MARILYN GONZALEZ	EDR Digital Archive
	LAURA GONSALEZ	EDR Digital Archive
	JENNY WONG	EDR Digital Archive
2017	RUBEN GUTIERREZ	Cole Information
	HECTOR GONZALEZ	Cole Information
	JUAN BRAVO	Cole Information
	SAMUEL MUNOZ	Cole Information
	FRANCISCA SANTIAGO	Cole Information
	B SHLYAKHTER	Cole Information
2014	RUBEN GUTIERREZ	Cole Information
	CARLOS RUIZ	Cole Information
	FRANCISCA SANTIAGO	Cole Information
	SID KOSSOWSKY	Cole Information
	VICENTE TEPANCAL	Cole Information

FINDINGS

Year	Uses	Source
2014	FELICIAN VILLA	Cole Information
2010	RUBEN GUTIERREZ	Cole Information
	LUIS CALIXTO	Cole Information
	FRANCISCA SANTIAGO	Cole Information
	VICENTE TEPANCAL	Cole Information
	FELICIAN VILLA	Cole Information
2005	Santiago Francisca v	Hill-Donnelly Corporation
	Tepancal Vicente v	Hill-Donnelly Corporation
	Villa Feliciano vv 718 871 064 C	Hill-Donnelly Corporation
	JNN DISTRIBUTORS INC	Cole Information
	ANA HERNANDEZ	Cole Information
	PALACIOS RAYMUNDO	Cole Information
	WILLIE TORRES	Cole Information
	ROCIO ARELLANO	Cole Information
	MICHAEL MAINENTI	Cole Information
	FRANCISCA SANTIAGO	Cole Information
	ENRIQUE GALVAN	Cole Information
	CARLOS PESANTEZ	Cole Information
	VICENTE TEPANCAL	Cole Information
	NANCY FALES	Cole Information
	GERMAN ARAGON	Cole Information
	HILDA REID	Cole Information
	JOSE CASQUERA	Cole Information
2000	CARMEN MORALES	Cole Information
	JOHN SCHREIBER	Cole Information
	CARMEN MORALES	Cole Information
	JOHN SCHREIBER	Cole Information
1997	FALES Nancy	NYNEX
	KEHOE Marie	NYNEX
	SCHREIBER Florence	NYNEX
	SHAHJAHAN Sarker	NYNEX
1992	SMALL, F	Cole Information

FINDINGS

Year	Uses	Source
1992	SCHREIBER, FLORENCE	Cole Information
	MUKUL, MOHAMMAD	Cole Information
	KEHOE, MARIE	Cole Information
1973	Giufti G	New York Telephone
	Santurro A	New York Telephone
	Schreiber Henry	New York Telephone
1949	Bergamini R M	New York Telephone Company
	Gamboni Frank J	New York Telephone Company
	Kessler John	New York Telephone Company
	Moretti Josephine	New York Telephone Company

422 40TH ST

Year	Uses	Source
2020	SAMANTHA SANTIAGO	EDR Digital Archive
	DESTINY HERNANDEZ	EDR Digital Archive
	BERNABE GONZALEZ	EDR Digital Archive
2017	SAMANTHA SANTIAGO	Cole Information
2014	GONZALEZ BERNABE	Cole Information
2010	BERNABE GONZALEZ	Cole Information
2005	No Current Listing	Hill-Donnelly Corporation
	GONZALEZ BERNABE	Cole Information
1949	Berryman Wm J	New York Telephone Company

424 40TH ST

Year	Uses	Source
2020	SHEZHAO HUANG	EDR Digital Archive
	SHUHONG RONG	EDR Digital Archive
	BI HUANG	EDR Digital Archive
	ZHAO SHE	EDR Digital Archive
	ALEX HUANG	EDR Digital Archive
	HUI HUANG	EDR Digital Archive
	FANG WU	EDR Digital Archive
2017	ZHAO SHE	Cole Information
	ALEX HUANG	Cole Information

FINDINGS

Year	Uses	Source
2014	BI HUANG	Cole Information
	ZHAO SHE	Cole Information
2010	ZHAO SHE	Cole Information
	JENNY HUANG	Cole Information
	HUI HUANG	Cole Information
2005	H Huang Hui Bing Number	Hill-Donnelly Corporation
	h Wu Jenny	Hill-Donnelly Corporation
	JENNY WU	Cole Information
	ZHAO SHE	Cole Information
	HUI HUANG	Cole Information
2000	HUI B HUANG	Cole Information
	JENNY WU	Cole Information
	JENNY WU	Cole Information
	HUI HUANG	Cole Information
1973	Corvaglia G	New York Telephone
	De Vito Wm N	New York Telephone
1949	Quinn John J	New York Telephone Company
1945	Abrahamsen Marion Mrs	New York Telephone
	Terrett John Mrs	New York Telephone
1940	Greenberg Kitty Miss	New York Telephone
	Perelson Bernard E	New York Telephone

426 40TH ST

Year	Uses	Source
1949	Aba Inc Almaz Mrs	New York Telephone Company

44TH AVE

3949 44TH AVE

Year	Uses	Source
1934	STUDER HANNAH TCHR PS 29 R BQ	R. L. Polk & Co.

FINDINGS

4TH

3919 4TH

Year	Uses	Source
1934	CUPO JOSEPHINE HAIRDRSR H	R. L. Polk & Co.

3946 4TH

Year	Uses	Source
1934	SUSSMAN JULIUS USHER R	R. L. Polk & Co.

3949 4TH

Year	Uses	Source
1934	KAPLAN ROSE MRS R	R. L. Polk & Co.

3952 4TH

Year	Uses	Source
1934	THIERER ISAAC TAILOR H	R. L. Polk & Co.

4TH AVE

3907 4TH AVE

Year	Uses	Source
2020	BALTAZAR KEVIN E	EDR Digital Archive
	NEW YORK SPINE INSTITUTE	EDR Digital Archive
	TO HARELL PT	EDR Digital Archive
	DHD MEDICAL PC	EDR Digital Archive
	DIERON JOSEPH T	EDR Digital Archive
	SYNERGY MEDICAL PRACTICE PC	EDR Digital Archive

3913 4TH AVE

Year	Uses	Source
2020	HISPANO ENVIO MULTISERVICE CRP	EDR Digital Archive

3917 4TH AVE

Year	Uses	Source
2020	TAQUERIA LEL MAGUEY	EDR Digital Archive

FINDINGS

3918 4TH AVE

Year	Uses	Source
2020	EXPRESS BROOKLYN TILE LLC	EDR Digital Archive

3919 4TH AVE

Year	Uses	Source
2020	3919 KANG DA LLC	EDR Digital Archive
	NG WU LILEA MARIA	EDR Digital Archive
	BERKYS VIZCAINO	EDR Digital Archive
	HEYDI GUEVARA	EDR Digital Archive
	ALYA ALGHAZEER	EDR Digital Archive
	ALADEEN ALGHAZEER	EDR Digital Archive
	RICHARD JENKINS	EDR Digital Archive
	NAJEEB ALGHAZEER	EDR Digital Archive
	ARIF ALGHAZEER	EDR Digital Archive
	LINA GARCIA	EDR Digital Archive
2017	BERKYS VIZCAINO	Cole Information
	LINA GARCIA	Cole Information
2014	ARIF ALGHAZEER	Cole Information
2010	STAR	Cole Information
	DANNY FLORES	Cole Information
	LINA GARCIA	Cole Information
	ARIF ALGHAZEER	Cole Information
	EAMAN ALLAHABI	Cole Information
2005	Aighazeer Arif	Hill-Donnelly Corporation
	Estetica Isabel Unisex is 01oi	Hill-Donnelly Corporation
	Flores Danny	Hill-Donnelly Corporation
	Garcia Lina	Hill-Donnelly Corporation
	h Theagene Daniel	Hill-Donnelly Corporation
	ESTETICA ISABEL UNISEX	Cole Information
	AURELIO GARCIA	Cole Information
	GLADYS GONZALEZ	Cole Information
	EDMUNDO GURBILLON	Cole Information
	ABDO AHMED	Cole Information

FINDINGS

Year	Uses	Source
2005	DANNY FLORES	Cole Information
	LIZNETTE GURBILLON	Cole Information
	IBELISSE RIVAS	Cole Information
	ARIF ALGHAZEER	Cole Information
	DANIEL THEAGENE	Cole Information
	H JAMAI	Cole Information
2000	A1 PERFORMANCE REALTY COMPANY	Cole Information
	PERFORMANCE REALTY	Cole Information
	LICAUSI ANTHONY J	Cole Information
	REYES JENNY DDS	Cole Information
	PAOLA GIRALDO	Cole Information
	MAMNUEL GONZALEZ	Cole Information
1997	A One Performance Realty Co	NYNEX
	Diegeo Travel Svce	NYNEX
	Licausi Anthony J	NYNEX
	Performance Realty	NYNEX
	Proformance Realty	NYNEX
	Reyes Dental Office	NYNEX
	GONZALEZ M	NYNEX
	HERNANDEZ Jose	NYNEX
1995	LICAUSI, ANTHONY J	Cole Information
	PERFORMANCE REALTY	Cole Information
	PROFORMANCE REALTY	Cole Information
	REYES DENTAL OFFICE	Cole Information
	A1 PERFORMANCE REALTY CO	Cole Information
1992	A 1 PERFORMANCE	NYNEX Informantion Resource Co.
	A1 PERFORMANCE REALTY CO	NYNEX Informantion Resource Co.
	GONZALEZ M	NYNEX Informantion Resource Co.
	HERNANDEZ JOSE	NYNEX Informantion Resource Co.
	LICAUSI ANTHONY J	NYNEX Informantion Resource Co.
	PERFORMANCE REALTY	NYNEX Informantion Resource Co.
	PROFORMANCE REALTY	NYNEX Informantion Resource Co.

FINDINGS

Year	Uses	Source
1992	LICAUSI, ANTHONY J	Cole Information
	PERFORMANCE REALTY	Cole Information
	PROFORMANCE REALTY	Cole Information
	A1 PERFORMANCE REALTY CO	Cole Information
	HERNANDEZ, JOSE	Cole Information
	GONZALEZ, M	Cole Information
1985	CASH REGISTER REPAIR	NYNEX Information Resources Company
1976	ACEVEDO DAVID	New York Telephone
	LOPEZ ALVIN	New York Telephone
	MUNOZ ARTURO	New York Telephone
1973	Acevedo David	New York Telephone
	Munoz Arturo	New York Telephone
	Sokoloski H M	New York Telephone
1970	Acevedo David	New York Telephone
	Munoz Arturo	New York Telephone
1965	Astarita Jas J rl est ins	New York Telephone
	Patsys Fruits & Vegetables	New York Telephone
	Rosario Manuel	New York Telephone
1960	ASTARITA JAS J RL EST INS	New York Telephone
	CAHILL BERTHA	New York Telephone
	PATSYS FRUITS & VEGETABLES	New York Telephone
	Astarita Jas J rl est Ins	New York Telephone Company
	Cahill Bertha	New York Telephone Company
	Patsys Fruits & Vegetables	New York Telephone Company
1949	Astarita Jas J rl est Ins	New York Telephone Company
	Farnell Fred M ins	New York Telephone Company
	Kastanos Christ	New York Telephone Company
1945	Astarita Jas J rl est ins	New York Telephone
	Farnell Fred ins	New York Telephone
1940	Astarita Jas J rl est ins	New York Telephone
	Auto Svce Radiatr Co	New York Telephone
1934	REIS CHARLOTTE R	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	REIS GEO ELECTN H	R. L. Polk & Co.
	REIS JOS LAB R	R. L. Polk & Co.
	RYAN WM P ICE R	R. L. Polk & Co.
	TAYLOR CHRISTOPHER LAB R	R. L. Polk & Co.
	TAYLOR FRED LAB H	R. L. Polk & Co.
	TAYLOR HELEN CLK R	R. L. Polk & Co.
	WALSH JOHN LAB H	R. L. Polk & Co.
1928	CARDOZO EDW RL EST	New York Telephone
	KOWALSKI PETER STORAGE BATRS	New York Telephone

3921 4TH AVE

Year	Uses	Source
2017	STOP & BUY GROCERY	Cole Information
2014	STOP & BUY GROCERY	Cole Information
	JUANITA & MECHY HAIR SALON	Cole Information
2010	CARMENS HAIR STYLISTS	Cole Information
	STOP & BUY DELI GROCERY	Cole Information
2005	Carmens Hair Stylists i s	Hill-Donnelly Corporation
1997	Fortieth Street Auto Parts	NYNEX
1995	FORTIETH STREET AUTO PARTS	Cole Information
1992	FORTIETH STREET AUTO PARTS	NYNEX Informantion Resource Co.
	FORTIETH STREET AUTO PARTS	Cole Information
1985	FORTIETH STREET AUTO PARTS	NYNEX Information Resources Company
1980	VARELA AUTO PARTS CORP	New York Telephone
1940	Daniels A S ignitn	New York Telephone
1934	DANIELS ALF S AUTO SUPPLIES	R. L. Polk & Co.
	RIDGE BATTERY CO	R. L. Polk & Co.
1928	ATLANTIC MOTOR CAR CO	New York Telephone

3923 4TH AVE

Year	Uses	Source
2010	JUANA PARRA	Cole Information
1976	DYNAMIC AWARDS INC	New York Telephone
1965	Quality Dairy	New York Telephone

FINDINGS

Year	Uses	Source
1960	QUALITY DAIRY	New York Telephone
	Quality Dairy	New York Telephone Company
1945	Auto Svce Radiator Co	New York Telephone

3949 4TH AVE

Year	Uses	Source
1934	WHITE JOHN H	R. L. Polk & Co.

3970 4TH AVE

Year	Uses	Source
1980	GONZALEZ CARMELO	New York Telephone

4000 4TH AVE

Year	Uses	Source
1928	MENZE GEO W R	New York Telephone

4004 4TH AVE

Year	Uses	Source
2020	SUNSET PARK PREP SCHOOL	EDR Digital Archive
	CENTER FOR FAMILY LIFE AT DWY	EDR Digital Archive
	LMCMC	EDR Digital Archive
	ANDRES MARTINEZ	EDR Digital Archive
2017	DEWEY MS	Cole Information
	MS 821 SUNSET PARK PREP SCHOOL	Cole Information
	CITY OF NEW YORK	Cole Information
	CENTER FOR FAMILY LIFE AT DEWEY	Cole Information
2014	DEWEY MS	Cole Information
	MS 821 SUNSET PARK PREP SCHOOL	Cole Information
	CITY OF NEW YORK	Cole Information
	CENTER FOR FAMILY LIFE AT DEWEY	Cole Information
2010	MIDDLE SCHOOL 821	Cole Information
	LUTHERAN MEDICAL CTR	Cole Information
	MIDDLE SCHOOL 136	Cole Information
	BROOKLYN SCHOOL DISTRICT 15	Cole Information
2005	Center For Family Life Dewey	Hill-Donnelly Corporation

FINDINGS

Year	Uses	Source
2005	Hispanic Young Peoples Altern	Hill-Donnelly Corporation
	Lakeside Family & Children Svc	Hill-Donnelly Corporation
	Middle School	Hill-Donnelly Corporation
	Middle School	Hill-Donnelly Corporation
	TS 136	Cole Information
	UNITED PUERTO RICAN ORGN OF SUNSET P	Cole Information
	C O DEWEY JUNIOR HIGH SCHOOL 136	Cole Information
2000	HISPANIC YOUNG PEOPLES CHORUS	Cole Information
	UNITED PUERTO RICAN ORGANIZATION OF SUNSET PARK	Cole Information
	NEW YORK CITY OF EDUCATION	Cole Information
	ROBERT SPEIGER	Cole Information
	CENTER FOR FAMILY LIFE AT DEWEY	Cole Information
	LAKESIDE FAMILY & CHILDREN SERVICES DMH PROGRAMS	Cole Information
1997	Center For Family Life At Dew ey	NYNEX
	Center For Family Life At Dew ey	NYNEX
	Hispanic Young Peoples Chorus	NYNEX
	Orlando John custodan	NYNEX
	United Puerto Rican Organization Of Sunset Park	NYNEX
1995	NYC EDUCATION-COMMUNITY SCHOOL BOARDS-SCHOOLS-JUNIOR HIGH & INTERMED-DEWEY CHARLES Q JHS 1366	Cole Information
	CENTER FOR FAMILY LIFE AT DEWEY	Cole Information
	UNITED PUERTO RICAN ORGANIZATION OF SUNSET PARK	Cole Information
	HISPANIC YOUNG PEOPLES' CHORUS	Cole Information
	ORLANDO, JOHN, CUSTODIAN	Cole Information
1992	D ALESSIO RONALD	NYNEX Informantion Resource Co.
	CENTER FOR FAMILY LIFE AT DEWEY	Cole Information
	NYC EDUCATION-COMMUNITY SCHOOL BOARDS-SCHOOLS-JUNIOR HIGH & INTERMED-DEWEY CHARLES Q JHS 136	Cole Information
	ORLANDO, JOHN, CUSTODIAN	Cole Information
1985	ASTARITA FRANK	NYNEX Information Resources Company

FINDINGS

Year	Uses	Source
1976	NEW YORK CITY OF EDUCATION CITY BOARD OF BROOKLYN COMMUNITY SCHOOL DISTRICT	New York Telephone
1973	Dewey Charles O	New York Telephone
	No	New York Telephone
1970	NEW YORK EDUCATION BOARD Junior High Schl Reading Coordntor	New York Telephone
1965	NY CENTRAL SYSTEM EDUCATION BOARD OF Junior High Schl Reading Coordentor	New York Telephone

4008 4TH AVE

Year	Uses	Source
1985	ASSOCIATED SUPERMARKET	NYNEX Information Resources Company

4011 4TH AVE

Year	Uses	Source
1934	CARLSON BERGER ELECTN R	R. L. Polk & Co.

4013 4TH AVE

Year	Uses	Source
2020	SAM'S CAR WASH	EDR Digital Archive
2017	SAMUELS CAR EMPORIUM INC	Cole Information
	SAMS CAR WASH	Cole Information
2014	SAMS CAR WASH	Cole Information
2010	BATAN TOWING SVC	Cole Information
	SAMS CAR WASH	Cole Information
	SAMUELS CAR EMPORIUM INC	Cole Information
2005	Batan Towing Svc i	Hill-Donnelly Corporation
	Elsaun Inc	Hill-Donnelly Corporation
	Sams Car Wash	Hill-Donnelly Corporation
	1ST ST	Hill-Donnelly Corporation
	ELSAUN INC	Cole Information
2000	ELSAUN INCORPORATED	Cole Information
	ELSAUN INCORPORATED	Cole Information
1997	Elsant Inc	NYNEX
1995	ECUADOR SVCE STA INC	Cole Information

FINDINGS

Year	Uses	Source
1995	BORIS AUTO PARTS & REPR	Cole Information
1992	BORIS AUTO PARTS & REPR	NYNEX Informantion Resource Co.
	BORIS AUTO PARTS & REPR	NYNEX Informantion Resource Co.
	ECUADOR SVCE STA INC	NYNEX Informantion Resource Co.
	ECUADOR SVCE STA INC	Cole Information
	BORIS AUTO PARTS & REPR	Cole Information
	BATAN TOWING SERVICE INC	Cole Information
1985	BORIS AUTO PARTS & REPR	NYNEX Information Resources Company
	ECUADOR SVCE STA INC	NYNEX Information Resources Company
1976	DUFINE HARRY	New York Telephone
	LASTING SVCE CENTER INC	New York Telephone
1970	Erasmus Svce Stas	New York Telephone
	Waljean Svce Sta Inc	New York Telephone
1965	Waljean Svce Sta Inc	New York Telephone
	Waljean Svce Stas Inc	New York Telephone
1960	ALANCLIF SVCE STAS INC	New York Telephone
	ALANCLIF SVCE STAS INC	New York Telephone
	BORO PLUMBING & HEATING CORP	New York Telephone
	Alanclif Svce Stas Inc	New York Telephone Company
	Alanclif Svce Stas Inc	New York Telephone Company
	Boro Plumbing & Heating Corp	New York Telephone Company
1949	Alanclif Gas & Svce Sta	New York Telephone Company
	ALANCLIF GAS & SVCE STA	New York Telephone Company
1940	Alanclif Gas & Svce Sta	New York Telephone
1934	ALANCHF GAS & SERVICE STATION INC CLIFFORD A GOLDBERG PRES GAS STATION	R. L. Polk & Co.
	SEEDMAN S CERTIFIED STORES	R. L. Polk & Co.
1928	ALANCLIF GAS & SERVICE STA	New York Telephone

4015 4TH AVE

Year	Uses	Source
1965	Johnson Sophihe B Mrs	New York Telephone

FINDINGS

4017 4TH AVE

Year	*Uses*	*Source*
1934	HELEN GARMENT WKR	R. L. Polk & Co.

4022 4TH AVE

Year	*Uses*	*Source*
1928	PARIS CHAS E LWYR	New York Telephone

4024 4TH AVE

Year	*Uses*	*Source*
1970	Longo Laura	New York Telephone

4TH ST

3950 4TH ST

Year	*Uses*	*Source*
1973	Lund L F	New York Telephone

FINDINGS

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
369 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
382 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
383 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
385 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
3907 4TH AVE	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
391 40TH ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3913 4TH AVE	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3917 4TH AVE	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3918 4TH AVE	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3919 4TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
3919 4TH AVE	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
3919 4TH AVE	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3919 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3921 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3921 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3921 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3921 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3921 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3921 4TH AVE	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3921 4TH AVE	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3921 4TH AVE	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3921 4TH AVE	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3921 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
3921 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
3921 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
3923 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
3923 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
3923 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
3923 4TH AVE	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3923 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3946 4TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
3949 44TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
3949 4TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
3949 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
3950 4TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
3952 4TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
3970 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
400 40TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
4000 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
4004 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
4004 4TH AVE	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4004 4TH AVE	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4004 4TH AVE	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4004 4TH AVE	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4004 4TH AVE	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4004 4TH AVE	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
4004 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4004 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4004 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4004 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4004 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4004 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4004 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4008 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4011 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
4013 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
4013 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
4013 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
4013 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
4013 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
4013 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
4013 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4013 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4013 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4013 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4013 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4013 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4013 4TH AVE	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
4013 4TH AVE	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4013 4TH AVE	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4013 4TH AVE	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4013 4TH AVE	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4013 4TH AVE	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
4015 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
4017 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
4022 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
4024 4TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
403 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
408 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
409 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
409 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
409 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
409 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
409 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
409 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
409 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
409 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
409 40TH ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
409 40TH ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
409 40TH ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
409 40TH ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
409 40TH ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
409 40TH ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
409 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
409 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
411 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
411 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
411 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
411 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
411 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
411 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
412 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
413 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
413 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
413 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
413 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
413 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
413 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
413 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
413 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
413 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
413 40TH ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
413 40TH ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
413 40TH ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
413 40TH ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
413 40TH ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
413 40TH ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
414 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
414 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
414 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
414 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
414 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
414 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
414 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
414 40TH ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
414 40TH ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
414 40TH ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
414 40TH ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
414 40TH ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
414 40TH ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
415 40 972	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
415 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
415 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
415 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
415 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
415 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
415 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
415 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
415 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
415 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
415 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
415 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
415 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
415 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
415 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1965, 1960, 1949, 1945, 1940, 1934, 1928
415 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1960, 1949, 1945, 1940, 1934, 1928
415 40TH ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
415 40TH ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
415 40TH ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
415 40TH ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
415 40TH ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
415 40TH ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
416 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
418 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
418 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
418 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
418 40TH ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
418 40TH ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
418 40TH ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
418 40TH ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
418 40TH ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
418 40TH ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
418 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
420 40 J	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
420 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
420 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934
420 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
420 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
420 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
420 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
420 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
420 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
420 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
420 40TH ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
420 40TH ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
420 40TH ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
420 40TH ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
420 40TH ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
420 40TH ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
420 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
422 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
422 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
422 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
422 40TH ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
422 40TH ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
422 40TH ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
422 40TH ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

FINDINGS

Address Researched	Address Not Identified in Research Source
422 40TH ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
422 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
424 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1949, 1945, 1940, 1934, 1928
424 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1928
424 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
424 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
424 40TH	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
424 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
424 40TH ST	2020, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
424 40TH ST	2020, 2017, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
424 40TH ST	2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
424 40TH ST	2020, 2017, 2014, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
424 40TH ST	2020, 2017, 2014, 2010, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
424 40TH ST	2020, 2017, 2014, 2010, 2005, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
424 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928
424 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1940, 1934, 1928
424 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1934, 1928
426 40TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1997, 1995, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1945, 1940, 1934, 1928

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
4001 4th Avenue	1980

APPENDIX F - Previous Environmental Reports

CASTLETON
ENVIRONMENTAL

January 25, 2019

Donald Middleton
Middleton Environmental Inc.
54 George Street
Babylon, New York 11702

RE: Phase II Environmental Site Assessment
4001-4011 4th Avenue, Brooklyn, New York

Dear Mr. Middleton:

Please find the attached Phase II Environmental Site Assessment Report for the property located at 4001-4011 4th Avenue, Brooklyn New York.

Thank you for the opportunity. Please call with any questions or comments.

Very truly yours,
Castleton Environmental Geologic Services, DPC



Frank P. Castellano, PG
Principal

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

CASTLETON
ENVIRONMENTAL

54 George Street, Babylon Village, NY 11702
206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 OFFICE
631-482-9042 FAX
www.castletonenv.com

Phase II Environmental Site Assessment
4001-4011 4th Avenue
Brooklyn, New York



Prepared for: Donald Middleton
Middleton Environmental Inc.
54 George Street
Babylon, New York 11702

PHASE II ENVIRONMENTAL SITE ASSESSMENT
4001-4011 4TH AVENUE
BROOKLYN, NEW YORK
JANUARY 2019
CASTLETON PROJECT NUMBER: MEIN1901

Table of Contents

1.0 INTRODUCTION 1
2.0 SITE BACKGROUND 1
3.0 PHASE II ESA FIELD INVESTIGATION 1
3.1 Geophysical Survey 2
3.2 Soil Investigation 2
4.0 ANALYTICAL RESULTS AND DATA DISCUSSION 3
5.0 CONCLUSIONS AND RECOMMENDATIONS 4
6.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS 4

Figures

Figure 1 – Vicinity Map
Figure 2 – Site and Sampling Plan

Appendices

Appendix A – Soil Boring Logs
Appendix B – Laboratory Analytical Reports

1.0 INTRODUCTION

Castleton Environmental Geologic Services DPC (Castleton) has prepared the following Phase II Environmental Site Assessment (ESA) report to document the work performed at 4001-4011 4th Avenue, Brooklyn, New York (the site). The investigation was performed based upon review of the Phase I ESA by Merritt Environmental Consulting Corp. (MECC) dated January 7, 2019.

The objectives of this work were to determine if the sites historic and current usage as a gasoline station has impacted the subsurface. The objective was met through the performance of a geophysical survey and the collection and laboratory analysis of soil samples.

2.0 SITE BACKGROUND

The site is located at 4001-4011 4th Avenue, Brooklyn, New York (Figure 1). The site is located on a plot size approximately 10,017 square feet. The site is currently used as a gas station with a convenience store and parking. The building was constructed in 1965.

Castleton reviewed the Phase I ESA prepared by MECC dated January 7, 2019. The MECC Phase I ESA identified that site has been a gasoline since its first developed use. According to the historical Sanborn Maps, a gasoline tank is present at the corner of 4th Avenue and 10th Street during the years 1926-1951.

MECC recommended further evaluation to determine if any documentation is available or if additional investigation (Phase II) is warranted. Subsequent documentation regarding the gasoline tank shown on the 1926-1951 Sanborn Maps was not provided.

3.0 PHASE II ESA FIELD INVESTIGATION

The objective of this Phase II ESA was to assess subsurface quality in relation to historic and current on-site filling station operations at the site.

The following scope of work was completed to assess subsurface conditions:

Task	Objective
Geophysical Survey	Determine if any subsurface anomalies indicative of underground storage tanks (USTs) and to clear underground utilities
Soil Sampling	Characterize site soil quality for impacts related to filling station operations

On-site work was completed on January 15, 2019. Sample collection locations are depicted on Figure 2.

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

3.1 Geophysical Survey

A geophysical survey was performed to identify evidence of subsurface anomalies and to mark on-site utilities in proposed subsurface work areas. The survey was performed using a variety of remote sensing equipment/methods including a magnetometer to identify ferrous metallic objects, ground penetrating radar (GPR) to identify changes in soil density and a pipe locating device to trace piping runs. The geophysical survey was performed by Delta Geophysics, Inc. of Catasauqua, Pennsylvania.

As described in the PBS records included in the Phase I ESA, 4 4,000-gallon USTs are currently in use at the site and were identified during the geophysical survey to clear boring locations.

Nine suspect (USTs) were identified that are currently not in use. Four suspect UST anomalies are centralized under the canopy between the active dispensers. Five suspect UST anomalies are located at the western portion of the site.

A metal anomaly not indicative of a UST was identified at northern portion of the site. A suspect UST was not identified at the northern portion of the site where the gas tank was shown on the historic Sanborn Maps.

All on site utilities were cleared before intrusive activities.

3.2 Soil Investigation

Soil borings were advanced to assess soil conditions at the site. Boring locations were selected based on potential areas identified during the geophysical survey. Soil borings were advanced with direct push technology (Geoprobe®) by Coastal Environmental Solutions, Inc. of Medford, New York.

Six soil borings were advanced. Soil samples were collected continuously from each boring location, logged and field screened with a PID for the presence of VOCs. Elevated field sensory (PID), olfactory or visible evidence of impacts to soil were observed in each of the borings ranging from 22.9 ppm in SB01 to 5,285 ppm in SB04. Soil was observed to consist of silty fine and medium sand. Groundwater was not encountered during this investigation. Soil boring logs are provided as Appendix A.

The following table describes the boring location, area of concern associated with each boring, and sample collected for laboratory analysis.

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

Boring	Area of Concern	Highest Soil PID Readings (ppm)	Boring Depth (feet)	Soil Analytical Sample Interval(s)
SB01	Area of former UST (Sanborn Map) and metal anomaly	22.9	25	18-20 feet
SB02	Area of former UST (Sanborn Map) and metal anomaly	425.9	20	4-6 feet
SB03	Area of former UST (Sanborn Map) and metal anomaly	2,195	22	12-14 feet
SB04	West of the five suspect USTs	5,285	30	16-18 feet
SB05	West of the five suspect USTs	3,963	20	10-15 feet
SB06	South of the five suspect USTs and west of the currently in use USTs	4,955	24.5	18-20 feet

Soil retained for laboratory analysis was placed into laboratory supplied glassware and submitted under chain of custody to York Analytical Laboratories of Stratford, Connecticut, a New York State Department of Health (NYSDOH) ELAP certified laboratory. Soil samples were analyzed for:

- CP-51 VOCs via EPA Method 8260, and
- CP-51 SVOCs via EPA Method 8270

4.0 ANALYTICAL RESULTS AND DATA DISCUSSION

Soil analytical results were compared to NYSDEC CP-51 Soil Cleanup Levels (SCLs) for petroleum impacted soil and NYSDEC Part 375 Soil Cleanup Objectives (SCOs).

Soil analytical results reported concentrations SVOCs as non-detect or below SCLs and SCOs in the six soil sample analyzed.

VOCs above SCLs were reported in five of the six soil samples. VOCs above Commercial SCOs were reported in two of the six samples analyzed.

Analytical results and laboratory report are presented in Appendix B.

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

5.0 CONCLUSIONS AND RECOMMENDATIONS

Castleton has prepared the following Phase II ESA report to document the work performed at 4001-4011 4th Avenue, Brooklyn, New York. The investigation was performed based upon review of the Phase I ESA by MECC dated January 7, 2019.

The objectives of this work were to determine if the sites historic and current usage as a gasoline station has impacted the subsurface. The objective was met through the performance of a geophysical survey and the collection and laboratory analysis of soil samples.

The geophysical survey identified the presence of the 4 in use USTs, nine suspect USTs that are currently not in use, and one metal anomaly that is not indicative of a UST.


Six soil boring were advanced, and six soil samples collected for laboratory analysis. Analytical results reported concentrations of VOCs above applicable standards in five of the six soil samples analyzed.

Castleton recommends the following:

- Notification of these findings be made to NYSDEC
- The suspect USTs be assessed and, if are present, properly removed as per NYSDEC protocols
- Petroleum impacts to soil be delineated and remediated under the NYSDEC Spills Program

6.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS





Frank P. Castellano, PG
Principal

Jessica Ferngren, PG
Sr. Project Manager

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

CASTLETON ENVIRONMENTAL

FIGURES

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com




Figure 1 – Vicinity Map

4001-4011 4th Avenue

Brooklyn, New York

+




Figure 2 – Site Plan

4001-4011 4th Avenue

Brooklyn, New York

CASTLETON
ENVIRONMENTAL

APPENDIX A

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com



Locations are approximate

Boring # **SB01**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**25 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 9:25		DATE: 1/15/2019	
COMPLETION TIME: 9:50		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	4	Asphalt Brown silty fine SAND, trace fine gravel	PID = 0.0 ppm.	
5-10 ft	5	3	Brown silty fine SAND, trace fine gravel	PID = 8.2 ppm.	
10-15 ft	5	3.5	Brown silty fine SAND, trace fine gravel	PID = 0.8 ppm.	
15-20 ft	5	1.5	Brown silty fine SAND, trace fine gravel Perched water @ 20-21 feet	PID = 22.9 ppm.	
20-25 ft	5	3	Brown clayey SAND, trace fine gravel	PID = 0.0 ppm.	



Locations are approximate

Boring # **SB02**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**20 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 9:50		DATE: 1/15/2019	
COMPLETION TIME: 10:10		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	3	Asphalt Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 23.4 ppm.	
5-10 ft	5	2.5	Brown silty fine SAND, trace fine gravel, brick	PID = 423.4 ppm.	
10-15 ft	5	2	Brown silty fine SAND, trace fine gravel, brick	PID = 0.0 ppm.	
15-20 ft	5	3	Brown silty fine SAND, trace fine gravel, brick	PID = 0.0 ppm.	



Locations are approximate

Boring # **SB03**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**22 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 10:10		DATE: 1/15/2019	
COMPLETION TIME: 11:00		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	0.5	Asphalt Black silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 23.4 ppm.	
5-10 ft	5	3.5	Black silty fine SAND, trace fine gravel, brick - Petroleum odor Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 423.4 ppm.	
10-15 ft	5	4	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 0.0 ppm.	
15-20 ft	5	2.5	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 0.0 ppm.	
20-22 ft	2	0.5	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor Refusal @ 22'	PID = 0.0 ppm.	



Locations are approximate

Boring # **SB04**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**30 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 11:00		DATE: 1/15/2019	
COMPLETION TIME: 11:40		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	0.5	Asphalt Dark brown silty fine SAND, brick - Petroleum odor	PID = 126.7 ppm.	
5-10 ft	5	2	Brown silty fine SAND, brick - Petroleum odor	PID = 148.9 ppm.	
10-15 ft	5	2	Brown silty fine SAND, brick - Petroleum odor	PID = 3,414 ppm.	
15-20 ft	5	2.5	Brown silty fine SAND, brick - Petroleum odor	PID = 5,285 ppm.	
20-25 ft	5	3	Brown silty fine SAND, brick - Petroleum odor	PID = 4,675 ppm.	
25-30 ft	5	2.5	Brown silty fine SAND, brick - Petroleum odor	PID = 368.4 ppm.	



Locations are approximate

Boring # **SB05**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**20 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 11:40		DATE: 1/15/2019	
COMPLETION TIME: 12:00		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	1	Concrete Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 2,634 ppm.	
5-10 ft	5	2	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 2,391 ppm.	
10-15 ft	5	0.5	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 3,963 ppm.	
15-20 ft	5	0.5	Brown silty fine SAND, trace fine gravel, brick - Petroleum odor	PID = 1,516 ppm.	



Locations are approximate

Boring # **SB06**	MW#	Page 1	of 1
PROJECT: 4001-4011 4th Avenue			
JOB # MEIN1901			
LOGGED BY:	CL	PRJ. MNGR.:	JF
DRILLING CONTRACTOR: Coastal Environmental Solutions			
DRILL METHOD: GeoProbe 6610DT			
DRILLER: Tom			
Borehole diameter/drill bit type: **Macrocore (2" diameter)**		total depth	**24.5 ft**
		elevation	**NA**
HAMMER WT: NA		DROP: NA	
START TIME: 12:00		DATE: 1/15/2019	
COMPLETION TIME: 12:20		DATE: 1/15/2019	
BACKFILL TIME: 12:30		DATE: 1/15/2019	

Sample Depth	Advance (ft)	Recovered (ft)	Soil Description Unified Soil Classification System	Notes	Casing depth: NA / Screen depth: NA
0-5 ft	5	0.5	Concrete Tan silty fine SAND, trace fine gravel, brick	PID = 53.7 ppm.	
5-10 ft	5	0.5	Brown silty fine SAND, trace fine gravel	PID = 10.7 ppm.	
10-15 ft	5	1.5	Brown silty fine SAND, trace fine gravel	PID = 248.6 ppm.	
15-20 ft	5	2	Brown silty fine SAND, trace fine gravel	PID = 4,955 ppm.	
20-24.5 ft	4.5	0.5	Brown silty fine SAND, trace fine gravel	PID = 4,815 ppm.	

CASTLETON
ENVIRONMENTAL

APPENDIX B

54 George Street, Babylon Village, NY 11702 I 206 West 23rd Street, 4th Floor, New York, NY 10011
631-482-1818 Office I 631-321-4349 Fax
www.castletonenv.com

Sample ID York ID Sampling Date Client Matrix		NYSDEC CP/SCO Table 2-Gasoline	NYSDEC CP/SCO Table 3-Fuel Oil	NYSDEC Part 375 Unrestricted Use Soil Cleanup Objectives	NYSDEC Part 375 Restricted Use Soil Cleanup Objectives - Restricted Residential	NYSDEC Part 375 Restricted Use Soil Cleanup Objectives- Commercial	SB01 19A0642-01 1/15/2019 9:50:00 AM Soil		SB02 19A0642-02 1/15/2019 10:10:00 AM Soil		SB03 19A0642-03 1/15/2019 11:00:00 AM Soil		SB04 19A0642-04 1/15/2019 11:40:00 AM Soil		SB05 19A0642-05 1/15/2019 12:00:00 PM Soil		SB06 19A0642-06 1/15/2019 12:20:00 PM Soil	
Compound	**CAS Number**						Result	Q	Result	Q	Result	Q	Result	Q	Result	Q	Result	Q
Volatile Organics, CP-51 (formerly STARS) List		mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg		mg/Kg		mg/Kg		mg/Kg		mg/Kg		mg/Kg	
Dilution Factor							1		100		200		10000		1000		5000	
1,2,4-Trimethylbenzene	95-63-6	3.6	3.6	3.6	52	190	0.00650		**4.400**	D	**22**	D	**1,200**	D	**57**	D	**360**	D
1,3,5-Trimethylbenzene	108-67-8	8.4	8.4	8.4	52	190	0.00290	J	0.170		**9.100**	D	**830**	D	**19**	D	**57**	D
Benzene	71-43-2	0.06	0.06	0.06	4.8	44	0.00680		0.00370	J	**1.200**	D	**20**	D	**2.400**	D	**3.600**	D
Ethyl Benzene	100-41-4	1	1	1	41	390	0.00310	J	0.100		**10**	D	**1,100**	D	**21**	D	**77**	D
Isopropylbenzene	98-82-8	2.3	2.3	~	~	~	0.00220	U	0.0780		**3**	D	**48**	D	**3.700**	D	**9.600**	D
Methyl tert-butyl ether (MTBE)	1634-04-4	0.93	~	0.93	100	500	0.0560		0.00350	J	0.0460		0.270	U	0.220	U	0.180	U
Naphthalene	91-20-3	12	12	12	100	500	0.00310	J	0.190		0.140		**88**	BD	6.300	BD	**23**	BD
n-Butylbenzene	104-51-8	12	12	12	100	500	0.00220	U	0.0930		0.200		**31**	D	2.700	D	6.800	D
n-Propylbenzene	103-65-1	3.9	3.9	3.9	100	500	0.00220	U	0.130		**4.800**	D	**170**	D	**11**	D	**34**	D
o-Xylene	95-47-6	~	~	~	~	~	0.00220	U	0.00250	U	3.700	D	650	D	32	D	120	D
p- & m- Xylenes	179601-23-1	~	~	~	~	~	0.00540	J	0.0130		22	D	1,600	D	82	D	350	DE
p-Isopropyltoluene	99-87-6	10	10	~	~	~	0.00220	U	0.170		2.900	D	**15**	D	1.400	D	2.300	D
sec-Butylbenzene	135-98-8	11	11	11	100	500	0.00220	U	0.110		2.100	D	**21**	D	1.600	D	3.900	D
tert-Butylbenzene	98-06-6	5.9	5.9	5.9	100	500	0.00220	U	0.0340		0.120		0.270	U	0.220	U	0.180	U
Toluene	108-88-3	0.7	0.7	0.7	100	500	0.00220	U	0.00360	J	**8.300**	D	**1,500**	D	**64**	D	**370**	D
Xylenes, Total	1330-20-7	0.26	0.26	0.26	100	500	0.00650	U	0.0130	J	**26**	D	**2,300**	D	**110**	D	**480**	DE
Semi-Volatiles, CP-51 (formerly STARS) List		mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg		mg/Kg		mg/Kg		mg/Kg		mg/Kg		mg/Kg	
Dilution Factor							2		2		2		2		2		2	
Acenaphthene	83-32-9	~	20	20	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Acenaphthylene	208-96-8	~	100	100	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Anthracene	120-12-7	~	100	100	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(a)anthracene	56-55-3	~	1	1	1	5.6	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(a)pyrene	50-32-8	~	1	1	1	1	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(b)fluoranthene	205-99-2	~	1	1	1	5.6	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(g,h,i)perylene	191-24-2	~	100	100	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Benzo(k)fluoranthene	207-08-9	~	0.8	0.8	3.9	56	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Chrysene	218-01-9	~	1	1	3.9	56	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Dibenzo(a,h)anthracene	53-70-3	~	0.33	0.33	0.33	0.56	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Fluoranthene	206-44-0	~	100	100	100	500	0.0450	U	0.0870	JD	0.0560	JD	0.0540	U	0.0450	U	0.0460	U
Fluorene	86-73-7	~	30	30	100	500	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Indeno(1,2,3-cd)pyrene	193-39-5	~	0.5	0.5	0.5	5.6	0.0450	U	0.0450	U	0.0440	U	0.0540	U	0.0450	U	0.0460	U
Naphthalene	91-20-3	12	12	12	100	500	0.0450	U	0.180	D	1.600	D	1.500	D	2.900	DE	0.120	D
Phenanthrene	85-01-8	~	100	100	100	500	0.0450	U	0.100	D	0.0740	JD	0.0540	U	0.0450	U	0.0460	U
Pyrene	129-00-0	~	100	100	100	500	0.0450	U	0.0880	JD	0.0470	JD	0.0540	U	0.0450	U	0.0460	U
Total Solids							%		%		%		%		%		%	
Dilution Factor							1		1		1		1		1		1	
% Solids	solids	~	~	~	~	~	91		93.100		93.200		77.100		91.200		90.300	

NOTES:

Any Regulatory Exceedences are color coded by Regulation

Q is the Qualifier Column with definitions as follows:

D=result is from an analysis that required a dilution

J=analyte detected at or above the MDL (method detection limit) but below the RL (Reporting Limit) - data is estimated

U=analyte not detected at or above the level indicated

B=analyte found in the analysis batch blank

E=result is estimated and cannot be accurately reported due to levels encountered or interferences

P=this flag is used for pesticide and PCB (Aroclor) target compounds when there is a % difference for detected concentrations that exceed method dictated limits between the two GC columns used for analysis

NT=this indicates the analyte was not a target for this sample

~=this indicates that no regulatory limit has been established for this analyte

Technical Report

prepared for:

Castleton Environmental
54 George Street
Babylon NY, 11702
Attention: Jessica Ferngren

Report Date: 01/23/2019
Client Project ID: MEIN1901
York Project (SDG) No.: 19A0642

Report Date: 01/23/2019
Client Project ID: MEIN1901
York Project (SDG) No.: 19A0642

Castleton Environmental
54 George Street
Babylon NY, 11702
Attention: Jessica Ferngren

Purpose and Results

This report contains the analytical data for the sample(s) identified on the attached chain-of-custody received in our laboratory on January 16, 2019 with a temperature of 1.5 C. The project was identified as your project: **MEIN1901**.

The analyses were conducted utilizing appropriate EPA, Standard Methods, and ASTM methods as detailed in the data summary tables.

All samples were received in proper condition meeting the customary acceptance requirements for environmental samples except those indicated under the Sample and Analysis Qualifiers section of this report.

All analyses met the method and laboratory standard operating procedure requirements except as indicated by any data flags, the meaning of which are explained in the Sample and Data Qualifiers Relating to This Work Order section of this report and case narrative if applicable.

The results of the analyses, which are all reported on dry weight basis (soils) unless otherwise noted, are detailed in the following pages.

Please contact Client Services at 203.325.1371 with any questions regarding this report.

York Sample ID	Client Sample ID	Matrix	Date Collected	Date Received
19A0642-01	SB01	Soil	01/15/2019	01/16/2019
19A0642-02	SB02	Soil	01/15/2019	01/16/2019
19A0642-03	SB03	Soil	01/15/2019	01/16/2019
19A0642-04	SB04	Soil	01/15/2019	01/16/2019
19A0642-05	SB05	Soil	01/15/2019	01/16/2019
19A0642-06	SB06	Soil	01/15/2019	01/16/2019

General Notes for York Project (SDG) No.: 19A0642

1. The RLs and MDLs (Reporting Limit and Method Detection Limit respectively) reported are adjusted for any dilution necessary due to the levels of target and/or non-target analytes and matrix interference. The RL(REPORTING LIMIT) is based upon the lowest standard utilized for the calibration where applicable.
2. Samples are retained for a period of thirty days after submittal of report, unless other arrangements are made.
3. York's liability for the above data is limited to the dollar value paid to York for the referenced project.
4. This report shall not be reproduced without the written approval of York Analytical Laboratories, Inc.
5. All analyses conducted met method or Laboratory SOP requirements. See the Sample and Data Qualifiers Section for further information.
6. It is noted that no analyses reported herein were subcontracted to another laboratory, unless noted in the report.
7. This report reflects results that relate only to the samples submitted on the attached chain-of-custody form(s) received by York.
8. Analyses conducted at York Analytical Laboratories, Inc. Stratford, CT are indicated by NY Cert. No. 10854; those conducted at York Analytical Laboratories, Inc., Richmond Hill, NY are indicated by NY Cert. No. 12058.

Approved By: 

Date: 01/23/2019

Benjamin Gulizia
Laboratory Director

Sample Information

Client Sample ID: **SB01** **York Sample ID:** **19A0642-01**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 9:50 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**6.5**		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-67-8	**1,3,5-Trimethylbenzene**	**2.9**	J	ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
71-43-2	**Benzene**	**6.8**		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
100-41-4	**Ethyl Benzene**	**3.1**	J	ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-82-8	Isopropylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1634-04-4	**Methyl tert-butyl ether (MTBE)**	**56**		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
91-20-3	**Naphthalene**	**3.1**	J	ug/kg dry	2.2	8.6	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI			
104-51-8	n-Butylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
103-65-1	n-Propylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
95-47-6	o-Xylene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
179601-23-1	**p- & m- Xylenes**	**5.4**	J	ug/kg dry	4.3	8.6	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
99-87-6	p-Isopropyltoluene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
135-98-8	sec-Butylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-06-6	tert-Butylbenzene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-88-3	Toluene	ND		ug/kg dry	2.2	4.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1330-20-7	Xylenes, Total	ND		ug/kg dry	6.5	13	1	EPA 8260C	01/18/2019 08:45	01/18/2019 19:28	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,NJ			

	Surrogate Recoveries	Result	Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*102 %*	*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*102 %*	*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*109 %*	*76-130*

Sample Information

Client Sample ID: **SB01** **York Sample ID:** **19A0642-01**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 9:50 am	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
208-96-8	Acenaphthylene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
120-12-7	Anthracene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
218-01-9	Chrysene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
206-44-0	Fluoranthene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
86-73-7	Fluorene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	NELAC-NY10854,NJDEP,PADEP		
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
91-20-3	Naphthalene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
85-01-8	Phenanthrene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
129-00-0	Pyrene	ND		ug/kg dry	45	91	2	EPA 8270D	01/22/2019 07:32	01/22/2019 15:29	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*54.7 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*71.8 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*66.4 %*	*24-116*

Total Solids

Log-in Notes:

Sample Notes:

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst

Sample Information

Client Sample ID: SB01 **York Sample ID:** 19A0642-01

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 9:50 am	01/16/2019

Total Solids **Log-in Notes:** **Sample Notes:**

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	* % Solids	91.0		%	0.100	1	SM 2540G Certifications: CTDOH	01/22/2019 11:58	01/22/2019 16:28	MAC

Sample Information

Client Sample ID: SB02 **York Sample ID:** 19A0642-02

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 10:10 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List **Log-in Notes:** **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	1,2,4-Trimethylbenzene	4400		ug/kg dry	250	500	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/21/2019 11:58	LLJ
108-67-8	1,3,5-Trimethylbenzene	170	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
71-43-2	Benzene	3.7	J	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
100-41-4	Ethyl Benzene	100		ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
98-82-8	Isopropylbenzene	78	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
1634-04-4	Methyl tert-butyl ether (MTBE)	3.5	J	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
91-20-3	Naphthalene	190	IS-HI	ug/kg dry	2.5	10	1	EPA 8260C Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI	01/18/2019 08:45	01/18/2019 19:56	LLJ
104-51-8	n-Butylbenzene	93	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
103-65-1	n-Propylbenzene	130	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
95-47-6	o-Xylene	ND		ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
179601-23-1	p- & m- Xylenes	13		ug/kg dry	5.0	10	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
99-87-6	p-Isopropyltoluene	170	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
135-98-8	sec-Butylbenzene	110	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ
98-06-6	tert-Butylbenzene	34	IS-HI	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 08:45	01/18/2019 19:56	LLJ

Sample Information

Client Sample ID: SB02 **York Sample ID:** 19A0642-02

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 10:10 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
108-88-3	**Toluene**	**3.6**	J	ug/kg dry	2.5	5.0	1	EPA 8260C Certifications:	01/18/2019 08:45 CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/18/2019 19:56	LLJ
1330-20-7	**Xylenes, Total**	**13**	J	ug/kg dry	7.5	15	1	EPA 8260C Certifications:	01/18/2019 08:45 CTDOH,NELAC-NY10854,NELAC-NY12058,NJ	01/18/2019 19:56	LLJ

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*122 %*		*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*90.5 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*246 %*	IS-HI, S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
208-96-8	Acenaphthylene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
120-12-7	Anthracene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
218-01-9	Chrysene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
206-44-0	**Fluoranthene**	**87**	J	ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
86-73-7	Fluorene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW
91-20-3	**Naphthalene**	**180**		ug/kg dry	45	89	2	EPA 8270D Certifications:	01/22/2019 07:32 CTDOH,NELAC-NY10854,NJDEP,PADEP	01/22/2019 21:49	OW

Sample Information

Client Sample ID: SB02 **York Sample ID:** 19A0642-02

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 10:10 am	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
85-01-8	**Phenanthrene**	**100**		ug/kg dry	45	89	2	EPA 8270D	01/22/2019 07:32	01/22/2019 21:49	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
129-00-0	**Pyrene**	**88**	J	ug/kg dry	45	89	2	EPA 8270D	01/22/2019 07:32	01/22/2019 21:49	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*61.4 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*73.5 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*75.9 %*	*24-116*

Total Solids

Log-in Notes:

Sample Notes:

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**93.1**		%	0.100	1	SM 2540G	01/22/2019 11:58	01/22/2019 16:28	MAC
							Certifications: CTDOH			

Sample Information

Client Sample ID: SB03 **York Sample ID:** 19A0642-03

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:00 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**22000**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-67-8	**1,3,5-Trimethylbenzene**	**9100**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
71-43-2	**Benzene**	**1200**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
100-41-4	**Ethyl Benzene**	**10000**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-82-8	**Isopropylbenzene**	**3000**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1634-04-4	**Methyl tert-butyl ether (MTBE)**	**46**	IS-HI	ug/kg dry	2.6	5.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 20:23	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
91-20-3	**Naphthalene**	**140**		ug/kg dry	2.6	11	1	EPA 8260C	01/18/2019 08:45	01/18/2019 20:23	LLJ
								Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI			

Sample Information

Client Sample ID: **SB03** **York Sample ID:** **19A0642-03**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:00 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
104-51-8	**n-Butylbenzene**	**200**		ug/kg dry	2.6	5.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 20:23	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
103-65-1	**n-Propylbenzene**	**4800**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
95-47-6	**o-Xylene**	**3700**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
179601-23-1	**p- & m- Xylenes**	**22000**		ug/kg dry	1100	2100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
99-87-6	**p-Isopropyltoluene**	**2900**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
135-98-8	**sec-Butylbenzene**	**2100**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-06-6	**tert-Butylbenzene**	**120**		ug/kg dry	2.6	5.3	1	EPA 8260C	01/18/2019 08:45	01/18/2019 20:23	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-88-3	**Toluene**	**8300**		ug/kg dry	530	1100	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1330-20-7	**Xylenes, Total**	**26000**		ug/kg dry	1600	3200	200	EPA 8260C	01/18/2019 08:45	01/21/2019 16:56	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,NJ			

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*388 %*	IS-HI, S-03	*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*104 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*1100 %*	S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
208-96-8	Acenaphthylene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
120-12-7	Anthracene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			

Sample Information

Client Sample ID: SB03 **York Sample ID:** 19A0642-03

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:00 am	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
218-01-9	Chrysene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
206-44-0	**Fluoranthene**	**56**	J	ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
86-73-7	Fluorene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	NELAC-NY10854,NJDEP,PADEP		
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
91-20-3	**Naphthalene**	**1600**		ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
85-01-8	**Phenanthrene**	**74**	J	ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
129-00-0	**Pyrene**	**47**	J	ug/kg dry	44	88	2	EPA 8270D	01/22/2019 07:32	01/22/2019 22:36	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*78.2 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*73.7 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*83.8 %*	*24-116*

Total Solids

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**93.2**		%	0.100	1	SM 2540G	01/22/2019 11:58	01/22/2019 16:28	MAC
							Certifications:	CTDOH		

Sample Information

Client Sample ID: SB04 **York Sample ID:** 19A0642-04

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:40 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst

Sample Information

Client Sample ID: **SB04** **York Sample ID:** **19A0642-04**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:40 am	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**1200000**		ug/kg dry	27000	54000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-67-8	**1,3,5-Trimethylbenzene**	**830000**		ug/kg dry	14000	27000	5000	EPA 8260C	01/21/2019 09:52	01/21/2019 17:22	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
71-43-2	**Benzene**	**20000**	IS-HI	ug/kg dry	270	540	100	EPA 8260C	01/21/2019 09:52	01/21/2019 12:52	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
100-41-4	**Ethyl Benzene**	**1100000**		ug/kg dry	14000	27000	5000	EPA 8260C	01/21/2019 09:52	01/21/2019 17:22	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-82-8	**Isopropylbenzene**	**48000**		ug/kg dry	2700	5400	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1634-04-4	Methyl tert-butyl ether (MTBE)	ND	IS-HI	ug/kg dry	270	540	100	EPA 8260C	01/21/2019 09:52	01/21/2019 12:52	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
91-20-3	**Naphthalene**	**88000**	B	ug/kg dry	2700	11000	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI			
104-51-8	**n-Butylbenzene**	**31000**		ug/kg dry	2700	5400	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
103-65-1	**n-Propylbenzene**	**170000**		ug/kg dry	2700	5400	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
95-47-6	**o-Xylene**	**650000**		ug/kg dry	27000	54000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
179601-23-1	**p- & m- Xylenes**	**1600000**		ug/kg dry	54000	110000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
99-87-6	**p-Isopropyltoluene**	**15000**		ug/kg dry	270	540	100	EPA 8260C	01/21/2019 09:52	01/21/2019 12:52	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
135-98-8	**sec-Butylbenzene**	**21000**		ug/kg dry	2700	5400	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 15:35	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-06-6	tert-Butylbenzene	ND		ug/kg dry	270	540	100	EPA 8260C	01/21/2019 09:52	01/21/2019 12:52	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-88-3	**Toluene**	**1500000**		ug/kg dry	27000	54000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1330-20-7	**Xylenes, Total**	**2300000**		ug/kg dry	81000	160000	10000	EPA 8260C	01/21/2019 09:52	01/22/2019 12:27	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,NJ			

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*96.5 %*	IS-HI	*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*110 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*174 %*	S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst

Sample Information

Client Sample ID: **SB04** **York Sample ID:** **19A0642-04**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:40 am	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
208-96-8	Acenaphthylene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
120-12-7	Anthracene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
218-01-9	Chrysene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
206-44-0	Fluoranthene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
86-73-7	Fluorene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	NELAC-NY10854,NJDEP,PADEP		
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
91-20-3	**Naphthalene**	**1500**		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
85-01-8	Phenanthrene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
129-00-0	Pyrene	ND		ug/kg dry	54	110	2	EPA 8270D	01/22/2019 07:32	01/22/2019 23:24	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*53.5 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*77.7 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*82.0 %*	*24-116*

Total Solids

Log-in Notes:

Sample Notes:

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst

Sample Information

Client Sample ID: SB04 **York Sample ID:** 19A0642-04

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 11:40 am	01/16/2019

Total Solids **Log-in Notes:** **Sample Notes:**

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**77.1**		%	0.100	1	SM 2540G Certifications: CTDOH	01/22/2019 11:58	01/22/2019 16:28	MAC

Sample Information

Client Sample ID: SB05 **York Sample ID:** 19A0642-05

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:00 pm	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List **Log-in Notes:** **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**57000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
108-67-8	**1,3,5-Trimethylbenzene**	**19000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
71-43-2	**Benzene**	**2400**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
100-41-4	**Ethyl Benzene**	**21000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
98-82-8	**Isopropylbenzene**	**3700**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
1634-04-4	Methyl tert-butyl ether (MTBE)	ND		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
91-20-3	**Naphthalene**	**6300**	B	ug/kg dry	220	870	100	EPA 8260C Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI	01/21/2019 09:52	01/21/2019 13:46	LLJ
104-51-8	**n-Butylbenzene**	**2700**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
103-65-1	**n-Propylbenzene**	**11000**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
95-47-6	**o-Xylene**	**32000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
179601-23-1	**p- & m- Xylenes**	**82000**		ug/kg dry	4400	8700	1000	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 16:02	LLJ
99-87-6	**p-Isopropyltoluene**	**1400**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
135-98-8	**sec-Butylbenzene**	**1600**		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ
98-06-6	tert-Butylbenzene	ND		ug/kg dry	220	440	100	EPA 8260C Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA	01/21/2019 09:52	01/21/2019 13:46	LLJ

Sample Information

Client Sample ID: **SB05** **York Sample ID:** **19A0642-05**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:00 pm	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
108-88-3	**Toluene**	**64000**		ug/kg dry	2200	4400	1000	EPA 8260C Certifications:	01/21/2019 09:52	01/21/2019 16:02 CTDOH,NELAC-NY10854,NELAC-NY12058,PA	LLJ
1330-20-7	**Xylenes, Total**	**110000**		ug/kg dry	6500	13000	1000	EPA 8260C Certifications:	01/21/2019 09:52	01/21/2019 16:02 CTDOH,NELAC-NY10854,NELAC-NY12058,NJ	LLJ

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*88.1 %*		*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*100 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*139 %*	S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
208-96-8	Acenaphthylene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
120-12-7	Anthracene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
218-01-9	Chrysene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
206-44-0	Fluoranthene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
86-73-7	Fluorene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 NELAC-NY10854,NJDEP,PADEP	OW
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW
91-20-3	**Naphthalene**	**2900**		ug/kg dry	45	90	2	EPA 8270D Certifications:	01/22/2019 07:32	01/23/2019 00:11 CTDOH,NELAC-NY10854,NJDEP,PADEP	OW

Sample Information

Client Sample ID: **SB05** **York Sample ID:** **19A0642-05**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:00 pm	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
85-01-8	Phenanthrene	ND		ug/kg dry	45	90	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:11	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
129-00-0	Pyrene	ND		ug/kg dry	45	90	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:11	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*69.5 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*80.1 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*85.1 %*	*24-116*

Total Solids

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**91.2**		%	0.100	1	SM 2540G	01/22/2019 11:58	01/22/2019 16:28	MAC
							Certifications: CTDOH			

Sample Information

Client Sample ID: **SB06** **York Sample ID:** **19A0642-06**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:20 pm	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
95-63-6	**1,2,4-Trimethylbenzene**	**360000**		ug/kg dry	8900	18000	5000	EPA 8260C	01/21/2019 09:52	01/21/2019 17:50	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-67-8	**1,3,5-Trimethylbenzene**	**57000**		ug/kg dry	1800	3500	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
71-43-2	**Benzene**	**3600**	IS-HI	ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
100-41-4	**Ethyl Benzene**	**77000**		ug/kg dry	1800	3500	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-82-8	**Isopropylbenzene**	**9600**		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1634-04-4	Methyl tert-butyl ether (MTBE)	ND	IS-HI	ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
91-20-3	**Naphthalene**	**23000**	B	ug/kg dry	1800	7100	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: NELAC-NY10854,NELAC-NY12058,PADEP,NJI			

Sample Information

Client Sample ID: **SB06** **York Sample ID:** **19A0642-06**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:20 pm	01/16/2019

Volatile Organics, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 5035A

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
104-51-8	**n-Butylbenzene**	**6800**		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
103-65-1	**n-Propylbenzene**	**34000**		ug/kg dry	1800	3500	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
95-47-6	**o-Xylene**	**120000**		ug/kg dry	1800	3500	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
179601-23-1	**p- & m- Xylenes**	**350000**	VOA-E	ug/kg dry	3500	7100	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
99-87-6	**p-Isopropyltoluene**	**2300**		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
135-98-8	**sec-Butylbenzene**	**3900**		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
98-06-6	tert-Butylbenzene	ND		ug/kg dry	180	350	100	EPA 8260C	01/21/2019 09:52	01/21/2019 14:41	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
108-88-3	**Toluene**	**370000**		ug/kg dry	8900	18000	5000	EPA 8260C	01/21/2019 09:52	01/21/2019 17:50	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,PA			
1330-20-7	**Xylenes, Total**	**480000**	VOA-E	ug/kg dry	5300	11000	1000	EPA 8260C	01/21/2019 09:52	01/21/2019 16:29	LLJ
								Certifications: CTDOH,NELAC-NY10854,NELAC-NY12058,NJ			

	Surrogate Recoveries	Result		Acceptance Range
17060-07-0	*Surrogate: SURR: 1,2-Dichloroethane-d4*	*108 %*	IS-HI	*77-125*
2037-26-5	*Surrogate: SURR: Toluene-d8*	*103 %*		*85-120*
460-00-4	*Surrogate: SURR: p-Bromofluorobenzene*	*139 %*	S-03	*76-130*

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes: **Sample Notes:**

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
83-32-9	Acenaphthene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
208-96-8	Acenaphthylene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
120-12-7	Anthracene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
56-55-3	Benzo(a)anthracene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
50-32-8	Benzo(a)pyrene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
205-99-2	Benzo(b)fluoranthene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			
191-24-2	Benzo(g,h,i)perylene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications: CTDOH,NELAC-NY10854,NJDEP,PADEP			

Sample Information

Client Sample ID: **SB06** **York Sample ID:** **19A0642-06**

York Project (SDG) No.	Client Project ID	Matrix	Collection Date/Time	Date Received
19A0642	MEIN1901	Soil	January 15, 2019 12:20 pm	01/16/2019

Semi-Volatiles, CP-51 (formerly STARS) List

Log-in Notes:

Sample Notes:

Sample Prepared by Method: EPA 3550C

CAS No.	Parameter	Result	Flag	Units	Reported to LOD/MDL	LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
207-08-9	Benzo(k)fluoranthene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
218-01-9	Chrysene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
53-70-3	Dibenzo(a,h)anthracene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
206-44-0	Fluoranthene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
86-73-7	Fluorene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	NELAC-NY10854,NJDEP,PADEP		
193-39-5	Indeno(1,2,3-cd)pyrene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
91-20-3	**Naphthalene**	**120**		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
85-01-8	Phenanthrene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		
129-00-0	Pyrene	ND		ug/kg dry	46	91	2	EPA 8270D	01/22/2019 07:32	01/23/2019 00:59	OW
								Certifications:	CTDOH,NELAC-NY10854,NJDEP,PADEP		

	Surrogate Recoveries	Result	Acceptance Range
4165-60-0	*Surrogate: SURR: Nitrobenzene-d5*	*55.6 %*	*22-108*
321-60-8	*Surrogate: SURR: 2-Fluorobiphenyl*	*79.8 %*	*21-113*
1718-51-0	*Surrogate: SURR: Terphenyl-d14*	*77.2 %*	*24-116*

Total Solids

Log-in Notes:

Sample Notes:

Sample Prepared by Method: % Solids Prep

CAS No.	Parameter	Result	Flag	Units	Reported to LOQ	Dilution	Reference Method	Date/Time Prepared	Date/Time Analyzed	Analyst
solids	*** % Solids**	**90.3**		%	0.100	1	SM 2540G	01/22/2019 11:58	01/22/2019 16:28	MAC
							Certifications:	CTDOH		

Volatile Analysis Sample Containers

Lab ID	Client Sample ID	Volatile Sample Container
19A0642-01	SB01	40mL Vial with Stir Bar-Cool 4° C
19A0642-02	SB02	40mL Vial with Stir Bar-Cool 4° C
19A0642-03	SB03	40mL Vial with Stir Bar-Cool 4° C
19A0642-04	SB04	40mL Vial with Stir Bar-Cool 4° C
19A0642-05	SB05	40mL Vial with Stir Bar-Cool 4° C
19A0642-06	SB06	40mL Vial with Stir Bar-Cool 4° C

Sample and Data Qualifiers Relating to This Work Order

VOA-E	The concentration reported for this analyte is an estimated value above the linear range of the instrument for EPA SW846-5035/8260 (>200ppb). Re-analysis using 5035/8260 medium level prep. resulted in a detection below the reporting limit (<500ppb).
S-03	The surrogate recovery for this sample is outside of established control limits due to a sample matrix effect. This effect was confirmed by reanalysis.
J	Detected below the Reporting Limit but greater than or equal to the Method Detection Limit (MDL/LOD) or in the case of a TIC, the result is an estimated concentration.
IS-HI	The internal std associated with this target compound did not meet acceptance criteria (area >200% CCV) at the stated dilution due to matrix effects. Sample was rerun to confirm matrix effects.
CCV-E	The value reported is ESTIMATED. The value is estimated due to its behavior during continuing calibration verification (>20% Difference for average Rf or >20% Drift for quadratic fit).
B	Analyte is found in the associated analysis batch blank. For volatiles, methylene chloride and acetone are common lab contaminants.

Definitions and Other Explanations

*	Analyte is not certified or the state of the samples origination does not offer certification for the Analyte.
ND	NOT DETECTED - the analyte is not detected at the Reported to level (LOQ/RL or LOD/MDL)
RL	REPORTING LIMIT - the minimum reportable value based upon the lowest point in the analyte calibration curve.
LOQ	LIMIT OF QUANTITATION - the minimum concentration of a target analyte that can be reported within a specified degree of confidence. This is the lowest point in an analyte calibration curve that has been subjected to all steps of the processing/analysis and verified to meet defined criteria. This is based upon NELAC 2009 Standards and applies to all analyses.
LOD	LIMIT OF DETECTION - a verified estimate of the minimum concentration of a substance in a given matrix that an analytical process can reliably detect. This is based upon NELAC 2009 Standards and applies to all analyses conducted under the auspices of EPA SW-846.
MDL	METHOD DETECTION LIMIT - a statistically derived estimate of the minimum amount of a substance an analytical system can reliably detect with a 99% confidence that the concentration of the substance is greater than zero. This is based upon 40 CFR Part 136 Appendix B and applies only to EPA 600 and 200 series methods.
Reported to	This indicates that the data for a particular analysis is reported to either the LOD/MDL, or the LOQ/RL. In cases where the "Reported to" is located above the LOD/MDL, any value between this and the LOQ represents an estimated value which is "J" flagged accordingly. This applies to volatile and semi-volatile target compounds only.
NR	Not reported
RPD	Relative Percent Difference
Wet	The data has been reported on an as-received (wet weight) basis
Low Bias	Low Bias flag indicates that the recovery of the flagged analyte is below the laboratory or regulatory lower control limit. The data user should take note that this analyte may be biased low but should evaluate multiple lines of evidence including the LCS and site-specific MS/MSD data to draw bias conclusions. In cases where no site-specific MS/MSD was requested, only the LCS data can be used to evaluate such bias.
High Bias	High Bias flag indicates that the recovery of the flagged analyte is above the laboratory or regulatory upper control limit. The data user should take note that this analyte may be biased high but should evaluate multiple lines of evidence including the LCS and site-specific MS/MSD data to draw bias conclusions. In cases where no site-specific MS/MSD was requested, only the LCS data can be used to evaluate such bias.
Non-Dir.	Non-dir. flag (Non-Directional Bias) indicates that the Relative Percent Difference (RPD) (a measure of precision) among the MS and MSD data is outside the laboratory or regulatory control limit. This alerts the data user where the MS and MSD are from site-specific samples that the RPD is high due to either non-homogeneous distribution of target analyte between the MS/MSD or indicates poor reproducibility for other reasons.

If EPA SW-846 method 8270 is included herein it is noted that the target compound N-nitrosodiphenylamine (NDPA) decomposes in the gas chromatographic inlet and cannot be separated from diphenylamine (DPA). These results could actually represent 100% DPA, 100% NDPA or some combination of the two. For this reason, York reports the combined result for n-nitrosodiphenylamine and diphenylamine for either of these compounds as a combined concentration as Diphenylamine.

If Total PCBs are detected and the target aroclors reported are "Not detected", the Total PCB value is reported due to the presence of either or both Aroclors 1262 and 1268 which are non-target aroclors for some regulatory lists.

2-chloroethylvinyl ether readily breaks down under acidic conditions. Samples that are acid preserved, including standards will exhibit breakdown. The data user should take note.

Certification for pH is no longer offered by NYDOH ELAP.

Semi-Volatile and Volatile analyses are reported down to the LOD/MDL, with values between the LOD/MDL and the LOQ being "J" flagged as estimated results.

For analyses by EPA SW-846-8270D, the Limit of Quantitation (LOQ) reported for benzidine is based upon the lowest standard used for calibration and is not a verified LOQ due to this compound's propensity for oxidative losses during extraction/concentration procedures and non-reproducible chromatographic performance.

York Analytical Laboratories, Inc.
120 Research Drive, Stratford, CT 06615 | 132-02 89th Ave, Queens, NY 11418
clientservices@yorklab.com
www.yorklab.com

Field Chain-of-Custody Record

NOTE: YORK's Standard Terms & Conditions are listed on the back side of this document.
This document serves as your written authorization for YORK to proceed with the analyses requested below.
Your signature binds you to YORK's Standard Terms & Conditions.

YORK Project No.: 19A0643

Page 1 of 1

YOUR Information	Report To:	Invoice To:	YOUR Project Number	Turn-Around Time
Company: Castleton Environmental	Company:	Company:	MEIN1901	RUSH - Next Day
Address: 54 George St Babylon, NY	Address: SAME	Address: SAME	YOUR Project Name: MEIN1901	RUSH - Two Day
Phone: 631 [illegible] 1818	Phone:	Phone:		RUSH - Three Day
Contact: Jessica Terngren	Contact:	Contact:		RUSH - Four Day
E-mail: jessica@castletonenv.com	E-mail:	E-mail:	YOUR PO#:	Standard (5-7 Day) X

Please print clearly and legibly. All information must be complete. Samples will not be logged in and the turn-around-time clock will not begin until any questions by YORK are resolved.

Samples Collected by: (print your name above and sign below)
Charles Lambert

Matrix Codes
S - soil / solid
GW - groundwater
DW - drinking water
WW - wastewater
O - Oil | Other

Samples From
New York X
New Jersey
Connecticut
Pennsylvania
Other

Report / EDD Type (circle selections)
~~Summary Report~~ | CT RCP | ~~Standard Excel EDD~~
QA Report | CT RCP DQA/DUE | EQuIS (Standard)
NY ASP A Package | NJDEP Reduced Deliverables | NYSDEC EQuIS
NY ASP B Package | NJDKQP | NJDEP SRP HazSite
Other:

YORK Reg. Comp.
Compared to the following Regulation(s): (please fill in)

Sample Identification	Sample Matrix	Date/Time Sampled	Analysis Requested	Container Description
SB01	S	1/15/19 9:50	CP-51 VOCs via 8260, CP51 SVOCs via 8270	terracore 1&1, 8oz jar
SB02		10:10		
SB03		11:00		
SB04		11:40		
SB05		12:00		
SB06		12:20		

Comments:

Preservation: (check all that apply)
HCl ___ MeOH ___ HNO_3 ___ H_2SO_4 ___ NaOH ___ ZnAc ___
Ascorbic Acid ___ Other: ___

Special Instruction
Field Filtered ___
Lab to Filter ___

Samples Relinquished by / Company	Date/Time	Samples Received by / Company
[signature]	1/16/19 8:40am	[signature]
Samples Received by / Company	Date/Time	Samples Relinquished by / Company
Samples Relinquished by / Company	Date/Time	Samples Received by / Company

Date/Time	Samples Relinquished by / Company	Date/Time
1/16/19 8:40AM		
Date/Time	Samples Received by / Company	Date/Time
Date/Time	Samples Received in LAB by / Date/Time	Temp. Received at Lab
	TC Mahl 1/16/19 1647	1.5 Degrees C

BP SERVICE STATION
4001-4010 4TH AVENUE
BROOKLYN, NEW YORK
SPILL # 18-11146

Supplemental
Remedial Investigation
Report
(RIR)

NEW YORK STATE DEPARTMENT OF
ENVIRONMENTAL CONSERVATION
REGION II
LONG ISLAND CITY
NEW YORK

PREPARED BY:

BERNINGER ENVIRONMENTAL
17 OLD DOCK ROAD
YAPHANK, NEW YORK 11980

June 2020

Table of Contents

1.0 INTRODUCTION

2.0 SITE BACKGROUND

3.0 SITE HISTORY

4.0 SCOPE OF WORK

5.0 SUMMARY OF FINDINGS

6.0 REMEDIAL ALTERNATIVES

7.0 PROJECT SCHEDULE

8.0 CONCLUSION

FIGURES

Figure-1 Site Location

Figure-2 Site Map with boring/sampling locations

Figures-3 a-h Boring Logs

ATTACHMENTS

Attachment-A Current Site Layout/Schematic

Attachment-B Previous Phase II ESA

Attachment-C Lab Data Package

TABLE

Table-1 Tabulated Soil Data

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
17 Old Dock Road
Yaphank • New York • 11980
Phone: 631 • 589 • 6521
web: www.wrses.com

June 17th, 2020

Veronica Zhune
New York State Environmental Conservation
Division of Environmental Remediation, Region 2
47-40 21st Street
Long Island City, New York 11101

Re: BP Service Station
4001-4010 4th Avenue
Brooklyn, New York 11232

Remedial Investigation Work Plan
NYSDEC Spill #18-11146
(RIWP)

Dear Ms. Zhune,

1.0 INTRODUCTION

The following document is a Remedial Investigation Report (RIR) developed for the subject site based upon the approved Remedial Investigation Work Plan (RIWP), which supplemented previous Phase I and Phase II Environmental Site Assessments (ESAs) performed at the site. The previously conducted Phase II ESA identified environmental conditions above standards and warranted further supplemental investigation to further the extent of contamination. This supplemental RIR will discuss the findings from the supplemental investigation and propose remedial alternatives to address the contamination discovered within soils at the site. Included within this Report is a discussion on the following: site background, site history, summary of supplemental findings, remedial alternatives, and a conclusion on the results.

2.0 SITE BACKGROUND

The site is located at 4001-4011 4th Avenue, Brooklyn, New York- Figure 1. The site is located on a plot size approximately 10,017 square feet. The site is currently used as a gas station with a convenience store and parking. The building was constructed in 1965. Castleton reviewed the Phase I ESA prepared by Merritt Environmental Consulting Corporation (MECC) dated January 7, 2019. The MECC Phase I ESA identified that the site has been a gasoline station since its first developed use. According to the historical Sanborn Maps, a gasoline tank was present at the corner of 4th Avenue and 10th Street during the years 1926-1951. MECC recommended further evaluation to

determine if any documentation is available or if additional investigation (Phase II) is warranted. Subsequent documentation regarding the gasoline tank shown on the 1926-1951 Sanborn Maps was not provided. A Phase II was subsequently performed based on the recommendations outlined in the Phase I ESA. Please refer to Attachment-A for a survey of the current layout of the station.

3.0 SITE HISTORY

A Phase II ESA was performed by Castleton Environmental during January of 2019, which included a series of borings conducted at key locations throughout the property and a ground penetrating radar (GPR) survey to identify any potential former UST's. Six (6) soil borings were advanced on the Subject Property in the vicinity of the UST's. Soil samples were collected continuously from each boring location, logged and field screened with a PID for the presence of VOCs. Elevated field sensory (PID), olfactory or visible evidence of impacts to soil were observed in each of the borings ranging from 22.9 ppm in SB01 to 5,285 ppm in SB04. Soil analytical results were compared to NYSDEC CP-51 Soil Cleanup Levels (SCLs) for petroleum impacted soil and NYSDEC Part 375 Soil Cleanup Objectives (SCOs). Soil analytical results reported concentrations of SVOCs as non-detect or below SCLs and SCOs in all of the six (6) soil samples analyzed. VOCs above SCLs were reported in five (5) of the six (6) soil samples. VOCs above commercial-use SCOs were reported in two (2) of the six (6) samples analyzed. Based upon these findings a spill was reported and spill number # 18-11146 was assigned to the site. Please refer to Attachment-B for the previously conducted Phase II by another contractor.

4.0 SCOPE OF WORK

The previously conducted Phase II ESA concluded that the need for further investigation was necessary in order to further define the nature and extent of contamination discovered in soil. The focus was to vertically delineate the contamination discovered at previous sample locations and attempt to locate groundwater. The results of the GPR survey were also recommended to be confirmed through the performance of test pits in the former UST areas. The following summary of findings section details the results from the supplemental investigation compared to the applicable standards.

5.0 SUMMARY OF FINDINGS

The following summary of findings discusses the results from the supplemental RIR conducted on April 29, 2020. The supplemental borings conducted included: three (3) test pit borings(B-1-3) in areas of the previously identified former USTs were performed in order to confirm the results of the GPR survey. Borings B-4 and B-5 were conducted at former locations were soil contamination was discovered at depth, but never delineated. B-6 and B-7 were test pits in an additional area where the

previous GPR survey found suspected former USTs. Finally, B-8 was conducted down gradient of the suspected former USTs and B-4 and B-5. All borings were advanced until refusal was encountered preventing further vertical advancement of sample tooling.

5.1 Former UST Identification

A total of (9) suspected former UST's were identified in a GPR survey conducted during the Phase II ESA. In order to confirm this data and the existence of former USTs from past operations, a series of test pits were conducted in order to confirm the results of the GPR. Three (3) borings (B-1-3) and (B-6-7) were conducted along the string of suspected USTs discovered during the GPR as depicted on Figure-2. A rotary mason bit affixed to the boring rig was used to advance through the upper layer of concrete approximately twelve inches (12") in depth. A void of about one (1') was observed from one (1') to two and a half (2.5') feet were refusal was encountered at all three (3) test pit locations. The consistent refusal at precisely the same depth in all three (3) test pits is an indication that the previous GPR survey was accurate and most likely attributed to previous abandonment of the UST's in place. Based on the field observations at all three (3) borings, B-1-3, the tanks when abandoned were filled with concrete and left in place.

5.2 Supplemental Soil Sampling Locations and Results

A series of borings were conducted at previous sampling locations in an effort to vertically delineate contamination documented in soil. Borings B-4(former SB06) and B-5(between SB04 and former SB05) were collected at the previous Phase II locations. Boring B-8 was collected down gradient of B-4 and B-5 near the southwest corner of the property in an attempt to laterally delineate contamination discovered in the vicinity of the former USTs. Borings were collected utilizing the duel tube sampling system and continuous grab samples were extracted in five foot (5') intervals and screened in 2.5' intervals with a PID meter for the presence of VOCs. B-4 was the first delineation boring performed from 0-30' until refusal was encountered at 30' bgs. PID readings from 15-25' bgs were averaging approximately 4,500 ppm on the PID meter and subsided significantly from 25'-30' in the 500-190 ppm range with the bottom sample (B-4@ 27.5'-30'). A sample from 27.5'-30' was submitted to the lab for testing for VOCs via EPA 8260D. The results still indicated multiple BTEX petroleum constituents above unrestricted Part-375 SCOs. As mentioned above advancement beyond thirty feet (30') bgs was not feasible and most likely attributed to bedrock as rock fragments were discovered at the bottom of the last soil liner. B-5 was collected between the previous borings (SB04 and SB05) were vertical delineation was not achieved. Continuous samples were collected from grade surface to approximately 32.5' bgs. Refusal was again encountered and rock fragments were observed in the bottom sample tube at 32.5'. Again, this refusal was likely attributed to contact with bedrock. A sample at the bottom of the boring from 30-32.5' was submitted for lab analysis via VOC analysis. The lab results

indicated only minor VOC detections all significantly below the Part-375 unrestricted SCOs. B-8 was collected down gradient from the hot spot areas B-4 and B-5 and was sampled from the surface to a depth of thirty four (34') feet below grade surface. Marginal PID readings (1,500-2,500 ppm) were documented from 10'-20' bgs and subsided steadily to only 25 ppm at 34' bgs. Bedrock refusal was again encountered at 34' bgs and rock fragments were observed at the bottom of the soil sampling liner at 34' bgs. Please refer to Figure-3a-h for boring logs. Please see Table-1 for tabulated lab results compared to SCOs. The lab data package is included as Attachment-C.

6.0 REMEDIAL ALTERNATIVES

The results of the supplemental soil samples have indicated the need for remedial actions in soils with the main focus on the interval from 10'- 25' bgs. The goal is to provide in-situ remediation at areas where impacted soils have exceeded the Part-375 unrestricted-use SCOs. Please read below for remedial alternatives to treating the impacted soil discovered at the site.

5.1 Soil Vapor Extraction (SVE)

Soil Vapor Extraction (SVE) is a technology used to remove volatile organic vapors from the un-saturated zone often referred to as the vadose zone. Off-gassing of petroleum contamination emanating from the soil is extracted through a series of vertical screened pipes and exhausted to the atmosphere. This technology allows for mass removal of petroleum related contamination including sorbed contamination in the soil matrix. Soil Vapor Extraction is a reasonable in-situ alternative to remedy soil contamination at this site, especially where contamination extends beyond the capabilities of excavation. This technology would also prevent having to excavate former USTs and contaminated soil in areas where multiple underground utilities exist along with utilities associated with the operation of the active gas station. Based upon the location of the contaminated soil and the on-going operations of the current business, the SVE technology is deemed the most reasonable alternative to remediating soils to applicable levels.

5.2 Enhanced Biological Degradation

Enhance bio injections are another alternative to treating soil contamination in the vadose zone. A series of injection wells are used to deliver an oxidant solution or a microbial mixture to the contaminated vadose zone in order to promote biological degradation. This technology although practical and efficient, may not be conducive to achieve a timely clean-up based on the significant levels of contamination discovered in soil.

7.0 PROJECT SCHEDULE

Upon approval of this supplemental RIR, BEI will begin to draft a Remedial Action Plan (RAP) to address contaminated soils. The RAP will be submitted 45 days from the approval of this Report and issued to the Department for approval. The RAP will include: a remedial plan for addressing contaminated soil in the vadose zone, remedial action objectives (RAOs), operation monitoring and maintenance (OMM) and system termination.

8.0 CONCLUSION

In conclusion, the supplemental sampling data will be used to develop a Remedial Action Plan (RAP) in order to address soil contamination. No groundwater was encountered during any of the investigations conducted and is expected to be approximately 50 feet or more below grade surface. The supplemental sampling results indicated that vertical delineation was achieved at the B-5 and B-8 locations. At the B-4 location delineation was not feasible due to bedrock refusal at a depth of thirty feet (30') bgs. The majority of contamination at this boring was detected in the fifteen (15') feet to twenty five (25') horizon with PID readings as high as 4,500 ppm. Beyond this depth from 25'-30' PID readings drastically waned to levels in the 500 ppm range. Based upon the successful vertical delineation at two (2) locations B-5 and B-8, and the inability to advance beyond the refusals encountered at the surface of the bedrock at the B-6 location, a Remedial Action Plan (RAP) to address contaminated soils will be issue to the Department. Any questions or comments regarding this Report can be directed to BEI.

Sincerely,

Justin Halpin
Project Manager/Scientist

Alicia Patti
Geologist

enc: Figure-1 Site Location
Figure-2 Supplemental Boring Locations
Attachment-A Site Survey Layout
Attachment-B Previous Phase II ESA

FIGURES




Figure-1
Site Location
Brooklyn, NY



Site Map
Boring Locations
Figure-2

BP Service Station
4001-4010 4th Avenue
Brooklyn, NY

BEi Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-1

PROJECT: BP 4th Avenue Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-1	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
FT 0		GROUND SURFACE						
		First 8" concrete and an approximate 10" void of soil from 8" to 18" or 1.5'	0.0	NA	NA			
1.5'		Refusal most likely due to the former tanks backfilled with concrete; unable to advance past 2.5' Refusal at 2.5'						
2.5								
5								

Notes: Refusal at 2.5'
Sampling: No Sample Collected

FIGURE: 3-a
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-2

PROJECT: BP 4th Avenue Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

DEPTH	GRAPHIC	SUBSURFACE PROFILE BORING LOCATION: B-2	SAMPLE PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		First 8" concrete and an approximate 10" void of soil from 8" to 18" or 1.5'	0.0	NA	NA			
1.5'		Refusal most likely due to the former tanks backfilled with concrete; unable to advance past 2.5' Refusal at 2.5'	0.0	NA	NA			
2.5								
5								

Notes: Refusal at 2.5'
Sampling: No Sample Collected

FIGURE: 3-b
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-3

PROJECT: BP 4th Avenue Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-3	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		First 8" concrete and an approximate 10" void of soil from 8" to 18" or 1.5'	0.0	NA	NA			
1.5'		Refusal most likely due to the former tanks backfilled with concrete; unable to advance past 2.5' Refusal at 2.5'	0.0	NA	NA			
2.5								
5								

Notes: Refusal at 2.5'
Sampling: No Sample Collected

FIGURE: 3-c
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-4

PROJECT: BP 4th Ave Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-4	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		10YR-6/4; Light yellowish brown silty fine sand trace gravel, strong odor	38.7	80	SM			
2.5		10YR-6/4; Light yellowish brown silty fine sand trace gravel, strong odor	38.7	80	SM			
5		10YR-5/3; Brown silty fine sand, trace gravel, strong odor	25.0	80	SM			
7.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	25.0	80	SM			
10		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	199	80	SM			
12.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	199	80	SM			
15		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	4500	80	SM			
17.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	4500	80	SM			
20		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	4250	80	SM			
22.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	4250	80	SM			
25		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	900	80	SM			
27.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor; bedrock fragments	500	80	SM			Sample obtained from 27.5'-30'
30		Refusal at 30.0'						
32.5								

Notes: Refusal at 30.0'
Sampling: B-4 Collected at 27.5'-30.0'

FIGURE: 3-d
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-5

PROJECT: BP 4th Ave Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-5	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		10YR-6/4; Light yellowish brown silty fine sand trace gravel, strong odor	2350	80	SM			
2.5		10YR-6/4; Light yellowish brown silty fine sand trace gravel, strong odor	2350	80	SM			
5		10YR-5/3; Brown silty fine sand, trace gravel, strong odor	2390	80	SM			
7.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	2390	80	SM			
10		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	3875	80	SM			
12.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	3875	80	SM			
15		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	1500	80	SM			
17.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	1500	80	SM			
20		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	380	80	SM			
22.5		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	380	80	SM			
25		10YR-5/3; Brown fine sand and silt, trace gravel, strong odor	80	80	SM			
27.5		10YR-5/3; Brown fine sand and silt, trace gravel, odor	80	80	SM			
30		10YR-5/3; Brown fine sand and silt, trace gravel, odor; rock fragments	70	80	SM			Sample obtained from 30-32.5'
32.5		Refusal at 32.5'						

Notes: Refusal at 32.5'
Sampling: B-4 Collected at 30.0'-32.5'

FIGURE: 3-e
METHOD: Direct Push
BORING COMPANY: BEI

April 29, 2020

HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-6

PROJECT: BP 4th Avenue Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-6	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		NA	0.0	NA	SM			
2.5		Refusal at 3.0'	0.0	NA	SM			
5								
7.5								
10								
12.5								
15								
17.5								
20								
22.5								
25								
27.5								
30								

Notes: Refusal at 3.0'
Sampling: No Sample Collected

FIGURE: 3-f
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-7

PROJECT: BP 4th Avenue Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY

SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-7	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		NA	0.0	NA	SM			
2.5		Refusal at 3.0'	0.0	NA	SM			
5								
7.5								
10								
12.5								
15								
17.5								
20								
22.5								
25								
27.5								
30								

Notes: Refusal at 3.0'
Sampling: No Sample Collected

FIGURE: 3-g
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

LOG OF BORING: B-8

PROJECT: BP 4th Avenue Brooklyn
CLIENT: The Macchia Group
LOCATION: 4001-4010 4th Ave, Brooklyn, NY


SUBSURFACE PROFILE			SAMPLE					
DEPTH	GRAPHIC	BORING LOCATION: B-8	PID (ppm)	Recov.%	AGI Sym			WELL DETAILS
		GROUND SURFACE						
FT 0		10YR-5/3; Brown fine sand and silt trace gravel, odor	1600	80	SM			
2.5		10YR-5/3; Brown fine sand and silt trace gravel, odor	1600	80	SM			
5		10YR-5/3; Brown fine sand and silt trace gravel, odor	1870	80	SM			
7.5		10YR-5/3; Brown fine sand and silt trace gravel, odor	1870	80	SM			
10		10YR-5/3; Brown fine sand and silt trace gravel, odor	2490	80	SM			
12.5		10YR-5/3; Brown fine sand and silt trace gravel, odor	2490	80	SM			
15		10YR-5/3; Brown fine sand and silt trace gravel, odor	1430	80	SM			
17.5		10YR-5/3; Brown fine sand and silt trace gravel, odor	1430	80	SM			
20		10YR-5/3; Brown fine sand and silt trace gravel, odor	315	80	SM			
22.5		10YR-5/3; Brown fine sand and silt trace gravel, odor	315	80	SM			
25		10YR-5/3; Brown fine sand and silt trace gravel, odor	110	80	SM			
27.5		10YR-5/3; Brown fine sand and silt trace gravel, odor	90	80	SM			
30		10YR-5/3; Brown fine sand and silt trace gravel, odor	50.2	80	SM			
32.5		10YR-5/3; Brown fine sand and silt trace gravel, no odor	25.5	80	SM			
35		Refusal at 34.0'						

Notes: Refusal at 34.0'
Sampling: No Sample Collected

FIGURE: 3-h
METHOD: Direct Push
BORING COMPANY: BEI
April 29, 2020
HOLE DIAMETER: 2.25"
LOGGED BY: Halpin and Patti

ATTACHMENTS

Attachment-A
Current Site Layout Schematic



4TH AVE

0 1 2 5 10 15 20

GASOLINE SERVICE STATION

WITH ACCESSORY CONVENIENCE STORE U.G. 16 B&E
& SELF SERVE DISPENSERS

1 PUMP & TANK SITE PLAN

1" = 10'-0"

TANK MONITORING SYSTEM NOTE(S) & LEGEND :

H = ALARM HORN

L = FLASHING LIGHT

= EMERGENCY CUT OFF SWITCH

* ALARM HORN AND FLASHING LIGHT, CONNECTED TO D.E.C. APPROVED TANK MONITORING SYSTEM TO INDICATE HIGH LEVEL ALARM.

* HIGH LEVEL ALARM, BOTH AUDIBLE AND VISUAL, TO BE TRIGGERED WHEN TANK IS NO MORE THAN 90 % FULL.

* INSTALLATION MUST BE INSTALLED IN ACCORDANCE WITH FEDERAL REGULATION - 40 CFR PARTS 280 AND 281.

NOTE: WHERE INDICATED EXISTING, STEEL SINGLE WALLED UG GASO. TANK TO BE LINED (2-TOTAL), EACH TANK MUST BE LINED AS TO COMPLY WITH ALL TESTING AND REGULATIONS THAT GOVERN INCLUDING USA FEDERAL REGULATIONS (CFR), NEW YORK STATE DEPT. OF ENVIROMENT CONSERVATION, NEW YORK CODE RULES AND REGULATIONS (NYCRR) AND NEW YORK CITY FIRE DEPARTMENT. SEE NPTES "C" & "D" ON DWG. P&T-002 FO RMORE INFORMATION.

EXISTING 2-4,000 GAL. UG SINGLE WALL STEEL FUEL TANKS TO BE LINED. REPLACE CONC. MAT, FOR MORE INFO. SEE DWG P&T-004. REPLACE MANHOLE ON EA. TANK. REMOVE ALL STP & INSTALL NEW STP AS INDICATED. REMOVE ALL PIPING, VALVES, ETC. AND INSTALL NEW AS INDICATED. (C)

TANK LEVEL MONITOR (TLM) CONNECTED TO VEEDER ROOT SYSTEM (TYP. 1-EA. TANK) (4)

BSA APPR'D EXTRACTOR FLOAT VALVE (GAL. 247-83-SM) I-REQ'D IN EA. GASO. TANK EXCEPT DIESEL TANK

(4)NEW DIRECT FILL W/ 4 NEW NYC APPR'D 15 GAL SPILL CONTAINMENT DEVICE AND MECHANICAL OVERFILL PROTECTION DEVICE ON EACH FILL LINE (5)(6)

NEW STAGE-I VAPORY RECOVERY DRYBREAK

(4) NEW 2" DIA. VENT 15' ABOVE GRADE & 10' FROM THE NEAREST BLDG. OPENING & WELL BRACED IN POSITION C.A.R.B. APPROVED P/N CAPS (GASO. TANKS ONLY), GC TO INSTALL 2" DIA. VENT MANIFOLD, SEE DET. ON DWG. P&T-007 (GASO. TANKS ONLY)

NEW 2" SINGLE WALL FIBERGLASS VENT PIPING (PICH BACK TO TANK 1/8" PER FOOT, BACKFILL PER MANUFACTURER'S SPECS.

NEW ANULAR PROBE MONITOR (1 REQ'R EA. TANK) WHERE INDICATED ONLY

(4)NEW DIRECT FILL W/ 4 NEW NYC APPR'D 15 GAL SPILL CONTAINMENT DEVICE AND MECHANICAL OVERFILL PROTECTION DEVICE ON EACH FILL LINE (5)(6)

TANK LEVEL MONITOR (TLM) CONNECTED TO VEEDER ROOT SYSTEM (TYP. 1-EA. TANK) (4)

(3) NEW TOTAL SUBMERSIBLE PUMP IN A STP SUMP, PROVIDE (4) NEW 42" DIA. MANHOLE (1) REQUIRED IN EA. TANK) (4)


STICK LINE IN MANHOLE (1 REQUIRED IN EA. TANK) WHERE INDICATED

REPLACE CONC. MAT & INSTALL NEW PIPING, ETC. AS NOTED, SEE DWGS. P&T-004, P&T-005, P&T-006 FOR MORE INFO.

EXISTING 2-4,000 GAL. UG DOUBLE WALLED MOTOR FUEL TANKS TO BE LINED. REPLACE CONC. MAT, FOR MORE INFO. SEE DWG P&T-004. REPLACE MANHOLE ON EA. TANK. REMOVE ALL STP & INSTALL NEW STP AS INDICATED. REMOVE ALL PIPING, VALVES, ETC. AND INSTALL NEW AS INDICATED. (C)
NOTE: WHERE INDICATED EXISTING, DOUBLE WALLED UG GASO. TANK TO BE LINED (2-TOTAL), EACH TANK MUST BE LINED AS TO COMPLY WITH ALL TESTING AND REGULATIONS THAT GOVERN INCLUDING USA FEDERAL REGULATIONS (CFR), NEW YORK STATE DEPT. OF ENVIROMENT CONSERVATION, NEW YORK CODE RULES AND REGULATIONS (NYCRR) AND NEW YORK CITY FIRE DEPARTMENT. SEE NPTES "C" & "D" ON DWG. P&T-002 FO RMORE INFORMATION.


NOTE

1. EXACT LOCATION OF EXISTING TANK FITTINGS TO BE VERIFY IN THE FIELD.



U-BOLLARD DETAIL

N.T.S.



DRIVE MAT DETAIL

1" = 1'-0"

NOTES:

(1) REMOVE ALL EXISTING CONCRETE PUMP ISLAND, DISPENSERS, TANK STP SUMPS, FILLS, VAPOR RECOVERY MANHOLES, TOP SLAB, AND RELATED PIPING AND REPLACE WITH AMERON DUALOY 3000/L NONMETALLIC PIPING UNLESS OTHERWISE NOTED. DISPENSERS TO BE REFURBISHED AND REUSED.

(2) PIPING SHOWN IS DIAGRAMMATIC ONLY. REFER TO MANUFACTURER'S INSTALLATION MANUAL FOR PROPER INSTALLATION.

(3) GENERAL CONTRACTOR TO VERIFY IN FIELD THE EXACT NUMBER OF TANK OPENINGS AND FITTING LOCATIONS AND NOTIFY ARCHITECT OF ANY DISCREPANCIES.

(4) AT THE TIME OF COMPLETION THE CONTRACTOR SHALL FILE AN AFFIDAVIT WITH THE NEW YORK CITY FIRE DEPARTMENT STATING WORK AND REQUIRED TESTS PERFORMED ON ANY TANKS/PIPING, TESTS RESULTS SHALL BE NOTED AND A COPY SHALL BE SENT TO THE OWNER AND THE ARCHITECT.

(5) GENERAL CONTRACTOR SHALL BE RESPONSIBLE FOR ALL APPLICABLE TESTING/INSPECTIONS OF TANKS AND PIPING SYSTEM UPON COMPLETION OF PROJECT AS REQUIRED BY THE NEW YORK CITY FIRE DEPARTMENT RULES AND REGULATIONS. GENERAL CONTRACTOR TO CONTACT THE NEW YORK CITY FIRE DEPARTMENT AT (718) 644.2462 FOR THIS INFORMATION.

(6) CONTRACTOR MUST CONFORM TO THE REQUIREMENTS OF THE NEW YORK CITY ELECTRICAL CODE AND FILE A CERTIFICATE OF ELECTRICAL INSPECTION UPON COMPLETION OF THE WORK WITH THE NEW YORK CITY FIRE DEPARTMENT.

(7) LOCATION AND NUMBER OF EXISTING PUMPS AND TANKS TO BE VERIFIED BY THE NEW YORK CITY FIRE DEPARTMENT.

(8) THE BIDDING CONTRACTOR SHALL VISIT THE SITE AND BECOME FAMILIAR WITH ALL EXISTING CONDITIONS AND PROPOSED WORK ITEMS TO BE COMPLETED AS NOTED ON THE DRAWINGS PRIOR TO BIDDING.

(9) THE CONTRACTOR SHALL VERIFY THE TYPE AND EXACT LOCATION OF ALL EXISTING TANK PIPING, MPD'S PANS, AND FITTING PENETRATIONS INTO THE TANK. NOTIFY ARCHITECT OF RECORD IN WRITING OF ANY DISCREPANCIES PRIOR TO CONSTRUCTION.

(10) ANY UNDERGROUND DRAINAGE LINES, WATER LINES, SEWER LINES, ELECTRICAL LINES, ETC. THAT MAY BE ENCOUNTERED DURING THE COURSE OF CONSTRUCTION SHALL BE REMOVED AND REROUTED AS REQUIRED. GENERAL CONTRACTOR TO NOTIFY ARCHITECT AND OWNER IMMEDIATELY.

(11) PROVIDE COLOR AND SYMBOL CODES ON ALL FILLS AND GAUGE PORTS AS PER A.P.I., N.Y.S.D.E.C. AND OWNER'S STANDARDS. PRODUCT I.D. MARKERS SHALL BE INSTALLED ON ALL FILL PORTS PER N.Y.S.D.E.C. REQUIREMENTS.

(12) GENERAL CONTRACTOR TO PRECISION TEST TANKS, PIPING SYSTEM, ETC. PRIOR TO CONSTRUCTION OF PROJECT AS PER NEW YORK CITY FIRE DEPARTMENT RULES AND REGULATIONS. GENERAL CONTRACTOR SHALL SECURE THE SERVICES OF THE NEW YORK CITY FIRE DEPARTMENT FOR TESTING PURPOSES. AFTER INSTALLATION GENERAL CONTRACTOR SHALL SCHEDULE A TEST TO BE DONE BY OWNER ON TANKS, PIPING, ETC. GENERAL CONTRACTOR SHALL NOT BACK FILL UNTIL ALL TESTING HAS BEEN DONE.

(13) GENERAL CONTRACTOR SHALL BE RESPONSIBLE FOR PROVIDING A "SPARK TEST" OF THE CATHODICALLY PROTECTED PIPE WITNESSED BY A NEW YORK CITY FIRE DEPARTMENT INSPECTOR BEFORE BACK FILL INSPECTION IS SCHEDULED. (IF APPLICABLE)

(14) GENERAL CONTRACTOR TO ASSURE THAT ELECTRICAL EXPLOSION PROOF CONNECTIONS ARE PROVIDED AND IN GOOD CONDITION AT EACH TANK SUMP AS REQUIRED PER N.F.P.A. AND N.E.C. CODES.

(15) GENERAL CONTRACTOR SHALL PATCH AND REPAIR AREAS OF THE CONCRETE DRIVE MAT, SURROUNDING THE ISLANDS, DISTURBED BY CONSTRUCTION WITH A MINIMUM OF 0'-8" THICK CONCRETE, 0'-4" CRUSHED STONE AND (1) LAYER OF #5 REBARS EACH WAY.

N.Y.C. FIRE DEPARTMENT APPROVAL / EQUIPMENT LIST

EQ. NO.	EQUIPMENT	MANUFACTURER	MODEL NUMBER	C of A NUMBER
(1)	MULTI-PRODUCT BLENDER DISPENSER W/SB3	"WAYNE" OVATION	B12/B223DI/6K DOB 2-HOSE	5082
	DISPENSER PAN	ENVIRO	DEEP PAN	
(2)	NOT USED			
(3)	UNDERGROUND PIPING	SMITH FIBERCAST	RED THREAD IIA	5099
(4)	SUBMERSIBLE TURBINE PUMP	FE PETRO	1 1/2 HP W/ INTAKE FILTER SCREEN	4834
(5)	MECHANICAL OVERFILL PREVENTION DEVICE	OPW	61SO (GRAVITY FILL)	4902
(6)	SPILL CONTAINMENT DEVICE	OPW	1-2115 (15 GALLON)	4978
(7)	FLEXIBLE CONNECTOR	TITEFLEX	FIRESAFE	
(8)	EXTRACTOR FITTING - CROSS	OPW	233VM-4433	
(9)	LEAK DETECTION SYSTEM	VEEDER ROOT	TLS 350	4853
	AUTOMATIC TANK GAUGE TANK LEVEL PROBE TANK HYDROSTATIC SUMP SENSOR ELECTRONIC LINE LEAK DETECTOR STP SUMP SENSOR DISPENSER PAN SENSOR			
(10)	EXIST. DOUBLE WALLED TANKS TO BE LINED	VIF	EXIST. (2-TOTAL) 4000 GALLONS	VIF
(11)	EXIST. STEEL SINGLE WALLED TANKS TO BE LINED	VIF	EXIST. (2-TOTAL) 4000 GALLONS	VIF

AS-BUILT DRAWINGS & INSTALLER STATEMENT:

G.C./ INSTALLER SHALL PROVIDE A COMPLETE SET OF AS BUILT DRAWINGS TO SCALE DEPICTING PRECISE LOCATION OF ALL COMPONENTS INSTALLED (INCLUDING PRODUCT/ VAPOR LINE SIZES & LOCATIONS, CONDUIT SIZES & LOCATIONS, ETC.) PRIOR TO OWNER'S ACCEPTANCE.

THESE PLANS MUST INCLUDE A STATEMENT BY THE INSTALLER THAT THE SYSTEM HAS BEEN INSTALLED IN COMPLIANCE WITH THE NEW YORK STATE STANDARDS FOR NEW AND SUBSTANTIALLY MODIFIED PETROLEUM STORAGE FACILITIES, 6 NYCRR PART 614.

LICENSED INSTALLER'S FINAL STATEMENT

I, _____ COMPLETED THE INSTALLATION OF THE EQUIPMENT DESCRIBED IN THE ANNEXED PLANS ON _____. THE INSTALLATION COMPLIES FULLY WITH THE REQUIREMENTS OF THE NEW YORK STATE PETROLEUM BULK STORAGE CODE 6 NYCRR PART 614.

_____
SIGNATURE OF THE LICENSED INSTALLER

FILL BOX IDENTIFICATION REQUIREMENTS:

IDENTIFICATION REQUIREMENTS SHALL CONFORM TO AMERICAN PETROLEUM INSTITUTE STANDARDS

AMENDED

VAPOR HOSE CONNECTION:	UNLEADED (LOWER)	UNLEADED (HIGHER)	DIESEL
ORANGE	BLACK CROSS WHITE BACKGROUND	WHITE CROSS RED BACKGROUND	YELLOW

ACCEPTABLE FOR PERMIT UNDER DIRECTIVE NO. 14/1975
DEC 28 2010
KAUSAR AHMAD

320041897
SC343628763

REV	DATE	DESCRIPTION
-	6-17-09	ISSUED TO BID
-	6-24-09	ISSUED TO BLDG DEPT. FOR APPROVAL
-	8-31-09	AS BUILT CONDITIONS

DRAWING: PUMP & TANK SITE PLAN AND EQUIPMENT SCHEDULE

LOCATION: 4001 4th LLC
4001-11 4th AVE
BROOKLYN, NEW YORK

BLOCK 774 | LOT 6 | MAP --- | ZONE C-8 IN R6

VASSALOTTI ARCHITECTS, L.L.P.
ASSOCIATES
3000 MARCUS AVE. LAKE SUCCESS, NY 11042

DWN. BY	CHK. BY
JEFF V.	A.D.

SCALE: AS NOTED

DATE	JOB NO.
6-17-09	08-0071

PAGE NO.: DWG. 4 OF 9

DWG. NO.: P&T-004.00

Attachment-B
Previous Phase II ESA

Attachment-C
Lab Data Package

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

May 13, 2020

Justin Halpin
WRS d.b.a Berninger Environmental
17 Old Dock Road
Yaphank, NY 11980
TEL: (631) 589-6521
FAX: (631) 589-6528

RE: BP Gas; 4001-4010 4th Avenue, Brooklyn, Order No.: 2005010

Dear Justin Halpin:

American Analytical Laboratories, LLC. received 2 sample(s) on 5/1/2020 for the analyses presented in the following report.

Samples were analyzed in accordance with the test procedures documented on the chain of custody and detailed throughout the text of this report. The results reported herein relate only to the items tested or to the samples as received by the laboratory. This report may not be reproduced, except in full, without the approval of American Analytical Laboratories, LLC and is not considered complete without a cover page and chain of custody documentation. The limits (LOQ) provided in the data package are analytical reporting limits and not Federal or Local mandated values to which the sample results should be compared.

There were no problems with the analyses and all data for associated QC met laboratory specifications. If there are any exceptions a Case Narrative is provided in the report or the data is qualified either on the sample results or in the QC section of the report. This package has been reviewed by American Analytical Laboratories' QA Department/Laboratory Director to comply with NELAC standards prior to report submittal.

If you have any questions regarding these tests results, please do not hesitate to call (631) 454-6100 or email me directly at lbeyer@american-analytical.com.

Sincerely,

Lori Beyer

Lori Beyer
Lab Director
American Analytical Laboratories, LLC.

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Workorder Sample Summary

WO#: **2005010**

13-May-20

CLIENT: WRS d.b.a Berninger Environmental

Project: BP Gas; 4001-4010 4th Avenue, Brooklyn, NY

Lab SampleID	Client Sample ID	Tag No	Date Collected	Date Received	Matrix
2005010-001A	B-4 @ 27.5-30'		4/29/2020 11:30:00 AM	5/1/2020 11:15:00 AM	Soil
2005010-002A	B-5 @ 30-32.5'		4/29/2020 1:00:00 PM	5/1/2020 11:15:00 AM	Soil

CHAIN OF CUSTODY

AMERICAN ANALYTICAL LABORATORIES

56 Toledo Street, Farmingdale NY 11735
(T) 631-454-6100 (F) 631-454-8027
www.american-analytical.com

CERTIFICATIONS
NY ELAP - 11418 PA DEP - 68-00573
NJ DEP - NY050 CT DOH - PH-0205

Client Information

Company Name: BEI
Address: 17 Old Dock Rd.
City: Yaphank State: NY Zip: 11980
Project Contact: Justin H.
Phone #: 631-589-6521
E-mail: jhalpin2nurses.com

Project Information

Project Name: BP Gas
Street: 4001-4010 4th Avenue
City: Brooklyn State: NY Zip:
Project # / Purchase Order #: 15487
Sampler's Name / Company: Justin H. / BEI
Sampler's Signature:

Analytical Test / Information

8260 (VOC's)

LAB SAMPLE # (LAB USE ONLY)	Sample Information: Client Sample ID	Sample Type	Matrix Code	Sample Collection: Date	Time	Glass / Plastic	Sample Containers: Total # of bottles	Number of Each Preserved Bottle: NONE	HCl	NaOH	HNO_3	H_2SO_4	DI Water (5035A)	MeOH	OTHER	8260 (VOC's)
2005010-001	B-4 @ 27.5-30'	G	S	4/29/20	11:30	G	1	X								X
002	B-5 @ 30-32.5'	G	S	↓	11:00	G	1	X								X

Turnaround Time (Business Days)

Standard
- [x] 7-10 Business Days
- [ ] 5 Day *RUSH*
- [ ] 4 Day *RUSH*
- [ ] 3 Day *RUSH*
- [ ] 2 Day *RUSH*
- [ ] 1 Day *RUSH*

Please contact laboratory for rush service availability

SAMPLE TYPE
G = Grab
C = Composite
B = Blank

MATRIX CODE
L = Liquid, PC = Paint Chip
S = Soil, SL = Sludge
O = Oil, SD = Solid
W = Wipe, M = Misc

ELECTRONIC DELIVERABLES
NYCRR Part 375 - please circle
Unres/ Comm/ Industrial/ Residential/ Res Residential/ PGW
NJ Soil Clean Up Criteria
CP 51 - Gas / Fuel
TOGS
SCDOH Action Levels
TCLP Hazardous Waste
NYSDEC EQUIS

Comments / Remarks
Rot 32/09
Cooler Temp: 2.4C

Sample custody must be documented below, each time samples change possession, with a signature, date, and time.

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME
	5/1/20 11:15	Toby Wedgwood	P Masi	5/1/20 11:15	P Masi
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Sample Log-In Check List

Client Name: Berninger Work Order Number: 2005010 RcptNo: 1

Logged by:	Lori Beyer	5/1/2020 11:15:00 AM	Lori Beyer
Completed By:	Lori Beyer	5/1/2020 11:16:32 AM	Lori Beyer
Reviewed By:	Phyllis Masi	5/4/2020	Phyllis Masi

Chain of Custody

1.	Is Chain of Custody complete?	Yes ☑	No ☐	Not Present ☐
2.	How was the sample delivered?	Client		

Log In

3.	Coolers are present?	Yes ☑	No ☐	NA ☐
4.	Shipping container/cooler in good condition?	Yes ☑	No ☐	
	Custody seals intact on shipping container/cooler?	Yes ☐	No ☐	Not Present ☑
	No. Seal Date:	Signed By:		
5.	Was an attempt made to cool the samples?	Yes ☑	No ☐	NA ☐
6.	Were all samples received at a temperature of >0° C to 6.0°C	Yes ☑	No ☐	NA ☐
7.	Sample(s) in proper container(s)?	Yes ☑	No ☐	
8.	Sufficient sample volume for indicated test(s)?	Yes ☑	No ☐	
9.	Are samples (except VOA and ONG) properly preserved?	Yes ☑	No ☐	
10.	Was preservative added to bottles?	Yes ☐	No ☑	NA ☐
11.	Is the headspace in the VOA vials less than 1/4 inch or 6 mm?	Yes ☐	No ☐	No VOA Vials ☑
12.	Were any sample containers received broken?	Yes ☐	No ☑	
13.	Does paperwork match bottle labels? (Note discrepancies on chain of custody)	Yes ☑	No ☐	
14.	Are matrices correctly identified on Chain of Custody?	Yes ☑	No ☐	
15.	Is it clear what analyses were requested?	Yes ☑	No ☐	
16.	Were all holding times able to be met? (If no, notify customer for authorization.)	Yes ☑	No ☐	

Special Handling (if applicable)

17. Was client notified of all discrepancies with this order? Yes ☐ No ☐ NA ☑

Person Notified: _____ Date: _____
By Whom: _____ Via: ☐ eMail ☐ Phone ☐ Fax ☐ In Person
Regarding: _____
Client Instructions: _____

18. Additional remarks:

Cooler Information

Cooler No	Temp ºC	Condition	Seal Intact	Seal No	Seal Date	Signed By

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Case Narrative

WO#: **2005010**
Date: **5/13/2020**

CLIENT: WRS d.b.a Berninger Environmental
Project: BP Gas; 4001-4010 4th Avenue, Brooklyn, NY

Samples were analyzed using the methods outlined in the following references:

Test Methods for Evaluating Solid Waste, Physical/Chemical Methods, SW846 and additional methods as detailed throughout the text of the report. All method blanks, laboratory spikes, and/or matrix spikes met quality assurance objectives with exceptions notated in this Narrative discussion.

Soil sample results analyzed for Volatile Organics via preparation method SW846 Method 5035A by the Low Level procedures potentially may be estimated, "J" (biased low) since the samples for this test were not collected according to the 5035A Method. Analysis was performed from intact soil jar. Volatile LCS are analyzed with preservatives - HCL/Methanol depending on level of analysis (high/low) similar to sample analysis. Outliers can be attributed to the presence of chemical preservatives. 2-Chloroethyl vinyl ether readily breaks down under acidic conditions. Samples that are acid preserved, including standards will exhibit breakdown. The data user should take note.

Sample B-4 @ 27.5-30' required reanalysis at high level due to heavy matrix interferences.

The following parameters (if included in this report) are not offered by NY ELAP: VOA 8260 Soil; 1,2,4,5-Tetramethylbenzene, Chlorodifluoromethane, Diisopropyl ether, Ethanol, Freon-114, p-Diethylbenzene, p-Ethyltoluene, Limonene. VOA 8260 Liquid; 1,2,4,5-Tetramethylbenzene, Chlorodifluoromethane, Freon-114, p-Diethylbenzene, p-Ethyltoluene, Limonene. Pesticides 8081 Soil; DBCP. Herbicides 8151 Soil; 3,5-Dichlorobenzoic Acid, 4-Nitrophenol, Acifluorfen, Bentazon, Chloramben, DCPA, Picloram, SM 2540G Total Volatile Solids, Soil TKN, Soil Organic Nitrogen, Total Phosphorus in soil, Percent Moisture, pH in non-potable water and temperature at which pH is measured, SM 4500-SO3 B Sulfite in Liquid, Total Sulfur in Soil, Acid Soluble Chloride by ASTMC1152, Water Soluble Chloride by ASTMC1218, Chlorine Demand by SM 2350 B, Total Residual Chlorine in Liquid and Reactivity to Sulfide and Reactivity to Cyanide.

The test results meet the requirements of the NYSDOH and NELAC standards, except where noted. The information contained in this analytical report is the sole property of American Analytical Laboratories, LLC. or the client for which this report was issued. The results contained in this report are only representative of the samples received. The sample receipt checklist is included as part of this lab report. Conditions can vary at different times and at different sampling conditions. American Analytical is not responsible for the use or interpretation of the data included herein.

American Analytical Laboratories, LLC.
56 Toledo Street
Farmingdale, New York 11735
TEL: (631) 454-6100 FAX: (631) 454-8027
Website: www.American-Analytical.com

Definition Only

WO#: **2005010**
Date: **5/13/2020**

Definitions:

Sample Result and QC Summary Qualifiers - Level I and Level II Reports
ND - Not detected at the reporting limit/Limit of Quantitation

B - The analyte was detected in the associated method blank. For volatiles, methylene chloride and acetone are common lab contaminants. Data users should consider anything <5x the blank value as artifact.

E - The value is above the quantitation range

D - Analyte concentration was obtained from diluted analysis or from analysis using reduced sample volume.

J - The analyte was detected below the limit of quantitation but greater than the established Limit of Detection (LOD). There is greater uncertainty associated with these results and data should be considered as estimated.

U - The compound was analyzed for but not detected.

H - Holding time for preparation or analysis has been exceeded.

S - Spike recovery is outside accepted recovery limits.

R - RPD is outside accepted recovery range.

P - Secondary column exceeds 40% difference for GC test.

* - Calibration exceeds method requirement. Due to the large number of analytes for organic testing, the method allows 10% of analytes to have %RSD and/or %D to be >20%.
LOD - Limit of Detection; the lowest level the analyte can be determined to be statistically different from a blank.
LOQ - Limit of Quantitation; the lowest amount of analyte in a sample that can be quantitatively determined with suitable precision and accuracy.
PQL - Practical Quantitation Limit; the lowest level that can be reliably achieved within the specific limits of Precision and accuracy. Listed on the QC Summary Forms.
m - Analyte was manually integrated for GC/MS.
+ - Concentration exceeds regulatory level for TCLP

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-4 @ 27.5-30'
Lab Order:	2005010	**Collection Date:**	4/29/2020 11:30:00 AM
Project:	BP Gas; 4001-4010 4th Avenue, Brooklyn, NY	**Matrix:**	SOIL
Lab ID:	2005010-001A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
PERCENT MOISTURE			**D2216**				Analyst: **JaP**
Percent Moisture	10.6	0	1.00		wt%	1	5/5/2020 9:00:00 AM
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
1,1,1,2-Tetrachloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1,1-Trichloroethane	4.0	1.1	5.7	J	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1,2,2-Tetrachloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1,2-Trichloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1-Dichloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1-Dichloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,1-Dichloropropene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2,3-Trichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2,3-Trichloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2,4,5-Tetramethylbenzene	5100	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
1,2,4-Trichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2,4-Trimethylbenzene	28000	280	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
1,2-Dibromo-3-chloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2-Dibromoethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2-Dichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2-Dichloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,2-Dichloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,3,5-Trimethylbenzene	9600	280	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
1,3-Dichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,3-dichloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,4-Dichlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
1,4-Dioxane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
2,2-Dichloropropane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
2-Butanone	ND	5.7	11	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
2-Chloroethyl vinyl ether	ND	11	23	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
2-Chlorotoluene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
2-Hexanone	ND	5.7	11	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
2-Propanol	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
4-Chlorotoluene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-4 @ 27.5-30'
Lab Order:	2005010	**Collection Date:**	4/29/2020 11:30:00 AM
Project:	BP Gas; 4001-4010 4th Avenue, Brooklyn, NY	**Matrix:**	SOIL
Lab ID:	2005010-001A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
4-Isopropyltoluene	3000	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
4-Methyl-2-pentanone	ND	5.7	11	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Acetone	ND	5.7	11	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Benzene	850	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
Bromobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Bromochloromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Bromodichloromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Bromoform	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Bromomethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Carbon disulfide	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Carbon tetrachloride	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Chlorobenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Chlorodifluoromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Chloroethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Chloroform	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Chloromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
cis-1,2-Dichloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
cis-1,3-Dichloropropene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Cyclohexane	8700	110	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
Dibromochloromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Dibromomethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Dichlorodifluoromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Diisopropyl ether	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Ethanol	ND	57	57	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Ethylbenzene	9500	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
Freon-114	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Hexachlorobutadiene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Isopropylbenzene	1900	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
m,p-Xylene	34000	560	2800	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
Methyl Acetate	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Methyl tert-butyl ether	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Methylene chloride	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
n-Butylbenzene	2400	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-4 @ 27.5-30'
Lab Order:	2005010	**Collection Date:**	4/29/2020 11:30:00 AM
Project:	BP Gas; 4001-4010 4th Avenue, Brooklyn, NY	**Matrix:**	SOIL
Lab ID:	2005010-001A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
n-Propylbenzene	10000	56	280	D	µg/Kg-dry	50	5/12/2020 5:59:00 AM
Naphthalene	210	1.1	5.7		µg/Kg-dry	1	5/7/2020 7:10:00 AM
o-Xylene	13000	280	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
p-Diethylbenzene	10000	280	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
p-Ethyltoluene	21000	280	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
sec-Butylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Styrene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
t-Butyl alcohol	ND	2.9	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
tert-Butylbenzene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Tetrachloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Toluene	17000	280	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
trans-1,2-Dichloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
trans-1,3-Dichloropropene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Trichloroethene	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Trichlorofluoromethane	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Vinyl acetate	210	1.1	5.7		µg/Kg-dry	1	5/7/2020 7:10:00 AM
Vinyl chloride	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Xylenes, Total	47000	850	4200	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
Methylcyclohexane	29000	560	1400	D	µg/Kg-dry	250	5/12/2020 10:48:00 PM
Acrolein	ND	14	29	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM
Acrylonitrile	ND	1.1	5.7	U	µg/Kg-dry	1	5/7/2020 7:10:00 AM

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-5 @ 30-32.5'
Lab Order:	2005010	**Collection Date:**	4/29/2020 1:00:00 PM
Project:	BP Gas; 4001-4010 4th Avenue, Brooklyn, NY	**Matrix:**	SOIL
Lab ID:	2005010-002A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
PERCENT MOISTURE			**D2216**				Analyst: **JaP**
Percent Moisture	10.2	0	1.00		wt%	1	5/5/2020 9:00:00 AM
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
1,1,1,2-Tetrachloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1,1-Trichloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1,2,2-Tetrachloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1,2-Trichloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1-Dichloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1-Dichloroethene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,1-Dichloropropene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2,3-Trichlorobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2,3-Trichloropropane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2,4,5-Tetramethylbenzene	1.7	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2,4-Trichlorobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2,4-Trimethylbenzene	13	1.1	5.6		µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2-Dibromo-3-chloropropane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2-Dibromoethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2-Dichlorobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2-Dichloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,2-Dichloropropane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,3,5-Trimethylbenzene	2.6	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,3-Dichlorobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,3-dichloropropane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,4-Dichlorobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
1,4-Dioxane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
2,2-Dichloropropane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
2-Butanone	ND	5.6	11	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
2-Chloroethyl vinyl ether	ND	11	22	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
2-Chlorotoluene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
2-Hexanone	ND	5.6	11	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
2-Propanol	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
4-Chlorotoluene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM

American Analytical Laboratories, LLC.

Date: *13-May-20*

ELAP ID : 11418

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-5 @ 30-32.5'
Lab Order:	2005010	**Collection Date:**	4/29/2020 1:00:00 PM
Project:	BP Gas; 4001-4010 4th Avenue, Brooklyn, NY	**Matrix:**	SOIL
Lab ID:	2005010-002A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
4-Isopropyltoluene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
4-Methyl-2-pentanone	ND	5.6	11	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Acetone	19	5.6	11		µg/Kg-dry	1	5/7/2020 3:08:00 PM
Benzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Bromobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Bromochloromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Bromodichloromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Bromoform	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Bromomethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Carbon disulfide	2.3	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Carbon tetrachloride	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Chlorobenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Chlorodifluoromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Chloroethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Chloroform	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Chloromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
cis-1,2-Dichloroethene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
cis-1,3-Dichloropropene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Cyclohexane	ND	2.2	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Dibromochloromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Dibromomethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Dichlorodifluoromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Diisopropyl ether	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Ethanol	ND	56	56	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Ethylbenzene	2.3	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Freon-114	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Hexachlorobutadiene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Isopropylbenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
m,p-Xylene	9.6	2.2	11	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Methyl Acetate	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Methyl tert-butyl ether	30	1.1	5.6		µg/Kg-dry	1	5/7/2020 3:08:00 PM
Methylene chloride	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
n-Butylbenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM

American Analytical Laboratories, LLC.

Date: *13-May-20*

ELAP ID : 11418

CLIENT:	WRS d.b.a Berninger Environmental	**Client Sample ID:**	B-5 @ 30-32.5'
Lab Order:	2005010	**Collection Date:**	4/29/2020 1:00:00 PM
Project:	BP Gas; 4001-4010 4th Avenue, Brooklyn, NY	**Matrix:**	SOIL
Lab ID:	2005010-002A		

Certificate of Results

Analyses	Sample Result	LOD	LOQ	Qual	Units	DF	Date/Time Analyzed
VOLATILE SW-846 METHOD 8260D			**SW8260D**		**SW5035A**		Analyst: **IR**
n-Propylbenzene	1.6	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Naphthalene	9.9	1.1	5.6		µg/Kg-dry	1	5/7/2020 3:08:00 PM
o-Xylene	6.0	1.1	5.6		µg/Kg-dry	1	5/7/2020 3:08:00 PM
p-Diethylbenzene	2.3	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
p-Ethyltoluene	7.7	1.1	5.6		µg/Kg-dry	1	5/7/2020 3:08:00 PM
sec-Butylbenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Styrene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
t-Butyl alcohol	ND	2.8	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
tert-Butylbenzene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Tetrachloroethene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Toluene	5.4	1.1	5.6	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
trans-1,2-Dichloroethene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
trans-1,3-Dichloropropene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Trichloroethene	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Trichlorofluoromethane	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Vinyl acetate	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Vinyl chloride	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Xylenes, Total	16	3.4	17	J	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Methylcyclohexane	ND	2.2	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Acrolein	ND	14	28	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM
Acrylonitrile	ND	1.1	5.6	U	µg/Kg-dry	1	5/7/2020 3:08:00 PM

Table-1
Tabulated Soil Data

American Analytical Laboratories, LLC. 2005010
WorkOrder: 2005010
Client: WRS d.b.a Berninger Environmental
Project: BP Gas; 4001-4010 4th Avenue, Brooklyn, NY

		Client Sample ID:		B-4 @ 27.5-30'		B-5 @ 30-32.5'		DEC Part 375	DEC Part 375
		Laboratory ID:		2005010-001		2005010-002		Unrestricted Use/	Restricted
		Sampling Date:		04/29/2020		04/29/2020		*-CP-51 Protection	Residential
Cas #:	Procedure:	Analyte:	Units:		Q		Q	of GW / Eco Res.	
E-11870	PERCENT MOISTURE	Percent Moisture	wt%	10.6		10.2		NA	NA
630-20-6	VOLATILE SW-846 METHOD 8260D	1,1,1,2-Tetrachloroethane	PPB	1.1	U	1.1	U	NA	NA
71-55-6	VOLATILE SW-846 METHOD 8260D	1,1,1-Trichloroethane	PPB	4.0	J	1.1	U	680	100,000
79-34-5	VOLATILE SW-846 METHOD 8260D	1,1,2,2-Tetrachloroethane	PPB	1.1	U	1.1	U	600*	NA
76-13-1	VOLATILE SW-846 METHOD 8260D	1,1,2-Trichloro-1,2,2-trifluoroethane	PPB	1.1	U	1.1	U	NA	NA
79-00-5	VOLATILE SW-846 METHOD 8260D	1,1,2-Trichloroethane	PPB	1.1	U	1.1	U	NA	NA
75-34-3	VOLATILE SW-846 METHOD 8260D	1,1-Dichloroethane	PPB	1.1	U	1.1	U	270	26,000
75-35-4	VOLATILE SW-846 METHOD 8260D	1,1-Dichloroethene	PPB	1.1	U	1.1	U	330	100,000
563-58-6	VOLATILE SW-846 METHOD 8260D	1,1-Dichloropropene	PPB	1.1	U	1.1	U	NA	NA
87-61-6	VOLATILE SW-846 METHOD 8260D	1,2,3-Trichlorobenzene	PPB	1.1	U	1.1	U	20,000*	NA
96-18-4	VOLATILE SW-846 METHOD 8260D	1,2,3-Trichloropropane	PPB	1.1	U	1.1	U	340*	NA
95-93-2	VOLATILE SW-846 METHOD 8260D	1,2,4,5-Tetramethylbenzene	PPB	5100	D	1.7	J	NA	NA
120-82-1	VOLATILE SW-846 METHOD 8260D	1,2,4-Trichlorobenzene	PPB	1.1	U	1.1	U	3,400*	NA
95-63-6	VOLATILE SW-846 METHOD 8260D	**1,2,4-Trimethylbenzene**	PPB	28000	D	13		*3,600*	52,000
96-12-8	VOLATILE SW-846 METHOD 8260D	1,2-Dibromo-3-chloropropane	PPB	1.1	U	1.1	U	NA	NA
106-93-4	VOLATILE SW-846 METHOD 8260D	1,2-Dibromoethane	PPB	1.1	U	1.1	U	NA	NA
95-50-1	VOLATILE SW-846 METHOD 8260D	1,2-Dichlorobenzene	PPB	1.1	U	1.1	U	1,100	100,000
107-06-2	VOLATILE SW-846 METHOD 8260D	1,2-Dichloroethane	PPB	1.1	U	1.1	U	20	3,100
78-87-5	VOLATILE SW-846 METHOD 8260D	1,2-Dichloropropane	PPB	1.1	U	1.1	U	700,000*	NA
108-67-8	VOLATILE SW-846 METHOD 8260D	**1,3,5-Trimethylbenzene**	PPB	9600	D	2.6	J	*8,400*	52,000
541-73-1	VOLATILE SW-846 METHOD 8260D	1,3-Dichlorobenzene	PPB	1.1	U	1.1	U	2,400	49,000
142-28-9	VOLATILE SW-846 METHOD 8260D	1,3-dichloropropane	PPB	1.1	U	1.1	U	300*	NA
106-46-7	VOLATILE SW-846 METHOD 8260D	1,4-Dichlorobenzene	PPB	1.1	U	1.1	U	1,800	13,000
123-91-1	VOLATILE SW-846 METHOD 8260D	1,4-Dioxane	PPB	1.1	U	1.1	U	100	13,000
594-20-7	VOLATILE SW-846 METHOD 8260D	2,2-Dichloropropane	PPB	1.1	U	1.1	U	NA	NA
78-93-3	VOLATILE SW-846 METHOD 8260D	2-Butanone	PPB	5.7	U	5.6	U	300*	NA
110-75-8	VOLATILE SW-846 METHOD 8260D	2-Chloroethyl vinyl ether	PPB	11	U	11	U	NA	NA
95-49-8	VOLATILE SW-846 METHOD 8260D	2-Chlorotoluene	PPB	1.1	U	1.1	U	NA	NA
591-78-6	VOLATILE SW-846 METHOD 8260D	2-Hexanone	PPB	5.7	U	5.6	U	NA	NA
67-63-0	VOLATILE SW-846 METHOD 8260D	2-Propanol	PPB	1.1	U	1.1	U	NA	NA
106-43-4	VOLATILE SW-846 METHOD 8260D	4-Chlorotoluene	PPB	1.1	U	1.1	U	NA	NA
99-87-6	VOLATILE SW-846 METHOD 8260D	4-Isopropyltoluene	PPB	3000	D	1.1	U	10,000	NA
108-10-1	VOLATILE SW-846 METHOD 8260D	4-Methyl-2-pentanone	PPB	5.7	U	5.6	U	100*	NA
67-64-1	VOLATILE SW-846 METHOD 8260D	Acetone	PPB	5.7	U	19		50	100,000
71-43-2	VOLATILE SW-846 METHOD 8260D	**Benzene**	PPB	850	D	1.1	U	*60*	4,800
108-86-1	VOLATILE SW-846 METHOD 8260D	Bromobenzene	PPB	1.1	U	1.1	U	NA	NA
74-97-5	VOLATILE SW-846 METHOD 8260D	Bromochloromethane	PPB	1.1	U	1.1	U	NA	NA
75-27-4	VOLATILE SW-846 METHOD 8260D	Bromodichloromethane	PPB	1.1	U	1.1	U	NA	NA
75-25-2	VOLATILE SW-846 METHOD 8260D	Bromoform	PPB	1.1	U	1.1	U	NA	NA
74-83-9	VOLATILE SW-846 METHOD 8260D	Bromomethane	PPB	1.1	U	1.1	U	NA	NA
75-15-0	VOLATILE SW-846 METHOD 8260D	Carbon disulfide	PPB	1.1	U	2.3	J	2,700*	NA
56-23-5	VOLATILE SW-846 METHOD 8260D	Carbon tetrachloride	PPB	1.1	U	1.1	U	760	2,400
108-90-7	VOLATILE SW-846 METHOD 8260D	Chlorobenzene	PPB	1.1	U	1.1	U	1,100	100,000
75-45-6	VOLATILE SW-846 METHOD 8260D	Chlorodifluoromethane	PPB	1.1	U	1.1	U	NA	NA
75-00-3	VOLATILE SW-846 METHOD 8260D	Chloroethane	PPB	1.1	U	1.1	U	NA	NA
67-66-3	VOLATILE SW-846 METHOD 8260D	Chloroform	PPB	1.1	U	1.1	U	370	49,000
74-87-3	VOLATILE SW-846 METHOD 8260D	Chloromethane	PPB	1.1	U	1.1	U	NA	NA
156-59-2	VOLATILE SW-846 METHOD 8260D	cis-1,2-Dichloroethene	PPB	1.1	U	1.1	U	250	100,000
10061-01-5	VOLATILE SW-846 METHOD 8260D	cis-1,3-Dichloropropene	PPB	1.1	U	1.1	U	NA	NA
110-82-7	VOLATILE SW-846 METHOD 8260D	Cyclohexane	PPB	8700	D	2.2	U	NA	NA
124-48-1	VOLATILE SW-846 METHOD 8260D	Dibromochloromethane	PPB	1.1	U	1.1	U	10,000*	NA
74-95-3	VOLATILE SW-846 METHOD 8260D	Dibromomethane	PPB	1.1	U	1.1	U	NA	NA
75-71-8	VOLATILE SW-846 METHOD 8260D	Dichlorodifluoromethane	PPB	1.1	U	1.1	U	NA	NA
108-20-3	VOLATILE SW-846 METHOD 8260D	Diisopropyl ether	PPB	1.1	U	1.1	U	NA	NA
64-17-5	VOLATILE SW-846 METHOD 8260D	Ethanol	PPB	57	U	56	U	NA	NA
100-41-4	VOLATILE SW-846 METHOD 8260D	**Ethylbenzene**	PPB	9500	D	2.3	J	*1,000*	41,000
76-14-2	VOLATILE SW-846 METHOD 8260D	Freon-114	PPB	1.1	U	1.1	U	NA	NA
87-68-3	VOLATILE SW-846 METHOD 8260D	Hexachlorobutadiene	PPB	1.1	U	1.1	U	NA	NA
98-82-8	VOLATILE SW-846 METHOD 8260D	Isopropylbenzene	PPB	1900	D	1.1	U	2,300	NA
179601-23-	VOLATILE SW-846 METHOD 8260D	**m,p-Xylene**	PPB	34000	D	9.6	J	*260*	100,000
79-20-9	VOLATILE SW-846 METHOD 8260D	Methyl Acetate	PPB	1.1	U	1.1	U	NA	NA
1634-04-4	VOLATILE SW-846 METHOD 8260D	Methyl tert-butyl ether	PPB	1.1	U	30		930	100,000
75-09-2	VOLATILE SW-846 METHOD 8260D	Methylene chloride	PPB	1.1	U	1.1	U	50	100,000
104-51-8	VOLATILE SW-846 METHOD 8260D	n-Butylbenzene	PPB	2400	D	1.1	U	12,000	NA
103-65-1	VOLATILE SW-846 METHOD 8260D	**n-Propylbenzene**	PPB	10000	D	1.6	J	*3,900*	100,000
91-20-3	VOLATILE SW-846 METHOD 8260D	Naphthalene	PPB	210		9.9		12,000	NA
95-47-6	VOLATILE SW-846 METHOD 8260D	**o-Xylene**	PPB	13000	D	6.0		*260*	100,000
105-05-5	VOLATILE SW-846 METHOD 8260D	p-Diethylbenzene	PPB	10000	D	2.3	J	NA	NA
622-96-8	VOLATILE SW-846 METHOD 8260D	p-Ethyltoluene	PPB	21000	D	7.7		NA	NA
135-98-8	VOLATILE SW-846 METHOD 8260D	sec-Butylbenzene	PPB	1.1	U	1.1	U	11,000	100,000
100-42-5	VOLATILE SW-846 METHOD 8260D	Styrene	PPB	1.1	U	1.1	U	300,000*	NA
75-65-0	VOLATILE SW-846 METHOD 8260D	t-Butyl alcohol	PPB	2.9	U	2.8	U	NA	NA
98-06-6	VOLATILE SW-846 METHOD 8260D	tert-Butylbenzene	PPB	1.1	U	1.1	U	5,900	100,000
127-18-4	VOLATILE SW-846 METHOD 8260D	Tetrachloroethene	PPB	1.1	U	1.1	U	1,300	19,000
108-88-3	VOLATILE SW-846 METHOD 8260D	**Toluene**	PPB	17000	D	5.4	J	*700*	100,000
156-60-5	VOLATILE SW-846 METHOD 8260D	trans-1,2-Dichloroethene	PPB	1.1	U	1.1	U	190	100,000
10061-02-6	VOLATILE SW-846 METHOD 8260D	trans-1,3-Dichloropropene	PPB	1.1	U	1.1	U	NA	NA
79-01-6	VOLATILE SW-846 METHOD 8260D	Trichloroethene	PPB	1.1	U	1.1	U	470	21,000
75-69-4	VOLATILE SW-846 METHOD 8260D	Trichlorofluoromethane	PPB	1.1	U	1.1	U	NA	NA
108-05-4	VOLATILE SW-846 METHOD 8260D	Vinyl acetate	PPB	210		1.1	U	NA	NA
75-01-4	VOLATILE SW-846 METHOD 8260D	Vinyl chloride	PPB	1.1	U	1.1	U	20	900
108-87-2	VOLATILE SW-846 METHOD 8260D	Methylcyclohexane	PPB	29000	D	2.2	U	NA	NA
107-02-8	VOLATILE SW-846 METHOD 8260D	Acrolein	PPB	14	U	14	U	NA	NA
107-13-1	VOLATILE SW-846 METHOD 8260D	Acrylonitrile	PPB	1.1	U	1.1	U	NA	NA

BP SERVICE STATION
4001-4010 4TH AVENUE
BROOKLYN, NEW YORK
SPILL # 18-11146

Remedial Action Plan
(RAP)

Prepared for:
NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
REGION II
LONG ISLAND CITY
NEW YORK

NEW YORK STATE OF OPPORTUNITY | Department of Environmental Conservation

PREPARED BY:

BERNINGER ENVIRONMENTAL
17 OLD DOCK ROAD
YAPHANK, NEW YORK 11980

BEi

August 2020

Table of Contents

INTRODUCTION **(1)**

SITE BACKGROUND **(1)**

SITE HISTORY **(2)**

REMEDIAL ACTION OBJECTIVES (RAOs) **(2)**

REMEDIAL ACTION PLAN (RAP) **(3)**

OPERATION MONITORING AND MAINTENANCE (OMM) **(3)**

HEALTH AND SAFETY **(4)**

PROJECT SCHEDULE **(4)**

CONCLUSION **(5)**

FIGURES

Figure-1 - Site Location

Figure-2 - Proposed SVE well locations

Figure-3 - SVE well construction details

Figure-4 - Recover Shed Piping Schematic

Figure-5 - Previous sampling locations

ATTACHMENTS

Attachment-A - New York State DEC Spill Reports

Attachment-B - SVE Engineering Control specs

Attachment-C - Emission Control specs

Berninger Environmental
groundwater consultants, scientist and geologists
17 Old Dock Road
Yaphank • New York • 11980 **Phone: 631 • 589 • 6521**
A Division of WRS Environmental Services **Fax: 631 • 924 • 8105**

August 14th, 2020

Veronica Zhune
New York State Environmental Conservation
Division of Environmental Remediation, Region 2
47-40 21st Street
Long Island City, New York 11101

Re: BP Service Station
4001-4010 4th Avenue
Brooklyn, New York 11232

Remedial Action Plan
NYSDEC Spill #18-11146
(RAP)

Dear Ms. Zhune,

Introduction

Berninger Environmental (BEI), has prepared this Remedial Action Plan (RAP) for the subject site based upon the data generated from the Remedial Investigation (RI). The RI identified contamination in soil which exceeded the New York State Part-375 soil clean-up objectives (SCOs) at select areas near the former USTs. The following plan has been developed to address areas where contamination exceeds standards in soil in order to meet the Remedial Action Objectives (RAOs) established for the site. Please read below for further information regarding the remedial action selected to address the contamination discovered during the RI. Please see Figure-1 for the site location.

Site Background

The site is located at 4001-4010 4th Avenue, Brooklyn, New York- Figure 1. The site is situated on a plot size approximately 10,017 square feet. The site is currently used as a gas station with a convenience store and parking. The building was constructed in 1965. Castleton reviewed the Phase I ESA prepared by Merritt Environmental Consulting Corporation (MECC) dated January 7, 2019. The MECC Phase I ESA identified that the site has been a gasoline station since its first developed use. According to the historical Sanborn Maps, a gasoline tank was present at the corner of 4th Avenue and 10th Street during the years 1926-1951. MECC recommended further evaluation to determine if any documentation is available or if additional investigation (Phase II) is warranted. Subsequent documentation regarding the gasoline tank shown on the 1926-1951 Sanborn Maps was not provided. A Phase II was subsequently performed based on the recommendations outlined in the Phase I ESA. Please refer to Attachment-A for a survey of the current layout of the station.

Site History

A Phase II ESA was performed by Castleton Environmental during January of 2019, which included a series of borings conducted at key locations throughout the property and a ground penetrating radar (GPR) survey to identify any potential former UST's. Six (6) soil borings were advanced on the Subject Property in the vicinity of the UST's. Soil samples were collected continuously from each boring location, logged and field screened with a PID for the presence of VOCs. Elevated field sensory (PID), olfactory or visible evidence of impacts to soil were observed in each of the borings ranging from 22.9 ppm in SB01 to 5,285 ppm in SB04. Soil analytical results were compared to NYSDEC CP-51 Soil Cleanup Levels (SCLs) for petroleum impacted soil and NYSDEC Part 375 Soil Cleanup Objectives (SCOs). Soil analytical results reported concentrations of SVOCs as non-detect or below SCLs and SCOs in all of the six (6) soil samples analyzed. VOCs above SCLs were reported in five (5) of the six (6) soil samples. VOCs above commercial-use SCOs were reported in two (2) of the six (6) samples analyzed. Based upon these findings a spill was reported and spill number # 18-11146 was assigned to the site.

Based on the findings from the Phase II ESA conducted during January 2019, a supplemental sub-surface investigation was conducted in an attempt to confirm the presence of former USTs , delineate the vertical extent of contamination and also attempt to reach groundwater. A total of eight (8) borings were conducted to supplement the Phase II data. Borings B-1, B-2 and B-3 were conducted in the areas where the GPR documented possible former USTs. Refusal was encountered at each of these boring locations at exactly 2.5' below grade surface (bgs) indicating that the old USTs are still present in the ground and were abandoned in place with concrete. B-6 and B-7 were conducted in the second area of suspect former USTs and refusal was encountered at three feet (3') bgs indicating again, that the former USTs were abandoned with concrete. Borings B-4, B-5 and B-8 were conducted in order to delineate vertical contamination previously discovered at these locations. All of these samples had elevated PID detections from approximately 5'-25' below grade. Vertical delineation at B-5 and B-8 was achieved based on lab data and low PID readings at B-8, but B-4 still had detections above the SCOs at thirty (30') bgs. BEI was unable to advance deeper beyond 30' bgs at B-4 due to bedrock refusal. Bedrock was also encountered at B-5 and B-8 causing refusal at 32.5' and 34' respectively. The elevated concentrations in soil detected at the B-4, B-5 and B-8 locations prompted the development of this RAP. Please refer to Figure-5 for the previous sample locations. Please read below for the remedial strategy selected to remedy vadose zone soil contamination.

Remedial Action Objectives (RAO's)

Remedial Action Objectives (RAO's) have been established for soil as per the following documents: 6 NYCRR Part-375 for soil (Part 375) unrestricted-commercial-use soil clean-up objectives established in Part-375 shall follow the clean-up levels listed as Unrestricted Use Soil Cleanup Objectives as per Table 375-6.8a, to the extent feasible.

Remedial Action Plan (RAP)

The proposed remedy for the site includes a clean-up technology widely used to treat petroleum impacted soil. Soil Vapor Extraction (SVE) is a technology used to remove volatile organic vapors from the un-saturated zone often referred to as the vadose zone. Off-gassing of petroleum contamination within the vadose zone is extracted through a series of vertical screened pipes (SVE well points) and exhausted to the atmosphere. This allows for mass removal of petroleum related sorbed contamination in the soil matrix.

A total of four (4) SVE wells are proposed to be installed at the subject site as depicted on Figure-2. Well construction details include: five(5') feet of schedule 40 PVC riser pipe with twenty five feet (5') of schedule 40 PVC 0.02" slot screen from 5'-30' below grade surface (bgs). SVE well construction details are illustrated in Figure-3. The piping will be trenched below grade in line and brought to grade at the south end of the property where it will continue to the remediation shed as separate lines routed and manifolded in the equipment room for control over individual zones. This will allow for future optimization of the system in order to balance effectiveness based on contaminant removal. SVE piping from each well will enter into the equipment room where separate ball valves and sampling ports will be installed on the manifold. Vacuum gauges will also be installed on each leg in order to monitor adequate effectiveness and air flow. Post manifold piping will continue on one (1) line and affixed to the engineering control (EC) EN-523 (or similar series) vacuum inlet. Please refer to Attachment-B for the spec sheet on the EN-523. A water knockout drum will be installed between the influent piping and the blower unit to prevent any unwanted moisture from entering the blower intake. The installation of this moisture separator will help to extend the life of the blower and prevent catastrophic failure due to moisture intake. A fresh air inlet will be introduced prior to the blower inlet and connected to the main influent piping leg, which will help to reduce exhaust stack emissions via dilution by fresh air. The post run effluent piping will consist of 2" galvanized pipe with the ability to withstand excessive heat generated by the blower exhaust. In-line air emission control equipment (GPC-3 Carbon Drum unit) will be installed, if necessary based on the first sampling event, in order to eliminate volatile concentrations prior to exiting the exhaust stack. Please see emission control specs as Attachment-C. Galvanized pipe will exit the equipment shed and change over to schedule 40, 2" PVC and extend to five feet (5') above the roof line of the remediation housing shed.(*total stack height from grade 15'). The equipment room piping scheme and blower connection is depicted in Figure- 4. A system shutdown warning light will be wired into the electrical configuration to allow for visual confirmation that the system is operational. If at anytime the system shutdown warning light is observed to be in the off position, this would indicate possible mechanical or electrical failure. This would prompt the property manager to contact BEI in order to diagnose the reason for failure.

Operation, Monitoring and Maintenance (OMM)

During the first month of operation weekly inspections will be conducted in order to inspect various components of the system and gauge airflow. During this time influent screening and lab testing should be conducted in order to establish a baseline for future calculation of mass contaminant

removal. An OMM checklist will be provided to the technician assigned to perform these preventative tasks, which includes: inspection of all electrical wiring and SVE blower components, visual inspection of all above grade piping to ensure there are no cracks or leaks, inspection of system shutdown warning device and inspection of the exhaust or discharge point to verify no air intakes have been located nearby. Effluent emission sampling will be conducted on a quarterly basis with a six liter (6L) summa canister and submitted to a New York State certified laboratory for testing by EPA method 8260 (VOCs). In addition to the routine OMM activities described here, the building's owner and tenants will be provided information that explains the systems operation, maintenance and monitoring. Therefore, at any time during the systems operation, the building's owner or tenants may check that the system is operating properly. BEI will establish a point of contact with the property manager in the event that the system becomes inoperable ("system fault condition"). If a major repair requires the system to be offline for longer than a 24-hour period, the representative of the owner will contact the NYSDEC to discuss the problem and offer a schedule for repair.

A OMM report will be issued to the NYSDEC on a quarterly basis documenting all routine inspection activities and effluent emission results. The report will include: a brief report describing inspection and maintenance activities, tabulated effluent lab data, and air flow/vacuum readings for the engineering control.

Health and Safety

It is anticipated that level D personal protective equipment (PPE) will be used during the performance of the borings and well installations. All personnel on-site will be properly trained and certified by the Occupational Safety and Health Act (OSHA) according to the regulations set forth in the Code of Federal Regulations 29 (CFR) 1910.

Level D PPE includes the following:

- Eye protection- Wear goggles or face shield (splash prevention)
- Head- Hard hat when required
- Hands- Wear neoprene gloves
- Feet- Wear steel-toe boots with chemical resistant soles or neoprene covers
- Clothing- Long sleeve shirts and long pant legs.

Project Schedule

BEI will be prepared to mobilize within sixty (60) days of approval of this Work Plan. It is anticipated that the duration of the job will take approximately 7-10 working days to complete. Upon completion all work will be documented as per below.

Conclusion:

A Construction Completion Report (CCR) will be drafted to document the construction layout of the proposed system. The CCR will include as built drawings detailing the system construction, baseline effluent concentrations and also document the EC associated with the system. The extraction well specifications and proposed monitoring and maintenance procedures, along with post mitigation testing results will also be discussed, as well as the protocol for system termination procedures. Any questions or comments regarding this RAP can be directed to BEI.

Sincerely,
Berninger Environmental

Justin Halpin
Scientist/Project Manager

Alicia Patti
Geologist

cc: Joe Macchia (The Macchia Group)

FIGURES





Figure-1
Site Location
Brooklyn, NY



Site Map
Proposed Soil Vapor
Extraction Wells
FIGURE-2

BP Service Station
4001-4010 4th Avenue
Brooklyn, NY

BEi Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

SVE Well Log

Figure-3


Project: BP Gas Station
Client: The Macchia Group
Location: 4001 4th Avenue Brooklyn, NY
Well No: SVE-1-4 **Use:** Soil Vapor Extraction
Install Method: Direct Push
Casing Type: sch 40 PVC **Casing Dia:** 2" **Casing Length:** 5'
Screen Type: sch 40 PVC **Screen Dia:** 2" **Screen Length:** 25'
Screen Slot: 0.02" **Gravel Pack:** #2 fil-pro
Casing Seal: Clean Fill **Finish:** below grade

Date: TBD
Be Job No:
Installer: BEI
Bore Hole Dia: 3.5"
Sample Method: N/A
Depth to Water: NA
Total Depth: 30'
Security: below grade

Depth bgs	Sample Information	Well Design	Identification/Remarks
0	right angle PVC elbow		2" solid PVC riser
	(5') of 2" PVC riser		to equipment shed
10'			
20'	Fil-pro gravel pack		
			(25') of 2" PVC .02" slot screen
30'			2" PVC well point
	DTB 30'		
40'			

BEi Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

PLAN VIEW



SCALE AS SHOWN

SVE Equipment
Room Schematic
FIGURE-4

BP Service Station
4001 4th Avenue
Brooklyn, New York

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980




Site Map
Boring Locations
Figure-5

BP Service Station
4001-4010 4th Avenue
Brooklyn, NY

BEi Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

ATTACHMENTS

Attachment-A
Current Station Layout



4TH AVE

0 1 2 5 10 15 20

GASOLINE SERVICE STATION

WITH ACCESSORY CONVENIENCE STORE U.G. 16 B&E
& SELF SERVE DISPENSERS

1 PUMP & TANK SITE PLAN

1" = 10'-0"

TANK MONITORING SYSTEM NOTE(S) & LEGEND :

H = ALARM HORN

L = FLASHING LIGHT

= EMERGENCY CUT OFF SWITCH

* ALARM HORN AND FLASHING LIGHT, CONNECTED TO D.E.C. APPROVED TANK MONITORING SYSTEM TO INDICATE HIGH LEVEL ALARM.

* HIGH LEVEL ALARM, BOTH AUDIBLE AND VISUAL, TO BE TRIGGERED WHEN TANK IS NO MORE THAN 90 % FULL.

* INSTALLATION MUST BE INSTALLED IN ACCORDANCE WITH FEDERAL REGULATION - 40 CFR PARTS 280 AND 281.

NOTE: WHERE INDICATED EXISTING, STEEL SINGLE WALLED UG GASO. TANK TO BE LINED (2-TOTAL), EACH TANK MUST BE LINED AS TO COMPLY WITH ALL TESTING AND REGULATIONS THAT GOVERN INCLUDING USA FEDERAL REGULATIONS (CFR), NEW YORK STATE DEPT. OF ENVIROMENT CONSERVATION, NEW YORK CODE RULES AND REGULATIONS (NYCRR) AND NEW YORK CITY FIRE DEPARTMENT. SEE NPTES "C" & "D" ON DWG. P&T-002 FO RMORE INFORMATION.

EXISTING 2-4,000 GAL. UG SINGLE WALL STEEL FUEL TANKS TO BE LINED. REPLACE CONC. MAT, FOR MORE INFO. SEE DWG P&T-004. REPLACE MANHOLE ON EA. TANK. REMOVE ALL STP & INSTALL NEW STP AS INDICATED. REMOVE ALL PIPING, VALVES, ETC. AND INSTALL NEW AS INDICATED. (C)

TANK LEVEL MONITOR (TLM) CONNECTED TO VEEDER ROOT SYSTEM (TYP. 1-EA. TANK) (4)

BSA APPR'D EXTRACTOR FLOAT VALVE (GAL. 247-83-SM) I-REQ'D IN EA. GASO. TANK EXCEPT DIESEL TANK

(4)NEW DIRECT FILL W/ 4 NEW NYC APPR'D 15 GAL SPILL CONTAINMENT DEVICE AND MECHANICAL OVERFILL PROTECTION DEVICE ON EACH FILL LINE (5)(6)

NEW STAGE-I VAPORY RECOVERY DRYBREAK

(4) NEW 2" DIA. VENT 15' ABOVE GRADE & 10' FROM THE NEAREST BLDG. OPENING & WELL BRACED IN POSITION C.A.R.B. APPROVED P/N CAPS (GASO. TANKS ONLY), GC TO INSTALL 2" DIA. VENT MANIFOLD, SEE DET. ON DWG. P&T-007 (GASO. TANKS ONLY)

NEW 2" SINGLE WALL FIBERGLASS VENT PIPING (PICH BACK TO TANK 1/8" PER FOOT, BACKFILL PER MANUFACTURER'S SPECS.

NEW ANULAR PROBE MONITOR (1 REQ'R EA. TANK) WHERE INDICATED ONLY

(4)NEW DIRECT FILL W/ 4 NEW NYC APPR'D 15 GAL SPILL CONTAINMENT DEVICE AND MECHANICAL OVERFILL PROTECTION DEVICE ON EACH FILL LINE (5)(6)

TANK LEVEL MONITOR (TLM) CONNECTED TO VEEDER ROOT SYSTEM (TYP. 1-EA. TANK) (4)

(3) NEW TOTAL SUBMERSIBLE PUMP IN A STP SUMP, PROVIDE (4) NEW 42" DIA. MANHOLE (1) REQUIRED IN EA. TANK) (4)


STICK LINE IN MANHOLE (1 REQUIRED IN EA. TANK) WHERE INDICATED

REPLACE CONC. MAT & INSTALL NEW PIPING, ETC. AS NOTED, SEE DWGS. P&T-004, P&T-005, P&T-006 FOR MORE INFO.

EXISTING 2-4,000 GAL. UG DOUBLE WALLED MOTOR FUEL TANKS TO BE LINED. REPLACE CONC. MAT, FOR MORE INFO. SEE DWG P&T-004. REPLACE MANHOLE ON EA. TANK. REMOVE ALL STP & INSTALL NEW STP AS INDICATED. REMOVE ALL PIPING, VALVES, ETC. AND INSTALL NEW AS INDICATED. (C)
NOTE: WHERE INDICATED EXISTING, DOUBLE WALLED UG GASO. TANK TO BE LINED (2-TOTAL), EACH TANK MUST BE LINED AS TO COMPLY WITH ALL TESTING AND REGULATIONS THAT GOVERN INCLUDING USA FEDERAL REGULATIONS (CFR), NEW YORK STATE DEPT. OF ENVIROMENT CONSERVATION, NEW YORK CODE RULES AND REGULATIONS (NYCRR) AND NEW YORK CITY FIRE DEPARTMENT. SEE NPTES "C" & "D" ON DWG. P&T-002 FO RMORE INFORMATION.


NOTE

1. EXACT LOCATION OF EXISTING TANK FITTINGS TO BE VERIFY IN THE FIELD.



U-BOLLARD DETAIL

N.T.S.



DRIVE MAT DETAIL

1" = 1'-0"

NOTES:

(1) REMOVE ALL EXISTING CONCRETE PUMP ISLAND, DISPENSERS, TANK STP SUMPS, FILLS, VAPOR RECOVERY MANHOLES, TOP SLAB, AND RELATED PIPING AND REPLACE WITH AMERON DUALOY 3000/L NONMETALLIC PIPING UNLESS OTHERWISE NOTED. DISPENSERS TO BE REFURBISHED AND REUSED.

(2) PIPING SHOWN IS DIAGRAMMATIC ONLY. REFER TO MANUFACTURER'S INSTALLATION MANUAL FOR PROPER INSTALLATION.

(3) GENERAL CONTRACTOR TO VERIFY IN FIELD THE EXACT NUMBER OF TANK OPENINGS AND FITTING LOCATIONS AND NOTIFY ARCHITECT OF ANY DISCREPANCIES.

(4) AT THE TIME OF COMPLETION THE CONTRACTOR SHALL FILE AN AFFIDAVIT WITH THE NEW YORK CITY FIRE DEPARTMENT STATING WORK AND REQUIRED TESTS PERFORMED ON ANY TANKS/PIPING, TESTS RESULTS SHALL BE NOTED AND A COPY SHALL BE SENT TO THE OWNER AND THE ARCHITECT.

(5) GENERAL CONTRACTOR SHALL BE RESPONSIBLE FOR ALL APPLICABLE TESTING/INSPECTIONS OF TANKS AND PIPING SYSTEM UPON COMPLETION OF PROJECT AS REQUIRED BY THE NEW YORK CITY FIRE DEPARTMENT RULES AND REGULATIONS. GENERAL CONTRACTOR TO CONTACT THE NEW YORK CITY FIRE DEPARTMENT AT (718) 644.2462 FOR THIS INFORMATION.

(6) CONTRACTOR MUST CONFORM TO THE REQUIREMENTS OF THE NEW YORK CITY ELECTRICAL CODE AND FILE A CERTIFICATE OF ELECTRICAL INSPECTION UPON COMPLETION OF THE WORK WITH THE NEW YORK CITY FIRE DEPARTMENT.

(7) LOCATION AND NUMBER OF EXISTING PUMPS AND TANKS TO BE VERIFIED BY THE NEW YORK CITY FIRE DEPARTMENT.

(8) THE BIDDING CONTRACTOR SHALL VISIT THE SITE AND BECOME FAMILIAR WITH ALL EXISTING CONDITIONS AND PROPOSED WORK ITEMS TO BE COMPLETED AS NOTED ON THE DRAWINGS PRIOR TO BIDDING.

(9) THE CONTRACTOR SHALL VERIFY THE TYPE AND EXACT LOCATION OF ALL EXISTING TANK PIPING, MPD'S PANS, AND FITTING PENETRATIONS INTO THE TANK. NOTIFY ARCHITECT OF RECORD IN WRITING OF ANY DISCREPANCIES PRIOR TO CONSTRUCTION.

(10) ANY UNDERGROUND DRAINAGE LINES, WATER LINES, SEWER LINES, ELECTRICAL LINES, ETC. THAT MAY BE ENCOUNTERED DURING THE COURSE OF CONSTRUCTION SHALL BE REMOVED AND REROUTED AS REQUIRED. GENERAL CONTRACTOR TO NOTIFY ARCHITECT AND OWNER IMMEDIATELY.

(11) PROVIDE COLOR AND SYMBOL CODES ON ALL FILLS AND GAUGE PORTS AS PER A.P.I., N.Y.S.D.E.C. AND OWNER'S STANDARDS. PRODUCT I.D. MARKERS SHALL BE INSTALLED ON ALL FILL PORTS PER N.Y.S.D.E.C. REQUIREMENTS.

(12) GENERAL CONTRACTOR TO PRECISION TEST TANKS, PIPING SYSTEM, ETC. PRIOR TO CONSTRUCTION OF PROJECT AS PER NEW YORK CITY FIRE DEPARTMENT RULES AND REGULATIONS. GENERAL CONTRACTOR SHALL SECURE THE SERVICES OF THE NEW YORK CITY FIRE DEPARTMENT FOR TESTING PURPOSES. AFTER INSTALLATION GENERAL CONTRACTOR SHALL SCHEDULE A TEST TO BE DONE BY OWNER ON TANKS, PIPING, ETC. GENERAL CONTRACTOR SHALL NOT BACK FILL UNTIL ALL TESTING HAS BEEN DONE.

(13) GENERAL CONTRACTOR SHALL BE RESPONSIBLE FOR PROVIDING A "SPARK TEST" OF THE CATHODICALLY PROTECTED PIPE WITNESSED BY A NEW YORK CITY FIRE DEPARTMENT INSPECTOR BEFORE BACK FILL INSPECTION IS SCHEDULED. (IF APPLICABLE)

(14) GENERAL CONTRACTOR TO ASSURE THAT ELECTRICAL EXPLOSION PROOF CONNECTIONS ARE PROVIDED AND IN GOOD CONDITION AT EACH TANK SUMP AS REQUIRED PER N.F.P.A. AND N.E.C. CODES.

(15) GENERAL CONTRACTOR SHALL PATCH AND REPAIR AREAS OF THE CONCRETE DRIVE MAT, SURROUNDING THE ISLANDS, DISTURBED BY CONSTRUCTION WITH A MINIMUM OF 0'-8" THICK CONCRETE, 0'-4" CRUSHED STONE AND (1) LAYER OF #5 REBARS EACH WAY.

N.Y.C. FIRE DEPARTMENT APPROVAL / EQUIPMENT LIST

EQ. NO.	EQUIPMENT	MANUFACTURER	MODEL NUMBER	C of A NUMBER
(1)	MULTI-PRODUCT BLENDER DISPENSER W/SB3	"WAYNE" OVATION	B12/B223DI/6K DOB 2-HOSE	5082
	DISPENSER PAN	ENVIRO	DEEP PAN	
(2)	NOT USED			
(3)	UNDERGROUND PIPING	SMITH FIBERCAST	RED THREAD IIA	5099
(4)	SUBMERSIBLE TURBINE PUMP	FE PETRO	1 1/2 HP W/ INTAKE FILTER SCREEN	4834
(5)	MECHANICAL OVERFILL PREVENTION DEVICE	OPW	61SO (GRAVITY FILL)	4902
(6)	SPILL CONTAINMENT DEVICE	OPW	1-2115 (15 GALLON)	4978
(7)	FLEXIBLE CONNECTOR	TITEFLEX	FIRESAFE	
(8)	EXTRACTOR FITTING - CROSS	OPW	233VM-4433	
(9)	LEAK DETECTION SYSTEM	VEEDER ROOT	TLS 350	4853
	AUTOMATIC TANK GAUGE TANK LEVEL PROBE TANK HYDROSTATIC SUMP SENSOR ELECTRONIC LINE LEAK DETECTOR STP SUMP SENSOR DISPENSER PAN SENSOR			
(10)	EXIST. DOUBLE WALLED TANKS TO BE LINED	VIF	EXIST. (2-TOTAL) 4000 GALLONS	VIF
(11)	EXIST. STEEL SINGLE WALLED TANKS TO BE LINED	VIF	EXIST. (2-TOTAL) 4000 GALLONS	VIF

AS-BUILT DRAWINGS & INSTALLER STATEMENT:

G.C./ INSTALLER SHALL PROVIDE A COMPLETE SET OF AS BUILT DRAWINGS TO SCALE DEPICTING PRECISE LOCATION OF ALL COMPONENTS INSTALLED (INCLUDING PRODUCT/ VAPOR LINE SIZES & LOCATIONS, CONDUIT SIZES & LOCATIONS, ETC.) PRIOR TO OWNER'S ACCEPTANCE.

THESE PLANS MUST INCLUDE A STATEMENT BY THE INSTALLER THAT THE SYSTEM HAS BEEN INSTALLED IN COMPLIANCE WITH THE NEW YORK STATE STANDARDS FOR NEW AND SUBSTANTIALLY MODIFIED PETROLEUM STORAGE FACILITIES, 6 NYCRR PART 614.

LICENSED INSTALLER'S FINAL STATEMENT

I, _____ COMPLETED THE INSTALLATION OF THE EQUIPMENT DESCRIBED IN THE ANNEXED PLANS ON _____. THE INSTALLATION COMPLIES FULLY WITH THE REQUIREMENTS OF THE NEW YORK STATE PETROLEUM BULK STORAGE CODE 6 NYCRR PART 614.

_____
SIGNATURE OF THE LICENSED INSTALLER

FILL BOX IDENTIFICATION REQUIREMENTS:

IDENTIFICATION REQUIREMENTS SHALL CONFORM TO AMERICAN PETROLEUM INSTITUTE STANDARDS.

AMENDED

VAPOR HOSE CONNECTION:	UNLEADED (LOWER)	UNLEADED (HIGHER)	DIESEL
ORANGE	BLACK CROSS WHITE BACKGROUND	WHITE CROSS RED BACKGROUND	YELLOW

ACCEPTABLE FOR PERMIT UNDER DIRECTIVE NO. 14/1975
DEC 28 2010
KAUSAR AHMAD

320041897
SC343628763

REGISTERED ARCHITECT JAMES P. VASSALOTTI 026076 STATE OF NEW YORK

REV	DATE	DESCRIPTION
-	6-17-09	ISSUED TO BID
-	6-24-09	ISSUED TO BLDG DEPT. FOR APPROVAL
-	8-31-09	AS BUILT CONDITIONS

DRAWING: PUMP & TANK SITE PLAN AND EQUIPMENT SCHEDULE

LOCATION: 4001 4th LLC
4001-11 4th AVE
BROOKLYN, NEW YORK

BLOCK 774 | LOT 6 | MAP --- | ZONE C-8 IN R6

VASSALOTTI ARCHITECTS, L.L.P. ASSOCIATES
3000 MARCUS AVE. LAKE SUCCESS, NY 11042

DWN. BY	CHK. BY
JEFF V.	A.D.

SCALE: AS NOTED

DATE	JOB NO.
6-17-09	08-0071

PAGE NO. DWG. 4 OF 9

DWG. NO. P&T-004.00

Attachment-B
EN-523 SVE Motor
Specs

Environmental / Chemical Processing Blowers

ROTRON®

EN 523 & CP 523

3.0 HP High Pressure Sealed Regenerative w/Explosion-Proof Motor

FEATURES

- Manufactured in the USA - ISO 9001 and NAFTA compliant
- Maximum flow: 84 SCFM
- Maximum pressure: 140 IWG
- Maximum vacuum: 135 IWG
- Standard motor: 3.0 HP, explosion-proof
- Cast aluminum blower housing, impeller , cover & manifold; cast iron flanges (threaded); teflon® lip seal
- UL & CSA approved motor with permanently sealed ball bearings for explosive gas atmospheres Class I Group D minimum
- Sealed blower assembly
- Quiet operation within OSHA standards

MOTOR OPTIONS

- International voltage & frequency (Hz)
- Chemical duty, high efficiency, inverter duty or industry-specific designs
- Various horsepowers for application-specific needs

BLOWER OPTIONS

- Corrosion resistant surface treatments & sealing options
- Remote drive (motorless) models
- Slip-on or face flanges for application-specific needs


ACCESSORIES

- Flowmeters reading in SCFM
- Filters & moisture separators
- Pressure gauges, vacuum gauges, & relief valves
- Switches - air flow, pressure, vacuum, or temperature
- External mufflers for additional silencing
- Air knives (used on blow-off applications)
- Variable frequency drive package




Blower Performance at Standard Conditions

60 Hz



50 Hz




This document is for informational purposes only and should not be considered as a binding description of the products or their performance in all applications. The performance data on this page depicts typical performance under controlled laboratory conditions. AMETEK is not responsible for blowers driven beyond factory specified speed, temperature, pressure, flow or without proper alignment. Actual performance will vary depending on the operating environment and application. AMETEK products are not designed for and should not be used in medical life support applications. AMETEK reserves the right to revise its products without notification. The above characteristics represent standard products. For product designed to meet specific applications, contact AMETEK Technical & Industrial Products Sales department.

AMETEK TECHNICAL & INDUSTRIAL PRODUCTS
75 North Street, Saugerties, NY 12477
USA: +1 215-256-6601 - Europe: +44 (0) 845 366 9664 - Asia: +86 21 5763 1258
Customer Service Fax: +1 215.256.1338
www.ametektip.com

AMETEK®
TECHNICAL & INDUSTRIAL PRODUCTS

ROTRON®

3.0 HP High Pressure Sealed Regenerative w/Explosion-Proof Motor



NOTES
1 TERMINAL BOX CONNECTOR HOLE 3/4" NPT FEMALE THREAD.
2 DRAWING NOT TO SCALE, CONTACT FACTORY FOR SCALE CAD DRAWING.
3 CONTACT FACTORY FOR BLOWER MODEL LENGTHS NOT SHOWN.

		Part/Model Number			
Specification	Units	EN523M5L 038223	EN523M72L 038184	CP523FU5LR TBD	CP523FU72LR 038968
Motor Enclosure - Shaft Mtl.	-	3	3	3	3
Horsepower	-	Explosion-proof-CS	Explosion-proof-CS	Chem XP-SS	Chem XP-SS
Phase - Frequency	-	Single-60 hz	Three-60 hz	Single-60 hz	Three-60 hz
Voltage	AC	230	230/460	230	230/460
Motor Nameplate Amps	Amps (A)	15.5-14.5	7.4/3.7	15.5-14.5	7.4/3.7
Max. Blower Amps	Amps (A)	18.1-16.7	8/4	18.1-16.7	8/4
Inrush Amps	Amps (A)	94-88	62/31	94-88	62/31
Service Factor	-	1	0/0	1	0/0
Starter Size	-	1.0	1.0	1.0	1.0
Thermal Protection	-	Class B - Pilot Duty	Class B - Pilot Duty	Class B - Pilot Duty	Class B - Pilot Duty
XP Motor Class - Group	-	I-D	I-D	I-D	I-D
Shipping Weight	Lbs	126	126	150	126
	Kg	57.2	57.2	68	57.2

Voltage - ROTRON motors are designed to handle a broad range of world voltages and power supply variations. Our dual voltage 3 phase motors are factory tested and certified to operate on both: **208-230/415-460 VAC-3 ph-60 Hz** and **190-208/380-415 VAC-3 ph-50 Hz**. Our dual voltage 1 phase motors are factory tested and certified to operate on both: **104-115/208-230 VAC-1 ph-60 Hz** and **100-110/200-220 VAC-1 ph-50 Hz**. All voltages above can handle a ±10% voltage fluctuation. Special wound motors can be ordered for voltages outside our certified range.

Operating Temperatures - Maximum operating temperature: Motor winding temperature (winding rise plus ambient) should not exceed 140°C for Class F rated motors or 120°C for Class B rated motors. Blower outlet air temperature should not exceed 140°C (air temperature rise plus inlet temperature). Performance curve maximum pressure and suction points are based on a 40°C inlet and ambient temperature. Consult factory for inlet or ambient temperatures above 40°C.

Maximum Blower Amps - Corresponds to the performance point at which the motor or blower temperature rise with a 40°C inlet and/or ambient temperature reaches the maximum operating temperature.

XP Motor Class - Group - See Explosive Atmosphere Classification Chart in Section I


This document is for informational purposes only and should not be considered as a binding description of the products or their performance in all applications. The performance data on this page depicts typical performance under controlled laboratory conditions. AMETEK is not responsible for blowers driven beyond factory specified speed, temperature, pressure, flow or without proper alignment. Actual performance will vary depending on the operating environment and application. AMETEK products are not designed for and should not be used in medical life support applications. AMETEK reserves the right to revise its products without notification. The above characteristics represent standard products. For product designed to meet specific applications, contact AMETEK Technical & Industrial Products Sales department.


AMETEK TECHNICAL & INDUSTRIAL PRODUCTS
75 North Street, Saugerties, NY 12477
USA: +1 215-256-6601 - Europe: +44 (0) 845 366 9664 - Asia: +86 21 5763 1258
Customer Service Fax: +1 215.256.1338
www.ametektip.com


AMETEK®
TECHNICAL & INDUSTRIAL PRODUCTS

Attachment-C
Emission Control
Specs

Carbon Adsorber–Vapor Phase
GPC 3








Sales Drawing #119776
03/22/05
©CARBONAIR 2005


CARBONAIR
www.carbonair.com


GPC Drum Series Carbon Vessels

Carbonair's gas phase carbon absorbers are designed to provide an efficient and economical means to control odor, toxic vapors, and corrosive gases. Several types of activated carbons are available for a variety of applications.

Specifications*







Model	GPC 3	GPC 3H	GPC 3.85
Flow Range (cfm)	20 - 100	20 - 270	36 - 360
Carbon Capacity (lb)	200	180	250
Vessel Diameter or Plot Size	2'	2'	2'-4"
Vessel Height	3'-0"	3'-0"	3'-6"
Bed Area (ft^2)	2.7	2.7	3.7
Empty Weight (lb)	65	65	100
Operating Weight (lb)	265	265	350
Influent Connection	2" FPT	4" FPT	4" FPT
Effluent Connection	2" FPT	4" FPT	4" FPT

Design Features

- **Drums meet UN standards**
- **Baked enamel exterior**
- **Epoxy-phenolic interior lining**

Options

- ☐ Influent/effluent sample and pressure taps
- ☐ Influent/effluent ducting
- ☐ Humidity control
- ☐ Discharge stack
- ☐ Blowers
- ☐ Complete line of granular activated carbon

Service Centers

FLORIDA
4710 Dignan Street
Jacksonville, FL 32254
800.241.7833
904.387.4465
904.387.5058 Fax

MINNESOTA
7500 Boone Ave N #101
Brooklyn Park, MN 55428
800.526.4999
763.315.4771
763.315.4614 Fax

TEXAS
4889 Hunter Rd. Bldg 1-C
San Marcos, TX 78666
800.893.5937
512.392.0085
512.392.0066 Fax

VIRGINIA
4003 West Main Street
Salem, VA 24153
800.204.0324
540.380.5913
540.380.5920 Fax

*Specifications subject to change without notice.

BP SERVICE STATION
4001-4010 4TH AVENUE
BROOKLYN, NEW YORK
SPILL # 18-11146

Supplemental
Remedial Investigation
Pilot Study
Work Plan

NEW YORK STATE DEPARTMENT OF
ENVIRONMENTAL CONSERVATION
REGION II
LONG ISLAND CITY
NEW YORK

NEW YORK STATE OF OPPORTUNITY | Department of Environmental Conservation

PREPARED BY:

BERNINGER ENVIRONMENTAL
17 OLD DOCK ROAD
YAPHANK, NEW YORK 11980

BEi

December 2021

Table of Contents

1.0 INTRODUCTION

2.0 SITE BACKGROUND

3.0 SITE HISTORY

4.0 SCOPE OF WORK

5.0 REMEDIAL PILOT STUDY
5.1 SVE Pilot Test

6.0 REPORTING

7.0 HEALTH AND SAFETY

8.0 CONCLUSION

FIGURES

Figure-1 Site Location

Figure-2 Site Map with boring/sampling locations

Figure-3 Proposed Monitoring Well Log

Figure-4 Graph VOCs vs. Time

Figure-5 Graph Vacuum vs. Distance

Figure-6 SVE Well Log (Pilot Well)

ATTACHMENTS

Attachment-A Site Survey

Attachment-B SVE Pilot Vacuum Blower Specs

Berninger Environmental
groundwater consultants, geologists and scientists
17 Old Dock Road
Yaphank • New York • 11980 **Phone: 631 • 589 • 6521**
A WRS Environmental Services Company **Fax: 631 • 589 • 6528**

December 3rd, 2021

Mr. Jonathan Kolleeny
New York State Department of Environmental Conservation (DEC)
Division of Environmental Remediation
Professional Geologist-Region 2
47-40 21st Street
Long Island City, NY 11101

Re: BP Service Station
4001 4th Avenue (and 40th St)
Brooklyn, New York

Supplemental Investigation
Groundwater Sampling/ Pilot Study
Spill # 1811146

Dear Mr. Kolleeny,

1.0 INTRODUCTION

The following is a Supplemental Investigation Work Plan, that addresses the comments in the DEC letter dated November 5th, 2021. The letter provides comments on the *Supplemental Investigation Soil and Groundwater Report dated October 8th, 2021.* In brief, the letter discusses the need for further investigation with the performance of a pilot test in order to evaluate a remedy for impacted site media. Please read below for the proposed supplemental groundwater sampling locations and the proposed pilot remedy.

2.0 SITE BACKGROUND

The site is located at 4001-4010 4th Avenue, Brooklyn, New York- Figure 1. The site is located on a plot size approximately 10,017 square feet. The site is currently used as a gas station with a convenience store and parking. The building was constructed in 1965 and has been a gasoline station since its first developed use. A Phase II was performed based on the recommendations outlined in the Phase I ESA and supplemental investigations were performed thereafter. Please refer to Attachment-A for a survey of the current layout of the station.

3.0 SITE HISTORY

A supplemental investigation was conducted subsequent to the Phase II investigation that identified impacted soils above State soil clean-up objectives (SCOs) and the presence of underground storage

tanks (USTs) from the old gas station. The supplemental investigation concluded that soil contamination was vertically delineated, but groundwater impacts (perched water at ~30 feet bgs) discovered required additional investigation in order to determine the lateral extent of the contamination.

4.0 SCOPE OF WORK

The proposed scope of work involves the collection of groundwater samples via the installation of monitoring wells down gradient of the previous water sample collected at the newly installed MW-1. Please see Figure-2 for the previous groundwater sample (MW-1) location and the two (2) proposed locations (MW-2 and MW-3). Samples are located near the 4th Avenue subway line in order to determine the potential impacts to sensitive receptors. The depth of the subway tunnel will also be evaluated in order to determine these potential impacts. Please see Attachment-C for estimated subway line. The depth to the perched water layer in this region is approximately thirty feet (30') below grade surface, as discovered during the previous investigation. Two (2) one inch (1") monitoring wells will be installed at the locations proposed on Figure-2. Well specifications are anticipated to consist of: ten feet (10') of schedule 40 PVC well 0.20" slot screen (15'-25') with schedule 40 PVC riser pipe finishing to grade surface (0-15'). Please see Figure-3 well specs log.

Clean poly-tubing affixed with a check valve sampling device will be used to purge 3-5 well volumes of water prior to sample procurement. All soil and groundwater samples will be placed in laboratory approved glassware and transported on at 36 °F under strict chain of custody to a New York State ELAP certified laboratory for testing via EPA 8260C for VOCs.

5.0 REMEDIAL PILOT STUDY

5.0 Pilot Testing

In order to determine the radius of influence and determine the number of recovery wells that will be needed to successfully treat the plume area, a pilot test will be conducted at one (1) proposed location. The overall goal is to confirm the mass transfer of contaminants from the dissolved phase to the vapor phase and the extent at which effectiveness is achieved. The test is proposed to take place at one (1) location (SVE-PW) within the plume as depicted on Figure-2. The wells will be installed in five foot (5') increments stepping away from the pilot well.

5.1 SVE Pilot Test

It is anticipated that based on the geology in this area, an approximate ROI of 5'-10' is estimated. A vacuum cut off point of approximately 0.1 inches/H2O will be used as the minimum influence required based on distance. SVE effluent exhaust emissions will also be charted vs. time to confirm the SVE is operating effectively and removing volatile contamination. Effluent exhaust emissions will be gauged with a photo ionization detector (PID) meter and also analyzed via six liter (6) summa canister for testing by EPA method TO-15, VOCs.

The pilot results will also be graphed to document effluent VOC concentrations vs. time and measure vacuum influence versus distance. An example of the data charted is depicted as Figure-4 (VOC Concentrations vs. time) and Figure-5 (Vac vs. distance). The data generated from the pilot test will also be tabulated to include: elapsed time, vacuum readings, flow rates and PID concentrations.

Well head vacuum at the wells will be gauged for influence utilizing a magnahelic gauge. The monitoring wells are situated so that testing can be conducted in five foot (5') increments away from the pilot well. The first measurements will be conducted approximately five (5') from the pilot well with the remaining wells being tested from a 10' and 15' radius from the pilot location. The well locations and the anticipated radius of influence (ROI) is depicted on Figure-2.

The SVE pilot well (SVE-PW) will be installed within the plume area in the vicinity of the new wells. The actual location will be determined on the installation date based upon the pre-clearing of underground utilities. The proposed location of the SVE pilot well is depicted on Figure-2.

The well will be installed with a track mounted Geoprobe via direct push method using 3.25" hollow stem casing rods. Well construction details for SVE-PW are as follows: 10 feet (10') of 2" diameter, schedule 40 PVC slotted screen; fifteen feet (15') of 2", schedule 40 PVC solid riser pipe will finish the well to grade. The annular space surrounding the well screen will be filled with clean gravel pack. The pilot well will be connected to a 110 volt 1hp explosion proof Rotron® blower motor with flow rates during operation of 25-30 CFM and vacuum at the wellhead of approximately 5-10 inches/H2O. See Attachment-B for blower specifications. Please refer to Figure-6 for SVE well specs.

6.0 REPORTING

A Report of Findings will be issued upon receipt of the lab results. The Report will include a summary of the results compared to standards and a pilot test report with the measurements recorded from the testing.

7.0 HEALTH AND SAFETY

It is anticipated that level D personal protective equipment (PPE) will be used during the installation of the SVE/AS points and all associated piping. All personnel on-site will be will be properly trained and certified by the Occupational Safety and Health Act (OSHA) according to the regulations set forth in the Code of Federal Regulations 29 (CFR) 1910.

Level D PPE includes the following:

- Eye protection- Wear goggles or face shield (splash prevention)
- Head- Hard hat when required

- Hands- Wear neoprene gloves
- Feet- Wear steel-toe boots with chemical resistant soles or neoprene covers
- Clothing- Long sleeve shirts and long pant legs.

8.0 CONCLUSION

Based on the results from the investigation results a remedial plan will be developed in order to treat contaminated media at the site. The plan will be proposed based on the pilot study test results and the radius of influence established from the data collected. A Report of Findings will also be drafted with results of the subway terminal investigation and also the groundwater sampling results from the monitoring wells. Any questions or comments regarding this Work Plan can be directed to BEI.

Sincerely,
Berninger Environmental

Justin Halpin
Scientist/Project Manager

FIGURES





Figure-1
Site Location
Brooklyn, NY



Site Map
Proposed Sampling Locations
Figure-2

BP Service Station
4001-4010 4th Avenue
Brooklyn, NY

BEi Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980


Proposed Monitoring Well Log


Figure-3

Project: BP Service Station
Client: The Macchia Group
Location: 4001 4th Avenue Brooklyn
Well No: MW-2 and 3 **Use:** Monitoring/Sampling/Pilot Testing
Install Method: Direct Push
Casing Type: sch 40 PVC to poly **Casing Dia:** 2" **Casing Length:** 25'
Screen Type: sch 40 PVC **Screen Dia:** 2" **Screen Length:** 10'
Screen Slot: 0.02" **Gravel Pack:** #2 fil-pro
Casing Seal: Clean Fill **Finish:** 5" Manhole Flush mount

Date: TBD
Be Job No:
Installer: BEI
Bore Hole Dia: 2.5"
Sample Method: EPA 8260
Depth to Water: 30'
Total Depth: 35'
Security: 2" j-plug/ 5"manhole

Depth bgs	Sample Information	Well Design	Identification/Remarks
0	5" cast iron manhole		flush mounted cement sealed
5'			
10'	(25') of 1" PVC riser		
20'			
30'	Fil-pro gravel pack		(10') of 1" PVC 0.02" slot screen DTW 30'
40'		DTB (35')	


SVE
VOCs vs. Time
FIgure-4
PID Concentraiotns (ppm)
Time (minutes)
Series1
0
2
5
8
19
25
25
0
5
10
15
20
25
30



SVE Pilot Test
Vacuum vs. Distance
Figure-5
20.1
15.1
10.1
5.1
0.1
Vacuum (Inches of Water)
15
1.5
1
0.8
0.4
0
5
10
15
25
Distance from Extraction Well (feet)
Series1

SVE Well Log

Figure-6


Project: BP Gas Station
Client: The Macchia Group
Location: 4001 4th Avenue Brooklyn
Well No: SVE-Pilot Well **Use:** Soil Vapor Extraction
Install Method: Direct Push
Casing Type: sch 40 PVC **Casing Dia:** 2" **Casing Length:** 15'
Screen Type: sch 40 PVC **Screen Dia:** 2" **Screen Length:** 10'
Screen Slot: 0.02" **Gravel Pack:** #2 fil-pro
Casing Seal: Clean Fill **Finish:** below grade

Date: TBD
Be Job No:
Installer: BEI
Bore Hole Dia: 3.5"
Sample Method: N/A
Depth to Water: 30'
Total Depth: 25'
Security: below grade

Depth bgs	Sample Information	Well Design	Identification/Remarks
0	right angle PVC elbow		2" solid PVC riser to trench piping and vacuum
5'			
10'	(15') of 2" PVC riser		
15'			
20'	Fil-pro gravel pack		(10') of 2" PVC .02" slot screen
25'	DTB 25'		2" PVC well point

ATTACHMENTS

Attachment-A



TANK MONITORING SYSTEM NOTE(S) & LEGEND :

H = ALARM HORN

L = FLASHING LIGHT

= EMERGENCY CUT OFF SWITCH

* ALARM HORN AND FLASHING LIGHT, CONNECTED TO D.E.C. APPROVED TANK MONITORING SYSTEM TO INDICATE HIGH LEVEL ALARM.

* HIGH LEVEL ALARM, BOTH AUDIBLE AND VISUAL, TO BE TRIGGERED WHEN TANK IS NO MORE THAN 90 % FULL.

* INSTALLATION MUST BE INSTALLED IN ACCORDANCE WITH FEDERAL REGULATION - 40 CFR PARTS 280 AND 281.

NOTE: WHERE INDICATED EXISTING, STEEL SINGLE WALLED UG GASO. TANK TO BE LINED (2-TOTAL), EACH TANK MUST BE LINED AS TO COMPLY WITH ALL TESTING AND REGULATIONS THAT GOVERN INCLUDING USA FEDERAL REGULATIONS (CFR), NEW YORK STATE DEPT. OF ENVIROMENT CONSERVATION, NEW YORK CODE RULES AND REGULATIONS (NYCRR) AND NEW YORK CITY FIRE DEPARTMENT. SEE NPTES "C" & "D" ON DWG. P&T-002 FO RMORE INFORMATION.

EXISTING 2-4,000 GAL. UG SINGLE WALL STEEL FUEL TANKS TO BE LINED. REPLACE CONC. MAT, FOR MORE INFO. SEE DWG P&T-004. REPLACE MANHOLE ON EA. TANK. REMOVE ALL STP & INSTALL NEW STP AS INDICATED. REMOVE ALL PIPING, VALVES, ETC. AND INSTALL NEW AS INDICATED.

TANK LEVEL MONITOR (TLM) CONNECTED TO VEEDER ROOT SYSTEM (TYP. 1-EA. TANK) (9)

BSA APPR'D EXTRACTOR FLOAT VALVE (GAL. 247-83-SM) I-REQ'D IN EA. GASO. TANK EXCEPT DIESEL TANK

(4)NEW DIRECT FILL W/ 4 NEW NYC APPR'D 15 GAL SPILL CONTAINMENT DEVICE AND MECHANICAL OVERFILL PROTECTION DEVICE ON EACH FILL LINE (5)(6)

NEW STAGE-I VAPORY RECOVERY DRYBREAK

(4) NEW 2" DIA. VENT 15' ABOVE GRADE & 10' FROM THE NEAREST BLDG. OPENING & WELL BRACED IN POSITION C.A.R.B. APPROVED P/V CAPS (GASO. TANKS ONLY), GC TO INSTALL 2" DIA. VENT MANIFOLD, SEE DET. ON DWG. P&T-007 (GASO. TANKS ONLY)

NEW 2" SINGLE WALL FIBERGLASS VENT PIPING (PICH BACK TO TANK 1/8" PER FOOT, BACKFILL PER MANUFACTURER'S SPECS.

NEW ANULAR PROBE MONITOR (1 REQ'R EA. TANK) WHERE INDICATED ONLY

(4)NEW DIRECT FILL W/ 4 NEW NYC APPR'D 15 GAL SPILL CONTAINMENT DEVICE AND MECHANICAL OVERFILL PROTECTION DEVICE ON EACH FILL LINE (5)(6)

TANK LEVEL MONITOR (TLM) CONNECTED TO VEEDER ROOT SYSTEM (TYP. 1-EA. TANK) (9)

(3) NEW TOTAL SUBMERSIBLE PUMP IN A STP SUMP, PROVIDE (4) NEW 42" DIA. MANHOLE (1) REQUIRED IN EA. TANK) (4)

STICK LINE IN MANHOLE (1 REQUIRED IN EA. TANK) WHERE INDICATED

REPLACE CONC. MAT & INSTALL NEW PIPING, ETC. AS NOTED, SEE DWGS. P&T-004, P&T-005, P&T-006 FOR MORE INFO.

EXISTING 2-4,000 GAL. UG DOUBLE WALLED MOTOR FUEL TANKS TO BE LINED. REPLACE CONC. MAT, FOR MORE INFO. SEE DWG P&T-004. REPLACE MANHOLE ON EA. TANK. REMOVE ALL STP & INSTALL NEW STP AS INDICATED. REMOVE ALL PIPING, VALVES, ETC. AND INSTALL NEW AS INDICATED. (C)

NOTE: WHERE INDICATED EXISTING, DOUBLE WALLED UG GASO. TANK TO BE LINED (2-TOTAL), EACH TANK MUST BE LINED AS TO COMPLY WITH ALL TESTING AND REGULATIONS THAT GOVERN INCLUDING USA FEDERAL REGULATIONS (CFR), NEW YORK STATE DEPT. OF ENVIROMENT CONSERVATION, NEW YORK CODE RULES AND REGULATIONS (NYCRR) AND NEW YORK CITY FIRE DEPARTMENT. SEE NPTES "C" & "D" ON DWG. P&T-002 FO RMORE INFORMATION.

NOTES:

(1) REMOVE ALL EXISTING CONCRETE PUMP ISLAND, DISPENSERS, TANK STP SUMPS, FILLS, VAPOR RECOVERY MANHOLES, TOP SLAB, AND RELATED PIPING AND REPLACE WITH AMERON DUALOY 3000/L NONMETALLIC PIPING UNLESS OTHERWISE NOTED. DISPENSERS TO BE REFURBISHED AND REUSED.

(2) PIPING SHOWN IS DIAGRAMMATIC ONLY. REFER TO MANUFACTURER'S INSTALLATION MANUAL FOR PROPER INSTALLATION.

(3) GENERAL CONTRACTOR TO VERIFY IN FIELD THE EXACT NUMBER OF TANK OPENINGS AND FITTING LOCATIONS AND NOTIFY ARCHITECT OF ANY DISCREPANCIES.

(4) AT THE TIME OF COMPLETION THE CONTRACTOR SHALL FILE AN AFFIDAVIT WITH THE NEW YORK CITY FIRE DEPARTMENT STATING WORK AND REQUIRED TESTS PERFORMED ON ANY TANKS/PIPING. TESTS RESULTS SHALL BE NOTED AND A COPY SHALL BE SENT TO THE OWNER AND THE ARCHITECT.

(5) GENERAL CONTRACTOR SHALL BE RESPONSIBLE FOR ALL APPLICABLE TESTING/INSPECTIONS OF TANKS AND PIPING SYSTEM UPON COMPLETION OF PROJECT AS REQUIRED BY THE NEW YORK CITY FIRE DEPARTMENT RULES AND REGULATIONS. GENERAL CONTRACTOR TO CONTACT THE NEW YORK CITY FIRE DEPARTMENT AT (718) 644.2462 FOR THIS INFORMATION.

(6) CONTRACTOR MUST CONFORM TO THE REQUIREMENTS OF THE NEW YORK CITY ELECTRICAL CODE AND FILE A CERTIFICATE OF ELECTRICAL INSPECTION UPON COMPLETION OF THE WORK WITH THE NEW YORK CITY FIRE DEPARTMENT.

(7) LOCATION AND NUMBER OF EXISTING PUMPS AND TANKS TO BE VERIFIED BY THE NEW YORK CITY FIRE DEPARTMENT.

(8) THE BIDDING CONTRACTOR SHALL VISIT THE SITE AND BECOME FAMILIAR WITH ALL EXISTING CONDITIONS AND PROPOSED WORK ITEMS TO BE COMPLETED AS NOTED ON THE DRAWINGS PRIOR TO BIDDING.

(9) THE CONTRACTOR SHALL VERIFY THE TYPE AND EXACT LOCATION OF ALL EXISTING TANK PIPING, MPD'S PANS, AND FITTING PENETRATIONS INTO THE TANK. NOTIFY ARCHITECT OF RECORD IN WRITING OF ANY DISCREPANCIES PRIOR TO CONSTRUCTION.

(10) ANY UNDERGROUND DRAINAGE LINES, WATER LINES, SEWER LINES, ELECTRICAL LINES, ETC. THAT MAY BE ENCOUNTERED DURING THE COURSE OF CONSTRUCTION SHALL BE REMOVED AND REROUTED AS REQUIRED. GENERAL CONTRACTOR TO NOTIFY ARCHITECT AND OWNER IMMEDIATELY.

(11) PROVIDE COLOR AND SYMBOL CODES ON ALL FILLS AND GAUGE PORTS AS PER A.P.I., N.Y.S.D.E.C. AND OWNER'S STANDARDS. PRODUCT I.D. MARKERS SHALL BE INSTALLED ON ALL FILL PORTS PER N.Y.S.D.E.C. REQUIREMENTS.

(12) GENERAL CONTRACTOR TO PRECISION TEST TANKS, PIPING SYSTEM, ETC. PRIOR TO CONSTRUCTION OF PROJECT AS PER NEW YORK CITY FIRE DEPARTMENT RULES AND REGULATIONS. GENERAL CONTRACTOR SHALL SECURE THE SERVICES OF THE NEW YORK CITY FIRE DEPARTMENT FOR TESTING PURPOSES. AFTER INSTALLATION GENERAL CONTRACTOR SHALL SCHEDULE A TEST TO BE DONE BY OWNER ON TANKS, PIPING, ETC. GENERAL CONTRACTOR SHALL NOT BACK FILL UNTIL ALL TESTING HAS BEEN DONE.

(13) GENERAL CONTRACTOR SHALL BE RESPONSIBLE FOR PROVIDING A "SPARK TEST" OF THE CATHODICALLY PROTECTED PIPE WITNESSED BY A NEW YORK CITY FIRE DEPARTMENT INSPECTOR BEFORE BACK FILL INSPECTION IS SCHEDULED. (IF APPLICABLE)

(14) GENERAL CONTRACTOR TO ASSURE THAT ELECTRICAL EXPLOSION PROOF CONNECTIONS ARE PROVIDED AND IN GOOD CONDITION AT EACH TANK SUMP AS REQUIRED PER N.F.P.A. AND N.E.C. CODES.

(15) GENERAL CONTRACTOR SHALL PATCH AND REPAIR AREAS OF THE CONCRETE DRIVE MAT, SURROUNDING THE ISLANDS, DISTURBED BY CONSTRUCTION WITH A MINIMUM OF 0'-8" THICK CONCRETE, 0'-4" CRUSHED STONE AND (1) LAYER OF #3 REBARS EACH WAY.

N.Y.C. FIRE DEPARTMENT APPROVAL / EQUIPMENT LIST

EQ. NO.	EQUIPMENT	MANUFACTURER	MODEL NUMBER	C of A NUMBER
(1)	MULTI-PRODUCT BLENDER DISPENSER W/SS3	"WAYNE" OVATION	B12/3223DI/6K DOB 2-HOSE	5082
	DISPENSER PAN	ENVIRON	DEEP PAN	
(2)	NOT USED			
(3)	UNDERGROUND PIPING	SMITH FIBERCAST	RED THREAD IIA	5099
(4)	SUBMERSIBLE TURBINE PUMP	FE PETRO	1 1/2 HP W/ INTAKE FILTER SCREEN	4834
(5)	MECHANICAL OVERFILL PREVENTION DEVICE	OPW	61SO (GRAVITY FILL)	4902
(6)	SPILL CONTAINMENT DEVICE	OPW	1-21S (15 GALLON)	4978
(7)	FLEXIBLE CONNECTOR	TITEFLEX	FIRESAFE	
(8)	EXTRACTOR FITTING - CROSS	OPW	233VM-4433	
(9)	LEAK DETECTION SYSTEM	VEEDER ROOT	TLS 350	4853
	AUTOMATIC TANK GAUGE TANK LEVEL PROBE TANK HYDROSTATIC SUMP SENSOR ELECTRONIC LINE LEAK DETECTOR STP SUMP SENSOR DISPENSER PAN SENSOR			
(10)	EXIST. DOUBLE WALLED TANKS TO BE LINED	VIF	EXIST. (2-TOTAL) 4000 GALLONS	VIF
(11)	EXIST. STEEL SINGLE WALLED TANKS TO BE LINED	VIF	EXIST. (2-TOTAL) 4000 GALLONS	VIF

FILL BOX IDENTIFICATION REQUIREMENTS:

IDENTIFICATION REQUIREMENTS SHALL CONFORM TO AMERICAN PETROLEUM INSTITUTE STANDARDS

AMENDED

VAPOR HOSE CONNECTION:	UNLEADED (LOWER)	UNLEADED (HIGHER)	DIESEL
ORANGE	BLACK CROSS WHITE BACKGROUND	WHITE CROSS RED BACKGROUND	YELLOW

ACCEPTABLE FOR PERMIT UNDER DIRECTIVE NO. 14/1975

DEC 28 2010

KAUSAR AHMAD

AS-BUILT DRAWINGS & INSTALLER STATEMENT:

G.C./ INSTALLER SHALL PROVIDE A COMPLETE SET OF AS BUILT DRAWINGS TO SCALE DEPICTING PRECISE LOCATION OF ALL COMPONENTS INSTALLED (INCLUDING PRODUCT/ VAPOR LINE SIZES & LOCATIONS, CONDUIT SIZES & LOCATIONS, ETC.) PRIOR TO OWNER'S ACCEPTANCE.

THESE PLANS MUST INCLUDE A STATEMENT BY THE INSTALLER THAT THE SYSTEM HAS BEEN INSTALLED IN COMPLIANCE WITH THE NEW YORK STATE STANDARDS FOR NEW AND SUBSTANTIALLY MODIFIED PETROLEUM STORAGE FACILITIES, 6 NYCRR PART 614.

LICENSED INSTALLER'S FINAL STATEMENT

I, _____ COMPLETED THE INSTALLATION OF THE EQUIPMENT DESCRIBED IN THE ANNEXED PLANS ON _____. THE INSTALLATION COMPLIES FULLY WITH THE REQUIREMENTS OF THE NEW YORK STATE PETROLEUM BULK STORAGE CODE 6 NYCRR PART 614.

SIGNATURE OF THE LICENSED INSTALLER

320041897
SC343628763

JAMES V. VASSALOTTI — LICENSED PROFESSIONAL ENGINEER — 035878 — STATE OF NEW YORK

GASOLINE SERVICE STATION

WITH ACCESSORY COVENIENCE STORE U.G. 16 B&E & SELF SERVE DISPENSERS


1 PUMP & TANK SITE PLAN

1" = 10'-0"

4TH AVE


NOTE:

1. EXACT LOCATION OF EXISTING TANK FITTINGS TO BE VERIFY IN THE FIELD.



U-BOLLARD DETAIL

N.T.S.



DRIVE MAT DETAIL

1" = 1'-0"

REV	DATE	DESCRIPTION
-	6-17-09	ISSUED TO BID
-	6-24-09	ISSUED TO BLDG DEPT. FOR APPROVAL
-	8-31-09	AS BUILT CONDITIONS

DRAWING: PUMP & TANK SITE PLAN AND EQUIPMENT SCHEDULE

LOCATION: 4001 4th LLC — 4001-11 4th AVE BROOKLYN, NEW YORK

BLOCK 774 | LOT 6 | MAP --- | ZONE C-8 IN R6

VASSALOTTI ARCHITECTS, L.L.P. ASSOCIATES
3000 MARCUS AVE. LAKE SUCCESS, NY 11042

DWN. BY JEFF V. | CHK. BY A.D.

SCALE AS NOTED

DATE 6-17-09 | JOB NO. 08-0071

PAGE NO. DWG. 4 OF 9

DWG. NO. P&T-004.00

EN 404
Explosion-Proof Regenerative Blower

Attachment-B

FEATURES

- Manufactured in the USA
- Maximum flow: 107 SCFM
- Maximum pressure: 57″ WG
- Maximum vacuum: 52″ WG
- Standard motor: 1.0 HP
- Blower construction — cast aluminum housing, cover, impeller & manifold; cast iron flanges
- UL & CSA approved motors for Class I, Group D atmospheres
- Sealed blower assembly
- Quiet operation within OSHA standards

OPTIONS


- TEFC motors
- 50 Hz motors
- International voltages
- Other HP motors
- Corrosion resistant surface treatments
- Remote drive (motorless) models


ACCESSORIES

- Moisture separators
- Explosion-proof motor starters
- Inline & inlet filters
- Vacuum & pressure gauges
- Relief valves
- External mufflers





BLOWER PERFORMANCE AT STANDARD CONDITIONS





EN 404
Explosion-Proof Regenerative Blower





DIMENSIONS: IN / MM
TOLERANCES: .XX ± .08 / 2.0
.XXX ± .030 / .800
(UNLESS OTHERWISE NOTED)

MODEL	L (IN)±.30	L (MM)±8
EN404AR72ML	15.55	395
EN404AR58ML	16.43	417

A 0.75" NPT CONDUIT CONNECTION AT 12 O'CLOCK POSITION

SPECIFICATIONS

MODEL	EN404AR58ML		EN404AR72ML	
Part No.	038173		038174	
Motor Enclosure Type	Explosion-proof		Explosion-proof	
Horsepower	1.0		1.0	
Phase — Frequency	Single — 60 Hz		Three - 60 Hz	
Voltage	115	230	208-230	460
Motor Nameplate Amps	12	6	3.4	1.7
Maximum Blower Amps[1]	14.5	7.2	3.5	1.8
Inrush Amps	70	35	19	9.5
Starter Size	0	00	00	00
Service Factor	1.0		1.0	
Thermal Protection	Automatic		Pilot Duty	
Bearing Type	Sealed, Ball		Sealed, Ball	
Shipping Weight	72 lb (36 kg)		65 lb (30 kg)	

BLOWER LIMITATIONS

Min. Flow @ Max. Suction	0 SCFM @ −52" WG	0 SCFM @ −52" WG
Min. Flow @ Max. Pressure	0 SCFM @ 57" WG	0 SCFM @ 57" WG

[1]Corresponds to the performance point at which the blower and/or motor temperature rise reaches the limit of the thermal protection in the motor.

Specifications subject to change without notice. Please contact factory for specification updates.

Google Maps 4001 4th Ave



Imagery ©2021 Bluesky, CNES / Airbus, Maxar Technologies, Sanborn, Map data ©2021 Google 20 ft

Attachment - C
Sub-way line (BMT)
Est. Location

BP SERVICE STATION
4001-4010 4TH AVENUE
BROOKLYN, NEW YORK
SPILL # 18-11146

Supplemental
Remedial Investigation
Work Plan

NEW YORK STATE DEPARTMENT OF
ENVIRONMENTAL CONSERVATION
REGION II
LONG ISLAND CITY
NEW YORK



PREPARED BY:

BERNINGER ENVIRONMENTAL
17 OLD DOCK ROAD
YAPHANK, NEW YORK 11980

BEi

March 2022
revised1

Table of Contents

1.0 INTRODUCTION

2.0 SITE BACKGROUND

3.0 SITE HISTORY

4.0 SCOPE OF WORK

5.0 REMEDIAL PILOT STUDY

6.0 REPORTING

7.0 HEALTH AND SAFETY

8.0 CONCLUSION

FIGURES

Figure-1 Site Location

Figure-2 Site Map with boring/sampling locations

Figure-3 Proposed Monitoring Well Log

Figure-4 Previous Sampling Locations

ATTACHMENTS

Attachment-A Site Survey
Attachment-B Subway Line Map

Berninger Environmental
groundwater consultants, geologists and scientists
17 Old Dock Road
Yaphank • New York • 11980 **Phone: 631 • 589 • 6521**
A WRS Environmental Services Company **Fax: 631 • 589 • 6528**

March 28th, 2022

Mr. Jonathan Kolleeny
New York State Department of Environmental Conservation (DEC)
Division of Environmental Remediation
Professional Geologist-Region 2
47-40 21st Street
Long Island City, NY 11101

Re: BP Service Station
4001 4th Avenue (and 40th St)
Brooklyn, New York

Supplemental Investigation (revised)
Groundwater Sampling/ Pilot Study
Spill # 1811146

Dear Mr. Kolleeny,

1.0 INTRODUCTION

The following is a Supplemental Investigation Work Plan, that addresses the comments in the DEC letter dated November 5th, 2021. The letter provides comments on the *Supplemental Investigation Soil and Groundwater Report dated October 8th, 2021.* In brief, the letter discusses the need for further investigation with the performance of a pilot test in order to evaluate a remedy for impacted site media. Please read below for the proposed supplemental groundwater sampling locations and the proposed Pilot Study Work Plan to be developed based on supplemental data collected.

2.0 SITE BACKGROUND

The site is located at 4001-4010 4th Avenue, Brooklyn, New York- Figure 1. The site is located on a plot size approximately 10,017 square feet. The site is currently used as a gas station with a convenience store and parking. The building was constructed in 1965 and has been a gasoline station since its first developed use. A Phase II was performed based on the recommendations outlined in the Phase I ESA and supplemental investigations were performed thereafter. Please refer to Attachment-A for a survey of the current layout of the station.

3.0 SITE HISTORY

A supplemental investigation was conducted subsequent to the Phase II investigation that identified impacted soils above State soil clean-up objectives (SCOs) and the presence of underground storage

tanks (USTs) from the old gas station. The supplemental investigation concluded that soil contamination was vertically delineated, but groundwater impacts (perched water at ~30 feet bgs) discovered required additional investigation in order to determine the lateral extent of the contamination.

4.0 SCOPE OF WORK

The proposed scope of work involves the collection of groundwater samples via the installation of monitoring wells down gradient of the previous water sample collected at the newly installed MW-1. Please see Figure-2 for the previous groundwater sample (MW-1) location and the two (2) proposed locations (MW-2 and MW-3). The MW-2 and MW-3 locations were formerly sample locations B-5 and B-8 and previously screened/sampled, therefore no soil will be sampled during the well installations. Significant VOC impacts were documented at each of these locations. Please see Figure-4 for the previous sampling locations from the remedial investigation. Samples are located near the 4th Avenue subway line in order to determine the potential impacts to sensitive receptors. The depth of the subway tunnel will also be evaluated in order to determine these potential impacts. Please see Attachment-B for estimated sub-way line. The depth to the perched water layer in this region is approximately thirty feet (30') below grade surface, as discovered during the previous investigation. Two (2) two inch (2") monitoring wells will be installed at the locations proposed on Figure-2. Well specifications are anticipated to consist of: ten feet (10') of schedule 40 PVC well 0.20" slot screen (25'-35') with schedule 40 PVC riser pipe finishing to grade surface (0-25'). Please see Figure-3 well specs log.

Clean poly-tubing affixed with a check valve sampling device will be used to purge 3-5 well volumes of water prior to sample procurement. All groundwater samples will be placed in laboratory approved glassware and transported on at 36 °F under strict chain of custody to a New York State ELAP certified laboratory for testing via EPA 8260C for VOCs.

5.0 REMEDIAL PILOT STUDY

A Pilot Study Work Plan (PSWP) will be developed based on the sampling results from the newly installed monitoring wells (MW-2 and MW-3). Upon receipt of this data and remedial strategy can be developed in order to propose treatment of both soil and groundwater. Initially, soil vapor extraction (SVE) is the intended remedy to treat soil contamination and will operate in conjunction with either air sparging or in-situ chemical oxidation. The groundwater sampling data will be used to determine the correct pathway toward remediation of groundwater and the PSWP will be developed subsequent to the evaluation of all contaminated site media.

6.0 REPORTING

A Report of Findings will be issued upon receipt of the lab results. The Report will include a summary of the results compared to standards and a pilot test report with the measurements recorded from the testing.

7.0 HEALTH AND SAFETY

It is anticipated that level D personal protective equipment (PPE) will be used during the installation of the SVE/AS points and all associated piping. All personnel on-site will be will be properly trained and certified by the Occupational Safety and Health Act (OSHA) according to the regulations set forth in the Code of Federal Regulations 29 (CFR) 1910.

Level D PPE includes the following:

- Eye protection- Wear goggles or face shield (splash prevention)
- Head- Hard hat when required
- Hands- Wear neoprene gloves
- Feet- Wear steel-toe boots with chemical resistant soles or neoprene covers
- Clothing- Long sleeve shirts and long pant legs.

8.0 CONCLUSION

Based on the results from the investigation a remedial plan will be developed in order to treat contaminated media (soil and groundwater) at the site. A PSWP will be developed utilizing soil and groundwater data from the new wells installed. A Report of Findings will also be drafted with results of the subway terminal investigation and also the groundwater sampling results from the monitoring wells. Any questions or comments regarding this Work Plan can be directed to BEI.

Sincerely,
Berninger Environmental

Justin Halpin
Scientist/Project Manager

FIGURES





Figure-1
Site Location
Brooklyn, NY



Site Map
Proposed Sampling Locations
Figure-2

BP Service Station
4001-4010 4th Avenue
Brooklyn, NY

Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980


Proposed Monitoring Well Log

Figure-3

Project: BP Service Station
Client: The Macchia Group
Location: 4001 4th Avenue Brooklyn
Well No: MW-2 and 3 **Use:** Monitoring/Sampling/Pilot Testing
Install Method: Direct Push
Casing Type: sch 40 PVC **Casing Dia:** 2" **Casing Length:** 25'
Screen Type: sch 40 PVC **Screen Dia:** 2" **Screen Length:** 10'
Screen Slot: 0.02" **Gravel Pack:** #2 fil-pro
Casing Seal: Clean Fill **Finish:** 5" Manhole Flush mount

Date: TBD
Be Job No:
Installer: BEI
Bore Hole Dia: 2.5"
Sample Method: EPA 8260
Depth to Water: 30'
Total Depth: 35'
Security: 2" j-plug/ 5"manhole

Depth bgs	Sample Information	Well Design	Identification/Remarks
0	5" cast iron manhole		flush mounted cement sealed
5'			
10'	(25') of 2" PVC riser		
20'			
30'	Fil-pro gravel pack		(10') of 2" PVC 0.02" slot screen DTW 30'
40'		DTB (35')	




Site Map
Boring Locations
Figure-4

BP Service Station
4001-4010 4th Avenue
Brooklyn, NY

BEi Berninger Environmental
groundwater consultants, geologists and scientists
A WRS Environmental Services Company
Phone: 631 589 6521
17 Old Dock Road Yaphank, NY 11980

ATTACHMENTS

ATTACHMENT-A



TANK MONITORING SYSTEM NOTE(S) & LEGEND :

H = ALARM HORN

L = FLASHING LIGHT

= EMERGENCY CUT OFF SWITCH

* ALARM HORN AND FLASHING LIGHT, CONNECTED TO D.E.C. APPROVED TANK MONITORING SYSTEM TO INDICATE HIGH LEVEL ALARM.

* HIGH LEVEL ALARM, BOTH AUDIBLE AND VISUAL, TO BE TRIGGERED WHEN TANK IS NO MORE THAN 90 % FULL.

* INSTALLATION MUST BE INSTALLED IN ACCORDANCE WITH FEDERAL REGULATION - 40 CFR PARTS 280 AND 281.

NOTE: WHERE INDICATED EXISTING, STEEL SINGLE WALLED UG GASO. TANK TO BE LINED (2-TOTAL), EACH TANK MUST BE LINED AS TO COMPLY WITH ALL TESTING AND REGULATIONS THAT GOVERN INCLUDING USA FEDERAL REGULATIONS (CFR), NEW YORK STATE DEPT. OF ENVIROMENT CONSERVATION, NEW YORK CODE RULES AND REGULATIONS (NYCRR) AND NEW YORK CITY FIRE DEPARTMENT. SEE NPTES "C" & "D" ON DWG. P&T-002 FO RMORE INFORMATION.

EXISTING 2-4,000 GAL. UG SINGLE WALL STEEL FUEL TANKS TO BE LINED. REPLACE CONC. MAT, FOR MORE INFO. SEE DWG P&T-004. REPLACE MANHOLE ON EA. TANK. REMOVE ALL STP & INSTALL NEW STP AS INDICATED. REMOVE ALL PIPING, VALVES, ETC. AND INSTALL NEW (C) AS INDICATED.

TANK LEVEL MONITOR (TLM) CONNECTED TO VEEDER ROOT SYSTEM (TYP. 1-EA. TANK) (9)

BSA APPR'D EXTRACTOR FLOAT VALVE (GAL. 247-83-SM) I-REQ'D IN EA. GASO. TANK EXCEPT DIESEL TANK

(4)NEW DIRECT FILL W/ 4 NEW NYC APPR'D 15 GAL SPILL CONTAINMENT DEVICE AND MECHANICAL OVERFILL PROTECTION DEVICE ON EACH FILL LINE (5)(6)

NEW STAGE-I VAPORY RECOVERY DRYBREAK

(4) NEW 2" DIA. VENT 15' ABOVE GRADE & 10' FROM THE NEAREST BLDG. OPENING & WELL BRACED IN POSITION C.A.R.B. APPROVED P/V CAPS (GASO. TANKS ONLY), GC TO INSTALL 2" DIA. VENT MANIFOLD, SEE DET. ON DWG. P&T-007 (GASO. TANKS ONLY)

NEW 2" SINGLE WALL FIBERGLASS VENT PIPING (PICH BACK TO TANK 1/8" PER FOOT, BACKFILL PER MANUFACTURER'S SPECS.

NEW ANULAR PROBE MONITOR (1 REQ'R EA. TANK) WHERE INDICATED ONLY

(4)NEW DIRECT FILL W/ 4 NEW NYC APPR'D 15 GAL SPILL CONTAINMENT DEVICE AND MECHANICAL OVERFILL PROTECTION DEVICE ON EACH FILL LINE (5)(6)

TANK LEVEL MONITOR (TLM) CONNECTED TO VEEDER ROOT SYSTEM (TYP. 1-EA. TANK) (9)

(3) NEW TOTAL SUBMERSIBLE PUMP IN A STP SUMP, PROVIDE (4) NEW 42" DIA. MANHOLE (1) REQUIRED IN EA. TANK) (4)

STICK LINE IN MANHOLE (1 REQUIRED IN EA. TANK) WHERE INDICATED

REPLACE CONC. MAT & INSTALL NEW PIPING, ETC. AS NOTED, SEE DWGS. P&T-004, P&T-005, P&T-006 FOR MORE INFO.

EXISTING 2-4,000 GAL. UG DOUBLE WALLED MOTOR FUEL TANKS TO BE LINED. REPLACE CONC. MAT, FOR MORE INFO. SEE DWG P&T-004. REPLACE MANHOLE ON EA. TANK. REMOVE ALL STP & INSTALL NEW STP AS INDICATED. REMOVE ALL PIPING, VALVES, ETC. AND INSTALL NEW (C) AS INDICATED.
NOTE: WHERE INDICATED EXISTING, DOUBLE WALLED UG GASO. TANK TO BE LINED (2-TOTAL), EACH TANK MUST BE LINED AS TO COMPLY WITH ALL TESTING AND REGULATIONS THAT GOVERN INCLUDING USA FEDERAL REGULATIONS (CFR), NEW YORK STATE DEPT. OF ENVIROMENT CONSERVATION, NEW YORK CODE RULES AND REGULATIONS (NYCRR) AND NEW YORK CITY FIRE DEPARTMENT. SEE NPTES "C" & "D" ON DWG. P&T-002 FO RMORE INFORMATION.

NOTES:

(1) REMOVE ALL EXISTING CONCRETE PUMP ISLAND, DISPENSERS, TANK STP SUMPS, FILLS, VAPOR RECOVERY MANHOLES, TOP SLAB, AND RELATED PIPING AND REPLACE WITH AMERON DUALOY 3000/L NONMETALLIC PIPING UNLESS OTHERWISE NOTED. DISPENSERS TO BE REFURBISHED AND REUSED.

(2) PIPING SHOWN IS DIAGRAMMATIC ONLY. REFER TO MANUFACTURER'S INSTALLATION MANUAL FOR PROPER INSTALLATION.

(3) GENERAL CONTRACTOR TO VERIFY IN FIELD THE EXACT NUMBER OF TANK OPENINGS AND FITTING LOCATIONS AND NOTIFY ARCHITECT OF ANY DISCREPANCIES.

(4) AT THE TIME OF COMPLETION THE CONTRACTOR SHALL FILE AN AFFIDAVIT WITH THE NEW YORK CITY FIRE DEPARTMENT STATING WORK AND REQUIRED TESTS PERFORMED ON ANY TANKS/PIPING. TESTS RESULTS SHALL BE NOTED AND A COPY SHALL BE SENT TO THE OWNER AND THE ARCHITECT.

(5) GENERAL CONTRACTOR SHALL BE RESPONSIBLE FOR ALL APPLICABLE TESTING/INSPECTIONS OF TANKS AND PIPING SYSTEM UPON COMPLETION OF PROJECT AS REQUIRED BY THE NEW YORK CITY FIRE DEPARTMENT RULES AND REGULATIONS. GENERAL CONTRACTOR TO CONTACT THE NEW YORK CITY FIRE DEPARTMENT AT (718) 644.2462 FOR THIS INFORMATION.

(6) CONTRACTOR MUST CONFORM TO THE REQUIREMENTS OF THE NEW YORK CITY ELECTRICAL CODE AND FILE A CERTIFICATE OF ELECTRICAL INSPECTION UPON COMPLETION OF THE WORK WITH THE NEW YORK CITY FIRE DEPARTMENT.

(7) LOCATION AND NUMBER OF EXISTING PUMPS AND TANKS TO BE VERIFIED BY THE NEW YORK CITY FIRE DEPARTMENT.

(8) THE BIDDING CONTRACTOR SHALL VISIT THE SITE AND BECOME FAMILIAR WITH ALL EXISTING CONDITIONS AND PROPOSED WORK ITEMS TO BE COMPLETED AS NOTED ON THE DRAWINGS PRIOR TO BIDDING.

(9) THE CONTRACTOR SHALL VERIFY THE TYPE AND EXACT LOCATION OF ALL EXISTING TANK PIPING, MPD'S PANS, AND FITTING PENETRATIONS INTO THE TANK. NOTIFY ARCHITECT OF RECORD IN WRITING OF ANY DISCREPANCIES PRIOR TO CONSTRUCTION.

(10) ANY UNDERGROUND DRAINAGE LINES, WATER LINES, SEWER LINES, ELECTRICAL LINES, ETC. THAT MAY BE ENCOUNTERED DURING THE COURSE OF CONSTRUCTION SHALL BE REMOVED AND REROUTED AS REQUIRED. GENERAL CONTRACTOR TO NOTIFY ARCHITECT AND OWNER IMMEDIATELY.

(11) PROVIDE COLOR AND SYMBOL CODES ON ALL FILLS AND GAUGE PORTS AS PER A.P.I., N.Y.S.D.E.C. AND OWNER'S STANDARDS. PRODUCT I.D. MARKERS SHALL BE INSTALLED ON ALL FILL PORTS PER N.Y.S.D.E.C. REQUIREMENTS.

(12) GENERAL CONTRACTOR TO PRECISION TEST TANKS, PIPING SYSTEM, ETC. PRIOR TO CONSTRUCTION OF PROJECT AS PER NEW YORK CITY FIRE DEPARTMENT RULES AND REGULATIONS. GENERAL CONTRACTOR SHALL SECURE THE SERVICES OF THE NEW YORK CITY FIRE DEPARTMENT FOR TESTING PURPOSES. AFTER INSTALLATION GENERAL CONTRACTOR SHALL SCHEDULE A TEST TO BE DONE BY OWNER ON TANKS, PIPING, ETC. GENERAL CONTRACTOR SHALL NOT BACK FILL UNTIL ALL TESTING HAS BEEN DONE.

(13) GENERAL CONTRACTOR SHALL BE RESPONSIBLE FOR PROVIDING A "SPARK TEST" OF THE CATHODICALLY PROTECTED PIPE WITNESSED BY A NEW YORK CITY FIRE DEPARTMENT INSPECTOR BEFORE BACK FILL INSPECTION IS SCHEDULED. (IF APPLICABLE)

(14) GENERAL CONTRACTOR TO ASSURE THAT ELECTRICAL EXPLOSION PROOF CONNECTIONS ARE PROVIDED AND IN GOOD CONDITION AT EACH TANK SUMP AS REQUIRED PER N.F.P.A. AND N.E.C. CODES.

(15) GENERAL CONTRACTOR SHALL PATCH AND REPAIR AREAS OF THE CONCRETE DRIVE MAT, SURROUNDING THE ISLANDS, DISTURBED BY CONSTRUCTION WITH A MINIMUM OF 0'-8" THICK CONCRETE, 0'-4" CRUSHED STONE AND (1) LAYER OF #3 REBARS EACH WAY.

N.Y.C. FIRE DEPARTMENT APPROVAL / EQUIPMENT LIST

EQ. NO.	EQUIPMENT	MANUFACTURER	MODEL NUMBER	C of A NUMBER
1	MULTI-PRODUCT BLENDER DISPENSER W/SB3	"WAYNE" OVATION	B12/3223DI/6K DOB 2-HOSE	5082
	DISPENSER PAN	ENVIRO	DEEP PAN	
2	NOT USED			
3	UNDERGROUND PIPING	SMITH FIBERCAST	RED THREAD IIA	5099
4	SUBMERSIBLE TURBINE PUMP	FE PETRO	1 1/2 HP W/ INTAKE FILTER SCREEN	4834
5	MECHANICAL OVERFILL PREVENTION DEVICE	OPW	61SO (GRAVITY FILL)	4902
6	SPILL CONTAINMENT DEVICE	OPW	1-2115 (15 GALLON)	4978
7	FLEXIBLE CONNECTOR	TITEFLEX	FIRESAFE	
8	EXTRACTOR FITTING - CROSS	OPW	233VM-4433	
9	LEAK DETECTION SYSTEM	VEEDER ROOT	TLS 350	4853
	AUTOMATIC TANK GAUGE TANK LEVEL PROBE TANK HYDROSTATIC SUMP SENSOR ELECTRONIC LINE LEAK DETECTOR STP SUMP SENSOR DISPENSER PAN SENSOR			
10	EXIST. DOUBLE WALLED TANKS TO BE LINED	VIF	EXIST. (2-TOTAL) 4000 GALLONS	VIF
11	EXIST. STEEL SINGLE WALLED TANKS TO BE LINED	VIF	EXIST. (2-TOTAL) 4000 GALLONS	VIF

FILL BOX IDENTIFICATION REQUIREMENTS:

IDENTIFICATION REQUIREMENTS SHALL CONFORM TO AMERICAN PETROLEUM INSTITUTE STANDARDS

AMENDED

VAPOR HOSE CONNECTION:	UNLEADED (LOWER)	UNLEADED (HIGHER)	DIESEL
ORANGE	BLACK CROSS WHITE BACKGROUND	WHITE CROSS RED BACKGROUND	YELLOW

ACCEPTABLE FOR PERMIT UNDER DIRECTIVE NO. 14/1975
DEC 28 2010
KAUSAR AHMAD

AS-BUILT DRAWINGS & INSTALLER STATEMENT:

G.C./ INSTALLER SHALL PROVIDE A COMPLETE SET OF AS BUILT DRAWINGS TO SCALE DEPICTING PRECISE LOCATION OF ALL COMPONENTS INSTALLED (INCLUDING PRODUCT/ VAPOR LINE SIZES & LOCATIONS, CONDUIT SIZES & LOCATIONS, ETC.) PRIOR TO OWNER'S ACCEPTANCE.

THESE PLANS MUST INCLUDE A STATEMENT BY THE INSTALLER THAT THE SYSTEM HAS BEEN INSTALLED IN COMPLIANCE WITH THE NEW YORK STATE STANDARDS FOR NEW AND SUBSTANTIALLY MODIFIED PETROLEUM STORAGE FACILITIES, 6 NYCRR PART 614.

LICENSED INSTALLER'S FINAL STATEMENT

I, _____ COMPLETED THE INSTALLATION OF THE EQUIPMENT DESCRIBED IN THE ANNEXED PLANS ON _____. THE INSTALLATION COMPLIES FULLY WITH THE REQUIREMENTS OF THE NEW YORK STATE PETROLEUM BULK STORAGE CODE 6 NYCRR PART 614.

SIGNATURE OF THE LICENSED INSTALLER

320041897
SC343628763


JAMES V. VASSALOTTI — LICENSED PROFESSIONAL ENGINEER — 035878 — STATE OF NEW YORK

GASOLINE SERVICE STATION

WITH ACCESSORY COVENIENCE STORE U.G. 16 B&E & SELF SERVE DISPENSERS


1 PUMP & TANK SITE PLAN

1" = 10'-0"



U-BOLLARD DETAIL

N.T.S.



DRIVE MAT DETAIL

1" = 1'-0"

NOTE:

1. EXACT LOCATION OF EXISTING TANK FITTINGS TO BE VERIFY IN THE FIELD.

REV	DATE	DESCRIPTION
-	6-17-09	ISSUED TO BID
-	6-24-09	ISSUED TO BLDG DEPT. FOR APPROVAL
-	8-31-09	AS BUILT CONDITIONS

DRAWING: PUMP & TANK SITE PLAN AND EQUIPMENT SCHEDULE

LOCATION: 4001 4th LLC
4001-11 4th AVE
BROOKLYN, NEW YORK

BLOCK 774 | LOT 6 | MAP --- | ZONE C-8 IN R6

VASSALOTTI ARCHITECTS, L.L.P. ASSOCIATES
3000 MARCUS AVE. LAKE SUCCESS, NY 11042

DWN. BY	CHK. BY
JEFF V.	A.D.

SCALE: AS NOTED

DATE	JOB NO.
6-17-09	08-0071

PAGE NO.: DWG. 4 OF 9

DWG. NO.: P&T-004.00

Google Maps 4001 4th Ave



Imagery ©2021 Bluesky, CNES / Airbus, Maxar Technologies, Sanborn, Map data ©2021 Google 20 ft

Attachment - B

Sub-way line (BMT)

Est. Location

APPENDIX G - EDR Environmental Liens and AUL

4001 4th Avenue
4001 4th Avenue
Brooklyn, NY 11232

Inquiry Number: 7571432.7
February 20, 2024

EDR Environmental Lien and AUL Search

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

EDR Environmental Lien and AUL Search

The EDR Environmental Lien and AUL Search Report provides results from a search of available current land title records for environmental cleanup liens and other activity and use limitations, such as engineering controls and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied address information to:

- search for parcel information and/or legal description;
- search for ownership information;
- research official land title documents recorded at jurisdictional agencies such as recorders' offices, registries of deeds, county clerks' offices, etc.;
- access a copy of the deed;
- search for environmental encumbering instrument(s) associated with the deed;
- provide a copy of any environmental encumbrance(s) based upon a review of key words in the instrument(s) (title, parties involved, and description); and
- provide a copy of the deed or cite documents reviewed.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR Environmental Lien and AUL Search

TARGET PROPERTY INFORMATION

ADDRESS

4001 4th Avenue
4001 4th Avenue
Brooklyn, NY 11232

ENVIRONMENTAL LIEN

Environmental Lien: Found ☐ Not Found ☒

OTHER ACTIVITY AND USE LIMITATIONS (AULs)

AULs: Found ☐ Not Found ☒

RESEARCH SOURCE

Source 1:

New York City Register of Deeds
Kings, NY

PROPERTY INFORMATION

Deed 1:

Type of Deed:	Bargain & Sale Deed
Title is vested in:	4001 4th LLC
Title received from:	Estron Oil Corp
Deed Dated	9/9/2008
Deed Recorded:	9/22/2008
Book:	NA
Page:	NA
Volume:	NA
Instrument:	2008091800252001
Docket:	NA
Land Record Comments:	see exhibit
Miscellaneous Comments:	NA
Legal Description:	see exhibit
Legal Current Owner:	4001 4th LLC
Parcel # / Property Identifier:	block 714 lot 6
Comments:	see exhibit

Deed Exhibit 1

NYC DEPARTMENT OF FINANCE
OFFICE OF THE CITY REGISTER

This page is part of the instrument. The City Register will rely on the information provided by you on this page for purposes of indexing this instrument. The information on this page will control for indexing purposes in the event of any conflict with the rest of the document.

2008091800252001001E2D08

RECORDING AND ENDORSEMENT COVER PAGE **PAGE 1 OF 4**

Document ID: 2008091800252001 Document Date: 09-09-2008 Preparation Date: 09-18-2008
Document Type: DEED
Document Page Count: 3

PRESENTER:
FIRST AMERICAN -UNIONDALE*PICK-UP*
333 EARLE OVINGTON BLVD,
TITLE# 3001-246037 K DS
UNIONDALE, NY 11553
516-832-3206
lwing@firstam.com

RETURN TO:
HOWARD STAVE, ESQ.
473 OLD COURTHOUSE ROAD
MANHASSET HILLS, NY 11040

PROPERTY DATA

Borough	Block	Lot	Unit	Address
BROOKLYN	714	6	Entire Lot	4001 4 AVENUE

Property Type: COMMERCIAL REAL ESTATE

CROSS REFERENCE DATA

CRFN_____ *or* Document ID_____ *or* _____ Year____ Reel ___ Page____ *or* File Number_____

PARTIES

GRANTOR/SELLER:
ESTRON OIL CORP.
242 DREXEL AVENUE
WESTBURY, NY 11590

GRANTEE/BUYER:
4001 4TH LLC
556 CENTRAL AVENUE
BETHPAGE, NY 11714

FEES AND TAXES

Mortgage		
Mortgage Amount:	$	0.00
Taxable Mortgage Amount:	$	0.00
Exemption:		
TAXES: County (Basic):	$	0.00
City (Additional):	$	0.00
Spec (Additional):	$	0.00
TASF:	$	0.00
MTA:	$	0.00
NYCTA:	$	0.00
Additional MRT:	$	0.00
TOTAL:	$	0.00
Recording Fee:	$	52.00
Affidavit Fee:	$	0.00

Filing Fee:	
$	165.00
NYC Real Property Transfer Tax:	
$	39,375.00
NYS Real Estate Transfer Tax:	
$	6,000.00

RECORDED OR FILED IN THE OFFICE OF THE CITY REGISTER OF THE CITY OF NEW YORK
Recorded/Filed 09-22-2008 10:46
City Register File No.(CRFN):
2008000374174

City Register Official Signature

First American Title Insurance Company of New York
3001-246037

BARGAIN AND SALE DEED WITH COVENANT AGAINST GRANTOR'S ACTS (INDIVIDUAL OR CORPORATION)

THIS INDENTURE, made the 9th September 2008

between ESTRON OIL CORP., a domestic corporation with principal offices located at 242 Drexel Avenue, Westbury, N.Y. 11590, party of the first part, and

4001 4th LLC, with principal offices located at 556 Central Avenue, Bethpage, NY 11714, party of the second part,

WITNESSETH, that the party of the first part, in consideration of Ten Dollars, lawful money of the United States, paid by the party of the second part, does hereby grant and release unto the party of the second part, the heirs or successors and assigns of the party of the second party forever,

County: Kings
Section: 3
Block: 714
Lot: 6

All, that certain plot, or piece or parcel of land, with the buildings and improvements thereon erected, situate, lying and being in the County of Kings, City and State of New York, bounded and described as follows:

SEE DESCRIPTION ATTACHED

Premises known as and by the street number 4001 4th Avenue, Brooklyn, N.Y.

Grantor(s) herein being the same as the grantee(s) in deed dated March 31, 1965 and recorded in the Office of the Clerk of the County of Kings on June 7, 1965 in Liber 9393, page 20.

TOGETHER with all right, title and interest, in any, of the party of the first part in and to any streets and roads abutting the above described premises to the center lines thereof; **TOGETHER** with the appurtenances and all the estate and rights of the party of the first part in and to said premises; **TO HAVE AND TO HOLD** the premises herein granted unto the party of the second part, the heirs or successors and assigns of the party of the second part forever.

AND the party of the first part covenants that the party of the first part has not done or suffered anything whereby the said premises have been encumbered in an way whatever, except as aforesaid.

AND the party of the first part, in compliance with Section 13 of the Lien Law, covenants that the party of the first part will receive the consideration for this conveyance and will hold the right to receive such consideration as a trust fund to be applied first for the purpose of paying the cost of improvement and will apply the same first to the payment of the cost of improvement before using any part of the total of the same for any other purpose.

First American Title Insurance Company of New York

Title No. 3001-246037

SCHEDULE "A"

ALL THAT CERTAIN PLOT, PIECE OR PARCEL OF LAND, SITUATE, LYING AND BEING IN THE BOROUGH OF BROOKLYN, COUNTY OF KINGS, CITY AND STATE OF NEW YORK, BOUNDED AND DESCRIBED AS FOLLOWS, TO WIT:

BEGINNING AT THE CORNER FORMED BY THE INTERSECTION OF THE EASTERLY SIDE OF FOURTH AVENUE WITH THE SOUTHERLY SIDE OF FORTIETH STREET;

RUNNING THENCE EASTERLY ALONG THE SOUTHERLY SIDE OF FORTIETH STREET ONE HUNDRED (100) FEET;

THENCE SOUTHERLY PARALLEL WITH FOURTH AVENUE ONE HUNDRED (100) FEET TWO (2) INCHES TO THE CENTRE LINE OF THE BLOCK BETWEEN FORTIETH AND FORTY-FIRST STREETS;

THENCE WESTERLY ALONG SAID CENTRE LINE OF THE BLOCK AND PARALLEL WITH FORTIETH STREET, ONE HUNDRED (100) FEET TO THE EASTERLY SIDE OF FOURTH AVENUE AND

THENCE NORTHERLY ALONG THE EASTERLY SIDE OF FOURTH AVENUE, ONE HUNDRED (100) FEET TWO (2) INCHES TO THE CORNER, THE POINT OR PLACE OF BEGINNING.

THE policy to be issued under this report will insure the title to such buildings and improvements erected on the premises, which by law constitute real property.

FOR CONVEYANCING ONLY: TOGETHER with all the right, title and interest of the party of the first part, of in and to the land lying in the street in front of and adjoining said premises.

the cost of improvement before using any part of the total of the same for any other purpose.

The word "party" shall be construed as if it reads "parties" whenever the sense of this indenture so requires.

IN WITNESS WHEREOF, the party of the first part has duly executed this deed the day and year first above written.

ESTRON OIL CORP.,

BY: Harvey Nager,
Vice President

STATE OF NEW YORK)

ss:

COUNTY OF NASSAU)

On the 9th day of September , in the year 200 8 before me the undersigned, a notary public in and for the said State, personally appeared Harvey Nager personally known to me or proved to me on the basis of satisfactory evidence to be the individual(s) whose name(s) is(are) subscribed tothe within instrument and acknowledged to me that he/she/they executed the same in his/her/their capacit(ies) and that by his/her/their signature(s) on the instrument, the individual(s) or the person upon behalf of which the individual(s) acted, executed the instrument.

Mary R. McD

Notary Public - Mary R. McDonough

Mary R. McDonough
Notary Public, State of New York
No. 01MC6122521
Qualified in Suffolk County
Commission Expires February 14, 2009

BARGAIN AND SALE DEED
with Covenant Against Grantor's Acts

Title No. 3001-246037


ESTRON OIL CORP.
TO
4001 4th LLC

Section: 3
Block: 714
Lot: 6
County or Town: Kings County
Street Address: 4001 4th Ave.
Brooklyn, N.Y. 11232

Return by Mail To:

Howard Stave, Esq.
473 Old Courthouse Road
Manhasset Hills, N.Y. 11040

NYC DEPARTMENT OF FINANCE
OFFICE OF THE CITY REGISTER



2008091800252001001SE389

SUPPORTING DOCUMENT COVER PAGE **PAGE 1 OF 1**

Document ID: 2008091800252001 Document Date: 09-09-2008 Preparation Date: 09-18-2008
Document Type: DEED

ASSOCIATED TAX FORM ID: 2008090900116

SUPPORTING DOCUMENTS SUBMITTED:

	Page Count
DEP CUSTOMER REGISTRATION FORM FOR WATER AND SEWER BILLING	1
RP - 5217 REAL PROPERTY TRANSFER REPORT	1

FOR CITY USE ONLY

C1. County Code | C2. Date Deed Recorded (Month / Day / Year)

C3. Book OR C4. Page

C5. CRFN

REAL PROPERTY TRANSFER REPORT

STATE OF NEW YORK
STATE BOARD OF REAL PROPERTY SERVICES

RP - 5217NYC

(Rev 11/2002)

PROPERTY INFORMATION

1. Property Location: 4001 (STREET NUMBER) | 4 AVENUE (STREET NAME) | BROOKLYN (BOROUGH) | 11232 (ZIP CODE)

2. Buyer Name: 4001 4TH LLC (LAST NAME / COMPANY) (FIRST NAME)

(LAST NAME / COMPANY) (FIRST NAME)

3. Tax Billing Address: Indicate where future Tax Bills are to be sent if other than buyer address (at bottom of form) (LAST NAME / COMPANY) (FIRST NAME)

(STREET NUMBER AND STREET NAME) (CITY OR TOWN) (STATE) (ZIP CODE)

4. Indicate the number of Assessment Roll parcels transferred on the deed: 1 # of Parcels OR ☐ Part of a Parcel

4A. Planning Board Approval - N/A for NYC

4B. Agricultural District Notice - N/A for NYC

5. Deed Property Size: (FRONT FEET) X (DEPTH) OR (ACRES)

Check the boxes below as they apply:

6. Ownership Type is Condominium ☐

7. New Construction on Vacant Land ☐

8. Seller Name: ESTRON OIL CORP. (LAST NAME / COMPANY) (FIRST NAME)

(LAST NAME / COMPANY) (FIRST NAME)

9. Check the box below which most accurately describes the use of the property at the time of sale:

A ☐ One Family Residential
B ☐ 2 or 3 Family Residential
C ☐ Residential Vacant Land
D ☐ Non-Residential Vacant Land
E ☑ Commercial
F ☐ Apartment
G ☐ Entertainment / Amusement
H ☐ Community Service
I ☐ Industrial
J ☐ Public Service

SALE INFORMATION

10. Sale Contract Date: 8 / 26 / 2008 (Month / Day / Year)

11. Date of Sale / Transfer: 9 / 9 / 2008 (Month / Day / Year)

12. Full Sale Price: $ 1,500,000.00

(Full Sale Price is the total amount paid for the property including personal property. This payment may be in the form of cash, other property or goods, or the assumption of mortgages or other obligations.) *Please round to the nearest whole dollar amount.*

13. Indicate the value of personal property included in the sale:

14. Check one or more of these conditions as applicable to transfer:

A ☐ Sale Between Relatives or Former Relatives
B ☐ Sale Between Related Companies or Partners in Business
C ☐ One of the Buyers is also a Seller
D ☐ Buyer or Seller is Government Agency or Lending Institution
E ☐ Deed Type not Warranty or Bargain and Sale (Specify Below)
F ☐ Sale of Fractional or Less than Fee Interest (Specify Below)
G ☐ Significant Change in Property Between Taxable Status and Sale Dates
H ☐ Sale of Business is Included in Sale Price
I ☐ Other Unusual Factors Affecting Sale Price (Specify Below)
J ☑ None

ASSESSMENT INFORMATION - Data should reflect the latest Final Assessment Roll and Tax Bill

15. Building Class: G 4

16. Total Assessed Value (of all parcels in transfer):

17. Borough, Block and Lot / Roll identifier(s) (If more than three, attach sheet with additional identifier(s)):

BROOKLYN 714 6

CERTIFICATION

I certify that all of the items of information entered on this form are true and correct (to the best of my knowledge and belief) and I understand that the making of any willful false statement of material fact herein will subject me to the provisions of the penal law relative to the making and filing of false instruments.

BUYER

BUYER SIGNATURE: [signature] DATE: 9/9/08

556 (STREET NUMBER) Central Ave. (STREET NAME (AFTER SALE))

Bethpage (CITY OR TOWN) N.Y. (STATE) 11714 (ZIP CODE)

BUYER'S ATTORNEY

Steve (LAST NAME) Howard (FIRST NAME)

516 (AREA CODE) 627-6300 (TELEPHONE NUMBER)

SELLER

X [signature] (SELLER SIGNATURE) 9/9/08 (DATE)

2008090900116201

CERTIFICATION

I certify that all of the items of information entered on this form are true and correct (to the best of my knowledge and belief) and understand that the making of any willful false statement of material fact herein will subject me to the provisions of the penal law relative to the making and filing of false instruments.

BUYER

BUYER SIGNATURE: [signature] | DATE: 9/9/2008

556 | STREET NUMBER: Central Ave. | STREET NAME (AFTER SALE)

Bethpage | CITY OR TOWN: NY | STATE: 11714 | ZIP CODE

BUYER'S ATTORNEY

LAST NAME: Stave | FIRST NAME: Howard

AREA CODE: 516 | TELEPHONE NUMBER: 627-6300

SELLER

SELLER SIGNATURE: [signature] | DATE: 9/9/08

2008090900116201

The City of New York
Department of Environmental Protection
Bureau of Customer Services
59-17 Junction Boulevard
Flushing, NY 11373-5108

www.nyc.gov/dep

Customer Registration Form for Water and Sewer Billing

Property and Owner Information:

(1) Property receiving service is located in the Borough of **BROOKLYN**
Block: **714** Lot: **6**

(2) Account Number (if applicable):
Meter Number (if available–include the letter):

(3) Street Address of Property Receiving Service:
Street **4001 4 AVENUE** City **NY** State **NY** Zip **11232**

(4) Full name, mailing address, home phone and business phone numbers of owner of property receiving service: (please provide information on owner ONLY; do NOT give information on property manager or tenant):
Owner's Name Business: **4001 4TH LLC**
or Individual:
(Last Name) (First Name) (MI)
Street **556 CENTRAL AVENUE** City **BETHPAGE** State **NY** Zip **11714**
Home Phone(Numbers only): Business Phone(Numbers only):

Customer Billing Information:

PLEASE NOTE:

A. Water and sewer charges are the legal responsibility of the owner of a property receiving water and/or sewer service. The owner's responsibility to pay such charges is not affected by any lease, license or other arrangement, or any assignment of responsibility for payment of such charges.

B. Water and sewer charges constitute a lien on the property until paid. In addition to legal action against the owner, a failure to pay such charges when due may result in foreclosure of the lien by the City of New York, or the property being placed in a lien sale by the City.

C. Original bills for water and/or sewer service will be mailed to the owner, at the owner's address specified on this form. DEP will provide a duplicate copy of bills to one other party (such as a managing agent) if so requested below, provided, however, that any failure or delay by DEP in providing duplicate copies of bills shall in no way relieve the owner from his/her/its liability to pay all outstanding water and sewer charges.

(5) If you would like a duplicate copy of bills sent to another party, please check here ☐ and fill out the following information:
Name of Party to Receive Duplicate Copies of Bills:

(6) Mailing Address: Street City State Zip

(7) Relationship to Owner (check one): Managing Agent ☐ Mortgagee ☐
Tenant ☐ Other (please explain):

Owner's Approval

The undersigned certifies that he/she/it is the owner of the property receiving service referenced above; that he/she/it has read and understands Paragraphs A, B, C under the section captioned "Customer Billing Information"; and that the information supplied by the undersigned on this form is true and complete to the best of his/her/its knowledge.

(8) E-mail:

(9) Name of Owner: 4001 4th LLC

(10) Signature: _____

Name and Title of Person Signing for Owner, if applicable: George J. Macchia, Managing Member

Date(mm/dd/yyyy): 09/09/2008

BCS-7CRF Rev. 05/2003

2008090900116101

APPENDIX H - User Questionnaire

Lesova
ENVIRONMENTAL GROUP

Phase I Environmental Site Assessment User Questionnaire

(To be completed by the user of the Phase I ESA)

Completed By: Shie Lefkowitz

Relationship to Subject Property: Tenant

Subject Property Address: 4001 4th Avenue, Brooklyn NY 11232 **Date:** 02/26/2024

Please answer the following questions to the best of your knowledge:

1) Are there any environmental liens filed or recorded against the property? No

2) Are there activity and use limitations that are in place on the property or that have been filed or recorded against the property?

3) Do you have any specialized knowledge or experience related to the property or nearby properties? No

4) Does the purchase price being paid for this property reasonably reflect the fair market value of the property? Yes or No

   If NO, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?

5) Property Information:
   a. Do you know the past uses of the property? Yes or No

      If yes, describe: BP Gas Station
   b. Do you know of specific chemicals present or previously used at the property? Yes or No

If yes, describe:_____

c. Do you know of spills or other releases that have taken place at the property? Yes or No

If yes, describe:_____

d. Do you know of any environmental cleanups that have occurred at the property? Yes or No

If yes, describe:

6) Based on your knowledge and experience related to the property, are there any obvious indicators that point to the presence or likely presence of releases at the property? Yes or No

If yes, describe:_____

Optional Questions (not required for landowner liability protections):

7) Why is the Phase I ESA being performed?

_____

_____

8) What is the proposed usage of the subject property?

_____

9) What type of property transaction is occurring?

_____

APPENDIX B
Health and Safety Plan

HALEY & ALDRICH, INC.
SITE-SPECIFIC SAFETY PLAN

FOR

4001 4th Avenue Redevelopment Site

4001 4th Avenue, Brooklyn, NY

Project/File No. 0210815

Prepared By: Hailey Russell	**Date: 8/19/2025**
Approvals: The following signatures constitute approval of this Health & Safety Plan.	
Insert Field Safety Managers electronic signature.	
Field Safety Manager: Choose an item.	**Date:** Click or tap to enter a date.
Project Manager: Paul Probasco	**Date: 8/21/2025**
HASP Valid Through: 8/31/2026	

Table of Contents

Page

STOP WORK AUTHORITY **I**

ISSUANCE AND COMPLIANCE **II**

EMERGENCY EVENT PROCEDURES **III**

PROJECT INFORMATION AND CONTACTS **IV**

DIRECTIONS TO THE NEAREST HOSPITAL **V**

DIRECTIONS TO THE NEAREST URGENT CARE **VII**

1. WORK SCOPE **8**

Project Task Breakdown 8
Subcontractor(s) Tasks 8

2. SITE OVERVIEW / DESCRIPTION **9**

Site Classification 9
Site Description 9
Background and Historic Site Usage 9
Site Status 9
Site Plan 9
Work Areas 9

3. HAZARD ASSESSMENT **11**

Site Chemical Hazards 11
Site Hazards Checklist 12
Weather 12
High Winds 13
Biological 14
Location/Terrain 17
Miscellaneous 19
Task Hazard Summary 21
Summary of Physical Hazards & Controls 26

4. PROTECTIVE MEASURES **35**

Required Safety & Personal Protective Equipment 35

5. TRAINING REQUIREMENTS **36**

Site Specific Training Requirements 36
Task Specific Training Requirements 36

6. AIR MONITORING PLAN AND EQUIPMENT **37**

Air Monitoring/Screening Equipment Requirements 37
Personal Exposure Monitoring 37
Monitoring Plans 37

7. DECONTAMINATION & DISPOSAL METHODS **39**

Personal Hygiene Safeguards 39

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

Decontamination Supplies 39
Location of Decontamination Station 39
Standard Personal Decontamination Procedures 40
Disposal Methods 41
Disposal of Single Use Personal Protective Equipment 41

8. SITE CONTROL 43

Communication 43
Visitors 43
Zoning 43

9. SITE SPECIFIC EMERGENCY RESPONSE PLAN 44

Pre-Emergency Planning 44
Onsite Emergency Response Equipment 44
EVACUATION ALARM 45
EVACUATION ROUTES 45
EVACUATION MUSTER POINT(S)/ SHELTER AREA(S) 45
EVACUTION RESPONSE DRILLS 45
Emergency Type 46
Notification 46
Response Action 46
Evacuation Plan/Route 46

10. HASP ACKNOWLEDGEMENT FORM 47

Attachments

Attachment A	HASP Amendment Form
Attachment B	Training Requirements
Attachment C	Roles and Responsibilities
Attachment D	Job Safety Analyses
Attachment E	Project Site Forms
Attachment F	Site-Specific Operating Procedures

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

STOP WORK AUTHORITY

In accordance with Haley & Aldrich (Haley & Aldrich) Stop Work Authority Operating Procedure (OP1035), any individual has the right to refuse to perform work that he or she believes to be unsafe without fear of retaliation. He or she also has the authority, obligation, and responsibility to stop others from working in an unsafe manner.

STOP Work Authority is the stop work policy for all personnel and subcontractors on the Site. When work has been stopped due to an unsafe condition, Haley & Aldrich site management (e.g., Project Manager [PM], Site Health & Safety Officer [SHSO], etc.) and the Haley & Aldrich Senior Project Manager (SPM) will be notified immediately.

Reasons for issuing a stop work order include, but are not limited to:

- The belief/perception that injury to personnel or accident causing significant damage to property or equipment is imminent.
- A Haley & Aldrich subcontractor is in breach of site safety requirements and/or their own site HASP.
- Identifying a substandard condition (e.g., severe weather) or activity that creates an unacceptable safety risk as determined by a qualified person.

Work will not resume until the unsafe act has been stopped OR sufficient safety precautions have been taken to remove or mitigate the risk to an acceptable degree. Stop work orders will be documented as part of an on-site stop work log, on daily field reports to include the activity/activities stopped, the duration, person stopping work, person in-charge of stopped activity/activities, and the corrective action agreed to and/or taken. Once work has been stopped, only the Haley & Aldrich SPM or SHSO can give the order to resume work. Haley & Aldrich senior management is committed to support anyone who exercises his or her “Stop Work” authority.

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

ISSUANCE AND COMPLIANCE

This HASP has been prepared in accordance with Occupational Safety and Health Administration (OSHA) regulations (CFR 29, Parts 1904, 1910, and 1926) if such are applicable.

The specific requirements of this HASP include precautions for hazards that exist during this project and may be revised as new information is received or as site conditions change.

- This HASP must be signed by all Haley & Aldrich personnel involved in implementation of the SOW (Section 2 of this HASP).
- This HASP, or a current signed copy, must be retained at all times when Haley & Aldrich staff are present.
- Revisions to this HASP must be outlined within the contents of the HASP. If immediate or minor changes are necessary, the Field Safety Manager (FSM), Haley & Aldrich, SSO and/or Project Manager (PM) may use Attachment 1 (HASP Amendment Form), presented at the end of this HASP. Any revision to the HASP requires employees and subcontractors to be informed of the changes so that they understand the requirements of the change.
- Deviations from this HASP are permitted with approval from the Haley & Aldrich FSM, PM, or Senior Health & Safety Manager (SHSM). Unauthorized deviations may constitute a violation of Haley & Aldrich company procedures/policies and may result in disciplinary action.
- This HASP will be relied upon by Haley & Aldrich's subcontractors and visitors to the site. Haley & Aldrich's subcontractors must have their own HASP which will address hazards specific to their trade that is not included in this HASP. This HASP will be made available for review to Haley & Aldrich's subcontractors and other interested parties (e.g. Facility personnel and regulatory agencies) to ensure that Haley & Aldrich has properly informed our subcontractors and others of the potential hazards associated with the implementation of the SOW to the extent that Haley &Aldrich is aware.

This site-specific HASP provides only site-specific descriptions and work procedures. General safety and health compliance programs in support of this HASP (e.g., injury reporting, medical surveillance, personal protective equipment (PPE) selection, etc.) are described in detail in the Haley &Aldrich Corporate Health and Safety Program Manual and within Haley & Aldrich's Standard Operating Procedures Both the manual and SOPs can be located on the Haley & Aldrich's Company Intranet. When appropriate, users of this HASP should always refer to these resources and incorporate to the extent possible. The manual and SOPs are available to clients and regulators upon request.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

EMERGENCY EVENT PROCEDURES

1 - ASSESS THE SCENE

- **STOP WORK**
- Review the situation and ascertain if it's safe to enter the area.
- Evacuate the site if the conditions are unsafe.

2 - EVALUATE THE EMERGENCY

- **Call 911, or designated emergency number, if required.**
- **Provide first aid for the victim if qualified and safe to do so.**
  - First aid will be addressed using the onsite first aid kit. *
    - If providing first aid, remember to use proper first aid universal precautions if blood or bodily fluids are present.
- **If exposure to hazardous substance is suspected, immediately vacate the contaminated area.**
  - Remove any contaminated clothing and/or equipment.
  - Wash any affected dermal/ocular area(s) with water for at least 15 minutes.
  - Seek immediate medical assistance if any exposure symptoms are present.

** Note: Haley & Aldrich employees are not required or expected to administer first aid / CPR to any Haley & Aldrich staff member, Contractor, or Civilian personnel at any time; it is Haley & Aldrich´s position that those who do are doing so on their own behalf and not as a function of their job.*

3 - SECURE THE AREA

- **Cordon off the incident area, if possible.**
  - Notify any security personnel, if required.
  - Escort all non-essential personnel out of the area, if able.

4 - REPORT ON-SITE ACCIDENTS / INCIDENTS TO PM / SSO

- **Notify the PM and SSO as soon as it is safe to do so.**
  - Assist PM and SSO in completing any additional tasks, as required.

5 - INVESTIGATE / REPORT THE INCIDENT

- **Record details of the incident for input to the Haley and Aldrich H&S Reporting Tool.**
  - Complete any additional forms as requested by the PM and SSO.

6 - TAKE CORRECTIVE ACTION

- **Implement corrective actions per the PM following root cause analysis.**
  - Complete Lessons Learned form.


Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

PROJECT INFORMATION AND CONTACTS	
Project Name: 4001 4th Avenue Redevelopment Site	**Haley & Aldrich File No.:** 0210815
Location: 4001 4th Avenue, Brooklyn NY	
Client/Site Contact: Phone Number:	4 Ave Property LLC Ari Schwartz 718.408.8778
Haley & Aldrich Field Representative: Phone Number: Emergency Phone Number:	Zavier Richards 929.696.2279 332.236.9927
Haley & Aldrich Project Manager: Phone Number: Emergency Phone Number:	**Paul Probasco** 914.504.2554 646.530.4184
Field Safety Manager: Phone Number: Emergency Phone Number:	Brian Ferguson 617.886.7439 617.908.2761
Subcontractor Project Manager: Phone Number:	NA NA
Nearest Hospital: Address: (see map on next page) Phone Number:	**NYU Langone Hospital – Brooklyn – Emergency Department** 5500 2nd Ave, Brooklyn, NY 11200 Brooklyn, NY 11220 718.630.7185
Nearest Occ. Health Clinic: http://www.talispoint.com/liberty/ext/ Address: (see map on next page) Phone Number:	Call Work Care 888.449.7787
Liberty Mutual Claim Policy:	**WC6Z11254100035**
Emergency Response Number:	**911**
Other Local Emergency Response Number:	N/A
Other Ambulance, Fire, Police, or Environmental Emergency Resources:	911

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

DIRECTIONS TO THE NEAREST HOSPITAL

Liberty Mutual Medical Location Directory



Directions to the Nearest Hospital:

Head toward 40th St on 4th Ave. Go for 79 ft.

Then 0.01 miles

Turn right onto 40th St. Go for 0.1 mi.

Then 0.1 miles

Turn right onto 5th Ave. Go for 256 ft.

Then 0.05 miles

Turn right onto 41st St. Go for 0.3 mi.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Then 0.3 miles

Turn left onto 3rd Ave. Go for 0.6 mi.

Then 0.6 miles

Keep right onto 3rd Ave. Go for 262 ft.

Then 0.05 miles

Turn right onto 55th St. Go for 0.1 mi.

Then 0.1 miles

Turn left onto 2nd Ave. Go for 98 ft.

Then 0.02 miles

NYU Langone Hospital Brooklyn
150 55th St, Brooklyn, NY 11220-2508

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

DIRECTIONS TO THE NEAREST URGENT CARE

Liberty Mutual Medical Location Directory

Paste map and directions showing route to nearest hospital here.

Call Work Care for guidance to nearest Occupational Health Clinic 888-449-7787

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

1. WORK SCOPE

This Site-Specific Health and Safety Plan addresses the health and safety practices and procedures that will be exercised by all Haley & Aldrich employees participating in all work on the Project Site. This plan is based on an assessment of the site-specific health and safety risks available to Haley & Aldrich and Haley & Aldrich's experience with other similar project sites. The scope of work includes the following:

Remedial Oversight (including excavation, UST removal, sub-slab depressurization system [SSDS] installation, soil vapor extraction [SVE] system installation, cutoff wall installation), Soil Sampling, and Soil Vapor/Groundwater Sampling (if needed)

Project Task Breakdown

Task No.	Task Description	Employee(s) Assigned	Work Date(s) or Duration
1	Remedial Oversight – Excavation, UST Removal, SSDS Installation, SVE System Installation, Cutoff Wall Installation	Zavier Richards	5 months
2	Soil Sampling	Zavier Richards	5 months
3	Soil Vapor / Groundwater Sampling (if needed)	Zavier Richards	5 months (if needed)

Subcontractor(s) Tasks

Firm Name	Work Activity	Work Date(s) or Duration
N/A	N/A	N/A

Projected Start Date: 10/1/2025

Projected Completion Date: 3/1/2026

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

2. SITE OVERVIEW / DESCRIPTION

Site Classification

Commercial

Site Description

The Site is located in the Sunset Park neighborhood of Brooklyn and is identified as Block 714, Lot 6 on the New York City tax map. The Site is approximately 10,017 square feet (sq ft) (0.23 acres) and was previously improved with a one-story structure formerly utilized as a convenience store, located in the eastern portion of the Site; an overhead canopy from the former gasoline filling station operations in the central portion of the Site; four 4,000-gal USTs, containing gasoline/ethanol or diesel and associated fill ports, located to the southwest of the overhead canopy; and paved parking areas. The previous Site features have been demolished and the former retail petroleum station operations ceased in December 2024. The Site is bound by 40th Street followed by mixed-use commercial and residential buildings to the north, a commercial car wash and auto repair to the south, residential apartment buildings to the east, and 4th Avenue followed by Intermediate School (I.S.) 136 to the west.

Background and Historic Site Usage

Based on the findings of the March 2024 Phase I ESA prepared by Lesova Environmental Group (LEG), the Site was comprised of one tax lot developed with a one-story concrete structure and a gasoline filling/auto service station with one (1) UST circa 1926 and a second lot which was vacant. The 1942 Sanborn map depicted the Site merged as one (1) lot with previous use similar to the 1926 map with a garage to the south of the lot. The Site was operated as an automotive service station, lubrication, minor repair, and office use with parking area until at least August 1965. The configuration of Site changed and was identified with a cement brick one-story construction with a gasoline filling station circa 1970. A historical City Directory search indicated that the Site was previously operated as a gasoline filling station and auto service station.

Site Status

Indicate current activity status and describe operations at the site:

Inactive

The Site is currently vacant.

Site Plan

Is a site plan or sketch available? Yes


Work Areas

List and identify each specific work areas(s) on the job site and indicate its location(s) on the site plan:

Entire site

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Site Plan



Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

3. HAZARD ASSESSMENT

Indicate all hazards that may be present at the site and for each task. If any of these potential hazards are checked, it is the Project Manager's responsibility to determine how to eliminate / minimize the hazard to protect onsite personnel.

Site Chemical Hazards

Is this Site impacted with chemical contamination? Yes

Source of information about contaminants: Previous Investigation

Contaminant of Concern	Location/Media	Concentration	Units
1,2,4-Trimethylbenzene	**Soil**	**1,200**	**mg/kg**
Benzene	**Soil**	**20**	**mg/kg**
Ethylbenzene	**Soil**	**1,100**	**mg/kg**
Naphthalene	**Soil**	**89**	**mg/kg**
Xylenes	**Soil**	**2,300**	**mg/kg**
Toluene	**Soil**	**1,500**	**mg/kg**
BTEX/VOCs	**Groundwater**	**40,200**	**ug/L**
1,2,4-Trimethylbenzene	**Groundwater**	**790**	**ug/L**
Naphthalene	**Groundwater**	**160**	**ug/L**

VOCs: include all organic compounds (substances made up of predominantly carbon and hydrogen) with boiling temperatures in the range of 50-260 degrees C, excluding pesticides. This means that they are likely to be present as a vapor or gas in normal ambient temperatures. Substances which are included in the VOC category include aliphatic hydrocarbons (such as hexane), aldehydes, aromatic hydrocarbons (such as benzene, toluene, and the xylenes or BTEX), and oxygenated compounds (such as acetone and similar ketones). The term VOC often is used in a legal or regulatory context and in such cases the precise definition is a matter of law.

VOCs are released from oil and gasoline refining, storage and combustion as well as from a wide range of industrial processes. Processes involving fuels, solvents, paints or the use of chemicals are the most significant sources. VOCs may also be emitted from cleaning products, degreasing products, fabrics, carpets, plastic products, glues, printed material, varnishes, wax, disinfectants, and cosmetics.

Typically, VOCs are present in gas or vapor and will enter the body by breathing contaminated air. Higher concentrations of VOCs may occur in areas of poor ventilation.

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

1,2,4-Trimethylbenzene: is a colorless liquid chemical with a strong, pleasant scent. 1,2,4-trimethylbenzene is a major part of what is known in the petroleum industry as the 'C9 fraction.' Oil refineries produce large amounts of C9 fraction each year for use as a gasoline additive.

BTEX/VOCs: BTEX is an acronym for benzene, toluene, ethylbenzene and xylenes. These compounds are VOCs, are common in petroleum-related products (e.g., oil, gasoline, coal-tar DNAPL, etc.), and frequently co-occur at hazardous waste sites. Benzene, toluene, ethylbenzene, and xylenes have acute and chronic harmful effects on the central nervous system. Benzene is classified as a carcinogen. Short-term health effects of low-level BTEX exposure include drowsiness, dizziness, accelerated heart rate, headaches, tremors, confusion, and unconsciousness.

Naphthalene: is a colorless or white/brown solid in flake or cake form, with mothball odor. Commonly found in coal tar, gasoline, or diesel fuels. Used to make mothballs and lubricants. This is a carcinogen and should be handled with extreme caution. Is a combustible solid and when heated is a dangerous fire hazard. Finely dispersed particles can form explosive mixtures. Absorption will cause irritation or burning to skin or eyes. Inhalation will cause irritation to nose and throat. High exposures will lead to headache, fatigue, tremors, and nausea. May also cause damage to liver and kidneys. The PEL 10 ppm averaged over an 8 hour shift.

Xylenes: are colorless liquids with a faint, sweet odor. There are three forms of xylene (meta-, ortho-, and para-), which are referred to as isomers. They are chemically classified as hydrocarbons, meaning they contain hydrogen and carbon atoms. These are chemicals of serious flammability and will easily ignite with heat, sparks or flames. Their flash point range is between 85-115 degrees F. The PEL is 10 ppm averaged over an 8 hour shift.

Typically, these are solvents in making paint, adhesives, and other chemicals. Their odor threshold varies greatly, and this should not be the sole indicator in exposures. Their vapors are heavier than air, but less dense than water, therefore they float. Can be inhaled or absorbed through the skin. Inhalation can irritate throat and nose and cause coughing, headache or dizziness. Absorption can cause skin rash, dryness or redness. Repeated exposures may affect concentration, memory, vision, and muscle coordination.

Site Hazards Checklist			
Weather			
Hot Temperatures	Cold Temperatures	High Winds	Lightning Storms

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Hot Temperatures

Heat stress may occur at any time work is being performed at elevated ambient temperatures. Because heat stress is one of the most common and potentially serious illnesses associated with outdoor work during hot seasons, regular monitoring and other preventative measures are vital. Site workers must learn to recognize and treat the various forms of heat stress. The best approach is preventative heat stress management.

H&A employees and their subcontractors should be aware of potential health effects and/or physical hazards of working when there are hot temperatures or a high heat index. Refer OP1015-Heat Stress for a discussion on hot weather hazards.

Cold Temperatures

Cold stress may occur at any time work is being performed at low ambient temperatures and high velocity winds. Because cold stress is common and has potentially serious illnesses associated with outdoor work during cold seasons, regular monitoring and other preventative measures are vital.

Refer to OP1003-Cold Stress for additional information and mitigation controls.

High Winds

While high winds are commonly associated with severe thunderstorms and hurricanes they may also occur as a result of differences in air pressures, such as when a cold front passes across the area. They can cause downed trees and power lines, and flying debris (such as dust or larger debris), which adds additional risks and could lead to power outages, transportation disruptions, damage to buildings and vehicles, and serious injury.

Wind Advisory are issued for sustained winds 25 to 39 mph and/or gusts to 57 mph. High Wind warnings are issued by the National Weather Service when high wind speeds may pose a hazard or is life threatening. The criteria for this warning will varies by state. The Beaufort Wind Scale is a helpful tool to when dealing with high winds.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Lightning Storms

Where the threat of electrical storms and the hazard of lightning exist staff shall ensure site procedures exist to: (1) detect when lightning is in the near vicinity and when there is a potential for lightning and (2) to notify appropriate site personnel of these conditions and (3) implement protocols to stop work and seek shelter.

The 30-30 Rule states that if time between seeing the lightning and hearing the thunder is less than 30 seconds, you are in danger and must seek shelter. You must also stay indoors for more than 30 minutes after hearing the last clap of thunder.

Biological			
Mosquitoes	Stinging Insects	Large/Small Mammals	Wildlife Droppings

Mosquitos

Work outdoors with temperatures above freezing will likely bring staff into contact with mosquitos. There are a variety of mosquito species that can transmit a range of diseases. Birds act as reservoirs for the viruses that can be collected by the mosquito and transmitted to a person. Majority of mosquitos are mainly a nuisance but staff need to take appropriate precautions to minimize the potential transmission of a virus that can result in one of the following diseases: West Nile, Eastern Equine Encephalitides and Western Encephalitides. Knowing some key steps that can minimize the risk of mosquito bites is, therefore, important in reducing the risks. Workers working outdoors should be aware that the use of PPE techniques is essential to preventing mosquito bites especially when working at sites where mosquitoes may be active and biting.

Use repellents containing DEET, picaridin, IR3535, and some oil of lemon eucalyptus and para-menthane-diol products provide longer-lasting protection. To optimize safety and effectiveness, repellents should be used according to the label instructions. Cover as much of your skin as possible by wearing shirts with long-sleeves, long pants, and socks whenever possible. Avoid use of perfumes and colognes when working outdoors during peak times when mosquitoes may be active; mosquitoes may be more attracted to individuals wearing perfumes and colognes.

Stinging Insects

Stinging Insects fall into two major groups: Apidae (honeybees and bumblebees) and vespids (wasps, yellow jackets, and hornets). Apidae are docile and usually do not sting unless provoked. The stinger of the honeybee has multiple barbs, which usually detach after a sting. Vespids have few barbs and can inflict multiple stings.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

There are several kinds of stinging insects that might be encountered on the project site. Most stings will only result in a temporary injury. However, sometimes the effects can be more severe, even life-threatening depending on where you are stung and what allergies you have. Being stung in the throat area of the neck may cause edema (swelling caused by fluid build-up in the tissues) around the throat and may make breathing difficult.

In rare cases, a severe allergic reaction can occur. This can cause "anaphylaxis" or anaphylactic shock with symptoms appearing immediately or up to 30 minutes later. Symptoms include; Hives, itching and swelling in areas other than the sting site, swollen eyes/eyelids, wheezing, chest tightness, difficulty breathing, hoarse voice, swelling of the tongue, dizziness or sharp drop in blood pressure, shock, unconsciousness or cardiac arrest. Reactions can occur the first time you are stung or with subsequent stings. If you see any signs of reaction, or are unsure, call or have a co-worker call emergency medical services (e.g., 911) right away. Get medical help for stings near the eyes, nose or throat. Stay with the person who has been stung to monitor their reaction.

Staff who are allergic to bee stings are encouraged to inform their staff/project manager. If staff member carries an Epi-pen (i.e., epinephrine autoinjector) they are encouraged to inform their colleagues in case they are stung and are incapable of administering the injection. Examine site for any signs of activity or a hive/nest. If you see several insects flying around, see if they are entering/exiting from the same place. Most will not sting unless startled or attacked. Do not swat, let insects fly away on their own. If you must, walk away slowly or gently "blow" them away. If a nest is disturbed and you hear "wild" buzzing, protect your face with your hands and run from the area immediately. Wear long sleeves, long pants, and closed-toed boots. Wear light colored clothes such as khakis. Avoid brightly colored, patterned, or black clothing. Tie back long hair to avoid bees or wasps from entanglement. Do not wear perfumes, colognes or scented soaps as they contain fragrances that are attractive. If bee or wasp is found in your car, stop and leave windows open.

Small Mammals

Rodents, are the most abundant order of mammals. There are hundreds of species of rats; the most common are the black and brown rat. Other rodents you may encounter are mice, beavers, squirrels, guinea pigs, capybaras and coypu.

The Brown Rat has small ears, blunt nose, and short hair. It is approximately 14-18” long (with tail). They frequently infest garbage/rubbish, slaughterhouses, domestic dwellings, warehouses, and supermarkets. They also frequent any space with an easy meal and potential nesting sites. The Black Rat is identified by its tail, that is always longer than the length from the head to the body. It is also slimmer and more agile than the Brown rat. Its size varies according to its environment and food supply.

The House Mouse has the amazing ability to adapt and can frequently be found in human dwellings. In buildings, mice will live anywhere and difficult to keep out. Mice are omnivorous, they will eat anything. Rats and mice often become a serious problem in cold winter months when they seek food and warmth inside buildings. They may suddenly appear in large numbers when excavation work disturbs their in-ground nesting locations or their food source is changed.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Some major problems caused by rats and mice are contaminating the food they eat with urine and excrement. Gnawing into materials such as paper, wood, or upholstery, to use as nest material. Also gnawing plastic, cement, soft metals such as lead and aluminum, and wiring, which may cause a fire hazard. Occasionally biting people and may kill small animals. They, or the parasites they carry, like fleas, mites and worms, spread many diseases such as salmonella, trichinosis, rat bite fever, hantavirus, Weil's disease, and bubonic plague. They damage ornamental plants by burrowing among the roots or feeding on new growth. They also eat garden vegetables, such as corn and squash. These rodents have been a problem for centuries, because of their incredible ability to survive and are so difficult to eliminate. In addition, they are extremely compatible with human behavior and needs.

Avoid contact with rodents, if possible. Avoid contact with rodent excrement. Do not eat food or water that may have encountered rodent excrement. If exposed, wash hands and avoid touching your face with your hands.

Large Mammals

When working in remote locations staff may come near wild or stray dogs, coyotes, foxes or other large animals. It is important that staff avoid contact with these animals.

There are increasing reports of wild dog attacks on household pets, attacks on human are uncommon and rare or infrequent at best. However, attacks by individual or small groups of domestic dogs occur frequently resulting in injury or a fatality on rare occasion. Wild dogs may become skilled at hunting in groups for small game and large game from rabbits and hares to deer and moose. The impact of wild dogs, on livestock and wildlife, varies by location and is influenced by factors such as availability of other food, number of dogs, and competition by other predators. Wild dogs kill house cats and may injure or kill domestic dogs. Areas where people have not hunted and trapped wild dogs, a fear of humans may not have developed and in such dogs may attack people and children. This can be a serious problem in areas where feral dogs feed at and live around garbage dumps near human dwellings. Such situations occur most frequently around small remote towns. In urban settings domestic dogs can be territorial and exhibit aggressive behavior such as barking and snarling when their area is encroached. It is not uncommon for domestic dogs to travel in small packs.

If the pack displays aggressive behavior and charges do not run or turn your back. When confronted by one or more dog it is important not to run or exhibit any behavior that may be construed as a challenge (e.g., looking the dog in the eyes, showing your teeth, or attempting to pet the dog).Stand still and place your work bag between you and the dog and then begin to move slowly away from the dog(s) while not turning your back. If you see a stray dog approaching from a distance, look for a place that's secure. Step inside a fenced area, enter a place of business, or knock on a neighbor's door. It is always better to be safe than risk a potentially dangerous situation.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Wildlife Droppings

Project sites involving abandoned buildings may bring staff into contact with animal droppings. There are many diseases that one can be exposed to from a variety of animals.

Mice and Rats
Hantavirus is transmitted to humans from dried droppings, urine, or saliva of mice and rats. The disease begins as a flu-like illness with fever, chills, and muscle aches, but can rapidly progress to a life-threatening condition marked by respiratory failure as fluids fill the lungs. Persons working in infested buildings are at increased risk to this disease, particularly during dusty clean-up activities.

Birds and Bats
Large populations of roosting birds may present a disease risk. The most serious health risks arise from disease organisms that grow in the nutrient-rich accumulations of bird droppings, feathers and debris under a roost, particularly if roosts have been active for years.

Histoplasmosis and Cryptococcosis are the most common fungal diseases associated with bird and bat dropping. Infection occurs when spores, carried by the air, are inhaled, especially after a roost has been disturbed. The active and inactive roosts of blackbirds, starlings and cowbirds have also been found to be heavily contaminated with fungus spores. Most infections are mild and produce either no symptoms or a minor influenza-like illness. Occasionally the disease can cause high fever, blood abnormalities, pneumonia and even death.

Do not touch droppings with unprotected hands. Avoid disturbing the droppings and generating dust. Employee work practices and dust control measures that eliminate or reduce dust generation during removal of manure from a building will also reduce risks of infection and development of disease. Use an industrial vacuum cleaner with a high-efficiency (HEPA) filter to bag contaminated material.

Location/Terrain			
Slip/Trip/Falls	SIMOPS	Economically Depressed	Choose an item.

Slips, Trips & Falls

Slip and trip injuries are the most frequent injuries to workers. Statistics show most falls happen on the same level resulting from slips and trips. Both slips and trips result from unintended or unexpected change in the contact between the feet and the ground or walking surface. Good housekeeping, quality of walking surfaces (flooring), awareness of surroundings, selection of proper footwear, and appropriate pace of walking are critical for preventing fall accidents.

Site workers will be walking on a variety of irregular surfaces, that may affect their balance. Extra care

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

must be taken to walk cautiously near rivers because the bottom of the riverbed maybe slick and may not be visible. Rocks, gradient changes, sandy bottoms, and debris may be present but not observable.

Take your time and pay attention to where you are going. Adjust your stride to a pace that is suitable for the walking surface and the tasks you are doing. Check the work area to identify hazards - beware of trip hazards such as wet floors, slippery floors, and uneven surfaces or terrain. Establish and utilize a pathway free of slip and trip hazards. Choose a safer walking route. Carry loads you can see over. Keep work areas clean and free of clutter. Communicate hazards to on-site personnel and remove hazards as appropriate.

SIMOPS

SIMOPS are described as the potential class of activities which could bring about an undesired event or set of circumstances, e.g., safety, environment, damage to assets, schedule, commercial, financial, etc. SIMOPS are defined as performing two or more operations concurrently.

SIMOPS should be identified at an early stage before operations commence to understand issues such as schedule and physical clashes, maintenance activities, failure impacts, interferences between vessels, contracts and third part interfaces and environmental impacts.

Coordinate project with site activities. Identify and understand the hazards associated with the host and client's activities. Integrate site emergency response protocols where appropriate and communicate to all project staff. Integrate site communication protocols and communicate to all project staff.

Economically Depressed Areas

Economically depressed areas may have high crime rates. Projects involving work in and around inactive industrial sites may bring staff into contact with indigent and homeless persons. Staff could be subjected to crime that includes but may not be limited to thievery, vandalism, and violence. Prior to the start of work staff need to understand the work locations and the potential for exposure to low level crime.

Staff members should never work alone in these areas. A buddy system is required. Conduct during daylight hours. Secure equipment and vehicles. If warranted, contact the local police department for a security detail. Leave the work area immediately and contact the local authorities if staff members feel threatened or are threatened.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Miscellaneous			
Extended Shift	Night Work	Choose an item.	Choose an item.

Extended Shift

An extended shift can include extending a workday beyond eight hours. Extended or unusual work shifts may be more stressful physically, mentally, and emotionally. Non-traditional shifts and extended work hours may disrupt the body's regular schedule, leading to increased fatigue, stress, and lack of concentration. This leads to an increased risk of operator error, injuries and/or accidents. The degree to which an individual is exposed to fatigue risk factors depends upon the work schedule. As both the duration of the workday and the number of days worked increase so does the fatigue risk factors. Staff Managers need to be aware of the fatigue risk factors and ensure projects are structured to mitigate these factors. Staff Members also have a responsibility to manage the personal fatigue risk factors that they can control outside of work (e.g, duration and quality of sleep, diet, drugs, and alcohol)

Fatigue is a message to the body to rest and can be eliminated with proper rest. However, if rest is not possible, fatigue can increase and becomes distressing and eventually debilitating. Fatigue symptoms, both mental and physical, vary and depend on the person and degree of overexertion. Examples include: weariness, sleepiness, irritability, reduced alertness, lack of memory, concentration and motivation, increased susceptibility to illness, depression, headache, loss of appetite, and digestive problems.

When possible, managers should limit use of extended shifts and increase the number of days worked. Working shifts longer than 8 hours generally result in reduced productivity and alertness. Additional breaks and meals should be provided when working extended shift periods. Tasks requiring heavy physical labor or intense concentration should be performed at the beginning of the shift if possible. This is an important consideration for pre-emergency planning.

Make efforts, when feasible, to ensure that unavoidable extended work shifts and shift changes allow affected employees time for adequate rest and recovery. Project Managers need to plan to have an adequate number of personnel available to enable workers to take breaks, eat meals, relax, and sleep.

Plan for regular and frequent breaks throughout the work shift. If at remote sites, ensure if possible, that there is a quiet, secluded area designated for rest and recuperation. In addition to formal breaks such as lunch or dinner, encourage use of micro breaks to change positions, move about, and shift concentration. Personnel should look to obtain an adequate quantity and quality of sleep.

Night Work

The way work is planned and scheduled can increase the risk of fatigue. Scheduling work in a way that fails to allow staff members enough time for travel to and from work and/or allow for sufficient time for sleep can cause fatigue. Working at times when staff members are biologically programmed to

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

sleep and working for long periods of time can also produce fatigue. Working night shift, including the number of consecutive nights can be a significant fatigue risk factor if not managed properly.

Night shifts may be more stressful physically, mentally, and emotionally. They can disrupt the body's regular schedule, leading to increased fatigue, stress, and lack of concentration. These effects lead to an increased risk of operator error, injuries and/or accidents. The degree which an individual is exposed to fatigue risk factors depends upon the work schedule. As both the duration of the workday and number of days worked increase so does the exposure to fatigue risk factors. Staff Managers need to be aware of the fatigue risk factors and ensure projects are structured to mitigate these risk factors.

Employers must ensure that employees are not exposed to hazardous chemicals or other agents in excess of health standards. Working extended shifts may involve prolonged exposures to hazards which exceed established standards. Employers should implement measures to monitor and limit exposures. Controls may include limiting time employees may remain at the project site; having clean locations for employee rest areas; or rest areas located sufficiently up wind of contaminated sites.

Minimize or redesign routine administrative tasks to ensure staff members can focus on core duties during their night work. Limit consecutive night shifts worked. If a project requiring staff to work beyond four nights requires a fatigue management plan. Ensure that rosters allow for at least two full night's sleep after the last night shift before returning to day shift. Regular and frequent breaks are needed. Comprehensive training on fatigue risk factors for the staff members assigned to the project. Optimal sleeping conditions during the day (e.g., dark/quiet rooms, minimize distractions, light meal prior to sleep).

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Task Hazard Summary

Task 1 – Excavation/Trenching (Remedial Oversight)

There are multiple hazards associated with working in and around excavations and trenches including cave-ins, potential running soils, dislodged excavated soils, lack of proper access and egress. Nonfatal, and even fatal, injuries may occur in association with excavation and trenching activities with a greater frequency than one might expect. Causes of bodily injury, illness, or death include asphyxiation, internal injuries due to physical crushing, falling objects and toxic exposures.


Excavations five (5) feet deep or greater require a protective system unless the excavation is made entirely in stable rock. If the depth is less than five (5) feet deep, a competent person may determine that a protective system is not required. Trenches 20 feet deep or greater require that the protective system be designed by a registered professional engineer or be based on tabulated data prepared and/or approved by a registered professional.

H&A Staff Members shall not enter a trench that is five feet deep or greater unless a protective system is used or the soil(s) have been characterized and benched and/or sloped appropriately.

The following are list identifies the types of protective measures that can be used in the event a staff member is required to enter an excavation or trench.

- **Sloping** involves cutting back the trench wall at an angle inclined away from the excavation.

- **Benching** means a method of protecting workers from cave-ins by excavating the sides of an excavation to form one or a series of horizontal levels or steps, usually with vertical or near vertical surfaces between levels. Benching cannot be done in Type C soil. Below is a diagram indicating the appropriate slope angle for both sloping and benching.



- **Shoring** requires installing aluminum hydraulic or other types of supports to prevent soil movement and cave-ins.
- **Shielding** protects workers by using trench boxes or other types of supports to prevent soil cave-ins.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Designing a protective system can be complex because you must consider many factors: soil classification, depth of cut, water content of soil, changes caused by weather or climate, surcharge loads (e.g., spoil, other materials to be used in the trench) and other operations in the vicinity.

See OP 1001 Excavation and Trenching Safety for more information.

Task 1 – Stockpiling (Remedial Oversight)

Stockpiling of soils is conducted for a range of services that can include but are not limited to: building, foundation, utility excavation, drilling spoils containment and environmental cleanup. Familiarity with basic heavy construction safety is an essential component of all hauling projects. Potential hazards related to stockpiling operations include, but are not limited to encountering underground or overhead utilities, traffic and heavy equipment, and the use or unexpected encountering of toxic or hazardous substances. While staff members do not operate heavy equipment, they may work in close proximity to the equipment and may be exposed to many of the same hazards as the Contractor. Care should be taken during material stockpiling that the staff is not in the line of fire of the loading equipment (swing radius/traffic pattern). The staff should be aware of any setback requirements of stockpile surcharges near trenches and excavations.

Task 1 - Hauling Soils Off-site (Remedial Oversight)

Hauling Soils Off-site is conducted for a range of services that can include but are not limited to: building, foundation, utility excavation and environmental cleanup. Familiarity with basic heavy construction safety is an essential component of all hauling projects. Potential hazards related to hauling soils off-site operations include, but are not limited to encountering underground or overhead utilities, traffic and heavy equipment, generated waste, and the use or unexpected encountering of toxic or hazardous substances. While staff members do not operate heavy equipment, they may work in close proximity to the equipment and may be exposed to many of the same hazards as the Contractor. Care should be taken during loading of truck/container that the staff is not in the line of fire of the loading equipment (swing radius/traffic pattern) or of the falling spoils/soil from the loading bucket or truck bed. The staff should be aware at all times of subsurface stability as a truck may tip during truck loading and unloading due items such as but not limited to uneven surface, poorly or uncompacted subsurface, thawing soils, saturated soils and proximity to excavation. It is imperative that staff are aware of emergency / communication protocols with the Contractor prior to the start of work.

Task 1 – SSDS/SVE Installation (Remedial Oversight)

An active SSDS will be installed beneath the building slab and connected to the SVE system.
The SSDS will consist of a horizontal perforated piping installed in a permeable layer under the vapor barrier. The permeable layer will consist of washed aggregate, or similar permeable material. The

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

horizontal piping will consist of perforated schedule 40 PVC pipes with leader pipes connecting to the vertical risers. The vertical risers will be constructed of solid steep pipe risers and exit through the cover systems with sealed penetrations. Each riser will have a sample port assembly installed in the cellar. Potential hazards related to SSDS installation oversight include, but are not limited to: potential running soils, dislodged excavated soils, and lack of proper access and egress.

The SVE system will consist of vapor extraction points (VEP) installed in the excavated area. The VEPs will be constructed of schedule 40 PVC with 0.010-inch slot screens. Each VEP well will have a 2-inch diameter, schedule 40 PVC installed under the concrete slab. Each VEP well piping will enter the basement area through sealed penetrations in the basement concrete wall. The 2-inch diameter pipes will each have a dedicated sample port and valve prior to being plumed to a four-inch header pipe that will be connected to the SVE system. The potential hazards from SSDS installation oversight also apply to the installation of the SVE system, in addition to potential hazards from drilling operations such as encountering underground or overhead utilities, traffic and heavy equipment, hoisting heavy tools, steel impacts, open rotation entanglement, and the planned or unexpected encountering of toxic or hazardous substances. Care should be taken while entering and exiting excavations or trenches, and when assessing the SSDS/SVE installation.

Task 1 - Steel Sheeting (Remedial Oversight)

Installation of Steel sheeting is typically conducted for foundations and utility trenches. Familiarity with basic heavy construction safety is an essential component of all piles installation. Potential hazards related to steel sheeting installation include, but are not limited to encountering line of fire, underground or overhead utilities, noise, traffic and heavy equipment, and overhead work, Cranes or Lifting Equipment. While staff members do not operate heavy equipment, they will work in close proximity to the equipment and may be exposed to many of the same hazards as the Contractor. Care should be taken during unloading of piles from delivery trucks or hoisting of piles onto the rig as staff may often be in the line of fire or swing radius of the cranes. Staff should be aware at all times of all overhead hoisting operations even during pile installation. Staff should always maintain a safe distance to the pile driving rig during installation as the pile/hammer/accessories may break free of the rig due to vibration/impact. Always have an “exit strategy” in mind when working near the pile driving hammer. It is imperative that staff are aware of emergency / communication protocols with the Contractor prior to the start of work.

Task 2 – Soil Sampling

Soil sampling by H&A staff on active construction sites can be conducted in conjunction with a wide range activities such as building construction, earthwork and soil management related activities. These activities can include, but are not limited to: drill spoil characterization and management during building foundation element installation, characterization of excavated soils for management/disposal/reuse during earthwork activities, and as part of environmental remedial activities such as delineation and confirmation sampling. Familiarity with basic heavy construction safety, site conditions (geotechnical

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

and environmental), and potential soil contaminants are essential components of soil sampling performed on active sites. Potential hazards related to soil sampling at construction sites include, but are not limited to: encountering site vehicle traffic and heavy equipment operations, manual lifting, generated waste, contact or exposure to impacted soil, and encountering unknown toxic or hazardous substances. Although soil sampling is commonly performed within active excavations, from stockpiles, or within trench excavations, sampling locations and situations will vary depending on site conditions. Care should be taken while entering and exiting excavations or trenches, and when accessing (climbing up or down) soil stockpiles, ensuring that the sampling area is not being actively accessed by construction equipment. Care should also be taken with handling of potentially environmentally impacted soil during sampling, with appropriate PPE identified and used. At no time during classification activities are personnel to reach for debris near machinery that is in operation, place any samples in their mouth, or come in contact with the soils without the use of gloves. Staff will have to carry and use a variety of sampling tools, equipment, containers, and potentially heavy sample bags. It is imperative that staff are aware of emergency / communication protocols with the Contractor prior to the start of work.

Task 3 – Soil Vapor

Soil gas sampling is employed as an indirect indicator of contamination in soil or groundwater particularly over and around landfill waste sites, or groundwater plumes. Soil gas sampling points can be installed manually using a slam bar or power driven mechanical devices (e.g., demolition hammer or Geoprobe) may be used based on site conditions (i.e., pavement, frozen ground, very dense clays, etc.). Soil gas samples can be drawn through the probe itself, or through Teflon tubing inserted through the probe and attached to the probe point. Samples are collected and analyzed as described below. Other field air monitoring devices, such as the Combustible Gas Indicator (CGI) and the Organic Vapor Analyzer (OVA), can also be used, depending on specific site conditions.

Because the sample is being drawn from underground, and no contamination is introduced into the breathing zone, soil gas sampling usually occurs in Level D. Nevertheless, ambient air should be constantly monitored to obtain background and breathing zone readings during the sampling procedure in the event the seal around the sampling point is breached. As long as the levels in ambient air do not rise above background, no upgrade of the level of protection is needed. Also, an underground utility search must be performed prior to sampling.

Task 3 – Groundwater Sampling

Environmental water sampling could include activities such as groundwater sampling from permanent or temporary wells, or surface water sampling from streams, rivers, lakes, ponds, lagoons, and surface impoundments.

Sampling tasks could involve uncapping, purging (pumping water out of the well), and sampling, and/or monitoring, new or existing monitoring wells. A mechanical pump may be used to purge the wells and

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

can be hand-, gas-, or electric-operated. Water samples taken from the wells are then placed in containers and shipped to an analytical laboratory for analysis. The physical hazards of these operations are primarily associated with the collection methods and procedures used.

When sampling bodies of water containing known or suspected hazardous substances, adequate precautions must be taken to ensure the safety of sampling personnel. The sampling team member collecting the sample should not get too close to the edge, where ground failure or slips, trips or falls may cause him/her to lose his/her balance. The person performing the sampling should have fall restraint or protection for the task. When conducting sampling from a boat in an impoundment or flowing waters, appropriate vessel safety procedures should be followed. Avoid lifting heavy coolers with back muscles; instead, use ergonomic lifting techniques, team lift or mechanical lifts. Wear proper gloves, such as when handling sample containers to avoid contacting any materials that may have spilled out of the sample containers.

Inhalation and absorption of COCs are the primary routes of entry associated with water sampling, due to the manipulation of sample media and equipment, manual transfer of media into sample containers, and proximity of operations to the breathing zone. During this project, several different groundwater sampling methodologies may be used based on equipment accessibility and the types of materials to be sampled. These sampling methods may include hand or mechanical bailing. The primary hazards associated with these specific sampling procedures are not potentially serious; however, other operations in the area or the conditions under which samples must be collected may present chemical and physical hazards. The hazards directly associated with groundwater sampling procedures are generally limited to strains or sprains from hand bailing, and potential eye hazards. Exposure to water containing COCs is also possible. All tools and equipment that will be used at the site must be intrinsically safe (electronics and electrical equipment) and non-sparking or explosion-proof (hand tools).

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Potential Task Hazards	Task 1 Remedial Oversight – Excavation, UST Removal, SSDS Installation, SVE System Installation, Steel Sheeting Installation	Task 2 Soil Sampling	Task 3 Soil Vapor/ Groundwater Sampling (if needed)
Heavy Equipment	☒	☐	☐
Noise	☒	☐	☐
Slippery Surfaces	☒	☒	☒
Congested Area	☒	☒	☒
Ergonomics	☒	☒	☒
Excavation/Trenching	☒	☒	☐
Ground Disturbance	☒	☐	☐
Heavy Equipment	☒	☐	☐
Line of Fire	☒	☒	☒
Overhead Utilities	☒	☐	☐
Underground Utilities	☒	☐	☐
Sharp Objects	☒	☒	☒
Cranes-Lifting Operations	☒	☐	☐
Hand/Power Tools	☐	☒	☒
Inadequate Lighting	☒	☐	☐
Manual Lifting	☐	☒	☒
Repetitive Motion	☐	☒	☒
Other: Specify	☐	☐	☐

Summary of Physical Hazards & Controls

Heavy Equipment

Staff must be careful and alert when working around heavy equipment, failure or breakage and limited visibility can lead to accidents and worker injury. Heavy equipment such as cranes, drills, haul trucks, or other can fail during operation increasing chances of worker injury. Equipment of this nature shall be visually inspected and checked for proper working order prior to commencement of field work. Those

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

operating heavy equipment must meet all requirements to operate the equipment. Haley & Aldrich, Inc. staff that supervise projects or are associated with high risk projects that involve digging or drilling should use due diligence when working with a construction firm.

See OP1052 Heavy Equipment for additional information.

Controls

- Only approach equipment once you have confirmed contact with the operator (e.g., operator places the bucket on the ground).
- Always maintain visual contact with operators and keep out of the strike zone whenever possible.
- Always be alert to the position of the equipment around you.
- Always approach heavy equipment with an awareness of the swing radius and traffic routes of all equipment and never go beneath a hoisted load.
- Avoid fumes created by heavy equipment exhaust.

Noise

Working around heavy equipment (drill rigs, excavators, etc.) often creates excessive noise. The effects of noise include physical damage to the ear, pain, and temporary and/or permanent hearing loss. Workers can also be startled, annoyed, or distracted by noise during critical activities. Noise monitoring data that indicates that working within 25 feet of operating heavy equipment result in exposure to hazardous levels of noise (levels greater than 85 dBA).

See OP 1031 Hearing Conservation for additional information.

Controls

- Personnel are required to use hearing protection (earplugs or earmuffs) within 25 feet of any operating piece of heavy equipment.
- Limit the amount of time spent at a noise source.
- Move to a quiet area to gain relief from hazardous noise sources.
- Increase the distance from the noise source to reduce exposure.

Slippery Surfaces

Both slips and trips result from unintended or unexpected change in the contact between the feet and ground or walking surface. Good housekeeping, quality of walking surfaces, selection of proper footwear, and appropriate pace of walking are critical for preventing fall accidents. Slips happen where there is too little friction or traction between the footwear and walking surface.

Common causes of slips are wet or oily surfaces, spills, weather hazards, loose unanchored rugs or mats and flooring or other walking surfaces that do not have same degree of traction in all areas.

Weather-related slips and falls become a serious hazard as winter conditions often make for wet or icy surfaces outdoors. Even wet organic material or mud can create hazardous walking conditions. Spills and leaks can also lead to slips and falls.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Controls

- Evaluate the work area to identify any conditions that may pose a slip hazard.
- Address any spills, drips or leaks immediately.
- Mark areas where slippery conditions exist.
- Select proper footwear or enhance traction with additional PPE.
- Where conditions are uncertain or environmental conditions result in slippery surfaces walk slowly, take small steps, and slide feet on wet or slippery surfaces.

Congested Areas

Working in congested areas can expose both workers and the public to a wide range of hazards depending upon the specific activities taking place. Staff Members need to understand the work scope, work areas, equipment on-site, and internal traffic patterns to minimize or eliminate exposure potential.

Controls

- Provide barricades, fencing, warning signs/signals and adequate lighting to protect people while working in or around congested areas.
- Vehicles and heavy equipment with restricted views to the rear should have functioning back-up alarms that are audible above the surrounding noise levels. Whenever possible, use a signaler to assist heavy equipment operators and/or drivers in backing up or maneuvering in congested areas.
- Lay out traffic control patterns to eliminate excessive congestion.
- Workers in congested areas should always wear high visibility clothing.
- Be aware of Line of Fire hazards when performing work activities in congested areas.
- Hazards associated with SIMOPs should be discussed daily at Tailgate Safety Meetings.

Ergonomics

Most Work-related Musculoskeletal Disorders (WMSDs) are caused by Ergonomic Stressors. Ergonomic Stressors are caused by poor workplace practices and/or insufficient design, which may present ergonomic risk factors. These stressors include, but not limited to, repetition, force, extreme postures, static postures, quick motions, contact pressure, vibration, and cold temperatures.

WMSDs are injuries to the musculoskeletal system, which involves bones, muscles, tendons, ligaments, and other tissues in the system. Symptoms may include numbness, tightness, tingling, swelling, pain, stiffness, fatigue, and/or redness. WMSD are usually caused by one or more Ergonomic Stressors. There may be individual differences in susceptibility and symptoms among employees performing similar tasks. Any symptoms are to be taken seriously and reported immediately.

See OP1053 Ergonomics for more information.

Controls

- Ensure workstations are ergonomically correct so bad posture is not required to complete tasks.
- Take periodic breaks over the course of the day.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

- Stretch during break times.
- Break up tasks that require repetitive motion.
- Contact Corporate H&S with any ergonomic concerns

Excavation & Trenches

There are multiple hazards associated with working in and around excavations and trenches including cave-ins, potential running soils, dislodged excavated soils, lack of proper access and egress. Nonfatal, and even fatal, injuries may occur in association with excavation and trenching activities with a greater frequency than one might expect. Causes of bodily injury, illness, or death include asphyxiation, internal injuries due to physical crushing, falling objects and toxic exposures.

See OP1001 Excavation and Trenching Safety for more information.

Controls

- Do not enter an exaction unless it has been inspected and has appropriate protective measures in place: shoring, benching, or sloping.
    - Protective measures are required for excavations that are 5 feet or deeper.
- If entry is required verify with the on-site competent person that:
    - no atmospheric hazards exist or have the potential to exist
    - there is no standing water or water removal operations are in place
    - the daily inspection has occurred
    - spoil piles, equipment or other is at least 2 feet from the edge
    - There is safe access and egress to the excavation which can include ladders, steps, ramps or other safe means. The means of access and egress shall be no more than 25’ away.
- If there is any doubt about the safety of the excavation personnel will not enter the excavation or trench and will contact the PM and the Regional Safety Manager.
- Do not stand on the long side of the cut. If required ensure there are no tension cracks.

Ground Disturbance

Ground disturbance is defined as any activity disturbing the ground. Ground disturbance activities include, but are not limited to, excavating, trenching, drilling (either mechanically or by hand), digging, plowing, grading, tunneling and pounding posts or stakes.

Because of the potential hazards associated with striking an underground utility or structure, the operating procedure for underground utility clearance shall be followed prior to performing any ground disturbance activities.

See OP1020 Working Near Utilities

Controls

Prior to performing ground disturbance activities, the following requirements should be applied:

- Confirm all approvals and agreements (as applicable) either verbal or written have been obtained.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

- Request for line location has been registered with the applicable One-Call or Dial Before You Dig organization, when applicable.
    - Whenever possible, ground disturbance areas should be adequately marked or staked prior to the utility locators site visit.
- Notification to underground facility operator/owner(s) that may not be associated with any known public notification systems such as the One-Call Program regarding the intent to cause ground disturbance within the search zone.
- Notifications to landowners and/or tenant, where deemed reasonable and practicable.
- Proximity and Common Right of Way Agreements shall be checked if the line locator information is inconclusive.

Choose a building block.

Line of Fire

Line of fire refers to the path an object will travel. Examples of line of fire situations typically observed on project sites include lifting/hoisting, lines under tension, objects that can fall or roll, pressurized objects or lines, springs or stored energy, work overhead, vehicles and heavy equipment.

Controls

- Never walk under a suspended load.
- Be aware and stay clear of tensioned lines such as cable, chain and rope.
- Be cautious of torque stresses that drilling equipment and truck augers can generate. Equipment can rotate unexpectedly long after applied torque force has been stopped.
- Springs and other items can release tremendous energy if compressed and suddenly released
- Items under tension and pressure can release tremendous energy if it is suddenly released.
- Not all objects may be overhead; be especially mindful of top-heavy items and items being transported by forklift or flatbed.
- Secure objects that can roll such as tools, cylinders, and pipes.
- Stay clear of soil cuttings or soil stockpiles generated during drilling operations and excavations, be aware that chunks of soil, rocks, and debris can fall or roll.

Overhead Utilities

When work is undertaken near overhead electrical lines, the distance maintained from those lines shall also meet the minimum distances for electrical hazards as defined in Table 1 below. Note: utilities other than overhead electrical utilities need to be considered when performing work.

Table 1 Minimal Radial Clearance Distances *

Normal System Voltage Kilovolts (kV)	Required Minimal Radial Clearance Distance (feet/meters)
0 – 50	**10/3.05**

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

51 – 100	**12/3.66**
101 – 200	**15/4.57**
201 – 300	**10/6.1**
301 – 500	**25/7.62**
501 – 750	**35/10.67**
750 - 1000	**45/13.72**

* For those locations where the utility has specified more stringent safe distances, those distances shall be observed.

Controls

- To prevent damage, guy wires shall be visibly marked and work barriers or spotters provided in those areas where work is being conducted.
    - When working around guy wires, the minimum radial clearance distances for electrical power shall be observed.
- The PM shall research and determine if the local, responsible utility or client has more restrictive requirements than those stated in Table 1.
- If equipment cannot be positioned in accordance with the requirements established in Table 1 the lines need to be de-energized.

Underground Utilities

Various forms of underground/overhead utility lines or conveyance pipes may be encountered during site activities. Prior to the start of intrusive operations, utility clearance is mandated, as well as obtaining authorization from all concerned public utility department offices. Should intrusive operations cause equipment to come into contact with utility lines, the SHSO, Project Manager, and Regional H&S Manager shall be notified immediately. Work will be suspended until the client and applicable utility agency is contacted and the appropriate actions for the situation can be addressed.

See OP1020 Work Near Utilities for complete information.

Controls

- Obtain as-built drawings for the areas being investigated from the property owner;
- Visually review each proposed soil boring locations with the property owner or knowledgeable site representative;
- Perform a geophysical survey to locate utilities;
- Hire a private line locating firm to determine location of utility lines that are present at the property;
- Identifying a no-drill or dig zone;
- Hand dig or use vacuum excavation in the proposed ground disturbance locations if insufficient data is unavailable to accurately determine the location of the utility lines.

Sharp Objects

Workers who handle sharp edged objects like sheets of steel or glass are at risk of cuts. Workers who handle sharp edged objects are also at risk of cuts. Injuries may occur to hands, fingers, or legs when

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

they are in the way of the blade, when the blade slips, or if an open blade is handled unexpectedly. Other hazards at job sites include stepping on sharp objects (e.g. wooden boards with protruding nails, sharp work-tools, chisels, etc.) and colliding with sharp and/or protruding objects.

Controls
Always be alert when handling sharps. Never look away or become distracted while handling sharp objects. Use caution when working with tools; use right tool for the job. Keep tools sharp, dull blades are a safety hazard, requiring more force to make cuts which can lead to tool slippage. Wear appropriate PPE and do not handle sharp objects (i.e., broken glass) with bare hands. Use mechanical devices, when possible. Stay away from building debris; avoid handling site debris or placing your hand where you cannot see. Watch out for barbed wire and electrical fences; cover with a car mat or equivalent to cross or walk around; use the buddy system to avoid entanglement; wear gloves. Do not leave unprotected sharps unattended. Use protective shields, cases, styrofoam blocks, etc. Pass a sharp by handing it over carefully by the handle with the blade down or retracted. Fixed open blades are prohibited. Always cut away from the body, making several passes when cutting thicker materials. Make sure blades are fitted properly into the knife. Never cut items with a blade or other sharp object on your lap. Never try to catch a blade or cutting tool that is falling.

Cranes/ Lifting Equipment

Lifting operations is considered a high-risk activity and a permit to work may be required in certain situations. When performing work activities requiring cranes or lifting equipment, a hazard analysis of the lift shall be completed in line with the Lift Plan Analysis Form during the project and job phases. The two types of lifts common on projects include:

Incidental Lift
The use of equipment such as backhoes, track hoes, front-end loaders, side loaders and similar earth-moving equipment for lifting per its design. These types of lifts present many, if not more hazards than traditional critical lifts because they often do not get the same level of attention.

Critical Lift
A lift in which the dropping, upset or collision of parts, components or assemblies could present a significant risk of personal injury or property damage. A lift can also be designated as critical by the Project Manager, Lifting Subcontractor, or Client because of special circumstances or hazards. No critical lift may proceed without a *Lifting Operations Permit* signed and accepted by the Lift Leader and reviewed with the Project Manager.

See OP1049 Lifting Operations and OP 1070 Rigging Safety for additional information.

Controls
- Complete the Lift Plan Analysis Form and if required Critical Lift Permit
- Only competent operators, Lift Leaders and Riggers shall perform lifting operations.
- All personnel not involved with the lift shall be kept at no less than 3 times the length of the boom.
- Employees shall not work or walk under a suspended load.
- The Lift Leader shall consider the stability of the ground prior to each lift.
- All lifting equipment, slinging, and rigging shall be inspected and the inspection documented.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

- Suspended loads shall be attended unless physically secured to prevent unintended movement.

Lifting shall not commence:

- If the load exceeds the dynamic or static capacities of the lifting equipment.
- Unless all safety devices installed on the lifting equipment are operational.
- Unless the Lift Leader has visually examined all lifting devices and equipment prior to use.
- Unless a visual assessment of the lift has been completed, and the Lift Leader has determined the lift method and equipment are safe and ready for use.

Hand and Power Tools

Hand and power tools can expose staff to a wide range of hazards depending upon the tool used. Hazards can include but are not limited to: falling, flying, abrasive, and splashing objects, or harmful dusts, fumes, mists, vapors, or gases.

Serious accidents often occur before steps are taken to evaluate and avoid or eliminate tool-related hazards. Staff must recognize the hazards associated with the different types of tools and the safety precautions necessary to prevent those hazards.

See OP 1026 Hand and Power Tools for more information.

Controls

- Keep all tools in good condition with regular maintenance.
- Use the right tool for the job. Do not use a tool for a task which it was not designed for.
- Examine each tool for damage before use and do not use damaged tools.
- For tools that are damaged or defective, red tag the tool and take out of service.
- Operate tools per the manufacturers' instructions.
- Use the appropriate personal protective equipment.
- All electrically powered tools will be connected through a ground fault circuit interrupter (GFCI).
- All personnel must be trained on the use of the tool they are utilizing.

Inadequate Lighting

Work may be conducted during off-hours when natural light is limited or nonexistent. Reduced or inadequate lighting limits one's ability to see which may increase the risk of an accident or injury. Regulations require work that is conducted at night meet specific requirements regarding project site illumination. Staff may also find themselves working in buildings or locations where the power has been cutoff or where only emergency lighting is operational. It is important that staff have appropriate means of lighting to ensure work and access to the site is done safely.

Controls

- Nighttime project sites conducted on a roadway must have appropriate lighting consistent with the MUTCD. Contact the PM if lighting is not sufficient and poses a hazard.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

- Non roadway projects must have an appropriate level of lighting that allows work to be completed safely and effectively. Staff should bring additional means of lighting (e.g., flashlight) as a precaution when working at night or areas that require illumination for the work to be conducted safely.

Manual Lifting/Moving

Most materials associated with investigation, remedial, or construction-related activities are moved by hand. The human body is subject to damage in the forms of back injury, muscle strains, and hernia if caution is not observed in the handling process.

Controls

- Under no circumstances should any one person lift more than 49 pounds unassisted.
- Always push, not pull, the object when possible.
- Size up the load before lifting. If it is heavy or clumsy, get a mechanical aid or help from a worker.
- Bend the knees; it is the single most important aspect of lifting.
- When performing the lift:
    - Place your feet close to the object and center yourself over the load.
    - Get a good handhold.
    - Lift straight up, smoothly and let your legs do the work, not your back!
    - Avoid overreaching or stretching to pick up or set down a load.
    - Do not twist or turn your body once you have made the lift.
    - Make sure beforehand that you have a clear path to carry the load.
    - Set the load down properly.

Repetitive Motion

Repetitive Motion or Strain Injuries are injuries effecting muscles, nerves, and tendons by repetitive movement and overuse. Almost any kind of awkward or repetitive motion you make could lead to an injury over time. Actions like bending or twisting of the wrists, reaching for materials, working with your hands above shoulder level, or grasping objects can increase wear and tear on the body. The condition mostly effects the upper body.

Controls

- Arrange your work zone, supplies and tools as much as possible to avoid reaching, leaning, bending and twisting your waist or wrists.
- During rest breaks, use stretches to loosen up your body.
- Vary tasks if you can so that you are not making the same movement repeatedly over for a long period.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

4. PROTECTIVE MEASURES

The personal protective equipment and safety equipment (if listed) is specific to the associated task. The required PPE and equipment listed must be onsite during the task being performed. Work shall not commence unless the required PPE or Safety Equipment is present.

Required Safety & Personal Protective Equipment

Required Personal Protective Equipment (PPE)	**Task 1**	**Task 2**	**Task 3**	
	Remedial Oversight – Excavation, UST Removal, SSDS Installation, SVE System Installation, Steel Sheeting Installation	Soil Sampling	Soil Vapor/ Groundwater Sampling (if needed)	Enter task description.
Hard hat	☒	☒	☒	☐
Safety Glasses	☒	☒	☒	☐
Safety Toed Shoes	☒	☒	☒	☐
Class 2 Safety Vest	☒	☒	☒	☐
Hearing Protection	☒	☒	☒	☐
Nitrile Gloves	☒	☒	☒	☐
Cut Resistant Gloves	☒	☒	☒	☐
Level of protection required	D	D	D	Select
Required Safety Equipment				
First Aid Kit	☒	☒	☒	☐

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

5. TRAINING REQUIREMENTS

The table below lists the training requirements staff must have respective to their assigned tasks and that are required to access the Site.

Site Specific Training Requirements
HAZWOPER - 40 Hour (Initial)
HAZWOPER - 8 Hour (Annual Refresher)
Site Specific Orientation
SST Certification Card

Task Specific Training Requirements				
Required Training Type	**Task 1**	**Task 2**	**Task 3**	**Task 4**
	Remedial Oversight – Excavation, UST Removal, SSDS Installation, SVE System Installation, Steel Sheeting Installation	Soil Sampling	Soil Vapor/ Groundwater Sampling (if needed)	Enter task description.
HAZWOPER – 40 Hour (Initial); HAZWOPER – 8 Hour (Annual Refresher); Site-Specific Orientation; and, SST Card	☒	☒	☒	☐

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

6. AIR MONITORING PLAN AND EQUIPMENT

Exposures to airborne substances shall be fully characterized throughout project operations to ensure that exposure controls are effectively selected and modified as needed.

Is air/exposure monitoring required at this work site for personal protection? Yes

Is perimeter monitoring required for community protection? Yes

Air monitoring plan not applicable No

Air Monitoring/Screening Equipment Requirements

TSI Dusttrak II Desktop 8530 Dust/Aerosol Monitor

Photo-Ionization Detector (PID) 10.6eV

The required equipment listed above must be on site. Work shall not commence unless the equipment is present and in working order.

Dust Suppression Techniques

Preventative measures for dust generation may include wetting site fill and soil, construction of an engineered construction entrance with gravel pad, a truck wash area, covering soils with tarps, and limiting vehicle speeds to five miles per hour.

Personal Exposure Monitoring

No asbestos, lead-based paint, or radiological hazards have been identified within the vicinity of the proposed excavation area at the Site (see Section 2.0). Therefore, personal exposure monitoring is not required during excavation.

Monitoring Plans

Parameter/ Contaminant	Equipment	Action Level	Response Activity
Benzene	Benzene-Specific PID and/or Draeger Tubes	0.5 ppm	• Continue work and monitoring.
		> 0.5 ppm	• Implement engineering controls • Test for benzene with PID or colorimetric tubes. • If results are non-detect, continue monitoring every 15 minutes until concentrations return to background levels.
		≥ 1 ppm	• Contact FSM to implement PPE upgrades.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

	5 ppm for 5 minutes	• Cease work. • Contact FSM.

Zone Location and Monitoring Interval
Breathing zone and edge of Exclusion Zone.

This monitoring plan is based on Federal OSHA PELs for Benzene.

Parameter/ Contaminant	Equipment	Action Level	Response Activity
VOCs	PID 10.6 eV	< 10 ppm	Continue work and monitoring.
		>10 ppm for 5 minutes	Clear Instrument and Re-Monitor the Area. Implement PPE upgrades
		>10 ppm for >5 minutes	Evacuate the area and call the RHSM and/or PM for further guidance. Implement engineering controls.

Zone Location and Monitoring Interval
Upwind and Downwind of the Work Zone. Recorded every 15 minutes

***If chemical does not have an action level use TLV or REL, whichever is lowest, to be used as an action level. If TLV or REL are the same as PEL, cut the PEL in half for an action level.**

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

7. DECONTAMINATION & DISPOSAL METHODS

All possible and necessary steps shall be taken to reduce or minimize contact with chemicals and contaminated/impacted materials while performing field activities (e.g., avoid sitting or leaning on, walking through, dragging equipment through or over, tracking, or splashing potential or known contaminated/impacted materials.)

Personal Hygiene Safeguards

The following minimum personal hygiene safeguards shall be adhered to:

1. No smoking or tobacco products in any project work areas.
2. No eating or drinking in the exclusion zone.
3. It is required that personnel present on site wash hands before eating, smoking, taking medication, chewing gum/tobacco, using the restroom, or applying cosmetics and before leaving the site for the day.

It is recommended that personnel present on site shower or bathe at home at the end of each day of working on the site.

Decontamination Supplies

All decontamination should be conducted at the project site in designated zones or as dictated by Client requirements. Decontamination should not be performed on Haley & Aldrich owned or leased premises.

☐ Acetone	☒ Distilled Water	☐ Polyethylene Sheeting
☒ Alconox Soap	☒ Drums	☐ Pressure/Steam Cleaner
☒ Brushes	☐ Hexane	☒ Tap Water
☒ Disposal Bags	☐ Methanol	☐ Wash tubs
☒ 5 Gallon Buckets	☒ Paper Towels	☐ Other: Specify

Location of Decontamination Station

N/A

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Standard Personal Decontamination Procedures

Outer gloves and boots should be decontaminated periodically as necessary and at the end of the day. Brush off solids with a hard brush and clean with soap and water or other appropriate cleaner whenever possible. Remove inner gloves carefully by turning them inside out during removal. Wash hands and forearms frequently. It is good practice to wear work-designated clothing while on-site which can be removed as soon as possible. Non-disposable overalls and outer work clothing should be bagged onsite prior to laundering. If gross contamination is encountered on-site contact the Project Manager and Field Safety Manager to discuss proper decontamination procedures.

The steps required for decontamination will depend upon the degree and type of contamination but will generally follow the sequence below.

1. Remove and wipe clean hard hat
2. Rinse boots and gloves of gross contamination
3. Scrub boots and gloves clean
4. Rinse boots and gloves
5. Remove outer boots (if applicable)
6. Remove outer gloves (if applicable)
7. Remove Tyvek coverall (if applicable)
8. Remove respirator, wipe clean and store (if applicable)
9. Remove inner gloves (if outer gloves were used)

PPE that is not grossly contaminated can be bagged and disposed in regular trash receptacles.

Small Equipment Decontamination

Pretreatment of heavily contaminated equipment may be conducted as necessary:

1. Remove gross contamination using a brush or wiping with a paper towel
2. Soak in a solution of Alconox and water (if possible)
3. Wipe off excess contamination with a paper towel

Standard decontamination procedure:

4. Wash using a solution of Alconox and water
5. Rinse with potable water
6. Rinse with distilled/deionized water

Inspect the equipment for any remaining contamination and repeat as necessary.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Disposal Methods

Procedures for disposal of contaminated materials, decontamination waste, and single use personal protective equipment shall meet applicable client, locate, State, and Federal requirements.

Disposal of Single Use Personal Protective Equipment

PPE that is not grossly contaminated can be bagged and disposed in regular trash receptacles. PPE that is grossly contaminated must be bagged (sealed and field personnel should communicate with the Project Manager to determine proper disposal.

Disposal Method for Contaminated Soil

- Contaminated soil cuttings and spoils must be containerized for disposal off-site unless otherwise specifically directed.
- Soil cuttings and spoils determined to be free of contamination through field screening can usually be returned to the boreholes or excavations from which they came.

Any additional requirements that are designated by the workplan or by client specifications should be entered here.

Disposal Method for Contaminated Groundwater

- Contaminated groundwater must be containerized in a drum for disposal off-site unless otherwise specifically directed.

Any additional requirements that are designated by the workplan or by client specifications should be entered here.

Standard Disposal Methods for Contaminated Materials

- Excess sample solids, decontamination materials, rags, brushes, poly-sheeting, etc. that are determined to be free of contamination through field screening can usually be disposed into client-approved, on-site trash receptacles.
- Uncontaminated wash water may be discarded onto the ground surface away from surface water bodies in areas where infiltration can occur.
- Contaminated materials must be segregated into liquids or solids and containerized separately for offsite disposal.

Any additional requirements that are designated by the workplan or by client specifications should be entered here.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

8. SITE CONTROL

The overall purpose of site control is to minimize potential contamination of workers, protect the public from the site's hazards, and prevent vandalism. Site control is especially important in emergency situations. The degree of site control necessary depends on site characteristics, site size, and the surrounding community. The following information identifies the elements used to control the activities and movements of people and equipment at the project site.

Communication
Internal Haley & Aldrich site personnel will communicate with other Haley & Aldrich staff member and/or subcontractors or contractors with: Face to Face Communication Cellular Phones
External H&S site personnel will use the following means to communicate with off-site personnel or emergency services. Cellular Phones
Visitors
Project Site Will visitors be required to check-in prior to accessing the project site? Yes
Visitor Access Authorized visitors that require access to the project site need to be provided with known information with respect to the site operations and hazards as applicable to the purpose of their site visit. Authorized visitors must have the required PPE and appropriate training to access the project site.
Zoning
Work Zone The work zone will be clearly delineated to ensure that the general public or unauthorized worker access is prevented. The following will be used: Temporary Fencing Cones Flagging Tape Barricades

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

9. SITE SPECIFIC EMERGENCY RESPONSE PLAN

The Emergency Response Plan addresses potential emergencies at this site, procedures for responding to these emergencies, roles, responsibilities during emergency response, and training. This section also describes the provisions this project has made to coordinate its emergency response with other contractors onsite and with offsite emergency response organizations (as applicable).

During the development of this emergency response plan, local, state, and federal agency disaster, fire, and emergency response organizations were consulted (if required) to ensure that this plan is compatible and integrated with plans of those organizations. Documentation of the dates of these consultations are the names of individuals contacted is kept on file and available upon request.

The site has been evaluated for potential emergency occurrences, based on site hazards, and the major categories of emergencies that could occur during project work are:

- Fire(s)/Combustion
- Hazardous Material Event
- Medical Emergency
- Natural Disaster

A detailed list of emergency types and response actions are summarized in Table X below. Prior to the start of work, the SSO will update the table with any additional site-specific information regarding evacuations, muster points, or additional emergency procedures. The SSO will establish evacuation routes and assembly areas for the Site. All personnel entering the Site will be informed of these routes and assembly areas.

Pre-Emergency Planning

Before the start of field activities, the Project Manager will ensure preparation has been made in anticipation of emergencies. Preparatory actions include the following:

Meeting with the subcontractor/and or client concerning the emergency procedures in the event a person is injured. Appropriate actions for specific scenarios will be reviewed. These scenarios will be discussed, and responses determined before the sampling event commences. A form of emergency communication (i.e.; Cell phone, Air horn, etc.) between the Project Manager and subcontractor and/or client will be agreed on before the work commences.

A training session (i.e., “safety meeting”) given by the Project Manager or their designee informing all field personnel of emergency procedures, locations of emergency equipment and their use, and proper evacuation procedures.

Ensuring field personnel are aware of the existence of the emergency response HASP and ensuring a copy of the HASP accompanies the field team(s).

Onsite Emergency Response Equipment

Emergency procedures may require specialized equipment to facilitate work rescue, contamination control and reduction or post-emergency cleanup. Emergency response equipment stocked

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Table 9.1 Emergency Equipment and Emergency PPE			
Emergency Equipment	**Specific Type**	**Quantity Stocked**	**Location Stored**
First Aid Kit	H&A Provided	1	Per field person
Decontamination Solution	Alconox Spray Bottole	1	With field team/storage box or other
Spill Kit	Spill Pads or Spill Kit	1	With field team/storage box or other
Emergency PPE	**Specific Type**	**Quantity Stocked**	**Location Stored**
Select	Enter text	Enter text	Enter text

EVACUATION ALARM
Will be communicated during the Onsite Kickoff Meeting
EVACUATION ROUTES
Will be given a map after site specific training
EVACUATION MUSTER POINT(S)/ SHELTER AREA(S)
Will be given a locations after site specific training
EVACUTION RESPONSE DRILLS
The Site relies on outside emergency responders and a drill is not required.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Table 9-2 – Emergency Planning

Emergency Type	Notification	Response Action	Evacuation Plan/Route
Chemical Exposure	Report event to SSO immediately	Refer to Safety Data Sheet for required actions	Remove personnel from work zone
Fire - Small	Notify SSO and contact 911	Use fire extinguisher if safe and qualified to do so	Mobilize to *Muster Point*
Fire – Large/Explosion	Notify SSO and contact 911	Evacuate immediately	Mobilize to *Muster Point*
Hazardous Material – Spill/Release	Notify SSO; SSO will contact PM to determine if additional agency notification is	If practicable don PPE and use spill kit and applicable procedures to contain the release	See Evacuation Map for route, move at least 100 ft upwind of spill location
Medical – Bloodborne Pathogen	Notify SSO	If qualified dispose in container or call client or city to notify for further instruction.	None Anticipated
Medical – First Aid	Notify SSO	If qualified perform first aid duties	None Anticipated
Medical – Trauma	If life threatening or transport is required call 911, immediately	Wait at site entrance for ambulance	Noe Anticipated
Security Threat	Notify SSO who will call 911 as warranted	Keep all valuables out of site and work zones delineated.	None Anticipated
Weather – Earthquake/Tsunami's	STOP WORK and evacuate Site upon any earthquake	Turn off equipment and evacuate as soon as is safe to do so	Mobilize to *Shelter Location*
Weather – Lightning Storm	STOP WORK	Work may resume 30 minutes after the last observed lightning.	None Anticipated
Weather – Tornadoes/Hurricanes	Monitor weather conditions STOP WORK and evacuate the site	Evacuate to shelter location or shelter in place immediately	Mobilize to *Shelter Location*
MUSTER POINT Will be communicated during the Onsite Kickoff Meeting		*SHELTER LOCATION* Will be communicated during the Onsite Kickoff Meeting	
In case of site emergencies, site personnel shall be evacuated per this table and will not participate in emergency response activities. Site emergencies shall be reported to local, state, and federal governmental agencies as required.			

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

10. HASP ACKNOWLEDGEMENT FORM

All Haley & Aldrich employees onsite must sign this form prior to entering the site.

I hereby acknowledge receipt of, and briefing on, this HASP prior to the start of on-site work. I declare that I understand and agree to follow the provisions, processes, and procedures set forth herein at all times while working on this site.

Printed Name	Signature	Date

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

ATTACHMENT A
HASP AMENDMENT FORM

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

HASP AMENDMENT FORM

This form is to be used whenever there is an immediate change in the project scope that will require an amendment to the HASP. For project scope changes associated with "add-on" tasks, the changes must be made in the body of the HASP. Before changes can be made, a review of the potential hazards must be initiated by the Haley & Aldrich Project Manager.

This original form must remain on site with the original HASP. If additional copies of this HASP have been distributed, it is the Project Manager's responsibility to forward a signed copy of this amendment to those who have copies.

Amendment No.	
Site Name	
Work Assignment No.	
Date	
Type of Amendment	
Reason for Amendment	
Alternate Safeguard Procedures	
Required Changes in PPE	

Project Manager Name (Print)	Project Manager Signature	Date

Health & Safety Approver Name (Print)	Health & Safety Approver Signature	Date

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

ATTACHMENT B
TRAINING REQUIREMENTS

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

TRAINING REQUIREMENTS

Health and Safety Training Requirements

Personnel will not be permitted to supervise or participate in field activities until they have been trained to a level required by their job function and responsibility. Haley & Aldrich staff members, contractors, subcontractors, and consultants who have the potential to be exposed to contaminated materials or physical hazards must complete the training described in the following sections.

The Haley & Aldrich Project Manager/FSM will be responsible for maintaining and providing to the client/site manager documentation of Haley & Aldrich staff members' compliance with required training as requested. Records shall be maintained per OSHA requirements.

40-Hour Health and Safety Training

The 40-Hour Health and Safety Training course provides instruction on the nature of hazardous waste work, protective measures, proper use of personal protective equipment, recognition of signs and symptoms which might indicate exposure to hazardous substances, and decontamination procedures. It is required for all personnel working on-site, such as equipment operators, general laborers, and supervisors, who may be potentially exposed to hazardous substances, health hazards, or safety hazards consistent with 29 CFR 1910.120.

8-hour Annual Refresher Training

Personnel who complete the 40-hour health and safety training are subsequently required to attend an annual 8-hour refresher course to remain current in their training. When required, site personnel must be able to show proof of completion (i.e., certification) at an 8-hour refresher training course within the past 12 months.

8-Hour Supervisor Training

On-site managers and supervisors directly responsible for, or who supervise staff members engaged in hazardous waste operations, should have eight additional hours of Supervisor training in accordance with 29 CFR 1910.120. Supervisor Training includes, but is not limited to, accident reporting/investigation, regulatory compliance, work practice observations, auditing, and emergency response procedures.

Additional Training for Specific Projects

Haley & Aldrich personnel will ensure their personnel have received additional training on specific instrumentation, equipment, confined space entry, construction hazards, etc., as necessary to perform their duties. This specialized training will be provided to personnel before engaging in the specific work activities including:

- Client specific training or orientation
- Competent person excavations
- Confined space entry (entrant, supervisor, and attendant)
- Heavy equipment including aerial lifts and forklifts
- First aid/ CPR
- Use of fall protection
- Use of nuclear density gauges
- Asbestos awareness

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

ATTACHMENT C
ROLES AND RESPONSIBILITIES

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

SITE ROLES AND RESPONSIBILITIES

Haley & Aldrich Personnel

Field Safety Manager (FSM)

The Haley & Aldrich FSM is a full-time Haley & Aldrich staff member, trained as a safety and health professional, who is responsible for the interpretation and approval of this Safety Plan. Modifications to this Safety Plan cannot be undertaken by the PM or the SSO without the approval of the FSM.

Specific duties of the FSM include:

- Approving and amending the Safety Plan for this project
- Advising the PM and SHSOs on matter relating to health and safety
- Recommending appropriate personal protective equipment (PPE) and air monitoring instrumentation
- Maintaining regular contact with the PM and SSO to evaluate the conditions at the property and new information which might require modifications to the HASP and
- Reviewing and approving JSAs developed for the site-specific hazards.

Project Manager (PM)

The Haley & Aldrich PM is responsible for ensuring that the requirements of this HASP are implemented at that project location. Some of the PM´s specific responsibilities include:

- Assuring that all personnel to whom this HASP applies have received a copy of it;
- Providing the FSM with updated information regarding environmental conditions at the site and the scope of site work;
- Providing adequate authority and resources to the on-site SHSO to allow for the successful implementation of all necessary safety procedures;
- Supporting the decisions made by the SHSO;
- Maintaining regular communications with the SHSO and, if necessary, the FSM;
- Coordinating the activities of all subcontractors and ensuring that they are aware of the pertinent health and safety requirements for this project;
- Providing project scheduling and planning activities; and
- Providing guidance to field personnel in the development of appropriate Job Safety Analysis (JSA) relative to the site conditions and hazard assessment.

Site Health & Safety Officer (SHSO)

The SHSO is responsible for field implementation of this HASP and enforcement of safety rules and regulations. SHSO functions may include some or all of the following:

- Act as Haley & Aldrich´s liaison for health and safety issues with client, staff, subcontractors, and agencies.
- Verify that utility clearance has been performed by Haley & Aldrich subcontractors.
- Oversee day-to-day implementation of the Safety Plan by Haley & Aldrich personnel on site.

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

- Interact with subcontractor project personnel on health and safety matters.
- Verify use of required PPE as outlined in the safety plan.
- Inspect and maintain Haley & Aldrich safety equipment, including calibration of air monitoring instrumentation used by Haley & Aldrich.
- Perform changes to HASP and document in Appendix A of the HASP as needed and notify appropriate persons of changes.
- Investigate and report on-site accidents and incidents involving Haley & Aldrich and its subcontractors.
- Verify that site personnel are familiar with site safety requirements (e.g., the hospital route and emergency contact numbers).
- Report accidents, injuries, and near misses to the Haley & Aldrich PM and FSM as needed.

The SHSO will conduct initial site safety orientations with site personnel (including subcontractors) and conduct toolbox and safety meetings thereafter with Haley & Aldrich employees and Haley & Aldrich subcontractors at regular intervals and in accordance with Haley & Aldrich policy and contractual obligations. The SHSO will track the attendance of site personnel at Haley & Aldrich orientations, toolbox talks, and safety meetings.

Field Personnel

Haley & Aldrich personnel are responsible for following the health and safety procedures specified in this HASP and for performing their work in a safe and responsible manner. Some of the specific responsibilities of the field personnel are as follows:

- Reading the HASP in its entirety prior to the start of on-site work;
- Submitting a completed Safety Plan Acceptance Form and documentation of medical surveillance and training to the SHSO prior to the start of work;
- Attending the pre-entry briefing prior to beginning on-site work;
- Bringing forth any questions or concerns regarding the content of the Safety Plan to the PM or the SHSO prior to the start of work;
- Stopping work when it is not believed it can be performed safely;
- Reporting all accidents, injuries and illnesses, regardless of their severity, to the SHSO;
- Complying with the requirements of this safety plan and the requests of the SHSO; and
- Reviewing the established JSAs for the site-specific hazards on a daily basis and prior to each shift change, if applicable.

Visitors

Authorized visitors (e.g., Client Representatives, Regulators, Haley & Aldrich management staff, etc.) requiring entry to any work location on the site will be briefed by the Site Supervisor on the hazards present at that location. Visitors will be escorted at all times at the work location and will be responsible for compliance with their employer´s health and safety policies. In addition, this safety plan specifies the minimum acceptable qualifications, training and personal protective equipment which are required for entry to any controlled work area; visitors must comply with these

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

requirements at all times. Unauthorized visitors, and visitors not meeting the specified qualifications, will not be permitted within established controlled work areas.

SUBCONTRACTOR PERSONNEL

Subcontractor Site Representative

Each contractor and subcontractor shall designate a Contractor Site Representative. The Contractor Site Representative will interface directly with Insert Staff Name Here, the Subcontractor Site Safety Manager, with regards to all areas that relate to this safety plan and safety performance of work conducted by the contractor and/or subcontractor workforce. Contractor Site Representatives for this site are listed in the Contact Summary Table at the beginning of the Safety Plan.

Subcontractor Site Safety Manager

Each contractor / subcontractor will provide a qualified representative who will act as their Site Safety Manager (Sub-SSM). This person will be responsible for the planning, coordination, and safe execution of subcontractor tasks, including preparation of job hazard analyses (JHA), performing daily safety planning, and coordinating directly with the Haley & Aldrich SHSO for other site safety activities. This person will play a lead role in safety planning for Subcontractor tasks, and in ensuring that all their employees and lower tier subcontractors are in adherence with applicable local, state, and/or federal regulations, and/or industry and project specific safety standards or best management practices.

General contractors / subcontractors are responsible for preparing a site-specific HASP and/or other task specific safety documents (e.g., JHAs), which are, at a minimum, in compliance with local, state, and/or federal other regulations, and/or industry and project specific safety standards or best management practices. The contractor(s)/subcontractor(s) safety documentation will be at least as stringent as the health and safety requirements of the Haley & Aldrich Project specific HASP.

Safety requirements include, but are not limited to: legal requirements, contractual obligations and industry best practices. Contractors/subcontractors will identify a site safety representative during times when contractor/subcontractor personnel are on the Site. All contractor/subcontractor personnel will undergo a field safety orientation conducted by the Haley & Aldrich SHSO and/or PM prior to commencing site work activities. All contractors / subcontractors will participate in Haley & Aldrich site safety meetings and their personnel will be subject to training and monitoring requirements identified in this Safety Plan. If the contractors / subcontractors means and methods deviate from the scope of work described in Section 1 of this Safety Plan, the alternate means and methods must be submitted, reviewed and approved by the Haley & Aldrich SHSO and/or PM prior to the commencement of the work task. Once approved by the Haley & Aldrich SHSO and/or PM, the alternate means and methods submittal will be attached to this Safety Plan as an Addendum.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

ATTACHMENT D
JOB SAFETY ANALYSES

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.



4001 4TH AVENUE REDEVELOPMENT SITE

KEY TASK 1: Remedial Oversight – Excavation, UST Removal, SSDS Installation, SVE System Installation, Cutoff Wall Installation

Subtask Category	Potential Hazards	Controls
Oversight	Slips, Trips, and Falls	• Take your time and pay attention to where you are going • Adjust your stride to a pace that is suitable for the walking surface and tasks you are doing • Check the work area to identify hazards – beware of trip hazards such as wet floors, slippery floors, and uneven surfaces or terrain • Establish and utilize a pathway free of slip and trip hazards • Choose a safer walker route • Carry loads you can see over • Keep work areas clean and free of clutter • Communicate hazards to on-site personnel – remove hazards as appropriate
Oversight	Weather-related hazards	• Avoid slippery surfaces as a result of cold weather • Seek shelter in the event of a lightning storm and stay clear of potential
Oversight	Cold stress	• Take breaks indoors, hand warmers
Oversight	Heat stress	• Taking cooling breaks, maintain hydration (if work occurs in warmer months)
Oversight	Heavy equipment	• Personal protective equipment, licensed excavator/machine operators • Maintain a safe distance from moving equipment and observe equipment swing radii • Make eye contact with operators and get their acknowledgement before moving around heavy equipment

Note: This HASP has been developed for Haley & Aldrich purposes only and is not for use by others.

		• Stay out of line of fire • Avoid pinch points
Oversight	Lifting	• All personnel not involved with the lift shall be kept at no less than 3 times the length of the boom. • Employees shall not work or walk under a suspended load.
Oversight	Noise reduction	• Personnel protective equipment, ear plugs or earmuffs
Oversight	Work site access and controls	• Observe all work site access and controls before entering work area • Use only routes that are designated for personnel • Do not change or alter established work site access or controls
Oversight	Utility locators and underground hazards	• Observe work from a distance in case of utility strike • Immediately evacuate work area in the event of a utility strike
Oversight	Vehicle traffic/safety	• Watch out for vehicular traffic in and around work area • Access work area along routes that are least busy
KEY TASK 2: Soil Sampling		
Subtask Category	**Potential Hazards**	**Controls**
Soil Sampling	Slips, trips, and falls	• See above.
Soil Sampling	Weather-related hazards	• See above.
Soil Sampling	Heat stress	• See above.
Soil Sampling	Cold stress	• See above.
KEY TASK 3: Soil Vapor/ Groundwater Sampling		
Subtask Category	**Potential Hazards**	**Controls**
Soil vapor sampling / Groundwater sampling	Slips, trips, and falls	• See above.
Soil vapor sampling / Groundwater sampling	Weather-related hazards	• See above.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

Soil vapor sampling / Groundwater sampling	Heat stress	• See above.
Soil vapor sampling / Groundwater sampling	Cold stress	• See above.

Note: This HASP is developed for Haley & Aldrich purposes only and not for use by others.

APPENDIX C
Quality Assurance Project Plan

HALEY ALDRICH

www.haleyaldrich.com

QUALITY ASSURANCE PROJECT PLAN
4001 4TH AVENUE REDEVELOPMENT SITE
NYSDEC SITE NO. C224412
4001-4011 4TH AVENUE
BROOKLYN, NEW YORK

by
H & A of New York Engineering and Geology LLP
New York, New York

for
4th Ave Property LLC
New York, New York

File No. 0210815
October 2025

Executive Summary

This Quality Assurance Project Plan (QAPP) outlines the scope of the quality assurance and quality control (QA/QC) activities associated with the site monitoring activities associated with the Interim Remedial Measures Work Plan (IRMWP) for 4001 4th Avenue in Brooklyn, New York (Site).

Protocols for sample collection, sample handling and storage, chain-of-custody procedures, and laboratory and field analyses are described herein or specifically referenced to related project documents.

Table of Contents

Page

Executive Summary i
List of Tables v
List of Attachments v

1. Project Description 1

1.1 PROJECT OBJECTIVES 1
1.2 SITE DESCRIPTION AND SITE HISTORY 1
1.3 LABORATORY PARAMETERS 1
1.4 SAMPLING LOCATIONS 1

2. Project Organization and Responsibilities 2

2.1 PROJECT TEAM 2
2.2 MANAGEMENT RESPONSIBILITIES 2
2.3 QUALITY ASSURANCE RESPONSIBILITIES 2
2.3.1 QA Officer 3
2.3.2 Data Validation Staff 3
2.4 LABORATORY RESPONSIBILITIES 3
2.4.1 Laboratory Project Manager 3
2.4.2 Laboratory Operations Manager 3
2.4.3 Laboratory QA Officer 3
2.4.4 Laboratory Sample Custodian 4
2.4.5 Laboratory Technical Personnel 4
2.5 FIELD RESPONSIBILITIES 4
2.5.1 Field Coordinator 4
2.5.2 Field Team Personnel 5

3. Sampling Procedures 6

3.1 SAMPLE CONTAINERS 6
3.2 SAMPLE LABELING 6
3.3 FIELD QC SAMPLE COLLECTION 6
3.3.1 Field Duplicate Sample Collection 6
3.4 GENERAL DECONTAMINATION PROCEDURES 6

4. Custody Procedures 8

4.1 FIELD CUSTODY PROCEDURES 8
4.1.1 Field Procedures 9
4.1.2 Transfer of Custody and Shipment Procedures 9
4.2 LABORATORY CHAIN-OF-CUSTODY PROCEDURES 10
4.3 STORAGE OF SAMPLES 10
4.4 FINAL PROJECT FILES CUSTODY PROCEDURES 10

Table of Contents

Page

5. Calibration Procedures and Frequency 12

5.1 FIELD INSTRUMENT CALIBRATION PROCEDURES 12
5.2 LABORATORY INSTRUMENT CALIBRATION PROCEDURES 12

6. Analytical Procedures 13

6.1 FIELD ANALYTICAL PROCEDURES 13
6.2 LABORATORY ANALYTICAL PROCEDURES 13
6.2.1 List of Project Target Compounds and Laboratory Detection Limits 13
6.2.2 List of Method-Specific Quality Control Criteria 13

7. Internal Quality Control Checks 14

7.1 FIELD QUALITY CONTROL 14
7.1.1 Field Blanks 14
7.1.2 Trip Blanks 14
7.2 LABORATORY PROCEDURES 14
7.2.1 Field Duplicate Samples 14
7.2.2 Matrix Spike Samples 15
7.2.3 Laboratory Control Sample Analyses 15
7.2.4 Surrogate Compound/Internal Standard Recoveries 15
7.2.5 Calibration Verification Standards 16
7.2.6 Laboratory Method Blank Analyses 16

8. Data Quality Objectives 17

8.1 PRECISION 17
8.1.1 Definition 17
8.1.2 Field Precision Sample Objectives 17
8.1.3 Laboratory Precision Sample Objectives 17
8.2 ACCURACY 18
8.2.1 Definition 18
8.2.2 Field Accuracy Objectives 18
8.3 LABORATORY ACCURACY OBJECTIVES 18
8.4 REPRESENTATIVENESS 19
8.4.1 Definition 19
8.4.2 Measures to Ensure Representativeness of Field Data 19
8.5 COMPLETENESS 19
8.5.1 Definition 19
8.5.2 Field Completeness Objectives 19
8.5.3 Laboratory Completeness Objectives 19
8.6 COMPARABILITY 20
8.6.1 Definition 20
8.6.2 Measures to Ensure Comparability of Laboratory Data 20

Table of Contents

Page

8.7 LEVEL OF QUALITY CONTROL EFFORT 20

9. Data Reduction, Validation, and Reporting 21

9.1 DATA REDUCTION 21
9.1.1 Field Data Reduction Procedures 21
9.1.2 Laboratory Data Reduction Procedures 21
9.1.3 Quality Control Data 21
9.2 DATA VALIDATION 21
9.3 DATA REPORTING 22

10. Performance and System Audits 23

10.1 FIELD PERFORMANCE AND SYSTEM AUDITS 23
10.1.1 Internal Field Audit Responsibilities 23
10.1.2 External Field Audit Responsibilities 23
10.2 LABORATORY PERFORMANCE AND SYSTEM AUDITS 23
10.2.1 Internal Laboratory Audit Responsibilities 23
10.2.2 External Laboratory Audit Responsibilities 24

11. Preventive Maintenance 25

11.1 FIELD INSTRUMENT PREVENTIVE MAINTENANCE 25
11.2 LABORATORY INSTRUMENT PREVENTIVE MAINTENANCE 25

12. Specific Routine Procedures Used to Assess Data Precision, Accuracy, and Completeness 26

12.1 FIELD MEASUREMENTS 26
12.2 LABORATORY DATA 26

13. Quality Assurance Reports 27

References 28

List of Tables

Table No.	Title
I	Summary of Analysis Method, Preservation Method, Holding Time, Sample Size Requirements and Sample Containers

List of Attachments

Attachment	Title
A	Project Team Resumes

1. Project Description

This Quality Assurance Project Plan (QAPP) has been prepared as a component of the Interim Remedial Measure Work Plan (IRMWP) for the 4001 4th Avenue Site in Brooklyn, New York (Site).

1.1 PROJECT OBJECTIVES

The primary objective for data collection activities is to collect sufficient data necessary to monitor the nature of any remaining soil impacts.

1.2 SITE DESCRIPTION AND SITE HISTORY

The general Site description and Site history are provided in the IRMWP incorporated herein by reference.

1.3 LABORATORY PARAMETERS

The laboratory parameters for soil include:

- Target Compound List (TCL) volatile organic compounds (VOCs) using U.S. Environmental Protection Agency (EPA) Method 8260;
- TCL semi-volatile organic compounds (SVOCs) using EPA Method 8270;
- Total Analyte List (TAL) metals using EPA Method 6010;
- Polychlorinated biphenyls (PCBs) using EPA Method 8082;
- TCL pesticides using EPA Method 8081;
- Per- and polyfluoroalkyl substances (PFAS) using EPA Method 1633A; and,
- 1,4-dioxane using EPA Method 8270 SIM.

Note: PFAS will be collected in accordance with the New York State Department of Environmental Conservation (NYSDEC), Division of Environmental Remediation (DER), Sampling, Analysis and Assessment of Per- and Polyfluoroalkyl Substances (PFAS) under NYSDEC Part 375 Remedial Program, April 2023.

Laboratory parameters for disposal samples will be determined by the disposal facility after an approved facility has been determined.

1.4 SAMPLING LOCATIONS

The IRMWP provides the locations of soil borings that will be sampled.

2. Project Organization and Responsibilities

This section defines the roles and responsibilities of the individuals who will perform the IRMWP monitoring activities. A New York State Department of Health (NYSDOH)-certified analytical laboratory will perform the analyses of environmental samples collected at the Site.

2.1 PROJECT TEAM

The following project personnel are anticipated for oversight of the IRMWP implementation. Applicable Project personnel resumes are provided in Appendix E of the IRMWP and in Attachment A.

NYSDEC Case Manager	Shawn Roberts
NYSDOH Case Manager	Christopher Budd
Remediation Engineer	Suzanne M. Bell, P.E.
Qualified Environmental Professional (QEP)	Mari Conlon, P.G.
Project Manager	Paul Probasco, P.G.
Haley & Aldrich of New York* Health & Safety Director	Brian Fitzpatrick, CHMM
Health & Safety Officer (HSO)	Brian Ferguson
Quality Assurance (QA) Officer	Nicole Mooney
Third Party Validator	Katherine Miller

**H & A of New York Engineering and Geology LLP (Haley & Aldrich of New York)*

2.2 MANAGEMENT RESPONSIBILITIES

The Project Manager is responsible for managing the implementation of the IRMWP and monitoring and coordinating the collection of data. The Project Manager is responsible for technical quality control (QC) and project oversight. The Project Manager's responsibilities include the following:

- Acquire and apply technical and corporate resources as needed to ensure performance within budget and schedule restraints;
- Review work performed to ensure quality, responsiveness, and timeliness;
- Communicate with the client point of contact concerning the progress of the monitoring activities;
- Assure corrective actions are taken for deficiencies cited during audits of IRMWP monitoring activities; and
- Assure compliance with the Site Health and Safety Plan (HASP).

2.3 QUALITY ASSURANCE RESPONSIBILITIES

The QA team will consist of a QA Officer and the Data Validation Staff. QA responsibilities are described as follows:

2.3.1 QA Officer

The QA Officer reports directly to the Project Manager and will be responsible for overseeing the review of field and laboratory data. Additional responsibilities include the following:

- Assure the application and effectiveness of the QAPP by the analytical laboratory and the project staff; and,
- Provide input to the Project Manager as to corrective actions that may be required as a result of the above-mentioned evaluations.

The QA Officer will be assisted by the Data Validation Staff in the evaluation and validation of field and laboratory-generated data.

2.3.2 Data Validation Staff

The Data Validation Staff will be independent of the laboratory and familiar with the analytical procedures performed. The validation will include a review of each validation criterion as prescribed by the guidelines presented in Section 9.2 of this document and will be presented in a Data Usability Summary Report (DUSR) for submittal to the QA Officer.

2.4 LABORATORY RESPONSIBILITIES

The Environmental Laboratory Approval Program (ELAP)-approved laboratory to be used will be Alpha Analytical, located in Westborough, Massachusetts. Laboratory services in support of the IRMWP monitoring include the following personnel:

2.4.1 Laboratory Project Manager

The Laboratory Project Manager will report directly to the QA Officer and Project Manager and will be responsible for ensuring all resources of the laboratory are available on an as-required basis. The Laboratory Project Manager will also be responsible for the approval of the final analytical reports.

2.4.2 Laboratory Operations Manager

The Laboratory Operations Manager will report to the Laboratory Project Manager and will be responsible for coordinating laboratory analysis, supervising in-house chain-of-custody reports, scheduling sample analyses, overseeing data review, and overseeing preparation of analytical reports.

2.4.3 Laboratory QA Officer

The Laboratory QA Officer will have sole responsibility for the review and validation of the analytical laboratory data. The Laboratory QA Officer will provide Case Narrative descriptions of any data quality issues encountered during the analyses conducted by the laboratory. The QA Officer will also define appropriate QA procedures, overseeing QA/QC documentation.

2.4.4 Laboratory Sample Custodian

The Laboratory Sample Custodian will report to the Laboratory Operations Manager and will be responsible for the following:

- Receive and inspect the incoming sample containers;
- Record the condition of the incoming sample containers;
- Sign appropriate documents;
- Verify chain-of-custody and its correctness;
- Notify the Project Manager and Operations Manager of sample receipt and inspection;
- Assign a unique identification number and enter each into the sample receiving log;
- Initiate transfer of samples to laboratory analytical sections; and
- Control and monitor access/storage of samples and extracts.

2.4.5 Laboratory Technical Personnel

The Laboratory Technical Staff will have the primary responsibility for the performance of sample analysis and the execution of the QA procedures developed to determine the data quality. These activities will include the proper preparation and analysis of the project samples in accordance with the laboratory's Quality Assurance Manual (QAM) and associated Standard Operating Procedures (SOPs).

2.5 FIELD RESPONSIBILITIES

2.5.1 Field Coordinator

The Field Coordinator is responsible for the overall operation of the field team and reports directly to the Project Manager. The Field Coordinator works with the project HSO to conduct operations in compliance with the project HASP. The Field Coordinator will facilitate communication and coordinate efforts between the Project Manager and the field team members.

Other responsibilities include the following:

- Develop and implement field-related work plans, ensuring schedule compliance, and adhering to management-developed project requirements;
- Coordinate and manage field staff;
- Perform field system audits;
- Oversee QC for technical data provided by the field staff;
- Prepare and approve text and graphics required for field team efforts;
- Coordinate and oversee technical efforts of subcontractors assisting the field team;
- Identify problems in the field; resolve difficulties in consultation with the Project QA Officer and Project Manager; implement and document corrective action procedures; and,
- Participate in preparation of the final reports.

2.5.2 Field Team Personnel

Field Team Personnel will be responsible for the following:

- Perform field activities as detailed in the IRMWP and in compliance with the Field Sampling Plan (FSP) and QAPP.
- Immediately report any accidents and/or unsafe conditions to the Site HSO and take reasonable precautions to prevent injury.

3. Sampling Procedures

The FSP in the NYSDEC-approved Remedial Investigation Work Plan (RIWP) provides the SOPs for sampling required by the IRMWP. Sampling will be conducted in general accordance with the NYSDEC Technical Guidance for Site Investigation and Remediation (DER-10) and the Sampling, Analysis and Assessment of PFAS under NYSDEC Part 375 Remedial Program (April 2023) when applicable.

3.1 SAMPLE CONTAINERS

Sample containers for each sampling task will be provided by the laboratory performing the analysis. The containers will be cleaned by the manufacturer to meet or exceed the analyte specifications established in the EPA's "Specifications and Guidance for Obtaining Contaminant-Free Sample Containers," April 1992, OSWER Directive #9240.0-0.5A. Certificates of analysis for each lot of sample containers used will be maintained by the laboratory.

The appropriate sample containers, preservation methods, maximum holding times, and handling requirements for each sampling task are provided in Table I.

3.2 SAMPLE LABELING

Each sample will be labeled with a unique sample identifier that will facilitate tracking and cross-referencing of sample information. Field blanks and field duplicate samples will also be numbered with a unique sample identifier to prevent analytical bias of field QC samples.

Refer to the FSP for the sample labeling procedures.

3.3 FIELD QC SAMPLE COLLECTION

3.3.1 Field Duplicate Sample Collection

3.3.1.1 Soil Samples

Soil field duplicates will be collected as specified in the following procedure:

1. Soil for VOC analysis will be removed from the sampling device as specified in the FSP.
2. Soil for non-VOC analysis will be removed from the sampling device and collected into clean laboratory-provided containers.

3.4 GENERAL DECONTAMINATION PROCEDURES

Care must be taken to minimize the potential for transfer of contaminated materials to the ground or onto other materials. Regardless of the size or nature of the equipment being decontaminated, the process will utilize a series of steps that involve removal of gross material (dirt, grease, oil, etc.), washing with a detergent, and multiple rinsing steps. In lieu of a series of washes and rinse steps, steam cleaning with low-volume, high-pressure equipment (i.e., steam cleaner) is acceptable.

Exploration equipment and all monitoring equipment in contact with the sampling media must be decontaminated prior to initiating site activities, in between exploration locations to minimize cross-contamination, and prior to mobilizing off the Site after completion of Site work.

The following specific decontamination procedure is recommended for sampling equipment and tools:

- Brush loose soil off equipment;
- Wash equipment with laboratory grade detergent (i.e., Alconox or equivalent);
- Rinse with tap water;
- Rinse equipment with distilled water;
- Allow water to evaporate before reusing equipment; and
- Wrap equipment in aluminum foil when not being used.

4. Custody Procedures

Sample custody is addressed in three parts: field sample collection, laboratory analysis, and final project files. Custody of a sample begins when it is collected by or transferred to an individual and ends when that individual relinquishes or disposes of the sample.

A sample is under custody if:

1. The item is in actual possession of a person;
2. The item is in the view of the person after being in actual possession of the person;
3. The item was in actual possession and subsequently stored to prevent tampering; or
4. The item is in a designated and identified secure area.

4.1 FIELD CUSTODY PROCEDURES

Field personnel will keep written records of field activities on applicable preprinted field forms or in a bound field notebook to record data collecting activities. These records will be written legibly in ink and will contain pertinent field data and observations. Entry errors or changes will be crossed out with a single line, dated, and initialed by the person making the correction. Field forms and notebooks will be periodically reviewed by the Field Coordinator.

The beginning of each entry in the logbook or preprinted field form will contain the following information:

- Date;
- Start time;
- Weather;
- Names of field personnel (including subcontractors);
- Level of personal protective equipment (PPE) used at the Site; and
- Names of all visitors and the purpose of their visit.

For each measurement and sample collected, the following information will be recorded:

- Detailed description of sample location;
- Equipment used to collect the sample or make the measurement and the date the equipment was calibrated;
- Time sample was collected;
- Description of the sample conditions;
- Depth sample was collected (if applicable);
- Volume and number of containers filled with the sample; and
- Sampler's identification.

4.1.1 Field Procedures

The following procedure describes the process to maintain the integrity of the samples:

- Upon collection samples are placed in the proper containers. In general, samples collected for organic analysis will be placed in pre-cleaned glass containers, and samples collected for inorganic analysis will be placed in pre-cleaned plastic (polyethylene) bottles. Refer to the FSP for sample packaging procedures.
- Samples will be assigned a unique sample number and will be affixed to a sample label. Refer to the FSP for sample labeling procedures.
- Samples will be properly and appropriately preserved by field personnel in order to minimize loss of the constituent(s) of interest due to physical, chemical, or biological mechanisms.
- Appropriate volumes will be collected to ensure that the appropriate reporting limits can be successfully achieved and that the required QC sample analyses can be performed.

4.1.2 Transfer of Custody and Shipment Procedures

- A chain-of-custody record will be completed at the time of sample collection and will accompany each shipment of project samples to the laboratory. The field personnel collecting the samples will be responsible for the custody of the samples until the samples are relinquished to the laboratory. Sample transfer will require the individuals relinquishing and receiving the samples to sign, date, and note the time of sample transfer on the chain-of-custody record.
- Samples will be shipped or delivered in a timely fashion to the laboratory so that holding times and/or analysis times as prescribed by the methodology can be met.
- Samples will be transported in containers (coolers) that will maintain the refrigeration temperature for those parameters for which refrigeration is required in the prescribed preservation protocols.
- Samples will be placed in an upright position and limited to one layer of samples per cooler. Additional bubble wrap or packaging material will be added to fill the cooler. Shipping containers will be secured with strapping tape and custody tape for shipment to the laboratory.
- When samples are split with the NYSDEC representatives, a separate chain-of-custody will be prepared and marked to indicate with whom the samples are shared. The person relinquishing the samples will require the representative's signature acknowledging sample receipt.
- If samples are sent by a commercial carrier, a bill of lading will be used. A copy of the bill of lading will be retained as part of the permanent record. Commercial carriers will not sign the custody record as long as the custody record is sealed inside the sample cooler and the custody tape remains intact.
- Samples will be picked up by a laboratory courier or transported to the laboratory the same day they are collected, unless collected on a weekend or holiday. In these cases, the samples will be stored in a secure location until delivery to the laboratory. Additional ice will be added to the cooler as needed to maintain proper preservation temperatures.

4.2 LABORATORY CHAIN-OF-CUSTODY PROCEDURES

A Sample Custodian will be designated by the laboratory and will have the responsibility to receive all incoming samples. Once received, the custodian will document if the sample is received in good condition (i.e., unbroken, cooled, etc.) and that the associated paperwork, such as chain-of-custody forms, has been completed. The custodian will sign the chain-of-custody forms.

The custodian will also document if sufficient sample volume has been received to complete the analytical program. The Sample Custodian will then place the samples into secure, limited-access storage (refrigerated storage, if required). The Sample Custodian will assign a unique number to each incoming sample for use in the laboratory. The unique number will then be entered into the sample-receiving log, with the verified time and date of receipt also noted.

Consistent with the analyses requested on the chain-of-custody form, analyses by the laboratory's analysts will begin in accordance with the appropriate methodologies. Samples will be removed from secure storage with internal chain-of-custody sign-out procedures followed.

4.3 STORAGE OF SAMPLES

Empty sample bottles will be returned to secure and limited-access storage after the available volume has been consumed by the analysis. Upon completion of the entire analytical work effort, samples will be disposed of by the Sample Custodian. The length of time that samples are held will be at least 30 days after reports have been submitted. Disposal of remaining samples will be completed in compliance with all federal, state, and local requirements.

4.4 FINAL PROJECT FILES CUSTODY PROCEDURES

The final project files will be the central repository for all documents with information relevant to sampling and analysis activities as described in this QAPP. The Haley & Aldrich of New York Project Manager will be the custodian of the project file. The project files, including all relevant records, reports, logs, field notebooks, pictures, subcontractor reports, and data reviews, will be maintained in a secured, limited-access area and under the custody of the Project Director or their designee.

The final project file will include the following:

- Project plans and drawings;
- Field data records;
- Sample identification documents and soil boring/monitoring well logs;
- All chain-of-custody documentation;
- Correspondence;
- References, literature;
- Laboratory data deliverables;
- Data validation and assessment reports;
- Progress reports, QA reports; and

- Final report.

The laboratory will be responsible for maintaining analytical logbooks, laboratory data, and sample chain-of-custody documents. Raw laboratory data files and copies of hard copy reports will be inventoried and maintained by the laboratory for a period of six years, at which time the laboratory will contact the Haley & Aldrich of New York Project Manager regarding the disposition of the project-related files.

5. Calibration Procedures and Frequency

5.1 FIELD INSTRUMENT CALIBRATION PROCEDURES

Several field instruments will be used for both on-site screening of samples and for health and safety monitoring, as described in the HASP. On-site air monitoring for health and safety purposes may be accomplished using a vapor detection device, such as a photoionization detector (PID).

Field instruments will be calibrated at the beginning of each day and checked during field activities to verify performance. Instrument-specific calibration procedures will be performed in accordance with the instrument manufacturer's requirements.

5.2 LABORATORY INSTRUMENT CALIBRATION PROCEDURES

Reference materials of known purity and quality will be utilized for the analysis of environmental samples. The laboratory will carefully monitor the preparation and use of reference materials, including solutions, standards, and reagents, through well-documented procedures.

All solid chemicals and acids/bases used by the laboratory will be rated as "reagent grade" or better. All gases will be "high" purity or better. All Standard Reference Materials (SRMs) or Performance Evaluation (PE) materials will be obtained from approved vendors of the National Institute of Standards and Technology (NIST; formerly National Bureau of Standards), the EPA Environmental Monitoring Support Laboratories (EMSL), or reliable Cooperative Research and Development Agreement (CRADA)-certified commercial sources.

6. Analytical Procedures

Analytical procedures to be utilized for analysis of environmental samples will be based on referenced EPA analytical protocols and/or project-specific SOPs.

6.1 FIELD ANALYTICAL PROCEDURES

Field analytical procedures include the measurement of pH, temperature, oxidation-reduction potential (ORP), dissolved oxygen (DO), and specific conductivity during sampling of groundwater, and the qualitative measurement of VOCs during the collection of soil samples.

6.2 LABORATORY ANALYTICAL PROCEDURES

Laboratory analyses will be based on the EPA methodology requirements promulgated in:

- "Test Methods for Evaluating Solid Waste," SW-846, EPA, Office of Solid Waste, and promulgated updates, 1986.

6.2.1 List of Project Target Compounds and Laboratory Detection Limits

The method detection limits (MDLs) studies are performed by the laboratories in accordance with the procedures established in the Code of Federal Regulations, Title 40, Part 136.

Laboratory parameters for soil samples are listed in the IRMWP. Laboratory parameters for disposal samples will be determined by the disposal facility after an approved facility has been determined.

6.2.2 List of Method-Specific Quality Control Criteria

The laboratory SOPs include a section that presents the minimum QC requirements for the project analyses. Section 7.0 references the frequency of the associated QC samples for each sampling effort and matrix.

7. Internal Quality Control Checks

This section presents the internal QC checks that will be employed for field and laboratory measurements.

7.1 FIELD QUALITY CONTROL

7.1.1 Field Blanks

Internal QC checks will include analysis of field blanks to validate equipment cleanliness. Whenever possible, dedicated equipment will be employed to reduce the possibility of cross-contamination of samples.

7.1.2 Trip Blanks

Trip blanks samples will be prepared by the project laboratory using ASTM International (ASTM) Type II or equivalent water placed within pre-cleaned 40-milliliter (mL) VOC vials equipped with Teflon septa. Trip blanks will accompany each sample delivery group (SDG) of environmental samples collected for analysis of VOCs.

Trip blank samples will be placed in each cooler that stores and transports project samples that are to be analyzed for VOCs.

7.2 LABORATORY PROCEDURES

Procedures which contribute to maintenance of overall laboratory QA/QC include appropriately cleaned sample containers, proper sample identification and logging, applicable sample preservation, storage, and analysis within prescribed holding times, and use of controlled materials.

7.2.1 Field Duplicate Samples

The precision or reproducibility of the data generated will be monitored through the use of field duplicate samples. Field duplicate analysis will be performed at a frequency of one in 20 project samples.

Precision will be measured in terms of the absolute value of the relative percent difference (RPD) as expressed by the following equation:

$$RPD = [|R1-R2|/[(R1+R2)/2]] \; X \; 100\%$$

Acceptance criteria for duplicate analyses performed on solid matrices will be 100 percent, air matrices will be 35 percent, and aqueous matrices will be 35 percent (or the absolute difference rule was satisfied if detects were less than five times the Reporting Limit [RL] for solid and aqueous matrices only). RPD values outside these limits will require an evaluation of the sampling and/or analysis procedures by the project QA Officer and/or laboratory QA Director. Corrective actions may include re-analysis of additional sample aliquots and/or qualification of the data for use.

7.2.2 Matrix Spike Samples

Ten percent of each project sample matrix for each analytical method performed will be spiked with known concentrations of the specific target compounds/analytes.

The amount of the compound recovered from the sample compared to the amount added will be expressed as a percent recovery. The percent recovery of an analyte is an indication of the accuracy of an analysis within the site-specific sample matrix. Percent recovery will be calculated for matrix spike and matrix spike duplicate (MS/MSD) samples using the following equation.

$$\%\ Recovery = \frac{Spiked\ Sample - Background}{Known\ Value\ of\ Spike} x100\%$$

If the QC value falls outside the control limits (Upper Control Limit [UCL] or Lower Control Limit [LCL]) due to sample matrix effects, the results will be reported with appropriate data qualifiers. To determine the effect a non-compliant MS recovery has on the reported results, the recovery data will be evaluated as part of the validation process.

7.2.3 Laboratory Control Sample Analyses

The laboratory will perform Laboratory Control Sample (LCS) analyses prepared from SRMs. The SRMs will be supplied from an independent manufacturer and traceable to NIST materials with known concentrations of each target analyte to be determined by the analytical methods performed. In cases where an independently supplied SRM is not available, the LCS may be prepared by the laboratory from a reagent lot other than that used for instrument calibration.

The laboratory will evaluate LCS analyses in terms of percent recovery using the most recent laboratory-generated control limits.

LCS recoveries that do not meet acceptance criteria will be deemed invalid. Analysis of project samples will cease until an acceptable LCS analysis has been performed. If sample analysis is performed in association with an out-of-control LCS sample analysis, the data will be deemed invalid.

Corrective actions will be initiated by the Haley & Aldrich of New York QA Officer and/or Laboratory QA Officer to investigate the problem. After the problem has been identified and corrected, the solution will be noted in the instrument run logbook, and re-analysis of project samples will be performed, if possible.

The analytical anomaly will be noted in the SDG Case Narrative and reviewed by the Data Validator. The Data Validator will confirm that appropriate corrective actions were implemented and recommend the applicable use of the affected data.

7.2.4 Surrogate Compound/Internal Standard Recoveries

For VOCs, surrogates will be added to each sample prior to analysis to establish purge and trap efficiency. Quantitation will be accomplished via internal standardization techniques.

The recovery of surrogate compounds and internal standards will be monitored by laboratory personnel to assess possible Site-specific matrix effects on instrument performance.

For SVOC analyses, surrogates will be added to the raw sample to assess extraction efficiency. Internal standards will be added to all sample extracts and instrument calibration standards immediately before analysis for quantitation via internal standardization techniques.

Method-specific QC limits are provided in the attached laboratory method SOPs. Surrogate compound/internal standard recoveries that do not fall within accepted QC limits for the analytical methodology performed will have the analytical results flagged with data qualifiers as appropriate by the laboratory and will not be noted in the laboratory report Case Narrative.

To ascertain the effect non-compliant surrogate compound/internal standard recoveries may have on the reported results, the recovery data will be evaluated as part of the validation process. The Data Validator will provide recommendations for corrective actions, including but not limited to additional data qualification.

7.2.5 Calibration Verification Standards

Calibration verification (CV) standards will be utilized to confirm instrument calibrations and performance throughout the analytical process. CV standards will be prepared as prescribed by the respective analytical protocols. Continuing calibration will be verified by compliance with method-specific criteria prior to additional analysis of project samples.

Non-compliant analysis of CV standards will require immediate corrective action by the project laboratory QA Officer and/or designated personnel. Corrective action may include re-analysis of each affected project sample, a detailed description of the problem, the corrective action undertaken, the person who performed the action, and the resolution of the problem.

7.2.6 Laboratory Method Blank Analyses

Method blank sample analysis will be performed as part of each analytical batch for each methodology performed. If target compounds are detected in the method blank samples, the reported results will be flagged by the laboratory in accordance with SOPs. The Data Validator will provide recommendations for corrective actions, including but not limited to additional data qualification.

8. Data Quality Objectives

Sampling that will be performed as described in the IRMWP is designed to produce data of the quality necessary to achieve the minimum standard requirements of the field and laboratory analytical objectives described below. These data are being obtained with the primary objective of assessing levels of contaminants of concern associated with the Site.

The overall project data quality objective (DQO) is to implement procedures for field data collection, sample collection, handling, and laboratory analysis and reporting that achieve the project objectives. The following section is a general discussion of the criteria that will be used to measure the achievement of the project DQO.

8.1 PRECISION

8.1.1 Definition

Precision is defined as a quantitative measure of the degree to which two or more measurements are in agreement. Precision will be determined by collecting and analyzing field duplicate samples and by creating and analyzing laboratory duplicates from one or more of the field samples. The overall precision of measurement data is a mixture of sampling and analytical factors. The analytical results from the field duplicate samples will provide data on sampling precision. The results from duplicate samples created by the laboratory will provide data on analytical precision. The measurement of precision will be stated in terms of RPD. RPD is defined as the absolute difference of duplicate measurements divided by the mean of these analyses, normalized to a percentage.

8.1.2 Field Precision Sample Objectives

Field precision will be assessed through collection and measurement of field duplicate samples at a rate of one duplicate per 20 investigative samples. The RPD criteria for the project field duplicate samples will be +/- 100 percent for soil, +/- 35 percent for groundwater for parameters of analysis detected at concentrations greater than five times the laboratory RL, and +/- 35 percent for air for parameters of analysis detected at any concentration.

8.1.3 Laboratory Precision Sample Objectives

Laboratory precision will be assessed through the analysis of LCS and laboratory control sample duplicate (LCSD) and MS/MSD samples for groundwater and soil samples, and the analysis of laboratory duplicate samples for air and soil vapor samples. Air and soil vapor laboratory duplicate sample analyses will be performed by analyzing the same Summa canister twice. The RPD criteria for the air/soil vapor laboratory duplicate samples will be +/- 35 percent for parameters of analysis detected at concentrations greater than five times the laboratory RL.

8.2 ACCURACY

8.2.1 Definition

Accuracy relates to the bias in a measurement system. Bias is the difference between the observed and the "true" value. Sources of error are the sampling process, field contamination, preservation techniques, sample handling, sample matrix, sample preparation, and analytical procedure limitations.

8.2.2 Field Accuracy Objectives

Sampling bias will be assessed by evaluating the results of the field equipment rinse and trip blanks. Equipment rinse and trip blanks will be collected as appropriate based on sampling and analytical methods for each sampling effort.

If non-dedicated sampling equipment is used, equipment rinse blanks will be collected by passing ASTM Type II water over and/or through the respective sampling equipment utilized during each sampling effort. One equipment rinse blank will be collected for each type of non-dedicated sampling equipment used for the sampling effort. Equipment rinse blanks will be analyzed for each target parameter for the respective sampling effort for which environmental media have been collected. (Note: If dedicated or disposable sampling equipment is used, equipment rinse samples will not be collected as part of that field effort.)

Trip blank samples will be prepared by the laboratory and provided with each shipping container, which includes containers for the collection of groundwater samples for the analysis of VOCs. Trip blank samples will be analyzed for each VOC for which groundwater samples have been collected for analysis.

8.3 LABORATORY ACCURACY OBJECTIVES

Analytical bias will be assessed through the use of LCS and Site-specific MS sample analyses. LCS analyses will be performed with each analytical batch of project samples to determine the accuracy of the analytical system.

One set of MS/MSD analyses will be performed with each batch of 20 project samples collected for analysis to assess the accuracy of the identification and quantification of analytes within the Site-specific sample matrices. Additional sample volume will be collected at sample locations selected for the preparation of MS/MSD samples so that the standard laboratory RLs are achieved.

The accuracy of analyses that include a sample extraction procedure will be evaluated through the use of system monitoring or surrogate compounds. Surrogate compounds will be added to each sample, standard, blank, and QC sample prior to sample preparation and analysis. Surrogate compound percent recoveries will provide information on the effect of the sample matrix on the accuracy of the analyses.

8.4 REPRESENTATIVENESS

8.4.1 Definition

Representativeness expresses the degree to which sample data represent a characteristic of a population, a parameter variation at a sampling point, or an environmental condition. Representativeness is a qualitative parameter that is dependent upon the design of the sampling program. The representativeness criterion is satisfied through the proper selection of sampling locations, the quantity of samples, and the use of appropriate procedures to collect and analyze the samples.

8.4.2 Measures to Ensure Representativeness of Field Data

Representativeness will be addressed by prescribing sampling techniques and the rationale used to select sampling locations. Sampling locations may be biased (based on existing data, instrument surveys, observations, etc.) or unbiased (completely random or stratified-random approaches).

8.5 COMPLETENESS

8.5.1 Definition

Completeness is a measure of the amount of valid (usable) data obtained from a measuring system compared to the total amount anticipated to be obtained. The completeness goal for all data uses is that a sufficient amount of valid data be generated so that determinations can be made related to the intended data use with a sufficient degree of confidence. Valid data are determined by independent confirmation of compliance with method-specific and project-specific DQOs. The calculation of data set completeness will be performed by the following equation.

$$\frac{Number\ of\ Valid\ Sample\ Results}{Total\ Number\ of\ Samples\ Planned}\ X\ 100 = \%\ Complete$$

8.5.2 Field Completeness Objectives

Completeness is a measure of the number of valid measurements obtained from measurements taken in this project versus the number planned. Field completeness objective for this project will be greater than 90 percent.

8.5.3 Laboratory Completeness Objectives

Laboratory data completeness objective is a measure of the amount of valid data obtained from laboratory measurements. The evaluation of the data completeness will be performed at the conclusion of each sampling and analysis effort.

The completeness of the data generated will be determined by comparing the amount of valid data, based on independent validation, with the total laboratory data set. The completeness goal will be greater than 90 percent.

8.6 COMPARABILITY

8.6.1 Definition

Comparability is a qualitative parameter expressing the confidence with which one data set can be compared to another.

8.6.2 Measures to Ensure Comparability of Laboratory Data

Comparability of laboratory data will be measured from the analysis of SRMs obtained from either EPA CRADA suppliers or the NIST. The reported analytical data will also be presented in standard units of mass of contaminant within a known volume of environmental media. The standard units for various sample matrices are as follows:

- Solid Matrices – micrograms per kilogram (µg/kg) for PFAS analyses, milligrams per kilogram (mg/kg) of media (Dry Weight).

8.7 LEVEL OF QUALITY CONTROL EFFORT

If non-dedicated sampling equipment is used, equipment rinse blanks will be prepared by field personnel and submitted for analysis of target parameters. Equipment rinse blank samples will be analyzed to check for potential cross-contamination between sampling locations that may be introduced during the investigation. One equipment rinse blank will be collected per sampling event to the extent that non-dedicated sampling equipment is used.

If necessary, a separate equipment rinse blank sample will be collected for PFAS to assess potential contamination introduced from utilized equipment. (Note: If dedicated or disposable sampling equipment is used, equipment rinse samples will not be collected as part of that field effort.)

Trip blanks will be used to assess the potential for contamination during sample storage and shipment. Trip blanks will be provided with the sample containers to be used for the collection of groundwater samples for the analysis of VOCs. Trip blanks will be preserved and handled in the same manner as the project samples. One trip blank will be included along with each shipping container containing project samples to be analyzed for VOCs.

Method blank samples will be prepared by the laboratory and analyzed concurrently with all project samples to assess potential contamination introduced during the analytical process.

Field duplicate samples will be collected and analyzed to determine sampling and analytical reproducibility. One field duplicate will be collected for every 20 or fewer investigative samples collected for off-Site laboratory analysis.

MS will provide information to assess the precision and accuracy of the analysis of the target parameters within the environmental media collected. One MS/MSD will be collected for every 20 or fewer investigative samples per sample matrix.

Note: Soil MS/MSD samples require triple sample volume for VOCs only.

9. Data Reduction, Validation, and Reporting

Data generated by the laboratory operation will be reduced and validated prior to reporting in accordance with the following procedures:

9.1 DATA REDUCTION

9.1.1 Field Data Reduction Procedures

Field data reduction procedures will be minimal in scope compared to those implemented in the laboratory setting. The pH, conductivity, temperature, turbidity, DO, ORP, and breathing zone VOC readings collected in the field will be generated from direct read instruments. The data will be written into field logbooks immediately after measurements are taken. If errors are made, data will be legibly crossed out, initialed, and dated by the field member, and corrected in a space adjacent to the original entry.

9.1.2 Laboratory Data Reduction Procedures

Laboratory data reduction procedures are provided by the appropriate chapter of the EPA's "Test Methods for Evaluating Solid Waste," SW-846, Third Edition. Errors will be noted and corrections made with the original notations crossed out legibly. Analytical results for soil samples will be calculated and reported on a dry weight basis.

9.1.3 Quality Control Data

QC data (e.g., laboratory duplicates, surrogates, MS, and MSD) will be compared to the method acceptance criteria. Data determined to be acceptable will be entered into the laboratory information management system.

Unacceptable data will be appropriately qualified in the project report. Case Narratives will be prepared, which will include information concerning data that fell outside acceptance limits and any other anomalous conditions encountered during sample analysis.

9.2 DATA VALIDATION

Data validation procedures of the analytical data will be performed by the Haley & Aldrich of New York QA Officer or designee using the following documents as guidance for the review process:

- "U.S. EPA National Functional Guidelines for Organic Data Review," "Analysis of Volatile Organic Compounds in Air Contained in Canisters by Method TO-15," "Sampling, Analysis, and Assessment of Per- and Polyfluoroalkyl Substances Under NYSDEC's Part 375 Remedial Programs," and the "U.S. EPA National Functional Guidelines for Inorganic Data Review."
- The specific data qualifiers used will be applied to the reported results as presented and defined in the EPA National Functional Guidelines. Validation will be performed by qualified personnel at the direction of the Haley & Aldrich of New York QA Officer. Tier 1 data validation (the equivalent of EPA's Stage 2A validation) will be performed to evaluate data quality.

- The completeness of each data package will be evaluated by the Data Validator. Completeness checks will be administered on all data to determine that the deliverables are consistent with the NYSDEC Analytical Services Protocol (ASP) Category A and Category B data package requirements. The validator will determine whether the required items are present and request copies of missing deliverables (if necessary) from the laboratory.

9.3 DATA REPORTING

Data reporting procedures will be carried out for field and laboratory operations as indicated below:

- Field Data Reporting: Field data reporting will be conducted principally through the transmission of report sheets containing tabulated results of measurements made in the field and documentation of field calibration activities.
- Laboratory Data Reporting: The laboratory data reporting package will enable data validation based on the protocols described above. The final laboratory data report format will include the QA/QC sample analysis deliverables to enable the development of a DUSR based on NYSDEC DER-10, Appendix 2B.

10. Performance and System Audits

A performance audit is an independent quantitative comparison with data routinely obtained in the field or the laboratory. Performance audits include two separate, independent parts: internal and external audits.

10.1 FIELD PERFORMANCE AND SYSTEM AUDITS

10.1.1 Internal Field Audit Responsibilities

Internal audits of field activities will be initiated at the discretion of the Project Manager and will include the review of sampling and field measurements. The audits will verify that all procedures are being followed. Internal field audits will be conducted periodically during the project. The audits will include examination of the following:

- Field sampling records, screening results, and instrument operating records;
- Sample collection;
- Handling and packaging in compliance with procedures;
- Maintenance of QA procedures; and
- Chain-of-custody reports.

10.1.2 External Field Audit Responsibilities

External audits may be conducted by the Project Coordinator at any time during the field operations. These audits may or may not be announced and are at the discretion of the NYSDEC. The external field audits can include (but are not limited to) the following:

- Sampling equipment decontamination procedures;
- Sample bottle preparation procedures;
- Sampling procedures;
- Examination of HASPs;
- Procedures for verification of field duplicates; and
- Field screening practices.

10.2 LABORATORY PERFORMANCE AND SYSTEM AUDITS

10.2.1 Internal Laboratory Audit Responsibilities

The laboratory system audits are typically conducted by the laboratory QA Officer or designee on an annual basis. The system audit will include an examination of laboratory documentation, including sample receiving logs, sample storage, chain-of-custody procedures, sample preparation and analysis, and instrument operating records.

At the conclusion of internal system audits, reports will be provided to the laboratory's operating divisions for appropriate comment and remedial/corrective action where necessary. Records of audits and corrective actions will be maintained by the Laboratory QA Officer.

10.2.2 External Laboratory Audit Responsibilities

External audits will be conducted as required by the NYSDEC, NYSDOH, or designee. External audits may include any of the following:

- Review of laboratory analytical procedures
- Laboratory on-site visits
- Submission of performance evaluation samples for analysis

Failure of any of the above audit procedures can lead to laboratory de-certification. An audit may consist of, but not be limited to:

- Sample receipt procedures
- Custody, sample security, and log-in procedures
- Review of instrument calibration logs
- Review of QA procedures
- Review of logbooks
- Review of analytical SOPs
- Personnel interviews

A review of a data package from samples recently analyzed by the laboratory can include (but not be limited to) the following:

- Comparison of the resulting data to the SOP or method
- Verification of initial and continuing calibrations within control limits
- Verification of surrogate recoveries and instrument timing results
- Review of extended quantitation reports for comparisons of library spectra to instrument spectra, where applicable
- Assurance that samples are run within holding times

11. Preventive Maintenance

11.1 FIELD INSTRUMENT PREVENTIVE MAINTENANCE

The field equipment preventive maintenance program is designed to ensure the effective completion of the sampling effort and to minimize equipment downtime. Program implementation is concentrated in three areas:

- Maintenance responsibilities
- Maintenance schedules
- Inventory of critical spare parts and equipment

The maintenance responsibilities for field equipment will be assigned to the task leaders in charge of specific field operations. Field personnel will be responsible for daily field checks and calibrations and for reporting any problems with the equipment. The maintenance schedule will follow the manufacturer's recommendations. In addition, the field personnel will be responsible for determining that an inventory of spare parts will be maintained with the field equipment. The inventory will primarily contain parts that are subject to frequent failure, have limited useful lifetimes, and/or cannot be obtained in a timely manner.

11.2 LABORATORY INSTRUMENT PREVENTIVE MAINTENANCE

Analytical instruments at the laboratory will undergo routine and/or preventive maintenance. The extent of the preventive maintenance will be a function of the complexity of the equipment.

Generally, annual preventive maintenance service will involve cleaning, adjusting, inspecting, and testing procedures designed to deduce instrument failure and/or extend useful instrument life. Between visits, routine operator maintenance and cleaning will be performed according to manufacturer's specifications by laboratory personnel.

12. Specific Routine Procedures Used to Assess Data Precision, Accuracy, and Completeness

12.1 FIELD MEASUREMENTS

Field-generated information will be reviewed by the Field Coordinator and typically includes evaluation of bound logbooks/forms, data entry, and calculation checks. Field data will be assessed by the Project Coordinator, who will review the field results for compliance with the established QC criteria that are specified in Sections 7.0 and 8.0 of this QAPP. The accuracy of pH and specific conductance will be assessed using daily instrument calibration, calibration check, and blank data. Accuracy will be measured by determining the percent recovery (% R) of calibration check standards. Precision of the pH and specific conductance measurements will be assessed on the basis of the reproducibility of duplicate readings of a field sample and will be measured by determining the RPD. Accuracy and precision of the soil VOC screening will be determined using duplicate readings of calibration checks. Field data completeness will be calculated using the following equation:

$$Completeness = \frac{Valid\ (usable)\ Data\ Obtained}{Total\ Data\ Planned} \ X\ 100$$

12.2 LABORATORY DATA

Laboratory data will be assessed by the Haley & Aldrich of New York QA Officer or designee, who will review the laboratory results for compliance with the established QC criteria that are specified in Sections 7.0 and 8.0 of this QAPP.

13. Quality Assurance Reports

Critically important to the successful implementation of the QAPP is a reporting system that provides the means by which the program can be reviewed, problems identified, and programmatic changes made to improve the plan.

QA reports to management can include:

- Audit reports, internal and external audits, with responses
- Performance evaluation sample results: internal and external sources
- Daily QA/QC exception reports/corrective actions

QA/QC corrective action reports will be prepared by the Haley & Aldrich of New York QA Officer when appropriate and presented to the project and/or laboratory management personnel so that performance criteria can be monitored for all analyses from each analytical department. The updated trend/QA charts prepared by the laboratory QA personnel will be distributed and reviewed by various levels of the laboratory management.

References

1. New York State Department of Environmental Conservation, NYSDEC Analytical Services Protocol (ASP), Bureau of Environmental Investigation, 1991 with updates.

2. New York State Department of Environmental Conservation, NYSDEC, Division of Environmental Remediation, Technical Guidance for Site Investigation and Remediation, DER-10, May 2010.

3. New York State Department of Environmental Conservation, NYSDEC, Division of Environmental Remediation, Sampling, Analysis and Assessment of Per- and Polyfluoroalkyl Substances (PFAS) under NYSDEC Part 375 Remedial Program, April 2023.

4. United States Environmental Protection Agency (1991). Preparation Aids for the Development of Category I Quality Assurance Project Plans. U.S. EPA/600/8-91/003, Risk Reduction Engineering Laboratory, Office of Research and Development, Cincinnati, Ohio, February 1991.

5. United States Environmental Protection Agency, (1992). Specifications and Guidance for Contaminant-Free Sample Containers. OSWER Directive 9240.0-05A, April 1992.

6. United States Environmental Protection Agency, (1993). Data Quality Objectives Process for Superfund Interim Final Guidance. U.S. EPA/540/R-93-071, Office of Solid Waste and Emergency Response (OSWER), September 1993.

7. United States Environmental Protection Agency, (1999). EPA Requirements for Quality Assurance Project Plans for Environmental Data Operations. EPA QA/R-5 Interim Final, November 1999.

8. United States Environmental Protection Agency. Test Methods for Evaluating Solid Waste, Office of Solid Waste, U.S. EPA, SW-846, November 1986, with updates.

9. United States Environmental Protection Agency. U.S. EPA National Functional Guidelines for Organic Data Review. U.S. EPA 540/R-2017-002.

10. United States Environmental Protection Agency. U.S. EPA National Functional Guidelines for Organic Data Review. U.S. EPA 540/R-2017-001.

TABLE

TABLE I
SUMMARY OF ANALYSIS METHOD, PRESERVATION METHOD, HOLDING TIME, SAMPLE SIZE REQUIREMENTS, AND SAMPLE CONTAINERS
4001 4TH AVENUE REDEVELOPMENT SITE
4001-4011 4TH AVENUE
BROOKLYN, NEW YORK

Analysis/Method[2]	Sample Type	Preservation	Holding Time	Volume/Weight	Container[3]
Volatile Organic Compounds/8260	Soil	1 - 1 Vial MeOH/2 Vial Water, Cool, 4 ± 2 °C	14 days[1]	120 mL	3 - 40ml glass vials
Semivolatile Organic Compounds/8270	Soil	Cool, 4 ± 2 °C	14 days extraction / 40 days analysis	250 mL	1 - 8 oz Glass
Pesticides/8081	Soil	Cool, 4 ± 2 °C	14 days extraction / 40 days analysis	250 mL	1 - 4 oz Glass
Polychlorinated Biphenyls/8082	Soil	Cool, 4 ± 2 °C	14 days extraction / 40 days analysis	250 mL	1 - 4 oz Glass
TAL Metals/6010	Soil	Cool, 4 ± 2 °C	180 days	60 mL	1 - 4 oz Glass
PFAS/1633A	Soil	Cool, 4 ± 2 °C	28 days extraction / 40 days analysis	To be determined by laboratory	1 - HDPE container
1,4-Dioxane/8270 SIM	Soil	Cool, 4 ± 2 °C	14 days extraction / 40 days analysis	250 mL	1 - 8 oz Glass

Notes:

1. Terracores and encores must be frozen within 48 hours of collection

2. Equivalent method can be used.

3. Volume may vary by laboratory and/or equivalent method.

ATTACHMENT A
Project Team Resumes

SUZANNE BELL, PE

Program Manager, Environmental Engineer

EDUCATION

BS, Biosystems Engineering, University of Arizona

PROFESSIONAL REGISTRATIONS

AZ: Environmental Engineer (Reg. No. 61995)
NY: Professional Engineer (Reg No. 106301)

PROFESSIONAL COMMITTEES

American Council of Engineering Companies of New York – New York State Department of Environmental Conservation Committee Member – 2024-2025

SPECIAL STUDIES AND COURSES

40-Hour OSHA Hazardous Waste and Operations Emergency Response Training (29 CFR 1910.120 and 40 CFR 265.16)
8-Hour HAZWOPER Refresher Course

Suzanne is a senior project manager with over 17 years of experience in the environmental consulting industry. She has worked on soil and groundwater environmental investigations, remediation projects, and prepared reports for private, industrial, and government clients. Her technical experience includes remediation systems; soil and groundwater feasibility studies; Phase I site investigations; environmental file review and historical research; stormwater assessments and SWPPP preparation; reclamation planning for the sand and gravel mining industry; air permitting; and data interpretation.

In New York, Suzanne has experience as an Engineer of Record in completing site closure documentation including Remedial Closure Reports reviewed by the Office of Environmental Remediation as well as Final Engineering Reports and Site Management Plans reviewed by the New York State Department of Environmental Conservation.

Suzanne has managed the investigation, remedial design, remediation and closeout of sites in the Brownfield Cleanup Program and petroleum spill case sites. Her background also includes developing and complying with approved site management plans overseeing the operation and maintenance of on-site engineering controls, such as soil vapor extraction systems, sub-slab depressurization systems, product recovery systems, and ensuring the protection of human health and the environment.

RELEVANT PROJECT EXPERIENCE

Bedford Beverly Redevelopment Site, Brooklyn, New York. Suzanne served as engineer of record for execution of Remedial Action Work Plans for an approximately 5.31-acre non-contiguous property located in the Flatbush neighborhood in the borough of Brooklyn, New York under the New York State Brownfield Cleanup Program (NYSBCP). The remedy included removal of thirteen undocumented underground storage tanks (USTs), removal of over 115,000 tons of non-hazardous and hazardous soil, hotspot excavations, injections of zerovalent iron to treat tetrachlorethylene in groundwater, injection of alkaline-activated persulfate to treat petroleum-based volatile organic compounds in groundwater and establishing a Site Management Plan (SMP) for Institutional and Engineering Controls. The site is being redeveloped from a vacant auto service center, vast open air parking lots, and a vacant commercial building into a vibrant community development. In addition to new residential housing, which includes affordable units, and commercial spaces, the project has preserved the highly recognizable Sears Roebuck & Company Department Store. This includes maintaining its historical architecture, updating the building to meet modern standards, introducing commercial spaces that were previously underutilizing, and maintaining the character of the neighborhood.

Development, EPA Site RCRA-02-2009-7306, NYSDEC Site 243016, Former Port Mobil Terminal, Staten Island, New York. Engineer and project manager responsible for the preparation of the feasibility study, preparation of the Interim Remedial Report, completion of the Interim Remedial Measure, completion of the remedial investigation stages, continued execution of the Monitoring and Natural Attenuation Program, preparation of the Remedial Action Work Plan/Remedial Designs, and RCRA Closure procedures for the Port Mobil Terminal Site under an Environmental Protection Agency and New York State DEC Consent Order. The Site has a footprint of approximately 240 acres with a planned development for commercial/industrial uses.

Rogers Snyder Brownfield Site, 858 Rogers Avenue and 2605 Snyder Avenue, Brooklyn, New York. Suzanne served as engineer of record for execution of Remedial Action Work Plan at the Rogers Snyder redevelopment project under the NYSBCP. Responsible for remedial oversight of excavation and removal of non-hazardous and hazardous soil, endpoint sample collection, air monitoring, communication with soil brokerage firm and environmental laboratory, preparation of the FER.

Former Garone Bros Auto Service Center Site, 352-362 Shepherd Avenue, Brooklyn, New York. Suzanne served as engineer of record for execution of Remedial Action Work Plan at the 352-362 Shepherd redevelopment project under the NYSBCP. Responsible for remedial oversight of excavation and removal of non-hazardous soil, removal of USTs, endpoint sample collection, air monitoring, communication with soil brokerage firm and environmental laboratory, preparation of the FER.

Former Fielder Waterproofing & Masonry Site, 91 Bruckner Boulevard, Bronx, New York. Suzanne served as engineer of record for execution of Remedial Action Work Plan at the 91 Bruckner redevelopment project under the NYSBCP. Responsible for remedial oversight of excavation and removal of non-hazardous and hazardous soil, removal of USTs, endpoint sample collection, air monitoring, communication with soil brokerage firm and environmental laboratory, preparation of the FER and SMP.

828 Metropolitan Avenue Site, 808-834 Metropolitan Avenue, Brooklyn, New York. Suzanne served as project manager and engineer of record for execution of Remedial Action Work Plan at the 828 Metropolitan Avenue redevelopment project under the NYSBCP. Responsible for remedial oversight of excavation and removal of non-hazardous soil, removal of USTs, endpoint sample collection, air monitoring, communication with soil brokerage firm and environmental laboratory, preparation of Daily Field Reports (DFRs) and the Final Engineering Report (FER).

Waterfront Property Management, 89-91 Gerry Street and 93 Gerry Street, Brooklyn, New York. Suzanne served as project manager for execution of Remedial Action Work Plans at the former Just4Wheels Site and Just4Wheels Site 2 under the New York State Brownfield Cleanup Program (NYSBCP). Responsible for remedial oversight of excavation and removal of non-hazardous and hazardous soil, endpoint sample collection, removal of USTs, air monitoring, dewatering system installation support, communication with soil brokerage firm and environmental laboratory, preparation of DFRs and the FER.

Multiple Clients, Remedial Investigation Work Plans and BCP Applications, New York City, New York. As project manager and engineer, Suzanne has prepared NYSBCP Applications and Remedial Investigation Work Plans for the New York State Department of Environmental Conservation (NYSDEC) for sites within the New York City boroughs.

Multiple Clients, Remedial Action Work Plans, New York City, New York. As project manager and engineer of record, Suzanne has prepared Remedial Action Work Plans for the NYSDEC for sites within the New York City boroughs.

Excavation Oversight and CAMP Monitoring, Various Sites, New York City, New York. Suzanne has served as project manager for projects under the New York City Office of Environmental Remediation (NYCOER) program and NYSBCP. Her responsibilities included managing excavation oversight, air monitoring, and logging trucks for off-site disposal.

Aerospace Manufacturing Facility, Feasibility Study and Remedial Action Plan, Chula Vista, CA. Suzanne co-authored feasibility studies for soil and ground water impacted by chlorinated solvents, metals, and PCBs. She screened ex-situ and in-situ remedial alternatives for effectiveness, implementability, and protectiveness of human health. She also assessed alternative cleanup levels for technical and economic feasibility of achieving background concentrations in accordance with State Water Resources Control Board Resolution 92-49. Additionally, she evaluated groundwater remedial alternatives, including bioremediation, monitored natural attenuation (MNA), pump and treat, chemical oxidation, chemical reduction, and engineered and institutional controls. Lastly, she prepared engineering cost estimates and conceptual designs. Assisted with the preparation of remedial action plans: a bioremediation remedy and MNA program for groundwater, and excavation of contaminated soil.

Aerospace Manufacturing Facility, Groundwater Remediation and Bioremediation Pilot Test, Riverside, CA. Suzanne assisted with data analysis and reporting for the bioremediation pilot test study for groundwater impacted by chlorinated solvents, hexavalent chromium, and 1,4-dioxane. She evaluated site data for trends indicative of MNA using statistical analysis.

Goodyear Tire & Rubber Company, Phoenix Goodyear Airport South Superfund Site, Goodyear, Arizona. Suzanne prepared reports and performed data analysis related to the groundwater monitoring program and operation and maintenance of groundwater treatment systems. Currently, two groundwater extraction and remediation systems are capable of treating more than 1 million gallons per day of groundwater contaminated with trichloroethylene. The upper groundwater zone is treated with an air stripper, while the lower zone is treated with granulated activated carbon. Treated groundwater is reinjected into their respective zones.

Soil and Groundwater Remediation Systems, Arizona. Suzanne **p**erformed operation, maintenance, and sampling activities for two soil vapor extraction systems to remove tetrachloroethylene from subsurface soils at two different dry-cleaning facilities. She prepared soil vapor extraction GAC system test reports in accordance with Maricopa County Air Quality Department Permits.

ASTM Phase I Environmental Site Assessments, Arizona. Suzanne assisted with ASTM Phase I ESAs at various industrial facilities in central and southern Arizona. She evaluated site conditions and regulatory implications as they related to the owner's or potential buyer's property development plans.

Phoenix-Goodyear Airport-North Superfund Site, Focused Feasibility Study, Goodyear, Arizona. Suzanne was a member of team that prepared a source area remediation focused feasibility study report. She evaluated several technologies and alternatives to treat groundwater contaminated with trichloroethylene (TCE) and perchlorate. She analyzed remedial alternatives, including in-well air stripping, a hydraulic barrier, nano- and macro-scale zero-valent iron, anaerobic reductive dechlorination, in-situ chemical oxidation (permanganate), and electrical resistive heating. She prepared cost estimates, conceptual designs, remediation technology summaries, and sustainability evaluation of the alternatives.

Enhanced In-Situ Bioremediation (EISB) and Chemical Reduction Using a Nanoscale, Zero-Valent Metallic Alloy to Treat Co-disposed Chloroethanes and Chloroethenes in Groundwater, Manufacturing Facility, Canton, MA. Suzanne performed data analysis and prepared status reports on effectiveness of EISB in treating chlorinated solvents in shallow groundwater. She reported on the performance monitoring results for the permeable reactive barrier in deep zone groundwater.

Hayden Facilities RI/FS, ASARCO LLC, Hayden, Arizona. Suzanne served as Quality Assurance Officer for the air monitoring program at a copper smelting facility. She developed site-specific data validation procedures according EPA guidelines for several analytical methods.

Market Evaluation for Nanoscale Zero-Valent Iron, Stamford, Connecticut. Suzanne used EPA CERCLIS Public Access Database and select State databases to estimate the market size for potential use of nanoscale zero-valent iron (nZVI) as a remediation technology. She compiled competing vendor information and quotes to estimate the average cost of similar products. She utilized the U.S. Patent and Trademark Office database to analyze competing technologies.

Arizona Pollutant Discharge Elimination System (AZPDES) and National Pollutant Discharge Elimination System (NPDES) Permits, Arizona. Suzanne prepared AZPDES and NPDES) permit renewal applications for a copper mining facility in Southern Arizona, which included updates to the facility's Storm Water Pollution Prevention Plan (SWPPP) and QA Manual.

Spill Prevention, Control and Countermeasure Plans, Aggregate Mining Facilities, Arizona. Suzanne assisted with a Spill Prevention, Control and Countermeasure Plans (SPCC) for aggregate mining facilities in Arizona. She performed site visit, evaluated fuel and oil tanks and secondary containment areas, assisted with calculations to verify compliance, and prepared report.

Copper Mining Facility, Miami, Arizona. Suzanne assisted with Toxic Release Inventory (TRI) and Toxic Substances Control Act (TSCA) reporting, both submitted to the EPA.

Storm Water Pollution Prevention Plan, Franciscan Friars of California, Gila County, Arizona. Suzanne updated the SWPPP for construction activities related to the closure of a historic Gibson copper mine, authorized under the Arizona Pollutant Discharge Elimination System "General Permit for Discharge from Construction Activities to Waters of the United States." The Former Gibson Mine is a small, historic copper mine, located approximately 7 miles southwest of Miami, Arizona, in Gila County. Construction activities covered under the updated SWPPP consisted of the excavation, hauling, and removal of approximately 80,000 tons of soil cover from the Mineral Creek side of the site to mine-scarred areas on the Pinto Creek side of the site. Also included was final grading of the site, which consisted of re-contouring and re-defining any portion of the drainages that were on site; and revegetation.

Stormwater Pollution Prevention Plans, Vulcan Materials Company, Western Division, Arizona. Suzanne prepared SWPPP for 11 aggregate mining facilities in Arizona. Performed site visits, analyzed stormwater flows, prepared reports, and completed Notices of Intent for the Arizona Department of Environmental Quality under a Multi-Sector General Permit.

Uranium Enrichment Facility, Lea County, New Mexico. Suzanne prepared quarterly and annual groundwater monitoring reports, semi-annual radioactive effluent release reports, and radiological environmental monitoring program reports in accordance with New Mexico Environment Department regulations and the Nuclear Regulatory Commission. Performed quarterly data validation on a variety of matrices and analytical methods. She prepared site-specific environmental monitoring procedures, which included field sampling techniques; data collection, management and validation; and an air modeling software package.

Rocket Testing and Research Facility, Western U.S. Suzanne analyzed and evaluated groundwater quality data, prepared reports, and managed data for this Resource Conservation and Recovery Act (RCRA) site. Assisted with management of sampling, analysis, and reporting of constituents of concern for fractured sandstone bedrock aquifer impacted by chlorinated solvents and emergent chemicals 1,4-dioxane, perchlorate, and n-nitrosodimethylamine (NDMA). Performed data validation of water quality data according to U.S. EPA National Functional Guidelines. Queried data from client environmental data management system and prepared summary tables, concentration plots, and water level hydrographs using Microsoft Excel programs. She prepared a quarterly analytical schedule using an Access database application, updated the site-specific Health & Safety Plan, and participated in lean training, which reduced cost of groundwater monitoring tasks by 25 percent.

Federal Superfund Site, Eastern Massachusetts. Suzanne performed data validation and quality assurance/quality control of soil and groundwater data according to U.S. EPA National Functional Guidelines. She performed third-party database updates.

Great Western Bank, Cortaro Ranch Property, Marana, Arizona. For site characterization of undeveloped land, Suzanne performed surficial soil sampling, analytical laboratory coordination, data analysis, and report preparation.

Twin Buttes Properties, Inc., Southern Arizona. Suzanne assisted with report and analytical table preparation for the characterization and analysis of current and historical hydrologic conditions at an inactive mine site near Sahuarita, Arizona in support of regulatory compliance.

Skyworks Solutions, Inc. Site, Newbury Park, California. Suzanne assisted with report and analytical table preparation for a subsurface investigation characterizing the lateral and vertical extent of soil and groundwater impacts from known releases of TCE, 1,4-dioxane and other organic compounds.

PUBLICATIONS

"Mixed Redox Catalytic Destruction of Chlorinated Solvents in Soils and Groundwater," with S. Gao, E. Rupp, M. Willinger, T. Foley, B. Barbaris, A.E., Saez, R.G. Arnold and E. Betterton. In Environmental Challenges in The Pacific Basin, 2008; Annals of the New York Academy of Sciences, Vol. 1140, pp 435-445. PMID: 18991945

INVITED LECTURER OR SPEAKER

"Catalytic Destruction of Perchloroethylene," with E. Betterton, R. Arnold and Eduardo Saez, Presenter - NASA Space Grant Student Symposium, Phoenix, Arizona. April 2007.



MARI C. CONLON

Senior Client Account Manager

EDUCATION

MS, Geology, Boston College

BS, Geology with a minor in Economics and Business, Lafayette College

PROFESSIONAL REGISTRATIONS

NY: Professional Geologist (License No. 000769)

PROFESSIONAL SOCIETIES

Big Apple Brownfield Awards, Co-Chair, 2018-2022

Big Apple Brownfield Awards Nomination Committee, 2016-2025

New York City Brownfield Partnership Executive Board, 2021-2025

SPECIAL STUDIES AND COURSES

40-Hour OSHA Hazardous Waste Operations and Emergency Response Training (29 CFR 1910.120)

10-Hour OSHA Construction Safety

8-Hour OSHA Supervisor of Hazardous Waste (29 CFR 1910.120 & 29 CFR 1926.65)

Mari is a senior client account manager with experience in soil, groundwater and soil vapor investigation and a focus on remedial design and implementation. She is also experienced in completion of numerous Phase I Environmental Site Assessments and Phase II Environmental Site Investigations, site characterization, hazardous materials analysis, regulatory closure reports as well as remedial design and implementation.

Mari has experience in composing site closure documentation including Remedial Closure Reports and Noise Installation Reports reviewed by the Office of Environmental Remediation as well as Final Engineering Reports and Site Management Plans reviewed by the New York State Department of Environmental Conservation. Mari has also worked on city rezoning proposals by performing work associated with and composing the Hazardous Materials Analysis chapter included in Final Environmental Impact Statements published by New York City Department of Planning. Analysis methods were performed in accordance with the City Environmental Quality Review (CEQR) guidelines for neighborhoods including East New York, Brooklyn, Jerome Avenue, Brooklyn, Inwood, and Manhattan.

Mari has managed the investigation, remedial design, remediation and closeout of multiple inactive Resource Conservation and Recovery Act (RCRA) hazardous waste sites, New York State Superfund sites and petroleum spill case sites. Her background includes developing and complying with approved site management plans overseeing the operation and maintenance of on-site engineering controls, such as soil vapor extraction systems, sub-slab depressurization systems, product recovery systems, etc., and ensuring the protection of human health and the environment.

RELEVANT PROJECT EXPERIENCE

State and City Agencies

School Construction Authority, Waste Characterization and Excavation Materials Disposal Plan, Brooklyn, New York. Project manager for consulting services for New York Public School 127. Services included composition of an Excavated Materials Disposal Plan, collection of waste characterization samples and preparation of and preparation of a findings and recommendations report.

Department of City Planning, Rezoning Environmental Impact Statement, Bronx, New York. Project lead for analysis and composing the Hazardous Materials Chapter as per City Environmental Quality Review (CEQR) Technical Manual guidelines included in the Final Environmental Impact Statement (FEIS) for an approximately 92-block area primarily along Jerome Avenue and its east-west commercial corridors in the Bronx. The review assessed the potential for the

presence of hazardous materials in soil and/or groundwater at both the projected and potential development sites identified in the reasonable worst-case development scenario under the proposed East New York Rezoning Proposal. Procedures involved site inspections and review of historic Sanborn fire insurance maps, city directories and city/state regulatory databases. The assessment identified that each of the 146 projected and potential development sites has some associated concern regarding environmental conditions. As a result, the proposed zoning map actions include (E) designations (E-366) for all privately-held projected and potential development sites.

Department of City Planning, Rezoning Environmental Impact Statement, Brooklyn, New York. Project lead for performance analysis and composing the Hazardous Materials Chapter as per CEQR Technical Manual guidelines included in the FEIS for an approximately 190-block area of East New York, Cypress Hills, and Ocean Hill neighborhoods of Brooklyn, New York. The review assessed the potential for the presence of hazardous materials in soil and/or groundwater at both the projected and potential development sites identified in the reasonable worst-case development scenario under the proposed East New York Rezoning Proposal. Procedures involved site inspections and review of historic Sanborn fire insurance maps, city directories and city/state regulatory databases. The assessment identified that each of the 186 projected and potential development sites has some associated concern regarding environmental conditions. As a result, the proposed zoning map actions include (E) designations (E-366) for all privately-held projected and potential development sites.

Redevelopment and Remediation

Titan Equity Group, Hotel Redevelopment, Bronx, New York. Project manager for a hotel redevelopment in the south Bronx. The site has been assigned New York City Office of Environmental Remediation (NYC OER) E-Designation status for hazardous materials, noise, and air quality. Services included completion of a remedial investigation, composition of a Remedial Investigation Report and development of Hazardous Material Remedial Action Work Plan and Air Quality/Noise Remedial Action Plan as per NYC OER requirements.

The Related Companies, Chelsea Mixed-Use Redevelopment, New York, New York. Field geologist for oversight of the remediation of a mixed-use residential and commercial building, the second of a two-building development on 30th Street. Contaminants of concern included volatile and semi-volatile organic compounds associated with historic operations and underground storage tanks (USTs) located on the Site. The Site was given an E-designation (E-142) for hazardous materials and noise as part of the Highline/West Chelsea rezoning proposal. To satisfy the requirements of the E-designation program, soil was excavated to at least 12 feet below grade and bottom endpoint collected showing no contaminants of concern exceeding the New York State Department of Environmental Conservation (NYSDEC) Unrestricted Use Soil Cleanup Objectives (SCO). By achieving Unrestricted Use SCOs, no engineering controls were necessary, although the building slab was included as part of development, and removal of the hazardous materials E-designation was requested.

Tishman Speyer, Long Island City Residential Development, Long Island City, New York. Field geologist for remedial oversight and implementation of a Community Air Monitoring Program during concurrent remediation and development of three Brownfield Cleanup Program (BCP) sites located in Long Island City, New York. The Sites were grossly contaminated with creosote, a carcinogenic chemical formed from the distillation of various tars. Remediation strategies included soil excavation and in-situ soil stabilization. To prevent migration of groundwater off-site, a temporary and later a permanent capture well system was installed on the western boundary of the property. The BCP site located on the western portion of the property left residual contamination in place requiring installation of a sub-slab depressurization system.

Queens West Development Corporation, Queens Waterfront Development, Long Island City, New York. Field geologist for performance of site management post remedial action. Services included annual groundwater monitoring, evaluation of engineering and institutional controls completion and Period Review Reports. In addition to conducting annual site management activities, responsibilities included composing a work plan to evaluate the transition from active sub-slab depressurization systems to passive. Upon NYSDEC approval, active systems were shut down for 30 days prior to a sub-slab vapor sampling event evaluation soil vapor, indoor and outdoor air conditions for

potential vapor intrusion risk. As results indicated no evidence of vapor intrusion, continued pressure monitoring was conducted for from the existing monitoring ports for one year assessing whether negative pressure was held by the existing slab by stack-effect or other passive processes.

Jim Beam Brands Co., Brownfield Cleanup Program Remediation Site, Long Island City, New York. Field geologist for oversight of the installation of an Electrical Resistive Heating (ERH) system implemented in order to remediate trichloroethylene groundwater plumes in shallow/intermediate and deep groundwater on- and off-site. The Site, a former stapler manufacturing facility, underwent various remedies, including a Soil Vapor Extraction system, air sparging, ozone injection and chemical oxidation using potassium permanganate injections, which resulted in little reduction to contamination levels and rebounding chlorinated solvents. Components of the ERH system installed included electrodes for delivery of steam, vapor recovery wells, and groundwater monitoring wells. The site is currently under remediation in the state BCP program.

Due Diligence and Site Characterization

Manufacturing Plants, Multiple Investors, Environmental and Compliance Assessment Portfolio United States. Project lead for completion of Phase I Environmental Site Assessments (ESAs) and Limited Compliance Reviews for multiple auto parts manufacturing facilities throughout the United States. Services included completion of Phase I ESAs in accordance with the American Society for Testing and Materials E1527-13 requirements and a limited review of each facility's compliance liabilities including issues pertaining to the Resource Conservation and Recovery Act, Greenhouse Gas Emission Standards and Tier II Emergency and Hazardous Chemical Inventory reporting requirements.

ARM Parking, Environmental Site Assessment and Subsurface Investigation, Brooklyn, New York. Project manager for site assessment and subsurface investigation of parking facility in Sunset Park neighborhood, Brooklyn, New York. Services included ground penetrating radar survey for former and current petroleum USTs, completion of a subsurface investigation of soils and composition of Limited Subsurface Investigation Report.

Spill Consulting

The Trump Organization, Spill Consulting Services, New York, New York. Project manager for consulting services provided after incidental release of calcium carbonate ice rink paint to the Central Park Pond from Wollman Rink. Services included liaising with NYSDEC regarding violations, consent order and required corrective action. Corrective action included designing alterations to the existing on-site drainage plans and routing all meltwater containing paint into the combined sewer system. Coordination was required with property owner, operations personnel, New York City Department of Parks and NYSDEC.

Richmond Gardens Apartments, Spill Management and Closure Services, Staten Island, New York. Project lead responsible for spill closure activities and reporting for Spill 1105661 located at the Richmond Gardens Apartment Complex in the Richmond neighborhood of Staten Island, New York. The spill was opened in 2011 when several underground storage tanks were identified adjacent to the apartments at Jersey Street and Hendricks Avenue. The tanks were cleaned and removed and impacted soils surrounding the tank area excavated to the extent possible. Excavation of all impacted material was not feasible due to the proximity of the tanks to the apartment buildings. Residual contamination in soil and groundwater remained and was monitored through 2016. Upon reviewing the groundwater monitoring data from over 12 consecutive quarters, it was apparent monitored natural attenuation was not a feasible option and an in situ chemical oxidation (ISCO) remedy was approved by NYSDEC. Due to success of the pilot test, the ISCO injection event was implemented utilizing pressure pulse technology to deliver the alkaline activated persulfate solution to the subsurface.

HALEY ALDRICH



PAUL G. PROBASCO, P.G., LSRP

Senior Project Manager, Hydrogeologist

EDUCATION

M.S., Environmental Sciences, University of Virginia
M.S., Hydrogeology, Rensselaer Polytechnic Institute
B.S., Geological Sciences, Cook College, Rutgers University

PROFESSIONAL REGISTRATIONS

2012/ PA: Professional Geologist (Reg. No. PG005055)
2018/ NY: Professional Geologist (Reg. No. 001138)
2021/ NJ: Licensed Site Remediation Professional (Reg. No. 835739)

PROFESSIONAL SOCIETIES

National Ground Water Association

SPECIAL STUDIES AND COURSES

40-Hour OSHA Hazardous Waste Operations and Emergency Response Training (29 CFR 1910.120)
8-Hour OSHA Site Supervisor Training

Paul is a hydrogeologist and project manager with over 18 years of experience in the environmental consulting industry. He applies his expertise in the investigation and remediation of contaminated sites for private and public-sector clients. He has managed and conducted site and remedial investigations, remedial planning and design, and remedial actions at sites in state and Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) regulatory programs. Paul is skilled in technical groundwater investigations in unconsolidated and bedrock aquifers, assessment of soil conditions through core sampling and direct-sensing techniques, and application of analytical models toward understanding contaminant transport and fate. His environmental remediation experience focuses on management and oversight of in situ remedial approaches, including enhanced in situ bioremediation, chemical reduction and oxidation, and enhanced monitored natural attenuation.

RELEVANT PROJECT EXPERIENCE

Confidential clients – Brownfield redevelopment, multiple properties, Brooklyn, New York. As project manager, Paul managed due diligence environmental assessments and remedial investigations of sites pursuing entry into and sites within the New York State Department of Environmental Conservation (NYSDEC) Brownfield Cleanup Program. Coordinated and managed field investigations including a Phase II environmental site assessment and a remedial investigation of soil, groundwater, and soil vapor impacted from previous petroleum UST operations. Developed scopes of work and responsible for managing project budget, schedule, and communications with the client and NYSDEC. Prepared and managed multiple deliverables including project work plans and summary reports describing sampling activities and findings.

U.S. Navy – NAVFAC Mid-Atlantic, Former Naval Weapons Industrial Reserve Plant, groundwater remedial design, Bedford, Massachusetts. As project manager, Paul managed groundwater remedial design, pre-design aquifer testing, supplemental groundwater investigation, and vapor intrusion investigation activities at a former Navy installation. Responsible for managing project budget, schedule, and biweekly meetings with the client, EPA, and MassDEP. Coordinated and managed field activities that consisted of permanent monitoring well installations in a heterogeneous glacial till, aquifer pump and slug tests, temporary well installations and sampling, soil gas point installations and sampling, and the collection of sub-slab and indoor air samples from an off-site residence. Prepared and managed multiple deliverables including project work plans and a site management plan, preliminary assessment, groundwater

investigation report, community involvement plan, and technical memorandum describing focused groundwater and vapor intrusion investigation activities and findings.

U.S. Navy – NAVFAC Mid-Atlantic, Naval Station Newport, pre-design investigation at contaminated bedrock aquifer site, Middletown, Rhode Island. Paul served as project manager for a groundwater pre-design investigation at a contaminated bedrock aquifer site where previous in situ bioremediation had limited success with reducing chlorinated volatile organic compound (CVOC) concentrations in groundwater. He developed a hydraulic testing approach using pump tests and a bromide tracer test to improve understanding of the distribution of an amendment injected into a single well. Coordinated and managed vegetation clearing, a well inventory, two comprehensive site-wide groundwater gauging and sampling events, and preparation of a hydraulic testing work plan and a groundwater pre-design investigation report.

U.S. Navy – NAVFAC Mid-Atlantic, Naval Station Newport, remedial investigation at former tank farm, Portsmouth, Rhode Island. As project hydrogeologist, Paul developed a remedial investigation approach and conducted data analysis to apportion sources of total petroleum hydrocarbons (TPH) in soil at a former tank farm. The approach consisted of grid-based soil sampling across the previously delineated petroleum-impacted area; analysis of soil samples for TPH, saturated hydrocarbons, and biomarkers; and statistical analysis and petroleum fingerprinting of soil data to apportion heavy and mid-distillate components of the TPH that exceed the site cleanup goal. The approach was incorporated into the sampling and analysis plan for the site. Following soil sample and data acquisition, Paul managed data analysis and source apportionment.

U.S. Navy – NAVFAC Mid-Atlantic, Naval Station Newport, groundwater discharge to surface water investigation, Middletown, Rhode Island. Paul served as project hydrogeologist and developed an investigation approach that incorporated aerial infrared imaging, focused porewater sampling, and a vertical tracer study to evaluate groundwater discharge to an estuary. The approach was incorporated into the draft thermal imaging and vertical tracer testing work plan.

Confidential client – former New York air brake manufacturing facility, post-closure operations, maintenance, and monitoring, Watertown, New York. Paul was the project manager for ongoing operations, maintenance, and monitoring (OM&M) of a former manufacturing facility in the 19th year of a 30-year post-closure OM&M program. He managed project tasks, budget, and invoicing. Technical tasks included evaluation of groundwater elevation and chemical data to assess the long-term effectiveness of a groundwater pump and treat system that was installed to remove and prevent off-site transport of volatile organic compounds (VOCs) in groundwater. Paul prepared Annual Groundwater Monitoring Reports that presented findings from the data evaluation to the New York State Department of Environmental Conservation (NYSDEC), and prepared and submitted to NYSDEC a Periodic Review Report that summarized the protectiveness of engineering controls operated and maintained at the site during the previous three years.

Confidential client – former Henry Harris Landfill, remedial investigation and remedial action work plan development, Harrison Township, New Jersey. As the project geologist and task manager, Paul developed a conceptual site model for a former sanitary landfill site that incorporated understanding of the site hydrogeology, contaminant sources, and contaminant distribution to identify data gaps in completing the site remedial investigation (RI). He managed field activities to address data gaps with the RI, which included evaluation of groundwater-surface water interactions, installation of monitoring wells, and targeted soil sampling at soil-related areas of concern. Paul prepared a subsequent Remedial Action Work Plan for soil, groundwater, and surface water at the site, which incorporated the landfill closure plan and proposed Monitored Natural Attenuation (MNA) to address impacts to groundwater. Following implementation of a quarterly groundwater monitoring program, multiple lines of evidence in support of MNA as an effective remedy for groundwater were presented in a Groundwater Remedial Action Report.

Ingersoll Rand – manufacturing facility, pilot and full-scale bioremediation implementation, Hamilton, New Jersey. As project geologist**,** Paul managed and provided field oversight of a full-scale enhanced in situ bioremediation (EISB) remedy to address elevated concentrations of chlorinated VOCs in shallow groundwater at an active manufacturing facility. The full-scale remedy included delivery of emulsified vegetable oil (EVO), ZVI, and KB-1 Plus® microbial culture to outdoor and indoor injection locations. The full-scale remedy was implemented following the completion of a field-scale EISB pilot study that included delivery of amendments under pressure and gravity-fed conditions. Prior to the full-scale EISB remedy, a Groundwater Remedial Action Workplan was prepared that summarized the remedial investigation progress, results of the field pilot study, and scope of work for implementation of the full-scale remedy.

Ingersoll Rand – former manufacturing facility, remedial investigation and conceptual site model refinement, Phillipsburg, New Jersey. Paul served as the field geologist and task manager for the drilling, geophysical logging, packer testing, and construction of monitoring wells in a karst subsurface. Coordinated drilling, investigation-derived waste, and geophysical logging/packer testing subcontractors that included managing changes to the schedule based on variability in subsurface conditions. Monitoring well construction was based on the analytical results for(VOCs in groundwater samples collected from multiple depth intervals within each borehole. Dual or triplet monitoring wells were installed at multiple locations to characterize VOCs in groundwater with depth and provide data on VOC concentrations at the water table (shallow well) for evaluation of potential vapor intrusion.

In addition, Paul analyzed and summarized approximately 20 years of groundwater gauging and analytical data from approximately 80 monitoring and recovery wells at this 383-acre site as part of the conceptual site model development and refinement. Groundwater levels, fracture orientations, chlorinated VOC concentrations, and light nonaqueous phase liquid (LNAPL) extent data were evaluated as part of the conceptual site model development.



BRIAN FITZPATRICK, CHMM

Corporate Director, Health and Safety

EDUCATION

M.P.A., Environmental Policy, Syracuse University
B.S., Environmental Science, University of Massachusetts-Amherst
A.S., Chemistry, Valley Forge Military Junior College
Commissioned Officer, United States Army

CERTIFICATIONS

Certified Hazardous Materials Manager (Reg. No. 13454)
Certified Department of Transportation Shipper
Certified International Air Transport Authority Shipper

PROFESSIONAL SOCIETIES

Alliance of Hazardous Materials Professionals
Academy of Certified Hazardous Materials Managers, New England Chapter

SPECIAL STUDIES AND COURSES

Department of Transportation
International Air Transport Authority
Incident Commander
Confined Space Entry and Rescue
Radiation Safety Officer
RCRA Hazardous Waste
Massachusetts Industrial Waste Water Operator Grade 2I (expired)

AWARDS

Presidents Club Award (one million hours worked without a recordable injury), Cabot Corporation
Chancellors Award for Excellence, Syracuse University

Brian ensures the work we do for our clients is done safely – knowing this reduces costs, improves service quality and site conditions, and ultimately protects our clients' reputations. In addition to building the Haley & Aldrich Health & Safety (H&S) culture, Brian is hands-on with clients to help improve their and their partners' safety cultures.

He has extensive expertise in the Occupational Safety and Health Administration (OSHA) general industry, process safety management, and construction safety programs. He is an active member of the Alliance of Hazardous Materials Professionals and the New England chapter of the Academy of Certified Hazardous Materials Managers.

Brian knows an organization's success is predicated on empowering its people to safely work within the complex, living processes in which they operate. He is a student of human factors in the workplace, of the phenomena of human error and drift into failure, and of the safety applications of Lean techniques.

RELEVANT PROJECT EXPERIENCE

Haley & Aldrich, Inc., Burlington, Massachusetts. As Chief Health and Safety Officer, Brian has led and facilitated the development and implementation of corporate health and safety (H&S) improvement plans to enhance compliance and improve H&S performance. In Brian's time with Haley & Aldrich, Inc., the company has realized dramatic improvement on H&S goals and in Key Performance Indicators. Brian is responsible for developing a risk competence culture, where our staff are empowered to look for and engage to address risk before anyone is injured. Brian oversees the development, implementation and continuous improvement of all H&S programs for the company. Additional responsibilities include:

- Developing a safety culture through incident reporting, root cause analysis, behavior-based safety, hazard recognition and risk assessment, communication, and developing leaders;

- Monitoring proposed and existing SH&E regulations and legislation to determine their impact on operations and to ensure continued compliance;
- Overseeing the safety, industrial hygiene, and toxicology programs for over 600 staff members engaged in remediation, construction, health and safety, consulting, and general office work across 28 offices in the United States and on assignment to international project sites;
- Continuously seeks to improve H&S performance as measured by the OSHA Incident Rating (IR) and Worker's Compensation Experience Modification Rating (EMR), as well as Leading Indicators developed with the management team; and
- Participating in the corporate audit program as an auditor or lead auditor;

Energy Client, California. As Chief Health and Safety Officer, Brian led and facilitated the Alliance Partnership Safety Council in 2017, is still an active contributor to the council, and hosts routine contractor safety forums for the client. Brian is actively involved in the development and implementation of program safety, health, and environmental (SH&E) plans to ensure safe operations on project sites. Brian developed permits and Health and Safety Plans for large projects and routinely audits the site safety. Additional responsibilities include:

- Driving reporting and behavior-based safety initiatives to support our internal safety culture and developing monthly summary reports to illustrate performance to our client.
- Develop, assess and continuously improve site safety plans and practices, including specific safety protocols for working safely over and around water.
- Worked as an extension of the client's organization to provide assurance that the remedy was completed safely and consistent with client-specific requirements.
- Support on-site safety personnel in ensuring the health and safety of the general public, our staff, and our sub-contracted employees.
- Audits and visits sites to ensure compliance with our internal policies and client-specific requirements.

Energy Client, Ohio. As Chief Health and Safety Officer, Brian supports the project team in developing and executing client and project specific health and safety measures, such as a site specific Health and Safety Plan, Job Hazard Analyses, Industrial Hygiene program, and site specific training. Brian also routinely visits the site to assess current practices and condition and to ensure continuous improvement. Additional responsibilities include:

- Develop, assess, and continuously improve site safety plans and practices, including specific safety protocols to comply with supplemental EH&S requirements such as the Duke Health and Safety Handbook, Environmental Supplemental, and EHS Keys to Life.
- Develop, assess, and continuously improve site safety plans and practices to address the risks associated with the work being performed on site, as well as the environmental conditions and simultaneous operations, including trenching and excavation, hot work, work over and near water, heavy equipment, HAZWOPER, etc.
- Worked as an extension of the client's organization to provide assurance that the remedy was completed safely and consistent with client-specific requirements.
- Support on-site safety personnel in ensuring the health and safety of the general public, our staff, and our sub-contracted employees.
- Audits and visits site to ensure compliance with our internal policies and client-specific requirements.

BRIAN A. FERGUSON

Senior Health & Safety Manager

EDUCATION

MS, Geotechnical Engineering, Tufts University, Medford, Massachusetts
BS, Civil Engineering, State University of New York - Environmental, Science, and Forestry, Syracuse, New York
AS, Applied Science and Technology (Nuclear Engineering), Thomas A. Edison State College, Trenton, New Jersey

CERTIFICATIONS

BCSP Certified Safety Professional (#CSP-45145)
BCSP Associate Safety Professional (#ASP-31270)

PROFESSIONAL SOCIETIES

Associate Safety Professional – 2019
Order of the Engineer – 2000
Boston Society of Civil Engineers (BSCE)
American Society of Civil Engineers (ASCE)

SPECIAL STUDIES AND COURSES

American Concrete Institute – Certified Field Technician Certified Grade 1
Radiation Safety and Operations of Nuclear Testing Equipment – Troxler
40-Hour OSHA Hazardous Waste Operations Training (+ 8-Hour annual refresher)
10-Hour OSHA Construction training
Confined Space Entry Training
16-Hour Asbestos Operations and Maintenance
24-Hour Asbestos Inspector
Asbestos Inspector License (June 2018 and renewed Annually)

ENGINEERING EXPERIENCE

Brian has over 23 years of experience serving as a project engineer on a variety of real estate development projects. His project experience has included monitoring field investigations, performing construction oversight, performing due diligence, engineering analyses, performing geotechnical analyses, developing geotechnical recommendations, and preparing geotechnical reports, and project specifications.

As a project engineer, in addition to providing engineering design support, Brian has managed and participated in many field service activities. Field work has included construction monitoring and documentation of contractors' deep and shallow foundation-related construction, including slurry walls, caissons, pile driving, pile cap installation, earthwork, backfilling and compaction, installation of soldier pile and wood lagging support systems, installation of tie backs and rock anchors, reading inclinometers, conducting in-place field unit weight tests, tie-back load testing, seismograph installation, monitoring, and evaluating, and preparation of footing bearing surfaces. Other responsibilities have included site development activities, including placement of utilities and subgrade preparation for roads; observations and testing to determine that work is completed in compliance with contract documents; on-site soil management; sampling of soil and groundwater for chemical laboratory testing and conducting in situ field screening; maintenance of job records including pile driving logs, results of field density tests, records of caisson and footing installations; preparation of daily field reports; in contact with key personnel; and resolution of field related problems.

RELEVANT PROJECT EXPERIENCE

Fenway Center. Project engineer for the construction of laboratory space constructed over the Massachusetts Turnpike, two residential towers, and the Fenway Area consisting of 8 to 14 stories and multiple levels below grade. Construction responsibilities included coordination of construction monitoring, observing Support of Excavation (SOE) and footing installation, coordination of installation of Slurry Walls, assisting with project management, reviewing

weekly field construction reports, reviewing, and responding to geotechnical design submittals, and attending project meetings.

Massachusetts Institute of Technology, The Schwarzman College of Computing Project. Project Engineer for a new approximately eight stories above ground and one story below ground building and contains approximately 189,000 gross square feet (gsf) of mixed-use space for: offices, research laboratory, academic, event, collaboration, meetings, café, convening, and associated services. Responsibilities included coordination of construction monitoring, observing SOE, micropile, and Caisson Installation, assisting with project management, reviewing weekly field construction reports, reviewing, and responding to geotechnical design submittals, and attending project meetings. Brian also was the main point of contact for construction-related issues with the project owner and contractors.

Massachusetts Institute of Technology, Graduate Housing Project. Project Engineer for construction of two new five- to eight- story residential buildings with a total gross floor space of approximately 261,000 square feet (sq ft). Responsibilities included coordination of construction monitoring, observing SOE, micropile, and Caisson Installation, assisting with project management, reviewing weekly field construction reports, reviewing and responding to geotechnical design submittals, and attending project meetings. Brian was the main point of contact for construction-related issues with the project owner and contractors and conducted Health & Safety Audits of Haley & Aldrich personnel during construction.

Edwards Vacuum Project. Project Engineer for a new single-level 101,000-sq ft building with a mezzanine located in the south portion of the proposed building. Responsibilities included developing subsurface exploration program coordination, writing the Geotech Report, and coordinating field staff to observe construction activities, including mass excavation of approximately 100,000 cubic yards of soil, installation of spread footing, and construction dewatering. Brian assisted with project management, reviewing weekly field construction reports, reviewing, and responding to geotechnical design submittals, and attending project meetings. Brian was the main point of contact for construction-related issues with the project owner and contractors and conducted Health & Safety Audits of Haley & Aldrich personnel during construction.

St. Elizabeth's Hospital – **West Campus Forensic Evaluations, Washington, D.C.** Project Engineer for forensic evaluations on the adaptive reuse of former hospital buildings. Responsibilities included coordination of a field exploration program, including test borings and test pits to obtain subsurface information for project design and construction, overseeing multiple field personnel and subcontractors, assisting with project management, reviewing subcontractors invoices, reviewing and summarizing subsurface data, and writing data reports.

NICOLE MOONEY

Assistant Project Manager | Geologist

EDUCATION

B.S., Earth and Environmental Science with a minor in Oceanography, University of Michigan-Ann Arbor

SPECIAL STUDIES AND COURSES

40-Hour OSHA Hazardous Waste Operations and Emergency Response Training (29 CFR 1910.120)
8-Hour OSHA Hazardous Waste Worker Refresher Training (29 CFR 1910.120)
8-Hour OSHA HAZWOPER Supervisor for Construction Training
OSHA 10-Hour Construction Safety
OSHA 30-Hour Construction
NYC SST-307 8-Hour Fall Prevention for Construction
NYC SST-302 2-Hour Drug and Alcohol Awareness for Construction
DOT Hazmat Employee & RCRA Hazardous Waste Generator Training
American Red Cross Adult First Aid/CPR/AED Training and Bloodborne Pathogens Training
USACE Construction Quality Management for Contractors
Level I Antiterrorism Awareness Training

Nicole is a geologist with over four years of experience in site characterization and investigation, subsurface investigations, preparation of technical reports and work plans, and data collection and analysis. She has extensive experience conducting Phase I Environmental Site Assessments (ESAs), Phase II Environmental Site Investigations (ESIs), and other aspects of environmental due diligence. She has experience with preparation and overseeing execution of remedial investigation and actions at sites within the New York State Department of Environmental Conservation (NYSDEC) Brownfield Cleanup Program (BCP) and the New York City Mayor's Office of Environmental Remediation (NYCOER). She has performed soil, groundwater, and soil vapor sampling events and has drafted various site investigation plans and reports.

RELEVANT PROJECT EXPERIENCE

Environmental Investigation, Site Characterization, and Remediation

340 Myrtle Development LLC, 340 Myrtle Avenue, Brooklyn, New York. As a project geologist, Nicole coordinated and managed implementation of the Remedial Action Work Plan (RAWP) at the approximately 8,828 square foot site enrolled in the NYSDEC BCP. The remedial action included excavation and off-site disposal of soil, installation of an active sub-slab depressurization system (including cover system), installation of injection wells, and reinstallation of permanent monitoring wells for post-remedy groundwater monitoring. Nicole was responsible for the preparation of the Final Engineering Report (FER) and the Site Management Plan (SMP) which are undergoing review by the NYSDEC. Construction for the new development is currently ongoing and, when completed, the site will be improved with a new eight-story mixed-use commercial and residential building with a full cellar level.

B Contractors Group, LLC, 711-713 East 214th Street, Bronx, New York. As a project geologist, Nicole was responsible for coordinating and managing the implementation of the NYCOER-approved Remedial Action Plan (RAP) and preparing the Remedial Closure Report (RCR) for the approximately 6,252 square foot site. The redevelopment included a new eight-story residential building with a full cellar level.

650 Southern Blvd Bronx LLC, 650 Southern Boulevard, Bronx, New York. As a project geologist, Nicole was responsible for preparation and implementation of the Remedial Investigation Work Plan (RIWP), which included the installation of eleven soil borings, seven permanent groundwater monitoring wells (some of which extended into

bedrock), and seven soil vapor points, and the collection of soil, groundwater, and soil vapor samples. Nicole was also responsible for preparation of the Citizen Participation Plan (CPP), Remedial Investigation Report (RIR), and RAWP. The site is in the pre-construction phase.

Degraw Holdings LLC, 563 Sackett Street Site, Brooklyn, New York. As a project geologist, Nicole was responsible for due diligence during acquisition, including preparation of the Phase I ESA and Limited Phase II ESI. The initial Limited Phase II ESI and delineation sampling have been completed and the Limited Phase II ESI Delineation Report, Brownfield Cleanup Agreement (BCA) Major Amendment Application, and Supplemental Remedial Investigation Report (SRIR) are being drafted.

291 Wallabout Realty LLC, 291 Wallabout Street, Brooklyn, New York. As a project geologist, Nicole was responsible for the due diligence during acquisition of the property, including preparation of a Phase I ESA, Phase II ESI, BCP Application, and RIWP.

401 West 207th Realty LLC, 401 West 207th Street, New York, New York. As a project geologist, Nicole was responsible for oversight during implementation of the RAWP under the NYSDEC BCP. During remediation, Nicole observed and documented the excavation and proper disposal of on-site soil required for installation of the foundational elements. Nicole oversaw the proper cleaning and removal of two underground storage tanks encountered during excavation.

BCP Applications and Remedial Investigation Work Plans for NYSDEC. Nicole has prepared several BCP Application packages for various clients in New York State, which requires reviewing the site's history, including any previous investigation reports available, to assist with entry into the BCP to be remediated and redeveloped in accordance with applicable NYSDEC requirements. Nicole also prepares an RIWP to be submitted to the NYSDEC either concurrently or following submittal of the BCP Application for full investigation of the site to facilitate proper remedial action.

Excavation Oversight and CAMP Monitoring, Various Sites, Bronx, Brooklyn, and Queens, New York. As a project geologist, Nicole completed remedial oversight for several projects in the NYCOER cleanup program and NYSDEC BCP. Her responsibilities included excavation oversight, air monitoring, truck logging during off-site disposal of excavated materials, collection of endpoint and/or documentation samples, vapor barrier inspection, and oversight of installation of post-remedy groundwater monitoring wells.

Multiple Clients, Phase I ESAs and Due Diligence, Multiple Locations in New York. As a project geologist, Nicole completed several Phase I ESAs for buyers of properties in New York. She has extensive experience completing site reconnaissance and reviewing historical site documentation to identify potential environmental concerns at properties.

Multiple Clients, Phase II ESIs, Multiple Locations in New York. As a project geologist, Nicole conducted several Phase II ESIs for projects in New York, including oversight of the installation of soil borings, groundwater monitoring wells, and soil vapor points and the collection of soil, groundwater, and soil vapor samples. She assisted with the development of sampling plans based on previous environmental investigations and due diligence findings.

Former Grissom Air Force Base, Kokomo, Indiana. As a project geologist, Nicole was responsible for coordinating and performing quarterly groundwater sampling and/or Land Use Control (LUC) inspections in accordance with the deeds and Decision Documents for nine sites (FT001, FT002, SS190, SS035, SS053, SS058, LF003, LF004, and SS049) located on the 2,722-acre former Grissom Air Force Base under the Base Realignment and Closure (BRAC)/Environmental Construction Optimization Services (BECOS) program. Nicole was also responsible for the coordination and implementation of a Data Gap Investigation (DGI) at the SS035, SS053, and SS058 sites and a Site Investigation (SI) at the former Navy Skeet Range (site SR406). Nicole prepared LUC Inspection reports, Annual Groundwater Monitoring Reports, an SI Report, a DGI Report, and the Five-Year Review Report for this work.

KATHERINE R. MILLER

Senior Project Manager

EDUCATION

BS, Chemistry, University of Arizona

SPECIAL STUDIES AND COURSES

40-Hour OSHA Hazardous Waste Operations and Emergency Response Training (29 CFR 1910.120 and 40 CFR 265.16)
8-Hour OSHA Refresher Training (29 CFR 1910.120)
Level IV Data Validation Training

AWARDS

Pinnacle Award, 2009
Pathfinder Award, 2014

In her 10+ years at Haley & Aldrich, Katherine has worked on soil and groundwater environmental investigations and the preparation of environmental reports for private, industrial, and government-based project clients. She is a qualified Data Validator capable of performing various levels of validation on laboratory water quality data according to US Environmental Protection Agency (EPA) National Functional Guidelines and to U.S. Department of Energy radiochemical guidelines. She also has experience designing and maintaining databases for project-specific needs.

Project management responsibilities for a $1.5 million per year stormwater project include preparation of subcontractor bids and contracts; preparation of cost estimates, proposals, and reports; coordination of field testing programs; and interpretation of chemical testing results. She has interacted with local regulatory agencies.

RELEVANT PROJECT EXPERIENCE

Confidential Aerospace Manufacturer, Groundwater Monitoring, Western U.S. Katherine served as project manager for the comprehensive stormwater management program. Responsibilities included project finance management and data management including quality assurance/quality control (QA/QC) and interpretation of chemical testing results. Evaluated QA/QC of groundwater quality data, prepared reports and managed data for the site. Performed data validation of quarterly water quality data from over 300 locations according to EPA National Functional Guidelines and to DOE radiochemical guidelines over a six-year period. Also, responsible for updating and maintaining the integrity of over 200,000 records during that time period. Assisted with management of sampling, analysis, and reporting of constituents of concern, ensured compliance with post-closure permit monitoring and reporting requirements, Data Management Plan, QAPP, and Environmental Data Management System, and ensured and maintained 100% compliance with the QAPP and Data Management Plan. Additionally, prepared groundwater data summaries for proposed extraction wells including comparisons to site NPDES outfall limits in support of Groundwater Interim Measures planning.

Asarco Hayden Plant Site, Hayden, Arizona. Katherine assisted with field preparation, QA/QC of analytical data, and data validation as part of the Remedial Investigation/Feasibility Work Plan including soil, sediment, air, process water, surface water, and stormwater.

Former MGP Site, California. Katherine assisted with report preparation, QA/QC of soil and/or groundwater quality data, and data validation for the investigation of three large former MGP sites in an urban, residential setting; includes over 200 residential properties.

General Manufacturing, Leitchfield, Kentucky. Katherine assisted with report preparation, QA/QC of soil and/or groundwater quality data, and data validation for a soil and groundwater RCRA site. Groundwater monitoring is conducted annually at more than 50 locations for volatile organic compounds (VOCs), including 1,4-dioxane and semi-volatile organic compound (SVOCs).

Skyworks Solutions, Inc., Newbury Park, California. Katherine assisted with report preparation, QA/QC of soil and/or groundwater quality data, and data validation at groundwater remediation site. She monitored for VOCs, including 1,4-dioxane, and inorganic chemicals, including hexavalent chromium.

Teledyne Scientific Company, Thousand Oaks, California. Katherine assisted with report preparation for this groundwater assessment site. Monitored natural attenuation has been instituted as the long-term site remedy.

Port of Redwood City, Permitting and Sediment Characterization, California. Katherine assisted with report preparation, QA/QC of sampling data, and data validation.

Kiewit Infrastructure West, Sediment Quality Study, California. Katherine assisted with report preparation, QA/QC of sampling data, and data validation.

Aeolian Yacht Harbor, Permitting, Eel Grass Conservation and Sediment Characterization, California. Katherine assisted with report preparation, QA/QC of sampling data, and data validation.

Marin County, Paradise Cay Permitting and Sediment Characterization, California. Katherine assisted with report preparation, QA/QC of sampling data, and data validation.

APPENDIX D
Excavation Work Plan

APPENDIX D – EXCAVATION WORK PLAN (EWP)

D-1 Notification

At least 15 days prior to the start of any activity that is anticipated to encounter remaining contamination or breach or alter the 4001 4th Avenue Site's (the Site) cover system, the Site owner or their representative will notify the New York State Department of Environmental Conservation (NYSDEC) contacts listed in the table below (Table I). The information in Table I will be updated as necessary to provide accurate contact information.

Table I: Notifications*	
Shawn Roberts, NYSDEC Case Manager	518-402-9799, shawn.roberts@dec.ny.gov
David Gardner, NYSDEC Supervisor	518-402-9818, david.gardner@dec.ny.gov
Christopher Budd, NYSDOH Case Manager	518-402-1769, christopher.budd@health.ny.gov
Note: **Notifications are subject to change and will be updated as necessary.*	

This notification will include:

- A detailed description of the work to be performed, including the location and areal extent of excavation, plans/drawings for Site re-grading, intrusive elements or utilities to be installed below the soil cover, estimated volumes of contaminated soil to be excavated, any modifications of truck routes, and any work that may impact an engineering control (EC);
- A summary of environmental conditions anticipated to be encountered in the work areas, including the nature and concentration levels of contaminants of concern, the potential presence of grossly contaminated media, and plans for any pre-construction sampling;
- A schedule for the work, detailing the start and completion of all intrusive work;
- A summary of the applicable components of this EWP;
- A statement that the work will be performed in compliance with this EWP, 29 CFR 1910.120 and 29 CFR 1926 Subpart P;
- A copy of the contractor's health and safety plan (HASP), in electronic format, if it differs from the HASP provided in Appendix B of the Interim Remedial Measures Work Plan (IRMWP);
- Identification of disposal facilities for potential waste streams; and,
- Identification of sources of any anticipated backfill, along with the required request to import form and all supporting documentation including, but not limited to, chemical testing results.

The NYSDEC project manager will review the notification and may impose additional requirements for the excavation that are not listed in this EWP.

D-2 Soil Screening Methods

Visual, olfactory, and instrument-based (e.g., photoionization detector) soil screening will be performed during all excavations into known or potentially contaminated material (remaining contamination) or a breach of the cover system. A qualified environmental professional (QEP) as defined in Title 6 of the

New York Codes, Rules and Regulations (NYCRR) Part 375, a professional engineer (P.E.) who is licensed and registered in New York State, or a qualified person who directly reports to a P.E. who is licensed and registered in New York State will perform the screening. Soil screening will be performed when invasive work is done and will include all excavation and invasive work performed during development, such as excavations for foundations and utility work, after issuance of the Certificate of Completion.

Soils will be segregated based on previous environmental data and screening results into material that requires off-site disposal and material that requires testing to determine if the material can be reused on the Site as soil beneath a cover or if the material can be used as cover soil. Further discussion of off-site disposal of materials and on-site reuse is provided in Sections B-6 and B-7 of this Appendix.

D-3 Soil Staging Methods

Soil stockpiles will be continuously encircled with a berm and/or silt fence. Hay bales will be used as needed near catch basins, surface waters, and other discharge points. Stockpiles will be kept covered at all times with appropriately anchored tarps. Stockpiles will be routinely inspected and damaged tarp covers will be promptly replaced. Stockpiles will be inspected at a minimum of once each week and after every storm event. Results of inspections will be recorded in a logbook maintained at the site and available for inspection by the NYSDEC.

D-4 Materials Excavation and Load-Out

A QEP as defined in 6 NYCRR Part 375, a P.E. who is licensed and registered in New York State, or a qualified person who directly reports to a P.E. who is licensed and registered in New York State will oversee all invasive work and the excavation and load-out of all excavated material.

The owner of the property and remedial party (if applicable) and its contractors are responsible for the safe execution of all invasive and other work performed under this EWP. The presence of utilities and easements on the Site will be investigated by the QEP. It will be determined whether a risk or impediment to the planned work under this IRMWP is posed by utilities or easements on the Site. A Site utility stakeout will be completed for all utilities prior to any ground intrusive activities at the Site.

Loaded vehicles leaving the Site will be appropriately lined, tarped, securely covered, manifested, and placarded in accordance with appropriate federal, state, local, and New York State Department of Transportation (NYSDOT) requirements (and all other applicable transportation requirements).

A truck wash will be operated on the Site, as appropriate. The QEP will be responsible for ensuring that all outbound trucks will be washed at the truck wash before leaving the Site until the activities performed under this section are complete. Truck wash waters will be collected and disposed of off-site in an appropriate manner. Locations where vehicles enter or exit the Site shall be inspected daily for evidence of off-site soil tracking.

The QEP will be responsible for ensuring that all egress points for truck and equipment transport from the Site are clean of dirt and other materials derived from the Site during intrusive excavation activities. Cleaning of the adjacent streets will be performed as needed to maintain a clean condition with respect to Site-derived materials. Material accumulated from the street cleaning and egress cleaning activities will be disposed off-site at a permitted landfill facility in accordance with all applicable local, state, and federal regulations.

D-5 Materials Transport Off-Site

All transport of materials will be performed by licensed haulers in accordance with appropriate local, state, and federal regulations, including 6 NYCRR Part 364. Haulers will be appropriately licensed and trucks properly placarded. Material transported by trucks exiting the Site will be secured with tight-fitting covers. Loose-fitting canvas-type truck covers will be prohibited. If loads contain wet material capable of producing free liquid, truck liners will be used.

Truck transport routes are as follows: Trucks will enter the Site from 40th Street and exit by turning right onto 40th Street from the designated point of egress along the northeastern boundary of the Site. Alternatively, trucks will enter the Site from 4th Avenue and exit by turning right onto 4th Avenue from the designated point of egress along the northwestern boundary of the Site. All trucks loaded with Site materials will exit the vicinity of the Site using an approved truck route. This is the most appropriate route and takes into account: (a) limiting transport through residential areas and past sensitive sites; (b) use of city-mapped truck routes; (c) prohibiting off-site queuing of trucks entering the facility; (d) limiting total distance to major highways; (e) promoting safety in access to highways; and (f) overall safety in transport.

Egress points for truck and equipment transport from the Site will be kept clean of dirt and other materials during Site remediation and development. Trucks will be prohibited from stopping and idling in the neighborhood outside the Site. Queuing of trucks will be performed on-site in order to minimize off-site disturbance. Off-site queuing will be prohibited.

D-6 Materials Disposal Off-Site

All material excavated and removed from the Site will be treated as contaminated and regulated material and will be transported and disposed of off-site in a permitted facility in accordance with all local, state, and federal regulations. If disposal of material from this Site is proposed for unregulated off-site disposal (i.e., clean soil removed for development purposes), a formal request with an associated plan will be made to the NYSDEC project manager. Unregulated off-site management of materials from this Site will not occur without formal NYSDEC project manager approval.

Off-site disposal locations for excavated soils will be identified in the pre-excavation notification. This will include estimated quantities and a breakdown by class of disposal facility if appropriate [e.g., hazardous waste disposal facility, solid waste landfill, petroleum treatment facility, construction and demolition (C&D) debris recovery facility]. Actual disposal quantities and associated documentation will be reported to the NYSDEC in the Periodic Review Report (PRR). This documentation will include, but will not be limited to: waste profiles, test results, facility acceptance letters, manifests, bills of lading and facility receipts.

Non-hazardous historic fill and contaminated soils taken off-site will be handled consistent with 6 NYCRR Parts 360, 361, 362, 363, 364 and 365. Material that does not meet Unrestricted Use Soil Cleanup Objectives (UUSCOs) is prohibited from being taken to a New York State C&D debris recovery facility (6 NYCRR Subpart 360-15 registered or permitted facility).

D-7 Materials Reuse On-Site

The QEP as defined in 6 NYCRR Part 375 will ensure that procedures defined for materials reuse in this IRMWP are followed and that unacceptable material (i.e., contaminated) does not remain on the Site. Contaminated on-site material, including historic fill and contaminated soil, that is acceptable for reuse on the Site will be placed below the demarcation layer or impervious surface, and will not be reused within a cover soil layer, within landscaping berms, or as backfill for subsurface utility lines.

Proposed materials for reuse on the Site must be sampled for full suite analytical parameters including per- and polyfluoroalkyl substances (PFAS) and 1,4-dioxane. The sampling frequency will be in accordance with Division of Environmental Remediation (DER)-10 Table 5.4(e)10 unless prior approval is obtained from the NYSDEC project manager for modification of the sampling frequency. The analytical results of soil/fill material testing must meet the site use criteria presented in NYSDEC DER-10 Appendix 5 – Allowable Constituent Levels for Imported Fill or Soil for all constituents listed, and the NYSDEC Sampling, Analysis, and Assessment of Per- and Polyfluoroalkyl Substances April 2023 guidance values. Approvals for modifications to the analytical parameters must be obtained from the NYSDEC project manager prior to the sampling event.

Soil/fill material for reuse on the Site will be segregated and staged as described in Sections B-2 and B-3 of this EWP. The anticipated size and location of stockpiles will be provided in the 15-day notification to the NYSDEC project manager. Stockpile locations will be based on the location of Site excavation activities and proximity to nearby Site features. Material reuse on the Site will comply with requirements of NYSDEC DER-10 Section 5.4(e)4. Any modifications to the requirements of DER-10 Section 5.4(e)4 must be approved by the NYSDEC project manager.

Any demolition material proposed for reuse on the Site will be sampled for asbestos and the results will be reported to the NYSDEC for acceptance. Concrete crushing or processing on the Site will not be performed without prior NYSDEC approval. Organic matter (wood, roots, stumps, etc.) or other solid waste derived from clearing and grubbing of the Site will not be reused on the Site.

D-8 Fluids Management

All liquids to be removed from the Site, including but not limited to, excavation dewatering, decontamination waters and groundwater monitoring well purge and development waters, will be handled, transported, and disposed of off-site at a permitted facility in accordance with applicable local, state, and federal regulations. Dewatering, purge, and development fluids will not be recharged back to the land surface or subsurface of the Site, and will be managed off-site, unless prior approval is obtained from NYSDEC.

Discharge of water generated during large-scale construction activities to surface waters (i.e., a local pond, stream, or river) will be performed under a State Pollutant Discharge Elimination System (SPDES) permit.

D-9 Backfill from Off-Site Sources

All materials proposed for import onto the Site will be approved by the QEP, as defined in 6 NYCRR Part 375, and will be in compliance with provisions in this IRMWP prior to receipt at the Site. A Request to Import/Reuse Fill or Soil form, which can be found at

http://www.dec.ny.gov/regulations/67386.html, will be prepared and submitted to the NYSDEC project manager allowing a minimum of five business days for review. A copy of the form is presented in Appendix F of the IRMWP.

Material from industrial sites, spill sites, other environmental remediation sites, or potentially contaminated sites will not be imported to the Site.

All imported soils will meet the backfill and cover soil quality standards established in 6 NYCRR 375-6.7(d) and DER-10 Appendix 5 for residential use. Based on an evaluation of the land use, protection of groundwater, and protection of ecological resources criteria, the resulting soil quality standards meet Track 1 UUSCOs in all areas of the Site except the Track 4 area. Soils that meet "general" fill requirements under 6 NYCRR Part 360.13, but do not meet backfill or cover soil objectives for this Site, will not be imported onto the Site without prior approval by the NYSDEC project manager. Soil material will be sampled for the full suite of analytical parameters, including PFAS and 1, 4-dioxane. Solid waste will not be imported onto the Site.

Trucks entering the Site with imported soils will be securely covered with tight-fitting covers. Imported soils will be stockpiled separately from excavated materials and covered to prevent dust releases.

D-10 Stormwater Pollution Prevention

Barriers and hay bale checks will be installed and inspected once a week and after every storm event, as necessary. Results of inspections will be recorded in a logbook maintained at the Site and available for inspection by the NYSDEC. All necessary repairs shall be made immediately.

Accumulated sediments will be removed as required to keep the barrier and hay bale check functional. All undercutting or erosion of the silt fence toe anchor shall be repaired immediately with appropriate backfill materials. Manufacturer's recommendations will be followed for replacing silt fencing damaged due to weathering.

Erosion and sediment control measures identified in the IRMWP shall be observed to ensure that they are operating correctly. Where discharge locations or points are accessible, they shall be inspected to ascertain whether erosion control measures are effective in preventing significant impacts to receiving waters. Silt fencing or hay bales will be installed around the entire perimeter of the construction area.

D-11 Excavation Contingency Plan

If underground tanks or other previously unidentified contaminant sources are found during post-remedial subsurface excavations or after development-related construction, excavation activities will be suspended until sufficient equipment is mobilized to address the condition. The NYSDEC project manager will be promptly notified of the discovery.

Sampling will be performed on product, sediment, surrounding soils, etc. as necessary to determine the nature of the material and the proper disposal method. Chemical analysis will be performed for a full list of analytes (Target Analyte List [TAL] metals, Target Compound List [TCL] volatiles and semi-volatiles [including 1,4-dioxane], TCL pesticides and polychlorinated biphenyls [PCBs], and PFAS), unless the Site history and previous sampling results provide sufficient justification to limit the list of analytes. In this

case, a reduced list of analytes will be proposed to the NYSDEC project manager for approval prior to sampling. Any tanks will be closed as per NYSDEC regulations and guidance.

Identification of unknown or unexpected contaminated media identified by screening during invasive site work will be promptly communicated by phone within two hours to NYSDEC's project manager. Reportable quantities of petroleum product will also be reported to the NYSDEC spills hotline. These findings will be also included in applicable reports.

D-12 Community Air Monitoring Plan (CAMP)

A figure showing the location of air sampling stations based on generally prevailing wind conditions will be provided as part of the notification process and to the NYSDEC during daily field reports. These locations will be adjusted on a daily or more frequent basis based on actual wind directions to provide one upwind and at least one downwind monitoring station. Exceedances of action levels listed in the CAMP will be reported to NYSDEC and New York State Department of Health (NYSDOH) project managers.

D-12A: Special Requirements for Work Within 20 Feet of Potentially Exposed Individuals or Structures

When work areas are within 20 feet of potentially exposed populations or occupied structures, the continuous monitoring locations for volatile organic compounds (VOCs) and particulates must reflect the nearest potentially exposed individuals and the location of ventilation system intakes for nearby structures. The use of engineering controls such as vapor/dust barriers, temporary negative-pressure enclosures, or special ventilation devices will be considered to prevent exposures related to work activities and to control dust and odors. Consideration will be given to implementing the planned activities when potentially exposed populations are at a minimum, such as during weekends or evening hours in non-residential settings.

- If total VOC concentrations opposite the walls of occupied structures or next to intake vents exceed 1 part per million, monitoring may occur within the occupied structure(s) pending access. Depending upon the nature of contamination, chemical-specific colorimetric tubes of sufficient sensitivity may be necessary for comparing the exposure point concentrations with appropriate pre-determined response levels (response actions should also be pre-determined). Background readings in the occupied spaces must be taken prior to commencement of the planned work. Any unusual background readings should be discussed with NYSDOH prior to commencement of the work.
- If total particulate concentrations opposite the walls of occupied structures or next to intake vents exceed 150 micrograms per cubic meter, work activities will be suspended until controls are implemented and are successful in reducing the total particulate concentration to 150 micrograms per cubic meter or less at the monitoring point.
- Depending upon the nature of contamination and remedial activities, other parameters (e.g., explosivity, oxygen, hydrogen sulfide, carbon monoxide) may also need to be monitored. Response levels and actions should be pre-determined, as necessary, for each site.

D-13 Odor Control Plan

This odor control plan is capable of controlling emissions of nuisance odors on-site and off-site. If nuisance odors are identified at the Site boundary, or if odor complaints are received, work will be halted, and the source of odors will be identified and corrected. Work will not resume until all nuisance odors have been abated. The NYSDEC and NYSDOH will be notified of all odor events and of any other complaints about the project. Implementation of all odor controls, including the halt of work, is the responsibility of the remedial party's Remediation Engineer, and any measures that are implemented will be discussed in the PRR.

All necessary means will be employed to prevent on- and off-site nuisances. At a minimum, these measures will include: (a) limiting the area of open excavations and size of soil stockpiles; (b) shrouding open excavations with tarps and other covers; and (c) using foams to cover exposed odorous soils. If odors develop and cannot be otherwise controlled, additional means to eliminate odor nuisances will include: (d) direct load-out of soils to trucks for off-site disposal; (e) use of chemical odorants in spray or misting systems; and, (f) use of staff to monitor odors in surrounding neighborhoods.

If nuisance odors develop during intrusive work that cannot be corrected, or where the control of nuisance odors cannot otherwise be achieved due to on-site conditions or close proximity to sensitive receptors, odor control will be achieved by sheltering the excavation and handling areas in a temporary containment structure equipped with appropriate air venting/filtering systems.

D-14 Dust Control Plan

Particulate monitoring must be conducted according to the CAMP provided in Section B-12. If particulate levels at the Site exceed the thresholds listed in the CAMP or if airborne dust is observed on the Site or leaving the Site, the dust suppression techniques listed below will be employed. The remedial party will also take the measures listed below to prevent dust production on the Site.

A dust suppression plan that addresses dust management during invasive on-site work will include, at a minimum, the items listed below:

- Dust suppression will be achieved using a dedicated on-site water truck for road wetting. The truck will be equipped with a water cannon capable of spraying water directly onto off-road areas including excavations and stockpiles.
- Clearing and grubbing of larger areas will be done in stages to limit the area of exposed, unvegetated soils vulnerable to dust production.
- Gravel will be used on roadways to provide a clean and dust-free road surface.
- On-site roads will be limited in total area to minimize the area required for water truck sprinkling.

D-15 Other Nuisances

A plan for rodent control will be developed and utilized by the contractor prior to and during Site clearing and Site grubbing, and during all remedial work.

A plan will be developed and utilized by the contractor for all remedial work to ensure compliance with local noise control ordinances.

APPENDIX E
Resumes



JAMES BELLEW

Principal

EDUCATION

M.S., Environmental Geology, Queens College
B.S., Geology, Pre-Law, Environmental Science, Binghamton University

PROFESSIONAL SOCIETIES

American Council of Engineering Companies, Member, 2017
Urban Land Institute, Member, 2016
Business Council of New York, Member, 2018

SPECIAL STUDIES AND COURSES

40-Hour OSHA Hazardous Waste Operations and Emergency Response Training (29 CFR 1910.120)
30-Hour OSHA Construction Safety and Heath
8-hour OSHA Site Supervisor Certification
OSHA Confined Space Entry Training Certification
Erosion and Sediment Control, New York, No. 006925
USDOT/IATA Training on the Shipping and/or Transportation of Hazardous Materials

James has a hands-on approach to every project. He believes that being present and putting himself into his clients' shoes is the best way to understand their needs. As a Principal, James's expertise includes due diligence, environmental risk development, building surveys, remedial investigations, remedial design, and technical oversight. Mr. Bellew has completed over 50 NYCOER E-Designation Sites and NYSDEC Brownfield Cleanup Program Sites which include preparation of all reports through to the certificate of completion and a certificate of occupancy.

Clients appreciate James' strategies from the inception of a project through closure under various regulatory programs nationwide. That comprehensive approach is what James loves the most about his job. He enjoys taking on complex projects and finding rational, cost-effective, remedial solutions.

RELEVANT PROJECT EXPERIENCE

Development, EPA Site RCRA-02-2009-7306, NYSDEC Site 243016, Former Port Mobil Terminal, Staten Island, New York. Principal responsible for the preparation of the feasibility study, preparation of the Interim Remedial Reports, completion of the Interim Remedial Measures, completion of the remedial investigation stages, continued execution of the Monitoring and Natural Attenuation Program, preparation of the Remedial Action Work Plan/Remedial Designs, and RCRA Closure procedures for the Port Mobil Terminal Site under an Environmental Protection Agency and New York State DEC Consent Order. The Site has a footprint of 240-Acres SF with a planned development for commercial/industrial uses.

Government, NYCDDC Shirley Chisholm Recreational Center, Brooklyn, New York. Principal for the project released by the New York City Department of Design and Construction, on behalf of the NYC Parks Department, for the design and construction of a new recreational center located at 3002 Foster Avenue in Brooklyn New York. Scope of services included execution of a Phase II Environmental Site Assessment, soil characterization, remedial oversight, geotechnical percolation testing and closure with the NYC Department of Environmental Protection.

Development's, New York State Superfund Site 224136, Former NuHart Plastics Site, New York State Superfund Site (NuHart West) and NYSDEC Brownfield Program Site C224287 (NuHart East), Brooklyn, New York. Principal for the preparation of the feasibility study, offsite investigation reports, RCRA (Resource Conservation and Recovery Act) Closure Work Plan, execution of the RCRA Closure, preparation of the Brownfield Cleanup Application (NuHart East), 100% Remedial Design, preparation of all BCP related work plans (NuHart East), coordination to vest the Site for 421-, Final Engineering Reports, RCRA Closure Reports, Site Management Plan, Remedial Memorandum and all community

outreach programs for a former plasticizer facility with on- and off-site pollutant concerns. Responsible for all remedial cost and alternative analysis with the client to bring the Site to a certificate of completion. NuHart is a high-profile Site that requires coordination with the New York State Department of Environmental Conservation (NYSDEC), the New York City Office of Environmental Remediation (NYCOER), local regulatory agencies, community stakeholders and local elected officials. Remediation included shipping off a majority of the Site soil for thermal desorption under a nonhazardous contained in determination for thermal treatment, erection of a negative pressure enclosure in OU-1, groundwater extraction and treatment, underground storage tank (UST) removal, ex-situ chemical soil mixing of Zero Valent Iron (OU-1), In Situ Injection of Zero Valent Iron (OU-2), containment walls (OU-1 and OU-2), In Situ Soil Stabilization and Solidification, and automated LNAPL recovery (OU-2). The NuHart East Site has completed the remediation and received the Certificate of Completion from the NYSDEC in 2023 and the NuHart West Site is receiving its Certificate of Completion in 2025 with an anticipated transition from a Class 2 to a Class 4 Inactive Hazardous waste Site.

Development, NYSDEC Site C224345, 101 Fleet Place, Brooklyn, New York. Principal responsible for the due diligence during acquisition, preparation of the Brownfield Cleanup Program Application, Change of Use Documents, BCA Amendments, remedial investigation, remedial action design (BCP and OER) and Final Engineering Report for the former bus depot Site under the New York State Brownfield Cleanup program and NYCOER E-Designation Programs (Air/Noise). The Site has a footprint of 20,000 SF with a planned development of a 21-story mixed use building with approximately 292 units which include affordable housing. This Site received a NYSDEC Certificate of Completion in 2024.

Development, NYSDEC Site C231150 644 East 14th Street, New York, New York. Principal responsible for the due diligence during acquisition, preparation of the Brownfield Cleanup Program Application, Change of Use Documents, BCA Amendments, remedial investigation, remedial action design and Final Engineering Report for the 644 East 14th Street Site under the New York State Brownfield Cleanup program. The Site has a footprint of 10,000 SF with a planned development of a 24-story mixed use building with approximately 196 units which include affordable housing. The Site received a certificate of completion from the NYSDEC in 2024.

Development, NYSDEC Site C224338 Former Garone Bros Auto Site, 352-362 Shepherd, Brooklyn, New York. Principal responsible for the due diligence during acquisition, preparation of the Brownfield Cleanup Program Application, Change of Use Documents, BCA Amendments, remedial investigation, remedial action design (BCP and OER) and Final Engineering Report for the former Garone Bros Auto Site under the New York State Brownfield Cleanup program and NYCOER E-Designation Programs (Air/Noise). The Site has a footprint of 10,000 SF with a planned development of a 7-story mixed use building with approximately 56 units which include affordable housing. The Site received a certificate of completion from the NYSDEC in 2024.

Development's, NYSDEC Sites C224369, C224348, Speedway Portfolio, Multiple Boroughs, New York. Principal responsible for the expedited due diligence during acquisition of 5 former Speedway Sites of Phase I ESA's and Limited Phase II ESI's, preparation of the Brownfield Cleanup Program Applications, Remedial Investigation Work Plans, Interim Remedial Measure Work Plans, Air/Noise Remedial Action Work Plans (NYCOER), remedial investigations, remedial action designs (BCP and OER), Final Engineering Reports and Site Management Plans. Five of the Sites including 808-834 Metropolitan (C224368), 210 Greenpoint Avenue (C224348) 1885 Atlantic (C224347), 2864 Atlantic (C224349) and 401 West 207th (C231151), were accepted into the NYSDEC Brownfield Cleanup program. The remedial actions for the Sites included a variety of approaches which consisting of in situ chemical treatment for groundwater, soil vapor extraction, excavation and dewatering removal and treatment. All of the Sites received a certificate of completion from the NYSDEC in 2023 and 2024.

Development, NYSDEC Site C203127, 138 Bruckner Boulevard, Bronx, New York. Principal responsible for the due diligence during acquisition, preparation of the Brownfield Cleanup Program Application, Change of Use Documents, coordination to vest the Site for 421-a, BCA Amendments, remedial investigation, remedial action design (BCP and OER) and Final Engineering Report for the former Zaro's Bakery Site under the New York State Brownfield Cleanup program and NYCOER E-Designation Programs (Air/Noise). The Site has a footprint of 50,000 SF with a planned

development of a 12-story mixed use building with approximately 447 units which include affordable housing. The Site received a certificate of completion from the NYSDEC in 2023.

Development, NYSDEC Site C203156 Former Mill Sanitary Wiping Cloth Site, 40 Bruckner Boulevard, Bronx, New York. Principal responsible for the due diligence during acquisition, preparation of the Brownfield Cleanup Program Application, Change of Use Documents, BCA Amendments, remedial investigation, remedial action design (BCP and OER) and Final Engineering Report for the former Mill Sanitary Wiping Cloth Site under the New York State Brownfield Cleanup program and NYCOER E-Designation Programs (Air/Noise). The Site has a footprint of 45,000 SF with a planned development of a 12-story mixed use building with approximately 480 units which include affordable housing. The Site received a certificate of completion from the NYSDEC in 2023.

Development, NYSDEC Site C203121, 310 Grand Concourse, Bronx, New York. Principal responsible for environmental and construction management services required to successfully navigate this two-building redevelopment project through the NYSDEC Brownfield Cleanup Program (BCP) and NYCOER E-Designation Program (Air/Noise). Project included site investigation, design, and remediation for development of two buildings within a 30,000 square-foot lot in the Bronx, New York. Remediation included excavation of approximately 20,000 cubic yards of soil, groundwater extraction and treatment, underground storage tank (UST) removal, design, and installation an ex-situ chemical in situ soil stabilization process for elevated levels of metals.

Development, NYSDEC Site C224299, 297 Wallabout Street, Brooklyn New York. Principal responsible for the due diligence during acquisition, preparation of the Brownfield Cleanup Program Application, Change of Use Documents, BCA Amendments, remedial investigation, and remedial action design (BCP and OER), Final Engineering Report and Site Management Plan for the 297 Wallabout Street Site under the New York State Brownfield Cleanup program and NYCOER E-Designation Programs (Air). Successfully delineated the onsite tetrachloroethene (PCE) plume in soil and groundwater. The Site is currently in the remedial implementation phase. Remediation included excavation of approximately 5,000 cubic yards of soil, groundwater extraction and treatment, underground storage tank (UST) removal, design, and installation an ex-situ chemical oxidation process for chlorinated solvents and monitoring and natural attenuation. The Site received a certificate of completion from the NYSDEC in 2024.

Development, NYSDEC Site C224239, Former Techtronics Site (8 Walworth Street), Brooklyn, New York. Principal for the remedial investigation, remedial action design and remedial action implementation for the former Techtronics Site under the New York State Brownfield Cleanup program as a Participant where trichloroethene (TCE) and tetrachloroethene (PCE) were encountered in soil and groundwater. James successfully delineated the vertical and lateral extents of the plumes which were identified as an upgradient, on-site. For this Site we have designed source removal to 20'bgs, Zero Valent Iron (ZVI) Reactive Barrier Wall, in situ ZVI injections sitewide and a vertical vapor mitigation system. The Site is currently in the remedial implementation phase.

Development, New York City OER Site - 346 Grand Concourse, Bronx, New York. Principal for the proposed 9-story, 60 key commercial building with one-level deep cellar. Design phase environmental services consist of guiding the Site through the New York City Office of Environmental of Remediation Voluntary Cleanup and E-Designation Programs, including Hazmat, Air Quality and Noise requirements. This program included submission of a Remedial Investigation Work Plan, implementation of a Remedial Investigation, submittal of a Remedial Investigation Report, Remedial Action Work Plans (Hazmat Air and Noise) and the Final Installation Report for the Certificate of Occupancy.

Development, New York City OER Site - 3294 Atlantic Avenue, Brooklyn, New York. Principal for the proposed 12-story, 80 key commercial building with one-level deep cellar. Design phase environmental services consist of guiding the Site through the New York City Office of Environmental of Remediation Voluntary Cleanup and E-Designation Programs, including Hazmat, Air Quality and Noise requirements. This program included submission of a Remedial Investigation Work Plan, implementation of a Remedial Investigation, submittal of a Remedial Investigation Report, Remedial Action Work Plans (Hazmat Air and Noise) and the Final Installation Report for the Certificate of Occupancy.

Development, New York City OER Site - 590-594 Myrtle Avenue, Brooklyn, New York. Principal for the proposed 6-story, 12-unit residential building with one-level deep cellar. Design phase environmental services consist of guiding the Site through the New York City Office of Environmental of Remediation Voluntary Cleanup and E-Designation Programs, including Hazmat, Air Quality and Noise requirements. This program included submission of a Remedial Investigation Work Plan, implementation of a Remedial Investigation, submittal of a Remedial Investigation Report, Remedial Action Work Plans (Hazmat Air and Noise) and the Final Installation Report for the Certificate of Occupancy.

Development, New York City OER Site - 3530 Webster Avenue, Bronx, New York. Principal for the proposed 8-story, 75 key commercial building with one-level deep cellar. Design phase environmental services consist of guiding the Site through the New York City Office of Environmental of Remediation Voluntary Cleanup and E-Designation Programs, including Hazmat, Air Quality and Noise requirements. This program included submission of a Remedial Investigation Work Plan, implementation of a Remedial Investigation, submittal of a Remedial Investigation Report, Remedial Action Work Plans (Hazmat Air and Noise). The project is currently in the construction phase of the NYCOER program.

Development, Former BP Station, Elmhurst Queens, New York. Principal for the preparation of a full environmental impact statement with respect to a mixed-use development proposed in Elmhurst Queens for submission to the NYC Department of City Planning to rezone the project. The work included a full impact assessment of the proposed construction with respect to the neighborhood, evaluation of green/open spaces for the community and environmental site investigation and remediation services.

Development, NYSDEC Site C224204, Former Delta Metals Site, Brooklyn, New York. Senior Project manager for the remedial investigation and remedial action design for the former Delta Metal Products Company. Project is under the New York State Brownfield Cleanup program as a Participant where TCE and tetrachloroethene (PCE) were encountered in soil and groundwater. James successfully delineated the vertical and lateral extents of the plumes which were identified as an upgradient, on-site and downgradient plume. Investigation results triggered the NYSDEC to utilize its call-out contract to perform a plume track down for the immediate area and identify additional Potentially Responsible Parties. The design for an Air Sparge Soil Vapor Extraction system has been accepted and the project is currently under construction.

Manufacturing-Industrial, Hess Amerada, Bogota and Edgewater, New Jersey. Senior Project Manager and technical Lead for the construction management services for the demolition of two waterfront terminals on the Hackensack and Hudson rivers. Services included demolition design, submittal review, site execution and coordination of activities related to asbestos abatement, demolition of buildings, thirty holding tanks, piping structures, containment structures and storm water structures.

Manufacturing-Industrial, PQ Corporation, Northeastern United States. Senior Project Manager responsible for the design and implementation of a three phased program for handling polychlorinated biphenyl (PCB) containing materials on approximately 100 tank structures at large, active industrial sites, which included coating removal, encapsulation, demolition, and Toxic Substances Control Act (TSCA) remediation. He was responsible for development of the overall program, specifications, drawings, bid packages, construction oversight and project administration until closure. The program also included design and oversight of a new façade and roof upgrades completed concurrently to client operations.

Development, NYSDEC Site C224194, Former Cascade Laundry, Brooklyn, New York. Senior Project Manager responsible for environmental and construction management services required to successfully navigate a seven-building redevelopment project through the NYSDEC Brownfield Cleanup Program (BCP) and NYCOER E-Designation Program (Air/Noise). Project included site investigation, design, and remediation for development of seven buildings within a 2-acre site in Brooklyn, New York. Remediation included excavation of approximately 40,000 cubic yards of soil, groundwater extraction and treatment, underground storage tank (UST) removal, design, and installation of a sub slab depressurization system (SSDS) and ex situ chemical oxidation of groundwater impacted by petroleum.

Development, New York City OER Site - 520-534 West 29th Street, New York, New York. James was responsible for environmental site investigation and remediation activities required to successfully navigate the project through the

NYCOER's E-Designation and Voluntary Cleanup Programs. This program included submission of a Remedial Investigation Work Plan, implementation of a Remedial Investigation, submittal of a Remedial Investigation Report, Remedial Action Work Plans (Hazmat Air and Noise). The project is currently in the construction phase of the NYCOER program.

Development, New York State Brownfield Site, BJ's Wholesale, Brooklyn, New York. Senior Project Manager for the remedial execution within the NYSDEC BCP and NYCOER E-Designation programs at an 8-acre peninsula in Gravesend Bay being redeveloped by BJ's Wholesale Club (BJ's) into a "big-box" warehouse and parking garage, and a publicly accessible, waterfront open space. He implemented a comprehensive community air monitoring plan (CAMP), managed the design and installation of a passive sub slab depressurization system, and oversaw handling and off-site disposal of impacted material generated by BJ's (the Lessee for the subject site) during their foundation construction activities.

Development, New York State Brownfield Site, Coney Island, Brooklyn, New York. Senior Project Manager responsible for the environmental design during the rehabilitation and expansion of a 1970s-era mixed-use complex, which covers an area equivalent to three city blocks. He facilitated the BCP applications for two adjacent parcels within the complex impacted by historic dry-cleaning uses. Site investigations performed had documented the presence of PCE in soil gas and was delineated over three separate structural slabs in commercial and residential space utilizing a mobile laboratory. He designed and installed two sub-slab depressurization systems and prepared Remedial Investigation Work Plan which outlined work required to delineate the vertical and horizontal extent of the impacted soils, soil vapor and groundwater at both BCP sites. The system was designed with below slab suction pits, remote sensing vacuum monitoring points, and a variable frequency drive blower tied into the monitoring points for optimization and power savings.

Development, New York City OER Site - Memorial Sloan Kettering Cancer Center (MSKCC), New York, New York. Project Manager for environmental remediation for this MSKCC development project. James was solely responsible for subsurface investigation and remediation activities, large, manufactured gas plant (MGP) gas holder removal (from former Con Edison Operations), UST removal, daily status updates to the NYCOER, implementation of the CAMP and the management, handling, characterization, and off-site disposal of MGP impacted soil and dewatering fluids.

New York State Spill Remediation, Metropolitan Transportation Agency Bridges and Tunnels, New York, New York. Project Manager responsible for execution of a remedial action scope which included UST removal, excavation of 600 cubic yards of petroleum impacted soil, design and installation of a groundwater extraction and treatment system and post remediation samples. He implemented the In Situ Chemical Oxidation program for the injection of 54,000 gallons of 8 percent solution Fenton's Reagent and the O&M (Operation & Maintenance) of the petroleum spill with respect to Fenton's performance and the plume migration.

Various Public Schools, New York City School Construction Authority, New York, New York. Project Manager responsible for environmental remediation proposed several school developments sites, including PS 312, P.S. 281, and PS 27K. Assisted in the design and implementation of the remediation programs for the sites for petroleum spills, PCB TSCA contamination and hazardous lead hot spots.

Development, i.Park Edgewater, Edgewater, New Jersey. Project Manager responsible for the design and environmental remediation on-site. Implemented the construction plan for remediation of arsenic, pitch- and PCB-impacted soil for excavation and off-site disposal of 20,000 tons. He managed the air monitoring system on-site which consisted of four permanent stations set upwind and downwind on-site for volatile organic compounds (VOCs) and particulate migration off-site. Also, James performed redesigns throughout the project to keep within the current schedule and budget.

Development, New York State Brownfield, Queens West, Long Island City, New York. Project Manager responsible for oversight of the Environmental Remediation on-site. James implemented the construction plan for remediation of 20,000 cubic yards of LNAPL on the Site; he assisted in design and oversight of the In Situ Chemical Oxidation mixing on-site. The project was eventually developed into three large towers and a new school.

Manufactured Gas Plant, National Grid, Rockaway, New York. James aided in the design and implementation of the soil characterization plan for MGP impacted sands. After delineation of the contamination plume, drafted work plans and site layout of the negative pressure tent. He performed and trained the on-site staff on the use of personal air monitoring equipment and aided with design considerations on the installation of a waterloo barrier to be advanced to minus 80 feet below grade surface. James also helped with the design and permitting for the groundwater treatment system installed on-site.

Manufactured Gas Plant, Con Edison, New York, New York. Environmental engineer for responsible party for all environmental issues associated with this job, including transportation and disposal of 8,000 tons of MGP contaminated soil from former Con Edison operations. James scheduled weekly work for all civil and environmental tasks on the job. He was responsible for the design and installation of the dewatering treatment system with a daily discharge of 25,000 gallons per day of MGP -impacted water.

New York State Superfund Project, NYSDEC, Hicksville, New York. James performed O&M and reporting on the Site's Potassium Permanganate Injection system, which was on a timed system; maintained the system, troubleshooting problems and ensuring that the proper ratios were being injected. He performed the fieldwork for analysis and drafted interim reports for the project manager.

Retail Petroleum, New York State Spills Program, Hess Amerada, Various Locations, New York. Environmental Engineer responsible for the design and installation of groundwater and soil vapor remedial systems at over 30 retail petroleum stations for Hess. Responsible for ensuring that the remedial systems were operating properly and performing repairs as necessary during operation. He performed groundwater and soil vapor monitoring and drafted O&M reports for the NYSDEC. Plume size ranged from within the retail station property with monitoring off-site impacts in local neighborhoods greater than a 3-mile radius.

Retail Petroleum, New York State Spills Program, British Petroleum (BP), Various Locations, New York. Environmental Engineer responsible for the design and installation of groundwater and soil vapor remedial systems at over 10 retail petroleum stations for BP. He was responsible for ensuring that the remedial systems were operating properly and performing repairs necessary during operation. He performed groundwater and soil vapor monitoring and drafted O&M reports for the NYSDEC. Plume size ranged from within the retail station property with monitoring off-site impacts in local neighborhoods greater than a 2-mile radius.

Development, 524 West 19th Street, New York, NY (Metal Shutter Homes). Project Engineer responsible party for all environmental and civil issues associated with this job, including transportation and disposal of 5,000 tons of MGP contaminated soil from former Con Edison operations. James scheduled weekly work for all civil and environmental tasks on the job. He successfully redesigned the grout cutoff wall connections to the installed steel sheeting with a secant wall installed off-site. He provided technical guidance for drilling 4-foot diameter exploratory casings for subsurface anomalies. Additionally, James was responsible for the design and installation of the dewatering treatment system with a daily discharge of 25,000 gallons per day of MGP impacted water.

EPA Superfund Site, Newtown Creek Superfund, Brooklyn, New York. Environmental Engineer who aided in the design of the pump and treat system installed at Peerless Importers. He also aided in the design and installation of the harbor boom set up. Operated and Maintained groundwater/LNAPL extraction systems on-site and performed monthly site gauging as part of the O&M plan.



MARI C. CONLON

Senior Client Account Manager

EDUCATION

MS, Geology, Boston College

BS, Geology with a minor in Economics and Business, Lafayette College

PROFESSIONAL REGISTRATIONS

NY: Professional Geologist (License No. 000769)

PROFESSIONAL SOCIETIES

Big Apple Brownfield Awards, Co-Chair, 2018-2022

Big Apple Brownfield Awards Nomination Committee, 2016-2025

New York City Brownfield Partnership Executive Board, 2021-2025

SPECIAL STUDIES AND COURSES

40-Hour OSHA Hazardous Waste Operations and Emergency Response Training (29 CFR 1910.120)

10-Hour OSHA Construction Safety

8-Hour OSHA Supervisor of Hazardous Waste (29 CFR 1910.120 & 29 CFR 1926.65)

Mari is a senior client account manager with experience in soil, groundwater and soil vapor investigation and a focus on remedial design and implementation. She is also experienced in completion of numerous Phase I Environmental Site Assessments and Phase II Environmental Site Investigations, site characterization, hazardous materials analysis, regulatory closure reports as well as remedial design and implementation.

Mari has experience in composing site closure documentation including Remedial Closure Reports and Noise Installation Reports reviewed by the Office of Environmental Remediation as well as Final Engineering Reports and Site Management Plans reviewed by the New York State Department of Environmental Conservation. Mari has also worked on city rezoning proposals by performing work associated with and composing the Hazardous Materials Analysis chapter included in Final Environmental Impact Statements published by New York City Department of Planning. Analysis methods were performed in accordance with the City Environmental Quality Review (CEQR) guidelines for neighborhoods including East New York, Brooklyn, Jerome Avenue, Brooklyn, Inwood, and Manhattan.

Mari has managed the investigation, remedial design, remediation and closeout of multiple inactive Resource Conservation and Recovery Act (RCRA) hazardous waste sites, New York State Superfund sites and petroleum spill case sites. Her background includes developing and complying with approved site management plans overseeing the operation and maintenance of on-site engineering controls, such as soil vapor extraction systems, sub-slab depressurization systems, product recovery systems, etc., and ensuring the protection of human health and the environment.

RELEVANT PROJECT EXPERIENCE

State and City Agencies

School Construction Authority, Waste Characterization and Excavation Materials Disposal Plan, Brooklyn, New York. Project manager for consulting services for New York Public School 127. Services included composition of an Excavated Materials Disposal Plan, collection of waste characterization samples and preparation of and preparation of a findings and recommendations report.

Department of City Planning, Rezoning Environmental Impact Statement, Bronx, New York. Project lead for analysis and composing the Hazardous Materials Chapter as per City Environmental Quality Review (CEQR) Technical Manual guidelines included in the Final Environmental Impact Statement (FEIS) for an approximately 92-block area primarily along Jerome Avenue and its east-west commercial corridors in the Bronx. The review assessed the potential for the

presence of hazardous materials in soil and/or groundwater at both the projected and potential development sites identified in the reasonable worst-case development scenario under the proposed East New York Rezoning Proposal. Procedures involved site inspections and review of historic Sanborn fire insurance maps, city directories and city/state regulatory databases. The assessment identified that each of the 146 projected and potential development sites has some associated concern regarding environmental conditions. As a result, the proposed zoning map actions include (E) designations (E-366) for all privately-held projected and potential development sites.

Department of City Planning, Rezoning Environmental Impact Statement, Brooklyn, New York. Project lead for performance analysis and composing the Hazardous Materials Chapter as per CEQR Technical Manual guidelines included in the FEIS for an approximately 190-block area of East New York, Cypress Hills, and Ocean Hill neighborhoods of Brooklyn, New York. The review assessed the potential for the presence of hazardous materials in soil and/or groundwater at both the projected and potential development sites identified in the reasonable worst-case development scenario under the proposed East New York Rezoning Proposal. Procedures involved site inspections and review of historic Sanborn fire insurance maps, city directories and city/state regulatory databases. The assessment identified that each of the 186 projected and potential development sites has some associated concern regarding environmental conditions. As a result, the proposed zoning map actions include (E) designations (E-366) for all privately-held projected and potential development sites.

Redevelopment and Remediation

Titan Equity Group, Hotel Redevelopment, Bronx, New York. Project manager for a hotel redevelopment in the south Bronx. The site has been assigned New York City Office of Environmental Remediation (NYC OER) E-Designation status for hazardous materials, noise, and air quality. Services included completion of a remedial investigation, composition of a Remedial Investigation Report and development of Hazardous Material Remedial Action Work Plan and Air Quality/Noise Remedial Action Plan as per NYC OER requirements.

The Related Companies, Chelsea Mixed-Use Redevelopment, New York, New York. Field geologist for oversight of the remediation of a mixed-use residential and commercial building, the second of a two-building development on 30th Street. Contaminants of concern included volatile and semi-volatile organic compounds associated with historic operations and underground storage tanks (USTs) located on the Site. The Site was given an E-designation (E-142) for hazardous materials and noise as part of the Highline/West Chelsea rezoning proposal. To satisfy the requirements of the E-designation program, soil was excavated to at least 12 feet below grade and bottom endpoint collected showing no contaminants of concern exceeding the New York State Department of Environmental Conservation (NYSDEC) Unrestricted Use Soil Cleanup Objectives (SCO). By achieving Unrestricted Use SCOs, no engineering controls were necessary, although the building slab was included as part of development, and removal of the hazardous materials E-designation was requested.

Tishman Speyer, Long Island City Residential Development, Long Island City, New York. Field geologist for remedial oversight and implementation of a Community Air Monitoring Program during concurrent remediation and development of three Brownfield Cleanup Program (BCP) sites located in Long Island City, New York. The Sites were grossly contaminated with creosote, a carcinogenic chemical formed from the distillation of various tars. Remediation strategies included soil excavation and in-situ soil stabilization. To prevent migration of groundwater off-site, a temporary and later a permanent capture well system was installed on the western boundary of the property. The BCP site located on the western portion of the property left residual contamination in place requiring installation of a sub-slab depressurization system.

Queens West Development Corporation, Queens Waterfront Development, Long Island City, New York. Field geologist for performance of site management post remedial action. Services included annual groundwater monitoring, evaluation of engineering and institutional controls completion and Period Review Reports. In addition to conducting annual site management activities, responsibilities included composing a work plan to evaluate the transition from active sub-slab depressurization systems to passive. Upon NYSDEC approval, active systems were shut down for 30 days prior to a sub-slab vapor sampling event evaluation soil vapor, indoor and outdoor air conditions for

potential vapor intrusion risk. As results indicated no evidence of vapor intrusion, continued pressure monitoring was conducted for from the existing monitoring ports for one year assessing whether negative pressure was held by the existing slab by stack-effect or other passive processes.

Jim Beam Brands Co., Brownfield Cleanup Program Remediation Site, Long Island City, New York. Field geologist for oversight of the installation of an Electrical Resistive Heating (ERH) system implemented in order to remediate trichloroethylene groundwater plumes in shallow/intermediate and deep groundwater on- and off-site. The Site, a former stapler manufacturing facility, underwent various remedies, including a Soil Vapor Extraction system, air sparging, ozone injection and chemical oxidation using potassium permanganate injections, which resulted in little reduction to contamination levels and rebounding chlorinated solvents. Components of the ERH system installed included electrodes for delivery of steam, vapor recovery wells, and groundwater monitoring wells. The site is currently under remediation in the state BCP program.

Due Diligence and Site Characterization

Manufacturing Plants, Multiple Investors, Environmental and Compliance Assessment Portfolio United States. Project lead for completion of Phase I Environmental Site Assessments (ESAs) and Limited Compliance Reviews for multiple auto parts manufacturing facilities throughout the United States. Services included completion of Phase I ESAs in accordance with the American Society for Testing and Materials E1527-13 requirements and a limited review of each facility's compliance liabilities including issues pertaining to the Resource Conservation and Recovery Act, Greenhouse Gas Emission Standards and Tier II Emergency and Hazardous Chemical Inventory reporting requirements.

ARM Parking, Environmental Site Assessment and Subsurface Investigation, Brooklyn, New York. Project manager for site assessment and subsurface investigation of parking facility in Sunset Park neighborhood, Brooklyn, New York. Services included ground penetrating radar survey for former and current petroleum USTs, completion of a subsurface investigation of soils and composition of Limited Subsurface Investigation Report.

Spill Consulting

The Trump Organization, Spill Consulting Services, New York, New York. Project manager for consulting services provided after incidental release of calcium carbonate ice rink paint to the Central Park Pond from Wollman Rink. Services included liaising with NYSDEC regarding violations, consent order and required corrective action. Corrective action included designing alterations to the existing on-site drainage plans and routing all meltwater containing paint into the combined sewer system. Coordination was required with property owner, operations personnel, New York City Department of Parks and NYSDEC.

Richmond Gardens Apartments, Spill Management and Closure Services, Staten Island, New York. Project lead responsible for spill closure activities and reporting for Spill 1105661 located at the Richmond Gardens Apartment Complex in the Richmond neighborhood of Staten Island, New York. The spill was opened in 2011 when several underground storage tanks were identified adjacent to the apartments at Jersey Street and Hendricks Avenue. The tanks were cleaned and removed and impacted soils surrounding the tank area excavated to the extent possible. Excavation of all impacted material was not feasible due to the proximity of the tanks to the apartment buildings. Residual contamination in soil and groundwater remained and was monitored through 2016. Upon reviewing the groundwater monitoring data from over 12 consecutive quarters, it was apparent monitored natural attenuation was not a feasible option and an in situ chemical oxidation (ISCO) remedy was approved by NYSDEC. Due to success of the pilot test, the ISCO injection event was implemented utilizing pressure pulse technology to deliver the alkaline activated persulfate solution to the subsurface.

SUZANNE BELL, PE

Program Manager, Environmental Engineer

EDUCATION

BS, Biosystems Engineering, University of Arizona

PROFESSIONAL REGISTRATIONS

AZ: Environmental Engineer (Reg. No. 61995)
NY: Professional Engineer (Reg No. 106301)

PROFESSIONAL COMMITTEES

American Council of Engineering Companies of New York – New York State Department of Environmental Conservation Committee Member – 2024-2025

SPECIAL STUDIES AND COURSES

40-Hour OSHA Hazardous Waste and Operations Emergency Response Training (29 CFR 1910.120 and 40 CFR 265.16)
8-Hour HAZWOPER Refresher Course

Suzanne is a senior project manager with over 17 years of experience in the environmental consulting industry. She has worked on soil and groundwater environmental investigations, remediation projects, and prepared reports for private, industrial, and government clients. Her technical experience includes remediation systems; soil and groundwater feasibility studies; Phase I site investigations; environmental file review and historical research; stormwater assessments and SWPPP preparation; reclamation planning for the sand and gravel mining industry; air permitting; and data interpretation.

In New York, Suzanne has experience as an Engineer of Record in completing site closure documentation including Remedial Closure Reports reviewed by the Office of Environmental Remediation as well as Final Engineering Reports and Site Management Plans reviewed by the New York State Department of Environmental Conservation.

Suzanne has managed the investigation, remedial design, remediation and closeout of sites in the Brownfield Cleanup Program and petroleum spill case sites. Her background also includes developing and complying with approved site management plans overseeing the operation and maintenance of on-site engineering controls, such as soil vapor extraction systems, sub-slab depressurization systems, product recovery systems, and ensuring the protection of human health and the environment.

RELEVANT PROJECT EXPERIENCE

Bedford Beverly Redevelopment Site, Brooklyn, New York. Suzanne served as engineer of record for execution of Remedial Action Work Plans for an approximately 5.31-acre non-contiguous property located in the Flatbush neighborhood in the borough of Brooklyn, New York under the New York State Brownfield Cleanup Program (NYSBCP). The remedy included removal of thirteen undocumented underground storage tanks (USTs), removal of over 115,000 tons of non-hazardous and hazardous soil, hotspot excavations, injections of zerovalent iron to treat tetrachlorethylene in groundwater, injection of alkaline-activated persulfate to treat petroleum-based volatile organic compounds in groundwater and establishing a Site Management Plan (SMP) for Institutional and Engineering Controls. The site is being redeveloped from a vacant auto service center, vast open air parking lots, and a vacant commercial building into a vibrant community development. In addition to new residential housing, which includes affordable units, and commercial spaces, the project has preserved the highly recognizable Sears Roebuck & Company Department Store. This includes maintaining its historical architecture, updating the building to meet modern standards, introducing commercial spaces that were previously underutilizing, and maintaining the character of the neighborhood.

Development, EPA Site RCRA-02-2009-7306, NYSDEC Site 243016, Former Port Mobil Terminal, Staten Island, New York. Engineer and project manager responsible for the preparation of the feasibility study, preparation of the Interim Remedial Report, completion of the Interim Remedial Measure, completion of the remedial investigation stages, continued execution of the Monitoring and Natural Attenuation Program, preparation of the Remedial Action Work Plan/Remedial Designs, and RCRA Closure procedures for the Port Mobil Terminal Site under an Environmental Protection Agency and New York State DEC Consent Order. The Site has a footprint of approximately 240 acres with a planned development for commercial/industrial uses.

Rogers Snyder Brownfield Site, 858 Rogers Avenue and 2605 Snyder Avenue, Brooklyn, New York. Suzanne served as engineer of record for execution of Remedial Action Work Plan at the Rogers Snyder redevelopment project under the NYSBCP. Responsible for remedial oversight of excavation and removal of non-hazardous and hazardous soil, endpoint sample collection, air monitoring, communication with soil brokerage firm and environmental laboratory, preparation of the FER.

Former Garone Bros Auto Service Center Site, 352-362 Shepherd Avenue, Brooklyn, New York. Suzanne served as engineer of record for execution of Remedial Action Work Plan at the 352-362 Shepherd redevelopment project under the NYSBCP. Responsible for remedial oversight of excavation and removal of non-hazardous soil, removal of USTs, endpoint sample collection, air monitoring, communication with soil brokerage firm and environmental laboratory, preparation of the FER.

Former Fielder Waterproofing & Masonry Site, 91 Bruckner Boulevard, Bronx, New York. Suzanne served as engineer of record for execution of Remedial Action Work Plan at the 91 Bruckner redevelopment project under the NYSBCP. Responsible for remedial oversight of excavation and removal of non-hazardous and hazardous soil, removal of USTs, endpoint sample collection, air monitoring, communication with soil brokerage firm and environmental laboratory, preparation of the FER and SMP.

828 Metropolitan Avenue Site, 808-834 Metropolitan Avenue, Brooklyn, New York. Suzanne served as project manager and engineer of record for execution of Remedial Action Work Plan at the 828 Metropolitan Avenue redevelopment project under the NYSBCP. Responsible for remedial oversight of excavation and removal of non-hazardous soil, removal of USTs, endpoint sample collection, air monitoring, communication with soil brokerage firm and environmental laboratory, preparation of Daily Field Reports (DFRs) and the Final Engineering Report (FER).

Waterfront Property Management, 89-91 Gerry Street and 93 Gerry Street, Brooklyn, New York. Suzanne served as project manager for execution of Remedial Action Work Plans at the former Just4Wheels Site and Just4Wheels Site 2 under the New York State Brownfield Cleanup Program (NYSBCP). Responsible for remedial oversight of excavation and removal of non-hazardous and hazardous soil, endpoint sample collection, removal of USTs, air monitoring, dewatering system installation support, communication with soil brokerage firm and environmental laboratory, preparation of DFRs and the FER.

Multiple Clients, Remedial Investigation Work Plans and BCP Applications, New York City, New York. As project manager and engineer, Suzanne has prepared NYSBCP Applications and Remedial Investigation Work Plans for the New York State Department of Environmental Conservation (NYSDEC) for sites within the New York City boroughs.

Multiple Clients, Remedial Action Work Plans, New York City, New York. As project manager and engineer of record, Suzanne has prepared Remedial Action Work Plans for the NYSDEC for sites within the New York City boroughs.

Excavation Oversight and CAMP Monitoring, Various Sites, New York City, New York. Suzanne has served as project manager for projects under the New York City Office of Environmental Remediation (NYCOER) program and NYSBCP. Her responsibilities included managing excavation oversight, air monitoring, and logging trucks for off-site disposal.

Aerospace Manufacturing Facility, Feasibility Study and Remedial Action Plan, Chula Vista, CA. Suzanne co-authored feasibility studies for soil and ground water impacted by chlorinated solvents, metals, and PCBs. She screened ex-situ and in-situ remedial alternatives for effectiveness, implementability, and protectiveness of human health. She also assessed alternative cleanup levels for technical and economic feasibility of achieving background concentrations in accordance with State Water Resources Control Board Resolution 92-49. Additionally, she evaluated groundwater remedial alternatives, including bioremediation, monitored natural attenuation (MNA), pump and treat, chemical oxidation, chemical reduction, and engineered and institutional controls. Lastly, she prepared engineering cost estimates and conceptual designs. Assisted with the preparation of remedial action plans: a bioremediation remedy and MNA program for groundwater, and excavation of contaminated soil.

Aerospace Manufacturing Facility, Groundwater Remediation and Bioremediation Pilot Test, Riverside, CA. Suzanne assisted with data analysis and reporting for the bioremediation pilot test study for groundwater impacted by chlorinated solvents, hexavalent chromium, and 1,4-dioxane. She evaluated site data for trends indicative of MNA using statistical analysis.

Goodyear Tire & Rubber Company, Phoenix Goodyear Airport South Superfund Site, Goodyear, Arizona. Suzanne prepared reports and performed data analysis related to the groundwater monitoring program and operation and maintenance of groundwater treatment systems. Currently, two groundwater extraction and remediation systems are capable of treating more than 1 million gallons per day of groundwater contaminated with trichloroethylene. The upper groundwater zone is treated with an air stripper, while the lower zone is treated with granulated activated carbon. Treated groundwater is reinjected into their respective zones.

Soil and Groundwater Remediation Systems, Arizona. Suzanne **p**erformed operation, maintenance, and sampling activities for two soil vapor extraction systems to remove tetrachloroethylene from subsurface soils at two different dry-cleaning facilities. She prepared soil vapor extraction GAC system test reports in accordance with Maricopa County Air Quality Department Permits.

ASTM Phase I Environmental Site Assessments, Arizona. Suzanne assisted with ASTM Phase I ESAs at various industrial facilities in central and southern Arizona. She evaluated site conditions and regulatory implications as they related to the owner's or potential buyer's property development plans.

Phoenix-Goodyear Airport-North Superfund Site, Focused Feasibility Study, Goodyear, Arizona. Suzanne was a member of team that prepared a source area remediation focused feasibility study report. She evaluated several technologies and alternatives to treat groundwater contaminated with trichloroethylene (TCE) and perchlorate. She analyzed remedial alternatives, including in-well air stripping, a hydraulic barrier, nano- and macro-scale zero-valent iron, anaerobic reductive dechlorination, in-situ chemical oxidation (permanganate), and electrical resistive heating. She prepared cost estimates, conceptual designs, remediation technology summaries, and sustainability evaluation of the alternatives.

Enhanced In-Situ Bioremediation (EISB) and Chemical Reduction Using a Nanoscale, Zero-Valent Metallic Alloy to Treat Co-disposed Chloroethanes and Chloroethenes in Groundwater, Manufacturing Facility, Canton, MA. Suzanne performed data analysis and prepared status reports on effectiveness of EISB in treating chlorinated solvents in shallow groundwater. She reported on the performance monitoring results for the permeable reactive barrier in deep zone groundwater.

Hayden Facilities RI/FS, ASARCO LLC, Hayden, Arizona. Suzanne served as Quality Assurance Officer for the air monitoring program at a copper smelting facility. She developed site-specific data validation procedures according EPA guidelines for several analytical methods.

Market Evaluation for Nanoscale Zero-Valent Iron, Stamford, Connecticut. Suzanne used EPA CERCLIS Public Access Database and select State databases to estimate the market size for potential use of nanoscale zero-valent iron (nZVI) as a remediation technology. She compiled competing vendor information and quotes to estimate the average cost of similar products. She utilized the U.S. Patent and Trademark Office database to analyze competing technologies.

Arizona Pollutant Discharge Elimination System (AZPDES) and National Pollutant Discharge Elimination System (NPDES) Permits, Arizona. Suzanne prepared AZPDES and NPDES) permit renewal applications for a copper mining facility in Southern Arizona, which included updates to the facility's Storm Water Pollution Prevention Plan (SWPPP) and QA Manual.

Spill Prevention, Control and Countermeasure Plans, Aggregate Mining Facilities, Arizona. Suzanne assisted with a Spill Prevention, Control and Countermeasure Plans (SPCC) for aggregate mining facilities in Arizona. She performed site visit, evaluated fuel and oil tanks and secondary containment areas, assisted with calculations to verify compliance, and prepared report.

Copper Mining Facility, Miami, Arizona. Suzanne assisted with Toxic Release Inventory (TRI) and Toxic Substances Control Act (TSCA) reporting, both submitted to the EPA.

Storm Water Pollution Prevention Plan, Franciscan Friars of California, Gila County, Arizona. Suzanne updated the SWPPP for construction activities related to the closure of a historic Gibson copper mine, authorized under the Arizona Pollutant Discharge Elimination System "General Permit for Discharge from Construction Activities to Waters of the United States." The Former Gibson Mine is a small, historic copper mine, located approximately 7 miles southwest of Miami, Arizona, in Gila County. Construction activities covered under the updated SWPPP consisted of the excavation, hauling, and removal of approximately 80,000 tons of soil cover from the Mineral Creek side of the site to mine-scarred areas on the Pinto Creek side of the site. Also included was final grading of the site, which consisted of re-contouring and re-defining any portion of the drainages that were on site; and revegetation.

Stormwater Pollution Prevention Plans, Vulcan Materials Company, Western Division, Arizona. Suzanne prepared SWPPP for 11 aggregate mining facilities in Arizona. Performed site visits, analyzed stormwater flows, prepared reports, and completed Notices of Intent for the Arizona Department of Environmental Quality under a Multi-Sector General Permit.

Uranium Enrichment Facility, Lea County, New Mexico. Suzanne prepared quarterly and annual groundwater monitoring reports, semi-annual radioactive effluent release reports, and radiological environmental monitoring program reports in accordance with New Mexico Environment Department regulations and the Nuclear Regulatory Commission. Performed quarterly data validation on a variety of matrices and analytical methods. She prepared site-specific environmental monitoring procedures, which included field sampling techniques; data collection, management and validation; and an air modeling software package.

Rocket Testing and Research Facility, Western U.S. Suzanne analyzed and evaluated groundwater quality data, prepared reports, and managed data for this Resource Conservation and Recovery Act (RCRA) site. Assisted with management of sampling, analysis, and reporting of constituents of concern for fractured sandstone bedrock aquifer impacted by chlorinated solvents and emergent chemicals 1,4-dioxane, perchlorate, and n-nitrosodimethylamine (NDMA). Performed data validation of water quality data according to U.S. EPA National Functional Guidelines. Queried data from client environmental data management system and prepared summary tables, concentration plots, and water level hydrographs using Microsoft Excel programs. She prepared a quarterly analytical schedule using an Access database application, updated the site-specific Health & Safety Plan, and participated in lean training, which reduced cost of groundwater monitoring tasks by 25 percent.

Federal Superfund Site, Eastern Massachusetts. Suzanne performed data validation and quality assurance/quality control of soil and groundwater data according to U.S. EPA National Functional Guidelines. She performed third-party database updates.

Great Western Bank, Cortaro Ranch Property, Marana, Arizona. For site characterization of undeveloped land, Suzanne performed surficial soil sampling, analytical laboratory coordination, data analysis, and report preparation.

Twin Buttes Properties, Inc., Southern Arizona. Suzanne assisted with report and analytical table preparation for the characterization and analysis of current and historical hydrologic conditions at an inactive mine site near Sahuarita, Arizona in support of regulatory compliance.

Skyworks Solutions, Inc. Site, Newbury Park, California. Suzanne assisted with report and analytical table preparation for a subsurface investigation characterizing the lateral and vertical extent of soil and groundwater impacts from known releases of TCE, 1,4-dioxane and other organic compounds.

PUBLICATIONS

"Mixed Redox Catalytic Destruction of Chlorinated Solvents in Soils and Groundwater," with S. Gao, E. Rupp, M. Willinger, T. Foley, B. Barbaris, A.E., Saez, R.G. Arnold and E. Betterton. In Environmental Challenges in The Pacific Basin, 2008; Annals of the New York Academy of Sciences, Vol. 1140, pp 435-445. PMID: 18991945

INVITED LECTURER OR SPEAKER

"Catalytic Destruction of Perchloroethylene," with E. Betterton, R. Arnold and Eduardo Saez, Presenter - NASA Space Grant Student Symposium, Phoenix, Arizona. April 2007.

HALEY ALDRICH



PAUL G. PROBASCO, P.G., LSRP

Senior Project Manager, Hydrogeologist

EDUCATION

M.S., Environmental Sciences, University of Virginia
M.S., Hydrogeology, Rensselaer Polytechnic Institute
B.S., Geological Sciences, Cook College, Rutgers University

PROFESSIONAL REGISTRATIONS

2012/ PA: Professional Geologist (Reg. No. PG005055)
2018/ NY: Professional Geologist (Reg. No. 001138)
2021/ NJ: Licensed Site Remediation Professional (Reg. No. 835739)

PROFESSIONAL SOCIETIES

National Ground Water Association

SPECIAL STUDIES AND COURSES

40-Hour OSHA Hazardous Waste Operations and Emergency Response Training (29 CFR 1910.120)
8-Hour OSHA Site Supervisor Training

Paul is a hydrogeologist and project manager with over 18 years of experience in the environmental consulting industry. He applies his expertise in the investigation and remediation of contaminated sites for private and public-sector clients. He has managed and conducted site and remedial investigations, remedial planning and design, and remedial actions at sites in state and Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) regulatory programs. Paul is skilled in technical groundwater investigations in unconsolidated and bedrock aquifers, assessment of soil conditions through core sampling and direct-sensing techniques, and application of analytical models toward understanding contaminant transport and fate. His environmental remediation experience focuses on management and oversight of in situ remedial approaches, including enhanced in situ bioremediation, chemical reduction and oxidation, and enhanced monitored natural attenuation.

RELEVANT PROJECT EXPERIENCE

Confidential clients – Brownfield redevelopment, multiple properties, Brooklyn, New York. As project manager, Paul managed due diligence environmental assessments and remedial investigations of sites pursuing entry into and sites within the New York State Department of Environmental Conservation (NYSDEC) Brownfield Cleanup Program. Coordinated and managed field investigations including a Phase II environmental site assessment and a remedial investigation of soil, groundwater, and soil vapor impacted from previous petroleum UST operations. Developed scopes of work and responsible for managing project budget, schedule, and communications with the client and NYSDEC. Prepared and managed multiple deliverables including project work plans and summary reports describing sampling activities and findings.

U.S. Navy – NAVFAC Mid-Atlantic, Former Naval Weapons Industrial Reserve Plant, groundwater remedial design, Bedford, Massachusetts. As project manager, Paul managed groundwater remedial design, pre-design aquifer testing, supplemental groundwater investigation, and vapor intrusion investigation activities at a former Navy installation. Responsible for managing project budget, schedule, and biweekly meetings with the client, EPA, and MassDEP. Coordinated and managed field activities that consisted of permanent monitoring well installations in a heterogeneous glacial till, aquifer pump and slug tests, temporary well installations and sampling, soil gas point installations and sampling, and the collection of sub-slab and indoor air samples from an off-site residence. Prepared and managed multiple deliverables including project work plans and a site management plan, preliminary assessment, groundwater

investigation report, community involvement plan, and technical memorandum describing focused groundwater and vapor intrusion investigation activities and findings.

U.S. Navy – NAVFAC Mid-Atlantic, Naval Station Newport, pre-design investigation at contaminated bedrock aquifer site, Middletown, Rhode Island. Paul served as project manager for a groundwater pre-design investigation at a contaminated bedrock aquifer site where previous in situ bioremediation had limited success with reducing chlorinated volatile organic compound (CVOC) concentrations in groundwater. He developed a hydraulic testing approach using pump tests and a bromide tracer test to improve understanding of the distribution of an amendment injected into a single well. Coordinated and managed vegetation clearing, a well inventory, two comprehensive site-wide groundwater gauging and sampling events, and preparation of a hydraulic testing work plan and a groundwater pre-design investigation report.

U.S. Navy – NAVFAC Mid-Atlantic, Naval Station Newport, remedial investigation at former tank farm, Portsmouth, Rhode Island. As project hydrogeologist, Paul developed a remedial investigation approach and conducted data analysis to apportion sources of total petroleum hydrocarbons (TPH) in soil at a former tank farm. The approach consisted of grid-based soil sampling across the previously delineated petroleum-impacted area; analysis of soil samples for TPH, saturated hydrocarbons, and biomarkers; and statistical analysis and petroleum fingerprinting of soil data to apportion heavy and mid-distillate components of the TPH that exceed the site cleanup goal. The approach was incorporated into the sampling and analysis plan for the site. Following soil sample and data acquisition, Paul managed data analysis and source apportionment.

U.S. Navy – NAVFAC Mid-Atlantic, Naval Station Newport, groundwater discharge to surface water investigation, Middletown, Rhode Island. Paul served as project hydrogeologist and developed an investigation approach that incorporated aerial infrared imaging, focused porewater sampling, and a vertical tracer study to evaluate groundwater discharge to an estuary. The approach was incorporated into the draft thermal imaging and vertical tracer testing work plan.

Confidential client – former New York air brake manufacturing facility, post-closure operations, maintenance, and monitoring, Watertown, New York. Paul was the project manager for ongoing operations, maintenance, and monitoring (OM&M) of a former manufacturing facility in the 19th year of a 30-year post-closure OM&M program. He managed project tasks, budget, and invoicing. Technical tasks included evaluation of groundwater elevation and chemical data to assess the long-term effectiveness of a groundwater pump and treat system that was installed to remove and prevent off-site transport of volatile organic compounds (VOCs) in groundwater. Paul prepared Annual Groundwater Monitoring Reports that presented findings from the data evaluation to the New York State Department of Environmental Conservation (NYSDEC), and prepared and submitted to NYSDEC a Periodic Review Report that summarized the protectiveness of engineering controls operated and maintained at the site during the previous three years.

Confidential client – former Henry Harris Landfill, remedial investigation and remedial action work plan development, Harrison Township, New Jersey. As the project geologist and task manager, Paul developed a conceptual site model for a former sanitary landfill site that incorporated understanding of the site hydrogeology, contaminant sources, and contaminant distribution to identify data gaps in completing the site remedial investigation (RI). He managed field activities to address data gaps with the RI, which included evaluation of groundwater-surface water interactions, installation of monitoring wells, and targeted soil sampling at soil-related areas of concern. Paul prepared a subsequent Remedial Action Work Plan for soil, groundwater, and surface water at the site, which incorporated the landfill closure plan and proposed Monitored Natural Attenuation (MNA) to address impacts to groundwater. Following implementation of a quarterly groundwater monitoring program, multiple lines of evidence in support of MNA as an effective remedy for groundwater were presented in a Groundwater Remedial Action Report.

Ingersoll Rand – manufacturing facility, pilot and full-scale bioremediation implementation, Hamilton, New Jersey. As project geologist**,** Paul managed and provided field oversight of a full-scale enhanced in situ bioremediation (EISB) remedy to address elevated concentrations of chlorinated VOCs in shallow groundwater at an active manufacturing facility. The full-scale remedy included delivery of emulsified vegetable oil (EVO), ZVI, and KB-1 Plus® microbial culture to outdoor and indoor injection locations. The full-scale remedy was implemented following the completion of a field-scale EISB pilot study that included delivery of amendments under pressure and gravity-fed conditions. Prior to the full-scale EISB remedy, a Groundwater Remedial Action Workplan was prepared that summarized the remedial investigation progress, results of the field pilot study, and scope of work for implementation of the full-scale remedy.

Ingersoll Rand – former manufacturing facility, remedial investigation and conceptual site model refinement, Phillipsburg, New Jersey. Paul served as the field geologist and task manager for the drilling, geophysical logging, packer testing, and construction of monitoring wells in a karst subsurface. Coordinated drilling, investigation-derived waste, and geophysical logging/packer testing subcontractors that included managing changes to the schedule based on variability in subsurface conditions. Monitoring well construction was based on the analytical results for(VOCs in groundwater samples collected from multiple depth intervals within each borehole. Dual or triplet monitoring wells were installed at multiple locations to characterize VOCs in groundwater with depth and provide data on VOC concentrations at the water table (shallow well) for evaluation of potential vapor intrusion.

In addition, Paul analyzed and summarized approximately 20 years of groundwater gauging and analytical data from approximately 80 monitoring and recovery wells at this 383-acre site as part of the conceptual site model development and refinement. Groundwater levels, fracture orientations, chlorinated VOC concentrations, and light nonaqueous phase liquid (LNAPL) extent data were evaluated as part of the conceptual site model development.

NICOLE MOONEY

Assistant Project Manager | Geologist

EDUCATION

B.S., Earth and Environmental Science with a minor in Oceanography, University of Michigan-Ann Arbor

SPECIAL STUDIES AND COURSES

40-Hour OSHA Hazardous Waste Operations and Emergency Response Training (29 CFR 1910.120)
8-Hour OSHA Hazardous Waste Worker Refresher Training (29 CFR 1910.120)
8-Hour OSHA HAZWOPER Supervisor for Construction Training
OSHA 10-Hour Construction Safety
OSHA 30-Hour Construction
NYC SST-307 8-Hour Fall Prevention for Construction
NYC SST-302 2-Hour Drug and Alcohol Awareness for Construction
DOT Hazmat Employee & RCRA Hazardous Waste Generator Training
American Red Cross Adult First Aid/CPR/AED Training and Bloodborne Pathogens Training
USACE Construction Quality Management for Contractors
Level I Antiterrorism Awareness Training

Nicole is a geologist with over four years of experience in site characterization and investigation, subsurface investigations, preparation of technical reports and work plans, and data collection and analysis. She has extensive experience conducting Phase I Environmental Site Assessments (ESAs), Phase II Environmental Site Investigations (ESIs), and other aspects of environmental due diligence. She has experience with preparation and overseeing execution of remedial investigation and actions at sites within the New York State Department of Environmental Conservation (NYSDEC) Brownfield Cleanup Program (BCP) and the New York City Mayor's Office of Environmental Remediation (NYCOER). She has performed soil, groundwater, and soil vapor sampling events and has drafted various site investigation plans and reports.

RELEVANT PROJECT EXPERIENCE

Environmental Investigation, Site Characterization, and Remediation

340 Myrtle Development LLC, 340 Myrtle Avenue, Brooklyn, New York. As a project geologist, Nicole coordinated and managed implementation of the Remedial Action Work Plan (RAWP) at the approximately 8,828 square foot site enrolled in the NYSDEC BCP. The remedial action included excavation and off-site disposal of soil, installation of an active sub-slab depressurization system (including cover system), installation of injection wells, and reinstallation of permanent monitoring wells for post-remedy groundwater monitoring. Nicole was responsible for the preparation of the Final Engineering Report (FER) and the Site Management Plan (SMP) which are undergoing review by the NYSDEC. Construction for the new development is currently ongoing and, when completed, the site will be improved with a new eight-story mixed-use commercial and residential building with a full cellar level.

B Contractors Group, LLC, 711-713 East 214th Street, Bronx, New York. As a project geologist, Nicole was responsible for coordinating and managing the implementation of the NYCOER-approved Remedial Action Plan (RAP) and preparing the Remedial Closure Report (RCR) for the approximately 6,252 square foot site. The redevelopment included a new eight-story residential building with a full cellar level.

650 Southern Blvd Bronx LLC, 650 Southern Boulevard, Bronx, New York. As a project geologist, Nicole was responsible for preparation and implementation of the Remedial Investigation Work Plan (RIWP), which included the installation of eleven soil borings, seven permanent groundwater monitoring wells (some of which extended into

bedrock), and seven soil vapor points, and the collection of soil, groundwater, and soil vapor samples. Nicole was also responsible for preparation of the Citizen Participation Plan (CPP), Remedial Investigation Report (RIR), and RAWP. The site is in the pre-construction phase.

Degraw Holdings LLC, 563 Sackett Street Site, Brooklyn, New York. As a project geologist, Nicole was responsible for due diligence during acquisition, including preparation of the Phase I ESA and Limited Phase II ESI. The initial Limited Phase II ESI and delineation sampling have been completed and the Limited Phase II ESI Delineation Report, Brownfield Cleanup Agreement (BCA) Major Amendment Application, and Supplemental Remedial Investigation Report (SRIR) are being drafted.

291 Wallabout Realty LLC, 291 Wallabout Street, Brooklyn, New York. As a project geologist, Nicole was responsible for the due diligence during acquisition of the property, including preparation of a Phase I ESA, Phase II ESI, BCP Application, and RIWP.

401 West 207th Realty LLC, 401 West 207th Street, New York, New York. As a project geologist, Nicole was responsible for oversight during implementation of the RAWP under the NYSDEC BCP. During remediation, Nicole observed and documented the excavation and proper disposal of on-site soil required for installation of the foundational elements. Nicole oversaw the proper cleaning and removal of two underground storage tanks encountered during excavation.

BCP Applications and Remedial Investigation Work Plans for NYSDEC. Nicole has prepared several BCP Application packages for various clients in New York State, which requires reviewing the site's history, including any previous investigation reports available, to assist with entry into the BCP to be remediated and redeveloped in accordance with applicable NYSDEC requirements. Nicole also prepares an RIWP to be submitted to the NYSDEC either concurrently or following submittal of the BCP Application for full investigation of the site to facilitate proper remedial action.

Excavation Oversight and CAMP Monitoring, Various Sites, Bronx, Brooklyn, and Queens, New York. As a project geologist, Nicole completed remedial oversight for several projects in the NYCOER cleanup program and NYSDEC BCP. Her responsibilities included excavation oversight, air monitoring, truck logging during off-site disposal of excavated materials, collection of endpoint and/or documentation samples, vapor barrier inspection, and oversight of installation of post-remedy groundwater monitoring wells.

Multiple Clients, Phase I ESAs and Due Diligence, Multiple Locations in New York. As a project geologist, Nicole completed several Phase I ESAs for buyers of properties in New York. She has extensive experience completing site reconnaissance and reviewing historical site documentation to identify potential environmental concerns at properties.

Multiple Clients, Phase II ESIs, Multiple Locations in New York. As a project geologist, Nicole conducted several Phase II ESIs for projects in New York, including oversight of the installation of soil borings, groundwater monitoring wells, and soil vapor points and the collection of soil, groundwater, and soil vapor samples. She assisted with the development of sampling plans based on previous environmental investigations and due diligence findings.

Former Grissom Air Force Base, Kokomo, Indiana. As a project geologist, Nicole was responsible for coordinating and performing quarterly groundwater sampling and/or Land Use Control (LUC) inspections in accordance with the deeds and Decision Documents for nine sites (FT001, FT002, SS190, SS035, SS053, SS058, LF003, LF004, and SS049) located on the 2,722-acre former Grissom Air Force Base under the Base Realignment and Closure (BRAC)/Environmental Construction Optimization Services (BECOS) program. Nicole was also responsible for the coordination and implementation of a Data Gap Investigation (DGI) at the SS035, SS053, and SS058 sites and a Site Investigation (SI) at the former Navy Skeet Range (site SR406). Nicole prepared LUC Inspection reports, Annual Groundwater Monitoring Reports, an SI Report, a DGI Report, and the Five-Year Review Report for this work.

APPENDIX F
NYSDEC Request to Import/Reuse Form

NEW YORK STATE
DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Request to Import/Reuse Fill or Soil

This form is based on the information required by DER-10, Section 5.4(e) and 6NYCRR Part 360.13. Use of this form is not a substitute for reading the applicable regulations and Technical Guidance document.

SECTION 1 – SITE BACKGROUND

The allowable site use is: Choose an item

Have Ecological Resources been identified? Choose an item

Is this soil originating from the site? Choose an item

How many cubic yards of soil will be imported/reused? Choose an item

If greater than 1000 cubic yards will be imported, enter volume to be imported:

SECTION 2 – MATERIAL OTHER THAN SOIL

Is the material to be imported gravel, rock or stone? Choose an item

Does it contain less than 10%, by weight, material that passes a size 100 sieve? Choose an item

Is this virgin material from a permitted mine or quarry? Choose an item

Is this material recycled concrete or brick from a DEC registered processing facility? Choose an item

SECTION 3 - SAMPLING

Provide a brief description of the number and type of samples collected in the space below:

Example Text: 5 discrete samples were collected and analyzed for VOCs. 2 composite samples were collected and analyzed for SVOCs, Inorganics & PCBs/Pesticides.

If the material meets requirements of DER-10 section 5.4(e)5 (other material), no chemical testing needed.

SECTION 3 CONT'D - SAMPLING

Provide a brief written summary of the sampling results or attach evaluation tables (compare to DER-10, Appendix 5):

Example Text: Arsenic was detected up to 17 ppm in 1 (of 5) samples; the allowable level is 16 ppm.

If Ecological Resources have been identified use the "If Ecological Resources are Present" column in Appendix 5.

SECTION 4 – SOURCE OF FILL

Name of person providing fill and relationship to the source:

Location where fill was obtained:

Identification of any state or local approvals as a fill source:

If no approvals are available, provide a brief history of the use of the property that is the fill source:

Provide a list of supporting documentation included with this request:

The information provided on this form is accurate and complete.

_____ _____

Signature Date

_____

Print Name

_____

Firm

Revised April 2023

APPENDIX G
Environmental Footprint Analysis and Climate Screening Checklist

H & A OF NEW YORK ENGINEERING
AND GEOLOGY, LLP
213 W. 35th Street
7th Floor
New York, NY 10001
646.277.5685

October 8, 2025
File No. 0210815

New York State Department of Environmental Conservation
Division of Environmental Remediation
625 Broadway, 12th Floor
Albany, NY 12233-7014

Subject: Interim Remedial Measure Work Plan
4001 4th Avenue Redevelopment Site
4001-4011 4th Avenue
Brooklyn, New York
BCP Site C224412

H & A of New York Engineering and Geology, LLP (Haley & Aldrich of New York) presents the following environmental footprint analysis in accordance with U.S. Environmental Protection Agency (EPA) 542-R-12-002 for the proposed Interim Remedial Measure Work Plan (IRMWP) of the above-referenced site located at 4001-4011 4th Avenue, Queens, New York (Site).

4001 4TH AVENUE REDEVELOPMENT SITE – PROPOSED WORK PLAN

The IRMWP is anticipated to result in estimated totals of:

- 1836.20 metric million British thermal units (MMBtus) of energy used;
- 147.30 tons of total greenhouse gas emissions (CO2e);
- 5705.67 pounds (lbs) of NOx + SOx +PM emissions; and,
- 21.43 lbs of Hazardous Air Pollutants (HAP) emissions.

Energy

- 140.35 MMbtus used for on-site activities, such as air monitoring.
- 0.26 MMbtus used for Grid Electricity Generation.
- 230.41 MMbtus used for transportation of personnel and equipment.
- 1,465.18 MMbtus used for off-site activities.

Greenhouse Gas Emissions (CO2e)

- 22,435.52 tons of CO2e produced from on-site activities, such as excavation.
- 42.09 tons of CO2e produced from Grid Electricity Generation.
- 37,234.76 tons of CO2e produced from transportation of personnel and equipment.
- 234,874.27 tons of CO2e produced from off-site activities.

Water Usage

- 8400 gallons of water are estimated to be used during the investigation.

Overall, the estimated environmental footprint of the IRMWP is dominated by off-site activities, which include off-site laboratory analysis and diesel fuel production. Transportation of materials and personnel is the next largest contributor to the environmental footprint of the IRMWP, which is anticipated to generate 37,235 lbs of CO2e and use 230 MMbtus of energy. Off-site energy use is anticipated to comprise 79.79 of all energy use and off-site greenhouse gas emissions to comprise 79.73 of all emissions for the investigation.

Sincerely yours,
H & A OF NEW YORK ENGINEERING AND GEOLOGY, LLP


Environmental Footprint Summary


Core Element	Metric		Unit of Measure	Footprint						
				Interim Remedial Measures	-	-	-	-	-	Total
Materials & Waste	M&W-1	Refined materials used on-site	Tons	7.0	0.0	0.0	0.0	0.0	0.0	7.0
	M&W-2	% of refined materials from recycled or reused material	%	0.0%						0.0%
	M&W-3	Unrefined materials used on-site	Tons	0.000	0.000	0.000	0.000	0.000	0.000	0.0
	M&W-4	% of unrefined materials from recycled or reused material	%							
	M&W-5	On-site hazardous waste disposed of off-site	Tons	0.0	0.0	0.0	0.0	0.0	0.0	0.0
	M&W-6	On-site non-hazardous waste disposed of off-site	Tons	8,415.8	0.0	0.0	0.0	0.0	0.0	8,415.8
	M&W-7	Recycled or reused waste	Tons	10.0	0.0	0.0	0.0	0.0	0.0	10.0
	M&W-8	% of total potential waste recycled or reused	%	0.1%						0.1%
Water (used on-site)	W-1	Public water use	MG	0.0084	0.0000	0.0	0.0	0.0	0.0	0.0084
	W-2	Groundwater use	MG	0.0	0.0	0.0	0.0	0.0	0.0	0.0
	W-3	Surface water use	MG	0.0	0.0	0.0	0.0	0.0	0.0	0.0
	W-4	Reclaimed water use	MG	0.0	0.0	0.0	0.0	0.0	0.0	0.0
	W-5	Storm water use	MG	0.0	0.0	0.0	0.0	0.0	0.0	0.0
	W-6	User-defined water resource #1	MG	0.0	0.0	0.0	0.0	0.0	0.0	0.0
	W-7	User-defined water resource #2	MG	0.0	0.0	0.0	0.0	0.0	0.0	0.0
	W-8	Wastewater generated	MG	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Energy	E-1	Total energy used (on-site and off-site)	MMBtu	1,836.2	0.0	0.0	0.0	0.0	0.0	1,836.2
	E-2	Energy voluntarily derived from renewable resources								
	E-2A	On-site renewable energy generation or use + on-site biodiesel use + biodiesel and other renewable resource use for transportation	MMBtu	0.0	0.0	0.0	0.0	0.0	0.0	0.0
	E-2B	Voluntary purchase of renewable electricity	MWh	0.0	0.0	0.0	0.0	0.0	0.0	0.0
	E-3	Voluntary purchase of RECs	MWh	0.0	0.0	0.0	0.0	0.0	0.0	0.0
	E-4	On-site grid electricity use	MWh	0.037	0.000	0.000	0.000	0.000	0.000	0.0
Air	A-1	On-site NOx, SOx, and PM emissions	Pounds	111.1	0.0	0.0	0.0	0.0	0.0	111.1
	A-2	On-site HAP emissions	Pounds	0.0	0.0	0.0	0.0	0.0	0.0	0.0
	A-3	Total NOx, SOx, and PM emissions	Pounds	5,705.7	0.0	0.0	0.0	0.0	0.0	5,705.7
	A-3A	Total NOx emissions	Pounds	1,586.7	0.0	0.0	0.0	0.0	0.0	1,586.7
	A-3B	Total SOx emissions	Pounds	719.5	0.0	0.0	0.0	0.0	0.0	719.5
	A-3C	Total PM emissions	Pounds	3,399.5	0.0	0.0	0.0	0.0	0.0	3,399.5
	A-4	Total HAP emissions	Pounds	21.4	0.0	0.0	0.0	0.0	0.0	21.4
	A-5	Total greenhouse gas emissions	Tons CO2e*	147.3	0.0	0.0	0.0	0.0	0.0	147.3
Land & Ecosystems	Qualitative Description									


** Total greenhouse gases emissions (in CO2e) include consideration of CO2, CH4, and N2O (Nitrous oxide) emissions.*
"MMBtu" = millions of Btus
"MG" = millions of gallons
"CO2e" = carbon dioxide equivalents of global warming potential
"MWh" = megawatt hours (i.e., thousands of kilowatt-hours or millions of Watt-hours)
"Tons" = short tons (2,000 pounds)

The above metrics are consistent with EPA's Methodology for Understanding and Reducing a Project's Environmental Footprint (EPA 542-R-12-002), February 2012

Notes:


All Energy Use by Remedy Component and Scope
(in MMbtu)
2000
1800
1600
1400
1200
1000
800
600
400
200
0
Interim Remedial Measures
-
-
-
-
-
Other Off-Site (Scope 3b)
Transportation (Scope 3a)
Grid Electricity Generation (Scope 2)
On-site (Scope 1)
Total Energy All Components = 1836.2 MMbtus


All Energy Use by Remedy Component
Interim Remedial Measures = 100%
- = 0%
- = 0%
- = 0%
- = 0%
- = 0%
Total Energy All Components = 1836.2 MMbtus



All Energy Use by Scope
On-site (Scope 1) = 7.6%
Grid Electricity Generation (Scope 2) = 0%
Transportation (Scope 3a) = 12.5%
Other Off-Site (Scope 3b) = 79.8%
Total Energy All Scopes = 1836.2 MMbtus


Total Energy MMbtus							
	Interim Remedial Measures	-	-	-	-	-	Total
On-site (Scope 1)	140.3	0.0	0.0	0.0	0.0	0.0	140.3
Grid Electricity Generation (Scope 2)	0.3	0.0	0.0	0.0	0.0	0.0	0.3
Transportation (Scope 3a)	230.4	0.0	0.0	0.0	0.0	0.0	230.4
Other Off-Site (Scope 3b)	1,465.2	0.0	0.0	0.0	0.0	0.0	1,465.2
Total	1,836.2	0.0	0.0	0.0	0.0	0.0	1,836.2


Interim Remedial Measures = 100%
- = 0%
- = 0%
- = 0%
- = 0%
- = 0%

Total Energy All Components = 1836.2 MMbtus
Total Energy All Scopes = 1836.2 MMbtus

On-site (Scope 1) = 7.6%
Grid Electricity Generation (Scope 2) = 0%
Transportation (Scope 3a) = 12.5%
Other Off-Site (Scope 3b) = 79.8%


All GHG Emissions by Remedy Component and Scope
(in Tons)
160
140
120
100
80
60
40
20
0
Interim Remedial Measures
-
-
-
-
-
Other Off-Site (Scope 3b)
Transportation (Scope 3a)
Grid Electricity Generation (Scope 2)
On-site (Scope 1)
GHG All Components = 147.3 Tons CO2e


All GHG Emissions by Remedy Component
Interim Remedial Measures = 100%
- = 0%
- = 0%
- = 0%
- = 0%
- = 0%
GHG All Components = 147.3 Tons CO2e



All GHG Emissions by Scope
On-site (Scope 1) = 7.6%
Grid Electricity Generation (Scope 2) = 0%
Transportation (Scope 3a) = 12.6%
Other Off-Site (Scope 3b) = 79.7%
GHG All Scopes = 147.3 Tons CO2e


GHG Tons CO2e							
	Interim Remedial Measures	-	-	-	-	-	Total
On-site (Scope 1)	11.2	0.0	0.0	0.0	0.0	0.0	11.2
Grid Electricity Generation (Scope 2)	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Transportation (Scope 3a)	18.6	0.0	0.0	0.0	0.0	0.0	18.6
Other Off-Site (Scope 3b)	117.4	0.0	0.0	0.0	0.0	0.0	117.4
Total	147.3	0.0	0.0	0.0	0.0	0.0	147.3


Interim Remedial Measures = 100%
- = 0%
- = 0%
- = 0%
- = 0%
- = 0%

GHG All Components = 147.3 Tons CO2e
GHG All Scopes = 147.3 Tons CO2e

On-site (Scope 1) = 7.6%
Grid Electricity Generation (Scope 2) = 0%
Transportation (Scope 3a) = 12.6%
Other Off-Site (Scope 3b) = 79.7%


All NOx Emissions by Remedy Component by Scope
(in Lbs)
1800
1600
1400
1200
1000
800
600
400
200
0
Interim Remedial Measures
-
-
-
-
-
Other Off-Site (Scope 3b)
Transportation (Scope 3a)
Grid Electricity Generation (Scope 2)
On-site (Scope 1)
NOx All Components = 1586.7 lbs


All NOx Emissions by Remedy Component
Interim Remedial Measures = 100%
- = 0%
- = 0%
- = 0%
- = 0%
- = 0%
NOx All Components = 1586.7 lbs



All NOx Emissions by Scope
On-site (Scope 1) = 6.4%
Grid Electricity Generation (Scope 2) = 0%
Transportation (Scope 3a) = 16.1%
Other Off-Site (Scope 3b) = 77.4%
NOx All Scopes = 1586.7 lbs


NOx lbs							
	Interim Remedial Measures	-	-	-	-	-	Total
On-site (Scope 1)	101.9	0.0	0.0	0.0	0.0	0.0	101.9
Grid Electricity Generation (Scope 2)	0.1	0.0	0.0	0.0	0.0	0.0	0.1
Transportation (Scope 3a)	256.1	0.0	0.0	0.0	0.0	0.0	256.1
Other Off-Site (Scope 3b)	1,228.7	0.0	0.0	0.0	0.0	0.0	1,228.7
Total	1,586.7	0.0	0.0	0.0	0.0	0.0	1,586.7


Interim Remedial Measures = 100%
- = 0%
- = 0%
- = 0%
- = 0%
- = 0%

NOx All Components = 1586.7 lbs
NOx All Scopes = 1586.7 lbs

On-site (Scope 1) = 6.4%
Grid Electricity Generation (Scope 2) = 0%
Transportation (Scope 3a) = 16.1%
Other Off-Site (Scope 3b) = 77.4%


All SOx Emissions by Remedy Component and Scope
(in Lbs)
800
700
600
500
400
300
200
100
0
Interim Remedial Measures
-
-
-
-
-
Other Off-Site (Scope 3b)
Transportation (Scope 3a)
Grid Electricity Generation (Scope 2)
On-site (Scope 1)
SOx All Components = 719.5 lbs


All SOx Emissions by Remedy Component
Interim Remedial Measures = 100%
- = 0%
- = 0%
- = 0%
- = 0%
- = 0%
SOx All Components = 719.5 lbs



All SOx Emissions by Scope
On-site (Scope 1) = 0%
Grid Electricity Generation (Scope 2) = 0%
Transportation (Scope 3a) = 1.1%
Other Off-Site (Scope 3b) = 98.8%
SOx All Scopes = 719.5 lbs


	SOx lbs						
	Interim Remedial Measures	-	-	-	-	-	Total
On-site (Scope 1)		0.1	0.0	0.0	0.0	0.0	0.1
Grid Electricity Generation (Scope 2)		0.2	0.0	0.0	0.0	0.0	0.2
Transportation (Scope 3a)		8.0	0.0	0.0	0.0	0.0	8.0
Other Off-Site (Scope 3b)		711.2	0.0	0.0	0.0	0.0	711.2
Total		719.5	0.0	0.0	0.0	0.0	719.5


Interim Remedial Measures = 100%
- = 0%
- = 0%
- = 0%
- = 0%
- = 0%

SOx All Components = 719.5 lbs
SOx All Scopes = 719.5 lbs

On-site (Scope 1) = 0%
Grid Electricity Generation (Scope 2) = 0%
Transportation (Scope 3a) = 1.1%
Other Off-Site (Scope 3b) = 98.8%


All PM Emissions by Remedy Component and Scope
(in Lbs)
4000
3500
3000
2500
2000
1500
1000
500
0
Interim Remedial Measures
-
-
-
-
-
Other Off-Site (Scope 3b)
Transportation (Scope 3a)
Grid Electricity Generation (Scope 2)
On-site (Scope 1)
PM All Components = 3399.5 lbs


All PM Emissions by Remedy Component
Interim Remedial Measures = 100%
- = 0%
- = 0%
- = 0%
- = 0%
- = 0%
PM All Components = 3399.5 lbs


All PM Emissions by Scope
On-site (Scope 1) = 0.3%
Grid Electricity Generation (Scope 2) = 0%
Transportation (Scope 3a) = 0.2%
Other Off-Site (Scope 3b) = 99.6%
PM All Scopes = 3399.5 lbs


PM
lbs


	Interim Remedial Measures	-	-	-	-	-	Total
On-site (Scope 1)	9.1	0.0	0.0	0.0	0.0	0.0	9.1
Grid Electricity Generation (Scope 2)	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Transportation (Scope 3a)	5.6	0.0	0.0	0.0	0.0	0.0	5.6
Other Off-Site (Scope 3b)	3,384.8	0.0	0.0	0.0	0.0	0.0	3,384.8
Total	3,399.5	0.0	0.0	0.0	0.0	0.0	3,399.5


Interim Remedial Measures = 100%
- = 0%
- = 0%
- = 0%
- = 0%
- = 0%

PM All Components = 3399.5 lbs
PM All Scopes = 3399.5 lbs

On-site (Scope 1) = 0.3%
Grid Electricity Generation (Scope 2) = 0%
Transportation (Scope 3a) = 0.2%
Other Off-Site (Scope 3b) = 99.6%


All HAPs Emissions by Remedy Component and Scope
(in Lbs)
25
20
15
10
5
0
Interim Remedial Measures
-
-
-
-
-
Other Off-Site (Scope 3b)
Transportation (Scope 3a)
Grid Electricity Generation (Scope 2)
On-site (Scope 1)
HAPs All Components = 21.4 lbs


All HAP Emissions by Remedy Component
Interim Remedial Measures = 100%
- = 0%
- = 0%
- = 0%
- = 0%
- = 0%
HAPs All Components = 21.4 lbs


All HAP Emissions by Scope
On-site (Scope 1) = 0.2%
Grid Electricity Generation (Scope 2) = 0%
Transportation (Scope 3a) = 6.7%
Other Off-Site (Scope 3b) = 93.1%
HAPs All Scopes = 21.4 lbs

HAPs lbs							
	Interim Remedial Measures	-	-	-	-	-	Total
On-site (Scope 1)		0.0	0.0	0.0	0.0	0.0	0.0	0.0
Grid Electricity Generation (Scope 2)		0.0	0.0	0.0	0.0	0.0	0.0	0.0
Transportation (Scope 3a)		1.4	0.0	0.0	0.0	0.0	0.0	1.4
Other Off-Site (Scope 3b)		19.9	0.0	0.0	0.0	0.0	0.0	19.9
Total		21.4	0.0	0.0	0.0	0.0	0.0	21.4

Interim Remedial Measures = 100%
- = 0%
- = 0%
- = 0%
- = 0%
- = 0%

HAPs All Components = 21.4 lbs
HAPs All Scopes = 21.4 lbs

On-site (Scope 1) = 0.2%
Grid Electricity Generation (Scope 2) = 0%
Transportation (Scope 3a) = 6.7%
Other Off-Site (Scope 3b) = 93.1%

Spreadsheets for Environmental Footprint Analysis (SEFA) Version 3.0, November 2019
4001 4th Avenue Redevelopment Site - Interim Remedial Measure Work Plan

Input Summary

Remedy Component Number →		1	2	3	4	5	6									Remedy Component Subtotals						
		Column headings in Row 6 must match the name of "Input" tabs in this workbook for Columns C - P in this table to be populated ("0" in Row 4 means "Input" tab is turned Off and will not be grouped to a Remedy Component (Columns Q - V) or used in subsequent calculations)																				
Item		Interim Remedial Measures	Input Template (2)	Input Template (3)	Input Template (4)	Input Template (5)	Input Template (6)	Input Template (7)	Input Template (8)	Input Template (9)	Input Template (10)	Input Template (11)	Input Template (12)	Input Template (13)	Input Template (14)	1	2	3	4	5	6	Total
On-Site																						
On-site Renewable Energy																						
Renewable electricity generated on-site	MWh	0														0	0	0	0	0	0	0
Landfill gas combusted on-site for energy use	ccf CH_4	0														0	0	0	0	0	0	0
On-site biodiesel use	gal	0														0	0	0	0	0	0	0
On-site biodiesel use - Other	gal	0														0	0	0	0	0	0	0
User-defined on-site renewable energy use #1	TBD	0														0	0	0	0	0	0	0
User-defined on-site renewable energy use #2	TBD	0														0	0	0	0	0	0	0
On-Site Conventional Energy																						
Grid electricity	MWh	0.03744														0.03744	0	0	0	0	0	0.03744
On-site diesel use - Other	Gal	0														0	0	0	0	0	0	0
On-site diesel use <75 hp	Gal	0														0	0	0	0	0	0	0
On-site diesel use 75<hp<750	Gal	1008.791209														1008.7912	0	0	0	0	0	1008.7912
On-site diesel use >750 hp	Gal	0														0	0	0	0	0	0	0
On-site gasoline use - Other	Gal	0														0	0	0	0	0	0	0
On-site gasoline use <25 hp	Gal	0														0	0	0	0	0	0	0
On-site gasoline use >25 hp	Gal	0														0	0	0	0	0	0	0
On-site natural gas use	ccf	0														0	0	0	0	0	0	0
On-site compressed natural gas use - Other	ccf	0														0	0	0	0	0	0	0
On-site compressed natural gas use	ccf	0														0	0	0	0	0	0	0
On-site liquified petroleum gas use - Other	gal	0														0	0	0	0	0	0	0
On-site liquified petroleum gas use	gal	0														0	0	0	0	0	0	0
Other forms of on-site conventional energy use #1	TBD	0														0	0	0	0	0	0	0
Other forms of on-site conventional energy use #2	TBD	0														0	0	0	0	0	0	0
Other On-site Emissions																						
On-site HAP process emissions	Lbs	0														0	0	0	0	0	0	0
On-site GHG emissions	Lbs CO2e	0														0	0	0	0	0	0	0
On-site carbon storage	Lbs CO2e	0														0	0	0	0	0	0	0
GHG avoided by flaring on-site landfill methane	ccf CH4	0														0	0	0	0	0	0	0
Other on-site NOx emissions or reductions	Lbs	0														0	0	0	0	0	0	0
Other on-site SOx emissions or reductions	Lbs	0														0	0	0	0	0	0	0
Other on-site PM emissions or reductions	Lbs	0														0	0	0	0	0	0	0
Electricity Generation																						
Grid electricity	MWh	0.03744														0.03744	0	0	0	0	0	0.03744
Voluntary purchase of renewable electricity	MWh	0														0	0	0	0	0	0	0
Voluntary purchase of RECs	MWh	0														0	0	0	0	0	0	0
Transportation																						
Transportation Fuel Use Breakdown																						
Biodiesel use - Personnel Transport	gal	0														0	0	0	0	0	0	0
Biodiesel use - Personnel Transport - User Defined	gal	0														0	0	0	0	0	0	0
Biodiesel use - Equipment Transport	gal	0														0	0	0	0	0	0	0
Biodiesel use - Equipment Transport - User Defined	gal	0														0	0	0	0	0	0	0
Biodiesel use - Material Transport	gal	0														0	0	0	0	0	0	0
Biodiesel use - Material Transport - User Defined	gal	0														0	0	0	0	0	0	0
Biodiesel use - Waste Transport	gal	0														0	0	0	0	0	0	0
Biodiesel use - Waste Transport - User Defined	gal	0														0	0	0	0	0	0	0
Diesel use - Personnel Transport - other vehicles	gal	337.7														337.7	0	0	0	0	0	337.7
Diesel use - Personnel Transport - car	gal	0														0	0	0	0	0	0	0
Diesel use - Personnel Transport - passenger truck	gal	0														0	0	0	0	0	0	0
Diesel use - Personnel Transport - User Defined	gal	0														0	0	0	0	0	0	0
Diesel use - Equipment Transport	gal	10.8														10.8	0	0	0	0	0	10.8
Diesel use - Equipment Transport - User Defined	gal	0														0	0	0	0	0	0	0
Diesel use - Material Transport	gal	170.833														170.833	0	0	0	0	0	170.833
Diesel use - Material Transport - User Defined	gal	0														0	0	0	0	0	0	0
Diesel use - Waste Transport	gal	946.6														946.6	0	0	0	0	0	946.6
Diesel use - Waste Transport - User Defined	gal	0														0	0	0	0	0	0	0
Gasoline use - Personnel Transport - other vehicles	gal	0														0	0	0	0	0	0	0
Gasoline use - Personnel Transport - car	gal	80														80	0	0	0	0	0	80
Gasoline use - Personnel Transport - passenger truck	gal	134.9														134.9	0	0	0	0	0	134.9
Gasoline use - Personnel Transport - User Defined	gal	0														0	0	0	0	0	0	0
Gasoline use - Equipment Transport	gal	0														0	0	0	0	0	0	0
Gasoline use - Equipment Transport - User Defined	gal	0														0	0	0	0	0	0	0
Natural Gas use - Personnel Transport	ccf	0														0	0	0	0	0	0	0
Natural Gas use - Personnel Transport - User Defined	ccf	0														0	0	0	0	0	0	0
Natural Gas use - Equipment Transport	ccf	0														0	0	0	0	0	0	0

Spreadsheets for Environmental Footprint Analysis (SEFA) Version 3.0, November 2019
4001 4th Avenue Redevelopment Site - Interim Remedial Measure Work Plan

Input Summary

Remedy Component Number →		1	2	3	4	5	6									Remedy Component Subtotals						
		Column headings in Row 6 must match the name of "Input" tabs in this workbook for Columns C - P in this table to be populated ("0" in Row 4 means "Input" tab is turned Off and will not be grouped to a Remedy Component (Columns Q - V) or used in subsequent calculations)																				
Item		Interim Remedial Measures	Input Template (2)	Input Template (3)	Input Template (4)	Input Template (5)	Input Template (6)	Input Template (7)	Input Template (8)	Input Template (9)	Input Template (10)	Input Template (11)	Input Template (12)	Input Template (13)	Input Template (14)	1	2	3	4	5	6	Total
Conventional Energy																						
Transportation diesel use	gal	1465.933														1465.933	0	0	0	0	0	1465.933
Transportation gasoline use	gal	214.9														214.9	0	0	0	0	0	214.9
Transportation natural gas use	ccf	0														0	0	0	0	0	0	0
User-defined conventional energy transportation #1	TBD	0														0	0	0	0	0	0	0
User-defined conventional energy transportation #2	TBD	0														0	0	0	0	0	0	0
Renewable Energy																						
Transportation biodiesel use	gal	0														0	0	0	0	0	0	0
User-defined renewable energy transportation #1	TBD	0														0	0	0	0	0	0	0
User-defined renewable energy transportation #2	TBD	0														0	0	0	0	0	0	0
Off-Site																						
Construction Materials																						
Aluminum, Rolled Sheet	lb	0														0	0	0	0	0	0	0
Asphalt, mastic	lb	0														0	0	0	0	0	0	0
Asphalt, paving-grade	lb	0														0	0	0	0	0	0	0
Ethanol, Corn, 95%	lb	0														0	0	0	0	0	0	0
Ethanol, Corn, 99.7%	lb	0														0	0	0	0	0	0	0
Ethanol, Petroleum, 99.7%	lb	0														0	0	0	0	0	0	0
Gravel/Sand Mix, 65% Gravel	lb	0														0	0	0	0	0	0	0
Gravel/sand/clay	lb	0														0	0	0	0	0	0	0
HDPE	lb	0														0	0	0	0	0	0	0
Photovoltaic system (installed)	W	0														0	0	0	0	0	0	0
PVC	lb	0														0	0	0	0	0	0	0
Portland cement, US average	lb	0																				
Ready-mixed concrete, 20 MPa	ft3	0														0	0	0	0	0	0	0
Round Gravel	lb	0														0	0	0	0	0	0	0
Sand	lb	0														0	0	0	0	0	0	0
Stainless Steel	lb	0														0	0	0	0	0	0	0
Steel	lb	14055.69674														14055.697	0	0	0	0	0	14055.697
Other refined construction materials	lb	0														0	0	0	0	0	0	0
Other unrefined construction materials	lb	0														0	0	0	0	0	0	0
Treatment Materials & Chemicals																						
Cheese Whey	lbs	0														0	0	0	0	0	0	0
Emulsified vegetable oil	lbs	0														0	0	0	0	0	0	0
Granular activated carbon, primary	lbs	0														0	0	0	0	0	0	0
Granular activated carbon, regenerated	lbs	0														0	0	0	0	0	0	0
Hydrogen Peroxide, 50% in H2O	lbs	0														0	0	0	0	0	0	0
Iron (II) Sulfate	lbs	0														0	0	0	0	0	0	0
Lime, Hydrated, Packed	lbs	0														0	0	0	0	0	0	0
Molasses	lbs	0														0	0	0	0	0	0	0
Phosphoric Acid, 70% in H2O	lbs	0														0	0	0	0	0	0	0
Potassium Permanganate	lbs	0														0	0	0	0	0	0	0
Sodium Hydroxide, 50% in H2O	lbs	0														0	0	0	0	0	0	0
Other Treatment Chemicals & Materials	lbs	0														0	0	0	0	0	0	0
Material Type																						
Total Virgin Refined Materials	tons	7.027848368														7.0278484	0	0	0	0	0	7.0278484
Total Recycled Refined Materials	tons	0														0	0	0	0	0	0	0
Total Reused Refined Materials	tons	0														0	0	0	0	0	0	0
Total Refined Material	tons	7.027848368														7.0278484	0	0	0	0	0	7.0278484
Total Virgin Unrefined Materials	tons	0														0	0	0	0	0	0	0
Total Recycled Unrefined Materials	tons	0														0	0	0	0	0	0	0
Total Reused Unrefined Materials	tons	0														0	0	0	0	0	0	0
Total Unrefined Material	tons	0														0	0	0	0	0	0	0
Fuel Processing																						
Biodiesel produced	gal	0														0	0	0	0	0	0	0
Diesel produced	gal	2474.724209														2474.7242	0	0	0	0	0	2474.7242
Gasoline produced	gal	214.9														214.9	0	0	0	0	0	214.9
Compressed natural gas produced	ccf	0														0	0	0	0	0	0	0
Liquified petroleum gas produced	gal	0														0	0	0	0	0	0	0
Natural gas produced	ccf	0														0	0	0	0	0	0	0
Water Use																						
Public Water Supply	gal x 1000	8.4														8.4	0	0	0	0	0	8.4
Extracted Groundwater	gal x 1000	0														0	0	0	0	0	0	0
Surface Water	gal x 1000	0														0	0	0	0	0	0	0
Reclaimed Water	gal x 1000	0														0	0	0	0	0	0	0
Collected/Diverted Storm Water	gal x 1000	0														0	0	0	0	0	0	0
User-defined water resource #1	gal x 1000	0														0	0	0	0	0	0	0
User-defined water resource #2	gal x 1000	0														0	0	0	0	0	0	0

Input Summary

Remedy Component Number →		1	2	3	4	5	6									Remedy Component Subtotals						
		Column headings in Row 6 must match the name of "Input" tabs in this workbook for Columns C - P in this table to be populated ("0" in Row 4 means "Input" tab is turned Off and will not be grouped to a Remedy Component (Columns Q - V) or used in subsequent calculations)																				
Item		Interim Remedial Measures	Input Template (2)	Input Template (3)	Input Template (4)	Input Template (5)	Input Template (6)	Input Template (7)	Input Template (8)	Input Template (9)	Input Template (10)	Input Template (11)	Input Template (12)	Input Template (13)	Input Template (14)	1	2	3	4	5	6	Total
Waste/Recycle Handling																						
Hazardous waste incineration	lbs	0														0	0	0	0	0	0	0
Off-site waste water treatment (POTW)	gal x 1000	0														0	0	0	0	0	0	0
Off-site non-hazardous waste landfill	tons	8415.7632														8415.7632	0	0	0	0	0	8415.7632
Off-site hazardous waste landfill	tons	0														0	0	0	0	0	0	0
Recycled/Reused On-Site	tons	0														0	0	0	0	0	0	0
Recycled/Reused Off-Site	tons	10														10	0	0	0	0	0	10
Solid Waste Totals																						
Total Non-Hazardous Waste	tons	8415.7632														8415.7632	0	0	0	0	0	8415.7632
Total Hazardous Waste	tons	0														0	0	0	0	0	0	0
Total Recycled/Reused	tons	10														10	0	0	0	0	0	10
Total Waste (all types)	tons	8425.7632														8425.7632	0	0	0	0	0	8425.7632
Lab Services																						
Off-site Laboratory Analysis - Other	sample	36														36	0	0	0	0	0	36
Off-site Laboratory Analysis - Metals	sample	12														12	0	0	0	0	0	12
Off-site Laboratory Analysis - Mercury	sample	0														0	0	0	0	0	0	0
Off-site Laboratory Analysis - Inorganic Anions	sample	0														0	0	0	0	0	0	0
Off-site Laboratory Analysis - Alkalinity	sample	0														0	0	0	0	0	0	0
Off-site Laboratory Analysis - Perchlorate	sample	0														0	0	0	0	0	0	0
Off-site Laboratory Analysis - Nitrogen/Nitrate	sample	0														0	0	0	0	0	0	0
Off-site Laboratory Analysis - Sulfate	sample	0														0	0	0	0	0	0	0
Off-site Laboratory Analysis - PCBs	sample	12														12	0	0	0	0	0	12
Off-site Laboratory Analysis - VOCs	sample	18														18	0	0	0	0	0	18
Off-site Laboratory Analysis - SVOCs	sample	12														12	0	0	0	0	0	12
Resource Extraction for Electricity																						
Coal extraction and processing	MWh	0.0114192														0.0114192	0	0	0	0	0	0.0114192
Natural gas extraction and processing	MWh	0.01269216														0.0126922	0	0	0	0	0	0.0126922
Nuclear fuel extraction and processing	MWh	0.00741312														0.0074131	0	0	0	0	0	0.0074131
Oil extraction and processing	MWh	0.00026208														0.0002621	0	0	0	0	0	0.0002621
Other fuel extraction and processing	MWh	0.00003744														3.744E-05	0	0	0	0	0	3.744E-05
Electricity Transmission																						
Transmission and distribution losses	MWh	0.03744														0.03744	0	0	0	0	0	0.03744

Input Summary

Remedy Component Number →		1	2	3	4	5	6									Remedy Component Subtotals						
		Column headings in Row 6 must match the name of "Input" tabs in this workbook for Columns C - P in this table to be populated ("0" in Row 4 means "Input" tab is turned Off and will not be grouped to a Remedy Component (Columns Q - V) or used in subsequent calculations)																				
Item		Interim Remedial Measures	Input Template (2)	Input Template (3)	Input Template (4)	Input Template (5)	Input Template (6)	Input Template (7)	Input Template (8)	Input Template (9)	Input Template (10)	Input Template (11)	Input Template (12)	Input Template (13)	Input Template (14)	1	2	3	4	5	6	Total
Other																						
User-defined material #1	gal	0														0	0	0	0	0	0	0
User-defined material #2	TBD	0														0	0	0	0	0	0	0
User-defined material #3	TBD	0														0	0	0	0	0	0	0
User-defined material #4	TBD	0														0	0	0	0	0	0	0
User-defined material #5	TBD	0														0	0	0	0	0	0	0
User-defined material #6	TBD	0														0	0	0	0	0	0	0
User-defined material #7	TBD	0														0	0	0	0	0	0	0
User-defined material #8	TBD	0														0	0	0	0	0	0	0
User-defined material #9	TBD	0														0	0	0	0	0	0	0
User-defined material #10	TBD	0														0	0	0	0	0	0	0
User-defined material #11	TBD	0														0	0	0	0	0	0	0
User-defined material #12	TBD	0														0	0	0	0	0	0	0
User-defined material #13	TBD	0														0	0	0	0	0	0	0
User-defined material #14	TBD	0														0	0	0	0	0	0	0
User-defined material #15	TBD	0														0	0	0	0	0	0	0
User-defined material #16	TBD	0														0	0	0	0	0	0	0
User-defined material #17	TBD	0														0	0	0	0	0	0	0
User-defined material #18	TBD	0														0	0	0	0	0	0	0
User-defined material #19	TBD	0														0	0	0	0	0	0	0
User-defined material #20	TBD	0														0	0	0	0	0	0	0
User-defined Waste Destinations																						
User-defined recycled/reused on-site #1	TBD	0														0	0	0	0	0	0	0
User-defined recycled/reused on-site #2	TBD	0														0	0	0	0	0	0	0
User-defined recycled/reused on-site #3	TBD	0														0	0	0	0	0	0	0
User-defined recycled/reused off-site #1	TBD	0														0	0	0	0	0	0	0
User-defined recycled/reused off-site #2	TBD	0														0	0	0	0	0	0	0
User-defined recycled/reused off-site #3	TBD	0														0	0	0	0	0	0	0
User-defined non-hazardous waste destination #1	TBD	0														0	0	0	0	0	0	0
User-defined non-hazardous waste destination #2	TBD	0														0	0	0	0	0	0	0
User-defined non-hazardous waste destination #3	TBD	0														0	0	0	0	0	0	0
User-defined hazardous waste destination #1	TBD	0														0	0	0	0	0	0	0
User-defined hazardous waste destination #2	TBD	0														0	0	0	0	0	0	0
User-defined hazardous waste destination #3	TBD	0														0	0	0	0	0	0	0

Interim Remedial Measures - On-Site Footprint (Scope 1)

Contributors to Footprints	Units	Usage	Energy		GHG		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
On-Site														
On-site Renewable Energy														
Renewable electricity generated on-site	MWh	0	3.413	0										
Landfill gas combusted on-site for energy use	ccf CH4	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
On-site biodiesel use	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
On-site biodiesel use - User Defined	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
User-defined on-site renewable energy use #1	gal	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined on-site renewable energy use #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
On-site Renewable Energy Subtotals				**0**		**0**		**0**		**0**		**0**		**0**
Notes:														
On-site Conventional Energy														
On-site grid electricity	MWh	0.03744	3.413	0.127783										
On-site diesel use - Other	Gal	0	0.139	0	22.5	0	0.17	0	0.0054	0	0.0034	0	5.2E-06	0
On-site diesel use <75 hp	Gal	0	0.139	0	22.21	0	0.1565	0	0.000145	0	0.0145	0	0.00004	0
On-site diesel use 75<hp<750	Gal	1008.791	0.139	140.222	22.24	22435.52	0.101	101.8879	0.00013	0.131143	0.009	9.079121	0.00004	0.040352
On-site diesel use >750 hp	Gal	0	0.139	0	22.24	0	0.149	0	0.00013	0	0.006	0	0.00004	0
On-site gasoline use - Other	Gal	0	0.124	0	19.6	0	0.11	0	0.0045	0	0.00054	0	0.000039	0
On-site gasoline use <25 hp	Gal	0	0.124	0	17.48	0	0.037	0	0.00025	0	0.165	0	0.00008	0
On-site gasoline use >25 hp	Gal	0	0.124	0	19.93	0	0.032	0	0.00029	0	0.002	0	0.00009	0
On-site natural gas use	ccf	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
On-site compressed natural gas use - Other	ccf	0	NP		1957.835	0	16.0325	0	0.023045	0	0.2775	0	0	0
On-site compressed natural gas use	ccf	0	NP		1957.835	0	16.0325	0	0.023045	0	0.2775	0	0	0
On-site liquified petroleum gas use - Other	gal	0	NP		12.69	0	0.021	0	0.00013	0	0.001	0	0	0
On-site liquified petroleum gas use	gal	0	NP		12.69	0	0.021	0	0.00013	0	0.001	0	0	0
Other forms of on-site conventional energy use #1	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
Other forms of on-site conventional energy use #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
On-site Conventional Energy Subtotals				**140**		**22,436**		**102**		**0**		**9**		**0**
Notes:														
Other On-site Emissions														
On-site HAP process emissions	lbs	0											1	0
On-site GHG emissions	lbs CO2e	0			1	0								
On-site carbon storage	lbs CO2e	0			1	0								
GHG avoided by flaring on-site landfill methane	Lbs	0			-262	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
Other on-site NOx emissions or reductions	lbs	0					1	0						
Other on-site SOx emissions or reductions	lbs	0							1	0				
Other on-site PM emissions or reductions	lbs	0									1	0		
User-defined recycled/reused on-site #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined recycled/reused on-site #3	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined recycled/reused off-site #1	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
Notes:														
On-site Totals				**140.35**		**22,436**		**102**		**0**		**9**		**0**

Interim Remedial Measures - Electricity Generation Footprint (Scope 2)

Contributors to Footprints	Units	Usage	Energy		GHG		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
Electricity Generation														
Grid electricity	MWh	0.03744	6.929	0.259422	1124.3	42.09379	2.2421	0.083944	4.607887	0.172519	0.057518	0.002153	0.210237	0.007871
Voluntary purchase of renewable electricity	MWh	0												
Voluntary purchase of RECs	MWh	0												
Notes:														

Interim Remedial Measures - Transportation Footprint (Scope 3a)

Category	Units	Usage	Energy		Greenhouse Gas		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
Conventional Energy														
Transportation diesel use	gal	1465.933	0.139	203.7647	22.5	32983.49	0.17	249.2086	0.0054	7.916038	0.0034	4.984172	5.2E-06	0.007623
Transportation diesel use - car	gal	0	0.139	0	22.57	0	0.015	0	0.0002	0	0.003	0	0.00252	0
Transportation diesel use - passenger truck	gal	0	0.139	0	22.545	0	0.0585	0	0.0002	0	0.007	0	0.002605	0
Transportation diesel use - User Defined	gal	0	0.139	0	22.5	0	0.17	0	0.0054	0	0.0034	0	5.2E-06	0
Transportation gasoline use	gal	0	0.124	0	19.6	0	0.11	0	0.0045	0	0.00054	0	0.000039	0
Transportation gasoline use - car	gal	80	0.124	9.92	19.77	1581.6	0.027	2.16	0.00036	0.0288	0.003	0.24	0.0067	0.536
Transportation gasoline use - passenger truck	gal	134.9	0.124	16.7276	19.79	2669.671	0.035	4.7215	0.00036	0.048564	0.003	0.4047	0.00661	0.891689
Transportation gasoline use - User Defined	gal	0	0.124	0	19.6	0	0.11	0	0.0045	0	0.00054	0	0.000039	0
Transportation natural gas use	ccf	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
Transportation natural gas use - User Defined	ccf	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
User-defined conventional energy transportation #1	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined conventional energy transportation #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
Conventional Energy Subtotals				**230**		**37,235**		**256**		**8**		**6**		**1**
Notes:														
Renewable Energy														
Transportation biodiesel use	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
Transportation biodiesel use - User Defined	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
User-defined renewable energy transportation #1	TBD	0	Biodiesel		0	0	0	0	0	0	0	0	Ref.	
User-defined renewable energy transportation #2	TBD	0	npg or pmp		0	0	0	0	0	0	0	0	0	0
Renewable Energy Subtotals				**0**		**0**		**0**		**0**		**0**		**0**
Notes:														
Transportation Totals				**230**		**37235**		**256**		**8**		**6**		**1**

Interim Remedial Measures - Off-Site Footprint (Scope 3b)

Category	Units	Usage	Energy		Greenhouse Gas		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
Construction Materials														
Aluminum, Rolled Sheet	lb	0	0.0633	0	9.15	0	0.0148	0	0.0283	0	0.0088	0	0.00102	0
Asphalt, mastic	lb	0	0.0412	0	0.85	0	0.00271	0	0.00798	0	0.000766	0	0.00107	0
Asphalt, paving-grade	lb	0	0.5	0	8.58	0	0.0299	0	0.0969	0	0.0091	0	0.0133	0
Ethanol, Corn, 95%	lb	0	0.0318	0	-0.0199	0	0.00425	0	0.00303	0	0.000469	0	8.46E-05	0
Ethanol, Corn, 99.7%	lb	0	0.0324	0	0.0591	0	0.00431	0	0.0031	0	0.000472	0	0.000087	0
Ethanol, Petroleum, 99.7%	lb	0	0.0205	0	1.25	0	0.00199	0	0.00214	0	0.000277	0	5.89E-05	0
Gravel/Sand Mix, 65% Gravel	lb	0	2.48E-05	0	0.0024	0	0.000018	0	4.52E-06	0	2.61E-06	0	3.08E-07	0
Gravel/sand/clay	lb	0	0.000028	0	0.00335	0	1.65E-05	0	0.000015	0	0.000002	0	2.05E-10	0
HDPE	lb	0	0.0332	0	1.94	0	0.00325	0	0.00409	0	0.000439	0	6.41E-05	0
Photovoltaic system (installed)	W	0	0.0336	0	4.47	0	0.015	0	0.032	0	0.00063	0	2.9E-06	0
PVC	lb	0	0.0262	0	2.02	0	0.004	0	0.00274	0	0.000372	0	0.000375	0
Portland cement, US average	lb	0	0.0139	0	1.34	0	0.00654	0	0.0104	0	0.00378	0	0.00097	0
Ready-mixed concrete, 20 MPa	ft3	0	0.217	0	19.5	0	0.0975	0	0.154	0	0.057	0	0.0141	0
Round Gravel	lb	0	2.48E-05	0	0.0024	0	0.000018	0	4.52E-06	0	2.61E-06	0	3.08E-07	0
Sand	lb	0	2.48E-05	0	0.0024	0	0.000018	0	4.52E-06	0	2.61E-06	0	3.08E-07	0
Stainless Steel	lb	0	0.0116	0	3.4	0	0.0075	0	0.012	0	0.0044	0	0.000144	0
Steel	lb	14055.7	0.0044	61.84507	1.1	15461.27	0.0014	19.67798	0.0017	23.89468	0.00056	7.87119	0.000067	0.941732
Other refined construction materials	lb	0	0.01885	0	2.115	0	0.004038	0	0.005133	0	0.001443	0	0.000163	0
Other unrefined construction materials	lb	0	0.000028	0	0.00335	0	1.65E-05	0	0.000015	0	0.000002	0	2.05E-10	0

Notes:

Interim Remedial Measures - Off-Site Footprint (Scope 3b)

Category	Units	Usage	Energy		Greenhouse Gas		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
Treatment Materials & Chemicals														
Cheese Whey	lbs	0	0.0025	0	0.031	0	0.000062	0	0.000033	0	0.000002	0	NP	
Emulsified vegetable oil	lbs	0	0.0077	0	3.44	0	0.0066	0	0.0019	0	0.000033	0	NP	
Granular activated carbon, primary	lbs	0	0.0356	0	4.82	0	0.0793	0	0.128	0	0.000987	0	0.000657	0
Granular activated carbon, regenerated	lbs	0	0.00873	0	1.7	0	0.00733	0	0.0129	0	0.000886	0	0.000671	0
Hydrogen Peroxide, 50% in H2O	lbs	0	0.00979	0	1.19	0	0.00142	0	0.0024	0	0.000308	0	6.29E-05	0
Iron (II) Sulfate	lbs	0	0.00147	0	0.167	0	0.000316	0	0.000589	0	0.000103	0	0.000023	0
Lime, Hydrated, Packed	lbs	0	0.00206	0	0.762	0	0.000513	0	0.000358	0	0.00013	0	6.57E-06	0
Molasses	lbs	0	0.0044	0	0.48	0	0.0011	0	0.00024	0	4.1E-06	0	NP	
Phosphoric Acid, 70% in H2O	lbs	0	0.0067	0	0.882	0	0.00282	0	0.0294	0	0.00171	0	0.000163	0
Potassium Permanganate	lbs	0	0.00981	0	1.16	0	0.00234	0	0.0032	0	0.000422	0	0.000122	0
Sodium Hydroxide, 50% in H2O	lbs	0	0.00977	0	1.09	0	0.00194	0	0.00352	0	0.000403	0	0.000129	0
Other Treatment Chemicals & Materials	lbs	0	0.015	0	1.67	0	0.003	0	0.0065	0	0.00061	0	0.000016	0
Notes:														
Fuel Processing														
Biodiesel produced	gal	0	0.029	0	-16.8	0	0.018	0	0.033	0	0.00082	0	NP	
Diesel produced	gal	2474.724	0.017	42.07031	3.02	7473.667	0.0051	12.62109	0.0062	15.34329	0.0017	4.207031	0.0011	2.722197
Gasoline produced	gal	214.9	0.033	7.0917	2.8	601.72	0.0046	0.98854	0.005	1.0745	0.0015	0.32235	0.001	0.2149
Liquefied Petroleum Gas Produced	gal	0	0.088	0	1.47	0	0.0016	0	0.0024	0	0.0007	0	0.0003	0
Natural Gas - Compressed Produced	ccf	0	19.983	0	343.92	0	0.4732	0	2.1651	0	0.1846	0	0.2895	0
Natural Gas Produced	ccf	0	0.0052	0	2.2	0	0.0037	0	0.0046	0	0.000072	0	6.1E-06	0
Fuel Processing Subtotals				**49.16201**		**8075.387**		**13.60963**		**16.41779**		**4.529381**		**2.937097**
Notes:														
Public water	gal x 1000	8.4	0.0092	0.07728	5	42	0.0097	0.08148	0.0059	0.04956	0.016	0.1344	0.000015	0.000126
User-defined water resource #1	gal x 1000	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined water resource #2	gal x 1000	0	0	0	0	0	0	0	0	0	0	0	0	0
Notes:														

Interim Remedial Measures - Off-Site Footprint (Scope 3b)

Category	Units	Usage	Energy		Greenhouse Gas		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
Off-Site Services														
Hazardous waste incineration	lb	0	0.00609	0	2.43	0	0.0016	0	0.00167	0	0.000209	0	0.000087	0
Off-site waste water treatment (POTW)	gal x 1000	0	0.015	0	4.4	0	0.016	0	0.015	0	NP		NP	
Off-site non-hazardous waste landfill	ton	8415.763	0.16	1346.522	25	210394.1	0.14	1178.207	0.075	631.1822	0.4	3366.305	0.0014	11.78207
Off-site hazardous waste landfill	ton	0	0.18	0	27.5	0	0.154	0	0.0825	0	0.44	0	0.00154	0
Off-site Laboratory Analysis - Other	sample	36	0.058071	2.090557	6.853438	246.7238	0.131402	4.73047	0.303876	10.93953	0.04557	1.640514	0.033017	1.188595
Off-site Laboratory Analysis - Metals	sample	12	0.212	2.544	27.4693	329.6316	0.6423	7.7076	1.5072	18.0864	0.2264	2.7168	0.1643	1.9716
Off-site Laboratory Analysis - Mercury	sample	0	0.073171	0	9.325458	0	0.212744	0	0.49824	0	0.074736	0	0.054233	0
Off-site Laboratory Analysis - Inorganic Anions	sample	0	0.007402	0	0.645948	0	0.006768	0	0.014793	0	0.002202	0	0.001554	0
Off-site Laboratory Analysis - Alkalinity	sample	0	0.01744	0	1.338192	0	0.007011	0	0.01325	0	0.00194	0	0.001283	0
Off-site Laboratory Analysis - Perchlorate	sample	0	0.023885	0	1.871705	0	0.007981	0	0.014154	0	0.002055	0	0.001287	0
Off-site Laboratory Analysis - Nitrogen/Nitrate	sample	0	0.033648	0	4.29897	0	0.095459	0	0.222665	0	0.03351	0	0.024251	0
Off-site Laboratory Analysis - Sulfate	sample	0	0.014122	0	1.472673	0	0.007981	0	0.013602	0	0.00198	0	0.001202	0
Off-site Laboratory Analysis - PCBs	sample	12	0.051277	0.615323	5.224902	62.69882	0.083334	1.000007	0.190477	2.285729	0.028439	0.341272	0.021208	0.254499
Off-site Laboratory Analysis - VOCs	sample	18	0.076204	1.371681	9.016814	162.3027	0.104498	1.880965	0.227074	4.087328	0.033951	0.611115	0.023589	0.424606
Off-site Laboratory Analysis - SVOCs	sample	12	0.07156	0.858722	7.870422	94.44506	0.145945	1.751334	0.337304	4.047646	0.050485	0.605824	0.037258	0.447093
Notes:														
Resource Extraction for Electricity														
Coal extraction and processing	MWh	0.011419	3.1	0.034872	180.0	2.055456	0.8	0.008793	0.2	0.001713	0.0	0.000206	NP	
Natural gas extraction and processing	MWh	0.012692	1.6	0.020711	270.0	3.426883	0.2	0.002285	13.0	0.164998	0.0	9.01E-05	NP	
Nuclear fuel extraction and processing	MWh	0.007413	0.2	0.001153	25.0	0.185328	0.2	0.001112	0.5	0.003707	0.0	1.11E-05	NP	
Oil extraction and processing	MWh	0.000262	2.3	0.000602	270.0	0.070762	1.7	0.000446	0.1	1.81E-05	0.0	1.1E-05	NP	
Other fuel extraction and processing	MWh	3.74E-05	0	0	0	0	0	0	0	0	0	0	0	0
Resource Extraction Subtotals				**0.057337**		**5.738429**		**0.012635**		**0.170436**		**0.000318**		**0**
Notes:														
Electricity Transmission														
Transmission and distribution losses	MWh	0.03744	1.0342	0.03872	112.43	4.209379	0.22421	0.008394	0.460789	0.017252	0.005752	0.000215	0.021024	0.000787
Notes:														

Interim Remedial Measures - Off-Site Footprint (Scope 3b)

Category	Units	Usage	Energy		Greenhouse Gas		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
User-defined Materials														
User-defined material #1	gal	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #3	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #4	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #5	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #6	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #7	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #8	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #9	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #10	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #11	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #12	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #13	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #14	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #15	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #16	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #17	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #18	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #19	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #20	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
Notes:														
User-defined Waste Destinations														
User-defined recycled/reused off-site #1	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined recycled/reused off-site #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined recycled/reused off-site #3	TBD	0	y(MMBtu/u		(lbs CO2e/u		Ox(lbs/unit)		Ox(lbs/unit)		M(lbs/unit)		APs(lbs/unit	
User-defined non-hazardous waste destination #1	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined non-hazardous waste destination #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined non-hazardous waste destination #3	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined hazardous waste destination #1	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined hazardous waste destination #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined hazardous waste destination #3	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
Notes:														
Off-site Totals				**1465.183**		**234878.5**		**1228.667**		**711.1786**		**3384.756**		**19.9482**

Interim Remedial Measures - Intermediate Totals

Category	Units	Usage	Energy		Greenhouse Gas		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
Total Grid Electricity Footprint														
On-site grid electricity	MWh	0.03744	3.413	0.127783										
Electricity Generation														
Grid electricity	MWh	0.03744	6.929	0.259422	1124.3	42.09379	2.2421	0.083944	4.607887	0.172519	0.057518	0.002153	0.210237	0.007871
Resource Extraction for Electricity														
Coal extraction and processing	MWh	0.011419	3.1	0.034872	180.0	2.055456	0.8	0.008793	0.2	0.001713	0.0	0.000206	NP	
Natural gas extraction and processing	MWh	0.012692	1.6	0.020711	270.0	3.426883	0.2	0.002285	13.0	0.164998	0.0	9.01E-05	NP	
Nuclear fuel extraction and processing	MWh	0.007413	0.2	0.001153	25.0	0.185328	0.2	0.001112	0.5	0.003707	0.0	1.11E-05	NP	
Oil extraction and processing	MWh	0.000262	2.3	0.000602	270.0	0.070762	1.7	0.000446	0.1	1.81E-05	0.0	1.1E-05	NP	
Other fuel extraction and processing	MWh	3.74E-05	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0
Electricity Transmission														
Transmission and distribution losses	MWh	0.03744	1.0342	0.03872	112.43	4.209379	0.22421	0.008394	0.460789	0.017252	0.005752	0.000215	0.021024	0.000787
Total Grid Electricity Footprint				**0**		**52**		**0**		**0**		**0**		**0**
Total Fuel Footprints														
Total Gasoline Footprint														
On-site gasoline use - Other	gal	0	0.124	0	19.6	0	0.11	0	0.0045	0	0.00054	0	0.000039	0
On-site gasoline use <25 hp	gal	0	0.124	0	17.48	0	0.037	0	0.00025	0	0.165	0	0.00008	0
On-site gasoline use >25 hp	gal	0	0.124	0	19.93	0	0.032	0	0.00029	0	0.002	0	0.00009	0
Transportation gasoline use	gal	0	0.124	0	19.6	0	0.11	0	0.0045	0	0.00054	0	0.000039	0
Transportation gasoline use - car	gal	80	0.124	9.92	19.77	1581.6	0.027	2.16	0.00036	0.0288	0.003	0.24	0.0067	0.536
Transportation gasoline use - passenger truck	gal	134.9	0.124	16.7276	19.79	2669.671	0.035	4.7215	0.00036	0.048564	0.003	0.4047	0.00661	0.891689
Transportation gasoline use - User Defined	gal	0	0.124	0	19.6	0	0.11	0	0.0045	0	0.00054	0	0.000039	0
Gasoline produced	gal	214.9	0.033	7.0917	2.8	601.72	0.0046	0.98854	0.005	1.0745	0.0015	0.32235	0.001	0.2149
Total Gasoline Footprint		**214.9**		**33.7393**		**4852.991**		**7.87004**		**1.151864**		**0.96705**		**1.642589**
Total Diesel Footprint														
On-site diesel use - Other	gal	0	0.139	0	22.5	0	0.17	0	0.0054	0	0.0034	0	5.2E-06	0
On-site diesel use <75 hp	gal	0	0.139	0	22.21	0	0.1565	0	0.000145	0	0.0145	0	0.00004	0
On-site diesel use 75<hp<750	gal	1008.791	0.139	140.222	22.24	22435.52	0.101	101.8879	0.00013	0.131143	0.009	9.079121	0.00004	0.040352
On-site diesel use >750 hp	gal	0	0.139	0	22.24	0	0.149	0	0.00013	0	0.006	0	0.00004	0
Transportation diesel use	gal	1465.933	0.139	203.7647	22.5	32983.49	0.17	249.2086	0.0054	7.916038	0.0034	4.984172	5.2E-06	0.007623
Transportation diesel use - car	gal	0	0.139	0	22.57	0	0.015	0	0.0002	0	0.003	0	0.00252	0
Transportation diesel use - passenger truck	gal	0	0.139	0	22.545	0	0.0585	0	0.0002	0	0.007	0	0.002605	0
Transportation diesel use - User Defined	gal	0	0.139	0	22.5	0	0.17	0	0.0054	0	0.0034	0	5.2E-06	0
Diesel produced	gal	2474.724	0.017	42.07031	3.02	7473.667	0.0051	12.62109	0.0062	15.34329	0.0017	4.207031	0.0011	2.722197
Total Diesel Footprint		**2474.724**		**386.057**		**62892.68**		**363.7176**		**23.39047**		**18.27032**		**2.770171**
Total Biodiesel Footprint														
On-site biodiesel use	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
On-site biodiesel use - User Defined	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
Transportation biodiesel use	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
Transportation biodiesel use - User Defined	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
Biodiesel produced	gal	0	0.029	0	-16.8	0	0.018	0	0.033	0	0.00082	0	NP	
Total Biodiesel Footprint		**0**		**0**		**0**		**0**		**0**		**0**		**0**
Total Natural Gas Footprint														
On-site natural gas use	ccf	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
Transportation natural gas use	ccf	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
Transportation natural gas use - User Defined	ccf	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
Natural gas produced	ccf	0	0.0052	0	2.2	0	0.0037	0	0.0046	0	0.000072	0	6.1E-06	0
Total Natural Gas Footprint		**0**		**0**		**0**		**0**		**0**		**0**		**0**
Total Liquified Petroleum Gas Footprint														
On-site liquified petroleum gas use - Other	ccf	0	NP		12.69	0	0.021	0	0.00013	0	0.001	0	0	0
On-site liquified petroleum gas use	ccf	0	NP		12.69	0	0.021	0	0.00013	0	0.001	0	0	0
Liquified petroleum gas produced	ccf	0	0.088	0	1.47	0	0.0016	0	0.0024	0	0.0007	0	0.0003	0
Total Natural Gas Footprint		**0**		**0**		**0**		**0**		**0**		**0**		**0**
Total Compressed Gas Footprint														
On-site compressed gas use - Other	ccf	0	NP		1957.835	0	16.0325	0	0.023045	0	0.2775	0	0	0
On-site compressed gas use	ccf	0	NP		1957.835	0	16.0325	0	0.023045	0	0.2775	0	0	0
Compressed gas produced	ccf	0	19.983	0	343.92	0	0.4732	0	2.1651	0	0.1846	0	0.2895	0
Total Natural Gas Footprint		**0**		**0**		**0**		**0**		**0**		**0**		**0**

Notes:

Note: Please refer to the "Default Conversions" tab for references for the default conversion factors used on this calculation sheet.

Space below available for notes and calculations:

All Components - On-Site Footprint (Scope 1)

Contributors to Footprints	Units	Usage	Energy		GHG		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
On-Site														
On-site Renewable Energy														
Renewable electricity generated on-site	MWh	0	3.413	0										
Landfill gas combusted on-site for energy use	ccf CH4	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
On-site biodiesel use	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
On-site biodiesel use - User Defined	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
User-defined on-site renewable energy use #1	gal	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined on-site renewable energy use #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
On-site Renewable Energy Subtotals				**0**		**0**		**0**		**0**		**0**		**0**
Notes:														
On-site Conventional Energy														
On-site grid electricity	MWh	0.03744	3.413	0.127783										
On-site diesel use - Other	Gal	0	0.139	0	22.5	0	0.17	0	0.0054	0	0.0034	0	5.2E-06	0
On-site diesel use <75 hp	Gal	0	0.139	0	22.21	0	0.1565	0	0.000145	0	0.0145	0	0.00004	0
On-site diesel use 75<hp<750	Gal	1008.791	0.139	140.222	22.24	22435.52	0.101	101.8879	0.00013	0.131143	0.009	9.079121	0.00004	0.040352
On-site diesel use >750 hp	Gal	0	0.139	0	22.24	0	0.149	0	0.00013	0	0.006	0	0.00004	0
On-site gasoline use - Other	Gal	0	0.124	0	19.6	0	0.11	0	0.0045	0	0.00054	0	0.000039	0
On-site gasoline use <25 hp	Gal	0	0.124	0	17.48	0	0.037	0	0.00025	0	0.165	0	0.00008	0
On-site gasoline use >25 hp	Gal	0	0.124	0	19.93	0	0.032	0	0.00029	0	0.002	0	0.00009	0
On-site natural gas use	ccf	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
On-site compressed natural gas use - Other	ccf	0	NP		1957.835	0	16.0325	0	0.023045	0	0.2775	0	0	0
On-site compressed natural gas use	ccf	0	NP		1957.835	0	16.0325	0	0.023045	0	0.2775	0	0	0
On-site liquified petroleum gas use - Other	gal	0	NP		12.69	0	0.021	0	0.00013	0	0.001	0	0	0
On-site liquified petroleum gas use	gal	0	NP		12.69	0	0.021	0	0.00013	0	0.001	0	0	0
Other forms of on-site conventional energy use #1	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
Other forms of on-site conventional energy use #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
On-site Conventional Energy Subtotals				**140**		**22,436**		**102**		**0**		**9**		**0**
Notes:														
Other On-site Emissions														
On-site HAP process emissions	lbs	0											1	0
On-site GHG emissions	lbs CO2e	0			1	0								
On-site carbon storage	lbs CO2e	0			1	0								
GHG avoided by flaring on-site landfill methane	Lbs	0			-262	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
Other on-site NOx emissions or reductions	lbs	0					1	0						
Other on-site SOx emissions or reductions	lbs	0							1	0				
Other on-site PM emissions or reductions	lbs	0									1	0		
User-defined recycled/reused on-site #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined recycled/reused on-site #3	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined recycled/reused off-site #1	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
Notes:														
On-site Totals				**140.35**		**22,436**		**102**		**0.13**		**9**		**0.0404**

All Components - Electricity Generation Footprint (Scope 2)

Contributors to Footprints	Units	Usage	Energy		GHG		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
Electricity Generation														
Grid electricity	MWh	0.03744	6.929	0.259422	N/A*	42.09379	N/A*	0.083944	N/A*	0.172519	N/A*	0.002153	N/A*	0.007871
**** Conversion factors are not applied to grid electricity in the "All Components" tab since multiple fuel mixes may be used. The value for each cell shaded yellow in Row 51 is the sum of values from Components 1 - 6.***														
Voluntary purchase of renewable electricity	MWh	0												
Voluntary purchase of RECs	MWh	0												
Notes:														

All Components - Transportation Footprint (Scope 3a)

Category	Units	Usage	Energy		Greenhouse Gas		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
Conventional Energy														
Transportation diesel use	gal	1465.933	0.139	203.7647	22.5	32983.49	0.17	249.2086	0.0054	7.916038	0.0034	4.984172	5.2E-06	0.007623
Transportation diesel use - car	gal	0	0.139	0	22.57	0	0.015	0	0.0002	0	0.003	0	0.00252	0
Transportation diesel use - passenger truck	gal	0	0.139	0	22.545	0	0.0585	0	0.0002	0	0.007	0	0.002605	0
Transportation diesel use - User Defined	gal	0	0.139	0	22.5	0	0.17	0	0.0054	0	0.0034	0	5.2E-06	0
Transportation gasoline use	gal	0	0.124	0	19.6	0	0.11	0	0.0045	0	0.00054	0	0.000039	0
Transportation gasoline use - car	gal	80	0.124	9.92	19.77	1581.6	0.027	2.16	0.00036	0.0288	0.003	0.24	0.0067	0.536
Transportation gasoline use - passenger truck	gal	134.9	0.124	16.7276	19.79	2669.671	0.035	4.7215	0.00036	0.048564	0.003	0.4047	0.00661	0.891689
Transportation gasoline use - User Defined	gal	0	0.124	0	19.6	0	0.11	0	0.0045	0	0.00054	0	0.000039	0
Transportation natural gas use	ccf	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
Transportation natural gas use - User Defined	ccf	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
User-defined conventional energy transportation #1	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined conventional energy transportation #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
Conventional Energy Subtotals				**230**		**37,235**		**256**		**8**		**6**		**1**
Notes:														
Renewable Energy														
Transportation biodiesel use	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
Transportation biodiesel use - User Defined	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
User-defined renewable energy transportation #1	TBD	0	Biodiesel		0	0	0	0	0	0	0	0	Ref.	
User-defined renewable energy transportation #2	TBD	0	npg or pmp;		0	0	0	0	0	0	0	0	0	0
Renewable Energy Subtotals				**0**		**0**		**0**		**0**		**0**		**0**
Notes:														
Transportation Totals				**230**		**37235**		**256**		**7.99**		**5.63**		**1.44**

All Components - Off-Site Footprint (Scope 3b)

Category	Units	Usage	Energy		Greenhouse Gas		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
Construction Materials														
Aluminum, Rolled Sheet	lb	0	0.0633	0	9.15	0	0.0148	0	0.0283	0	0.0088	0	0.00102	0
Asphalt, mastic	lb	0	0.0412	0	0.85	0	0.00271	0	0.00798	0	0.000766	0	0.00107	0
Asphalt, paving-grade	lb	0	0.5	0	8.58	0	0.0299	0	0.0969	0	0.0091	0	0.0133	0
Ethanol, Corn, 95%	lb	0	0.0318	0	-0.0199	0	0.00425	0	0.00303	0	0.000469	0	8.46E-05	0
Ethanol, Corn, 99.7%	lb	0	0.0324	0	0.0591	0	0.00431	0	0.0031	0	0.000472	0	0.000087	0
Ethanol, Petroleum, 99.7%	lb	0	0.0205	0	1.25	0	0.00199	0	0.00214	0	0.000277	0	5.89E-05	0
Gravel/Sand Mix, 65% Gravel	lb	0	2.48E-05	0	0.0024	0	0.000018	0	4.52E-06	0	2.61E-06	0	3.08E-07	0
Gravel/sand/clay	lb	0	0.000028	0	0.00335	0	1.65E-05	0	0.000015	0	0.000002	0	2.05E-10	0
HDPE	lb	0	0.0332	0	1.94	0	0.00325	0	0.00409	0	0.000439	0	6.41E-05	0
Photovoltaic system (installed)	W	0	0.0336	0	4.47	0	0.015	0	0.032	0	0.00063	0	2.9E-06	0
PVC	lb	0	0.0262	0	2.02	0	0.004	0	0.00274	0	0.000372	0	0.000375	0
Portland cement, US average	lb	0	0.0139	0	1.34	0	0.00654	0	0.0104	0	0.00378	0	0.00097	0
Ready-mixed concrete, 20 MPa	ft3	0	0.217	0	19.5	0	0.0975	0	0.154	0	0.057	0	0.0141	0
Round Gravel	lb	0	2.48E-05	0	0.0024	0	0.000018	0	4.52E-06	0	2.61E-06	0	3.08E-07	0
Sand	lb	0	2.48E-05	0	0.0024	0	0.000018	0	4.52E-06	0	2.61E-06	0	3.08E-07	0
Stainless Steel	lb	0	0.0116	0	3.4	0	0.0075	0	0.012	0	0.0044	0	0.000144	0
Steel	lb	14055.7	0.0044	61.84507	1.1	15461.27	0.0014	19.67798	0.0017	23.89468	0.00056	7.87119	0.000067	0.941732
Other refined construction materials	lb	0	0.01885	0	2.115	0	0.004038	0	0.005133	0	0.001443	0	0.000163	0
Other unrefined construction materials	lb	0	0.000028	0	0.00335	0	1.65E-05	0	0.000015	0	0.000002	0	2.05E-10	0

Notes:

All Components - Off-Site Footprint (Scope 3b)

Category	Units	Usage	Energy		Greenhouse Gas		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
Treatment Materials & Chemicals														
Cheese Whey	lbs	0	0.0025	0	0.031	0	0.000062	0	0.000033	0	0.000002	0	NP	
Emulsified vegetable oil	lbs	0	0.0077	0	3.44	0	0.0066	0	0.0019	0	0.000033	0	NP	
Granular activated carbon, primary	lbs	0	0.0356	0	4.82	0	0.0793	0	0.128	0	0.000987	0	0.000657	0
Granular activated carbon, regenerated	lbs	0	0.00873	0	1.7	0	0.00733	0	0.0129	0	0.000886	0	0.000671	0
Hydrogen Peroxide, 50% in H2O	lbs	0	0.00979	0	1.19	0	0.00142	0	0.0024	0	0.000308	0	6.29E-05	0
Iron (II) Sulfate	lbs	0	0.00147	0	0.167	0	0.000316	0	0.000589	0	0.000103	0	0.000023	0
Lime, Hydrated, Packed	lbs	0	0.00206	0	0.762	0	0.000513	0	0.000358	0	0.00013	0	6.57E-06	0
Molasses	lbs	0	0.0044	0	0.48	0	0.0011	0	0.00024	0	4.1E-06	0	NP	
Phosphoric Acid, 70% in H2O	lbs	0	0.0067	0	0.882	0	0.00282	0	0.0294	0	0.00171	0	0.000163	0
Potassium Permanganate	lbs	0	0.00981	0	1.16	0	0.00234	0	0.0032	0	0.000422	0	0.000122	0
Sodium Hydroxide, 50% in H2O	lbs	0	0.00977	0	1.09	0	0.00194	0	0.00352	0	0.000403	0	0.000129	0
Other Treatment Chemicals & Materials	lbs	0	0.015	0	1.67	0	0.003	0	0.0065	0	0.00061	0	0.000016	0
Notes:														
Fuel Processing														
Biodiesel produced	gal	0	0.029	0	-16.8	0	0.018	0	0.033	0	0.00082	0	NP	
Diesel produced	gal	2474.724	0.017	42.07031	3.02	7473.667	0.0051	12.62109	0.0062	15.34329	0.0017	4.207031	0.0011	2.722197
Gasoline produced	gal	214.9	0.033	7.0917	2.8	601.72	0.0046	0.98854	0.005	1.0745	0.0015	0.32235	0.001	0.2149
Liquefied Petroleum Gas Produced	gal	0	0.088	0	1.47	0	0.0016	0	0.0024	0	0.0007	0	0.0003	0
Natural Gas - Compressed Produced	ccf	0	19.983	0	343.92	0	0.4732	0	2.1651	0	0.1846	0	0.2895	0
Natural Gas Produced	ccf	0	0.0052	0	2.2	0	0.0037	0	0.0046	0	0.000072	0	6.1E-06	0
Fuel Processing Subtotals				**49.16201**		**8075.387**		**13.60963**		**16.41779**		**4.529381**		**2.937097**
Notes:														
Public water	gal x 1000	8.4	0.0092	0.07728	5	42	0.0097	0.08148	0.0059	0.04956	0.016	0.1344	0.000015	0.000126
User-defined water resource #1	gal x 1000	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined water resource #2	gal x 1000	0	0	0	0	0	0	0	0	0	0	0	0	0
Notes:														

All Components - Off-Site Footprint (Scope 3b)

Category	Units	Usage	Energy		Greenhouse Gas		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
Off-Site Services														
Hazardous waste incineration	lb	0	0.00609	0	2.43	0	0.0016	0	0.00167	0	0.000209	0	0.000087	0
Off-site waste water treatment (POTW)	gal x 1000	0	0.015	0	4.4	0	0.016	0	0.015	0	NP		NP	
Off-site non-hazardous waste landfill	ton	8415.763	0.16	1346.522	25	210394.1	0.14	1178.207	0.075	631.1822	0.4	3366.305	0.0014	11.78207
Off-site hazardous waste landfill	ton	0	0.18	0	27.5	0	0.154	0	0.0825	0	0.44	0	0.00154	0
Off-site Laboratory Analysis - Other	sample	36	0.058071	2.090557	6.853438	246.7238	0.131402	4.73047	0.303876	10.93953	0.04557	1.640514	0.033017	1.188595
Off-site Laboratory Analysis - Metals	sample	12	0.212	2.544	27.4693	329.6316	0.6423	7.7076	1.5072	18.0864	0.2264	2.7168	0.1643	1.9716
Off-site Laboratory Analysis - Mercury	sample	0	0.073171	0	9.325458	0	0.212744	0	0.49824	0	0.074736	0	0.054233	0
Off-site Laboratory Analysis - Inorganic Anions	sample	0	0.007402	0	0.645948	0	0.006768	0	0.014793	0	0.002202	0	0.001554	0
Off-site Laboratory Analysis - Alkalinity	sample	0	0.01744	0	1.338192	0	0.007011	0	0.01325	0	0.00194	0	0.001283	0
Off-site Laboratory Analysis - Perchlorate	sample	0	0.023885	0	1.871705	0	0.007981	0	0.014154	0	0.002055	0	0.001287	0
Off-site Laboratory Analysis - Nitrogen/Nitrate	sample	0	0.033648	0	4.29897	0	0.095459	0	0.222665	0	0.03351	0	0.024251	0
Off-site Laboratory Analysis - Sulfate	sample	0	0.014122	0	1.472673	0	0.007981	0	0.013602	0	0.00198	0	0.001202	0
Off-site Laboratory Analysis - PCBs	sample	12	0.051277	0.615323	5.224902	62.69882	0.083334	1.000007	0.190477	2.285729	0.028439	0.341272	0.021208	0.254499
Off-site Laboratory Analysis - VOCs	sample	18	0.076204	1.371681	9.016814	162.3027	0.104498	1.880965	0.227074	4.087328	0.033951	0.611115	0.023589	0.424606
Off-site Laboratory Analysis - SVOCs	sample	12	0.07156	0.858722	7.870422	94.44506	0.145945	1.751334	0.337304	4.047646	0.050485	0.605824	0.037258	0.447093
Notes:														
Resource Extraction for Electricity														
Coal extraction and processing	MWh	0.011419	3.1	0.034872	180.0	2.055456	0.8	0.008793	0.2	0.001713	0.0	0.000206	NP	
Natural gas extraction and processing	MWh	0.012692	1.6	0.020711	270.0	3.426883	0.2	0.002285	13.0	0.164998	0.0	9.01E-05	NP	
Nuclear fuel extraction and processing	MWh	0.007413	0.2	0.001153	25.0	0.185328	0.2	0.001112	0.5	0.003707	0.0	1.11E-05	NP	
Oil extraction and processing	MWh	0.000262	2.3	0.000602	270.0	0.070762	1.7	0.000446	0.1	1.81E-05	0.0	1.1E-05	NP	
Other fuel extraction and processing	MWh	3.74E-05	0	0	0	0	0	0	0	0	0	0	0	0
Resource Extraction Subtotals				**0.057337**		**5.738429**		**0.012635**		**0.170436**		**0.000318**		**0**
Notes:														
Electricity Transmission														
Transmission and distribution losses	MWh	0.03744	1.0342	0.03872										
Notes:														

All Components - Off-Site Footprint (Scope 3b)

Category	Units	Usage	Energy		Greenhouse Gas		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
User-defined Materials														
User-defined material #1	gal	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #3	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #4	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #5	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #6	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #7	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #8	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #9	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #10	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #11	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #12	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #13	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #14	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #15	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #16	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #17	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #18	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #19	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined material #20	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
Notes:														
User-defined Waste Destinations														
User-defined recycled/reused off-site #1	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined recycled/reused off-site #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined recycled/reused off-site #3	TBD	0	y(MMBtu/u		(lbs CO2e/u		Ox(lbs/unit)		Ox(lbs/unit)		M(lbs/unit)		APs(lbs/unit	
User-defined non-hazardous waste destination #1	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined non-hazardous waste destination #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined non-hazardous waste destination #3	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined hazardous waste destination #1	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined hazardous waste destination #2	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
User-defined hazardous waste destination #3	TBD	0	0	0	0	0	0	0	0	0	0	0	0	0
Notes:														
Off-site Totals				**1465.183**		**234874.3**		**1228.659**		**711.1613**		**3384.756**		**19.94742**

All Components - Intermediate Totals

Category	Units	Usage	Energy		Greenhouse Gas		NOx		SOx		PM		HAPs	
			Conv. Factor	MMBtus	Conv. Factor	lbs CO2e	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs	Conv. Factor	lbs
Total Grid Electricity Footprint														
On-site grid electricity	MWh	0.03744	3.413	0.127783										
Electricity Generation														
Grid electricity	MWh	0.03744	6.929	0.259422	1124.3	42.09379	2.2421	0.083944	4.607887	0.172519	0.057518	0.002153	0.210237	0.007871
Resource Extraction for Electricity														
Coal extraction and processing	MWh	0.011419	3.1	0.034872	180.0	2.055456	0.8	0.008793	0.2	0.001713	0.0	0.000206	NP	
Natural gas extraction and processing	MWh	0.012692	1.6	0.020711	270.0	3.426883	0.2	0.002285	13.0	0.164998	0.0	9.01E-05	NP	
Nuclear fuel extraction and processing	MWh	0.007413	0.2	0.001153	25.0	0.185328	0.2	0.001112	0.5	0.003707	0.0	1.11E-05	NP	
Oil extraction and processing	MWh	0.000262	2.3	0.000602	270.0	0.070762	1.7	0.000446	0.1	1.81E-05	0.0	1.1E-05	NP	
Other fuel extraction and processing	MWh	3.74E-05	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0
Electricity Transmission														
Transmission and distribution losses	MWh	0.03744	1.0342	0.03872	112.43	4.209379	0.22421	0.008394	0.460789	0.017252	0.005752	0.000215	0.021024	0.000787
Total Grid Electricity Footprint				**0**		**52**		**0**		**0**		**0**		**0**
Total Fuel Footprints														
Total Gasoline Footprint														
On-site gasoline use - Other	gal	0	0.124	0	19.6	0	0.11	0	0.0045	0	0.00054	0	0.000039	0
On-site gasoline use <25 hp	gal	0	0.124	0	17.48	0	0.037	0	0.00025	0	0.165	0	0.00008	0
On-site gasoline use >25 hp	gal	0	0.124	0	19.93	0	0.032	0	0.00029	0	0.002	0	0.00009	0
Transportation gasoline use	gal	0	0.124	0	19.6	0	0.11	0	0.0045	0	0.00054	0	0.000039	0
Transportation gasoline use - car	gal	80	0.124	9.92	19.77	1581.6	0.027	2.16	0.00036	0.0288	0.003	0.24	0.0067	0.536
Transportation gasoline use - passenger truck	gal	134.9	0.124	16.7276	19.79	2669.671	0.035	4.7215	0.00036	0.048564	0.003	0.4047	0.00661	0.891689
Transportation gasoline use - User Defined	gal	0	0.124	0	19.6	0	0.11	0	0.0045	0	0.00054	0	0.000039	0
Gasoline produced	gal	214.9	0.033	7.0917	2.8	601.72	0.0046	0.98854	0.005	1.0745	0.0015	0.32235	0.001	0.2149
Total Gasoline Footprint		**214.9**		**33.7393**		**4852.991**		**7.87004**		**1.151864**		**0.96705**		**1.642589**
Total Diesel Footprint														
On-site diesel use - Other	gal	0	0.139	0	22.5	0	0.17	0	0.0054	0	0.0034	0	5.2E-06	0
On-site diesel use <75 hp	gal	0	0.139	0	22.21	0	0.1565	0	0.000145	0	0.0145	0	0.00004	0
On-site diesel use 75<hp<750	gal	1008.791	0.139	140.222	22.24	22435.52	0.101	101.8879	0.00013	0.131143	0.009	9.079121	0.00004	0.040352
On-site diesel use >750 hp	gal	0	0.139	0	22.24	0	0.149	0	0.00013	0	0.006	0	0.00004	0
Transportation diesel use	gal	1465.933	0.139	203.7647	22.5	32983.49	0.17	249.2086	0.0054	7.916038	0.0034	4.984172	5.2E-06	0.007623
Transportation diesel use - car	gal	0	0.139	0	22.57	0	0.015	0	0.0002	0	0.003	0	0.00252	0
Transportation diesel use - passenger truck	gal	0	0.139	0	22.545	0	0.0585	0	0.0002	0	0.007	0	0.002605	0
Transportation diesel use - User Defined	gal	0	0.139	0	22.5	0	0.17	0	0.0054	0	0.0034	0	5.2E-06	0
Diesel produced	gal	2474.724	0.017	42.07031	3.02	7473.667	0.0051	12.62109	0.0062	15.34329	0.0017	4.207031	0.0011	2.722197
Total Diesel Footprint		**2474.724**		**386.057**		**62892.68**		**363.7176**		**23.39047**		**18.27032**		**2.770171**
Total Biodiesel Footprint														
On-site biodiesel use	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
On-site biodiesel use - User Defined	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
Transportation biodiesel use	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
Transportation biodiesel use - User Defined	gal	0	0.127	0	22.3	0	0.2	0	0	0	0.00099	0	NP	
Biodiesel produced	gal	0	0.029	0	-16.8	0	0.018	0	0.033	0	0.00082	0	NP	
Total Biodiesel Footprint		**0**		**0**		**0**		**0**		**0**		**0**		**0**
Total Natural Gas Footprint														
On-site natural gas use	ccf	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
Transportation natural gas use	ccf	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
Transportation natural gas use - User Defined	ccf	0	0.103	0	13.1	0	0.01	0	6.3E-06	0	0.00076	0	8.4E-06	0
Natural gas produced	ccf	0	0.0052	0	2.2	0	0.0037	0	0.0046	0	0.000072	0	6.1E-06	0
Total Natural Gas Footprint		**0**		**0**		**0**		**0**		**0**		**0**		**0**
Total Liquified Petroleum Gas Footprint														
On-site liquified petroleum gas use - Other	ccf	0	NP		12.69	0	0.021	0	0.00013	0	0.001	0	0	0
On-site liquified petroleum gas use	ccf	0	NP		12.69	0	0.021	0	0.00013	0	0.001	0	0	0
Liquified petroleum gas produced	ccf	0	0.088	0	1.47	0	0.0016	0	0.0024	0	0.0007	0	0.0003	0
Total Natural Gas Footprint		**0**		**0**		**0**		**0**		**0**		**0**		**0**
Total Compressed Gas Footprint														
On-site compressed gas use - Other	ccf	0	NP		1957.835	0	16.0325	0	0.023045	0	0.2775	0	0	0
On-site compressed gas use	ccf	0	NP		1957.835	0	16.0325	0	0.023045	0	0.2775	0	0	0
Compressed gas produced	ccf	0	19.983	0	343.92	0	0.4732	0	2.1651	0	0.1846	0	0.2895	0
Total Natural Gas Footprint		**0**		**0**		**0**		**0**		**0**		**0**		**0**

Notes:

Note: Please refer to the "Default Conversions" tab for references for the default conversion factors used on this calculation sheet.

Space below available for notes and calculations:

Climate Screening Checklist

Background Information

- Project Manager: Paul Probasco
- Site Name: 4001 4th Avenue Redevelopment Site (the "Site")
- Site Number: C224412
- Site Location: 4001-4011 4th Avenue, Brooklyn, New York
- Site Elevation (average above sea level): Approximately 58 feet above sea level (Google Earth)




- ClimAID Region (Responding Climate Change in New York State (ClimAID) - NYSERDA): Region 4 – New York City and Long Island



- Remedial Stage/Site Classification: Investigation.
- Contamination - Media Impacted/ Contaminants of Concern: Volatile organic compounds (VOCs) specifically petroleum-related VOCs (benzene, toluene, ethylbenzene, and xylenes [BTEX]) and semi-volatile organic compounds (SVOCs), specifically polycyclic aromatic hydrocarbons (PAHs), and metals in soil; VOCs in groundwater; and VOCs in soil vapor.
- Proposed/Current Remedy: The proposed Interim Remedial Measure Work Plan (IRMWP) includes the excavation of source material to 12 feet below ground surface (ft bgs); the closure and removal of four 4,000-gallon underground storage tanks (USTs); and installation of hydraulic control around the 12-ft excavation to the west and south via sealed steel sheeting, secant pile wall, or industry equivalent extending to 50 ft bgs. Additional remedy components for the remaining portion of the Site will be addressed under a forthcoming Remedial Action Work Plan (RAWP) to be submitted to the New York State Department of Environmental Conservation (NYSDEC) and New York State Department of Health (NYSDOH) for review and approval.
- What is the predicted timeframe of the remedy? Will components of the remedy still be in place in 10+ years? The predicted timeframe for the implementation of the Interim Remedial Measure Work Plan (IRMWP) is November 2025 to December 2025. Components of the remedy that will be in place in 10+ years include the hydraulic barrier.
- Is the site in proximity to any sensitive receptors? (e.g., wetlands, waterbodies, residential properties, hospitals, schools, drinking water supplies, etc.) There are three sensitive receptors within a 500-ft radius of the Site: New York City Public I.S. 136, located west of the Site beyond 4th Avenue; Family Day Care Graciela's Little Angels, located approximately 250 ft to the south of the Site; and Sunset Park Group Family Daycare, located approximately 475 ft to the west of the Site.

Is the site in a disadvantaged community (DAC) or potential environmental justice area (PEJA) (Use DECinfolocator: DECinfo Locator (ny.gov))?

X Yes ☐ No



If the site is in a DAC or PEJA, will climate impacts be magnified? If yes, list how and why.

☐ Yes X No

Should thresholds of concern be lowered to account for magnification of impacts? If yes, indicate how lower thresholds will be used in the screening.

☐ Yes X No

Climate Screening Table*

Potential Climate Hazards	**Relevant to the Site Location** (Y/N/NA)[1]	**Projected Change** (Resilience Analysis and Planning Tool (RAPT)/arcgis.com[3]	**Potential to Impact Remedy** (Y/N)	**Is remedy/site already resilient?** (Y/N)[4]
Precipitation	N	N/A	N/A	N/A
Temperature[2] (Extreme Heat or Cold Weather Impacts)	N	N/A	N/A	N/A
Sea Level Rise	N	N/A	N/A	N/A
Flooding	N	N/A	N/A	N/A
Storm Surge	N	N/A	N/A	N/A
Wildfire	N	N/A	N/A	N/A
Drought	N	N/A	N/A	N/A
Storm Severity	N	N/A	N/A	N/A
Landslides	N	N/A	N/A	N/A
Other Hazards:	N/A	N/A	N/A	N/A

* Links to potential data sources can be found on the following page

[1] If the first column is N --> The rest of the columns will be N/A, the hazard is not applicable to the site.

[2] Extreme Heat: periods of three or more days above 90°F- Extreme Cold: Individual days with minimum temperatures at or below 0 degrees F (NYSERDA ClimAID report)

[3] List the projected change in specific terms or units e.g. inches of rainfall, feet of sea level rise, etc.

[4] If final column is Y, provide reasoning, if the final column is N --> Climate Vulnerability Assessment (CVA) required.

Required Next Steps (If no further action is required, provide justification):

Conduct severe weather storm inspections during the active remedy. Inspect dewatering systems prior to anticipated storm events that could result in a power outage, and after storm events.

Potential Data Sources (not an exhaustive list)- from Superfund Climate Resilience: Vulnerability Assessment | US EPA

NYSERDA ClimAID report- Responding Climate Change in New York State (ClimAID) - NYSERDA

FEMA- National Flood Hazard Layer | FEMA.gov

NOAA- National Storm Surge Risk Maps - Version 3 (noaa.gov)

Department of Agriculture Forest Service Wildfire Risk to Communities

EPA Climate Change Indicators in the United States

EPA Climate Resilience Evaluation & Awareness Tool (CREAT) | U.S. Climate Resilience Toolkit

EPA National Stormwater Calculator

National Integrated Drought Information System U.S. Drought Portal

National Interagency Coordination Center National Interagency Fire Center

National Oceanic and Atmospheric Administration Coastal Services Digital Coast

- Resources to help communities assess coastal hazards, such as the Sea Level Rise Viewer for visualizing community-level impacts of flooding or sea level rise and downloadable LIDAR data

National Oceanic and Atmospheric Administration National Centers for Environmental Information website

National Oceanic and Atmospheric Administration Sea Level Trends

National Weather Service Climate Prediction Center

National Weather Service National Hurricane Center

National Weather Service Sea, Lake, and Overland Surges from Hurricanes (SLOSH)

National Weather Service Storm Surge Hazard Maps

U.S. Federal Government Climate Resilience Toolkit: The Climate Explorer

U.S. Army Corps of Engineers Climate Preparedness and Resilience

U.S. Geological Survey Coastal Change Hazards Portal

U.S. Geological Survey Landslide Hazards Program

U.S. Geological Survey National Ground-water Monitoring Network Data Portal

U.S. Geological Survey National Climate Change Viewer

U.S. Geological Survey National Water Dashboard

U.S. Geological Survey StreamStats

NYS Department of State- Assess | Department of State (ny.gov)

NYSERDA NY Costal Floodplain Mapper- Home Page (ny.gov)

NYSDEC Coastal Erosion Hazards- Coastal Areas Regulated By The CEHA Permit Program - NYDEC

NYSDOH Heat Index- health.ny.gov/environmental/weather/vulnerability_index/county_maps.htm

APPENDIX H
Community Air Monitoring Plan

Appendix 1A
New York State Department of Health
Generic Community Air Monitoring Plan

Overview

A Community Air Monitoring Plan (CAMP) requires real-time monitoring for volatile organic compounds (VOCs) and particulates (i.e., dust) at the downwind perimeter of each designated work area when certain activities are in progress at contaminated sites. The CAMP is not intended for use in establishing action levels for worker respiratory protection. Rather, its intent is to provide a measure of protection for the downwind community (i.e., off-site receptors including residences and businesses and on-site workers not directly involved with the subject work activities) from potential airborne contaminant releases as a direct result of investigative and remedial work activities. The action levels specified herein require increased monitoring, corrective actions to abate emissions, and/or work shutdown. Additionally, the CAMP helps to confirm that work activities did not spread contamination off-site through the air.

The generic CAMP presented below will be sufficient to cover many, if not most, sites. Specific requirements should be reviewed for each situation in consultation with NYSDOH to ensure proper applicability. In some cases, a separate site-specific CAMP or supplement may be required. Depending upon the nature of contamination, chemical- specific monitoring with appropriately-sensitive methods may be required. Depending upon the proximity of potentially exposed individuals, more stringent monitoring or response levels than those presented below may be required. Special requirements will be necessary for work within 20 feet of potentially exposed individuals or structures and for indoor work with co-located residences or facilities. These requirements should be determined in consultation with NYSDOH.

Reliance on the CAMP should not preclude simple, common-sense measures to keep VOCs, dust, and odors at a minimum around the work areas.

Community Air Monitoring Plan

Depending upon the nature of known or potential contaminants at each site, real-time air monitoring for VOCs and/or particulate levels at the perimeter of the exclusion zone or work area will be necessary. Most sites will involve VOC and particulate monitoring; sites known to be contaminated with heavy metals alone may only require particulate monitoring. If radiological contamination is a concern, additional monitoring requirements may be necessary per consultation with appropriate DEC/NYSDOH staff.

Continuous monitoring will be required for all ground intrusive activities and during the demolition of contaminated or potentially contaminated structures. Ground intrusive activities include, but are not limited to, soil/waste excavation and handling, test pitting or trenching, and the installation of soil borings or monitoring wells.

Periodic monitoring for VOCs will be required during non-intrusive activities such as the collection of soil and sediment samples or the collection of groundwater samples from existing monitoring wells. “Periodic” monitoring during sample collection might reasonably consist of taking a reading upon arrival at a sample location, monitoring while opening a well cap or

overturning soil, monitoring during well baling/purging, and taking a reading prior to leaving a sample location. In some instances, depending upon the proximity of potentially exposed individuals, continuous monitoring may be required during sampling activities. Examples of such situations include groundwater sampling at wells on the curb of a busy urban street, in the midst of a public park, or adjacent to a school or residence.

VOC Monitoring, Response Levels, and Actions

Volatile organic compounds (VOCs) must be monitored at the downwind perimeter of the immediate work area (i.e., the exclusion zone) on a continuous basis or as otherwise specified. Upwind concentrations should be measured at the start of each workday and periodically thereafter to establish background conditions, particularly if wind direction changes. The monitoring work should be performed using equipment appropriate to measure the types of contaminants known or suspected to be present. The equipment should be calibrated at least daily for the contaminant(s) of concern or for an appropriate surrogate. The equipment should be capable of calculating 15-minute running average concentrations, which will be compared to the levels specified below.

1. If the ambient air concentration of total organic vapors at the downwind perimeter of the work area or exclusion zone exceeds 5 parts per million (ppm) above background for the 15-minute average, work activities must be temporarily halted and monitoring continued. If the total organic vapor level readily decreases (per instantaneous readings) below 5 ppm over background, work activities can resume with continued monitoring.

2. If total organic vapor levels at the downwind perimeter of the work area or exclusion zone persist at levels in excess of 5 ppm over background but less than 25 ppm, work activities must be halted, the source of vapors identified, corrective actions taken to abate emissions, and monitoring continued. After these steps, work activities can resume provided that the total organic vapor level 200 feet downwind of the exclusion zone or half the distance to the nearest potential receptor or residential/commercial structure, whichever is less - but in no case less than 20 feet, is below 5 ppm over background for the 15-minute average.

3. If the organic vapor level is above 25 ppm at the perimeter of the work area, activities must be shutdown.

4. All 15-minute readings must be recorded and be available for State (DEC and NYSDOH) personnel to review. Instantaneous readings, if any, used for decision purposes should also be recorded.

Particulate Monitoring, Response Levels, and Actions

Particulate concentrations should be monitored continuously at the upwind and downwind perimeters of the exclusion zone at temporary particulate monitoring stations. The particulate monitoring should be performed using real-time monitoring equipment capable of measuring particulate matter less than 10 micrometers in size (PM-10) and capable of integrating over a period of 15 minutes (or less) for comparison to the airborne particulate action level. The equipment must be equipped with an audible alarm to indicate exceedance of the action level. In addition, fugitive dust migration should be visually assessed during all work activities.

1. If the downwind PM-10 particulate level is 100 micrograms per cubic meter (mcg/m^3) greater than background (upwind perimeter) for the 15-minute period or if airborne dust is observed leaving the work area, then dust suppression techniques must be employed. Work may continue with dust suppression techniques provided that downwind PM-10 particulate levels do not exceed 150 mcg/m^3 above the upwind level and provided that no visible dust is migrating from the work area.

2. If, after implementation of dust suppression techniques, downwind PM-10 particulate levels are greater than 150 mcg/m^3 above the upwind level, work must be stopped and a re-evaluation of activities initiated. Work can resume provided that dust suppression measures and other controls are successful in reducing the downwind PM-10 particulate concentration to within 150 mcg/m^3 of the upwind level and in preventing visible dust migration.

3. All readings must be recorded and be available for State (DEC and NYSDOH) and County Health personnel to review.

December 2009

Appendix 1B
Fugitive Dust and Particulate Monitoring

A program for suppressing fugitive dust and particulate matter monitoring at hazardous waste sites is a responsibility on the remedial party performing the work. These procedures must be incorporated into appropriate intrusive work plans. The following fugitive dust suppression and particulate monitoring program should be employed at sites during construction and other intrusive activities which warrant its use:

1. Reasonable fugitive dust suppression techniques must be employed during all site activities which may generate fugitive dust.

2. Particulate monitoring must be employed during the handling of waste or contaminated soil or when activities on site may generate fugitive dust from exposed waste or contaminated soil. Remedial activities may also include the excavation, grading, or placement of clean fill. These control measures should not be considered necessary for these activities.

3. Particulate monitoring must be performed using real-time particulate monitors and shall monitor particulate matter less than ten microns (PM10) with the following minimum performance standards:

(a) Objects to be measured: Dust, mists or aerosols;
(b) Measurement Ranges: 0.001 to 400 mg/m3 (1 to 400,000 :ug/m3);
(c) Precision (2-sigma) at constant temperature: +/- 10 :g/m3 for one second averaging; and +/- 1.5 g/m3 for sixty second averaging;
(d) Accuracy: +/- 5% of reading +/- precision (Referred to gravimetric calibration with SAE fine test dust (mmd= 2 to 3 :m, g= 2.5, as aerosolized);
(e) Resolution: 0.1% of reading or 1g/m3, whichever is larger;
(f) Particle Size Range of Maximum Response: 0.1-10;
(g) Total Number of Data Points in Memory: 10,000;
(h) Logged Data: Each data point with average concentration, time/date and data point number
(i) Run Summary: overall average, maximum concentrations, time/date of maximum, total number of logged points, start time/date, total elapsed time (run duration), STEL concentration and time/date occurrence, averaging (logging) period, calibration factor, and tag number;
(j) Alarm Averaging Time (user selectable): real-time (1-60 seconds) or STEL (15 minutes), alarms required;
(k) Operating Time: 48 hours (fully charged NiCd battery); continuously with charger;
(l) Operating Temperature: -10 to 50^{o} C (14 to 122^{o} F);
(m) Particulate levels will be monitored upwind and immediately downwind at the working site and integrated over a period not to exceed 15 minutes.

4. In order to ensure the validity of the fugitive dust measurements performed, there must be appropriate Quality Assurance/Quality Control (QA/QC). It is the responsibility of the remedial party to adequately supplement QA/QC Plans to include the following critical features: periodic instrument calibration, operator training, daily instrument performance (span) checks, and a record keeping plan.

5. The action level will be established at 150 ug/m3 (15 minutes average). While conservative,

this short-term interval will provide a real-time assessment of on-site air quality to assure both health and safety. If particulate levels are detected in excess of 150 ug/m3, the upwind background level must be confirmed immediately. If the working site particulate measurement is greater than 100 ug/m3 above the background level, additional dust suppression techniques must be implemented to reduce the generation of fugitive dust and corrective action taken to protect site personnel and reduce the potential for contaminant migration. Corrective measures may include increasing the level of personal protection for on-site personnel and implementing additional dust suppression techniques (see paragraph 7). Should the action level of 150 ug/m3 continue to be exceeded work must stop and DER must be notified as provided in the site design or remedial work plan. The notification shall include a description of the control measures implemented to prevent further exceedances.

6. It must be recognized that the generation of dust from waste or contaminated soil that migrates off-site, has the potential for transporting contaminants off-site. There may be situations when dust is being generated and leaving the site and the monitoring equipment does not measure PM10 at or above the action level. Since this situation has the potential to allow for the migration of contaminants off-site, it is unacceptable. While it is not practical to quantify total suspended particulates on a real-time basis, it is appropriate to rely on visual observation. If dust is observed leaving the working site, additional dust suppression techniques must be employed. Activities that have a high dusting potential--such as solidification and treatment involving materials like kiln dust and lime--will require the need for special measures to be considered.

7. The following techniques have been shown to be effective for the controlling of the generation and migration of dust during construction activities:

(a) Applying water on haul roads;
(b) Wetting equipment and excavation faces;
(c) Spraying water on buckets during excavation and dumping;
(d) Hauling materials in properly tarped or watertight containers;
(e) Restricting vehicle speeds to 10 mph;
(f) Covering excavated areas and material after excavation activity ceases; and
(g) Reducing the excavation size and/or number of excavations.

Experience has shown that the chance of exceeding the 150ug/m3 action level is remote when the above-mentioned techniques are used. When techniques involving water application are used, care must be taken not to use excess water, which can result in unacceptably wet conditions. Using atomizing sprays will prevent overly wet conditions, conserve water, and provide an effective means of suppressing the fugitive dust.

8. The evaluation of weather conditions is necessary for proper fugitive dust control. When extreme wind conditions make dust control ineffective, as a last resort remedial actions may need to be suspended. There may be situations that require fugitive dust suppression and particulate monitoring requirements with action levels more stringent than those provided above. Under some circumstances, the contaminant concentration and/or toxicity may require additional monitoring to protect site personnel and the public. Additional integrated sampling and chemical analysis of the dust may also be in order. This must be evaluated when a health and safety plan is developed and when appropriate suppression and monitoring requirements are established for protection of health and the environment.

Special Requirements for Work Within 20 Feet of Potentially Exposed Individuals or Structures

When work areas are within 20 feet of potentially exposed populations or occupied structures, the continuous monitoring locations for VOCs and particulates must reflect the nearest potentially exposed individuals and the location of ventilation system intakes for nearby structures. The use of engineering controls such as vapor/dust barriers, temporary negative-pressure enclosures, or special ventilation devices should be considered to prevent exposures related to the work activities and to control dust and odors. Consideration should be given to implementing the planned activities when potentially exposed populations are at a minimum, such as during weekends or evening hours in non-residential settings.

- If total VOC concentrations opposite the walls of occupied structures or next to intake vents exceed 1 ppm, monitoring should occur within the occupied structure(s). Background readings in the occupied spaces must be taken prior to commencement of the planned work. Any unusual background readings should be discussed with NYSDOH prior to commencement of the work.

- If total particulate concentrations opposite the walls of occupied structures or next to intake vents exceed 150 mcg/m^3, work activities should be suspended until controls are implemented and are successful in reducing the total particulate concentration to 150 mcg/m^3 or less at the monitoring point.

- Depending upon the nature of contamination and remedial activities, other parameters (e.g., explosivity, oxygen, hydrogen sulfide, carbon monoxide) may also need to be monitored. Response levels and actions should be pre-determined, as necessary, for each site.

Special Requirements for Indoor Work With Co-Located Residences or Facilities

Unless a self-contained, negative-pressure enclosure with proper emission controls will encompass the work area, all individuals not directly involved with the planned work must be absent from the room in which the work will occur. Monitoring requirements shall be as stated above under "Special Requirements for Work Within 20 Feet of Potentially Exposed Individuals or Structures" except that in this instance "nearby/occupied structures" would be adjacent occupied rooms. Additionally, the location of all exhaust vents in the room and their discharge points, as well as potential vapor pathways (openings, conduits, etc.) relative to adjoining rooms, should be understood and the monitoring locations established accordingly. In these situations, it is strongly recommended that exhaust fans or other engineering controls be used to create negative air pressure within the work area during remedial activities. Additionally, it is strongly recommended that the planned work be implemented during hours (e.g. weekends or evenings) when building occupancy is at a minimum.

Safety Data Sheet

Section 1 – Chemical Products and Company Identification

Product Names: BioSolve® Pinkwater®

Product Uses: Remediation of hydrocarbon (oil, fuel, petrochemical) contamination, including: impacted soils, suppression of VOCs, decontamination of equipment and protective clothing, and surface washing

Manufacturer:
The BioSolve Company
24 Victory Lane
Dracut, MA 01826 USA

Contact Information:

+1 (800) 225-3909	US, Canada, Mexico and Puerto Rico
+1 (781) 482-7900	All other locations

Section 2 – Hazards Identification

Health Hazards:

Eye Contact:	Causes transient eye irritation
Skin Contact:	May cause mild, transient irritation
Ingestion:	May be harmful if swallowed; can cause gastrointestinal irritation, nausea, vomiting and/or diarrhea

Hazard Mitigation: Wear protective gloves and eye/face protection
Avoid prolonged breathing of spray

Environmental Hazards: Moderately toxic to aquatic life. Avoid discharge to storm drains and waterways

GHS Classification: Toxic to aquatic life, Acute Category 2

Section 3 – Composition/Information on Ingredients

Proprietary formulation with nonionic surfactants (32% active ingredients in water)

BioSolve products contain no caustic, d-limonene or hydrocarbon solvents.

BioSolve products do not contain any hazardous ingredients as defined by CERCLA, Massachusetts Right to Know Law and California Prop 65. All ingredients are TSCA compliant.

Section 4 – First Aid Measures

Eyes: Immediately flush eyes with water for at least 15 minutes. Hold eyelids apart while flushing to rinse entire surface of eye and lids with water. Seek medical attention for lasting irritation.

Skin: Rinse exposed area and wash with mild soap and water for several minutes. Seek medical attention if irritation develops.

Ingestion: Seek medical attention in the event of serious or persistent abdominal discomfort, nausea or diarrhea.

Inhalation: Inhalation of concentrated vapors resulting from spraying or heating in confined or poorly ventilated areas may cause irritation of nose and throat. Remove person to fresh air and seek medical attention if irritation persists.

Section 5 – Fire Fighting Measures

Suitable Extinguishing Media: None required; BioSolve products are non-flammable

Special Protective Equipment for Firefighters: None necessary

Unusual Fire or Explosive Hazards: None

Section 6 – Accidental Release Measures

In case of accidental release, breakage or leakage: Eliminate or contain source with inert material, such as sand, earth, absorbent pads, etc. Transfer liquid to suitable containers for recovery, re-use or disposal. Wipe up or mop up using water. Hard surfaces (e.g., floors, driveways) may be slippery; use care to avoid falling.

Rinse area with water. Avoid flow of run-off to surface waters. Always check with local regulations before discharging effluent to storm drains or sewers.

Section 7 – Handling and Storage

Handling: Minimize periods of exposure to extreme temperatures. Keep from freezing. If frozen, separation may occur; thaw and stir thoroughly prior to use. Freezing will not affect product performance.

Precautions: Chemical resistant gloves and eye protection are recommended while mixing and using.

Incompatibilities: Avoid contact with strong acids or strong oxidants.

Storage: Recommended storage temperature: 35° – 120° F (1° – 48° C).

Shelf Life: If unopened, more than 10 years.

Section 8 – Exposure Controls / Personal Protection

Eyes Protection: Safety glasses; chemical goggles or face shield recommended when spraying to protect against backsplash and drift.

Skin Protection: Rubber or latex gloves recommended.

Respiratory Protection: None required, except if application results in significant misting of product. If so, use of an approved air purifying respirator is recommended.

Engineering Controls: For indoor use or for use in a confined space, normal ventilation is generally satisfactory.

Section 9 – Physical and Chemical Properties

Appearance: Deep red

Odor: Mild, pleasant sassafras fragrance

Concentration: ~32% active ingredients as sold

Boiling Point	265°F/129°C	**Vapor Pressure mm/Hg**	Not available
Melting/Freezing Point	28°F/-2°C	**Vapor Density (Air=1)**	Not available
Flash Point	Non-flammable	**Surface Tension***	29 Dyne/cm @25°C
Flammability Limits	Not applicable	**Viscosity (concentrate)**	490 centipoise
Reactivity with Water	None	**Viscosity (6% solution)**	1.5 centipoise
Evaporation Rate	Not determined	**Solubility in Water**	100%
Specific Gravity	1.01 gms/cc	**VOC Content**	Not determined
	8.43 lbs/U.S. gal	**pH**	9

*6% solution

Section 10 – Stability and Reactivity

Chemical Stability: Stable; will not decompose if used according to manufacturer's directions.

Conditions to Avoid: Prolonged exposure to heat may cause product degradation. Freezing should also be avoided as discussed in Section 7.

Incompatible Materials: Normally unreactive. Avoid strong alkalis, strong acids, strong oxidizing agents and materials with reactive hydroxyl compounds. These materials could damage the product and reduce its effectiveness during application.

Hazardous Decomposition Products: None are known.

Hazardous Polymerization: Will not occur.

Section 11 – Toxicological Information

Overview: No adverse acute or chronic health effects expected if product used in accordance with manufacturer's directions.

Carcinogenicity: No ingredient has been shown to cause cancer in laboratory animals.

Specific Organ Toxicity: None are known.

Section 12 – Ecological Considerations

Persistence and Degradability: The total of the organic components contained in this product is not classified as readily biodegradable (OECD-301 A-F). However, this product is inherently biodegradable with 60% degradation in 28 days (OECD-301B) and estimated >95% degradation in 120 days.

Bioaccumulation Potential: The bioaccumulation factor in fish has been estimated to be low, ranging from 87 to 344.

Mobility: No data available

Aquatic Toxicity:

LC_{50} of Concentrate (As shipped)		
Mysidopsis bahia	48-hours	3.6 mg/L
Menidia beryllina	96-hours	6.4 mg/L
LC50 of 3% Dilute Solution (As Used)		
Mysidopsis bahia	48-hours	185 mg/L
Menidia beryllina	96-hours	247 mg/L
LC50 of 6% Dilute Solution (As Used)		
Daphnia magna	48-hours	287 mg/L
Pimephales promelas	96-hours	124 mg/L
Onchorhynchus mykiss	96-hours	177 mg/L

Section 13 - Disposal

DO NOT DUMP INTO STORM DRAINS OR INTO ANY BODY OF WATER. All disposal practices must be in compliance with all Federal, State/Provincial and local laws and regulations. As manufactured, BioSolve products do not meet the definition of a hazardous waste. Small quantities of unused and uncontaminated product may be discharged to a qualified wastewater treatment facility. Always obtain approval from local and Federal regulatory agencies prior to discarding this product into public sewers.

As your supplier, we have no control over your handling and use of this product. However, the intended use of this product as a remediation and/or surface washing agent may produce wastewater containing emulsified or dispersed hydrocarbons that may be classified as a hazardous waste and should be treated and disposed of accordingly.

Section 14 – Transportation Information

USDOT Freight Class 55 (Liquid Cleaning Compound, Non-Hazardous)
This product is not regulated by USDOT or Canadian TDG when shipped domestically by land.

North American Industry Classification System (NAICS) # 325613

U.S. ITC, Harmonized Tariff Schedule B Classification: 3402.90.30.00

Section 15 – Regulatory Information

This product is considered non-hazardous as defined by CERCLA, according to OSHA, Massachusetts Right to Know Law and California Prop 65.

Toxic Substances Control Act:	All components of this product are on the TSCA inventory or are exempt from TSCA Inventory requirements under 40 CFR 720.30.
CEPA – Domestic Substances List:	All substances contained in this product are listed on the Canadian Domestic Substances List (DSL) or not required to be listed.
Canadian CPR Compliance:	This product has been classified in accordance with the hazard criteria of the Canadian Controlled Products Regulations (CPR) and the SDS contains all the information required by the CPR
WHMIS Classification:	D2B Eye or skin irritant

Regulatory requirements are subject to change and may differ from one location to another; it is the buyer's responsibility to ensure that its activities comply with Federal, state or provincial and local laws.

Section 16 – Other Information

HMIS Rating	Health Hazard:	1 (Eye/Skin Irritant)
	Fire Hazard:	0
	Reactivity:	0
	Personal Protective Equipment:	Rubber gloves, safety glasses or face shield
NFPA Rating	Health:	1 (Eye/Skin Irritant)
	Flammability:	0
	Reactivity:	0
	Other Hazard:	None

BioSolve Pinkwater is on the US Environmental Protection Agency's NCP Product Schedule. This listing does NOT mean that EPA approves, recommends, licenses, certifies or authorizes the use of BioSolve Pinkwater on an oil discharge. This listing means only that data have been submitted to EPA as required by Subpart J of the National Contingency Plan, 40 CFR Section 300.915.

SDS Effective Date: January 1, 2018

The information contained herein is accurate to the best of our knowledge. The BioSolve Company makes no warranty of any kind, express or implied, concerning the safe use of this material in your process or application or in combination with other substances.

For more information, visit: www.biosolve.com

SAFETY DATA SHEET

SOIL EQUIVALENT FOAM AC-667SE

Section 1. Identification

GHS product identifier : SOIL EQUIVALENT FOAM AC-667SE

Chemical name : Proprietary Surfactant.

Other means of identification : Starch modified hydrolyzed protein surfactant.

Product type : Liquid.

Relevant identified uses of the substance or mixture and uses advised against

Product use : Aqueous Surfactant. Spray application for VOC and Odor control.

Area of application : Industrial applications.

Supplier/Manufacturer : Rusmar, Inc.
216 Garfield Avenue
West Chester, PA 19380
Phone: 610-436-4314
Fax: 610-436-8436

e-mail address of person responsible for this SDS : info@rusmarinc.com
Website: www.rusmarinc.com

Emergency telephone number (with hours of operation) : 888 488 8044 or 212 682 1200
CHEMTREC 800 424 9300

Section 2. Hazards identification

OSHA/HCS status : While this material is not considered hazardous by the OSHA Hazard Communication Standard (29 CFR 1910.1200), this SDS contains valuable information critical to the safe handling and proper use of the product. This SDS should be retained and available for employees and other users of this product.

Classification of the substance or mixture : Not classified.

GHS label elements

Signal word : No signal word.

Hazard statements : No known significant effects or critical hazards.

Precautionary statements

Prevention : Not applicable.

Response : Not applicable.

Storage : Not applicable.

Disposal : Not applicable.

Hazards not otherwise classified : None known.

Section 3. Composition/information on ingredients

Substance/mixture : Substance

Chemical name : Proprietary Surfactant.

Other means of identification : Starch modified hydrolyzed protein surfactant.

CAS number/other identifiers

CAS number : Not available.

Product code : Not available.

Ingredient name	Other names	%	CAS number
Proprietary Surfactant.	-	100	-

Any concentration shown as a range is to protect confidentiality or is due to batch variation.

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health and hence require reporting in this section.

Section 4. First aid measures

Description of necessary first aid measures

Eye contact : Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for and remove any contact lenses. Get medical attention if irritation occurs.

Inhalation : Remove victim to fresh air and keep at rest in a position comfortable for breathing. Get medical attention if symptoms occur.

Skin contact : Flush contaminated skin with plenty of water. Remove contaminated clothing and shoes. Get medical attention if symptoms occur.

Ingestion : Wash out mouth with water. Remove victim to fresh air and keep at rest in a position comfortable for breathing. If material has been swallowed and the exposed person is conscious, give small quantities of water to drink. Do not induce vomiting unless directed to do so by medical personnel. Get medical attention if symptoms occur.

Most important symptoms/effects, acute and delayed

Potential acute health effects

Eye contact : No known significant effects or critical hazards.

Inhalation : No known significant effects or critical hazards.

Skin contact : No known significant effects or critical hazards.

Ingestion : No known significant effects or critical hazards.

Over-exposure signs/symptoms

Eye contact : No specific data.

Inhalation : No specific data.

Skin contact : No specific data.

Ingestion : No specific data.

Indication of immediate medical attention and special treatment needed, if necessary

Notes to physician : Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.

Specific treatments : No specific treatment.

Section 4. First aid measures

Protection of first-aiders : No action shall be taken involving any personal risk or without suitable training.

See toxicological information (Section 11)

Section 5. Fire-fighting measures

Extinguishing media

Suitable extinguishing media : Use an extinguishing agent suitable for the surrounding fire.

Unsuitable extinguishing media : None known.

Specific hazards arising from the chemical : In a fire or if heated, a pressure increase will occur and the container may burst.

Hazardous thermal decomposition products : Decomposition products may include the following materials:
carbon dioxide
carbon monoxide
sulfur oxides
Ammonia.

Special protective actions for fire-fighters : Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training.

Special protective equipment for fire-fighters : Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

Section 6. Accidental release measures

Personal precautions, protective equipment and emergency procedures

For non-emergency personnel : No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Put on appropriate personal protective equipment.

For emergency responders : If specialised clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".

Environmental precautions : Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).

Methods and materials for containment and cleaning up

Small spill : Stop leak if without risk. Move containers from spill area. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.

Section 6. Accidental release measures

Large spill : Stop leak if without risk. Move containers from spill area. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see Section 13). Dispose of via a licensed waste disposal contractor. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.

Section 7. Handling and storage

Precautions for safe handling

Protective measures : Put on appropriate personal protective equipment (see Section 8).

Advice on general occupational hygiene : Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.

Conditions for safe storage, including any incompatibilities : Store in accordance with local regulations. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination.

Section 8. Exposure controls/personal protection

Control parameters

Occupational exposure limits

None.

Appropriate engineering controls : Good general ventilation should be sufficient to control worker exposure to airborne contaminants.

Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.

Individual protection measures

Hygiene measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.

Eye/face protection : Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.

Skin protection

Section 8. Exposure controls/personal protection

Hand protection : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.

Body protection : Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.

Other skin protection : Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.

Respiratory protection : Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary. Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator.

Section 9. Physical and chemical properties

Appearance

Physical state : Liquid. [Viscous Gel.]

Color : Opaque. [Dark]

Odor : Cinnamon.

Odor threshold : Not available.

pH : Not available.

Melting point : Not available.

Boiling point : 99°C (210.2°F)

Flash point : Non-flammable. ASTM E1354.

Evaporation rate : Not available.

Flammability (solid, gas) : Not applicable.

Lower and upper explosive (flammable) limits : Not available.

Vapor pressure : 3.3 kPa (25 mm Hg) [room temperature]

Vapor density : Not available.

Relative density : 0.99 to 1.01

Solubility : Easily soluble in the following materials: cold water and hot water.

Solubility in water : Easily soluble.

Partition coefficient: n-octanol/water : Not available.

Auto-ignition temperature : Not available.

Decomposition temperature : Not available.

SADT : Not available.

Viscosity : Not available.

Section 10. Stability and reactivity

Reactivity : No specific test data related to reactivity available for this product or its ingredients.

Chemical stability : The product is stable.

Possibility of hazardous reactions : Under normal conditions of storage and use, hazardous reactions will not occur.

Under normal conditions of storage and use, hazardous polymerization will not occur.

Conditions to avoid : Keep from freezing. Keep away from heat.

Incompatible materials : No specific data.

Hazardous decomposition products : Low levels of sulfur oxides and ammonia on exposure to high temperatures.

Section 11. Toxicological information

Information on toxicological effects

Acute toxicity

Not available.

Conclusion/Summary : Not expected.

Irritation/Corrosion

Not available.

Sensitization

Not available.

Mutagenicity

Conclusion/Summary : Not available.

Carcinogenicity

Conclusion/Summary : Not available.

Reproductive toxicity

Conclusion/Summary : Not available.

Teratogenicity

Conclusion/Summary : Not available.

Specific target organ toxicity (single exposure)

Not available.

Specific target organ toxicity (repeated exposure)

Not available.

Aspiration hazard

Not available.

Information on the likely routes of exposure : Not available.

Section 11. Toxicological information

Potential acute health effects

Eye contact : No known significant effects or critical hazards.

Inhalation : No known significant effects or critical hazards.

Skin contact : No known significant effects or critical hazards.

Ingestion : No known significant effects or critical hazards.

Symptoms related to the physical, chemical and toxicological characteristics

Eye contact : No specific data.

Inhalation : No specific data.

Skin contact : No specific data.

Ingestion : No specific data.

Delayed and immediate effects and also chronic effects from short and long term exposure

Short term exposure

Potential immediate effects : Not available.

Potential delayed effects : Not available.

Long term exposure

Potential immediate effects : Not available.

Potential delayed effects : Not available.

Potential chronic health effects

Not available.

General : No known significant effects or critical hazards.

Carcinogenicity : No known significant effects or critical hazards.

Mutagenicity : No known significant effects or critical hazards.

Teratogenicity : No known significant effects or critical hazards.

Developmental effects : No known significant effects or critical hazards.

Fertility effects : No known significant effects or critical hazards.

Numerical measures of toxicity

Acute toxicity estimates

Not available.

Section 12. Ecological information

Toxicity

Not available.

Persistence and degradability

Conclusion/Summary : OECD METHOD 301

Section 12. Ecological information

Product/ingredient name	Aquatic half-life	Photolysis	Biodegradability
Proprietary Surfactant.	-	-	Readily

Bioaccumulative potential

Not available.

Mobility in soil

Soil/water partition coefficient (K_{OC}) : Not available.

Other adverse effects : No known significant effects or critical hazards.

Section 13. Disposal considerations

Disposal methods : The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Empty containers or liners may retain some product residues. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

Section 14. Transport information

	DOT Classification	IMDG	IATA
UN number	Not regulated.	Not regulated.	Not regulated.
UN proper shipping name	-	-	-
Transport hazard class(es)	-	-	-
Packing group	-	-	-
Environmental hazards	No.	No.	No.
Additional information	-	-	-

Special precautions for user : **Transport within user's premises:** always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

Section 14. Transport information

Transport in bulk according to Annex II of MARPOL 73/78 and the IBC Code : Not available.

Section 15. Regulatory information

U.S. Federal regulations : **United States inventory (TSCA 8b)**: Not determined.

Clean Air Act Section 112 (b) Hazardous Air Pollutants (HAPs) : Not listed

Clean Air Act Section 602 Class I Substances : Not listed

Clean Air Act Section 602 Class II Substances : Not listed

DEA List I Chemicals (Precursor Chemicals) : Not listed

DEA List II Chemicals (Essential Chemicals) : Not listed

SARA 302/304

Composition/information on ingredients

No products were found.

SARA 304 RQ : Not applicable.

SARA 311/312

Classification : Not applicable.

Composition/information on ingredients

No products were found.

SARA 313

Not applicable.

State regulations

Massachusetts : This material is not listed.

New York : This material is not listed.

New Jersey : This material is not listed.

Pennsylvania : This material is not listed.

California Prop. 65

None of the components are listed.

Chemical Weapon Convention List Schedules I, II & III Chemicals

Not listed.

Montreal Protocol (Annexes A, B, C, E)

Not listed.

Stockholm Convention on Persistent Organic Pollutants

Not listed.

Rotterdam Convention on Prior Inform Consent (PIC)

Not listed.


Section 15. Regulatory information

UNECE Aarhus Protocol on POPs and Heavy Metals

Not listed.

Section 16. Other information

Hazardous Material Information System (U.S.A.)



Caution: HMIS® ratings are based on a 0-4 rating scale, with 0 representing minimal hazards or risks, and 4 representing significant hazards or risks Although HMIS® ratings are not required on SDSs under 29 CFR 1910. 1200, the preparer may choose to provide them. HMIS® ratings are to be used with a fully implemented HMIS® program. HMIS® is a registered mark of the National Paint & Coatings Association (NPCA). HMIS® materials may be purchased exclusively from J. J. Keller (800) 327-6868.

The customer is responsible for determining the PPE code for this material.

National Fire Protection Association (U.S.A.)



Reprinted with permission from NFPA 704-2001, Identification of the Hazards of Materials for Emergency Response Copyright ©1997, National Fire Protection Association, Quincy, MA 02269. This reprinted material is not the complete and official position of the National Fire Protection Association, on the referenced subject which is represented only by the standard in its entirety.

Copyright ©2001, National Fire Protection Association, Quincy, MA 02269. This warning system is intended to be interpreted and applied only by properly trained individuals to identify fire, health and reactivity hazards of chemicals. The user is referred to certain limited number of chemicals with recommended classifications in NFPA 49 and NFPA 325, which would be used as a guideline only. Whether the chemicals are classified by NFPA or not, anyone using the 704 systems to classify chemicals does so at their own risk.

Procedure used to derive the classification

Classification	Justification
Not classified.	

History

Date of issue/Date of revision : 05/28/2015

Date of previous issue : No previous validation

Version : 1

Prepared by : IHS

Section 16. Other information

Key to abbreviations : ATE = Acute Toxicity Estimate
BCF = Bioconcentration Factor
GHS = Globally Harmonized System of Classification and Labelling of Chemicals
IATA = International Air Transport Association
IBC = Intermediate Bulk Container
IMDG = International Maritime Dangerous Goods
LogPow = logarithm of the octanol/water partition coefficient
MARPOL 73/78 = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution)
UN = United Nations

References : HCS (U.S.A.)- Hazard Communication Standard
International transport regulations

Indicates information that has changed from previously issued version.

Notice to reader

To the best of our knowledge, the information contained herein is accurate. However, neither the above-named supplier, nor any of its subsidiaries, assumes any liability whatsoever for the accuracy or completeness of the information contained herein.
Final determination of suitability of any material is the sole responsibility of the user. All materials may present unknown hazards and should be used with caution. Although certain hazards are described herein, we cannot guarantee that these are the only hazards that exist.

SAFETY DATA SHEET

LONG DURATION FOAM AC-645

Section 1. Identification

GHS product identifier : LONG DURATION FOAM AC-645

Chemical name : Proprietary Surfactant.

Other means of identification : Aqueous anionic surfactant mixture.

Product type : Liquid.

Relevant identified uses of the substance or mixture and uses advised against

Product use : Aqueous Surfactant. Spray application for VOC and Odor control.

Area of application : Industrial applications.

Supplier/Manufacturer : Rusmar, Inc.
216 Garfield Avenue
West Chester, PA 19380
Phone: 610-436-4314
Fax: 610-436-8436

e-mail address of person responsible for this SDS : info@rusmarinc.com
Website: www.rusmarinc.com

Emergency telephone number (with hours of operation) : 888 488 8044 or 212 682 1200
CHEMTREC 800 424 9300

Section 2. Hazards identification

OSHA/HCS status : While this material is not considered hazardous by the OSHA Hazard Communication Standard (29 CFR 1910.1200), this SDS contains valuable information critical to the safe handling and proper use of the product. This SDS should be retained and available for employees and other users of this product.

Classification of the substance or mixture : Not classified.

GHS label elements

Signal word : No signal word.

Hazard statements : No known significant effects or critical hazards.

Precautionary statements

Prevention : Not applicable.

Response : Not applicable.

Storage : Not applicable.

Disposal : Not applicable.

Hazards not otherwise classified : None known.

Section 3. Composition/information on ingredients

Substance/mixture : Substance

Chemical name : Proprietary Surfactant.

Other means of identification : Aqueous anionic surfactant mixture.

CAS number/other identifiers

CAS number : Not available.

Product code : Not available.

Ingredient name	Other names	%	CAS number
Proprietary Surfactant.	-	100	-

Any concentration shown as a range is to protect confidentiality or is due to batch variation.

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health and hence require reporting in this section.

Section 4. First aid measures

Description of necessary first aid measures

Eye contact : Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for and remove any contact lenses. Get medical attention if irritation occurs.

Inhalation : Remove victim to fresh air and keep at rest in a position comfortable for breathing. Get medical attention if symptoms occur.

Skin contact : Flush contaminated skin with plenty of water. Remove contaminated clothing and shoes. Get medical attention if symptoms occur.

Ingestion : Wash out mouth with water. Remove victim to fresh air and keep at rest in a position comfortable for breathing. If material has been swallowed and the exposed person is conscious, give small quantities of water to drink. Do not induce vomiting unless directed to do so by medical personnel. Get medical attention if symptoms occur.

Most important symptoms/effects, acute and delayed

Potential acute health effects

Eye contact : No known significant effects or critical hazards.

Inhalation : No known significant effects or critical hazards.

Skin contact : No known significant effects or critical hazards.

Ingestion : No known significant effects or critical hazards.

Over-exposure signs/symptoms

Eye contact : No specific data.

Inhalation : No specific data.

Skin contact : No specific data.

Ingestion : No specific data.

Indication of immediate medical attention and special treatment needed, if necessary

Notes to physician : Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.

Specific treatments : No specific treatment.

Section 4. First aid measures

Protection of first-aiders : No action shall be taken involving any personal risk or without suitable training.

See toxicological information (Section 11)

Section 5. Fire-fighting measures

Extinguishing media

Suitable extinguishing media : Use an extinguishing agent suitable for the surrounding fire.

Unsuitable extinguishing media : None known.

Specific hazards arising from the chemical : In a fire or if heated, a pressure increase will occur and the container may burst.

Hazardous thermal decomposition products : Decomposition products may include the following materials:
carbon dioxide
carbon monoxide
sulfur oxides

Special protective actions for fire-fighters : Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training.

Special protective equipment for fire-fighters : Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

Section 6. Accidental release measures

Personal precautions, protective equipment and emergency procedures

For non-emergency personnel : No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Put on appropriate personal protective equipment.

For emergency responders : If specialised clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".

Environmental precautions : Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).

Methods and materials for containment and cleaning up

Small spill : Stop leak if without risk. Move containers from spill area. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.

Section 6. Accidental release measures

Large spill : Stop leak if without risk. Move containers from spill area. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see Section 13). Dispose of via a licensed waste disposal contractor. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.

Section 7. Handling and storage

Precautions for safe handling

Protective measures : Put on appropriate personal protective equipment (see Section 8).

Advice on general occupational hygiene : Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.

Conditions for safe storage, including any incompatibilities : Store in accordance with local regulations. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination.

Section 8. Exposure controls/personal protection

Control parameters

Occupational exposure limits

None.

Appropriate engineering controls : Good general ventilation should be sufficient to control worker exposure to airborne contaminants.

Environmental exposure controls : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.

Individual protection measures

Hygiene measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.

Eye/face protection : Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.

Skin protection

Section 8. Exposure controls/personal protection

Hand protection : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.

Body protection : Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.

Other skin protection : Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.

Respiratory protection : Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary. Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator.

Section 9. Physical and chemical properties

Appearance

Physical state : Liquid. [Clear viscous liquid.]

Color : Translucent. White.

Odor : Odorless.

Odor threshold : Not available.

pH : Not available.

Melting point : Not available.

Boiling point : 99°C (210.2°F)

Flash point : Not applicable.

Evaporation rate : Not available.

Flammability (solid, gas) : Not applicable.

Lower and upper explosive (flammable) limits : Not available.

Vapor pressure : 3.3 kPa (25 mm Hg) [room temperature]

Vapor density : Not available.

Relative density : 1.01 to 1.06

Solubility : Easily soluble in the following materials: cold water and hot water.

Solubility in water : Easily soluble.

Partition coefficient: n-octanol/water : Not available.

Auto-ignition temperature : Not available.

Decomposition temperature : Not available.

SADT : Not available.

Viscosity : Not available.

Section 10. Stability and reactivity

Reactivity : No specific test data related to reactivity available for this product or its ingredients.

Chemical stability : The product is stable.

Possibility of hazardous reactions : Under normal conditions of storage and use, hazardous reactions will not occur.

Under normal conditions of storage and use, hazardous polymerization will not occur.

Conditions to avoid : Keep away from heat.

Incompatible materials : No specific data.

Hazardous decomposition products : Low levels of sulfur oxides on exposure to high temperatures (concentrate).

Section 11. Toxicological information

Information on toxicological effects

Acute toxicity

Not available.

Conclusion/Summary : Not expected.

Irritation/Corrosion

Not available.

Sensitization

Not available.

Mutagenicity

Conclusion/Summary : Not available.

Carcinogenicity

Conclusion/Summary : Not available.

Reproductive toxicity

Conclusion/Summary : Not available.

Teratogenicity

Conclusion/Summary : Not available.

Specific target organ toxicity (single exposure)

Not available.

Specific target organ toxicity (repeated exposure)

Not available.

Aspiration hazard

Not available.

Information on the likely routes of exposure : Not available.

Section 11. Toxicological information

Potential acute health effects

Eye contact : No known significant effects or critical hazards.

Inhalation : No known significant effects or critical hazards.

Skin contact : No known significant effects or critical hazards.

Ingestion : No known significant effects or critical hazards.

Symptoms related to the physical, chemical and toxicological characteristics

Eye contact : No specific data.

Inhalation : No specific data.

Skin contact : No specific data.

Ingestion : No specific data.

Delayed and immediate effects and also chronic effects from short and long term exposure

Short term exposure

Potential immediate effects : Not available.

Potential delayed effects : Not available.

Long term exposure

Potential immediate effects : Not available.

Potential delayed effects : Not available.

Potential chronic health effects

Not available.

General : No known significant effects or critical hazards.

Carcinogenicity : No known significant effects or critical hazards.

Mutagenicity : No known significant effects or critical hazards.

Teratogenicity : No known significant effects or critical hazards.

Developmental effects : No known significant effects or critical hazards.

Fertility effects : No known significant effects or critical hazards.

Numerical measures of toxicity

Acute toxicity estimates

Not available.

Section 12. Ecological information

Toxicity

Not available.

Persistence and degradability

Not available.

Section 12. Ecological information

Bioaccumulative potential

Not available.

Mobility in soil

Soil/water partition coefficient (K_{OC}) : Not available.

Other adverse effects : No known significant effects or critical hazards.

Section 13. Disposal considerations

Disposal methods : The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Empty containers or liners may retain some product residues. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

Section 14. Transport information

	DOT Classification	IMDG	IATA
UN number	Not regulated.	Not regulated.	Not regulated.
UN proper shipping name	-	-	-
Transport hazard class(es)	-	-	-
Packing group	-	-	-
Environmental hazards	No.	No.	No.
Additional information	-	-	-

Special precautions for user : **Transport within user's premises:** always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

Transport in bulk according to Annex II of MARPOL 73/78 and the IBC Code : Not available.

Section 15. Regulatory information

U.S. Federal regulations : **United States inventory (TSCA 8b)**: Not determined.

Clean Air Act Section 112 (b) Hazardous Air Pollutants (HAPs) : Not listed

Clean Air Act Section 602 Class I Substances : Not listed

Clean Air Act Section 602 Class II Substances : Not listed

DEA List I Chemicals (Precursor Chemicals) : Not listed

DEA List II Chemicals (Essential Chemicals) : Not listed

SARA 302/304

Composition/information on ingredients

No products were found.

SARA 304 RQ : Not applicable.

SARA 311/312

Classification : Not applicable.

Composition/information on ingredients

No products were found.

SARA 313

Not applicable.

State regulations

Massachusetts : This material is not listed.

New York : This material is not listed.

New Jersey : This material is not listed.

Pennsylvania : This material is not listed.

California Prop. 65

None of the components are listed.

Chemical Weapon Convention List Schedules I, II & III Chemicals

Not listed.

Montreal Protocol (Annexes A, B, C, E)

Not listed.

Stockholm Convention on Persistent Organic Pollutants

Not listed.

Rotterdam Convention on Prior Inform Consent (PIC)

Not listed.

UNECE Aarhus Protocol on POPs and Heavy Metals

Not listed.

United States

Section 16. Other information

Hazardous Material Information System (U.S.A.)

Health	0
Flammability	0
Physical hazards	0

Caution: HMIS® ratings are based on a 0-4 rating scale, with 0 representing minimal hazards or risks, and 4 representing significant hazards or risks Although HMIS® ratings are not required on SDSs under 29 CFR 1910. 1200, the preparer may choose to provide them. HMIS® ratings are to be used with a fully implemented HMIS® program. HMIS® is a registered mark of the National Paint & Coatings Association (NPCA). HMIS® materials may be purchased exclusively from J. J. Keller (800) 327-6868.

The customer is responsible for determining the PPE code for this material.

National Fire Protection Association (U.S.A.)



Reprinted with permission from NFPA 704-2001, Identification of the Hazards of Materials for Emergency Response Copyright ©1997, National Fire Protection Association, Quincy, MA 02269. This reprinted material is not the complete and official position of the National Fire Protection Association, on the referenced subject which is represented only by the standard in its entirety.

Copyright ©2001, National Fire Protection Association, Quincy, MA 02269. This warning system is intended to be interpreted and applied only by properly trained individuals to identify fire, health and reactivity hazards of chemicals. The user is referred to certain limited number of chemicals with recommended classifications in NFPA 49 and NFPA 325, which would be used as a guideline only. Whether the chemicals are classified by NFPA or not, anyone using the 704 systems to classify chemicals does so at their own risk.

Procedure used to derive the classification

Classification	Justification
Not classified.	

History

Date of issue/Date of revision : 05/28/2015

Date of previous issue : No previous validation

Version : 1

Prepared by : IHS

Key to abbreviations : ATE = Acute Toxicity Estimate
BCF = Bioconcentration Factor
GHS = Globally Harmonized System of Classification and Labelling of Chemicals
IATA = International Air Transport Association
IBC = Intermediate Bulk Container
IMDG = International Maritime Dangerous Goods
LogPow = logarithm of the octanol/water partition coefficient
MARPOL 73/78 = International Convention for the Prevention of Pollution From Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution)
UN = United Nations

Section 16. Other information

References : HCS (U.S.A.)- Hazard Communication Standard
International transport regulations

Indicates information that has changed from previously issued version.

Notice to reader

To the best of our knowledge, the information contained herein is accurate. However, neither the above-named supplier, nor any of its subsidiaries, assumes any liability whatsoever for the accuracy or completeness of the information contained herein.
Final determination of suitability of any material is the sole responsibility of the user. All materials may present unknown hazards and should be used with caution. Although certain hazards are described herein, we cannot guarantee that these are the only hazards that exist.

APPENDIX I
Proposed Notification to I.S. 136 Charles O. Dewey Middle School

H & A OF NEW YORK ENGINEERING
AND GEOLOGY, LLP
213 W. 35th St
7th Floor
New York, NY 10001
646.277.5685

November 4, 2025
File No. 0210815

I.S. 136 Charles O. Dewey Middle School
4004 4th Avenue
Brooklyn, New York 11232

Attention: Myrna Gonzalez Rojas
Principal/Director

Subject: Interim Remedial Measure Notification Letter
4001 4th Avenue Redevelopment Site
NYSDEC Site No. C224412
4001-4011 4th Avenue
Brooklyn, New York

Dear Myrna Gonzalez Rojas:


On behalf of 4 Ave Property LLC, H & A of New York Engineering and Geology, LLP (Haley & Aldrich of New York) is sending this letter as official notification regarding the Interim Remedial Measure (IRM) for the 4001 4th Avenue Redevelopment Site, New York State Department of Environmental Conservation (NYSDEC) Site No. C224412, located at 4001-4011 4th Avenue in Brooklyn, New York (Site). The objective of this IRM is to facilitate the removal of four 4,000-gallon underground storage tanks (USTs) and associated impacted soils. The IRM will be completed in accordance with the NYSDEC-approved IRM Work Plan (IRMWP), and the Site will be locked and inaccessible to the public during IRM implementation. The proposed IRM activities are summarized as follows:

- Implementation of a Community Air Monitoring Plan (CAMP), including monitoring for the presence of volatile organic compounds (VOCs) and particulates. Dust, odor, and nuisance controls will be implemented, (as needed);
- Equipment mobilization;
- Concrete pavement removal in the area of excavation;
- Support-of-excavation (SOE) installation to the west and south of the tank area;
- Excavation and off-Site disposal of historic fill and hydrocarbon contaminated soil;
- Although not anticipated, localized dewatering (as needed);
- Cleaning and removal of residual UST contents;
- Removal of USTs and/or associated appurtenances;
- Collection of confirmation samples; and,
- Installation of a demarcation barrier and backfilling of the UST area with a 6-inch-thick temporary cover of NYSDEC-approved certified clean fill and/or gravel.


Implementation of the IRM activities will be conducted in accordance with the NYSDEC approved IRMWP available at https://extapps.dec.ny.gov/data/DecDocs/C224412/, which includes measures for community air monitoring.

Should you have any questions or comments, please feel free to contact the NYSDEC Project Manager (Shawn Roberts) at Shawn.Roberts@dec.ny.gov, the New York State Department of Health (NYSDOH) Project Manager (Christopher Budd) at Christopher.Budd@health.ny.gov.

Sincerely yours,
H & A OF NEW YORK ENGINEERING AND GEOLOGY, LLP



Nicole A. Mooney
Assistant Project Manager



Mari C. Conlon
Senior Associate