PHASE I ENVIRONMENTAL SITE ASSESSMENT

for

213 Meadow Street
Brooklyn, New York

Prepared For:

GO Quay, LLC
432 Park Avenue South, 2nd Floor
New York, New York

Prepared By:

Langan Engineering, Environmental, Surveying,
Landscape Architecture and Geology, D.P.C.
300 Kimball Drive
Parsippany, New Jersey 07054
NJ Certificate of Authorization No: 24GA27996400

Amanda Forsburg, CHMM
Senior Project Scientist

Steven Ciambruschini, P.G., L.E.P.
Senior Principal / Senior Vice President

Commencement Date: 20 January 2022
Final Report Completion: 11 March 2022

100964202

LANGAN

TABLE OF CONTENTS

Page No.

EXECUTIVE SUMMARY i

1.0 INTRODUCTION 1

2.0 RELIANCE/LIMITATIONS 1

3.0 SITE DESCRIPTION 3

4.0 GEOLOGIC AND HYDROGEOLOGIC CONDITIONS 4

5.0 USER PROVIDED INFORMATION 4

5.1 Title Records 5

5.2 Environmental Liens or Activity and Use Limitations 5

5.3 Specialized Knowledge 5

5.4 Valuation Reduction for Environmental Issues 5

5.5 Commonly Known Information 6

5.6 Documentation Provided by the User 6

6.0 REVIEW OF PREVIOUS LAND USE 8

6.1 Sanborn Fire Insurance Maps 8

6.2 City Directory Search 11

7.0 REGULATORY DATABASE SEARCH 12

8.0 GOVERNMENT AGENCY RECORDS REVIEW 22

9.0 SITE RECONNAISSANCE 26

10.0 ADDITIONAL ISSUES 27

10.1 Wetlands/Floodplain Designation 28

10.2 Protected Endangered Species / Critical Habitats 28

10.3 Asbestos 28

10.4 Lead-based Paint 29

10.5 Lead in Drinking Water 29

10.6 Indoor Air / Microbial Assessment (Mold) 29

TABLE OF CONTENTS

10.7 Radon 29

10.8 Historical and Archaeological Review 29

11.0 DEVIATIONS 30

12.0 FINDINGS/OPINIONS 31

13.0 CONCLUSIONS 32

14.0 QUALIFICATIONS / CERTIFICATION 33

TABLE OF CONTENTS

LIST OF TABLES

Table 1 **List of Contacts**

LIST OF FIGURES

Figure 1 **Site Location Map**
Figure 2 **Tax Map**
Figure 3 **Zoning Map**

APPENDICES

Appendix A **User Questionnaire**
Appendix B **Property Owner/Operator/Key Site Manager Questionnaire**
Appendix C **Sanborn Maps**
Appendix D **City Directory Search**
Appendix E **Environmental Database Radius Report**
Appendix F **Government Correspondence and Records**
Appendix G **Site Photographs**
Appendix H **Langan Resumes**

EXECUTIVE SUMMARY

This Phase I Environmental Site Assessment (ESA) was prepared by Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. on behalf of GO Quay, LLC to identify current or potential environmental concerns and Recognized Environmental Conditions (RECs) at the ±56,200 square foot proposed development site consisting of the property at 213 Meadow Street (Block 2951, Lots 1, 5, and 45) located in Brooklyn, New York ("site" or "subject property"). The ESA included a site inspection, review of historical information, completion of a federal/state/local environmental database search, and interviews with local and state agencies to assess current and past site conditions.

The subject property is zoned M3-1 Heavy Manufacturing District and is used primarily for storage with a small one-story structure located on Lot 45, and is currently occupied by Castle Demolition truck storage and repairs, food truck storage, and scaffolding storage areas. An out-of-service fuel oil aboveground storage tank (AST) and three 275-gallon ASTs containing waste oil, motor oil, and hydraulic oil AST are present in Lot 45. A one-story storage shed is located in Lot 45 also contains approximately 14 55-gallons drum containing degreasers, motor oil, and hydraulic oil staged on secondary containment pallets. The ASTs and drums will require proper closure and removal prior to site redevelopment.

The subject property was operated for oil truck parking, junk yards, and auto wrecking on the western portion of the property from 1965 through 2007 and as a solid waste transfer facility for yard waste and residential, institutional, and commercial waste from at least 2004 through 2012. Historical and current uses of surrounding sites includes a private garage with truck repair, paint room, gasoline tank, wire product manufacturing, an oil/fuel company, metals stamping, and metal products manufacturing between 1951 and 2007, a vinyl plastics company and a chemical products company with manufacturing facilities between 1965 and 2007, gasoline storage between 1933 and 1988, auto wrecking between 1965 and 1977, an automobile repair facility (1933-1987), filling stations (1933-1968), and an oil terminal (1933-1968).

A Phase II Environmental Investigation (EI) conducted by Langan in February 2022 revealed the presence of contaminated historic fill material impacted with heavy metals and semi-volatile organic compounds (SVOCs), some of which exceeded New York State Department of Environmental Conservation (NYSDEC) Commercial Restricted Use Soil Cleanup Objectives (RUSCOs), Industrial RUSCOs, and Protection of Groundwater Soil Cleanup Objectives (SCOs). Groundwater analytical results revealed the presence of elevated concentration of metals and SVOCs, which are consistent with contaminated historic fill

impacts observed in soil. Odors were encountered in some borings and elevated photoionization detector (PID) readings were also present in certain borings as further described below.

Based on information obtained during the visual inspection of the subject property, review of environmental databases and historic information, and contact with federal/state/local official agencies, the following recognized environmental conditions (RECs), historic recognized environmental conditions (HRECs), de minimis conditions, and business environmental risks that may impact proposed redevelopment of the site were identified:

Recognized Environmental Conditions

A REC is defined as the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment. It is the opinion of the environmental professional that the following represent RECs:

Presence of Contaminated Historic Fill

Based on the findings of the 2022 Phase II EI, contaminated fill impacted with elevated concentrations of metals and SVOCs above the NYSDEC Soil Cleanup Objectives is present in the subsurface at the subject property. Odors and elevated PID readings were also detected, suggesting contamination may be present that was not found during the initial Phase II EI or that weathered petroleum contamination and nuisance soil conditions are present. The presence of contaminated historic fill material will require implementation of soil handling and management procedures to address excavation, reuse, handling, and possible offsite disposal of this material during site redevelopment. The presence of contaminated fill represents a REC.

Historical Recognized Environmental Conditions

An HREC is defined as a past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls. It is the opinion of the environmental professional that the following represent HRECs:

Spill Case #9315532

The subject property is identified in the NY Spills database for a release reported to the department on 31 March 1994 and assigned NYSDEC Spill No. 9315532. According to the case narrative provided by EDR, a tank truck spilled approximately 5-gallons of diesel onto

the concrete and clean up was in progress at the time the spill was reported. No additional information was provided and the spill was administratively closed on 31 March 1994. It is of the opinion of the environmental professional that the closed spill represents an HREC.

De Minimis Conditions

A de minimis condition is defined as a condition that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. It is the opinion of the environmental professional that the following represent de minimis conditions:

Motor Oil Release

Evidence of a release of oil limited to small, isolated areas on the concrete in the southeastern lot of the subject property was observed during Langan's ESA site inspection. Staining was observed on the concrete and speedy dry had been placed on the stained concrete. No gaps or cracks were observed. There was no evidence of a substantial release that would impact the subsurface of the subject property.

Business Environmental Risks

A BER is defined as a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated in this practice. Consideration of BER issues may involve addressing one or more non-scope considerations. It is the opinion of the environmental professional that the following represent business environmental risks:

Current and Historical Site Operations

Historical uses of concern at the subject property included oil truck parking, auto wrecking, and a junk yard between 1960 and 2007 and as a solid waste transfer facility for yard waste and residential, institutional, and commercial waste from at least 2004 through 2012. Current site use includes truck storage and repairs including three in-service 275-gallon ASTs and one out-of-service AST.

Langan completed a Phase II EI in February 2022 to determine if current and historical site operations have impacted subsurface conditions. Soil analytical results revealed the presence of contaminated fill material (discussed above). The potential exists that impacts resulting from these uses may be present at the subject property but were not found during the initial Phase II EI. However, odors were observed at all except one boring. Elevated PID readings were detected between 4.8 parts-per-million (ppm) and 171 ppm at two borings at 8 and 17 feet below

ground surface (bgs) suggesting contamination may be present that was not found during the initial Phase II EI or that weathered petroleum contamination is present and nuisance soil conditions are present. Based on these findings, it is the opinion of the environmental professional that the potential for subsurface impacts as a result of current and historical site use at the subject property represents a business environmental risk.

Potential Presence of Undocumented Underground Storage Tanks

While no evidence of USTs was observed during the site inspection or noted during this ESA, the site has historically been operated for automotive-related purposes. Due to this historical use of the site, it is the opinion of the environmental professional that the potential presence of waste oil or motor oil USTs beneath the lots or adjacent sidewalks represents a business environmental risk. During any proposed site redevelopment, a contingency plan to properly remove and dispose of any USTs that may be encountered in accordance with state and local regulations should be employed. The geophysical utility clearance completed on 3 February 2022 as part of the Phase II EI did detect some small unidentified buried objects in the vicinity of boring LSB-3, LSB-4, and LSB-7 as described in that report.

1.0 INTRODUCTION

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. (Langan) has completed a Phase I Environmental Site Assessment (ESA) of a ±56,200 square foot site located at 213 Meadow Street, Brooklyn, Kings County, New York (Figure 1).

This ESA was conducted to identify current or potential environmental concerns and/or Recognized Environmental Conditions (RECs) resulting from past or current activities on the subject property, as well as to evaluate immediately surrounding environs with the potential to impact upon the property. The assessment consisted of a site reconnaissance of all accessible property areas, a review of State and Federal environmental databases as they concern the subject property and surrounding areas, contact with Federal, State and local agencies, a review of Sanborn Fire Insurance Maps of the subject property and surrounding areas, and a review of local/county records.

The ESA was conducted in a manner consistent with industry standard and practice and in accordance with the Standards of the American Society for Testing and Materials (ASTM) E1527-13 Standard Practice for Environmental Site Assessments. Any deviations from this practice are provided in Section 11.0 of this report.

2.0 RELIANCE/LIMITATIONS

This ESA report was prepared for GO Quay, LLC, for the 213 Meadow Street project and for the objectives of due diligence. The report is intended to be used in its entirety. Excerpts taken from this report are not necessarily representative of the assessment findings. Langan cannot assume responsibility for use of this report for any property other than the subject property addressed herein, or by any third party, without a written authorization from Langan.

Langan's scope of services, as described in the proposal dated 14 December 2021, was limited to that agreed to with GO Quay, LLC and no other services beyond those explicitly stated are implied. No exploratory borings, sampling of soil, soil vapor, or groundwater, or laboratory analysis were performed by Langan as part of the scope of services. Reliance on this report is conditioned on agreement to the terms and conditions provided with the December 2021 proposal.

This Phase I ESA was not intended to be a definitive investigation of possible environmental impacts at the subject property. The purpose of this investigation was limited to determining if there is reason to suspect the possibility of Recognized Environmental Conditions (RECs) at the subject property. It should be understood that even the most comprehensive Phase I ESA may fail to detect environmental liabilities at a particular site. Therefore, Langan cannot "insure" or "certify" that the subject property is free of environmental impacts. No expressed or implied representation or warranty is included or intended in this report, except that our services were performed, within the limits prescribed by our client, with the customary thoroughness and competence of our profession. The user is cautioned that federal, state, and local laws may impose environmental obligations that are beyond the scope of ASTM Practice E 1527-13.

The conclusions, opinions and recommendations provided in this report are based solely on the following activities:

- Visual observations of the subject property and the immediate vicinity at the time of Langan's site visit;
- Review of relevant available historical information; and,
- Correspondence and/or discussion with personnel knowledgeable about the site.

The conclusions, opinions and recommendations are intended exclusively for the purpose stated herein, at the specified subject property, as it existed at the time of our site visit.

The User is responsible for the review and identification of environmental liens, activity, and use limitations, and for ascertaining reasons for significantly lower purchase property price in accordance with Section 6 of ASTM E 1527-13. A questionnaire covering these above-concerns was provided to GO Quay, LLC and is included as Appendix A. In addition, a similar questionnaire was provided to the property owner but was not returned; a blank copy is included as Appendix B. If any of these above-concerns were uncovered during the course of the Phase I ESA, they are addressed in this report.

The report findings are based in part on information provided by local, county and state officials and environmental databases from Federal and State sources. Langan assumes no responsibility for the accuracy and completeness of this information.

Visual observations discussed in this report represent conditions at the time of the site inspection and may not be representative of the past or future site conditions.

As per ASTM E1527-13, Phase I ESA Report deviations, as well as professional opinions regarding these deviations, are listed in Section 11.0.

This ESA has been prepared for the sole use of GO Quay, LLC. This ESA should not be relied upon by other parties without the express consent of Langan and GO Quay, LLC. In accordance with Section 4.6 of ASTM E 1527-13 and 40 CFR §312.20, a Phase I ESA may be considered valid for one year starting from the commencement date of the assessment listed on the front cover of this report. The formal property acquisition/real estate transaction must take place during this period. However, the following components must be conducted or updated within 180 days (six months) prior to the date of the property acquisition/real estate transaction:

- Interviews with past and present owners, operators and occupants;
- Searches for recorded environmental cleanup liens;
- Review of governmental records;
- Site Reconnaissance of the property and adjoining properties; and,
- The declaration by the Environmental Professional.

3.0 SITE DESCRIPTION

The subject property is designated as Block 2951, Lots 1, 5, and 45 by the New York City Department of Finance (Figure 2). The subject property is mostly undeveloped with a small one-story structure located on Lot 45, and is currently occupied Castle Demolition truck storage and repairs, food truck storage, and scaffolding storage areas.

The subject property is bound to the north by an undeveloped lot used for automobile junking and storage, followed by Ten Eyck Street and a one-story industrial/ manufacturing building; to the east by the undeveloped lot used for automobile junking and storage followed by Stewart Avenue and a two-story industrial/manufacturing building complex; to the south by Meadow Street followed by a two-story industrial/manufacturing building and parking areas; and, to the west by Varick Avenue followed by a two-story industrial/manufacturing waste management building and transfer station. The subject property is located within an area of dense industrial and manufacturing development on the city block bound by Ten Eyck Street to the north, Stewart Avenue to the east, Meadow Street to the south, and Varick Avenue to the west.

The property is currently zoned as a manufacturing district (M1-3).

4.0 GEOLOGIC AND HYDROGEOLOGIC CONDITIONS

For the purpose of report completeness and to better understand the subsurface conditions, the geologic conditions in the general area of the subject property are discussed in this section.

Based on borings completed during the February 2022 Phase II Environmental Investigation discussed in Section 5.6, site stratigraphy in the western portions of the site consists of a 1- to 2-foot thick layer of concrete underlain by a 4- to 6-foot layer of fill followed by native sand and silty sand. The central portion of the site consists of a 6-foot layer of fill underlain by native sand and silty sand. The eastern portion of the site consists of a 2-foot thick layer of concrete, underlain by an 8- to 15-foot layer of fill followed by native sand, silt, and clay. All borings were completed to approximately 20 feet below ground surface (bgs).

The "Surficial Geologic Map of New York" by the New York State Museum State Geological Survey indicates that the surficial geology at the site consists of till which is generally an impermeable layer comprised of poorly sorted and variably sized clasts. According to the "Bedrock and Engineering Geologic Maps of New York County" by Charles A. Baskerville the site is underlain by the Hartland Formation which consists of interbedded units of feldspar, schist, and amphibolite.

Groundwater was encountered between 9.5 and 11.5 feet bgs in monitoring wells completed during the Phase II EI. Based on site/area topography, groundwater flow is anticipated to be to the west, toward English Kills, a tributary of Newton Creek.

5.0 USER PROVIDED INFORMATION

A questionnaire was completed by the User and is included in Appendix A. Information obtained from this questionnaire is discussed in the sections below. Documents provided by the User are discussed in this section.

5.1 Title Records

A Title Search was not provided by the User for this ESA. Langan completed a limited review of available online records maintained by the New York City Department of Finance to determine current and former site ownership. These records are discussed in Section 8.0.

5.2 Environmental Liens or Activity and Use Limitations

Reasonably ascertainable recorded land title records and lien records that are filed under federal, tribal, state, or local law should be reviewed to identify environmental liens or activity and use limitations, if any, that are currently recorded against the property. Any environmental liens or activity and use limitations are required to be reported to the Environmental Professional conducting the ESA per ASTM E1527-13.

No environmental liens or use limitations (engineering or institutional controls) were identified for the subject property in the radius report or by the User.

5.3 Specialized Knowledge

Specialized knowledge is defined by ASTM E 1527-13 as *"any specialized knowledge or experience that is material to recognized environmental conditions in connection with the property*". For example, a User is involved in the same line of business as current or former occupants of the property or adjoining property and has specialized knowledge of the chemicals and processes used in this line of business.

The User did not provide specialized knowledge material related to recognized environmental conditions in connection with the property as part of this ESA.

5.4 Valuation Reduction for Environmental Issues

In a transaction involving the purchase of a parcel of commercial real estate, the User shall consider the relationship of the purchase price of the property to the fair market value of the property if the property was not affected by hazardous substances or petroleum products. The User should try to identify an explanation for a lower price which does not reasonably reflect fair market value if the property were not contaminated.

The User indicated that no valuation reduction for environmental issues occurred for the subject property.

5.5 Commonly Known Information

If the user is aware of any commonly known or reasonably ascertainable information within the local community about the property that is material to recognized environmental conditions in connection with the property, it is the User's responsibility to communicate such information. This information may include past uses of the property, specific chemicals that were used on site, spills or releases or environmental cleanups that have taken place.

No additional information regarding the environmental condition of the subject site was provided to Langan.

5.6 Documentation Provided by the User

The following previous environmental report pertinent to the property located at 213 Meadow Street is provided in Appendix C:

- *Phase II Environmental Investigation Report,* by Langan, dated 11 March 2022

Phase II Environmental Investigation Report

Langan completed a Phase II Environmental Investigation (EI) in February 2022 to determine if current and historical site operations have impacted subsurface conditions. Seven soil borings, four groundwater monitoring wells, and four soil vapor points were completed across the subject property. Eleven soil samples (plus one duplicate sample), four groundwater samples (plus one duplicate sample), and four soil vapor samples (plus one duplicate sample) were collected for laboratory analysis.

Site stratigraphy generally consisted of between 4 and 15 feet of fill below the site cover and underlain by native sand. All borings were completed to approximately 20 feet below ground surface (bgs).

Odors were observed at all except one boring. Elevated photoionization detector (PID) readings were detected between 4.8 parts-per-million (ppm) and 171 ppm at two borings at 8 and 17 feet bgs, suggesting contamination may be present that was not found during this initial Phase II EI or that weathered petroleum

contamination and nuisance soil conditions are present. However, staining was not observed in any soil borings completed as part of the Phase II EI.

Heavy metal and/or semi-volatile organic compounds (SVOCs) were identified above the NYSDEC SCOs in all seven soil borings. The heavy metals including arsenic, barium, copper, lead, and/or mercury were detected in all soil borings except LSB-4 and LSB-7 at concentrations exceeding the Commercial RUSCOs, Protection of Groundwater SCOs, and/or Industrial RUSCOs. SVOCs, including benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, and/or dibenzo(a,h)anthracene were detected in all soil borings except LSB-1 and LSB-6 above the Commercial RUSCOs, Protection of Groundwater and/or Restricted Industrial RUSCOs. The volatile organic compound (VOC) acetone, a common laboratory artifact, was detected in one soil boring and perfluorooctanesulfonic acid (PFOS) was detected above the proposed soil SCO in one sample. No other compounds were detected in any of the soil samples collected above the Commercial RUSCOs, Protection of Groundwater SCOs, or Industrial RUSCOs.

Metals were detected in exceedance of the NYSDEC standards and guidance values (SGVs) in all four monitoring wells, including iron, lead, magnesium, manganese, and/or sodium. SVOCs including benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, and indeno(1,2,3-cd)pyrene were detected above the SGVs in two samples. The VOC acetone, a common laboratory artifact, was detected in one sample above the SGVs. 1,4-Dioxane was detected above the drinking water maximum contaminant level (MCL) in two samples and PFOS and perfluorooctanoic acid (PFOA) were detected above the guidance values in all four samples. No other compounds were detected in any of the groundwater samples collected above the SGVs or guidance values.

Soil vapor analytical results revealed the presence of three out of the eight chlorinated VOCs that are listed in the New York State Department of Health (NYSDOH) Vapor Intrusion Guidance Decision Matrices at concentrations below those that would require monitoring or mitigation when compared against the matrices screening levels.

No additional information regarding the environmental condition of the subject site was provided to Langan.

6.0 REVIEW OF PREVIOUS LAND USE

Historic Sanborn Fire Insurance Maps and City Directory Information were requested from Environmental Data Resources (EDR) of Shelton, Connecticut. Provided are descriptions of the materials provided by these resources.

6.1 Sanborn Fire Insurance Maps

Sanborn Fire Insurance Maps of the subject property and surrounding area dated 1888, 1907, 1933, 1951, 1965, 1968, 1977, 1979, 1980, 1981, 1982, 1986, 1987, 1988, 1989, 1990, 1991, 1992, 1993, 1994, 1995, 2001, 2002, 2003, 2004, 2005, 2006, and 2007 were obtained from Environmental Data Resources and reviewed as part of this ESA. Copies of Sanborn Maps are provided in Appendix C.

Subject Property

The subject property was identified on Sanborn Maps as being undeveloped from 1888 through 1951 and Ten Eyck Street and Meadow Street to the north and south are labeled as not open during this time period. In 1965, the subject property is labeled as junk and auto wrecking and oil truck parking, and four one-story storage buildings are shown. No changes are shown through 1977, when only one storage building remains, and again through 1986 when the one storage building is no longer shown. In 1989 the subject property is no longer labeled for oil truck parking. In 2001 a portion of the site is depicted as a lumber yard. No changes are shown through 2007.

Adjacent – North

The property to the north on Block 2951 is shown as undeveloped from 1888 through 2007. Ten Eyck Street is labeled an unpaved from 1965 through 2007.

Between 1888 and 1951, the adjacent property to the north across Ten Eyck Street is depicted as being vacant. In 1951, a private garage with an office building, painting room, truck repair facility, and gasoline tank are shown, and the frontage along Varick Avenue is labeled as Preferred Oil Co. Inc. In 1977, the office building is labeled as wire products manufacturing. In 1991 the wire products manufacturer is no longer labeled, and the Varick Avenue frontage is now identified as Vijax Fuel Corp. No changes are shown through 2007.

Adjacent – East

The property to the east on Block 2951 is shown as undeveloped from 1888 through 2007.

In 1888, the adjacent property to the east across Stewart Avenue is depicted as being vacant. In 1907, the property is depicted as part of the Cross, Austin, & Ireland Lumber Yard. No changes are shown through 1933. In 1951, the property is developed with a one- to two-story plastic film manufacturing facility with a one-story warehouse and a disconnected pump house. In 1965, the development is identified as the Elm Coated Fabrics Co. Inc. which operated with vinyl plastics and has expanded to include a larger complex with a one to two-story warehouse and manufacturing space. No changes are shown through 1988. In 1989, the complex is now labeled as Kalex Chemical Products Inc. and is identified as manufacturing use. No changes are shown through 1992. In 1993, the property is no longer labeled as Kalex Chemical Products Inc. No changes are shown through 2007.

Adjacent – South

In 1888, the adjacent properties to the south are depicted as being vacant. No changes are shown in 1907. In 1933, two storage sheds and a two-story structure labeled as A & Rigger with a gasoline tank are shown. In 1951 and 1965, additional one-story buildings of unspecified use and additional two-story structures labeled rigger storage is shown. No changes are shown through 1968. In 1977, the two-story rigger storage building is no longer shown, and a traveling crane is now depicted. No changes are shown through 1986 when the original one-story storage buildings are no longer shown. In 1989, the rest of the storage sheds are no longer depicted, and the gasoline tank is no longer shown. No changes are shown through 2007.

Adjacent – West

In 1888, the adjacent property to the west is depicted as undeveloped and the former extent of Newtown Creek is mapped further to the west on the adjacent block. No changes are shown in 1907 except that Newtown Creek is no longer mapped on the block. In 1933, the property is now depicted as a lumber corporation with a small one-story office building. No changes are shown in 1951. In 1965, the property is now labeled as auto wrecking and parking and depicted with a one-story storage building in the central portion of the site. No changes are shown in 1968. In 1977, the property has been developed as Tubeco Inc. Ecology

Plant with various parking structures and four-story building. No substantive changes are shown through 2007 with the exception that the operator name changes to Star Recycling, Inc. in 1994 and Waste Management in 2005.

Sanborn Map Review Conclusions

The Sanborn Map review revealed historical uses of concern at the subject property including oil truck parking, auto wrecking, and a junk yard between 1960 and 2007.

As discussed in Section 5.6, Langan completed a Phase II EI in February 2022 to determine if current and historical site operations have impacted subsurface conditions. Soil analytical results revealed the presence of contaminated fill material but the Phase II EI did not otherwise identify the presence of impacts associated with historical or current site operations in soil, groundwater, or soil vapor. However, the potential exists that impacts resulting from these uses may be present at the subject property. It is the opinion of the environmental professional that the potential for subsurface impacts as a result of current and historical site use at the subject property represents a business environmental risk.

Historical uses of concern were identified on adjacent properties to the north, including a private garage with truck repair, paint room, gasoline tank, wire product manufacturing, an oil/fuel company, metals stamping, and metal products manufacturing between 1951 and 2007. Historical uses of concern were also identified on adjacent properties to the east including a vinyl plastics company and a chemical products company, both with manufacturing facilities between 1965 and 2007. A gasoline tank is shown on the property to the south between 1933 and 1988 and the adjacent property to the west was used for auto wrecking between 1965 and 1977.

Surrounding property uses of potential concern include an automobile repair facility approximately 455 feet to the north and hydraulically downgradient (1933-1987), filling stations located approximately 310 and 395 feet to the north and hydraulically downgradient of the subject property (1933-1968), and an oil terminal (1933-1968) located hydraulically downgradient of the subject property approximately 200-feet to the northwest across the intersection of Varick Avenue and Ten Eyck Street.

The Phase II EI conducted by Langan in February 2022 revealed the presence of fill material impacted with metals SVOCs, which are typical of urban areas. Groundwater analytical results revealed the presence of elevated concentration of metals and SVOCs which are consistent with fill impacts observed in soil. Evidence of impacts from surrounding sites were not identified.

6.2 City Directory Search

City directory information was obtained from EDR in an attempt to identify past uses of the subject property and establishments in the surrounding area. As provided in the City Directory Abstract (Appendix D), business directories including city, cross-reference and telephone directories were reviewed. City directories include the site address for the years 1960 and 1965.

The City Directory Report for the subject property listings consists of auto wrecking and demolition and salvage companies. The following historic listings refer to businesses of potential concern that were formerly located on the subject property:

Address	Business Name	Listing Date
190 Varick Avenue	Genl Wrecking Corp	1960
	Demolition & Salvage Co Inc.	1960
	South Shore Wrecking Corp.	1965

Listings over the years for adjacent properties identified businesses of potential concern and confirmed site uses presented on the Sanborn Maps including a fuel oil company (1949-1994) and wire products manufacturer (1970-1973) on the adjacent property to the north, a recycling/waste management facility (1973-2017) on the adjacent property to the west, the coated fabrics and chemical company on the adjacent property to the east (1949-1985), and the fuel oil company across the intersection of Varick Street and Ten Eyck Street to the northwest (1945).

City Directory Review Conclusions

Based on the review of the City Directory Abstract, the Sanborn Maps (discussed above), and the radius report (discussed in detail below), it is the opinion of the environmental professional that the potential for subsurface impacts as a result of current and historical site use at the subject property represents a business environmental risk.

7.0 REGULATORY DATABASE SEARCH

A database search report that identifies sites listed on state and federal databases within the ASTM-required radii was obtained for the property from Environmental Data Resources, Inc. (EDR) of Shelton, Connecticut. A copy of EDR's complete report is provided as Appendix E.

The report included the following databases specified by the ASTM Phase I protocol as well as non-ASTM databases (not listed):

RECOMMENDED/**REQUIRED** SEARCH DISTANCES
1.0-mile
Federal National Priority List (NPL)
Federal RCRA CORRACTS Facilities List
State- and Tribal-Equivalent NPL
0.5-mile
Federal Delisted NPL
Federal CERCLIS/SEMS**
Federal CERCLIS NFRAP List/SEMS-Archive**
Federal RCRA non-CORRACTS TSD Facilities List
State- and Tribal-Equivalent CERCLIS
State and Tribal Landfill and/or Solid Waste Disposal Site Lists
State and Tribal Leaking Underground Storage Tanks (LUSTs)
State and Tribal Voluntary Cleanup Sites
State and Tribal Brownfields Sites
Subject Property and Adjacent Properties Only
Federal RCRA Generators List
State and Tribal Registered Storage Tanks
Subject Property Only
Federal ERNS List
Federal Institutional Controls/Engineering Controls Registries
State and Tribal Institutional Controls/Engineering Controls Registries

* A description of these databases and a complete listing of sites identified on the above-referenced databases is provided in the EDR Report.

** As of March 2016, SEMS replaced the CERCLIS database and SEMS-Archive replaced the CERCLIS NFRAP database.

Subject Property

The subject property is identified as Castle Sanitation Corporation and Casalino Interior Demolition located at 213 Meadow Street in the following databases searched by the EDR radius report:

- Casalino Interior Demolition is identified in the NY Spills database for a release reported to the department on 31 March 1994 and assigned NYSDEC Spill No. 9315532. According to the case narrative provided by NYSDEC, a tank truck spilled approximately 5-gallons of diesel onto the concrete and clean up was in progress by Whale Co. at the time of the spill report. No additional information was provided and the spill was administratively closed on 31 March 1994.
- Casalino Interior Demolition is identified in the Solid Waste Facilities/Landfill Sites (SWF/LF) database as an inactive C&D processing facility.
- Recovered Government Archive Landfill database for having previously been classified as a landfill facility between 2004 and 2012.
- Facility Index System (FINDS) database (No. NYR00G305) for non-major National Pollutant Discharge Elimination System (NPDES) non-major and storm water industrial permits and the Environmental Compliance & History (ECHO) database (No. 110070625464) for facility tracking under the Clean Water Act for a minor permit. No violations are currently identified during the most recent compliance period from July-September 2021, although violations were reported for submission of late discharge monitoring reports during the January-March 2021 and April-June 2021 compliance periods.

Surrounding Properties

Based on the large number of database records identified within one mile of the subject property (348), Langan limited the review of surrounding properties to adjacent sites and sites within 1/8-mile from the subject property. It is the environmental professional's opinion that based on the dense development of the site area, and former, current and proposed use of the site that the review of the database pertaining to this more limited area is appropriate.

Langan evaluated the following to determine whether additional environmental records with respect to these facilities, including the orphan sites, should be reviewed:

- Case status (i.e., whether a No Further Action letter has been issued or a case has been closed);

- Type of database and whether the presence of soil or ground water contamination is known;
- Distance of the site from the subject property; and,
- Whether the site is upgradient or downgradient of the subject property based on local topography and the anticipated western groundwater flow direction.

Database	No. of Sites within 1-mile	Adjacent sites (Y/N)	No. of Adjacent Sites
NPL	1	N	--

Database	No. of Sites within 1/2-mile	Adjacent sites (Y/N)	No. of Adjacent Sites
RCRA-TSDF	0	N	--

Database	No. of Sites Reported	Adjacent sites (Y/N)	No. of Adjacent Sites
SEMS	2	N	--
SEMS-ARCHIVE	5	N	--
RCRA-LQG	7	N	--
RCRA-SQG	3	Y	1
RCRA-VSQG	5	Y	1
RCRA NonGen/NLR	37	Y	5
NY MANIFEST	49	Y	8
PA MANIFEST	2	N	--
NJ MANIFEST	13	Y	3
NY SHWS	15	N	--
NY SWF/LF	30	Y	1
NY UST	20	Y	1
NY MOSF UST	4	N	--
NY CBS	3	N	--
NY MOSF	5	N	--
NY AST	17	Y	2
NY CBS AST	2	N	--
NY MOSF AST	4	N	--
NY ENG CONTROLS	3	N	--
NY INST CONTROL	3	N	--
NY VCP	6	N	--
NY BROWNFIELDS	6	N	--
NY SWRCY	12	N	--
ROD	1	N	--
NY HSWDS	7	N	--
FUELS PROGRAM	1	N	--
EDR MGP	3	N	--

Database	No. of Sites within 1/8-mile	No. Cases Open/Closed	Open Upgradient Cases	No of Adjacent Sites
LTANKS	4	0 / 4	0	0
NY Spills	37	0 / 46	0	7

Langan reviewed the information provided using the above criteria and the findings for adjacent and notable records are discussed below.

Newtown Creek

The Newtown Creek Superfund Site is a tidal arm of the New York-New Jersey Harbor Estuary, comprised of five tributaries over approximately 3.8-miles between the northwestern boundary of Brooklyn and the southwestern boundary of Queens. The Creek historically contained more than 50 oil and petrochemical refineries, fertilizer and glue factories, sawmills, lumber yards, and coal yards along its banks. A multi-year Remedial Investigation and Feasibility Study began in February 2010 and is anticipated to be completed in early 2019 according to the USEPA. To date, no decision documents have been issued by the USEPA confirming a proposed remedial action for each of the four Operable Units (OUs) of the Site. The geospatial site location is defined at the English Kills section of Newtown Creek, which is located at the south end of Ivy Hill Road in Brooklyn, New York. It is the opinion of the environmental professional that the potential for adverse environmental impacts to the subject property from this site is low.

210 Varick Avenue

The property located adjacent to the north and hydraulically cross-gradient of the subject property at 210 Varick Avenue is identified as Vijax Corporation in the NY UST database as unregulated/closed Petroleum Bulk Storage (PBS) Facility No. 2-080454 for one 2,750-gallon No. 2 fuel oil UST closed in place on 1 September 2002 and one 4,000-gallon No. 2 fuel oil UST closed in place on 1 October 1981. The site is also identified in the following databases:

- NY Spills database for a release reported to the department on 17 March 2015 and assigned NYSDEC Spill No. 1411768. According to the NYSDEC case narrative provided by EDR, a concrete truck overturned and spilled approximately 15-gallons of diesel onto the street only. FDNY cleaned up the spilled product and placed it into a drum for disposal. The spill was administratively closed on 17 March 2015.

- NY Spills database for a release reported to the department on 20 July 2011 and assigned NYSDEC Spill No. 1205626. According to the NYSDEC case narrative provided by EDR, a spill was discovered during a site investigation at the neighboring property to the west. The investigation found contamination in soil and groundwater associated with a gasoline UST and the property owners of 210 Varick Avenue were requested to perform a site investigation to investigate the source of the spill. The property owner was non-responsive and no investigation was performed; NYSDEC ultimately determined that there was no evidence of a threat to the public or the environment from the contamination found and the spill was administratively closed on 22 September 2015.
- Con Edison is identified in the RCRA NonGen/NLR database for forms received by the USEPA on 15 June 2014 classifying the site as not a generator of hazardous waste. Historical generator information includes forms received by the USEPA on 15 May 2014 classifying the site as a small quantity generator. No violations are reported for the facility. The site is also identified on the NY Manifest database for the disposal of waste impacted with hazardous concentrations of lead in 2018.

Varick Avenue & Meadow Street

Con Edison, located adjacent to the southwest and hydraulically cross-gradient of the subject property at Varick Avenue and Meadow Street was identified in the RCRA NonGen/NLR database for forms received by the USEPA on 6 May 2015 classifying the site as not a generator of hazardous waste. Historical generator information includes forms received by the USEPA on 5 February 2016 and 6 May 2015 classifying the site as a large quantity generator. No violations were reported for the facility. The property was also identified on the NY Manifest database for the disposal of waste impacted with hazardous concentrations of lead in 2015.

Stewart Avenue & Meadow Street

Con Edison, located adjacent to the southeast and hydraulically upgradient of the subject property at Stewart Avenue and Meadow Street was identified in the following databases:

- RCRA NonGen/NLR database for forms received by the USEPA on 26 February 2015 classifying the site as not a generator of hazardous waste. Historical generator information includes forms received by the USEPA on 26 February 2015 classifying the site as a small quantity generator (SQG). No violations were reported for the facility.

- RCRA Very Small Quantity Generator (VSQG) database for forms received by the USEPA on 1 June 2016 classifying the site as a very small quantity generator of hazardous waste. Historical generator information includes forms received by the USEPA on 23 July 2009 and 1 June 2016 classifying the site as a conditionally exempt small quantity generator (CESQG). No violations were reported for the facility.
- NY Manifest database for the disposal of waste impacted with hazardous concentrations of lead in 2009 and 2015.
- NJ Manifest database for the disposal of hazardous waste in 2015.
- The site is also identified as Manhole #57877 and identified in the NY Spills database for a release reported to the department on 21 January 2000 and assigned NYSDEC Spill No. 9912167. According to the case narrative provided by EDR, approximately a half quart of unknown oil was found on 100 gallons of water contained within a manhole and cleanup was pending. The spill was administratively closed on 19 March 2002.
- The site is also identified as Unknown – Drum Run and is identified in the NY Spills database for a release reported to the department on 27 July 2017 and assigned NYSDEC Spill No. 1704150. According to the case narrative provided by EDR, smaller containers of waste oil were overpacked into a 55-gallon drum and was ready for pickup. No additional information was provided and the spill was administratively closed on 1 September 2017.

<u>221-243 Meadow Street</u>

Vault 434, located adjacent to the east and hydraulically upgradient of the subject property at 221 Meadow Street was identified in the NY Spills database for a release reported to the department on 9 October 2002 and assigned NYSDEC Spill No. 0207116. According to the case narrative provided by EDR, dielectric fluid leaked from a transformer and mixed with soil on the concrete floor of the vault. The spill was contained and cleaned up. Asbestos abatement and closure of the transformer occurred, and the transformer was removed from the vault. The spill was administratively closed on 29 March 2003. The site was also identified in the NY Manifest database for the disposal of unspecified hazardous waste.

Vault 434, located at 221-41 Meadow Street, was identified in the NY Spills database for a release reported to the department on 10 January 2008 and assigned NYSDEC Spill No. 0508686. According to the case narrative provided by EDR, approximately one quart of an unknown oil was mixed with leaves on the concrete floor of the vault. The spill was contained and cleaned up. The spill was administratively closed on 10 January 2008.

Con Edison, located at 243 Meadow Street, was identified in the RCRA LQG database for forms received by the USEPA on 7 April 2014 classifying the site as a large quantity generator for the generation of hazardous waste impacted with lead. Historical generator information includes forms received by the USEPA on 29 March 2013 classifying the site as a CESQG and on 29 April 2013 classifying the site as not a generator. No violations were reported for the facility. Additionally, the property is identified in the following databases:

- NY Manifest database for the disposal of unreported hazardous waste.
- NY Spills database for a release reported to the department on 7 September 2006 and assigned NYSDEC Spill No. 0606519. According to the case narrative provided by EDR, dielectric fluid was seen leaking and entering a sewer drain. No additional information was provided and the spill was administratively closed on 7 September 2006.

1250 Metropolitan Avenue

Consolidated Packaging Group, located adjacent to the east and hydraulically up-gradient of the subject property at 1250 Metropolitan Avenue is identified in the following databases:

- RCRA SQG database for forms received by the USEPA on 7 March 2008 classifying the site as a small quantity generator of ignitable waste, and waste impacted with hazardous concentrations of spend halogenated and non-halogenated solvents. Historical generator information includes forms received by the USEPA on 8 March 1990, 21 January 2004, 1 January 2006, 1 January 2007, and 7 March 2008 classifying the site as a small quantity generator, and on 1 January 2001, 19 February 2002, and 16 December 2004 classifying the site as a large quantity generator. Violations were reported for the facility.
- NJ Manifest database for the disposal of hazardous waste in 2004, 2005, 2006, and 2007.
- NY Manifest database for the disposal of waste impacted with hazardous concentrations of spent halogenated solvents and ignitable waste in 2006,
- US Aerometric Information Retrieval System (US AIRS) databases for compliance monitoring.
- FINDS and ECHO databases for being active in the RCRA program.

The subject property is also identified as Aljo Auto Electric Corp and is identified in the RCRA NonGen/NLR database for forms received by the USEPA on 1 January 2007 classifying the site as not a generator of hazardous waste. Historical generator information includes forms received by the USEPA on 8 July 1999 and 1 January 2006 classifying the site as not a generator, and on 11 August 1994 classifying the site as a SQG. No violations were reported for the facility.

221 Varick Street

Waste Management of NY LLC, located adjacent to the west and hydraulically down-gradient of the subject property at 215-221 Varick Avenue, is identified in the following databases:

- NY AST database as active PBS Facility No. 2-605532 for one 2,000-gallon diesel AST closed and removed on 1 January 1990, one in-service 275-gallon waste oil/used oil AST installed on 1 January 1990, one in-service 550-gallon lube oil AST installed on 1 January 1990, and one in-service 550-gallon hydraulic oil AST installed on 15 January 1997.
- NY AST database as unregulated/closed PBS Facility No. 2-602605 for one 2,000-gallon diesel AST converted to non-regulated use, one 275-gallon AST of unreported contents converted to non-regulated use, and one 275-gallon lube oil AST tank converted to non-regulated use.
- RCRA NonGen/NLR database for forms received by the USEPA on 1 January 2007 classifying the site as not a generator of hazardous waste. Historical generator information includes forms received by the USEPA on 1 January 2006 classifying the site as not a generator, on 22 July 2005 classifying the site as a large quantity generator. Violations were reported for the facility but the case is reportedly closed.
- NY Manifest database for the disposal of ignitable waste in 2007.
- SWF/LF database as an active transfer station for yard waste and residential, institutional, and commercial waste.
- NY Financial Assurance for closure of the transfer station in 2004.

NY LTANKS

The NY LTANKS database contains an inventory of reported leaking storage tank incidents from April 1986 to the present. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents identified within this database are either tank test failures, tank failures or tank overfills.

According to the Radius Report provided by EDR, there are four NY LTANKS sites located within 1/8-mile of the subject property; each of the spill cases associated with these sites were administratively closed between 1987 and 2006. There are no NY LTANK sites located adjacent to the subject property. Due to the closed regulatory status of the spill cases, it is the opinion of the environmental professional that the potential for adverse impacts to the subject property from these sites is low.

NY Spills

The NY Spills database includes data collected on spills reported to NYSDEC. It includes spills active as of April 1, 1986, as well as spills occurring since this date. According to the Radius Report provided by EDR, there are 37 NY Spills sites located within 1/8-mile of the subject property; each of the NY Spills cases were administratively closed between 1992 and 2019. There are seven NY Spills sites located adjacent to the subject property and are discussed in detail above. Due to the cleanup activities completed and the closed regulatory status of the spill cases, it is the opinion of the environmental professional that the potential for adverse impacts to the subject property from these sites is low. Two notable closed spills are discussed below.

Manhattan Poly Bag Corp, located approximately 310 feet to the northwest and downgradient of the subject property at 1150 Metropolitan Avenue is identified in the NY Spills database for a release reported to the facility on 22 November 2006 and assigned NYSDEC Spill No. 0609662. According to the case narrative provided by EDR, petroleum odors and staining along with elevated PID readings were identified in eight soil borings during a Phase II Environmental Site Investigation. Elevated VOCs, SVOCs and metals were present in groundwater. A remediation work plan was submitted and sodium persulfate injections were performed. Groundwater sampling was performed after chemical injections and showed decreased levels of VOCs and SVOCs in groundwater and a No Further Action letter was approved for the site. The spill was administratively closed on 28 July 2009.

Metro Garage located approximately 296 feet to the north and cross-gradient of the subject property at 1188 Metropolitan Avenue is identified in the NY Spill database for a release reported to the department on 17 June 2003 and assigned NYSDEC Spill No. 0302832. According to the case narrative provided by EDR, a gas station that was never registered was court ordered to remove tanks onsite. Seven 550-gallon tanks were removed, three 550-gallon tanks were abandoned in place, and four additional tanks were planned to be removed. The soil in the excavation area of these USTs

was heavily contaminated. Delineation was performed and soil and groundwater samples were collected and revealed concentrations of VOCs and SVOCs in upgradient monitoring wells. The exceedances were linked to a potential previously closed UST at the neighboring property. Additional sampling was performed around that closed UST at the neighboring property. VOCs and SVOC results came back well below standards. NYSDEC determined that there was no threat to the public or the environment and the spill was administratively closed on 18 January 2012.

Government Databases Review Conclusions

The subject property is identified in the NY Spills database for a release reported to the department on 31 March 1994 and assigned NYSDEC Spill No. 9315532. According to the case narrative provided by EDR, a tank truck spilled approximately 5-gallons of diesel onto the concrete and clean up was in progress by Whale Co. No additional information was provided and the spill was administratively closed on 31 March 1994. It is of the opinion of the environmental professional that the closed spill represents an HREC.

Based on the review of the City Directory Abstract and the Sanborn Maps (discussed above) and the radius report, historical uses of concern at the subject property included oil truck parking, auto wrecking, and a junk yard between 1960 and 2007 and as a solid waste transfer facility for yard waste and residential, institutional, and commercial waste from at least 2004 through 2012.

As discussed in Section 5.6, Langan completed a Phase II EI in February 2022 to determine if current and historical site operations have impacted subsurface conditions. Soil analytical results revealed the presence of contaminated fill material but the Phase II EI. However, the potential exists that impacts resulting from these uses may be present at the subject property. It is the opinion of the environmental professional that the potential for subsurface impacts as a result of current and historical site use at the subject property represents a business environmental risk.

Based on the review of the City Directory Abstract and the Sanborn Maps (discussed above) and the radius report, historical and current uses of surrounding sites includes a private garage with truck repair, paint room, gasoline tank, wire product manufacturing, an oil/fuel company, metals stamping, and metal products manufacturing between 1951 and 2007, a vinyl plastics company and a chemical products company with manufacturing facilities between 1965 and 2007, gasoline storage between 1933 and 1988, auto

wrecking between 1965 and 1977, an automobile repair facility (1933-1987), filling stations (1933-1968), and an oil terminal (1933-1968).

A Phase II Environmental Investigation (EI) conducted by Langan in February 2022 revealed the presence of fill material impacted with metals and semi-volatile organic compounds (SVOCs), which are typical of urban areas. Groundwater analytical results revealed the presence of elevated concentration of metals and SVOCs, which are consistent with fill impacts observed in soil. Evidence of impacts from surrounding sites were not identified.

Additionally, the potential for vapor intrusion impacts to the subject property from onsite or nearby sources was evaluated. No specific potential vapor intrusion concerns (pVICs) were identified as part of this Phase I ESA or in the soil vapor analytical results from the Phase II EI; however, it should be noted that due to the number of spill sites identified in the area of the subject property and the associated potential for groundwater impacts in the site area, vapor intrusion issues at the site may exist. These conditions are consistent with the urban setting in which the subject property is located and do not present a specific or unique concern for the subject property.

8.0 GOVERNMENT AGENCY RECORDS REVIEW

Federal, state and local agencies were contacted via written correspondence, telephone interviews and/or personnel interviews regarding records of environmental concerns, violations, and/or permits, or any other potentially environmentally-relevant records on the subject property. In additional, government information that was readily available online on government websites was also reviewed. A listing of agencies/individuals contacted by Langan as part of this ESA is provided in Table 1. Copies of government correspondence are provided in Appendix F.

US Environmental Protection Agency (USEPA)

Langan reviewed the online USEPA MyProperty database (https://enviro.epa.gov/facts/myproperty/) and the RCRAInfo Search, ECHO, and the Superfund Enterprise Management System (SEMS) databases maintained online by USEPA. Review of available records verified the radius report listings discussed in Section 7.0.

US Fish and Wildlife Service (US FWS)

Information regarding critical habitats or endangered species with the vicinity of the subject property was obtained from the US FWS Information Service Information for Planning and Conservation online database (https://ecos.fws.gov/ipac/). The federally-listed candidate insect species the monarch butterfly, the federally-listed threatened bird species the piping plover and the red knot, and the flowering plant seabeach amaranth and the federally-listed endangered bird species the roseate tern are known to exist in the vicinity of the subject property.

New York State Department of Environmental Conservation Region 2

The NYSDEC Region 2 office was contacted by Langan on 20 January 2022 and online file review requests were submitted for the subject property. In an email dated 21 January 2022, Langan received a response acknowledging receipt of the request. To date, no response has been received. If any additional pertinent information is provided subsequent to issuance of this report, it will be provided as an addendum. Langan also reviewed the Environmental Site Database records maintained online by the NYSDEC. No storage tanks or remediation sites were identified for the subject property. Spill No. 9315532 was identified for the site and is discussed in detail above.

NYSDEC Division of Fish, Wildlife, & Marine Resources

Langan reviewed records maintained online on the NYSDEC Environmental Resource Mapper (http://www.dec.ny.gov/gis/erm/) which revealed that no state-designated significant natural communities and rare plants and animals are found in the vicinity of the subject property. Based on these results, a written records request was not submitted.

New York State Department of Health (NYSDOH)

The NYSDOH Records Access Officer was contacted by Langan on 20 January 2022 and an online file review requests was submitted for the subject property. In an email dated 21 January 2022, Langan received acknowledgement from the NYSDOH of the records request. To date, no response has been received by Langan regarding this request. If any additional pertinent information is provided subsequent to issuance of this report that will change the conclusions of this report, it will be provided as an addendum.

New York City Department of Environmental Protection (NYCDEP)

On 20 January 2022, the NYCDEP online FOIL request form was submitted for the subject property. In an email dated 20 January 2022, Langan received acknowledgement from the NYCDEP of the records request. In an email dated 26 January 2022, Langan received a response indicating that no records are available for the subject property. If any

additional pertinent information is provided subsequent to issuance of this report that will change the conclusions of this report, it will be provided as an addendum.

According to records maintained online by the NYCDEP Clean Air Tracking System (CATS), no boiler records are documented for the subject property.

New York City Department of Health & Mental Hygiene (NYC DOHMH)

The NYC DOHMH Records Office was contacted by Langan and an online file review request was submitted for the subject property on 20 January 2022. In an email dated 8 February 2022, Langan received acknowledgement from the NYC DOHMH of the records request. In a letter dated 7 February 2022, Langan received a response from the Office of Environmental Investigations stating no records are available for the subject property. If any additional pertinent information is provided subsequent to issuance of this report that will change the conclusions of this report, it will be provided as an addendum.

New York City Department of City Planning (NYC DCP)

An electronic version (effective zoning date 23 November 2021) of the NYC Zoning Map for the subject property was downloaded from the NYC DCP website (http://www.nyc.gov/html/dcp/html/zone/zh_zmaptable.shtml).

New York City Mayor's Office of Environmental Coordination (NYC MOEC)

Records maintained online by NYC MOEC through the CEQR Access Portal (https://a002-ceqraccess.nyc.gov/ceqr/) were reviewed on 20 January 2022. The subject property was not identified as being a part of the CEQR program.

'E'-Designation Status

The New York City Department of City Planning coordinated a program identifying properties for special environmental concerns based on documented historical use, neighborhood noise concerns, and neighborhood air quality issues. These properties are identified on 'E'-designated sites on zoning maps and in the NYC Department of Buildings (NYCDOB) Building Information System (BIS) database. The NYCDOB is restricted from issuing building permits for the property until the NYC Mayor's Office of Environmental Remediation (NYC OER) has reviewed information prepared by an environmental professional and made a determination to issue of "Notice-of-No-Objection" or a "Notice-to-Proceed" to the NYCDOB. Prior to the NYCOER's creation in 2008, the NYC Department of Environmental Protection (NYCDEP) conducted these reviews.

Langan reviewed the following information sources to determine if the subject property is listed as an 'E'-designated property:

- Appendix C: CEQR Environmental Designations List (https://zr.planning.nyc.gov/appendix-c-table-1-city-environmental-quality-review-ceqr-environmental-requirements-e-designations) on 18 February 2022
- Appendix C: CEQR Restrictive Declaration List (https://zr.planning.nyc.gov/appendix-c-table-2-city-environmental-quality-review-ceqr-environmental-requirements-environmental) on 18 February 2022
- NYCOER Environmental Project Information Center (EPIC) (https://a002-epic.nyc.gov/app/search/erdproperty) on 18 February 2022, and,
- NYCDOB BIS on 18 February 2022 (http://a810-bisweb.nyc.gov/bisweb/bispi00.jsp)

The subject property was not listed as an E-designated site based on these resources.

New York City Department of Buildings (NYC DOB)

Langan completed a limited review of available records maintained online by the NYC DOB. The only Certificate of Occupancy available for Lot 45 was dated 22 July 1993 and revealed that the lot is approved for a junk and salvage yard and parking. This corresponds to a permits approved in 1993 to change the use of the lot for vacant to junk and salvage yard and to erect temporary structures and install three 275-gallon motor oil tanks for this use. A demolition permit was issued for the lot in 1911. The only Certificate of Occupancy available for Lot 1 was dated 11 December 1956 and revealed that the lot is approved for a junk yard, metal and car wrecking, and a temporary shed. No information was available for Lot 5.

New York City Department of Finance (NYC DOF)

Langan completed a limited review of available records maintained online by the NYC DOF to determine current and former site ownership (https://a836-acris.nyc.gov/CP/). According to the DOF Automated City Register Information System (ACRIS), Lot 45 is currently owned by Meadow St. Rlty Corp, and Lot 1 and 5 are currently owned by 190 Varick Ave Realty Cp. Ownership history was available from 1969 to present. The ownership information reviewed provided no additional information regarding environmental conditions related to past usage different than represented by review of other historical information sources.

9.0 SITE RECONNAISSANCE

Langan conducted an inspection of the site on 25 January 2022. The inspection included a walk-through inspection of the entire site for the purposes of identifying Recognized Environmental Conditions (RECs). Typical RECs may include:

Drum storage	Dumpsters	Aboveground storage tanks	Stained areas
Drains and Sumps	Wells	Underground storage tanks	Pump stations
Waste piles	Landfills	Loading and transfer areas	Boiler rooms
Pits, Ponds, Lagoons	Swales	Process air vents	Process sinks
Storm sewers	Trenches	Detention ponds	PCBs
Impoundments	Lagoons	Floor drains and piping	Transformers
Septic systems	Dry wells	Waste treatment areas	Capacitors
Rail spurs	Incinerators	Compressor discharges	Odors
Pools of liquid	Wastewater	Stressed vegetation	Surface waters

Limiting conditions encountered during the inspection of the site included the following:

- Portions of ground surface in each lot could not be observed due to truck parking and equipment storage.

Photographs of the subject property taken during the site inspection are provided in Appendix G. Langan was accompanied by a representative from Castle Demolition who provided access to onsite buildings and answered questions during the site inspection. A questionnaire was not completed by the property owner, operator, and site manager; a blank copy is included as Appendix B. The inspection included a walk-through inspection of the entire site for the purposes of identifying Recognized Environmental Conditions (RECs) as detailed below.

The southeast and southern portions of the subject property is occupied by Castle Demolition Corporation (Lot 45), the southwestern portion of the subject property is leased and used as food truck parking and contains a storage container used as an office (Lot 1), and the northwestern portion of the site is leased and used as scaffolding storage and contains several storage containers used as an office and storage (Lot 5). Lot 45 is separated by fencing into two parcels for Castle Demolition Corporation's operations. One area is used as truck storage and the other area is used as the truck repair area. The truck repair area contains a one-story shed along with several other storage containers and structures providing roofs over supplies and materials. All lots are separated by fencing and are only accessible from the street.

An out-of-service fuel oil AST is present in the south-central area of Lot 45 under a partial shed, and three 275-gallon ASTs, consisting of one waste oil, one motor oil, and one hydraulic oil AST are present in the northeastern portion in the truck repair area of Lot 45. Additionally located in the truck repair area is a one-story storage shed in the north-central portion of Lot 45 and contained approximately 14 55-gallons drum containing degreasers, motor oil, and hydraulic oil. The drums were staged on secondary containment pallets. Additional quart and gallon-sized containers containing a variety of degreasers and motor oil were also observed in the storage shed. Speedy dry and stained concrete were observed throughout the truck repair area in the southeastern lot. Several suspected drains and open-hole sumps were observed under metal plates throughout the subject property. At the time of the site inspection, the representative onsite from Castle Demolition could not confirm the purpose of the drains and open-hole sumps.

Adjacent Properties

A visual inspection of adjoining properties from the subject property line and public rights-of-way including a visual inspection where hazardous substances may be or may have been stored, treated, handled, or disposed was also conducted.

Limiting conditions encountered during the inspection of adjoining properties were encountered due to the dense urban nature of the surrounding areas which only allowed for limited line of sight that did not extend to areas where hazardous materials or substances might be stored.

Properties located adjacent to the subject property consist of warehouses, truck parking and staging, and a Waste Management facility. No other visual evidence of hazardous material storage, treatment, handling, or disposal areas was observed at adjacent properties.

10.0 ADDITIONAL ISSUES

The following items fall outside the scope of ASTM 1527-13, however Langan can and often does provide these services to its clients if specifically requested and included in the proposed scope of work or are issues that may impact current or proposed site use.

10.1 Wetlands/Floodplain Designation

Langan reviewed the United States Fish and Wildlife National Wetland Inventory (NWI) and New York State Freshwater Wetlands maps. Based on these documents no mapped wetlands are listed on the subject property. No evidence of the presence of existing onsite wetlands was identified during Langan's site inspection. However, a formal wetland and floodplain designation assessment was not conducted as part of this ESA.

10.2 Protected Endangered Species / Critical Habitats

A determination regarding the potential presence of protected or endangered species and critical habitats on or near the subject property was not conducted as part of this ESA. This determination is often required in order to receive state or federal grants, loans, and/or permits.

Based on historic use of the subject property and the current condition and urban setting of the site, the potential presence of threatened or endangered (T&E) species on the site is low. A request for information regarding T&E species on the site was provided to New York State Division of Fish, Wildlife and Marine Resources (NYSDFWMR) and to the United States Fish and Wildlife Service (USFWS). This correspondence is discussed in detail in Section 8.0.

10.3 Asbestos

In 1973, use of sprayed on fireproofing on structural building components was prohibited by the EPA. On July 12, 1989, EPA issued a final rule banning most friable asbestos-containing products. The following specific asbestos-containing products remain banned: flooring felt, roll board, and corrugated, commercial, or specialty paper. In addition, the regulation continues to ban the use of asbestos in products that have not historically contained asbestos, otherwise referred to as "new uses" of asbestos. Use of asbestos in textured paint and in patching compounds used on wall and ceiling joints was banned in 1977.

An asbestos survey was not conducted as part of this ESA as there are no permanent structures present at the subject property.

10.4 Lead-based Paint

In 1977, the Consumer Product Safety Commission (CPSC) banned the use of lead based paint (LBP) in housing and restricted maximum levels in lead in new residential paint to less than 0.05% by weight. A lead-based paint inspection was not conducted as part of this ESA as there are no permanent structures present at the subject property.

10.5 Lead in Drinking Water

A lead in drinking water survey was not conducted as part of this ESA.

10.6 Indoor Air / Microbial Assessment (Mold)

A mold survey was not conducted as part of this ESA.

10.7 Radon

The subject property is located in a Tier 3 Zone as identified by USEPA based on sampling conducted of buildings within the site area. The Tier 3 Zone is considered an area of low radon gas intrusion potential with typically concentrations less than 2 pCi/liter. A radon survey of the existing building was not conducted as part of this ESA. Radon test results from adjacent or surrounding properties are not necessarily indicative of radon conditions on the subject property. As no building specific radon survey documentation was provided to Langan, no opinion regarding potential risks associated with radon gas exposure can be made.

As per USEPA guidelines, the only way to assess potential radon gas exposure risks is to conduct a radon assessment. In addition, the US EPA recommends that follow-up tests on large buildings should be conducted when major modifications are made either to the building structure or HVAC system or the HVAC system's operation settings.

10.8 Historical and Archaeological Review

Langan reviewed the NYCityMap (http://maps.nyc.gov/doitt/nycitymap/) to review the potential presence of historical landmark buildings near the subject property. As of 18 February 2022, no historical landmark buildings were identified on or near the property.

In addition, Langan reviewed the New York City Landmarks Preservation Commission (NYCLPC) online historic maps (https://nyclpc.maps.arcgis.com/apps/webappviewer/index.html?id=93a88691cace4067828b1eede432022b). As of 18 February 2022, no Historic Districts or Landmarks were identified on the subject property.

Langan also reviewed the NYSHPO online database (http://nysparks.com/shpo/online-tools/). As of 18 February 2022, no National Register Listed or State Register Listed sites were identified on or adjacent to the subject property.

11.0 DEVIATIONS

This Phase I ESA conforms with ASTM with the following deviations noted:

- Data gaps in excess of 5 years were encountered during the review of historic resources;
- Government agencies that have not responded to record review inquiries are listed above - additional pertinent information provided to Langan subsequent to the issuance of this report will be provided in an addendum;
- Limited visual access was provided as part of this ESA due to vehicles parked across the subject property as identified in Section 9.0;
- Based on the large number of database records identified within one mile of the subject property (348), Langan limited the review of surrounding properties to adjacent sites and sites within 1/8-mile from the subject property;
- Interviews of former business operators were not conducted;
- Interviews of property owners were not conducted;
- Questionnaires were not completed by the property owner, operator, or site manager; and,
- A FOIL request was not submitted to the New York City Fire Department (FDNY) as response times do not meet ASTM's Reasonable Time and Cost requirements.

It is the opinion of the reviewing Environmental Professional that the above deficiencies will not detrimentally affect the identification of potential recognized environmental conditions. This opinion is based on the following factors:

- Based on the Sanborn Maps and the City Directory information reviewed, the use of the property is consistent between the 5-year data gaps. Therefore, operations on the site between these data gaps will not detrimentally affect the identification potential RECs.
- Langan limited the database review to adjacent sites and sites within 1/8-mile from the subject property. It is the environmental professional's opinion that based on the dense development of the site area, and former, current and proposed use of the site that the review of the database pertaining to this more limited area is appropriate and will not detrimentally affect the identification of potential recognized environmental conditions.

12.0 FINDINGS/OPINIONS

Based on information obtained during the visual inspection of the subject property, review of environmental databases and historic information, and contact with federal/state/local official agencies, the following recognized environmental conditions (RECs), historic recognized environmental conditions (HRECs), de minimis conditions and business environmental risks that may impact proposed redevelopment of the site were identified:

1. Presence of contaminated urban fill;
2. Spill Case #9315532;
3. Motor Oil Release;
4. Current and historic site operation; and,
5. Potential presence of undocumented USTs.

Contaminated fill material impacted with metals and SVOCs at concentrations exceeding the NYSDEC Commercial RUSCOs, Industrial RUSCOs, and/or Protection of Groundwater SCOs was identified at the subject property during the Phase II EI. Finding 1 represents a REC. The subject property is identified in the NY Spills database for a release reported to the department on 31 March 1994 and assigned NYSDEC Spill No. 9315532. The spill was administratively closed on 31 March 1994, therefore Finding 2 represents a HREC. Evidence of a release of oil limited to small, isolated areas on the concrete in the southeastern lot of the subject property was observed during Langan's site inspection. It is the opinion of the environmental professional that Finding 3 represents a de minimis

condition. Historical site use consisted of oil truck parking, auto wrecking, and a junk yard between 1965 and 2007 and a solid waste transfer facility between 2004 and 2012. Current site use includes vehicle storage and repairs including three in-service 275-gallon ASTs and one out-of-service AST. Although odors and elevated PID readings were detected in fill during the investigation, the Phase II EI did not identify specific impacts associated with historical site use. It is the opinion of the environmental professional that Finding 4 represents a BER. It is the opinion of the environmental professional that undocumented USTs may be present beneath the site or sidewalk adjacent to the site. Therefore, Finding 5 represents a business environmental risk.

13.0 CONCLUSIONS

Langan has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E1527-13 of a ±56,200 square foot site located at 213 Meadow Street, Brooklyn, Kings County, New York, the subject property. Any exceptions to, or deletions from, this practice are described in Section 11.0 of this report.

Based on information obtained during the visual inspection of the subject property, review of environmental databases and historic information, and contact with federal/state/local official agencies, this assessment has revealed the following recognized environmental conditions (RECs) in connection with the property:

Recognized Environmental Conditions

It is the opinion of the environmental professional that the following represent RECs:

Presence of Contaminated Urban Fill

Based on the findings of the 2022 Phase II EI, contaminated fill impacted with elevated concentrations of metals and SVOCs above the NYSDEC Soil Cleanup Objectives is present in the subsurface at the subject property. Odors and elevated PID readings were also detected, suggesting contamination may be present that was not found during the initial Phase II EI or that weathered petroleum contamination and nuisance soil conditions are present. The presence of fill material will require implementation of soil handling and management procedures to address excavation, reuse, handling, and possible offsite disposal of this material during site redevelopment. The presence of contaminated fill represents a REC.

14.0 QUALIFICATIONS / CERTIFICATION

The following professionals assisted in the completion of this report.

We, the undersigned, declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in §312.10 of 40 CFR 312 and we have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property as documented in Appendix H. We have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Site Inspection Completed By:



Molly Mattern
Senior Staff Scientist

Report Written By:



Amanda Forsburg, CHMM
Senior Project Scientist

Report Reviewed By:



Steven Ciambruschini, P.G., L.E.P.
Senior Principal / Senior Vice President

\\langan.com\data\PAR\data2\100964202\Project Data_Discipline\Environmental\Reports\2022-03 - Phase I ESA\213 Meadow Street Phase I ESA (FINAL 2022-03-11).docx

TABLES

TABLE 1
TABLE OF CONTACTS

Federal

United States Environmental Protection Agency
Region 2 (NJ, NY, PR, VI)
https://foiaonline.regulations.gov/foia/action/public/home

United States Fish and Wildlife Service
https://ecos.fws.gov/ipac/gettingStarted/map

State

New York State Department of Environmental Conservation – Region II
http://www.dec.ny.gov/public/103696.html

Records Access Office
New York State Department of Health
Corning Tower, Room 2364
Albany, New York 12237-0044
foil@health.ny.gov

The New York Natural Heritage Program
http://www.dec.ny.gov/gis/erm/
http://nynhp.org/ProjectScreening

City

New York City Mayor's Office of Environmental Coordination
http://www.nyc.gov/html/oec/html/ceqr/ceqr_access.shtml

New York City Department of Environmental Protection
http://www.nyc.gov/html/dep/html/contact_us/foil.shtml

Ms. Renee Bryant, Records Access Officer
New York City Department of Health and Mental Hygiene
Gotham Center
42-09 28th Street, 14th Floor, CN31
Long Island City, NY 11101
recordsaccess@health.nyc.gov

Ms. Leslie Ifill
Fire Department of New York City
FDNY Bureau of Legal Affairs
Public Records Unit
9 MetroTech Center, 4th Floor
Brooklyn, NY 11201

FIGURES



Notes:
1. World topographic basemap is provided through Langan's Esri ArcGIS software licensing and ArcGIS online.
2. Parcel data provided by NYC MapPLUTO 21v1.

LANGAN
300 Kimball Drive
Parsippany, NJ 07054
T: 973.560.4900 F: 973.560.4901 www.langan.com

Langan Engineering & Environmental Services, Inc.
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.
Langan International LLC
Collectively known as Langan

NJ CERTIFICATE OF AUTHORIZATION No. 24GA27996400

Project	213 MEADOW STREET BROOKLYN NEW YORK
Drawing Title	SITE LOCATION MAP
Project No.	100964201
Date	2/22/2022
Scale	1" = 2,000'
Drawn By	IHB
Last Revised	
Figure	1

© 2017 Langan

Path: \\langan.com\data\PAR\data2\100964201\Project Data\ArcGIS\MXD\Environmental_Figures\Figure 1 - Site Location Map.mxd



LANGAN
300 Kimball Drive
Parsippany, NJ 07054
T: 973.560.4900 F: 973.560.4901 www.langan.com
Langan Engineering & Environmental Services, Inc.
Langan Engineering, Environmental, Surveying and Landscape Architecture, D.P.C.
Langan International LLC
Collectively known as Langan
NJ CERTIFICATE OF AUTHORIZATION No. 24GA27996400

Project	213 MEADOW STREET BROOKLYN NEW YORK
Drawing Title	TAX MAP
Project No.	100964201
Date	3/1/2022
Scale	1" = 100'
Drawn By	IHB
Last Revised	
Figure	2

© 2017 Langan

Path: \\langan.com\data\PAR\data2\100964201\Project Data\ArcGIS\MXD\Environmental_Figures\10.5\Figure 2 - Tax Map.mxd


MX-8
R6B
R6A
R7-2*
M1-2/R6A
M1-2/R6
R6
R7A
R6B
M1-1
M1-2
R6A
C4-4A
C8-2
C4-4
C4-3
C4-4L
EC-4
R7D
R7-1
R6
M1-3
M3-1
M1-4/R7A
MX-4
M1-2
R7A
R6A
R6B
R7-2
R7A
M1-1
R7D
R6
R6B
R6A
R7A
R6B
R6A
R6B
R6A
R6B
R6

APPENDIX A

USER QUESTIONNAIRE

LANGAN

ASTM PRACTICE E 1527-13: USER/CLIENT QUESTIONNAIRE

Please complete the below form and return to
Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.

Providing the following information (if available) to the environmental professional (Langan) is one of the requirements to qualify for one of the *Landowner Liability Protections* offered under CERCLA. Missing or incomplete information could result in a determination that "all appropriate inquiry" is not complete.

General Information

User/Client Name (s): GO Quay LLC

Property Name: 213 Meadow Street, Brooklyn, NY

Address: 213 Meadow Street, Brooklyn, NY

Block 2591; Lot 1, 5, and 45

Property Type: Storage Facility

Type of Property Transaction:

- Purchase of property ☐
- Financing of property ☐
- Sale of property ☐
- Ground Lease ☐
- Build to Suit Lease ☐
- Other Development for purposes of conveyance of new facility / ground lease

Reason Why Phase I ESA is required: Due diligence

Site Contact (s): Daniel Colasuonno

Required Information

The citation at the end of each item (e.g. 40 CFR 312.XX) is the section of EPA's November 1, 2005 AAI Final Rule which discusses that item.

	Yes	No
(1.) Environmental cleanup liens that are filed or recorded against the site (40 CFR 312.25). Did a search of recorded land title records (or judicial records where appropriate) identify any environmental liens filed or recorded against the property under federal, tribal, state or local law?	☐	☒
(2.) Activity and Land Use (AUL) limitations that are in place on the site or that have been filed or recorded in a registry (40 CFR 312.26). Did a search of recorded land title records (or judicial records where appropriate) identify any AULs, such as engineering controls, land use restrictions or institutional controls that are in place at the property and/or have been filed or recorded against the property under federal, tribal, state or local law?	☐	☒

LANGAN

	Yes	No
(3.) Specialized knowledge or experience of the person seeking to qualify for LLP (40 CFR 312.28).		
Do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?	☐	☒
(4.) Relationship of the purchase price to the fair market value of the property if it were not contaminated (40 CFR 312.29).	**Yes**	**No**
(a.) Does the purchase price being paid for this property reasonably reflect the fair market value of the property? [If no, proceed to Parts 4a and 4b.]	☒	☐
(b.) If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?	☐	☐
(c.) Identify an explanation for the lower price and provide a written record of such explanation as an attachment.		
(5.) Commonly known or reasonably known or reasonably ascertainable information about the property (40 CFR 312.30).	**Yes**	**No**
Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example,	☐	☒
(a.) Do you know the past uses of the property?	☐	☐
(b.) Do you know of specific chemicals that are present or once were present at the property?	☐	☐
(c.) Do you know of spills or other chemical releases that have taken place at the property?	☐	☐
(d.) Do you know of any environmental cleanups that have taken place at the property?	☐	☐
(6.) The degree of obviousness of the presence or likely presence of contamination at the property, and the ability to detect the contamination by appropriate Investigation (40 CFR 312.31).	**Yes**	**No**
Based on your knowledge and experience related to the property are there any obvious indicators that point to the presence or likely presence of releases at the property?	☐	☒

SIGNATURE:

It is understood that the information presented in this form is an integral part of the Phase I ESA process and that Langan will evaluate and rely on this information in the development of the final Phase I ESA report.

Completed By: Simeon Maleh

Print/Type Name: Simeon Maleh

Title: Executive Vice President, Development

Company: Gotham Organization

Date: 3/4/2022

APPENDIX B

PROPERTY OWNER / OPERATOR / KEY SITE MANAGER QUESTIONNAIRE

LANGAN

ASTM PRACTICE E 1527-13:
OWNER/OPERATOR/SITE-MANAGER QUESTIONNAIRE

Please complete the below form and return to
Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.

Project Location/Address: _____

_____

_____

ASTM E-1527-13, Section 9.4

Are you aware of any of the following located on the subject property:

Pits, Ponds, or Lagoons?	**Yes** ☐ **No** ☐
Stained Soil or Pavement?	**Yes** ☐ **No** ☐
Stressed Vegetation?	**Yes** ☐ **No** ☐
Solid Waste (including trash, construction debris, or demolition debris)?	**Yes** ☐ **No** ☐
Wastewater or Discharges into Drains, Ditches, Underground Injection System, or Stream?	**Yes** ☐ **No** ☐
Wells (including dry wells, irrigation wells, injection wells, abandoned wells, or other wells)?	**Yes** ☐ **No** ☐
Septic Systems or Cesspools?	**Yes** ☐ **No** ☐

ASTM E-1527-13, Section 10.9

Do you know of any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the property?	**Yes** ☐ **No** ☐
Do you know of any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on, or from the property?	**Yes** ☐ **No** ☐
Do you know of any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products?	**Yes** ☐ **No** ☐

ASTM E-1527-13, Section 10.8

Are you aware if any of the documents listed below exists and if so, whether copies can and will be provided to the Consultant performing the ESA?

	Unaware	Document Exists	Copy will be provided
Environmental site assessment reports	☐	☐	☐
Environmental compliance audit reports	☐	☐	☐
Environmental permits (such as solid waste disposal permits, hazardous waste disposal permits, NPDES permits, wastewater permits, underground injection permits)	☐	☐	☐
Registrations for underground and aboveground storage tanks	☐	☐	☐
Material safety data sheets	☐	☐	☐
Community-right-to-know plan	☐	☐	☐
Safety plans; preparedness and prevention plans; spill prevention, countermeasure and control plans, facility response plan, etc.	☐	☐	☐
Reports regarding hydrogeologic conditions on the property or surrounding area	☐	☐	☐
Notices or other correspondence from any governmental agency relating to past or current violations of environmental laws with respect to the property or relating to environmental liens encumbering the property	☐	☐	☐
Hazardous waste generator notices or reports	☐	☐	☐
Geotechnical studies	☐	☐	☐
Risk Assessments	☐	☐	☐
Recorded Activity and Use Limitations	☐	☐	☐
Environmental Cleanup Reports	☐	☐	☐

Do you have contact information for the prior owner of the property? **Yes** ☐ **No** ☐
If yes, please provide information below:

Prior Owner's Name _____

Contact person _____

Address _____

_____

Telephone _____

Do you have contact information for the prior occupant of the property? **Yes** ☐ **No** ☐
If yes, please provide information below:

Prior Occupant's Name _____

Contact person _____

Address _____

_____

Telephone _____

Do you have information on the prior facility manager of the property? **Yes** ☐ **No** ☐
If yes, please provide information below:

Prior Facility Manager's Name _____

Contact person _____

Address _____

_____

Telephone _____

This form was completed by:

Property Owner ☐ Operator ☐ Key Site Manager ☐ User ☐ EP ☐

Name: _____

Address: _____

_____

Signature: _____ Date: _____

APPENDIX C

SANBORN MAPS

213 Meadow Street

213 Meadow Street

Brooklyn, NY 11237

Inquiry Number: 6826547.3

January 20, 2022

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

01/20/22

Site Name:

213 Meadow Street
213 Meadow Street
Brooklyn, NY 11237
EDR Inquiry # 6826547.3

Client Name:

Langan Engineering
300 Kimball Drive, 4th Floor
Parsippany, NJ 07054-2172
Contact: Molly Mattern

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Langan Engineering were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 54F1-4ED2-B780

PO # NA

Project 213 Meadow Street

Maps Provided:

2007	1994	1986	1951
2006	1993	1982	1933
2005	1992	1981	1907
2004	1991	1980	1888
2003	1990	1979	
2002	1989	1977	
2001	1988	1968	
1995	1987	1965	

Sanborn® Library search results

Certification #: 54F1-4ED2-B780

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Langan Engineering (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2007 Source Sheets

Volume 9, Sheet 60
2007

Volume 9, Sheet 58
2007

2006 Source Sheets

Volume 9, Sheet 58
2006

Volume 9, Sheet 60
2006

2005 Source Sheets

Volume 9, Sheet 58
2005

Volume 9, Sheet 60
2005

2004 Source Sheets

Volume 9, Sheet 58
2004

Volume 9, Sheet 60
2004

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2003 Source Sheets

Volume 9, Sheet 58
2003

Volume 9, Sheet 60
2003

2002 Source Sheets

Volume 9, Sheet 58
2002



Volume 9, Sheet 60
2002

2001 Source Sheets

Volume 9, Sheet 58
2001

Volume 9, Sheet 60
2001

1995 Source Sheets

Volume 9, Sheet 58
1995

Volume 9, Sheet 60
1995

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1994 Source Sheets

Volume 9, Sheet 58
1994

Volume 9, Sheet 60
1994

1993 Source Sheets

Volume 9, Sheet 58
1993-Jan

Volume 9, Sheet 60
1993-Jan

Volume 9, Sheet 60
1993-Dec

Volume 9, Sheet 58
1993-Dec

1992 Source Sheets

Volume 9, Sheet 58
1992



Volume 9, Sheet 60
1992

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1991 Source Sheets

Volume 9, Sheet 58
1991

Volume 9, Sheet 60
1991

1990 Source Sheets

Volume 9, Sheet 58
1990

Volume 9, Sheet 60
1990

1989 Source Sheets

Volume 9, Sheet 58
1989

Volume 9, Sheet 60
1989

1988 Source Sheets



Volume 9, Sheet 58
1988



Volume 9, Sheet 60
1988

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1987 Source Sheets

Volume 9, Sheet 58
1987



Volume 9, Sheet 60
1987

1986 Source Sheets



Volume 9, Sheet 58
1986



Volume 9, Sheet 60
1986

1982 Source Sheets



Volume 9, Sheet 60
1982

Volume 9, Sheet 58
1982

1981 Source Sheets

Volume 9, Sheet 58
1981

Volume 9, Sheet 60
1981

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1980 Source Sheets



Volume 9, Sheet 60
1980

Volume 9, Sheet 58
1980

1979 Source Sheets

Volume 9, Sheet 58
1979



Volume 9, Sheet 60
1979

1977 Source Sheets

Volume 9, Sheet 58
1977

Volume 9, Sheet 60
1977

1968 Source Sheets



Volume 9, Sheet 58
1968



Volume 9, Sheet 60
1968

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1965 Source Sheets

Volume 9, Sheet 58
1965



Volume 9, Sheet 60
1965

1951 Source Sheets

Volume 9, Sheet 58
1951



Volume 9, Sheet 60
1951

1933 Source Sheets



Volume 9, Sheet 58
1933

Volume 9, Sheet 60
1933



Volume 9, Sheet 61
1933

1907 Source Sheets



Volume 9, Sheet 79
1907



Volume 9, Sheet 80
1907

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1888 Source Sheets

Volume 9, Sheet 243
1888

Volume 9, Sheet 244
1888



Volume 9, Sheet 246
1888



Volume 9, Sheet 247
1888

Certified Sanborn® Map

2007



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	2007

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 9, Sheet 58
Volume 9, Sheet 60

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	2006

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	2005

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #	54F1-4ED2-B780
Copyright	2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	2001

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N

Certified Sanborn® Map

1994



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1994

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 58
Volume 9, Sheet 60
Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: 213 Meadow Street
Address: 213 Meadow Street
City, ST, ZIP: Brooklyn, NY 11237
Client: Langan Engineering
EDR Inquiry: 6826547.3
Order Date: 01/20/2022
Certification #: 54F1-4ED2-B780
Copyright 1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1991

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 9, Sheet 60
Volume 9, Sheet 58

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #54F1-4ED2-B780

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1990

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1989

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #54F1-4ED2-B780

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #	54F1-4ED2-B780
Copyright	1988

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #	54F1-4ED2-B780
Copyright	1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 9, Sheet 60
Volume 9, Sheet 58

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #54F1-4ED2-B780

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1986

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1982

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 58
Volume 9, Sheet 60

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1981

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1980

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 58
Volume 9, Sheet 60

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #54F1-4ED2-B780

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1979

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1977

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N

Certified Sanborn® Map

1968



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #54F1-4ED2-B780

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1968

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1965

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N

Certified Sanborn® Map

1951



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1951

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #	54F1-4ED2-B780
Copyright	1933

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 61
Volume 9, Sheet 60
Volume 9, Sheet 58

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #54F1-4ED2-B780

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #:	54F1-4ED2-B780
Copyright	1907

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 9, Sheet 80
Volume 9, Sheet 79

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	213 Meadow Street
Address:	213 Meadow Street
City, ST, ZIP:	Brooklyn, NY 11237
Client:	Langan Engineering
EDR Inquiry:	6826547.3
Order Date:	01/20/2022
Certification #	54F1-4ED2-B780
Copyright	1888

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 9, Sheet 247
Volume 9, Sheet 246
Volume 9, Sheet 244
Volume 9, Sheet 243

0 Feet 150 300 600

N

APPENDIX D

CITY DIRECTORY SEARCH

213 Meadow Street
213 Meadow Street
Brooklyn, NY 11237

Inquiry Number: 6826547.5
January 25, 2022

The EDR-City Directory Abstract

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1928 through 2017. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 200 feet of the target property.

A summary of the information obtained is provided in the text of this report.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

Data by
infoUSA®
Copyright©2008
All Rights Reserved

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	Source	TP	Adjoining	Text Abstract	Source Image
2017	Cole Information Services	-	X	X	-
2014	Cole Information Services	-	X	X	-
2009	Cole Information Services	-	X	X	-
2005	Hill-Donnelly Corporation	-	X	X	-
2004	Cole Information Services	-	X	X	-
2000	Cole Information Services	-	X	X	-
1999	Cole Information Services	-	X	X	-
1997	NYNEX	-	X	X	-
1994	Cole Information Services	-	X	X	-
1992	NYNEX Informantion Resource Co.	-	X	X	-

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1985	NYNEX Information Resources Company	-	X	X	-
1980	New York Telephone	-	-	-	-
1976	New York Telephone	-	X	X	-
1973	New York Telephone	-	X	X	-
1970	New York Telephone	-	X	X	-
1965	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1960	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
	New York Telephone Company	-	X	X	-
	New York Telephone Company	X	X	X	-
1949	New York Telephone Company	-	X	X	-
1945	New York Telephone	-	X	X	-
1940	New York Telephone	-	-	-	-
1934	R. L. Polk & Co.	-	-	-	-
1928	New York Telephone	-	-	-	-

EXECUTIVE SUMMARY

SELECTED ADDRESSES

The following addresses were selected by the client, for EDR to research. An "X" indicates where information was identified.

Address	*Type*	*Findings*
227 Stewart Avenue	Client Entered	
210 Varick Avenue	Client Entered	X
221 Varick Avenue	Client Entered	X
204 Meadow Street	Client Entered	
200 Meadow Street	Client Entered	
188 Meadow Street	Client Entered	
194 Meadow Street	Client Entered	
190 Varick Avenue	Client Entered	X
208 Varick Avenue	Client Entered	

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

213 Meadow Street
Brooklyn, NY 11237

FINDINGS DETAIL

Target Property research detail.

Varick Avenue

190 Varick Avenue

Year	*Uses*	*Source*
1965	South Shore Wrecking Corp	New York Telephone
1960	DEMOLITION & SALVAGE CO INC	New York Telephone
	Demolition & Salvage Co Inc	New York Telephone Company
	GENL WRECKING CORP	New York Telephone Company

208 Varick Avenue

Year	*Uses*	*Source*

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

MEADOW ST

192 MEADOW ST

Year	Uses	Source
2004	ERIC WEIL	Cole Information Services

STEWART AVE

200 STEWART AVE

Year	Uses	Source
2017	GUAN S MUSHROOM	Cole Information Services
2014	KORYEO INTERNATIONAL CORPORATION	Cole Information Services
2009	KORYEO INTERNATIONAL CORP	Cole Information Services
	LUCKY DELIGHT	Cole Information Services
2004	OCCUPANT UNKNOWN	Cole Information Services
	KORYEO INTL	Cole Information Services
	MAINSTREAM CONSULTING INC	Cole Information Services
1999	KORYEO INTERNATIONAL CORPORATION	Cole Information Services
1994	KORYEO INTERNATIONAL CORP	Cole Information Services

218 STEWART AVE

Year	Uses	Source
2014	S SANDS	Cole Information Services

220 STEWART AVE

Year	Uses	Source
2017	ACCURATE CUSTOM ENTRANCE CORP	Cole Information Services
2014	ACCURATE CUSTOM ENTRANCE CORPORATION	Cole Information Services
2009	ACCURATE CUSTOM ENTRANCES INC	Cole Information Services
2005	Accurate Custom Entrance Corp	Hill-Donnelly Corporation
	Beechwood Mountain 2 o	Hill-Donnelly Corporation
2004	BEECHWOOD MOUNTAIN LLC	Cole Information Services

FINDINGS

Year	Uses	Source
2004	JOSEPH RUBIN	Cole Information Services
2000	WALDON MIR WORKS	Cole Information Services
	EURO SALES & MKTG	Cole Information Services
1999	GOLD STAR SEATING	Cole Information Services
	ARKWIN HOME PRODUCTS	Cole Information Services
	WALDON MIRROR WORKS INCORPORATED	Cole Information Services
1997	Waldon Mirror Works Inc	NYNEX
1994	WALDON MIRROR WORKS INC	Cole Information Services
1992	GOOD WORLD TRADING N Y	NYNEX Informantion Resource Co.
1985	KALFLEX DIVISION OF KALEX CHEMICAL PRODUCTS INC	NYNEX Information Resources Company
	KALEX CHEMICAL PRODUCTS INC ELM COATED FABRICS DIV KALFLEX DIVISION	NYNEX Information Resources Company
	ELM COATED FABRICS DIV OF KALEX CHEMICAL PRODUCTS INC	NYNEX Information Resources Company
1976	GRACE W R & CO	New York Telephone
1973	Elm Coated Fabrics Div	New York Telephone
	Grace W R & Co	New York Telephone
1970	Elm Coated Fabrics Div of W R Grace & Co	New York Telephone
	GRACE W R & CO	New York Telephone
	Elm Coated Fabrics Div	New York Telephone
	Resiloid Corp	New York Telephone
1965	GRACE W R & CO	New York Telephone
	Elm Coated Fabrics Div	New York Telephone
	Resitoid Corp	New York Telephone
	Resitoid Cor P	New York Telephone
1960	Resiloid Corn	New York Telephone Company
	ELM COATED FABRBCS CO INC OFFICE & FACTORY	New York Telephone
	RESILOID CORN	New York Telephone
	ELM COATED FABRBCS CO INC Office & factory	New York Telephone Company
1949	Resiloid Corp	New York Telephone Company

FINDINGS

STEWERT AVE

220 STEWERT AVE

Year	Uses	Source
1976	ELM COATED FABRICS DIV OF W R GRACE & CO MFG OFCS & PLANT	New York Telephone

VARICK AVE

210 VARICK AVE

Year	Uses	Source
2017	NY LIVESTOCK MARKET INC	Cole Information Services
2014	NY LIVESTOCK MARKET INCORPORATED	Cole Information Services
2004	MEAGHAN MULHOLLAND	Cole Information Services
1994	STANCO UTILITIES	Cole Information Services
	HY-ATOMIC OIL CO	Cole Information Services
	VIJAX FUEL CORP	Cole Information Services
	HANNEY FUEL OIL CO	Cole Information Services
	MACDAVE OIL BURNER CO INC	Cole Information Services

221 VARICK AVE

Year	Uses	Source
2017	STAR RECYCLING INC	Cole Information Services
2009	WASTE MANAGEMENT	Cole Information Services
	STAR RECYCLING INC	Cole Information Services
1999	G & A MOVING & STORAGE COMPANY	Cole Information Services
	STAR RECYCLING INCORPORATED	Cole Information Services
1994	STAR RECYCLING INC	Cole Information Services

Varick Avenue

210 Varick Avenue

Year	Uses	Source
1973	INDUSTRIAL WIRE PRODS CO INC	New York Telephone
1970	Greater NY Termnl Inc ofc	New York Telephone
	INDUSTRL WIRE PRODS CO	New York Telephone
1965	Greater NY Termnl Inc oft	New York Telephone

FINDINGS

Year	Uses	Source
1965	MM Oil Burner Corp	New York Telephone
	MORTON FUEL OIL CORP	New York Telephone
	PREFERRED OIL GO INC	New York Telephone
	PREFERRED OIL HEAT INC	New York Telephone
1960	Greater NY Termnl Inc ofc	New York Telephone Company
	MORTON FUEL OIL CORP	New York Telephone Company
	PREFERRED OIL CO INC C	New York Telephone Company
	GREATER NY TERMINL INC OFC	New York Telephone
1949	Morton Fuel Oil Corp	New York Telephone Company
	Pioneer Utilities Corp oil brnrs	New York Telephone Company
	Preferred Oil Co Inc	New York Telephone Company

221 Varick Avenue

Year	Uses	Source
2005	G & A Moving & Storage Co Inc	Hill-Donnelly Corporation
	lo oo	Hill-Donnelly Corporation
	Star Recycling Inc	Hill-Donnelly Corporation
2000	STAR RECYCLING INC	Cole Information Services
1997	G & A Moving And Storage Inc	NYNEX
	G & A Moving And Storage Inc	NYNEX
	STAR RECYCLING INC	NYNEX
1973	Ecology Inc	New York Telephone
1945	Zenith Fuel Co	New York Telephone

FINDINGS

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
188 Meadow Street	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
192 MEADOW ST	2017, 2014, 2009, 2005, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
194 Meadow Street	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
200 Meadow Street	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
200 STEWART AVE	2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
204 Meadow Street	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
210 VARICK AVE	2009, 2005, 2000, 1999, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
210 Varick Avenue	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1945, 1940, 1934, 1928
218 STEWART AVE	2017, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
220 STEWART AVE	2005, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
220 STEWART AVE	2017, 2014, 2009, 2004, 1999, 1994, 1980, 1945, 1940, 1934, 1928
220 STEWERT AVE	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
221 VARICK AVE	2014, 2005, 2004, 2000, 1997, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928
221 Varick Avenue	2017, 2014, 2009, 2004, 1999, 1994, 1992, 1985, 1980, 1976, 1970, 1965, 1960, 1949, 1940, 1934, 1928
227 Stewart Avenue	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1965, 1960, 1949, 1945, 1940, 1934, 1928

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
213 Meadow Street	2017, 2014, 2009, 2005, 2004, 2000, 1999, 1997, 1994, 1992, 1985, 1980, 1976, 1973, 1970, 1949, 1945, 1940, 1934, 1928

APPENDIX E

ENVIRONMENTAL DATABASE RADIUS REPORT

LANGAN

213 Meadow Street
213 Meadow Street
Brooklyn, NY 11237

Inquiry Number: 6826547.2s
January 20, 2022

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	1244
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-9
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527-21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

213 MEADOW STREET
BROOKLYN, NY 11237

COORDINATES

Latitude (North):	40.7130410 - 40ˆ 42' 46.94''
Longitude (West):	73.9282110 - 73ˆ 55' 41.55''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	590532.1
UTM Y (Meters):	4507243.5
Elevation:	14 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14115940 BROOKLYN, NY
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150522
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
213 MEADOW STREET
BROOKLYN, NY 11237

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	CASTLE SANITATION CO	213 MEADOW STREET	FINDS, ECHO		TP
A2	CASALINO INTERIOR DE	213 MEADOW ST	NY RGA LF		TP
A3	CASALINO INTERIOR DE	213 MEADOW ST	NY SWF/LF, NY Spills		TP
A4	VAULT 434	221 MEADOW STREET	NY Spills	Higher	1 ft.
A5	VAULT V560	221-41 MEADOW ST	NY Spills	Higher	1 ft.
B6	CON EDISON	VARICK AVE & MEADOW	NY MANIFEST	Lower	29, 0.005, WSW
B7	CON EDISON	VARICK AVE & MEADOW	RCRA NonGen / NLR	Lower	29, 0.005, WSW
A8	CON EDISON	STEWART AVE & MEADOW	NJ MANIFEST	Higher	37, 0.007, East
A9	CON EDISON	MEADOW ST & STEWART	RCRA-VSQG, NY MANIFEST, NJ MANIFEST	Higher	37, 0.007, East
A10	CON EDISON	STEWART AVE & MEADOW	NY MANIFEST	Higher	37, 0.007, East
A11	UNKNOWN - DRUM RUN	MEADOW STREET & STEW	NY Spills	Higher	37, 0.007, East
A12	CON EDISON	STEWART AVE & MEADOW	RCRA NonGen / NLR, FINDS, ECHO	Higher	37, 0.007, East
A13	MANHOLE 57877	MEADOW ST/STEWART AV	NY Spills	Higher	38, 0.007, East
B14	WASTE MANAGEMENT OF	215 VARICK AVENUE	NY AST	Lower	77, 0.015, West
B15	WMNY VARICK 1 TRANSF	215 VARICK AVENUE	NY SWF/LF, NY Financial Assurance	Lower	77, 0.015, West
A16	CONSOLIDATED EDISON	221 241 MEADOW ST V4	NY MANIFEST	Higher	101, 0.019, East
A17	DIELECTRIC FLUID GOI	243 MEADOW STREET	NY Spills	Higher	114, 0.022, East
A18	CON EDISON - MANHOLE	243 MEADOW STREET	RCRA-LQG, FINDS, ECHO, NY MANIFEST	Higher	114, 0.022, East
C19	VIJAX CORPORATION	210 VARICK AVENUE	NY UST	Lower	128, 0.024, WNW
C20	TO ROADWAY	IFO 210 VARICK AVE	NY Spills	Lower	128, 0.024, WNW
C21	COMMERCIAL BUILDING	210-222 VARICK AVENU	NY Spills	Lower	128, 0.024, WNW
C22	CON EDISON	210 VARICK AVE	NY MANIFEST	Lower	128, 0.024, WNW
C23	CON EDISON SERVICE B	210 VARICK AVE	RCRA NonGen / NLR	Lower	128, 0.024, WNW
C24	NEW TOWN CREEK	225 VARICK AVE	NY Spills	Lower	150, 0.028, WNW
D25	SB 55893	200 STEWART AVE	NY Spills	Higher	181, 0.034, ESE
B26	VARICK ST & MEADOW S	VARICK ST & MEADOW S	NY Spills	Lower	201, 0.038, SW
B27	CON EDISON	OPP 180 VARICK AVE	NY MANIFEST	Lower	205, 0.039, SSW
C28	TRANSFORMER #2279/EM	231 VARICK ST	NY Spills	Lower	219, 0.041, WNW
C29	ROADWAY - PARKING SP	222 VARRICK AVE	NY Spills	Lower	233, 0.044, NW
B30	WASTE MANAGEMENT OF	221 VARICK AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	236, 0.045, West
B31	WASTE MANAGEMENT OF	221 VARICK AVENUE	NY AST	Lower	236, 0.045, West
E32	RIGHT-WAY DEALER WAR	1202 METROPOLITAN AV	NY UST, RCRA NonGen / NLR, FINDS, ECHO, NY...	Lower	252, 0.048, NNW
D33	CON EDISON	STEWART AVE & STAGG	NY MANIFEST	Higher	285, 0.054, SE
D34	CON EDISON	STEWART AVE & STAGG	RCRA NonGen / NLR, FINDS, ECHO	Higher	285, 0.054, SE
D35	CON EDISON	STEWART AVE & STAGG	NJ MANIFEST	Higher	285, 0.054, SE
C36	STORAGE BUILDING	1194 METROPOLITAN AV	NY Spills	Lower	292, 0.055, NW
C37	CON EDISON	FRONT OF 1196 METROP	NY MANIFEST	Lower	295, 0.056, NNW
C38	METRO	1188 METROPOLITAN AV	NY Spills	Lower	296, 0.056, NW
C39	TRUCK IN CREEK	221 ZARICK AVENUE	NY Spills	Lower	303, 0.057, WNW

MAPPED SITES SUMMARY

Target Property Address:
213 MEADOW STREET
BROOKLYN, NY 11237

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
C40	MANHATTAN POLYBAG CO	1150 METROPOLITAN AV	NY Spills, NY MANIFEST	Lower	310, 0.059, WNW
C41	MANHATTAN POLY BAG	1150 METROPOLITAN AV	RCRA NonGen / NLR, NY MANIFEST	Lower	310, 0.059, WNW
C42	MANHATTAN POLY BAG C	METROPOLITAN AVE	RCRA-VSQG, NY AST	Lower	310, 0.059, WNW
C43	LOT	1150 METROPOLITAN AV	NY Spills	Lower	310, 0.059, WNW
C44	AID AUTO STORES, INC	1150 METROPOLITAN AV	RCRA NonGen / NLR, FINDS, ECHO	Lower	310, 0.059, WNW
F45	ALJO AUTO ELECTRIC C	1250 METROPOLITAN AV	RCRA NonGen / NLR	Lower	338, 0.064, NE
F46	CONSOLIDATED PACKAGI	1250 METROPOLITAN AV	NY AIRS, NY MANIFEST	Lower	338, 0.064, NE
F47	CONSOLIDATED PACKAGI	1250 METROPOLITAN AV	RCRA-SQG, FINDS, ECHO, NJ MANIFEST	Lower	338, 0.064, NE
E48	METROPOLITAN STEWART	METROPOLITAN STEWART	NY Spills	Lower	345, 0.065, North
D49	CON EDISON	179 STEWART AVE	NJ MANIFEST	Higher	366, 0.069, SSE
D50	CON EDISON	179 STEWART AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	366, 0.069, SSE
D51	CON EDISON	179 STEWART AVE	NY MANIFEST	Higher	366, 0.069, SSE
G52	PATSON CORP	85 MEADOW ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	366, 0.069, WSW
G53	209 MORGAN AVE. CORP	85 MEADOW STREET	NY UST	Lower	366, 0.069, WSW
G54	APT BUILDING TANK	85 MEADOW STREET	NY LTANKS	Lower	366, 0.069, WSW
H55	VARICK AVENUE	165 VARICK AVENUE	NY SHWS	Lower	371, 0.070, SSW
H56	VARICK AVENUE	165 VARICK AVENUE	NY HSWDS	Lower	371, 0.070, SSW
E57	1201 METROPOLITAN AV	1201 METROPOLITAN AV	NY Spills	Lower	372, 0.070, NNW
C58	JJ KANG ENTERPRISE,	1188 METROPOLITAN AV	NY UST	Lower	377, 0.071, NW
C59	BUY RITE GARAGE INC	1188 METROPOLITAN AV	RCRA NonGen / NLR, ICIS, US AIRS	Lower	377, 0.071, NW
C60	METRO GARAGE	1188 METROPOLITAN AV	NY AST, NY Spills	Lower	377, 0.071, NW
E61	NYCDEP - GENERAL STO	1201 METROPOLITAN AV	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Lower	384, 0.073, NNW
E62	NYC DEP	1201 METROPOLITAN AV	NJ MANIFEST	Lower	384, 0.073, NNW
H63	NYC DEPT OF SANITAT	VARICK AVE	RCRA-VSQG	Lower	405, 0.077, SSW
H64	NYC DEPART OF SANITA	VARICK AVE	NY LTANKS, NY Spills, NY MANIFEST	Lower	405, 0.077, SSW
H65	DSNY BK DISTRICT 1/4	161 VARICK AVENUE	NY UST	Lower	405, 0.077, SSW
I66	GRAND STREET BRIDGE	METROPOLITAN AVE	NY Spills	Lower	412, 0.078, WNW
F67	SUNSHINE BISCUITS IN	1251 METROPOLITAN AV	NY LTANKS, NY UST	Lower	419, 0.079, NE
I68	MANHOLE #15350	VARICK AVE & METROPO	NY Spills	Lower	433, 0.082, NW
I69	ROADWAY	METROPOLITAN AVE & V	NY Spills	Lower	433, 0.082, NW
70	CON EDISON - MANHOLE	169 GARDNER AVE	NY MANIFEST	Higher	449, 0.085, East
F71	SUNSHINE BISCUITS	1251 METROPOLITAN AV	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	455, 0.086, NE
J72	46-25 METROPOLITAN A	46025 METROPOLITAN A	NY Spills	Lower	461, 0.087, NW
G73	COMMERCIAL PROPERTY	175 VARICK AVE	NY Spills	Lower	493, 0.093, SW
G74	M. FINE LUMBER CO. I	175 VARICK AVE	NY UST	Lower	493, 0.093, SW
F75	ROADWAY	METROPOLITAN/GARDNER	NY Spills	Lower	501, 0.095, NE
F76	CON EDISON - MANHOLE	GARDNER AVE AND METR	RCRA-LQG	Lower	510, 0.097, NE
F77	CON EDISON	GARDNER AVE & METROP	RCRA NonGen / NLR	Lower	510, 0.097, NE
F78	CONSOLIDATED EDISON	GARDNER AVE & METROP	NY MANIFEST	Lower	510, 0.097, NE

MAPPED SITES SUMMARY

Target Property Address:
213 MEADOW STREET
BROOKLYN, NY 11237

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
H79	CON EDISON	SCHOLES & VARICK	RCRA NonGen / NLR, NY MANIFEST	Lower	543, 0.103, South
K80	NYC DEP	165 STEWART AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	554, 0.105, SSE
L81	NEW TOWN CREEK	GRANT & STEWART ST	NY Spills	Lower	609, 0.115, North
K82	HI TECH HOLDINGS LLC	492 SCHOLES STREET	NY SWRCY	Lower	610, 0.116, South
K83	HI-TECH RESOURCE REC	492 SCHOLES STREET	NY UST	Lower	610, 0.116, South
K84	SYNTHETIC PROTECTIVE	492 SCHOLES ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	610, 0.116, South
K85	CASILINO CONTRACTING	160 STEWART AVE	NY Spills	Higher	613, 0.116, SE
J86	CONSOLIDATED CARPET	1157 GRAND ST	NY LTANKS	Lower	617, 0.117, NNW
J87	ULTIMATE TRUCK & EQU	1157 GRAND ST	RCRA-VSQG	Lower	617, 0.117, NNW
J88	ULTIMATE TRUCK & EQU	1157 GRAND STREET	NY AST	Lower	617, 0.117, NNW
J89	ULTIMATE TRUCK & EQU	1157 GRAND STREET	NY Spills	Lower	617, 0.117, NNW
M90	CON EDISON	FRONT OF 140 VARICK	NY MANIFEST	Lower	625, 0.118, South
I91	CON EDISON - MANHOLE	1131 GRAND STREET	RCRA-LQG, NY MANIFEST	Lower	649, 0.123, NW
I92	1131 GRAND ET IAC	1131 GRAND STREET	NY UST	Lower	649, 0.123, NW
I93	MANHOLE 1299	1131 GRAND ST	NY Spills	Lower	649, 0.123, NW
I94	VAULT 2597	METROPOLITAN AV	NY Spills	Lower	655, 0.124, WNW
I95	NEWTOWN CREEK	METROPOLITAN BRIDGE	NY Spills	Lower	655, 0.124, WNW
I96	MANHOLE #36370	GRAND ST/METROPOLITA	NY Spills	Lower	655, 0.124, WNW
I97	METROPOLITAIN AVE &	METROPOLITAIN AVE &	NY Spills	Lower	655, 0.124, WNW
I98	METROPOLITAN AVE BRI	METROPOLITAN AVENUE	NY Spills	Lower	655, 0.124, WNW
I99	METROPOLITAN AVE BRI	OVER ENGLISH KILLS C	NY Spills	Lower	655, 0.124, WNW
N100	CON EDISON	228 GARDNER AVE	NY MANIFEST	Lower	682, 0.129, NE
L101	CONSOLIDATED CARPET	1181 GRAND STREET	NY UST	Lower	697, 0.132, North
L102	CONSOLIDATED CARPET	1181 GRAND ST	RCRA NonGen / NLR, NY MANIFEST	Lower	697, 0.132, North
L103	NYC FIRE DEPT ENGINE	1201 GRAND ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	727, 0.138, North
L104	ENGINE COMPANY 206	1201 GRAND STREET	NY UST	Lower	727, 0.138, North
L105	ENGINE COMPANY 206	1201 GRAND STREET	NY AST	Lower	727, 0.138, North
N106	WASTE MANAGEMENT OF	232 GARDNER AVENUE	NY SWF/LF, NY Spills	Lower	727, 0.138, NNE
N107	WASTE MANAGEMENT OF	232 GARDNER AVENUE	NY AST	Lower	727, 0.138, NNE
M108	HI-TECH RESOURCE REC	130 VARICK AVENUE	NY SWF/LF	Lower	728, 0.138, South
M109	HI-TECH RESOURCE REC	130 VARICK AVE	RCRA NonGen / NLR	Lower	728, 0.138, South
O110	BAYSIDE FUEL OIL DEP	1100 GRAND ST	RCRA NonGen / NLR, FTTS, HIST FTTS, FINDS, ECHO	Higher	752, 0.142, WNW
O111	BAYSIDE FUEL OIL DEP	1100 GRAND ST	NY MOSF, NY Spills, NY SPDES	Higher	752, 0.142, WNW
O112	BAYSIDE FUEL OIL DEP	1100 GRAND ST	FINDS, FUELS PROGRAM	Higher	752, 0.142, WNW
O113	BAYSIDE FUEL OIL DEP	1100 GRAND STREET	NY MOSF UST, NY MOSF AST	Higher	752, 0.142, WNW
L114	UNION BEER DIST. L.L	1213-17 GRAND ST	NY UST	Lower	756, 0.143, North
L115	1213 GRAND STREET	1213 GRAND STREET	NY LTANKS, NY Spills	Lower	756, 0.143, North
M116	COOPER RECYCLING; LL	123 VARICK AVENUE	NY SWF/LF, NY Spills, NY Financial Assurance, NY...	Lower	771, 0.146, South
M117	WASTE MANAGEMENT OF	123 VARICK AVE	RCRA-SQG, US AIRS, PA MANIFEST, NY MANIFEST, NJ...	Lower	771, 0.146, South

MAPPED SITES SUMMARY

Target Property Address:
213 MEADOW STREET
BROOKLYN, NY 11237

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
M118	WASTE MANAGEMENT OF	123 VARICK AVENUE	NY AST	Lower	771, 0.146, South
P119	MIONE TRANSIT MIX	1301 METROPOLITAN AV	RCRA NonGen / NLR, FINDS, ECHO	Lower	788, 0.149, ENE
P120	WASTE MANAGEMENT OF	1301 METROPOLITAN AV	NY SWF/LF	Lower	788, 0.149, ENE
P121	1301 METROPOLITAN AV	1301 METROPOLITAN AV	NY UST	Lower	788, 0.149, ENE
122	NEWTOWN CREEK SUPERF	NEWTOWN CRK - N LAT	NPL, SEMS, RCRA-SQG, ROD, PRP, NY MANIFEST	Lower	794, 0.150, NW
O123	NYCDOT - METROPOLITA	1109 METROPOLITAN AV	RCRA-LQG, FINDS, ECHO, NY MANIFEST, NJ MANIFEST	Higher	799, 0.151, WNW
M124	CON EDISON	VARICK AND MESEROLE	RCRA NonGen / NLR, FINDS, ECHO	Lower	801, 0.152, South
N125	CON EDISON	GARDNER AVE & GRAND	NY MANIFEST	Lower	815, 0.154, NNE
N126	CON EDISON	GARDNER AVE & GRAND	NJ MANIFEST	Lower	815, 0.154, NNE
N127	CON EDISON	GARDNER AVE & GRAND	RCRA NonGen / NLR	Lower	815, 0.154, NNE
M128	CON EDISON	W SIDE VARICK ST	NJ MANIFEST	Lower	816, 0.155, South
M129	CON EDISON	W SIDE VARICK ST	NY MANIFEST	Lower	816, 0.155, South
M130	CON EDISON	VARICK & MESEROLE ST	NJ MANIFEST	Lower	816, 0.155, South
M131	CON EDISON	VARICK ST & MESEROLE	NY MANIFEST	Lower	816, 0.155, South
M132	CON EDISON	VARICK ST & MESEROLE	RCRA NonGen / NLR, FINDS, ECHO	Lower	816, 0.155, South
M133	CON EDISON	VARICK ST & MESEROLE	RCRA NonGen / NLR	Lower	816, 0.155, South
Q134	ALLOCCO RECYCLING LT	575 SCHOLES STREET	NY SWRCY, NY Spills	Higher	908, 0.172, ESE
P135	CON ED - V 4628	SCOTT AVE & METRO AV	RCRA NonGen / NLR, NY MANIFEST	Lower	947, 0.179, ENE
O136	L & H ASSOCIATES C/O	1101-1107 METROPOLIT	NY UST	Lower	974, 0.184, WNW
R137	CON EDISON	585 MESSEROLE ST	NY MANIFEST	Higher	994, 0.188, ESE
R138	CON EDISON - MANHOLE	585 MESSEROLE ST	RCRA-LQG	Higher	994, 0.188, ESE
S139	ALFRED CHEMICAL CORP	111 GARDNER AVE.	NY CBS, NY AST, NY CBS AST, NY Spills	Lower	1004, 0.190, SE
S140	ALFRED CHEMICAL CORP	111 GARDNER AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	1004, 0.190, SE
T141	WOOD-TEX PANELS INC	108 VARICK AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1049, 0.199, SSE
U142	GREENWALD INDUSTRIES	1340 METROPOLITAN AV	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1072, 0.203, East
V143	ROLLING FRITO-LAY SA	222 MORGAN AVENUE	NY AST	Lower	1079, 0.204, West
V144	EASTERN TRANSFER OF	222 MORGAN AVE	NY SWF/LF, NY LTANKS, NY SPDES	Lower	1079, 0.204, West
R145	MESEROLE STREET RECY	568 MESEROLE STREET	NY SWRCY	Higher	1099, 0.208, ESE
U146	CON EDISON SERVICE B	ONDERDONK AVE & METR	RCRA NonGen / NLR, NY MANIFEST	Lower	1105, 0.209, ENE
T147	ENEQUIST CHEMICAL CO	100 VARICK AVE	RCRA-LQG, NY CBS AST, FINDS, ECHO, PA MANIFEST, NY...	Lower	1112, 0.211, South
T148	ENEQUIST CHEMICAL	100 VARICK AVENUE	NY AST	Lower	1112, 0.211, South
T149	EMEQUIFT CHEMICAL CO	100 VARICK AVE	NY LTANKS	Lower	1112, 0.211, South
T150	ENEQUIST CHEMICAL CO	100 VARICK AVENUE	NY CBS, NY AST, NY Spills	Lower	1112, 0.211, South
W151	NEWTOWN USED AUTO PA	1074 GRAND STREET	NY AST	Lower	1114, 0.211, West
W152	NEWTOWN AUTO SALES &	1074 GRAND STREET	NY SWF/LF, NY SPDES	Lower	1114, 0.211, West
Q153	GADS INC	594 SCHOLES STREET	NY SWF/LF	Higher	1123, 0.213, East
Q154	BFI WASTE SERVICES O	594 SCHOLES STREET	NY AST	Higher	1123, 0.213, East
T155	CON EDISON - MANHOLE	VARICK AVE	RCRA-LQG	Lower	1125, 0.213, South
T156	CON EDISON	VARICK AVE	NY MANIFEST	Lower	1125, 0.213, South

MAPPED SITES SUMMARY

Target Property Address:
213 MEADOW STREET
BROOKLYN, NY 11237

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Q157	BFI (598-636 SCHOLES	598-636 SCHOLES STRE	NY SWF/LF, NY SWRCY	Higher	1137, 0.215, East
W158	CLOSED-LACKOF RECENT	1105 METROPOLITAN AV	NY LTANKS	Lower	1144, 0.217, WNW
159	1101 METROPOLITAN AV	1101 METROPOLITAN AV	NY LTANKS	Lower	1171, 0.222, WNW
X160	BLINN DRUG CO	16 REWE ST	NY UST	Lower	1173, 0.222, NW
Y161	A&I REALTY	20 REWE ST	RCRA NonGen / NLR, FINDS	Lower	1182, 0.224, NNW
Y162	A&I REALTY	20 REWE ST	NY MANIFEST	Lower	1182, 0.224, NNW
W163	ACME ALBERT STEEL DR	1050 GRAND ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1184, 0.224, West
X164	12 REWE STREET LLC	12 REWE STREET	NY AST	Lower	1191, 0.226, NW
X165	12 REWE STREET LLC	12 REWE STREET	NY UST	Lower	1191, 0.226, NW
U166	AVALANCHE CONTRACTIN	46-26 METROPOLITAN A	NY SWF/LF	Lower	1196, 0.227, ENE
167	CHARLES J KING INC	1301 GRAND ST	NY SWF/LF, NY UST, NY SWRCY, RCRA NonGen / NLR, NY...	Lower	1217, 0.230, NE
W168	GRAND PETROLEUM, LLC	1049 GRAND STREET	NY UST	Higher	1223, 0.232, West
W169	B P PRODUCTS NORTH A	1049 GRAND ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1223, 0.232, West
170	8 REWE STREET, LLC	8 REWE STREET	NY UST	Lower	1250, 0.237, NW
Z171	NYC DEP HAZ MAT	200 MORGAN AVENUE	NY MOSF, NY LIENS, NY Spills, NY MANIFEST	Lower	1253, 0.237, WSW
Z172	CON EDISON	FRONT OF 200 MORGAN	NY MANIFEST	Lower	1253, 0.237, WSW
Z173	MORGAN OIL TERMINALS	200 MORGAN AVE	NY MOSF UST, NY Spills, RCRA NonGen / NLR, FINDS,...	Lower	1253, 0.237, WSW
U174	CAPITAL AUTO SALVAGE	4600 METROPOLITAN AV	NY AST	Lower	1273, 0.241, East
U175	METRO AUTO SALVAGE	4600 METROPOLITAN AV	NY SWF/LF, NY CBS, NY AST, NY Spills, NY SPDES	Lower	1273, 0.241, East
176	ALLOCCO RECYCLING (6	606 MESEROLE STREET	NY SWRCY	Higher	1275, 0.241, ESE
AA177	RANDOLPH ASSOCIATES	165 RANDOLPH STREET	NY UST, NY Spills	Higher	1307, 0.248, SE
Y178	NEW YORK TELEPHONE C	15 REWE ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1313, 0.249, NNW
AA179	CAL OSTLUND INC	185 RANDOLPH ST	NY LTANKS, RCRA NonGen / NLR, FINDS, ECHO, NY...	Higher	1336, 0.253, SE
AB180	FRITO LAY	202-218 MORGAN AVENU	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Lower	1386, 0.262, WSW
AB181	FRITO-LAY	202 MORGAN AVENUE	NY SWF/LF, NY Spills, NY MANIFEST	Lower	1386, 0.262, WSW
182	DURITE S&V & MAINT.	250 MORGAN AVE	NY SWF/LF	Higher	1402, 0.266, West
AC183	WASTE MANAGEMENT OF	101 VARICK AVENUE	NY SWRCY, NY Spills, NY SPDES	Lower	1406, 0.266, South
184	GREEN HILL	2 REWE ST & 300 VAND	NY LTANKS	Lower	1445, 0.274, WNW
185	COTOIA ENTERPRISES	46-26 METROPOLITAN A	NY SWRCY	Lower	1448, 0.274, East
186	YRC BROOKLYN (187)	1313 GRAND ST	RCRA-VSQG, NY LTANKS, NY Spills, FINDS, ECHO, NY...	Lower	1452, 0.275, NE
AA187	NEO RAY LIGHTING PRO	537 JOHNSON AVENUE	RCRA-VSQG, NY LTANKS, NY UST, ICIS, US AIRS,...	Higher	1494, 0.283, SSE
AD188	140 MORGAN AVE/BROOK	140 MORGAN AVENUE	NY LTANKS, NY Spills	Lower	1627, 0.308, SW
AC189	JOYVA VACANT LOT	498 JOHNSON AVENUE	NY VCP	Lower	1630, 0.309, South
AE190	BROWNING FERRIS	72 SCOTT AVE	NY SWF/LF, NY LTANKS, NY CBS, NY AST, NY CBS AST,...	Higher	1637, 0.310, ESE
AE191	255 RANDOLPH STREET	255 RANDOLPH ST	NY BROWNFIELDS, NY MANIFEST	Higher	1716, 0.325, ESE
192	DANGELO AUTO SALES &	582 JOHNSON AVE	NY SWF/LF	Higher	1726, 0.327, SSE
AF193	APT COMPLEX	349 SCHOLES ST	NY LTANKS	Higher	1727, 0.327, SW
194	345 TENEYCK STREET	345 TENEYCK STREET	NY LTANKS	Higher	1730, 0.328, West
AD195	100 MORGAN AVENUE	100 MORGAN AVE	NY LTANKS	Lower	1785, 0.338, SW

MAPPED SITES SUMMARY

Target Property Address:
213 MEADOW STREET
BROOKLYN, NY 11237

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AG196	T & T SCRAP LLC	340 MASPETH AVENUE	NY SWF/LF, NY Spills, NY SPDES	Lower	1809, 0.343, NNW
AG197	NEW YORK RECYCLERS;	340 MASPETH AVENUE	NY SWF/LF	Lower	1809, 0.343, NNW
AH198	FEDEX FACILITY	300 MASPETH AVE	NY LTANKS, NY Spills	Lower	1813, 0.343, NNW
AI199	JOYVA CORPORATION	53 VARICK AVE	NY LTANKS	Higher	1814, 0.344, South
AJ200	CORNISH KNIT GOODS/C	121 INGRAHAM ST./89	NY ENG CONTROLS, NY INST CONTROL, NY VCP	Higher	1827, 0.346, South
AJ201	CORNISH MINI MILLS	121 INGRAHAM ST	NY LTANKS	Higher	1827, 0.346, South
AG202	TANKS-A-LOT CO	362 MASPETH AVE	SEMS-ARCHIVE	Lower	1840, 0.348, North
AG203	TANKS-A-LOT COMPANY	362 MASPETH AVENUE	NY HSWDS	Lower	1840, 0.348, North
AG204	BCF OIL REFINING, IN	360 MASPETH AVENUE	NY SWF/LF, NY LTANKS, NY MOSF UST, NY MOSF, NY...	Lower	1852, 0.351, NNW
AG205	US ENVIRONMENTAL PRO	C O BCF OIL REFINING	SEMS, NY SHWS, RCRA NonGen / NLR, PRP, ECHO, NY...	Lower	1852, 0.351, NNW
AG206	BCF, 360 MASPETH AVE	360 MASPETH AVENUE,	NY VCP	Lower	1852, 0.351, NNW
AK207	COOPER TANK AND WELD	222 MASPETH AVENUE	NY SWF/LF, NY Financial Assurance	Higher	1854, 0.351, NW
AE208	ROLET FOOD PRODUCTS	70 SCOTT AVE	NY LTANKS	Higher	1859, 0.352, SE
AJ209	UNOCCUPIED WAREHOUSE	88 PORTER AVENUE	NY LTANKS	Higher	1860, 0.352, South
AK210	EQUITY WORKS	MASPETH AND VANDERVO	EDR MGP	Higher	1864, 0.353, NW
AK211	FONTANA TRANSFER STA	252 MASPETH AVENUE	NY SWF/LF	Lower	1895, 0.359, NW
AH212	GREENPOINT ENERGY FA	287 MASPETH AVENUE	NY CBS, NY AST, NY MOSF AST, NY Spills, NY AIRS,...	Higher	1897, 0.359, NNW
AH213	GREENPOINT	287 MASPETH AVENUE	EDR MGP	Higher	1897, 0.359, NNW
AH214	BKLYN UNION GAS /GRE	287 MASPETH AVE	SEMS-ARCHIVE	Higher	1897, 0.359, NNW
AH215	GREENPOINT	287 MASPETH AVENUE	NY SHWS, NY SWF/LF, NY LTANKS, NY MOSF, NY TANKS,...	Higher	1897, 0.359, NNW
AH216	BUG, MASPETH GATE ST	285 MASPETH AVENUE	NY HSWDS	Higher	1899, 0.360, NNW
AH217	BKLYN UNION GAS /MAS	285 MASPETH AVE	SEMS-ARCHIVE	Higher	1899, 0.360, NNW
AF218	SCHOLES ST. STATION	SCHOLES ST 7 BOGART	EDR MGP	Higher	1901, 0.360, SW
AL219	DITMAS OIL ASSOCIATE	364 MASPETH AVENUE	NY MOSF UST, NY AST, NY CBS AST, NY MOSF AST, NY...	Lower	1908, 0.361, North
AL220	OFFICE BUILDING	364 MASPETH AVE	NY LTANKS	Lower	1908, 0.361, North
AL221	DITMAS OIL ASSOCIATE	364 MASPETH AVENUE	NY LTANKS, NY CBS, NY MOSF, NY Spills, NY SPDES	Lower	1908, 0.361, North
222	46-81 METROPOLITAN A	46-81 METROPOLITAN A	NY BROWNFIELDS	Lower	1914, 0.363, East
223	APARTMENT BUILDING	35 MEADOW STREET	NY LTANKS	Higher	1945, 0.368, WSW
AM224	LEWIS FLUSHING CORP.	1819 FLUSHING AVENUE	NY LTANKS	Higher	1946, 0.369, ESE
225	MORGAN TERMINAL	200 MORGAN AVE	NY HSWDS	Higher	1958, 0.371, SW
226	F & W WOODWORK CO	1267 FLUSHING AVE	NY LTANKS, NY Spills, RCRA NonGen / NLR, NY...	Higher	2001, 0.379, SE
AI227	DERBY TEXTILE CORPOR	41 VARICK AVENUE	NY LTANKS, NY UST	Higher	2004, 0.380, South
228	88 INGRAHAM REALTY C	88 INGRAHAM ST	RCRA-SQG, NY ENG CONTROLS, NY INST CONTROL, NY...	Higher	2005, 0.380, SSW
229	EMPIRE WAREHOUSE	1312-1324 FLUSHING A	NY LTANKS	Higher	2041, 0.387, ESE
AJ230	CORNELL BEVERAGES IN	105 HARRISON PLACE	NY LTANKS, NY UST	Higher	2074, 0.393, South
231	308 MAUJER ST	308 MAUJER ST	NY LTANKS	Higher	2077, 0.393, West
AM232	NATIONWIDE SCRAP LLC	18-19 FLUSHING AVENU	NY SWRCY	Higher	2132, 0.404, ESE
233	KORNBLUM, SIDNEY	394 JOHNSON AVE.	SEMS-ARCHIVE, LEAD SMELTERS	Higher	2143, 0.406, SSW
AN234	MS POWER INC	187 MASPETH VE	NY SWF/LF	Higher	2229, 0.422, NW

MAPPED SITES SUMMARY

Target Property Address:
213 MEADOW STREET
BROOKLYN, NY 11237

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AN235	MAGNUM BODY SHOP INC	185A MASPETH AVE	NY SWF/LF	Higher	2229, 0.422, NW
236	U. S. WASTE MANAGEME	48 KNICKERBOCKER (69	NY SWF/LF	Higher	2271, 0.430, SSW
AN237	BUG, EQUITY WORKS	MASPETH AND MORGAN A	NY HSWDS	Higher	2289, 0.434, WNW
AO238	UNIVERSAL SCRAP PROC	27 STEWART AVE	NY SWF/LF, NY Spills, NY SPDES	Higher	2329, 0.441, SSE
239	47-40 METROPOLITAN A	47-40 METROPOLITAN A	NY LTANKS	Higher	2341, 0.443, East
AP240	M & C TRANSFER STATI	58-26 47 STREET	NY SWF/LF	Lower	2352, 0.445, NE
AP241	NMS WASTE PAPER	58-35 47TH STREET	NY SWRCY, NY Spills	Lower	2384, 0.452, NE
AP242	GPB WASTE NY DBA NY/	58-35 47TH STREET	NY SWRCY	Lower	2384, 0.452, NE
AQ243	18-51 FLUSHING AVE/Q	18-51 FLUSHING AVENU	NY LTANKS	Higher	2396, 0.454, East
AO244	FORMER UNIVERSAL SCR	1181 FLUSHING AVENUE	NY BROWNFIELDS, NY Spills	Higher	2417, 0.458, SSE
245	TRANSCON LINES TERMI	430 MASPETH AVE	NY LTANKS, NY UST, RCRA NonGen / NLR, NY MANIFEST	Lower	2465, 0.467, NNE
AR246	FORMER JAYER PLATING	2 INGRAHAM ST	NY SHWS, NY VCP, NY BROWNFIELDS	Higher	2492, 0.472, SSW
AR247	FORMER JAYER PLATING	2 INGRAHAM STREET	NY HSWDS	Higher	2492, 0.472, SSW
248	UNIVERSAL USED AUTO	1175 FLUSHING AVE	NY SWF/LF, NY Spills	Higher	2536, 0.480, SSE
AQ249	1884 FLUSHING AVENUE	1884 FLUSHING AVENUE	NY LTANKS, NY Spills	Higher	2549, 0.483, East
250	COGENT TRANSFER; LLC	105-115 THAMES STREE	NY SWF/LF, NY Financial Assurance	Higher	2573, 0.487, South
AS251	57-00 MASPETH AVE LL	5700 47TH ST	NY SWF/LF, NY UST, NY AST, NY Spills	Lower	2576, 0.488, NNE
AS252	ISLAND TRANS CORP	5700 47TH STREET	NY LTANKS	Lower	2576, 0.488, NNE
253	BKLYN UNION GAS /EQU	MASPETH & MORGAN AVE	SEMS-ARCHIVE	Higher	2587, 0.490, WNW
254	881-889 GRAND STREET	885 GRAND ST	RCRA-LQG, NY LTANKS, NY MANIFEST	Higher	2597, 0.492, West
255	RAPID ARMORED CORPOR	254 SCHOLES STREET	NY SHWS, NY Spills	Higher	2866, 0.543, WSW
256	TECHNICAL METAL FINI	214 STARR STREET	SEMS-ARCHIVE, NY SHWS	Higher	3203, 0.607, SSE
257	FORMER KLINK COSMO C	364 RICHARDSON STREE	NY SHWS	Higher	3377, 0.640, NW
258	GOODMAN BROTHERS CO	18 DIVISION PLACE	RCRA-VSQG, NY SHWS, NY UST, NY CBS, NY AST, NY CBS..	Higher	3896, 0.738, NW
259	FORMER LOMBARDY STRE	171 LOMBARDY STREET	NY SHWS, NY CBS, NY AST, NY CBS AST, NY MANIFEST	Higher	3994, 0.756, NNW
260	95 LOMBARDY ST./ACME	95 LOMBARDY ST	NY SHWS, NY UST	Higher	4091, 0.775, NW
AT261	FORMER ACME STEEL PA	513 PORTER AVENUE	NY SHWS	Higher	4361, 0.826, NNW
AT262	ACME STEEL/BRASS FOU	72 ANTHONY STREET	NY SHWS	Higher	4361, 0.826, NNW
263	TOP HAT CLEANERS	152 GRAHAM AVE	RCRA-VSQG, NY SHWS, ICIS, US AIRS, NY MANIFEST	Higher	4367, 0.827, WSW
264	FORMER W.L.K. CORP.	58-30 57TH STREET	NY SHWS	Higher	4817, 0.912, ENE
265	CITY BARREL CO.	421-429 MEEKER STREE	NY SHWS	Higher	5213, 0.987, WNW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
CASTLE SANITATION CO 213 MEADOW STREET BROOKLYN, NY 11237	FINDS ECHO Registry ID: 110070625464	N/A
CASALINO INTERIOR DE 213 MEADOW ST BROOKLYN, NY	NY RGA LF	N/A
CASALINO INTERIOR DE 213 MEADOW ST BROOKLYN, NY 11237	NY SWF/LF NY Spills Spill Number/Closed Date: 9315532 / 1994-03-31 Site ID: 214676 Spill Date: 1994-03-31	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---------- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---- Land Use Control Information System
US ENG CONTROLS ---- Engineering Controls Sites List
US INST CONTROLS ---- Institutional Controls Sites List

Federal ERNS list

ERNS ---- Emergency Response Notification System

Lists of state and tribal leaking storage tanks

INDIAN LUST ---- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---- Listing of Leaking Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST ---- Underground Storage Tank Listing
NY CBS UST ---- Chemical Bulk Storage Database
INDIAN UST ---- Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

NY RES DECL ---- Restrictive Declarations Listing

Lists of state and tribal voluntary cleanup sites

INDIAN VCP ---- Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

NY ERP ---- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE ---- Registered Waste Tire Storage & Facility List
INDIAN ODI ---- Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ---- Torres Martinez Reservation Illegal Dump Site Locations
ODI ---- Open Dump Inventory
IHS OPEN DUMPS ---- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---- Delisted National Clandestine Laboratory Register
NY DEL SHWS ---- Delisted Registry Sites
US CDL ---- National Clandestine Laboratory Register
NY PFAS ---- PFAS Contamination Site Location Listing

EXECUTIVE SUMMARY

Local Lists of Registered Storage Tanks

NY HIST UST ---- Historical Petroleum Bulk Storage Database
NY HIST AST ---- Historical Petroleum Bulk Storage Database

Local Land Records

LIENS 2 ---- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
NY Hist Spills ---- SPILLS Database
NY SPILLS 90 ---- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
RMP ---- Risk Management Plans
PADS ---- PCB Activity Database System
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
US MINES ---- Mines Master Index File
ABANDONED MINES ---- Abandoned Mines
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
UXO ---- Unexploded Ordnance Sites
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY DRYCLEANERS ---- Registered Drycleaners
NY E DESIGNATION ---- E DESIGNATION SITE LISTING
NY VAPOR REOPENED ---- Vapor Intrusion Legacy Site List
NY UIC ---- Underground Injection Control Wells
NY COOLING TOWERS ---- Registered Cooling Towers
NY LEAD ---- Lead-based Paint Testing Results
MINES MRDS ---- Mineral Resources Data System

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Auto ---- EDR Exclusive Historical Auto Stations

EXECUTIVE SUMMARY

EDR Hist Cleaner..... EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS..... Recovered Government Archive State Hazardous Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 10/20/2021 has revealed that there is 1 NPL site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NEWTOWN CREEK SUPERF Cerclis ID:: 206282 EPA Id: NYN000206282	***NEWTOWN CRK - N LAT***	***NW 1/8 - 1/4 (0.150 mi.)***	***122***	***433***

Lists of Federal sites subject to CERCLA removals and CERCLA orders

SEMS: SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the SEMS list, as provided by EDR, and dated 10/20/2021 has revealed that there are 2

SEMS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NEWTOWN CREEK SUPERF	***NEWTOWN CRK - N LAT***	***NW 1/8 - 1/4 (0.150 mi.)***	***122***	***433***
Site ID: 0206282				
EPA Id: NYN000206282				
US ENVIRONMENTAL PRO	***C O BCF OIL REFINING***	***NNW 1/4 - 1/2 (0.351 mi.)***	***AG205***	***901***
Site ID: 0204261				
EPA Id: NYD068273044				

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 10/20/2021 has revealed that there are 5 SEMS-ARCHIVE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BKLYN UNION GAS /GRE	287 MASPETH AVE	NNW 1/4 - 1/2 (0.359 mi.)	AH214	987
Site ID: 0201977				
EPA Id: NYD980532014				
BKLYN UNION GAS /MAS	285 MASPETH AVE	NNW 1/4 - 1/2 (0.360 mi.)	AH217	1012
Site ID: 0201996				
EPA Id: NYD980532220				
KORNBLUM, SIDNEY	***394 JOHNSON AVE.***	***SSW 1/4 - 1/2 (0.406 mi.)***	***233***	***1096***
BKLYN UNION GAS /EQU	MASPETH & MORGAN AVE	WNW 1/4 - 1/2 (0.490 mi.)	253	1165
Site ID: 0201980				
EPA Id: NYD980532048				

Lower Elevation	Address	Direction / Distance	Map ID	Page
TANKS-A-LOT CO	362 MASPETH AVE	N 1/4 - 1/2 (0.348 mi.)	AG202	866
Site ID: 0201827				
EPA Id: NYD980509228				

Lists of Federal RCRA generators

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 09/13/2021 has revealed that there are 7 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE EPA ID:: NYP004297362	***243 MEADOW STREET***	***E 0 - 1/8 (0.022 mi.)***	***A18***	***37***
NYCDOT - METROPOLITA EPA ID:: NYD987032364	***1109 METROPOLITAN AV***	***WNW 1/8 - 1/4 (0.151 mi.)***	***O123***	***441***
CON EDISON - MANHOLE EPA ID:: NYP004287686	585 MESSEROLE ST	ESE 1/8 - 1/4 (0.188 mi.)	R138	483

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - MANHOLE EPA ID:: NYP004197893	GARDNER AVE AND METR	NE 0 - 1/8 (0.097 mi.)	F76	265
CON EDISON - MANHOLE EPA ID:: NYP004296299	***1131 GRAND STREET***	***NW 0 - 1/8 (0.123 mi.)***	***I91***	***314***
ENEQUIST CHEMICAL CO EPA ID:: NYD002028827	***100 VARICK AVE***	***S 1/8 - 1/4 (0.211 mi.)***	***T147***	***522***
CON EDISON - MANHOLE EPA ID:: NYP004287884	VARICK AVE	S 1/8 - 1/4 (0.213 mi.)	T155	559

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 09/13/2021 has revealed that there are 3 RCRA-SQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED PACKAGI EPA ID:: NYD986892412	***1250 METROPOLITAN AV***	***NE 0 - 1/8 (0.064 mi.)***	***F47***	***122***
WASTE MANAGEMENT OF EPA ID:: NYD982744815	***123 VARICK AVE***	***S 1/8 - 1/4 (0.146 mi.)***	***M117***	***402***
NEWTOWN CREEK SUPERF EPA ID:: NYN000206282	***NEWTOWN CRK - N LAT***	***NW 1/8 - 1/4 (0.150 mi.)***	***122***	***433***

EXECUTIVE SUMMARY

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 09/13/2021 has revealed that there are 5 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID:: NYP004186029	***MEADOW ST & STEWART***	***E 0 - 1/8 (0.007 mi.)***	***A9***	***19***

Lower Elevation	Address	Direction / Distance	Map ID	Page
MANHATTAN POLY BAG C EPA ID:: NYD982272627	***METROPOLITAN AVE***	***WNW 0 - 1/8 (0.059 mi.)***	***C42***	***96***
NYCDEP - GENERAL STO EPA ID:: NYR000113217	***1201 METROPOLITAN AV***	***NNW 0 - 1/8 (0.073 mi.)***	***E61***	***217***
NYC DEPT OF SANITAT EPA ID:: NYR000109116	VARICK AVE	SSW 0 - 1/8 (0.077 mi.)	H63	227
ULTIMATE TRUCK & EQU EPA ID:: NYN008029019	1157 GRAND ST	NNW 0 - 1/8 (0.117 mi.)	J87	295

Lists of state- and tribal hazardous waste facilities

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 01/06/2022 has revealed that there are 15 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GREENPOINT Site Code: 372971 Class Code: Significant threat to the public health or environment - action required.	***287 MASPETH AVENUE***	***NNW 1/4 - 1/2 (0.359 mi.)***	***AH215***	***988***
FORMER JAYER PLATING Site Code: 57074	***2 INGRAHAM ST***	***SSW 1/4 - 1/2 (0.472 mi.)***	***AR246***	***1130***
RAPID ARMORED CORPOR Site Code: 588258	***254 SCHOLES STREET***	***WSW 1/2 - 1 (0.543 mi.)***	***255***	***1176***
TECHNICAL METAL FINI Site Code: 57764	***214 STARR STREET***	***SSE 1/2 - 1 (0.607 mi.)***	***256***	***1180***
FORMER KLINK COSMO C Site Code: 405851 Class Code: Significant threat to the public health or environment - action required.	364 RICHARDSON STREE	NW 1/2 - 1 (0.640 mi.)	257	1183
GOODMAN BROTHERS CO	***18 DIVISION PLACE***	***NW 1/2 - 1 (0.738 mi.)***	***258***	***1186***

Site Code: 505634
Class Code: Significant threat to the public health or environment - action required.

FORMER LOMBARDY STRE	***171 LOMBARDY STREET***	***NNW 1/2 - 1 (0.756 mi.)***	***259***	***1214***
Site Code: 486951				
Class Code: Significant threat to the public health or environment - action required.				
95 LOMBARDY ST./ACME	***95 LOMBARDY ST***	***NW 1/2 - 1 (0.775 mi.)***	***260***	***1221***
Site Code: 405853				
Class Code: Significant threat to the public health or environment - action required.				
FORMER ACME STEEL PA	513 PORTER AVENUE	NNW 1/2 - 1 (0.826 mi.)	AT261	1226
Site Code: 494893				
ACME STEEL/BRASS FOU	72 ANTHONY STREET	NNW 1/2 - 1 (0.826 mi.)	AT262	1228
Site Code: 405855				
Class Code: Significant threat to the public health or environment - action required.				
TOP HAT CLEANERS	***152 GRAHAM AVE***	***WSW 1/2 - 1 (0.827 mi.)***	***263***	***1230***
Site Code: 504341				
FORMER W.L.K. CORP.	58-30 57TH STREET	ENE 1/2 - 1 (0.912 mi.)	264	1240
Site Code: 371165				
Class Code: Significant threat to the public health or environment - action required.				
CITY BARREL CO.	421-429 MEEKER STREE	WNW 1/2 - 1 (0.987 mi.)	265	1243
Site Code: 55909				

Lower Elevation	Address	Direction / Distance	Map ID	Page
VARICK AVENUE	165 VARICK AVENUE	SSW 0 - 1/8 (0.070 mi.)	H55	179
Site Code: 55914				
US ENVIRONMENTAL PRO	***C O BCF OIL REFINING***	***NNW 1/4 - 1/2 (0.351 mi.)***	***AG205***	***901***
Site Code: 56747				

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 09/30/2021 has revealed that there are 30 NY SWF/LF sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GADS INC	594 SCHOLES STREET	E 1/8 - 1/4 (0.213 mi.)	Q153	556
BFI (598-636 SCHOLES	***598-636 SCHOLES STRE***	***E 1/8 - 1/4 (0.215 mi.)***	***Q157***	***563***
DURITE S&V & MAINT.	250 MORGAN AVE	W 1/4 - 1/2 (0.266 mi.)	182	750
BROWNING FERRIS	***72 SCOTT AVE***	***ESE 1/4 - 1/2 (0.310 mi.)***	***AE190***	***800***
DANGELO AUTO SALES &	582 JOHNSON AVE	SSE 1/4 - 1/2 (0.327 mi.)	192	819
COOPER TANK AND WELD	***222 MASPETH AVENUE***	***NW 1/4 - 1/2 (0.351 mi.)***	***AK207***	***911***
GREENPOINT	***287 MASPETH AVENUE***	***NNW 1/4 - 1/2 (0.359 mi.)***	***AH215***	***988***
MS POWER INC	187 MASPETH VE	NW 1/4 - 1/2 (0.422 mi.)	AN234	1098
MAGNUM BODY SHOP INC	185A MASPETH AVE	NW 1/4 - 1/2 (0.422 mi.)	AN235	1099
U. S. WASTE MANAGEME	48 KNICKERBOCKER (69	SSW 1/4 - 1/2 (0.430 mi.)	236	1099
UNIVERSAL SCRAP PROC	***27 STEWART AVE***	***SSE 1/4 - 1/2 (0.441 mi.)***	***AO238***	***1102***
UNIVERSAL USED AUTO	***1175 FLUSHING AVE***	***SSE 1/4 - 1/2 (0.480 mi.)***	***248***	***1140***
COGENT TRANSFER; LLC	***105-115 THAMES STREE***	***S 1/4 - 1/2 (0.487 mi.)***	***250***	***1154***

Lower Elevation	Address	Direction / Distance	Map ID	Page
WMNY VARICK 1 TRANSF	***215 VARICK AVENUE***	***W 0 - 1/8 (0.015 mi.)***	***B15***	***34***

Lower Elevation	Address	Direction / Distance	Map ID	Page
WASTE MANAGEMENT OF	***232 GARDNER AVENUE***	***NNE 1/8 - 1/4 (0.138 mi.)***	***N106***	***352***
HI-TECH RESOURCE REC	130 VARICK AVENUE	S 1/8 - 1/4 (0.138 mi.)	M108	356
COOPER RECYCLING; LL	***123 VARICK AVENUE***	***S 1/8 - 1/4 (0.146 mi.)***	***M116***	***393***
WASTE MANAGEMENT OF	1301 METROPOLITAN AV	ENE 1/8 - 1/4 (0.149 mi.)	P120	423
EASTERN TRANSFER OF	***222 MORGAN AVE***	***W 1/8 - 1/4 (0.204 mi.)***	***V144***	***512***
NEWTOWN AUTO SALES &	***1074 GRAND STREET***	***W 1/8 - 1/4 (0.211 mi.)***	***W152***	***552***
AVALANCHE CONTRACTIN	46-26 METROPOLITAN A	ENE 1/8 - 1/4 (0.227 mi.)	U166	587
CHARLES J KING INC	***1301 GRAND ST***	***NE 1/8 - 1/4 (0.230 mi.)***	***167***	***588***
METRO AUTO SALVAGE	***4600 METROPOLITAN AV***	***E 1/8 - 1/4 (0.241 mi.)***	***U175***	***691***
FRITO-LAY	***202 MORGAN AVENUE***	***WSW 1/4 - 1/2 (0.262 mi.)***	***AB181***	***747***
T & T SCRAP LLC	***340 MASPETH AVENUE***	***NNW 1/4 - 1/2 (0.343 mi.)***	***AG196***	***824***
NEW YORK RECYCLERS;	340 MASPETH AVENUE	NNW 1/4 - 1/2 (0.343 mi.)	AG197	828
BCF OIL REFINING, IN	***360 MASPETH AVENUE***	***NNW 1/4 - 1/2 (0.351 mi.)***	***AG204***	***869***
FONTANA TRANSFER STA	252 MASPETH AVENUE	NW 1/4 - 1/2 (0.359 mi.)	AK211	915
M & C TRANSFER STATI	58-26 47 STREET	NE 1/4 - 1/2 (0.445 mi.)	AP240	1107
57-00 MASPETH AVE LL	***5700 47TH ST***	***NNE 1/4 - 1/2 (0.488 mi.)***	***AS251***	***1155***

Lists of state and tribal leaking storage tanks

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 08/09/2021 has revealed that there are 40 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CAL OSTLUND INC	***185 RANDOLPH ST***	***SE 1/4 - 1/2 (0.253 mi.)***	***AA179***	***705***
Spill Number/Closed Date: 0212548 / 2005-12-07				
Site ID: 120041				
Spill Date: 2003-03-20				
NEO RAY LIGHTING PRO	***537 JOHNSON AVENUE***	***SSE 1/4 - 1/2 (0.283 mi.)***	***AA187***	***779***
Spill Number/Closed Date: 8806105 / 1992-10-07				
Site ID: 155588				
Spill Date: 1988-10-19				
BROWNING FERRIS	***72 SCOTT AVE***	***ESE 1/4 - 1/2 (0.310 mi.)***	***AE190***	***800***
Spill Number/Closed Date: 9703477 / 1997-06-25				
Spill Number/Closed Date: 9708693 / 2004-10-20				
Site ID: 144360				
Site ID: 144361				
Spill Date: 1997-06-20				
Spill Date: 1997-10-24				
APT COMPLEX	349 SCHOLES ST	SW 1/4 - 1/2 (0.327 mi.)	AF193	820
Spill Number/Closed Date: 0300325 / 2004-03-24				
Site ID: 117954				
Spill Date: 2003-03-12				
345 TENEYCK STREET	345 TENEYCK STREET	W 1/4 - 1/2 (0.328 mi.)	194	821
Spill Number/Closed Date: 9210082 / 1992-12-01				

Site ID: 300237
Spill Date: 1992-12-01

JOYVA CORPORATION | 53 VARICK AVE | S 1/4 - 1/2 (0.344 mi.) | AI199 | 833
Spill Number/Closed Date: 0302698 / 2003-07-23
Site ID: 303353
Spill Date: 2003-06-13

CORNISH MINI MILLS | 121 INGRAHAM ST | S 1/4 - 1/2 (0.346 mi.) | AJ201 | 865
Spill Number/Closed Date: 9600503 / 1996-11-22
Site ID: 239705
Spill Date: 1996-04-11

ROLET FOOD PRODUCTS | 70 SCOTT AVE | SE 1/4 - 1/2 (0.352 mi.) | AE208 | 912
Spill Number/Closed Date: 0109443 / 2002-01-14
Site ID: 179351
Spill Date: 2001-12-26

UNOCCUPIED WAREHOUSE | 88 PORTER AVENUE | S 1/4 - 1/2 (0.352 mi.) | AJ209 | 913
Spill Number/Closed Date: 0210928 / 2014-11-19
Site ID: 209777
Spill Date: 2003-01-31

GREENPOINT | 287 MASPETH AVENUE | NNW 1/4 - 1/2 (0.359 mi.) | AH215 | 988
Spill Number/Closed Date: 9009058 / 2003-03-04
Spill Number/Closed Date: 9211562 / 2007-02-06
Site ID: 118273
Site ID: 181619
Spill Date: 1990-11-16
Spill Date: 1993-01-07

APARTMENT BUILDING | 35 MEADOW STREET | WSW 1/4 - 1/2 (0.368 mi.) | 223 | 1050
Spill Number/Closed Date: 0601731 / 2006-08-29
Site ID: 364030
Spill Date: 2006-05-16

LEWIS FLUSHING CORP. | 1819 FLUSHING AVENUE | ESE 1/4 - 1/2 (0.369 mi.) | AM224 | 1052
Spill Number/Closed Date: 8800833 / 1993-11-05
Site ID: 288930
Spill Date: 1988-04-27

F & W WOODWORK CO | 1267 FLUSHING AVE | SE 1/4 - 1/2 (0.379 mi.) | 226 | 1055
Spill Number/Closed Date: 9308847 / 1993-10-21
Site ID: 60933
Spill Date: 1993-10-21

DERBY TEXTILE CORPOR | 41 VARICK AVENUE | S 1/4 - 1/2 (0.380 mi.) | AI227 | 1062
Spill Number/Closed Date: 9713513 / 2004-08-18
Site ID: 331363
Spill Date: 1998-03-05

EMPIRE WAREHOUSE | 1312-1324 FLUSHING A | ESE 1/4 - 1/2 (0.387 mi.) | 229 | 1087
Spill Number/Closed Date: 9903972 / 2000-08-23
Site ID: 111006
Spill Date: 1999-07-06

CORNELL BEVERAGES IN | 105 HARRISON PLACE | S 1/4 - 1/2 (0.393 mi.) | AJ230 | 1089
Spill Number/Closed Date: 0706869 / 2008-10-17
Spill Number/Closed Date: 9610865 / 2008-10-17
Site ID: 387468
Site ID: 92955
Spill Date: 2007-09-20

Spill Date: 1996-12-03

308 MAUJER ST — 308 MAUJER ST — W 1/4 - 1/2 (0.393 mi.) — 231 — 1094
Spill Number/Closed Date: 0305120 / 2006-01-31
Site ID: 144741
Spill Date: 2003-08-14

47-40 METROPOLITAN A — 47-40 METROPOLITAN A — E 1/4 - 1/2 (0.443 mi.) — 239 — 1105
Spill Number/Closed Date: 9502665 / 2000-07-21
Site ID: 330742
Spill Date: 1995-06-01

18-51 FLUSHING AVE/Q — 18-51 FLUSHING AVENU — E 1/4 - 1/2 (0.454 mi.) — AQ243 — 1110
Spill Number/Closed Date: 9100841 / 2003-03-06
Site ID: 268451
Spill Date: 1991-04-22

1884 FLUSHING AVENUE — ***1884 FLUSHING AVENUE*** — ***E 1/4 - 1/2 (0.483 mi.)*** — ***AQ249*** — ***1151***
Spill Number/Closed Date: 9307524 / 1995-03-31
Site ID: 71544
Spill Date: 1993-09-21

881-889 GRAND STREET — ***885 GRAND ST*** — ***W 1/4 - 1/2 (0.492 mi.)*** — ***254*** — ***1166***
Spill Number/Closed Date: 8901284 / 2008-07-21
Site ID: 92038
Spill Date: 1989-05-09

Lower Elevation	Address	Direction / Distance	Map ID	Page
APT BUILDING TANK	85 MEADOW STREET	WSW 0 - 1/8 (0.069 mi.)	G54	178
Spill Number/Closed Date: 0504662 / 2005-12-09 Site ID: 349596 Spill Date: 2005-07-19				
NYC DEPART OF SANITA	***VARICK AVE***	***SSW 0 - 1/8 (0.077 mi.)***	***H64***	***231***
Spill Number/Closed Date: 0305740 / 2003-10-16 Site ID: 158270 Spill Date: 2003-08-29				
SUNSHINE BISCUITS IN	***1251 METROPOLITAN AV***	***NE 0 - 1/8 (0.079 mi.)***	***F67***	***244***
Spill Number/Closed Date: 8607890 / 1987-03-25 Site ID: 110767 Spill Date: 1987-03-24				
CONSOLIDATED CARPET	1157 GRAND ST	NNW 0 - 1/8 (0.117 mi.)	J86	293
Spill Number/Closed Date: 9511303 / 2006-02-07 Site ID: 193820 Spill Date: 1995-12-07				
1213 GRAND STREET	***1213 GRAND STREET***	***N 1/8 - 1/4 (0.143 mi.)***	***L115***	***389***
Spill Number/Closed Date: 9807882 / 2002-05-15 Site ID: 290514 Spill Date: 1998-09-28				
EASTERN TRANSFER OF	***222 MORGAN AVE***	***W 1/8 - 1/4 (0.204 mi.)***	***V144***	***512***
Spill Number/Closed Date: 0009585 / 2003-08-28 Spill Number/Closed Date: 9312206 / 1994-01-17 Site ID: 302888 Site ID: 302889 Spill Date: 2000-11-21 Spill Date: 1994-01-17				
EMEQUIFT CHEMICAL CO	100 VARICK AVE	S 1/8 - 1/4 (0.211 mi.)	T149	544

Spill Number/Closed Date: 0502445 / 2006-05-31
Site ID: 346803
Spill Date: 2005-05-31

CLOSED-LACKOF RECENT — 1105 METROPOLITAN AV — WNW 1/8 - 1/4 (0.217 mi.) — W158 — 564
Spill Number/Closed Date: 8802460 / 2003-03-05
Site ID: 183945
Spill Date: 1988-06-17

1101 METROPOLITAN AV — 1101 METROPOLITAN AV — WNW 1/8 - 1/4 (0.222 mi.) — 159 — 566
Spill Number/Closed Date: 9800642 / 2006-05-17
Site ID: 190461
Spill Date: 1998-04-15

GREEN HILL — 2 REWE ST & 300 VAND — WNW 1/4 - 1/2 (0.274 mi.) — 184 — 757
Spill Number/Closed Date: 0302094 / 2006-01-31
Site ID: 191858
Spill Date: 2003-05-29

YRC BROOKLYN (187) — ***1313 GRAND ST*** — ***NE 1/4 - 1/2 (0.275 mi.)*** — ***186*** — ***759***
Spill Number/Closed Date: 1004888 / 2013-02-22
Spill Number/Closed Date: 8708981 / 1992-10-07
Site ID: 438179
Site ID: 170911
Spill Date: 2010-07-30
Spill Date: 1988-01-21

140 MORGAN AVE/BROOK — ***140 MORGAN AVENUE*** — ***SW 1/4 - 1/2 (0.308 mi.)*** — ***AD188*** — ***797***
Spill Number/Closed Date: 8910515 / 1990-02-03
Site ID: 113471
Spill Date: 1990-01-30

100 MORGAN AVENUE — 100 MORGAN AVE — SW 1/4 - 1/2 (0.338 mi.) — AD195 — 822
Spill Number/Closed Date: 9909719 / 2000-11-20
Site ID: 328581
Spill Date: 1999-11-10

FEDEX FACILITY — ***300 MASPETH AVE*** — ***NNW 1/4 - 1/2 (0.343 mi.)*** — ***AH198*** — ***828***
Spill Number/Closed Date: 0204002 / 2005-12-22
Site ID: 291369
Spill Date: 2002-07-15

BCF OIL REFINING, IN — ***360 MASPETH AVENUE*** — ***NNW 1/4 - 1/2 (0.351 mi.)*** — ***AG204*** — ***869***
Spill Number/Closed Date: 9008251 / 2003-09-02
Spill Number/Closed Date: 9112627 / 2003-09-02
Site ID: 80010
Site ID: 211456
Spill Date: 1990-09-25
Spill Date: 1992-03-11

OFFICE BUILDING — 364 MASPETH AVE — N 1/4 - 1/2 (0.361 mi.) — AL220 — 1030
Spill Number/Closed Date: 2100155 / Not Reported
Site ID: 617823
Spill Date: 2021-04-06

DITMAS OIL ASSOCIATE — ***364 MASPETH AVENUE*** — ***N 1/4 - 1/2 (0.361 mi.)*** — ***AL221*** — ***1031***
Spill Number/Closed Date: 0514281 / 2006-04-24
Site ID: 360969
Spill Date: 2006-03-14

TRANSCON LINES TERMI — ***430 MASPETH AVE*** — ***NNE 1/4 - 1/2 (0.467 mi.)*** — ***245*** — ***1116***
Spill Number/Closed Date: 9206929 / 1997-07-03

Site ID: 260707
Spill Date: 1992-09-09

ISLAND TRANS CORP | 5700 47TH STREET | NNE 1/4 - 1/2 (0.488 mi.) | AS252 | 1164
Spill Number/Closed Date: 0709978 / 2007-12-28
Site ID: 391172
Spill Date: 2007-12-18

Lists of state and tribal registered storage tanks

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 20 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GRAND PETROLEUM, LLC Database: UST, Date of Government Version: 09/20/2021	1049 GRAND STREET	W 1/8 - 1/4 (0.232 mi.)	W168	600
RANDOLPH ASSOCIATES Database: UST, Date of Government Version: 09/20/2021	***165 RANDOLPH STREET***	***SE 1/8 - 1/4 (0.248 mi.)***	***AA177***	***697***

Lower Elevation	Address	Direction / Distance	Map ID	Page
VIJAX CORPORATION Database: UST, Date of Government Version: 09/20/2021	210 VARICK AVENUE	WNW 0 - 1/8 (0.024 mi.)	C19	41
RIGHT-WAY DEALER WAR Database: UST, Date of Government Version: 09/20/2021	***1202 METROPOLITAN AV***	***NNW 0 - 1/8 (0.048 mi.)***	***E32***	***71***
209 MORGAN AVE. CORP Database: UST, Date of Government Version: 09/20/2021	85 MEADOW STREET	WSW 0 - 1/8 (0.069 mi.)	G53	176
JJ KANG ENTERPRISE, Database: UST, Date of Government Version: 09/20/2021	1188 METROPOLITAN AV	NW 0 - 1/8 (0.071 mi.)	C58	184
DSNY BK DISTRICT 1/4 Database: UST, Date of Government Version: 09/20/2021	161 VARICK AVENUE	SSW 0 - 1/8 (0.077 mi.)	H65	235
SUNSHINE BISCUITS IN Database: UST, Date of Government Version: 09/20/2021	***1251 METROPOLITAN AV***	***NE 0 - 1/8 (0.079 mi.)***	***F67***	***244***
M. FINE LUMBER CO. I Database: UST, Date of Government Version: 09/20/2021	175 VARICK AVE	SW 0 - 1/8 (0.093 mi.)	G74	262
HI-TECH RESOURCE REC Database: UST, Date of Government Version: 09/20/2021	492 SCHOLES STREET	S 0 - 1/8 (0.116 mi.)	K83	281
1131 GRAND ET IAC Database: UST, Date of Government Version: 09/20/2021	1131 GRAND STREET	NW 0 - 1/8 (0.123 mi.)	I92	319
CONSOLIDATED CARPET Database: UST, Date of Government Version: 09/20/2021	1181 GRAND STREET	N 1/8 - 1/4 (0.132 mi.)	L101	333
ENGINE COMPANY 206 Database: UST, Date of Government Version: 09/20/2021	1201 GRAND STREET	N 1/8 - 1/4 (0.138 mi.)	L104	346
UNION BEER DIST. L.L Database: UST, Date of Government Version: 09/20/2021	1213-17 GRAND ST	N 1/8 - 1/4 (0.143 mi.)	L114	383

Lower Elevation	Address	Direction / Distance	Map ID	Page
1301 METROPOLITAN AV Database: UST, Date of Government Version: 09/20/2021	1301 METROPOLITAN AV	ENE 1/8 - 1/4 (0.149 mi.)	P121	424
L & H ASSOCIATES C/O Database: UST, Date of Government Version: 09/20/2021	1101-1107 METROPOLIT	WNW 1/8 - 1/4 (0.184 mi.)	O136	478
BLINN DRUG CO Database: UST, Date of Government Version: 09/20/2021	16 REWE ST	NW 1/8 - 1/4 (0.222 mi.)	X160	567
12 REWE STREET LLC Database: UST, Date of Government Version: 09/20/2021	12 REWE STREET	NW 1/8 - 1/4 (0.226 mi.)	X165	585
CHARLES J KING INC Database: UST, Date of Government Version: 09/20/2021	***1301 GRAND ST***	***NE 1/8 - 1/4 (0.230 mi.)***	***167***	***588***
8 REWE STREET, LLC Database: UST, Date of Government Version: 09/20/2021	8 REWE STREET	NW 1/8 - 1/4 (0.237 mi.)	170	627

NY MOSF UST: Major Oil Storage Facilities Database. Facilities are licensed pursuant to Article 12 of the Navigation Law, 6 NYCRR Part 610 and 17 NYCRR Part 30. These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater. Includes MOSF's licensed or closed since April 1, 1986, (responsibility was transferred from DOT on October 13, 1985) plus available data obtained from DOT facilities licensed since Article 12 became law on April 1, 1978.

A review of the NY MOSF UST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 4 NY MOSF UST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BAYSIDE FUEL OIL DEP	***1100 GRAND STREET***	***WNW 1/8 - 1/4 (0.142 mi.)***	***O113***	***373***

Lower Elevation	Address	Direction / Distance	Map ID	Page
MORGAN OIL TERMINALS	***200 MORGAN AVE***	***WSW 1/8 - 1/4 (0.237 mi.)***	***Z173***	***677***
BCF OIL REFINING, IN	***360 MASPETH AVENUE***	***NNW 1/4 - 1/2 (0.351 mi.)***	***AG204***	***869***
DITMAS OIL ASSOCIATE	***364 MASPETH AVENUE***	***N 1/4 - 1/2 (0.361 mi.)***	***AL219***	***1013***

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 09/20/2021 has revealed that there are 3 NY CBS sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ALFRED CHEMICAL CORP Facility Status: Unregulated/Closed CBS Number: 2-000023 CBS Number: 2-000037	***111 GARDNER AVE.***	***SE 1/8 - 1/4 (0.190 mi.)***	***S139***	***486***
ENEQUIST CHEMICAL CO Facility Status: Unregulated/Closed CBS Number: 2-000027	***100 VARICK AVENUE***	***S 1/8 - 1/4 (0.211 mi.)***	***T150***	***546***
METRO AUTO SALVAGE Facility Status: Unregulated/Closed	***4600 METROPOLITAN AV***	***E 1/8 - 1/4 (0.241 mi.)***	***U175***	***691***

EXECUTIVE SUMMARY

CBS Number: 2-000496

NY MOSF: These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

A review of the NY MOSF list, as provided by EDR, and dated 09/20/2021 has revealed that there are 5 NY MOSF sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BAYSIDE FUEL OIL DEP	***1100 GRAND ST***	***WNW 1/8 - 1/4 (0.142 mi.)***	***O111***	***365***
Tank Status: Active Facility Id: 2-1280				
GREENPOINT	***287 MASPETH AVENUE***	***NNW 1/4 - 1/2 (0.359 mi.)***	***AH215***	***988***
Tank Status: Unregulated/Closed Facility Id: 2-2340				

Lower Elevation	Address	Direction / Distance	Map ID	Page
NYC DEP HAZ MAT	***200 MORGAN AVENUE***	***WSW 1/8 - 1/4 (0.237 mi.)***	***Z171***	***629***
Tank Status: Inactive Facility Id: 2-1500				
BCF OIL REFINING, IN	***360 MASPETH AVENUE***	***NNW 1/4 - 1/2 (0.351 mi.)***	***AG204***	***869***
Tank Status: Inactive Facility Id: 2-2600				
DITMAS OIL ASSOCIATE	***364 MASPETH AVENUE***	***N 1/4 - 1/2 (0.361 mi.)***	***AL221***	***1031***
Tank Status: Unregulated/Closed Facility Id: 2-1340				

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 17 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BFI WASTE SERVICES O	594 SCHOLES STREET	E 1/8 - 1/4 (0.213 mi.)	Q154	556
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-604450				

Lower Elevation	Address	Direction / Distance	Map ID	Page
WASTE MANAGEMENT OF	215 VARICK AVENUE	W 0 - 1/8 (0.015 mi.)	B14	30
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-605532				
WASTE MANAGEMENT OF	221 VARICK AVENUE	W 0 - 1/8 (0.045 mi.)	B31	68
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-602605				
MANHATTAN POLY BAG C	***METROPOLITAN AVE***	***WNW 0 - 1/8 (0.059 mi.)***	***C42***	***96***
Database: AST, Date of Government Version: 09/20/2021				

Facility Id: 2-248746				
METRO GARAGE	***1188 METROPOLITAN AV***	***NW 0 - 1/8 (0.071 mi.)***	***C60***	***202***
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-602411				
ULTIMATE TRUCK & EQU	1157 GRAND STREET	NNW 0 - 1/8 (0.117 mi.)	J88	309
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-612699				
ENGINE COMPANY 206	1201 GRAND STREET	N 1/8 - 1/4 (0.138 mi.)	L105	349
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-601787				
WASTE MANAGEMENT OF	232 GARDNER AVENUE	NNE 1/8 - 1/4 (0.138 mi.)	N107	354
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-602602				
WASTE MANAGEMENT OF	123 VARICK AVENUE	S 1/8 - 1/4 (0.146 mi.)	M118	412
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-602618				
ALFRED CHEMICAL CORP	***111 GARDNER AVE.***	***SE 1/8 - 1/4 (0.190 mi.)***	***S139***	***486***
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-000037 Facility Id: 2-000023				
ROLLING FRITO-LAY SA	222 MORGAN AVENUE	W 1/8 - 1/4 (0.204 mi.)	V143	510
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-612410				
ENEQUIST CHEMICAL	100 VARICK AVENUE	S 1/8 - 1/4 (0.211 mi.)	T148	543
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-233072				
ENEQUIST CHEMICAL CO	***100 VARICK AVENUE***	***S 1/8 - 1/4 (0.211 mi.)***	***T150***	***546***
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-000027				
NEWTOWN USED AUTO PA	1074 GRAND STREET	W 1/8 - 1/4 (0.211 mi.)	W151	550
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-610198				
12 REWE STREET LLC	12 REWE STREET	NW 1/8 - 1/4 (0.226 mi.)	X164	583
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-608670				
CAPITAL AUTO SALVAGE	4600 METROPOLITAN AV	E 1/8 - 1/4 (0.241 mi.)	U174	687
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-608207				
METRO AUTO SALVAGE	***4600 METROPOLITAN AV***	***E 1/8 - 1/4 (0.241 mi.)***	***U175***	***691***
Database: AST, Date of Government Version: 09/20/2021 Facility Id: 2-000496				

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there are

2 NY CBS AST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ALFRED CHEMICAL CORP	***111 GARDNER AVE.***	***SE 1/8 - 1/4 (0.190 mi.)***	***S139***	***486***
Facility Status: 2				
Facility Status: 1				
CBS Number: 2-000023				
CBS Number: 2-000037				
ENEQUIST CHEMICAL CO	***100 VARICK AVE***	***S 1/8 - 1/4 (0.211 mi.)***	***T147***	***522***
Facility Status: 1				
Facility Status: 1				
CBS Number: 2-000027				

NY MOSF AST: Major Oil Storage Facilities Database. Facilities are licensed pursuant to Article 12 of the Navigation Law, 6 NYCRR Part 610 and 17 NYCRR Part 30. These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater. Includes MOSF's licensed or closed since April 1, 1986, (responsibility was transferred from DOT on October 13, 1985) plus available data obtained from DOT facilities licensed since Article 12 became law on April 1, 1978.

A review of the NY MOSF AST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 4 NY MOSF AST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BAYSIDE FUEL OIL DEP	***1100 GRAND STREET***	***WNW 1/8 - 1/4 (0.142 mi.)***	***O113***	***373***
Facility Status: 1				
Facility Status: 1				
Facility Status: 4				
GREENPOINT ENERGY FA	***287 MASPETH AVENUE***	***NNW 1/4 - 1/2 (0.359 mi.)***	***AH212***	***916***
Facility Status: 3				
Facility Status: 3				

Lower Elevation	Address	Direction / Distance	Map ID	Page
BCF OIL REFINING, IN	***360 MASPETH AVENUE***	***NNW 1/4 - 1/2 (0.351 mi.)***	***AG204***	***869***
Facility Status: 2				
Facility Status: 1				
DITMAS OIL ASSOCIATE	***364 MASPETH AVENUE***	***N 1/4 - 1/2 (0.361 mi.)***	***AL219***	***1013***
Facility Status: 1				
Facility Status: 3				

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 01/06/2022 has revealed that there are 3 NY ENG CONTROLS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CORNISH KNIT GOODS/C	***121 INGRAHAM ST./89***	***S 1/4 - 1/2 (0.346 mi.)***	***AJ200***	***834***

Site Code: 58133

88 INGRAHAM REALTY C	***88 INGRAHAM ST***	***SSW 1/4 - 1/2 (0.380 mi.)***	***228***	***1065***

Site Code: 58534

Lower Elevation	Address	Direction / Distance	Map ID	Page
FRITO LAY	***202-218 MORGAN AVENU***	***WSW 1/4 - 1/2 (0.262 mi.)***	***AB180***	***712***

Site Code: 407689

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 01/06/2022 has revealed that there are 3 NY INST CONTROL sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CORNISH KNIT GOODS/C	***121 INGRAHAM ST./89***	***S 1/4 - 1/2 (0.346 mi.)***	***AJ200***	***834***

Site Code: 58133

88 INGRAHAM REALTY C	***88 INGRAHAM ST***	***SSW 1/4 - 1/2 (0.380 mi.)***	***228***	***1065***

Site Code: 58534

Lower Elevation	Address	Direction / Distance	Map ID	Page
FRITO LAY	***202-218 MORGAN AVENU***	***WSW 1/4 - 1/2 (0.262 mi.)***	***AB180***	***712***

Site Code: 407689

Lists of state and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 6 NY VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CORNISH KNIT GOODS/C	***121 INGRAHAM ST./89***	***S 1/4 - 1/2 (0.346 mi.)***	***AJ200***	***834***

Database: VCP, Date of Government Version: 01/06/2022
Site Code: 58133

GREENPOINT	***287 MASPETH AVENUE***	***NNW 1/4 - 1/2 (0.359 mi.)***	***AH215***	***988***

Database: VCP, Date of Government Version: 01/06/2022
Site Code: 57149

88 INGRAHAM REALTY C	***88 INGRAHAM ST***	***SSW 1/4 - 1/2 (0.380 mi.)***	***228***	***1065***

Database: VCP, Date of Government Version: 01/06/2022
Site Code: 58534

FORMER JAYER PLATING	***2 INGRAHAM ST***	***SSW 1/4 - 1/2 (0.472 mi.)***	***AR246***	***1130***

Database: VCP, Date of Government Version: 01/06/2022
Site Code: 56868

Lower Elevation	Address	Direction / Distance	Map ID	Page
JOYVA VACANT LOT	498 JOHNSON AVENUE	S 1/4 - 1/2 (0.309 mi.)	AC189	799

Database: VCP, Date of Government Version: 01/06/2022

Site Code: 56948

BCF, 360 MASPETH AVE Database: VCP, Date of Government Version: 01/06/2022 Site Code: 56908	360 MASPETH AVENUE,	NNW 1/4 - 1/2 (0.351 mi.)	AG206	910

Lists of state and tribal brownfield sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 01/06/2022 has revealed that there are 6 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
255 RANDOLPH STREET Site Code: 534911	***255 RANDOLPH ST***	***ESE 1/4 - 1/2 (0.325 mi.)***	***AE191***	***816***
GREENPOINT Site Code: 57389	***287 MASPETH AVENUE***	***NNW 1/4 - 1/2 (0.359 mi.)***	***AH215***	***988***
FORMER UNIVERSAL SCR Site Code: 505316	***1181 FLUSHING AVENUE***	***SSE 1/4 - 1/2 (0.458 mi.)***	***AO244***	***1111***
FORMER JAYER PLATING Site Code: 567066 Site Code: 435675	***2 INGRAHAM ST***	***SSW 1/4 - 1/2 (0.472 mi.)***	***AR246***	***1130***

Lower Elevation	Address	Direction / Distance	Map ID	Page
FRITO LAY Site Code: 407689	***202-218 MORGAN AVENU***	***WSW 1/4 - 1/2 (0.262 mi.)***	***AB180***	***712***
46-81 METROPOLITAN A Site Code: 623115	46-81 METROPOLITAN A	E 1/4 - 1/2 (0.363 mi.)	222	1048

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

Registered Recycling Facility List from the Department of Environmental Conservation.

A review of the NY SWRCY list, as provided by EDR, and dated 09/30/2021 has revealed that there are 12 NY SWRCY sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ALLOCCO RECYCLING LT	***575 SCHOLES STREET***	***ESE 1/8 - 1/4 (0.172 mi.)***	***Q134***	***473***
MESEROLE STREET RECY	568 MESEROLE STREET	ESE 1/8 - 1/4 (0.208 mi.)	R145	517
BFI (598-636 SCHOLES	***598-636 SCHOLES STRE***	***E 1/8 - 1/4 (0.215 mi.)***	***Q157***	***563***
ALLOCCO RECYCLING (6	606 MESEROLE STREET	ESE 1/8 - 1/4 (0.241 mi.)	176	696
BROWNING FERRIS	***72 SCOTT AVE***	***ESE 1/4 - 1/2 (0.310 mi.)***	***AE190***	***800***
NATIONWIDE SCRAP LLC	18-19 FLUSHING AVENU	ESE 1/4 - 1/2 (0.404 mi.)	AM232	1095

Lower Elevation	Address	Direction / Distance	Map ID	Page
HI TECH HOLDINGS LLC	492 SCHOLES STREET	S 0 - 1/8 (0.116 mi.)	K82	280

Lower Elevation	Address	Direction / Distance	Map ID	Page
CHARLES J KING INC	***1301 GRAND ST***	***NE 1/8 - 1/4 (0.230 mi.)***	***167***	***588***
WASTE MANAGEMENT OF	***101 VARICK AVENUE***	***S 1/4 - 1/2 (0.266 mi.)***	***AC183***	***751***
COTOIA ENTERPRISES	46-26 METROPOLITAN A	E 1/4 - 1/2 (0.274 mi.)	185	758
NMS WASTE PAPER	***58-35 47TH STREET***	***NE 1/4 - 1/2 (0.452 mi.)***	***AP241***	***1107***
GPB WASTE NY DBA NY/	58-35 47TH STREET	NE 1/4 - 1/2 (0.452 mi.)	AP242	1109

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 08/09/2021 has revealed that there are 37 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VAULT 434	221 MEADOW STREET	0 - 1/8 (0.000 mi.)	A4	10
Spill Number/Closed Date: 0207116 / 2003-04-29				
Site ID: 149972				
Spill Date: 2002-10-09				
VAULT V560	221-41 MEADOW ST	0 - 1/8 (0.000 mi.)	A5	12
Spill Number/Closed Date: 0508686 / 2008-01-10				
Site ID: 354319				
Spill Date: 2005-10-20				
UNKNOWN - DRUM RUN	MEADOW STREET & STEW	E 0 - 1/8 (0.007 mi.)	A11	25
Spill Number/Closed Date: 1704150 / 2017-09-01				
Site ID: 555372				
Spill Date: 2017-07-27				
MANHOLE 57877	MEADOW ST/STEWART AV	E 0 - 1/8 (0.007 mi.)	A13	29
Spill Number/Closed Date: 9912167 / 2002-03-19				
Site ID: 195609				
Spill Date: 2000-01-21				
DIELECTRIC FLUID GOI	243 MEADOW STREET	E 0 - 1/8 (0.022 mi.)	A17	36
Spill Number/Closed Date: 0606519 / 2006-09-07				
Site ID: 369880				
Spill Date: 2006-09-07				
SB 55893	200 STEWART AVE	ESE 0 - 1/8 (0.034 mi.)	D25	55
Spill Number/Closed Date: 0403838 / 2004-10-04				
Site ID: 118871				
Spill Date: 2004-07-10				
CASILINO CONTRACTING	160 STEWART AVE	SE 0 - 1/8 (0.116 mi.)	K85	291
Spill Number/Closed Date: 9705382 / 1997-08-04				
Spill Number/Closed Date: 9706947 / 1997-11-13				
Site ID: 231976				
Site ID: 117602				
Spill Date: 1997-08-04				
Spill Date: 1997-09-11				

Lower Elevation	Address	Direction / Distance	Map ID	Page
TO ROADWAY	IFO 210 VARICK AVE	WNW 0 - 1/8 (0.024 mi.)	C20	43

Spill Number/Closed Date: 1411768 / 2015-03-17 Site ID: 505566 Spill Date: 2015-03-17				
COMMERCIAL BUILDING Spill Number/Closed Date: 1205626 / 2015-09-22 Site ID: 468588 Spill Date: 2011-07-20	210-222 VARICK AVENU	WNW 0 - 1/8 (0.024 mi.)	C21	44
NEW TOWN CREEK Spill Number/Closed Date: 0708123 / 2007-10-25 Site ID: 388965 Spill Date: 2007-10-25	225 VARICK AVE	WNW 0 - 1/8 (0.028 mi.)	C24	54
VARICK ST & MEADOW S Spill Number/Closed Date: 9606739 / 1998-05-13 Site ID: 324811 Spill Date: 1996-08-26	VARICK ST & MEADOW S	SW 0 - 1/8 (0.038 mi.)	B26	57
TRANSFORMER #2279/EM Spill Number/Closed Date: 0912190 / 2010-04-01 Site ID: 425064 Spill Date: 2010-02-22	231 VARICK ST	WNW 0 - 1/8 (0.041 mi.)	C28	58
ROADWAY - PARKING SP Spill Number/Closed Date: 1900848 / 2019-04-30 Site ID: 586692 Spill Date: 2019-04-24	222 VARRICK AVE	NW 0 - 1/8 (0.044 mi.)	C29	60
STORAGE BUILDING Spill Number/Closed Date: 9107650 / 1992-11-19 Spill Number/Closed Date: 9514664 / 1996-02-20 Site ID: 180407 Site ID: 180408 Spill Date: 1991-10-16 Spill Date: 1996-02-15	1194 METROPOLITAN AV	NW 0 - 1/8 (0.055 mi.)	C36	83
METRO Spill Number/Closed Date: 0206511 / 2003-10-20 Site ID: 99221 Spill Date: 2002-09-23	1188 METROPOLITAN AV	NW 0 - 1/8 (0.056 mi.)	C38	87
TRUCK IN CREEK Spill Number/Closed Date: 0708122 / 2007-11-06 Site ID: 388964 Spill Date: 2007-10-25	221 ZARICK AVENUE	WNW 0 - 1/8 (0.057 mi.)	C39	88
MANHATTAN POLYBAG CO Spill Number/Closed Date: 0609662 / 2009-07-28 Site ID: 373955 Spill Date: 2006-11-22	***1150 METROPOLITAN AV***	***WNW 0 - 1/8 (0.059 mi.)***	***C40***	***89***
LOT Spill Number/Closed Date: 1905844 / 2019-09-24 Site ID: 593894 Spill Date: 2019-09-05	1150 METROPOLITAN AV	WNW 0 - 1/8 (0.059 mi.)	C43	109
METROPOLITAN STEWART Spill Number/Closed Date: 9802640 / 1998-06-02 Site ID: 267906 Spill Date: 1998-05-30	METROPOLITAN STEWART	N 0 - 1/8 (0.065 mi.)	E48	165
1201 METROPOLITAN AV	1201 METROPOLITAN AV	NNW 0 - 1/8 (0.070 mi.)	E57	183

Spill Number/Closed Date: 0407964 / 2006-01-26
Site ID: 332541
Spill Date: 2004-10-18

METRO GARAGE	***1188 METROPOLITAN AV***	***NW 0 - 1/8 (0.071 mi.)***	***C60***	***202***

Spill Number/Closed Date: 0011310 / 2003-09-15
Spill Number/Closed Date: 0206038 / 2004-03-16
Spill Number/Closed Date: 0711153 / 2008-01-22
Spill Number/Closed Date: 0302832 / 2012-01-18
Site ID: 173941
Site ID: 173942
Site ID: 392573
Site ID: 99222
Spill Date: 2001-01-17
Spill Date: 2002-09-10
Spill Date: 2008-01-22
Spill Date: 2003-06-17

NYC DEPART OF SANITA	***VARICK AVE***	***SSW 0 - 1/8 (0.077 mi.)***	***H64***	***231***

Spill Number/Closed Date: 0201226 / 2006-03-29
Spill Number/Closed Date: 0204630 / 2003-02-13
Site ID: 164054
Site ID: 164055
Spill Date: 2002-05-02
Spill Date: 2002-08-01

GRAND STREET BRIDGE	METROPOLITAN AVE	WNW 0 - 1/8 (0.078 mi.)	I66	242

Spill Number/Closed Date: 9610924 / 1998-04-28
Spill Number/Closed Date: 9708562 / 1997-10-22
Site ID: 89187
Site ID: 89188
Spill Date: 1996-12-04
Spill Date: 1997-10-22

MANHOLE #15350	VARICK AVE & METROPO	NW 0 - 1/8 (0.082 mi.)	I68	248

Spill Number/Closed Date: 9906203 / 1999-11-10
Site ID: 64194
Spill Date: 1999-08-24

ROADWAY	METROPOLITAN AVE & V	NW 0 - 1/8 (0.082 mi.)	I69	249

Spill Number/Closed Date: 0811297 / 2009-01-14
Site ID: 408867
Spill Date: 2009-01-13

46-25 METROPOLITAN A	46025 METROPOLITAN A	NW 0 - 1/8 (0.087 mi.)	J72	256

Spill Number/Closed Date: 9204008 / 2013-10-28
Site ID: 84865
Spill Date: 1992-07-07

COMMERCIAL PROPERTY	175 VARICK AVE	SW 0 - 1/8 (0.093 mi.)	G73	257

Spill Number/Closed Date: 0601947 / 2011-11-18
Site ID: 364315
Spill Date: 2006-05-23

ROADWAY	METROPOLITAN/GARDNER	NE 0 - 1/8 (0.095 mi.)	F75	264

Spill Number/Closed Date: 9706343 / 1997-08-25
Site ID: 101342
Spill Date: 1997-08-25

NEW TOWN CREEK	GRANT & STEWART ST	N 0 - 1/8 (0.115 mi.)	L81	279

Spill Number/Closed Date: 9905180 / 1999-08-26

Site ID: 316312
Spill Date: 1999-07-30

ULTIMATE TRUCK & EQU Spill Number/Closed Date: 1611187 / 2017-07-24 Site ID: 542056 Spill Date: 2017-03-07	1157 GRAND STREET	NNW 0 - 1/8 (0.117 mi.)	J89	311
MANHOLE 1299 Spill Number/Closed Date: 0503634 / 2005-08-31 Site ID: 348262 Spill Date: 2005-06-27	1131 GRAND ST	NW 0 - 1/8 (0.123 mi.)	I93	321
VAULT 2597 Spill Number/Closed Date: 0312422 / 2004-07-15 Spill Number/Closed Date: 9702070 / 2003-02-24 Spill Number/Closed Date: 9710120 / 1997-12-05 Site ID: 299538 Site ID: 299539 Site ID: 299540 Spill Date: 2004-02-08 Spill Date: 1997-05-17 Spill Date: 1997-12-02	METROPOLITAN AV	WNW 0 - 1/8 (0.124 mi.)	I94	323
NEWTOWN CREEK Spill Number/Closed Date: 0011304 / 2003-12-23 Site ID: 274022 Spill Date: 2001-01-17	METROPOLITAN BRIDGE	WNW 0 - 1/8 (0.124 mi.)	I95	326
MANHOLE #36370 Spill Number/Closed Date: 9906205 / 1999-11-10 Site ID: 237077 Spill Date: 1999-08-24	GRAND ST/METROPOLITA	WNW 0 - 1/8 (0.124 mi.)	I96	327
METROPOLITAIN AVE & Spill Number/Closed Date: 9706334 / 1997-08-25 Site ID: 322309 Spill Date: 1997-08-25	METROPOLITAIN AVE &	WNW 0 - 1/8 (0.124 mi.)	I97	328
METROPOLITAN AVE BRI Spill Number/Closed Date: 0205135 / 2002-08-16 Site ID: 237049 Spill Date: 2002-08-15	METROPOLITAN AVENUE	WNW 0 - 1/8 (0.124 mi.)	I98	329
METROPOLITAN AVE BRI Spill Number/Closed Date: 0402660 / 2006-08-25 Site ID: 244729 Spill Date: 2004-06-04	OVER ENGLISH KILLS C	WNW 0 - 1/8 (0.124 mi.)	I99	330

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 09/13/2021 has revealed that

there are 37 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID:: NYP004738902	***STEWART AVE & MEADOW***	***E 0 - 1/8 (0.007 mi.)***	***A12***	***26***
CON EDISON EPA ID:: NYP004738878	***STEWART AVE & STAGG***	***SE 0 - 1/8 (0.054 mi.)***	***D34***	***79***
CON EDISON EPA ID:: NYP004738597	***179 STEWART AVE***	***SSE 0 - 1/8 (0.069 mi.)***	***D50***	***167***
NYC DEP EPA ID:: NYP003662772	***165 STEWART AVE***	***SSE 0 - 1/8 (0.105 mi.)***	***K80***	***276***
BAYSIDE FUEL OIL DEP EPA ID:: NYD980526420	***1100 GRAND ST***	***WNW 1/8 - 1/4 (0.142 mi.)***	***O110***	***360***
GREENWALD INDUSTRIES EPA ID:: NYD986931533	***1340 METROPOLITAN AV***	***E 1/8 - 1/4 (0.203 mi.)***	***U142***	***504***
ACME ALBERT STEEL DR EPA ID:: NYD000390716	***1050 GRAND ST***	***W 1/8 - 1/4 (0.224 mi.)***	***W163***	***575***
B P PRODUCTS NORTH A EPA ID:: NYR000126615	***1049 GRAND ST***	***W 1/8 - 1/4 (0.232 mi.)***	***W169***	***616***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID:: NYP004779559	VARICK AVE & MEADOW	WSW 0 - 1/8 (0.005 mi.)	B7	15
CON EDISON SERVICE B EPA ID:: NYP004532883	210 VARICK AVE	WNW 0 - 1/8 (0.024 mi.)	C23	51
WASTE MANAGEMENT OF EPA ID:: NYR000133298	***221 VARICK AVE***	***W 0 - 1/8 (0.045 mi.)***	***B30***	***61***
RIGHT-WAY DEALER WAR EPA ID:: NYR000025478	***1202 METROPOLITAN AV***	***NNW 0 - 1/8 (0.048 mi.)***	***E32***	***71***
MANHATTAN POLY BAG EPA ID:: NYD098227267	***1150 METROPOLITAN AV***	***WNW 0 - 1/8 (0.059 mi.)***	***C41***	***93***
AID AUTO STORES, INC EPA ID:: NYD058581497	***1150 METROPOLITAN AV***	***WNW 0 - 1/8 (0.059 mi.)***	***C44***	***110***
ALJO AUTO ELECTRIC C EPA ID:: NY0000575225	1250 METROPOLITAN AV	NE 0 - 1/8 (0.064 mi.)	F45	115
PATSON CORP EPA ID:: NYN008019051	***85 MEADOW ST***	***WSW 0 - 1/8 (0.069 mi.)***	***G52***	***172***
BUY RITE GARAGE INC EPA ID:: NYU005001680	***1188 METROPOLITAN AV***	***NW 0 - 1/8 (0.071 mi.)***	***C59***	***197***
SUNSHINE BISCUITS EPA ID:: NYD078159936	***1251 METROPOLITAN AV***	***NE 0 - 1/8 (0.086 mi.)***	***F71***	***251***
CON EDISON EPA ID:: NYP004186102	GARDNER AVE & METROP	NE 0 - 1/8 (0.097 mi.)	F77	268
CON EDISON EPA ID:: NYP004161857	***SCHOLES & VARICK***	***S 0 - 1/8 (0.103 mi.)***	***H79***	***272***
SYNTHETIC PROTECTIVE EPA ID:: NYD001282631	***492 SCHOLES ST***	***S 0 - 1/8 (0.116 mi.)***	***K84***	***285***
CONSOLIDATED CARPET	***1181 GRAND ST***	***N 1/8 - 1/4 (0.132 mi.)***	***L102***	***338***

EPA ID:: NYR000028340				
NYC FIRE DEPT ENGINE EPA ID:: NYR000040360	***1201 GRAND ST***	***N 1/8 - 1/4 (0.138 mi.)***	***L103***	***342***
HI-TECH RESOURCE REC EPA ID:: NYN008014441	130 VARICK AVE	S 1/8 - 1/4 (0.138 mi.)	M109	358
MIONE TRANSIT MIX EPA ID:: NYD157709486	***1301 METROPOLITAN AV***	***ENE 1/8 - 1/4 (0.149 mi.)***	***P119***	***419***
CON EDISON EPA ID:: NYP004741005	***VARICK AND MESEROLE***	***S 1/8 - 1/4 (0.152 mi.)***	***M124***	***450***
CON EDISON EPA ID:: NYP004839324	GARDNER AVE & GRAND	NNE 1/8 - 1/4 (0.154 mi.)	N127	457
CON EDISON EPA ID:: NYP004779476	***VARICK ST & MESEROLE***	***S 1/8 - 1/4 (0.155 mi.)***	***M132***	***466***
CON EDISON EPA ID:: NYP004779625	VARICK ST & MESEROLE	S 1/8 - 1/4 (0.155 mi.)	M133	470
CON ED - V 4628 EPA ID:: NYP004005286	***SCOTT AVE & METRO AV***	***ENE 1/8 - 1/4 (0.179 mi.)***	***P135***	***475***
ALFRED CHEMICAL CORP EPA ID:: NYR000062570	***111 GARDNER AVE***	***SE 1/8 - 1/4 (0.190 mi.)***	***S140***	***494***
WOOD-TEX PANELS INC EPA ID:: NYD001641489	***108 VARICK AVE***	***SSE 1/8 - 1/4 (0.199 mi.)***	***T141***	***498***
CON EDISON SERVICE B EPA ID:: NYP004330460	***ONDERDONK AVE & METR***	***ENE 1/8 - 1/4 (0.209 mi.)***	***U146***	***518***
A&I REALTY EPA ID:: NYR000233767	***20 REWE ST***	***NNW 1/8 - 1/4 (0.224 mi.)***	***Y161***	***569***
CHARLES J KING INC EPA ID:: NYD012573648	***1301 GRAND ST***	***NE 1/8 - 1/4 (0.230 mi.)***	***167***	***588***
MORGAN OIL TERMINALS EPA ID:: NYD074359472	***200 MORGAN AVE***	***WSW 1/8 - 1/4 (0.237 mi.)***	***Z173***	***677***
NEW YORK TELEPHONE C EPA ID:: NYD980755680	***15 REWE ST***	***NNW 1/8 - 1/4 (0.249 mi.)***	***Y178***	***700***

ROD: Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid the cleanup.

A review of the ROD list, as provided by EDR, and dated 10/20/2021 has revealed that there is 1 ROD site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NEWTOWN CREEK SUPERF	***NEWTOWN CRK - N LAT***	***NW 1/8 - 1/4 (0.150 mi.)***	***122***	***433***

FUELS PROGRAM: This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

A review of the FUELS PROGRAM list, as provided by EDR, and dated 08/13/2021 has revealed that there is 1 FUELS PROGRAM site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BAYSIDE FUEL OIL DEP Company Seq ID: 4980 Facility ID: 82643	***1100 GRAND ST***	***WNW 1/8 - 1/4 (0.142 mi.)***	***O112***	***372***

NY HSWDS: The List includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity The latest version of the study is frozen in time. The sites on the study will not automatically be made superfund sites, rather each site will be further evaluated for listing in the registry. So overtime they will be added to the registry or not.

A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there are 7 NY HSWDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GREENPOINT ENERGY FA Facility Id: HS2012	***287 MASPETH AVENUE***	***NNW 1/4 - 1/2 (0.359 mi.)***	***AH212***	***916***
BUG, MASPETH GATE ST	285 MASPETH AVENUE	NNW 1/4 - 1/2 (0.360 mi.)	AH216	1010
MORGAN TERMINAL	200 MORGAN AVE	SW 1/4 - 1/2 (0.371 mi.)	225	1053
BUG, EQUITY WORKS Facility Id: HS2009	MASPETH AND MORGAN A	WNW 1/4 - 1/2 (0.434 mi.)	AN237	1100
FORMER JAYER PLATING Facility Id: HS2044	2 INGRAHAM STREET	SSW 1/4 - 1/2 (0.472 mi.)	AR247	1139

Lower Elevation	Address	Direction / Distance	Map ID	Page
VARICK AVENUE Facility Id: HS2043	165 VARICK AVENUE	SSW 0 - 1/8 (0.070 mi.)	H56	181
TANKS-A-LOT COMPANY	362 MASPETH AVENUE	N 1/4 - 1/2 (0.348 mi.)	AG203	868

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 49 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID: NYP004186029	***MEADOW ST & STEWART***	***E 0 - 1/8 (0.007 mi.)***	***A9***	***19***
CON EDISON EPA ID: NYP004738902	STEWART AVE & MEADOW	E 0 - 1/8 (0.007 mi.)	A10	24
CONSOLIDATED EDISON	221 241 MEADOW ST V4	E 0 - 1/8 (0.019 mi.)	A16	35

EPA ID: NYP004103461				
CON EDISON - MANHOLE	***243 MEADOW STREET***	***E 0 - 1/8 (0.022 mi.)***	***A18***	***37***
EPA ID: NYP004297362				
CON EDISON	STEWART AVE & STAGG	SE 0 - 1/8 (0.054 mi.)	D33	78
EPA ID: NYP004738878				
CON EDISON	179 STEWART AVE	SSE 0 - 1/8 (0.069 mi.)	D51	171
EPA ID: NYP004738597				
CON EDISON - MANHOLE	169 GARDNER AVE	E 0 - 1/8 (0.085 mi.)	70	251
EPA ID: NYP004907632				
NYC DEP	***165 STEWART AVE***	***SSE 0 - 1/8 (0.105 mi.)***	***K80***	***276***
EPA ID: NYP003662772				
NYCDOT - METROPOLITA	***1109 METROPOLITAN AV***	***WNW 1/8 - 1/4 (0.151 mi.)***	***O123***	***441***
EPA ID: NYD987032364				
CON EDISON	585 MESSEROLE ST	ESE 1/8 - 1/4 (0.188 mi.)	R137	481
EPA ID: NYP004287686				
GREENWALD INDUSTRIES	***1340 METROPOLITAN AV***	***E 1/8 - 1/4 (0.203 mi.)***	***U142***	***504***
EPA ID: NYD986931533				
ACME ALBERT STEEL DR	***1050 GRAND ST***	***W 1/8 - 1/4 (0.224 mi.)***	***W163***	***575***
EPA ID: NYD000390716				
B P PRODUCTS NORTH A	***1049 GRAND ST***	***W 1/8 - 1/4 (0.232 mi.)***	***W169***	***616***
EPA ID: NYR000126615				

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
CON EDISON	VARICK AVE & MEADOW	WSW 0 - 1/8 (0.005 mi.)	B6	13
EPA ID: NYP004779559				
CON EDISON	210 VARICK AVE	WNW 0 - 1/8 (0.024 mi.)	C22	50
EPA ID: NYP004532883				
CON EDISON	OPP 180 VARICK AVE	SSW 0 - 1/8 (0.039 mi.)	B27	58
EPA ID: NYP004779555				
WASTE MANAGEMENT OF	***221 VARICK AVE***	***W 0 - 1/8 (0.045 mi.)***	***B30***	***61***
EPA ID: NYR000133298				
RIGHT-WAY DEALER WAR	***1202 METROPOLITAN AV***	***NNW 0 - 1/8 (0.048 mi.)***	***E32***	***71***
EPA ID: NYR000025478				
CON EDISON	FRONT OF 1196 METROP	NNW 0 - 1/8 (0.056 mi.)	C37	85
EPA ID: NYP004595328				
MANHATTAN POLYBAG CO	***1150 METROPOLITAN AV***	***WNW 0 - 1/8 (0.059 mi.)***	***C40***	***89***
EPA ID: NYD982272627				
MANHATTAN POLY BAG	***1150 METROPOLITAN AV***	***WNW 0 - 1/8 (0.059 mi.)***	***C41***	***93***
EPA ID: NYD098227267				
CONSOLIDATED PACKAGI	***1250 METROPOLITAN AV***	***NE 0 - 1/8 (0.064 mi.)***	***F46***	***118***
EPA ID: NYD986892412				
NYCDEP - GENERAL STO	***1201 METROPOLITAN AV***	***NNW 0 - 1/8 (0.073 mi.)***	***E61***	***217***
EPA ID: NYR000113217				
NYC DEPART OF SANITA	***VARICK AVE***	***SSW 0 - 1/8 (0.077 mi.)***	***H64***	***231***
EPA ID: NYR000109116				
SUNSHINE BISCUITS	***1251 METROPOLITAN AV***	***NE 0 - 1/8 (0.086 mi.)***	***F71***	***251***

EPA ID: NYD078159936				
CONSOLIDATED EDISON EPA ID: NYP004197893	GARDNER AVE & METROP	NE 0 - 1/8 (0.097 mi.)	F78	271
CON EDISON EPA ID: NYP004161857	***SCHOLES & VARICK***	***S 0 - 1/8 (0.103 mi.)***	***H79***	***272***
SYNTHETIC PROTECTIVE EPA ID: NYD001282631 EPA ID: NYP000776369	***492 SCHOLES ST***	***S 0 - 1/8 (0.116 mi.)***	***K84***	***285***
CON EDISON EPA ID: NYP004717112	FRONT OF 140 VARICK	S 0 - 1/8 (0.118 mi.)	M90	313
CON EDISON - MANHOLE EPA ID: NYP004296299	***1131 GRAND STREET***	***NW 0 - 1/8 (0.123 mi.)***	***I91***	***314***
CON EDISON EPA ID: NYP004710216	228 GARDNER AVE	NE 1/8 - 1/4 (0.129 mi.)	N100	332
CONSOLIDATED CARPET EPA ID: NYR000028340	***1181 GRAND ST***	***N 1/8 - 1/4 (0.132 mi.)***	***L102***	***338***
NYC FIRE DEPT ENGINE EPA ID: NYR000040360	***1201 GRAND ST***	***N 1/8 - 1/4 (0.138 mi.)***	***L103***	***342***
COOPER RECYCLING; LL EPA ID: NYP000889022	***123 VARICK AVENUE***	***S 1/8 - 1/4 (0.146 mi.)***	***M116***	***393***
WASTE MANAGEMENT OF EPA ID: NYD982744815	***123 VARICK AVE***	***S 1/8 - 1/4 (0.146 mi.)***	***M117***	***402***
NEWTOWN CREEK SUPERF EPA ID: NYN000206282	***NEWTOWN CRK - N LAT***	***NW 1/8 - 1/4 (0.150 mi.)***	***122***	***433***
CON EDISON EPA ID: NYP004839324	GARDNER AVE & GRAND	NNE 1/8 - 1/4 (0.154 mi.)	N125	454
CON EDISON EPA ID: NYP004779625	W SIDE VARICK ST	S 1/8 - 1/4 (0.155 mi.)	M129	461
CON EDISON EPA ID: NYP004779476	VARICK ST & MESEROLE	S 1/8 - 1/4 (0.155 mi.)	M131	465
CON ED - V 4628 EPA ID: NYP004005286	***SCOTT AVE & METRO AV***	***ENE 1/8 - 1/4 (0.179 mi.)***	***P135***	***475***
WOOD-TEX PANELS INC EPA ID: NYD001641489	***108 VARICK AVE***	***SSE 1/8 - 1/4 (0.199 mi.)***	***T141***	***498***
CON EDISON SERVICE B EPA ID: NYP004330460	***ONDERDONK AVE & METR***	***ENE 1/8 - 1/4 (0.209 mi.)***	***U146***	***518***
ENEQUIST CHEMICAL CO EPA ID: NYD002028827	***100 VARICK AVE***	***S 1/8 - 1/4 (0.211 mi.)***	***T147***	***522***
CON EDISON EPA ID: NYP004287884	VARICK AVE	S 1/8 - 1/4 (0.213 mi.)	T156	562
A&I REALTY EPA ID: NYR000233767	20 REWE ST	NNW 1/8 - 1/4 (0.224 mi.)	Y162	575
NYC DEP HAZ MAT EPA ID: NYP003662657	***200 MORGAN AVENUE***	***WSW 1/8 - 1/4 (0.237 mi.)***	***Z171***	***629***
CON EDISON EPA ID: NYP004718086	FRONT OF 200 MORGAN	WSW 1/8 - 1/4 (0.237 mi.)	Z172	676
MORGAN OIL TERMINALS	***200 MORGAN AVE***	***WSW 1/8 - 1/4 (0.237 mi.)***	***Z173***	***677***

EPA ID: NYD074359472

NEW YORK TELEPHONE C EPA ID: NYD980755680	***15 REWE ST***	***NNW 1/8 - 1/4 (0.249 mi.)***	***Y178***	***700***

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there are 2 PA MANIFEST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
WASTE MANAGEMENT OF Generator EPA Id: NYD982744815	***123 VARICK AVE***	***S 1/8 - 1/4 (0.146 mi.)***	***M117***	***402***
ENEQUIST CHEMICAL CO Generator EPA Id: NYD002028827	***100 VARICK AVE***	***S 1/8 - 1/4 (0.211 mi.)***	***T147***	***522***

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 13 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004738902	STEWART AVE & MEADOW	E 0 - 1/8 (0.007 mi.)	A8	18
CON EDISON EPA Id: NYP004186029	***MEADOW ST & STEWART***	***E 0 - 1/8 (0.007 mi.)***	***A9***	***19***
CON EDISON EPA Id: NYP004738878	STEWART AVE & STAGG	SE 0 - 1/8 (0.054 mi.)	D35	82
CON EDISON EPA Id: NYP004738597	179 STEWART AVE	SSE 0 - 1/8 (0.069 mi.)	D49	166
NYCDOT - METROPOLITA EPA Id: NYD987032364	***1109 METROPOLITAN AV***	***WNW 1/8 - 1/4 (0.151 mi.)***	***O123***	***441***
B P PRODUCTS NORTH A EPA Id: NYR000126615	***1049 GRAND ST***	***W 1/8 - 1/4 (0.232 mi.)***	***W169***	***616***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED PACKAGI EPA Id: NYD986892412	***1250 METROPOLITAN AV***	***NE 0 - 1/8 (0.064 mi.)***	***F47***	***122***
NYC DEP EPA Id: NYR000113217	1201 METROPOLITAN AV	NNW 0 - 1/8 (0.073 mi.)	E62	224
WASTE MANAGEMENT OF EPA Id: NYD982744815	***123 VARICK AVE***	***S 1/8 - 1/4 (0.146 mi.)***	***M117***	***402***
CON EDISON EPA Id: NYP004839324	GARDNER AVE & GRAND	NNE 1/8 - 1/4 (0.154 mi.)	N126	455
CON EDISON EPA Id: NYP004779625	W SIDE VARICK ST	S 1/8 - 1/4 (0.155 mi.)	M128	460
CON EDISON	VARICK & MESEROLE ST	S 1/8 - 1/4 (0.155 mi.)	M130	462

EPA Id: NYP004741039
EPA Id: NYP004741005

ENEQUIST CHEMICAL CO	***100 VARICK AVE***	***S 1/8 - 1/4 (0.211 mi.)***	***T147***	***522***

EPA Id: NYD002028827

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 3 EDR MGP sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
EQUITY WORKS	MASPETH AND VANDERVO	NW 1/4 - 1/2 (0.353 mi.)	AK210	915
GREENPOINT	287 MASPETH AVENUE	NNW 1/4 - 1/2 (0.359 mi.)	AH213	986
SCHOLES ST. STATION	SCHOLES ST 7 BOGART	SW 1/4 - 1/2 (0.360 mi.)	AF218	1013

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 12 records.

Site Name	Database(s)
MEEKER AVENUE PLUME	Proposed NPL, SEMS
BOX STREET GW	NY SHWS
INGRAHAM STREET SIDEWALK GW	NY SHWS
NORTH OF CORNISH KNIT GOODS	NY SHWS
JONES MOTORS	NY SHWS
MEEKER AVENUE PLUME TRACKDOWN	NY SHWS
MORGAN OIL TERMINAL	NY SHWS
K - SCHOLES ST. STATION	NY SHWS, NY BROWNFIELDS
WOLFF-ALPORT CHEMICAL COMPANY	NY SHWS
A&G USED AUTO PART D/B/A PARTS ARE	NY SWF/LF
EQUITY WORKS	NY VCP
SCHOLES ST. STATION	NY VCP

OVERVIEW MAP - 6826547.2S



0 1/4 1/2 1 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- County Boundary
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 213 Meadow Street	CLIENT: Langan Engineering
ADDRESS: 213 Meadow Street Brooklyn NY 11237	CONTACT: Molly Mattern
LAT/LONG: 40.713041 / 73.928211	INQUIRY #: 6826547.2s DATE: January 20, 2022 11:29 am

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 6826547.2S



0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- County Boundary
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 213 Meadow Street	CLIENT: Langan Engineering
ADDRESS: 213 Meadow Street Brooklyn NY 11237	CONTACT: Molly Mattern INQUIRY #: 6826547.2s
LAT/LONG: 40.713041 / 73.928211	DATE: January 20, 2022 11:30 am

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	1	0	0	NR	1
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	1	1	NR	NR	2
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	5	NR	NR	5
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		3	4	NR	NR	NR	7
RCRA-SQG	0.250		1	2	NR	NR	NR	3
RCRA-VSQG	0.250		5	0	NR	NR	NR	5
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		1	0	3	11	NR	15
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500	1	1	11	18	NR	NR	31
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		4	5	31	NR	NR	40
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		9	11	NR	NR	NR	20
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	2	2	NR	NR	4
NY CBS	0.250		0	3	NR	NR	NR	3
NY MOSF	0.500		0	2	3	NR	NR	5
NY AST	0.250		5	12	NR	NR	NR	17
NY CBS AST	0.250		0	2	NR	NR	NR	2
NY MOSF AST	0.500		0	1	3	NR	NR	4
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	3	NR	NR	3
NY INST CONTROL	0.500		0	0	3	NR	NR	3
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	6	NR	NR	6
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		0	0	6	NR	NR	6
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWRCY	0.500		1	5	6	NR	NR	12
NY SWTIRE	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	0.001		0	NR	NR	NR	NR	0
NY PFAS	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	0.001		0	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	0.001		0	NR	NR	NR	NR	0
LIENS 2	0.001		0	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
NY Spills	0.125	1	37	NR	NR	NR	NR	38
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		17	20	NR	NR	NR	37
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	1	0	0	NR	1
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	0.001	1	0	NR	NR	NR	NR	1
DOCKET HWC	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
ECHO	0.001	1	0	NR	NR	NR	NR	1
UXO	1.000		0	0	0	0	NR	0
FUELS PROGRAM	0.250		0	1	NR	NR	NR	1
NY AIRS	0.001		0	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	0	NR	NR	NR	0
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0
NY Financial Assurance	0.001		0	NR	NR	NR	NR	0
NY HSWDS	0.500		1	0	6	NR	NR	7
NY MANIFEST	0.250		25	24	NR	NR	NR	49
PA MANIFEST	0.250		0	2	NR	NR	NR	2
NJ MANIFEST	0.250		6	7	NR	NR	NR	13
NY SPDES	0.001		0	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	0.001		0	NR	NR	NR	NR	0
NY COOLING TOWERS	0.001		0	NR	NR	NR	NR	0
NY LEAD	0.001		0	NR	NR	NR	NR	0
MINES MRDS	0.001		0	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	3	0	NR	3
EDR Hist Auto	0.125		0	NR	NR	NR	NR	0
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	0.001		0	NR	NR	NR	NR	0
NY RGA LF	0.001	1	0	NR	NR	NR	NR	1
- Totals --		5	116	117	99	11	0	348

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **CASTLE SANITATION CORPORATION** **FINDS** **1026001446**
Target **213 MEADOW STREET** **ECHO** **N/A**
Property **BROOKLYN, NY 11237**

Site 1 of 14 in cluster A

Actual: **14 ft.**

FINDS:
Registry ID: 110070625464

Click Here:

Environmental Interest/Information System:
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1026001446
Registry ID:	110070625464
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070625464
Name:	CASTLE SANITATION CORPORATION
Address:	213 MEADOW STREET
City,State,Zip:	BROOKLYN, NY 11237

A2 **CASALINO INTERIOR DEMOLITION** **NY RGA LF** **S114955461**
Target **213 MEADOW ST** **N/A**
Property **BROOKLYN, NY**

Site 2 of 14 in cluster A

Actual: **14 ft.**

RGA LF:

2012	CASALINO INTERIOR DEMOLITION	213 MEADOW ST
2011	CASALINO INTERIOR DEMOLITION	213 MEADOW ST
2010	CASALINO INTERIOR DEMOLITION	213 MEADOW ST
2009	CASALINO INTERIOR DEMOLITION	213 MEADOW ST
2008	CASALINO INTERIOR DEMOLITION	213 MEADOW ST
2007	CASALINO INTERIOR DEMOLITION	213 MEADOW ST
2006	CASALINO INTERIOR DEMOLITION	213 MEADOW ST
2005	CASALINO INTERIOR DEMOLITION	213 MEADOW ST
2004	CASALINO INTERIOR DEMOLITION	213 MEADOW ST

A3 **CASALINO INTERIOR DEMOLITION** **NY SWF/LF** **S105841899**
Target **213 MEADOW ST** **NY Spills** **N/A**
Property **BROOKLYN, NY 11237**

Site 3 of 14 in cluster A

Actual: **14 ft.**

SWF/LF:

Name:	CASALINO INTERIOR DEMOLITION
Address:	213 MEADOW ST
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE

CASALINO INTERIOR DEMOLITION (Continued) **S105841899**

Region Code:	2
Phone Number:	7184782292
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	CASALINO; ANTHONY OWNER
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[24W33]
Active:	No
East Coordinate:	590550
North Coordinate:	4507452
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	2-6104-00009
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

SPILLS:

Name:	213 MEADOW ST.
Address:	213 MEADOW ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9315532 / 1994-03-31
Facility ID:	9315532
Facility Type:	ER
DER Facility ID:	177864
Site ID:	214676
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1994-03-31
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1994-03-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-03-31
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

CASALINO INTERIOR DEMOLITION (Continued) **S105841899**

Date Entered In Computer:	1994-04-05
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	WHALECO
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"SPILL CONTAINED ON CONCRETE PIER - CLEAN UP IN PROGRESS BY WHALECO."

All Materials:

Site ID:	214676
Operable Unit ID:	997568
Operable Unit:	01
Material ID:	387281
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A4
< 1/8
1 ft.

VAULT 434 **NY Spills** **S106008225**
221 MEADOW STREET **N/A**
BROOKLYN, NY

Site 4 of 14 in cluster A

Relative: Higher
Actual: 14 ft.

SPILLS:

Name:	VAULT 434
Address:	221 MEADOW STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0207116 / 2003-04-29
Facility ID:	0207116
Facility Type:	ER
DER Facility ID:	127541
Site ID:	149972
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	2002-10-09
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2002-10-09
CID:	204
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

VAULT 434 (Continued) **S106008225**

Date Entered In Computer:	2002-10-09
Spill Record Last Update:	2003-04-29
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	BILL MURPHY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY E2MIS NOTES 145505 10/9/02 - 1310 G. PALLADINO - 46015 - O.S. - BQE, REPORTS FINDING 10 GALS OF DIELECTRIC FLUID MIXED WITH SOIL ON THE CONCRETE FLOOR OF V 434 (5B27). OIL LEAKED FROM THE GROUND HANDLE & SECONDARY BUSHING OF THE TRANSFORMER. SPILL IS CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE INVOLVED. NO INJURIES RELATED TO THE SPILL. NO PRIVATE PROPERTY AFFECTED. NO SEWER CONNECTIONS. NO SUMPS. NO LARGE CRACKS IN THE STRUCTURE. HISTORICAL PCB COUNT OF THE UNIT IS 6 PPM FROM 1/18/99. PCB SAMPLE TAKEN. CHAIN OF CUSTODY FORM # CC09724 FILLED OUT AND MARKED 'E' (WITHIN 8 HRS) PRIORITY, CLEANUP TO BEGIN AS 50 - 499. J. GAGLIO OF E.H. & S. WAS INFORMED. TANKER ORDERED. EPA # ORDERED. ENV. OPS. INFORMED. TJ - 50495 UPDATE 10/9/02 15:55 HRS -- J. GAGLIO OF EH&S REPORTS TANKER IS REMOVING OIL FROM TRANSFORMER. NO SUMP IN STRUCTURE. WALKIN VAULT WITH OIL ON PAD -- NO ACTIVE LEAK. CLEANUP BEING DONE 50-499 PPM. THIS WILL BE A PARTIAL CLEANUP DUE TO ASBESTOS ABATEMENT REQUIRED IN STRUCTURE. UPDATE: 10/9/02 - 1654 W. THORNGREN - EQ GP, REPORTS TANKER REMOVED 425 GALS OF OIL FROM THE TRANSFORMER. TRANSFORMER HOLDS 427 GALS. 2 GALS LEAKED INTO VAULT. UPDATE 10/9/02 16:55 HRS. -- J. GAGLIO OF EH&S REPORTS CORPORATE TRANSPORATION WILL FAX MANIFEST TO E.R.T. TONIGHT. ROBERTO DIAZ OF D.E.P. REQUESTED COPIES OF E2MIS REPORT, CHEM LAB RESULTS, CLEANUP DOCUMENTATION AND DOCUMENTATION REGARDING ASBESTOS ABATEMENT AND TRANSFORMER REMOVAL. ENV. TAG TO REMAIN PENDING ASBESTOS ABATEMENT AND REMOVAL OF TRANSFORMER. SAMPLE WAS SENT TO CHEM LAB ABOUT 20 MIN. AGO. D.E.P. IS STILL ON SITE AT THIS TIME. - UPDATE 10/9/02 18:40 HRS. -- JOHN GAGLIO OF REPORTS TINO FERNANDEZ OF BROOKLYN ENV. OPS. GAVE D.E.P. OUR CLEANUP PLAN WHICH ISTAKE UP ANY SOIL AND CLEAN DOWN UNTIL THEY SEE NO MORE SIGNS OF OIL AND DOUBLE WASH THE SECTION OF PAD AFFECTED BY 2-GAL. SPILL. EVERYTHING TO BE HANDLED AS 50-499 PPM DUE TO SAMPLE GETTING OUT LATE TO CHEM LAB. UPDATE @ 1857 HRS 10/9 LAB RESULTS RECEIVED SEQ #02-09499-001 @ 4PPM. UPDATE @ 1930 HRS 10/9 C.FERNANDEZ REPORTS CREW SCRAPPED & WASHED SIDE OF TRANSFORMER WITH RAGS & BIO GEN, DUG OUT 6 OF OIL SOAKED DIRT CREATING ONE BARREL OF WASTE. PLACED MAT & BALONIES AROUND TRANSFORMER TO PREVENT FURTHER LEAKAGE. PARTIAL CLEANUP COMPLETED. COMPLETION PENDING ASBESTOS ABATMENT & REMOVAL OF TRANSFORMER. DEBRIS BROUGHT BACK UNDER ONE TRIP RULE. UPDATE 11/25/02 AT MORNING MEETING EQUIP PLANNER PETE MLADINICH STATED THE ASBESTOS ABATEMENT WAS COMPLETED OVER THE WEEKEND. UPDATE 11/26/02 17:40 HRS. -- G. PALLADINO OF NETWORKS REPORTS TRANSFORMER WAS REMOVED FROM VAULT. JOB NOW PENDING FINAL CLEANUP. UPDATE: 11/26/02 - 2200 R. ESPONDA - ENV. OPS., REPORTS CLEANUP COMPLETED BY DOUBLE WASHING STRUCTURE WITH BIO GEN 760. WASTE PRODUCT REMOVED WITH VACTOR. NO SUMP."
Remarks:	"CON ED 145505 OIL LEAKED FROM TRANSFORMER - HISTORICAL PCB RECORD - TEST DATE 1/18/99 - NEW SAMPLE TAKEN "

All Materials:

Site ID:	149972
Operable Unit ID:	859934
Operable Unit:	01
Material ID:	517701

VAULT 434 (Continued) **S106008225**

Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A5 **VAULT V560** **NY Spills** **S107416222**
221-41 MEADOW ST **N/A**
< 1/8 **BROOKLYN, NY**
1 ft.

Site 5 of 14 in cluster A

Relative: **Higher**
Actual: **14 ft.**

SPILLS:

Name:	VAULT V560
Address:	221-41 MEADOW ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0508686 / 2008-01-10
Facility ID:	0508686
Facility Type:	ER
DER Facility ID:	301659
Site ID:	354319
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-10-20
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2005-10-20
CID:	77
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-10-20
Spill Record Last Update:	2008-01-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	ERT DESK'
DEC Memo:	"01/10/08 - See eDocs for Con Ed report detailing cleanup and closure. 161566. 10/20/05 - 0145. A. WALKER - 33596 - FOD, WHILE PLACING GROUNDS ON FDR 5B28 (ACCT: C3242), REPORTS FINDING APPROX 1 QT OF AN UNKNOWN OIL MIXED WITH LEAVES ON THE CONCRETE FLOOR OF WALK IN V560. SPILL IS CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE INVOLVED. NO INJURIES. NO PRIVATE PROPERTY AFFECTED. NO SEWER CONNECTIONS. NO SUMPS OR DRAINS. NO PARKING RESTRICTIONS POSTED. HISTORICAL PCB COUNT OF UNIT IS 2 PPM DTD 2/18/03. BQE WILL

VAULT V560 (Continued) **S107416222**

BE ASKED TO PRESSURE TEST UNIT IN MORNING. ENV TAG # 48743 PLACED IN STRUCTURE. PCB SAMPLE TAKEN. CHAIN OF CUSTODY FORM # DD18918 FILLED OUT AND MARKED 'E' PRIORITY. CLEANUP PENDING LAB RESULT. TJ - 50495 "

Remarks: "1/4 qt of unkn oil in vault onto concrete floor. clean-up pending lab results. con ed ref 161566. no to 5 qusetions."

All Materials:

Site ID:	354319
Operable Unit ID:	1111738
Operable Unit:	01
Material ID:	2101785
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B6 **CON EDISON** **NY MANIFEST** **S121967312**
WSW **VARICK AVE & MEADOW ST** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.005 mi.
29 ft. **Site 1 of 8 in cluster B**

Relative: **Lower**

Actual: **12 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	VARICK AVE & MEADOW ST
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP004779559
Facility Status:	Not reported
Location Address 1:	W SIDE VARICK ST & STAGG ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004779559
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported

CON EDISON (Continued) **S121967312**

Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/2015
Trans1 Recv Date:	05/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/07/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004779559
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002624292GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B7 **CON EDISON** **RCRA NonGen / NLR** **1019324939**
WSW **VARICK AVE & MEADOW ST** **NYP004779559**
< 1/8 **BROOKLYN, NY 11237**
0.005 mi.
29 ft. **Site 2 of 8 in cluster B**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150506
Handler Name:	CON EDISON	
Handler Address:		VARICK AVE & MEADOW ST
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYP004779559
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1019324939**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON CO OF NY INC
Legal Status:	Private
Date Became Current:	20150506
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PL
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON CO OF NY INC
Legal Status:	Private

CON EDISON (Continued) **1019324939**

Date Became Current: 20150506
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - MANHOLE 43886
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150506
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150506
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

CON EDISON (Continued) **1019324939**

Evaluation Action Summary:
Evaluations: No Evaluations Found

A8 **CON EDISON** **NJ MANIFEST** **S120667930**
East **STEWART AVE & MEADOW AVE** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.007 mi.
37 ft. **Site 6 of 14 in cluster A**

Relative:
Higher

Actual:
14 ft.

NJ MANIFEST:

EPA Id:	NYP004738902
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610323GBF
EPA ID:	NYP004738902
Date Shipped:	2/26/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

CON EDISON (Continued) **S120667930**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

A9 **CON EDISON** **RCRA-VSQG 1014396338**
East **MEADOW ST & STEWART AVE** **NY MANIFEST NYP004186029**
< 1/8 **BROOKLYN, NY 11237** **NJ MANIFEST**
0.007 mi.
37 ft. **Site 7 of 14 in cluster A**

Relative: **Higher**
Actual: **14 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		MEADOW ST & STEWART AVE
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYP004186029
Contact Name:		CAROLINE ISKANDER
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		718-666-4714
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No

CON EDISON (Continued) **1014396338**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160707
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090723
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CON EDISON (Continued) **1014396338**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160601
Handler Name: CON EDISON
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: MEADOW ST & STEWART AVE
City,State,Zip: BROOKLYN, NY 11237
Country: USA
EPA ID: NYP004186029
Facility Status: Not reported
Location Address 1: MH57876 MEADOW ST & STEWART
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004186029
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

CON EDISON (Continued) **1014396338**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/10/2009
Trans1 Recv Date:	08/10/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/12/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004186029
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000894851GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYP004186029
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported

CON EDISON (Continued) **1014396338**

Contact:	CAROLINE ISKANDER
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	000894851GBF
EPA ID:	NYP004186029
Date Shipped:	08/10/2009
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/10/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/12/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111

CON EDISON (Continued) **1014396338**

Quantity: 100 G

A10 **CON EDISON** **NY MANIFEST** **S117740710**
East **STEWART AVE & MEADOW AVE** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.007 mi.
37 ft. **Site 8 of 14 in cluster A**

Relative:
Higher

Actual:
14 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	STEWART AVE & MEADOW AVE
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP004738902
Facility Status:	Not reported
Location Address 1:	NWC STAGG ST & MEADOW AVE
Code:	BP
Location Address 2:	M 57877
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004738902
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/26/2015
Trans1 Recv Date:	02/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004738902
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported

CON EDISON (Continued) **S117740710**

Manifest Tracking Number:	002610323GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	2000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A11 **UNKNOWN - DRUM RUN** **NY Spills** **S121100931**
East **MEADOW STREET & STEWART AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.007 mi.
37 ft. **Site 9 of 14 in cluster A**

Relative: **Higher**
Actual: **14 ft.**

SPILLS:

Name:	UNKNOWN - DRUM RUN
Address:	MEADOW STREET & STEWART AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1704150 / 2017-09-01
Facility ID:	1704150
Facility Type:	ER
DER Facility ID:	508940
Site ID:	555372
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C2
SWIS:	2401
Spill Date:	2017-07-27
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2017-07-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial

UNKNOWN - DRUM RUN (Continued) **S121100931**

Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-07-27
Spill Record Last Update:	2017-09-01
Spiller Name:	VICTOR
Spiller Company:	UNKNOWN
Spiller Address:	MEADOW STREET
Spiller Company:	999
Contact Name:	VICTOR
DEC Memo:	"07/27/17-Hiralkumar Patel. 2:56 PM:- spoke with Victor. he mentioned that multiple smaller containers of waste oil were overpacked into one 55 gal drum. drum is along Meadow St sidewalk between Stewart Ave and Gardner Ave. 9/1/17- DEC Piper - Drum not found as part of 9/1/17 drum run. Spill closed. "
Remarks:	"55 gallon drum needs pick up. material has been packed."

All Materials:

Site ID:	555372
Operable Unit ID:	1303411
Operable Unit:	01
Material ID:	2309994
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

A12 **CON EDISON** **RCRA NonGen / NLR** **1018279092**
East **STEWART AVE & MEADOW AVE** **FINDS** **NYP004738902**
< 1/8 **BROOKLYN, NY 11237** **ECHO**
0.007 mi.
37 ft. **Site 10 of 14 in cluster A**

Relative: **Higher**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150226
Handler Name:	CON EDISON	
Handler Address:		STEWART AVE & MEADOW AVE
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYP004738902
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified

CON EDISON (Continued) **1018279092**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

CON EDISON (Continued) **1018279092**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150226
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150226
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067685856

Click Here:

Environmental Interest/Information System:

CON EDISON (Continued) **1018279092**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279092
Registry ID:	110067685856
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067685856
Name:	CON EDISON
Address:	STEWART AVE & MEADOW AVE
City,State,Zip:	BROOKLYN, NY 11237

A13 **MANHOLE 57877** **NY Spills** **S104509296**
East **MEADOW ST/STEWART AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.007 mi.
38 ft. **Site 11 of 14 in cluster A**

Relative: **Higher**

Actual: **14 ft.**

SPILLS:

Name:	MANHOLE 57877
Address:	MEADOW ST/STEWART AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9912167 / 2002-03-19
Facility ID:	9912167
Facility Type:	ER
DER Facility ID:	162970
Site ID:	195609
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2000-01-21
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-01-21
CID:	382
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-21
Spill Record Last Update:	2002-03-19
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	STEVEN CRIBBIN

MANHOLE 57877 (Continued) **S104509296**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL "
Remarks: "1/2 QT UNKNOWN OIL ON 100 GALS OF WATER CONTAINED IN MANHOLE. CLEAN UP PENDING. CON ED 129-702"

All Materials:
Site ID: 195609
Operable Unit ID: 1090869
Operable Unit: 01
Material ID: 294060
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

B14 **WASTE MANAGEMENT OF NEW YORK, LLC** **NY AST** **A100175767**
West **215 VARICK AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.015 mi.
77 ft. **Site 3 of 8 in cluster B**

Relative: **Lower**
Actual: **11 ft.**

AST:
Name: WASTE MANAGEMENT OF NEW YORK, LLC
Address: 215 VARICK AVENUE
City,State,Zip: BROOKLYN, NY 11237
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-605532
Program Type: PBS
UTM X: 590414.75804
UTM Y: 4507453.86839
Expiration Date: 03/29/2026
Site Type: Other

Affiliation Records:
Site Id: 27399
Affiliation Type: Facility Owner
Company Name: WASTE MANAGEMENT OF NEW YORK LLC
Contact Type: ENVIRONMENTAL MANAGER
Contact Name: JAY KAPLAN
Address1: 123 VARICK AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11237
Country Code: 001
Phone: (718) 533-5310
EMail: Not reported
Fax Number: Not reported
Modified By: BKFALVEY
Date Last Modified: 2011-04-28

Site Id: 27399

WASTE MANAGEMENT OF NEW YORK, LLC (Continued) **A100175767**

Affiliation Type:	Facility Operator
Company Name:	WASTE MANAGEMENT OF NEW YORK, LLC
Contact Type:	Not reported
Contact Name:	PETER DELUCA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 533-5266
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BKFALVEY
Date Last Modified:	2011-04-28

Site Id:	27399
Affiliation Type:	Emergency Contact
Company Name:	WASTE MANAGEMENT OF NEW YORK LLC
Contact Type:	Not reported
Contact Name:	JAY KAPLAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 773-1814
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BKFALVEY
Date Last Modified:	2011-04-28

Site Id:	27399
Affiliation Type:	Mail Contact
Company Name:	WASTE MANAGEMENT OF NEW YORK, LLC
Contact Type:	ENVIRONMENTAL MANAGER
Contact Name:	JAY KAPLAN
Address1:	123 VARICK AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 533-5310
EMail:	JKAPLAN2@WM.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-11-12

Tank Info:

Tank Number:	001
Tank Id:	60012
Material Code:	0008
Common Name of Substance:	Diesel

WASTE MANAGEMENT OF NEW YORK, LLC (Continued) **A100175767**

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
E01 - Piping Secondary Containment - Diking (AG only)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/1990
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	002
Tank Id:	60013
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

K99 - Spill Prevention - Other
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1990
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported

WASTE MANAGEMENT OF NEW YORK, LLC (Continued) **A100175767**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	waste oil/used oil
Tank Number:	003
Tank Id:	60014
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
K99 - Spill Prevention - Other
L09 - Piping Leak Detection - Exempt Suction Piping
E01 - Piping Secondary Containment - Diking (AG only)
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
D11 - Pipe Type - Flexible Piping

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1990
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	lube oil
Tank Number:	004
Tank Id:	231439
Material Code:	0010
Common Name of Substance:	Hydraulic Oil

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
E01 - Piping Secondary Containment - Diking (AG only)
D11 - Pipe Type - Flexible Piping
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping

WASTE MANAGEMENT OF NEW YORK, LLC (Continued) **A100175767**

J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/15/1997
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	hydraulic oil

B15 **WMNY VARICK 1 TRANSFER STATION** **NY SWF/LF** **S102632777**
West **215 VARICK AVENUE** **NY Financial Assurance** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.015 mi.
77 ft. **Site 4 of 8 in cluster B**

Relative: **Lower**
Actual: **11 ft.**

SWF/LF:

Name:	WMNY VARICK 1 TRANSFER STATION
Address:	215 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	ACTIVE
Region Code:	2
Phone Number:	7185335266
Owner Name:	Waste Management of NY; LLC
Owner Type:	Private
Owner Address:	215 Varick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11237
Owner Email:	Not reported
Owner Phone:	7185335310
Contact Name:	Jay Kaplan
Contact Address:	215 Varick Avenue
Contact Addr2:	Not reported
Contact City,St,Zip:	Brooklyn, NY 11237
Contact Email:	jkaplan2@wm.com
Contact Phone:	7185335310
Activity Desc:	Transfer station - permit
Activity Number:	[24T66]
Active:	Yes
East Coordinate:	590448
North Coordinate:	4507405
Accuracy Code:	4.2 - Utilization of GIS and existing spatial data
Regulatory Status:	SAPA
Waste Type:	Yard Waste;MSW (Residential/Institutional & Commercial)
Authorization #:	2-6104-00010/00002
Authorization Date:	10/30/2018
Expiration Date:	10/21/2019

WMNY VARICK 1 TRANSFER STATION (Continued) **S102632777**

Operator Name: Waste Management of NY; LLC
Operator Type: Private
Laste Date: Not reported

NY Financial Assurance 1:
Name: WMNY VARICK 1 TRANSFER STATION
Address: 215 VARICK AVENUE
City,State,Zip: BROOKLYN, NY
Owner Name: Waste Management of NY; LLC
Region: 2
Estimate Type: Closure
Estimate Amount: 705,500
Estimate Date: 03/01/2001
Mechanism: Surety bond - Performance
Mechanism Amount: 962,450
Issue Date: 02/09/2004
Activity Number: 24T66
Activity Description: z Retired - Transfer station - permit

A16 **CONSOLIDATED EDISON** **NY MANIFEST** **1009241817**
East **221 241 MEADOW ST V434** **N/A**
< 1/8 **BROOKLYN, NY 11201**
0.019 mi.
101 ft. **Site 12 of 14 in cluster A**

Relative:
Higher

Actual:
14 ft.

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 221 241 MEADOW ST V434
City,State,Zip: BROOKLYN, NY 11201
Country: USA
EPA ID: NYP004103461
Facility Status: Not reported
Location Address 1: 221 241 MEADOW ST V434
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004103461
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

A17 **DIELECTRIC FLUID GOING INTO SEWER** **NY Spills** **S108130677**
East **243 MEADOW STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.022 mi.
114 ft. **Site 13 of 14 in cluster A**

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name:	DIELECTRIC FLUID GOING INTO SEWER
Address:	243 MEADOW STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0606519 / 2006-09-07
Facility ID:	0606519
Facility Type:	ER
DER Facility ID:	319744
Site ID:	369880
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-09-07
Investigator:	GDBREEN
Referred To:	Not reported
Reported to Dept:	2006-09-07
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-09-07
Spill Record Last Update:	2006-09-08
Spiller Name:	Not reported
Spiller Company:	CON ED CUSTOMER
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERTS
DEC Memo:	"202322. see eDocs Referred to spills for follow-up. Breen"
Remarks:	"SOME REACHED UNKNOWN HOW MUCH STILL INVESTIGATING: OWNED BY ANOTHER COMPANY. 202322"

All Materials:

Site ID:	369880
Operable Unit ID:	1127707
Operable Unit:	01
Material ID:	2117308
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A18 **CON EDISON - MANHOLE 57876** **RCRA-LQG** **1016450709**
East **243 MEADOW STREET** **FINDS** **NYP004297362**
< 1/8 **BROOKLYN, NY 11237** **ECHO**
0.022 mi. **NY MANIFEST**
114 ft. **Site 14 of 14 in cluster A**

Relative: **Higher**
Actual: **14 ft.**

RCRA-LQG:

Date Form Received by Agency:	20140407
Handler Name:	CON EDISON - MANHOLE 57876
Handler Address:	243 MEADOW STREET
Handler City,State,Zip:	BROOKLYN, NY 11237
EPA ID:	NYP004297362
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	401-765-1500
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON - MANHOLE 57876 (Continued) **1016450709**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130329
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private

CON EDISON - MANHOLE 57876 (Continued) **1016450709**

Date Became Current: 20130329
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140407
Handler Name: CON EDISON - MANHOLE 57876
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130329
Handler Name: CON EDISON MANHOLE: 57876
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130429
Handler Name: CON EDISON MANHOLE: 57876
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

CON EDISON - MANHOLE 57876 (Continued) **1016450709**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110055936509

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016450709
Registry ID:	110055936509
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055936509
Name:	CON EDISON - MANHOLE 57876
Address:	243 MEADOW STREET
City,State,Zip:	BROOKLYN, NY 11237

NY MANIFEST:

Name:	CON EDISON MANHOLE: 57876
Address:	243 MEADOW ST
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP004297362
Facility Status:	Not reported
Location Address 1:	243 MEADOW STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004297362
Mailing Name:	CON EDISON MANHOLE: 57876
Mailing Contact:	CON ED
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

C19
WNW
< 1/8
0.024 mi.
128 ft.

VIJAX CORPORATION
210 VARICK AVENUE
BROOKLYN, NY 11237

Site 1 of 20 in cluster C

NY UST **U001832798**
N/A

Relative:
Lower

Actual:
11 ft.

UST:

Name:	VIJAX CORPORATION
Address:	210 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Id/Status:	2-080454 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590422.37837
UTM Y:	4507509.01297
Site Type:	Other

Affiliation Records:

Site Id:	1615
Affiliation Type:	Facility Owner
Company Name:	VIJAX CORPORATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	210 VARICH AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 497-4491
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1615
Affiliation Type:	Mail Contact
Company Name:	VIJAX CORPORATION
Contact Type:	Not reported
Contact Name:	RONALD CATOGGIO
Address1:	210 VARICH AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 497-4491
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1615
Affiliation Type:	Facility Operator
Company Name:	VIJAX CORPORATION
Contact Type:	Not reported
Contact Name:	ANTHONY LOSQUADRO
Address1:	Not reported

VIJAX CORPORATION (Continued) **U001832798**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 497-4491
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	1615
Affiliation Type:	Emergency Contact
Company Name:	VIJAX CORPORATION
Contact Type:	Not reported
Contact Name:	ANTHONY LOSQUADRO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 497-4491
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	5420
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2750
Install Date:	Not reported
Date Tank Closed:	09/01/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	ZZ
Date Test:	11/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

D10 - Pipe Type - Copper
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C03 - Pipe Location - Aboveground/Underground Combination

VIJAX CORPORATION (Continued) **U001832798**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I05 - Overfill - Vent Whistle

Tank Number:	002
Tank ID:	5421
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	4000
Install Date:	10/01/1981
Date Tank Closed:	10/01/1981
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	ZZ
Date Test:	11/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)

C20 **TO ROADWAY** **NY Spills** **S117851233**
WNW **IFO 210 VARICK AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.024 mi.
128 ft. **Site 2 of 20 in cluster C**

Relative: **Lower**
Actual: **11 ft.**

SPILLS:

Name:	TO ROADWAY
Address:	IFO 210 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1411768 / 2015-03-17
Facility ID:	1411768
Facility Type:	ER
DER Facility ID:	460383
Site ID:	505566
DEC Region:	2
Spill Cause:	Traffic Accident
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2015-03-17
Investigator:	HRPATEL
Referred To:	Not reported

TO ROADWAY (Continued) **S117851233**

Reported to Dept:	2015-03-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-03-17
Spill Record Last Update:	2015-03-17
Spiller Name:	Not reported
Spiller Company:	ALL AMERICAN TRANSIT MIX
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	FIREFIGHTER SALVESEN
DEC Memo:	"03/17/15-Hiralkumar Patel. 1:03 PM:- spoke with FDNY Hazmat 1. a concrete mix truck overturned onto street and spilled approx. 15 gal diesel onto street only. no soil or sewers were affected. FDNY has pumped spilled product from street and remaining oil from the saddle tank, into 85 gal drum. oil drum will be placed onto tow truck."
Remarks:	"truck overturned, no sewers etc. fd on scene for c/u"

All Materials:

Site ID:	505566
Operable Unit ID:	1254873
Operable Unit:	01
Material ID:	2257509
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

C21 **COMMERCIAL BUILDING** **NY Spills** **S112226424**
WNW **210-222 VARICK AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.024 mi.
128 ft. **Site 3 of 20 in cluster C**

Relative: **Lower**
Actual: **11 ft.**

SPILLS:

Name:	COMMERCIAL BUILDING
Address:	210-222 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237-1027
Spill Number/Closed Date:	1205626 / 2015-09-22
Facility ID:	1205626
Facility Type:	ER
DER Facility ID:	422873
Site ID:	468588
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4

COMMERCIAL BUILDING (Continued) **S112226424**

SWIS:	2401
Spill Date:	2011-07-20
Investigator:	RVKETANI
Referred To:	021114 CASE REFERAL PACKAGE TO LEGAL
Reported to Dept:	2011-07-20
CID:	Not reported
Water Affected:	GROUNDWATER
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2012-09-05
Spill Record Last Update:	2015-09-22
Spiller Name:	ANTHONY LOSQUADRO
Spiller Company:	COMMERCIAL BUILDING
Spiller Address:	210-222 VARICK AVENUE
Spiller Company:	999
Contact Name:	ANTHONY LOSQUADRO
DEC Memo:	"9/5/12 - Raphael Ketani. The subject site is a commercial building owned by Anthony Losquadro, 210-222 Varick Avenue, Brooklyn, 11237-1027. His phone is (917) 681-1206. According to an old deed in ACRIS, Mr. Losquadro lives at 94 Payne Whitney Lane in Manhasset, NY. For 210 Varick Avenue, there is PBS case #2-080454. The facility listed is VIJAX Corp. at 210 Varick Avenue. A 275 gal. UST with #2 oil was closed in place on 9/1/02. A 4000 gal. UST with gasoline was closed in place on 10/1/81. The 222 Varick Avenue site used to house oil delivery trucks. Now, the 222 address houses a tiling company called Buy Tile. A metal recycling company operates out of 210 Varick Avenue. The spill was originally reported by the consultants (Sander Sternig, Director) at Volumetric Techniques, Ltd. (631) 472-4848 in their 7/20/11 soil and groundwater delineation report for their client next door, Metro Garage gas station at 1188 Metropolitan Avenue, Brooklyn. The soil and groundwater results for SB-5 and MW-1 in the 7/20/11 Volumetric report indicate exceedences of the CP-51 standards. The suite of exceedences are reflective of gasoline contamination, not fuel oil. The consultants for Volumetric have indicated that the Metro Garage UST near SB-5 and MW-1 held only diesel. However, there is a UST nearby just inside the former VIJAX building at 210-222 Varick Avenue. The UST was allegedly used to fuel oil delivery trucks with gasoline. A later investigation of the abandoned Metro Garage diesel UST was done and a report was generated by Volumetric dated 1/6/12. Two soil borings were done next to the diesel UST. The results indicated very little residual oil contamination in the soil. 9/13/12 - Raphael Ketani. A draft CSL was submitted to Hassan Hussein, supervisor of Unit C in Region 2 DER. Mr. Hussein approved the CSL and it was sent out today. 9/18/12 - Raphael Ketani. Anthony Losquadro (917) 681-1206 called yesterday regarding the CSL. He wanted to know what it was about. I explained that soil and groundwater contamination had been found at MW-1 and MW-2 during an investigation for Metro Garage. He said that his gasoline UST and fuel oil UST had been closed in place many years ago after they both had passing EZ-3 tank tests. I told him that the contamination is in the subsurface and his property is the closest

COMMERCIAL BUILDING (Continued) **S112226424**

facility to the wells. He said that he had a subsurface investigation performed by Fenley & Nicol and everything was fine in the subsurface. I asked him to send me the Fenley & Nicol report and the passing tank tests. He said he will. He asked for the reports showing that contamination was found. I sent him the Volumetric Techniques 7/20/11 and 1/6/12 reports by e-mail (tony@vijax.com). Later, Mr. Losquadro sent me a tank system integrity report dated 8/22/02 and the Fenley & Nicol Limited Subsurface Investigation and Tank Closure Report dated 12/19/02. The tank system report was for only the 4,000 gal. gasoline UST. The tank system had passed the integrity test. The Fenley & Nicol report dealt with an investigation of only the gasoline UST. The UST was located in the southwest corner of the property. Four (4) soil borings were performed around the UST and were turned into temporary monitoring wells. These wells were TW-1 to TW-4. Two (2) additional temporary wells were installed in the vicinity of the tank. These wells are TW-5a and TW-6a. The borings went down to 8 feet, except TW-6a went to 12 feet. The soil samples were taken from 0 to 4 feet and from 4 to 8 feet. TW-1 had virtually no PID detects. TW-2 had 10.8 ppm at 0 to 4 feet. TW-3 had 5.8 ppm at 0 to 4 feet. TW-4 had 2 ppm at 0 to 4 feet and 79.2 ppm at 4 to 8 feet with olfactory detection of odors. TW-5a had 63 ppm at 0 to 4 feet and 75 ppm at 4 to 8 feet. TW-6a had 5.8 ppm at 0 to 4 feet, 0.4 ppm or less deeper. Groundwater was determined to vary from 6.7 feet to 8.6 feet below grade and flowed north to Metropolitan Avenue. Groundwater samples were taken from TW-1 (upgradient), TW-2 (downgradient) and TW-6a (northernmost location). All of the results were non-detect for VOCs and SVOCs. It was not indicated in the report that the soil samples had been sent to a lab for analysis. I found the report and the investigation to be deficient. I drafted a letter for the review of Mr. Hussein. In the letter, I requested that Mr. Losquadro have a new investigation performed to delineate the soil and groundwater contamination throughout the 210-222 Varick Avenue site. 9/20/12 - Raphael Ketani. Mr. Hussein approved the letter and it was sent out today. A due date of October 19, 2012 was set for the submission of the work plan. 11/13/12 - Raphael Ketani. The deadline for submission of the work plan had passed. I drafted a strongly worded letter for the review of Mr. Hussein. In the letter, I ordered Mr. Losquadro to submit the work plan by November 30, 2012. I stated that he was in violation of Section 173 and Section 176 of Article 12 of the Navigation Law. If he doesn't send the work plan, then the case will be referred to the Office of General Counsel and he may face fines, penalties and prosecution. The letter was approved by Mr. Hussein and was sent out with a green return card. 11/19/12 - Raphael Ketani. The green card was returned, but there was only a mark in the signature box for the receiving party. 12/4/12 - Raphael Ketani. The work plan was not received by the November 30, 2012 due date. A draft Stipulation Agreement package was put together and submitted to Mr. Hussein for his approval. Mr. Hussein approved the Stipulation Agreement and it was sent to Anthony Losquadro at 222 Varick and to Joseph Losquadro at 94 Whitney Lane, Manhasset, NY, 11030. According to the ACRIS property database, the Losquadro Family, LLC owns 222 Varick. So they were put on the Stip itself. A deadline of January 4, 2013 was set for the receipt of the signed Stip. The Stip Package went out today. 12/14/12 - Raphael Ketani. The green return card for the Stipulation Agreement package was received today with a mark in the signature box. 12/21/12 - Raphael Ketani. Robert Dooley from The Law Office of Frederick Eisenbud (The

COMMERCIAL BUILDING (Continued) **S112226424**

Environmental Law Firm, 6165 Jericho Turnpike, Commack, NY, 11725-2803, (631) 493-9800/rd@li-envirolaw.com) called to request an extension of the deadline for submitting the Stipulation Agreement. I granted him an extension to January 25, 2013. Later, Mr. Eisenbud sent me an e-mail requesting additional documentation regarding the spill investigation at the Metro Garage site at 1188 Metropolitan Avenue, Brooklyn (#0302832). He also asked a number of questions about the Metro Garage investigation and included questions from Mike Zobel of Fenley & Nicol. Lastly, Mr. Eisenbud asked whether Losquadro Family LLC could be reimbursed by making a claim to the Spill Fund for the expense of the investigation work if their investigation indicates that 210-222 Varick Avenue is not the source of the contamination at MW-1. 12/24/12 - Raphael Ketani. I responded to Mr. Eisenbud's e-mail by sending him a pdf of the VTEQE 6/7/11 investigation report and by stating the reasons why the spill case was being kept open for 210-222 Varick Avenue. These reasons were: 1) soil and groundwater samples were analyzed for MW-1 for VOCs. These VOCs were typical of gasoline. 2) there is a gasoline UST near MW-1 and just inside the building footprint. So it is not unreasonable to assume that the gasoline contamination came from this UST system. 3) there are no gasoline USTs under the Metro garage site which are near MW-1, only a fuel oil UST. 4) the gasoline contamination is less at the downgradient location of boring SB-4 than it is at SB-5. 5) aside from these points, a report was obtained for the site at 210-222 Varick Avenue which indicated that fuel oil had leaked from the fuel oil UST system and hinted at elevated contamination. I finished the e-mail by stating that I would have to get back to him regarding reimbursement for the expense of the investigative work that will be performed - if the results indicate that 210-222 Varick is not the source. 12/27/12 - Raphael Ketani. I sent an e-mail to Mr. Eisenbud wherein I referred him to John Urda, Assistant Regional Attorney. Mr. Urda can answer his question about reimbursement for his client. 1/2/2013 - Raphael Ketani. I received information regarding reimbursement for the costs of doing an investigation for contamination that is not the responsibility of the property owner. I forwarded the information to Mr. Eisenbud. 1/24/13 - Raphael Ketani. A conference call took place between Mr. Zobel, Mr. Eisenbud and myself regarding the site and the previous Fenley & Nicol investigation. I told them that samples from SB-5 and MW-1 had indicated gasoline contamination, but Metro Garage had only a diesel fuel UST in this area. I added that groundwater flow was due north and the contamination was less at a further downgradient boring SB-4. Mr. Eisenbud stated that SB-5 and MW-1 were sidegradient, not downgradient and didn't reflect contamination from his client's property. I told them that there were high PID hits at the 4 to 8 foot interval at TW-4 and at both the 0 to 4 foot and 4 to 8 foot internvals at TW-5A. So there were indications of soil contamination that had never been addressed. I added now that the DEC was made aware of this, we were obligated to request that an investigation take place. Mr. Eisenbud pointed out that there was no groundwater contamination from the gasoline UST. So, the contamination at MW-1 was from somewhere else. I told both of them that an investigation needed to take place in order to resolve the matter. Mr. Eisenbud requested an extension of the deadline for submission of the Stipulation Agreement. I gave him until February 8. I added that a work plan will need to be submitted that will describe an investigation of all of the tanks below the property. With that, the

COMMERCIAL BUILDING (Continued) **S112226424**

conversation ended. 2/13/13 - Raphael Ketani. I tried to contact Mr. Dooley (631) 493-9800/rd@li-envirolaw.com regarding the submission of the overdue signed STIP, but could only leave a message. Mr. Dooley called me back. He said that he is involved in the case, but Mr. Eisenbud has the case file and so he is the person to talk to. However, he isn't here now. Mr. Dooley said that he had no idea why the STIP hadn't been signed and forwarded to the DEC, but he will let Mr. Eisenbud know that the DEC is looking for the document. He asked for a two day extension to submit the STIP. I told him that I will grant the two day extension, but, if the STIP is not received by that time, then I will be forced to pass the case up to our legal division. Mr. Dooley said that he understood. 2/15/13 - Raphael Ketani. Mr. Dooley called regarding the STIP. He said that due to the deadline being today for submission of the STIP, there is not enough time to go over it with Mr. Losquadro and get him to sign it. Also, he had heard about other spill sites having work plans instead of STIPs for oil spill cases. I told Mr. Dooley that the STIP was sent because the DEC was not receiving cooperation from Mr. Losquadro - in other words, no investigative work was taking place. Mr. Dooley said that he understood. Mr. Dooley asked whether the DEC was willing to accept a work plan at this time. I told him Yes, but the plan must cover an investigation of the entire site as we don't know what is taking place below the property regarding the oil contamination. Mr. Dooley said that he will send the DEC a work plan very soon. 3/18/13 - Raphael Ketani. I reviewed the Fenley & Nicol 3/7/13 Remedial Investigation Work Plan. There is a 2750 gal. fuel oil AST and a 4000 gal. gasoline UST below the site. Both passed the tightness tests on 11/4/97. The gas UST was retested on 8/22/02 and passed the second tightness test. Both tanks were abandoned in place with concrete slurry on 9/3/02. A GPR survey will be performed across the site in order to locate any utilities. The borings will be hand cleared down to 5 feet. Sampling will be every 3 feet. The soil and groundwater samples will be tested via method 8260 for samples that are collected from around the gasoline UST. For samples that are collected from around the fuel oil AST, the testing will be via methods 8260 and 8270. I found the work plan to be unacceptable. First, the number of borings is insufficient for determining whether there is contamination around the tanks, given their large sizes. Second, standard split spoon sampling is with a 2 foot split spoon. Third, it is not mentioned that soil sampling will take place in the vicinity of former borings TW-4 and TW-5a, where the contamination was originally found around the gasoline UST. Fourth, the well that they plan to install next to the fuel oil AST is not downgradient. Fifth, no borings were planned just inside of the garage door at 222 Varick Avenue that is next to Metro Garage. I drafted a letter for the review of Mr. Hussein stating the above deficiencies and requesting that a new work plan be submitted within 30 days of the response letter (by April 22). 3/19/13 - Raphael Ketani. Mr. Hussein approved the letter and it was sent out. 3/20/13 - Raphael Ketani. In response to the 3/19/13 letter, Mr. Dooley called me. We discussed the work that was being requested by the DEC. He said that it was much more than he expected and that he thought the object of the investigation was to see whether there was oil contamination below and around the tanks at 210-220 Varick Avenue, not to also investigate 222 Varick Avenue for an orphan tank. I reminded him that both the soil and the groundwater at the location MW-1, outside of the garage at 222 Varick, have gasoline contamination. I also stated again that Metro

COMMERCIAL BUILDING (Continued) **S112226424**

Garage does not have a gasoline tank in this area. So, given the analytes concentrations, there must be a gasoline UST nearby. The most likely location would be just inside 222 Varick. Mr. Dooley stated that it was not possible to do borings with a geoprobe inside the building as the ceiling was too low. I told him that there are all kinds of small equipment that can do the boring and, worse comes to worse, the consultants can use a small power drill to core the concrete floor and then do hand soil coring. I added that this was not easy, but I had seen it done on a number of projects where a geoprobe couldn't be used. Mr. Dooley stated that this was a possibility, but that he wanted to talk to Fenley & Nicole first before doing any of this work. I told him that would be fine. 5/10/13 - Raphael Ketani. As Mr. Dooley (631) 493-9800/rd@li-envirolaw.com has not responded since 3/20/13 and as the Department has not received the signed STIP (which was due 2/15/13) nor the revised Remedial Investigation Work Plan (which was due 4/22/13), I sent him an e-mail stating that either he sends the signed STIP or the revised work plan by May 31, or else a legal case will be initiated. 5/13/13 - Raphael Ketani. Mr. Dooley sent me an e-mail stating that the DEC will receive the work plan by the end of the week. 6/14/13 - Raphael Ketani. As neither the work plan nor the Stipulation Agreement have been forthcoming, I referred the spill case to our legal division. 2/7/14 - Raphael Ketani. There has been no contact from Mr. Losquadro or his consultant. There have been no changes regarding site status or property ownership. Ownership of the entire site is split into two groups: according to a 7/28/92 deed in ACRIS, 222 Varick Avenue is owned in common by Paul and Anthony Losquadro (both at 94 Payne Whitney Lane, Manhasset, New York) and by Monica Losquadro (145 Hicks Street, Brooklyn); 210-220 Varick is owned by the Losquadro Family, LLC. 2/11/14 - Raphael Ketani. A revised case referal was submitted to the Region 2 legal division. 10/30/14 - Raphael Ketani. I spoke to Sandy Sternig (631) 472-4848/cell (631) 514-1094 today (the consultant who had installed MW-1 and MW-2 outside of the site) about 222 Varick Avenue. He told me new information about the alleged gasoline UST at 222 Varick Avenue. Mr. Sternig said that he thought the UST was a little inside and to the right of the garage entrance nearest Metro Garage. I then asked Mr. Sternig how Dennis Firpo (the owner of Metro Garage to the north) knew about the pump island and the tank. He said that Mr. Firpo used to own the property 222 Varick Avenue when the tank and pump were there and then had sold the property to Mr. Losquadro years ago. I checked ACRIS and there is a deed dated 7/28/92 which shows the change in ownership from 222 Varick Avenue Corporation to Paul Losquadro (94 Payne Whitney Lane), Anthony Losquadro (94 Payne Whitney Lane) and Monica Losquadro (145 Hicks Street, Brooklyn). 9/16/15 - Raphael Ketani. I tried to contact Mr. Frederick Eisenbud [(The Environmental Law Firm, 6165 Jericho Turnpike, Commack, NY, 11725-2803, (631) 493-9800] by phone regarding progress at the site. I contacted Mr. Eisenbud as Mr. Dooley had left the law firm some time ago. In my message, I asked whether any work was taking place at the site. 9/22/15 - Raphael Ketani. Mr. Eisenbud still hasn't returned my phone call. The spill case data and information were discussed amongst staff at the Region 2 office of the Department. It was concluded that there is no evidence of a threat to the public or the environment from the contamination that was found at MW-1, SB-5 and around the fuel oil tank (according to the Fenley and Nicol report). It was decided that the spill case should be closed. Therefore, the spill case was administratively

COMMERCIAL BUILDING (Continued) **S112226424**

closed effective 9/22/15."
Remarks: "Spill discovered during a site investigation of the neighboring gas station."

All Materials:
Site ID: 468588
Operable Unit ID: 1218505
Operable Unit: 01
Material ID: 2216883
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: .00
Oxygenate: Not reported

C22 **CON EDISON** **NY MANIFEST** **S117736561**
WNW **210 VARICK AVE** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.024 mi.
128 ft. **Site 4 of 20 in cluster C**

Relative: **Lower**
Actual: **11 ft.**

NY MANIFEST:
Name: CON EDISON
Address: 210 VARICK AVE
City,State,Zip: BROOKLYN, NY 11237
Country: USA
EPA ID: NYP004532883
Facility Status: Not reported
Location Address 1: 210 VARICK AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11237
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004532883
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported

CON EDISON (Continued) **S117736561**

Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	05/15/2014
Trans1 Recv Date:	05/15/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004532883
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002406841GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C23 **CON EDISON SERVICE BOX: 3** **RCRA NonGen / NLR** **1017775453**
WNW **210 VARICK AVE** **NYP004532883**
< 1/8 **BROOKLYN, NY 11237**
0.024 mi.
128 ft. **Site 5 of 20 in cluster C**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:		20140615
Handler Name:	CON EDISON SERVICE BOX:	3
Handler Address:		210 VARICK AVE
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYP004532883

Actual:
11 ft.

CON EDISON SERVICE BOX: 3 (Continued) **1017775453**

Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No

CON EDISON SERVICE BOX: 3 (Continued) **1017775453**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140515
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140515
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140615
Handler Name: CON EDISON SERVICE BOX: 3	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON SERVICE BOX: 3 (Continued) **1017775453**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

C24 **NEW TOWN CREEK** **NY Spills** **S108956055**
WNW **225 VARICK AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.028 mi.
150 ft. **Site 6 of 20 in cluster C**

Relative:
Lower

Actual:
10 ft.

SPILLS:

Name:	NEW TOWN CREEK
Address:	225 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0708123 / 2007-10-25
Facility ID:	0708123
Facility Type:	ER
DER Facility ID:	338526
Site ID:	388965
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2007-10-25
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2007-10-25
CID:	408
Water Affected:	NEW TOWN CREEK
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-10-25
Spill Record Last Update:	2007-10-25
Spiller Name:	Not reported
Spiller Company:	NOT YET AVAILABLE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	GREGG GALIETTI
DEC Memo:	"Duplicate spill see 0708122"

NEW TOWN CREEK (Continued) **S108956055**

Remarks: "while loading THE GARBAGE ONTO THE TRUCK THE GARBAGE TRUCK ROLLED INTO THE CREEK; SLICK ON TOP OF WATER;"

All Materials:

Site ID:	388965
Operable Unit ID:	1146118
Operable Unit:	01
Material ID:	2136480
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	388965
Operable Unit ID:	1146118
Operable Unit:	01
Material ID:	2136481
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D25 **SB 55893** **NY Spills** **S106470894**
ESE **200 STEWART AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.034 mi.
181 ft. **Site 1 of 7 in cluster D**

Relative: **Higher**
Actual: **14 ft.**

SPILLS:

Name:	SB 55893
Address:	200 STEWART AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0403838 / 2004-10-04
Facility ID:	0403838
Facility Type:	ER
DER Facility ID:	103273
Site ID:	118871
DEC Region:	2
Spill Cause:	Vandalism
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-07-10
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2004-07-10
CID:	27
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other

SB 55893 (Continued) **S106470894**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-10
Spill Record Last Update:	2004-10-04
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"e2mis no 154293 ROSALIE REPORTS WHILE ON LOCATION HE SAW A PERSON FROM KORYO CORP, ORIENTAL MARINE PRODUCTS INC (IN FRONT 200 STEWART) AVE, DUMP A GALLON OF LIQUID INTO OUR SB-55893. HE THINKS IT SMELLS LIKE TERPENTINE. THE POLICE ARRIVED AND SO DID THE FDNY. ROSALIE WILL TAKE 3 SAMPLES. THIS IS A THIRD PARTY SPILL. Lab Sequence Number: 04-05405-001: Analysis indicates the presence of a substance similar to a light fuel oil. UPDATE: 10-JUL-2004 2226HRS 7/10/04 = 19:45 Hrs = Env. Ops. Supv. C.Fernandez reports that upon arrival at location a Mr. Steve Hong, Manager of Koreyo International Corp., approached him and admitted that his employees had poured paint thinner and oil based primer into our structure. After Mr. Fernandez spoke with Mr. DeMeo of the DEC on his cell phone it was agreed that Mr. Fernandez would call Clean Harbors to clean the structure as soon as possible. Mr. Fernandez was also informed that Officer Valente from the NYS DEC would be arriving soon. Officer Valente issued a summons to the consumer and informed him that Con Edison would have Clean Harbors clean the structure and bill him for it. FOD personnel, Mr. Rosalie and Mr. Ciampa, gave their statement to Officer Valente (of which Mr. Fernandez has a copy) and also gave Mr. Fernandez a written statement. At 17:50 Hrs Clean Harbors personnel arrived, proceeded to clean the structure and completed the job at 19:30 Hrs. From beginning to end Mr. Fernandez kept in touch with Mr.DeMeo, Mr. Silano and shift manager Mr. Sorrentino. Clean Harbors manifest, job sheet and Con Edison employees statements will be located in the Environmental Operations office. UPDATE: 10-JUL-2004 2234HRS TAG 30402 WAS REMOVED JOB IS 100% COMPLETE"
Remarks:	"CALLER REPORTS 1 GALLON OF UNKNOWN SUBSTANCE. SMELLS LIKE TURPENTINE THAT WAS POURED INTO THE SERVICE BOX. UNKNOWN FOR SURE MATERIAL SPILLED. LAW ENFORCEMENT IS REQUESTED FROM DEC."

All Materials:

Site ID:	118871
Operable Unit ID:	886238
Operable Unit:	01
Material ID:	491394
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B26 **VARICK ST & MEADOW ST** **NY Spills** **S102401958**
SW **VARICK ST & MEADOW ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.038 mi.
201 ft. **Site 5 of 8 in cluster B**

Relative: **Lower**

Actual: **12 ft.**

SPILLS:

Name:	VARICK ST & MEADOW ST
Address:	VARICK ST & MEADOW ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9606739 / 1998-05-13
Facility ID:	9606739
Facility Type:	ER
DER Facility ID:	261647
Site ID:	324811
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1996-08-26
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1996-08-26
CID:	282
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-08-26
Spill Record Last Update:	2003-01-21
Spiller Name:	TIM SOILCH
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	MR FREIER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL On 8/26 Tim Solich of Con Ed CIG reported that spill size was less than 200 gallon, less than 10 gallon into sewer and oil contained less than 10 ppm pcb. 8/27/98 (Katz notes): Steve Zalloughi, Env. Manager - Bushing failure on cemter of 3 units, 14-yr. old large, pad-mounted transformer. 65 gallons transformer oil released - some into sewer, 5 gallons contained in basin - Clean Ventures. STAR (Transfer Station - Waste Mgmt. of NY, 221 Varick Ave., operations supervisor - Anthony Gusmano (718) 497-8011) used wood chips to contain the oil. Used SLIX to clean street and picked up wood chips. <10 ppm PCB by record."
Remarks:	"spill went on the sidewalk and some went into the sewer system. a crew is on the scene cleaning the spill up. "

All Materials:

Site ID:	324811
Operable Unit ID:	1037880
Operable Unit:	01
Material ID:	346008
Material Code:	0020A

VARICK ST & MEADOW ST (Continued) **S102401958**

Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B27 **CON EDISON** **NY MANIFEST** **S118090333**
SSW **OPP 180 VARICK AVE** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.039 mi.
205 ft. **Site 6 of 8 in cluster B**

Relative:
Lower

Actual:
13 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 180 VARICK AVE
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP004779555
Facility Status:	Not reported
Location Address 1:	OPP 180 VARICK AVE
Code:	BP
Location Address 2:	MH 43888
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004779555
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

C28 **TRANSFORMER #2279/EMIS#220280** **NY Spills** **S110140421**
WNW **231 VARICK ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.041 mi.
219 ft. **Site 7 of 20 in cluster C**

Relative:
Lower

Actual:
10 ft.

SPILLS:

Name:	TRANSFORMER #2279/EMIS#220280
Address:	231 VARICK ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0912190 / 2010-04-01
Facility ID:	0912190

TRANSFORMER #2279/EMIS#220280 (Continued) **S110140421**

Facility Type:	ER
DER Facility ID:	373974
Site ID:	425064
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2010-02-22
Investigator:	Con Ed Unassigned
Referred To:	Not reported
Reported to Dept:	2010-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-22
Spill Record Last Update:	2010-04-01
Spiller Name:	ERT
Spiller Company:	CON EDISON
Spiller Address:	231 VARICK ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"04/01/10 - See eDocs for Con Ed report detailing cleanup and closure. 2/22/10 - Raphael Ketani. I spoke to Paul Walsh from the Con Ed ERT desk (212) 580-8383. He said that the spill was from a manhole that was found to be smoking at 6:03AM this morning. Oil was discovered on the street and in the catch basin nearby at 10:50AM. A crew could not inspect the manhole until it had cooled down. Two pints of oil were on the street and 1 gal. of dielectric fluid had run into the catch basin. Mr. Walsh stated that even though the oil had entered the basin, it did not travel into the sewer pipe that connects the basin to the rest of the sewer. He said that he is still waiting on the PCB content report. He should have it soon. The crew is still on the scene. Mr. Walsh will call me with the PCB results. Mr. Walsh called me back. He said that his supervisor was now on the scene. He's been informed that there is a green substance on the street. They don't know where it is from or what it is. Additionally, the historic information on the transformer is from 4/7/03 and simply says that the PCB concentration is 0 ppm. So Con Ed will take samples from the manhole and the catch basin. Mr. Walsh will get back to me. 2/23/10 - Raphael Ketani. I spoke to Dennis Michael Ides at the ERT desk. He said that the analytical results came back. The grab sample from the street had 12 ppm of PCBs in the oil. The sample from the transformer itself had 13 ppm of PCBs. He said that he was at the site during the cleanup. The spill consisted of 1 gal. down the catch basin and two pints on the pavement. He said that everything was cleaned up. "
Remarks:	"SOME MAY HAVE BEEN LOST INTO SEWER. CONTAINED AND CLEAN UP PENDING"

All Materials:

Site ID:	425064
Operable Unit ID:	1180798

TRANSFORMER #2279/EMIS#220280 (Continued) **S110140421**

Operable Unit:	01
Material ID:	2174791
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

C29 **ROADWAY - PARKING SPOT** **NY Spills** **S123663172**
NW **222 VARRICK AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.044 mi.
233 ft. **Site 8 of 20 in cluster C**

Relative: **Lower**

Actual: **10 ft.**

SPILLS:

Name:	ROADWAY - PARKING SPOT
Address:	222 VARRICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1900848 / 2019-04-30
Facility ID:	1900848
Facility Type:	ER
DER Facility ID:	538022
Site ID:	586692
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2019-04-24
Investigator:	PXLAKHAN
Referred To:	Not reported
Reported to Dept:	2019-04-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-04-24
Spill Record Last Update:	2019-04-30
Spiller Name:	METRO FUEL
Spiller Company:	METRO FUEL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ANTHONY LOSQUARO
DEC Memo:	"04/26/19 - Lakhani A citizen reported that a fuel delivery truck leaked oil to the roadway. The fuel company was Metro Fuel. Metro placed speedy dry onto the road to absorb the oil. Neither soil nor drains/sewers were affected. 04/30/19 - Lakhani Spill was cleaned. Spill is closed."
Remarks:	"Fuel delivery truck parked on the street that is actively leaking

ROADWAY - PARKING SPOT (Continued) **S123663172**

fuel onto the road. No driver around. Owner info obtained from the marking on the side of the truck."

All Materials:

Site ID:	586692
Operable Unit ID:	1334372
Operable Unit:	01
Material ID:	2343674
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

B30 **WASTE MANAGEMENT OF NY LLC** **RCRA NonGen / NLR** **1008374579**
West **221 VARICK AVE** **NY MANIFEST** **NYR000133298**
< 1/8 **BROOKLYN, NY 11237**
0.045 mi.
236 ft. **Site 7 of 8 in cluster B**

Relative: **Lower**

Actual: **8 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	WASTE MANAGEMENT OF NY LLC
Handler Address:	221 VARICK AVE
Handler City,State,Zip:	BROOKLYN, NY 11237-1026
EPA ID:	NYR000133298
Contact Name:	JAY KAPLAN
Contact Address:	VARICK AVE
Contact City,State,Zip:	BROOKLYN, NY 11237
Contact Telephone:	718-533-5310
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	VARICK AVE
Mailing City,State,Zip:	BROOKLYN, NY 11237
Owner Name:	WASTE MANAGEMENT OF NY LLC
Owner Type:	Private
Operator Name:	WASTE MANAGEMENT OF NY LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

WASTE MANAGEMENT OF NY LLC (Continued) **1008374579**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE

WASTE MANAGEMENT OF NY LLC (Continued) **1008374579**

Waste Code: D005
Waste Description: BARIUM

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: WASTE MANAGEMENT OF NY LLC
Legal Status: Private
Date Became Current: 20050720
Date Ended Current: Not reported
Owner/Operator Address: 123 VARICK AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: 718-533-5310
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WASTE MANAGEMENT OF NY LLC
Legal Status: Private
Date Became Current: 20050720
Date Ended Current: Not reported
Owner/Operator Address: 221 VARICK AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: 718-533-5310
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WASTE MANAGEMENT OF NY LLC
Legal Status: Private
Date Became Current: 20050720
Date Ended Current: Not reported
Owner/Operator Address: 221 VARICK AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: 718-533-5310
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WASTE MANAGEMENT OF NY LLC
Legal Status: Private
Date Became Current: 20050720
Date Ended Current: Not reported
Owner/Operator Address: 123 VARICK AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: 718-533-5310
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: WASTE MANAGEMENT OF NY LLC
Federal Waste Generator Description: Not a generator, verified

WASTE MANAGEMENT OF NY LLC (Continued) **1008374579**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: WASTE MANAGEMENT OF NY LLC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20050722
Handler Name: WASTE MANAGEMENT OF NY LLC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56291
NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20090708
Actual Return to Compliance Date: 20090817
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090826
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported

WASTE MANAGEMENT OF NY LLC (Continued) **1008374579**

Appeal Resolution Date:	Not reported
Disposition Status Date:	20090826
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYACY
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported

WASTE MANAGEMENT OF NY LLC (Continued) **1008374579**

Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20090708
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYACY
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090817
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20050922
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NY MANIFEST:

Name:	WASTE MANAGEMENT OF NY LLC
Address:	221 VARICK AVE
City,State,Zip:	BROOKLYN, NY 11237-1026
Country:	USA
EPA ID:	NYR000133298
Facility Status:	Not reported
Location Address 1:	221 VARICK AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000133298
Mailing Name:	WASTE MANAGEMENT OF NY LLC
Mailing Contact:	WASTE MANAGEMENT OF NY LLC
Mailing Address 1:	221 VARICK AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237

WASTE MANAGEMENT OF NY LLC (Continued) **1008374579**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7185335310

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD986607380
Trans2 State ID:	Not reported
Generator Ship Date:	05/11/2007
Trans1 Recv Date:	05/11/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/17/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000133298
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	000186452JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	120
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B31 **WASTE MANAGEMENT OF NEW YORK/WM DIV. NY** **NY AST** **U003396745**
West **221 VARICK AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.045 mi.
236 ft. **Site 8 of 8 in cluster B**

Relative:
Lower

Actual:
8 ft.

AST:

Name:	WASTE MANAGEMENT OF NEW YORK/WM DIV. NY
Address:	221 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-602605
Program Type:	PBS
UTM X:	590411.85561
UTM Y:	4507489.30677
Expiration Date:	N/A
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	24562
Affiliation Type:	Facility Owner
Company Name:	WASTE MANAGEMENT OF NEW YORK/WM DIV. NY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	123 VARICK AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 386-7900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24562
Affiliation Type:	Mail Contact
Company Name:	WASTE MANAGEMENT OF NEW YORK/WM DIV. NY
Contact Type:	Not reported
Contact Name:	ANTHONY LOMANGINO
Address1:	123 VARICK AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 386-7900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24562
Affiliation Type:	Facility Operator
Company Name:	WASTE MANAGEMENT OF NEW YORK/WM DIV. NY
Contact Type:	Not reported
Contact Name:	ANTHONY LOMANGINO

WASTE MANAGEMENT OF NEW YORK/WM DIV. NY (Continued) **U003396745**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 497-8011
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24562
Affiliation Type:	Emergency Contact
Company Name:	WASTE MANAGEMENT OF NEW YORK/WM DIV. NY
Contact Type:	Not reported
Contact Name:	ANTHONY LOMANGINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 497-8011
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	50699
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	C01 - Pipe Location - Aboveground
	F99 - Pipe External Protection - Other
	D99 - Pipe Type - Other
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	01/01/1990
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

WASTE MANAGEMENT OF NEW YORK/WM DIV. NY (Continued) **U003396745**

Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: diesel

Tank Number: 002
Tank Id: 50700
Material Code: 9999
Common Name of Substance: Other

Equipment Records:
B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
I00 - Overfill - None
H00 - Tank Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 01/01/1990
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: other

Tank Number: 003
Tank Id: 50701
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G01 - Tank Secondary Containment - Diking (Aboveground)
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use

WASTE MANAGEMENT OF NEW YORK/WM DIV. NY (Continued) **U003396745**

Pipe Model:	Not reported
Install Date:	01/01/1990
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	lube oil

E32 **RIGHT-WAY DEALER WAREHOUSE INC** **NY UST** **1001113557**
NNW **1202 METROPOLITAN AVE** **RCRA NonGen / NLR** **NYR000025478**
< 1/8 **BROOKLYN, NY 11237** **FINDS**
0.048 mi. **ECHO**
252 ft. **Site 1 of 5 in cluster E** **NY MANIFEST**

Relative:
Lower

Actual:
12 ft.

UST:

Name:	RIGHT-WAY DEALER WAREHOUSE
Address:	1202 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY 11237
Id/Status:	2-158445 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590509.40799
UTM Y:	4507563.03050
Site Type:	Other

Affiliation Records:

Site Id:	5303
Affiliation Type:	Facility Owner
Company Name:	KAMPNER REALTY COMPANY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	80 BUSINESS PARK DR ST 103
Address2:	Not reported
City:	ARMONK
State:	NY
Zip Code:	10504
Country Code:	001
Phone:	(914) 273-1825
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	5303
Affiliation Type:	Mail Contact
Company Name:	KAMPNER REALTY COMPANY
Contact Type:	Not reported
Contact Name:	STEVE STABILE
Address1:	80 BUSINESS PARK DR ST 103
Address2:	Not reported
City:	ARMONK
State:	NY

RIGHT-WAY DEALER WAREHOUSE INC (Continued) **1001113557**

Zip Code:	10504
Country Code:	001
Phone:	(914) 273-1825
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	5303
Affiliation Type:	Facility Operator
Company Name:	RIGHT-WAY DEALER WAREHOUSE
Contact Type:	Not reported
Contact Name:	RIGHT WAY DEALER WAREHOUSE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 366-1312
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	5303
Affiliation Type:	Emergency Contact
Company Name:	KAMPNER REALTY COMPANY
Contact Type:	Not reported
Contact Name:	STEVE STABILE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(914) 273-1825
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	8516
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1500
Install Date:	Not reported
Date Tank Closed:	06/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

RIGHT-WAY DEALER WAREHOUSE INC (Continued) **1001113557**

Tightness Test Method: 03
Date Test: 10/01/1989
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 51475
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: 06/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: RIGHT-WAY DEALER WAREHOUSE INC
Handler Address: 1202 METROPOLITAN AVE
Handler City,State,Zip: BROOKLYN, NY 11237-1007
EPA ID: NYR000025478
Contact Name: Not reported
Contact Address: METROPOLITAN AVE

RIGHT-WAY DEALER WAREHOUSE INC (Continued) **1001113557**

Contact City,State,Zip:	BROOKLYN, NY 11237
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	METROPOLITAN AVE
Mailing City,State,Zip:	BROOKLYN, NY 11237
Owner Name:	RIGHT-WAY CORP HEADQUARTERS
Owner Type:	Private
Operator Name:	RIGHT-WAY CORP HEADQUARTERS
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

RIGHT-WAY DEALER WAREHOUSE INC (Continued) **1001113557**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RIGHT-WAY CORP HEADQUARTERS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	RTE 22 & PUTNAM LAKE RD
Owner/Operator City,State,Zip:	BREWSTER, NY 10509
Owner/Operator Telephone:	914-278-5888
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	RIGHT-WAY CORP HEADQUARTERS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	RTE 22 & PUTNAM LAKE RD
Owner/Operator City,State,Zip:	BREWSTER, NY 10509
Owner/Operator Telephone:	914-278-5888
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator

RIGHT-WAY DEALER WAREHOUSE INC (Continued) **1001113557**

Owner/Operator Name: RIGHT-WAY CORP HEADQUARTERS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: RTE 22 & PUTNAM LAKE RD
Owner/Operator City,State,Zip: BREWSTER, NY 10509
Owner/Operator Telephone: 914-278-5888
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990708
Handler Name: RIGHT-WAY DEALER WAREHOUSE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: RIGHT-WAY DEALER WAREHOUSE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: RIGHT-WAY DEALER WAREHOUSE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960613
Handler Name: RIGHT-WAY DEALER WAREHOUSE INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

RIGHT-WAY DEALER WAREHOUSE INC (Continued) **1001113557**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004525844

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001113557
Registry ID:	110004525844
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004525844
Name:	RIGHT-WAY DEALER WAREHOUSE INC
Address:	1202 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY 11237

NY MANIFEST:

Name:	RIGHT-WAY DEALERS WAREHOUSE
Address:	1202 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY 11237-1007
Country:	USA
EPA ID:	NYR000025478
Facility Status:	Not reported
Location Address 1:	1202 METROLPOLITAN AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

RIGHT-WAY DEALER WAREHOUSE INC (Continued) **1001113557**

NY MANIFEST:

EPAID:	NYR000025478
Mailing Name:	RIGHT-WAY DEALERS WAREHOUSE
Mailing Contact:	TIMOTHY WILLIAMS
Mailing Address 1:	1202 METROPOLITAN AVENUE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7163661312

D33 **CON EDISON** **NY MANIFEST** **S117740707**
SE **STEWART AVE & STAGG ST** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.054 mi.
285 ft. **Site 2 of 7 in cluster D**

Relative:
Higher

Actual:
14 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	STEWART AVE & STAGG ST
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP004738878
Facility Status:	Not reported
Location Address 1:	STEWART AVE & STAGG ST
Code:	BP
Location Address 2:	SB 60388
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004738878
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/26/2015

CON EDISON (Continued) **S117740707**

Trans1 Recv Date:	02/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004738878
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610831GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D34 **CON EDISON** **RCRA NonGen / NLR** **1018279089**
SE **STEWART AVE & STAGG ST** **FINDS** **NYP004738878**
< 1/8 **BROOKLYN, NY 11237** **ECHO**
0.054 mi.
285 ft. **Site 3 of 7 in cluster D**

Relative: **Higher**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150226
Handler Name:	CON EDISON	
Handler Address:		STEWART AVE & STAGG ST
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYP004738878
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770

CON EDISON (Continued) **1018279089**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

CON EDISON (Continued) **1018279089**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150226
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150226
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1018279089**

FINDS:
Registry ID: 110067685838

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279089
Registry ID:	110067685838
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067685838
Name:	CON EDISON
Address:	STEWART AVE & STAGG ST
City,State,Zip:	BROOKLYN, NY 11237

D35 **CON EDISON** **NJ MANIFEST** **S120667927**
SE **STEWART AVE & STAGG ST** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.054 mi.
285 ft. **Site 4 of 7 in cluster D**

Relative:
Higher

Actual:
14 ft.

NJ MANIFEST:

EPA Id:	NYP004738878
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610831GBF
EPA ID:	NYP004738878
Date Shipped:	2/26/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

CON EDISON (Continued) **S120667927**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

C36 **STORAGE BUILDING** **NY Spills** **S103569112**
NW **1194 METROPOLITAN AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.055 mi.
292 ft. **Site 9 of 20 in cluster C**

Relative: **Lower**

Actual: **10 ft.**

SPILLS:

Name:	1194 METROPOLITAN AVE
Address:	1194 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9107650 / 1992-11-19
Facility ID:	9107650
Facility Type:	ER
DER Facility ID:	151314
Site ID:	180407
DEC Region:	2
Spill Cause:	Other
Spill Class:	D5
SWIS:	2401
Spill Date:	1991-10-16
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1991-10-16
CID:	Not reported
Water Affected:	Not reported

STORAGE BUILDING (Continued) **S103569112**

Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	1992-11-19
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-10-23
Spill Record Last Update:	2003-06-17
Spiller Name:	Not reported
Spiller Company:	DENNIS FIRPO/BUYRITE FUEL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 10/10/95: This is additional information about material spilled from the translation of the old spill file: CONTAMINATED SOIL."
Remarks:	"REFERRED TO LAW ENFORCEMENT ECO"

All Materials:

Site ID:	180407
Operable Unit ID:	958103
Operable Unit:	01
Material ID:	419844
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	STORAGE BUILDING
Address:	1194 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9514664 / 1996-02-20
Facility ID:	9514664
Facility Type:	ER
DER Facility ID:	151314
Site ID:	180408
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	1996-02-15
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	1996-02-15
CID:	199
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

STORAGE BUILDING (Continued) **S103569112**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-15
Spill Record Last Update:	2003-04-29
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	CHIEF MUSSORFITI
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY "
Remarks:	"FIRE IN A BUILDING WHERE THEY STORE TRUCKS - FUEL LEAKING FROM 2 TRUCKS APPROX 50 GAL ATTM TO PUT OUT FIRE AND CLEAN UP NOW DEP CONTACTED "

All Materials:

Site ID:	180408
Operable Unit ID:	1029202
Operable Unit:	01
Material ID:	354793
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C37 **CON EDISON** **NY MANIFEST** **S117066828**
NNW **FRONT OF 1196 METROPOLITAN AV** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.056 mi.
295 ft. **Site 10 of 20 in cluster C**

Relative:
Lower

Actual:
10 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FRONT OF 1196 METROPOLITAN AV
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP004595328
Facility Status:	Not reported
Location Address 1:	FRONT OF 1196 METROPOLITAN AV
Code:	BP
Location Address 2:	SB15351
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004595328
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL

CON EDISON (Continued) **S117066828**

Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/14/2014
Trans1 Recv Date:	07/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004595328
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002504274GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	70
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C38 **METRO** **NY Spills** **S106007736**
NW **1188 METROPOLITAN AVE** **N/A**
< 1/8 **GREEN POINT, NY**
0.056 mi.
296 ft. **Site 11 of 20 in cluster C**

Relative:
Lower

Actual:
10 ft.

SPILLS:

Name:	METRO
Address:	1188 METROPOLITAN AVE
City,State,Zip:	GREEN POINT, NY
Spill Number/Closed Date:	0206511 / 2003-10-20
Facility ID:	0206511
Facility Type:	ER
DER Facility ID:	88204
Site ID:	99221
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	2002-09-23
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2002-09-23
CID:	322
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-23
Spill Record Last Update:	2003-10-20
Spiller Name:	Not reported
Spiller Company:	METRO
Spiller Address:	1188 METROPOLITAN AVE
Spiller Company:	001
Contact Name:	DENNIS FIRPO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 10/20/03 TJD spill closed. open spill on property is 0302832."
Remarks:	"while digging around the stick line contaminated soil found "

All Materials:

Site ID:	99221
Operable Unit ID:	858125
Operable Unit:	01
Material ID:	517115
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C39 **TRUCK IN CREEK** **NY Spills** **S108956054**
WNW **221 ZARICK AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.057 mi.
303 ft. **Site 12 of 20 in cluster C**

Relative: **Lower**

Actual: **7 ft.**

SPILLS:

Name:	TRUCK IN CREEK
Address:	221 ZARICK AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0708122 / 2007-11-06
Facility ID:	0708122
Facility Type:	ER
DER Facility ID:	338525
Site ID:	388964
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	2007-10-25
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2007-10-25
CID:	74
Water Affected:	ENGLISH KILLS CREEK
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-10-25
Spill Record Last Update:	2007-11-06
Spiller Name:	GREG GALIETTI
Spiller Company:	ACTION CARTING ENV SERVIC
Spiller Address:	451 FRELINGHUYSEN AVE
Spiller Company:	001
Contact Name:	JAY KAPLAN
DEC Memo:	"Miller Env. performed cleanup. They will send documentation of work ,though not much oil/ diesel was spillend and/ or recovered."
Remarks:	"Unattended truck drove into creek - into a navigable waterway - no injuries. Fire dept is on the scene. Fuel is entering waterway - vehicle was still running. ****** CALLER REQUESTS A DEC REP CONTACT HIM ****** "

All Materials:

Site ID:	388964
Operable Unit ID:	1146117
Operable Unit:	01
Material ID:	2136479
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C40 **MANHATTAN POLYBAG CORP** **NY Spills** **S108296225**
WNW **1150 METROPOLITAN AVE** **NY MANIFEST** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.059 mi.
310 ft. **Site 13 of 20 in cluster C**

Relative: **Lower**

Actual: **7 ft.**

SPILLS:

Name:	COMMERCIAL WAREHOUSE
Address:	1150 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0609662 / 2009-07-28
Facility ID:	0609662
Facility Type:	ER
DER Facility ID:	323677
Site ID:	373955
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	2006-11-22
Investigator:	AXDORONO
Referred To:	NFA
Reported to Dept:	2006-11-22
CID:	410
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-11-22
Spill Record Last Update:	2009-07-28
Spiller Name:	MATT BOECKEL
Spiller Company:	COMMERCIAL WAREHOUSE
Spiller Address:	1150 METROPOLITAN AVE
Spiller Company:	001
Contact Name:	MATT BOECKEL
DEC Memo:	"12/11/06-Hiralkumar Patel. received message from Matt (Cell: 631-767-9098) from Associated Environmental. spoke to John at Associated and asked him to DEC Rahman. 12/18/06 Rahman- Phase II(partial) Subsurface Investigation is prepared by Associated Environmental Services Ltd(Matthew Boeckel@631.234.4280).The site was utilized as a paving company and a oil company from at least 1807 to the late 1960s.Sanborn Fire Insurance Maps indicated the presence of large gasoline and fuel oil storage tanks.The site is currently utilized as warehouse and distribution purposes.During the Phase II investigation, soil/ground water samples were collected from the ground surface to a depth of 20' below grade.A majority of the site could not be investigated due to the presence of merchandise.Ground water flows to the west, towards English Kills.There was petroleum based odor and staining as well as elevated PID readings detected in the soil samples collected from borings B-1 through B-8. Ground water analytical results show presence of elevated levels of VOCs(MTBE- 33 ug/l,Naphthalene-6900 ug/l),SVOCs and RCRA metals.RP's consultant plans to conduct additional investigation after clearing the interior of the subject building that could not be accessed due to storage of

MANHATTAN POLYBAG CORP (Continued) **S108296225**

merchandise. Spill case is transferred to Remediation section B for determination regarding further investigation/remedial work. 1/11/2007 - Vadim Brevdo spoke with Matt (Consultant) and agreed that Site Investigation Work Plan can be submitted to Vadim Brevdo's name. Vadim Brevdo 1/25/2007 - Vadim Brevdo spoke with Matt Boeckel of Associated Environmental Service, reviwed and approved remedial investigation work plan dated January 18, 2007. Approval letter is dated January 24. 02/16/07: This spill case transferred from V. Brevdo to J. Kolleeny. Tried calling Matt Boeckel of Associated Environmental Services (631-234-4280), but he was out; spoke with John Schretzmayer, mentioned some deficiencies with reports submitted (Phase II Remedial Investigation report (2/7/07) and Interim Remedial Measure Work Plan (2/8/07)), including inaccurate boring labelling on site plan, lack of former tank locations depicted on site plan, and need for greater detail regarding remedial proposal of sodium persulfate injections, such as quantity of material to be injected and health and safety considerations. Also asked that electronic versions of each report be submitted. John said Matt will get back to me. - JK 02/23/07: After discussing deficiencies in Interim Remedial Measure Work Plan with Matt Boeckel of Assoc. Env'tal Svcs, and receiving several faxed revised versions, entitled Remedial Measure Work Plan (with site location figure, Sanborn map showing former tank locations, more detailed discussion of proposed sodium persulfate injections with health and safety considerations, added language about soil sampling during installation of permanent monitoring wells and surveying of wells to determine groundwater flow direction, analytical parameters changed to STARS list of petroleum-related VOCs and SVOCs), I sent approval letter (in eDocs) to 221 Realty Co., LLC of 500 Broadway, Brooklyn, NY 11211, attn: Alex Gross, with cc's to Ken Zucker of Beechwood Mountain, LLC and Matt of AES. Approval letter asked for additional permanent well near boring B-9, installation and sampling of permanent wells prior to chem. ox. injections to determine baseline GW conditions, and commented that if follow-up GW monitoring fails to show sodium persulfate effectiveness, alternative remedial approach must be developed. Also, sent email to Matt of AES asking for hard copy of finalized work plan report, and electronic copies of all site-related reports. - J. Kolleeny 08/07/2007: This spill case was transferred to A. Doronova. -AD 09/2007: Spoke to Matt Boeckel regarding implementation of the work plan. He said that they encountering constant refusal during soil borings, so they need to use different drilling equipment. AES plans to perform this work in a few weeks. Matt will call back with an update information. AD 01/09/2008: Call and spoke with Jon of AES regarding work plan status update. He promised to get back. AD 02/28/2008: Jon of AES called and asked if they may re-locate proposed monitoring wells due to technical difficulties (thick layer of concrete - 3ft and more). He also wants to meet with us at the site. Told him to send us a site diagram with new locations for the wells and said that site visit may be possible next week. Spoke with J. Kolleeny regarding wells installation on this site. Called and left a message to Jon of AES. Talked later with him regarding concrete specification, groundwater depth and if air rotary drilling was applied. Jon said that concrete is re-bar concrete; air rotary drilling could not be applied due to low clearance - 8' and groundwater depth from the basement floor is about 5' deep. The site visit was scheduled on Monday, March 3, 2008. AD 03/03/2008: Received a message from AES, left on Friday, February 29, 2008 at 5 PM, that

MANHATTAN POLYBAG CORP (Continued) **S108296225**

they would like to re-schedule site visit. Called and spoke with Christina of AES. The site visit was cancelled for today. AD 03/05/2008: Scheduled new site visit for Friday March 7, 2008. AD 03/07/2008: Visited the site with J. Kolleeny. Met there with John Schretzmayer of AES. He showed the property and explained why some of the injection points could not be installed. The soil has some elevated levels of SVOC contamination, groundwater result indicates exeedances in VOC. We discussed the implementation of the proposed remedial action plan and agreed to reduce the numbers of proposed injection point from 21 to 15 and add one more monitoring well. AD 08/07/2008: Called and left a message to J. Schretzmayer of AES regarding a summary report submission. AD 08/14/2008: Called and left a message to J. Schretzmayer of AES. AD 08/15/2008: Received a message from AES. The hard copy of the report will be submitted next week. AD 09/19/2008: Did not receive report. Spoke with a secretary of AES, left a message for J. Schretzmayer regarding the report submission. AD 10/14/2008: Called and left a message to J. Schretzmayer to call me back. AES email address is: <AssociatedEnv@aol.com>. AD 10/29/2008: Received the report. DL to eDocs. Will review. AD 11/03/2008: Reviewed the report. It states that a total of four monitoring wells were installed at the site. The analytical results for the April 2008 groundwater samples indicated that there were several VOCs and SVOCs at concentrations exceeding their NYSDEC standards (MTBE in MW-01 at 44 ppb). To remove dissolved phase contamination in the groundwater, AES used sodium persulfate solution (oxidizer) by introducing it via 14 injection wells at a depth of 10 to 15' bellow grade. October 2008 groundwater sampling event was scheduled to determine if the chemical oxidant solution has effectively reduced contaminant concentrations in the groundwater. A summary report will be provided to DEC following October 2008 monitoring event with conclusions and recommendations. AD 03/30/2009: Called to AES and left a message to a secretary for J. Shretzmayer regarding a QMR submission. AD 04/27/2009: Did not receive any response yet. Called and left a message to Mr. Shretzmayer. AD 05/08/2009: Received ecopy of the IRM - Groundwater Sampling Report from J. Shretzmayer of AES via e-mail. DL to eDocs. AD 05/11/2009: Received a hard copy of the report. Will review. AD 05/14/2009: Reviewed the report. It states that on February 9, 2009 AES sampled three out of four monitoring wells at the site. The most contaminated well MW-4 could not be located due to the debris and reorganization of the warehouse. Baseline GW sampling in April 2008 indicated several VOCs and SVOCs at concentrations exceeding their NYSDEC standards (MTBE in MW-01 at 44 ppb). February 2009 sampling results indicated lower levels of SVOCs and MTBE in well MW-1 and ND levels of VOCs and SVOCs in wells MW-2 and MW-3. Based on the analytical results of the GW sampling and due to the fact that the subject site is occupied and soil removal is not feasible, the consultant recommends no further actions for this site. Discussed the site with J. Kolleeny of DEC. Called and spoke with Christine Mazzarella of AES. Asked if the location of the well MW-4 could be found, they should sample it, if not - than they should try to collect groundwater grab sample in its vicinity. Ms. Mazzarella will get back to us with their response. AD 07/13/2009: Received an e-mail from C. Mazzarella of AES saying: Hello Ainura Attached please find subject report for your review.? Please reference?Spill #06-09662. Please contact us with any questions or comments following your review of the attached. Thank you Christine Mazzarella Associated Environmental

MANHATTAN POLYBAG CORP (Continued) **S108296225**

Services, Ltd. 25 Central Avenue Hauppauge, New York 11788 631 234 4280 tel 631 234 4297 fax DL the report to eDocs. Will review. AD 07/21/2009: Reviewed the report. It states that on May 27, 2009 AES sampled one temporary well point in the vicinity of well MW-4, according to the DEC request. The most contaminated well MW-4 could not be located during previous sampling event, due to the debris and reorganization of the warehouse. May 2009 sampling results indicated low levels of SVOCs and MTBE and ND levels of VOCs in the area of well MW-4. Based on historical analytical results of the GW sampling and due to the fact that the subject site is occupied and soil removal is not feasible, the consultant recommends no further actions for this site. Discussed the site with J. Kolleeny of DEC. Taking into consideration investigative and remedial activities performed at the site, clear decreasing trend of VOCs and SVOCs in GW, and current GW conditions, it was decided to approve NFA request for this site. AD 07/27/2009: Issued and sent NFA letter. DL to eDocs. Case closed. AD"

Remarks: "PHASE TWO CONDUCTED AT SITE: LAB RESULTS REVEALED ELEVATED CONATMINENTS IN SOIL AND GROUNDWATER ABOVE STATE LEVEL: SITE WAS HISTORIACALLY UTILIZED FROM EARLY 1900'S TO THE LATE 1960'S AS A ASPHALT PAVING COMPANY, AND OIL TERMINAL:"

All Materials:

Site ID:	373955
Operable Unit ID:	1131643
Operable Unit:	01
Material ID:	2121356
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	MANHATTAN POLYBAG CORP
Address:	1150 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY 11237-0000
Country:	USA
EPA ID:	NYD982272627
Facility Status:	Not reported
Location Address 1:	1150 METROPOLITAN AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD982272627
Mailing Name:	MANHATTAN POLYBAG CORP
Mailing Contact:	GARY KAUFMAN
Mailing Address 1:	1150 METROPOLITAN AVE

MANHATTAN POLYBAG CORP (Continued) **S108296225**

Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183264770

C41 **MANHATTAN POLY BAG** **RCRA NonGen / NLR** **1007204964**
WNW **1150 METROPOLITAN AVENUE** **NY MANIFEST** **NYD098227267**
< 1/8 **BROOKLYN, NY 11237**
0.059 mi.
310 ft. **Site 14 of 20 in cluster C**

Relative: **Lower**
Actual: **7 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	MANHATTAN POLY BAG	
Handler Address:		1150 METROPOLITAN AVENUE
Handler City,State,Zip:		BROOKLYN, NY 11237-0000
EPA ID:		NYD098227267
Contact Name:		GARY KAUFMAN
Contact Address:		1150 METROPOLITAN AVENUE
Contact City,State,Zip:		BROOKLYN, NY 11237-0000
Contact Telephone:		718-326-4770 9999
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		1150 METROPOLITAN AVENUE
Mailing City,State,Zip:		BROOKLYN, NY 11237-0000
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

MANHATTAN POLY BAG (Continued) **1007204964**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20060101
Handler Name: MANHATTAN POLY BAG	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101

MANHATTAN POLY BAG (Continued) **1007204964**

Handler Name: MANHATTAN POLY BAG
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920120
Handler Name: MANHATTAN POLY BAG
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 322223
NAICS Description: COATED PAPER BAG AND POUCH MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: MANHATTAN POLYBAG CO
Address: 1150 METROPOLITAN AVENUE
City,State,Zip: BROOKLYN, NY 11237-0000
Country: USA
EPA ID: NYD098227267
Facility Status: Not reported
Location Address 1: 1150 METROPOLITAN AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11237
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD098227267
Mailing Name: MANHATTAN POLYBAG CO
Mailing Contact: MANHATTAN POLYBAG CO

MANHATTAN POLY BAG (Continued) **1007204964**

Mailing Address 1:	1150 METROPOLITAN AVENUE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183264770

C42 **MANHATTAN POLY BAG CORP** **RCRA-VSQG 1000239979**
WNW **METROPOLITAN AVE** **NY AST NYD982272627**
< 1/8 **BROOKLYN, NY 11237**
0.059 mi.
310 ft. **Site 15 of 20 in cluster C**

Relative: **Lower**

Actual: **7 ft.**

RCRA-VSQG:

Date Form Received by Agency:	20070101
Handler Name:	MANHATTAN POLY BAG CORP
Handler Address:	METROPOLITAN AVE
Handler City,State,Zip:	BROOKLYN, NY 11237
EPA ID:	NYD982272627
Contact Name:	GARY R KAUFMAN
Contact Address:	METROPOLITAN AVE
Contact City,State,Zip:	BROOKLYN, NY 11237
Contact Telephone:	718-326-4770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	METROPOLITAN AVE
Mailing City,State,Zip:	BROOKLYN, NY 11237
Owner Name:	WILLIAM KAUFMAN
Owner Type:	Private
Operator Name:	MANHATTAN POLY REALTY
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported

MANHATTAN POLY BAG CORP (Continued) **1000239979**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2003

Click Here for Biennial Reporting System Data:
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL

MANHATTAN POLY BAG CORP (Continued) **1000239979**

ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: NONE
Waste Description: Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MANHATTAN POLY REALTY
Legal Status:	Private
Date Became Current:	19861201
Date Ended Current:	Not reported
Owner/Operator Address:	METROPOLITAN AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11237
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MANHATTAN POLY REALTY
Legal Status:	Private
Date Became Current:	19861201
Date Ended Current:	Not reported
Owner/Operator Address:	METROPOLITAN AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11237
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WILLIAM KAUFMAN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

MANHATTAN POLY BAG CORP (Continued) **1000239979**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WILLIAM KAUFMAN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MANHATTAN POLY BAG
Legal Status: Private
Date Became Current: 19861201
Date Ended Current: Not reported
Owner/Operator Address: METROPOLITAN AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990729
Handler Name: MANHATTAN POLY BAG CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MANHATTAN POLY BAG CORP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MANHATTAN POLY BAG CORP
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY

MANHATTAN POLY BAG CORP (Continued) **1000239979**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19870911
Handler Name: MANHATTAN POLY BAG CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980225
Handler Name: MANHATTAN POLY BAG
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: MANHATTAN POLY BAG CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020221
Handler Name: MANHATTAN POLY BAG CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

MANHATTAN POLY BAG CORP (Continued) **1000239979**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040228
Handler Name: MANHATTAN POLY BAG CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 322223
NAICS Description: COATED PAPER BAG AND POUCH MANUFACTURING

NAICS Code: 323112
NAICS Description: COMMERCIAL FLEXOGRAPHIC PRINTING

NAICS Code: 326112
NAICS Description: PLASTICS PACKAGING FILM AND SHEET (INCLUDING LAMINATED) MANUFACTURING

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: LDR - General
Date Violation was Determined: 19940325
Actual Return to Compliance Date: 19940428
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19940425
Enforcement Identifier: 000
Date of Enforcement Action: 19940325
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYADS
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported

MANHATTAN POLY BAG CORP (Continued) **1000239979**

SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported

MANHATTAN POLY BAG CORP (Continued) **1000239979**

Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19940325
Actual Return to Compliance Date: 19940428
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19940425
Enforcement Identifier: 000
Date of Enforcement Action: 19940325
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYADS
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported

MANHATTAN POLY BAG CORP (Continued) **1000239979**

SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20020128
Actual Return to Compliance Date: 20020221
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001

MANHATTAN POLY BAG CORP (Continued) **1000239979**

Date of Enforcement Action:	20020204
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYHHN
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19940125
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYADS
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19940428
Scheduled Compliance Date:	19940425
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19920415
Evaluation Responsible Agency:	EPA Contractor/Grantee
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2TRC
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19930119

MANHATTAN POLY BAG CORP (Continued) **1000239979**

Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19940125
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYADS
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19940428
Scheduled Compliance Date:	19940425
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19981111
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2MD
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20020128
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20020221
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

AST:

Name:	MANHATTAN POLY BAG CORP
Address:	1150 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY 11237
Region:	STATE

MANHATTAN POLY BAG CORP (Continued) **1000239979**

DEC Region: 2
Site Status: Active
Facility Id: 2-248746
Program Type: PBS
UTM X: 590352.85630
UTM Y: 4507571.99810
Expiration Date: 07/07/2007
Site Type: Other

Affiliation Records:

Site Id: 9843
Affiliation Type: Facility Owner
Company Name: MANHATTAN POLY BAG CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 1150 METROPOLITAN AVE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11237
Country Code: 001
Phone: (718) 326-4770
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 9843
Affiliation Type: Mail Contact
Company Name: MANHATTAN POLY BAG CORP
Contact Type: Not reported
Contact Name: GARY KAUFMAN
Address1: 1150 METROPOLITAN AVE
Address2: PO BOX 370-713
City: BROOKLYN
State: NY
Zip Code: 11237
Country Code: 001
Phone: (718) 326-4770
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 9843
Affiliation Type: Facility Operator
Company Name: MANHATTAN POLY BAG CORP
Contact Type: Not reported
Contact Name: GARY KAUFMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 326-4770
EMail: Not reported
Fax Number: Not reported

MANHATTAN POLY BAG CORP (Continued) **1000239979**

Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	9843
Affiliation Type:	Emergency Contact
Company Name:	MANHATTAN POLY BAG CORP
Contact Type:	Not reported
Contact Name:	GARY KAUFMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 326-4770
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	004
Tank Id:	11157
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	I04 - Overfill - Product Level Gauge (A/G)
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

C43 **LOT** **NY Spills** **S125359732**
WNW **1150 METROPOLITAN AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.059 mi.
310 ft. **Site 16 of 20 in cluster C**

Relative: **Lower**

Actual: **7 ft.**

SPILLS:

Name:	LOT
Address:	1150 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1905844 / 2019-09-24
Facility ID:	1905844
Facility Type:	ER
DER Facility ID:	323677
Site ID:	593894
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2019-09-05
Investigator:	RHLIN
Referred To:	Not reported
Reported to Dept:	2019-09-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-09-05
Spill Record Last Update:	2019-09-24
Spiller Name:	Not reported
Spiller Company:	METRO DIESEL GARAGE INC
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CELEST OKOLI
DEC Memo:	"9/5/19- Zhune called Celest Okoli 347-672-6059. Could not get him. Left a massage. 9/5/19- At 1:30pm Zhune called Celest Okoli 347-672-6059. Could not get him. Left a massage. 9/6/19-Zhune called Celest Okoli 347-672-6059. Could not get him. Left a massage. 9/6/19-celest called Zhune. Celest said the company is Metro Diesel Garage. the saddle tank of one of the trucks is leaking. Spill went to the catch basin and it went to the ground. There is a sheen into the waterway. Diesel is seeping gradually to the river. At the back of the truck is the river. Power Vac was hire to clean the spill in the catch basin. 9/6/19-Lin-Visited site. Truck is no longer leaking. Speedy dry was put down. No soil contamination was found. No sheen was observed in the creek. Case closed. Metro Diesel Garage 718-381-5050 "
Remarks:	"loss to soil from vehicles"

All Materials:

Site ID:	593894
Operable Unit ID:	1341468
Operable Unit:	01
Material ID:	2351376

LOT (Continued) **S125359732**

Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

C44 **AID AUTO STORES, INC.** **RCRA NonGen / NLR** **1000102708**
WNW **1150 METROPOLITAN AVE** **FINDS** **NYD058581497**
< 1/8 **BROOKLYN, NY 11237** **ECHO**
0.059 mi.
310 ft. **Site 17 of 20 in cluster C**

Relative: **Lower**
Actual: **7 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	AID AUTO STORES, INC.	
Handler Address:		1150 METROPOLITAN AVE
Handler City,State,Zip:		BROOKLYN, NY 11237-1006
EPA ID:		NYD058581497
Contact Name:		Not reported
Contact Address:		METROPOLITAN AVE
Contact City,State,Zip:		BROOKLYN, NY 11237
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		METROPOLITAN AVE
Mailing City,State,Zip:		BROOKLYN, NY 11237
Owner Name:		AID AUTO STORES INC.
Owner Type:		Private
Operator Name:		AID AUTO STORES INC.
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported

AID AUTO STORES, INC. (Continued) **1000102708**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D002
Waste Description:	CORROSIVE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	AID AUTO STORES INC.
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

AID AUTO STORES, INC. (Continued) **1000102708**

Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	AID AUTO STORES INC.
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	AID AUTO STORES INC.
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: AID AUTO STORES, INC.	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: AID AUTO STORES, INC.	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

AID AUTO STORES, INC. (Continued) **1000102708**

Receive Date: 20070101
Handler Name: AID AUTO STORES, INC.
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19820311
Handler Name: AID AUTO STORES, INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported

AID AUTO STORES, INC. (Continued) **1000102708**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19880930
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:

Registry ID: 110009467460

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000102708
Registry ID:	110009467460
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009467460
Name:	AID AUTO STORES, INC.
Address:	1150 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY 11237

F45 **ALJO AUTO ELECTRIC CORP** **RCRA NonGen / NLR** **1000912276**
NE **1250 METROPOLITAN AVE** **NY0000575225**
< 1/8 **BROOKLYN, NY 11237**
0.064 mi.
338 ft. **Site 1 of 9 in cluster F**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	ALJO AUTO ELECTRIC CORP
Handler Address:	1250 METROPOLITAN AVE
Handler City,State,Zip:	BROOKLYN, NY 11237-1103
EPA ID:	NY0000575225
Contact Name:	Not reported
Contact Address:	PO BOX 704
Contact City,State,Zip:	BROOKLYN, NY 11237
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	PO BOX 704
Mailing City,State,Zip:	BROOKLYN, NY 11237
Owner Name:	ANGELO BORGIA
Owner Type:	Private
Operator Name:	ANGELO BORGIA
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

ALJO AUTO ELECTRIC CORP (Continued) **1000912276**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D006
Waste Description:	CADMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D035
Waste Description:	METHYL ETHYL KETONE
Waste Code:	D040
Waste Description:	TRICHLORETHYLENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ANGELO BORGIA
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 704
Owner/Operator City,State,Zip:	BROOKLYN, NY 11237
Owner/Operator Telephone:	718-417-6771
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

ALJO AUTO ELECTRIC CORP (Continued) **1000912276**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ANGELO BORGIA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 704
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: 718-417-6771
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ANGELO BORGIA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 704
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: 718-417-6771
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: ALJO AUTO ELECTRIC CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: ALJO AUTO ELECTRIC CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ALJO AUTO ELECTRIC CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY

ALJO AUTO ELECTRIC CORP (Continued) **1000912276**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19940811
Handler Name:	ALJO AUTO ELECTRIC CORP
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

F46 **CONSOLIDATED PACKAGING GROUP INC-1250 METROPOLITA** **NY AIRS S106534423**
NE **1250 METROPOLITAN AVE** **NY MANIFEST N/A**
< 1/8 **BROOKLYN, NY 11237**
0.064 mi.
338 ft. **Site 2 of 9 in cluster F**

Relative: **Lower**
Actual: **13 ft.**

AIRS:

Name:	CONSOLIDATED PACKAGING GROUP INC-1250 METROPOLITA
Address:	1250 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY 11237
DECID:	2610400151
Process ID:	Not reported
Latitude:	40.714328098
Longitude:	73.926174116
FIPS Code:	Not reported
Auth Type Code:	ATV
Permit Status:	Expired
Auth Status Code:	Not reported
Emissions:	Not reported
Issue date:	11/29/2005
Expired Date:	03/20/2006
Emission Unit date:	Not reported
Contamination:	Not reported

CONSOLIDATED PACKAGING GROUP INC-1250 METROPOLITA (Continued) **S106534423**

EPA Control Code: Not reported
Control Eff: Not reported
Unit: Not reported

Permit Status: Expired
Auth Status Code: Not reported
Emissions: Not reported
Issue date: 03/20/2006
Expired Date: Not reported
Emission Unit date: Not reported
Contamination: Not reported
EPA Control Code: Not reported
Control Eff: Not reported
Unit: Not reported

Permit Status: Expired
Auth Status Code: Not reported
Emissions: Not reported
Issue date: 11/14/2001
Expired Date: 03/20/2006
Emission Unit date: Not reported
Contamination: Not reported
EPA Control Code: Not reported
Control Eff: Not reported
Unit: Not reported

Permit Status: Not reported
Auth Status Code: Not reported
Emissions: 0.01061656
Issue date: Not reported
Expired Date: Not reported
Emission Unit date: UFAC01
Contamination: PM25-PRI
EPA Control Code: Not reported
Control Eff: Not reported
Unit: TON

Permit Status: Not reported
Auth Status Code: Not reported
Emissions: 0.04871279
Issue date: Not reported
Expired Date: Not reported
Emission Unit date: EI0001
Contamination: PM25-PRI
EPA Control Code: Not reported
Control Eff: Not reported
Unit: TON

Permit Status: Not reported
Auth Status Code: Not reported
Emissions: 0.0031
Issue date: Not reported
Expired Date: Not reported
Emission Unit date: UFAC01
Contamination: 7440439
EPA Control Code: Not reported
Control Eff: Not reported

CONSOLIDATED PACKAGING GROUP INC-1250 METROPOLITA (Continued) **S106534423**

Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	UFAC01
Contamination:	7440417
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	UFAC01
Contamination:	206440
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	UFAC01
Contamination:	205992
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.1405
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	UFAC01
Contamination:	NOX
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	TON
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.0002
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	UFAC01
Contamination:	7440484
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB

CONSOLIDATED PACKAGING GROUP INC-1250 METROPOLITA (Continued) **S106534423**

Click this hyperlink while viewing on your computer to access
37 additional NY AIRS: record(s) in the EDR Site Report.

NY MANIFEST:

Name:	CONSOLIDATED PACKAGING
Address:	1250 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYD986892412
Facility Status:	Not reported
Location Address 1:	1250 METROPOLITAN AV
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986892412
Mailing Name:	CONSOLIDATED PACKAGING
Mailing Contact:	CONSOLIDATED PACKAGING
Mailing Address 1:	1250 METROPOLITAN AVENUE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184173434

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	12/07/2006
Trans1 Recv Date:	12/07/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/07/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986892412
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	000189063CEX
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

CONSOLIDATED PACKAGING GROUP INC-1250 METROPOLITA (Continued) **S106534423**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15750
Units:	P - Pounds
Number of Containers:	63
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F003
Waste Code 1_2:	F005
Waste Code 1_3:	D001
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

F47 **CONSOLIDATED PACKAGING GROUP** **RCRA-SQG** **1000245333**
NE **1250 METROPOLITAN AVE** **FINDS** **NYD986892412**
< 1/8 **BROOKLYN, NY 11237** **ECHO**
0.064 mi. **NJ MANIFEST**
338 ft. **Site 3 of 9 in cluster F**

Relative: **Lower**
Actual: **13 ft.**

RCRA-SQG:

Date Form Received by Agency:	20080307
Handler Name:	CONSOLIDATED PACKAGING GROUP
Handler Address:	1250 METROPOLITAN AVE
Handler City,State,Zip:	BROOKLYN, NY 11237
EPA ID:	NYD986892412
Contact Name:	GARY KAUFMAN
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	201-440-4240
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2007
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	BERGEN TNPK
Mailing City,State,Zip:	RIDGEFIELD PARK, NJ 07660
Owner Name:	CONSOLIDATED PACKAGING
Owner Type:	Private
Operator Name:	CONSOLIDATED PACKAGING

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Biennial: List of Years
Year: 2007

Click Here for Biennial Reporting System Data:
Year: 2003

Click Here for Biennial Reporting System Data:
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: RELIABLE POLY PACKAGING CO - ALEX GROSS
Legal Status: Private
Date Became Current: 20040101
Date Ended Current: Not reported
Owner/Operator Address: 1250 METROPOLITAN AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: 718-326-4770
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RELIABLE POLY PACK: CO
Legal Status: Private
Date Became Current: 19800101

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Date Ended Current:	Not reported
Owner/Operator Address:	METROPOLITAN AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11237
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RELIABLE POLY PACKAGING CO - ALEX GROSS
Legal Status:	Private
Date Became Current:	20040101
Date Ended Current:	Not reported
Owner/Operator Address:	1250 METROPOLITAN AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11237
Owner/Operator Telephone:	718-326-4770
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RELIABLE POLY PACKAGING CO INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	RELIABLE POLY PACK: CO
Legal Status:	Private
Date Became Current:	19800101
Date Ended Current:	Not reported
Owner/Operator Address:	METROPOLITAN AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11237
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED PACKAGING
Legal Status:	Private
Date Became Current:	19801231
Date Ended Current:	Not reported
Owner/Operator Address:	30 BERGEN TNPK
Owner/Operator City,State,Zip:	RIDGEFIELD PARK, NJ 07660
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Owner/Operator Name: CONSOLIDATED PACKAGING GROUP LLC
Legal Status: Private
Date Became Current: 20040101
Date Ended Current: Not reported
Owner/Operator Address: 1250 METROPOLITAN AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: 718-326-4770
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ALEX GROSS
Legal Status: Private
Date Became Current: 19800101
Date Ended Current: Not reported
Owner/Operator Address: METROPOLITAN AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED PACKAGING
Legal Status: Private
Date Became Current: 19801231
Date Ended Current: Not reported
Owner/Operator Address: 30 BERGEN TNPK
Owner/Operator City,State,Zip: RIDGEFIELD PARK, NJ 07660
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: CONSOLIDATED PACKAGING GROUP LLC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CONSOLIDATED PACKAGING GROUP LLC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900308
Handler Name: RELIABLE POLY PACKAGING CO INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20041216
Handler Name: CONSOLIDATED PACKAGING GROUP LLC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: RELIABLE POY PACK CO
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020219
Handler Name: RELIABLE POLY RACK
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Receive Date: 20040121
Handler Name: RELIABLE POLY PACK: CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080307
Handler Name: CONSOLIDATED PACKAGING GROUP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 322223
NAICS Description: COATED PAPER BAG AND POUCH MANUFACTURING

NAICS Code: 326111
NAICS Description: PLASTICS BAG AND POUCH MANUFACTURING

NAICS Code: 326112
NAICS Description: PLASTICS PACKAGING FILM AND SHEET (INCLUDING LAMINATED) MANUFACTURING

NAICS Code: 326199
NAICS Description: ALL OTHER PLASTICS PRODUCT MANUFACTURING

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Disposition Status Date: 20100407
Disposition Status: DR
Disposition Status Description: DROPPED
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 36370
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20100407
Disposition Status: DR
Disposition Status Description: DROPPED
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 36370
Final Monetary Amount: Not reported
Paid Amount: Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Manifest
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20100407
Disposition Status: DR
Disposition Status Description: DROPPED
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 36370
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Disposition Status Date:	20100407
Disposition Status:	DR
Disposition Status Description:	DROPPED
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	36370
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20100407
Disposition Status: DR
Disposition Status Description: DROPPED
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 36370
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Disposition Status Date:	20100407
Disposition Status:	DR
Disposition Status Description:	DROPPED
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	36370
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20061219
Actual Return to Compliance Date:	20100407
Return to Compliance Qualifier:	Unverifiable
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20080118
Enforcement Responsible Agency:	State
Enforcement Docket Number:	CO2-200711224-1
Enforcement Attorney:	C.C.
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20100407
Disposition Status:	DR
Disposition Status Description:	DROPPED
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	36370
Final Monetary Amount:	Not reported
Paid Amount:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Container Use and Management
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20100407
Disposition Status: DR
Disposition Status Description: DROPPED
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 36370
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Container Use and Management
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Disposition Status Date:	20100407
Disposition Status:	DR
Disposition Status Description:	DROPPED
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	36370
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20061219
Actual Return to Compliance Date:	20100407
Return to Compliance Qualifier:	Unverifiable
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20080118
Enforcement Responsible Agency:	State
Enforcement Docket Number:	CO2-200711224-1
Enforcement Attorney:	C.C.
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20100407
Disposition Status:	DR
Disposition Status Description:	DROPPED
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	36370
Final Monetary Amount:	Not reported
Paid Amount:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20100407
Disposition Status: DR
Disposition Status Description: DROPPED
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 36370
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Manifest
Date Violation was Determined:	20061219
Actual Return to Compliance Date:	20100407
Return to Compliance Qualifier:	Unverifiable
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20080118
Enforcement Responsible Agency:	State
Enforcement Docket Number:	CO2-200711224-1
Enforcement Attorney:	C.C.
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20100407
Disposition Status:	DR
Disposition Status Description:	DROPPED
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	36370
Final Monetary Amount:	Not reported
Paid Amount:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20100407
Disposition Status: DR
Disposition Status Description: DROPPED
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 36370
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20051206
Actual Return to Compliance Date: 20060220
Return to Compliance Qualifier: Documented
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20060120
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2AHJ
Enforcement Responsible Sub-Organization: RPB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Manifest
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20100407
Disposition Status: DR
Disposition Status Description: DROPPED
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 36370
Final Monetary Amount: Not reported
Paid Amount: Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-General Facility Standards
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20100407
Disposition Status: DR
Disposition Status Description: DROPPED
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 36370
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Disposition Status Date:	20100407
Disposition Status:	DR
Disposition Status Description:	DROPPED
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	36370
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-General Facility Standards
Date Violation was Determined:	20061219
Actual Return to Compliance Date:	20100407
Return to Compliance Qualifier:	Unverifiable
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20080118
Enforcement Responsible Agency:	State
Enforcement Docket Number:	CO2-200711224-1
Enforcement Attorney:	C.C.
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20100407
Disposition Status:	DR
Disposition Status Description:	DROPPED
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	NYJRI
Enforcement Responsible Sub-Organization:	CO
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	36370
Final Monetary Amount:	Not reported
Paid Amount:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20051206
Actual Return to Compliance Date: 20060220
Return to Compliance Qualifier: Documented
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20060120
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2AHJ
Enforcement Responsible Sub-Organization: RPB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Manifest
Date Violation was Determined: 20061219
Actual Return to Compliance Date: 20100407
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080118
Enforcement Responsible Agency: State
Enforcement Docket Number: CO2-200711224-1
Enforcement Attorney: C.C.
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20100407
Disposition Status: DR
Disposition Status Description: DROPPED
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYJRI
Enforcement Responsible Sub-Organization: CO
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 36370
Final Monetary Amount: Not reported
Paid Amount: Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20051206
Actual Return to Compliance Date: 20060220
Return to Compliance Qualifier: Documented
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20060120
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2AHJ
Enforcement Responsible Sub-Organization: RPB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20070816
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier: NYTLR
Evaluation Responsible Sub-Organization: CO
Actual Return to Compliance Date: 20100407
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20070816
Evaluation Responsible Agency: State

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYTLR
Evaluation Responsible Sub-Organization:	CO
Actual Return to Compliance Date:	20100407
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20061219
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	CO
Actual Return to Compliance Date:	20100407
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20061219
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	CO
Actual Return to Compliance Date:	20100407
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19930121
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20070816
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYTLR
Evaluation Responsible Sub-Organization:	CO
Actual Return to Compliance Date:	20100407

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20061219
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	CO
Actual Return to Compliance Date:	20100407
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20061219
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	CO
Actual Return to Compliance Date:	20100407
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20070816
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYTLR
Evaluation Responsible Sub-Organization:	CO
Actual Return to Compliance Date:	20100407
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20061219
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	CO
Actual Return to Compliance Date:	20100407
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Evaluation Date:	20070816
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYTLR
Evaluation Responsible Sub-Organization:	CO
Actual Return to Compliance Date:	20100407
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20061219
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	CO
Actual Return to Compliance Date:	20100407
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19981110
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2MD
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20070816
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYTLR
Evaluation Responsible Sub-Organization:	CO
Actual Return to Compliance Date:	20100407
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20070816
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYTLR

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Evaluation Responsible Sub-Organization: CO
Actual Return to Compliance Date: 20100407
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20051206
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2AHJ
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: 20060220
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20070816
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier: NYTLR
Evaluation Responsible Sub-Organization: CO
Actual Return to Compliance Date: 20100407
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20070816
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier: NYTLR
Evaluation Responsible Sub-Organization: CO
Actual Return to Compliance Date: 20100407
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20061219
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYJRI
Evaluation Responsible Sub-Organization: CO
Actual Return to Compliance Date: 20100407
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20061219
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYJRI
Evaluation Responsible Sub-Organization: CO
Actual Return to Compliance Date: 20100407
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20100407
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: NOT A SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier: NYJHE
Evaluation Responsible Sub-Organization: CO
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20051206
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2AHJ
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: 20060220
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20061219
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYJRI
Evaluation Responsible Sub-Organization: CO
Actual Return to Compliance Date: 20100407
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20051206
Evaluation Responsible Agency: EPA

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2AHJ
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	20060220
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110009462465

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000245333
Registry ID:	110009462465
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009462465
Name:	ALJO AUTO ELECTRIC CORP
Address:	1250 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY 11237

NJ MANIFEST:

EPA Id:	NYD986892412
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	7184173434
Emergency Phone:	Not reported
Contact:	ALEX GROSS
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	000000

Manifest:

Manifest Number:	000679165SKS
EPA ID:	NYD986892412
Date Shipped:	01/07/2008

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/07/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/07/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H020
Quantity:	15000 P

Manifest Number:	NJA5114181
EPA ID:	NYD986892412
Date Shipped:	02/06/2005
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/06/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/06/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	03170621
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	000578838SKS
EPA ID:	NYD986892412
Date Shipped:	09/17/2007
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/17/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/17/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H02
Quantity:	16000 P

Manifest Number:	NJA5112384
EPA ID:	NYD986892412
Date Shipped:	05/09/2006
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/09/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/09/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06210621
Was Load Rejected:	No

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5112622
EPA ID:	NYD986892412
Date Shipped:	05/23/2005
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/23/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/23/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06240521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	000651382SKS
EPA ID:	NYD986892412
Date Shipped:	11/19/2007
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Date Trans1 Transported Waste:	11/19/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/19/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	000189538CEX
EPA ID:	NYD986892412
Date Shipped:	02/07/2007
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/07/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/07/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H06
Quantity:	16000 P

Manifest Number:	NJA5297831
EPA ID:	NYD986892412
Date Shipped:	08/28/2006
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/28/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/28/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	09270621
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Manifest Number:	NJA5042852
EPA ID:	NYD986892412
Date Shipped:	08/15/2005
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/15/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/15/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	09120521
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	000224455SKS
EPA ID:	NYD986892412
Date Shipped:	05/30/2007
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/30/2007
Date Trans2 Transported Waste:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/30/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H02
Quantity:	16000 P

Manifest Number:	NJA5083330
EPA ID:	NYD986892412
Date Shipped:	02/05/2004
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/05/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/05/2004
TSDF EPA Facility Name:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	03170421
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5114254
EPA ID:	NYD986892412
Date Shipped:	11/23/2005
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/23/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/23/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	02140621
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	004257981JJK

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

EPA ID:	NYD986892412
Date Shipped:	08/19/2008
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD980772768
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/19/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/19/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	5 P

Manifest Number:	000292262SKS
EPA ID:	NYD986892412
Date Shipped:	07/17/2007
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/17/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/17/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H02
Quantity:	15000 P

Manifest Number:	000189946CEX
EPA ID:	NYD986892412
Date Shipped:	04/11/2007
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/11/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/11/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H02
Quantity:	16000 P

Manifest Number:	NJA5038388
EPA ID:	NYD986892412
Date Shipped:	04/22/2004
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/22/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/22/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05100422
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5062356
EPA ID:	NYD986892412
Date Shipped:	08/03/2004
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/03/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/03/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08300425
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	000651454SKS
EPA ID:	NYD986892412
Date Shipped:	12/04/2007
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/04/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/04/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA4026918
EPA ID:	NYD986892412
Date Shipped:	12/30/2004
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	NJD071629976
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/30/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

CONSOLIDATED PACKAGING GROUP (Continued) **1000245333**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/30/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	01310522
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

E48 **METROPOLITAN STEWART AVE** **NY Spills** **S103274820**
North **METROPOLITAN STEWART AVE** **N/A**
< 1/8 **QUEENS, NY**
0.065 mi.
345 ft. **Site 2 of 5 in cluster E**

Relative: **Lower**

Actual: **11 ft.**

SPILLS:

Name:	METROPOLITAN STEWART AVE
Address:	METROPOLITAN STEWART AVE
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9802640 / 1998-06-02
Facility ID:	9802640
Facility Type:	ER
DER Facility ID:	218254
Site ID:	267906
DEC Region:	2
Spill Cause:	Traffic Accident
Spill Class:	C4
SWIS:	4101
Spill Date:	1998-05-30
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1998-05-30
CID:	216
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-05-30
Spill Record Last Update:	1998-06-02
Spiller Name:	PASQUALE LOPEZ
Spiller Company:	CABEL TRUCKING

METROPOLITAN STEWART AVE (Continued) **S103274820**

Spiller Address:	KENVILE
Spiller Company:	001
Contact Name:	FIREFIGHTER HACK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 5/30/98 Spoke to NYFD Captain Doherty: FD recovered oil and put 50 gal into 55 gallon drum. put biosolve on street and flushed sewer. Nothing recoverable left in street or on sewer."
Remarks:	"truck hit a tractor trailor causing the above spill whick is now in the sewer system the fd is trying to recover what they can they have a sander enroute and they req a call from rep "

All Materials:

Site ID:	267906
Operable Unit ID:	1063298
Operable Unit:	01
Material ID:	320965
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	80.00
Units:	G
Recovered:	50.00
Oxygenate:	Not reported

D49 **CON EDISON** **NJ MANIFEST** **S120667906**
SSE **179 STEWART AVE** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.069 mi.
366 ft. **Site 5 of 7 in cluster D**

Relative:
Higher

Actual:
14 ft.

NJ MANIFEST:

EPA Id:	NYP004738597
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002610788GBF
EPA ID:	NYP004738597
Date Shipped:	2/25/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

CON EDISON (Continued) **S120667906**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

D50 **CON EDISON** **RCRA NonGen / NLR** **1018279063**
SSE **179 STEWART AVE** **FINDS** **NYP004738597**
< 1/8 **BROOKLYN, NY 11237** **ECHO**
0.069 mi.
366 ft. **Site 6 of 7 in cluster D**

Relative: RCRA NonGen / NLR:
Higher

Actual: Date Form Received by Agency:		20150225
14 ft. Handler Name:	CON EDISON	
Handler Address:		179 STEWART AVE
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYP004738597
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported

CON EDISON (Continued) **1018279063**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

CON EDISON (Continued) **1018279063**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20150225
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20150225
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20160205
Handler Name:	CON EDISON - SERVICE BOX 67739
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

CON EDISON (Continued) **1018279063**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150225
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150225
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067685598

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

CON EDISON (Continued) **1018279063**

ECHO:
- Envid: 1018279063
- Registry ID: 110067685598
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067685598
- Name: CON EDISON
- Address: 179 STEWART AVE
- City,State,Zip: BROOKLYN, NY 11237

D51 **CON EDISON** **NY MANIFEST** **S117740682**
SSE **179 STEWART AVE** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.069 mi.
366 ft. **Site 7 of 7 in cluster D**

Relative:
Higher

Actual:
14 ft.

NY MANIFEST:
- Name: CON EDISON
- Address: 179 STEWART AVE
- City,State,Zip: BROOKLYN, NY 11237
- Country: USA
- EPA ID: NYP004738597
- Facility Status: Not reported
- Location Address 1: 179 STEWART AVE
- Code: BP
- Location Address 2: Not reported
- Total Tanks: Not reported
- Location City: BROOKLYN
- Location State: NY
- Location Zip: 11237
- Location Zip 4: Not reported

NY MANIFEST:
- EPAID: NYP004738597
- Mailing Name: CON EDISON
- Mailing Contact: CON EDISON
- Mailing Address 1: 4 IRVING PL
- Mailing Address 2: 15TH FL
- Mailing City: NEW YORK
- Mailing State: NY
- Mailing Zip: 10003
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: Not reported

NY MANIFEST:
- Document ID: Not reported
- Manifest Status: Not reported
- seq: Not reported
- Year: 2018
- Trans1 State ID: NJD003812047
- Trans2 State ID: Not reported
- Generator Ship Date: 02/25/2015
- Trans1 Recv Date: 02/25/2015
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 02/27/2015
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYP004738597

CON EDISON (Continued) **S117740682**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002610788GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	8000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

G52 **PATSON CORP** **RCRA NonGen / NLR** **1011490373**
WSW **85 MEADOW ST** **FINDS** **NYN008019051**
< 1/8 **BROOKLYN, NY 11237** **ECHO**
0.069 mi.
366 ft. **Site 1 of 5 in cluster G**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:		20080509
Handler Name:	PATSON CORP	
Handler Address:		85 MEADOW ST
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYN008019051
Contact Name:		RICHARD MULLARE
Contact Address:		MEADOW ST
Contact City,State,Zip:		BROOKLYN, NY 11237
Contact Telephone:		718-497-7272
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified

Actual:
6 ft.

PATSON CORP (Continued) **1011490373**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	MEADOW ST
Mailing City,State,Zip:	BROOKLYN, NY 11237
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

PATSON CORP (Continued) **1011490373**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20080616
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20080509
Handler Name: PATSON CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violation:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported

PATSON CORP (Continued) **1011490373**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20080508
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2MD
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:

Registry ID: 110001613120

Click Here:

Environmental Interest/Information System:

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
AIR SYNTHETIC MINOR
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
RISK AND TECHNOLOGY REVIEW
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when

PATSON CORP (Continued) **1011490373**

complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1011490373
Registry ID:	110001613120
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110001613120
Name:	PATSON CORPORATION
Address:	85 MEADOW STREET
City,State,Zip:	BROOKLYN, NY 11206

G53 **209 MORGAN AVE. CORP.** **NY UST** **U004045182**
WSW **85 MEADOW STREET** **N/A**
< 1/8 **BROOKLYN, NY 11206**
0.069 mi.
366 ft. **Site 2 of 5 in cluster G**

Relative: **Lower**

Actual: **6 ft.**

UST:

Name:	209 MORGAN AVE. CORP.
Address:	85 MEADOW STREET
City,State,Zip:	BROOKLYN, NY 11206
Id/Status:	2-609985 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590022.08781
UTM Y:	4507262.61140
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	349533
Affiliation Type:	Facility Owner
Company Name:	MARTIN FRIEDMAN
Contact Type:	PRESIDENT
Contact Name:	MARTIN FRIEDMAN
Address1:	174 OUTLED 65 ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 387-5422
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG

209 MORGAN AVE. CORP. (Continued) **U004045182**

Date Last Modified: 2005-07-20

Site Id: 349533
Affiliation Type: Mail Contact
Company Name: 209 MORGAN AVE CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: 372 TEN EYK ST
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11206
Country Code: 001
Phone: (718) 497-5444
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-07-20

Site Id: 349533
Affiliation Type: Facility Operator
Company Name: 209 MORGAN AVE. CORP.
Contact Type: Not reported
Contact Name: MARTIN FRIEDMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 497-5444
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-07-20

Site Id: 349533
Affiliation Type: Emergency Contact
Company Name: MARTIN FRIEDMAN
Contact Type: Not reported
Contact Name: MARTIN FRIEDMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 387-5422
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-07-20

Tank Info:

Tank Number: #1
Tank ID: 207283

209 MORGAN AVE. CORP. (Continued) **U004045182**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	07/07/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KXTANG
Last Modified:	04/14/2017

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
L00 - Piping Leak Detection - None
I05 - Overfill - Vent Whistle

G54 **APT BUILDING TANK** **NY LTANKS** **S106972250**
WSW **85 MEADOW STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.069 mi.
366 ft. **Site 3 of 5 in cluster G**

Relative: **Lower**
Actual: **6 ft.**

LTANKS:

Name:	APT BUILDING TANK
Address:	85 MEADOW STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0504662 / 2005-12-09
Facility ID:	0504662
Site ID:	349596
Spill Date:	2005-07-19
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2005-07-19
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

APT BUILDING TANK (Continued) **S106972250**

Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-20
Spill Record Last Update:	2005-12-09
Spiller Name:	MR FRIEDMAN
Spiller Company:	GARAGE
Spiller Address:	84 MEADOW STREET
Spiller County:	001
Spiller Contact:	MR FRIEDMAN
Spiller Phone:	(718) 614-1896
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	296031
DEC Memo:	"Sangesland spoke to Vicky at Island Tank. This is a heating oil tank in the garage area of an apartment building. Island Tank is already doing the dig out and knows to take the end point samples. No Tank Test Failure or Contaminated Soil letter was sent. 09.22.05 SR// Sharif spoke with Mr. Friedman . He informed me Island Tank took care of the problem. I tried to hold Vicky but not able. 12/09/05-Sharif// I rec'd report prepared by Island Tank.The UST was 3000 gallons and was removed from the property as clean scrap metal.Six end point samples were taken from the UST cavity. Approx. 26 yards of contaminated soil was removed from the hole.Soil analytical result came back almost clean with no significant contaminants left at the site.Disposal manifests are provided. NFA action required."
Remarks:	"LINES ON 3000 GALLON TANK ARE ROTTED AND THEY NEED TO REMOVE SOME CONTAMINATED SOIL"

All Materials:

Site ID:	349596
Operable Unit ID:	1107185
Operable Unit:	01
Material ID:	2097080
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H55 **VARICK AVENUE** **NY SHWS** **S105973022**
SSW **165 VARICK AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 10013**
0.070 mi.
371 ft. **Site 1 of 6 in cluster H**

Relative:
Lower

Actual:
12 ft.

SHWS:

Name:	VARICK AVENUE
Address:	165 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 10013
Program:	HW
Site Code:	55914
Classification:	N

VARICK AVENUE (Continued) **S105973022**

Region:	2
Acres:	3.540
HW Code:	224017
Record Add:	11/18/1999
Record Upd:	04/03/2007
Updated By:	KALEWAND
Site Description:	"This property is located in Brooklyn (Block #2962 - lots 1, 5, & 37), and is owned by Rhino Trust (Albert Realty Co.). The site is a vacant lot, except for two, one-story shed buildings in a state of disrepair. The site has a develop- ment history dating back to the early 1900's; site uses have included an asphalt paving company and a lumber company. As a result of an environmental survey of this site conducted in 1988 and 1989, traces of 4-chloroaniline, pentachlorophenol, butyl-ben zylpthalate; di-N-butylphthalate and flouranthene were found. Metals and total petroleum hydrocarbons were also found in the soils, surface and groundwater. Contamination of soils by metals was found to include: silver, barium, cadmium, chromium , iron, lead and copper. Concentrations of metals in the groundwater exceeded groundwater quality standards for lead and iron. Rhino Trust has carried out a supplemental site assessment under a consent order in the summer of 1992. An interpretation of the analytical results from the previous investigation has been inconclusive due to data gaps in the reports. Rhino Trust performed a Supplemental Site Assessment, and the fieldwork was completed in 1994. The PRP has removed the contaminated soils. Hazardous waste is no longer present and significant threat no longer exists."
Env Problem:	"Contaminated soils have been removed but groundwater contamination evidently due to construction and demolition debris (non-hazardous), still exists."
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	3
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	MULTIPLE OWNERS
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	Unknown
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Rhino Trust
Owner Address:	P.O. BOX 637
Owner Addr2:	Not reported
Owner City,St,Zip:	ASPEN, CO 81612

VARICK AVENUE (Continued) **S105973022**

Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	*** MULTIPLE OWNERS ***
Owner Address:	P.O. BOX 637
Owner Addr2:	Not reported
Owner City,St,Zip:	ASPEN, CO 81612
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

H56 **VARICK AVENUE** **NY HSWDS** **S105212104**
SSW **165 VARICK AVENUE** **N/A**
< 1/8 **BROOKLYN, NY, NY 11237**
0.070 mi.
371 ft. **Site 2 of 6 in cluster H**

Relative: **Lower**

Actual: **12 ft.**

HSWDS:

Facility ID:	HS2043
Region:	2
Facility Status:	None
Owner Type:	Puplic
Owner:	Rhino Trust
Owner Address:	P.O. Box 637
Owner Phone:	(303)920-9307
Operator Type:	Not reported
Operator:	Not reported
Operator:	Not reported
Operator Phone:	Not reported
EPA ID:	None
Registry:	D
Registry Site ID:	224017
RCRA Permitted:	Unknown
Site Code:	Construction and Demolition Debris Site
Owner City State:	Aspen, CO 81612
Operator City State:	Not reported
Quadrange:	Brooklyn, NY
Latitude:	40 43 00
Longitude:	73 56 00
Acres:	3.54
Operator Date:	Unknown
Close Date:	Unknown
Completed:	PSA/IRM
Active:	Unknown
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	Yes
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	No

VARICK AVENUE (Continued) **S105212104**

Semi Volatile Organic Compounds Disposed:	Yes
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	Groundwater
Analytical Info Exists for Surface:	Surface Water
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Surface Soil
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	EPTox
Analytical Info Exists for TCLP:	TCLP
Threat to Environment/Public Health:	Environmental/Public
Surface Water Contamination:	Unknown
Surface Water Body Class:	SD
Groundwater Contamination:	Yes
Groundwater Classification:	Sole
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	No
Any Known Fish or Wildlife:	No
Hazardous Exposure:	No
Site Has Controlled Acess:	Yes
Ambient Air Contamination:	No
Direct Contact:	No
EPA Hazardous Ranking System Score:	1.3
Inventory:	Not reported
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	Not reported
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

E57 **1201 METROPOLITAN AVE** **NY Spills** **S106722285**
NNW **1201 METROPOLITAN AVE** **N/A**
< 1/8 **QUEENS, NY**
0.070 mi.
372 ft. **Site 3 of 5 in cluster E**

Relative:
Lower

Actual:
10 ft.

SPILLS:

Name:	1201 METROPOLITAN AVE
Address:	1201 METROPOLITAN AVE
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0407964 / 2006-01-26
Facility ID:	0407964
Facility Type:	ER
DER Facility ID:	267718
Site ID:	332541
DEC Region:	2
Spill Cause:	Other
Spill Class:	D4
SWIS:	4101
Spill Date:	2004-10-18
Investigator:	TPFESTA
Referred To:	Not reported
Reported to Dept:	2004-10-18
CID:	403
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-18
Spill Record Last Update:	2006-01-31
Spiller Name:	LT.SMITHWICK
Spiller Company:	Not reported
Spiller Address:	1201 METROPOLITAN AVE
Spiller Company:	001
Contact Name:	LT.SMITHWICK
DEC Memo:	"1/26/05 - Closed as per 2006 spill closure initiative program guidance."
Remarks:	"ruptured fuel tank caused about 12 gallons to spill out. they are leaving the over pact drum that they pumped the fuel in for pick-up."

All Materials:

Site ID:	332541
Operable Unit ID:	1094774
Operable Unit:	01
Material ID:	574905
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	12.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C58 **JJ KANG ENTERPRISE, INC.** **NY UST** **U003065891**
NW **1188 METROPOLITAN AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.071 mi.
377 ft. **Site 18 of 20 in cluster C**

Relative:
Lower

Actual:
9 ft.

UST:

Name:	JJ KANG ENTERPRISE, INC.
Address:	1188 METROPOLITAN AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Id/Status:	2-602411 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	08/17/2025
UTM X:	590428.35289
UTM Y:	4507574.49366
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	24368
Affiliation Type:	Mail Contact
Company Name:	JJ KANG ENTERPRISE, INC.
Contact Type:	Not reported
Contact Name:	JERNAIL SINGH
Address1:	1188 METROPOLITAN AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 366-0949
EMail:	GENERALMOTOR53@GMAIL.COM
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2020-09-08

Site Id:	24368
Affiliation Type:	Emergency Contact
Company Name:	DIECOR REALTY CORP.
Contact Type:	Not reported
Contact Name:	JERNAIL SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 217-4991
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-03-05

Site Id:	24368
Affiliation Type:	Facility Owner
Company Name:	DIECOR REALTY CORP.
Contact Type:	PRESIDENT
Contact Name:	JERNAIL SINGH
Address1:	1194 METROPOLITAN AVENUE

JJ KANG ENTERPRISE, INC. (Continued) **U003065891**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 628-5000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-03-01

Site Id:	24368
Affiliation Type:	Facility Operator
Company Name:	JJ KANG ENTERPRISE, INC.
Contact Type:	Not reported
Contact Name:	JERNAIL SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 366-0949
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-03-01

Tank Info:

Tank Number:	01
Tank ID:	50004
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	05/01/1955
Date Tank Closed:	02/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	21
Date Test:	03/26/2001
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JMKRIMGO
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

JJ KANG ENTERPRISE, INC. (Continued) **U003065891**

B01 - Tank External Protection - Painted/Asphalt Coating
J01 - Dispenser - Pressurized Dispenser
F00 - Pipe External Protection - None

Tank Number:	019
Tank ID:	232527
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	01/01/2008
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	10/22/2019

Equipment Records:

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin
I03 - Overfill - Automatic Shut-Off
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser

Tank Number:	02
Tank ID:	50005
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	05/01/1955
Date Tank Closed:	02/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	21
Date Test:	03/26/2001
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JMKRIMGO

JJ KANG ENTERPRISE, INC. (Continued) **U003065891**

Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 020
Tank ID: 232528
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 01/01/2008
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DAFRANCI
Last Modified: 10/22/2019

Equipment Records:

F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser

Tank Number: 021
Tank ID: 232529
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 01/01/2008
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground

JJ KANG ENTERPRISE, INC. (Continued) **U003065891**

Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DAFRANCI
Last Modified: 10/22/2019

Equipment Records:

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG

Tank Number: 022
Tank ID: 232530
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 01/01/2008
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DAFRANCI
Last Modified: 10/22/2019

Equipment Records:

C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E04 - Piping Secondary Containment - Double walled UG

JJ KANG ENTERPRISE, INC. (Continued) **U003065891**

J01 - Dispenser - Pressurized Dispenser

Tank Number: 023
Tank ID: 232531
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 01/01/2008
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DAFRANCI
Last Modified: 10/22/2019

Equipment Records:

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG

Tank Number: 03
Tank ID: 50006
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1955
Date Tank Closed: 02/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 03/26/2001
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JMKRIMGO
Last Modified: 04/14/2017

JJ KANG ENTERPRISE, INC. (Continued) **U003065891**

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	04
Tank ID:	50007
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	05/01/1955
Date Tank Closed:	02/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	21
Date Test:	03/26/2001
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JMKRIMGO
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	05
Tank ID:	50008
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	05/01/1955
Date Tank Closed:	02/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

JJ KANG ENTERPRISE, INC. (Continued) **U003065891**

Tightness Test Method: 21
Date Test: 03/26/2001
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JMKRIMGO
Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number: 06
Tank ID: 50009
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1955
Date Tank Closed: 02/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 03/26/2001
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JMKRIMGO
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 07
Tank ID: 50010
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1955
Date Tank Closed: 02/01/1999

JJ KANG ENTERPRISE, INC. (Continued) **U003065891**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 03/26/2001
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JMKRIMGO
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number: 08
Tank ID: 50011
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1955
Date Tank Closed: 02/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 03/26/2001
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JMKRIMGO
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 09

JJ KANG ENTERPRISE, INC. (Continued) **U003065891**

Tank ID: 50012
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1955
Date Tank Closed: 02/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 03/26/2001
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JMKRIMGO
Last Modified: 04/14/2017

Equipment Records:
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number: 10
Tank ID: 50013
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/05/1955
Date Tank Closed: 02/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 21
Date Test: 03/26/2001
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JMKRIMGO
Last Modified: 04/14/2017

Equipment Records:
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None

JJ KANG ENTERPRISE, INC. (Continued) **U003065891**

I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number: 11
Tank ID: 50014
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 08/01/1991
Date Tank Closed: 02/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JMKRIMGO
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G99 - Tank Secondary Containment - Other
H00 - Tank Leak Detection - None
I00 - Overfill - None
A01 - Tank Internal Protection - Epoxy Liner
B04 - Tank External Protection - Fiberglass
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser

Tank Number: 12
Tank ID: 50015
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1080
Install Date: 08/01/1991
Date Tank Closed: 02/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JMKRIMGO
Last Modified: 04/14/2017

Equipment Records:

JJ KANG ENTERPRISE, INC. (Continued) **U003065891**

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G99 - Tank Secondary Containment - Other
I01 - Overfill - Float Vent Valve
H00 - Tank Leak Detection - None
B04 - Tank External Protection - Fiberglass
D02 - Pipe Type - Galvanized Steel
A99 - Tank Internal Protection - Other
F99 - Pipe External Protection - Other

Tank Number: 13
Tank ID: 50016
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1080
Install Date: 08/01/1991
Date Tank Closed: 02/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0003
Common Name of Substance: #6 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JMKRIMGO
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G99 - Tank Secondary Containment - Other
I01 - Overfill - Float Vent Valve
H00 - Tank Leak Detection - None
B04 - Tank External Protection - Fiberglass
D02 - Pipe Type - Galvanized Steel
A99 - Tank Internal Protection - Other
F99 - Pipe External Protection - Other

Tank Number: 14
Tank ID: 50017
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 03/01/1999
Date Tank Closed: 02/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported

JJ KANG ENTERPRISE, INC. (Continued) **U003065891**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JMKRIMGO
Last Modified: 04/14/2017

Equipment Records:

F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)
I01 - Overfill - Float Vent Valve
H00 - Tank Leak Detection - None
B04 - Tank External Protection - Fiberglass
D02 - Pipe Type - Galvanized Steel
A99 - Tank Internal Protection - Other

Tank Number: 15
Tank ID: 50018
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 08/01/1991
Date Tank Closed: 12/12/2014
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 03/25/2001
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DAFRANCI
Last Modified: 02/06/2018

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None

C59 **BUY RITE GARAGE INC** **RCRA NonGen / NLR** **1001818359**
NW **1188 METROPOLITAN AVE** **ICIS** **NYU005001680**
< 1/8 **BROOKLYN, NY 11237** **US AIRS**
0.071 mi.
377 ft. **Site 19 of 20 in cluster C**

Relative: **Lower**
Actual: **9 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	BUY RITE GARAGE INC	
Handler Address:		1188 METROPOLITAN AVE
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYU005001680
Contact Name:		Not reported
Contact Address:		METROPOLITAN AVE
Contact City,State,Zip:		BROOKLYN, NY 11237
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		METROPOLITAN AVE
Mailing City,State,Zip:		BROOKLYN, NY 11237
Owner Name:		NON REGULATED
Owner Type:		Private
Operator Name:		NON REGULATED
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

BUY RITE GARAGE INC (Continued) **1001818359**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NON REGULATED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	718-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NON REGULATED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	718-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

BUY RITE GARAGE INC (Continued) **1001818359**

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NON REGULATED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	718-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990928
Handler Name: BUY RITE GARAGE INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: BUY RITE GARAGE INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: BUY RITE GARAGE INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

BUY RITE GARAGE INC (Continued) **1001818359**

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19990910
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2MML
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

ICIS:
Enforcement Action ID: 02-2000-1062

BUY RITE GARAGE INC (Continued) **1001818359**

FRS ID: 110009488465
Action Name: BUYRITE UNITED FUEL & OIL COMPANY
Facility Name: BUY RITE GARAGE INC
Facility Address: 1188 METROPOLITAN AVE
BROOKLYN, NY 11237
Enforcement Action Type: CAA 113A Admin Compliance Order (Non-Penalty)
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 113A
Facility SIC Code: 4932
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.714257
Longitude in Decimal Degrees: -73.929321
Permit Type Desc: Not reported
Program System Acronym: 3793
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-1999-0017
FRS ID: 110009488465
Action Name: BUY-RITE GARAGE INC
Facility Name: BUY RITE GARAGE INC
Facility Address: 1188 METROPOLITAN AVE
BROOKLYN, NY 11237
Enforcement Action Type: Civil Judicial Action
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Judicial
EA Type Code: CIV
Facility SIC Code: 4932
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.714257
Longitude in Decimal Degrees: -73.929321
Permit Type Desc: Not reported
Program System Acronym: 3793
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: BUY RITE GARAGE INC
Address: 1188 METROPOLITAN AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 4932

Facility Name: BUY RITE GARAGE INC
Address: 1188 METROPOLITAN AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 4932

Facility Name: BUY RITE GARAGE INC
Address: 1188 METROPOLITAN AVE
Tribal Indicator: N

BUY RITE GARAGE INC (Continued) **1001818359**

Fed Facility: No
NAIC Code: Not reported
SIC Code: 4932

Facility Name: BUY RITE GARAGE INC
Address: 1188 METROPOLITAN AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 4932

US AIRS MINOR:
Envid: 1001818359
Region Code: 02
Programmatic ID: AIR 020000003604700500
Facility Registry ID: 110009488465
D and B Number: Not reported
Primary SIC Code: 4932
NAICS Code: 221210
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR 020000003604700500
Facility Registry ID: 110009488465
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-03-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

C60 **METRO GARAGE** **NY AST** **S108982334**
NW **1188 METROPOLITAN AVE** **NY Spills** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.071 mi.
377 ft. **Site 20 of 20 in cluster C**

Relative: **Lower**
Actual: **9 ft.**

AST:
Name: JJ KANG ENTERPRISE, INC.
Address: 1188 METROPOLITAN AVENUE
City,State,Zip: BROOKLYN, NY 11237
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-602411
Program Type: PBS
UTM X: 590428.35289
UTM Y: 4507574.49366
Expiration Date: 08/17/2025
Site Type: Retail Gasoline Sales

METRO GARAGE (Continued) **S108982334**

Affiliation Records:

Site Id:	24368
Affiliation Type:	Mail Contact
Company Name:	JJ KANG ENTERPRISE, INC.
Contact Type:	Not reported
Contact Name:	JERNAIL SINGH
Address1:	1188 METROPOLITAN AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 366-0949
EMail:	GENERALMOTOR53@GMAIL.COM
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2020-09-08

Site Id:	24368
Affiliation Type:	Emergency Contact
Company Name:	DIECOR REALTY CORP.
Contact Type:	Not reported
Contact Name:	JERNAIL SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 217-4991
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-03-05

Site Id:	24368
Affiliation Type:	Facility Owner
Company Name:	DIECOR REALTY CORP.
Contact Type:	PRESIDENT
Contact Name:	JERNAIL SINGH
Address1:	1194 METROPOLITAN AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 628-5000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-03-01

Site Id:	24368
Affiliation Type:	Facility Operator
Company Name:	JJ KANG ENTERPRISE, INC.
Contact Type:	Not reported
Contact Name:	JERNAIL SINGH

METRO GARAGE (Continued) **S108982334**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 366-0949
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-03-01

Tank Info:

Tank Number:	024
Tank Id:	281852

Equipment Records:

G12 - Tank Secondary Containment - Double-Walled (AG only)
I05 - Overfill - Vent Whistle
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
J06 - Dispenser - Tank Mounted Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Galvanized Steel Alloy
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/2018
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DAFRANCI
Last Modified:	10/22/2019
Material Name:	diesel

Tank Number:	025
Tank Id:	281853

Equipment Records:

G12 - Tank Secondary Containment - Double-Walled (AG only)
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping

METRO GARAGE (Continued) **S108982334**

F00 - Pipe External Protection - None
J06 - Dispenser - Tank Mounted Dispenser
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Galvanized Steel Alloy
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/2018
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DAFRANCI
Last Modified:	10/22/2019
Material Name:	diesel
Tank Number:	026
Tank Id:	281854

Equipment Records:

G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
J06 - Dispenser - Tank Mounted Dispenser
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/2018
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DAFRANCI
Last Modified:	10/22/2019
Material Name:	diesel
Tank Number:	027
Tank Id:	281855

METRO GARAGE (Continued) **S108982334**

Equipment Records:

G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
J06 - Dispenser - Tank Mounted Dispenser
D02 - Pipe Type - Galvanized Steel
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/2018
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DAFRANCI
Last Modified:	10/22/2019
Material Name:	diesel

SPILLS:

Name:	PREMIUM OIL
Address:	1188 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0011310 / 2003-09-15
Facility ID:	0011310
Facility Type:	ER
DER Facility ID:	276844
Site ID:	173941
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-01-17
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2001-01-17
CID:	270
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

METRO GARAGE (Continued) **S108982334**

Date Entered In Computer:	2001-01-17
Spill Record Last Update:	2003-09-15
Spiller Name:	CALLER
Spiller Company:	PREMIUM OIL
Spiller Address:	1188 METROPOLITIAN AV
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 9/15/03 - AUSTIN - STREET SPILL - CLOSED IN DATABASE - ORIG. ASSIGNED TO ROMMEL - END"
Remarks:	"pipe broke on truck and caller thinks that some may have gotten into sewer. clean up in progress"

All Materials:

Site ID:	173941
Operable Unit ID:	832708
Operable Unit:	01
Material ID:	541630
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	METRO GARAGE
Address:	1188 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0206038 / 2004-03-16
Facility ID:	0206038
Facility Type:	ER
DER Facility ID:	276844
Site ID:	173942
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	2002-09-10
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2002-09-11
CID:	270
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2002-09-11
Spill Record Last Update:	2004-03-16
Spiller Name:	CALLER
Spiller Company:	METRO GARAGE

METRO GARAGE (Continued) **S108982334**

Spiller Address:	1188 METROPOLITIAN AV
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 3/16/04-Vought-This spill closed and referred to spill #0302832 at same location."
Remarks:	"piping failure on tanks at location. "

All Materials:

Site ID:	173942
Operable Unit ID:	858526
Operable Unit:	01
Material ID:	516652
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	IN ROADWAY
Address:	1188 METROPOLITAN
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0711153 / 2008-01-22
Facility ID:	0711153
Facility Type:	ER
DER Facility ID:	342171
Site ID:	392573
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2008-01-22
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2008-01-22
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-01-22
Spill Record Last Update:	2011-07-22
Spiller Name:	MITCHEL
Spiller Company:	RIGHT WAY FUEL OIL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	FIREMAN SARNELL
DEC Memo:	"1/22/08 - Raphael Ketani. I called Fireman Scott Sarnell of Hazmat 1 (347) 203-6886. He said that a tanker truck had leaked #2 oil onto

METRO GARAGE (Continued) **S108982334**

the street at Metropolitan Avenue and Varick Street. The surface spill is about 100 feet long and covers a 4 lane road. So the surface spill is about 50 gals. He said there is another 90 gals. in the sewer. Fireman Sarnell said that Sanitation is sending a sander. I contacted DOS and DEP about the spill. Later, I received an updated spill report stating that the NYFD units were containing the spill. Fireman Sarnell also stated in the revised report that Right Way Fuel Oil (718) 574-4004 had hired Trade Winds to do the cleanup. As the NYFD is containing the street spill, Trade Winds is coming to do the cleanup, and the DEP and DOS have been notified, I am closing the spill case. 1/23/08 - Raphael Ketani. I contacted Right Way and spoke to Mitchel. He said they were welding the pipe that had leaked on the truck. He said that Trade Winds had worked into the night yesterday and they will finish the cleanup today. He said they had pumped out the sewer."

Remarks: "50 GALLONS ON GROUND WITH AN UNDETERMINED AMOUNT IN THE SEWER; IN ROUTE TO SCENE AND REPOSONSIBLE PARTY ON SITE; UNITS ON SCENE ARE CONTAINING THE MATERIAL AND THE RESPONSIBLE PARTY WILL BE HANDLING THE CLEAN UP;"

All Materials:

Site ID:	392573
Operable Unit ID:	1149565
Operable Unit:	01
Material ID:	2140096
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	392573
Operable Unit ID:	1149565
Operable Unit:	01
Material ID:	2140094
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	METRO GARAGE
Address:	1188 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY 11237
Spill Number/Closed Date:	0302832 / 2012-01-18
Facility ID:	0302832
Facility Type:	ER
DER Facility ID:	396848
Site ID:	99222
DEC Region:	2
Spill Cause:	Other

METRO GARAGE (Continued) **S108982334**

Spill Class:	C4
SWIS:	2401
Spill Date:	2003-06-17
Investigator:	RVKETANI
Referred To:	Not reported
Reported to Dept:	2003-06-17
CID:	216
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-17
Spill Record Last Update:	2013-06-14
Spiller Name:	DENNIS FIRPO
Spiller Company:	METRO GARAGE
Spiller Address:	1188 METROPOLITAN AVE
Spiller Company:	999
Contact Name:	CHARLES SCHMIDGALL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL Sangesland DDO Charles Schmidgall of Aggressive Environmental 631-224-1680 Gas Station which was never registered is now under an EPA court order to pull tanks. Of 10 - 550's on site, 7 were removed, 3 are under the building and are being abandoned in place. 4 other tanks are also probably being pulled: Two 1080 gal, One 2000 gal, One 4000 gal. The owner would like to get two of these tanks approved for heating oil storage. Mr. Schmidgall says the excavation is heavily contaminated. He is trying to dig out as much contaminated soil as possible. Sangesland directed him to do a delineation and a remediation plan. Contaminated soil letter was sent to the owner: Dennis Firpo 1188 Metropolitan Ave. Brooklyn, NY 11237 10/20/03 TJD cross reference spill #0206511. 12/9/03 TJD Spill reassigned Demeo greater than greater than greater than Rommel. 3/16/04-Vought-See also closed spill #0206038 at same location. PBS 2-602411 5/18/2006 - Mike - Contacted Dennis Firpo who is aware that he needs to deal with soil problem. Also spoke with Russel Construction (718-909-0148) who is doing the work with Agressive Environmental. Firpo still has fines he has to pay to the EPA. Work along with soil testing and removal of if contamination, is going to be performed within the next eight weeks by Russel Construction once the fines are paid. Gave the spill number to Russel Construction so they can report back once the work is done at the site. 10/29/10 - Austin - Reassigned from Scibelli in Albany to Ketani in Region 2 for following up and closing - end 11/9/10 - Raphael Ketani. The spill was called in on 6/17/03. The spill involved the discovery of contaminated soil while removing the tanks. The site is block and lot 2945 and 8. According to the deed dated 12/23/93 in ACRIS, the owner is Diecor Realty Corp., 1176 Metropolitan Avenue, Brklyn, 11237. The NYC MAP DoITT database shows the site address as including 228 and 230 Varick Avenue. The property includes an L shaped building along the southern part of the combined property. The PBS is #2-602411. There were 23 tanks. The first 14 were closed and removed on 2/1/99. Tank #15 is a 550 gal. UST with #2 oil. Tanks #16 to #23 are each 4,000 gals. and contain either

METRO GARAGE (Continued) **S108982334**

gasoline or diesel fuel. The owner is listed as Die Cor Realty Corp., 1194 Metropolitan Avenue, Brklyn. Dennis Firpo is the contact at (718) 628-5000. Mail goes to Mr. Firpo (718) 381-5050 at 1188 Metropolitan Avenue. There is no paper file. There is only a CSL in the E-docs. There are 4 other spill cases for 1188 Metropolitan Avenue. These are closed cases: 0011310; 0206038 (referred to this case); 0206511 (referred to this case); 0711153. In general, the cases involved spills of oil onto the ground and into the sewers, and contaminated soil. I tried to contact Mr. Firpo, the owner, at (718) 381-5050. I reached his secretary. She said that he wasn't in yet, but that she will give him my message. I asked her whether the addresses 1176 and 1194 were part of the same company. She said that she didn't think they were. I asked her whether (718) 628-5000 was also Mr. Firpo's number. She said that I could call this number, too. Mr. Firpo called me back. He said that Russel Construction (718) 909-0148 had done all of the tank pulling and cleaning. He said that he wasn't sure whether he had the cleanup report, but he will look for it. I told him that if he doesn't have the report and Russel doesn't have the report, then a new investigation will need to take place. I asked him what the correct name of the company was. Mr. Firpo said it's called Metro Garage. I tried to contact Russel Construction and request a copy of the cleanup report, but I could only leave a phone message for James. 11/15/10 - Raphael Ketani. Mike Gimelfarb of GE Consulting (718) 997-1282/ cell (917) 868-4713/e-mail gimelfarb.m@att.net called regarding the site. He said that he was the consultant on the job. He thought that all of the reports had been sent to the DEC. I told him that we had nothing. He said that he will look into the matter. Later, I spoke to James. He said that the phone number I had called was his number, not that of Russel Construction. He had no forwarding information regarding Russel Construction. Next, I tried to contact Mr. Firpo. However, again, I reached one of his secretaries. I left a message that I could not get the cleanup report from Russel Construction and that he was responsible for either providing the report or doing another investigation. Mr. Firpo returned my call. He said that he contacted his architect, Mr. Gimelfarb, and Russel Construction. He said that they, as well as he, are looking for the cleanup report. 12/14/10 - Raphael Ketani. Rich Spadalik of ARCO (631) 586-5900 called to request information regarding the spill. He wanted to know who were the parties involved in the cleanup of the site. I gave him the various names. Mr. Spadalik said that Russel Construction went out of business. He tried to contact them (as they owed him money), but he had no success and couldn't find them. He said that he will look for any documents that he has. 2/18/11 - Raphael Ketani. As there has been no response in some time from either Mr. Firpo or Mr. Gimelfarb, and as I haven't received the remediation report, I sent a followup letter to Mr. Firpo. I set a deadline of March 18, 2011 for the remediation report to be submitted or for another soil investigation to take place. 3/3/11 - Raphael Ketani. Mr. Gimelfarb [(718) 997-1282/ cell (917) 868-4713/e-mail gimelfarb.m@att.net] called me today. He wanted to know what Mr. Firpo needed to resolve the spill case. I told him that either he should send me the complete remediation report for the work that was performed previously or he should start a new investigation. Mr. Gimelfarb stated that Russel Construction did the work. However, they were out of business and so the remediation report could not be obtained. I told Mr. Gimelfarb that, in such a case, a new investigation will have to be performed.

METRO GARAGE (Continued) **S108982334**

I told him that Mr. Firpo had until March 18 to send the DEC a work plan for the new investigation. Mr. Gimelfarb said that he understood. Later, Sandy of Volumetric Techniques (VTEQE) (631) 472-4848 called. He wanted to know what the site was about and what the DEC was asking to be done. I told him that the DEC was requiring a full soil and groundwater contamination delineation and groundwater flow determination. He said that he will submit a proposal to Mr. Firpo. He said to contact him in 3 weeks if DEC doesn't hear back from him. 3/14/11 - Raphael Ketani. I spoke to Ariel Czemerinski cell (516) 987-1662. He wanted to know what type of work was required at the site. I told him that the soil and groundwater contamination will need to be delineated and the groundwater flow direction will need to be determined. 3/18/11 - Raphael Ketani. As the work plan had not been submitted by today, the deadline that was indicated in the followup letter, I sent a STIP package to Mr. Firpo. I set a deadline for submission of the signed STIP of April 15. 3/23/11 - Raphael Ketani. The green return card was received with a squiggle as someone's signature in the signature box. Today, I received the soil and groundwater delineation work plan from Volumetric Techniques (VTEQE), Ltd. dated 3/22/11. I began my reivew. 3/24/11 - Raphael Ketani. Jared Bretas (212) 788-3220 of the Mayor's Office of Environmental Remediation called. He said that there is a tax lene on Mr. Firpo's property. The Mayor's Office is trying to estimate how much the property is worth in preparation for an auction. I read some of the case notes to Mr. Bretas. He thanked me and the call ended. 3/28/11 - Raphael Ketani. I finished my review of the VTEQE work plan. They proposed 5 boring locations which they estimated to be on the downgradient side of 3 abandoned tanks, 5 active tanks and 3 pump islands. They will collect the most contaminated soil sample, the lowest dry soil sample and a groundwater sample from each boring. As this is an initial investigation, I found the plan to be acceptable. I called up Sander Sternig, Director (631) 472-4848, and told him that the plan was acceptable and to proceed as soon as possible. 4/15/11 - Raphael Ketani. The investigation report was due today. I tried to contact Mr. Sternig (631) 472-4848, but could only leave a message. The message stated that the report was due today. I spoke to Mr. Firpo (718) 381-5050. I asked him why the STIP wasn't sent in. He said that he had given Mr. Gimelfarb all of his paperwork. I told Mr. Firpo that he needed to send the signed STIP to the DEC and today was the due date. I added that he was risking receiving fines and penalties by not sending in the STIP on time. Mr. Firpo said that he will contact Mr. Gimelfarb and try to find out why the STIP wasn't sent in. I asked Mr. Firpo who he had retained as a contractor. He said that it was VTEQE. I told him that the DEC had approved the work plan some time ago and we are now waiting for the investigation report. Mr. Firpo said that he will get back to me. Later, Mr. Firpo called me and said that he had the STIP. He said that he will FAX the signed STIP and send the original by regular mail. I received the FAXed version of the STIP a little while later. 4/16/11 - Raphael Ketani. Mr. Sternig (Sandy) (631) 472-4848/cell (631) 514-1094 called me today, saturday, and left a message. He said that the investigation work was conducted on 4/8/11. There was contamination upgradient. End point samples were taken. The samples have been sent to the lab. 4/18/11 - Raphael Ketani. Today I received the signed STIP with the original signature which had arrived by regular mail. I walked it up to our legal division with a cover memo to our director, Suzanne Matei. 4/21/11 - Raphael Ketani. I received the STIP package

METRO GARAGE (Continued) **S108982334**

with the approval signature of Suzanne Matei, Director of Region 2. I sent the approved STIP to Mr. Firpo. 5/23/11 - Raphael Ketani. I spoke to Mr. Sternig (Sandy) (631) 472-4848/cell (631) 514-1094. He said that he received the analytical results. There is gasoline contamination both upgradient and downgradient. The concentrations of the different analytes are greater upgradient. The upgradient sample was taken at the edge of the sidewalk where there is another property (a large warehouse that fronts on Metropolitan and Varick) that has a gas UST, according to Mr. Sternig. There is also a diesel pump in this building. He added that one has to walk down the block and look inside and I would see an old car over the UST and the diesel pump. Mr. Sternig said that he will not submit the investigation report as Mr. Firpo owes him lots of money. I tried to contact Mr. Firpo (718) 381-5050, but I could only leave a message that the DEC needed to receive the investigation report. 5/24/11 - Raphael Ketani. I made an unannounced site visit. Metro Garage is a SUNOCO station. They service cars and pump gas. The site is at the corner of Varick Avenue and Metropolitan Avenue. I saw one round mark in the sidewalk in front of the site which was probably from a soil boring. Across Varick Avenue there was what looked like a warehouse. I saw a fill port and vent pipe for the warehouse, but nothing else. 5/25/11 - Raphael Ketani. I tried to contact Mr. Firpo, but could only leave a message. Later, I contacted Mr. Sternig and asked him to include a page in the investigation report that he will submit showing a schedule for the additional work that must take place and for sending in reports. He said that he will. 5/26/11 - Raphael Ketani. Mr. Firpo (718) 381-5050/cell (917) 603-0377 tried to contact me yesterday after work, but I wasn't in. I tried to return his call today, but could only leave a message. Mr. Firpo returned my call. I told him that the DEC hadn't received the investigation report. He said that he thought Mr. Sternig was going to send it when he talked to him weeks ago. I told him that Mr. Sternig was holding the report until he receives more money. Mr. Firpo said that he will give Mr. Sternig enough money so that he releases the report. He said that I should get the report next week. I told Mr. Firpo that I will keep an eye out for it. 6/16/11 - Raphael Ketani. I received the June 7, 2011 VTEQE soil and groundwater delineation report yesterday. Groundwater was found to be at about 8 feet below grade. It is believed to be tidal as Maspeth Creek is one block to the north and one block to the west. The soil results were almost entirely non-detect for the first three samples and below CP-51 standards for #4 and #5 (except for 1,2,4-trimethylbenzene which was a little elevated). SVOCs were almost entirely non-detect or below standards. For the groundwater, only the sample from #5 had exceedences that were slightly elevated. There were six analytes and the highest concentration was 277 ppb for 1,2,4-trimethylbenzene in the sample from #5. Well installation is supposed to take place during mid-July. Sampling is supposed to take place during mid-August. A RAP will be submitted in mid-September. I spoke to Mr. Sternig (Sandy) (631) 472-4848/cell (631) 514-1094 about the results and data in the report. I asked him where the active diesel tank was. He said that it is under the sidewalk near boring #5. Mr. Sternig added that the diesel pump is here, too. He said that it didn't make sense to install another boring between locations #4 and #5 because the utilities below the sidewalk prevented him from putting another boring in a middle location. He could have installed another boring near the edge of the building, but then he would have been next to one of the borings. I told Mr. Sternig that installing

METRO GARAGE (Continued) **S108982334**

just the two borings sounded fine. I also told him that the only issue I saw was the groundwater contamination at #5. I added that he should install two permanent wells, one at #5 and one further south to see whether the contamination is from off site. I stated that he should try a couple of groundwater evacuations to see whether the water will clean up. Mr. Sternig said that he will approach Mr. Firpo with the idea of installing the wells and doing the groundwater recovery and sampling. However, Mr. Firpo still owes him lots of money. 7/22/11 - Raphael Ketani. I spoke to Mr. Sternig (Sandy) (631) 472-4848/cell (631) 514-1094. He said that he had installed a couple of wells upgradient of Metro Garage. He found many gas constituents in the groundwater just upgradient and fewer constituents in the groundwater further upgradient. Mr. Sternig believes that there are gas USTs in this neighboring building at about 230 Varick Avenue, but he could not find any PBS registrations for the facility. He added that Mr. Firpo never had gas USTs in an upgradient location bordering the neighboring building. He said that the DEC will receive a report regarding this part of the investigation by e-mail and hard copy. I told him that I will look out for them. I reminded Mr. Sterning that he had said that he will approach Mr. Firpo regarding the installation of two permanent recovery wells. Mr. Sternig said that he had forgotten to approach Mr. Firpo about this, but he will. Later, Mr. Sternig sent me the VTEQE 7/20/11 data results report. This report showed that well MW-1 was installed next to boring #5 just upgradient (allegedly) and that well MW-2 was installed about 75 feet further upgradient. Both wells were at the corners of the neighboring, upgradient building. Well MW-1 is supposedly next to a gasoline UST that is in this neighboring building. The soil analytical results for borings #1 to #5 were almost entirely non-detect or below CP-51 standards for VOCs, except for a couple of hits for boring #5. These were 6500 ppb of 1,2,4-trimethylbenzene and 2595 ppb of total xylenes. The SVOCs were almost entirely non-detect. Groundwater samples for the 5 borings were almost entirely non-detect. However, the sample for #5 had many below standard hits. Naphthalene was at 141 ppb, 1,2,4-trimethylbenzene was at 277 ppb and total xylenes were at 237 ppb. The groundwater SVOCs were almost entirely non-detect with several hits for the #5 sample. Only groundwater results were presented for MW-1 and MW-2. They showed many VOC and SVOC hits and exceedences. MW-1 had very high exceedences for phenanthrene (4470 ppb), flourene (1280 ppb), and four other SVOCs in the hundreds of parts per billion. MW-2 had very high exceedences for naphthalene (906 ppb), and 4-isopropyltoluene (488 ppb). I spoke to Mr. Sternig (631) 472-4848/cell (631) 514-1094 about the neighboring building. He said that he had talked to Mr. Firpo about this neighbor. Mr. Firpo told him that there used to be a pump island inside the building for delivering gasoline. The building used to house an oil delivery company, but now houses a granite supply company. Allegedly, there is a gasoline UST just inside and below the entrance to the neighboring building. I asked Mr. Sternig about MW-1 and boring #5 and why the groundwater results were so different. He said that boring #5 was just a geoprobe punch. He took a quick groundwater sample and then filled the hole. MW-1 was constructed as a permanent monitoring well. Mr. Sternig said that he saw a sheen on the water when he was developing the well. I asked Mr. Sternig whether he was sure about the address of the neighboring building. He said that he was. I asked him who the tenant or owner was. He said that he didn't know. After this, the conversation ended.

METRO GARAGE (Continued) **S108982334**

I checked the 230 Varick Avenue address. It did not appear in the Spills or PBS databases. Google Earth lists the building at 226 Varick Avenue. However, this address also doesn't appear in either database. I will make a site visit in order to determine the correct address and the ownership of the property. 8/5/11 - Raphael Ketani. I made an unannounced visit to the building to the south which abuts Metro Garage on Varick Avenue. The building used to house an oil trucking company called VIJAX. It now houses a tile company called Buy Tile. There was a vent pipe sticking out from the wall near well MW-2. However, the fill pipe had been removed. I met an employee of the tile company and he told me that Anthony Losquadro owns the building. He showed me mail that was in the inside mailbox for Mr. Losquadro. The pieces of mail didn't have a company name, but the address was 222 Varick Avenue, Brooklyn, 11237-1027. Mr. Losquadro's phone is (917) 681-1206. I looked around the insides of the building and didn't see any oil spills. I assumed that if there still were tanks, that they were somewhere below the floor.
========== THE INFORMATION WITHIN THE LINES PERTAINS TO 210 VARICK AVENUE, NOT 222 VARICK AVENUE. I returned to the office and checked the PBS database. I found PBS case #2-080454. The facility is VIJAX Corp. at 210 Varick Avenue. A 275 gal. UST with #2 oil was closed in place on 9/1/02. A 4000 gal. UST with gasoline was closed in place on 10/1/81. Mr. Losquadro was listed as the operator contact. The E-docs for this PBS case contain a file which has passing tank tests for both USTs. The tests were of the Horner EZY 3 type and took place on 11/4/97. A check of Property Shark revealed that 210 Varick Avenue is a corner building, NOT a building next to Metro Garage.
========== I checked the Spills database, but did not find any spill cases for VIJAX, nor for the addresses 210 or 222 Varick Avenue. The NYC MAP DoITT database includes 222 to 226 Varick Avenue as the same building. The Property Shark database lists 222 Varick Avenue as block and lot 2945 and 10. Mr. Losquadro is the latest owner. 8/8/11 - Raphael Ketani. I contacted Sandy Sternig (631) 472-4848/cell (631) 514-1094. I explained that the DEC had reviewed the 7/20/11 VTEQE report. I added that, according to the soil and groundwater results, the DEC has determined that the abandoned diesel UST in the southwest corner of Metro Garage may have leaked in the past. I asked Mr. Sternig to install borings around this tank. He said that the clearance is the real problem. He has 4 foot rods. He's not sure he will have enough clearance under the roof of the bay. I told him to find the equipment that will do the job and to install the borings around the tank and to the bottom of the tank grave. He said that he will contact Mr. Firpo regarding the request for additional work. 8/11/11 - Raphael Ketani. Yesterday, Mr. Sternig sent me the e-mail shown below: I spoke with Mr. Firpo regarding our conversation on Monday. Mr. Firpo believes that the diesel UST tank was tested prior to concrete slurry abandonment. He has reached out to the contractor for that documentation. If end point samples and satisfactory tank test data are not produced then we will attempt borings within the building. Mr. Firpo also explains that this UST was installed about 2 years prior to the abandonment. He has no objections on providing the recent delineation reports to the owner of 230 Varick St. 8/16/11 - Raphael Ketani. Mr. Sternig sent me the following e-mail: Speaking with Dennis Firpo, Mr. Firpo explained

METRO GARAGE (Continued) **S108982334**

that the present dispenser pump resides above the abandoned UST under the rear garage bay is the original pump. Said dispenser pump originally was connected to the now abandoned diesel UST under the rear garage bay. This diesel dispenser pump is presently connected to the newly installed diesel UST on the north side of the subject property via double walled piping. The original connection to the UST used less than five (5) feet of connecting piping. This area was excavated during re-piping yielding the present connection. The 550 UST heating oil tank also in this area was installed in 2006 during the station redevelopment. Mr. Firpo also explained that the Fire Department was present during the abandonment and would have seen the excavated piping. 9/12/11 - Raphael Ketani. I tried to contact Mr. Sternig (631) 472-4848/cell (631) 514-1094 regarding whether soil borings were performed next to the abandoned diesel UST. 9/13/11 - Raphael Ketani. Mr. Sternig returned my call and left a phone message. He said that Mr. Firpo is still waiting for the tank testing contractor to send him the paperwork for the testing before letting any soil work take place. Mr. Sternig said in the message that he had told Mr. Firpo that the State is loosing patients with him and wants the soil investigation around the tank to move forward. Mr. Sternig finished the message by stating that this is where things stand today. 9/14/11 - Raphael Ketani. I put together a letter to Mr. Firpo explaining that he was in violation of the STIP and that he had until September 30 to submit a work plan for performing borings in the vicinity of the abandoned diesel UST, or else he would face legal action. 9/20/11 - Raphael Ketani. I received the green return card for the 9/14/11 letter, but it did not have a date on it, nor a signature. 9/21/11 - Raphael Ketani. Mr. Sternig sent me an e-mail with the documentation regarding the abandoned UST. He wrote that the documentation was not sufficient for DEC's purposes (it was just a one page tank cleaning, removal, abandonment affidavit from 2008). Mr. Firpo authorized VTEQE to perform soil borings around the UST. The borings will take place this friday. 9/27/11 - Raphael Ketani. Mr. Sternig (631) 472-4848/cell (631) 514-1094 sent me an e-mail. In the e-mail, he stated that two sets of soil and groundwater samples were taken next to the abandoned diesel UST on its south side. Groundwater was at 7.5 feet below grade. Both soil samples had odors of old gasoline and OVA hits up to 110ppm. Data will be submitted to the DEC in about 2 weeks. 10/18/11 - Raphael Ketani. I spoke to Mr. Sternig regarding receipt of the data. He said that the samples were processed and that he has the results. However, he is waiting to be paid for the work before sending the report to the DEC. He expects to submit the report sometime during October 2011. Mr. Sternig added as a sidenote that during the installation of the borings, a water line was severed. This line had not been indicated on the markout. 1/10/12 - Raphael Ketani. I received the VTEQE 1/6/12 Bay Soil and Groundwater Delineation Report. I began my review. 1/18/12 - Raphael Ketani. I finished my review. Two locations were bored on 9/20/11. At each location at soil sample (7.5') and a groundwater sample (10'-12') were taken. The soil VOCs were well below standards and so were the SVOCs. Most of the SVOCs were non-detect. There were several oil analytes present, but their concentrations were well below standards. The groundwater samples were mostly non-detect for VOCs and SVOCs. The analytes that were found were very low. As the information in the case file indicates that there is minimal soil and groundwater contamination from on site facilities, I have determined that there is no threat to the public or the environment. Therefore,

METRO GARAGE (Continued) **S108982334**

Remarks: I closed the spill case. I sent Mr. Sternig a spill closure letter." "spill at gas station taking out tanks discovered spill req dec to call him "

All Materials:

Site ID:	99222
Operable Unit ID:	869660
Operable Unit:	01
Material ID:	507282
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E61 **NYCDEP - GENERAL STOREHOUSE #1** **RCRA-VSQG** **1006810515**
NNW **1201 METROPOLITAN AVE** **FINDS** **NYR000113217**
< 1/8 **BROOKLYN, NY 11237** **ECHO**
0.073 mi. **NY MANIFEST**
384 ft. **Site 4 of 5 in cluster E**

Relative: **Lower**
Actual: **10 ft.**

RCRA-VSQG:

Date Form Received by Agency:	20131226
Handler Name:	NYCDEP - GENERAL STOREHOUSE #1
Handler Address:	1201 METROPOLITAN AVE
Handler City,State,Zip:	BROOKLYN, NY 11237
EPA ID:	NYR000113217
Contact Name:	SHAY MCATAMNEY
Contact Address:	JUNCTION BLVD
Contact City,State,Zip:	FLUSHING, NY 11373
Contact Telephone:	718-595-4618
Contact Fax:	Not reported
Contact Email:	SMCATAMNEY@DEP.NYC.GOV
Contact Title:	ENVIRONMENTAL COMPLIANCE MANAGER
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	JUNCTION BLVD
Mailing City,State,Zip:	FLUSHING, NY 11373
Owner Name:	NYC DEPT OF ENVIRONMENTAL PROTECTION
Owner Type:	Municipal
Operator Name:	NYC DEPT OF ENVIRONMENTAL PROTECTION
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No

NYCDEP - GENERAL STOREHOUSE #1 (Continued) **1006810515**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140108
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001

NYCDEP - GENERAL STOREHOUSE #1 (Continued) **1006810515**

Waste Description: IGNITABLE WASTE

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D008
Waste Description: LEAD

Waste Code: D009
Waste Description: MERCURY

Waste Code: D018
Waste Description: BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYCDEP - GENERAL STOREHOUSE #1
Legal Status:	Municipal
Date Became Current:	20030204
Date Ended Current:	Not reported
Owner/Operator Address:	1201 METROPOLITAN AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11237
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYC DEPT OF ENVIRONMENTAL PROTECTION
Legal Status:	Municipal
Date Became Current:	19960529
Date Ended Current:	Not reported
Owner/Operator Address:	59-17 JUNCTION BLVD
Owner/Operator City,State,Zip:	FLUSHING, NY 11373
Owner/Operator Telephone:	212-639-9675
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYCDEP-BWSO
Legal Status:	Municipal
Date Became Current:	20030204
Date Ended Current:	Not reported
Owner/Operator Address:	59-17 JUNCTION BLVD
Owner/Operator City,State,Zip:	FLUSHING, NY 11373-5108
Owner/Operator Telephone:	718-366-3322
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYC DEPT OF ENVIRONMENTAL PROTECTION
Legal Status:	Municipal
Date Became Current:	19960529
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported

NYCDEP - GENERAL STOREHOUSE #1 (Continued) **1006810515**

Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: GENERAL STOREHOUSE #1
Legal Status: Municipal
Date Became Current: 20030204
Date Ended Current: Not reported
Owner/Operator Address: 1201 METROPOLITAN AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: 718-595-5272
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYCDEP-BWSO
Legal Status: Municipal
Date Became Current: 20030204
Date Ended Current: Not reported
Owner/Operator Address: 59-17 JUNCTION BLVD
Owner/Operator City,State,Zip: FLUSHING, NY 11373-5108
Owner/Operator Telephone: 718-595-5330
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYCDEP-BWSO
Legal Status: Municipal
Date Became Current: 20030204
Date Ended Current: Not reported
Owner/Operator Address: 59-17 JUNCTION BLVD
Owner/Operator City,State,Zip: FLUSHING, NY 11373-5108
Owner/Operator Telephone: 718-595-5330
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYCDEP - GENERAL STOREHOUSE #1
Legal Status: Municipal
Date Became Current: 20030204
Date Ended Current: Not reported
Owner/Operator Address: 1201 METROPOLITAN AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYCDEP - GENERAL STOREHOUSE #1

NYCDEP - GENERAL STOREHOUSE #1 (Continued) **1006810515**

Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCDEP - GENERAL STOREHOUSE #1
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20030204
Handler Name: GENERAL STOREHOUSE #1
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040831
Handler Name: NYCDEP - GENERAL STOREHOUSE #1
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20131226
Handler Name: NYCDEP - GENERAL STOREHOUSE #1
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

NYCDEP - GENERAL STOREHOUSE #1 (Continued) **1006810515**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 22131
NAICS Description: WATER SUPPLY AND IRRIGATION SYSTEMS

NAICS Code: 49311
NAICS Description: GENERAL WAREHOUSING AND STORAGE

NAICS Code: 53112
NAICS Description: LESSORS OF NONRESIDENTIAL BUILDINGS (EXCEPT MINIWAREHOUSES)

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110014359096

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1006810515
Registry ID: 110014359096
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110014359096
Name: NYCDEP - GENERAL STOREHOUSE #1
Address: 1201 METROPOLITAN AVE
City,State,Zip: BROOKLYN, NY 11237

NY MANIFEST:
Name: NYCDEP
Address: 1201 METROPOLITAN AVE
City,State,Zip: BROOKLYN, NY 11237
Country: USA
EPA ID: NYR000113217
Facility Status: Not reported
Location Address 1: 1201 METROPOLITAN AVE
Code: BP

NYCDEP - GENERAL STOREHOUSE #1 (Continued) **1006810515**

Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000113217
Mailing Name:	NYCDEP
Mailing Contact:	W YULINSKY
Mailing Address 1:	59-17 JUNCTION BLVD 3RD FL
Mailing Address 2:	Not reported
Mailing City:	FLUSHING
Mailing State:	NY
Mailing Zip:	11373
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7185955272

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/04/2009
Trans1 Recv Date:	09/04/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/04/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000113217
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001085997GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100

NYCDEP - GENERAL STOREHOUSE #1 (Continued) **1006810515**

Units:	L
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

E62 **NYC DEP** **NJ MANIFEST** **S109533845**
NNW **1201 METROPOLITAN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.073 mi.
384 ft. **Site 5 of 5 in cluster E**

Relative: **Lower**

Actual: **10 ft.**

NJ MANIFEST:

EPA Id:	NYR000113217
Mail Address:	59-17 JUNCTION BLVD
Mail City/State/Zip:	FLUSHING 11373
Facility Phone:	7185955272
Emergency Phone:	Not reported
Contact:	JOHN ZOLLO
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001085997GBF
EPA ID:	NYR000113217
Date Shipped:	09/04/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/04/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

NYC DEP (Continued) **S109533845**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/04/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FLUSHING 11373
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	100 P

Manifest Number:	003531975JJK
EPA ID:	NYR000113217
Date Shipped:	08/01/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/01/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/01/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

NYC DEP (Continued) **S109533845**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FLUSHING 11373
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	136 G

Manifest Number:	001057023GBF
EPA ID:	NYR000113217
Date Shipped:	01/11/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/11/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/11/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	FLUSHING 11373
Reason Load Was Rejected:	Not reported

NYC DEP (Continued) **S109533845**

Waste:
Manifest Year: Not reported
Waste Code: D001
Hand Code: H141
Quantity: 20 G

H63 **NYC DEPT OF SANITATION** **RCRA-VSQG** **1006810235**
SSW **VARICK AVE** **NYR000109116**
< 1/8 **BROOKLYN, NY 11237**
0.077 mi.
405 ft. **Site 3 of 6 in cluster H**

Relative: **Lower**
Actual: **12 ft.**

RCRA-VSQG:

Date Form Received by Agency:		20070101
Handler Name:	NYC DEPT OF SANITATION	
Handler Address:		VARICK AVE
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYR000109116
Contact Name:		JOHN S PAWLOWSKI
Contact Address:		BEAVER ST
Contact City,State,Zip:		NEW YORK, NY 10004
Contact Telephone:		917-237-5985
Contact Fax:		Not reported
Contact Email:		UPAWLOWSKI@PACE.EDU
Contact Title:		Not reported
EPA Region:		02
Land Type:		Municipal
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		BEAVER ST
Mailing City,State,Zip:		NEW YORK, NY 10004
Owner Name:		NEW YORK CITY DEPARTMENT OF SANITATION
Owner Type:		Municipal
Operator Name:		CITY OF NY DEPARTMENT OF SANITATION
Operator Type:		Municipal
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported

NYC DEPT OF SANITATION (Continued) **1006810235**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2003

Click Here for Biennial Reporting System Data:

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CITY OF NEW YORK OF SANITATION
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	161 VARICK AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11237
Owner/Operator Telephone:	347-881-9722

NYC DEPT OF SANITATION (Continued) **1006810235**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF NY DEPARTMENT OF SANITATION
Legal Status: Municipal
Date Became Current: 19801231
Date Ended Current: Not reported
Owner/Operator Address: BEAVER ST
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NEW YORK CITY DEPARTMENT OF SANITATION
Legal Status: Municipal
Date Became Current: 19801231
Date Ended Current: Not reported
Owner/Operator Address: BEAVER ST
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NEW YORK CITY DEPARTMENT OF SANITATION
Legal Status: Municipal
Date Became Current: 19801231
Date Ended Current: Not reported
Owner/Operator Address: BEAVER ST
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF NY DEPARTMENT OF SANITATION
Legal Status: Municipal
Date Became Current: 19801231
Date Ended Current: Not reported
Owner/Operator Address: BEAVER ST
Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYC DEPT OF SANITATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported

NYC DEPT OF SANITATION (Continued) **1006810235**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: NYC DEPT OF SANITATION	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20020912
Handler Name: NYC DEPT OF SANITATION	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20040618
Handler Name: NYC DEPT OF SANITATION	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	92411
NAICS Description:	ADMINISTRATION OF AIR AND WATER RESOURCE AND SOLID WASTE MANAGEMENT PROGRAMS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

NYC DEPT OF SANITATION (Continued) **1006810235**

Evaluation Action Summary:
Evaluations: No Evaluations Found

H64 **NYC DEPART OF SANITATION (VARICK ST)** **NY LTANKS** **S106003231**
SSW **VARICK AVE** **NY Spills** **N/A**
< 1/8 **BROOKLYN, NY 11237** **NY MANIFEST**
0.077 mi.
405 ft. **Site 4 of 6 in cluster H**

Relative: **Lower**
Actual: **12 ft.**

LTANKS:

Name:	DEPT OF SANITATION SITE
Address:	161 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0305740 / 2003-10-16
Facility ID:	0305740
Site ID:	158270
Spill Date:	2003-08-29
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	2003-08-29
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-08-29
Spill Record Last Update:	2003-10-16
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	138348
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 10/16/03 1030 Hrs - Sawyer - I talked to Roland Fisher of Tyree Environmental about the soil contamination in the area of the two 550 gallon tanks that they have already removed. Monday 10/20 they are going to remove contaminated soil and try to get clean endpoint samples from the four sides. There is a previous spill open at this address please reference #0201226. Closed. "
Remarks:	"CALLER DUG UP OLD TANKS THAT LEAKED."

All Materials:

Site ID:	158270
Operable Unit ID:	874196
Operable Unit:	01

NYC DEPART OF SANITATION (VARICK ST) (Continued) **S106003231**

Material ID:	502981
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	161 / 165 VARICK AVE
Address:	161 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0201226 / 2006-03-29
Facility ID:	0201226
Facility Type:	ER
DER Facility ID:	138348
Site ID:	164054
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	2002-05-02
Investigator:	DJEATON
Referred To:	Not reported
Reported to Dept:	2002-05-02
CID:	205
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-05-02
Spill Record Last Update:	2006-03-29
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER Spill Nos. 0305740 and 0204630 have been consolidated under this Spill No. 8/20/02: FUTURE DEPT OF SANITATION DISTRICT 1 AND 4 GARAGE. HIGH LEVELS OF PCB'S. HWR MEETING WITH LIRO ON 8/20/02. SMM. 10/16/03 1030 Hrs - Sawyer - I discussed with Roland Fisher of Tyree Environmental the contaminated soil in the area of the removal of the two 550 gallon tanks. He told me about the excavation planned for 10/20. I informed him that this site had tested high for PCB's in the past. This factor must also be addressed. 10/20/03 1030 Hrs - Sawyer - Met with Roland Fisher and Barry Aronowitz of Arnell Construction Corp. at the site. They had a back hoe dig out approximatly 35 cubic yds with no endpoints in site. Overall contractor stopped excavation

NYC DEPART OF SANITATION (VARICK ST) (Continued) **S106003231**

with plans to meet and discuss another path of remediation. 02/15/06 File reviewed, DOS has submitted various reports. D. Wolterding had previous contact with the DOS, recommended signing agreement - no legal agreement signed. 03/29/06 Recommended next: Transfer project from spills to Haz Waste Remediation, PCBs an issue here. BURA to forward to BURC/REGION."

Remarks: "caller doing site work found contaminated soil."

All Materials:

Site ID:	164054
Operable Unit ID:	854559
Operable Unit:	01
Material ID:	522645
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SPILL NUMBER 0204630
Address:	161 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0204630 / 2003-02-13
Facility ID:	0204630
Facility Type:	ER
DER Facility ID:	138348
Site ID:	164055
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	2002-08-01
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2002-08-01
CID:	257
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-01
Spill Record Last Update:	2003-02-13
Spiller Name:	CURTIS CASEY
Spiller Company:	Not reported
Spiller Address:	161 VARICK AVE
Spiller Company:	001
Contact Name:	CURTIS CASEY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 2/13/2003 - Closed Due To The Nature / Extent Of The Spill

NYC DEPART OF SANITATION (VARICK ST) (Continued) **S106003231**

	Report"
Remarks:	"during some diging on site they came across this tank which appears to have been filled with water and some did spill"

All Materials:

Site ID:	164055
Operable Unit ID:	855776
Operable Unit:	01
Material ID:	518871
Material Code:	0060A
Material Name:	wastewater
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	NYC DEPART OF SANITATION (VARICK ST)
Address:	VARICK AVE
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYR000109116
Facility Status:	Not reported
Location Address 1:	161 VARICK AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000109116
Mailing Name:	NYC DEPART OF SANITATION (VARICK ST)
Mailing Contact:	CURTIS CASEY
Mailing Address 1:	161 VARICK AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9175782357

H65 **DSNY BK DISTRICT 1/4 GARAGE** **NY UST** **U004122263**
SSW **161 VARICK AVENUE** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.077 mi.
405 ft. **Site 5 of 6 in cluster H**

Relative: **Lower**

Actual: **12 ft.**

UST:

Name:	DSNY BK DISTRICT 1/4 GARAGE
Address:	161 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Id/Status:	2-610872 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	10/19/2022
UTM X:	590493.26574
UTM Y:	4507230.73845
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	400593
Affiliation Type:	Facility Owner
Company Name:	NYC DEPARTMENT OF SANITATION
Contact Type:	ASSISTANT CHIEF
Contact Name:	JOSEPH CENDAGORTA
Address1:	125 WORTH STREET, ROOM 823B
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10013
Country Code:	001
Phone:	(646) 885-4856
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-04-14

Site Id:	400593
Affiliation Type:	Facility Operator
Company Name:	DSNY BK DISTRICT 1/4 GARAGE
Contact Type:	Not reported
Contact Name:	DAVID KUPERSZMID
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 571-6413
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-11-16

Site Id:	400593
Affiliation Type:	Mail Contact
Company Name:	NYC DEPARTMENT OF SANITATION
Contact Type:	Not reported
Contact Name:	FRANK SCARPACI
Address1:	125 WORTH STREET

DSNY BK DISTRICT 1/4 GARAGE (Continued) **U004122263**

Address2:	ROOM 823 B
City:	NEW YORK
State:	NY
Zip Code:	10013
Country Code:	001
Phone:	(646) 885-4887
EMail:	FSCARPACI@DSNY.NYC.GOV
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-11-16

Site Id:	400593
Affiliation Type:	Emergency Contact
Company Name:	NYC DEPARTMENT OF SANITATION
Contact Type:	Not reported
Contact Name:	BUREAU OF CLEANING & COLLECTION
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 885-5051
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXAJOKU
Date Last Modified:	2015-11-18

Tank Info:

Tank Number:	001
Tank ID:	223930
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	10/19/2007
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2710
Common Name of Substance:	Biodiesel

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	DMPOKRZY
Last Modified:	01/03/2018

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B04 - Tank External Protection - Fiberglass

DSNY BK DISTRICT 1/4 GARAGE (Continued) **U004122263**

E04 - Piping Secondary Containment - Double walled UG
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
I03 - Overfill - Automatic Shut-Off
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None

Tank Number: 002
Tank ID: 223929
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 10/19/2007
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DMPOKRZY
Last Modified: 01/03/2018

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None

Tank Number: 003
Tank ID: 229956
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 2500
Install Date: 10/19/2007
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0010

DSNY BK DISTRICT 1/4 GARAGE (Continued) **U004122263**

Common Name of Substance: Hydraulic Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DMPOKRZY
Last Modified: 01/03/2018

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double walled UG
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
J02 - Dispenser - Suction Dispenser
F04 - Pipe External Protection - Fiberglass
C03 - Pipe Location - Aboveground/Underground Combination
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

Tank Number: 004
Tank ID: 223928
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 2500
Install Date: 10/19/2007
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0015
Common Name of Substance: Motor Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DMPOKRZY
Last Modified: 01/03/2018

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double walled UG
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C03 - Pipe Location - Aboveground/Underground Combination
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

DSNY BK DISTRICT 1/4 GARAGE (Continued) **U004122263**

I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 005
Tank ID: 223927
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 550
Install Date: 10/19/2007
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DMPOKRZY
Last Modified: 01/03/2018

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
J00 - Dispenser - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double walled UG
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 006
Tank ID: 223934
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 10/19/2007
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2710
Common Name of Substance: Biodiesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DMPOKRZY

DSNY BK DISTRICT 1/4 GARAGE (Continued) **U004122263**

Last Modified: 01/03/2018

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

Tank Number: 007
Tank ID: 223933
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 10/19/2007
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DMPOKRZY
Last Modified: 01/03/2018

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E04 - Piping Secondary Containment - Double walled UG
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None

Tank Number: 008
Tank ID: 229957

DSNY BK DISTRICT 1/4 GARAGE (Continued) **U004122263**

Tank Status: In Service
Material Name: In Service
Capacity Gallons: 2500
Install Date: 10/19/2007
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0010
Common Name of Substance: Hydraulic Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DMPOKRZY
Last Modified: 01/03/2018

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double walled UG
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 009
Tank ID: 223932
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 2500
Install Date: 10/19/2007
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0015
Common Name of Substance: Motor Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: D
Modified By: DMPOKRZY
Last Modified: 01/03/2018

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
I02 - Overfill - High Level Alarm

DSNY BK DISTRICT 1/4 GARAGE (Continued) **U004122263**

B04 - Tank External Protection - Fiberglass
L09 - Piping Leak Detection - Exempt Suction Piping
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
C03 - Pipe Location - Aboveground/Underground Combination
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I03 - Overfill - Automatic Shut-Off

Tank Number:	010
Tank ID:	223931
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	550
Install Date:	10/19/2007
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	D
Modified By:	DMPOKRZY
Last Modified:	01/03/2018

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
J00 - Dispenser - None
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
E04 - Piping Secondary Containment - Double walled UG
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

I66 **GRAND STREET BRIDGE** **NY Spills** **S102149278**
WNW **METROPOLITAN AVE** **N/A**
< 1/8 **QUEENS, NY**
0.078 mi.
412 ft. **Site 1 of 12 in cluster I**

Relative: SPILLS:
Lower

Name:	METROPOLITAN AVE
Address:	METROPOLITAN AVE
City,State,Zip:	QUEENS, NY

Actual:
4 ft.

GRAND STREET BRIDGE (Continued) **S102149278**

Spill Number/Closed Date:	9610924 / 1998-04-28
Facility ID:	9610924
Facility Type:	ER
DER Facility ID:	81499
Site ID:	89187
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	4101
Spill Date:	1996-12-04
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1996-12-04
CID:	351
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-04
Spill Record Last Update:	1998-04-28
Spiller Name:	JOHN GARCIA
Spiller Company:	METRO FUEL
Spiller Address:	500 KINGSLAND AV
Spiller Company:	001
Contact Name:	JOHN GARCIA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE CLEANED BY RP. "
Remarks:	"BROKEN PIPE ON TRUCK CAUSED SPILL "

All Materials:

Site ID:	89187
Operable Unit ID:	1042315
Operable Unit:	01
Material ID:	558313
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	30.00
Oxygenate:	Not reported

Name:	GRAND STREET BRIDGE
Address:	METROPOLITAN AVE
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9708562 / 1997-10-22
Facility ID:	9708562
Facility Type:	ER
DER Facility ID:	81499
Site ID:	89188
DEC Region:	2

GRAND STREET BRIDGE (Continued) **S102149278**

Spill Cause:	Human Error
Spill Class:	E5
SWIS:	4101
Spill Date:	1997-10-22
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1997-10-22
CID:	311
Water Affected:	GOWANUS CANAL
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-22
Spill Record Last Update:	1997-10-24
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE mmmmm FAX TO DEP. UNFOUNDED - MARK WAS THERE."
Remarks:	"caller states that workers on the bridge are cleaning same and run off is going into the canal. "

All Materials:

Site ID:	89188
Operable Unit ID:	1051721
Operable Unit:	01
Material ID:	330526
Material Code:	0045A
Material Name:	cleaning chemicals/products
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F67 **SUNSHINE BISCUITS INC** **NY LTANKS** **1000788133**
NE **1251 METROPOLITAN AVE** **NY UST** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.079 mi.
419 ft. **Site 4 of 9 in cluster F**

Relative: LTANKS:
Lower

Name:	1251 METROPOLITAN AVE. /
Address:	1251 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8607890 / 1987-03-25
Facility ID:	8607890
Site ID:	110767
Spill Date:	1987-03-24

Actual:
12 ft.

SUNSHINE BISCUITS INC (Continued) **1000788133**

Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1987-03-25
SWIS:	2401
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-03-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-04-02
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	SUNSHINE BISQUIT
Spiller Address:	1251 METROPOLITAN AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	96975
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was "
Remarks:	"2000 GALLONS (NO-LEAD) GASOLINE UNDERGROUND TANK SYSTEM FAILED PETRO TITE @ -.107 G/HR. POSSIBLE CAUSE EXTERNAL TEMPERATURE.CONTRACTOR ADVIS"

All TTF:

Facility ID:	8607890
Spill Number:	8607890
Spill Tank Test:	1530658
Site ID:	110767
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	110767
Operable Unit ID:	905528
Operable Unit:	01
Material ID:	473380
Material Code:	0009

SUNSHINE BISCUITS INC (Continued) **1000788133**

Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

UST:
Name: SUNSHINE BISCUITS INC
Address: 1251 METROPOLITAN AVE
City,State,Zip: BROOKLYN, NY 11237
Id/Status: 2-245070 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 590657.22867
UTM Y: 4507553.62098
Site Type: Unknown

Affiliation Records:
Site Id: 9517
Affiliation Type: Facility Owner
Company Name: SUNSHINE BISCUITS INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 100 WOODBRIDGE CENTER DR
Address2: Not reported
City: WOODBRIDGE
State: NJ
Zip Code: 07095
Country Code: 001
Phone: (201) 855-4000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 9517
Affiliation Type: Mail Contact
Company Name: SUNSHINE BISCUITS INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 100 WOODBRIDGE CENTER DR
Address2: Not reported
City: WOODBRIDGE
State: NJ
Zip Code: 07095
Country Code: 001
Phone: (201) 855-4000
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

SUNSHINE BISCUITS INC (Continued) **1000788133**

Site Id:	9517
Affiliation Type:	Facility Operator
Company Name:	SUNSHINE BISCUITS INC
Contact Type:	Not reported
Contact Name:	SUNSHINE BISCUITS INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 456-1220
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9517
Affiliation Type:	Emergency Contact
Company Name:	SUNSHINE BISCUITS INC
Contact Type:	Not reported
Contact Name:	JACQUES MICHEL EYMA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 723-4098
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	40471
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	4000
Install Date:	12/01/1979
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

SUNSHINE BISCUITS INC (Continued) **1000788133**

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Number:	002
Tank ID:	40472
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	2000
Install Date:	12/01/1979
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)

I68 **MANHOLE #15350** **NY Spills** **S104194307**
NW **VARICK AVE & METROPOLITAN** **N/A**
< 1/8 **BROOKLYN, NY**
0.082 mi.
433 ft. **Site 2 of 12 in cluster I**

Relative: **Lower**
Actual: **8 ft.**

SPILLS:

Name:	MANHOLE #15350
Address:	VARICK AVE & METROPOLITAN
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9906203 / 1999-11-10
Facility ID:	9906203
Facility Type:	ER
DER Facility ID:	61901
Site ID:	64194
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4

MANHOLE #15350 (Continued) **S104194307**

SWIS:	2401
Spill Date:	1999-08-24
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1999-08-24
CID:	252
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-08-24
Spill Record Last Update:	2000-06-01
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	MARK SCHLAGEL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con ed e2mis notes: 3 quarts of unknown oil on 1200 gallons of water in MH15350. Took 1 sample. lsn #99-08879 <1ppm. <1.0 ppm clean up complete and tag removed. Incident is closed. "
Remarks:	"NO WATER WAYS OR SEWERS AFFECTED-SAMPLE TAKEN-CLEAN UP PENDING RESULTS-CON ED #127390"

All Materials:

Site ID:	64194
Operable Unit ID:	1084645
Operable Unit:	01
Material ID:	302471
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I69 **ROADWAY** **NY Spills** **S109414366**
NW **METROPOLITAN AVE & VARICK AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.082 mi.
433 ft. **Site 3 of 12 in cluster I**

Relative: **Lower**
Actual: **8 ft.**

SPILLS:

Name:	ROADWAY
Address:	METROPOLITAN AVE & VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0811297 / 2009-01-14
Facility ID:	0811297
Facility Type:	ER
DER Facility ID:	358126

ROADWAY (Continued) **S109414366**

Site ID:	408867
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D5
SWIS:	2401
Spill Date:	2009-01-13
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2009-01-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-01-13
Spill Record Last Update:	2009-01-14
Spiller Name:	ECO NICHOLS
Spiller Company:	SUNOCO GAS
Spiller Address:	METROPOLITAN AVE & VARICK AVE
Spiller Company:	999
Contact Name:	ECO NICHOLS
DEC Memo:	"Sangesland spoke to ECO Nichols. He says a gas station was doing tank work and during his site inspection he saw 1 gal of antifreeze on the pavement."
Remarks:	"Caller states a truck was leaking fluid onto the blacktop. Caller was also concerned about the vehicle selling fuel from the roadside. Speedy dry was put down by employees, some product did go into a storm drain."

All Materials:

Site ID:	408867
Operable Unit ID:	1165377
Operable Unit:	01
Material ID:	2156784
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

70
East
< 1/8
0.085 mi.
449 ft.

CON EDISON - MANHOLE 57887
169 GARDNER AVE
BROOKLYN, NY 11237

NY MANIFEST **S120958060**
N/A

Relative:
Higher

Actual:
14 ft.

NY MANIFEST:

Name:	CON EDISON - MANHOLE 57887
Address:	169 GARDNER AVE
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP004907632
Facility Status:	Not reported
Location Address 1:	169 GARDNER AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004907632
Mailing Name:	CON EDISON - MANHOLE 57887
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

F71
NE
< 1/8
0.086 mi.
455 ft.

Site 5 of 9 in cluster F

SUNSHINE BISCUITS
1251 METROPOLITAN AVE
MASPETH, NY 11378

RCRA NonGen / NLR **1000381578**
FINDS **NYD078159936**
ECHO
NY MANIFEST

Relative:
Lower

Actual:
12 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	SUNSHINE BISCUITS	
Handler Address:		1251 METROPOLITAN AVE
Handler City,State,Zip:		MASPETH, NY 11378
EPA ID:		NYD078159936
Contact Name:		Not reported
Contact Address:		METROPOLITAN AVE
Contact City,State,Zip:		MASPETH, NY 11378
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported

SUNSHINE BISCUITS (Continued) **1000381578**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	METROPOLITAN AVE
Mailing City,State,Zip:	MASPETH, NY 11378
Owner Name:	SUNSHINE BISCUITS
Owner Type:	Private
Operator Name:	SUNSHINE BISCUITS
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

SUNSHINE BISCUITS (Continued) **1000381578**

Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SUNSHINE BISCUITS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SUNSHINE BISCUITS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	SUNSHINE BISCUITS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: SUNSHINE BISCUITS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY

SUNSHINE BISCUITS (Continued) **1000381578**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: SUNSHINE BISCUITS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: SUNSHINE BISCUITS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19890530
Handler Name: SUNSHINE BISCUITS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

SUNSHINE BISCUITS (Continued) **1000381578**

FINDS:
Registry ID: 110001572236

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000381578
Registry ID:	110001572236
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110001572236
Name:	SUNSHINE BISCUITS
Address:	1251 METROPOLITAN AVE
City,State,Zip:	MASPETH, NY 11378

NY MANIFEST:

Name:	SUNSHINE BISCUITS
Address:	1251 METROPOLITAN AVE
City,State,Zip:	MASPETH, NY 11378
Country:	USA
EPA ID:	NYD078159936
Facility Status:	Not reported
Location Address 1:	1251 METROPOLITAN AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MASPETH
Location State:	NY
Location Zip:	11378
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD078159936
Mailing Name:	SUNSHINE BISCUITS
Mailing Contact:	SUNSHINE BISCUITS
Mailing Address 1:	1251 METROPOLITAN AVE
Mailing Address 2:	Not reported
Mailing City:	FLUSHING
Mailing State:	NY
Mailing Zip:	11378
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183490890

J72 **46-25 METROPOLITAN AVE** **NY Spills** **S102671916**
NW **46025 METROPOLITAN AVE** **N/A**
< 1/8 **RIDGEWOOD, NY**
0.087 mi.
461 ft. **Site 1 of 5 in cluster J**

Relative: **Lower**

Actual: **9 ft.**

SPILLS:

Name:	46-25 METROPOLITAN AVE
Address:	46025 METROPOLITAN AVE
City,State,Zip:	RIDGEWOOD, NY
Spill Number/Closed Date:	9204008 / 2013-10-28
Facility ID:	9204008
Facility Type:	ER
DER Facility ID:	78016
Site ID:	84865
DEC Region:	2
Spill Cause:	Other
Spill Class:	A3
SWIS:	4101
Spill Date:	1992-07-07
Investigator:	AAOBLIGA
Referred To:	Not reported
Reported to Dept:	1992-07-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-07-08
Spill Record Last Update:	2013-10-29
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 4/12/04-Vought-Spill transferred from Tibbe to Rommel as per Rommel 12/29/05 Transferred to E. Hampston via Spill Initative. Called listed owner via PBS information (J. Brown 718-243-4581) no pickup, no voice mail. Will forward letter requesting information. 11/02/06 Reassigned to Sun.(JS/MS) 2/13/07: Original contact number on PBS is for former location (on Jay Street) of MTA facility. Contact made with representative at 646.252.5777. Rachel Kron who is in charge of MTA spills will get back to me (MS) upon obtaining associated documents. (JS/MS) 5/15/07: As per R. Kron, MTA meets with DEC monthly and this site will be brought up at next meeting. She will contact me with update after meeting. See M.Tibbe. (JS/MS) 8/2/07: DEC still has not heard from MTA. Will contact Mrs. Kron again and issue a letter if necessary. (JS/MS) 12/3/07: Site should be brought up at next MTE/DEC meeting. (JS/MS) 04-04-08: Transferred to Tibbe. 11/12/10 - spill re-assigned from Tibbe to Joe O'Connell 11/28/11 - Obligado - Spill re-assigned from O'Connell to Obligado 10/30/13 - I reviewed the file. File contains a Phase I and II report prepared for MTA. The Phase I report mentions the spill. Apparently,

46-25 METROPOLITAN AVE (Continued) **S102671916**

the spill was called in as a result of contaminated soil found during excavation of the 550 USTs. There were historically 18 550 USTs at the site encased in concrete. The Phase 1 report referrences a UST Removal Management Report prepared by Kemron Enviornmental Services, dated September 1992. The actual report is not included in the Phase 1. According to the Phase 1 description of the report, soil contamination was discovered in the vicinity of the former UST area. The tanks were enclosed in a concrete vault. The tanks and soil were excavated and analysis of final pit samples indicated no soil contamination. The contamination was reportedly removed in its entirety. During the Phase II assessment, 3 soil borings and 1 monitoring well was installed in the vicinity of this former 550 gallon UST area. While petroleum staining and odors were noted in 3 of the 4 soil borings, analytical results were below SCOs for VOCs. SVOCs were predominantly below SCOs with the exception of some minor exceedence of PAHs which were attributed to historic fill. The GW sample from B/MW5 within the former tank footprint was ND for both VOCs and SVOCS. Based on the documents in the file, it appears that this spill has been remediated in 1992 when the tanks were pulled. The 2000 Phase II investigation confirmed that there were limited impacts to the environment. According to the file, the site was purchased by MTA and has already been redeveloped into a new receiving facility. This spill is closed."

Remarks: "CONTAM SOIL DISCOVERED DURING EXCAVATION. WILL STOCKPILE, TEST, & DISPOSE."

All Materials:

Site ID:	84865
Operable Unit ID:	971401
Operable Unit:	01
Material ID:	411771
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

G73 **COMMERCIAL PROPERTY** **NY Spills** **S107788365**
SW **175 VARICK AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.093 mi.
493 ft. **Site 4 of 5 in cluster G**

Relative: **Lower**
Actual: **6 ft.**

SPILLS:

Name:	COMMERCIAL PROPERTY
Address:	175 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0601947 / 2011-11-18
Facility ID:	0601947
Facility Type:	ER
DER Facility ID:	314541
Site ID:	364315
DEC Region:	2
Spill Cause:	Equipment Failure

COMMERCIAL PROPERTY (Continued) **S107788365**

Spill Class:	C3
SWIS:	2401
Spill Date:	2006-05-23
Investigator:	RVKETANI
Referred To:	FINAL REMEDIAL ACTION REPORT BY 1/31/09
Reported to Dept:	2006-05-23
CID:	409
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-23
Spill Record Last Update:	2011-11-21
Spiller Name:	CHET BIJOOR
Spiller Company:	COMMERCIAL PROPERTY
Spiller Address:	175 VARICK AVE
Spiller Company:	999
Contact Name:	CHET BIJOOR
DEC Memo:	"05/24/06-Vought-Spill transferred from DEC Vought to DEC Tang as per DEC Austin due to necessity of long term remediation. 07/13/06-Vought-Received call from Amit Haryani (Earth Tech 973-337-4218) who is representing Waste Management. NYC looking to buy property from Waste management and as part of due diligence two rounds of site investigation were performed and gasoline contamination was detected in soil and groundwater. Onsite and offsite investigation was performed and source was inconclusive due to occurrence of off site contamination and spill case was filed with DEC. Waste Management hired Earth Tech to perform additional investigation and determine groundwater flow direction. Earth Tech prepared Site Investigation workplan and requesting meeting with DEC to discuss scope of work. Waste Management wishes to be proactively aggressive in pursuing cleanup due to possible NYC purchase. ---------- ---------- 10/16/06 Re-assigned from Yau to Chanda (Chanda) 12/21/06: Kartik Chanda of DEC called Mr.Amit Haryani(Earth Tech) regarding the site update information. He stated that Earth Tech has prepared site investigation work plan and he will send DEC office as soon as possible. 01/12/07: Chanda received Supplemental Site Investigation Work Plan, August, 2006 and Health & Safety Plan, August 2006, prepared by Earth Tech, Inc. 2/6/07: Chanda reviewed the site investigation work plan and approved with the following conditions on 2/6/07: 1.The Department requires an additional monitoring well (MW-7) should be installed at location down- gradient of the existing monitoring well (MW-1). 2. A surrounding property sketch including property layout and usage must be submitted to the Department. North arrow and scale must also be included on the site plan. 2/7/07: Chanda sent a letter to RP(Jay Kaplan) and Amit Haryani(Earth Tech), requiring that a site investigation summary report be submitted to DEC for review by 4/6/2007. 4/10/07: Chanda received a phone call from Amit Haryani(Earth Tech.) regarding to extension time to submit investigation report. He will send Time extension request letter as soon as possible. 4/11/07: Chanda

COMMERCIAL PROPERTY (Continued) **S107788365**

received an extention request letter from Earth Tech, Inc on 4/11/07. 4/12/07: Chanda sent the approval letter to RP(Jay Kaplan) and Amit Haryani (Earth Tech), requiring that a Site Investigation Summary Report be submitted to DEC for review by June 11, 2007. 4/16/07: Chanda received an email from Amit Haryani, Earth Tech, Inc. He proposed to use the Membrane Interface Probe (MIP) to delineate the extent of soil contamination on-site. 4/25/07: Per conversation with Joe Sun and Consultant (Amit)regarding of the Triad Approach method.Joe Sun is satisfied with explanation regarding Membrane Interface Probe (MIP). The Department recommends using the MIP to delineate the extent of soil contamination on- site.(Chanda) 6/18/07: Chanda received an email from Amit Haryani, Earth Tech. He requested that he would like to set a meeting with NYSDEC. He proposed to meet on 7/2/07 to discuss about investigation findings and recommendations. 7/2/07: Amit Haryani, Joseph J. Fiteni(Earth Tech), Jay Kaplan, and Christopher P. Prucha (Wast Management) attened to meet in DEC office with Kartik Chanda,and Joe Sun of DEC to discuss site investigation results and remediation method regarding the GW contamination at the site.The meeting is concluded that a remedial action plan is required to be submitted to the DEC for approval. 9/6/07: Chanda received a Supplemental Site Investigation Report (SSIR) prepared by Earth Tech dated on Auguest 29, 2007. 9/25/07: Chnada reviewed the SSIR report and has the following comment: The groundwater(GW) analytical results showed elevated levels of VOCs. For well MW-2, the levels of BTEX and MTBE are 6,660 ppb and 27 ppb, respectively. In addition benzene and MTBE were detected in the temporary well points (TW-1 and TW-2) and a permanent monitoring well (MW-1). The high VOCs concentrations indicated that the GW had been contaminated and thus, is required to be remediated and monitored. On 9/25/07: Chanda approves the SSIR. A Remedial Action Plan (RAP) be submitted to the NYSDEC by 11/12/07. The RAP shall detail the work proposed to remediate all contaminated media. 10/12/07: Chanda received a RAP from Mr. Jay Kaplan, Environmental Manager, Wast management of New York, LLC dated 10/2/07 prepared by Construction Service International, Inc., dated October 2007. 10/24/07: On 10/23/07, Chanda reviewed and approved the RAP with the following conditions: 1.Soil endpoint samples will be collected in accordance with DER-10 in the area of concern subsequent to the soil excavation near the UST area. 2.The permanent monitoring wells should be developed and sampled to determine baseline groundwater quality conditions prior to implementing the RegenOX"! and ORC Advanced"! injections. 3. Several parameters, including temperature, pH, oxidation-redox potential (ORP), conductivity and dissolved oxygen (DO) shall be monitored in all the monitoring wells. Any potential accumulation of vapors during the injection activities shall be avoided. 4. If follow-up groundwater monitoring indicates that the RegenOX"! and ORC Advanced"! are not effectively reducing contaminant concentrations, an alternative remedial approach must be developed. 10/24/07: Chanda sent an approval letter to RP (Jay Kaplan) and his consultant, requiring that the RP shall implement the RAP incorporating the above conditions according to the schedule indicated in table -2 of the RAP. 3/17/08: Chanda received a letter with RAP implementation schedule and site plan for existing wells, new well location (MW-8), proposed in-situ remediation injection locations for this site. UST Closure and GW remediation project schedule are figure-5. The Remedial Action Report will be submit to DEC by 8/8/08.(see eDocs) 7/28/08: Chanda received a Supplemental

COMMERCIAL PROPERTY (Continued) **S107788365**

Baseline Groundwater Results prepared by Construction Services International, Inc., dated 7/22/08. (see eDocs) 8/01/08: Chanda received a Remedial Action Plan Revised Implementation Schedule from Construction Services International, Inc. dated 7/30/08. Revised Implementation Schedule stated that a final remediation report will be submitted in January 2009.(see eDocs) 8/26/08: Chanda sent a letter to RP and his consultant, requiring that the final remedial report be submitted to DEC by 1/31/09 for review and approval. 11/12/10 - spill re-assigned from Tibbe to Joe O'Connell 11/2/11 - Raphael Ketani. Spill case reassigned from O'Connell to Ketani. 11/8/11 - Raphael Ketani. I received an e-mail from Mr. O'Connell. He said that Craig Stevens cell (443) 871-8347 called him regarding the site. Mr. Stevens wanted to meet with DEC staff to discuss what is going on at the site. Mr. Stevens later sent Mr. O'Connell the January 7, 2011 Remedial Action Work Plan Addendum 2 and the July 12, 2011 Remedial Action Work Plan Addendum 2, Revision 1. 11/9/11 - Raphael Ketani. Mr. Stevens contacted Mr. O'Connell again, who referred him to Hassan Hussein, the manager of the Hazardous Materials Unit. Mr. Hussein called Mr. Stevens and I and we had a conference call. Mr. Stevens said that soil excavation was taking place and that he would like to meet with us and show us the site. We tentatively set up a site meeting for monday, 11/14/11, at 11 AM. The spill was reported to the DEC on 5/23/06 as a site where groundwater contamination was being treated and further investigation was taking place. According to ACRIS, the site is block and lot 2962 and 11. The City took over the property from Louis Fine of M. Fine Lumber. The deed was dated 5/28/86. The PBS is #2-604641. There was a 550 gal. UST with diesel fuel that was removed on 7/1/2000. M. Fine Lumber was the owner at the time. There are no other spill cases. Craig Stevens, PG, Principal Hydrogeologist, is at Construction Services International, Inc., 918 Chesapeake Avenue, Anapolis, MD, 21403, (410) 268-7261/ cell (443) 871-8347. I reviewed the July 12, 2011 RAWP Addendum 2, Revision 1. The site is a former Fine Lumber Yard. The material is petroleum from a UST that was removed. Two (2) applications of the treatment solutions were applied to the groundwater. Mr. Stevens stated that the applications were effective in reducing the contamination in the groundwater. The former UST area is very contaminated at 7 to 9 feet below grade, about just above the water table. The contaminants are VOCs. During 3/2008, the UST was removed. During 11/2008 and 12/2008, there was a round of treatment solution injections for each month. Six (6) rounds of groundwater monitoring took place from February to October of 2009. During 3/2010, more groundwater monitoring took place. During 6/2010, 7 borings and 3 more monitoring wells were installed, and soil and groundwater samples were collected. The 9/2010 letter report stated that during 6/2010 there was a supplemental environmental study. The vertical extent of the contamination was defined and it was found that the petroleum was not migrating laterally beyond the locations of MW-2R and MW-10 (historically the most contaminated locations). The purpose of the Addendum is to provide the scope of work for addressing the soil contamination at 7 to 9 feet below grade. RegenOx will be used as a contingency plan if the bulk of the contaminated soil can not be removed. The soil results will be compared to STARS standards. The building will be demolished and some of the wells may be destroyed in the process. 11/10/11 - Raphael Ketani. I tried to find the paper files for the case, but could not locate anything. 11/14/11 - Raphael Ketani. A site visit took place today. In

COMMERCIAL PROPERTY (Continued) **S107788365**

attendance were Paul John, DEC Regional Environmental Engineer, Hassan Hussein, DEC Environmental Engineer III - head of the Hazardous Materials Unit, myself, Mr. Stevens of CSI Environmental, John Sullivan, Site Manager Waste Management of New York, and Christopher Prucha, CPG - Waste Management. Mr. Stevens presented the site history and the efforts that were made to investigate and remediate the site. It was stated that the site is owned by Waste Management. The City plans to buy the site and build a salt storage facility on the eastern half of the property. This part of the property will be convered with asphalt by the City. The property borders the English Kills. Groundwater is at about 5 feet to 7 feet below grade, depending on the season. Ninety seven percent of the contaminant mass was at the 7 to 9 foot level and has been removed. The contamination is not moving off site. We then toured the site itself. It was a vacant lot. The building had been torn down. Mr. Stevens pointed out on a site plan where the 550 gal. diesel UST had been. We saw a depression where contaminated soil had been excavated. Mr. Stevens explained a little more about the remediation efforts. After this we left the site. Before leaving, Mr. Stevens gave me copies of the 11/13/09 Remedial Action Status Report, 9/14/10 June 2010 Post-Remedial Action Environmental Study Report, 11/4/11 Remedial Action Closure Report, and a copy on disc of the November 2011 WMNY Closure Report. 11/18/11 - Raphael Ketani. I reviewed the Construction Services November 13, 2009 Remedial Action Status Report, September 14, 2010 June 2010 Post Remedial Action Environmental Study Report, and November 4, 2011 Remedial Action Closure Report. The 11/13/09 Remedial Action Status Report described the two rounds of treatment solution injections and listed the groundwater analyte VOC concentrations up to the 10/6/09 and 10/7/09 sampling round. The results for MW-2R and MW-10 were still very high with hits predominantly in the triple digit range for most analytes. The 9/14/10 June 2010 Post Remedial Action Environmental Study Report described that the soil analytical results and the groundwater analytes suggest that the contaminants are still mostly bound up in the soil (Construction Services estimates the total is 97% of the VOC mass) and are not being readily released. The bulk of the adsorbed VOCs are in an area from SB-1 to SB-4 and include MW-2R and MW-10. However, the contamination is not leaving the site. The groundwater analyte results (6/24/10 and 6/25/10 rounds) were in the high double digits to 4,000 ppb of total xylenes at boring SB-3. The results for MW-2R and MW-10 actually decreased, in general, from the concentrations in the October 2010 samples 10/6/09 and 10/7/09. The 11/4/11 Remedial Action Closure Report stated that soil excavation was completed during August 2011. Residual hydrocarbons were found in the soil at a depth of 7 to 9 feet below grade in an area from well MW-10 to well MW-2R. About 700 cubic yards of soil were removed. The excavation area was partially within the footprint of the former building. Groundwater samples were taken from wells MW-2R to MW-7 and MW-9 to MW-12 on 8/8/11 (the other wells were destroyed when the building was knocked down earlier). Table 2 shows that the analyte concentrations for the groundwater sample from MW-2R typically vary from non-detect to the high double digits with only four analytes showing up to 190 ppb. However, the 8/8/11 sample from MW-10 has 4 analytes up to 490 ppb and three analytes up to 2300 ppb. These results for MW-10 are in the low range for all of the results that have been obtained from this well over the course of the 4 years of sampling from 2008 to 2011. Table 5 contains the post excavation soil

COMMERCIAL PROPERTY (Continued) **S107788365**

sampling results. The great majority of the analytes from each sample are non-detect. Sample EX BASE 5 had 230 ppb of benzene, but this was the only hit of significance amongst all of the data in the table. A statement towards the end of the report says that the fill in the area is a source of high concentrations of analytes. There are pictures in the report which show the sidewalls of the excavation. One picture shows historical fill over red-brown glacial sediments (possibly more fill) which is underlain by dark brownish gray clay and sand. As a side note, it was mentioned to staff at the DEC by Mr. Stevens and Mr. Sullivan that the NYC DOS wants to pave the eastern part of the site where the excavating took place and put up a salt shed (see e-docs). As the great majority of the contamination was removed when the soil was excavated in the eastern part of the site, and as the groundwater analyte concentrations were largely non-detect or low by 8/8/11, and as the site is underlain with historical fill which yields various analytes, and as the area surrounding the site is an industrial area which generates contaminants, and as the future use of the site will be a salt shed on pavement, I have determined that the remaining contamination is not a threat to the public or the environment. Therefore, I am closing the spill case. 11/21/11 - Raphael Ketani. I sent a Spill Closure Letter to Mr. Stevens, Mr. Sullivan and Mr. Prucha. "

Remarks: "THIS IS GROUNDWATER CONTAMINATION. CLEAN UP IS NOT IN PROCESS. THEY ARE STILL INVESTIGATING THE AREA."

All Materials:

Site ID:	364315
Operable Unit ID:	1122343
Operable Unit:	01
Material ID:	2111817
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

G74 **M. FINE LUMBER CO. INC.** **NY UST** **U003749710**
SW **175 VARICK AVE** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.093 mi.
493 ft. **Site 5 of 5 in cluster G**

Relative: **Lower**
Actual: **6 ft.**

UST:

Name:	M. FINE LUMBER CO. INC.
Address:	175 VARICK AVE
City,State,Zip:	BROOKLYN, NY 11237
Id/Status:	2-604641 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590526.52856
UTM Y:	4507295.42567
Site Type:	Trucking/Transportation/Fleet Operation

M. FINE LUMBER CO. INC. (Continued) **U003749710**

Affiliation Records:

Site Id:	26512
Affiliation Type:	Facility Owner
Company Name:	LOUIS FINE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	175 VARICK AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 381-5200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	26512
Affiliation Type:	Mail Contact
Company Name:	M. FINE LUMBER CO. INC.
Contact Type:	Not reported
Contact Name:	MERRITT FINE
Address1:	175 VARICK AVE.
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 381-5200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	26512
Affiliation Type:	Facility Operator
Company Name:	M. FINE LUMBER CO. INC.
Contact Type:	Not reported
Contact Name:	MERRITT FINE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 381-5200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	26512
Affiliation Type:	Emergency Contact
Company Name:	LOUIS FINE
Contact Type:	Not reported
Contact Name:	MERRITT FINE

M. FINE LUMBER CO. INC. (Continued) **U003749710**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 381-5200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	58432
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/2000
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

F75 **ROADWAY** **NY Spills** **S102663535**
NE **METROPOLITAN/GARDNER** **N/A**
< 1/8 **BROOKLYN, NY**
0.095 mi.
501 ft. **Site 6 of 9 in cluster F**

Relative: **Lower**

Actual: **12 ft.**

SPILLS:

Name:	ROADWAY
Address:	METROPOLITAN/GARDNER
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9706343 / 1997-08-25
Facility ID:	9706343
Facility Type:	ER

ROADWAY (Continued) **S102663535**

DER Facility ID:	89803
Site ID:	101342
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1997-08-25
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1997-08-25
CID:	252
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-08-25
Spill Record Last Update:	1997-08-26
Spiller Name:	GABE WEBER
Spiller Company:	ABC TRANSPORT
Spiller Address:	1 QUINBY ST
Spiller Company:	001
Contact Name:	GABE WEBER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT SAME AS 9706334"
Remarks:	"DECK HOSE ON TRUCK BROKE CAUSING SPILL OF MATERIAL ON TO ROADWAY SPILL HAS BEEN CLEANED UP"

All Materials:

Site ID:	101342
Operable Unit ID:	1049711
Operable Unit:	01
Material ID:	331926
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

F76 **CON EDISON - MANHOLE 68205** **RCRA-LQG** **1014397467**
NE **GARDNER AVE AND METROPOLITAN A** **NYP004197893**
< 1/8 **BROOKLYN, NY 11211**
0.097 mi.
510 ft. **Site 7 of 9 in cluster F**

Relative: RCRA-LQG:
Lower

Date Form Received by Agency:	20100323
Handler Name:	CON EDISON - MANHOLE 68205
Handler Address:	GARDNER AVE AND METROPOLITAN A
Handler City,State,Zip:	BROOKLYN, NY 11211

Actual:
12 ft.

CON EDISON - MANHOLE 68205 (Continued) **1014397467**

EPA ID:	NYP004197893
Contact Name:	FRANKLYN MURRAY
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-2808
Contact Fax:	Not reported
Contact Email:	MURRAYFR@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2009
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No

CON EDISON - MANHOLE 68205 (Continued) **1014397467**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20091009
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20091009
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CON EDISON - MANHOLE 68205 (Continued) **1014397467**

Historic Generators:
Receive Date: 20100323
Handler Name: CON EDISON - MANHOLE 68205
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20091009
Handler Name: CON EDISON
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

F77 **CON EDISON** **RCRA NonGen / NLR** **1014396346**
NE **GARDNER AVE & METROPOLITAN AVE** **NYP004186102**
< 1/8 **BROOKLYN, NY 11211**
0.097 mi.
510 ft. **Site 8 of 9 in cluster F**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20160601
Handler Name: CON EDISON
Handler Address: GARDNER AVE & METROPOLITAN AVE
Handler City,State,Zip: BROOKLYN, NY 11211
EPA ID: NYP004186102
Contact Name: CAROLINE ISKANDER
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 718-666-4714
Contact Fax: Not reported
Contact Email: Not reported

CON EDISON (Continued) **1014396346**

Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported

CON EDISON (Continued) **1014396346**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160621
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20090724
Handler Name: CON EDISON	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160601
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

F78 **CONSOLIDATED EDISON** **NY MANIFEST** **S119073342**
NE **GARDNER AVE & METROPOLITAN AVE** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.097 mi.
510 ft. **Site 9 of 9 in cluster F**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	GARDNER AVE & METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY 11211
Country:	USA
EPA ID:	NYP004197893
Facility Status:	Not reported
Location Address 1:	GARDNER AVE AND METROPOLITAN A
Code:	BP
Location Address 2:	VE
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11211
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004197893
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	10/09/2009
Trans1 Recv Date:	10/09/2009
Trans2 Recv Date:	10/12/2009
TSD Site Recv Date:	10/13/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004197893
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	000893912GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CONSOLIDATED EDISON (Continued) **S119073342**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	700
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H79 **CON EDISON** **RCRA NonGen / NLR** **1012185380**
South **SCHOLES & VARICK** **NY MANIFEST** **NYP004161857**
< 1/8 **BROOKLYN, NY 11232**
0.103 mi.
543 ft. **Site 6 of 6 in cluster H**

Relative: **Lower**
Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20160601
Handler Name:	CON EDISON	
Handler Address:		SCHOLES & VARICK
Handler City,State,Zip:		BROOKLYN, NY 11232
EPA ID:		NYP004161857
Contact Name:		HERMAN BAKER
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		718-267-3853
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		4 IRVING PL, RM 828
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported

CON EDISON (Continued) **1012185380**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160706
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON (Continued) **1012185380**

Historic Generators:
Receive Date: 20081015
Handler Name: CON EDISON
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160601
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: SCHOLES & VARICK
City,State,Zip: BROOKLYN, NY 11232
Country: USA
EPA ID: NYP004161857
Facility Status: Not reported
Location Address 1: SCHOLES AND VARICK ST MH 43890
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11232
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004161857

CON EDISON (Continued) **1012185380**

Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/16/2008
Trans1 Recv Date:	10/16/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/16/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004161857
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001433602FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	B007
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON (Continued) **1012185380**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

K80 **NYC DEP** **RCRA NonGen / NLR** **1014395389**
SSE **165 STEWART AVE** **NY MANIFEST** **NYP003662772**
< 1/8 **BROOKLYN, NY 11237**
0.105 mi.
554 ft. **Site 1 of 5 in cluster K**

Relative: **Higher**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20060403
Handler Name:	NYC DEP	
Handler Address:		165 STEWART AVE
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYP003662772
Contact Name:		JOANNE NURSE
Contact Address:		JUNCTION BLVD
Contact City,State,Zip:		FLUSHING, NY 11373
Contact Telephone:		718-595-4675
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		PAA
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		JUNCTION BLVD
Mailing City,State,Zip:		FLUSHING, NY 11373
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported

NYC DEP (Continued) **1014395389**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20101007
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20060403
Handler Name: NYC DEP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

NYC DEP (Continued) **1014395389**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: NYC DEP
Address: 165 STEWART AVE
City,State,Zip: BROOKLYN, NY 11237
Country: USA
EPA ID: NYP003662772
Facility Status: Not reported
Location Address 1: 165 STEWART AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11201
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP003662772
Mailing Name: NYC DEP
Mailing Contact: NYC DEP
Mailing Address 1: 96 05 HORACE HARDING EXPWY
Mailing Address 2: Not reported
Mailing City: CORONA
Mailing State: NY
Mailing Zip: 11368
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7185954784

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD049178296
Trans2 State ID: Not reported
Generator Ship Date: 03/22/2006
Trans1 Recv Date: 03/22/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/04/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP003662772
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: CDX109000000
TSDF ID 2: Not reported
Manifest Tracking Number: NYG4454496
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N

NYC DEP (Continued) **1014395389**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	120
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L81 **NEW TOWN CREEK** **NY Spills** **S104193436**
North **GRANT & STEWART ST** **N/A**
< 1/8 **QUEENS, NY**
0.115 mi.
609 ft. **Site 1 of 8 in cluster L**

Relative: **Lower**

Actual: **7 ft.**

SPILLS:

Name:	NEW TOWN CREEK
Address:	GRANT & STEWART ST
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9905180 / 1999-08-26
Facility ID:	9905180
Facility Type:	ER
DER Facility ID:	255019
Site ID:	316312
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	C3
SWIS:	4101
Spill Date:	1999-07-30
Investigator:	SACCACIO
Referred To:	Not reported
Reported to Dept:	1999-07-30
CID:	211
Water Affected:	NEW TOWN CREEK
Spill Source:	Commercial Vehicle
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

NEW TOWN CREEK (Continued) **S104193436**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-07-30
Spill Record Last Update:	1999-08-26
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MARK GUITERAS
DEC Memo:	""
Remarks:	"CALLER STATES EMPLOYEE FROM WASTE MANAGEMENT WAS CLEANING TRUCK AND RUN OFF ENTERED CREEK - CALLER HAS INFORMATION OF FISH KILL AFTER OPERATION - WASTE MANAGEMENT DOES HAVE FACILTY NEAR-BY - NO CLEAN UP - SHEEN OBSERVED ON SURFACE"

All Materials:

Site ID:	316312
Operable Unit ID:	1079611
Operable Unit:	01
Material ID:	301490
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

K82 **HI TECH HOLDINGS LLC D/B/A SCHOLES STREET RECYCLIN** **NY SWRCY** **S116357461**
South **492 SCHOLES STREET** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.116 mi.
610 ft. **Site 2 of 5 in cluster K**

Relative: **Lower**

Actual: **13 ft.**

SWRCY:

Name:	HI TECH HOLDINGS LLC D/B/A SCHOLES STREET RECYCLING
Address:	492 SCHOLES STREET
City,State,Zip:	BROOKLYN, NY 11237
Region:	2
Facility Address 2:	Not reported
Phone Number:	7183865750
Owner Type:	Private
Owner Name:	Hi Tech Holdings LLC
Owner Address:	130 Varick Ave
Owner Address 2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11237
Owner Email:	Not reported
Owner Phone:	7183865750
Contact Name:	Vincent C. Zambrotta
Contact Address:	Not reported
Contact Address 2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	vinnyz@mrtcarting.com
Contact Phone:	7183865750
Activity Desc:	RHRF - registration
Activity Number:	[24MF9]

HI TECH HOLDINGS LLC D/B/A SCHOLES STREET RECYCLING (Continued) **S116357461**

Active:	Yes
East Coordinate:	590578
North Coordinate:	4507234
Accuracy Code:	Not reported
Regulatory Status:	Registration
Permit #:	24MF9
Auth. Date:	Not reported
Expiration Date:	Not reported
Waste Types:	Paper/Cardboard;Source Separated Recyclables (Metal/Glass/Paper/Plastic);Commingled Paper;Metals (Ferrous);Metals (Non-Ferrous);Plastics
Operator Name:	Vincent Zambrotta
Operator Type:	Private
Last Date:	10/26/2016

K83 **HI-TECH RESOURCE RECOVERY INC** **NY UST** **U003740150**
South **492 SCHOLES STREET** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.116 mi.
610 ft. **Site 3 of 5 in cluster K**

Relative:
Lower

Actual:
13 ft.

UST:

Name:	HI-TECH RESOURCE RECOVERY INC
Address:	492 SCHOLES STREET
City,State,Zip:	BROOKLYN, NY 11237
Id/Status:	2-604389 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590604.00257
UTM Y:	4507234.02097
Site Type:	Other

Affiliation Records:

Site Id:	26263
Affiliation Type:	Facility Owner
Company Name:	HI-TECH RESOURCE RECOVERY INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	130 VARICK AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 386-5750
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	26263
Affiliation Type:	Mail Contact
Company Name:	HI-TECH RESOURCE RECOVERY INC
Contact Type:	Not reported
Contact Name:	MR. VINCENT ZAMBROTTA
Address1:	130 VARICK AVENUE

HI-TECH RESOURCE RECOVERY INC (Continued) **U003740150**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 386-5750
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	26263
Affiliation Type:	Facility Operator
Company Name:	HI-TECH RESOURCE RECOVERY INC
Contact Type:	Not reported
Contact Name:	VINCENT ZAMBROTTA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 386-5750
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	26263
Affiliation Type:	Emergency Contact
Company Name:	HI-TECH RESOURCE RECOVERY INC
Contact Type:	Not reported
Contact Name:	VINCENT ZAMBROTTA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 386-5750
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	133R
Tank ID:	57549
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	11/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

HI-TECH RESOURCE RECOVERY INC (Continued) **U003740150**

Material Code: ZZZZ
Common Name of Substance: Invalid Material - Please Fix

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 264Y
Tank ID: 57548
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 11/01/1995
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: ZZZZ
Common Name of Substance: Invalid Material - Please Fix

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number: 480J
Tank ID: 57551
Tank Status: Closed - In Place
Material Name: Closed - In Place

HI-TECH RESOURCE RECOVERY INC (Continued) **U003740150**

Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	11/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	ZZZZ
Common Name of Substance:	Invalid Material - Please Fix
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J00 - Dispenser - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number:	681K
Tank ID:	57550
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	11/01/1995
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	ZZZZ
Common Name of Substance:	Invalid Material - Please Fix
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J00 - Dispenser - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

K84 **SYNTHETIC PROTECTIVE COATING CO INC** **RCRA NonGen / NLR** **1000409321**
South **492 SCHOLES ST** **FINDS** **NYD001282631**
< 1/8 **BROOKLYN, NY 11237** **ECHO**
0.116 mi. **NY MANIFEST**
610 ft. **Site 4 of 5 in cluster K**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	SYNTHETIC PROTECTIVE COATING CO INC
Handler Address:	492 SCHOLES ST
Handler City,State,Zip:	BROOKLYN, NY 11237-1023
EPA ID:	NYD001282631
Contact Name:	Not reported
Contact Address:	SCHOLES ST
Contact City,State,Zip:	BROOKLYN, NY 11237
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	SCHOLES ST
Mailing City,State,Zip:	BROOKLYN, NY 11237
Owner Name:	SYNTHETIC PROTECTIVE COATING CO INC
Owner Type:	Private
Operator Name:	SYNTHETIC PROTECTIVE COATING CO INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

SYNTHETIC PROTECTIVE COATING CO INC (Continued) **1000409321**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SYNTHETIC PROTECTIVE COATING CO INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999

SYNTHETIC PROTECTIVE COATING CO INC (Continued) **1000409321**

Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SYNTHETIC PROTECTIVE COATING CO INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SYNTHETIC PROTECTIVE COATING CO INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: SYNTHETIC PROTECTIVE COATING CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: SYNTHETIC PROTECTIVE COATING CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101

SYNTHETIC PROTECTIVE COATING CO INC (Continued) **1000409321**

Handler Name: SYNTHETIC PROTECTIVE COATING CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19830302
Handler Name: SYNTHETIC PROTECTIVE COATING CO INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported

SYNTHETIC PROTECTIVE COATING CO INC (Continued) **1000409321**

SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19881123
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:

Registry ID: 110004333285

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000409321
Registry ID:	110004333285
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004333285
Name:	SYNTHETIC PROTECTIVE COATING CO INC
Address:	492 SCHOLES ST
City,State,Zip:	BROOKLYN, NY 11237

NY MANIFEST:

Name:	SYNTHETIC PROTECTIVE COATING
Address:	492 SCHOLES ST
City,State,Zip:	BROOKLYN, NY 11237-1023
Country:	USA
EPA ID:	NYD001282631
Facility Status:	Not reported

SYNTHETIC PROTECTIVE COATING CO INC (Continued) **1000409321**

Location Address 1:	492 SCHOLES ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD001282631
Mailing Name:	SYNTHETIC PROTECTIVE COATING
Mailing Contact:	SYNTHETIC PROTECTIVE COATING
Mailing Address 1:	492 SCHOLES STREET
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

Name:	SYNTHETIC PROTECTIVE COATING CO
Address:	492 SCHOLES ST
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP000776369
Facility Status:	Not reported
Location Address 1:	492 SCHOLES ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000776369
Mailing Name:	SYNTHETIC PROTECTIVE COATING CO
Mailing Contact:	SYNTHETIC PROTECTIVE COATING CO
Mailing Address 1:	492 SCHOLES STREET
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183662200

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

K85 **CASILINO CONTRACTING** **NY Spills** **S102663427**
SE **160 STEWART AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.116 mi.
613 ft. **Site 5 of 5 in cluster K**

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name:	CASILINO CONTRACTING
Address:	160 STEWART AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9705382 / 1997-08-04
Facility ID:	9705382
Facility Type:	ER
DER Facility ID:	191167
Site ID:	231976
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1997-08-04
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1997-08-04
CID:	266
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-08-04
Spill Record Last Update:	2003-02-18
Spiller Name:	PETER LEPORE
Spiller Company:	WHALECO FUEL OIL
Spiller Address:	1 COFFEY STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"BROKEN COULING ON DECK HOSE. ONTO ROAADWAY AND SIDEWALK. HOSE BEING REPAIRED. BEING CLEANED UP."

All Materials:

Site ID:	231976
Operable Unit ID:	1048645
Operable Unit:	01
Material ID:	334598
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	15.00
Oxygenate:	Not reported

CASILINO CONTRACTING (Continued) **S102663427**

Name:	CASALINO
Address:	160 STEWART ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9706947 / 1997-11-13
Facility ID:	9706947
Facility Type:	ER
DER Facility ID:	102303
Site ID:	117602
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1997-09-11
Investigator:	LUCE
Referred To:	Not reported
Reported to Dept:	1997-09-11
CID:	257
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-09-11
Spill Record Last Update:	1997-11-13
Spiller Name:	PETER LETORE
Spiller Company:	WHALECO
Spiller Address:	5560 58TH ST
Spiller Company:	001
Contact Name:	NONE
DEC Memo:	""
Remarks:	"DECK HOSE BROKE SPILL ALREADY CLEANED UP "

All Materials:

Site ID:	117602
Operable Unit ID:	1050305
Operable Unit:	01
Material ID:	332529
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

J86 **CONSOLIDATED CARPET** **NY LTANKS** **S102619094**
NNW **1157 GRAND ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.117 mi.
617 ft. **Site 2 of 5 in cluster J**

Relative: **Lower**
Actual: **4 ft.**

LTANKS:

Name:	CONSOLIDATED CARPET
Address:	1157 GRAND ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9511303 / 2006-02-07
Facility ID:	9511303
Site ID:	193820
Spill Date:	1995-12-07
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	ADZHITOM
Referred To:	INVESTIGATION/DELINEATION
Reported to Dept:	1995-12-07
CID:	323
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1995-12-07
Spill Record Last Update:	2006-02-07
Spiller Name:	STEVEN SACCHINELLI
Spiller Company:	CONSOLIDATED CARPET
Spiller Address:	1157 GRAND ST
Spiller County:	001
Spiller Contact:	STEVEN SACCHINELLI
Spiller Phone:	(718) 456-8207
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	161550
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL This spill was reassigned from DEC Sigona to Rommel on January 7, On Thursday January 25, 1996, Dave Pulvermiller of MTS Environserve called A.Sigona and informed that the 550 gallon UST which failed a tank test would be removed along with two other 550 gallon gasoline USTs. They would be taking samples and doing a site assessment during the tank removal. The tanks will be registered and will submit a substantial modification application. The tanks will be removed the week of January 29, 1996, and DEC Sigona is planning to view the excavations on Tuesday January 30, 1996 at 3:30 PM. The consultant plans to sample and test using EPA method 8020. 3/10/05 - Received Phase II Investigation Report from Laurel Environmental. Re-assigned to Zhitomirsky for followup. - KST 4/25/2005 I left a message for Carla Sullivan.AZ 4/27/2005 Conversation with Carla Sullivan (Laurel Environmental). They plan to excavate contaminated soil and take post excavation samples. I requested to take groundwater samples if gorundwater is encountered. GWT is 10' below the grade. The tank was located at 1181 Grand Street.This is a

CONSOLIDATED CARPET (Continued) **S102619094**

warehouse. They will submit a report in June 2005. AZ 7-27-2005 Laurel Environmental informed DEC that they will remove contaminated soils and apply ORC into the exposed groundwater during the week of August 1, 2005. AZ 10/14/2005 I reviewed Soil Removal Report for this spill. A letter was sent to Laurel Env. with my comments. The letter stated that the following deficiencies were noticed in the report: 1. Post excavation soil samples were not taken 2. The site plan was not drawn to scale 3. Groundwater flow direction was not indicated on the plan 4. Well design diagrams were not submitted 5. Soil samples were not collected and screened during well installation. The report stated that analytical results of groundwater samples collected during this investigation indicate minor exceedances of State water quality standards in samples collected from wells MW-1and MW-2. Laurel Environmental recommended no further action with respect to the removed USTs. The Department could not approve no further action at this time. In consultation with J. Kolleeny it was decided that an additional monitoring well should be installed near the excavated area. Soil samples should be collected during well installation and analyzed in a laboratory. Groundwater at the site should be monitored and sampled again three months after the recent samples were taken. Laboratory data should be provided for all compounds analyzed by EPA Method 8021 plus MTBE, and the results compared to State guidelines. These recommendations were mailed to Laurel Env. AZ 1/17/2006 Additional investigation/delineation is pending. Field work has been done. AZ 2/7/2006 I have reviewed a report by Laurel Environmental Assosiates (LEA). The report states that LEA installed 3 one-inch groundwater monitoring wells. On December 16, 2005, LEA purged and sampled the wells. Laboratory analysis inicates that with the exception of a slight exceedance of m and p xylenes and total xylenes at 7 ppb in MW-2, the concentrations of VOCs are below NYSDEC ambient groundwater criteria. According to the report, the tank and contaminated soil have been removed and groundwater treated in-situ. Based on this information the spill is closed. This spill case was discussed with Koon Tang on 1/23/2006 and he concurred with this decision. AZ"

Remarks: "TEST METHOD NDE MODEL 1000, UNKNOWN LEAK RATE."

All TTF:

Facility ID:	9511303
Spill Number:	9511303
Spill Tank Test:	1544300
Site ID:	193820
Tank Number:	1
Tank Size:	550
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

CONSOLIDATED CARPET (Continued) **S102619094**

Site ID:	193820
Operable Unit ID:	1021843
Operable Unit:	01
Material ID:	358651
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

J87 **ULTIMATE TRUCK & EQUIPMENT** **RCRA-VSQG** **1023678946**
NNW **1157 GRAND ST** **NYN008029019**
< 1/8 **BROOKLYN, NY 11211**
0.117 mi.
617 ft. **Site 3 of 5 in cluster J**

Relative: **Lower**
Actual: **4 ft.**

RCRA-VSQG:

Date Form Received by Agency:	20170315
Handler Name:	ULTIMATE TRUCK & EQUIPMENT
Handler Address:	1157 GRAND ST
Handler City,State,Zip:	BROOKLYN, NY 11211
EPA ID:	NYN008029019
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	GRAND ST
Mailing City,State,Zip:	BROOKLYN, NY 11211
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170315
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20170315
Handler Name:	ULTIMATE TRUCK & EQUIPMENT
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Used Oil - Generators
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20170307
Actual Return to Compliance Date: 20180620
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20170316

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180620
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSC
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20170307
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYSC
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20180620
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20170307
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYSC
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20180620
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20170307
Evaluation Responsible Agency: State

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180620
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20170307
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180620
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20170307
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180620
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20170307
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180620
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20170307
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180620

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20170307
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180620
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20170307
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180620
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20170307
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180620
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20170307
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180620
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

ULTIMATE TRUCK & EQUIPMENT (Continued) **1023678946**

Evaluation Date:	20170307
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180620
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20170307
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180620
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20170307
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180620
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

J88 **ULTIMATE TRUCK & EQUIPMENT** **NY AST** **A100433679**
NNW **1157 GRAND STREET** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.117 mi.
617 ft. **Site 4 of 5 in cluster J**

Relative: AST:
Lower

Actual:
4 ft.

Name:	ULTIMATE TRUCK & EQUIPMENT
Address:	1157 GRAND STREET
City,State,Zip:	BROOKLYN, NY 11211
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-612699
Program Type:	PBS
UTM X:	Not reported
UTM Y:	Not reported
Expiration Date:	04/19/2022

ULTIMATE TRUCK & EQUIPMENT (Continued) **A100433679**

Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id: 545607
Affiliation Type: Facility Owner
Company Name: JOSEPH GOLDBERGER
Contact Type: MEMBER
Contact Name: JOSEPH GOLDBERGER
Address1: 85 N. LORNA LANE
Address2: Not reported
City: SUFFERN
State: NY
Zip Code: 10901
Country Code: 001
Phone: (718) 599-1119 120
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-04-19

Site Id: 545607
Affiliation Type: Mail Contact
Company Name: ULTIMATE TRUCK & EQUIPMENT
Contact Type: Not reported
Contact Name: JOSEPH GOLDBERGER
Address1: 1157 GRAND STREET
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11211
Country Code: 001
Phone: (718) 599-1119 120
EMail: JOEY@ULTITRUCK.COM
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-04-19

Site Id: 545607
Affiliation Type: Facility Operator
Company Name: ULTIMATE TRUCK & EQUIPMENT
Contact Type: Not reported
Contact Name: ELI GOLDBERGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 599-1119
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-04-19

Site Id: 545607
Affiliation Type: Emergency Contact
Company Name: JOSEPH GOLDBERGER
Contact Type: Not reported

ULTIMATE TRUCK & EQUIPMENT (Continued) **A100433679**

Contact Name:	Not reported
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 681-8061
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-04-19

Tank Info:

Tank Number:	001
Tank Id:	267498

Equipment Records:

J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
I01 - Overfill - Float Vent Valve
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2010
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DAFRANCI
Last Modified:	04/19/2017
Material Name:	waste oil/used oil

J89 **ULTIMATE TRUCK & EQUIPMENT** **NY Spills** **S120701231**
NNW **1157 GRAND STREET** **N/A**
< 1/8 **BROOKLYN, NY**
0.117 mi.
617 ft. **Site 5 of 5 in cluster J**

Relative: SPILLS:
Lower

Name:	ULTIMATE TRUCK & EQUIPMENT
Address:	1157 GRAND STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1611187 / 2017-07-24

Actual:
4 ft.

ULTIMATE TRUCK & EQUIPMENT (Continued) **S120701231**

Facility ID:	1611187
Facility Type:	ER
DER Facility ID:	495776
Site ID:	542056
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	2401
Spill Date:	2017-03-07
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2017-03-13
CID:	Not reported
Water Affected:	NEWTOWN CREEK
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2017-03-13
Spill Record Last Update:	2017-07-24
Spiller Name:	Eli Goldberger
Spiller Company:	Ultimate Truck & Equipment
Spiller Address:	1157 Grand Street
Spiller Company:	999
Contact Name:	JOEY GOLDBERGER
DEC Memo:	"Inspection findings forwarded to OGC (Mintzer). Owner's son (Eli) was advised of findings and given direction to clean affected areas and prevent further discharges by modifying housekeeping activities. Unregister 275 waste oil tank in service - no labeling, color coding or inspection records. 7/20/17 TJD Site inspection. Met onsite with owner (Joey). The zipper drains have been cleaned of residual product. Oil water separator has been serviced (Saftey Clean) and is now operating as designed. General housekeeping of shop area is improved. Owner is in the process of loading debris from rear storage yard into a roll-off container for offsite recycling/disposal. Bulkhead remains in poor condition - owner states he is obtaining quotes for repair and/or replacement. DeMeo spoke at length with owner regarding pollution prevention and best management practices. 275 Waste oil tank is properly labeled and color coded - secondary containment beneath AST has been cleaned. No further requirements from the R2 Spills program. Outstanding violations to be addressed by other DEC programs. Spill closed."
Remarks:	"Multi-program inspection performed due to recent complaint from Riverkeeper. Housekeeping issues with resultant petroleum discharges identified as follows: 1) Petroleum discharge to interior zipper/trench drain interior to the structure discharging to a poorly maintained oil water separator with ultimate discharge to NYC sewer system (not known at this time if sewer is storm, sanitary or combined) 2) Oil drip pan (estimated 5 gallon capacity) was found overturned in rear of property, adjacent to Newtown Creek, with visible petroleum impacts to surrounding debris, vegetation and soil. 3) Oil residue and stained concrete surrounding and within secondary containment of unregistered Waste Oil 275 AST 4) Various housekeeping

ULTIMATE TRUCK & EQUIPMENT (Continued) **S120701231**

issues throughout facility with visible petroleum staining and/or accumulation noted both interior and exterior to structure with visible rainbow sheens emanating from spilled petroleum products at time of inspection"

All Materials:

Site ID:	542056
Operable Unit ID:	1290593
Operable Unit:	01
Material ID:	2296450
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

M90 **CON EDISON** **NY MANIFEST** **S117738642**
South **FRONT OF 140 VARICK AV** **N/A**
< 1/8 **BROOKLYN, NY 11237**
0.118 mi.
625 ft. **Site 1 of 13 in cluster M**

Relative:
Lower

Actual:
12 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FRONT OF 140 VARICK AV
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP004717112
Facility Status:	Not reported
Location Address 1:	FRONT OF 140 VARICK AV
Code:	BP
Location Address 2:	SB43891
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004717112
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON (Continued) **S117738642**

seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	01/21/2015
Trans1 Recv Date:	01/21/2015
Trans2 Recv Date:	01/26/2015
TSD Site Recv Date:	01/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004717112
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620053GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I91 **CON EDISON - MANHOLE 36370** **RCRA-LQG** **1016450605**
NW **1131 GRAND STREET** **NY MANIFEST** **NYP004296299**
< 1/8 **BROOKLYN, NY 11211**
0.123 mi.
649 ft. **Site 4 of 12 in cluster I**

Relative: RCRA-LQG:
Lower

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - MANHOLE 36370
Handler Address:	1131 GRAND STREET
Handler City,State,Zip:	BROOKLYN, NY 11211

Actual:
5 ft.

CON EDISON - MANHOLE 36370 (Continued) **1016450605**

EPA ID:	NYP004296299
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	401-765-1500
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No

CON EDISON - MANHOLE 36370 (Continued) **1016450605**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130326
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130326
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CON EDISON - MANHOLE 36370 (Continued) **1016450605**

Historic Generators:

Receive Date:	20140327
Handler Name:	CON EDISON - MANHOLE 36370
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130326
Handler Name:	CON EDISON MANHOLE: 36370
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130426
Handler Name:	CON EDISON MANHOLE: 36370
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	1131 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211

CON EDISON - MANHOLE 36370 (Continued) **1016450605**

Country:	USA
EPA ID:	NYP004296299
Facility Status:	Not reported
Location Address 1:	1131 GRAND STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11211
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004296299
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	03/26/2013
Trans1 Recv Date:	03/26/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/26/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004296299
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002017253GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON - MANHOLE 36370 (Continued) **1016450605**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I92 **1131 GRAND ET IAC** **NY UST** **U003178587**
NW **1131 GRAND STREET** **N/A**
< 1/8 **BROOKLYN, NY 11211**
0.123 mi.
649 ft. **Site 5 of 12 in cluster I**

Relative: **Lower**
Actual: **5 ft.**

UST:

Name:	1131 GRAND ET IAC
Address:	1131 GRAND STREET
City,State,Zip:	BROOKLYN, NY 11211
Id/Status:	2-603035 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590394.22702
UTM Y:	4507588.38256
Site Type:	Other

Affiliation Records:

Site Id:	24989
Affiliation Type:	Facility Owner
Company Name:	RICHARD LEE
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	374 MELROSE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 417-0016
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24989
Affiliation Type:	Mail Contact
Company Name:	BO BO POULTRY INC

1131 GRAND ET IAC (Continued) **U003178587**

Contact Type:	Not reported
Contact Name:	Not reported
Address1:	324 MELROSE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 417-0016
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24989
Affiliation Type:	Facility Operator
Company Name:	1131 GRAND ET IAC
Contact Type:	Not reported
Contact Name:	RICHARD LEE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 417-0016
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24989
Affiliation Type:	Emergency Contact
Company Name:	RICHARD LEE
Contact Type:	Not reported
Contact Name:	RICHARD LEE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 417-0016
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	52736
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	7500
Install Date:	Not reported
Date Tank Closed:	06/01/1997

1131 GRAND ET IAC (Continued) **U003178587**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
H00 - Tank Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

I93 **MANHOLE 1299** **NY Spills** **S106969136**
NW **1131 GRAND ST** **N/A**
< 1/8 **BROOKLYN, NY**
0.123 mi.
649 ft. **Site 6 of 12 in cluster I**

Relative: **Lower**

Actual: **5 ft.**

SPILLS:

Name:	MANHOLE 1299
Address:	1131 GRAND ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0503634 / 2005-08-31
Facility ID:	0503634
Facility Type:	ER
DER Facility ID:	294628
Site ID:	348262
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	2005-06-27
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2005-06-27
CID:	77
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-06-27

MANHOLE 1299 (Continued) **S106969136**

Spill Record Last Update:	2005-08-31
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON 151710
Spiller Address:	128 WEST AVE
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"e2mis no 159434 J. IOCCO REPORTS FINDING APPROX 1/2 GAL OF DIELECTRIC FLUID THAT LEAKED FROM THE BOTTOM OF THE TRANSFORMER IN TM1299 ONTO APPROX 30 GALS OF WATER. SPILL IS CONTAINED TO THE STRUCTURE. NO SEWERS OR WATERWAYS AFFECTED. NO MOVEMENT IN THE WATER. CANNOT VERIFY THE EXISTENCE OF ANY SEWER CONNECTIONS, SUMPS OR DRAINS. WHILE CLEANING THE STRUCTURE, MR. IOCCO INADVERTANTLY SUCKED UP SOME OF THE OIL INTO VACTOR # 60766. HE WILL FINISH THE CLEANUP AND THE VEHICLE WILL REMAIN ON LOC PENDING LAB RESULT. TAG # 46462 PLACED IN STRUCTURE. PCB SAMPLE TAKEN. BQE WILL SEND OUT A CREW TO PRESSURE TEST THE TRANSFORMER. HISTORICAL PCB COUNT OF TRANSFORMER IS 22 PPM DTD 4/1/94. TAG WILL REMAIN IN STRUCTURE PENDING LAB RESULT. UPDATE: 6/27/05 - 1130. FDR # FOR TM1299 IS SD3143. AS PER SHIFT MGR M. CARUSO, UNIT WAS PRESSURE TESTED BY BQE AND HELD PRESSURE. #9 O.S. M. ROTONDI FEELS OIL IN STRUCTURE IS MOTOR OIL. TJ - 50495 LAB RESULT RECEIVED 6/27/05 - 1512. 05-06177. 31 PPM. TJ - 50495 UPDATE - 6/27/05 - 2000HRS. S. ADEDAPO REPORTS DOUBLE WASHED STRUCTURE WITH 760 BIOGEN. REMOVED ALL LIQUIDS AND DEBRIS WITH VACTOR. NO LEAKING CO. EQUIPMENT FOUND. ENV. STOP TAG REMAINS IN PLACE PENDING TRANSFORMER REMOVAL. CN#19661 Update - 6/29/05 0900hrs. This is to clarify the status of this incident. As per G. Palladino to D. Hearns he is reporting that unit is not leaking but will be replaced on outage. Tag remains in place pending transformer removal. cn#19661 6/30/05 1330HRS O.S. C.LABARBARA ENVIR OPPS REPORTS NETW REMOVED AND REPLACED UNIT .#9 TIEING BACK UNIT.REMOVED ENVIR TAG# 46462. G DONATONE UPDATE 6/30/2005 14:30 HRS... PER OS C. LABARBARA ON 6/29 AFTER THE UNIT WAS REMOVED, ENVIRONMENTAL OPS EMPLOYEE GUY CASTRO WASHED THE STRUCTURE, THE STRUCTURE WAS COMPLETELY CLEAN..... E.VESCE. Closed. 8-31-05. GB "
Remarks:	"1/2 GAL OF DIELECTRIC FLUID DUE TO EQUIPMENT FAILURE OF TRANSFORMER. CLEAN-UP PENDING DE-ENERGIZING OF FEEDER. REF # 159434"

All Materials:

Site ID:	348262
Operable Unit ID:	1105920
Operable Unit:	01
Material ID:	1968415
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I94 **VAULT 2597** **NY Spills** **S102150597**
WNW **METROPOLITAN AV** **N/A**
< 1/8 **BROOKLYN, NY**
0.124 mi.
655 ft. **Site 7 of 12 in cluster I**

Relative: **Lower**

Actual: **0 ft.**

SPILLS:

Name:	VAULT 2597
Address:	METROPOLITAN AV
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0312422 / 2004-07-15
Facility ID:	0312422
Facility Type:	ER
DER Facility ID:	242317
Site ID:	299538
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-02-08
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2004-02-08
CID:	41
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-08
Spill Record Last Update:	2004-07-15
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"FEB 8 2004 09:59 Hrs B/Q NETWKS. DEPT. SPLICER R.CILENTO EMP# 44214 REPORTS: WHILE PASSING LOCATION NOTICED STEAM COMEING FROM V2597 (FEEDER # 6B57) FOUND: APPROX. 10 GAL'S OF UNKNOWN OIL ON APPROX. 800 GAL'S OF WATER. SPILL APPEARS TO BE CONTAINED AT THIS TIME. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. NO KNOWN SUMP OR PUMP PRESENT. NO KNOWN SEWER CONNECTION PRESENT. LIQ. SAMPLE TAKEN FROM SPILL & MARKED PRIORITY E CHAIN OF CUSTODY# DD-08255. CLEANUP PENDING TEST RESULTS. INITIAL CLEANUP BEING DONE AS 50-499. UNIT CANNOT BE PRESSURE TESTED AT THIS TIME, DUE TO THE QUANTITY OF WATER IN STRUCTURE. UPDATE 08-FEB-2004 11:00 HRS. UNIT HISTORICAL DATA: SERIAL# F124431, CLASS CODE-GU8, MFG CODE-GE, INSTALL DATE 1/1/65, HIST. PCB RESULTS- 11/8/02 - 9PPM. OIL CAPACITY FOR V-2597=295 GALLONS. THIS VAULT PREVIOUSLY LISTED IN OPEN INCIDENT # 148227. SEE 148227 FOR DETAILS. EPA# NYP 004 117 834 Update 2/9/04 Estimated amount is 35 gals unknown petroleum. No sewer or waterway affected. ENVIR. OPER. MECH-A P.ROSADO EMP# 82008 REPORTS: DBL WASHED STRUCTURE WITH BIO-GEN 760. ASTORIA TANKER REMOVED ALL LIQUIDS FROM UNIT & STRUCTURE. ENVIR.TAG LEFT IN PLACE PENDING UNIT REMOVAL. PRELIMINARY CLEANUP IS COMPLETE AT THIS TIME. Vault #2597 Inc# 152016 all liquids were removed,

VAULT 2597 (Continued) **S102150597**

partially cleaned, and double washed; weep holes were sealed with cement on the east side of the structure that connected to VS-1433; stop tag remains in place for Vaults 2597,and 1856. W. Eckstein, env. ops mech reports as of this time partially cleaned structures so that asbestos abatement could be done this date (3/11/04). 3/11/04 2000 HRS S.ASFOUR NETW REPORTS ASBESTOS ABATEMENT IS COMPLETE IN V2597. update 3-25-04 05:40hrs k. hufford reports, double washed structure again and left tag in place. UPDATE - 3/25/04 - 10HRS Steve Asfour Netw reports asbestos abatement was done in V1856. Secondary gap has been cut and the asbestos shells have been removed. Transformer is ready to be removed from structure. Clean up can be completed when unit is removed. 4/19/04 1850 HRS LIPORI REPORTS CLEANUP COMPLETED DOULBED WASHED STRUCTURE USING BIO GEN 760 .REMOVED ENVIR TAG#33636 . BOTH UNITS ARE REMOVED INCIDENT CLOSED."

Remarks: "UNKNOWN PETROLEUM IN TRANSFORMER VAULT. NO SEWERS OR WATERWAYS. NO SMOKE OR FIRE. NO VISIBLE OIL. NO CRACKS IN STRUCTURE. EAST OF RIVER STREET"

All Materials:

Site ID:	299538
Operable Unit ID:	879878
Operable Unit:	01
Material ID:	497630
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BQE E/B &
Address:	METROPOLITAN AV
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9702070 / 2003-02-24
Facility ID:	9702070
Facility Type:	ER
DER Facility ID:	242317
Site ID:	299539
DEC Region:	2
Spill Cause:	Traffic Accident
Spill Class:	C4
SWIS:	2401
Spill Date:	1997-05-17
Investigator:	GUTIERREZ
Referred To:	Not reported
Reported to Dept:	1997-05-17
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

VAULT 2597 (Continued) **S102150597**

Remediation Phase:	0
Date Entered In Computer:	1997-05-17
Spill Record Last Update:	2003-02-24
Spiller Name:	DONALD ULMER
Spiller Company:	F & T DISTRIBUTORS
Spiller Address:	70 PETERSBURG RD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"TRACTOR HIT AN OBJECT IN THE ROAD AND IT RUPTURED THE TANK - SPILL HAS BEEN CONTAINED AND SAND WAS APPLIED TO THE SPILL BY NYC DOT"

All Materials:

Site ID:	299539
Operable Unit ID:	1047996
Operable Unit:	01
Material ID:	335004
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	NEWTON CREEK REG #B7
Address:	METROPOLITAN AV
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9710120 / 1997-12-05
Facility ID:	9710120
Facility Type:	ER
DER Facility ID:	242317
Site ID:	299540
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	2401
Spill Date:	1997-12-02
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1997-12-02
CID:	365
Water Affected:	LOWER NY BAY
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-12-02
Spill Record Last Update:	1997-12-05
Spiller Name:	RUSS BETTERS
Spiller Company:	NYC DEP
Spiller Address:	RT42

VAULT 2597 (Continued) **S102150597**

Spiller Company: 001
Contact Name: JIM DALY
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT Referred to Brian Mitchell - Water Unit."
Remarks: "REGULATOR GADGE CLOSED BY ITSELF CAUSING SPILL OF .010305 MILLION GALLONS INTO THE LOWER NY BAY. CREW OPENED GATE & IT OKAY NOW."

All Materials:
Site ID: 299540
Operable Unit ID: 1056499
Operable Unit: 01
Material ID: 328438
Material Code: 0062A
Material Name: raw sewage
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

I95 **NEWTOWN CREEK** **NY Spills** **S104952192**
WNW **METROPOLITAN BRIDGE** **N/A**
< 1/8 **BROOKLYN, NY**
0.124 mi.
655 ft. **Site 8 of 12 in cluster I**

Relative: **Lower**
Actual: **0 ft.**

SPILLS:
Name: NEWTOWN CREEK
Address: METROPOLITAN BRIDGE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0011304 / 2003-12-23
Facility ID: 0011304
Facility Type: ER
DER Facility ID: 222873
Site ID: 274022
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 2001-01-17
Investigator: JMROMMEL
Referred To: Not reported
Reported to Dept: 2001-01-17
CID: 257
Water Affected: NEW TOWN CREEK
Spill Source: Unknown
Spill Notifier: Federal Government
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-01-17
Spill Record Last Update: 2003-12-23
Spiller Name: DENNIS FIRPO

NEWTOWN CREEK (Continued) **S104952192**

Spiller Company:	PREMIUM OIL
Spiller Address:	1188 METROPOLITAN AV
Spiller Company:	001
Contact Name:	CHAD DAVIDSON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL See also 0011310 1188 Metropolitan - pipe on truck broke, #4 fuel oil entered storm drain and Newtown Creek. "
Remarks:	"sheen in water"

All Materials:

Site ID:	274022
Operable Unit ID:	833361
Operable Unit:	01
Material ID:	541624
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I96 **MANHOLE #36370** **NY Spills** **S104194308**
WNW **GRAND ST/METROPOLITAN AVE** **N/A**
< 1/8 **BROOKLYN, NY**
0.124 mi.
655 ft. **Site 9 of 12 in cluster I**

Relative: **Lower**

Actual: **0 ft.**

SPILLS:

Name:	MANHOLE #36370
Address:	GRAND ST/METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9906205 / 1999-11-10
Facility ID:	9906205
Facility Type:	ER
DER Facility ID:	195318
Site ID:	237077
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1999-08-24
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1999-08-24
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-08-24

MANHOLE #36370 (Continued) **S104194308**

Spill Record Last Update:	2000-06-01
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	BILL MURPHY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con ed e2mis notes: Approx 3-quarts of unknown oil on 1200 gallons of water in MH-36370. Took 1-sample. lsn#99-08878 <1ppm, cleanup complete and tag removed. Incident is closed. "
Remarks:	"APPROX. 3 QUARTS OF ABOVE MATERIAL DISCOVERED ONTOP OF 1200 GALLONS OF WATER AT ABOVE LOCATION. CLEAN UP PENDING TEST RESULTS. CON ED # 127391. NO CALL BACK REQUESTED."

All Materials:

Site ID:	237077
Operable Unit ID:	1080645
Operable Unit:	01
Material ID:	302473
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I97 **METROPOLITAIN AVE & GRAND** **NY Spills** **S102663534**
WNW **METROPOLITAIN AVE & GRAND** **N/A**
< 1/8 **BROOKLYN, NY**
0.124 mi.
655 ft. **Site 10 of 12 in cluster I**

Relative:
Lower

Actual:
0 ft.

SPILLS:

Name:	METROPOLITAIN AVE & GRAND
Address:	METROPOLITAIN AVE & GRAND
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9706334 / 1997-08-25
Facility ID:	9706334
Facility Type:	ER
DER Facility ID:	259651
Site ID:	322309
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1997-08-25
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1997-08-25
CID:	205
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

METROPOLITAIN AVE & GRAND (Continued) **S102663534**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-08-25
Spill Record Last Update:	1997-08-26
Spiller Name:	SAME
Spiller Company:	ABC TRANSPORT
Spiller Address:	18-65 4ND STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT REFERRED TO FD- SANITATION AND FAXED ECS."
Remarks:	"LEAKING FROM TANK AFTER KICKING UP STONE THAT CUT HOSE."

All Materials:

Site ID:	322309
Operable Unit ID:	1052464
Operable Unit:	01
Material ID:	331917
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I98 **METROPOLITAN AVE BRIDGE** **NY Spills** **S107409500**
WNW **METROPOLITAN AVENUE** **N/A**
< 1/8 **BROOKLYN, NY**
0.124 mi.
655 ft. **Site 11 of 12 in cluster I**

Relative:
Lower

Actual:
0 ft.

SPILLS:

Name:	METROPOLITAN AVE BRIDGE
Address:	METROPOLITAN AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0205135 / 2002-08-16
Facility ID:	0205135
Facility Type:	ER
DER Facility ID:	195292
Site ID:	237049
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	2002-08-15
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2002-08-15
CID:	207
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported

METROPOLITAN AVE BRIDGE (Continued) **S107409500**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-15
Spill Record Last Update:	2002-08-16
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	PINAKIN PATEL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 8/16/2002-VOUGHT-Spoke with Pinakin Patel on 8/16. No spill associated with bridge work. Work performed was replacement of a a steel roadplate. No spill occurred."
Remarks:	"NOTIFICATION DOT IS WORKING ON BRIDGE "

I99 **METROPOLITAN AVE BRIDGE** **NY Spills** **S106469921**
WNW **OVER ENGLISH KILLS CREEK** **N/A**
< 1/8 **BROOKLYN, NY**
0.124 mi.
655 ft. **Site 12 of 12 in cluster I**

Relative: **Lower**

Actual: **0 ft.**

SPILLS:

Name:	METROPOLITAN AVE BRIDGE
Address:	OVER ENGLISH KILLS CREEK
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0402660 / 2006-08-25
Facility ID:	0402660
Facility Type:	ER
DER Facility ID:	201025
Site ID:	244729
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-06-04
Investigator:	qxabidi
Referred To:	Not reported
Reported to Dept:	2004-06-10
CID:	407
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-10
Spill Record Last Update:	2006-08-25
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JOHN KURREY

METROPOLITAN AVE BRIDGE (Continued) **S106469921**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 6/10/04 Tipple updating////wood cribbing below movable bridge soaked with oil,approx 10'x20' area. (Sample results back today) and gasoline approx 2' below pavement at the intersection of Metropolitan and Varick Streets. DOT will excavate as per design for both bridge footing and roadway and properly dispose of all contaminated debris. Report will follow once the subsurface work is completed. 06/28/06: This spill is transferred from Mr. Koon Tang to Q.Abidi. Contacted to Mr. John Kurrey at (212)788-2083 regarding information of spill. He said that they did rebuilding the bridge and collected soil samples. He will find out the report and he will fax me. -QA 07/07/06: Reviewed report of soil samples analytical data recieved today from Mr. John Kurre by mail. Soil samples are not cleaned yet. They have to do additional Investigation including Investigation of groundwater and soil sampling from different locations. -QA 08/17/06: Recieved call from Mr. John Kurre he said this is not the remedial project. He excavated the soil where the have made the bidge. He also said that whole neighbourhood is contaminated. He will send a letter explaining the situation. -QA 08/21/06: Called Mr. John Kurre he will send a letter soon because he is not going to do anything over there. He will explain the situation in the letter. -QA 08/23/06: Called Mr. John Kurre and asked about waste manifest report. He said that he will fax it to me at the earliest. -QA 08/24/06: Called Mr. John Kurre for waste manifest report and left message to call me back. -QA 08/25/06: According to the letter of Mr. John Kurre, Director, Environmental Engineering unit, Only contaminated soil encountered during construction activities was excavated and the excavated soil was disposed of at a licenced and permitted disposal facility. No attempt was made to identify the source of the spill. Currently the metropolitan bridge construction has been completed and all excavated areas were backfilled with clean fill and the bridge roadways were replaced. Based on this information staff closed the spill. -QA "

Remarks: "Cleanup is pending."

All Materials:

Site ID:	244729
Operable Unit ID:	884318
Operable Unit:	01
Material ID:	490277
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Site ID:	244729
Operable Unit ID:	884318
Operable Unit:	01
Material ID:	490276
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L

METROPOLITAN AVE BRIDGE (Continued) **S106469921**

Recovered: .00
Oxygenate: Not reported

N100 **CON EDISON** **NY MANIFEST** **S117538353**
NE **228 GARDNER AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.129 mi.
682 ft. **Site 1 of 6 in cluster N**

Relative: **Lower**
Actual: **10 ft.**

NY MANIFEST:
Name: CON EDISON
Address: 228 GARDNER AVE
City,State,Zip: BROOKLYN, NY 11211
Country: USA
EPA ID: NYP004710216
Facility Status: Not reported
Location Address 1: 228 GARDNER AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11211
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004710216
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 12/21/2014
Trans1 Recv Date: 12/30/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/30/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004710216
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014161753JJK

CON EDISON (Continued) **S117538353**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1658
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	B002
Waste Code 1_6:	Not reported

L101 **CONSOLIDATED CARPET TRADE WORKROOM INC.** **NY UST** **U003065847**
North **1181 GRAND STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.132 mi.
697 ft. **Site 2 of 8 in cluster L**

Relative:
Lower

Actual:
2 ft.

UST:

Name:	CONSOLIDATED CARPET TRADE WORKROOM INC.
Address:	1181 GRAND STREET
City,State,Zip:	BROOKLYN, NY 11211
Id/Status:	2-233234 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590484.60849
UTM Y:	4507679.73838
Site Type:	Other

Affiliation Records:

Site Id:	8476
Affiliation Type:	Facility Owner
Company Name:	CONSOLIDATED CARPET TRADE WORKROOM INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1181 GRAND STREET
Address2:	Not reported

CONSOLIDATED CARPET TRADE WORKROOM INC. (Continued) **U003065847**

City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 456-8207
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8476
Affiliation Type:	Mail Contact
Company Name:	CONSOLIDATED CARPET TRADE WORKROOM
Contact Type:	Not reported
Contact Name:	MICHAEL TASSONE
Address1:	Not reported
Address2:	1181 GRAND STREET
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 456-8207
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8476
Affiliation Type:	Facility Operator
Company Name:	CONSOLIDATED CARPET TRADE WORKROOM INC.
Contact Type:	Not reported
Contact Name:	CONSOLIDATED CARPET
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 456-8207
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	8476
Affiliation Type:	Emergency Contact
Company Name:	CONSOLIDATED CARPET TRADE WORKROOM INC.
Contact Type:	Not reported
Contact Name:	MICHAEL TASSONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 456-8207
EMail:	Not reported

CONSOLIDATED CARPET TRADE WORKROOM INC. (Continued) **U003065847**

Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	24154
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	06/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	08/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	002
Tank ID:	24155
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	03/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	03
Date Test:	08/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

CONSOLIDATED CARPET TRADE WORKROOM INC. (Continued) **U003065847**

Equipment Records:

H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number:	003
Tank ID:	50719
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	004
Tank ID:	50720
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

CONSOLIDATED CARPET TRADE WORKROOM INC. (Continued) **U003065847**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 005
Tank ID: 50721
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

L102 **CONSOLIDATED CARPET TRADE WORK** **RCRA NonGen / NLR** **1001119547**
North **1181 GRAND ST** **NY MANIFEST** **NYR000028340**
1/8-1/4 **BROOKLYN, NY 11211**
0.132 mi.
697 ft. **Site 3 of 8 in cluster L**

Relative: **Lower**
Actual: **2 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	CONSOLIDATED CARPET TRADE WORK
Handler Address:	1181 GRAND ST
Handler City,State,Zip:	BROOKLYN, NY 11211-1811
EPA ID:	NYR000028340
Contact Name:	Not reported
Contact Address:	GRAND ST
Contact City,State,Zip:	BROOKLYN, NY 11211
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	GRAND ST
Mailing City,State,Zip:	BROOKLYN, NY 11211
Owner Name:	DAVID MEBERG
Owner Type:	Private
Operator Name:	DAVID MEBERG
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CONSOLIDATED CARPET TRADE WORK (Continued) **1001119547**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DAVID MEBERG
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1181 GRAND ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11211
Owner/Operator Telephone:	718-456-8207
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	DAVID MEBERG
Legal Status:	Private
Date Became Current:	Not reported

CONSOLIDATED CARPET TRADE WORK (Continued) **1001119547**

Date Ended Current:	Not reported
Owner/Operator Address:	1181 GRAND ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11211
Owner/Operator Telephone:	718-456-8207
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DAVID MEBERG
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1181 GRAND ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11211
Owner/Operator Telephone:	718-456-8207
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name:	CONSOLIDATED CARPET TRADE WORK
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	CONSOLIDATED CARPET TRADE WORK
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	CONSOLIDATED CARPET TRADE WORK
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

CONSOLIDATED CARPET TRADE WORK (Continued) **1001119547**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960819
Handler Name: CONSOLIDATED CARPET TRADE WORK
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED CARPET TRADE WORKROOM
Address: 1181 GRAND ST
City,State,Zip: BROOKLYN, NY 11211-1811
Country: USA
EPA ID: NYR000028340
Facility Status: Not reported
Location Address 1: 1181 GRAND STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11211
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000028340
Mailing Name: CONSOLIDATED CARPET TRADE WORKROOM
Mailing Contact: STEVEN SACCHINELLI
Mailing Address 1: 1181 GRAND STREET
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11211
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7184568207

L103 **NYC FIRE DEPT ENGINE CO 206** **RCRA NonGen / NLR** **1001197481**
North **1201 GRAND ST** **FINDS** **NYR000040360**
1/8-1/4 **BROOKLYN, NY 11211** **ECHO**
0.138 mi. **NY MANIFEST**
727 ft. **Site 4 of 8 in cluster L**

Relative: **Lower**
Actual: **5 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	NYC FIRE DEPT ENGINE CO 206
Handler Address:	1201 GRAND ST
Handler City,State,Zip:	BROOKLYN, NY 11211-1811
EPA ID:	NYR000040360
Contact Name:	Not reported
Contact Address:	GRAND ST
Contact City,State,Zip:	BROOKLYN, NY 11206
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	GRAND ST
Mailing City,State,Zip:	BROOKLYN, NY 11206
Owner Name:	NYC FIRE DEPT
Owner Type:	Municipal
Operator Name:	NYC FIRE DEPT
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

NYC FIRE DEPT ENGINE CO 206 (Continued) **1001197481**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	X003
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYC FIRE DEPT
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1201 GRAND ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11206
Owner/Operator Telephone:	718-965-8206
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYC FIRE DEPT
Legal Status:	Municipal
Date Became Current:	Not reported

NYC FIRE DEPT ENGINE CO 206 (Continued) **1001197481**

Date Ended Current:	Not reported
Owner/Operator Address:	1201 GRAND ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11206
Owner/Operator Telephone:	718-965-8206
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYC FIRE DEPT
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1201 GRAND ST
Owner/Operator City,State,Zip:	BROOKLYN, NY 11206
Owner/Operator Telephone:	718-965-8206
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name:	NYC FIRE DEPT ENGINE CO 206
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name:	NYC FIRE DEPT ENGINE CO 206
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name:	NYC FIRE DEPT ENGINE CO 206
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

NYC FIRE DEPT ENGINE CO 206 (Continued) **1001197481**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970604
Handler Name: NYC FIRE DEPT ENGINE CO 206
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004534834

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001197481
Registry ID: 110004534834
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004534834
Name: NYC FIRE DEPT ENGINE CO 206
Address: 1201 GRAND ST
City,State,Zip: BROOKLYN, NY 11211

NY MANIFEST:
Name: NYC FIRE DEPT ENGINE CO 206
Address: 1201 GRAND ST
City,State,Zip: BROOKLYN, NY 11211-1811
Country: USA
EPA ID: NYR000040360

NYC FIRE DEPT ENGINE CO 206 (Continued) **1001197481**

Facility Status: Not reported
Location Address 1: 1201 GRAND ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11206
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000040360
Mailing Name: NYC FIRE DEPT ENGINE CO 206
Mailing Contact: DANIEL DONOGHUE
Mailing Address 1: 1201 GRAND ST
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11206
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7189658206

L104 **ENGINE COMPANY 206** **NY UST** **U004078183**
North **1201 GRAND STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.138 mi.
727 ft. **Site 5 of 8 in cluster L**

Relative:
Lower

Actual:
5 ft.

UST:
Name: ENGINE COMPANY 206
Address: 1201 GRAND STREET
City,State,Zip: BROOKLYN, NY 11211
Id/Status: 2-601787 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 590528.30617
UTM Y: 4507695.11062
Site Type: Other

Affiliation Records:
Site Id: 23749
Affiliation Type: Facility Owner
Company Name: F.D.N.Y.
Contact Type: Not reported
Contact Name: Not reported
Address1: 9 METROTECH CENTER
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201-3857
Country Code: 001
Phone: (718) 999-2094
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI

ENGINE COMPANY 206 (Continued) **U004078183**

Date Last Modified: 2016-09-15

Site Id: 23749
Affiliation Type: Mail Contact
Company Name: F.D.N.Y. - BLDG. MAINTENANCE
Contact Type: Not reported
Contact Name: DIRECTOR
Address1: 48-34 35TH STREET
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 784-6510
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 23749
Affiliation Type: Facility Operator
Company Name: ENGINE COMPANY 206
Contact Type: Not reported
Contact Name: COMPANY OFFICER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 965-8206
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 23749
Affiliation Type: Emergency Contact
Company Name: F.D.N.Y.
Contact Type: Not reported
Contact Name: EOC/NOTIFICATION DESK
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 999-2094
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-01-07

Tank Info:

Tank Number: 001
Tank ID: 47793

ENGINE COMPANY 206 (Continued) **U004078183**

Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	Not reported
Date Tank Closed:	02/01/2001
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number:	003
Tank ID:	47795
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1100
Install Date:	Not reported
Date Tank Closed:	12/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
F00 - Pipe External Protection - None

ENGINE COMPANY 206 (Continued) **U004078183**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

L105 **ENGINE COMPANY 206** **NY AST** **U003178529**
North **1201 GRAND STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.138 mi.
727 ft. **Site 6 of 8 in cluster L**

Relative: **Lower**

Actual: **5 ft.**

AST:

Name:	ENGINE COMPANY 206
Address:	1201 GRAND STREET
City,State,Zip:	BROOKLYN, NY 11211
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-601787
Program Type:	PBS
UTM X:	590528.30617
UTM Y:	4507695.11062
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	23749
Affiliation Type:	Facility Owner
Company Name:	F.D.N.Y.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	9 METROTECH CENTER
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201-3857
Country Code:	001
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-09-15

Site Id:	23749
Affiliation Type:	Mail Contact
Company Name:	F.D.N.Y. - BLDG. MAINTENANCE
Contact Type:	Not reported
Contact Name:	DIRECTOR
Address1:	48-34 35TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-6510
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

ENGINE COMPANY 206 (Continued) **U003178529**

Site Id:	23749
Affiliation Type:	Facility Operator
Company Name:	ENGINE COMPANY 206
Contact Type:	Not reported
Contact Name:	COMPANY OFFICER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 965-8206
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23749
Affiliation Type:	Emergency Contact
Company Name:	F.D.N.Y.
Contact Type:	Not reported
Contact Name:	EOC/NOTIFICATION DESK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-01-07

Tank Info:

Tank Number:	002
Tank Id:	47794
Material Code:	0009
Common Name of Substance:	Gasoline

Equipment Records:

A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported

ENGINE COMPANY 206 (Continued) **U003178529**

Install Date:	Not reported
Capacity Gallons:	1100
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1997
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	gasoline

Tank Number:	004
Tank Id:	47796
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground
F00 - Pipe External Protection - None
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	005
Tank Id:	55980
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G01 - Tank Secondary Containment - Diking (Aboveground)
J02 - Dispenser - Suction Dispenser

ENGINE COMPANY 206 (Continued) **U003178529**

C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
F05 - Pipe External Protection - Jacketed
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1998
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	diesel

N106 **WASTE MANAGEMENT OF NY (232 GARDNER)** **NY SWF/LF** **S105841929**
NNE **232 GARDNER AVENUE** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.138 mi.
727 ft. **Site 2 of 6 in cluster N**

Relative: **Lower**
Actual: **10 ft.**

SWF/LF:

Name:	WASTE MANAGEMENT OF NY (232 GARDNER)
Address:	232 GARDNER AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	7185335308
Owner Name:	Waste management of NY
Owner Type:	Private
Owner Address:	123 Varick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11237
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Tara Hemmer
Contact Address:	123 Varick Avenue
Contact Addr2:	Not reported
Contact City,St,Zip:	Brooklyn, NY 11237
Contact Email:	Not reported
Contact Phone:	7185335308
Activity Desc:	C&D processing - permit
Activity Number:	[24W98]
Active:	No
East Coordinate:	590800
North Coordinate:	4507700
Accuracy Code:	2.1 - NYSDEC 100 m grid collection
Regulatory Status:	Permit
Waste Type:	Wood (Clean)
Authorization #:	2-6101-00113
Authorization Date:	3/10/1997

WASTE MANAGEMENT OF NY (232 GARDNER) (Continued) **S105841929**

Expiration Date: 3/10/2002
Operator Name: Not reported
Operator Type: Not reported
Laste Date: Not reported

SPILLS:

Name:	232 GARDNER AVE
Address:	232 GARDNER AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9705376 / 1997-08-04
Facility ID:	9705376
Facility Type:	ER
DER Facility ID:	105306
Site ID:	121322
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1997-08-04
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1997-08-04
CID:	281
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-08-04
Spill Record Last Update:	2003-02-24
Spiller Name:	UNKNOWN
Spiller Company:	Not reported
Spiller Address:	232 GARDNER AVE
Spiller Company:	001
Contact Name:	MIKE CONNOLLY
DEC Memo:	""
Remarks:	"MALFUNCTIONING OIL BURNER. CREW ON SCENE AND CLEAN UP IS IN PROGRESS."

All Materials:

Site ID:	121322
Operable Unit ID:	1051373
Operable Unit:	01
Material ID:	334594
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	50.00
Oxygenate:	Not reported

N107 **WASTE MANAGEMENT OF NEW YORK,LLC** **NY AST** **S107782970**
NNE **232 GARDNER AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.138 mi.
727 ft. **Site 3 of 6 in cluster N**

Relative:
Lower

Actual:
10 ft.

AST:

Name:	WASTE MANAGEMENT OF NEW YORK,LLC
Address:	232 GARDNER AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-602602
Program Type:	PBS
UTM X:	590679.03443
UTM Y:	4507683.30132
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	24559
Affiliation Type:	Facility Owner
Company Name:	WASTE MANAGEMENT OF NEW YORK,LLC
Contact Type:	ENVIRONMENTAL MANAGER
Contact Name:	JAY KAPLAN
Address1:	123 VARICK AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 533-5310
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MABARTLE
Date Last Modified:	2005-03-17

Site Id:	24559
Affiliation Type:	Mail Contact
Company Name:	WASTE MANAGEMENT OF NEW YORK,LLC
Contact Type:	ENVIRONMENTAL MANAGER
Contact Name:	JAY KAPLAN
Address1:	123 VARICK AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 533-5310
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MABARTLE
Date Last Modified:	2005-03-17

Site Id:	24559
Affiliation Type:	Facility Operator
Company Name:	WASTE MANAGEMENT OF NEW YORK,LLC
Contact Type:	Not reported
Contact Name:	JAY KAPLAN

WASTE MANAGEMENT OF NEW YORK,LLC (Continued) **S107782970**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 533-5310
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MABARTLE
Date Last Modified:	2005-03-17

Site Id:	24559
Affiliation Type:	Emergency Contact
Company Name:	WASTE MANAGEMENT OF NEW YORK,LLC
Contact Type:	Not reported
Contact Name:	JAY KAPLAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 533-5310
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MABARTLE
Date Last Modified:	2005-03-17

Tank Info:

Tank Number:	001
Tank Id:	50689
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
D11 - Pipe Type - Flexible Piping
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1994

WASTE MANAGEMENT OF NEW YORK,LLC (Continued) **S107782970**

Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/01/2005
Register:	True
Modified By:	MABARTLE
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	002
Tank Id:	50690
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
L00 - Piping Leak Detection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D11 - Pipe Type - Flexible Piping

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel Tank in Concrete
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1994
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/01/2005
Register:	True
Modified By:	MABARTLE
Last Modified:	04/14/2017
Material Name:	diesel

M108 **HI-TECH RESOURCE RECOVERY INC** **NY SWF/LF** **S105841723**
South **130 VARICK AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.138 mi.
728 ft. **Site 2 of 13 in cluster M**

Relative: SWF/LF:
Lower

Name:	HI-TECH RESOURCE RECOVERY INC
Address:	130 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	ACTIVE

Actual:
12 ft.

HI-TECH RESOURCE RECOVERY INC (Continued) **S105841723**

Region Code:	2
Phone Number:	7183865750
Owner Name:	Hi-Tech Resource Recovery Inc.
Owner Type:	Private
Owner Address:	7310 Edsall Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Glendale, NY 11385
Owner Email:	atarantola@mrtcarting.com
Owner Phone:	7183660834
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[24T73]
Active:	Yes
East Coordinate:	590541
North Coordinate:	4507211
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	MSW (Residential/Institutional & Commercial);Commingled Paper & Containers;Corrugated Cardboard;Metals (Ferrous & Non-Ferrous);Commingled Plastics;Wood (Brush/ Branches/ Trees/ Stumps)
Authorization #:	2-6104-00012/00004
Authorization Date:	7/9/2019
Expiration Date:	5/4/2021
Operator Name:	Hi-Tech Resource Recovery Inc
Operator Type:	Private
Laste Date:	Not reported

Name:	HI-TECH RESOURCE RECOVERY INC
Address:	130 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	ACTIVE
Region Code:	2
Phone Number:	7183865750
Owner Name:	Hi-Tech Resource Recovery Inc.
Owner Type:	Private
Owner Address:	7310 Edsall Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Glendale, NY 11385
Owner Email:	atarantola@mrtcarting.com
Owner Phone:	7183660834
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - permit
Activity Number:	[24W73]
Active:	Yes
East Coordinate:	590541
North Coordinate:	4507211
Accuracy Code:	Not reported

HI-TECH RESOURCE RECOVERY INC (Continued) **S105841723**

Regulatory Status:	Permit
Waste Type:	Construction & Demolition Debris;Metals (Ferrous);Metals (Non-Ferrous);Paper / Cardboard;Plastics
Authorization #:	2-6104-00012/00004
Authorization Date:	7/9/2019
Expiration Date:	5/4/2021
Operator Name:	Hi-Tech Resource Recovery Inc
Operator Type:	Private
Laste Date:	Not reported

M109 **HI-TECH RESOURCE RECOVERY INC** **RCRA NonGen / NLR** **1008374412**
South **130 VARICK AVE** **NYN008014441**
1/8-1/4 **BROOKLYN, NY 11237**
0.138 mi.
728 ft. **Site 3 of 13 in cluster M**

Relative: **Lower**

Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	HI-TECH RESOURCE RECOVERY INC
Handler Address:	130 VARICK AVE
Handler City,State,Zip:	BROOKLYN, NY 11237
EPA ID:	NYN008014441
Contact Name:	VINCENT ZAMBROTTA
Contact Address:	Not reported
Contact City,State,Zip:	NY
Contact Telephone:	718-386-5750
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NY
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported

HI-TECH RESOURCE RECOVERY INC (Continued) **1008374412**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20040402
Handler Name:	HI-TECH RESOURCE RECOVERY INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

HI-TECH RESOURCE RECOVERY INC (Continued) **1008374412**

Receive Date: 20060101
Handler Name: HI-TECH RESOURCE RECOVERY INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: HI-TECH RESOURCE RECOVERY INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

O110 **BAYSIDE FUEL OIL DEPOT CORP** **RCRA NonGen / NLR** **1000366366**
WNW **1100 GRAND ST** **FTTS** **NYD980526420**
1/8-1/4 **BROOKLYN, NY 11211** **HIST FTTS**
0.142 mi. **FINDS**
752 ft. **Site 1 of 6 in cluster O** **ECHO**

Relative:
Higher

Actual:
14 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: BAYSIDE FUEL OIL DEPOT CORP
Handler Address: 1100 GRAND ST
Handler City,State,Zip: BROOKLYN, NY 11211-1701
EPA ID: NYD980526420
Contact Name: Not reported
Contact Address: SHORE PKWY
Contact City,State,Zip: BROOKLYN, NY 11214
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02

BAYSIDE FUEL OIL DEPOT CORP (Continued) **1000366366**

Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	SHORE PKWY
Mailing City,State,Zip:	BROOKLYN, NY 11214
Owner Name:	ALFRED ALLEGRETTI
Owner Type:	Private
Operator Name:	ALFRED ALLEGRETTI
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No

BAYSIDE FUEL OIL DEPOT CORP (Continued) **1000366366**

Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	K051
Waste Description:	API SEPARATOR SLUDGE FROM THE PETROLEUM REFINING INDUSTRY.
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ALFRED ALLEGRETTI
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1776 SHORE PKWY
Owner/Operator City,State,Zip:	BROOKLYN, NY 11214
Owner/Operator Telephone:	718-372-9800
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	ALFRED ALLEGRETTI
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1776 SHORE PKWY
Owner/Operator City,State,Zip:	BROOKLYN, NY 11214
Owner/Operator Telephone:	718-372-9800
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	ALFRED ALLEGRETTI
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1776 SHORE PKWY
Owner/Operator City,State,Zip:	BROOKLYN, NY 11214

BAYSIDE FUEL OIL DEPOT CORP (Continued) **1000366366**

Owner/Operator Telephone: 718-372-9800
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: BAYSIDE FUEL OIL DEPOT CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: BAYSIDE FUEL OIL DEPOT CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: BAYSIDE FUEL OIL DEPOT CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980406
Handler Name: BAYSIDE FUEL OIL DEPOT CORP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

BAYSIDE FUEL OIL DEPOT CORP (Continued) **1000366366**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FTTS INSP:
Inspection Number: 2000062114616 2
Region: 02
Inspection Date: 06/21/00
Inspector: A. REDDY, DT
Violation occurred: No
Investigation Type: EPCRA, Enforcement, Federal Conducted
Investigation Reason: Neutral Scheme, Region
Legislation Code: EPCRA
Facility Function: Processor

HIST FTTS INSP:
Inspection Number: 2000062114616 2
Region: 02
Inspection Date: Not reported
Inspector: A. REDDY, DT
Violation occurred: No
Investigation Type: EPCRA, Enforcement, Federal Conducted
Investigation Reason: Neutral Scheme, Region
Legislation Code: EPCRA
Facility Function: Processor

FINDS:
Registry ID: 110004386860

Click Here:

Environmental Interest/Information System:
NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United

BAYSIDE FUEL OIL DEPOT CORP (Continued) **1000366366**

States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000366366
Registry ID:	110004386860
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004386860
Name:	BAYSIDE - GRAND STREET TERMINAL
Address:	1100 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211

O111 **BAYSIDE FUEL OIL DEPOT-1100 GRAND ST** **NY MOSF** **S102150611**
WNW **1100 GRAND ST** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY 11211** **NY SPDES**
0.142 mi.
752 ft. **Site 2 of 6 in cluster O**

Relative:
Higher

Actual:
14 ft.

MOSF:

Name:	BAYSIDE FUEL OIL DEPOT CORP.
Address:	1100 GRAND STREET
City,State,Zip:	BROOKLYN, NY 11211
Facility ID:	2-1280
Program Type:	MOSF
Tank Status:	Active
Expiration Date:	03/31/2023
Dec Region:	2
UTMX:	590199.08129
UTMY:	4507510.10481

SPILLS:

Name:	CIBRO TERMINAL
Address:	1100 GRAND STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9505983 / 2009-03-25
Facility ID:	9505983
Facility Type:	ER

BAYSIDE FUEL OIL DEPOT-1100 GRAND ST (Continued) **S102150611**

DER Facility ID:	119283
Site ID:	280171
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	2401
Spill Date:	1995-08-15
Investigator:	LXZIELIN
Referred To:	Not reported
Reported to Dept:	1995-08-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-09-11
Spill Record Last Update:	2009-03-25
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"03/25/09 - LZ According to Anna-Marie Franzese of Bayside Fuel Oil Depot, who inquired a facility's employee, during removal of an UST, contaminated soil of unknown quantity was disposed of. The spill case is closed. Prior to Sept, 2004 data translation this spill Lead_DEC Field was BREEN "
Remarks:	"TANK REMOVAL - FOUND SOME CONTAMINATED SOIL - ESTIMATING SOME AMOUNT - GEORGE BREEN FROM DEC ON SITE"

All Materials:

Site ID:	280171
Operable Unit ID:	1020784
Operable Unit:	01
Material ID:	363971
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

Name:	DRILL 1
Address:	1100 GRAND ST
City,State,Zip:	BROOKLYN, NY 11207
Spill Number/Closed Date:	1701952 / 2017-05-30
Facility ID:	1701952
Facility Type:	ER
DER Facility ID:	503704
Site ID:	550075

BAYSIDE FUEL OIL DEPOT-1100 GRAND ST (Continued) **S102150611**

DEC Region:	2
Spill Cause:	Unknown
Spill Class:	E5
SWIS:	2401
Spill Date:	2017-05-30
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2017-05-30
CID:	Not reported
Water Affected:	NEW TOWN CREEK
Spill Source:	Chemical Bulk Storage Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-05-30
Spill Record Last Update:	2017-05-30
Spiller Name:	DRILL FRANK
Spiller Company:	DRILL
Spiller Address:	1100 GRAND ST
Spiller Company:	999
Contact Name:	DRILL FRANK
DEC Memo:	"**********DRILL**********"
Remarks:	"DRILL DRILL DRILL"

All Materials:

Site ID:	550075
Operable Unit ID:	1298154
Operable Unit:	01
Material ID:	2304303
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2000.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	OIL FACILITY
Address:	1100 GRAND STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2009285 / 2021-03-19
Facility ID:	2009285
Facility Type:	ER
DER Facility ID:	119283
Site ID:	616268
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2021-02-08
Investigator:	RHLIN
Referred To:	Not reported

BAYSIDE FUEL OIL DEPOT-1100 GRAND ST (Continued) **S102150611**

Reported to Dept:	2021-02-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2021-02-08
Spill Record Last Update:	2021-03-19
Spiller Name:	VINCENT ALLEGRETTI
Spiller Company:	BAY SIDE FUEL OIL DEPOT
Spiller Address:	1100 GRAND STREET
Spiller Company:	999
Contact Name:	VINCENT ALLEGRETTI
DEC Memo:	"2/8/21 - Sekhon Due to human error 1000 - 3000 gallons spilled, contained, Miller environmental on its way. Case discussed with DEC Austin & DEC Lin dispatched to investigate. 2/9/21 - Kim - I returned to the site at 10AM. Dan with Miller Environmental and Mike with Bayside Fuel were on site. Miller Environmental had a crew working on the soil covered tanks, removing impacted snow and soil. A Miller Environmental guzzler vacuum truck was being used to collect impacted material. Dan with Miller Environmental stated that oil started coming out of the gauge opening, which is located close to the concrete curb surrounding the soil covered tanks, and a small amount of oil went over the curb. Some oil also likely came out of the vent lines as well. The impacted area past the concrete curb was removed and drummed. The majority of the oil went into the drain located on top of the soil covered tanks and into the soil covering the tanks within the concrete curb. This drainage system discharges to a holding tank connected to the Oil Water Separator. I did not observe any spilled oil in the Oil Water Separator. Mike with Bayside Fuel showed me some of the site's monitoring wells; I did not observe any spilled oil in the monitoring wells. 2/12/21 - Kim - I revisited the Bayside Terminal today at 11:30AM and met with Dan Goodwin with Miller Environmental. Miller is continuing to work on removing the contaminated soil on top of the soil covered tanks. Today they were working on the area towards Newtown Creek and closer to where the storm drain on top of the tanks is located. Miller Environmental's crew was working on removing another load of soil by hand-digging impacted soil and using a Miller guzzler truck. As there is a storm expected over the weekend, Miller are going to cover any unexcavated areas impacted by the spilled oil with a tarp. Based on the current forecast, it is questionable whether they will be able to continue working on the cleanup on Tuesday. 2/16/21 - Kim - I spoke with Dan Goodwin with Miller Environmental this morning. Today, they had a rolloff truck remove 2 containers with waste debris for disposal. In anticipation of the storm over this past 3-day weekend, they cancelled soil excavation work for today. On Friday 2/12, they covered unexcavated, soil-impacted areas on top of these tanks with a plastic cover that appeared to have held up well over the weekend. There are some areas on top of these tanks where precipitation accumulated, so they placed absorbent booms within the concrete curb to contain any oil. There was no sheen observed on Newtown Creek and

BAYSIDE FUEL OIL DEPOT-1100 GRAND ST (Continued) **S102150611**

no sheen observed on standing puddles of water located outside of the concrete curb. 2/23/21 - Kim - I revisited the Bayside Terminal today at 10AM and met with'Dan Murphy with Miller and a crew that were at on site today continuing to dig contaminated soil and collecting the contaminated soil with their guzzler truck. They are planning to have a rolloff truck remove 1 container with waste debris for disposal today. Dan Murphy anticipates that they may be able to complete digging the contaminated soil tomorrow. 3/19/21-lin-According to Bayside Fuel Depot, the terminal operator was conducting a transfer between tanks following a power outage. During the transfer, the operator left his post to check on a person trying to gain access to the control room. The power outage affected the high alarm's ability to operate to design criteria. When the operator returned he noticed the release and stopped the transfer. Inventory reconciliation indicate the release was 1,870 gallons. Majority of the oil made it to the collection system on-site and went to a holding tank. About 1,876 gallons of oil and water was pumped out from the holding tank. According to miller most of the liquid pumped out from the holding tank was oil (approximately 1,600 gallons. About 200 to 300 gallons of oil made it onto the soil on the tank farm. The contaminated soil was removed using a guzzler and trenches were dug to capture the oil. Spills staff confirmed that the contaminated soil was removed from the tank farm using a PID meter. Groundwater monitoring wells on-site were checked and no free product were found in all the wells that were checked. All waste material generated were properly disposed of. Case closed."

Remarks: "Oil depot spilled and has been stopped and has osro oil spill response company or MEG miller environmental Group. is on the way. all contents spilled into the ground."

All Materials:

Site ID:	616268
Operable Unit ID:	1363391
Operable Unit:	01
Material ID:	2375640
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3000.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	CIBRO TERMINALS
Address:	1100 GRAND STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9007551 / 2009-03-25
Facility ID:	9007551
Facility Type:	ER
DER Facility ID:	119283
Site ID:	139620
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	A3
SWIS:	2401
Spill Date:	1990-10-10

BAYSIDE FUEL OIL DEPOT-1100 GRAND ST (Continued) **S102150611**

Investigator:	LXZIELIN
Referred To:	Not reported
Reported to Dept:	1990-10-10
CID:	Not reported
Water Affected:	KILLS
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-10-10
Spill Record Last Update:	2009-03-25
Spiller Name:	Not reported
Spiller Company:	CIBRO
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"03/25/09 - LZ The spill has been contained by employing booms and cleaned up. The spill case is closed. Prior to Sept, 2004 data translation this spill Lead_DEC Field was BREEN DEC SIGONA REASSIGNED TO GEORGE BREEN ON 1/23/98"
Remarks:	"TANK OVERFILL, BARGE UNLOADING INTO 200K TANK, HUMAN ERROR CAUSED OVERFILL, AAA IS ON SITE TO CLEAN UP BOOMS HAVE BEEN DEPLOYED, USCG HAS BEEN NOTIFIED, NYCDEP & NYCFD ALSO NOTIFIED."

All Materials:

Site ID:	139620
Operable Unit ID:	948205
Operable Unit:	01
Material ID:	431403
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5000.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	CIBRO TERMINALS
Address:	1100 GRAND STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9104487 / 2009-03-25
Facility ID:	9104487
Facility Type:	ER
DER Facility ID:	119283
Site ID:	139621
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	2401
Spill Date:	1991-07-26
Investigator:	LXZIELIN
Referred To:	Not reported

BAYSIDE FUEL OIL DEPOT-1100 GRAND ST (Continued) **S102150611**

Reported to Dept:	1991-07-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-07-29
Spill Record Last Update:	2009-03-25
Spiller Name:	Not reported
Spiller Company:	CIBRO
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"03/25/09 - LZ Free product of unknown quantity has been extracted from the well. Presently, no monitoring well at the facility indicates the presence of free product (based on weekly and monthly reports on gauging of monitoring wells). The spill case is closed. . Prior to Sept, 2004 data translation this spill Lead_DEC Field was BREEN 11/18/94: REASSIGNED FROM SIGONA TO BREEN ON 11/18/94. 10/10/95: This is additional information about material spilled from the translation of the old spill file: WEATHERED #2F.0."
Remarks:	"DISCOVERED IN 4 SITE WELL #2"

All Materials:

Site ID:	139621
Operable Unit ID:	955257
Operable Unit:	01
Material ID:	423551
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPDES:

Name:	BAYSIDE FUEL OIL DEPOT-1100 GRAND ST
Address:	1100 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211
Permit Number:	NY0007641
State-Region:	2
Expiration Date:	12/31/2025
Current Major Minor Status:	Minor
Primary Facility SIC Code:	5171
State Water Body Name:	ENGLISH KILLS
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	5.00000000
Total App Design Flow(MGD):	Not reported

BAYSIDE FUEL OIL DEPOT-1100 GRAND ST (Continued) **S102150611**

UDF1:	DMR
Lat/Long:	40.713760 / 73.9320435
DMR Cognizant Official:	SCOTT VITELLO
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	BAYSIDE FUEL OIL DEPOT CORPORATION
Non-Gov Permit Street Address:	1776 SHORE PKWY
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11214
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	BAYSIDE FUEL OIL DEPOT CORP
Non-Gov Facility Street Address:	BAYSIDE FUEL OIL DEPOT-1100 GRAND STREET
Non-Gov Facility Supplemental Location:	1100 GRAND STREET
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	02030201010
Region Permit Processed:	C
Dow Discharge Class Code:	01
SPDES Class Description:	State Significant Industrial
Affiliation Type Description:	Private
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

O112 **BAYSIDE FUEL OIL DEPORT CORP** **FINDS 1016158527**
WNW **1100 GRAND ST** **FUELS PROGRAM N/A**
1/8-1/4 **BROOKLYN, NY 11231**
0.142 mi.
752 ft. **Site 3 of 6 in cluster O**

Relative:
Higher

Actual:
14 ft.

FINDS:
Registry ID: 110070241347

Click Here:

Environmental Interest/Information System:
GASOLINE AND DIESEL PRODUCERS

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

FUELS PROGRAM:

Name:	BAYSIDE FUEL OIL DEPORT CORP
Address:	1100 GRAND ST
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11231
Program Type:	Diesel
Company Seq. ID:	4980
Business Activity:	Pipeline/Pass-Through Terminal, Truck Loading Terminal/Locomotive Marker Facility
Company Name:	BAYSIDE FUEL OIL DEPOT CORP
Company Address:	1776 SHORE PARKWAY BROOKLYN, NY 11214

BAYSIDE FUEL OIL DEPORT CORP (Continued) **1016158527**

Facility ID:	82643
Facility Type:	Diesel/Biodiesel
Facility Activity:	Mobile Facility, Truck Loading Terminal/Locomotive Marker Facility, Pipeline/Pass-Through Terminal Facility
Subject to 80.1403:	Not reported
Fuel Only For Off Road:	Yes
Fuel Created:	Not reported
D Code:	Not reported
OTAQ Program ID:	OTAQREG10027506

O113 **BAYSIDE FUEL OIL DEPOT CORP.** **NY MOSF UST** **S102633581**
WNW **1100 GRAND STREET** **NY MOSF AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.142 mi.
752 ft. **Site 4 of 6 in cluster O**

Relative:
Higher

Actual:
14 ft.

MOSF UST:

Id/Status:	2-1280 / ACTIVE FACILITY
SWIS Code:	61
Facility Town:	NEW YORK CITY
Contact Phone:	(718) 387-6641
Emergency Contact:	VINCENT ALLEGRETTI
Emergency Telephone:	(718) 372-9800
CBS Number:	Not reported
SPDES Num:	0-007641
Total Tanks:	8
Total Capacity:	1651241
Avg Throughput:	130000
License Stat:	1
Facility Type:	STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Prod Xfer Options:	AC
Expiration Date:	03/31/2002
Applic Rcvd:	01/05/2001
Operator:	VINCENT ALLEGRETTI
Owner Name:	BAYSIDE FUEL OIL DEPOT CORP.
Owner Address:	1776 SHORE PARKWAY
Owner City,St,Zip:	BROOKLYN, NY 11214-
Owner Telephone:	(718) 372-9800
Owner Type:	Corporate/Commercial
Owner Status:	1
Owner Mark:	Second Owner
Mail To Name:	BAYSIDE FUEL OIL DEPOT CORP.
Mail To Address:	1776 SHORE PARKWAY
Mail To Address 2:	PO BOX 140128
Mail City,St,Zip:	BROOKLYN, NY 11214-0002
Mail To Contact:	VINCENT ALLEGRETTI
Mail To Telephone:	(718) 372-9800
Legal Agent Name:	ALFRED ALLEGRETTI
Legal Agent Address:	1776 SHORE PARKWAY
Legal Agent City,St,Zip:	BROOKLYN, NY 11214-
Date Filed:	03/65
Latitude:	14|42|45
Longitude:	73|55|45

Tank ID:	001
Tank Location:	UNDERGROUND
Install Date:	12/37

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Capacity (Gal):	99960
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	Impressed Current
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	42
Dispenser:	Suction
Test Date:	03/96
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	002
Tank Location:	UNDERGROUND
Install Date:	12/37
Capacity (Gal):	249984
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	Impressed Current
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	42
Dispenser:	Suction
Test Date:	03/96
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Federal Id No: Not reported
COI Date: / /

Tank ID: 003
Tank Location: UNDERGROUND
Install Date: 12/37
Capacity (Gal): 149982
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: Epoxy Liner
Tank External: Impressed Current
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: None
Leak Detection: Groundwater Well
Overfill Protection: 42
Dispenser: Suction
Test Date: 03/96
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 07/13/1999
Inspector Initials: GN
Inspector Status: Not reported
Pipe Flag: False
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 10/31/2001
Federal Id No: Not reported
COI Date: / /

Tank ID: 004
Tank Location: UNDERGROUND
Install Date: 12/37
Capacity (Gal): 249984
Product: DIESEL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: Epoxy Liner
Tank External: Impressed Current
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: None
Leak Detection: Groundwater Well
Overfill Protection: 42
Dispenser: Suction
Test Date: 03/96
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 07/13/1999

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	005
Tank Location:	UNDERGROUND
Install Date:	12/37
Capacity (Gal):	249984
Product:	DIESEL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	Impressed Current
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	42
Dispenser:	Suction
Test Date:	03/96
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	00A
Tank Location:	UNDERGROUND
Install Date:	12/65
Capacity (Gal):	550
Product:	EMPTY
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Leak Detection:	Groundwater Well
Overfill Protection:	None
Dispenser:	Suction
Test Date:	01/88
Date Closed:	00/00
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	00B
Tank Location:	UNDERGROUND
Install Date:	12/65
Capacity (Gal):	550
Product:	EMPTY
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	None
Dispenser:	Suction
Test Date:	01/88
Date Closed:	00/00
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	00C
Tank Location:	UNDERGROUND
Install Date:	12/65
Capacity (Gal):	550
Product:	EMPTY
Tank Status:	In Service
Tank Type:	Steel/carbon steel

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	None
Dispenser:	Suction
Test Date:	01/88
Date Closed:	00/00
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	00D
Tank Location:	UNDERGROUND
Install Date:	12/65
Capacity (Gal):	550
Product:	EMPTY
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	None
Dispenser:	Suction
Test Date:	01/88
Date Closed:	00/00
Status of Data:	Complete
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Tank ID:	OBF1
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	2000
Product:	EMPTY
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	None
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	OPS
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	7200
Product:	EMPTY
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	Groundwater Well
Overfill Protection:	None
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Inspected Date:	07/13/1999
Inspector Initials:	GN
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	04/01/2001

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

MOSF AST:

MOSF Number:	2-1280
SWIS Code:	61
Facility Town:	NEW YORK CITY
Facility Phone:	(718) 387-6641
Emergency Contact Name:	VINCENT ALLEGRETTI
Emergency Contact Phone:	(718) 372-9800
Total Tanks:	8
Total Capacity:	1651241
Daily Throughput:	130000
License Status:	1
Facility Type:	STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Product Transfer Operation:	AC
Facility Status:	IN SERVICE
Operator Name:	VINCENT ALLEGRETTI
Owner Name:	BAYSIDE FUEL OIL DEPOT CORP.
Owner Address:	1776 SHORE PARKWAY
Owner City,St,Zip:	BROOKLYN, NY 11214-
Owner Phone:	(718) 372-9800
Owner Type:	Corporate/Commercial
Owner Status:	1
Owner Mark:	Second Owner
Mailing Name:	BAYSIDE FUEL OIL DEPOT CORP.
Mailing Address:	1776 SHORE PARKWAY
Mailing Address 2:	PO BOX 140128
Mailing City,St,Zip:	BROOKLYN, NY 11214-0002
Mailing Contact:	VINCENT ALLEGRETTI
Mailing Phone:	(718) 372-9800
Legal Agent Name:	ALFRED ALLEGRETTI
Legal Agent Address:	1776 SHORE PARKWAY
Legal Agent City,St,Zip:	BROOKLYN, NY 11214-
LIC Expires:	03/31/2002

Tank ID:	OBF-2
Tank Location:	ABOVEGROUND
Install Date:	11/99
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	Impervious Underlayment
Leak Detection:	None
Overfill Protection:	Vent Whistle
Dispensing Mthd:	Gravity
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Capacity (gal): 275
Lat/Long: 14|42|45 / 73|55|45
Federal ID: Not reported
Inspected Date: 07/13/1999
Inspector: GN
Renew Date: 10/31/2001
Inspected State: Not reported
Pipe Flag: False
Vessel ID: Not reported
Reserve Flag: True
Tank Status: In Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: Not reported
Pollution Discharge Elimination System Num: 0-007641
Date Legal Agent Filed with Secretary of State: 03/65

Tank ID: 000
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Install Date: 12/88
Product: EMPTY
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: CATHODIC PROTECTION
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Secondary Containment: None
Leak Detection: Concrete Pad w/channels
Overfill Protection: None
Dispensing Mthd: Gravity
Test Date: Not reported
Date Closed: 00/00
Status of Data: Complete
Capacity (gal): 5000
Lat/Long: 14|42|45 / 73|55|45
Federal ID: Not reported
Inspected Date: 07/13/1999
Inspector: GN
Renew Date: 10/31/2001
Inspected State: Not reported
Pipe Flag: False
Vessel ID: Not reported
Reserve Flag: True
Tank Status: In Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: Not reported
Pollution Discharge Elimination System Num: 0-007641
Date Legal Agent Filed with Secretary of State: 03/65

Tank ID: OBF

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Install Date:	08/92
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	81
Leak Detection:	53
Overfill Protection:	64
Dispensing Mthd:	Suction
Test Date:	Not reported
Date Closed:	08/92
Status of Data:	Complete
Capacity (gal):	1080
Lat/Long:	14|42|45 / 73|55|45
Federal ID:	Not reported
Inspected Date:	07/13/1999
Inspector:	GN
Renew Date:	10/31/2001
Inspected State:	Not reported
Pipe Flag:	False
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	In Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-007641
Date Legal Agent Filed with Secretary of State:	03/65

Tank ID:	006
Tank Location:	ABOVEGROUND
Install Date:	12/72
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	FIBERGLASS REINFORCED PLASTIC
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	75
Leak Detection:	53
Overfill Protection:	42
Dispensing Mthd:	Suction
Test Date:	06/01
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	649992
Lat/Long:	14|42|45 / 73|55|45
Federal ID:	Not reported

BAYSIDE FUEL OIL DEPOT CORP. (Continued) **S102633581**

Inspected Date:	07/13/1999
Inspector:	GN
Renew Date:	10/31/2001
Inspected State:	Not reported
Pipe Flag:	False
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	In Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-007641
Date Legal Agent Filed with Secretary of State:	03/65

L114 **UNION BEER DIST. L.L.C.** **NY UST** **U000408173**
North **1213-17 GRAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.143 mi.
756 ft. **Site 7 of 8 in cluster L**

Relative: **Lower**

Actual: **7 ft.**

UST:

Name:	UNION BEER DIST. L.L.C.
Address:	1213-17 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211
Id/Status:	2-010863 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590613.32312
UTM Y:	4507664.88008
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	92
Affiliation Type:	Facility Owner
Company Name:	UB DISTRIBUTOR L.L.C.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1213 GRAND STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 497-2407
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	92
Affiliation Type:	Mail Contact
Company Name:	UB DISTRIBUTORS L.L.C.
Contact Type:	Not reported
Contact Name:	WAREHOUSE OPERTATIONS MGR
Address1:	1213-17 GRAND STREET

UNION BEER DIST. L.L.C. (Continued) **U000408173**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 497-2407
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	92
Affiliation Type:	Facility Operator
Company Name:	UNION BEER DIST. L.L.C.
Contact Type:	Not reported
Contact Name:	MICHAEL BROPHY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 497-2407
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	92
Affiliation Type:	Emergency Contact
Company Name:	UB DISTRIBUTOR L.L.C.
Contact Type:	Not reported
Contact Name:	MICHAEL BROPHY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 389-5059
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	30375
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	09/01/1998
Date Tank Closed:	09/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

UNION BEER DIST. L.L.C. (Continued) **U000408173**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 10
Date Test: 05/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 002
Tank ID: 30376
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 09/01/1998
Date Tank Closed: 09/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 10
Date Test: 05/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 003
Tank ID: 30377
Tank Status: Closed - Removed
Material Name: Closed - Removed

UNION BEER DIST. L.L.C. (Continued) **U000408173**

Capacity Gallons:	4000
Install Date:	09/01/1998
Date Tank Closed:	09/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	10
Date Test:	05/01/1996
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	004
Tank ID:	30378
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

UNION BEER DIST. L.L.C. (Continued) **U000408173**

Tank Number:	005
Tank ID:	30379
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	006
Tank ID:	30380
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

UNION BEER DIST. L.L.C. (Continued) **U000408173**

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 007
Tank ID: 30381
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other

Tank Number: 008
Tank ID: 30382
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

UNION BEER DIST. L.L.C. (Continued) **U000408173**

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other

Tank Number:	009
Tank ID:	30383
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None

L115 **1213 GRAND STREET** **NY LTANKS** **S103479685**
North **1213 GRAND STREET** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.143 mi.
756 ft. **Site 8 of 8 in cluster L**

Relative: **Lower**
Actual: **7 ft.**

LTANKS:

Name:	UB DISTRIBUTORS
Address:	1213 GRAND STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9807882 / 2002-05-15
Facility ID:	9807882
Site ID:	290514
Spill Date:	1998-09-28
Spill Cause:	Tank Overfill

1213 GRAND STREET (Continued) **S103479685**

Spill Source:	Commercial/Industrial
Spill Class:	B2
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1998-09-28
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-09-28
Spill Record Last Update:	2002-05-15
Spiller Name:	STEVE BRAUN
Spiller Company:	UB DISTRIBUTORS
Spiller Address:	1213 GRAND ST
Spiller County:	001
Spiller Contact:	STEVE BRAUN
Spiller Phone:	(718) 444-3400
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	86699
DEC Memo:	""
Remarks:	"during tank closure caller found soil contamination by top of tank cause appears to be overfill"

All Materials:

Site ID:	290514
Operable Unit ID:	1065455
Operable Unit:	01
Material ID:	315423
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	290514
Operable Unit ID:	1065455
Operable Unit:	01
Material ID:	315422
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

1213 GRAND STREET (Continued) **S103479685**

SPILLS:

Name:	UNION BEER FACILITY
Address:	1213 GRAND ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1207649 / 2012-12-27
Facility ID:	1207649
Facility Type:	ER
DER Facility ID:	424999
Site ID:	470708
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	2401
Spill Date:	2012-10-30
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2012-10-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-10-30
Spill Record Last Update:	2013-04-26
Spiller Name:	MICHAEL SEMMINELLO
Spiller Company:	UNION BEER FACILITY
Spiller Address:	1213 GRAND ST
Spiller Company:	999
Contact Name:	MICHAEL SEMMINELLO
DEC Memo:	"Location is English Kills section of Newtown Creek . Sangesland spoke to Tracy at spill center for owner. She said the canal overflowed into the basement, knocked over drums of oil, oil floated on top of canal water and spilled back into the canal. Facility has no power. No cleanup happening yet. 10/30/12- Zhune responded to this site and spoke to Tim 347-351-1166. He brougt me to the truck mechanic shop but I could not get inside becouse he had no keys to open the door. I saw oil (black oil) outside the shop and a heavy rainbow sheen in the water (Gowanus canal). Tim said tomorrow the Environmental Company is going to do the clean up. 10/31/12-Zhune spoke to tracy. She said Environmental Products and Service are going to clean tha spill. She said call J. Bradshw 518-470-0010 and find out if they are going to do the the clean up. Zhune called J. Bradshw at 2:00 PM. he said we are going to the site now. 12/27/12-Trace Murphy from Spill Canter Inc. emailed the spill cloure letter provided by Environmental Products & Services of Vermont Inc. dated December 21, 2012. On October 31, 2012, Environmental Products and Servises of Vermont Inc. was contacted to respond to a motor oil release of aproximately 400 gallons located at Transervice Logistics. The motor oil was located in drums within the building. The canal adjacent to the property fooded and caused the drums to spill. The motor oil then covered the duck floor and parking lot outside of the building. The area impacted by the oil was absorbed with speedi-dry,

1213 GRAND STREET (Continued) **S103479685**

sweep it up, and placed into drums for disposal. the parking lot and interior floor was pressure washed. a total of 4 drums of oil soaked debris were generated snd 2 drums of liquid for disposal. The drums were removed from site and trasnported to Environmental Products & Service of Vermont Inc. in the Port of Albany, New York recycling Disposal. Spill Closed. "

Remarks: "Storm related: water came into basement of facility tipping over 55 gal drums with motor oil & used oil. Cleanup is pending."

All Materials:

Site ID:	470708
Operable Unit ID:	1220568
Operable Unit:	01
Material ID:	2219184
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	400.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	1213 GRAND STREET
Address:	1213 GRAND STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9512436 / 2002-05-15
Facility ID:	9512436
Facility Type:	ER
DER Facility ID:	86699
Site ID:	97266
DEC Region:	2
Spill Cause:	Other
Spill Class:	B3
SWIS:	2401
Spill Date:	1995-01-04
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1996-01-05
CID:	216
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-01-05
Spill Record Last Update:	2002-05-15
Spiller Name:	ROMEO SANTOS
Spiller Company:	GING TRUCK LEASEING CORP
Spiller Address:	1213 GRAND STREET
Spiller Company:	001
Contact Name:	JOE DEMARCO
DEC Memo:	""

1213 GRAND STREET (Continued) **S103479685**

Remarks: "CALLER TOOK SOIL SAMPLES FOUND SOME CONTAMINATION AT ABOVE BUSSINESS AND THE SAMPLES ARE BEING SENT OUT FOR TESTING "

All Materials:

Site ID:	97266
Operable Unit ID:	1026657
Operable Unit:	01
Material ID:	356180
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

M116 **COOPER RECYCLING; LLC.** **NY SWF/LF** **S103517663**
South **123 VARICK AVENUE** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY 11237** **NY Financial Assurance**
0.146 mi. **NY MANIFEST**
771 ft. **Site 4 of 13 in cluster M** **NY SPDES**

Relative:
Lower

Actual:
11 ft.

SWF/LF:

Name:	WASTE MANAGEMENT OF NY; LLC
Address:	123 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	7185335308
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	TARA HEMMER
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[24W89]
Active:	No
East Coordinate:	590500
North Coordinate:	4507400
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	Not reported
Authorization #:	2-6104-00013
Authorization Date:	10/30/1996
Expiration Date:	10/30/2001
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

COOPER RECYCLING; LLC. (Continued) **S103517663**

Name:	WASTE MANAGEMENT OF NY; LLC
Address:	123 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	7185335308
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	TARA HEMMER
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[24T89]
Active:	No
East Coordinate:	590500
North Coordinate:	4507400
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	Not reported
Authorization #:	2-6104-00013
Authorization Date:	10/30/1996
Expiration Date:	10/30/2001
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

Name:	COOPER RECYCLING; LLC.
Address:	123 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	7185335398
Owner Name:	Adrienne Cooper
Owner Type:	Private
Owner Address:	123 Varick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11237
Owner Email:	Not reported
Owner Phone:	7184974431
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[24W89]
Active:	No
East Coordinate:	590588

COOPER RECYCLING; LLC. (Continued) **S103517663**

North Coordinate: 4507083
Accuracy Code: 4.2 - Utilization of GIS and existing spatial data
Regulatory Status: Permit
Waste Type: Not reported
Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Cooper Recycling
Operator Type: Private
Laste Date: Not reported

Name: COOPER RECYCLING; LLC.
Address: 123 VARICK AVENUE
City,State,Zip: BROOKLYN, NY 11237
Flag: ACTIVE
Region Code: 2
Phone Number: 7185335398
Owner Name: Adrienne Cooper
Owner Type: Private
Owner Address: 123 Varick Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11237
Owner Email: Not reported
Owner Phone: 7184974431
Contact Name: Not reported
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: CDDHRF - permit
Activity Number: [24CP0089]
Active: Yes
East Coordinate: 590497
North Coordinate: 4507117
Accuracy Code: Not reported
Regulatory Status: Permit
Waste Type: Construction & Demolition Debris;Brick
Authorization #: 2-6104-00012/00003
Authorization Date: 4/30/2020
Expiration Date: 4/29/2025
Operator Name: Cooper Recycling
Operator Type: Private
Laste Date: Not reported

SPILLS:
Name: SPILL NUMBER 0204059
Address: 123 VARICK AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0204059 / 2002-07-30
Facility ID: 0204059
Facility Type: ER
DER Facility ID: 251293
Site ID: 289786
DEC Region: 2
Spill Cause: Other
Spill Class: C3

COOPER RECYCLING; LLC. (Continued) **S103517663**

SWIS:	2401
Spill Date:	2002-07-18
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2002-07-18
CID:	199
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-07-18
Spill Record Last Update:	2002-07-30
Spiller Name:	MIKE BAVARO
Spiller Company:	CITY & COUNTY PAVING CO
Spiller Address:	11-21 154TH ST
Spiller Company:	001
Contact Name:	JAY KAPLAN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 7/23/2002 SPOKE WITH JAY KAPLAN, HE WILL SEND IN PHOTOS AND MANIFESTS FOR CLOSURE"
Remarks:	"city and county waste truck was dumping at the transfer station and a container that was ill marked tipped over spilling the materal - all state power vac. is enroute for clean up - they should be able to recover all materal as it spilled to concrete "

All Materials:

Site ID:	289786
Operable Unit ID:	856865
Operable Unit:	01
Material ID:	518318
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	150.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WASTE MANAG.
Address:	123 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0512331 / 2006-03-28
Facility ID:	0512331
Facility Type:	ER
DER Facility ID:	251293
Site ID:	358625
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2006-01-24

COOPER RECYCLING; LLC. (Continued) **S103517663**

Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2006-01-24
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-01-24
Spill Record Last Update:	2006-03-28
Spiller Name:	JAY KAPLAN
Spiller Company:	WASTE MANAG.
Spiller Address:	123 VARICK AVE
Spiller Company:	001
Contact Name:	JAY KAPLAN
DEC Memo:	"Off hours 01/31/06 Sharif// Left a messege for Jay Kaplan,(718)533-5310 to follow up the clean up. 03/21/06 Sharif Rahman- I called Jay Kaplan again and left a messege for him to call DEC back. 03/28/06 Sharif Rahman- Rec'd waste disposal manifest and fact sheet from Waste Management(WM).NFA required."
Remarks:	"filter broke, clean up crews are schedualed to arrive in the morning. Contained within an oil/water seperator."

All Materials:

Site ID:	358625
Operable Unit ID:	1115862
Operable Unit:	01
Material ID:	2105970
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WASTE MANAGMENT OF NY
Address:	123 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9805562 / 2012-09-25
Facility ID:	9805562
Facility Type:	ER
DER Facility ID:	251293
Site ID:	311469
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	1998-08-04
Investigator:	VXBREVDO
Referred To:	Not reported

COOPER RECYCLING; LLC. (Continued) **S103517663**

Reported to Dept:	1998-08-04
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1998-08-04
Spill Record Last Update:	2012-09-25
Spiller Name:	K RADHAKRISHNAN
Spiller Company:	WASTE MANAGMENT OF NY
Spiller Address:	123 VARICK AVE
Spiller Company:	001
Contact Name:	KARTHIK RADHAKRISHNAN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN 06/16/06: This spill is transferred from Mike Mulqueen to Mr. Koon Tang. 09/25/2012 - This is tank failure. Accoring to spill report spilled product was contained and all recovered. No data or information exists to indicate soil or groundwater contamiantion. Facility is covered with asphalt and/or buildings. No threat of exposure exists. Spill case can be closed. Closed effective September 25, 2012. V. Brevdo"
Remarks:	"TANK FAILURE AT ABOVE LOCATION. MATERIAL CONTAINED AND ALL RECOVERED. NO CALL BACK REQUESTED."

All Materials:

Site ID:	311469
Operable Unit ID:	1066749
Operable Unit:	01
Material ID:	320302
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

NY Financial Assurance 1:

Name:	COOPER RECYCLING; LLC.
Address:	123 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY
Owner Name:	Adrienne Cooper
Region:	2
Estimate Type:	Closure
Estimate Amount:	423,000
Estimate Date:	03/01/2001
Mechanism:	Surety bond - Performance
Mechanism Amount:	520,000
Issue Date:	03/10/2014
Activity Number:	24CP0089

COOPER RECYCLING; LLC. (Continued) **S103517663**

Activity Description: CDDHRF - permit

NY MANIFEST:

Name:	ALLIED SANITATION
Address:	123 VARICK AVE
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP000889022
Facility Status:	Not reported
Location Address 1:	123 VARICK AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000889022
Mailing Name:	ALLIED SANITATION
Mailing Contact:	ANTHONY CUCINOTTA
Mailing Address 1:	123 VARICK AVENUE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7187794650

SPDES:

Name:	VARICK II
Address:	123 VARICK AVE
City,State,Zip:	BROOKLYN, NY 11237
Permit Number:	NY0201260
State-Region:	02
Expiration Date:	07/31/2011
Current Major Minor Status:	Minor
Primary Facility SIC Code:	4953
State Water Body Name:	ENGLISH KILLS
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	DMR
Lat/Long:	40.709722 / -73.930556
DMR Cognizant Official:	JAY KAPLAN, ENVIR MGR
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	WASTE MANAGEMENT OF NY, LLC
Non-Gov Permit Street Address:	VARICK II
Non-Gov Permit Supplemental Location:	123 VARICK AVE

COOPER RECYCLING; LLC. (Continued) **S103517663**

Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11237
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	WASTE MANAGEMENT OF NY, LLC
Non-Gov Facility Street Address:	VARICK II
Non-Gov Facility Supplemental Location:	123 VARICK AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11237
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	VARICK II
Address:	123 VARICK AVE
City,State,Zip:	BROOKLYN, NY 11237
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	WASTE MANAGEMENT OF NY, LLC
Non-Gov Permit Street Address:	VARICK II
Non-Gov Permit Supplemental Location:	123 VARICK AVE
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11237
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	WASTE MANAGEMENT OF NY, LLC
Non-Gov Facility Street Address:	VARICK II
Non-Gov Facility Supplemental Location:	123 VARICK AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11237
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	VARICK II
Address:	123 VARICK AVE
City,State,Zip:	BROOKLYN, NY 11237
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047

COOPER RECYCLING; LLC. (Continued) **S103517663**

Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	WASTE MGMT OF NY LLC
Non-Gov Permit Street Address:	123 VARICK AVE
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11237
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	WASTE MANAGEMENT OF NY, LLC
Non-Gov Facility Street Address:	VARICK II
Non-Gov Facility Supplemental Location:	123 VARICK AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11237
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	VARICK II
Address:	123 VARICK AVE
City,State,Zip:	BROOKLYN, NY 11237
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	WASTE MGMT OF NY LLC
Non-Gov Permit Street Address:	123 VARICK AVE
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11237
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	WASTE MANAGEMENT OF NY, LLC
Non-Gov Facility Street Address:	VARICK II
Non-Gov Facility Supplemental Location:	123 VARICK AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11237
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

M117 **WASTE MANAGEMENT OF NEW YORK LLC** **RCRA-SQG** **1000248669**
South **123 VARICK AVE** **US AIRS** **NYD982744815**
1/8-1/4 **BROOKLYN, NY 11237** **PA MANIFEST**
0.146 mi. **NY MANIFEST**
771 ft. **Site 5 of 13 in cluster M** **NJ MANIFEST**

Relative: **Lower**
Actual: **11 ft.**

RCRA-SQG:

Date Form Received by Agency:	20070101
Handler Name:	WASTE MANAGEMENT OF NEW YORK LLC
Handler Address:	123 VARICK AVE
Handler City,State,Zip:	BROOKLYN, NY 11237
EPA ID:	NYD982744815
Contact Name:	JAY KAPLAN
Contact Address:	VARICK AVE
Contact City,State,Zip:	BROOKLYN, NY 11237
Contact Telephone:	718-533-5310
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	VARICK AVE
Mailing City,State,Zip:	BROOKLYN, NY 11237
Owner Name:	WASTE MANAGEMENT OF NEW YORK LLC
Owner Type:	Private
Operator Name:	WASTE MANAGEMENT OF NEW YORK LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

WASTE MANAGEMENT OF NEW YORK LLC (Continued) **1000248669**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D005
Waste Description:	BARIUM
Waste Code:	D006
Waste Description:	CADMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D027
Waste Description:	1,4-DICHLOROBENZENE

WASTE MANAGEMENT OF NEW YORK LLC (Continued) **1000248669**

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Waste Code: D040
Waste Description: TRICHLORETHYLENE

Waste Code: NONE
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: WASTE MGMT
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 123 VARICK AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: 718-386-7900
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WASTE MANAGEMENT OF NEW YORK LLC
Legal Status: Private
Date Became Current: 19801231
Date Ended Current: Not reported
Owner/Operator Address: 123 VARICK AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: 718-533-5310
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WASTE MGMT
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 123 VARICK AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: 718-386-7900
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WASTE MANAGEMENT OF NEW YORK LLC
Legal Status: Private
Date Became Current: 19801231
Date Ended Current: Not reported
Owner/Operator Address: 123 VARICK AVE
Owner/Operator City,State,Zip: BROOKLYN, NY 11237
Owner/Operator Telephone: 718-533-5310
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

WASTE MANAGEMENT OF NEW YORK LLC (Continued) **1000248669**

Owner/Operator Indicator:	Operator
Owner/Operator Name:	WASTE MANAGEMENT OF NEW YORK LLC
Legal Status:	Private
Date Became Current:	19801231
Date Ended Current:	Not reported
Owner/Operator Address:	123 VARICK AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11237
Owner/Operator Telephone:	718-533-5310
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WASTE MANAGEMENT OF NEW YORK LLC
Legal Status:	Private
Date Became Current:	19801231
Date Ended Current:	Not reported
Owner/Operator Address:	123 VARICK AVE
Owner/Operator City,State,Zip:	BROOKLYN, NY 11237
Owner/Operator Telephone:	718-533-5310
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19950502
Handler Name:	STAR RECYCLING - WASTE MGMT
Federal Waste Generator Description:	Not reported
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20020521
Handler Name:	STAR RECYCLING - WASTE MGMT
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	WASTE MANAGEMENT OF NEW YORK LLC
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

WASTE MANAGEMENT OF NEW YORK LLC (Continued) **1000248669**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: WASTE MANAGEMENT OF NEW YORK LLC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980318
Handler Name: STAR RECYCLING - WASTE MGMT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20031112
Handler Name: WASTE MANAGEMENT OF NEW YORK LLC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

WASTE MANAGEMENT OF NEW YORK LLC (Continued) **1000248669**

US AIRS MINOR:
Envid: 1000248669
Region Code: 02
Programmatic ID: AIR NY0000002610400013
Facility Registry ID: 110004433104
D and B Number: Not reported
Primary SIC Code: 4953
NAICS Code: 999999
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002610400013
Facility Registry ID: 110004433104
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-03-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400013
Facility Registry ID: 110004433104
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-08-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Manifest Details:
Year: 2006
Manifest Number: PAH132852
Manifest Type: TSD Copy
Generator EPA Id: NYD982744815
Generator Date: 05/10/2006
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE
TSD Facility City: LEWISBERRY
TSD Facility State: PA
Facility Telephone: 718-533-5310
Page Number: 1

WASTE MANAGEMENT OF NEW YORK LLC (Continued) **1000248669**

Line Number: 2
Waste Number: D002
Container Number: 3
Container Type: Fiberboard or plastic drums, barrels, kegs
Waste Quantity: 15
Unit: Gallons (liquids only)
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2006
Manifest Number: PAH132852
Manifest Type: TSD Copy
Generator EPA Id: NYD982744815
Generator Date: 05/10/2006
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE
TSD Facility City: LEWISBERRY
TSD Facility State: PA
Facility Telephone: 718-533-5310
Page Number: 1
Line Number: 1
Waste Number: D001
Container Number: 1
Container Type: Metal drums, barrels, kegs
Waste Quantity: 400
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

NY MANIFEST:
Name: ALLIED SANITATION CORP
Address: 123 VARICK AVE
City,State,Zip: BROOKLYN, NY 11237
Country: USA
EPA ID: NYD982744815
Facility Status: Not reported
Location Address 1: 123 VARICK AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11237
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD982744815
Mailing Name: ALLIED SANITATION CORP
Mailing Contact: TONY CUCINOTTA

WASTE MANAGEMENT OF NEW YORK LLC (Continued) **1000248669**

Mailing Address 1:	123 VARICK AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183867900

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYR000080549
Trans2 State ID:	NJD982792384
Generator Ship Date:	11/13/2006
Trans1 Recv Date:	11/13/2006
Trans2 Recv Date:	11/13/2006
TSD Site Recv Date:	11/14/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982744815
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	000186410JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

WASTE MANAGEMENT OF NEW YORK LLC (Continued) **1000248669**

NJ MANIFEST:

EPA Id:	NYD982744815
Mail Address:	123 VARICK AVENUE
Mail City/State/Zip:	BROOKLYN 11237
Facility Phone:	7185335310
Emergency Phone:	Not reported
Contact:	JAY KAPLAN
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5210625
EPA ID:	NYD982744815
Date Shipped:	01/06/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYR000080549
Transporter 2 EPA ID:	NJD986607380
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/06/2005
Date Trans2 Transported Waste:	01/07/2005
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/07/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	04250522

WASTE MANAGEMENT OF NEW YORK LLC (Continued) **1000248669**

Was Load Rejected:	BROOKLYN 11237
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5287893
EPA ID:	NYD982744815
Date Shipped:	08/15/2006
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJD982792384
Transporter 2 EPA ID:	NJD982792384
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/15/2006
Date Trans2 Transported Waste:	08/21/2006
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/21/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	10020625
Was Load Rejected:	BROOKLYN 11237
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5214113
EPA ID:	NYD982744815
Date Shipped:	07/22/2005
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYR000080549
Transporter 2 EPA ID:	NJD980525786
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported

WASTE MANAGEMENT OF NEW YORK LLC (Continued) **1000248669**

Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/22/2005
Date Trans2 Transported Waste:	08/03/2005
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/03/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	12050521
Was Load Rejected:	BROOKLYN 11237
Reason Load Was Rejected:	Not reported

M118 **WASTE MANAGEMENT OF NEW YORK, LLC** **NY AST** **U003396750**
South **123 VARICK AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.146 mi.
771 ft. **Site 6 of 13 in cluster M**

Relative:
Lower

Actual:
11 ft.

AST:

Name:	WASTE MANAGEMENT OF NEW YORK, LLC
Address:	123 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-602618
Program Type:	PBS
UTM X:	590540.20583
UTM Y:	4507108.82098
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	24575
Affiliation Type:	Facility Owner
Company Name:	WASTE MANAGEMENT OF NEW YORK, LLC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	123 VARICK AVENUE
Address2:	Not reported

WASTE MANAGEMENT OF NEW YORK, LLC (Continued) **U003396750**

City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 533-5310
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-07-22

Site Id:	24575
Affiliation Type:	Mail Contact
Company Name:	WASTE MANAGEMENT OF NEW YORK, LLC.
Contact Type:	ENVIRONMENTAL MANAGER
Contact Name:	JAY KAPLAN
Address1:	123 VARICK AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 533-5310
EMail:	JKAPLAN2@HOTMAIL.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-09-29

Site Id:	24575
Affiliation Type:	Facility Operator
Company Name:	WASTE MANAGEMENT OF NEW YORK, LLC
Contact Type:	Not reported
Contact Name:	RAYMOND HUBLALL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 533-5367
EMail:	Not reported
Fax Number:	Not reported
Modified By:	EXROSSAN
Date Last Modified:	2005-03-28

Site Id:	24575
Affiliation Type:	Emergency Contact
Company Name:	WASTE MANAGEMENT OF NEW YORK, LLC.
Contact Type:	Not reported
Contact Name:	JAY KAPLAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 533-5310
EMail:	Not reported

WASTE MANAGEMENT OF NEW YORK, LLC (Continued) **U003396750**

Fax Number:	Not reported
Modified By:	EXROSSAN
Date Last Modified:	2005-03-28

Tank Info:

Tank Number:	001
Tank Id:	50733
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

	G00 - Tank Secondary Containment - None
	D00 - Pipe Type - No Piping
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	F00 - Pipe External Protection - None
	C00 - Pipe Location - No Piping
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1997
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/01/1997
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	other

Tank Number:	002
Tank Id:	50734
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:

	J02 - Dispenser - Suction Dispenser
	G00 - Tank Secondary Containment - None
	C01 - Pipe Location - Aboveground
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D99 - Pipe Type - Other
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed

WASTE MANAGEMENT OF NEW YORK, LLC (Continued) **U003396750**

Pipe Model:	Not reported
Install Date:	11/01/1997
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/01/1997
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	other

Tank Number:	003
Tank Id:	50735
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1990
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/28/2014
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	004
Tank Id:	50736
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

J00 - Dispenser - None
I04 - Overfill - Product Level Gauge (A/G)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

WASTE MANAGEMENT OF NEW YORK, LLC (Continued) **U003396750**

D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1990
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/28/2014
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	005
Tank Id:	50737
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/01/1990
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	01/01/1990
Register:	True
Modified By:	TRANSLAT
Last Modified:	04/14/2017
Material Name:	diesel

WASTE MANAGEMENT OF NEW YORK, LLC (Continued) **U003396750**

Tank Number: 006
Tank Id: 50738
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

J00 - Dispenser - None
I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
E00 - Piping Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 01/01/1990
Capacity Gallons: 1100
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 07/28/2009
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: waste oil/used oil

Tank Number: 007
Tank Id: 53500
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L09 - Piping Leak Detection - Exempt Suction Piping
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron

WASTE MANAGEMENT OF NEW YORK, LLC (Continued) **U003396750**

Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1997
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/28/2014
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	lube oil

Tank Number:	008
Tank Id:	53501
Material Code:	0010
Common Name of Substance:	Hydraulic Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1997
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/28/2014
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	hydraulic oil

Tank Number:	009
Tank Id:	54991
Material Code:	0010
Common Name of Substance:	Hydraulic Oil

Equipment Records:

J02 - Dispenser - Suction Dispenser

WASTE MANAGEMENT OF NEW YORK, LLC (Continued) **U003396750**

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1990
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/28/2014
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	hydraulic oil

P119 **MIONE TRANSIT MIX** **RCRA NonGen / NLR** **1000311791**
ENE **1301 METROPOLITAN AVE** **FINDS** **NYD157709486**
1/8-1/4 **BROOKLYN, NY 11237** **ECHO**
0.149 mi.
788 ft. **Site 1 of 4 in cluster P**

Relative: **Lower**
Actual: **10 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	MIONE TRANSIT MIX	
Handler Address:		1301 METROPOLITAN AVE
Handler City,State,Zip:		BROOKLYN, NY 11237-1102
EPA ID:		NYD157709486
Contact Name:		Not reported
Contact Address:		METROPOLITAN AVE
Contact City,State,Zip:		BROOKLYN, NY 11237
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		METROPOLITAN AVE
Mailing City,State,Zip:		BROOKLYN, NY 11237
Owner Name:		UNKNOWN

MIONE TRANSIT MIX (Continued) **1000311791**

Owner Type:	Private
Operator Name:	UNKNOWN
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

MIONE TRANSIT MIX (Continued) **1000311791**

Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	UNKNOWN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	UNKNOWN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	UNKNOWN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: MIONE TRANSIT MIX	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

MIONE TRANSIT MIX (Continued) **1000311791**

Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MIONE TRANSIT MIX
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MIONE TRANSIT MIX
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19890705
Handler Name: MIONE TRANSIT MIX
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110009470018

MIONE TRANSIT MIX (Continued) **1000311791**

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000311791
Registry ID:	110009470018
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009470018
Name:	MIONE TRANSIT MIX
Address:	1301 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY 11237

P120 **WASTE MANAGEMENT OF NY; INC. (REG** **NY SWF/LF** **S105841926**
ENE **1301 METROPOLITAN AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.149 mi.
788 ft. **Site 2 of 4 in cluster P**

Relative: **Lower**
Actual: **10 ft.**

SWF/LF:

Name:	WASTE MANAGEMENT OF NY; INC. (REG
Address:	1301 METROPOLITAN AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	7185335308
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	TARA HEMMER
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[24WD4]
Active:	No
East Coordinate:	590841
North Coordinate:	4507554
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported

WASTE MANAGEMENT OF NY; INC. (REG (Continued) **S105841926**

Operator Name: Not reported
Operator Type: Not reported
Laste Date: Not reported

P121 **1301 METROPOLITAN AVE.** **NY UST** **U004277390**
ENE **1301 METROPOLITAN AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.149 mi.
788 ft. **Site 3 of 4 in cluster P**

Relative:
Lower

Actual:
10 ft.

UST:
Name: 1301 METROPOLITAN AVE.
Address: 1301 METROPOLITAN AVE
City,State,Zip: BROOKLYN, NY 11237
Id/Status: 2-612853 / Unregistered
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: Not reported
UTM Y: Not reported
Site Type: Other

Affiliation Records:
Site Id: 566793
Affiliation Type: Facility Owner
Company Name: PEABODY WEBSTER HOLDINGS LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 4106 GLENWOOD ROAD
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11210
Country Code: 001
Phone: (718) 859-6500
EMail: Not reported
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2018-02-13

Site Id: 566793
Affiliation Type: Mail Contact
Company Name: Not reported
Contact Type: Not reported
Contact Name: CONSTANCE CINCOTTA
Address1: 4106 GLENWOOD ROAD
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11210
Country Code: 001
Phone: (718) 859-6500
EMail: LAURA@GLENWOODMASON.COM
Fax Number: Not reported
Modified By: MRBARROW
Date Last Modified: 2018-02-13

1301 METROPOLITAN AVE. (Continued) **U004277390**

Site Id:	566793
Affiliation Type:	Emergency Contact
Company Name:	PEABODY WEBSTER HOLDINGS LLC
Contact Type:	Not reported
Contact Name:	CONSTANCE CINCOTTA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 859-6500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2018-02-13

Tank Info:

Tank Number:	1A
Tank ID:	275034
Tank Status:	Unregistered
Material Name:	Unregistered
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass reinforced plastic [FRP]
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MRBARROW
Last Modified:	02/13/2018

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number:	1B
Tank ID:	275035
Tank Status:	Unregistered
Material Name:	Unregistered
Capacity Gallons:	550
Install Date:	Not reported

1301 METROPOLITAN AVE. (Continued) **U004277390**

Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 02/13/2018

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Number: 1C
Tank ID: 275036
Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 02/13/2018

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
G02 - Tank Secondary Containment - Vault (w/access)

1301 METROPOLITAN AVE. (Continued) **U004277390**

Tank Number: 1D
Tank ID: 275037
Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 02/13/2018

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None

Tank Number: 1E
Tank ID: 275038
Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 02/13/2018

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None

1301 METROPOLITAN AVE. (Continued) **U004277390**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J00 - Dispenser - None

Tank Number: 1F
Tank ID: 275039
Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 02/13/2018

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)

Tank Number: 1G
Tank ID: 275040
Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 02/13/2018

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
J00 - Dispenser - None

1301 METROPOLITAN AVE. (Continued) **U004277390**

H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Number: 1H
Tank ID: 275041
Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 02/13/2018

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number: 1I
Tank ID: 275042
Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported

1301 METROPOLITAN AVE. (Continued) **U004277390**

Modified By: MRBARROW
Last Modified: 02/13/2018

Equipment Records:

J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)

Tank Number: 1J
Tank ID: 275043
Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 02/13/2018

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None

Tank Number: 1K
Tank ID: 275044
Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True

1301 METROPOLITAN AVE. (Continued) **U004277390**

Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 02/13/2018

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
J00 - Dispenser - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None

Tank Number: 1L
Tank ID: 275045
Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 02/13/2018

Equipment Records:

J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G02 - Tank Secondary Containment - Vault (w/access)

Tank Number: 1M
Tank ID: 275046

1301 METROPOLITAN AVE. (Continued) **U004277390**

Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 02/13/2018

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Number: 1N
Tank ID: 275047
Tank Status: Unregistered
Material Name: Unregistered
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass reinforced plastic [FRP]
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MRBARROW
Last Modified: 02/13/2018

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
J00 - Dispenser - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

1301 METROPOLITAN AVE. (Continued) **U004277390**

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None

122
NW
1/8-1/4
0.150 mi.
794 ft.

Relative:
Lower

Actual:
-1 ft.

NEWTOWN CREEK SUPERFUND SITE
NEWTOWN CRK - N LAT 40.715192
NEW YORK, NY 99999

NPL **1011845384**
SEMS **NYN000206282**
RCRA-SQG
ROD
PRP
NY MANIFEST

NPL:

EPA Region:	2
EPA ID:	NYN000206282
Site ID:	206282
Name:	NEWTOWN CREEK
Address:	SOUTH END OF IVY HILL ROAD
City,State,Zip:	BROOKLYN, QUEENS, NY 11222
Federal:	N
Final Date:	2010-09-29 00:00:00
Latitude:	40.715192
Longitude:	-73.930762
Site Score:	50
NAI:	Not reported
Native American Entity:	Not reported

SEMS:

Site ID:	0206282
EPA ID:	NYN000206282
Name:	NEWTOWN CREEK
Address:	SOUTH END OF IVY HILL ROAD
Address 2:	Not reported
City,State,Zip:	BROOKLYN, QUEENS, NY 11222
Cong District:	12
FIPS Code:	Not reported
Latitude:	+40.715192
Longitude:	-073.930762
FF:	N
NPL:	Currently on the Final NPL
Non NPL Status:	Not reported

SEMS Detail:

Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	2008-08-15 05:00:00
Finish Date:	8/15/2008 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region: 02

NEWTOWN CREEK SUPERFUND SITE (Continued) **1011845384**

Site ID: 0206282
EPA ID: NYN000206282
Site Name: NEWTOWN CREEK
NPL: F
FF: N
OU: 00
Action Code: NP
Action Name: PROPOSED
SEQ: 1
Start Date: 2009-09-23 04:00:00
Finish Date: 9/23/2009 4:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0206282
EPA ID: NYN000206282
Site Name: NEWTOWN CREEK
NPL: F
FF: N
OU: 00
Action Code: HR
Action Name: HAZRANK
SEQ: 1
Start Date: 2009-06-01 05:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0206282
EPA ID: NYN000206282
Site Name: NEWTOWN CREEK
NPL: F
FF: N
OU: 01
Action Code: CO
Action Name: RI/FS
SEQ: 1
Start Date: 2010-02-05 05:00:00
Finish Date: 7/7/2011 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0206282
EPA ID: NYN000206282
Site Name: NEWTOWN CREEK
NPL: F
FF: N
OU: 00
Action Code: NF
Action Name: NPL FINL
SEQ: 1
Start Date: 2010-09-29 04:00:00
Finish Date: 9/29/2010 4:00:00 AM
Qual: Not reported

NEWTOWN CREEK SUPERFUND SITE (Continued) **1011845384**

Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	01
Action Code:	TA
Action Name:	TECH ASSIST
SEQ:	1
Start Date:	2014-09-11 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	01
Action Code:	TA
Action Name:	TECH ASSIST
SEQ:	2
Start Date:	2014-10-31 04:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	02
Action Code:	RO
Action Name:	ROD
SEQ:	3
Start Date:	2021-04-12 04:00:00
Finish Date:	4/12/2021 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	01
Action Code:	BD
Action Name:	PRP RI/FS
SEQ:	1

NEWTOWN CREEK SUPERFUND SITE (Continued) **1011845384**

Start Date:	2011-07-07 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	02
Action Code:	NK
Action Name:	PRP FS
SEQ:	1
Start Date:	2018-12-20 06:00:00
Finish Date:	4/12/2021 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Ovrsght

RCRA-SQG:

Date Form Received by Agency:	20120321
Handler Name:	NEWTOWN CREEK SUPERFUND SITE
Handler Address:	NEWTOWN CRK - N LAT 40.715192
Handler City,State,Zip:	NEW YORK, NY 99999
EPA ID:	NYN000206282
Contact Name:	JIM QUADRINI
Contact Address:	W GRAND AVE STE 300
Contact City,State,Zip:	MONTVALE, NJ 07645-1813
Contact Telephone:	201-930-9890 1012
Contact Fax:	201-930-9805
Contact Email:	JQUADRINI@ANCHORQEA.COM
Contact Title:	PARTNER ANCHOR QEA
EPA Region:	02
Land Type:	Other
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	W GRAND AVE STE 300
Mailing City,State,Zip:	MONTVALE, NJ 07645-1813
Owner Name:	CAROLINE KWAN-US EPA
Owner Type:	Private
Operator Name:	DAY PITNEY LLP
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No

NEWTOWN CREEK SUPERFUND SITE (Continued) **1011845384**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D004
Waste Description:	ARSENIC
Waste Code:	D006
Waste Description:	CADMIUM
Waste Code:	D007

NEWTOWN CREEK SUPERFUND SITE (Continued) **1011845384**

Waste Description: CHROMIUM

Waste Code: D008
Waste Description: LEAD

Waste Code: D009
Waste Description: MERCURY

Waste Code: D010
Waste Description: SELENIUM

Waste Code: D015
Waste Description: TOXAPHENE (C10 H10 CL8, TECHNICAL CHLORINATED CAMPHENE, 67-69 PERCENT CHLORINE)

Waste Code: D020
Waste Description: CHLORDANE

Waste Code: D031
Waste Description: HEPTACHLOR (AND ITS EPOXIDE)

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CAROLINE KWAN-US EPA
Legal Status:	Private
Date Became Current:	19800101
Date Ended Current:	Not reported
Owner/Operator Address:	290 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10007
Owner/Operator Telephone:	212-637-4275
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	DAY PITNEY LLP
Legal Status:	Private
Date Became Current:	20120416
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20120321
Handler Name:	NEWTOWN CREEK SUPERFUND SITE
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

NEWTOWN CREEK SUPERFUND SITE (Continued) **1011845384**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 54162
NAICS Description: ENVIRONMENTAL CONSULTING SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ROD:
No Details: No Details

PRP:
PRP Name:
APOLLO PETROLEUM TRANSPORT LLC
APOLLO PIPELINE LLC
APOLLO TRANSPORT INC
BP AMERICA HEADQUARTERS
BP AMERICA HEADQUARTERS
BP AMERICA HEADQUARTERS
BROOKLYN UNION GAS
BROOKLYN UNION GAS
BROOKLYN UNION GAS
EXXONMOBIL CORPORATION
EXXONMOBIL CORPORATION
EXXONMOBIL CORPORATION
GETTY PETROLEUM MARKETING INC
GETTY TERMINALS CORP
KINGS LAND REALTY INC
METRO BIOFUELS LLC
METRO ENERGY GROUP LLC
METRO FUEL OIL CO.
METRO PLUMBING SERVICES CORP
METRO TERMINALS CORP

Click this hyperlink while viewing on your computer to access
9 additional PRP: record(s) in the EDR Site Report.

NY MANIFEST:
Name: NEWTOWN CREEK SUPERFUND SITE
Address: NEWTOWN CRK - N LAT 40.715192
City,State,Zip: NEW YORK, NY 99999
Country: USA
EPA ID: NYN000206282
Facility Status: Not reported
Location Address 1: - VERNON BLVD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: LONG ISLAND CITY
Location State: NY

NEWTOWN CREEK SUPERFUND SITE (Continued) **1011845384**

Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYN000206282
Mailing Name:	NEWTOWN CREEK SUPERFUND SITE
Mailing Contact:	C/O ANCHOR QEA LLC
Mailing Address 1:	TICE BLVD - SUITE
Mailing Address 2:	Not reported
Mailing City:	WO0ODCLIFF LAKE
Mailing State:	NJ
Mailing Zip:	07677
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2015710912

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	CTD021816889
Trans2 State ID:	Not reported
Generator Ship Date:	10/31/2014
Trans1 Recv Date:	10/31/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYN000206282
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD021816889
TSDF ID 2:	Not reported
Manifest Tracking Number:	013301186JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	55
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.

NEWTOWN CREEK SUPERFUND SITE (Continued) **1011845384**

Specific Gravity:	1
Waste Code:	F003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O123 **NYCDOT - METROPOLITAN AVENUE BASCULE BRIDGE** **RCRA-LQG** **1000791719**
WNW **1109 METROPOLITAN AVE** **FINDS** **NYD987032364**
1/8-1/4 **BROOKLYN, NY 11211** **ECHO**
0.151 mi. **NY MANIFEST**
799 ft. **Site 5 of 6 in cluster O** **NJ MANIFEST**

Relative: **Higher**
Actual: **16 ft.**

RCRA-LQG:

Date Form Received by Agency:	20160121
Handler Name:	NYCDOT - METROPOLITAN AVENUE BASCULE BRIDGE
Handler Address:	1109 METROPOLITAN AVE
Handler City,State,Zip:	BROOKLYN, NY 11211
EPA ID:	NYD987032364
Contact Name:	JOHN KURRE
Contact Address:	WATER ST 5TH FL
Contact City,State,Zip:	NEW YORK, NY 10041
Contact Telephone:	212-839-4019
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	VARICK AVE
Mailing City,State,Zip:	BROOKLYN, NY 11237
Owner Name:	NYCDOT
Owner Type:	State
Operator Name:	NYCDOT BRIDGES
Operator Type:	State
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported

NYCDOT - METROPOLITAN AVENUE BASCULE BRIDGE (Continued) **1000791719**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190315
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYCDOT
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2 RECTOR ST 4TH FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10006
Owner/Operator Telephone:	212-788-1721
Owner/Operator Telephone Ext:	Not reported

NYCDOT - METROPOLITAN AVENUE BASCULE BRIDGE (Continued) **1000791719**

Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYCDOT
Legal Status:	State
Date Became Current:	19610215
Date Ended Current:	Not reported
Owner/Operator Address:	55 WATER ST 5TH FL
Owner/Operator City,State,Zip:	NEW YORK, NY 10041
Owner/Operator Telephone:	212-839-4019
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	NYCDOT BRIDGES
Legal Status:	State
Date Became Current:	19621011
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYCDOT
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2 RECTOR ST 4TH FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10006
Owner/Operator Telephone:	212-788-1721
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	NYCDOT
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2 RECTOR ST 4TH FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10006
Owner/Operator Telephone:	212-788-1721
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	NYCDOT METROPOLITAN AVE BRG #2240290
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

NYCDOT - METROPOLITAN AVENUE BASCULE BRIDGE (Continued) **1000791719**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYCDOT METROPOLITAN AVE BRG #2240290
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19930413
Handler Name: NYCDOT METROPOLITAN AVE BRG #2240290
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20160121
Handler Name: NYCDOT - METROPOLITAN AVENUE BASCULE BRIDGE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 238320
NAICS Description: PAINTING AND WALL COVERING CONTRACTORS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NYCDOT - METROPOLITAN AVENUE BASCULE BRIDGE (Continued) **1000791719**

FINDS:
Registry ID: 110008085623

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000791719
Registry ID:	110008085623
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110008085623
Name:	NYCDOT - METROPOLITAN AVENUE BASCULE BRIDGE
Address:	1109 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY 11211

NY MANIFEST:

Name:	NYCDOT
Address:	METROPOLITAN AVE BRG OVER
City,State,Zip:	BROOKLYN, NY 11211
Country:	USA
EPA ID:	NYD987032364
Facility Status:	Not reported
Location Address 1:	METROPOLITAN -GRAND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10006
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987032364
Mailing Name:	NYCDOT
Mailing Contact:	JOHN KIRINCIC
Mailing Address 1:	2 RECTOR ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10006
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7189639213

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported

NYCDOT - METROPOLITAN AVENUE BASCULE BRIDGE (Continued) **1000791719**

Year:	2018
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2015
Trans1 Recv Date:	10/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987032364
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	008915181FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D008
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYD987032364
Mail Address:	2 RECTOR STREET
Mail City/State/Zip:	NEW YORK 10006
Facility Phone:	2127882083
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00

NYCDOT - METROPOLITAN AVENUE BASCULE BRIDGE (Continued) **1000791719**

Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5104662
EPA ID:	NYD987032364
Date Shipped:	04/30/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/30/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/05/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05250422
Was Load Rejected:	NEW YORK 10006
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5104699
EPA ID:	NYD987032364
Date Shipped:	05/10/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

NYCDOT - METROPOLITAN AVENUE BASCULE BRIDGE (Continued) **1000791719**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/10/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/10/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05270422
Was Load Rejected:	NEW YORK 10006
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5025311
EPA ID:	NYD987032364
Date Shipped:	08/09/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/09/2004
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/09/2004

NYCDOT - METROPOLITAN AVENUE BASCULE BRIDGE (Continued) **1000791719**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08310421
Was Load Rejected:	NEW YORK 10006
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5227102
EPA ID:	NYD987032364
Date Shipped:	05/13/2005
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/13/2005
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/13/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06200522
Was Load Rejected:	NEW YORK 10006
Reason Load Was Rejected:	Not reported

NYCDOT - METROPOLITAN AVENUE BASCULE BRIDGE (Continued) **1000791719**

Manifest Number:	NJA5083136
EPA ID:	NYD987032364
Date Shipped:	02/23/2006
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NYD046765574
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/23/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/23/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	04130621
Was Load Rejected:	NEW YORK 10006
Reason Load Was Rejected:	Not reported

M124 **CON EDISON** **RCRA NonGen / NLR** **1018279295**
South **VARICK AND MESEROLE ST VAULT 3** **FINDS** **NYP004741005**
1/8-1/4 **BROOKLYN, NY 11237** **ECHO**
0.152 mi.
801 ft. **Site 7 of 13 in cluster M**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150302
Handler Name:	CON EDISON	
Handler Address:		VARICK AND MESEROLE ST VAULT 3
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYP004741005
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported

CON EDISON (Continued) **1018279295**

Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1018279295**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20150302
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20150302
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - VAULT 3570

CON EDISON (Continued) **1018279295**

Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150302
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150302
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067688657

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

CON EDISON (Continued) **1018279295**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018279295
Registry ID:	110067688657
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067688657
Name:	CON EDISON
Address:	VARICK AND MESEROLE ST VAULT 3
City,State,Zip:	BROOKLYN, NY 11237

N125 **CON EDISON** **NY MANIFEST** **S118259873**
NNE **GARDNER AVE & GRAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.154 mi.
815 ft. **Site 4 of 6 in cluster N**

Relative: **Lower**

Actual: **8 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	GARDNER AVE & GRAND ST
City,State,Zip:	BROOKLYN, NY 11233
Country:	USA
EPA ID:	NYP004839324
Facility Status:	Not reported
Location Address 1:	GARDNER AVE & GRAND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11233
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004839324
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047

CON EDISON (Continued) **S118259873**

Trans2 State ID:	Not reported
Generator Ship Date:	09/16/2015
Trans1 Recv Date:	09/16/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/17/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004839324
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002625158GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N126 **CON EDISON** **NJ MANIFEST** **S120676764**
NNE **GARDNER AVE & GRAND ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11233**
0.154 mi.
815 ft. **Site 5 of 6 in cluster N**

Relative: NJ MANIFEST:
Lower

EPA Id:	NYP004839324
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported

Actual:
8 ft.

CON EDISON (Continued) **S120676764**

SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002625158GBF
EPA ID:	NYP004839324
Date Shipped:	9/16/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

N127 **CON EDISON** **RCRA NonGen / NLR** **1019325582**
NNE **GARDNER AVE & GRAND ST** **NYP004839324**
1/8-1/4 **BROOKLYN, NY 11233**
0.154 mi.
815 ft. **Site 6 of 6 in cluster N**

Relative: **Lower**
Actual: **8 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150916
Handler Name:	CON EDISON	
Handler Address:		GARDNER AVE & GRAND ST
Handler City,State,Zip:		BROOKLYN, NY 11233
EPA ID:		NYP004839324
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1019325582**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20150916
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private

CON EDISON (Continued) **1019325582**

Date Became Current: 20150916
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - VAULT 4535
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150916
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150916
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

CON EDISON (Continued) **1019325582**

Evaluation Action Summary:
Evaluations: No Evaluations Found

M128 **CON EDISON** **NJ MANIFEST** **S120671513**
South **W SIDE VARICK ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.155 mi.
816 ft. **Site 8 of 13 in cluster M**

Relative: **Lower**

Actual: **11 ft.**

NJ MANIFEST:

EPA Id:	NYP004779625
Mail Address:	IRVING PL15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014454086JJK
EPA ID:	NYP004779625
Date Shipped:	5/6/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

CON EDISON (Continued) **S120671513**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

M129 **CON EDISON** **NY MANIFEST** **S121967313**
South **W SIDE VARICK ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.155 mi.
816 ft. **Site 9 of 13 in cluster M**

Relative: **Lower**

Actual: **11 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	W SIDE VARICK ST
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP004779625
Facility Status:	Not reported
Location Address 1:	W SIDE VARICK ST & MESEROLE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004779625
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/2015
Trans1 Recv Date:	05/06/2015

CON EDISON (Continued) **S121967313**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/11/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004779625
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454086JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	4000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

M130 **CON EDISON** **NJ MANIFEST** **S120668124**
South **VARICK & MESEROLE ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.155 mi.
816 ft. **Site 10 of 13 in cluster M**

Relative: NJ MANIFEST:
Lower

Actual: EPA Id:	NYP004741039
11 ft. Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY047
Municipal:	Not reported

CON EDISON (Continued) **S120668124**

Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014087302JJK
EPA ID:	NYP004741039
Date Shipped:	3/2/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

EPA Id:	NYP004741005
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THERESA BURKARD
Comments:	Not reported

CON EDISON (Continued) **S120668124**

SIC Code:	Not reported
County:	NY047
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014087300JJK
EPA ID:	NYP004741005
Date Shipped:	3/2/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

M131 **CON EDISON** **NY MANIFEST** **S118256554**
South **VARICK ST & MESEROLE ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.155 mi.
816 ft. **Site 11 of 13 in cluster M**

Relative:
Lower

Actual:
11 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	VARICK ST & MESEROLE ST
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP004779476
Facility Status:	Not reported
Location Address 1:	VARICK ST & MESEROLE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004779476
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/2015
Trans1 Recv Date:	05/06/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/11/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004779476
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454085JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S118256554**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	9000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

M132 **CON EDISON** **RCRA NonGen / NLR** **1019324937**
South **VARICK ST & MESEROLE ST** **FINDS** **NYP004779476**
1/8-1/4 **BROOKLYN, NY 11237** **ECHO**
0.155 mi.
816 ft. **Site 12 of 13 in cluster M**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150506
Handler Name:	CON EDISON	
Handler Address:		VARICK ST & MESEROLE ST
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYP004779476
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported

CON EDISON (Continued) **1019324937**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

CON EDISON (Continued) **1019324937**

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150506
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20150506
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - MANHOLE 43892
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150506
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

CON EDISON (Continued) **1019324937**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20150506
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069383367

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019324937
Registry ID:	110069383367
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069383367
Name:	CON EDISON
Address:	VARICK ST & MESEROLE ST
City,State,Zip:	BROOKLYN, NY 11237

M133 **CON EDISON** **RCRA NonGen / NLR** **1019324941**
South **VARICK ST & MESEROLE ST** **NYP004779625**
1/8-1/4 **BROOKLYN, NY 11237**
0.155 mi.
816 ft. **Site 13 of 13 in cluster M**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20150506
Handler Name:	CON EDISON	
Handler Address:		VARICK ST & MESEROLE ST
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYP004779625
Contact Name:		THOMAS TEELING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		IRVING PL 15TH FL NE
Mailing City,State,Zip:		NEW YORK, NY 10003
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CON EDISON (Continued) **1019324941**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON CO OF NY INC
Legal Status:	Private
Date Became Current:	20150506
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PL
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON CO OF NY INC
Legal Status:	Private

CON EDISON (Continued) **1019324941**

Date Became Current: 20150506
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160205
Handler Name: CON EDISON - MANHOLE 43893
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150506
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150506
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

CON EDISON (Continued) **1019324941**

Evaluation Action Summary:
Evaluations: No Evaluations Found

Q134 **ALLOCCO RECYCLING LTD (SCHOLES ST)** **NY SWRCY** **S103272921**
ESE **575 SCHOLES STREET** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.172 mi.
908 ft. **Site 1 of 4 in cluster Q**

Relative:
Higher

Actual:
15 ft.

SWRCY:

Name:	ALLOCCO RECYCLING LTD (SCHOLES ST)
Address:	575 SCHOLES STREET
City,State,Zip:	BROOKLYN, NY 11237
Region:	2
Facility Address 2:	Not reported
Phone Number:	7183493094
Owner Type:	Private
Owner Name:	Michael Allocco
Owner Address:	540 Kingsand Ave
Owner Address 2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Email:	Mike@alloccorecycling.com
Owner Phone:	7183493094
Contact Name:	Not reported
Contact Address:	Not reported
Contact Address 2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	RHRF - registration
Activity Number:	[24MG6]
Active:	No
East Coordinate:	590866
North Coordinate:	4507400
Accuracy Code:	Not reported
Regulatory Status:	Registration
Permit #:	24MG6
Auth. Date:	3/28/2014
Expiration Date:	Not reported
Waste Types:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Last Date:	10/26/2016

SPILLS:

Name:	575 SCHOLES AVENUE
Address:	575 SCHOLES AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9610612 / 1996-11-25
Facility ID:	9610612
Facility Type:	ER
DER Facility ID:	199340
Site ID:	242575
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3

ALLOCCO RECYCLING LTD (SCHOLES ST) (Continued) **S103272921**

SWIS:	2401
Spill Date:	1996-11-25
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1996-11-25
CID:	351
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-11-25
Spill Record Last Update:	2007-02-27
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	FIREMAN CASTAGNA
DEC Memo:	""
Remarks:	"FD ON SCENE OF SPILL - LITTLE INFO AT THIS TIME - IN PROCESS OF RECOVERING"

All Materials:

Site ID:	242575
Operable Unit ID:	1042047
Operable Unit:	01
Material ID:	342826
Material Code:	0029C
Material Name:	hydrogen chloride
Case No.:	07647010
Material FA:	Hazardous Material
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	575 SCHOLES ST/B'KLYN/JLJ
Address:	575 SCHOLES ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8707214 / 1987-11-21
Facility ID:	8707214
Facility Type:	ER
DER Facility ID:	146106
Site ID:	173694
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	1987-11-21
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-11-21
CID:	Not reported

ALLOCCO RECYCLING LTD (SCHOLES ST) (Continued) **S103272921**

Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	1987-11-21
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-11-27
Spill Record Last Update:	2003-08-20
Spiller Name:	Not reported
Spiller Company:	JLJ CO.
Spiller Address:	575 SCHOLES ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was "
Remarks:	"TANK PARTIALLY FILLED WITH PRODUCT WAS BEING CUT UP BY SCRAP YARD. CONTACT: STEVE SPALIRO (718) 366-6513."

All Materials:

Site ID:	173694
Operable Unit ID:	912946
Operable Unit:	01
Material ID:	466181
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P135 **CON ED - V 4628** **RCRA NonGen / NLR** **1007206190**
ENE **SCOTT AVE & METRO AVE** **NY MANIFEST** **NYP004005286**
1/8-1/4 **BROOKLYN, NY 11237**
0.179 mi.
947 ft. **Site 4 of 4 in cluster P**

Relative: **Lower**
Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		19980228
Handler Name:	CON ED - V 4628	
Handler Address:		SCOTT AVE & METRO AVE
Handler City,State,Zip:		BROOKLYN, NY 11237-0000
EPA ID:		NYP004005286
Contact Name:		ANTHONY DRUMMINGS
Contact Address:		CONSOLIDATED EDISON INC
Contact City,State,Zip:		NEW YORK, NY 10003-0000
Contact Telephone:		212-460-3770
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported

CON ED - V 4628 (Continued) **1007206190**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	CONSOLIDATED EDISON INC
Mailing City,State,Zip:	NEW YORK, NY 10003-0000
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

CON ED - V 4628 (Continued) **1007206190**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED - V 4628	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980228
Handler Name: CON ED - V 4628	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980226
Handler Name: CON ED - V 4628	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	2211
NAICS Description:	ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code:	22111

CON ED - V 4628 (Continued) **1007206190**

NAICS Description: ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON CO
Address:	SCOTT AVE & METRO AVE
City,State,Zip:	BROOKLYN, NY 11237-0000
Country:	USA
EPA ID:	NYP004005286
Facility Status:	Not reported
Location Address 1:	SCOTT AND METRO AVENUE V4628
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	Not reported
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004005286
Mailing Name:	CONSOLIDATED EDISON CO
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

O136 **L & H ASSOCIATES C/O TROON MGMT.** **NY UST** **U001833096**
WNW **1101-1107 METROPOLITAN AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.184 mi.
974 ft. **Site 6 of 6 in cluster O**

Relative:
Lower

Actual:
11 ft.

UST:

Name:	L & H ASSOCIATES C/O TROON MGMT.
Address:	1101-1107 METROPOLITAN AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Id/Status:	2-109932 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590089.61071
UTM Y:	4507606.12417
Site Type:	Other

L & H ASSOCIATES C/O TROON MGMT. (Continued) **U001833096**

Affiliation Records:

Site Id:	3334
Affiliation Type:	Facility Owner
Company Name:	L & H ASSOCIATES C/O TROON MGMT
Contact Type:	OFFICE MGR
Contact Name:	THERESA THORNTON
Address1:	885 THIRD AVE, ROOM #1780
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 230-8229
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2008-04-24

Site Id:	3334
Affiliation Type:	Mail Contact
Company Name:	TROON MGMT
Contact Type:	Not reported
Contact Name:	THERESA THORNTON
Address1:	885 THIRD AVE, ROOM #1780
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 230-8339
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2008-04-24

Site Id:	3334
Affiliation Type:	Facility Operator
Company Name:	L & H ASSOCIATES C/O TROON MGMT.
Contact Type:	Not reported
Contact Name:	KINGSLAND & PAUL CHIEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 782-8676
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2008-04-24

Site Id:	3334
Affiliation Type:	Emergency Contact
Company Name:	L & H ASSOCIATES C/O TROON MGMT
Contact Type:	Not reported
Contact Name:	LLOYD NELSON

L & H ASSOCIATES C/O TROON MGMT. (Continued) **U001833096**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 824-8701
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-03-07

Tank Info:

Tank Number:	001
Tank ID:	7869
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	7500
Install Date:	Not reported
Date Tank Closed:	04/26/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	CGFREEDM
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number:	002
Tank ID:	222583
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	7500
Install Date:	Not reported
Date Tank Closed:	04/02/2008
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

L & H ASSOCIATES C/O TROON MGMT. (Continued) **U001833096**

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: CGFREEDM
Last Modified: 04/14/2017

Equipment Records:

J00 - Dispenser - None
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
C03 - Pipe Location - Aboveground/Underground Combination

R137 **CON EDISON** **NY MANIFEST** **S119073533**
ESE **585 MESSEROLE ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.188 mi.
994 ft. **Site 1 of 3 in cluster R**

Relative: **Higher**

Actual: **14 ft.**

NY MANIFEST:
Name: CON EDISON
Address: 585 MESSEROLE ST
City,State,Zip: BROOKLYN, NY 11237
Country: USA
EPA ID: NYP004287686
Facility Status: Not reported
Location Address 1: N/W/C MESEROLE ST & GARDENER AVE
Code: BP
Location Address 2: MH 58002
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11237
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004287686
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON EDISON (Continued) **S119073533**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/07/2013
Trans1 Recv Date:	02/07/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/07/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004287686
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002016000GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R138
ESE
1/8-1/4
0.188 mi.
994 ft.

CON EDISON - MANHOLE 58002
585 MESSEROLE ST
BROOKLYN, NY 11237

Site 2 of 3 in cluster R

RCRA-LQG **1016150097**
NYP004287686

Relative:
Higher

Actual:
14 ft.

RCRA-LQG:

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - MANHOLE 58002
Handler Address:	585 MESSEROLE ST
Handler City,State,Zip:	BROOKLYN, NY 11237
EPA ID:	NYP004287686
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	518-473-8034
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON - MANHOLE 58002 (Continued) **1016150097**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130207
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private

CON EDISON - MANHOLE 58002 (Continued) **1016150097**

Date Became Current:	20130207
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20140327
Handler Name:	CON EDISON - MANHOLE 58002
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20130207
Handler Name:	CON EDISON MANHOLE: 58002
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

S139 **ALFRED CHEMICAL CORP.** **NY CBS** **S102147546**
SE **111 GARDNER AVE.** **NY AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11237** **NY CBS AST**
0.190 mi. **NY Spills**
1004 ft. **Site 1 of 2 in cluster S**

Relative:
Lower

Actual:
13 ft.

CBS:

Name:	ALFRED CHEMICAL CORP.
Address:	111 GARDNER AVE
City,State,Zip:	BROOKLYN, NY 11237
CBS Number:	2-000023
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	590792.10533
UTMY:	4507237.30487

Name:	ALFRED CHEMICAL CORP.
Address:	111 GARDNER AVE
City,State,Zip:	BROOKLYN, NY 11237
CBS Number:	2-000037
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	590792.23647
UTMY:	4507236.42952

AST:

Name:	ALFRED CHEMICAL CORP.
Address:	111 GARDNER AVE
City,State,Zip:	BROOKLYN, NY 11237
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000037
Program Type:	CBS
UTM X:	590792.23647
UTM Y:	4507236.42952
Expiration Date:	N/A
Site Type:	Chemical Distributor

Tank Info:

Tank Number:	0002B
Tank Id:	183323
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1988
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True

ALFRED CHEMICAL CORP. (Continued) **S102147546**

Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

Tank Number:	16
Tank Id:	182826
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Plastic
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	06/01/1988
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/1992
Register:	True
Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

Tank Number:	5
Tank Id:	182827
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1988
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

Tank Number:	7
Tank Id:	182825
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	05/01/1982
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True

ALFRED CHEMICAL CORP. (Continued) **S102147546**

Modified By: CBSInit
Last Modified: 03/21/2005
Material Name: Not reported

Tank Info:

Tank Number: 0002B
Tank Id: 183323
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Plastic
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 06/01/1988
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: CBSInit
Last Modified: 03/21/2005
Material Name: Not reported

Tank Number: 16
Tank Id: 182826
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Plastic
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 06/01/1988
Capacity Gallons: 1500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 05/01/1992
Register: True
Modified By: CBSInit
Last Modified: 03/21/2005
Material Name: Not reported

Tank Number: 5
Tank Id: 182827
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Plastic
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 06/01/1988
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported

ALFRED CHEMICAL CORP. (Continued) **S102147546**

Register: True
Modified By: CBSInit
Last Modified: 03/21/2005
Material Name: Not reported

Tank Number: 7
Tank Id: 182825
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 05/01/1982
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: CBSInit
Last Modified: 03/21/2005
Material Name: Not reported

CBS AST:
CBS Number: 2-000023
ICS Number: 2-700265
PBS Number: Not reported
MOSF Number: Not reported
SPDES Number: Not reported
Facility Status: IN SERVICE
Facility Type: I
Telephone: (718) 821-0909
Facility Town: NEW YORK CITY
Region: STATE
Expiration Date: 02/24/1995
Total Capacity of All Active Tanks(gal): 0
Operator: DON GALLOP
Emergency Contact: DON GALLOP
Emergency Phone: (201) 360-1253
Owner Name: ALFRED CHEMICAL CORP.
Owner Address: 111 GARDNER AVE.
Owner City,St,Zip: BROOKLYN, NY 11237
Owner Telephone: (718) 821-0909
Owner Type: Corporate/Commercial
Owner Sub Type: Not reported
Mail Name: ALFRED CHEMICAL CORP.
Mail Contact Addr: 111 GARDNER AVE.
Mail Contact Addr2: Not reported
Mail Contact Contact: DON GALLOP
Mail Contact City,St,Zip: BROOKLYN, NY 11237
Mail Phone: (718) 821-0909

Tank Id: 16
CAS Number: 7664382
Federal ID: Not reported
Tank Status: 0

ALFRED CHEMICAL CORP. (Continued) **S102147546**

Install Date:	06/88
Tank Closed:	05/92
Capacity (Gal):	1500
Chemical:	Phosphoric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	Other
Tank Error Status:	No Missing Data
Date Entered:	02/24/1989
Certified Date:	12/04/1992
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Unknown
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Haz Percent:	80
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	11/02/92
Is It There:	False
Delinquent:	False
Date Expired:	02/24/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	03/23/1995

Tank Id:	0002B
CAS Number:	7782505
Federal ID:	Not reported
Tank Status:	0
Install Date:	06/88
Tank Closed:	00/00
Capacity (Gal):	2000
Chemical:	Chlorine
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	Other
Tank Error Status:	No Missing Data
Date Entered:	04/28/1989
Certified Date:	02/05/1993
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None

ALFRED CHEMICAL CORP. (Continued) **S102147546**

External Protection:	None
Pipe Location:	None
Pipe Type:	Unknown
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Haz Percent:	15
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	01/04/93
Is It There:	False
Delinquent:	False
Date Expired:	04/28/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	05/24/1995

Tank Id:	5
CAS Number:	27176870
Federal ID:	Not reported
Tank Status:	0
Install Date:	06/88
Tank Closed:	00/00
Capacity (Gal):	2000
Chemical:	Dodecylbenzenesulfonic acid
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	Other
Tank Error Status:	No Missing Data
Date Entered:	02/24/1989
Certified Date:	12/04/1992
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Unknown
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Haz Percent:	10
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False

ALFRED CHEMICAL CORP. (Continued) **S102147546**

Renew Date:	11/02/92
Is It There:	False
Delinquent:	False
Date Expired:	02/24/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	03/23/1995

Tank Id:	7
CAS Number:	1310583
Federal ID:	Not reported
Tank Status:	0
Install Date:	05/82
Tank Closed:	00/00
Capacity (Gal):	5000
Chemical:	Potassium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	Other
Tank Error Status:	No Missing Data
Date Entered:	02/24/1989
Certified Date:	12/04/1992
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Unknown
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Haz Percent:	80
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	11/02/92
Is It There:	False
Delinquent:	False
Date Expired:	02/24/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	03/23/1995

SPILLS:

Name:	111 GARDNER AVENUE
Address:	111 GARDNER AVENUE
City,State,Zip:	BROOKLYN, NY

ALFRED CHEMICAL CORP. (Continued) **S102147546**

Spill Number/Closed Date:	9311997 / 1994-01-11
Facility ID:	9311997
Facility Type:	ER
DER Facility ID:	63513
Site ID:	66304
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C4
SWIS:	2401
Spill Date:	1994-01-11
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1994-01-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	1994-01-11
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-12
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was 10/10/95: This is additional information about material spilled from the translation of the old spill file: POWDER SUBSTANCE."
Remarks:	"3 CARDBOARD & PLASTIC CONTAINERS - HAZMAT SECTION WAS NOTIFIED - CALL KEN FRADKIM @ DEP WILL HANDLE AND WILL CALL BACK IF NEEDS HELP."

All Materials:

Site ID:	66304
Operable Unit ID:	994006
Operable Unit:	01
Material ID:	391002
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

S140 **ALFRED CHEMICAL CORP** **RCRA NonGen / NLR** **1004760849**
SE **111 GARDNER AVE** **FINDS** **NYR000062570**
1/8-1/4 **BROOKLYN, NY 11237** **ECHO**
0.190 mi.
1004 ft. **Site 2 of 2 in cluster S**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	ALFRED CHEMICAL CORP	
Handler Address:		111 GARDNER AVE
Handler City,State,Zip:		BROOKLYN, NY 11237
EPA ID:		NYR000062570
Contact Name:		Not reported
Contact Address:		GARDNER AVE
Contact City,State,Zip:		BROOKLYN, NY 11237
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		GARDNER AVE
Mailing City,State,Zip:		BROOKLYN, NY 11237
Owner Name:		NON REGULATED
Owner Type:		Private
Operator Name:		NON REGULATED
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

ALFRED CHEMICAL CORP (Continued) **1004760849**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NON REGULATED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	718-821-0909
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NON REGULATED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	718-821-0909
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

ALFRED CHEMICAL CORP (Continued) **1004760849**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NON REGULATED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	718-821-0909
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19981023
Handler Name: ALFRED CHEMICAL CORP	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: ALFRED CHEMICAL CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: ALFRED CHEMICAL CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19981023
Handler Name: ALFRED CHEMICAL CORP	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

ALFRED CHEMICAL CORP (Continued) **1004760849**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110002093289

Click Here:

Environmental Interest/Information System:
NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ALFRED CHEMICAL CORP (Continued) **1004760849**

ECHO:
- Envid: 1004760849
- Registry ID: 110002093289
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002093289
- Name: ALFRED CHEMICAL CORP
- Address: 111 GARDNER AVENUE
- City,State,Zip: BROOKLYN, NY 11237

T141 **WOOD-TEX PANELS INC** **RCRA NonGen / NLR** **1000184307**
SSE **108 VARICK AVE** **FINDS** **NYD001641489**
1/8-1/4 **BROOKLYN, NY 11237** **ECHO**
0.199 mi. **NY MANIFEST**
1049 ft. **Site 1 of 7 in cluster T**

Relative: **Lower**
Actual: **13 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	WOOD-TEX PANELS INC	
Handler Address:		108 VARICK AVE
Handler City,State,Zip:		BROOKLYN, NY 11237-1217
EPA ID:		NYD001641489
Contact Name:		Not reported
Contact Address:		VARICK AVE
Contact City,State,Zip:		BROOKLYN, NY 11237
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		VARICK AVE
Mailing City,State,Zip:		BROOKLYN, NY 11237
Owner Name:		WOOD-TEX PANELS INC
Owner Type:		Private
Operator Name:		WOOD-TEX PANELS INC
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported

WOOD-TEX PANELS INC (Continued) **1000184307**

Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F017
Waste Description:	Not Defined
Waste Code:	U220
Waste Description:	BENZENE, METHYL- (OR) TOLUENE
Waste Code:	U239
Waste Description:	BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

WOOD-TEX PANELS INC (Continued) **1000184307**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	WOOD-TEX PANELS INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WOOD-TEX PANELS INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WOOD-TEX PANELS INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: WOOD-TEX PANELS INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: WOOD-TEX PANELS INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

WOOD-TEX PANELS INC (Continued) **1000184307**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	WOOD-TEX PANELS INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19800814
Handler Name:	WOOD-TEX PANELS INC
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	3219
NAICS Description:	OTHER WOOD PRODUCT MANUFACTURING

NAICS Code:	32191
NAICS Description:	MILLWORK

Facility Has Received Notices of Violation:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19850909
Actual Return to Compliance Date:	19860212
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19851227
Enforcement Identifier:	001
Date of Enforcement Action:	19851127
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No

WOOD-TEX PANELS INC (Continued) **1000184307**

Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported

WOOD-TEX PANELS INC (Continued) **1000184307**

Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19850909
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19860212
Scheduled Compliance Date:	19851227
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19880524
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110001573663

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000184307
Registry ID:	110001573663
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110001573663
Name:	WOOD-TEX PANELS INC

WOOD-TEX PANELS INC (Continued) **1000184307**

Address: 108 VARICK STREET
City,State,Zip: BROOKLYN, NY 11237

NY MANIFEST:
Name: WOOD-TEX PANELS INC
Address: 108 VARICK AVE
City,State,Zip: BROOKLYN, NY 11237-1217
Country: USA
EPA ID: NYD001641489
Facility Status: Not reported
Location Address 1: 108 VARICK AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11237
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD001641489
Mailing Name: WOOD-TEX PANELS INC
Mailing Contact: PACKIN DAVID PRESIDENT
Mailing Address 1: 108 VARICK AVE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11237
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2123669292

U142 **GREENWALD INDUSTRIES INC** **RCRA NonGen / NLR** **1000457874**
East **1340 METROPOLITAN AVE** **FINDS** **NYD986931533**
1/8-1/4 **BROOKLYN, NY 11237** **ECHO**
0.203 mi. **NY MANIFEST**
1072 ft. **Site 1 of 5 in cluster U**

Relative: **Higher**
Actual: **16 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: GREENWALD INDUSTRIES INC
Handler Address: 1340 METROPOLITAN AVE
Handler City,State,Zip: BROOKLYN, NY 11237
EPA ID: NYD986931533
Contact Name: Not reported
Contact Address: METROPOLITAN AVE
Contact City,State,Zip: BROOKLYN, NY 11237
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported

GREENWALD INDUSTRIES INC (Continued) **1000457874**

Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	METROPOLITAN AVE
Mailing City,State,Zip:	BROOKLYN, NY 11237
Owner Name:	GREENWALD INDUSTRIES INC
Owner Type:	Private
Operator Name:	GREENWALD INDUSTRIES INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414

GREENWALD INDUSTRIES INC (Continued) **1000457874**

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GREENWALD INDUSTRIES INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	GREENWALD INDUSTRIES INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	GREENWALD INDUSTRIES INC
Legal Status:	Private

GREENWALD INDUSTRIES INC (Continued) **1000457874**

Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19950419
Handler Name: GREENWALD INDUSTRIES INC
Federal Waste Generator Description: Not reported
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: GREENWALD INDUSTRIES INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: GREENWALD INDUSTRIES INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19901123
Handler Name: GREENWALD INDUSTRIES INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

GREENWALD INDUSTRIES INC (Continued) **1000457874**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19921216
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported

GREENWALD INDUSTRIES INC (Continued) **1000457874**

Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110004456446

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000457874
Registry ID: 110004456446
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004456446
Name: GREENWALD INDUSTRIES INC
Address: 1340 METROPOLITAN AVE
City,State,Zip: BROOKLYN, NY 11237

NY MANIFEST:
Name: GREENWALD INDUSTRIES INC
Address: 1340 METROPOLITAN AVE
City,State,Zip: BROOKLYN, NY 11237
Country: USA
EPA ID: NYD986931533
Facility Status: Not reported
Location Address 1: 1340 METROPOLITAN AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11237
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986931533
Mailing Name: GREENWALD INDUSTRIES INC
Mailing Contact: GREENWALD INDUSTRIES INC
Mailing Address 1: 1340 METROPOLITAN AVENUE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11237
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7188219000

V143 **ROLLING FRITO-LAY SALES** **NY AST** **A100410466**
West **222 MORGAN AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.204 mi.
1079 ft. **Site 1 of 2 in cluster V**

Relative:
Lower

Actual:
12 ft.

AST:

Name:	ROLLING FRITO-LAY SALES
Address:	222 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-612410
Program Type:	PBS
UTM X:	590047.41060
UTM Y:	4507318.82300
Expiration Date:	04/24/2020
Site Type:	Other

Affiliation Records:

Site Id:	507021
Affiliation Type:	Facility Owner
Company Name:	ROLLING FRITO-LAY SALES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	7701 LEGACY DRIVE, FRITO-LAY, INC.
Address2:	Not reported
City:	PLANO
State:	TX
Zip Code:	75024
Country Code:	001
Phone:	(972) 334-7000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-04-24

Site Id:	507021
Affiliation Type:	Mail Contact
Company Name:	ROLLING FRITO-LAY SALES
Contact Type:	Not reported
Contact Name:	CLINTON PALMER
Address1:	222 MORGAN AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(917) 449-1837
EMail:	CLINT.PALMER@PEPSICO.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-04-24

Site Id:	507021
Affiliation Type:	Facility Operator
Company Name:	ROLLING FRITO-LAY SALES
Contact Type:	Not reported
Contact Name:	CLINTON A. PALMER

ROLLING FRITO-LAY SALES (Continued) **A100410466**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 449-1837
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-04-24

Site Id:	507021
Affiliation Type:	Emergency Contact
Company Name:	ROLLING FRITO-LAY SALES
Contact Type:	Not reported
Contact Name:	CLINTON PALMER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 449-1837
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2015-04-24

Tank Info:

Tank Number:	001
Tank Id:	255309

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E01 - Piping Secondary Containment - Diking (AG only)
L00 - Piping Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J01 - Dispenser - Pressurized Dispenser
F00 - Pipe External Protection - None
K99 - Spill Prevention - Other
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/07/2007
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

ROLLING FRITO-LAY SALES (Continued) **A100410466**

Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	motor oil
Tank Number:	002
Tank Id:	255310

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
E01 - Piping Secondary Containment - Diking (AG only)
L00 - Piping Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
F00 - Pipe External Protection - None
K99 - Spill Prevention - Other
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/07/2007
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

V144 **EASTERN TRANSFER OF NY; INC (N.Y. MATER** **NY SWF/LF** **S103592538**
West **222 MORGAN AVE** **NY LTANKS** **N/A**
1/8-1/4 **BROOKLYN, NY 11237** **NY SPDES**
0.204 mi.
1079 ft. **Site 2 of 2 in cluster V**

Relative: **Lower**
Actual: **12 ft.**

SWF/LF:

Name:	EASTERN TRANSFER OF NY; INC (N.Y. MATER
Address:	222 MORGAN AVE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	7184973100
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported

EASTERN TRANSFER OF NY; INC (N.Y. MATER (Continued) **S103592538**

Owner Phone:	Not reported
Contact Name:	LOUIS D'AMBROSIO
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[24T76]
Active:	No
East Coordinate:	590116
North Coordinate:	4507117
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	2-6104-00097
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

Name:	EASTERN TRANSFER OF NY; INC (N.Y. MATER
Address:	222 MORGAN AVE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	7184973100
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	LOUIS D'AMBROSIO
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[24W76]
Active:	No
East Coordinate:	590116
North Coordinate:	4507117
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	2-6104-00097
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

EASTERN TRANSFER OF NY; INC (N.Y. MATER (Continued) **S103592538**

LTANKS:

Name:	QUATTRO PROPERTIES
Address:	222 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0009585 / 2003-08-28
Facility ID:	0009585
Site ID:	302888
Spill Date:	2000-11-21
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2000-11-21
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2000-11-21
Spill Record Last Update:	2003-08-28
Spiller Name:	JAMES JULIANO, PROP MGR
Spiller Company:	QUATTRO PROPERTIES, LLC
Spiller Address:	213-19 99TH AVENUE
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	244717
DEC Memo:	""
Remarks:	"CALLER PULLED TANK AND FOUND CONTAMINATED SOIL.WOULD LIKE A CALL FROM DEC 11-21-00 TIS STRANGE BUT R. SPADALIK IS NO LONGER AT F&N WHEN I CALLED THE TEL#AND EXT,THATS WHAT THE PERSON AT THAT TEL#SAID ROBERT.L"

All Materials:

Site ID:	302888
Operable Unit ID:	830684
Operable Unit:	01
Material ID:	543525
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	222 MORGAN AVENUE

EASTERN TRANSFER OF NY; INC (N.Y. MATER (Continued) **S103592538**

Address:	222 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9312206 / 1994-01-17
Facility ID:	9312206
Site ID:	302889
Spill Date:	1994-01-17
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1994-01-17
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1994-01-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-20
Spill Record Last Update:	2003-08-28
Spiller Name:	Not reported
Spiller Company:	222 MORGAN AVENUE
Spiller Address:	222 MORGAN AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	244717
DEC Memo:	""
Remarks:	"FIRE @ PLANT NOTIFIED DEP, UNK. ACTIONS. 11/18 UPDATE ROBERT KEPICH / DEP 595-6777 / 50-60 GAL DIESSEL HYDRAULIC NO CALL BACK. 100PM SPOKE TO ENZO HE SAID FIRE DIESSEL HYDRAULIC OIL P/U DISPOSE INDRUM"

All Materials:

Site ID:	302889
Operable Unit ID:	990817
Operable Unit:	01
Material ID:	391198
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPDES:

Name:	METRO NEW YORK SERVICE CENTER
Address:	222 MORGAN AVE

EASTERN TRANSFER OF NY; INC (N.Y. MATER (Continued) **S103592538**

City,State,Zip:	BROOKLYN, NY 11237
Permit Number:	NYR00E651
State-Region:	02
Expiration Date:	09/30/2017
Current Major Minor Status:	Minor
Primary Facility SIC Code:	4213
State Water Body Name:	ENGLISH KILLS WATERWAY
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	+40.712 / -73.933
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	ELPIDIO BURGOS
Non-Gov Permit Street Address:	METRO NEW YORK SERVICE CENTER
Non-Gov Permit Supplemental Location:	85 COMMERCE DR
Non-Gov Permit City:	SOMERSET
Non-Gov Permit State Code:	NJ
Non-Gov Permit Zip Code:	08878
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	ROLLING FRITO-LAY SALES LP
Non-Gov Facility Street Address:	METRO NEW YORK SERVICE CENTER
Non-Gov Facility Supplemental Location:	85 COMMERCE DR
Non-Gov Facility City:	SOMERSET
Non-Gov Facility State Code:	NJ
Non-Gov Facility Zip Code:	08873
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	METRO NEW YORK SERVICE CENTER
Address:	222 MORGAN AVE
City,State,Zip:	BROOKLYN, NY 11237
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	ROLLING FRITO-LAY SALES LP
Non-Gov Permit Street Address:	85 COMMERCE DR
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	SOMERSET
Non-Gov Permit State Code:	NJ
Non-Gov Permit Zip Code:	08872
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	ROLLING FRITO-LAY SALES LP

EASTERN TRANSFER OF NY; INC (N.Y. MATER (Continued) **S103592538**

Non-Gov Facility Street Address:	METRO NEW YORK SERVICE CENTER
Non-Gov Facility Supplemental Location:	85 COMMERCE DR
Non-Gov Facility City:	SOMERSET
Non-Gov Facility State Code:	NJ
Non-Gov Facility Zip Code:	08873
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	METRO NEW YORK SERVICE CENTER
Address:	222 MORGAN AVE
City,State,Zip:	BROOKLYN, NY 11237
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	ROLLING FRITO-LAY SALES LP
Non-Gov Facility Street Address:	METRO NEW YORK SERVICE CENTER
Non-Gov Facility Supplemental Location:	85 COMMERCE DR
Non-Gov Facility City:	SOMERSET
Non-Gov Facility State Code:	NJ
Non-Gov Facility Zip Code:	08873
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

R145 **MESEROLE STREET RECYCLING INC./FILIBERTO RECYCLING** **NY SWRCY** **S105838144**
ESE **568 MESEROLE STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.208 mi.
1099 ft. **Site 3 of 3 in cluster R**

Relative: SWRCY:
Higher

Name:	MESEROLE STREET RECYCLING INC./FILIBERTO RECYCLING
Address:	568 MESEROLE STREET
City,State,Zip:	BROOKLYN, NY 11237
Region:	2
Facility Address 2:	Not reported
Phone Number:	7184565000

Actual:
14 ft.

MESEROLE STREET RECYCLING INC./FILIBERTO RECYCLING (Continued) **S105838144**

Owner Type:	Private
Owner Name:	Filiberto Recycling
Owner Address:	568 Meserole Street
Owner Address 2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11237
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	RUDOLPH FILIBERTO
Contact Address:	Not reported
Contact Address 2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	RHRF - registration
Activity Number:	[24MB5]
Active:	No
East Coordinate:	590803
North Coordinate:	4507257
Accuracy Code:	4.3 - Utilization of Digital Orthophoto Quads
Regulatory Status:	Permit
Permit #:	2-6104-00214
Auth. Date:	3/21/2005
Expiration Date:	3/21/2010
Waste Types:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Last Date:	Not reported

U146 **CON EDISON SERVICE BOX: 54420** **RCRA NonGen / NLR** **1016960837**
ENE **ONDERDONK AVE & METROPOLITAN** **NY MANIFEST** **NYP004330460**
1/8-1/4 **RIDGEWOOD, NY 11385**
0.209 mi.
1105 ft. **Site 2 of 5 in cluster U**

Relative: **Lower**

Actual: **11 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20130817
Handler Name:	CON EDISON SERVICE BOX: 54420
Handler Address:	ONDERDONK AVE & METROPOLITAN
Handler City,State,Zip:	RIDGEWOOD, NY 11385
EPA ID:	NYP004330460
Contact Name:	MARK MOORE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-466-8516
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OPERATING SUPERVISOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003

CON EDISON SERVICE BOX: 54420 (Continued) **1016960837**

Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported

CON EDISON SERVICE BOX: 54420 (Continued) **1016960837**

Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:

Receive Date: 20130717
Handler Name: CON EDISON SERVICE BOX: 54420
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130817
Handler Name: CON EDISON SERVICE BOX: 54420
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: ONDERDONK AVE & METROPOLITAN
City,State,Zip: RIDGEWOOD, NY 11385
Country: USA
EPA ID: NYP004330460
Facility Status: Not reported
Location Address 1: ES ONDENDORK 225’ S METROPOLITAN
Code: BP
Location Address 2: SB #54420
Total Tanks: Not reported
Location City: FLUSHING
Location State: NY
Location Zip: 11385

CON EDISON SERVICE BOX: 54420 (Continued) **1016960837**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004330460
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 07/17/2013
Trans1 Recv Date: 07/17/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/17/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004330460
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002086386GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON SERVICE BOX: 54420 (Continued) **1016960837**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T147 **ENEQUIST CHEMICAL CO INC** **RCRA-LQG** **1000350776**
South **100 VARICK AVE** **NY CBS AST** **NYD002028827**
1/8-1/4 **BROOKLYN, NY 11237** **FINDS**
0.211 mi. **ECHO**
1112 ft. **Site 2 of 7 in cluster T** **PA MANIFEST**
NY MANIFEST
Relative: **NJ MANIFEST**
Lower

Actual: RCRA-LQG:
13 ft.

Date Form Received by Agency:	20070101
Handler Name:	ENEQUIST CHEMICAL CO INC
Handler Address:	100 VARICK AVE
Handler City,State,Zip:	BROOKLYN, NY 11237-1283
EPA ID:	NYD002028827
Contact Name:	Not reported
Contact Address:	VARICK AVE
Contact City,State,Zip:	BROOKLYN, NY 11237
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	VARICK AVE
Mailing City,State,Zip:	BROOKLYN, NY 11237
Owner Name:	THE ENEQUIST CHEMICAL CO INC
Owner Type:	Private
Operator Name:	THE ENEQUIST CHEMICAL CO INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	P030
Waste Description:	CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	THE ENEQUIST CHEMICAL CO INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE ENEQUIST CHEMICAL CO INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THE ENEQUIST CHEMICAL CO INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: ENEQUIST CHEMICAL CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: ENEQUIST CHEMICAL CO INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ENEQUIST CHEMICAL CO INC

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800820
Handler Name: ENEQUIST CHEMICAL CO INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 325998
NAICS Description: ALL OTHER MISCELLANEOUS CHEMICAL PRODUCT AND PREPARATION MANUFACTURING

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19851118
Actual Return to Compliance Date: 19860212
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19860221
Enforcement Identifier: 001
Date of Enforcement Action: 19860121
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYDEC
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19851118
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19860212

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Scheduled Compliance Date:	19860221
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20100629
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

CBS AST:

CBS Number:	2-000027
ICS Number:	2-125129
PBS Number:	2-233072
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	IN SERVICE
Facility Type:	A
Telephone:	(718) 497-1200
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	04/07/2003
Total Capacity of All Active Tanks(gal):	4000
Operator:	ENEQUIST CHEMICAL CO. INC.
Emergency Contact:	WALTER SCHWARTZ
Emergency Phone:	(718) 497-1200
Owner Name:	RJR REALTY CO., LTD
Owner Address:	1500 PAERDAGET AVENUE N
Owner City,St,Zip:	BROOKLYN, NY 11236
Owner Telephone:	(718) 209-1010
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	ENEQUIST CHEMICAL CO. INC.
Mail Contact Addr:	100 VARICK AVE.
Mail Contact Addr2:	Not reported
Mail Contact Contact:	WALTER SCHWARTZ
Mail Contact City,St,Zip:	BROOKLYN, NY 11237
Mail Phone:	(718) 497-1200
Tank Id:	007
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	11/88
Tank Closed:	Not reported
Capacity (Gal):	1500
Chemical:	Sodium hydroxide

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	04/07/1989
Certified Date:	02/05/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	Catch Basin
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	01/04/93
Is It There:	False
Delinquent:	False
Date Expired:	04/07/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	01/18/2001

Tank Id:	006
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	10/88
Tank Closed:	Not reported
Capacity (Gal):	2500
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	04/07/1989
Certified Date:	02/05/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	Catch Basin
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	01/04/93
Is It There:	False
Delinquent:	False
Date Expired:	04/07/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	01/18/2001

Tank Id:	005
CAS Number:	7664939
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	10/79
Tank Closed:	08/92
Capacity (Gal):	6000
Chemical:	Sulfuric acid
Tank Location:	Indoors, Belowground
Tank Type:	Steel/carbon steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	04/07/1989
Certified Date:	02/05/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	93
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	01/04/93
Is It There:	False
Delinquent:	False
Date Expired:	04/07/95

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	01/18/2001

Tank Id:	003
CAS Number:	7647010
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	07/61
Tank Closed:	08/92
Capacity (Gal):	3000
Chemical:	Hydrochloric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	04/07/1989
Certified Date:	02/05/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Rubber Liner
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	100
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	01/04/93
Is It There:	False
Delinquent:	False
Date Expired:	04/07/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	01/18/2001

Tank Id:	001
CAS Number:	7697372
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	07/61
Tank Closed:	08/92
Capacity (Gal):	3000

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Chemical:	Nitric acid
Tank Location:	Indoors, Belowground
Tank Type:	Stainless steel alloy
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	04/07/1989
Certified Date:	02/05/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Wrapped Steel
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	67
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	01/04/93
Is It There:	False
Delinquent:	False
Date Expired:	04/07/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	01/18/2001

Tank Id:	004
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	07/61
Tank Closed:	08/92
Capacity (Gal):	3000
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Belowground
Tank Type:	Steel/carbon steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	04/07/1989
Certified Date:	02/05/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	25
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	01/04/93
Is It There:	False
Delinquent:	False
Date Expired:	04/07/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	01/18/2001

Tank Id:	002
CAS Number:	7647010
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	03/74
Tank Closed:	08/92
Capacity (Gal):	6000
Chemical:	Hydrochloric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass coated steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	04/07/1989
Certified Date:	02/05/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	31
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	01/04/93
Is It There:	False
Delinquent:	False

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Date Expired: 04/07/95
Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 01/18/2001

FINDS:
Registry ID: 110000323551

Click Here:

Environmental Interest/Information System:
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000350776
Registry ID: 110000323551
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110000323551
Name: ENEQUIST CHEMICAL CO INC
Address: 100 VARICK AVE.
City,State,Zip: BROOKLYN, NY 11237

Manifest Details:
Year: 2006
Manifest Number: PAH320646
Manifest Type: TSD Copy
Generator EPA Id: NYD002028827
Generator Date: 06/30/2006
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE
TSD Facility City: LEWISBERRY
TSD Facility State: PA
Facility Telephone: 718-497-1200
Page Number: 1
Line Number: 1

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Waste Number: D002
Container Number: 1
Container Type: Metal drums, barrels, kegs
Waste Quantity: 55
Unit: Gallons (liquids only)
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2006
Manifest Number: PAH320646
Manifest Type: TSD Copy
Generator EPA Id: NYD002028827
Generator Date: 06/30/2006
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE
TSD Facility City: LEWISBERRY
TSD Facility State: PA
Facility Telephone: 718-497-1200
Page Number: 1
Line Number: 1
Waste Number: D005
Container Number: 1
Container Type: Metal drums, barrels, kegs
Waste Quantity: 55
Unit: Gallons (liquids only)
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

NY MANIFEST:
Name: ENEQUIST CHEMICAL COMPANY INCORPORATED
Address: 100 VARICK AVE
City,State,Zip: BROOKLYN, NY 11237-1283
Country: USA
EPA ID: NYD002028827
Facility Status: Not reported
Location Address 1: 100 VARICK AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11237
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD002028827
Mailing Name: ENEQUIST CHEMICAL COMPANY INCORPORATED
Mailing Contact: WALTER SCHWARTZ
Mailing Address 1: 100 VARICK AVENUE

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184971200

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	NJ0000027193
Generator Ship Date:	06/30/2006
Trans1 Recv Date:	06/30/2006
Trans2 Recv Date:	07/10/2006
TSD Site Recv Date:	07/11/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002028827
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	PAH0320646
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	55
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D005
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

NJ MANIFEST:

EPA Id:	NYD002028827
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	X
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5312788
EPA ID:	NYD002028827
Date Shipped:	03/29/2006
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/29/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/29/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06220621

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5312763
EPA ID:	NYD002028827
Date Shipped:	03/31/2006
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/31/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/04/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06220621
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA2829650
EPA ID:	NYD002028827
Date Shipped:	04/03/2006
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/03/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/03/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06080622
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA2829648
EPA ID:	NYD002028827
Date Shipped:	04/03/2006
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/03/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/03/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06080622
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5312765
EPA ID:	NYD002028827
Date Shipped:	03/29/2006
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/29/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/29/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06140622
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5312786
EPA ID:	NYD002028827
Date Shipped:	03/31/2006
TSDF EPA ID:	NJD002200046

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/31/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/04/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05310635
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5312766
EPA ID:	NYD002028827
Date Shipped:	03/29/2006
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/29/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/29/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06140622
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA2829649
EPA ID:	NYD002028827
Date Shipped:	04/03/2006
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/03/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/03/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Manifest Discrepancy Type:	Not reported
Data Entry Number:	06080622
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5312764
EPA ID:	NYD002028827
Date Shipped:	03/29/2006
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/29/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/29/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06140622
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported
Manifest Number:	NJA5312787
EPA ID:	NYD002028827
Date Shipped:	03/29/2006
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

ENEQUIST CHEMICAL CO INC (Continued) **1000350776**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/29/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/29/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06140622
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

T148 **ENEQUIST CHEMICAL** **NY AST** **A100382296**
South **100 VARICK AVENUE** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.211 mi.
1112 ft. **Site 3 of 7 in cluster T**

Relative: **Lower**

Actual: **13 ft.**

AST:

Name:	ENEQUIST CHEMICAL
Address:	100 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-233072
Program Type:	PBS
UTM X:	590579.25393
UTM Y:	4507062.82724
Expiration Date:	N/A
Site Type:	Chemical Distributor

Tank Info:

Tank Number:	006
Tank Id:	66159
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

ENEQUIST CHEMICAL (Continued) **A100382296**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/21/2006
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	Not reported

Tank Number:	007
Tank Id:	10958
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/21/2006
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	Not reported

T149 **EMEQUIFT CHEMICAL CORP - MISC** **NY LTANKS** **S118953501**
South **100 VARICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY**
0.211 mi.
1112 ft. **Site 4 of 7 in cluster T**

Relative: LTANKS:
Lower

Actual: Name:	EMEQUIFT CHEMICAL CORP - MISC
13 ft. Address:	100 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0502445 / 2006-05-31
Facility ID:	0502445
Site ID:	346803
Spill Date:	2005-05-31
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	rjfeng
Referred To:	MW INSTALLATION DUE 5/31/2006
Reported to Dept:	2005-05-31
CID:	407
Water Affected:	Not reported
Spill Notifier:	Federal Government

EMEQUIFT CHEMICAL CORP - MISC (Continued) **S118953501**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-05-31
Spill Record Last Update:	2006-05-31
Spiller Name:	WALTER SCHWARTZ
Spiller Company:	EMEQUIFT CHEMICAL CORP
Spiller Address:	100 BARICK AVE
Spiller County:	001
Spiller Contact:	JOESEPH CREFCENZO
Spiller Phone:	(718) 497-1200
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	293056
DEC Memo:	"Phase 1 & Phase 2 done - found petroleum mixed with paint 10.14.05 SR// Sharif rec'd the site assesment report with remedial action plan. I suggested to prepare a health & safety plan, set a time frame to complete the remedial work and installation of monitoring wells to confirm the ground water flow.Paul Stewart of ACT,Inc will forward DEC an addendum. 12/20/05-Sharif//Case was transferred to Koon Tang for reassignment since the site is going through extensive remedial activities. 1/11/2006 - Feng - File reviewed by Feng: 1) On 5/2005, ATC performed Phase I/Phase II Environmental Site Assessment (ESA) for the site, and found elevated VOCs present in soil and groundwater beneath the western portion of the sotrage yard. and the source might be the historical gasoline UST and storage of solvents. 2) On 10/25/2005, ATC proposed RAP to remediate the site. a) removal of contaminated soil beneath the storage yard, b) install monitoring wells. DEC approved the RAP. Waiting for soil excavation report, MWs installation, and groundwater sampling results. 2/1/2006 - Feng - call from Caroline Cadalso (ACT) stated that about 700 tons of soil were excavated, endpoint samples were taken. groundwater encountered at 12' and it looks like perched water. They plan to install the monitoring well deeper, down to 25'-35' bg to delineate the extend of contamination. approved. (RJF) 3/22/2006 - Feng - Remedial Closure Report, prepared by ACT, dated 3/20/2006. ACT excavated the contaminated soil from Area A, B, C and D down to depth of 12' bg. Endpoint samples show high PERC concentration found in Area B and Area D. Extend the excavation of soil in Area B, and 2nd round of soil samples show low concentration (only one were sent for lab analysis). Confirmatory samples were taken from Area D, show low concentration (only one were sent for lab analysis). 3 MWs were installed and groundwater contour were provided. Groundwater flows to northwest. Analyticals show low concentration. ACT requested spill closure. Spill closure request was denied and letter sent requiring 2 more monitoring wells in the 2 former drain. According to Phase II site assessment, high PERC has been found in former drain B (soil boring SB-3). Installtion report due 5/31/2006. 4/24/2006 - Feng - Addendum to Closure Report dated 3/20/2006, 4/5/2006 submitted by Advanced CleanUp Technologies, Inc. 2 monitoring wells were installed in the former Drain B (W-5) and former Drain D (W-4). Groundwater depth encounterred at 10'. Screen depth of 25'-35' bg. low Soil concentration. Groundwater samples show low concentration, 8.73 ppb of Trichloroethene, 11.4 ppb Tetrachloroethene and 10.9 ppb 1,2-dichloroethene in W-4. Request closure. Emailed to Caroline

EMEQUIFT CHEMICAL CORP - MISC (Continued) **S118953501**

Cadalso and inquired if it is perched or true groundwater at 10' and if we missed the groundwater at 10'-25'. (RJF) 5/31/2006 - Feng - Have been discussed with DEC Joe Sun. Spill closed for: 1) source removal, soil was excavated down to 12' bg and endpoint samples are in low concentration. 2) The groundwater encountered at about 10 feet is perched water due to low recharge. 3) The groundwater samples taken from 12' bg in Phase II is present in fill material (fill material found from 12' to 20' bg). 4) 5 Groundwater samples collected from 25' to 35' bg show low contamination (given that contaminants are PCE and TCE, deeper gw was selected). 5) Sensitive Receptor survey was done and it is fine. Spill closed and NFA issued. (RJF)"

Remarks: ""

All Materials:

Site ID:	346803
Operable Unit ID:	1104563
Operable Unit:	01
Material ID:	584786
Material Code:	0055A
Material Name:	paint
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	346803
Operable Unit ID:	1104563
Operable Unit:	01
Material ID:	584785
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

T150 **ENEQUIST CHEMICAL CO. INC.** **NY CBS** **S106971941**
South **100 VARICK AVENUE** **NY AST** **N/A**
1/8-1/4 **BROOKLYN, NY 11237** **NY Spills**
0.211 mi.
1112 ft. **Site 5 of 7 in cluster T**

Relative: **Lower**

Actual: **13 ft.**

CBS:

Name:	ENEQUIST CHEMICAL CO. INC.
Address:	100 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
CBS Number:	2-000027
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	590606.88886

ENEQUIST CHEMICAL CO. INC. (Continued) **S106971941**

UTMY: 4507068.33341

AST:

Name:	ENEQUIST CHEMICAL CO. INC.
Address:	100 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000027
Program Type:	CBS
UTM X:	590606.88886
UTM Y:	4507068.33341
Expiration Date:	N/A
Site Type:	Chemical Distributor

Tank Info:

Tank Number:	001
Tank Id:	183131
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Stainless Steel Alloy
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	07/01/1961
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1992
Register:	True
Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

Tank Number:	002
Tank Id:	183132
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	03/01/1974
Capacity Gallons:	6000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1992
Register:	True
Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

Tank Number: 003

ENEQUIST CHEMICAL CO. INC. (Continued) **S106971941**

Tank Id:	183133
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1961
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1992
Register:	True
Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

Tank Number:	004
Tank Id:	183134
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1961
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1992
Register:	True
Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

Tank Number:	005
Tank Id:	183135
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	10/01/1979
Capacity Gallons:	6000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1992
Register:	True
Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

Tank Number:	006

ENEQUIST CHEMICAL CO. INC. (Continued) **S106971941**

Tank Id:	183136
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/01/1988
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/14/2006
Register:	True
Modified By:	KAKYER
Last Modified:	02/20/2007
Material Name:	Not reported

Tank Number:	007
Tank Id:	183137
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1988
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	03/14/2006
Register:	True
Modified By:	KAKYER
Last Modified:	02/20/2007
Material Name:	Not reported

SPILLS:

Name:	100 VARICK/ENEQUIST CHEM
Address:	100 VARICK ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9202219 / 1994-11-23
Facility ID:	9202219
Facility Type:	ER
DER Facility ID:	258768
Site ID:	321213
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	2401
Spill Date:	1992-05-22
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1992-05-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Local Agency

ENEQUIST CHEMICAL CO. INC. (Continued) **S106971941**

Cleanup Ceased:	1994-11-23
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-05-29
Spill Record Last Update:	2002-11-01
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"FD & DEP HAZ MAT TEAMS ON SCENE; WATER VAPOR AND CLOUD OBSERVED."

All Materials:

Site ID:	321213
Operable Unit ID:	966307
Operable Unit:	01
Material ID:	413486
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

W151 **NEWTOWN USED AUTO PARTS/SCRAP METAL PROCESSOR** **NY AST** **A100295268**
West **1074 GRAND STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.211 mi.
1114 ft. **Site 1 of 6 in cluster W**

Relative:
Lower

Actual:
13 ft.

AST:

Name:	NEWTOWN USED AUTO PARTS/SCRAP METAL PROCESSOR
Address:	1074 GRAND STREET
City,State,Zip:	BROOKLYN, NY 11237
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-610198
Program Type:	PBS
UTM X:	590108.01017
UTM Y:	4507519.62934
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	363543
Affiliation Type:	Facility Owner
Company Name:	FREDERICK KIRSCHBAUM
Contact Type:	MANAGER
Contact Name:	GEORGE KIRSCHBAUM
Address1:	1935 S.E. 21ST
Address2:	Not reported

NEWTOWN USED AUTO PARTS/SCRAP METAL PROCESSOR (Continued) **A100295268**

City:	CAPE CORAL
State:	FL
Zip Code:	33990
Country Code:	001
Phone:	(347) 386-3391
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-05-05

Site Id:	363543
Affiliation Type:	Mail Contact
Company Name:	NEWTOWN USED AUTO PARTS/
Contact Type:	Not reported
Contact Name:	GEORGE KIRSCHBAUM
Address1:	SCRAP METAL PROCESSORS
Address2:	1074 GRAND STREET
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 599-2300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-05-05

Site Id:	363543
Affiliation Type:	Facility Operator
Company Name:	NEWTOWN USED AUTO PARTS/SCRAP METAL PROCESSOR
Contact Type:	Not reported
Contact Name:	FREDERICK KIRSCHBAUM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 599-2300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-05-05

Site Id:	363543
Affiliation Type:	Emergency Contact
Company Name:	FREDERICK KIRSCHBAUM
Contact Type:	Not reported
Contact Name:	GEORGE KIRSCHBAUM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 682-8858
EMail:	Not reported

NEWTOWN USED AUTO PARTS/SCRAP METAL PROCESSOR (Continued) **A100295268**

Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-05-05

Tank Info:

Tank Number:	1
Tank Id:	211521
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
I01 - Overfill - Float Vent Valve
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
H05 - Tank Leak Detection - In-Tank System (ATG)
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/2005
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/01/2010
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

W152 **NEWTOWN AUTO SALES & AUTO PARTS INC** **NY SWF/LF** **S108146024**
West **1074 GRAND STREET** **NY SPDES** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.211 mi.
1114 ft. **Site 2 of 6 in cluster W**

Relative:
Lower

Actual:
13 ft.

SWF/LF:

Name:	NEWTOWN AUTO SALES & AUTO PARTS INC
Address:	1074 GRAND STREET
City,State,Zip:	BROOKLYN, NY 11211
Flag:	INACTIVE
Region Code:	2
Phone Number:	7185992300
Owner Name:	New Town Used Auto Sales & Auto Parts; Inc.
Owner Type:	Private
Owner Address:	1074 Grand Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Email:	Not reported

NEWTOWN AUTO SALES & AUTO PARTS INC (Continued) **S108146024**

Owner Phone:	7185992300
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	VDF - large - registration
Activity Number:	[24V50009]
Active:	No
East Coordinate:	590127
North Coordinate:	4507524
Accuracy Code:	4.2 - Utilization of GIS and existing spatial data
Regulatory Status:	Registration
Waste Type:	End of Life Vehicles
Authorization #:	24V50009
Authorization Date:	2/27/2020
Expiration Date:	2/26/2025
Operator Name:	New Town Used Auto Sales & Auto Parts; Inc.
Operator Type:	Not reported
Laste Date:	Not reported

Name:	NEWTOWN AUTO SALES & AUTO PARTS INC
Address:	1074 GRAND STREET
City,State,Zip:	BROOKLYN, NY 11211
Flag:	INACTIVE
Region Code:	2
Phone Number:	7185992300
Owner Name:	New Town Used Auto Sales & Auto Parts; Inc.
Owner Type:	Private
Owner Address:	1074 Grand Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Email:	Not reported
Owner Phone:	7185992300
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[7096848]
Active:	No
East Coordinate:	590131
North Coordinate:	4507523
Accuracy Code:	4.2 - Utilization of GIS and existing spatial data
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	New Town Used Auto Sales & Auto Parts; Inc.
Operator Type:	Not reported
Laste Date:	Not reported

NEWTOWN AUTO SALES & AUTO PARTS INC (Continued) **S108146024**

SPDES:

Name:	NEW TOWN USED AUTO SALES & PARTS INC
Address:	1074 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211
Permit Number:	NYR00E019
State-Region:	02
Expiration Date:	09/30/2017
Current Major Minor Status:	Minor
Primary Facility SIC Code:	5015
State Water Body Name:	ENGLISH KILLS
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	+40.713 / -73.933
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	TABS CONSULTING GROUP INC
Non-Gov Permit Street Address:	NEW TOWN USED AUTO SALES & PARTS INC
Non-Gov Permit Supplemental Location:	2 52ND ST, BOX B11
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11223
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NEW TOWN USED AUTO SALES & PARTS INC
Non-Gov Facility Street Address:	NEW TOWN USED AUTO SALES & PARTS INC
Non-Gov Facility Supplemental Location:	1074 GRAND ST
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	NEW TOWN USED AUTO SALES & PARTS INC
Address:	1074 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	NEW TOWN USED AUTO SALES AND AUTO PARTS INC
Non-Gov Permit Street Address:	1074 GRAND ST
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN

NEWTOWN AUTO SALES & AUTO PARTS INC (Continued) **S108146024**

Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11211
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NEW TOWN USED AUTO SALES & PARTS INC
Non-Gov Facility Street Address:	NEW TOWN USED AUTO SALES & PARTS INC
Non-Gov Facility Supplemental Location:	1074 GRAND ST
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	NEW TOWN USED AUTO SALES & PARTS INC
Address:	1074 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	NEW TOWN USED AUTO SALES & PARTS INC
Non-Gov Facility Street Address:	NEW TOWN USED AUTO SALES & PARTS INC
Non-Gov Facility Supplemental Location:	1074 GRAND ST
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Q153 **GADS INC** **NY SWF/LF** **S107406892**
East **594 SCHOLES STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.213 mi.
1123 ft. **Site 2 of 4 in cluster Q**

Relative: **Higher**

Actual: **16 ft.**

SWF/LF:

Name:	GADS INC
Address:	594 SCHOLES STREET
City,State,Zip:	BROOKLYN, NY 11237
Flag:	ACTIVE
Region Code:	2
Phone Number:	7184162190
Owner Name:	Michael Allocco
Owner Type:	Private
Owner Address:	540 Kingsland Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Email:	Not reported
Owner Phone:	7183493094
Contact Name:	Anthony Strano
Contact Address:	594 Scholes Street
Contact Addr2:	Not reported
Contact City,St,Zip:	Brooklyn, NY 11237
Contact Email:	anthony@alloccorecycling.com
Contact Phone:	7184182190
Activity Desc:	C&D processing - permit
Activity Number:	[24WF7]
Active:	Yes
East Coordinate:	590889
North Coordinate:	4507379
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	Construction & Demolition Debris;Metals (Ferrous);Metals (Non-Ferrous);Concrete;Paper / Cardboard;Plastics;Wood (Chips);Wood (Unadulterated)
Authorization #:	2-6104-01347/00001
Authorization Date:	9/20/2021
Expiration Date:	9/16/2026
Operator Name:	Michael Allocco
Operator Type:	Private
Laste Date:	Not reported

Q154 **BFI WASTE SERVICES OF NJ, INC.** **NY AST** **A100159805**
East **594 SCHOLES STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.213 mi.
1123 ft. **Site 3 of 4 in cluster Q**

Relative: **Higher**

Actual: **16 ft.**

AST:

Name:	BFI WASTE SERVICES OF NJ, INC.
Address:	594 SCHOLES STREET
City,State,Zip:	BROOKLYN, NY 11237
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-604450
Program Type:	PBS
UTM X:	590901.87620
UTM Y:	4507326.39538

BFI WASTE SERVICES OF NJ, INC. (Continued) **A100159805**

Expiration Date: 02/25/2010
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:
Site Id: 26324
Affiliation Type: Facility Owner
Company Name: BFI WAST SERVICES OF NJ, INC.
Contact Type: GENERAL MANAGER
Contact Name: NICHOLAS FYTROS
Address1: 72 SCOTT AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11237
Country Code: 001
Phone: (718) 497-4000
EMail: Not reported
Fax Number: Not reported
Modified By: EXROSSAN
Date Last Modified: 2005-03-28

Site Id: 26324
Affiliation Type: Mail Contact
Company Name: BFI WASTE SERVICES OF NJ, INC.
Contact Type: Not reported
Contact Name: SAM RIVERA, MAINT MGR
Address1: 72 SCOTT AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11237
Country Code: 001
Phone: (718) 497-4000
EMail: Not reported
Fax Number: Not reported
Modified By: KXTANG
Date Last Modified: 2005-02-16

Site Id: 26324
Affiliation Type: Facility Operator
Company Name: BFI WASTE SERVICES OF NJ, INC.
Contact Type: Not reported
Contact Name: SAM RIVERA/MAINT MANAGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NY
Zip Code: Not reported
Country Code: 001
Phone: (718) 497-4000
EMail: Not reported
Fax Number: Not reported
Modified By: EXROSSAN
Date Last Modified: 2005-03-28

Site Id: 26324
Affiliation Type: Emergency Contact
Company Name: BFI WAST SERVICES OF NJ, INC.

BFI WASTE SERVICES OF NJ, INC. (Continued) **A100159805**

Contact Type:	Not reported
Contact Name:	SAM RIVERA/MAINT MANAGER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 497-5169 119
EMail:	Not reported
Fax Number:	Not reported
Modified By:	EXROSSAN
Date Last Modified:	2005-03-28

Tank Info:

Tank Number:	01
Tank Id:	57797
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

J02 - Dispenser - Suction Dispenser
G04 - Tank Secondary Containment - Double-Walled (Underground)
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I02 - Overfill - High Level Alarm
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/1999
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	KXTANG
Last Modified:	04/14/2017
Material Name:	diesel

T155 **CON EDISON - MANHOLE 43894** **RCRA-LQG** **1016150117**
South **VARICK AVE** **NYP004287884**
1/8-1/4 **BROOKLYN, NY 11237**
0.213 mi.
1125 ft. **Site 6 of 7 in cluster T**

Relative: **Lower**
Actual: **13 ft.**

RCRA-LQG:

Date Form Received by Agency:	20140327
Handler Name:	CON EDISON - MANHOLE 43894
Handler Address:	VARICK AVE
Handler City,State,Zip:	BROOKLYN, NY 11237
EPA ID:	NYP004287884
Contact Name:	DENNIS HUACON
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	518-473-8034
Contact Email:	HUACOND@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner Type:	Private
Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON - MANHOLE 43894 (Continued) **1016150117**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20130208
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private

CON EDISON - MANHOLE 43894 (Continued) **1016150117**

Date Became Current: 20130208
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140327
Handler Name: CON EDISON - MANHOLE 43894
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20130208
Handler Name: CON EDISON MANHOLE: 43894
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

T156 **CON EDISON** **NY MANIFEST** **S119073535**
South **VARICK AVE** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.213 mi.
1125 ft. **Site 7 of 7 in cluster T**

Relative:
Lower

Actual:
13 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	VARICK AVE
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP004287884
Facility Status:	Not reported
Location Address 1:	OPP 98 VARICK AVE
Code:	BP
Location Address 2:	MH 43894
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11211
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004287884
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	02/08/2013
Trans1 Recv Date:	02/08/2013
Trans2 Recv Date:	02/11/2013
TSD Site Recv Date:	02/11/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004287884
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002015966GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S119073535**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q157 **BFI (598-636 SCHOLES STREET)** **NY SWF/LF** **S112258024**
East **598-636 SCHOLES STREET** **NY SWRCY** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.215 mi.
1137 ft. **Site 4 of 4 in cluster Q**

Relative: **Higher**

Actual: **16 ft.**

SWF/LF:

Name:	BFI (598-636 SCHOLES STREET)
Address:	598-636 SCHOLES STREET
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	6102866844
Owner Name:	BFI Waste Systems of New Jersey
Owner Type:	Private
Owner Address:	420 Quarry Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Morgantown, PA 19543
Owner Email:	Not reported
Owner Phone:	6102866844
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[24T25]
Active:	No
East Coordinate:	590859
North Coordinate:	4507332
Accuracy Code:	Not reported

BFI (598-636 SCHOLES STREET) (Continued) **S112258024**

Regulatory Status:	None
Waste Type:	MSW (Residential/Institutional & Commercial)
Authorization #:	2-6104-00022/00001
Authorization Date:	11/30/2010
Expiration Date:	11/30/2015
Operator Name:	Mark Pedersen
Operator Type:	Private
Laste Date:	Not reported

SWRCY:

Name:	BFI (598-636 SCHOLES STREET)
Address:	598-636 SCHOLES STREET
City,State,Zip:	BROOKLYN, NY 11237
Region:	2
Facility Address 2:	Not reported
Phone Number:	6102866844
Owner Type:	Private
Owner Name:	BFI Waste Systems of New Jersey
Owner Address:	420 Quarry Road
Owner Address 2:	Not reported
Owner City,St,Zip:	Morgantown, PA 19543
Owner Email:	Not reported
Owner Phone:	6102866844
Contact Name:	Not reported
Contact Address:	Not reported
Contact Address 2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	RHRF - registration
Activity Number:	[24M25]
Active:	No
East Coordinate:	590859
North Coordinate:	4507332
Accuracy Code:	Not reported
Regulatory Status:	None
Permit #:	2-6104-00022/00001
Auth. Date:	11/30/2010
Expiration Date:	11/30/2015
Waste Types:	Commingled Recyclables;Commingled Paper
Operator Name:	Mark Pedersen
Operator Type:	Private
Last Date:	Not reported

W158 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S100346426**
WNW **1105 METROPOLITAN AV** **N/A**
1/8-1/4 **NYC, NY**
0.217 mi.
1144 ft. **Site 3 of 6 in cluster W**

Relative:
Lower

Actual:
11 ft.

LTANKS:

Name:	CLOSED-LACKOF RECENT INFO
Address:	1105 METROPOLITAN AV
City,State,Zip:	NYC, NY
Spill Number/Closed Date:	8802460 / 2003-03-05
Facility ID:	8802460
Site ID:	183945

CLOSED-LACKOF RECENT INFO (Continued) **S100346426**

Spill Date:	1988-06-17
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1988-06-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-06-24
Spill Record Last Update:	2003-03-18
Spiller Name:	CONTACT JOE
Spiller Company:	STERLING OPTICAL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	153958
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ADMIN.CLOSED / / : Replace Vent Line, Empty Tank & Retest. 03/05/2003- Closed Due To The Nature / Extent Of The Spill Report"
Remarks:	"L R =-20 GPH. NEVER STABILIZED 7.5K TANK.CLOSED DUE TO LACK OF ANY RECENT INFO- DOES NOT MEET ANY CLEAN UP REQUIREMENTS."

All TTF:

Facility ID:	8802460
Spill Number:	8802460
Spill Tank Test:	1534139
Site ID:	183945
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	183945
Operable Unit ID:	919680
Operable Unit:	01

CLOSED-LACKOF RECENT INFO (Continued) **S100346426**

Material ID:	458025
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

159 WNW 1/8-1/4 0.222 mi. 1171 ft.
1101 METROPOLITAN AVE
1101 METROPOLITAN AVE
BROOKLYN, NY

NY LTANKS **S103238306** **N/A**

Relative: Lower
Actual: 10 ft.

LTANKS:

Name:	1101 METROPOLITAN AVE
Address:	1101 METROPOLITAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9800642 / 2006-05-17
Facility ID:	9800642
Site ID:	190461
Spill Date:	1998-04-15
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1998-04-15
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-04-15
Spill Record Last Update:	2006-05-17
Spiller Name:	USA TANKS
Spiller Company:	1101 METROPOLITIAN AVE
Spiller Address:	1101 METROPOLITIAN AVE
Spiller County:	001
Spiller Contact:	USA TANKS
Spiller Phone:	(718) 384-9151
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	158882
DEC Memo:	"5/17/06 - Mike - PBS# 2-109932 Tank was closed in place. Only one tank exsisted at site, Spill Report suggests tank #2 failed but there is no #2 tank. Occupant has documentation for proper closing and of no contamination. March 20, 2006 - have not worked on this spill to date - Jones Next Step - establish contact with site owner as per spill report."

1101 METROPOLITAN AVE (Continued) **S103238306**

Remarks: "TESTED TANK.TANK FAILED."

All TTF:

Facility ID:	9800642
Spill Number:	9800642
Spill Tank Test:	1545783
Site ID:	190461
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	190461
Operable Unit ID:	1061125
Operable Unit:	01
Material ID:	322598
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

X160 **BLINN DRUG CO** **NY UST** **U000396985**
NW **16 REWE ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.222 mi.
1173 ft. **Site 1 of 3 in cluster X**

Relative: **Lower**

Actual: **4 ft.**

UST:

Name:	BLINN DRUG CO
Address:	16 REWE ST
City,State,Zip:	BROOKLYN, NY 11211
Id/Status:	2-117501 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590278.47170
UTM Y:	4507804.03037
Site Type:	Other

Affiliation Records:

Site Id:	4009
Affiliation Type:	Facility Owner

BLINN DRUG CO (Continued) **U000396985**

Company Name:	BLINN DRUG CO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	16 REWE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 963-1606
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4009
Affiliation Type:	Mail Contact
Company Name:	BLINN DRUG CO
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	16 REWE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 963-1606
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4009
Affiliation Type:	Facility Operator
Company Name:	BLINN DRUG CO
Contact Type:	Not reported
Contact Name:	WILLIAM BLINDERMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 963-1606
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4009
Affiliation Type:	Emergency Contact
Company Name:	BLINN DRUG CO
Contact Type:	Not reported
Contact Name:	WILLIAM BLINDERMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported

BLINN DRUG CO (Continued) **U000396985**

State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 963-1606
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 8583
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 3000
Install Date: Not reported
Date Tank Closed: 03/01/2000
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 03
Date Test: 02/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Y161 **A&I REALTY** **RCRA NonGen / NLR** **1023968722**
NNW **20 REWE ST** **FINDS** **NYR000233767**
1/8-1/4 **BROOKLYN, NY 11211**
0.224 mi.
1182 ft. **Site 1 of 3 in cluster Y**

Relative:
Lower

Actual:
3 ft.

RCRA NonGen / NLR:

Date Form Received by Agency: 20180912
Handler Name: A&I REALTY
Handler Address: 20 REWE ST
Handler City,State,Zip: BROOKLYN, NY 11211
EPA ID: NYR000233767
Contact Name: JIM HOLIBER
Contact Address: E TREMONT AVE
Contact City,State,Zip: BRONX, NY 10461
Contact Telephone: 718-792-8800 1002

A&I REALTY (Continued) **1023968722**

Contact Fax:	718-408-2021
Contact Email:	JHOLIBER@MARJAM.COM
Contact Title:	CHIEF COUNSEL
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	E TREMONT AVE
Mailing City,State,Zip:	BRONX, NY 10461
Owner Name:	A&I REALTY CORP
Owner Type:	Private
Operator Name:	MARJAM SUPPLY CO INC AS TENANT
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

A&I REALTY (Continued) **1023968722**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180912
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D004
Waste Description:	ARSENIC
Waste Code:	D005
Waste Description:	BARIUM
Waste Code:	D006
Waste Description:	CADMIUM
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D009
Waste Description:	MERCURY
Waste Code:	D010
Waste Description:	SELENIUM
Waste Code:	D011
Waste Description:	SILVER
Waste Code:	D012
Waste Description:	ENDRIN (1,2,3,4,10,10-HEXACHLORO-1,7-EPOXY-1,4,4A,5,6,7,8,8A-OCTAHYDRO-1,4-ENDO, ENDO-5,8-DIMETH-ANO-NAPHTHALENE)
Waste Code:	D013
Waste Description:	LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER)
Waste Code:	D014
Waste Description:	METHOXYCHLOR (1,1,1-TRICHLORO-2,2-BIS [P-METHOXYPHENYL] ETHANE)
Waste Code:	D015
Waste Description:	TOXAPHENE (C10 H10 CL8, TECHNICAL CHLORINATED CAMPHENE, 67-69 PERCENT CHLORINE)

A&I REALTY (Continued) **1023968722**

Waste Code: D016
Waste Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Waste Code: D017
Waste Description: 2,4,5-TP SILVEX (2,4,5-TRICHLOROPHENOXYPROPIONIC ACID)

Waste Code: D018
Waste Description: BENZENE

Waste Code: D019
Waste Description: CARBON TETRACHLORIDE

Waste Code: D020
Waste Description: CHLORDANE

Waste Code: D021
Waste Description: CHLOROBENZENE

Waste Code: D022
Waste Description: CHLOROFORM

Waste Code: D023
Waste Description: O-CRESOL

Waste Code: D024
Waste Description: M-CRESOL

Waste Code: D025
Waste Description: P-CRESOL

Waste Code: D026
Waste Description: CRESOL

Waste Code: D027
Waste Description: 1,4-DICHLOROBENZENE

Waste Code: D028
Waste Description: 1,2-DICHLOROETHANE

Waste Code: D029
Waste Description: 1,1-DICHLOROETHYLENE

Waste Code: D030
Waste Description: 2,4-DINITROTOLUENE

Waste Code: D031
Waste Description: HEPTACHLOR (AND ITS EPOXIDE)

Waste Code: D032
Waste Description: HEXACHLOROBENZENE

Waste Code: D033
Waste Description: HEXACHLOROBUTADIENE

Waste Code: D034
Waste Description: HEXACHLOROETHANE

A&I REALTY (Continued) **1023968722**

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

Waste Code: D036
Waste Description: NITROBENZENE

Waste Code: D037
Waste Description: PENTACHLOROPHENOL

Waste Code: D038
Waste Description: PYRIDINE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: A&I REALTY CORP
Legal Status: Private
Date Became Current: 19830718
Date Ended Current: Not reported
Owner/Operator Address: 885 CONKLIN ST
Owner/Operator City,State,Zip: FARMINGDALE, NY 11735
Owner/Operator Telephone: 718-792-8800
Owner/Operator Telephone Ext: 1002
Owner/Operator Fax: 718-408-2021
Owner/Operator Email: JHOLIBER@MARJAM.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: MARJAM SUPPLY CO INC AS TENANT
Legal Status: Private
Date Became Current: 19830718
Date Ended Current: Not reported
Owner/Operator Address: 885 CONKLIN ST
Owner/Operator City,State,Zip: FARMINGDALE, NY 11735
Owner/Operator Telephone: 718-792-8800
Owner/Operator Telephone Ext: 1002
Owner/Operator Fax: 718-408-2021
Owner/Operator Email: JHOLIBER@MARJAM.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: MARJAM SUPPLY CO INC AS TENANT
Legal Status: Private
Date Became Current: 19830718
Date Ended Current: Not reported
Owner/Operator Address: 885 CONKLIN ST
Owner/Operator City,State,Zip: FARMINGDALE, NY 11735
Owner/Operator Telephone: 718-792-8800
Owner/Operator Telephone Ext: 1002
Owner/Operator Fax: 718-408-2021
Owner/Operator Email: JHOLIBER@MARJAM.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: A&I REALTY CORP
Legal Status: Private
Date Became Current: 19830718
Date Ended Current: Not reported
Owner/Operator Address: 885 CONKLIN ST
Owner/Operator City,State,Zip: FARMINGDALE, NY 11735
Owner/Operator Telephone: 718-792-8800

A&I REALTY (Continued) **1023968722**

Owner/Operator Telephone Ext: 1002
Owner/Operator Fax: 718-408-2021
Owner/Operator Email: JHOLIBER@MARJAM.COM

Historic Generators:
Receive Date: 20180912
Handler Name: A&I REALTY
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20171101
Handler Name: A&I REALTY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 42331
NAICS Description: LUMBER, PLYWOOD, MILLWORK, AND WOOD PANEL MERCHANT WHOLESALERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110070205728

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

A&I REALTY (Continued) **1023968722**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Y162 **A&I REALTY** **NY MANIFEST** **S121968986**
NNW **20 REWE ST** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.224 mi.
1182 ft. **Site 2 of 3 in cluster Y**

Relative: **Lower**
Actual: **3 ft.**

NY MANIFEST:

Name:	A&I REALTY
Address:	20 REWE ST
City,State,Zip:	BROOKLYN, NY 11211
Country:	USA
EPA ID:	NYR000233767
Facility Status:	Not reported
Location Address 1:	20 REWE ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11211
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000233767
Mailing Name:	A&I REALTY
Mailing Contact:	A&I REALTY
Mailing Address 1:	20 REWE ST
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11211
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

W163 **ACME ALBERT STEEL DRUM INC** **RCRA NonGen / NLR** **1000195208**
West **1050 GRAND ST** **FINDS** **NYD000390716**
1/8-1/4 **BROOKLYN, NY 11211** **ECHO**
0.224 mi. **NY MANIFEST**
1184 ft. **Site 4 of 6 in cluster W**

Relative: **Higher**
Actual: **14 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	ACME ALBERT STEEL DRUM INC
Handler Address:	1050 GRAND ST
Handler City,State,Zip:	BROOKLYN, NY 11211-1701
EPA ID:	NYD000390716
Contact Name:	Not reported
Contact Address:	GRAND ST
Contact City,State,Zip:	BROOKLYN, NY 11211
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported

ACME ALBERT STEEL DRUM INC (Continued) **1000195208**

Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	GRAND ST
Mailing City,State,Zip:	BROOKLYN, NY 11211
Owner Name:	ACME ALBERT STEEL DRUM INC
Owner Type:	Private
Operator Name:	ACME ALBERT STEEL DRUM INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported

ACME ALBERT STEEL DRUM INC (Continued) **1000195208**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F017
Waste Description:	Not Defined
Waste Code:	U220
Waste Description:	BENZENE, METHYL- (OR) TOLUENE
Waste Code:	U239
Waste Description:	BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ACME ALBERT STEEL DRUM INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	ACME ALBERT STEEL DRUM INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

ACME ALBERT STEEL DRUM INC (Continued) **1000195208**

Owner/Operator Indicator: Operator
Owner/Operator Name: ACME ALBERT STEEL DRUM INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990708
Handler Name: ACME ALBERT STEEL DRUM INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: ACME ALBERT STEEL DRUM INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ACME ALBERT STEEL DRUM INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800818
Handler Name: ACME ALBERT STEEL DRUM INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No

ACME ALBERT STEEL DRUM INC (Continued) **1000195208**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 42184
NAICS Description: INDUSTRIAL SUPPLIES WHOLESALERS

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 19850605
Actual Return to Compliance Date: 19860212
Return to Compliance Qualifier: Observed
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported

ACME ALBERT STEEL DRUM INC (Continued) **1000195208**

Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19850605
Actual Return to Compliance Date: 19860212
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19860110
Enforcement Identifier: 001
Date of Enforcement Action: 19851210
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYDEC

ACME ALBERT STEEL DRUM INC (Continued) **1000195208**

Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19850605
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19860212
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19990902
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2TM
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19850605
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19860212
Scheduled Compliance Date: 19860110
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:

ACME ALBERT STEEL DRUM INC (Continued) **1000195208**

Registry ID: 110001573761

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000195208
Registry ID:	110001573761
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110001573761
Name:	ACME ALBERT STEEL DRUM INC
Address:	1050 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211

NY MANIFEST:

Name:	ACME ALBERT STEEL DRUM INC
Address:	1050 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211-1701
Country:	USA
EPA ID:	NYD000390716
Facility Status:	Not reported
Location Address 1:	1050 GRAND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11211
Location Zip 4:	1701

NY MANIFEST:

EPAID:	NYD000390716
Mailing Name:	ACME ALBERT STEEL DRUM INC
Mailing Contact:	SEIGEL GERALD PRES
Mailing Address 1:	1050 GRAND ST
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11211
Mailing Zip 4:	1701
Mailing Country:	USA
Mailing Phone:	2123841616

X164 **12 REWE STREET LLC** **NY AST** **A100293860**
NW **12 REWE STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.226 mi.
1191 ft. **Site 2 of 3 in cluster X**

Relative:
Lower

Actual:
5 ft.

AST:

Name:	12 REWE STREET LLC
Address:	12 REWE STREET
City,State,Zip:	BROOKLYN, NY 11211
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-608670
Program Type:	PBS
UTM X:	590246.73166
UTM Y:	4507792.59936
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

Site Id:	30522
Affiliation Type:	Facility Owner
Company Name:	12 REWE STREET LLC
Contact Type:	Not reported
Contact Name:	PAUL BARY
Address1:	20 REWE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-6465
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-01-19

Site Id:	30522
Affiliation Type:	Mail Contact
Company Name:	12 REWE STREET LLC
Contact Type:	Not reported
Contact Name:	JM HOLIBER
Address1:	20 REWE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-6465
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-01-19

Site Id:	30522
Affiliation Type:	Facility Operator
Company Name:	12 REWE STREET LLC
Contact Type:	Not reported
Contact Name:	PAUL BANY

12 REWE STREET LLC (Continued) **A100293860**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-6465
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2017-05-25

Site Id:	30522
Affiliation Type:	Emergency Contact
Company Name:	12 REWE STREET LLC
Contact Type:	Not reported
Contact Name:	PAUL BARY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(631) 682-3074
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-01-19

Tank Info:

Tank Number:	01
Tank Id:	65474
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	J02 - Dispenser - Suction Dispenser
	G00 - Tank Secondary Containment - None
	H00 - Tank Leak Detection - None
	I02 - Overfill - High Level Alarm
	L09 - Piping Leak Detection - Exempt Suction Piping
	B00 - Tank External Protection - None
	F00 - Pipe External Protection - None
	C01 - Pipe Location - Aboveground
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/28/2016
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported

12 REWE STREET LLC (Continued) **A100293860**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	DMPOKRZY
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

X165 **12 REWE STREET LLC** **NY UST** **U004062595**
NW **12 REWE STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.226 mi.
1191 ft. **Site 3 of 3 in cluster X**

Relative:
Lower

Actual:
5 ft.

UST:

Name:	12 REWE STREET LLC
Address:	12 REWE STREET
City,State,Zip:	BROOKLYN, NY 11211
Id/Status:	2-608670 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590246.73166
UTM Y:	4507792.59936
Site Type:	Other

Affiliation Records:

Site Id:	30522
Affiliation Type:	Facility Owner
Company Name:	12 REWE STREET LLC
Contact Type:	Not reported
Contact Name:	PAUL BARY
Address1:	20 REWE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-6465
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-01-19

Site Id:	30522
Affiliation Type:	Mail Contact
Company Name:	12 REWE STREET LLC
Contact Type:	Not reported
Contact Name:	JM HOLIBER
Address1:	20 REWE ST
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-6465
EMail:	Not reported
Fax Number:	Not reported

12 REWE STREET LLC (Continued) **U004062595**

Modified By: DMPOKRZY
Date Last Modified: 2017-01-19

Site Id: 30522
Affiliation Type: Facility Operator
Company Name: 12 REWE STREET LLC
Contact Type: Not reported
Contact Name: PAUL BANY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 388-6465
EMail: Not reported
Fax Number: Not reported
Modified By: JAAVERSA
Date Last Modified: 2017-05-25

Site Id: 30522
Affiliation Type: Emergency Contact
Company Name: 12 REWE STREET LLC
Contact Type: Not reported
Contact Name: PAUL BARY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (631) 682-3074
EMail: Not reported
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-01-19

Tank Info:

Tank Number: 100
Tank ID: 66160
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 5000
Install Date: 10/28/2016
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DMPOKRZY

12 REWE STREET LLC (Continued) **U004062595**

Last Modified: 04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I05 - Overfill - Vent Whistle

U166 **AVALANCHE CONTRACTING; INC. (COTOIA)** **NY SWF/LF** **S108950342**
ENE **46-26 METROPOLITAN AVENUE** **N/A**
1/8-1/4 **MASPETH, NY 11378**
0.227 mi.
1196 ft. **Site 3 of 5 in cluster U**

Relative: **Lower**
Actual: **11 ft.**

SWF/LF:

Name:	AVALANCHE CONTRACTING; INC. (COTOIA)
Address:	46-26 METROPOLITAN AVENUE
City,State,Zip:	MASPETH, NY 11378
Flag:	INACTIVE
Region Code:	2
Phone Number:	7183811134
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	MARCANGELO COTOIA
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[41W29]
Active:	No
East Coordinate:	590922
North Coordinate:	4507548
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	2-6305-00020
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

167
NE
1/8-1/4
0.230 mi.
1217 ft.

CHARLES J KING INC
1301 GRAND ST
BROOKLYN, NY 11211

NY SWF/LF **1000231689**
NY UST **NYD012573648**
NY SWRCY
RCRA NonGen / NLR
NY SPDES

Relative:
Lower

Actual:
6 ft.

SWF/LF:

Name:	EMPIRE METAL TRADING LLC
Address:	1301 GRAND STREET
City,State,Zip:	BROOKLYN, NY 11211
Flag:	ACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Charles J. King Inc.
Owner Type:	Not reported
Owner Address:	1301 Grand Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Email:	wdking@att.net
Owner Phone:	7184975571
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Scrap metal processor - registration
Activity Number:	[24V30001]
Active:	Yes
East Coordinate:	590770
North Coordinate:	4507777
Accuracy Code:	4.2 - Utilization of GIS and existing spatial data
Regulatory Status:	Registration
Waste Type:	Scrap Metal - Ferrous ;Scrap Metal - Non-ferrous
Authorization #:	24V30001
Authorization Date:	11/8/2019
Expiration Date:	11/7/2024
Operator Name:	Empire Metal Trading LLC
Operator Type:	Not reported
Laste Date:	Not reported

UST:

Name:	EMPIRE METAL TRADING LLC
Address:	1301 GRAND STREET
City,State,Zip:	BROOKLYN, NY 11211
Id/Status:	2-001074 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	04/15/2026
UTM X:	590762.19992
UTM Y:	4507778.16059
Site Type:	Other

Affiliation Records:

Site Id:	11
Affiliation Type:	Mail Contact
Company Name:	EMPIRE METAL TRADING LLC
Contact Type:	Not reported

CHARLES J KING INC (Continued) **1000231689**

Contact Name:	WAYNE KING
Address1:	1301 GRAND STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 497-1950
EMail:	WAYNE@EMPIREMETALTRADING.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-09-29

Site Id:	11
Affiliation Type:	Facility Operator
Company Name:	CHARLES J. KING INC.
Contact Type:	Not reported
Contact Name:	WAYNE KING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 497-1950
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-09-29

Site Id:	11
Affiliation Type:	Emergency Contact
Company Name:	CHARLES J. KING INC.
Contact Type:	Not reported
Contact Name:	WAYNE KING
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 497-1950
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-09-29

Site Id:	11
Affiliation Type:	Facility Owner
Company Name:	CHARLES J. KING INC.
Contact Type:	MEMBER
Contact Name:	WAYNE KING
Address1:	1301 GRAND STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211

CHARLES J KING INC (Continued) **1000231689**

Country Code:	001
Phone:	(718) 497-5571
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-04-11

Tank Info:

Tank Number:	01
Tank ID:	701
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1957
Date Tank Closed:	11/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	02
Date Test:	05/01/1996
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Number:	02
Tank ID:	51086
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	12/01/1957
Date Tank Closed:	11/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	02
Date Test:	05/01/1996
Next Test Date:	Not reported

CHARLES J KING INC (Continued) **1000231689**

Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Number: 03
Tank ID: 702
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 12/01/1958
Date Tank Closed: 11/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 02
Date Test: 06/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H99 - Tank Leak Detection - Other

Tank Number: 04
Tank ID: 51087
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 12/01/1958
Date Tank Closed: 11/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

CHARLES J KING INC (Continued) **1000231689**

Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 02
Date Test: 06/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

H99 - Tank Leak Detection - Other
G03 - Tank Secondary Containment - Vault (w/o access)
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 05
Tank ID: 703
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 1080
Install Date: 02/08/1974
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 21
Date Test: 08/15/2016
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DAFRANCI
Last Modified: 04/11/2019

Equipment Records:

F99 - Pipe External Protection - Other
H05 - Tank Leak Detection - In-Tank System (ATG)
D11 - Pipe Type - Flexible Piping
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E04 - Piping Secondary Containment - Double walled UG
I03 - Overfill - Automatic Shut-Off
A01 - Tank Internal Protection - Epoxy Liner
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping

CHARLES J KING INC (Continued) **1000231689**

Tank Number:	06
Tank ID:	51088
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1080
Install Date:	02/08/1974
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	21
Date Test:	08/15/2016
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DAFRANCI
Last Modified:	04/11/2019

Equipment Records:

F99 - Pipe External Protection - Other
H05 - Tank Leak Detection - In-Tank System (ATG)
A01 - Tank Internal Protection - Epoxy Liner
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I03 - Overfill - Automatic Shut-Off
D11 - Pipe Type - Flexible Piping

SWRCY:

Name:	CHARLES J KING INC
Address:	1301 GRAND STREET
City,State,Zip:	BROOKLYN, NY 11211
Region:	2
Facility Address 2:	Not reported
Phone Number:	7184971950
Owner Type:	Not reported
Owner Name:	Charles J King Inc
Owner Address:	1301 Grand Street
Owner Address 2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Email:	wdking@att.net
Owner Phone:	7184971950
Contact Name:	Wayne KIng
Contact Address:	Not reported
Contact Address 2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	wdking@att;net
Contact Phone:	7184971950
Activity Desc:	RHRF - exempt (non-VDF)
Activity Number:	[24M00]

CHARLES J KING INC (Continued) **1000231689**

Active:	No
East Coordinate:	590770
North Coordinate:	4507777
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Permit #:	Not reported
Auth. Date:	Not reported
Expiration Date:	Not reported
Waste Types:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Last Date:	Not reported

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	CHARLES J KING INC	
Handler Address:		1301 GRAND ST
Handler City,State,Zip:		BROOKLYN, NY 11211-1802
EPA ID:		NYD012573648
Contact Name:		Not reported
Contact Address:		GRAND ST
Contact City,State,Zip:		BROOKLYN, NY 11211
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		GRAND ST
Mailing City,State,Zip:		BROOKLYN, NY 11211
Owner Name:		CHARLES J KING INC
Owner Type:		Private
Operator Name:		CHARLES J KING INC
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

CHARLES J KING INC (Continued) **1000231689**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CHARLES J KING INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CHARLES J KING INC
Legal Status:	Private

CHARLES J KING INC (Continued) **1000231689**

Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	CHARLES J KING INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: CHARLES J KING INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: CHARLES J KING INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name: CHARLES J KING INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

CHARLES J KING INC (Continued) **1000231689**

Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19800625
Handler Name:	CHARLES J KING INC
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	42193
NAICS Description:	RECYCLABLE MATERIAL WHOLESALERS

Facility Has Received Notices of Violation:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported

CHARLES J KING INC (Continued) **1000231689**

Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19981023
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2MD
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

SPDES:

Name:	EMPIRE METAL TRADING LLC
Address:	1301 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211
Permit Number:	NYR00A895
State-Region:	02
Expiration Date:	09/30/2017
Current Major Minor Status:	Minor
Primary Facility SIC Code:	5093
State Water Body Name:	ENGLISH KILLS, NEWTOWN CREEK
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	40.717 / -73.929
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	CHARLES J KING INC
Non-Gov Permit Street Address:	EMPIRE METAL TRADING LLC
Non-Gov Permit Supplemental Location:	1301 GRAND ST
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11211
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	CHARLES J KING INC
Non-Gov Facility Street Address:	CHARLES J KING INC
Non-Gov Facility Supplemental Location:	1301 GRAND ST
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	Not reported
Region Permit Processed:	Not reported

CHARLES J KING INC (Continued) **1000231689**

Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	EMPIRE METAL TRADING LLC
Address:	1301 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	CHARLES J KING INC
Non-Gov Permit Street Address:	1301 GRAND ST
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11211
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	CHARLES J KING INC
Non-Gov Facility Street Address:	CHARLES J KING INC
Non-Gov Facility Supplemental Location:	1301 GRAND ST
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	EMPIRE METAL TRADING LLC
Address:	1301 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	CHARLES J KING INC
Non-Gov Facility Street Address:	CHARLES J KING INC
Non-Gov Facility Supplemental Location:	1301 GRAND ST

CHARLES J KING INC (Continued) **1000231689**

Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

W168 **GRAND PETROLEUM, LLC** **NY UST** **U000410022**
West **1049 GRAND STREET** **N/A**
1/8-1/4 **BROOKLYN, NY 11211**
0.232 mi.
1223 ft. **Site 5 of 6 in cluster W**

Relative:
Higher

Actual:
15 ft.

UST:

Name:	GRAND PETROLEUM, LLC
Address:	1049 GRAND STREET
City,State,Zip:	BROOKLYN, NY 11211
Id/Status:	2-456969 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	10/21/2023
UTM X:	590088.27907
UTM Y:	4507533.91091
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	20169
Affiliation Type:	Emergency Contact
Company Name:	ATLANTIS MANAGEMENT GROUP II, LLC
Contact Type:	Not reported
Contact Name:	ENVIRONMENTAL HELPDESK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(914) 699-9500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-10-21

Site Id:	20169
Affiliation Type:	Mail Contact
Company Name:	ATLANTIS MANAGEMENT GROUP II LLC
Contact Type:	Not reported
Contact Name:	ALPER KADIOGLU
Address1:	555 S. COLUMBUS AVENUE
Address2:	SUITE 201
City:	MOUNT VERNON
State:	NY

GRAND PETROLEUM, LLC (Continued) **U000410022**

Zip Code:	10550
Country Code:	001
Phone:	(914) 699-9500
EMail:	ALPER@ATLANTISMGMT.COM
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-02-24

Site Id:	20169
Affiliation Type:	Facility Operator
Company Name:	GRAND PETROLEUM, LLC
Contact Type:	Not reported
Contact Name:	ADNAN TAHINCIOGLU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 599-1549
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-08-13

Site Id:	20169
Affiliation Type:	Facility Owner
Company Name:	ATLANTIS MANAGEMENT GROUP II, LLC
Contact Type:	MEMBER
Contact Name:	ALPER KADIOGLU
Address1:	555 S. COLUMBUS AVE., SUITE 201
Address2:	Not reported
City:	MOUNT VERNON
State:	NY
Zip Code:	10550
Country Code:	001
Phone:	(914) 699-9500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2018-08-10

Tank Info:

Tank Number:	001
Tank ID:	172965
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	Not reported
Date Tank Closed:	07/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0009
Common Name of Substance:	Gasoline

GRAND PETROLEUM, LLC (Continued) **U000410022**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: cgfreedm
Last Modified: 04/14/2017

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
F03 - Pipe External Protection - Original Impressed Current
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin

Tank Number: 001-A
Tank ID: 6812
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 03
Date Test: 03/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Tank Number: 002
Tank ID: 172858
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 6000
Install Date: Not reported
Date Tank Closed: 02/01/2001
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported

GRAND PETROLEUM, LLC (Continued) **U000410022**

Modified By: cgfreedm
Last Modified: 04/14/2017

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
C02 - Pipe Location - Underground/On-ground
F03 - Pipe External Protection - Original Impressed Current
J01 - Dispenser - Pressurized Dispenser

Tank Number: 002-A
Tank ID: 172859
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 03
Date Test: 03/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Tank Number: 003
Tank ID: 172869
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 6000
Install Date: Not reported
Date Tank Closed: 02/01/2001
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: cgfreedm
Last Modified: 04/14/2017

GRAND PETROLEUM, LLC (Continued) **U000410022**

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)
F03 - Pipe External Protection - Original Impressed Current
C02 - Pipe Location - Underground/On-ground
J01 - Dispenser - Pressurized Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)

Tank Number:	003-A
Tank ID:	172870
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	03
Date Test:	03/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Tank Number:	004
Tank ID:	36753
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	03
Date Test:	03/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel

GRAND PETROLEUM, LLC (Continued) **U000410022**

F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 005
Tank ID: 36754
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 03/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 006
Tank ID: 36755
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 03/01/1993
Next Test Date: Not reported

GRAND PETROLEUM, LLC (Continued) **U000410022**

Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 007
Tank ID: 36756
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 03/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 008
Tank ID: 36757
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

GRAND PETROLEUM, LLC (Continued) **U000410022**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 03/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 009
Tank ID: 36758
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 03/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 010
Tank ID: 36759
Tank Status: Closed - Removed
Material Name: Closed - Removed

GRAND PETROLEUM, LLC (Continued) **U000410022**

Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	03/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	011
Tank ID:	36760
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	03/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

GRAND PETROLEUM, LLC (Continued) **U000410022**

Tank Number:	012
Tank ID:	36761
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	03/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	013
Tank ID:	36762
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	03/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

GRAND PETROLEUM, LLC (Continued) **U000410022**

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	014
Tank ID:	36763
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	03
Date Test:	03/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	015
Tank ID:	36764
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

GRAND PETROLEUM, LLC (Continued) **U000410022**

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	016
Tank ID:	36765
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	017
Tank ID:	36766
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

GRAND PETROLEUM, LLC (Continued) **U000410022**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 018
Tank ID: 36767
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 1
Tank ID: 172948
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 12000
Install Date: 09/01/2003
Date Tank Closed: Not reported

GRAND PETROLEUM, LLC (Continued) **U000410022**

Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	14
Date Test:	01/27/2004
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSBAPTIS
Last Modified:	04/14/2017

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	1-A
Tank ID:	172950
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	03/01/2002
Date Tank Closed:	01/01/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Tank Number:	2
Tank ID:	172951
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	12000
Install Date:	09/01/2003
Date Tank Closed:	Not reported

GRAND PETROLEUM, LLC (Continued) **U000410022**

Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	14
Date Test:	01/27/2004
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSBAPTIS
Last Modified:	04/14/2017

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G04 - Tank Secondary Containment - Double-Walled (Underground)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
J01 - Dispenser - Pressurized Dispenser
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None

Tank Number:	2-A
Tank ID:	172961
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	03/01/2002
Date Tank Closed:	01/01/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Tank Number:	3
Tank ID:	172962
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	12000
Install Date:	09/01/2003
Date Tank Closed:	Not reported

GRAND PETROLEUM, LLC (Continued) **U000410022**

Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	14
Date Test:	01/27/2004
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MSBAPTIS
Last Modified:	04/14/2017

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin

Tank Number:	3-A
Tank ID:	172964
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	6000
Install Date:	03/01/2002
Date Tank Closed:	01/01/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Tank Number:	4
Tank ID:	63600
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	03/01/2002
Date Tank Closed:	03/01/2002

GRAND PETROLEUM, LLC (Continued) **U000410022**

Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	KAKyer
Last Modified:	04/14/2017

Equipment Records:

A03 - Tank Internal Protection - Fiberglass Liner (FRP)
I04 - Overfill - Product Level Gauge (A/G)
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J01 - Dispenser - Pressurized Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)
G04 - Tank Secondary Containment - Double-Walled (Underground)

W169 **B P PRODUCTS NORTH AMERICA INC #48359** **RCRA NonGen / NLR** **1007571102**
West **1049 GRAND ST** **NJ MANIFEST** **NYR000126615**
1/8-1/4 **BROOKLYN, NY 11211** **NY MANIFEST**
0.232 mi.
1223 ft. **Site 6 of 6 in cluster W**

Relative:
Higher

Actual:
15 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	20090709
Handler Name:	B P PRODUCTS NORTH AMERICA INC #48359
Handler Address:	1049 GRAND ST
Handler City,State,Zip:	BROOKLYN, NY 11211
EPA ID:	NYR000126615
Contact Name:	PAULA SKRYJA
Contact Address:	PO BOX 6038
Contact City,State,Zip:	ARTESIA, NY 90702-6038
Contact Telephone:	410-551-6074
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	PO BOX 6038
Mailing City,State,Zip:	ARTESIA, NY 90702-6038
Owner Name:	NO NAME FOUND
Owner Type:	Private

B P PRODUCTS NORTH AMERICA INC #48359 (Continued) **1007571102**

Operator Name:	NO NAME FOUND
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

B P PRODUCTS NORTH AMERICA INC #48359 (Continued) **1007571102**

Hazardous Waste Summary:
Waste Code: D018
Waste Description: BENZENE

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: BP PRODUCTS NORTH AMERICA INC
Legal Status: Private
Date Became Current: 20040501
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NO NAME FOUND
Legal Status: Private
Date Became Current: 20040501
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NO NAME FOUND
Legal Status: Private
Date Became Current: 20040501
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: BP PRODUCTS NORTH AMERICA INC
Legal Status: Private
Date Became Current: 20040501
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NO NAME FOUND
Legal Status: Private

B P PRODUCTS NORTH AMERICA INC #48359 (Continued) **1007571102**

Date Became Current:	20040501
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	NO NAME FOUND
Legal Status:	Private
Date Became Current:	20040501
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	B P PRODUCTS NORTH AMERICA INC #48359
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20070101
Handler Name:	B P PRODUCTS NORTH AMERICA INC #48359
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20090709
Handler Name:	B P PRODUCTS NORTH AMERICA INC #48359
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

B P PRODUCTS NORTH AMERICA INC #48359 (Continued) **1007571102**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040729
Handler Name: B P PRODUCTS NORTH AMERICA INC #48359
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44711
NAICS Description: GASOLINE STATIONS WITH CONVENIENCE STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:
EPA Id: NYR000126615
Mail Address: P.O. BOX 80249
Mail City/State/Zip: RANCHO SANTA 92688
Facility Phone: 9494605200
Emergency Phone: Not reported
Contact: FRANK LOBELLO
Comments: Not reported
SIC Code: Not reported
County: 00
Municipal: 00
Previous EPA Id: Not reported
Gen Flag: X
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 001274608JJK
EPA ID: NYR000126615
Date Shipped: 02/06/2008
TSDF EPA ID: NJD991291105
Transporter EPA ID: NJR000023036
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported

B P PRODUCTS NORTH AMERICA INC #48359 (Continued) **1007571102**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/06/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/06/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	RANCHO SANTA 92688
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D018
Hand Code:	H040
Quantity:	200 P

Manifest Number:	001274597JJK
EPA ID:	NYR000126615
Date Shipped:	06/14/2007
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000023036
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/14/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

B P PRODUCTS NORTH AMERICA INC #48359 (Continued) **1007571102**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/14/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	RANCHO SANTA 92688
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D018
Hand Code:	H14
Quantity:	200 P

Manifest Number:	NJA5246518
EPA ID:	NYR000126615
Date Shipped:	02/09/2006
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000023036
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/09/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/09/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

B P PRODUCTS NORTH AMERICA INC #48359 (Continued) **1007571102**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	04040621
Was Load Rejected:	RANCHO SANTA 92688
Reason Load Was Rejected:	Not reported

Manifest Number:	001274847JJK
EPA ID:	NYR000126615
Date Shipped:	10/23/2008
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000023036
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/23/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/23/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	RANCHO SANTA 92688
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D018
Hand Code:	H141
Quantity:	200 P

B P PRODUCTS NORTH AMERICA INC #48359 (Continued) **1007571102**

Manifest Number:	NJA5246585
EPA ID:	NYR000126615
Date Shipped:	06/19/2006
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000023036
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/19/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/19/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08070622
Was Load Rejected:	RANCHO SANTA 92688
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5008728
EPA ID:	NYR000126615
Date Shipped:	12/05/2004
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000023036
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/05/2004
Date Trans2 Transported Waste:	Not reported

B P PRODUCTS NORTH AMERICA INC #48359 (Continued) **1007571102**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/06/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	02030521
Was Load Rejected:	RANCHO SANTA 92688
Reason Load Was Rejected:	Not reported

NY MANIFEST:

Name:	AMOCO 48359
Address:	1049 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211
Country:	USA
EPA ID:	NYR000126615
Facility Status:	Not reported
Location Address 1:	1049 GRAND STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN‘
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000126615
Mailing Name:	AMOCO 48359
Mailing Contact:	FRANK LOBELLO
Mailing Address 1:	PO BOX 80249
Mailing Address 2:	Not reported
Mailing City:	RANCHO SANTA MARGARITA
Mailing State:	CA
Mailing Zip:	92688
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9494605200

B P PRODUCTS NORTH AMERICA INC #48359 (Continued) **1007571102**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJR000023036
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2008
Trans1 Recv Date:	10/23/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/23/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000126615
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	001274847JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

170 NW 1/8-1/4 0.237 mi. 1250 ft. | **8 REWE STREET, LLC**
8 REWE STREET
BROOKLYN, NY 11211 | **NY UST** | **U004076426**
N/A

Relative: Lower

Actual: 6 ft.

UST:

Name:	8 REWE STREET, LLC
Address:	8 REWE STREET
City,State,Zip:	BROOKLYN, NY 11211
Id/Status:	2-114308 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590173.96816
UTM Y:	4507768.11354
Site Type:	Other

Affiliation Records:

Site Id:	3728
Affiliation Type:	Mail Contact
Company Name:	8 REWE STREET, LLC
Contact Type:	Not reported
Contact Name:	BRUCE RESPLER
Address1:	885 CONKLIN STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-6465
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2007-02-22

Site Id:	3728
Affiliation Type:	Facility Operator
Company Name:	8 REWE STREET, LLC
Contact Type:	Not reported
Contact Name:	MARJAN SUPPLY CO.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-6465
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2007-02-22

Site Id:	3728
Affiliation Type:	Emergency Contact
Company Name:	8 REWE STREET, LLC
Contact Type:	Not reported
Contact Name:	FRANK MISSANO
Address1:	Not reported

8 REWE STREET, LLC (Continued) **U004076426**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 388-6465
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2007-02-22

Site Id:	3728
Affiliation Type:	Facility Owner
Company Name:	8 REWE STREET, LLC
Contact Type:	MEMBER
Contact Name:	JAMES BUTLER
Address1:	8 REWE STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 388-6465
EMail:	Not reported
Fax Number:	Not reported
Modified By:	msbaptis
Date Last Modified:	2007-02-22

Tank Info:

Tank Number:	001
Tank ID:	4073
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	7500
Install Date:	06/01/1979
Date Tank Closed:	04/01/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	21
Date Test:	06/08/2004
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
K99 - Spill Prevention - Other
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
F00 - Pipe External Protection - None

8 REWE STREET, LLC (Continued) **U004076426**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)

Z171 **NYC DEP HAZ MAT** **NY MOSF** **S102143390**
WSW **200 MORGAN AVENUE** **NY LIENS** **N/A**
1/8-1/4 **BROOKLYN, NY 11201** **NY Spills**
0.237 mi. **NY MANIFEST**
1253 ft. **Site 1 of 3 in cluster Z**

Relative:
Lower

Actual:
10 ft.

MOSF:

Name:	MORGAN OIL TERMINALS CORP.
Address:	200 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Facility ID:	2-1500
Program Type:	MOSF
Tank Status:	Inactive
Expiration Date:	Not reported
Dec Region:	2
UTMX:	590073.27268
UTMY:	4507217.06314

LIENS:

Name:	MORGAN OIL TERMINALS CORP.
Address:	200 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY
Region:	2
Spill No:	92-09135
Tax Map Id:	2942-101, 157, 160, 207, 220
Lien Request Received:	06/17/1996
Request Sent To APA Or Vendor:	07/18/1996
Draft Lien Received From Vendor:	11/19/1996
Approved Lien To Administrator:	Not reported
Signed By Administrator:	Not reported
Received From Administrator:	Not reported
Sent For Filing:	Not reported
Resent For Filing:	Not reported
Proof Of Service Received:	Not reported
Sent To OAG:	11/25/1996
Amount:	$561,620.28
Release Required:	Not reported
Sent To Administrator:	Not reported
Signed By Adminstrator:	Not reported
Received From Adminsitrator:	Not reported
Release Sent To OAG:	Not reported
Complete:	True
Release:	False
Withdrawn:	False

Name:	MORGAN OIL TERMINALS CORP.
Address:	200 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY
Region:	2
Spill No:	92-09135
Tax Map Id:	2942-101, 157, 160, 207, 220

NYC DEP HAZ MAT (Continued) **S102143390**

Lien Request Received:	03/22/1994
Request Sent To APA Or Vendor:	12/05/1994
Draft Lien Received From Vendor:	05/31/1995
Approved Lien To Administrator:	Not reported
Signed By Administrator:	Not reported
Received From Administrator:	Not reported
Sent For Filing:	Not reported
Resent For Filing:	Not reported
Proof Of Service Received:	Not reported
Sent To OAG:	06/05/1995
Amount:	$71,828.17
Release Required:	Not reported
Sent To Administrator:	Not reported
Signed By Adminstrator:	Not reported
Received From Adminsitrator:	Not reported
Release Sent To OAG:	Not reported
Complete:	True
Release:	False
Withdrawn:	False

SPILLS:

Name:	MORGAN OIL CORP
Address:	200 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8808176 / 1995-08-07
Facility ID:	8808176
Facility Type:	ER
DER Facility ID:	57235
Site ID:	59301
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	A3
SWIS:	2401
Spill Date:	1989-01-10
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1989-01-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Citizen
Cleanup Ceased:	1995-08-07
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-01-19
Spill Record Last Update:	2004-04-07
Spiller Name:	Not reported
Spiller Company:	MORGAN OIL COMPANY
Spiller Address:	MORGAN AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"OIL DUMPED INTO CREEK WHICH EMPTIES INTO EAST RIVER, USUALLY TAKES PLACE DURING THE NIGHT."

NYC DEP HAZ MAT (Continued) **S102143390**

All Materials:

Site ID:	59301
Operable Unit ID:	924580
Operable Unit:	01
Material ID:	452941
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	MORGAN OIL CORP.
Address:	200 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9211657 / 2003-11-19
Facility ID:	9211657
Facility Type:	ER
DER Facility ID:	57235
Site ID:	59303
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	A1
SWIS:	2401
Spill Date:	1992-12-23
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1992-12-23
CID:	Not reported
Water Affected:	ENGLISH KILL
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1993-01-14
Spill Record Last Update:	2012-04-19
Spiller Name:	Not reported
Spiller Company:	MORGAN OIL CORP.
Spiller Address:	200 MORGAN AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"4/19/12-Vought-Project manager for PIN project at Morgan Terminal (Open spill 9209135). Located box in file room with notes and reports from DEC Sigona PBS Inspection and Case. This file added to PIN drawer as PBS data may be needed for further cost recovery by NYSOAG if applicable."
Remarks:	"19 WELLS PUT ON SITE 15 WELLS SHOWS CONTAMINATION/REMEDIAL INVESTIGATION REPORT PREPARED BY FENLY AND NICOL. SITE SHOWS FREE PRODUCT MIGRATING OFF-SITE. DEC TO CLEAN/INSPECT MOUNDED TANKS/LEAKS."
	Not reported

NYC DEP HAZ MAT (Continued) **S102143390**

All Materials:

Site ID:	59303
Operable Unit ID:	976105
Operable Unit:	01
Material ID:	405044
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	MORGAN OIL TERMINAL
Address:	200 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9209135 / Not Reported
Facility ID:	9209135
Facility Type:	ER
DER Facility ID:	57235
Site ID:	59302
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	A1
SWIS:	2401
Spill Date:	1992-11-06
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	1992-11-06
CID:	Not reported
Water Affected:	ENGLISH KILLS
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Federal Government
Cleanup Ceased:	1995-02-28
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	1992-11-10
Spill Record Last Update:	2021-06-30
Spiller Name:	Not reported
Spiller Company:	CITIFUEL INC.
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"after discussing with DEC Austin, case transferred to DEC Patel. the subject spill case was reported by USCG. as per hand written notes from previous project manager, estimated 200-300 gal of material was observed in the English Kills during inspection on 11/06/1992. 04/20/12-Hiralkumar Patel. DEC remarks from 11/06/1992 to 04/19/12 are stored separately in e-docs. DEC Vought forwarded email from DEC Ketani who received email from Bill Hughes from GeoQuest, Inc. dated 02/07/12. Bill mentioned that scaffolding company has left the site and left mess behind. they are currently cleaning up the site. Bill

NYC DEP HAZ MAT (Continued) **S102143390**

Hughes GeoQuest, Inc. Ph. (860) 243-1757 Ext. 103 (860) 402-9592 (C) email: williamhughes01@gmail.com 1:00 PM:- left message for Bill at GeoQuest. 2:00 PM:- visited site with DEC Vought. site contains lots of junk left behind by scaffolding company. no environmental work in progress. found multiple wells (some destroyed and some in bad condition) on and around the property. Vought showed a large aboveground tank in concrete vault along south side of the property. some rainbow and silver sheen (could be mixed of biological and petroleum) observed on water in creek along north of the site. 04/27/12-Hiralkumar Patel. 10:16 AM:- received message from Bill. 11:43 AM:- spoke with Bill. he mentioned that due to access issue with the previous tenant (scaffolding company) for couple of years and large piles of junk left behind after tenant left, no environmental work is in progress at the site. once all the scaffolding junk removed, they are planning to conduct additional soil/gw investigation for additional data. asked him to send summary of work done till now and future plan. also asked him to submit property owner's contact information. 5/8/12-Vought-Vought and Patel held teleconference with NYSOAG Judith Karpen and State will only release lien upon cleanup of site to satisfaction of NYSDEC. Karpen noted that new owner was English Kills and former owner was Corpus Christi and that Corpus Christi declared bankruptcy and as a result State will receive minor settlement amount in lieu of total monies spent. Karpen noted that Corpus Christi may have secured eight million dollar loan for cleanup (as per former OAG Buss) but not sure if monies are being used for cleanup and also not sure whether Corpus Christi or English Kills is supervising cleanup. Karpen will begin file research upon completion of file review by DEC Patel and subsequent call to NYSOAG Karpen. Spill transferred to DEC Patel as per RSE. 05/18/12-Hiralkumar Patel. completed review of available documents and found following: 1) 10/12/2006: Robert Feller from Bond, Schoeneck & King, PLLC sent fax including a singed copy of Agreement for Discharge of Environmental Liens. RCC & York Associates, Inc. signed the agreement. RCC agreed on following terms: - payment of $ 25,000 upon execution of this agreement - upon completion of cleanup of environmental contamination to the satisfaction of NYS DEC, RCC or its assigns, heirs, or successors of interest, shall pay $ 100,000 - upon receipt of the final payment, DEC shall issue a release of its said environmental liens against the said property 2) 05/27/2009: DEC Ketani referred case to legal as no response to the STIP letter (dated 03/18/09). 05/23/12-Hiralkumar Patel. 2:40 PM:- received email from Bill including summary of work done by GeoQuest and disposal manifests for soil removed during removal of eastern tanks (400,000 gal and 200,000 gal). GeoQuest is planning to remove southern tanks (total five tanks). once the tank complex has been removed and extent of the sub-surface structure is known, a proposed plan of action for determining the extent of the subsurface contamination will be submitted. Bill will visit the site on 05/30/12. 05/24/12-Hiralkumar Patel. alternate address: 192-200 Morgan Ave MOSF #: 2-1500. MOSF registration showing tanks still in-service. registration expired on 03/31/1991. other spill #: 8808176, 9105949, 9112693, 9208755 and 9211657 spill # 8808176 was reported on 01/13/1989 as 100 gal #2 oil dumped into creek. case closed on 08/07/1995. no documents on e-docs. spill # 9105949 was reported on 09/03/1991 as #6 oil found in creek which might be coming from a 55 gal abandoned drum or from bulkhead. case closed 09/19/1991. spill # 9112693 was reported on 03/12/1992 as 50 gal #6

NYC DEP HAZ MAT (Continued) **S102143390**

oil spilled. case closed on 03/13/1992. spill # 9208755 was reported on 10/29/1992 as 50 gal #6 oil sludge spilled during tank cleaning operation. spill cleaned up by Citi Fuel. case closed on 02/05/1998. spill # 9211657 was reported on 12/23/1992 by DEC Mitchell due to contamination found in wells as part of PIN job. 05/25/12-Hiarlkumar Patel. 12:43 PM:- spoke with DEC legal regarding case initiation and confirmed no legal action from region 2 office as owner was doing work. 05/30/12-Hiralkumar Patel. 1:30 PM:- visited site. met Bill. found tank removal operation at the site. crew already removed more than 70% of the tank #1 (which is closest to the Morgan Ave - 647,000 gal tank). found about 12 inches thick concrete pad under the tank metal. water found on the side of the tank pad and oil found on water. no petroleum odors noticed. Bill mentioned that tank removal operation begun probably at the beginning of the month. informed him that the department has not received any work plans or notification to MOSF regarding removal of the tanks. after discussing with DEC Austin, asked Bill to stop tank removal work immediately and informed him that work should only be resumed after getting approval from the Department. Bill spoke with property owner and requested a meeting in DEC office. informed Bill that meeting can be scheduled once required work plan/documents submitted to the Department. during visit, met with Jacques Guillet (914-309-4317), contractor who is removing tank metals. informed him about no more work without the department's approval. 2:30 PM:- spoke with Ms. Karpen. she found the Agreement for Discharge of Environmental Liens (dated 10/12/2006) in her file. she will review available documents to see if any consent order or STIP signed for cleanup work. informed her about a meeting requested by RP. she mentioned that she needs to review the entire file and the work plan/documents, that will be submitted by RP, before any meeting with RP. she requested copy of work plan/documents, once submitted. 05/31/12-Hiralkumar Patel. discussed with DEC Austin and DEC Vought. Austin required submission of following documents: - work plan for tanks removal including community air monitoring plan and health and safety plan - submission of MOSF application for tanks closure - copy of NYC DOB's work permit for tanks removal - documentation about notification to FDNY 1:52 PM:- received email from Bill. he mentioned that the site owner has a prospective tenant who would rent part of the space (starting in two weeks), but currently, access to the area being rented is blocked by physical obstacles on the ground. Bill asked if they can move stockpiled soil to other part of the site and remove already cut-up steel off-site. discussed with DEC Austin. Austin approved to move soil and metal to other part of the site, but no off-site disposal without approval of the work plan. 2:25 PM:- spoke with Bill and informed him that the department approves moving of stockpiled soil and cut-up steel to other part of the site, but does not approve off-site disposal of any material until all required documents submitted and approved. asked him to send property owner's contact info. asked Bill about well monitoring. Bill mentioned that wells were lastly checked in 2009 before scaffolding removed. after removing scaffolding, most of the wells are covered under dirt/metal and are not accessible. asked Bill about DOB work permit. he believes that permit is not needed for tank removal. asked him to check with NYC DOB regarding required work permit. 06/01/12-Hiralkumar Patel. 2:01 PM:- received email from Bill including property owner's contact info. English Kills Ventures LLC c/o Asher Zwebner, Trustee 5014 16th Avenue, Suite 110 Brooklyn, NY 11219 6:15 PM:- sent email to Bill and asked to provide owner's phone number and email address.

NYC DEP HAZ MAT (Continued) **S102143390**

06/05/12-Hiralkumar Patel. 11:08 AM:- received email from Bill. he mentioned that property owner asked to send documents to their attorney. Robert H. Feller, Esq. **property owner's attorney** Bond, Schoeneck & King, PLLC. 111 Washington Avenue Albany, NY 12210-2211 Ph. (518) 533-3222 Fax (518) 533-3299 email: rfeller@bsk.com 1:44 PM:- received email from Bill. due to open tank excavation pit, he requested to backfill it using on-site stockpiled soil. 2:33 PM:- forwarded Bill's email to DEC Austin for review. 6/6/12-Vought-DEC Patel received email from GeoQuest (Bill Hughes Ph:860-243-1757 Cell:860-402-5292) that When you closed down the site on Wednesday (5-30-12) you may not have realized that a dangerous condition resulted - an open pit. Granted, the work area is theoretically closed to any and all persons and/or vehicles, but we all know that stuff happens. In addition, the open pit is subject to flooding which could result in a multitude of unforeseeable problems including exacerbating the danger of this site condition.We propose the following solution: 1) Continue the removal of the steel bottom of the tank (at the very least) and store the steel on-site. The next level of action would be to also remove the steel back wall (south wall), remaining steel west wall (only about 30% still remains), and remove the remainder of the north wall (storing all removed steel on-site, of course). 2) Back-fill the open pit with the on-site soil as you and I discussed. The on-site soil is fill removed from the tank top and walls which exhibits no sign of any contamination. The backfilling of this area would eliminate a very dangerous situation. 3) Consider allowing the stored steel to be removed from the site. It could be used to pay for the rental equipment. Steel is steel- it is not a source of contamination. 4) Consider the power of inertia- the longer a project remains stalled, the harder it is to get it moving again. Regards. DEC Patel forwarded email to RSE with request for advisement and RSE forwarded mail to DEC Vought asking to look into matter. Vought called and spoke to Geoquest who noted that tanks bottoms were approximately 5-6'below grade on concrete and close to groundwater. Geoquest also noted that the concrete under the tanks was at groundwater level. Vought after concurring with DEC Farrar called back Geoquest and noted that backfilled soils must meet STARS Memo #1 parameters. Vought also called and spoke to NYCOEM McIntyre who noted that site is not in a NYC Program and as such there are to date no institutional or engineering controls for site but that if applicants are interested in alternate SCOs associated with a different program then they should call NYCOER Chawla. Vought spoke to DEC Patel who noted that when he was onsite last week he also noted to contractor that wells will need to be installed at the tank locations through the concrete. Vought to meet Hughes on site at 1pm today and required that: 1)samples be collected from the soil pile analyzied for Full List 8260/8270 (due to history of chlorinated solvents) 2)note that wells will be required in the future in the backfilled areas 3)Submission of analyticals to DEC for review prior to use as backfill. Vought received callback from Hughes who noted that site was zoned M-1(manufacturing). Vought performed site visit and received call from Hughes who noted that his car broke down in Brooklyn and he will not be able to make it to site but will arrange to have sampling company come to site and collect sam[ple. Vought repeated that sample must be collected for 8260/8270 Full List and compared to STARS Memo#1 values. Vought observed approximately 2O' high by 70' long pile of soil up against large MOSF tank but noted no petroleum odors or staining in pile. Vought also observed standing

NYC DEP HAZ MAT (Continued) **S102143390**

water in open tank pit and water was connected to soil as west wall of UST removed down to tank bottom. No sheen or product in water in tank pit. Bottom of tank pit composed of concrete pad and steel(of which is scheduled to be removed). Vought met English Kills (Arthur Schwartz Ph:732-309-2063) onsite and discussed tank removal and future use of site (which may be parking lot for buses) as well as need for installation of wells at tank location through concrete pad as per DEC Patel. Vought also observed approximately 6' width of soil between steel tank and outer support wall with no staining as well. Note soil pile covering many monitoring wells. Rush turnaround time will be requested for soil samples as well. Vought sent email update to Kumar. 6/7/12-Vought-Received message from Hughes and returned call and left message to return call with confirmation of sample collection. Vought received callback from Hughes who was enroute to site to perform soil sampling of proposed soils for backfill (EPA 8260/8270 Full List) due to former presence of chlorinated solvents as well as petroleum in tank. Results to be compared to STARS Alternative Guidance values and examined for possible Haz Waste contaminants as well. Results should be received and Hughes will follow up with Vought on Friday. 06/12/12-Hiralkumar Patel. 11:58 AM:- received email from Bill including sample results. three samples were collected. some SVOCs found in samples. found maximum 460 ppb of Naphthalene in one sample. Bill requested approval to backfill the excavation. DEC Austin and DEC Vought inspected site. based on observations during the site inspection, Austin mentioned that the department does not approve backfilling of the tank excavation. he asked for a meeting in DEC office, with property owner. 2:36 PM:- spoke with Bill and informed him about the discussion with DEC Austin. asked him to set up meeting with property owner. 4:25 PM:- sent email to Bill. informed him that the department does not approve backfilling of the excavation. informed him that the department requests a meeting with property owner. asked him to provide timing for the meeting. email copied to DEC Vought, DEC Austin, Judy Karpen, Jay Soltis (jsoltis@geoquestinc.com) and Marc Casslar (mcasslar@geoquestinc.com). 06/14/12-Hiralkumar Patel. 11:51 AM:- received email from Bill. he mentioned that him, Marc Casslar (GeoQuest) and Robert Feller (owner's attorney) will meet at 10 AM on 06/20/12, in DEC office. spoke with DEC Austin. he requested presence of property owner. he mentioned that if owner brings his attorney, then DEC attorney will be present in the meeting and it will be an enforcment issue. 2:32 PM:- spoke with Bill and informed him about discussion with DEC Austin. Bill asked to reply by email. 06/18/12-Hiralkumar Patel. discussed with DEC Vouth, DEC Austin and Judith Karpen. Ms. Karpen is still reviewing legal documents. as the legal review is pending, Austin mentioned that the meeting on 06/20/12 will be to discuss technical issues only. 3:31 PM:- sent email to Bill including meeting agenda. informed him that this meeting will be for technical discussion only. email copied to DEC Austin, DEC Vought, Judy Karpen, Jay Soltis and Marc Casslar. 06/20/12-Hiralkumar Patel. 10:00 AM:- discussed with DEC Austin, DEC Vought, Bill, Marc Casslar, Robert Feller and Ryan Karben during meeting in DEC office and agreed upon following: - notification to NYC DOB and FDNY (if applicable) - submission of MOSF application for tanks removal - monitoring of bulkhead during low tide for possible oil seepage into the creek and installation of boom, if product seepage noted - submission of tank removal plan, including health and safety plan and CAMP, by the end of 07/16/12 - subsurface soil and

NYC DEP HAZ MAT (Continued) **S102143390**

groundwater investigation, at and around the tanks location during discussion, Bill mentioned that removal of remaining tanks would take another 6-8 months and subsurface investigation will be peformed after that. informed RP that the department requires delineation under the tank pads, via installation of wells through the pads. also, the department may require replacement of wells, if existing wells are destroyed or clogged. during discussion, Austin approved to use on-site stockpiled soil to backfill the tank excavation and RP agreed that depends on future site use, backfilled soil may be removed during future development. asked RP to submit MOSF application for tanks removal. Ryan Scott Karben, Esq. **owner's representative** Law Office of Ryan Scott Karben 11 Tara Drive Pomona, NY 10970 Ph. (914) 536-4402 email: ryan@ryankarben.com 1:01 PM:- spoke with Judy. she mentioned that due to statue of limitation, she can not enforce for money spent more than 6 years ago. also, there is no dicussion about spill remediation in the Agreement for Discharge of Environmental Liens signed by RCC & York Associates, Inc. in 2006. she also mentioned that bankruptcy court has found environmental liens be not valid. 06/29/12-Hiralkumar Patel. 3:50 PM:- spoke with Bill and informed him that a STIP agreement will be mailed today. 4:06 PM:- sent STIP letter to Mr. Feller. informed him that the signed STIP and a tank removal plan (including schedule) must be submitted by the end of 07/27/12. letter emailed to Mr. Feller, DEC Austin, DEC Urda, Ms. Karpen, Bill, Mr. Casslar and Mr. Karben. 07/05/12-Hiralkumar Patel. 12:14 PM:- received email from Bill including MOSF notification, tank removal plan and health & safety plan (including CAMP). 1:02 PM:- sent email to Bill. informed him that a signed stipulation must be submitted to the Department prior to review of any work plans. email copied to DEC Austin, DEC Urda, Ms. Karpen, Mr. Fellller, Mr. Casslar and Mr. Karben. 07/12/12-Hiralkumar Patel. received email from Mr. Casslar (at 6:11 PM on 07/11/12) including revised STIP and CAP. Mr. Casslar noted following nine reasons for changes in STIP and CAP: - the spill occurred in 1992, more than 20 years ago - the oil terminal has been closed for almost 20 years - all of the tanks were emptied, cleaned, and inspected more than 18 years ago - active remediation of groundwater was conducted for about 8 years - NYSDEC concluded almost 8 years ago that no further benefit could be achieved from active groundwater remediation - all of the work was conducted under the supervision of the NYSDEC - no new spills have occurred since the facility was closed - the site has been used and occupied at various times in the last 20 years and there is no indication that a risk to human health or safety exists; and - throughout time the importance of removing the tanks has been continuously discussed 07/18/12-Hiralkumar Patel. discussed with DEC Austin, DEC Vought, DEC Urda and Ms. Karpen. Ms. Karpen will discuss with Patrick Hallaway in AG's office to discuss about third party claim to the spill fund by the property owner. discussed submitted revised CAP and changed as needed. Urda will revised the CAP after gets update from Ms. Karpen. 07/31/12-Hiralkumar Patel. visited site. found water in tank excavation area. some sheen observed on water. 3:23 PM:- received email from Ms. Karpen inquiring if English Kills had a Phase I done prior to purchasing the property. 08/01/12-Hiralkumar Patel. 4:43 PM:- sent email to Ms. Karpen. informed her that the department does not have any Phase I report in file and doesn't know if English Kills ever conducted Phase I investigation. 08/03/12-Hiralkumar Patel. received call from DEC Urda. he will arrange a conference call with

NYC DEP HAZ MAT (Continued) **S102143390**

AG's office and spill fund. 08/07/12-Hiralkumar Patel. yesterday (08/06/12), DEC Austin, DEC Vought, DEC Urda, DEC Ben Conlon, Ms. Karpen (AG's office), Bonnie Riggi (AG's office), Luzette Baker (spill fund) and Patrick Halloway (spill fund) discussed the case and decided to send a consent order. spoke with DEC Urda. he has asked DEC Leszek to review available MOSF documents and waiting for his response before drafting response to the revised STIP sent by RP. 3:48 PM:- spoke with DEC Ian Beilby who inquired about spill # 1202045, which was reported by BCP contractor as they noticed some sheen in water near the site. informed Ian that no sheen observed during the site visit on 05/31/12 and based on site observation, case 1202045 is closed. during conversation, Ian mentioned that they have meeting with EPA on 08/09/12 regarding Newtown Creek cleanup project and will discuss about possible impact to the creek from the Morgan Terminal. asked Ian to update after meeting. 08/13/12-Hiralkumar Patel. 3:33 PM:- received call from DEC Beilby. he mentioned that EPA and respondent's consultant (Anchor QEA) are considering sending a letter (104E request) to English Kills Ventures LLC requiring to submit all investigation/compliance documents for review. 08/14/12-Hiralkumar Patel. 2:47 PM:- received email from DEC Beilby. he will send CD of available documents to AnchorQEA. 08/14/12-Ian Beilby CD with edoc files sent to AnchorQEA for review and possible 104e request. 08/16/12-Hiralkumar Patel. 12:38 PM:- received email from DEC Michele Albert including copy of cover letter that was sent to Anchor QEA (with document CD). 09/06/12-Hiralkumar Patel. reviewed tank removal plan, submitted previously on 07/05/12. abstract of tank removal plan: - fill material removed from the top and sides of the tank will be assigned to one of two piles - if soil appears normal with no dark stains or odor it will be placed onto a clean pile - if soil has dark stains or odor or if it registers on a PID meter it will be placed onto a dirty pile and be stored on and under plastic for sampling, laboratory analysis and eventually off-site disposal - when half of the bottom plate has been removed, the excavation resulting from the tank removal will be partially backfilled to allow the excavator to move into the tnak area to reach the remainder of the bottom plate and the tank back wall - upon completion of the removal of each tank section, the excavation for that tank section will be backfilled and compacted to grade - use of previously excavated clean fill from the on-site clean pile is done with the understanding that in the future, this fill may have to be sampled and/or remediated the tank removal plan does not discuss about endpoint sampling. 10/23/12-Hiralkumar Patel. received email from DEC Urda (at 10:39 AM on 10/17/12) including copy of email from Mr. Feller. Mr. Feller sent signed copy of the consent order. as per the Corrective Action Plan of the Consent Order, the Department must be notified two days prior to backfilling of any part of the excavation and the Department may require collection of endpoint soil and groundwater samples. waiting for copy of fully executed Consent Order. 11/13/12-Hiralkumar Patel. 11:46 AM:- received email from DEC Urda including fully-executed order. 11/29/12-Hiralkumar Patel. 4:07 PM:- spoke with Bill. they started work about 2-3 days ago. 12/05/12-Hiralkumar Patel. 2:55 PM:- visited site. crew was working in tank pit, cutting angle brackets to the south wall of tank. no structural supports were observed to the south wall. also noted that the tank pit was partially backfilled, without prior notification to the department as required in signed consent order. 3:25 PM:- left message for Bill and asked him to ensure worker's safety. 3:50 PM:-

NYC DEP HAZ MAT (Continued) **S102143390**

sent email to Bill regarding operation at the site. asked him to ensure safe operation. email copied to DEC Urda and Mr. Feller. 12/06/12-Hiralkumar Patel. 11:08 AM:- received email from Bill. he has spoke with Jacques and was informed that there is still a piece of the bottom plate attached to the south wall as well as the eastern end wall and the angle brackets are for tank stiffness, and are not for structural integrity. 2:16 PM:- spoke with Bill regarding partial backfilling of excavation without prior notice to the department. he mentioned that the excavation was partially backfilled so a backhoe can be used for further work. he mentioned that soil in tank excavation pit will be tested as part of investigation after tank removal and removed, if found contaminated. 12/10/12-Hiralkumar Patel. received email from Bill (at 4:18 PM on 12/09/12). he mentioned that when remedial investigation work plan is submitted, the soil in the area occupied by the tanks will be addressed along with the soils on the remainder of the property. 01/22/13-Hiralkumar Patel. 9:00 AM:- visited site. first section of the tank is removed completely and area has been backfilled to grade. no crew was on-site. 03/20/13-Hiralkumar Patel. 10:45 AM:- visited site. crew was removing the tank. the site is divided in two sections: section towards Morgan Ave is occupied by buses and section towards the water is occupied by construction equipments. 05/04/13-Hiralkumar Patel. another spill reported at the site (spill #: 1301162) by FDNY as fire occurred in tank pit during tank removal. 1:30 PM:- visited site. FDNY had left. met with Jacques Guillet, site supervisor. he mentioned that due to very hot weather, some of the left over oil got vaporized and flash fire occurred. FDNY extinguished the fire and stopped work until they get fitness certificate. FDNY issued violation order (# A181083). Mr. Guillet mentioned that work will resume only after necessary documents submitted to FDNY. inspected tank pit. only eastern section of last tank left. found burned steel in tank pit. no odors noted. as per Mr. Guillet, no one was injured. 05/06/13-Hiralkumar Patel. 9:17 AM:- DEC Urda forwarded email from Mr. Feller (dated 05/02/13). Mr. Feller mentioned that tank removal report will be submitted by 05/31/13, as approved by DEC. 05/24/13-Hiralkumar Patel. 11:03 AM:- received call from Bill. he inquired about document from previous contractors regarding cleaning of tanks. 11:10 AM:- sent email to Bill including copy of report from Winston Contracting dated 02/25/1995. 05/31/13-Hiralkumar Patel. 10:42 AM:- received email from Bill including tank removal report. abstract: - two tanks (# 6 and 7) in eastern tank complex - five tanks (# 1 through 5) in southern tank complex - tanks were fabricated on the site from individual steel plates with welded seams - tank structures were supported with internal steel angle brackets welded into a rigid pattern - soil was placed on the exterior of the tanks to create bunders , and appeared to consist of the same fill-type materials underlying the property - both the eastern (with two tanks # 6 and 7) and southern (with five tanks # 1 through 5) tank complexes were constructed approx. 4 ft bg - on-site soil, including bunkering material, was utilized to backfill the excavations - during the remvoal of the tank bottom plates, small quantities of free product were occasionally observed on groundwater - when encountered, the oil was collected using oil absorbent material - total of 835.84 tons of soil, from removal of eastern tanks, transported in Mar. 2012 - total of 1,696.63 tons of soil, from removal of southern tanks, transported in Aug. 2012 2:18 PM:- tank removal report forwarded to Ms. Karpen. 2:22 PM:- sent email to

NYC DEP HAZ MAT (Continued) **S102143390**

Bill and asked to submit remedial investigation work plan and tank registration forms as per item # 5 and 6 of the correction action plan of the signed consent order. email copied to DEC Urda, Ms. Karpen, Mr. Casslar, Mr. Feller and Mr. Karben. 05/31/13-Hiralkumar Patel. 2:57 PM:- received email from Bill. he inquired if tank removal report is accepted. he mentioned that investigation work plan will be submitted within 30 days of acceptance of the tank removal report. he also mentioned that required tank registration forms will be submitted upon approval of the remedial investigation work plan. 06/04/13-Hiralkumar Patel. discussed with DEC Leszek regarding submission of MOSF/PBS forms. he mentioned that required tank registration forms should be submitted now to correct the tank status. 06/05/13-Hiralkumar Patel. 3:02 PM:- sent email to Bill. informed him that the tank removal report is accepted. informed him that as per the signed consent order, a remedial investigation work plan is due within 30 days of submission of the tank removal report. asked him to submit the work plan on or before June 30, 2013. also asked him to submit required tank registration forms now instead of waiting for work plan approval. email copied to DEC Urda, Ms. Karpen, Mr. Casslar, Mr. Feller and Mr. Karben. 06/20/13-Hiralkumar Patel. 11:41 AM:- received email from Bill including PBS/MOSF applications. 06/25/13-Hiralkumar Patel. discussed with DEC Leszek about PBS/MOSF forms. he mentioned that hard copy must be submitted with original signature. 12:56 PM:- sent email to Bill and asked him to submit hard copy of required PBS/MOSF forms with original signature. 06/28/13-Hiralkumar Patel. received signed hard copy of PBS/MOSF forms. gave forms to DEC Leszek for review and processing. 07/01/13-Hiralkumar Patel. received email from Marc Casslar from GeoQuest including Remedial Investigation Work Plan. abstract: - total of 12 soil borings wil be advanced to the base concrete slab of the former southern tank complex - for the eastern tank complex, a total of 8 soil borings will be advanced to the base concrete slab - 2 of the borings in each complex will be advanced through the slab to a total depth of 12 ft bg - soil with the highest PID readings or the most visual or olfactory contamination will be collected for lab analysis - soil samples will be analyzed for DRO, VOCs by 8260B and PAHs by 8270 - five (5) additional borings will be developed as 1 inch monitoring wells, with 5 ft of screen and sufficient riser, in the vicinity of the former tanks - work can commence within 90 to 120 days after the acceptance of this work plan - report should be completed within 180 days after commencement work the proposed work plan is not acceptable for following reasons: - it proposes to begin work within 90 to 120 days after the acceptance of the work plan. the department requires that investigation work must begin within 45 days of work plan approval - it propose to submit report within 180 days after commencement of work. the department requires that Remedial Investigation Report must be submitted within 120 days of work plan - a scaled site map must be submitted including all previous boring/well locations and location of proposed borings/wells - it proposes installation of 1 inch well with 5 ft screen. work plan does not specify minimum depth of proposed wells. the proposed wells must be at least 2 inch in diameter and must be installed to minimum depth of 12 ft bg with 10 ft of screen - all existing monitoring wells must be gauged and sampled 10:26 AM:- spoke with Marc at GeoQuest. asked him to submit revised work plan with following changes: - investigation work must begin within 45 days of department’s approval (instead of within 90 to 120 days) - Remedial Investigation Report

NYC DEP HAZ MAT (Continued) **S102143390**

must be submitted within 120 days of department's approval (instead of 180 days after commencement of work) - revised scaled site map including all previous boring/well locations, alongwith location of proposed borings/wells - wells must be at least 2 inch in diameter and must be installed to minimum depth of 12 ft bg with 10 ft of screen - gauging/sampling of all existing monitoring wells Marc mentioned that site access may be issue for field work. informed him that the site is being used as parking lot, occupied by buses which can be moved for field work. Marc mentioned that Bill is out of office till next week and will submit revised work plan upon his arrival. 3:40 PM:- received message from Sam Levin, attorney for property owner. Sam Levin Ph. (347) 564-3597 07/02/13-Hiralkumar Patel. 1:16 PM:- spoke with Mr. Levin. he inquired about insurance carrier of previous property owners. informed him that no such information seen in file. suggested him to review available files. he will talk to Bill. 07/19/13-Hiralkumar Patel. 4:12 PM:- received email from Bill including work plan, with changes in work schedule only. but no changes about well diameter or depth. 08/02/13-Hiralkumar Patel. Bill proposed to install total 20 soil borings to the base concrete slab in former two tank fields, but soil above concrete bases are basically on-site backfill soil which was removed from around the tanks during tank removal. as such there is no need to sample this soil again. instead deeper and larger diameter monitoring wells are needed at the source area. 1:26 PM:- spoke with Bill. informed him that the department requires minimum 4-inch wells at former tank locations, to a minimum depth of 12 ft bg with 10 ft of screen. asked him to submit revised work plan. Bill asked to send email with comments on work plan. 08/06/13-Hiralkumar Patel. discussed with DEC Vought. as stated in signed consent order, complete delineation (on- and off-site) is required. 11:12 AM:- spoke with Bill. informed him that the department requires complete delineation of contamination, which includes impact to off-site also. asked him to submit revised work plan including off-site delineation. strongly suggested him to locate previous monitoring wells and sample existing wells prior to finalizing the work plan. Bill asked for written note about the requirements. 1:52 PM:- sent email to Bill. informed him that as per the signed consent order, the department requires complete delineation of contamination. asked him to submit a revised RIWP, by the end of 09/13/13, including on- and off-site delineation. suggested him to locate and sample existing wells prior to finalizing the RIWP. email copied to DEC Urda, Mr. Feller, Jay Soltis (jsoltis@geoquestinc.com) and ekvllc@gmail.com. 08/20/13-Hiralkumar Patel. 4:35 PM:- received message from Bill. 08/21/13-Hiralkumar Patel. 12:42 PM:- left message for Bill. 08/22/13-Hiralkumar Patel. 11:29 AM:- received message from Bill. 08/26/13-Hiralkumar Patel. 12:52 PM:- spoke with Bill. he inquired about reason for 4 inch well. informed him that 4 inch wells are preferred in case product recovery or other remediation needed. he mentioned that as there was not much oil found on concrete pad during tanks removal, property owner wants to install 2 inch well. informed him that its ok to install 2 inch well now, but the department may require to install larger diameter well based on investigation results. he agreed to it. Bill will submit work plan by first week of Sept. 2013. 09/13/13-Hiralkumar Patel. 2:05 PM:- received email from DEC Beilby. he mentioned that EPA will visit site on 09/18/13 to determine whether there are any likely on-site point source discharges to Newtown Creek. 10/03/13-Hiralkumar Patel. 12:19 PM:-

NYC DEP HAZ MAT (Continued) **S102143390**

received email from DEC Beilby. Anchor QEA indicated that the morgan oil terminal would not likely be targeted for sampling because of a lack of discharge. 10/29/13-Hiralkumar Patel. received email from Bill (at 2:02 PM on 10/28/13) including a revised work plan. Bill proposes to install total of twenty (20) soil borings to the base concrete slab of the former tank complexes. two borings will be advanced to 12 ft bg. three (3) 2-inch wells will be installed to 15 ft depth, with 10 ft of screen. Bill also proposes to sample seven (7) existing wells. the submitted work plan does not include information about number of wells available at the site and it only proposes to investigate soils and groundwater in the footprint and vicinity of the former tank complexes. 11/14/13-Hiralkumar Patel. 2:55 PM:- spoke with Bill. discussed about existing wells and complete delineation. Bill mentioned that they found total 12 wells. out of 12 wells, product found in 5 of the existing wells. asked Bill to submit a revised work plan including site map with location of all existing wells and information about product in existing wells. informed him that further delineation may be requuired, based on investigation results. 3:17 PM:- sent email to Bill and asked to submit a revised work plan. 11/26/13-Hiralkumar Patel. received email from Bill (at 4:14 PM on 11/20/13) including work plan with revised site map including location of wells where free product found. 12/20/13-Hiralkumar Patel. 11:30 AM:- sent letter to property owner approving work plan, pending inclusion of immediate gauging of wells to determine product thickness, installation of absorbent socks in impacted wells and weekly monitoring/removal of product from wells. asked owner to submit monthly records of well gauging/product removal activities and investigation report by the end of 06/30/2014. letter emailed to Bill, DEC Urda and Mr. Feller. 01/08/14-Hiralkumar Patel. DEC Peter Malaty (Fish, Wildlife and Marine Resources) visited site earlier today to inspect bulkhead at the site. during inspection, he noted spill of unknown amount of motor fuel onto the soil, from one of the parked bus at the site. he sent pictures taken during the site visit. 11:28 AM:- left message for Bill and informed him about unreported spill, from a bus, at the site. asked him to call back with bus company's information. informed him that the department requires reporting of this spill incident and cleanup of spilled material. 11:36 AM:- sent email to Bill including pictures received from DEC Peter. informed Bill that the department requires reporting of this spill incident and immediate cleanup. also asked him to provide bus company's information. 01/10/14-Hiralkumar Patel. 12:28 PM:- received call from Bill. discussed about unreported spill under the parked bus. he will ask bus owner/operator to report the spill. Bill mentioned that spill was cleaned up. spoke with Bill about installation of absorbent socks in well and removing product. he mentioned that no work has been done yet and they believe that installing absorbent socks in wells would not do any benefit. asked Bill to submit written reply to the requirement of well gauging/product removal as listed in letter dated 12/20/13. 03/10/14-Hiralkumar Patel. 10:43 AM:- received email from Bill including addendum to remedial investigation work plan dated 10/18/13. Bill proposed to install an appropriate absorbent sock , as soon as practical, into each of the contaminated wells and weekly checking and repalcement of these socks. specific work schedule is missing in the addendum. 04/23/14-Hiralkumar Patel. 1:33 PM:- left message for Bill. 06/02/14-Hiralkumar Patel. 4:48 PM:- received email from Bill including a letter including summary of interim remedial

NYC DEP HAZ MAT (Continued) **S102143390**

measures. on 05/14/14, GeoQuest gauged wells previously reported to contain LNAPL (MW-14, MW-15, MW-28A, MW-34 and MW-40) and installed absorbent socks. they visited site again on 05/21/14 and replaced the absorbent socks. found product in all five wells during both visits. product thickness (in ft): ---------05/14/14-----05/21/14 MW-14------0.90---------0.72 MW-15-----0.001--------0.001 MW-28A----0.001--------0.001 MW-34------6.20---------0.01 MW-40------1.50---------0.45 absorbent sock weight difference (in oz) on 05/21/14: ---------weight diff. MW-14------25.8 MW-15-------3.0 MW-28A------1.1 MW-34------11.0 MW-40------47.7 06/23/14-Hiralkumar Patel. 3:44 PM:- received email from Bill including a letter including summary of interim remedial measures. on 06/11/14, GeoQuest gauged wells with the installed absorbent socks. a previously obstructed well (MW-12) has been available and installed absorbent sock in it. previously reported to contain LNAPL (MW-14, MW-15, MW-28A, MW-34 and MW-40) and installed absorbent socks. they visited site again on 05/21/14 and replaced the absorbent socks. found product in all five wells during both visits. product thickness (in ft): ---------06/11/14 MW-12------0.001 MW-14------0.001 MW-15------0.001 MW-34------0.001 MW-40------0.001 absorbent sock weight difference (in oz) on 06/11/14: ---------weight diff. MW-14------35.6 MW-15-------5.1 MW-28A------2.0 MW-34-------4.2 MW-40------42.5 10/28/14-Hiralkumar Patel. 11:24 AM:- received email from Bill including remedial investigation report. abstract: - on 06/09/14, installed 20 soil borings in the area under and around the former bulk storage tanks - twelve (12) soil borings (B-1 through B-12) were advanced to a depth of 5 ft within the footprint of the former southern tank complex, six (6) soil borings (E-1 through E-6) were advanced to a depth of five ft within the footprint of the former eastern tank complex, and two borings (B-13 and B-14) were advanced to a depth of 15 ft bg along the north side of the southern tank complex - ten soil samples were submitted for lab analysis - on 06/10/14, three (3) 2-inch monitoring wells, with ten (10) ft of screen, were installed to a depth of fifteen (15) ft bg - total of ten monitoring wells were sampled for analysis: seven existing wells (FN-19, FN-20, FN-22, FN-28A, FN-31, FN-35 and FN-39) and three new wells (GQ-41, GQ-42 and GQ-43) - boring logs shows the predominant material encountered in the footprint of each tank complex was: brown, dark brown or black sand with silt or sand, silt, and clay, with a variety of crushed materials: asphalt, brick, pieces of concrete, stone, coal, plus ceraimc, glass, metal, wood and paper - groundwater was encountered at 3.5 ft bg in boring B-13 and B-14 - direction of groundwater flow across the site ‘would be expected’ to be predominantly west to east and from south to north ---------- - the exception is on the southern side of the former Southern tank complex where it is believed that the 17 ft high bunkering wall filled with permeable fill, has influenced the local flow direction, forcing a reported southeasterly flow direction ---------- - very minor VOCs detection noted in few samples - SVOCs were detected in all soil samples (backfill material found in soil borings) - using absorbent socks in wells with product, a total of 1.5 gal of product has been removed to-date - there are at least two USTs still on-site including a 3,000 to 5,000 gal UST in a vault in the northwest corner of the site and a 1,000 gal heating oil tank on the south side of the terminal buiding - recommends removal of remaining tanks and continuation of interim-remedial measures (product recovery using absorbent socks in wells with product) the

NYC DEP HAZ MAT (Continued) **S102143390**

report is missing site map with location of existing tanks and well FN-28A. 11/04/14-Hiralkumar Patel. 8:57 AM:- sent email to Bill. asked him to submit site map with location of existing tanks and well FN-28A. also asked him to submit records of interim remedial measures as per the department's letter dated 12/20/13 (copy attached in email). email copied to Aaron Abraham (aarbenabe@yahoo.com), Marc Casslar (mcasslar@geoquestinc.com), Jay Soltis (jsoltis@geoquestinc.com) and lepmanagement89@gmail.com. 11/06/14-Hiralkumar Patel. 2:14 PM:- received email from Bill including site map with location of existing tanks and well FN-28A. Bill mentioned that location of FN-28/FN-28A is uncertain. according to well location maps available to GeoQuest, there should be two wells close together off of the eastern end of the office buildiing, labeled FN-28 and FN-28A, but when GeoQuest did the well usability survey in September 2013 they could only locate one well. Bill will refer this well from now on as FN-28A. 11/10/14-Hrialkumar Patel. 9:15 AM:- received email from Bill including well monitoring data table, which was previously submitted in June. 10:22 AM:- sent email to Bill and asked him to submit interim remedial measure record from June to Nov. email copied to lepmanagement89@gmail.com, Mr. Abraham, Mr. Casslar, Mr. Soltis. 12/24/14-Hiralkumar Patel. 12:08 PM:- received email from Bill: My apologies, there have been no sock exchanges since our last report. We initiated the Interim Remedial Measures (IRM) and made our first report, but, while the initial levels were high, the levels dropped quickly to near zero floating product and we wanted to wait a bit to see if the levels would rebound and by how much. We just completed another round and it appears that the levels, for the most part, have remained low except for one well- FN-40, which still shows some floating product. We were unable to access FN-34 for this round of sampling. absorbent sock weight difference (in oz) on 11/11/14: ---------weight diff. MW-12-------7.5 MW-14------38.5 MW-15------29.0 MW-28A------8.8 MW-40------54.8 01/21/15-Hiralkumar Patel. 8:57 AM:- left message for Bill inquiring update about recommended tank removal. 01/28/15-Hiralkumar Patel. 3:03 PM:- received call from Bill. asked him about status on recommended tank removal. he mentioned that they are waiting for approval from DEC on investigation report. he also mentioned that owner is planning to use the site as it is and there is no redevelopment plan at this time. 07/10/15-Hiralkumar Patel. received email from Paul McGaha (at 6:02 PM on 06/22/15) from McGaha Consulting including well gauging record. Mr. McGaha was recently contracted to assist with project. he inspected site on 06/12/15 and gauged seven existing wells (MW-12, MW-14, MW-15, MW-28A, MW-34, MW-39 and MW-40). 2.35 ft of floating product was noted in well MW-15. absorbent socks with weight difference were found in wells MW-12, MW-28A and MW-40. Paul McGaha McGaha Consulting, Inc. Ph. (908) 285-1207 Fax (888) 680-2762 email: paul.mcgaha@mcgahaconsulting.com Mr. McGaha mentioned that responsible parties will be initiating a remedial action at the property upon approval of the remedial investigation report (dated Sep. 2014 and submitted on 10/28/14). in that report, GeoQuest recommended removal of two USTs and continuation of interim remedial measure program. 09/02/15-Hiralkumar Patel. 1:39 PM:- spoke with Mr. McGaha. informed him that property owner has failed to comply with a requirement of weekly well gauging and monthly submission of well gauging report. Mr. McGaha recommended use of a more active remedial method instead of absorbent socks. asked him to submit a written plan

NYC DEP HAZ MAT (Continued) **S102143390**

for review. 2:38 PM:- sent email to Mr. McGaha and asked to submit written plan for alternative remedial method. email copied to LEP Management (lepmanagement89@gmail.com). 12/11/15-Hiralkumar Patel. a new spill report (# 1509305) received from a member of Newton Creek Alliance. spill report was filed due to oil slick and heavy sheen noted in creek adjacent to the subject site. 3:35 PM:- spoke with Mr. McGaha. he mentioned that this afternoon, he was informed about sheen along side of the property but doesn't think it came from the site. they will install absorbent booms in the creek. 4:10 PM:- inspected site. no sheen noted on water in the creek. 4:36 PM:- spoke with Mr. McGaha. informed him about observations during the site visit. he mentioned that booms will be installed this weekend. 12/14/15-Hiralkumar Patel. 7:52 AM:- left message for Mr. McGaha. 11:15 AM:- received email from Mr. McGaha including some pics. he mentioned that booms were deployed early Saturday morning. residual sheen was present on the water, therefore, the booms were allowed to cross the waterway closer to the boats docked in the inlet, and pulled back to their current position to collect the floating material causing the sheen. a security camera has been focused on the area to monitor the conditions. Mr. McGaha submitted pics from security camera. pics taken on 12/12/15 at 9:13 am, 10:27 am, 11:45 am, 12:02 pm, 1:03 pm, 2:10 pm, 3:15 pm, and 4:35 pm. Paul mentioned that the condition will continue to be monitored and the boom will not be removed until the condition is no longer present. pics show sheen on water. 11:23 AM:- received email from Mr. McGaha including interim remedial measure report. abstract: - report included well gauging data since May 2014 - since May 2014, wells FN-12, FN-14, FN-15, FN-28A and FN-40 were gauged on 05/14/14, 05/21/14, 06/11/14, 12/11/14, 06/12/15 and 09/21/15 - well FN-39 was also gauged during 06/12/15 and 09/21/15 events - absorbent socks have been used to collect LNAPL in wells exhibiting floating product - based on available data, groundwater elevations fluctuate between 1.32 ft above mean sea level at FN-12 in Dec. 2014 to 8.88 ft above mean sea level at FN-34 in May 2014 - total of 3.38 gal of oil have been collected using the absorbent socks since May 2014 - weight of oil was converted to gallons using the specific gravity of #6 fuel oil - site has acquired equipment capable of pumping LNAPL from the groundwater table during liquid product recovery events - based on product recovery amount, Morgan Terminal requests that the frequency of petroleum pumping and absorbent sock removal and replacement be modified to biweekly events. Morgan Terminal also requests that the reporting frequency and submission of Interim Remedial Measures Progress Reports be modified to quarterly reporting product thickness (in ft) in wells:
----------FN-12-----FN-14-----FN-15-----FN-28A-----FN-34-----FN-4
0
05/14/14----------0.90----------6.20------1.
50
05/21/14----------0.72----------0.
45
12/11/14--------1.32------0.02------2.50-------7.00----------0.
40 06/12/15----------2.35
09/21/15--------4.60------0.10------0.20-------0.04------0.23------0.
06 12/15/15-Hiralkumar Patel. received email from Willis (at 4:28 PM on 12/14/15) from Newtown Creek Alliance including pics of the creek showing sheen. Willis went to the site and met property owner and manager. Willis mentioned that property owner, Arthur, made strong

NYC DEP HAZ MAT (Continued) **S102143390**

claims that no product was migrating off his property and likely someone spilled a quart of oil into the water. 8:30 AM:- after discussing with DEC Austin last night, visited site this morning during high tide. minor non-recoverable sheen noted on water in the creek. based on observations during the site visit, it looks like the site has been divided into following four sections: - eastern end of the property (the former eastern tank complex) has been separated from the rest of the site using chain-linked fence. there are sheds on the eastern most part of the site, along the water so could not inspect waterbody from the land - the former southern tank complex area is now occupied by a lumber yard - the remaining area of the site between the creek and the former tank complex (southern tank complex) is used as a parking lot occupied by a private bus company - the northwest corner of the site (former maintenance building), immediately west of the end of the creek, is used as parking lot also noted repaved parking lot around the former maintenance building and a wooden deck along the bulkhead, on east of the former maintenance building. as per available site maps, few monitoring wells were installed around the former maintenance building, including well FN-46 which is along the bulkhead and closest to the point where sheen noted on creek recently. during site visit, there were some vehicles parked on-site and could not see any of the formerly installed monitoring wells around former maintenance building in remaining open area. 9:36 AM:- spoke with Mr. McGaha inquiring about well gauging data. he mentioned that property owner has hired someone who gauge and remove product from the monitoring wells and Paul has prepared report based on data received from property owner. asked Mr. McGaha to send email confirming this activity and including contact information for the person who is gauging wells and removing product. also asked him to schedule gauging of all monitoring wells in presence of DEC personnel. informed him that this may require moving parked vehicles. 2:02 PM:- sent email to Mr. McGaha and asked him to submit - an email (or a letter) confirming his involvement in the project (active field duties vs report preparation/submission based on information collected/submitted by others) - contact name and number for the person/contractor who is gauging on-site wells and recovering product - photographs from the security camera at every hour beginning at 5 PM on 12/12/2015 email copied to DEC Austin, DEC DeMeo, DEC Urda, LEP Management (lepmanagement89@gmail.com) and Arthur Schwartz (aschwartzesq@optonline.net). reviewed NYC ACRIS record and noted that the site has been sold to new property owner in Mar. 2014. Greenpoint Bushwick LLC. **current property owner** 675 3rd Avenue, 8th Floor New York, NY 10017 2:55 PM:- sent email to Mr. McGaha and asked to submit property owner/manager's contact information. email copied to LEP Management and Arthur Schwartz. 3:02 PM:- spoke with Aaron Cohen, property's leasing manager. he is aware of the issue in the creek. he mentioned that property owner (represented by Robert Feller) is planning to conduct further investigation in this matter. he also mentioned that a local contractor (Newtown Williamsburg) was gauging the wells and recovering product. asked Mr. Cohen to schedule a field work for well gauging and product recovery, in presence of DEC personnel. he agreed to it and will ask Mr. McGaha/well gauging technician to schedule this work, in this week. Mr. Cohen mentioned that project managers from DEC Permit unit were on-site recently regarding bulkhead permit issue. Aaron Cohen **property's leasing manager** LEP Management Ph. (347) 901-9045 email: lepmanagement89@gmail.com 3:36 PM:- received

NYC DEP HAZ MAT (Continued) **S102143390**

email from Mr. McGaha. he mentioned that McGaha Consulting, Inc. has provided consulting services for the property including a site visit to demonstrate the operation of the interface meter and well gauging procedures to the previous on-site technician responsible for collection of well gauging data and just last week a second visit to demonstrate the operation of the interface meter and well gauging procedures to the site's new on-site technician. Mr. McGaha has made recommendations for the improvement of well gauging techniques and have prepared a proposal to deliver a mobile pumping system to remove free product from the wells containing free product using a double diaphragm pump. Mr. McGaha was also requested to prepare a standard Interim Remedial Measures Report submission containing well gauging data that is collected and provided by the property's on-site technician, which was recently provided by email. Mr. McGaha mentioned that the on-site technician responsible for well gauging is Mr. Issac Gut. Isaac Gut **on-site technician for well gauging** Ph. (914) 319-1104 (347) 771-7927 email: gut.isaac@gmail.com 3:38 PM:- received email from Mr. McGaha including photographs from on-site security camera. 3:55 PM:- spoke with Sandra Reyes-Guerra (Regional Environmental Permit). she and Justin Falls (DEC Habitat Protection) were on-site as part of bulkhead repair permit application. Sandra doesn't recall noticing any sheen on water. 12/16/15-Hiralkumar Patel. received email from Mr. McGaha (at 9:58 PM on 12/15/15) confirming field work on 12/18/15. 8:00 AM:- visited site. inspected western end of the creek, along the bulkhead east of the former maintenance building. noted some sheen on water. 8:51 AM:- sent email to Mr. McGaha. informed him about a wooden deck in the area of monitoring well FN-46 which is along the bulkhead and closest to the point where sheen noted in creek recently. asked him to have this deck lifted, if possible, for access during field work on 12/18/15. informed him that a new well may be needed in this area, if accessing existing well is not possible. 12/17/15-Hiralkumar Patel. 8:00 AM:- visited site. found sheen on water near the bulkhead at the end of the creek. re-inspected area around the former maintenance building. found formerly installed monitoring well FN-34. some part of the parking lot has been repaved. reviewed NYC ACRIS record and google maps and noted following: - the former Morgan Terminal site occupied lots 101, 207, 220, 160 and 157 on block 2942 - the creek is divided in two sections: north and south and both sections are part of private property - the northern half section of the creek is part of lot # 105 - the southern half section of the creek is subdivided. the eastern portion of the subdivided creek is actually lot # 157 and the western portion of the subdivided creek is part of lot # 101 - all five morgan terminal lots (101, 207, 220, 160 and 157) were owned by Corpus Christi Resources, LLC. from 10/2007 to 12/2008 - all five morgan terminal lots were owned by English Kills Ventures, LLC. from 12/2008 to 04/2014 - in Apr. 2014, former morgan terminal lots were sold to different entities: * lot 101 to Greenpoint Bushwick LLC. * lot 207 to Bushwick Star Management LLC. * lot 157 to 192 Morgan Realty LLC. * lots 220 and 160 to Morgan Williamburg LLC. owners for all five lots have same address: 675 3rd Avenue, 8th Floor New York, NY 10017 12/18/15-Hiralkumar Patel. 11:30 AM:- visited site. met Steve (McGaha Consulting) and Isaac (owner's representative) and gauged wells FN-12, FN-14, FN-15A, FN-22, FN-28A, FN-34, FN-39 and FN-40. inspected creek and noted some sheen on water. - well FN-34 is located in northwest corner of the site, west of the former maintenance building. no product found on top of the water, but heavy

NYC DEP HAZ MAT (Continued) **S102143390**

tar like material noted on side of the well casing and at the bottom of the well. - well FN-28A is located east of the two-story building. no product noted in this well - wells FN-12, FN-14, FN-15A, FN-22, FN-39 and FN-40 are located in alley (access to 190 Morgan Ave) on south side of the former southern tank complex. - well FN-39 is located on south side of the alley. no product noted in this well - well FN-15A is located north side of the alley (adjacent to former tank complex wall). free phase petroleum product noted in the well. due to product viscosity, water interface was not used to measure thickness. a product sample was collected for fingerprint analysis. - well FN-12 is located on north side of the alley (adjacent to former tank complex wall and east of well FN-15). no product noted in this well. - well FN-40 is located on south side of alley (south of well FN-12). 0.4 ft of product noted in this well, and noted diesel like odors. - well FN-14 is located in middle of alley (southeast of well FN-12 and closest accessible well to 190 Morgan Ave). free phase product noted in the well. due to clogged bottom, could not measure product thickness. product sample collected for fingerprint analysis. diesel like odors noted in the well - well FN-22 is located far south end of the open lot on south side of the property. no product noted in this well 1:46 PM:- spoke with Mr. Cohen and informed him about finding product in wells. asked him to analyze product samples. due to diesel like odors in wells located in the alley, went to site 190 Morgan Ave which is a bus repair facility. met with on-site operator who refused to provide name and number. he provided business email (jbrserviceinc@gmail.com) and allowed access to the repair area for inspection. noted a waste oil tank along south wall of the facility. I left site after this. Steve was going to check two more wells: FN-16 (east of FN-15 and adjacent to former tank complex wall) and FN-19 (at curb on southwest side of the site and at the entrance of the alley) 12/21/15-Hiralkumar Patel. 9:27 AM:- spoke with Mr. McGaha and discussed observations during the site visit. asked him to submit a summary of field activity on 12/18/15. 9:35 AM:- spoke with Mr. Cohen. based on field observations, asked him to immediately remove product from the impacted monitoring wells and conduct weekly well gauging/product recovery, for at least a month. Mr. Cohen inquired about approval of remedial action report submitted in Oct. 2014. informed him that the report recommended removal of two on-site tank systems. after reviewing the report, the department had discussed tank removal activity with consultant at that time and waiting for result of tank removal activities. 12/23/15-Hiralkumar Patel. 8:18 AM:- left message for Mr. McGaha inquiring about status on product removal from impacted wells at the site. 8:20 AM:- left message for Mr. Cohen inquiring about status on product removal from impacted wells at the site. 8:25 AM:- sent email to Mr. Cohen and Mr. McGaha. asked them to submit document confirming removal of free phase product from impacted monitoring wells. 11:10 AM:- spoke with Mr. McGaha. he is going to the site today to deliver the pump system for product removal. he believes that product from the impacted wells will be removed today. asked him to send email, once product removed from the wells. 12/24/15-Hiralkumar Patel. 9:38 AM:- sent email to Mr. Cohen and Mr. McGaha inquiring about document confirming removal of free phase product from the impacted wells. 11:00 AM:- received email from Isaac. he mentioned that today they will be pump wells with product and gauge accessible wells. 11:02 AM:- sent email to Isaac. asked him to provide information about amount of oil recovered from each well and to re-gauge existing wells. email copied to Mr.

NYC DEP HAZ MAT (Continued) **S102143390**

Cohen and Mr. McGaha. 2:00 PM:- received email from Isaac. he mentioned that they are having trouble with the pump. 12/28/15-Hiralkumar Patel. received email from Isaac (at 6:28 PM on 12/24/15). he gauged eight wells and found product in one well. he is unable to pump out oil due to pump issue. received another email from Isaac (at 6:51 PM on 12/24/15) including gauging data for eight wells. almost 2 ft product found in well FN-15A. 12/29/15-Hiralkumar Patel. 8:52 AM:- sent email to Isaac inquiring update on removal of free phase product from impacted monitoring wells at the site. email copied to Mr. Cohen and Mr. McGaha. 12/30/15-Hiralkumar Patel. 10:50 AM:- left message for Mr. Cohen inquiring update on product removal from impacted monitoring wells. 10:53 AM:- left message for Mr. McGaha. 11:03 AM:- received email from Isaac stating that pump does not work. 11:10 AM:- sent email to Isaac. informed him that if the pump does not work, then alternate method must be used. also informed him that the Department requires immediate removal of free phase petroleum product from the impacted monitoring wells at the site and document confirming such activity must be submitted to the Department no later than COB December 31, 2015. email copied to Mr. Cohen and Mr. McGaha. 01/04/16-Hiralkumar Patel. received email from Isaac (at 7:50 PM on 12/31/15). they gauged wells today and found 2 ft of product in well FN-15A. he mentioned that product was removed from the impacted well. they have not found product in other wells. they are working on uncovering more wells. 1:20 PM:- sent email to Isaac and asked to provide schedule for this week's well gauging activities so site visit can be made. email copied to Mr. McGaha and Mr. Cohen. 01/05/16-Hiralkumar Patel. received email from Isaac (at 4:40 PM on 01/04/16). he will be on-site on 01/08/16 to gauge the wells. 01/08/16-Hiralkumar Patel. 9:15 AM:- visited site and met Patrick, person working for property management. while at the site, witnessed gauging of two monitoring wells: FN-14 and FN-15A. thin layer of product noted in well MW-14 and approx. 1 ft of product noted in well MW-15A. asked Patrick to remove product from the wells. he will continue gauging other wells. inspected creek and found no sheen on water. 10:59 AM:- spoke with Isaac and asked him to continue weekly well gauging and product removal until further notice. 1:03 PM:- sent email to Mr. McGaha and asked to submit report for fingerprint analysis. email copied to Mr. Cohen. 2:29 PM:- received email from Isaac including well gauging summary. product found in well FN-15A only. 2:59 PM:- received email from Mr. McGaha. he has not received fingerprint results yet. 01/15/16-Hiralkumar Patel. received email from Isaac (at 6:38 PM on 01/14/16) including well gauging data. out of seven monitoring wells gauged, product found (approx. 1 ft) in well FN-15A only. 01/19/16-Hiralkumar Patel. 12:25 PM:- received email from Mr. McGaha including result of fingerprint analysis for two product samples collected on 01/12/16. Mr. McGaha stated results present the findings of undermined . I have requested the laboratory provide any additional details available regarding the carbon chain length etc. reviewed fingerprint sample results. as per lab report, two product sample (White Top & Black Top) were collected on 01/12/16. also as per comments in the lab report: petroleum hydrocarbon chromatogram most closely resembles diesel fuel / fuel #2. the sample was quantitated against C9-C alkane hydrocarbon standard. 01/20/16-Hiralkumar Patel. 10:36 AM:- spoke with Mr. McGaha regarding product sample collection for fingerprint analysis. he mentioned that result of product samples collected on 12/18/16 were inconclusive, so they collected another set of samples on 01/12/16.

NYC DEP HAZ MAT (Continued) **S102143390**

informed Mr. McGaha that as per gauging data from Isaac, product found in only one well FN-15A during gauging on 12/24/15, 12/31/15, 01/08/16 and 01/14/16. asked him to submit result of fingerprint analysis for product samples collected on 12/18/15 and information about from where the two product samples were collected on 01/12/16. reviewed chain-of-custody submitted with fingerprint analysis report and it was noted that the sample was collected from NJ. also, there is no indication anywhere in the report that these product samples were collected from 200 Morgan Ave. 10:51 AM:- spoke with Mr. McGaha again and informed him about sampling location (NJ) noted in chain-of-custody. at this time, he mentioned that sampling report he submitted yesterday is actually for samples collected on 12/18/16. he thinks lab filled up the chain-of-custody when samples were dropped there. asked him to send letter report including sample result and explaining issues with chain-of-custody. 11:05 AM:- left message for Mr. Cohen. 2:00 PM:- received email from Mr. McGaha explaining information noted on chain-of-custody. Regarding the fingerprint samples collected on 12/18/2015. The results of these samples were submitted on January 19, 2016. Today you pointed out errors on the chain of custody related to these samples. The information on the chain of custody is wrong. Steve collected the samples on 12/18/2015, when you were on-site, and dropped the samples to our office location that evening. Steve told me the labels for the samples were filled out, but he did not have a chain of custody. I requested another individual to get the samples to the laboratory. It is at this point that the sample was mishandled and errors were introduced into the process. After our phone call I took a closer look at the chain of custody and attempted to determining what happened to the samples. Just before but also after our second phone call, I learned that the samples were not dropped off to the laboratory until after the Christmas and New Year holidays. When they were dropped off, they were dropped to our sales representative for Phoenix Laboratories for delivery to Phoenix Laboratory. The laboratory sales representative completed the chain of custody so that the samples could be processed. The information for the chain of custody was provided by the individual who was requested to get the samples to the laboratory. Unfortunately, for fear of reprimand for not delivering the samples on time, that individual did not consult Steve or I for the correct details for the chain of custody. When inquiring about the time-frame to receive the results I was presented with an excuse for the delay which. The samples were obviously mishandled. I take full responsibility for this situation. I chose an under-qualified person to complete what I considered to be a simple task, and get the samples to the laboratory. The chain of custody was completed poorly, at best, and is the only reason for this communication. The transport of the samples to the laboratory had nothing to do with the responsible party for Morgan Terminal. The samples from Morgan Terminal were analyzed by a NY State certified laboratory. The fingerprint analysis samples delivered to Phoenix were the only fingerprint analysis samples we have collected since 12/18/2015. I apologize for the situation and I will again offer to re-sample the product for fingerprint analysis to eliminate issues related to the sample handling and chain of custody errors caused during sample delivery to the laboratory. 01/25/16-Hiralkumar Patel. 1:01 PM:- sent email to Mr. McGaha. informed him that the department has not received a report for field work conducted on 12/18/15. asked him to submit report, including details about product sample and analysis

NYC DEP HAZ MAT (Continued) **S102143390**

and results of subsequent well gauging/product recovery activities. email copied to Mr. Cohen and Arthur Schwartz (aschwartzesq@optonline.net). 01/26/16-Hiralkumar Patel. received email from Mr. McGaha (at 10:47 PM at 01/25/16) including an interim remedial measures progress report. abstract: - a magnetometer survey was performed to locate all monitoring wells at the property that have been covered or for which the current location is currently not visible or known. the report is missing date and result of this survey ---------- - wells FN-12, FN-14, FN-15, FN-22, FN-28A, FN-34 and FN-39 (and also FN-40 which is not listed in text part of the report) were gauged on 12/18/16 - sample of LNAPL was collected from FN-14 and FN-15 - groundwater elevations fluctuate between 1.32 ft above mean sea level at FN-12 in Dec. 2014 to 8.88 ft above mean sea level at FN-34 in May 2014 - morgan terminal has removed 1.029 gal of oil during the reporting period between 12/14/15 and 01/15/16 - owner requested to modify well gauging/product recovery schedule from weekly to bi-weekly the submitted report is considered incomplete due to: - missing results of magnetometer survey - site map including location of formerly removed tanks and all the wells installed in past whether it is visible or not at this point 1:46 PM:- sent email to Mr. McGaha and asked him to submit revised report including following: 1. result of magnetometer survey performed (to locate all monitoring wells at the property that have been covered or for which the current location is currently not visible or known) at the site, including date of the survey. 2. a scaled site map including current site use, existing structures, tank systems and monitoring wells. ask him to mark working condition of each available monitoring well. also informed Mr. McGaha that the Department does not agree with the proposed Remedial Action Schedule submitted in the report and requires continuation of weekly well gauging/product removal. asked him to submit a revised report no later than COB February 05, 2016. email copied to Mr. Cohen. 02/03/16-Hiralkumar Patel. 10:13 AM:- sent email to Mr. McGaha and asked him to include results of weekly well gauging for the week of Jan. 18, Jan. 25 and Feb. 1st, in the revised report (due on 02/05/16). email copied to Mr. Cohen. 02/09/16-Hiralkumar Patel. 1:31 PM:- spoke with Mr. McGaha and inquired him about report. he just received some missing information about well monitoring/gauging last week and the report will be submitted by tomorrow morning. 02/10/16-Hiralkumar Patel. 2:06 PM:- received email from Mr. McGaha including amended interim remedial measures progress report. the amended report includes date (12/16/15) and result of magnetometer survey, description of existing site use and location of on-site structures, and results of well gauging conducted on 02/05/16. on-site wells were not gauged on 01/22/16 and 01/29/16 as site was covered with snow. during well gauging on 02/05/16, 2.4 ft of product found in well FN-15. 02/16/16-Hiralkumar Patel. received email from Mr. McGaha (at 5:27 PM on 02/12/16) including well gauging data for week of Feb. 8th. total of ten wells (FN-12, FN-14, FN-19, FN-22, FN-28, FN-34, FN-39, FN-40, GW-42 and GQ-43) were gauged. record does not include result for well FN-15. record includes numbers, but does not include information about what this numbers represent to. also there is no result for well FN-15. 9:16 AM:- sent email to Mr. McGaha inquiring about result for well FN-15. also inquired about numbers listed in last week's well gauging data. email copied to Mr. Cohen, Cameron Hendrick (deweyhendrick@yahoo.com) and Arthur Schwartz (aschwartzesq@optonline.net). 11:58 AM:- sent letter to English Kills

NYC DEP HAZ MAT (Continued) **S102143390**

Ventures LLC requiring submission of revised RIR including: 1) continuation of weekly groundwater monitoring/product removal, 2) inspection/maintenance of boom in the creek and 3) further groundwater delineation via installation of monitoring wells along creek. asked property owner to submit revised RIR no later than 05/31/16. letter emailed to Mr. McGaha, Mr. Feller and Mr. Cohen. letter copied to DEC Austin, DEC Vought, DEC DeMeo and DEC Urda. 03/24/16-Hiralkumar Patel. 12:04 PM:- received email from Mr. McGaha including a aerial map with proposed location of two monitoring wells. Mr. McGaha mentioned that they have added new absorbent boom in the waterway adjacent to the property to address the sheen on the water that has been/is being observed in the last several months. the new boom does not extend across the entire waterway, and does not capture material that may be entering the waterway from the outfall at the end of the waterway. the goal is to determine if the sheen originates from outfall or another location. they have also performed a dye trace of drains at the subject building to determine if the source of the sheen on the waterway could originate from piping below the property. a magnetometer was used to locate additional monitoring wells at the property. they have located 11 monitoring wells. additional effort has been scheduled to continue this effort. repair of the damaged wells is also being scheduled. the magnetometer also identified an anomaly near the small structure at the north side of the property. additional investigation of the anomaly is proposed including a small excavation above the anomaly. Mr. McGaha mentioned that weekly well gauging is continuing. 03/25/16-Hiralkumar Patel. 2:42 PM:- sent email to Mr. McGaha and asked him to submit a scaled site map including all existing wells and location of proposed monitoring wells. email copied to Arthur Schwartz and Mr. Cohen. 04/07/16-Hiralkumar Patel. received email from Mr. McGaha (at 10:17 PM on 04/06/16) including a site map with location of two proposed wells. he mentioned that the wells at the property will be repaired and re-surveyed for horizontal position and elevation following the installation of the two proposed wells. he also mentioned that the survey will allow for an improved scaled map, but they do not anticipate improving the maps until the survey is complete. 04/08/16-Hiralkumar Patel. 3:08 PM:- sent email to Mr. McGaha and informed him that proposed well locations look fine. 06/02/16-Hiralkumar Patel. received email from Mr. McGaha (at 12:55 PM on 06/01/16) including remedial investigation report. abstract: - remedial investigatory efforts performed at the site between Feb. 2016 and May 2016: weekly well gauging and LNAPL removal; monitoring well repair; magnetometer survey; dye trace - two (2) 2-inch monitoring wells (MC-1 and MC-2) were installed at the south and west side of bulkhead at the end of inlet, to a depth of 20 ft bg with 15 ft of screen - during the well installation the soil was screened using PID. PID readings were not detected above background levels - site is underlain by dark, very loose to medium compacted, fine to medium-grained sand with a trace pebbles, silt, brick and concrete - at 12 ft a peat layer consisting of very soft to medium compacted peat and/or organic silt with trace plant fibers and fine sand was encountered - soil samples were not collected during installation of wells MC-1 and MC-2 -------- - groundwater samples were collected from MC-1 and MC-2 - found CVOCs in groundwater sample from MC-2 - wells FN-12, FN-14, FN-15, FN-22, FN-28A, FN-34, FN-39, FN-40, FN-42, MC-1 and MC-2 were gauged weekly - during the reporting period, absorbent socks were used to collect LNAPL form wells - in addition

NYC DEP HAZ MAT (Continued) **S102143390**

to absorbent socks, a double diaphragm pump is used to collect LNAPL directly from wells containing LNAPL during regular product recovery events - based on all available data, groundwater elevations fluctuate between 1.32 ft above mean sea level at FW-12 in Dec. 2014 to 15 ft above mean sea level at FN-34 in May 2014 - presence of LNAPL is currently limited to an isolated area surrounding FN-14, FN-15 and FN-40 - manholes of the nine of the existing wells (FN-12, FN-14, FN-15, FN-22, FN-28, FN-34, FN-39, FN-40 and FN-42) were replaced - magnetometer survey was helpful in locating a total of 12 existing monitoring wells at the site (these wells were known for last couple of years) - magnetometer survey was hindered by the presence of steel storage container near the office building, therefore, the location of 550 gal heating oil tank could not be determined - the 3,000 gal diesel tank was not located at the property and it is presumed that the tank was previously removed - one anomaly indicative of a suspect UST was identified during the magnetometer survey. the anomaly was located 8 ft east from the south corner of the ancillary building at the north side of the property. the anomaly was approx. 4 ft wide and extended approx. 3 ft from the wall of the ancillary building. the asphalt paving was removed above the area of the anomaly and soil was excavated to a depth of 5 ft bg, however, no UST or evidence of petroleum were discovered in this location - in an effort to investigate potential sources related to the oil sheen identified on the English Kills, the drains at the bus area and the domestic drains within the building were tested with a non-hazardous dye. dye was not identified in the creek ---------- - during a period of low tide, the skeleton of what appears to be a boat was observed in the mud at the bottom of the inlet below the water - based on the initial site characterization soil samples collected by Fenley & Nicol in 1993 and the more recent soil samples collected by GeoQuest in 2014, the contaminants identified in soil are considered historic fill and not related to a specific discharge incident or area of concern ---------- groundwater analyticals: ----------MC-2 1,2-Dichlorobenzene----------40 1,3-Dichlorobenzene----------4 1,4-Dichlorobenzene----------10 Chlorobenzene----------8 cis-1,2-Dichloroethene-------11 Vinyl Chloride----------12 - during weekly gauging since Mar. 2016, product found in wells FN-14 (0.01 to 0.31 ft), FN-15 (0.01 to 0.49 ft) and FN-40 (0.13 to 0.60 ft) recommendations: - probing the mud with a tile probe is recommended to determine if an un-natural structural may be present in the mud below the creek - additional investigation for detection of chlorinated compounds in MC-2 - bi-weekly (instead of weekly) gauging of wells - further investigation for USTs using GPR Survey 06/13/16-Hiralkumar Patel. 2:08 PM:- left message for Mr. McGaha. asked him to submit missing boring/well logs for MC-1/MC-2 and Appendix A. also asked him to call back to discuss use of Proposed Conceptual Approach to Site Remediation dated 07/11/2005. 2:09 PM:- sent email to Mr. McGaha and asked to submit missing information in the report. email copied to Mr. Schwartz and Mr. Cohen. 06/16/16-Hiralkumar Patel. received email from Mr. McGaha (at 2:32 PM on 06/15/16). he mentioned that missing information will be submitted in few days. 08/31/16-Hiralkumar Patel. 11:16 AM:- sent email to Mr. McGaha and asked him to submit missing information immediately. email copied to Mr. Schwartz and Mr. Cohen. 12:03 PM:- received email from Mr. McGaha including boring logs for MC-1 and MC-2 and Remediation System Evaluation report prepared for EPA dated 06/04/2003. as per

NYC DEP HAZ MAT (Continued) **S102143390**

boring logs: - concrete fill and silty sand noted in both borings - both borings were installed to 20 ft bg - groundwater was found at 11 ft bg in MC-1 and 10 ft in MC-2 - gross contamination encountered at 12-13 ft bg - PID reading above 100 ppm recorded below 5 ft depth in MC-1 with maximum of 950 ppm recorded at the end of boring - PID readings noted below 5 ft depth in MC-2 with maximum of 150 ppm at the end of boring Mr. McGaha mentioned that to make the deadline for the submission of the recent report, he relied on verbal communication with Derik, the field technician on-site during the recent field work, regarding the description of soil at MC-1, MC-2, and the soil at the anomaly investigated. Mr. McGaha questioned Derik about gross contamination in MC-1, he described the area of moist and black with an obvious odor. Derick described the layer as having the texture of wood chips. Mr. McGaha stated that this observation did not translate into groundwater contamination, based on the analytical results of the groundwater sample at MC-1, however, the finding warrants further investigation. he intends to inspect the bulkhead on the water side at the same depth to determine if the gross contamination can be associated with the sheen observed on the water. this work will be performed during the investigation of the structure identified on the bottom of the waterway. 09/13/16-Hiralkumar Patel. 1:44 PM:- received message from Mr. McGaha. he mentioned that during well monitoring, they noted product in one of the two wells installed along bulkhead. they are planning to install a pneumatic skimmer to recover product. Mr. McGaha will submit a written work plan for review. 09/15/16-Hiralkumar Patel. 1:01 PM:- sent email to Mr. McGaha and asked him to submit a revised RIR (including discussion of elevated PID readings and field observations that were noted in the boring logs) and results of well monitoring/product recovery since May 2016, by the end of 09/30/16. email copied to Mr. Cohen and Mr. Schwartz. 09/20/16-Hiralkumar Patel. 1:07 PM:- received email from greenpoint11237@gmail.com (without any name) stating that the new well that we installed near the bulkhead recently which has been showing small amounts of oil, we are pumping the oil every day as per Mr. Mcgaha suggestion. Additionally, the two booms that were installed in the water will be changed soon. 09/23/16-Hiralkumar Patel. 2:21 PM:- received email from Mr. McGaha including interim remedial measure report. 09/28/16-Hiralkumar Patel. received email from Mr. McGaha (at 8:56 PM on 09/27/16) including link to amended RIR. 10/26/16-Hiralkumar Patel. DEC Falls came to discuss issues at the site. they received an application for bulkhead repair permit. informed DEC Falls about petroleum contaminated soil and groundwater at the site. 11/01/16-Hiralkumar Patel. 3:30 PM:- received email from Mr. McGaha including interim remedial measure report for Oct. 2016. 11/07/16-Hiralkumar Patel. abstract of amended RIR dated 09/30/16: - two wells (MC-1 and MC-2) were installed - concrete fill and silty sand noted in both borings - both borings were installed to 20 ft bg - groundwater was found at 11 ft bg in MC-1 and 10 ft in MC-2 - gross contamination encountered at 12-13 ft bg - PID reading above 100 ppm recorded below 5 ft depth in MC-1 with maximum of 950 ppm recorded at the end of boring - PID readings noted below 5 ft depth in MC-2 with maximum of 150 ppm at the end of boring - on 09/11/16, LNAPL was identified in well MC-1 - the fact that LNAPL was not immediately identified in MC-1, suggests that the LNAPL could originate closer to the bulkhead and/or north of MC-1, placing a potential source of LNAPL under the boiler house building. the boiler house building is downgradient of the 3,000 gal diesel potentially existing UST

NYC DEP HAZ MAT (Continued) **S102143390**

location - a magnetometer survey failed to identify the 3,000 gal UST - will conduct ground penetrating radar survey to locate 3,000 gal UST - if the ground penetrating radar survey does not locate the UST, a hole will be dug by hand to determine if the USTs are in the areas identified on historical maps - monitoring wells (FN-12, FN-14, FN-15, FN-22, FN-28A, FN-34, FN-39, FN-40, FN-42, MC-1 and MC-2) gauged weekly - absorbent socks and double diaphragm pump were used to collect LNAPL - groundwater flow tends to be in a northeast direction - proposes to excavate immediately adjacent to the bulkhead that parallels Morgan Ave to a depth of 14 ft bg to investigate presence of sheen on both side of bulkhead in area of MC-1. the size of the excavation will be limited to 14 ft bg inside the bulkhead, and is expected to be the width of a single backhoe bucket (2 ft) and 6-8 ft long to allow the arm of the excavator to reach the required depth - will remove any LANPL from the excavation and install a 4 inch diameter recovery sump - property owner proposes to use previously approved conceptual approach dated 07/11/2005 - during weekly gauging, found product in wells FN-15 and FN-40 - report notes that well FN-12 is in close proximity to a water line that has somehow been damaged and is leaking water. the water level is just below grade from 09/02/16 through 09/16/16. abstract of interim remedial measure report dated Oct. 2016: - gauged wells FN-12, FN-14, FN-15, FN-28A, FN-34, FN-39, FN-40, FN-42, MC-1 and MC-2 - total of 5.87 gal of oil have been collected using the absorbent socks since May 2014 - total of 3.91 gal of oil have been collected by pumping since Dec. 18, 2015 - will replace boom in creek - will install an active LNAPL skimmer near the bulkhead to the Newtown Creek inlet that parallels Morgan Ave (in area of well MC-1) - weekly gauging data from 09/16/16 through 10/28/16 shows presence of product in wells FN-15, FN-40 and MC-1 (0.38 ft on 09/23/16) discussed with DEC Austin and DEC Vought. based on result of historical investigation and recent groundwater monitoring, the department will request: - installation of additional monitoring wells (south of FN-40, east of FN-14, northeast of FN-14, couple of well on north side of former southern tank complex, at least two wells east of MC-2 along the bulkhead) to confirm containment of plume and for continuous monitoring/product removal - continuation of well monitoring/product removal (on monthly basis) and submission of quarterly reports until site development a meeting with property owner is needed to discuss future actions and submission of a RAWP. 3:06 PM:- spoke with DEC Falls regarding requirements for bulkhead permit application. he mentioned that missing information in the application can be discussed during meeting with property owner in office. Caroline Kwan Project Manager Special Projects Branch U.S. Environmental Protection Agency Ph. (212) 637-4275 email: kwan.caroline@epa.gov Supinderjit Kaur Remedial Project Manager EPA, Region 2, ERRD-SPB-MPS PH. (212) 637-4167 email: kaur.supinderjit@epa.gov 11/08/16-Hiralkumar Patel. 8:52 AM:- left message for (and sent email to) Mr. McGaha requesting a call back. email copied to Mr. Schwartz and Mr. Cohen. 11/10/16-Hiralkumar Patel. 1:34 PM:- received call from Mr. McGaha. informed him that to discuss further remediation activities at the site and actions related to bulkhead repair/replacement work, the department likes to meet property owner, environmental contractor/consultant and contractor for bulkhead work. Mr. McGaha will call back after discussing with property owner. 11/18/16-Hiralkumar Patel. 12:04 PM:- received email from Mr. McGaha confirming meeting on 12/14/16. 12/06/16-Hiralkumar Patel. spoke with

NYC DEP HAZ MAT (Continued) **S102143390**

Mr. McGaha. he confirmed that Mr. Schwartz, Allan and himself will meet DEC on 12/14/16. asked him about any consultant/engineer who will be handling bulkhead repair/replacement project. he will contact property owner. 12/14/16-Hiralkumar Patel. 1:00 PM:- met with Mr. Schwartz, Mr. McGaha, Allan Francis, DEC Vought, DEC Urda, DEC Chan, DEC Greco and DEC Falls. Mr. Schwartz mentioned that they are planning to replace rotted sections of bulkhead above water line and planning to work during low tide. DEC permit unit has asked for detailed plan on bulkhead repair work, including containment procedure and counter measures on-hand. asked Mr. Schwartz to inform DEC prior to beginning of bulkhead work and report immediately of any petroleum discharge issue during bulkhead work. to remediate remaining petroleum contaminated areas at the site, Mr. McGaha proposed following: - a test pit trench perpendicular to bulkhead in the area of well MC-1 - placement of larger diameter recovery well in proposed trench in area of MC-1 with installation of skimmer at beginning and possible use of pump & treat technique later on - a pump test prior to beginning pump & treat operation in area of MC-1 to confirm radius of influence - in-situ remediation using oxidants in alley - a pilot test prior to application of oxidants in alley prior to in-situ remediation at the site, informed Mr. Schwartz and Mr. McGaha that the department requires additional monitoring wells to the north, east and south of existing wells MW-15, MW-14 and MW-40 to confirm plume containment and effectiveness of in-situ remediation. Mr. Schwartz mentioned that a re-zoning application has been submitted to city department for redevelopment of the site in a manufacturing building. asked Mr. Schwartz to submit copy of re-zoning application. Allan Francis **site manager** Ph. (347) 859-6925 email: allanfrancis73@gmail.com Arthur Schwartz, esq. PH. (732) 905-1008 email: arthur@aschwartzesq.com 2:59 PM:- sent email to Mr. McGaha requesting property owner's mailing address. email copied to Mr. Francis, Mr. Schwartz and LEP Management. 12/16/16-Hiralkumar Patel. 1:47 PM:- received email from Mr. McGaha including mailing address for property owner. Novack Burnbaum Crystal LLP. 675 Third Avenue, 8th Floor New York, NY 10017 Attn.: Edward Burnbaum 3:30 PM:- sent letter to owners of lot # 101 (Greenpoint Bushwick LLC.) and 207 (Bushwick Star Management LLC.) including approval for amended RIR dated 09/30/16 and requiring submission of RAWP within 90 days of the date of this letter (as per the signed consent order). asked them to include following in RAWP, which was agreed upon during meeting: 1) details about installation of sentinel wells on lot 207, 2) sampling methodology during installation of sentinel wells, 3) test pit investigation at location of MC-1, 4) active remediation at location of MC-1 and 5) application of oxidants to treat groundwater contamination on lot 207. letter emailed to DEC Urda, DEC Greco, DEC Falls, DEC Chan, Mr. Schwartz, Mr. McGaha and LEP Management. 12/19/16-Hiralkumar Patel. 2:52 PM:- received email from Mr. Schwartz including a copy of letter to NYC Dept. of City Planning. as per the letter, a site redevelopment is proposed including one (1) 10-story building. one of the site plan shows garage in cellar. no other construction details are available. 12/23/16-Hiralkumar Patel. 2:21 PM:- received email from Mr. McGaha including interim remedial measure report for Nov. 2016. -wells FN-12, FN-14, FN-15, FN-19, FN-22, FN-28A, FN-34, FN-39, FN-40, FN-42, MC-1 and MC-2 were gauged - based on all available data, groundwater elevations fluctuate between 1.22 ft bg at FN-12 on 08/18/16 to 13.85 ft bg at MC-1 on 11/25/16 - total of 4.31 gal of oil have been collected by pumping

NYC DEP HAZ MAT (Continued) **S102143390**

since Dec, 2015 - weekly gauging data from 11/08/16 through 12/02/16 shows presence of product in wells FN-15 (0.12 to 0.65 ft) and FN-40 (0.14 to 0.25 ft) 01/11/17-Hiralkumar Patel. received email from DEC legal including copy of full-executed modification to the consent order. 01/26/17-Hiralkumar Patel. received email from Mr. McGaha (at 6:40 PM on 01/25/17) including interim remedial measure report for Dec. 2016. -wells FN-12, FN-14, FN-15, FN-19, FN-22, FN-28A, FN-34, FN-39, FN-40, FN-42, MC-1 and MC-2 were gauged - based on all available data, groundwater elevations fluctuate between 1.22 ft bg at FN-12 on 08/18/16 to 13.85 ft bg at MC-1 on 11/25/16 - total of 4.40 gal of oil have been collected by pumping since Dec, 2015 - wells were gauged three times in Dec. 2016: 12/02/16, 12/06/16 and 12/22/16 - gauging data shows presence of product in wells FN-15 (0.22 to 0.33 ft) and FN-40 (0.18 to 0.24 ft) - proposes to submit a remedial action work plan by 03/13/17 02/06/17-Hiralkumar Patel. DEC Austin received an email (on 02/04/17) from Seth Friedland. he mentioned that his client is seeking to develop the site and they are having an exploratory meeting with OER on 02/08/17. Seth D. Friedland Friedland Law, LLC. PH. (212) 344-1400 Ext. 202 (917) 902-6386 Fax (212) 344-8735 Efax (646) 304-1916 email: sfriedland@friedland.law discussed with OAG Karpen and informed her about scheduled meeting between site developer and NYC OER. inquired her about status on environmental lien on property. 2/27/17-Vought-Conference call on 2/24/17 with RSE, Vought, and Patel. Friedland noted that the site developer he is working for is Arthur Schwartz, who is also the current property owner. Friedland noted that he and Schwartz went to OER to seek possible help on having NYC Dept of Planning rezone the site via a zoning application and were hoping that OER could facilitate the process. Friedland noted that they are considering redeveloping the property for commercial purposes and were intending to perform excavation for at least one underground level . Friedland noted that at time of conference call, his only authorized role was in the rezoning effort but that he may be also brought in as counsel for the environmental issues. Friedland also noted he know nothing of the bulkhead issues with DEC Permits and DEC to send him copy of last email chain. Friedland also noted that Magaha was currently working on RAP as previously discussed with DEC. Freidland also noted he knew of prior Consent Order on site and may possibly want to explore closure of the Consent Order so that Schwartz may enter the OER BCP Program. RSE and Vought replied that any possible closure of the Consent Order would have to go through DEC OGC. Friedland noted that they would proceed with developing the RAP until the possible zoning change is approved and that he would get back to DEC with more information. 2/27/17-Vought-Received email on 2/26/17 from Friedland with cc to RSE and DEC Patel that Randy, Jeff and Kumar, Glad we were able to catch up on Friday. In response to your questions and requests for further information about the project, and DEC s interest in the proposed development of this site, here is some further information about the proposed development project and the zoning changes that are going to be needed to see it through to fruition. Any assistance that DEC can provide of course would be very much appreciated. Here is a very quick summary of the our client s interaction so far with the Department of City Planning (DCP) on the critical zoning issues: First meeting with DCP on February 4, 2016: We need Zoning map amendment from M3-1 to M1-5 that would enable the redevelopment of the Premises with a ten (10) story, 495,370 square foot building. (A copy of the architect s renderings

NYC DEP HAZ MAT (Continued) **S102143390**

showing the proposed building is attached). Designed to align with the City s vision of the North Brooklyn IBZ. The proposal now contains one building (as opposed to two), which rises to ten (10) stories, and consists of 495,370 square feet of commercial floor area (office and retail building). (A copy of the most recent revised Proposed Plans from December 2016, is also attached hereto). Met with City Planning again, January 2017 (LAST MONTH): At that meeting, the following was discussed: 1)Need to Further Revise the plans to depict a more realistic proposal that will incorporate the following: a.Noise; b.Emissions; c.What floor plates could be used without the sky exposure plane; d.Parking whether we need all the proposed spaces and whether we should have the cellar parking when it is prone to flooding; e.Incorporating higher than the current 12 floor to ceiling heights; f.Pedestrian and vehicular (truck) access; g.Creek access; h.Flood resiliency; i.Types of businesses and how the newly constructed buildings will meet their needs; j.Ventilation - if there is going to be manufacturing use shared with commercial use; 2)Create an urban planning report to support the case for the density, which will include: a. Transportation; b. Neighboring uses; c.Waterfront esplanade 3.Marketing/real estate analysis that shows the proposed uses are needed in this neighborhood. Thanks again, and enjoy the remainder of your week-end. Regards . Vought added attached rendering and revised proposed plans to D2. Vought sent reply to Friedland with cc to RSE, Patel, OGC Urda, NYSOAG Karpen, DEC Greco and DEC Falls that Seth, It was good talking to you as well on Friday and thanks for the email below as well as the attached conceptual site plans. The plans show the development of an underground parking garage so this would certainly be optimum as it would likely allow for source removal down to and including the water table. The Department can assist in expediting the review of any proposed plans as well as participate in any meetings to facilitate approval of such plans. I will also inform both OGC and the NYSOAG of your possible request, as per our teleconference, to close the Consent Order, pending the rezoning of the site. I will also forward you the email chain with regards to the bulkhead and Permit issues we discussed on Friday. Thanks as well and keep us posted. Vought sent OGC Urda and NYSAOG Karpen spill notes above from Fridays call. Vought sent another email to Friedland that Seth, After checking my emails, I realized I have no external emails regarding the Bulkhead Permit request. Please contact Tamara Greco or Justin Falls, copied above, for more information regarding the permit request, if needed. Thanks, . Vought received reply from Friedland with cc to all that Thanks very much, Jeff. I sincerely appreciate it. 03/24/17-Hiralkumar Patel. 12:58 PM:- received email from Mr. McGaha including remedial action work plan. summary: - selected remedial alternatives involves isolating the historic fill over the entire footprint of the site with a cap in areas not already capped with asphalt or concrete and treating residual areas of petroleum contamination using in-situ chemical oxidation and multi-phase extraction for residual LNAPL, establishing an declaration of covenant and restrictions and environmental easement, along with site management plan and operation, maintenance and monitoring plan - capping of currently exposed soil will be performed using a demarcation layer, followed by subgrade material asphalt paving - in-situ chemical oxidation is proposed in the vicinity of monitoring wells FN-14, FN-15 and FN-40 - oxidant solutions would be injected into the soil and groundwater through 15 injection points constructed as temporary well points to a depth of

NYC DEP HAZ MAT (Continued) **S102143390**

approx. 4-5 ft bg, or 0-2 ft below the water table - three additional monitoring wells would be installed to monitor progress of oxidation remediation efforts in this area - multiphase extraction will be performed at the bulkhead with the Newtown Creek and near MC-1 to removal LNAPL and groundwater contamination - multiphase extraction will be operated until LNAPL is removed and groundwater contamination meets stable and acceptable concentrations - following completion of RAWP implementation, quarterly groundwater monitoring would be implemented to document effectiveness of the remedy - groundwater would be samples for one year (four monitoring events) ---------- - track 4 - industrial restricted use soil cleanup objectives are proposed ---------- the work plan does not include sampling methodology during installation of sentinel wells.
07/10/17-Hiralkumar Patel. 10:25 AM:- spoke with Mr. McGaha inquiring about current status on product recovery. he will submit report and interim work plan to address LNAPL contamination. 09/18/17-Hiralkumar Patel. received email from Mr. McGaha (at 11:55 AM on 09/12/17) including an interim remedial measure progress report (last report submitted on 01/25/17). report included results of gauging events conducted until 09/05/17. since 12/22/16, product noted in following wells: product thickness (in ft):
----------FN-14------FN-15------FN-40------MC-1
01/12/17----------0.12-------0.12
03/09/17----------0.28-------0.66
03/30/17----------0.42----------5.14
04/06/17----------0.68-------0.31------3.59
04/19/17----------0.36----------4.89
04/28/17----------0.29-------0.75------3.71
05/11/17----------0.62-------1.56------3.72
05/26/17----------0.46----------3.37
06/02/17----------0.81----------3.01
08/08/17--------0.20-------0.30----------1.10
08/15/17--------0.10-------0.20----------0.80
08/23/17--------0.10-------0.20----------0.40
08/29/17--------0.10-------0.10----------0.29
09/05/17--------0.20-------0.20----------0.40 Mr. McGaha is preparing proposal for operation of an alternative LNAPL remediation system. received email from DEC Ian Beilby. he received pics from NYC's consultant claiming NAPL seeping from bulkhead along the site. 09/20/17-Hiralkumar Patel. 1:15 PM:- visited site and met Arron Abraham (347-773-9633, aarbenabe@yahoo.com) from property management office. inspected creek inlet adjacent in northwest corner of the site (near well location MC-1). noted two layers of sausage booms covering southern half of bulkhead which is owned by former morgan terminal. minor sheen was noted within boom area. no signs of product were noted outside the booms. need to re-inspect area during low tide. 09/25/17-Hiralkumar Patel. received powerpoint presentation from DEC Ian Beilby. pics show seepage of free product from bulkhead towards northern section of inlet which is not covered by booms. 10:08 AM:- sent email to Mr. McGaha inquiring about plan for alternative LNAPL remediation system. email copied to LEP Management, Mr. Schwartz and Mr. Abraham. 09/27/17-Hiralkumar Patel. 9:30 AM:- visited site and met Mr. Abraham. noted heavy sheen between absorbent booms and bulkhead. some of the sheen had escaped boom area as one end of the boom was in air during low tide. spoke with Mr. McGaha. asked Mr. Abraham and Mr. McGaha to adjust booms to contain oil seepage. also asked Mr. McGaha about remediation plan. after

NYC DEP HAZ MAT (Continued) **S102143390**

reviewing pump option, he wants to use previously proposed remedial method: installation of sump between well MC-1 and bulkhead and pumping oil into oil/water separator and discharge water into sewer system after getting necessary permit. 10/03/17-Hiralkumar Patel. 11:51 AM:- received email from Mr. Abraham. he mentioned that a hard boom with sweeps will be installed in the creek. 10/04/17-Hiralkumar Patel. 10:25 AM:- left message for Mr. Abraham inquiring about installation of hard boom and sweeps, and update on site redevelopment plans. 11/04/17-Hiralkuamr Patel. 5:30 PM:- visited site while investigating a report of oil sheen (spill #: 1707515) in Newtown Creek. found free phase product between the bulkhead and boom in the creek. petroleum sheen were noted outside the boom area. a drainage pipe was visible in bulkhead wall due to low tide at the time of inspection. no signs of oil discharge from the drainage pipe. 11/09/17-Hiralkumar Patel. 12:16 PM:- left message for Mr. McGaha. 11/16/17-Hiralkumar Patel. received email from Wardah Azhar from CDM Smith (EPA consultant working on Newtown Creek superfund cleanup) inquiring about the site. Wardah Azhar CDM Smith Ph. (303) 383-2364 email: azharw@cdmsmith.com 11/28/17-Hiralkumar Patel. 11:16 AM:- received message from Mr. McGaha. he mentioned that remediation system for LNAPL has been installed. 12:02 PM:- spoke with Mr. McGaha. he mentioned that a remediation system has been installed and he likes to discuss it prior to turning it on. asked Mr. McGaha to submit details about the remediation system for review. 12/07/17-Hiralkumar Patel. 12:28 PM:- left message for Ms. Azhar. 12:37 PM:- received call from Ms. Azhar. she requested copy of documents/reports received since 2015. 12/11/17-Hiralkumar Patel. as instructed, reports requested by CDM were sent to DEC Austin. 06/07/18-Hiralkumar Patel. DEC Austin forwarded email from Newtown Creek Alliance including site pics of collapsed bulkhead. 8:11AM:- left message for Mr. McGaha. DEC Piper inspected the site and found no sheens emanating from the shoreline. discussed with DEC Stephen Watts in permits. Steve mentioned that they have sent a second incomplete notice on 12/28/16 for an application originally received on 07/20/15. they have not received any response after that. 07/11/18-Hiralkumar Patel. 10:59 AM:- spoke with Mr. McGaha and inquired him about details of remediation system as discussed in Nov. 2017. he mentioned that the system was installed and being managed/monitored by owner's on-site representative. Mr. McGaha will submit remediation system details and summary of work performed since Sept. 2017, by end of the week. Mr. McGaha doesn't know anything about bulkhead work. 07/13/18-Hiralkumar Patel. 1:19 PM:- sent email to Mr. McGaha and asked him to submit remediation system design details and summary of work performed since Sept. 2017. 1:33 PM:- received email from Mr. McGaha including an IRM progress report and design details of LNAPL recovery system installed at well location MC-1. the LNAPL recovery system has been running since Oct. 2017 and has collected approx. 140 gal of oil. according to on-site system attendant, since the LNAPL pumping system has been installed, a significant decrease has been observed on the sheen in the Newtown Creek. also as per site attendant, bulkhead was partially collapsed at the site. report also mentioned that a water leak occurred in the alley in Feb. 2018, causing water to rise to grade in wells FN-39 and FN-12, making it impossible to measure a depth to water at these wells. few weeks later, 04/10/18, wells FN-15a and FN-14 were also under water. the water line leak is reportedly going to be repaired in the near future. report included results of gauging events

NYC DEP HAZ MAT (Continued) **S102143390**

conducted until 07/03/18. since 09/05/16 (last IRM report), product was noted in following wells: product thickness (in ft):
----------FN-14------FN-15------FN-40
12/01/17----------0.18
05/29/18--------0.91-------0.82 06/05/18--------0.70-------1.10
06/12/18--------0.01-------0.69 06/19/18--------0.02-------0.09
06/26/18--------0.01-------1.10 07/03/18----------0.80
08/10/18-Hiralkumar Patel. spoke with DEC Falls. he inspected site on 06/21/18 after bulkhead collapsed. he noticed repair activity without proper permit and asked to stop work. when he re-inspected the site in early July, bulkhead work was completed. Justin issued a NOV on 07/17/18. recently, he received a permit application to legalize previously replaced bulkhead. 09/05/18-Hiralkumar Patel. 12:40 PM:- visited site. currently, the site is being used by a lumber company and almost entire site is full of lumber. on-site tenant mentioned that they moved to the site in Nov. 2017 and doesn't know anything about on-site well monitoring. inspected water channel along the side of the property. silver sheen was noted within/outside the boom at the end of the channel near well MC-1. found partially sunken boat (boom around it) in middle of the channel along the side of the property. no sheen was noted around the boat. inspected on-site building near well MC-1 (former maintenance building), but no oil recovery system was found within the building. inspected alley on south side of the site. multiple 5 gal oil pails and two 55 gal drums were found along the building wall. 5 gal pails were empty but open. one of the drum was closed, but the other drum contained oil to the top and was open. 1:12 pm:- left message for Mr. McGaha and informed him about pails/drums in alley. asked him to immediately secure oil drum and remove other containers. 1:59 PM:- received call from Mr. McGaha. he mentioned 5 gal pails and 55 gal oil drum were removed from the site when lumber company occupied the site. the closed drum contains boom/dirt removed during well monitoring activities. he also confirmed that site representative has closed the oil drum. oil drum and pails will be removed soon. asked Mr. McGaha to schedule a site inspection. 10/05/18-Hiralkumar Patel. 9:30 AM:- visited site and met Mr. McGaha and Arron Abraham. Mr. McGaha showed location of oil recovery tank which is near northeast corner of main building, between the building wall and south bulkhead at the end of water channel. a compressor for the oil recovery system is in basement of main building. total of 240 gal of oil has been recovered since beginning of oil recovery using double diaphragm pump. the 275 gal tank was pumped out last month. asked Mr. McGaha to submit details about time duration and amount recovered from well MC-1. inspected wells in alley on south side of the site where oil found in well FN-15 only. based on shallow depth of groundwater beneath the alley and detection of oil in only one well now, suggested Mr. McGaha/Mr. Abraham to expedite remediation via soil excavation, removal of free phase product and installation of a larger diameter well in the excavation to recover any remaining product. Mr. McGaha will discuss with property owner. Mr. McGaha also proposed to install an another well, north of well MC-1 to increase product recovery using two wells, instead of one. asked him to submit email with plan for additional well installation and remediation via excavation (if approved by property owner) in south alley. 02/07/19-Hiralkumar Patel. discussed with DEC general counsel regarding compliance of existing consent order and pending bulkhead violations. DEC legal will contact property owner to discuss possible way to expedite both

NYC DEP HAZ MAT (Continued) **S102143390**

petroleum remediation and correction of bulkhead violations. 02/12/19-Hrialkuamr Patel. 9:28 AM:- sent email to Mr. McGaha requesting update regarding proposed installation of an additional well near MC-1 to expedite LNAPL recovery, and possible excavation in south alley to remove heavily contaminated material. email copied to lepmanagement89@gmail.com. 03/11/19-Hiralkumar Patel. received email from Mr. McGaha (at 7:49 PM on 03/10/19) including a RAWP. 04/19/19-Hiralkumar Patel. reviewed RAWP submitted on 03/10/19. the RAWP proposes: 1) isolating the historic fill over the entire footprint of the site with in areas not already capped with asphalt or concrete, 2) treating residual areas of contamination via excavation (approx. 25 ft by 35 ft to a depth of 5 ft bg) in alley. endpoint samples from sidewalls will be collected after excavation in alley. bottom samples will not be collected as excavation will be below the water table. a larger diameter (not specified in the RAWP) will be installed with excavation area for post remediation well gauging for a period of three months. 3) multi-phase extraction (including oil/water separator and discharge permit) for LNAPL near well MC-1 via installation of additional recovery wells. multiphase extraction will be operated until LNAPL is removed and groundwater contamination meets stable and acceptable concentrations 4) establishing an declaration of covenant and restrictions and environmental easement. one of the prohibition will be residential land usage without NYSDEC approval 5) submission of site management plan including groundwater sampling from existing wells. groundwater will be sampled for one year (four monitoring events) for VOCs, SVOCs and metals. the RAWP needs to be revised due to following: - the work plan does not include size of replacement well in the alley after excavation - the work plan proposes to analyze soil samples for EPH and SVOCs, and not VOCs/SVOCs - schedule milestone refers to weeks from remedial action start 10:16 AM:- spoke with Mr. McGaha and discussed the proposed RAWP dated Mar. 2019. he mentioned that a 6 inch well will be installed in excavation in alley. informed Mr. McGaha that a revised RAWP is needed including following: - well size in alley excavation - all soil/groundwater samples must be analyzed for VOCs/SVOCs/metals - schedule milestone should be weeks from the RAWP approval (not weeks from remedial action start) 05/08/19-Hiralkumar Patel. 10:45 AM:- sent email to Mr. McGaha and asked him to submit a re-revised RAWP including/correcting following: - size of replacement well that will be installed in the alley after excavation - analysis of all samples for VOCs and SVOCs - schedule milestones should be weeks from the RAWP approval instead of weeks from remediation action start - clarification on # of recovery wells that will be installed around the existing well MC-1 email copied to lepmanagement89@gmail.com, Arthur Schwartz (arthur@aschwartzesq.com) and Aaron Abraham (aarbenabe@yahoo.com). 05/23/19-Hiralkumar Patel. 1:51 PM:- sent email to Mr. McGaha inquiring updates on submission of re-revised RAWP. email copied to lepmanagement89@gmail.com, Arthur Schwartz and Aaron Abraham. 05/30/19-Hiralkumar Patel. 7:41 AM:- received email from Mr. McGaha with a re-revised RAWP including information requested in email dated 05/08/19. a 6 inch diameter well will be installed in a proposed excavation in the alley. the RAWP does not specify total # of wells be installed around MC-1, but proposes to install more product recovery points if needed to achieve remediation completion date of three years. 01/14/20-Hiralkumar Patel. 2:30 PM:- spoke with Mr. McGaha inquiring updates. he mentioned that property owner implemented the proposed Remedial

NYC DEP HAZ MAT (Continued) **S102143390**

Action Work Plan dated May 2019 without being approved by the Department. property owner conducted excavation in alley in Nov. 2019. Mr. McGaha was informed about field work shortly before and was asked to collect endpoint samples. Mr. McGaha visited the site during excavation and collected endpoint samples. the excavation was backfilled without installing proposed larger diameter well. Mr. McGaha has installed two (2) 2-inch diameter wells around existing well MC-1, but no product was noted in new wells. Mr. McGaha stated that the 275 gal product recovery tank was pumped out last month. asked Mr. McGaha to submit report for work conducted at the site. 01/15/20-Hiralkumar Patel. 9:00 AM:- visited site. noted gravel surface in alley indicating possible excavation activities in the alley. no sheen noted in the creek. previously installed boom was damaged and needs to be replaced. noted one new monitoring well near southwest corner of the on-site building (approx. 25 ft away from previously installed well MC-1 near bulkhead). 9:19 AM:- spoke with Aaron Abraham and asked him to 1) submit report for work done to date by the end of 01/22/20, and 2) replace boom in the creek by tomorrow. Aaron Abraham Ph. (347) 294-9566 email: aarbenabe@yahoo.com 10:36 AM:- sent email to Mr. Abraham and asked him to 1) replace boom in the creek by tomorrow, and 2) submit report for activities conducted since Jan. 2018. asked him to submit report by the end of 01/22/20. email copied to Mr. McGaha. 11:44 AM:- received call from Mr. Abraham. he mentioned that Mr. McGaha has ordered a new boom which will be placed in the creek upon arrival (should be done before 01/18/20). he also mentioned that on-site meeting (to gauge wells) will be scheduled after submission of a required report by 01/22/20. 01/23/20-Hiralkumar Patel. 9:17 AM:- sent email to Mr. Abraham and asked him to immediately submit 1) confirmation of replacement of absorbent boom in the creek, and 2) report including details of remediation activities conducted at the site since Jan. 2018. email copied to Mr. McGaha. 01/24/20-Hiralkumar Patel. received email from Mr. McGaha (at 8:10 PM on 01/23/20) including a limited RAR. the report was found incomplete and needed revision due to following: - report is a mixture of a field activities and proposed remedial action. need to remove information previously submitted in the Remedial Action Work Plan dated May 2019 - details about slug test are missing - the report is missing Figure 3, Figure 5, scaled site map with excavation area and endpoint sample locations, endpoint sampling depths, and pictures confirming replacement of boom in the creek - as per first paragraph in Section 3.5, base samples were not collected as excavation extended below the groundwater, but the second paragraph in the same section mention about collection of base samples. also third paragraph in section 3.9 states groundwater was not encountered in the excavation' - there is confusing details about depth of excavation in the alley. as per text on page 11, area was excavated to depth of 8 ft bg, but page 34 states excavation ranged from 5 to 12 ft bg - the report is missing result of waste characterization sampling - as per Section 3.4, excavation was conducted in the vicinity of monitoring wells FN-14, FN-15 and FN-40, but review of attached pictures suggests excavation did not include area of well FN-14 where near 3 feet of product has been noted since 08/24/2018 ---------- (this was clarified later in a revised Limited RAR dated Feb. 2020 submitted on 02/06/20) - the Report is missing detailed logs for wells MC-3 and MC-4. as per the Report, these wells were installed on 05/19/19, but there is no mention about this work in a RAWP submitted on 05/30/19. - section 3.2.9 reads Field notes

NYC DEP HAZ MAT (Continued) **S102143390**

are included in Appendix 4 , but there are no field notes in the report. - the report is missing schedule for installation of replacement well FN-15R and frequency of proposed VEFRring. the Report should include a separate section for proposed remedial activities (addendum to the previously submitted RAWP) such as installation of replacement well FN-15R (including a map with well location), vacuum enhanced fluid recovery (including frequency) at well location MC-1, monthly gauging (and product removal, if noted) of wells in the alley, and groundwater sampling to confirm achievement of remedial goals. 9:07 AM:- left message for Mr. McGaha. 10:02 AM:- received call from Mr. Abraham requesting to schedule a site inspection. informed him that the submitted Limited RAR needs to be revised and site inspection will be scheduled upon review of the revised Limited RAR, once received. 1:45 PM:- sent email to Mr. McGaha and asked him to submit a revised Limited RAR. email copied to Mr. Abraham, Arthur Schwartz and LEP Management. 02/03/20-Hiralkumar Patel. 1:04 PM:- sent email to Mr. McGaha and asked him to submit the revised Limited RAR. email copied to Mr. Abraham, Arthur Schwartz and LEP Management. 02/06/20-Hiralkumar Patel. received email from Mr. McGaha (at 12:05 AM today) including a revised Limited Remedial Action Report which was found incorrect/incomplete. summary: - a slug test was performed at well FN-34 on 03/08/19 - well was pumped while continuous depth to groundwater measurements were collected. when the water level drooped to within one foot of the bottom of the well, the well was allowed to recharge while continuous depth to groundwater measurements were collected - results of three tests presented a hydraulic conductivity of 5.774e-002 m/day - volume of water collected over time was measured and a recharge rate of 2 gal/min was determined - results of slug test indicate that the proposed 5 gal/min oil-water separate could accommodate two multiphase extraction wells and one single phase extraction well --------- - current system near MC-1 is equipped with an oil-water separator, but the system bypasses the oil-water separator and collects only oil from a skimmer positioned in MC-1 - two additional wells MC-3 and MC-4 were installed on 05/19/19 - both wells MC-3 and MC-4 were 2 inch in diameter and 18 ft deep, with screen from 5 to 18 ft bg - groundwater was noted between 9.2 and 9.9 ft bg in wells MC-3 and MC-4 - wells MC-3 and MC-4 were found dry during gauging on 01/03/20 and 01/10/20 - absorbent boom in the creek was replaced 11/16/16, 09/08/17, 11/15/17, 05/31/18, 05/10/19, 08/15/19 and 01/19/20 - excavation was conducted in alley on 11/02/19 - LNAPL has not been identified in FN-14 since Sept. 2017. previously submitted table of well gauging data presents 0.0 as a depth to oil but erroneously reported as oil thickness as a result of spreadsheet calculation error ---------- - LNAPL has not been identified in FN-40 since Dec. 2017 - soil 'near' FN-4 and 'around' FM-15 (25 ft wide by 35 ft long area) were excavated to an average depth of 6 ft bg with over excavation (to 12 ft bg) near former well FN-15 - well FN-15 was removed during excavation - neither groundwater nor LNAPL accumulated in the excavation - based on slug test, absence of groundwater in excavation may be attributable to the density of the soil at the site - a water pipe was damaged during excavation activities resulting in water entering the northeast end of the excavation ---------- - accumulated water was isolated by damming the water at the northeast end of the excavation - water was mixed with soil and disposed with the soil - due to heavy use of the alley, excavation occurred on Saturday and all excavated material was live-loaded directly into

NYC DEP HAZ MAT (Continued) **S102143390**

trucks - total of 205.1 tons of soil were removed - six endpoint sidewall soil samples were collected at the base of the excavation around the perimeter and two endpoint bottom soil samples were collected for 8260/8270 analyses proposed remedial activities (page 27): - will replace former well FN-15 with a 6 inch diameter well FN-15R following the re-surfacing of the area - well FN-15R will be installed to a depth of 15 ft bg, with 1 ft of riser and 14 ft of screen - monthly gauging for wells FN-15R, FN-35, FN-40, FN-12 and FN-14 with product removal, if noted - wells in alley will be gauged for a period of six months - well gauging will be discontinued if no LNAPL noted in alley after six month's monitoring - single phase LNAPL removal will continue at MC-1 until LNAPL is removed from this well - VEFR will be performed at MC-1 on a quarterly basis until LNAPL is removed from this well - absorbent boom in the creek will be maintained and replaced as needed - wells MC-1, MC-2, MC-3, MC-4, FN-34, FN-28A and GQ-41 will be sampled for VOC/SVOC to investigate groundwater near the creek - wells FN-12, FN-14, FN-15R, FN-39, FN-40 and FN-22 will be sampled for VOC/SVOC to investigate groundwater near the alley - interim remedial measure progress report will be submitted semiannually - upon approval of RAWP, site capping will be performed - a RAR will be submitted including deed notice, engineering control for soil, monitored natural attenuation for groundwater under site management plan as per gauging data table, product was not observed in any well except MC-1 and FN-15 since Dec. 2017. as per submitted report, total of twelve (12) wells are currently being monitored: FN-12, FN-14, FN-19, FN-22, FN-28A (or FN-28), FN-34, FN-39, FN-40, FN-42, MC-2, MC-3 and MC-4. well FN-15 was recently removed during excavation in alley and a product recovery system installed in well MC-1. 10:05 AM:- sent email to Mr. McGaha and asked him to submit a re-revised report correcting/including following: - last bullet on page 30 reads: Recorded Declaration of Covenants and Restrictions (if required) . This is required. - as per key note on figure 3, endpoint sample locations are indicated as proposed monitoring well locations - as per list of Figures on page 4, Figure 5 should be Location of Waste Classification and Post Excavation Sampling Points , but figure 5 on page 48/49 is surrounding Land Use Map - as per section 2.2.9 on page 27, field notes should be in Appendix E, but it only includes site photographs - as per section 2.4 on page 27, excavation was performed in the vicinity of monitoring wells FN-14, FN-15 and FN-40, but as per last paragraph on page 20, soil near FN-40 and around FN-15 were excavated - as per appendix list on page 6, Appendix F should be Result of Slug Test, but it is missing - analytical results of waste classification are missing in Appendix G - report is missing pics of replaced boom in the creek - report missing couple of pages on Table 1 (missing gauging data for 08/31/18 to 12/07/18, 05/10/19 to 08/02/19, and 11/08/19 to 01/03/20) email copied to Mr. Abraham, Arthur Schwartz and LEP Management. 02/12/20-Hiralkumar Patel. received email from Mr. McGaha (at 4:52 PM on 02/11/20) stating that replacement well at FN-15 has been scheduled for installation for early next week. 02/20/20-Hiralkumar Patel. received email from Mr. McGaha (at 3:48 PM on 02/19/20) stating that well installed is rescheduled for next week. 02/26/20-Hiralkumar Patel. 2:17 PM:- received email from Mr. McGaha. he mentioned that they have rescheduled the well installation for next Tuesday (03/03/20). they are trying to schedule a vacuum extraction event for next Tuesday also. 03/02/20-Hiralkumar Patel. received email from Mr. McGaha (at

NYC DEP HAZ MAT (Continued) **S102143390**

12:22 PM on 02/28/20) with a revised Limited RIR including correct/missing information as requested in email dated 02/06/20. 05/21/20-Hiralkumar Patel. 3:05 PM:- received email from DEC Austin. he received pics/video from Newtown Creek Alliance showing water leak from the site (which now occupied by a concrete plant) into the creek and cement dust cloud over the concrete plant. 05/26/20-Hiralkumar Patel. 10:11 AM:- sent email to Mr. McGaha has asked him to provide update on installation of well FN-15R and result of well gauging/VEFRring. also asked him to mark maps for location of MC-3 and MC-4. 1:20 PM:- visited site to confirm report of water leak and cement dust at the site. no cement dust cloud or water leak noted at the site. no petroleum sheen noted in boomed area at the end of the creek. reviewed video sent by Newtown Creek Alliance which shows low water level in the creek. as the water level in the creek was high during the inspection, there was no water leak observed. the northwest portion of the site (at the end of creek where well MC-1 is located) was previously used as a parking lot and now being used for lumber storage. the remaining site (more than 75%) which used to be a lumber storage yard until late 2019 is now occupied by a concrete plant. as per lumber yard operator, they sold site lease in Nov. 2019 and construction of the concrete plant begun in Nov. 2019. the concrete plant started its operation in Feb. 2020. concrete plant uses entrance on Morgan Ave for truck entering the plant and uses access at the end of south alley as exit route for trucks. the entire site is now capped with concrete surface. noted a new well (possibly FN-15R proposed in Limited RAR) in previously excavated area in the alley. lumber is stored, around existing wells, on northwest portion of the site. due to heavy operation, could not confirm existence of previously installed monitoring wells in the concrete plant area. 07/08/20-Hiralkumar Patel. 12:24 PM:- sent email to Mr. McGaha and asked him to provide update on installation of replacement well and well monitoring/product recovery. 07/09/20-Hiralkumar Patel. Willis Elkins (welkins@newtowncreekalliance.org) of Newtown Creek Alliance reported another spill (# 2002669) due to sheen observed in creek. 07/10/20-Hiralkumar Patel. 10:12 AM:- spoke with DEC Sekhon who visited site yesterday. he did not observe any petroleum sheen in or out of the boom area. 07/23/20-Hiralkumar Patel. DEC Austin received a complaint from Newtown Creek Alliance about some water discharge from the concrete plant at the site. 12:30 PM:- visited site to inspect any dust/oil discharge into the creek from the site. noted water dripping from behind the bulkhead along the concrete plant, but no signs of any concrete dust or petroleum discharge noted. noted some silver sheen at the end of creek, but no petroleum sheen was noted in the creek. during inspection, noted two 55 gal drums near well MC-1. also noted that the well MC-1 was open and oil recovery pump was outside the well. 07/27/20-Hiralkumar Patel. DEC Austin received email from Newtown Creek Alliance including pics of drum/oil recovery hose near well MC-1. 07/28/20-Hiralkumar Patel. discussed with DEC Austin. he asked to readjust hard boom to close open area at one end and also to replace dirty sausage boom. 9:28 AM:- spoke with Mr. McGaha and inquired him about open well MC-1. Mr. McGaha stated that Aaron (site representative) reported some issue with float within the well. so Aaron removed oil recovery system to fix the float. asked Mr. McGaha to schedule site visit to fix hard boom/replace sausage boom/gauge wells. 10:37 AM:- sent email to Mr. McGaha and asked him to provide site updates (including installation of well FN-15R and product recovery) and schedule for boom

NYC DEP HAZ MAT (Continued) **S102143390**

fix/replacement. email copied to Mr. Abraham, Arthur Schwartz and LEP Management. 07/29/20-Hiralkumar Patel. 2:31 PM:- received email from Mr. McGaha stating that contractor is expected to tighten the hard boom and replace the soft boom tomorrow. he also mentioned that the LNAPL collection drum was reportedly a temporary condition and has been cleaned up. 07/31/20-Hiralkumar Patel. 2:25 PM:- received email from Mr. McGaha including site pics confirming fixing/replacement of booms. he mentioned that the soft boom has been replaced and a pipe was installed along the bulkhead to allow the rise and fall of the hard boom that is now closer to the bulkhead. also, the drums near MCMW-1 have been cleaned up. 08/03/20-Hiralkumar Patel. DEC Austin received pics from Newtown Creek Alliance showing some used booms stockpiled atop the bulkhead. 1:40 PM:- sent email to Mr. McGaha including pics of used booms stored atop the bulkhead. asked him to have these booms removed immediately. also asked him to submit an interim remedial measure report as proposed in the limited RAR. 08/05/20-Hiralkumar Patel. discussed with DEC Austin, OGC and RD. based on review of available information, Austin asked to visit the site during low tide to inspect bulkhead/outfall adjacent to the site. 10:27 AM:- sent email to DEC Susan Maresca requesting help to get tide cycle near the site. email copied to DEC Austin. 08/06/20-Hiralkumar Patel. 6:00 PM:- visited site during low tide. no signs of oil seepage were noted from bulkhead near well MC-1 or from an outfall (which is approx. 50-60 ft north of well MC-1 location). noted some open areas in bulkhead. no sheen was noted on water. oily garbage bag and wheelbarrow were noted on-land near well MC-1. also noted garbage bags (possibly containing dirty booms as per site occupant) on side of bulkhead. the soft boom that was placed in the creek on 07/30/20 was found partially soaked and needs to be replaced. 6:28 PM:- left message for Mr. McGaha. 08/07/20-Hiralkumar Patel. 1:11 PM:- sent email to Mr. McGaha including site pics taken yesterday. asked him to have boom in creek replaced with clean one, clean/remove oily debris and bags containing used booms. 08/11/20-Hiralkumar Patel. 11:20 AM:- received email from Mr. McGaha. he mentioned that the boom in the creek is new. a piece of metal roofing fell in the water, landing on the boom and causing it to be stained with mud. the spent boom has been secured in drums which should be picked up next week. Mr. McGaha stated that the Interim Remedial Measures Report is being finalized, and needs to be reviewed by the property owner. 08/19/20-Hiralkumar Patel. 12:03 PM:- received email from Mr. McGaha including an IRM report which was found incomplete/unacceptable. the report also includes information that has already been submitted previously. 2:34 PM:- sent email to Mr. McGaha and asked him to submit a revised report including only details of work performed since Jan. 2020. asked him to submit a revised report including/correcting following: - the report states on page 10 that 'capping of the site with concrete was performed between March and May 2020', but as per on-site occupant the site was capped and the on-site concrete plant was in operation by Feb. 2020. Please confirm this timeline and update current use of the site - revised Table 1 including well gauging measurements since Jan. 2020 - remove tables 2 (post excavation sample results) and 3 (soil cleanup objectives) - revised scaled site plan including 'all' existing monitoring wells (submitted figures don't include location of wells MC-3, MC-4 and FN-15R) - (no need for Fig. 2 and 3 which were submitted previously in the Limited RAR) - construction details (well depth/diameter, screen length/depth, riser length/depth) of

NYC DEP HAZ MAT (Continued) **S102143390**

replacement well MW-15R - disposal manifest for oil impacted booms removed from the creek to date. - details about method/condition that will be used to determine need for vacuum enhanced fluid recovery from well MC-1 - schedule for sampling of existing wells for lab analysis - revised schedule for well gauging and report submission {all existing wells must be gauged monthly (instead of quarterly) and reports must be submitted quarterly (instead of annually)} email copied to Mr. Schwartz, LEP Management and Mr. Abraham. 08/20/20-Hiralkumar Patel. 10:21 AM:- received email from Willis Elkins from Newtown Creek Alliance including pics showing accumulation of dark material on outside of hard boom at the site. 2:30 PM:- visited site to confirm any product seepage/accumulation inside/outside boom. no signs of any sheen or product seepage were noted in the creek. noted few 55 drums at the site possibly storing previously removed soft booms that were stored in garbage bags atop bulkhead. 2:44 PM:- sent site pics to DEC Austin. 08/28/20-Hiralkumar Patel. 10:53 AM:- received email from Mr. McGaha including a revised IRM report but it needs to be re-revised to clarify/correct/include information. 09/09/20-Hiralkumar Patel. 10:52 AM:- sent email to Mr. McGaha and asked him to submit re-revised report including/correcting/clarifying following: - as per information provided to date, the oil recovery system in well MC-1 is equipped with floatable sensor and it pumps only oil and not oil and water. and as per the revised report, the 275 gal tank associated with the oil recovery system has been emptied five times since installation. is that mean, approx. 1,000 gal of oil recovered from MC-1? or does this system pumps water also? if it pumps water also, then what is % of oil in total volume removed from the tank? - the well gauging measurement table needs to be revised. first of all, it does not include any details about depth to water for wells FN-12, FN-39, MC-2, MC-3 and MC-4 (as per well data monitoring forms included in Appendix E, wells MC-3 and MC-4 were found dry but this information is missing in the table). second, there are two different sets of data for 01/10/2020. third, as per the table, well FN-15 was present with no product during gauging in month of Jan, but the well was removed during excavation in Nov. 2019. - include well gauging data after 07/10/20 also asked him to provide schedule for next well gauging. as per the report, there are total of fourteen (14) wells available to gauge. asked Mr. McGaha to make sure that all fourteen wells are accessible during this site visit. also recommended him to collect groundwater samples from these wells during the visit. email copied to Mr. Schwartz, LEP Management and Mr. Abraham. 09/24/20-Hiralkumar Patel. 12:49 PM:- sent email to Mr. McGaha inquiring update on re-revised report and schedule for next well gauging. email copied to Mr. Schwartz, LEP Management and Mr. Abraham. 10/09/20-Hiralkumar Patel. 11:25 AM:- received email from Mr. McGaha. he mentioned that groundwater is influenced by the tide and at times the floatable sensor is swamped resulting in the collection of water rather than oil. also the floatable sensor can stick causing it to collect water. tank pumping contractor reported presence of 10-20% of oil in the tank. Mr. McGaha stated that gauging was performed at MC-3 and MC-4 but notation of no water was not added to the table. gauging was not performed at MC-2, since this well is no longer accessible. well FN-12 has not been relocated since the excavation in the alley. a metal detector will be used to locate and uncover this well location. Mr. McGaha will submit an amended report including all available well gauging data. 2:09 PM:- sent email to

NYC DEP HAZ MAT (Continued) **S102143390**

Mr. McGaha and inquired him about reason for no accessibility to well MC-2. also asked him to schedule site inspection on 10/22/20, if possible. 2:41 PM:- received email from Mr. McGaha stating that well MC-2 is not accessible as tenant placed storage container on it. 10/14/20-Hiralkumar Patel. 10:10 AM:- received email from Mr. McGaha stating that container (over well MC-2) cannot be moved. 10/22/20-Hiralkumar Patel. 9:00 AM:- visited site and met Mr. McGaha and Aaron Abraham. Aaron gauged wells MC-1, MC-3, MC-4, FN-14, FN-15R, FN-19, FN-22, FN-28, FN-34 and FN-40. well MC-2 was not accessible due to storage container at the location. wells FN-12, FN-39 and FN-42 were not accessible as were buried under dirt/concrete. Mr. McGaha had brought GPR to locate wells FN-12, FN-39 and FN-42. during well gauging in south alley, another monitoring well was noted south of well FN-40 and west of well which is listed as FN-22 in reports from McGaha Consulting. reviewed old site maps and noted that the well FN-22 listed in reports from McGaha Consulting is actually well FN-24 and the unknown well noted during site visit earlier today is well FN-22. inspected creek during the site visit. sheen or product was not observed in the creek, but the soft boom was found stained. asked Mr. McGaha to replace the soft boom in the creek. observations during well gauging: - well MC-1: this well is equipped with an oil recovery system and has a floating sensor in it. the sensor was removed for well gauging. layer of oil was noted on floating sensor. very little oil was noted on water using oil/water interface, but noted a thick layer of oil on oil/water interface probe once removed from the well. Mr. McGaha mentioned that system in well MC-1 continuously pumps oil into oil/water separator tank and that could be the reason for not detecting much oil using the oil/water interface. asked Mr. McGaha to gauge oil/water separator tank weekly. also asked him to turn off oil recovery system in MC-1 once a month and gauge well MC-1 24 hours after turning off the system. - well MC-3: this well is within 10 ft to the northeast of well MC-1. no product was noted in well MC-3. - well MC-4: no oil detection by oil/water interface probe, but oil sheen noted on the probe. asked Mr. McGaha to place an absorbent sock in the well and have the sock inspected/photographed weekly. - well FN-14: no product/sheen observed - well FN-15R: no product/sheen observed - well FN-19: no product/sheen observed - well FN-22 (actually well FN-24 as per historical maps): no product/sheen observed - well FN-28: no product/sheen observed - well FN-34: no oil detection by oil/water interface probe, but oil sheen noted on the probe. asked Mr. McGaha to place an absorbent sock in the well and have the sock inspected/photographed weekly. - well FN-40: this well is approx. 30 ft southeast of well FN-15R. area around well FN-15R was excavated in Nov. 2019. during well gauging today, approx. 1 ft of heavy product was noted in well FN-40. asked Mr. McGaha to initiate product recovery from well FN-40. Mr. McGaha recommended excavation around well FN-40 to expedite remediation. asked Mr. McGaha to submit the pending re-revised report including observations/data of today's inspection, and recommendations/proposals to address product gauging/recovery in wells MC-1, MC-4, FN-34 and FN-40. 12:45 PM:- sent email to Mr. McGaha and informed him confusing notation about well FN-22 and FN-24. asked him to include the actual well FN-22 in future well gauging/monitoring/sampling. asked him to correct well notations in the revised report. email copied to Aaron. 10/23/20-Hiralkumar Patel. 12:15 PM:- sent email to Mr. McGaha and asked him to immediately

NYC DEP HAZ MAT (Continued) **S102143390**

remove product from well FN-40. email copied to Aaron. 1:07 PM:- received email from Aaron Abraham confirming that he pumped out the well FN-40 today. 10/29/20-Hiralkumar Patel. 2:05 PM:- sent email to Mr. McGaha inquiring updates on re-revised report including details about recent site inspection and recommendations based on field observations. email copied to Mr. Abraham. 11/02/20-Hiralkumar Patel. 1:45 PM:- received email from Mr. Abraham. he stated that he has pumped well FN-40 in the alley that had product, removing nearly all product, and now it has only a sheen. he has put in an absorbent sock which should eliminate the sheen. he also put absorbent socks in the two wells in the small yard by the water that had a sheen. he will measure large oil tank today and forward the results to Paul. 12/16/20-Hiralkumar Patel. received copy of a joint permit application package for bulkhead replacement at the site. - four borings (B1 through B4) were installed along the bulkhead - boring B1 was in area of existing well MC-2 - boring B4 was in area of existing well MC-1 - silty sand, clay, wood and fill material were noted in borings - groundwater was noted at 14 ft bg in B1, 12.5 ft bg in B2, 8 ft bg in B3 and 12 ft bg in B4 noted following issues with the bulkhead replacement application: - no pollution control methods proposed in section 6 (i) of the Joint Application Form - incorrect information in section E.1 (g) of Full Environmental Assessment Form Part 1 - Project and Setting. there is history of storage of chlorinated solvents in two of the seven major storage tanks, but the applicant has failed to indicate that - the applicant has only listed remediation project # 241117 in section E.1 (h) of Full Environmental Assessment Form Part 1 - Project and Setting, but has failed to mention spill cases at the site (total of eleven spills reported at the site to date) 1:28 PM:- sent email to Mr. Abraham and reminded him about pending revised report including additional remedial activities discussed during the site visit on 10/22/2020. email copied to Mr. McGaha. 12/22/20-Hiralkumar Patel. received email from Mr. McGaha (at 6:55 PM on 12/21/20) including a revised interim remedial measure report. Mr. McGaha mentioned that LNAPL in well FN-40 has been reduced to a sheen, therefore, the remediation approach is to monitor this well for a little longer. summary of IRM: - on 01/19/20 and 08/01/20, absorbent boom, used to control a petroleum sheen on the water, was removed and replaced - on 03/05/20, well FN-15 was replaced by well FN-15R at the same location. well FN-15R was constructed with 2 inch diameter riser from grade to 1 ft bg and screen from 1 ft to 20 ft bg - on 03/20/20 and 07/20/20, the LNAPL recovery system 275 gal AST was emptied and a high volume extraction event was performed at MC-1 - as per disposal manifests, total of 1,700 gal of oily water was disposed on 03/20/20 and 1,000 gal of oily water was disposed on 07/20/20 - weekly gauging events have continued at FN-14, FN-19, FN-22, FN-28A, FN-34, FN-40, FN-42, MC-3 and MC-4 - automated and manual LNAPL recovery is ongoing at MC-1 - proportions of oil in oil/water mixture removed from the site is estimated to be approx. 20% oil - spent absorbent boom from the creek are stored in drums for later disposal proposed remedial activities: - wells FN-14, FN-15R, FN-19, FN-22, FN-28A, FN-34, FN-40, FN-42, MC-3 and MC-4 will be gauged monthly for six months, after which time, if no LNAPL is identified, monthly gauging will be discontinued - absorbent socks will be used to passively remove sheen of oil in wells FN-34 and FN-40 (also include well MC-4 where sheen noted during gauging on 10/22/20) - single phase LNAPL removal will continue at MC-1 until LNAPL is removed from the well - LNAPL removal

NYC DEP HAZ MAT (Continued) **S102143390**

system in MC-1 will be shut down for a day once per month to allow the pump to be removed from MC-1 and LNAPL thickness to be gauged. at this time, the thickness of oil in the AST servicing the LNAPL recovery system will also be measured - VEFR will be performed at MC-1 on a quarterly basis until LNAPL is removed from this well - absorbent boom in the Newtown Creek will be maintained and replaced as needed until a sheen on the groundwater is no longer detected - wells MC-1, MC-2, MC-3, MC-4, FN-34, FN-28A and GQ-41 (not shown on map) will be sampled for VOCs/SVOCs to investigate groundwater near the Newtown Creek - wells FN-12, FN-14, FN-15R, FN-39, FN-40 and FN-22 (FN-24 as per historical maps) will be sampled for VOCs/SVOCs to investigate groundwater near the alley (as per note in table 1, wells FN-12 and FN-39 are generally covered with soil due to traffic in alley) - upon removal of LNAPL at MC-1, a remedial action report will be submitted detailing the installed site cap, including a deed notice, engineering controls for soil, monitored natural attenuation for groundwater under a site management plan ---------- the proposed remedial activities in the IRM includes only submission of a remedial action report upon removal of LNPAL from MC-1, but does not include any proposal to submit an interim reports (bi-annual interim remedial action reports should be submitted). 01/22/21-Hiralkumar Patel. 11:29 AM:- sent email to DEC Lisa Horwitz including comments on the bulkhead replacement application. email copied to DEC Austin, DEC Falls and OGC Heather. 11:31 AM:- sent email to OGC Heather including comments on the IRM Report and bulkhead replacement application. email copied to DEC Austin. 06/30/21-Hiralkumar Patel. 10:00 AM:- DEC Horwitz, DEC Falls, OGC Heather, Andrew Thyberg (andrew.thyberg@bayenviro.com) and Patrick McPeak (pmcpeak@peakcivilassociates.com). **need to add gauging data on site map.** **MOSF documents on e-docs are only part of larger file in box located in basement storage.**"

Remarks: "CLEANUP BY DEC WINSTON CONTRACTING INC. SUPERVISED BY SIGONA (DEC)"

All Materials:

Site ID:	59302
Operable Unit ID:	972795
Operable Unit:	01
Material ID:	406198
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	200 MORGAN AVE.
Address:	200 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9208755 / 1998-02-05
Facility ID:	9208755
Facility Type:	ER
DER Facility ID:	57235
Site ID:	305060
DEC Region:	2
Spill Cause:	Equipment Failure

NYC DEP HAZ MAT (Continued) **S102143390**

Spill Class:	C4
SWIS:	2401
Spill Date:	1992-10-29
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1992-10-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-10-30
Spill Record Last Update:	1998-02-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"DURING TANK CLEANING OPERATION HOSE COUPLING FAILED -SLUDGE LEAKED TO SOIL AREA EXCAV AND DRUM CONTAM SOIL WILL DISPOSE NRC 142527 CALLED CITI-FUEL HAS CLEANED UP SPILL/SOME CONTAM SOIL NEED TO BE CL"

All Materials:

Site ID:	305060
Operable Unit ID:	972281
Operable Unit:	01
Material ID:	405835
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	MORGAN OIL CORP
Address:	200 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9105949 / 1991-09-19
Facility ID:	9105949
Facility Type:	ER
DER Facility ID:	57235
Site ID:	251343
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	B3
SWIS:	2401
Spill Date:	1991-09-03
Investigator:	SJMILLER

NYC DEP HAZ MAT (Continued) **S102143390**

Referred To:	Not reported
Reported to Dept:	1991-09-03
CID:	Not reported
Water Affected:	NEWTOWN CREEK
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Other
Cleanup Ceased:	1991-09-19
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-09-03
Spill Record Last Update:	2004-04-07
Spiller Name:	Not reported
Spiller Company:	MORGAN OIL CORP
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MILLER 10/10/95: This is additional information about material spilled from the translation of the old spill file: SHEEN, GLOBS."
Remarks:	"APPEARS TO BE COMING FROM A 55 GAL ABANDONED DRUM IN CREEK. OR MAY BE DUE TO A BULKHEAD (LOW TIDE)"

All Materials:

Site ID:	251343
Operable Unit ID:	956456
Operable Unit:	01
Material ID:	421709
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	200 MORGAN AVE
Address:	200 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9112693 / 1992-03-13
Facility ID:	9112693
Facility Type:	ER
DER Facility ID:	57235
Site ID:	251344
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	1992-03-12
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1992-03-12
CID:	Not reported
Water Affected:	Not reported

NYC DEP HAZ MAT (Continued) **S102143390**

Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1992-03-13
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-03-20
Spill Record Last Update:	2003-09-23
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE "
Remarks:	"FD ON SCENE. SPEEDY-DRY APPLIED"

All Materials:

Site ID:	251344
Operable Unit ID:	963025
Operable Unit:	01
Material ID:	414255
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	IN THE CHANNEL
Address:	200 MORGAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1202045 / 2012-05-31
Facility ID:	1202045
Facility Type:	ER
DER Facility ID:	419184
Site ID:	464793
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2012-05-30
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2012-05-31
CID:	Not reported
Water Affected:	ENGLISH KILLS
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

NYC DEP HAZ MAT (Continued) **S102143390**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-05-31
Spill Record Last Update:	2012-08-07
Spiller Name:	BRIAN CISKOWITZ
Spiller Company:	UNKNOWN
Spiller Address:	200 MORGAN AVE
Spiller Company:	999
Contact Name:	BRIAN CISKOWITZ
DEC Memo:	"05/31/12-Hiralkumar Patel. 9:30 AM:- visited site. no oil or sheen observed. after discussing with DEC Austin, case closed."
Remarks:	""

All Materials:

Site ID:	464793
Operable Unit ID:	1214830
Operable Unit:	01
Material ID:	2212900
Material Code:	9999
Material Name:	other - brown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

Name:	NYC DEP HAZ MAT
Address:	200 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY 11201
Country:	USA
EPA ID:	NYP003662657
Facility Status:	Not reported
Location Address 1:	200 MORGAN AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11201
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP003662657
Mailing Name:	NYC DEP HAZ MAT
Mailing Contact:	JOANNE NURSE
Mailing Address 1:	59 17 JUNCTION BLVD
Mailing Address 2:	Not reported
Mailing City:	FLUSHING
Mailing State:	NY
Mailing Zip:	11373
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7185954675

Z172 **CON EDISON** **NY MANIFEST** **S117738733**
WSW **FRONT OF 200 MORGAN AV** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.237 mi.
1253 ft. **Site 2 of 3 in cluster Z**

Relative:
Lower

Actual:
10 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FRONT OF 200 MORGAN AV
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYP004718086
Facility Status:	Not reported
Location Address 1:	FRONT OF 200 MORGAN AV
Code:	BP
Location Address 2:	SB16505
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004718086
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	01/23/2015
Trans1 Recv Date:	01/23/2015
Trans2 Recv Date:	01/26/2015
TSD Site Recv Date:	01/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004718086
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002620156GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117738733**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	250
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Z173 **MORGAN OIL TERMINALS CORP** **NY MOSF UST** **1000889835**
WSW **200 MORGAN AVE** **NY Spills** **NYD074359472**
1/8-1/4 **BROOKLYN, NY 11237** **RCRA NonGen / NLR**
0.237 mi. **FINDS**
1253 ft. **Site 3 of 3 in cluster Z** **ECHO**
NY MANIFEST

Relative:
Lower

Actual:
10 ft.

MOSF UST:

Id/Status:	2-1500 / INACTIVE FACILITY
SWIS Code:	61
Facility Town:	NEW YORK CITY
Contact Phone:	(718) 366-5108
Emergency Contact:	HENRY FOSTER
Emergency Telephone:	(718) 857-6472
CBS Number:	Not reported
SPDES Num:	0-032824
Total Tanks:	7
Total Capacity:	1925000
Avg Throughput:	0
License Stat:	3
Facility Type:	STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Prod Xfer Options:	AC
Expiration Date:	03/31/1991
Applic Rcvd:	01/14/1991
Operator:	HENRY FOSTER
Owner Name:	MORGAN OIL TERMINALS CORP.
Owner Address:	200 MORGAN AVENUE
Owner City,St,Zip:	BROOKLYN, NY 11337-
Owner Telephone:	(718) 366-5108
Owner Type:	Corporate/Commercial
Owner Status:	1
Owner Mark:	First Owner

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Mail To Name:	MORGAN OIL TERMINALS CORP.
Mail To Address:	C/O SHATZKIN & FURMAN, P.C.
Mail To Address 2:	60 CUTTER MILL RD., SUITE 206
Mail City,St,Zip:	GREAT NECK, NY 11021-
Mail To Contact:	SCOTT E. FURMAN
Mail To Telephone:	(516) 487-3703
Legal Agent Name:	SCOTT FURMAN
Legal Agent Address:	60 CUTTERMILL ROAD
Legal Agent City,St,Zip:	GREAT NECK, NY 11021-
Date Filed:	00/82
Latitude:	40|42|40
Longitude:	73|56|00

Tank ID:	1
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	645000
Product:	NOS 5 OR 6 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	02/22/1994
Inspector Initials:	Not reported
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	03/28/1990
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/23/1993
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	2
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	7000
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	02/22/1994
Inspector Initials:	Not reported
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	03/28/1990
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/23/1993
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	3
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	55000
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	02/22/1994
Inspector Initials:	Not reported
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	03/28/1990
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/23/1993
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	4
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	67000
Product:	NOS 1,2, OR 4 FUEL OIL

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	02/22/1994
Inspector Initials:	Not reported
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	03/28/1990
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/23/1993
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	5
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	507000
Product:	NOS 5 OR 6 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	02/22/1994
Inspector Initials:	Not reported
Inspector Status:	Not reported
Pipe Flag:	False
License Issued:	03/28/1990
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/23/1993
Federal Id No:	Not reported
COI Date:	/ /

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Tank ID: 6
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 400000
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: None
Leak Detection: None
Overfill Protection: High Level Alarm
Dispenser: Suction
Test Date: Not reported
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 02/22/1994
Inspector Initials: Not reported
Inspector Status: Not reported
Pipe Flag: False
License Issued: 03/28/1990
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/23/1993
Federal Id No: Not reported
COI Date: / /

Tank ID: 7
Tank Location: UNDERGROUND
Install Date: 00/00
Capacity (Gal): 244000
Product: NOS 1,2, OR 4 FUEL OIL
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Aboveground
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Painted/Asphalt Coating
Second Contain: None
Leak Detection: None
Overfill Protection: High Level Alarm
Dispenser: Suction
Test Date: Not reported
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 02/22/1994
Inspector Initials: Not reported
Inspector Status: Not reported
Pipe Flag: False
License Issued: 03/28/1990

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/23/1993
Federal Id No: Not reported
COI Date: / /

SPILLS:
Name: NEW TOWN CREEK
Address: 200 MORGAN AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 2002669 / 2020-07-14
Facility ID: 2002669
Facility Type: ER
DER Facility ID: 419184
Site ID: 608367
DEC Region: 2
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 2401
Spill Date: 2020-07-09
Investigator: HSSEKHON
Referred To: Not reported
Reported to Dept: 2020-07-09
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2020-07-09
Spill Record Last Update: 2020-07-14
Spiller Name: WILLIS ELKINS
Spiller Company: UNKNOWN
Spiller Address: 200 MORGAN AVE
Spiller Company: 999
Contact Name: WILLIS ELKINS
DEC Memo: "7/9/20 - Sekhon Got access to the creek through 200 morgan ave (Gotham Ready Mix). No sheen observed. Due to hot weather pieces of sediments burping up to the surface. DEC Austin updated. 7/14 - Sekhon Site visited again. very little amount of leftover sediments (from last week) noticed. No sheen observed anywhere in the vicinity. Case discussed with DEC Austin and closed. "
Remarks: "booms failing to keep oil contained"

All Materials:
Site ID: 608367
Operable Unit ID: 1355522
Operable Unit: 01
Material ID: 2366699
Material Code: 9999
Material Name: other - oil
Case No.: Not reported
Material FA: Other

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	MORGAN OIL TERMINALS CORP
Handler Address:	200 MORGAN AVE
Handler City,State,Zip:	BROOKLYN, NY 11237-1014
EPA ID:	NYD074359472
Contact Name:	Not reported
Contact Address:	21ST ST NYSDEC
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	21ST ST NYSDEC
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	UNKNOWN
Owner Type:	Private
Operator Name:	UNKNOWN
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	UNKNOWN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	UNKNOWN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: UNKNOWN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: MORGAN OIL TERMINALS CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MORGAN OIL TERMINALS CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MORGAN OIL TERMINALS CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Electronic Manifest Broker: Not reported

Receive Date: 19940412
Handler Name: MORGAN OIL TERMINALS CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960701
Handler Name: NYSDEC - MORGAN TERMINAL SITE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110009468290

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000889835

MORGAN OIL TERMINALS CORP (Continued) **1000889835**

Registry ID:	110009468290
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009468290
Name:	MORGAN OIL TERMINALS CORP
Address:	200 MORGAN AVE
City,State,Zip:	BROOKLYN, NY 11237

NY MANIFEST:

Name:	NYSDEC
Address:	200 MORGAN AVE
City,State,Zip:	BROOKLYN, NY 11237-1014
Country:	USA
EPA ID:	NYD074359472
Facility Status:	Not reported
Location Address 1:	47-40 21ST STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD074359472
Mailing Name:	NYSDEC
Mailing Contact:	JOSEPH SCEPPA
Mailing Address 1:	47-40 21ST STREET
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184824933

U174 **CAPITAL AUTO SALVAGE & SALES, INC.** **NY AST** **A100295036**
East **4600 METROPOLITAN AVENUE** **N/A**
1/8-1/4 **RIDGEWOOD, NY 11385**
0.241 mi.
1273 ft. **Site 4 of 5 in cluster U**

Relative:
Lower

Actual:
11 ft.

AST:

Name:	CAPITAL AUTO SALVAGE & SALES, INC.
Address:	4600 METROPOLITAN AVENUE
City,State,Zip:	RIDGEWOOD, NY 11385
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-608207
Program Type:	PBS
UTM X:	590949.23371
UTM Y:	4507536.98132
Expiration Date:	12/15/2024
Site Type:	Other

Affiliation Records:

Site Id:	30059

CAPITAL AUTO SALVAGE & SALES, INC. (Continued) **A100295036**

Affiliation Type:	Mail Contact
Company Name:	4600 METRO CORP.
Contact Type:	Not reported
Contact Name:	PAUL MACDONNELL
Address1:	4600 METROPOLITAN AVENUE
Address2:	Not reported
City:	RIDGEWOOD
State:	NY
Zip Code:	11385
Country Code:	001
Phone:	(718) 381-9090
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-03-16

Site Id:	30059
Affiliation Type:	Facility Operator
Company Name:	CAPITAL AUTO SALVAGE & SALES INC
Contact Type:	Not reported
Contact Name:	PAUL MACDONNELL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 381-9090
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-03-16

Site Id:	30059
Affiliation Type:	Emergency Contact
Company Name:	4600 METRO CORP
Contact Type:	Not reported
Contact Name:	PAUL MACDONNELL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 617-0180
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-03-16

Site Id:	30059
Affiliation Type:	Facility Owner
Company Name:	4600 METRO CORP.
Contact Type:	CONSULTANT
Contact Name:	NORMAN TEITLER
Address1:	4600 METROPOLITAN AVE
Address2:	Not reported

CAPITAL AUTO SALVAGE & SALES, INC. (Continued) **A100295036**

City:	RIDGEWOOD
State:	NY
Zip Code:	11385
Country Code:	001
Phone:	(718) 381-9090
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-11-05

Tank Info:

Tank Number:	001
Tank Id:	64892
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Fiberglass Coated Steel
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	55
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/10/2009
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	002
Tank Id:	65381
Material Code:	2642
Common Name of Substance:	Used Oil (Heating, On-Site Consumption)

Equipment Records:

J00 - Dispenser - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

CAPITAL AUTO SALVAGE & SALES, INC. (Continued) **A100295036**

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/10/2009
Register: True
Modified By: NRLOMBAR
Last Modified: 04/14/2017
Material Name: used oil (heating, on-site consumption)

Tank Number: 003
Tank Id: 254934

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
E00 - Piping Secondary Containment - None

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Fiberglass Reinforced Plastic
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/15/2014
Capacity Gallons: 200
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: NTFREEMA
Last Modified: 04/14/2017
Material Name: waste oil/used oil

U175 **METRO AUTO SALVAGE** **NY SWF/LF** **S106015178**
East **4600 METROPOLITAN AVE** **NY CBS** **N/A**
1/8-1/4 **RIDGEWOOD, NY 11385** **NY AST**
0.241 mi. **NY Spills**
1273 ft. **Site 5 of 5 in cluster U** **NY SPDES**

Relative:
Lower

Actual:
11 ft.

SWF/LF:

Name:	CAPITAL AUTO SALVAGE & SALES INC
Address:	4600 METROPOLITAN AVE
City,State,Zip:	QUEENS, NY 11385
Flag:	INACTIVE
Region Code:	2
Phone Number:	7183819090
Owner Name:	CAPITAL AUTO SALVAGE & SALES; INC.
Owner Type:	Private
Owner Address:	4600 Metropolitan Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Ridgewood, NY 11385
Owner Email:	JAMESMACDIESEL@GMAIL.COM
Owner Phone:	7183819090
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[7117789]
Active:	No
East Coordinate:	590971
North Coordinate:	4507550
Accuracy Code:	4.2 - Utilization of GIS and existing spatial data
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	CAPITAL AUTO SALVAGE & SALES; INC.
Operator Type:	Not reported
Laste Date:	Not reported

Name:	METRO AUTO SALVAGE & SALES INC
Address:	4600 METROPOLITAN AVE
City,State,Zip:	RIDGEWOOD, NY 11385
Flag:	INACTIVE
Region Code:	2
Phone Number:	7183819090
Owner Name:	Metro Auto Salvage & Sales Inc
Owner Type:	Private
Owner Address:	4600 Metropolitan Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Ridgewood, NY 11385
Owner Email:	Not reported
Owner Phone:	7182578584
Contact Name:	Vincent Marino
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	NY
Contact Email:	Parts@MetroAutoSalvage.com

METRO AUTO SALVAGE (Continued) **S106015178**

Contact Phone: 7183819090
Activity Desc: Vehicle Dismantling Facility
Activity Number: [7097170]
Active: No
East Coordinate: 590900
North Coordinate: 4507549
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Not reported
Operator Type: Not reported
Laste Date: Not reported

Name: CAPITAL AUTO SALVAGE & SALES INC
Address: 4600 METROPOLITAN AVE
City,State,Zip: QUEENS, NY 11385
Flag: ACTIVE
Region Code: 2
Phone Number: 7183819090
Owner Name: CAPITAL AUTO SALVAGE & SALES; INC.
Owner Type: Private
Owner Address: 4600 Metropolitan Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Ridgewood, NY 11385
Owner Email: JAMESMACDIESEL@GMAIL.COM
Owner Phone: 7183819090
Contact Name: Not reported
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: VDF - large - registration
Activity Number: [41V50004]
Active: Yes
East Coordinate: 590971
North Coordinate: 4507550
Accuracy Code: 4.2 - Utilization of GIS and existing spatial data
Regulatory Status: Registration
Waste Type: End of Life Vehicles;Lead-acid Batteries;Mix Coolant/Engine Oil/Washing Fluid/Water;Engine Coolant/Antifreeze
Authorization #: 41V50004
Authorization Date: 11/15/2019
Expiration Date: 11/14/2024
Operator Name: CAPITAL AUTO SALVAGE & SALES; INC.
Operator Type: Not reported
Laste Date: Not reported

CBS:
Name: METRO AUTO SAVAGE & SALES, INC.
Address: 4600 METROPOLITAN AVE
City,State,Zip: RIDGEWOOD, NY 11368
CBS Number: 2-000496
Program Type: CBS

METRO AUTO SALVAGE (Continued) **S106015178**

Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: Not reported
UTMY: Not reported

AST:
Name: METRO AUTO SAVAGE & SALES, INC.
Address: 4600 METROPOLITAN AVE
City,State,Zip: RIDGEWOOD, NY 11368
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-000496
Program Type: CBS
UTM X: Not reported
UTM Y: Not reported
Expiration Date: N/A
Site Type: Other

Tank Info:

Tank Number: 01
Tank Id: 237146
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Plastic
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 06/10/2009
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 04/25/2011
Register: True
Modified By: KAKYER
Last Modified: 08/30/2011
Material Name: Not reported

SPILLS:
Name: METRO AUTO SALVAGE
Address: 4600 METROPOLITAN AVE
City,State,Zip: RIDGEWOOD, NY
Spill Number/Closed Date: 0330014 / 2006-01-05
Facility ID: 0330014
Facility Type: ER
DER Facility ID: 215176
Site ID: 263989
DEC Region: 2
Spill Cause: Deliberate
Spill Class: C3
SWIS: 4101
Spill Date: 2003-06-17
Investigator: EXHAMPST
Referred To: Not reported
Reported to Dept: 2003-06-18

METRO AUTO SALVAGE (Continued) **S106015178**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-18
Spill Record Last Update:	2006-01-05
Spiller Name:	SAME
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 12/29/05 Transferred to E. Hampston via Spill Initiative. Contaced DLE caller who reported spill seeking update on referal to other Department representatives or issuance of tickets. 1/5/05 Lt. Fitzpatrick (DLE) indicated that the site was visited in conjunction with NYPD Auto Crimes group. He returned to site with ECO and tickets were issued. Consent Order R2-20030820-221 signed on 8/21/03. Close based on implementation of Order and regulation by DSHM. "
Remarks:	"Location is a junk yard. Various unpermitted discharges of automotive waste fluids found on ground surface at above location."

All Materials:

Site ID:	263989
Operable Unit ID:	881432
Operable Unit:	01
Material ID:	496514
Material Code:	0005A
Material Name:	auto waste fluids
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPDES:

Name:	METRO AUTO SALVAGE
Address:	4600 METROPOLITAN AVE
City,State,Zip:	RIDGEWOOD, NY 11385
Permit Number:	NYR00E042
State-Region:	02
Expiration Date:	03/31/2012
Current Major Minor Status:	Minor
Primary Facility SIC Code:	5015
State Water Body Name:	ENGLISH KILLS
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported

METRO AUTO SALVAGE (Continued) **S106015178**

UDF1:	Not reported
Lat/Long:	+40.713889 / -73.923056
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY081
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	METRO AUTO SALVAGE AND SALES INC
Non-Gov Permit Street Address:	METRO AUTO SALVAGE AND SALES INC
Non-Gov Permit Supplemental Location:	4600 METROPLOITAN AVE
Non-Gov Permit City:	RIDGEWOOD
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11385
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	METRO AUTO SALVAGE AND SALES INC
Non-Gov Facility Street Address:	METRO AUTO SALVAGE AND SALES INC
Non-Gov Facility Supplemental Location:	4600 METROPOLITAN AVE
Non-Gov Facility City:	RIDGEWOOD
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11385
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	METRO AUTO SALVAGE
Address:	4600 METROPOLITAN AVE
City,State,Zip:	RIDGEWOOD, NY 11385
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY081
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	METRO AUTO SALVAGE & SALES INC
Non-Gov Permit Street Address:	4600 METROPOLITAN AVE
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	RIDGEWOOD
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11385
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	METRO AUTO SALVAGE AND SALES INC
Non-Gov Facility Street Address:	METRO AUTO SALVAGE AND SALES INC
Non-Gov Facility Supplemental Location:	4600 METROPOLITAN AVE
Non-Gov Facility City:	RIDGEWOOD
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11385
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported

METRO AUTO SALVAGE (Continued) **S106015178**

Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	METRO AUTO SALVAGE
Address:	4600 METROPOLITAN AVE
City,State,Zip:	RIDGEWOOD, NY 11385
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY081
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	METRO AUTO SALVAGE AND SALES INC
Non-Gov Facility Street Address:	METRO AUTO SALVAGE AND SALES INC
Non-Gov Facility Supplemental Location:	4600 METROPOLITAN AVE
Non-Gov Facility City:	RIDGEWOOD
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11385
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

176
ESE
1/8-1/4
0.241 mi.
1275 ft.

ALLOCCO RECYCLING (606 MESEROLE) **NY SWRCY** **S121133113**
606 MESEROLE STREET **N/A**
BROOKLYN, NY 11237

Relative:
Higher

Actual:
14 ft.

SWRCY:

Name:	ALLOCCO RECYCLING (606 MESEROLE)
Address:	606 MESEROLE STREET
City,State,Zip:	BROOKLYN, NY 11237
Region:	2
Facility Address 2:	Not reported
Phone Number:	7183493094
Owner Type:	Private
Owner Name:	Michael ALLOCCO
Owner Address:	Not reported
Owner Address 2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	MIKE@alloccorecycling.com
Owner Phone:	7183493097
Contact Name:	Michael Allocco
Contact Address:	540 Kingsland Avenue
Contact Address 2:	Not reported

ALLOCCO RECYCLING (606 MESEROLE) (Continued) **S121133113**

Contact City,St,Zip:	Brooklyn, NY 11222
Contact Email:	Not reported
Contact Phone:	7183493094
Activity Desc:	RHRF - registration
Activity Number:	[24MH2]
Active:	Yes
East Coordinate:	590900
North Coordinate:	4507350
Accuracy Code:	1 - No accuracy stated
Regulatory Status:	Registration
Permit #:	Not reported
Auth. Date:	Not reported
Expiration Date:	Not reported
Waste Types:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Last Date:	10/3/2017

AA177 **RANDOLPH ASSOCIATES** **NY UST** **U000400166**
SE **165 RANDOLPH STREET** **NY Spills** **N/A**
1/8-1/4 **BROOKLYN, NY 11237**
0.248 mi.
1307 ft. **Site 1 of 3 in cluster AA**

Relative:
Higher

Actual:
14 ft.

UST:

Name:	RANDOLPH ASSOCIATES
Address:	165 RANDOLPH STREET
City,State,Zip:	BROOKLYN, NY 11237
Id/Status:	2-258296 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590738.53243
UTM Y:	4507088.55183
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	10692
Affiliation Type:	Facility Owner
Company Name:	RANDOLPH ASSOCIATES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	60 EAST 56TH STREET
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10022
Country Code:	001
Phone:	(212) 751-4627
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-08-30

Site Id:	10692
Affiliation Type:	Mail Contact
Company Name:	MID-COUNTY MECHANICAL INC

RANDOLPH ASSOCIATES (Continued) **U000400166**

Contact Type:	Not reported
Contact Name:	KEN KASPER
Address1:	121-06 89TH AVENUE
Address2:	Not reported
City:	RICHMOND HILL
State:	NY
Zip Code:	11418
Country Code:	001
Phone:	(718) 847-1800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-08-30

Site Id:	10692
Affiliation Type:	Facility Operator
Company Name:	RANDOLPH ASSOCIATES
Contact Type:	Not reported
Contact Name:	RANDOLPH ASSOCIATES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 751-4627
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-08-30

Site Id:	10692
Affiliation Type:	Emergency Contact
Company Name:	RANDOLPH ASSOCIATES
Contact Type:	Not reported
Contact Name:	RANDOLPH ASSOCIATES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(212) 751-4627
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-08-30

Tank Info:

Tank Number:	001
Tank ID:	13287
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	12/01/1949
Date Tank Closed:	07/01/2004

RANDOLPH ASSOCIATES (Continued) **U000400166**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	03/20/2003
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

I05 - Overfill - Vent Whistle
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None

SPILLS:

Name:	165 RANDOLPH ST ASSOC
Address:	165 RANDOLPH ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9110290 / 1995-03-30
Facility ID:	9110290
Facility Type:	ER
DER Facility ID:	65478
Site ID:	68801
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1991-12-31
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1991-12-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1995-03-30
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-01-07
Spill Record Last Update:	1995-03-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported

RANDOLPH ASSOCIATES (Continued) **U000400166**

Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks: ""

All Materials:
Site ID: 68801
Operable Unit ID: 963887
Operable Unit: 01
Material ID: 418839
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 6.00
Units: G
Recovered: .00
Oxygenate: Not reported

Y178 **NEW YORK TELEPHONE CO** **RCRA NonGen / NLR** **1000136852**
NNW **15 REWE ST** **FINDS** **NYD980755680**
1/8-1/4 **BROOKLYN, NY 11211** **ECHO**
0.249 mi. **NY MANIFEST**
1313 ft. **Site 3 of 3 in cluster Y**

Relative: **Lower**
Actual: **4 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 20070101
Handler Name: NEW YORK TELEPHONE CO
Handler Address: 15 REWE ST
Handler City,State,Zip: BROOKLYN, NY 11211-1707
EPA ID: NYD980755680
Contact Name: Not reported
Contact Address: PENN PLZ ROOM 1650
Contact City,State,Zip: NEW YORK, NY 10121
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: PENN PLZ ROOM 1650
Mailing City,State,Zip: NEW YORK, NY 10121
Owner Name: NEW YORK TELEPHONE CO
Owner Type: Private
Operator Name: NEW YORK TELEPHONE CO
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No

NEW YORK TELEPHONE CO (Continued) **1000136852**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	NONE
Waste Description:	Not Defined

NEW YORK TELEPHONE CO (Continued) **1000136852**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK TELEPHONE CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NEW YORK TELEPHONE CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NEW YORK TELEPHONE CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: NEW YORK TELEPHONE CO	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: NEW YORK TELEPHONE CO	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

NEW YORK TELEPHONE CO (Continued) **1000136852**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19830523
Handler Name: NEW YORK TELEPHONE CO
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD - General
Date Violation was Determined: 19910712
Actual Return to Compliance Date: 19910712
Return to Compliance Qualifier: Not Resolved
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported

NEW YORK TELEPHONE CO (Continued) **1000136852**

Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19910712
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: HA
Actual Return to Compliance Date: 19910712
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110004389714

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000136852
Registry ID: 110004389714

NEW YORK TELEPHONE CO (Continued) **1000136852**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004389714
Name: NEW YORK TELEPHONE CO
Address: 15 REWE ST
City,State,Zip: BROOKLYN, NY 11211

NY MANIFEST:
Name: NYNEX
Address: 15 REWE ST
City,State,Zip: BROOKLYN, NY 11211-1707
Country: USA
EPA ID: NYD980755680
Facility Status: Not reported
Location Address 1: 222 TEALL AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: SYRACUSE
Location State: NY
Location Zip: 13217
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD980755680
Mailing Name: NYNEX
Mailing Contact: B WARREN
Mailing Address 1: 441 9TH AVE-RM 501
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10001
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2125027694

AA179 **CAL OSTLUND INC** **NY LTANKS** **1000126948**
SE **185 RANDOLPH ST** **RCRA NonGen / NLR** **NYD001341908**
1/4-1/2 **BROOKLYN, NY 11237** **FINDS**
0.253 mi. **ECHO**
1336 ft. **Site 2 of 3 in cluster AA** **NY MANIFEST**

Relative:
Higher

Actual:
14 ft.

LTANKS:
Name: X
Address: 185 RANDOLPH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0212548 / 2005-12-07
Facility ID: 0212548
Site ID: 120041
Spill Date: 2003-03-20
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: rmpiper
Referred To: Not reported
Reported to Dept: 2003-03-20
CID: 422

CAL OSTLUND INC (Continued) **1000126948**

Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-03-20
Spill Record Last Update:	2005-12-07
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ISSAC MUNGRA
Spiller Phone:	(718) 857-9800
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	104250
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 3/20/03, AUSTIN, DDO - TANK FAILED LOCATOR PLUS TEST (PASS/FAIL) - SENT OUT TTF LETTER 1/7/04-Vought-Spill transferred from Vought to Austin. 01/27/04 - Sawyer - Spill transferred from Austin to Sawyer. 11/25/05- DEc Piper sent out another ttf letter to Ken Kasper Mid-County Mechanical Inc. 121-06 89th Ave, Richmond hill, NY 11418 12/7/05- DEC Piper recieved sufficient evidence to close spill. Minor repairs made to tank, specifically vent line. No contaminated soil found during uncovering of top of tank. See e-docs if warranted."
Remarks:	""

All TTF:

Facility ID:	0212548
Spill Number:	0212548
Spill Tank Test:	1528116
Site ID:	120041
Tank Number:	Not reported
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	99
Test Method 2:	Alternate Test per former 613.5(a)(2)(v)
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	120041
Operable Unit ID:	866004
Operable Unit:	01
Material ID:	512280
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

CAL OSTLUND INC (Continued) **1000126948**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	CAL OSTLUND INC	
Handler Address:		185 RANDOLPH ST
Handler City,State,Zip:		BROOKLYN, NY 11237-1306
EPA ID:		NYD001341908
Contact Name:		Not reported
Contact Address:		PO BOX 412
Contact City,State,Zip:		BROOKLYN, NY 11237
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		PO BOX 412
Mailing City,State,Zip:		BROOKLYN, NY 11237
Owner Name:		CAL OSTLUND
Owner Type:		Private
Operator Name:		CAL OSTLUND
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported

CAL OSTLUND INC (Continued) **1000126948**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F005
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE,

CAL OSTLUND INC (Continued) **1000126948**

2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CAL OSTLUND
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CAL OSTLUND
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CAL OSTLUND
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: CAL OSTLUND INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CAL OSTLUND INC (Continued) **1000126948**

Receive Date: 20060101
Handler Name: CAL OSTLUND INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CAL OSTLUND INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19891214
Handler Name: CAL OSTLUND INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004333908

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource

CAL OSTLUND INC (Continued) **1000126948**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000126948
Registry ID:	110004333908
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004333908
Name:	CAL OSTLUND INC
Address:	185 RANDOLPH STREET
City,State,Zip:	BROOKLYN, NY 11237

NY MANIFEST:

Name:	CAL OSTLUND INC
Address:	185 RANDOLPH ST
City,State,Zip:	BROOKLYN, NY 11237-1306
Country:	USA
EPA ID:	NYD001341908
Facility Status:	Not reported
Location Address 1:	185 RANDOLPH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD001341908
Mailing Name:	CAL OSTLUND INC
Mailing Contact:	THOMAS ROWINSKI
Mailing Address 1:	185 RANDOLPH STREET
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184566483

AB180 **FRITO LAY** **NY ENG CONTROLS** **S109416391**
WSW **202-218 MORGAN AVENUE** **NY INST CONTROL** **N/A**
1/4-1/2 **BROOKLYN, NY 11237** **NY BROWNFIELDS**
0.262 mi.
1386 ft. **Site 1 of 2 in cluster AB**

Relative:
Lower

Actual:
13 ft.

ENG CONTROLS:

Name:	FRITO LAY
Address:	202-218 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Site Code:	407689
HW Code:	C224133
Control Code:	13
Control Type:	ENG
Date Record Added:	10/22/2013
Date Rec Updated:	05/31/2017
Updated By:	CHPOST
Site Description:	"Location: The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features: The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures. Current Zoning and Land Use: The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site: The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Site Geology and Hydrogeology: The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel."
Env Problem:	"The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site."
Health Problem:	"The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied."
Dump:	False

FRITO LAY (Continued) **S109416391**

Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2008-12-11 13:40:00
Record Upd:	2013-09-20 14:10:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	P03
Owner Name:	Patricia Sacco, Library Information Supervisor
Owner Company:	Brooklyn Public Library Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Keith Massa
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Cedric Robinson
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099
Owner Country:	United States of America
HW Code:	C224133
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	MERCURY

FRITO LAY (Continued) **S109416391**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	ER1609278
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2018-04-13 15:49:00
Record Updated:	2018-04-13 15:49:00
Updated By:	CHPOST
Crossref ID:	2013000399904
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2013-10-11 11:05:00
Record Updated:	2013-10-11 11:05:00
Updated By:	KPSARNOW
Crossref ID:	C224133
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2013-10-28 11:27:00
Record Updated:	2013-10-28 11:27:00
Updated By:	JEBROWN
Crossref ID:	A2-0622-0709
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2013-10-28 11:27:00
Record Updated:	2013-10-28 11:27:00
Updated By:	JEBROWN
Crossref ID:	08/20/2009
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2013-10-28 11:26:00
Record Updated:	2013-10-28 11:26:00
Updated By:	JEBROWN
Name:	FRITO LAY
Address:	202-218 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Site Code:	407689
HW Code:	C224133
Control Code:	22
Control Type:	ENG
Date Record Added:	10/22/2013
Date Rec Updated:	05/31/2017
Updated By:	CHPOST
Site Description:	"Location: The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To

FRITO LAY (Continued) **S109416391**

the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features: The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures. Current Zoning and Land Use: The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site: The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Site Geology and Hydrogeology: The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel."

Env Problem:	"The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site."
Health Problem:	"The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2008-12-11 13:40:00
Record Upd:	2013-09-20 14:10:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	P03
Owner Name:	Patricia Sacco, Library Information Supervisor
Owner Company:	Brooklyn Public Library Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported

FRITO LAY (Continued) **S109416391**

Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Keith Massa
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Cedric Robinson
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099
Owner Country:	United States of America
HW Code:	C224133
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	ER1609278
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.

FRITO LAY (Continued) **S109416391**

Record Added Date:	2018-04-13 15:49:00
Record Updated:	2018-04-13 15:49:00
Updated By:	CHPOST
Crossref ID:	2013000399904
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2013-10-11 11:05:00
Record Updated:	2013-10-11 11:05:00
Updated By:	KPSARNOW
Crossref ID:	C224133
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2013-10-28 11:27:00
Record Updated:	2013-10-28 11:27:00
Updated By:	JEBROWN
Crossref ID:	A2-0622-0709
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2013-10-28 11:27:00
Record Updated:	2013-10-28 11:27:00
Updated By:	JEBROWN
Crossref ID:	08/20/2009
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2013-10-28 11:26:00
Record Updated:	2013-10-28 11:26:00
Updated By:	JEBROWN

Name:	FRITO LAY
Address:	202-218 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Site Code:	407689
HW Code:	C224133
Control Code:	18
Control Type:	ENG
Date Record Added:	10/22/2013
Date Rec Updated:	05/31/2017
Updated By:	CHPOST
Site Description:	"Location: The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features: The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures. Current Zoning and Land Use: The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site: The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Site Geology and Hydrogeology: The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site.

FRITO LAY (Continued) **S109416391**

	Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel."
Env Problem:	"The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site."
Health Problem:	"The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2008-12-11 13:40:00
Record Upd:	2013-09-20 14:10:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	P03
Owner Name:	Patricia Sacco, Library Information Supervisor
Owner Company:	Brooklyn Public Library Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Keith Massa
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Cedric Robinson
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099

FRITO LAY (Continued) **S109416391**

Owner Country:	United States of America
HW Code:	C224133
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	ER1609278
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2018-04-13 15:49:00
Record Updated:	2018-04-13 15:49:00
Updated By:	CHPOST
Crossref ID:	2013000399904
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2013-10-11 11:05:00
Record Updated:	2013-10-11 11:05:00
Updated By:	KPSARNOW
Crossref ID:	C224133
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2013-10-28 11:27:00
Record Updated:	2013-10-28 11:27:00
Updated By:	JEBROWN
Crossref ID:	A2-0622-0709
Cross Ref Type Code:	23

FRITO LAY (Continued) **S109416391**

Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2013-10-28 11:27:00
Record Updated:	2013-10-28 11:27:00
Updated By:	JEBROWN
Crossref ID:	08/20/2009
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2013-10-28 11:26:00
Record Updated:	2013-10-28 11:26:00
Updated By:	JEBROWN
Name:	FRITO LAY
Address:	202-218 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Site Code:	407689
HW Code:	C224133
Control Code:	15
Control Type:	ENG
Date Record Added:	10/22/2013
Date Rec Updated:	05/31/2017
Updated By:	CHPOST
Site Description:	"Location: The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features: The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures. Current Zoning and Land Use: The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site: The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Site Geology and Hydrogeology: The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel."
Env Problem:	"The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site."
Health Problem:	"The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the

FRITO LAY (Continued) **S109416391**

movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied."

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2008-12-11 13:40:00
Record Upd:	2013-09-20 14:10:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	P03
Owner Name:	Patricia Sacco, Library Information Supervisor
Owner Company:	Brooklyn Public Library Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Keith Massa
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Cedric Robinson
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099
Owner Country:	United States of America
HW Code:	C224133
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

FRITO LAY (Continued) **S109416391**

HW Code:	C224133
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	ER1609278
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2018-04-13 15:49:00
Record Updated:	2018-04-13 15:49:00
Updated By:	CHPOST
Crossref ID:	2013000399904
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2013-10-11 11:05:00
Record Updated:	2013-10-11 11:05:00
Updated By:	KPSARNOW
Crossref ID:	C224133
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2013-10-28 11:27:00
Record Updated:	2013-10-28 11:27:00
Updated By:	JEBROWN
Crossref ID:	A2-0622-0709
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2013-10-28 11:27:00
Record Updated:	2013-10-28 11:27:00
Updated By:	JEBROWN
Crossref ID:	08/20/2009
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2013-10-28 11:26:00
Record Updated:	2013-10-28 11:26:00
Updated By:	JEBROWN

INST CONTROL:

Name:	FRITO LAY
Address:	202-218 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Site Code:	407689
Control Name:	Landuse Restriction

FRITO LAY (Continued) **S109416391**

HW Code: C224133
Control Code: 25
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 05/31/2017
Updated By: CHPOST
Site Code: 407689
Site Description: "Location: The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features: The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures. Current Zoning and Land Use: The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site: The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Site Geology and Hydrogeology: The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel."
Env Problem: "The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site."
Health Problem: "The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported

FRITO LAY (Continued) **S109416391**

Record Add: 2008-12-11 13:40:00
Record Upd: 2013-09-20 14:10:00
Updated By: ldennist
Own Op: Document Repository
Sub Type: P03
Owner Name: Patricia Sacco, Library Information Supervisor
Owner Company: Brooklyn Public Library Bushwick Branch
Owner Address: 340 Bushwick Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Keith Massa
Owner Company: Rolling Frito-Lay Sales, LP
Owner Address: 7701 Legacy Drive
Owner Addr2: Not reported
Owner City,St,Zip: Plano, TX 75024-4099
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Cedric Robinson
Owner Company: Rolling Frito-Lay Sales, LP
Owner Address: 7701 Legacy Drive
Owner Addr2: Not reported
Owner City,St,Zip: Plano, TX 75024-4099
Owner Country: United States of America
HW Code: C224133
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: tetrachloroethene (PCE)

FRITO LAY (Continued) **S109416391**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: ER1609278
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-04-13 15:49:00
Record Updated: 2018-04-13 15:49:00
Updated By: CHPOST
Crossref ID: 2013000399904
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2013-10-11 11:05:00
Record Updated: 2013-10-11 11:05:00
Updated By: KPSARNOW
Crossref ID: C224133
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: A2-0622-0709
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: 08/20/2009
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2013-10-28 11:26:00
Record Updated: 2013-10-28 11:26:00
Updated By: JEBROWN

Name: FRITO LAY
Address: 202-218 MORGAN AVENUE
City,State,Zip: BROOKLYN, NY 11237
Site Code: 407689
Control Name: Soil Management Plan
HW Code: C224133
Control Code: 14
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 05/31/2017
Updated By: CHPOST
Site Code: 407689
Site Description: "Location: The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features: The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures. Current Zoning and Land Use: The site is currently

FRITO LAY (Continued) **S109416391**

vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site: The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Site Geology and Hydrogeology: The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel."

Env Problem: "The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site."

Health Problem: "The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2008-12-11 13:40:00
Record Upd: 2013-09-20 14:10:00
Updated By: ldennist
Own Op: Document Repository
Sub Type: P03
Owner Name: Patricia Sacco, Library Information Supervisor
Owner Company: Brooklyn Public Library Bushwick Branch
Owner Address: 340 Bushwick Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Keith Massa
Owner Company: Rolling Frito-Lay Sales, LP

FRITO LAY (Continued) **S109416391**

Owner Address: 7701 Legacy Drive
Owner Addr2: Not reported
Owner City,St,Zip: Plano, TX 75024-4099
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Cedric Robinson
Owner Company: Rolling Frito-Lay Sales, LP
Owner Address: 7701 Legacy Drive
Owner Addr2: Not reported
Owner City,St,Zip: Plano, TX 75024-4099
Owner Country: United States of America
HW Code: C224133
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: ER1609278
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-04-13 15:49:00
Record Updated: 2018-04-13 15:49:00
Updated By: CHPOST
Crossref ID: 2013000399904
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier

FRITO LAY (Continued) **S109416391**

Record Added Date: 2013-10-11 11:05:00
Record Updated: 2013-10-11 11:05:00
Updated By: KPSARNOW
Crossref ID: C224133
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: A2-0622-0709
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: 08/20/2009
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2013-10-28 11:26:00
Record Updated: 2013-10-28 11:26:00
Updated By: JEBROWN

Name: FRITO LAY
Address: 202-218 MORGAN AVENUE
City,State,Zip: BROOKLYN, NY 11237
Site Code: 407689
Control Name: Monitoring Plan
HW Code: C224133
Control Code: 31
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 05/31/2017
Updated By: CHPOST
Site Code: 407689
Site Description: "Location: The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features: The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures. Current Zoning and Land Use: The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site: The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Site Geology and Hydrogeology: The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel."
Env Problem: "The remedial plan for the site was implemented such that the site no

FRITO LAY (Continued) **S109416391**

longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site."

Health Problem: "The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2008-12-11 13:40:00
Record Upd: 2013-09-20 14:10:00
Updated By: ldennist
Own Op: Document Repository
Sub Type: P03
Owner Name: Patricia Sacco, Library Information Supervisor
Owner Company: Brooklyn Public Library Bushwick Branch
Owner Address: 340 Bushwick Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Keith Massa
Owner Company: Rolling Frito-Lay Sales, LP
Owner Address: 7701 Legacy Drive
Owner Addr2: Not reported
Owner City,St,Zip: Plano, TX 75024-4099
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Cedric Robinson
Owner Company: Rolling Frito-Lay Sales, LP
Owner Address: 7701 Legacy Drive
Owner Addr2: Not reported
Owner City,St,Zip: Plano, TX 75024-4099
Owner Country: United States of America
HW Code: C224133
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN

FRITO LAY (Continued) **S109416391**

Waste Code: Not reported
HW Code: C224133
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: ER1609278
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-04-13 15:49:00
Record Updated: 2018-04-13 15:49:00
Updated By: CHPOST
Crossref ID: 2013000399904
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2013-10-11 11:05:00
Record Updated: 2013-10-11 11:05:00
Updated By: KPSARNOW
Crossref ID: C224133
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: A2-0622-0709
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN

FRITO LAY (Continued) **S109416391**

Crossref ID: 08/20/2009
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2013-10-28 11:26:00
Record Updated: 2013-10-28 11:26:00
Updated By: JEBROWN

Name: FRITO LAY
Address: 202-218 MORGAN AVENUE
City,State,Zip: BROOKLYN, NY 11237
Site Code: 407689
Control Name: Site Management Plan
HW Code: C224133
Control Code: 32
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 05/31/2017
Updated By: CHPOST
Site Code: 407689
Site Description: "Location: The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features: The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures. Current Zoning and Land Use: The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site: The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Site Geology and Hydrogeology: The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel."
Env Problem: "The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site."
Health Problem: "The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential

FRITO LAY (Continued) **S109416391**

exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2008-12-11 13:40:00
Record Upd: 2013-09-20 14:10:00
Updated By: ldennist
Own Op: Document Repository
Sub Type: P03
Owner Name: Patricia Sacco, Library Information Supervisor
Owner Company: Brooklyn Public Library Bushwick Branch
Owner Address: 340 Bushwick Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Keith Massa
Owner Company: Rolling Frito-Lay Sales, LP
Owner Address: 7701 Legacy Drive
Owner Addr2: Not reported
Owner City,St,Zip: Plano, TX 75024-4099
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Cedric Robinson
Owner Company: Rolling Frito-Lay Sales, LP
Owner Address: 7701 Legacy Drive
Owner Addr2: Not reported
Owner City,St,Zip: Plano, TX 75024-4099
Owner Country: United States of America
HW Code: C224133
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: ARSENIC

FRITO LAY (Continued) **S109416391**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: ER1609278
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-04-13 15:49:00
Record Updated: 2018-04-13 15:49:00
Updated By: CHPOST
Crossref ID: 2013000399904
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2013-10-11 11:05:00
Record Updated: 2013-10-11 11:05:00
Updated By: KPSARNOW
Crossref ID: C224133
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: A2-0622-0709
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: 08/20/2009
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2013-10-28 11:26:00
Record Updated: 2013-10-28 11:26:00
Updated By: JEBROWN

Name: FRITO LAY
Address: 202-218 MORGAN AVENUE
City,State,Zip: BROOKLYN, NY 11237
Site Code: 407689
Control Name: O&M Plan
HW Code: C224133
Control Code: 33
Control Type: INST

FRITO LAY (Continued) **S109416391**

Dt record added: 10/22/2013
Dt rec updated: 05/31/2017
Updated By: CHPOST
Site Code: 407689
Site Description: "Location: The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features: The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures. Current Zoning and Land Use: The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site: The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Site Geology and Hydrogeology: The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel."
Env Problem: "The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site."
Health Problem: "The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2008-12-11 13:40:00
Record Upd: 2013-09-20 14:10:00
Updated By: ldennist

FRITO LAY (Continued) **S109416391**

Own Op: Document Repository
Sub Type: P03
Owner Name: Patricia Sacco, Library Information Supervisor
Owner Company: Brooklyn Public Library Bushwick Branch
Owner Address: 340 Bushwick Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Keith Massa
Owner Company: Rolling Frito-Lay Sales, LP
Owner Address: 7701 Legacy Drive
Owner Addr2: Not reported
Owner City,St,Zip: Plano, TX 75024-4099
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Cedric Robinson
Owner Company: Rolling Frito-Lay Sales, LP
Owner Address: 7701 Legacy Drive
Owner Addr2: Not reported
Owner City,St,Zip: Plano, TX 75024-4099
Owner Country: United States of America
HW Code: C224133
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133

FRITO LAY (Continued) **S109416391**

Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: ER1609278
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-04-13 15:49:00
Record Updated: 2018-04-13 15:49:00
Updated By: CHPOST
Crossref ID: 2013000399904
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2013-10-11 11:05:00
Record Updated: 2013-10-11 11:05:00
Updated By: KPSARNOW
Crossref ID: C224133
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: A2-0622-0709
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: 08/20/2009
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2013-10-28 11:26:00
Record Updated: 2013-10-28 11:26:00
Updated By: JEBROWN

Name: FRITO LAY
Address: 202-218 MORGAN AVENUE
City,State,Zip: BROOKLYN, NY 11237
Site Code: 407689
Control Name: IC/EC Plan
HW Code: C224133
Control Code: 34
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 05/31/2017
Updated By: CHPOST
Site Code: 407689
Site Description: "Location: The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features: The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures. Current Zoning and Land Use: The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site: The site was previously used as a scrap metal

FRITO LAY (Continued) **S109416391**

yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Site Geology and Hydrogeology: The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel."

Env Problem: "The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site."

Health Problem: "The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2008-12-11 13:40:00
Record Upd: 2013-09-20 14:10:00
Updated By: ldennist
Own Op: Document Repository
Sub Type: P03
Owner Name: Patricia Sacco, Library Information Supervisor
Owner Company: Brooklyn Public Library Bushwick Branch
Owner Address: 340 Bushwick Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11206
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Keith Massa
Owner Company: Rolling Frito-Lay Sales, LP
Owner Address: 7701 Legacy Drive
Owner Addr2: Not reported
Owner City,St,Zip: Plano, TX 75024-4099

FRITO LAY (Continued) **S109416391**

Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Cedric Robinson
Owner Company: Rolling Frito-Lay Sales, LP
Owner Address: 7701 Legacy Drive
Owner Addr2: Not reported
Owner City,St,Zip: Plano, TX 75024-4099
Owner Country: United States of America
HW Code: C224133
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: ER1609278
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-04-13 15:49:00
Record Updated: 2018-04-13 15:49:00
Updated By: CHPOST
Crossref ID: 2013000399904
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2013-10-11 11:05:00
Record Updated: 2013-10-11 11:05:00
Updated By: KPSARNOW

FRITO LAY (Continued) **S109416391**

Crossref ID: C224133
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: A2-0622-0709
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: 08/20/2009
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2013-10-28 11:26:00
Record Updated: 2013-10-28 11:26:00
Updated By: JEBROWN

Name: FRITO LAY
Address: 202-218 MORGAN AVENUE
City,State,Zip: BROOKLYN, NY 11237
Site Code: 407689
Control Name: Environmental Easement
HW Code: C224133
Control Code: J
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 05/31/2017
Updated By: CHPOST
Site Code: 407689
Site Description: "Location: The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features: The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures. Current Zoning and Land Use: The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site: The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Site Geology and Hydrogeology: The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel."
Env Problem: "The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals,

FRITO LAY (Continued) **S109416391**

	such as lead and mercury, in soil throughout the site."
Health Problem:	"The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2008-12-11 13:40:00
Record Upd:	2013-09-20 14:10:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	P03
Owner Name:	Patricia Sacco, Library Information Supervisor
Owner Company:	Brooklyn Public Library Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Keith Massa
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Cedric Robinson
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099
Owner Country:	United States of America
HW Code:	C224133
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	TETRACHLOROETHYLENE (PCE)

FRITO LAY (Continued) **S109416391**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: ER1609278
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-04-13 15:49:00
Record Updated: 2018-04-13 15:49:00
Updated By: CHPOST
Crossref ID: 2013000399904
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2013-10-11 11:05:00
Record Updated: 2013-10-11 11:05:00
Updated By: KPSARNOW
Crossref ID: C224133
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: A2-0622-0709
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: 08/20/2009
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date

FRITO LAY (Continued) **S109416391**

Record Added Date: 2013-10-28 11:26:00
Record Updated: 2013-10-28 11:26:00
Updated By: JEBROWN

Name: FRITO LAY
Address: 202-218 MORGAN AVENUE
City,State,Zip: BROOKLYN, NY 11237
Site Code: 407689
Control Name: Ground Water Use Restriction
HW Code: C224133
Control Code: 08
Control Type: INST
Dt record added: 10/22/2013
Dt rec updated: 05/31/2017
Updated By: CHPOST
Site Code: 407689
Site Description: "Location: The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features: The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures. Current Zoning and Land Use: The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site: The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Site Geology and Hydrogeology: The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel."
Env Problem: "The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site."
Health Problem: "The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied."

FRITO LAY (Continued) **S109416391**

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2008-12-11 13:40:00
Record Upd:	2013-09-20 14:10:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	P03
Owner Name:	Patricia Sacco, Library Information Supervisor
Owner Company:	Brooklyn Public Library Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Keith Massa
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Cedric Robinson
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099
Owner Country:	United States of America
HW Code:	C224133
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133

FRITO LAY (Continued) **S109416391**

Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C224133
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: ER1609278
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-04-13 15:49:00
Record Updated: 2018-04-13 15:49:00
Updated By: CHPOST
Crossref ID: 2013000399904
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2013-10-11 11:05:00
Record Updated: 2013-10-11 11:05:00
Updated By: KPSARNOW
Crossref ID: C224133
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: A2-0622-0709
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2013-10-28 11:27:00
Record Updated: 2013-10-28 11:27:00
Updated By: JEBROWN
Crossref ID: 08/20/2009
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2013-10-28 11:26:00
Record Updated: 2013-10-28 11:26:00
Updated By: JEBROWN

BROWNFIELDS:

Name:	FRITO LAY
Address:	202-218 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Program:	BCP
Site Code:	407689
Acres:	2.760
HW Code:	C224133
SWIS:	2401
Town:	New York City
Record Added Date:	12/11/2008

FRITO LAY (Continued) **S109416391**

Record Updated Date:	04/15/2021
Update By:	SMQUANDT
Site Description:	"Location: The site is located at 202-218 Morgan Avenue in an urban area in the north end of the Borough of Brooklyn, Kings County. To the north of the property is a warehouse, to the east and south is the English Kills, a tributary to the Newtown Creek, and to the west the site is bordered by Morgan Avenue, between Ten Eyck Street and Stagg Street. Site Features: The site property is approximately 2.8 acres in area and is currently undeveloped with no standing structures. Current Zoning and Land Use: The site is currently vacant, and is zoned for industrial use. The surrounding parcels are currently used for a combination of commercial and industrial use. Past Use of the Site: The site was previously used as a scrap metal yard. The activities related to this type of business are the apparent source of site-wide PCB contamination. Scrap activities and the presence of historic fill material are believed to be the cause of the site-wide metals contamination. Site Geology and Hydrogeology: The site is approximately 13 feet above mean sea level. Depth to groundwater is approximately 11 feet below ground surface. The nearest water body is the English Kills, a tributary to the Newtown Creek, which abuts the eastern and south sides of the site. Groundwater flow is to the southeast. The site soil is primarily fill material to the water table. Below the fill material the site is underlain by sand and gravel."
Env Problem:	"The remedial plan for the site was implemented such that the site no longer presents a significant environmental threat due to the ongoing release of arsenic contamination from source areas in the soil to groundwater, as well as the high levels of PCBs and other metals, such as lead and mercury, in soil throughout the site."
Health Problem:	"The site is fenced and covered with asphalt and concrete; therefore, people are not expected to come into contact with site-related contaminants in soil and groundwater unless they dig below the site cover system. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings which are developed and occupied."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2008-12-11 13:40:00
Record Upd:	2013-09-20 14:10:00
Updated By:	ldennist
Own Op:	Document Repository
Sub Type:	P03
Owner Name:	Patricia Sacco, Library Information Supervisor

FRITO LAY (Continued) **S109416391**

Owner Company:	Brooklyn Public Library Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Keith Massa
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Cedric Robinson
Owner Company:	Rolling Frito-Lay Sales, LP
Owner Address:	7701 Legacy Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Plano, TX 75024-4099
Owner Country:	United States of America
HW Code:	C224133
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224133
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

FRITO LAY (Continued) **S109416391**

Crossref ID:	ER1609278
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2018-04-13 15:49:00
Record Updated:	2018-04-13 15:49:00
Updated By:	CHPOST
Crossref ID:	2013000399904
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2013-10-11 11:05:00
Record Updated:	2013-10-11 11:05:00
Updated By:	KPSARNOW
Crossref ID:	C224133
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2013-10-28 11:27:00
Record Updated:	2013-10-28 11:27:00
Updated By:	JEBROWN
Crossref ID:	A2-0622-0709
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2013-10-28 11:27:00
Record Updated:	2013-10-28 11:27:00
Updated By:	JEBROWN
Crossref ID:	08/20/2009
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2013-10-28 11:26:00
Record Updated:	2013-10-28 11:26:00
Updated By:	JEBROWN

AB181 **FRITO-LAY** **NY SWF/LF** **S108635814**
WSW **202 MORGAN AVENUE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11237** **NY MANIFEST**
0.262 mi.
1386 ft. **Site 2 of 2 in cluster AB**

Relative:
Lower

Actual:
13 ft.

SWF/LF:

Name:	KARNAK (NEWTOWN METAL CORP.)
Address:	202 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	7183660717
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	STANLEY K. HORNG
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit

FRITO-LAY (Continued) **S108635814**

Activity Number: [24T60]
Active: No
East Coordinate: 589900
North Coordinate: 4507500
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: 2-6101-00015
Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Not reported
Operator Type: Not reported
Laste Date: Not reported

SPILLS:
Name: DRUM RUN
Address: 202 MORGAN AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0700119 / 2007-05-23
Facility ID: 0700119
Facility Type: ER
DER Facility ID: 328885
Site ID: 379402
DEC Region: 2
Spill Cause: Abandoned Drums
Spill Class: C3
SWIS: 2401
Spill Date: 2007-04-04
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 2007-04-04
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2007-04-04
Spill Record Last Update: 2007-05-23
Spiller Name: VICTOR LEE
Spiller Company: ON SIDEWALK
Spiller Address: 202 MORGAN AV
Spiller Company: 001
Contact Name: VICTOR LEE
DEC Memo: "add to next drum run 05/23/07 Drum was not found on 05/22/07."
Remarks: "DRUM ON SIDEWALK NEEDS TO BE PICKED UP"

All Materials:
Site ID: 379402
Operable Unit ID: 1136884
Operable Unit: 01
Material ID: 2126828
Material Code: 0022

FRITO-LAY (Continued) **S108635814**

Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Name:	FRITO-LAY
Address:	202 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYR000188193
Facility Status:	Not reported
Location Address 1:	202 MORGAN AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000188193
Mailing Name:	FRITO-LAY
Mailing Contact:	BRYAN TISKOWITZ
Mailing Address 1:	202-218 MORGAN AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYR000159962
Trans2 State ID:	Not reported
Generator Ship Date:	12/07/2012
Trans1 Recv Date:	12/07/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/10/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000188193
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	009979236JJK

FRITO-LAY (Continued) **S108635814**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	31706
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	B007
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

182
West
1/4-1/2
0.266 mi.
1402 ft.

DURITE S&V & MAINT. CORP.
250 MORGAN AVE
BROOKLYN, NY 11237

NY SWF/LF **S105841904**
N/A

Relative:
Higher

Actual:
16 ft.

SWF/LF:

Name:	DURITE S&V & MAINT. CORP.
Address:	250 MORGAN AVE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	7184177271
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	STEVE RUSSEL; OWNER
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration

DURITE S&V & MAINT. CORP. (Continued) **S105841904**

Activity Number:	[24W67]
Active:	No
East Coordinate:	589000
North Coordinate:	4507200
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	Not reported
Authorization #:	2-6104-00016
Authorization Date:	5/21/1991
Expiration Date:	5/31/1996
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

AC183 **WASTE MANAGEMENT OF NY; INC.; (101 VARIC** **NY SWRCY** **S104953192**
South **101 VARICK AVENUE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11237** **NY SPDES**
0.266 mi.
1406 ft. **Site 1 of 2 in cluster AC**

Relative: SWRCY:
Lower

Actual: Name:	WASTE MANAGEMENT OF NY; INC.; (101 VARIC
9 ft. Address:	101 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Region:	2
Facility Address 2:	Not reported
Phone Number:	7183867900
Owner Type:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner Address 2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	ANTHONY LOMANGINO; PRES.
Contact Address:	Not reported
Contact Address 2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	RHRF - registration
Activity Number:	[24MD7]
Active:	No
East Coordinate:	Not reported
North Coordinate:	Not reported
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Permit #:	Not reported
Auth. Date:	Not reported
Expiration Date:	Not reported
Waste Types:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Last Date:	Not reported

SPILLS:

Name:	INDUSTRIAL

WASTE MANAGEMENT OF NY; INC.; (101 VARIC (Continued) **S104953192**

Address:	101 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2001862 / 2021-03-11
Facility ID:	2001862
Facility Type:	ER
DER Facility ID:	554957
Site ID:	606526
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	3101
Spill Date:	2020-06-13
Investigator:	VSZHUNE
Referred To:	Not reported
Reported to Dept:	2020-06-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2020-06-13
Spill Record Last Update:	2021-03-16
Spiller Name:	Not reported
Spiller Company:	WATCOS
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	FRANCIS CONDRICK
DEC Memo:	"6/13/20-Lin-According to caller, a former employee was suspected to open the valve to a diesel tote and about 40 gallons of diesel went onto facility concrete and a storm drain. The storm drain goes to the Newtown creek but the oil was contained in the drain and did not make it out to the creek. ACV was hired to perform the cleanup and pump out the drain. DEC Zhune was dispatched to site. Site contact: Leon Bangari 917-468-8097 ACV environmental 718-456-7779 ext 5516 6/13/20-Zhune responded to this spill. During my inspection I observed the surface cleaned. It was cleaned by Watco personal. Watco checked the four storm drain and the oil did not go to the creek, ACV confirmed that the oil did not reach the creek. ACV was going to pumped out the oil from the storm drain. Sunil- 347-865-9937 3/11/21- Zhune- Jesse Rivera from ACV Enviro sent the following email. Attaches are the T&M and manifest document for the clean up at Varick Ave. ACV was called by Watco companies to pump out and wash down storm drain that was impacted by approx.. 2-3 gallons of diesel. ACV cleaned the affected storm drain and also 3 more that were connected. Spill Closed."
Remarks:	"clean up in progress was removed from storm drain"

All Materials:

Site ID:	606526
Operable Unit ID:	1353693
Operable Unit:	01
Material ID:	2364702
Material Code:	0008

WASTE MANAGEMENT OF NY; INC.; (101 VARIC (Continued) **S104953192**

Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	WASTE MANAGEMENT
Address:	101 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1001432 / 2010-09-02
Facility ID:	1001432
Facility Type:	ER
DER Facility ID:	264863
Site ID:	434486
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2010-05-06
Investigator:	HRAHMED
Referred To:	Not reported
Reported to Dept:	2010-05-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-06
Spill Record Last Update:	2010-09-02
Spiller Name:	JAY KAPLAN
Spiller Company:	HISTORICAL SPILL
Spiller Address:	101 VARICK AVE
Spiller Company:	999
Contact Name:	JAY KAPLAN
DEC Memo:	"7/7/10-HRAHMED-Receieved Remedial Action report from Day Environmental. 8/4/10-HRAHMED-Started Reviewing Remedial Action report. PBS#2-605608 Requirements: 1) Update PBS records to reflect closure and removal of 8000 gal UST and resolve conflicts with Fire dept. record "
Remarks:	"During excavation abandoned tank filled with concrete was found. Soil was contaminated. Clean up is in progress. Environmnetal Consultant has been hired to perform an environmnetal closure report and remeidiation."

All Materials:

Site ID:	434486
Operable Unit ID:	1185310
Operable Unit:	01
Material ID:	2179628
Material Code:	0001A

WASTE MANAGEMENT OF NY; INC.; (101 VARIC (Continued) **S104953192**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	WASTE MANAGEMENT
Address:	101 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0012799 / 2001-03-05
Facility ID:	0012799
Facility Type:	ER
DER Facility ID:	264863
Site ID:	329115
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-03-03
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2001-03-03
CID:	396
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-03
Spill Record Last Update:	2001-07-11
Spiller Name:	Not reported
Spiller Company:	LAFAYETTE GRINDING
Spiller Address:	115 BANKER ST
Spiller Company:	001
Contact Name:	NYC DEP
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO nyfd RESPONDED TO SCENE OF SMOKING DEBRIS. NO SPILL"
Remarks:	"caller was advised by waste management that they picked up a 20 yard roll off container of unk. material in dirt...it is smoking...container was picked up at lafayette grinding and transported to wastemanagement facility...it is still there now."

All Materials:

Site ID:	329115
Operable Unit ID:	834334
Operable Unit:	01
Material ID:	543069
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other

WASTE MANAGEMENT OF NY; INC.; (101 VARIC (Continued) **S104953192**

Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPDES:

Name:	WASTE MANAGEMENT OF NY LLC - NYC HAULING
Address:	101 VARICK AVE
City,State,Zip:	BROOKLYN, NY 10454
Permit Number:	NYR00D388
State-Region:	02
Expiration Date:	03/31/2012
Current Major Minor Status:	Minor
Primary Facility SIC Code:	4212
State Water Body Name:	ENGLISH KILLS CREEK
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	+40.708806 / -73.928222
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	WAST MANAGEMENT OF NEW YORK LLC
Non-Gov Permit Street Address:	NYC HAULING
Non-Gov Permit Supplemental Location:	123 VARICK AVE
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11237
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	WASTE MANAGEMENT OF NEW YORK LLC
Non-Gov Facility Street Address:	WASTE MANAGEMENT OF NY LLC - NYC HAULING
Non-Gov Facility Supplemental Location:	123 VARICK AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11237
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	WASTE MANAGEMENT OF NY LLC - NYC HAULING
Address:	101 VARICK AVE
City,State,Zip:	BROOKLYN, NY 10454
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

WASTE MANAGEMENT OF NY; INC.; (101 VARIC (Continued) **S104953192**

Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	WASTE MANAGEMENT OF NEW YORK LLC
Non-Gov Permit Street Address:	123 VARICK AVE
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11237
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	WASTE MANAGEMENT OF NEW YORK LLC
Non-Gov Facility Street Address:	WASTE MANAGEMENT OF NY LLC - NYC HAULING
Non-Gov Facility Supplemental Location:	123 VARICK AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11237
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	WASTE MANAGEMENT OF NY LLC - NYC HAULING
Address:	101 VARICK AVE
City,State,Zip:	BROOKLYN, NY 10454
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	WASTE MANAGEMENT OF NEW YORK LLC
Non-Gov Facility Street Address:	WASTE MANAGEMENT OF NY LLC - NYC HAULING
Non-Gov Facility Supplemental Location:	123 VARICK AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11237
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

184
WNW
1/4-1/2
0.274 mi.
1445 ft.

GREEN HILL
2 REWE ST & 300 VANDERVOO
BROOKLYN, NY

NY LTANKS **S105999093**
N/A

Relative:
Lower

Actual:
9 ft.

LTANKS:

Name:	GREEN HILL
Address:	2 REWE ST & 300 VANDERVOO
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0302094 / 2006-01-31
Facility ID:	0302094
Site ID:	191858
Spill Date:	2003-05-29
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JXZHAO
Referred To:	Not reported
Reported to Dept:	2003-05-29
CID:	297
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-05-29
Spill Record Last Update:	2006-01-31
Spiller Name:	ALBERT CHAN
Spiller Company:	Not reported
Spiller Address:	2 REWE ST & 300 VANDERVOO
Spiller County:	001
Spiller Contact:	ALBERT CHAN
Spiller Phone:	(718) 963-2800
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	160009
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHAO Sangesland DDO Zhao is assigned because consultant dealt with her on this site. Contaminated soil letter was sent to: Consultant is: Andrew Drotleff of TRC Raviv Assoc (973-564-6006 x285) 57 East Willow St., Millburn, NJ 07041 Site is a corner lot with 2 addresses: (2 Rewe St & 300 Vandervoort) PBS 2-608764 Two tanks are being abandoned in place (3,000 gal and 2,000) One tank had pin holes in it and water poured in from raised water table. The second tank appeared OK, but had some oil odor from the soil in the piping area. 10/31/2005 - JZ: Zhao spoke with Andrew Drotleff, TRC. Recently took GW samples from 3 wells. Sesults are favorable and look clean. Report will be send in end November. 1/31/2006 - JZ: Report was submitted and reviewed. spill is closed. "
Remarks:	"CALLERS COMPANY PERFORMING A TANK CLOSURE AND CONTAMINATED SOIL WAS DISCOVERED AROUND 2 TANKS"

All Materials:

Site ID:	191858
Operable Unit ID:	870003

GREEN HILL (Continued) **S105999093**

Operable Unit:	01
Material ID:	506580
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Site ID:	191858
Operable Unit ID:	870003
Operable Unit:	01
Material ID:	506579
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

185 **COTOIA ENTERPRISES** **NY SWRCY** **S105842300**
East **46-26 METROPOLITAN AVE.** **N/A**
1/4-1/2 **RIDGEWOOD, NY 0**
0.274 mi.
1448 ft.

Relative: **Lower**

Actual: **9 ft.**

SWRCY:

Name:	COTOIA ENTERPRISES
Address:	46-26 METROPOLITAN AVE.
City,State,Zip:	RIDGEWOOD, NY 0
Region:	2
Facility Address 2:	Not reported
Phone Number:	7183811134
Owner Type:	Not reported
Owner Name:	Marcangelo Cotoia
Owner Address:	46-26 Metropolitan Ave.
Owner Address 2:	Not reported
Owner City,St,Zip:	Ridgewood, NY 11385
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Address 2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	RHRF - registration
Activity Number:	[00M00]
Active:	No
East Coordinate:	Not reported
North Coordinate:	Not reported
Accuracy Code:	Not reported
Regulatory Status:	Not reported

COTOIA ENTERPRISES (Continued) **S105842300**

Permit #:	2-3790-91-07
Auth. Date:	Not reported
Expiration Date:	Not reported
Waste Types:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Last Date:	Not reported

186
NE
1/4-1/2
0.275 mi.
1452 ft.

Relative:
Lower

Actual:
4 ft.

YRC BROOKLYN (187)
1313 GRAND ST
BROOKLYN, NY 11211

RCRA-VSQG **1004756458**
NY LTANKS **NYD095769782**
NY Spills
FINDS
ECHO
NY MANIFEST
NY SPDES

RCRA-VSQG:

Date Form Received by Agency:		20070101
Handler Name:	ROADWAY EXPRESS	
Handler Address:		1313 GRAND ST
Handler City,State,Zip:		BROOKLYN, NY 11211
EPA ID:		NYD095769782
Contact Name:		THOMAS W GERHOLD
Contact Address:		ROE AVE
Contact City,State,Zip:		OVERLAND PARK, KS 66211
Contact Telephone:		913-344-3066
Contact Fax:		Not reported
Contact Email:		TOM.GERHOLD@YELLOWROADWAY.COM
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		ROE AVE
Mailing City,State,Zip:		OVERLAND PARK, KS 66211
Owner Name:		ROADWAY EXPRESS
Owner Type:		Private
Operator Name:		ROADWAY EXPRESS
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported

YRC BROOKLYN (187) (Continued) **1004756458**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE

YRC BROOKLYN (187) (Continued) **1004756458**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ROADWAY SERVICES INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ROADWAY EXPRESS
Legal Status:	Private
Date Became Current:	19850301
Date Ended Current:	Not reported
Owner/Operator Address:	1077 GORGE BLVD
Owner/Operator City,State,Zip:	AKRON, OH 44309
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ROADWAY EXPRESS
Legal Status:	Private
Date Became Current:	19850301
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ROADWAY EXPRESS
Legal Status:	Private
Date Became Current:	19850301
Date Ended Current:	Not reported
Owner/Operator Address:	1077 GORGE BLVD
Owner/Operator City,State,Zip:	AKRON, OH 44309
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ROADWAY EXPRESS
Legal Status:	Private
Date Became Current:	19850301
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported

YRC BROOKLYN (187) (Continued) **1004756458**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060306
Handler Name: ROADWAY EXPRESS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ROADWAY EXPRESS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19860728
Handler Name: ROADWAY EXPRESS INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060307
Handler Name: ROADWAY EXPRESS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

YRC BROOKLYN (187) (Continued) **1004756458**

List of NAICS Codes and Descriptions:
NAICS Code: 484122
NAICS Description: GENERAL FREIGHT TRUCKING, LONG-DISTANCE, LESS THAN TRUCKLOAD

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

LTANKS:
Name: ROADWAY EXPRESS
Address: 1313 GRAND ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1004888 / 2013-02-22
Facility ID: 1004888
Site ID: 438179
Spill Date: 2010-07-30
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: JBVOUGHT
Referred To: Not reported
Reported to Dept: 2010-07-30
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2010-07-30
Spill Record Last Update: 2013-02-22
Spiller Name: PHYLLIS TAINISH DEPT A-20
Spiller Company: ROADWAY EXPRESS INC
Spiller Address: 1077 GORGE BLVD
Spiller County: 999
Spiller Contact: MARK SHIRLEY
Spiller Phone: (212) 292-2210
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 143819
DEC Memo: "7/30/10 - Raphael Ketani. Advanced Tank Service (Jeff McKenzie - (800) 440-8265) did a tank system test. The system failed and the spill was called in today. The subject UST is 1,000 gal. and contains #2 oil. It was installed on 12/1/88. The site is Roadway Express Inc., 1313 Grand Street, Brooklyn. The local contact is Marc Shirley (212) 292-2210. There are two PBS cases, #2-157724 and 32-043826. The #2-157724 case shows 17 tanks that were all closed prior to March 1991. The #2-043826 case shows 21 tanks. Most of the tanks had diesel or gasoline. One 1,000 gal. tank has #2 oil. Sixteen tanks were

YRC BROOKLYN (187) (Continued) **1004756458**

closed prior to March 1991. Four tanks were closed and removed on 9/1/88. The one active tank is the 1,000 gal. UST. Mail goes to Roadway Express Inc., 1077 Gorge Blvd., Akron, OH, 44310, attn: Phyllis Tainish - Dept. A-20, (330) 258-2475. The owner is Roadway Express, 1077 Gorge Blvd., Akron, OH, 44309, (216) 384-1717, local number (718) 821-5410 - Jack Leslie T.M. A TTF letter was sent to the mailing address. 8/27/10 Received 2 voicemail messages from Jeff Lawson, consultant from Cleveland, OH. Phone: (440)268-0333. He requested more time to respond to ttf letter. I was not aware of this spill case until yesterday. This is a non-regulated site since the tank stores less than 1000 gallons of heating oil. He requested more time to respond to the ttf letter and he believed the site was unregulated. I called him today at approximately 3:15 PM and left a message allowing more time for a response; stating that based on the info in DEC database the site is unregulated, but the spill must be addressed as per NL; and that he should call me this afternoon or next week so we can discuss the case. bf 9/20/10 Found letter dated 8/27/10 on my desk. It was received by DEC on 9/3/10. The letter asks the questions that were answeered in the voicemail on 8/27/10. Letter is in e-docs. bf 1/19/11 Received voicemail from PBS Voicemail at 9:46 from Jeff Lawson. Phone:(440)268-0333. He stated that they are ready to close the tank and would like to discuss. I returned call at approx. 1:30 PM and left a message to call me. bf 1/26/11 Spoke to Mike Ruffoni of Reliance Environmental (717)735-9508. Explained that he needs to address ttf. They are still not sdure why tank failed. Tank removal is planned. bf 2/22/13-Vought-This spill transferred from Falvey to Vought as Vought performing comprehensive file and site review in relation to reviewing results for above tank excavation and removal as well as all former tanks on property. This spill closed and referred to open Spill 0910021 at same site."

Remarks: "cleanup pending - sub contractor reporting"

All TTF:

Facility ID:	1004888
Spill Number:	1004888
Spill Tank Test:	2489265
Site ID:	438179
Tank Number:	21
Tank Size:	1000
Material:	0001
EPA UST:	False
UST:	True
Cause:	03
Source:	01
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	RVKETANI
Last Modified Date:	Not reported

All Materials:

Site ID:	438179
Operable Unit ID:	1188844
Operable Unit:	01
Material ID:	2183775
Material Code:	0001A

YRC BROOKLYN (187) (Continued) **1004756458**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	1313 GRAND ST/BKLYN/ROADW
Address:	1313 GRAND ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8708981 / 1992-10-07
Facility ID:	8708981
Site ID:	170911
Spill Date:	1988-01-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-10-07
SWIS:	2401
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1988-01-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-01-26
Spill Record Last Update:	2002-11-13
Spiller Name:	Not reported
Spiller Company:	ROADWAY EXPRESS
Spiller Address:	1313 GRAND ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	143819
DEC Memo:	""
Remarks:	"1K TANK SYSTEM FAILED HYDROSTATIC AIR TEST, TO REMOVE PRODUCT ON 1/21/88 AND REPLACE TANK."

All TTF:

Facility ID:	8708981
Spill Number:	8708981
Spill Tank Test:	1533057
Site ID:	170911
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported

YRC BROOKLYN (187) (Continued) **1004756458**

Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	170911
Operable Unit ID:	914235
Operable Unit:	01
Material ID:	464329
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	ROADWAY EXPRESS
Address:	1313 GRAND ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0103983 / 2001-07-28
Facility ID:	0103983
Facility Type:	ER
DER Facility ID:	143819
Site ID:	170910
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-07-14
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2001-07-14
CID:	211
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-14
Spill Record Last Update:	2002-05-15
Spiller Name:	LEONA BOWSER
Spiller Company:	ROADWAY EXPRESS
Spiller Address:	1077 GORGE BLVD
Spiller Company:	001

YRC BROOKLYN (187) (Continued) **1004756458**

Contact Name:	LEONA BOWSER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD All cleaned up by the spiller."
Remarks:	"CRACK IN FUEL LINE CAUSED SPILL - SPEEDY DRY CONTAINED SPILL AND CLEAN UP IN PROGRESS"

All Materials:

Site ID:	170910
Operable Unit ID:	842517
Operable Unit:	01
Material ID:	532494
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	ROADWAY EXPRESS INC
Address:	1313 GRAND ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9808077 / 2007-09-12
Facility ID:	9808077
Facility Type:	ER
DER Facility ID:	143819
Site ID:	170912
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	1998-09-30
Investigator:	WXSUN
Referred To:	TCR PREPARED BY APEX ENV.
Reported to Dept:	1998-10-01
CID:	366
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-01
Spill Record Last Update:	2007-09-12
Spiller Name:	JACK LESLIE
Spiller Company:	ROADWAY EXPRESS INC
Spiller Address:	1313 GRAND ST
Spiller Company:	001
Contact Name:	JACK LESLIE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN TANK REMOVAL. SOIL AROUND FILL CONTAMINATED, STOCKPILED. SAMPLES TAKEN. SOIL SAMPLES SHOWED HIGH SEMI-VOLS. TCLP DONE ON SAMPLES 11/3/03 - AUSTIN - REVIEW OF PBS FOR SITE FOUND ALL TANKS

YRC BROOKLYN (187) (Continued) **1004756458**

CLOSED OUT - CLOSURE REPORT IN UNASSIGNED SPILLS FILE - REASSIGN THIS REPORT AS PART OF PROJECT TRANSFERS BETWEEN SECTIONS - END 06/16/06: This spill is transferred from Mike Mulqueen to Mr. Koon Tang. 10/30/06 Reassigned from Tang to Sun. (MS) 8/6/07: Tank Closure Report re-located. Performed by Apex Environmental in February 1999. Reviewing for possible closure. (JS/MS) 9/11/07: All VOC was non-detect, SVOC was above but re-submited for TCLP and was below. (JS/MS) 9/12/07: TCR from APEX shows that site has been adequetely cleaned after the removal of fuel, diesel, and waste oil USTs. Approx 300 tons of soil was disposed of properly and the excavations were all backfilled with certified clean fill. A NFA letter was sent to Phyllis Tainish - the representative of Roadway Express Inc., at 1077 Gorge Blvd in Akron, OH 44310. This spill case closed on 9/12/07. (JS/MS)"

Remarks: "CALLER STATES A MINOR SPILL ON GROUND. CLEAN UP HAS BEEN ARRANGED."

All Materials:

Site ID:	170912
Operable Unit ID:	1069256
Operable Unit:	01
Material ID:	315608
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	ROADWAY EXPRESS TRUCKING TERMINAL
Address:	1313 GRAND STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0910021 / 2013-02-22
Facility ID:	0910021
Facility Type:	ER
DER Facility ID:	423271
Site ID:	422759
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2009-12-09
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2009-12-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-12-09

YRC BROOKLYN (187) (Continued) **1004756458**

Spill Record Last Update: 2013-02-22
Spiller Name: DERRIC KEARNS
Spiller Company: NORTH AMERICAN TERMINALS MANAGEMENT
Spiller Address: 1313 GRAND ST
Spiller Company: 999
Contact Name: DERRIC KEARNS
DEC Memo: "Phase 2 being done for a property transfer. Two groundwater samples slightly over limits for Benzene. Property Owner is: North American Terminals Management Inc. Attn: Miss Coleman Natmi Truck Terminals LLC c/o LaSalle Investment Management Inc. 100 East Pratt St.20th Flr Baltimore, Maryland 21202 No CSL letter was sent out, because Mr. Kearns said a full Phase 2 report was completed and he believes NYSDEC may just close the case out with the minor benzene numbers. Sangesland asked Mr. Kearns to submit the report to Hasan Ahmed and wait for further direction from the DEC for either closure or additional work. 02/24/10-HRAHMED-Deric Kearns (267 685 1800) called to get an update. Ask him to send me an electronic version of the report. 10/27/11 - Austin - Spill Transferred from Ahmed to Vought - end 7/31/12-Vought-Received call from and spoke to Mathew Sabbetta (Arcadis Ph:267-685-1800x1803). Contact is Robert Zimmermann (Arcadis Ph:330-434-1995). Site has a 1000-gallon #2 fuel tank that was noted in 2/11. Approximately fifteen soil borings were performed and one monitoring well was installed. 8/30/12-Vought-Reviewed July 2011 Subsurface Investigation Report and UST Investigation Report received via email on 7/31/12 from Matt Sabbetta. Complete file review by Vought: Vought reviewed Spills and PBS Database: PBS #2-043826 (expired 12/01): One 1000-gallon #2 fuel oil UST in service; one 2000-gallon diesel UST closed in 1998; two 4000-gallon diesel USTs closed in 1998; one 500-gallon gasoline UST closed in 1998; eight 550-gallon gasoline USTs and eight 550-gallon diesel USTs in service. PBS #2-157724(expired 10/92): Seventeen 550-gallon diesel USTs in service. SPILL 8708981: 1000-gallon UST system failed hydrostatic test and product to be removed and tank replaced as per caller remarks. No spill notes and no reports in e-docs. Spill closed 10/7/92. SPILL 9808077: As per DEC Remarks, Tank Closure Report from APEX shows that site has been adequetely cleaned after the removal of fuel, diesel, and waste oil USTs. Approx 300 tons of soil was disposed of properly and the excavations were all backfilled with certified clean fill. A NFA letter was sent to Phyllis Tainish - the representative of Roadway Express Inc., at 1077 Gorge Blvd in Akron, OH 44310. This spill case closed on 9/12/07. (JS/MS) Vought noted no report in edocs and no file able to be located in historical file room. SPILL 0103983: Caller Remarks noted that CRACK IN FUEL LINE CAUSED SPILL - SPEEDY DRY CONTAINED SPILL AND CLEAN UP IN PROGRESS . Spill closed on 7/28/01 and DEC remarks spill was all cleaned up . No reports in e-docs. SPILL 1004888: Tank Test failure of a 1000-gallon fuel oil UST and still spill open. No files in e-docs. SPILL 1130727: Spill report of contaminated soil. E-docs had Underground Storage Tank Closure report submitted by Reliance Environmental dated 3/28/11. Spill closed on 11/30/11. Removal of one 1000-gallon UST containing #2 fuel oil. Tank was out of service since 11/09 and was used as part of the maintenance garage heating system. UST was in concrete vault and 50-gallons of sludge and waste was removed from UST and tank and associated piping was removed from the ground. No holes or voids observed in tank and tank appeared to be in good condition . Groundwater was encountered at an initial depth of 5 feet below ground surface within the tank grave and was observed to

YRC BROOKLYN (187) (Continued) **1004756458**

contain a petroleum hydrocarbon layer . Elevated PID readings and staining in soils in northeastern sidewall of excavation at approximately 4.5'bg. Final excavation was 15' x 12' x 6'. No soil samples collected from base of excavation as they were below soil water interface. Photo in report shows recovery from water table in excavation. Soil analyticals show PAH exceedences attributable to fill. Spill closed by DEC Piper on 11/30/11 as no CP-51 Unrestricted Use exceedences for VOCs. 9/17/12-Vought-Continued File Review by Vought. Vought spoke with DEC Falvey (project manager of open TTF spill 1004888 and noted that UST that was subject of TTF in 1004888 was removed as subject of closed spill spill 1130727. Falvey agreed that spill 1004888 could be closed and that no PBS update was needed to reflect closure of 1000-gallon #2 fuel oil UST since all other tanks were administratively closed and the site falls currently under the 1100-gallon PBS registration requirement. July 2011 Subsurface Investigation Report (Arcadis)-4/25/12. Sampling done without written instruction from DEC as numerous requests submitted to DEC project manager Hasan Ahmed with out a response. Groundwater sampling done following discussion with DEC Ahmed and RSE in 6/10. DEC required soil and groundwater sample be taken across various locations onsite however DEC did not send letter formalizing requirements. Soil borings from previous investigations also included in report. Phase I and Phase II completed in 2009 and showed elevated SVOCs, metals in soil and 43ppb benzene in groundwater. In 2009 soil temporary wells were installed and subsequently abandoned. Maximum benzene concentrations in groundwater of 17ppb and spill 0910021 was reported. A Groundwater Investigation Report was submitted to DEC on 12/21/09. DEC Ahmed during a follow up conversation requested borings locations be placed around various former USTs, near a GPR anomoly and in the central asphalt lot. Soil analyticals showed no CP51 SCO exceedences and groundwater analyticals showed 57ppb napthalene(SW5). Report concludes that additional investigation is not warranted. Vought spoke to DEC Ahmed who forwarded email for 12/21/09 report however due to large file size, a separate CD would have to be sent from Arcadis. Former 1000 Gallon Underground Storage Tank (UST) Investigation (Arcadis)-4/25/12. Seven soil borings installed around 1000-gallon gasoline UST including collection of seven groundwater samples. No soil samples were above Part 375 Unrestricted SCOs excluding elevated PAHs which can be attributed to fill material. Groundwater samples also showed no TOGs exceedences. 9/17/12-Vought-Called and left message for Arcadis (Zimmerman) to send in Groundwater Investigation Report dated 10/23/09 via CD and Tank Closure Report for spill 9808077. Vought reviewed abbreviated Phase II Groundwater Investigation Report received from email from DEC Ahmed. Vought added Abbreviated Phase II to e-docs. Additional groundwater samples collected in August 2009 around the existing and former USTs. Cover Letter dated 12/21/09 for Report notes that either Newtown Creek or historic fill is source of dissolved phase benzene observed in site groundwater . Seven borings installed via Geoprobe and four of these were installed to assess downgradient locations of potential sources areas . Maximum concentrations of 17ppb benzene were noted. Report notes that there is not ample background information available at this time to determine potential sources . 9/18/12-Vought-Called Deric Kearns and left message to return call and that DEC needed copy of 1998 Tank Closure Report. Vought also sent email to Kearns with DEC requirements including submission of USTs and piping on site plans for both PBS Registrations, Submission

YRC BROOKLYN (187) (Continued) **1004756458**

of Tank Closure Report for closed spill 9808077 or possible investigation around USTs and piping as no leak detection and no tightness testing data in PBS Registration, closure of open spill 104888 at same site and referral to open spill 1103727, Submission of complete Groundwater Investigation Report dated 12/21/09. Vought received email from Kearns that We received your email and voicemail messages, thanks for laying these items out for us. We have begun to review our historic files and are actively trying to track down these items. I will contact you directly if we have any questions. 12/12/12-Vought-Received call from contact (Claudio) who is working for potential purchaser (Tony Argento) who is wishing to purchase property for use of production films. Contact for Claudio is Ph:917-939-8034 email:claudio@broadway-stages.com). Vought forwarded 9/18/12 email string to Kearns to Claudio with cc to Kearns. 2/12/13-Vought-Received call from and spoke to Ruben Byerley (YRC Freight Ph:913-344-3644 email:ruben.byerley@yrcfreight.com) and he is manager of environmental services for the corporate owner and operator. He was requesting file review and Vought told him to return call to Vought in one week for update. 2/20/13-Vought-File review by Vought. Vought received two CDs dated 12/13/12 that contained the following files: APEX UST Closure Report(9/20/99) ARCADIS Subsurface Investigation (4/25/12)-reviewed by Vought above ARCADIS UST Investigation and Closure Report(4/25/12)-reviewed by Vought above ARCADIS Groundwater Investigation(10/23/99) ATC Phase I ESA (4/27/09) ATC Phase II ESA (4/27/09) Misc. Documents Relating to Former 3000-Gallon UST (1988) Document Review by Vought of above documents: Misc. Documents Relating to Former 3000-Gallon UST-1988. Proposal to replace 1000-gallon heating oil tank with all associated piping into the garage furnace and fill and abandon second tank near office with concrete slurry. Contamination was minimal because leak was caught almost immediately . 1000-gallon UST was replaced and 3000-gallon UST by office was filled with concrete. UST Closure Report (APEX Environmental)-9/20/99. One 2000-gallon, two (4000-gallon) and one 500 gallon UST were removed on 9/29/98. Diesel fuel used for refueling tractor trailers. English Kills/Maspeth Creek to the north and east and commercial properties to the south and west of site. Facility has two story office building with a large connecting loading dock. Product dispenser was dismantled and product was removed from the USTs. Tanks were reported to be in good condition with minor pitting and no holes. Soil excavation at diesel USTs was 28’x36’x10’deep and seven endpoint samples collected. Used motor oil UST excavation in garage was 12’x6’ and five endpoint samples were collected. 171 tons of soil were removed from the site. Soil endpoint analyticals for alll three tanks were non-detect for VOCs. Report recommends No Further Action. Phase I Environmental Site Assesssment (ATC)-4/27/09. Report notes that YRC Logistics is at site and report prepared for NATMI Trucking Terminals, LLC. Property was occupied by a saw mill and lumber yard before trucking terminal and maintenance facility was built onsite in 1959. Fill port and vent pipe noted adjacent to western exterior wall of the property’s office building. Scrap metal facility is potentially upgradient of site. Report recommends performance of a Phase II investigation. Property currently used as a cross-dock truck terminal by YRC Logistics and a truck maintenance facility is on the northern portion of the property. Phase II Environmental Site Assessment (ATC)-4/27/09. Phase II included a GPR survey and subsuface investigation. GPR found a 6-foot by 6-foot anamoly approximately two feet below grade in the

YRC BROOKLYN (187) (Continued) **1004756458**

area of the observed fill port and vent pipe on the southwestern portion of the property . Five Geoprobe borings installed to a maximum depth of 15'bg. Groundwater at 15'bg. Peat found at 6-10'bg in some borings and groundwater is from 5-8'bg. No petroleum related VOCs in soil and groundwater samples noted 43ppb benzene in sample B1. ATC recommends additional investigation to see if GPR anamoly is a UST and installation of monitoring wells to delineate bezene contamination in groundwater. Groundwater Investigation Report (ARCADIS)-10/23/09. Additional investigation by ARCADIS upon review of Phase II by ATC dated 4/27/09. Metals and PAHs in soils were indicative of historic fills and were not observed in groundwater. Purpose of investigation was to confirm 43pp benzene in B1 groundwater sample in ATC Phase II. Seven borings installed via Geoprobe. Groundwater analyticals show: 1.6ppb benzene (TW5) and 17ppb benzene(TW7). Groundwater samples analyzed for 8260/8270 analyses. Groundwater sample collected at B1 of ATC Phase II was non-detect for benzene. Possible sources of benzene include historic fill materials beneath the site and the close proximity of the sample locations to the heavily polluted Newtown Creek . Report recommends submission to DEC. 2/22/13-Vought-After completion of file review by Vought, spill closed due to minor benzene only detections in groundwater possibly attributable to historic fill and or contaminant contribution fron adjacent Newtown Creek or English Kills. Area also heavy industrialized for past 100 years. Groundwater benzene concentrations are within natural attenuation parameters and likley oxidizing conditions in soil necessary for promotion of aerobic degradation. Vought called YRC Byerly for address of spill closure letter for this spill and Spill 1004888 for same site and 1000-gallon UST TTF (removal discussed above). Received email from YRC Byerly that mailing address for Spill Closure Letter is: YRC Freight Attn: Ruben Byerley (MS-A650) 10990 Roe Ave. Overland Park, KS 66211 Vought sent out Closure Letter to Byerly via mail and email with cc to ARCADIS Kearns. "

Remarks: ""

All Materials:

Site ID:	422759
Operable Unit ID:	1178587
Operable Unit:	01
Material ID:	2172057
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	YELLOW ROADWAY CORP
Address:	1313 GRAND ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1103727 / 2011-11-30
Facility ID:	1103727
Facility Type:	ER
DER Facility ID:	143819
Site ID:	451299

YRC BROOKLYN (187) (Continued) **1004756458**

DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2011-03-01
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2011-07-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-07-05
Spill Record Last Update:	2011-11-30
Spiller Name:	Not reported
Spiller Company:	YELLOW ROADWAY CORP
Spiller Address:	1313 GRAND ST
Spiller Company:	999
Contact Name:	CHRIS MCDONALD
DEC Memo:	"Mike from Reliance. Tank was taken out. 11/30/11- DECPiper reviewd tank closure rpeort. Low level VOC below 6NYCRR Table 375-6.8(a)unrestricted use was detected. SVOC's slightly above most likely related to fill material in area. Based on work to date, this spill is closed. See edocs if warranted. "
Remarks:	"soil contamination found during tank removal, clean up pending"

All Materials:

Site ID:	451299
Operable Unit ID:	1201497
Operable Unit:	01
Material ID:	2198023
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	TRUCK FACITLITY
Address:	1313 GRAND STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1207926 / 2015-10-02
Facility ID:	1207926
Facility Type:	ER
DER Facility ID:	423271
Site ID:	470986
DEC Region:	2
Spill Cause:	Storm
Spill Class:	D4

YRC BROOKLYN (187) (Continued) **1004756458**

SWIS:	2401
Spill Date:	2012-10-31
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2012-10-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-10-31
Spill Record Last Update:	2015-10-02
Spiller Name:	Not reported
Spiller Company:	HURRICANE SANDY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	PHILIP STARK
DEC Memo:	"contractor on site. under control. will send info when completed to DEC Piper. yrc worldwide - overland park, KS - 913-344-5205 left message requesting info. 10/2/15- DEC Piper received closure documentation. Based on work to date, this spill is closed. See Dec docs for report. "
Remarks:	"LEAKED SURING STORM. CLEAN UP WITH BE DONE BY HEPECO"

All Materials:

Site ID:	470986
Operable Unit ID:	1220845
Operable Unit:	01
Material ID:	2219471
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

FINDS:

Registry ID: 110004375872

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits

YRC BROOKLYN (187) (Continued) **1004756458**

issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004756458
Registry ID:	110004375872
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004375872
Name:	YRC BROOKLYN (187)
Address:	1313 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211

NY MANIFEST:

Name:	ROADWAY EXPRESS INC
Address:	1313 GRAND ST
City,State,Zip:	BROOKLYN, NY 11211
Country:	USA
EPA ID:	NYD095769782
Facility Status:	Not reported
Location Address 1:	1313 GRAND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11211
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD095769782
Mailing Name:	ROADWAY EXPRESS INC
Mailing Contact:	ROADWAY EXPRESS INC
Mailing Address 1:	1313 GRAND STREET
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11211
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7188215410

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported

YRC BROOKLYN (187) (Continued) **1004756458**

Generator Ship Date:	11/28/2007
Trans1 Recv Date:	11/28/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/04/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD095769782
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD982270506
TSDF ID 2:	Not reported
Manifest Tracking Number:	000092800SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	14
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	D039
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

SPDES:

Name:	YRC INC DBA YRC FREIGHT INC (187)
Address:	1313 GRAND AVE
City,State,Zip:	BROOKLYN, BOROUGH OF, NY 11211
Permit Number:	NYR00D143
State-Region:	02
Expiration Date:	09/30/2017
Current Major Minor Status:	Minor
Primary Facility SIC Code:	4213
State Water Body Name:	ENGLISH KILLS TO NEWTON CREEK
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported

YRC BROOKLYN (187) (Continued) **1004756458**

UDF1:	Not reported
Lat/Long:	40.717 / -73.924
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	YRC INC
Non-Gov Permit Street Address:	YRC INC DBA YRC FREIGHT INC (187)
Non-Gov Permit Supplemental Location:	10990 ROE AVE MS A650
Non-Gov Permit City:	OVERLAND PARK
Non-Gov Permit State Code:	KS
Non-Gov Permit Zip Code:	66211
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	YRC INC
Non-Gov Facility Street Address:	YRC INC DBA YRC FREIGHT INC (187)
Non-Gov Facility Supplemental Location:	10990 ROE AVE MS A650
Non-Gov Facility City:	OVERLAND PARK
Non-Gov Facility State Code:	KS
Non-Gov Facility Zip Code:	66211
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	YRC INC DBA YRC FREIGHT INC (187)
Address:	1313 GRAND AVE
City,State,Zip:	BROOKLYN, BOROUGH OF, NY 11211
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	YRC INC
Non-Gov Permit Street Address:	10990 ROE AVE MS A650
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	OVERLAND PARK
Non-Gov Permit State Code:	KS
Non-Gov Permit Zip Code:	66211
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	YRC INC
Non-Gov Facility Street Address:	YRC INC DBA YRC FREIGHT INC (187)
Non-Gov Facility Supplemental Location:	10990 ROE AVE MS A650
Non-Gov Facility City:	OVERLAND PARK
Non-Gov Facility State Code:	KS
Non-Gov Facility Zip Code:	66211
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported

YRC BROOKLYN (187) (Continued) **1004756458**

Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	YRC INC DBA YRC FREIGHT INC (187)
Address:	1313 GRAND AVE
City,State,Zip:	BROOKLYN, BOROUGH OF, NY 11211
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Stormwater SWPPP Location
Non-Gov Permit Org Formal Name:	YRC INC
Non-Gov Permit Street Address:	YRC INC DBA YRC FREIGHT INC (187)
Non-Gov Permit Supplemental Location:	557 EAST TALLMADGE AVE
Non-Gov Permit City:	AKRON
Non-Gov Permit State Code:	OH
Non-Gov Permit Zip Code:	44310
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	YRC INC
Non-Gov Facility Street Address:	YRC INC DBA YRC FREIGHT INC (187)
Non-Gov Facility Supplemental Location:	10990 ROE AVE MS A650
Non-Gov Facility City:	OVERLAND PARK
Non-Gov Facility State Code:	KS
Non-Gov Facility Zip Code:	66211
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	YRC INC DBA YRC FREIGHT INC (187)
Address:	1313 GRAND AVE
City,State,Zip:	BROOKLYN, BOROUGH OF, NY 11211
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	YRC INC
Non-Gov Facility Street Address:	YRC INC DBA YRC FREIGHT INC (187)
Non-Gov Facility Supplemental Location:	10990 ROE AVE MS A650
Non-Gov Facility City:	OVERLAND PARK
Non-Gov Facility State Code:	KS
Non-Gov Facility Zip Code:	66211

YRC BROOKLYN (187) (Continued) **1004756458**

State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

AA187 **NEO RAY LIGHTING PRODUCTS** **RCRA-VSQG** **1000139537**
SSE **537 JOHNSON AVENUE** **NY LTANKS** **NYD001502509**
1/4-1/2 **BROOKLYN, NY 11237** **NY UST**
0.283 mi. **ICIS**
1494 ft. **Site 3 of 3 in cluster AA** **US AIRS**
FINDS
Relative: Higher **ECHO**
NY MANIFEST
Actual: 14 ft.

RCRA-VSQG:

Date Form Received by Agency:	20070101
Handler Name:	NEO-RAY PRODUCTIONS INC
Handler Address:	537 JOHNSON AVE
Handler City,State,Zip:	BROOKLYN, NY 11237
EPA ID:	NYD001502509
Contact Name:	BOB BLUMEN
Contact Address:	JOHNSON AVE
Contact City,State,Zip:	BROOKLYN, NY 11237
Contact Telephone:	718-456-7400
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	JOHNSON AVE
Mailing City,State,Zip:	BROOKLYN, NY 11237
Owner Name:	CORPORATION NEO-RAY PRODUCTIONS
Owner Type:	Private
Operator Name:	CORPORATION NEO-RAY PRODUCTIONS
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CORPORATION NEO-RAY PRODUCTIONS
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CORPORATION NEO-RAY PRODUCTIONS
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CORPORATION NEO-RAY PRODUCTIONS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CORPORATION NEO-RAY PRODUCTIONS
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990714
Handler Name: NEO-RAY PRODUCTIONS INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20050722
Handler Name: NEO-RAY PRODUCTIONS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NEO-RAY PRODUCTIONS INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NEO-RAY PRODUCTIONS INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20000811
Handler Name: NEO-RAY PRODUCTIONS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: NEO-RAY LIGHTING
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 335129
NAICS Description: OTHER LIGHTING EQUIPMENT MANUFACTURING

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19901024
Actual Return to Compliance Date:	19910208
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19910115
Enforcement Identifier:	001
Date of Enforcement Action:	19901130
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20031007
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYYWG
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19901024
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19910208
Scheduled Compliance Date: 19910115
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20070906
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYSAN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

LTANKS:

Name:	537 JOHNSON AV
Address:	537 JOHNSON AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8806105 / 1992-10-07
Facility ID:	8806105
Site ID:	155588
Spill Date:	1988-10-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-10-07
SWIS:	2401
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1988-10-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-10-31
Spill Record Last Update:	2003-10-08
Spiller Name:	Not reported
Spiller Company:	NEO RAY LIGHTING
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	131784
DEC Memo:	""
Remarks:	"2K TK SYSTEM FAILED PETRO-TITE, L R = -1.284 GPH."

All TTF:

Facility ID:	8806105
Spill Number:	8806105
Spill Tank Test:	1534783
Site ID:	155588
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 155588
Operable Unit ID: 922935
Operable Unit: 01
Material ID: 454460
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: Not reported

UST:
Name: NEO-RAY PRODUCTS INC
Address: 537 JOHNSON AVE
City,State,Zip: BROOKLYN, NY 11237
Id/Status: 2-085308 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 590763.85405
UTM Y: 4507004.06136
Site Type: Other

Affiliation Records:
Site Id: 2037
Affiliation Type: Facility Owner
Company Name: MITCHELL CONN
Contact Type: Not reported
Contact Name: Not reported
Address1: 537 JOHNSON AVENUE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11237
Country Code: 001
Phone: (718) 456-7400
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 2037
Affiliation Type: Mail Contact
Company Name: NEO-DAY PRODUCTS
Contact Type: Not reported
Contact Name: Not reported
Address1: 537 JOHNSON AVENUE

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Address2:	537 JOHNSON AVENUE
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 456-7400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2037
Affiliation Type:	Facility Operator
Company Name:	NEO-RAY PRODUCTS INC
Contact Type:	Not reported
Contact Name:	NEO-RAY PRODUCTS INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 456-7400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2037
Affiliation Type:	Emergency Contact
Company Name:	MITCHELL CONN
Contact Type:	Not reported
Contact Name:	ANGELO ROSARIO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 456-7400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	00A
Tank ID:	3297
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	04/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 03
Date Test: 06/01/1998
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None

Tank Number: 00B
Tank ID: 3298
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: ZZ
Date Test: 03/01/1999
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 00C
Tank ID: 3299
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Capacity Gallons:	1080
Install Date:	Not reported
Date Tank Closed:	08/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	03
Date Test:	03/01/1999
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	00D
Tank ID:	3300
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1750
Install Date:	Not reported
Date Tank Closed:	04/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	03
Date Test:	03/01/1999
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

ICIS:

Enforcement Action ID:	NY000A0000261040002300006
FRS ID:	110012589822
Action Name:	ATLITE INC 360470081400006
Facility Name:	ATLITE INC
Facility Address:	537 JOHNSON AVE BROOKLYN, NY 11237
Enforcement Action Type:	Administrative Order
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	SCAAAO
Facility SIC Code:	3471
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.70893
Longitude in Decimal Degrees:	-73.925
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610400023
Facility NAICS Code:	332813
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000261040002300004
FRS ID:	110012589822
Action Name:	ATLITE INC 360470081400004
Facility Name:	ATLITE INC
Facility Address:	537 JOHNSON AVE BROOKLYN, NY 11237
Enforcement Action Type:	Administrative Order
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	SCAAAO
Facility SIC Code:	3471
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.70893
Longitude in Decimal Degrees:	-73.925
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002610400023
Facility NAICS Code:	332813
Tribal Land Code:	Not reported

Enforcement Action ID:	HQ-100018946
FRS ID:	110012589822
Action Name:	Neo-Ray Products Inc.
Facility Name:	NEO RAY LIGHTING PRODUCTS
Facility Address:	537 JOHNSON AVENUE BROOKLYN, NY 11237
Enforcement Action Type:	Notice of Noncompliance Issued
Facility County:	KINGS
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NONC
Facility SIC Code:	3646
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.708807
Longitude in Decimal Degrees:	-73.925748
Permit Type Desc:	Not reported

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Program System Acronym: 23483
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-1988-0136
FRS ID: 110012589822
Action Name: NEO-RAY LIGHTING SYSTEMS INC
Facility Name: NEO RAY LIGHTING PRODUCTS
Facility Address: 537 JOHNSON AVENUE
BROOKLYN, NY 11237
Enforcement Action Type: CAA 113 Notice Of Violation
Facility County: KINGS
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 113
Facility SIC Code: 3646
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.708807
Longitude in Decimal Degrees: -73.925748
Permit Type Desc: Not reported
Program System Acronym: 23483
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 02-000F000360470081400002
FRS ID: 110012589822
Action Name: ATLITE INC 360470081400002
Facility Name: ATLITE INC
Facility Address: 537 JOHNSON AVE
BROOKLYN, NY 11237
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 3471
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.70893
Longitude in Decimal Degrees: -73.925
Permit Type Desc: Not reported
Program System Acronym: NY0000002610400023
Facility NAICS Code: 332813
Tribal Land Code: Not reported

Facility Name: NEO-RAY PRODUCTS INC
Address: 537 JOHNSON AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3646

Facility Name: NEO-RAY PRODUCTS INC
Address: 537 JOHNSON AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

SIC Code: 3646

Facility Name: NEO-RAY PRODUCTS INC
Address: 537 JOHNSON AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3646

Facility Name: NEO-RAY PRODUCTS INC
Address: 537 JOHNSON AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3646

Facility Name: NEO-RAY PRODUCTS INC
Address: 537 JOHNSON AVE
Tribal Indicator: N
Fed Facility: No
NAIC Code: Not reported
SIC Code: 3646

US AIRS (AFS):
Envid: 1000139537
Region Code: 02
County Code: NY047
Programmatic ID: AIR NY0000002610400023
Facility Registry ID: 110012589822
D and B Number: Not reported
Facility Site Name: ATLITE INC
Primary SIC Code: 3471
NAICS Code: 332813
Default Air Classification Code: SMI
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS (AFS):
Region Code: 02
Programmatic ID: AIR NY0000002610400023
Facility Registry ID: 110012589822
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-06-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400023
Facility Registry ID: 110012589822
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Activity Date: 1985-08-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400023
Facility Registry ID: 110012589822
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1987-03-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400023
Facility Registry ID: 110012589822
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1987-12-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400023
Facility Registry ID: 110012589822
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-05-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400023
Facility Registry ID: 110012589822
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-05-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400023
Facility Registry ID: 110012589822

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1991-06-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400023
Facility Registry ID: 110012589822
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1992-01-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400023
Facility Registry ID: 110012589822
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1992-12-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400023
Facility Registry ID: 110012589822
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-08-15 00:00:00
Activity Status Date: 1985-08-15 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 02
Programmatic ID: AIR NY0000002610400023
Facility Registry ID: 110012589822
Air Operating Status Code: OPR
Default Air Classification Code: SMI
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-09-04 00:00:00
Activity Status Date: 1985-09-04 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

Region Code:	02
Programmatic ID:	AIR NY0000002610400023
Facility Registry ID:	110012589822
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1985-07-22 00:00:00
Activity Status Date:	1985-07-22 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

FINDS:
Registry ID: 110012589822

Click Here:

Environmental Interest/Information System:
NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
AIR SYNTHETIC MINOR
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and

NEO RAY LIGHTING PRODUCTS (Continued) **1000139537**

it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000139537
Registry ID:	110012589822
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110012589822
Name:	ATLITE INC
Address:	537 JOHNSON AVE
City,State,Zip:	BROOKLYN, NY 11237

NY MANIFEST:

Name:	NEO RAY
Address:	537 JOHNSON AVENUE
City,State,Zip:	BROOKLYN, NY 11237-0000
Country:	USA
EPA ID:	NYD001502509
Facility Status:	Not reported
Location Address 1:	537 JOHNSON AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	RIDGEWOOD
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD001502509
Mailing Name:	NEO RAY
Mailing Contact:	NEO RAY
Mailing Address 1:	100 ANDREWS RD
Mailing Address 2:	Not reported
Mailing City:	SCHENECTADY
Mailing State:	NY
Mailing Zip:	12307
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184567400

AD188 **140 MORGAN AVE/BROOKLYN** **NY LTANKS S102145602**
SW **140 MORGAN AVENUE** **NY Spills N/A**
1/4-1/2 **BROOKLYN, NY**
0.308 mi.
1627 ft. **Site 1 of 2 in cluster AD**

Relative:
Lower

Actual:
13 ft.

LTANKS:

Name:	140 MORGAN AVE/BROOKLYN
Address:	140 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY

140 MORGAN AVE/BROOKLYN (Continued) **S102145602**

Spill Number/Closed Date:	8910515 / 1990-02-03
Facility ID:	8910515
Site ID:	113471
Spill Date:	1990-01-30
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1990-02-03
SWIS:	2401
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1990-02-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-02-07
Spill Record Last Update:	2003-04-09
Spiller Name:	Not reported
Spiller Company:	PETRO HEAT & POWER
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	99025
DEC Memo:	""
Remarks:	"CUSTOMER OVER ORDERED & FUEL GAUGE WAS BROKEN, CLEANED UP BY PETRO HEAT & POWER SPILL TEAM."

All Materials:

Site ID:	113471
Operable Unit ID:	937444
Operable Unit:	01
Material ID:	443617
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	GORDON INTERNATIONAL/BKLN
Address:	140 MORGAN AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8909334 / 1989-12-26
Facility ID:	8909334
Facility Type:	ER

140 MORGAN AVE/BROOKLYN (Continued) **S102145602**

DER Facility ID:	99025
Site ID:	169713
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	1989-12-23
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1989-12-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1989-12-26
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-01-03
Spill Record Last Update:	1990-02-14
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"SATURDAY ROUTINE DELIVERY MADE - CUSTOMER REPORTED SPILL ON ASPHALT. PETRO TEAM RESPONDED - TYREE BROS CALLED TO CLEAN"

All Materials:

Site ID:	169713
Operable Unit ID:	934266
Operable Unit:	01
Material ID:	442499
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AC189 **JOYVA VACANT LOT** **NY VCP** **S113922066**
South **498 JOHNSON AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11237**
0.309 mi.
1630 ft. **Site 2 of 2 in cluster AC**

Relative: VCP:
Lower

Name:	JOYVA VACANT LOT
Address:	498 JOHNSON AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Program Type:	VCP
Site Code:	56948

Actual:
13 ft.

JOYVA VACANT LOT (Continued) **S113922066**

HW Code:	V00332
Site Class:	N
SWIS:	2401
Region:	2
Town:	New York City
Acres:	Not reported
Date Record Added:	11/30/2000
Date Record Updated:	07/14/2004
Updated By:	VCPTRANS
Site Description:	"The site did not qualify for addition to the Registry of Inactive Hazardous Disposal Sites"
Env Problem:	""
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	Joyva Corporation
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AE190 **BROWNING FERRIS** **NY SWF/LF** **S102639161**
ESE **72 SCOTT AVE** **NY LTANKS** **N/A**
1/4-1/2 **BROOKLYN, NY 11237** **NY CBS**
0.310 mi. **NY AST**
1637 ft. **Site 1 of 3 in cluster AE** **NY CBS AST**
NY SWRCY
Relative: **NY Spills**
Higher **NY MANIFEST**
NY SPDES
Actual:
15 ft.

SWF/LF:

Name:	BFI - ALLIED (WM - STEEL LOS)
Address:	72 SCOTT AVE
City,State,Zip:	BROOKLYN, NY 11237

BROWNING FERRIS (Continued) **S102639161**

Flag:	INACTIVE
Region Code:	2
Phone Number:	7184974000
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	RUSS KRUK
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[24T99]
Active:	No
East Coordinate:	590900
North Coordinate:	4507300
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	2-6101-00120
Authorization Date:	1/7/1991
Expiration Date:	1/31/2002
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

LTANKS:

Name:	BROWNING FERRIS INDUSTRIA
Address:	72 SCOTT AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9703477 / 1997-06-25
Facility ID:	9703477
Site ID:	144360
Spill Date:	1997-06-20
Spill Cause:	Tank Failure
Spill Source:	Commercial Vehicle
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1997-06-20
CID:	312
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-06-20
Spill Record Last Update:	1997-06-26

BROWNING FERRIS (Continued) **S102639161**

Spiller Name:	Not reported
Spiller Company:	TRUCK-LOAD EXPRESS
Spiller Address:	901 KCK WAY
Spiller County:	001
Spiller Contact:	TIM HORKAY
Spiller Phone:	(718) 497-1282
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	166356
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"PRIVATE HAULER HAD A RUPTURED FUEL TANK IN THE YARD OF BFI - CLEANED UP"

All Materials:

Site ID:	144360
Operable Unit ID:	1049436
Operable Unit:	01
Material ID:	336359
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	25.00
Oxygenate:	Not reported

Name:	72 SCOTT AVE
Address:	72 SCOTT AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9708693 / 2004-10-20
Facility ID:	9708693
Site ID:	144361
Spill Date:	1997-10-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	1997-10-24
CID:	322
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-24
Spill Record Last Update:	2004-10-20
Spiller Name:	TYREE
Spiller Company:	BFI - 72 SCOTT
Spiller Address:	72 SCOTT AVE
Spiller County:	001

BROWNING FERRIS (Continued) **S102639161**

Spiller Contact: TYREE - GINA
Spiller Phone: (516) 249-3150
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 166356
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 3/11/03 - SAMUEL- File available in active unassigned spill files. 8/18/2004 Consultant called to say there is a DEC Consent Order on this site which covers the tank. Tank was closed in place. Sangesland requested copies of soil boring/testing done under the tank to prove it is clean. When this information is submitted, DEC will closed the case out. 9/14/2004 Consultant called to say they can not find any historical soil boring work, so they have contracted with Impact Environmental to do new soil borings around the tank and sample them to EPA Method 8260. 10/14/2004 Sangesland reviewed a submittal from Maureen Frazier of Schillinger Environmental. They have hired Impact Environmental to do soil borings. A report should be submitted to DEC by 10/29/2004. 10/20/2004 Impact Environmental called in a new spill on the site. Found Diesel contaminated Soil Ref Spill #0408008 Both of these spills 0408008 and 9708693 have been closed and referred back to the original spill # 9702085 -"
Remarks: ""

All TTF:
Facility ID: 9708693
Spill Number: 9708693
Spill Tank Test: 1545422
Site ID: 144361
Tank Number: 1
Tank Size: 4000
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 20
Test Method 2: USTest 2000/P/LL plus USTest 2000/U
Leak Rate: .00
Gross Fail: F
Modified By: Spills
Last Modified Date: Not reported

CBS:
Name: BROOKLYN STEEL & TUBE CORPORATION
Address: 72 SCOTT AVENUE
City,State,Zip: BROOKLYN, NY 11237
CBS Number: 2-000150
Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: 591001.83018
UTMY: 4507116.31529

AST:
Name: BROOKLYN STEEL & TUBE CORPORATION

BROWNING FERRIS (Continued) **S102639161**

Address:	72 SCOTT AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000150
Program Type:	CBS
UTM X:	591001.83018
UTM Y:	4507116.31529
Expiration Date:	N/A
Site Type:	Manufacturing (Other than Chemical)/Processing

Tank Info:

Tank Number:	1
Tank Id:	187695
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/1952
Capacity Gallons:	15000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/01/1990
Register:	True
Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

CBS AST:

CBS Number:	2-000150
ICS Number:	2-125074
PBS Number:	Not reported
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	IN SERVICE
Facility Type:	D
Telephone:	(718) 497-2100
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	07/19/1991
Total Capacity of All Active Tanks(gal):	0
Operator:	R.M. HANNA
Emergency Contact:	R.F. FINLEY
Emergency Phone:	(718) 497-2100
Owner Name:	BROOKLYN STEEL & TUBE CORPORATION
Owner Address:	72-88 SCOTT AVE.
Owner City,St,Zip:	BROOKLYN, NY 11237
Owner Telephone:	(718) 497-2100
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	BROOKLYN STEEL & TUBE CORPORATION
Mail Contact Addr:	72-88 SCOTT AVE.
Mail Contact Addr2:	Not reported

BROWNING FERRIS (Continued) **S102639161**

Mail Contact Contact:	R.F. FINLEY
Mail Contact City,St,Zip:	BROOKLYN, NY 11237
Mail Phone:	(718) 497-2100
Tank Id:	1
CAS Number:	7664939
Federal ID:	Not reported
Tank Status:	Not reported
Install Date:	04/52
Tank Closed:	11/90
Capacity (Gal):	15000
Chemical:	Sulfuric acid
Tank Location:	Indoors, Belowground
Tank Type:	Steel/carbon steel
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	3
Date Entered:	07/19/1989
Certified Date:	07/19/1989
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Wrapped Steel
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	03/15/91
Is It There:	False
Delinquent:	False
Date Expired:	07/19/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	03/15/1991

SWRCY:

Name:	BFI - ALLIED (WM - STEEL LOS)
Address:	72 SCOTT AVE
City,State,Zip:	BROOKLYN, NY 11237
Region:	2
Facility Address 2:	Not reported
Phone Number:	7184974000
Owner Type:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner Address 2:	Not reported

BROWNING FERRIS (Continued) **S102639161**

Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	RUSS KRUK
Contact Address:	Not reported
Contact Address 2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	RHRF - registration
Activity Number:	[24M99]
Active:	No
East Coordinate:	590900
North Coordinate:	4507300
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Permit #:	2-6101-00120
Auth. Date:	1/7/1991
Expiration Date:	1/31/2002
Waste Types:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Last Date:	Not reported

Name:	J.L.J. RECYCLING CONTRACTORS CORP.
Address:	72 SCOTT AVENUE
City,State,Zip:	BROOKLYN, NY 0
Region:	2
Facility Address 2:	Not reported
Phone Number:	7184974000
Owner Type:	Not reported
Owner Name:	Joseph Lostritto
Owner Address:	72 Scott Ave.
Owner Address 2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11237
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Address 2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	RHRF - registration
Activity Number:	[00M00]
Active:	No
East Coordinate:	Not reported
North Coordinate:	Not reported
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Permit #:	2-6104-00022/00001-0
Auth. Date:	Not reported
Expiration Date:	Not reported
Waste Types:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Last Date:	Not reported

BROWNING FERRIS (Continued) **S102639161**

SPILLS:

Name:	BFI
Address:	72 SCOTT ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0408008 / 2004-10-20
Facility ID:	0408008
Facility Type:	ER
DER Facility ID:	267814
Site ID:	332606
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	2401
Spill Date:	2004-10-19
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2004-10-19
CID:	407
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-19
Spill Record Last Update:	2004-10-20
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	TOM FALATO
DEC Memo:	"This spill has been consolidated with an older open spill report: Both spill #0408008 and spill #9708693 have been closed and referred to #9702085"
Remarks:	"Detected contamination in the soil."

All Materials:

Site ID:	332606
Operable Unit ID:	1094837
Operable Unit:	01
Material ID:	574970
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BROWNING FERRIS INDUST
Address:	72 SCOTT AVENUE
City,State,Zip:	BROOKLYN, NY

BROWNING FERRIS (Continued) **S102639161**

Spill Number/Closed Date:	9703275 / 1997-06-16
Facility ID:	9703275
Facility Type:	ER
DER Facility ID:	166356
Site ID:	144359
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	1997-06-13
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	1997-06-16
CID:	252
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-06-16
Spill Record Last Update:	1997-06-18
Spiller Name:	TIM HORKAY
Spiller Company:	BROWNING FERRIS INDUST
Spiller Address:	72 SCOTT AVE
Spiller Company:	001
Contact Name:	TIM HORKAY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD "
Remarks:	"SPILL WAS CAUSED BY HYDRAULIC HOSE COMING LOOSE-SPILL HAS BEEN CLEANED UP"

All Materials:

Site ID:	144359
Operable Unit ID:	1049274
Operable Unit:	01
Material ID:	336171
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

Name:	BFI
Address:	72 SCOTT AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9702085 / 2004-12-03
Facility ID:	9702085
Facility Type:	ER
DER Facility ID:	166356
Site ID:	144358

BROWNING FERRIS (Continued) **S102639161**

DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	2401
Spill Date:	1997-05-18
Investigator:	JMROMMEL
Referred To:	Not reported
Reported to Dept:	1997-05-18
CID:	370
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-18
Spill Record Last Update:	2004-12-08
Spiller Name:	DAVID MCLAUGHLIN
Spiller Company:	BFI
Spiller Address:	136 SICKER RD
Spiller Company:	001
Contact Name:	TIM HORKAY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 3/11/03 - SAMUEL- File available in active unassigned spill files. 4/12/04-Vought-Spill transferred from Tomasello to Rommel as per Rommel. 10/20/2004 Sangesland has consolidated 3 spills into one: Spill 9708693 - has been closed and cross ref to this spill #9702085 Spill 0408008 - new soil boring contamination - closed & ref to 9702085 12/3/04 Reviewed Impact Enmtl report dated October 2004. NFA letter mailed to BFI Rommel"
Remarks:	"caller removing a tank and found soil spill contained in soil will also excavate soil and remove"

All Materials:

Site ID:	144358
Operable Unit ID:	1044796
Operable Unit:	01
Material ID:	335019
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	PARKING GARAGE
Address:	72 SCOTT AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0609017 / 2006-11-07
Facility ID:	0609017
Facility Type:	ER
DER Facility ID:	166356

BROWNING FERRIS (Continued) **S102639161**

Site ID:	373114
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2006-11-06
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2006-11-06
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-11-06
Spill Record Last Update:	2006-11-07
Spiller Name:	DERRICK BEAUREGAURD
Spiller Company:	TRUCK #1618
Spiller Address:	1160 RANDALL AVE
Spiller Company:	001
Contact Name:	SAM RIVERA
DEC Memo:	"11/07/06-Hiralkumar Patel. received during off hours duty. spoke with Derrick. as per Derrick, there was only diesel spill, not #2 oil spill. it was actually 2 grade diesel. spill happened due to ruptured saddle tank. spilled on concrete parking lot and it all contained. Castleton was on scene. spill cleaned up by absorbent pads. no soil/sewer/drain affected. all cleaned up. spoke with jake at castleton. all cleaned up."
Remarks:	"THE AMOUNT IS 1/2 AND 1/2 OF EACH MATERIAL; TRUCK IS A FUEL TANKER AND WAS CARRYING 2000 GALLONS; SENT EMERGENCY SPILL REPONSE CASTLETON ENVIRO. SPOKE WITH JAKE # 973-332-4972; HAS BEEN CONTAINED; WILL BE CLEANED BY CASTLETON ENVIRO. ;"

All Materials:

Site ID:	373114
Operable Unit ID:	1130837
Operable Unit:	01
Material ID:	2120510
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	373114
Operable Unit ID:	1130837
Operable Unit:	01
Material ID:	2120511
Material Code:	0008
Material Name:	diesel

BROWNING FERRIS (Continued) **S102639161**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BROWNING FERRIS INDUSTRIE
Address:	72 SCOTT AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9709681 / 1997-11-20
Facility ID:	9709681
Facility Type:	ER
DER Facility ID:	166356
Site ID:	199905
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	1997-11-20
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1997-11-20
CID:	266
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-11-20
Spill Record Last Update:	1997-11-21
Spiller Name:	JIM VAN WOERT
Spiller Company:	BROWNING FERRIS INDUSTRIE
Spiller Address:	72 SCOTT AVENUE
Spiller Company:	001
Contact Name:	JIM VAN WOERT
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG CALLED UP JIM VAN @ BROWNING FERRIS & CONFIRMED CLEAN-UP. NO IMPACT TO FLOOR DRAINS ON SIDEWALKS."
Remarks:	"BROKEN HYDRAULIC LINE ON ROLL-OFF TRUCK. ONTO CONCRETE AND ASPHALT. CLEANED UP."

All Materials:

Site ID:	199905
Operable Unit ID:	1056009
Operable Unit:	01
Material ID:	328016
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G

BROWNING FERRIS (Continued) **S102639161**

Recovered: 40.00
Oxygenate: Not reported

NY MANIFEST:
Name: BROWNING FERRIS
Address: 72 SCOTT AVE
City,State,Zip: BROOKLYN, NY 11237-0000
Country: USA
EPA ID: NYR000064568
Facility Status: Not reported
Location Address 1: 72 SCOTT AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11237
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000064568
Mailing Name: BROWNING FERRIS
Mailing Contact: JIM VAN WOERT
Mailing Address 1: 72 SCOTT AVE
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11237
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7184974000

SPDES:

Name: BFI WASTE SYSTEMS OF NEW JERSEY INC
Address: 72 SCOTT AVE
City,State,Zip: BROOKLYN, NY 11237
Permit Number: NYR00C271
State-Region: 02
Expiration Date: 03/31/2012
Current Major Minor Status: Minor
Primary Facility SIC Code: 4212
State Water Body Name: NEWTOWN CREEK
Limit Set Status Flag: Active
Total Actual Average Flow(MGD): Not reported
Total App Design Flow(MGD): Not reported
UDF1: Not reported
Lat/Long: +40.709944 / -73.922306
DMR Cognizant Official: Not reported
UDF2: Not reported
UDF3: Not reported
FIPS County Code: NY047

Non-Gov Permit Affiliation Type Desc: DMR Mailing Address
Non-Gov Permit Org Formal Name: BFI WASTE SYSTEMS OF NEW JERSEY INC

BROWNING FERRIS (Continued) **S102639161**

Non-Gov Permit Street Address:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Non-Gov Permit Supplemental Location:	1057 LOWER SOUTH ST
Non-Gov Permit City:	BRONX
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10454
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	BFI SCOTT AVE
Non-Gov Facility Street Address:	72 SCOTT AVE
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11237
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Address:	72 SCOTT AVE
City,State,Zip:	BROOKLYN, NY 11237
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Non-Gov Permit Street Address:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Non-Gov Permit Supplemental Location:	1057 LOWER SOUTH ST
Non-Gov Permit City:	BRONX
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10454
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Non-Gov Facility Street Address:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Non-Gov Facility Supplemental Location:	920 E 132ND ST
Non-Gov Facility City:	BRONX
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10454
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Address:	72 SCOTT AVE
City,State,Zip:	BROOKLYN, NY 11237
UDF2:	Not reported

BROWNING FERRIS (Continued) **S102639161**

UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Non-Gov Permit Street Address:	920 E 132ND ST
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BRONX
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10454
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	BFI SCOTT AVE
Non-Gov Facility Street Address:	72 SCOTT AVE
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11237
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Address:	72 SCOTT AVE
City,State,Zip:	BROOKLYN, NY 11237
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Non-Gov Permit Street Address:	920 E 132ND ST
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BRONX
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	10454
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Non-Gov Facility Street Address:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Non-Gov Facility Supplemental Location:	920 E 132ND ST
Non-Gov Facility City:	BRONX
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10454
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

BROWNING FERRIS (Continued) **S102639161**

Name:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Address:	72 SCOTT AVE
City,State,Zip:	BROOKLYN, NY 11237
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	BFI SCOTT AVE
Non-Gov Facility Street Address:	72 SCOTT AVE
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11237
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Address:	72 SCOTT AVE
City,State,Zip:	BROOKLYN, NY 11237
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Non-Gov Facility Street Address:	BFI WASTE SYSTEMS OF NEW JERSEY INC
Non-Gov Facility Supplemental Location:	920 E 132ND ST
Non-Gov Facility City:	BRONX
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	10454
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported

BROWNING FERRIS (Continued) **S102639161**

Name: Not reported
Contacts Title: Not reported
Contacts Email: Not reported
NOI Submission Date: Not reported

AE191 **255 RANDOLPH STREET** **NY BROWNFIELDS S120706187**
ESE **255 RANDOLPH ST** **NY MANIFEST N/A**
1/4-1/2 **BROOKLYN, NY 11237**
0.325 mi.
1716 ft. **Site 2 of 3 in cluster AE**

Relative: **Higher**
Actual: **16 ft.**

BROWNFIELDS:
Name: 255 RANDOLPH STREET
Address: 255 RANDOLPH STREET
City,State,Zip: BROOKLYN, NY 11237
Program: BCP
Site Code: 534911
Acres: 0.427
HW Code: C224247
SWIS: 2401
Town: New York City
Record Added Date: 10/25/2016
Record Updated Date: 01/25/2021
Update By: JCGRATHW
Site Description: "Location: The site is located in an urban area on the north side of Randolph Street just east of Scott Avenue in an industrial section of Brooklyn. Site Features: Most of the 17,741 square foot (SF) property is covered with a 15,000 SF warehouse building with a small dirt lot located on the north side of the building. The site is adjacent to the Long Island Railroad (LIRR) right-of-way. Current Zoning and Land Use: The lot and the surrounding area are currently zoned M3-1 (Manufacturing/Industrial). There are no residential uses within the surrounding area. The property is currently vacant. Past Use of the Site: The site was last used for warehousing by Handy Lee Enterprises, an importer of Asian food products, from approximately 2006 until August 2015. The City Directory Abstract states the site was occupied by a sheet metal fabricator in the 1990s. Prior to this, according to Sanborn Fire Insurance Maps, the site was associated with the manufacture of ammonia for many decades, from at least 1907 to 1985. Sanborn maps from 1933 through 2007 show two exterior steel ammonia tanks and an acid storage area on adjacent property to the east, with no indication of production operations within the site. However, the 1907 Sanborn map shows the manufacturing facility in a different location on the block, with components of such facility within the footprint of the current site (acid tank and evaporation pan) or partially within the footprint of the current Site (storage area, grinding and mixing area, acid chambers). None of the Sanborn maps or other historical resources indicate the use or storage of chlorinated solvents, which are key contaminants of concern at the site. Site Geology and Hydrogeology: The depth to groundwater is approximately 15 feet below grade, with the flow towards the north."
Env Problem: "Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Soil, soil vapor and groundwater are impacted with tetrachloroethene (PCE) and its breakdown compounds: trichloroethene (TCE), cis-1,2-dichloroethene (1,2-DCE), and vinyl chloride. "
Health Problem: "Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised

255 RANDOLPH STREET (Continued) **S120706187**

	as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6
Sub Type:	P02
Owner Name:	James Juliano
Owner Company:	255 Randolph Street Properties, LLC
Owner Address:	213-19 99th Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Queens Village, NY 11429
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	James Juliano
Owner Company:	255 Randolph Street Properties, LLC
Owner Address:	213-19 99th Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Queens Village, NY 11429
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library - Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 16
Owner Address:	444 Thomas S. Boyland Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11212
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

255 RANDOLPH STREET (Continued) **S120706187**

NY MANIFEST:

Name:	255 RANDOLPH STREET
Address:	255 RANDOLPH ST
City,State,Zip:	BROOKLYN, NY 11237
Country:	USA
EPA ID:	NYR000238444
Facility Status:	Not reported
Location Address 1:	255 RANDOLPH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000238444
Mailing Name:	255 RANDOLPH STREET
Mailing Contact:	JAMES JULIANO
Mailing Address 1:	255 RANDOLPH STREET
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7184655600

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAC300006038
Trans2 State ID:	Not reported
Generator Ship Date:	12/20/2018
Trans1 Recv Date:	12/20/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/21/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000238444
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX168000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	016328044JJK
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

255 RANDOLPH STREET (Continued) **S120706187**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	37470
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

192
SSE
1/4-1/2
0.327 mi.
1726 ft.

DANGELO AUTO SALES & PARTS CORP **NY SWF/LF** **S108145799**
582 JOHNSON AVE **N/A**
BROOKLYN, NY 11237

Relative:
Higher

Actual:
14 ft.

SWF/LF:

Name:	DANGELO AUTO SALES & PARTS CORP
Address:	582 JOHNSON AVE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	Not reported
Active:	No
East Coordinate:	590850
North Coordinate:	4506966
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported

DANGELO AUTO SALES & PARTS CORP (Continued) **S108145799**

Expiration Date: Not reported
Operator Name: Not reported
Operator Type: Not reported
Laste Date: Not reported

AF193 **APT COMPLEX** **NY LTANKS** **S105998649**
SW **349 SCHOLES ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.327 mi.
1727 ft. **Site 1 of 2 in cluster AF**

Relative: **Higher**
Actual: **16 ft.**

LTANKS:

Name:	APT COMPLEX
Address:	349 SCHOLES ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0300325 / 2004-03-24
Facility ID:	0300325
Site ID:	117954
Spill Date:	2003-03-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2003-04-09
CID:	39
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-04-09
Spill Record Last Update:	2004-03-24
Spiller Name:	Not reported
Spiller Company:	APT COMPLEX
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	JOHN
Spiller Phone:	(718) 497-6044
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	102538
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD Called John (718) 497-6044, left message. Allison Walsh returned call. Allison is a Lawyer, representing APT Complex, (John). She asked that the tank test failure letter sent to her. Her address is 460 Park Avenue New York, NY 10022. # (212) 421-2150 Letter was prepared and sent 4/10/03. This facility is not registered with PBS E.R. Tank test letter was returned 5/2/03. Tank test failure letter sent to John 349 Scholes Street Brooklyn, NY 11206 E.R. 10/22/03. YK. Facility registered on 4/25/03 PBS # 2-608900. However, TT is overdue. 2/2/2004. YK faxed an old TTF letter dated April 10, 2003 to David Yudelson (212-421-2150 X 219) attorney for this property. 2/23/04. J.Krimgold talked to David Y. Tank taken out of service but

APT COMPLEX (Continued) **S105998649**

not close yet. Trade-Winds did soil borings(?). He should call me back today with more info. 3/24/04. J.Krimgold reviewed a letter report prepared by Trade-Winds dated 3/16/04. 3 soil samples was taken by drilling through the tank bottom of 3000 gal tank and 2 samples from 1100 gal tank. All came out negative. NFA letter on 3/24/04. "

Remarks: "tank test failure "

All TTF:

Facility ID:	0300325
Spill Number:	0300325
Spill Tank Test:	1528245
Site ID:	117954
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	117954
Operable Unit ID:	866409
Operable Unit:	01
Material ID:	508406
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

194 **345 TENEYCK STREET** **NY LTANKS** **S102672003**
West **345 TENEYCK STREET** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.328 mi.
1730 ft.

Relative: **Higher**

Actual: **19 ft.**

LTANKS:

Name:	345 TENEYCK STREET
Address:	345 TENEYCK STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9210082 / 1992-12-01
Facility ID:	9210082
Site ID:	300237
Spill Date:	1992-12-01
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial

345 TENEYCK STREET (Continued) **S102672003**

Spill Class:	C3
Cleanup Ceased:	1992-12-01
SWIS:	2401
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1992-12-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-12-02
Spill Record Last Update:	1992-12-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	242863
DEC Memo:	""
Remarks:	"FAULTY PETROMETER-OIL OUT FILL PIPE TO CONCRETE SIDEWALK-SPEEDI-DRI APPLIED-SPILL TEAM ENROUTE TO P/U AND DISPOSE"

All Materials:

Site ID:	300237
Operable Unit ID:	974178
Operable Unit:	01
Material ID:	407093
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AD195 **100 MORGAN AVENUE** **NY LTANKS** **S104278698**
SW **100 MORGAN AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.338 mi.
1785 ft. **Site 2 of 2 in cluster AD**

Relative: LTANKS:
Lower

Actual: Name:	100 MORGAN AVENUE
13 ft. Address:	100 MORGAN AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9909719 / 2000-11-20
Facility ID:	9909719
Site ID:	328581
Spill Date:	1999-11-10

100 MORGAN AVENUE (Continued) **S104278698**

Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1999-11-10
CID:	281
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-11-10
Spill Record Last Update:	2000-11-20
Spiller Name:	KEVIN LUMPE
Spiller Company:	STEEL LOS LP
Spiller Address:	HICKSVILLE RD
Spiller County:	001
Spiller Contact:	KEVIN LUMPE
Spiller Phone:	(516) 576-3165
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	264440
DEC Memo:	""
Remarks:	"TANK PERFORMED AT ABOVE LOCATION. PLANS HAVE BEEN MADE TO REMOVE TANK. NO CALL BACK REQUESTED."

All TTF:

Facility ID:	9909719
Spill Number:	9909719
Spill Tank Test:	1547833
Site ID:	328581
Tank Number:	Not reported
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	328581
Operable Unit ID:	1084487
Operable Unit:	01
Material ID:	298793
Material Code:	0001A
Material Name:	#2 fuel oil

100 MORGAN AVENUE (Continued) **S104278698**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AG196 **T & T SCRAP LLC** **NY SWF/LF** **S116554258**
NNW **340 MASPETH AVENUE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11211** **NY SPDES**
0.343 mi.
1809 ft. **Site 1 of 7 in cluster AG**

Relative:
Lower

Actual:
12 ft.

SWF/LF:

Name:	T N T SCRAP LLC
Address:	340 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Flag:	ACTIVE
Region Code:	2
Phone Number:	7183664017
Owner Name:	T N T Scrap
Owner Type:	Private
Owner Address:	340 Maspeth Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Email:	Not reported
Owner Phone:	7183664017
Contact Name:	Timothy Fulton
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	info@tntscrap.com
Contact Phone:	7183664017
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[41J]
Active:	Yes
East Coordinate:	590313
North Coordinate:	4508024
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

SPILLS:

Name:	TNT SCRAP YARD
Address:	340 MASPETH AVE
City,State,Zip:	BROOKLYN, NY 11211
Spill Number/Closed Date:	1400237 / 2014-04-24
Facility ID:	1400237
Facility Type:	ER
DER Facility ID:	448349

T & T SCRAP LLC (Continued) **S116554258**

Site ID:	493470
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	2401
Spill Date:	2014-04-07
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2014-04-07
CID:	Not reported
Water Affected:	ENGLISH KILLS
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-04-07
Spill Record Last Update:	2014-04-24
Spiller Name:	TNT SCRAP METAL
Spiller Company:	TNT SCRAP METAL
Spiller Address:	340 MASPETH AVE
Spiller Company:	999
Contact Name:	ANONYMOUS EMAILER
DEC Memo:	"Referred to DLE for follow up. DEC Piper spoke with DLE Iovino on 4/8. Her inspection revealed no sighs of diesel spillage, tank or sheen on water or bulkhead. Bsaed on DLE inspection and anonynous call with no additional info, this spill is closed. "
Remarks:	">>> 4/7/2014 20:18 >>> The following information was received through the DEC website Report an Environmental Violation Online or sent directly by the complainant to an OPP dispatch mailbox: Who Did It: TNT Scrap Yard on Maspeth ave Brooklyn, NY. On Newtown Creek What Occurred: There is a large amount of what looks and smells like diesel fuel flowing into the Newtown Creek from the scrap yard. It is in the rear right hand side if looking from the water. When Did It Occur: 4/7/14. Late afternoon evening. Appears to be running with storm water run off. County: Kings Municipality: Brooklyn Location Or Address: 340 Maspeth Ave How Did It Occur: It looks like their old fuel truck is leaking out diesel into the creek. Complainants Name: Complainants Phone: Complainants Email: Date of Submittal: 04/07/2014"
	Not reported

All Materials:

Site ID:	493470
Operable Unit ID:	1242974
Operable Unit:	01
Material ID:	2243575
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

T & T SCRAP LLC (Continued) **S116554258**

SPDES:

Name:	T & T SCRAP LLC
Address:	340 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Permit Number:	NYR00E223
State-Region:	02
Expiration Date:	09/30/2017
Current Major Minor Status:	Minor
Primary Facility SIC Code:	5093
State Water Body Name:	ENGLISH KILLS
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	+40.717 / -73.929
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	T & T SCRAP LLC
Non-Gov Permit Street Address:	T & T SCRAP LLC
Non-Gov Permit Supplemental Location:	340 MASPETH AVE
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11211
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	T & T SCRAP LLC
Non-Gov Facility Street Address:	T & T SCRAP LLC
Non-Gov Facility Supplemental Location:	340 MASPETH AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	T & T SCRAP LLC
Address:	340 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	T & T SCRAP LLC
Non-Gov Permit Street Address:	340 MASPETH AVE
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN

T & T SCRAP LLC (Continued) **S116554258**

Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11211
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	T & T SCRAP LLC
Non-Gov Facility Street Address:	T & T SCRAP LLC
Non-Gov Facility Supplemental Location:	340 MASPETH AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	T & T SCRAP LLC
Address:	340 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	T & T SCRAP LLC
Non-Gov Facility Street Address:	T & T SCRAP LLC
Non-Gov Facility Supplemental Location:	340 MASPETH AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

AG197 **NEW YORK RECYCLERS; INC. (MASPETH AVE)** **NY SWF/LF** **S105841915**
NNW **340 MASPETH AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11211**
0.343 mi.
1809 ft. **Site 2 of 7 in cluster AG**

Relative: **Lower**
Actual: **12 ft.**

SWF/LF:

Name:	NEW YORK RECYCLERS; INC. (MASPETH AVE)
Address:	340 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Flag:	INACTIVE
Region Code:	2
Phone Number:	7183492540
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	TIMOTHY FULTON
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[24WE6]
Active:	No
East Coordinate:	590567
North Coordinate:	4508105
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Concrete;Asphalt;Brick;Rock;Soil (Clean)
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

AH198 **FEDEX FACILITY** **NY LTANKS** **S106004598**
NNW **300 MASPETH AVE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.343 mi.
1813 ft. **Site 1 of 7 in cluster AH**

Relative: **Lower**
Actual: **12 ft.**

LTANKS:

Name:	FEDEX
Address:	300 MASPETH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0204002 / 2005-12-22
Facility ID:	0204002
Site ID:	291369
Spill Date:	2002-07-15
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401

FEDEX FACILITY (Continued) **S106004598**

Investigator:	aaobliga
Referred To:	Not reported
Reported to Dept:	2002-07-17
CID:	207
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-07-17
Spill Record Last Update:	2006-01-06
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	JERRY SWART
Spiller Phone:	(412) 262-6291
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	235924
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 2/13/2003 - Closed Due To The Nature / Extent Of The Spill Report 10/3/05 - Spill transferred from Vought to Obligado."
Remarks:	"black tarry substance"

All Materials:

Site ID:	291369
Operable Unit ID:	855266
Operable Unit:	01
Material ID:	518262
Material Code:	0063A
Material Name:	unknown hazardous material
Case No.:	Not reported
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	FEDEX
Address:	300 MASPETH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0202804 / 2005-12-22
Facility ID:	0202804
Facility Type:	ER
DER Facility ID:	235924
Site ID:	205400
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B4
SWIS:	2401
Spill Date:	2002-06-17
Investigator:	aaobliga

FEDEX FACILITY (Continued) **S106004598**

Referred To:	NFA
Reported to Dept:	2002-06-17
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-06-17
Spill Record Last Update:	2005-12-22
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	300 MASPETH AV
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 10/15/04-Vought-File review by Vought: Access Agreement-7/10/02. Access agreement for FedEx to remove USTs and portion of tankfield on adjacent property. Letter from Testwell Labs(Pearce) to FedEx(Swart)-7/10/02. Work proposal for installation of nine soil borings, field screening of soil samples, conversion of three of the borings into monitoring wells, quarterly sampling of the wells and further excavation of the soil and piping. Letter from Testwell Labs(Pearce) to DEC Vought-7/22/02. Soil samples were taken from the walls and groundwater after the underground fuel storage tanks and surrounding had been removed... Testwell recommends: 1)backfilling of UST excavation 2)SVOC's are due to fill material 3)if wells are deemed necessary they are to be installed at a later date after site work (piles and foundations) is complete 4)remaining vent lines terminate at surface level and remaining contaminated soil on adjacent property should be removed. Letter from Gannett Fleming (Ernst) to DEC Vought-8/13/02. This letter is intended to inform the NYSDEC of the projected site remediation activities. Based on the endpoint soil data (samples WSW and SSW no further action is recommended for the soil beneath facility footprint which is currently under construcion . No groundwater monitoring wells are proposed inside the facility. Gannett Fleming will provide a comprehensive site investigation report on both the UST removal and for the black tar like substance found in the southwestern portion of the site . Report from Gannett Fleming to DEC Vought-8/28/04. This letter provides a summary of the additional investigation activities and sample analysis that have taken place..... Removal of twenty (550-gallon) gasoline USTs and 900 tons of impacted soil. See above 7/22/02 entry for endpoint analyticals. Soil analyticals show 7750ppb 1,3,5-trimethylbenzene(WSW Wall) and 6470ppb xylene(WSW Wall), 110ppb benzene(vent x bottom), 110ppb benzene(Vent x sw), 120ppb benzene(n wall composite), 5900ppb 1,3,5-trimethylbenzene(n wall composite), 11000ppb 1,2,4-trimethylbenzene(n wall composite). Groundwater analytical from one well shows 40ppb benzene and 26ppb xylene. Black stained soil exhibiting a strong petroleum odor was observed adjacent to the southwestern portion of the existing warehouse . Seven test pits were dug to delineate the stained soil but no groundwater samples were collected. Report recommends: 1)no further actions for

FEDEX FACILITY (Continued) **S106004598**

soils south and west of the former UST area 2)additional delineation north and east of the former UST area via Geoprobe 3)installation of six montoring wells (two upgradient and four downgradient). Investigation activities will be provided to DEC in a supplemental site investigation report. Soil analyticals shos PAH exceedences throughout site due to fill material. Report from Gannett Fleming to DEC Vought-6/8/04. This letter report documents the results of investigative activities conducted.... A review of historic Sanborn maps indicate a Brooklyn Union Gas bulk petroleum storage and distribution terminal was present in the southwestern portion of the site in 1951. Installation of six monitoring wells. An additional well was installed to replace a well destroyed in the tankfield excavation. Groundwater at a depth of 8' below grade. ..groundwater flows to the north in the northern portion of the site. Groundwater flows converge to the east in the southern portion of the site . Groundwater analyticals show 21ppb ethylbenzene(MW1), 13ppb 1,3,5-trimethylbenzene(MW1), 97ppb napthalene(MW1), 10ppb benzene(MW2), 7ppb ethylbenzene(MW2), 93ppb napthalene(MW2), 20ppb benzene(MW7), 7ppb ethylbenzene(MW7), 35ppb xylene(MW7), 52ppb napthalene(MW7). Soil analyticals showed no VOC exceedences and SVOC exceedences attributable to fill material. Report recommends: 1)no further action with respect to soil 2)no further action for onsite groundwater due to poor regional groundwater quality . Report requests no further action. DEC requires: 1)one full year of groundwater monitoring prior to closure. 10/18/04-Vought-Sent letter with above requirement. 9/27/05 - Obligado - SITE TRANSFERRED FROM VOUGHT TO OBLIGADO 9/30/05 - Obligado - Called Manfred Bohms, left message. 10/03/05 - Obligado - Spoke with Manfred Bohms (516) 671-8440. Said that a final quarterly monitoring report should be received by Department in a few weeks. 11/7/05 - Obligado - Review final quarterly monitoring report. Ground water results show 28 ppb benzene (MW1), 28 ppb ethylbenzene (mw1), 10 ppb xylenes (mw1), 3 ppb benzene (mw3), 34 ppb benzene (mw7), 6 ppb toluene (mw7), 32 ppb xylenes (mw7), 150 ppb napthalene (mw7). Conclusions: GW data indicate ground water contmaination is stagnant. GW flow and quality have remained consistent throughout monitoring program. Stagnant gw plume indicate groundwater impacts representative of regional groundwater quality . Requests no further action. Will discuss with Joe Sun. 12/22/05 - Obligado - Spoke with Koon. Approves NFA. Minor residual contamination possibly coming from offsite - former Brooklyn Union is across the street. Spill closed. Letter sent. "

Remarks: "they were excavating a previously closed tank & came across it by the piping - they will excavate & stock pile the soil"

All Materials:

Site ID:	205400
Operable Unit ID:	855853
Operable Unit:	01
Material ID:	520642
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

FEDEX FACILITY (Continued) **S106004598**

Name:	FEDEX FACILITY
Address:	300 MASPETH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0810227 / 2008-12-12
Facility ID:	0810227
Facility Type:	ER
DER Facility ID:	235924
Site ID:	407744
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2008-12-12
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2008-12-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-12-12
Spill Record Last Update:	2008-12-12
Spiller Name:	MIKE DOWGER
Spiller Company:	FEDEX
Spiller Address:	300 MASPETH AVE
Spiller Company:	999
Contact Name:	MIKE DOWGER
DEC Memo:	"Sangesland spoke to Dan at Miller. He said there was a spill in the FEDEX parking lot from 20 gal diesel from a delivery truck. Vac truck is sucking out the drain. Because of the rain earlier today there was standing water in the sump and the product was floating on top of the water. Speedie Dry was applied to the parking lot area. 3PM Everything is now cleaned up and Miller is packing up their gear and leaving."
Remarks:	"Caller states a leaking fuel tank on a truck caused fuel to spill onto the parking lot and ran into a storm sewer. Miller environmental is cleaning up."

All Materials:

Site ID:	407744
Operable Unit ID:	1164280
Operable Unit:	01
Material ID:	2155653
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AI199 **JOYVA CORPORATION** **NY LTANKS** **S118953482**
South **53 VARICK AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.344 mi.
1814 ft. **Site 1 of 2 in cluster AI**

Relative:
Higher

Actual:
14 ft.

LTANKS:

Name:	JOYVA CORPORATION
Address:	53 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0302698 / 2003-07-23
Facility ID:	0302698
Site ID:	303353
Spill Date:	2003-06-13
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2003-06-13
CID:	297
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-13
Spill Record Last Update:	2003-07-23
Spiller Name:	MORT TUROSS
Spiller Company:	JOYVA CORPORATION
Spiller Address:	53 VARICK AV
Spiller County:	001
Spiller Contact:	MORT TUROSS ENERGY STORAG
Spiller Phone:	(718) 257-4045
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	245115
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND Sangesland DDO Tank Test Failure letter sent to: Mort Tuross Joyva Corporation 53 Varick Ave Brooklyn, NY 11237 7/23/2003 - Energy Storage Systems Inc (718-257-8470) sent in a letter which stated that the problem was found on a fitting. The tank was retested and past. During the excavation to the top of the tank, no contamination was found. The tank was repaired, backfilled and put back into service. Spill Closed"
Remarks:	"NO CONTAMINATION FOUND AROUND THE TANK"

All TTF:

Facility ID:	0302698
Spill Number:	0302698
Spill Tank Test:	1528449
Site ID:	303353
Tank Number:	Not reported
Tank Size:	2000
Material:	0001
EPA UST:	Not reported

JOYVA CORPORATION (Continued) **S118953482**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	303353
Operable Unit ID:	870434
Operable Unit:	01
Material ID:	507158
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AJ200 **CORNISH KNIT GOODS/CORNISH MINI-MILLS** **NY ENG CONTROLS** **S110043685**
South **121 INGRAHAM ST./89 PORTER AVE.** **NY INST CONTROL** **N/A**
1/4-1/2 **BROOKLYN, NY 11237** **NY VCP**
0.346 mi.
1827 ft. **Site 1 of 4 in cluster AJ**

Relative:
Higher

Actual:
17 ft.

ENG CONTROLS:

Name:	CORNISH KNIT GOODS/CORNISH MINI-MILLS
Address:	121 INGRAHAM ST./89 PORTER AVE.
City,State,Zip:	BROOKLYN, NY 11237
Site Code:	58133
HW Code:	V00409
Control Code:	18
Control Type:	ENG
Date Record Added:	05/10/2010
Date Rec Updated:	11/08/2021
Updated By:	MXMAGLOI
Site Description:	"Location: The Cornish Knit Goods/Cornish Mini-Mills site is located at 89 Porter Avenue, Brooklyn, NY. The former address of this site was 121 Ingraham Street/89-111 Porter Ave. The 0.57 acre site is in East Williamsburg, an urban area of Brooklyn. The tax map identifies the site as Block 2993, Lot 1. The site is bordered by Porter Avenue to the west, by Ingraham Street to the south, by Joyva Candy Factory's parking lot to the east, and by Johnson Avenue to the north. Site Features: The site is completely covered by a four story building, which was renovated in order to be designated for restricted residential use. Current zoning/use(s): The site is in an area zoned M1-2, light manufacturing. The site building is currently operated as the Peter Jay Sharp Center for Opportunity (PJSCO). The building is used as shelter and rehabilitation center for homeless men. The surrounding parcels are currently used for a combination of commercial, industrial and residential. Historical Use(s): Until 1980

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

the property was operated by Cornish Knit Goods/Cornish Mini-Mills as a textile factory. From 1980 until 1995, the building was vacant, and it was illegally operated as a dry cleaning facility and as a stolen car scrap yard. In 2000, the property was owned by ABC Closing Corp. and the owner entered in a Voluntary Cleanup Agreement (VCA) with NYSDEC. In 2003, site ownership was transferred to Porter Avenue HDFC, a subsidiary of the DOE Fund, Inc., and the VCA was amended to reflect the change in ownership. Dry cleaning activities and uncontrolled disposal of waste solvents (perchloroethylene, or PCE, and its breakdown product trichloroethylene, or TCE) led to contamination of the soil and groundwater at the site. Site Geology and Hydrogeology: The surficial geology in the vicinity of the site is characterized by layered loose sediment. Soils recovered from the western portion of the site appear to be loose sands and sediments to approximately nine feet below ground surface (bgs) mixed with fill material such as gravels, brick, and old timbers. From 9 feet bgs to the top of the water table (approximately 13 feet bgs), soils are compact clays and sands. Soils recovered from drilling in the eastern portion of the site were characterized as fill. Groundwater depth ranges from 7 feet below ground surface (ft bgs) at the northwest portion of the site, 11-11.5 ft bgs across the western portion of the site, and 12-12.5 ft bgs across the southeast portion of the site. "

Env Problem: "Nature and Extent of the Contamination: Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern at the site included the volatile organic compounds (VOCs) tetrachloroethylene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene (DCE) and vinyl chloride (VC) in soil, groundwater and soil vapor. A vapor barrier and an Air Sparge/Soil Vapor Extraction System (AS/SVES) were installed and are operating on site to mitigate the remaining PCE and TCE contamination in soil vapor. Remaining contamination in soil and groundwater is being managed under a Site Management Plan. "

Health Problem: "Groundwater beneath the site is contaminated with volatile organic compounds (VOCs), primarily tetrachloroethene (PCE), at levels above NYS drinking water standards. There are no active public water supply wells within a one mile radius of the site and public exposure to contaminated groundwater is unlikely because all businesses and residences are supplied by public water. Exposure to contaminated soil is not expected since the site is covered by buildings and is paved. A vapor barrier and active soil vapor extraction system is at the site to prevent exposures from soil vapor intrusion. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-11-30 14:48:00
Record Upd: 2011-04-11 15:21:00
Updated By: IXMUNTEA
Own Op: 1
Sub Type: 06
Owner Name: John McDonald

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Owner Company:	The DOE Fund, Inc.
Owner Address:	345 East 102nd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	John McDonald
Owner Company:	Porter Avenue HDFC A DIV. OF DOE FUND Inc.
Owner Address:	345 EAST 102ND STREET, 3RD FLOOR
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10029
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	John McDonald
Owner Company:	The DOE Fund, Inc.
Owner Address:	345 East 102nd Street, Third Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
HW Code:	V00409
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	METHYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	1,1,1,2-TETRACHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	00-TEMP-03-24(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS
Crossref ID:	2010000128456
Cross Ref Type Code:	25

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Cross Ref Type:	County Recording Identifier
Record Added Date:	2011-04-13 14:06:00
Record Updated:	2011-04-13 14:06:00
Updated By:	JHOCONNE
Name:	CORNISH KNIT GOODS/CORNISH MINI-MILLS
Address:	121 INGRAHAM ST./89 PORTER AVE.
City,State,Zip:	BROOKLYN, NY 11237
Site Code:	58133
HW Code:	V00409
Control Code:	22
Control Type:	ENG
Date Record Added:	01/21/2009
Date Rec Updated:	11/08/2021
Updated By:	MXMAGLOI
Site Description:	"Location: The Cornish Knit Goods/Cornish Mini-Mills site is located at 89 Porter Avenue, Brooklyn, NY. The former address of this site was 121 Ingraham Street/89-111 Porter Ave. The 0.57 acre site is in East Williamsburg, an urban area of Brooklyn. The tax map identifies the site as Block 2993, Lot 1. The site is bordered by Porter Avenue to the west, by Ingraham Street to the south, by Joyva Candy Factory's parking lot to the east, and by Johnson Avenue to the north. Site Features: The site is completely covered by a four story building, which was renovated in order to be designated for restricted residential use. Current zoning/use(s): The site is in an area zoned M1-2, light manufacturing. The site building is currently operated as the Peter Jay Sharp Center for Opportunity (PJSCO). The building is used as shelter and rehabilitation center for homeless men. The surrounding parcels are currently used for a combination of commercial, industrial and residential. Historical Use(s): Until 1980 the property was operated by Cornish Knit Goods/Cornish Mini-Mills as a textile factory. From 1980 until 1995, the building was vacant, and it was illegally operated as a dry cleaning facility and as a stolen car scrap yard. In 2000, the property was owned by ABC Closing Corp. and the owner entered in a Voluntary Cleanup Agreement (VCA) with NYSDEC. In 2003, site ownership was transferred to Porter Avenue HDFC, a subsidiary of the DOE Fund, Inc., and the VCA was amended to reflect the change in ownership. Dry cleaning activities and uncontrolled disposal of waste solvents (perchloroethylene, or PCE, and its breakdown product trichloroethylene, or TCE) led to contamination of the soil and groundwater at the site. Site Geology and Hydrogeology: The surficial geology in the vicinity of the site is characterized by layered loose sediment. Soils recovered from the western portion of the site appear to be loose sands and sediments to approximately nine feet below ground surface (bgs) mixed with fill material such as gravels, brick, and old timbers. From 9 feet bgs to the top of the water table (approximately 13 feet bgs), soils are compact clays and sands. Soils recovered from drilling in the eastern portion of the site were characterized as fill. Groundwater depth ranges from 7 feet below ground surface (ft bgs) at the northwest portion of the site, 11-11.5 ft bgs across the western portion of the site, and 12-12.5 ft bgs across the southeast portion of the site. "
Env Problem:	"Nature and Extent of the Contamination: Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern at the site included the volatile organic compounds (VOCs) tetrachloroethylene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

	(DCE) and vinyl chloride (VC) in soil, groundwater and soil vapor. A vapor barrier and an Air Sparge/Soil Vapor Extraction System (AS/SVES) were installed and are operating on site to mitigate the remaining PCE and TCE contamination in soil vapor. Remaining contamination in soil and groundwater is being managed under a Site Management Plan. "
Health Problem:	"Groundwater beneath the site is contaminated with volatile organic compounds (VOCs), primarily tetrachloroethene (PCE), at levels above NYS drinking water standards. There are no active public water supply wells within a one mile radius of the site and public exposure to contaminated groundwater is unlikely because all businesses and residences are supplied by public water. Exposure to contaminated soil is not expected since the site is covered by buildings and is paved. A vapor barrier and active soil vapor extraction system is at the site to prevent exposures from soil vapor intrusion. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2009-11-30 14:48:00
Record Upd:	2011-04-11 15:21:00
Updated By:	IXMUNTEA
Own Op:	1
Sub Type:	06
Owner Name:	John McDonald
Owner Company:	The DOE Fund, Inc.
Owner Address:	345 East 102nd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	John McDonald
Owner Company:	Porter Avenue HDFC A DIV. OF DOE FUND Inc.
Owner Address:	345 EAST 102ND STREET, 3RD FLOOR
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10029
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	John McDonald
Owner Company:	The DOE Fund, Inc.
Owner Address:	345 East 102nd Street, Third Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
HW Code:	V00409
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	DICHLOROETHYLENE

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	METHYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	1,1,1,2-TETRACHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	00-TEMP-03-24(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS
Crossref ID:	2010000128456
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2011-04-13 14:06:00
Record Updated:	2011-04-13 14:06:00
Updated By:	JHOCONNE

Name:	CORNISH KNIT GOODS/CORNISH MINI-MILLS
Address:	121 INGRAHAM ST./89 PORTER AVE.
City,State,Zip:	BROOKLYN, NY 11237
Site Code:	58133
HW Code:	V00409
Control Code:	15
Control Type:	ENG
Date Record Added:	05/10/2010
Date Rec Updated:	11/08/2021
Updated By:	MXMAGLOI
Site Description:	"Location: The Cornish Knit Goods/Cornish Mini-Mills site is located at 89 Porter Avenue, Brooklyn, NY. The former address of this site was 121 Ingraham Street/89-111 Porter Ave. The 0.57 acre site is in East Williamsburg, an urban area of Brooklyn. The tax map identifies the site as Block 2993, Lot 1. The site is bordered by Porter Avenue to the west, by Ingraham Street to the south, by Joyva Candy Factory's parking lot to the east, and by Johnson Avenue to the north. Site Features: The site is completely covered by a four story building, which was renovated in order to be designated for restricted residential use. Current zoning/use(s): The site is in an area zoned M1-2, light manufacturing. The site building is currently operated as the Peter Jay Sharp Center for Opportunity (PJSCO). The

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

building is used as shelter and rehabilitation center for homeless men. The surrounding parcels are currently used for a combination of commercial, industrial and residential. Historical Use(s): Until 1980 the property was operated by Cornish Knit Goods/Cornish Mini-Mills as a textile factory. From 1980 until 1995, the building was vacant, and it was illegally operated as a dry cleaning facility and as a stolen car scrap yard. In 2000, the property was owned by ABC Closing Corp. and the owner entered in a Voluntary Cleanup Agreement (VCA) with NYSDEC. In 2003, site ownership was transferred to Porter Avenue HDFC, a subsidiary of the DOE Fund, Inc., and the VCA was amended to reflect the change in ownership. Dry cleaning activities and uncontrolled disposal of waste solvents (perchloroethylene, or PCE, and its breakdown product trichloroethylene, or TCE) led to contamination of the soil and groundwater at the site. Site Geology and Hydrogeology: The surficial geology in the vicinity of the site is characterized by layered loose sediment. Soils recovered from the western portion of the site appear to be loose sands and sediments to approximately nine feet below ground surface (bgs) mixed with fill material such as gravels, brick, and old timbers. From 9 feet bgs to the top of the water table (approximately 13 feet bgs), soils are compact clays and sands. Soils recovered from drilling in the eastern portion of the site were characterized as fill. Groundwater depth ranges from 7 feet below ground surface (ft bgs) at the northwest portion of the site, 11-11.5 ft bgs across the western portion of the site, and 12-12.5 ft bgs across the southeast portion of the site. "

Env Problem: "Nature and Extent of the Contamination: Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern at the site included the volatile organic compounds (VOCs) tetrachloroethylene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene (DCE) and vinyl chloride (VC) in soil, groundwater and soil vapor. A vapor barrier and an Air Sparge/Soil Vapor Extraction System (AS/SVES) were installed and are operating on site to mitigate the remaining PCE and TCE contamination in soil vapor. Remaining contamination in soil and groundwater is being managed under a Site Management Plan. "

Health Problem: "Groundwater beneath the site is contaminated with volatile organic compounds (VOCs), primarily tetrachloroethene (PCE), at levels above NYS drinking water standards. There are no active public water supply wells within a one mile radius of the site and public exposure to contaminated groundwater is unlikely because all businesses and residences are supplied by public water. Exposure to contaminated soil is not expected since the site is covered by buildings and is paved. A vapor barrier and active soil vapor extraction system is at the site to prevent exposures from soil vapor intrusion. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-11-30 14:48:00
Record Upd: 2011-04-11 15:21:00
Updated By: IXMUNTEA

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Own Op:	1
Sub Type:	06
Owner Name:	John McDonald
Owner Company:	The DOE Fund, Inc.
Owner Address:	345 East 102nd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	John McDonald
Owner Company:	Porter Avenue HDFC A DIV. OF DOE FUND Inc.
Owner Address:	345 EAST 102ND STREET, 3RD FLOOR
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10029
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	John McDonald
Owner Company:	The DOE Fund, Inc.
Owner Address:	345 East 102nd Street, Third Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
HW Code:	V00409
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	METHYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	1,1,1,2-TETRACHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	00-TEMP-03-24(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Updated By:	VCPTRANS
Crossref ID:	2010000128456
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2011-04-13 14:06:00
Record Updated:	2011-04-13 14:06:00
Updated By:	JHOCONNE
Name:	CORNISH KNIT GOODS/CORNISH MINI-MILLS
Address:	121 INGRAHAM ST./89 PORTER AVE.
City,State,Zip:	BROOKLYN, NY 11237
Site Code:	58133
HW Code:	V00409
Control Code:	13
Control Type:	ENG
Date Record Added:	05/10/2010
Date Rec Updated:	11/08/2021
Updated By:	MXMAGLOI
Site Description:	"Location: The Cornish Knit Goods/Cornish Mini-Mills site is located at 89 Porter Avenue, Brooklyn, NY. The former address of this site was 121 Ingraham Street/89-111 Porter Ave. The 0.57 acre site is in East Williamsburg, an urban area of Brooklyn. The tax map identifies the site as Block 2993, Lot 1. The site is bordered by Porter Avenue to the west, by Ingraham Street to the south, by Joyva Candy Factory's parking lot to the east, and by Johnson Avenue to the north. Site Features: The site is completely covered by a four story building, which was renovated in order to be designated for restricted residential use. Current zoning/use(s): The site is in an area zoned M1-2, light manufacturing. The site building is currently operated as the Peter Jay Sharp Center for Opportunity (PJSCO). The building is used as shelter and rehabilitation center for homeless men. The surrounding parcels are currently used for a combination of commercial, industrial and residential. Historical Use(s): Until 1980 the property was operated by Cornish Knit Goods/Cornish Mini-Mills as a textile factory. From 1980 until 1995, the building was vacant, and it was illegally operated as a dry cleaning facility and as a stolen car scrap yard. In 2000, the property was owned by ABC Closing Corp. and the owner entered in a Voluntary Cleanup Agreement (VCA) with NYSDEC. In 2003, site ownership was transferred to Porter Avenue HDFC, a subsidiary of the DOE Fund, Inc., and the VCA was amended to reflect the change in ownership. Dry cleaning activities and uncontrolled disposal of waste solvents (perchloroethylene, or PCE, and its breakdown product trichloroethylene, or TCE) led to contamination of the soil and groundwater at the site. Site Geology and Hydrogeology: The surficial geology in the vicinity of the site is characterized by layered loose sediment. Soils recovered from the western portion of the site appear to be loose sands and sediments to approximately nine feet below ground surface (bgs) mixed with fill material such as gravels, brick, and old timbers. From 9 feet bgs to the top of the water table (approximately 13 feet bgs), soils are compact clays and sands. Soils recovered from drilling in the eastern portion of the site were characterized as fill. Groundwater depth ranges from 7 feet below ground surface (ft bgs) at the northwest portion of the site, 11-11.5 ft bgs across the western portion of the site, and 12-12.5 ft bgs across the southeast portion of the site. "
Env Problem:	"Nature and Extent of the Contamination: Post-Remediation: Remediation at the site is complete. Prior to remediation, the

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

primary contaminants of concern at the site included the volatile organic compounds (VOCs) tetrachloroethylene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene (DCE) and vinyl chloride (VC) in soil, groundwater and soil vapor. A vapor barrier and an Air Sparge/Soil Vapor Extraction System (AS/SVES) were installed and are operating on site to mitigate the remaining PCE and TCE contamination in soil vapor. Remaining contamination in soil and groundwater is being managed under a Site Management Plan. "

Health Problem:	"Groundwater beneath the site is contaminated with volatile organic compounds (VOCs), primarily tetrachloroethene (PCE), at levels above NYS drinking water standards. There are no active public water supply wells within a one mile radius of the site and public exposure to contaminated groundwater is unlikely because all businesses and residences are supplied by public water. Exposure to contaminated soil is not expected since the site is covered by buildings and is paved. A vapor barrier and active soil vapor extraction system is at the site to prevent exposures from soil vapor intrusion. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2009-11-30 14:48:00
Record Upd:	2011-04-11 15:21:00
Updated By:	IXMUNTEA
Own Op:	1
Sub Type:	06
Owner Name:	John McDonald
Owner Company:	The DOE Fund, Inc.
Owner Address:	345 East 102nd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	John McDonald
Owner Company:	Porter Avenue HDFC A DIV. OF DOE FUND Inc.
Owner Address:	345 EAST 102ND STREET, 3RD FLOOR
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10029
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	John McDonald
Owner Company:	The DOE Fund, Inc.
Owner Address:	345 East 102nd Street, Third Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
HW Code:	V00409
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Waste Code: Not reported
HW Code: V00409
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1,1,2-TETRACHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 00-TEMP-03-24(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: 2010000128456
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-04-13 14:06:00
Record Updated: 2011-04-13 14:06:00
Updated By: JHOCONNE

INST CONTROL:
Name: CORNISH KNIT GOODS/CORNISH MINI-MILLS
Address: 121 INGRAHAM ST./89 PORTER AVE.
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58133
Control Name: Soil Management Plan
HW Code: V00409
Control Code: 14
Control Type: INST
Dt record added: 01/21/2009
Dt rec updated: 11/08/2021
Updated By: MXMAGLOI
Site Code: 58133
Site Description: "Location: The Cornish Knit Goods/Cornish Mini-Mills site is located at 89 Porter Avenue, Brooklyn, NY. The former address of this site was 121 Ingraham Street/89-111 Porter Ave. The 0.57 acre site is in East Williamsburg, an urban area of Brooklyn. The tax map identifies the site as Block 2993, Lot 1. The site is bordered by Porter Avenue to the west, by Ingraham Street to the south, by Joyva Candy

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Factory's parking lot to the east, and by Johnson Avenue to the north. Site Features: The site is completely covered by a four story building, which was renovated in order to be designated for restricted residential use. Current zoning/use(s): The site is in an area zoned M1-2, light manufacturing. The site building is currently operated as the Peter Jay Sharp Center for Opportunity (PJSCO). The building is used as shelter and rehabilitation center for homeless men. The surrounding parcels are currently used for a combination of commercial, industrial and residential. Historical Use(s): Until 1980 the property was operated by Cornish Knit Goods/Cornish Mini-Mills as a textile factory. From 1980 until 1995, the building was vacant, and it was illegally operated as a dry cleaning facility and as a stolen car scrap yard. In 2000, the property was owned by ABC Closing Corp. and the owner entered in a Voluntary Cleanup Agreement (VCA) with NYSDEC. In 2003, site ownership was transferred to Porter Avenue HDFC, a subsidiary of the DOE Fund, Inc., and the VCA was amended to reflect the change in ownership. Dry cleaning activities and uncontrolled disposal of waste solvents (perchloroethylene, or PCE, and its breakdown product trichloroethylene, or TCE) led to contamination of the soil and groundwater at the site. Site Geology and Hydrogeology: The surficial geology in the vicinity of the site is characterized by layered loose sediment. Soils recovered from the western portion of the site appear to be loose sands and sediments to approximately nine feet below ground surface (bgs) mixed with fill material such as gravels, brick, and old timbers. From 9 feet bgs to the top of the water table (approximately 13 feet bgs), soils are compact clays and sands. Soils recovered from drilling in the eastern portion of the site were characterized as fill. Groundwater depth ranges from 7 feet below ground surface (ft bgs) at the northwest portion of the site, 11-11.5 ft bgs across the western portion of the site, and 12-12.5 ft bgs across the southeast portion of the site. "

Env Problem: "Nature and Extent of the Contamination: Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern at the site included the volatile organic compounds (VOCs) tetrachloroethylene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene (DCE) and vinyl chloride (VC) in soil, groundwater and soil vapor. A vapor barrier and an Air Sparge/Soil Vapor Extraction System (AS/SVES) were installed and are operating on site to mitigate the remaining PCE and TCE contamination in soil vapor. Remaining contamination in soil and groundwater is being managed under a Site Management Plan. "

Health Problem: "Groundwater beneath the site is contaminated with volatile organic compounds (VOCs), primarily tetrachloroethene (PCE), at levels above NYS drinking water standards. There are no active public water supply wells within a one mile radius of the site and public exposure to contaminated groundwater is unlikely because all businesses and residences are supplied by public water. Exposure to contaminated soil is not expected since the site is covered by buildings and is paved. A vapor barrier and active soil vapor extraction system is at the site to prevent exposures from soil vapor intrusion. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-11-30 14:48:00
Record Upd: 2011-04-11 15:21:00
Updated By: IXMUNTEA
Own Op: 1
Sub Type: 06
Owner Name: John McDonald
Owner Company: The DOE Fund, Inc.
Owner Address: 345 East 102nd Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: John McDonald
Owner Company: Porter Avenue HDFC A DIV. OF DOE FUND Inc.
Owner Address: 345 EAST 102ND STREET, 3RD FLOOR
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10029
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: John McDonald
Owner Company: The DOE Fund, Inc.
Owner Address: 345 East 102nd Street, Third Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: V00409
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1,1,2-TETRACHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Waste Code: Not reported
Crossref ID: 00-TEMP-03-24(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: 2010000128456
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-04-13 14:06:00
Record Updated: 2011-04-13 14:06:00
Updated By: JHOCONNE

Name: CORNISH KNIT GOODS/CORNISH MINI-MILLS
Address: 121 INGRAHAM ST./89 PORTER AVE.
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58133
Control Name: Monitoring Plan
HW Code: V00409
Control Code: 31
Control Type: INST
Dt record added: 05/10/2010
Dt rec updated: 11/08/2021
Updated By: MXMAGLOI
Site Code: 58133
Site Description: "Location: The Cornish Knit Goods/Cornish Mini-Mills site is located at 89 Porter Avenue, Brooklyn, NY. The former address of this site was 121 Ingraham Street/89-111 Porter Ave. The 0.57 acre site is in East Williamsburg, an urban area of Brooklyn. The tax map identifies the site as Block 2993, Lot 1. The site is bordered by Porter Avenue to the west, by Ingraham Street to the south, by Joyva Candy Factory's parking lot to the east, and by Johnson Avenue to the north. Site Features: The site is completely covered by a four story building, which was renovated in order to be designated for restricted residential use. Current zoning/use(s): The site is in an area zoned M1-2, light manufacturing. The site building is currently operated as the Peter Jay Sharp Center for Opportunity (PJSCO). The building is used as shelter and rehabilitation center for homeless men. The surrounding parcels are currently used for a combination of commercial, industrial and residential. Historical Use(s): Until 1980 the property was operated by Cornish Knit Goods/Cornish Mini-Mills as a textile factory. From 1980 until 1995, the building was vacant, and it was illegally operated as a dry cleaning facility and as a stolen car scrap yard. In 2000, the property was owned by ABC Closing Corp. and the owner entered in a Voluntary Cleanup Agreement (VCA) with NYSDEC. In 2003, site ownership was transferred to Porter Avenue HDFC, a subsidiary of the DOE Fund, Inc., and the VCA was amended to reflect the change in ownership. Dry cleaning activities and uncontrolled disposal of waste solvents (perchloroethylene, or PCE, and its breakdown product trichloroethylene, or TCE) led to contamination of the soil and groundwater at the site. Site Geology and Hydrogeology: The surficial geology in the vicinity of the site is characterized by layered loose sediment. Soils recovered from the western portion of the site appear to be loose sands and sediments to approximately nine feet below ground surface (bgs) mixed with fill material such as gravels, brick, and old timbers. From 9 feet bgs to

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

	the top of the water table (approximately 13 feet bgs), soils are compact clays and sands. Soils recovered from drilling in the eastern portion of the site were characterized as fill. Groundwater depth ranges from 7 feet below ground surface (ft bgs) at the northwest portion of the site, 11-11.5 ft bgs across the western portion of the site, and 12-12.5 ft bgs across the southeast portion of the site. "
Env Problem:	"Nature and Extent of the Contamination: Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern at the site included the volatile organic compounds (VOCs) tetrachloroethylene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene (DCE) and vinyl chloride (VC) in soil, groundwater and soil vapor. A vapor barrier and an Air Sparge/Soil Vapor Extraction System (AS/SVES) were installed and are operating on site to mitigate the remaining PCE and TCE contamination in soil vapor. Remaining contamination in soil and groundwater is being managed under a Site Management Plan. "
Health Problem:	"Groundwater beneath the site is contaminated with volatile organic compounds (VOCs), primarily tetrachloroethene (PCE), at levels above NYS drinking water standards. There are no active public water supply wells within a one mile radius of the site and public exposure to contaminated groundwater is unlikely because all businesses and residences are supplied by public water. Exposure to contaminated soil is not expected since the site is covered by buildings and is paved. A vapor barrier and active soil vapor extraction system is at the site to prevent exposures from soil vapor intrusion. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2009-11-30 14:48:00
Record Upd:	2011-04-11 15:21:00
Updated By:	IXMUNTEA
Own Op:	1
Sub Type:	06
Owner Name:	John McDonald
Owner Company:	The DOE Fund, Inc.
Owner Address:	345 East 102nd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	John McDonald
Owner Company:	Porter Avenue HDFC A DIV. OF DOE FUND Inc.
Owner Address:	345 EAST 102ND STREET, 3RD FLOOR
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10029
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	John McDonald

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Owner Company: The DOE Fund, Inc.
Owner Address: 345 East 102nd Street, Third Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: V00409
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1,1,2-TETRACHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 00-TEMP-03-24(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: 2010000128456
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-04-13 14:06:00
Record Updated: 2011-04-13 14:06:00
Updated By: JHOCONNE

Name: CORNISH KNIT GOODS/CORNISH MINI-MILLS
Address: 121 INGRAHAM ST./89 PORTER AVE.
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58133
Control Name: Deed Restriction
HW Code: V00409
Control Code: A
Control Type: INST
Dt record added: 05/10/2010
Dt rec updated: 11/08/2021
Updated By: MXMAGLOI

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Site Code: 58133

Site Description: "Location: The Cornish Knit Goods/Cornish Mini-Mills site is located at 89 Porter Avenue, Brooklyn, NY. The former address of this site was 121 Ingraham Street/89-111 Porter Ave. The 0.57 acre site is in East Williamsburg, an urban area of Brooklyn. The tax map identifies the site as Block 2993, Lot 1. The site is bordered by Porter Avenue to the west, by Ingraham Street to the south, by Joyva Candy Factory's parking lot to the east, and by Johnson Avenue to the north. Site Features: The site is completely covered by a four story building, which was renovated in order to be designated for restricted residential use. Current zoning/use(s): The site is in an area zoned M1-2, light manufacturing. The site building is currently operated as the Peter Jay Sharp Center for Opportunity (PJSCO). The building is used as shelter and rehabilitation center for homeless men. The surrounding parcels are currently used for a combination of commercial, industrial and residential. Historical Use(s): Until 1980 the property was operated by Cornish Knit Goods/Cornish Mini-Mills as a textile factory. From 1980 until 1995, the building was vacant, and it was illegally operated as a dry cleaning facility and as a stolen car scrap yard. In 2000, the property was owned by ABC Closing Corp. and the owner entered in a Voluntary Cleanup Agreement (VCA) with NYSDEC. In 2003, site ownership was transferred to Porter Avenue HDFC, a subsidiary of the DOE Fund, Inc., and the VCA was amended to reflect the change in ownership. Dry cleaning activities and uncontrolled disposal of waste solvents (perchloroethylene, or PCE, and its breakdown product trichloroethylene, or TCE) led to contamination of the soil and groundwater at the site. Site Geology and Hydrogeology: The surficial geology in the vicinity of the site is characterized by layered loose sediment. Soils recovered from the western portion of the site appear to be loose sands and sediments to approximately nine feet below ground surface (bgs) mixed with fill material such as gravels, brick, and old timbers. From 9 feet bgs to the top of the water table (approximately 13 feet bgs), soils are compact clays and sands. Soils recovered from drilling in the eastern portion of the site were characterized as fill. Groundwater depth ranges from 7 feet below ground surface (ft bgs) at the northwest portion of the site, 11-11.5 ft bgs across the western portion of the site, and 12-12.5 ft bgs across the southeast portion of the site. "

Env Problem: "Nature and Extent of the Contamination: Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern at the site included the volatile organic compounds (VOCs) tetrachloroethylene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene (DCE) and vinyl chloride (VC) in soil, groundwater and soil vapor. A vapor barrier and an Air Sparge/Soil Vapor Extraction System (AS/SVES) were installed and are operating on site to mitigate the remaining PCE and TCE contamination in soil vapor. Remaining contamination in soil and groundwater is being managed under a Site Management Plan. "

Health Problem: "Groundwater beneath the site is contaminated with volatile organic compounds (VOCs), primarily tetrachloroethene (PCE), at levels above NYS drinking water standards. There are no active public water supply wells within a one mile radius of the site and public exposure to contaminated groundwater is unlikely because all businesses and residences are supplied by public water. Exposure to contaminated soil is not expected since the site is covered by buildings and is paved. A vapor barrier and active soil vapor extraction system is at

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

the site to prevent exposures from soil vapor intrusion. "
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-11-30 14:48:00
Record Upd: 2011-04-11 15:21:00
Updated By: IXMUNTEA
Own Op: 1
Sub Type: 06
Owner Name: John McDonald
Owner Company: The DOE Fund, Inc.
Owner Address: 345 East 102nd Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: John McDonald
Owner Company: Porter Avenue HDFC A DIV. OF DOE FUND Inc.
Owner Address: 345 EAST 102ND STREET, 3RD FLOOR
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10029
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: John McDonald
Owner Company: The DOE Fund, Inc.
Owner Address: 345 East 102nd Street, Third Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: V00409
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

HW Code: V00409
Waste Type: 1,1,1,2-TETRACHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 00-TEMP-03-24(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: 2010000128456
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-04-13 14:06:00
Record Updated: 2011-04-13 14:06:00
Updated By: JHOCONNE

Name: CORNISH KNIT GOODS/CORNISH MINI-MILLS
Address: 121 INGRAHAM ST./89 PORTER AVE.
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58133
Control Name: Landuse Restriction
HW Code: V00409
Control Code: 25
Control Type: INST
Dt record added: 05/10/2010
Dt rec updated: 11/08/2021
Updated By: MXMAGLOI
Site Code: 58133
Site Description: "Location: The Cornish Knit Goods/Cornish Mini-Mills site is located at 89 Porter Avenue, Brooklyn, NY. The former address of this site was 121 Ingraham Street/89-111 Porter Ave. The 0.57 acre site is in East Williamsburg, an urban area of Brooklyn. The tax map identifies the site as Block 2993, Lot 1. The site is bordered by Porter Avenue to the west, by Ingraham Street to the south, by Joyva Candy Factory's parking lot to the east, and by Johnson Avenue to the north. Site Features: The site is completely covered by a four story building, which was renovated in order to be designated for restricted residential use. Current zoning/use(s): The site is in an area zoned M1-2, light manufacturing. The site building is currently operated as the Peter Jay Sharp Center for Opportunity (PJSCO). The building is used as shelter and rehabilitation center for homeless men. The surrounding parcels are currently used for a combination of commercial, industrial and residential. Historical Use(s): Until 1980 the property was operated by Cornish Knit Goods/Cornish Mini-Mills as a textile factory. From 1980 until 1995, the building was vacant, and it was illegally operated as a dry cleaning facility and as a stolen car scrap yard. In 2000, the property was owned by ABC Closing Corp. and the owner entered in a Voluntary Cleanup Agreement (VCA) with NYSDEC. In 2003, site ownership was transferred to Porter Avenue HDFC, a subsidiary of the DOE Fund, Inc., and the VCA was amended to reflect the change in ownership. Dry cleaning activities and uncontrolled disposal of waste solvents (perchloroethylene, or PCE,

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

and its breakdown product trichloroethylene, or TCE) led to contamination of the soil and groundwater at the site. Site Geology and Hydrogeology: The surficial geology in the vicinity of the site is characterized by layered loose sediment. Soils recovered from the western portion of the site appear to be loose sands and sediments to approximately nine feet below ground surface (bgs) mixed with fill material such as gravels, brick, and old timbers. From 9 feet bgs to the top of the water table (approximately 13 feet bgs), soils are compact clays and sands. Soils recovered from drilling in the eastern portion of the site were characterized as fill. Groundwater depth ranges from 7 feet below ground surface (ft bgs) at the northwest portion of the site, 11-11.5 ft bgs across the western portion of the site, and 12-12.5 ft bgs across the southeast portion of the site. "

Env Problem: "Nature and Extent of the Contamination: Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern at the site included the volatile organic compounds (VOCs) tetrachloroethylene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene (DCE) and vinyl chloride (VC) in soil, groundwater and soil vapor. A vapor barrier and an Air Sparge/Soil Vapor Extraction System (AS/SVES) were installed and are operating on site to mitigate the remaining PCE and TCE contamination in soil vapor. Remaining contamination in soil and groundwater is being managed under a Site Management Plan. "

Health Problem: "Groundwater beneath the site is contaminated with volatile organic compounds (VOCs), primarily tetrachloroethene (PCE), at levels above NYS drinking water standards. There are no active public water supply wells within a one mile radius of the site and public exposure to contaminated groundwater is unlikely because all businesses and residences are supplied by public water. Exposure to contaminated soil is not expected since the site is covered by buildings and is paved. A vapor barrier and active soil vapor extraction system is at the site to prevent exposures from soil vapor intrusion. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-11-30 14:48:00
Record Upd: 2011-04-11 15:21:00
Updated By: IXMUNTEA
Own Op: 1
Sub Type: 06
Owner Name: John McDonald
Owner Company: The DOE Fund, Inc.
Owner Address: 345 East 102nd Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: John McDonald
Owner Company: Porter Avenue HDFC A DIV. OF DOE FUND Inc.

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Owner Address: 345 EAST 102ND STREET, 3RD FLOOR
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10029
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: John McDonald
Owner Company: The DOE Fund, Inc.
Owner Address: 345 East 102nd Street, Third Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: V00409
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1,1,2-TETRACHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 00-TEMP-03-24(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: 2010000128456
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-04-13 14:06:00
Record Updated: 2011-04-13 14:06:00
Updated By: JHOCONNE

Name: CORNISH KNIT GOODS/CORNISH MINI-MILLS
Address: 121 INGRAHAM ST./89 PORTER AVE.
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58133

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Control Name: O&M Plan
HW Code: V00409
Control Code: 33
Control Type: INST
Dt record added: 05/10/2010
Dt rec updated: 11/08/2021
Updated By: MXMAGLOI
Site Code: 58133
Site Description: "Location: The Cornish Knit Goods/Cornish Mini-Mills site is located at 89 Porter Avenue, Brooklyn, NY. The former address of this site was 121 Ingraham Street/89-111 Porter Ave. The 0.57 acre site is in East Williamsburg, an urban area of Brooklyn. The tax map identifies the site as Block 2993, Lot 1. The site is bordered by Porter Avenue to the west, by Ingraham Street to the south, by Joyva Candy Factory's parking lot to the east, and by Johnson Avenue to the north. Site Features: The site is completely covered by a four story building, which was renovated in order to be designated for restricted residential use. Current zoning/use(s): The site is in an area zoned M1-2, light manufacturing. The site building is currently operated as the Peter Jay Sharp Center for Opportunity (PJSCO). The building is used as shelter and rehabilitation center for homeless men. The surrounding parcels are currently used for a combination of commercial, industrial and residential. Historical Use(s): Until 1980 the property was operated by Cornish Knit Goods/Cornish Mini-Mills as a textile factory. From 1980 until 1995, the building was vacant, and it was illegally operated as a dry cleaning facility and as a stolen car scrap yard. In 2000, the property was owned by ABC Closing Corp. and the owner entered in a Voluntary Cleanup Agreement (VCA) with NYSDEC. In 2003, site ownership was transferred to Porter Avenue HDFC, a subsidiary of the DOE Fund, Inc., and the VCA was amended to reflect the change in ownership. Dry cleaning activities and uncontrolled disposal of waste solvents (perchloroethylene, or PCE, and its breakdown product trichloroethylene, or TCE) led to contamination of the soil and groundwater at the site. Site Geology and Hydrogeology: The surficial geology in the vicinity of the site is characterized by layered loose sediment. Soils recovered from the western portion of the site appear to be loose sands and sediments to approximately nine feet below ground surface (bgs) mixed with fill material such as gravels, brick, and old timbers. From 9 feet bgs to the top of the water table (approximately 13 feet bgs), soils are compact clays and sands. Soils recovered from drilling in the eastern portion of the site were characterized as fill. Groundwater depth ranges from 7 feet below ground surface (ft bgs) at the northwest portion of the site, 11-11.5 ft bgs across the western portion of the site, and 12-12.5 ft bgs across the southeast portion of the site. "
Env Problem: "Nature and Extent of the Contamination: Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern at the site included the volatile organic compounds (VOCs) tetrachloroethylene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene (DCE) and vinyl chloride (VC) in soil, groundwater and soil vapor. A vapor barrier and an Air Sparge/Soil Vapor Extraction System (AS/SVES) were installed and are operating on site to mitigate the remaining PCE and TCE contamination in soil vapor. Remaining contamination in soil and groundwater is being managed under a Site Management Plan. "
Health Problem: "Groundwater beneath the site is contaminated with volatile organic

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

compounds (VOCs), primarily tetrachloroethene (PCE), at levels above NYS drinking water standards. There are no active public water supply wells within a one mile radius of the site and public exposure to contaminated groundwater is unlikely because all businesses and residences are supplied by public water. Exposure to contaminated soil is not expected since the site is covered by buildings and is paved. A vapor barrier and active soil vapor extraction system is at the site to prevent exposures from soil vapor intrusion. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-11-30 14:48:00
Record Upd: 2011-04-11 15:21:00
Updated By: IXMUNTEA
Own Op: 1
Sub Type: 06
Owner Name: John McDonald
Owner Company: The DOE Fund, Inc.
Owner Address: 345 East 102nd Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: John McDonald
Owner Company: Porter Avenue HDFC A DIV. OF DOE FUND Inc.
Owner Address: 345 EAST 102ND STREET, 3RD FLOOR
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10029
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: John McDonald
Owner Company: The DOE Fund, Inc.
Owner Address: 345 East 102nd Street, Third Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: V00409
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1,1,2-TETRACHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 00-TEMP-03-24(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: 2010000128456
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-04-13 14:06:00
Record Updated: 2011-04-13 14:06:00
Updated By: JHOCONNE

Name: CORNISH KNIT GOODS/CORNISH MINI-MILLS
Address: 121 INGRAHAM ST./89 PORTER AVE.
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58133
Control Name: Ground Water Use Restriction
HW Code: V00409
Control Code: 08
Control Type: INST
Dt record added: 05/10/2010
Dt rec updated: 11/08/2021
Updated By: MXMAGLOI
Site Code: 58133
Site Description: "Location: The Cornish Knit Goods/Cornish Mini-Mills site is located at 89 Porter Avenue, Brooklyn, NY. The former address of this site was 121 Ingraham Street/89-111 Porter Ave. The 0.57 acre site is in East Williamsburg, an urban area of Brooklyn. The tax map identifies the site as Block 2993, Lot 1. The site is bordered by Porter Avenue to the west, by Ingraham Street to the south, by Joyva Candy Factory’s parking lot to the east, and by Johnson Avenue to the north. Site Features: The site is completely covered by a four story building, which was renovated in order to be designated for restricted residential use. Current zoning/use(s): The site is in an area zoned M1-2, light manufacturing. The site building is currently operated as the Peter Jay Sharp Center for Opportunity (PJSCO). The building is used as shelter and rehabilitation center for homeless men. The surrounding parcels are currently used for a combination of commercial, industrial and residential. Historical Use(s): Until 1980 the property was operated by Cornish Knit Goods/Cornish Mini-Mills as a textile factory. From 1980 until 1995, the building was vacant, and

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

it was illegally operated as a dry cleaning facility and as a stolen car scrap yard. In 2000, the property was owned by ABC Closing Corp. and the owner entered in a Voluntary Cleanup Agreement (VCA) with NYSDEC. In 2003, site ownership was transferred to Porter Avenue HDFC, a subsidiary of the DOE Fund, Inc., and the VCA was amended to reflect the change in ownership. Dry cleaning activities and uncontrolled disposal of waste solvents (perchloroethylene, or PCE, and its breakdown product trichloroethylene, or TCE) led to contamination of the soil and groundwater at the site. Site Geology and Hydrogeology: The surficial geology in the vicinity of the site is characterized by layered loose sediment. Soils recovered from the western portion of the site appear to be loose sands and sediments to approximately nine feet below ground surface (bgs) mixed with fill material such as gravels, brick, and old timbers. From 9 feet bgs to the top of the water table (approximately 13 feet bgs), soils are compact clays and sands. Soils recovered from drilling in the eastern portion of the site were characterized as fill. Groundwater depth ranges from 7 feet below ground surface (ft bgs) at the northwest portion of the site, 11-11.5 ft bgs across the western portion of the site, and 12-12.5 ft bgs across the southeast portion of the site. "

Env Problem: "Nature and Extent of the Contamination: Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern at the site included the volatile organic compounds (VOCs) tetrachloroethylene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene (DCE) and vinyl chloride (VC) in soil, groundwater and soil vapor. A vapor barrier and an Air Sparge/Soil Vapor Extraction System (AS/SVES) were installed and are operating on site to mitigate the remaining PCE and TCE contamination in soil vapor. Remaining contamination in soil and groundwater is being managed under a Site Management Plan. "

Health Problem: "Groundwater beneath the site is contaminated with volatile organic compounds (VOCs), primarily tetrachloroethene (PCE), at levels above NYS drinking water standards. There are no active public water supply wells within a one mile radius of the site and public exposure to contaminated groundwater is unlikely because all businesses and residences are supplied by public water. Exposure to contaminated soil is not expected since the site is covered by buildings and is paved. A vapor barrier and active soil vapor extraction system is at the site to prevent exposures from soil vapor intrusion. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-11-30 14:48:00
Record Upd: 2011-04-11 15:21:00
Updated By: IXMUNTEA
Own Op: 1
Sub Type: 06
Owner Name: John McDonald
Owner Company: The DOE Fund, Inc.
Owner Address: 345 East 102nd Street

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: John McDonald
Owner Company: Porter Avenue HDFC A DIV. OF DOE FUND Inc.
Owner Address: 345 EAST 102ND STREET, 3RD FLOOR
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10029
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: John McDonald
Owner Company: The DOE Fund, Inc.
Owner Address: 345 East 102nd Street, Third Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: V00409
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1,1,2-TETRACHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 00-TEMP-03-24(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: 2010000128456
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-04-13 14:06:00

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Record Updated: 2011-04-13 14:06:00
Updated By: JHOCONNE

Name: CORNISH KNIT GOODS/CORNISH MINI-MILLS
Address: 121 INGRAHAM ST./89 PORTER AVE.
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58133
Control Name: Site Management Plan
HW Code: V00409
Control Code: 32
Control Type: INST
Dt record added: 05/10/2010
Dt rec updated: 11/08/2021
Updated By: MXMAGLOI
Site Code: 58133
Site Description: "Location: The Cornish Knit Goods/Cornish Mini-Mills site is located at 89 Porter Avenue, Brooklyn, NY. The former address of this site was 121 Ingraham Street/89-111 Porter Ave. The 0.57 acre site is in East Williamsburg, an urban area of Brooklyn. The tax map identifies the site as Block 2993, Lot 1. The site is bordered by Porter Avenue to the west, by Ingraham Street to the south, by Joyva Candy Factory's parking lot to the east, and by Johnson Avenue to the north. Site Features: The site is completely covered by a four story building, which was renovated in order to be designated for restricted residential use. Current zoning/use(s): The site is in an area zoned M1-2, light manufacturing. The site building is currently operated as the Peter Jay Sharp Center for Opportunity (PJSCO). The building is used as shelter and rehabilitation center for homeless men. The surrounding parcels are currently used for a combination of commercial, industrial and residential. Historical Use(s): Until 1980 the property was operated by Cornish Knit Goods/Cornish Mini-Mills as a textile factory. From 1980 until 1995, the building was vacant, and it was illegally operated as a dry cleaning facility and as a stolen car scrap yard. In 2000, the property was owned by ABC Closing Corp. and the owner entered in a Voluntary Cleanup Agreement (VCA) with NYSDEC. In 2003, site ownership was transferred to Porter Avenue HDFC, a subsidiary of the DOE Fund, Inc., and the VCA was amended to reflect the change in ownership. Dry cleaning activities and uncontrolled disposal of waste solvents (perchloroethylene, or PCE, and its breakdown product trichloroethylene, or TCE) led to contamination of the soil and groundwater at the site. Site Geology and Hydrogeology: The surficial geology in the vicinity of the site is characterized by layered loose sediment. Soils recovered from the western portion of the site appear to be loose sands and sediments to approximately nine feet below ground surface (bgs) mixed with fill material such as gravels, brick, and old timbers. From 9 feet bgs to the top of the water table (approximately 13 feet bgs), soils are compact clays and sands. Soils recovered from drilling in the eastern portion of the site were characterized as fill. Groundwater depth ranges from 7 feet below ground surface (ft bgs) at the northwest portion of the site, 11-11.5 ft bgs across the western portion of the site, and 12-12.5 ft bgs across the southeast portion of the site. "
Env Problem: "Nature and Extent of the Contamination: Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern at the site included the volatile organic compounds (VOCs) tetrachloroethylene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

(DCE) and vinyl chloride (VC) in soil, groundwater and soil vapor. A vapor barrier and an Air Sparge/Soil Vapor Extraction System (AS/SVES) were installed and are operating on site to mitigate the remaining PCE and TCE contamination in soil vapor. Remaining contamination in soil and groundwater is being managed under a Site Management Plan. "

Health Problem: "Groundwater beneath the site is contaminated with volatile organic compounds (VOCs), primarily tetrachloroethene (PCE), at levels above NYS drinking water standards. There are no active public water supply wells within a one mile radius of the site and public exposure to contaminated groundwater is unlikely because all businesses and residences are supplied by public water. Exposure to contaminated soil is not expected since the site is covered by buildings and is paved. A vapor barrier and active soil vapor extraction system is at the site to prevent exposures from soil vapor intrusion. "
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-11-30 14:48:00
Record Upd: 2011-04-11 15:21:00
Updated By: IXMUNTEA
Own Op: 1
Sub Type: 06
Owner Name: John McDonald
Owner Company: The DOE Fund, Inc.
Owner Address: 345 East 102nd Street
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
Own Op: 4
Sub Type: E
Owner Name: John McDonald
Owner Company: Porter Avenue HDFC A DIV. OF DOE FUND Inc.
Owner Address: 345 EAST 102ND STREET, 3RD FLOOR
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10029
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: John McDonald
Owner Company: The DOE Fund, Inc.
Owner Address: 345 East 102nd Street, Third Floor
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10029
Owner Country: United States of America
HW Code: V00409
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: DICHLOROETHYLENE

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: METHYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: 1,1,1,2-TETRACHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00409
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 00-TEMP-03-24(I
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS
Crossref ID: 2010000128456
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-04-13 14:06:00
Record Updated: 2011-04-13 14:06:00
Updated By: JHOCONNE

VCP:
Name: CORNISH KNIT GOODS/CORNISH MINI-MILLS
Address: 121 INGRAHAM ST./89 PORTER AVE.
City,State,Zip: BROOKLYN, NY 11237
Program Type: VCP
Site Code: 58133
HW Code: V00409
Site Class: C
SWIS: 2401
Region: 2
Town: New York City
Acres: 0.570
Date Record Added: 11/30/2000
Date Record Updated: 07/09/2018
Updated By: MXMAGLOI
Site Description: "Location: The Cornish Knit Goods/Cornish Mini-Mills site is located at 89 Porter Avenue, Brooklyn, NY. The former address of this site was 121 Ingraham Street/89-111 Porter Ave. The 0.57 acre site is in East Williamsburg, an urban area of Brooklyn. The tax map identifies the site as Block 2993, Lot 1. The site is bordered by Porter Avenue to the west, by Ingraham Street to the south, by Joyva Candy Factory’s parking lot to the east, and by Johnson Avenue to the

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

north. Site Features: The site is completely covered by a four story building, which was renovated in order to be designated for restricted residential use. Current zoning/use(s): The site is in an area zoned M1-2, light manufacturing. The site building is currently operated as the Peter Jay Sharp Center for Opportunity (PJSCO). The building is used as shelter and rehabilitation center for homeless men. The surrounding parcels are currently used for a combination of commercial, industrial and residential. Historical Use(s): Until 1980 the property was operated by Cornish Knit Goods/Cornish Mini-Mills as a textile factory. From 1980 until 1995, the building was vacant, and it was illegally operated as a dry cleaning facility and as a stolen car scrap yard. In 2000, the property was owned by ABC Closing Corp. and the owner entered in a Voluntary Cleanup Agreement (VCA) with NYSDEC. In 2003, site ownership was transferred to Porter Avenue HDFC, a subsidiary of the DOE Fund, Inc., and the VCA was amended to reflect the change in ownership. Dry cleaning activities and uncontrolled disposal of waste solvents (perchloroethylene, or PCE, and its breakdown product trichloroethylene, or TCE) led to contamination of the soil and groundwater at the site. Site Geology and Hydrogeology: The surficial geology in the vicinity of the site is characterized by layered loose sediment. Soils recovered from the western portion of the site appear to be loose sands and sediments to approximately nine feet below ground surface (bgs) mixed with fill material such as gravels, brick, and old timbers. From 9 feet bgs to the top of the water table (approximately 13 feet bgs), soils are compact clays and sands. Soils recovered from drilling in the eastern portion of the site were characterized as fill. Groundwater depth ranges from 7 feet below ground surface (ft bgs) at the northwest portion of the site, 11-11.5 ft bgs across the western portion of the site, and 12-12.5 ft bgs across the southeast portion of the site. "

Env Problem: "Nature and Extent of the Contamination: Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern at the site included the volatile organic compounds (VOCs) tetrachloroethylene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene (DCE) and vinyl chloride (VC) in soil, groundwater and soil vapor. A vapor barrier and an Air Sparge/Soil Vapor Extraction System (AS/SVES) were installed and are operating on site to mitigate the remaining PCE and TCE contamination in soil vapor. Remaining contamination in soil and groundwater is being managed under a Site Management Plan. "

Health Problem: "Groundwater beneath the site is contaminated with volatile organic compounds (VOCs), primarily tetrachloroethene (PCE), at levels above NYS drinking water standards. There are no active public water supply wells within a one mile radius of the site and public exposure to contaminated groundwater is unlikely because all businesses and residences are supplied by public water. Exposure to contaminated soil is not expected since the site is covered by buildings and is paved. A vapor barrier and active soil vapor extraction system is at the site to prevent exposures from soil vapor intrusion. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2009-11-30 14:48:00
Record Upd:	2011-04-11 15:21:00
Updated By:	IXMUNTEA
Own Op:	1
Sub Type:	06
Owner Name:	John McDonald
Owner Company:	The DOE Fund, Inc.
Owner Address:	345 East 102nd Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	John McDonald
Owner Company:	Porter Avenue HDFC A DIV. OF DOE FUND Inc.
Owner Address:	345 EAST 102ND STREET, 3RD FLOOR
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10029
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	John McDonald
Owner Company:	The DOE Fund, Inc.
Owner Address:	345 East 102nd Street, Third Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10029
Owner Country:	United States of America
HW Code:	V00409
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	METHYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	VINYL CHLORIDE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	1,1,1,2-TETRACHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00409
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

CORNISH KNIT GOODS/CORNISH MINI-MILLS (Continued) **S110043685**

Crossref ID:	00-TEMP-03-24(I
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS
Crossref ID:	2010000128456
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2011-04-13 14:06:00
Record Updated:	2011-04-13 14:06:00
Updated By:	JHOCONNE

AJ201 **CORNISH MINI MILLS** **NY LTANKS** **S102232671**
South **121 INGRAHAM ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.346 mi.
1827 ft. **Site 2 of 4 in cluster AJ**

Relative: **Higher**

Actual: **17 ft.**

LTANKS:

Name:	CORNISH MINI MILLS
Address:	121 INGRAHAM ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9600503 / 1996-11-22
Facility ID:	9600503
Site ID:	239705
Spill Date:	1996-04-11
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1996-04-11
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-04-11
Spill Record Last Update:	2000-04-25
Spiller Name:	H2M GROUP
Spiller Company:	CORNISH MINI MILLS
Spiller Address:	121 INGRAHAM ST
Spiller County:	001
Spiller Contact:	H2M GROUP
Spiller Phone:	(516) 756-8000
Spiller Extention:	484
DEC Region:	2
DER Facility ID:	197159
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE HAS A PLATE THAT IS JUST BOLTED DOWN. NO SPILL."
Remarks:	"facility has two tank on site 5000 gal tank was not tested but deemed un testable"

CORNISH MINI MILLS (Continued) **S102232671**

All TTF:

Facility ID:	9600503
Spill Number:	9600503
Spill Tank Test:	1544470
Site ID:	239705
Tank Number:	1
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	01
Test Method 2:	Petro-Tite/Petro Comp
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	239705
Operable Unit ID:	1031931
Operable Unit:	01
Material ID:	353898
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AG202 **TANKS-A-LOT CO** **SEMS-ARCHIVE** **1003863743**
North **362 MASPETH AVE** **NYD980509228**
1/4-1/2 **BROOKLYN, NY 11211**
0.348 mi.
1840 ft. **Site 3 of 7 in cluster AG**

Relative:
Lower

Actual:
12 ft.

SEMS Archive:

Site ID:	0201827
EPA ID:	NYD980509228
Name:	TANKS-A-LOT CO
Address:	362 MASPETH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11211
Cong District:	12
FIPS Code:	36047
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	02
Site ID:	0201827
EPA ID:	NYD980509228

TANKS-A-LOT CO (Continued) **1003863743**

Site Name:	TANKS-A-LOT CO
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1980-07-01 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	02
Site ID:	0201827
EPA ID:	NYD980509228
Site Name:	TANKS-A-LOT CO
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1980-04-01 05:00:00
Finish Date:	1980-04-01 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0201827
EPA ID:	NYD980509228
Site Name:	TANKS-A-LOT CO
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	1980-07-01 04:00:00
Finish Date:	1980-07-01 04:00:00
Qual:	N
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0201827
EPA ID:	NYD980509228
Site Name:	TANKS-A-LOT CO
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1980-07-01 04:00:00
Qual:	L
Current Action Lead:	EPA Perf

AG203 **TANKS-A-LOT COMPANY** **NY HSWDS** **S108146424**
North **362 MASPETH AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11211**
0.348 mi.
1840 ft. **Site 4 of 7 in cluster AG**

Relative:
Lower

Actual:
12 ft.

HSWDS:

Facility ID:	Not reported
Region:	2
Facility Status:	Unknown
Owner Type:	Puplic
Owner:	David Calleia
Owner Address:	362 Maspeth Ave.
Owner Phone:	(212)647-0700
Operator Type:	Same
Operator:	Unknown
Operator:	Unknown
Operator Phone:	Unknown
EPA ID:	NYD000010024
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	None
RCRA Permitted:	Unknown
Site Code:	Leaking tanks, drums, lagoons, other containers
Owner City State:	Brooklyn
Operator City State:	Not reported
Quadrange:	Unknown
Latitude:	Unknown
Longitude:	Unknown
Acres:	0.00
Operator Date:	Unknown
Close Date:	Unknown
Completed:	Unknown
Active:	Not reported
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	No
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	None
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown
Groundwater Contamination:	Unknown
Groundwater Classification:	Unknown
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	Unknown

TANKS-A-LOT COMPANY (Continued) **S108146424**

Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

AG204 **BCF OIL REFINING, INC** **NY SWF/LF** **1001754932**
NNW **360 MASPETH AVENUE** **NY LTANKS** **N/A**
1/4-1/2 **BROOKLYN, NY 11211** **NY MOSF UST**
0.351 mi. **NY MOSF**
1852 ft. **Site 5 of 7 in cluster AG** **NY MOSF AST**
NY Spills
Relative: **NY SPDES**
Lower

Actual: **12 ft.**

SWF/LF:

Name:	BCF OIL REFINING INC.
Address:	360 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Flag:	INACTIVE
Region Code:	2
Phone Number:	7183879710
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	SALVATORE CORTESE
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported

BCF OIL REFINING, INC (Continued) **1001754932**

Contact Phone:	Not reported
Activity Desc:	Waste oil storage; reprocessing or rerefining facility
Activity Number:	[24O59]
Active:	No
East Coordinate:	Not reported
North Coordinate:	Not reported
Accuracy Code:	1 - No accuracy stated
Regulatory Status:	None
Waste Type:	Not reported
Authorization #:	2-6101-00075
Authorization Date:	8/21/1992
Expiration Date:	8/21/1995
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

LTANKS:

Name:	BCF REFINING
Address:	360 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9008251 / 2003-09-02
Facility ID:	9008251
Site ID:	80010
Spill Date:	1990-09-25
Spill Cause:	Tank Failure
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Class:	A1
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1990-10-26
CID:	Not reported
Water Affected:	ENGLISH KILLS
Spill Notifier:	Federal Government
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-11-05
Spill Record Last Update:	2003-09-02
Spiller Name:	Not reported
Spiller Company:	BCF OIL REFINING
Spiller Address:	360 MASPETH AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	74202
DEC Memo:	""
Remarks:	"SLICK OF OIL APPROX 8FT X 2FT FOUND ON SHORELINE ADJACENT TO PROPERTY,GROUND SATURATED WITH OIL, DEPLOYED BOOM, NYCDEP AT SCENE."

All Materials:

Site ID:	80010

BCF OIL REFINING, INC (Continued) **1001754932**

Operable Unit ID: 945466
Operable Unit: 01
Material ID: 562071
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: BCF OIL REFINING
Address: 360 MASPETH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9112627 / 2003-09-02
Facility ID: 9112627
Site ID: 211456
Spill Date: 1992-03-11
Spill Cause: Tank Failure
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Class: A1
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1992-03-11
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1992-03-11
Spill Record Last Update: 2003-09-02
Spiller Name: SAL CORTESE
Spiller Company: BCF OIL REFINNING, INC.
Spiller Address: 360 MASPETH AVENUE
Spiller County: 001
Spiller Contact: SAL CORTESE
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 74202
DEC Memo: ""
Remarks: "MOSF # 02-2600; PRODUCT DISCOVERED IN MONITORING WELL # 1"

All Materials:
Site ID: 211456
Operable Unit ID: 966221
Operable Unit: 01
Material ID: 414191
Material Code: 0009
Material Name: gasoline
Case No.: Not reported

BCF OIL REFINING, INC (Continued) **1001754932**

Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: True

Site ID: 211456
Operable Unit ID: 966221
Operable Unit: 01
Material ID: 572806
Material Code: 1213A
Material Name: MTBE (methyl-tert-butyl ether)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: True

Site ID: 211456
Operable Unit ID: 966221
Operable Unit: 01
Material ID: 414192
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: True

MOSF UST:
Id/Status: 2-2600 / INACTIVE FACILITY
SWIS Code: 61
Facility Town: Not reported
Contact Phone: (718) 387-9710
Emergency Contact: SALVATORE CORTESE
Emergency Telephone: (718) 387-9710
CBS Number: Not reported
SPDES Num: 0-036609
Total Tanks: 19
Total Capacity: 780574
Avg Throughput: 20000
License Stat: 3
Facility Type: APARTMENT BUILDING
Prod Xfer Options: Tank Truck
Expiration Date: / /
Applic Rcvd: 02/09/1995
Operator: SALVATORE CORTESE
Owner Name: BCF OIL REFINING, INC
Owner Address: 360 MASPETH AVENUE
Owner City,St,Zip: BROOKLYN, NY 11211-
Owner Telephone: (718) 387-9710
Owner Type: Corporate/Commercial
Owner Status: 1

BCF OIL REFINING, INC (Continued) **1001754932**

Owner Mark:	First Owner
Mail To Name:	BCF OIL REFINING, INC
Mail To Address:	360 MASPETH AVENUE
Mail To Address 2:	Not reported
Mail City,St,Zip:	BROOKLYN, NY 11211-
Mail To Contact:	SALVATORE CORTESE
Mail To Telephone:	(718) 387-9710
Legal Agent Name:	GILBERT WALLACH, ESQ.
Legal Agent Address:	50 BROADWAY-25 FLOOR
Legal Agent City,St,Zip:	NEW YORK, NY 10004-
Date Filed:	00/86
Latitude:	40|43|40
Longitude:	73|54|52

Tank ID:	01
Tank Location:	UNDERGROUND
Install Date:	04/82
Capacity (Gal):	20000
Product:	UNKNOWN
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Wrapped (Piping)
Second Contain:	Diking
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	05/93
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/09/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	/ /
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/03/1995
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	02
Tank Location:	UNDERGROUND
Install Date:	04/82
Capacity (Gal):	20000
Product:	UNKNOWN
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON

BCF OIL REFINING, INC (Continued) **1001754932**

Pipe Internal: None
Pipe External: Wrapped (Piping)
Second Contain: Diking
Leak Detection: None
Overfill Protection: High Level Alarm
Dispenser: Suction
Test Date: 05/93
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 07/09/1999
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: / /
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/03/1995
Federal Id No: Not reported
COI Date: / /

Tank ID: 03
Tank Location: UNDERGROUND
Install Date: 04/82
Capacity (Gal): 20000
Product: UNKNOWN
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Wrapped (Piping)
Second Contain: Diking
Leak Detection: None
Overfill Protection: High Level Alarm
Dispenser: Suction
Test Date: 06/94
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 07/09/1999
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: / /
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/03/1995
Federal Id No: Not reported
COI Date: / /

Tank ID: 04
Tank Location: UNDERGROUND
Install Date: 04/82
Capacity (Gal): 20000

BCF OIL REFINING, INC (Continued) **1001754932**

Product:	UNKNOWN
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Wrapped (Piping)
Second Contain:	Diking
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/09/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	/ /
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/03/1995
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	05
Tank Location:	UNDERGROUND
Install Date:	04/82
Capacity (Gal):	20000
Product:	UNKNOWN
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Wrapped (Piping)
Second Contain:	Diking
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	05/93
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/09/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	/ /
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/03/1995
Federal Id No:	Not reported

BCF OIL REFINING, INC (Continued) **1001754932**

COI Date: / /

Tank ID: 06
Tank Location: UNDERGROUND
Install Date: 04/82
Capacity (Gal): 20000
Product: UNKNOWN
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Wrapped (Piping)
Second Contain: Diking
Leak Detection: None
Overfill Protection: High Level Alarm
Dispenser: Suction
Test Date: Not reported
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 07/09/1999
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: / /
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/03/1995
Federal Id No: Not reported
COI Date: / /

Tank ID: 07
Tank Location: UNDERGROUND
Install Date: 04/82
Capacity (Gal): 20000
Product: UNKNOWN
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Wrapped (Piping)
Second Contain: Diking
Leak Detection: None
Overfill Protection: High Level Alarm
Dispenser: Suction
Test Date: 06/94
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 07/09/1999
Inspector Initials: AS

BCF OIL REFINING, INC (Continued) **1001754932**

Inspector Status: Not reported
Pipe Flag: True
License Issued: / /
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/03/1995
Federal Id No: Not reported
COI Date: / /

Tank ID: 08
Tank Location: UNDERGROUND
Install Date: 04/82
Capacity (Gal): 20000
Product: UNKNOWN
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Wrapped (Piping)
Second Contain: Diking
Leak Detection: None
Overfill Protection: High Level Alarm
Dispenser: Suction
Test Date: Not reported
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 07/09/1999
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: / /
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/03/1995
Federal Id No: Not reported
COI Date: / /

Tank ID: 09
Tank Location: UNDERGROUND
Install Date: 04/82
Capacity (Gal): 20000
Product: UNKNOWN
Tank Status: In Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: Painted/Asphalt Coating
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: Wrapped (Piping)
Second Contain: Diking
Leak Detection: None

BCF OIL REFINING, INC (Continued) **1001754932**

Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/09/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	/ /
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/03/1995
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	10
Tank Location:	UNDERGROUND
Install Date:	01/89
Capacity (Gal):	6000
Product:	UNKNOWN
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Wrapped (Piping)
Second Contain:	Diking
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	05/93
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/09/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	/ /
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/03/1995
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	15
Tank Location:	UNDERGROUND
Install Date:	04/82
Capacity (Gal):	50000
Product:	NOS 5 OR 6 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None

BCF OIL REFINING, INC (Continued) **1001754932**

Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	Diking
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	05/93
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/09/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	/ /
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/03/1995
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	16
Tank Location:	UNDERGROUND
Install Date:	04/82
Capacity (Gal):	100000
Product:	NOS 5 OR 6 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	Diking
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/09/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	/ /
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/03/1995
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	18

BCF OIL REFINING, INC (Continued) **1001754932**

Tank Location:	UNDERGROUND
Install Date:	04/85
Capacity (Gal):	4000
Product:	DIESEL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Wrapped (Piping)
Second Contain:	None
Leak Detection:	None
Overfill Protection:	None
Dispenser:	Suction
Test Date:	06/94
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/09/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	/ /
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/03/1995
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	19
Tank Location:	UNDERGROUND
Install Date:	00/00
Capacity (Gal):	550
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	In Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	07/09/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	/ /
Vessel Id:	Not reported

BCF OIL REFINING, INC (Continued) **1001754932**

Renew Flag: True
Renew Date: 11/03/1995
Federal Id No: Not reported
COI Date: / /

MOSF:
Name: BCF OIL REFINING, INC
Address: 360 MASPETH AVENUE
City,State,Zip: BROOKLYN, NY 11211
Facility ID: 2-2600
Program Type: MOSF
Tank Status: Inactive
Expiration Date: Not reported
Dec Region: 2
UTMX: 590372.16955
UTMY: 4508045.77666

MOSF AST:
MOSF Number: 2-2600
SWIS Code: 61
Facility Town: Not reported
Facility Phone: (718) 387-9710
Emergency Contact Name: SALVATORE CORTESE
Emergency Contact Phone: (718) 387-9710
Total Tanks: 19
Total Capacity: 780574
Daily Throughput: 20000
License Status: 3
Facility Type: APARTMENT BUILDING
Product Transfer Operation: Tank Truck
Facility Status: TEMPORARILY OUT-OF-SERVICE
Operator Name: SALVATORE CORTESE
Owner Name: BCF OIL REFINING, INC
Owner Address: 360 MASPETH AVENUE
Owner City,St,Zip: BROOKLYN, NY 11211-
Owner Phone: (718) 387-9710
Owner Type: Corporate/Commercial
Owner Status: 1
Owner Mark: First Owner
Mailing Name: BCF OIL REFINING, INC
Mailing Address: 360 MASPETH AVENUE
Mailing Address 2: Not reported
Mailing City,St,Zip: BROOKLYN, NY 11211-
Mailing Contact: SALVATORE CORTESE
Mailing Phone: (718) 387-9710
Legal Agent Name: GILBERT WALLACH, ESQ.
Legal Agent Address: 50 BROADWAY-25 FLOOR
Legal Agent City,St,Zip: NEW YORK, NY 10004-
LIC Expires: / /

Tank ID: 11
Tank Location: ABOVEGROUND
Install Date: 04/33
Product: NOS 5 OR 6 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None

BCF OIL REFINING, INC (Continued) **1001754932**

Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Wrapped (Piping
Secondary Containment:	Concrete Dike
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispensing Mthd:	Suction
Test Date:	05/93
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	110000
Lat/Long:	40|43|40 / 73|54|52
Federal ID:	Not reported
Inspected Date:	07/09/1999
Inspector:	AS
Renew Date:	11/03/1995
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	In Service
COI Date:	/ /
Date License Issued:	/ /
Date License Application Received:	02/09/1995
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-036609
Date Legal Agent Filed with Secretary of State:	00/86

Tank ID:	12
Tank Location:	ABOVEGROUND
Install Date:	04/33
Product:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Wrapped (Piping
Secondary Containment:	Concrete Dike
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispensing Mthd:	Suction
Test Date:	05/93
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	110000
Lat/Long:	40|43|40 / 73|54|52
Federal ID:	Not reported
Inspected Date:	07/09/1999
Inspector:	AS
Renew Date:	11/03/1995
Inspected State:	Not reported
Pipe Flag:	True

BCF OIL REFINING, INC (Continued) **1001754932**

Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	In Service
COI Date:	/ /
Date License Issued:	/ /
Date License Application Received:	02/09/1995
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-036609
Date Legal Agent Filed with Secretary of State:	00/86

Tank ID:	14
Tank Location:	ABOVEGROUND
Install Date:	04/33
Product:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Wrapped (Piping
Secondary Containment:	Concrete Dike
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispensing Mthd:	Suction
Test Date:	05/93
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	110000
Lat/Long:	40|43|40 / 73|54|52
Federal ID:	Not reported
Inspected Date:	07/09/1999
Inspector:	AS
Renew Date:	11/03/1995
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	In Service
COI Date:	/ /
Date License Issued:	/ /
Date License Application Received:	02/09/1995
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-036609
Date Legal Agent Filed with Secretary of State:	00/86

Tank ID:	17
Tank Location:	ABOVEGROUND
Install Date:	04/51
Product:	NOS 5 OR 6 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron

BCF OIL REFINING, INC (Continued) **1001754932**

Pipe Internal:	None
Pipe External:	None
Secondary Containment:	Concrete Dike
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispensing Mthd:	Suction
Test Date:	06/94
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	110000
Lat/Long:	40|43|40 / 73|54|52
Federal ID:	Not reported
Inspected Date:	07/09/1999
Inspector:	AS
Renew Date:	11/03/1995
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	In Service
COI Date:	/ /
Date License Issued:	/ /
Date License Application Received:	02/09/1995
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-036609
Date Legal Agent Filed with Secretary of State:	00/86

Tank ID:	20
Tank Location:	ABOVEGROUND
Install Date:	04/82
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Dispensing Mthd:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	24
Lat/Long:	40|43|40 / 73|54|52
Federal ID:	Not reported
Inspected Date:	07/09/1999
Inspector:	AS
Renew Date:	11/03/1995
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	In Service

BCF OIL REFINING, INC (Continued) **1001754932**

COI Date: / /
Date License Issued: / /
Date License Application Received: 02/09/1995
Chemical Bulk Storage Number: Not reported
Pollution Discharge Elimination System Num: 0-036609
Date Legal Agent Filed with Secretary of State: 00/86

SPILLS:
Name: BCF OIL
Address: 360 MASPETH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9700680 / 1997-04-16
Facility ID: 9700680
Facility Type: ER
DER Facility ID: 74202
Site ID: 211457
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: A1
SWIS: 2401
Spill Date: 1997-04-15
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1997-04-15
CID: 369
Water Affected: ENGLISH KILLS
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Federal Government
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1997-04-15
Spill Record Last Update: 2003-09-02
Spiller Name: SAL CORTESE
Spiller Company: BCF OIL FACILITY
Spiller Address: 360 MASPETH AVENUE
Spiller Company: 001
Contact Name: SAL CORTESE
DEC Memo: ""
Remarks: "USCG received notice from DEC Hussein- Report of a continuous discharge to Waterbody."

All Materials:
Site ID: 211457
Operable Unit ID: 1046964
Operable Unit: 01
Material ID: 337272
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00

BCF OIL REFINING, INC (Continued) **1001754932**

Oxygenate: Not reported

Name: BCF OIL REFINING INC
Address: 360 MASPETH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 8910891 / 1990-02-16
Facility ID: 8910891
Facility Type: ER
DER Facility ID: 74202
Site ID: 211455
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: A1
SWIS: 2401
Spill Date: 1990-02-14
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1990-02-14
CID: Not reported
Water Affected: ENGLISH KILLS
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Federal Government
Cleanup Ceased: 1990-02-16
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1990-02-28
Spill Record Last Update: 2003-09-02
Spiller Name: SAL CORTESE
Spiller Company: BCF OIL INC.
Spiller Address: 360 MASPETH AVE
Spiller Company: 001
Contact Name: SAL CORTESE
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE DEC referred this site cleanup to USEPA for RCRA Cleanup action. This spill site cleanup has been consolidated under Spill No. 9406807. "
Remarks: "USCG ON SCENE-BCF TO DO CLEAN UP"

All Materials:
Site ID: 211455
Operable Unit ID: 937875
Operable Unit: 01
Material ID: 440442
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: BCF OIL

BCF OIL REFINING, INC (Continued) **1001754932**

Address:	360 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9700679 / 2003-09-02
Facility ID:	9700679
Facility Type:	ER
DER Facility ID:	74202
Site ID:	286994
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	A1
SWIS:	2401
Spill Date:	1997-04-15
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1997-04-15
CID:	211
Water Affected:	ENGLISH KILLS
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-04-15
Spill Record Last Update:	2003-09-02
Spiller Name:	SAL CORTESE
Spiller Company:	BCF OIL
Spiller Address:	360 MASPETH AV
Spiller Company:	001
Contact Name:	SAL CORTESE
DEC Memo:	""
Remarks:	"Company is cleaning tanks for inspection and discharge pipes are leaking water and PCB oil mixture - Pipe 1 discharging at 1 GPM & Pipe 2 discharging at 5 GPM the discharge is to English Kills"

All Materials:

Site ID:	286994
Operable Unit ID:	1046962
Operable Unit:	01
Material ID:	337271
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	286994
Operable Unit ID:	1046962
Operable Unit:	01
Material ID:	337270
Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported

BCF OIL REFINING, INC (Continued) **1001754932**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BCF OIL REFINING INC.
Address:	360 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9403829 / 2003-09-02
Facility ID:	9403829
Facility Type:	ER
DER Facility ID:	74202
Site ID:	80011
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	A1
SWIS:	2401
Spill Date:	1994-06-17
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1994-06-17
CID:	Not reported
Water Affected:	ENGLISH KILLS
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-09-26
Spill Record Last Update:	2004-06-07
Spiller Name:	Not reported
Spiller Company:	BCF OIL REFINING, INC.
Spiller Address:	360 MASPETH AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"USCG NIOTIFIED DEC OF OIL CONTAMINATION AT SPDES OUTFALL, AND ALONG THE SHORELINE OF THE ENGLISH KILLS. USCG REQUESTED BOOMING. DEC INVESTIGATED WITH DEP. DEC SIGONA HIRED MILRO TO CLEANOUT OWS."

All Materials:

Site ID:	80011
Operable Unit ID:	1000808
Operable Unit:	01
Material ID:	383992
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BCF OIL REFINING, INC (Continued) **1001754932**

Name:	BCF OIL REFINING INC
Address:	360 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8701849 / 1987-06-10
Facility ID:	8701849
Facility Type:	ER
DER Facility ID:	74202
Site ID:	80009
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	A1
SWIS:	2401
Spill Date:	1987-06-04
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1987-06-04
CID:	Not reported
Water Affected:	FLUSHING BAY
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Federal Government
Cleanup Ceased:	1987-06-10
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-06-05
Spill Record Last Update:	2003-09-19
Spiller Name:	SAL CORTESE
Spiller Company:	BCF OIL
Spiller Address:	360 MASPETH AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"MALFUNCTION IN THE OIL/WATER SEPARATOR. USCG ON THE SCENE."

All Materials:

Site ID:	80009
Operable Unit ID:	906265
Operable Unit:	01
Material ID:	471741
Material Code:	1721A
Material Name:	spdes discharge
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	80009
Operable Unit ID:	906265
Operable Unit:	01
Material ID:	471740
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

BCF OIL REFINING, INC (Continued) **1001754932**

Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BCF OIL REFINERY, INC
Address:	360 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9406807 / 2014-10-29
Facility ID:	9406807
Facility Type:	ER
DER Facility ID:	74202
Site ID:	80012
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	A1
SWIS:	2401
Spill Date:	1994-08-19
Investigator:	AXDORONO
Referred To:	Not reported
Reported to Dept:	1994-08-19
CID:	Not reported
Water Affected:	ENGLISH KILL
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-10-20
Spill Record Last Update:	2014-10-29
Spiller Name:	Not reported
Spiller Company:	BCF OIL REFINERY, INC
Spiller Address:	360 MASPETH AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 04/25/95: SEE SPILL #9403829. DEC (Sigona) issued a hazardous waste cleanup contractor on 3/27/2000 under H0413. DEC referred this site cleanup to USEPA for RCRA Cleanup action. This spill site cleanup has been consolidated under Spill No. 9406807. 4/21/04 - Spill manager's name switched to Tipple from Sigona. 8/23/04 - Raphael Ketani. Case transferred to Jeff Vought. 7/3/12 - Austin - A synopsis to date of the basic activities on this site: Region 2 Spills staff did a PIN project on this site in the 1990s when it was abandoned by the owner, who found PCBS in his stored waste oil tanks. We re-diverted the storm drainage away from the storage tanks to prevent an overflow condition, and secured the site. The EPA then came in, and did a Superfund emergency removal of the hot oil from the tanks. They gave it back to DEC for a NYS Superfund investigation. After Jim Quinn's section did their Superfund investigation of the site, they found there were no hazardous wastes (PCBs) in the ground/groundwater. The original oil spill report, #9406807 (the one of this record), was closed in the interim by Kevin

BCF OIL REFINING, INC (Continued) **1001754932**

Hale, since it was in the State Superfund program. There is still petroleum g.w. contamination from the waste oil operations, so we need to re-open this spill report (#9406807), and assign it to one of our Remediation staff in Region 2 to continue the investigation, presumably under a PIN project. I have done so, by transferring this spill to Vadim Brevedo's section (Remediation Section B , as per the Regional Remediation Engineer. DEC Brevdo will assign this site to a project manager in his section for review and determination of further action. - end 02/12/2013: This spill case was transferred to A. Doronova. - AD Looked for property information on PropertyShark and NYC ACRIS database. According to the results: this property was sold by City of NY in 2006 to Newtown Development LLC. The property was bought at foreclosure. The Newtown Development company was represented by an attorney - Seth Friedland of Friedland Laifer & Robbins, LLP. Address of attorney: 62 William Street, 3rd Floor New York, NY 10005 Phone: 212-344-1400 Called and left a message to Mr. Friedland on his voicemail. Did not find on the Internet any other contact info for Newtown Development LLC. There is no listing for Newtown Development LLC on Department of State's Division of Corporations database. There is a company with a similar name - Newtown Development Group LLC. The company address is: Newtown Development Group LLC 2208 Astoria Blvd. Astoria, NY Phone: (718)545-1850 Called on the listed phone and left a message. Later in the day called and left a message with a secretary of Mr. Friedland. She told me that Newtown Development LLC is still their client. 1:12 PM - Received a call from Mr. Friedland. He told me that the site was cleaned by DEC and they had some kind of agreement with the state that the site will be remediated before purchasing it in 2006. Asked him to submit this agreement and also asked him for RP contact information. He said that he will speak with his client and get back to us in a day. AD 02/13/2013: Received a message from Mr. Friedland. Called and spoke with him. Mr. Friedland was authorized by the property owner to represent him in this case. CEUS Env. will probably be a consultant for the site. Mr. Friedland will confirm it later. He gave the address and contact info of the owner of the site: Marcello Porcelli - president Newtown Development, LLC c/o Fabrizio Realty 364 Maspeth Ave, Brooklyn, NY phone: (718) 782-4200 Mr. Friedland asked for next course of actions required by DEC. Told him that after I review the case file I will issue a letter to his client with a request for further actions depending on soil and groundwater data. Told him to file FOIL request in a meantime to get site-related data. Mr. Friedland will e-mail me a copy of the comfort letter his client received from DEC. Put site priority as P0. AD 02/25/2013: Reviewed the 2009 Investigation Report. The highest concentration of TVOCs is in shoreline sample point PW-1 at 1200 ppb detected in October 2007. Called and left a message to Mr. Friedland. AD 02/26/2013: Called and spoke with Mr. Friedland regarding the site reconnaissance. Requested to inspect all site-related wells and to collect groundwater samples, then based on the result to propose next course of actions. Later in the day received the following e-mail from Mr. Fridland: Dear Ms. Doronova: As just discussed, you advised me that you reviewed the latest available sampling data in NYSDEC's records for this site which are from 2009. Because of the age of those results, you have requested that more current sampling results from the above site be obtained and submitted. You also indicated that the readings in the files were relatively modest with one of the highest reading in the range of 1,300 parts. In this regard, you have requested that our

BCF OIL REFINING, INC (Continued) **1001754932**

client's consultant do the following: " Inspect the wells for sampling ability and determine the status of the wells (you said you thought there were 17 wells on the site); " Sample groundwater from the wells for VOC's and SVOC's which would relate to fuel oil and PCB's; " Upon the consultant's review and analysis of the sampling results, you would like the consultant to submit a Site Sampling Status Report documenting the sampling results. " In the Site Sampling Status Report, depending on the sampling results, you would also like the consultant to recommend a course of action ranging from a request for spill closure, to continued monitoring and natural attenuation, or another method of remediation that will lead to closure, as recommended by our consultant. Please review my summary above and kindly either confirm my understanding above, or add any other language modifications to this email that you feel are appropriate. Once I receive your response hereto, I will arrange for authority for the consultant to perform the required tasks. Thanks again for your cooperation and assistance. Regards. Sent from my BlackBerry Seth D. Friedland Friedland Laifer & Robbins, LLP 62 William Street New York, New York 10005 T 212.344.1400 x. 202 F 212.344.8735 C 917.902.6386 Efax 646.304.1916 email: sfriedland@friedlandlaifer Sent an e-mail to Mr. Friedland confirming the course of actions. AD 03/06/2013: Received the following e-mail from Mr. Friedland: Dear Ms. Doronova, Our client's consultants went to the site to inspect the wells as you requested. They were able to locate and identify approximately 7 or 8 wells so far. Also, the BCF site has been used as an impound lot by New York City for the parking of cars for the last year or so, so it may have been difficult for the consultants to locate some of the wells because of the presence of parked cars. Can you send me a copy of the well map you had reviewed so the consultants can try to reconcile the current site conditions with the site plan in your files. Thanks very much. Sent from my BlackBerry Seth D. Friedland Friedland Laifer & Robbins, LLP Sent the requested site plans. AD 06/03/2013: Sent an e-mail to Mr. Frieland with a request for site status update info. Requested to submit a summary report by end of June. Later in the day received the following e-mail from Mr. Frieland: Ms. Doronova, I know they are working on trying to finalize the report, but the consultants have a couple of questions. Would it be possible to discuss the report questions before they finalize and submit it in order to expedite the process? I can arrange a telephone call with them at a mutually convenient time if ok with you. Thanks for your patience. Seth D. Friedland Gave him time when I am avalable to take conference call. AD 06/04/2013: Finalized time for the conference call for 1:30 PM for June 6, 2013. AD 06/06/2013: received an e-mail from Mr. Friedland with some site maps from the new report. Had a conference call with Mr. Friedland and his consultant. Discussed the new groundwater data and issues with report presentation. The complete report will be submitted to DEC as scheduled by June 30, 2013. AD 06/28/2013: Received the following e-mail from John Rhodes of CEUS Engineering: Ms. Doronova, Attached is the Site Sampling Report and Petition for Closure of NYSDEC Spill Number 9406807 for the former BCF Site. I am also sending this report to you next week in hard copy with a CD containing the report. Please confirm receipt. Thank you for your assistance on this project, John A. Rhodes, P.E., F.NSPE CEUS Engineering, P.C. NJ: 5 Bedford Place, Morristown, 07960 NY: 62 William Street, 3rd Floor, New York, 10005 646 465 2494 DL the report to eDocs. Will review. AD 08/09/2013: Reviewed the report. It states

BCF OIL REFINING, INC (Continued) **1001754932**

that the Site was an Inactive Hazardous Waste Site investigated and cleaned-up through a cooperative arrangement between the NYSDEC, New York City (NYC), the United States Environmental Protection Agency (EPA) and a purchaser of the property, Newtown Development, LLC (NDL) to convert an abandoned hazardous waste site back to a beneficial use. According to the report, as part of the cooperative arrangement, the following have been accomplished: - The NYSDEC responded to discharges of petroleum from the former BCF facility, closed an oil water separator, cleaned up surface debris, supervised and funded a Demonstration of Method Applicability Study (DMA) and a Remedial Investigation (RI), led the Traid team during the RI, partnered with NDL to allow the innocent landowner purchase of the Site, and provided the successful regulatory framework and oversight for the project that led to the current status. - The EPA transferred their CERCLA oversight role to the NYSDEC, subordinated a lien against the property so that NDL could move forward to purchase the property and the remediation move forward, provided the expertise for the Triad approach including participation on the Triad team, provided the regulatory framework and oversight for the decontamination of the steel that otherwise would have been TOSCA waste, and performed an emergency removal action that included cleaning and closure of numerous tanks containing PCB laden oils. - The NYSDEC along with EPA, NYC and NDL led the development of the cooperative arrangement as part of the City s and State s interest in economic development and repatriation of contaminated and abandoned property, coordinated local regulatory and other support for the project, participated on the Triad team and promoted the successful approach to cleaning-up the Site to others addressing contaminated properties in NYC. - NDL (along with NYSDEC and NYC) led the conceptual development of the cooperative arrangement, purchased and funded the property allowing the entire enterprise to move forward, demolished the above ground structures, decontaminated and recycled the steel from tanks and piping; identified, leased to and interfaced with an industrial operation on the property (the impound lot operations for NYC s Marshal s operations), covered and leveled the ground with inch quarry stone, and managed the property to allow all other parties (EPA, NYSDEC, Triad team) to do what they needed to do. NDL is now addressing the residual petroleum (fuel oil) contamination issue brought to NDL s attention by NYSDEC as a continuing obligation to which they agreed as part of the cooperative arrangement and in continued cooperation with the NYSDEC, now through the Region 2 office. 2013 GW sampling: The report states that in February and March of 2013 contractors for NDL conducted groundwater sampling and testing and related activities in accordance with the plan approved by the Region 2 office. The 2013 follow?up groundwater elevation measurements and testing confirmed the southerly flow direction of groundwater from the southern portion of the Site. Additionally, through an examination of the construction of the retaining wall and elevations of the underlying clay layer we confirmed that the retaining wall was keyed into the clay and thereby inhibiting direct impacts on the English Kill from the petroleum release on the Site. The monitoring wells in the southern portion of the Site are representative of downgradient groundwater conditions to the north of the Site. GW data - SVOCs in GW: Naphthalene was not above this groundwater standard in the 2013 follow up testing.The consultant recommends no further action regarding the SVOC contaminants detected at the Site. BTEX: The NYSDEC noted BTEX compounds (benzene, toluene,

BCF OIL REFINING, INC (Continued) **1001754932**

ethylbenzene and xylene) in most of the wells on the properly exceeding their respective Class GA Groundwater standard. The concentrations of BTEX compounds in the 2013 testing were consistent with the concentrations in the RI testing (2009), with improvement but also localized increases in concentrations. The average values of toluene, ethylbenzene and xylene all dropped between the 2009 RI testing and the 2013 testing. In 2009 the average or the total of these three compounds was 7.7 ug/l. By 2013, this average had dropped to 1.9 ug/l. However, the average benzene value increased slightly, from 34.6 ug/l at the time of the RI to 67.5 ug/l in 2013. This is likely due to the small amount of LNAPL that was encountered in MW-12 (0.04 inches) thereby biasing high the average value; and our decision to sample groundwater in MW-12 after removal of this LNAPL even though wells with LNAPL were not sampled during the RI. A longer period of record for MW-7, a downgradient well for contaminants from the northern portion of the BCF Site. Total BTEX and benzene concentrations have dropped over the past five years until they are now nearly within Class GA Groundwater standards. A similar record is indicated for the other wells monitoring the BCF Site. however, the BTEX compounds are not migrating. The furthest downgradient well to the south towards the English Kills, MW-16, contained no BTEX compounds (or any other compounds) exceeding Class GA Groundwater Standards. Further, the retaining wall extends around the entire southern portion of the Site, thereby inhibiting flow into the English Kills. Similarly, the furthest downgradient well to the northeast along the Maspeth Avenue utility beddings, MW-7, contained only benzene at 1.1 ug/l, only slightly above its Class GA Groundwater Standard of 1.0 ug/l. (Isopropylbenzene was also detected at 20 ug/l, above its Class GA Groundwater Standard of 5 ug/l.) Therefore, according to the consultant, the VOC constituents of fuel oil are not migrating beyond the property in significant concentrations. GW data comparison (TVOCs in ppb): well 2009 2013 MW-6 193 23 MW-7 17 24 MW-8 349 99 MW-9 47 89 MW-10 19 6.7 MW-12 366 654 MW-13 25 175 MW-14 88 64 MW-15 101 121 MW-16 55 6 MW-17 277 187 Six wells: MW-6, MW-8, MW-10, MW-14, MW-16 and MW-17 showed decrease in TVOCs levels. Five wells: MW-7, MW-9, MW-12, MW-13 and MW-15 indicated increase in TVOCs. The most contaminated well is MW-12 with 654ppb of TVOCs. Free product in 2013: The 2013 testing confirmed LNAPL at two locations (wells MW-12 and MW-15), in lower amounts than identified during the RI. The area where LNAPL had been suspected but not confirmed by the RI contained no LNAPL in 2013. The RI mobility/recoverability testing was repeated. The LNAPL observed in 2013 was confirmed to be essentially immobile and practicably non-recoverable. The consultant recommends no further action regarding the remaining LNAPL at the site. Exposure assesment: The area of the BCF Site has a long industrial history, much of it as an oil terminal stemming back to 1933. The surrounding area has been industrial including land uses such as the National Grid Greenpoint Energy Facility (Keyspan), major pipelines, scrap metal recycling and oil terminals. Today the Site is an impound lot for the City of New York. The New York City Planning Department s objectives are to keep the area industrial. Groundwater at and in the vicinity of the Site is not potable and not used for any purpose including industrial. Groundwater is sufficiently deep that exposure to users of the industrial property is unlikely, although basic controls during construction would be appropriate. Furthermore, the remaining groundwater contamination is not migrating off the property in

BCF OIL REFINING, INC (Continued) **1001754932**

significant amounts. Therefore, there is no potential for exposure to contaminated groundwater other than when deep excavation is done during redevelopment construction or for utility repairs in the immediate vicinity of the Site. The only environmental receptor is the English Kills adjoining the southern portion of the Site. The English Kills is an industrial waterway with barge and other industrial and commercial traffic. A major outfall of the NYC sewer system is located just upstream of the BCF Site. The RIR indicates that contaminants in the sediment in the English Kills come from upgradient sources and not the BCF Site. The Site groundwater evaluation shows minimal if any impact to the English Kills from the Site. Therefore, there is no significant threat to any environmental receptors from the Site. There are no residential or other sensitive use properties in the vicinity and the entire stretch of Maspeth avenue where the Site is located is exclusively heavy industrial and commercial. Soil vapor intrusion is not a current concern due to the lack of structures. Should future structures be desired on this industrial property, soil vapor intrusion can be better addressed at that time, if necessary. The remaining contamination poses no threat to the current and likely future users of the property. None of the targeted contaminants are present in the upper two feet of soil. Currently, any contaminated soil is well separated from current users by the three-quarter inch gravel placed on the ground surface after the demolition of the aboveground facilities as required by the NYSDEC. A Sensitive Receptor Survey was done in conjunction with the 2013 testing. The Sensitive Receptor survey concluded that there was no threat to human health or the environment. The 2013 testing reported here shows the groundwater plume to be stable and consistent with what was found during the RI. Conditions are improving with time. Contaminants associated with fuel oil are not migrating off-site. Furthermore, the BCF Site is capped with gravel and mine millings and currently supporting an industrial operation; it will continue to support an industrial operation based on NYC plans and the Site s location. There is no impact to the English Kills indicated by the 2009 or 2013 testing. With the stable plume, low and improving concentrations of contaminants, lack of significant off-site migration, and a cap protecting an industrial operation; the Site conditions are fully protective of public health and the environment at this industrial property. Therefore, the consultant petitions for closure of NYSDEC Spill Number 9406807. GW data is limited to only two sampling rounds. The lates data indicated increase in Benzene levels. Free product on two wells. Will discuss the closure request with J. Kolleeny. 08/29/2013: Discussed the closure request with J. Kolleeny of DEC. It was decided that although VOC concentrations in some site wells have decreased since the last groundwater sampling event, performed at the site in 2009, the submitted data indicate that free product is present in two site wells, total VOC concentrations increased in five site wells, and benzene levels increased in seven wells. In light of these conditions, further actions are warranted at the site. AD 09/04/2013: Issued and sent a DEC Response letter to Mr. Porcelli stating that spill case closure cannot be approved at this time and that free product recovery and groundwater monitoring and sampling of site wells should continue in order to eliminate free product to the extent feasible and establish a clear decreasing trend of groundwater contaminant levels. DL pdf copy of the leter to eDocs. AD 09/18/2013: Received a phone call from John A. Rhodes of CEUS Engineering. He

BCF OIL REFINING, INC (Continued) **1001754932**

wanted to discuss free product recovery and GW sampling for the site. Told him to measure LNAPL thickness before bailing it out and suggested to install oil absorbent socks into the wells with free product, if it recharges at very slow rate. Permitted the omission of wells MW-7, MW-05, MW-10 and MW-16 from the sampling program. Also required to sample the rest of the site wells only for VOCs. AD 10/03/2013: Received the following e-mail from J. Rhodes: Ainura, We are going to sample the wells at BCF on Monday, October 7. To re-iterate the plan: We ll be sampling wells MW-8, 9, 12, 13, 14, 15 and 17. We ll test for VOCs (no SVOCS or PCBs), and for petroleum compounds (STARS list compounds). We ll gage the wells for product and evaluate increases or decreases, bale the wells as appropriate, and use absorbent socks after baling the wells. We ll report the results to you shortly after receiving the laboratory analytical reports. I also want to tell you that we collected a few samples from the BCF wells last month to get a preliminary idea of what trends were like. We will include the results from these samples in our next report. Let me know if there are any problems with the above. Thanks, John Rhodes, P.E. AD 12/26/2013: Received the following e-mail from J. Rhodes: Ainura, Attached is the BCF Groundwater Sampling Report. I am also sending you the report in hard copy with a CD. Please confirm receipt. Thanks, Ainura, John John A. Rhodes, P.E. CEUS Engineering, P.C. NJ: 5 Bedford Place, Morristown, NJ 07960 NY: 62 William Street, New York, NY 10005 646 465 2494 JRhodes@CEUSEngineeringPC.com JARhodes1@Verizon.net DL the report to eDocs. Will review. AD 01/10/2014: Reviewed the report. It states that additional groundwater sampling and testing requested by the NYSDEC in September 2013 was conducted in September and up to November 4, 2013. The additional work included sampling and testing of seven wells for specific constituents of petroleum, a trend analysis of groundwater concentrations, and limited remediation comprised of the application of absorbent socks in wells that contained or recently contained LNAPL. Additionally, NDL added a round of groundwater sampling and testing in an effort to better understand contaminant trends. Performed site activities include: - Sample wells MW-8, 9, 12, 13, 14, 15, and 17, - Analyze samples for petroleum VOCs (EPA Method 8260 STARS, no SVOCS or PCBs), - Gauge wells for product to evaluate increases or decreases, and, - Conduct a limited remediation by applying petroleum absorbent socks. Monitoring wells were gauged on September 16, October 8, and November 1, 2013. This gauging confirmed the prior gauging on 2/28/2013, 3/28/2013 and 4/22/2013, as well as the prior readings made during the RI and by Rust in 1998. The groundwater flow in the northern portion of the Site to the north was confirmed. Groundwater from the southern portion of the Site flows south toward the English Kills; this was also confirmed by recent measurements. The presence of the retaining wall at the south end of the Site affects local groundwater flow. This retaining wall is tied into the native clay unit thereby minimizing direct impacts of contaminated groundwater, if any, to the English Kills. MW-16 is a key downgradient well to the south of the BCF source areas. Absorbent socks were employed in wells MW-12, and prophylactically in MW-14 where product was observed during one gauging event, and in MW-15 where a suspended organic sediment was suspected. Due to the one inch diameter of piezometer PZ K-11, a peristaltic pump was used to remove product if encountered in the well. Upon the discovery of product in what is believed to be well MW-2, absorbent socks were applied at that location as well. GW data comparison (TVOCs in ppb): well 2009

BCF OIL REFINING, INC (Continued) **1001754932**

03/2013 10/2013 MW-6 193 23 NS MW-7 17 24 NS MW-8 349 99 ND MW-9 47 89 88 MW-10 19 6.7 NS MW-12 366 654 448 MW-13 25 175 191 MW-14 88 64 65 MW-15 101 121 129 MW-16 55 6 NS MW-17 277 187 ND Three wells: MW-8, MW-12 and MW-17 showed decrease in TVOCs levels. Three wells: MW-9, MW-15 and MW-14 indicated same levels of TVOC for both sampling events. Well MW-13 showed a slight increase in TVOCs. The most contaminated well is MW-12 with 448ppb of TVOCs. Conclusions: According to the consultant, the Exposure Assessment and Sensitive Receptor survey concluded that there was no threat to human health or the environment from the BCF Site. The current and likely future use of the Site and surrounding area is industrial. No threat to the industrial use of the property and surrounding area is presented by the current Site conditions. LNAPL, if any remains, is not a threat to the public or the environment, and practicably unrecoverable. During 2013, LNAPL was intermittently encountered only in small pockets. Through the use of absorbent socks, we have recovered approximately 1 gallon of oil in the latter half of 2013. Although CEUS will continue the application of absorbent socks for prophylactic reasons, further remedial activity will not be significantly effective and would yield diminished returns. Maintaining an open Spill Case will not affect this condition. The 2013 groundwater testing shows remaining contaminant concentrations in all wells to be following an exponential decay pattern similar to that observed in MW-7. The key downgradient well MW-17 decreased in contaminant concentrations over 2013 to the point where the most recent sampling and testing results (October 8) were below Class GA Groundwater Standards. Two other key downgradient wells, MW-16 and MW-7, have also reached the Class GA Groundwater Standards. MW-13, 14 and MW-15 are at lower concentrations and as a result their degradation patterns are not as pronounced. However, concentrations are not significantly increasing, if at all. After repeated groundwater samples and tests from these wells that show no significant contaminant concentrations, further sampling and testing would be of no value. There are currently no receptors for the contaminated groundwater remaining and unlikely to be any receptors in the future for this industrial Site. To the south, the discharge of groundwater to the English Kills is limited by a low permeability retaining wall keyed into the natural clay deposits as described in the RIR. Similarly, a significant contamination is not migrating to the north into the area of high industrial traffic along Maspeth Avenue. Based on the data. the consultant petitioning the NYSDEC for closure of the Spill Number 9406807 stating that there is no threat to the public or the environment from the BCF Site today, and none likely in the future. No remediation is necessary or practicable; further remedial activity will not be significantly effective and would yield diminished returns. No further value is served by additional sampling and testing of groundwater. While TVOCs are low in the site wells and the most contaminated well shows 448 ppb of TVOCs, there still is a free product in some of the site wells. Will diccuss the site with J. Kolleeny of DEC. AD 01/15/2014: Discussed the spill closure request with J. Kolleeny of DEC. The decision was that DEC cannot close the spill case at this time, due to reapearing free product in few site wells. GW sampling frequency could be reduced to a semi-annual basis and some wells could be removed from the sampling program (wells with ND levels of TVOCs). Wells with free product should be monitored on a continious basis to establish decreasing trends. AD 02/2014: Left a message to Mr. Rhodes. AD

BCF OIL REFINING, INC (Continued) **1001754932**

07/08/2014: Received a call from Mr. Friedland. Explained him that DEC requires to monitor free product at the site wells on a continious basis to establish decreasing trend. AD 10/22/2014: Received the following e-mail from Mr. Rhodes: Ainura, Attached is a report on the former BCF Facility, Spill No. 9406807. As you will see in the report, no oil remains at the site in the any of the locations where it was previously detected. As this was the DEC s last concern for this site, we are now renewing our request that this spill case be closed. You will note in the report that in June of this year we found MW-11, a well in which the DEC had observed oil during the RI. We were able to recover a small amount of oil from the well until July when no oil returned. Although we continue to employ absorbent socks to the well, no oil has returned to the well as of today. Throughout our monitoring in 2014, no oil was detected in any of the other areas of the site where it had been previously detected. Therefore, with the absence of oil in the MW-11 area, we conclude that the site is now practicably oil free. Please let me know if you have any questions. We look forward to your earliest response. John A. Rhodes, P.E., F.NSPE CEUS Engineering, P.C. NJ: 5 Bedford Place, Morristown, NJ 07960 NY: 62 William Street, New York, NY 10005 646 465 2494 JRhodes@CEUSEngineering.com JARhodes1@Verizon.net Will review. AD 10/28/2014: Reviewed the report. It states that free product monitoring was conducted at the site. LNAPL OBSERVATIONS AND REMEDIATION: After the departure of the impound lot operation in late September, SEUS located MW-11, the 2 well adjacent to the 1 diameter piezometer PZK?11. Since its discovery on June 2, 2014, MW-11 replaced PZK-11 for monitoring and product recovery actions. given its larger size, which makes it more representative of conditions in the area of concern. Product was recovered from MW-11 on the first day of discovery by peristaltic pump, and then by the use of absorption socks. No measurable amount of product has been detected in MW-11 since July 9, 2014. The product observations in calendar year 2014 for MW-11 and MW-2, indicated that these two wells accumulated sufficient oil to stain absorbent socks. No product was indicated in any other well during calendar year 2014. SEUS had applied absorbent socks to all wells in which product had been reported in the past, observed during the investigations or suspected of being present. For a time, small amounts of product absorbed onto the socks and the socks were periodically replaced. As of October 2014, no product is indicated to be absorbing onto any of the absorbent socks that continue to be deployed in all wells in which product had once been indicated or suspected. Conclusions and recommendations: No recoverable LNAPL has been encountered at the former BCF facility since June 2014. The consultant intend to continue the application of absorbent socks for prophylactic and ongoing monitoring reasons, but requests that this activity not hold up the closure of the Spill Case. The Exposure Assessment and Sensitive Receptor Survey presented in prior reports concluded that there is no threat to human health or the environment from the BCF Site. The current and likely future use of the Site and surrounding area is industrial or heavy commercial. No threat to the industrial or heavy commercial use of the property and surrounding area is presented by the current Site conditions. Will discuss the spill closure request with J. kolleeny of DEC. AD 10/29/2014: Discussed the spill closure recommendation with J. Kolleeny of DEC. Given the latest GW monitoring results it was decided to approve spill closure request. Issued and sent a letter to Marcello Porcelli of Newtown

BCF OIL REFINING, INC (Continued) **1001754932**

Development, LLC. Case closed. AD"

Remarks: "STORMWATER OVERFLOWING, OIL/WATER SEPARATOR SYSTEM WHICH FEEDS THROUGH OIL STORAGE AND TREATMENT SYSTEM. OIL STORAGE CONT./W PCBS. DEC HIRED CONT. TO INSTALL BY PASS TO ALLOW STORMWATER TO FLOW."

All Materials:

Site ID:	80012
Operable Unit ID:	1004223
Operable Unit:	01
Material ID:	379839
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPDES:

Name:	BCF OIL REFINING, INC
Address:	360 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Permit Number:	NY0036609
State-Region:	02
Expiration Date:	10/01/1997
Current Major Minor Status:	Minor
Primary Facility SIC Code:	5093
State Water Body Name:	NEWTOWN CK
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	0.001
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	40.719806 / -73.925056
DMR Cognizant Official:	SALVATORE CORTESE, PRESIDENT
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	BCF OIL REFINING, INC
Non-Gov Permit Street Address:	BCF OIL REFINING, INC
Non-Gov Permit Supplemental Location:	360 MASPETH AVENUE
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11211
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	BCF OIL REFINING, INC
Non-Gov Facility Street Address:	BCF OIL REFINING, INC
Non-Gov Facility Supplemental Location:	360 MASPETH AVENUE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	02030201010
Region Permit Processed:	Not reported

BCF OIL REFINING, INC (Continued) **1001754932**

Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	BCF OIL REFINING, INC
Address:	360 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	BCF OIL REFINING, INC
Non-Gov Permit Street Address:	BCF OIL REFINING, INC
Non-Gov Permit Supplemental Location:	360 MASPETH AVENUE
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11211
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	BCF OIL REFINING, INC
Non-Gov Facility Street Address:	BCF OIL REFINING, INC
Non-Gov Facility Supplemental Location:	360 MASPETH AVENUE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	BCF OIL REFINING, INC
Address:	360 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	BCF OIL REFINING, INC
Non-Gov Permit Street Address:	360 MASPETH AVENUE
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11211
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	BCF OIL REFINING, INC
Non-Gov Facility Street Address:	BCF OIL REFINING, INC
Non-Gov Facility Supplemental Location:	360 MASPETH AVENUE

BCF OIL REFINING, INC (Continued) **1001754932**

Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	BCF OIL REFINING, INC
Address:	360 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	BCF OIL REFINING, INC
Non-Gov Permit Street Address:	360 MASPETH AVENUE
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11211
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	BCF OIL REFINING, INC
Non-Gov Facility Street Address:	BCF OIL REFINING, INC
Non-Gov Facility Supplemental Location:	360 MASPETH AVENUE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

AG205 **US ENVIRONMENTAL PROTECTION AGENCY** **SEMS** **1000272490**
NNW **C O BCF OIL REFINING SITE** **NY SHWS** **NYD068273044**
1/4-1/2 **BROOKLYN, NY 11211** **RCRA NonGen / NLR**
0.351 mi. **PRP**
1852 ft. **Site 6 of 7 in cluster AG** **ECHO**
NY MANIFEST

Relative:
Lower

Actual:
12 ft.

SEMS:

Site ID:	0204261
EPA ID:	NYD068273044
Name:	BCF OIL REFINING, INC.
Address:	360 MASPETH AVENUE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11211
Cong District:	12

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

FIPS Code: 36047
Latitude: Not reported
Longitude: Not reported
FF: N
NPL: Not on the NPL
Non NPL Status: Removal Only Site (No Site Assessment Work Needed)

SEMS Detail:
Region: 02
Site ID: 0204261
EPA ID: NYD068273044
Site Name: BCF OIL REFINING, INC.
NPL: N
FF: N
OU: 00
Action Code: RV
Action Name: RMVL
SEQ: 2
Start Date: 2001-01-03 05:00:00
Finish Date: 10/26/2001 4:00:00 AM
Qual: S
Current Action Lead: EPA Perf

Region: 02
Site ID: 0204261
EPA ID: NYD068273044
Site Name: BCF OIL REFINING, INC.
NPL: N
FF: N
OU: 00
Action Code: RS
Action Name: RV ASSESS
SEQ: 1
Start Date: 2000-03-27 05:00:00
Finish Date: 3/29/2000 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0204261
EPA ID: NYD068273044
Site Name: BCF OIL REFINING, INC.
NPL: N
FF: N
OU: 00
Action Code: AR
Action Name: ADMIN REC
SEQ: 1
Start Date: 2000-09-29 04:00:00
Finish Date: Not reported
Qual: V
Current Action Lead: EPA Perf

Region: 02
Site ID: 0204261
EPA ID: NYD068273044
Site Name: BCF OIL REFINING, INC.
NPL: N

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

FF:	N
OU:	00
Action Code:	RV
Action Name:	RMVL
SEQ:	1
Start Date:	2000-05-25 04:00:00
Finish Date:	1/2/2001 5:00:00 AM
Qual:	S
Current Action Lead:	EPA Perf

SHWS:

Name:	B.C.F. OIL REFINING, INC.
Address:	360-362 MASPETH AVENUE, SOUTHSIDE
City,State,Zip:	BROOKLYN, NY 11211
Program:	HW
Site Code:	56747
Classification:	N
Region:	2
Acres:	1.900
HW Code:	224034
Record Add:	07/14/2004
Record Upd:	04/13/2011
Updated By:	JAQUINN
Site Description:	"The BCF Oil site is located within an urban, industrialized area of East Williamsburg, Brooklyn. Previously existing buildings and above ground storage tanks have been removed, and the property is being used as a Marshall's impound lot. A National Grid facility borders the site on the north, Newtown Creek on the south, a city automobile impound lot on the east and a scrap metal processing facility on the west. The total area is 1.9 acres, of which 0.3 acres is land under water. The property was used as a petroleum distribution facility for many years, starting in the early 1900?s. In 1980, the terminal was modified for use as a waste oil processing facility, and was used for waste oil recycling from 1980 to 1994. Routine sampling detected PCBs in the waste oil, and operations ceased in 1994. The property is zoned M3 (manufacturing/industrial), and it is currently used to store impounded automobiles. The site consists primarily of historic fill placed upon wetlands. Groundwater exists approximately 5 to 10 feet below grade and flows both to the north and south from the site. A remedial investigation of the site has been completed. The site was managed as a single operable unit. See also NYSDEC spill #9406807"
Env Problem:	"Based upon investigations conducted to date, the primary contaminant of concern at the site are those associated with petroleum. Separate phase petroleum contamination has been detected in numerous locations, although mobile product may be more limited. The site was extensively assessed for PCB contamination, but no significant levels of PCBs were detected on site. PCBs were detected in the Newtown Creek sediment, but the sediment contamination appears to be part of a larger problem and not related to releases from the site. A significant threat created by the potential for release of PCB-contaminated oil stored in dilapidated storage tank areas was eliminated by a removal action performed by the USEPA in 2000/2001."
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	C/O SETH D. FRIEDLAND, ESQ.
Owner Company:	NEWTON DEVELOPMENT LLC
Owner Address:	62 WILLIAM STREET
Owner Addr2:	THIRD FLOOR
Owner City,St,Zip:	NEW YORK, NY 10005
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Gerald Esposito
Owner Company:	Brooklyn Community Board 1
Owner Address:	Brooklyn Community Board 1
Owner Addr2:	435 Graham Ave
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Shelly Paus
Owner Company:	Brooklyn Public Library, Leonard Branch
Owner Address:	Brooklyn Public Library, Leonard Branch
Owner Addr2:	81 Devoe St.
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101	
Handler Name:	US ENVIRONMENTAL PROTECTION AGENCY	
Handler Address:	C O BCF OIL REFINING SITE	
Handler City,State,Zip:	BROOKLYN, NY 11211	
EPA ID:	NYD068273044	
Contact Name:	THOMAS P BUDROE	
Contact Address:	WOODBRIDGE AVE	360-3
Contact City,State,Zip:	EDISON, NJ 08837	
Contact Telephone:	732-906-6191	
Contact Fax:	Not reported	
Contact Email:	Not reported	
Contact Title:	Not reported	

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

EPA Region:	02	
Land Type:	Not reported	
Federal Waste Generator Description:	Not a generator, verified	
Non-Notifier:	Not reported	
Biennial Report Cycle:	Not reported	
Accessibility:	Not reported	
Active Site Indicator:	Not reported	
State District Owner:	NY	
State District:	NYSDEC R2	
Mailing Address:	WOODBRIDGE AVE	360-3
Mailing City,State,Zip:	EDISON, NJ 08837	
Owner Name:	OWNERNAME	
Owner Type:	Private	
Operator Name:	OWNERNAME	
Operator Type:	Private	
Short-Term Generator Activity:	No	
Importer Activity:	No	
Mixed Waste Generator:	No	
Transporter Activity:	No	
Transfer Facility Activity:	No	
Recycler Activity with Storage:	No	
Small Quantity On-Site Burner Exemption:	No	
Smelting Melting and Refining Furnace Exemption:	No	
Underground Injection Control:	No	
Off-Site Waste Receipt:	No	
Universal Waste Indicator:	No	
Universal Waste Destination Facility:	No	
Federal Universal Waste:	No	
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported	
Active Site Converter Treatment storage and Disposal Facility:	Not reported	
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported	
Active Site State-Reg Handler:	---	
Federal Facility Indicator:	Not reported	
Hazardous Secondary Material Indicator:	NN	
Sub-Part K Indicator:	Not reported	
Commercial TSD Indicator:	No	
Treatment Storage and Disposal Type:	Not reported	
2018 GPRA Permit Baseline:	Not on the Baseline	
2018 GPRA Renewals Baseline:	Not on the Baseline	
Permit Renewals Workload Universe:	Not reported	
Permit Workload Universe:	Not reported	
Permit Progress Universe:	Not reported	
Post-Closure Workload Universe:	Not reported	
Closure Workload Universe:	Not reported	
202 GPRA Corrective Action Baseline:	No	
Corrective Action Workload Universe:	No	
Subject to Corrective Action Universe:	No	
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No	
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No	
TSDFs Only Subject to CA under Discretionary Auth Universe:	No	
Corrective Action Priority Ranking:	No NCAPS ranking	
Environmental Control Indicator:	No	
Institutional Control Indicator:	No	
Human Exposure Controls Indicator:	N/A	
Groundwater Controls Indicator:	N/A	
Operating TSDF Universe:	Not reported	
Full Enforcement Universe:	Not reported	

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D008
Waste Description: LEAD

Waste Code: F001
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: K049
Waste Description: SLOP OIL EMULSION SOLIDS FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K051
Waste Description: API SEPARATOR SLUDGE FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K052
Waste Description: TANK BOTTOMS (LEADED) FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: X001
Waste Description: Not Defined

Waste Code: X003
Waste Description: Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

Historic Generators:

Receive Date:	20060101
Handler Name:	US ENVIRONMENTAL PROTECTION AGENCY
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	US ENVIRONMENTAL PROTECTION AGENCY
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19841114
Handler Name:	TANKS-A-LOT INC
Federal Waste Generator Description:	Not reported
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20020227
Handler Name:	US ENVIRONMENTAL PROTECTION AGENCY
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	92411
NAICS Description:	ADMINISTRATION OF AIR AND WATER RESOURCE AND SOLID WASTE MANAGEMENT

US ENVIRONMENTAL PROTECTION AGENCY (Continued) **1000272490**

PROGRAMS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

PRP:
PRP Name: BCF OIL REFINING INC
BCF OIL REFINING INC
BCF OIL REFINING INC
CARY FIELDS
CARY FIELDS
CARY FIELDS

ECHO:
Envid: 1000272490
Registry ID: 110001595854
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110001595854
Name: BCF OIL REFINING, INC.
Address: 360 MASPETH AVENUE
City,State,Zip: BROOKLYN, NY 11211

NY MANIFEST:
Name: TANKS A LOT INC
Address: C O BCF OIL REFINING SITE
City,State,Zip: BROOKLYN, NY 11211
Country: USA
EPA ID: NYD068273044
Facility Status: Not reported
Location Address 1: 360 MASPETH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11211
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD068273044
Mailing Name: TANKS A LOT INC
Mailing Contact: MICHAEL CALLEIA
Mailing Address 1: 2890 WOODBRIDGE AVE
Mailing Address 2: Not reported
Mailing City: EDISON
Mailing State: NJ
Mailing Zip: 08837
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7183879710

AG206 **BCF, 360 MASPETH AVENUE** **NY VCP** **S113922054**
NNW **360 MASPETH AVENUE, SOUTHSIDE** **N/A**
1/4-1/2 **BROOKLYN, NY 11211**
0.351 mi.
1852 ft. **Site 7 of 7 in cluster AG**

Relative: **Lower**

Actual: **12 ft.**

VCP:

Name:	BCF, 360 MASPETH AVENUE
Address:	360 MASPETH AVENUE, SOUTHSIDE
City,State,Zip:	BROOKLYN, NY 11211
Program Type:	VCP
Site Code:	56908
HW Code:	V00255
Site Class:	N
SWIS:	2401
Region:	2
Town:	New York City
Acres:	Not reported
Date Record Added:	11/30/2000
Date Record Updated:	03/31/2009
Updated By:	BRWOLOSE
Site Description:	"See project 224034"
Env Problem:	""
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	B.C.F. OIL REFINING, INC.
Owner Address:	360 MASPETH AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11211
Owner Country:	United States of America
Own Op:	6
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	B.C.F. Oil Refining, Inc.- Registere
Owner Address:	360 MASPETH AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11211
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported

BCF, 360 MASPETH AVENUE (Continued) **S113922054**

Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

AK207 **COOPER TANK AND WELDING CORP** **NY SWF/LF** **S107783541**
NW **222 MASPETH AVENUE** **NY Financial Assurance** **N/A**
1/4-1/2 **BROOKLYN, NY 11211**
0.351 mi.
1854 ft. **Site 1 of 3 in cluster AK**

Relative:
Higher

Actual:
15 ft.

SWF/LF:

Name:	COOPER TANK AND WELDING CORP
Address:	222 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Flag:	ACTIVE
Region Code:	2
Phone Number:	7183847727
Owner Name:	Adrienne Cooper
Owner Type:	Private
Owner Address:	123 Varick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11237
Owner Email:	Not reported
Owner Phone:	7184974431
Contact Name:	Ray Kvedaras
Contact Address:	123 Varick Avenue
Contact Addr2:	Not reported
Contact City,St,Zip:	Brooklyn, NY 11237
Contact Email:	rkvedaras@coopertank.com
Contact Phone:	7183847727
Activity Desc:	C&D processing - permit
Activity Number:	[24W21]
Active:	Yes
East Coordinate:	590039
North Coordinate:	4507913
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	Construction & Demolition Debris;Metals (Ferrous);Metals (Non-Ferrous);Plastics;Paper / Cardboard;Wood (Chips);Concrete
Authorization #:	2-6101-00061/00003
Authorization Date:	11/2/2018
Expiration Date:	10/28/2020
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

NY Financial Assurance 1:

Name:	COOPER TANK AND WELDING CORP
Address:	222 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Owner Name:	Adrienne Cooper
Region:	2
Estimate Type:	Closure Estimate
Estimate Amount:	355,000
Estimate Date:	03/01/2001
Mechanism:	Surety bond - Performance
Mechanism Amount:	355,000

COOPER TANK AND WELDING CORP (Continued) **S107783541**

Issue Date: 06/15/2006
Activity Number: 24W21
Activity Description: z Retired - C&D processing - permit

AE208 **ROLET FOOD PRODUCTS** **NY LTANKS** **S105230593**
SE **70 SCOTT AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.352 mi.
1859 ft. **Site 3 of 3 in cluster AE**

Relative: **Higher**
Actual: **18 ft.**

LTANKS:

Name:	ROLET FOOD PRODUCTS
Address:	70 SCOTT AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0109443 / 2002-01-14
Facility ID:	0109443
Site ID:	179351
Spill Date:	2001-12-26
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	2001-12-26
CID:	198
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-26
Spill Record Last Update:	2002-01-14
Spiller Name:	MARK TURETSKY
Spiller Company:	ROLET FOOD PRODUCTS
Spiller Address:	70 SCOTT AVE
Spiller County:	001
Spiller Contact:	MARK TURETSKY
Spiller Phone:	(718) 497-0476
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	150523
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY KOLLEENY OF DEC VISITED SITE. 275-GAL TANK IN ROOFTOP ENCLOSURE RUPTURED OVER X-MAS HOLIDAY, OWNER ESTIMATES ABOUT 75 GALLONS WAS LEFT IN TANK AND LEAKED OUT. OIL WENT THROUGH FLOOR OF ENCLOSURE AND INTO CRAWL SPACE ABOVE ROOF, CONTAMINATING ROOFING MATERIALS; A SMALL AMOUNT ALSO LEAKED THROUGH INTO WAREHOUSE BLDG BELOW. NO OIL WAS RELEASED INTO ENVIRONMENT. PETROLEUM TANK CLEANERS DID CLEANUP, WITH ABSORBENT ON CONCRETE/METAL SURFACES, AND REMOVAL/DISPOSAL OF IMPACTED ROOF TAR PAPER. NO RESIDUAL ODORS."
Remarks:	"TANK RUPTURED OF A 275 GAL TANK - THERE WAS UNK AMOUNT LEFT IN TANK PRODUCT THAT LEAKED WAS ABSORBED WITH SPEEDI-DRI."

All Materials:

ROLET FOOD PRODUCTS (Continued) **S105230593**

Site ID:	179351
Operable Unit ID:	846731
Operable Unit:	01
Material ID:	530649
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AJ209 **UNOCCUPIED WAREHOUSE** **NY LTANKS** **S105998052**
South **88 PORTER AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11237**
0.352 mi.
1860 ft. **Site 3 of 4 in cluster AJ**

Relative: **Higher**
Actual: **18 ft.**

LTANKS:

Name:	UNOCCUPIED WAREHOUSE
Address:	88 PORTER AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Spill Number/Closed Date:	0210928 / 2014-11-19
Facility ID:	0210928
Site ID:	209777
Spill Date:	2003-01-31
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	VXBREVDO
Referred To:	Not reported
Reported to Dept:	2003-01-31
CID:	390
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-01-31
Spill Record Last Update:	2014-11-19
Spiller Name:	ALLAN HOFFMAN
Spiller Company:	UNOCCUPIED WAREHOUSE
Spiller Address:	88 PORTER AV
Spiller County:	001
Spiller Contact:	ALLAN HOFFMAN
Spiller Phone:	(718) 381-3000
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	30119
DEC Memo:	"04/19/10 - LZ A TTF letter (eDocs) sent to Hymel Porter Realty. Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 1/30/2003 - DO - To-Do letter sent. Tank is not

UNOCCUPIED WAREHOUSE (Continued) **S105998052**

registered. Owner has received Order on Consent recently. Contact Person: Allan Hoffman Mailing Address: 105 Harrison Place, Brooklyn, NY 11237. 6/20/05- Reassigned to Benjamin 3/2006 - file transferred to region 2. Need to determine status of consent order and investigation in response to to-do letter. 07/16/13 - Spill Case is transferred from Leszek Zielinski (PBS Unit) to V. Brevdo (Section B) as per DER Region 2 decision - Tank Test Failure Spill Case. VB 11/19/2014 - V. Brevdo No spillage, leak, product release occurred in this Tank Test Failure spill case. Tank has been closed in place on 05/21/2010. The location is in the paved industrial park. Exposure risk is unlikely. No known threat to the environment or human health. Spill case is closed effective 11/19/2014. No spill closure letter is issued. VB"

Remarks: "tank failed test - no spillage"

All TTF:

Facility ID:	0210928
Spill Number:	0210928
Spill Tank Test:	1527994
Site ID:	209777
Tank Number:	1
Tank Size:	5000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	209777
Operable Unit ID:	864182
Operable Unit:	01
Material ID:	514297
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AK210
NW
1/4-1/2
0.353 mi.
1864 ft.

EQUITY WORKS
MASPETH AND VANDERVORT AVES.
BROOKLYN, NY 11211

Site 2 of 3 in cluster AK

Relative:
Higher

Actual:
15 ft.

EDR MGP **1008407885**
N/A

Manufactured Gas Plants:
No additional information available

AK211
NW
1/4-1/2
0.359 mi.
1895 ft.

FONTANA TRANSFER STATION
252 MASPETH AVENUE
BROOKLYN, NY 11211

Site 3 of 3 in cluster AK

Relative:
Lower

Actual:
13 ft.

NY SWF/LF **S105841907**
N/A

SWF/LF:

Name:	FONTANA TRANSFER STATION
Address:	252 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Flag:	INACTIVE
Region Code:	2
Phone Number:	7183847727
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	JACK BORDORE; OWNER
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	C&D processing - registration
Activity Number:	[24W52]
Active:	No
East Coordinate:	Not reported
North Coordinate:	Not reported
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	2-6101-00067
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

AH212 **GREENPOINT ENERGY FACILITY** **NY CBS** **S100494601**
NNW **287 MASPETH AVENUE** **NY AST** **N/A**
1/4-1/2 **BROOKLYN, NY 11211** **NY MOSF AST**
0.359 mi. **NY Spills**
1897 ft. **Site 2 of 7 in cluster AH** **NY AIRS**
NY HSWDS

Relative:
Higher

Actual:
14 ft.

CBS:

Name:	NATIONAL GRID GREENPOINT SERVICE CENTER
Address:	287 MASPETH AVE.
City,State,Zip:	BROOKLYN, NY 11211
CBS Number:	2-000519
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	590235.61396
UTMY:	4508095.73908

AST:

Name:	NATIONAL GRID GREENPOINT SERVICE CENTER
Address:	287 MASPETH AVE.
City,State,Zip:	BROOKLYN, NY 11211
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000519
Program Type:	CBS
UTM X:	590235.61396
UTM Y:	4508095.73908
Expiration Date:	N/A
Site Type:	Utility (Other than Municipal)

Tank Info:

Tank Number:	004
Tank Id:	264549
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1998
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/10/2017
Register:	True
Modified By:	ACDANIEL
Last Modified:	09/12/2017
Material Name:	Not reported

MOSF AST:

MOSF Number:	2-2340
SWIS Code:	61
Facility Town:	NEW YORK CITY
Facility Phone:	(718) 963-5414
Emergency Contact Name:	ROBERT GUIDI

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Emergency Contact Phone:	(718) 963-5414
Total Tanks:	0
Total Capacity:	0
Daily Throughput:	0
License Status:	Not reported
Facility Type:	MANUFACTURING
Product Transfer Operation:	CD
Facility Status:	ABANDONED/REMOVED
Operator Name:	ROBERT GUIDI
Owner Name:	BROOKLYN UNION GAS
Owner Address:	195 MONTAGUE STREET
Owner City,St,Zip:	BROOKLYN, NY 11201-
Owner Phone:	(718) 963-5414
Owner Type:	Corporate/Commercial
Owner Status:	1
Owner Mark:	First Owner
Mailing Name:	BROOKLYN UNION GAS
Mailing Address:	287 MASPETH AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11211-
Mailing Contact:	ROBERT GUIDI
Mailing Phone:	(718) 963-5414
Legal Agent Name:	SECRETARY OF STATE OF THE STATE OF NY
Legal Agent Address:	195 MONTAGUE STREET
Legal Agent City,St,Zip:	BROOKLYN, NY 11201-
LIC Expires:	03/31/1992

Tank ID:	T-1001
Tank Location:	ABOVEGROUND
Install Date:	00/73
Product:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Wrapped (Piping
Secondary Containment:	Other
Leak Detection:	Groundwater Well
Overfill Protection:	High Level Alarm
Dispensing Mthd:	Suction
Test Date:	Not reported
Date Closed:	10/91
Status of Data:	Complete
Capacity (gal):	417826
Lat/Long:	40|43|28 / 73|55|41
Federal ID:	Not reported
Inspected Date:	/ /
Inspector:	Not reported
Renew Date:	10/30/1991
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	0
COI Date:	/ /

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Date License Issued: 10/23/1991
Date License Application Received: 02/06/1992
Chemical Bulk Storage Number: Not reported
Pollution Discharge Elimination System Num: Not reported
Date Legal Agent Filed with Secretary of State: 02/78

Tank ID: T-1002
Tank Location: ABOVEGROUND
Install Date: 00/73
Product: EMPTY
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: CATHODIC PROTECTION
Pipe Location: Aboveground/Underground Combination
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: Wrapped (Piping
Secondary Containment: Other
Leak Detection: Groundwater Well
Overfill Protection: High Level Alarm
Dispensing Mthd: Suction
Test Date: 12/90
Date Closed: 11/91
Status of Data: Complete
Capacity (gal): 417826
Lat/Long: 40|43|28 / 73|55|41
Federal ID: Not reported
Inspected Date: / /
Inspector: Not reported
Renew Date: 10/30/1991
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Tank Status: 0
COI Date: / /
Date License Issued: 10/23/1991
Date License Application Received: 02/06/1992
Chemical Bulk Storage Number: Not reported
Pollution Discharge Elimination System Num: Not reported
Date Legal Agent Filed with Secretary of State: 02/78

Tank ID: T-1003
Tank Location: ABOVEGROUND
Install Date: 00/56
Product: EMPTY
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: PAINTED [e.g. asphaltic]
Pipe Location: Aboveground/Underground Combination
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: Wrapped (Piping
Secondary Containment: 8A
Leak Detection: Groundwater Well

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Overfill Protection:	High Level Alarm
Dispensing Mthd:	Suction
Test Date:	12/90
Date Closed:	11/91
Status of Data:	Complete
Capacity (gal):	1969093
Lat/Long:	40|43|28 / 73|55|41
Federal ID:	Not reported
Inspected Date:	/ /
Inspector:	Not reported
Renew Date:	10/30/1991
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	0
COI Date:	/ /
Date License Issued:	10/23/1991
Date License Application Received:	02/06/1992
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	Not reported
Date Legal Agent Filed with Secretary of State:	02/78

Tank ID:	T-1004
Tank Location:	ABOVEGROUND
Install Date:	00/56
Product:	EMPTY
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Wrapped (Piping
Secondary Containment:	8A
Leak Detection:	02
Overfill Protection:	High Level Alarm
Dispensing Mthd:	Suction
Test Date:	12/90
Date Closed:	11/91
Status of Data:	Complete
Capacity (gal):	1969093
Lat/Long:	40|43|28 / 73|55|41
Federal ID:	Not reported
Inspected Date:	/ /
Inspector:	Not reported
Renew Date:	10/30/1991
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	0
COI Date:	/ /
Date License Issued:	10/23/1991
Date License Application Received:	02/06/1992
Chemical Bulk Storage Number:	Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Pollution Discharge Elimination System Num: Not reported
Date Legal Agent Filed with Secretary of State: 02/78

Tank ID: T-1005
Tank Location: ABOVEGROUND
Install Date: 00/56
Product: EMPTY
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: PAINTED [e.g. asphaltic]
Pipe Location: Aboveground/Underground Combination
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: Wrapped (Piping
Secondary Containment: Concrete Dike
Leak Detection: Groundwater Well
Overfill Protection: High Level Alarm
Dispensing Mthd: Suction
Test Date: 12/90
Date Closed: 11/91
Status of Data: Complete
Capacity (gal): 1969093
Lat/Long: 40|43|28 / 73|55|41
Federal ID: Not reported
Inspected Date: / /
Inspector: Not reported
Renew Date: 10/30/1991
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Tank Status: 0
COI Date: / /
Date License Issued: 10/23/1991
Date License Application Received: 02/06/1992
Chemical Bulk Storage Number: Not reported
Pollution Discharge Elimination System Num: Not reported
Date Legal Agent Filed with Secretary of State: 02/78

SPILLS:
Name: NATIONAL GRID
Address: 287 MASPETH AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1903222 / 2019-06-28
Facility ID: 1903222
Facility Type: ER
DER Facility ID: 394939
Site ID: 591177
DEC Region: 2
Spill Cause: Human Error
Spill Class: C4
SWIS: 2401
Spill Date: 2019-06-28
Investigator: PXLAKHAN
Referred To: Not reported
Reported to Dept: 2019-06-28

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-06-28
Spill Record Last Update:	2019-06-28
Spiller Name:	KEN WALSH
Spiller Company:	MILLER ENVIRONMENTAL
Spiller Address:	287 MASPETH AVE
Spiller Company:	999
Contact Name:	KEN WALSH
DEC Memo:	"06/28/19 - Lakhani 1 gallon spilled while National Grid was cutting into their gas line on their site. There was oil condensate in the pipe. 1 gallon spilled to the asphalt surface. The remaining product was caught in spill buckets. Cleanup is being performed by Miller Environmental. "
Remarks:	""

All Materials:

Site ID:	591177
Operable Unit ID:	1338800
Operable Unit:	01
Material ID:	2348308
Material Code:	0013
Material Name:	lube oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	NATIONAL GRID PROPERTY
Address:	287 MASPETH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2005923 / 2020-09-30
Facility ID:	2005923
Facility Type:	ER
DER Facility ID:	394939
Site ID:	611731
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2020-09-30
Investigator:	RJFENG
Referred To:	Not reported
Reported to Dept:	2020-09-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2020-09-30
Spill Record Last Update:	2020-09-30
Spiller Name:	NANCY WAGNER
Spiller Company:	NATIONAL GRID
Spiller Address:	287 MASTIC AVE
Spiller Company:	999
Contact Name:	NANCY WAGNER
DEC Memo:	"9/30/2020 - Feng - Desk Duty in office. Spoke to Nancy Wagner of Miller Environmental. The correct address is 287 Maspeth Ave, Brooklyn. It is a National Grid property. They were doing a fire test today. The fire retardant form, a baking soda like chemical was spilled on the pavement of the basement. The facility is equipped with a gas pump. The chemical material was using in the fire test and spilled on the ground. No known the quantity it spilled. No impact to the soil and drain. The company who spilled the material will vac it up and remove it. She will call them for updates and will respond to my email. Nancy Wagner Miller Environmental 631-506-9144 NWagner@millerenv.com Received photos from Nancy Wagner. It is the dry chemical or fire retardant material, fell from the overhead fire suppression system at the gas pumps. As per R. Austin, it is not something DEC would respond. Spill is closed. "
Remarks:	"unk amount of product freed. clean up pending."

All Materials:

Site ID:	611731
Operable Unit ID:	1358879
Operable Unit:	01
Material ID:	2370324
Material Code:	0980A
Material Name:	fire retardant foam
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	COMMERCIAL PROPERTY
Address:	287 MASPETH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2006012 / 2020-12-02
Facility ID:	2006012
Facility Type:	ER
DER Facility ID:	394939
Site ID:	611830
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C5
SWIS:	2401
Spill Date:	2020-09-25

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Investigator:	EJKIM
Referred To:	Not reported
Reported to Dept:	2020-10-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2020-10-02
Spill Record Last Update:	2020-12-04
Spiller Name:	Not reported
Spiller Company:	NAT GRID
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CHRIS MORRIS
DEC Memo:	"10/2/20 - Kim - Desk Duty - I called Chris with GEI who stated that this spill is at a State Superfund site; DEC-Albany PM: Greta White. The spill that was called in is not directly related to the Former MGP site. In the southwest corner of the site there are 7 USTs (4 in one bank and 3 in another) that were associated with a former varnish company that closed in 1933. The tank systems have been out of service for approximately 80-90 years. As part of the GEI Work Plan, they investigated the USTs and dug some borings and test pits. In the soil from the borings, GEI found some staining and high PID readings and in a test pit, the water had a sheen. The tanks are supposed to have stored turpentine. After GEI pulled that tanks and inspected them, they found a few inches of water and a small amount of product. The product smelled almost like fuel oil with a hint of a solvent smell. These tanks are located beneath the building foundation so their removal would be complicated. 12/2/20 - Kim - I received a call from DEC-Albany PM Greta White. This spill case is being consolidated and will be managed by DEC White under Remedial MGP Site no. 224052, K - Greenpoint MGP - Energy Center. This spill case is closed."
Remarks:	"superfund site - cleanup pending - under investigation"

All Materials:

Site ID:	611830
Operable Unit ID:	1358975
Operable Unit:	01
Material ID:	2370441
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AIRS:

Name:	GREENPOINT ENERGY CTR

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Address:	287 MASPETH AVE
City,State,Zip:	BROOKLYN, NY 11211
DECID:	2610100071
Process ID:	Not reported
Latitude:	40.720050931
Longitude:	73.930320909
FIPS Code:	Not reported
Auth Type Code:	ATV
Permit Status:	Issued
Auth Status Code:	Not reported
Emissions:	Not reported
Issue date:	10/31/2017
Expired Date:	12/10/2022
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported
Permit Status:	Expired
Auth Status Code:	Not reported
Emissions:	Not reported
Issue date:	12/11/2012
Expired Date:	12/10/2017
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported
Permit Status:	Expired
Auth Status Code:	Not reported
Emissions:	Not reported
Issue date:	09/18/2007
Expired Date:	09/17/2012
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported
Permit Status:	Expired
Auth Status Code:	Not reported
Emissions:	Not reported
Issue date:	09/12/2007
Expired Date:	Not reported
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported
Permit Status:	Expired
Auth Status Code:	Not reported
Emissions:	Not reported
Issue date:	02/20/2003

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Expired Date: 09/11/2007
Emission Unit date: Not reported
Contamination: Not reported
EPA Control Code: Not reported
Control Eff: Not reported
Unit: Not reported

Permit Status: Expired
Auth Status Code: Not reported
Emissions: Not reported
Issue date: 01/31/2005
Expired Date: 09/11/2007
Emission Unit date: Not reported
Contamination: Not reported
EPA Control Code: Not reported
Control Eff: Not reported
Unit: Not reported

Permit Status: Expired
Auth Status Code: Not reported
Emissions: Not reported
Issue date: 06/16/2003
Expired Date: 09/11/2007
Emission Unit date: Not reported
Contamination: Not reported
EPA Control Code: Not reported
Control Eff: Not reported
Unit: Not reported

AIRS Detail:
DECID: 2610100071
Facility Name: GREENPOINT ENERGY CTR
Auth Type: ATV

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PARTICULATES
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Year:	Not reported
CAS #:	Not reported
Contaminant:	VOC
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	SULFUR DIOXIDE
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	TOTAL HAP
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	PM-10
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000124389
Contaminant:	CARBON DIOXIDE
Amount(Lbs/Yr):	29067
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	065996932
Contaminant:	PITCH, COAL TAR, HIGH-TEMP.
Amount(Lbs/Yr):	0.46999999999999997
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007446095
Contaminant:	SULFUR DIOXIDE
Amount(Lbs/Yr):	3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000124389
Contaminant:	CARBON DIOXIDE
Amount(Lbs/Yr):	524183
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 4256

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 1568

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 87

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 9

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 137151

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 236

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 1

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 77

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY210000

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 6362

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 114

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 96

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 065996932
Contaminant: PITCH, COAL TAR, HIGH-TEMP.
Amount(Lbs/Yr): 2.9999999999999999E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 1389

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 065996932
Contaminant: PITCH, COAL TAR, HIGH-TEMP.
Amount(Lbs/Yr): 0.46999999999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 29067

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Amount(Lbs/Yr): 353

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 524183

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 4256

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 1568

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 87

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 9

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 137151

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 236

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 1

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 77

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 6362

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 114

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 96

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 065996932
Contaminant: PITCH, COAL TAR, HIGH-TEMP.
Amount(Lbs/Yr): 2.9999999999999999E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 1389

Issue Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Expiration Date: Not reported
Year: 2016
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 353

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000078922
Contaminant: SEC-BUTYL ALCOHOL (8CI)
Amount(Lbs/Yr): 0.02

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 3.5988071674e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 2.2292524622e-005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 5.598012426e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 0.00079990823645

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 4.7980926208e-005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 2.7537824533

Issue Date: Not reported
Expiration Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Year: 2012
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 0.0044585049245

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 3.4094449422

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 2.36038496

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000111762
Contaminant: ETHANOL, 2-BUTOXY-
Amount(Lbs/Yr): 0.03

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 4.7982114717e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 667766

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 9.9960262934e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 0.0010254307006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

CAS #: 000193395
Contaminant: INDENO[1,2,3-CD]PYRENE
Amount(Lbs/Yr): 3.5988071674e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 3.5988071674e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 5.997615776e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 2.3605424016e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 2.3605424016e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 3666

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 001746016
Contaminant: 2,3,7,8-TETRACHLORODIBENZO-P-DIOXIN
Amount(Lbs/Yr): 1.8232682681e-009

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 0.00099960262934

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439965

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Contaminant: MANGANESE
Amount(Lbs/Yr): 0.0007596979983

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 1.4077622727e-008

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.0021991257845

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 0.0041983310432

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 0.00039963304782

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 0.0087965031382

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 2.3990463104e-005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.0021985987738

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440473
Contaminant: CHROMIUM

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Amount(Lbs/Yr): 0.0027981893484

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 0.00016793324173

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 0.0016993244699

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.004598172095

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 0.057976952502

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 3.56126

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 6.47104

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007727437
Contaminant: SULFURIC ACID BARIUM SALT
Amount(Lbs/Yr): 0.01

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 4.7980926208e-005

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 4.44884

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 013463677
Contaminant: TITANIUM DIOXIDE
Amount(Lbs/Yr): 0.08

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 014807966
Contaminant: TALC
Amount(Lbs/Yr): 0.02

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.0015735899733

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 065996932
Contaminant: PITCH, COAL TAR, HIGH-TEMP.
Amount(Lbs/Yr): 0.39

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 068855549
Contaminant: KIESELGHUR SODA ASH FLUX CALCINED
Amount(Lbs/Yr): 0.01

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 1157.3180408

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 1142.7700131

Issue Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Expiration Date: Not reported
Year: 2012
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 5429.25

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 1315.68

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 0.0044913830703

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 8.2169856504e-008

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 8.2169856504e-008

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000056495
Contaminant: 3-METHYLCHOLANTHRENE
Amount(Lbs/Yr): 1.8506019817e-007

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 1.2338793675e-007

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000057976
Contaminant: 7,12-DIMETHYLBENZ[A]ANTHRACENE
Amount(Lbs/Yr): 1.6442819861e-006

Issue Date: Not reported
Expiration Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Year:	2012
CAS #:	000071432
Contaminant:	BENZENE
Amount(Lbs/Yr):	0.00014389045528
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000074828
Contaminant:	METHANE
Amount(Lbs/Yr):	0.22137
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000074840
Contaminant:	ETHANE
Amount(Lbs/Yr):	0.32674
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000074986
Contaminant:	PROPANE
Amount(Lbs/Yr):	0.10963082307
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000083329
Contaminant:	ACENAPHTHENE
Amount(Lbs/Yr):	1.8506019817e-007
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000085018
Contaminant:	PHENANTHRENE
Amount(Lbs/Yr):	1.1648274951e-006
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000086737
Contaminant:	FLUORENE
Amount(Lbs/Yr):	2.878278223e-007
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000091203
Contaminant:	NAPHTHALENE
Amount(Lbs/Yr):	4.1796751294e-005
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 2.4664229792e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 0.14389045528

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 0.00023296549902

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 0.17815008748

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 0.12333467595

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 2.4668153528e-007

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 807388

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 5.1383812066e-007

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000191242

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 0.0018930997447

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000193395
Contaminant: INDENO[1,2,3-CD]PYRENE
Amount(Lbs/Yr): 1.8506019817e-007

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 1.8506019817e-007

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 3.0830287239e-007

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 1.2338793675e-007

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 1.2338793675e-007

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 6464.124

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 1.9320943619e-005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439965
Contaminant: MANGANESE

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Amount(Lbs/Yr): 3.905169717e-005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 2.3316824757e-005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.00011304438654

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 0.00021211188012

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 2.0553524826e-005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 0.00045217754618

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 1.2332114896e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.00011196016105

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 6.3113607506e-005

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007440484
Contaminant:	COBALT
Amount(Lbs/Yr):	8.632480427e-006
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007440508
Contaminant:	COPPER
Amount(Lbs/Yr):	8.6444524755e-005
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007440622
Contaminant:	VANADIUM
Amount(Lbs/Yr):	0.00014606094982
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007440666
Contaminant:	ZINC
Amount(Lbs/Yr):	0.0029802610998
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007446095
Contaminant:	SULFUR DIOXIDE
Amount(Lbs/Yr):	3.01542
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007664417
Contaminant:	AMMONIA
Amount(Lbs/Yr):	0.0432
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007782492
Contaminant:	SELENIUM
Amount(Lbs/Yr):	2.4664229792e-006
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	010024972
Contaminant:	NITROUS OXIDE
Amount(Lbs/Yr):	0.14278
Issue Date:	Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Expiration Date: Not reported
Year: 2012
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 8.22231173e-005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 065996932
Contaminant: PITCH, COAL TAR, HIGH-TEMP.
Amount(Lbs/Yr): 0.56

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 0.7810339434

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 2106.538107

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 9659.49

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 2378.35

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 0.098349373334

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 1.5734325318e-006

Issue Date: Not reported
Expiration Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Year: 2012
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 1.5734325318e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000056495
Contaminant: 3-METHYLCHOLANTHRENE
Amount(Lbs/Yr): 3.5988071674e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 2.3605424016e-006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000057976
Contaminant: 7,12-DIMETHYLBENZ[A]ANTHRACENE
Amount(Lbs/Yr): 3.1987284139e-005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 0.0027537824533

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 4.66106

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 6.26882

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 2.0981199645

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 6.4710400000000003

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 065996932
Contaminant: PITCH, COAL TAR, HIGH-TEMP.
Amount(Lbs/Yr): 0.39000000000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 89.014716563254296

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 1068.3075928999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 5429.1800000000003

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 1308.8299999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000078922
Contaminant: SEC-BUTYL ALCOHOL (8CI)
Amount(Lbs/Yr): 0.01

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000111762

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Contaminant: ETHANOL, 2-BUTOXY-
Amount(Lbs/Yr): 0.02

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007727437
Contaminant: SULFURIC ACID BARIUM SALT
Amount(Lbs/Yr): 0.01

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 013463677
Contaminant: TITANIUM DIOXIDE
Amount(Lbs/Yr): 5.9999999999999998E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 014807966
Contaminant: TALC
Amount(Lbs/Yr): 0.01

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 0NY075000
Contaminant: PARTICULATES
Amount(Lbs/Yr): 0.26000000000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 0NY075005
Contaminant: PM-10
Amount(Lbs/Yr): 0.26000000000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 0NY075100
Contaminant: UNSPECIATED PARTICULATES (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 0.26000000000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 0NY998000
Contaminant: VOC
Amount(Lbs/Yr): 19.390000000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000050000
Contaminant: FORMALDEHYDE

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Amount(Lbs/Yr):	9.8260462281297603E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000074828
Contaminant:	METHANE
Amount(Lbs/Yr):	0.01
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000074840
Contaminant:	ETHANE
Amount(Lbs/Yr):	6.2688199999999998
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000074986
Contaminant:	PROPANE
Amount(Lbs/Yr):	2.0962231953343502
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000106978
Contaminant:	BUTANE
Amount(Lbs/Yr):	2.7512929438763298
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000109660
Contaminant:	PENTANE
Amount(Lbs/Yr):	3.4063626924183201
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000110543
Contaminant:	HEXANE
Amount(Lbs/Yr):	2.3582510947511399
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000124389
Contaminant:	CARBON DIOXIDE
Amount(Lbs/Yr):	667766
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000630080
Contaminant:	CARBON MONOXIDE
Amount(Lbs/Yr):	3666.8099999999999

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 8.6282457471472396E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 5.6867983333470401E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 22.4114

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 8.2169944940508506E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 268.88821886913598

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 28412.93

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 2275.1772000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 130498292
Contaminant: POLYCYCLIC AROMATIC HYDROCARBONS
Amount(Lbs/Yr): 1.0041797072368099

Issue Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Expiration Date: Not reported
Year: 2009
CAS #: 000078922
Contaminant: SEC-BUTYL ALCOHOL (8CI)
Amount(Lbs/Yr): 2.9999999999999999E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000111762
Contaminant: ETHANOL, 2-BUTOXY-
Amount(Lbs/Yr): 5.0000000000000003E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007727437
Contaminant: SULFURIC ACID BARIUM SALT
Amount(Lbs/Yr): 0.02

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 013463677
Contaminant: TITANIUM DIOXIDE
Amount(Lbs/Yr): 0.12

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 014807966
Contaminant: TALC
Amount(Lbs/Yr): 0.02

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 068855549
Contaminant: KIESELGHUR SODA ASH FLUX CALCINED
Amount(Lbs/Yr): 0.01

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 0.5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 8.2170617120287802E-6

Issue Date: Not reported
Expiration Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Year: 2009
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 8.2170617120287802E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 1.23254245230983E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 1.8231543877852001E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 1.16407421999054E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 0.51356215587817799

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 0.014379740364589

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 23.440100000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 31.579699999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 10.9559926587345

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 14.379740364589001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 0.0232814843998107

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 17.8034880704435

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 12.3254917410763

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 4649984

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 8553.0962999999992

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 8.5026922877807498E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000050328

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 1.36043076604492E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 1.36043076604492E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 2.0406461490673802E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 0.00238075384057861

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 4.04535

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 5.4389500000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 1.8139076880598901

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000078922
Contaminant: SEC-BUTYL ALCOHOL (8CI)
Amount(Lbs/Yr): 0.01

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000083329
Contaminant: ACENAPHTHENE

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Amount(Lbs/Yr): 3.1476948252290001E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 1.9272769185636399E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 4.8964141725784401E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 6.9155230607283397E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 4.19692643363867E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 2.3807538405786102

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 0.00385455383712727

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 2.9475999930973198

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 2.04064614906738

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000111762
Contaminant: ETHANOL, 2-BUTOXY-
Amount(Lbs/Yr): 0.02

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 4.1969264336386697E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 796150

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 8.7435967367472207E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 0.00140903892550488

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 3.1476948252290001E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 5.2461580420483299E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 2.0406461490673802E-6

Issue Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Expiration Date: Not reported
Year: 2009
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 2.0406461490673802E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 4958.2200000000003

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 001746016
Contaminant: 2,3,7,8-TETRACHLORODIBENZO-P-DIOXIN
Amount(Lbs/Yr): 2.07858372568733E-9

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 8.7435967367472203E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 6.6451335199278901E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 1.2103284815572E-8

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.00192359128208439

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 3.5245115419737902E-3

Issue Date: Not reported
Expiration Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Year:	2009
CAS #:	007440382
Contaminant:	ARSENIC
Amount(Lbs/Yr):	3.3558699400971999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440393
Contaminant:	BARIUM
Amount(Lbs/Yr):	7.6943651283375601E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440417
Contaminant:	BERYLLIUM
Amount(Lbs/Yr):	2.0984632168193299E-5
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440439
Contaminant:	CADMIUM
Amount(Lbs/Yr):	1.8520649817536201E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440473
Contaminant:	CHROMIUM
Amount(Lbs/Yr):	2.3559944036243301E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440484
Contaminant:	COBALT
Amount(Lbs/Yr):	1.4689242517735299E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440508
Contaminant:	COPPER
Amount(Lbs/Yr):	0.00142616988932341
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440622
Contaminant:	VANADIUM
Amount(Lbs/Yr):	4.0220544989037202E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 0.0507128610731339

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 3.6389

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 5.6143999999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007727437
Contaminant: SULFURIC ACID BARIUM SALT
Amount(Lbs/Yr): 0.01

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 4.19692643363867E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 3.8599000000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 013463677
Contaminant: TITANIUM DIOXIDE
Amount(Lbs/Yr): 4.0000000000000001E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 014807966
Contaminant: TALC
Amount(Lbs/Yr): 0.01

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 025321226

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 1.3604307660449199E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 065996932
Contaminant: PITCH, COAL TAR, HIGH-TEMP.
Amount(Lbs/Yr): 0.14999999999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 1606.35604407497

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 0.17000000000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 7367.8900000000003

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 1787.3299999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 130498292
Contaminant: POLYCYCLIC AROMATIC HYDROCARBONS
Amount(Lbs/Yr): 0.38

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 5.0643453626285804E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439987
Contaminant: MOLYBDENUM

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Amount(Lbs/Yr): 1.1141559797782899E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 2.1270250523040001E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 0.0445662391911315

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 1.1141559797782899E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.01418016701536

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 8.6093871164685896E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 2.8360234603109101E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 4.1769722011425203E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 2.43088577406172E-4

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 2.4308658885395302E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 5.0643453626285802E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 2.6630901103651401E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 1.8231543877852001E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 3.03860721757715E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 1.23254245230983E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 1.23254245230983E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 001746016
Contaminant: 2,3,7,8-TETRACHLORODIBENZO-P-DIOXIN
Amount(Lbs/Yr): 1.18318857004577E-8

Issue Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Expiration Date: Not reported
Year: 2009
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 0.00384890247559772

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 2.6334595885668601E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 2.0257381450514301E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 1.21544288703086E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 8.5081002092160095E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 0.29373203103245799

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 2.3295988668091499E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 2.43088577406172E-4

Issue Date: Not reported
Expiration Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Year: 2009
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 17.29692

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 32.598399999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007727437
Contaminant: SULFURIC ACID BARIUM SALT
Amount(Lbs/Yr): 0.02

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 160.96396081215099

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 22336.66

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 3.2547628439923002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.00149719090823646

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 1.44034

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 1.1441978639495001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 5.5330968347869105E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 2.8641913027132198E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 7.4812937258236301E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 1856.684

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 2.0295700000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 1.3019051375969199E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 1.9528577063953798E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440666

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Contaminant: ZINC
Amount(Lbs/Yr): 1.8877624495155301E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 0.0330057076139278

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 7.1604782567830604E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 1.496258745164 7299E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 1.1715555396597299E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 1.5622861651163001E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 0.00136700039447677

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 6312.9107999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Amount(Lbs/Yr): 2.1525296365980601E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 1.5622861651163001E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 7.8114308255815192E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 0.5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 1.56220662302755E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 7.9202943396957504E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 1.1715555396597299E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 5.4680015779070601E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 1.8225081084581901E-6

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 001746016
Contaminant: 2,3,7,8-TETRACHLORODIBENZO-P-DIOXIN
Amount(Lbs/Yr): 7.8314371491764998E-10

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 068855549
Contaminant: KIESELGHUR SODA ASH FLUX CALCINED
Amount(Lbs/Yr): 0.01

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 2.09504

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 0.79213698273426703

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 2.6844642192661299E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 2.4736197614341499E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 013463677
Contaminant: TITANIUM DIOXIDE
Amount(Lbs/Yr): 0.12

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 014807966
Contaminant: TALC
Amount(Lbs/Yr): 0.02

Issue Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Expiration Date: Not reported
Year: 2008
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 5.2819887058753499E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 5.2819887058753499E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 3.2547628439923001E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 9.1622199999999996

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 1911600

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 9.1133359631784402E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 130498292
Contaminant: POLYCYCLIC AROMATIC HYDROCARBONS
Amount(Lbs/Yr): 0.82112696238247196

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 5.2809132182284502E-4

Issue Date: Not reported
Expiration Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Year: 2008
CAS #: 000078922
Contaminant: SEC-BUTYL ALCOHOL (8CI)
Amount(Lbs/Yr): 2.9999999999999999E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 7.9202943396957504E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 7.9202943396957504E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 9.2415981318997795E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 0.92415981318997797

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 1.5058100000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 1.6924766788759999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000111762
Contaminant: ETHANOL, 2-BUTOXY-
Amount(Lbs/Yr): 5.0000000000000003E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 0.70412176243045899

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 7.1604782567830604E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 2.6844642192661299E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 001746016
Contaminant: 2,3,7,8-TETRACHLORODIBENZO-P-DIOXIN
Amount(Lbs/Yr): 7.8314371491764998E-10

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 0NY075005
Contaminant: PM-10
Amount(Lbs/Yr): 0

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 1.3019051375969199E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 5.2819887058753499E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.00149719090823646

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007439965

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Contaminant: MANGANESE
Amount(Lbs/Yr): 2.4736197614341499E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 7.4812937258236301E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 160.96404938420901

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 0.70412176243045899

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 1.56220662302755E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 7.8114308255815192E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 1.9528577063953798E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000078922
Contaminant: SEC-BUTYL ALCOHOL (8CI)
Amount(Lbs/Yr): 0.13

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 014807966
Contaminant: TALC

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Amount(Lbs/Yr): 0.11

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 2.0634921520950099E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 0.79213698273426703

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 2.0295700000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 5.2819887058753499E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 1.1715555396597299E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 5.2809132182284405E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 9.5469200000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 0.92415981318997797

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 9.2415981318997795E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 7.9202943396957504E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 22336.66

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 1.6924766788759999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 3.2547628439923001E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 1.5058100000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 013463677
Contaminant: TITANIUM DIOXIDE
Amount(Lbs/Yr): 0.57999999999999996

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 7.1604782567830604E-4

Issue Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Expiration Date: Not reported
Year: 2007
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 7.9202943396957504E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 1911600

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 2.09504

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 1.1441978639495001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 5.5330968347869105E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 068855549
Contaminant: KIESELGHUR SODA ASH FLUX CALCINED
Amount(Lbs/Yr): 4.0000000000000001E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 7.9202943396957504E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 130498292
Contaminant: POLYCYCLIC AROMATIC HYDROCARBONS
Amount(Lbs/Yr): 0.821127427809342

Issue Date: Not reported
Expiration Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Year: 2007
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 0.0330057076139278

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 6312.9107999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 2.8641913027132198E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 2.52

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 1.5622861651163001E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 1.5622861651163001E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 1.8225081084581901E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007727437
Contaminant: SULFURIC ACID BARIUM SALT
Amount(Lbs/Yr): 0.10000000000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 1.4962587451647299E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 0.00136700039447677

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 3.2547628439923002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 1.1715555396597299E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 7.1604782567830604E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 1.8877624495155301E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 1.44034

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 5.4680015779070601E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000111762

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Contaminant: ETHANOL, 2-BUTOXY-
Amount(Lbs/Yr): 0.23999999999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 9.1133359631784402E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 2006.0440000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 014807966
Contaminant: TALC
Amount(Lbs/Yr): 0.11

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007727437
Contaminant: SULFURIC ACID BARIUM SALT
Amount(Lbs/Yr): 0.10000000000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 2.52

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 3.5289437550528098E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 4.70525834007041E-10

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Amount(Lbs/Yr):	4.70525834007041E-10
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000056553
Contaminant:	BENZO(A)ANTHRACENE
Amount(Lbs/Yr):	9.41051668014082E-10
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000071432
Contaminant:	BENZENE
Amount(Lbs/Yr):	9.8810425141478502E-7
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000074828
Contaminant:	METHANE
Amount(Lbs/Yr):	1.6100000000000001E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000074840
Contaminant:	ETHANE
Amount(Lbs/Yr):	2.1700000000000001E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000074986
Contaminant:	PROPANE
Amount(Lbs/Yr):	7.5284133441126503E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000083329
Contaminant:	ACENAPHTHENE
Amount(Lbs/Yr):	1.39198655320058E-9
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000085018
Contaminant:	PHENANTHRENE
Amount(Lbs/Yr):	7.9989391781196896E-9
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000086737
Contaminant:	FLUORENE
Amount(Lbs/Yr):	2.0879798298008599E-9

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000091203
Contaminant:	NAPHTHALENE
Amount(Lbs/Yr):	2.8702075874429498E-7
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000091576
Contaminant:	2-METHYL NAPHTHALENE
Amount(Lbs/Yr):	1.6703838638406899E-8
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000106978
Contaminant:	BUTANE
Amount(Lbs/Yr):	9.8810425141478511E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000108883
Contaminant:	TOLUENE
Amount(Lbs/Yr):	1.5997878356239401E-6
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000109660
Contaminant:	PENTANE
Amount(Lbs/Yr):	1.2233671684183101E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000110543
Contaminant:	HEXANE
Amount(Lbs/Yr):	8.4694650121267304E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000120127
Contaminant:	ANTHRACENE
Amount(Lbs/Yr):	1.39198655320058E-9
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000129000
Contaminant:	PYRENE
Amount(Lbs/Yr):	3.4799663830014401E-9
Issue Date:	Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Expiration Date: Not reported
Year: 2006
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 0.00214940217627335

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 1.39198655320058E-9

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 2.0879798298008599E-9

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 9.41051668014082E-10

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 9.41051668014082E-10

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 3.4799663830014398E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 2.6447744510810898E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 1.8095825191607501E-7

Issue Date: Not reported
Expiration Date: Not reported

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Year: 2006
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 7.6559260426031703E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 1.4615858808606E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 1.3919865532005801E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 3.0623704170412698E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 8.3519193192034496E-9

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 7.6559260426031703E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 9.7439058724040298E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 5.8463435234424198E-8

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 5.9159428511024398E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 1.6007845361806601E-6

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 2.0183805021408299E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 2.2399999999999998E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 1.6703838638406899E-8

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 1.5399999999999999E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 5.6463100080844898E-7

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 1832464

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000630080

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 6248.9574000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 9.3972599999999993

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 155.94937863010699

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 28238.18

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 2003.4223999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 130498292
Contaminant: POLYCYCLIC AROMATIC HYDROCARBONS
Amount(Lbs/Yr): 0.98776151731499895

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000078922
Contaminant: SEC-BUTYL ALCOHOL (8CI)
Amount(Lbs/Yr): 0.13

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000111762
Contaminant: ETHANOL, 2-BUTOXY-
Amount(Lbs/Yr): 0.23999999999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 013463677
Contaminant: TITANIUM DIOXIDE

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Amount(Lbs/Yr): 0.57999999999999996

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 068855549
Contaminant: KIESELGHUR SODA ASH FLUX CALCINED
Amount(Lbs/Yr): 4.0000000000000001E-2

AIRS Emissions:
County: KINGS
Municipality: BROOKLYN
Facility ID: 2610100071
Facility Name: GREENPOINT ENERGY CTR
SIC Code: 4923

Year: 2019
VOC(tons): 1.3799999999999999
NOx(tons): 5.5599999999999996
Co(tons): 3.7200000000000002
Co2(tons): 471.51999999999998
Particulates: 0
PM10(tons): 1.1499999999999999
PM2.5(tons): 8.0000000000000002E-2
HAPS: 0
So2: 0

Year: 2018
VOC(tons): 0.57999999999999996
NOx(tons): 7.04
Co(tons): 2.0099999999999998
Co2(tons): 654.99000000000001
Particulates: 0.13
PM10(tons): 0.02
PM2.5(tons): 0.10000000000000001
HAPS: 0
So2: 0

Year: 2017
VOC(tons): 0.41999999999999998
NOx(tons): 5.2599999999999998
Co(tons): 1.6799999999999999
Co2(tons): 818.11000000000001
Particulates: 0.10000000000000001
PM10(tons): 0
PM2.5(tons): 0.10000000000000001
HAPS: 0
So2: 0

Year: 2016
VOC(tons): 0.93000000000000005
NOx(tons): 3.9399999999999999
Co(tons): 2.6699999999999999
Co2(tons): 579.99000000000001
Particulates: 0.82999999999999996
PM10(tons): 0.82999999999999996
PM2.5(tons): 0

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

HAPS:	0
So2:	0
Year:	2015
VOC(tons):	1.1200000000000001
NOx(tons):	4.8099999999999996
Co(tons):	3.48
Co2(tons):	779.54999999999995
Particulates:	1
PM10(tons):	1
PM2.5(tons):	0
HAPS:	0
So2:	0
Year:	2014
VOC(tons):	1.2
NOx(tons):	4.8300000000000001
Co(tons):	3.1099999999999999
Co2(tons):	403.69
Particulates:	0.98999999999999999
PM10(tons):	0.98999999999999999
PM2.5(tons):	0
HAPS:	0
So2:	0
Year:	2013
VOC(tons):	1.1899999999999999
NOx(tons):	4.8300000000000001
Co(tons):	3.23
Co2(tons):	403.69
Particulates:	1.05
PM10(tons):	1.05
PM2.5(tons):	0
HAPS:	0
So2:	0
Year:	2012
VOC(tons):	0.66000000000000003
NOx(tons):	2.71
Co(tons):	1.8300000000000001
Co2(tons):	333.88
Particulates:	1.1499999999999999
PM10(tons):	1.1499999999999999
PM2.5(tons):	0.57999999999999996
HAPS:	0
So2:	0
Year:	2011
VOC(tons):	0.66000000000000003
NOx(tons):	2.71
Co(tons):	1.8300000000000001
Co2(tons):	333.88
Particulates:	0.57999999999999996
PM10(tons):	0.57999999999999996
PM2.5(tons):	4.0000000000000001E-2
HAPS:	0
So2:	0

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Year:	2010
VOC(tons):	0.90000000000000002
NOx(tons):	3.6800000000000002
Co(tons):	2.48
Co2(tons):	397.80000000000001
Particulates:	0.80000000000000004
PM10(tons):	0.80000000000000004
PM2.5(tons):	0.80000000000000004
HAPS:	0
So2:	0

HSWDS:

Facility ID:	HS2012
Region:	2
Facility Status:	Unknown
Owner Type:	Publ Utily
Owner:	Brooklyn Union Gas Co.
Owner Address:	195 Montague Street
Owner Phone:	(718)403-3053
Operator Type:	Unknown
Operator:	Unknown
Operator:	Unknown
Operator Phone:	Unknown
EPA ID:	NYD980532014
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	Unknown
RCRA Permitted:	Unknown
Site Code:	Coal Gasification Plant
Owner City State:	Brooklyn
Operator City State:	Not reported
Quadrange:	Unknown
Latitude:	40 43 10 N
Longitude:	73 55 45 W
Acres:	0.00
Operator Date:	1928
Close Date:	Unknown
Completed:	PA
Active:	Unknown
PCB's Disposed:	Unknown
Pesticides Disposed:	No
Metals Disposed:	Unknown
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	Environmental
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown

GREENPOINT ENERGY FACILITY (Continued) **S100494601**

Groundwater Contamination:	Unknown
Groundwater Classification:	Unknown
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	Unknown
Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	Not reported
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	Not reported
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

AH213 **GREENPOINT** **EDR MGP** **1008407892**
NNW **287 MASPETH AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11211**
0.359 mi.
1897 ft. **Site 3 of 7 in cluster AH**

Relative: Manufactured Gas Plants:
Higher No additional information available

Actual:
14 ft.

AH214 **BKLYN UNION GAS /GREENPOINT ENERGY FACIL** **SEMS-ARCHIVE** **1003863851**
NNW **287 MASPETH AVE** **NYD980532014**
1/4-1/2 **BROOKLYN, NY 11222**
0.359 mi.
1897 ft. **Site 4 of 7 in cluster AH**

Relative:
Higher

Actual:
14 ft.

SEMS Archive:

Site ID:	0201977
EPA ID:	NYD980532014
Name:	BKLYN UNION GAS /GREENPOINT ENERGY FACIL
Address:	287 MASPETH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11222
Cong District:	12
FIPS Code:	36047
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	02
Site ID:	0201977
EPA ID:	NYD980532014
Site Name:	BKLYN UNION GAS /GREENPOINT ENERGY FACIL
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1986-09-24 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	02
Site ID:	0201977
EPA ID:	NYD980532014
Site Name:	BKLYN UNION GAS /GREENPOINT ENERGY FACIL
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1986-09-05 04:00:00
Finish Date:	1986-09-24 04:00:00
Qual:	N
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0201977
EPA ID:	NYD980532014
Site Name:	BKLYN UNION GAS /GREENPOINT ENERGY FACIL
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1

BKLYN UNION GAS /GREENPOINT ENERGY FACIL (Continued) **1003863851**

Start Date: 1981-06-01 04:00:00
Finish Date: 1981-06-01 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf

AH215 **GREENPOINT** **NY SHWS** **S104787368**
NNW **287 MASPETH AVENUE** **NY SWF/LF** **N/A**
1/4-1/2 **BROOKLYN, NY 11211** **NY LTANKS**
0.359 mi. **NY MOSF**
1897 ft. **Site 5 of 7 in cluster AH** **NY TANKS**
NY VCP
Relative: Higher **NY BROWNFIELDS**
NY Spills
Actual: 14 ft. **NY MANIFEST**

SHWS:
Name: K - GREENPOINT MGP - ENERGY CENTER
Address: 287 MASPETH AVENUE
City,State,Zip: BROOKLYN, NY 11211
Program: HW
Site Code: 372971
Classification: Significant threat to the public health or environment - action required.
Region: 2
Acres: 117.000
HW Code: 224052
Record Add: 11/02/2006
Record Upd: 06/07/2021
Updated By: DJEATON
Site Description: "Location: The site is a large parcel located along Newtown Creek at 287 Maspeth Avenue in Brooklyn,NY in Kings County. It is bounded by Newtown Creek to the east, Maspeth Ave. to the south, Vandevoort Ave. to the west, and Lombardy St. to the north. This is a large property at 117 acres. Site Features: The site is currently known as the Greenpoint Energy Center and houses a major liquefied natural gas storage facility and compressor station, an operations center for KeySpan's distribution and service units, and a warehouse facility. Current zoning and land uses: Surrounding land uses are mixed industrial, residential, and commercial. The nearest residential land use is located adjacent to the northwest corner of the site. Past use of the site: A large manufactured gas plant (MGP) and byproduct coking operation operated on the site from 1928 until 1952. Coal tar has been found in subsurface soils, but the full extent of contamination has not yet been established. The surrounding neighborhood has also been subject to a large petroleum spill, apparently unrelated to the MGP. A VCA to address the northeast corner of the property was listed under V00631. This work was undertaken to allow expansion of the existing liquefied gas facility and included a relatively small portion of the site. A site-wide RI began in the summer of 2012. The RI will be conducted in 3 phases. Site Geology/hydrogeology: The site is underlain by fill and heterogeneous glacial deposits that include outwash sands with till and lenticular silt deposits. Bedrock is approximately 200 feet below the ground surface. Groundwater flows northeasterly, toward the Newtown Creek."
Env Problem: "A remedial investigation (RI) of the site was performed in a phased approach based on geography and the proximity to adjacent or nearby

GREENPOINT (Continued) **S104787368**

water bodies. Phases 1 and 2 of the RI were located on the eastern and southern boundaries of the site, respectively, and were implemented between October 2011 and March 2016. Phase 3 encompassed the remainder of the site and was implemented between April 2016 and July 2019. An earlier pre-design investigation (PDI) and supplemental PDI were performed to evaluate the potential need for an interim remedial measure (IRM) for non-aqueous phase liquid (NAPL) containment along the Newtown Creek loading platform. The PDI findings indicated that there were no identified subsurface NAPL migration pathways from the site to Newtown Creek sediment, and potentially mobile NAPL was not identified. Throughout the course of site investigations, soil, groundwater, and sediment samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), metals and cyanide. In addition, soils were analyzed for pesticides, herbicides, hexavalent chromium and total organic carbon while groundwater was analyzed for per- and polyfluoroalkyl substances (PFAS) and 1,4-dioxane. Sediment analysis also included pesticides, herbicides, ammonia, hexavalent chromium, dioxins and furans, total petroleum hydrocarbons (TPH), diesel range organics (DRO), black carbon, pH, sulfide, total nitrogen, total organic carbon, total phosphorus, normal alkanes and isoprenoid hydrocarbons. Soil vapor and indoor air have been analyzed for VOCs and naphthalene. Nature and Extent of Contamination: The principal contaminant of concern at the site is MGP related coal tar and associated petroleum contamination. Coal tar contains various volatile organic compounds (VOCs), primarily benzene, toluene, ethylbenzenes, and xylenes (collectively known as BTEX). A family of compounds referred to as polycyclic aromatic hydrocarbons (PAHs) are also associated with MGP coal tar. Areas of potentially NAPL-saturated soil were generally isolated to the southern portion of the Loading Platform Area and in the vicinity of Holder 1 along Maspeth Avenue. Three wells have accumulated recoverable coal tar; two in the loading platform area and one along Maspeth Avenue. No visual observations of potentially NAPL-saturated soil have been identified in the borings advanced within the site interior and no measurable NAPL has been visually observed in any of the wells installed within the interior. Soil: Soil concentrations above the Industrial Use Soil Cleanup Objectives (IUSCOs) primarily included PAHs. In the shallow zone, PAH exceedances of the IUSCOs were identified throughout the site; PAH concentrations generally decreased with depth and were largely identified in areas with noted physical impacts, particularly the Loading Platform Area where PAH exceedances of IUSCOs continued into the deep zone. The maximum concentration of total PAHs was observed near the Loading Dock Area at a concentration of 67,350 mg/kg in a sample collected from three to four feet below grade (ft bg). Concentrations of BTEX above the IUSCOs were identified in a limited number (total of three) samples sitewide. The maximum total BTEX concentration detected was 2,137.4 mg/kg from a sample collected from 15-16 ft bg along the Maspeth Alignment. Detections of metals in soil were mostly limited to the shallow zone. Detections in the intermediate or deep zones were limited to sporadic and relatively low detections of arsenic. Detections of cyanide were few and relatively low in concentration. The cyanide detections were generally limited to the site interior and were confined to the shallow soil zone. The maximum cyanide concentration detected was 29.4 mg/kg from three to four ft bg in the area of the former purifiers. There have been no detections of

GREENPOINT (Continued) **S104787368**

pesticides or herbicides above the IUSCOs. There were no PCB detections in soil above IUSCOs. Groundwater: Groundwater exceedances of standards and guidance values primarily included total BTEX, PAHs, chlorinated volatile organic compounds (CVOCs) and metals; cyanide and PCBs were detected in exceedance less frequently. The areas of elevated BTEX and PAH concentrations were primarily located near the southern Loading Platform Area in the vicinity of the identified soil impacts and along the southern property boundary along Maspeth Avenue. Elevated CVOC concentrations were generally found along the northern and western site perimeters and can be attributed to off-site sources. Total BTEX in groundwater ranged from non-detect (ND) to 455,100 parts per billion (ppb). Total PAHs in groundwater ranged from ND to 12,459 ppb. Numerous metals were detected above their corresponding standards, including arsenic, iron, lead, magnesium, manganese, and sodium, likely associated with regional conditions rather than historical site operations. Total cyanide concentrations in groundwater ranged from ND to 1,060 ppb. PCB exceedances were limited to three of the 148 groundwater samples analyzed, with a maximum total concentration of 1.54 ppb. Groundwater results were non-detect for 1,4-dioxane. While perfluorooctanesulfonic acid (PFOS) and perfluorooctanoic acid (PFOA) were occasionally detected in groundwater above guidance values, total PFAS concentrations were not detected in any well above guidance values. The maximum PFOS concentration detected was 57.9 parts per trillion (ppt) while the maximum PFOA concentration was 97.5 ppt and maximum total PFAS concentration was 256.17 ppt. These PFAS concentrations are not indicative of a source area and concentrations are likely associated with off-site sources. Soil Vapor: Sub-slab vapor and indoor air samples were collected during 2018 and 2019. Results varied across the site from no further action (nine buildings) to identifying sources and resampling (two buildings) to mitigation recommendations (three buildings). Additional SVI sampling is to take place during the 2021 heating season."

Health Problem:	"Public exposures to wastes in soil and groundwater at the site are unlikely since access to the site is restricted. Potential impacts from soil vapors need to be evaluated. Potential exposures to seepage from the site in the adjacent Newtown Creek are unknown. Eating of fish and shellfish from Newtown Creek is restricted based on fish advisories for the East River, which apply to Newtown Creek as a tributary."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	False
Record Add:	2006-11-06 14:08:00
Record Upd:	2013-09-20 14:11:00
Updated By:	ldennist
Own Op:	1
Sub Type:	NNN
Owner Name:	N/A
Owner Company:	BROOKLYN UNION GAS COMPANY

GREENPOINT (Continued) **S104787368**

Owner Address: 1 METROTECH CENTER
Owner Addr2: Not reported
Owner City,St,Zip: BROOKLYN, NY 11201
Owner Country: United States of America
HW Code: 224052
Waste Type: BENZO(A)PYRENE
Waste Quantity: 33.00
Waste Code: Not reported
HW Code: 224052
Waste Type: NAPHTHALENE
Waste Quantity: 17.00
Waste Code: Not reported
HW Code: 224052
Waste Type: PYRENE
Waste Quantity: 83.00
Waste Code: Not reported
HW Code: 224052
Waste Type: BENZENE
Waste Quantity: 3.30
Waste Code: Not reported
HW Code: 224052
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224052
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2006012
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-12-02 13:44:00
Record Updated: 2020-12-02 13:44:00
Updated By: GLWHITE

SWF/LF:
Name: NATIONAL GRID
Address: 287 MASPETH AVENUE
City,State,Zip: BROOKLYN, NY 11222
Flag: ACTIVE
Region Code: 2
Phone Number: 7182705786
Owner Name: Mattia Auriemma
Owner Type: Private
Owner Address: 84-24 Ditmas Ave
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11236
Owner Email: Not reported
Owner Phone: 7182705786
Contact Name: Mattia Auriemma
Contact Address: Not reported
Contact Addr2: Not reported
Contact City,St,Zip: Not reported
Contact Email: mattia@nationalgrid.com
Contact Phone: 7182705786
Activity Desc: C&D processing - registration
Activity Number: [24W38]

GREENPOINT (Continued) **S104787368**

Active:	Yes
East Coordinate:	590245
North Coordinate:	4508023
Accuracy Code:	4.3 - Utilization of Digital Orthophoto Quads
Regulatory Status:	Registration
Waste Type:	Asphalt;Concrete;Brick;Rock;Soil (Clean);Construction & Demolition Debris
Authorization #:	24W38
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Larry Caonigro
Operator Type:	Private
Laste Date:	9/8/2021

LTANKS:

Name:	CLOSED-LACKOF RECENT INFO
Address:	287 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9009058 / 2003-03-04
Facility ID:	9009058
Site ID:	118273
Spill Date:	1990-11-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1990-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1990-11-20
Spill Record Last Update:	2003-03-04
Spiller Name:	Not reported
Spiller Company:	BROOKLYN UNION GAS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	102793
DEC Memo:	""
Remarks:	"4K TANK FAILED HORNER EZY CHECK WITH AN UNDETERMINED LEAK RATE, WILL EXCAVATE, ISOLATE,REPAIR & RETEST. CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS."

All TTF:

Facility ID:	9009058
Spill Number:	9009058

GREENPOINT (Continued) **S104787368**

Spill Tank Test:	1537896
Site ID:	118273
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	118273
Operable Unit ID:	949558
Operable Unit:	01
Material ID:	432836
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	KEYSPAN ENERGY
Address:	287 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Spill Number/Closed Date:	9211562 / 2007-02-06
Facility ID:	9211562
Site ID:	181619
Spill Date:	1993-01-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	VSZHUNE
Referred To:	Not reported
Reported to Dept:	1993-01-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-01-08
Spill Record Last Update:	2007-02-06
Spiller Name:	FACILITY MANAGER

GREENPOINT (Continued) **S104787368**

Spiller Company:	KEYSPAN ENERGY
Spiller Address:	ONE METROTECH CENTER
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	14020
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL This spill case was reassigned from DEC (Sigona) to Rommel on 01/07/2004. Per Bart Polozzitti of Keyspan(516-545-5511), major renovations have occurred at the site. The tank may have been removed, he will forward relevant information when gathered. 01/02/07-Zhune got an e-mail from Bart Polozzitti requesting additional time to get the information. He said hopefully he will get it by 02/17/07. Bart Polozzitti cell # 646-2350403 01/09/07 Bart sent the information a tightness test report from Tanknology Corp. and a letter is included. The letter state the following: The subject underground storage tank (361A)located at 287 Maspeth Ave. Brooklyn, New York was tightness tested unsuccessfully on january 7, 1993. The other three fuel thanks on the same facility (Nos. 363, 364 &365) were tested tight on the same day. After repairing the vent connections causing the ullage leak above the level of product, the tank was retested on January 25, 1993 and passed. There was no release at any time to the surrounding environment. Spill Closed "
Remarks:	"EIR"

All TTF:

Facility ID:	9211562
Spill Number:	9211562
Spill Tank Test:	1541042
Site ID:	181619
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	181619
Operable Unit ID:	978534
Operable Unit:	01
Material ID:	404952
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

GREENPOINT (Continued) **S104787368**

Recovered: .00
Oxygenate: Not reported

MOSF:
Name: GREENPOINT ENERGY FACILITY
Address: 287 MASPETH AVENUE
City,State,Zip: BROOKLYN, NY 11211
Facility ID: 2-2340
Program Type: MOSF
Tank Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: 590195.67868
UTMY: 4507995.25372

TANKS:
Name: NATIONAL GRID GREENPOINT SERVICE CENTER
Address: 287 MASPETH AVENUE
City,State,Zip: BROOKLYN, NY 11211
Facility Id: 2-306398
Region: STATE
DEC Region: 2
Site Status: Active
Program Type: PBS
Expiration Date: 07/14/2022
UTM X: 590235.61396
UTM Y: 4508095.73908

VCP:
Name: GREENPOINT
Address: 287 MASPETH AVENUE
City,State,Zip: BROOKLYN, NY 11211
Program Type: VCP
Site Code: 57149
HW Code: V00631
Site Class: A
SWIS: 2401
Region: 2
Town: New York City
Acres: 2.000
Date Record Added: 01/16/2003
Date Record Updated: 06/30/2009
Updated By: GWCROSS
Site Description: " The Greenpoint Energy Center is located in the Greenpoint section of Brooklyn, New York. The surrounding area is dominated by industrial and commercial uses with a limited residential area northwest of the the site. "
Env Problem: "The site is impacted by MGP residuals. Coal tar is present at the site. KeySpan has proposed to remediate the most accessible contamination and leave the remaining contamination in place. The proposed remedy is under review by the department."
Health Problem: "Public exposures to wastes in soil and groundwater at the site are unlikely since access to the site is restricted. Potential impacts from soil vapors need to be evaluated. Potential exposures to seepage from the site in the adjacent Newtown Creek are unknown. Eating of

GREENPOINT (Continued) **S104787368**

fish and shellfish from Newtown Creek is restricted based on fish advisories for the East River, which apply to Newtown Creek as a tributary."

Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	KEYSPAN ENERGY DELIVERY - NY
Owner Address:	ONE METROTECH CENTER
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11201
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	KEYSPAN ENERGY DELIVERY - NY
Owner Address:	ONE METROTECH CENTER
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11201
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	9009058
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2003-01-16 09:45:00
Record Updated:	2003-01-16 09:46:00
Updated By:	brhumphr
Crossref ID:	9305107
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2003-01-16 09:46:00
Record Updated:	2003-01-16 09:46:00
Updated By:	brhumphr

BROWNFIELDS:

Name:	K - GREENPOINT MGP - ENERGY CENTER
Address:	287 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Program:	BCP
Site Code:	57389
Acres:	119.000
HW Code:	C224052
SWIS:	2401

GREENPOINT (Continued) **S104787368**

Town:	New York City
Record Added Date:	04/30/2004
Record Updated Date:	12/07/2009
Update By:	MOBARRIE
Site Description:	"See Site 224052"
Env Problem:	""
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	KEYSPAN
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	Unknown
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	KEY SPAN
Address:	287 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0004653 / 2003-02-24
Facility ID:	0004653
Facility Type:	ER
DER Facility ID:	102793
Site ID:	181394
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	B3
SWIS:	2401
Spill Date:	2000-07-18
Investigator:	SACCACIO
Referred To:	Not reported
Reported to Dept:	2000-07-18
CID:	211
Water Affected:	Not reported

GREENPOINT (Continued) **S104787368**

Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-18
Spill Record Last Update:	2003-02-24
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JOHN TUFFARELLI
DEC Memo:	""
Remarks:	"CALLER STATES PRIVATE TRACTOR TRAILER OWNERS MAKE REPAIR TO THEIR VEHICLES IN THE STREET AND THE RESIDUAL FUEL IS SPILLED ON STREET AND THERE IS NO CLEAN UP "

All Materials:

Site ID:	181394
Operable Unit ID:	825775
Operable Unit:	01
Material ID:	549386
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GREENPOINT KEY SPAN
Address:	287 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0303442 / 2003-07-09
Facility ID:	0303442
Facility Type:	ER
DER Facility ID:	102793
Site ID:	181395
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	2003-07-02
Investigator:	JXZHAO
Referred To:	Not reported
Reported to Dept:	2003-07-02
CID:	199
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

GREENPOINT (Continued) **S104787368**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-07-02
Spill Record Last Update:	2003-08-08
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	BART POLIZZOTTI
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHAO "
Remarks:	"contractor cleaning out drain accidentally dumped approx 2 yds of oily sludge type materal on ground at location - clean up crew enroute"

All Materials:

Site ID:	181395
Operable Unit ID:	870549
Operable Unit:	01
Material ID:	504309
Material Code:	0058A
Material Name:	sludge
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BROOKLYN UNION
Address:	287 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9714234 / 1998-03-31
Facility ID:	9714234
Facility Type:	ER
DER Facility ID:	102793
Site ID:	181396
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	1998-03-24
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1998-03-24
CID:	211
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-03-24

GREENPOINT (Continued) **S104787368**

Spill Record Last Update:	1998-05-22
Spiller Name:	MARY CASEY
Spiller Company:	BROOKLYN UNION
Spiller Address:	287 MASPETH AV
Spiller Company:	001
Contact Name:	MARY CASEY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE CLEANED BY RP. "
Remarks:	"DRUM LEAKED CAUSING SPILL ONTO SOIL - SOIL HAS BEEN EXCAVATED"

All Materials:

Site ID:	181396
Operable Unit ID:	1060065
Operable Unit:	01
Material ID:	325205
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

Name:	DRUM RUN
Address:	287 MASPETH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0908872 / 2009-12-09
Facility ID:	0908872
Facility Type:	ER
DER Facility ID:	370502
Site ID:	421533
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2009-11-07
Investigator:	HRAHMED
Referred To:	Not reported
Reported to Dept:	2009-11-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-07
Spill Record Last Update:	2009-12-09
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	KAKEEMA

GREENPOINT (Continued) **S104787368**

DEC Memo: "12/09/09-HRAHMED-One Drum of oil was vacuumed up during DRUM RUN on 12/04/09. DEP and Sanitation were notified. This case is closed. "
Remarks: "1238 THE CALLER ADVISED THE DRUM WAS LABELED BY DEP AND THEY ARE AWAITING DEC TO PICKUP THE DRUM."

All Materials:
Site ID: 421533
Operable Unit ID: 1177420
Operable Unit: 01
Material ID: 2170210
Material Code: 0063A
Material Name: unknown hazardous material
Case No.: Not reported
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

Name: ROADWAY
Address: 287 MASPETH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0506134 / 2005-08-18
Facility ID: 0506134
Facility Type: ER
DER Facility ID: 102793
Site ID: 351275
DEC Region: 2
Spill Cause: Other
Spill Class: Not reported
SWIS: 2401
Spill Date: 2005-08-18
Investigator: JBVOUGHT
Referred To: Not reported
Reported to Dept: 2005-08-18
CID: 409
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2005-08-18
Spill Record Last Update: 2005-08-18
Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN
Spiller Company: 999
Contact Name: ED MILLER
DEC Memo: "8/18/05-Vought-Called Ed and NYFD and NYPD left scene. FDNY put sand around pooled oil. NO responsible parties seen. FDNY diked oil. Pool is near gutter and spill originated from the middle of the street. Pooled oil is 3'x3'. FDNY contact is Captain Horton (Ladder 146) and Captain Villendahl (Engine 206). No sewers or drains affected and DEP

GREENPOINT (Continued) **S104787368**

was contacted. Vought called Sanitation Operations and they were previously called and are on their way. Spill closed by Vought."
Remarks: "YOU CAN SEE THE TRAIL OF MOTOR OIL ON THE ROADWAY. CLEAN UP IS NOT IN PROCESS. NOT THEIR RESPOSIBILY. ED CELL #917-731-8543."

All Materials:
Site ID: 351275
Operable Unit ID: 1108800
Operable Unit: 01
Material ID: 2098772
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 25.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: DRUM RUN
Address: 287 MASPETH AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0908424 / 2009-11-06
Facility ID: 0908424
Facility Type: ER
DER Facility ID: 370033
Site ID: 421024
DEC Region: 2
Spill Cause: Abandoned Drums
Spill Class: C4
SWIS: 2401
Spill Date: 2009-10-27
Investigator: HRAHMED
Referred To: Not reported
Reported to Dept: 2009-10-27
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2009-10-27
Spill Record Last Update: 2009-11-06
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: JOE SLEEM
DEC Memo: "11/06/09-HRAHMED-one 50 gal drum was found and emptied during drum run on 11/06/09. DEP and Sanitation were notified. This case is closed. "
Remarks: "55Gal drum, half full/not leaking"

GREENPOINT (Continued) **S104787368**

All Materials:

Site ID:	421024
Operable Unit ID:	1176958
Operable Unit:	01
Material ID:	2169669
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	22.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	KEYSPAN COMPLEX
Address:	287 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0413650 / 2005-04-04
Facility ID:	0413650
Facility Type:	ER
DER Facility ID:	102793
Site ID:	342804
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	2401
Spill Date:	2005-03-31
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2005-03-31
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2005-03-31
Spill Record Last Update:	2005-04-04
Spiller Name:	ED MILLER
Spiller Company:	KEYSPAN COMPLEX
Spiller Address:	287 MASBETH AVE
Spiller Company:	001
Contact Name:	ED MILLER
DEC Memo:	"minor spill - closed"
Remarks:	"10 GALLONS OF AGATINE PARTS CLEANER: WHEN MOVING A DRUM WITH A FORK LIFT, THE DRIVER PUT TEH FORK THROUGH THE DRUM: IN PROCESS OF BEING CLEANED UP:"

Name:	SUBSTATION
Address:	287 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0310061 / 2003-12-17

GREENPOINT (Continued) **S104787368**

Facility ID:	0310061
Facility Type:	ER
DER Facility ID:	102793
Site ID:	94159
DEC Region:	2
Spill Cause:	Other
Spill Class:	C3
SWIS:	2401
Spill Date:	2003-11-26
Investigator:	CESAWYER
Referred To:	Not reported
Reported to Dept:	2003-11-26
CID:	403
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2003-12-17
Spiller Name:	MIKE RUSSO
Spiller Company:	SUBSTATION
Spiller Address:	287MASPETH AVE.
Spiller Company:	001
Contact Name:	MIKE RUSSO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 12/11/03 1038 Hrs - Sawyer - Talked to Rob Lowe and Bart Polozotti (516) 545-5511 of Keyspan. They said it was taken care of in house. One of the hazmat personnel, an Eddie will get back to me with disposal information. Closed."
Remarks:	"1-3 gallons spilled out at a substation and all of it was cleaned up"
	Not reported

All Materials:

Site ID:	94159
Operable Unit ID:	877718
Operable Unit:	01
Material ID:	499002
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SOIL
Address:	287 MASPETH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1701762 / 2018-08-15
Facility ID:	1701762
Facility Type:	ER

GREENPOINT (Continued) **S104787368**

DER Facility ID:	394939
Site ID:	548872
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2017-05-22
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2017-05-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-05-23
Spill Record Last Update:	2018-08-15
Spiller Name:	BRITTANY
Spiller Company:	NATIONAL GRID
Spiller Address:	287 MASPETH AVE
Spiller Company:	999
Contact Name:	BRITTANY
DEC Memo:	"05/23/17-Hiralkumar Patel. 1:17 PM:- spoke with Brittany. they are removing two USTs: one 4,000 gal gasoline and one 1,000 gal diesel UST. during removal of diesel tank, crew noted some odors and upto 100 ppm on PID in soil. the tanks were located on concrete pad at 9 ft bg. crew has removed concrete pad and noted groundwater at bottom of excavation at approx. 10 ft bg. no sheen or product noted on groundwater. D&B will remove tank piping and dispenser islands and will collect endpoint soil and groundwater samples. two new tanks will be installed at the same location. Brittany Gaddy D&B Engineering and Architects, P.C. Ph. (516) 364-9890 Ext. 3439 email: bgaddy@db-eng.com National Grid **site operator** 175 East Old Country Road Hicksville, NY 11801 Attn.: Michael Lauro Environmental Engineering Ph. (516) 545-2562 email: michael.lauro@nationalgrid.com 1:39 PM:- sent letter to Mr. Lauro requiring submission of spill cleanup report by the end of 06/30/17. letter emailed to Mr. Lauro and Brittany. case assigned to DEC Zhune. 8/1/17- Brittany email-As discussed, attached to this email is analytical data, tables and an end point sample location map for NYSDEC review for Spill No. 1701762. Below is a detailed summary of the work that is taking place during the removal and installation of two USTs at the National Grid Greenpoint Energy Center, located at 287 Maspeth Avenue in Brooklyn. National Grid is in the process of removing a 4,000-gallon gasoline UST and a 1,000-gallon diesel UST. Upon removal of the USTs, the Contractor will install 27 concrete filled piles, pour a bottom slab and install two new 10,000-gallon USTs in the same location. Existing piping will be removed after the new tanks are in place and the excavation backfilled. End point samples will also be collected for piping excavation as requested by DEC. On May 23, 2017 during excavation related to existing tank removal, some soils were identified that appeared to be impacted due to elevated PID readings

GREENPOINT (Continued) **S104787368**

and a diesel odor. D&B notified the NYSDEC of a historical petroleum release at the site and a spill case initiated. Soil with elevated PID readings was segregated. Upon removal of the USTs, 14 end point samples were collected and analyzed for the tank excavation. Please see attached for a site plan of the existing fueling station that has been marked with approximate end point sample locations. Table 1, which provides a summary of the removed tanks is attached for reference. Table 2, which provides a summary of PID Readings is also attached for reference. Analytical data related to the endpoint sampling indicates that all VOCs were non detect with the exception of sample GBN which has one exceedance. For sample GBN, benzene was detected at a concentration of 250 ug/kg which exceeds for unrestricted use. This concentration of benzene does not exceed for restricted industrial use. There were several SVOC exceedances for unrestricted and restricted use; however, the Site is known to contain historic fill. Soil borings taken from the area near the USTs show historic fill present up to 12-17 feet below grade.
Additionally, the National Grid Greenpoint Energy Center is a former MGP site and is adjoined by Newtown Creek, a designated Superfund site to the east. As the DEC has requested that the tank closure report include piping excavation endpoint samples, the report cannot be finalized until the new tank installation is complete. However, due to the results of the endpoint sampling below the old USTs, we are requesting NYSDEC review/approval of analytical data provided to close Spill No. 1701762 at this time. A groundwater sample was collected from the base of the former UST excavation. The groundwater sample indicate one VOC (1500 ug/lt Naphathalene)and multiple SVOCs exceedance their repective NYSDEC GWGS. Following the product piping, vent piping and dispensers island removal, five (5) soil sample were collected from those respective areas. All VOC conccentrations were determined to be below their respective SCO's limits. However, the two (2) samples analyzed via EPA Methos 8270, sample 2 and sample 4, exhibited concentrations of several SVOCs above their respective SCOs. On July 30, 2018 I received an email from John Miller and I spoke with him. The email stated that My name is John Miller and I am the NYSDEC project manager for Greenpoint MGP Site (224052). I was informed recently that National Grid is hoping to close out a spill at the site. My understanding is that any contamination that remains related to the spill would be address under the MPG program. I only just to heard of this issue last week, but after speaking with Grid it sounds like reasonable approach. I wanted to confirm with you whether you agree or not. Do you have any issues or concern?. Based on John Miller's email that any contamination that remains related to the spill would be addressed under the MPG program # 224052 this spill is closed. Spill closed. "

Remarks: "clean up is pending soil tested positive for materials pbs 2-306398"

All Materials:

Site ID:	548872
Operable Unit ID:	1296965
Operable Unit:	01
Material ID:	2303087
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported

GREENPOINT (Continued) **S104787368**

Recovered: Not reported
Oxygenate: Not reported

Name: BROOKLYN UNION GAS
Address: 287 MASPETH AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9305107 / 2005-03-28
Facility ID: 9305107
Facility Type: ER
DER Facility ID: 102793
Site ID: 118274
DEC Region: 2
Spill Cause: Other
Spill Class: C3
SWIS: 2401
Spill Date: 1993-07-13
Investigator: JMROMMEL
Referred To: Not reported
Reported to Dept: 1993-07-23
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1993-07-26
Spill Record Last Update: 2005-03-28
Spiller Name: Not reported
Spiller Company: BROOKLYN UNION GAS
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL / / : CONTAMINATION FOUND. INVESTIGATING. 10/10/95: This is additional information about material spilled from the translation of the old spill file: TANK REMOVAL. 4/12/04-Vought-Spill transferred from Tibbe to Rommel as per Rommel. 3/28/05 - spill closed, refer to 9211562 for tracking. KST"
Remarks: "TANK REMOVAL - WAIT FOR RESULTS."

All Materials:
Site ID: 118274
Operable Unit ID: 986690
Operable Unit: 01
Material ID: 567298
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported

GREENPOINT (Continued) **S104787368**

Name:	NAT GRID GREEN POINT FACILITY
Address:	287 MASPETH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1006581 / 2010-09-17
Facility ID:	1006581
Facility Type:	ER
DER Facility ID:	394939
Site ID:	439941
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2010-09-17
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2010-09-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-09-17
Spill Record Last Update:	2010-09-17
Spiller Name:	Not reported
Spiller Company:	NAT GRID
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MARTIN BRUCELLA
DEC Memo:	""
Remarks:	"APPROX 25-30 GALLONS OF GAS MAIN DRIP WATER SPILLED TO SOIL/ASPHALT AND GRAVEL. CLEANUP IN PROGRESS."

All Materials:

Site ID:	439941
Operable Unit ID:	1190570
Operable Unit:	01
Material ID:	2185598
Material Code:	9999
Material Name:	other - GAS MAIN DRIP WATER
Case No.:	Not reported
Material FA:	Other
Quantity:	30.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Click this hyperlink while viewing on your computer to access
7 additional NY SPILL: record(s) in the EDR Site Report.

NY MANIFEST:

Name:	KEYSPAN - LNG PLANT GREENPOINT

GREENPOINT (Continued) **S104787368**

Address:	287 MASPETH AVE
City,State,Zip:	BROOKLYN, NY 11211-0000
Country:	USA
EPA ID:	NYD006978795
Facility Status:	Not reported
Location Address 1:	287 MASPETH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11211
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD006978795
Mailing Name:	KEYSPAN - LNG PLANT GREENPOINT
Mailing Contact:	AMY DROGALIS
Mailing Address 1:	175 E OLD COUNTRY RD
Mailing Address 2:	Not reported
Mailing City:	HICKSVILLE
Mailing State:	NY
Mailing Zip:	11801
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9175600908

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	12/30/2014
Trans1 Recv Date:	12/30/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/07/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD006978795
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000806357VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141

GREENPOINT (Continued) **S104787368**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH216 **BUG, MASPETH GATE STATION** **NY HSWDS** **S108147014**
NNW **285 MASPETH AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY 11222**
0.360 mi.
1899 ft. **Site 6 of 7 in cluster AH**

Relative:
Higher

Actual:
14 ft.

HSWDS:

Facility ID:	Not reported
Region:	2
Facility Status:	Unknown
Owner Type:	Publ Utily
Owner:	Brooklyn Union Gas
Owner Address:	195 Montague Street
Owner Phone:	(718)403-3053
Operator Type:	Unknown
Operator:	Unknown
Operator:	Unknown
Operator Phone:	Unknown
EPA ID:	NYD980532220
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	Unknown
RCRA Permitted:	Unknown
Site Code:	Coal Gasification Plant
Owner City State:	Brooklyn
Operator City State:	Not reported
Quadrange:	Unknown
Latitude:	40 43 10 N
Longitude:	73 55 45 W
Acres:	0.00
Operator Date:	1981
Close Date:	Unknown
Completed:	PA
Active:	Unknown
PCB's Disposed:	Unknown
Pesticides Disposed:	No
Metals Disposed:	No
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	No

BUG, MASPETH GATE STATION (Continued) **S108147014**

Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	Environmental
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown
Groundwater Contamination:	Unknown
Groundwater Classification:	Unknown
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	Unknown
Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

AH217 **BKLYN UNION GAS /MASPETH GATE STA** **SEMS-ARCHIVE** **1003863866**
NNW **285 MASPETH AVE** **NYD980532220**
1/4-1/2 **BROOKLYN, NY 11222**
0.360 mi.
1899 ft. **Site 7 of 7 in cluster AH**

Relative:
Higher

Actual:
14 ft.

SEMS Archive:

Site ID:	0201996
EPA ID:	NYD980532220
Name:	BKLYN UNION GAS /MASPETH GATE STA
Address:	285 MASPETH AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11222
Cong District:	12
FIPS Code:	36047
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	02
Site ID:	0201996
EPA ID:	NYD980532220
Site Name:	BKLYN UNION GAS /MASPETH GATE STA
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1986-09-24 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	02
Site ID:	0201996
EPA ID:	NYD980532220
Site Name:	BKLYN UNION GAS /MASPETH GATE STA
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1981-06-01 04:00:00
Finish Date:	1981-06-01 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0201996
EPA ID:	NYD980532220
Site Name:	BKLYN UNION GAS /MASPETH GATE STA
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1

BKLYN UNION GAS /MASPETH GATE STA (Continued) **1003863866**

Start Date: 1986-09-05 04:00:00
Finish Date: 1986-09-24 04:00:00
Qual: N
Current Action Lead: EPA Perf

AF218 **SCHOLES ST. STATION** **EDR MGP** **1008407899**
SW **SCHOLES ST 7 BOGART STS. MESSEROLE AND MORGAN AVE.** **N/A**
1/4-1/2 **BROOKLYN, NY 11206**
0.360 mi.
1901 ft. **Site 2 of 2 in cluster AF**

Relative: **Higher**
Actual: **17 ft.**

Manufactured Gas Plants:
No additional information available

AL219 **DITMAS OIL ASSOCIATES, INC.** **NY MOSF UST** **S103275710**
North **364 MASPETH AVENUE** **NY AST** **N/A**
1/4-1/2 **BROOKLYN, NY 11211** **NY CBS AST**
0.361 mi. **NY MOSF AST**
1908 ft. **Site 1 of 3 in cluster AL** **NY AIRS**

Relative: **Lower**
Actual: **12 ft.**

MOSF UST:

Id/Status:	2-1340 / ACTIVE FACILITY
SWIS Code:	61
Facility Town:	NEW YORK CITY
Contact Phone:	(718) 782-4200
Emergency Contact:	ROBERTO PORCELLI
Emergency Telephone:	(718) 782-4200
CBS Number:	Not reported
SPDES Num:	0-005789
Total Tanks:	19
Total Capacity:	3515318
Avg Throughput:	560000
License Stat:	1
Facility Type:	STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Prod Xfer Options:	AD
Expiration Date:	03/31/2002
Applic Rcvd:	01/05/2001
Operator:	ROBERTO PORCELLI
Owner Name:	MALU PROPERTIES, INC.
Owner Address:	364 MASPETH AVENUE
Owner City,St,Zip:	BROOKLYN, NY 11211-
Owner Telephone:	(718) 782-4200
Owner Type:	Corporate/Commercial
Owner Status:	2
Owner Mark:	Second Owner
Mail To Name:	DITMAS OIL ASSOCIATES, INC.
Mail To Address:	364 MASPETH AVENUE
Mail To Address 2:	Not reported
Mail City,St,Zip:	BROOKLYN, NY 11211-
Mail To Contact:	ROBERTO PORCELLI
Mail To Telephone:	(718) 782-4200
Legal Agent Name:	FRIEDLAND, LEIFFER, ROBBINS, LLP
Legal Agent Address:	233 BROADWAY

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Legal Agent City,St,Zip:	NEW YORK, NY 10274-
Date Filed:	Not reported
Latitude:	40|43|05
Longitude:	73|55|40

Tank ID:	001
Tank Location:	UNDERGROUND
Install Date:	01/70
Capacity (Gal):	4000
Product:	DIESEL
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	13
Pipe Location:	Not reported
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Impressed Current
Second Contain:	Other
Leak Detection:	Other
Overfill Protection:	53
Dispenser:	Suction
Test Date:	12/98
Date Closed:	Not reported
Status of Data:	Minor Errors
Inspected Date:	10/26/1998
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	002
Tank Location:	UNDERGROUND
Install Date:	04/76
Capacity (Gal):	2000
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Not reported
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	Impressed Current
Second Contain:	Other
Leak Detection:	None
Overfill Protection:	53
Dispenser:	Suction
Test Date:	12/98
Date Closed:	Not reported
Status of Data:	Minor Errors

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Inspected Date:	10/26/1998
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	003
Tank Location:	UNDERGROUND
Install Date:	04/76
Capacity (Gal):	1080
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Not reported
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Contain:	Other
Leak Detection:	None
Overfill Protection:	None
Dispenser:	Suction
Test Date:	12/98
Date Closed:	Not reported
Status of Data:	Minor Errors
Inspected Date:	10/26/1998
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	004
Tank Location:	UNDERGROUND
Install Date:	02/83
Capacity (Gal):	1080
Product:	UNKNOWN
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Not reported
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Second Contain:	Other
Leak Detection:	None
Overfill Protection:	None
Dispenser:	Gravity
Test Date:	02/99
Date Closed:	Not reported
Status of Data:	Minor Errors
Inspected Date:	10/26/1998
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	005
Tank Location:	UNDERGROUND
Install Date:	11/68
Capacity (Gal):	1080
Product:	UNKNOWN
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Not reported
Pipe Type:	GALVANIZED STEEL
Pipe Internal:	None
Pipe External:	None
Second Contain:	Other
Leak Detection:	None
Overfill Protection:	None
Dispenser:	Gravity
Test Date:	12/98
Date Closed:	Not reported
Status of Data:	Minor Errors
Inspected Date:	10/26/1998
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	108
Tank Location:	UNDERGROUND
Install Date:	12/65
Capacity (Gal):	244964
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	Temporarily Out Of Service

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	8
Leak Detection:	Groundwater Well
Overfill Protection:	23
Dispenser:	Submersible
Test Date:	08/98
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	10/26/1998
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	109
Tank Location:	UNDERGROUND
Install Date:	12/65
Capacity (Gal):	245101
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	8
Leak Detection:	Groundwater Well
Overfill Protection:	23
Dispenser:	Submersible
Test Date:	08/98
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	10/26/1998
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Tank ID:	110
Tank Location:	UNDERGROUND
Install Date:	12/65
Capacity (Gal):	288643
Product:	DIESEL
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Second Contain:	8
Leak Detection:	Groundwater Well
Overfill Protection:	23
Dispenser:	Submersible
Test Date:	08/98
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	10/26/1998
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	10/31/2001
Federal Id No:	Not reported
COI Date:	/ /

AST:

Name:	DITMAS OIL ASSOCIATES, INC.
Address:	364 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000328
Program Type:	CBS
UTM X:	590476.38524
UTM Y:	4508036.27253
Expiration Date:	N/A
Site Type:	Storage Terminal/Petroleum Distributor

Tank Info:

Tank Number:	10
Tank Id:	192184
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1996
Capacity Gallons:	12500
Tightness Test Method:	NN

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/01/2004
Register:	True
Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

CBS AST:

CBS Number:	2-000328
ICS Number:	Not reported
PBS Number:	Not reported
MOSF Number:	2-1340
SPDES Number:	-
Facility Status:	IN SERVICE
Facility Type:	B
Telephone:	(718) 782-4200
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	03/23/2003
Total Capacity of All Active Tanks(gal):	12500
Operator:	ROBERTO PORCELLI
Emergency Contact:	ROBERTO PORCELLI
Emergency Phone:	(718) 782-4200
Owner Name:	MALU PROPERTIES, INC.
Owner Address:	364 MASPETH AVENUE
Owner City,St,Zip:	BROOKLYN, NY 11211
Owner Telephone:	(718) 782-4200
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	DITMAS OIL ASSOCIATION
Mail Contact Addr:	364 MASPETH AVENUE
Mail Contact Addr2:	Not reported
Mail Contact Contact:	MR. ROBERTO PORCELLI
Mail Contact City,St,Zip:	BROOKLYN, NY 11211
Mail Phone:	(718) 782-4200

Tank Id:	10
CAS Number:	1330207
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	07/96
Tank Closed:	Not reported
Capacity (Gal):	12500
Chemical:	Xylene (mixed)
Tank Location:	Indoors, Belowground
Tank Type:	Steel/carbon steel
Total Tanks:	1
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	01/21/1997
Certified Date:	01/24/2001
Substance:	More than one Hazardous Substance on DEC List
Internal Protection:	Epoxy Liner
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	None
Overfill Protection:	24
Haz Percent:	52
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	40|43|05 / 73|55|40
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	2
Certificate Needs to be Printed:	40|43|05 / 73|55|40
Fiscal Amt for Registration Fee Correct:	40|43|05 / 73|55|40
Renewal Has Been Printed for Facility:	40|43|05 / 73|55|40
Pre-Printed Renewal App Last Printed:	40|43|05 / 73|55|40

MOSF AST:

MOSF Number:	2-1340
SWIS Code:	61
Facility Town:	NEW YORK CITY
Facility Phone:	(718) 782-4200
Emergency Contact Name:	ROBERTO PORCELLI
Emergency Contact Phone:	(718) 782-4200
Total Tanks:	19
Total Capacity:	3515318
Daily Throughput:	560000
License Status:	1
Facility Type:	STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Product Transfer Operation:	AD
Facility Status:	IN SERVICE
Operator Name:	ROBERTO PORCELLI
Owner Name:	MALU PROPERTIES, INC.
Owner Address:	364 MASPETH AVENUE
Owner City,St,Zip:	BROOKLYN, NY 11211-
Owner Phone:	(718) 782-4200
Owner Type:	Corporate/Commercial
Owner Status:	2
Owner Mark:	Second Owner
Mailing Name:	DITMAS OIL ASSOCIATES, INC.
Mailing Address:	364 MASPETH AVENUE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BROOKLYN, NY 11211-
Mailing Contact:	ROBERTO PORCELLI
Mailing Phone:	(718) 782-4200
Legal Agent Name:	FRIEDLAND, LEIFFER, ROBBINS, LLP
Legal Agent Address:	233 BROADWAY
Legal Agent City,St,Zip:	NEW YORK, NY 10274-
LIC Expires:	03/31/2002

Tank ID:	010
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Install Date:	07/96
Product:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	CATHODIC PROTECTION
Pipe Location:	Not reported
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	Concrete Dike
Leak Detection:	Groundwater Well
Overfill Protection:	High Level Alarm
Dispensing Mthd:	Suction
Test Date:	07/96
Date Closed:	12/00
Status of Data:	Minor Errors
Capacity (gal):	14500
Lat/Long:	40|43|05 / 73|55|40
Federal ID:	Not reported
Inspected Date:	10/26/1998
Inspector:	AS
Renew Date:	10/31/2001
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005789
Date Legal Agent Filed with Secretary of State:	Not reported

Tank ID:	10
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Install Date:	07/96
Product:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	Concrete Dike
Leak Detection:	Groundwater Well
Overfill Protection:	High Level Alarm
Dispensing Mthd:	Suction
Test Date:	07/96
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	14500
Lat/Long:	40|43|05 / 73|55|40
Federal ID:	Not reported
Inspected Date:	10/26/1998

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Inspector:	AS
Renew Date:	10/31/2001
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005789
Date Legal Agent Filed with Secretary of State:	Not reported

Tank ID:	101
Tank Location:	ABOVEGROUND
Install Date:	12/65
Product:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	Concrete Dike
Leak Detection:	35
Overfill Protection:	23
Dispensing Mthd:	Suction
Test Date:	11/00
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	97812
Lat/Long:	40|43|05 / 73|55|40
Federal ID:	Not reported
Inspected Date:	10/26/1998
Inspector:	AS
Renew Date:	10/31/2001
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005789
Date Legal Agent Filed with Secretary of State:	Not reported

Tank ID:	102
Tank Location:	ABOVEGROUND
Install Date:	12/65
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Tank Internal:	Epoxy Liner
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	Concrete Dike
Leak Detection:	35
Overfill Protection:	23
Dispensing Mthd:	Suction
Test Date:	11/00
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	97812
Lat/Long:	40|43|05 / 73|55|40
Federal ID:	Not reported
Inspected Date:	10/26/1998
Inspector:	AS
Renew Date:	10/31/2001
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005789
Date Legal Agent Filed with Secretary of State:	Not reported

Tank ID:	103
Tank Location:	ABOVEGROUND
Install Date:	12/65
Product:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	Concrete Dike
Leak Detection:	35
Overfill Protection:	23
Dispensing Mthd:	Suction
Test Date:	10/97
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	88379
Lat/Long:	40|43|05 / 73|55|40
Federal ID:	Not reported
Inspected Date:	10/26/1998
Inspector:	AS
Renew Date:	10/31/2001
Inspected State:	Not reported

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005789
Date Legal Agent Filed with Secretary of State:	Not reported

Tank ID:	104
Tank Location:	ABOVEGROUND
Install Date:	12/65
Product:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	Fiberglass Liner (FRP
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	Concrete Dike
Leak Detection:	Groundwater Well
Overfill Protection:	23
Dispensing Mthd:	Suction
Test Date:	11/97
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	177968
Lat/Long:	40|43|05 / 73|55|40
Federal ID:	Not reported
Inspected Date:	10/26/1998
Inspector:	AS
Renew Date:	10/31/2001
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005789
Date Legal Agent Filed with Secretary of State:	Not reported

Tank ID:	105
Tank Location:	ABOVEGROUND
Install Date:	12/65
Product:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	Epoxy Liner
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	Concrete Dike
Leak Detection:	35
Overfill Protection:	23
Dispensing Mthd:	Suction
Test Date:	11/00
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	194819
Lat/Long:	40|43|05 / 73|55|40
Federal ID:	Not reported
Inspected Date:	10/26/1998
Inspector:	AS
Renew Date:	10/31/2001
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005789
Date Legal Agent Filed with Secretary of State:	Not reported

Tank ID:	106
Tank Location:	ABOVEGROUND
Install Date:	12/66
Product:	NOS 1,2, OR 4 FUEL OIL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION/PAINTED [e.g. asphaltic]
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	Concrete Dike
Leak Detection:	93
Overfill Protection:	23
Dispensing Mthd:	Suction
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Complete
Capacity (gal):	98994
Lat/Long:	40|43|05 / 73|55|40
Federal ID:	Not reported
Inspected Date:	10/26/1998
Inspector:	AS
Renew Date:	10/31/2001
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005789
Date Legal Agent Filed with Secretary of State:	Not reported

Tank ID:	107
Tank Location:	ABOVEGROUND
Install Date:	12/69
Product:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Secondary Containment:	78
Leak Detection:	Groundwater Well
Overfill Protection:	23
Dispensing Mthd:	Suction
Test Date:	08/92
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	448609
Lat/Long:	40|43|05 / 73|55|40
Federal ID:	Not reported
Inspected Date:	10/26/1998
Inspector:	AS
Renew Date:	10/31/2001
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005789
Date Legal Agent Filed with Secretary of State:	Not reported

Tank ID:	111
Tank Location:	ABOVEGROUND
Install Date:	12/69
Product:	UNLEADED GASOLINE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Secondary Containment:	78
Leak Detection:	Groundwater Well
Overfill Protection:	23
Dispensing Mthd:	Suction
Test Date:	11/97
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	452503
Lat/Long:	40|43|05 / 73|55|40
Federal ID:	Not reported
Inspected Date:	10/26/1998
Inspector:	AS
Renew Date:	10/31/2001
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005789
Date Legal Agent Filed with Secretary of State:	Not reported

Click this hyperlink while viewing on your computer to access
3 additional NY_AST_MOS: record(s) in the EDR Site Report.

AIRS:

Name:	DITMAS TERMINAL - 364 MASPETH AVENUE
Address:	364 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
DECID:	2610100163
Process ID:	010EI
Latitude:	Not reported
Longitude:	Not reported
FIPS Code:	36047
Auth Type Code:	Not reported
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.00566579
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	U00103
Contamination:	PM25-PRI
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	TON
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.08804
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	U00103
Contamination:	SO2

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	TON
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.00736999
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	U00103
Contamination:	PM10-PRI
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	TON
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.0031
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	U00103
Contamination:	7440473
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.0001
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	U00103
Contamination:	7439965
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.0076
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	U00103
Contamination:	7439921
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	13.125
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	EI0001
Contamination:	VOC
EPA Control Code:	Not reported
Control Eff:	Not reported

DITMAS OIL ASSOCIATES, INC. (Continued) **S103275710**

Unit:	TON
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	7.1903652
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	1TANKS
Contamination:	VOC
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	TON
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	4.44000005
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	1TANKS
Contamination:	1330207
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	10.9300003
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	1TANKS
Contamination:	108883
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	3350
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	1RACKS
Contamination:	1634044
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB

Click this hyperlink while viewing on your computer to access
24 additional NY AIRS: record(s) in the EDR Site Report.

AL220 **OFFICE BUILDING** **NY LTANKS** **S127481837**
North **364 MASPETH AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.361 mi.
1908 ft. **Site 2 of 3 in cluster AL**

Relative: **Lower**

Actual: **12 ft.**

LTANKS:

Name:	OFFICE BUILDING
Address:	364 MASPETH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	2100155 / Not Reported
Facility ID:	2100155
Site ID:	617823
Spill Date:	2021-04-06
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HSSEKHON
Referred To:	Not reported
Reported to Dept:	2021-04-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	2021-04-06
Spill Record Last Update:	2021-07-12
Spiller Name:	Not reported
Spiller Company:	CASATERIA OIL CORP
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	WILLIAM KLEIN
Spiller Phone:	(718) 762-5200
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	565539
DEC Memo:	"4/7/21-lin- PBS# 2-610575 2,000 #2 fuel oil UST. Cathodic test failure. Contractor will replace anode to make the repair. No spill. They tested the tank system about a month ago and it passed. As part of the regulation, they will conduct another tightness test after the repair is made. The contractor will forward the tightness test results to the case manager when its available. Contractor Info: William Kelin 718-762-5200 (office) 917-807-1143 (cell) wrklein@franklincompany.com Property owner contact info: malu properties inc 275 Madison ave, 37th floor Ny, NY 10016 elmubarak dabo edabo@largavista.com agood@largavista.com 6/18 - Sekho n email send to RP & contractor to send updates. 6/25/21 - Sekhon email send to RP & contractor to send updates. Got email from Rp that they are evaluating proposals from contractor to remove tank. 7/12/21 - Sekhon Richard Levato Edabo@largavista.com Richard Levato Advanced Site Restoration 62 William Street New York NY 10005"
Remarks:	"Test failure no spill"

All Materials:

Site ID:	617823

OFFICE BUILDING (Continued) **S127481837**

Operable Unit ID:	1364985
Operable Unit:	01
Material ID:	2377451
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AL221 **DITMAS OIL ASSOCIATES, INC.** **NY LTANKS** **S103827207**
North **364 MASPETH AVENUE** **NY CBS** **N/A**
1/4-1/2 **BROOKLYN, NY 11211** **NY MOSF**
0.361 mi. **NY Spills**
1908 ft. **Site 3 of 3 in cluster AL** **NY SPDES**

Relative: **Lower**

Actual: **12 ft.**

LTANKS:

Name:	IN PARKING LOT
Address:	364 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0514281 / 2006-04-24
Facility ID:	0514281
Site ID:	360969
Spill Date:	2006-03-14
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2006-03-14
CID:	444
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-14
Spill Record Last Update:	2006-04-24
Spiller Name:	JIM CAREY
Spiller Company:	IN PARKING LOT
Spiller Address:	364 MASPETCH AVE
Spiller County:	001
Spiller Contact:	JIM CAREY
Spiller Phone:	(646) 772-5889
Spiller Extention:	CELL
DEC Region:	2
DER Facility ID:	102823
DEC Memo:	"03/14/06-Hiralkumar Patel. Spoke with Jim at Metro Fuel. property has 2000 gal AST. when driver read gauge he found that he could deliver more than 1000 gal. but after delivering 899 gal, tank overfilled and spilled on concrete floor. driver is doing initial

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

cleanup. cleanup crew is already left for site. Jim is also goint to site and will call back once he reach on site regarding concrete condition and cleaning process. the measuring gauge is not working properly. Received call from Jim and as per him, oil spilled on solid concrete without affecting soil or drain/sewer. all cleaned up. as i couldn't find PBS registration, i got owner's information from Jim. Organization Name: US Tow INc. Contact Person: Joe Lopez / Randy Number: (718) 246-5566 FAX: (718) 802-1988 called at US Tow and Ms. Randy told me that they rent this property at 364 Maspeth Ave. she doesn't have any idea about PBS. Left message for Mr. Mike who is owner. Received call from Ms. Randy and as they don't have their tank registered, she was asking for registration forms. Letter sent out requesting tank registration and replacement/repairment of faulty guage. faxed to US Tow Inc. 04/21/06-Hiralkumar Patel. Called at US Tow, but Ms. Randy will be back on Monday Apr. 24. 04/24/06-Hiralkumar Patel. Spoke with Ms. Randy at US Tow and she will mail the registration form soon. as the spill was cleaned on day of incident and no soil/groundwater/sewer/drain affected, case is closed."

Remarks: "STORAGE TANK OVERFILL AND IN PROCESS OF CLEANING UP"

All Materials:

Site ID:	360969
Operable Unit ID:	1118070
Operable Unit:	01
Material ID:	2108583
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CBS:

Name:	DITMAS OIL ASSOCIATES, INC.
Address:	364 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
CBS Number:	2-000328
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	590476.38524
UTMY:	4508036.27253

MOSF:

Name:	DITMAS OIL ASSOCIATES, INC.
Address:	364 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Facility ID:	2-1340
Program Type:	MOSF
Tank Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

UTMX: 590561.18213
UTMY: 4508000.25067

SPILLS:

Name:	DITMAS OIL COMPANY
Address:	364 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9011585 / 1991-02-05
Facility ID:	9011585
Facility Type:	ER
DER Facility ID:	102823
Site ID:	118306
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	A1
SWIS:	2401
Spill Date:	1991-02-04
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1991-02-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Fire Department
Cleanup Ceased:	1991-02-05
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-02-11
Spill Record Last Update:	2003-09-19
Spiller Name:	ROBERTO PORTCELLI
Spiller Company:	DITMAS OIL COMAPNY'
Spiller Address:	364 MASPETH AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"CAROLINA TRUCKING 414 MASPETH COMPLAINED OF GASOLINE ODORS,NYCFD HAZMAT & NYCDEP HAZMAT RESPONDED,OBSERVED AIR RELEASE FROM VENTS OF TANKS #108,109 &110,TOOK READINGS OF 29%LEL 10FT FROM VENTS"

All Materials:

Site ID:	118306
Operable Unit ID:	948604
Operable Unit:	01
Material ID:	428121
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

Name:	DITMAS OIL COMPANY
Address:	364 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9208027 / 1992-10-12
Facility ID:	9208027
Facility Type:	ER
DER Facility ID:	102823
Site ID:	118307
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B1
SWIS:	2401
Spill Date:	1992-10-12
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1992-10-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Citizen
Cleanup Ceased:	1992-10-12
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-10-15
Spill Record Last Update:	2003-09-19
Spiller Name:	ROBERTO PORCELLI
Spiller Company:	DITMAS OIL COMPANY
Spiller Address:	364 MASPETH AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"Air complaint."

All Materials:

Site ID:	118307
Operable Unit ID:	974831
Operable Unit:	01
Material ID:	408634
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	DITMAS OIL COMPANY
Address:	364 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9006603 / 2017-02-15
Facility ID:	9006603
Facility Type:	ER
DER Facility ID:	102823

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

Site ID:	112706
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	A3
SWIS:	2401
Spill Date:	1990-09-15
Investigator:	VXBREVDO
Referred To:	Not reported
Reported to Dept:	1990-09-15
CID:	Not reported
Water Affected:	ENGLISH KILLS
Spill Source:	Major Facility (MOSF) > 400,000 gal
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-10-30
Spill Record Last Update:	2017-02-15
Spiller Name:	OSCAR PORCELLI
Spiller Company:	DITMAS OIL COMPANY
Spiller Address:	364 MASPETH AVE
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"02-21-12 - LZ The Fourth Quarter 2011 Status Report prepared by CEUS Engineering, P.C. is in eDocs. 11/30/11 - LZ The Third Quarter 2011 Status Report prepared by CEUS Engineering, P.C. is in eDocs. 9/23/11 - Austin - Spoke with Jim Quinn of DEC/DER in Albany. He indicated that the former BCF waste oil facility located at 360 Maspeth Ave. (next store to this Ditmas/Gaseteria site) had been cleaned suffciently of haz. waste contamination that it was being d-listed as a Superfund site. The remaining issue on the site was petroleum contamination (floating product). Gaseteria/Ditmas/Newtown Development LLC have taken title to the BCF property adjoining theirs, and have been exonerated of liability for the SSF cleanup, but were still liable for the oil spill cleanup as the new owners. The BCF project (originally under spill 3 9406807, assigned to Hale in Albany) will be coming back to the Region, and will be assigned along with this spill (9006603) to a Remediation Section (either Brevdo or Hussein) for remediation of both adjoining sites. Quinn will send down information on the discussions with Gaseteria, et. al. regarding their responsibilities in this matter. - end 09/06/11 - LZ Reviewed the Second Quarter 2011 Status Report (eDocs)describing the activities at the site. bioremediation, now temporarily suspended, is scheduled to be retested in the spring 2012. MW-21 that has been destroyed and MW-9R, located nearby, takes over function of MW-21. 07/20/11 - LZ The April 28, 2011 First Quarter Status report (eDocs) quartely report shows that free product appeared in 6 wells; the highest thickness of it was 0.21 foot. The next report is due August 15, 2011. 03/03/11 - LZ The February 14, 2011 RAWP (eDocs) has been approved by DEC letter dated 03/03/11 (eDocs), including quarterly well monitoring and quarterly submission of reports. 11/02/10 - LZ Has reviewed and approves a CEUS Engineering request for a 90-day extension to collect additional data, design a petroleum recovery system, and submit a revised remedial action work plan. The work plan

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

to be submitted by January 31, 2011. In eDocs is the October 29, 2010 Third Quarter 2010 report. 10/12/10 - LZ The July 30, 2010, quarterly report (eDocs) by CEUS Engineering, P.C., proposes installation of recovery wells south of MW-2 where free product still exists. After five wells are installed, vacuum truck extraction will be performed and its results analyze to determine whether to continue weekly vacuuming or to install a recovery system. 04/22/10 - LZ Staff reviewed the March 31, 2010 report(eDocs)prepared by CEUS Engineering, P.C. To improve the effectiveness of bioremediation, CEUS Engineering proposes the complete extraction of free product. Vacuum-enhanced product recovery will be conducted using temporary extraction points in the vicinity of MW-2 until free product is removed, while the bioremediation process is suspended. Bioremediation will resume in the fall of 2010, utilizing monthly bio-applications, and the process will be monitored by sampling performed quarterly. Staff approved the proposed modifications to product recovery and bioremediation operations as well as the proposed schedule of the future activities requiring that vacuum-enhanced product recovery must be conducted at least weekly. 02/12/10 - LZ John Rhodes (phone 646-465-2494), since his comany CEUS took over the project, requested an extension to submit the report by March 31, 2010. Request granted. 10/27/09 - LZ Reviewed the AST quarterly report (eDocs) that covers April - June 2009 activities. Monthly gauging were conducted in 17 onsite and offsite wells. Well MW-2 exhibited free product during every gauging (0.006 -0.07 foot). 09/16/09 - LZ E-mailed Chris Tomasello of AST, LLC requesting a 2nd quarter 2009 report be submitted by September 22th. In addition to previous reports, this report should include the amount of recovered product and all, listed in TAGM 4046, VOCs, SVOCs, and MTBE being analyzed (we spoke about this in April). 05/04/09 - LZ The May 1, 2009, Advanced Site Restoration Quarterly Status Report (eDocs) covers remedial activities from January to April 2009. The monitoring well network was gauged on January 6, February 6, and March 4, 2009, and sampled on April 13, 2009. Gauging was performed at MW-2 through MW-6, MW-8, MW-10, MW-16, MW-17, MW-19, and MW-21.The groundwater samples were analyzed for VOCs, including BTEX and MTBE. Total BTEX concentrations ranged from non-detected to 350 ug/l (MW-10). MTBE concentrations ranged from non-detected to 11 ug/l (MW-21). Concentration of BTEX in excess of applicable NYSDEC GWQS were detected in 3 groundwater samples collected during this groundwater sampling event. The next sampling event is scheduled for July, 2009. LNAPL was last detected on March 6, 2009 in MW-2 and was bailed out from this well. 05/04/09 - LZ The October-December 2008 quarterly report (eDocs) prepared by Advanced Site Restoration, indicates that 500 gallons of Bio Rem LLC H-10 were pumped monthly into the sit s bio-irrigation system. Since October 2006, total 53.5 gallons of LNAPL have been removed from the ground. Free product still exists in MW-2 and MW-17. Twelve wells (MW-2 through MW-6, MW-8, MW-10, MW-16, MW-17, and MW-19 through MW-21) were gauged on 10/01/08, 11/03/08, and 12/17/08. On October 1, 2008, monitoring wells MW-3 through MW-6, MW-8, MW-10, MW-16, and MW-19 were sampled: total BTEX concentration range was found from non-detected to 68 ug/l (MW-19); MTBE concentration range was found from non-detected to 9 ug/l(MW-5). 06/16/08 - LZ A report, dated April 2008, prepared by the ASR, provides data concerning remediation efforts and the level of current contamination at the site. From October 2006 to February 2008, 53.5 gallons of LNAPL has been extracted from groundwater. The ASR has

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

applied 30,000 gallons of bio solution-BioREm H-10. Total BTEX has decreased in all monitoring wells, except MW-2. Free product is still in MW-2 and MW-17. 08/08/06 -Zielinski A site visit and a meeting with Mr. Tomasello of ASR. Sent a letter to Mr. Tomasello((see eDocs) requesting installation of three additional wells, reinstallation of MW1, MW11, and W9. 07/18/06 - Zielinski A review of the July 2006 monthly montoring report received from Advanced Site Restoration, LLC,(ASR) indicates that at wells MW-2 and MW-6 concentraction of benzene and total BTEX concentration is relatively high. Results from other seven wells indicate low contamination of groundwater. In August, staff will visit the site. In August, ASR will submit a quarterly report regarding the status of remedation process at the site. 08/18/04 - Zielinski In its letter of August 18, 2004, the department requested that the delineation of petrolum contamination had to be performed by Ditmas Oil Association. In addition, a remedial action plan must be submitted by the facility. These documents have not been received by the department, a review of files on July 5, 2006, shows. 4/21/04 - This project is re-assigned to Zhao from Sigona. Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHAO This site spill cleanup has been consolidated under Spill No. 9006603. 09/15/90: SPILLER WILL DISPOSE OF SOIL PROPERLY & ASSURE WARNING SYSTEM IS IN PROPER WORKING ORDER, SPILL TO BE REFERRED TO MOSF COORDINATOR. DEC Sigona performed follow-up investigation and discovered groundwater contamination. Site is under a consent order to performed remediation of groundwater and tidal wetlands. 06/29/12 - THIS SPILL CASE HAS BEEN TRANSFERRED TO SECTION B ON 06/29/12 AS DISCUSSED WITH RANDY AUSTIN 07/31/2012 - V. Brevdo Received Second Quarter 2012 Status Report, dated July 20, 2012. Reviewed Report. The Ditmas Oil Terminal (the Site) was an independent petroleum products storage and distribution bulk terminal. The Site was located in an industrial area of Greenpoint, Brooklyn, adjacent to the English Kill, a part of Newtown Creek. The Site received various petroleum products from barges in the adjacent waterway and the Buckeye pipeline that ran through the Site. Fuel was stored in above and below ground storage tanks and then pumped into trucks through an underground piping system. Petroleum products stored included gasoline, kerosene, diesel, No. 2 Fuel Oil and Bunker C oil. A major spill in excess of 40,000 gallons of gasoline occurred on January 15, 1975 during the Gulf operation according to DEC and Coast Guard records. Tank Number 7, a 475,000 gallon storage tank, was overfilled causing gasoline to fill the surrounding (permeable) retaining dyke to a depth of eight feet. Gasoline was observed emerging from the sea wall at the English Kill. An estimated 1,000 gallons reached the English Kill where the fire department prevented the deployment of berms due to a fire hazard. Additional dissolved contaminants reached the English Kill as the result of water being added to the retaining dyke in an attempt to reduce the gasoline s flow into the ground. The Site was decommissioned between February 2004 and June 2005. Approximately twenty petroleum storage tanks were removed from service. (A 2000 gallon fuel oil Underground Storage Tank (UST) remained for heating the onsite office building.) Underground contamination was delineated. All tanks and underground piping were drained of their content, demolished and removed from the Site. The Site is now a motor vehicles impound lot operated by the NYC Marshal. Remediation of the Site has progressed since 2004 under the NYSDEC approved Facility Closure and Oil Spill Remedial Action Plan under the Order on Consent. In 2011 and to date in 2012,

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

approximately 25 gallons of relatively well separated product was recovered using skimmers and peristaltic pumps, and 62 gallons of emulsified product and oily water by bailing. Additional amounts were recovered during vacuum truck visits. Planned activities for the fourth quarter of 2012 include the following: Commencement of the bioremediation and induced oil recovery pilot test; Placement of the scavenger with groundwater pump in recovery well R-9; Continued Gauging and Quarterly testing in accordance with the approved Monitoring Plan; Commencement of Performance Monitoring of the bioremediation and oil recovery pilot test. V. Brevdo 11/09/2012 - Brevdo CEUS Engineering, P.C. (CEUS) submitted status Report for the former Ditmas Terminal. The following provides a Status Report in accordance with Consent Order R2?0272?97?12; the NYSDEC approved Facility Closure and Oil Spill Remedial Action Plan 1 October 2004 (RAP); the Remedial Action Work Plan Addendum and Fourth Quarter 2010 Status Report 8 February 2011 (RAWP Addendum); and the NYSDEC approval letters 18 August 2004, 5 November 2004, 22 April 2010, 5 January 2011 and 3 March 2011 for the former Ditmas Oil Terminal at 364 Maspeth Avenue, Brooklyn, NY (the Site). This Status Report has been prepared by CEUS Engineering, P.C. (CEUS) with field and data management assistance from Advanced Site Restoration, LLC (ASR). Product removal will continue using the skimmer with groundwater depression, a standalone skimmer, a peristaltic pump and bailing.V. Brevdo 07/29/2013 - V. Brevdo E-mail from consultant wiht attached 2nd Quarter 2013 monitoring report. Vadim, Attached is the 2nd Quarter Status Report for the former Ditmas Oil Terminal. I will also follow-up with a hard copy and compact disk. Many thanks, John A. Rhodes, P.E., F.NSPE CEUS Engineering, P.C. NJ: 5 Bedford Place, Morristown, 07960 NY: 62 William Street, 3rd Floor, New York, 10005 646 465 2494 10/31/2013 - V. Brevdo E-mails from CEUS Engineering: Vadim, Attached is the 3rd Quarter Status Report for the former Ditmas Terminal, minus the laboratory analytical reports that I will send you in a separate email. I will also send you a hard copy and CD by mail. Please confirm receipt. Thanks, John A. Rhodes, P.E. CEUS Engineering, P.C. NJ: 5 Bedford Place, Morristown, NJ 07960 NY: 62 William Street, New York, NY 10005 646 465 2494 JRhodes@CEUSEngineeringPC.com JARhodes1@Verizon.net Vadim, Attached are the laboratory analytical reports to accompany the 3rd Quarter Status Report sent in an earlier email. Thanks, John A. Rhodes, P.E. E-Mail from Brevdo of DEC to John Rhodes of CEUS: Dear Mr. Rhodes: This is to acknowledge receipt of two e-mails with attached status report and lab analytical reports. I will review in the upcoming few days and will get back to you if need be. Contact me if you have questions. Thank you. Vadim Brevdo 11/06/2013 - V. Brevdo Summary of the project status as of 11/06/13. Former Ditmas Oil Terminal, 364 Maspeth Avenue, Brooklyn (Spill No. 9006603) The Ditmas Oil Terminal (the Site) was an independent petroleum products storage and distribution bulk terminal. Remediation of the Site has progressed since 2004. The Site was decommissioned between February 2004 and June 2005. Approximately twenty petroleum storage tanks were removed from service. Underground contamination was delineated. All tanks and underground piping were drained of their content, demolished and removed from the Site. The Site is now a motor vehicles impound lot operated by the NYC Marshal. The Department approved Facility Closure / Oil Spill Remedial Action Plan and Addendum in October 2004 and March 2011 respectively. Initially, approximately 15,000 gallons of product and water were removed from test pits. A bioremediation

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

system was designed and installed in 2005. The system consisted of a series of trenches to allow seepage of a solution to enhance the biological degradation of petroleum contaminants. The March 2011 RAWP addendum required upgraded recovery of product using mechanical oil skimmer. The upgraded system began operation in September 2012. On November 5, 2013, CEUS Engineering, P.C. (CEUS) submitted remediation Status Report for the 3rd quarter of 2013. Planned activities for the 4th quarter of 2013 associated with further implementation of a RAWP Addendum remain similar to those undertaken in 3rd quarter of 2013, and include the following: Continuation of the bioremediation system operation, including the water depression pumping, oil skimming, treatment plant operation; continued evaluation of the effectiveness of the remedial system and its improvements, cleaning of discharge trenches; gauging and quarterly testing; periodic removal of oily water with a vacuum truck. Recoverable product will continue to be removed by peristaltic pump, skimmer or baling, followed by absorbent socks. CEUS advised the Department of their opinion that the Site is affected by migration of contaminants from the upgradient Key Span / National Grid Greenpoint facility (a.k.a. former Equity Manufactured Gas Plant site) which is undergoing remedial investigation via State Superfund program. The Department s oversight of said State Superfund project is conducted by DER s Remedial Bureau C in Central Office, Albany. Region 2 Project Manager for the Former Ditmas Oil Terminal petroleum spill remediation project and Central Office project manager for the Key Span / National Grid Greenpoint State Superfund project discussed future coordination of investigative and remedial work on these adjacent properties. VB 02/10/2014 V. Brevdo - CEUS submitted 4th Quarter 2013 Status Report, dated February 3, 2014. Estimated time frame for completion of the remediation and submission of the Final Engineering Report is early 2015, which is in the Section 5 Estimated Schedule , page 11 of the report. VB 05/02/2014 - V. Brevdo CEUS submitted 1st Quarter 2014 Status Report, dated April 28, 2014. VB 08/06/2014 - V. Brevdo CEUS submitted 2nd quarter 2014 Status Report, dated August 6, 2014. VB. 11/07/2014 - V. Brevdo CEUS/Advanced Site Restoration submitted 3rd quarter 2014 Status Report, dated November 7, 2014. Request Department’s approval of several cleanup technology changes. Department is reviewing the report. VB. 11/10/2014 - V. Brevdo Current Project Status Synopsis: Former Ditmas Oil Terminal, 364 Maspeth Avenue, Brooklyn (Spill No. 9006603) The Ditmas Oil Terminal (the Site) was an independent petroleum products storage and distribution bulk terminal. The Site was decommissioned between February 2004 and June 2005. Remediation of the Site has progressed since 2004 and is implemented under the Order on Consent. Approximately twenty petroleum storage tanks were removed from service. Underground contamination was delineated. All tanks and underground piping were drained of their content, demolished and removed from the Site. The Site is now a motor vehicles impound lot operated by the NYC Marshal. The Department approved Facility Closure / Oil Spill Remedial Action Plan and Addendum in October 2004 and March 2011 respectively. Initially, approximately 15,715 gallons of product and water were removed from test pits. A bioremediation system was designed and installed in 2005. The system consists of a series of trenches to allow seepage of a solution to enhance the biological degradation of petroleum contaminants. The March 2011 RAWP addendum required upgraded recovery of product using mechanical oil skimmer. The upgraded system began operation in September 2012. On November 7, 2014, CEUS Engineering,

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

P.C. / Advanced Site Restoration (CEUS / ASR) submitted remediation status report for the 3rd quarter of 2014. As of the end of the third quarter, 2014, the active oil recovery portion of the bioremediation system (skimmer and water depression pump) has eliminated the presence of product in MW-2 area. However, product continues to be detected in R-10 and MW-22 areas. Therefore, CEUS/ASR petitioned the Department for cessation of the active (by pumping) oil recovery operation in the MW-2 area and moving the pumping equipment to other areas. Absorbent socks will continue to be applied at MW-2 and maintained to capture product should it re-appear. CEUS/ASR also proposed several other modifications to the RAWP: elimination of three destroyed wells from monitoring program; pumping water from MW-22 and evaluating the reason MW-22 is slower than the other wells to improve; and adding biodegradable dye or sodium chloride as means of evaluating concentration changes and flows during pumping. CEUS / ASR plans to accomplish remedial objectives and petition the Department for closure of spill case tentatively in early to mid 2015. RP (Malu Properties) continues cooperation with USEPA Remedial Investigation for the Newtown Creek CERCLA Site. Malu Properties has allowed the USEPA to set up a water sampling station on the property s recently repaired bulkhead. Malu Properties also assisted the USEPA in establishing automated sampling station for storm water in the region. The next groundwater sampling is scheduled for December 2014. On November 10, 2014, the Department issued letter of approval of the 3rd quarter 2014 remediation status report and recommendations contained in the report. VB 05-01-2015 - V. Brevdo Former Ditmas Oil Terminal, 364 Maspeth Avenue, Brooklyn (Spill No. 9006603) On April 30, 2015, CEUS Engineering, P.C. / Advanced Site Restoration (CEUS / ASR) submitted remediation status report for the 1st quarter of 2015. As reported in earlier status reports, the active oil recovery portion of the bioremediation system (skimmer and water depression pump) has eliminated the presence of product in MW-2 area. Absorbent socks continue to be applied and maintained to capture product when it re-appear. To date, no product has reappeared in the MW-2 area. However, product continues to be detected in R-10 area. After conducting tidal and product recovery tests, CEUS/ASR decided to implement automatic product recovery in R-10 area to increase recovery rate. Implementation of automated product recovery in R-10 was included in the approved RAWP should absorbent socks be inefficient in removing the product. CEUS/ASR intends to install a belt skimmer in R-10. The next groundwater sampling is scheduled for May 2015. VB 08-25-2015 - V. Brevdo On August 25, 2015, CEUS Engineering, P.C. / Advanced Site Restoration (CEUS / ASR) submitted remediation status report for the second quarter of 2015. As reported in earlier status reports, the active oil recovery portion of the bioremediation system (skimmer and water depression pump) has eliminated the presence of product in MW-2 area. Absorbent socks continue to be applied and maintained to capture product when it re-appear. To date, no product has reappeared in the MW-2 area. However, product continues to be detected in R-10 area. After conducting tidal and product recovery tests, CEUS/ASR decided to implement automatic product recovery in R-10 area to increase recovery rate. Implementation of automated product recovery in R-10 was included in the approved RAWP should absorbent socks be inefficient in removing the product. CEUS/ASR intended to install a belt skimmer in R-10. However, over the second quarter, insufficient product has collected in R-10 area to meet the minimal requirements

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

for removal by a belt skimmer. Therefore, CEUS delayed implementation of product removal by a belt skimmer, and continue using absorbent sock instead. Groundwater was tested on June 8, 2015. The next groundwater sampling is scheduled for September 2015. VB 11-02-2015 - V. Brevdo Former Ditmas Oil Terminal, 364 Maspeth Avenue, Brooklyn (Spill No. 9006603) The Ditmas Oil Terminal (the Site) was an independent petroleum products storage and distribution bulk terminal. The Site was decommissioned between February 2004 and June 2005. Remediation of the Site has progressed since 2004 and is implemented under the Order on Consent. Approximately twenty petroleum storage tanks were removed from service. Underground contamination was delineated. All tanks and underground piping were drained of their content, demolished and removed from the Site. The Site is now a motor vehicles impound lot operated by the NYC Marshal. The Department approved Facility Closure / Oil Spill Remedial Action Plan and Addendum in October 2004 and March 2011 respectively. Initially, approximately 15,715 gallons of product and water were removed from test pits. A bioremediation system was designed and installed in 2005. The system consists of a series of trenches to allow seepage of a solution to enhance the biological degradation of petroleum contaminants. The March 2011 RAWP addendum required upgraded recovery of product using mechanical oil skimmer. The upgraded system began operation in September 2012. On November 2, 2015, CEUS Engineering, P.C. / Advanced Site Restoration (CEUS / ASR) submitted remediation status report for the third quarter of 2015. The Department is reviewed the report which has good news. CEUS / ASR intensified effort at product removal from recovery well R-10, coordinating recovery with the tides, and have not detected product since early August 2015. CEUS / ASR feel that they may be able to declare the Site product free in the upcoming few months. The focused recovery efforts on well MW-22 have also been successful. As extended pumping indicated improving conditions, CEUS / ASR took an unscheduled sample on September 29, 2015 in which benzene was detected at low concentrations of 29 microgram per liter (ppb). CEUS / ASR intend to continue focused efforts and sampling and testing to check for rebound. However, if aforementioned improvements continue, then all contaminants in all wells are expected to be below standards / cleanup criteria or trending downward criteria. Therefore, CEUS anticipate being in a position for closure in the spring of 2016. VB 02-02-2016 - V. Brevdo Former Ditmas Oil Terminal, 364 Maspeth Avenue, Brooklyn (NYSDEC Spill No. 9006603) The Ditmas Oil Terminal (the Site) was an independent petroleum products storage and distribution bulk terminal. The Site was decommissioned between February 2004 and June 2005. Remediation of the Site has progressed since 2004 and is implemented under the Order on Consent. Approximately twenty petroleum storage tanks were removed from service. Underground contamination was delineated. All tanks and underground piping were drained of their content, demolished and removed from the Site. The Site is now a motor vehicles impound lot operated by the NYC Marshal. The Department approved Facility Closure / Oil Spill Remedial Action Plan and Addendum in October 2004 and March 2011 respectively. Initially, approximately 15,715 gallons of product and water were removed from test pits. A bioremediation system was designed and installed in 2005. The system consists of a series of trenches to allow seepage of a solution and oxygenated water to enhance the biological degradation of petroleum contaminants. The March 2011 RAWP addendum required upgraded recovery

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

of product using mechanical oil skimmer. The upgraded system began operation in September 2012. On February 1, 2016, CEUS Engineering, P.C. / Advanced Site Restoration (CEUS / ASR) submitted remediation status report for the fourth quarter of 2015. No free product has been encountered in any well other than R-10 since June 2014. CEUS / ASR therefore proposed the cessation of product gauging and recovery in all wells other than R-10. CEUS / ASR will continue to monitor for product in R-10 well and recover product using absorbent socks. CEUS/ ASR concluded that the bioremediation is no longer necessary except to enable the surging of MW-22, an inland well, and the discharge of contaminated water pumped from MW-22. CEUS /ASR proposed to maintain the bioremediation system while they continue to address the conditions at MW-22, and operate the system in conjunction with activities related to MW-22. Planned activities for the next quarter as related to the RAWP Addendum include the following: The bioremediation system will be maintained and operated on an as-needed basis to accommodate continued sampling and/or remedial activities at MW-22; If benzene concentrations remain elevated at MW-22 during upcoming March 2016 sampling event, CEUS /ASR will recommence remedial activities, including pumping and pulsing of the well; Sampling and testing will continue for wells MW-8 and MW-23 for at least two more quarters to confirm a downward trend in benzene concentrations; Frequent monitoring for product in well R-10 will continue and product, if encountered, will be removed using absorbent socks. A scope of reduction in the sampling/monitoring and remedial activities in the next quarter is presented in detail on Page 10 of the January 31, 2016 Status Report. On February 2, 2016, the Department approved Fourth Quarter 2015 Status Report including the course of action and reduction of the scope of sampling/monitoring and remediation activities proposed by CEUS /ASR. CEUS /ASR anticipate to accomplish closure of this spill case in late 2016 or early 2017. VB May 2, 2016 - V. Brevdo Received and e-mail from John A. Rhodes of CEUS Engineering, P.C. and first quarter of 2016 monitoring report: Vadim, Attached is the 1st Quarter 2016 Status Report for the former Ditmas Terminal. There is not much to report as we were unable to do much over the winter. However, we have put the treatment system back on line and have begun working on MW-22, so we should have more news in the next status report. Benzene in MW-22 and product in R-10 are about the same. Thanks, John John A. Rhodes, P.E., F.NSPE CEUS Engineering, P.C. NJ: 5 Bedford Place, Morristown, NJ 07960 NY: 62 William Street, New York, NY 10005 646 465 2494 JRhodes@CEUSEngineering.com JARhodes1@Verizon.net 08/03/2016 - V. Brevdo On August 1, 2016, CEUS Engineering, P.C. / Advanced Site Restoration (CEUS / ASR) submitted remediation status report for the second quarter of 2016. CEUS / ASR continued gauging and product recovery activities for well R-10. Product recovery was done using the absorbent socks. Planned activities for the next quarter as related to the RAWP Addendum include the following: The bioremediation system will be maintained and operated on an as-needed basis to accommodate continued sampling and/or remedial activities at MW-22; CEUS / ASR will continue the recent successful activities in the MW-22 area to improve rate of contaminant degradation, including sustained and monitored pumping, and surging of the well; CEUS / ASR will continue frequent monitoring for product in R-10, and remove it using absorbent socks should it be encountered. CEUS /ASR anticipate to accomplish closure of this spill case in late 2016 or early 2017. VB 10/28/2016 - V. Brevdo On October 31, 2016, CEUS Engineering, P.C.

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

/ Advanced Site Restoration (CEUS / ASR) submitted remediation status report for the third quarter of 2016. CEUS / ASR concluded that the recalcitrant oil observed in well R-10 was the result of seepage from the blocked sewer. Upon removal of the blocked portion of the sewer pipe, the oily sediment and soil in the vicinity of the blocked portion of the pipe, no oil has been detected in R?10. No oil has been detected anywhere on the former Ditmas property and the oil recovery program has been completed. The March, June and September 2016 sampling and testing show benzene concentrations in remaining wells to be below or near 100 ?g/l with the exception of MW?22. Focused activities on MW?22 will continue. CEUS /ASR anticipate to accomplish closure of this spill case in 2017. VB 02/01/2017 - V. Brevdo On February 1, 2017, CEUS Engineering / ASR submitted 4Q 2016 Site Status Report and Spill Case Closure Petition. Upon review of both report and petition, DEC project manager requested ASR to revise report and petition to make a better and more compelling case to support merits of spill case closure petition. VB 02/15/2017 - V. Brevdo Former Ditmas Oil Terminal, 364 Maspeth Avenue, Brooklyn (NYSDEC Spill No. 9006603). Project Summary and Spill Case Closure Decision. The Ditmas Oil Terminal (the Site) was an independent petroleum products storage and distribution bulk terminal. The Site was decommissioned between February 2004 and June 2005. Remediation of the Site has progressed since 2004 and is implemented under the Order on Consent. Approximately twenty petroleum storage tanks were removed from service. Underground contamination was delineated. All tanks and underground piping were drained of their content, demolished and removed from the Site. The Site is now a short term parking area for film production trailers, and other commercial fleet vehicles. Previously, it was a motor vehicles impound lot operated by the NYC Marshal. The Department approved Facility Closure / Oil Spill Remedial Action Plan and Addendum in October 2004 and March 2011 respectively. Initially, approximately 15,715 gallons of product and water were removed from test pits. A bioremediation system was designed and installed in 2005. The system consists of a series of trenches to allow seepage of a solution to enhance the biological degradation of petroleum contaminants. The March 2011 RAWP addendum required upgraded recovery of product using mechanical oil skimmer in Recovery Well R-9 near Monitoring Well MW-2. The upgraded system began operation in September 2012 and completed oil recovery by June 2014. CEUS / ASR therefore proposed the cessation of product gauging and recovery in all wells other than R-10, where oil recovery continued. Additionally, CEUS/ ASR concluded that the bioremediation is no longer necessary except to enable the surging of MW-22 and the discharge of contaminated water pumped from MW-22. CEUS /ASR maintained the bioremediation system while they continue to address the conditions at MW-22, and operate the system in conjunction with activities related to MW-22. On October 31, 2016, CEUS Engineering, P.C. / Advanced Site Restoration (CEUS / ASR) submitted remediation status report for the third quarter of 2016. CEUS / ASR concluded that the recalcitrant oil observed in well R-10 was the result of seepage from the blocked sewer. Upon removal of the blocked portion of the sewer pipe, the oily sediment and soil in the vicinity of the blocked portion of the pipe, no oil has been detected in R?10. As of February, 2017, no oil has been detected anywhere on the former Ditmas property and the oil recovery program has been completed. The March, June and September 2016 sampling and testing show benzene concentrations in remaining wells to be below or near 100 ?g/l with

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

the exception of MW?22. Focused activities on MW?22 continued through December 2016. In the 4th Quarter 2014 Status Report (dated January 31, 2015), a proposal was submitted to undertake tests on MW-22 and a pilot study involving surging to try to increase the rate of contaminant reduction. This proposal was approved by the NYSDEC, and the tests conducted in the spring of 2015 and pilot study begun in September of 2015. Initially, a dye study demonstrated that MW-22 was not being adequately affected by the bioremediation system - oxygenated water was not reaching the area of the well. Aquifer testing evaluated the hydraulic conductivity to be 0.85 gallons per day per foot squared, a substantially lower value than that measured in surrounding areas. With the low hydraulic conductivity and lack of flow to the south toward the bio-remediation trenches and the English Kills, the only sensitive receptor for contaminated groundwater, CEUS/ASR concluded that remaining contaminants were isolated and contained, and not affecting the English Kills. Further, CEUS/ASR concluded that continued surging of the well would have limited effectiveness as the spreading of oxygenated water via the bio-remediation trenches or the recovery of contaminated water would be limited by the low hydraulic conductivity. In turn, CEUS/ASR submitted that the dissolved groundwater concentrations at MW-22 posed no further threat to human health and the environment and have been addressed to the extent feasible. CEUS /ASR proposed closure of this spill case in February, 2017, based on the following criteria: " The Primary Spill Source has been addressed, " Free product has been removed, " Grossly contaminated soil has been addressed to the extent feasible, " The remaining areas of contaminated soil have been addressed to the extent feasible as per CP-51 Soil Cleanup Guidance, " Residual groundwater contaminants either meet standards/cleanup guidance values or are within the range acceptable to the Department, " The nature and extent of groundwater contamination has been delineated, " Dissolved groundwater concentrations have been addressed to the extent feasible, " No migration of contaminants off site is occurring and no threats to sensitive receptors exist, " Remaining contamination is contained, " No threat of exposure to vapors from remaining contamination exists, and, " The Site poses no further threat to human health and the environment for the contemplated use. The Department closed this spill case on February 15, 2017. "

Remarks: "GASOLINE Spill into secondary containment - NYCDEP,USCG,NYCFD ON SCENE, ALARM FAILURE CAUSED PRODUCT TO EXIT THROUGH VENT IN FIRE EXTINGUISHING SYSTEM,APPROX 200 CU YDS OF CONTAMINATED SOIL."

All Materials:

Site ID:	112706
Operable Unit ID:	944116
Operable Unit:	01
Material ID:	434056
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1000.00
Units:	G
Recovered:	.00
Oxygenate:	True

Site ID: 112706

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

Operable Unit ID:	944116
Operable Unit:	01
Material ID:	572591
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	True

Name:	GASETERIA OIL CORP
Address:	364 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9812647 / 2003-09-19
Facility ID:	9812647
Facility Type:	ER
DER Facility ID:	102823
Site ID:	112707
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	2401
Spill Date:	1999-01-07
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1999-01-13
CID:	384
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-13
Spill Record Last Update:	2003-09-19
Spiller Name:	OSCAR PORCELLI
Spiller Company:	GASETERIA OIL CORP
Spiller Address:	364 MASPETH AVE
Spiller Company:	001
Contact Name:	OSCAR PORCELLI
DEC Memo:	""
Remarks:	"LEAKED FROM AN UNDERGROUND PIPE. CLEAN UP WILL BE COMPLETED BY CALLER'S COMPANY. SAMPLES WERE TAKEN."

All Materials:

Site ID:	112707
Operable Unit ID:	1069897
Operable Unit:	01
Material ID:	312923
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPDES:

Name:	TERMINNALLE
Address:	364 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Permit Number:	NY0005789
State-Region:	02
Expiration Date:	01/01/2004
Current Major Minor Status:	Minor
Primary Facility SIC Code:	5171
State Water Body Name:	ENGLISH KILLS
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	0.022
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	40.718306 / -73.929583
DMR Cognizant Official:	MANUG AYDIN
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	TERMINNALLE
Non-Gov Permit Street Address:	TERMINNALLE
Non-Gov Permit Supplemental Location:	364 MASPETH AVENUE
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11211
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	TERMINNALLE
Non-Gov Facility Street Address:	TERMINNALLE
Non-Gov Facility Supplemental Location:	364 MASPETH AVENUE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

Name:	TERMINNALLE
Address:	364 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
UDF2:	001702
UDF3:	SD

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	TERMINNALLE
Non-Gov Permit Street Address:	TERMINNALLE
Non-Gov Permit Supplemental Location:	364 MASPETH AVENUE
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11211
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	TERMINNALLE
Non-Gov Facility Street Address:	TERMINNALLE
Non-Gov Facility Supplemental Location:	364 MASPETH AVENUE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	TERMINNALLE
Address:	364 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	TERMINNALLE
Non-Gov Permit Street Address:	364 MASPETH AVENUE
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11211
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	TERMINNALLE
Non-Gov Facility Street Address:	TERMINNALLE
Non-Gov Facility Supplemental Location:	364 MASPETH AVENUE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

DITMAS OIL ASSOCIATES, INC. (Continued) **S103827207**

Name:	TERMINNALLE
Address:	364 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
UDF2:	001702
UDF3:	SD
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	TERMINNALLE
Non-Gov Permit Street Address:	364 MASPETH AVENUE
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11211
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	TERMINNALLE
Non-Gov Facility Street Address:	TERMINNALLE
Non-Gov Facility Supplemental Location:	364 MASPETH AVENUE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11211
State Water Body:	02030201010
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

222
East
1/4-1/2
0.363 mi.
1914 ft.

46-81 METROPOLITAN AVE **NY BROWNFIELDS** **S127990275**
46-81 METROPOLITAN AVENUE **N/A**
QUEENS, NY 11385

Relative:
Lower

Actual:
9 ft.

BROWNFIELDS:

Name:	46-81 METROPOLITAN AVE
Address:	46-81 METROPOLITAN AVENUE
City,State,Zip:	QUEENS, NY 11385
Program:	BCP
Site Code:	623115
Acres:	4.490
HW Code:	C241260
SWIS:	4101
Town:	New York City
Record Added Date:	08/06/2021
Record Updated Date:	12/06/2021
Update By:	HMDUDEK
Site Description:	"Location: The site is located at 46-81 Metropolitan Avenue and occupies Queens Borough Tax Block 2611, Lot 71. The site is bound to the north by a bulkhead, the majority of which is a part of the east-adjoining lot, followed by Newtown Creek (a National Priorities List [NPL] site), followed by a parking lot and Grand Avenue; to the east by a grocery store, caf , liquor store, and an asphalt-paved parking area; to the south by Metropolitan Avenue followed by a wholesale grocery store and industrial buildings; and to the west by a concrete supplier and a New York City Transit Authority building,

46-81 METROPOLITAN AVE (Continued) **S127990275**

followed by Newtown Creek. Surrounding properties include single- and multi-story buildings occupied by industrial and commercial occupants. Site Features: The site is approximately 4.5 acres (195,698 square feet) in area and is located in an industrial part of the Ridgewood neighborhood of Queens, New York. According to the 2013 United States Geological Survey (USGS) Brooklyn Quadrangle 7.5-Minute Series Topographic Maps, the site is at an elevation of about 5 to 10 feet above mean sea level (msl). The site and surrounding area slope down to the northwest towards Newtown Creek. The site primarily consists of an asphalt parking lot with a one-story bus maintenance building with an attached two-story office building in the southern portion of the site, and four office trailers in the northeastern portion of the site. Current Zoning and Land Use: According to the New York City (NYC) Planning Commission Zoning Map 13b, the site is located in an M3-1 manufacturing zoning district. M3 districts are designated as areas with heavy industries that generate noise, traffic or pollutants. Typical uses include power plants, solid waste transfer facilities and recycling plants, and fuel supply depots. Past Use of the Site: The site has been occupied by commercial and industrial facilities since as early as 1902. The site is currently developed with a large asphalt paved parking lot, offices and a bus maintenance facility. The historical and current site uses of environmental concern include: automotive repair operations (1971-present); gasoline filling station (1971-2006); Bohack Terminal (1936-1950); and, Hardy, Voorhees and Co. Lumber Yard and Planing Mill (1902). Previous studies dating back to 2014 indicated that stored petroleum and hazardous substances were associated with the current bus repair operations. In addition, several regulatory listings for the site (Resource Conservation and Recovery Act Generators [RCRA], Facility Index System, New York State Department of Environmental Conservation [NYSDEC] Spills and NYSDEC Petroleum Bulk Storage Facilities databases) identified petroleum storage, petroleum releases (closed status) and hazardous waste generation at the site. Previous studies indicate that a total of 21 underground storage tanks (USTs) were removed from the site (along with petroleum-impacted soil and groundwater), and petroleum spills were reported and closed. These reports also indicate that at least one closed-in-place UST; hazardous lead; and petroleum-impacted soil and petroleum-impacted groundwater, including light non-aqueous phase liquid (LNAPL), remain at the site, despite documented remedial efforts related to the petroleum spills. In addition, chlorinated solvents were identified in sub-slab soil vapor at the site. Site Geology and Hydrogeology: The site is underlain by fill to depths ranging from about 4 to 9 feet below grade surface (bgs) across the site; the fill generally consists of sand with varying amounts of gravel, brick, slag, glass, and coal ash. The fill is underlain by native soil which consists of varying amounts of clay, peat, sand and silt. Groundwater was encountered at about 3.5 to 7.5 feet bgs. Groundwater flow is presumed to be to the north towards Newtown Creek. The United States Geological Survey (USGS) Bedrock and Engineering Geologic Maps of New York County and Parts of Kings and Queens Counties, New York, and Parts of Bergen and Hudson Counties, New Jersey estimate bedrock to be about 200-feet bgs and indicate the bedrock underlying the site is the Hartland Formation. The Hartland Formation is comprised of a dark gray, medium to coarse-grained muscovite-biotite-garnet (mica) schist and gray fine-grained quartz-feldspar granulite with biotite and garnet, with localized

46-81 METROPOLITAN AVE (Continued) **S127990275**

	concentrations of granite and intrusions of coarse-grained granitic pegmatite."
Env Problem:	"Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2021-11-01 12:16:00
Record Upd:	2021-11-01 12:16:00
Updated By:	GWBURKE
Own Op:	6
Sub Type:	P03
Owner Name:	Brett Richer
Owner Company:	46-81 Metro Ground Lessee LLC
Owner Address:	c/o Prologis, Inc.
Owner Addr2:	1800 Wazee Street, Suite 500
Owner City,St,Zip:	Denver, CO 80202
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

---

223 **APARTMENT BUILDING** **NY LTANKS** **S107789405**
WSW **35 MEADOW STREET** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.368 mi.
1945 ft.

Relative:
Higher

Actual:
20 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	35 MEADOW STREET
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0601731 / 2006-08-29
Facility ID:	0601731
Site ID:	364030
Spill Date:	2006-05-16
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401

APARTMENT BUILDING (Continued) **S107789405**

Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2006-05-16
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-16
Spill Record Last Update:	2006-08-29
Spiller Name:	DEREK DENCKLA
Spiller Company:	APARTMENT BUILDING
Spiller Address:	35 MEADOW STREET
Spiller County:	001
Spiller Contact:	DEREK DENCKLA
Spiller Phone:	(917) 674-9040
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	314232
DEC Memo:	"05/17/06-Hiralkumar Patel. Spoke to Jim at Protest. it was 1500 gal AST. tank was cleaned in past and doesn't have manhole. and Jim found dry leak and thinks it is from patch on top of tank. he hasn't find any oil stains on floor. he has send proposal to owner and planning to clean tank and to put manhole on tank. haven't found PBS number. Spoke to Derek. he is process of buying this property and gave current owner's name and number. Joseph Heimlich (718) 381-2405 As per Derek, he has closing of this property on Jun 30 2006. once he will get property on his name, he will remove tank and system. owner is not using tank currently. asked him to send tank test results and letter signed by current owner and purchaser stating that they will remove tank after closing and tank is not in use currently by end of tomorrow. told Derek that as this tank is more than 1100 gal capacity, it has to be registered with PBS eventhought they are planning to remove it after Jun. Spoke to Joseph. as per him, he has turn off boiler and tank is not in use currently. tank has oil less than half of the volume. told Joseph that if Department receive letter from him and Derek, Department can wait till they remove tank. but tank has to registered with PBS now. send out letter with tank registration requirement. faxed to Joseph and Derek. Joseph Heimlich 35 Meadow Street Brooklyn, NY 11206 FAX (718) 381-2875 05/19/06-Hiralkumar Patel. Received letter from Joseph and Derek. abstract: - owner is selling property and property is set to close on or about July 30, 2006. - heating season is over and boiler is currently turned off and will remain turned off through contract closing date - based on tank test, owner has cancelled all scheduled oil deliveries and suspended oil delivery service until further notice. 08/01/06-Hiralkumar Patel. spoke with Derek. he is no longer in process of buying this property. spoke with Joseph. owner has removed oil, clean tank and sealed it back. he didn't do any isolation test or system test after tank cleaning. asked Joseph to do system test again. he will call ABC tank for further testing. 08/02/06-Hiralkumar Patel. received call from Robert from ABC Tank. they will do system test probably next week. Robert will call once he gets test result. 08/29/06-Hiralkumar Patel. spoke with Donna at ABC

APARTMENT BUILDING (Continued) **S107789405**

Tank. they have changed rubber gasket on tank. she doesn't have any information about system test. she will check and call back. received call from Donna. she got test result and will fax it. got passing system test in fax. tank is registered now. PBS#: 2-610289 based on available informations, case closed."

Remarks: ""

All Materials:

Site ID:	364030
Operable Unit ID:	1122083
Operable Unit:	01
Material ID:	2111568
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AM224 **LEWIS FLUSHING CORP.** **NY LTANKS** **S106703215**
ESE **1819 FLUSHING AVENUE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.369 mi.
1946 ft. **Site 1 of 2 in cluster AM**

Relative: **Higher**

Actual: **18 ft.**

LTANKS:

Name:	LEWIS FLUSHING CORP.
Address:	1819 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	8800833 / 1993-11-05
Facility ID:	8800833
Site ID:	288930
Spill Date:	1988-04-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1993-11-05
SWIS:	2401
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1988-04-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-04-29
Spill Record Last Update:	2003-01-27
Spiller Name:	Not reported
Spiller Company:	LEWIS FLUSHING CORP.
Spiller Address:	Not reported
Spiller County:	001

LEWIS FLUSHING CORP. (Continued) **S106703215**

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 234005
DEC Memo: ""
Remarks: "3,500 GALLON TANK SYSTEM FAILED PETROTITE TANK TEST AT 2.5 GALLONS PER HOUR. COULD NOT MAINTAIN LEVEL IN TEST EQUIPMENT."

All TTF:
Facility ID: 8800833
Spill Number: 8800833
Spill Tank Test: 1533765
Site ID: 288930
Tank Number: Not reported
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 288930
Operable Unit ID: 916321
Operable Unit: 01
Material ID: 460004
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Oxygenate: Not reported

---

225 SW 1/4-1/2 0.371 mi. 1958 ft.

MORGAN TERMINAL
200 MORGAN AVE
NEW YORK, NY

NY HSWDS **S108146606**
N/A

Relative: Higher

Actual: 15 ft.

HSWDS:
Facility ID: Not reported
Region: 2
Facility Status: Unknown
Owner Type: Puplic
Owner: Morgan Oil Corporation
Owner Address: c/o Shatzkin&F 99 Wall St
Owner Phone: Unknown
Operator Type: Puplic

MORGAN TERMINAL (Continued) **S108146606**

Operator:	N/A
Operator:	N/A
Operator Phone:	Not reported
EPA ID:	Not reported
Registry:	Unknown
Registry Site ID:	Unknown
RCRA Permitted:	Unknown
Site Code:	Leaking tanks, drums, lagoons, other containers
Owner City State:	New York, NY
Operator City State:	Not reported
Quadrange:	Brooklyn Quadrangle
Latitude:	40 42 30 N
Longitude:	73 56 00 W
Acres:	0.00
Operator Date:	> 40 yrs
Close Date:	Unknown
Completed:	Unknown
Active:	No
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	Yes
Asbestos Disposed:	Yes
Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	Groundwater
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Surface Soil
Analytical Info Exists for Substance:	Subsurface
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	TCLP
Threat to Environment/Public Health:	Environmental
Surface Water Contamination:	Yes
Surface Water Body Class:	SD
Groundwater Contamination:	Yes
Groundwater Classification:	SoleSource
Drinking Water Contamination:	No
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	No
Site Has Controlled Acess:	No
Ambient Air Contamination:	No
Direct Contact:	No
EPA Hazardous Ranking System Score:	Not reported
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported

MORGAN TERMINAL (Continued) **S108146606**

Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

226
SE
1/4-1/2
0.379 mi.
2001 ft.

F & W WOODWORK CO
1267 FLUSHING AVE
BROOKLYN, NY 11237

NY LTANKS **1000554921**
NY Spills **NYD986974129**
RCRA NonGen / NLR
NY MANIFEST

Relative:
Higher

Actual:
17 ft.

LTANKS:

Name:	1267 FLUSHING AVENUE
Address:	1267 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9308847 / 1993-10-21
Facility ID:	9308847
Site ID:	60933
Spill Date:	1993-10-21
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1993-10-21
SWIS:	2401
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1993-10-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-10-21
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	BAERENKLAU FUEL OIL CO.
Spiller Address:	740 JAMAICA AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2

F & W WOODWORK CO (Continued) **1000554921**

DER Facility ID: 59401
DEC Memo: ""
Remarks: "SPEEDY DRY USED."

All Materials:
Site ID: 60933
Operable Unit ID: 987772
Operable Unit: 01
Material ID: 570164
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: 1267 FLUSHING AVE/C F & W
Address: 1267 FLUSHING AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9110833 / 2001-11-07
Facility ID: 9110833
Facility Type: ER
DER Facility ID: 59401
Site ID: 72106
DEC Region: 2
Spill Cause: Human Error
Spill Class: C4
SWIS: 2401
Spill Date: 1991-08-23
Investigator: TOMASELLO
Referred To: Not reported
Reported to Dept: 1992-01-17
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: 2001-11-07
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1992-02-06
Spill Record Last Update: 2001-11-07
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "TONE CLEANING; NYCDEP ISSUED CLEANUP ORDER."

F & W WOODWORK CO (Continued) **1000554921**

RCRA NonGen / NLR:

Date Form Received by Agency:		20070101
Handler Name:	F & W WOODWORK CO	
Handler Address:		1267 FLUSHING AVE
Handler City,State,Zip:		BROOKLYN, NY 11237-2302
EPA ID:		NYD986974129
Contact Name:		Not reported
Contact Address:		FLUSHING AVE
Contact City,State,Zip:		BROOKLYN, NY 11237
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		NY
State District:		NYSDEC R2
Mailing Address:		FLUSHING AVE
Mailing City,State,Zip:		BROOKLYN, NY 11237
Owner Name:		FRANZ FISCHER
Owner Type:		Private
Operator Name:		FRANZ FISCHER
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported

F & W WOODWORK CO (Continued) **1000554921**

202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	FRANZ FISCHER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

F & W WOODWORK CO (Continued) **1000554921**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	FRANZ FISCHER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	FRANZ FISCHER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	UNKNOWN
Owner/Operator City,State,Zip:	UNKNOWN, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: F & W WOODWORK CO	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: F & W WOODWORK CO	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: F & W WOODWORK CO	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

F & W WOODWORK CO (Continued) **1000554921**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19910821
Handler Name: F & W WOODWORK CO	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violation:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number: Not reported	
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type: Not reported	
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number: Not reported	
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported

F & W WOODWORK CO (Continued) **1000554921**

Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19921216
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NY MANIFEST:

Name:	F W WOODWORK
Address:	1267 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11237-2302
Country:	USA
EPA ID:	NYD986974129
Facility Status:	Not reported
Location Address 1:	1267 FLUSHING AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11237
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986974129
Mailing Name:	F W WOODWORK
Mailing Contact:	RAY CRUZ
Mailing Address 1:	1267 FLUSHING AVE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11237
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7188211300

AI227 **DERBY TEXTILE CORPORATION** **NY LTANKS** **U000411048**
South **41 VARICK AVENUE** **NY UST** **N/A**
1/4-1/2 **BROOKLYN, NY 11237**
0.380 mi.
2004 ft. **Site 2 of 2 in cluster AI**

Relative:
Higher

Actual:
16 ft.

LTANKS:

Name:	DERBY TEXTILE CORP
Address:	41 VARICK AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9713513 / 2004-08-18
Facility ID:	9713513
Site ID:	331363
Spill Date:	1998-03-05
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	1998-03-05
CID:	322
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-03-05
Spill Record Last Update:	2004-08-18
Spiller Name:	KEITH
Spiller Company:	DERBY TEXTILE CORP
Spiller Address:	41 VARICK AVE
Spiller County:	001
Spiller Contact:	KEITH
Spiller Phone:	(718) 384-9151
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	266507
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND Sub to USA tanks, Keith 718-384-9151. 8/18/2004 Sangesland reviewed a package from William Fried of Derby Textile Corp. (718-628-6300). Receipts show that PTC returned to the site 3/26-3/31 1998 (2 weeks after the initial spill report). They excavated to tank top and replaced all lines. No contamination was found. Tank was cleaned and then retested - Passed."
Remarks:	"GROSS FAILURE "

All TTF:

Facility ID:	9713513
Spill Number:	9713513
Spill Tank Test:	1545656
Site ID:	331363
Tank Number:	1
Tank Size:	3000
Material:	0002
EPA UST:	Not reported
UST:	Not reported

DERBY TEXTILE CORPORATION (Continued) **U000411048**

Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	331363
Operable Unit ID:	1056368
Operable Unit:	01
Material ID:	324528
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

UST:

Name:	DERBY TEXTILE CORPORATION
Address:	41 VARICK AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Id/Status:	2-477982 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590685.03398
UTM Y:	4506768.31548
Site Type:	Other

Affiliation Records:

Site Id:	21224
Affiliation Type:	Mail Contact
Company Name:	DERBY TEXTILE CORPORATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	41 VARICK AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 628-6300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-05-12

Site Id:	21224
Affiliation Type:	Facility Operator

DERBY TEXTILE CORPORATION (Continued) **U000411048**

Company Name:	DERBY TEXTILE CORPORATION
Contact Type:	Not reported
Contact Name:	WOLF FRIED
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 628-6300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-05-12

Site Id:	21224
Affiliation Type:	Emergency Contact
Company Name:	DERBY TEXTILE CORPORATION
Contact Type:	Not reported
Contact Name:	WOLF FRIED
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 628-6300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-05-12

Site Id:	21224
Affiliation Type:	Facility Owner
Company Name:	DERBY TEXTILE CORPORATION
Contact Type:	V.P.
Contact Name:	WOLF FRIED
Address1:	41 VARICK AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 628-6300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2016-05-12

Tank Info:

Tank Number:	001
Tank ID:	38456
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2700
Install Date:	01/01/1931

DERBY TEXTILE CORPORATION (Continued) **U000411048**

Date Tank Closed:	12/09/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	12/07/2015
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MRBARROW
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None

228
SSW
1/4-1/2
0.380 mi.
2005 ft.

88 INGRAHAM REALTY CORP
88 INGRAHAM ST
BROOKLYN, NY 11206

RCRA-SQG **1000425382**
NY ENG CONTROLS **NYD020592838**
NY INST CONTROL
NY VCP
NY MANIFEST

Relative:
Higher

Actual:
21 ft.

RCRA-SQG:

Date Form Received by Agency:	20110725
Handler Name:	88 INGRAHAM REALTY CORP
Handler Address:	88 INGRAHAM ST
Handler City,State,Zip:	BROOKLYN, NY 11206
EPA ID:	NYD020592838
Contact Name:	WILLIAM EISEN
Contact Address:	BELLAVERDE WAY
Contact City,State,Zip:	DELRAY BEACH, FL 33445
Contact Telephone:	561-496-5200
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	FORMER OWNER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	INGRAHAM ST
Mailing City,State,Zip:	BROOKLYN, NY 11206
Owner Name:	MARTIN ZIMMERMAN
Owner Type:	Private
Operator Name:	MARTIN ZIMMERMAN
Operator Type:	Private

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Hazardous Waste Summary:
Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MARTIN ZIMMERMAN
Legal Status: Private
Date Became Current: 20030315
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MARTIN ZIMMERMAN
Legal Status: Private
Date Became Current: 20030315
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: POPULAR UNIFORM RENTAL
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: POPULAR UNIFORM RENTAL
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: POPULAR UNIFORM RENTAL
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Receive Date: 19850710
Handler Name: POPULAR UNIFORM RENTAL
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20110725
Handler Name: 88 INGRAHAM REALTY CORP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 23899
NAICS Description: ALL OTHER SPECIALTY TRADE CONTRACTORS

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19870330
Actual Return to Compliance Date: 19870330
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19830401
Enforcement Identifier: 001
Date of Enforcement Action: 19830330
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYDEC
Enforcement Responsible Sub-Organization: Not reported

88 INGRAHAM REALTY CORP (Continued) **1000425382**

SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19870330
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19870330
Scheduled Compliance Date: 19830401
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

ENG CONTROLS:
Name: POPULAR HAND LAUNDRY
Address: 88 INGRAHM STREET
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58534
HW Code: V00170
Control Code: 15
Control Type: ENG
Date Record Added: 02/23/2016
Date Rec Updated: 11/19/2019
Updated By: LSZINOMA
Site Description: "Location: The site is located at 88 Ingraham Street in Brooklyn, NY. Site Features: It consists of a two story building with an adjoining garage. The building comprises approximately 11,000 sq ft. and occupies the entire site. Current Zoning/Use: The site is currently used as for storage and restoration of antique furniture and artwork. The surrounding area is industrial. Historical Use: Since 1933 the building has been used for skein dying, dry cleaning and laundry operations. The site was acquired by Popular Hand Laundry (circa 1970) which operated dry cleaning services. Prior to 1970, a dry cleaning and laundry facility was operated by Klink. The site remedial program is being performed by 88 Ingraham Realty Corp. and Popular Hand Laundry and Cleaners of Richmond Hill, Inc. under the DEC's Voluntary Cleanup Program. Site Geology and Hydrogeology: Groundwater was detected at about 15 feet below grade, and measurements of groundwater elevation indicated that groundwater flow is to the north. "
Env Problem: "Nature and extent of contamination: Post remediation: remediation at

88 INGRAHAM REALTY CORP (Continued) **1000425382**

	the site is complete. prior to remediation, the primary contaminants of concern were the chlorinated solvents tetrachloroethene and trichloroethene in soil, groundwater and soil vapor. Remediation has successfully achieved soil cleanup objectives for commercial and industrial use. Remaining contamination in soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2009-10-06 08:02:00
Record Upd:	2013-09-20 14:17:00
Updated By:	ldennist
Own Op:	6
Sub Type:	03
Owner Name:	William Eisen
Owner Company:	88 ingraham Realty Corporation
Owner Address:	7700 Bella verde Way
Owner Addr2:	Not reported
Owner City,St,Zip:	Delray Beach, FL 33446
Owner Country:	United States of America
HW Code:	V00170
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00170
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00170
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00170
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	W2-0813-98-06(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS
Name:	POPULAR HAND LAUNDRY
Address:	88 INGRAHM STREET
City,State,Zip:	BROOKLYN, NY 11237
Site Code:	58534
HW Code:	V00170

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Control Code:	13
Control Type:	ENG
Date Record Added:	02/23/2016
Date Rec Updated:	11/19/2019
Updated By:	LSZINOMA
Site Description:	"Location: The site is located at 88 Ingraham Street in Brooklyn, NY. Site Features: It consists of a two story building with an adjoining garage. The building comprises approximately 11,000 sq ft. and occupies the entire site. Current Zoning/Use: The site is currently used as for storage and restoration of antique furniture and artwork. The surrounding area is industrial. Historical Use: Since 1933 the building has been used for skein dying, dry cleaning and laundry operations. The site was acquired by Popular Hand Laundry (circa 1970) which operated dry cleaning services. Prior to 1970, a dry cleaning and laundry facility was operated by Klink. The site remedial program is being performed by 88 Ingraham Realty Corp. and Popular Hand Laundry and Cleaners of Richmond Hill, Inc. under the DEC's Voluntary Cleanup Program. Site Geology and Hydrogeology: Groundwater was detected at about 15 feet below grade, and measurements of groundwater elevation indicated that groundwater flow is to the north. "
Env Problem:	"Nature and extent of contamination: Post remediation: remediation at the site is complete. prior to remediation, the primary contaminants of concern were the chlorinated solvents tetrachloroethene and trichloroethene in soil, groundwater and soil vapor. Remediation has successfully achieved soil cleanup objectives for commercial and industrial use. Remaining contamination in soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2009-10-06 08:02:00
Record Upd:	2013-09-20 14:17:00
Updated By:	ldennist
Own Op:	6
Sub Type:	03
Owner Name:	William Eisen
Owner Company:	88 ingraham Realty Corporation
Owner Address:	7700 Bella verde Way
Owner Addr2:	Not reported
Owner City,St,Zip:	Delray Beach, FL 33446
Owner Country:	United States of America
HW Code:	V00170
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00170
Waste Type:	tetrachloroethene (PCE)

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-0813-98-06(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

INST CONTROL:
Name: POPULAR HAND LAUNDRY
Address: 88 INGRAHM STREET
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58534
Control Name: Landuse Restriction
HW Code: V00170
Control Code: 25
Control Type: INST
Dt record added: 02/23/2016
Dt rec updated: 11/19/2019
Updated By: LSZINOMA
Site Code: 58534
Site Description: "Location: The site is located at 88 Ingraham Street in Brooklyn, NY. Site Features: It consists of a two story building with an adjoining garage. The building comprises approximately 11,000 sq ft. and occupies the entire site. Current Zoning/Use: The site is currently used as for storage and restoration of antique furniture and artwork. The surrounding area is industrial. Historical Use: Since 1933 the building has been used for skein dying, dry cleaning and laundry operations. The site was acquired by Popular Hand Laundry (circa 1970) which operated dry cleaning services. Prior to 1970, a dry cleaning and laundry facility was operated by Klink. The site remedial program is being performed by 88 Ingraham Realty Corp. and Popular Hand Laundry and Cleaners of Richmond Hill, Inc. under the DEC's Voluntary Cleanup Program. Site Geology and Hydrogeology: Groundwater was detected at about 15 feet below grade, and measurements of groundwater elevation indicated that groundwater flow is to the north. "
Env Problem: "Nature and extent of contamination: Post remediation: remediation at the site is complete. prior to remediation, the primary contaminants of concern were the chlorinated solvents tetrachloroethene and trichloroethene in soil, groundwater and soil vapor. Remediation has successfully achieved soil cleanup objectives for commercial and industrial use. Remaining contamination in soil vapor is being managed under a Site Management Plan. "
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump: False

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-10-06 08:02:00
Record Upd: 2013-09-20 14:17:00
Updated By: ldennist
Own Op: 6
Sub Type: 03
Owner Name: William Eisen
Owner Company: 88 ingraham Realty Corporation
Owner Address: 7700 Bella verde Way
Owner Addr2: Not reported
Owner City,St,Zip: Delray Beach, FL 33446
Owner Country: United States of America
HW Code: V00170
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-0813-98-06(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Name: POPULAR HAND LAUNDRY
Address: 88 INGRAHM STREET
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58534
Control Name: Soil Management Plan
HW Code: V00170
Control Code: 14
Control Type: INST
Dt record added: 02/23/2016
Dt rec updated: 11/19/2019
Updated By: LSZINOMA
Site Code: 58534
Site Description: "Location: The site is located at 88 Ingraham Street in Brooklyn, NY. Site Features: It consists of a two story building with an adjoining garage. The building comprises approximately 11,000 sq ft. and

88 INGRAHAM REALTY CORP (Continued) **1000425382**

occupies the entire site. Current Zoning/Use: The site is currently used as for storage and restoration of antique furniture and artwork. The surrounding area is industrial. Historical Use: Since 1933 the building has been used for skein dying, dry cleaning and laundry operations. The site was acquired by Popular Hand Laundry (circa 1970) which operated dry cleaning services. Prior to 1970, a dry cleaning and laundry facility was operated by Klink. The site remedial program is being performed by 88 Ingraham Realty Corp. and Popular Hand Laundry and Cleaners of Richmond Hill, Inc. under the DEC's Voluntary Cleanup Program. Site Geology and Hydrogeology: Groundwater was detected at about 15 feet below grade, and measurements of groundwater elevation indicated that groundwater flow is to the north. "

Env Problem: "Nature and extent of contamination: Post remediation: remediation at the site is complete. prior to remediation, the primary contaminants of concern were the chlorinated solvents tetrachloroethene and trichloroethene in soil, groundwater and soil vapor. Remediation has successfully achieved soil cleanup objectives for commercial and industrial use. Remaining contamination in soil vapor is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-10-06 08:02:00
Record Upd: 2013-09-20 14:17:00
Updated By: ldennist
Own Op: 6
Sub Type: 03
Owner Name: William Eisen
Owner Company: 88 ingraham Realty Corporation
Owner Address: 7700 Bella verde Way
Owner Addr2: Not reported
Owner City,St,Zip: Delray Beach, FL 33446
Owner Country: United States of America
HW Code: V00170
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: Hazardous Substances

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-0813-98-06(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Name: POPULAR HAND LAUNDRY
Address: 88 INGRAHM STREET
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58534
Control Name: IC/EC Plan
HW Code: V00170
Control Code: 34
Control Type: INST
Dt record added: 02/23/2016
Dt rec updated: 11/19/2019
Updated By: LSZINOMA
Site Code: 58534
Site Description: "Location: The site is located at 88 Ingraham Street in Brooklyn, NY. Site Features: It consists of a two story building with an adjoining garage. The building comprises approximately 11,000 sq ft. and occupies the entire site. Current Zoning/Use: The site is currently used as for storage and restoration of antique furniture and artwork. The surrounding area is industrial. Historical Use: Since 1933 the building has been used for skein dying, dry cleaning and laundry operations. The site was acquired by Popular Hand Laundry (circa 1970) which operated dry cleaning services. Prior to 1970, a dry cleaning and laundry facility was operated by Klink. The site remedial program is being performed by 88 Ingraham Realty Corp. and Popular Hand Laundry and Cleaners of Richmond Hill, Inc. under the DEC's Voluntary Cleanup Program. Site Geology and Hydrogeology: Groundwater was detected at about 15 feet below grade, and measurements of groundwater elevation indicated that groundwater flow is to the north. "
Env Problem: "Nature and extent of contamination: Post remediation: remediation at the site is complete. prior to remediation, the primary contaminants of concern were the chlorinated solvents tetrachloroethene and trichloroethene in soil, groundwater and soil vapor. Remediation has successfully achieved soil cleanup objectives for commercial and industrial use. Remaining contamination in soil vapor is being managed under a Site Management Plan. "
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-10-06 08:02:00

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Record Upd: 2013-09-20 14:17:00
Updated By: ldennist
Own Op: 6
Sub Type: 03
Owner Name: William Eisen
Owner Company: 88 ingraham Realty Corporation
Owner Address: 7700 Bella verde Way
Owner Addr2: Not reported
Owner City,St,Zip: Delray Beach, FL 33446
Owner Country: United States of America
HW Code: V00170
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-0813-98-06(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Name: POPULAR HAND LAUNDRY
Address: 88 INGRAHM STREET
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58534
Control Name: Ground Water Use Restriction
HW Code: V00170
Control Code: 08
Control Type: INST
Dt record added: 02/23/2016
Dt rec updated: 11/19/2019
Updated By: LSZINOMA
Site Code: 58534
Site Description: "Location: The site is located at 88 Ingraham Street in Brooklyn, NY. Site Features: It consists of a two story building with an adjoining garage. The building comprises approximately 11,000 sq ft. and occupies the entire site. Current Zoning/Use: The site is currently used as for storage and restoration of antique furniture and artwork. The surrounding area is industrial. Historical Use: Since 1933 the building has been used for skein dying, dry cleaning and laundry operations. The site was acquired by Popular Hand Laundry (circa 1970) which operated dry cleaning services. Prior to 1970, a dry cleaning and laundry facility was operated by Klink. The site remedial program is being performed by 88 Ingraham Realty Corp. and Popular Hand Laundry and Cleaners of Richmond Hill, Inc. under the

88 INGRAHAM REALTY CORP (Continued) **1000425382**

DEC's Voluntary Cleanup Program. Site Geology and Hydrogeology: Groundwater was detected at about 15 feet below grade, and measurements of groundwater elevation indicated that groundwater flow is to the north. "

Env Problem: "Nature and extent of contamination: Post remediation: remediation at the site is complete. prior to remediation, the primary contaminants of concern were the chlorinated solvents tetrachloroethene and trichloroethene in soil, groundwater and soil vapor. Remediation has successfully achieved soil cleanup objectives for commercial and industrial use. Remaining contamination in soil vapor is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-10-06 08:02:00
Record Upd: 2013-09-20 14:17:00
Updated By: ldennist
Own Op: 6
Sub Type: 03
Owner Name: William Eisen
Owner Company: 88 ingraham Realty Corporation
Owner Address: 7700 Bella verde Way
Owner Addr2: Not reported
Owner City,St,Zip: Delray Beach, FL 33446
Owner Country: United States of America
HW Code: V00170
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-0813-98-06(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Name:	POPULAR HAND LAUNDRY
Address:	88 INGRAHM STREET
City,State,Zip:	BROOKLYN, NY 11237
Site Code:	58534
Control Name:	Deed Restriction
HW Code:	V00170
Control Code:	A
Control Type:	INST
Dt record added:	02/23/2016
Dt rec updated:	11/19/2019
Updated By:	LSZINOMA
Site Code:	58534
Site Description:	"Location: The site is located at 88 Ingraham Street in Brooklyn, NY. Site Features: It consists of a two story building with an adjoining garage. The building comprises approximately 11,000 sq ft. and occupies the entire site. Current Zoning/Use: The site is currently used as for storage and restoration of antique furniture and artwork. The surrounding area is industrial. Historical Use: Since 1933 the building has been used for skein dying, dry cleaning and laundry operations. The site was acquired by Popular Hand Laundry (circa 1970) which operated dry cleaning services. Prior to 1970, a dry cleaning and laundry facility was operated by Klink. The site remedial program is being performed by 88 Ingraham Realty Corp. and Popular Hand Laundry and Cleaners of Richmond Hill, Inc. under the DEC's Voluntary Cleanup Program. Site Geology and Hydrogeology: Groundwater was detected at about 15 feet below grade, and measurements of groundwater elevation indicated that groundwater flow is to the north. "
Env Problem:	"Nature and extent of contamination: Post remediation: remediation at the site is complete. prior to remediation, the primary contaminants of concern were the chlorinated solvents tetrachloroethene and trichloroethene in soil, groundwater and soil vapor. Remediation has successfully achieved soil cleanup objectives for commercial and industrial use. Remaining contamination in soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2009-10-06 08:02:00
Record Upd:	2013-09-20 14:17:00
Updated By:	ldennist
Own Op:	6
Sub Type:	03
Owner Name:	William Eisen
Owner Company:	88 ingraham Realty Corporation
Owner Address:	7700 Bella verde Way
Owner Addr2:	Not reported
Owner City,St,Zip:	Delray Beach, FL 33446

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Owner Country: United States of America
HW Code: V00170
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-0813-98-06(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Name: POPULAR HAND LAUNDRY
Address: 88 INGRAHM STREET
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58534
Control Name: O&M Plan
HW Code: V00170
Control Code: 33
Control Type: INST
Dt record added: 02/23/2016
Dt rec updated: 11/19/2019
Updated By: LSZINOMA
Site Code: 58534
Site Description: "Location: The site is located at 88 Ingraham Street in Brooklyn, NY. Site Features: It consists of a two story building with an adjoining garage. The building comprises approximately 11,000 sq ft. and occupies the entire site. Current Zoning/Use: The site is currently used as for storage and restoration of antique furniture and artwork. The surrounding area is industrial. Historical Use: Since 1933 the building has been used for skein dying, dry cleaning and laundry operations. The site was acquired by Popular Hand Laundry (circa 1970) which operated dry cleaning services. Prior to 1970, a dry cleaning and laundry facility was operated by Klink. The site remedial program is being performed by 88 Ingraham Realty Corp. and Popular Hand Laundry and Cleaners of Richmond Hill, Inc. under the DEC's Voluntary Cleanup Program. Site Geology and Hydrogeology: Groundwater was detected at about 15 feet below grade, and measurements of groundwater elevation indicated that groundwater flow is to the north. "
Env Problem: "Nature and extent of contamination: Post remediation: remediation at the site is complete. prior to remediation, the primary contaminants of concern were the chlorinated solvents tetrachloroethene and trichloroethene in soil, groundwater and soil vapor. Remediation has successfully achieved soil cleanup objectives for commercial and

88 INGRAHAM REALTY CORP (Continued) **1000425382**

	industrial use. Remaining contamination in soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2009-10-06 08:02:00
Record Upd:	2013-09-20 14:17:00
Updated By:	ldennist
Own Op:	6
Sub Type:	03
Owner Name:	William Eisen
Owner Company:	88 ingraham Realty Corporation
Owner Address:	7700 Bella verde Way
Owner Addr2:	Not reported
Owner City,St,Zip:	Delray Beach, FL 33446
Owner Country:	United States of America
HW Code:	V00170
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00170
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00170
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00170
Waste Type:	Hazardous Substances
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	W2-0813-98-06(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS

Name:	POPULAR HAND LAUNDRY
Address:	88 INGRAHM STREET
City,State,Zip:	BROOKLYN, NY 11237
Site Code:	58534
Control Name:	Site Management Plan
HW Code:	V00170
Control Code:	32
Control Type:	INST
Dt record added:	02/23/2016

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Dt rec updated:	11/19/2019
Updated By:	LSZINOMA
Site Code:	58534
Site Description:	"Location: The site is located at 88 Ingraham Street in Brooklyn, NY. Site Features: It consists of a two story building with an adjoining garage. The building comprises approximately 11,000 sq ft. and occupies the entire site. Current Zoning/Use: The site is currently used as for storage and restoration of antique furniture and artwork. The surrounding area is industrial. Historical Use: Since 1933 the building has been used for skein dying, dry cleaning and laundry operations. The site was acquired by Popular Hand Laundry (circa 1970) which operated dry cleaning services. Prior to 1970, a dry cleaning and laundry facility was operated by Klink. The site remedial program is being performed by 88 Ingraham Realty Corp. and Popular Hand Laundry and Cleaners of Richmond Hill, Inc. under the DEC's Voluntary Cleanup Program. Site Geology and Hydrogeology: Groundwater was detected at about 15 feet below grade, and measurements of groundwater elevation indicated that groundwater flow is to the north. "
Env Problem:	"Nature and extent of contamination: Post remediation: remediation at the site is complete. prior to remediation, the primary contaminants of concern were the chlorinated solvents tetrachloroethene and trichloroethene in soil, groundwater and soil vapor. Remediation has successfully achieved soil cleanup objectives for commercial and industrial use. Remaining contamination in soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2009-10-06 08:02:00
Record Upd:	2013-09-20 14:17:00
Updated By:	ldennist
Own Op:	6
Sub Type:	03
Owner Name:	William Eisen
Owner Company:	88 ingraham Realty Corporation
Owner Address:	7700 Bella verde Way
Owner Addr2:	Not reported
Owner City,St,Zip:	Delray Beach, FL 33446
Owner Country:	United States of America
HW Code:	V00170
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00170
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

88 INGRAHAM REALTY CORP (Continued) **1000425382**

HW Code: V00170
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-0813-98-06(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

Name: POPULAR HAND LAUNDRY
Address: 88 INGRAHM STREET
City,State,Zip: BROOKLYN, NY 11237
Site Code: 58534
Control Name: Monitoring Plan
HW Code: V00170
Control Code: 31
Control Type: INST
Dt record added: 02/23/2016
Dt rec updated: 11/19/2019
Updated By: LSZINOMA
Site Code: 58534
Site Description: "Location: The site is located at 88 Ingraham Street in Brooklyn, NY. Site Features: It consists of a two story building with an adjoining garage. The building comprises approximately 11,000 sq ft. and occupies the entire site. Current Zoning/Use: The site is currently used as for storage and restoration of antique furniture and artwork. The surrounding area is industrial. Historical Use: Since 1933 the building has been used for skein dying, dry cleaning and laundry operations. The site was acquired by Popular Hand Laundry (circa 1970) which operated dry cleaning services. Prior to 1970, a dry cleaning and laundry facility was operated by Klink. The site remedial program is being performed by 88 Ingraham Realty Corp. and Popular Hand Laundry and Cleaners of Richmond Hill, Inc. under the DEC's Voluntary Cleanup Program. Site Geology and Hydrogeology: Groundwater was detected at about 15 feet below grade, and measurements of groundwater elevation indicated that groundwater flow is to the north. "
Env Problem: "Nature and extent of contamination: Post remediation: remediation at the site is complete. prior to remediation, the primary contaminants of concern were the chlorinated solvents tetrachloroethene and trichloroethene in soil, groundwater and soil vapor. Remediation has successfully achieved soil cleanup objectives for commercial and industrial use. Remaining contamination in soil vapor is being managed under a Site Management Plan. "
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump: False
Structure: False
Lagoon: False
Landfill: False

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-10-06 08:02:00
Record Upd: 2013-09-20 14:17:00
Updated By: ldennist
Own Op: 6
Sub Type: 03
Owner Name: William Eisen
Owner Company: 88 ingraham Realty Corporation
Owner Address: 7700 Bella verde Way
Owner Addr2: Not reported
Owner City,St,Zip: Delray Beach, FL 33446
Owner Country: United States of America
HW Code: V00170
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00170
Waste Type: Hazardous Substances
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-0813-98-06(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

VCP:
Name: POPULAR HAND LAUNDRY
Address: 88 INGRAHM STREET
City,State,Zip: BROOKLYN, NY 11237
Program Type: VCP
Site Code: 58534
HW Code: V00170
Site Class: C
SWIS: 2401
Region: 2
Town: New York City
Acres: Not reported
Date Record Added: 11/30/2000
Date Record Updated: 02/27/2018
Updated By: JHOCONNE
Site Description: "Location: The site is located at 88 Ingraham Street in Brooklyn, NY. Site Features: It consists of a two story building with an adjoining garage. The building comprises approximately 11,000 sq ft. and

88 INGRAHAM REALTY CORP (Continued) **1000425382**

	occupies the entire site. Current Zoning/Use: The site is currently used as for storage and restoration of antique furniture and artwork. The surrounding area is industrial. Historical Use: Since 1933 the building has been used for skein dying, dry cleaning and laundry operations. The site was acquired by Popular Hand Laundry (circa 1970) which operated dry cleaning services. Prior to 1970, a dry cleaning and laundry facility was operated by Klink. The site remedial program is being performed by 88 Ingraham Realty Corp. and Popular Hand Laundry and Cleaners of Richmond Hill, Inc. under the DEC's Voluntary Cleanup Program. Site Geology and Hydrogeology: Groundwater was detected at about 15 feet below grade, and measurements of groundwater elevation indicated that groundwater flow is to the north. "
Env Problem:	"Nature and extent of contamination: Post remediation: remediation at the site is complete. prior to remediation, the primary contaminants of concern were the chlorinated solvents tetrachloroethene and trichloroethene in soil, groundwater and soil vapor. Remediation has successfully achieved soil cleanup objectives for commercial and industrial use. Remaining contamination in soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2009-10-06 08:02:00
Record Upd:	2013-09-20 14:17:00
Updated By:	ldennist
Own Op:	6
Sub Type:	03
Owner Name:	William Eisen
Owner Company:	88 ingraham Realty Corporation
Owner Address:	7700 Bella verde Way
Owner Addr2:	Not reported
Owner City,St,Zip:	Delray Beach, FL 33446
Owner Country:	United States of America
HW Code:	V00170
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00170
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00170
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00170
Waste Type:	Hazardous Substances

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: W2-0813-98-06(R
Cross Ref Type Code: 20
Cross Ref Type: Haz. Substance ID
Record Added Date: 2000-11-30 16:07:00
Record Updated: 2005-02-24 15:54:00
Updated By: VCPTRANS

NY MANIFEST:
Name: POPULAR UNIFORM RENTAL
Address: 88 INGRAHM ST
City,State,Zip: BROOKLYN, NY 11237-1479
Country: USA
EPA ID: NYD020592838
Facility Status: Not reported
Location Address 1: 88 INGRAHM ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11237
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD020592838
Mailing Name: POPULAR UNIFORM RENTAL
Mailing Contact: POPULAR UNIFORM RENTAL
Mailing Address 1: 88 INGRAHM STREET
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11237
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7184973000

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYR000134957
Trans2 State ID: PAD982661381
Generator Ship Date: 12/12/2013
Trans1 Recv Date: 12/12/2013
Trans2 Recv Date: 12/13/2013
TSD Site Recv Date: 01/03/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD020592838
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: MID980615298
TSDF ID 2: Not reported
Manifest Tracking Number: 011979923JJK

88 INGRAHAM REALTY CORP (Continued) **1000425382**

Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D039
Waste Code 1_2:	D043
Waste Code 1_3:	F002
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

---

229 **EMPIRE WAREHOUSE** **NY LTANKS** **S104278053**
ESE **1312-1324 FLUSHING AVE** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.387 mi.
2041 ft.

Relative:
Higher

Actual:
23 ft.

LTANKS:

Name:	EMPIRE WAREHOUSE
Address:	1312-1324 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9903972 / 2000-08-23
Facility ID:	9903972
Site ID:	111006
Spill Date:	1999-07-06
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1999-07-06
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False

EMPIRE WAREHOUSE (Continued) **S104278053**

Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-07-06
Spill Record Last Update:	2000-08-23
Spiller Name:	JOE CARDONE
Spiller Company:	EMPIRE WAREHOUSE
Spiller Address:	1312-1324 FLUSHING AVE
Spiller County:	001
Spiller Contact:	JOE CARDONE
Spiller Phone:	(718) 366-7500
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	97140
DEC Memo:	""
Remarks:	"TANK FAILED THE TEST."

All TTF:

Facility ID:	9903972
Spill Number:	9903972
Spill Tank Test:	1547341
Site ID:	111006
Tank Number:	1
Tank Size:	7500
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	111006
Operable Unit ID:	1078415
Operable Unit:	01
Material ID:	303871
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AJ230 **CORNELL BEVERAGES INC** **NY LTANKS** **U000394301**
South **105 HARRISON PLACE** **NY UST** **N/A**
1/4-1/2 **BROOKLYN, NY 11237**
0.393 mi.
2074 ft. **Site 4 of 4 in cluster AJ**

Relative: **Higher**

Actual: **20 ft.**

LTANKS:

Name:	COMMERCIAL
Address:	105 HARRISON PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0706869 / 2008-10-17
Facility ID:	0706869
Site ID:	387468
Spill Date:	2007-09-20
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2007-09-20
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-09-20
Spill Record Last Update:	2008-10-17
Spiller Name:	ALLEN HOFFMAN
Spiller Company:	COMMERCIAL
Spiller Address:	105 HARRISON PLACE
Spiller County:	001
Spiller Contact:	ALLEN HOFFMAN
Spiller Phone:	(718) 381-3000
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	83354
DEC Memo:	"9/21/07 bf: Called Allan Hoffman 718-381-3000 and left message to call me back. Sent ttf letter to: Allan Hoffman Cornell Beverages, Inc. 105 Harrison Place Brooklyn, NY 11237 9/24/07 Received call from Donna Hoffman. Tank failed with a dry leak and the tank is ot in use at this time. She said that she they are working on the repair or closure of the tank. They are not sure which they want to do at this time. She did not know how to proceed on repairs. I told her that her tank company may do repairs and she should contact them or another company. She also wanted to know about closure. I told her it would need to be emptied and cleaned prior to filling it with sand, cement, or foam. If it's removed in place, it would also need emptying and cleaning prior to its removal. I told her I sent Allan Hoffman a letter on Friday explaining how to proceed. bf 10/31/07 On 10/12/07, received letter from A. Hoffman. They are in the process of locating a company to do the repair work. They only fill the tank half full and that was the approximate level at which the test was performed. Leak is a dry leak. he will be having surgery on 10/16 and will be recovering two weeks after that. bf 11/8/07 Received call from A.

CORNELL BEVERAGES INC (Continued) **U000394301**

Hoffman. He requested a list of contractors to repair tank. I faxed him the list and disclaimer. Fax:718-381-3001. bf 4/11/08 received letter from Allan Hoffman of Cornell. Fill box was replaced by Empire Fuel and the work order was attached. Passing tank test results were also attached. 10/15/08 Informed by Alan Hoffman that fill box is above ground so any spills would be visible. bf"

Remarks: "PBS No: 2-069787 "

All TTF:

Facility ID:	0706869
Spill Number:	0706869
Spill Tank Test:	1764122
Site ID:	387468
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	387468
Operable Unit ID:	1144670
Operable Unit:	01
Material ID:	2134979
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	CORNELL BEVERAGES
Address:	105 HARRISON PLACE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9610865 / 2008-10-17
Facility ID:	9610865
Site ID:	92955
Spill Date:	1996-12-03
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1996-12-03

CORNELL BEVERAGES INC (Continued) **U000394301**

CID:	266
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-03
Spill Record Last Update:	2008-10-22
Spiller Name:	ALLAN HOFFMAN
Spiller Company:	CORNELL BEVERAGES
Spiller Address:	105 HARRISON PLACE
Spiller County:	001
Spiller Contact:	ALLAN HOFFMAN
Spiller Phone:	(718) 381-3000
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	83354
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN 6/30/97 - sent letter 06/16/06: This spill is transferred from Mike Mulqueen to Mr. Koon Tang. 10/17/08 This case is being closed partly because of lack of information. Tank passed subsequent tests. Property owner, Allan hoffman states in 10/17/08 letter that vent pipe was the cause of failure. He has no other information. bf"
Remarks:	"SPILLER TO BE NOTIFIED. FURTHER TESTING UP TO SPILLER."

All TTF:

Facility ID:	9610865
Spill Number:	9610865
Spill Tank Test:	1544907
Site ID:	92955
Tank Number:	Not reported
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	92955
Operable Unit ID:	1038767
Operable Unit:	01
Material ID:	343084
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

CORNELL BEVERAGES INC (Continued) **U000394301**

Recovered: .00
Oxygenate: Not reported

UST:
Name: CORNELL BEVERAGES INC
Address: 105 HARRISON PLACE
City,State,Zip: BROOKLYN, NY 11237
Id/Status: 2-069787 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 01/14/2022
UTM X: 590446.68782
UTM Y: 4506770.24224
Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:
Site Id: 1507
Affiliation Type: Mail Contact
Company Name: CORNELL BEVERAGES INC
Contact Type: VICE PRESIDENT
Contact Name: ALLAN HOFFMAN
Address1: 105 HARRISON PLACE
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11237
Country Code: 001
Phone: (718) 381-3000
EMail: ALLAN@CORNELLBEV.COM
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2017-03-06

Site Id: 1507
Affiliation Type: Facility Operator
Company Name: CORNELL BEVERAGES INC
Contact Type: Not reported
Contact Name: ALLAN HOFFMAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 381-3000
EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 2006-11-01

Site Id: 1507
Affiliation Type: Emergency Contact
Company Name: CORNELL BEVERAGES INC
Contact Type: Not reported
Contact Name: ALLAN HOFFMAN

CORNELL BEVERAGES INC (Continued) **U000394301**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 381-3000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2006-11-01

Site Id:	1507
Affiliation Type:	Facility Owner
Company Name:	STHM REALTY CORP
Contact Type:	VICE PRESIDENT
Contact Name:	ALLAN HOFFMAN
Address1:	105 HARRISON PLACE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11237
Country Code:	001
Phone:	(718) 381-3000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-03-06

Tank Info:

Tank Number:	001
Tank ID:	2581
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	3000
Install Date:	01/01/1960
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	99
Date Test:	12/22/2016
Next Test Date:	12/22/2017
Pipe Model:	Not reported
Modified By:	TankSys
Last Modified:	04/27/2020

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

CORNELL BEVERAGES INC (Continued) **U000394301**

I04 - Overfill - Product Level Gauge (A/G)
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
I05 - Overfill - Vent Whistle

---

231 **308 MAUJER ST** **NY LTANKS** **S105999626**
West **308 MAUJER ST** **N/A**
1/4-1/2 **BROOKLYN, NY**
0.393 mi.
2077 ft.

Relative: **Higher**

Actual: **29 ft.**

LTANKS:

Name:	308 MAUJER ST
Address:	308 MAUJER ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0305120 / 2006-01-31
Facility ID:	0305120
Site ID:	144741
Spill Date:	2003-08-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	JBLISTER
Referred To:	Not reported
Reported to Dept:	2003-08-14
CID:	216
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-08-14
Spill Record Last Update:	2006-01-31
Spiller Name:	Not reported
Spiller Company:	FRED GELFAR
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FRED GELFAR
Spiller Phone:	(516) 455-4775
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	123363
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND Will send a TTF as soon as RP provides a proper mailing address 8/19/2003 TTF Letter sent to: Fred Gelfar 2941 Charlotte Drive Merrick, NY 11566 1/31/06 Received copy of 10/04/04 tightness report showing tank passed. Closed spill out based on report. J Lister"
Remarks:	"TANK TEST FAILURE THEY WILL RETEST "

308 MAUJER ST (Continued) **S105999626**

All TTF:

Facility ID:	0305120
Spill Number:	0305120
Spill Tank Test:	1528589
Site ID:	144741
Tank Number:	1
Tank Size:	2000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

AM232 **NATIONWIDE SCRAP LLC** **NY SWRCY** **S116357466**
ESE **18-19 FLUSHING AVENUE** **N/A**
1/4-1/2 **RIDGEWOOD, NY 11385**
0.404 mi.
2132 ft. **Site 2 of 2 in cluster AM**

Relative:
Higher

Actual:
24 ft.

SWRCY:

Name:	NATIONWIDE SCRAP LLC
Address:	18-19 FLUSHING AVENUE
City,State,Zip:	RIDGEWOOD, NY 11385
Region:	2
Facility Address 2:	Not reported
Phone Number:	5167757922
Owner Type:	Private
Owner Name:	Nationwide Scrap LLC
Owner Address:	18-19 Flushing Ave
Owner Address 2:	Not reported
Owner City,St,Zip:	Ridgewood, NY 11385
Owner Email:	Not reported
Owner Phone:	7182335069
Contact Name:	Margaret Ferrante
Contact Address:	Not reported
Contact Address 2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	nationwidescrap@yahoo.com
Contact Phone:	7182335069
Activity Desc:	RHRF - registration
Activity Number:	[41MA7]
Active:	No
East Coordinate:	591145
North Coordinate:	4507293
Accuracy Code:	Not reported
Regulatory Status:	Registration
Permit #:	41MA7
Auth. Date:	Not reported
Expiration Date:	Not reported
Waste Types:	Source Separated Recyclables (Metal/Glass/Paper/Plastic);Commingled

NATIONWIDE SCRAP LLC (Continued) **S116357466**

Paper;Paper / Cardboard;Office Paper;PET;Plastics
Operator Name: Not reported
Operator Type: Not reported
Last Date: 12/12/2016

233
SSW
1/4-1/2
0.406 mi.
2143 ft.

KORNBLUM, SIDNEY
394 JOHNSON AVE.
BROOKLYN, NY 11206

SEMS-ARCHIVE **1018149164**
LEAD SMELTERS **NYN000206627**

Relative:
Higher

Actual:
19 ft.

SEMS Archive:
Site ID: 0206627
EPA ID: NYN000206627
Name: KORNBLUM, SIDNEY
Address: 394 JOHNSON AVE.
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11206
Cong District: Not reported
FIPS Code: 36047
FF: N
NPL: Not on the NPL
Non NPL Status: Referred to Removal - NFRAP

SEMS Archive Detail:
Region: 02
Site ID: 0206627
EPA ID: NYN000206627
Site Name: KORNBLUM, SIDNEY
NPL: N
FF: N
OU: 00
Action Code: HX
Action Name: PRE-CERC
SEQ: 1
Start Date: 2012-10-19 04:00:00
Finish Date: 2012-10-19 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 02
Site ID: 0206627
EPA ID: NYN000206627
Site Name: KORNBLUM, SIDNEY
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 2014-05-16 05:00:00
Finish Date: 2014-05-16 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0206627
EPA ID: NYN000206627

KORNBLUM, SIDNEY (Continued) **1018149164**

Site Name:	KORNBLUM, SIDNEY
NPL:	N
FF:	N
OU:	00
Action Code:	HX
Action Name:	PRE-CERC
SEQ:	3
Start Date:	2014-05-16 05:00:00
Finish Date:	2014-05-16 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206627
EPA ID:	NYN000206627
Site Name:	KORNBLUM, SIDNEY
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	2014-10-16 05:00:00
Finish Date:	2014-10-16 05:00:00
Qual:	H
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206627
EPA ID:	NYN000206627
Site Name:	KORNBLUM, SIDNEY
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	2014-10-01 05:00:00
Finish Date:	2015-03-31 05:00:00
Qual:	N
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206627
EPA ID:	NYN000206627
Site Name:	KORNBLUM, SIDNEY
NPL:	N
FF:	N
OU:	00
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	1
Start Date:	2014-10-30 04:00:00
Finish Date:	2016-11-23 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

KORNBLUM, SIDNEY (Continued) **1018149164**

Lead Smelter Sites:

Site ID:	206627
Facility Region Id:	2
Latitude:	Not reported
Longitude:	Not reported
CoC Ind:	Not reported
Contaminant Name:	Not reported
FF Ind:	N
NAI:	N
Non-Primary Site-Sub Type:	Not reported
NPL:	Not on the NPL
Primary Site-Sub Type:	Metal fabrication/finishing/coating and allied industries (Manufacturing/Processing/Maintenance)
Special Initiative:	Unrecognized Smelter per 2001 Report

AN234 **MS POWER INC** **NY SWF/LF** **S108146009**
NW **187 MASPETH VE** **N/A**
1/4-1/2 **BROOKLYN, NY 11211**
0.422 mi.
2229 ft. **Site 1 of 3 in cluster AN**

Relative: **Higher**
Actual: **18 ft.**

SWF/LF:

Name:	MS POWER INC
Address:	187 MASPETH VE
City,State,Zip:	BROOKLYN, NY 11211
Flag:	INACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	Not reported
Active:	No
East Coordinate:	589950
North Coordinate:	4507862
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

AN235
NW
1/4-1/2
0.422 mi.
2229 ft.

MAGNUM BODY SHOP INC
185A MASPETH AVE
BROOKLYN, NY 11211

Site 2 of 3 in cluster AN

NY SWF/LF **S107785410**
N/A

Relative:
Higher

Actual:
18 ft.

SWF/LF:

Name:	MAGNUM BODY SHOP INC
Address:	185A MASPETH AVE
City,State,Zip:	BROOKLYN, NY 11211
Flag:	INACTIVE
Region Code:	2
Phone Number:	7183029792
Owner Name:	Bart Buchman
Owner Type:	Private
Owner Address:	185A Maspeth Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Email:	bartautosmart@yahoo.com
Owner Phone:	7184153315
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[7091251]
Active:	No
East Coordinate:	589945
North Coordinate:	4507859
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

236
SSW
1/4-1/2
0.430 mi.
2271 ft.

U. S. WASTE MANAGEMENT; INC.
48 KNICKERBOCKER (69 INGRAHAM ST)
BROOKLYN, NY 11237

NY SWF/LF **S105841758**
N/A

Relative:
Higher

Actual:
22 ft.

SWF/LF:

Name:	U. S. WASTE MANAGEMENT; INC.
Address:	48 KNICKERBOCKER (69 INGRAHAM ST)
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	7188212422
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported

U. S. WASTE MANAGEMENT; INC. (Continued) **S105841758**

Owner Phone:	Not reported
Contact Name:	PETER SANTOS; PRESIDENT
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[24TA4]
Active:	No
East Coordinate:	590400
North Coordinate:	4506700
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	2-6104-00176
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

AN237 **BUG, EQUITY WORKS** **NY HSWDS** **S102872851**
WNW **MASPETH AND MORGAN AVENUES** **N/A**
1/4-1/2 **BROOKLYN, NY 11222**
0.434 mi.
2289 ft. **Site 3 of 3 in cluster AN**

Relative:
Higher

Actual:
18 ft.

HSWDS:

Facility ID:	HS2009
Region:	2
Facility Status:	Unknown
Owner Type:	Publ Utily
Owner:	(formerly) Brooklyn Union Gas
Owner Address:	195 Montague Street
Owner Phone:	(718)403-3053
Operator Type:	Unknown
Operator:	Unknown
Operator:	Unknown
Operator Phone:	Unknown
EPA ID:	NYD980532048
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	Unknown
RCRA Permitted:	Unknown
Site Code:	Coal Gasification Plant
Owner City State:	Brooklyn
Operator City State:	Not reported
Quadrange:	Unknown
Latitude:	40 43 00 N
Longitude:	73 56 15 W
Acres:	0.00
Operator Date:	1896
Close Date:	1928
Completed:	PA
Active:	No
PCB's Disposed:	Unknown
Pesticides Disposed:	No
Metals Disposed:	No

BUG, EQUITY WORKS (Continued) **S102872851**

Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	Environmental
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown
Groundwater Contamination:	Unknown
Groundwater Classification:	Unknown
Drinking Water Contamination:	Unknown
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	Unknown
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	Unknown
Ambient Air Contamination:	Unknown
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	Unknown
Inventory:	Not reported
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	Not reported
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

AO238 **UNIVERSAL SCRAP PROCESSORS CORP** **NY SWF/LF** **S111072463**
SSE **27 STEWART AVE** **NY Spills** **N/A**
1/4-1/2 **BROOKLYN, NY 11237** **NY SPDES**
0.441 mi.
2329 ft. **Site 1 of 2 in cluster AO**

Relative:
Higher

Actual:
17 ft.

SWF/LF:

Name:	UNIVERSAL SCRAP PROCESSORS CORP
Address:	27 STEWART AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	7183812234
Owner Name:	Universal Scrap Processors Corp
Owner Type:	Private
Owner Address:	27 Stewart Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11237
Owner Email:	universalscrapprocessor@gmail.com
Owner Phone:	7183812234
Contact Name:	James Ruggiero
Contact Address:	27 Steward Avenue
Contact Addr2:	Not reported
Contact City,St,Zip:	Brooklyn, NY 11237
Contact Email:	universalscrapprocessors@gmail.com
Contact Phone:	7183812234
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[7106524]
Active:	No
East Coordinate:	590778
North Coordinate:	4506792
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Universal Scrap Processors Corp
Operator Type:	Private
Laste Date:	Not reported

SPILLS:

Name:	UNIVERSAL SCRAP PROCESSOR
Address:	27 STEWART AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1305242 / 2017-10-05
Facility ID:	1305242
Facility Type:	ER
DER Facility ID:	440924
Site ID:	485801
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	2401
Spill Date:	2013-08-14
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2013-08-14
CID:	Not reported

UNIVERSAL SCRAP PROCESSORS CORP (Continued) **S111072463**

Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-08-14
Spill Record Last Update:	2017-10-05
Spiller Name:	NORMAN TEICLER
Spiller Company:	UNIVERSAL SCRAP PROCESSOR
Spiller Address:	27 STEWART AVE
Spiller Company:	999
Contact Name:	NORMAN TEICLER
DEC Memo:	"4/4/16 - See BCP C224210, K. Forster, PM. Spill to remain open until BCP complete. 10/5/17 TJD Site inspection. The former junk yard operating at this address is no longer in business. All structures have been removed from the property and the parcel is now vacant. As per above note this site is in the BCP program which is being managed by Central Office DER staff. Following the inspection, DeMeo (R2) contacted Forster (CO) regarding this reported housekeeping condition at a former junk yard site - based upon staff discussions the following decision has been made. Spill 1305242 is closed and cross-referenced to spill 0510000. CO DER staff will manage both the spill and BCP project simultaneously. "
Remarks:	"sheen noted on water, c/u pending, DEC Inspection"

All Materials:

Site ID:	485801
Operable Unit ID:	1235458
Operable Unit:	01
Material ID:	2234716
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.25
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

SPDES:

Name:	UNIVERSAL SCRAP PROCESSORS CORP
Address:	27 STEWART AVE
City,State,Zip:	BROOKLYN, NY 11237
Permit Number:	NYR00E020
State-Region:	02
Expiration Date:	09/30/2017
Current Major Minor Status:	Minor
Primary Facility SIC Code:	5093
State Water Body Name:	ENGLISH KILLS
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	Not reported

UNIVERSAL SCRAP PROCESSORS CORP (Continued) **S111072463**

Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	+40.706 / -73.925
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	TABS CONSULTING GROUP INC
Non-Gov Permit Street Address:	UNIVERSAL SCRAP PROCESSORS CORP
Non-Gov Permit Supplemental Location:	2 52ND ST, BOX B11
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11232
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	UNIVERSAL SCRAP PROCESSORS CORP
Non-Gov Facility Street Address:	UNIVERSAL SCRAP PROCESSORS CORP
Non-Gov Facility Supplemental Location:	27 STEWART AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11237
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	UNIVERSAL SCRAP PROCESSORS CORP
Address:	27 STEWART AVE
City,State,Zip:	BROOKLYN, NY 11237
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	UNIVERSAL SCRAP PROCESSORS CORP
Non-Gov Permit Street Address:	27 STEWART AVE
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	BROOKLYN
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11237
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	UNIVERSAL SCRAP PROCESSORS CORP
Non-Gov Facility Street Address:	UNIVERSAL SCRAP PROCESSORS CORP
Non-Gov Facility Supplemental Location:	27 STEWART AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11237
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported

UNIVERSAL SCRAP PROCESSORS CORP (Continued) **S111072463**

Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Name:	UNIVERSAL SCRAP PROCESSORS CORP
Address:	27 STEWART AVE
City,State,Zip:	BROOKLYN, NY 11237
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY047
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	UNIVERSAL SCRAP PROCESSORS CORP
Non-Gov Facility Street Address:	UNIVERSAL SCRAP PROCESSORS CORP
Non-Gov Facility Supplemental Location:	27 STEWART AVE
Non-Gov Facility City:	BROOKLYN
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11237
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

239
East
1/4-1/2
0.443 mi.
2341 ft.

47-40 METROPOLITAN AVE **NY LTANKS** **S101658341**
47-40 METROPOLITAN AVE **N/A**
QUEENS, NY

Relative:
Higher

Actual:
18 ft.

LTANKS:

Name:	47-40 METROPOLITAN AVE
Address:	47-40 METROPOLITAN AVE
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9502665 / 2000-07-21
Facility ID:	9502665
Site ID:	330742
Spill Date:	1995-06-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1995-06-01

47-40 METROPOLITAN AVE (Continued) **S101658341**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-06-16
Spill Record Last Update:	2000-07-21
Spiller Name:	MS CAROLE LEISTMAN
Spiller Company:	CHEMICAL BANK, FIDUCIARY
Spiller Address:	270 PARK AVENUE, 20TH FL
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	266022
DEC Memo:	""
Remarks:	"ON CONCRETE FLOOR - SMALL LEAK - FAILED AIR TEST"

All TTF:

Facility ID:	9502665
Spill Number:	9502665
Spill Tank Test:	1543880
Site ID:	330742
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	330742
Operable Unit ID:	1013891
Operable Unit:	01
Material ID:	367723
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AP240 **M & C TRANSFER STATION;INC.** **NY SWF/LF** **S105841784**
NE **58-26 47 STREET** **N/A**
1/4-1/2 **WEST MASPETH, NY 11378**
0.445 mi.
2352 ft. **Site 1 of 3 in cluster AP**

Relative: **Lower**
Actual: **7 ft.**

SWF/LF:

Name:	M & C TRANSFER STATION;INC.
Address:	58-26 47 STREET
City,State,Zip:	WEST MASPETH, NY 11378
Flag:	INACTIVE
Region Code:	2
Phone Number:	7184175185
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	THONY MESSINA
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[41T42]
Active:	No
East Coordinate:	591000
North Coordinate:	4508800
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	2-6304-00157
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

AP241 **NMS WASTE PAPER** **NY SWRCY** **S105842307**
NE **58-35 47TH STREET** **NY Spills** **N/A**
1/4-1/2 **MASPETH, NY 11378**
0.452 mi.
2384 ft. **Site 2 of 3 in cluster AP**

Relative: **Lower**
Actual: **13 ft.**

SWRCY:

Name:	NMS WASTE PAPER
Address:	58-35 47TH STREET
City,State,Zip:	MASPETH, NY 11378
Region:	2
Facility Address 2:	Not reported
Phone Number:	7183811319
Owner Type:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner Address 2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported

NMS WASTE PAPER (Continued) **S105842307**

Owner Phone:	Not reported
Contact Name:	MICHAEL J. SINISI
Contact Address:	Not reported
Contact Address 2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	RHRF - registration
Activity Number:	[41M13]
Active:	No
East Coordinate:	591200
North Coordinate:	4508400
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Permit #:	2-6304-00296
Auth. Date:	8/21/1992
Expiration Date:	8/21/1997
Waste Types:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Last Date:	Not reported

SPILLS:

Name:	WASTE PAPER REMOVAL COMPA
Address:	58-35 47TH STREET
City,State,Zip:	MASPETH QUEENS, NY
Spill Number/Closed Date:	0404192 / 2005-01-31
Facility ID:	0404192
Facility Type:	ER
DER Facility ID:	229102
Site ID:	282212
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	4101
Spill Date:	2004-07-19
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2004-07-19
CID:	408
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-19
Spill Record Last Update:	2005-02-01
Spiller Name:	JOEL ADRIAN
Spiller Company:	SHOCK WOODFORD COMPANY
Spiller Address:	5 WEST MAIN ST SUITE 109
Spiller Company:	001
Contact Name:	JOEL ADRIAN
DEC Memo:	"12/23/04 Tipple updating//all prior notes lost in database// Tipple

NMS WASTE PAPER (Continued) **S105842307**

has conducted two site visits, the last of which was 12/22 PM. There had been a machinery problem in the recycling facility which required the excavation of a large area of the floor. Tipple met with Joel Adrian of the Jacques Whitford company to conduct a visual/ olfactory inspection of the excavation. The excavation was approximately 20-25' long by 10-12' wide and extended about 6 foot below the floor surface. The excavation revealed no visual, olfactory /PID evidence of petroleum products, what the excavation did reveal was broken brick, some concrete, glass and what I observed to be clean brown soil. Jacques Whitford will grab one sample from this excavation and advance two geoprobe borings to groundwater and collect samples from the soil/water interface. The results of the three above described samples will be used to determine weather any additional actions will be required. 12/29/04 tipple delivering a STIP and CAP to the site while the two additional borings are being advanced. Upon arrival at the site, the Rig was too large to maneuver through the available space, the additional borings have been tentatively rescheduled for next Tuesday Jan. 4, 05 1/31/05 reviewed submission, discussed with DEC Attorney Nehila, Oliva & Nehila ok with closing if data is ok. Data has some SVOC exceedances which can be associated with the broken asphalt pieces in the urban fill material which I witnessed in the excavation. NFA letter written including a caveat which reads if excavation is to proceed, a health and safety plan must be followed. "
Not reported
Remarks: "11/18/04 site mtg. with contractor, purchaser, and agent. Discussed the future actions necessary to attain a NFA."

All Materials:
Site ID: 282212
Operable Unit ID: 887419
Operable Unit: 01
Material ID: 488202
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported

AP242 **GPB WASTE NY DBA NY/NJ RECYCLING (FORMERLY RAPID P** **NY SWRCY** **S120839218**
NE **58-35 47TH STREET** **N/A**
1/4-1/2 **MASPETH, NY 11378**
0.452 mi.
2384 ft. **Site 3 of 3 in cluster AP**

Relative: **Lower**
Actual: **13 ft.**

SWRCY:
Name: GPB WASTE NY DBA NY/NJ RECYCLING (FORMERLY RAPID PROCESSING)
Address: 58-35 47TH STREET
City,State,Zip: MASPETH, NY 11378
Region: 2
Facility Address 2: Not reported
Phone Number: 7183490500
Owner Type: Private
Owner Name: GPB Waste NY LLC
Owner Address: 535 West 24th Street

GPB WASTE NY DBA NY/NJ RECYCLING (FORMERLY RAPID PROCESSING) (Continued) **S120839218**

Owner Address 2:	Not reported
Owner City,St,Zip:	New York, NY 10011
Owner Email:	Not reported
Owner Phone:	2122352650
Contact Name:	Jose Ortiz
Contact Address:	Not reported
Contact Address 2:	Not reported
Contact City,St,Zip:	NY
Contact Email:	jose@rapidprocessingllc.com
Contact Phone:	7183490500
Activity Desc:	RHRF - registration
Activity Number:	[41M13]
Active:	Yes
East Coordinate:	591077
North Coordinate:	4507948
Accuracy Code:	Not reported
Regulatory Status:	Registration
Permit #:	41M13
Auth. Date:	Not reported
Expiration Date:	Not reported
Waste Types:	Commingled Paper;Paper / Cardboard
Operator Name:	Not reported
Operator Type:	Not reported
Last Date:	1/10/2017

AQ243 **18-51 FLUSHING AVE/QUEENS** **NY LTANKS** **S100146969**
East **18-51 FLUSHING AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.454 mi.
2396 ft. **Site 1 of 2 in cluster AQ**

Relative: **Higher**
Actual: **25 ft.**

LTANKS:

Name:	18-51 FLUSHING AVE/QUEENS
Address:	18-51 FLUSHING AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9100841 / 2003-03-06
Facility ID:	9100841
Site ID:	268451
Spill Date:	1991-04-22
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1991-04-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-04-23
Spill Record Last Update:	2003-03-06
Spiller Name:	Not reported

18-51 FLUSHING AVE/QUEENS (Continued) **S100146969**

Spiller Company:	FRITO-LAY
Spiller Address:	7701 LEGACY DRIVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	218683
DEC Memo:	""
Remarks:	"TANK PULL,OLD TANK FROM 70'S, DISCOVERED HOLES IN BOTTOM OF TANK,SHEENON WATER IN EXCAVATION,FRANKLIN CO IS DOING EXCAVATION WORK."

All Materials:

Site ID:	268451
Operable Unit ID:	952122
Operable Unit:	01
Material ID:	427009
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AO244 **FORMER UNIVERSAL SCRAP METAL PROCESSORS CORP.** **NY BROWNFIELDS S117394468**
SSE **1181 FLUSHING AVENUE** **NY Spills N/A**
1/4-1/2 **BROOKLYN, NY 11237**
0.458 mi.
2417 ft. **Site 2 of 2 in cluster AO**

Relative:
Higher

Actual:
18 ft.

BROWNFIELDS:

Name:	FORMER UNIVERSAL SCRAP METAL PROCESSORS CORP.
Address:	1181 FLUSHING AVENUE
City,State,Zip:	BROOKLYN, NY 11237
Program:	BCP
Site Code:	505316
Acres:	0.502
HW Code:	C224210
SWIS:	2401
Town:	New York City
Record Added Date:	03/10/2015
Record Updated Date:	01/06/2021
Update By:	SMQUANDT
Site Description:	"Location: The Former Universal Scrap Metal Processors Corp. site is located in an urban area in the East Williamsburg neighborhood of Brooklyn, Kings County. The irregularly-shaped site has approximately 109 feet of street frontage on Flushing Avenue and 203 feet of street frontage on Stewart Avenue. Site Features: The property was partially developed with a 1-story 4,500 square foot commercial building which was constructed in 1931, but demolished in 2016. The site is currently vacant, surrounded by a fence and unpaved. Current Zoning and Land Use: The site is located in a M1-2 zone which allows nearly all industrial type uses. Additional uses are allowed, including office, hotel, and retail. M1 districts are often buffers between M2

FORMER UNIVERSAL SCRAP METAL PROCESSORS CORP. (Continued) **S117394468**

or M3 districts and adjacent residential or commercial districts. The scrap metal operation which previously occupied the building and property no longer operates. Past Use of the Site: The entire property was used as a railroad freight yard from sometime between 1888 and 1907 to sometime between 1951 and 1965. The south end of the site was utilized as a filling station from approximately 1955 until at least 2003. The southern portion of the site and the building were used for auto repair from 1955 until 2007. The northern portion of the property was used as an auto scrap yard from 1981 through 2007. From 2007 through 2014 the property was used as a scrap metal facility. In January 2006, under Spill #0510000, eleven (11) 550-gallon gasoline underground storage tanks (USTs) and 240 tons of petroleum-impacted soil were removed, and a chemical oxidant was applied to treat groundwater. Site Geology and Hydrogeology: Soil at the site is described as historic fill to a depth of approximately 4 feet below the surface followed by native brown fine sand with silt. The bedrock in this area of Brooklyn is an igneous intrusive classified as the Ravenswood grano-diorite of middle Ordovician to middle Cambrian age. Bedrock was not encountered during the remedial investigation, but is anticipated to reside at depths greater than 100 feet below grade. Unconsolidated sediments overlie the bedrock and consist of Pleistocene aged sand, gravel and silty clays, deposited by glacial-fluvial activity. Non-native fill materials consisting of dredge spoils, rubble and/or other materials have historically been used to reinforce and extend shoreline areas and to raise and improve the drainage of low lying areas. Depth to groundwater at the site is approximately 12 feet below grade and flows to the north/ northeast, toward the English Kills Channel. Groundwater flow is also highly variable as it may be influenced by the subway tunnel which runs underground north of the site."

Env Problem:

"Site soils and groundwater have been analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, pesticides and poly chlorinated biphenyls (PCBs). Soil vapor has been analyzed for VOCs. Soil: Several VOCs have been detected in site soils, primarily petroleum constituents including 1,2,4-trimethylbenzene at concentrations up to 910 parts per million (ppm) (Unrestricted Use Soil Cleanup Objective (UUSCO) is 3.6 ppm), 1,3,5-trimethylbenzene up to 320 ppm (UUSCO is 8.4), benzene up to 1.9 ppm (UUSCO is 0.06 ppm), ethylbenzene up to 190 ppm (UUSCO is 1 ppm), n-propylbenzene up to 140 ppm (UUSCO is 3.9 ppm), n-butylbenzene up to 70 ppm (UUSCO is 12 ppm), sec-butylbenzene up to 23 ppm (UUSCO is 11 ppm), m-p-xylenes up to 720 ppm (UUSCO is 0.26 ppm), o-xylene up to 260 ppm (UUSCO is 0.26 ppm), toluene up to 20 ppm (UUSCO is 0.7 ppm), and naphthalene up to 17 ppm (UUSCO is 12 ppm). Chlorinated volatile organic compounds (CVOCs) were detected at two locations, including tetrachloroethene at concentrations up to 22 ppm (UUSCO is 1.3 ppm), cis-1,2-dichloroethene up to 27 ppm (UUSCO is 0.25 ppm), trans-1,2-dichloroethene up to 2.3 ppm (UUSCO is 0.19), and vinyl chloride up to 3 ppm (UUSCO is 0.02 ppm). Several Polycyclic aromatic hydrocarbons (PAHs) were also detected in shallow subsurface soils, including benzo(a)anthracene at concentrations up to 1.5 ppm (UUSCO is 1 ppm), benzo(a)pyrene up to 1.1 ppm (UUSCO is 1 ppm), indeno(1,2,3-cd)pyrene up to 0.72 ppm (UUSCO is 0.5 ppm), benzo(b)fluoranthene up to 1.1 ppm (UUSCO is 1 ppm), benzo(k)fluoranthene up to 0.9 ppm (UUSCO is 0.8 ppm), and chrysene up to 1.6 ppm (UUSCO is 1 ppm). Metals, including mercury were detected at concentrations up to 1.57 ppm (UUSCO is 0.18 ppm), barium

FORMER UNIVERSAL SCRAP METAL PROCESSORS CORP. (Continued) **S117394468**

up to 446 ppm (UUSCO is 350 ppm), cadmium up to 7.67 ppm (UUSCO is 2.5 ppm), copper up to 266 ppm (UUSCO is 50 ppm), lead up to 754 ppm (UUSCO is 63 ppm), and zinc up to 1,100 ppm (UUSCO is 109 ppm). Groundwater: Several petroleum-related VOCs were detected in site groundwater including 1,2,4-trimethylbenzene up to 1,400 parts per billion (ppb) (NYSDEC groundwater quality standard is 5 ppb), 1,3,5-trimethylbenzene up to 400 ppb (standard is 5 ppb), benzene up to 380 ppb (standard is 1 ppb), ethylbenzene up to 940 ppb (standard is 5 ppb), isopropylbenzene up to 79 ppb (standard is 5 ppb), m-p-xylenes up to 3,700 ppb (standard is 5 ppb), methyl ethyl ketone up to 780 ppb (standard is 50 ppb), MTBE up to 66 ppb (standard is 10 ppb), naphthalene up to 250 ppb (standard is 10 ppb), n-butylbenzene up to 20 ppb (standard is 5 ppb), sec-butylbenzene up to 13 ppb (standard is 5 ppb), n-propylbenzene up to 200 ppb (standard is 5 ppb), o-xylene up to 1,500 ppb (standard is 5 ppb), and toluene up to 1,100 ppb (standard is 5 ppb). Minor detections of CVOCs were also found, including tetrachloroethene at concentrations up to 8.1 ppb (standard is 5 ppb), and trichloroethene up to 7.4 ppb (standard is 5 ppb). Metals were also detected in site groundwater, including lead at concentrations up to 59 ppb (standard is 25 ppb), barium up to 1,330 ppb (standard is 1,000 ppb), cadmium up to 18 ppb (standard is 5 ppb), magnesium up to 95,100 ppb (standard is 35,000 ppb), manganese up to 44,800 ppb (standard is 300 ppb), sodium up to 343,000 ppb (standard is 20,000 ppb), and iron up to 868,000 ppb (standard is 300 ppb). The manganese, magnesium, and sodium is believed to be naturally-occurring. PCB-1016 was also detected at 0.16 ppb (standard is 0.09 ppb). Soil Vapor: In soil gas, several CVOCs were detected, including tetrachloroethene up to 34.3 micrograms per cubic meter (ug/m^3), trichloroethene up to 11.3 ug/m^3, cis-1,2-dichloroethene up to 109 ug/m^3, and vinyl chloride up to 2,530 ug/m^3. Benzene was detected up to 1,140 ug/m^3."

Health Problem: "The site is completely fenced, which restricts public access. However, persons who enter the site could contact contaminants in the soil by walking on the site, digging or otherwise disturbing the soil. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater and soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site redevelopment and occupancy. Additional evaluation is needed to determine whether actions are needed to address soil vapor intrusion off-site."

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported

FORMER UNIVERSAL SCRAP METAL PROCESSORS CORP. (Continued) **S117394468**

Updated By:	Not reported
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Public Library- Bushwick Branch
Owner Address:	340 Bushwick Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Dawson Stellberger
Owner Company:	25C LLC
Owner Address:	249 Smith Street
Owner Addr2:	#140
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Yoel Schwimmer
Owner Company:	flushing stewart LLC
Owner Address:	12 Spencer STreet
Owner Addr2:	2nd Floor
Owner City,St,Zip:	Brooklyn, NY 11205
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Abe Wurzberger
Owner Company:	Flushing Stewart LLC
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 4
Owner Address:	1420 Bushwick Ave
Owner Addr2:	Rm 370
Owner City,St,Zip:	Brooklyn, NY 11237
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dawson Stellberger
Owner Company:	25C LLC
Owner Address:	249 Smith Street
Owner Addr2:	#140
Owner City,St,Zip:	Brooklyn, NY 11231
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board 1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America

FORMER UNIVERSAL SCRAP METAL PROCESSORS CORP. (Continued) **S117394468**

HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	COMMERCIAL PROPERTY
Address:	1181 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1410058 / Not Reported
Facility ID:	1410058
Facility Type:	ER
DER Facility ID:	458645
Site ID:	503722
DEC Region:	2
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	2401
Spill Date:	2015-01-14
Investigator:	AXDORONO
Referred To:	BROWNFIELD PROGRAM. PM IN ALBANY
Reported to Dept:	2015-01-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2015-01-14
Spill Record Last Update:	2017-06-29
Spiller Name:	Not reported
Spiller Company:	COMMERCIAL PROPERTY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CHARLIE SOSIK
DEC Memo:	"1/14/2015 - Feng - Duty Desk. Left call back information to the receptionist at EBC (631-504-6000) and asked Charles Sosik to call back. 3/30/2016 Feng This spill is transferred from J. Feng to V. Brevdo as per J. Vought. 03/31/2016: This spill case was transferred to A. Doronova. - AD 05/20/2016: called and left a message for Mr. Sosik with the receptionist. AD 09/20/2016: Called and left a message to Mr. Sosik with the receptionist. AD 09/29/2016: Looked for the owner information on the Internet. Found records saying that Riverside Developers USA is the property owner. called and spoke with the receptionist. Her name is Rachel Mittelman. She informed me that they are longer involved with this property. She will find out the new owner info. AD 09/30/2016: Received a phone call from Joe

FORMER UNIVERSAL SCRAP METAL PROCESSORS CORP. (Continued) **S117394468**

Greenfeld. He was referred by Ms. Mittelman. He is representative of the new owner of the site. The company name is All Year Management. Phone numbers: (718)623-9430, ext.111, 110,989; (917)-470-3650. He said that they will retain Mr. Sosik's company to deal with this spill. He will gather more info and get back. AD 01/19/2017: Called and left a message for Mr. Greenfeld regarding update info. Later in the day received a call from Mr. Greenfeld. He said that they still work with Mr. Sosik on the site remediation, and that a work plan will be submitted to DEC shortly. AD 06/29/2017: Called and spoke with Charlie Sosik. He informed me that this site is in Brownfield Program and is managed by Albany. He will sent an e-mail with info. AD"

Remarks: "contamination based on sample results"

All Materials:

Site ID:	503722
Operable Unit ID:	1253072
Operable Unit:	01
Material ID:	2255271
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

---

245 NNE 1/4-1/2 0.467 mi. 2465 ft. **TRANSCON LINES TERMINAL** **NY LTANKS** **1000693502**
430 MASPETH AVE **NY UST** **NYD986995512**
BROOKLYN, NY 11211 **RCRA NonGen / NLR**
NY MANIFEST

Relative: Lower
Actual: 8 ft.

LTANKS:

Name:	430 MASPETH AVE.
Address:	430 MASPETH AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	9206929 / 1997-07-03
Facility ID:	9206929
Site ID:	260707
Spill Date:	1992-09-09
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1992-09-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True

TRANSCON LINES TERMINAL (Continued) **1000693502**

Remediation Phase:	0
Date Entered In Computer:	1992-09-18
Spill Record Last Update:	2003-06-06
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	212920
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 10/10/95: This is additional information about material spilled from the translation of the old spill file: CONTAMINATED SOIL. 7/3/97 - AUSTIN - REMEDIATION PROJECT DONE AND FINISHED WITH OXYGEN RELEASING COMPOUND BEING PLACED IN WELLS - NO FURTHER ACTION REQUIRED - NFA LETTER ISSUED 7/3/97 - CLOSE"
Remarks:	"DURING TANK REMOVAL U/G SOIL CONTAMINATED DISOV. STOCKPILED, SAMPLED, WILL DISPOSE AS NECESSARY- TRANS-CON BANKRUPT CALLER REPRESENTS HOLDING CO. MCLAREN HART WILL SEND ASSESSMENT TO AUSTIN"

All Materials:

Site ID:	260707
Operable Unit ID:	970698
Operable Unit:	01
Material ID:	407610
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-10.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

UST:

Name:	TRANSCON LINES
Address:	430 MASPETH AVENUE
City,State,Zip:	BROOKLYN, NY 11211
Id/Status:	2-016071 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	590565.30494
UTM Y:	4508073.53886
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	107
Affiliation Type:	Facility Owner
Company Name:	TRANSCON LINES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	430 MASPETH AVENUE
Address2:	Not reported

TRANSCON LINES TERMINAL (Continued) **1000693502**

City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 385-8800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JMKRIMGO
Date Last Modified:	2005-03-24

Site Id:	107
Affiliation Type:	Mail Contact
Company Name:	TRANSCON LINES
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	430 MASPETH AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11211
Country Code:	001
Phone:	(718) 385-8800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JMKRIMGO
Date Last Modified:	2005-03-24

Site Id:	107
Affiliation Type:	Facility Operator
Company Name:	TRANSCON LINES
Contact Type:	Not reported
Contact Name:	TRANSCON LINES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 388-8000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JMKRIMGO
Date Last Modified:	2005-03-24

Site Id:	107
Affiliation Type:	Emergency Contact
Company Name:	TRANSCON LINES
Contact Type:	Not reported
Contact Name:	JOHN WILEY, TERMINAL M ANAGER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 385-8800
EMail:	Not reported

TRANSCON LINES TERMINAL (Continued) **1000693502**

Fax Number: Not reported
Modified By: JMKRIMGO
Date Last Modified: 2005-03-24

Tank Info:

Tank Number: 001
Tank ID: 26929
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 08/01/1992
Date Tank Closed: 09/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 002
Tank ID: 26930
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 08/01/1992
Date Tank Closed: 09/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

TRANSCON LINES TERMINAL (Continued) **1000693502**

Equipment Records:
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number:	003
Tank ID:	26931
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	08/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number:	004
Tank ID:	26932
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	08/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel

TRANSCON LINES TERMINAL (Continued) **1000693502**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 005
Tank ID: 26933
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 08/01/1992
Date Tank Closed: 09/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 006
Tank ID: 26934
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 08/01/1992
Date Tank Closed: 09/01/1992

TRANSCON LINES TERMINAL (Continued) **1000693502**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 007
Tank ID: 26935
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 08/01/1992
Date Tank Closed: 09/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 008

TRANSCON LINES TERMINAL (Continued) **1000693502**

Tank ID:	26936
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	08/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number:	009
Tank ID:	26937
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	08/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

TRANSCON LINES TERMINAL (Continued) **1000693502**

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser

Tank Number: 010
Tank ID: 26938
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 08/01/1992
Date Tank Closed: 09/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number: 011
Tank ID: 26939
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: 08/01/1992
Date Tank Closed: 09/01/1992
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

TRANSCON LINES TERMINAL (Continued) **1000693502**

I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping

Tank Number:	012
Tank ID:	26940
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	08/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number:	013
Tank ID:	26941
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	08/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported

TRANSCON LINES TERMINAL (Continued) **1000693502**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

RCRA NonGen / NLR:

Date Form Received by Agency:	20070101
Handler Name:	TRANSCON LINES TERMINAL
Handler Address:	430 MASPETH AVE
Handler City,State,Zip:	BROOKLYN, NY 11211-1704
EPA ID:	NYD986995512
Contact Name:	Not reported
Contact Address:	MASPETH AVE
Contact City,State,Zip:	BROOKLYN, NY 11211
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	MASPETH AVE
Mailing City,State,Zip:	BROOKLYN, NY 11211
Owner Name:	L GUMPORT TURSTEE OF BANK
Owner Type:	Private
Operator Name:	L GUMPORT TURSTEE OF BANK
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

TRANSCON LINES TERMINAL (Continued) **1000693502**

Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL

TRANSCON LINES TERMINAL (Continued) **1000693502**

ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	L GUMPORT TURSTEE OF BANK
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	355 S GRAND AVE 40TH FL
Owner/Operator City,State,Zip:	LOS ANGELES, CA 90071-3101
Owner/Operator Telephone:	213-617-7070
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	L GUMPORT TURSTEE OF BANK
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	355 S GRAND AVE 40TH FL
Owner/Operator City,State,Zip:	LOS ANGELES, CA 90071-3101
Owner/Operator Telephone:	213-617-7070
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	L GUMPORT TURSTEE OF BANK
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	355 S GRAND AVE 40TH FL
Owner/Operator City,State,Zip:	LOS ANGELES, CA 90071-3101
Owner/Operator Telephone:	213-617-7070
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name:	TRANSCON LINES TERMINAL
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

TRANSCON LINES TERMINAL (Continued) **1000693502**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: TRANSCON LINES TERMINAL
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: TRANSCON LINES TERMINAL
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19930622
Handler Name: TRANSCON LINES TERMINAL
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: TRANSCON LINES

TRANSCON LINES TERMINAL (Continued) **1000693502**

Address:	430 MASPETH AVE
City,State,Zip:	BROOKLYN, NY 11211-1704
Country:	USA
EPA ID:	NYD986995512
Facility Status:	Not reported
Location Address 1:	430 MASPETH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11211
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986995512
Mailing Name:	TRANSCON LINES
Mailing Contact:	LAWRENCE V WILSON
Mailing Address 1:	10851 SUNSET PLAZA / RAMPICO
Mailing Address 2:	Not reported
Mailing City:	SUNSET
Mailing State:	MO
Mailing Zip:	63127
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3148219333

AR246 **FORMER JAYER PLATING** **NY SHWS S110487597**
SSW **2 INGRAHAM ST** **NY VCP N/A**
1/4-1/2 **EAST WILLIAMSBURG, NY 11206** **NY BROWNFIELDS**
0.472 mi.
2492 ft. **Site 1 of 2 in cluster AR**

Relative:
Higher

Actual:
19 ft.

SHWS:

Name:	FORMER JAYER PLATING
Address:	2 INGRAHAM ST
City,State,Zip:	EAST WILLIAMSBURG, NY 11206
Program:	HW
Site Code:	57074
Classification:	N
Region:	2
Acres:	0.500
HW Code:	224036
Record Add:	02/21/2002
Record Upd:	02/28/2018
Updated By:	JEBROWN

Site Description: "Site being handled under BCP - C224036 Location: The Former Jayer Plating site is located at 2 Ingraham Street in the East Williamsburg Area of Brooklyn, New York. Site Features: The site is a 0.5 acre warehouse and is bordered on the south by Harrison Place, on the north by Ingraham Street, on the west by Bogart Street, and on the east by Morgan Avenue. The site is affected by an easement for the New York City Water Tunnel No. 3. Current Zoning and Land Use: The current zoning of the property is M1-2 (light manufacturing), and it is currently vacant. The surrounding land use is mainly manufacturing (M-1 and M-2) with residential (R-6) farther east and west of the site. The businesses in the immediate area include warehouses, auto

FORMER JAYER PLATING (Continued) **S110487597**

scrap yards, masonry materials sales, waste management and trucking. The neighborhood surrounding the site includes some residential units interspersed with commercial properties. A New York City Transit Authority subway line is located beneath Harrison Place, and there are rail yards nearby which are connected to the Long Island Railroad Bushwick Branch. Past Use of the Site: Prior 1946 the Site was used as an orphanage. In 1948, the site was occupied by an umbrella manufacturing plant and a metal plating company between 1946 and early 1990's. After the 1990's, the site has been used as a warehouse without major changes. The site structure has been unoccupied since April 2016. Site Geology and Hydrogeology: The site is underlain by 0 to 8 feet of fill. The fill consists predominantly of silty sands with gravel, bricks, rock fragments, concrete, and coal cinders. Native soils beneath the fill layer consist of medium to fine sand and silt and continues with slight variations up to 35 feet below ground surface (bgs). Clay was encountered at several boring locations at depths greater than 6 feet bgs. The depth to groundwater is approximately 15 feet below grade. The regional groundwater flow direction is roughly south to north, towards the English Kills. "

Env Problem:	"This site is now in the BCP as 2 Ingraham Street site (C224036). Project was reclassed to N. "
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	01
Owner Name:	Joe Brunner
Owner Company:	Bogart Holdings LLC
Owner Address:	390 Berry Street, Suite 200
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11249
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C05
Owner Name:	Gerald A. Esposito
Owner Company:	Brooklyn Community Board 1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Loren Williams
Owner Company:	Brooklyn Public Library, Central Branch
Owner Address:	10 Grand Army Plaza
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238

FORMER JAYER PLATING (Continued) **S110487597**

Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

VCP:

Name:	2 INGRAHAM STREET
Address:	2 INGRAHAM STREET
City,State,Zip:	BROOKLYN, NY 11206
Program Type:	VCP
Site Code:	56868
HW Code:	V00184
Site Class:	N
SWIS:	2401
Region:	2
Town:	New York City
Acres:	Not reported
Date Record Added:	11/30/2000
Date Record Updated:	06/16/2009
Updated By:	IXMUNTEA
Site Description:	"2 Ingraham Street, site represents the Block 3084, Lot 1, in the Williamsburg Area of Brooklyn, NY 11206. The site is a 0.5 acre warehouse. The property is bordered by Ingraham Street to the north, by Marrisson Place to the south, by Bogart Street to the west and by Morgan Avenue to the east. The current use of the site is commercial. Before 1998, the building was used for cloth manufacturing and one of its section was used as a plating factory (Former Jayer Plating Co.). In spring 1998, the warehouse was vacant. The neighbourhood was mixed industrial, residential, and commercial. In the western section of the warehouse, where the plating factory has operated a deep corroded dry drain was noticed. In this area the concrete floor was also broken and corroded, perhaps due to waste bath residues of the metal plating processes on the floor. The VCP investigation was not compleated and the Volunteer Cleanup Agreement negotiations have been closed . See project C224036 "
Env Problem:	""
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6

FORMER JAYER PLATING (Continued) **S110487597**

Sub Type:	ZZZ
Owner Name:	CARL SAVRYN
Owner Company:	Milhan Realty Corporation
Owner Address:	2 INGRAHAM ST.
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11206
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BROWNFIELDS:

Name:	2 INGRAHAM STREET - OFF-SITE
Address:	2 INGRAHAM ST
City,State,Zip:	EAST WILLIAMSBURG, NY 11206
Program:	BCP
Site Code:	567066
Acres:	Not reported
HW Code:	C224036A
SWIS:	2401
Town:	New York City
Record Added Date:	02/22/2018
Record Updated Date:	04/02/2021
Update By:	JCGRATHW
Site Description:	"This project (2 Ingraham Street Off-Site, C224036A) was created to investigate for potential off-site impacts from the 2 Ingraham Street BCP Site (C224036). Location: This site is the off-site component to the 2 Ingraham Street Site located at 2 Ingraham Street in the East Williamsburg Area of Brooklyn, New York. Site Features: The BCP site is a 0.5 acre warehouse and is bordered on the south by Harrison Place, on the north by Ingraham Street, on the west by Bogart Street, and on the east by Morgan Avenue. The BCP site is affected by an easement for the New York City Water Tunnel No. 3. Current Zoning and Land Use: The current zoning of the BCP site is M1-2 (light manufacturing), and it is currently vacant. The surrounding land use is mainly manufacturing (M-1 and M-2) with residential (R-6) farther east and west of the site. The businesses in the immediate area include warehouses, auto scrap yards, masonry materials sales, waste management and trucking. The neighborhood surrounding the site includes some residential units interspersed with commercial properties. A New York City Transit Authority subway line is located beneath Harrison Place, and there are rail yards nearby which are connected to the Long Island Railroad Bushwick Branch. Past Use of the Site: Prior 1946 the BCP site was used as an orphanage. In 1948, the BCP site was occupied by an umbrella manufacturing plant and a metal plating company between 1946 and early 1990's. After the 1990's, the BCP site has been used as a warehouse without major changes. The site structure has been unoccupied since April 2016. Site Geology and Hydrogeology: The BCP site is underlain by 0 to 8 feet of fill. The fill consists predominantly of silty sands with

FORMER JAYER PLATING (Continued) **S110487597**

	gravel, bricks, rock fragments, concrete, and coal cinders. Native soils beneath the fill layer consist of medium to fine sand and silt and continues with slight variations up to 35 feet below ground surface (bgs). Clay was encountered at several boring locations at depths greater than 6 feet bgs. The depth to groundwater is approximately 15 feet below grade. The regional groundwater flow direction is roughly south to north, towards the English Kills. "
Env Problem:	"This Site represents an off-site project to investigate the area surrounding BCP Site C224036, 2 Ingraham Street. The environmental assessment below is for C224036. Off-site investigation including groundwater sampling, soil vapor sampling, and soil vapor intrusion investigation is planned. Nature and Extent of Contamination: The primary contaminants of concern off-site include metals, and volatile organic compounds (VOCs). Previous environmental investigation in the area revealed concentrations of metals and VOCs exceeding Standards, Criteria, and Guidance values in the soil and/or groundwater. Based upon investigations to date, shallow soils (up to 5 feet below ground surface) are contaminated with metals. Data results from soils sampling reported metals (lead, mercury and nickel). Maximum detections vs. applicable unrestricted use or protection of groundwater cleanup objectives are as follows: lead at 106 parts per million (ppm) vs. 63 ppm, mercury at 18.2 ppm vs. 0.73 ppm, and nickel at 433 ppm vs. 130 ppm. Groundwater sampling indicates metals and VOCs contamination above Class GA groundwater standards. Some metals were found in relative low levels in groundwater and are likely related to the presence of historic fill. Maximum groundwater detections vs. standards are as follows: tetrachloroethene at 17 parts per billion (ppb) vs. 5 ppb, trichloroethene at 140 ppb vs. 5 ppb, chromium at 10,800 ppb vs. 50 ppb, and nickel at 8,690 ppb vs. 100 ppb. "
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2018-03-07 12:41:00
Record Upd:	2018-03-07 12:41:00
Updated By:	JXPEREZM
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	C224036A
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

FORMER JAYER PLATING (Continued) **S110487597**

HW Code:	C224036A
Waste Type:	nickel
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224036A
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224036A
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224036A
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C224036A
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

Name:	2 INGRAHAM STREET
Address:	2 INGRAHAM ST
City,State,Zip:	EAST WILLIAMSBURG, NY 11206
Program:	BCP
Site Code:	435675
Acres:	1.800
HW Code:	C224036
SWIS:	2401
Town:	New York City
Record Added Date:	06/04/2010
Record Updated Date:	06/15/2021
Update By:	GWBURKE
Site Description:	"Location: The 2 Ingraham Street site is located at 2 Ingraham Street in the East Williamsburg Area of Brooklyn, New York. Site Features: The site is a 0.5 acre warehouse and is bordered on the south by Harrison Place, on the north by Ingraham Street, on the west by Bogart Street, and on the east by Morgan Avenue. The site is affected by an easement for the New York City Water Tunnel No. 3. Current Zoning and Land Use: The current zoning of the property is M1-2 (light manufacturing), and it is currently vacant. The surrounding land use is mainly manufacturing (M-1 and M-2) with residential (R-6) farther east and west of the site. The businesses in the immediate area include warehouses, auto scrap yards, masonry materials sales, waste management and trucking. The neighborhood surrounding the site includes some residential units interspersed with commercial properties. A New York City Transit Authority subway line is located beneath Harrison Place, and there are rail yards nearby which are connected to the Long Island Railroad Bushwick Branch. Past Use of the Site: Prior 1946 the Site was used as an orphanage. In 1948, the site was occupied by an umbrella manufacturing plant and a metal

FORMER JAYER PLATING (Continued) **S110487597**

plating company between 1946 and early 1990's. After the 1990's, the site has been used as a warehouse without major changes. The site structure has been unoccupied since April 2016. Site Geology and Hydrogeology: The site is underlain by 0 to 8 feet of fill. The fill consists predominantly of silty sands with gravel, bricks, rock fragments, concrete, and coal cinders. Native soils beneath the fill layer consist of medium to fine sand and silt and continues with slight variations up to 35 feet below ground surface (bgs). Clay was encountered at several boring locations at depths greater than 6 feet bgs. The depth to groundwater is approximately 15 feet below grade. The regional groundwater flow direction is roughly south to north, towards the English Kills. "

Env Problem:

"Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. The primary contaminants of concern at the site include metals, SVOCs, and VOCs. Environmental investigation in the area revealed concentrations of metals, SVOCs, and VOCs exceeding Standards, Criteria, and Guidance values (SCGs) in the soil and/or groundwater. Soil: Based upon investigations to date, sub-surface soils are contaminated with metals, SVOCS, and VOCs. Results from soils sampling reported metals (chromium, lead, mercury, and nickel), SVOCs (polyaromatic hydrocarbons or PAHs), and VOCs(tetrachloroethene or PCE). The PAHs contamination in soils is likely related to the presence of historic fill. Maximum detections vs. applicable unrestricted use or protection of groundwater soil cleanup objectives (UUSCO/PGWSCO) are as follows: chromium at 8,400 ppm vs. 19 ppm, lead at 607 ppm vs. 63 ppm, mercury at 1,790 ppm vs. 0.73 ppm, nickel at 3,720 ppm vs. 130 ppm, several PAHs including benzo(a)pyrene at 16 ppm vs. 1 ppm, and PCE at 1.9 ppm vs. 0.47 ppm. Mercury and nickel (up to 18.2 ppm, and 433 ppm, respectively) were detected off-site at soil boring SSB7N. Lead (up to 106 ppm) was detected off-site at soil boring SB8. Groundwater: Groundwater sampling indicates metals and VOCs contamination above Class GA groundwater standards. Some metals were found in relative low levels in groundwater and are likely related to the presence of historic fill. Maximum groundwater detections vs. standards are as follows: chromium at 110,000 parts per billion (ppb) vs. 50 ppb, lead at 461 ppb vs. 25 ppb, and nickel at 90,900 ppb vs. 100 ppb. PCE (up to 17 ppb) and mercury (up to 3.3 ppb) were detected in off-site downgradient groundwater at MW-7. Chromium, lead, and nickel (up to 10,800 ppb, 802 ppb, and 8,690 ppb, respectively) were detected off-site in down-gradient groundwater at MW-8. Trichloroethene up to 140 ppb was detected off-site in groundwater at MW-6. Soil Vapor: Elevated levels of VOCs were detected in sub-slab soil vapor. The maximum concentrations of PCE and 1,1,1-Trichloroethane in sub-slab soil vapor were detected in the northwestern/northeastern portion of the site at the respective concentrations of 827 micrograms per cubic meter (ug/m3) and 1,220 ug/m3. In addition, soil vapor intrusion (SVI) levels for methylene chloride (e.g., 42 ug/m3 [below the slab] and 20.5 ug/m3 [indoor air]) require additional assessment, investigation or mitigation in accordance with NYSDOH SVI matrices. Therefore, additional sampling is needed to determine whether actions are needed to address soil vapor intrusion on- and off-site. Significant Threat: Recent public events held at the site and past unapproved activities are likely to increase the risk of direct contact with the contamination visually observed on the surface of the slab and/or slab areas with broken

FORMER JAYER PLATING (Continued) **S110487597**

	concrete in which the upper soils likely contain hazardous waste levels of contamination. Contravention of SCOs for metals pose a significant threat to human health due to accessibility. Also, metals contamination in soil at the source area exceeds respective industrial and/or protection of groundwater SCOs. This has resulted in contamination of shallow groundwater at levels several orders of magnitude above standards, creating a significant threat to the environment."
Health Problem:	"Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. People may come into contact with contaminants in soils if they dig below the surface or contact exposed soil. Volatile organic compounds in soil vapor (air spaces within the soil) may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because the site is vacant, the inhalation of site-related contaminants due to soil vapor intrusion does not represent a current concern. The potential exists for the inhalation of site contaminants due to soil vapor intrusion in the event the site is re-occupied and for any future buildings developed on the site. Additional evaluation is needed to determine whether actions are needed to address soil vapor intrusion off-site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-09-20 13:57:00
Record Upd:	2016-09-28 14:18:00
Updated By:	JXPEREZM
Own Op:	1
Sub Type:	06
Owner Name:	Steve Novenstein
Owner Company:	74 Bogart LLC
Owner Address:	c/o Storage Deluxe Realty
Owner Addr2:	26 W. 17th Street, Suite 801
Owner City,St,Zip:	new york, NY 10011
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Joseph Brunner
Owner Company:	Bogart Holdings LLC
Owner Address:	390 Berry Street, Suite 200
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11249
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Loren Williams
Owner Company:	Brooklyn Public Library, Central Branch
Owner Address:	10 Grand Army Plaza

FORMER JAYER PLATING (Continued) **S110487597**

Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11238
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Gerald A. Esposito
Owner Company:	Brooklyn Community Board 1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Steve Novenstein
Owner Company:	74 Bogart LLC
Owner Address:	c/o Storage Deluxe Realty
Owner Addr2:	26 W. 17th Street, Suite 801
Owner City,St,Zip:	new york, NY 10011
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	C224036-09-10
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-02-10 08:47:00
Record Updated:	2020-02-10 09:32:00
Updated By:	SMQUANDT
Crossref ID:	11/10/2010
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2020-02-10 08:48:00
Record Updated:	2020-02-10 08:48:00
Updated By:	JXPEREZM
Crossref ID:	224036
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2018-02-28 08:41:00
Record Updated:	2018-02-28 08:41:00
Updated By:	JEBROWN
Crossref ID:	V00184
Cross Ref Type Code:	04
Cross Ref Type:	VCP Site ID
Record Added Date:	2018-02-28 08:39:00
Record Updated:	2018-02-28 08:39:00
Updated By:	JEBROWN
Crossref ID:	9830001
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2016-03-30 11:11:00
Record Updated:	2016-03-30 11:11:00
Updated By:	JXPEREZM

AR247 **FORMER JAYER PLATING** **NY HSWDS** **S104495031**
SSW **2 INGRAHAM STREET** **N/A**
1/4-1/2 **EAST WILLIAMSBURG, NY 11206**
0.472 mi.
2492 ft. **Site 2 of 2 in cluster AR**

Relative:
Higher

Actual:
19 ft.

HSWDS:

Facility ID:	HS2044
Region:	2
Facility Status:	None
Owner Type:	Puplic
Owner:	Millhan Realty Co./Carl Savryn
Owner Address:	Not reported
Owner Phone:	(212)972-8600
Operator Type:	Puplic
Operator:	Jayer Plating
Operator:	Jayer Plating
Operator Phone:	Not reported
EPA ID:	Not reported
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	Not reported
RCRA Permitted:	No
Site Code:	Industrial Site
Owner City State:	Not reported
Operator City State:	Not reported
Quadrange:	Brooklyn
Latitude:	40 42 22 N
Longitude:	73 56 30 W
Acres:	1.80
Operator Date:	1946
Close Date:	1990
Completed:	PRP Phase2
Active:	No
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	Yes
Asbestos Disposed:	Unknown
Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	Groundwater
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Subsurface
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	TCLP
Threat to Environment/Public Health:	Environmental
Surface Water Contamination:	Unknown
Surface Water Body Class:	SD
Groundwater Contamination:	Yes
Groundwater Classification:	Sole Sourc
Drinking Water Contamination:	No
Drinking Water Supply is Active:	Yes
Any Known Fish or Wildlife:	No
Hazardous Exposure:	Unknown
Site Has Controlled Acess:	Yes

FORMER JAYER PLATING (Continued) **S104495031**

Ambient Air Contamination:	No
Direct Contact:	Unknown
EPA Hazardous Ranking System Score:	N/A
Inventory:	Not reported
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	Not reported
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

248
SSE
1/4-1/2
0.480 mi.
2536 ft.

UNIVERSAL USED AUTO PARTS INC (BROOKLYN) **NY SWF/LF** **S107488576**
1175 FLUSHING AVE **NY Spills** **N/A**
BROOKLYN, NY 11237

Relative:
Higher

Actual:
19 ft.

SWF/LF:

Name:	UNIVERSAL USED AUTO PARTS INC (BROOKLYN)
Address:	1175 FLUSHING AVE
City,State,Zip:	BROOKLYN, NY 11237
Flag:	INACTIVE
Region Code:	2
Phone Number:	7183811000
Owner Name:	Universal Used Auto Parts Inc
Owner Type:	Private
Owner Address:	1175 Flushing Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11237
Owner Email:	unviersalscapprocessors@gmail.com
Owner Phone:	7183811000
Contact Name:	Louis Ruggiero
Contact Address:	1175 Flushing Avenue
Contact Addr2:	Not reported
Contact City,St,Zip:	Brooklyn, NY 11237
Contact Email:	universalscrapprocessors@gmail.com
Contact Phone:	7183811000
Activity Desc:	Vehicle Dismantling Facility

UNIVERSAL USED AUTO PARTS INC (BROOKLYN) (Continued) **S107488576**

Activity Number: [7094890]
Active: No
East Coordinate: 590817
North Coordinate: 4506665
Accuracy Code: Not reported
Regulatory Status: Not reported
Waste Type: Not reported
Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Universal Used Auto Parts Inc
Operator Type: Private
Laste Date: Not reported

SPILLS:
Name: OLD GAS STATION -MTBE
Address: 1175 FLUSHING AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0510000 / Not Reported
Facility ID: 0510000
Facility Type: ER
DER Facility ID: 305928
Site ID: 355883
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2005-11-21
Investigator: KMFORSTE
Referred To: RAP IMPLEMNTD; REPLACE/REPAIR WELLS OCT '1
Reported to Dept: 2005-11-21
CID: 407
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 4
Date Entered In Computer: 2005-11-21
Spill Record Last Update: 2021-06-30
Spiller Name: UNKNOWN
Spiller Company: OLD GAS SATION
Spiller Address: 1175 FLUSHING AVE
Spiller Company: 001
Contact Name: UNKNOWN
DEC Memo: "need to send CSL 01/13/06-Vought-Received call from Ted Yen (718-857-3100) and returned call and no answer on phone. 02/24/06-Vought-Spoke with Ted Yen and tank closure report. 02/27/06-Hiralkumar Patel. Abstracts of Tank Closure Report: - Work performed: notification with NYSDEC for closure of tanks, excavation, cleaning/purging and removal of eleven (11) 550 gallon gasoline USTs - total of 239.78 tons of contaminated soil was removed from the site and transported to Soil Safe Inc. Bridgeport in Logan Township NJ. - soil and site assessments were conducted using PGM 30 PID. - based on

UNIVERSAL USED AUTO PARTS INC (BROOKLYN) (Continued) **S107488576**

visual and olfactory evidence, there was some contamination localized in the area located on the west perimeter of the tank grave near the fill pipes. (PID readings 80-150 ppm) - six end point soil samples (EP-1, EP-2, EP-3, EP-4, BS-1 & BS-2) taken from the four side walls and mid-grave east and mid-grave west. - groundwater flow is assumed to be in a westerly direction. - no groundwater intrusion in the pit. - groundwater contamination was identified from a Phase-II subsurface assessment previously conducted by Giorgio Envirnomental. - no private wells in the vicinity of tanks. - two groundwater wells were installed at depth of 22'-24' on two separate locations on the subject property. One monitoring well installed on the middle of the previous tank grave and second well was installed on northwest of the previous tank grave (east of office) Report Review Letter, with the requirement of water sample at middle of previous tank grave, sent out to James Ruggiero. faxed to Ted yen at don carlo. 03/28/06-Hiralkumar Patel. REceived fax from Don Carlo regarding groundwater sample result. but i have received only first four pages, and doesn't have lab results. Spoke with Danny and he told me that he going to drop report personally today. 04/04/06-Vought-Received and reviewed groundwater analyticals received from Don Carlo Environmental Services-3/27/06. Groundwater analyticals show 130ppb benzene(MW1), 1600ppb toluene(MW1), 1200ppb ethylbenzene(MW1), 4400ppb xylene(MW1) and 300ppb napthalene(MW1). Spill referred to DEC Austin for transfer due to groundwater contamination. 04/06/06-Vought-Spill transferred from DEC Vought to DEC Tang as per DEC Austin due to groundwater contamination and need for long term remediation. 4/12/06 - reviewed the case file. Will wait for the next round of groundwater sample before assigning the priority. - KST. 10/30/06 - Reassigned from Tang to Sun. (JS/MS) 1/3/07: Called Don Carlo (Ted Yen) and left message with secretary inquiring about latest round of ground water sampling at site. Expecting a return call. (JS/MS) 3/1/07: Followed up with Don Carlo- client has not yet paid them for the last round of groundwater sampling, once payment is received, sampling will be performed. (JS/MS) 7/28/07: Client has paid and on-site sampling is to be conducted on 7/15/07 as per Dan from DCS Services. (JS/MS) 1/24/08: MS spoke to Ted to get update. He said property came under new ownership and he is waiting for them to approve proposal to continue work. He will call back this afternoon or tomorrow to let me know details as he was out of office. (MS/JS) 2/5/08: DCES is taking 5th sampling event in 3 weeks from today. Danny from DCES is emailing all results to DEC to obtain electronic copies. (JS/MS) 4/3/08: Spoke to Danny Singh from Don Carlo. Reported frozen groundwater in monitoring wells. Supposed to resample 4/10/08. (JS/MM) 4/23/08: Email from Don Carlo (JS/MM) Please be advised that the groundwater samples at the above referenced site were collected as per our telephone conversation; however, the samples weren't collected on April 10, 2008 they were collected approx one week later. The samples were sent to York Analytical Laboratories in Stratford, CT for analysis. Upon receipt of the analytical results, you will receive the necessary lab data together with our Groundwater monitoring table. Danny Singh 06/02/08: Received groundwater table from Don Carlo Environmental; missing lab results from latest round of sampling. Ask to resubmit and correct for updated TAGM 4046 table. York Labs MDL for MTBE, BTEX 50 ppb to 125 ppb...when groundwater standards are 0.7/5/10 ppb (JS/MM) 08/05/08: Transferred to Kolleeny/Mandac. - JK 10/13/08: Danny Singh stated Don Carlo did not sample because owner did not give permission to sample (JK/MM)

UNIVERSAL USED AUTO PARTS INC (BROOKLYN) (Continued) **S107488576**

01/06/09: Left message with receptionist for Danny Singh to call back with update. (JK/KG) 01/15/09: Tried to call Don Carlo, but no answer (JK/KG) 01/26/09: Left message with receptionist for Danny Singh to call back with update. (JK/KG) 02/03/09: K. Green sent D. Singh email: Mr. Singh, I will be managing Spill No. 0510000 located at 1175 Flushing Avenue from now on, under supervision of Jon Kolleeny. My contact information is provided below. Can you please provide me with an update on status of this site? Latest rpt I have is a GW monitoring rpt for samples collected in April 2008. Have you been able to collect any samples since then? Please feel free to contact me if you have any questions. Response from Singh: Ms. Green, We have tried several times to contact owner for monies to continue with GW monitoring at site. Todate no response were gained. Our office will not continue with monitoring until money is received from client. (JK/KG) 02/09/09: Letter sent to Ruggiero requesting: Dept requires that a subsurface investig work plan be prepared & submitted for our review by 3/13/09. Work plan should include install'n of at least one addt'l monitoring well to further delineate GW contaminant plume and determine GW flow direction. During well install'n, soil must be sampled continuously and screened with a PID, and sample with highest PID reading and sample just above water table should be submitted for lab analysis. New and existing wells should be surveyed so that local GW flow direction can be determined, and GW samples should be collected from all wells for lab analysis. Work plan should include a site location map and a site plan showing current and former tank locations and locations of existing and proposed monitoring wells, and a North arrow and scale bar must be included on site plan. An investigation summary rpt with conclusions and recommendations should be submitted to DEC. SIWP due 3/19/09. (JK/KG) 02/17/09: Letter sent on 2/9/09 to Mr. Ruggiero at 1175 Flushing Ave was returned to sender. Addressee moved and did not leave a forwarding address. Sent Danny Singh an email to see if he has any contact information for Mr. Ruggiero. (JK/KG) 02/23/09: No response from D. Singh pertaining contact info for Ruggiero. Property Shark gives an address for Ruggiero in Howard Beach, NY. Re-sent letter requesting work plan be submitted by 3/27/09. Letter sent to 163-14 92nd St, Howard Beach, NY 11414. J. Kolleeny also sent an email to D. Singh requesting updated contact info (if any) for Ruggiero. (JK/KG) 03/25/09: On 3/4/09 Jon rec'd call from D. Singh stating that Ruggiero rec'd letter and the work will be performed. Singh was supposed to fax a letter to Jon. (JK/KG) 03/31/09: I spoke to D. Singh to find out status of site. He said DCES just received payment from Ruggiero and once the check clears they will begin to prepare the work plan. He will give me an update in the next couple of days.(JK/KG) 04/06/09: Rec'd voice message from D. Singh on 4/3/09 stating that payment has been rec'd and he has begun preparing the work plan. He was requesting an extension until 4/6/09. Rec'd pdf of work plan; under review. (JK/KG) 04/13/09: Rev'd work plan and spoke to D. Singh about making some revisions. He will resubmit a pdf of the revised plan and send me a hard copy. (JK/KG) 04/21/09: Rec'd pdf of revised Subsurface Investigation & GW Monitoring Well Work Plan dated 4/20/09. D. Singh will mail hardcopy. Letter sent approving work plan; investig summary rpt is due 6/19/09. Scope of work includes install'n of an addt'l monitoring well, collection of soil and GW samples, and submission of investig summary rpt. Letter states that new and existing wells should be surveyed so that local GW flow direction can be determined and that proposed well MW-3 should be installed as close as possible

UNIVERSAL USED AUTO PARTS INC (BROOKLYN) (Continued) **S107488576**

to existing on-site building, conditions permitting. D. Sing has indicated that property is a metal scrap/salvage yard and open space is limited. (JK/KG) 06/15/09: Rec'd pdf and hardcopy of Envt'l Subsurface Assessment rpt dated 6/5/09 prepared by Don Carlo. Spoke to D. Singh and requested well install'n/boring log for W-3 and site map. He said wells were not surveyed because owner did not want to pay to have it done. Well W-3 was installed on 4/22/09 and all wells were sampled for GW on 4/23/09. No SVOCs or VOCs detected in soil samples collected from B-3 (W-3). No SVOCs or VOCs detected in GW in W-2 and W-3. No SVOCs detected in GW in W-1. Detected VOCs include: Benzene (99 ug/L), n-Butylbenzene (59 ug/L), Ethylbenzene (990 ug/L), Isopropylbenzene (68 ug/L), Napthalene (850 ug/L), n-Propylbenzene (150 ug/L), 1,2,4-Trimethlybenzene (2,200 ug/L), 1,3,5-Trimethlybenzene (640 ug/L), m,p-Xylene (3,700 ug/L), o-Xylene (91 ug/L). (JK/KG) 06/16/09: Rec'd pdf of boring log for W-3 and site plan with well locations. I spoke to Danny Singh and requested a well construction log as well. I asked him if depths given on GW analysis table were depths to water measured for each sample. He said they were. There is a huge discepency in depths. W-1 and W-2 were installed to depths of 22 and 24 ft bgs and measured depths to water vary from 32' bgs to 14' bgs (i.e., deeper than total depth of well). Danny said he would look into it. I also asked him what kind of probe they were using to measure depth to water. He said it is an electronic water sensing device and it doesn't detect product. I also asked him to find out what is smallest interval probe can detect, since usually it is 0.01'. He said he doesn't have well construction details for W-1 or W-2. I asked him if W-3 was installed as close to building as possible and he said that it was. There is a scale for trucks directly behind building and well was installed next to a dumpster in an area that would be accessible. (JK/KG) 06/18/09: Letter dated 6/17/09 sent to Ruggiero requiring a work plan for a supplemental subsurface investigation be submitted by 7/17/09. Wells must be surveyed. A Stipulation Agreement was issued to Ruggiero on 6/18/09. Signed stip is due on 7/2/09. (JK/KG) 07/02/09: Rec'd faxed copy of signed Stipulation Agreement. Called Mr. Ruggiero (718-381-1000 or 718-791-4351) and he said a hard copy of Stip would be delivered today. He wanted clarification on letter sent on 6/17. I told him contaminant plume needs to be delineated and that was reason DEC is requiring a work plan for further investigation. He said he contacted a surveyor but they were not familiar with surveying monitoring wells. I explained to him process of surveying wells. Rec'd original signed Stip. (JK/KG) 07/06/09: Stipulation Agreement was executed on 7/3/09. (JK/KG) 07/14/09: Rec'd messsage from Zeb Youngman of P.W. Grosser (631-589-6353). Spoke to Youngman on 7/14. He said he was contacted by Ruggiero to submit a proposal for the additional investigation. If PWGC's proposal is accepted he will need some extra time to submit the work plan. (JK/KG) 07/20/09: Rec'd call from Ruggiero. He informed me that he has hired PWGC and a work plan will be submitted soon. Rec'd an email from Youngman as well, stating he will have the work plan by 7/23/09. (JK/KG) 07/23/09: Rec'd pdf of Monitoring Well Installation / Groundwater Monitoring Work Plan dated 7/21/09 submitted by PWGC. The work plan proposes installation of one permanent and three temporary monitoring wells, collection of groundwater samples, a groundwater elevation survey, and implementation of quarterly groundwater monitoring at the site for one year. The work plan was approved with the following comments: During well installation, soil must be sampled and screened

UNIVERSAL USED AUTO PARTS INC (BROOKLYN) (Continued) **S107488576**

continuously, and the sample with the highest PID reading and the deepest dry soil sample should be submitted for laboratory analysis. If PID readings are not detected, only the deepest dry soil sample need be analyzed. In addition to surveying the existing and new monitoring wells, well construction details such as well depth and screened interval should be determined for the existing wells. If the existing wells are not screened appropriately to assess groundwater conditions, additional wells will need to be installed. Well construction logs should be provided for all wells. The proposal to limit quarterly monitoring to a one-year period is not approved at this time. The results of this investigation should be presented in a summary report with conclusions and recommendations for further action. An investigation summary report is due by 9/25/09. Email for Ruggiero - JCR327@aol.com (JK/KG) 07/29/09: Rec'd call from Youngman. He was at the site today to survey and assess the condition of the existing wells. He sent a revised site plan showing the GW flow direction and proposed location of the new well, as well as GW elevation survey data. (eDocs)(JK/KG) 08/03/09: A copy of the executed Stip sent certified mail to Ruggiero was returned to the Dept. as unclaimed. It was resent to Ruggiero via email and regular mail. Spoke to Ruggiero and he said he receives mail at the Howard Beach address. (JK/KG) 08/05/09: Rec'd an email from Youngman stating that PWGC will be installing the well and performing soil and groundwater sampling on 8/7. (JK/KG) 09/21/09: Rec'd call from Ruggiero. He said PWGC has proposed injections and he wanted to know if it would be a good approach for site. I told him that I would have to review recent data when rpt is submitted. Once rpt is submitted & reviewed he would like to discuss PWGC's recommendations as soon as possible. He can be reached on his cell phone (718-791-4351). Rec'd Monitoring Well Installation / First Quarter Groundwater Monitoring Report dated 9/21/09 submitted by PWGC. On 8/7/09 one permanent and three temporary monitoring wells were installed. Soil and GW contamination was encountered. The new and existing monitoring wells were surveyed and groundwater flow is northerly. Soil samples were collected at 10-12' and 14-16' bgs from borings GW-1, 2, and 3 and at 10-12' bgs from MW-4. Depth to water is approximately 12' bgs. VOCs in excess of RSCO's were found in GW-1 (10-12' and 14-16'), GW-2(14-16'), and GW-3(14-16'). Summary of GW samples: MW-1: Total VOCs - 2,779 ug/L MW-2: Total VOCs - 185 ug/L MW-3: Total VOCs - 3.26 ug/L MW-4: Total VOCs - 4.04 ug/L GW-1: Total VOCs - 9,217 ug/L GW-2: Total VOCs - 7,570 ug/L GW-3: Total VOCs - 2,849 ug/L PWGC recommends chemical oxidation and ORC injections, followed by quarterly monitoring and reporting. Need to respond to recommendations. Contaminant plume needs to be delineated prior to remedial action. (JK/KG) 09/22/09: A letter was sent to Ruggiero requiring a brief work plan with a diagram showing the proposed locations for the new wells by 10/23/09. At least 2 wells should be installed: one to the NE of the former USTs and one to the SW of the former USTs. Soil samples should be collected during installation. After the wells have been installed and sampled a remedial action plan detailing PWGC's proposed remedial strategy should be submitted. (JK/KG) 09/23/09: Zeb Youngman called to discuss the requirement to install additional wells. He doesn't think they are necessary. I told him that the contaminant plume needs to be delineated prior to implementing remedial action. The well proposed to the SW of the former USTs does not need to be installed at this time. (JK/KG) 11/3/09 Spill case transferred from J. Kolleeny to J.A. Maisonave. - JAM 11/4/09 Spoke

UNIVERSAL USED AUTO PARTS INC (BROOKLYN) (Continued) **S107488576**

to Zeb Youngman. He will be submitting a work plan to install additional monitoring wells and propose RegenOx injections to address soil and GW contamination. - JAM 1/20/10 Reviewed the Remedial Action Work Plan (RAWP) submitted by P.W. Grosser (PWG) via email on January 4, 2010. The report is dated December 2009. The work plan proposes injecting chemical oxidants and oxygen releasing compounds to address groundwater contamination in the former UST area and installing two (2) additional monitoring wells to fully delineate groundwater contamination. Details are as follows: 1. 15 injection points in an area approximately 30 X 50 feet. 2. Based on RegenOx calculations, a total of 2,640 lbs of RegenOx and 450lbs of ORC advanced will be injected in 2 events. 3. First injection event will consist of 1,500 lbs of RegenOx (750 lbs each of Part-A and Part-B) 4. Second injection event will consist of a mixture of 1,110 lbs of RegenOx (750 lbs of Part-A, 360 lbs of Part-B) and 450 lbs of ORC advanced. 5. Installing 2 monitoring wells to the North and South of the Former UST area to fully delineate groundwater contamination. I issued a response letter to James Ruggiero approving the installation of the two monitoring wells. The locations of the wells should be modified as shown on a diagram, which was attached and issued with the letter. A third well should be installed to the northwest of the on-site building, between existing wells MW-2 and MW-4, also shown on the diagram. Groundwater samples should be collected from all wells and analyzed for the TAGM 4046 list of petroleum related VOCs as well as for chlorinated solvents (in response to the one boring have a solvent odor according to the Sept 2009 well installation report). A summary report should be submitted for review prior to implementing the proposed remedy and should include any changes to the remedy based on new information. The RAWP and DEC response letter are uploaded to eDocs. - JAM 2/5/10 Received an email from Jon Eichler from PW Grosser. The 3 monitoring wells will be installed Saturday, February 6th. - JAM 3/31/10 Received the Supplemental Monitoring Well Installation and Sampling Report submitted by PW Grosser dated March 15, 2010. On February 6, 2010, three new monitoring wells (MW-5 through MW-7) were installed and well MW-4 was re-installed because it had been destroyed. Groundwater was encountered at approx. 12 feet. Soil was screened and sampled only in new wells. PID readings above background were only observed in well MW-7 from 4' to 12' below grade. A soil sample was collected from deepest dry soil interval in each of wells and also from 5'-7' depth interval of MW-7 (highest PID reading). Laboratory results showed several VOCs in soil samples collected from MW-6 and MW-7, however, concentrations were below RSCOs. No VOCs were detected in soil from well MW-5. Groundwater samples were collected from wells MW-1 through MW-7. VOCs were detected at concentrations exceeding DEC standards from wells MW-1, MW-2, MW-5, MW-6, and MW-7, and Total VOCs ranged from 58 ug/L in well MW-5 to 12,413 ug/L in well MW-1. Even though well MW-1 had highest concentration of Total VOCs, well MW-2 had highest concentrations of petroleum related VOCs (MW-1 had Acetone concentration of 11,500 ug/L). Total BTEX concentration in well MW-2 was 2,517 ug/L. Contamination in MW-2 has always been relatively low in previous sampling events (185 ug/L Total VOCs from August 2009 sampling event). PW Grosser does not propose any changes in the RAWP, which was submitted in January 2010, even though the Total VOC concentrations increased in well MW-2. On March 31, 2010, DEC issued a letter appproving the RAWP and states that, Follow-up groundwater sampling must be performed subsequent to the chemical oxidant and ORC

UNIVERSAL USED AUTO PARTS INC (BROOKLYN) (Continued) **S107488576**

injections to evaluate the effectiveness of the remedy. If this remedy is not effective at reducing groundwater contamination, then additional remediation will be required. The report and the approval letter are uploaded to eDocs. - JAM 10/20/10 From emails with Jim Eichler: First round of ChemOx injections performed on July 30 and 31, 2010. The second round of injections occurred on September 11, 2010. The first post-injection sampling is scheduled for Tuesday, October 26, 2010. The Remedial Action Report should be completed in November 2010. - JAM 05/09/11: This spill case is transferred from J. Maisonave to J. Kolleeny. Received email from John Eichler of PW Grosser: We are performing a round of quarterly GW monitoring at 1175 Flushing Avenue in Brooklyn this Friday. I sent email reply asking him to send me pdf's of any rpts more recent than their 3/15/10 Suppl'tal Mon Well Install'n & Sampling Rpt, and noting that Joe Maisonave's notes indicated he was expecting a Remedial Action Rpt in late 2010. Eichler sent reply: We re finalizing RAR. We ve had some delays with project, but chemox injections went smoothly. We ll have RAR to you soon. - J. Kolleeny 06/03/11: Reviewed May 2011 Remedial Action Rpt by P.W. Grosser (in eDocs). Rpt summarizes injections of RegenOx and ORC Advanced in August and Sept. 2010 and gives results of GW sampling done in Feb. and Oct. 2010, before and after injections. Most impacted wells, MW-1 and MW-2, showed significant declines in contaminant levels after injections: MW-1 had 1,021 ug/L total VOCs in Oct. 2010, down from 12,413 ug/L in Feb. 2010; MW-2 had 892 ug/L tVOCs in Oct. 2010, down from 4,540 ug/L in Feb. 2010. Rpt recommends replacing wells MW-5 and MW-7, which were damaged/destroyed (resp.) by site activities, and continued quarterly GW sampling to monitor contam trends. I sent email (in eDocs) to James Ruggiero (RP, jcr327@aol.com), cc to John Eichler of PWGC, approving these recommendations. Changed site priority ranking from P0 to P2 since site is in follow-up monitoring after remedial action. - J. Kolleeny 04/13/12: Received email from John Eichler of PWGC, with attached pdf file of GW Mon Rpt by PWGC (rpt was dated Jan. 2012 until I pointed this out to John, then he sent rpt with April 2012 on title page; both are in eDocs). Email stated: Jon, Attached is GW mon rpt for this site. We intend to replace damaged monitoring wells and perform another round of sampling in very near future. I will give you 2 weeks notice of this fieldwork. Please contact me with your questions and comments. Rpt presents results of GW sampling in Dec. 2011; four of 7 wells were sampled; MW-3 and MW-7 could not be found and MW-5 is partially filled with sediment so could not be sampled. Sample results for wells sampled show significant impacts only in MW-1, which had 4,207 ug/L total VOCs (up from 1,748 ug/L in May 2011). PWGC recommends continued quarterly GW sampling and replacement of wells MW-3, MW-5 and MW-7. I sent email (in eDocs) to James Ruggiero (RP, jcr327@aol.com), cc to John Eichler, approving continued quarterly GW sampling and replacement of wells MW-5 and MW-7; said MW-3 need not be replaced at this time, but if significant increases in VOCs are seen in wells MW-4 and/or MW-7, then MW-3 should be replaced. I further noted that if contam in MW-1 does not decrease significantly, then addt'l injections and/or other remedial actions may be warranted. - JK 10/04/12: Received email from John Eichler of PWGC: Jon, We will be replacing and repairing damaged monitoring wells at Spill Site # 05-10000 located at 1175 Flushing Avenue in Brooklyn on Saturday, October 13, 2012. We will sample wells approximately 2 weeks after that. Please contact me if you have any questions or comments. Thank you. - J. Kolleeny 03/06/13: I sent

UNIVERSAL USED AUTO PARTS INC (BROOKLYN) (Continued) **S107488576**

email to John Eichler of PWGC: John, It's been a while since I've heard anything about this site or received a GW monitoring rpt. Latest GW data I have are from Dec. 2011 (submitted in an April 2012 monitoring rpt). Your email below [10/4/12] states that damaged monitoring wells at site were to be replaced in Oct. 2012, and then sampled two weeks afterwards. Were damaged wells replaced? If so, which ones? April 2012 rpt indicates that well MW-5 was dry, having been partly filled in with sediment; MW-5 is only well down-gradient of former UST area, where RegenOx/ORC Advanced injections were performed, so replacement (or flushing/redevelopment) of that well is critical. Have monitoring wells (replaced and previously existing) been sampled? I've had an inquiry regarding this site from my supervisors here at DEC. Please provide a project update as soon as possible. Received email reply from Eichler: Jon, We replaced monitoring wells MW-2 and MW-7, and repaired MW-4. I checked MW-5 during repair and it appears to be viable. So all of wells, with exception of MW-3 (consistently outside impacted area), are ready to be sampled. I have impressed upon owner importance of sampling wells as soon as possible. I expect that he will respond quickly and I will let you know as soon as we schedule a round. Please contact me if you would like to discuss this further. I then sent reply: Thanks for your quick response. If I understand your email correctly, replacement wells were installed but no GW sampling has been done at site since Dec. 2011. Please let me know if you need me to contact owner about doing sampling. Eichler sent reply: Thanks. Jaime Ruggiero (owner) just responded to me. It looks like we re back on track. I will contact you next week with schedule. - J. Kolleeny 04/16/13: On 4/84/13, I sent email to John Eichler of PWGC: John, Have you been able to schedule a round of GW sampling at this site? Recently, DEC has been concerned about housekeeping practices at this site (an active scrap processing facility), and I would like to be able to confirm that on-site activities are not adversely impacting monitoring wells and GW in general. Please let me know as soon as possible. On 4/16/13, Eichler sent reply: Jon, We re looking to sample monitoring wells at 1175 Flushing Ave, Brooklyn on Saturday, May 4. Please contact me if you have any questions. - J. Kolleeny 06/05/13: Received email from John Eichler of PWGC: Jon, I just wanted to let you know that we did sample monitoring wells at 1175 Flushing Ave on May 29th. I am expecting data soon and will prepare a rpt for your review. Please contact me if you have any questions. - JK 10/23/13: I sent email to John Eichler of PWGC: John, I haven't heard from you about this site in a while (since April 2013). Was a round of GW sampling performed? If so, was a rpt prepared? Please send update on status of site, and if GW sampling was done, please send monitoring rpt or at least lab data. Eichler sent reply: Jon, I ll send you data tables for last round of sampling, and a rpt. Owner of property is looking to redevelop site. Redevelopment would include some more remediation. I will contact you soon to discuss this with you. - J. Kolleeny 11/05/13: Received email from John Eichler of PWGC: Jon, Attached is historical data table for 1175 Atlantic [sic] Avenue, Brooklyn. As you know, site underwent an initial remedial excavation and subsequent chemical injection. However, gasoline-related VOCs remain elevated in portions of site. I will call you soon to discuss site s options. Data (in eDocs) show significant increases in contam levels in a number of wells: well MW-1 had 6,159 ug/L total VOCs (up from 4,207 ug/L in Dec. 2011), well MW-2 had 24,002 ug/L tVOCs (up dramatically from 86 ug/L in Dec.

UNIVERSAL USED AUTO PARTS INC (BROOKLYN) (Continued) **S107488576**

2011), well MW-4 had 392 ug/L tVOCs (up from ND in Dec. 2011), well MW-7 had 992 ug/L tVOCs (up from 144 ug/L in Dec. 2011). I sent email to Eichler: John, Thanks for sending May 2013 GW data. I took a quick look and compared results with data from Dec. 2011, and I'm a little alarmed by dramatic increase in total VOCs in well MW-2. That well only had 86 ug/L total VOCs in Dec. 2011, but May 2013 result shows 24,000 ug/L tVOCs! A site plan in April 2012 rpt shows well MW-2 on up-gradient edge of site (along Stewart Ave.), in terms of GW flow direction. Were wells gauged in May 2013 to determine up-to-date flow direction? Do you have any ideas of what could have caused dramatic increase in total VOCs in well MW-2? Feel free to call to discuss. Eichler sent reply: Jon, MW-2 is one of wells we re-installed (due to damage) prior to last sampling. While new location is only a few ft from old location (in order to avoid vehicles), it seems we hit a hotter spot. I will call you. - J. Kolleeny 07/24/14: Reviewed GW Monitoring Rpt May 2014 by PW Grosser Consulting, Inc., received via email from John Eichler on 7/22/14 (in DecDocs). Eichler's email stated: Jon, Attached for your review is Monitoring Well Sampling Rpt for 1175 Flushing Ave in Brooklyn. Results of this most recent sampling round indicate a decrease in contaminant concentrations. PWGC recommends continued GW monitoring and removal of a recently-discovered out-of-service fuel oil UST located in subject building. Please contact me with your questions and comments. Rpt presents results of well gauging and sampling in May 2014. No LNAPL was detected in any wells. Depth to water/water table elevation measurements suggest GW flow to NE. GW samples were collected from 5 existing mon wells; well MW-7, in area of site operations (auto scrapping), was destroyed (2nd time a well at that location has been destroyed by site ops). Sample results show well MW-1 had 2,675 ug/L total VOCs (down from 6,159 ug/L in May 2013), well MW-2 had 1,110 ug/L tVOCs (down dramatically from 24,002 ug/L in May 2013), well MW-3 was ND (same as in May 2013), well MW-4 had 0.92 ug/l of benzene (below std), with no other detections (down from 392 ug/L in May 2013), well MW-5 was ND (down from 22 ug/L tVOCs in May 2013), well MW-6 had 4 VOC J detections of ~1-2 ug/L each (was ND in May 2013). Rpt states that absence of contam in up-gradient wells MW-5 & MW-6 indicate contam is from on-site source, and based on contam levels in MW-1 & MW-2, PWGC recommends continued GW sampling to monitor GW quality trends. Rpt makes no mention of recently discovered fuel oil UST mentioned in Eichler's email. On 7/24/14, I sent email to Eichler, cc to James Ruggiero, RP (jcr327@aol.com): John, Thanks for monitoring rpt. I agree with recommendation to remove out-of-service fuel oil UST. Tank should be registered and listed as removed by filing a PBS Application/Information Correction Form, and a UST Closure Assessment should be performed and results presented in a Closure Rpt. I also agree with recommendation for addt'l GW sampling to monitor trends in contaminant concentrations. However, I'm not sure if we have ever agreed formally on a GW monitoring schedule for this site. Table 3 in rpt, with historical GW sampling results, shows sampling events performed at irregular intervals ranging from about 6 months to about a year and a half. Other spill sites I manage which have comparable contaminant levels in GW are usually on a quarterly sampling schedule, and I'd like to require quarterly sampling at this site as a way to keep closer track of GW trends, evaluate possible need for addt'l remedial injections, and expedite movement of this case towards closure. Please discuss this with your client and let me know if he will agree to this schedule. Also, I'd like to request two

UNIVERSAL USED AUTO PARTS INC (BROOKLYN) (Continued) **S107488576**

small modifications to future monitoring rpts: (1) Table 2 lists main gasoline-related compounds that DEC regulates, which is good, but it lacks a line for Total VOCs; please add a line for Total VOCs to this table in future rpts. (2) Table 3, with historical GW data, provides a complete list of all VOCs; analyte list should be reduced to report only gasoline-related VOCs as listed in Table 2. These changes will help facilitate my review of rpts. Please let me know if these changes can be made to monitoring rpts. Feel free to contact me if you have any questions/comments. - J. Kolleeny 06/08/15: Reviewed GW Mon Rpt for May 2015 (in DecDocs), submitted via email from John Eichler of PW Grosser on 6/1/15. GW gauging & sampling in April 2015 showed no LNAPL detected; well MW-1 had 3,596 ug/L total VOCs (up from 2,675 ug/L in May 2014), well MW-2 had 1,566 ug/L tVOCs (up from 1,110 ug/L in May 2014), well MW-3 was not sampled, well MW-4 was virtually ND (same as May 2014), well MW-5 had 25 ug/L tVOCs (was ND in May 2014), well MW-6 had 20 ug/L tVOCs (up from ND in May 2014), well MW-7 has been destroyed by site operations (for 2nd time). Rpt states that MW-3 is consistently located outside of contaminant plume. Water table map shows GW flow direction to SE. Rpt text concludes that contam levels decreased after chem ox injections, but then increased in May 2013, possibly due to changes in water table elevations or GW flow direction related to dewatering in subway tunnel adjacent to site; levels decreased again in May 2014. Data for May 2015 show migration of contam from source area around MW-1 in direction of GW flow to NE (?sic) towards MW-2. PW Grosser recommends continued sampling to monitoring GW quality trends at site. - J. Kolleeny Spill transferred from J. Kolleeny to K. Forster since property is part of the BCP (K. Forster) 3/30/17: Working with BCP Consultant, Environmental Business Consultants, to submit a work plan for the off-site groundwater investigation. - K. Forster Consultant is awaiting disposal facility acceptance based on waste characterization sampling results. Remedial work is anticipated to begin in April. jeb (3/29/2018) 6/30/21: BCA for Site C224210 terminated due to lengthy delays. Sent request to James Ruggiero for a work plan to address remaining groundwater contamination. New attorney representing James. Maggie Macdonald, mmacdonald@sprlaw.com. - kmf"

Remarks: "phase 2 investigation."

All Materials:

Site ID:	355883
Operable Unit ID:	1113215
Operable Unit:	01
Material ID:	2103281
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	True

Site ID:	355883
Operable Unit ID:	1113215
Operable Unit:	01
Material ID:	2159416
Material Code:	1213A

UNIVERSAL USED AUTO PARTS INC (BROOKLYN) (Continued) **S107488576**

Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	True
Site ID:	355883
Operable Unit ID:	1113215
Operable Unit:	01
Material ID:	2159417
Material Code:	2645A
Material Name:	BTEX
Case No.:	Not reported
Material FA:	Oxygenates
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	True

AQ249 **1884 FLUSHING AVENUE** **NY LTANKS** **S102143431**
East **1884 FLUSHING AVENUE** **NY Spills** **N/A**
1/4-1/2 **RIDGEWOOD, NY**
0.483 mi.
2549 ft. **Site 2 of 2 in cluster AQ**

Relative:
Higher

Actual:
28 ft.

LTANKS:

Name:	1884 FLUSHING AVENUE
Address:	1884 FLUSHING AVENUE
City,State,Zip:	RIDGEWOOD, NY
Spill Number/Closed Date:	9307524 / 1995-03-31
Facility ID:	9307524
Site ID:	71544
Spill Date:	1993-09-21
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1995-03-31
SWIS:	4101
Investigator:	KSTANG
Referred To:	Not reported
Reported to Dept:	1993-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-09-22
Spill Record Last Update:	2003-10-30
Spiller Name:	Not reported
Spiller Company:	CHEEMA CONTRACT.
Spiller Address:	Not reported
Spiller County:	001

1884 FLUSHING AVENUE (Continued) **S102143431**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	67685
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "
Remarks:	"FIELD PORT - RAN DOWN STREET W/ RAIN WATER - SEWER AFFECTED OVERFILLED FIELD PORT - KOON TANG ON SITE."

All Materials:

Site ID:	71544
Operable Unit ID:	988605
Operable Unit:	01
Material ID:	393784
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	18-84 FLUSHING AVE.
Address:	18-84 FLUSHING AVE.
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9209246 / 1992-11-09
Facility ID:	9209246
Facility Type:	ER
DER Facility ID:	326181
Site ID:	161416
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	C4
SWIS:	4101
Spill Date:	1992-11-09
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1992-11-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	1992-11-09
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-11-10
Spill Record Last Update:	2007-01-26
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported

1884 FLUSHING AVENUE (Continued) **S102143431**

Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "DELIBERATELY DUMPING GASOLINE DOWN SEWER HAZ MAT ON SCENE DEP WILL BE RESPONDING NO CALL BACK NECESSARY"

All Materials:
Site ID: 161416
Operable Unit ID: 972898
Operable Unit: 01
Material ID: 406304
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

Name: 18-84 FLUSHING AVE.
Address: 18-84 FLUSHING AVE.
City,State,Zip: QUEENS, NY
Spill Number/Closed Date: 9209883 / 2004-04-12
Facility ID: 9209883
Facility Type: ER
DER Facility ID: 326181
Site ID: 161417
DEC Region: 2
Spill Cause: Unknown
Spill Class: D4
SWIS: 4101
Spill Date: 1992-11-24
Investigator: SJMILLER
Referred To: Not reported
Reported to Dept: 1992-11-24
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1992-11-24
Spill Record Last Update: 2007-01-26
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was S. MILLER CLOSED BY ROMMEL."
Remarks: ""

1884 FLUSHING AVENUE (Continued) **S102143431**

All Materials:

Site ID:	161417
Operable Unit ID:	973705
Operable Unit:	01
Material ID:	406914
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

250 South 1/4-1/2 0.487 mi. 2573 ft.

COGENT TRANSFER; LLC
105-115 THAMES STREET
BROOKLYN, NY 11237

NY SWF/LF **S126508458**
NY Financial Assurance **N/A**

Relative: Higher

Actual: 25 ft.

SWF/LF:

Name:	COGENT TRANSFER; LLC
Address:	105-115 THAMES STREET
City,State,Zip:	BROOKLYN, NY 11237
Flag:	ACTIVE
Region Code:	2
Phone Number:	7184561307
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Aziz Kahany
Contact Address:	105-115 Thames Street
Contact Addr2:	Not reported
Contact City,St,Zip:	Brooklyn, NY 11237
Contact Email:	azizkahany@yahoo.com
Contact Phone:	7184561307
Activity Desc:	Transfer station - permit
Activity Number:	[24T40]
Active:	Yes
East Coordinate:	590503
North Coordinate:	4506611
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	MSW (Residential/Institutional & Commercial);Corrugated Cardboard;Metals (Ferrous & Non-Ferrous)
Authorization #:	2-6104-00096/00002
Authorization Date:	6/3/2020
Expiration Date:	4/28/2021
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

COGENT TRANSFER; LLC (Continued) **S126508458**

NY Financial Assurance 1:

Name:	COGENT TRANSFER; LLC
Address:	105-115 THAMES STREET
City,State,Zip:	BROOKLYN, NY
Owner Name:	Nino Tristani
Region:	2
Estimate Type:	Closure
Estimate Amount:	136,000
Estimate Date:	03/01/2001
Mechanism:	Surety bond - Performance
Mechanism Amount:	165,000
Issue Date:	10/19/2010
Activity Number:	24T40
Activity Description:	z Retired - Transfer station - permit

AS251 **57-00 MASPETH AVE LLC** **NY SWF/LF** **U001835911**
NNE **5700 47TH ST** **NY UST** **N/A**
1/4-1/2 **MASPETH, NY 11378** **NY AST**
0.488 mi. **NY Spills**
2576 ft. **Site 1 of 2 in cluster AS**

Relative: **Lower**
Actual: **7 ft.**

SWF/LF:

Name:	PEBBLE LANE ASSOCIATES LLC
Address:	57-00 47TH STREET
City,State,Zip:	MASPETH, NY 11378
Flag:	ACTIVE
Region Code:	2
Phone Number:	7184562520
Owner Name:	US Concrete; Inc
Owner Type:	Private
Owner Address:	331 N. Main Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Euless, TX 76039
Owner Email:	Not reported
Owner Phone:	8178254105
Contact Name:	Gerard Weldon
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	gweldon@us-concrete.com
Contact Phone:	7184562520
Activity Desc:	C&D processing - registration
Activity Number:	[41W64]
Active:	Yes
East Coordinate:	590991
North Coordinate:	4508196
Accuracy Code:	2.1 - NYSDEC 100 m grid collection
Regulatory Status:	Registration
Waste Type:	Asphalt;Brick;Concrete;Rock;Soil (Clean);Glass;Metals (Ferrous);Metals (Non-Ferrous);Construction & Demolition Debris
Authorization #:	41W64
Authorization Date:	4/27/2009
Expiration Date:	Not reported
Operator Name:	Anthony Bruno
Operator Type:	Not reported
Laste Date:	5/5/2021

57-00 MASPETH AVE LLC (Continued) **U001835911**

UST:

Name:	57-00 MASPETH AVE LLC
Address:	5700 47TH ST
City,State,Zip:	MASPETH, NY 11378
Id/Status:	2-318744 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	12/16/2018
UTM X:	590958.14326
UTM Y:	4508126.22378
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	14712
Affiliation Type:	Mail Contact
Company Name:	57-00 MASPETH AVENUE, LLC
Contact Type:	Not reported
Contact Name:	ROSSANA BORTONE
Address1:	57-00 47TH STREET
Address2:	Not reported
City:	MASPETH
State:	NY
Zip Code:	11378
Country Code:	001
Phone:	(718) 456-8636
EMail:	PFIEFFER40@AOL
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-02-27

Site Id:	14712
Affiliation Type:	Facility Operator
Company Name:	57-00 MASPETH AVE LLC
Contact Type:	Not reported
Contact Name:	ROSSANA BORTONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 456-8636
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-12-16

Site Id:	14712
Affiliation Type:	Facility Owner
Company Name:	57-00 MASPETH AVENUE LLC
Contact Type:	OWNER
Contact Name:	ROSSANA BORTONE
Address1:	57-00 47TH STREET
Address2:	Not reported
City:	MASPETH
State:	NY

57-00 MASPETH AVE LLC (Continued) **U001835911**

Zip Code:	11378
Country Code:	001
Phone:	(718) 456-8636
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-02-27

Site Id:	14712
Affiliation Type:	Emergency Contact
Company Name:	5700 MASPETH AVENUE LLC
Contact Type:	Not reported
Contact Name:	ROSSANA BORTONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 456-8636
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-09-08

Tank Info:

Tank Number:	001
Tank ID:	16720
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	10/01/1985
Date Tank Closed:	09/19/2013
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel

Tightness Test Method:	21
Date Test:	12/21/2007
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	NRLOMBAR
Last Modified:	04/14/2017

Equipment Records:

D02 - Pipe Type - Galvanized Steel
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
I02 - Overfill - High Level Alarm
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground

57-00 MASPETH AVE LLC (Continued) **U001835911**

H05 - Tank Leak Detection - In-Tank System (ATG)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F02 - Pipe External Protection - Original Sacrificial Anode

Tank Number:	002
Tank ID:	16721
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	10/01/1985
Date Tank Closed:	12/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
F02 - Pipe External Protection - Original Sacrificial Anode

Tank Number:	003
Tank ID:	16722
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	10/01/1985
Date Tank Closed:	12/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

B00 - Tank External Protection - None

57-00 MASPETH AVE LLC (Continued) **U001835911**

C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F02 - Pipe External Protection - Original Sacrificial Anode
D00 - Pipe Type - No Piping

Tank Number: 004
Tank ID: 16723
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1080
Install Date: 10/01/1985
Date Tank Closed: 12/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D00 - Pipe Type - No Piping
F02 - Pipe External Protection - Original Sacrificial Anode

AST:
Name: 57-00 MASPETH AVE LLC
Address: 5700 47TH ST
City,State,Zip: MASPETH, NY 11378
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-318744
Program Type: PBS
UTM X: 590958.14326
UTM Y: 4508126.22378
Expiration Date: 12/16/2018
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:
Site Id: 14712
Affiliation Type: Mail Contact

57-00 MASPETH AVE LLC (Continued) **U001835911**

Company Name:	57-00 MASPETH AVENUE, LLC
Contact Type:	Not reported
Contact Name:	ROSSANA BORTONE
Address1:	57-00 47TH STREET
Address2:	Not reported
City:	MASPETH
State:	NY
Zip Code:	11378
Country Code:	001
Phone:	(718) 456-8636
EMail:	PFIEFFER40@AOL
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-02-27

Site Id:	14712
Affiliation Type:	Facility Operator
Company Name:	57-00 MASPETH AVE LLC
Contact Type:	Not reported
Contact Name:	ROSSANA BORTONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 456-8636
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-12-16

Site Id:	14712
Affiliation Type:	Facility Owner
Company Name:	57-00 MASPETH AVENUE LLC
Contact Type:	OWNER
Contact Name:	ROSSANA BORTONE
Address1:	57-00 47TH STREET
Address2:	Not reported
City:	MASPETH
State:	NY
Zip Code:	11378
Country Code:	001
Phone:	(718) 456-8636
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2014-02-27

Site Id:	14712
Affiliation Type:	Emergency Contact
Company Name:	5700 MASPETH AVENUE LLC
Contact Type:	Not reported
Contact Name:	ROSSANA BORTONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported

57-00 MASPETH AVE LLC (Continued) **U001835911**

State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 456-8636
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-09-08

Tank Info:

Tank Number:	005
Tank Id:	16724
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F02 - Pipe External Protection - Original Sacrificial Anode

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/01/1985
Capacity Gallons:	6000
Tightness Test Method:	14
Date Test:	11/22/2002
Next Test Date:	Not reported
Date Tank Closed:	03/08/2006
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	2
Tank Id:	235859
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G09 - Tank Secondary Containment - Modified Double-Walled

57-00 MASPETH AVE LLC (Continued) **U001835911**

(Aboveground)
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/03/2000
Capacity Gallons:	180
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	motor oil
Tank Number:	3
Tank Id:	235860
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
I00 - Overfill - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/03/2000
Capacity Gallons:	180
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017

57-00 MASPETH AVE LLC (Continued) **U001835911**

Material Name: waste oil/used oil

SPILLS:
Name: 57-00 47TH ST
Address: 57-00 47TH ST
City,State,Zip: MASPETH, NY
Spill Number/Closed Date: 9411004 / 1994-11-17
Facility ID: 9411004
Facility Type: ER
DER Facility ID: 125954
Site ID: 147965
DEC Region: 2
Spill Cause: Deliberate
Spill Class: C4
SWIS: 4101
Spill Date: 1994-11-17
Investigator: SMMARTIN
Referred To: Not reported
Reported to Dept: 1994-11-17
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Federal Government
Cleanup Ceased: 1994-11-17
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1994-12-09
Spill Record Last Update: 2004-03-29
Spiller Name: Not reported
Spiller Company: ISLAND TRANSPORTATION
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks: "NYC DEP WAS NOTIFIED"

All Materials:
Site ID: 147965
Operable Unit ID: 1004912
Operable Unit: 01
Material ID: 376868
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Oxygenate: Not reported

AS252 **ISLAND TRANS CORP** **NY LTANKS** **S104495815**
NNE **5700 47TH STREET** **N/A**
1/4-1/2 **MASPETH, NY**
0.488 mi.
2576 ft. **Site 2 of 2 in cluster AS**

Relative: **Lower**

Actual: **7 ft.**

LTANKS:

Name:	ISLAND TRANS CORP
Address:	5700 47TH STREET
City,State,Zip:	MASPETH, NY
Spill Number/Closed Date:	0709978 / 2007-12-28
Facility ID:	0709978
Site ID:	391172
Spill Date:	2007-12-18
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	bkfalvey
Referred To:	Not reported
Reported to Dept:	2007-12-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-12-18
Spill Record Last Update:	2008-06-30
Spiller Name:	CHRIS MALLOY
Spiller Company:	Not reported
Spiller Address:	5700 47TH STREET
Spiller County:	001
Spiller Contact:	CHRIS MALLOY
Spiller Phone:	(413) 572-1900
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	340805
DEC Memo:	"12/21/07 Received call from Sean Healy of Getty. He believes the vent line failed due to fitting at tank was loose. No contamination found. Metro Environmental will be testing line tonight. Will send test report and letter. bf 12/28/07 received fax from Laurie Jodice of Tyree. There was a crossover line that was not removed. Fitting for line was plugged and tank was restested by Metro Environmental and passed. Called Sean Healy and he told me no signs of petroleum contamination was found during repairs. He then transferred me to Laurie Jodice of Tyree who is the project manager. I told her I need test results and letter regarding contamination. She said that she will send letter and send test results when she gets them. Letter stating no visdible signs of petroleum contamination received by fax from L. Jodice. Received passing tightness test results. NFA. bf"
Remarks:	"PBS No: 2-318744"

All TTF:

Facility ID:	0709978
Spill Number:	0709978
Spill Tank Test:	2384326

ISLAND TRANS CORP (Continued) **S104495815**

Site ID:	391172
Tank Number:	Not reported
Tank Size:	4000
Material:	0008
EPA UST:	Not reported
UST:	True
Cause:	99
Source:	01
Test Method:	14
Test Method 2:	VacuTest
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	391172
Operable Unit ID:	1148233
Operable Unit:	01
Material ID:	2138722
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

253
WNW
1/4-1/2
0.490 mi.
2587 ft.

BKLYN UNION GAS /EQUITY WORKS **SEMS-ARCHIVE** **1003863854**
MASPETH & MORGAN AVE **NYD980532048**
BROOKLYN, NY 11222

Relative:
Higher

Actual:
24 ft.

SEMS Archive:

Site ID:	0201980
EPA ID:	NYD980532048
Name:	BKLYN UNION GAS /EQUITY WORKS
Address:	MASPETH & MORGAN AVE
Address 2:	Not reported
City,State,Zip:	BROOKLYN, NY 11222
Cong District:	12
FIPS Code:	36047
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	02
Site ID:	0201980
EPA ID:	NYD980532048
Site Name:	BKLYN UNION GAS /EQUITY WORKS
NPL:	N
FF:	N
OU:	00
Action Code:	VS

BKLYN UNION GAS /EQUITY WORKS (Continued) **1003863854**

Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1986-09-24 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse
Region:	02
Site ID:	0201980
EPA ID:	NYD980532048
Site Name:	BKLYN UNION GAS /EQUITY WORKS
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1986-09-05 04:00:00
Finish Date:	1986-09-24 04:00:00
Qual:	N
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0201980
EPA ID:	NYD980532048
Site Name:	BKLYN UNION GAS /EQUITY WORKS
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1981-06-01 04:00:00
Finish Date:	1981-06-01 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

254
West
1/4-1/2
0.492 mi.
2597 ft.

881-889 GRAND STREET DEVELOPMENT
885 GRAND ST
BROOKLYN, NY 11211

RCRA-LQG **1000458276**
NY LTANKS **NYD986936649**
NY MANIFEST

Relative:
Higher

Actual:
36 ft.

RCRA-LQG:

Date Form Received by Agency:	20180220
Handler Name:	881-889 GRAND STREET DEVELOPMENT
Handler Address:	885 GRAND ST
Handler City,State,Zip:	BROOKLYN, NY 11211
EPA ID:	NYD986936649
Contact Name:	CHARLES POWERS
Contact Address:	NEWTOWN RD
Contact City,State,Zip:	PLAINVIEW, NY 11803
Contact Telephone:	516-932-3228 101
Contact Fax:	516-932-3288
Contact Email:	CPOWERS@CNSENVIRO.COM
Contact Title:	PRESIDENT-CNS ENVIRONMENTAL
EPA Region:	02

881-889 GRAND STREET DEVELOPMENT (Continued) **1000458276**

Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	BROADWAY
Mailing City,State,Zip:	BRONX, NY 10463
Owner Name:	885 GRAND STREET CORP
Owner Type:	Private
Operator Name:	885 DEVELOPMENT LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No

881-889 GRAND STREET DEVELOPMENT (Continued) **1000458276**

Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	885 DEVELOPMENT LLC
Legal Status:	Private
Date Became Current:	20170601
Date Ended Current:	Not reported
Owner/Operator Address:	5925 BROADWAY
Owner/Operator City,State,Zip:	BRONX, NY 10463
Owner/Operator Telephone:	718-884-7676
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GEORGE ADOMAITES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	56-29 METROPOLITAN AVE
Owner/Operator City,State,Zip:	QUEENS, NY 11385
Owner/Operator Telephone:	718-366-1881
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GEORGE ADOMAITES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	56-29 METROPOLITAN AVE

881-889 GRAND STREET DEVELOPMENT (Continued) **1000458276**

Owner/Operator City,State,Zip:	QUEENS, NY 11385
Owner/Operator Telephone:	718-366-1881
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	885 GRAND STREET CORP
Legal Status:	Private
Date Became Current:	20040228
Date Ended Current:	Not reported
Owner/Operator Address:	5925 BROADWAY
Owner/Operator City,State,Zip:	BRONX, NY 10463
Owner/Operator Telephone:	718-884-7676
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	85 DEVELOPMENT LLC
Legal Status:	Private
Date Became Current:	20170601
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	885 GRAND STREET CORP
Legal Status:	Private
Date Became Current:	20040228
Date Ended Current:	Not reported
Owner/Operator Address:	5925 BROADWAY
Owner/Operator City,State,Zip:	BRONX, NY 10463
Owner/Operator Telephone:	718-884-7676
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	GEORGE ADOMAITES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	56-29 METROPOLITAN AVE
Owner/Operator City,State,Zip:	QUEENS, NY 11385
Owner/Operator Telephone:	718-366-1881
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	885 GRAND STREET CORP
Legal Status:	Private

881-889 GRAND STREET DEVELOPMENT (Continued) **1000458276**

Date Became Current:	20040228
Date Ended Current:	Not reported
Owner/Operator Address:	5925 BROADWAY
Owner/Operator City,State,Zip:	BRONX, NY 10463
Owner/Operator Telephone:	718-884-7676
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	GEORGE ADOMAITES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	56-29 METROPOLITAN AVE
Owner/Operator City,State,Zip:	QUEENS, NY 11385
Owner/Operator Telephone:	718-366-1881
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	85 DEVELOPMENT LLC
Legal Status:	Private
Date Became Current:	20170601
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	GEORGE ADOMAITES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	56-29 METROPOLITAN AVE
Owner/Operator City,State,Zip:	QUEENS, NY 11385
Owner/Operator Telephone:	718-366-1881
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	GEORGE ADOMAITES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	56-29 METROPOLITAN AVE
Owner/Operator City,State,Zip:	QUEENS, NY 11385
Owner/Operator Telephone:	718-366-1881
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

881-889 GRAND STREET DEVELOPMENT (Continued) **1000458276**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GEORGE ADOMAITES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	56-29 METROPOLITAN AVE
Owner/Operator City,State,Zip:	QUEENS, NY 11385
Owner/Operator Telephone:	718-366-1881
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20180220
Handler Name:	881-889 GRAND STREET DEVELOPMENT
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	19990708
Handler Name:	J & M AUTO REPAIRS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	J & M AUTO REPAIRS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	J & M AUTO REPAIRS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

881-889 GRAND STREET DEVELOPMENT (Continued) **1000458276**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20170616
Handler Name: 881-889 GRAND STREET DEVELOPMENT
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19910111
Handler Name: J & M AUTO REPAIRS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20170608
Handler Name: 881-889 GRAND STREET DEVELOPMENT
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 23611
NAICS Description: RESIDENTIAL BUILDING CONSTRUCTION

NAICS Code: 236116
NAICS Description: NEW MULTIFAMILY HOUSING CONSTRUCTION (EXCEPT OPERATIVE BUILDERS)

Facility Has Received Notices of Violations:
Violations: No Violations Found

881-889 GRAND STREET DEVELOPMENT (Continued) **1000458276**

Evaluation Action Summary:
Evaluations: No Evaluations Found

LTANKS:

Name:	J & M GAS
Address:	885 GRAND STREET
City,State,Zip:	BROOKLYN, NY 11211
Spill Number/Closed Date:	8901284 / 2008-07-21
Facility ID:	8901284
Site ID:	92038
Spill Date:	1989-05-09
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	2401
Investigator:	MJHAGGER
Referred To:	Not reported
Reported to Dept:	1989-05-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-05-09
Spill Record Last Update:	2008-07-22
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	30485
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL SEE SPILL NUMBER 8908532. 4/12/04-Vought-Spill transferred from Sullivan to Rommel as per Rommel. 2/2/07 - Haggerty - Alphonse Milo (718-388-7575) brought the property shortly after the tank test failures and is still owner today. He states he is will be building a parking lot on the subject property and all soil will be excavated for the foundation. I instructed Mr. Milo to contact the DEC as soon as possible because there is a good chance contamination is present. Spill to remain open 10/4/07 - Haggerty - received Phase II subsurface Investigation report from Al Milo. Phase II completed to satisfy the bank requirement. Report states that all soil samples and groundwater samples are below standards. MW's in the area surrounding the former tank field. No groundwater contamination was detected. PM stated that all tanks must be properly closed out in PBS wether tanks are registered or previously unknown and this spill will remain open until this is resolved. 07/21/08 - Haggerty: Spoke with Mrs. Milo. She stated that the PBS issue has been resovled. I checked the PBS

881-889 GRAND STREET DEVELOPMENT (Continued) **1000458276**

records to confirm. PBS# 2-478075. Spill closed"
Remarks: "THREE 550 GALLON TANKS FAIL HORNER-EZY CHEK - LR = -0.11982 GPH. NO DECISION ON ACTION TO BE TAKEN. ."

All TTF:
Facility ID: 8901284
Spill Number: 8901284
Spill Tank Test: 1535443
Site ID: 92038
Tank Number: Not reported
Tank Size: 0
Material: 1213A
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 92038
Operable Unit ID: 927414
Operable Unit: 01
Material ID: 449034
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Oxygenate: True

Site ID: 92038
Operable Unit ID: 927414
Operable Unit: 01
Material ID: 2135635
Material Code: 1213A
Material Name: MTBE (methyl-tert-butyl ether)
Case No.: 01634044
Material FA: Hazardous Material
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: True

NY MANIFEST:
Name: 881-889 GRAND STREET CORP
Address: 881-889 GRAND ST
City,State,Zip: BROOKLYN, NY 11211
Country: USA
EPA ID: NYD986936649

881-889 GRAND STREET DEVELOPMENT (Continued) **1000458276**

Facility Status:	Not reported
Location Address 1:	885 GRAND STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11211
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986936649
Mailing Name:	881-889 GRAND STREET CORP
Mailing Contact:	885 GRAND STREET CORP
Mailing Address 1:	881-885 GRAND ST
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11211
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJR986849705
Trans2 State ID:	Not reported
Generator Ship Date:	07/21/2017
Trans1 Recv Date:	07/21/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/21/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986936649
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	017578689JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

881-889 GRAND STREET DEVELOPMENT (Continued) **1000458276**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	53680
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

---

255 **RAPID ARMORED CORPORATION** **NY SHWS** **S123661630**
WSW **254 SCHOLES STREET** **NY Spills** **N/A**
1/2-1 **BROOKLYN, NY 11206**
0.543 mi.
2866 ft.

Relative:
Higher

Actual:
42 ft.

SHWS:

Name:	RAPID ARMORED CORPORATION
Address:	254 SCHOLES STREET
City,State,Zip:	BROOKLYN, NY 11206
Program:	HW
Site Code:	588258
Classification:	N
Region:	2
Acres:	0.630
HW Code:	224296
Record Add:	05/09/2019
Record Upd:	03/04/2021
Updated By:	KALEWAND
Site Description:	"Location: The subject site consists of 7 separate tax lots (block 3046, lots 22, 24, 26, 27, 47, 48 and 49) and is an irregularly shaped parcel. The following addresses are associated with the Site: 254-258 and 262-264 Scholes Street, and 249-257 Meserole Street. The Site fronts the south side of Scholes Street, extending south to Meserole Street, between Bushwick Avenue and Waterbury Street. The total Site area is approximately 27,500 square feet (0.63 acres). The site is currently used for vehicle maintenance for an armored car service. Site Features: The Site lots are currently occupied with warehouse-style buildings and a surface parking area. The site is surrounded by commercial properties to the south and east, Scholes Street to the north and a playground to the west. Current Zoning and Land Use: The site is zoned M1-1 (light manufacturing/industrial) and is located in an industrial business zone. Past Use of the Site: Historically, the site used for auto repair, machine repair, machine shops, printing, unspecified manufacturing and textile/knitting mill. Site Geology and Hydrogeology: The site is underlain by fill and sands extending to the groundwater interface. Fill layer ranges from 2 to 30 ft thick and consists of brown to red silty sand with concrete, brick and glass fragments. The sand is fine with few cobbles at shallower depths. Groundwater was measured below 32 ft depth."
Env Problem:	"Nature and Extent of Contamination: A limited subsurface

RAPID ARMORED CORPORATION (Continued) **S123661630**

investigation performed in early 2019 consisted of collection of soil, groundwater and soil vapor samples. Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, pesticides and PBCs. Soil No VOCs, SVOCs, metals, pesticides or PCBs were detected at concentrations exceeding the unrestricted use soil cleanup objectives. Groundwater VOCs were detected in groundwater at concentrations exceeding the applicable ambient water quality standards (AWQS), including: trichloroethene (TCE) at 16 parts per billion (ppb) compared to the AWQS of 5 ppb; cis-1,2-dichloroethene (DCE) at 220 ppb (AWQS is 5 ppb); vinyl chloride at 150 ppb (AWQS is 5 ppb); 1,2-dichlorobenzene at 410 ppb (AWQS is 3 ppb); and 1,4-dichlorobenzene at 160 ppb (AWQS is 3 ppb). Sub-slab soil vapor VOCs were detected at elevated concentrations including: tetrachloroethene (PCE) at 104 micrograms per cubic meter (ug/m3); TCE at 83 ug/m3; and chloroform at 33 ug/m3. "

Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	01
Owner Name:	James L. Sheero
Owner Company:	POM Realty Holdings, Inc.
Owner Address:	160 Oak Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Syosset, NY 11791
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	James L. Sheero
Owner Company:	Rapid Armored Corporation
Owner Address:	160 Oak Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Syosset, NY 11791
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

RAPID ARMORED CORPORATION (Continued) **S123661630**

SPILLS:

Name:	COMMERCIAL PROPERTY
Address:	254 SCHOLES ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1812027 / 2021-02-25
Facility ID:	1812027
Facility Type:	ER
DER Facility ID:	536422
Site ID:	583982
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	2019-03-06
Investigator:	SXWU
Referred To:	Not reported
Reported to Dept:	2019-03-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-03-06
Spill Record Last Update:	2021-03-30
Spiller Name:	MATTHEW CARROLL
Spiller Company:	COMMERCIAL PROPERTY
Spiller Address:	254 SCHOLES ST
Spiller Company:	999
Contact Name:	MATTHEW CARROLL
DEC Memo:	"3/6/2019 - Feng - Duty Desk. Left Matthew Carroll a message. Matthew Carroll Tenen Environmental 646-606-2332 3/7/2019 - Feng - Received email from Matthew Carroll that he is away on vacation and will call back on Monday. 3/11/2019 - Feng - Call back from Matt Carroll of Tenen Environmental. The site is currently used as an armored car facility. A realty broker company hired him to do a due diligent investigation to know the environmental liability. Unknown there is any development schedule. They installed soil borings. The groundwater samples collected revealed dissolved residual contamination and some chlorinated solvent, not too bad. Because of the cVOCs, they want to consider different program, maybe BCP. They will have a meeting tomorrow. He will update me on the owner's information, sending the Phase 1 and Phase 2 reports and decide whether to enter BCP. 03/13/19-Hiralkumar Patel. received Phase I and II reports from Matt. POM Realty Holdings, Inc. **property owner** 160 Oak Drive Syosset, New York 11791 Attn.: James L. Shreero Ph. (516) 880-8641 email: JShreero@payomatic.com during Phase I, review of available records revealed no evidence of recognized environmental conditions excepts following: - current use of portion of site for vehicle maintenance - historical use of the site for machine repair, machine shops, printing, unspecified manufacturing and textile/knit mill - historical use of the adjoining properties for machine shops, brass works, manufacturing, blacksmithing, auto wrecking, chemical

RAPID ARMORED CORPORATION (Continued) **S123661630**

filling, knit good processing and industrial-sized brewing facilities - presence of a large quantity generator of ignitable hazardous waste on an adjoining property summary of Phase II: - site includes lots # 22, 24, 26, 27, 47, 48 and 49 on block # 3046 - site lots are currently occupied with warehouse-style buildings, used for armored car activities including vehicle maintenance, and surface parking areas - site is underlain by fill and sands extending to the groundwater interface. fill layer ranges from 2 to 30 ft thick and consists of brown to red silty sand with concrete, brick and glass fragments. the sand is fine with few cobbles at shallower depths - installed six (6) soil borings (SB-1 through SB-6) to a depth of 35 ft bg, except boring SB-1 which was installed to a depth of 40 ft bg - signs (staining/odor/PID) of contamination were noted in boring SB-1 only - one soil sample was collected from each boring except boring SB-1 where two soil samples were collected - soil sample from 13-15 ft bg (with highest PID of 595.8 ppm) from SB-1 was lost in transit to the lab, so only one sample from 7-9 ft bg from SB-1 was analyzed - no contamination was noted in soil samples (even with 411.7 ppm on PID in sample from SB-1) - three (3) 1-in temporary wells (MW-1 through MW-3) were installed in soil borings SB-1, SB-2 and SB-3, respectively - well MW-1 was installed to a depth of 45 ft bg; wells MW-2 and MW-3 were installed to a depth of 40 ft bg - groundwater was measured at depths ranging from approx. 32.43 ft bg in MW-2 to 37.31 ft bg in MW-1 - measured 271.6 ppm on PID in headspace of well MW-1 - no visual evidence of petroleum impacts was observed in purged groundwater - minute petroleum VOC contamination (max. 26 ppb Xylene in MW-2) was noted in groundwater samples (even with 271.6 ppm in headspace of well MW-1) - installed four (4) soil-vapor points: probes SS-1 through SS-3 were installed within the existing buildings and probe SV-1 was installed in the exterior parking lot along Meserole St - soil-vapor probes were installed approx. 6 inches below the bottom of the existing concrete or asphalt slabs - minor petroleum VOCs noted in soil-vapor samples (max. 43.3 ug/m3 of Xylene in SS-1) - chlorinated VOCs noted in groundwater and soil-vapor samples groundwater analyticals (in ppb):
----------MW-1-----MW-2-----MW-3
1,1-Dichlorobenzene----------180------410------220
1,4-Dichlorobenzene----------69------160------120
Chlorobenzene----------27-------42-------38
cis-1,2-Dichloroethene----------7-------18------220
TCE----------16
Vinylchloride----------2-------12------150 soil-vapor
analyticals (in ug/m3): ----------SS-1------SS-3
Chloroform----------33---------8
1,1,1-Trichloroethane---------26--------46
TCE----------83--------30
PCE----------104--------15 alternate address
including all lots: 249-257 Meserole St, 254-264 Scholes St no PBS or other spills found. discussed with DEC Jane regarding detection of CVOCs in subsurface. she asked to refer case in couple of weeks if property owner does not meet Section A for BCP pre-application meeting. 12:23 PM:- left message for Matt and informed him about discussion with DEC Jane. 05/02/19-Hiralkumar Patel. 10:17 AM:- spoke with Matt who confirmed that BCP pre-app meeting has not happened yet. 10:36 AM:- sent p-site memo to DEC Jane. case assigned to DEC Jane. Site reclassed P to N 2/25/21. p-site closed out. Consulted with Patel Hiralkumar, no petroleum related concerns, okay to close."

RAPID ARMORED CORPORATION (Continued) **S123661630**

Remarks: "test confirm petro in gw. No tank in place. Investigation and c/u ongoing"

All Materials:
Site ID: 583982
Operable Unit ID: 1331652
Operable Unit: 01
Material ID: 2340864
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

---

256 **TECHNICAL METAL FINISHERS** **SEMS-ARCHIVE** **1003864057**
SSE **214 STARR STREET** **NY SHWS** **NYD980780894**
1/2-1 **BROOKLYN, NY 11237**
0.607 mi.
3203 ft.

Relative:
Higher

Actual:
34 ft.

SEMS Archive:
Site ID: 0202279
EPA ID: NYD980780894
Name: TECHNICAL METAL FINISHERS
Address: 214 STARR STREET
Address 2: Not reported
City,State,Zip: BROOKLYN, NY 11237
Cong District: 11
FIPS Code: 36047
FF: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:
Region: 02
Site ID: 0202279
EPA ID: NYD980780894
Site Name: TECHNICAL METAL FINISHERS
NPL: N
FF: N
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 1997-09-30 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 02
Site ID: 0202279
EPA ID: NYD980780894
Site Name: TECHNICAL METAL FINISHERS
NPL: N
FF: N

TECHNICAL METAL FINISHERS (Continued) **1003864057**

OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1984-09-01 05:00:00
Finish Date: 1984-09-01 05:00:00
Qual: Not reported
Current Action Lead: St Perf

Region: 02
Site ID: 0202279
EPA ID: NYD980780894
Site Name: TECHNICAL METAL FINISHERS
NPL: N
FF: N
OU: 00
Action Code: SI
Action Name: SI
SEQ: 1
Start Date: 1985-05-01 05:00:00
Finish Date: 1985-05-31 05:00:00
Qual: L
Current Action Lead: St Perf

Region: 02
Site ID: 0202279
EPA ID: NYD980780894
Site Name: TECHNICAL METAL FINISHERS
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: Not reported
Finish Date: 1984-09-01 05:00:00
Qual: L
Current Action Lead: St Perf

SHWS:
Name: TECHNICAL METAL FINISHERS
Address: 214 STARR STREET
City,State,Zip: BROOKLYN, NY
Program: HW
Site Code: 57764
Classification: C
Region: 2
Acres: Not reported
HW Code: 224008
Record Add: 11/18/1999
Record Upd: 03/23/2007
Updated By: dcwalsh
Site Description: "The Technical Metal Finishers Company was a plating company located in a light industrial/residential area. The company is out of business and the site is abandoned. The site was discovered in June 1982 when a fire occurred at the abandoned plant. The facility

TECHNICAL METAL FINISHERS (Continued) **1003864057**

	contained waste acids, caustics and cyanides stored in tanks and drums. The wastes contained in the tanks and drums were removed by a contractor hired by NYC Dept. of Environmental Protection. Clean up has been initiated by NYC Dept. of Environmental Protection through contract with Radiac Research Corporation. All tanks and debris have been removed from site and soil has been excavated. The building was demolished, and all work has been completed."
Env Problem:	"The site was delisted from the Registry as removal action conducted at the site has removed all hazardous waste."
Health Problem:	"NYSDOH has insufficient information to fully evaluate the potential for human exposures."
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	unknown
Disp Term:	unknown
Lat/Long:	40:42:22:0 / 73:55:22:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	1999-11-18 12:00:00
Updated By:	INITIAL
Own Op:	3
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	AL ROZELL
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	1
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	AL ROZELL
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
HW Code:	224008
Waste Type:	POSSIBLE CONTAMINATED FLOOR BOARDS
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224008
Waste Type:	AND SOIL AT SITE.
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	11
Cross Ref Type Code:	15
Cross Ref Type:	Congressional District
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2005-02-24 15:54:00
Updated By:	INITIAL
Crossref ID:	NYD980780894
Cross Ref Type Code:	05
Cross Ref Type:	EPA Site ID
Record Added Date:	1999-11-18 12:00:00

TECHNICAL METAL FINISHERS (Continued) **1003864057**

Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: 020
Cross Ref Type Code: 13
Cross Ref Type: Senate District
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2005-02-24 15:54:00
Updated By: INITIAL

257
NW
1/2-1
0.640 mi.
3377 ft.

FORMER KLINK COSMO CLEANERS **NY SHWS** **S109416412**
364 RICHARDSON STREET **N/A**
BROOKLYN, NY 11222

Relative:
Higher

Actual:
38 ft.

SHWS:
Name: FORMER KLINK COSMO CLEANERS
Address: 364 RICHARDSON STREET
City,State,Zip: BROOKLYN, NY 11222
Program: HW
Site Code: 405851
Classification: Significant threat to the public health or environment - action required.
Region: 2
Acres: 1.080
HW Code: 224130
Record Add: 10/28/2008
Record Upd: 07/26/2021
Updated By: HMDUDEK
Site Description: "Location The 1.08-acre site is located in the Greenpoint/East Williamsburg industrial section of Brooklyn, NY. The site is located on the southwest corner of the intersection of Vandervoort Avenue and Richardson Street. Please refer to Figures 1 2. Site Features The site is completely covered by a one-story brick building. Numerous other commercial and industrial properties are located to the north, south, and west of the site. The Greenpoint Little League fields and a National Grid energy facility are east of the site across Vandervoort Avenue. A small residential area is located 1-2 blocks north of the site. An eastbound on-ramp to the Brooklyn-Queens Expressway (I-278) is located 4 blocks to the north. Current Zoning and Land Use The site is zoned for (M1) manufacturing. Per NYC Planning, M1 districts typically include light industrial uses, such as woodworking shops, repair shops, and wholesale service and storage facilities. The site is currently used for sheet metal fabrication and offices. Past Use of the Site The Department began a Site Characterization in this area in2007 as part of a plume trackdown investigation (Meeker Avenue Plume Trackdown, Site ID No. 224121). This property was identified as a potential source of contamination based on its past use. Klink Cosmo Cleaners operated as a commercial dry cleaner from the 1950's to the mid 1990's. During that time, hazardous waste (spent halogenated solvents) was generated under EPA ID no. NYD000824334. Site Geology and Hydrogeology The site is underlain by urban fill unit (0.5-8 feet thick), a sand unit (approximately 100 feet thick) with varying textural features, and the Raritan (clay) Formation approximately 110 feet below ground surface (bgs). Groundwater is present approximately 35 feet bgs and flows north to northeast toward Newtown Creek. "
Env Problem: "Soil and groundwater were analyzed for volatile organic compounds

FORMER KLINK COSMO CLEANERS (Continued) **S109416412**

(VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Based upon investigations conducted to date, the primary contaminants of concern include VOCs and metals. Nature and Extent of Contamination: Soil The VOC source area was identified in the northeast corner of the current building at depths from 1 - 35 feet below ground surface (bgs). Tetrachloroethylene (PCE) was detected in soils on-site at concentrations up to 273 parts per million or ppm, exceeding the soil cleanup objective (SCO) for commercial use (150 ppm) and for the protection of groundwater (1.3 ppm). Trichloroethene (TCE) was detected in two on-site samples which slightly exceed the protection of groundwater SCO (0.47 ppm). PCE contaminated soil exceeding the protection of groundwater SCO extends off-site approximately ten feet to the north and east below the adjacent sidewalks of Vandervoort Avenue and Richardson Street. Metals contamination associated with urban fill was detected in shallow soil on-site. For example, lead was detected up to 2,680 ppm (exceeding the commercial SCO of 1,000 ppm) and arsenic up to 38.7 ppm (exceeding the commercial SCO of 16 ppm). The data does not indicate any off-site metal impacts in soil related to this site. Groundwater Based on the investigations conducted to date, the primary contaminants of concern detected in groundwater include PCE and trichloroethene (TCE). PCE has been found in shallow groundwater at concentrations up to 46,000 parts per billion or ppb (exceeding the groundwater standard of 5 ppb). PCE has also been found in deep groundwater (atop the Raritan clay) up to 4,500 ppb. TCE, a daughter product of PCE, was detected up to 2,100 ppb (exceeding the groundwater standard of 5 ppb). The groundwater plume extends north and east from the site to at least Lombardy street where it becomes co-mingled with contamination originating from other sites. Soil Vapor PCE has been found in soil vapor beneath the site at concentrations up to 2,090,000 micrograms per cubic meter, or ug/m^3. TCE has been found at concentrations up to 7,380 ug/m^3. Soil vapor intrusion sampling has been completed at twenty off-site structures. Actions described in Section 6.2 were needed to address potential exposure at twelve structures. "

Health Problem: "Direct contact with contaminants in the soil is unlikely because the site is covered by a building. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Sub?slab depressurization systems (SSDSs) have been installed in twelve off?site residential buildings to prevent the indoor air quality from being affected by the contamination in soil vapor in the area. SSDSs remain available to homeowners in the vicinity of the site who previously rejected the State s offer for a system. The on-site building does not have an SSDS; however, the potential for soil vapor intrusion is being addressed by the soil vapor extraction/air sparge system which is being constructed and will be operated on-site. "

Dump: False
Structure: True
Lagoon: False
Landfill: False

FORMER KLINK COSMO CLEANERS (Continued) **S109416412**

Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2008-10-28 12:21:00
Record Upd:	2016-03-02 09:54:00
Updated By:	DKHARRIN
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board #1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	4
Sub Type:	08
Owner Name:	Not reported
Owner Company:	AWL Industries
Owner Address:	364 Richardson Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	1
Sub Type:	01
Owner Name:	PAVLOVICH & COMPANY
Owner Company:	PAVLOVICH & COMPANY
Owner Address:	460 MORGAN AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11222-5706
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C04
Owner Name:	David Camara
Owner Company:	Brooklyn Public Library - Leonard Branch
Owner Address:	81 Devoe Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
HW Code:	224130
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224130
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224130
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224130
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224130

FORMER KLINK COSMO CLEANERS (Continued) **S109416412**

Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	224121
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2009-08-26 16:51:00
Record Updated:	2009-08-26 16:51:00
Updated By:	dkharrin
Crossref ID:	224129
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-10-31 14:34:00
Record Updated:	2008-10-31 14:34:00
Updated By:	MOBARRIE
Crossref ID:	224131
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-10-31 14:41:00
Record Updated:	2008-10-31 14:41:00
Updated By:	MOBARRIE
Crossref ID:	224132
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-10-31 14:41:00
Record Updated:	2008-10-31 14:41:00
Updated By:	MOBARRIE

258
NW
1/2-1
0.738 mi.
3896 ft.

Relative:
Higher

Actual:
35 ft.

GOODMAN BROTHERS CO STEEL DRUM DIV **1000190383**
18 DIVISION PLACE **NY SHWS** **NYD047683776**
BROOKLYN, NY 11222 **NY UST**
NY CBS
NY AST
NY CBS AST
NY Spills
RAATS
ICIS
FINDS
ECHO
NY AIRS
NY MANIFEST
NJ MANIFEST

RCRA-VSQG:

Date Form Received by Agency:	20070101
Handler Name:	GOODMAN BROTHERS STEEL DRUM CO INC
Handler Address:	18 DIVISION PLACE
Handler City,State,Zip:	BROOKLYN, NY 11222
EPA ID:	NYD047683776
Contact Name:	SIMON GOODMAN
Contact Address:	DIVISION PL
Contact City,State,Zip:	BROOKLYN, NY 11222
Contact Telephone:	718-782-3056
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	DIVISION PL
Mailing City,State,Zip:	BROOKLYN, NY 11222
Owner Name:	GOODMAN BROS STEEL DRUM CO INC
Owner Type:	Private
Operator Name:	GOODMAN BROS STEEL DRUM CO INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F017
Waste Description:	Not Defined
Waste Code:	U220
Waste Description:	BENZENE, METHYL- (OR) TOLUENE
Waste Code:	U239
Waste Description:	BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GOODMAN BROS STEEL DRUM CO INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	GOODMAN BROS STEEL DRUM CO INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GOODMAN BROS STEEL DRUM CO INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20060101
Handler Name: GOODMAN BROTHERS STEEL DRUM CO INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: GOODMAN BROTHERS STEEL DRUM CO INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800818
Handler Name: GOODMAN BROS STEEL DRUM CO INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940325
Handler Name: GOODMAN BROS STEEL DRUM CO INC
Federal Waste Generator Description: Large Quantity Generator

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960311
Handler Name: GOODMAN BROS. STEEL DRUM CO. INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980228
Handler Name: GOODMAN BROTHERS STEEL DRUM CO INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: GOODMAN BROS STEEL DRUM CO INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20021121
Handler Name: GOODMAN BROTHERS STEEL DRUM CO INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 42184
NAICS Description: INDUSTRIAL SUPPLIES WHOLESALERS

NAICS Code: 81131
NAICS Description: COMMERCIAL AND INDUSTRIAL MACHINERY AND EQUIPMENT (EXCEPT AUTOMOTIVE AND ELECTRONIC) REPAIR AND MAINTENANCE

NAICS Code: 81149
NAICS Description: OTHER PERSONAL AND HOUSEHOLD GOODS REPAIR AND MAINTENANCE

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19820902
Actual Return to Compliance Date: 19831206
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19870603
Actual Return to Compliance Date:	19871215
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19871022
Enforcement Identifier:	003
Date of Enforcement Action:	19870922
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYDEC
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 6500
Paid Amount: 6500
Final Count: 1
Final Amount: 6500

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	19990129
Actual Return to Compliance Date:	19990401
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	19990401
Enforcement Identifier:	000
Date of Enforcement Action:	19990301
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	R2
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	R2AHJ
Enforcement Responsible Sub-Organization:	RCB
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	20020103
Actual Return to Compliance Date:	20050126
Return to Compliance Qualifier:	Unverifiable
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20030618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	2-20020318-30
Enforcement Attorney:	SH
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20050126
Disposition Status:	DR
Disposition Status Description:	DROPPED
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person:	NYHHN
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	17500
Paid Amount:	8750
Final Count:	1
Final Amount:	17500

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	20020103
Actual Return to Compliance Date:	20050126
Return to Compliance Qualifier:	Unverifiable
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20020321
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	SH
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20050126
Disposition Status:	DR
Disposition Status Description:	DROPPED
Consent/Final Order Sequence Number:	Not reported

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19820902
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: Not reported
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19831206
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19930816
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2LG2
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19870603
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19871215
Scheduled Compliance Date: 19871022
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Evaluation Date:	20050126
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NOT A SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	NYJRI
Evaluation Responsible Sub-Organization:	CO
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19981210
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2AHJ
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19990401
Scheduled Compliance Date:	19990401
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20020103
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2AHJ
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20020315
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20020103
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20050126
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20020103
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20050126
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

SHWS:

Name:	FORMER GOODMAN BROTHERS STEEL DRUM CO.
Address:	18 DIVISION PLACE
City,State,Zip:	BROOKLYN, NY 11222
Program:	HW
Site Code:	505634
Classification:	Significant threat to the public health or environment - action required.
Region:	2
Acres:	0.670
HW Code:	224211
Record Add:	03/18/2015
Record Upd:	08/10/2020
Updated By:	HMDUDEK
Site Description:	"Location: The 0.67 acre site is located in the Greenpoint/East Williamsburg Industrial Area section of Kings County (Borough of Brooklyn, New York City). The site is located on the south side of Division Place between Kingsland and Debevoise Avenues. Site Features: The site is mostly covered with one-story buildings, with a storage yard located on the south side along Richardson Street. Current Zoning and Land Use: The site is zoned for manufacturing. The site is currently used for storage and light manufacturing. Numerous commercial, industrial, and residential properties surround the site. Past Use of the Site: Goodman Brothers began operations in 1909 as a re-conditioner and recycler of used steel drums for re-use or disposal. The Department's initial involvement with the facility was a RCRA inspection conducted in September 1982, as the company was a large quantity generator of hazardous waste above a sole-source aquifer. The company went out of business in June 2002. During the last 20 years of its operation, Goodman Brothers entered into one consent order with the USEPA (1983), and two consent orders with the Department (1987 and 2003), and agreed to pay penalties in the overall amount of $28,000 for numerous violations. Site Geology and Hydrogeology: The site is underlain by a sand/silty sand unit (~15-35' thick), a discontinuous sand/gravel unit within the

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

sand/silty sand unit (~5' thick), a discontinuous clayey silt unit within the sand/silty sand unit (~5' thick), and a sand unit below. Groundwater is approximately 15-20' below grade in the immediate vicinity of the site. Groundwater below the site flows toward the east in the direction of Newtown Creek (~3,600' away)."

Env Problem:	"Nature and Extent of Contamination: - Groundwater The primary contaminants in groundwater are Volatile Organic Compounds or VOCs and Per/ polyfluoroalkyl substances (PFAS). For example, the chlorinated VOC, cis-1,2 dichloroethene (DCE) was detected up to 61,000 parts per billion or ppb, compared to groundwater standard of 5 ppb. The PFAS compound Perfluorooctanoic acid (PFOA) was detected up to 5,100 parts per trillion or ppt, compared to a groundwater standard of 10 ppt. - Soil The primary contaminants in soil are VOCs and Polychlorinated Biphenyls (PCBs). For example, the chlorinated VOC, tetrachloroethene (PCE) was detected up to 1,200 parts per million or ppm. This exceeds the commercial Soil Cleanup Objective (SCO) of 150 ppm. Total PCBs were detected up on 130 ppm, which exceeds the commercial SCO of 1 ppm. Soil Vapor: Numerous VOCs were detected in soil vapor. For example, DCE was detected up to 5,600,000 micrograms per cubic meter (ug/m3). Numerous Significant Threat: The site poses a significant environmental threat due to ongoing releases of PCE (and its breakdown products), BTEX compounds, and PCBs from source areas into soil groundwater and soil vapor."
Health Problem:	"Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential for soil vapor intrusion in on-site and off-site structures exists and should be evaluated and may need to be evaluated for off-site structures. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2015-03-30 09:44:00
Record Upd:	2015-03-30 09:44:00
Updated By:	DKHARRIN
Own Op:	Document Repository
Sub Type:	C04
Owner Name:	David Camara
Owner Company:	Brooklyn Public Library - Leonard Branch
Owner Address:	81 Devoe Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
Own Op:	4
Sub Type:	E

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Owner Name:	Not reported
Owner Company:	Art Furniture Co.
Owner Address:	275 Richardson Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222-5641
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Kris Rutkowski
Owner Company:	King Tower Properties, Inc.
Owner Address:	18 Division Place
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Hieronima Rutkowska
Owner Company:	Richland Properties, Inc.
Owner Address:	275 Richardson Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222-5641
Owner Country:	United States of America
HW Code:	224211
Waste Type:	1,1,1-trichloroethane
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224211
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224211
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224211
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224211
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224211
Waste Type:	PCB aroclor 1260
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD047683776
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	2015-03-30 09:45:00
Record Updated:	2015-03-30 09:45:00
Updated By:	DKHARRIN
Crossref ID:	NYD047699061
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	2015-08-25 14:25:00
Record Updated:	2015-08-25 14:25:00

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Updated By: RXSCHICK

UST:

Name:	GOODMAN BROS STEEL DRUM
Address:	18 DIVISION PLACE
City,State,Zip:	BROOKLYN, NY 11222
Id/Status:	2-017620 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589559.19127
UTM Y:	4508238.80696
Site Type:	Other

Affiliation Records:

Site Id:	150
Affiliation Type:	Facility Owner
Company Name:	GOODMAN BROTHERS STEEL DRUM CO.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	18 DIVISION PLACE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 782-3056
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	150
Affiliation Type:	Mail Contact
Company Name:	GOODMAN BROTHERS STEEL DRUM CO.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	18 DIVISION PLACE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 782-3056
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	150
Affiliation Type:	Facility Operator
Company Name:	GOODMAN BROTHERS STEEL DRUM CO.
Contact Type:	Not reported
Contact Name:	IRVING GOODMAN
Address1:	Not reported
Address2:	Not reported

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 782-3056
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	150
Affiliation Type:	Emergency Contact
Company Name:	GOODMAN BROTHERS STEEL DRUM CO.
Contact Type:	Not reported
Contact Name:	MORTMAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 494-7704
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	27072
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	500
Install Date:	01/01/1997
Date Tank Closed:	01/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number:	002
Tank ID:	27073
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1100
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None

Tank Number:	003
Tank ID:	27074
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1100
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

CBS:

Name:	GOODMAN BROTHERS STEEL DRUM
Address:	18 DIVISION PLACE
City,State,Zip:	BROOKLYN, NY 11222
CBS Number:	2-000008
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	589528.43560
UTMY:	4508245.39054

AST:

Name:	GOODMAN BROTHERS STEEL DRUM
Address:	18 DIVISION PLACE
City,State,Zip:	BROOKLYN, NY 11222
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000008
Program Type:	CBS
UTM X:	589528.43560
UTM Y:	4508245.39054
Expiration Date:	N/A
Site Type:	Manufacturing (Other than Chemical)/Processing

Tank Info:

Tank Number:	00001
Tank Id:	182699
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/01/2000
Register:	True
Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Tank Number:	00001-A
Tank Id:	194176
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	02/01/2000
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/18/2012
Register:	True
Modified By:	LXZIELIN
Last Modified:	05/18/2012
Material Name:	Not reported

CBS AST:

CBS Number:	2-000008
ICS Number:	2-125161
PBS Number:	Not reported
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	IN SERVICE
Facility Type:	I
Telephone:	(718) 782-3038
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	02/03/2003
Total Capacity of All Active Tanks(gal):	3000
Operator:	RAY KRUZINSKI/FRANK CATALDI
Emergency Contact:	IRVING GOODMAN
Emergency Phone:	(212) 737-7181
Owner Name:	GOODMAN BROTHERS STEEL DRUM CO.
Owner Address:	18 DIVISION PL.
Owner City,St,Zip:	BROOKLYN, NY 11222
Owner Telephone:	(718) 782-3056
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	GOODMAN BROTHERS STEEL DRUM CO.
Mail Contact Addr:	18 DIVISION PL.
Mail Contact Addr2:	Not reported
Mail Contact Contact:	IRVING GOODMAN
Mail Contact City,St,Zip:	BROOKLYN, NY 11222
Mail Phone:	(718) 782-3056

Tank Id:	00001-A
CAS Number:	7647010
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	02/00
Tank Closed:	Not reported
Capacity (Gal):	3000
Chemical:	Hydrochloric acid
Tank Location:	Indoors, Belowground
Tank Type:	Fiberglass reinforced plastic [FRP]

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Total Tanks:	1
Tank Secret:	False
Tank Secondary Containment:	Cut-off Walls
Tank Error Status:	No Missing Data
Date Entered:	01/16/2001
Certified Date:	01/17/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Other
External Protection:	Other
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	Other
Pipe External:	Other
Pipe Flag:	Other
Leak Detection:	Interstitial Monitoring
Overfill Protection:	Product Level Gauge
Haz Percent:	31
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	11/02/92
Is It There:	False
Delinquent:	False
Date Expired:	02/03/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	11/07/2000

Tank Id:	00001
CAS Number:	7647010
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	00/00
Tank Closed:	02/00
Capacity (Gal):	5000
Chemical:	Hydrochloric acid
Tank Location:	Indoors, Belowground
Tank Type:	Fiberglass coated steel
Total Tanks:	1
Tank Secret:	False
Tank Secondary Containment:	Cut-off Walls
Tank Error Status:	No Missing Data
Date Entered:	02/03/1989
Certified Date:	01/17/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Fiberglass Liner (FRP
External Protection:	Fiberglass
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Leak Detection:	None
Overfill Protection:	Catch Basin
Haz Percent:	31
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	11/02/92
Is It There:	False
Delinquent:	False
Date Expired:	02/03/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	11/07/2000

SPILLS:

Name:	GOODMAN BROT STEEL DRUMS
Address:	18 DIVISION ST
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0109317 / 2003-02-13
Facility ID:	0109317
Facility Type:	ER
DER Facility ID:	161369
Site ID:	193547
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-12-20
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2001-12-20
CID:	199
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-20
Spill Record Last Update:	2003-02-13
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CRAIG GOODMAN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND ADMINISTRATIVE CLOSURE - AUSTIN"
Remarks:	"WHILE DOING MAINTAINCE ON A PUMP APPROX 1 QT OF WASTE WATER LEAKED OUT - ALL MATERAL CLEANED UP"

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

All Materials:

Site ID:	193547
Operable Unit ID:	846668
Operable Unit:	01
Material ID:	530525
Material Code:	0060A
Material Name:	wastewater
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Name:	GOODMAN BROT STEEL DRUMS
Address:	18 DIVISION PL
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0109316 / 2003-07-07
Facility ID:	0109316
Facility Type:	ER
DER Facility ID:	242844
Site ID:	300204
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	2401
Spill Date:	2001-12-20
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2001-12-20
CID:	199
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-20
Spill Record Last Update:	2003-07-07
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CRAIG GOODMAN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND "
Remarks:	"WHILE DOING ROUTINE MAINTAINCE ON COMPRESSOR 2-3 GAL OF MOTOR OIL SPILLED FROM MACHINERY"

All Materials:

Site ID:	300204
Operable Unit ID:	847677
Operable Unit:	01

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Material ID:	530524
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

RAATS:

Entry No:	1
Facility ID:	NYD047683776
Type:	Not reported
Docket No:	83-0211
Region:	02
Issue Date:	06/24/1983
Final Date:	01/31/1983
Status:	Consent Agreement/Final Order
Additional:	Not reported
Action ID:	2021
Action:	3008 (A)
Violation No:	Not reported
Viol No Cited:	1 122.22
Total No Cited:	Not reported
Reg Type:	CFR
Prop. Penalty:	5,000.00
Final Penalty:	4,000.00
Total Prop. Penalty:	7,500.00
Comments:	Not reported

Entry No:	1
Facility ID:	NYD047683776
Type:	Not reported
Docket No:	83-0211
Region:	02
Issue Date:	06/24/1983
Final Date:	01/31/1983
Status:	Consent Agreement/Final Order
Additional:	Not reported
Action ID:	2021
Action:	3008 (A)
Violation No:	Not reported
Viol No Cited:	2 265.31
Total No Cited:	Not reported
Reg Type:	CFR
Prop. Penalty:	1,500.00
Final Penalty:	4,000.00
Total Prop. Penalty:	7,500.00
Comments:	Not reported

Entry No:	1
Facility ID:	NYD047683776
Type:	Not reported
Docket No:	83-0211
Region:	02

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Issue Date: 06/24/1983
Final Date: 01/31/1983
Status: Consent Agreement/Final Order
Additional: Not reported
Action ID: 2021
Action: 3008 (A)
Violation No: Not reported
Viol No Cited: 3 265.173(A)
Total No Cited: Not reported
Reg Type: CFR
Prop. Penalty: 1,000.00
Final Penalty: 4,000.00
Total Prop. Penalty: 7,500.00
Comments: Not reported

ICIS:
Enforcement Action ID: NY000A0000261010015000328
FRS ID: 110000892017
Action Name: Not reported
Facility Name: GOODMAN BROS STEEL DRUM CO-18DIVISIONPL
Facility Address: 18 DIVISION PL
BROOKLYN, NY 11222
Enforcement Action Type: Administrative Order
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 3412
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.720775
Longitude in Decimal Degrees: 73.9414628
Permit Type Desc: Not reported
Program System Acronym: NY0000002610100150
Facility NAICS Code: 332439
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261010015000321
FRS ID: 110000892017
Action Name: Not reported
Facility Name: GOODMAN BROS STEEL DRUM CO-18DIVISIONPL
Facility Address: 18 DIVISION PL
BROOKLYN, NY 11222
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 3412
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.720775
Longitude in Decimal Degrees: 73.9414628
Permit Type Desc: Not reported
Program System Acronym: NY0000002610100150
Facility NAICS Code: 332439
Tribal Land Code: Not reported

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

FINDS:
Registry ID: 110000892017

Click Here:

Environmental Interest/Information System:
AIR EMISSIONS CLASSIFICATION UNKNOWN
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000190383
Registry ID:	110000892017
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000892017
Name:	GOODMAN BROS STEEL DRUM CO-18DIVISIONPL
Address:	18 DIVISION PLACE
City,State,Zip:	BROOKLYN, NY 11222

AIRS:

Name:	GOODMAN BROS STEEL DRUM CO-18DIVISIONPL
Address:	18 DIVISION PL
City,State,Zip:	BROOKLYN, NY 11222
DECID:	2610100150
Process ID:	Not reported
Latitude:	40.720775234
Longitude:	73.941462833
FIPS Code:	Not reported
Auth Type Code:	ATV
Permit Status:	Expired
Auth Status Code:	Not reported
Emissions:	Not reported
Issue date:	07/30/2002
Expired Date:	Not reported
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported
Permit Status:	Expired
Auth Status Code:	Not reported

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Emissions:	Not reported
Issue date:	01/12/2000
Expired Date:	07/30/2002
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported

NY MANIFEST:

Name:	FORMER GOODMAN BROS STEEL DRUM CO
Address:	18 DIVISION PLACE
City,State,Zip:	BROOKLYN, NY 11222
Country:	USA
EPA ID:	NYD047683776
Facility Status:	Not reported
Location Address 1:	18 DIVISION PLACE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11222
Location Zip 4:	5699

NY MANIFEST:

EPAID:	NYD047683776
Mailing Name:	FORMER GOODMAN BROS STEEL DRUM CO
Mailing Contact:	MICHAEL HAGGERTY
Mailing Address 1:	625 BROADWAY
Mailing Address 2:	Not reported
Mailing City:	ALBANY
Mailing State:	NY
Mailing Zip:	12233
Mailing Zip 4:	7016
Mailing Country:	USA
Mailing Phone:	5184029688

NJ MANIFEST:

EPA Id:	NYD047683776
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	X
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

GOODMAN BROTHERS CO STEEL DRUM DIV (Continued) **1000190383**

Manifest:

Manifest Number:	NJA5031614
EPA ID:	NYD047683776
Date Shipped:	01/27/2004
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	NJD002454544
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/27/2004
Date Trans2 Transported Waste:	01/30/2004
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/30/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	03090422
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

259
NNW
1/2-1
0.756 mi.
3994 ft.

FORMER LOMBARDY STREET LACQUER AND SOAP MFG.
171 LOMBARDY STREET
BROOKLYN, NY 11222

NY SHWS **S102637940**
NY CBS **N/A**
NY AST
NY CBS AST
NY MANIFEST

Relative:
Higher

Actual:
53 ft.

SHWS:

Name:	FORMER LOMBARDY STREET LACQUER AND SOAP MFG.
Address:	171 LOMBARDY STREET
City,State,Zip:	BROOKLYN, NY 11222
Program:	HW
Site Code:	486951
Classification:	Significant threat to the public health or environment - action

FORMER LOMBARDY STREET LACQUER AND SOAP MFG. (Continued) **S102637940**

required.
Region: 2
Acres: 0.460
HW Code: 224182
Record Add: 09/17/2013
Record Upd: 08/10/2020
Updated By: HMDUDEK
Site Description: "Location: The approximately 1/2 acre site is located in the Greenpoint/East Williamsburg Industrial Area section of Kings County (Borough of Brooklyn, New York City). The site is located on the northeast corner of the intersection of Lombardy Street and Varick Avenue. Site Features: The site is completely covered by two (2) masonry block buildings. Current Zoning and Land Use(s): The site is zoned for manufacturing. The site is currently utilized as a warehouse. Numerous commercial and industrial properties are located to the north, east, and west of the site. A National Grid energy facility is located south of the site across Lombardy Street. The Brooklyn-Queens Expressway (I-278) is located 1 block north of the site. A residential area is located 2 blocks southwest of the site. Newtown Creek is located 4 blocks east of the site. Past Use(s) of the Site: The Department began a Site Characterization in this area during the Summer of 2011 as part of a plume trackdown investigation (Meeker Avenue Plume Trackdown, DEC Site ID No. 224121). This particular area was specifically targeted for investigation based on its previous use as a lacquer storage facility in the 1930s, as a soap manufacturer from the early 1950s to 1989, and on data collected by the Department during investigations conducted at an adjacent site between 2007-2009 (ACME Steel - Brass Foundry) which indicated the presence of an additional source area along Varick Avenue between Anthony and Lombardy Streets. Site Geology and Hydrogeology: The site is underlain by a sand unit (~110' thick) with a discontinuous clayey silt/silty sand unit within the sand unit, and the Raritan formation. Groundwater is present at a depth of approximately 45-50' below ground surface in the vicinity of the site. Groundwater flows north towards Newtown Creek, which lies approximately 1,600' northeast of the site."
Env Problem: "Nature and Extent of Contamination: - Groundwater The primary contaminant of concern at the site is tetrachloroethene (PCE). PCE has been found in shallow groundwater at concentrations up to 8,400 ppb, and in deep groundwater up to 20,000 ppb, well above the Part 703.5 class GA standard of 5 ppb. - Soil PCE has been found in soil up to 23,000 ppm @ 1-1.5' below grade adjacent to a site-related cesspool, which is well above the soil cleanup objective for unrestricted use (1.3 ppm). Significant Threat: The site poses a significant environmental threat due to the ongoing release of PCE from source areas into soil and groundwater and a significant threat to public health due to the concentrations of PCE detected in groundwater and soil, in conjunction with the proximity of occupied structures."
Health Problem: "Direct contact with contaminants in the soil is unlikely because the site is covered with buildings and pavement. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the

FORMER LOMBARDY STREET LACQUER AND SOAP MFG. (Continued) **S102637940**

indoor air of buildings, is referred to as soil vapor intrusion. The potential for soil vapor intrusion to occur in on-site structures should be evaluated. In addition, off-site sampling indicates soil vapor intrusion is a concern for off-site buildings."

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-09-18 11:54:00
Record Upd: 2013-09-18 11:54:00
Updated By: DKHARRIN
Own Op: Document Repository
Sub Type: C05
Owner Name: Not reported
Owner Company: Brooklyn Community Board #1
Owner Address: 435 Graham Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11222
Owner Country: United States of America
Own Op: 1
Sub Type: 01
Owner Name: Not reported
Owner Company: 20 Rewe Street Ltd.
Owner Address: 885 Conklin Street
Owner Addr2: Not reported
Owner City,St,Zip: Farmingdale, NY 11735-2400
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C04
Owner Name: David Camara
Owner Company: Brooklyn Public Library - Leonard Branch
Owner Address: 81 Devoe Street
Owner Addr2: Not reported
Owner City,St,Zip: Brooklyn, NY 11211
Owner Country: United States of America
HW Code: 224182
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 224182
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

CBS:
Name: CHLORAL GROUP

FORMER LOMBARDY STREET LACQUER AND SOAP MFG. (Continued) **S102637940**

Address:	171 LOMBARDY ST
City,State,Zip:	BROOKLYN, NY 11222
CBS Number:	2-000036
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	590050.93977
UTMY:	4508620.25158

AST:

Name:	CHLORAL GROUP
Address:	171 LOMBARDY ST
City,State,Zip:	BROOKLYN, NY 11222
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000036
Program Type:	CBS
UTM X:	590050.93977
UTM Y:	4508620.25158
Expiration Date:	N/A
Site Type:	Unknown

Tank Info:

Tank Number:	00001
Tank Id:	183321
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1988
Capacity Gallons:	400
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

Tank Number:	00002
Tank Id:	183322
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1988
Capacity Gallons:	400
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

FORMER LOMBARDY STREET LACQUER AND SOAP MFG. (Continued) **S102637940**

Date Tank Closed:	Not reported
Register:	True
Modified By:	CBSInit
Last Modified:	03/21/2005
Material Name:	Not reported

CBS AST:

CBS Number:	2-000036
ICS Number:	2-125127
PBS Number:	Not reported
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	TEMPORARILY OUT-OF-SERVICE
Facility Type:	Not reported
Telephone:	(718) 388-2056
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	04/28/1991
Total Capacity of All Active Tanks(gal):	0
Operator:	KENNETH GOLDSTEIN
Emergency Contact:	FRANK TERRANOUA
Emergency Phone:	(516) 358-9276
Owner Name:	CHLORAL CHEMICAL CORP.
Owner Address:	171 LOMBARDY ST.
Owner City,St,Zip:	BROOKLYN, NY 11222
Owner Telephone:	(718) 388-2056
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	CHLORAL CHEMICAL CORP.
Mail Contact Addr:	171 LOMBARDY ST.
Mail Contact Addr2:	Not reported
Mail Contact Contact:	FRANK TERRANOUA
Mail Contact City,St,Zip:	BROOKLYN, NY 11222
Mail Phone:	(718) 388-2056

Tank Id:	00002
CAS Number:	7782505
Federal ID:	Not reported
Tank Status:	Not reported
Install Date:	06/88
Tank Closed:	00/00
Capacity (Gal):	400
Chemical:	Chlorine
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	Other
Tank Error Status:	2
Date Entered:	04/28/1989
Certified Date:	04/28/1989
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Unknown
Pipe Internal:	Not reported

FORMER LOMBARDY STREET LACQUER AND SOAP MFG. (Continued) **S102637940**

Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	02/12/91
Is It There:	False
Delinquent:	False
Date Expired:	04/28/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	02/12/1991

Tank Id:	00001
CAS Number:	7782505
Federal ID:	Not reported
Tank Status:	Not reported
Install Date:	06/88
Tank Closed:	00/00
Capacity (Gal):	400
Chemical:	Chlorine
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	Other
Tank Error Status:	2
Date Entered:	04/28/1989
Certified Date:	04/28/1989
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Unknown
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6101
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	02/12/91
Is It There:	False
Delinquent:	False
Date Expired:	04/28/91

FORMER LOMBARDY STREET LACQUER AND SOAP MFG. (Continued) **S102637940**

Owner Mark: 1
Certificate Needs to be Printed: False
Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 02/12/1991

NY MANIFEST:
Name: LOMBARDY STREET SOAP & LACQUER MANUFACTURING
Address: 171 LOMBARDY ST
City,State,Zip: BROOKLYN, NY 11222
Country: USA
EPA ID: NYR000220129
Facility Status: Not reported
Location Address 1: 171 LOMBARDY ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: BROOKLYN
Location State: NY
Location Zip: 11222
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000220129
Mailing Name: LOMBARDY STREET SOAP & LACQUER MANUFACTURING
Mailing Contact: LOMBARDY STREET SOAP & LACQUER MANUFACTURING
Mailing Address 1: 171 LOMBARDY ST
Mailing Address 2: Not reported
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11222
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYR000191726
Trans2 State ID: PAD982661381
Generator Ship Date: 11/03/2017
Trans1 Recv Date: 11/03/2017
Trans2 Recv Date: 11/06/2017
TSD Site Recv Date: 11/13/2017
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000220129
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: RID040098352
TSDF ID 2: Not reported
Manifest Tracking Number: 009987450FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N

FORMER LOMBARDY STREET LACQUER AND SOAP MFG. (Continued) **S102637940**

Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

260
NW
1/2-1
0.775 mi.
4091 ft.

95 LOMBARDY ST./ACME ARCH. PRODS., INC. **NY SHWS U003652054**
95 LOMBARDY ST **NY UST N/A**
BROOKLYN, NY 11222

Relative:
Higher

Actual:
45 ft.

SHWS:

Name:	ACME STEEL/METAL WORKS
Address:	95 LOMBARDY STREET
City,State,Zip:	BROOKLYN, NY 11222
Program:	HW
Site Code:	405853
Classification:	Significant threat to the public health or environment - action required.
Region:	2
Acres:	1.010
HW Code:	224131
Record Add:	10/28/2008
Record Upd:	03/25/2021
Updated By:	HMDUDEK
Site Description:	"Location: The 1.01 acre site is located in the Greenpoint/East Williamsburg Industrial Area section of Kings County (Borough of Brooklyn, New York City). The site is located on the east side of Vandervoort Avenue between Anthony and Lombardy Streets. Site Features: The site is completely covered by one (1) two-story and three (3) one-story brick buildings. The site is surrounded by other commercial and industrial properties. Sergeant William Dougherty Playground is located immediately north of the site across Anthony Street, and the eastbound on-ramp to the Brooklyn-Queens Expressway (I-278) is located one block to the north. A small residential area

95 LOMBARDY ST./ACME ARCH. PRODS., INC. (Continued) **U003652054**

is located one block south of the site. Current Zoning/Use(s): The site is zoned for manufacturing. The site is currently used as a granite warehouse and showroom at 95 Lombardy Street, and a paper distribution office and a kitchen cabinet warehouse/showroom at 46 Anthony Street. Historical Use(s): The Department began a Site Characterization in this area during the Spring of 2007 as part of a plume trackdown investigation (Meeker Avenue Plume Trackdown, DEC Site ID No. 224121). This particular location was specifically targeted for investigation based on Sanborn fire insurance map data indicating that the site was utilized as a metal fabricator and painting facility from the 1930's to the late 2000's, and a Department database which lists the site as a generator of F001 waste (spent halogenated solvents used in de-greasing). Site Geology and Hydrogeology: The site is underlain by a fill unit (0.5-9' thick), a sand/silty sand unit (~100' thick), a discontinuous clay/silt unit (~1-10' thick) within the sand/silty sand unit at various depths within the site area, a sand and gravel unit (~5' thick), and the Raritan Formation (~120-125' below ground surface). Groundwater is approximately 35-45' below ground surface in the vicinity of the site. Groundwater flows northeast toward Newtown Creek, which lies approximately 2,500' northeast of the site."

Env Problem: "Nature and Extent of Contamination: - Groundwater The primary contaminant of concern at the site is trichloroethene (TCE). TCE has been found on-site in shallow groundwater at concentrations up to 66,000 ppb, and in deep groundwater at concentrations up to 70,000 parts per billion or ppb, exceeding Part 703.5 class GA standards (5 ppb). Concentrations of tetrachloroethene (up to 8,000 ppb) and 1,2-dichloroethene (3,200 ppb) have also been found above their respective Part 703.5 class GA standards (5 ppb each). - Soil TCE was detected in soil at 2.3 parts per million or ppm in one sample (exceeding the unrestricted Soil Cleanup Objective). - Soil Vapor and Indoor Air Concentrations of PCE in soil vapor have been found up to 3,100 ug/m^3. Concentrations of TCE in soil vapor have been found up to 4,500 ug/m^3, and in indoor air up to 13 ug/m^3. Significant Threat: The site poses a significant environmental threat due to ongoing releases of TCE from source areas into soil and groundwater."

Health Problem: "Exposure to site-related contamination in drinking water and soil is unlikely since area homes and businesses are supplied with public water and contaminants are below the ground surface. Since the possibility exists for vapors from site-related chemicals to migrate into nearby homes and businesses, soil vapor intrusion sampling will continue in the area and data evaluated as they become available. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2008-10-28 12:21:00
Record Upd: 2013-09-20 14:01:00
Updated By: ldennist
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported

95 LOMBARDY ST./ACME ARCH. PRODS., INC. (Continued) **U003652054**

Owner Company:	Brooklyn Community Board #1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	4
Sub Type:	01
Owner Name:	PAUL BURDYN
Owner Company:	ACME ARCHITECTURAL PRODUCTS, INC.
Owner Address:	251 LOMBARDY STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11222
Owner Country:	United States of America
Own Op:	1
Sub Type:	01
Owner Name:	MAUREEN BABIS
Owner Company:	NYC IDA
Owner Address:	110 WILLIAM STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10038
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C04
Owner Name:	David Camara
Owner Company:	Brooklyn Public Library - Leonard Branch
Owner Address:	81 Devoe Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
HW Code:	224131
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	224130
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-10-31 14:41:00
Record Updated:	2008-10-31 14:41:00
Updated By:	MOBARRIE
Crossref ID:	224132
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-10-31 14:42:00
Record Updated:	2008-10-31 14:42:00
Updated By:	MOBARRIE
Crossref ID:	224121
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2009-01-30 12:36:00
Record Updated:	2009-01-30 12:36:00
Updated By:	JAAVERSA
Crossref ID:	224129
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-10-31 14:34:00
Record Updated:	2008-10-31 14:34:00
Updated By:	MOBARRIE

95 LOMBARDY ST./ACME ARCH. PRODS., INC. (Continued) **U003652054**

UST:

Name:	95 LOMBARDY ST./ACME ARCH. PRODS., INC.
Address:	95 LOMBARDY ST
City,State,Zip:	BROOKLYN, NY 11222
Id/Status:	2-603942 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589779.31460
UTM Y:	4508524.42989
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	25835
Affiliation Type:	Facility Owner
Company Name:	WHITEHEAD COMPANY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	513 PORTER AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 384-7800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25835
Affiliation Type:	Mail Contact
Company Name:	ACME ARCHITECTURAL PRODUCTS, INC.
Contact Type:	Not reported
Contact Name:	MILDRED OLSEN
Address1:	513 PORTER AVENUE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 384-7800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25835
Affiliation Type:	Facility Operator
Company Name:	95 LOMBARDY ST./ACME ARCH. PRODS., INC.
Contact Type:	Not reported
Contact Name:	ACME ARCH PRODS., INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

95 LOMBARDY ST./ACME ARCH. PRODS., INC. (Continued) **U003652054**

Zip Code:	Not reported
Country Code:	001
Phone:	(718) 384-7800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25835
Affiliation Type:	Emergency Contact
Company Name:	WHITEHEAD COMPANY
Contact Type:	Not reported
Contact Name:	WILLIAM MCDONNELL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 384-7800
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank ID:	56116
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	8500
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I05 - Overfill - Vent Whistle
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G08 - Tank Secondary Containment - Flexible Internal Lining (Bladder)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

95 LOMBARDY ST./ACME ARCH. PRODS., INC. (Continued) **U003652054**

Tank Number:	2
Tank ID:	56117
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1080
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TRANSLAT
Last Modified:	04/14/2017

Equipment Records:

I05 - Overfill - Vent Whistle
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
G08 - Tank Secondary Containment - Flexible Internal Lining (Bladder)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

AT261 **FORMER ACME STEEL PARTITION CO.** **NY SHWS** **S118950564**
NNW **513 PORTER AVENUE** **N/A**
1/2-1 **BROOKLYN, NY 11222**
0.826 mi.
4361 ft. **Site 1 of 2 in cluster AT**

Relative:
Higher

Actual:
50 ft.

SHWS:

Name:	FORMER ACME STEEL PARTITION CO.
Address:	513 PORTER AVENUE
City,State,Zip:	BROOKLYN, NY 11222
Program:	HW
Site Code:	494893
Classification:	P
Region:	2
Acres:	Not reported
HW Code:	224192
Record Add:	05/14/2014
Record Upd:	03/03/2020
Updated By:	JHOCONNE

Site Description: "Location: The site is located at 513 Porter Avenue in the Greenpoint section of the Borough of Brooklyn. It is bounded by Cherry Street to the north, Porter Avenue to the east, and Anthony Street to the south. Site Features: The site was once occupied by 5 contiguous, 1-story masonry construction buildings with an area of 39,000 sq. ft. (181.95 ft. x 200 ft.) constructed in 1950 (now demolished). Sergeant William Dougherty Playground was located immediately west of the site (now partially demolished and closed). The eastbound on-ramp to the

FORMER ACME STEEL PARTITION CO. (Continued) **S118950564**

Brooklyn-Queens Expressway (I-278) is located immediately north of the site. A small residential area is located two block south of the site. Current Zoning and Land Use: The site is located in a manufacturing area. The site was used as a staging area for equipment and materials as part of the Kosciuszko Bridge replacement project. Past Use of the Site: The site was operated by the ACME Steel Partition Company until 2007 when operations at the property ceased. The property was acquired via eminent domain by the NYSDOT as part of the Kosciuszko Bridge replacement project. Site Geology and Hydrogeology: The site is underlain by a fill unit (0.5-9' thick), a sand/silty sand unit (~100' thick), a discontinuous clay/silt unit (~1-10' thick) within the sand/silty sand unit at various depths within the site area, a sand and gravel unit (~5' thick), and the Raritan Formation (~120-125' below ground surface). Groundwater is approximately 35-45' below ground surface in the vicinity of the site. Groundwater flows northeast toward Newtown Creek, which lies approximately 2,500' northeast of the site."

Env Problem:	"Nature and Extent of Contamination: Soil - PCE has been found in on-site soils at concentrations up to 2.2 ppm, which is slightly above the soil cleanup objective for unrestricted use (1.3 ppm). Lead had been found up to 6,400 ppm, which is well above the soil cleanup objective for restricted residential use (400 ppm). Lead-hazardous soils were also identified on-site. Groundwater - The primary contaminants of concern at the site are tetrachloroethene (PCE), trichloroethene (TCE), and lead. PCE (up to 70 parts per billion, or ppb), TCE (up to 80 ppb), and lead (up to 254 ppb) have been found at concentrations slightly above their Part 703.5 class GA standards of 5, 5, and 25 ppb respectively. Soil Vapor - PCE has been found in soil vapor at concentrations up to 11,000 micrograms per cubic meter (ug/m3). TCE has been found at concentrations up to 106 ug/m3. "
Health Problem:	"As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	B99
Owner Name:	Robert Adams
Owner Company:	NYS Dept of Transportation
Owner Address:	1 Hunters Point Plaza
Owner Addr2:	47-40 21st Street; Real Estate Rm 317
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported

FORMER ACME STEEL PARTITION CO. (Continued) **S118950564**

Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

AT262 **ACME STEEL/BRASS FOUNDRY** **NY SHWS** **S118950559**
NNW **72 ANTHONY STREET** **N/A**
1/2-1 **BROOKLYN, NY 11222**
0.826 mi.
4361 ft. **Site 2 of 2 in cluster AT**

Relative:
Higher

Actual:
50 ft.

SHWS:
Name: ACME STEEL/BRASS FOUNDRY
Address: 72 ANTHONY STREET
City,State,Zip: BROOKLYN, NY 11222
Program: HW
Site Code: 405855
Classification: Significant threat to the public health or environment - action required.
Region: 2
Acres: 1.210
HW Code: 224132
Record Add: 10/28/2008
Record Upd: 10/28/2020
Updated By: HMDUDEK
Site Description: "Location: The 1.21 acre site is located in the Greenpoint/East Williamsburg Industrial Area section of Kings County (Borough of Brooklyn, New York City). The site is located on the east side of Porter Avenue between Anthony and Lombardy Streets. Site Features: The site consists of one 1-story brick building, three 1-story metal sheds, two truck parking areas and a bus parking lot. The site is surrounded by other commercial and industrial properties. A large National Grid energy facility is located one block south of the site across Lombardy Street. Sergeant William Dougherty Playground is located one block northwest of the site across Anthony Street, and the elevated Brooklyn-Queens Expressway (I-278) is located one block to the north. A small residential area is located one block southwest of the site. Current Zoning/Use(s): The site is zoned for manufacturing. The site is currently used as a marble and granite distribution warehouse and and a City-Wide truck maintenance shop at 498 Porter Avenue. Historical Use(s): The Department began a Site Characterization in this area during the Spring of 2007 as part of a plume trackdown investigation (Meeker Avenue Plume Trackdown, DEC Site ID No. 224121). This particular location was specifically targeted for investigation based on Sanborn fire insurance map data indicating that the site was utilized as a brass foundry from the 1960's to 1993, and a Department database which lists the site as a generator of F001 waste (spent halogenated solvents used in de-greasing). This investigation was conducted in several phases, and was completed in the Summer of 2009. Site Geology and Hydrogeology: The site is underlain by a fill unit (0.5-9' thick), a sand/silty sand unit (~110' thick), a discontinuous clay/silt unit (~1-10' thick) within the sand/silty sand unit at various depths within the site area, a sand and gravel unit (~5' thick), and the Raritan Formation (~130-135' below ground surface). Groundwater is approximately 45-55' below ground surface in the vicinity of the

ACME STEEL/BRASS FOUNDRY (Continued) **S118950559**

	site. Groundwater flows northeast toward Newtown Creek, which lies approximately 2,000' northeast of the site."
Env Problem:	"Nature and Extent of Contamination: - Groundwater The primary contaminant of concern at the site is tetrachloroethene (PCE). PCE has been detected up to 1,800 parts per billion or ppb (compared to a groundwater standard of 5 ppb). - Soil PCE has been found in on-site soils at concentrations up to 220 parts per million or ppm (compared to a commercial use soil cleanup objective of 150 ppm). - Soil Vapor Concentrations of PCE have been found up to 19,000 ug/m^3. Concentrations of TCE have been found up to 1,300 ug/m^3. "
Health Problem:	"Exposure to site-related contamination in drinking water and soil is unlikely since area homes and businesses are supplied with public water and contaminants are below the ground surface. Since the possibility exists for vapors from site-related chemicals to migrate into nearby homes and businesses, soil vapor intrusion sampling will continue in the area and data evaluated as they become available. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2008-10-28 10:35:00
Record Upd:	2015-02-27 08:53:00
Updated By:	DKHARRIN
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Brooklyn Community Board #1
Owner Address:	435 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11222
Owner Country:	United States of America
Own Op:	1
Sub Type:	01
Owner Name:	MAUREEN BABIS
Owner Company:	NYC IDA
Owner Address:	110 WILLILAM STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10038
Owner Country:	United States of America
Own Op:	4
Sub Type:	01
Owner Name:	PAUL BURDYN
Owner Company:	ACME ARCHITECTURAL PRODUCTS, INC.
Owner Address:	251 LOMBARDY STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	BROOKLYN, NY 11222
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C04
Owner Name:	David Camara
Owner Company:	Brooklyn Public Library - Leonard Branch
Owner Address:	81 Devoe Street

ACME STEEL/BRASS FOUNDRY (Continued) **S118950559**

Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11211
Owner Country:	United States of America
HW Code:	224132
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224132
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	224132
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	224129
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-10-31 14:34:00
Record Updated:	2008-10-31 14:34:00
Updated By:	MOBARRIE
Crossref ID:	224130
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-10-31 14:41:00
Record Updated:	2008-10-31 14:41:00
Updated By:	MOBARRIE
Crossref ID:	224131
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2008-10-31 14:42:00
Record Updated:	2008-10-31 14:42:00
Updated By:	MOBARRIE
Crossref ID:	224121
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2009-01-30 12:36:00
Record Updated:	2009-01-30 12:36:00
Updated By:	JAAVERSA

263
WSW
1/2-1
0.827 mi.
4367 ft.

TOP HAT CLEANERS
152 GRAHAM AVE
BROOKLYN, NY 11206

RCRA-VSQG **1004758111**
NY SHWS **NYD986982908**
ICIS
US AIRS
NY MANIFEST

Relative:
Higher

Actual:
27 ft.

RCRA-VSQG:

Date Form Received by Agency:		20070101
Handler Name:	TOP HAT CLEANERS	
Handler Address:		152 GRAHAM AVE
Handler City,State,Zip:		BROOKLYN, NY 11206
EPA ID:		NYD986982908
Contact Name:		REINA DIAZ
Contact Address:		GRAHAM AVE
Contact City,State,Zip:		BROOKLYN, NY 11206
Contact Telephone:		718-388-2611
Contact Fax:		Not reported
Contact Email:		Not reported

TOP HAT CLEANERS (Continued) **1004758111**

Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	GRAHAM AVE
Mailing City,State,Zip:	BROOKLYN, NY 11206
Owner Name:	REINA DIAZ
Owner Type:	Private
Operator Name:	REINA DIAZ
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported

TOP HAT CLEANERS (Continued) **1004758111**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D002
Waste Description:	CORROSIVE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	REINA DIAZ
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	37-49 95TH ST
Owner/Operator City,State,Zip:	JACKSON HEIGHTS, NY 11372
Owner/Operator Telephone:	718-458-5540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	REINA DIAZ
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	37-49 95TH ST
Owner/Operator City,State,Zip:	JACKSON HEIGHTS, NY 11372
Owner/Operator Telephone:	718-458-5540
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	REINA DIAZ
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	37-49 95TH ST
Owner/Operator City,State,Zip:	JACKSON HEIGHTS, NY 11372
Owner/Operator Telephone:	718-458-5540

TOP HAT CLEANERS (Continued) **1004758111**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20060101
Handler Name: TOP HAT CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: TOP HAT CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970206
Handler Name: TOP HAT CLEANERS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

TOP HAT CLEANERS (Continued) **1004758111**

SHWS:
Name: TOP HAT CLEANERS
Address: 152 GRAHAM AVE.
City,State,Zip: BROOKLYN, NY 11206
Program: HW
Site Code: 504341
Classification: N
Region: 2
Acres: 0.057
HW Code: 224208
Record Add: 02/03/2015
Record Upd: 07/20/2021
Updated By: JHOCONNE
Site Description: "Location: The Site is located at 152 Graham Avenue in the Borough of Brooklyn, Kings County, NY. The site is located in the East Williamsburg section of Brooklyn, New York. The property is bordered by Graham Avenue on the west, by a three-story mixed commercial/residential building to the north, by a four-story mixed commercial/residential building and a three-story mixed commercial/residential building to the south, and by a four-story residential building to the east. The three-story building located to the southeast of the site also has a dry cleaner on the first floor. Site Features: The 2,500 square foot (0.057 acre) site parcel is occupied by a three-story building built in 1920. The site parcel also contains an open yard area behind (east of) the structure. The first floor is occupied by a dry cleaner and the upper two floors are occupied by residential apartments. Current Zoning and Land Use: The current site use is a dry cleaner (Top Hat Cleaners) on the first floor with residential apartments on the second and third floors. Past Use of the Site: According to the historical records, a dry cleaner has occupied the 152 Graham Ave location since approximately 1960. A Phase I study at the adjacent property (154 Graham Avenue) identified current and prior occupants of the ground floor retail space (pastry shop, shoe retailer and moving company, among others) which were not likely to be a source for chlorinated VOC impacts beneath the site. The report identifies the dry cleaner at 152 Graham Avenue (Top Hat Cleaners) as the most likely source of the contaminants identified in soil vapor. Site Geology and Hydrogeology: The site elevation is approximately 27 feet above mean sea level. Soil lithology consists of two main types of soils. The first soil type was fill material that consisted of fine to medium sand to silt with fine to coarse gravel and traces of brick and other miscellaneous debris. The second type was natural material composed of fine to coarse sand to silt with fine to coarse gravel and little clay. Groundwater was encountered between 17.5 feet and 22.5 feet below ground surface. Groundwater flow was determined to be in the north to northwest direction. Site is transferred and being remediated under BCP Site No. C224208."
Env Problem: "Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs). Based upon investigations conducted to date, the primary contaminant of concern is tetrachloroethene (PCE). Soil - Sampling of soil beneath and behind the site structure was limited due to inability to access the area with a drill rig. Sample results from other media indicate that a source area of higher contaminant concentrations may be present beneath the site structure. Two detections of PCE were observed in soil borings advanced during the Site Characterization. PCE was

TOP HAT CLEANERS (Continued) **1004758111**

detected at MW-02 (0.0036 ppm 17 19) and MW-04 (0.0017 ppm 5 6). Both detections are below the NYCRR Part 375 Soil Clean-up Objective of 1.3 ppm for PCE meeting both Unrestricted Use and Protection of Groundwater objectives. Groundwater - PCE was found in groundwater at two of the three boring locations advanced into the water table. Concentrations in contravention of the Class GA Groundwater standard of five (5) ppb were observed at 56 ppb and 10 ppb. Each of these exceedances were located in the public sidewalk immediately off the site parcel. Soil Vapor & Indoor Air A Vapor Intrusion Investigation was performed at the adjacent building to the north (154 Graham Avenue) as part of a real estate transaction. As part of that investigation two sub-slab vapor samples, one basement indoor air sample, and one ambient air sample were collected. At sub-slab location SG2, 43,399 ug/m3 of PCE was detected in soil vapor. (Note that the concentration reported is from a sample that was diluted 600 times. The concentration of PCE in the undiluted sample was 10,171 ug/m3, which exceeded the calibration range of the equipment.) Trichloroethylene (TCE) was detected at 1074 ug/m3 in the diluted sample and at 1504 ug/m3 in the undiluted sub-slab vapor sample. Cis-1,2-dichlorothylene (cis-1,2-DCE) was detected at 2180 ug/m3 in the diluted sample and at 1110 ug/m3 in the undiluted sub-slab vapor sample. Indoor air sampling results identified 44.1 ug/m3 of PCE and 0.43 ug/m3 of TCE in the basement air sample. See site no. C224208 for additional updates."

Health Problem: "People may contact contaminated soil or groundwater if they dig below the ground surface. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion on-site. Additional investigation of the potential for soil vapor intrusion to occur off-site is needed."

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: A
Owner Name: Not reported
Owner Company: Belio Urena
Owner Address: 37-49 95th St.
Owner Addr2: Not reported
Owner City,St,Zip: Jackson Heights, NY 11372
Owner Country: United States of America
Own Op: 4

TOP HAT CLEANERS (Continued) **1004758111**

Sub Type:	E
Owner Name:	Daniel Diaz
Owner Company:	Top Hat Cleaners
Owner Address:	152 Graham Ave.
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	6
Sub Type:	NNN
Owner Name:	Reina Diaz
Owner Company:	RP
Owner Address:	152 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	6
Sub Type:	NNN
Owner Name:	Belio Urena
Owner Company:	RP
Owner Address:	152 Graham Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Brooklyn, NY 11206
Owner Country:	United States of America
Own Op:	6
Sub Type:	NNN
Owner Name:	Elvis Diaz
Owner Company:	English speaking son of Owner/Operator - Daniel Diaz
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NY
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

ICIS:

Enforcement Action ID:	NY000A0000261040096200327
FRS ID:	110004480865
Action Name:	TOP HAT CLEANERS 36047R192400327
Facility Name:	TOP HAT CLEANERS
Facility Address:	152 GRAHAM AVE BROOKLYN, NY 112062602
Enforcement Action Type:	Notice of Violation
Facility County:	KINGS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.70676

TOP HAT CLEANERS (Continued) **1004758111**

Longitude in Decimal Degrees: -73.94311
Permit Type Desc: Not reported
Program System Acronym: NY0000002610400962
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261040096200314
FRS ID: 110004480865
Action Name: TOP HAT CLEANERS 36047R192400314
Facility Name: TOP HAT CLEANERS
Facility Address: 152 GRAHAM AVE
BROOKLYN, NY 112062602
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.70676
Longitude in Decimal Degrees: -73.94311
Permit Type Desc: Not reported
Program System Acronym: NY0000002610400962
Facility NAICS Code: 812320
Tribal Land Code: Not reported

Enforcement Action ID: NY000A0000261040096200304
FRS ID: 110004480865
Action Name: TOP HAT CLEANERS 36047R192400304
Facility Name: TOP HAT CLEANERS
Facility Address: 152 GRAHAM AVE
BROOKLYN, NY 112062602
Enforcement Action Type: Notice of Violation
Facility County: KINGS
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 7216
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 40.70676
Longitude in Decimal Degrees: -73.94311
Permit Type Desc: Not reported
Program System Acronym: NY0000002610400962
Facility NAICS Code: 812320
Tribal Land Code: Not reported

US AIRS MINOR:
Envid: 1004758111
Region Code: 02
Programmatic ID: AIR NY0000002610400962
Facility Registry ID: 110004480865
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF

TOP HAT CLEANERS (Continued) **1004758111**

Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002610400962
Facility Registry ID: 110004480865
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-11-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002610400962
Facility Registry ID: 110004480865
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-09-17 00:00:00
Activity Status Date: 2002-09-17 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610400962
Facility Registry ID: 110004480865
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-05-09 00:00:00
Activity Status Date: 2005-05-09 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000002610400962
Facility Registry ID: 110004480865
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-08-07 00:00:00
Activity Status Date: 2013-08-07 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

NY MANIFEST:
Name: TOP HAT CLNRS
Address: 152 GRAHAM AVE
City,State,Zip: BROOKLYN, NY 11206

TOP HAT CLEANERS (Continued) **1004758111**

Country:	USA
EPA ID:	NYD986982908
Facility Status:	Not reported
Location Address 1:	152 GRAHAM AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BROOKLYN
Location State:	NY
Location Zip:	11206
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986982908
Mailing Name:	TOP HAT CLNRS
Mailing Contact:	LOU SANCHEZ
Mailing Address 1:	152 GRAHAM AVENUE
Mailing Address 2:	Not reported
Mailing City:	BROOKLYN
Mailing State:	NY
Mailing Zip:	11206
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183382611

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	11/11/2009
Trans1 Recv Date:	11/11/2009
Trans2 Recv Date:	11/13/2009
TSD Site Recv Date:	11/25/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986982908
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	002316054SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported

TOP HAT CLEANERS (Continued) **1004758111**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	195
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D007
Waste Code 1_3:	D029
Waste Code 1_4:	D039
Waste Code 1_5:	D040
Waste Code 1_6:	Not reported

264
ENE
1/2-1
0.912 mi.
4817 ft.

FORMER W.L.K. CORP.
58-30 57TH STREET
MASPETH, NY 11378

NY SHWS **S109209067**
N/A

Relative:
Higher

Actual:
25 ft.

SHWS:

Name:	FORMER W.L.K. CORP.
Address:	58-30 57TH STREET
City,State,Zip:	MASPETH, NY 11378
Program:	HW
Site Code:	371165
Classification:	Significant threat to the public health or environment - action required.
Region:	2
Acres:	2.010
HW Code:	241097
Record Add:	09/29/2006
Record Upd:	11/15/2021
Updated By:	GWBURKE
Site Description:	"Location: The Former W.L.K. Corp. Site (58-30 57th St.) is located near the intersection of Grand Avenue and 57th Street in Maspeth, Queens County, New York. Site Features: The site is identified on the Queens Business Borough Tax Map as Block 2610, Lots 412 and 440 and is approximately 2.01 acres in size. The site is bordered on the north by MTA/LIRR rail lines, on the south by Grand Avenue, on the east by 57th Street, and on the west by a commercial/industrial property. The site is mostly paved, with a small area overgrown with vegetation (former railroad spur) present adjacent to the western portion of the building. Current Zoning and Land Use: Lots 412 and 440 are currently zoned M3-l. The site is currently used as a lumber yard with some offices. The surrounding parcels are currently used for a combination of commercial, light industrial, and transportation. The closest residential area is directly across 57th Street. Past Use of the Site: The northern portion of the site has historically been used by a radiator distribution facility (1930's-1940's), a steel pipe distributor (1950's- early 1970's), corrugated box company (early 1980's), a beer distributing company (mid/late 1980's), and a recycling facility (early 1990's - early 2000's). The southern portion of the site is currently occupied by

FORMER W.L.K. CORP. (Continued) **S109209067**

offices and has been used for several businesses. A lubricating oils company occupied this portion of the site at least from 1936 into the 1970's. Over the years other occupants included an oil company sales office, a milk products company, and an engineering firm. Also, a filling station was located on the site at the corner of Grand Avenue and 57th Street from early 1930's to early 1970's. Site Geology and Hydrogeology: Based on soil collected by continuous sampling activities, stratigraphy along the northwestern portion of the site consists of between 8 and 10 feet of fine to medium sand with trace silt and gravel. Along the northern portion of the property the subsurface material is made up of fill consisting of fine sand and rock fragments. The fine to medium sand/silty-sand in the area of the former rail spur next to the loading dock is underlain by a gray to brown clay that is at least several feet thick. The water table is generally encountered at a depth of approximately eight feet below ground surface (bgs) in either the clay or the overlying sand. The shallow groundwater flow is generally southwest."

Env Problem: "Nature and Extent of Contamination: The primary contaminants of concern at the site include chlorinated volatile organic compounds (CVOCs), specifically, Tetrachloroethylene (PCE) and 1,1,1-Trichloroethane (TCA) and their respective breakdown products. Soil: Exceedances of standards, criteria, and guidance in the on-site soils include TCE (max. 31 ppm), 1,1,1-TCA (1.1 ppm), PCE (max. 2.6 ppm), and total 1,2-DCE (max. 46.2 ppm). Groundwater: Exceedances of standards, criteria, and guidance in the groundwater include 1,1,1-TCA (max. 16 ppb), TCE (max. 710 ppb), PCE (max. 47 ppb), and total 1,2-DCE (max. 548 ppb). Samples taken off-site, adjacent to the former railroad spur area, revealed exceedances in the groundwater of 1,1,1-TCA (max. 71,000 ppb), TCE (360,000 ppb) and 1,2-DCE (max. 42,000 ppb). Soil Vapor: Elevated levels of VOCs were detected in sub-slab soil vapor and indoor air. The maximum concentrations of PCE and TCE in sub-slab soil vapor were detected in the western portion of the existing warehouse at the respective concentrations of 22 micrograms per cubic meter (ug/m3) and 2,310 ug/m3. The maximum concentrations of PCE and TCE in indoor air were detected in the same portion of the warehouse at the concentrations of 1.8 ug/m3 and 2.5 ug/m3. Sampling indicates that contaminated soil vapor extends off-site with TCE in sub-slab soil vapor and indoor air up to 7,260 ug/m3 and 0.38 ug/m3, respectively. Significant Threat: The site presents a significant threat to the environment due to significant groundwater and soil contamination. PCE and TCA are chlorinated volatile organics that are mobile in groundwater, persistent in soil vapor, and considered carcinogenic. Groundwater was observed approximately 8 feet below ground surface and determined flowing in a southwesterly direction. Contamination has been detected migrating downgradient from the site. "

Health Problem: "Further investigation is needed to assess the nature and extent of site-related contamination and the potential for exposure to site contaminants. The site currently has several buildings and a paved parking lot, therefore, contact with subsurface contamination is unlikely. Exposure to site-related contaminants in drinking water is not expected because the area is served by public water. NYSDOH and NYSDEC will evaluate the need for additional investigations to determine the potential for soil vapor intrusion to occur. "

Dump: False
Structure: False
Lagoon: False

FORMER W.L.K. CORP. (Continued) **S109209067**

Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	73:54'47" / 40:43'15"
Dell:	False
Record Add:	2006-09-29 11:13:00
Record Upd:	2013-09-19 14:58:00
Updated By:	kbdilige
Own Op:	1
Sub Type:	NNN
Owner Name:	BERNARD ETRA
Owner Company:	RUBY REALTY CO.
Owner Address:	58-30 57TH STREET
Owner Addr2:	Not reported
Owner City,St,Zip:	MASPETH, NY 11378
Owner Country:	United States of America
HW Code:	241097
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241097
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241097
Waste Type:	1,1,1 TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241097
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241097
Waste Type:	1,1,1-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241097
Waste Type:	1,1,1-Trichloroethane(TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

265
WNW
1/2-1
0.987 mi.
5213 ft.

CITY BARREL CO.
421-429 MEEKER STREET
BROOKLYN, NY 11378

NY SHWS **S105972440**
N/A

Relative:
Higher

Actual:
14 ft.

SHWS:

Name:	CITY BARREL CO.
Address:	421-429 MEEKER STREET
City,State,Zip:	BROOKLYN, NY 11378
Program:	HW
Site Code:	55909
Classification:	N
Region:	2
Acres:	Not reported
HW Code:	224005
Record Add:	11/18/1999
Record Upd:	12/16/2003
Updated By:	kstang
Site Description:	"The site did not qualify for addition to the Registry of Inactive Hazardous Disposal Sites. This site was listed in the Eckhardt subcommittee report as a disposal site. Investigation by the NYSDEC Regional offices indicate that this is an industrial operation to recycle, recover and refurbish drums and that no apparent disposal of hazardous or toxic waste have occurred here."
Env Problem:	"None known. No apparent disposal of significant quantities of any hazardous waste."
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

Count: 12 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BROOKLYN	S125896301	BOX STREET GW	BOX STREET BTW MANHATTAN AVE A	11222	NY SHWS
BROOKLYN	S113916751	INGRAHAM STREET SIDEWALK GW	INGRAHAM STREET	11237	NY SHWS
BROOKLYN	S113917078	NORTH OF CORNISH KNIT GOODS	JOHNSON AVE	11206	NY SHWS
BROOKLYN	S105972439	JONES MOTORS	LOMBARDY STREET (FOOT OF NEWTO		NY SHWS
BROOKLYN	S113922158	EQUITY WORKS	MASPETH AND VANDERVORT AVES.	11211	NY VCP
BROOKLYN	S113916693	MEEKER AVENUE PLUME TRACKDOWN	MEEKER AVENUE	11222	NY SHWS
BROOKLYN	1026004733	MEEKER AVENUE PLUME	MEEKER AVENUE	11222	Proposed NPL, SEMS
BROOKLYN	S113916666	MORGAN OIL TERMINAL	224038 MORGAN OIL TERMINAL		NY SHWS
BROOKLYN	S110487592	K - SCHOLES ST. STATION	SCHOLES ST 7 BOGART STS, MESSE	11206	NY SHWS, NY BROWNFIELDS
BROOKLYN	S113922100	SCHOLES ST. STATION	SCHOLES ST 7 BOGART STS, MESSE	11206	NY VCP
QUEENS	S122985415	A&G USED AUTO PART D/B/A PARTS ARE	1937 B FLUSHING AVERNUE	11385	NY SWF/LF
RIDGEWOOD	S118628347	WOLFF-ALPORT CHEMICAL COMPANY	1127-1129 IRVING AVENUE	11385	NY SHWS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 10/20/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 11/29/2021
Number of Days to Update: 24

Source: EPA
Telephone: N/A
Last EDR Contact: 01/13/2022
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 10/20/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 11/29/2021
Number of Days to Update: 24

Source: EPA
Telephone: N/A
Last EDR Contact: 01/13/2022
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 10/20/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 11/29/2021
Number of Days to Update: 24

Source: EPA
Telephone: N/A
Last EDR Contact: 01/13/2022
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 05/25/2021
Date Data Arrived at EDR: 06/24/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 12/29/2021
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 10/20/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 11/29/2021
Number of Days to Update: 24

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 01/13/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 10/20/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 11/29/2021
Number of Days to Update: 24

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 01/13/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 09/13/2021
Date Data Arrived at EDR: 09/15/2021
Date Made Active in Reports: 10/12/2021
Number of Days to Update: 27

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 12/17/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 09/13/2021
Date Data Arrived at EDR: 09/15/2021
Date Made Active in Reports: 10/12/2021
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/17/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 09/13/2021
Date Data Arrived at EDR: 09/15/2021
Date Made Active in Reports: 10/12/2021
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/17/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 09/13/2021
Date Data Arrived at EDR: 09/15/2021
Date Made Active in Reports: 10/12/2021
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/17/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 09/13/2021
Date Data Arrived at EDR: 09/15/2021
Date Made Active in Reports: 10/12/2021
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/17/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 07/12/2021
Date Data Arrived at EDR: 08/06/2021
Date Made Active in Reports: 10/22/2021
Number of Days to Update: 77

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 11/08/2021
Next Scheduled EDR Contact: 02/21/2022
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 08/23/2021
Date Data Arrived at EDR: 08/23/2021
Date Made Active in Reports: 11/12/2021
Number of Days to Update: 81

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/18/2021
Next Scheduled EDR Contact: 03/06/2022
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 08/23/2021
Date Data Arrived at EDR: 08/23/2021
Date Made Active in Reports: 11/12/2021
Number of Days to Update: 81

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/19/2021
Next Scheduled EDR Contact: 03/07/2022
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 09/13/2021
Date Data Arrived at EDR: 09/21/2021
Date Made Active in Reports: 12/15/2021
Number of Days to Update: 85

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 12/16/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 01/06/2022
Next Scheduled EDR Contact: 02/21/2022
Data Release Frequency: Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 09/30/2021
Date Data Arrived at EDR: 10/28/2021
Date Made Active in Reports: 11/29/2021
Number of Days to Update: 32

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 12/22/2021
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 05/17/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 06/01/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 05/27/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 05/27/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88
Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/06/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/27/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 05/28/2021
Date Data Arrived at EDR: 06/22/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 90
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 08/09/2021
Date Data Arrived at EDR: 08/10/2021
Date Made Active in Reports: 09/24/2021
Number of Days to Update: 45
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/10/2021
Next Scheduled EDR Contact: 02/21/2022
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/29/2021
Date Data Arrived at EDR: 02/17/2021
Date Made Active in Reports: 03/22/2021
Number of Days to Update: 33

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 12/18/2021
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 09/20/2021
Date Data Arrived at EDR: 09/22/2021
Date Made Active in Reports: 12/13/2021
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/16/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 09/20/2021
Date Data Arrived at EDR: 09/22/2021
Date Made Active in Reports: 12/13/2021
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/16/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 09/20/2021
Date Data Arrived at EDR: 09/22/2021
Date Made Active in Reports: 12/13/2021
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/16/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 09/20/2021
Date Data Arrived at EDR: 09/22/2021
Date Made Active in Reports: 12/13/2021
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 12/16/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 05/28/2021
Date Data Arrived at EDR: 06/22/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 90

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 05/17/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/06/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/27/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 06/01/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 05/27/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 05/27/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 09/20/2021
Date Data Arrived at EDR: 09/22/2021
Date Made Active in Reports: 12/13/2021
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 12/16/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 08/26/2021
Date Data Arrived at EDR: 09/16/2021
Date Made Active in Reports: 12/06/2021
Number of Days to Update: 81

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 12/13/2021
Next Scheduled EDR Contact: 03/28/2022
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 08/26/2021
Date Data Arrived at EDR: 09/14/2021
Date Made Active in Reports: 12/03/2021
Number of Days to Update: 80

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 12/13/2021
Next Scheduled EDR Contact: 03/28/2022
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 01/06/2022
Next Scheduled EDR Contact: 02/21/2022
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 01/06/2022
Next Scheduled EDR Contact: 02/21/2022
Data Release Frequency: Quarterly

Lists of state and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 12/14/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 01/06/2022
Next Scheduled EDR Contact: 02/21/2022
Data Release Frequency: Semi-Annually

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC

New York City voluntary cleanup program sites.

Date of Government Version: 12/06/2021
Date Data Arrived at EDR: 12/08/2021
Date Made Active in Reports: 01/06/2022
Number of Days to Update: 29

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 12/08/2021
Next Scheduled EDR Contact: 03/21/2022
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 01/06/2022
Next Scheduled EDR Contact: 02/21/2022
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 01/06/2022
Next Scheduled EDR Contact: 02/21/2022
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 06/10/2021
Date Data Arrived at EDR: 06/10/2021
Date Made Active in Reports: 08/17/2021
Number of Days to Update: 68

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 12/08/2021
Next Scheduled EDR Contact: 03/28/2022
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 12/02/2021
Next Scheduled EDR Contact: 03/21/2022
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 09/30/2021
Date Data Arrived at EDR: 10/28/2021
Date Made Active in Reports: 11/29/2021
Number of Days to Update: 32

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 12/22/2021
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 10/22/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 01/13/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 10/28/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 05/18/2021
Date Data Arrived at EDR: 05/18/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 77

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/16/2021
Next Scheduled EDR Contact: 03/07/2022
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 01/06/2022
Date Data Arrived at EDR: 01/06/2022
Date Made Active in Reports: 01/07/2022
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 01/06/2022
Next Scheduled EDR Contact: 02/21/2022
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 05/18/2021
Date Data Arrived at EDR: 05/18/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 77

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/16/2021
Next Scheduled EDR Contact: 03/07/2022
Data Release Frequency: Quarterly

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 11/05/2021
Next Scheduled EDR Contact: 02/14/2022
Data Release Frequency: Varies

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 07/27/2021
Date Data Arrived at EDR: 07/28/2021
Date Made Active in Reports: 10/21/2021
Number of Days to Update: 85
Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 11/01/2021
Next Scheduled EDR Contact: 02/14/2022
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 10/20/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 11/29/2021
Number of Days to Update: 24
Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 01/13/2022
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 09/12/2021
Date Data Arrived at EDR: 09/13/2021
Date Made Active in Reports: 09/28/2021
Number of Days to Update: 15
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 12/16/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Quarterly

SPILLS: Spills Information Database
Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 08/09/2021
Date Data Arrived at EDR: 08/10/2021
Date Made Active in Reports: 09/24/2021
Number of Days to Update: 45

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/10/2021
Next Scheduled EDR Contact: 02/21/2022
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 09/13/2021
Date Data Arrived at EDR: 09/15/2021
Date Made Active in Reports: 10/12/2021
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 12/17/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 08/10/2021
Date Data Arrived at EDR: 08/17/2021
Date Made Active in Reports: 10/22/2021
Number of Days to Update: 66

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 11/16/2021
Next Scheduled EDR Contact: 02/28/2022
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 01/14/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 01/07/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 11/08/2021
Next Scheduled EDR Contact: 02/21/2022
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 09/13/2021
Date Data Arrived at EDR: 09/15/2021
Date Made Active in Reports: 09/28/2021
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 12/17/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 11/01/2021
Next Scheduled EDR Contact: 02/14/2022
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 11/05/2021
Next Scheduled EDR Contact: 02/14/2022
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 12/17/2021
Next Scheduled EDR Contact: 03/28/2022
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 08/14/2020
Date Made Active in Reports: 11/04/2020
Number of Days to Update: 82

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 11/16/2021
Next Scheduled EDR Contact: 02/28/2022
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 10/18/2021
Date Data Arrived at EDR: 10/20/2021
Date Made Active in Reports: 01/10/2022
Number of Days to Update: 82

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 01/19/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 10/20/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 11/29/2021
Number of Days to Update: 24

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 12/01/2021
Next Scheduled EDR Contact: 03/14/2022
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 10/20/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 11/12/2021
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/20/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 12/15/2021
Number of Days to Update: 40

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 01/13/2022
Next Scheduled EDR Contact: 02/14/2022
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 11/19/2020
Date Data Arrived at EDR: 01/08/2021
Date Made Active in Reports: 03/22/2021
Number of Days to Update: 73

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 01/07/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/29/2021
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 07/29/2021
Date Data Arrived at EDR: 08/24/2021
Date Made Active in Reports: 11/19/2021
Number of Days to Update: 87
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 12/01/2020
Date Made Active in Reports: 02/09/2021
Number of Days to Update: 70
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 11/30/2021
Next Scheduled EDR Contact: 03/14/2022
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 12/02/2021
Next Scheduled EDR Contact: 03/14/2022
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 11/05/2021
Next Scheduled EDR Contact: 02/14/2022
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 12/27/2021
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 10/26/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2021
Date Data Arrived at EDR: 10/13/2021
Date Made Active in Reports: 01/10/2022
Number of Days to Update: 89

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 01/03/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 09/15/2021
Date Made Active in Reports: 12/14/2021
Number of Days to Update: 90

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 12/17/2021
Next Scheduled EDR Contact: 04/04/2022
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 01/04/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 07/26/2021
Date Data Arrived at EDR: 07/27/2021
Date Made Active in Reports: 10/22/2021
Number of Days to Update: 87

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 11/01/2021
Next Scheduled EDR Contact: 02/14/2022
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 12/09/2021
Next Scheduled EDR Contact: 02/28/2022
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 10/20/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 11/29/2021
Number of Days to Update: 24

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 01/13/2022
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/09/2021
Date Data Arrived at EDR: 08/24/2021
Date Made Active in Reports: 11/19/2021
Number of Days to Update: 87

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 11/22/2021
Next Scheduled EDR Contact: 03/07/2022
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 06/30/2021
Date Data Arrived at EDR: 07/01/2021
Date Made Active in Reports: 09/28/2021
Number of Days to Update: 89

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 12/20/2021
Next Scheduled EDR Contact: 03/14/2022
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/22/2021
Next Scheduled EDR Contact: 03/07/2022
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/22/2021
Next Scheduled EDR Contact: 03/07/2022
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 09/14/2021
Date Data Arrived at EDR: 09/15/2021
Date Made Active in Reports: 12/15/2021
Number of Days to Update: 91
Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 12/14/2021
Next Scheduled EDR Contact: 03/21/2022
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 05/05/2021
Date Data Arrived at EDR: 05/18/2021
Date Made Active in Reports: 08/17/2021
Number of Days to Update: 91
Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 11/22/2021
Next Scheduled EDR Contact: 03/14/2022
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 07/02/2020
Date Made Active in Reports: 09/17/2020
Number of Days to Update: 77
Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 01/11/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82
Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 11/23/2021
Next Scheduled EDR Contact: 03/07/2022
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 01/04/2022
Date Made Active in Reports: 01/10/2022
Number of Days to Update: 6
Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 01/04/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 08/13/2021
Date Data Arrived at EDR: 08/13/2021
Date Made Active in Reports: 10/22/2021
Number of Days to Update: 70
Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 11/15/2021
Next Scheduled EDR Contact: 02/28/2022
Data Release Frequency: Quarterly

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 07/14/2021
Date Data Arrived at EDR: 07/29/2021
Date Made Active in Reports: 10/25/2021
Number of Days to Update: 88

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 09/29/2021
Date Data Arrived at EDR: 09/30/2021
Date Made Active in Reports: 12/23/2021
Number of Days to Update: 84

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 12/20/2021
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners
A listing of all registered drycleaning facilities.

Date of Government Version: 09/02/2021
Date Data Arrived at EDR: 09/02/2021
Date Made Active in Reports: 11/23/2021
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 12/02/2021
Next Scheduled EDR Contact: 03/21/2022
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 12/13/2021
Date Data Arrived at EDR: 12/17/2021
Date Made Active in Reports: 12/30/2021
Number of Days to Update: 13

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 12/13/2021
Next Scheduled EDR Contact: 03/28/2022
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 10/01/2021
Date Data Arrived at EDR: 10/01/2021
Date Made Active in Reports: 12/21/2021
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 12/20/2021
Next Scheduled EDR Contact: 04/11/2022
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 06/11/2020
Date Data Arrived at EDR: 06/16/2020
Date Made Active in Reports: 09/02/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 12/02/2021
Next Scheduled EDR Contact: 03/21/2022
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory
The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 10/29/2021
Date Made Active in Reports: 01/19/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 10/29/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 07/27/2021
Date Data Arrived at EDR: 07/29/2021
Date Made Active in Reports: 10/25/2021
Number of Days to Update: 88

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 01/18/2022
Next Scheduled EDR Contact: 05/02/2022
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 12/01/2018
Date Data Arrived at EDR: 02/13/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 120

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 11/12/2021
Next Scheduled EDR Contact: 02/21/2022
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 08/29/2021
Date Data Arrived at EDR: 09/01/2021
Date Made Active in Reports: 11/23/2021
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 11/30/2021
Next Scheduled EDR Contact: 03/14/2022
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 10/05/2021
Date Data Arrived at EDR: 10/11/2021
Date Made Active in Reports: 01/05/2022
Number of Days to Update: 86

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 01/12/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 07/30/2021
Date Made Active in Reports: 10/22/2021
Number of Days to Update: 84

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 11/03/2021
Next Scheduled EDR Contact: 02/14/2022
Data Release Frequency: Varies

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 12/29/2021
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 12/29/2021
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Semi-Annually

MINES MRDS: Mineral Resources Data System

Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 11/23/2021
Next Scheduled EDR Contact: 03/07/2022
Data Release Frequency: Varies

PCS INACTIVE: Listing of Inactive PCS Permits

An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 12/29/2021
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Semi-Annually

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 03/24/2021
Date Data Arrived at EDR: 08/17/2021
Date Made Active in Reports: 08/17/2021
Number of Days to Update: 0

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 11/03/2021
Next Scheduled EDR Contact: 02/14/2022
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 10/25/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 10/25/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 10/25/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 10/25/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 10/25/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: Varies

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 10/25/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 10/25/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 11/29/2021
Next Scheduled EDR Contact: 03/14/2022
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 11/29/2021
Next Scheduled EDR Contact: 03/14/2022
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 10/25/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database

This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 10/25/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 10/25/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 07/01/2021
Date Data Arrived at EDR: 08/06/2021
Date Made Active in Reports: 08/20/2021
Number of Days to Update: 14

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 10/25/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 07/01/2021
Date Data Arrived at EDR: 08/06/2021
Date Made Active in Reports: 08/20/2021
Number of Days to Update: 14

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 10/25/2021
Next Scheduled EDR Contact: 02/07/2022
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/23/2021
Date Data Arrived at EDR: 08/10/2021
Date Made Active in Reports: 11/08/2021
Number of Days to Update: 90

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 11/12/2021
Next Scheduled EDR Contact: 02/21/2022
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 01/07/2022
Next Scheduled EDR Contact: 04/18/2022
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 01/10/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 02/11/2021
Date Made Active in Reports: 02/24/2021
Number of Days to Update: 13

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 11/29/2021
Next Scheduled EDR Contact: 02/28/2022
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 01/10/2022
Next Scheduled EDR Contact: 04/25/2022
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 12/06/2021
Next Scheduled EDR Contact: 03/21/2022
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

213 MEADOW STREET
213 MEADOW STREET
BROOKLYN, NY 11237

TARGET PROPERTY COORDINATES

Latitude (North):	40.713041 - 40ˆ 42’ 46.95’’
Longitude (West):	73.928211 - 73ˆ 55’ 41.56’’
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	590532.1
UTM Y (Meters):	4507243.5
Elevation:	14 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14115940 BROOKLYN, NY
Version Date:	2019

EDR’s GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 14 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3604970208F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
3604970202F	FEMA FIRM Flood data
3604970206F	FEMA FIRM Flood data
3604970204F	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
BROOKLYN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1 - 2 Miles NNE
Site Name:	Phelps Dodge Refining Corp
Site EPA ID Number:	NYD039138789
Groundwater Flow Direction:	DEPENDENT ON WELL PUMPING RATES.
Measured Depth to Water:	not available.
Hydraulic Connection:	Salt water intrusion may be present at the site. Information about the hydraulic connection between aquifers underlying the site is not available. The depth to bedrock is approximately 60 feet.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information is inferred in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site--specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Mesozoic
System:	Cretaceous
Series:	Upper Cretaceous
Code:	uK *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A3	USGS40000829330	1/4 - 1/2 Mile SSE
A4	USGS40000829306	1/4 - 1/2 Mile SSE
5	USGS40000829283	1/4 - 1/2 Mile SSE
9	USGS40000829428	1/4 - 1/2 Mile East
C10	USGS40000829706	1/4 - 1/2 Mile North
C11	USGS40000829722	1/4 - 1/2 Mile North
12	USGS40000829655	1/4 - 1/2 Mile NW
15	USGS40000829364	1/4 - 1/2 Mile WSW
21	USGS40000829247	1/4 - 1/2 Mile SSW
24	USGS40000829597	1/2 - 1 Mile WNW
25	USGS40000829202	1/2 - 1 Mile SSE
G26	USGS40000829232	1/2 - 1 Mile SW
28	USGS40000829791	1/2 - 1 Mile NNE
G29	USGS40000829233	1/2 - 1 Mile SW
30	USGS40000829234	1/2 - 1 Mile SW
31	USGS40000829116	1/2 - 1 Mile SSW
H32	USGS40000829101	1/2 - 1 Mile SSE
I33	USGS40000829273	1/2 - 1 Mile WSW
I34	USGS40000829261	1/2 - 1 Mile WSW
H35	USGS40000829082	1/2 - 1 Mile South
J37	USGS40000829385	1/2 - 1 Mile WSW
J38	USGS40000829386	1/2 - 1 Mile WSW
39	USGS40000829063	1/2 - 1 Mile SSW
40	USGS40000829528	1/2 - 1 Mile West
41	USGS40000829291	1/2 - 1 Mile WSW
K42	USGS40000829052	1/2 - 1 Mile SSW
L44	USGS40000829000	1/2 - 1 Mile South
K45	USGS40000829031	1/2 - 1 Mile SSW
K46	USGS40000829032	1/2 - 1 Mile SSW
47	USGS40000829962	1/2 - 1 Mile NNE
48	USGS40000829001	1/2 - 1 Mile SSW
49	USGS40000829883	1/2 - 1 Mile NE
M50	USGS40000829262	1/2 - 1 Mile WSW
L51	USGS40000828957	1/2 - 1 Mile SSW
N52	USGS40000829002	1/2 - 1 Mile SSW
N53	USGS40000829003	1/2 - 1 Mile SSW
54	USGS40000830095	1/2 - 1 Mile North
55	USGS40000829320	1/2 - 1 Mile WSW
56	USGS40000829892	1/2 - 1 Mile NW
M57	USGS40000829242	1/2 - 1 Mile WSW
58	USGS40000830073	1/2 - 1 Mile NNE
59	USGS40000830081	1/2 - 1 Mile NNW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NYREG1000000204	1/8 - 1/4 Mile ESE
2	NYREG1000000262	1/8 - 1/4 Mile SSW
B6	NYREG1000000136	1/4 - 1/2 Mile South
B7	NYREG1000000137	1/4 - 1/2 Mile South
B8	NYREG1000000148	1/4 - 1/2 Mile South
D13	NYREG1000000236	1/4 - 1/2 Mile NW
D14	NYREG1000000150	1/4 - 1/2 Mile NW
E16	NYREG1000000037	1/4 - 1/2 Mile NNW
E17	NYREG1000000036	1/4 - 1/2 Mile NNW
E18	NYREG1000000038	1/4 - 1/2 Mile NNW
E19	NYREG1000000043	1/4 - 1/2 Mile NNW
E20	NYREG1000000042	1/4 - 1/2 Mile NNW
F22	NYREG1000000185	1/4 - 1/2 Mile SSW
F23	NYREG1000000188	1/2 - 1 Mile SSW
G27	NYREG1000000018	1/2 - 1 Mile SW
36	NYREG1000000142	1/2 - 1 Mile WNW
43	NYREG1000000104	1/2 - 1 Mile NNW

PHYSICAL SETTING SOURCE MAP - 6826547.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	213 Meadow Street	CLIENT:	Langan Engineering
ADDRESS:	213 Meadow Street Brooklyn NY 11237	CONTACT:	Molly Mattern
		INQUIRY #:	6826547.2s
LAT/LONG:	40.713041 / 73.928211	DATE:	January 20, 2022 11:30 am

Copyright © 2022 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database | EDR ID Number

1
ESE
1/8 - 1/4 Mile
Higher

NY WELLS **NYREG1000000204**

Well Number:	K003554	Owner:	Allocco Recycling
Well Depth:	80	Diameter:	4
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

2
SSW
1/8 - 1/4 Mile
Lower

NY WELLS **NYREG1000000262**

Well Number:	K003610	Owner:	Cooper Tank Recycling
Well Depth:	79	Diameter:	4
Casing Length:	0	Screen Diameter:	4
Screen Length:	10		

A3
SSE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000829330**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1990. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	70	Well Hole Depth Units:	ft

A4
SSE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000829306**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1346. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	168	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

5
SSE
1/4 - 1/2 Mile
Higher | **FED USGS** | **USGS40000829283**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2598. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

B6
South
1/4 - 1/2 Mile
Higher | **NY WELLS** | **NYREG1000000136**

Well Number:	K003491T	Owner:	Shield Environmental Associates
Well Depth:	23	Diameter:	2
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

B7
South
1/4 - 1/2 Mile
Higher | **NY WELLS** | **NYREG1000000137**

Well Number:	K003492T	Owner:	Shield Environmental Associates
Well Depth:	23	Diameter:	2
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

B8
South
1/4 - 1/2 Mile
Higher | **NY WELLS** | **NYREG1000000148**

Well Number:	K003502	Owner:	Shield Environmental Associates
Well Depth:	23	Diameter:	2
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

9
East
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000829428**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 1947. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	83
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

C10
North
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000829706**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 675. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	222	Well Hole Depth Units:	ft

C11
North
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000829722**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1977. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	163	Well Hole Depth Units:	ft

12
NW
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000829655**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 569. 1	Type:	Well
Description:	Not Reported	HUC:	02030201

Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	190	Well Hole Depth Units:	ft

D13
NW
1/4 - 1/2 Mile
Higher

NY WELLS **NYREG1000000236**

Well Number:	K003584	Owner:	Cooper Tank And Welding Corporation
Well Depth:	200	Diameter:	4
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

D14
NW
1/4 - 1/2 Mile
Higher

NY WELLS **NYREG1000000150**

Well Number:	K003504	Owner:	Cooper Tank And Welding Corporation
Well Depth:	80	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

15
WSW
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000829364**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 889. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	74
Well Depth Units:	ft	Well Hole Depth:	74
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	265	Level reading date:	1985-10-01
Feet below surface:	Not Reported	Feet to sea level:	3.53
Note:	Not Reported		
Level reading date:	1985-05-21	Feet below surface:	Not Reported
Feet to sea level:	4.48	Note:	Not Reported
Level reading date:	1984-12-18	Feet below surface:	Not Reported
Feet to sea level:	4.95	Note:	Not Reported
Level reading date:	1984-10-05	Feet below surface:	Not Reported
Feet to sea level:	5.16	Note:	Not Reported

Level reading date:	1984-06-27	Feet below surface:	Not Reported
Feet to sea level:	5.47	Note:	Not Reported
Level reading date:	1984-03-15	Feet below surface:	Not Reported
Feet to sea level:	5.13	Note:	Not Reported
Level reading date:	1984-01-05	Feet below surface:	Not Reported
Feet to sea level:	5.76	Note:	Not Reported
Level reading date:	1983-09-29	Feet below surface:	Not Reported
Feet to sea level:	4.96	Note:	Not Reported
Level reading date:	1983-06-29	Feet below surface:	Not Reported
Feet to sea level:	4.59	Note:	Not Reported
Level reading date:	1983-03-25	Feet below surface:	Not Reported
Feet to sea level:	3.96	Note:	Not Reported
Level reading date:	1982-12-21	Feet below surface:	Not Reported
Feet to sea level:	3.69	Note:	Not Reported
Level reading date:	1982-10-06	Feet below surface:	Not Reported
Feet to sea level:	3.86	Note:	Not Reported
Level reading date:	1982-06-30	Feet below surface:	Not Reported
Feet to sea level:	3.96	Note:	Not Reported
Level reading date:	1982-04-02	Feet below surface:	Not Reported
Feet to sea level:	4.19	Note:	Not Reported
Level reading date:	1981-12-29	Feet below surface:	Not Reported
Feet to sea level:	4.01	Note:	Not Reported
Level reading date:	1981-09-23	Feet below surface:	Not Reported
Feet to sea level:	4.10	Note:	Not Reported
Level reading date:	1981-06-24	Feet below surface:	Not Reported
Feet to sea level:	4.28	Note:	Not Reported
Level reading date:	1981-03-18	Feet below surface:	Not Reported
Feet to sea level:	5.36	Note:	Not Reported
Level reading date:	1980-12-30	Feet below surface:	Not Reported
Feet to sea level:	3.96	Note:	Not Reported
Level reading date:	1980-09-23	Feet below surface:	Not Reported
Feet to sea level:	5.06	Note:	Not Reported
Level reading date:	1980-06-24	Feet below surface:	Not Reported
Feet to sea level:	5.14	Note:	Not Reported
Level reading date:	1980-03-13	Feet below surface:	Not Reported
Feet to sea level:	4.02	Note:	Not Reported
Level reading date:	1979-12-18	Feet below surface:	Not Reported
Feet to sea level:	4.92	Note:	Not Reported
Level reading date:	1979-09-17	Feet below surface:	Not Reported
Feet to sea level:	4.57	Note:	Not Reported
Level reading date:	1979-06-28	Feet below surface:	Not Reported
Feet to sea level:	4.07	Note:	Not Reported

Level reading date:	1979-03-26	Feet below surface:	Not Reported
Feet to sea level:	5.46	Note:	Not Reported
Level reading date:	1978-12-22	Feet below surface:	Not Reported
Feet to sea level:	5.11	Note:	Not Reported
Level reading date:	1978-10-02	Feet below surface:	Not Reported
Feet to sea level:	5.94	Note:	Not Reported
Level reading date:	1978-06-23	Feet below surface:	Not Reported
Feet to sea level:	3.93	Note:	Not Reported
Level reading date:	1978-04-04	Feet below surface:	Not Reported
Feet to sea level:	4.06	Note:	Not Reported
Level reading date:	1978-01-03	Feet below surface:	Not Reported
Feet to sea level:	4.29	Note:	Not Reported
Level reading date:	1977-09-22	Feet below surface:	Not Reported
Feet to sea level:	3.81	Note:	Not Reported
Level reading date:	1977-07-07	Feet below surface:	Not Reported
Feet to sea level:	3.33	Note:	Not Reported
Level reading date:	1977-03-29	Feet below surface:	Not Reported
Feet to sea level:	2.60	Note:	Not Reported
Level reading date:	1976-12-22	Feet below surface:	Not Reported
Feet to sea level:	2.81	Note:	Not Reported
Level reading date:	1976-09-23	Feet below surface:	Not Reported
Feet to sea level:	3.25	Note:	Not Reported
Level reading date:	1976-07-09	Feet below surface:	Not Reported
Feet to sea level:	3.97	Note:	Not Reported
Level reading date:	1976-06-28	Feet below surface:	Not Reported
Feet to sea level:	3.21	Note:	Not Reported
Level reading date:	1976-03-23	Feet below surface:	Not Reported
Feet to sea level:	3.02	Note:	Not Reported
Level reading date:	1975-12-16	Feet below surface:	Not Reported
Feet to sea level:	3.17	Note:	Not Reported
Level reading date:	1975-10-07	Feet below surface:	Not Reported
Feet to sea level:	3.10	Note:	Not Reported
Level reading date:	1975-06-30	Feet below surface:	Not Reported
Feet to sea level:	2.80	Note:	Not Reported
Level reading date:	1975-03-26	Feet below surface:	Not Reported
Feet to sea level:	2.67	Note:	Not Reported
Level reading date:	1974-12-19	Feet below surface:	Not Reported
Feet to sea level:	1.99	Note:	Not Reported
Level reading date:	1974-09-04	Feet below surface:	Not Reported
Feet to sea level:	2.44	Note:	Not Reported
Level reading date:	1974-06-26	Feet below surface:	Not Reported
Feet to sea level:	2.58	Note:	Not Reported

Level reading date:	1974-03-19	Feet below surface:	Not Reported
Feet to sea level:	2.36	Note:	Not Reported
Level reading date:	1974-01-09	Feet below surface:	Not Reported
Feet to sea level:	2.26	Note:	Not Reported
Level reading date:	1973-09-24	Feet below surface:	Not Reported
Feet to sea level:	1.86	Note:	Not Reported
Level reading date:	1973-07-02	Feet below surface:	Not Reported
Feet to sea level:	2.22	Note:	Not Reported
Level reading date:	1973-04-03	Feet below surface:	Not Reported
Feet to sea level:	0.97	Note:	Not Reported
Level reading date:	1972-12-27	Feet below surface:	Not Reported
Feet to sea level:	1.70	Note:	Not Reported
Level reading date:	1972-10-02	Feet below surface:	Not Reported
Feet to sea level:	1.57	Note:	Not Reported
Level reading date:	1972-07-10	Feet below surface:	Not Reported
Feet to sea level:	1.94	Note:	Not Reported
Level reading date:	1972-03-28	Feet below surface:	Not Reported
Feet to sea level:	0.27	Note:	Not Reported
Level reading date:	1972-01-13	Feet below surface:	Not Reported
Feet to sea level:	0.44	Note:	Not Reported
Level reading date:	1971-09-27	Feet below surface:	Not Reported
Feet to sea level:	0.57	Note:	Not Reported
Level reading date:	1971-03-08	Feet below surface:	Not Reported
Feet to sea level:	1.08	Note:	Not Reported
Level reading date:	1970-11-02	Feet below surface:	Not Reported
Feet to sea level:	1.02	Note:	Not Reported
Level reading date:	1970-03-13	Feet below surface:	Not Reported
Feet to sea level:	1.52	Note:	Not Reported
Level reading date:	1969-11-12	Feet below surface:	Not Reported
Feet to sea level:	0.49	Note:	Not Reported
Level reading date:	1969-09-05	Feet below surface:	Not Reported
Feet to sea level:	0.24	Note:	Not Reported
Level reading date:	1969-04-23	Feet below surface:	Not Reported
Feet to sea level:	-0.34	Note:	Not Reported
Level reading date:	1968-11-06	Feet below surface:	Not Reported
Feet to sea level:	-3.34	Note:	Not Reported
Level reading date:	1968-04-22	Feet below surface:	Not Reported
Feet to sea level:	0.46	Note:	Not Reported
Level reading date:	1967-10-20	Feet below surface:	Not Reported
Feet to sea level:	-0.01	Note:	Not Reported
Level reading date:	1967-03-28	Feet below surface:	Not Reported
Feet to sea level:	-0.64	Note:	Not Reported

Level reading date:	1966-10-24	Feet below surface:	Not Reported
Feet to sea level:	-2.53	Note:	Not Reported
Level reading date:	1966-05-03	Feet below surface:	Not Reported
Feet to sea level:	-0.64	Note:	Not Reported
Level reading date:	1965-10-28	Feet below surface:	Not Reported
Feet to sea level:	-1.85	Note:	Not Reported
Level reading date:	1965-09-14	Feet below surface:	Not Reported
Feet to sea level:	-2.21	Note:	Not Reported
Level reading date:	1964-10-30	Feet below surface:	Not Reported
Feet to sea level:	-1.79	Note:	Not Reported
Level reading date:	1964-04-27	Feet below surface:	Not Reported
Feet to sea level:	-0.19	Note:	Not Reported
Level reading date:	1963-11-05	Feet below surface:	Not Reported
Feet to sea level:	-1.31	Note:	Not Reported
Level reading date:	1963-04-29	Feet below surface:	Not Reported
Feet to sea level:	-0.13	Note:	Not Reported
Level reading date:	1962-12-04	Feet below surface:	Not Reported
Feet to sea level:	-0.88	Note:	Not Reported
Level reading date:	1962-04-26	Feet below surface:	Not Reported
Feet to sea level:	-0.54	Note:	Not Reported
Level reading date:	1961-12-28	Feet below surface:	Not Reported
Feet to sea level:	-1.92	Note:	Not Reported
Level reading date:	1961-10-02	Feet below surface:	Not Reported
Feet to sea level:	-2.45	Note:	Not Reported
Level reading date:	1961-03-28	Feet below surface:	Not Reported
Feet to sea level:	-3.06	Note:	Not Reported
Level reading date:	1960-12-27	Feet below surface:	Not Reported
Feet to sea level:	-3.44	Note:	Not Reported
Level reading date:	1960-09-28	Feet below surface:	Not Reported
Feet to sea level:	-4.38	Note:	Not Reported
Level reading date:	1960-07-05	Feet below surface:	Not Reported
Feet to sea level:	-4.23	Note:	Not Reported
Level reading date:	1960-03-31	Feet below surface:	Not Reported
Feet to sea level:	-4.56	Note:	Not Reported
Level reading date:	1960-01-14	Feet below surface:	Not Reported
Feet to sea level:	-4.97	Note:	Not Reported
Level reading date:	1959-10-07	Feet below surface:	Not Reported
Feet to sea level:	-5.06	Note:	Not Reported
Level reading date:	1959-07-17	Feet below surface:	Not Reported
Feet to sea level:	-4.44	Note:	Not Reported
Level reading date:	1959-03-18	Feet below surface:	Not Reported
Feet to sea level:	-4.96	Note:	Not Reported

Level reading date:	1958-01-10	Feet below surface:	Not Reported
Feet to sea level:	-4.06	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	Not Reported
Feet to sea level:	-4.44	Note:	Not Reported
Level reading date:	1957-06-27	Feet below surface:	Not Reported
Feet to sea level:	-3.61	Note:	Not Reported
Level reading date:	1957-03-27	Feet below surface:	Not Reported
Feet to sea level:	-3.58	Note:	Not Reported
Level reading date:	1956-12-18	Feet below surface:	Not Reported
Feet to sea level:	-3.19	Note:	Not Reported
Level reading date:	1956-11-29	Feet below surface:	Not Reported
Feet to sea level:	-3.09	Note:	Not Reported
Level reading date:	1956-10-25	Feet below surface:	Not Reported
Feet to sea level:	-3.01	Note:	Not Reported
Level reading date:	1956-10-02	Feet below surface:	Not Reported
Feet to sea level:	-3.06	Note:	Not Reported
Level reading date:	1956-08-02	Feet below surface:	Not Reported
Feet to sea level:	-3.00	Note:	Not Reported
Level reading date:	1956-07-11	Feet below surface:	Not Reported
Feet to sea level:	-2.95	Note:	Not Reported
Level reading date:	1956-06-05	Feet below surface:	Not Reported
Feet to sea level:	-3.05	Note:	Not Reported
Level reading date:	1956-05-15	Feet below surface:	Not Reported
Feet to sea level:	-3.26	Note:	Not Reported
Level reading date:	1956-03-05	Feet below surface:	Not Reported
Feet to sea level:	-3.53	Note:	Not Reported
Level reading date:	1956-02-03	Feet below surface:	Not Reported
Feet to sea level:	-3.69	Note:	Not Reported
Level reading date:	1955-12-22	Feet below surface:	Not Reported
Feet to sea level:	-3.74	Note:	Not Reported
Level reading date:	1955-11-15	Feet below surface:	Not Reported
Feet to sea level:	-4.04	Note:	Not Reported
Level reading date:	1955-10-07	Feet below surface:	Not Reported
Feet to sea level:	-4.61	Note:	Not Reported
Level reading date:	1955-08-25	Feet below surface:	Not Reported
Feet to sea level:	-4.74	Note:	Not Reported
Level reading date:	1955-07-27	Feet below surface:	Not Reported
Feet to sea level:	-4.72	Note:	Not Reported
Level reading date:	1955-06-23	Feet below surface:	Not Reported
Feet to sea level:	-4.43	Note:	Not Reported
Level reading date:	1955-04-26	Feet below surface:	Not Reported
Feet to sea level:	-4.91	Note:	Not Reported

Level reading date:	1955-03-29	Feet below surface:	Not Reported
Feet to sea level:	-5.07	Note:	Not Reported
Level reading date:	1955-02-25	Feet below surface:	Not Reported
Feet to sea level:	-5.33	Note:	Not Reported
Level reading date:	1955-01-25	Feet below surface:	Not Reported
Feet to sea level:	-5.34	Note:	Not Reported
Level reading date:	1954-12-27	Feet below surface:	Not Reported
Feet to sea level:	-5.61	Note:	Not Reported
Level reading date:	1954-06-29	Feet below surface:	Not Reported
Feet to sea level:	-6.25	Note:	Not Reported
Level reading date:	1954-05-27	Feet below surface:	Not Reported
Feet to sea level:	-6.72	Note:	Not Reported
Level reading date:	1954-04-28	Feet below surface:	Not Reported
Feet to sea level:	-6.79	Note:	Not Reported
Level reading date:	1954-03-30	Feet below surface:	Not Reported
Feet to sea level:	-6.87	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	-7.02	Note:	Not Reported
Level reading date:	1954-01-28	Feet below surface:	Not Reported
Feet to sea level:	-7.19	Note:	Not Reported
Level reading date:	1953-12-23	Feet below surface:	Not Reported
Feet to sea level:	-7.15	Note:	Not Reported
Level reading date:	1953-12-02	Feet below surface:	Not Reported
Feet to sea level:	-7.25	Note:	Not Reported
Level reading date:	1953-10-02	Feet below surface:	Not Reported
Feet to sea level:	-7.61	Note:	Not Reported
Level reading date:	1953-08-03	Feet below surface:	Not Reported
Feet to sea level:	-7.45	Note:	Not Reported
Level reading date:	1953-06-23	Feet below surface:	Not Reported
Feet to sea level:	-7.47	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	-7.91	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	-8.26	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	-8.82	Note:	Not Reported
Level reading date:	1953-02-27	Feet below surface:	Not Reported
Feet to sea level:	-9.10	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	-9.37	Note:	Not Reported
Level reading date:	1952-12-24	Feet below surface:	Not Reported
Feet to sea level:	-10.14	Note:	Not Reported

Level reading date:	1952-12-05	Feet below surface:	Not Reported
Feet to sea level:	-10.54	Note:	Not Reported
Level reading date:	1952-11-03	Feet below surface:	Not Reported
Feet to sea level:	-11.13	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	-12.22	Note:	Not Reported
Level reading date:	1952-07-25	Feet below surface:	Not Reported
Feet to sea level:	-12.62	Note:	Not Reported
Level reading date:	1952-06-24	Feet below surface:	Not Reported
Feet to sea level:	-13.11	Note:	Not Reported
Level reading date:	1952-05-27	Feet below surface:	Not Reported
Feet to sea level:	-13.84	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	-14.33	Note:	Not Reported
Level reading date:	1952-03-24	Feet below surface:	Not Reported
Feet to sea level:	-15.09	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	-15.88	Note:	Not Reported
Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	-16.33	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	-16.98	Note:	Not Reported
Level reading date:	1951-11-28	Feet below surface:	Not Reported
Feet to sea level:	-17.37	Note:	Not Reported
Level reading date:	1951-11-02	Feet below surface:	Not Reported
Feet to sea level:	-17.86	Note:	Not Reported
Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-18.29	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-18.53	Note:	Not Reported
Level reading date:	1951-07-26	Feet below surface:	Not Reported
Feet to sea level:	-18.97	Note:	Not Reported
Level reading date:	1951-06-28	Feet below surface:	Not Reported
Feet to sea level:	-19.39	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-19.79	Note:	Not Reported
Level reading date:	1951-05-02	Feet below surface:	Not Reported
Feet to sea level:	-20.22	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-20.97	Note:	Not Reported
Level reading date:	1951-02-26	Feet below surface:	Not Reported
Feet to sea level:	-21.64	Note:	Not Reported

Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-22.36	Note:	Not Reported
Level reading date:	1950-12-20	Feet below surface:	Not Reported
Feet to sea level:	-24.01	Note:	Not Reported
Level reading date:	1950-11-28	Feet below surface:	Not Reported
Feet to sea level:	-24.60	Note:	Not Reported
Level reading date:	1950-10-31	Feet below surface:	Not Reported
Feet to sea level:	-24.76	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-24.78	Note:	Not Reported
Level reading date:	1950-08-29	Feet below surface:	Not Reported
Feet to sea level:	-24.63	Note:	Not Reported
Level reading date:	1950-07-27	Feet below surface:	Not Reported
Feet to sea level:	-24.48	Note:	Not Reported
Level reading date:	1950-06-29	Feet below surface:	Not Reported
Feet to sea level:	-24.52	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-24.63	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-24.97	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-24.90	Note:	Not Reported
Level reading date:	1950-03-01	Feet below surface:	Not Reported
Feet to sea level:	-25.44	Note:	Not Reported
Level reading date:	1950-01-26	Feet below surface:	Not Reported
Feet to sea level:	-25.69	Note:	Not Reported
Level reading date:	1949-12-28	Feet below surface:	Not Reported
Feet to sea level:	-25.78	Note:	Not Reported
Level reading date:	1949-11-28	Feet below surface:	Not Reported
Feet to sea level:	-25.76	Note:	Not Reported
Level reading date:	1949-10-31	Feet below surface:	Not Reported
Feet to sea level:	-25.53	Note:	Not Reported
Level reading date:	1949-09-28	Feet below surface:	Not Reported
Feet to sea level:	-25.59	Note:	Not Reported
Level reading date:	1949-08-31	Feet below surface:	Not Reported
Feet to sea level:	-25.62	Note:	Not Reported
Level reading date:	1949-07-28	Feet below surface:	Not Reported
Feet to sea level:	-25.72	Note:	Not Reported
Level reading date:	1949-06-30	Feet below surface:	Not Reported
Feet to sea level:	-25.89	Note:	Not Reported
Level reading date:	1949-06-01	Feet below surface:	Not Reported
Feet to sea level:	-26.02	Note:	Not Reported

Level reading date:	1949-04-28	Feet below surface:	Not Reported
Feet to sea level:	-26.14	Note:	Not Reported
Level reading date:	1949-04-05	Feet below surface:	Not Reported
Feet to sea level:	-26.39	Note:	Not Reported
Level reading date:	1949-02-23	Feet below surface:	Not Reported
Feet to sea level:	-27.08	Note:	Not Reported
Level reading date:	1949-01-27	Feet below surface:	Not Reported
Feet to sea level:	-27.47	Note:	Not Reported
Level reading date:	1948-12-28	Feet below surface:	Not Reported
Feet to sea level:	-27.87	Note:	Not Reported
Level reading date:	1948-12-14	Feet below surface:	Not Reported
Feet to sea level:	-28.03	Note:	Not Reported
Level reading date:	1948-11-04	Feet below surface:	Not Reported
Feet to sea level:	-28.60	Note:	Not Reported
Level reading date:	1948-10-06	Feet below surface:	Not Reported
Feet to sea level:	-28.94	Note:	Not Reported
Level reading date:	1948-08-30	Feet below surface:	Not Reported
Feet to sea level:	-29.46	Note:	Not Reported
Level reading date:	1948-07-26	Feet below surface:	Not Reported
Feet to sea level:	-30.22	Note:	Not Reported
Level reading date:	1948-06-30	Feet below surface:	Not Reported
Feet to sea level:	-30.77	Note:	Not Reported
Level reading date:	1948-06-02	Feet below surface:	Not Reported
Feet to sea level:	-31.35	Note:	Not Reported
Level reading date:	1948-04-27	Feet below surface:	Not Reported
Feet to sea level:	-32.12	Note:	Not Reported
Level reading date:	1948-03-26	Feet below surface:	Not Reported
Feet to sea level:	-32.84	Note:	Not Reported
Level reading date:	1948-03-02	Feet below surface:	Not Reported
Feet to sea level:	-33.43	Note:	Not Reported
Level reading date:	1948-02-03	Feet below surface:	Not Reported
Feet to sea level:	-34.37	Note:	Not Reported
Level reading date:	1948-01-07	Feet below surface:	Not Reported
Feet to sea level:	-35.55	Note:	Not Reported
Level reading date:	1947-12-17	Feet below surface:	Not Reported
Feet to sea level:	-35.93	Note:	Not Reported
Level reading date:	1947-11-26	Feet below surface:	Not Reported
Feet to sea level:	-36.76	Note:	Not Reported
Level reading date:	1947-11-20	Feet below surface:	Not Reported
Feet to sea level:	-36.87	Note:	Not Reported
Level reading date:	1947-10-31	Feet below surface:	Not Reported
Feet to sea level:	-37.15	Note:	Not Reported

Level reading date:	1947-10-14	Feet below surface:	Not Reported
Feet to sea level:	-37.22	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	Not Reported
Feet to sea level:	-37.17	Note:	Not Reported
Level reading date:	1947-09-30	Feet below surface:	Not Reported
Feet to sea level:	-37.13	Note:	Not Reported
Level reading date:	1947-09-16	Feet below surface:	Not Reported
Feet to sea level:	-37.00	Note:	Not Reported
Level reading date:	1947-08-27	Feet below surface:	Not Reported
Feet to sea level:	-36.56	Note:	Not Reported
Level reading date:	1947-08-13	Feet below surface:	Not Reported
Feet to sea level:	-36.15	Note:	Not Reported
Level reading date:	1947-07-30	Feet below surface:	Not Reported
Feet to sea level:	-35.58	Note:	Not Reported
Level reading date:	1947-07-23	Feet below surface:	Not Reported
Feet to sea level:	-35.29	Note:	Not Reported
Level reading date:	1947-07-16	Feet below surface:	Not Reported
Feet to sea level:	-35.21	Note:	Not Reported
Level reading date:	1947-07-07	Feet below surface:	Not Reported
Feet to sea level:	-35.95	Note:	Not Reported
Level reading date:	1947-07-02	Feet below surface:	Not Reported
Feet to sea level:	-36.46	Note:	Not Reported
Level reading date:	1947-07-01	Feet below surface:	Not Reported
Feet to sea level:	-36.32	Note:	Not Reported
Level reading date:	1947-06-30	Feet below surface:	Not Reported
Feet to sea level:	-36.69	Note:	Not Reported
Level reading date:	1947-06-24	Feet below surface:	Not Reported
Feet to sea level:	-37.12	Note:	Not Reported
Level reading date:	1947-06-20	Feet below surface:	Not Reported
Feet to sea level:	-37.16	Note:	Not Reported
Level reading date:	1947-06-13	Feet below surface:	Not Reported
Feet to sea level:	-37.06	Note:	Not Reported
Level reading date:	1947-06-06	Feet below surface:	Not Reported
Feet to sea level:	-36.95	Note:	Not Reported
Level reading date:	1947-05-29	Feet below surface:	Not Reported
Feet to sea level:	-36.78	Note:	Not Reported
Level reading date:	1947-05-23	Feet below surface:	Not Reported
Feet to sea level:	-36.63	Note:	Not Reported
Level reading date:	1947-05-17	Feet below surface:	Not Reported
Feet to sea level:	-36.47	Note:	Not Reported
Level reading date:	1947-05-16	Feet below surface:	Not Reported
Feet to sea level:	-36.41	Note:	Not Reported

Level reading date:	1947-05-10	Feet below surface:	Not Reported
Feet to sea level:	-35.93	Note:	Not Reported
Level reading date:	1947-05-03	Feet below surface:	Not Reported
Feet to sea level:	-35.89	Note:	Not Reported
Level reading date:	1947-04-26	Feet below surface:	Not Reported
Feet to sea level:	-35.43	Note:	Not Reported
Level reading date:	1947-04-19	Feet below surface:	Not Reported
Feet to sea level:	-35.17	Note:	Not Reported
Level reading date:	1947-04-18	Feet below surface:	Not Reported
Feet to sea level:	-35.09	Note:	Not Reported
Level reading date:	1947-03-29	Feet below surface:	Not Reported
Feet to sea level:	-33.64	Note:	Not Reported
Level reading date:	1947-03-22	Feet below surface:	Not Reported
Feet to sea level:	-33.32	Note:	Not Reported
Level reading date:	1947-03-08	Feet below surface:	Not Reported
Feet to sea level:	-34.08	Note:	Not Reported
Level reading date:	1947-03-01	Feet below surface:	Not Reported
Feet to sea level:	-35.65	Note:	Not Reported
Level reading date:	1947-02-22	Feet below surface:	Not Reported
Feet to sea level:	-36.06	Note:	Not Reported
Level reading date:	1947-02-15	Feet below surface:	Not Reported
Feet to sea level:	-36.93	Note:	Not Reported
Level reading date:	1947-02-08	Feet below surface:	Not Reported
Feet to sea level:	-37.58	Note:	Not Reported
Level reading date:	1947-02-01	Feet below surface:	Not Reported
Feet to sea level:	-38.31	Note:	Not Reported
Level reading date:	1947-01-25	Feet below surface:	Not Reported
Feet to sea level:	-39.01	Note:	Not Reported
Level reading date:	1947-01-18	Feet below surface:	Not Reported
Feet to sea level:	-37.73	Note:	Not Reported
Level reading date:	1947-01-10	Feet below surface:	Not Reported
Feet to sea level:	-37.61	Note:	Not Reported
Level reading date:	1946-10-19	Feet below surface:	Not Reported
Feet to sea level:	-31.90	Note:	Not Reported
Level reading date:	1946-10-12	Feet below surface:	Not Reported
Feet to sea level:	-27.83	Note:	Not Reported
Level reading date:	1946-10-05	Feet below surface:	Not Reported
Feet to sea level:	-20.51	Note:	Not Reported
Level reading date:	1946-09-23	Feet below surface:	Not Reported
Feet to sea level:	-36.25	Note:	Not Reported
Level reading date:	1946-09-16	Feet below surface:	Not Reported
Feet to sea level:	-37.75	Note:	Not Reported

Level reading date:	1946-08-30	Feet below surface:	Not Reported
Feet to sea level:	-38.35	Note:	Not Reported
Level reading date:	1946-08-19	Feet below surface:	Not Reported
Feet to sea level:	-38.17	Note:	Not Reported
Level reading date:	1946-07-30	Feet below surface:	Not Reported
Feet to sea level:	-37.69	Note:	Not Reported
Level reading date:	1946-07-08	Feet below surface:	Not Reported
Feet to sea level:	-37.25	Note:	Not Reported
Level reading date:	1946-06-10	Feet below surface:	Not Reported
Feet to sea level:	-36.63	Note:	Not Reported
Level reading date:	1946-05-27	Feet below surface:	Not Reported
Feet to sea level:	-36.17	Note:	Not Reported
Level reading date:	1946-05-20	Feet below surface:	Not Reported
Feet to sea level:	-35.97	Note:	Not Reported
Level reading date:	1946-05-13	Feet below surface:	Not Reported
Feet to sea level:	-35.55	Note:	Not Reported
Level reading date:	1946-05-06	Feet below surface:	Not Reported
Feet to sea level:	-35.32	Note:	Not Reported
Level reading date:	1946-04-29	Feet below surface:	Not Reported
Feet to sea level:	-35.07	Note:	Not Reported
Level reading date:	1946-04-22	Feet below surface:	Not Reported
Feet to sea level:	-35.31	Note:	Not Reported
Level reading date:	1946-04-15	Feet below surface:	Not Reported
Feet to sea level:	-35.44	Note:	Not Reported
Level reading date:	1946-04-08	Feet below surface:	Not Reported
Feet to sea level:	-35.56	Note:	Not Reported
Level reading date:	1946-04-01	Feet below surface:	Not Reported
Feet to sea level:	-35.67	Note:	Not Reported
Level reading date:	1946-03-25	Feet below surface:	Not Reported
Feet to sea level:	-35.66	Note:	Not Reported
Level reading date:	1946-03-18	Feet below surface:	Not Reported
Feet to sea level:	-35.80	Note:	Not Reported
Level reading date:	1946-03-11	Feet below surface:	Not Reported
Feet to sea level:	-35.79	Note:	Not Reported
Level reading date:	1946-03-04	Feet below surface:	Not Reported
Feet to sea level:	-35.75	Note:	Not Reported
Level reading date:	1946-02-25	Feet below surface:	Not Reported
Feet to sea level:	-35.66	Note:	Not Reported
Level reading date:	1946-02-18	Feet below surface:	Not Reported
Feet to sea level:	-35.67	Note:	Not Reported
Level reading date:	1946-02-11	Feet below surface:	Not Reported
Feet to sea level:	-35.61	Note:	Not Reported

Level reading date:	1946-01-08	Feet below surface:	Not Reported
Feet to sea level:	-35.07	Note:	Not Reported
Level reading date:	1945-12-03	Feet below surface:	Not Reported
Feet to sea level:	-34.78	Note:	Not Reported
Level reading date:	1945-11-06	Feet below surface:	Not Reported
Feet to sea level:	-34.30	Note:	Not Reported
Level reading date:	1945-09-28	Feet below surface:	Not Reported
Feet to sea level:	-33.23	Note:	Not Reported
Level reading date:	1945-09-12	Feet below surface:	Not Reported
Feet to sea level:	-32.54	Note:	Not Reported
Level reading date:	1945-08-08	Feet below surface:	Not Reported
Feet to sea level:	-30.12	Note:	Not Reported
Level reading date:	1945-07-23	Feet below surface:	Not Reported
Feet to sea level:	-30.27	Note:	Not Reported
Level reading date:	1945-07-03	Feet below surface:	Not Reported
Feet to sea level:	-30.41	Note:	Not Reported
Level reading date:	1945-06-04	Feet below surface:	Not Reported
Feet to sea level:	-30.46	Note:	Not Reported

E16
NNW
1/4 - 1/2 Mile
Lower

NY WELLS **NYREG1000000037**

Well Number:	K003398	Owner:	Brooklyn Union Gas
Well Depth:	30	Diameter:	2
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

E17
NNW
1/4 - 1/2 Mile
Lower

NY WELLS **NYREG1000000036**

Well Number:	K003397	Owner:	Brooklyn Union Gas
Well Depth:	30	Diameter:	2
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

E18
NNW
1/4 - 1/2 Mile
Lower

NY WELLS **NYREG1000000038**

Well Number:	K003399	Owner:	Brooklyn Union Gas
Well Depth:	30	Diameter:	2
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

E19
NNW
1/4 - 1/2 Mile
Lower

NY WELLS **NYREG1000000043**

Well Number:	K003404	Owner:	Brooklyn Union
Well Depth:	20	Diameter:	4
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

E20
NNW
1/4 - 1/2 Mile
Lower

NY WELLS **NYREG1000000042**

Well Number:	K003403	Owner:	Brooklyn Union
Well Depth:	20	Diameter:	4
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

21
SSW
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000829247**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 3111. 1	Type:	Well
Description:	0001	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	95
Well Hole Depth Units:	ft		

F22
SSW
1/4 - 1/2 Mile
Higher

NY WELLS **NYREG1000000185**

Well Number:	K003535	Owner:	Rapid Ready Mix Corporation
Well Depth:	80	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

F23
SSW
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000000188**

Well Number:	K003538	Owner:	North Shore Ready Mix
Well Depth:	100	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

24
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829597**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 677. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	215	Well Hole Depth Units:	ft

25
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829202**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2568. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	100	Well Hole Depth Units:	ft

G26
SW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829232**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 893. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	118	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G27
SW
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000000018**

Well Number:	K003120D	Owner:	Bart, Alvin
Well Depth:	76	Diameter:	8
Casing Length:	56	Screen Diameter:	6
Screen Length:	20		

28
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829791**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 436. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	217	Well Hole Depth Units:	ft

G29
SW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829233**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 955. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	72	Well Hole Depth Units:	ft

30
SW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829234**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1130. 1	Type:	Well
Description:	1301	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	89	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

31
SSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829116**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 894. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	282	Well Hole Depth Units:	ft

H32
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829101**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1576. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	68	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	22	Level reading date:	1969-04-23
Feet below surface:	Not Reported	Feet to sea level:	2.13
Note:	Not Reported		

Level reading date:	1968-11-06	Feet below surface:	Not Reported
Feet to sea level:	-1.59	Note:	Not Reported
Level reading date:	1968-04-22	Feet below surface:	Not Reported
Feet to sea level:	2.68	Note:	Not Reported
Level reading date:	1967-10-20	Feet below surface:	Not Reported
Feet to sea level:	1.81	Note:	Not Reported
Level reading date:	1967-03-28	Feet below surface:	Not Reported
Feet to sea level:	1.37	Note:	Not Reported
Level reading date:	1966-10-24	Feet below surface:	Not Reported
Feet to sea level:	-0.39	Note:	Not Reported
Level reading date:	1966-05-03	Feet below surface:	Not Reported
Feet to sea level:	1.92	Note:	Not Reported
Level reading date:	1965-09-15	Feet below surface:	Not Reported
Feet to sea level:	-0.04	Note:	Not Reported
Level reading date:	1965-05-03	Feet below surface:	Not Reported
Feet to sea level:	0.89	Note:	Not Reported

Level reading date:	1964-10-30	Feet below surface:	Not Reported
Feet to sea level:	0.55	Note:	Not Reported
Level reading date:	1964-04-27	Feet below surface:	Not Reported
Feet to sea level:	2.46	Note:	Not Reported
Level reading date:	1963-04-11	Feet below surface:	Not Reported
Feet to sea level:	2.69	Note:	Not Reported
Level reading date:	1962-04-26	Feet below surface:	Not Reported
Feet to sea level:	2.64	Note:	Not Reported
Level reading date:	1961-12-27	Feet below surface:	Not Reported
Feet to sea level:	1.13	Note:	Not Reported
Level reading date:	1961-01-09	Feet below surface:	Not Reported
Feet to sea level:	-0.69	Note:	Not Reported
Level reading date:	1960-01-14	Feet below surface:	Not Reported
Feet to sea level:	-0.81	Note:	Not Reported
Level reading date:	1959-03-18	Feet below surface:	Not Reported
Feet to sea level:	-1.83	Note:	Not Reported
Level reading date:	1957-03-15	Feet below surface:	Not Reported
Feet to sea level:	-1.50	Note:	Not Reported
Level reading date:	1953-01-13	Feet below surface:	Not Reported
Feet to sea level:	-8.08	Note:	Not Reported
Level reading date:	1952-01-02	Feet below surface:	Not Reported
Feet to sea level:	-14.55	Note:	Not Reported
Level reading date:	1950-12-12	Feet below surface:	Not Reported
Feet to sea level:	-17.74	Note:	Not Reported
Level reading date:	1949-12-16	Feet below surface:	Not Reported
Feet to sea level:	-19.23	Note:	Not Reported

I33
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829273**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1490. 1	Type:	Well
Description:	2301	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	135	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

I34
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829261**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 37. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	130	Well Hole Depth Units:	ft

H35
South
1/2 - 1 Mile
Higher

FED USGS **USGS40000829082**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1575. 1	Type:	Well
Description:	3401	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	85	Well Hole Depth Units:	ft

36
WNW
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000000142**

Well Number:	K003496	Owner:	Lees Farm
Well Depth:	85	Diameter:	4
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

J37
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829385**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1283. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	240	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J38
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829386**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 724. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	137	Well Hole Depth Units:	ft

39
SSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829063**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 87. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	160	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	184	Level reading date:	1941-05-31
Feet below surface:	Not Reported	Feet to sea level:	-9.41
Note:	Not Reported		

Level reading date:	1941-05-24	Feet below surface:	Not Reported
Feet to sea level:	-9.39	Note:	Not Reported
Level reading date:	1941-05-17	Feet below surface:	Not Reported
Feet to sea level:	-9.36	Note:	Not Reported
Level reading date:	1941-05-10	Feet below surface:	Not Reported
Feet to sea level:	-9.36	Note:	Not Reported
Level reading date:	1941-05-03	Feet below surface:	Not Reported
Feet to sea level:	-9.32	Note:	Not Reported
Level reading date:	1941-04-26	Feet below surface:	Not Reported
Feet to sea level:	-9.30	Note:	Not Reported
Level reading date:	1941-04-19	Feet below surface:	Not Reported
Feet to sea level:	-9.27	Note:	Not Reported
Level reading date:	1941-04-12	Feet below surface:	Not Reported
Feet to sea level:	-9.27	Note:	Not Reported
Level reading date:	1941-04-05	Feet below surface:	Not Reported
Feet to sea level:	-9.25	Note:	Not Reported

Level reading date:	1941-03-29	Feet below surface:	Not Reported
Feet to sea level:	-9.25	Note:	Not Reported
Level reading date:	1941-03-22	Feet below surface:	Not Reported
Feet to sea level:	-9.24	Note:	Not Reported
Level reading date:	1941-03-15	Feet below surface:	Not Reported
Feet to sea level:	-9.24	Note:	Not Reported
Level reading date:	1941-03-08	Feet below surface:	Not Reported
Feet to sea level:	-9.22	Note:	Not Reported
Level reading date:	1941-03-01	Feet below surface:	Not Reported
Feet to sea level:	-9.22	Note:	Not Reported
Level reading date:	1941-02-22	Feet below surface:	Not Reported
Feet to sea level:	-9.22	Note:	Not Reported
Level reading date:	1941-02-15	Feet below surface:	Not Reported
Feet to sea level:	-9.22	Note:	Not Reported
Level reading date:	1941-02-08	Feet below surface:	Not Reported
Feet to sea level:	-9.22	Note:	Not Reported
Level reading date:	1941-02-01	Feet below surface:	Not Reported
Feet to sea level:	-9.23	Note:	Not Reported
Level reading date:	1941-01-25	Feet below surface:	Not Reported
Feet to sea level:	-9.23	Note:	Not Reported
Level reading date:	1941-01-18	Feet below surface:	Not Reported
Feet to sea level:	-9.24	Note:	Not Reported
Level reading date:	1941-01-11	Feet below surface:	Not Reported
Feet to sea level:	-9.24	Note:	Not Reported
Level reading date:	1941-01-04	Feet below surface:	Not Reported
Feet to sea level:	-9.26	Note:	Not Reported
Level reading date:	1940-12-28	Feet below surface:	Not Reported
Feet to sea level:	-9.25	Note:	Not Reported
Level reading date:	1940-12-21	Feet below surface:	Not Reported
Feet to sea level:	-9.24	Note:	Not Reported
Level reading date:	1940-12-14	Feet below surface:	Not Reported
Feet to sea level:	-9.20	Note:	Not Reported
Level reading date:	1940-12-07	Feet below surface:	Not Reported
Feet to sea level:	-9.19	Note:	Not Reported
Level reading date:	1940-11-30	Feet below surface:	Not Reported
Feet to sea level:	-9.16	Note:	Not Reported
Level reading date:	1940-11-23	Feet below surface:	Not Reported
Feet to sea level:	-9.13	Note:	Not Reported
Level reading date:	1940-11-16	Feet below surface:	Not Reported
Feet to sea level:	-9.13	Note:	Not Reported
Level reading date:	1940-11-09	Feet below surface:	Not Reported
Feet to sea level:	-9.10	Note:	Not Reported

Level reading date:	1940-11-02	Feet below surface:	Not Reported
Feet to sea level:	-9.05	Note:	Not Reported
Level reading date:	1940-10-26	Feet below surface:	Not Reported
Feet to sea level:	-9.03	Note:	Not Reported
Level reading date:	1940-10-19	Feet below surface:	Not Reported
Feet to sea level:	-8.98	Note:	Not Reported
Level reading date:	1940-10-12	Feet below surface:	Not Reported
Feet to sea level:	-8.92	Note:	Not Reported
Level reading date:	1940-10-05	Feet below surface:	Not Reported
Feet to sea level:	-8.91	Note:	Not Reported
Level reading date:	1940-09-28	Feet below surface:	Not Reported
Feet to sea level:	-8.88	Note:	Not Reported
Level reading date:	1940-09-21	Feet below surface:	Not Reported
Feet to sea level:	-8.82	Note:	Not Reported
Level reading date:	1940-09-14	Feet below surface:	Not Reported
Feet to sea level:	-8.74	Note:	Not Reported
Level reading date:	1940-09-07	Feet below surface:	Not Reported
Feet to sea level:	-8.67	Note:	Not Reported
Level reading date:	1940-08-31	Feet below surface:	Not Reported
Feet to sea level:	-8.51	Note:	Not Reported
Level reading date:	1940-08-24	Feet below surface:	Not Reported
Feet to sea level:	-8.55	Note:	Not Reported
Level reading date:	1940-08-17	Feet below surface:	Not Reported
Feet to sea level:	-8.44	Note:	Not Reported
Level reading date:	1940-08-10	Feet below surface:	Not Reported
Feet to sea level:	-8.50	Note:	Not Reported
Level reading date:	1940-08-03	Feet below surface:	Not Reported
Feet to sea level:	-8.34	Note:	Not Reported
Level reading date:	1940-07-20	Feet below surface:	Not Reported
Feet to sea level:	-8.86	Note:	Not Reported
Level reading date:	1940-07-13	Feet below surface:	Not Reported
Feet to sea level:	-8.70	Note:	Not Reported
Level reading date:	1940-07-06	Feet below surface:	Not Reported
Feet to sea level:	-8.72	Note:	Not Reported
Level reading date:	1940-06-29	Feet below surface:	Not Reported
Feet to sea level:	-7.98	Note:	Not Reported
Level reading date:	1940-06-22	Feet below surface:	Not Reported
Feet to sea level:	-8.45	Note:	Not Reported
Level reading date:	1940-06-15	Feet below surface:	Not Reported
Feet to sea level:	-8.10	Note:	Not Reported
Level reading date:	1940-06-08	Feet below surface:	Not Reported
Feet to sea level:	-7.91	Note:	Not Reported

Level reading date:	1940-06-01	Feet below surface:	Not Reported
Feet to sea level:	-7.83	Note:	Not Reported
Level reading date:	1940-05-25	Feet below surface:	Not Reported
Feet to sea level:	-7.79	Note:	Not Reported
Level reading date:	1940-05-18	Feet below surface:	Not Reported
Feet to sea level:	-7.78	Note:	Not Reported
Level reading date:	1940-05-11	Feet below surface:	Not Reported
Feet to sea level:	-7.77	Note:	Not Reported
Level reading date:	1940-05-04	Feet below surface:	Not Reported
Feet to sea level:	-7.75	Note:	Not Reported
Level reading date:	1940-04-27	Feet below surface:	Not Reported
Feet to sea level:	-7.73	Note:	Not Reported
Level reading date:	1940-04-20	Feet below surface:	Not Reported
Feet to sea level:	-7.72	Note:	Not Reported
Level reading date:	1940-04-13	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1940-04-06	Feet below surface:	Not Reported
Feet to sea level:	-7.60	Note:	Not Reported
Level reading date:	1940-03-30	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1940-03-23	Feet below surface:	Not Reported
Feet to sea level:	-7.71	Note:	Not Reported
Level reading date:	1940-03-16	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1940-03-09	Feet below surface:	Not Reported
Feet to sea level:	-7.71	Note:	Not Reported
Level reading date:	1940-03-02	Feet below surface:	Not Reported
Feet to sea level:	-7.68	Note:	Not Reported
Level reading date:	1940-02-24	Feet below surface:	Not Reported
Feet to sea level:	-7.71	Note:	Not Reported
Level reading date:	1940-02-17	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1940-02-10	Feet below surface:	Not Reported
Feet to sea level:	-8.44	Note:	Not Reported
Level reading date:	1940-02-03	Feet below surface:	Not Reported
Feet to sea level:	-8.47	Note:	Not Reported
Level reading date:	1940-01-27	Feet below surface:	Not Reported
Feet to sea level:	-8.37	Note:	Not Reported
Level reading date:	1940-01-20	Feet below surface:	Not Reported
Feet to sea level:	-8.43	Note:	Not Reported
Level reading date:	1940-01-13	Feet below surface:	Not Reported
Feet to sea level:	-8.51	Note:	Not Reported

Level reading date:	1940-01-06	Feet below surface:	Not Reported
Feet to sea level:	-8.73	Note:	Not Reported
Level reading date:	1939-12-30	Feet below surface:	Not Reported
Feet to sea level:	-8.58	Note:	Not Reported
Level reading date:	1939-12-23	Feet below surface:	Not Reported
Feet to sea level:	-8.73	Note:	Not Reported
Level reading date:	1939-12-16	Feet below surface:	Not Reported
Feet to sea level:	-8.77	Note:	Not Reported
Level reading date:	1939-12-09	Feet below surface:	Not Reported
Feet to sea level:	-8.56	Note:	Not Reported
Level reading date:	1939-12-02	Feet below surface:	Not Reported
Feet to sea level:	-8.70	Note:	Not Reported
Level reading date:	1939-11-25	Feet below surface:	Not Reported
Feet to sea level:	-8.92	Note:	Not Reported
Level reading date:	1939-11-18	Feet below surface:	Not Reported
Feet to sea level:	-9.02	Note:	Not Reported
Level reading date:	1939-11-11	Feet below surface:	Not Reported
Feet to sea level:	-8.91	Note:	Not Reported
Level reading date:	1939-11-04	Feet below surface:	Not Reported
Feet to sea level:	-8.93	Note:	Not Reported
Level reading date:	1939-10-28	Feet below surface:	Not Reported
Feet to sea level:	-8.98	Note:	Not Reported
Level reading date:	1939-10-21	Feet below surface:	Not Reported
Feet to sea level:	-8.92	Note:	Not Reported
Level reading date:	1939-10-14	Feet below surface:	Not Reported
Feet to sea level:	-8.98	Note:	Not Reported
Level reading date:	1939-10-07	Feet below surface:	Not Reported
Feet to sea level:	-8.82	Note:	Not Reported
Level reading date:	1939-09-30	Feet below surface:	Not Reported
Feet to sea level:	-8.87	Note:	Not Reported
Level reading date:	1939-09-23	Feet below surface:	Not Reported
Feet to sea level:	-7.99	Note:	Not Reported
Level reading date:	1939-09-16	Feet below surface:	Not Reported
Feet to sea level:	-7.92	Note:	Not Reported
Level reading date:	1939-09-08	Feet below surface:	Not Reported
Feet to sea level:	-7.87	Note:	Not Reported
Level reading date:	1939-09-01	Feet below surface:	Not Reported
Feet to sea level:	-7.82	Note:	Not Reported
Level reading date:	1939-08-25	Feet below surface:	Not Reported
Feet to sea level:	-7.76	Note:	Not Reported
Level reading date:	1939-08-18	Feet below surface:	Not Reported
Feet to sea level:	-7.70	Note:	Not Reported

Level reading date:	1939-08-11	Feet below surface:	Not Reported
Feet to sea level:	-7.63	Note:	Not Reported
Level reading date:	1939-08-04	Feet below surface:	Not Reported
Feet to sea level:	-7.60	Note:	Not Reported
Level reading date:	1939-07-28	Feet below surface:	Not Reported
Feet to sea level:	-7.53	Note:	Not Reported
Level reading date:	1939-07-07	Feet below surface:	Not Reported
Feet to sea level:	-7.33	Note:	Not Reported
Level reading date:	1939-06-30	Feet below surface:	Not Reported
Feet to sea level:	-7.33	Note:	Not Reported
Level reading date:	1939-06-23	Feet below surface:	Not Reported
Feet to sea level:	-7.33	Note:	Not Reported
Level reading date:	1939-06-16	Feet below surface:	Not Reported
Feet to sea level:	-7.36	Note:	Not Reported
Level reading date:	1939-06-09	Feet below surface:	Not Reported
Feet to sea level:	-7.38	Note:	Not Reported
Level reading date:	1939-06-02	Feet below surface:	Not Reported
Feet to sea level:	-7.39	Note:	Not Reported
Level reading date:	1939-05-26	Feet below surface:	Not Reported
Feet to sea level:	-7.41	Note:	Not Reported
Level reading date:	1939-05-19	Feet below surface:	Not Reported
Feet to sea level:	-7.45	Note:	Not Reported
Level reading date:	1939-05-12	Feet below surface:	Not Reported
Feet to sea level:	-7.48	Note:	Not Reported
Level reading date:	1939-05-05	Feet below surface:	Not Reported
Feet to sea level:	-7.46	Note:	Not Reported
Level reading date:	1939-04-28	Feet below surface:	Not Reported
Feet to sea level:	-7.48	Note:	Not Reported
Level reading date:	1939-04-21	Feet below surface:	Not Reported
Feet to sea level:	-7.48	Note:	Not Reported
Level reading date:	1939-04-15	Feet below surface:	Not Reported
Feet to sea level:	-7.50	Note:	Not Reported
Level reading date:	1939-04-08	Feet below surface:	Not Reported
Feet to sea level:	-7.52	Note:	Not Reported
Level reading date:	1939-03-31	Feet below surface:	Not Reported
Feet to sea level:	-7.61	Note:	Not Reported
Level reading date:	1939-03-24	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1939-03-17	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1939-03-10	Feet below surface:	Not Reported
Feet to sea level:	-7.63	Note:	Not Reported

Level reading date:	1939-03-03	Feet below surface:	Not Reported
Feet to sea level:	-7.92	Note:	Not Reported
Level reading date:	1939-02-24	Feet below surface:	Not Reported
Feet to sea level:	-7.70	Note:	Not Reported
Level reading date:	1939-02-17	Feet below surface:	Not Reported
Feet to sea level:	-7.72	Note:	Not Reported
Level reading date:	1939-02-10	Feet below surface:	Not Reported
Feet to sea level:	-7.74	Note:	Not Reported
Level reading date:	1939-02-03	Feet below surface:	Not Reported
Feet to sea level:	-7.79	Note:	Not Reported
Level reading date:	1939-01-27	Feet below surface:	Not Reported
Feet to sea level:	-7.85	Note:	Not Reported
Level reading date:	1939-01-20	Feet below surface:	Not Reported
Feet to sea level:	-7.86	Note:	Not Reported
Level reading date:	1939-01-13	Feet below surface:	Not Reported
Feet to sea level:	-7.89	Note:	Not Reported
Level reading date:	1939-01-06	Feet below surface:	Not Reported
Feet to sea level:	-7.93	Note:	Not Reported
Level reading date:	1938-12-30	Feet below surface:	Not Reported
Feet to sea level:	-7.95	Note:	Not Reported
Level reading date:	1938-12-23	Feet below surface:	Not Reported
Feet to sea level:	-8.00	Note:	Not Reported
Level reading date:	1938-12-16	Feet below surface:	Not Reported
Feet to sea level:	-8.03	Note:	Not Reported
Level reading date:	1938-12-09	Feet below surface:	Not Reported
Feet to sea level:	-8.07	Note:	Not Reported
Level reading date:	1938-12-02	Feet below surface:	Not Reported
Feet to sea level:	-8.13	Note:	Not Reported
Level reading date:	1938-11-25	Feet below surface:	Not Reported
Feet to sea level:	-8.13	Note:	Not Reported
Level reading date:	1938-11-18	Feet below surface:	Not Reported
Feet to sea level:	-8.17	Note:	Not Reported
Level reading date:	1938-11-11	Feet below surface:	Not Reported
Feet to sea level:	-8.16	Note:	Not Reported
Level reading date:	1938-11-04	Feet below surface:	Not Reported
Feet to sea level:	-8.21	Note:	Not Reported
Level reading date:	1938-10-28	Feet below surface:	Not Reported
Feet to sea level:	-8.22	Note:	Not Reported
Level reading date:	1938-10-21	Feet below surface:	Not Reported
Feet to sea level:	-8.24	Note:	Not Reported
Level reading date:	1938-10-14	Feet below surface:	Not Reported
Feet to sea level:	-8.27	Note:	Not Reported

Level reading date:	1938-10-07	Feet below surface:	Not Reported
Feet to sea level:	-8.29	Note:	Not Reported
Level reading date:	1938-09-30	Feet below surface:	Not Reported
Feet to sea level:	-8.33	Note:	Not Reported
Level reading date:	1938-09-23	Feet below surface:	Not Reported
Feet to sea level:	-8.36	Note:	Not Reported
Level reading date:	1938-09-16	Feet below surface:	Not Reported
Feet to sea level:	-8.38	Note:	Not Reported
Level reading date:	1938-09-09	Feet below surface:	Not Reported
Feet to sea level:	-8.36	Note:	Not Reported
Level reading date:	1938-09-02	Feet below surface:	Not Reported
Feet to sea level:	-8.34	Note:	Not Reported
Level reading date:	1938-08-26	Feet below surface:	Not Reported
Feet to sea level:	-8.28	Note:	Not Reported
Level reading date:	1938-08-19	Feet below surface:	Not Reported
Feet to sea level:	-8.26	Note:	Not Reported
Level reading date:	1938-08-12	Feet below surface:	Not Reported
Feet to sea level:	-8.22	Note:	Not Reported
Level reading date:	1938-08-05	Feet below surface:	Not Reported
Feet to sea level:	-8.18	Note:	Not Reported
Level reading date:	1938-07-29	Feet below surface:	Not Reported
Feet to sea level:	-8.13	Note:	Not Reported
Level reading date:	1938-07-22	Feet below surface:	Not Reported
Feet to sea level:	-8.08	Note:	Not Reported
Level reading date:	1938-07-15	Feet below surface:	Not Reported
Feet to sea level:	-8.08	Note:	Not Reported
Level reading date:	1938-07-08	Feet below surface:	Not Reported
Feet to sea level:	-8.00	Note:	Not Reported
Level reading date:	1938-07-01	Feet below surface:	Not Reported
Feet to sea level:	-7.96	Note:	Not Reported
Level reading date:	1938-06-25	Feet below surface:	Not Reported
Feet to sea level:	-7.93	Note:	Not Reported
Level reading date:	1938-06-18	Feet below surface:	Not Reported
Feet to sea level:	-7.86	Note:	Not Reported
Level reading date:	1938-06-11	Feet below surface:	Not Reported
Feet to sea level:	-7.83	Note:	Not Reported
Level reading date:	1938-06-04	Feet below surface:	Not Reported
Feet to sea level:	-7.82	Note:	Not Reported
Level reading date:	1938-05-28	Feet below surface:	Not Reported
Feet to sea level:	-7.77	Note:	Not Reported
Level reading date:	1938-05-21	Feet below surface:	Not Reported
Feet to sea level:	-7.76	Note:	Not Reported

Level reading date:	1938-05-14	Feet below surface:	Not Reported
Feet to sea level:	-7.74	Note:	Not Reported
Level reading date:	1938-05-07	Feet below surface:	Not Reported
Feet to sea level:	-7.74	Note:	Not Reported
Level reading date:	1938-04-30	Feet below surface:	Not Reported
Feet to sea level:	-7.72	Note:	Not Reported
Level reading date:	1938-04-23	Feet below surface:	Not Reported
Feet to sea level:	-7.71	Note:	Not Reported
Level reading date:	1938-04-16	Feet below surface:	Not Reported
Feet to sea level:	-7.68	Note:	Not Reported
Level reading date:	1938-04-09	Feet below surface:	Not Reported
Feet to sea level:	-7.66	Note:	Not Reported
Level reading date:	1938-04-02	Feet below surface:	Not Reported
Feet to sea level:	-7.67	Note:	Not Reported
Level reading date:	1938-03-26	Feet below surface:	Not Reported
Feet to sea level:	-7.67	Note:	Not Reported
Level reading date:	1938-03-19	Feet below surface:	Not Reported
Feet to sea level:	-7.69	Note:	Not Reported
Level reading date:	1938-03-12	Feet below surface:	Not Reported
Feet to sea level:	-7.71	Note:	Not Reported
Level reading date:	1938-03-05	Feet below surface:	Not Reported
Feet to sea level:	-7.73	Note:	Not Reported
Level reading date:	1938-02-26	Feet below surface:	Not Reported
Feet to sea level:	-7.76	Note:	Not Reported
Level reading date:	1938-02-19	Feet below surface:	Not Reported
Feet to sea level:	-7.79	Note:	Not Reported
Level reading date:	1938-02-12	Feet below surface:	Not Reported
Feet to sea level:	-7.83	Note:	Not Reported
Level reading date:	1938-02-04	Feet below surface:	Not Reported
Feet to sea level:	-7.84	Note:	Not Reported
Level reading date:	1938-01-28	Feet below surface:	Not Reported
Feet to sea level:	-7.89	Note:	Not Reported
Level reading date:	1938-01-21	Feet below surface:	Not Reported
Feet to sea level:	-7.91	Note:	Not Reported
Level reading date:	1938-01-14	Feet below surface:	Not Reported
Feet to sea level:	-7.93	Note:	Not Reported
Level reading date:	1938-01-07	Feet below surface:	Not Reported
Feet to sea level:	-7.99	Note:	Not Reported
Level reading date:	1937-12-31	Feet below surface:	Not Reported
Feet to sea level:	-8.02	Note:	Not Reported
Level reading date:	1937-12-24	Feet below surface:	Not Reported
Feet to sea level:	-8.04	Note:	Not Reported

Level reading date:	1937-12-18	Feet below surface:	Not Reported
Feet to sea level:	-8.06	Note:	Not Reported
Level reading date:	1937-12-11	Feet below surface:	Not Reported
Feet to sea level:	-8.13	Note:	Not Reported
Level reading date:	1937-12-04	Feet below surface:	Not Reported
Feet to sea level:	-8.13	Note:	Not Reported
Level reading date:	1937-11-27	Feet below surface:	Not Reported
Feet to sea level:	-8.18	Note:	Not Reported
Level reading date:	1937-11-20	Feet below surface:	Not Reported
Feet to sea level:	-8.23	Note:	Not Reported
Level reading date:	1937-11-13	Feet below surface:	Not Reported
Feet to sea level:	-8.23	Note:	Not Reported
Level reading date:	1937-11-08	Feet below surface:	Not Reported
Feet to sea level:	-8.25	Note:	Not Reported

40
West
1/2 - 1 Mile
Higher

FED USGS **USGS40000829528**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 678. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	221	Well Hole Depth Units:	ft

41
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829291**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 426. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	140	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K42
SSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829052**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 36. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	115
Well Hole Depth Units:	ft		

43
NNW
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000000104**

Well Number:	K003459	Owner:	City Recycling
Well Depth:	60	Diameter:	4
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

L44
South
1/2 - 1 Mile
Higher

FED USGS **USGS40000829000**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1031. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

K45
SSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829031**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1153. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported

Well Depth Units:	Not Reported	Well Hole Depth:	103
Well Hole Depth Units:	ft		

K46
SSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829032**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1273. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	275	Well Hole Depth Units:	ft

47
NNE
1/2 - 1 Mile
Lower

FED USGS **USGS40000829962**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 438. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	208	Well Hole Depth Units:	ft

48
SSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829001**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1336. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	163	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

49
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000829883**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 437. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	260	Well Hole Depth Units:	ft

M50
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829262**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2533. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	92	Well Hole Depth Units:	ft

L51
SSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000828957**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 887. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	125	Well Hole Depth Units:	ft

N52
SSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829002**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 2136. 1	Type:	Well
Description:	1001	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	112	Well Hole Depth Units:	ft

N53
SSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829003**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 236. 1	Type:	Well
Description:	1008	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	130	Well Depth Units:	ft
Well Hole Depth:	130	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	52	Level reading date:	1954-12-17
Feet below surface:	Not Reported	Feet to sea level:	-8.30
Note:	Not Reported		

Level reading date:	1954-06-29	Feet below surface:	Not Reported
Feet to sea level:	-9.31	Note:	Not Reported
Level reading date:	1954-05-27	Feet below surface:	Not Reported
Feet to sea level:	-8.45	Note:	Not Reported
Level reading date:	1954-04-28	Feet below surface:	Not Reported
Feet to sea level:	-10.08	Note:	Not Reported
Level reading date:	1954-03-30	Feet below surface:	Not Reported
Feet to sea level:	-9.85	Note:	Not Reported
Level reading date:	1954-02-25	Feet below surface:	Not Reported
Feet to sea level:	-9.49	Note:	Not Reported
Level reading date:	1954-01-28	Feet below surface:	Not Reported
Feet to sea level:	-10.11	Note:	Not Reported
Level reading date:	1953-12-23	Feet below surface:	Not Reported
Feet to sea level:	-10.76	Note:	Not Reported
Level reading date:	1953-12-02	Feet below surface:	Not Reported
Feet to sea level:	-10.78	Note:	Not Reported
Level reading date:	1953-10-28	Feet below surface:	Not Reported
Feet to sea level:	-10.03	Note:	Not Reported
Level reading date:	1953-10-02	Feet below surface:	Not Reported
Feet to sea level:	-11.58	Note:	Not Reported
Level reading date:	1953-08-28	Feet below surface:	Not Reported
Feet to sea level:	-11.23	Note:	Not Reported
Level reading date:	1953-08-03	Feet below surface:	Not Reported

Feet to sea level:	-11.25	Note:	Not Reported
Level reading date:	1953-06-24	Feet below surface:	Not Reported
Feet to sea level:	-10.48	Note:	Not Reported
Level reading date:	1953-05-25	Feet below surface:	Not Reported
Feet to sea level:	-10.59	Note:	Not Reported
Level reading date:	1953-04-27	Feet below surface:	Not Reported
Feet to sea level:	-11.85	Note:	Not Reported
Level reading date:	1953-03-24	Feet below surface:	Not Reported
Feet to sea level:	-12.38	Note:	Not Reported
Level reading date:	1953-02-27	Feet below surface:	Not Reported
Feet to sea level:	-12.18	Note:	Not Reported
Level reading date:	1953-02-05	Feet below surface:	Not Reported
Feet to sea level:	-12.68	Note:	Not Reported
Level reading date:	1952-12-24	Feet below surface:	Not Reported
Feet to sea level:	-12.74	Note:	Not Reported
Level reading date:	1952-12-05	Feet below surface:	Not Reported
Feet to sea level:	-12.60	Note:	Not Reported
Level reading date:	1952-11-03	Feet below surface:	Not Reported
Feet to sea level:	-13.70	Note:	Not Reported
Level reading date:	1952-09-23	Feet below surface:	Not Reported
Feet to sea level:	-16.95	Note:	Not Reported
Level reading date:	1952-08-25	Feet below surface:	Not Reported
Feet to sea level:	-16.73	Note:	Not Reported
Level reading date:	1952-07-23	Feet below surface:	Not Reported
Feet to sea level:	-17.79	Note:	Not Reported
Level reading date:	1952-06-24	Feet below surface:	Not Reported
Feet to sea level:	-17.05	Note:	Not Reported
Level reading date:	1952-05-27	Feet below surface:	Not Reported
Feet to sea level:	-17.69	Note:	Not Reported
Level reading date:	1952-04-29	Feet below surface:	Not Reported
Feet to sea level:	-19.03	Note:	Not Reported
Level reading date:	1952-03-24	Feet below surface:	Not Reported
Feet to sea level:	-19.20	Note:	Not Reported
Level reading date:	1952-02-20	Feet below surface:	Not Reported
Feet to sea level:	-20.10	Note:	Not Reported
Level reading date:	1952-01-29	Feet below surface:	Not Reported
Feet to sea level:	-20.88	Note:	Not Reported
Level reading date:	1951-12-20	Feet below surface:	Not Reported
Feet to sea level:	-22.55	Note:	Not Reported
Level reading date:	1951-11-28	Feet below surface:	Not Reported
Feet to sea level:	-22.59	Note:	Not Reported

Level reading date:	1951-09-26	Feet below surface:	Not Reported
Feet to sea level:	-24.85	Note:	Not Reported
Level reading date:	1951-08-28	Feet below surface:	Not Reported
Feet to sea level:	-25.66	Note:	Not Reported
Level reading date:	1951-07-26	Feet below surface:	Not Reported
Feet to sea level:	-25.95	Note:	Not Reported
Level reading date:	1951-06-28	Feet below surface:	Not Reported
Feet to sea level:	-25.47	Note:	Not Reported
Level reading date:	1951-05-29	Feet below surface:	Not Reported
Feet to sea level:	-26.24	Note:	Not Reported
Level reading date:	1951-05-02	Feet below surface:	Not Reported
Feet to sea level:	-26.53	Note:	Not Reported
Level reading date:	1951-03-27	Feet below surface:	Not Reported
Feet to sea level:	-26.63	Note:	Not Reported
Level reading date:	1951-02-26	Feet below surface:	Not Reported
Feet to sea level:	-26.78	Note:	Not Reported
Level reading date:	1951-01-30	Feet below surface:	Not Reported
Feet to sea level:	-27.90	Note:	Not Reported
Level reading date:	1950-12-20	Feet below surface:	Not Reported
Feet to sea level:	-28.49	Note:	Not Reported
Level reading date:	1950-11-28	Feet below surface:	Not Reported
Feet to sea level:	-28.00	Note:	Not Reported
Level reading date:	1950-10-31	Feet below surface:	Not Reported
Feet to sea level:	-27.98	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	Not Reported
Feet to sea level:	-29.66	Note:	Not Reported
Level reading date:	1950-08-29	Feet below surface:	Not Reported
Feet to sea level:	-29.53	Note:	Not Reported
Level reading date:	1950-07-27	Feet below surface:	Not Reported
Feet to sea level:	-29.04	Note:	Not Reported
Level reading date:	1950-06-29	Feet below surface:	Not Reported
Feet to sea level:	-27.59	Note:	Not Reported
Level reading date:	1950-06-05	Feet below surface:	Not Reported
Feet to sea level:	-26.28	Note:	Not Reported
Level reading date:	1950-04-27	Feet below surface:	Not Reported
Feet to sea level:	-28.80	Note:	Not Reported
Level reading date:	1950-03-29	Feet below surface:	Not Reported
Feet to sea level:	-28.80	Note:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

54
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000830095**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 1560. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	101	Well Hole Depth Units:	ft

55
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829320**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 715. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	120	Well Hole Depth Units:	ft

56
NW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829892**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 679. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	218	Well Hole Depth Units:	ft

M57
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000829242**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 637. 1	Type:	Well
Description:	4101	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	212	Well Hole Depth Units:	ft

58
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000830073**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 1918. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	82	Well Hole Depth Units:	ft

59
NNW
1/2 - 1 Mile
Higher

FED USGS **USGS40000830081**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	K 689. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	160	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for KINGS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for KINGS COUNTY, NY

Number of sites tested: 51

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.750 pCi/L	100%	0%	0%
Basement	1.370 pCi/L	88%	10%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX F

GOVERNMENT CORRESPONDENCE AND RECORDS

Molly Mattern

From: donotreply@records.nyc.gov
Sent: Thursday, January 20, 2022 4:14 PM
To: Molly Mattern
Subject: [External] [OpenRecords] Request FOIL-2022-826-00315 Submitted to Department of Environmental Protection (DEP)

Follow Up Flag: Follow up
Flag Status: Flagged

Your request FOIL-2022-826-00315 has been successfully submitted to the Department of Environmental Protection (DEP). The details of your request are shown below.

Request Title: 213 Meadow Street (Block 2591, Lots 1, 5, and 45), Brooklyn NY

Request Description: Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the property at 213 Meadow Street (Block 2591, Lots 1, 5, and 45), Brooklyn NY.

Attached File: 1-Site_Location.pdf: 1-Site_Location.pdf

Requester's Contact Information

Name:
Molly Mattern
Title:
Not provided
Organization:
Langan Engineering
Email:
mmattern@langan.com
Phone Number:
(973) 560-4900
Fax Number:
Not provided
Street Address (line 1):
300 Kimball Drive
Street Address (line 2):
Floor 4
City:
Parsippany
State:
NJ
Zip Code:
07054

You can view the request and take any necessary action at the following webpage: https://a860-openrecords.nyc.gov/request/view/FOIL-2022-826-00315.

Molly Mattern

From: donotreply@records.nyc.gov
Sent: Wednesday, January 26, 2022 9:18 AM
To: Molly Mattern
Subject: [External] [OpenRecords] Request FOIL-2022-826-00315 Closed

Follow Up Flag: Follow up
Flag Status: Flagged

The Department of Environmental Protection (DEP) has **closed** your FOIL request FOIL-2022-826-00315 for the following reasons:

- A diligent search for records responsive to your request did not locate any such records. Accordingly, your request is denied.

You may appeal the decision to deny access to material that was redacted in part or withheld in entirety by contacting the agency's FOIL Appeals Officer: foilappeals@dep.nyc.gov within 30 days.

Molly Mattern

From: New York DEC Support <newyorkdec@mycusthelp.net>
Sent: Friday, January 21, 2022 9:13 AM
To: Molly Mattern
Subject: [External] FOIL Request :: W095078-012122

Follow Up Flag: Flag for follow up
Flag Status: Flagged

Dear Molly:

Thank you for your Freedom of Information Law (FOIL) request. Your request has been received and is being processed. Your request was received in this office on 1/21/2022 and given the reference number FOIL #W095078-012122 for tracking purposes. You may expect the Department's response to your request no later than **2/18/2022**.

Record Requested: **213 Meadow Street (Block 2591, Lots 1, 5, and 45), Brooklyn NY Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the property at 213 Meadow Street (Block 2591 Lots 1, 5, and 45), Brooklyn NY.**

You can monitor the progress of your request at the link below and you'll receive an email when your request has been completed. Again, thank you for using the FOIL Center.

https://mycusthelp.com/NEWYORKDEC/_rs/RequestLogin.aspx

New York State Department of Environmental Conservation, Record Access Office

---

Track the issue status and respond at:
https://newyorkdec.mycusthelp.com/webapp//_rs/RequestEdit.aspx?rid=95078

NEW YORK STATE OF OPPORTUNITY. Department of Health

KATHY HOCHUL
Governor

MARY T. BASSETT, M.D., M.P.H.
Commissioner

KRISTIN M. PROUD
Acting Executive Deputy Commissioner

January 21, 2022

Molly Mattern
Langan Engineering
300 Kimball Dr.
Parsippany, NJ 07054

FOIL #: 22-01-362
RE: 213 Meadow Street, Brooklyn, NY

Dear Molly Mattern:

This will acknowledge receipt of your request for records under the Freedom of Information Law (FOIL), received by this office on January 20, 2022.

Your request has been forwarded to the appropriate Department program area(s) to identify documents that are responsive to your request and which may be made available pursuant to all applicable provisions of the Freedom of Information Law.

A determination as to whether your request is granted or denied will be reached in approximately 20 business days or we will notify you in writing if the responsible program area(s) should require additional time to locate, assemble, and review documents that may be responsive to your request.

Please note that, pursuant to Article 6 of the Public Officers Law, a charge may be applied to your request, including the actual cost of the medium used to respond to your Freedom of Information Law request and/or other related costs. When responsive records have been identified, you will be informed of any cost and how payment should be made.

Sincerely,

Rosemarie Hewig, Esq.
Records Access Officer

RH/sjp

NEW YORK STATE OF OPPORTUNITY. Department of Health

KATHY HOCHUL
Governor

MARY T. BASSETT, M.D., M.P.H.
Commissioner

KRISTIN M. PROUD
Acting Executive Deputy Commissioner

February 18, 2022

Molly Mattern
Langan Engineering
300 Kimball Dr.
Parsippany, NJ 07054

FOIL #: 22-01-362

Dear Molly Mattern:

This letter is in regard to your Freedom of Information Law (FOIL) request of January 20, 2022, which is currently being processed.

Please be advised this Office is unable to respond to your request by the date previously given to you because a diligent search for responsive documents is still being conducted.

We estimate that this Office will complete its process by April 4, 2022. The Department will notify you in writing when/if the responsive materials are available for release or if the time needed to complete your request extends beyond the above date.

Should you require additional information or wish to discuss this matter further, please do not hesitate to contact me at (518) 474-8734.

Sincerely,

Rosemarie Hewig, Esq.
Records Access Officer

RH/dt

Molly Mattern

From: recordsaccess <recordsaccess@health.nyc.gov>
Sent: Tuesday, February 8, 2022 1:58 PM
To: Molly Mattern
Subject: [External] Re: [OpenRecords] FOIL Request Submitted to Department of Health and Mental Hygiene (DOHMH)

Follow Up Flag: Follow up
Flag Status: Flagged

FOIL Control #: 2022FR00325

The NYC Department of Health and Mental Hygiene (DOHMH) acknowledges receipt of your Freedom of Information Law request. It has been assigned the above-noted control number and has been forwarded to the following bureau for processing:

Environmental Health Services
Alfreda Torbert, e-mail: atorber1@health.nyc.gov
Sheba Taylor-Medina, e-mail: staylor2@health.nyc.gov

You should receive a response from the program/bureau within twenty(20) business days. Please note that as of January 1, 2019, the Department may charge the statutorily allowable fee of 25¢ per page for photocopied pages of FOIL responses. You will be advised by the program/bureau of the fee that is due and, upon receipt of your payment by check or money order, the copies will be forwarded to you.
All inquiries about the status of your request should be made with the program/bureau and control number noted above.

Thank you,

FOIL Administration
New York City Department of Health and Mental Hygiene
347-396-6011 (ph.)
347-396-6087 (f)
recordsaccess@health.nyc.gov

From: donotreply@records.nyc.gov <donotreply@records.nyc.gov>
Sent: Thursday, January 20, 2022 4:16 PM
To: mmattern@langan.com <mmattern@langan.com>
Subject: [OpenRecords] FOIL Request Submitted to Department of Health and Mental Hygiene (DOHMH)

Your request has been emailed to the Department of Health and Mental Hygiene (DOHMH) because that agency is not yet using the portal to respond to FOIL requests. The details of your request are shown below. No further information will be available on the OpenRecords portal regarding this request.
Request Title: 213 Meadow Street (Block 2591, Lots 1, 5, and 45), Brooklyn NY

Request Description: Please consider this a formal Freedom of Information Law (FOIL) request for records

regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the property at 213 Meadow Street (Block 2591 Lots 1, 5, and 45), Brooklyn NY.

Attached File: 1-Site_Location.pdf: 1-Site_Location.pdf

Requester's Contact Information

Name:
Molly Mattern
Title:
Not provided
Organization:
Langan Engineering
Email:
mmattern@langan.com
Phone Number:
(973) 560-4900
Fax Number:
Not provided
Street Address (line 1):
300 Kimball Drive
Street Address (line 2):
Floor 4
City:
Parsippany
State:
NJ
Zip Code:
07054

Please contact the Department of Health and Mental Hygiene (DOHMH) via email at foil@health.nyc.gov for any further information.

Sent from the New York City Department of Health & Mental Hygiene. This email and any files transmitted with it may contain confidential information and are intended solely for the use of the individual or entity to whom they are addressed. This footnote also confirms that this email message has been swept for the presence of computer viruses.

NEW YORK CITY DEPARTMENT OF
HEALTH AND MENTAL HYGIENE
Dave Chokshi, MD. MSc
Commissioner

, FR Christopher D'Andrea
Director

Office of Environmental Investigations
125 Worth St., Room 630
New York, NY 10013

Tel. 1 646 632-6104
Fax 1 646 632-6105

February 7, 2022

E Langan
Engineering and Environmental Services, P.C.
300 Kimball Drive
Parsippany, NJ 07054

Request No: 2022FR00220

Dear Sir/Madam

In response to your recent request for environmental records on:

- 213 Meadow Street, Brooklyn, NY

Please note the following:

☒ The Office of Environmental Investigations has "NO" record of an investigation at the above address.

☐ Enclosed are copies of the requested records we have on file.

Sincerely,

Christopher D'Andrea, MS, CIH
Director

United States Department of the Interior

FISH AND WILDLIFE SERVICE
Long Island Ecological Services Field Office
340 Smith Road
Shirley, NY 11967-2258
Phone: (631) 286-0485 Fax: (631) 286-4003

In Reply Refer To: January 20, 2022
Consultation Code: 05E1LI00-2022-SLI-0496
Event Code: 05E1LI00-2022-E-01133
Project Name: 213 Meadow Street (Block 2591, Lots 1, 5, and 45), Brooklyn NY

Subject: List of threatened and endangered species that may occur in your proposed project location or may be affected by your proposed project

To Whom It May Concern:

The enclosed species list identifies threatened, endangered, proposed and candidate species, as well as proposed and final designated critical habitat, that may occur within the boundary of your proposed project and/or may be affected by your proposed project. The species list fulfills the requirements of the U.S. Fish and Wildlife Service (Service) under section 7(c) of the Endangered Species Act (Act) of 1973, as amended (16 U.S.C. 1531 *et seq.*).

New information based on updated surveys, changes in the abundance and distribution of species, changed habitat conditions, or other factors could change this list. Please feel free to contact us if you need more current information or assistance regarding the potential impacts to federally proposed, listed, and candidate species and federally designated and proposed critical habitat. Please note that under 50 CFR 402.12(e) of the regulations implementing section 7 of the Act, the accuracy of this species list should be verified after 90 days. This verification can be completed formally or informally as desired. The Service recommends that verification be completed by visiting the ECOS-IPaC website at regular intervals during project planning and implementation for updates to species lists and information. An updated list may be requested through the ECOS-IPaC system by completing the same process used to receive the enclosed list.

The purpose of the Act is to provide a means whereby threatened and endangered species and the ecosystems upon which they depend may be conserved. Under sections 7(a)(1) and 7(a)(2) of the Act and its implementing regulations (50 CFR 402 *et seq.*), Federal agencies are required to utilize their authorities to carry out programs for the conservation of threatened and endangered species and to determine whether projects may affect threatened and endangered species and/or designated critical habitat.

A Biological Assessment is required for construction projects (or other undertakings having similar physical impacts) that are major Federal actions significantly affecting the quality of the human environment as defined in the National Environmental Policy Act (42 U.S.C. 4332(2)

(c)). For projects other than major construction activities, the Service suggests that a biological evaluation similar to a Biological Assessment be prepared to determine whether the project may affect listed or proposed species and/or designated or proposed critical habitat. Recommended contents of a Biological Assessment are described at 50 CFR 402.12.

If a Federal agency determines, based on the Biological Assessment or biological evaluation, that listed species and/or designated critical habitat may be affected by the proposed project, the agency is required to consult with the Service pursuant to 50 CFR 402. In addition, the Service recommends that candidate species, proposed species and proposed critical habitat be addressed within the consultation. More information on the regulations and procedures for section 7 consultation, including the role of permit or license applicants, can be found in the "Endangered Species Consultation Handbook" at:

http://www.fws.gov/endangered/esa-library/pdf/TOC-GLOS.PDF

Please be aware that bald and golden eagles are protected under the Bald and Golden Eagle Protection Act (16 U.S.C. 668 *et seq.*), and projects affecting these species may require development of an eagle conservation plan (http://www.fws.gov/windenergy/eagle_guidance.html). Additionally, wind energy projects should follow the wind energy guidelines (http://www.fws.gov/windenergy/) for minimizing impacts to migratory birds and bats.

Guidance for minimizing impacts to migratory birds for projects including communications towers (e.g., cellular, digital television, radio, and emergency broadcast) can be found at: http://www.fws.gov/migratorybirds/CurrentBirdIssues/Hazards/towers/towers.htm; http://www.towerkill.com; and http://www.fws.gov/migratorybirds/CurrentBirdIssues/Hazards/towers/comtow.html.

We appreciate your concern for threatened and endangered species. The Service encourages Federal agencies to include conservation of threatened and endangered species into their project planning to further the purposes of the Act. Please include the Consultation Tracking Number in the header of this letter with any request for consultation or correspondence about your project that you submit to our office.

Attachment(s):

- Official Species List

Official Species List

This list is provided pursuant to Section 7 of the Endangered Species Act, and fulfills the requirement for Federal agencies to "request of the Secretary of the Interior information whether any species which is listed or proposed to be listed may be present in the area of a proposed action".

This species list is provided by:

Long Island Ecological Services Field Office
340 Smith Road
Shirley, NY 11967-2258
(631) 286-0485

Project Summary

Consultation Code: 05E1LI00-2022-SLI-0496
Event Code: Some(05E1LI00-2022-E-01133)
Project Name: 213 Meadow Street (Block 2591, Lots 1, 5, and 45), Brooklyn NY
Project Type: ** OTHER **
Project Description: Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the property at 213 Meadow Street (Block 2591 Lots 1, 5, and 45), Brooklyn NY.

Project Location:

Approximate location of the project can be viewed in Google Maps: https://www.google.com/maps/@40.7130045,-73.9284963543846,14z

Counties: Kings County, New York

Endangered Species Act Species

There is a total of 5 threatened, endangered, or candidate species on this species list.

Species on this list should be considered in an effects analysis for your project and could include species that exist in another geographic area. For example, certain fish may appear on the species list because a project could affect downstream species.

IPaC does not display listed species or critical habitats under the sole jurisdiction of NOAA Fisheries[1], as USFWS does not have the authority to speak on behalf of NOAA and the Department of Commerce.

See the "Critical habitats" section below for those critical habitats that lie wholly or partially within your project area under this office's jurisdiction. Please contact the designated FWS office if you have questions.

---

1. NOAA Fisheries, also known as the National Marine Fisheries Service (NMFS), is an office of the National Oceanic and Atmospheric Administration within the Department of Commerce.

Birds

NAME	STATUS
Piping Plover *Charadrius melodus* Population: [Atlantic Coast and Northern Great Plains populations] - Wherever found, except those areas where listed as endangered. There is **final** critical habitat for this species. The location of the critical habitat is not available. Species profile: https://ecos.fws.gov/ecp/species/6039	Threatened
Red Knot *Calidris canutus rufa* There is **proposed** critical habitat for this species. The location of the critical habitat is not available. Species profile: https://ecos.fws.gov/ecp/species/1864	Threatened
Roseate Tern *Sterna dougallii dougallii* Population: Northeast U.S. nesting population No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/2083	Endangered

Insects

NAME	STATUS
Monarch Butterfly *Danaus plexippus* No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/9743	Candidate

Flowering Plants

NAME	STATUS
Seabeach Amaranth *Amaranthus pumilus*	Threatened

No critical habitat has been designated for this species.
Species profile: https://ecos.fws.gov/ecp/species/8549

Critical habitats

THERE ARE NO CRITICAL HABITATS WITHIN YOUR PROJECT AREA UNDER THIS OFFICE'S JURISDICTION.

MyProperty Search Results

INFORMATION FOUND FOR THE SUBMITTED ADDRESS

The entered address was found within the EPA Facility Registry System (FRS) list of address records.

Search Criteria
Address Searched: 213 Meadow Street
City Searched: Brooklyn
State Searched: NY

Query executed on 01/20/2022 04:40 PM

Facility Name	Address	City	State	Postal Code
CASTLE SANITATION CORPORATION Facility Report Summary Report Compliance Report	213 MEADOW STREET	BROOKLYN	NY	11237

Note: Click on the above Facility Report link to view a detailed list of known EPA and State Environmental Interests.
Click on the above Summary Report link to view environmental activities by this facility that may affect air, water, and land.
Click on the above Compliance Report link to view the current and past compliance history of this facility.

Disclaimer: The MyProperty reports are provided solely for informational purposes. They do not provide legal advice, have legally binding effec or expressly or implicitly create, expand, or limit any legal rights, obligations, responsibilities, expectations, or benefits in regard to any person. EF maintains the application to enhance public access to environmental information. This service has continual data updates, and we will correct erro brought to our attention, as appropriate.

LAST UPDATED ON {MONTH DAY, YYYY}

Related Topics: Envirofacts

FRS

FRS Facility Detail Report

CASTLE SANITATION CORPORATION

EPA Registry Id: 110070625464
213 MEADOW STREET
BROOKLYN, NY 11237



Legend

- Selected Facility
- EPA Facility of Interest
- State/Tribe Facility of Interest

The facility locations displayed come from the FRS Spatial Coordinates tables. They are the best representative locations for the displayed facilities based on the accuracy of the collection method and quality assurance checks performed against each location. The North American Datum of 1983 is used to display all coordinates.

Facility Registry Service Links:

- Facility Registry Service (FRS) Overview
- FRS Facility Query
- FRS Organization Query
- EZ Query
- FRS Physical Data Model
- FRS Geospatial Model

Report an Error

Environmental Interests

Information System	System Facility Name	Information System Id/Report Link	Environmental Interest Type	Data Source	Last Updated Date	Supplemental Environmental Interests:
NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (ICIS-NPDES)	CASTLE SANITATION CORPORATION	NYR00G305	ICIS-NPDES NON-MAJOR	ICIS		
NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (ICIS-NPDES)	CASTLE SANITATION CORPORATION	NYR00G305	STORM WATER INDUSTRIAL	ICIS		

Additional EPA Reports: MyEnvironment Enforcement and Compliance Site Demographics Facility Coordinates Viewer Environmental Justice Map Viewer Watershed Report

Standard Industrial Classification Codes (SIC)

Data Source	SIC Code	Description	Primary
NPDES	4212	LOCAL TRUCKING WITHOUT STORAGE	

Facility Codes and Flags

EPA Region:	02
Duns Number:	
Congressional District Number:	07
Legislative District Number:	
HUC Code/Watershed:	02030201 / NORTHERN LONG ISLAND
US Mexico Border Indicator:	
Federal Facility:	
Tribal Land:	

Alternative Names

No Alternative Names returned.

Organizations

No Organizations returned.

National Industry Classification System Codes (NAICS)

No NAICS Codes returned.

Facility Mailing Addresses

No Facility Mailing Addresses returned.

Contacts

No Contacts returned.

Query executed on: JAN-20-2022

Last updated on September 24, 2015

An official website of the United States government

MENU

Search EPA.gov

Related Topics: **Envirofacts** <https://epa.gov/enviro>

CONTACT US <https://www.epa.gov/enviro/forms/contact-us-about-envirofacts>

Home <https://enviro.epa.gov> | Multisystem Search <https://enviro.epa.gov/facts/multisystem.html> | Topic Searches <https://www.epa.gov/enviro/topic-searches> | System Data Searches <https://www.epa.gov/enviro/system-data-searches> | About the Data <https://www.epa.gov/enviro/about-data> | Data Downloads <https://www.epa.gov/enviro/data-downloads> | Widgets <https://www.epa.gov/enviro/widgets> | Services <https://www.epa.gov/enviro/web-services> | Mobile <https://www.epa.gov/enviro/uv-index-mobile-app> | Other Datasets <https://epa.gov/node/111331>

CASTLE SANITATION CORPORATION
213 MEADOW STREET
BROOKLYN, NY 11237

**You can navigate within the map with your mouse.*

EPA Facility Information

This query was executed on JAN-20-2022

Integrated Compliance Information System (ICIS)

Facility

FACILITY NAME (1)	CASTLE SANITATION CORPORATION	**NPDES**	NYR00G305
STREET 1	213 MEADOW STREET	**SIC CODE**	4212 = Local Trucking, Without Storage

CITY		**MAJOR / MINOR**	
COUNTY NAME	Kings	**TYPE OF OWNERSHIP**	Corporation
STATE	NY	**ACTIVITY STATUS**	Effective
ZIP CODE	11237	**INACTIVE DATE**	
REGION	Region 2	**TYPE OF PERMIT ISSUED**	General Permit Covered Facility
LATITUDE	40.712936	**ORIGINAL PERMIT ISSUE DATE**	16-FEB-2018
LONGITUDE	-73.928108	**PERMIT ISSUED DATE**	16-FEB-2018
LAT/LON CODE OF ACCURACY	5	**PERMIT EXPIRED DATE**	28-FEB-2023
LAT/LON METHOD	Interpolation-Map		
LAT/LON SCALE	24000	**USGS HYDRO BASIN CODE**	
LAT/LON DATUM	NAD83	**FLOW**	
RECEIVING WATERS	NEWTOWN CREEK	**FEDERAL GRANT IND**	
PRETREATMENT CODE		**SLUDGE CLASS FAC IND**	NON-POTW
MAILING NAME		**SLUDGE RELATED PERMIT NUM**	
MAILING STREET (1)		**ANNUAL DRY SLUDGE PROD**	
MAILING STREET (2)			
MAILING CITY			
MAILING STATE			

MAILING ZIP CODE			
COGNIZANT OFFICIAL		**COGNIZANT OFFICIAL TEL**	

This facility has permits to discharge the following chemical/substances through the points (pipes) listed in the table below:

PARAMETER CODE	**PARAMETER DESCRIPTION** <https://epa.gov//enviro.epa.gov/html/emci/system_chemical_name.html>	**NUMBER OF DISCHARGE POINTS**
1330207	Xylene [mix of m+o+p]	4
71432	Benzene	4
108883	Toluene	4
100414	Ethylbenzene	4
	Oil & Grease	8
	Chemical Oxygen Demand [COD]	8

Additional Information can be obtained from Water Discharge Permit Information ICIS Search.

Data Refresh Information

<https://epa.gov/resources/echo-data/about-the-data#sources>

Detailed Facility Report

Facility Summary

CASTLE SANITATION CORPORATION
213 MEADOW STREET, BROOKLYN, NY 11237

FRS (Facility Registry Service) ID: 110070625464
EPA Region: 02
Latitude: 40.71283
Longitude: -73.92806
Locational Data Source: FRS
Industries:
Indian Country: N

Enforcement and Compliance Summary

Statute	Insp (5 Years)	Date of Last Inspection	Compliance Status	Qtrs with NC (Noncompliance) (of 12)	Qtrs with Significant Violation	Informal Enforcement Actions (5 years)	Formal Enforcement Actions (5 years)	Penalties from Formal Enforcement Actions (5 years)	EPA Cases (5 years)	Penalties from EPA Cases (5 years)
CWA	--	--	No Violation Identified	2	0	--	--	--	--	--

Regulatory Information

Clean Air Act (CAA): No Information
Clean Water Act (CWA): Minor, Permit Effective (NYR00G305)
Resource Conservation and Recovery Act (RCRA): No Information
Safe Drinking Water Act (SDWA): No Information

Other Regulatory Reports

Air Emissions Inventory (EIS): No Information
Greenhouse Gas Emissions (eGGRT): No Information
Toxic Releases (TRI): No Information
Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Known Data Problems

Facility/System Characteristics

Facility/System Characteristics

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110070625464					N	40.71283	-73.92806
ICIS-NPDES	CWA	NYR00G305	Minor: General Permit Covered Facility	Effective	Industrial Stormwater	02/28/2023	N	40.712936	-73.928108

Facility Address

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110070625464	CASTLE SANITATION CORPORATION	213 MEADOW STREET, BROOKLYN, NY 11237	
ICIS-NPDES	CWA	NYR00G305	CASTLE SANITATION CORPORATION	213 MEADOW STREET, BROOKLYN, NY 11237	Kings County

Facility SIC (Standard Industrial Classification) Codes

System	Identifier	SIC Code	SIC Description
ICIS-NPDES	NYR00G305	4212	Local Trucking, Without Storage
NPDES	NYR00G305	4212	Local Trucking, Without Storage

Facility NAICS (North American Industry Classification System) Codes

System	Identifier	NAICS Code	NAICS Description
No data records returned			

Facility Industrial Effluent Guidelines

Identifier	Effluent Guideline (40 CFR Part)	Effluent Guideline Description
No data records returned		

Facility Tribe Information

Reservation Name	Tribe Name	EPA Tribal ID	Distance to Tribe (miles)
No data records returned			

Enforcement and Compliance

Compliance Monitoring History (5 years)

Statute	Source ID	System	Activity Type	Compliance Monitoring Type	Lead Agency	Date	Finding (if applicable)
No data records returned							

Entries in italics are not counted in EPA compliance monitoring strategies or annual results.

Compliance Summary Data

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
CWA	NYR00G305	No	09/30/2021	2	01/14/2022

Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violation Type				QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12	QTR 13+
	CWA (Source ID: NYR00G305)				10/01-12/31/18	01/01-03/31/19	04/01-06/30/19	07/01-09/30/19	10/01-12/31/19	01/01-03/31/20	04/01-06/30/20	07/01-09/30/20	10/01-12/31/20	01/01-03/31/21	04/01-06/30/21	07/01-09/30/21	10/01-01/14/22
	Facility-Level Status				**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**Violation Identified**	**Violation Identified**	**No Violation Identified**	**Undetermined**
	Quarterly Noncompliance Report History													Reportable Noncompliance	Reportable Noncompliance		
	Benchmark Limit Exceedances (No Violation): Pollutant	**Disch Point**	**Mon Loc**	**Freq**													
CWA	Chemical Oxygen Demand [COD] E	001 - Q	Effluent Gross	NMth										LIMIT VIOLATION			
CWA	Chemical Oxygen Demand [COD] E	002 - Q	Effluent Gross	NMth								13%					
CWA	Chemical Oxygen Demand [COD] E	003 - Q	Effluent Gross	NMth								8%					13%
CWA	Chemical Oxygen Demand [COD] E	003 - A	Effluent Gross	NMth													13%
CWA	Chemical Oxygen Demand [COD] E	004 - Q	Effluent Gross	NMth								15%					

Statute	Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12	QTR 13+
	Permit Schedule Violations													
CWA	Annual Report and Certification										**01/28/2021**	**06/02/2021**		

Informal Enforcement Actions (5 Years)

Statute	System	Source ID	Type of Action	Lead Agency	Date
No data records returned					

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

Formal Enforcement Actions (5 Years)

Statute	System	Law/Section	Source ID	Action Type	Case No.	Lead Agency	Case Name	Issued/Filed Date	Settlements/Actions	Settlement/Action Date	Federal Penalty Assessed	State/Local Penalty Assessed	Penalty Amount Collected	SEP Cost	Comp Action Cost
No data records returned															

Environmental Conditions

Watershed(s)

12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database))	WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database))	State Water Body Name (ICIS (Integrated Compliance Information System))	Beach Closures Within Last Year	Beach Closures Within Last Two Years	Pollutants Potentially Related to Impairment	Watershed with ESA (Endangered Species Act)-listed Aquatic Species?
020301010405	East River-Hudson River	NEWTOWN CREEK	No	No	Chemical Oxygen Demand (COD)	Yes

Assessed Waters From Latest State Submission (ATTAINS)

State	Report Cycle	Assessment Unit ID	Assessment Unit Name	Water Condition	Cause Groups Impaired	Drinking Water Use	Aquatic Life	Fish Consumption Use	Recreation Use	Other Use
NY	2016	NY1702-0104	Central Park Reservoir	Good		Fully Supporting	Insufficient Information	Insufficient Information	Insufficient Information	Insufficient Information
NY	2016	NY1702-0011	East River, Lower	Impaired - 303(d) Listed - With Restoration Plan	ORGANIC ENRICHMENT/OXYGEN DEPLETION | POLYCHLORINATED BIPHENYLS (PCBS) | TRASH		Insufficient Information	Insufficient Information		Not Supporting
NY	2016	NY1702-0002	Newtown Creek and tidal tribs	Impaired - 303(d) Listed - With Restoration Plan	ORGANIC ENRICHMENT/OXYGEN DEPLETION | PATHOGENS | TRASH		Not Supporting	Insufficient Information		Not Supporting
NY	2016	NY1702-0257	Ridgewood Reservoir	Unknown		Insufficient Information	Insufficient Information	Insufficient Information	Insufficient Information	Insufficient Information
NY	2016	NY1702-0105	The Lake in Central Park	Impaired - 303(d) Listed	NUTRIENTS		Insufficient Information	Insufficient Information	Not Supporting	Not Supporting
NY	2016	NY1701-0022	Upper New York Bay	Impaired - 303(d) Listed	POLYCHLORINATED BIPHENYLS (PCBS)		Insufficient Information	Not Supporting		Insufficient Information

Air Quality Nonattainment Areas

Pollutant	Within Nonattainment Status Area?	Nonattainment Status Applicable Standard(s)	Within Maintenance Status Area?	Maintenance Status Applicable Standard(s)
Ozone	Yes	1-Hour Ozone (1979); 8-Hour Ozone (2008); 8-Hour Ozone (2015)	No	
Lead	No		No	
Particulate Matter	No		Yes	PM-2.5 (1997); PM-2.5 (2006)
Carbon Monoxide	No		Yes	Carbon Monoxide (1971)
Sulfur Dioxide	No		No	

Pollutants

Toxics Release Inventory History of Reported Chemicals Released in Pounds per Year at Site

TRI Facility ID	Year	Total Air Emissions	Surface Water Discharges	Off-Site Transfers to POTWs (Publicly Owned Treatment Works)	Underground Injections	Releases to Land	Total On-site Releases	Total Off-site Transfers
No data records returned								

Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name
No data records returned

Community

EJSCREEN EJ Indexes

Eleven primary environmental justice (EJ) indexes of EJSCREEN, EPA's screening tool for EJ concerns. EPA uses these indexes to identify geographic areas that may warrant further consideration or analysis for potential EJ concerns. The index values below are for the Census block group in which the facility is located. Note that use of these indexes does not designate an area as an "EJ community" or "EJ facility." EJSCREEN provides screening level indicators, not a determination of the existence or absence of EJ concerns. For more information, see the EJSCREEN home page.

Census Block Group EJ Indexes (percentile)	
Particulate Matter (PM 2.5)	58.9
Ozone	58.9
NATA Diesel PM	61.3
NATA Air Toxics Cancer Risk	58.9
NATA Respiratory Hazard Index (HI)	59.1
Traffic Proximity	68.2
Lead Paint Indicator	66.9
National Priority List (NPL) Site Proximity	73
Risk Management Plan (RMP) Site Proximity	60.6
Hazardous Waste Proximity	83.5
Wastewater Discharge Proximity	94.8

Number of EJ Indexes Above 80th Percentile
2

View EJSCREEN Report

Demographic Profile of Surrounding Area (1 Mile)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2010 U.S. Census and 2014 - 2018 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. EPA's spatial processing methodology considers the overlap between the selected radii and the census blocks (for U.S. Census demographics) and census block groups (for ACS demographics) in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary.

General Statistics	
Total Persons (U.S. Census)	83,210
Population Density	27,778/sq.mi.
Percent People of Color	68%
Households in Area	32,563
Housing Units in Area	32,039
Total Persons (ACS (American Community Survey))	84,953
Households on Public Assistance	1,405
Persons With Low Income	36,324
Percent With Low Income	43%

Geography	
Radius of Selected Area	1 mi.
Center Latitude	40.71283
Center Longitude	-73.92806
Land Area	96%

Age Breakdown - Persons (%)	
Children 5 years and younger	5,157 (6%)
Minors 17 years and younger	17,358 (21%)
Adults 18 years and older	65,853 (79%)
Seniors 65 years and older	6,366 (8%)

Race Breakdown - Persons (%)	
White	40,831 (49%)
African-American	9,239 (11%)
Hispanic-Origin	47,387 (57%)
Asian/Pacific Islander	5,371 (6%)
American Indian	916 (1%)
Other/Multiracial	26,854 (32%)

Education Level (Persons 25 & older) - Persons (%)	
Less than 9th Grade	7,110 (12.01%)
9th through 12th Grade	6,340 (10.71%)

Geography	
Water Area	4%

Income Breakdown - Households (%)	
Less than $15,000	5,731 (17.6%)
$15,000 - $25,000	3,049 (9.36%)
$25,000 - $50,000	6,006 (18.45%)
$50,000 - $75,000	4,626 (14.21%)
Greater than $75,000	13,147 (40.38%)

Education Level (Persons 25 & older) - Persons (%)	
High School Diploma	12,547 (21.19%)
Some College/2-year	10,343 (17.46%)
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	22,875 (38.63%)

Detailed Facility Report

Facility Summary

CASTLE SANITATION CORPORATION
213 MEADOW STREET, BROOKLYN, NY 11237

FRS (Facility Registry Service) ID: 110070625464
EPA Region: 02
Latitude: 40.71283
Longitude: -73.92806
Locational Data Source: FRS
Industries:
Indian Country: N

Enforcement and Compliance Summary

Statute	Insp (5 Years)	Date of Last Inspection	Compliance Status	Qtrs with NC (Noncompliance) (of 12)	Qtrs with Significant Violation	Informal Enforcement Actions (5 years)	Formal Enforcement Actions (5 years)	Penalties from Formal Enforcement Actions (5 years)	EPA Cases (5 years)	Penalties from EPA Cases (5 years)
CWA	--	--	No Violation Identified	2	0	--	--	--	--	--

Regulatory Information

Clean Air Act (CAA): No Information
Clean Water Act (CWA): Minor, Permit Effective (NYR00G305)
Resource Conservation and Recovery Act (RCRA): No Information
Safe Drinking Water Act (SDWA): No Information

Other Regulatory Reports

Air Emissions Inventory (EIS): No Information
Greenhouse Gas Emissions (eGGRT): No Information
Toxic Releases (TRI): No Information
Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Known Data Problems

Facility/System Characteristics

Facility/System Characteristics

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110070625464					N	40.71283	-73.92806
ICIS-NPDES	CWA	NYR00G305	Minor: General Permit Covered Facility	Effective	Industrial Stormwater	02/28/2023	N	40.712936	-73.928108

Facility Address

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110070625464	CASTLE SANITATION CORPORATION	213 MEADOW STREET, BROOKLYN, NY 11237	
ICIS-NPDES	CWA	NYR00G305	CASTLE SANITATION CORPORATION	213 MEADOW STREET, BROOKLYN, NY 11237	Kings County

Facility SIC (Standard Industrial Classification) Codes

System	Identifier	SIC Code	SIC Description
ICIS-NPDES	NYR00G305	4212	Local Trucking, Without Storage
NPDES	NYR00G305	4212	Local Trucking, Without Storage

Facility NAICS (North American Industry Classification System) Codes

System	Identifier	NAICS Code	NAICS Description
No data records returned			

Facility Industrial Effluent Guidelines

Identifier	Effluent Guideline (40 CFR Part)	Effluent Guideline Description
No data records returned		

Facility Tribe Information

Reservation Name	Tribe Name	EPA Tribal ID	Distance to Tribe (miles)
No data records returned			

Enforcement and Compliance

Compliance Monitoring History (5 years)

Statute	Source ID	System	Activity Type	Compliance Monitoring Type	Lead Agency	Date	Finding (if applicable)
No data records returned							

Entries in italics are not counted in EPA compliance monitoring strategies or annual results.

Compliance Summary Data

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
CWA	NYR00G305	No	09/30/2021	2	01/14/2022

Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violation Type				QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12	QTR 13+
	CWA (Source ID: NYR00G305)				10/01-12/31/18	01/01-03/31/19	04/01-06/30/19	07/01-09/30/19	10/01-12/31/19	01/01-03/31/20	04/01-06/30/20	07/01-09/30/20	10/01-12/31/20	01/01-03/31/21	04/01-06/30/21	07/01-09/30/21	10/01-01/14/22
	Facility-Level Status				**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**No Violation Identified**	**Violation Identified**	**Violation Identified**	**No Violation Identified**	**Undetermined**
	Quarterly Noncompliance Report History													Reportable Noncompliance	Reportable Noncompliance		
	Benchmark Limit Exceedances (No Violation): Pollutant	**Disch Point**	**Mon Loc**	**Freq**													
CWA	Chemical Oxygen Demand [COD] E	001 - Q	Effluent Gross	NMth										LIMIT VIOLATION			
CWA	Chemical Oxygen Demand [COD] E	002 - Q	Effluent Gross	NMth								13%					
CWA	Chemical Oxygen Demand [COD] E	003 - Q	Effluent Gross	NMth								8%					13%
CWA	Chemical Oxygen Demand [COD] E	003 - A	Effluent Gross	NMth													13%
CWA	Chemical Oxygen Demand [COD] E	004 - Q	Effluent Gross	NMth								15%					

Statute	Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12	QTR 13+
	Permit Schedule Violations													
CWA	Annual Report and Certification										**01/28/2021**	**06/02/2021**		

Informal Enforcement Actions (5 Years)

Statute	System	Source ID	Type of Action	Lead Agency	Date
No data records returned					

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

Formal Enforcement Actions (5 Years)

Statute	System	Law/Section	Source ID	Action Type	Case No.	Lead Agency	Case Name	Issued/Filed Date	Settlements/Actions	Settlement/Action Date	Federal Penalty Assessed	State/Local Penalty Assessed	Penalty Amount Collected	SEP Cost	Comp Action Cost
No data records returned															

Environmental Conditions

Watershed(s)

12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database))	WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database))	State Water Body Name (ICIS (Integrated Compliance Information System))	Beach Closures Within Last Year	Beach Closures Within Last Two Years	Pollutants Potentially Related to Impairment	Watershed with ESA (Endangered Species Act)-listed Aquatic Species?
020301010405	East River-Hudson River	NEWTOWN CREEK	No	No	Chemical Oxygen Demand (COD)	Yes

Assessed Waters From Latest State Submission (ATTAINS)

State	Report Cycle	Assessment Unit ID	Assessment Unit Name	Water Condition	Cause Groups Impaired	Drinking Water Use	Aquatic Life	Fish Consumption Use	Recreation Use	Other Use
NY	2016	NY1702-0104	Central Park Reservoir	Good		Fully Supporting	Insufficient Information	Insufficient Information	Insufficient Information	Insufficient Information
NY	2016	NY1702-0011	East River, Lower	Impaired - 303(d) Listed - With Restoration Plan	ORGANIC ENRICHMENT/OXYGEN DEPLETION | POLYCHLORINATED BIPHENYLS (PCBS) | TRASH		Insufficient Information	Insufficient Information		Not Supporting
NY	2016	NY1702-0002	Newtown Creek and tidal tribs	Impaired - 303(d) Listed - With Restoration Plan	ORGANIC ENRICHMENT/OXYGEN DEPLETION | PATHOGENS | TRASH		Not Supporting	Insufficient Information		Not Supporting
NY	2016	NY1702-0257	Ridgewood Reservoir	Unknown		Insufficient Information	Insufficient Information	Insufficient Information	Insufficient Information	Insufficient Information
NY	2016	NY1702-0105	The Lake in Central Park	Impaired - 303(d) Listed	NUTRIENTS		Insufficient Information	Insufficient Information	Not Supporting	Not Supporting
NY	2016	NY1701-0022	Upper New York Bay	Impaired - 303(d) Listed	POLYCHLORINATED BIPHENYLS (PCBS)		Insufficient Information	Not Supporting		Insufficient Information

Air Quality Nonattainment Areas

Pollutant	Within Nonattainment Status Area?	Nonattainment Status Applicable Standard(s)	Within Maintenance Status Area?	Maintenance Status Applicable Standard(s)
Ozone	Yes	1-Hour Ozone (1979); 8-Hour Ozone (2008); 8-Hour Ozone (2015)	No	
Lead	No		No	
Particulate Matter	No		Yes	PM-2.5 (1997); PM-2.5 (2006)
Carbon Monoxide	No		Yes	Carbon Monoxide (1971)
Sulfur Dioxide	No		No	

Pollutants

Toxics Release Inventory History of Reported Chemicals Released in Pounds per Year at Site

TRI Facility ID	Year	Total Air Emissions	Surface Water Discharges	Off-Site Transfers to POTWs (Publicly Owned Treatment Works)	Underground Injections	Releases to Land	Total On-site Releases	Total Off-site Transfers
No data records returned								

Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name
No data records returned

Community

EJSCREEN EJ Indexes

Eleven primary environmental justice (EJ) indexes of EJSCREEN, EPA's screening tool for EJ concerns. EPA uses these indexes to identify geographic areas that may warrant further consideration or analysis for potential EJ concerns. The index values below are for the Census block group in which the facility is located. Note that use of these indexes does not designate an area as an "EJ community" or "EJ facility." EJSCREEN provides screening level indicators, not a determination of the existence or absence of EJ concerns. For more information, see the EJSCREEN home page.

Census Block Group EJ Indexes (percentile)	
Particulate Matter (PM 2.5)	58.9
Ozone	58.9
NATA Diesel PM	61.3
NATA Air Toxics Cancer Risk	58.9
NATA Respiratory Hazard Index (HI)	59.1
Traffic Proximity	68.2
Lead Paint Indicator	66.9
National Priority List (NPL) Site Proximity	73
Risk Management Plan (RMP) Site Proximity	60.6
Hazardous Waste Proximity	83.5
Wastewater Discharge Proximity	94.8

Number of EJ Indexes Above 80th Percentile
2

View EJSCREEN Report

Demographic Profile of Surrounding Area (1 Mile)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2010 U.S. Census and 2014 - 2018 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. EPA's spatial processing methodology considers the overlap between the selected radii and the census blocks (for U.S. Census demographics) and census block groups (for ACS demographics) in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary.

General Statistics	
Total Persons (U.S. Census)	83,210
Population Density	27,778/sq.mi.
Percent People of Color	68%
Households in Area	32,563
Housing Units in Area	32,039
Total Persons (ACS (American Community Survey))	84,953
Households on Public Assistance	1,405
Persons With Low Income	36,324
Percent With Low Income	43%

Geography	
Radius of Selected Area	1 mi.
Center Latitude	40.71283
Center Longitude	-73.92806
Land Area	96%

Age Breakdown - Persons (%)	
Children 5 years and younger	5,157 (6%)
Minors 17 years and younger	17,358 (21%)
Adults 18 years and older	65,853 (79%)
Seniors 65 years and older	6,366 (8%)

Race Breakdown - Persons (%)	
White	40,831 (49%)
African-American	9,239 (11%)
Hispanic-Origin	47,387 (57%)
Asian/Pacific Islander	5,371 (6%)
American Indian	916 (1%)
Other/Multiracial	26,854 (32%)

Education Level (Persons 25 & older) - Persons (%)	
Less than 9th Grade	7,110 (12.01%)
9th through 12th Grade	6,340 (10.71%)

Geography	
Water Area	4%

Income Breakdown - Households (%)	
Less than $15,000	5,731 (17.6%)
$15,000 - $25,000	3,049 (9.36%)
$25,000 - $50,000	6,006 (18.45%)
$50,000 - $75,000	4,626 (14.21%)
Greater than $75,000	13,147 (40.38%)

Education Level (Persons 25 & older) - Persons (%)	
High School Diploma	12,547 (21.19%)
Some College/2-year	10,343 (17.46%)
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	22,875 (38.63%)

Related Topics: Envirofacts

FRS

FRS Facility Detail Report

CASTLE SANITATION CORPORATION

EPA Registry Id: 110070625464
213 MEADOW STREET
BROOKLYN, NY 11237



Legend

- Selected Facility
- EPA Facility of Interest
- State/Tribe Facility of Interest

The facility locations displayed come from the FRS Spatial Coordinates tables. They are the best representative locations for the displayed facilities based on the accuracy of the collection method and quality assurance checks performed against each location. The North American Datum of 1983 is used to display all coordinates.

Facility Registry Service Links:

- Facility Registry Service (FRS) Overview
- FRS Facility Query
- FRS Organization Query
- EZ Query
- FRS Physical Data Model
- FRS Geospatial Model

Report an Error

Environmental Interests

Information System	System Facility Name	Information System Id/Report Link	Environmental Interest Type	Data Source	Last Updated Date	Supplemental Environmental Interests:
NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (ICIS-NPDES)	CASTLE SANITATION CORPORATION	NYR00G305	ICIS-NPDES NON-MAJOR	ICIS		
NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (ICIS-NPDES)	CASTLE SANITATION CORPORATION	NYR00G305	STORM WATER INDUSTRIAL	ICIS		

Additional EPA Reports: MyEnvironment Enforcement and Compliance Site Demographics Facility Coordinates Viewer Environmental Justice Map Viewer Watershed Report

Standard Industrial Classification Codes (SIC)

Data Source	SIC Code	Description	Primary
NPDES	4212	LOCAL TRUCKING WITHOUT STORAGE	

Facility Codes and Flags

EPA Region:	02
Duns Number:	
Congressional District Number:	07
Legislative District Number:	
HUC Code/Watershed:	02030201 / NORTHERN LONG ISLAND
US Mexico Border Indicator:	
Federal Facility:	
Tribal Land:	

Alternative Names

No Alternative Names returned.

Organizations

No Organizations returned.

National Industry Classification System Codes (NAICS)

No NAICS Codes returned.

Facility Mailing Addresses

No Facility Mailing Addresses returned.

Contacts

No Contacts returned.

Query executed on: JAN-20-2022

Last updated on September 24, 2015

An official website of the United States government

MENU

Search EPA.gov

Related Topics: **Envirofacts** <https://epa.gov/enviro>

CONTACT US <https://www.epa.gov/enviro/forms/contact-us-about-envirofacts>

Home <https://enviro.epa.gov> | Multisystem Search <https://enviro.epa.gov/facts/multisystem.html> | Topic Searches <https://www.epa.gov/enviro/topic-searches> | System Data Searches <https://www.epa.gov/enviro/system-data-searches> | About the Data <https://www.epa.gov/enviro/about-data> | Data Downloads <https://www.epa.gov/enviro/data-downloads> | Widgets <https://www.epa.gov/enviro/widgets> | Services <https://www.epa.gov/enviro/web-services> | Mobile <https://www.epa.gov/enviro/uv-index-mobile-app> | Other Datasets <https://epa.gov/node/111331>

CASTLE SANITATION CORPORATION
213 MEADOW STREET
BROOKLYN, NY 11237

**You can navigate within the map with your mouse.*

EPA Facility Information

This query was executed on JAN-20-2022

Integrated Compliance Information System (ICIS)

Facility

FACILITY NAME (1)	CASTLE SANITATION CORPORATION	**NPDES**	NYR00G305
STREET 1	213 MEADOW STREET	**SIC CODE**	4212 = Local Trucking, Without Storage

CITY		**MAJOR / MINOR**	
COUNTY NAME	Kings	**TYPE OF OWNERSHIP**	Corporation
STATE	NY	**ACTIVITY STATUS**	Effective
ZIP CODE	11237	**INACTIVE DATE**	
REGION	Region 2	**TYPE OF PERMIT ISSUED**	General Permit Covered Facility
LATITUDE	40.712936	**ORIGINAL PERMIT ISSUE DATE**	16-FEB-2018
LONGITUDE	-73.928108	**PERMIT ISSUED DATE**	16-FEB-2018
LAT/LON CODE OF ACCURACY	5	**PERMIT EXPIRED DATE**	28-FEB-2023
LAT/LON METHOD	Interpolation-Map		
LAT/LON SCALE	24000	**USGS HYDRO BASIN CODE**	
LAT/LON DATUM	NAD83	**FLOW**	
RECEIVING WATERS	NEWTOWN CREEK	**FEDERAL GRANT IND**	
PRETREATMENT CODE		**SLUDGE CLASS FAC IND**	NON-POTW
MAILING NAME		**SLUDGE RELATED PERMIT NUM**	
MAILING STREET (1)		**ANNUAL DRY SLUDGE PROD**	
MAILING STREET (2)			
MAILING CITY			
MAILING STATE			

MAILING ZIP CODE			
COGNIZANT OFFICIAL		**COGNIZANT OFFICIAL TEL**	

This facility has permits to discharge the following chemical/substances through the points (pipes) listed in the table below:

PARAMETER CODE	**PARAMETER DESCRIPTION** <https://epa.gov//enviro.epa.gov/html/emci/system_chemical_name.html>	**NUMBER OF DISCHARGE POINTS**
1330207	Xylene [mix of m+o+p]	4
71432	Benzene	4
108883	Toluene	4
100414	Ethylbenzene	4
	Oil & Grease	8
	Chemical Oxygen Demand [COD]	8

Additional Information can be obtained from Water Discharge Permit Information ICIS Search.

Data Refresh Information

<https://epa.gov/resources/echo-data/about-the-data#sources>

CEQR Project Search

Keyword

Lead Agency

-- Select Lead Agency --

CEQR Number

Project Name

Community District

-- Select Community District --

Borough / Block / Lot

-- Select Boro --

2591

1

Search | Clear (../ceqr)

No Results Found

No projects found matching your criteria.

Disclaimer and Notes:

The database contains records of CEQR projects, which were filed with the Mayor's Office of Environmental Coordination from January 1, 2005 to the present. While some older records are available in the database, records that cannot be found on CEQR Access should be requested from the agency that was responsible for preparing it (the “Lead Agency”). If any errors are found in the database, please notify the Mayor’s Office of Environmental Coordination (ceqraccess@cityhall.nyc.gov). The Mayor’s Office of Environmental Coordination makes no representation as to the accuracy of the information in the database or its suitability for any purpose, and disclaims any liability for errors that may be contained therein.

Copyright 2020 The City of New York

Contact Us (http://www1.nyc.gov/home/contact-us.page)

Privacy Policy (http://www1.nyc.gov/home/privacy-policy.page)

Terms of Use (http://www1.nyc.gov/home/terms-of-use.page)

CEQR Project Search

Keyword

Lead Agency

-- Select Lead Agency --

CEQR Number

Project Name

Community District

-- Select Community District --

Borough / Block / Lot

-- Select Boro --

2591

5

Search | Clear (../ceqr)

No Results Found

No projects found matching your criteria.

Disclaimer and Notes:

The database contains records of CEQR projects, which were filed with the Mayor's Office of Environmental Coordination from January 1, 2005 to the present. While some older records are available in the database, records that cannot be found on CEQR Access should be requested from the agency that was responsible for preparing it (the “Lead Agency”). If any errors are found in the database, please notify the Mayor’s Office of Environmental Coordination (ceqraccess@cityhall.nyc.gov). The Mayor’s Office of Environmental Coordination makes no representation as to the accuracy of the information in the database or its suitability for any purpose, and disclaims any liability for errors that may be contained therein.

Copyright 2020 The City of New York

Contact Us (http://www1.nyc.gov/home/contact-us.page)

Privacy Policy (http://www1.nyc.gov/home/privacy-policy.page)

Terms of Use (http://www1.nyc.gov/home/terms-of-use.page)

CEQR Project Search

Keyword

Lead Agency

-- Select Lead Agency --

CEQR Number

Project Name

Community District

-- Select Community District --

Borough / Block / Lot

-- Select Boro --

2591

45

Search | Clear (../ceqr)

No Results Found

No projects found matching your criteria.

Disclaimer and Notes:

The database contains records of CEQR projects, which were filed with the Mayor's Office of Environmental Coordination from January 1, 2005 to the present. While some older records are available in the database, records that cannot be found on CEQR Access should be requested from the agency that was responsible for preparing it (the "Lead Agency"). If any errors are found in the database, please notify the Mayor's Office of Environmental Coordination (ceqraccess@cityhall.nyc.gov). The Mayor's Office of Environmental Coordination makes no representation as to the accuracy of the information in the database or its suitability for any purpose, and disclaims any liability for errors that may be contained therein.

Copyright 2020 The City of New York

Contact Us (http://www1.nyc.gov/home/contact-us.page)

Privacy Policy (http://www1.nyc.gov/home/privacy-policy.page)

Terms of Use (http://www1.nyc.gov/home/terms-of-use.page)

DECinfo Locator Legend (Active Layers)

Environmental Cleanup

- Remediation Parcels
- Remediation Sites

Environmental Monitoring

- Lakes and Reservoirs
- Estuaries
- Rivers and Streams
- Shorelines
- Hydrologic Unit Code (HUC) 10
- Air Quality Monitoring Sites
- Community Air Quality Reports
- Aquatic Biological Monitoring
- Aquatic Toxicity Monitoring
- Archived Harmful Algal Bloom Reports
- Harmful Algal Bloom Reports

Public Involvement

- Potential Environmental Justice Areas
- OEJ Grants
- Environmental Excellence Awards Winners
- Climate Smart Communities
- Climate Smart Communities Grants
- Zero-emission Vehicle Rebates
- Zero-emission Vehicle Infrastructure Grants

Environmentally Sensitive Areas

- Critical Environmental Areas
- Regulatory Tidal Wetlands Areas

Reference Layers

- DEC Regional Offices
- County Boundary

(/)

Request a Record

Please make your request specific so you receive the fastest service. After you submit a FOIL request you will receive a confirmation number so you can track the status of the response. The agency will notify you about how much time is required to respond to your request.

Category (optional)

Selecting a category helps clarify which agency will receive the request by listing agencies grouped by categories.

Environment

Agency (required)

Select the agency that will handle your request.

Department of Environmental Protection (DEP)

Request Title (required)

213 Meadow Street (Block 2591, Lots 1, 5, and 45), Brooklyn NY

28 characters remaining

Note: The agency, category, and title of your request will be visible to the public. Do not enter personal information here.

Ex: Queens Blvd Roadwork Permit.

Request Description (required)

Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the property at 213 Meadow Street (Block 2591, Lots 1, 5, and 45), Brooklyn NY.

4599 characters remaining

Note: The request details you write here will not be visible to the public. However, the agency may post a description of the records provided.

Ex: Roadwork permits for work done in on Queens Blvd. between 40th and 45th streets, Borough of Queens, in September and October 2017.

Privacy - Terms

Upload File (optional, must be less than 20 Mb)

Clear File

1-Site Location.pdf

Personal Information

First and last name fields are required. The Email field is optional but recommended. If you do not provide an email you must enter either a phone number, fax number, or address in the Alternate Contact Information section.

This information will not be publicly viewable on this site. You must provide contact information so that the agency can respond to your request for records.

First Name (required)

Molly

27 characters remaining

Last Name (required)

Mattern

57 characters remaining

Email

mmattern@langan.com

Alternate Contact Information

No information entered in this section will be visible to the public.

Fields are included in case alternate contact method is needed.

Title

Your role in your organization (if applicable)

64 characters remaining

Organization

Langan Engineering

110 characters remaining

Phone

Privacy - Terms

(973) 560-4900

Fax

(555) 555-5555

Address

Address Line 1

300 Kimball Drive

Address Line 2

Floor 4

City

Parsippany

State / U.S. Territory

New Jersey

Zip

07054

Submit Request

Privacy - Terms

Directory of City Agencies (http://www1.nyc.gov/nyc-resources/agencies.page)

Contact NYC Government (http://www1.nyc.gov/home/contact-us.page)

City Employees (https://a127-ess.nyc.gov) Notify NYC (http://www.nyc.gov/notifynyc)

CityStore (http://a856-citystore.nyc.gov/)

Stay Connected (http://www1.nyc.gov/connect/social-media.page)

NYC Mobile Apps (http://www1.nyc.gov/connect/applications.page)

Maps (http://www1.nyc.gov/nyc-resources/nyc-maps.page)

Resident Toolkit (http://www1.nyc.gov/nyc-resources/resident-toolkit.page)

Search

City of New York. 2016 All Rights Reserved,
NYC is a trademark and service mark of the City of New York
Privacy Policy (http://www1.nyc.gov/home/privacy-policy.page).
Terms of Use (http://www1.nyc.gov/home/terms-of-use.page).

Privacy - Terms

Molly Mattern

From: donotreply@records.nyc.gov
Sent: Thursday, January 20, 2022 4:16 PM
To: Molly Mattern
Subject: [External] [OpenRecords] FOIL Request Submitted to Department of Health and Mental Hygiene (DOHMH)

Follow Up Flag: Follow up
Flag Status: Flagged

Your request has been emailed to the Department of Health and Mental Hygiene (DOHMH) because that agency is not yet using the portal to respond to FOIL requests. The details of your request are shown below. No further information will be available on the OpenRecords portal regarding this request.

Request Title: 213 Meadow Street (Block 2591, Lots 1, 5, and 45), Brooklyn NY

Request Description: Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the property at 213 Meadow Street (Block 2591 Lots 1, 5, and 45), Brooklyn NY.

Attached File: 1-Site_Location.pdf: 1-Site_Location.pdf

Requester's Contact Information

Name:
Molly Mattern
Title:
Not provided
Organization:
Langan Engineering
Email:
mmattern@langan.com
Phone Number:
(973) 560-4900
Fax Number:
Not provided
Street Address (line 1):
300 Kimball Drive
Street Address (line 2):
Floor 4
City:
Parsippany
State:
NJ
Zip Code:
07054

Please contact the Department of Health and Mental Hygiene (DOHMH) via email at foil@health.nyc.gov for any further information.

(/)

Request a Record

Please make your request specific so you receive the fastest service. After you submit a FOIL request you will receive a confirmation number so you can track the status of the response. The agency will notify you about how much time is required to respond to your request.

Category (optional)

Selecting a category helps clarify which agency will receive the request by listing agencies grouped by categories.

Health

Agency (required)

Select the agency that will handle your request.

Department of Health and Mental Hygiene (DOHMH)

Request Title (required)

213 Meadow Street (Block 2591, Lots 1, 5, and 45), Brooklyn NY

28 characters remaining

Note: The agency, category, and title of your request will be visible to the public. Do not enter personal information here.

Ex: Queens Blvd Roadwork Permit.

Request Description (required)

Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the property at 213 Meadow Street (Block 2591 Lots 1, 5, and 45), Brooklyn NY.

4601 characters remaining

Note: The request details you write here will not be visible to the public. However, the agency may post a description of the records provided.

Ex: Roadwork permits for work done in on Queens Blvd. between 40th and 45th streets, Borough of Queens, in September and October 2017.

Privacy - Terms

Upload File (optional, must be less than 20 Mb)

Clear File

1-Site Location.pdf

Personal Information

First and last name fields are required. The Email field is optional but recommended. If you do not provide an email you must enter either a phone number, fax number, or address in the Alternate Contact Information section.

This information will not be publicly viewable on this site. You must provide contact information so that the agency can respond to your request for records.

First Name (required)

Molly

27 characters remaining

Last Name (required)

Mattern

57 characters remaining

Email

mmattern@langan.com

Alternate Contact Information

No information entered in this section will be visible to the public.

Fields are included in case alternate contact method is needed.

Title

Your role in your organization (if applicable)

64 characters remaining

Organization

Langan Engineering

110 characters remaining

Phone

Privacy - Terms

(973) 560-4900

Fax

(555) 555-5555

Address

Address Line 1

300 Kimball Drive

Address Line 2

Floor 4

City

Parsippany

State / U.S. Territory

New Jersey

Zip

07054

Submit Request

Privacy - Terms

Directory of City Agencies (http://www1.nyc.gov/nyc-resources/agencies.page)

Contact NYC Government (http://www1.nyc.gov/home/contact-us.page)

City Employees (https://a127-ess.nyc.gov) Notify NYC (http://www.nyc.gov/notifynyc)

CityStore (http://a856-citystore.nyc.gov/)

Stay Connected (http://www1.nyc.gov/connect/social-media.page)

NYC Mobile Apps (http://www1.nyc.gov/connect/applications.page)

Maps (http://www1.nyc.gov/nyc-resources/nyc-maps.page)

Resident Toolkit (http://www1.nyc.gov/nyc-resources/resident-toolkit.page)

Search

City of New York. 2016 All Rights Reserved,
NYC is a trademark and service mark of the City of New York
Privacy Policy (http://www1.nyc.gov/home/privacy-policy.page).
Terms of Use (http://www1.nyc.gov/home/terms-of-use.page).

Privacy - Terms

EDGRZ6WUHHW %URRNO'Q1<



-DQXDU\

NP

6XUFH\UL {EUDU,QWHUSRLQWHU3RUW%26
$2 15 %2HRVH1DGDWHU1D\GQDH6UYH\UL
-DQD7\UL&LD-RQRQ F3HQVUHWDSRQULBWRUV DQG
WKH{6HU&RPLW\

3SDUWRQ RQLURQWDO &RQHUYDWLRQ
IRU DOHDD GF\PQW

Molly Mattern

From: noreply@its.ny.gov
Sent: Thursday, January 20, 2022 4:32 PM
To: Molly Mattern
Subject: [External] FOIL Request Confirmation from Open FOIL NY

Follow Up Flag: Follow up
Flag Status: Flagged

Thank you for submitting your FOIL request through Open FOIL NY.

Here is your Open FOIL NY confirmation information for future reference:

MATTERN_DEC_20220120163225863

MATTERN_DOH_20220120163225863

INFORMATION SUBMITTED:

Records Requested From	Department of Environmental Conservation Department of Health
Short Title	213 Meadow Street (Block 2591, Lots 1, 5, and 45), Brooklyn NY
Description	Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the property at 213 Meadow Street (Block 2591 Lots 1, 5, and 45), Brooklyn NY.
Uploaded Files	1-Site Location.pdf
FOIL Response Format	Email
If fees apply, please contact me if costs will be greater than	$0

Your FOIL request has been forwarded to the organization(s) you selected, and the respective Records Access Officer will contact you directly for further processing of

your request. Please allow up to five business days for such communication(s). For your convenience, here is additional contact information:

Department of Environmental Conservation
625 Broadway

Albany, NY 12233-1500

Department of Health
Corning Tower
Room 2364
Albany, NY 12237-0044

January 20, 2022 | 1:55 pm

COVID-19 Vaccines

Vaccine appointments are available at New York State mass vaccination sites for children ages 5- 11. Vaccines are also widely available through your child's pediatrician, family physician, local county health department, FQHC, or pharmacy.

FIND PROVIDER >
(https://covid19vaccine.health.ny.gov/)

Open FOIL NY (https://www.ny.gov/programs/open-foil-ny)

Submit a FOIL Request

In the form below, you can easily select up to three agencies/authorities and submit a FOIL request. All fields marked * are required for a successful submission. If the entity you seek is not listed, please access the New York State All Agencies website (http://www.ny.gov/agencies) for more information.

Thank you for using Open FOIL (https://www.ny.gov/programs/open-foil-ny) NY!

***Records Requested From:**

Department of Environmental Conservation

Additional Agency:

Department of Health

Helpful tip: some DOH records do not require a FOIL request. Find out more. (https://www.health.ny.gov/vital_records/)

+ ADD AGENCY

Title:

--

***First Name:**

Molly

Middle Initial:

***Last Name:**

Mattern

***Email:**

mmattern@langan.com

***Confirm Email:**

mmattern@langan.com

Organization / Affiliation:

Langan Engineering

Address Line 1:

300 Kimball Drive

Address Line 2:

Floor 4

City:

Parsippany

State / Province:

New Jersey

Zip / Postal Code:

07054

Country:

USA

Contact Phone Number:

(973) 560-4900

Fax Number:

Fax Number, include area code

***Short title of requested records:**

Information provided here helps the agency easily identify and categorize your request.

213 Meadow Street (Block 2591, Lots 1, 5, and 45), Brooklyn NY

***FOIL Request / Description of records sought:**

Please provide a clear description of the record(s) sought. Personal, private, sensitive, financial, medical, or health-related information should not be put into the “Description” field below, and should instead be uploaded in a separate document.

Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the property at 213 Meadow Street (Block 2591 Lots 1, 5, and 45), Brooklyn NY.

400/5000

Upload Document(s) in support of your FOIL request:

+ CHOOSE ✖ CANCEL

1-Site Location.pdf - 1.391866 MB

We accept common file types such as: Documents, PDFs, Spreadsheets, Images, etc. **1.39MB/20MB**

***Requested Response Format:**

Email

If fees apply, please contact me if costs will be greater than:
I understand that I will be notified if the fees exceed this amount prior to my request being filled.

$	0	.00

Additional Information

I am requesting this information for the following reason (may select more than one):

- [ ] **I am an individual seeking information for personal use**
- [ ] **I am affiliated with an educational or non-commercial scientific institution, and this request is made for a scholarly or scientific purpose**
- [ ] **I am a representative of, or affiliated with, the news media and this request is made as part of a news gathering effort**
- [ ] **I am affiliated with a private corporation and am seeking information for use in the company's business for commercial purpose**
- [ ] **I am affiliated with a private corporation and am seeking information for use in the company's business for non-commercial purpose**

The foregoing information will be used for statistical purposes.

CONTINUE TO REVIEW

Environmental Resource Mapper

Base Map: Topographical Using this map

- Search
- Tools
- **Layers and Legend**
  - Mussel Screening Streams
  - [x] Significant Natural Communities
    - Natural Communities Near This Location
  - [x] Rare Plants or Animals
  - [ ] Base Flood Elevation Plus 72/75 Inches Sea-level Rise
- Other Wetland Layers
- Reference Layers
- Tell Me More...
- Need A Permit?
- Contacts



IPaC **U.S. Fish & Wildlife Service**

Endangered Species Act Review

Step 1: Request an official species list

An official species list is a letter from the local U.S. Fish and Wildlife Service field office that assists in the evaluation of potential impacts of your project. It includes a list of species that should be considered under Section 7 of the Endangered Species Act, a project tracking number, and other pertinent information from the field office.

Does this project require an official species list?

☑ Yes, request a species list

Upon submitting this form, IPaC will provide a letter from the local U.S. Fish and Wildlife Service office containing a species list that fulfills the requirement listed above, a project tracking number, as well as other pertinent information from the local office.

The following information will be submitted to the U.S. Fish and Wildlife Service and will be part of the public record. All fields are required unless otherwise noted.

My contact information

Please provide your work contact information only. Personal information **should not** be provided.

Agency / organization type

Consultant

Full name

Morgan McBride

Street address

300 Kimball Drive

Floor 4 OPTIONAL

City

Parsippany

State

NJ

Zip

07054

Phone

(973) 560-4900

☐ Save this information to my profile

Project information

Project name

213 Meadow Street (Block 2591, Lots 1, 5, and 45), Brooklyn NY

Project description

Describe the location, size, scope, and timing of this project.

Please consider this a formal Freedom of Information Law (FOIL) request for records regarding buildings, construction, chemical spills, underground storage tanks (USTs), monitoring wells, groundwater sampling, asbestos abatement, radon, hazardous materials and any other documents that your department may have regarding the property at 213 Meadow Street (Block 2591 Lots 1, 5, and 45), Brooklyn NY.

Location

Lead agency

The agency responsible for conducting, permitting, or licensing this action.

☑ Use my contact agency / organization above

Classification

For internal reporting, help us classify the type of this project.

** Other **

I understand that I am providing this information so an official species list can be generated, based on data provided by my local U.S. Fish and Wildlife Service office for the project area that I entered.

The following authorizes the collection of the above information (5 U.S.C. 301; the Federal Records Act, 44 U.S.C. 3101; Homeland Security Act of 2002; Public Law 107-296, 6 U.S.C. 121; and Executive Order 9373) and will be maintained in accordance with the Privacy Act (5 U.S.C. 552a).

APPENDIX G

SITE PHOTOGRAPHS

LANGAN

Appendix G
Photographic Log
213 Meadow Street
Brooklyn, New York

Photo 1: View of the subject property, facing west.

Photo 2: Trucking storage lot located at the subject property, facing north.

Photo 3: View of the trucking repair area at the subject property, facing west.

Photo 4: Three 275-gallon aboveground storage tanks located in the trucking repair area at the subject property.

Photo 5: Degreaser and motor oil drum storage located in the trucking repair area at the subject property.

Photo 6: Degreaser and motor oil drum storage located in the trucking repair area at the subject property.

Photo 7: Out-of-service fuel oil AST located in the truck repair area at the subject property.

Photo 8: Location of the out-of-service fuel oil AST in the truck repair are at the subject property, facing west.

Photo 9: View of a rented portion of the subject property used for food truck storage, facing east.

Photo 10: View of a rented portion of the subject property used for food truck storage, facing west.

Photo 11: View of a rented portion of the subject property used for scaffolding storage, facing southeast.

Photo 12: View of a rented portion of the subject property used for scaffolding storage, facing south.

Photo 13: Adjacent property to the northeast portion of the subject property, facing southwest.

Photo 14: Adjacent property to the north of the subject property, facing northwest.

Photo 15: Adjacent property to the north of the subject property, facing north.

Photo 16: Adjacent property to the west of the subject property, facing west.

Photo 17: Adjacent property to the south of the subject property, facing south.

Photo 18: Adjacent property to the east of the subject property, facing east.

APPENDIX H

LANGAN RESUMES

MOLLY MATTERN

STAFF SCIENTIST

ENVIRONMENTAL ENGINEERING

Ms. Gutelius has over 4 years of environmental engineering, which includes conducting environmental site remediation at various industrial locations in New Jersey. Her specialties include environmental field sampling, construction oversight, data tabulation and analysis, and report composition. Ms. Gutelius is skilled in Groundwater Well Instillation / Monitoring, In-Situ Chemical Oxidation, and Low-Flow Sampling.

SELECTED PROJECTS

- 1010 Park Avenue, New York, NY
- 10-70 Western Avenue, Yonkers, NY
- 17th Street Development, New York, NY
- 2505 Bruckner Boulevard, Bronx, NY
- 291-307 Clay Pitts Road, New York, NY
- 363 Bond Street, Brooklyn, NY
- 450 Clermont Terrace Development, Union, NJ
- 460 West 42st Street, New York, NY
- 479 Degraw Street, Brooklyn, NY
- 530-548 West 53rd/543 West 52nd Street, New York, NY
- 861 Sloan Ave, Trenton, NJ
- Belleville Logistics Center, Belleville, NJ
- Brixmor, Tinton Falls, NJ
- Crow/Bryant Street Development, Brooklyn, NY
- Former BMS Campus, Hopewell, NJ
- Post & Shell, Long Island City, NY
- Wayfair Mold Abatement, Cranbury, NJ

EDUCATION

B.A., Environmental Science
Bucknell University

PROFESSIONAL REGISTRATION

40 Hour HAZWOPER – NJ

8 Hour HAZWOPPER – NJ

OSHA 10-Hour Training in Construction – NJ

AMANDA FORSBURG, CHMM

SENIOR PROJECT SCIENTIST

BROWNFIELD REDEVELOPMENT, DUE DILIGENCE AND SITE INVESTIGATION, REMEDIAL ACTIONS

Ms. Forsburg has 14 years of experience primarily focused on providing environmental support to redevelopment sites within the metropolitan New York area. She has experience with projects in the New York State Department of Environmental Conservation (NYSDEC) Brownfield Cleanup Program (BCP) and Spill Programs, New York City Office of Environmental Remediation (NYCOER) E-Designated and New York City Voluntary Cleanup Program (VCP) sites, and New York City Department of Environmental Protection (NYCDEP) remediation sites. Her field experience includes implementation and management of all phases of environmental projects involving soil, groundwater, and soil vapor contamination including Phase I inspections, Phase II site investigations, Remedial Investigations, and Remedial Actions.

During her tenure at Langan, Ms. Forsburg's experience has included schematic-, design-, and construction-phase project team involvement on numerous large scale construction projects requiring multi-disciplinary coordination and collaboration across different Langan teams and offices.

SELECTED PROJECTS

- 101 Murray Street, New York, NY (NYSDEC Spill Site, Multi-discipline)
- 110 University Place, New York, NY (NYSDEC Spill Site, Multi-discipline)
- 138 Willoughby Street, Brooklyn, NY (NYCOER E-Designation Site, Multi-discipline)
- 180 East 125th Street, New York, NY (NYCOER E-Designation Site, Multi-discipline)
- 1905 Surf Avenue, Brooklyn, NY (NYCOER E-Designation Site, Multi-discipline)
- 1921 Atlantic Avenue, Brooklyn, NY (NYSDEC BCP Site)
- 225 East 39th Street, New York, NY (NYCDEP Remediation Site, Multi-Discipline)
- 23-30 Borden Avenue, Queens, NY (NYSDEC BCP Site, Multi-discipline)
- 28-90 Review Avenue, Queens, NY (NYSDEC BCP Site, Multi-discipline)
- 280 West 155th Street, New York, NY (NYSDEC BCP Site, Multi-discipline)
- 311 West 42nd Street, New York, NY (NYCOER E-Designation Site, Multi-discipline)
- 363 and 365 Bond Street, Brooklyn, NY (NYSDEC BCP Site, Multi-discipline)
- 400 Park Avenue South, New York, NY (NYCOER E-Designation and VCP Site)
- 412 Greenwich Street, New York, NY (NYCOER E-Designation Site, Multi-discipline)

EDUCATION

B.A., Environmental Studies
Bucknell University

B.A., Environmental Geology
Bucknell University

PROFESSIONAL REGISTRATION

Certified Hazardous Materials Manager (CHMM)

OSHA 29 CFR 1910.120 Certification (HAZWOPER)

AFFILIATIONS

New Jersey Society of Women Environmental Professionals (NJSWEP) - MetroNet Committee

Association of Environmental and Engineering Geologists

Professional Women in Construction

Urban Land Institute, Norther New Jersey Chapter - Women's Leadership Initiative Co-Chair

- 42-50 24th Street, Queens, NY (NYSDEC Spill Site, Multi-discipline)
- 460 West 41st Street, New York, NY (NYCOER E-Designation Site, Multi-discipline)
- 505 West 19th Street, New York, NY (NYCOER E-Designation Site, Multi-discipline)
- 508 West 24th Street, New York, NY (NYCOER E-Designation and VCP Site, Multi-discipline)
- 525 West 52nd Street, New York, NY (NYCOER E-Designation Site, Multi-discipline)
- 53 West 53rd Street (MoMA Expansion), New York, NY (NYCOER E-Designation Site, Multi-discipline)
- 54 Crown Street, Brooklyn, NY (NYCOER E-Designation and VCP Site, Multi-discipline)
- 540 West 26th Street, New York, NY (NYSDEC Spill Site, Multi-discipline)
- 550 Tenth Avenue, New York, NY (NYCOER E-Designation Site, Multi-discipline)
- 68 Charlton Street, New York, NY (NYCOER E-Designation Site, Multi-discipline)
- Broome Street Parking Lot Site, New York, NY (NYSDEC BCP Site, Multi-discipline)
- Marble Collegiate Church Office Building, New York, NY (Multi-discipline)
- Norfolk Street Site, New York, NY (NYCOER E-Designation Site, Multi-discipline)

Steven Ciambruschini, PG, LEP

Principal/Vice President
Environmental Site Assessments/Investigations, Brownfield Remediation, UST Management

33 years in the industry ~ 28 years with Langan

Mr. Ciambruschini has over 30 years of experience in hydrogeologic and environmental investigations including management of environmental and geotechnical investigations relating to petroleum and chlorinated solvent spill sites, underground storage tank sites, manufactured gas plant sites, landfills, wastewater treatment facilities and industrial/commercial sites. His experience includes managing environmental compliance audits, remedial investigation, pre-acquisition due diligence and permitting assessment, feasibility studies and design, construction and operation of complex innovative remediation systems to treat, contain and recover contaminated soil and groundwater. These projects are managed under various NJDEP, PADEP, NYDEC, NYCDEP and CTDEP programs. Mr. Ciambruschini provides consultation to a diverse group of clients including private developers, utilities, retail and industrial facilities and is expert in assessing remediation options and funding options under various state and federal grant, loan and tax reimbursement programs including Brownfield programs.

Selected Projects

- Brodson Property, Montville NJ, (RCRA, NJDEP ACO Cleanup)
- Carroll Gardens, Brooklyn, NY (NY Brownfield, EPA Superfund, OER E-designated Site)
- Con Edison Appendix B Spill Sites - Various Locations, NY
- Former MGP Site, Brooklyn, NY (VCP Site)
- Extell Development, Hudson Yards, New York, NY (NYC E-designated, NYS Brownfield Site)
- Pan Graphics, Bergen County, NJ (ISRA, LSRP)
- New Jersey Turnpike General Environmental Services Contract, Various Sites, NJ
- Liberty Science Center, Jersey City, NJ (EO 215)
- Blue Back Square, West Hartford, CT (UST, Transfer Act, Brownfield)
- Hershey, Act II Investigation (PA VCP)
- Hershey, Naugatuck, CT (CT Transfer Act)
- Halby Chemical Sites, Various Sites, DE (CERCLA)
- Unisys, Middletown CT, (CT Transfer Act, Brownfield)
- Ryder Rental, Various Sites in CT (CT Transfer Act)
- St. Marks Avenue, Brooklyn, NY (Vapor Mitigation)
- Pan Graphics, Lodi, NJ (Eco Risk Assessment, LSRP)

Education

M.S., Geology
Montclair State University

M.A., Environmental Science
Montclair University

B.S., Environmental Science
Cook College, Rutgers University

Professional Registration

Professional Geologist (PG) in NY, DE, KY

Licensed Environmental Professional (LEP) in CT

Underground Storage Tank License in NJ

Affiliations

National Ground Water Association

Association of Ground Water Scientists and Engineers

American Association of Petroleum Geologists

Environmental Professionals of Connecticut

American Bar Association (ABA)

LANGAN