Advanced
Cleanup
Technologies
Environmental Consultants

PHASE I ENVIRONMENTAL SITE ASSESSMENT

233-249 Huron Street, Brooklyn, NY 11222

Tax Map #: Block 2524, Lot 46, 54
ACT Project #: A712-BKNY

Prepared for:

Cathay Bank
40-14 Main Street
Flushing, NY 11354

Prepared by:

Advanced Cleanup Technologies, Inc.
228 Park Avenue South, PMB 34864
New York, NY 10003

July 31, 2025

Table of Contents

1.0 EXECUTIVE SUMMARY 1

2.0 INTRODUCTION 2

2.1 Purpose 2

2.2 Detailed Scope of Services 3

2.3 Significant Assumptions 3

2.4 Limitations and Exceptions 3

2.5 Special Terms and Conditions 5

2.6 User Responsibilities 5

3.0 SITE DESCRIPTION 5

3.1 Location and Legal Description 5

3.2 Site and Vicinity Characteristics 5

3.3 Current Use of the Property 6

3.4 Description of Structures, Roads and Other Improvements 6

3.5 Current Use of Adjoining Properties 6

4.0 USER PROVIDED INFORMATION 6

4.1 Environmental Liens 7

5.0 RECORDS REVIEW 7

5.1 Standard Environmental Records Sources 7

5.2 Local Regulatory Agencies 9

5.3 Physical Setting Source 9

5.4 Historical Use Information of the Subject Property and Adjacent Properties 10

5.5 Historical City Directories 11

5.6 Previous Environmental Reports 12

6.0 SITE RECONNAISSANCE 12

6.1 Methodology and Limiting Conditions 12

6.2 General Site Setting 13

6.3 Exterior Observations 13

6.4 Interior Observations 13

6.5 Asbestos 13

6.6 Hazardous Materials 13
6.7 Storage Tanks 14
6.8 Radon 14
6.9 Potable Water 14
6.10 Lead Based Paint 14
6.11 PCBs 14
6.12 Tier I Vapor Encroachment Assessment 14
6.13 Cooling Towers 15
7.0 INTERVIEWS 15
7.1 Interview with Owner 15
7.2 Interview with Site Manager 15
7.3 Interview with Occupants 15
7.4 Interviews with Local Government Officials 15
7.5 Interviews with Others 15
8.0 FINDINGS 16
9.0 OPINION 16
10.0 CONCLUSIONS 16
11.0 DEVIATIONS 17
12.0 ADDITIONAL SERVICES 17
13.0 REFERENCES 17
14.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONALS 18
15.0 QUALIFICATIONS 18

Appendices

Appendix 1 Site Vicinity Map
Appendix 2 Site Plan
Appendix 3 Site Photographs
Appendix 4 Historical Research Documentation
Appendix 5 Database Search Results
Appendix 6 Regulatory Records Documentation
Appendix 7 Interview Documentation
Appendix 8 Qualifications of Environmental Professionals

1.0 EXECUTIVE SUMMARY

Property Address: 233-249 Huron Street, Brooklyn, NY 11222.

Property Usage: Vacant industrial warehouses and vacant lot.

Property Description: The subject property consists of a 1-story industrial warehouse with a partial basement, a 1-story industrial warehouse on grade and a vacant lot. The buildings have a combined footprint of approximately 15,000 square feet, and the property is approximately 17,500 square feet in area.

Subject	Acceptable	Routine Solution	Additional Study	Estimated Cost
Site History	No		Yes	Undetermined
Database Review	X			
Local Records Review	X			
Visual Observations	X			
Adjacent Properties	X			
USTs and ASTs	X			
PCBs	X			
Asbestos	X			
Radon	X			
Lead-Based Paint	X			

Advanced Cleanup Technologies, Inc. (ACT) has performed the Phase I Environmental Site Assessment in conformance with the scope of limitations of ASTM Practice E 1527-21 of 233-249 Huron Street, Brooklyn, NY 11222, the "subject property." Any exceptions to or deletions from this practice are described in Section 2.2 of this report. This assessment has revealed no evidence of recognized environmental conditions in connection with the subject property, except for the following:

- Historical onsite factory, foundry and machine shop usage.
- Confirmed onsite soil, soil vapor and groundwater contamination.
- Confirmed onsite vapor encroachment condition.

No controlled recognized environmental conditions were identified at the subject property. A controlled recognized environmental condition is a recognized environmental condition affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls (for example, activity and use limitations or other property use limitations).

No historical recognized environmental conditions were identified at the subject property. An historical recognized environmental condition is a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls.

No *de minimis* conditions were identified at the subject property. A *de minimis* condition is a condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies (excluding local asbestos and lead situations).

No data gaps were identified during this Phase I Environmental Site Assessment. A data gap is a lack of or inability to obtain information required by this practice despite good faith efforts by the environmental professional to gather such information. Data gaps may result from incompleteness in any of the activities required by this practice, including, but not limited to site reconnaissance and interviews.

2.0 INTRODUCTION

Pursuant to the request of Cathay Bank, as our client, ACT has conducted a Phase I Environmental Site Assessment (ESA) of 233-249 Huron Street, Brooklyn, NY 11222. The Assessment was performed to meet or surpass the industry standard established by ASTM's Standard Practice for Environmental Site Assessments (E 1527-21). This ESA was conducted in accordance with and subject to the proposal dated January 25, 2025.

2.1 Purpose

The purpose of this report is to assess the subject property for evidence of Recognized Environmental Conditions (RECs) in accordance with the provisions of ASTM Standard E 1527-21. As defined by the ASTM, the term recognized environmental condition means: "(1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products

in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment."

A material threat is "an obvious threat which is likely to lead to a release and that, in the opinion of the environmental professional, would likely result in impact to public health or the environment."

2.2 Detailed Scope of Services

The Phase I ESA includes a visual inspection of the subject property, improvements, and surrounding properties to identify potential recognized environmental conditions. The adjacent properties were viewed from the subject property and roadways to determine potential sources of contamination or environmental impacts that could migrate to the subject property.

Research into historical uses of the property and surrounding land and a review of regulatory agency files and databases pertaining to the property and surrounding properties were performed.

Interviews with property representatives regarding past and present conditions and interviews with local government officials were performed to determine if environmental issues exist at the subject property.

The Phase I ESA also contains non-ASTM items: a limited visual screening for suspect asbestos-containing materials, a limited screening for lead based paint, and a review of regulatory agency documents regarding lead in drinking water and radon in the vicinity of the subject property.

2.3 Significant Assumptions

Information and records provided by the user, outside vendors, and regulatory agencies consulted by ACT are assumed to be correct and complete.

2.4 Limitations and Exceptions

This practice constitutes "All Appropriate Inquiry" (AAI) into the previous ownership and uses of the property consistent with good commercial or customary practice in accordance with the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA, 42 U.S.C. 9601). Data gaps may occur in the event that a portion of the AAI practice cannot be fully

performed as per ASTM E 1527-21, despite the good faith effort of the environmental professional. This practice does not address local or state environmental assessment obligations that may be applicable to the property.

The purpose of this ESA is to assess the subject property with respect to the presence of hazardous substances or petroleum products in accordance with provisions of ASTM Standard E 1527-21. This practice is intended to permit the user, which may be a perspective purchaser or tenant, an owner, a lender or a property manager, to satisfy requirements to qualify as an innocent land owner, contiguous property owner, or bona fide prospective purchaser, hereinafter known as the Landowner Liability Protections (LLPs).

The innocent landowner defense applies to: (1) a person who did not know and had no reason to know that contamination existed on the subject property at the time the purchaser acquired the subject property; (2) a government entity which acquired the subject property by escheat, or through any other involuntary transfer or acquisition, or through the exercise of eminent domain authority by purchase or condemnation; or (3) a person who acquired the facility by inheritance or bequest. To qualify for the innocent landowner defense, such person must have made AAI on or before the data of purchase.

The contiguous property owner liability protection applies to a person who owns real property that is contiguous to, and that is or may be contaminated by hazardous substances from other real property that is not owned by that person. Furthermore, such person conducted AAI at the time of acquisition of the subject property and did not know or have reason to know that the subject property was or could be contaminated by a release or threatened release from the contiguous property.

The bona fide prospective purchaser liability protection allows a purchaser to acquire property with knowledge that it is contaminated. The BFPP liability protection applies to purchasers (and their tenants) that acquire ownership of a facility after January 11, 2002.

This Phase I ESA has been prepared to assess the potential environmental liabilities at the subject site with respect to data that Advanced Cleanup Technologies, Inc. has accumulated during the Phase I ESA. The conclusions presented in this report are based solely on the observations of the site at the time of the assessment. Data provided, including information provided by others, were utilized in assessing the site conditions. The accuracy of this Phase I ESA is subject to the accuracy of the information provided. Advanced Cleanup Technologies, Inc. is not responsible for areas not seen or information not collected.

This Phase I ESA was performed at the request of Cathay Bank in accordance with ASTM E 1527-21. The report has been prepared for the sole use of Cathay Bank; no other party may use the report without written consent from ACT and Cathay Bank.

2.5 Special Terms and Conditions

No special terms or condition are in addition to the scope outlined in Section 2.2 of this Phase I ESA.

2.6 User Responsibilities

This practice does not address the continuing obligations of the user, including protection of activity and use limitations (AULs), which are legal or physical restrictions or limitations on the use of, or access to, a site or facility; (1) to reduce or eliminate potential exposure to hazardous substances or petroleum products in the soil, soil vapor, groundwater, and/or surface water on the property, or (2) to prevent activities that could interfere with the effectiveness of a response action, in order to ensure maintenance of a condition of no significant risk to public health or the environment.

This practice also does not address the duty to take reasonable steps to prevent future releases or the duty to comply with legally required release reporting obligations.

3.0 SITE DESCRIPTION

3.1 Location and Legal Description

The address of the subject property is 233-249 Huron Street, Brooklyn, NY 11222. The New York City tax map identification number is Block 2524, Lot 46, 54.

3.2 Site and Vicinity Characteristics

The subject property is located in an industrial area in the Greenpoint section of the borough of Brooklyn in New York City. The immediate vicinity of the subject property contains industrial buildings. The subject property is located approximately 1,500 feet south of Newtown Creek and 1/2 mile east of East River.

3.3 Current Use of the Property

The subject property currently contains vacant warehouse buildings and a vacant lot. The current uses do not appear to be impacting the environmental quality of the subject property.

3.4 Description of Structures, Roads and Other Improvements

The subject property is located along the north side of Huron Street, between Provost Street to the east and McGuinness Boulevard to the west. Electric, water, and natural gas services enter underground from the south. All utility meters are located in the basement.

Heat and hot water were not supplied to the building at the time of the inspection. The building is connected to the municipal sewer system.

3.5 Current Use of Adjoining Properties

The exterior conditions of adjacent properties were viewed from the subject property and adjacent roadways.

North:	1-story industrial warehouse
South:	1- and 2-story industrial warehouses
East:	3-story industrial warehouse
West:	1-story warehouse

The adjacent properties do not appear to be impacting the environmental quality of the subject property.

4.0 USER PROVIDED INFORMATION

A User Questionnaire was provided to the real estate representatives of the subject property. The completed User Questionnaire has not been provided to ACT at the time of this report.

4.1 Environmental Liens

An environmental lien search is an inquiry into the existence of environmental cleanup liens against the subject property that are filed or recorded under federal, tribal, state, or local laws.

An environmental lien search was not included in the scope of work of this assessment and therefore was not performed. However, if the findings of a lien search performed by any other party reveal the presence of an environmental related lien on the subject property, this information should be forwarded to ACT for review, and any significant findings will be added to this assessment as an addendum.

5.0 RECORDS REVIEW

5.1 Standard Environmental Records Sources

In an effort to determine the potential impact from hazardous waste activities or petroleum products at the subject property, adjacent properties and surrounding area, a review of database information on waste sites within one mile of the subject property was conducted. The database report was provided to ACT by Environmental Risk Information Services on January 2, 2025.

The review included a search of the following Federal, United States Environmental Protection Agency (USEPA), and New York State Department of Environmental Conservation (NYSDEC) databases:

Source List	Minimum Search Distance (Miles)	Number of Sites Within the Minimum Search Distance	Follow-up Required
Federal NPL Site List	1.0	2	No
Federal Delisted NPL Site List	0.5	0	No
Federal CERCLIS List	0.5	4	No
Federal CERCLIS NFRAP Site List	0.5	2	No
Federal RCRA CORRACTS Facilities List	1.0	4	No
Federal RCRA TSD	0.5	0	No
Federal RCRA Generators List	0.25	83	No
Federal ERNS List	Property only	0	No
Federal IC/EC Registry	Property only	0	No

Other Federal List	Property only	0	No
State and Tribal SHWS	1.0	31	No
State and Tribal Landfill and/or SW Disposal	0.5	22	No
State and Tribal Leaking UST and Spills	0.5	236	No
State and Tribal Registered Storage Tanks	Property & adjoining properties	0	No
State and Tribal Brownfield and VCP Sites	0.5	12	No
Other Federal or State List	Property only	0	No

The subject property, 241-249 Huron Street, was identified in the following state and federal databases:

NYSDEC Spills List:

Spill No. 0011791 was reported at RZ Metal Corp 247 Huron Street on February 1, 2001 as a result of the discharge of an unknown substance, possibly 25 gallons of methylene diphenyl diisocyanate in May 2000. The spill was closed administratively on December 29, 2005.

Spill No. 1403242 was reported at 241-247 Huron on June 25, 2014 as a result of the discharge of heavy mineral oil into an onsite pit. The pit was cleaned out and the spill was closed on August 26, 2014.

USEPA RCRA Generators List

The subject property, J&J Bronze & Aluminum Casting Corp at 249 Huron Street is listed as a generator of metals wastes (lead, chromium, cadmium and barium), reactive and ignitable wastes commencing on July 1, 1978 and continuing through May 4, 2011.

NYSDEC Brownfields Cleanup Program

The subject property is in the process of applying to enter the New York State Brownfields Cleanup Program to investigate and remediate impacted media as part of the redevelopment of the property.

5.2 Local Regulatory Agencies

The New York City Department of Buildings (DOB) file contains a property file for Block 2524, Lots 46 and 54. The property address is listed as 233-249 Huron Street. The owner is listed as Daly NY LLC. The buildings are classified as industrial warehouse buildings, and the property is zoned in a M1-1 manufacturing district. The buildings have a combined footprint of approximately 15,000 square feet, and the property is approximately 17,500 square feet in area. The construction date is listed as 1920, with an alteration in 1968.

The property is listed as having no open DOB violations or Environmental Control Board violations.

There were 5 Certificates of Occupancy (C of Os) listed for the subject property on the DOB website. A C of O dated 1922 indicates that a factory is located at the property. A C of O dated January 11, 1943 indicates that a foundry, machine shop and pattern shop are located at the property. A C of O dated October 20, 1960 indicates that a 3-story building with a factory and office is located at the property. A March 9, 1961 C of O indicates that 237-239 Huron Street is a parking lot and a January 4, 1968 C of O indicates that a metal sorting and shipping business is located at the property.

The New York City Department of Health, Department of Environmental Protection, and Bureau of Fire Prevention have not responded to our information requests at the time of this report. Pertinent information received from these agencies will be provided in an addendum to this report.

5.3 Physical Setting Source

The topography of the area is flat. The vicinity of the site is approximately 12 feet above mean sea level. The ground surface in the vicinity of the property is covered with asphalt and concrete pavement and industrial buildings.

The subsurface beneath the site consists of unconsolidated sand and gravel layers from the ground surface to approximately 50 feet below ground surface where the Raritan confining unit is encountered. The major aquifer systems beneath the subject property are the Upper glacial and Lloyd aquifers. Bedrock beneath the subject property is located approximately 200 feet below ground surface. Regional ground water in the vicinity of the subject property is expected to flow northwest towards Newtown Creek and the East River.

5.4 Historical Use Information of the Subject Property and Adjacent Properties

Historical fire insurance maps for the years 1887 through 1989 were obtained from Environmental Risk Information Services and reviewed by ACT. Where necessary, historical aerial photographs for the years 1924-2021 were reviewed to supplement fire insurance map coverage.

Summary	Subject Property	As of 1887, the subject property was improved with 2- and 3-story dwellings and a 1-story "Straw Dyeing shed. By 1905, the eastern portion of the property was improved with a 2-story building occupied by "H.C. Fischer Iron Works." By 1916, the 2-story building was occupied by "Greenpoint Iron Foundry" and "Ornamental Iron Works". By 1942, the eastern portion of the property was labeled "Laundry Mach Shop". By 1951, the dwellings in western portion of the property were used for small shops. By 1965, the eastern portion property was used for scrap metal sorting and the western portion was vacant except for a small dwelling. By 1979, scrap metal sorting occupied the entire property except for the westernmost lot used as a loading dock. The property remained substantially the same through 2021.
	North	As of 1887, the properties were improved with a 3-story dwelling and a 1-and 2-story building, which was part of the "H.C. Fisher Iron Works." By 1916, the property was labeled "Greenpoint Iron Foundry," which extended onto the subject property. By 1942, the buildings were occupied by a "Brick Crushing Plant" and a 'wood working" shop. By 1979, the property was utilized for auto repair and warehousing. The property remained substantially the same through 2021.
	South	As of 1887, the property was improved with a 2-story and 4-story building utilized for "Leather Dressing". By 1905, a 3-story building was occupied by H. C. Kinde & Co. By 1916, a 1-story building covered the entire lot and was occupied by "F. Hecht & Co. Leather Works" By 1942, a 1- and 2-story building was occupied by a laundry business. The property remained substantially the same through 2021.
	East	As of 1887, the property was improved with a 1-story shed. By 1905, the property was occupied by a 3-story industrial building utilized for "Pattern Making and Cutting." By 1916, the property became part of "Lincoln Dye Works".

		By 1951, the property was labeled "Mach. Shop" and "Bronze Foundry". By 1987, the 3-story building was labeled manufacturing factory. The property remained substantially the same through 2021.
	West	As of 1887, the property was improved with a 3-story dwelling. By 1979, the property was occupied by a 1-story building labeled Auto Repair. The property remained substantially the same through 2021.

5.5 Historical City Directories

Historical city directories for the subject property and the adjacent properties for the years 1937 through 2023 were obtained from Environmental Risk Information Services and reviewed by ACT.

Summary	Subject Property	233 Huron Street: Residential occupants (1947-1965). 235 Huron Street: Residential occupants (1945-1997). 245 Huron Street: Kahn Leo M Laundry Machy (1945-1947). 247 Huron Street: Greenpoint Metal Co. (1952-1959), R&Z Metal Corp (1965-2023), GG Salvage Corp (2016-2020). 249 Huron Street: Lincoln Dye Works (1937-1939), Dossert Mfg Corp (1945-1970), Wilmar Bronze Foundry (1945-1970), J&J Brnz&Alm Cstng (1985-2023), Grand Renovatoin Inc (2008-2023), J&B Ironworks (2016-2023).
	North	230 Green Street: Stern Engraving (1952), Carpet Services (1955-1970), marine and construction contractors (1979-1997), electrical contractors (2003-2016), candy wholesaler (2020-2023). 234 Green Street: Iron works (1937-1965), auto body (1994-2023). 240 Green Street: brick company (1937-1952), iron works (1952-1983), auto center (1994-2023). 242 Green Street: Textiles (1939), paint & lacquer corp (1945), dyes & jibs (1947-1955), Focus Optical Corp

		(1965-1970), Precise Plastics (1979-1997).
	South	234 Huron Street: residential occupants (1937-2011), Rite Way Tire Service (2016-2023). 236 Huron Street: Weldize Corp (1937-1985), residential occupants (1990-2023). 240 Huron Street: laundry service (1937-2023). 246 Huron Street: Trucking and warehousing (1955-1985).
	East	251 Huron Street: No listings.
	West	231 Huron Street: No listings.

5.6 Previous Environmental Reports

ACT performed a Phase II Environmental Site Assessment of the subject property on February 25, 2025. The purpose of the Phase II assessment was to determine whether historical industrial operations at the subject property had affected its environmental quality. Field activities included the installation and sampling of four (4) soil borings, three (3) monitoring wells, four (4) sub-sab soil vapor probes and one (1) indoor air sample. All samples were analyzed by a NYSDOH-certified laboratory.

The results of the Phase II assessment indicated that soil and groundwater samples were contaminated with chlorinated volatile organic compounds (CVOCs) above regulatory criteria. The results also indicated that the concentrations of CVOCs in sub-slab soil vapor exceeded NYSDOH screening matrices and that a vapor encroachment condition was present beneath the existing building.

6.0 SITE RECONNAISSANCE

6.1 Methodology and Limiting Conditions

Paul Stewart of ACT performed a site inspection on February 18, 2025. A representative of the property provided access. The property was traversed on foot.

6.2 General Site Setting

The subject property is located in an industrial area in the Greenpoint section of Brooklyn. The topography of the area is flat. The immediate vicinity of the subject property contains industrial development.

6.3 Exterior Observations

The subject property contains a 1-story industrial warehouse with a partial basement, a 1-story industrial warehouse on grade and a vacant lot. The exteriors of the buildings are constructed of brick masonry. The buildings have rubber or asphalt gabled roofs. The vacant lot is located to the west of the two buildings and is covered with dirt and debris.

Solid waste storage with not observed during the inspection. No exterior storm drains were observed at the property. Tshere was no visible evidence of hazardous waste generation at the subject property. No stains, odors, or evidence of spills were observed throughout the property.

6.4 Interior Observations

The buildings are currently vacant. The interiors of the buildings consist of concrete floors; concrete and concrete block walls; and steel ceilings. The main entrances of the buildings are located on the south property boundary along Huron Street.

A partial basement was located in the southwest corner of the building. A small sump was observed in the basement floor. No stains, odors, or evidence of spills were observed in the vicinity of the sump or throughout the building interior.

6.5 Asbestos

A visual inspection of the property for suspect asbestos-containing materials (ACM) such as pipe and boiler insulation, ceiling tiles, and floor tiles was conducted. No suspect asbestos-containing materials were observed at the property.

These findings comprise only a preliminary inspection of the subject property for ACM and should not be interpreted as a formal asbestos survey. All federal, state, and local regulations should be followed with respect to SACM if renovations or demolition are to be performed at the property.

6.6 Hazardous Materials

A visual inspection of the property was conducted for evidence of potential hazardous material contamination. No hazardous materials were observed at the subject property. No areas of stressed vegetation or excavated areas were observed anywhere on the property. No indication of previous environmental investigations, such as groundwater monitoring wells, was observed at

the property or any adjoining properties. No pits, ponds, or lagoons indicative of hazardous waste disposal were observed at the property.

6.7 Storage Tanks

No aboveground storage tanks were observed at the property. No evidence of underground storage tanks, such as fill pipes or vent pipes, was observed at the property. No evidence of former underground storage tanks, such as asphalt or concrete patches, was observed at the property.

6.8 Radon

The New York State Department of Health maintains records of average radon levels by county. The average level for Kings County is less than 2 picoCuries per Liter (pCi/L). This level is considered to be within the normal background range. The United States Environmental Protection Agency standard for radon is 4.0 pCi/L.

6.9 Potable Water

The subject property is supplied water by the local municipality. The municipality monitors the quality of this water for organic and inorganic constituents, including lead, in accordance with federal law. The municipality must maintain lead concentrations at less than 15 micrograms per liter.

6.10 Lead Based Paint

A visual inspection of the property for chipped, peeling, or cracking paint was performed. No areas of chipped, peeling, or deteriorating paint were observed at the property. Painted surfaces were in good condition.

These findings comprise only a preliminary inspection for lead-based paint at the subject property and should not be interpreted as a formal lead-based paint inspection. All federal, state, and local regulations should be followed with respect to lead-based paint if renovations or demolition activities affecting painted surfaces are to be performed.

6.11 PCBs

No electrical transformers were observed at the property. The building does not contain an elevator. The building does not contain any other equipment that could contain substantial amounts of PCB-contaminated oil.

6.12 Tier I Vapor Encroachment Assessment

A Tier I Vapor Encroachment Assessment was performed on the subject property in accordance with ASTM E 2600-15, *Standard Guide for Vapor Encroachment Screening on*

Property Involved in Real Estate Transactions, December 2015. A Tier I Vapor Encroachment Assessment determines whether there actually is or is a potential for volatile vapors to encroach upon the subject property, producing a vapor encroachment condition. A vapor encroachment condition is the presence or likely presence of vapors in the subsurface of the subject property caused by the release of vapors from contaminated soil or groundwater either on or near the subject property.

As indicated in Section 5.6, a previous Phase II assessment identified sub-slab soil vapor levels that warranted mitigation pursuant to the NYSDOH soil vapor intrusion guidelines.

6.13 Cooling Towers

No cooling towers were observed at the property during the inspection.

7.0 INTERVIEWS

7.1 Interview with Owner

A Property Owner/Representative Questionnaire has not been returned at the time of this report.

7.2 Interview with Site Manager

A property manager was not available during the site inspection for interview.

7.3 Interview with Occupants

No site occupants were available during the site inspection for interview.

7.4 Interviews with Local Government Officials

ACT attempted to contact officials at the New York City Department of Buildings and Department of Environmental Protection to obtain information indicating recognized environmental conditions in connection with the subject property. No officials were available for interview regarding the subject property.

7.5 Interviews with Others

No additional interviews were conducted as part of this assessment.

8.0 FINDINGS

During the course of this Phase I ESA, ACT has not identified historical industrial operations and a vapor encroachment condition at recognized environmental conditions.

No controlled recognized environmental conditions, no historical recognized environmental conditions, and no *de minimis* conditions were identified at the subject property. No data gaps were identified during this assessment.

9.0 OPINION

Based on the scope of work performed, it is ACT's professional opinion that historical onsite industrial operations, confirmed soil, soil vapor and groundwater contamination and an onsite vapor encroachment condition are recognized environmental conditions at the subject property or that could adversely impact upon its environmental quality and warrants further environmental study.

10.0 CONCLUSIONS

Advanced Cleanup Technologies, Inc. (ACT) has performed the Phase I Environmental Site Assessment in conformance with the scope of limitations of ASTM Practice E 1527-21 of 233-249 Huron Street, Brooklyn, NY 11222, the "subject property." Any exceptions to or deletions from this practice are described in Section 2.2 of this report. This assessment has revealed no evidence of recognized environmental conditions in connection with the subject property, except for the following:

- Historical onsite factory, foundry and machine shop usage.
- Confirmed onsite soil, soil vapor and groundwater contamination.
- Confirmed onsite vapor encroachment condition.

11.0 DEVIATIONS

No deviations from the detailed scope of services outlined in Section 2.2 were performed as part of this Phase I ESA.

12.0 ADDITIONAL SERVICES

No additional services beyond the detailed scope of services outlined in Section 2.2 were performed as part of this Phase I ESA.

13.0 REFERENCES

American Society for Testing and Materials Practice E 1527-21, November 2021.

American Society for Testing and Materials Practice E 2600-15, December 2015.

U.S.E.P.A. Comprehensive Environmental Response, Compensation and Liability Act of 1980 (CERCLA) (42 U.S.C. 9601 et. seq.).

Databases obtained by ACT from Environmental Risk Information Services.

Historical City Directories obtained by ACT from Environmental Risk Information Services.

New York City Department of Buildings.

New York City Department of Health.

New York City Department of Environmental Protection.

New York City Bureau of Fire Prevention.

U.S.G.S. 7.5 Minute Series Topographic Map, Brooklyn, NY Quadrangle.

Hydrogeologic Framework of Long Island, New York by Smolensky, D.A., Buxton, H.T., and

Shernoff, P. K., 1989.

Fire Insurance Maps and Aerial Photographs obtained by ACT from Environmental Risk Information Services.

USEPA Safe Drinking Water Act, 42 USC 300, et. Seq. 1982.

14.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONALS

This practice must be conducted by an Environmental Professional (EP) or under the supervision of an EP, "a person meeting the education, training, and experience requirements as set forth in 40 CFR Part 312.10(b)." Individuals who do not qualify as EPs may assist in the performance of the AAI if appropriately trained and supervised by an EP. At a minimum, the EP must be involved in the planning of the site reconnaissance and interviews. The EP is also responsible for the review of the Phase I Environmental Site Assessment and interpretation of the information obtained via the Phase I Investigation.

ACT declares that to the best of our professional knowledge and belief we meet the definition of EP defined in 312.10 of 40 CFR Part 312. ACT has the specific qualifications based on education, training and experience to assess a property of the nature, history, and setting of the subject property. ACT has developed and performed the All Appropriate Inquiry in conformance with the standards and practices set forth in 40 CFR Part 312.

Dated: July 31, 2025



By: Paul Stewart, JD, MS, QEP
President

15.0 QUALIFICATIONS

The qualifications of the environmental professionals associated with the completion of this Phase I ESA are provided as an Appendix to this report.

APPENDICES

Appendix 1 Site Vicinity Map

Topographic Information



Current USGS Topo (2019)

0 0.2 0.4 0.8 Miles


N

Quadrangle(s): Brooklyn,NY

Source: USGS 7.5 Minute Topographic Map

Appendix 2 Site Plan

R & Z Metal Corporation



Appendix 3 Site Photographs

Appendix 4 Historical Research Documentation

FIRE INSURANCE MAPS

Project Property: 247 Huron Street, Brooklyn
247 Huron Street Brooklyn NY 11222
Project No: A712-BKNY
Requested By: Advanced Cleanup Technologies, Inc.
Order No: 25010100008
Date Completed: January 01, 2025

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Listed below, please find the results of our search for historic fire insurance maps from our in-house collection, performed in conjuction with your ERIS report.

Date	City	State	Volume	Sheet Number(s)
1989	Brooklyn	New York	4	46, 47, 48, 54, 55
1988	Brooklyn	New York	4	46, 47, 48, 54, 55
1987	Brooklyn	New York	4	46, 47, 48, 54, 55
1986	Brooklyn	New York	4	46, 47, 48, 54, 55
1983	Brooklyn	New York	4	46, 47, 48, 54, 55
1982	Brooklyn	New York	4	46, 47, 48, 54, 55
1981	Brooklyn	New York	4	46, 47, 48, 54, 55
1980	Brooklyn	New York	4	46, 47, 48, 54, 55
1979	Brooklyn	New York	4	46, 47, 48, 54, 55
1965	Brooklyn	New York	4	46, 47, 48, 54, 55
1951	Brooklyn	New York	4	46, 47, 48, 54, 55
1942	Brooklyn	New York	4	46, 47, 48, 54, 55
1916	Brooklyn	New York	4	46, 47, 48, 54, 55
1905	Brooklyn	New York	4	46, 47, 48, 54, 55
1887	Brooklyn	New York	4	91, 93, 94

Individual Fire Insurance Maps for the subject property and/or adjacent sites are included with the ERIS environmental database report to be used for research purposes only and cannot be resold for any other commercial uses other than for use in a Phase I environmental assessment.

Fire Insurance Map




0 87.5 175 350 525 700

Feet

1989

Address: 247 Huron Street Brooklyn NY 11222



Map sheet(s):
Volume 4: 46,47,48,54,55;

Order Number 25010100008

ERIS

Fire Insurance Map




1988

Address: 247 Huron Street Brooklyn NY 11222

0 87.5 175 350 525 700

Feet

N



Map sheet(s):
Volume 4: 46,47,48,54,55;

Order Number 25010100008


ERIS

Fire Insurance Map



1987

Address: 247 Huron Street Brooklyn NY 11222



Map sheet(s):
Volume 4: 46,47,48,54,55;

Order Number 25010100008


ERIS

Fire Insurance Map



1986

Address: 247 Huron Street Brooklyn NY 11222



Map sheet(s):
Volume 4: 46,47,48,54,55;

N

0 87.5 175 350 525 700

Feet

Order Number 25010100008


ERIS

Fire Insurance Map



1983

Address: 247 Huron Street Brooklyn NY 11222



Map sheet(s):
Volume 4: 46,47,48,54,55;

0 87.5 175 350 525 700
Feet

Order Number 25010100008


ERIS

Fire Insurance Map



1982

Address: 247 Huron Street Brooklyn NY 11222



Map sheet(s):
Volume 4: 46,47,48,54,55;


N

0 87.5 175 350 525 700
Feet

Order Number 25010100008

ERIS

Fire Insurance Map




0 87.5 175 350 525 700

Feet

1981

Address: 247 Huron Street Brooklyn NY 11222



Map sheet(s):
Volume 4: 46,47,48,54,55;

Order Number 25010100008


ERIS

Fire Insurance Map



1980

Address: 247 Huron Street Brooklyn NY 11222



Map sheet(s):
Volume 4: 46,47,48,54,55;

0 87.5 175 350 525 700
N
Feet

Order Number 25010100008


ERIS

Fire Insurance Map



1979

Address: 247 Huron Street Brooklyn NY 11222




Map sheet(s):
Volume 4: 46,47,48,54,55;

0 87.5 175 350 525 700
Feet

Order Number 25010100008

ERIS

Fire Insurance Map




1965

Address: 247 Huron Street Brooklyn NY 11222

0 87.5 175 350 525 700

Feet




Map sheet(s):
Volume 4: 46,47,48,54,55;

Order Number 25010100008

ERIS

Fire Insurance Map




0 87.5 175 350 525 700

Feet

1951

Address: 247 Huron Street Brooklyn NY 11222




Map sheet(s):
Volume 4: 46,47,48,54,55;

Order Number 25010100008


ERIS

Fire Insurance Map



1942

Address: 247 Huron Street Brooklyn NY 11222



Map sheet(s):
Volume 4: 46,47,48,54,55;

Order Number 25010100008


ERIS

Fire Insurance Map



1916

Address: 247 Huron Street Brooklyn NY 11222



Map sheet(s):
Volume 4: 46,47,48,54,55;

Order Number 25010100008

ERIS

Fire Insurance Map




0 87.5 175 350 525 700

Feet

N

1905

Address: 247 Huron Street Brooklyn NY 11222



Map sheet(s):
Volume 4: 46,47,48,54,55;

Order Number 25010100008


ERIS

Fire Insurance Map



1887

Address: 247 Huron Street Brooklyn NY 11222



Map sheet(s):
Volume 4: 91,93,94;

N

0 87.5 175 350 525 700

Feet

Order Number 25010100008

ERIS

HISTORICAL AERIALS

Project Property: 247 Huron Street, Brooklyn
247 Huron Street
Brooklyn NY 11222

Project No: A712-BKNY

Requested By: Advanced Cleanup Technologies, Inc.

Order No: 25010100008

Date Completed: January 02,2025

Aerial Maps included in this report are produced by the sources listed above and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property. ERIS provides no warranty of accuracy or liability. The information contained in this report has been produced using aerial photos listed in above sources by ERIS Information Inc. (in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS'. The maps contained in this report do not purport to be and do not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Date	Source	Scale	Comments
2021	United States Department of Agriculture	1" = 500'	
2019	United States Department of Agriculture	1" = 500'	
2017	United States Department of Agriculture	1" = 500'	
2015	United States Department of Agriculture	1" = 500'	
2013	United States Department of Agriculture	1" = 500'	
2011	United States Department of Agriculture	1" = 500'	
2009	United States Department of Agriculture	1" = 500'	
2006	United States Department of Agriculture	1" = 500'	
2002	United States Geological Survey	1" = 500'	
1995	United States Geological Survey	1" = 500'	
1991	United States Geological Survey	1" = 500'	Best Copy Available
1984	United States Geological Survey	1" = 500'	
1976	United States Geological Survey	1" = 500'	Best Copy Available
1966	United States Geological Survey	1" = 500'	
1959	United States Air Force	1" = 500'	Best Copy Available
1954	United States Geological Survey	1" = 500'	
1924	Fairchild	1" = 500'	




Year: 2021
Source: USDA
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS




Year: 2019
Source: USDA
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS




Year: 2017
Source: USDA
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS




Year: 2015
Source: USDA
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS




Year: 2013
Source: USDA
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS




Year: 2011
Source: USDA
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS




Year: 2009
Source: USDA
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS



Year: 2006
Source: USDA
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS



Year: 2002
Source: USGS
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS



Year: 1995
Source: USGS
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS




Year: 1991
Source: USGS
Scale: 1" = 500'
Comment: Best Copy Available

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS



Year: 1984
Source: USGS
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS



Year: 1976
Source: USGS
Scale: 1" = 500'
Comment: Best Copy Available

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS



Year: 1966
Source: USGS
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS



Year: 1959
Source: USAF
Scale: 1" = 500'
Comment: Best Copy Available

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS



Year: 1954
Source: USGS
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS



Year: 1924
Source: FAIRCHILD
Scale: 1" = 500'
Comment:

Address: 247 Huron Street, Brooklyn, NY
Approx Center: -73.95126475,40.73359024

Order No: 25010100008

ERIS

CITY DIRECTORY

Project Property:	*247 Huron Street, Brooklyn* *247 Huron Street* *Brooklyn,NY 11222*
Project No:	*A712-BKNY*
Requested By:	*Advanced Cleanup Technologies, Inc.*
Order No:	*25010100008*
Date Completed:	*January 03, 2025*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

January 03, 2025
RE: CITY DIRECTORY RESEARCH
247 Huron Street
Brooklyn,NY 11222

Thank you for contacting ERIS for an City Directory Search for the site described above. Our staff has conducted a reverse listing City Directory search to determine prior occupants of the subject site and adjacent properties. We have provided the nearest addresses(s) when adjacent addresses are not listed. If we have searched a range of addresses, all addresses in that range found in the Directory are included.

Note: Reverse Listing Directories generally are focused on more highly developed areas. Newly developed areas may be covered in the more recent years, but the older directories will tend to cover only the "central" parts of the city. To complete the search, we have either utilized the ACPL, Library of Congress, State Archives, and/or a regional library or history center as well as multiple digitized directories. These do not claim to be a complete collection of all reverse listing city directories produced.

ERIS has made every effort to provide accurate and complete information but shall not be held liable for missing, incomplete or inaccurate information. To complete this search we used the general range(s) below to search for relevant findings. If you believe there are additional addresses or streets that require searching please contact us at 866-517-5204.

Search Criteria:
225-275 of Green St
225-275 of Huron St
Search Notes:

Search Results Summary

Date	Source	Comment
2023	DIGITAL BUSINESS DIRECTORY	
2020	DIGITAL BUSINESS DIRECTORY	
2016	DIGITAL BUSINESS DIRECTORY	
2011	DIGITAL BUSINESS DIRECTORY	
2008	DIGITAL BUSINESS DIRECTORY	
2003	DIGITAL BUSINESS DIRECTORY	
2000	DIGITAL BUSINESS DIRECTORY	
1997	COLE	
1994	COLE	
1990	COLE	
1985	COLE	
1983	COLE	
1979	NY TELEPHONE COMPANY	
1975-76	COLE	
1970	NY TELEPHONE COMPANY	
1965	NY TELEPHONE COMPANY	
1959	NY TELEPHONE COMPANY	
1955	NY TELEPHONE COMPANY	
1952	NY TELEPHONE COMPANY	
1947	NY TELEPHONE COMPANY	
1945	NY TELEPHONE COMPANY	
1939	NY TELEPHONE COMPANY	
1937	NY TELEPHONE COMPANY	

2023 GREEN ST

SOURCE: DIGITAL BUSINESS DIRECTORY

226 **FARAZANA JAVAID**...*RESIDENTIAL*
226 **FEIT KHOKHAR**...*RESIDENTIAL*
226 **FREDDY ESCARFULLER**...*RESIDENTIAL*
226 **JOHN BOLLINGER**...*RESIDENTIAL*
226 **LESLIE MARTINEZ**...*RESIDENTIAL*
229 **BENRA WINDOWS**...*WINDOWS*
229 **DUAL TILT WINDOW & DOOR MFG**...*WINDOWS*
230 **SWEETLAND CANDY WHOLESALE**...*CANDY & CONFECTIONERY-WHOLESALE*
234 **KSK AUTO INTL**...*AUTOMOBILE BODY-REPAIRING & PAINTING*
240 **HERCULES CORP**...*BOILERS-REPAIRING & CLEANING*
240 **HERCULES CORP**...*FURNACESREPAIRING & CLEANING*
240 **KEY AUTO CTR**...*AUTOMOBILE REPAIRING & SERVICE*
248 **CINER CHEM & REFIN CO**...*SMELTERS-REFINERS-PRECIOUS METALS (MFRS)*
248 **CN ENVIRONMENTAL**...*ENVIRONMENTAL & ECOLOGICAL SERVICES*
252 **JENS RASMUSSEN**...*RESIDENTIAL*
252 **KINGSLAND PRINTING**...*PRINTERS (MFRS)*
252 **KINGSLAND PRINTING**...*COMMERCIAL PRINTING NEC (MFRS)*
252 **SOLVEIG KJOK**...*RESIDENTIAL*
252 **TOP CAT ELECTRIC INC**...*ELECTRIC CONTRACTORS*
259 **BROADWAY STAGES LTD**...*FILM STUDIO PRODUCTION FACILITIES*
259 **GLOBAL TISSUE HOLDING**...*HOLDING COMPANIES (NON-BANK)*
259 **MEDIALIGHT INC**...*DATA PROCESSING SOFTWARE*
269 **KIDZ HOUSE ENTERTAINMENT**...*STUDIO RENTAL*

2023 HURON ST

SOURCE: DIGITAL BUSINESS DIRECTORY

228 **GREENPOINTS PEST CONTROL CORP**...*PEST CONTROL*
234 **RITE WAY TIRE SVC**...*TIRE-DEALERS-RETAIL*
236 **BESS ADLER**...*RESIDENTIAL*
240 **WING GONG LAUNDRY INC**...*RECREATIONAL VEHICLE PARKS*
240 **WING GONG LAUNDRY INC**...*UNIFORM SUPPLY SERVICE*
240 **WING GONG LAUNDRY INC**...*LAUNDRIES*
240 **WING GONG LAUNDRY INC**...*LAUNDRIES-INDUSTRIAL & COMMERCIAL*
247 **R & Z METAL CORP**...*SCRAP METALS & IRON (WHLS)*
247 **R & Z METAL CORP**...*RECYCLING CENTERS (WHLS)*
249 **GRAND RENOVATIONS INC**...*HOME IMPROVEMENTS*
249 **GRAND RENOVATIONS INC**...*REMODELING & REPAIRING BLDG CONTRACTORS*
249 **HILLSIDE PLUMBING INC**...*PLUMBING CONTRACTORS*
249 **HILLSIDE PLUMBING INC**...*HEATING CONTRACTORS*
249 **J & B IRONWORKS INC**...*IRONWORK*
249 **J & J BRONZE & ALUMINUM**...*FOUNDRIES-STEEL (MFRS)*
249 **J B IRONWORKS INC**...*ORNAMENTAL METAL WORK (MFRS)*
249 **JOEL ESKIN**...*RESIDENTIAL*
249 **PENGUIN MAINTANCE**...*ELECTRIC CONTRACTORS*
249 **RAF CONSTRUCTION & DEV**...*CONSTRUCTION COMPANIES*
249 **REDLINE ELECTRIC INC**...*ELECTRIC CONTRACTORS*
254 **POLAND PLUMBING CO INC**...*MECHANICAL CONTRACTORS*
261 **JAYSE CRAFTY INC**...*NONCLASSIFIED ESTABLISHMENTS*
261 **Y CATS**...*CATERERS*
267 **U A CONSTRUCTION**...*CONSTRUCTION COMPANIES*
267 **U A CONSTRUCTION**...*GENERAL CONTRACTORS*
267 **U A CONSTRUCTION**...*FEDERAL GOVERNMENT CONTRACTORS*
267 **U A CONSTRUCTION**...*CONSTRUCTION MANAGEMENT*

226 **FARAZANA JAVAID**...*RESIDENTIAL*
226 **FEIT KHOKHAR**...*RESIDENTIAL*
226 **FREDDY ESCARFULLER**...*RESIDENTIAL*
226 **JOHN BOLLINGER**...*RESIDENTIAL*
229 **BENRA WINDOWS**...*WINDOWS*
229 **DUAL TILT WINDOW & DOOR MFG**...*WINDOWS*
230 **SWEETLAND CANDY WHOLESALE**...*CANDY & CONFECTIONERY-WHOLESALE*
234 **KSK AUTO INTL**...*AUTOMOBILE BODY-REPAIRING & PAINTING*
240 **HERCULES CORP**...*BOILERS-REPAIRING & CLEANING*
240 **HERCULES CORP**...*FURNACESREPAIRING & CLEANING*
240 **KEY AUTO CTR**...*AUTOMOBILE REPAIRING & SERVICE*
248 **CINER CHEM & REFIN CO**...*SMELTERS-REFINERS-PRECIOUS METALS (MFRS)*
248 **CN ENVIRONMENTAL**...*ENVIRONMENTAL & ECOLOGICAL SERVICES*
250 **SCOTT PRECIOUS METALS**...*SMELTERS-REFINERS-PRECIOUS METALS (MFRS)*
250 **SCOTT PRECIOUS METALS**...*GOLD SILVER & PLATINUMDEALERS*
252 **JENS RASMUSSEN**...*RESIDENTIAL*
252 **KINGSLAND PRINTING**...*PRINTERS (MFRS)*
252 **SOLVEIG KJOK**...*RESIDENTIAL*
252 **TOP CAT ELECTRIC INC**...*ELECTRIC CONTRACTORS*
252 **Y-CATS**...*CATERERS*
259 **BROADWAY STAGES LTD**...*FILM STUDIO PRODUCTION FACILITIES*
259 **MEDIALIGHT INC**...*NONCLASSIFIED ESTABLISHMENTS*
262 **ACHILLES CONSTRUCTION CO**...*BLACKSMITHS*
262 **ACHILLES CONSTRUCTION CO**...*IRONWORK*
262 **ACHILLES CONSTRUCTION CO**...*ORNAMENTAL METAL WORK (MFRS)*
262 **ACHILLES CONSTRUCTION CO**...*STEEL WORKS/BLAST FURNACES/ROLLING MLS*
262 **ACHILLES CONSTRUCTION CO**...*ABRASIVES (WHLS)*
269 **KIDZ HOUSE ENTERTAINMENT**...*STUDIO RENTAL*

228 **GREENPOINTS PEST CONTROL CORP**...*PEST CONTROL*
234 **RITE-WAY TIRE SVC**...*TIRE-DEALERS-RETAIL*
236 **BESS ADLER**...*RESIDENTIAL*
240 **WING GONG LAUNDRY INC**...*LAUNDRIES-INDUSTRIAL & COMMERCIAL*
240 **WING GONG LAUNDRY INC**...*UNIFORM SUPPLY SERVICE*
240 **WING GONG LAUNDRY INC**...*LAUNDRIES*
240 **WING GONG LAUNDRY INC**...*RECREATIONAL VEHICLE PARKS*
247 **G G SCRAP METALS**...*SCRAP METALS & IRON (WHLS)*
247 **R & Z METAL CORP**...*RECYCLING CENTERS (WHLS)*
247 **R & Z METAL CORP**...*SCRAP METALS & IRON (WHLS)*
249 **GRAND RENOVATIONS INC**...*HOME IMPROVEMENTS*
249 **GRAND RENOVATIONS INC**...*REMODELING & REPAIRING BLDG CONTRACTORS*
249 **HILLSIDE PLUMBING INC**...*PLUMBING CONTRACTORS*
249 **HILLSIDE PLUMBING INC**...*HEATING CONTRACTORS*
249 **J B IRONWORKS INC**...*ORNAMENTAL METAL WORK (MFRS)*
249 **J & B IRONWORKS INC**...*IRONWORK*
249 **J & J BRONZE & ALUMINUM**...*FOUNDRIES-STEEL (MFRS)*
249 **JOEL ESKIN**...*RESIDENTIAL*
249 **PENGUIN MAINTANCE**...*ELECTRIC CONTRACTORS*
249 **RAF CONSTRUCTION & DEV**...*CONSTRUCTION COMPANIES*
249 **REDLINE ELECTRIC INC**...*ELECTRIC CONTRACTORS*
254 **POLAND PLUMBING CO INC**...*MECHANICAL CONTRACTORS*
254 **PROJECTSPAN SERVICES**...*DISTRIBUTING SERVICE-CIRCULAR & SAMPLE*
261 **JAYSE CRAFTY INC**...*NONCLASSIFIED ESTABLISHMENTS*
261 **Y-CATS**...*CATERERS*
267 **U A CONSTRUCTION**...*GENERAL CONTRACTORS*
267 **U A CONSTRUCTION**...*CONSTRUCTION MANAGEMENT*
267 **U A CONSTRUCTION**...*CONSTRUCTION COMPANIES*
267 **U A CONSTRUCTION**...*FEDERAL GOVERNMENT CONTRACTORS*

2016 GREEN ST

SOURCE: DIGITAL BUSINESS DIRECTORY

226 **FARAZANA JAVAID**...*RESIDENTIAL*
226 **FEIT KHOKHAR**...*RESIDENTIAL*
226 **FREDDY ESCARFULLER**...*RESIDENTIAL*
226 **GOLEEL KHOKHAR**...*RESIDENTIAL*
226 **HAJI JAVAID**...*RESIDENTIAL*
226 **JOHN BOLLINGER**...*RESIDENTIAL*
226 **MINERVA ESCARFULLER**...*RESIDENTIAL*
226 **YASMEEN KHOKHAR**...*RESIDENTIAL*
229 **DUAL TILT WINDOW & DOOR MFG**...*WINDOWS*
230 **TOTAL ELECTRICAL CONSTR CO INC**...*FEDERAL GOVERNMENT CONTRACTORS*
240 **HERCULES CORP**...*BOILERS-REPAIRING & CLEANING*
240 **KEY AUTO CTR**...*AUTOMOBILE REPAIRING & SERVICE*
245 **EYE PRODUCTIONS INC**...*NONCLASSIFIED ESTABLISHMENTS*
248 **CINER CHEM & REFIN CO**...*SMELTERS-REFINERS-PRECIOUS METALS (MFRS)*
248 **CN ENVIRONMENTAL**...*ENVIRONMENTAL & ECOLOGICAL SERVICES*
250 **SCOTT PRECIOUS METALS**...*SMELTERS-REFINERS-PRECIOUS METALS (MFRS)*
252 **JENS RASMUSSEN**...*RESIDENTIAL*
252 **SOLVEIG KJOK**...*RESIDENTIAL*
252 **TOP CAT ELECTRIC INC**...*ELECTRIC CONTRACTORS*
259 **GLOBAL TISSUE HOLDING**...*HOLDING COMPANIES (NON-BANK)*
259 **MEDIALIGHT INC**...*NONCLASSIFIED ESTABLISHMENTS*
262 **ACHILLES CONSTRUCTION CO**...*IRONWORK*
262 **ACHILLES CONSTRUCTION CO**...*STEEL WORKS/BLAST FURNACES/ROLLING MLS*
269 **KIDZ HOUSE ENTERTAINMENT**...*STUDIO RENTAL*

2016 HURON ST

SOURCE: DIGITAL BUSINESS DIRECTORY

234 **RITE-WAY TIRE SVC**...*TIRE-DEALERS-RETAIL*
236 **BESS ADLER**...*RESIDENTIAL*
240 **WING GONG LAUNDRY INC**...*LAUNDRIES*
240 **WING GONG LAUNDRY INC**...*LAUNDRIES-INDUSTRIAL & COMMERCIAL*
247 **G G SALVAGE CORP**...*CLOTHING ACCESSORIES STORES*
247 **R & Z METAL CORP**...*SCRAP METALS & IRON (WHLS)*
249 **GRAND RENOVATIONS INC**...*REMODELING & REPAIRING BLDG CONTRACTORS*
249 **HILLSIDE PLUMBING INC**...*PLUMBING CONTRACTORS*
249 **J & B IRONWORKS INC**...*IRONWORK*
249 **J & J BRONZE & ALUMINUM**...*FOUNDRIES-STEEL (MFRS)*
249 **JOEL ESKIN**...*RESIDENTIAL*
249 **RAF CONSTRUCTION & DEV**...*CONSTRUCTION COMPANIES*
254 **K CONSTRUCTION**...*GENERAL CONTRACTORS*
254 **POLAND PLUMBING CO INC**...*MECHANICAL CONTRACTORS*
261 **Y-CATS**...*CATERERS*
267 **U A CONSTRUCTION**...*GENERAL CONTRACTORS*
267 **U A CONSTRUCTION**...*FEDERAL GOVERNMENT CONTRACTORS*

2011 GREEN ST

SOURCE: DIGITAL BUSINESS DIRECTORY

226 **DHARAM SINGH**...*RESIDENTIAL*
226 **FARAZANA JAVAID**...*RESIDENTIAL*
230 **GILSTON ELECTRICAL CONTRACT**...*RESEARCH & DEVELOPMENT IN BIOTECHNOLOGY*
230 **TOTAL ELECTRICAL CONSTR CO INC**...*ELECTRICAL CONTRS*
234 **KSK AUTO INTL**
240 **HERCULES CORP**...*PLUMBING & HVAC CONTRS*
240 **KEY AUTO CTR**...*GENERAL AUTOMOTIVE REPAIR*
248 **CINER CHEM & REFIN CO**...*PRIMARY SMELTING OF NONFERROUS METALS*
248 **CN ENVIRONMENTAL**...*RESEARCH & DEVELOPMENT IN BIOTECHNOLOGY*
250 **PRECIOUS SCOTT**...*RESIDENTIAL*
250 **RON DARLY**...*RESIDENTIAL*
250 **SCOTT PRECIOUS METALS**...*PRIMARY SMELTING OF NONFERROUS METALS*
252 **EDWARD RACKLEY**...*RESIDENTIAL*
252 **FILM SHOP LLC**
252 **MARK VALENTI**...*RESIDENTIAL*
252 **Y-CATS**...*CATERERS*
259 **BROADWAY STAGES LTD**
259 **GLOBAL TISSUE HOLDING**...*OFFICES OF OTHER HOLDING COMPANIES*
262 **ACHILLES CONSTRUCTION CO**...*FABRICATED STRUCTURAL METAL MFG*
262 **ENVIRONMENTAL LUMBER PRODUCTS**...*RESEARCH & DEVELOPMENT IN BIOTECHNOLOGY*
269 **ENVIPCO PICKUP & PROC SVC**...*INDUSTRIAL MACHINERY AND EQUIPMENT, NEC*
269 **KIDZ HOUSE ENTERTAINMENT**...*OTHER MOTION PICTURE & VIDEO INDUSTRIES*
269 **LUNA LIGHTING INC**...*ALL OTHER HOME FURNISHINGS STORES*

2011 HURON ST

SOURCE: DIGITAL BUSINESS DIRECTORY

234 **K PARR**...*RESIDENTIAL*
240 **GRANDCHILDS ENTERPRISES LTD**...*DRYCLEANING & LAUNDRY SVCS*
240 **WING GONG LAUNDRY INC**...*DRYCLEANING & LAUNDRY SVCS*
247 **R & Z METAL CORP**...*RECYCLABLE MATERIAL MERCHANT WHOLS*
249 **DAVID SCOTT**...*RESIDENTIAL*
249 **JAW CONSTRUCTION CORP**...*NEW SINGLE-FAMILY GENERAL CONTRS*
249 **NIKOLAS EDGE**...*RESIDENTIAL*
254 **K CONSTRUCTION**...*NEW SINGLE-FAMILY GENERAL CONTRS*
254 **POLAND PLUMBING CO INC**...*ELECTRICAL CONTRS*
262 **AUTOFEED MANUFACTURING INC**...*ALL OTHER MISC MFG*
267 **U A CONSTRUCTION**...*NEW SINGLE-FAMILY GENERAL CONTRS*

2008 GREEN ST

SOURCE: DIGITAL BUSINESS DIRECTORY

226 **CZESLAWA PONIATOWSKA**...*RESIDENTIAL*
226 **HAJI K JAVAID**...*RESIDENTIAL*
226 **MIAN REHMAN**...*RESIDENTIAL*
226 **MILAGROS VEGA**...*RESIDENTIAL*
226 **RONALD LOPEZ**...*RESIDENTIAL*
230 **GILSTON ELECTRICAL CONTRACT**...*ELECTRONIC RESEARCH & DEVELOPMENT*
230 **TOTAL ELECTRICAL CONSTR CO INC**...*ELECTRIC CONTRACTORS*
234 **KSK AUTO INTERNATIONAL**...*AUTO BODY REPAIR/PAINTING*
240 **KEY AUTO CENTER**...*GENERAL AUTO REPAIR*
240 **KEY AUTO CTR**...*AUTOMOBILE REPAIRING & SERVICE*
242 **S HELLERMAN INC**...*PROCESSES TEXTILE WASTE*
245 **FENIX AUTO BODY & TRANSMISSION**...*AUTO TRANSMISSION REPAIR*
247 **FERRONE CONTAINER SVC**...*GARBAGE COLLECTION*
248 **CINER CHEM & REFIN CO**...*SMELTERS & REFINERS-PRECIOUS METALS*
248 **CINER CHEM REFIN**...*RECOVERS & REFINES PRECIOUS METALS*
250 **PRECIOUS SCOTT METALS INC**...*WHOL SERVICE ESTABLISHMENT EQUIPMENT REFUSE SYSTEM PRIM*
250 **SCOTT PRECIOUS METALS**...*SMELTERS & REFINERS-PRECIOUS METALS*
252 **MARK VALENTI**...*RESIDENTIAL*
252 **TOM BILLS**...*RESIDENTIAL*
252 **TRIFFIN & JENS RASMUSSEN**...*RESIDENTIAL*
252 **Y-CATS**...*CATERERS*
262 **ACHILLES CONSTRUCTION CO**...*FABRICATED STRUCTURAL METAL (MFRS)*
262 **ACHILLES CONSTRUCTION CO INC**...*FABRICATOR OF STRUCTURAL STEEL*
262 **ENVIRONMENTAL LUMBER PRODUCTS**...*WHOL LUMBER/PLYWOOD/MILLWORK BUSINESS CONSULTING SERVIC*
262 **PARTY SHOOTERS**...*PHOTOGRAPHY*
269 **GEORGE L BIXBY**...*RESIDENTIAL*
269 **LUNA LIGHTING INC**...*ELECTRICAL CONTRACTOR MOTION PICTURE SERVICES*

2008 HURON ST

SOURCE: DIGITAL BUSINESS DIRECTORY

234 **KIMBERLY DUVAL**...*RESIDENTIAL*
234 **MATT DUCKLO**...*RESIDENTIAL*
234 **MELISSA BROWN**...*RESIDENTIAL*
236 **I ALLEN**...*RESIDENTIAL*
240 **PARTNERSHIP REALTY MANAGEMENT**...*NONRESIDENTIAL BUILDING OPERATOR APARTMENT BUILDING OPE*
240 **ROCKS & JEANS**...*COMMERCIAL LAUNDRY*
240 **WING GONG LAUNDRY**...*LAUNDRIES*
247 **R & Z METAL CORP**...*SCRAP METALS & IRON (WHOLESALE)*
249 **DAVID M SCOTT**...*RESIDENTIAL*
249 **DAVID SERVOS**...*RESIDENTIAL*
249 **GRAND RENOVATION INC**...*SINGLE-FAMILY HOUSE CONSTRUCTION*
249 **ROMAN SCOTT**...*RESIDENTIAL*
249 **TAMAKI MATSUZAKI**...*RESIDENTIAL*
249 **V & R EQUITIES LTD**...*REAL ESTATE HOLDING*
254 **K CONSTRUCTION**...*GENERAL CONTRACTORS*
254 **MJJO MECHANICAL CORP**...*PLUMBING/HEATING/AIR COND CONTRACTOR*
254 **POLAND PLUMBING CO INC**...*MECHANICAL CONTRACTORS*
262 **AUTOFEED MANUFACTURING INC**...*MANUFACTURERS*
267 **U A CONSTRUCTION**...*GENERAL CONTRACTORS*

2003 GREEN ST

SOURCE: DIGITAL BUSINESS DIRECTORY

226 **ADA BARBER**...*RESIDENTIAL*
226 **CZESLAWA PONIATOWSKA**...*RESIDENTIAL*
226 **MOHAMMED SAKHI**...*RESIDENTIAL*
226 **STEVE DEMERRTZIS**...*RESIDENTIAL*
230 **GILSTON ELECTRICAL CONTRACT**
240 **KEY AUTO CTR**...*ENGINE REPAIR*
242 **PROTOTYPE SPECIALISTS INC**...*METAL ROOFING AND ROOF DRAINAGE EQUIPMENT*
245 **FENEX AUTO BODY & TRANSMISSION**
247 **FERRONE CONTAINER SVC**...*REFUSE COLLECTION AND DISPOSAL SERVICES*
248 **C N ENVIRONMENTAL**
248 **CINER CHEM & REFIN CO**...*LEAD AND ZINC*
250 **SCOTT PRECIOUS METALS**...*LEAD AND ZINC*
252 **CINERGY PICTURES**
252 **M K COFFIN**...*RESIDENTIAL*
252 **THOMAS UMHOLTZ**...*RESIDENTIAL*
252 **TOM BILLS**...*RESIDENTIAL*
262 **ACHILLES CONSTRUCTION CO**
262 **ENVIRONMENTAL LUMBER PRODUCTS**
269 **LUNA LIGHTING INC**...*EDITING SERVICES, MOTION PICTURE PRODUCTION*
269 **TULLY CONSTRUCTION**

2003 HURON ST

SOURCE: DIGITAL BUSINESS DIRECTORY

236 **MIDI MANIA RECORDING**
240 **ROCKS & JEANS**
240 **WING GONG LAUNDRY**
247 **R & Z METAL CORP**
249 **ALL CAST PATTERN INC**
249 **J & J BRONZE & ALUMINUM**...*UTENSILS, CAST ALUMINUM*
249 **ROMAN SCOTT**...*RESIDENTIAL*
262 **AUTOFEED MANUFACTURING INC**...*FEATHERS AND FEATHER PRODUCTS*
262 **D PLYLEY**...*RESIDENTIAL*

2000 GREEN ST

SOURCE: DIGITAL BUSINESS DIRECTORY

226 **ADA BARBER**...*RESIDENTIAL*
226 **CZESLAWA PONIATOWSKA**...*RESIDENTIAL*
226 **MOHAMMED SAKHI**...*RESIDENTIAL*
227 **CLAVIER PIANO MARKETING**...*RECREATIONAL VEHICLE REPAIR SERVICES*
227 **SUPREME FINISHING & COATING**...*VIDEO AND AUDIO EQUIPMENT*
237 **LILLIE R PERRY**...*RESIDENTIAL*
240 **KEY AUTO CTR**...*ENGINE REPAIR*
242 **PROTOTYPE SPECIALISTS INC**...*METAL ROOFING AND ROOF DRAINAGE EQUIPMENT*
245 **FENEX AUTO BODY & TRANSMISSION**
247 **FERRONE CONTAINER SVC**...*REFUSE COLLECTION AND DISPOSAL SERVICES*
248 **C N ENVIRONMENTAL**
248 **CINER CHEM & REFIN CO**...*LEAD AND ZINC*
250 **SCOTT PRECIOUS METALS**...*LEAD AND ZINC*
252 **M K COFFIN**...*RESIDENTIAL*
252 **TOM BILLS**...*RESIDENTIAL*
262 **ACHILLES CONSTRUCTION CO**
262 **SEBRO PACKING CORP**
269 **LUNA LIGHTING INC**...*EDITING SERVICES, MOTION PICTURE PRODUCTION*
269 **TULLY CONSTRUCTION**

2000 HURON ST

SOURCE: DIGITAL BUSINESS DIRECTORY

236 **JACQUELINE ARRAGAO**...*RESIDENTIAL*
236 **JANELL OROURKE**...*RESIDENTIAL*
240 **ROCKS & JEANS**
240 **WING GONG LAUNDRY**
247 **GUNDEL METAL CO**
247 **R & Z METAL CORP**
249 **ALL CAST PATTERN INC**
249 **J & J BRONZE & ALUMINUM**...*UTENSILS, CAST ALUMINUM*
249 **SIGRID NUNEZ**...*RESIDENTIAL*
250 **PERFECT SHIRTS**
262 **AUTOFEED MANULACTURING INC**
262 **D PLYLEY**...*RESIDENTIAL*

1997 GREEN ST

SOURCE: COLE

213	MULTI TENANT RESIDENTIAL
214	TCHACL DMNSNS INC
214	TCHNCL DMNSNS TR
226	MULTI TENANT RESIDENTIAL
227	CLAVIER PIANO
227	SUPREME CTNG INC
230	FANCY WINDOWS & DRS
230	USA TH ENTRPRS
240	HERCULES CORP
240	KEY AUTO CENTER
242	PRITYP SPCISTS INC
247	FERONE MICHAEL
247	GREENE FREE REALTY
248	CA ENVIRONMENTAL
248	CINER CHEM & RFN CO
252	MULTI TENANT RESIDENTIAL
259	JDS DSPLY & DISTRO
262	ACHILS CAST CO INC
269	JUST PACKAGING INC
269	STAMFORD HYGNC CRP

1997 HURON ST

SOURCE: COLE

219	NP
234	NP
235	NP
236	MULTI TENANT RESIDENTIAL
240	ROCKS & JEANS
240	WING GONG LAUNDRY
240	WING GONG LNDRY
247	GUNDEL METI CO INC
247	R & Z METAL CORP
249	ALL CAST PTTRN INC
249	ALL J & J BRNZ CAST
249	J & J CASTINGSCORP
249	MULTI TENANT RESIDENTIAL
250	CLIOS SHRT PRS CRP
262	D PLYLEY
262	EUGENE CONSTAN

1994 GREEN ST

SOURCE: COLE

214	TECHNICAL DIMENSIONS
226	ADA BARBER
226	C PONATOWSKA
226	EUGENE TAPIA
227	SUPREME FINSHNG
230	FNCY WINDOWS&DOORS
234	EXECUTIVE AUTO BDY
240	HERCULES CORP
240	KEY AUTO CENTER
242	PROTOTYPE SPCLSTS
247	MICHAEL FERONE
248	C N ENVIRONMENTAL
248	CINER CHEMCL&REFNG
252	JEFFREY M CATALANO
252	M K COFFIN
252	TOM BILLS
259	J DS DISPLAY&DIST
259	JUST FLDNG CRTONS
262	ACHILLES CONST CO
269	HUDSON MKTG SVC
269	JUST PACKAGING INC
269	STAMFORD HYGIENIC

1994 HURON ST

SOURCE: COLE

216	BIBI PERSAUD
216	HITOSHI TOYODA
216	JOSE RODRIGUEZ
216	MUHAMMAD INAYAT
216	ROBERTO BRILLO
216	SILVIANO SANTOS
216	ZENON SANTOS
318	A&C EXCVTG&DEM
318	ART STUDIO CASTING
318	CLIOS SHIRT PRESS
318	D PILEY
318	DAHLIA JARRELL
318	DANIEL WALSH
318	GUNDEL METAL CO
318	J&J BRNZ&ALM CSTRG
318	JACQUELINE ARRAGAO
318	JAMEIL OROURKE
318	JAMINE GORDON
318	MICHAEL VAZQUEZ
318	NP
318	PABLO NARVAEZ
318	RBZ METAL CORP
318	SIGRID NUNEZ
318	WING GONG LAUNDRY
318	WNK AUTO COLLISION

1990 GREEN ST

SOURCE: COLE

214	TECHNEL DEMENSIONS
226	C PONIATOWSKA
226	MARTIN SCHNECK
227	COLIN HUNG
230	CONSCIENTIOUS ROOF
234	JOHN RHODES
240	HERCULES CORP
242	PROTOTYPE SPCLSTS
247	MICHAEL FERONE
248	CINERS CHEMCL&REFING
252	M X COLFIN
252	TOM BILLS
259	JUST FLDAG CRTONS
262	ACHILLES CONST CO
269	HUDSON MKTG SVC
269	JUST INDUSTRIES
269	JUST PACKAGING INC
269	STAMFORD HYGIENIC

1990 HURON ST

SOURCE: COLE

216	ROBERTO BRITO
216	ZENON SANTOS
234	ART STUDIO CASTING
235	NP
236	GADI BARAK
236	J GORDON
240	WING GONG INDRY
240	WING GONG LAUNDRY
247	GUNDEL METAL CO
247	R & Z METAL CORP
249	DANIEL WALSH
249	J & J BRAZ & ALM CSTNG
250	CHARLES WORLD INC
250	SINGS CRAFT INC
262	D PLYLEY
262	NASH METALWARE CO

1985 GREEN ST

SOURCE: COLE

0	MACMILLIAN BLOEDL
214	TECHNICAL DIMENSNS
226	M GDULA
230	CONSCIENTIOUS ROOF
240	HERCULES CORP
242	PROTOTYPE SPCLSTS
247	CINER CHEMCL&ROOFNG
252	DAVID KAPP
252	K SCOTT
252	TOM BILLS
259	JUST FLDNG CRTONS
262	ACHILLES CONST CO
269	JUST PACKAGING INC
273	NY RESTAURANT SUPP
273	STULMAN-EMRICK CO

1985 HURON ST

SOURCE: COLE

216	ALBERTO SANCHEZ
216	ALBERTO SANTOS
216	GERARDO MOLINA
235	NP
236	WELDIZE CORP WELDG
240	WING GONG LAUNDRY
246	F&F WRHSE&TRANSPTN
247	GUNDEL METAL CO
247	R&Z METAL CORP
249	J&J BRNZ&ALM CSTNG
249	JAMES M SANDLER
254	ANDONMATTEN SYSTEM
262	NASH METALWARE CO

1983 GREEN ST

SOURCE: COLE

214	TECHNICAL DIMENSNS
226	NP
230	METROTIN GOL MAME
234	HOYT TRANSPORTATN
240	AKS BOLLER SY INC
240	BANKS & UNDERWOOD CP
240	GI IRON WRKS & ST
240	HERCULES CORP
242	PRECISE ALL CORP
242	PRECISE PLASTICS
242	PROTOTYPE SPCIATS
247	CINER CHEMCL & REING
252	JONATHAN WATERS
252	MULTI TENANT RESIDENTIAL
259	JUST FLONG CRTONS
262	ACHILLES CONST CO
269	JUST PACKAGING INC
289	ON - SITE FUEL OI
289	ON - SITE PETR UNITD
289	STUFMAN - EMRICK CO
337	OAKLAND

1983 HURON ST

SOURCE: COLE

216	RENE TAYLOR
235	NP
236	WELDIZE CORP WELDG
240	WING GONG LAUNDRY
246	F & F TRUCKING CO INC
246	F & F WRHSE & TRANSPTN
247	R & Z METAL CORP
248	A S GOLDFARB
248	DAVID KAPP
248	J & J BRNZ & ALM CSING
262	NASH METALWARE CO

1979 GREEN ST

SOURCE: NY TELEPHONE COMPANY

214	TECHNICAL DIMENSIONS INC
226	NAZARIO CLARA
230	METROPOLITAN GENL MARINE WORKS INC
240	BANKS & UNDERWOOD CORP
242	PRECISE ALL CORP
242	PRECISE PLASTICS CORP
242	PROTOTYPE SPECIALISTS INC
245	CHAMBER TRANSPORT INC
247	CINER CHEMCL & REFINING CO INC
262	ACHILLES CONST CO INC
269	JUST PACKAGING INC
272	STULMAN-EMRICK LUMBER CO INC
273	REPUBLIC METALS CO
289	ON -SITE FUEL OIL INC

1979 HURON ST

SOURCE: NY TELEPHONE COMPANY

216	TOPPA MUHAMMAD B
236	WELDIZE CORP
240	BODIN BROS
240	WING GONG LNDRY
246	F & F WAREHSE & TRANSP CO
247	R & Z METAL CORP
254	APEX WASTEPAPER RECYCLING CO
262	NASH METALWARE CO INC

1975-76 GREEN ST

SOURCE: COLE

214	KING BEAR AUTO SV
214	KINGBEAR AUTO SV
214	POINT AUTO GLASS
226	MRS HELEN BRUDEREK
226	WALTER SAWICKI
234	IDE PROCESSES CORP
240	BANKS UNDERWOOD
242	PRECISE ALL CORP
244	BIG CHETESONS TRX
247	CINER CHEMCL&REFNG
262	ACHILLES CONST CO
262	L L SUMIN METL PRD
262	WASHINGTON STLEORD
289	PETROLEUM CONTR
289	REPUBLIC METALS CO
293	EXXON COMPANY USA

1975-76 HURON ST

SOURCE: COLE

216	A KHAMIS
216	GANGU BALKISHUN
216	J E RAMIREZ
216	MRS ANNA KANUCK
235	NP
236	WELDIZE CORP WELDG
240	BODIN BROS
240	WING GONG LAUNDRY
246	P&F WRHSE&TRANSPTN
247	REZ METAL CORP
254	APEX PAPER RCYCLNG

1970 GREEN ST

SOURCE: NY TELEPHONE COMPANY

214 POINT AUTO GLASS CO
226 APEN JOHN
226 BRUDEREK HELEN MRS
226 SAWICKI WALTER
230 BOLE LOU CARPET CARRIERS
230 KENMORE CARPT CORP WAREHSE
230 LOU BOLE CARPET CARRIERS
235 IDANA PCKGE DYING COINC
235 JAYMEE DYEING & FINISHING CO
240 BANKS & UNDERWOOD CORP
242 ERMER FRITZ B
242 FOCUS OPTICAL CORP
247 CINER CHEMCL & REFINING CO INC
247 CINER CHEMEL & REFINING CO INC
248 CHASE ROBERTS & CO VARNSH E
249 KRASILOSKY MICK MACHY MOVERS INC
249 KRASILOVSKY D & S
249 KRASILOVSKY DAVID B E
249 KRASILOVSKY MILTON INC MACHY MOVRS & RIGRS F
249 MAIN OFFICE
249 NIGHTS SUN & HOLIDYS NW HYD PK 516
249 NIGHTS SUN & HOLLDYS NW HYD PK 516
249 RIGGING DIV
249 WAREHSE
250 CENTRAL CASING CORP SAUSG CASINGS D8 E
250 CENTRAL CASING SALES CORP
250 HIGHT CASING CORP
250 HIGHT EQUIP & SUPLS CORP
250 LUFT CASING CORP SAUSG CASING
259 M & J DIE CO
262 ACHILLES CONST COINC
262 SUMIN LEO L METL PRODS E
262 WASHINGTON STEEL & ORDNANCE CO E
273 REPUBLIC METALS CO
289 PETROLEUM FOR CONTRACTORS

1970 HURON ST

SOURCE: NY TELEPHONE COMPANY

216 SANCHEZ MARIANO
236 WELDIZE CORP
240 BODIN BROS
240 WING GONG LNDRY
246 F&F WAREHSE&TRANSPTN CO
247 R&Z METAL CORP
249 DOSSERT MFG CORP
249 MARTIN CHAS A
249 WILMAR BRONZE FOUNDRY
250 MAGONE JOHN&SON
254 MIDTOWN SANITATION
258 LAMAS GABRIEL B
259 NASH METALWARE CO INC

1965 GREEN ST

SOURCE: NY TELEPHONE COMPANY

214 POINT AUTO GLASS CO
226 APEN JOHN
226 BRUDEREK HELEN MRS
226 DEMOTT EDWIN M
226 SAWICKL WALTER
230 KENMORE CARPT CORP WAREHS
234 KINGS CNTY PATTERN & MODEL WKS
235 CHWATT BROS INC SKEIN DYNG
235 CHWATT KIT GOODS DYEING CO INC
235 IDANA PCKGE DYING CO INC
242 ERMER FRITZ B
242 FOCUS OPTICAL CORP
247 CINER CHEMCL & REFINING CO INC
248 CHASE ROBERTS & CO VARNSH E
249 KRASILOSKY MICK MACHY MOVERS INC MAIN OFFICE
249 KRASILOVSKY DAVID B
249 KRASILOVSKY MILTON INC
249 MACHY MOVRS & RIGRS E
249 NIGHTS SUN HOLIDYS NW HYD PK 516
249 RIGGING DIR
249 RIGGING DIV NIGHTS SUN & HOLIDYS NW HYD PK 516
249 WARCHSE
250 CENTRAL CASING CORP SAUSG CASINGS D8
250 CENTRAL CASING SALES CORP
250 HIGHT CASING CORP
250 HIGHT EQUIP & SUPLS CORP
250 LUFT CASING CORP SAUSG CASING
259 M & J DIE CO
262 ACHILLES CONST CO INC
262 SUMIN LEO L METL PRODS
262 WASHINGTON STEEL & ORDNANCE CO
273 REPUBLIC METALS CO
275 PAK RITE FLEXIBLE PACKAGING CO
293 HUMBLE OIL & REFINING CO EASTERN ESCO REGION DIV NPR SHOP

1965 HURON ST

SOURCE: NY TELEPHONE COMPANY

216 VAZQUEZ MANUEL
233 SISKO BENJ
235 CRUZ DELFIN
235 CRUZ ELEANOR
235 FELICIANO SANTOS
236 WELDIZE CORP WELDNG Z0
240 BODIN BROS
240 WING GONG LAUNDRY
246 F & F WAREHSE & TRANSPTN CO
247 R & Z METAL CORP
249 DOSSERT MFG CORP ELECTRCL CONNECTORS
249 MARTIN CHAS A FNDRY
249 WILMAR BRONZE FOUNDRY
259 NASH METALWARE CO INC MFRS

1959 GREEN ST

SOURCE: NY TELEPHONE COMPANY

226	BRUDERER HELEN MRS
226	DEMOTT JUNE M
230	SPIEL CARPT SVCE
234	EAGLE ST LIGHTING EQUP CORP
234	KINGS CNTY PATTERN&MODEL WKS
235	CHWATT BROS INC
235	IDANA PCKGE DYING CO INC
240	METALEDGE MOULDING CORP
244	NATL PRETZEL CO INC
247	CINER CHEMCL&REFINING CO INC
248	CHASE VARNISH CO INC
248	EVER-NU MFG CO
248	GREENPOINT PAINT&VARNISH CORP
249	KRASILOVSKY MICK MACHY MOVRS&IRGRS
249	KRASILOVSKY MILTON INC
250	ATLAS CASING CORP
250	CENTRAL CASING CORP
250	LUFT CASLNG CORP
250	NENO CHEMCL CORP
252	SPERO FOOD PRODS CO
259	LANDERS PRNTNG&CUT OUT CO
259	LARSTAN PROCESSING CO INC
262	ACHILLES CONST CO INC
262	SUMLIN LEO L
262	WASHINGTON STEEL&ORDNANCE CO
269	DELTA ELECTRONICS INC
269	ELECTRONIC INDICATOR CORP
269	ROTATING COMPONENTS INC
275	PAK-RITE FLEXIBLE PACKAGING CO
778	DIXON JOHN

1959 HURON ST

SOURCE: NY TELEPHONE COMPANY

216	KANUCK ANNA MRS
233	CRANE WALTER G
233	KATKOWSKI ALEX
233	KRAKOWSKI PAUL
233	KRANZ ARTHUR W
233	ZARKEWICH JOHN V
235	LATIMER WM V
235	REILLY MICHL
235	ROSELL MANUEL J
236	WELDIZE CORP
240	BODIN BROS
240	WING GONG LAUNDRY
246	F&F TRUCKING CO
247	GREENPOINT METAL CO
247	PERLMAN SAM
249	DOSSERT MFG CORP
249	MARTIN CHAS A
249	WILMAR BRONZE FOUNDRY
254	MARONE JOHN&SON
254	MIDTOWN SANITATION
259	NASH METALWARE CO INC
262	CHEMICAL COMPOUNDING CO
262	HEPARIN INC
262	KOHN DANL N
262	KOHN&PECHNEICK
262	PROPEL CHEMCLS INC

1955 GREEN ST

SOURCE: NY TELEPHONE COMPANY

226 BRUDERCK HELEN MRS
230 LEXINGTON CARPET SVCE
234 KINGS CNTY PATTERN&MODEL WKS
234 SMITH MATTIE R MRS
235 MANHATAN YARN DYEING&BLEACHING WKS INC
240 METALEDGE MOULDING CORP
242 ERMER JWLRY MFG
242 Q&Q DIES&JIGS JWLRY FLNDNGS
242 Q&Q JWLRY FINDNGS
244 NATL PRETZEL CO INC
247 CINER CHEMCL&REFINING CO INC
248 CHASE ROBERTS&CO VARNSH
248 CHASE VARNISH CO INC
248 GREENPOINT PAINT&VARNISH CORP
248 SEALTEST PAINT&CHEMCL CO
249 CRATING DEPT
249 GARAGE
249 KRASILOVSKY DAVID&SAML TRUCKING INC
249 MAIN OFFICE
249 MILLWRIGHT DEPT
249 MOVING DEPT
249 NIGHTS SUNDAYS AND HOLIDAYS--
249 RIGGING DEPT
249 STORAGE DEPT
249 TRAFFIC DEPT
250 CENTRAL CASING CORP
250 LUFT CASING CORP
250 NENO CHEMCL CORP
252 SPERO FOOD PRODS CO
259 ACETATE BOX CORP
259 ALL-FLEX FOUNDATNS LTD
259 DELTA ELECTRONICS INC
259 ELECTRONIC INDICATOR CORP
259 LANDERS PRNTNG&CUT OUT CO
259 LARSTAN PROCESSING CO INC
259 ROTATING COMPONENTS INC
262 ACHILLES CONST CO INC
262 SUMIN LEC L METL PRODS
262 WASHINGTON STEEL&ORDNANCE CO
269 SEAL RITE CAULKING CO INC
269 SEAL RITE PAINT CO DIV OF SEAL RITE CAULKING CO INC
269 WALDMAN MILLS
273 REPUBLIC METALS CO
275 PAK-RITE FLEXIBLE PACKAGING CO
278 CAMEL LEAD COLOR&CHEMCL PRODS MFG CORP

1955 HURON ST

SOURCE: NY TELEPHONE COMPANY

216 KANUCK HELEN
216 KURECZKA MICHL
233 KATKOWSKI ALEX
233 KRANZ ARTHUR W
233 ZARKEWICZ JOHN W
235 BIELSKI HENRY N
235 KRAKOWSKI CHESTER A
235 RAPALSKI SYLVESTER J
235 ROSELL MANUEL J
236 WELDIZE CORP
240 BODIN BROS
240 WING GONG LAUNDRY
246 F&F TRUCKING CO
247 GREENPOINT METAL CO
247 PERLMAN SAM
249 DOSSERT MFG CORP
249 MARTIN CHAS A
249 WILMAR BRONZE FOUNDRY
259 NASH METALWARE CO INC
262 CHEMICAL COMPOUNDING CORP
262 HEPARIN INC
262 KOHN DANL N
262 KOHN EUGENE
262 KOHN&PECHENICK

1952 GREEN ST

SOURCE: NY TELEPHONE COMPANY

214 KULBITSKI PETER
215 MURACZEWSKI S
226 BRUDERER HELEN MRS
226 DE MOTT JOAN
226 WYSOCKI JOAN MRS
230 STERN ENGRNG CO
235 MANNAH YARN DYEING & BLEACHING
240 CRAWFORD & EDDY ARCH BRCH W1
240 EDDY & CRAWFORD ARCH BRICK
240 FOX ACCESSORIES CO
240 KINGS CNTY PATTERN&MODEL WKS
242 ERMER JWLRY MFG
242 Q&O DIES&JIGS JWLRY FLNDNGS
242 Q&Q JWLRY FLNDNGS
244 NATL PRETZEL CO OF SCRANTON PA
247 CINER CHEMCL&REFLNING CO INC
248 CHASE ROBERTS&CO
248 CHASE VARNISH CO INC
248 GREENPOINT PAINT & VARNISH CORP
250 CENTRAL CASING CORP
252 SPERO FOOD PRODS CO
253 BUCHMAN'S A SONS METAL&SALVAGE CORP
259 ACETATE BOX CORP
259 DELTA ELECTRONICS INC
259 ELECTRONIC INDICATOR CORP
259 LANDERS PRNTNG&CUTOUT CO
259 LARSTAN PROCESSING CO INC
259 TELVISN SUPL CO
262 ACHILLES CONSLT CO INC
262 ADVANCE CONTAINER CORP
262 ADVANCE CONTAINER CORP WAREHOUSE
262 SUMLIN LEO L METL PRODS CO
262 WASHINGTON STEEL&ORDNANCE CO
269 WALDMAN MILLS
273 REPUBLIC METALS CO
278 CAMEL LEAD COLOR&CHEMCL PRODS MFG CORP

1952 HURON ST

SOURCE: NY TELEPHONE COMPANY

216 KURECZKA MICHL
233 BIELSKI HENRY
233 EVANOSKY JOHN
233 RAPALSKI SYLVESTER
233 ZARKEWICZ JOHN
235 ROSELL MANUEL
236 WELDIZE CORP
238 BRINK ANN
238 MOHER THOS
240 BODIN BROS
240 WING GONG LAUNDRY
247 GREENPOINT METAL CO
247 PERLMAN SAM
249 DOSSERT MFG CORP
249 MARTIN CHAS
249 WILMAR BRONZE FOUNDRY
252 FERRARO COOPERAGE CO INC
254 BRUSHER PLASTICS MOLDING CORP
254 CHILO MFG CO
254 KIRSHENBAUM & SHERMAN
254 SHERMAN LEO
262 HEPARIN INC
262 KOHN & PECHENICK
262 KOHN DANL
262 KOHN EUGENE

1947 GREEN ST

SOURCE: NY TELEPHONE COMPANY

213	HALEY FRANCES MRS
234	KINGS CO PATTERN & MODEL WORKS
235	MANHATTAN YARN DYEING & BLEACHING WKS INC
240	CRAWFORD & EDDY ARCH BRICK
240	EDDY & CRAWFORD ARCH BRICK
240	FOX ACCESSORIES CO
242	Q& Q DIES & JIGS
244	MANUFACTURERS AID CO
246	CINER CHEMICAL & REFINING CO INC
248	CHASE ROBERTS & CO
248	CHASE VARNISH CO INC
248	GREENPOINT PAINT & VARNISH CORP
252	SPERO FOOD PRODS CO
253	A & M METAL SCRAP IRON & SALVAGE CO
253	BUCHMAN A I METALS & GENL MDSE
253	RUDNICK MORRIS
259	CHEMICAL PACKERS LABS
259	EMPIRE FRAMES
259	EVERGREEN LABS INC
259	U S COMMODITIES INC
263	ACHILLES CONST CO INC
263	SUMLIN LEO L METAL PRODS
273	REPUBLIC METALS CO
273	THOMSON CHEMICAL CO
278	CAMEL LEAD COLOR & CHEMICAL PRODS MFG CORP

1947 HURON ST

SOURCE: NY TELEPHONE COMPANY

202	KUNISKY JOHN
233	GAVRICK CATHERINE
236	MICHAELS CHARLIE
236	WELDIZE CORP
240	BODIN BROS
240	WING GONG LAUNDRY
245	IMPERIAL LAUNDRY MACHINERY CORP
245	KAHN FRANK J
245	KAHN LEO M
245	PARAMOUNT LAUNDRY MACHINERY CORP
245	TWINMATIC LAUNDRY MACHY CO
249	DOSSERT MFG CORP
249	MARTIN CHAS A
249	MIAMI BRONZE FOUNDRY
252	FERRARO COVERAGE CO INC
254	BALLOU SVC & INSTRUMENT CO INC
254	INTERIOR MARINE INC
256	CHEMICAL COMPOUNDING CORP
262	KOHN EUGENE

1945 GREEN ST

SOURCE: NY TELEPHONE COMPANY

213	HALEY FRANCES MRS
234	KINGS CO PATTERN & MODEL WORKS
235	MANHATTAN YARN DYEING & BLEACHING WKS INC
240	CRAWFORD & EDDY ARCH BRICK
240	EDDY & CRAWFORD ARCH BRICK
240	FOX ACCESSORIES CO
242	MASTERMIX PAINT & LACQUER CORP
246	CINER CHEMCL & REFINING CO INC
248	GREENPOINT PAINT & VARNISH CORP
252	CHEMICAL PACKERS LAB
252	SPERO FOOD PRODS CO
262	ACHILLES CONST CO INC
269	AMER POVAR CORP
273	REPUBLIC METALS CO
273	THOMSON CHEMCL CO
278	CAMEL LEAD COLOR & CHEMCL PRODS MFG CORP

1945 HURON ST

SOURCE: NY TELEPHONE COMPANY

202	SALECKI ALBERT
235	GARWICK CATHERINE
236	MICHAELS CHARLIE
236	WELDIZE CORP
240	WING GONG LAUNDRY
245	IMPERIAL LAUNDRY MACHINERY CORP
245	KAHN FRANK J
245	KAHN LEO M LAUNDRY MACHY
245	PARAMOUNT LAUNDRY MACHINERY CORP
245	TWINMATIC LAUNDRY MACHY CO
249	DOSSERT MFG CORP
249	MARTIN CHAS A
249	WILMAR BRONZE FOUNDRY
252	FERRARO COPPERAGE CO INC
254	BALLOU SVC & INSTRUMENT CO INC
254	INTERIOR MARINE INC
262	CHEMICAL COMPOUNDING CORP
280	BEAVER ENGNRNG & CONTG CO

1939 GREEN ST

SOURCE: NY TELEPHONE COMPANY

212	MARCINIAK FRANK A PLUMBR
234	KINGS CO PATTERN & MODEL WORKS
234	SPIGNER BROS IRON WKS
235	MANHATTAN DYE WORKS
235	MANHATTAN YARN DYEING & BLEACHING CO
240	CRAWFORD & EDDY
240	EDDY & CRAWFORD ARCH BRICK
240	FOX ACCESSORIES CO
242	QUEENS TEXTILE CO
246	CINER CHEMCL & REFINING CO
248	GREENPOINT PAINT & VARNISH CORP
250	MACHOVER S BAGS BURLAP
253	CONSTRUCTION MACHY SRVC
262	ACHILLES CONST CO INC
273	REPUBLIC METALS CORP
273	THOMSON CHEMICAL CO
275	GARGANI E & SONS INC
275	KELLY THOS F SCRAP IRON
278	CAMEL LEAD COLOR & CHEMEL PRODS MFG CORP

1939 HURON ST

SOURCE: NY TELEPHONE COMPANY

211	MITCHELL FELIX
236	MICHAELS CHARLIE
236	WELDIZE CORP
240	LILY LAUNDRY SERV INC
249	BUDD STORES INC
249	LINCOLN DYE WKS.
250	FERRARO COOPERAGE CO INC
254	WILMAR BRONZE FOUNDRY
262	CHEMICAL COMPOUNDING CORP
262	KOHN EUGENE
267	BKLYN SASHWEIGHT CO
267	METRO HOME APPLIANCE CO
280	BEAVER ENGNRNG & CONTG CO

1937 GREEN ST

SOURCE: NY TELEPHONE COMPANY

207	MALISZEWSKI EDW
212	MARCINIAK FRANK A
231	ACORN PATTERN & MODEL WKS
234	BULLOCK JOHN PATTERN & MODEL WKS
234	KINGS CO PATTERN & MODEL WORKS
234	SPIGNER BROS IRON WKS
235	MANHATTAN DYE WORKS
235	MANHATTAN YARN DYEING & BLEACHING CO
240	CRAWFORD & EDDY
240	FOX ACCESSORIES CO
248	GREENPOINT PAINT & VARNISH CORP
250	MACHOVER S
256	GLOBE PIPE & FITTING CO
273	REPUBLIC METALS CORP
273	THOMSON CHEMICAL CO
275	GARGANL E & SONS INC
286	FICK GEO H INC

1937 HURON ST

SOURCE: NY TELEPHONE COMPANY

211	WHITMAN JOHN H INC FUEL OLL
234	JEWTRAW WM JR
236	WELDIZE CORP
240	COHEN LOUIS LAUNDRY SERV
240	LILY LAUNDRY SERV INC
249	BUDD STORES INC
249	LINCOLN DYE WKS
250	FERRARO COOPERAGE CO INC
262	CHEMICAL COMPOUNDING CORP
262	KOHN EUGENE
262	MANDEL SERV INC
262	MANDEL VENTILATING CO
267	BKLYN SASHWEIGHT CO
267	METRO HOME APPLIANCE CO
280	BEAVER ENGNRNG & CONTG CO

Appendix 5 Database Search Results

DATABASE REPORT

Project Property:	*247 Huron Street, Brooklyn* *247 Huron Street* *Brooklyn NY 11222*
Project No:	*A712-BKNY*
Report Type:	*Database Report*
Order No:	*25010100008*
Requested by:	*Advanced Cleanup Technologies, Inc.*
Date Completed:	*January 2, 2025*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....9
Executive Summary: Site Report Summary - Surrounding Properties.....10
Executive Summary: Summary by Data Source.....55
Map.....107
Aerial.....110
Topographic Map.....111
Detail Report.....112
Unplottable Summary.....977
Unplottable Report.....979
Appendix: Database Descriptions.....996
Definitions.....1013

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:		*247 Huron Street, Brooklyn* *247 Huron Street Brooklyn NY 11222*
Project No:		*A712-BKNY*
Coordinates:		
	Latitude:	*40.73359024*
	Longitude:	*-73.95126475*
	UTM Northing:	*4,509,712.62*
	UTM Easting:	*588,555.16*
	UTM Zone:	*UTM Zone 18T*
Elevation:		*12 FT*

Order Information:

Order No:	*25010100008*
Date Requested:	*January 1, 2025*
Requested by:	*Advanced Cleanup Technologies, Inc.*
Report Type:	*Database Report*

Historicals/Products:

Aerial Photographs	*Historical Aerials (with Project Boundaries)*
City Directory Search	*CD - 1 Street Search*
ERIS Xplorer	*ERIS Xplorer*
Excel Add-On	*Excel Add-On*
Fire Insurance Maps	*US Fire Insurance Maps*
Physical Setting Report (PSR)	*Physical Setting Report (PSR)*
Product Summary	*Product Summary for Aerials, FIMs & Topos*
Vapor Screening Tool	*Vapor Screening Tool*

Executive Summary: Report Summary

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
Standard Environmental Records								
Federal								
NPL	Y	1	0	0	**1**	**1**	0	**2**
PROPOSED NPL	Y	1	0	0	0	0	0	0
DELETED NPL	Y	0.5	0	0	0	0	-	0
SEMS	Y	0.5	0	**1**	0	0	-	**1**
ODI	Y	0.5	0	0	0	0	-	0
SEMS ARCHIVE	Y	0.5	0	0	**1**	**3**	-	**4**
CERCLIS	Y	0.5	0	**1**	**1**	**2**	-	**4**
IODI	Y	0.5	0	0	0	0	-	0
CERCLIS NFRAP	Y	0.5	0	0	0	**2**	-	**2**
CERCLIS LIENS	Y	PO	0	-	-	-	-	0
RCRA CORRACTS	Y	1	0	0	0	0	**4**	**4**
RCRA TSD	Y	0.5	0	0	0	0	-	0
RCRA LQG	Y	0.25	0	**6**	**6**	-	-	**12**
RCRA SQG	Y	0.25	**1**	**2**	**2**	-	-	**5**
RCRA VSQG	Y	0.25	0	**3**	**1**	-	-	**4**
RCRA NON GEN	Y	0.25	0	**21**	**41**	-	-	**62**
RCRA CONTROLS	Y	0.5	0	0	0	0	-	0
FED ENG	Y	0.5	0	0	0	0	-	0
FED INST	Y	0.5	0	0	0	0	-	0
LUCIS	Y	0.5	0	0	0	0	-	0
NPL IC	Y	0.5	0	0	0	0	-	0
ERNS 1982 TO 1986	Y	PO	0	-	-	-	-	0
ERNS 1987 TO 1989	Y	PO	0	-	-	-	-	0
ERNS	Y	PO	0	-	-	-	-	0
FED BROWNFIELDS	Y	0.5	0	0	0	0	-	0
FEMA UST	Y	0.25	0	0	0	-	-	0
FRP	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
DELISTED FRP	Y	0.25	0	0	0	-	-	0
HIST GAS STATIONS	Y	0.25	0	**1**	0	-	-	**1**
REFN	Y	0.25	0	0	0	-	-	0
BULK TERMINAL	Y	0.25	0	0	**1**	-	-	**1**
SEMS LIEN	Y	PO	0	-	-	-	-	0
SUPERFUND ROD	Y	1	0	0	0	0	**1**	**1**
DOE FUSRAP	Y	1	0	0	0	0	0	0
State								
SHWS	Y	1	0	**1**	0	**8**	**22**	**31**
DELISTED SHWS	Y	1	0	0	0	0	0	0
HSWDS	Y	1	0	0	0	**2**	**10**	**12**
VAPOR	Y	1	0	0	0	0	**1**	**1**
SWF/LF	Y	0.5	0	**4**	**1**	**17**	-	**22**
LANDFILL INACTIVE	Y	0.5	0	0	0	0	-	0
WASTE TIRE	Y	0.5	0	0	0	0	-	0
OER CLEANUP	Y	0.25	0	0	**13**	-	-	**13**
RECYCLING	Y	0.5	0	**1**	0	**3**	-	**4**
LST	Y	0.5	0	**16**	**2**	**28**	-	**46**
DELISTED LST	Y	0.5	0	0	0	0	-	0
UST	Y	0.25	0	**11**	**8**	-	-	**19**
AST	Y	0.25	0	**10**	**12**	-	-	**22**
TANKS	Y	0.25	0	0	0	-	-	0
MOSF	Y	0.5	0	**1**	0	**5**	-	**6**
CBS	Y	0.25	0	**1**	0	-	-	**1**
DELISTED TANKS	Y	0.25	0	0	0	-	-	0
DELISTED COUNTY	Y	0.25	0	0	0	-	-	0
ENG	Y	0.5	0	0	0	**2**	-	**2**
INST	Y	0.5	0	0	0	**2**	-	**2**
VCP	Y	0.5	0	0	0	**1**	-	**1**
ERP	Y	0.5	0	0	0	0	-	0
BROWNFIELDS	Y	0.5	0	**1**	**2**	**8**	-	**11**
Tribal								
INDIAN LUST	Y	0.5	0	0	0	0	-	0
INDIAN UST	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
DELISTED INDIAN LST	Y	0.5	0	0	0	0	-	0
DELISTED INDIAN UST	Y	0.25	0	0	0	-	-	0
County	***No County databases were selected to be included in the search.***							
Additional Environmental Records								
Federal								
PFAS GHG	Y	0.5	0	0	0	0	-	0
OSC RESPONSE	Y	0.125	0	**1**	-	-	-	**1**
FINDS/FRS	Y	PO	**1**	**5**	-	-	-	**6**
TRIS	Y	PO	**1**	-	-	-	-	**1**
PFAS NPL	Y	0.5	0	0	0	0	-	0
PFAS FED SITES	Y	0.5	0	0	0	0	-	0
PFAS SSEHRI	Y	0.5	0	0	0	0	-	0
PFAS ERNS	Y	0.5	0	0	0	0	-	0
PFAS NPDES	Y	0.5	0	0	0	0	-	0
PFAS TRI	Y	0.5	0	0	0	0	-	0
PFAS WATER	Y	0.5	0	0	0	0	-	0
PFAS TSCA	Y	0.5	0	0	0	0	-	0
PFAS E-MANIFEST	Y	0.5	0	0	0	0	-	0
PFAS IND	Y	0.5	0	**2**	**4**	**9**	-	**15**
HMIRS	Y	0.125	0	0	-	-	-	0
NCDL	Y	0.125	0	0	-	-	-	0
TSCA	Y	0.125	0	0	-	-	-	0
HIST TSCA	Y	0.125	0	0	-	-	-	0
FTTS ADMIN	Y	PO	0	-	-	-	-	0
FTTS INSP	Y	PO	0	-	-	-	-	0
PRP	Y	PO	0	-	-	-	-	0
SCRD DRYCLEANER	Y	0.5	0	0	0	0	-	0
ICIS	Y	PO	**1**	**2**	-	-	-	**3**
FED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED FED DRY	Y	0.25	0	0	0	-	-	0
FUDS	Y	1	0	0	0	0	**1**	**1**
FUDS MRS	Y	1	0	0	0	0	0	0
FORMER NIKE	Y	1	0	0	0	0	0	0
PIPELINE INCIDENT	Y	PO	0	-	-	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
MLTS	Y	PO	0	-	-	-	-	0
HIST MLTS	Y	PO	0	-	-	-	-	0
MINES	Y	0.25	0	0	0	-	-	0
SMCRA	Y	1	0	0	0	0	0	0
MRDS	Y	1	0	0	0	0	0	0
LM SITES	Y	1	0	0	0	0	0	0
ALT FUELS	Y	0.25	0	0	0	-	-	0
CONSENT DECREES	Y	0.25	0	0	0	-	-	0
AFS	Y	PO	0	**1**	-	-	-	**1**
SSTS	Y	0.25	0	0	0	-	-	0
PCBT	Y	0.5	0	0	0	0	-	0
PCB	Y	0.5	0	0	0	0	-	0
POWER PLANTS	Y	0.125	0	0	-	-	-	0
State								
UIC	Y	PO	0	-	-	-	-	0
COOLING TOWERS NYC	Y	0.125	0	0	-	-	-	0
MGP	Y	1	0	0	0	0	**3**	**3**
NY SPILLS	Y	0.125	**3**	**187**	-	-	-	**190**
PFAS CONTAM	Y	0.5	0	0	**1**	0	-	**1**
PFAS	Y	0.5	0	0	0	**2**	-	**2**
PFAS LANDFILL	Y	0.5	0	0	0	0	-	0
DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED DRYCLEANERS	Y	0.25	0	**1**	**1**	-	-	**2**
NY MANIFEST	Y	0.125	0	**4**	-	-	-	**4**
REC MANIFEST	Y	0.25	0	**1**	0	-	-	**1**
GEN MANIFEST	Y	0.125	**2**	**38**	-	-	-	**40**
E DESIGNATION	Y	0.125	0	0	-	-	-	0
COOLING TOWERS	Y	0.125	0	0	-	-	-	0
TIER 2	Y	0.125	0	**10**	-	-	-	**10**
PROJECTS	Y	0.25	0	0	0	-	-	0
AIR PERMITS	Y	0.25	0	**1**	**1**	-	-	**2**
LIEN	Y	PO	0	-	-	-	-	0
Tribal	***No Tribal additional environmental record sources available for this State.***							

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
County	*No County additional environmental record sources available for this State.*							
Total:			*9*	*334*	*99*	*95*	*42*	*579*

**** PO – Property Only***
**** 'Property and adjoining properties' database search radii are set at 0.25 miles.***

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	NY SPILLS	RZ METAL CORP	247 HURON ST BROOKLYN NY 11222 ***Spill No | Close Date:*** *0011791 | 12/29/2005 12:00:00 AM*	SSW	0.00 / 0.00	0	112
1	NY SPILLS	MINERAL OIL SPILL	241-247 HURON STREET BROOKLYN NY ***Spill No | Close Date:*** *1403242 | 08/26/2014 12:00:00 AM*	SSW	0.00 / 0.00	0	113
2	RCRA SQG	J&J BRONZE & ALUMINUM CASTING CORP	249 HURON ST BROOKLYN NY 11222 ***EPA Handler ID:*** *NYR000154658*	SSW	0.00 / 0.00	0	114
2	NY SPILLS	APRT	249 HURON STREET BROOKLYN NY ***Spill No | Close Date:*** *0710964 | 01/31/2008 12:00:00 AM*	SSW	0.00 / 0.00	0	115
2	FINDS/FRS	J & J BRONZE & ALUMINUM CASTING CORP	249 HURON STREET BROOKLYN NY 11222-1801 ***Registry ID:*** *110000323383*	SSW	0.00 / 0.00	0	116
2	ICIS	J & J BRONZE & ALUMINUM CASTING CORP	249 HURON STREET BROOKLYN NY 11222-1801 ***Registry ID:*** *110000323383*	SSW	0.00 / 0.00	0	117
2	GEN MANIFEST	J&J BRONZE & ALUMINUM CASTING CORP	249 HURON ST BROOKLYN NY 11222	SSW	0.00 / 0.00	0	117
2	GEN MANIFEST	J & J BRONZE & ALUMINUM CASTING	249 HURON ST BROOKLYN NY 11222	SSW	0.00 / 0.00	0	117
2	TRIS	J & J BRONZE & ALUMINUM CASTING CORP	249 HURON ST BROOKLYN NY 11222	SSW	0.00 / 0.00	0	118

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
3	FINDS/FRS	MC GUINNESS MANAGEMENT CORP	231 HURON STREET BROOKLYN NY 11222 ***Registry ID:*** 110019433264	W	0.01 / 37.86	0	122
4	AST	KEYSTONE AUTO REPAIR INC DBA KEY AUTO CENTER	240 GREEN STREET Brooklyn NY 11222 ***Site ID | Site Status:*** 28976 | Unregulated/Closed	N	0.01 / 48.00	0	122
5	FINDS/FRS	CON EDISON - MANHOLE 8545	234 GREEN ST BROOKLYN NY 11222 ***Registry ID:*** 110055934850	NW	0.01 / 48.43	0	126
5	RCRA LQG	CON EDISON - MANHOLE 8545	234 GREEN ST BROOKLYN NY 11222 ***EPA Handler ID | Recycler Activity?:*** NYP004296745 | NO	NW	0.01 / 48.43	0	126
5	GEN MANIFEST	CON EDISON	234 GREEN ST BROOKLYN NY 11222	NW	0.01 / 48.43	0	128
6	RCRA NON GEN	C C BODY SHOP	230 GREEN ST BROOKLYN NY 11222 ***EPA Handler ID | Recycler Activity?:*** NYR000046607 | NO	NW	0.01 / 49.28	0	128
6	FINDS/FRS	C C BODY SHOP	230 GREEN ST BROOKLYN NY 11222 ***Registry ID:*** 110004538395	NW	0.01 / 49.28	0	130
7	FINDS/FRS	AJB BUILDERS & CO.	251 HURON ST BROOKLYN NY 11222 ***Registry ID:*** 110055291170	E	0.01 / 49.35	0	131
8	FINDS/FRS	CINER CHEMICAL & REFINING CO	246 GREEN ST BROOKLYN NY 11222 ***Registry ID:*** 110046098085	NE	0.01 / 66.25	0	132
8	ICIS	CINER CHEMICAL & REFINING CO	246 GREEN ST BROOKLYN NY 11222 ***Registry ID:*** 110046098085	NE	0.01 / 66.25	0	132
8	ICIS	CINER CHEMICAL & REFINING CO	246 GREEN ST BROOKLYN NY 11222 ***Registry ID:*** 110046098085	NE	0.01 / 66.25	0	132
8	TIER 2	Ciner Chemical& Refining Co	248 Green Street Brooklyn NY 11222	NE	0.01 / 66.25	0	132

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
8	AFS	CINER CHEMICAL & REFINING CO	246 GREEN ST BROOKLYN NY 11222	NE	0.01 / 66.25	0	133
9	NY SPILLS	PRIVATE RESIDENCE	298 GREEN AVE BROOKLYN NY ***Spill No* | *Close Date:*** 1206492 | 05/21/2014 12:00:00 AM	NNE	0.02 / 104.52	0	134
10	UST	WING GONG LAUNDRY INC	240-244 HURON ST 240 HURON ST BROOKLYN NY 11222 ***Site ID* | *Site Status:*** 3892 | Inactive	SSE	0.02 / 113.02	0	135
10	UST	WING GONG LAUNDRY	240 HURON STREET Brooklyn NY 11222 ***Site ID* | *Site Status:*** 22705 | Unregulated/Closed	SSE	0.02 / 113.02	0	137
10	DELISTED DRYCLEANERS	WING GONG LAUNDRY/ROCKS & JEANS	240/250 HURON STREET BROOKLYN NY 11222	SSE	0.02 / 113.02	0	139
11	RCRA LQG	CON EDISON - SERVICE BOX 7507	250 HURON ST BROOKLYN NY 11222 ***EPA Handler ID* | *Recycler Activity?:*** NYP005050018 | NO	SE	0.02 / 115.13	0	140
11	NY MANIFEST	CON EDISON - SERVICE BOX 7507	250 HURON ST BROOKLYN NY 11222	SE	0.02 / 115.13	0	141
12	GEN MANIFEST	CON EDISON	292 GREENE ST SB11660 BROOKLYN NY 11201	N	0.02 / 116.27	0	141
13	RCRA NON GEN	MCGUINNESS MANAGEMENT	330 MCGUINNESS BLVD BROOKLYN NY 11222-1820 ***EPA Handler ID* | *Recycler Activity?:*** NYR000141853 | NO	W	0.02 / 117.25	0	141
13	GEN MANIFEST	MCGUINNESS MANAGEMENT	330 MCGUINNESS BLVD BROOKLYN NY 11222	W	0.02 / 117.25	0	144
14	AST	S.C. TRUCK & AUTO REPAIR INC.	314 MCGUINESS BOULEVARD Brooklyn NY 11222 ***Site ID* | *Site Status:*** 29957 | Active	SW	0.02 / 126.67	0	146
15	GEN MANIFEST	CON EDISON	322 GREEN ST STRUCTURE # 11666 BROOKLYN NY	NE	0.03 / 133.09	-1	150

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
15	GEN MANIFEST	CON EDISON	322 GREEN AVE SB 11666 BROOKLYN NY 11238	NE	0.03 / 133.09	-1	151
15	GEN MANIFEST	CON EDISON	322 GREEN ST STRUCTURE # 11666 BROOKLYN NY	NE	0.03 / 133.09	-1	151
16	NY SPILLS	VACANT BUILDING	311 GREEN AVE. BROOKLYN NY ***Spill No* | *Close Date:*** 0707140 | 11/19/2007 12:00:00 AM	NNE	0.03 / 138.64	-1	151
16	NY SPILLS	WATER MAIN BREAK	311 GREEN AVENUE BROOKLYN NY ***Spill No* | *Close Date:*** 0707143 | 09/28/2007 12:00:00 AM	NNE	0.03 / 138.64	-1	153
17	HIST GAS STATIONS	Crew Levick Co.	267 Green Ave Brooklyn NY	NNW	0.03 / 146.61	0	153
18	NY SPILLS	CONSTRUCTION SITE	333 GREEN AVE BROOKLYN NY ***Spill No* | *Close Date:*** 0611233 | 04/24/2007 12:00:00 AM	NE	0.03 / 169.10	-1	154
19	RCRA LQG	CON EDISON - MANHOLE 752	S/S HURON ST 25` E/O MCGUINESS BLVD BROOKLYN NY 11205 ***EPA Handler ID* | *Recycler Activity?:*** NYP004151916 | NO	WSW	0.03 / 177.40	1	155
19	NY SPILLS	Spill Number 0004605	MCGUINESS AND HURON AV BROOKLYN NY ***Spill No* | *Close Date:*** 0004605 | 12/28/2000 12:00:00 AM	WSW	0.03 / 177.40	1	156
19	NY SPILLS	CON ED MANHOLE 4313	MC GUINNESS & HURON ST BROOKLYN NY ***Spill No* | *Close Date:*** 9307736 | 05/26/1995 12:00:00 AM	WSW	0.03 / 177.40	1	157
19	NY MANIFEST	CON EDISON - TRANSFORMER MANHOLE 752	MCGUINESS BLVD & HURON ST BROOKLYN NY 11222	WSW	0.03 / 177.40	1	158
19	GEN MANIFEST	CON EDISON	SEC HURON & MCGUINNESS MH 4313 BROOKLYN NY 11222	WSW	0.03 / 177.40	1	158
19	GEN MANIFEST	consoliated edison	S/S HURON ST 25` E/O MCGUINESS BLVD BROOKLYN NY 11205	WSW	0.03 / 177.40	1	158
20	BROWNFIELDS	262 Green	262-276 Green Street and 263 Huron Street Brooklyn NY 11211	ENE	0.03 / 182.41	-1	159

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
21	RCRA NON GEN	CINER CHEMICAL & REFINING CO INC	247 GREEN ST BROOKLYN NY 11222	NNE	0.04 / 206.80	-1	162
			***EPA Handler ID	Recycler Activity?:*** NYD046821070 | NO			
21	UST	247-251 GREEN STREET	247-251 GREEN STREET BROOKLYN NY 11222	NNE	0.04 / 206.80	-1	164
			***Site ID	Site Status:*** 29370 | Unregulated/Closed			
21	LST	FORMER WASTE TRANSFER STATION	247-251 GREEN ST BROOKLYN NY	NNE	0.04 / 206.80	-1	166
			***Spill No	Close Date:*** 0112015 | 01/27/2005 12:00:00 AM			
21	REC MANIFEST	CINER CHEMICAL REFINING CO INC	247 GREEN ST BROOKLYN NY 11222	NNE	0.04 / 206.80	-1	167
21	SWF/LF	MICHAEL FERONE (BRICK) CO.	247 GREENE ST Brooklyn NY 11222	NNE	0.04 / 206.80	-1	168
22	CERCLIS	FORTUNE METALS INC.	239 INDIA STREET BROOKLYN NY 11222	ESE	0.04 / 208.00	0	169
			Site EPA ID: NYR000170555				
22	NY SPILLS	262 HURON ST	262 HURON ST BROOKLYN NY	ESE	0.04 / 208.00	0	169
			***Spill No	Close Date:*** 9704312 | 07/21/1998 12:00:00 AM			
23	RCRA VSQG	FORTUNE METAL INC	239 INDIA ST BROOKLYN NY 11222	ESE	0.04 / 208.03	0	170
			***EPA Handler ID	Recycler Activity?:*** NYR000170555 | NO			
23	RCRA LQG	CON EDISON - SERVICE BOX 7508	256 HURON ST BROOKLYN NY 11222	ESE	0.04 / 208.03	0	172
			***EPA Handler ID	Recycler Activity?:*** NYP005050042 | NO			
23	NY MANIFEST	CON EDISON - SERVICE BOX 7508	256 HURON ST BROOKLYN NY 11222	ESE	0.04 / 208.03	0	173
23	GEN MANIFEST	FORTUNE METAL INC	239 INDIA STREET BROOKLYN NY 11222	ESE	0.04 / 208.03	0	173
23	SWF/LF	Fortune Metal	239 India Street Brooklyn NY 11222	ESE	0.04 / 208.03	0	173
23	SWF/LF	Fortune Metal	239 India Street Brooklyn NY 11222	ESE	0.04 / 208.03	0	177

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
23	RECYCLING	Fortune Metal	239 India Street Brooklyn NY 11222	ESE	0.04 / 208.03	0	178
23	OSC RESPONSE	Fortune Metals Inc.	239 India Street Brooklyn NY	ESE	0.04 / 208.03	0	178
24	NY SPILLS	217 INDIA STREET	217 INDIA STREET BROOKLYN NY ***Spill No* | *Close Date:*** 0007775 | 11/14/2000 12:00:00 AM	S	0.04 / 214.73	0	178
24	NY SPILLS	COMMERCIAL	217 INDIA ST BROOKLYN NY ***Spill No* | *Close Date:*** 2205227 | 09/15/2022 12:00:00 AM	S	0.04 / 214.73	0	179
25	AST	DC TRUCK & AUTO REPAIR SHOP INC.	219 INDIA STREET BROOKLYN NY 11222 ***Site ID* | *Site Status:*** 373006 | Active	SSE	0.04 / 215.20	0	180
26	NY SPILLS	HALF PINT OIL IN MAN HOLE 71471	GREEN STREET AND MCGUINNESS BROOKLYN NY ***Spill No* | *Close Date:*** 0704289 | 08/20/2007 10:23:00 AM	WNW	0.04 / 221.55	0	183
26	NY SPILLS	ROADWAY	GREENE ST MCGINNIS BLVD BROOKLYN NY ***Spill No* | *Close Date:*** 1607557 | 11/03/2016 12:00:00 AM	WNW	0.04 / 221.55	0	184
26	NY SPILLS	UNDERGROUND VAULT	MCGUINESS BLVD AND GREEN ST BROOKLYN NY ***Spill No* | *Close Date:*** 1812191 | 04/03/2019 12:00:00 AM	WNW	0.04 / 221.55	0	185
27	SEMS	FORTUNE METALS INC.	239 INDIA STREET BROOKLYN NY 11222 ***EPA ID:*** NYR000170555	ESE	0.04 / 226.31	0	186
28	GEN MANIFEST	CON EDISON	359 GREENE ST TM 808 BROOKLYN NY 11201	NE	0.04 / 231.42	-1	187
29	AST	TWO GUYS AUTO GLASS, INC.	302 MCGUINNESS BOULEVARD BROOKLYN NY 11222 ***Site ID* | *Site Status:*** 374288 | Active	SSW	0.05 / 241.37	1	187
30	RCRA VSQG	PULASKI SVC STA	321 MCGUINESS BLVD BROOKLYN NY 11222-1817 ***EPA Handler ID* | *Recycler Activity?:*** NYD095772919 | NO	W	0.05 / 250.88	1	192
30	UST	MJB SERVICE STATION INC	321 MCGUINNESS BOULEVARD Brooklyn NY 11222 ***Site ID* | *Site Status:*** 22673 | Active	W	0.05 / 250.88	1	194

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
30	NY SPILLS	PULASKI SERVICE STATION	321 MCGUINNESS BOULEVARD Brooklyn NY 11222 ***Spill No* | *Close Date:*** 9908882 | 04/05/2012 12:00:00 AM	W	0.05 / 250.88	1	204
30	NY SPILLS	SIDEWALK	321 MCGUINESS BLVD BROOKLYN NY ***Spill No* | *Close Date:*** 1609775 | 01/24/2017 12:00:00 AM	W	0.05 / 250.88	1	207
30	GEN MANIFEST	MJB SERVICE STATION (PULASKI SVC STA)	321 MCGUINESS BLVD BROOKLYN NY 11222	W	0.05 / 250.88	1	208
30	NY SPILLS	AIR	321 MCGUINNESS BLVD BROOKLYN NY ***Spill No* | *Close Date:*** 1812673 | 03/27/2019 12:00:00 AM	W	0.05 / 250.88	1	208
31	RCRA NON GEN	CON EDISON	237 INDIA ST BROOKLYN NY 11222 ***EPA Handler ID* | *Recycler Activity?:*** NYP004804605 | NO	ESE	0.05 / 269.11	0	209
31	RCRA NON GEN	CON EDISON	237 INDIA ST BROOKLYN NY 11222 ***EPA Handler ID* | *Recycler Activity?:*** NYP004798435 | NO	ESE	0.05 / 269.11	0	210
31	GEN MANIFEST	CON EDISON	237 INDIA ST SB 7530 BROOKLYN NY	ESE	0.05 / 269.11	0	211
31	GEN MANIFEST	CON EDISON	237 INDIA ST SB 7530 BRONX NY	ESE	0.05 / 269.11	0	212
32	SWF/LF	PRONTO DEMOLITION CORP.	73 PROVOST ST Brooklyn NY 11222	E	0.05 / 274.97	-1	212
33	RCRA NON GEN	CON EDISON SERVICE BOX: 8385	346 MCGUINESS BROOKLYN NY 11222 ***EPA Handler ID* | *Recycler Activity?:*** NYP004361838 | NO	NW	0.05 / 281.89	0	213
33	GEN MANIFEST	CON EDISON	F/O 346 MCGUINNESS BLVD SERVICE BOX # 8385 BROOKLYN NY 11222	NW	0.05 / 281.89	0	214
33	GEN MANIFEST	CON EDISON	346 MAGUINNESS AVE SB 8385 BROOKLYN NY	NW	0.05 / 281.89	0	214
34	NY SPILLS	FRANKLIN AND BEDFORD AVES	381 GREEN AVE BROOKLYN NY ***Spill No* | *Close Date:*** 0711578 | 02/04/2008 12:00:00 AM	ENE	0.06 / 294.15	-1	215

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
35	RCRA NON GEN	CON EDISON SERVICE BOX: 8385	348 MCGUINESS BLVD BROOKLYN NY 11222	NW	0.06 / 306.84	0	216
			***EPA Handler ID	Recycler Activity?:*** NYP004349015 | NO			
36	RCRA NON GEN	CON EDISON	242 FREEMAN ST BROOKLYN NY 11222	NNW	0.06 / 308.72	0	217
			***EPA Handler ID	Recycler Activity?:*** NYP004725644 | NO			
36	GEN MANIFEST	CON EDISON	242 FREEMAN ST SB8465 BROOKLYN NY 11201	NNW	0.06 / 308.72	0	218
37	NY SPILLS	RESIDENTIAL	352 MCGUINESS BLVD BROOKLYN NY	NW	0.06 / 331.18	0	218
			***Spill No	Close Date:*** 1911000 | 03/31/2020 12:00:00 AM			
37	NY SPILLS	APARTMENT COMPLEX	352 MCGUINNESS BLVD BROOKLYN NY	NW	0.06 / 331.18	0	219
			***Spill No	Close Date:*** 2108266 | 12/21/2021 12:00:00 AM			
38	NY SPILLS	MANHOLE 71304	MCGUINNESS BL/INDIA ST BROOKLYN NY	SW	0.06 / 342.07	1	220
			***Spill No	Close Date:*** 0002190 | 03/24/2004 12:00:00 AM			
38	NY SPILLS	MANHOLE #62845	MCGUINESS BLVE/INDIA ST BROOKLYN NY	SW	0.06 / 342.07	1	221
			***Spill No	Close Date:*** 9911540 | 03/04/2002 12:00:00 AM			
38	NY SPILLS	MANHOLE #71304	MCGUINNESS BLVD/INDIA ST BROOKLYN NY ***Spill No	Close Date:*** 0211464 | 12/08/2016 12:00:00 AM	SW	0.06 / 342.07	1	222
38	NY SPILLS	CON ED MANHOLE #71304	MCGINNIS/INDIA STREET BROOKLYN NY	SW	0.06 / 342.07	1	223
			***Spill No	Close Date:*** 0405049 | 01/19/2005 12:00:00 AM			
38	NY SPILLS	MANHOLE 713204	MCGUINESS BLVD/ INDIA ST. BROOKLYN NY ***Spill No	Close Date:*** 0402792 | 01/03/2005 12:00:00 AM	SW	0.06 / 342.07	1	224
38	NY SPILLS	INTERESCTION - MANHOLE #71304	MCGINNIS BLVD AND INDIA STREET BROOKLYN NY ***Spill No	Close Date:*** 0912432 | 03/12/2010 12:00:00 AM	SW	0.06 / 342.07	1	225
38	GEN MANIFEST	CONSOLIDATED EDISON	MH71304-MCGUINNESS BLVD &INDIA BROOKLYN NY	SW	0.06 / 342.07	1	226
38	GEN MANIFEST	NYSDOT	MCGUINESS BLVD & INDIA ST BROOKLYN NY	SW	0.06 / 342.07	1	227

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
38	GEN MANIFEST	CONSOLIDATED EDISON	MCGUINNESS & INDIA BROOKLYN NY 11201	SW	0.06 / 342.07	1	227
39	AST	FAISAL AUTO CARE CENTER INC.	315 MCGUINNESS BLVD Brooklyn NY 11222 ***Site ID*	*Site Status:*** 25838 | Active	SW	0.07 / 350.13	1	227
39	UST	GETTY 58088	315 MCGUINNESS BLVD Brooklyn NY 11222 ***Site ID*	*Site Status:*** 4261 | Unregulated/Closed	SW	0.07 / 350.13	1	230
39	NY SPILLS	VACANT AREA/FORMER GETTY	305-319 MCGUINNESS BLVD BROOKLYN NY ***Spill No*	*Close Date:*** 0400807 | 04/29/2014 12:00:00 AM	SW	0.07 / 350.13	1	243
39	NY SPILLS	315 MCGUINNESS BLVD	315 MCGUINNESS BLVD BROOKLYN NY ***Spill No*	*Close Date:*** 9111459 | 08/19/1992 12:00:00 AM	SW	0.07 / 350.13	1	246
40	RCRA LQG	CON EDISON - MANHOLE 4307	PROVOST ST BROOKLYN NY 11222 ***EPA Handler ID*	*Recycler Activity?:*** NYP004290326 | NO	E	0.07 / 354.25	-1	246
41	NY SPILLS	266 FREEMAN ST/BROOKLYN	266 FREEMAN STREET NEW YORK CITY NY ***Spill No*	*Close Date:*** 8905039 | 12/08/1992 12:00:00 AM	NE	0.07 / 355.29	-1	248
42	GEN MANIFEST	CON EDISON	PROVOST ST & HURON SB4306 BROOKLYN NY 11201	E	0.07 / 357.11	-1	249
43	AST	S.R. AUTO SERVICE, INC.	300 MCGUINNESS BOULEVARD Brooklyn NY 11222 ***Site ID*	*Site Status:*** 25900 | Active	SSW	0.07 / 364.12	1	249
43	NY SPILLS	AUTO BODY SHOP	300 MCGUINNES BLVD BROOKLYN NY ***Spill No*	*Close Date:*** 9613105 | 03/17/2016 12:00:00 AM	SSW	0.07 / 364.12	1	253
44	NY SPILLS	TWO GAL GREEN SUBSTANCE IN SB 7529	222 INDIA STREET BROOKLYN NY ***Spill No*	*Close Date:*** 0710905 | 03/20/2008 10:32:00 AM	SSE	0.07 / 373.23	0	254
45	NY SPILLS	GREEN ST & PROVOST/BKLYN	GREEN ST & PROVOST BROOKLYN NY ***Spill No*	*Close Date:*** 9011235 | 02/25/1991 12:00:00 AM	ENE	0.07 / 379.05	-2	255
46	NY SPILLS	EXXON TERMINAL	320 FREEMAN AVENUE BROOKLYN NY ***Spill No*	*Close Date:*** 8710916 | 03/30/1988 12:00:00 AM	NNE	0.07 / 380.07	-1	256

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
47	RCRA NON GEN	REPUBLIC METALS CO INC	273 GREEN ST BROOKLYN NY 11222-1207 ***EPA Handler ID	Recycler Activity?:*** NYD001213156 | NO	NE	0.08 / 398.70	-2	256
48	UST	MANNION SERVICE STATION	301 MCGUINNESS BOULEVARD BROOKLYN NY 11222 ***Site ID	Site Status:*** 19726 | Unregulated/Closed	SW	0.08 / 406.81	1	259
49	RCRA NON GEN	CON EDISON SERVICE BOX: 56190	239 JAVA ST BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYP004474466 | NO	SSE	0.08 / 410.45	0	264
49	GEN MANIFEST	CON EDISON	FRONT OF 239 JAVA ST SB8635 BROOKLYN NY 11222	SSE	0.08 / 410.45	0	265
49	GEN MANIFEST	CON EDISON	FRONT OF 239 JAVA ST SB56190 BROOKLYN NY 11222	SSE	0.08 / 410.45	0	265
49	GEN MANIFEST	CON EDISON	FRONT OF 239 JAVA ST SB56190 BROOKLYN NY 11222	SSE	0.08 / 410.45	0	265
49	GEN MANIFEST	CON EDISON	F/O 239 JAVA ST STRUCTURE 56190 BROOKLYN NY 11222	SSE	0.08 / 410.45	0	266
50	NY SPILLS	CONSTRUCTION PROJECT	347 FREEMAN ST BROOKLYN NY ***Spill No	Close Date:*** 0009812 | 11/30/2000 12:00:00 AM	NNE	0.08 / 423.27	-1	266
51	NY SPILLS	COMING FROM OUTSIDE- SINCE EARLY FEBRUARY	CORNER OF FREEMAN AND MCGUINESS BROOKLYN NY ***Spill No	Close Date:*** 1902180 | 06/03/2019 12:00:00 AM	NW	0.08 / 424.77	-1	267
52	RCRA NON GEN	NYCDOT PULASKI BRIDGE OVER NEWTOWN CREEK	MCGUINESS & FREEMAN BKLYN 11TH ST & JACKSON AVE QUEEN BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYD986993558 | NO	NW	0.08 / 448.30	0	268
52	NY SPILLS	TM #2907	FREEMAN STREET & MCGINNIS BLVD BROOKLYN NY ***Spill No	Close Date:*** 0706289 | 09/20/2007 08:43:00 AM	NW	0.08 / 448.30	0	270
53	NY SPILLS	SERVICE BOX 8463	210/212 FREEMAN AVENUE BROOKLYN NY ***Spill No	Close Date:*** 9901749 | 06/04/1999 12:00:00 AM	WNW	0.08 / 448.43	0	271
53	NY SPILLS	AT DUPLEX	212 FREEMAN ST BROOKLYN NY	WNW	0.08 / 448.43	0	272

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Spill No*	*Close Date:*** 1901371	05/09/2019 12:00:00 AM			
53	NY SPILLS	GROUND 212 FREEMAN ST.	212 FREEMAN STREET/ 212 GREEN STREET BROOKLYN NY ***Spill No*	*Close Date:*** 1812114	07/24/2019 12:00:00 AM	WNW	0.08 / 448.43	0	273
54	NY SPILLS	ROADWAY	FREEMAN & MCGUINESS ST BROOKLYN NY ***Spill No*	*Close Date:*** 0211776	02/28/2003 12:00:00 AM	NW	0.09 / 451.74	0	276
55	RCRA NON GEN	BAY CRANE SERVICE INC	255 FREEMAN ST BROOKLYN NY 11222 ***EPA Handler ID*	*Recycler Activity?:*** NYR000046383	NO	N	0.09 / 470.39	-1	277
55	GEN MANIFEST	BAY CRANE SERVICE INC	255 FREEMAN ST BROOKLYN NY	N	0.09 / 470.39	-1	279
56	RCRA NON GEN	CON EDISON MANHOLE: 7527	184 INDIA ST BROOKLYN NY 11222 ***EPA Handler ID*	*Recycler Activity?:*** NYP004345583	NO	SW	0.09 / 477.45	2	280
56	GEN MANIFEST	CON EDISON	184 INDIA ST SB 7527 BROOKLYN NY 11222	SW	0.09 / 477.45	2	281
57	NY SPILLS	EN TECH CORP	259 FREEMAN ST BROOKLYN NY ***Spill No*	*Close Date:*** 1810898	01/28/2019 12:00:00 AM	NNE	0.09 / 483.86	-1	281
58	UST	41-55 PROVOST CO	41-55 PROVOST ST 41 PROVOST ST Brooklyn NY 11222 ***Site ID*	*Site Status:*** 11210	Unregulated/Closed	SE	0.09 / 484.14	-1	282
59	PFAS IND	NUVITE CHEMICAL COMPOUNDS CORP	BROOKLYN NY	WNW	0.09 / 494.06	0	287
60	RCRA VSQG	NUVITE CHEMICAL COMPOUNDS CO	213 FREEMAN STREET BROOKLYN NY 11222 ***EPA Handler ID*	*Recycler Activity?:*** NYN008016354	NO	NW	0.10 / 527.09	0	287
60	RCRA SQG	NUVITE CHEMICAL	213 FREEMAN ST BROOKLYN NY 11222 ***EPA Handler ID:*** NYR000154708	NW	0.10 / 527.09	0	289
60	GEN MANIFEST	NUVITE CHEMICAL	213 FREEMAN ST BROOKLYN NY 11222	NW	0.10 / 527.09	0	290
60	TIER 2	NuVite Chemical Compounds Corp. 213 Freeman St. Brooklyn NY 11222	NY	NW	0.10 / 527.09	0	292

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
60	TIER 2	Nuvite Chemical Compounds Corp., 213 Freeman St., Brooklyn, NY 11222	NY	NW	0.10 / 527.09	0	293
60	TIER 2	Nuvite Chemical Compounds, 213 Freeman St., Brooklyn, NY 11222	Kings NY	NW	0.10 / 527.09	0	293
61	AST	200 FREEMAN ST	200 FREEMAN ST BROOKLYN NY 11222	WNW	0.10 / 528.53	1	293
			Site ID* | *Site Status: 13041 | Active				
62	NY SPILLS	FORMER NEY SMELTING AND REFINING COMPANY	269-277 FREEMAN STREET / 230-242 EAGLE ST/ 105 PROVOST STREET BROOKLYN NY 11222	NNE	0.10 / 547.04	-1	295
			Spill No* | *Close Date: 1006046 | 10/05/2010 12:00:00 AM				
63	SHWS	Former Ney Smelting and Refining Company	269 Freeman Street Greenpoint NY 11222	NNE	0.10 / 553.45	-1	298
64	NY SPILLS	RESIDENTIAL	366 MCGUINNESS BLVD BROOKLYN NY	NNW	0.11 / 560.68	-1	301
			Spill No* | *Close Date: 2305899 | 10/10/2023 12:00:00 AM				
64	NY SPILLS	ROADWAY	366 MCGUINNESS BLVD BROOKLYN NY	NNW	0.11 / 560.68	-1	301
			Spill No* | *Close Date: 2305891 | 10/31/2023 12:00:00 AM				
65	LST	203 JAVA ST.	203 JAVA ST BROOKLYN NY	SW	0.11 / 562.14	2	302
			Spill No* | *Close Date: 9303193 | 06/10/1993 12:00:00 AM				
66	RCRA NON GEN	CON EDISON SERVICE BOX: 7251	220 EAGLE ST BROOKLYN NY 11222	N	0.11 / 569.08	-1	303
			EPA Handler ID* | *Recycler Activity?: NYP004395091 | NO				
66	GEN MANIFEST	CON EDISON	220 EAGLE ST SB7251 BROOKLYN NY 11217	N	0.11 / 569.08	-1	304
67	NY SPILLS	PRIVATE RESIDENCE	214 EAGLE STREET NY	NNW	0.11 / 569.30	-1	305
			Spill No* | *Close Date: 1213916 | 12/27/2012 12:00:00 AM				
68	RCRA NON GEN	CON EDISON	JAVA ST & MCGUINESS BLVD BROOKLYN NY 11234	SSW	0.11 / 581.54	1	306

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***EPA Handler ID	Recycler Activity?:*** NYP004791919 | NO			
69	TIER 2	Skanska/Picone JV II 252 Java St. Brooklyn, NY 11222	NY	SE	0.11 / 603.40	-1	307
69	TIER 2	Welsbach Electric Corp. 252 Java St. Brooklyn, NY 11222	NY	SE	0.11 / 603.40	-1	307
69	TIER 2	Welsbach Electrical Corp. 252 Java St., Brooklyn, NY 11222 (REVISION)	NY	SE	0.11 / 603.40	-1	307
70	RCRA NON GEN	CON EDISON	234 JAVA ST BROOKLYN NY 11222	SSE	0.12 / 621.01	0	308
			***EPA Handler ID	Recycler Activity?:*** NYP004847406 | NO			
70	GEN MANIFEST	CON ED	234 JAVA ST SB 56190 BROOKLYN NY 11222	SSE	0.12 / 621.01	0	309
71	GEN MANIFEST	CON EDISON	FRONT OF 238 JAVA ST SB56190 BROOKLYN NY 11222	SSE	0.12 / 632.24	0	309
71	GEN MANIFEST	CON EDISON	238 JAVA SB 56190 BROOKLYN NY	SSE	0.12 / 632.24	0	310
71	GEN MANIFEST	CON EDISON	238 JAVA ST SB 56190 BROOKLYN NY	SSE	0.12 / 632.24	0	310
72	RCRA NON GEN	CON EDISON	230 JAVA ST & MCGUINESS BLVD BROOKLYN NY 11235	S	0.12 / 632.43	1	310
			***EPA Handler ID	Recycler Activity?:*** NYP004798765 | NO			
72	GEN MANIFEST	CON EDISON	230 JAVA ST MH 8636 BROOKLYN NY	S	0.12 / 632.43	1	311
73	UST	GREENPOINT NATIONAL GARAGE INC	276 MC GUINNESS BLVD BROOKLYN NY 11222	S	0.12 / 637.65	1	312
			***Site ID	Site Status:*** 9389 | Unregulated/Closed			
74	RCRA NON GEN	GREENPOINT NATIONAL GARAGE INC	276 MCGUINNESS BLVD BROOKLYN NY 11222-1811	S	0.12 / 637.70	1	317
			***EPA Handler ID	Recycler Activity?:*** NY0000080176 | NO			

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
74	GEN MANIFEST	GREENPOINT NATIONAL GARAGE INC	276 MCGUINNESS BLVD BROOKLYN NY	S	0.12 / 637.70	1	319
75	NY SPILLS	ABANDONED DRUMS	242 EAGLE ST BROOKLYN NY	NNE	0.12 / 638.81	-2	320
			Spill No* | *Close Date: 0203069 | 08/02/2002 12:00:00 AM				
76	GEN MANIFEST	CON EDISON	FRONT OF 183 HURON ST SB7498 BROOKLYN NY 11222	W	0.12 / 649.70	1	321
77	RCRA NON GEN	CON EDISON - NEWTOWN CRK WTR POLL PLT	329 GREENPOINT AVE ELECTRIC SERVICE AREA BROOKLYN NY 11222-1901	NE	0.12 / 649.95	-2	321
			EPA Handler ID* | *Recycler Activity?: NY0000228049 | NO				
77	RCRA NON GEN	EXXON CO USA-BROOKLYN TERMINAL	320 FREEMAN ST BROOKLYN NY 11222-1213	NE	0.12 / 649.95	-2	323
			EPA Handler ID* | *Recycler Activity?: NYD063855746 | NO				
77	RCRA SQG	NYCDEP BWT NEWTOWN CREEK WPCP	329 GREENPOINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	-2	326
			EPA Handler ID: NYD980779730				
77	AST	EXXON COMPANY,USA	320 FREEMAN STREET Brooklyn NY 11222	NE	0.12 / 649.95	-2	340
			Site ID* | *Site Status: 22853 | Inactive				
77	AST	NEWTOWN CREEK WWTP	329 GREENPOINT AVENUE BROOKLYN NY 11222	NE	0.12 / 649.95	-2	344
			Site ID* | *Site Status: 20122 | Active				
77	UST	NEWTOWN CREEK WWTP	329 GREENPOINT AVENUE BROOKLYN NY 11222	NE	0.12 / 649.95	-2	358
			Site ID* | *Site Status: 20122 | Active				
77	UST	EXXON COMPANY,USA	320 FREEMAN STREET Brooklyn NY 11222	NE	0.12 / 649.95	-2	397
			Site ID* | *Site Status: 22853 | Inactive				
77	CBS	NEWTOWN CREEK WWTP	329 GREENPOINT AVENUE BROOKLYN NY 11222	NE	0.12 / 649.95	-2	400
			Site ID* | *Site Status: 339175 | Active				
77	MOSF	NEWTON CREEK WPCP	329 GREENPOINT AVENUE BROOKLYN NY 11222	NE	0.12 / 649.95	-2	400
			Site ID* | *Site Status: 344985 | Unregulated/Closed				
77	NY SPILLS	NEWTOWN CREEK, STP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	400

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Spill No*	*Close Date:*** 9411493 | 12/02/1994 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WPCP DEP -DDC (JK)	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	401
			***Spill No*	*Close Date:*** 0000867 |			
77	NY SPILLS	NEWTOWN CREEK WPCP DEP -DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	402
			***Spill No*	*Close Date:*** 0001944 | 05/05/2005 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WPCP DEP -DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	403
			***Spill No*	*Close Date:*** 9408029 | 12/16/2002 12:00:00 AM			
77	NY SPILLS	EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	-2	405
			***Spill No*	*Close Date:*** 8907186 | 10/20/1989 12:00:00 AM			
77	NY SPILLS	EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	-2	405
			***Spill No*	*Close Date:*** 8912333 | 02/04/1998 12:00:00 AM			
77	NY SPILLS	EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	-2	406
			***Spill No*	*Close Date:*** 9012482 | 02/11/2010 12:00:00 AM			
77	NY SPILLS	301 GREENPOINT AVE	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	408
			***Spill No*	*Close Date:*** 9302991 | 06/05/1993 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	408
			***Spill No*	*Close Date:*** 0600090 | 04/04/2006 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	409
			***Spill No*	*Close Date:*** 0514208 | 03/13/2006 12:00:00 AM			
77	NY SPILLS	DEP FACILITY	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	410
			***Spill No*	*Close Date:*** 0514090 | 03/13/2006 12:00:00 AM			
77	NY SPILLS	ON THE ROAD	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	411
			***Spill No*	*Close Date:*** 0514375 | 03/16/2006 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WATER POLLU	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	412
			***Spill No*	*Close Date:*** 0511857 | 01/17/2006 12:00:00 AM			
77	NY SPILLS	MINOR SPILL	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	413

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Spill No*	*Close Date:*** 0512232 | 01/27/2006 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	414
			***Spill No*	*Close Date:*** 0603406 | 06/28/2006 12:00:00 AM			
77	NY SPILLS	POLUTION CONTROL PLANT	329 GREENPOINT AVE BROOKLYNN NY	NE	0.12 / 649.95	-2	415
			***Spill No*	*Close Date:*** 0711947 | 02/13/2008 12:00:00 AM			
77	NY SPILLS	NEWTON CREEK PLANT	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	416
			***Spill No*	*Close Date:*** 0611591 | 01/18/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WATER POLUTION CONTROL PLANT	329 GREEN POINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	-2	417
			***Spill No*	*Close Date:*** 0908611 | 11/02/2009 12:00:00 AM			
77	NY SPILLS	DEP WASTEWATER	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	418
			***Spill No*	*Close Date:*** 0512132 | 01/24/2006 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WATER POLLUTION CONTROL PLANT	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	418
			***Spill No*	*Close Date:*** 0810451 | 12/17/2008 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WPCP	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	419
			***Spill No*	*Close Date:*** 0650058 | 04/13/2006 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK WATER TREA	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	420
			***Spill No*	*Close Date:*** 0202662 | 06/12/2002 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	-2	421
			***Spill No*	*Close Date:*** 0706259 | 09/05/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WCPC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	422
			***Spill No*	*Close Date:*** 0705272 | 08/08/2007 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	423
			***Spill No*	*Close Date:*** 0701144 | 04/27/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WPCP DEP -DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	424
			***Spill No*	*Close Date:*** 9911559 | 02/26/2003 12:00:00 AM			

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
77	NY SPILLS	NEWTOWN CREEK WCPC	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	425
			Spill No* | *Close Date: 0809249 | 11/17/2008 12:00:00 AM				
77	NY SPILLS	POLLUTION PLANT	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	426
			Spill No* | *Close Date: 0511797 | 02/06/2006 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK WATER POLUTION CONTROL	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	427
			Spill No* | *Close Date: 0810194 | 12/12/2008 12:00:00 AM				
77	NY SPILLS	DEP WASTE WATER TREATMENT	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	428
			Spill No* | *Close Date: 0514457 | 03/17/2006 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK WATER PLAN	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	429
			Spill No* | *Close Date: 0307871 | 10/27/2003 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	430
			Spill No* | *Close Date: 0705172 | 08/09/2007 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	-2	431
			Spill No* | *Close Date: 0706180 | 08/31/2007 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK WPCP	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	432
			Spill No* | *Close Date: 0809701 | 12/02/2008 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	433
			Spill No* | *Close Date: 0510055 | 11/23/2005 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	433
			Spill No* | *Close Date: 0511191 | 12/27/2005 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK WPCP	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	434
			Spill No* | *Close Date: 0407841 | 01/28/2005 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK WATER POLUTION PLANT	329 GREEN POINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	-2	435
			Spill No* | *Close Date: 0806368 | 09/08/2008 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	436

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Spill No*	*Close Date:*** 0600869 | 04/24/2006 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WPCP DEP -DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	437
			***Spill No*	*Close Date:*** 0304007 | 07/17/2003 12:00:00 AM			
77	NY SPILLS	EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	-2	438
			***Spill No*	*Close Date:*** 8909181 | 12/19/1989 12:00:00 AM			
77	NY SPILLS	NEWTON CREEK PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	439
			***Spill No*	*Close Date:*** 0612936 | 03/02/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WPCP DEP -DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	440
			***Spill No*	*Close Date:*** 0013213 | 04/05/2001 12:00:00 AM			
77	NY SPILLS	NEWTON CREEK PLANT	301 GREENPOINT AVE. BROOKLYN NY	NE	0.12 / 649.95	-2	441
			***Spill No*	*Close Date:*** 0802830 | 06/11/2008 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WATER POLLUTION CONTROL	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	442
			***Spill No*	*Close Date:*** 0808966 | 11/10/2008 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEKWPCP DEP -DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	443
			***Spill No*	*Close Date:*** 9500431 | 05/05/2005 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	444
			***Spill No*	*Close Date:*** 0703835 | 07/05/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	445
			***Spill No*	*Close Date:*** 0610819 | 12/26/2006 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK WPCP	301 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	446
			***Spill No*	*Close Date:*** 0710149 | 12/24/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK CONT.PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	447
			***Spill No*	*Close Date:*** 0204403 | 07/29/2002 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WPCP DEP -DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	447
			***Spill No*	*Close Date:*** 9602370 | 04/18/2001 12:00:00 AM			
77	NY SPILLS	Spill Number 9809941	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	449

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Spill No*	*Close Date:*** 9809941 | 02/13/2003 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	450
			***Spill No*	*Close Date:*** 0500990 | 04/25/2005 12:00:00 AM			
77	NY SPILLS	EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	-2	451
			***Spill No*	*Close Date:*** 9004386 | 06/20/1995 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	451
			***Spill No*	*Close Date:*** 0405275 | 04/20/2005 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	453
			***Spill No*	*Close Date:*** 9614108 | 07/22/2005 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	454
			***Spill No*	*Close Date:*** 0509056 | 10/28/2005 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK WATER POLL	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	455
			***Spill No*	*Close Date:*** 0603250 | 06/26/2006 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WPCC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	456
			***Spill No*	*Close Date:*** 0603263 | 06/26/2006 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	456
			***Spill No*	*Close Date:*** 0603280 | 06/26/2006 12:00:00 AM			
77	NY SPILLS	13TH ST PUMP STATION	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	457
			***Spill No*	*Close Date:*** 0508779 | 10/25/2005 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WATER POLLU	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	458
			***Spill No*	*Close Date:*** 0701075 | 04/26/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	459
			***Spill No*	*Close Date:*** 0602385 | 06/02/2006 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	460
			***Spill No*	*Close Date:*** 0700138 | 04/05/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	461

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Spill No*	*Close Date:*** 0700483 | 04/16/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK WPCP	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	462
			***Spill No*	*Close Date:*** 0700197 | 04/09/2007 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	463
			***Spill No*	*Close Date:*** 0703363 | 06/22/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	-2	464
			***Spill No*	*Close Date:*** 0706548 | 09/12/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	465
			***Spill No*	*Close Date:*** 0706001 | 08/27/2007 12:00:00 AM			
77	NY SPILLS	AVENUE B PUMP STATION	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	-2	466
			***Spill No*	*Close Date:*** 0708718 | 11/13/2007 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	467
			***Spill No*	*Close Date:*** 0704882 | 08/01/2007 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	468
			***Spill No*	*Close Date:*** 0704883 | 08/01/2007 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	469
			***Spill No*	*Close Date:*** 0704884 | 07/31/2007 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK WATER PLAN	301 GREENPOINT AVE. BROOKLYN NY	NE	0.12 / 649.95	-2	470
			***Spill No*	*Close Date:*** 0707573 | 10/10/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	-2	470
			***Spill No*	*Close Date:*** 0709349 | 11/29/2007 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	471
			***Spill No*	*Close Date:*** 0804630 | 07/28/2008 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	472
			***Spill No*	*Close Date:*** 0804678 | 07/24/2008 12:00:00 AM			
77	NY SPILLS	NEW TOWN CREEK WATER PLAN	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	-2	473
			***Spill No*	*Close Date:*** 0804109 | 07/14/2008 12:00:00 AM			

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
77	NY SPILLS	NEW TOWN CREEK	301 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	474
			Spill No* | *Close Date: 0802371 | 06/02/2008 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK TREATMENT PLANT	329 GREEN POINT AVE - BROOKLYN NY	NE	0.12 / 649.95	-2	475
			Spill No* | *Close Date: 0810724 | 12/26/2008 12:00:00 AM				
77	NY SPILLS	DEP CONSTRUCTION SITE	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	476
			Spill No* | *Close Date: 0803882 | 07/17/2008 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK PLANT	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	477
			Spill No* | *Close Date: 1010132 | 12/27/2010 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK WATER POLL	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	478
			Spill No* | *Close Date: 0603777 | 07/06/2006 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	479
			Spill No* | *Close Date: 0610972 | 01/02/2007 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	480
			Spill No* | *Close Date: 0610780 | 12/26/2006 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK DEP SITE	329 GREEN POINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	-2	481
			Spill No* | *Close Date: 1001677 | 05/17/2010 12:00:00 AM				
77	NY SPILLS	NYC DEP FACILITY	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	482
			Spill No* | *Close Date: 1001442 | 05/07/2010 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK PLANT DEP	329 GREEN POINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	-2	483
			Spill No* | *Close Date: 0806630 | 09/15/2008 12:00:00 AM				
77	NY SPILLS	Spill Number 0206432	329 GREENPORT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	484
			Spill No* | *Close Date: 0206432 | 12/08/2003 12:00:00 AM				
77	NY SPILLS	ELEVATION -1 IN MAIN BLD	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	485
			Spill No* | *Close Date: 0908307 | 10/26/2009 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK WATER POLLUTION CONTROL PLANT	329 GREEN POINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	-2	485
			Spill No* | *Close Date: 0806127 | 09/02/2008 12:00:00 AM				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
77	NY SPILLS	NEWTOWN CREEK	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	486
			Spill No* | *Close Date: 0708099 | 10/26/2007 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	-2	487
			Spill No* | *Close Date: 0706475 | 10/25/2007 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	488
			Spill No* | *Close Date: 0609972 | 12/04/2006 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK	329 GREENPOINT AV BROOKLYNN NY	NE	0.12 / 649.95	-2	489
			Spill No* | *Close Date: 0805108 | 08/05/2008 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK TREATMENT	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	490
			Spill No* | *Close Date: 0307763 | 10/23/2003 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK WP	329 GREENPOINT AVE RD E BROOKLIN NY	NE	0.12 / 649.95	-2	491
			Spill No* | *Close Date: 0805503 | 08/13/2008 12:00:00 AM				
77	NY SPILLS	Spill Number 0108649	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	492
			Spill No* | *Close Date: 0108649 | 11/29/2001 12:00:00 AM				
77	NY SPILLS	NEWTON CREEK PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	493
			Spill No* | *Close Date: 0703611 | 06/28/2007 12:00:00 AM				
77	NY SPILLS	NYC SEWAGE TREATMENT PLANT	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	494
			Spill No* | *Close Date: 0904709 | 07/24/2009 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK WATER POLLUTION CONTROL PLANT	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	495
			Spill No* | *Close Date: 0810614 | 12/22/2008 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	-2	496
			Spill No* | *Close Date: 0710497 | 01/07/2008 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	497
			Spill No* | *Close Date: 0606073 | 08/28/2006 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	498
			Spill No* | *Close Date: 0510010 | 11/23/2005 12:00:00 AM				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
77	NY SPILLS	NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	499
			Spill No* | *Close Date: 0508162 | 10/11/2005 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK WPCP DEP -DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	499
			Spill No* | *Close Date: 9504909 | 05/05/2005 12:00:00 AM				
77	NY SPILLS	CONSTRUCTION SITE	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	501
			Spill No* | *Close Date: 0513125 | 02/17/2006 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK WPCP DEP -DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	502
			Spill No* | *Close Date: 8602874 | 07/31/1986 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	503
			Spill No* | *Close Date: 0502107 | 05/25/2005 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK WPCP DEP -DDC (JK)	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	503
			Spill No* | *Close Date: 9907560 |				
77	NY SPILLS	NEW TOWN CREEK WATER POLLUTION CONTROL PLANT	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	505
			Spill No* | *Close Date: 1007898 | 10/26/2010 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK WATER POLL CONTROL	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	506
			Spill No* | *Close Date: 1308089 | 11/08/2013 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK WWTP	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	507
			Spill No* | *Close Date: 1302071 | 06/03/2013 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	508
			Spill No* | *Close Date: 0510252 | 11/30/2005 12:00:00 AM				
77	NY SPILLS	NYC DEP NEWTON CREEK WATER POLLUTION CONTROL PLANT	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	508
			Spill No* | *Close Date: 1105600 | 08/17/2011 12:00:00 AM				
77	NY SPILLS	WHALECREEK CANAL	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	509
			Spill No* | *Close Date: 0510498 | 12/09/2005 12:00:00 AM				
77	NY SPILLS	NEWTOWN CREEK SEWER PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	510

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Spill No*	*Close Date:*** 0700018 | 04/02/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK PLANT	NEWTOWN CREEK PLANT NEW YORK CITY NY	NE	0.12 / 649.95	-2	511
			***Spill No*	*Close Date:*** 8604496 | 10/11/1986 12:00:00 AM			
77	NY SPILLS	ROAD C TUNNEL DEMO AREA	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	512
			***Spill No*	*Close Date:*** 0902642 | 06/04/2009 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK TREATMENT PLANT	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	-2	513
			***Spill No*	*Close Date:*** 0707652 | 10/11/2007 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	-2	514
			***Spill No*	*Close Date:*** 0804242 | 07/14/2008 12:00:00 AM			
77	NY SPILLS	CONSTRUCTION SITE	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	515
			***Spill No*	*Close Date:*** 0512289 | 01/27/2006 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	516
			***Spill No*	*Close Date:*** 0607498 | 01/04/2007 12:00:00 AM			
77	NY SPILLS	TULLY CONSTRUCTION	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	517
			***Spill No*	*Close Date:*** 0513123 | 02/17/2006 12:00:00 AM			
77	NY SPILLS	NYC DEP - WPCP	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	518
			***Spill No*	*Close Date:*** 0106038 | 12/01/2003 12:00:00 AM			
77	NY SPILLS	NEWTON CREEK PLANT	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	519
			***Spill No*	*Close Date:*** 0601593 | 05/12/2006 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	520
			***Spill No*	*Close Date:*** 0504567 | 07/18/2005 12:00:00 AM			
77	NY SPILLS	NEWTON CREEK PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	521
			***Spill No*	*Close Date:*** 0611175 | 01/08/2007 12:00:00 AM			
77	NY SPILLS	WATER POLLUTION CONTROL PLANT	329 GREEN POINT AVENUE BROOKLYN NY 11222	NE	0.12 / 649.95	-2	521
			***Spill No*	*Close Date:*** 0807189 | 09/26/2008 12:00:00 AM			
77	NY SPILLS	NEWTOWN CREEK	301 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	522
			***Spill No*	*Close Date:*** 0710837 | 01/13/2008 12:00:00 AM			

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
77	NY SPILLS	NEW TOWN CREEK WPCP	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	523
			Spill No* | *Close Date: 0808381 | 10/27/2008 12:00:00 AM				
77	NY SPILLS	Spill Number 9810145	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	524
			Spill No* | *Close Date: 9810145 | 10/04/1999 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	525
			Spill No* | *Close Date: 0502697 | 10/18/2005 12:00:00 AM				
77	NY SPILLS	NEW TOWN CREEK WWT PLANT	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	526
			Spill No* | *Close Date: 1002787 | 06/14/2010 12:00:00 AM				
77	NY SPILLS	PEGNO/TULLY JOINT VENTURE	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	527
			Spill No* | *Close Date: 0513124 | 02/17/2006 12:00:00 AM				
77	LST	NEWTOWN CREEK WPCP DEP -DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	528
			Spill No* | *Close Date: 9211551 | 01/08/1993 12:00:00 AM				
77	LST	NEWTOWN CREEK WPCP DEP -DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	529
			Spill No* | *Close Date: 0003594 | 05/05/2005 12:00:00 AM				
77	LST	EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	-2	530
			Spill No* | *Close Date: 9106287 | 10/16/1997 12:00:00 AM				
77	LST	NYC NEWTON CREEK WPCP	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	-2	531
			Spill No* | *Close Date: 9601620 | 07/31/1997 12:00:00 AM				
77	LST	EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	-2	532
			Spill No* | *Close Date: 9012950 | 12/27/2002 12:00:00 AM				
77	LST	NEW TOWN CREEK WATER POLL	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	533
			Spill No* | *Close Date: 0407835 | 10/19/2004 12:00:00 AM				
77	LST	MINOR SPILL	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	534
			Spill No* | *Close Date: 0512231 | 01/27/2006 12:00:00 AM				
77	LST	NEWTOWN CREEK SEWER PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	535
			Spill No* | *Close Date: 9700433 | 04/09/1997 12:00:00 AM				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
77	LST	NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	536
			***Spill No	Close Date:*** 0702645	06/04/2007 12:00:00 AM		
77	LST	DEPT OF CLEAN WATERS	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	536
			***Spill No	Close Date:*** 9606892	08/29/1996 12:00:00 AM		
77	LST	DEP WASTEWATER	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	537
			***Spill No	Close Date:*** 0512133	01/24/2006 12:00:00 AM		
77	LST	EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	-2	538
			***Spill No	Close Date:*** 9104730	03/30/1995 12:00:00 AM		
77	LST	EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	-2	539
			***Spill No	Close Date:*** 9101866	12/23/2002 12:00:00 AM		
77	LST	DEP WASTEWATER	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	-2	540
			***Spill No	Close Date:*** 0512131	01/24/2006 12:00:00 AM		
77	UST	EXXON COMPANY, U.S. A.	320 FREEMAN STREET Brooklyn NY 11222	NE	0.12 / 649.95	-2	541
			***Site ID	Site Status:*** 340334	Unregulated/Closed		
77	AST	THE CITY OF NEW YORK/NYCDEP	329 GREENPOINT AVENUE 329 GREENPOINT AVENUE Brooklyn NY 11222 ***Site ID	Site Status:*** 341773	Unregulated/Closed	NE	0.12 / 649.95	-2	542
77	NY SPILLS	FACILITY WASTE WATER TREATMENT PLANT	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	543
			***Spill No	Close Date:*** 1504424	07/27/2015 12:00:00 AM		
77	NY SPILLS	SEWAGE TREATMENT PLANT (NEW TOWN CREEK)	301 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	544
			***Spill No	Close Date:*** 1805468	08/21/2018 12:00:00 AM		
77	GEN MANIFEST	NYCDEP - NEWTON CREEK WPCP	329 GREENPOINT AVENUE BROOKLYN NY 11222	NE	0.12 / 649.95	-2	545
77	GEN MANIFEST	NYC DEP	329 GREENPOINT AVE BROOKLYN NY 11201	NE	0.12 / 649.95	-2	555
77	GEN MANIFEST	EXXON COMPANY USA 3020	320 FREEMAN ST BROOKLYN NY 11222	NE	0.12 / 649.95	-2	556

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
77	AIR PERMITS	NEWTOWN CREEK WASTEWATER RESOURCE RECOVERY FACILITY	329-69 GREENPOINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	-2	558
77	TIER 2	Nyc Dep Bwt Newtown Creek Wpcp	329 Greenpoint Ave Brooklyn NY 11222	NE	0.12 / 649.95	-2	559
77	TIER 2	Nyc Dep Bwt Newtown Creek Wpcp	329 Greenpoint Ave Brooklyn NY	NE	0.12 / 649.95	-2	559
77	TIER 2	NYC DEP BWT Newtown Creek WPCP	329 Greenpoint Ave Brooklyn NY 11222	NE	0.12 / 649.95	-2	559
77	NY SPILLS	NATIONAL GRID VEHICLE	327 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	559
			Spill No* | *Close Date: 2209274 | 02/17/2023 12:00:00 AM				
77	NY SPILLS	COMMERICAL EQUIPEMNT	327 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	560
			Spill No* | *Close Date: 2209494 | 03/03/2023 12:00:00 AM				
77	PFAS IND	NEWTOWN CREEK WATER POLLUTION CONTROL PLANT	BROOKLYN NY	NE	0.12 / 649.95	-2	561
77	NY SPILLS	YARD	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	562
			Spill No* | *Close Date: 2402362 | 09/13/2024 12:00:00 AM				
77	NY SPILLS	CRACKED FITTING	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	563
			Spill No* | *Close Date: 2402540 | 09/12/2024 12:00:00 AM				
77	NY SPILLS	WASTE WATER TX FACILITY	327 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	-2	564
			Spill No* | *Close Date: 2404227 | 08/22/2024 12:00:00 AM				
78	RCRA NON GEN	CON ED - MH 4308	JAVA ST & PROVOST ST BROOKLYN NY 11222-0000	SE	0.12 / 657.97	-1	565
			EPA Handler ID* | *Recycler Activity?: NYP004008553 | NO				
78	NY SPILLS	MANHOLE # TM2275	JAVA ST/PROVOST ST BROOKLYN NY	SE	0.12 / 657.97	-1	566
			Spill No* | *Close Date: 0012337 | 06/13/2003 12:00:00 AM				
78	RCRA LQG	CON EDISON - TRANSFORMER MANHOLE 2275	JAVA ST & PROVOST ST NEW YORK NY 10017	SE	0.12 / 657.97	-1	567

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***EPA Handler ID	Recycler Activity?:*** NYP004869271 | NO			
78	NY MANIFEST	CON ED	JAVA ST & PROVOST ST NEW YORK NY 10017	SE	0.12 / 657.97	-1	569
79	RCRA NON GEN	SKANSKA PICONE III JV	252 JAVA ST AKA 259 KENT ST BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYR000212837 | NO	SE	0.14 / 716.58	-1	569
80	RCRA NON GEN	CON EDISON SERVICE BOX: 7252	227 EAGLE ST BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYP004427720 | NO	N	0.14 / 729.78	-2	572
81	RCRA NON GEN	CON EDISON SERVICE BOX: 8198	237 KENT ST BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYP004312948 | NO	SSE	0.14 / 734.14	0	573
82	SEMS ARCHIVE	FOX & LONDON INC.	21 PROVOST ST BROOKLYN NY 11222 ***EPA ID:*** NYN000206649	SE	0.14 / 741.58	-1	574
83	CERCLIS	FOX & LONDON INC.	21 PROVOST ST BROOKLYN NY 11222 ***Site EPA ID:*** NYN000206649	SE	0.14 / 741.69	-1	575
83	RCRA NON GEN	FOX & LONDON INC	21 PROVOST AVE BROOKLYN NY 11222-1813 ***EPA Handler ID	Recycler Activity?:*** NYN008010340 | NO	SE	0.14 / 741.69	-1	576
84	UST	NORIS METALS	231 KENT ST Brooklyn NY 11222 ***Site ID	Site Status:*** 472661 | Unregulated/Closed	S	0.14 / 752.66	1	578
84	RCRA NON GEN	NORIS METAL	231 KENT ST BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYR000194705 | NO	S	0.14 / 752.66	1	581
85	UST	WJZ AUTO REPAIR INC	262-268 MCGUINNESS BLVD 262 MCGUINNESS BLVD Brooklyn NY 11222 ***Site ID	Site Status:*** 14149 | Unregulated/Closed	S	0.15 / 765.88	1	583
86	RCRA LQG	WALLCOTE PAINT CO	208 DUPONT ST BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYD001289131 | NO	N	0.15 / 786.45	-2	591
86	UST	HARCO CHEMICAL COATINGS	208 DUPONT STREET Brooklyn NY 11222 ***Site ID	Site Status:*** 25581 | Unregulated/Closed	N	0.15 / 786.45	-2	597

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
86	UST	HARCO CHEMICAL COATINGS	208 DUPONT ST Brooklyn NY 11222	N	0.15 / 786.45	-2	599
			***Site ID*	*Site Status:*** 340012	Unregulated/Closed		
86	AST	HARCO CHEMICAL COATINGS	208 DUPONT ST Brooklyn NY 11222	N	0.15 / 786.45	-2	600
			***Site ID*	*Site Status:*** 340012	Unregulated/Closed		
87	RCRA NON GEN	CON EDISON	209 KENT ST BROOKLYN NY 11222	SSW	0.15 / 804.84	4	600
			***EPA Handler ID*	*Recycler Activity?:*** NYP004790705	NO		
88	RCRA NON GEN	CON EDISON	185 EAGLE ST BROOKLYN NY 11222	NW	0.15 / 806.77	-2	602
			***EPA Handler ID*	*Recycler Activity?:*** NYP004758488	NO		
89	UST	996 MANHATTAN AVENUE	996 MANHATTAN AVENUE NEW YORK NY 11222	W	0.15 / 812.54	2	603
			***Site ID*	*Site Status:*** 612620	Unregulated/Closed		
89	OER CLEANUP	996 Manhattan Avenue	996 Manhattan Avenue Brooklyn NY	W	0.15 / 812.54	2	605
90	SWF/LF	POLYSTYRENE RECYCLING; INC.	220 DUPONT STREET Brooklyn NY 11222	NNE	0.15 / 814.69	-2	605
91	RCRA NON GEN	CONSOLIDATED SMELTING	25 PROVOST AVE BROOKLYN NY 11222-1813	SE	0.16 / 824.03	-2	606
			***EPA Handler ID*	*Recycler Activity?:*** NYN008010332	NO		
92	AST	982 MANHATTAN AVE	982 MANHATTAN AVENUE Brooklyn NY 11222	WSW	0.16 / 832.22	5	608
			***Site ID*	*Site Status:*** 30834	Unregulated/Closed		
93	RCRA NON GEN	CON EDISON SERVICE BOX: 8381	382 MCGUINESS BLVD BROOKLYN NY 11222	NNW	0.16 / 839.56	-3	610
			***EPA Handler ID*	*Recycler Activity?:*** NYP004389508	NO		
94	RCRA NON GEN	CON EDISON SERVICE BOX: 8461	183 FREEMAN ST BROOKLYN NY 11222	WNW	0.16 / 841.11	2	611
			***EPA Handler ID*	*Recycler Activity?:*** NYP004443081	NO		
95	OER CLEANUP	1026-1030 MANHATTAN AVENUE	1026-1030 MANHATTAN AVENUE Brooklyn NY	W	0.16 / 853.83	2	612
96	RCRA NON GEN	CON EDISON	177 EAGLE ST BROOKLYN NY 11222	NW	0.16 / 854.90	-1	613
			***EPA Handler ID*	*Recycler Activity?:*** NYP004809731	NO		

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
97	BROWNFIELDS	1036 Manhattan Ave BCP Site	1032 and 1036-1038 Manhattan Avenue Brooklyn NY 11222	W	0.16 / 856.30	2	614
98	RCRA NON GEN	CON EDISON SERVICE BOX: 08458	181 FREEMAN ST BROOKLYN NY 11222 ***EPA Handler ID | Recycler Activity?:*** NYP004443073 | NO	WNW	0.16 / 862.19	2	617
99	RCRA NON GEN	KELLY CLEANERS	1036 MANHATTAN AVE BROOKLYN NY 11222-1316 ***EPA Handler ID | Recycler Activity?:*** NYD049146186 | NO	W	0.16 / 864.41	2	618
100	RCRA NON GEN	AMSCOR INC	188 DUPONT ST BROOKLYN NY 11222 ***EPA Handler ID | Recycler Activity?:*** NYD986909612 | NO	NNW	0.17 / 879.82	-3	620
101	RCRA NON GEN	CON EDISON	210 KENT ST BROOKLYN NY 11222 ***EPA Handler ID | Recycler Activity?:*** NYP004798203 | NO	SSW	0.17 / 893.32	3	622
102	PFAS IND	AMSCOR CORPORATION - 188 DUPONT STREET	BROOKLYN NY	NNW	0.17 / 900.12	-3	623
103	PFAS IND	HARCO CHEMICAL COATINGS INC	BROOKLYN NY	N	0.17 / 903.43	-2	624
104	RCRA LQG	MTA NYCT GREEN STREET SUBSTATION	GREEN ST & MANHATTAN AVE BROOKLYN NY 11222 ***EPA Handler ID | Recycler Activity?:*** NYR000076620 | NO	W	0.17 / 910.86	3	625
105	RCRA NON GEN	SHELL OIL CO	256 MCGUINNES BLVD BROOKLYN NY 11222-1809 ***EPA Handler ID | Recycler Activity?:*** NYD987008166 | NO	S	0.17 / 918.56	1	627
105	UST	MC GUINNESS & KENT SERVICE STATION INC.	256 MCGUINNESS BOULEVARD 256 MCGUINNESS BLVD (KENT ST) Brooklyn NY 11222 ***Site ID | Site Status:*** 5932 | Active	S	0.17 / 918.56	1	629
106	AST	J & N ASSOC	158 DUPONT ST (AKA 158A DUPONT STREET) Brooklyn NY 11222 ***Site ID | Site Status:*** 4631 | Unregulated/Closed	NW	0.17 / 920.87	-2	640
107	OER CLEANUP	1048 MANHATTAN AVENUE	1048 MANHATTAN AVENUE Brooklyn NY	WNW	0.18 / 932.41	2	643
108	RCRA NON GEN	CON EDISION - TM615	DUPONT ST. AND MCGUINESS BLVD. NEW YORK NY 10003	NW	0.18 / 947.45	-3	643

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***EPA Handler ID	Recycler Activity?:*** NYP004082608 | NO			
109	RCRA SQG	MTA NYCT - GREENPOINT TUBE	INDIA ST & MANHATTAN AVE JACKSON AVE & 47TH RD BROOKLYN NY 11222 ***EPA Handler ID:*** NYR000208231	WSW	0.18 / 948.49	8	644
109	RCRA SQG	MTA NYCT - CROSSTOWN LINE I G LINE	INDIA ST & MANHATTAN AVE TO CHURCH & MCDONALD AVES BROOKLYN NY 11218 ***EPA Handler ID:*** NYR000229195	WSW	0.18 / 948.49	8	645
110	AST	ALEKSANDRA CHODOWIEC	161 JAVA STREET AP. 1 BROOKLYN NY 11222	WSW	0.18 / 961.96	12	647
			***Site ID	Site Status:*** 30478 | Unregulated/Closed			
111	RCRA LQG	CON EDISON - TRANSFORMER MANHOLE 753	253 GREENPOINT AVE BROOKLYN NY 11222	SSE	0.18 / 964.07	-2	649
			***EPA Handler ID	Recycler Activity?:*** NYP005133897 | NO			
112	RCRA NON GEN	APHRODITE CLEANER	1019 MANHATTAN AVE BROOKLYN NY 11222	W	0.18 / 969.82	3	650
			***EPA Handler ID	Recycler Activity?:*** NYD987003795 | NO			
112	DELISTED DRYCLEANERS	APHRODITE CLEANERS	1019 MANHATTAN AVENUE BROOKLYN NY 11222	W	0.18 / 969.82	3	652
113	OER CLEANUP	1050-1066 Manhattan Avenue	1050 Manhattan Avenue Brooklyn NY	WNW	0.18 / 972.99	2	652
114	AST	APARTMENT HOUSE	168 HURON STREET BROOKLYN NY 11222	W	0.19 / 982.29	3	653
			***Site ID	Site Status:*** 16611 | Active			
115	AST	158 GREEN INC	158 GREEN ST AKA 107 MANHATTAN AVE Brooklyn NY 11222 ***Site ID	Site Status:*** 460896 | Active	W	0.19 / 987.93	3	655
116	RCRA NON GEN	GREENSPAN & KUSHLIN ENGRAVING CORP	223 GREENPOINT AVE BROOKLYN NY 11222	SSE	0.19 / 988.30	-2	657
			***EPA Handler ID	Recycler Activity?:*** NYR000097212 | NO			
116	RCRA NON GEN	CON EDISON SERVICE BOX: 08140	223 GREENPOINT AVE BROOKLYN NY 11222	SSE	0.19 / 988.30	-2	659
			***EPA Handler ID	Recycler Activity?:*** NYP004575627 | NO			
116	RCRA NON GEN	CON EDISON	223 GREEENPOINT AVE & MCGUINNESS BLVD BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYP004183224 | NO	SSE	0.19 / 988.30	-2	660

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
117	RCRA NON GEN	NYC FIRE DEPT ENGINE CO 238	205 GREENPOINT AVE BROOKLYN NY 11222-2407 ***EPA Handler ID	Recycler Activity?:*** NYR000040428 | NO	S	0.19 / 1,000.18	1	662
117	AST	ENGINE COMPANY 238	205 GREENPOINT AVENUE Brooklyn NY 11222 ***Site ID	Site Status:*** 22504 | Unregulated/Closed	S	0.19 / 1,000.18	1	664
117	UST	ENGINE COMPANY 238	205 GREENPOINT AVENUE Brooklyn NY 11222 ***Site ID	Site Status:*** 22504 | Unregulated/Closed	S	0.19 / 1,000.18	1	670
117	RCRA NON GEN	CON EDISON SERVICE BOX: 8139	207 GREENPOINT AVE BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYP004434239 | NO	S	0.19 / 1,000.18	1	676
118	OER CLEANUP	946 Manhattan Avenue/160 Java Street	946 Manhattan Avenue Brooklyn NY	SW	0.19 / 1,010.27	14	677
119	OER CLEANUP	975 Manhattan Avenue	975 MANHATTAN AVENUE Brooklyn NY	WSW	0.19 / 1,016.23	7	677
120	OER CLEANUP	193 Greenpoint Avenue	193 GREENPOINT AVENUE Brooklyn NY	SSW	0.19 / 1,022.33	3	678
121	OER CLEANUP	977 Manhattan Avenue	977 Manhattan Avenue Brooklyn NY	WSW	0.19 / 1,024.41	6	678
122	RCRA NON GEN	INTERFLO TECHNOLOGIES	393 MCGUINNESS BLVD BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NY0000441139 | NO	NW	0.20 / 1,038.67	-3	678
123	RCRA NON GEN	CON EDISION - MH61605	MANHATTAN AVE NORTH OF JAVA MA NEW YORK NY 10003 ***EPA Handler ID	Recycler Activity?:*** NYP004084406 | NO	WSW	0.20 / 1,059.19	14	681
124	AST	J & N ASSOC	159 DUPONT ST Brooklyn NY 11222 ***Site ID	Site Status:*** 4630 | Unregulated/Closed	NW	0.20 / 1,064.94	-2	683
125	RCRA NON GEN	CON EDISON VAULT SUBMERSIBLE: 3826	NEWELL ST & GREEN POINT AVE 205 FEET S OF BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYP004431961 | NO	SSE	0.20 / 1,076.47	0	685
126	RCRA LQG	NYCDOT CONTRACT #HB107000GP & L & L PAINTING CO INC	GREENPOINT AVE BR NEWTOWN CREEK BROOKLYN NY 11232 ***EPA Handler ID	Recycler Activity?:*** NYR000199448 | NO	SSE	0.20 / 1,080.52	-3	686

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
127	OER CLEANUP	153 GREEN STREET	153 GREEN STREET Brooklyn NY	W	0.21 / 1,087.13	2	688
128	AST	146 CLAY LLC	400 MC GUINNESS BLVD Brooklyn NY 11222 ***Site ID*	*Site Status:*** 15854 | Unregulated/Closed	NNW	0.21 / 1,088.80	-3	688
129	RCRA NON GEN	CON EDISON	91 PAIDGE AVE & PROVOST ST BROOKLYN NY 11222 ***EPA Handler ID*	*Recycler Activity?:*** NYP004183273 | NO	NE	0.21 / 1,088.91	-3	690
130	AIR PERMITS	DIAMOND ASPHALT CORPORATION	91 Paidge Ave Brooklyn NY 11222	NE	0.21 / 1,090.66	-3	691
131	OER CLEANUP	175-177 GREENPOINT AVE	175-177 GREENPOINT AVE Brooklyn NY	SSW	0.21 / 1,092.93	10	692
132	RCRA NON GEN	CON EDISON MANHOLE: 55218	PAIDGE PL 300 FT S OF PROVOST ST E SIDE BROOKLYN NY 11201 ***EPA Handler ID*	*Recycler Activity?:*** NYP004279113 | NO	NNE	0.21 / 1,096.86	-4	692
133	RCRA NON GEN	CON EDISON	173 GREENPOINT AVE BROOKLYN NY 11222 ***EPA Handler ID*	*Recycler Activity?:*** NYP004788030 | NO	SSW	0.21 / 1,103.40	11	693
134	AST	947 ASSOCIATES, LLC	151 JAVA ST BROOKLYN NY 11222 ***Site ID*	*Site Status:*** 18276 | Unregulated/Closed	WSW	0.21 / 1,115.68	14	694
135	OER CLEANUP	148 GREEN STREET	148 GREEN STREET Brooklyn NY	W	0.21 / 1,120.22	2	697
136	NPL	NEWTOWN CREEK	SOUTH END OF IVY HILL ROAD BROOKLYN, QUEENS NY 11222 ***EPA ID:*** NYN000206282	E	0.21 / 1,121.54	-7	697
137	PFAS IND	LEVITON MFG CO INC	BROOKLYN NY	SE	0.21 / 1,127.50	-3	698
138	RCRA NON GEN	CON EDISON	167 GREENPOINT AVE BROOKLYN NY 11222 ***EPA Handler ID*	*Recycler Activity?:*** NYP004807921 | NO	SSW	0.22 / 1,137.28	13	699
139	RCRA NON GEN	VERIZON	GREEN POINT AVE & JEWEL ST INTERSECTION OF BROOKLYN NY 11222 ***EPA Handler ID*	*Recycler Activity?:*** NYP000965772 | NO	SE	0.22 / 1,175.86	-3	700

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
139	RCRA NON GEN	VERIZON	GREENPOINT AVE & JEWEL ST INTERSECTION OF BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYP000965707 | NO	SE	0.22 / 1,175.86	-3	701
139	RCRA NON GEN	CON EDISON	GREENPOINT AVE & JEWEL ST BROOKLYN NY 11235 ***EPA Handler ID	Recycler Activity?:*** NYP004792594 | NO	SE	0.22 / 1,175.86	-3	702
140	RCRA NON GEN	R & S STRAUSS	235 MCGUINESS BLVD BROOKLYN NY 11222-2305 ***EPA Handler ID	Recycler Activity?:*** NYR000025619 | NO	S	0.22 / 1,184.97	4	703
140	UST	SPEEDWAY # 7821	210 GREENPOINT AVENUE BROOKLYN NY 11222 ***Site ID	Site Status:*** 13746 | Unregulated/Closed	S	0.22 / 1,184.97	4	705
140	LST	MERIT S/S	210 GREENPOINT AVENUE BROOKLYN NY ***Spill No	Close Date:*** 9303423 | 10/28/2003 12:00:00 AM	S	0.22 / 1,184.97	4	724
140	RCRA VSQG	SPEEDWAY 7821	210 GREENPOINT AVE BROOKLYN NY 11222-2304 ***EPA Handler ID	Recycler Activity?:*** NYD982185944 | NO	S	0.22 / 1,184.97	4	725
140	OER CLEANUP	237 McGuinness Boulevard	210 Greenpoint Avenue Brooklyn NY	S	0.22 / 1,184.97	4	727
141	BROWNFIELDS	210 Greenpoint Avenue Redevelopment	210 GREENPOINT AVENUE BROOKLYN NY 11222	S	0.23 / 1,189.03	4	727
141	PFAS CONTAM	210 Greenpoint Avenue Redevelopment	210 GREENPOINT AVENUE BROOKLYN NY 11222	S	0.23 / 1,189.03	4	731
142	RCRA NON GEN	CON EDISON SERVICE BOX: 8624	143 JAVA ST BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYP004311346 | NO	WSW	0.23 / 1,191.50	15	735
143	RCRA LQG	CON EDISON - TRANSFORMER MANHOLE 658	120 DUPONT ST & MANHATTAN AVE BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYP004871584 | NO	WNW	0.23 / 1,195.38	3	736
144	RCRA NON GEN	CON EDISON MANHOLE: 8172	213 JEWEL ST BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYP004289914 | NO	SE	0.23 / 1,202.31	-3	738
145	RCRA NON GEN	CON EDISON SERVICE BOX: 08133	157 GREENPOINT AVE BROOKLYN NY 11222 ***EPA Handler ID	Recycler Activity?:*** NYP004441994 | NO	SW	0.23 / 1,203.56	16	739

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
146	RCRA NON GEN	CON EDISON	916 MANHATTAN AVE BROOKLYN NY 11222	SW	0.23 / 1,209.65	18	740
			***EPA Handler ID	Recycler Activity?:*** NYP004736971 | NO			
147	RCRA LQG	CON EDISON - MANHOLE 4328	MANHATTAN AVE & KENT ST INT BROOKLYN NY 11222	SW	0.23 / 1,230.05	19	741
			***EPA Handler ID	Recycler Activity?:*** NYP005151725 | NO			
148	LST	132-140 GREEN STREET	132-140 GREEN STREET NEW YORK CITY NY	W	0.23 / 1,231.45	2	742
			***Spill No	Close Date:*** 0011967 | 04/11/2003 12:00:00 AM			
149	BULK TERMINAL	SUNOCO MIDSTREAM LLC	BROOKLYN NY	N	0.24 / 1,244.06	-3	743
150	PFAS IND	BROOKLYN TERMINAL - SUNOCO LLC	BROOKLYN NY	N	0.24 / 1,254.22	-4	744
151	AST	DUPONT ASSOC	127 DUPONT ST Brooklyn NY 11222	NW	0.24 / 1,259.50	3	745
			***Site ID	Site Status:*** 4632 | Unregulated/Closed			
152	RCRA NON GEN	CON EDISON	178 GREENPOINT AVE BROOKLYN NY 11235	SSW	0.24 / 1,272.25	16	747
			***EPA Handler ID	Recycler Activity?:*** NYP004802682 | NO			
153	RCRA NON GEN	CON EDISON	131 EAGLE ST BROOKLYN NY 11222	WNW	0.24 / 1,280.75	3	749
			***EPA Handler ID	Recycler Activity?:*** NYP004884124 | NO			
154	OER CLEANUP	186 Greenpoint Avenue	186 Greenpoint Avenue Brooklyn NY	SSW	0.24 / 1,288.27	16	750
155	RCRA NON GEN	CON EDISON	132 HURON ST BROOKLYN NY 11222	W	0.25 / 1,310.09	3	750
			***EPA Handler ID	Recycler Activity?:*** NYP004813750 | NO			
156	AST	ST. ELIAS GREEK RITE ROMAN CATH. CHURCH	147 KENT STREET BROOKLYN NY 11222	WSW	0.25 / 1,313.93	19	751
			***Site ID	Site Status:*** 28224 | Active			
157	SWF/LF	Perez Interboro Asphalt C	99 Paidge Avenue Brooklyn NY 0	NE	0.26 / 1,371.75	-9	753
158	MOSF	BROOKLYN - SUNOCO LLC	25 PAIDGE AVENUE BROOKLYN NY 11222	N	0.26 / 1,398.14	-6	754
			***Site ID	Site Status:*** 344636 | Active			

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
158	LST	MOTIVA	25 PAIDGE AVENUE BROOKLYN NY	N	0.26 / 1,398.14	-6	754
			Spill No* | *Close Date: 9413568 | 10/28/2003 12:00:00 AM				
158	LST	MOTIVA	25 PAIDGE AVENUE BROOKLYN NY	N	0.26 / 1,398.14	-6	755
			Spill No* | *Close Date: 8703522 | 07/30/1987 12:00:00 AM				
158	PFAS	Arc Terminals New York Holdings, LLC	25 Paidge Ave Brooklyn NY	N	0.26 / 1,398.14	-6	756
159	SWF/LF	Greenpoint Scrap Metal	304 Greenpoint Avenue Brooklyn NY 11222	SE	0.27 / 1,403.94	-3	757
159	RECYCLING	Greenpoint Scrap Metal	304 Greenpoint Avenue Brooklyn NY 11222	SE	0.27 / 1,403.94	-3	758
160	LST	Spill Number 0010491	64 BOX ST BROOKLYN NY	NW	0.27 / 1,438.63	-1	759
			Spill No* | *Close Date: 0010491 | 06/13/2003 12:00:00 AM				
161	SHWS	Box Street GW	Box Street btw Manhattan Ave and McGuinness Blvd Brooklyn NY 11222	NW	0.29 / 1,537.99	-1	760
162	LST	DEPT OF SANITATION	459 N HENRY ST BROOKLYN NY	ENE	0.31 / 1,640.16	-11	761
			Spill No* | *Close Date: 0012519 | 04/23/2012 12:00:00 AM				
162	SWF/LF	DSNY Greenpoint Household Drop-Off	459 NORTH HENRY ST. (NEWTOWN CREEK IN GREENPOINT) Brooklyn NY 11222	ENE	0.31 / 1,640.16	-11	763
162	SWF/LF	DSNY Greenpoint Household Drop-Off	459 NORTH HENRY ST. (NEWTOWN CREEK IN GREENPOINT) Brooklyn NY 11222	ENE	0.31 / 1,640.16	-11	763
163	PFAS IND	NYC-DOS GREENPOINT MTS	BROOKLYN NY	ENE	0.31 / 1,649.02	-12	764
164	PFAS IND	LOVE MONKEY	BROOKLYN NY	SSE	0.32 / 1,671.83	0	765
165	SWF/LF	Rapid Processing (Humboldt Ave Brooklyn)	860 Humboldt Street Brooklyn NY 11222	ESE	0.32 / 1,684.11	-2	766

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
166	PFAS IND	GREENPOINT INCINERATOR NEW YORK CITY DEPARTMENT OF SANITATION NYCDOS	BROOKLYN NY	E	0.32 / 1,684.26	-3	767
167	BROWNFIELDS	Former BRT Railroad Car Barn	1121-1137 Manhattan Avenue/18 Box St. Brooklyn NY 11222	NW	0.32 / 1,689.97	1	767
168	LST	176 MCGUINNES AVE/GAS STA - TTF	176 MCGUINNESS BOULEVARD Brooklyn NY 11222	SSE	0.32 / 1,702.24	4	772
			***Spill No	Close Date:*** 9108332	10/27/2014 12:00:00 AM		
169	LST	120 JEWEL ST/BKLYN	120 JEWEL ST NEW YORK CITY NY	SE	0.33 / 1,759.40	-1	773
			***Spill No	Close Date:*** 8708714	09/30/1992 12:00:00 AM		
170	LST	CANDLELIGHT CIRCLE	BLDG# 15 CLAY NY	WNW	0.34 / 1,770.42	2	774
			***Spill No	Close Date:*** 9400007	04/29/1994 12:00:00 AM		
171	LST	29 ASH ST/BKLYN/UNIVERSAL	29 ASH ST BROOKLYN NY	NNW	0.34 / 1,803.85	-6	775
			***Spill No	Close Date:*** 8708297	07/18/2003 12:00:00 AM		
171	LST	29 ASH ST	29 ASH ST BROOKLYN NY	NNW	0.34 / 1,803.85	-6	776
			***Spill No	Close Date:*** 9709313	04/03/2003 12:00:00 AM		
172	BROWNFIELDS	29 Clay Property	29 Clay Street Brooklyn NY 11222	WNW	0.34 / 1,811.42	2	778
173	LST	330 CALYER ST.	330 CALYER STREET BROOKLYN NY	ESE	0.34 / 1,812.49	-2	780
			***Spill No	Close Date:*** 9401962	04/30/1998 12:00:00 AM		
174	SHWS	Carbona Products	330 CALYER STREET BROOKLYN NY 11222	ESE	0.35 / 1,843.12	-2	781
175	MOSF	FORMER MOBIL GREENPOINT TERMINAL	403 GREENPOINT AVENUE BROOKLYN NY 11222	E	0.35 / 1,872.27	-3	782
			***Site ID	Site Status:*** 345008	Unregulated/Closed		
176	SWF/LF	ECONOMY CONTAINER SERVICE	23 ASH ST Brooklyn NY 11222	NNW	0.36 / 1,878.18	-4	783

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
176	SWF/LF	F & P Resources LLC	23 Ash Street Brooklyn NY 11221	NNW	0.36 / 1,878.18	-4	783
177	SHWS	Former NuHart Plastic Manufacturing	65 DUPONT STREET BROOKLYN NY 11222	WNW	0.36 / 1,893.31	1	785
177	BROWNFIELDS	Former NuHart East	65 Dupont Street and 75 Dupont Street Brooklyn NY 11222	WNW	0.36 / 1,893.31	1	789
178	BROWNFIELDS	Clay Properties LLC	19-27 Clay Street and 60-62 Commercial Street Brooklyn NY 11222	WNW	0.36 / 1,893.59	2	794
179	SWF/LF	MANHATTAN AVE. RECYCLING CORP.	1166 MANHATTAN AVE. Brooklyn NY 11222	NW	0.36 / 1,899.59	-2	796
179	SWF/LF	NEW YORK RECYCLERS; INC.(Manhattan Ave)	1166-68 MANHATTAN AVENUE Brooklyn NY 11222	NW	0.36 / 1,899.59	-2	797
180	PFAS IND	PENSATO INDUSTRIES	BROOKLYN NY	NW	0.37 / 1,945.91	-1	798
181	BROWNFIELDS	49 Dupont Street	49 Dupont Street Greenpoint NY 11222	WNW	0.37 / 1,958.11	1	799
182	LST	111 MILTON ST/BKLYN	111 MILTON STREET NEW YORK CITY NY	SW	0.37 / 1,960.32	11	801
			Spill No* | *Close Date: 8911087 | 02/22/1990 12:00:00 AM				
182	LST	111 MILTON STREET	111 MILTON STREET BROOKLYN NY	SW	0.37 / 1,960.32	11	802
			Spill No* | *Close Date: 9312646 | 01/27/1994 12:00:00 AM				
183	LST	DEPT CONSUMER AFFAIRS	245 MESEROLE AVE GREENPOINT BROOKLYN NY	SE	0.37 / 1,974.30	-1	803
			Spill No* | *Close Date: 0305945 | 09/05/2003 12:00:00 AM				
184	SWF/LF	Allocco Recycling Ltd (Kingsland Ave)	540 Kingsland Avenue Brooklyn NY 11222	ENE	0.37 / 1,978.14	-10	804
184	SWF/LF	Allocco Recycling Ltd (Kingsland Ave)	540 Kingsland Avenue Brooklyn NY 11222	ENE	0.37 / 1,978.14	-10	805

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
184	RECYCLING	Allocco Recycling Ltd (Kingsland Ave)	540 Kingsland Avenue Brooklyn NY 11222	ENE	0.37 / 1,978.14	-10	806
185	SHWS	40-56 Commercial Street	40-56 Commercial Street Brooklyn NY 11222	WNW	0.38 / 1,997.25	1	807
186	SHWS	Greenpoint Manuf. and Design Ctr.	1155 Manhattan Avenue Brooklyn NY 11222	NW	0.39 / 2,085.08	-1	809
187	BROWNFIELDS	50 Commercial Street Development	50 and 56 Commercial Street and 15-17 Clay Street Brooklyn NY 11222	WNW	0.41 / 2,142.54	0	811
188	LST	CROSSTOWN ANNEX	65 COMMERCIAL STREET BROOKLYN NY	WNW	0.41 / 2,170.84	-2	814
			Spill No | Close Date: 9011113 | 01/30/2004 12:00:00 AM				
189	BROWNFIELDS	45 Commercial Street	45 Commercial Street Brooklyn NY 11222	WNW	0.41 / 2,175.38	-1	816
189	ENG	45 Commercial Street	45 Commercial Street Brooklyn NY 11222	WNW	0.41 / 2,175.38	-1	820
189	INST	45 Commercial Street	45 Commercial Street Brooklyn NY 11222	WNW	0.41 / 2,175.38	-1	825
190	LST	BULOVA CORPORATION	77 COMMERCIAL STREET BROOKLYN NY	NW	0.41 / 2,188.61	-2	830
			Spill No | Close Date: 0211097 | 04/09/2003 12:00:00 AM				
191	PFAS IND	UNITED METRO ENERGY - BROOKLYN TERMINAL	BROOKLYN NY	E	0.42 / 2,213.55	-5	831
192	PFAS IND	METAL SPECIALTIES-775-797 HUMBOLDT ST	BROOKLYN NY	SE	0.42 / 2,227.52	0	832
193	LST	SIMS METAL MANAGEMENT	30-27 GREENPOINT AVE LONG ISLAND CITY NY	ENE	0.42 / 2,233.84	-10	833
			Spill No | Close Date: 1200318 |			
193	SWF/LF	Sims Metal Management LIC	30-27 Greenpoint Avenue Long Island City NY 11101	ENE	0.42 / 2,233.84	-10	838

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
193	RECYCLING	Sims Metal Management LLC	30-27 Greenpoint Avenue Long Island City NY 11101	ENE	0.42 / 2,233.84	-10	839
193	SWF/LF	Sims Metal Management LLC	30-27 Greenpoint Avenue Long Island City NY 11101	ENE	0.42 / 2,233.84	-10	839
194	LST	37-41 MOULTRIE ST	37-41 MOULTRIE ST BROOKLYN NY	SE	0.43 / 2,247.21	0	840
			Spill No* | *Close Date: 0308536 | 05/06/2005 12:00:00 AM				
195	BROWNFIELDS	23-30 Borden Avenue Development	23-30 BORDEN AVENUE Long Island City NY 11101	NNE	0.43 / 2,281.90	-7	841
195	ENG	23-30 Borden Avenue Development	23-30 BORDEN AVENUE Long Island City NY 11101	NNE	0.43 / 2,281.90	-7	845
195	INST	23-30 Borden Avenue Development	23-30 BORDEN AVENUE Long Island City NY 11101	NNE	0.43 / 2,281.90	-7	849
196	LST	NYC WATER TREATMENT PLANT	NEWTOWN CREEK BROOKLYN NY	N	0.44 / 2,317.12	-9	853
			Spill No* | *Close Date: 9904793 | 07/23/2003 12:00:00 AM				
196	SEMS ARCHIVE	NEWTOWN CREEK SOLVENT DRUM	NEWTOWN CREEK QUEENS NY 11428	N	0.44 / 2,317.12	-9	854
			EPA ID: NYD987015245				
197	PFAS IND	COURIER PACKAGING CO INC	BROOKLYN NY	W	0.44 / 2,326.89	-3	855
198	PFAS	United Metro Energy Corp	500 Kingsland Ave Brooklyn NY	E	0.45 / 2,368.87	-6	856
199	HSWDS	Manhattan Adhesives	425-459 Green Point Avenue Brooklyn 11222 NY	E	0.45 / 2,389.83	-6	856
199	HSWDS	Manhattan Adhesives	425-459 Green Point Avenue Brooklyn NY	E	0.45 / 2,389.83	-6	857
200	CERCLIS	BROOKLYN TERM /MOBIL OIL CORP	300 NORTH HENRY ST BROOKLYN NY 11222	ESE	0.45 / 2,391.25	0	858
			Site EPA ID: NYD000824540				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
200	CERCLIS NFRAP	BROOKLYN TERM /MOBIL OIL CORP	300 NORTH HENRY ST BROOKLYN NY 11222 ***Site EPA ID:*** NYD000824540	ESE	0.45 / 2,391.25	0	860
200	MOSF	EXXON MOBIL OIL CORPORATION BROOKLYN TERMINAL	300 NORTH HENRY STREET Brooklyn NY 11222 ***Site ID | Site Status:*** 344640 | Unregulated/Closed	ESE	0.45 / 2,391.25	0	861
200	LST	MOBIL	300 NORTH HENRY STREET BROOKLYN NY ***Spill No | Close Date:*** 8910558 | 12/03/2003 12:00:00 AM	ESE	0.45 / 2,391.25	0	861
200	LST	MOBIL GREENPOINT	300 NORTH HENRY STREET BROOKLYN NY ***Spill No | Close Date:*** 8800842 | 04/23/2003 12:00:00 AM	ESE	0.45 / 2,391.25	0	862
200	LST	MOBIL GREENPOINT	300 NORTH HENRY STREET BROOKLYN NY ***Spill No | Close Date:*** 8808149 | 09/24/2003 12:00:00 AM	ESE	0.45 / 2,391.25	0	863
200	LST	MOBIL GREENPOINT	300 NORTH HENRY STREET BROOKLYN NY ***Spill No | Close Date:*** 9312129 | 10/16/2002 12:00:00 AM	ESE	0.45 / 2,391.25	0	864
201	CERCLIS	MANHATTAN ADHESIVES PLANT	425-459 GREENPOINT AVENUE BROOKLYN NY 11222 ***Site EPA ID:*** NYD980780811	E	0.45 / 2,401.39	-7	865
201	CERCLIS NFRAP	MANHATTAN ADHESIVES PLANT	425-459 GREENPOINT AVENUE BROOKLYN NY 11222 ***Site EPA ID:*** NYD980780811	E	0.45 / 2,401.39	-7	867
201	SHWS	Former Manhattan Adhesives Plant	425-459 Greenpoint Avenue Brooklyn NY	E	0.45 / 2,401.39	-7	868
201	SEMS ARCHIVE	MANHATTAN ADHESIVES PLANT	425-459 GREENPOINT AVENUE BROOKLYN NY 11222 ***EPA ID:*** NYD980780811	E	0.45 / 2,401.39	-7	870
202	SHWS	Mobil Oil Brooklyn Terminal	300 NORTH HENRY STREET BROOKLYN NY	ESE	0.46 / 2,403.01	0	870
202	SEMS ARCHIVE	BROOKLYN TERM /MOBIL OIL CORP	300 NORTH HENRY ST BROOKLYN NY 11222 ***EPA ID:*** NYD000824540	ESE	0.46 / 2,403.01	0	872
203	MOSF	DITMAS OIL-LONG ISLAND CITY	53-02 11TH ST LONG ISLAND CITY NY 11101	NNW	0.46 / 2,403.46	-8	873

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Site ID*	*Site Status:*** 345056 | Inactive			
204	LST	145 WEST STREET	145 WEST STREET BROOKLYN NY	W	0.46 / 2,411.32	-2	873
			Spill No* | *Close Date: 9408283 | 12/02/1994 12:00:00 AM				
204	LST	145 WEST STREET	145 WEST STREET BROOKLYN NY	W	0.46 / 2,411.32	-2	874
			Spill No* | *Close Date: 9408663 | 12/02/1994 12:00:00 AM				
205	SWF/LF	F.E.S. RECYCLING; INC. (SUMMIT CARTING)	425 GREENPOINT AVE Brooklyn NY 11222	E	0.46 / 2,415.05	-7	875
206	PFAS IND	UNITED BIOFUELS INC - 435 GREENPOINT AVE	BROOKLYN NY	E	0.46 / 2,417.00	-6	876
207	LST	STAGING SCAFFOLDING	25-20 BORDEN AVE LONG ISLAND CITY NY	NE	0.46 / 2,419.10	-7	876
			Spill No* | *Close Date: 0109751 | 07/29/2002 12:00:00 AM				
208	LST	BUSINESS	11-40 BORDEN AVE QUEENS NY	N	0.46 / 2,428.34	-6	877
			Spill No* | *Close Date: 0709037 | 07/24/2008 12:00:00 AM				
209	MOSF	UNITED METRO ENERGY CORP.	498 KINGSLAND AVENUE BROOKLYN NY 11222	E	0.46 / 2,441.00	-10	879
			Site ID* | *Site Status: 344649 | Active				
210	SHWS	58 Greenpoint Ave.-OER	58 Greenpoint Ave. Brooklyn NY 11222	WSW	0.47 / 2,457.49	2	879
211	PFAS IND	KB PROJECTS	BROOKLYN NY	WSW	0.47 / 2,497.74	1	880
212	LST	21-07 BORDEN AVE	21-07 BORDEN AVE QUEENS NY	NNE	0.47 / 2,506.56	-6	881
			Spill No* | *Close Date: 9614479 | 02/25/2003 12:00:00 AM				
213	SWF/LF	AFFIRMATIVE PIPE CLEANING	275 NORTH HENRY Street ?? NY 0	SE	0.48 / 2,514.91	1	882
214	VCP	101-105 West Street	101-105 West Street, Brooklyn Brooklyn NY 11222	WSW	0.48 / 2,532.43	0	882
215	NPL	MEEKER AVENUE PLUME	Meeker Avenue BROOKLYN NY 11222	ESE	0.48 / 2,556.23	2	885

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			EPA ID: NYN000203407				
216	SWF/LF	SUMMIT CARTING CORP	427 Greenpoint Ave Brooklyn NY 11222	E	0.48 / 2,556.34	-10	886
217	LST	51-02 21ST ST	51-02 21ST ST LONG ISLAND CITY NY	N	0.49 / 2,589.47	-4	886
			***Spill No	Close Date:*** 8806127	07/19/2004 12:00:00 AM		
218	SWF/LF	LEXUS TRANSFER AND RECYCLING INC.	3200 RAILROAD AVENUE Long Island city NY 11101	ENE	0.50 / 2,622.32	-7	888
219	SHWS	460 Kingsland Avenue	460 Kingsland Avenue Brooklyn NY 11222	E	0.51 / 2,672.69	-9	888
220	SHWS	Former Spic and Span Cleaners and Dyers Inc.	315 Kingsland Avenue Brooklyn NY 11222	SE	0.62 / 3,266.18	7	891
221	SUPERFUND ROD	NEWTOWN CREEK	SOUTH END OF IVY HILL ROAD BROOKLYN, QUEENS NY 1122	WNW	0.63 / 3,352.04	-12	895
222	SHWS	Former Presto Electroplating	9 North 15th Street Brooklyn NY 11222	SSW	0.65 / 3,412.97	-4	895
223	SHWS	36-04 Review Avenue	36-04 Review Avenue Long Island City NY 11101	E	0.67 / 3,518.37	6	897
224	SHWS	27-10 49th Avenue-OER	27-10 49th Avenue Long Island City NY 11101	NE	0.69 / 3,624.51	1	898
225	RCRA CORRACTS	KOSAN INDUSTRIAL CORP	5-49 49TH AVE LONG ISLAND CITY NY 11101-5610	NNW	0.71 / 3,732.29	3	900
			***EPA Handler ID	Recycler Activity?:*** NYD061949228	NO		
226	SHWS	Williamsburg – Former Pratt Refinery	26 N 12th St. Brooklyn NY 11211	SW	0.76 / 4,003.90	-4	905
227	VAPOR	Quanta Resources	37-80 Review Avenue Long Island City NY 10111	E	0.76 / 4,006.10	11	908
227	RCRA CORRACTS	REVIEW AVENUE DEVELOPMENT II	37-80 REVIEW AVE LONG ISLAND CITY NY 11101	E	0.76 / 4,006.10	11	908

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***EPA Handler ID	Recycler Activity?:*** NYD980592562 | NO			
227	SHWS	Quanta Resources	37-80 Review Avenue Long Island City NY 10111	E	0.76 / 4,006.10	11	915
228	RCRA CORRACTS	ACTIVE STEEL DRUM CO INC	52-30 34TH ST LONG ISLAND CITY NY 11101-3202 ***EPA Handler ID	Recycler Activity?:*** NYD003933355 | NO	ENE	0.77 / 4,069.36	7	919
229	SHWS	Arch Street Yards (LIRR)	Arch Street and Jackson Avenue Long Island City NY 11101	NNE	0.78 / 4,101.06	0	923
230	SHWS	83 Apollo Street OER	83 Apollo Street Brooklyn NY 11222	ESE	0.79 / 4,150.43	20	925
231	SHWS	Former Pratt Refinery	26 N. 12th Street Brooklyn NY 11249	SW	0.80 / 4,200.66	-6	927
232	SHWS	K - Williamsburg Works	Kent Ave & 12th Street Brooklyn NY 11211-	SW	0.81 / 4,269.27	-1	928
232	HSWDS	BUG, Williamsburg Works	Kent Avenue, North 12th Street Brooklyn 11211 NY	SW	0.81 / 4,269.27	-1	930
232	HSWDS	BUG, Williamsburg Works	Kent Avenue, North 12th Street Brooklyn 11211 NY	SW	0.81 / 4,269.27	-1	932
232	HSWDS	BUG, Williamsburg Works	Kent Avenue, North 12th Street Brooklyn 11211 NY	SW	0.81 / 4,269.27	-1	933
232	HSWDS	BUG, Williamsburg Works	Kent Avenue, North 12th Street Brooklyn 11211 NY	SW	0.81 / 4,269.27	-1	934
232	HSWDS	BUG. Williamsburg Works	Kent Avenue. North 12th Street Brooklyn 11211 NY	SW	0.81 / 4,269.27	-1	935
232	MGP	K - Williamsburg Works	Kent Ave & 12th Street Brooklyn NY 11211-	SW	0.81 / 4,269.27	-1	936
233	SHWS	Queens West - South	Center Blvd, 47th Rd, 48th Ave NY 11101	NNW	0.81 / 4,292.69	-7	937

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
234	SHWS	Former Berkman Bros Site	55 Eckford Street Brooklyn NY 11222	SSE	0.82 / 4,318.72	4	938
235	SHWS	Roehr Chemicals, Inc.	52-28 37th Street Long Island City NY 11101	E	0.82 / 4,325.38	21	939
236	SHWS	K - Wythe Ave. Station	Wythe Ave., Berry St., N 12th & 13th St Brooklyn NY 11211	SSW	0.82 / 4,347.68	4	943
236	MGP	K - Wythe Ave. Station	Wythe Ave., Berry St., N 12th & 13th St Brooklyn NY 11211	SSW	0.82 / 4,347.68	4	948
237	SHWS	Brooklyn North 1 Garage	50 Kent Avenue Brooklyn NY 11211	SW	0.83 / 4,359.31	-3	949
238	SHWS	Former Prestone Press	47-50 30TH STREET Long Island City NY 11101	ENE	0.85 / 4,477.54	-1	951
239	HSWDS	Peerless Property	3850 Review Ave. Long Island City 11101 NY	E	0.88 / 4,647.34	16	953
240	RCRA CORRACTS	OCONNER CAPITAL PARTNERS	5-36 46TH ROAD QUEENS NY 11101	NNW	0.88 / 4,647.64	-2	954
			EPA Handler ID | Recycler Activity?: NYD001264191 | NO				
241	SHWS	Former Green and White Cleaners	47-46 30th Street Long Island City NY 11101	ENE	0.88 / 4,657.31	-1	961
242	HSWDS	BUG, Peoples Works	Kent Ave. Brooklyn 11211 NY	SW	0.89 / 4,673.65	3	962
242	HSWDS	BUG, Peoples Works	Kent Ave. Brooklyn 11211 NY	SW	0.89 / 4,673.65	3	963
242	HSWDS	BUG, Peoples Works	Kent Ave. Brooklyn 11211 NY	SW	0.89 / 4,673.65	3	964
242	HSWDS	BUG, Peoples Works	Kent Ave. Brooklyn 11211 NY	SW	0.89 / 4,673.65	3	965

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
243	FUDS	NAVY FIRE FIGHTING SCH	NO CITY NY ***FUDS Property No:*** C02NY1088	SSW	0.90 / 4,775.99	13	966
244	MGP	K - Peoples Works	Kent Ave. S. 10th St., S. 11th St. Brooklyn NY 11211	SW	0.91 / 4,786.58	3	967
245	SHWS	Empire Varnish Company, Inc.	38 VARICK STREET BROOKLYN NY 11222	ESE	0.92 / 4,846.60	15	968
246	SHWS	Meeker Avenue Plume Trackdown	Meeker Avenue Brooklyn NY 11222	ESE	0.92 / 4,871.97	24	971
247	SHWS	Kent Terminal	Kent Ave. between 5th-11th St. Brooklyn NY 11211	SW	0.98 / 5,172.53	-1	973
248	SHWS	Queens West - North	46-00 FIFTH STREET LONG ISLAND CITY NY 11101	NNW	0.99 / 5,225.90	-7	974

Executive Summary: Summary by Data Source

Standard

Federal

NPL - National Priority List

A search of the NPL database, dated Sep 25, 2024 has found that there are 2 NPL site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MEEKER AVENUE PLUME	Meeker Avenue BROOKLYN NY 11222 ***EPA ID**: NYN000203407*	ESE	0.48 / 2,556.23	215

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEWTOWN CREEK	SOUTH END OF IVY HILL ROAD BROOKLYN, QUEENS NY 11222 ***EPA ID**: NYN000206282*	E	0.21 / 1,121.54	136

SEMS - SEMS List 8R Active Site Inventory

A search of the SEMS database, dated Oct 24, 2024 has found that there are 1 SEMS site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
FORTUNE METALS INC.	239 INDIA STREET BROOKLYN NY 11222 ***EPA ID**: NYR000170555*	ESE	0.04 / 226.31	27

SEMS ARCHIVE - SEMS List 8R Archive Sites

A search of the SEMS ARCHIVE database, dated Oct 24, 2024 has found that there are 4 SEMS ARCHIVE site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BROOKLYN TERM /MOBIL OIL CORP	300 NORTH HENRY ST BROOKLYN NY 11222 ***EPA ID**: NYD000824540*	ESE	0.46 / 2,403.01	202

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
FOX & LONDON INC.	21 PROVOST ST BROOKLYN NY 11222 ***EPA ID**: NYN000206649*	SE	0.14 / 741.58	82

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEWTOWN CREEK SOLVENT DRUM	NEWTOWN CREEK QUEENS NY 11428 ***EPA ID**: NYD987015245*	N	0.44 / 2,317.12	**196**
MANHATTAN ADHESIVES PLANT	425-459 GREENPOINT AVENUE BROOKLYN NY 11222 ***EPA ID**: NYD980780811*	E	0.45 / 2,401.39	**201**

CERCLIS - Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS

A search of the CERCLIS database, dated Oct 25, 2013 has found that there are 4 CERCLIS site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
FORTUNE METALS INC.	239 INDIA STREET BROOKLYN NY 11222 ***Site EPA ID**: NYR000170555*	ESE	0.04 / 208.00	**22**
BROOKLYN TERM /MOBIL OIL CORP	300 NORTH HENRY ST BROOKLYN NY 11222 ***Site EPA ID**: NYD000824540*	ESE	0.45 / 2,391.25	**200**

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
FOX & LONDON INC.	21 PROVOST ST BROOKLYN NY 11222 ***Site EPA ID**: NYN000206649*	SE	0.14 / 741.69	**83**
MANHATTAN ADHESIVES PLANT	425-459 GREENPOINT AVENUE BROOKLYN NY 11222 ***Site EPA ID**: NYD980780811*	E	0.45 / 2,401.39	**201**

CERCLIS NFRAP - CERCLIS - No Further Remedial Action Planned

A search of the CERCLIS NFRAP database, dated Oct 25, 2013 has found that there are 2 CERCLIS NFRAP site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BROOKLYN TERM /MOBIL OIL CORP	300 NORTH HENRY ST BROOKLYN NY 11222 ***Site EPA ID**: NYD000824540*	ESE	0.45 / 2,391.25	**200**

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
MANHATTAN ADHESIVES PLANT	425-459 GREENPOINT AVENUE BROOKLYN NY 11222 ***Site EPA ID**: NYD980780811*	E	0.45 / 2,401.39	**201**

RCRA CORRACTS - RCRA CORRACTS-Corrective Action

A search of the RCRA CORRACTS database, dated Oct 21, 2024 has found that there are 4 RCRA CORRACTS site(s) within

approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
KOSAN INDUSTRIAL CORP	5-49 49TH AVE LONG ISLAND CITY NY 11101-5610	NNW	0.71 / 3,732.29	225
	***EPA Handler ID | Recycler Activity?**: NYD061949228 | NO*			
REVIEW AVENUE DEVELOPMENT II	37-80 REVIEW AVE LONG ISLAND CITY NY 11101	E	0.76 / 4,006.10	227
	***EPA Handler ID | Recycler Activity?**: NYD980592562 | NO*			
ACTIVE STEEL DRUM CO INC	52-30 34TH ST LONG ISLAND CITY NY 11101-3202	ENE	0.77 / 4,069.36	228
	***EPA Handler ID | Recycler Activity?**: NYD003933355 | NO*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
OCONNER CAPITAL PARTNERS	5-36 46TH ROAD QUEENS NY 11101	NNW	0.88 / 4,647.64	240
	***EPA Handler ID | Recycler Activity?**: NYD001264191 | NO*			

RCRA LQG - RCRA Generator List

A search of the RCRA LQG database, dated Oct 21, 2024 has found that there are 12 RCRA LQG site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
CON EDISON - MANHOLE 8545	234 GREEN ST BROOKLYN NY 11222	NW	0.01 / 48.43	5
	***EPA Handler ID | Recycler Activity?**: NYP004296745 | NO*			
CON EDISON - SERVICE BOX 7507	250 HURON ST BROOKLYN NY 11222	SE	0.02 / 115.13	11
	***EPA Handler ID | Recycler Activity?**: NYP005050018 | NO*			
CON EDISON - MANHOLE 752	S/S HURON ST 25` E/O MCGUINESS BLVD BROOKLYN NY 11205 ***EPA Handler ID | Recycler Activity?**: NYP004151916 | NO*	WSW	0.03 / 177.40	19
CON EDISON - SERVICE BOX 7508	256 HURON ST BROOKLYN NY 11222	ESE	0.04 / 208.03	23
	***EPA Handler ID | Recycler Activity?**: NYP005050042 | NO*			
MTA NYCT GREEN STREET SUBSTATION	GREEN ST & MANHATTAN AVE BROOKLYN NY 11222	W	0.17 / 910.86	104
	***EPA Handler ID | Recycler Activity?**: NYR000076620 | NO*			
CON EDISON - TRANSFORMER MANHOLE 658	120 DUPONT ST & MANHATTAN AVE BROOKLYN NY 11222	WNW	0.23 / 1,195.38	143
	***EPA Handler ID | Recycler Activity?**: NYP004871584 | NO*			
CON EDISON - MANHOLE 4328	MANHATTAN AVE & KENT ST INT BROOKLYN NY 11222	SW	0.23 / 1,230.05	147

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	***EPA Handler ID | Recycler Activity?**: NYP005151725 | NO*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CON EDISON - MANHOLE 4307	PROVOST ST BROOKLYN NY 11222	E	0.07 / 354.25	40
	***EPA Handler ID | Recycler Activity?**: NYP004290326 | NO*			
CON EDISON - TRANSFORMER MANHOLE 2275	JAVA ST & PROVOST ST NEW YORK NY 10017	SE	0.12 / 657.97	78
	***EPA Handler ID | Recycler Activity?**: NYP004869271 | NO*			
WALLCOTE PAINT CO	208 DUPONT ST BROOKLYN NY 11222	N	0.15 / 786.45	86
	***EPA Handler ID | Recycler Activity?**: NYD001289131 | NO*			
CON EDISON - TRANSFORMER MANHOLE 753	253 GREENPOINT AVE BROOKLYN NY 11222	SSE	0.18 / 964.07	111
	***EPA Handler ID | Recycler Activity?**: NYP005133897 | NO*			
NYCDOT CONTRACT #HB107000GP & L & L PAINTING CO INC	GREENPOINT AVE BR NEWTOWN CREEK BROOKLYN NY 11232	SSE	0.20 / 1,080.52	126
	***EPA Handler ID | Recycler Activity?**: NYR000199448 | NO*			

RCRA SQG - RCRA Small Quantity Generators List

A search of the RCRA SQG database, dated Oct 21, 2024 has found that there are 5 RCRA SQG site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
J&J BRONZE & ALUMINUM CASTING CORP	249 HURON ST BROOKLYN NY 11222	SSW	0.00 / 0.00	2
	***EPA Handler ID**: NYR000154658*			
NUVITE CHEMICAL	213 FREEMAN ST BROOKLYN NY 11222	NW	0.10 / 527.09	60
	***EPA Handler ID**: NYR000154708*			
MTA NYCT - CROSSTOWN LINE I G LINE	INDIA ST & MANHATTAN AVE TO CHURCH & MCDONALD AVES BROOKLYN NY 11218 ***EPA Handler ID**: NYR000229195*	WSW	0.18 / 948.49	109
MTA NYCT - GREENPOINT TUBE	INDIA ST & MANHATTAN AVE JACKSON AVE & 47TH RD BROOKLYN NY 11222 ***EPA Handler ID**: NYR000208231*	WSW	0.18 / 948.49	109

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NYCDEP BWT NEWTOWN CREEK WPCP	329 GREENPOINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	77

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	***EPA Handler ID**: NYD980779730*			

RCRA VSQG - RCRA Very Small Quantity Generators List

A search of the RCRA VSQG database, dated Oct 21, 2024 has found that there are 4 RCRA VSQG site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
FORTUNE METAL INC	239 INDIA ST BROOKLYN NY 11222	ESE	0.04 / 208.03	23
	***EPA Handler ID	Recycler Activity?**: NYR000170555	NO*		
PULASKI SVC STA	321 MCGUINESS BLVD BROOKLYN NY 11222-1817	W	0.05 / 250.88	30
	***EPA Handler ID	Recycler Activity?**: NYD095772919	NO*		
NUVITE CHEMICAL COMPOUNDS CO	213 FREEMAN STREET BROOKLYN NY 11222	NW	0.10 / 527.09	60
	***EPA Handler ID	Recycler Activity?**: NYN008016354	NO*		
SPEEDWAY 7821	210 GREENPOINT AVE BROOKLYN NY 11222-2304	S	0.22 / 1,184.97	140
	***EPA Handler ID	Recycler Activity?**: NYD982185944	NO*		

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Oct 21, 2024 has found that there are 62 RCRA NON GEN site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
C C BODY SHOP	230 GREEN ST BROOKLYN NY 11222	NW	0.01 / 49.28	6
	***EPA Handler ID	Recycler Activity?**: NYR000046607	NO*		
MCGUINNESS MANAGEMENT	330 MCGUINNESS BLVD BROOKLYN NY 11222-1820	W	0.02 / 117.25	13
	***EPA Handler ID	Recycler Activity?**: NYR000141853	NO*		
CON EDISON	237 INDIA ST BROOKLYN NY 11222	ESE	0.05 / 269.11	31
	***EPA Handler ID	Recycler Activity?**: NYP004804605	NO*		
CON EDISON	237 INDIA ST BROOKLYN NY 11222	ESE	0.05 / 269.11	31
	***EPA Handler ID	Recycler Activity?**: NYP004798435	NO*		
CON EDISON SERVICE BOX: 8385	346 MCGUINESS BROOKLYN NY 11222	NW	0.05 / 281.89	33
	***EPA Handler ID	Recycler Activity?**: NYP004361838	NO*		
CON EDISON SERVICE BOX: 8385	348 MCGUINESS BLVD BROOKLYN NY 11222	NW	0.06 / 306.84	35

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	***EPA Handler ID | Recycler Activity?**: NYP004349015 | NO*			
CON EDISON	242 FREEMAN ST BROOKLYN NY 11222	NNW	0.06 / 308.72	36
	***EPA Handler ID | Recycler Activity?**: NYP004725644 | NO*			
CON EDISON SERVICE BOX: 56190	239 JAVA ST BROOKLYN NY 11222	SSE	0.08 / 410.45	49
	***EPA Handler ID | Recycler Activity?**: NYP004474466 | NO*			
NYCDOT PULASKI BRIDGE OVER NEWTOWN CREEK	MCGUINESS & FREEMAN BKLYN 11TH ST & JACKSON AVE QUEEN BROOKLYN NY 11222 ***EPA Handler ID | Recycler Activity?**: NYD986993558 | NO*	NW	0.08 / 448.30	52
CON EDISON MANHOLE: 7527	184 INDIA ST BROOKLYN NY 11222	SW	0.09 / 477.45	56
	***EPA Handler ID | Recycler Activity?**: NYP004345583 | NO*			
CON EDISON	JAVA ST & MCGUINESS BLVD BROOKLYN NY 11234	SSW	0.11 / 581.54	68
	***EPA Handler ID | Recycler Activity?**: NYP004791919 | NO*			
CON EDISON	234 JAVA ST BROOKLYN NY 11222	SSE	0.12 / 621.01	70
	***EPA Handler ID | Recycler Activity?**: NYP004847406 | NO*			
CON EDISON	230 JAVA ST & MCGUINESS BLVD BROOKLYN NY 11235	S	0.12 / 632.43	72
	***EPA Handler ID | Recycler Activity?**: NYP004798765 | NO*			
GREENPOINT NATIONAL GARAGE INC	276 MCGUINNESS BLVD BROOKLYN NY 11222-1811	S	0.12 / 637.70	74
	***EPA Handler ID | Recycler Activity?**: NY0000080176 | NO*			
CON EDISON SERVICE BOX: 8198	237 KENT ST BROOKLYN NY 11222	SSE	0.14 / 734.14	81
	***EPA Handler ID | Recycler Activity?**: NYP004312948 | NO*			
NORIS METAL	231 KENT ST BROOKLYN NY 11222	S	0.14 / 752.66	84
	***EPA Handler ID | Recycler Activity?**: NYR000194705 | NO*			
CON EDISON	209 KENT ST BROOKLYN NY 11222	SSW	0.15 / 804.84	87
	***EPA Handler ID | Recycler Activity?**: NYP004790705 | NO*			
CON EDISON SERVICE BOX: 8461	183 FREEMAN ST BROOKLYN NY 11222	WNW	0.16 / 841.11	94
	***EPA Handler ID | Recycler Activity?**: NYP004443081 | NO*			
CON EDISON SERVICE BOX: 08458	181 FREEMAN ST BROOKLYN NY 11222	WNW	0.16 / 862.19	98

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	***EPA Handler ID | Recycler Activity?**: NYP004443073 | NO*			
KELLY CLEANERS	1036 MANHATTAN AVE BROOKLYN NY 11222-1316	W	0.16 / 864.41	99
	***EPA Handler ID | Recycler Activity?**: NYD049146186 | NO*			
CON EDISON	210 KENT ST BROOKLYN NY 11222	SSW	0.17 / 893.32	101
	***EPA Handler ID | Recycler Activity?**: NYP004798203 | NO*			
SHELL OIL CO	256 MCGUINNES BLVD BROOKLYN NY 11222-1809	S	0.17 / 918.56	105
	***EPA Handler ID | Recycler Activity?**: NYD987008166 | NO*			
APHRODITE CLEANER	1019 MANHATTAN AVE BROOKLYN NY 11222	W	0.18 / 969.82	112
	***EPA Handler ID | Recycler Activity?**: NYD987003795 | NO*			
NYC FIRE DEPT ENGINE CO 238	205 GREENPOINT AVE BROOKLYN NY 11222-2407	S	0.19 / 1,000.18	117
	***EPA Handler ID | Recycler Activity?**: NYR000040428 | NO*			
CON EDISON SERVICE BOX: 8139	207 GREENPOINT AVE BROOKLYN NY 11222	S	0.19 / 1,000.18	117
	***EPA Handler ID | Recycler Activity?**: NYP004434239 | NO*			
CON EDISION - MH61605	MANHATTAN AVE NORTH OF JAVA MA NEW YORK NY 10003	WSW	0.20 / 1,059.19	123
	***EPA Handler ID | Recycler Activity?**: NYP004084406 | NO*			
CON EDISON VAULT SUBMERSIBLE: 3826	NEWELL ST & GREEN POINT AVE 205 FEET S OF BROOKLYN NY 11222	SSE	0.20 / 1,076.47	125
	***EPA Handler ID | Recycler Activity?**: NYP004431961 | NO*			
CON EDISON	173 GREENPOINT AVE BROOKLYN NY 11222	SSW	0.21 / 1,103.40	133
	***EPA Handler ID | Recycler Activity?**: NYP004788030 | NO*			
CON EDISON	167 GREENPOINT AVE BROOKLYN NY 11222	SSW	0.22 / 1,137.28	138
	***EPA Handler ID | Recycler Activity?**: NYP004807921 | NO*			
R & S STRAUSS	235 MCGUINESS BLVD BROOKLYN NY 11222-2305	S	0.22 / 1,184.97	140
	***EPA Handler ID | Recycler Activity?**: NYR000025619 | NO*			
CON EDISON SERVICE BOX: 8624	143 JAVA ST BROOKLYN NY 11222	WSW	0.23 / 1,191.50	142
	***EPA Handler ID | Recycler Activity?**: NYP004311346 | NO*			
CON EDISON SERVICE BOX: 08133	157 GREENPOINT AVE BROOKLYN NY 11222	SW	0.23 / 1,203.56	145

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	***EPA Handler ID | Recycler Activity?**: NYP004441994 | NO*			
CON EDISON	916 MANHATTAN AVE BROOKLYN NY 11222	SW	0.23 / 1,209.65	146
	***EPA Handler ID | Recycler Activity?**: NYP004736971 | NO*			
CON EDISON	178 GREENPOINT AVE BROOKLYN NY 11235	SSW	0.24 / 1,272.25	152
	***EPA Handler ID | Recycler Activity?**: NYP004802682 | NO*			
CON EDISON	131 EAGLE ST BROOKLYN NY 11222	WNW	0.24 / 1,280.75	153
	***EPA Handler ID | Recycler Activity?**: NYP004884124 | NO*			
CON EDISON	132 HURON ST BROOKLYN NY 11222	W	0.25 / 1,310.09	155
	***EPA Handler ID | Recycler Activity?**: NYP004813750 | NO*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CINER CHEMICAL & REFINING CO INC	247 GREEN ST BROOKLYN NY 11222	NNE	0.04 / 206.80	21
	***EPA Handler ID | Recycler Activity?**: NYD046821070 | NO*			
REPUBLIC METALS CO INC	273 GREEN ST BROOKLYN NY 11222-1207	NE	0.08 / 398.70	47
	***EPA Handler ID | Recycler Activity?**: NYD001213156 | NO*			
BAY CRANE SERVICE INC	255 FREEMAN ST BROOKLYN NY 11222	N	0.09 / 470.39	55
	***EPA Handler ID | Recycler Activity?**: NYR000046383 | NO*			
CON EDISON SERVICE BOX: 7251	220 EAGLE ST BROOKLYN NY 11222	N	0.11 / 569.08	66
	***EPA Handler ID | Recycler Activity?**: NYP004395091 | NO*			
CON EDISON - NEWTOWN CRK WTR POLL PLT	329 GREENPOINT AVE ELECTRIC SERVICE AREA BROOKLYN NY 11222-1901	NE	0.12 / 649.95	77
	***EPA Handler ID | Recycler Activity?**: NY0000228049 | NO*			
EXXON CO USA-BROOKLYN TERMINAL	320 FREEMAN ST BROOKLYN NY 11222-1213	NE	0.12 / 649.95	77
	***EPA Handler ID | Recycler Activity?**: NYD063855746 | NO*			
CON ED - MH 4308	JAVA ST & PROVOST ST BROOKLYN NY 11222-0000	SE	0.12 / 657.97	78
	***EPA Handler ID | Recycler Activity?**: NYP004008553 | NO*			
SKANSKA PICONE III JV	252 JAVA ST AKA 259 KENT ST BROOKLYN NY 11222	SE	0.14 / 716.58	79
	***EPA Handler ID | Recycler Activity?**: NYR000212837 | NO*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CON EDISON SERVICE BOX: 7252	227 EAGLE ST BROOKLYN NY 11222	N	0.14 / 729.78	80
	***EPA Handler ID | Recycler Activity?**: NYP004427720 | NO*			
FOX & LONDON INC	21 PROVOST AVE BROOKLYN NY 11222-1813	SE	0.14 / 741.69	83
	***EPA Handler ID | Recycler Activity?**: NYN008010340 | NO*			
CON EDISON	185 EAGLE ST BROOKLYN NY 11222	NW	0.15 / 806.77	88
	***EPA Handler ID | Recycler Activity?**: NYP004758488 | NO*			
CONSOLIDATED SMELTING	25 PROVOST AVE BROOKLYN NY 11222-1813	SE	0.16 / 824.03	91
	***EPA Handler ID | Recycler Activity?**: NYN008010332 | NO*			
CON EDISON SERVICE BOX: 8381	382 MCGUINESS BLVD BROOKLYN NY 11222	NNW	0.16 / 839.56	93
	***EPA Handler ID | Recycler Activity?**: NYP004389508 | NO*			
CON EDISON	177 EAGLE ST BROOKLYN NY 11222	NW	0.16 / 854.90	96
	***EPA Handler ID | Recycler Activity?**: NYP004809731 | NO*			
AMSCOR INC	188 DUPONT ST BROOKLYN NY 11222	NNW	0.17 / 879.82	100
	***EPA Handler ID | Recycler Activity?**: NYD986909612 | NO*			
CON EDISION - TM615	DUPONT ST. AND MCGUINESS BLVD. NEW YORK NY 10003	NW	0.18 / 947.45	108
	***EPA Handler ID | Recycler Activity?**: NYP004082608 | NO*			
GREENSPAN & KUSHLIN ENGRAVING CORP	223 GREENPOINT AVE BROOKLYN NY 11222	SSE	0.19 / 988.30	116
	***EPA Handler ID | Recycler Activity?**: NYR000097212 | NO*			
CON EDISON SERVICE BOX: 08140	223 GREENPOINT AVE BROOKLYN NY 11222	SSE	0.19 / 988.30	116
	***EPA Handler ID | Recycler Activity?**: NYP004575627 | NO*			
CON EDISON	223 GREEENPOINT AVE & MCGUINNESS BLVD BROOKLYN NY 11222	SSE	0.19 / 988.30	116
	***EPA Handler ID | Recycler Activity?**: NYP004183224 | NO*			
INTERFLO TECHNOLOGIES	393 MCGUINNESS BLVD BROOKLYN NY 11222	NW	0.20 / 1,038.67	122
	***EPA Handler ID | Recycler Activity?**: NY0000441139 | NO*			
CON EDISON	91 PAIDGE AVE & PROVOST ST BROOKLYN NY 11222	NE	0.21 / 1,088.91	129
	***EPA Handler ID | Recycler Activity?**: NYP004183273 | NO*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CON EDISON MANHOLE: 55218	PAIDGE PL 300 FT S OF PROVOST ST E SIDE BROOKLYN NY 11201 ***EPA Handler ID | Recycler Activity?**: NYP004279113 | NO*	NNE	0.21 / 1,096.86	132
VERIZON	GREEN POINT AVE & JEWEL ST INTERSECTION OF BROOKLYN NY 11222 ***EPA Handler ID | Recycler Activity?**: NYP000965772 | NO*	SE	0.22 / 1,175.86	139
VERIZON	GREENPOINT AVE & JEWEL ST INTERSECTION OF BROOKLYN NY 11222 ***EPA Handler ID | Recycler Activity?**: NYP000965707 | NO*	SE	0.22 / 1,175.86	139
CON EDISON	GREENPOINT AVE & JEWEL ST BROOKLYN NY 11235 ***EPA Handler ID | Recycler Activity?**: NYP004792594 | NO*	SE	0.22 / 1,175.86	139
CON EDISON MANHOLE: 8172	213 JEWEL ST BROOKLYN NY 11222 ***EPA Handler ID | Recycler Activity?**: NYP004289914 | NO*	SE	0.23 / 1,202.31	144

HIST GAS STATIONS - Historical Gas Stations

A search of the HIST GAS STATIONS database, dated Jul 1, 1930 has found that there are 1 HIST GAS STATIONS site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Crew Levick Co.	267 Green Ave Brooklyn NY	NNW	0.03 / 146.61	17

BULK TERMINAL - Petroleum Product and Crude Oil Rail Terminals

A search of the BULK TERMINAL database, dated Jun 6, 2024 has found that there are 1 BULK TERMINAL site(s) within approximately 0.25miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
SUNOCO MIDSTREAM LLC	BROOKLYN NY	N	0.24 / 1,244.06	149

SUPERFUND ROD - Superfund Decision Documents

A search of the SUPERFUND ROD database, dated Oct 24, 2024 has found that there are 1 SUPERFUND ROD site(s) within approximately 1.00miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEWTOWN CREEK	SOUTH END OF IVY HILL ROAD BROOKLYN, QUEENS NY 1122	WNW	0.63 / 3,352.04	221

State

SHWS - Registry of Inactive Hazardous Waste Disposal Sites in New York State

A search of the SHWS database, dated Nov 5, 2024 has found that there are 31 SHWS site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Former NuHart Plastic Manufacturing	65 DUPONT STREET BROOKLYN NY 11222	WNW	0.36 / 1,893.31	177
40-56 Commercial Street	40-56 Commercial Street Brooklyn NY 11222	WNW	0.38 / 1,997.25	185
Mobil Oil Brooklyn Terminal	300 NORTH HENRY STREET BROOKLYN NY	ESE	0.46 / 2,403.01	202
58 Greenpoint Ave.-OER	58 Greenpoint Ave. Brooklyn NY 11222	WSW	0.47 / 2,457.49	210
Former Spic and Span Cleaners and Dyers Inc.	315 Kingsland Avenue Brooklyn NY 11222	SE	0.62 / 3,266.18	220
36-04 Review Avenue	36-04 Review Avenue Long Island City NY 11101	E	0.67 / 3,518.37	223
27-10 49th Avenue-OER	27-10 49th Avenue Long Island City NY 11101	NE	0.69 / 3,624.51	224
Quanta Resources	37-80 Review Avenue Long Island City NY 10111	E	0.76 / 4,006.10	227
Arch Street Yards (LIRR)	Arch Street and Jackson Avenue Long Island City NY 11101	NNE	0.78 / 4,101.06	229
83 Apollo Street OER	83 Apollo Street Brooklyn NY 11222	ESE	0.79 / 4,150.43	230
Former Berkman Bros Site	55 Eckford Street Brooklyn NY 11222	SSE	0.82 / 4,318.72	234
Roehr Chemicals, Inc.	52-28 37th Street Long Island City NY 11101	E	0.82 / 4,325.38	235

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
K - Wythe Ave. Station	Wythe Ave., Berry St., N 12th & 13th St Brooklyn NY 11211	SSW	0.82 / 4,347.68	236
Empire Varnish Company, Inc.	38 VARICK STREET BROOKLYN NY 11222	ESE	0.92 / 4,846.60	245
Meeker Avenue Plume Trackdown	Meeker Avenue Brooklyn NY 11222	ESE	0.92 / 4,871.97	246

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Former Ney Smelting and Refining Company	269 Freeman Street Greenpoint NY 11222	NNE	0.10 / 553.45	63
Box Street GW	Box Street btw Manhattan Ave and McGuinness Blvd Brooklyn NY 11222	NW	0.29 / 1,537.99	161
Carbona Products	330 CALYER STREET BROOKLYN NY 11222	ESE	0.35 / 1,843.12	174
Greenpoint Manuf. and Design Ctr.	1155 Manhattan Avenue Brooklyn NY 11222	NW	0.39 / 2,085.08	186
Former Manhattan Adhesives Plant	425-459 Greenpoint Avenue Brooklyn NY	E	0.45 / 2,401.39	201
460 Kingsland Avenue	460 Kingsland Avenue Brooklyn NY 11222	E	0.51 / 2,672.69	219
Former Presto Electroplating	9 North 15th Street Brooklyn NY 11222	SSW	0.65 / 3,412.97	222
Williamsburg – Former Pratt Refinery	26 N 12th St. Brooklyn NY 11211	SW	0.76 / 4,003.90	226
Former Pratt Refinery	26 N. 12th Street Brooklyn NY 11249	SW	0.80 / 4,200.66	231
K - Williamsburg Works	Kent Ave & 12th Street Brooklyn NY 11211-	SW	0.81 / 4,269.27	232

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Queens West - South	Center Blvd, 47th Rd, 48th Ave NY 11101	NNW	0.81 / 4,292.69	233
Brooklyn North 1 Garage	50 Kent Avenue Brooklyn NY 11211	SW	0.83 / 4,359.31	237
Former Prestone Press	47-50 30TH STREET Long Island City NY 11101	ENE	0.85 / 4,477.54	238
Former Green and White Cleaners	47-46 30th Street Long Island City NY 11101	ENE	0.88 / 4,657.31	241
Kent Terminal	Kent Ave. between 5th-11th St. Brooklyn NY 11211	SW	0.98 / 5,172.53	247
Queens West - North	46-00 FIFTH STREET LONG ISLAND CITY NY 11101	NNW	0.99 / 5,225.90	248

HSWDS - Hazardous Substance Waste Disposal Sites

A search of the HSWDS database, dated Oct 24, 2003 has found that there are 12 HSWDS site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Peerless Property	3850 Review Ave. Long Island City 11101 NY	E	0.88 / 4,647.34	239
BUG, Peoples Works	Kent Ave. Brooklyn 11211 NY	SW	0.89 / 4,673.65	242
BUG, Peoples Works	Kent Ave. Brooklyn 11211 NY	SW	0.89 / 4,673.65	242
BUG, Peoples Works	Kent Ave. Brooklyn 11211 NY	SW	0.89 / 4,673.65	242
BUG, Peoples Works	Kent Ave. Brooklyn 11211 NY	SW	0.89 / 4,673.65	242

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Manhattan Adhesives	425-459 Green Point Avenue Brooklyn 11222 NY	E	0.45 / 2,389.83	199
Manhattan Adhesives	425-459 Green Point Avenue Brooklyn NY	E	0.45 / 2,389.83	199
BUG, Williamsburg Works	Kent Avenue, North 12th Street Brooklyn 11211 NY	SW	0.81 / 4,269.27	232
BUG, Williamsburg Works	Kent Avenue, North 12th Street Brooklyn 11211 NY	SW	0.81 / 4,269.27	232
BUG, Williamsburg Works	Kent Avenue, North 12th Street Brooklyn 11211 NY	SW	0.81 / 4,269.27	232
BUG, Williamsburg Works	Kent Avenue, North 12th Street Brooklyn 11211 NY	SW	0.81 / 4,269.27	232
BUG. Williamsburg Works	Kent Avenue. North 12th Street Brooklyn 11211 NY	SW	0.81 / 4,269.27	232

VAPOR - Vapor Intrusion Legacy Site List

A search of the VAPOR database, dated Jul 18, 2024 has found that there are 1 VAPOR site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Quanta Resources	37-80 Review Avenue Long Island City NY 10111	E	0.76 / 4,006.10	227

SWF/LF - Solid Waste Facilities and Landfills

A search of the SWF/LF database, dated Aug 17, 2023 has found that there are 22 SWF/LF site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Fortune Metal	239 India Street Brooklyn NY 11222	ESE	0.04 / 208.03	23
Fortune Metal	239 India Street Brooklyn NY 11222	ESE	0.04 / 208.03	23

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
AFFIRMATIVE PIPE CLEANING	275 NORTH HENRY Street ?? NY 0	SE	0.48 / 2,514.91	213

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
MICHAEL FERONE (BRICK) CO.	247 GREENE ST Brooklyn NY 11222	NNE	0.04 / 206.80	21
PRONTO DEMOLITION CORP.	73 PROVOST ST Brooklyn NY 11222	E	0.05 / 274.97	32
POLYSTYRENE RECYCLING; INC.	220 DUPONT STREET Brooklyn NY 11222	NNE	0.15 / 814.69	90
Perez Interboro Asphalt C	99 Paidge Avenue Brooklyn NY 0	NE	0.26 / 1,371.75	157
Greenpoint Scrap Metal	304 Greenpoint Avenue Brooklyn NY 11222	SE	0.27 / 1,403.94	159
DSNY Greenpoint Household Drop-Off	459 NORTH HENRY ST. (NEWTOWN CREEK IN GREENPOINT) Brooklyn NY 11222	ENE	0.31 / 1,640.16	162
DSNY Greenpoint Household Drop-Off	459 NORTH HENRY ST. (NEWTOWN CREEK IN GREENPOINT) Brooklyn NY 11222	ENE	0.31 / 1,640.16	162
Rapid Processing (Humboldt Ave Brooklyn)	860 Humboldt Street Brooklyn NY 11222	ESE	0.32 / 1,684.11	165
ECONOMY CONTAINER SERVICE	23 ASH ST Brooklyn NY 11222	NNW	0.36 / 1,878.18	176
F & P Resources LLC	23 Ash Street Brooklyn NY 11221	NNW	0.36 / 1,878.18	176
MANHATTAN AVE. RECYCLING CORP.	1166 MANHATTAN AVE. Brooklyn NY 11222	NW	0.36 / 1,899.59	179

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEW YORK RECYCLERS; INC. (Manhattan Ave)	1166-68 MANHATTAN AVENUE Brooklyn NY 11222	NW	0.36 / 1,899.59	179
Allocco Recycling Ltd (Kingsland Ave)	540 Kingsland Avenue Brooklyn NY 11222	ENE	0.37 / 1,978.14	184
Allocco Recycling Ltd (Kingsland Ave)	540 Kingsland Avenue Brooklyn NY 11222	ENE	0.37 / 1,978.14	184
Sims Metal Management LIC	30-27 Greenpoint Avenue Long Island City NY 11101	ENE	0.42 / 2,233.84	193
Sims Metal Management LLC	30-27 Greenpoint Avenue Long Island City NY 11101	ENE	0.42 / 2,233.84	193
F.E.S. RECYCLING; INC. (SUMMIT CARTING)	425 GREENPOINT AVE Brooklyn NY 11222	E	0.46 / 2,415.05	205
SUMMIT CARTING CORP	427 Greenpoint Ave Brooklyn NY 11222	E	0.48 / 2,556.34	216
LEXUS TRANSFER AND RECYCLING INC.	3200 RAILROAD AVENUE Long Island city NY 11101	ENE	0.50 / 2,622.32	218

OER CLEANUP - NYC OER Cleanup Sites

A search of the OER CLEANUP database, dated Oct 22, 2024 has found that there are 13 OER CLEANUP site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
996 Manhattan Avenue	996 Manhattan Avenue Brooklyn NY	W	0.15 / 812.54	89
1026-1030 MANHATTAN AVENUE	1026-1030 MANHATTAN AVENUE Brooklyn NY	W	0.16 / 853.83	95
1048 MANHATTAN AVENUE	1048 MANHATTAN AVENUE Brooklyn NY	WNW	0.18 / 932.41	107
1050-1066 Manhattan Avenue	1050 Manhattan Avenue Brooklyn NY	WNW	0.18 / 972.99	113

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
946 Manhattan Avenue/160 Java Street	946 Manhattan Avenue Brooklyn NY	SW	0.19 / 1,010.27	118
975 Manhattan Avenue	975 MANHATTAN AVENUE Brooklyn NY	WSW	0.19 / 1,016.23	119
193 Greenpoint Avenue	193 GREENPOINT AVENUE Brooklyn NY	SSW	0.19 / 1,022.33	120
977 Manhattan Avenue	977 Manhattan Avenue Brooklyn NY	WSW	0.19 / 1,024.41	121
153 GREEN STREET	153 GREEN STREET Brooklyn NY	W	0.21 / 1,087.13	127
175-177 GREENPOINT AVE	175-177 GREENPOINT AVE Brooklyn NY	SSW	0.21 / 1,092.93	131
148 GREEN STREET	148 GREEN STREET Brooklyn NY	W	0.21 / 1,120.22	135
237 McGuinness Boulevard	210 Greenpoint Avenue Brooklyn NY	S	0.22 / 1,184.97	140
186 Greenpoint Avenue	186 Greenpoint Avenue Brooklyn NY	SSW	0.24 / 1,288.27	154

RECYCLING - Recycling Facilities

A search of the RECYCLING database, dated May 21, 2024 has found that there are 4 RECYCLING site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Fortune Metal	239 India Street Brooklyn NY 11222	ESE	0.04 / 208.03	23

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Greenpoint Scrap Metal	304 Greenpoint Avenue Brooklyn NY 11222	SE	0.27 / 1,403.94	159

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Allocco Recycling Ltd (Kingsland Ave)	540 Kingsland Avenue Brooklyn NY 11222	ENE	0.37 / 1,978.14	184
Sims Metal Management LLC	30-27 Greenpoint Avenue Long Island City NY 11101	ENE	0.42 / 2,233.84	193

LST - Leaking Storage Tanks

A search of the LST database, dated Oct 21, 2024 has found that there are 46 LST site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
203 JAVA ST.	203 JAVA ST BROOKLYN NY	SW	0.11 / 562.14	65
	***Spill No** | **Close Date**: 9303193 | 06/10/1993 12:00:00 AM*			
MERIT S/S	210 GREENPOINT AVENUE BROOKLYN NY	S	0.22 / 1,184.97	140
	***Spill No** | **Close Date**: 9303423 | 10/28/2003 12:00:00 AM*			
132-140 GREEN STREET	132-140 GREEN STREET NEW YORK CITY NY	W	0.23 / 1,231.45	148
	***Spill No** | **Close Date**: 0011967 | 04/11/2003 12:00:00 AM*			
176 MCGUINNES AVE/GAS STA - TTF	176 MCGUINNESS BOULEVARD Brooklyn NY 11222	SSE	0.32 / 1,702.24	168
	***Spill No** | **Close Date**: 9108332 | 10/27/2014 12:00:00 AM*			
CANDLELIGHT CIRCLE	BLDG# 15 CLAY NY	WNW	0.34 / 1,770.42	170
	***Spill No** | **Close Date**: 9400007 | 04/29/1994 12:00:00 AM*			
111 MILTON ST/BKLYN	111 MILTON STREET NEW YORK CITY NY	SW	0.37 / 1,960.32	182
	***Spill No** | **Close Date**: 8911087 | 02/22/1990 12:00:00 AM*			
111 MILTON STREET	111 MILTON STREET BROOKLYN NY	SW	0.37 / 1,960.32	182
	***Spill No** | **Close Date**: 9312646 | 01/27/1994 12:00:00 AM*			
37-41 MOULTRIE ST	37-41 MOULTRIE ST BROOKLYN NY	SE	0.43 / 2,247.21	194
	***Spill No** | **Close Date**: 0308536 | 05/06/2005 12:00:00 AM*			
MOBIL	300 NORTH HENRY STREET BROOKLYN NY	ESE	0.45 / 2,391.25	200
	***Spill No** | **Close Date**: 8910558 | 12/03/2003 12:00:00 AM*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MOBIL GREENPOINT	300 NORTH HENRY STREET BROOKLYN NY	ESE	0.45 / 2,391.25	200
	Spill No* | *Close Date: *8800842* | *04/23/2003 12:00:00 AM*			
MOBIL GREENPOINT	300 NORTH HENRY STREET BROOKLYN NY	ESE	0.45 / 2,391.25	200
	Spill No* | *Close Date: *8808149* | *09/24/2003 12:00:00 AM*			
MOBIL GREENPOINT	300 NORTH HENRY STREET BROOKLYN NY	ESE	0.45 / 2,391.25	200
	Spill No* | *Close Date: *9312129* | *10/16/2002 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
FORMER WASTE TRANSFER STATION	247-251 GREEN ST BROOKLYN NY	NNE	0.04 / 206.80	21
	Spill No* | *Close Date: *0112015* | *01/27/2005 12:00:00 AM*			
NEWTOWN CREEK WPCP DEP - DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9211551* | *01/08/1993 12:00:00 AM*			
NEWTOWN CREEK WPCP DEP - DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0003594* | *05/05/2005 12:00:00 AM*			
EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9106287* | *10/16/1997 12:00:00 AM*			
NYC NEWTON CREEK WPCP	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9601620* | *07/31/1997 12:00:00 AM*			
EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9012950* | *12/27/2002 12:00:00 AM*			
NEW TOWN CREEK WATER POLL	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0407835* | *10/19/2004 12:00:00 AM*			
MINOR SPILL	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0512231* | *01/27/2006 12:00:00 AM*			
NEWTOWN CREEK SEWER PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9700433* | *04/09/1997 12:00:00 AM*			
NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	Spill No* | *Close Date: *0702645* | *06/04/2007 12:00:00 AM*			
DEPT OF CLEAN WATERS	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9606892* | *08/29/1996 12:00:00 AM*			
DEP WASTEWATER	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0512133* | *01/24/2006 12:00:00 AM*			
EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9104730* | *03/30/1995 12:00:00 AM*			
EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9101866* | *12/23/2002 12:00:00 AM*			
DEP WASTEWATER	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0512131* | *01/24/2006 12:00:00 AM*			
MOTIVA	25 PAIDGE AVENUE BROOKLYN NY	N	0.26 / 1,398.14	158
	Spill No* | *Close Date: *9413568* | *10/28/2003 12:00:00 AM*			
MOTIVA	25 PAIDGE AVENUE BROOKLYN NY	N	0.26 / 1,398.14	158
	Spill No* | *Close Date: *8703522* | *07/30/1987 12:00:00 AM*			
Spill Number 0010491	64 BOX ST BROOKLYN NY	NW	0.27 / 1,438.63	160
	Spill No* | *Close Date: *0010491* | *06/13/2003 12:00:00 AM*			
DEPT OF SANITATION	459 N HENRY ST BROOKLYN NY	ENE	0.31 / 1,640.16	162
	Spill No* | *Close Date: *0012519* | *04/23/2012 12:00:00 AM*			
120 JEWEL ST/BKLYN	120 JEWEL ST NEW YORK CITY NY	SE	0.33 / 1,759.40	169
	Spill No* | *Close Date: *8708714* | *09/30/1992 12:00:00 AM*			
29 ASH ST/BKLYN/UNIVERSAL	29 ASH ST BROOKLYN NY	NNW	0.34 / 1,803.85	171
	Spill No* | *Close Date: *8708297* | *07/18/2003 12:00:00 AM*			
29 ASH ST	29 ASH ST BROOKLYN NY	NNW	0.34 / 1,803.85	171
	Spill No* | *Close Date: *9709313* | *04/03/2003 12:00:00 AM*			
330 CALYER ST.	330 CALYER STREET BROOKLYN NY	ESE	0.34 / 1,812.49	173

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	Spill No* | *Close Date: *9401962* | *04/30/1998 12:00:00 AM*			
DEPT CONSUMER AFFAIRS	245 MESEROLE AVE GREENPOINT BROOKLYN NY	SE	0.37 / 1,974.30	183
	Spill No* | *Close Date: *0305945* | *09/05/2003 12:00:00 AM*			
CROSSTOWN ANNEX	65 COMMERCIAL STREET BROOKLYN NY	WNW	0.41 / 2,170.84	188
	Spill No* | *Close Date: *9011113* | *01/30/2004 12:00:00 AM*			
BULOVA CORPORATION	77 COMMERCIAL STREET BROOKLYN NY	NW	0.41 / 2,188.61	190
	Spill No* | *Close Date: *0211097* | *04/09/2003 12:00:00 AM*			
SIMS METAL MANAGEMENT	30-27 GREENPOINT AVE LONG ISLAND CITY NY	ENE	0.42 / 2,233.84	193
	Spill No* | *Close Date: *1200318* |			
NYC WATER TREATMENT PLANT	NEWTOWN CREEK BROOKLYN NY	N	0.44 / 2,317.12	196
	Spill No* | *Close Date: *9904793* | *07/23/2003 12:00:00 AM*			
145 WEST STREET	145 WEST STREET BROOKLYN NY	W	0.46 / 2,411.32	204
	Spill No* | *Close Date: *9408283* | *12/02/1994 12:00:00 AM*			
145 WEST STREET	145 WEST STREET BROOKLYN NY	W	0.46 / 2,411.32	204
	Spill No* | *Close Date: *9408663* | *12/02/1994 12:00:00 AM*			
STAGING SCAFFOLDING	25-20 BORDEN AVE LONG ISLAND CITY NY	NE	0.46 / 2,419.10	207
	Spill No* | *Close Date: *0109751* | *07/29/2002 12:00:00 AM*			
BUSINESS	11-40 BORDEN AVE QUEENS NY	N	0.46 / 2,428.34	208
	Spill No* | *Close Date: *0709037* | *07/24/2008 12:00:00 AM*			
21-07 BORDEN AVE	21-07 BORDEN AVE QUEENS NY	NNE	0.47 / 2,506.56	212
	Spill No* | *Close Date: *9614479* | *02/25/2003 12:00:00 AM*			
51-02 21ST ST	51-02 21ST ST LONG ISLAND CITY NY	N	0.49 / 2,589.47	217
	Spill No* | *Close Date: *8806127* | *07/19/2004 12:00:00 AM*			

UST - Underground Storage Tanks- UST-Petroleum Bulk Storage (PBS)

A search of the UST database, dated Nov 13, 2024 has found that there are 19 UST site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
WING GONG LAUNDRY	240 HURON STREET Brooklyn NY 11222 ***Site ID* | *Site Status**: 22705 | Unregulated/Closed*	SSE	0.02 / 113.02	10
WING GONG LAUNDRY INC	240-244 HURON ST 240 HURON ST BROOKLYN NY 11222 ***Site ID* | *Site Status**: 3892 | Inactive*	SSE	0.02 / 113.02	10
MJB SERVICE STATION INC	321 MCGUINNESS BOULEVARD Brooklyn NY 11222 ***Site ID* | *Site Status**: 22673 | Active*	W	0.05 / 250.88	30
GETTY 58088	315 MCGUINNESS BLVD Brooklyn NY 11222 ***Site ID* | *Site Status**: 4261 | Unregulated/Closed*	SW	0.07 / 350.13	39
MANNION SERVICE STATION	301 MCGUINNESS BOULEVARD BROOKLYN NY 11222 ***Site ID* | *Site Status**: 19726 | Unregulated/Closed*	SW	0.08 / 406.81	48
GREENPOINT NATIONAL GARAGE INC	276 MC GUINNESS BLVD BROOKLYN NY 11222 ***Site ID* | *Site Status**: 9389 | Unregulated/Closed*	S	0.12 / 637.65	73
NORIS METALS	231 KENT ST Brooklyn NY 11222 ***Site ID* | *Site Status**: 472661 | Unregulated/Closed*	S	0.14 / 752.66	84
WJZ AUTO REPAIR INC	262-268 MCGUINNESS BLVD 262 MCGUINNESS BLVD Brooklyn NY 11222 ***Site ID* | *Site Status**: 14149 | Unregulated/Closed*	S	0.15 / 765.88	85
996 MANHATTAN AVENUE	996 MANHATTAN AVENUE NEW YORK NY 11222 ***Site ID* | *Site Status**: 612620 | Unregulated/Closed*	W	0.15 / 812.54	89
MC GUINNESS & KENT SERVICE STATION INC.	256 MCGUINNESS BOULEVARD 256 MCGUINNESS BLVD (KENT ST) Brooklyn NY 11222 ***Site ID* | *Site Status**: 5932 | Active*	S	0.17 / 918.56	105
ENGINE COMPANY 238	205 GREENPOINT AVENUE Brooklyn NY 11222 ***Site ID* | *Site Status**: 22504 | Unregulated/Closed*	S	0.19 / 1,000.18	117
SPEEDWAY # 7821	210 GREENPOINT AVENUE BROOKLYN NY 11222 ***Site ID* | *Site Status**: 13746 | Unregulated/Closed*	S	0.22 / 1,184.97	140

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
247-251 GREEN STREET	247-251 GREEN STREET BROOKLYN NY 11222	NNE	0.04 / 206.80	21

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	Site ID* | *Site Status: *29370* | *Unregulated/Closed*			
41-55 PROVOST CO	41-55 PROVOST ST 41 PROVOST ST Brooklyn NY 11222	SE	0.09 / 484.14	58
	Site ID* | *Site Status: *11210* | *Unregulated/Closed*			
NEWTOWN CREEK WWTP	329 GREENPOINT AVENUE BROOKLYN NY 11222	NE	0.12 / 649.95	77
	Site ID* | *Site Status: *20122* | *Active*			
EXXON COMPANY,USA	320 FREEMAN STREET Brooklyn NY 11222	NE	0.12 / 649.95	77
	Site ID* | *Site Status: *22853* | *Inactive*			
EXXON COMPANY, U.S.A.	320 FREEMAN STREET Brooklyn NY 11222	NE	0.12 / 649.95	77
	Site ID* | *Site Status: *340334* | *Unregulated/Closed*			
HARCO CHEMICAL COATINGS	208 DUPONT ST Brooklyn NY 11222	N	0.15 / 786.45	86
	Site ID* | *Site Status: *340012* | *Unregulated/Closed*			
HARCO CHEMICAL COATINGS	208 DUPONT STREET Brooklyn NY 11222	N	0.15 / 786.45	86
	Site ID* | *Site Status: *25581* | *Unregulated/Closed*			

AST - The Bulk Storage Program Database - AST

A search of the AST database, dated Nov 13, 2024 has found that there are 22 AST site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
KEYSTONE AUTO REPAIR INC DBA KEY AUTO CENTER	240 GREEN STREET Brooklyn NY 11222	N	0.01 / 48.00	4
	Site ID* | *Site Status: *28976* | *Unregulated/Closed*			
S.C. TRUCK & AUTO REPAIR INC.	314 MCGUINESS BOULEVARD Brooklyn NY 11222	SW	0.02 / 126.67	14
	Site ID* | *Site Status: *29957* | *Active*			
DC TRUCK & AUTO REPAIR SHOP INC.	219 INDIA STREET BROOKLYN NY 11222	SSE	0.04 / 215.20	25
	Site ID* | *Site Status: *373006* | *Active*			
TWO GUYS AUTO GLASS, INC.	302 MCGUINNESS BOULEVARD BROOKLYN NY 11222	SSW	0.05 / 241.37	29
	Site ID* | *Site Status: *374288* | *Active*			
FAISAL AUTO CARE CENTER INC.	315 MCGUINNESS BLVD Brooklyn NY 11222	SW	0.07 / 350.13	39
	Site ID* | *Site Status: *25838* | *Active*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
S.R. AUTO SERVICE, INC.	300 MCGUINNESS BOULEVARD Brooklyn NY 11222 ***Site ID* | *Site Status**: 25900 | Active*	SSW	0.07 / 364.12	43
200 FREEMAN ST	200 FREEMAN ST BROOKLYN NY 11222 ***Site ID* | *Site Status**: 13041 | Active*	WNW	0.10 / 528.53	61
982 MANHATTAN AVE	982 MANHATTAN AVENUE Brooklyn NY 11222 ***Site ID* | *Site Status**: 30834 | Unregulated/Closed*	WSW	0.16 / 832.22	92
ALEKSANDRA CHODOWIEC	161 JAVA STREET AP. 1 BROOKLYN NY 11222 ***Site ID* | *Site Status**: 30478 | Unregulated/Closed*	WSW	0.18 / 961.96	110
APARTMENT HOUSE	168 HURON STREET BROOKLYN NY 11222 ***Site ID* | *Site Status**: 16611 | Active*	W	0.19 / 982.29	114
158 GREEN INC	158 GREEN ST AKA 107 MANHATTAN AVE Brooklyn NY 11222 ***Site ID* | *Site Status**: 460896 | Active*	W	0.19 / 987.93	115
ENGINE COMPANY 238	205 GREENPOINT AVENUE Brooklyn NY 11222 ***Site ID* | *Site Status**: 22504 | Unregulated/Closed*	S	0.19 / 1,000.18	117
947 ASSOCIATES, LLC	151 JAVA ST BROOKLYN NY 11222 ***Site ID* | *Site Status**: 18276 | Unregulated/Closed*	WSW	0.21 / 1,115.68	134
DUPONT ASSOC	127 DUPONT ST Brooklyn NY 11222 ***Site ID* | *Site Status**: 4632 | Unregulated/Closed*	NW	0.24 / 1,259.50	151
ST. ELIAS GREEK RITE ROMAN CATH. CHURCH	147 KENT STREET BROOKLYN NY 11222 ***Site ID* | *Site Status**: 28224 | Active*	WSW	0.25 / 1,313.93	156

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
EXXON COMPANY,USA	320 FREEMAN STREET Brooklyn NY 11222 ***Site ID* | *Site Status**: 22853 | Inactive*	NE	0.12 / 649.95	77
NEWTOWN CREEK WWTP	329 GREENPOINT AVENUE BROOKLYN NY 11222 ***Site ID* | *Site Status**: 20122 | Active*	NE	0.12 / 649.95	77
THE CITY OF NEW YORK/NYCDEP	329 GREENPOINT AVENUE 329 GREENPOINT AVENUE Brooklyn NY 11222	NE	0.12 / 649.95	77

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	Site ID* | *Site Status: *341773* | *Unregulated/Closed*			
HARCO CHEMICAL COATINGS	208 DUPONT ST Brooklyn NY 11222	N	0.15 / 786.45	86
	Site ID* | *Site Status: *340012* | *Unregulated/Closed*			
J & N ASSOC	158 DUPONT ST (AKA 158A DUPONT STREET) Brooklyn NY 11222	NW	0.17 / 920.87	106
	Site ID* | *Site Status: *4631* | *Unregulated/Closed*			
J & N ASSOC	159 DUPONT ST Brooklyn NY 11222	NW	0.20 / 1,064.94	124
	Site ID* | *Site Status: *4630* | *Unregulated/Closed*			
146 CLAY LLC	400 MC GUINNESS BLVD Brooklyn NY 11222	NNW	0.21 / 1,088.80	128
	Site ID* | *Site Status: *15854* | *Unregulated/Closed*			

MOSF - Major Oil Storage Facilities (MOSF)

A search of the MOSF database, dated Nov 13, 2024 has found that there are 6 MOSF site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
EXXON MOBIL OIL CORPORATION BROOKLYN TERMINAL	300 NORTH HENRY STREET Brooklyn NY 11222	ESE	0.45 / 2,391.25	200
	Site ID* | *Site Status: *344640* | *Unregulated/Closed*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEWTON CREEK WPCP	329 GREENPOINT AVENUE BROOKLYN NY 11222	NE	0.12 / 649.95	77
	Site ID* | *Site Status: *344985* | *Unregulated/Closed*			
BROOKLYN - SUNOCO LLC	25 PAIDGE AVENUE BROOKLYN NY 11222	N	0.26 / 1,398.14	158
	Site ID* | *Site Status: *344636* | *Active*			
FORMER MOBIL GREENPOINT TERMINAL	403 GREENPOINT AVENUE BROOKLYN NY 11222	E	0.35 / 1,872.27	175
	Site ID* | *Site Status: *345008* | *Unregulated/Closed*			
DITMAS OIL-LONG ISLAND CITY	53-02 11TH ST LONG ISLAND CITY NY 11101	NNW	0.46 / 2,403.46	203
	Site ID* | *Site Status: *345056* | *Inactive*			
UNITED METRO ENERGY CORP.	498 KINGSLAND AVENUE BROOKLYN NY 11222	E	0.46 / 2,441.00	209
	Site ID* | *Site Status: *344649* | *Active*			

CBS - Chemical Bulk Storage (CBS)

A search of the CBS database, dated Nov 13, 2024 has found that there are 1 CBS site(s) within approximately 0.25miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEWTOWN CREEK WWTP	329 GREENPOINT AVENUE BROOKLYN NY 11222	NE	0.12 / 649.95	77
	Site ID* | *Site Status: *339175* | *Active*			

ENG - Registry of Engineering Controls in New York State

A search of the ENG database, dated Nov 5, 2024 has found that there are 2 ENG site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
45 Commercial Street	45 Commercial Street Brooklyn NY 11222	WNW	0.41 / 2,175.38	189
23-30 Borden Avenue Development	23-30 BORDEN AVENUE Long Island City NY 11101	NNE	0.43 / 2,281.90	195

INST - Registry of Institutional Controls in New York State

A search of the INST database, dated Nov 5, 2024 has found that there are 2 INST site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
45 Commercial Street	45 Commercial Street Brooklyn NY 11222	WNW	0.41 / 2,175.38	189
23-30 Borden Avenue Development	23-30 BORDEN AVENUE Long Island City NY 11101	NNE	0.43 / 2,281.90	195

VCP - Voluntary Cleanup Agreements

A search of the VCP database, dated Nov 5, 2024 has found that there are 1 VCP site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
101-105 West Street	101-105 West Street, Brooklyn Brooklyn NY 11222	WSW	0.48 / 2,532.43	214

BROWNFIELDS - Brownfields Site List (Subset of Site Remediation)

A search of the BROWNFIELDS database, dated Nov 5, 2024 has found that there are 11 BROWNFIELDS site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
1036 Manhattan Ave BCP Site	1032 and 1036-1038 Manhattan Avenue Brooklyn NY 11222	W	0.16 / 856.30	97
210 Greenpoint Avenue Redevelopment	210 GREENPOINT AVENUE BROOKLYN NY 11222	S	0.23 / 1,189.03	141
Former BRT Railroad Car Barn	1121-1137 Manhattan Avenue/18 Box St. Brooklyn NY 11222	NW	0.32 / 1,689.97	167
29 Clay Property	29 Clay Street Brooklyn NY 11222	WNW	0.34 / 1,811.42	172
Former NuHart East	65 Dupont Street and 75 Dupont Street Brooklyn NY 11222	WNW	0.36 / 1,893.31	177
Clay Properties LLC	19-27 Clay Street and 60-62 Commercial Street Brooklyn NY 11222	WNW	0.36 / 1,893.59	178
49 Dupont Street	49 Dupont Street Greenpoint NY 11222	WNW	0.37 / 1,958.11	181
50 Commercial Street Development	50 and 56 Commercial Street and 15-17 Clay Street Brooklyn NY 11222	WNW	0.41 / 2,142.54	187

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
262 Green	262-276 Green Street and 263 Huron Street Brooklyn NY 11211	ENE	0.03 / 182.41	20
45 Commercial Street	45 Commercial Street Brooklyn NY 11222	WNW	0.41 / 2,175.38	189
23-30 Borden Avenue Development	23-30 BORDEN AVENUE Long Island City NY 11101	NNE	0.43 / 2,281.90	195

Non Standard

Federal

FINDS/FRS - Facility Registry Service/Facility Index

A search of the FINDS/FRS database, dated Aug 1, 2024 has found that there are 6 FINDS/FRS site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
J & J BRONZE & ALUMINUM CASTING CORP	249 HURON STREET BROOKLYN NY 11222-1801 ***Registry ID**: 110000323383*	SSW	0.00 / 0.00	2
MC GUINNESS MANAGEMENT CORP	231 HURON STREET BROOKLYN NY 11222 ***Registry ID**: 110019433264*	W	0.01 / 37.86	3
CON EDISON - MANHOLE 8545	234 GREEN ST BROOKLYN NY 11222 ***Registry ID**: 110055934850*	NW	0.01 / 48.43	5
C C BODY SHOP	230 GREEN ST BROOKLYN NY 11222 ***Registry ID**: 110004538395*	NW	0.01 / 49.28	6
AJB BUILDERS & CO.	251 HURON ST BROOKLYN NY 11222 ***Registry ID**: 110055291170*	E	0.01 / 49.35	7
CINER CHEMICAL & REFINING CO	246 GREEN ST BROOKLYN NY 11222 ***Registry ID**: 110046098085*	NE	0.01 / 66.25	8

TRIS - Toxics Release Inventory (TRI) Program

A search of the TRIS database, dated Sep 20, 2023 has found that there are 1 TRIS site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
J & J BRONZE & ALUMINUM CASTING CORP	249 HURON ST BROOKLYN NY 11222	SSW	0.00 / 0.00	2

PFAS IND - PFAS Industry Sectors

A search of the PFAS IND database, dated Sep 23, 2024 has found that there are 15 PFAS IND site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NUVITE CHEMICAL COMPOUNDS CORP	BROOKLYN NY	WNW	0.09 / 494.06	59
LOVE MONKEY	BROOKLYN NY	SSE	0.32 / 1,671.83	164

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
METAL SPECIALTIES-775-797 HUMBOLDT ST	BROOKLYN NY	SE	0.42 / 2,227.52	192
KB PROJECTS	BROOKLYN NY	WSW	0.47 / 2,497.74	211

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEWTOWN CREEK WATER POLLUTION CONTROL PLANT	BROOKLYN NY	NE	0.12 / 649.95	77
AMSCOR CORPORATION - 188 DUPONT STREET	BROOKLYN NY	NNW	0.17 / 900.12	102
HARCO CHEMICAL COATINGS INC	BROOKLYN NY	N	0.17 / 903.43	103
LEVITON MFG CO INC	BROOKLYN NY	SE	0.21 / 1,127.50	137
BROOKLYN TERMINAL - SUNOCO LLC	BROOKLYN NY	N	0.24 / 1,254.22	150
NYC-DOS GREENPOINT MTS	BROOKLYN NY	ENE	0.31 / 1,649.02	163
GREENPOINT INCINERATOR NEW YORK CITY DEPARTMENT OF SANITATION NYCDOS	BROOKLYN NY	E	0.32 / 1,684.26	166
PENSATO INDUSTRIES	BROOKLYN NY	NW	0.37 / 1,945.91	180
UNITED METRO ENERGY - BROOKLYN TERMINAL	BROOKLYN NY	E	0.42 / 2,213.55	191
COURIER PACKAGING CO INC	BROOKLYN NY	W	0.44 / 2,326.89	197

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
UNITED BIOFUELS INC - 435 GREENPOINT AVE	BROOKLYN NY	E	0.46 / 2,417.00	206

ICIS - Integrated Compliance Information System (ICIS)

A search of the ICIS database, dated Apr 13, 2024 has found that there are 3 ICIS site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
J & J BRONZE & ALUMINUM CASTING CORP	249 HURON STREET BROOKLYN NY 11222-1801 ***Registry ID**: 110000323383*	SSW	0.00 / 0.00	2
CINER CHEMICAL & REFINING CO	246 GREEN ST BROOKLYN NY 11222 ***Registry ID**: 110046098085*	NE	0.01 / 66.25	8
CINER CHEMICAL & REFINING CO	246 GREEN ST BROOKLYN NY 11222 ***Registry ID**: 110046098085*	NE	0.01 / 66.25	8

FUDS - Formerly Used Defense Sites

A search of the FUDS database, dated May 15, 2023 has found that there are 1 FUDS site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NAVY FIRE FIGHTING SCH	NO CITY NY ***FUDS Property No**: C02NY1088*	SSW	0.90 / 4,775.99	243

AFS - Air Facility System

A search of the AFS database, dated Oct 17, 2014 has found that there are 1 AFS site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
CINER CHEMICAL & REFINING CO	246 GREEN ST BROOKLYN NY 11222	NE	0.01 / 66.25	8

OSC RESPONSE - On-Scene Coordinator Response Sites

A search of the OSC RESPONSE database, dated Apr 4, 2024 has found that there are 1 OSC RESPONSE site(s) within approximately 0.12miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Fortune Metals Inc.	239 India Street Brooklyn NY	ESE	0.04 / 208.03	23

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key

State

MGP - Manufactured Gas Plants

A search of the MGP database, dated Aug 20, 2024 has found that there are 3 MGP site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
K - Wythe Ave. Station	Wythe Ave., Berry St., N 12th & 13th St Brooklyn NY 11211	SSW	0.82 / 4,347.68	236
K - Peoples Works	Kent Ave. S. 10th St., S. 11th St. Brooklyn NY 11211	SW	0.91 / 4,786.58	244

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
K - Williamsburg Works	Kent Ave & 12th Street Brooklyn NY 11211-	SW	0.81 / 4,269.27	232

NY SPILLS - Spill Incidents Database

A search of the NY SPILLS database, dated Oct 21, 2024 has found that there are 190 NY SPILLS site(s) within approximately 0.12 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
RZ METAL CORP	247 HURON ST BROOKLYN NY 11222	SSW	0.00 / 0.00	1
	Spill No* | *Close Date: *0011791* | *12/29/2005 12:00:00 AM*			
MINERAL OIL SPILL	241-247 HURON STREET BROOKLYN NY	SSW	0.00 / 0.00	1
	Spill No* | *Close Date: *1403242* | *08/26/2014 12:00:00 AM*			
APRT	249 HURON STREET BROOKLYN NY	SSW	0.00 / 0.00	2
	Spill No* | *Close Date: *0710964* | *01/31/2008 12:00:00 AM*			
PRIVATE RESIDENCE	298 GREEN AVE BROOKLYN NY	NNE	0.02 / 104.52	9
	Spill No* | *Close Date: *1206492* | *05/21/2014 12:00:00 AM*			
Spill Number 0004605	MCGUINESS AND HURON AV BROOKLYN NY	WSW	0.03 / 177.40	19
	Spill No* | *Close Date: *0004605* | *12/28/2000 12:00:00 AM*			
CON ED MANHOLE 4313	MC GUINNESS & HURON ST BROOKLYN NY	WSW	0.03 / 177.40	19

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	Spill No* | *Close Date: *9307736* | *05/26/1995 12:00:00 AM*			
262 HURON ST	262 HURON ST BROOKLYN NY	ESE	0.04 / 208.00	22
	Spill No* | *Close Date: *9704312* | *07/21/1998 12:00:00 AM*			
217 INDIA STREET	217 INDIA STREET BROOKLYN NY	S	0.04 / 214.73	24
	Spill No* | *Close Date: *0007775* | *11/14/2000 12:00:00 AM*			
COMMERCIAL	217 INDIA ST BROOKLYN NY	S	0.04 / 214.73	24
	Spill No* | *Close Date: *2205227* | *09/15/2022 12:00:00 AM*			
HALF PINT OIL IN MAN HOLE 71471	GREEN STREET AND MCGUINNESS BROOKLYN NY	WNW	0.04 / 221.55	26
	Spill No* | *Close Date: *0704289* | *08/20/2007 10:23:00 AM*			
ROADWAY	GREENE ST MCGINNIS BLVD BROOKLYN NY	WNW	0.04 / 221.55	26
	Spill No* | *Close Date: *1607557* | *11/03/2016 12:00:00 AM*			
UNDERGROUND VAULT	MCGUINESS BLVD AND GREEN ST BROOKLYN NY	WNW	0.04 / 221.55	26
	Spill No* | *Close Date: *1812191* | *04/03/2019 12:00:00 AM*			
PULASKI SERVICE STATION	321 MCGUINNESS BOULEVARD Brooklyn NY 11222	W	0.05 / 250.88	30
	Spill No* | *Close Date: *9908882* | *04/05/2012 12:00:00 AM*			
SIDEWALK	321 MCGUINESS BLVD BROOKLYN NY	W	0.05 / 250.88	30
	Spill No* | *Close Date: *1609775* | *01/24/2017 12:00:00 AM*			
AIR	321 MCGUINNESS BLVD BROOKLYN NY	W	0.05 / 250.88	30
	Spill No* | *Close Date: *1812673* | *03/27/2019 12:00:00 AM*			
RESIDENTIAL	352 MCGUINESS BLVD BROOKLYN NY	NW	0.06 / 331.18	37
	Spill No* | *Close Date: *1911000* | *03/31/2020 12:00:00 AM*			
APARTMENT COMPLEX	352 MCGUINNESS BLVD BROOKLYN NY	NW	0.06 / 331.18	37
	Spill No* | *Close Date: *2108266* | *12/21/2021 12:00:00 AM*			
MANHOLE 71304	MCGUINNESS BL/INDIA ST BROOKLYN NY	SW	0.06 / 342.07	38
	Spill No* | *Close Date: *0002190* | *03/24/2004 12:00:00 AM*			
MANHOLE #62845	MCGUINESS BLVE/INDIA ST BROOKLYN NY	SW	0.06 / 342.07	38

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	Spill No* | *Close Date: *9911540* | *03/04/2002 12:00:00 AM*			
MANHOLE #71304	MCGUINNESS BLVD/INDIA ST BROOKLYN NY	SW	0.06 / 342.07	38
	Spill No* | *Close Date: *0211464* | *12/08/2016 12:00:00 AM*			
CON ED MANHOLE #71304	MCGINNIS/INDIA STREET BROOKLYN NY	SW	0.06 / 342.07	38
	Spill No* | *Close Date: *0405049* | *01/19/2005 12:00:00 AM*			
MANHOLE 713204	MCGUINESS BLVD/ INDIA ST. BROOKLYN NY	SW	0.06 / 342.07	38
	Spill No* | *Close Date: *0402792* | *01/03/2005 12:00:00 AM*			
INTERESCTION - MANHOLE #71304	MCGINNIS BLVD AND INDIA STREET BROOKLYN NY	SW	0.06 / 342.07	38
	Spill No* | *Close Date: *0912432* | *03/12/2010 12:00:00 AM*			
VACANT AREA/FORMER GETTY	305-319 MCGUINNESS BLVD BROOKLYN NY	SW	0.07 / 350.13	39
	Spill No* | *Close Date: *0400807* | *04/29/2014 12:00:00 AM*			
315 MCGUINNESS BLVD	315 MCGUINNESS BLVD BROOKLYN NY	SW	0.07 / 350.13	39
	Spill No* | *Close Date: *9111459* | *08/19/1992 12:00:00 AM*			
AUTO BODY SHOP	300 MCGUINNES BLVD BROOKLYN NY	SSW	0.07 / 364.12	43
	Spill No* | *Close Date: *9613105* | *03/17/2016 12:00:00 AM*			
TWO GAL GREEN SUBSTANCE IN SB 7529	222 INDIA STREET BROOKLYN NY	SSE	0.07 / 373.23	44
	Spill No* | *Close Date: *0710905* | *03/20/2008 10:32:00 AM*			
TM #2907	FREEMAN STREET & MCGINNIS BLVD BROOKLYN NY	NW	0.08 / 448.30	52
	Spill No* | *Close Date: *0706289* | *09/20/2007 08:43:00 AM*			
SERVICE BOX 8463	210/212 FREEMAN AVENUE BROOKLYN NY	WNW	0.08 / 448.43	53
	Spill No* | *Close Date: *9901749* | *06/04/1999 12:00:00 AM*			
AT DUPLEX	212 FREEMAN ST BROOKLYN NY	WNW	0.08 / 448.43	53
	Spill No* | *Close Date: *1901371* | *05/09/2019 12:00:00 AM*			
GROUND 212 FREEMAN ST.	212 FREEMAN STREET/ 212 GREEN STREET BROOKLYN NY	WNW	0.08 / 448.43	53
	Spill No* | *Close Date: *1812114* | *07/24/2019 12:00:00 AM*			
ROADWAY	FREEMAN & MCGUINESS ST BROOKLYN NY	NW	0.09 / 451.74	54

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	Spill No* | *Close Date: *0211776* | *02/28/2003 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
VACANT BUILDING	311 GREEN AVE. BROOKLYN NY	NNE	0.03 / 138.64	16
	Spill No* | *Close Date: *0707140* | *11/19/2007 12:00:00 AM*			
WATER MAIN BREAK	311 GREEN AVENUE BROOKLYN NY	NNE	0.03 / 138.64	16
	Spill No* | *Close Date: *0707143* | *09/28/2007 12:00:00 AM*			
CONSTRUCTION SITE	333 GREEN AVE BROOKLYN NY	NE	0.03 / 169.10	18
	Spill No* | *Close Date: *0611233* | *04/24/2007 12:00:00 AM*			
FRANKLIN AND BEDFORD AVES	381 GREEN AVE BROOKLYN NY	ENE	0.06 / 294.15	34
	Spill No* | *Close Date: *0711578* | *02/04/2008 12:00:00 AM*			
266 FREEMAN ST/BROOKLYN	266 FREEMAN STREET NEW YORK CITY NY	NE	0.07 / 355.29	41
	Spill No* | *Close Date: *8905039* | *12/08/1992 12:00:00 AM*			
GREEN ST & PROVOST/BKLYN	GREEN ST & PROVOST BROOKLYN NY	ENE	0.07 / 379.05	45
	Spill No* | *Close Date: *9011235* | *02/25/1991 12:00:00 AM*			
EXXON TERMINAL	320 FREEMAN AVENUE BROOKLYN NY	NNE	0.07 / 380.07	46
	Spill No* | *Close Date: *8710916* | *03/30/1988 12:00:00 AM*			
CONSTRUCTION PROJECT	347 FREEMAN ST BROOKLYN NY	NNE	0.08 / 423.27	50
	Spill No* | *Close Date: *0009812* | *11/30/2000 12:00:00 AM*			
COMING FROM OUTSIDE-SINCE EARLY FEBRUARY	CORNER OF FREEMAN AND MCGUINESS BROOKLYN NY	NW	0.08 / 424.77	51
	Spill No* | *Close Date: *1902180* | *06/03/2019 12:00:00 AM*			
EN TECH CORP	259 FREEMAN ST BROOKLYN NY	NNE	0.09 / 483.86	57
	Spill No* | *Close Date: *1810898* | *01/28/2019 12:00:00 AM*			
FORMER NEY SMELTING AND REFINING COMPANY	269-277 FREEMAN STREET / 230-242 EAGLE ST/ 105 PROVOST STREET BROOKLYN NY 11222	NNE	0.10 / 547.04	62
	Spill No* | *Close Date: *1006046* | *10/05/2010 12:00:00 AM*			
RESIDENTIAL	366 MCGUINNESS BLVD BROOKLYN NY	NNW	0.11 / 560.68	64
	Spill No* | *Close Date: *2305899* | *10/10/2023 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ROADWAY	366 MCGUINNESS BLVD BROOKLYN NY	NNW	0.11 / 560.68	64
	Spill No* | *Close Date: *2305891* | *10/31/2023 12:00:00 AM*			
PRIVATE RESIDENCE	214 EAGLE STREET NY	NNW	0.11 / 569.30	67
	Spill No* | *Close Date: *1213916* | *12/27/2012 12:00:00 AM*			
ABANDONED DRUMS	242 EAGLE ST BROOKLYN NY	NNE	0.12 / 638.81	75
	Spill No* | *Close Date: *0203069* | *08/02/2002 12:00:00 AM*			
NEW TOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0510010* | *11/23/2005 12:00:00 AM*			
NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0508162* | *10/11/2005 12:00:00 AM*			
NEWTOWN CREEK WPCP DEP - DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9504909* | *05/05/2005 12:00:00 AM*			
CONSTRUCTION SITE	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0513125* | *02/17/2006 12:00:00 AM*			
NEWTOWN CREEK WPCP DEP - DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *8602874* | *07/31/1986 12:00:00 AM*			
NEW TOWN CREEK PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0502107* | *05/25/2005 12:00:00 AM*			
NEWTOWN CREEK WPCP DEP - DDC (JK)	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9907560* |			
NEW TOWN CREEK WATER POLLUTION CONTROL PLANT	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *1007898* | *10/26/2010 12:00:00 AM*			
NEW TOWN CREEK WATER POLL CONTROL	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *1308089* | *11/08/2013 12:00:00 AM*			
NEWTOWN CREEK WWTP	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *1302071* | *06/03/2013 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0510252* | *11/30/2005 12:00:00 AM*			
NYC DEP NEWTON CREEK WATER POLLUTION CONTROL PLANT	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *1105600* | *08/17/2011 12:00:00 AM*			
WHALECREEK CANAL	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0510498* | *12/09/2005 12:00:00 AM*			
NEWTOWN CREEK SEWER PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0700018* | *04/02/2007 12:00:00 AM*			
NEWTOWN CREEK PLANT	NEWTOWN CREEK PLANT NEW YORK CITY NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *8604496* | *10/11/1986 12:00:00 AM*			
ROAD C TUNNEL DEMO AREA	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0902642* | *06/04/2009 12:00:00 AM*			
NEWTOWN CREEK TREATMENT PLANT	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0707652* | *10/11/2007 12:00:00 AM*			
NEWTOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0804242* | *07/14/2008 12:00:00 AM*			
NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0603406* | *06/28/2006 12:00:00 AM*			
POLUTION CONTROL PLANT	329 GREENPOINT AVE BROOKLYNN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0711947* | *02/13/2008 12:00:00 AM*			
NEWTON CREEK PLANT	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0611591* | *01/18/2007 12:00:00 AM*			
NEWTOWN CREEK WATER POLUTION CONTROL PLANT	329 GREEN POINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0908611* | *11/02/2009 12:00:00 AM*			
DEP WASTEWATER	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0512132* | *01/24/2006 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEWTOWN CREEK WATER POLLUTION CONTROL	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0808966* | *11/10/2008 12:00:00 AM*			
NEWTOWN CREEKWPCP DEP - DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9500431* | *05/05/2005 12:00:00 AM*			
NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0703835* | *07/05/2007 12:00:00 AM*			
NEWTOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0610819* | *12/26/2006 12:00:00 AM*			
NEW TOWN CREEK WPCP	301 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0710149* | *12/24/2007 12:00:00 AM*			
NEWTOWN CREEK CONT. PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0204403* | *07/29/2002 12:00:00 AM*			
NEWTOWN CREEK WPCP DEP - DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9602370* | *04/18/2001 12:00:00 AM*			
Spill Number 9809941	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9809941* | *02/13/2003 12:00:00 AM*			
NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0500990* | *04/25/2005 12:00:00 AM*			
EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9004386* | *06/20/1995 12:00:00 AM*			
NEW TOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0405275* | *04/20/2005 12:00:00 AM*			
NEW TOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9614108* | *07/22/2005 12:00:00 AM*			
NEWTOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0509056* | *10/28/2005 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEW TOWN CREEK WATER POLL	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0603250* | *06/26/2006 12:00:00 AM*			
NEWTOWN CREEK WPCC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0603263* | *06/26/2006 12:00:00 AM*			
NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0603280* | *06/26/2006 12:00:00 AM*			
13TH ST PUMP STATION	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0508779* | *10/25/2005 12:00:00 AM*			
NEWTOWN CREEK WATER POLLU	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0701075* | *04/26/2007 12:00:00 AM*			
NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0602385* | *06/02/2006 12:00:00 AM*			
NEW TOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0700138* | *04/05/2007 12:00:00 AM*			
NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0700483* | *04/16/2007 12:00:00 AM*			
NEWTOWN CREEK WPCP	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0700197* | *04/09/2007 12:00:00 AM*			
NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0703363* | *06/22/2007 12:00:00 AM*			
NEWTOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0706548* | *09/12/2007 12:00:00 AM*			
NEWTOWN CREEK	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0706001* | *08/27/2007 12:00:00 AM*			
AVENUE B PUMP STATION	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0708718* | *11/13/2007 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEW TOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0704882* | *08/01/2007 12:00:00 AM*			
NEW TOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0704883* | *08/01/2007 12:00:00 AM*			
NEW TOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0704884* | *07/31/2007 12:00:00 AM*			
NEW TOWN CREEK WATER PLAN	301 GREENPOINT AVE. BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0707573* | *10/10/2007 12:00:00 AM*			
NEWTOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0709349* | *11/29/2007 12:00:00 AM*			
NEW TOWN CREEK	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0804630* | *07/28/2008 12:00:00 AM*			
NEW TOWN CREEK	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0804678* | *07/24/2008 12:00:00 AM*			
NEW TOWN CREEK WATER PLAN	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0804109* | *07/14/2008 12:00:00 AM*			
NEW TOWN CREEK	301 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0802371* | *06/02/2008 12:00:00 AM*			
NEW TOWN CREEK TREATMENT PLANT	329 GREEN POINT AVE - BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0810724* | *12/26/2008 12:00:00 AM*			
DEP CONSTRUCTION SITE	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0803882* | *07/17/2008 12:00:00 AM*			
NEWTOWN CREEK PLANT	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *1010132* | *12/27/2010 12:00:00 AM*			
NEW TOWN CREEK WATER POLL	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0603777* | *07/06/2006 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEW TOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0610972* | *01/02/2007 12:00:00 AM*			
NEWTOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0610780* | *12/26/2006 12:00:00 AM*			
NEW TOWN CREEK DEP SITE	329 GREEN POINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *1001677* | *05/17/2010 12:00:00 AM*			
NYC DEP FACILITY	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *1001442* | *05/07/2010 12:00:00 AM*			
NEWTOWN CREEK PLANT DEP	329 GREEN POINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0806630* | *09/15/2008 12:00:00 AM*			
Spill Number 0206432	329 GREENPORT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0206432* | *12/08/2003 12:00:00 AM*			
ELEVATION -1 IN MAIN BLD	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0908307* | *10/26/2009 12:00:00 AM*			
NEWTOWN CREEK WATER POLLUTION CONTROL PLANT	329 GREEN POINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0806127* | *09/02/2008 12:00:00 AM*			
NEWTOWN CREEK	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0708099* | *10/26/2007 12:00:00 AM*			
NEWTOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0706475* | *10/25/2007 12:00:00 AM*			
NEW TOWN CREEK PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0609972* | *12/04/2006 12:00:00 AM*			
NEWTOWN CREEK	329 GREENPOINT AV BROOKLYNN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0805108* | *08/05/2008 12:00:00 AM*			
NEWTOWN CREEK TREATMENT	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0307763* | *10/23/2003 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEW TOWN CREEK WP	329 GREENPOINT AVE RD E BROOKLIN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0805503* | *08/13/2008 12:00:00 AM*			
Spill Number 0108649	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0108649* | *11/29/2001 12:00:00 AM*			
NEWTON CREEK PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0703611* | *06/28/2007 12:00:00 AM*			
NYC SEWAGE TREATMENT PLANT	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0904709* | *07/24/2009 12:00:00 AM*			
NEWTOWN CREEK WATER POLLUTION CONTROL PLANT	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0810614* | *12/22/2008 12:00:00 AM*			
NEWTOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0710497* | *01/07/2008 12:00:00 AM*			
NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0606073* | *08/28/2006 12:00:00 AM*			
NEWTOWN CREEK, STP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9411493* | *12/02/1994 12:00:00 AM*			
NEWTOWN CREEK WPCP DEP - DDC (JK)	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0000867* |			
NEWTOWN CREEK WPCP DEP - DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0001944* | *05/05/2005 12:00:00 AM*			
NEWTOWN CREEK WPCP DEP - DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9408029* | *12/16/2002 12:00:00 AM*			
EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *8907186* | *10/20/1989 12:00:00 AM*			
EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *8912333* | *02/04/1998 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9012482* | *02/11/2010 12:00:00 AM*			
301 GREENPOINT AVE	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9302991* | *06/05/1993 12:00:00 AM*			
NEWTOWN CREEK PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0600090* | *04/04/2006 12:00:00 AM*			
NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0514208* | *03/13/2006 12:00:00 AM*			
DEP FACILITY	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0514090* | *03/13/2006 12:00:00 AM*			
ON THE ROAD	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0514375* | *03/16/2006 12:00:00 AM*			
NEWTOWN CREEK WATER POLLU	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0511857* | *01/17/2006 12:00:00 AM*			
MINOR SPILL	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0512232* | *01/27/2006 12:00:00 AM*			
NEW TOWN CREEK WATER TREA	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0202662* | *06/12/2002 12:00:00 AM*			
NEW TOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0706259* | *09/05/2007 12:00:00 AM*			
NEWTOWN CREEK WCPC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0705272* | *08/08/2007 12:00:00 AM*			
NEW TOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0701144* | *04/27/2007 12:00:00 AM*			
NEWTOWN CREEK WPCP DEP - DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9911559* | *02/26/2003 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEWTOWN CREEK WCPC	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0809249* | *11/17/2008 12:00:00 AM*			
POLLUTION PLANT	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0511797* | *02/06/2006 12:00:00 AM*			
NEWTOWN CREEK WATER POLUTION CONTROL	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0810194* | *12/12/2008 12:00:00 AM*			
DEP WASTE WATER TREATMENT	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0514457* | *03/17/2006 12:00:00 AM*			
NEW TOWN CREEK WATER PLAN	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0307871* | *10/27/2003 12:00:00 AM*			
NEWTOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0705172* | *08/09/2007 12:00:00 AM*			
NEW TOWN CREEK	329 GREENPOINT AVE RD E BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0706180* | *08/31/2007 12:00:00 AM*			
NEWTOWN CREEK WPCP	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0809701* | *12/02/2008 12:00:00 AM*			
NEW TOWN CREEK WPCP	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0510055* | *11/23/2005 12:00:00 AM*			
NEW TOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0511191* | *12/27/2005 12:00:00 AM*			
NEW TOWN CREEK WPCP	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0407841* | *01/28/2005 12:00:00 AM*			
NEWTOWN CREEK WATER POLUTION PLANT	329 GREEN POINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0806368* | *09/08/2008 12:00:00 AM*			
NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0600869* | *04/24/2006 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEWTOWN CREEK WPCP DEP - DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0304007* | *07/17/2003 12:00:00 AM*			
EXXON TERMINAL	320 FREEMAN STREET BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *8909181* | *12/19/1989 12:00:00 AM*			
NEWTON CREEK PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0612936* | *03/02/2007 12:00:00 AM*			
NEWTOWN CREEK WPCP DEP - DDC	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0013213* | *04/05/2001 12:00:00 AM*			
NEWTON CREEK PLANT	301 GREENPOINT AVE. BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0802830* | *06/11/2008 12:00:00 AM*			
CONSTRUCTION SITE	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0512289* | *01/27/2006 12:00:00 AM*			
NEWTOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0607498* | *01/04/2007 12:00:00 AM*			
TULLY CONSTRUCTION	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0513123* | *02/17/2006 12:00:00 AM*			
NYC DEP - WPCP	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0106038* | *12/01/2003 12:00:00 AM*			
NEWTON CREEK PLANT	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0601593* | *05/12/2006 12:00:00 AM*			
NEWTOWN CREEK	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0504567* | *07/18/2005 12:00:00 AM*			
NEWTON CREEK PLANT	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0611175* | *01/08/2007 12:00:00 AM*			
WATER POLLUTION CONTROL PLANT	329 GREEN POINT AVENUE BROOKLYN NY 11222	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0807189* | *09/26/2008 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEWTOWN CREEK	301 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0710837* | *01/13/2008 12:00:00 AM*			
NEW TOWN CREEK WPCP	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0808381* | *10/27/2008 12:00:00 AM*			
Spill Number 9810145	301 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *9810145* | *10/04/1999 12:00:00 AM*			
NEW TOWN CREEK	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0502697* | *10/18/2005 12:00:00 AM*			
NEW TOWN CREEK WWT PLANT	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *1002787* | *06/14/2010 12:00:00 AM*			
PEGNO/TULLY JOINT VENTURE	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0513124* | *02/17/2006 12:00:00 AM*			
FACILITY WASTE WATER TREATMENT PLANT	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *1504424* | *07/27/2015 12:00:00 AM*			
SEWAGE TREATMENT PLANT (NEW TOWN CREEK)	301 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *1805468* | *08/21/2018 12:00:00 AM*			
NATIONAL GRID VEHICLE	327 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *2209274* | *02/17/2023 12:00:00 AM*			
COMMERICAL EQUIPEMNT	327 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *2209494* | *03/03/2023 12:00:00 AM*			
YARD	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *2402362* | *09/13/2024 12:00:00 AM*			
CRACKED FITTING	329 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *2402540* | *09/12/2024 12:00:00 AM*			
WASTE WATER TX FACILITY	327 GREENPOINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *2404227* | *08/22/2024 12:00:00 AM*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEWTOWN CREEK WATER POLLUTION CONTROL PLANT	329 GREEN POINT AVE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0810451* | *12/17/2008 12:00:00 AM*			
NEWTOWN CREEK WPCP	329 GREENPOINT AVENUE BROOKLYN NY	NE	0.12 / 649.95	77
	Spill No* | *Close Date: *0650058* | *04/13/2006 12:00:00 AM*			
MANHOLE # TM2275	JAVA ST/PROVOST ST BROOKLYN NY	SE	0.12 / 657.97	78
	Spill No* | *Close Date: *0012337* | *06/13/2003 12:00:00 AM*			

PFAS CONTAM - PFAS Remedial Sites

A search of the PFAS CONTAM database, dated Nov 5, 2024 has found that there are 1 PFAS CONTAM site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
210 Greenpoint Avenue Redevelopment	210 GREENPOINT AVENUE BROOKLYN NY 11222	S	0.23 / 1,189.03	141

PFAS - Per- and Polyfluoroalkyl Substances (PFAS)

A search of the PFAS database, dated Jan 16, 2019 has found that there are 2 PFAS site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Arc Terminals New York Holdings, LLC	25 Paidge Ave Brooklyn NY	N	0.26 / 1,398.14	158
United Metro Energy Corp	500 Kingsland Ave Brooklyn NY	E	0.45 / 2,368.87	198

DELISTED DRYCLEANERS - Delisted Dry Cleaner Facilities

A search of the DELISTED DRYCLEANERS database, dated Sep 26, 2024 has found that there are 2 DELISTED DRYCLEANERS site (s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
WING GONG LAUNDRY/ROCKS & JEANS	240/250 HURON STREET BROOKLYN NY 11222	SSE	0.02 / 113.02	10
APHRODITE CLEANERS	1019 MANHATTAN AVENUE BROOKLYN NY 11222	W	0.18 / 969.82	112

NY MANIFEST - Hazardous Waste Manifest - Facilities

A search of the NY MANIFEST database, dated Jun 24, 2024 has found that there are 4 NY MANIFEST site(s) within approximately 0.12miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
CON EDISON - SERVICE BOX 7507	250 HURON ST BROOKLYN NY 11222	SE	0.02 / 115.13	11
CON EDISON - TRANSFORMER MANHOLE 752	MCGUINESS BLVD & HURON ST BROOKLYN NY 11222	WSW	0.03 / 177.40	19
CON EDISON - SERVICE BOX 7508	256 HURON ST BROOKLYN NY 11222	ESE	0.04 / 208.03	23

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CON ED	JAVA ST & PROVOST ST NEW YORK NY 10017	SE	0.12 / 657.97	78

REC MANIFEST - Receivers from Hazardous Waste Manifests

A search of the REC MANIFEST database, dated Jun 24, 2024 has found that there are 1 REC MANIFEST site(s) within approximately 0.25miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CINER CHEMICAL REFINING CO INC	247 GREEN ST BROOKLYN NY 11222	NNE	0.04 / 206.80	21

GEN MANIFEST - Generators from Hazardous Waste Manifests

A search of the GEN MANIFEST database, dated Jun 24, 2024 has found that there are 40 GEN MANIFEST site(s) within approximately 0.12miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
J & J BRONZE & ALUMINUM CASTING	249 HURON ST BROOKLYN NY 11222	SSW	0.00 / 0.00	2
J&J BRONZE & ALUMINUM CASTING CORP	249 HURON ST BROOKLYN NY 11222	SSW	0.00 / 0.00	2
CON EDISON	234 GREEN ST BROOKLYN NY 11222	NW	0.01 / 48.43	5

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
CON EDISON	292 GREENE ST SB11660 BROOKLYN NY 11201	N	0.02 / 116.27	12
MCGUINNESS MANAGEMENT	330 MCGUINNESS BLVD BROOKLYN NY 11222	W	0.02 / 117.25	13
CON EDISON	SEC HURON & MCGUINNESS MH 4313 BROOKLYN NY 11222	WSW	0.03 / 177.40	19
consoliated edison	S/S HURON ST 25` E/O MCGUINESS BLVD BROOKLYN NY 11205	WSW	0.03 / 177.40	19
FORTUNE METAL INC	239 INDIA STREET BROOKLYN NY 11222	ESE	0.04 / 208.03	23
MJB SERVICE STATION (PULASKI SVC STA)	321 MCGUINESS BLVD BROOKLYN NY 11222	W	0.05 / 250.88	30
CON EDISON	237 INDIA ST SB 7530 BRONX NY	ESE	0.05 / 269.11	31
CON EDISON	237 INDIA ST SB 7530 BROOKLYN NY	ESE	0.05 / 269.11	31
CON EDISON	346 MAGUINNESS AVE SB 8385 BROOKLYN NY	NW	0.05 / 281.89	33
CON EDISON	F/O 346 MCGUINNESS BLVD SERVICE BOX # 8385 BROOKLYN NY 11222	NW	0.05 / 281.89	33
CON EDISON	242 FREEMAN ST SB8465 BROOKLYN NY 11201	NNW	0.06 / 308.72	36
CONSOLIDATED EDISON	MCGUINNESS & INDIA BROOKLYN NY 11201	SW	0.06 / 342.07	38
NYSDOT	MCGUINESS BLVD & INDIA ST BROOKLYN NY	SW	0.06 / 342.07	38

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
CONSOLIDATED EDISON	MH71304-MCGUINNESS BLVD &INDIA BROOKLYN NY	SW	0.06 / 342.07	38
CON EDISON	F/O 239 JAVA ST STRUCTURE 56190 BROOKLYN NY 11222	SSE	0.08 / 410.45	49
CON EDISON	FRONT OF 239 JAVA ST SB56190 BROOKLYN NY 11222	SSE	0.08 / 410.45	49
CON EDISON	FRONT OF 239 JAVA ST SB56190 BROOKLYN NY 11222	SSE	0.08 / 410.45	49
CON EDISON	FRONT OF 239 JAVA ST SB8635 BROOKLYN NY 11222	SSE	0.08 / 410.45	49
CON EDISON	184 INDIA ST SB 7527 BROOKLYN NY 11222	SW	0.09 / 477.45	56
NUVITE CHEMICAL	213 FREEMAN ST BROOKLYN NY 11222	NW	0.10 / 527.09	60
CON ED	234 JAVA ST SB 56190 BROOKLYN NY 11222	SSE	0.12 / 621.01	70
CON EDISON	FRONT OF 238 JAVA ST SB56190 BROOKLYN NY 11222	SSE	0.12 / 632.24	71
CON EDISON	238 JAVA SB 56190 BROOKLYN NY	SSE	0.12 / 632.24	71
CON EDISON	238 JAVA ST SB 56190 BROOKLYN NY	SSE	0.12 / 632.24	71
CON EDISON	230 JAVA ST MH 8636 BROOKLYN NY	S	0.12 / 632.43	72
GREENPOINT NATIONAL GARAGE INC	276 MCGUINNESS BLVD BROOKLYN NY	S	0.12 / 637.70	74

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
CON EDISON	FRONT OF 183 HURON ST SB7498 BROOKLYN NY 11222	W	0.12 / 649.70	76

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CON EDISON	322 GREEN ST STRUCTURE # 11666 BROOKLYN NY	NE	0.03 / 133.09	15
CON EDISON	322 GREEN AVE SB 11666 BROOKLYN NY 11238	NE	0.03 / 133.09	15
CON EDISON	322 GREEN ST STRUCTURE # 11666 BROOKLYN NY	NE	0.03 / 133.09	15
CON EDISON	359 GREENE ST TM 808 BROOKLYN NY 11201	NE	0.04 / 231.42	28
CON EDISON	PROVOST ST & HURON SB4306 BROOKLYN NY 11201	E	0.07 / 357.11	42
BAY CRANE SERVICE INC	255 FREEMAN ST BROOKLYN NY	N	0.09 / 470.39	55
CON EDISON	220 EAGLE ST SB7251 BROOKLYN NY 11217	N	0.11 / 569.08	66
NYCDEP - NEWTON CREEK WPCP	329 GREENPOINT AVENUE BROOKLYN NY 11222	NE	0.12 / 649.95	77
NYC DEP	329 GREENPOINT AVE BROOKLYN NY 11201	NE	0.12 / 649.95	77
EXXON COMPANY USA 3020	320 FREEMAN ST BROOKLYN NY 11222	NE	0.12 / 649.95	77

TIER 2 - Tier 2 Report

A search of the TIER 2 database, dated Sep 28, 2022 has found that there are 10 TIER 2 site(s) within approximately 0.12miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Ciner Chemical& Refining Co	248 Green Street Brooklyn NY 11222	NE	0.01 / 66.25	8
Nuvite Chemical Compounds Corp., 213 Freeman St., Brooklyn, NY 11222	NY	NW	0.10 / 527.09	60
NuVite Chemical Compounds Corp. 213 Freeman St. Brooklyn NY 11222	NY	NW	0.10 / 527.09	60
Nuvite Chemical Compounds, 213 Freeman St., Brooklyn, NY 11222	Kings NY	NW	0.10 / 527.09	60


Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Skanska/Picone JV II 252 Java St. Brooklyn, NY 11222	NY	SE	0.11 / 603.40	69
Welsbach Electric Corp. 252 Java St. Brooklyn, NY 11222	NY	SE	0.11 / 603.40	69
Welsbach Electrical Corp. 252 Java St., Brooklyn, NY 11222 (REVISION)	NY	SE	0.11 / 603.40	69
Nyc Dep Bwt Newtown Creek Wpcp	329 Greenpoint Ave Brooklyn NY	NE	0.12 / 649.95	77
Nyc Dep Bwt Newtown Creek Wpcp	329 Greenpoint Ave Brooklyn NY 11222	NE	0.12 / 649.95	77
NYC DEP BWT Newtown Creek WPCP	329 Greenpoint Ave Brooklyn NY 11222	NE	0.12 / 649.95	77

AIR PERMITS - Air Permitted Facilities

A search of the AIR PERMITS database, dated Jan 31, 2024 has found that there are 2 AIR PERMITS site(s) within approximately 0.25 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEWTOWN CREEK WASTEWATER RESOURCE RECOVERY FACILITY	329-69 GREENPOINT AVE BROOKLYN NY 11222	NE	0.12 / 649.95	77

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
DIAMOND ASPHALT CORPORATION	91 Paidge Ave Brooklyn NY 11222	NE	0.21 / 1,090.66	130



Map: 1.0 Mile Radius


Order Number: 25010100008

Address: 247 Huron Street, Brooklyn, NY

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.5 Mile Radius


Order Number: 25010100008

Address: 247 Huron Street, Brooklyn, NY

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.25 Mile Radius

Order Number: 25010100008

Address: 247 Huron Street, Brooklyn, NY

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.




Aerial **Year: 2022**

Address: 247 Huron Street, Brooklyn, NY

Source: ESRI World Imagery

Order Number: 25010100008

© ERIS Information Inc.



Topographic Map

Year: 2019

Order Number: 25010100008

Address: 247 Huron Street, NY

Quadrangle(s): Brooklyn NY, Central Park NY,NJ

Source: USGS Topographic Map

© ERIS Information Inc.

Detail Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	1 of 2	SSW	0.00 / 0.00	12.03 / 0	RZ METAL CORP 247 HURON ST BROOKLYN NY 11222	NY SPILLS

Spill No:	0011791	**UST Trust:**	False
Site ID:	67947	**Spill Date:**	02/01/2001 10:55:00 AM
DER Facility ID:	64852	**Received Date:**	02/01/2001 11:04:00 AM
CID:	390	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	12/29/2005 12:00:00 AM
Water Body:		**Create Date:**	02/01/2001 12:00:00 AM
Class:	C3	**Update Date:**	03/31/2006 10:00:16 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	CXWHITFI
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	DEC		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"unk material ifo the above business - will call spill response as soon as this call is terminated"

DEC Remark:

"assigned to C. Whitfield in acklog initiative; no files received from region. Spoke to Joel Lehrman of R & Z Metals on 12/21/05. He said the unknown material was a biodegradable substance, for which they paid a fine in court. He does not recall which court. He may be confusing this incident with a May 2000 spill of 25 gallons of methylene diphenyldiisocyanate that was absorbed and contained. Since there are no other resources to contact, the spill report says 0 gallons spilled, and the company is still operating in the building, I am closing the spill per guidance issued with initiative."

Material Information

OP Unit ID:	833165	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	542086	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0064A		
Material Name:	unknown material		

Spiller Information

Spiller Name:	UNK
Spiller Company:	RZ METAL CORP
Spiller Address:	247 HURON ST
Spiller City:	BROOKLYN
Spiller State:	ZZ
Spiller Zip:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Country:	001
Contact Name:	UNK
Contact Phone:	(000) 000-0000
Contact Ext:	
Latitude:	40.733429700
Longitude:	-73.951067880

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	2 of 2	SSW	0.00 / 0.00	12.03 / 0	MINERAL OIL SPILL 241-247 HURON STREET BROOKLYN NY	NY SPILLS

Spill No:	1403242	**UST Trust:**	False
Site ID:	496594	**Spill Date:**	06/25/2014 12:00:00 PM
DER Facility ID:	451535	**Received Date:**	06/25/2014 12:38:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	08/26/2014 12:00:00 AM
Water Body:		**Create Date:**	06/25/2014 12:42:00 PM
Class:		**Update Date:**	10/28/2015 01:31:19 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SXMAHAT
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Housekeeping		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"DEC Mahat and DEC Demeo on scene now - cleanup pending"

DEC Remark:

"6/25/14-Vought-Duty desk officer. This spill assigned to DEC Mahat as Mahat part of multi-unit investigation (Spills, ECO and DEP) to investigate possible sources of recent product and sheens observed in nearby Newtown Creek. 8/20/14: Mahat An email was received from the property owner about the clean up and requested a site visit. Here is the email: Tried to phone you. Would like you to come over and check repairs we have made. Thanks very much. Joel & Andrew Lehrman R & Z Metal Recycling Corp 236 Huron St. Brooklyn, NY 11222 718-383-8820 R & Z Metal Recycling 247 Huron Street Brooklyn, New York 11222 PH; 718-383-8820 Fax; 718-349-2751 E Mail; rzmetal@aol.com Joel Lehrman cell; 516-359-7742 Andrew Lehrman cell; 917-596-4064 DEC Mahat replied to the Mr. Andrew Lehrman mentioning a site visit will be perform on 8/21/14. 8/21/14: Mahat Site Visit: DEC Mahat perforemed an inspection for the clean up. The pit where heavy mineral oil was observed was cleand uo by PTC. Few picture were taken from the vicinity of the tank. A manifest and narrative clean up was provided to the Department. It is uploaded on D2. Based on the site visit and the manifest provided, the Department does not require any further investigation for remediation and deleination action. Hencce, the spill case will be close in the database as the clean up process was completed. "

Material Information

OP Unit ID:	1246077	**Med Ind Air:**	False
OU:	01	**Med GW:**	True
Material ID:	2247176	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	2630		
Material Name:	mineral oil		

Spiller Information

Spiller Name:	
Spiller Company:	ANDREW LEHRMAN - R&J METAL RECYCLING CORP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: TOSH MAHAD
Contact Phone: (646) 423-6247
Contact Ext:
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	1 of 7	SSW	0.00 / 0.00	12.03 / 0	J&J BRONZE & ALUMINUM CASTING CORP 249 HURON ST BROOKLYN NY 11222	RCRA SQG

EPA Handler ID: NYR000154658
Gen Status Universe: Small Quantity Generator
Contact Name: VINCENT GROSSO
Contact Address: PO BOX 351 , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext: 718-383-2111
Contact Email:
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20080207
Location Latitude: 40.733384
Location Longitude: -73.951153
Recycler Activity(YES/NO)?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date: 20110504
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity W.O. Stor: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20080207
Handler Name: J&J BRONZE & ALUMINUM CASTING CORP
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20080208
Handler Name: J&J BRONZE & ALUMINUM CASTING CORP
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: J&J BRONZE & ALUMINIUM CASTING CORP
Date Became Current: 19780701
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1:
Street 2:
City:
State:
Country:
Zip Code:

Owner/Operator Ind: Current Owner
Type: Private
Name: J&J BRONZE & ALUMINIUM CASTING CORP
Date Became Current: 19780701
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1:
Street 2:
City:
State:
Country:
Zip Code:

Historical Handler Details

Receive Dt: 20080208
Generator Code Description: Small Quantity Generator
Handler Name: J&J BRONZE & ALUMINUM CASTING CORP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	2 of 7	SSW	0.00 / 0.00	12.03 / 0	APRT 249 HURON STREET BROOKLYN NY	NY SPILLS

Spill No: 0710964
Site ID: 392358
DER Facility ID: 341956
CID: 444
Program Type: ER
SWIS Code: 2401
Water Body:
Class:
Meets Std: False
Penalty: False
REM Phase: 0
UST Trust:
Spill Date: 01/16/2008 01:52:00 PM
Received Date: 01/16/2008 01:52:00 PM
CAC Date:
Insp Date:
Close Date: 01/31/2008 12:00:00 AM
Create Date: 01/16/2008 02:09:00 PM
Update Date: 01/31/2008 03:14:00 PM
DEC Region: 2
Lead DEC: hrpatel
After Hours: False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County: Kings
Contributing Factor: Unknown
Reported by: Local Agency
Referred to:
Source: Unknown
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"NO FURTHER INFO AVAILABLE"

DEC Remark:

"insufficient information. case closed."

Material Information

OP Unit ID:	1149367	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2139892	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		

Material Code: 0066A
Material Name: unknown petroleum

Spiller Information

Spiller Name: SHAWN DONOHUE
Spiller Company: APRT
Spiller Address: 249 HURON STREET
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: SHAWN DONOHUE
Contact Phone: (718) 595-5000
Contact Ext:
Latitude: 40.733466000
Longitude: -73.950877000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	3 of 7	SSW	0.00 / 0.00	12.03 / 0	J & J BRONZE & ALUMINUM CASTING CORP 249 HURON STREET BROOKLYN NY 11222-1801	FINDS/FRS

Registry ID: 110000323383
FIPS Code: 36047
HUC Code: 02030201
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 01-MAR-00
Update Date: 31-DEC-15
Interest Types: COMPLIANCE ACTIVITY, OSHA ESTABLISHMENT, SQG, TRI REPORTER
SIC Codes: 3365, 3366
SIC Code Descriptions: ALUMINUM FOUNDRIES, COPPER FOUNDRIES
NAICS Codes: 331524, 331525
NAICS Code Descriptions: ALUMINUM FOUNDRIES (EXCEPT DIE-CASTING)., COPPER FOUNDRIES (EXCEPT DIE-CASTING).
Conveyor: FRS-GEOCODE
Federal Facility Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 12
Census Block Code: 360470579002025
EPA Region Code: 02
County Name: KINGS
US/Mexico Border Ind:
Latitude: 40.73339
Longitude: -73.95087
Reference Point: CENTER OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 30
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110000323383
Data Source: Facility Registry Service - Single File
Program Acronyms:

2	4 of 7	SSW	0.00 / 0.00	12.03 / 0	J & J BRONZE & ALUMINUM CASTING CORP 249 HURON STREET BROOKLYN NY 11222-1801	ICIS

EPA Region: 02
Registry ID: 110000323383
Pgm Sys ID: NYR000154658
Pgm Sys Acrnm: RCRAINFO
Permit Type:
Federal Fac ID:
Tribal Land Code:
County: Kings
Latitude 83: 40.73336
Longitude 83: -73.95109

2	5 of 7	SSW	0.00 / 0.00	12.03 / 0	J&J BRONZE & ALUMINUM CASTING CORP 249 HURON ST BROOKLYN NY 11222	GEN MANIFEST

RCRA ID: NYR000154658
District Name: J&J BRONZE & ALUMINUM CASTING CORP
Contact Name: ROBERT A GROSSO
Business Phone No: 7183832111
Mailing Street 1: 249 HURON ST
Mailing Street 2:
Mailing City: BROOKLYN
Mailing State: NY
Mailing ZIP: 11222
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)
D006: CADMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2008: 5500 Pounds

2	6 of 7	SSW	0.00 / 0.00	12.03 / 0	J & J BRONZE & ALUMINUM CASTING 249 HURON ST BROOKLYN NY 11222	GEN MANIFEST

RCRA ID: NYP000946749
District Name: J & J BRONZE & ALUMINUM CASTING
Mailing State: NY
Mailing ZIP: 11222

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Name:	ROBERT A GRASSO	**Mailing ZIP Ext:**	
Business Phone No:	7183832111	**Mailing Country:**	USA
Mailing Street 1:	249 HURON ST	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	BROOKLYN	**Location County:**	KINGS

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2000: 6000 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2000: 800 Pounds; 50 Gallons; 400 Pounds

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	7 of 7	SSW	0.00 / 0.00	12.03 / 0	J & J BRONZE & ALUMINUM CASTING CORP 249 HURON ST BROOKLYN NY 11222	TRIS

TRI FD:	11222JJBRN249HU
FRS ID:	110000323383
BIA:	
Tribe:	
Facility Name:	J & J BRONZE & ALUMINUM CASTING CORP
Street Address:	249 HURON ST
City:	BROOKLYN
County:	KINGS
State:	NY
Zip:	11222
Latitude:	40.733360
Longitude:	-73.951090

1993 Details

TRI FD:	11222JJBRN249HU	**Underground:**	0.000000
Federal Facility:	NO	**Underground CL I:**	0.000000
Cas No Compound ID:	0007429905	**Underground C II-V:**	0.000000
Classification:	TRI	**Landfills:**	0.000000
Primary SIC:	3365	**RCRA C Landfill:**	0.000000
Primary NAICS:	331524	**Other Landfills:**	0.000000
Metal:	NO	**Land Treatment:**	0.000000
Carcinogen:	NO	**Surface Impndmnt:**	0.000000
Fugitive Air:	5.000000	**RCRA Surface IM:**	0.000000
Stack Air:	0.000000	**Other Surface I:**	0.000000
Water:	0.000000	**Other Disposal:**	0.000000

Chemical:	Aluminum (fume or dust)
Industry Sector Code:	331
Industry Sector:	Primary Metals
Parent Co Name:	J & J BRONZE & ALUMINUM CASTING CORP
On Site Release Total:	5.000000
Off Site Release Total:	0.000000

Off Site Recycled Total: 0.000000
Total Releases: 5.000000
One Time Release:

Horizontal Datum:

NAD83

CAS No:

7429-90-5

PFAS:

NO

PBT:

NO

1995 Details

TRI FD:	11222JJBRN249HU	***Underground:***	0.000000
Federal Facility:	NO	***Underground CL I:***	0.000000
Cas No Compound ID:	0007429905	***Underground C II-V:***	0.000000
Classification:	TRI	***Landfills:***	0.000000
Primary SIC:	3365	***RCRA C Landfill:***	0.000000
Primary NAICS:	331524	***Other Landfills:***	0.000000
Metal:	NO	***Land Treatment:***	0.000000
Carcinogen:	NO	***Surface Impndmnt:***	0.000000
Fugitive Air:	10.000000	***RCRA Surface IM:***	0.000000
Stack Air:	0.000000	***Other Surface I:***	0.000000
Water:	0.000000	***Other Disposal:***	0.000000

Chemical: Aluminum (fume or dust)
Industry Sector Code: 331
Industry Sector: Primary Metals
Parent Co Name: J & J BRONZE & ALUMINUM CASTING CORP
On Site Release Total: 10.000000
Off Site Release Total: 0.000000
Off Site Recycled Total: 0.000000
Total Releases: 10.000000
One Time Release:

Horizontal Datum:

NAD83

CAS No:

7429-90-5

PFAS:

NO

PBT:

NO

1997 Details

TRI FD:	11222JJBRN249HU	***Underground:***	0.000000
Federal Facility:	NO	***Underground CL I:***	0.000000
Cas No Compound ID:	0007429905	***Underground C II-V:***	0.000000
Classification:	TRI	***Landfills:***	0.000000
Primary SIC:	3365	***RCRA C Landfill:***	0.000000
Primary NAICS:	331524	***Other Landfills:***	0.000000

Metal:	NO	***Land Treatment:***	0.000000
Carcinogen:	NO	***Surface Impndmnt:***	0.000000
Fugitive Air:	10.000000	***RCRA Surface IM:***	0.000000
Stack Air:	0.000000	***Other Surface I:***	0.000000
Water:	0.000000	***Other Disposal:***	0.000000

Chemical: Aluminum (fume or dust)
Industry Sector Code: 331
Industry Sector: Primary Metals
Parent Co Name: J & J BRONZE & ALUMINUM CASTING CORP
On Site Release Total: 10.000000
Off Site Release Total: 0.000000
Off Site Recycled Total: 0.000000
Total Releases: 10.000000
One Time Release:

Horizontal Datum:

NAD83

CAS No:

7429-90-5

PFAS:

NO

PBT:

NO

1998 Details

TRI FD:	11222JJBRN249HU	***Underground:***	0.000000
Federal Facility:	NO	***Underground CL I:***	0.000000
Cas No Compound ID:	0007429905	***Underground C II-V:***	0.000000
Classification:	TRI	***Landfills:***	0.000000
Primary SIC:	3365	***RCRA C Landfill:***	0.000000
Primary NAICS:	331524	***Other Landfills:***	0.000000
Metal:	NO	***Land Treatment:***	0.000000
Carcinogen:	NO	***Surface Impndmnt:***	0.000000
Fugitive Air:	0.000000	***RCRA Surface IM:***	0.000000
Stack Air:	0.000000	***Other Surface I:***	0.000000
Water:	0.000000	***Other Disposal:***	0.000000

Chemical: Aluminum (fume or dust)
Industry Sector Code: 331
Industry Sector: Primary Metals
Parent Co Name: J & J BRONZE & ALUMINUM CASTING CORP
On Site Release Total: 0.000000
Off Site Release Total: 0.000000
Off Site Recycled Total: 0.000000
Total Releases: 0.000000
One Time Release:

Horizontal Datum:

NAD83

CAS No:

7429-90-5

PFAS:

NO

PBT:

NO

2000 Details

TRI FD:	11222JJBRN249HU	***Underground:***	0.000000
Federal Facility:	NO	***Underground CL I:***	0.000000
Cas No Compound ID:	0007429905	***Underground C II-V:***	0.000000
Classification:	TRI	***Landfills:***	0.000000
Primary SIC:	3365	***RCRA C Landfill:***	0.000000
Primary NAICS:	331524	***Other Landfills:***	0.000000
Metal:	NO	***Land Treatment:***	0.000000
Carcinogen:	NO	***Surface Impndmnt:***	0.000000
Fugitive Air:	10.000000	***RCRA Surface IM:***	0.000000
Stack Air:	0.000000	***Other Surface I:***	0.000000
Water:	0.000000	***Other Disposal:***	0.000000

Chemical: Aluminum (fume or dust)
Industry Sector Code: 331
Industry Sector: Primary Metals
Parent Co Name: J & J BRONZE & ALUMINUM CASTING CORP
On Site Release Total: 10.000000
Off Site Release Total: 0.000000
Off Site Recycled Total: 0.000000
Total Releases: 10.000000
One Time Release:

Horizontal Datum:

NAD83

CAS No:

7429-90-5

PFAS:

NO

PBT:

NO

2004 Details

TRI FD:	11222JJBRN249HU	***Underground:***	0.000000
Federal Facility:	NO	***Underground CL I:***	0.000000
Cas No Compound ID:	0007429905	***Underground C II-V:***	0.000000
Classification:	TRI	***Landfills:***	0.000000
Primary SIC:	3365	***RCRA C Landfill:***	0.000000
Primary NAICS:	331524	***Other Landfills:***	0.000000
Metal:	NO	***Land Treatment:***	0.000000
Carcinogen:	NO	***Surface Impndmnt:***	0.000000
Fugitive Air:	0.000000	***RCRA Surface IM:***	0.000000
Stack Air:	0.000000	***Other Surface I:***	0.000000
Water:	0.000000	***Other Disposal:***	0.000000

Chemical: Aluminum (fume or dust)
Industry Sector Code: 331
Industry Sector: Primary Metals
Parent Co Name: J & J BRONZE & ALUMINUM CASTING CORP
On Site Release Total: 0.000000
Off Site Release Total: 0.000000
Off Site Recycled Total: 0.000000
Total Releases: 0.000000
One Time Release:

Horizontal Datum:

NAD83

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CAS No:

7429-90-5

PFAS:

NO

PBT:

NO

---

3 | ***1 of1*** | ***W*** | ***0.01 / 37.86*** | ***12.37 / 0*** | ***MC GUINNESS MANAGEMENT CORP***
231 HURON STREET
BROOKLYN NY 11222 | ***FINDS/FRS***

Registry ID:	110019433264
FIPS Code:	
HUC Code:	02030201
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	20-NOV-04
Update Date:	29-OCT-14
Interest Types:	STATE MASTER
SIC Codes:	7532
SIC Code Descriptions:	TOP, BODY, AND UPHOLSTERY REPAIR SHOPS AND PAINT SHOPS
NAICS Codes:	811121
NAICS Code Descriptions:	AUTOMOTIVE BODY, PAINT, AND INTERIOR REPAIR AND MAINTENANCE.
Conveyor:	FRS-GEOCODE
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	12
Census Block Code:	360470579002025
EPA Region Code:	02
County Name:	KINGS
US/Mexico Border Ind:	
Latitude:	40.73331
Longitude:	-73.95163
Reference Point:	CENTER OF A FACILITY OR STATION
Coord Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value:	30
Datum:	NAD83
Source:	
Facility Detail Rprt URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110019433264
Data Source:	Facility Registry Service - Single File
Program Acronyms:	

---

4 | ***1 of1*** | ***N*** | ***0.01 / 48.00*** | ***11.99 / 0*** | ***KEYSTONE AUTO REPAIR INC***
DBA KEY AUTO CENTER
240 GREEN STREET
Brooklyn NY 11222 | ***AST***

Site ID:	28976	***Expiry:***	N/A
Site Status:	Unregulated/Closed	***County:***	Kings
Program No:	2-607122	***UTM X:***	588552.11726
Program Type Code:	PBS	***UTM Y:***	4509756.97827
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Other		

Tank Information

Prog No:	2-607122	***UDC Ind:***	1
Tank ID:	62358	***Red Tag Start Date:***	
Tank No:	001	***Red Tag End Date:***	
Tank Status:	5	***Tank Last Test:***	
Tank Status Desc:	Tank Converted to Non-Regulated Use	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:		***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	55	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: waste oil/used oil
Percent: 100.00

Equipment Information

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: I00
Code Name: None
Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: J00
Code Name: None

Type: Dispenser

Tank Information

Prog No:	2-607122	***UDC Ind:***	1
Tank ID:	62359	***Red Tag Start Date:***	
Tank No:	002	***Red Tag End Date:***	
Tank Status:	5	***Tank Last Test:***	
Tank Status Desc:	Tank Converted to Non-Regulated Use	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:		***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	55	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: waste oil/used oil
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: J00
Code Name: None
Type: Dispenser

Affiliation Information

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: KEYSTONE AUTO REPAIR INC DBA KEY AUTO CENTER
Contact Title:
Contact Name: BRUCE RABINOWITZ
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-6009
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: KEY AUTO CENTER
Contact Title:
Contact Name:
Address1: 240 GREEN STREET
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 389-6009
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: KEY AUTO CENTER
Contact Title:
Contact Name: BRUCE RABINOWITZ
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-6009
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: KEY AUTO CENTER
Contact Title:
Contact Name: BRUCE RABINOWITZ
Address1: 240 GREEN STEET
Address2:
City: BROOKLYN
State: NY

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Zip Code:	11222
Country Code:	001
Phone:	(718) 389-6009
Phone Ext:	
Email:	
Fax:	

---

5 | **1 of3** | **NW** | **0.01 / 48.43** | **12.02 / 0** | **CON EDISON - MANHOLE 8545**
234 GREEN ST
BROOKLYN NY 11222 | **FINDS/FRS**

Registry ID:	110055934850
FIPS Code:	36047
HUC Code:	02030201
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	17-SEP-13
Update Date:	27-JAN-15
Interest Types:	HAZARDOUS WASTE BIENNIAL REPORTER, LQG
SIC Codes:	
SIC Code Descriptions:	
NAICS Codes:	221122
NAICS Code Descriptions:	ELECTRIC POWER DISTRIBUTION.
Conveyor:	FRS-GEOCODE
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	12
Census Block Code:	360470579002026
EPA Region Code:	02
County Name:	KINGS
US/Mexico Border Ind:	
Latitude:	40.73405
Longitude:	-73.95149
Reference Point:	CENTER OF A FACILITY OR STATION
Coord Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value:	30
Datum:	NAD83
Source:	
Facility Detail Rprt URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110055934850
Data Source:	Facility Registry Service - Single File
Program Acronyms:	

---

5 | **2 of3** | **NW** | **0.01 / 48.43** | **12.02 / 0** | **CON EDISON - MANHOLE 8545**
234 GREEN ST
BROOKLYN NY 11222 | **RCRA LQG**

EPA Handler ID:	NYP004296745
Gen Status Universe:	Large Quantity Generator
Contact Name:	DENNIS HUACON
Contact Address:	4 , IRVING PLACE, 15TH FL NE , , NEW YORK , NY, 10003 , US
Contact Phone No and Ext:	212-460-2757
Contact Email:	HUACOND@CONED.COM
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20140327
Location Latitude:	40.73374
Location Longitude:	-73.954825
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20130327
Handler Name:	CON EDISON MANHOLE: 8545
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Emergency

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20130427
Handler Name:	CON EDISON MANHOLE: 8545
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20140327
Handler Name:	CON EDISON - MANHOLE 8545
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator
Source Type:	Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	4
Type:	Private	***Street 1:***	IRVING PLACE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20130327	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003
Owner/Operator Ind:	Current Operator	**Street No:**	4
Type:	Private	**Street 1:**	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20130327	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003

Historical Handler Details

Receive Dt:	20130427
Generator Code Description:	Not a Generator, Verified
Handler Name:	CON EDISON MANHOLE: 8545
Receive Dt:	20130327
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CON EDISON MANHOLE: 8545

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
5	3 of3	NW	0.01 / 48.43	12.02 / 0	CON EDISON 234 GREEN ST BROOKLYN NY 11222	GEN MANIFEST

RCRA ID:	NYP004296745	**Mailing State:**	NY
District Name:	CON EDISON	**Mailing ZIP:**	10003
Contact Name:	TOM TEELING	**Mailing ZIP Ext:**	
Business Phone No:	2124603770	**Mailing Country:**	USA
Mailing Street 1:	4 IRVING PLACE - 15TH FLOOR	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	NEW YORK	**Location County:**	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2013: 800 Gallons

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	1 of2	NW	0.01 / 49.28	12.02 / 0	C C BODY SHOP 230 GREEN ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID:	NYR000046607
Gen Status Universe:	No Report
Contact Name:	CARLOS CHAZEAU
Contact Address:	230 , GREEN ST , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:	718-937-7094
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20070101
Location Latitude:	40.733983

Location Longitude: -73.952044
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19971106
Handler Name: C C BODY SHOP
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20060101
Handler Name:	C C BODY SHOP
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20070101
Handler Name:	C C BODY SHOP
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	230 GREEN ST
Name:	CARLOS CHAZEAU	***Street 2:***	
Date Became Current:		***City:***	BROOKLYN
Date Ended Current:		***State:***	NY
Phone:	718-937-7094	***Country:***	US
Source Type:	Implementer	***Zip Code:***	11222

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	230 GREEN ST
Name:	CARLOS CHAZEAU	***Street 2:***	
Date Became Current:		***City:***	BROOKLYN
Date Ended Current:		***State:***	NY
Phone:	718-937-7094	***Country:***	
Source Type:	Notification	***Zip Code:***	11222

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	230 GREEN ST
Name:	CARLOS CHAZEAU	***Street 2:***	
Date Became Current:		***City:***	BROOKLYN
Date Ended Current:		***State:***	NY
Phone:	718-937-7094	***Country:***	US
Source Type:	Implementer	***Zip Code:***	11222

Historical Handler Details

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	C C BODY SHOP

Receive Dt:	19971106
Generator Code Description:	Very Small Quantity Generator
Handler Name:	C C BODY SHOP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	2 of2	NW	0.01 / 49.28	12.02 / 0	C C BODY SHOP 230 GREEN ST BROOKLYN NY 11222	FINDS/FRS

Registry ID:	110004538395
FIPS Code:	36047
HUC Code:	02030201
Site Type Name:	STATIONARY
Location Description:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Supplemental Location:	
Create Date:	01-MAR-00
Update Date:	09-AUG-10
Interest Types:	UNSPECIFIED UNIVERSE
SIC Codes:	
SIC Code Descriptions:	
NAICS Codes:	
NAICS Code Descriptions:	
Conveyor:	FRS-GEOCODE
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	12
Census Block Code:	360470579002026
EPA Region Code:	02
County Name:	KINGS
US/Mexico Border Ind:	
Latitude:	40.73404
Longitude:	-73.95165
Reference Point:	CENTER OF A FACILITY OR STATION
Coord Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value:	30
Datum:	NAD83
Source:	
Facility Detail Rprt URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110004538395
Data Source:	Facility Registry Service - Single File
Program Acronyms:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
7	1 of1	E	0.01 / 49.35	11.66 / 0	AJB BUILDERS & CO. 251 HURON ST BROOKLYN NY 11222	FINDS/FRS

Registry ID:	110055291170
FIPS Code:	
HUC Code:	02030201
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	27-JUN-13
Update Date:	
Interest Types:	STATE MASTER
SIC Codes:	7692
SIC Code Descriptions:	WELDING REPAIR
NAICS Codes:	
NAICS Code Descriptions:	
Conveyor:	FRS-GEOCODE
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	12
Census Block Code:	360470579002025
EPA Region Code:	02
County Name:	KINGS
US/Mexico Border Ind:	
Latitude:	40.733362
Longitude:	-73.951112
Reference Point:	ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value:	50
Datum:	NAD83
Source:	
Facility Detail Rprt URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110055291170
Data Source:	Facility Registry Service - Single File
Program Acronyms:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	1 of5	NE	0.01 / 66.25	11.72 / 0	CINER CHEMICAL & REFINING CO 246 GREEN ST BROOKLYN NY 11222	FINDS/FRS

Registry ID:	110046098085
FIPS Code:	36047
HUC Code:	02030201
Site Type Name:	STATIONARY
Location Description:	246 GREEN ST
Supplemental Location:	
Create Date:	25-JUN-12
Update Date:	05-FEB-16
Interest Types:	AIR MINOR, STATE MASTER
SIC Codes:	5093
SIC Code Descriptions:	SCRAP AND WASTE MATERIALS
NAICS Codes:	
NAICS Code Descriptions:	
Conveyor:	FRS-GEOCODE
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	12
Census Block Code:	360470579002026
EPA Region Code:	02
County Name:	KINGS
US/Mexico Border Ind:	
Latitude:	40.7341
Longitude:	-73.95094
Reference Point:	CENTER OF A FACILITY OR STATION
Coord Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value:	30
Datum:	NAD83
Source:	
Facility Detail Rprt URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110046098085
Data Source:	Facility Registry Service - Single File
Program Acronyms:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	2 of5	NE	0.01 / 66.25	11.72 / 0	CINER CHEMICAL & REFINING CO 246 GREEN ST BROOKLYN NY 11222	ICIS

EPA Region:	02	**Federal Fac ID:**	
Registry ID:	110046098085	**Tribal Land Code:**	
Pgm Sys ID:	NY0000NY2610100654	**County:**	Kings
Pgm Sys Acrnm:	AIR	**Latitude 83:**	40.73402
Permit Type:		**Longitude 83:**	-73.951848

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	3 of5	NE	0.01 / 66.25	11.72 / 0	CINER CHEMICAL & REFINING CO 246 GREEN ST BROOKLYN NY 11222	ICIS

EPA Region:	02	**Federal Fac ID:**	
Registry ID:	110046098085	**Tribal Land Code:**	
Pgm Sys ID:	NY0000002610100654	**County:**	Kings
Pgm Sys Acrnm:	AIR	**Latitude 83:**	40.73402
Permit Type:		**Longitude 83:**	-73.951848

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	4 of5	NE	0.01 / 66.25	11.72 / 0	Ciner Chemical& Refining Co 248 Green Street Brooklyn NY 11222	TIER 2

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Company Name:
DUN Bradstreet Cd:
County: Kings County (Brooklyn)
Latitude:
Longitude:
Report Method: Reported via Mail

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	5 of5	NE	0.01 / 66.25	11.72 / 0	CINER CHEMICAL & REFINING CO 246 GREEN ST BROOKLYN NY 11222	AFS

Afs ID: 36047R7734
Plant ID: 1094052
Epa Region: 02
Plant County: Kings
State No: 36
Primary Sic Code: 5093
Secondary Sic Code:
Naics Code:
Afs Gov Facility Des: PRIVATELY OWNED/OPERATED
Operating Status Def: Operating
Epa Classification Des: Potential uncontrolled emissions <100 tons/year
Epa Compliance Status: In Compliance With Procedural Requirements
State Compliance Status: In Compliance With Procedural Requirements

Fed Reportable: No
Current Hpv:
Loc Contrl Region:
Afs Gov Fac Code: 0
Operating Status: O
Epa Class Code: B
Epa Complian Stat: C
State Comp Status: C

Actions

Plant ID: 1094052
Anu1: 300
Date Achieved: 20120531
Penalty Amount: 0
Record Updated Dt: 20121130
Creation Date: 20121130
Key Action No:
Regional Data Element:
National Action Desc: STATE PCE/ON-SITE
All Air Program Def: 0-SIP Source
Result Def: IN COMPLIANCE
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

National Actn Type: PS
All Air Prog Codes: 0
Result Code: MC
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:

Historical Compliance - Air Program Level

Air Program Code: 0
Air Program Code Ref: SIP Source
Historical Compliance Date: 1204, 1301, 1302, 1303, 1304, 1401, 1402, 1403
Historical Compliance Status: C
Historical Compliance Stat Ref: In Compliance With Procedural Requirements

Air Program

Plant ID: 1094052
Air Program Code: 0
Air Program Status: O
Pollutant Code: FACIL
Chemical Abstract Service Nmbr:
Air Program Code Subparts:
Air Program Code Ref: SIP Source
Epa Classification Code Ref: Potential uncontrolled emissions <100 tons/year
Epa Compliance Status Ref: In Compliance With Procedural Requirements
Pollutant Code Ref:

Poll Classificatn: B
Poll Compli Status: C
Epa Class Code: B
Epa Compli Status: C

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Pollutant Classification Ref: Potential uncontrolled emissions <100 tons/year
Pollutant Complian Status Ref: In Compliance With Procedural Requirements

---

9 | **1 of1** | **NNE** | **0.02 / 104.52** | **11.69 / 0** | **PRIVATE RESIDENCE**
298 GREEN AVE
BROOKLYN NY | **NY SPILLS**

Spill No:	1206492	**UST Trust:**	False
Site ID:	469493	**Spill Date:**	10/01/2012 02:00:00 PM
DER Facility ID:	423797	**Received Date:**	10/01/2012 02:30:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	05/21/2014 12:00:00 AM
Water Body:		**Create Date:**	10/01/2012 02:32:00 PM
Class:	C4	**Update Date:**	05/21/2014 03:51:59 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	HRPATEL
REM Phase:	0	**After Hours:**	False

County: Kings
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Private Dwelling
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Tank is sweating oil. No oil on floor."

DEC Remark:

"Sangesland left a voicemail with the homeowner asking for more information on either repair or replacement on the tank. 05/21/14-Hiralkumar Patel. due to nature of the spill and based on available information, case closed administratively."

Material Information

OP Unit ID:	1219387	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2217891	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0001A
Material Name: #2 fuel oil

Spiller Information

Spiller Name: HENRY CRUZ
Spiller Company: PROPERTY OWNER
Spiller Address: 298 GREEN AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: DIECKMANN RESIDENCE
Contact Phone: 7186245579
Contact Ext:
Latitude: 40.687435000
Longitude: -73.958940000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
10	1 of3	SSE	0.02 / 113.02	11.99 / 0	WING GONG LAUNDRY INC 240-244 HURON ST 240 HURON ST BROOKLYN NY 11222	UST

Site ID: 3892
Site Status: Inactive
Program No: 2-116165
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Unknown

Expiry: N/A
County: Kings
UTM X: 588564.20887
UTM Y: 4509646.45515

Tank Information

Prog No: 2-116165
Tank ID: 4107
Tank No: 001
Tank Status: 5
Tank Status Desc: Tank Converted to Non-Regulated Use
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date:
Close Date: 01/01/1994
Tk Out of Serv Dt:
Capacity (Gal): 5000
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Affiliation Information

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: DANNY MOY
Contact Title:
Contact Name: DANNY MOY
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-6733
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: WING GONG LAUNDRY INC
Contact Title:
Contact Name: SEUNG NG
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-4861
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: DANNY MOY
Contact Title:
Contact Name:
Address1: 21 MCGUINNESS BLVD
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 389-6733
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: ZZZ
Company: DANNY MOY
Contact Title:
Contact Name:
Address1: 21 MCGUINNESS BLVD
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 389-6733
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
10	2 of3	SSE	0.02 / 113.02	11.99 / 0	WING GONG LAUNDRY 240 HURON STREET Brooklyn NY 11222	UST

Site ID: 22705
Site Status: Unregulated/Closed
Program No: 2-600725
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Other

Expiry: N/A
County: Kings
UTM X: 588566.65845
UTM Y: 4509678.91484

Tank Information

Prog No: 2-600725
Tank ID: 43456
Tank No: 001
Tank Status: 4
Tank Status Desc: Closed - In Place
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date:
Close Date: 01/18/2007
Tk Out of Serv Dt:
Capacity (Gal): 3000
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: H00
Code Name: None

Type: Tank Leak Detection

Equipment: I05
Code Name: Vent Whistle
Type: Overfill

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Affiliation Information

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: WING GONG LAUNDRY
Contact Title:
Contact Name: NG
Address1: 240 HURON STREET
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 389-4861
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: WING GONG LAUNDRY
Contact Title: PRESIDENT
Contact Name: SEUNG NG
Address1: 240 HURON ST
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 389-4861
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: WING GONG LAUNDRY
Contact Title:
Contact Name: NG
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 999
Phone: (718) 389-4861
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: WING GONG LAUNDRY
Contact Title:
Contact Name: NG
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 999
Phone: (718) 389-4861
Phone Ext:
Email:
Fax:

10	***3 of3***	***SSE***	***0.02 / 113.02***	***11.99 / 0***	***WING GONG LAUNDRY/ROCKS & JEANS 240/250 HURON STREET BROOKLYN NY 11222***	***DELISTED DRYCLEANERS***

SR No:
DEC ID: 2-6101-00640
Zip Code 4: 1802
Current Bus:
Latitude:
Longitude:
Record Date: 28-OCT-2019
Original Source: DRYC

Shut Down:
Alt Solvent: Y
Perchloroethylene:
Phone: 718-383-7051
Reg Effective Date: N/A
Inspection Date: 10MAY3
Drop Shop:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	1 of2	SE	0.02 / 115.13	12.06 / 0	CON EDISON - SERVICE BOX 7507 250 HURON ST BROOKLYN NY 11222	RCRA LQG

EPA Handler ID: NYP005050018
Gen Status Universe: Large Quantity Generator
Contact Name: ALYSSA SOTTO
Contact Address: 4 , IRVING PLACE, 15TH FL NE , , NEW YORK , NY, 10003 , US
Contact Phone No and Ext: 212-460-2757
Contact Email: SOTTOA@CONED.COM
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20180410
Location Latitude: 40.732932
Location Longitude: -73.955589
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20180410
Handler Name: CON EDISON - SERVICE BOX 7507
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Owner/Operator Details

Owner/Operator Ind: Current Owner
Street No: 4

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type:	Private	**Street 1:**	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20170419	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:	212-460-2757	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003
Owner/Operator Ind:	Current Operator	**Street No:**	4
Type:	Private	**Street 1:**	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20170419	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:	212-460-2757	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003

11	2 of2	SE	0.02 / 115.13	12.06 / 0	CON EDISON - SERVICE BOX 7507 250 HURON ST BROOKLYN NY 11222	NY MANIFEST

RCRA ID:	NYP005050018	**Mailing Street 1:**	4 IRVING PL
District Name:	CON EDISON - SERVICE BOX 7507	**Mailing Street 2:**	
Business Phone No:		**Mailing City:**	NEW YORK
Contact Name:	CON EDISON	**Mailing State:**	NY
Location ZIP Ext:		**Mailing ZIP:**	10003
Location County:	KINGS	**Mailing ZIP Ext:**	
Location Country:	USA	**Mailing Country:**	USA

12	1 of1	N	0.02 / 116.27	11.69 / 0	CON EDISON 292 GREENE ST SB11660 BROOKLYN NY 11201	GEN MANIFEST

RCRA ID:	NYP004734703	**Mailing State:**	NY
District Name:	CON EDISON	**Mailing ZIP:**	10003
Contact Name:	CON EDISON	**Mailing ZIP Ext:**	
Business Phone No:		**Mailing Country:**	USA
Mailing Street 1:	4 IRVING PL	**Location ZIP Ext:**	
Mailing Street 2:	15TH FL	**Location Country:**	USA
Mailing City:	NEW YORK	**Location County:**	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 750 Pounds

13	1 of2	W	0.02 / 117.25	12.35 / 0	MCGUINNESS MANAGEMENT 330 MCGUINNESS BLVD BROOKLYN NY 11222-1820	RCRA NON GEN

EPA Handler ID:	NYR000141853
Gen Status Universe:	No Report
Contact Name:	SEBASTIAN OLSZEWSKI
Contact Address:	330 , MCGUINNESS BLVD , , BROOKLYN , NY, 11222-1820 , US
Contact Phone No and Ext:	718-349-7610
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02

Land Type:	Private
Receive Date:	20070101
Location Latitude:	40.733744
Location Longitude:	-73.952101
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Oct, 2024.

Violation Details

Found Violation:	Yes
Citation:	
Violation Short Description:	Listing - General
Violation Type:	261.A
Violation Determined Date:	20100414
Scheduled Compliance Date:	
Return to Compliance:	Documented
Actual Return to Compl:	20100414
Violation Responsible Agency:	State

Enforcement Details

Enforcement Type:	120
Enforcement Type Description:	WRITTEN INFORMAL
Enforcement Action Date:	20100420
Enf Disposition Status:	ACTION SATISFIED (CASE CLOSED)
Disposition Status Date:	20100420
Enforcement Lead Agency:	State
Proposed Penalty Amount:	
Final Amount:	
Paid Amount:	

Evaluation Details

Evaluation Start Date:	20100414
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Violation Short Description:	Listing - General
Return to Compliance Date:	20100414
Evaluation Agency:	State

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without	No

Storage:

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060914
Handler Name: MCGUINNESS MANAGEMENT
Source Type: Implementer
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060915
Handler Name: MCGUINNESS MANAGEMENT
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D040
Waste Code Description: TRICHLOROETHYLENE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: MCGUINNESS MANAGEMENT
Source Type: Implementer
Federal Waste Generator Code: N

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	
Name:	MARIE BARB REALITY	***Street 2:***	
Date Became Current:	19910101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Implementer	***Zip Code:***	

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	MCGUINNESS MANAGEMENT	***Street 2:***	
Date Became Current:	20010101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Implementer	***Zip Code:***	

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	
Name:	MARIE BARB REALITY	***Street 2:***	
Date Became Current:	19910101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	MCGUINNESS MANAGEMENT	***Street 2:***	
Date Became Current:	20010101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	

Historical Handler Details

Receive Dt: 20060915
Generator Code Description: Small Quantity Generator
Handler Name: MCGUINNESS MANAGEMENT

Receive Dt: 20060914
Generator Code Description: Small Quantity Generator
Handler Name: MCGUINNESS MANAGEMENT

---

13 | ***2 of2*** | ***W*** | ***0.02 / 117.25*** | ***12.35 / 0*** | ***MCGUINNESS MANAGEMENT***
330 MCGUINNESS BLVD
BROOKLYN NY 11222 | ***GEN MANIFEST***

RCRA ID:	NYR000141853	***Mailing State:***	NY
District Name:	MCGUINNESS MANAGEMENT	***Mailing ZIP:***	11222
Contact Name:	NOEL BELGRACE	***Mailing ZIP Ext:***	
Business Phone No:	7183894483	***Mailing Country:***	USA
Mailing Street 1:	330 MCGUINNESS BLVD	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	BROOKLYN	***Location County:***	KINGS

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)
D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)

F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*
F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)

Waste Amounts By Year:

2016: 350 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)
D035: METHYL ETHYL KETONE (Waste Code Description from EPA Hazardous Waste Identification)
D039: TETRACHLOROETHYLENE (Waste Code Description from EPA Hazardous Waste Identification)
D040: TRICHLORETHYLENE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 40 Pounds; 35 Pounds; 100 Pounds; 40 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)
D035: METHYL ETHYL KETONE (Waste Code Description from EPA Hazardous Waste Identification)
D039: TETRACHLOROETHYLENE (Waste Code Description from EPA Hazardous Waste Identification)
D040: TRICHLORETHYLENE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2018: 385 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)
D035: METHYL ETHYL KETONE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*
F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)

Waste Amounts By Year:

2009: 110 Pounds; 60 Pounds; 36 Pounds; 36 Pounds
2010: 35 Pounds; 36 Pounds; 36 Pounds; 80 Pounds
2011: 36 Pounds; 35 Pounds; 25 Pounds; 36 Pounds; 36 Pounds; 80 Pounds; 110 Pounds; 25 Pounds
2012: 36 Pounds; 110 Pounds; 36 Pounds; 100 Pounds; 36 Pounds; 110 Pounds; 110 Pounds
2015: 300 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2013: 45 Gallons

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2014: 55 Gallons

14	1 of1	SW	0.02 / 126.67	12.46 / 0	S.C. TRUCK & AUTO REPAIR INC. 314 MCGUINESS BOULEVARD Brooklyn NY 11222	AST

Site ID:	29957	***Expiry:***	11/04/2012
Site Status:	Active	***County:***	Kings
Program No:	2-608105	***UTM X:***	588505.25133
Program Type Code:	PBS	***UTM Y:***	4509660.62118
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Other		

Tank Information

Prog No:	2-608105	***UDC Ind:***	1
Tank ID:	64466	***Red Tag Start Date:***	
Tank No:	001	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	05/01/2001	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	55	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			
Tank Location:	1		
Tank Location Desc:	Aboveground-contact w/ soil		
Category:	2		
Category Desc:	Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015		

Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: waste oil/used oil
Percent: 100.00

Equipment Information

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: G10
Code Name: Impervious Underlayment
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Tank Information

Prog No:	2-608105	**UDC Ind:**	1
Tank ID:	64467	**Red Tag Start Date:**	
Tank No:	002	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	05/01/2001	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	55	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	1		

Tank Location Desc: Aboveground-contact w/ soil
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: waste oil/used oil
Percent: 100.00

Equipment Information

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: G10
Code Name: Impervious Underlayment
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Tank Information

Prog No:	2-608105	**UDC Ind:**	1
Tank ID:	64468	**Red Tag Start Date:**	
Tank No:	003	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	05/01/2001	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	55	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI

Tank Model: **Last Modified:** 05/09/2022
Pipe Model:
Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: waste oil/used oil
Percent: 100.00

Equipment Information

Equipment: I00
Code Name: None
Type: Overfill

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G10
Code Name: Impervious Underlayment
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Affiliation Information

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: S.C. TRUCK & AUTO REPAIR INC.
Contact Title:
Contact Name: CHARLES GOODMAN
Address1: 314 MCGUINESS BOULEVARD
Address2:
City: BROOKLYN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 349-9822
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: S.C. TRUCK & AUTO REPAIR INC.
Contact Title:
Contact Name: CHARLES GOODMAN
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 349-9822
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: S.C. TRUCK & AUTO REPAIR INC.
Contact Title:
Contact Name: CHARLES GOODMAN
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 349-9822
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: S.C. TRUCK & AUTO REPAIR INC.
Contact Title:
Contact Name:
Address1: 314 MCGUINESS BLVD.
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 349-9822
Phone Ext:
Email:
Fax:

15	1 of3	NE	0.03 / 133.09	11.38 / -1	CON EDISON 322 GREEN ST STRUCTURE # 11666 BROOKLYN NY	GEN MANIFEST

RCRA ID: NYP004669065
District Name: CON EDISON
Contact Name: CON EDISON
Business Phone No: 2124603770
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Mailing Street 1:	4 IRVING PL 15TH FL	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	NEW YORK	**Location County:**	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2014: 20 Gallons

15	*2 of3*	*NE*	*0.03 / 133.09*	*11.38 / -1*	***CON EDISON*** ***322 GREEN AVE SB 11666*** ***BROOKLYN NY 11238***	***GEN MANIFEST***

RCRA ID:	NYP004625265	**Mailing State:**	NY
District Name:	CON EDISON	**Mailing ZIP:**	10003
Contact Name:	TOM TEELING	**Mailing ZIP Ext:**	
Business Phone No:		**Mailing Country:**	USA
Mailing Street 1:	4 IRVING PLACE 15TH FLOOR	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	NEW YORK	**Location County:**	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2014: 60 Gallons

15	*3 of3*	*NE*	*0.03 / 133.09*	*11.38 / -1*	***CON EDISON*** ***322 GREEN ST STRUCTURE # 11666*** ***BROOKLYN NY***	***GEN MANIFEST***

RCRA ID:	NYP004661781	**Mailing State:**	NY
District Name:	CON EDISON	**Mailing ZIP:**	10003
Contact Name:	CON EDISON	**Mailing ZIP Ext:**	
Business Phone No:	2124603770	**Mailing Country:**	USA
Mailing Street 1:	4 IRVING PL 15TH FL	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	NEW YORK	**Location County:**	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2014: 50 Gallons; 50 Gallons

16	*1 of2*	*NNE*	*0.03 / 138.64*	*11.38 / -1*	***VACANT BUILDING*** ***311 GREEN AVE.***	***NY SPILLS***

BROOKLYN NY

Spill No:	0707140	***UST Trust:***	False
Site ID:	387777	***Spill Date:***	09/27/2007 05:16:00 PM
DER Facility ID:	337254	***Received Date:***	09/27/2007 05:16:00 PM
CID:	406	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	11/19/2007 12:00:00 AM
Water Body:		***Create Date:***	09/28/2007 10:11:00 AM
Class:	C4	***Update Date:***	11/19/2007 12:51:23 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	RMPIPER
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Human Error		
Reported by:	Fire Department		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"While digging in the basement they hit the water main... the tank tipped over and is floating in the water. The tank is a 275gal. unknown how much material is in the water. DEP water is on scene and they are refusing the shut off the water. Crews cannot get to the tank because of the water. No clean up yet. ***Mike Ortiz NYC OEM have responders on route to the scene. ETA within 10-15 min. DEP Water is saying that the independent contractors have to shut off the water. DEP doesn't have the authority.*** ***Shay McAtamney NYC DEP 18:16 Water has been shut off. There's a lot of oil in the building*** pdate dup 0707143 Mary Merced of NYC OEM Duane Rose is field contact 646-879-0786 Reg 2 Rep will call him "

DEC Remark:

"workers working demolition site and broke a main-the force of water lifted the tank 250 gals tipped over and est 125 came out ontro grade and possibly the sewer also-FDNY was oin site and left-nypd and dep on site-DEP hazmat responding-OEM on site-responder to call Mr Rose-NYC Bldg dept enroute **Duplicate spill number 0707143 has been closed***** 10-4-07- DEC Piper sent CSL and PBS NOV for unregistered tank. 11/19/07- DEC Piper reviewed disposal manifests. Based on work to date, this spill is closed. No further action is granted. See e-doc's if warranted."

Material Information

OP Unit ID:	1144979	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2135288	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	KNOCK OUT CONTRACTING
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	STEVEN FINKLE
Contact Phone:	(347) 203-6886
Contact Ext:	
Latitude:	40.687581000
Longitude:	-73.958876000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
16	2 of2	NNE	0.03 / 138.64	11.38 / -1	WATER MAIN BREAK 311 GREEN AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0707143	**UST Trust:**	False
Site ID:	387780	**Spill Date:**	09/27/2007 05:30:00 PM
DER Facility ID:	337257	**Received Date:**	09/27/2007 07:03:00 PM
CID:	75	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	09/28/2007 12:00:00 AM
Water Body:	N/A	**Create Date:**	09/28/2007 10:11:00 AM
Class:	C4	**Update Date:**	09/28/2007 10:45:11 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	True

County: Kings
Contributing Factor: Other
Reported by: Local Agency
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"workers working demolition site and broke a main-the force of water lifted the tank 250 gals tipped over and est 125 came out ontro grade and possibly the sewer also-FDNY was oin site and left-nypd and dep on site-DEP hazmat responding-OEM on site-responder to call Mr Rose-NYC Bldg dept enroute **Already a working spill #0707140 see this spill number for details*****"

DEC Remark:

"Duplicate spill number to #0707140"

Material Information

OP Unit ID:	1144982	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2135291	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	True
Quantity:	125.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0008
Material Name: diesel

Spiller Information

Spiller Name: DWAYNE ROSE
Spiller Company: WATER MAIN BREAK
Spiller Address: 315 GREEN AVENUE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: DWAYNE ROSE
Contact Phone: (646) 879-0786
Contact Ext:
Latitude: 40.687581000
Longitude: -73.958876000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	1 of1	NNW	0.03 / 146.61	12.02 / 0	Crew Levick Co. 267 Green Ave Brooklyn NY	HIST GAS STATIONS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Station: Crew Levick Co.
Fac Name:
County:

---

18 | **1 of1** | **NE** | **0.03 / 169.10** | **11.36 / -1** | **CONSTRUCTION SITE 333 GREEN AVE BROOKLYN NY** | **NY SPILLS**

Spill No:	0611233	**UST Trust:**	False
Site ID:	375845	**Spill Date:**	01/09/2007 11:01:00 AM
DER Facility ID:	325450	**Received Date:**	01/09/2007 11:01:00 AM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	04/24/2007 12:00:00 AM
Water Body:		**Create Date:**	01/09/2007 11:24:00 AM
Class:	C4	**Update Date:**	04/24/2007 04:02:09 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SFRAHMAN
REM Phase:	0	**After Hours:**	False

County: Kings
Contributing Factor: Unknown
Reported by: Other
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"FOUND WHILE DIGGING AND VAC TRUCK ENROUTE"

DEC Remark:

"Site is an active construction site. One (maybe more??) tank(s) were found. A vac truck was called to remove the contents. Unknown if there is a spill at the site. Unknown if a PBS tank removal letter was submitted to DEC 01/30/07 Rahman- A closure report will be sent to DEC Sharif Rahman when the lab result is available.Sharif spoke with Mr. Bernie @(718)731-7011. 04/05/07 Bernie to send the report to DEC. 04/12/07 Bernie called me this afternoon and said he would send me the analytical today, report to follow later. 04/24/07 Waste disposal manifest, site plan, soil analytical data were provided.VOC/SVOC are within the TAGM limit.One 550 gallon tank was removed from the site.Report in edocs.spill closed.(SR)"

Material Information

OP Unit ID:	1133463	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2123271	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		

Material Code: 0002A
Material Name: #4 fuel oil

Spiller Information

Spiller Name: DONALD- SITE MANAGER
Spiller Company: CONSTRUCTION SITE
Spiller Address: 333 GREEN AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: DONALD- SITE MANAGER

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Phone: (302) 682-3615
Contact Ext:
Latitude: 40.687689000
Longitude: -73.957936000

19	1 of6	WSW	0.03 / 177.40	12.67 / 1	CON EDISON - MANHOLE 752 S/S HURON ST 25` E/O MCGUINESS BLVD BROOKLYN NY 11205	RCRA LQG

EPA Handler ID: NYP004151916
Gen Status Universe: Large Quantity Generator
Contact Name: FRANKLIN MURRAY
Contact Address:
Contact Phone No and Ext: 212-460-2808
Contact Email: MURRAYFR@CONED.COM
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20080221
Location Latitude: 40.732525
Location Longitude: -73.960666
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20080221
Handler Name: CON EDISON - MANHOLE 752
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: B007
Waste Code Description: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Hazardous Waste Code: D008
Waste Code Description: LEAD

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	4 IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20070720	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	4 IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20070720	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003

---

19 **2 of6** **WSW** **0.03 / 177.40** **12.67 / 1** **Spill Number 0004605 MCGUINESS AND HURON AV BROOKLYN NY** ***NY SPILLS***

Spill No:	0004605	**UST Trust:**	False
Site ID:	232184	**Spill Date:**	07/17/2000 01:00:00 PM
DER Facility ID:	191345	**Received Date:**	07/17/2000 02:41:00 PM
CID:	270	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	12/28/2000 12:00:00 AM
Water Body:		**Create Date:**	07/17/2000 12:00:00 AM
Class:	D4	**Update Date:**	12/28/2000 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	MCTIBBE
REM Phase:	0	**After Hours:**	False

County: Kings
Contributing Factor: Traffic Accident
Reported by: Affected Persons
Referred to:
Source: Commercial Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"traffic accident causd spill clean up crew on the way"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 12/28/00 - SPILL FROM RUPTURED BUS HOSE. ALL WENT INTO SEWER. POSSIBLE DEP VIOLATION."

Material Information

OP Unit ID:	825757	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	549342	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	True
Quantity:	4.00	**Med Surf:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Units:	G	**Med Subway:**	False
Recovered:	1.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0043A		
Material Name:	antifreeze		

Spiller Information

Spiller Name:	CALLER
Spiller Company:	NYC TRANSIT
Spiller Address:	370 JAY ST
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	-
Spiller Country:	001
Contact Name:	CALLER
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

---

19 | ***3 of6*** | ***WSW*** | ***0.03 / 177.40*** | ***12.67 / 1*** | ***CON ED MANHOLE 4313 MC GUINNESS & HURON ST BROOKLYN NY*** | ***NY SPILLS***

Spill No:	9307736	**UST Trust:**	False
Site ID:	160772	**Spill Date:**	09/24/1993 03:30:00 PM
DER Facility ID:	135742	**Received Date:**	09/24/1993 05:20:00 PM
CID:		**CAC Date:**	05/26/1995 12:00:00 AM
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	05/26/1995 12:00:00 AM
Water Body:		**Create Date:**	09/29/1993 12:00:00 AM
Class:	C3	**Update Date:**	09/25/1997 12:00:00 AM
Meets Std:	True	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	CAENGELH
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	DEC		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"NOTICED WHILE DRIVING BY PUMPING DIELECTRIC FLUID FROM VAULT INTO TANKER TRUCK."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT "

Material Information

OP Unit ID:	986248	**Med Ind Air:**	False
OU:	01	**Med GW:**	True
Material ID:	393985	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	50.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0017A		

Material Name: PCB oil

Spill Data

Material Name: PCB oil
Material Family: Petroleum
Quantity: 50
Units: Gallons
Recovered: 0

---

19 | **4 of6** | **WSW** | **0.03 / 177.40** | **12.67 / 1** | **CON EDISON - TRANSFORMER MANHOLE 752**
MCGUINESS BLVD & HURON ST
BROOKLYN NY 11222 | **NY MANIFEST**

RCRA ID: NYP004979353
District Name: CON EDISON - TRANSFORMER MANHOLE 752
Business Phone No:
Contact Name: CON EDISON
Location ZIP Ext:
Location County: KINGS
Location Country: USA

Mailing Street 1: 4 IRVING PL 15TH FL NE
Mailing Street 2:
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA

---

19 | **5 of6** | **WSW** | **0.03 / 177.40** | **12.67 / 1** | **CON EDISON**
SEC HURON & MCGUINNESS MH 4313
BROOKLYN NY 11222 | **GEN MANIFEST**

RCRA ID: NYP004273389
District Name: CON EDISON
Contact Name: TOM TEELING
Business Phone No: 2124603770
Mailing Street 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Street 2:
Mailing City: NEW YORK

Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2013: 800 Gallons

---

19 | **6 of6** | **WSW** | **0.03 / 177.40** | **12.67 / 1** | **consoliated edison**
S/S HURON ST 25` E/O MCGUINESS BLVD
BROOKLYN NY 11205 | **GEN MANIFEST**

RCRA ID: NYP004151916
District Name: consoliated edison
Contact Name: franklyn murray
Business Phone No: 2124602808
Mailing Street 1: 4 irving pl rm 828
Mailing Street 2:
Mailing City: new york

Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

B007: (Wastes containing polychlorinated biphenyls (PCBs)) Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Waste Amounts By Year:

2007: 600 Kilograms

Manifest Information

Waste Code(s):

B007: (Wastes containing polychlorinated biphenyls (PCBs)) Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.
D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 6710 Kilograms

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
20	1 of1	ENE	0.03 / 182.41	11.30 / -1	262 Green 262-276 Green Street and 263 Huron Street Brooklyn NY 11211	BROWNFIELDS

Site Code:	559019
HW Code:	C224265
Program:	BCP
Site Class:	N
Site Name:	262 Green
Site Address:	262-276 Green Street and 263 Huron Street
City:	Brooklyn
Zip:	11211
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.733930556
Longitude:	-73.950291667
SWIS:	2401
Acres:	0.570
Record Added:	2017-09-11 11:37:00
Record Update:	2022-07-21 14:50:00
Updated by:	AMSERVIS
Site Code (Web):	C224265
Program Type (Web):	BCP
Site Name (Web):	262 Green
Site Class (Web):	N
Address1 (Web):	262-276 Green Street and 263 Huron Street
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11211
County (Web):	Kings
Longitude (Web):	-73.950291667
Latitude (Web):	40.733930556
Site Code (GIS):	C224265
Site Name (GIS):	262 Green
Program (GIS):	BCP
Site Class (GIS):	N
Address1 (GIS):	262-276 Green Street and 263 Huron Street
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11211
County (GIS):	Kings
Site Class Desc:	No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Site Class Desc (Web): No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH: The site is completely fenced, which restricts public access. However, people who enter the site could come in contact with contaminants in the soil by walking on the site, digging or otherwise disturbing the soil. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the soil vapor (air spaces within the soil) may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because there are no on-site buildings, inhalation of site contaminants in indoor air due to soil vapor intrusion does not currently represent a concern. However, the potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site buildings. Sampling indicates soil vapor intrusion is not a concern for off-site buildings.

Description:

Location: The 262 Green Site is a 0.57-acre site located in an urban area. Site Features: The site is relatively flat and contains no buildings or structures. All previous structures were demolished. The site is unpaved and is surrounded by construction fencing. Current Zoning and Land Use: The site is currently inactive, and its zoning is M3-1. M3 districts are designated for areas with heavy industries that generate noise, traffic or pollutants. Surrounding land use includes the NYC Department of Public works water treatment plant to the east, and commercial properties to the north, south and west. The site is no longer in the BCP program. Past Use of the Site: Since initial development in the early 20th Century, the site has been used for several commercial and industrial purposes. Prior uses include bed manufacturing, jewelry manufacturing, and a metal products company. The property was most recently used by a steel fabrication and painting facility that occupied the Site for 40 years, until around 2014. Site Geology and Hydrogeology: The elevation of the property is approximately 11 feet above the National Geodetic Vertical Datum (NGVD). Subsurface soils at the Site consist of historic fill materials to a depth of approximately 2 to 5 feet below the surface followed by native silty-sand. Groundwater occurs beneath the Site at a depth of approximately 9-11 feet below grade. Groundwater flows east toward the Newtown Creek.

Assessment:

Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Based upon investigations conducted to date, the primary contaminants of concern include tert-butylbenzene and lead. The site is no longer in the BCP program due to voluntary withdrawal by the applicant. The site is not considered to be a significant threat. Soil - Tert-butylbenzene was found in the deep soil at 8.6 parts-per-million (ppm), exceeding the unrestricted use soil cleanup objective (USCO) of 5.9 ppm. Lead was detected in the soil at a maximum concentration of 4,120 ppm, exceeding its USCO of 63 ppm. One sample failed a Toxicity Characteristic Leaching Procedure (TCLP) test for lead, indicating some of the on-site soil would be classified as hazardous waste. Data does not indicate any off-site impacts in soil related to this site. Groundwater - Tert-butylbenzene was found in the groundwater at a maximum concentration of 13 parts-per-billion (ppb), exceeding the groundwater standard of 5 ppb. The maximum lead concentration was 32 ppb, exceeding the groundwater standard of 25 ppb. Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor - Trichloroethene (TCE) was detected in soil vapor at a maximum concentration of 40.2 micrograms per cubic meter. As TCE was not found in the soil or groundwater, the TCE in the soil vapor is not believed to be site-related. Data does not indicate any off-site impacts in soil vapor related to this site.

Owner Information

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Brooklyn Public Library - Greenpoint Branch
Owner Street: 107 Norman Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Yoel Schwimmer
Owner Company: 270 Green LLC
Owner Street: 199 lee avenue no. 693
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11211
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Yoel Shwimmer
Owner Company: 270 Green Holdings LLC
Owner Street: 199 lee avenue no. 693
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11211
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Brooklyn Community Board 1
Owner Street: 435 Graham Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11211
Country: United States of America

Owner Op: 01
Sub Type: P03
Owner Name: Yoel Goldman
Owner Company: 270 Green Holdings LLC
Owner Street: 199 Lee Avenue
Owner Street 2: #693
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11211
Country: United States of America

Owner Op: 01
Sub Type: P03
Owner Name: Robert Guttman
Owner Company: 270 Green LLC
Owner Street: 209 Harrison Ave
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11206
Country: United States of America

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Projects Information

Project Code:	04
Project Desc:	Remedial Design
Project Refer Name:	
End Date:	2019-07-26 00:00:00
End Status:	ACT
Operable Unit ID:	1307019
Operable Unit:	01
Operable Unit Desc:	Remedial Program
Code Name:	Remedial Design

Project Code:	02
Project Desc:	Remedial Investigation
Project Refer Name:	Remedial Investigation
End Date:	2019-07-26 00:00:00
End Status:	ACT
Operable Unit ID:	1307019
Operable Unit:	01
Operable Unit Desc:	Remedial Program
Code Name:	Remedial Investigation

Environmental Remediation

Operable Unit:	01
Contaminants:	lead, tert-butylbenzene, trichloroethene (TCE)

Operable Unit:	00
Contaminants:	lead, tert-butylbenzene, trichloroethene (TCE)

21	*1 of5*	*NNE*	*0.04 / 206.80*	*11.49 / -1*	***CINER CHEMICAL & REFINING CO INC*** ***247 GREEN ST*** ***BROOKLYN NY 11222***	***RCRA NON GEN***

EPA Handler ID:	NYD046821070
Gen Status Universe:	No Report
Contact Name:	ELI CINER
Contact Address:	247 , GREEN ST , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:	718-383-8900
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	
Receive Date:	20070101
Location Latitude:	40.734038
Location Longitude:	-73.951813
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date:	19891214
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Violation Short Description:	
Return to Compliance Date:	

Evaluation Agency: State

Evaluation Start Date: 19851220
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19830801
Handler Name: CINER CHEMICAL & REFINING CO INC
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060101
Handler Name: CINER CHEMICAL & REFINING CO INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: CINER CHEMICAL & REFINING CO INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	OWNERNAME	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	OWNERNAME	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	OWNERNAME	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	99999

Historical Handler Details

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	CINER CHEMICAL & REFINING CO INC

Receive Dt:	19830801
Generator Code Description:	Not a Generator, Verified
Handler Name:	CINER CHEMICAL & REFINING CO INC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
21	2 of5	NNE	0.04 / 206.80	11.49 / -1	247-251 GREEN STREET 247-251 GREEN STREET BROOKLYN NY 11222	UST

Site ID:	29370	**Expiry:**	N/A
Site Status:	Unregulated/Closed	**County:**	Kings
Program No:	2-607518	**UTM X:**	588565.04658
Program Type Code:	PBS	**UTM Y:**	4509765.18041
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Other		

Tank Information

Prog No:	2-607518	**UDC Ind:**	1
Tank ID:	63132	**Red Tag Start Date:**	
Tank No:	001	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:		**Next Test:**	
Close Date:	03/21/2002	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	4000	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		

Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: I00
Code Name: None
Type: Overfill

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J00
Code Name: None
Type: Dispenser

Affiliation Information

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: ANDRE BARNOWSKI
Contact Title:
Contact Name: ANDRE BARNOWSKI
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 349-2552

Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: ANDRE BARNOWSKI
Contact Title:
Contact Name:
Address1: 207 DUPONT STREET
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 349-2552
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: 207 DUPONT STREET
Contact Title:
Contact Name: ANDRE BARNOWSKI
Address1:
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 349-2552
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: 247-251 GREEN STREET
Contact Title:
Contact Name: ANDRE BARNOWSKI
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 349-2552
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
21	3 of5	NNE	0.04 / 206.80	11.49 / -1	FORMER WASTE TRANSFER STATION 247-251 GREEN ST BROOKLYN NY	LST

Spill No: 0112015
Site ID: 278817
DER Facility ID: 226388
CID: 257
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Failure
Water Body:

REM Phase: 0
UST Trust: True
Spill Date: 03/21/2002 12:00:00 PM
Rcvd Date: 03/21/2002 12:12:00 PM
CAC Date:
Insp Date:
Close Date: 01/27/2005 12:00:00 AM
Create Date: 03/21/2002 12:00:00 AM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Class:	B3	**Update Date:**	01/27/2005 04:15:32 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	JBVOUGHT
County:	Kings	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"during a tank removal caller found contaminated soil"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 7/17/2003-Vought-Initial copy of report sent on 5/8/2003. Second copy sent on 6/13/2003. Underground Storage Tank Closure Report-March 2002-RND Services (Sharima Ryan-845-348-6355). One (4000-gallon) diesel/fuel oil UST removed from 249 Green Street and one (2000-gallon) diesel UST removed from 251 Green Street. Both properties were once occupied by a demolition, carting and transfer station. Groundwater at a depth of 8' below grade and flows to the north. Site underlain by fill material (coal ash, wood, cinders). Excavation of impacted soil around 4000gal UST was performed to 8' below grade. Excavation on impacted soil around 2000-gal UST was also performed to a depth of 8' (disposal manifests for both tanks provided). Excavation around 4000-gal UST limited on south side due to presence of load bearing wall and excavation around 2000-gal UST limited on south and east walls. Four endpoint soil samples obtained from 4000-gal UST excavation (no bottom sample was obtained due to groundwater in excavation). Two endpoint samples obtained from 2000-gal UST excavation (no bottom sample was obtained due to groundwater in excavation). No east or south samples collected due foundation walls and no soil remaining. RND believes that groundwater has been impacted . A total of 178.25 tons of impacted soil were removed from the site. Soil analyticals show up to 6400ppb chrysene (PE21), 7600 benzo(a)anthracene(PE21) and 27000ppb benzo(a)pyrene(PE3) and 98000ppb phenanthrene(PE3). 7/17/2003-Vought-NYSDEC requires 1)groundwater sample. Vought spoke with Sharima Ryan and she requested email of requirement. Vought sent email on 7/17. 1/26/05-Vought-Spoke to Sharima Ryan and she requested NFA and analyticals were already sent. 1/27/05-Vought-New file review by Vought: Letter from RND(Ryan) to DEC Vought-5/20/04. Enclosed please find the groundwater results for the above referenced property . Two groundwater samples were collected from wells installed within the former tank excavations. Samples were analyzed for PAHs. Report is requesting closure. Groundwater shows no TOGs Groundwater exceedences. Spill closed by Vought."

Material Information

OP Unit ID:	848960	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	526029	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	SHARIMA RYAN
Spiller Company:	
Spiller Address:	247-251 GREEN ST
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	SHARIMA RYAN
Contact Phone:	(845) 348-6355
Contact Ext:	
Latitude:	40.734076200
Longitude:	-73.951827490

21	4 of5	NNE	0.04 / 206.80	11.49 / -1	CINER CHEMICAL REFINING CO INC 247 GREEN ST	REC MANIFEST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					BROOKLYN NY 11222	

RCRA ID: NYD046821070
District Name: CINER CHEMICAL REFINING CO INC
Contact Name: ELI OR JONATHA CINER
Business Phone No: 7183838900
Mailing Street 1: 247 GREEN ST
Mailing Street 2:
Mailing City: BROOKLYN
Mailing State: NY
Mailing Zip: 11222
Mailing Zip Extension: 1208
Mailing Country: USA
Location Zip Ext: 1208
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Received By Year:

1984: 10 Gallons

21	5 of5	NNE	0.04 / 206.80	11.49 / -1	MICHAEL FERONE (BRICK) CO. 247 GREENE ST Brooklyn NY 11222	SWF/LF

Activity Number: [24W65]
Facility Name (Act):
Location Addr (Act):
Location Addr2 (Act):
City (Act):
State (Act):
Zip Code (Act):
County (Act):
East Coord (Act):
North Coord (Act):
Facility Name:
Location Addr:
Location Addr2:
City:
State:
Zip Code:
County:
East Coord:
North Coord:
Data Source: SWMF - Inactive Facility Lists

Facility Name (InAct): MICHAEL FERONE (BRICK) CO.
Location Addr (InAct): 247 GREENE ST
Loc Addr2(InAct):
City (InAct): Brooklyn
State (InAct): NY
Zip Code (InAct): 11222
County (InAct): Kings
East Coord (InAct): 588505
North Coord (InAct): 4509775

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:
Activity Desc: C&D processing - registration
Regulatory Status:
Active: No
Dt of Last Inspection:
Expiration Dt:
Owner Type:
Owner Name:
Owner Address:
Owner Address2:
Owner City:
Owner State:
Owner Zip:
Owner Phone:
Owner Email:
Waste Types:

Authorization No: 2-6101-00003
Authrzation Issue Dt:
Operator Type:
Operator Name:
Phone No: 7183830843
Region: 2
Contact Name: MICHAEL FERONE; OWNER
Contact Address:
Contact Address2:
Contact City:
Contact State:
Contact Zip:
Contact Phone:
Contact Email:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
22	1 of2	ESE	0.04 / 208.00	11.70 / 0	FORTUNE METALS INC. 239 INDIA STREET BROOKLYN NY 11222	CERCLIS

Site ID:	0206493	**RNPL Status Code:**	N
Site EPA ID:	NYR000170555	**NPL Status:**	Not on the NPL
Site Street Address 2:		**RFED Facility Code:**	N
Site County Name:	KINGS	**RFED Facility Desc:**	Not a Federal Facility
Site FIPS Code:	36047	**USGS Hydro Unit No.:**	
Region Code:	02	**Site Cong. Dist. Code:**	
Site SMSA No.:		**ROT Desc:**	
Site Prim. Latitude:	+40.732673	**FR NPL Update No.:**	
Site Prim. Longitude:	-073.94966	**RFRA Code:**	
Lat Long Source:			

RNON NPL Status Desc: Removal Only Site (No Site Assessment Work Needed)

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	
Act Code ID:		**Act Start Date:**	
RAT Code:		**Act Complete Date:**	
RAT Short Name:		**AGT Order No.:**	0
RAT Name:		**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:		**SH Seq:**	
RAT Level:		**SH Start Date:**	
RAT DEF OU:		**SH Complete Date:**	
RFBS Code:		**SH Lead:**	
SPA Code:			
RAT Def:			

Site Desc: No description available
.

Site Alias: No alias data available

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	PRP Rsp Fed
Act Code ID:	001	**Act Start Date:**	8/12/2011 00:00:00
RAT Code:	PJ	**Act Complete Date:**	8/19/2011 00:00:00
RAT Short Name:	RP EM REM	**AGT Order No.:**	95
RAT Name:	POTENTIALLY RESPONSIBLE PARTY EMERGENCY REMOVAL	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:		**SH Complete Date:**	
RFBS Code:		**SH Lead:**	
SPA Code:	13		

RAT Def: The PRP or their contractors have begun construction work on-site in response to an emergency incident, and EPA provides on-site technical oversight and/or is part of an incident command system/unified command. The date of construction is reported in WasteLAN as the PRP Emergency Removal actual start date.

Site Desc:

Site Alias:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
22	2 of2	ESE	0.04 / 208.00	11.70 / 0	262 HURON ST 262 HURON ST BROOKLYN NY	NY SPILLS

Spill No:	9704312	**UST Trust:**	False
Site ID:	321523	**Spill Date:**	07/11/1997 01:00:00 AM
DER Facility ID:	259008	**Received Date:**	07/11/1997 10:07:00 AM
CID:	369	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	07/21/1998 12:00:00 AM
Water Body:		**Create Date:**	07/11/1997 12:00:00 AM
Class:	B3	**Update Date:**	07/21/1998 12:00:00 AM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	O'DOWD
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Citizen		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"caller was drilling and testing area and came across unk petro in the groundwater-said he was drilling below the watertable because it is high in the area-unsure why he was drilling said he was checking for cleanliness"

DEC Remark:

""

Material Information

OP Unit ID:	1047535	**Med Ind Air:**	False
OU:	01	**Med GW:**	True
Material ID:	561027	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	PETER BOZEWICZ
Contact Phone:	
Contact Ext:	
Latitude:	40.733370920
Longitude:	-73.950547730

23	***1 of8***	***ESE***	***0.04 / 208.03***	***11.70 / 0***	***FORTUNE METAL INC 239 INDIA ST BROOKLYN NY 11222***	***RCRA VSQG***

EPA Handler ID:	NYR000170555
Gen Status Universe:	VSG
Contact Name:	DANNY LAU
Contact Address:	239 , INDIA ST , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:	718-389-3000
Contact Email:	DANNY@FORTUNEGROUP.NET
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20091116
Location Latitude:	40.73222

Location Longitude: -73.955537
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Act W.O. Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20091116
Handler Name: FORTUNE METAL INC
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: NORMAN NG
Date Became Current: 19870822
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1:
Street 2:
City:
State:
Country:
Zip Code:

Owner/Operator Ind: Current Owner
Type: Private
Name: NORMAN NG
Date Became Current: 19870822
Street No: 8
Street 1: OSHAUGHNESSY LANE
Street 2:
City: CLOSTER

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Date Ended Current: | **State:** NJ
Phone: | **Country:** US
Source Type: Notification | **Zip Code:** 07624-3214

23	2 of8	ESE	0.04 / 208.03	11.70 / 0	CON EDISON - SERVICE BOX 7508 256 HURON ST BROOKLYN NY 11222	RCRA LQG

EPA Handler ID: NYP005050042
Gen Status Universe: Large Quantity Generator
Contact Name: ALYSSA SOTTO
Contact Address: 4 , IRVING PLACE, 15TH FL NE , , NEW YORK , NY, 10003 , US
Contact Phone No and Ext: 212-460-2757
Contact Email: SOTTOA@CONED.COM
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20180410
Location Latitude: 40.732932
Location Longitude: -73.955589
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20180410
Handler Name: CON EDISON - SERVICE BOX 7508
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	4
Type:	Private	***Street 1:***	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	***Street 2:***	
Dt Became Current:	20170419	***City:***	NEW YORK
Dt Ended Current:		***State:***	NY
Phone:	212-460-2757	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	10003

Owner/Operator Ind:	Current Operator	***Street No:***	4
Type:	Private	***Street 1:***	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	***Street 2:***	
Dt Became Current:	20170419	***City:***	NEW YORK
Dt Ended Current:		***State:***	NY
Phone:	212-460-2757	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	10003

---

23 ***3 of8*** ***ESE*** ***0.04 / 208.03*** ***11.70 / 0*** ***CON EDISON - SERVICE BOX 7508 256 HURON ST BROOKLYN NY 11222*** ***NY MANIFEST***

RCRA ID:	NYP005050042	***Mailing Street 1:***	4 IRVING PL
District Name:	CON EDISON - SERVICE BOX 7508	***Mailing Street 2:***	
Business Phone No:		***Mailing City:***	NEW YORK
Contact Name:	CON EDISON	***Mailing State:***	NY
Location ZIP Ext:		***Mailing ZIP:***	10003
Location County:	KINGS	***Mailing ZIP Ext:***	
Location Country:	USA	***Mailing Country:***	USA

---

23 ***4 of8*** ***ESE*** ***0.04 / 208.03*** ***11.70 / 0*** ***FORTUNE METAL INC 239 INDIA STREET BROOKLYN NY 11222*** ***GEN MANIFEST***

RCRA ID:	NYR000170555	***Mailing State:***	NY
District Name:	FORTUNE METAL INC	***Mailing ZIP:***	11222
Contact Name:	FORTUNE METAL INC	***Mailing ZIP Ext:***	
Business Phone No:		***Mailing Country:***	USA
Mailing Street 1:	239 INDIA ST	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	BROOKLYN	***Location County:***	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2014: 650 Gallons

---

23 ***5 of8*** ***ESE*** ***0.04 / 208.03*** ***11.70 / 0*** ***Fortune Metal 239 India Street Brooklyn NY 11222*** ***SWF/LF***

Activity Number:	[24M00]	***Facility Name (InAct):***	R&Z Metal
Facility Name (Act):	Fortune Metal	***Location Addr (InAct):***	247 Huron Street
Location Addr (Act):	239 India Street	***Loc Addr2(InAct):***	
Location Addr2 (Act):		***City (InAct):***	Brooklyn

City (Act):	Brooklyn	***State (InAct):***	NY
State (Act):	NY	***Zip Code (InAct):***	11211;11214;11215;11221;11222;11231
Zip Code (Act):	11222	***County (InAct):***	Kings
County (Act):	Kings	***East Coord (InAct):***	584652;585300;585806;588568;590321;590770
East Coord (Act):	588653;588875;589120	***North Coord (InAct):***	4492844;4502974;4503057;4507777;4508030;4509702
North Coord (Act):	4509421;4509644;4509887		
Facility Name:	Fortune Metal		
Location Addr:	239 India Street		
Location Addr2:			
City:	Brooklyn		
State:	NY		
Zip Code:	11222		
County:	Kings		
East Coord:	588653;588875;589120		
North Coord:	4509421;4509644;4509887		
Data Source:	SWMF - Active Facility Lists; SWMF - Inactive Facility Lists; SWMF - Active Solid Waste Management Facilities as of 08-17-2023		

SWMF - Active Facility Lists Details(Act)

Accuracy Code:		***Authorization No:***	
Activity Desc:	RHRF - exempt (non-VDF)	***Authrzation Issue Dt:***	
Regulatory Status:	Exempt	***Operator Type:***	
Active:	Yes	***Operator Name:***	
Dt of Last Inspection:		***Phone No:***	7183893200
Expiration Dt:		***Region:***	2
Owner Type:	Private	***Contact Name:***	
Owner Name:	Alan Friedman	***Contact Address:***	
Owner Address:	203 Vineland Avenue	***Contact Address2:***	
Owner Address2:		***Contact City:***	
Owner City:	Staten Island	***Contact State:***	
Owner State:	NY	***Contact Zip:***	
Owner Zip:	10312	***Contact Phone:***	
Owner Phone:		***Contact Email:***	
Owner Email:	ibyscrap@aol.com		
Waste Types:			

SWMF - Active Facility Lists Details(Act)

Accuracy Code:		***Authorization No:***	
Activity Desc:	RHRF - exempt (non-VDF)	***Authrzation Issue Dt:***	
Regulatory Status:	Exempt	***Operator Type:***	
Active:	Yes	***Operator Name:***	Allocco Recycling Ltd.
Dt of Last Inspection:	2/14/2019	***Phone No:***	7183493094
Expiration Dt:		***Region:***	2
Owner Type:	Private	***Contact Name:***	Michael Allocco Jr
Owner Name:	Michael Allocco	***Contact Address:***	
Owner Address:	540 Kingsland Avenue	***Contact Address2:***	
Owner Address2:		***Contact City:***	
Owner City:	Brooklyn	***Contact State:***	
Owner State:	NY	***Contact Zip:***	
Owner Zip:	11222	***Contact Phone:***	7183493094
Owner Phone:	7183493094	***Contact Email:***	mike@alloccorecycling.com
Owner Email:			
Waste Types:			

SWMF - Active Facility Lists Details(Act)

Accuracy Code:		***Authorization No:***	
Activity Desc:	RHRF - exempt (non-VDF)	***Authrzation Issue Dt:***	
Regulatory Status:	None	***Operator Type:***	
Active:	Yes	***Operator Name:***	
Dt of Last Inspection:		***Phone No:***	7183893000
Expiration Dt:		***Region:***	2

Owner Type:	Private	**Contact Name:**	
Owner Name:	The Fortune Group	**Contact Address:**	
Owner Address:	239 India Street	**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:	Brooklyn	**Contact State:**	
Owner State:	NY	**Contact Zip:**	
Owner Zip:	11222	**Contact Phone:**	
Owner Phone:	7183893000	**Contact Email:**	
Owner Email:			
Waste Types:			

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		**Authorization No:**	
Activity Desc:	RHRF - exempt (non-VDF)	**Authrzation Issue Dt:**	
Regulatory Status:		**Operator Type:**	
Active:	No	**Operator Name:**	Cropsey Scrap Iron & Metal Corp.
Dt of Last Inspection:		**Phone No:**	5167912300
Expiration Dt:		**Region:**	2
Owner Type:		**Contact Name:**	Robert Lopinto
Owner Name:	Cropsey Scrap Iron & Metal Corp.	**Contact Address:**	same
Owner Address:	2994 Cropsey Avenue	**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:	Brooklyn	**Contact State:**	
Owner State:	NY	**Contact Zip:**	
Owner Zip:	11214	**Contact Phone:**	5167912300
Owner Phone:		**Contact Email:**	shapiroengineers@att.net
Owner Email:			
Waste Types:			

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		**Authorization No:**	
Activity Desc:	RHRF - exempt (non-VDF)	**Authrzation Issue Dt:**	
Regulatory Status:		**Operator Type:**	
Active:	No	**Operator Name:**	
Dt of Last Inspection:		**Phone No:**	7184971950
Expiration Dt:		**Region:**	2
Owner Type:		**Contact Name:**	Wayne KIng
Owner Name:	Charles J King Inc	**Contact Address:**	
Owner Address:	1301 Grand Street	**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:	Brooklyn	**Contact State:**	
Owner State:	NY	**Contact Zip:**	
Owner Zip:	11211	**Contact Phone:**	7184971950
Owner Phone:	7184971950	**Contact Email:**	wdking@att;net
Owner Email:	wdking@att.net		
Waste Types:			

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		**Authorization No:**	
Activity Desc:	RHRF - exempt (non-VDF)	**Authrzation Issue Dt:**	
Regulatory Status:		**Operator Type:**	
Active:	No	**Operator Name:**	
Dt of Last Inspection:		**Phone No:**	7182223133
Expiration Dt:		**Region:**	2
Owner Type:		**Contact Name:**	Anthony DeConcillis
Owner Name:	Sixth Street Iron and Metal	**Contact Address:**	same
Owner Address:	163 6th Street	**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:	Brooklyn	**Contact State:**	
Owner State:	NY	**Contact Zip:**	
Owner Zip:	11215	**Contact Phone:**	7182223133
Owner Phone:		**Contact Email:**	anthony@dorannresources.com

Owner Email:
Waste Types:

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Regulatory Status:
Active: No
Dt of Last Inspection:
Expiration Dt:
Owner Type:
Owner Name: Benson Metal Corp.
Owner Address: 543 Smith Street
Owner Address2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11231
Owner Phone: 7187227754
Owner Email: tpetrosino@cropseymetals.com
Waste Types:

Authorization No:
Authrzation Issue Dt:
Operator Type:
Operator Name: Benson Metal Corp.
Phone No: 7187227754
Region: 2
Contact Name: Robert Lopinto
Contact Address:
Contact Address2:
Contact City:
Contact State:
Contact Zip:
Contact Phone: 5167912300
Contact Email: sharpiroengineers@att.net

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Regulatory Status:
Active: No
Dt of Last Inspection:
Expiration Dt:
Owner Type:
Owner Name: F & P Resources LLC
Owner Address: 340 Maspeth Avenue
Owner Address2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11221
Owner Phone: 7183664017
Owner Email:
Waste Types:

Authorization No:
Authrzation Issue Dt:
Operator Type:
Operator Name:
Phone No: 7183664017
Region: 2
Contact Name: Timothy Fulton
Contact Address: 340 Maspeth Avenue
Contact Address2:
Contact City: Brooklyn
Contact State: NY
Contact Zip: 11221
Contact Phone: 7183664017
Contact Email: barbara@tntscrap.com

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Regulatory Status: None
Active: No
Dt of Last Inspection:
Expiration Dt:
Owner Type: Private
Owner Name: R&Z Metal Recycling Corp
Owner Address: 247 Huron Street
Owner Address2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Owner Phone: 7183838820
Owner Email: RZMetal@aol.com
Waste Types:

Authorization No:
Authrzation Issue Dt:
Operator Type:
Operator Name:
Phone No: 7183838820
Region: 2
Contact Name: Joel Lehrman
Contact Address:
Contact Address2:
Contact City:
Contact State:
Contact Zip:
Contact Phone: 7183838820
Contact Email: RZMetal@aol.com

Active Solid Waste Management Facilities Details as of 08-17-2023

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)

Authorization No:
Authrzation Issue Dt:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Active: Yes
Expiration Dt:
Geo Reference: 239 India Street
Brooklyn, NY 11222
(40.732846582, -73.950204269)
Region: 2
Waste Types:

Owner Type: Private
Owner Name: The Fortune Group
Phone No: 7183893000

Active Solid Waste Management Facilities Details as of 08-17-2023

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Active: Yes
Expiration Dt:
Geo Reference: 540 Kingsland Avenue
Brooklyn, NY 11222
(40.735029397, -73.944583868)
Region: 2
Waste Types:

Authorization No:
Authrzation Issue Dt:
Owner Type: Private
Owner Name: Michael Allocco
Phone No: 7183493094

Active Solid Waste Management Facilities Details as of 08-17-2023

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Active: Yes
Expiration Dt:
Geo Reference: 304 Greenpoint Avenue
Brooklyn, NY 11222
(40.730872811, -73.947550894)
Region: 2
Waste Types:

Authorization No:
Authrzation Issue Dt:
Owner Type: Private
Owner Name: Alan Friedman
Phone No: 7183893200

23	6 of8	ESE	0.04 / 208.03	11.70 / 0	Fortune Metal 239 India Street Brooklyn NY 11222	SWF/LF

Activity Number: [24V30002]
Facility Name (Act):
Location Addr (Act):
Location Addr2 (Act):
City (Act):
State (Act):
Zip Code (Act):
County (Act):
East Coord (Act):
North Coord (Act):
Facility Name:
Location Addr:
Location Addr2:
City:
State:
Zip Code:
County:
East Coord:
North Coord:
Data Source: SWMF - Inactive Facility Lists

Facility Name (InAct): Fortune Metal
Location Addr (InAct): 239 India Street
Loc Addr2(InAct):
City (InAct): Brooklyn
State (InAct): NY
Zip Code (InAct): 11222
County (InAct): Kings
East Coord (InAct): 588653
North Coord (InAct): 4509644

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code: 4.2 - Utilization of GIS and existing spatial data
Activity Desc: Scrap metal processor - registration
Regulatory Status: Application
Active: No
Dt of Last Inspection:
Expiration Dt:

Authorization No:
Authrzation Issue Dt:
Operator Type:
Operator Name:
Phone No: 7183893000
Region: 2

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Type:	Private	**Contact Name:**	
Owner Name:	The Fortune Group	**Contact Address:**	
Owner Address:	239 India Street	**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:	Brooklyn	**Contact State:**	
Owner State:	NY	**Contact Zip:**	
Owner Zip:	11222	**Contact Phone:**	
Owner Phone:	7183893000	**Contact Email:**	
Owner Email:			
Waste Types:			

23	7 of8	ESE	0.04 / 208.03	11.70 / 0	**Fortune Metal** **239 India Street** **Brooklyn NY 11222**	RECYCLING

East Coordinate:	588653	**County:**	Kings
North Coordinate:	4509644	**Location Address2:**	

Details

Activity No:	[24M00]	**Authorization No:**	
Active:	Yes	**Auth Issue Date:**	
Activity Desc:	RHRF - exempt (non-VDF)	**Expiration DT:**	
Region:	2	**Owner Type:**	Private
Phone No:	7183893000	**Owner Name:**	The Fortune Group
Accuracy Code:			
Waste Types:			
Georeference:	239 India Street Brooklyn, NY 11222 (40.732846582, -73.950204269)		

23	8 of8	ESE	0.04 / 208.03	11.70 / 0	**Fortune Metals Inc.** **239 India Street** **Brooklyn NY**	OSC RESPONSE

Site ID:	7096	**Completed:**	8/19/2011
Last Po Rep:	8/19/2011	**NPL:**	Non NPL
No :	4	**Action Memo:**	
Site No:		**Contract No:**	
NRC No:		**RCRIS ID:**	
Date Created:	7/15/2011 18:51	**FPN No:**	
Site Category:	FieldActivity	**No Wells:**	
Primary Site Type:		**Is Initial:**	FALSE
Response Type:	PRP Oversight	**Is Final:**	TRUE
Response Authority:	CERCLA	**Region:**	Region II
Response Lead:	EPA	**Zip:**	11222
Incident Category:	Removal Action	**Latitude:**	40.7326731
Start Date:	8/12/2011	**Longitude:**	-73.9496641
CERCLIS ID:			
Oil Pollu Account No:			
Is Well Plugging Site:			
Is Original Action Memo:			
Is 12 Month Exemption:			
Is 2 Million Exemption:			
Is Ceiling Increase:			
Is Change in Response Scope:			
Url:	http://www.epaosc.org/Fortune		

24	1 of2	S	0.04 / 214.73	12.37 / 0	**217 INDIA STREET** **217 INDIA STREET** **BROOKLYN NY**	NY SPILLS

Spill No:	0007775	**UST Trust:**	False
Site ID:	87048	**Spill Date:**	10/02/2000 03:00:00 PM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

DER Facility ID:	79792	**Received Date:**	10/02/2000 03:00:00 PM
CID:	397	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	11/14/2000 12:00:00 AM
Water Body:		**Create Date:**	10/02/2000 12:00:00 AM
Class:	C1	**Update Date:**	11/14/2000 12:00:00 AM
Meets Std:	True	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SIGONA
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	DEC		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"caller recieved an anonymous call from subj who lives in apt building where landlord is keeping drum with an unk substance inside. 25 drums and some of the drums are open"

DEC Remark:

""

Material Information

OP Unit ID:	828481	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	545301	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0064A		
Material Name:	unknown material		

Spiller Information

Spiller Name:	SUPER
Spiller Company:	APT BUILDING
Spiller Address:	363 OCEAN PARKWAY
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	NONE
Contact Phone:	(000) 000-0000
Contact Ext:	
Latitude:	40.732709230
Longitude:	-73.951091030

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
24	2 of 2	S	0.04 / 214.73	12.37 / 0	COMMERCIAL 217 INDIA ST BROOKLYN NY	NY SPILLS

Spill No:	2205227	**UST Trust:**	False
Site ID:	642415	**Spill Date:**	09/15/2022 11:11:00 AM
DER Facility ID:	588855	**Received Date:**	09/15/2022 11:11:00 AM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	09/15/2022 12:00:00 AM

Water Body:		**Create Date:**	09/15/2022 11:13:00 AM
Class:	D5	**Update Date:**	09/15/2022 12:14:42 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	EJKIM
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"oil on the street and curb from multiple mechanic shops"

DEC Remark:

"9/15/22 - Kim - Desk Duty - This complaint regarding housekeeping at mechanics shops was forwarded to NYCDEP ECC who are planning to send someone out to check the area and possible impacts to storm drains. Spill case closed - end"

Material Information

OP Unit ID:	1389434	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2404447	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	MECHANIC SHOPS
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	ADAM KAHATI
Contact Phone:	(516) 512-2420
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
25	1 of1	SSE	0.04 / 215.20	12.37 / 0	DC TRUCK & AUTO REPAIR SHOP INC. 219 INDIA STREET BROOKLYN NY 11222	AST

Site ID:	373006	**Expiry:**	11/03/2016
Site Status:	Active	**County:**	Kings
Program No:	2-610383	**UTM X:**	588549.02443
Program Type Code:	PBS	**UTM Y:**	4509612.24230
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Other		

Tank Information

Prog No:	2-610383	**UDC Ind:**	1
Tank ID:	214315	**Red Tag Start Date:**	
Tank No:	112232	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	10/01/2005	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	275	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 2
Tank Location Desc: Aboveground-contact w/ impervious barrier
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: waste oil/used oil
Percent: 100.00

Equipment Information

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: A02
Code Name: Rubber Liner
Type: Tank Internal Protection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: H06
Code Name: Impervious Barrier/Concrete Pad (A/G)
Type: Tank Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Affiliation Information

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: DC TRUCK & AUTO REPAIR SHOP INC.
Contact Title:
Contact Name: SHUO ON MEI
Address1: 219 INDIA STREET
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 383-8689
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: DC TRUCK & AUTO REPAIR SHOP INC.
Contact Title:
Contact Name: SHUO ON MEI
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 383-8689
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: DC TRUCK & AUTO REPAIR SHOP INC.
Contact Title: PRESIDENT
Contact Name: SHUO ON MEI
Address1: 219 INDIA ST
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 383-8689
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: DC TRUCK & AUTO REPAIR SHOP INC.
Contact Title:
Contact Name: SHUO ON MEI
Address1:
Address2:
City:
State: NN
Zip Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Country Code: 001
Phone: (917) 682-7245
Phone Ext:
Email:
Fax:

---

26 | **1 of3** | **WNW** | **0.04 / 221.55** | **12.24 / 0** | **HALF PINT OIL IN MAN HOLE 71471 GREEN STREET AND MCGUINNESS BROOKLYN NY** | **NY SPILLS**

Spill No: 0704289
Site ID: 384411
DER Facility ID: 333820
CID: 78
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C4
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Unknown
Reported by: Responsible Party
Referred to:
Source: Unknown
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 07/16/2007 08:35:00 PM
Received Date: 07/16/2007 09:02:00 PM
CAC Date:
Insp Date:
Close Date: 08/20/2007 10:23:00 AM
Create Date: 07/17/2007 02:07:00 AM
Update Date: 08/20/2007 10:23:52 AM
DEC Region: 2
Lead DEC: gdbreen
After Hours: True

Caller Remark:

"1/2 pint in manhole and unknnown amount in sewer. con ed #207051 Clean up in progress. NO to all five questions."

DEC Remark:

"08/20/07 - See eDocs for Con Ed report detailing cleanup and closure. 207051. see eDocs"

Material Information

OP Unit ID: 1141716
OU: 01
Material ID: 2131923
CAS No:
Material Family: Petroleum
Quantity: .00
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0066A
Material Name: unknown petroleum

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: True
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: CON EDISON
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name:
Contact Phone:
Contact Ext:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					Latitude: **Longitude:**	
26	2 of3	WNW	0.04 / 221.55	12.24 / 0	ROADWAY GREENE ST MCGINNIS BLVD BROOKLYN NY	NY SPILLS

Spill No:	1607557	**UST Trust:**	False
Site ID:	535214	**Spill Date:**	11/02/2016 10:30:00 AM
DER Facility ID:	489169	**Received Date:**	11/02/2016 11:12:00 AM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	11/03/2016 12:00:00 AM
Water Body:		**Create Date:**	11/02/2016 11:15:00 AM
Class:	C4	**Update Date:**	11/03/2016 03:15:46 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	TJDEMEO
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Passenger Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"roadway only clean up in progress"

DEC Remark:

"11/3/16 TJD Roadway spill cleaned by FDNY. No soil or drainage affected. Spill closed."

Material Information

OP Unit ID:	1283916	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2289363	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	5.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	FIRE FIGHTERS CHAMBERS
Spiller Company:	UNKNOWN
Spiller Address:	GREENE ST MCGINNIS BLVD
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	FIRE FIGHTERS CHAMBERS
Contact Phone:	(347) 203-6886
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
26	3 of3	WNW	0.04 / 221.55	12.24 / 0	UNDERGROUND VAULT MCGUINESS BLVD AND GREEN ST BROOKLYN NY	NY SPILLS

Spill No:	1812191	**UST Trust:**	False
Site ID:	584154	**Spill Date:**	03/05/2019 03:29:00 PM
DER Facility ID:	536579	**Received Date:**	03/12/2019 03:30:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	04/03/2019 12:00:00 AM
Water Body:		**Create Date:**	03/12/2019 03:32:00 PM
Class:	C4	**Update Date:**	04/03/2019 01:49:18 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	PXLAKHAN
REM Phase:	0	**After Hours:**	False

County: Kings
Contributing Factor: Unknown
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"seeping into vault is petroleum natural gas - cleanup done and product came back"

DEC Remark:

"3/12/19 - Obligado - Desk Duty - Contamination found in a nat grid vault in the middle of the street. Appears to be an active seepage. Initial seepage a week ago on the 3/5. They returned to the same vault today and found additional petroleum seepage. This spill is assigned to Pratik Lakhani. 03/14/19 - Lakhani The National Grid Governor 114 vault has been experiencing repeat contamination, and presents a safety issue with our field crews. We will be returning to the site on Wednesday, March 20th at 8:00am with Miller Environmental to perform further decontamination of our vault. As discussed on the phone, our Governor vault only contains natural gas piping and equipment. There is no petroleum source in the vault from any National Grid equipment. National Grid fears that a petroleum product could be leaching into the pit from nearby businesses or residences. Current source unknown. Nicholas Calabro Scientist Environmental Management - DNY nationalgrid O - 516-545-2553 C - 516-408-8928 nicholas.calabro@nationalgrid.com 04/02/19 - Lakhani National Grid received the results for the grab water sample and soil sample that were taken from the vaults. The liquid gathered from Vault #2, which had a visible sheen and noticeable gasoline odor indicates low levels of petroleum contamination: benzene 180 ug/L, ethylbenzene 15 ug/L, toluene 20 ug/L, xylenes 25 ug/L. The debris gathered from the third manhole we opened shows much higher concentrations of both diesel and gasoline contamination: xylene 2500 ppb. The vault was cleaned. 04/03/19 - Lakhani Spill is closed."

Material Information

OP Unit ID:	1331821	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2341043	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0066A
Material Name: unknown petroleum

Spiller Information

Spiller Name:
Spiller Company: GAS STATION IN AREA
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: NICHOLAS CALABRO
Contact Phone: (516) 408-8928

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Contact Ext:						
Latitude:						
Longitude:						

27	1 of1	ESE	0.04 / 226.31	11.70 / 0	FORTUNE METALS INC. 239 INDIA STREET BROOKLYN NY 11222	SEMS

EPA ID:	NYR000170555	**Latitude:**	+40.732673
Pgm Sys ID (Map):	NYR000170555	**Longitude:**	-073.949664
Latitude83 (Map):		**Latitude83 (OD):**	
Longitude83 (Map):		**Longitude83 (OD):**	
Primary Nm (Map):	FORTUNE METALS INC.		
Loc Addr (Map):	239 INDIA ST		
Site Name:	FORTUNE METALS INC.		
Street Address:	239 INDIA STREET		
Street Address 2:			
City:	BROOKLYN		
County:	KINGS		
PGM SYS ID (OD):	NYR000170555		
Name (OD):	FORTUNE METALS INC.		
Loc Addr (OD):	239 INDIA ST		
City (OD):	BROOKLYN		
County (OD):	KINGS		
Postal (OD):	11222		
County Name (Map):	KINGS		
City Name (Map):	BROOKLYN		
Postal Code (Map):	11222		
State:	NY		
Zip:	11222		
Data Source:	EPA Superfund Data and Reports Active Site Inventory (List 8R Active); EPA FRS Interests Map - SEMS (Map); CalOES EPA RCRA TSDF Map - SEMS (OD)		

Site Level Information

Site ID:	0206493	**Superfund Alt Agmt:**	No
NPL:	Not on the NPL	**FIPS Code:**	36047
Federal Facility:	No	**Cong District:**	
FF Docket:	No	**Region:**	02
Non NPL Status:	Removal Only Site (No Site Assessment Work Needed)		

Action Information

Site ID:	0206493	**Start Actual:**	8/12/2011 4:00:00 AM
Operable Units:	00	**Finish Actual:**	8/19/2011 4:00:00 AM
Action Code:	PJ	**Qual:**	S
Action Name:	RP EM REM	**Curr Action Lead:**	EPA Ovrsght
SEQ:	1		
Region:	02		
FF Docket:	No		
NPL:	No		
Federal Facility:	No		

GIS Information

Registry ID:	110040142379	**Pgm Sys Acrnm:**	SEMS
Active Status:	NOT ON THE NPL	**Accuracy Value:**	30
Key Field:	SEMSNYR000170555	**HUC8 Code:**	02030201
Interest Type:	SUPERFUND (NON-NPL)	**HUC 12:**	
Fed Agency Name:		**Public Ind:**	Yes
Fed Facility Code:		**Pgm Report:**	no data yet
Federal Land Ind:		**Point X:**	-73.95018999999996
EPA Region Code:	02	**Point Y:**	40.732740001000025
Fips Code:	36047		
Collect Mth Desc:	ADDRESS MATCHING-HOUSE NUMBER		

Ref Point Desc: CENTER OF A FACILITY OR STATION
Latitude83: 40.73274
Longitude83: -73.95018999999999
Fac Url: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110040142379
Program Url:
Pgm Report Url: no data yet

CalOES EPA RCRA TSDF Map - SEMS Details

Registry ID: 110040142379
Interest Type: SUPERFUND (NON-NPL)
Active Status: NOT ON THE NPL
Pgm Sys Acrnm: SEMS
Federal Agency Nm:
Federal Land Ind:
Fed Facility Cd:
Public Ind: Yes
FIPS Code: 36047
HUC8 Code: 02030201
Longitude83: -73.95019
Latitude83: 40.73274
Pgm Report Url: no data yet
Program URL:
Fac Url: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110040142379

HUC 12:
Collect Mth Desc: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 30
Ref Point Desc: CENTER OF A FACILITY OR STATION
EPA Region Code: 02
Key Field: SEMSNYR000170555
Create Dt: 10/26/2021
Update Dt: 11/24/2021
Last Reported Dt:

---

28 | **1 of1** | **NE** | **0.04 / 231.42** | **11.06 / -1** | **CON EDISON**
359 GREENE ST TM 808
BROOKLYN NY 11201 | **GEN MANIFEST**

RCRA ID: NYP004756128
District Name: CON EDISON
Contact Name: DENNIS HUACON
Business Phone No: 2124603770
Mailing Street 1: 4 IRVING PL 15TH FL
Mailing Street 2:
Mailing City: NEW YORK

Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 1000 Pounds

---

29 | **1 of1** | **SSW** | **0.05 / 241.37** | **12.69 / 1** | **TWO GUYS AUTO GLASS, INC.**
302 MCGUINNESS BOULEVARD
BROOKLYN NY 11222 | **AST**

Site ID: 374288
Site Status: Active
Program No: 2-610415
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Other Wholesale/Retail Sales

Expiry: 12/01/2011
County: Kings
UTM X: 588506.60724
UTM Y: 4509602.61149

Tank Information

Prog No: 2-610415
Tank ID: 214767
Tank No: 001

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:

Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	01/01/2002	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	500	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: waste oil/used oil
Percent: 100.00

Equipment Information

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: A99
Code Name: Other
Type: Tank Internal Protection

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: K99
Code Name: Other
Type: Spill Prevention

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: E12
Code Name: Double-Walled (AG only)
Type: Piping Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: H02
Code Name: Interstitial - Manual Monitoring
Type: Tank Leak Detection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: L02
Code Name: Interstitial - Manual Monitoring
Type: Piping Leak Detection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Tank Information

Prog No:	2-610415	**UDC Ind:**	1
Tank ID:	214768	**Red Tag Start Date:**	
Tank No:	002	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	01/01/2002	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	500	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: lube oil
Percent: 100.00

Equipment Information

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: E12
Code Name: Double-Walled (AG only)
Type: Piping Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B04

Code Name: Fiberglass
Type: Tank External Protection

Equipment: L02
Code Name: Interstitial - Manual Monitoring
Type: Piping Leak Detection

Equipment: A99
Code Name: Other
Type: Tank Internal Protection

Equipment: K99
Code Name: Other
Type: Spill Prevention

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: H02
Code Name: Interstitial - Manual Monitoring
Type: Tank Leak Detection

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Tank Information

Prog No:	2-610415	***UDC Ind:***	1
Tank ID:	214769	***Red Tag Start Date:***	
Tank No:	003	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	01/01/2002	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	500	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: lube oil
Percent: 100.00

Equipment Information

Equipment: C01
Code Name: Aboveground

Type: Pipe Location

Equipment: E12
Code Name: Double-Walled (AG only)
Type: Piping Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: L02
Code Name: Interstitial - Manual Monitoring
Type: Piping Leak Detection

Equipment: K99
Code Name: Other
Type: Spill Prevention

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: H02
Code Name: Interstitial - Manual Monitoring
Type: Tank Leak Detection

Equipment: A99
Code Name: Other
Type: Tank Internal Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Affiliation Information

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: TWO GUYS AUTO GLASS, INC.
Contact Title:
Contact Name: GARY SHOKIN
Address1: 302 MCGUINNESS BOULEVARD
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 383-4808
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: WALL REALTY
Contact Title:
Contact Name: GARY SHOKIN
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (908) 720-6471
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: TWO GUYS AUTO GLASS, INC.
Contact Title:
Contact Name: STEPHEN CODY
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 383-4808
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: WALL REALTY
Contact Title: VP
Contact Name: GARY SHOKIN
Address1: 3333 NEW HYDE PARK ROAD
Address2:
City: NEW HYDE PARK
State: NY
Zip Code: 11042
Country Code: 001
Phone: (516) 869-2963
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	1 of6	W	0.05 / 250.88	12.52 / 1	PULASKI SVC STA 321 MCGUINESS BLVD BROOKLYN NY 11222-1817	RCRA VSQG

EPA Handler ID: NYD095772919
Gen Status Universe: VSG
Contact Name:
Contact Address: 321 , MCGUINESS BLVD , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 40.73331

Location Longitude: -73.952249
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Act W.O. Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19891010
Handler Name: PULASKI SVC STA
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990708
Handler Name: PULASKI SVC STA
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Waste Code Details

Hazardous Waste Code: NONE
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: PULASKI SVC STA
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: PULASKI SVC STA
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: UNKNOWN
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: UNKNOWN
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: UNKNOWN
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Notification
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country:
Zip Code: 99999

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Very Small Quantity Generator
Handler Name: PULASKI SVC STA

Receive Dt: 19990708
Generator Code Description: Not a Generator, Verified
Handler Name: PULASKI SVC STA

Receive Dt: 19891010
Generator Code Description: Large Quantity Generator
Handler Name: PULASKI SVC STA

30	2 of6	W	0.05 / 250.88	12.52 / 1	***MJB SERVICE STATION INC*** ***321 MCGUINNESS BOULEVARD*** ***Brooklyn NY 11222***	UST

Site ID: 22673
Site Status: Active
Program No: 2-600693
Program Type Code: PBS
Expiry: 03/24/2027
County: Kings
UTM X: 588452.97041
UTM Y: 4509697.37339

Program Type Desc: Petroleum Bulk Storage Program
Site Type: Retail Gasoline Sales

Tank Information

Prog No:	2-600693	**UDC Ind:**	0
Tank ID:	57341	**Red Tag Start Date:**	
Tank No:	4	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	08/29/2007
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	06	**Test Method:**	34
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	**Date Tested:**	
Install Date:	12/01/1999	**Next Test:**	
Close Date:		**Line Last Test Due:**	03/19/2019
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	8000	**Line Test Method:**	12
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: SEBASTIAN OLSZEWSKI
Class B Operator: SEBASTIAN OLSZEWSKI
Tank Owner Name: GUS KODOGIANNIS
Tank Owner Address: 321 MCGUINNESS BLVD BROOKLYN, NY. 11222

Material Information

Material Name: gasoline/ethanol
Percent: 10.00

Equipment Information

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Tank Information

Prog No:	2-600693	***UDC Ind:***	0
Tank ID:	43310	***Red Tag Start Date:***	
Tank No:	3	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	08/29/2007
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	34
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:	04/01/1987	***Next Test:***	
Close Date:		***Line Last Test Due:***	03/19/2019
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	12
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: SEBASTIAN OLSZEWSKI
Class B Operator: SEBASTIAN OLSZEWSKI
Tank Owner Name: GUS KODOGIANNIS
Tank Owner Address: 321 MCGUINNESS BLVD BROOKLYN, NY. 11222

Material Information

Material Name: gasoline/ethanol
Percent: 10.00

Equipment Information

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Tank Information

Prog No:	2-600693	***UDC Ind:***	0
Tank ID:	43308	***Red Tag Start Date:***	
Tank No:	1	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	08/29/2007
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	34
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:	04/01/1987	***Next Test:***	
Close Date:		***Line Last Test Due:***	03/19/2019
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	12
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022

Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: SEBASTIAN OLSZEWSKI
Class B Operator: SEBASTIAN OLSZEWSKI
Tank Owner Name: GUS KODOGIANNIS
Tank Owner Address: 321 MCGUINNESS BLVD BROOKLYN, NY. 11222

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Tank Information

Prog No:	2-600693	**UDC Ind:**	1
Tank ID:	217053	**Red Tag Start Date:**	
Tank No:	6	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	06	**Test Method:**	NN
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	**Date Tested:**	
Install Date:	04/01/1987	**Next Test:**	
Close Date:	12/09/2011	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: waste oil/used oil
Percent: 100.00

Equipment Information

Equipment: L00
Code Name: None
Type: Piping Leak Detection

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: D00
Code Name: No Piping

Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G02
Code Name: Vault (w/access)
Type: Tank Secondary Containment

Equipment: F00
Code Name: None
Type: Pipe External Protection

Tank Information

Prog No:	2-600693	***UDC Ind:***	0
Tank ID:	43311	***Red Tag Start Date:***	
Tank No:	5	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	08/29/2007
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	34
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:	04/01/1987	***Next Test:***	
Close Date:		***Line Last Test Due:***	03/19/2019
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	12
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: SEBASTIAN OLSZEWSKI
Class B Operator: SEBASTIAN OLSZEWSKI
Tank Owner Name: GUS KODOGIANNIS
Tank Owner Address: 321 MCGUINNESS BLVD BROOKLYN, NY. 11222

Material Information

Material Name: gasoline/ethanol
Percent: 10.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: I02

Code Name: High Level Alarm
Type: Overfill

Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Tank Information

Prog No:	2-600693	***UDC Ind:***	0
Tank ID:	43309	***Red Tag Start Date:***	
Tank No:	2	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	08/29/2007
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	34
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:	04/01/1987	***Next Test:***	
Close Date:		***Line Last Test Due:***	03/19/2019
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	12
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			
Tank Location:	5		

Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: SEBASTIAN OLSZEWSKI
Class B Operator: SEBASTIAN OLSZEWSKI
Tank Owner Name: GUS KODOGIANNIS
Tank Owner Address: 321 MCGUINNESS BLVD BROOKLYN, NY. 11222

Material Information

Material Name: gasoline/ethanol
Percent: 10.00

Equipment Information

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: H01

Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Affiliation Information

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: MJB SERVICE STATION INC
Contact Title:
Contact Name: GUS KODOGIANNIS
Address1: 321 MCGUINNESS BOULEVARD
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 389-4483
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: MJB SERVICE STATION INC
Contact Title:
Contact Name: GUS KODOGIANNIS
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 999
Phone: (718) 389-4483
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: MJB SERVICE STATION INC
Contact Title:
Contact Name: SEBASTIAN OLSZEWSKI
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-4483
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: MJB SERVICE STATION INC
Contact Title: MANAGER
Contact Name: SEBASTIAN OLSZEWSKI
Address1: 321 MCGUINNESS BLVD
Address2:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 389-4483
Phone Ext:	
Email:	
Fax:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	3 of6	W	0.05 / 250.88	12.52 / 1	PULASKI SERVICE STATION 321 MCGUINNESS BOULEVARD Brooklyn NY 11222	NY SPILLS

Spill No:	9908882	**UST Trust:**	False
Site ID:	125566	**Spill Date:**	10/21/1999 03:00:00 PM
DER Facility ID:	330319	**Received Date:**	10/21/1999 03:16:00 PM
CID:	233	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	04/05/2012 12:00:00 AM
Water Body:		**Create Date:**	10/21/1999 12:00:00 AM
Class:	B2	**Update Date:**	04/05/2012 12:09:41 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	VXBREVDO
REM Phase:	0	**After Hours:**	False

County:	Kings
Contributing Factor:	Human Error
Reported by:	Other
Referred to:	PETITION FOR CLOSURE NEEDS TO BE REVIEWED
Source:	Gasoline Station or other PBS Facility
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"construction work on the road ifo the gas station workers hit the underground fuel line fuel is seeping into the ground no clean up is underway at this point "

DEC Remark:

"8/3/05 File review (KMF): 10/21/99 Rommel Notes: Spoke to Mr. Kodogiannis. At 8am leak detector went off for diesel tank. He called maintenance. Apparently, Tully Construction may have ruptured line from submersible pump to dispenser island. Piping is double walled. Breaking up concrete now. Unknown exact amount lost. Have to do inventory. Maybe 500gal because pumped diesel from 8am-3pm. Diesel turned off since 3pm. Amoco S/S between Huron and Greene St. Not registered in database. Independent Amoco. Piping should be exposed in 1hr. Invoice from Alvin Petroleum dated 10/21/99. Alvin was called on location on a diesel pump out of order. Traced out electric and found OK. Checked STP motor and leak detector, found OK. Found possible problem underground. Suggest line test. Tank installation details provided by Keith Culley, Crawford. K. Culley got the info from Jan Sienkiewicz, President of Arek Petro Corp (50 Division Place, Bklyn NY 11222 (718-486-0011, 718-486-0022 fax)). 12/22/99 NYCDEP permitted dewatering for tank installation. There are water tank waste sampling data submitted by Geologic Services Corp. for Arek.
---------- 04/12/04 TRANSFERRED FROM TIBBE TO VOUGHT. 8/3/05 Reassigned from Vought to Foley. Foley is PM for adjacent property at 305-319 McGuinness Blvd (Spill #0400807). 06/20/06: Re-assigned from Foley to Yau. (Yau) 07/05/06: Prepared and sent an old spill letter to the property owner through certified mail. A site investigation report (SIR) is mandated by 08/05/06. (Yau) 07/10/06: Received invoice bills from property owner showing removal of contaminated soil and collection of groundwater samples. Waiting for laboratory results for collected samples. (Yau) 08/29/2006: Chris Tomasello called and inquired if our case file has any site investigaton report or tank closure report. Told him our file only has a tank installation report. Chris would like a copy of the installation report. After speaking to Joe, Chris must file a FOIL Request before we can send him a copy. Chris can come in and take a look if he prefers. Agreed that an investigation will be conducted since no report is available regarding the site status. (Yau) 10/16/06 Re-assigne from Yau to Chanda (Chanda) 10/31/06 Kartik Chanda of DEC called property owner(Mr. Gus Kodogiannis) to get updated information regarding this spill case. 10/31/06 Chanda receaved a phone call from Mr.Christofer (ASR) and inquired if our case file has any site investigation report or tank closure report. 11/15/06: Chanda sent a letter to the RP (Gus Kodogiannis), requireing taht a Site Investigation Report be submitted to DEC for review by 12/15/2006. 12/21/06: Chanda spoke with Mr. C. Tomasello (ASR) to get update information regarding this site. He stated that the investigation work is going and he need time extension to submit SIR. 12/21/06: Chanda received a time extension request by email from Chris Tomasello (ASR). 12/26/06: Chanda approves the time extension request based on the reasons presented. An investigation summary report is due to March 15,2007. 3/16/07: Chanda received an electronic copy of the Site Investigation Summary Report for Pulaski service Station by email from ASR. 3/26/07: Chanda received a hard copy of the Site Investigation Summary Report for Pulaski Service Station on 3/26/07. 4/10/07: Chanda reviewed the Investigation Summary Report and has the following comments: 1. ASR is suggested that it is highly likely that the contamination detected in the site was emanated from the adjacent, up-gradient, former Getty site(i.e., at 305 McGuinness Blvd.). but, DEC's review of the report shows that the adjacent site at 305 McGuinness is not up-gradient, but cross-gradient of the subject site based on the GW flow direction. 2. The edge of total VOC plume emanating from the adjacent site is about 100-250 ppb, while the total VOC concentration detected in MW ASR-3 of the subject site is 5,540 ppb. This shows that the contamination at the subject is not from the adjacent site. Based on the above reasons,the Department requires the followings: 1. Delineation of soil and groundwater contamination. 2. Submit the tank tightness and pressure test perform prior to March 11, 1997, and repair work performed on the tanks and associates fuel lines prior to March 11, 1997. 4/10/07: Kartik Chanda of DEC sent a letter to RP (Gus Kodogiannis) and his consultant (Chris Tomassello), requiring that the above documents must be submitted to the Department for review

by June 10, 2007. 6/12/07: Chanda called to Steven Muller, ASR, to get updated information regarding the site, and left message. 6/19/07: Chanda received an investigation work plan (IWP) from Advanced Site Restoration LLC(ASR)on 6/14/07. The IWP is proposed three monitoring well installation to delineate soil and/or groundwater contamination at the site. On 6/18/07, Chanda reviewed and approved the IWP with one additional soil boring/ monitoring well; the additional well will be determined that the contamination source come from upgradient another spill case or not. On 6/19/07, Chanda sent an approval letter to RP (Mr. Gus Kodogiannis) and his consultant (ASR), requiring that an investigation summary report be submitted to DEC for review by 8/18/07. 9/6/07: Chanda received a Final Investigation Summary Report (FISR) from Advanced Site Restoration, LLC., dated July 2007. 10/16/07: Chanda reviewed the final Investigation Summary report and has the following comments: 1. The soil analytical results from soil borings ASR-4, ASR-5, ASR-6 and ASR-7 showed elevated levels of VOCs. The levels of BTEX concentration ranged 64 ppb to 22,900 ppb. The levels of MTBE concentrations ranged from 00 ppb to 1,200 ppb. 2. The groundwater (GW) analytical results showed elevated levels of VOCs for monitoring wells ASR-4, ASR-5, ASR-6 and ASR-7. The levels of BTEX concentrations ranged from 883 ppb to 4,860 ppb. The levels of MTBE concentrations ranged from 160 to 630 ppb. 10/24/07: Chanda visited the site and meets with RP and his consultant, Steven Muller and Richard Levato of Advanced Site Restoration, LLC(ASR).Chanda discuss about the findings of investigation. It is concluded that they will submit the Test Results on USTs and will search the sources of contamination on/off-site area. 1/14/08: Chanda received an email (see eDocs) from Steve Muller, ASR regarding the site updated information. He stated that a GW monitoring report will be submit to DEC as soon as possible for review. 3/6/08: Chanda received a Supplemental Investigation Summary Report(SISR) from ASR dated February 2008. Chanda has reviewed the SISR and has the following comments: * The groundwater (GW) analytical results showed elevated levels of VOCs. Total BTEX concentrations ranged from 149 ppb to 5,319 ppb. MtBE was detected in five (5) monitoring wells (ASR-1 through ASR-4 and ASR-6), with concentrations ranging from 8 ppb to 1,400 ppb. Based on the findings of this supplemental investigation, ASR recommended the followings: • Continue quarterly sampling of all the monitoring wells. • Continue monthly monitoring on all of the monitoring wells. • Install a new monitoring well to the north of monitoring well ASR-1. • Prepare and submit a Pro-Active Remedial Action Plan. 4/25/08: On 4/24/08,Chanda has discussed with Joe Sun (NYSDEC) regarding the findings of the SISR.Chanda and Joe concurs with the above recommendations. Chanda sent a letter to RP and his consultant requiring that a Remedial Action Plan (RAP) and GW Quarterly Report must be submitted to the Department by 6/25/08 for review and approval. 6/23/08: Chanda received a Monthly Monitoring Report dated June 16, 2008 prepared by ASR for this site. All monitoring wells were sampled on June 5, 2008. 7/10/08: Chanda received a Remedial Action Plan (RAP) dated July 9, 2008, prepared by Advanced Site Restoration, LLC (ASR) on behalf of Pulaski Service Station Inc. (see eDocs) 7/15/08: Chanda has reviewed the RAP and has the following: -The Site Soil and Groundwater were contaminated by the petroleum related hydrocarbon. The RP's consultant, ASR proposes that the residual soil and groundwater contamination on the subject site can be successfully remediated, utilizing an in-situ bio-remediation approach. -The initial injection via nine injection points will introduce approximately 144 lbs of RegenOX to the subsurface. - Within three (3) months of the RegenOX application, a round of quarterly groundwater quality sampling and analysis will be conducted. -Continue to conduct monthly groundwater monitoring and quarterly groundwater sampling and analysis. -A report describing the bio-application, pre and post application groundwater quality analysis will be prepared nad submitted to the NYSDEC. 7/22/08: DER staff approved the RAP. Chanda sent an approval letter to RP and his consultant (ASR) requiring that the RAP be implemented by September 15, 2008. 10/30/08: Chanda received an email with EPA approval letter for RegenOX application. The RP's consultant (ASR) requests an extension on the implementation of the RAP. The Department approves the time extension. Chanda sent a letter to RP and his consultant requiring that the RAP must be implemented by 12/29/08. 12/7/11. Jennifer of Island Pump & Tank called yesterday to advise DEC that Island Tank will be removing a 550 gallon UST at this Gulf station on 12-8-11. Jennifer called from 631-462-2226. PBS registration is 2-600693. Breen 12/7/2011 Called Jennifer of Island Pump and Tank to find out about the status of Regenox remedial plan (RAP) approved by DEC in 2008. Jennifer was just retained to remove 550 gallon UST and is unable to provide insight into project status on RAP implementation. I left message on ASR's (consultant as of 2008) voice mail, asked Steven Muller or Chris Tomasello of ASR to call me regarding this project. I need to find out whether RAP (Regenox) was implemented. If implemented - where is report? Spill closure petition dated September 2009 refers to future implementation of the Regenox injections. If Regenox is yet to be implemented then spill closure would be inappropriate. Spill closure must follow satisfactory results of Regenox, not precede it. Brevdo 12/7/2011 Received a call from Rich Levato of ASR. ASR was rehired today to be a consultant of record for the project. Mr. Levado will be providing to me a current status of the project, report from a 550 gallon UST with post excavation end-point sampling data, any documentation that may have been generated between 2008 and present, and also will elaborate on the further course of action for the project. Mr. Levado stated he will e-mail me the project status and proposed further course of action. Brevdo 12/7/2011 E-mail communications with Rich Levato: Dear Mr. Levato, Thank you very much for the e-mail and information. This is extremely helpful. I look forward to working with you and your client to accomplish a complete site remediation and, ultimately, closing the spill based on all relevant technical information which would support spill closure. One additional item that we discussed during the telephone conversation earlier today was that I need to know whether Remedial Action Plan (RAP) for RegenOx application submitted by ASR in 2008 and approved by DEC in 2008 was implemented or not. If affirmatively, the results of the RAP implementation must be described in a Remedial Action Report and be part of any further considerations regarding possibility of spill closure. Furthermore, I would like you to be cognizant that any future discussion of a potential for spill closure by DEC will not be based solely on ASR's submission and DEC's review of a Tank Closure Report, but will rather be based on a submission of a Remedial Action Report or Spill Closure Petirion/Report. Remediatial Action Report or Spill Closure Petition/Report must describe (but not be limited to) the following: * Summary of all investigations and remedial actions that were completed at the site, including 550 gallon tank removal; * Summary of the Results of the investigative and remedial actions; * Comparison of the past and recent data; * Past and Recent soil and groundwater data; * Description of decreasing trend in groundwater concentrations; * Demonstration of improvement in environmental conditions of the site based on the remedy implemented; * Describe whether site has any current and/or future potential for human exposures to residual contaminants; * If any additional remedy is non-feasible, provide comprehensive explanation of the reasons for non-feasibility; * Describe whether any off-site contaminant migration occurs or has potential to occur. Thank you for your and your client's responsiveness on this matter, Respectfully, Vadim Brevdo Vadim Brevdo, P.E. Environmental Engineer Section Chief NYS Dept. of Environmental Conservation Division of Environmental Remediation Remediation Section B 47-40 21st Street Long Island City, NY 11101 Tel. 718-482-4928 Fax. 718-482-6358 e-mail: vxbrevdo@gw.dec.state.ny.us>>> Dana Levato 12/7/2011 12:41 PM >>> Vadim, It was a pleasure speaking with you this morning. Tomorrow, December 8, 2011, Island Pump & Tank has been scheduled to remove the 550 gallon waste oil tank from the site located at 321 McGiunness Blvd. Based on our conversation, ASR will also be on-site to collect end-point samples (one from each sidewall and the base). These samples will be analyzed for EPA Method 8260/8270 plus RCRA Metals. Additionally, ASR will be collecting groundwater samples to confirm that the site has remained in a site closure status. Once these results are received, ASR will be able to discuss closure and/or future work with the department. As we discussed, I am preparing historical data before July 2008 on one CD and work confirming remedial activities on a second CD. ASR will prepare and submit a Tank Closure Report. I want to thank you in advance for taking the time to help my client expedite this site. Sincerely, Richard Levato Principal Advanced Site Restoration, LLC 62 William Street, 3rd Floor New York, NY 10005 Office: 212.809.1110 Fax: 212.809.1779 www.askASR.com 3/29/2012 - Brevdo - ASR submitted Spill File Closure Report dated February 2012. I will review report and make conclusion whether conclsuions and recommendations to close spill are appropriate. Brevdo 3/29/2012 - Brevdo - results of DEC review of the Spill File Closure Report dated February 2012: The subject site is an active Gulf gasoline service station located at 321 McGuinness Boiulevard. To the south of the site, across Huron Street is a former Getty Gasoline service station with an open DEC Spill No. 0400807 currently being sold as condo units. This site of spill No. 0400807 is upgradient in ground flow direction from the subject site Spill no 9908882. Background Summary: 1) According to NYSDEC spills database,

on October 21, 1999, spill number 9908882 was assgined to the subject site for the release of 1,000 gallons of diesel fuel. 2) It has been reported that this crack and product release occurred during excavation activities by a city contractor along McGuinness Blvd. and not the fault of the owner/operator of the subject site. The city contractor removed as much of the contaminated soils by over excavating and replacing it with clean soil. 3) On October 26, 1999, Arek Petro Corporation perforemd a pressure tughtness test on the new fiberglass discharge line replacing the one that underwent damage leading to the spill. 4) On December 23, 1999, A.P. Gas Station Developer, Inc. revmoed 418.62 tons of contaminated soil from the subject site as a remedial solution to the spill that was caused by City contractor. 5) On January 27, 2007, ASR was retained by the property owner to investigate prior owrk and to close out the spill. ASR advanced three borings as per the NYSDEC request. 6) The three borings were converted into monitoring wells in the location of the reported diesel spill. All analytical results incidcated there were no SVOC's however the laboratory results did detect VOCs in hte groundwater. 7) ASR conducted a record search and discovered that the on the adjacent property to the subject site, indicated that it has an open NYSDEC Spill No. 0400807 and is listed for gasoline and MTBE in the groundwater. Teh groundwater survey indicated that gorundwater was flowing from the adjacent site onto the subjet site. 8) NYSDEC responded to this report, disagreeing that the groundater flow from the Getty station was upgradient, and noted that the informaiton indicated that it was cross-gradient. DEC also instructed the clinet to perform a subsurgace insvestigation of the site. 9) On June 23, 2007, four (4) additional grounwater monitoring wells were installed throughout the south side of the subject site closest to the adjacent property iwth the open spill number for gasoline and MTBE. Lab results of the gorundwater smapoles identified 4 wells as having elevated levels of MTBE and Benzene. Highest concentrations of ten (10) VOCs were detected between 37 ppb and 2,400 ppb. ASR also confirmed that the groundwater flow direction was to the northeast, which supported the prior statement that contamination from the Getty station was flowing onto the site. 10) In July of 2008, ASR submitted a Remedial Action Plan (RAP) to the NYSDEC and the EPA to propose a method to treat the contaminated plume. 11) The RAP was approved by bothe the NYSDEC and the EPA on or before October 23, 2008 to perform the in-situ remediation of groundwater contamination with petroleum compounds, utilizing RegenOx. 12) On December 8th and 9th, 2011 Island Pump nad Tank Corp, (Island) excavated, cleaned, and disposed of one 550 gallon Waste Oil UST. End point samples were collected. 13) February and March 2012 - Preparation and submission of a Site Closure Report. Improvement of environmental conditions: Remediation showed good progress in significantly reducing grounwater concentrations as follows: Well ASR-1 - BTEX reduction from 162 ppb in 2008 to ND in 2011. MTBE from 31 in 2008 ppb to ND in 2011. Well ASR-2 - BTEX and MTBE were ND in 2008 and 2011 Well ASR-3 - BTEX reduction from 1691 ppb in 2008 to 279 ppb in 2011. MTBE from 800 ppb in 2008 ppb to 100 ppb in 2011. Well ASR-4 - BTEX increase from 1420 ppb in 2008 to 3,215 ppb in 2011. MTBE from 360 ppb in 2008 ppb to 92 ppb in 2011. Well ASR-5 - BTEX reduction from 305 ppb in 2008 to ND ppb in 2011. MTBE from 850 ppb in 2008 ppb to ND ppb in 2011. Well ASR-7 - BTEX 4,160 ppb in 2011, MTBE - ND in 2011. Well ASR-8 - all NDs. I agree that concentrations in ASR 4 and ASR 7 appear to be impact from an upgradient site of former Getty station. Overall, RP has implemented an effective remediation that was feasible: excavation and treatment of grounwater with RegenOx. Implementation of further remedy is likely not feasible. Given the site continuous use as active gas station the remedy is sifficient and site poses no further threat to human health and the environment. Sensitive Receptor Survey demonstrated the following: There are no sufface water bodies located within 1,000 feet of the Site; The letter G subway train runs along Manhattan Avenue which is parallel to McGuinness Boulevard, one block over; A major gas main that is located under the sidewalk adjacent to the site and runs parallel with Jerome Avenue; Groundwater flows to the norht, northeast; In general, most commercial and private structures located within 1,000 feet of the site have basements; The three nearest basements are commercial/residential, which are located upgradient from the subject site; Review of available records at the NYSDEC incidated that there are no municipal or private wells located within 2,000 feet of the Site; Local potable water supply is obtained from reservoirs located approximately greater than 25 miles from the Site. Conclusions: Based on the soil and groundwater analytical results collected to date, the subject site poses no significant environmental threat to potenticla groundwater receptors. Based on past remediation activities on the subject site, the follow up testing, the established groundwater flow direction, and the location of the NYC water main, that the contamination is emanating from the upgradient site, rather than the subject site itself. Recommendations: Advansed Site Restoration, LLC respectfully requests the NYSDEC to consider the investigation and remediation of the petroleum hydrocarbon spill complete and issu a No Further Action Letter to close spill 9908882. My (Brevdo) conclusions based on the review of available file records and February 2012 Spill Closure Report is as follows: * Responsible Party has implemented an effective remediation that was feasible: excavation and treatment of grounwater with RegenOx. * Implementation of further remedy is unlikely to be feasible and is unlikely to further improve groundwater conditions. As mentioned above - groundwater remedy was effective and most of the wells show Non Detect. Concentrations in two wells can be attributed to impact from an upgradient site and do not pose threat to receptors. * No free product remains at the site. * No rossly contaminated soil with visible staining remains at the site. * Source of contamination has been removed. * Concentrations of contaminants in soil and groundwater are either at the levels of cleanup guidance values or higher but within acceptable range to DEC. * No migration of contaminant off site occurs. * Remaining contamination is contained, no threat of exposure to vapors from remaining contamination exists, and site poses no further threat to human health and environment. * Given the site's continuous use as active gas station the remedy is sifficient and site poses no further threat to human health and the environment. Based on the above conclusions spill closure is appropriate. Brevdo 04/05/2012 Spill is closed. The following e-mail sent to consultant with attached spill closure letter: Dear Mr. Levato: I have reviewed Spill Closure Report dated February 2012. I agree with ASR's recommendation for spill closure. Spill is closed effective April 5, 2012. Spill Closure letter is attached for your file. Respectfully, Vadim Brevdo "

Material Information

OP Unit ID:	1087568	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	297982	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	1000.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Name:
Spiller Company: TULLY CONSTRUCTION
Spiller Address:
Spiller City: QUEENS
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: HEDY KODOGIANNIS
Contact Phone: (718) 389-4483
Contact Ext:
Latitude: 40.732935840
Longitude: -73.952236190

30	4 of6	W	0.05 / 250.88	12.52 / 1	SIDEWALK 321 MCGUINESS BLVD BROOKLYN NY	NY SPILLS

Spill No: 1609775
Site ID: 538581
DER Facility ID: 492390
CID:
Program Type: ER
SWIS Code: 2401
Water Body:
Class:
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Unknown
Reported by: Other
Referred to:
Source: Unknown
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 01/24/2017 10:05:00 AM
Received Date: 01/24/2017 10:05:00 AM
CAC Date:
Insp Date:
Close Date: 01/24/2017 12:00:00 AM
Create Date: 01/24/2017 10:09:00 AM
Update Date: 01/24/2017 01:23:15 PM
DEC Region: 2
Lead DEC: vszhune
After Hours: False

Caller Remark:

"rev report will forwarded email with photos"

DEC Remark:

"1/24/17 TJD No contact information in spill report. Hotline contacted to obtain any other available information. Complaint came into dispatch via email. Photos sow rainbow sheen along sidewalk and roadway from unknown source. Discussed available information with RSE and dispatched FDO (Zhune) for site inspection. 1/24/17-Zhune visited the site. the site is a Gulf gas station. They were filling a truck. The driver jumped over the pipe, the nozzle came out and spilled 1 to 2 gallons of regular(87)gasoline. because is raining it looks is all over the pump. The personal from the gas station cleaned the spill. Spill closed. Harprent Sinh Store # 718-383-8430 321 Macguinnes Blvd 11222"

Material Information

OP Unit ID: 1287168
OU: 01
Material ID: 2292859
CAS No:
Material Family: Hazardous Material
Quantity:
Units:
Recovered:
Med Soil: False
Med Air: False
Material Code: 0063A
Material Name: unknown hazardous material

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Name: CHRIS PERSHEFF
Spiller Company: UNKNOWN
Spiller Address: 321 MCGUINESS BLVD
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: CHRIS PERSHEFF
Contact Phone:
Contact Ext:
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	5 of6	W	0.05 / 250.88	12.52 / 1	MJB SERVICE STATION (PULASKI SVC STA) 321 MCGUINESS BLVD BROOKLYN NY 11222	GEN MANIFEST

RCRA ID: NYD095772919
District Name: MJB SERVICE STATION (PULASKI SVC STA)
Contact Name: RUBY MACEDO
Business Phone No: 6314622226
Mailing Street 1: 40 DOULE CT
Mailing Street 2:
Mailing City: EAST NORTHPORT
Mailing State: NY
Mailing ZIP: 11731
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2012: 200 Pounds

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	6 of6	W	0.05 / 250.88	12.52 / 1	AIR 321 MCGUINNESS BLVD BROOKLYN NY	NY SPILLS

Spill No: 1812673
Site ID: 584652
DER Facility ID: 536507
CID:
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C4
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Unknown
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data
UST Trust: False
Spill Date: 03/27/2019 12:23:00 PM
Received Date: 03/27/2019 12:23:00 PM
CAC Date:
Insp Date:
Close Date: 03/27/2019 12:00:00 AM
Create Date: 03/27/2019 12:25:00 PM
Update Date: 03/27/2019 04:00:42 PM
DEC Region: 2
Lead DEC: PXLAKHAN
After Hours: False

Caller Remark:

"The following information was received through the DEC website "Report an Environmental Violation Online" or sent directly by the complainant to an OPP dispatch mailbox: Who Did It: Gulf Gas station, 321 McGuinness Boulevard between Green and Huron, Brooklyn, NY 11222 What Occurred: We have had an awful gas smell in our building for over a month. We have checked everything in the building, National Grid has confirmed it is not natural gas, and we suspect it is a spill or leak from the Gulf gas station. When Did It Occur: We noticed the horrible smell in the middle of February 2019. It has varied in how bad it is by day but it keeps coming back. County: Kings Municipality: Brooklyn Location Or Address: 321 McGuinness Boulevard between

Green and Huron How Did It Occur: I'm not sure. I don't know how to confirm this except to contact you. We have been smelling a very strong gas smell for over a month. We have lived in the same building for almost 2 years and this has never happened before. Additional Details: My building is 211 Green Street. We are across the street from the gas station. I have already filed a complaint with NYC DEP. I am worried about public health and safety. Complainants Name: Julia Howe Complainants Phone: 917-789-6123 Complainants Email: juliahowe8@gmail.com Date of Submittal: 03/27/2019"

DEC Remark:

"3/27/2019 - Feng - Duty Desk. Informed by Pratik Lakhani that he will call for information. see Spill 1812114 for the same odor complaint issue. 03/27/19 - Lakhani Julia Howe reported gasoline odors in her building located at 211 Green Street. The building is a 3 floor building with a basement. There are 6 units in the building. Julia and her 18 month year old child live on the second floor. The odors are the worst on the first floor. National Grid responded and determined that the odors were not natural gas. FDNY responded and inspected the site. FD found small cans of motor oil and removed them from the property. The odors persisted. The building's plumbing was checked and a small hole was found in the pipe leading to the main sewer line. The hole was patched and tenants noticed the odors dissipate. The tenants of 211 Green Street began detecting the odors in mi-February 2019. The odors are periodically observed. Spill is closed and referred to spill #1812114."

Material Information

OP Unit ID:	1332326	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2341575	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0064A		
Material Name:	unknown material		

Spiller Information

Spiller Name:	JULIA HOWE
Spiller Company:	GULF
Spiller Address:	321 MCGUINNESS BLVD
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	JULIA HOWE
Contact Phone:	(917) 789-6123
Contact Ext:	
Latitude:	
Longitude:	

31	***1 of4***	***ESE***	***0.05 / 269.11***	***11.65 / 0***	***CON EDISON 237 INDIA ST BROOKLYN NY 11222***	***RCRA NON GEN***

EPA Handler ID:	NYP004804605
Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20150709
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150709
Handler Name:	CON EDISON
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150709
Handler Name:	CON EDISON
Source Type:	Emergency
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Historical Handler Details

Receive Dt:	20150709
Generator Code Description:	Small Quantity Generator
Handler Name:	CON EDISON

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
31	2 of4	ESE	0.05 / 269.11	11.65 / 0	CON EDISON 237 INDIA ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID:	NYP004798435
Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02

Land Type: Private
Receive Date: 20150624
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150624
Handler Name: CON EDISON
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150624
Handler Name: CON EDISON
Source Type: Emergency
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Historical Handler Details

Receive Dt: 20150624
Generator Code Description: Small Quantity Generator
Handler Name: CON EDISON

31	3 of4	ESE	0.05 / 269.11	11.65 / 0	CON EDISON 237 INDIA ST SB 7530 BROOKLYN NY	GEN MANIFEST

RCRA ID: NYP004804605 **Mailing State:** NY

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

District Name:	CON EDISON	**Mailing ZIP:**	10003
Contact Name:	DENNIS HUACON	**Mailing ZIP Ext:**	
Business Phone No:	2124603770	**Mailing Country:**	USA
Mailing Street 1:	4 IRVING PL 15TH FL	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	NEW YORK	**Location County:**	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 50 Gallons

---

31 | ***4 of4*** | ***ESE*** | ***0.05 / 269.11*** | ***11.65 / 0*** | ***CON EDISON***
237 INDIA ST SB 7530
BRONX NY | ***GEN MANIFEST***

RCRA ID:	NYP004798435	**Mailing State:**	NY
District Name:	CON EDISON	**Mailing ZIP:**	10003
Contact Name:	DENNIS HUACON	**Mailing ZIP Ext:**	
Business Phone No:	2124603770	**Mailing Country:**	USA
Mailing Street 1:	4 IRVING PL 15TH FL	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	NEW YORK	**Location County:**	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 50 Gallons

---

32 | ***1 of1*** | ***E*** | ***0.05 / 274.97*** | ***11.30 / -1*** | ***PRONTO DEMOLITION CORP.***
73 PROVOST ST
Brooklyn NY 11222 | ***SWF/LF***

Activity Number:	[24W58]	**Facility Name (InAct):**	PRONTO DEMOLITION CORP.
Facility Name (Act):		**Location Addr (InAct):**	73 PROVOST ST
Location Addr (Act):		**Loc Addr2(InAct):**	
Location Addr2 (Act):		**City (InAct):**	Brooklyn
City (Act):		**State (InAct):**	NY
State (Act):		**Zip Code (InAct):**	11222
Zip Code (Act):		**County (InAct):**	Kings
County (Act):		**East Coord (InAct):**	588682
East Coord (Act):		**North Coord (InAct):**	4509637
North Coord (Act):			
Facility Name:			
Location Addr:			
Location Addr2:			
City:			
State:			
Zip Code:			
County:			
East Coord:			
North Coord:			
Data Source:	SWMF - Inactive Facility Lists		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		***Authorization No:***	
Activity Desc:	C&D processing - registration	***Authrzation Issue Dt:***	
Regulatory Status:		***Operator Type:***	
Active:	No	***Operator Name:***	
Dt of Last Inspection:		***Phone No:***	7180000000
Expiration Dt:		***Region:***	2
Owner Type:		***Contact Name:***	VINNY CUCCHIARI; TRUCK DRIVER
Owner Name:		***Contact Address:***	
Owner Address:		***Contact Address2:***	
Owner Address2:		***Contact City:***	
Owner City:		***Contact State:***	
Owner State:		***Contact Zip:***	
Owner Zip:		***Contact Phone:***	
Owner Phone:		***Contact Email:***	
Owner Email:			
Waste Types:			

33	***1 of3***	***NW***	***0.05 / 281.89***	***12.02 / 0***	***CON EDISON SERVICE BOX: 8385 346 MCGUINESS BROOKLYN NY 11222***	***RCRA NON GEN***

EPA Handler ID:	NYP004361838
Gen Status Universe:	No Report
Contact Name:	BENJAMIN WARE
Contact Address:	
Contact Phone No and Ext:	718-666-4515
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20131017
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20130917
Handler Name: CON EDISON SERVICE BOX: 8385
Source Type: Emergency
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20131017
Handler Name: CON EDISON SERVICE BOX: 8385
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20130917
Generator Code Description: Very Small Quantity Generator
Handler Name: CON EDISON SERVICE BOX: 8385

33	*2 of3*	*NW*	*0.05 / 281.89*	*12.02 / 0*	***CON EDISON*** ***F/O 346 MCGUINNESS BLVD*** ***SERVICE BOX # 8385*** ***BROOKLYN NY 11222***	***GEN MANIFEST***

RCRA ID: NYP004361838
District Name: CON EDISON
Contact Name: TOM TEELING
Business Phone No: 2124603770
Mailing Street 1: 4 IRVING PLACE 15TH FLOOR
Mailing Street 2:
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: NEW YORK

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2013: 100 Gallons

33	*3 of3*	*NW*	*0.05 / 281.89*	*12.02 / 0*	***CON EDISON*** ***346 MAGUINNESS AVE SB 8385*** ***BROOKLYN NY***	***GEN MANIFEST***

RCRA ID: NYP004349015
District Name: CON EDISON
Contact Name: CON EDISON
Business Phone No: 2124603770
Mailing Street 1: 4 IRVING PL 15TH FL
Mailing Street 2:
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2013: 60 Gallons

---

34 | ***1 of1*** | ***ENE*** | ***0.06 / 294.15*** | ***11.06 / -1*** | ***FRANKLIN AND BEDFORD AVES 381 GREEN AVE BROOKLYN NY*** | ***NY SPILLS***

Spill No:	0711578	***UST Trust:***	
Site ID:	393084	***Spill Date:***	02/02/2008 04:39:00 PM
DER Facility ID:	342703	***Received Date:***	02/02/2008 04:48:00 PM
CID:	41	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	02/04/2008 12:00:00 AM
Water Body:		***Create Date:***	02/02/2008 05:00:00 PM
Class:		***Update Date:***	02/04/2008 09:52:01 AM
Meets Std:	False	***DEC Region:***	2
Penalty:		***Lead DEC:***	hrpatel
REM Phase:	0	***After Hours:***	
County:	Kings		
Contributing Factor:	Human Error		
Reported by:	Other		
Referred to:			
Source:	Private Dwelling		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"cleanup in progress"

DEC Remark:

"02/04/08-Hiralkumar Patel. spoke with Dannis. oil spilled from vent pipe on concrete sidewalk. no spill in basement. all cleaned up. case closed."

Material Information

OP Unit ID:	1150058	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2140621	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	5.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	FERRENTINO OIL
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	999
Contact Name:	DENNIS GOLDSTIEN
Contact Phone:	(718) 832-6700
Contact Ext:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Latitude:		40.687942000				
Longitude:		-73.955737000				
35	1 of1	NW	0.06 / 306.84	12.05 / 0	CON EDISON SERVICE BOX: 8385 348 MCGUINESS BLVD BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004349015
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20130921
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20130821
Handler Name: CON EDISON SERVICE BOX: 8385
Source Type: Emergency
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20130921
Handler Name: CON EDISON SERVICE BOX: 8385

Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20130821
Generator Code Description: Very Small Quantity Generator
Handler Name: CON EDISON SERVICE BOX: 8385

---

36 | **1 of2** | **NNW** | **0.06 / 308.72** | **11.69 / 0** | **CON EDISON**
242 FREEMAN ST
BROOKLYN NY 11222 | **RCRA NON GEN**

EPA Handler ID: NYP004725644
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20150204
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150204
Handler Name: CON EDISON
Source Type: Emergency
Federal Waste Generator Code: 1

Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150204
Handler Name: CON EDISON
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20150204
Generator Code Description: Large Quantity Generator
Handler Name: CON EDISON

---

36 | **2 of2** | **NNW** | **0.06 / 308.72** | **11.69 / 0** | **CON EDISON**
242 FREEMAN ST SB8465
BROOKLYN NY 11201

GEN MANIFEST

RCRA ID: NYP004725644
District Name: CON EDISON
Contact Name: CON EDISON
Business Phone No:
Mailing Street 1: 4 IRVING PL
Mailing Street 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 2000 Pounds

---

37 | **1 of2** | **NW** | **0.06 / 331.18** | **11.72 / 0** | **RESIDENTIAL**
352 MCGUINESS BLVD
BROOKLYN NY

NY SPILLS

Spill No: 1911000
Site ID: 601681
DER Facility ID: 550260
CID:
Program Type: ER
SWIS Code: 2401
Water Body:
Class:
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Unknown
Reported by: Other
Referred to:
Source: Unknown
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data
UST Trust: False
Spill Date: 02/27/2020 12:00:00 PM
Received Date: 02/27/2020 12:34:00 PM
CAC Date:
Insp Date:
Close Date: 03/31/2020 12:00:00 AM
Create Date: 02/27/2020 12:37:00 PM
Update Date: 03/31/2020 02:09:42 PM
DEC Region: 2
Lead DEC: RHLIN
After Hours: False

Caller Remark:

"caller states apartment building has a very prominate gasoline odor in the apartment as well or stair well."

DEC Remark:

"2/27 - Sekhon Notifier complained about petroleum odors in the hallway and in stairwell. Case discussed with DEC Andre & DEC Rick Lin (daytime runner) dispatched to investigate. 2/27/20-Lin-The spill address is 352 McGuiness blvd and not 353 McGuiness blvd. The building has two (2) 275 gallon ASTs that are connected. They had a delivery today and the tanks are currently full. Only the fill pipe was found outside the building and the vent pipe was nowhere to be found on the outside. The building had put a new brick exterior on the first floor of the building and had covered the vent pipe. Therefore the vent pipe is located in between the new exterior brick and old exterior wall. We do not see any free product from inside or outside the building. The door to the basement was opened up and the odor is dissipating. 3/31/20-Lin-A licensed plumber was hired to relocate the vent pipe to outside the building. No oil spill was observed by the plumber when the vent pipe was moved to the outside of the building. Case closed. Juan (Super): 347-547-9949 Fation.dautllari@choicenewyork.com (Management): 646-650-2938 254 west 31st New York New York, 10001 6th floor"

Material Information

OP Unit ID:	1348791	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2359346	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	JUSTIN BENNINGTON
Spiller Company:	UNK
Spiller Address:	353 MCGUINESS BLVD
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	JUSTIN BENNINGTON
Contact Phone:	(407) 595-8797
Contact Ext:	
Latitude:	
Longitude:	

37	***2 of2***	***NW***	***0.06 / 331.18***	***11.72 / 0***	***APARTMENT COMPLEX 352 MCGUINNESS BLVD BROOKLYN NY***	***NY SPILLS***

Spill No:	2108266	***UST Trust:***	False
Site ID:	630207	***Spill Date:***	12/11/2021 07:44:00 PM
DER Facility ID:	577256	***Received Date:***	12/11/2021 07:44:00 PM
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	12/21/2021 12:00:00 AM
Water Body:		***Create Date:***	12/11/2021 07:47:00 PM
Class:	D3	***Update Date:***	12/21/2021 08:17:11 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	RMPIPER
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Caller states that there is an odor of fuel oil that is throughout her apartment building that is noxious. She is looking for assistance with this. Will not provide contact info."

DEC Remark:

"DEC Piper responded. Could not gain access though I spoke with a tenant. She will look in basement later and call me if necessary. 12/21/21 - DEC Piper- No callback received from building. Spill closed."

Material Information

OP Unit ID:	1377316	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2390870	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	APARTMENT OWNER
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	ANONYMOUS
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

38	*1 of9*	*SW*	*0.06 / 342.07*	*13.00 / 1*	***MANHOLE 71304 MCGUINNESS BL/INDIA ST BROOKLYN NY***	***NY SPILLS***

Spill No:	0002190	***UST Trust:***	False
Site ID:	299651	***Spill Date:***	05/22/2000 09:00:00 AM
DER Facility ID:	242402	***Received Date:***	05/22/2000 09:47:00 AM
CID:	382	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	03/24/2004 12:00:00 AM
Water Body:		***Create Date:***	05/22/2000 12:00:00 AM
Class:	C4	***Update Date:***	03/24/2004 12:00:00 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	JHOCONNE
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"6 gals oil on 5000 gals of water contained in manhole. clean up pending. con ed 131-520. manhole contains 2 feeders 61 and 63 "

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis no. 131520: There is approx. 6 gallons of unknown oil and 5,000 gallons of water in manhole. Cleanup pending samples results. Sample ID No. 00-05044 PCB 1 ppm PUMPED OUT MH WITH CON ED TANKER ON 5/30/00. SOURCE OF SPILL UNKNOWN. "

Material Information

OP Unit ID:	824101	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	550562	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	6.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	BILL MURPHY
Contact Phone:	(212) 580-6763
Contact Ext:	
Latitude:	
Longitude:	

38	*2 of9*	*SW*	*0.06 / 342.07*	*13.00 / 1*	***MANHOLE #62845 MCGUINESS BLVE/INDIA ST BROOKLYN NY***	***NY SPILLS***

Spill No:	9911540	***UST Trust:***	False
Site ID:	178495	***Spill Date:***	01/04/2000 11:00:00 AM
DER Facility ID:	149902	***Received Date:***	01/04/2000 11:50:00 AM
CID:	281	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	03/04/2002 12:00:00 AM
Water Body:		***Create Date:***	01/04/2000 12:00:00 AM
Class:	C4	***Update Date:***	03/04/2002 12:00:00 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	JHOCONNE
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Affected Persons		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"ABOVE MATERIAL DISCOVERED ABOVE LOCATION. SAMPLE TAKEN AND CLEAN UP IS PENDING TEST RESULTS. CON ED # 129485. NO CALL BACK REQUESTED MATERIAL IS ONTOP OF 100 GALLONS OF WATER."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL "

Material Information

OP Unit ID:	1086157	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	296996	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	5.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	STEVEN CRIBBIN
Contact Phone:	(212) 580-8576
Contact Ext:	
Latitude:	
Longitude:	

---

38 | ***3 of9*** | ***SW*** | ***0.06 / 342.07*** | ***13.00 / 1*** | ***MANHOLE #71304 MCGUINNESS BLVD/INDIA ST BROOKLYN NY*** | ***NY SPILLS***

Spill No:	0211464	***UST Trust:***	False
Site ID:	99683	***Spill Date:***	02/16/2003 09:55:00 AM
DER Facility ID:	88555	***Received Date:***	02/18/2003 04:59:00 PM
CID:	252	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	12/08/2016 12:00:00 AM
Water Body:		***Create Date:***	02/18/2003 12:00:00 AM
Class:	C3	***Update Date:***	12/08/2016 03:19:39 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	HRPATEL
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:	ERT		
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CREW WAS LOOKING FOR A LEAK ON THE RUN OF A FEEDER. UPON SEARCHING MANHOLES OIL WAS DISCOVERED. INVESTIGATION TO CONTINUE. "

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL 6/21/10 - changed Lead DEC to JMOCONNE (JOC) 11/18/16– Austin – This spill report is being transferred from Joe O'Connell to Kumar Patel - end 12/08/16-Hiralkumar Patel. the subject spill case was reported due to findings of oil in manhole while searching for leak in feeder line. no emis report in file. after discussing with DEC Austin, case closed due to nature of the

spill and lack of further information."

Material Information

OP Unit ID:	862632	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	511251	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller City:	UNKNOWN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	KEVIN MCARDLE
Contact Phone:	(212) 580-6763
Contact Ext:	
Latitude:	40.732566995
Longitude:	-73.952056612

38	***4 of9***	***SW***	***0.06 / 342.07***	***13.00 / 1***	***CON ED MANHOLE #71304 MCGINNIS/INDIA STREET BROOKLYN NY***	***NY SPILLS***

Spill No:	0405049	***UST Trust:***	False
Site ID:	301552	***Spill Date:***	08/09/2004 09:30:00 AM
DER Facility ID:	243684	***Received Date:***	08/09/2004 10:13:00 AM
CID:	444	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	01/19/2005 12:00:00 AM
Water Body:		***Create Date:***	08/09/2004 12:00:00 AM
Class:	C4	***Update Date:***	01/19/2005 01:38:16 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	SKARAKHA
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Responsible Party		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"1/2 GALLON OF OIL ON 40 GALLONS OF WATER: CLEAN UP IS PENDING TEST RESULTS: NO TO 5 QUESTIONS: CONED # 154779"

DEC Remark:

"e2mis no 154779 WALKER FOUND APPROX. 1/2 GAL. UNKNOWN OIL ON APPROX. 40 GAL. WATER IN MH-71304. SOURCE IS POSSIBLY AN OIL LINE FOR DEFUSION CHAMBER, BUT HE DOES NOT SEE IT LEAKING. SPILL APPEARS TO BE CONTAINED. SAMPLES FOR PCB AND OIL ID WERE TAKEN. CLEANUP TO BE ARRANGED BY TRANSMISSION OPERATIONS. Lab Sequence Number: 04-06277-001 - PCBs < 1 ppm Lab Sequence Number: 04-06299-001 - Analysis indicates the presence of a substance similar to a dielectric fluid. Removed/recovered liquid/solids____corp pump: 8/11/04 Used absorbents to remove residual fluids____ Yes, company forces 8/11/04 Name of Con Edison employee who inspected manhole

and determined that manhole was cleaned and that repairs were adequate - There is no evidence of any leakage on the repair or anywhere else in the manhole: Sam Walker Cleanup completed on: Date: 8/11/04 Time: 15:30"

Material Information

OP Unit ID:	887956	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	489045	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

OP Unit ID:	887956	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	489046	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	L	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	ERT DESK
Spiller Company:	CON ED MANHOLE #71304
Spiller Address:	MCGINNIS/INDIA STREET
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
38	5 of9	SW	0.06 / 342.07	13.00 / 1	MANHOLE 713204 MCGUINESS BLVD/ INDIA ST. BROOKLYN NY	NY SPILLS

Spill No:	0402792	***UST Trust:***	False
Site ID:	123847	***Spill Date:***	06/14/2004 11:40:00 AM
DER Facility ID:	107336	***Received Date:***	06/14/2004 12:55:00 PM
CID:	444	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	01/03/2005 12:00:00 AM
Water Body:		***Create Date:***	06/14/2004 12:00:00 AM
Class:	C4	***Update Date:***	01/03/2005 10:05:05 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	JHOCONNE
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Responsible Party		
Referred to:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source: Unknown
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"2000 GALLONS OF WATER(ON THIS), NO TO THE 5 QUESTIONS ABOUT WATERWAYS..."

DEC Remark:

"e2mis no. 153838: APPX 3 GALS OF UNK OIL ON APPX 2000 GALS OF WATER IN THE STRUCTURE. TOOK 2 LIQUID SAMPLES. LSN: 04-04613-001 - PCBs < 1 ppm LSN: 04-04614-001 - Analysis indicates the presence of a substance similar to a dielectric fluid. Clean Harbors power washed structure and removed 3200 gallons of material. Cleanup completed on 7/29/04. Cause of spill unknown."

Material Information

OP Unit ID:	886386	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	490406	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	3.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	ERT DESK
Spiller Company:	MANHOLE 713204
Spiller Address:	MCGUINESS BLVD/ INDIA ST.
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	ERT DESK
Contact Phone:	(212) 580-8383
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
38	6 of9	SW	0.06 / 342.07	13.00 / 1	INTERESCTION - MANHOLE #71304 MCGINNIS BLVD AND INDIA STREET BROOKLYN NY	NY SPILLS

Spill No:	0912432	**UST Trust:**	False
Site ID:	425320	**Spill Date:**	02/27/2010 03:45:00 PM
DER Facility ID:	374216	**Received Date:**	02/27/2010 04:26:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	03/12/2010 12:00:00 AM
Water Body:		**Create Date:**	02/27/2010 04:31:00 PM
Class:		**Update Date:**	08/24/2010 02:00:01 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	hrpatel
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Local Agency		
Referred to:			
Source:	Unknown		

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"35 gallons of unknown oil on 1,050 gallons of water; clean up is in progress; no waterways affected; manhole being cleaned; mixture is in tanker at this time"

DEC Remark:

"03/01/10-Hiralkumar Patel. 11:10 AM:- spoke with ERT. no update available yet. 03/10/10-Hiralkumar Patel. 3:54 PM:- spoke with Mike at ERT. no updates yet. Mike will send updated emis. 03/12/10-Hiralkumar Patel. received updated emis from ConEd. flange on blank off plate was leaking. leak stopped. cleanup completed. case closed. 8/24/10 - Austin - Spill contained and cleaned up by Con Ed - see Docs for EMIS report - spill closed - end"

Material Information

OP Unit ID:	1181043	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2175104	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	35.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	UNK
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	ERT
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

38	***7 of9***	***SW***	***0.06 / 342.07***	***13.00 / 1***	***CONSOLIDATED EDISON MH71304-MCGUINNESS BLVD &INDIA BROOKLYN NY***	***GEN MANIFEST***

RCRA ID:	NYP004123519	***Mailing State:***	NY
District Name:	CONSOLIDATED EDISON	***Mailing ZIP:***	10003
Contact Name:	FRANKLIN MURRAY	***Mailing ZIP Ext:***	
Business Phone No:	2124602808	***Mailing Country:***	USA
Mailing Street 1:	4 IRVING PLACE RM 828	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	NEW YORK	***Location County:***	KINGS

Manifest Information

Waste Code(s):

B007: (Wastes containing polychlorinated biphenyls (PCBs)) Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Waste Amounts By Year:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

2004: 194 Kilograms; 205 Kilograms

---

38 | ***8 of9*** | ***SW*** | ***0.06 / 342.07*** | ***13.00 / 1*** | ***NYSDOT MCGUINESS BLVD & INDIA ST BROOKLYN NY*** | ***GEN MANIFEST***

RCRA ID:	NYR000053298	***Mailing State:***	NY
District Name:	NYSDOT	***Mailing ZIP:***	11101
Contact Name:	JOCELYN DAMIS	***Mailing ZIP Ext:***	
Business Phone No:	2154223175	***Mailing Country:***	USA
Mailing Street 1:	30-30 THOMPSON AVE	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	LONG ISLAND CITY	***Location County:***	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1998: 20 Cubic yards; 20 Cubic yards; 20 Cubic yards; 20 Tons; 20 Tons; 20 Tons; 20 Tons; 20 Tons; 20 Cubic yards; 20 Cubic yards; 20 Tons; 20 Cubic yards
1999: 23 Tons; 24 Tons; 23 Tons; 24 Tons; 23 Tons; 24 Tons; 23 Tons; 23 Tons

---

38 | ***9 of9*** | ***SW*** | ***0.06 / 342.07*** | ***13.00 / 1*** | ***CONSOLIDATED EDISON MCGUINNESS & INDIA BROOKLYN NY 11201*** | ***GEN MANIFEST***

RCRA ID:	NYP004134615	***Mailing State:***	NY
District Name:	CONSOLIDATED EDISON	***Mailing ZIP:***	10003
Contact Name:	FRANKLIN MURRAY	***Mailing ZIP Ext:***	
Business Phone No:	2124602808	***Mailing Country:***	USA
Mailing Street 1:	4 IRVING PLACE RM 828	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	NEW YORK	***Location County:***	KINGS

Manifest Information

Waste Code(s):

B007: (Wastes containing polychlorinated biphenyls (PCBs)) Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Waste Amounts By Year:

2005: 157 Kilograms; 203 Kilograms

---

39 | ***1 of4*** | ***SW*** | ***0.07 / 350.13*** | ***13.06 / 1*** | ***FAISAL AUTO CARE CENTER INC. 315 MCGUINNESS BLVD Brooklyn NY 11222*** | ***AST***

Site ID:	25838	***Expiry:***	02/26/2004
Site Status:	Active	***County:***	Kings
Program No:	2-603947	***UTM X:***	588472.12669
Program Type Code:	PBS	***UTM Y:***	4509652.58303
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Other		

Tank Information

Prog No:	2-603947	***UDC Ind:***	1
Tank ID:	56124	***Red Tag Start Date:***	
Tank No:	001	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	04/01/1995	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	250	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: waste oil/used oil
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: H99
Code Name: Other
Type: Tank Leak Detection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: I99
Code Name: Other
Type: Overfill

Equipment: J02
Code Name: Suction Dispenser

Type: Dispenser

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Affiliation Information

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: FAISAL AUTO CARE CENTER INC.
Contact Title:
Contact Name: FAISAL IMRAM
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 349-2322
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: NISER BUTT
Contact Title:
Contact Name: NISER BUTT
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (917) 226-4427
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: NISER BUTT
Contact Title:
Contact Name:
Address1: 315 MCGUINNESS BLVD.
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 472-0059
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: FAISAL AUTO CARE CENTER INC.
Contact Title:
Contact Name: FAISAL IMRAN
Address1: 315 MCGUINNESS BLVD.
Address2: 315 MCGUINNESS BLVD.
City: BROOKLYN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 349-2322
Phone Ext:
Email:
Fax:

---

39 | **2 of4** | **SW** | **0.07 / 350.13** | **13.06 / 1** | **GETTY 58088**
315 MCGUINNESS BLVD
Brooklyn NY 11222 | **UST**

Site ID: 4261
Site Status: Unregulated/Closed
Program No: 2-146595
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Retail Gasoline Sales

Expiry: N/A
County: Kings
UTM X: 588516.22206
UTM Y: 4509618.33231

Tank Information

Prog No: 2-146595
Tank ID: 28256
Tank No: 053
Tank Status: 3
Tank Status Desc: Closed - Removed
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 08/01/1956
Close Date: 06/01/1992
Tk Out of Serv Dt:
Capacity (Gal): 550
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test: 07/01/1991
Tank Next Test Due:
Test Method: ZZ
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I00
Code Name: None
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Tank Information

Prog No:	2-146595	**UDC Ind:**	1
Tank ID:	28259	**Red Tag Start Date:**	
Tank No:	008	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	07/01/1991
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	ZZ
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	08/01/1956	**Next Test:**	
Close Date:	06/01/1992	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Tank Information

Prog No:	2-146595	***UDC Ind:***	1
Tank ID:	28254	***Red Tag Start Date:***	
Tank No:	003	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	07/01/1992
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	00
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	08/01/1956	***Next Test:***	
Close Date:	06/01/1992	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: D02
Code Name: Galvanized Steel

Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: F00
Code Name: None
Type: Pipe External Protection

Tank Information

Prog No:	2-146595	***UDC Ind:***	1
Tank ID:	28257	***Red Tag Start Date:***	
Tank No:	006	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	07/01/1991
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	ZZ
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	08/01/1956	***Next Test:***	
Close Date:	06/01/1992	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: I00
Code Name: None
Type: Overfill

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Tank Information

Prog No:	2-146595	***UDC Ind:***	1
Tank ID:	28258	***Red Tag Start Date:***	
Tank No:	073	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	07/01/1991
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	ZZ
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	08/01/1956	***Next Test:***	
Close Date:	06/01/1992	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: I00
Code Name: None
Type: Overfill

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Tank Information

Prog No:	2-146595	***UDC Ind:***	1
Tank ID:	28253	***Red Tag Start Date:***	
Tank No:	002	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	07/01/1991
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	ZZ
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	08/01/1956	***Next Test:***	
Close Date:	06/01/1992	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:

Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I00
Code Name: None
Type: Overfill

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Tank Information

Prog No:	2-146595	***UDC Ind:***	1
Tank ID:	28252	***Red Tag Start Date:***	
Tank No:	001	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	07/01/1991
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	ZZ
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	08/01/1956	***Next Test:***	
Close Date:	06/01/1992	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986

Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: I00
Code Name: None
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Tank Information

Prog No:	2-146595	***UDC Ind:***	1
Tank ID:	28261	***Red Tag Start Date:***	
Tank No:	010	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	07/01/1991
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	ZZ
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	08/01/1956	***Next Test:***	
Close Date:	06/01/1992	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022

Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Tank Information

Prog No:	2-146595	***UDC Ind:***	1
Tank ID:	28260	***Red Tag Start Date:***	
Tank No:	009	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	07/01/1991
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	ZZ
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	08/01/1956	***Next Test:***	

Close Date:	06/01/1992	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: B00
Code Name: None
Type: Tank External Protection

Tank Information

Prog No:	2-146595	**UDC Ind:**	1
Tank ID:	28262	**Red Tag Start Date:**	
Tank No:	011	**Red Tag End Date:**	

Tank Status:	3	**Tank Last Test:**	07/01/1991
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	ZZ
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	08/01/1956	**Next Test:**	
Close Date:	06/01/1992	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: I00
Code Name: None
Type: Overfill

Tank Information

Prog No:	2-146595	**UDC Ind:**	1
Tank ID:	28255	**Red Tag Start Date:**	

Tank No:	043	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	07/01/1991
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	ZZ
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	08/01/1956	**Next Test:**	
Close Date:	06/01/1992	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: I00
Code Name: None
Type: Overfill

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Affiliation Information

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: GETTY #58088
Contact Title:
Contact Name: JUAN GONZALEZ
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-9724
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: POWER TEST REALTY COMPANY LIMITED PARTNERSHIP
Contact Title:
Contact Name:
Address1: 125 JERICHO TURNPIKE
Address2:
City: JERICHO
State: NY
Zip Code: 11753
Country Code: 001
Phone: (516) 576-9500
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: GETYY PETROLEUM CORP
Contact Title:
Contact Name:
Address1: 3023 GREEN POINT AVENUE
Address2:
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 729-6500
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: POWER TEST REALTY COMPANY LIMITED PARTNERSHIP
Contact Title:
Contact Name: EDWARD WALDRON
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 729-6500
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
39	3 of4	SW	0.07 / 350.13	13.06 / 1	VACANT AREA/FORMER GETTY 305-319 MCGUINNESS BLVD BROOKLYN NY	NY SPILLS

Spill No:	0400807	**UST Trust:**	False
Site ID:	210812	**Spill Date:**	04/23/2004 11:00:00 AM
DER Facility ID:	174780	**Received Date:**	04/23/2004 01:07:00 PM
CID:	406	**CAC Date:**	08/02/2005 12:00:00 AM
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	04/29/2014 12:00:00 AM
Water Body:		**Create Date:**	04/23/2004 12:00:00 AM
Class:	C4	**Update Date:**	05/06/2014 02:52:19 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	AAOBLIGA
REM Phase:	0	**After Hours:**	False

County: Kings
Contributing Factor: Unknown
Reported by: Other
Referred to: SENT STIP TO NEW OWNER 4/23, DUE 5/21
Source: Unknown
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"saw no tanks but did do soil samples and they came back over the DEC limit for contamination. No clean up yet need DEC to help with the clean up decisions. They aren't sure where to start or how to go about doing it."

DEC Remark:

"send Cont. Soil Ltr 5/21/04 Assigned to Foley. Rommel 5/21/04 Contaminated soil letter sent by Sangesland on 5/4/04. Rommel received call from Rachel Ataman (631-462-5866) from Hydrotech who said we should have received report. Requested she resend. 5/21/04 Rachel Ataman, Hydrotech, did phase 1, phase 2 and delineation work. Will be sending reports. Working on Remediation Plan. 5/25/04 Received Phase II site assessment (Hydrotech, 4/20/04) and supplemental Phase II letter report(Hydrotech, 5/7/04). Will be sending remediation work plan when it is complete. 6/14/04 Received Remedial Action Plan prepared 6/9/04 by Hydrotech. 7/1/04 Phase II and supplemental site assessment reviewed. VOCs identified in soils around the concrete pad and within the drywells. No levels of any VOCs or SVOCs above TAGM were detected around the floor drain or hydraulic lifts. 7/2/04 RAP reviewed and conditionally approved. Requested two additional well locations, one south(area of SP-11) and one west(area of MW-1) of concrete patch. 7/7/04 Spoke to R. Ataman, Hydrotech. Excavation to begin Thursday 7/8/04. 1/5/05 Spoke to R. Ataman, Hydrotech. Will send groundwater investigation report this week. To also check with owner on property fencing. 1/19/05 Spoke to R. Ataman, Hydrotech. Will be sending groundwater results out tomorrow. 1/21/05 Received Quarterly Status Report (Sept-Nov 2004) from HydroTech. It does not appear from the report that the Remedial Action(as approved on 7/2/04) was implemented. Total BTEX in groundwater ranged from 48ppb(MW-1) to 22590ppb(MW-4). MTBE ranged from ND(MW-1) to 510ppb(MW-3). See spill #9111459, PBS 2-146595. Previously operated as a Getty station(as 315 McGuinness). 3/25/05 STIP issued(certified) and due back on 4/18/05. 4/14/05 STIP returned undeliverable. 4/29/05 Requested that ECO Deo Read III attempt to deliver stip to 390 Berry St. 5/18/05 Site visit. Spoke to Bill, Project Manager from Superior Construction (cell 347-242-1268). Obtained owner info: Isaac Hagar, 217 Havermayer St, Brooklyn NY 11211(718-599-8600). Requested ECO Lakeman attempt to deliver stip to 217 Havemayer Street. Stip due 6/9/05. 5/23/05 Spoke to M. Robbins, Hydro Tech. They are still consultant for Mr. Isaac Hagar. Faxed him a copy of 5/19/05 letter. He will coordinate with Mr. Hagar. 5/24/05 ECO Lakeman attempted delivery at 217 Havemayer and was unable to locate Mr. Hagar. Requested M. Robbins of Hydrotech forward the letter to Mr. Hagar. 5/26/05 Mailed letter to 217 Havemayer by certified mail(7004 1160 0001 8318 4170). 5/27/05 Received Remedial Action Report (HydroTech, 9/10/03) and Quarterly Status Report for 12/04-2/05(HydroTech, 4/11/05). 840 tons of petroleum contaminated soil was excavated in the central and northern portions of the site. The excavation was approximately 65' wide, 36' long, and was extended below the water table. Groundwater was encountered at 4-6'bgs. A total of 1500lbs of ORC was injected into the excavation sidewalls and bottom. Endpoint samples taken from area of excavation ranged from ND to 781040ppb(EP-5) total VOCs. Appears that most of the soil contamination is along the north and eastern sides of excavation(along Huron and McGuinness). No bottom samples taken. Groundwater samples collected on 2/16/05 from six on-site wells. Total VOCs ranged from 13ppb (MW-4) to 12906ppb(MW-6). 6/1/05 Spoke to ECO Chris Valenty. He issued stipulation letter to Mr. Isaac Hagar on 5/20/05. 6/16/05 Email from M. Robbins, Hydrotech. He met with Mr. Hagar who signed Hydrotech's proposal to perform the work described in DEC's most recent letter. Mr. Hagar has not yet paid Hydrotech. M. Robbins gave the stip to Mr. Hagar and told him to sign it. He said he would review it with his lawyer and give it back to M. Robbins next week. 7/7/05 Email from M. Robbins- Hydrotech will be starting field work next week. They will need a letter to obtain sidewalk permits. 8/8/05 Email from R. Ataman, HydroTech. Will install MW south of MW-7. 8/9/05 STIP effective. Investigation summary report due 10/8/05. RAP due 12/7/05. 9/14/05 Received vapor barrier/ventilation system design from HydroTech. 12/9/05 Received report for installation of 6 monitoring wells and 2 samples taken from beneath the building foundation. Only contaminated soil encountered above RSCO, during well installation, was for benzene (166ppb) at SP-6A, 6-8'bgs. Concentrations of VOCs in groundwater were as high as 77724ppb(MW-3) and 51756ppb(MW-2), in the sidewalk to the north, and also in the sidewalk along McGuinness Blvd in MW-5 at 57074ppb. Lower levels of VOCs were detected in the northwest corner of the site, in MW-1, at 7674ppb, and to the east, in MW-4 and MW-6, at 8366ppb and 14152ppb respectively. In summary, 841 tons of contaminated soil was removed. ORC was injected into the sidewalls and bottom of the tank excavation as a slurry. No VOCs were identified in the two samples collected from excavation. Benzene was the only contaminant detected in soil, in the boring east of the site. HydroTech expects that the elevated concentrations in MWs crossgradient and downgradient of the site will decrease over time due to source removal and ORC injection. Total VOC concentrations decreased from 22710ppb(8/04) to 13ppb(2/05) in former MW-4 and from 4355ppb(8/04) to 1950ppb(2/05) in former MW-2. 12/21/05 Spoke to Rachel Ataman and followed up with email. In order to fully delineate and get a better estimate of the contaminant plume, additional monitoring wells are warranted. Based upon those results and the next quarterly round, a remedial action plan can be submitted. Requested they submit a plan for the additional investigation prior to beginning any field work. 2/27/06 Spoke to R. Ataman, Hyrotech. Report for supplemental investigation condcuted in Jan 2006 submitted via

email. Monitoring well MW-8 was installed on the sidewalk along the north side of Huron Street, adjacent to an Exxon gasoline station. Monitoring wells MW-10 through MW-12 were installed into the median in the middle of McGuinness Blvd. MW-10 is located to the south of Huron Street. Monitoring well MW-11 and MW-12 are located to the north of Huron Street downgradient of the Exxon Station. The depth to water ranges from 5.90 feet in MW-4 to 7.26 feet in MW-11. 3/20/06 Spoke to Caroline Cadalso, Advanced Cleanup Technologies(631-293-4992 X21). They are the consultant for Norfolk Bank, the lender for the owner. Inquired about the status of the spill. 4/11/06 Received supplemental RAP for ORC injection prepared by HydroTech. The Area of Concern is the dissolved phase VOC plume present beneath the northern portion of the site and approximately 50 feet downgradient of the site.The total VOCs are at 8,366ppb in MW-4(located on the northeast corner of the Site) to 77,724 ppb in MW-3(north of the Site on the southern sidewalk of Huron Street). Propose to inject 810 pounds of ORC powder and 874 gallons of water; 20 pounds of ORC powder and 22 gallons of water per hole. Following the injection of the ORC slurry, a groundwater monitoring program will be implemented conducting gauging and sampling on a monthly basis. Samples will be obtained from each well and analyzed for dissolved oygen, dissolved iron and manganese, Redox potential and pH. Additional samples will be obtained from each well on a quarterly basis and analyzed for BTEX and MTBE. 5/3/06 Provided comments on RAP via email to R. Ataman, HydroTech. Requested more information regarding the length of the plume, contaminant mass sorbed to the soil, hydraulic conductivity, radius of influence, and groundwater data used to calculate oxygen demand. I also requested looking into placement of wells outside of the treatment zone to determine the effectiveness of the injections and to ensure groundwater is being treated and not just migrating. 6/13/06: Sun approves Supplemtal Remedial Action PLan (RAP) dated April 10, 2006 and letter report dated June 2, 2006 submitted by Hydro Tech. The approved RAP is to inject 810 pounds of ORC into 40 injection points. The injection points will be situated over 3 rows, each row will have 15 points. The points will be 5 feet apart and the rows will be 17 feet apart, THe rows will be situated on site and along the sidewalk of McGuinness Blvd and Huron Street. (Sun) 11/14/06-Sun: Kris Almskog (631-589-6353)of P.W. Grosser Consulting is the new consultant for the RP. He informed DEC today that he recently installed some monitoring wells inside the building and performed quarterly monitoring and sampling of the groundwater. He will submit a revised remedial action plan to RP and DEC for approval. (Sun) 01/23/07-Sun-Sun approves the Remedial Action Work Plan (RAWP), submitted by P.W. Grosser Consulting, Inc., dated January 2007 for this site and its addendum to the above RAWP dated January 17, 2007. The proposed remedial plan includes a Groundwater Monitoring Plan to track groundwater quality and natural attenuation of petroleum impact at the site. A vapor barrier, designed to prevent the potential infiltration of VOCs into the new structure, will be installed beneath the concrete slab floor in the basement of the building. A Sub-slab depressurization/venting system, consisting of two sets, of two rings of 4 inch HDPE corrugated interior pipe will be individually piped to the roof. The addendum to the proposed RAP dated January 16, 2007 proposes to replace the original vapor barrier material GSE 15-mil with a Grace Construction Product "Preprufe 300R".The Department approves the RAWP and its addendum with the following conditions: 1.Sub-Slab Ventilating System Sampling: A gas sample, from each of two sets of the sub-slab venting system emissions shall be collected within the first week of start-up of the sub-slab venting system. The effluent air sample shall be collected using SUMMA canisters and analyzed for VOC parameters in accordance with TO-15. VOC concentrations shall be compared to the stipulation agreement to determine if the addition of a granular activated carbon (GAC) system will be required. If concentrations in the stipulation agreement are exceeded, further action (e.g. confirmatory samples, GAC system installation) will be taken. 2.Venting Fan Inspection: The weatherproof radon-type fan and warning light/beacon shall be tested and inspected on an annual basis following start-up of the sub-slab venting system. The inspection shall be performed by a licensed HVAC professional or engineer to ensure continued proper operation. An inspection/service sign-off log shall be kept in fan housing as a record of the annual inspections. 3. Survey of all Monitoring Wells: All monitoring well shall be surveyed in order to determine groundwater flow direction at the site. 4.Effectiveness of Monitored Natural Attenuation (MNA): It must be demonstrated that groundwater contaminant concentrations are decreasing to GWQS in a reasonable time frame based on MNA approach. Upon reviewing analytical data, the Department may request further investigation/remedial action. Per Corrective Action Plan (RAP) attached to the Stipulation Agreement, within 45 days of the Department's approval of the RAP, Respondent shall implement the approved RAP. The Department requires five days advanced notice of any remedial work at the site. (Sun) 02/19/08:sun- Sun received the following email from Matin Meriwether of PW Grosser, (336-540-0093): I spoke to Regenesis today. They're making some changes to the original treatment area for the chemical injections at 305 McGuinness Blvd., so we're waiting on them to finalize our RAWP. They promised to have their revised proposal to me by the end of the week. Upon receiving it, I'll complete the RAWP and get it to you, along with the Phase II ESA, as soon as possible. (Sun) 3/20/08:Sun- Sun sent the followinh email to Matin Meriwether of PW Grosser, Hi, Mr. Meriwether, Please give an update on the status of the above referenced project, including Chemical Injection and start-up of Sub-slab Ventilation System. (Sun) 3/25/08-Sun- Sun receievd the Subsurface Investigation/Monitoring Well Instsllation Report, dated January 18, 2008, fro Martin Meriwether (Phone # 336-540-0094)of P.W. Grosser. 3/25/08-Sun: Sun sent the following email to Martin Meriwether of P. W. Grosser: I concur with your recommendation that TW-06 either be repaired or replaced prior to the completion of additional groundwater monitoring and sampling rounds. Upon replacing or repairing TW-06, all site monitoring wells should be surveyed to facilitate the determination of groundwater flow direction beneath the subject site.I am looking forward to witnessing the start-up of vapor recovery system within the next month. Please keep me posted. (Sun) 04/24/08-Sun:Sun sent the following email to Martin Meriwether of PW Grosser (336-540-0093) Dear Mr. Meriwether: It has been almost a month since our correspondence on 3/25/08, and I am still awaiting your response regarding the ORC injection. What is the problem in delaying the injection? and when will the soil vapor recovery system be turned on? Your immediate response to this email is urgently request. (Sun) 05/02/08-Sun: Sun visited the site to witness the testing of Sub-Slab Depressurization System, performed by Kris Almskog of P.W. Grosser Consulting (PWGC). PWGC will submit the ORC Injection Plan next Monday, 5/5/08 to DEC for review and approval. (Sun) 05/06/08-Sun-A DEC recived a Remedial Action Work Plan-Chemical Injection, prepared by PW Grosser Consulting (PWGC), dated May 2008. (Sun) 05/13/08-Sun: Sun approved the Remedial Action Plan for Chemical Injection with thr following conditions: 1)On Section 3.2, under the heading of REGEN-OX and ORC-A Application, it states that a total of 720 pounds of Regen-OX and 300 pounds of ORC-A will be applied during the initial treatment. Please submit the Regenesis documentation/calculation to DEC to show how the above numbers were derived; 2)It is expected that groundwater contaminant concentrations will decrease as a result of the Chemical Oxidant Injections and ORC-Advanced injections. It must be demonstrated that groundwater contaminant concentrations are decreasing to Groundwater Quality Standards in a reasonable time frame. Upon reviewing analytical data, the Department may request further investigation/remedial action. With the understanding that the above noted modifications are agreed to, the RAWP is hereby approved. Per Corrective Action Plan (RAP) attached to the Stipulation Agreement, within 45 days of the Department's approval of the RAP, Respondent shall implement the approved RAP. (Sun) 07/09/08-Sun: Sun sent the following email to the Consultant, Kris, In my letter to you and the owner (RP) date May 13, 2008, I requested that the RAP be implement within 45 days of the approved RAP. Now, please give me an update on the status of RAP implementation.Your immediately response is urgently requested. (Sun) 07-29-08: Transfered from Sun to Tibbe. 11/12/10 - spill re-assigned from Tibbe to Joe O'Connell. 1/10/12 - Obligado - Spill reassigned from O'Connell to Obligado 1/11/12 - Obligado - I spoke to Kris Almskog at PW Grosser. I told him I would review the most recent November 2011 report and the file and contact him. 4/23/12 - Obligado - I sent a STIP to the new owner: Ronel Ben-Dov 305 McGuiness Blvd LLC 254 Woodland Street Tenafly, NJ 07670 Email: Rbendov@dabbyinvestments.com 4/24/12 - Obligado - I received voice mail from Mr. Ben Dov confirming that he received the STIP via email and inquiring about it. 4/25/12 - Obligado - I called Mr. Ben Dov. He did not answer. The voicemail system was not working so I did not leave a message. I also recieved a call from Rich Levato of Biorem. He said Mr. Bendov is his client. He inquired about the letter I sent and we discussed the letter and Department requirements. 1/2/14 - Obligado - I emailed MR. Ben Dov again to try and resolve this open spill case. I asked him to call back the DEC. 1/21/14 - Obligado - Mr. Bendov submits Groundwater Sampling report, dated October 4, 2012. Groundwater samples were collected on June 25, 2012. Maximum total VOCs were found TW14. total BTEX at TW14 was 1040 ug/L.

Total VOCs were 1,643 ug/L. This well is underneath the sidewalk in front of the building. TW-03 had 129.3 ug/L total VOCs and TW-4 had 111.8 ug/L total VOCs. Most other wells were at or close to groundwater standards for most compounds. Petroleum compounds appear to be continuing to attenuate naturally following remedial excavation and ORC application. 2/25/14 - Obligado - I met Mr. Bendov at a site visit. I did a walk through of the the utility room in the basement, the garage, and the lobby. No petroleum odors evident. I inspected the SSDS system on the roof. Both SSDS blowers were operational. Mr. Bendov shut off the blowers, which set off an alarm, demonstrating that the system alarms were functional. It appears that the SSDS system is functioning as designed. I asked Mr. Bendov to provide the OMM checklist for the SSDS blower and a copy of the SSDS system designs for our records. 3/13/14 - Obligado - I discussed this site and the SSDS system with DOH Michael Hughes. He recommended the following: 1) Take a sample from the output of the SSDS to see what levels of petroleum VOCs may still be present. 2) If levels are low shut system down. (with DOH assisting review) 3)If levels still high then lets discuss about pressure field extension or shut down with olfactory monitoring, etc. 4/23/14 - Obligado - I received the vapor results from Mr. Bendov and forwarded the results to the DOH. 4/25/14 - Obligado - DOH reviewed the vapor sampling results from each leg. According to the DOH Michael Hughes it is my opinion that the levels measured in the effluent from the SSDS from either location would not be a potential soil vapor intrusion concern . Michael Hughes recommended the system could be shut down and to monitor for odors for a year prior to dismantling. 5/29/14 - Obligado - I forwarded the DOH comments to MR. Bendov. This spill is closed due to: 1) All sources of contamination removed. 2) Groundwater monitoring show VOC plume is attenuating. Limited impacts remain in only one well beneath the sidewalk with total VOCs at 1,643 ug/L in TW14. TW-03 had 129.3 ug/L total VOCs and TW-4 had 111.8 ug/L total VOCs. Most other wells were at or close to groundwater standards for most compounds. Petroleum compounds appear to be continuing to attenuate naturally following remedial excavation and ORC application. 3) Vapor Barrier and SSDS was installed under the building and operated for 5 years. DOH confirmed that based on the SSDS effluent, soil vapor intrusion does not appear to be a concern 4) Additional remediation is not feasible due to the site redevelopment and limited area of impact under sidewalk. 5) DEC inspection of the the utility room in the basement, the garage, and the lobby. No petroleum odors evident. 6) This spill no longer appears to be a threat to human health or the environment."

Material Information

OP Unit ID:	882839	***Med Ind Air:***	False
OU:	01	***Med GW:***	True
Material ID:	492044	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	L	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	True
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

OP Unit ID:	882839	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2106582	***Med SW:***	False
CAS No:	01634044	***Med DW:***	False
Material Family:	Hazardous Material	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	True
Med Air:	False		
Material Code:	1213A		
Material Name:	MTBE (methyl-tert-butyl ether)		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	RACHEL ATAMAN
Contact Phone:	(631) 462-5866
Contact Ext:	
Latitude:	40.732358410
Longitude:	-73.952138670

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
39	4 of4	SW	0.07 / 350.13	13.06 / 1	315 MCGUINNESS BLVD 315 MCGUINNESS BLVD BROOKLYN NY	NY SPILLS

Spill No:	9111459	**UST Trust:**	False
Site ID:	311934	**Spill Date:**	01/13/1992 12:00:00 PM
DER Facility ID:	251625	**Received Date:**	02/06/1992 11:11:00 AM
CID:		**CAC Date:**	08/19/1992 12:00:00 AM
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	08/19/1992 12:00:00 AM
Water Body:		**Create Date:**	02/12/1992 12:00:00 AM
Class:	C3	**Update Date:**	03/23/2005 03:17:20 PM
Meets Std:	True	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SULLIVAN
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Gasoline Station or other PBS Facility		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"SOIL BORING SHOWED PRODUCT, SHEEN DETECTED IN OTHER WELL."

DEC Remark:

"3/23/05 See spill file #0400807. Tank closure report submitted by EMS in 8/02. NFA letter issued by K. O'Dowd on 8/19/92.(KMF)"

Material Information

OP Unit ID:	965186	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	416495	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	L	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	TANNESE REALTY
Spiller Address:	55 JEFFREY PLACE
Spiller City:	MANHASSET
Spiller State:	NY
Spiller Zip:	11040
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.732746360
Longitude:	-73.952203640

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
40	1 of1	E	0.07 / 354.25	10.70 / -1	CON EDISON - MANHOLE 4307 PROVOST ST BROOKLYN NY 11222	RCRA LQG

EPA Handler ID:	NYP004290326

Gen Status Universe:	Large Quantity Generator
Contact Name:	DENNIS HUACON
Contact Address:	4 , IRVING PLACE, 15TH FL NE , , NEW YORK , NY, 10003 , US
Contact Phone No and Ext:	212-460-2757
Contact Email:	HUACOND@CONED.COM
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20140327
Location Latitude:	40.733685
Location Longitude:	-73.94972
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20130301
Handler Name:	CON EDISON MANHOLE: 4307
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Emergency

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20130401
Handler Name:	CON EDISON MANHOLE: 4307
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20140327

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Handler Name: CON EDISON - MANHOLE 4307
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	4
Type:	Private	**Street 1:**	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20130301	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003

Owner/Operator Ind:	Current Owner	**Street No:**	4
Type:	Private	**Street 1:**	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20130301	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003

Historical Handler Details

Receive Dt: 20130401
Generator Code Description: Not a Generator, Verified
Handler Name: CON EDISON MANHOLE: 4307

Receive Dt: 20130301
Generator Code Description: Very Small Quantity Generator
Handler Name: CON EDISON MANHOLE: 4307

---

41 | **1 of1** | **NE** | **0.07 / 355.29** | **11.05 / -1** | **266 FREEMAN ST/BROOKLYN**
266 FREEMAN STREET
NEW YORK CITY NY | **NY SPILLS**

Spill No:	8905039	**UST Trust:**	False
Site ID:	62941	**Spill Date:**	08/21/1989 12:48:00 PM
DER Facility ID:	60912	**Received Date:**	08/21/1989 01:03:00 PM
CID:		**CAC Date:**	12/08/1992 12:00:00 AM
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	12/08/1992 12:00:00 AM
Water Body:		**Create Date:**	12/07/1989 12:00:00 AM
Class:	B3	**Update Date:**	12/10/1992 12:00:00 AM
Meets Std:	True	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SIGONA
REM Phase:	0	**After Hours:**	False

County: Kings
Contributing Factor: Human Error
Reported by: Fire Department
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"1K TANK WITH #2 FUEL OIL FELL OFF FORK LIFT, TRIED TO FLUSH SPILL INTOSEWER, DEC TO INVESTIGATE."

DEC Remark:

""

Material Information

OP Unit ID:	930287	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	445475	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	True
Quantity:	250.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		

Spiller Information

Spiller Name:	
Spiller Company:	OK DEMOLITION
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.734819000
Longitude:	-73.950407000

42	***1 of1***	***E***	***0.07 / 357.11***	***10.91 / -1***	***CON EDISON PROVOST ST & HURON SB4306 BROOKLYN NY 11201***	***GEN MANIFEST***

RCRA ID:	NYP004699773	***Mailing State:***	NY
District Name:	CON EDISON	***Mailing ZIP:***	10003
Contact Name:	CON EDISON	***Mailing ZIP Ext:***	
Business Phone No:		***Mailing Country:***	USA
Mailing Street 1:	4 IRVING PL	***Location ZIP Ext:***	
Mailing Street 2:	15TH FL	***Location Country:***	USA
Mailing City:	NEW YORK	***Location County:***	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2014: 1500 Pounds

43	***1 of2***	***SSW***	***0.07 / 364.12***	***12.87 / 1***	***S.R. AUTO SERVICE, INC. 300 MCGUINNESS BOULEVARD Brooklyn NY 11222***	***AST***

Site ID:	25900	***Expiry:***	03/25/2029
Site Status:	Active	***County:***	Kings

Program No:	2-604011	**UTM X:**	588507.13443
Program Type Code:	PBS	**UTM Y:**	4509598.66443
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Other		

Tank Information

Prog No:	2-604011	**UDC Ind:**	1
Tank ID:	56388	**Red Tag Start Date:**	
Tank No:	102	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	02/01/1999	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	200	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: IHTESHAM RANA
Tank Owner Address: 239 JAVA ST BROOKLYN, NY. 11222

Material Information

Material Name: used oil (heating, on-site consumption)
Percent: 100.00

Equipment Information

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Tank Information

Prog No:	2-604011	**UDC Ind:**	1
Tank ID:	56387	**Red Tag Start Date:**	
Tank No:	101	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	02/01/1999	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	200	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: IHTESHAM RANA
Tank Owner Address: 239 JAVA ST BROOKLYN, NY. 11222

Material Information

Material Name: used oil (heating, on-site consumption)
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: G01

Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Affiliation Information

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: S.R. AUTO SERVICE, INC.
Contact Title:
Contact Name: MUHAMMAD RANA
Address1: 300 MCGUINNESS BOULEVARD
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 349-9742
Phone Ext:
Email: SRANA25@AOL.COM
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: IHTESHAM RANA
Contact Title:
Contact Name: IHTESHAM RANA
Address1: 300 McGuinness Blvd
Address2:
City: Brooklyn
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 349-9742
Phone Ext:
Email: srana25@aol.com
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: IHTESHAM I. RANA
Contact Title:
Contact Name: MUHAMMAD RANA
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (201) 653-7436
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: DAVID AND YAHUNDA YALOZ
Contact Title: PRESIDENT
Contact Name: IHTESHAM RANA
Address1: 239 JAVA ST
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone: (718) 389-1131
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
43	2 of2	SSW	0.07 / 364.12	12.87 / 1	AUTO BODY SHOP 300 MCGUINNES BLVD BROOKLYN NY	NY SPILLS

Spill No: 9613105
Site ID: 185700
DER Facility ID: 155320
CID: 311
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C3
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Human Error
Reported by: Citizen
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 02/05/1997 09:00:00 AM
Received Date: 02/05/1997 11:00:00 AM
CAC Date:
Insp Date:
Close Date: 03/17/2016 12:00:00 AM
Create Date: 02/05/1997 12:00:00 AM
Update Date: 03/17/2016 12:54:59 PM
DEC Region: 2
Lead DEC: RMPIPER
After Hours: False

Caller Remark:

"Caller states the body shop owners are pouring used motor oil into a tank that is leaking and has been leaking and no action is taken to correct the problem. caller was an elderly male calling from a pay phone. call back number and name can not be verified."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN 06/16/06: This spill is transferred from Mike Mulqueen to Mr. Koon Tang. 10/13/10 - Austin - Spill being transfered from Tang to Region 2 Spills staff - end 2/19/16- DEC Piper sent info request to Maria and Carmella Verna 61-08 228th St Bayside, NY 11364 David and Yahuda Yaloz 239 Java St Brooklyn, NY 11222 Sham Rana S.R. Auto Service Inc. 3/17/16- DEC Piper- Based on information provided, this spill is administratively closed. Housekeeping issue, 20 years old."

Material Information

OP Unit ID: 1044637
OU: 01
Material ID: 561114
CAS No:
Material Family: Petroleum
Quantity: .00
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0001A
Material Name: #2 fuel oil

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: True
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: UNKNOWN
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: UNKNOWN
Contact Phone: (000) 000-0000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Ext:
Latitude: 40.732454700
Longitude: -73.951829260

---

44 | **1 of1** | **SSE** | **0.07 / 373.23** | **12.20 / 0** | **TWO GAL GREEN SUBSTANCE IN SB 7529 222 INDIA STREET BROOKLYN NY** | **NY SPILLS**

Spill No: 0710905
Site ID: 392280
DER Facility ID: 341877
CID: 444
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C4
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Other
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 01/15/2008 12:25:00 PM
Received Date: 01/15/2008 12:34:00 PM
CAC Date:
Insp Date:
Close Date: 03/20/2008 10:32:00 AM
Create Date: 01/15/2008 12:46:00 PM
Update Date: 03/20/2008 10:33:04 AM
DEC Region: 2
Lead DEC: gdbreen
After Hours: False

Caller Remark:

"green substance leaking from a dumpster: pending testing as to clean up. 209485"

DEC Remark:

"03/20/08 - See eDocs for Con Ed report detailing cleanup and closure. 209485. see eDocs"

Material Information

OP Unit ID: 1149298
OU: 01
Material ID: 2139818
CAS No:
Material Family: Other
Quantity: 2.00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0064A
Material Name: unknown material

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: ERTSDESK
Spiller Company: CON EDISON SB # 7529
Spiller Address:
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: ERTSDESK
Contact Phone: (212) 580-8383
Contact Ext:
Latitude: 40.732616000
Longitude: -73.950806000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
45	1 of1	ENE	0.07 / 379.05	10.52 / -2	GREEN ST & PROVOST/BKLYN GREEN ST & PROVOST BROOKLYN NY	NY SPILLS

Spill No:	9011235	**UST Trust:**	False
Site ID:	143052	**Spill Date:**	01/23/1991 02:00:00 PM
DER Facility ID:	122034	**Received Date:**	01/23/1991 02:01:00 PM
CID:		**CAC Date:**	02/25/1991 12:00:00 AM
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	02/25/1991 12:00:00 AM
Water Body:		**Create Date:**	02/28/1991 12:00:00 AM
Class:		**Update Date:**	09/11/2006 07:52:59 AM
Meets Std:	True	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SJMILLER
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Affected Persons		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"BORING NEXT TO PIPELINE FOR ANODE GROUND BED(MAGNESIUM),SLUDGE LIKE MATERIAL FOUND IN (3) 20FT BORINGS, DEC (MILLER) AT SITE,1/22/91-14:00"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MILLER 02/25/91: EXXON INVESTIGATING ALONG GREEN ST WITHIN MONTH FAILED TO INDENTIFY A SUBSURFACE FLOATING PRODUCT,NEAREST TEST BORING OF EXXON WITHIN 50FT OF REPORTED BUCKEYE BORING,DEC TO CLOSELY MONITOR SITUATION. 10/10/95: This is additional information about material spilled from the translation of the old spill file: SLUDGE LIKE MATERIAL."

Material Information

OP Unit ID:	951376	**Med Ind Air:**	False
OU:	01	**Med GW:**	True
Material ID:	427786	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	-1.00	**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	BUCKEYE?
Spiller Address:	P O BOX 606-JFK
Spiller City:	JAMAICA
Spiller State:	NY
Spiller Zip:	11430
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
46	1 of1	NNE	0.07 / 380.07	11.38 / -1	EXXON TERMINAL 320 FREEMAN AVENUE BROOKLYN NY	NY SPILLS

Spill No:	8710916	**UST Trust:**	False
Site ID:	167657	**Spill Date:**	03/30/1988 11:00:00 AM
DER Facility ID:	141252	**Received Date:**	03/30/1988 12:17:00 PM
CID:		**CAC Date:**	03/30/1988 12:00:00 AM
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	03/30/1988 12:00:00 AM
Water Body:	WHALE CREEK	**Create Date:**	04/20/1988 12:00:00 AM
Class:	B3	**Update Date:**	04/07/2004 12:00:00 AM
Meets Std:	True	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SIGONA
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"LEAKING FLANGE ON PIPELINE.LEAK HAS BEEN STOPPED SHEEN ON WATER NEAR DOCK 10 X 50 FEET."

DEC Remark:

""

Material Information

OP Unit ID:	916784	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	462664	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	5.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	EXXON CORP
Spiller Address:	320 FREEMAN AVENUE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.734924000
Longitude:	-73.949325000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
47	1 of1	NE	0.08 / 398.70	10.37 / -2	REPUBLIC METALS CO INC 273 GREEN ST BROOKLYN NY 11222-1207	RCRA NON GEN

EPA Handler ID: NYD001213156

Gen Status Universe:	No Report
Contact Name:	
Contact Address:	273 , GREEN ST PO BOX 370 , , BROOKLYN , NY, 11223 , US
Contact Phone No and Ext:	
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	
Receive Date:	20070101
Location Latitude:	40.734071
Location Longitude:	-73.951471
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date:	19990714
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	EPA
Evaluation Start Date:	19930203
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	EPA

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19801128
Handler Name:	REPUBLIC METALS CO INC
Source Type:	Notification
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990708
Handler Name: REPUBLIC METALS CO INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: REPUBLIC METALS CO INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: REPUBLIC METALS CO INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: REPUBLIC METALS COMPANY INC
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: REPUBLIC METALS COMPANY INC
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Notification
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country:
Zip Code: 99999

Owner/Operator Ind: Current Operator
Type: Private
Name: REPUBLIC METALS COMPANY INC
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: REPUBLIC METALS CO INC

Receive Dt: 19990708
Generator Code Description: Not a Generator, Verified
Handler Name: REPUBLIC METALS CO INC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Dt: 19801128
Generator Code Description: Large Quantity Generator
Handler Name: REPUBLIC METALS CO INC

---

48 | **1 of1** | **SW** | **0.08 / 406.81** | **13.33 / 1** | **MANNION SERVICE STATION**
301 MCGUINNESS BOULEVARD
BROOKLYN NY 11222 | **UST**

Site ID: 19726
Site Status: Unregulated/Closed
Program No: 2-421006
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Storage Terminal/Petroleum Distributor

Expiry: N/A
County: Kings
UTM X: 588524.25462
UTM Y: 4509559.18941

Tank Information

Prog No: 2-421006
Tank ID: 14140
Tank No: 010
Tank Status: 3
Tank Status Desc: Closed - Removed
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 12/01/1974
Close Date: 09/01/1996
Tk Out of Serv Dt:
Capacity (Gal): 550
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Tank Information

Prog No: 2-421006
Tank ID: 14141
Tank No: 011
Tank Status: 3
Tank Status Desc: Closed - Removed
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 12/01/1974
Close Date: 09/01/1996
Tk Out of Serv Dt:
Capacity (Gal): 550
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Tank Owner Name:
Tank Owner Address:

Tank Information

Prog No:	2-421006	***UDC Ind:***	1
Tank ID:	14133	***Red Tag Start Date:***	
Tank No:	003	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	12/01/1974	***Next Test:***	
Close Date:	09/01/1996	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Tank Information

Prog No:	2-421006	***UDC Ind:***	1
Tank ID:	14135	***Red Tag Start Date:***	
Tank No:	005	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	12/01/1974	***Next Test:***	
Close Date:	09/01/1996	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Tank Information

Prog No:	2-421006	***UDC Ind:***	1
Tank ID:	14136	***Red Tag Start Date:***	
Tank No:	006	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN

Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1974	**Next Test:**	
Close Date:	09/01/1996	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Tank Information

Prog No:	2-421006	**UDC Ind:**	1
Tank ID:	14134	**Red Tag Start Date:**	
Tank No:	004	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1974	**Next Test:**	
Close Date:	09/01/1996	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Tank Information

Prog No:	2-421006	**UDC Ind:**	1
Tank ID:	14142	**Red Tag Start Date:**	
Tank No:	012	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1974	**Next Test:**	
Close Date:	09/01/1996	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			

Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Tank Information

Prog No:	2-421006	***UDC Ind:***	1
Tank ID:	14132	***Red Tag Start Date:***	
Tank No:	002	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	12/01/1974	***Next Test:***	
Close Date:	09/01/1996	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Tank Information

Prog No:	2-421006	***UDC Ind:***	1
Tank ID:	14131	***Red Tag Start Date:***	
Tank No:	001	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	12/01/1974	***Next Test:***	
Close Date:	09/01/1996	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Tank Information

Prog No:	2-421006	***UDC Ind:***	1
Tank ID:	14139	***Red Tag Start Date:***	
Tank No:	009	***Red Tag End Date:***	

Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1974	**Next Test:**	
Close Date:	09/01/1996	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Tank Information

Prog No:	2-421006	**UDC Ind:**	1
Tank ID:	14137	**Red Tag Start Date:**	
Tank No:	007	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1974	**Next Test:**	
Close Date:	09/01/1996	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Tank Information

Prog No:	2-421006	**UDC Ind:**	1
Tank ID:	14138	**Red Tag Start Date:**	
Tank No:	008	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1974	**Next Test:**	
Close Date:	09/01/1996	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
49	1 of5	SSE	0.08 / 410.45	12.01 / 0	CON EDISON SERVICE BOX: 56190 239 JAVA ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004474466
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20140421
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20140321
Handler Name: CON EDISON SERVICE BOX: 56190
Source Type: Emergency
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20140421
Handler Name: CON EDISON SERVICE BOX: 56190
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20140321
Generator Code Description: Very Small Quantity Generator
Handler Name: CON EDISON SERVICE BOX: 56190

49	2 of5	SSE	0.08 / 410.45	12.01 / 0	CON EDISON FRONT OF 239 JAVA ST SB8635 BROOKLYN NY 11222	GEN MANIFEST

RCRA ID: NYP004602868
District Name: CON EDISON
Contact Name: CON EDISON
Business Phone No:
Mailing Street 1: 4 IRVING PL
Mailing Street 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2014: 150 Gallons

49	3 of5	SSE	0.08 / 410.45	12.01 / 0	CON EDISON FRONT OF 239 JAVA ST SB56190 BROOKLYN NY 11222	GEN MANIFEST

RCRA ID: NYP004642427
District Name: CON EDISON
Contact Name: CON EDISON
Business Phone No:
Mailing Street 1: 4 IRVING PL
Mailing Street 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2014: 80 Gallons

49	4 of5	SSE	0.08 /	12.01 /	CON EDISON	GEN MANIFEST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
			410.45	0	FRONT OF 239 JAVA ST SB56190 BROOKLYN NY 11222	

RCRA ID: NYP004655064
District Name: CON EDISON
Contact Name: CON EDISON
Business Phone No:
Mailing Street 1: 4 IRVING PL
Mailing Street 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2014: 50 Gallons

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
49	5 of5	SSE	0.08 / 410.45	12.01 / 0	CON EDISON F/O 239 JAVA ST STRUCTURE 56190 BROOKLYN NY 11222	GEN MANIFEST

RCRA ID: NYP004474466
District Name: CON EDISON
Contact Name: TOM TEELING
Business Phone No: 2124603770
Mailing Street 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Street 2:
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2014: 50 Gallons

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
50	1 of1	NNE	0.08 / 423.27	11.04 / -1	CONSTRUCTION PROJECT 347 FREEMAN ST BROOKLYN NY	NY SPILLS

Spill No: 0009812
Site ID: 110975
DER Facility ID: 97118
CID: 257
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C4
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Unknown
Reported by: Other
Referred to:
Source: Unknown
UST Trust: False
Spill Date: 11/28/2000 03:00:00 PM
Received Date: 11/29/2000 12:12:00 PM
CAC Date:
Insp Date:
Close Date: 11/30/2000 12:00:00 AM
Create Date: 11/29/2000 12:00:00 AM
Update Date: 04/07/2003 12:00:00 AM
DEC Region: 2
Lead DEC: JMROMMEL
After Hours: False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"CALLER IS THE CONSUALTANT THAT IS OVER SEEING THE JOB AND CAME ACROSS THIS SPILL ON 11/28/00"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL While excavating, came across 1 crushed drum and misc. containers. "

Material Information

OP Unit ID:	830804	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	543747	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	MRS METZGER
Contact Phone:	(845) 987-1755
Contact Ext:	
Latitude:	40.735144260
Longitude:	-73.948423680

51	1 of1	NW	0.08 / 424.77	11.35 / -1	COMING FROM OUTSIDE- SINCE EARLY FEBRUARY CORNER OF FREEMAN AND MCGUINESS BROOKLYN NY	NY SPILLS

Spill No:	1902180	**UST Trust:**	False
Site ID:	590090	**Spill Date:**	05/31/2019 06:45:00 PM
DER Facility ID:	540319	**Received Date:**	05/31/2019 08:15:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	06/03/2019 12:00:00 AM
Water Body:		**Create Date:**	05/31/2019 08:18:00 PM
Class:	C4	**Update Date:**	06/03/2019 10:40:30 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	PXLAKHAN
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Caller states that she is one of the tenants who has been forcibly moved by the department of health due to the smell of gasoline. Concerned about an extremely strong smell of gasoline. Unknown the cause."

DEC Remark:

"06/03/19 - Lakhani Spill closed and referred to Spill #1812114."

Material Information

OP Unit ID:	1337738	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2347159	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	1.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	True		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	MARY CINADR
Contact Phone:	(518) 852-8501
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
52	1 of2	NW	0.08 / 448.30	11.68 / 0	NYCDOT PULASKI BRIDGE OVER NEWTOWN CREEK MCGUINESS & FREEMAN BKLYN 11TH ST & JACKSON AVE QUEEN BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID:	NYD986993558
Gen Status Universe:	No Report
Contact Name:	GEORGE ADELHART
Contact Address:	411 , MCGUINNES BLVD , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:	718-788-1830
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Municipal
Receive Date:	20070101
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19920306
Handler Name:	NYCDOT PULASKI BRIDGE OVER NEWTOWN CREEK
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Waste Code Details

Hazardous Waste Code:	D000
Waste Code Description:	DESCRIPTION
Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20060101
Handler Name:	NYCDOT PULASKI BRIDGE OVER NEWTOWN CREEK
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20070101
Handler Name:	NYCDOT PULASKI BRIDGE OVER NEWTOWN CREEK
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Municipal	***Street 1:***	NOT REQUIRED
Name:	NEW YORK CITY DEPT OF	***Street 2:***	

	TRANSPORTATION		
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	NY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Municipal	**Street 1:**	NOT REQUIRED
Name:	NEW YORK CITY DEPT OF TRANSPORTATION	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	NY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Municipal	**Street 1:**	NOT REQUIRED
Name:	NEW YORK CITY DEPT OF TRANSPORTATION	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	NY
Phone:	212-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	99999

Historical Handler Details

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	NYCDOT PULASKI BRIDGE OVER NEWTOWN CREEK
Receive Dt:	19920306
Generator Code Description:	Not a Generator, Verified
Handler Name:	NYCDOT PULASKI BRIDGE OVER NEWTOWN CREEK

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
52	2 of2	NW	0.08 / 448.30	11.68 / 0	TM #2907 FREEMAN STREET & MCGINNIS BLVD BROOKLYN NY	NY SPILLS

Spill No:	0706289	**UST Trust:**	False
Site ID:	386781	**Spill Date:**	09/05/2007 12:30:00 PM
DER Facility ID:	336187	**Received Date:**	09/05/2007 12:59:00 PM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	09/20/2007 08:43:00 AM
Water Body:		**Create Date:**	09/05/2007 01:09:00 PM
Class:	C4	**Update Date:**	09/20/2007 08:44:41 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	gdbreen
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"DRIPPING AT THIS TIME: ONGOING: 207874"

DEC Remark:

"09/20/07 - See eDocs for Con Ed report detailing cleanup and closure. 207874. see eDocs"

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material Information

OP Unit ID:	1144011	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2134296	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	20.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0020A		
Material Name:	transformer oil		

Spiller Information

Spiller Name:	ERTSDESK
Spiller Company:	CON EDISON
Spiller Address:	FREEMAN AVE & MCGINNIS BL
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	ERTSDESK
Contact Phone:	(212) 580-8383
Contact Ext:	
Latitude:	
Longitude:	

53	***1 of3***	***WNW***	***0.08 / 448.43***	***12.16 / 0***	***SERVICE BOX 8463 210/212 FREEMAN AVENUE BROOKLYN NY***	***NY SPILLS***

Spill No:	9901749	***UST Trust:***	False
Site ID:	289274	***Spill Date:***	05/14/1999 11:05:00 AM
DER Facility ID:	234243	***Received Date:***	05/14/1999 11:38:00 AM
CID:	204	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	06/04/1999 12:00:00 AM
Water Body:		***Create Date:***	05/14/1999 12:00:00 AM
Class:	C4	***Update Date:***	06/13/2000 12:00:00 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	JHOCONNE
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Local Agency		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CON ED NUMBER 124894 - ON 10 GALLONS OF WATER - CONTAINED - CLEANUP PENDING RESULTS OF TESTING "

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con ed e2mis notes: Approx 1.5 gallons unknown oil on approx 10 gallons water in S/B 8463. contained no sewer connection or sewers or waterways affected, no outside impact- no oil filled equipment in structure. <1. 00ppm, 5/17/99 - 1600 hrs , cleanup completed tag removed. "

Material Information

OP Unit ID:	1080512	***Med Ind Air:***	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OU:	01	**Med GW:**	True
Material ID:	305277	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	2.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	STEPHEN CRIBBEN
Contact Phone:	(212) 580-6763
Contact Ext:	
Latitude:	
Longitude:	

53	2 of3	WNW	0.08 / 448.43	12.16 / 0	AT DUPLEX 212 FREEMAN ST BROOKLYN NY	NY SPILLS

Spill No:	1901371	**UST Trust:**	False
Site ID:	588244	**Spill Date:**	05/08/2019 07:30:00 PM
DER Facility ID:	539540	**Received Date:**	05/08/2019 07:53:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	05/09/2019 12:00:00 AM
Water Body:		**Create Date:**	05/08/2019 07:56:00 PM
Class:		**Update Date:**	05/09/2019 11:10:42 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	HRPATEL
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"gasoline smell coming up from sewage trap (2' from Bedroom) in bedroom - also smells upstairs in house - Would like to have someone respond"

DEC Remark:

"5/9/19 - Sekhon Notifier complained about gasoline smell in her apt. DEC Kumar dispatched to investigate and for follow up. 05/09/19-Hiralkumar Patel. visited site (at 8:45 PM on 05/08/19). met Ms. Cinadr and crew of New York 1 news channel. noted mixed sewage odors near the entrance of Ms. Cinadr's residence. conducted PID survey inside Ms. Cinadr's residence and noted maximum of 5 ppm on PID. noted up to 4.5 ppm on PID near the wood ply covering the sump at the residence entrance. spoke with DEC Austin and DOH Nathan and informed them about findings. case closed and consolidated with spill #: 1812114."

Material Information

OP Unit ID:	1335909	**Med Ind Air:**	False
OU:	01	**Med GW:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material ID:	2345247	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	MARY CINADR
Contact Phone:	(518) 852-8501
Contact Ext:	
Latitude:	
Longitude:	

---

53 | ***3 of3*** | ***WNW*** | ***0.08 / 448.43*** | ***12.16 / 0*** | ***GROUND 212 FREEMAN ST. 212 FREEMAN STREET/ 212 GREEN STREET BROOKLYN NY*** | ***NY SPILLS***

Spill No:	1812114	**UST Trust:**	False
Site ID:	584074	**Spill Date:**	03/10/2019 10:32:00 AM
DER Facility ID:	539201	**Received Date:**	03/10/2019 10:32:00 AM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	07/24/2019 12:00:00 AM
Water Body:		**Create Date:**	03/10/2019 10:34:00 AM
Class:	C4	**Update Date:**	10/29/2019 02:31:47 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	RWAUSTIN
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"The following information was received through the DEC website "Report an Environmental Violation Online" or sent directly by the complainant to an OPP dispatch mailbox: Who Did It: There is a gas station located at 321 Mcguinness Blvd that has a leak from one of their underground tanks or lines that is penetrating the soil underneath my building causing gasoline vapors to come up through my walls into my apartment. We hired an indoor air quality expert who took air quality samples which show multiple components of gasoline in the air. These chemicals include known human carcinogens. This is a constant ongoing problem. What Occurred: Gasoline vapors are coming into my apartment constantly. This is been happening for approximately one month. It is a constant problem that does not ever go away. When Did It Occur: It started approximately one month ago around the second week of February, 2019 and has not stopped. This is a constant ongoing problem. It does not go away and come back. It is ever present. County: Kings Municipality: Brooklyn Location Or Address: I live in the building at 214 Green St., Apt. 2 B. The gas station is located next-door to my building at 321 McGuinness Boulevard. Both are in Brooklyn, New York, 11222. How Did It Occur: The contractor we hired believes there is an ongoing active gasoline leak from the service station next door. Additional Details: We have already contacted the DEC, NYC DOH and NYC DEP however this is an ongoing active problem that is not being resolved. Complainants Name: Jay Complainants Phone: 9177481021 Complainants Email: trenchcoatjedi@yahoo.com Date of Submittal: 03/10/2019"

DEC Remark:

"03/11/19 - Lakhani The DEC initially received this report as an NRC report (#1239599). Jay Stahl-Herz, the complainant, reported that his apartment building is being exposed to elevated levels of vapors associated with gasoline. The apartment building located at 412 Green Street is next to a Gulf gas

station at 321 McGuinness Blvd. DEC Lakhani responded to the vapor complaint on 03/08/19. Upon inspecting the site, DEC Lakhani did observe a faint olfactory odor in the gym. The building employs air purifiers to manage the odors. The building hired Oasis Indoor Environmental, a private consultant, to perform indoor air quality testing. Results were as follow: benzene 170 ug/m3, toluene 940 ug/m3, ethylbenzene 160 ug/m3, o-xylene 160 ug/m3, p/m-xylene 420 ug/m3, 1,3,5-trimethylbenzene 46 ug/m3, 1,2,4-trimethylbenzene 12 ug/m3. From the results, Oasis Indoor Environmental hypothesizes that there is most probably an active gasoline leak at the gas station. Not only do we see Isooctane and n-Heptane (heavier hydrocarbons), but also some light hydrocarbons such as n-Butane, n-Hexane, and Benzene. The presence of these lighter more volatile compounds (like n-Butane in such unusually high amounts) points to a very recent or ongoing gasoline leak. According to my colleague, these are due to the more volatile additives added to fuel during the winter time. Given this hypothesis, DEC Lakhani inspected the two (2) sumps in the basement of the property. No oil was found in either of the sump pits. PID values of 0 ppm were observed in the gym. DEC Lakhani returned to the site on 03/10/19 to inspect Jay's apartment. Jay has taped over outlets, switches, and baseboards. PID readings were 0 ppm throughout the home. Highest PID readings were found at the outlet at 0.8 ppm. Jay uses air purifiers in his home. He stated that he began observing the odors after 02/04/19. Jay and his wife observe the odors at the common wall between their apartment and the neighboring townhome. DEC Lakhani inspected the neighboring property and a tenant claimed they periodically smell gasoline odors whereas the odors in Jay apartment and building are persistent. PBS #2-600693 (Gulf Gas Station located at 321 McGuinness Blvd) The gas station was last inspected in 05/10/17. DEC Lakhani spoke to DEC Zielinski regarding the gas station. DEC Ajoku will inspect the site. 03/12/19 - Lakhani DEC received spill #1812191 on 03/12/19. National Grid found petroleum in a vault located at Green Street and McGuinness Blvd on 03/05/19. National Grid performed a cleanup and returned to the vault a week later and found that product returned to the vault. 03/15/19 - Lakhani DEC Lakhani went to investigate the building after the tenants complained of the odors returning to the hallways. Neither olfactory odors were observed nor any PID readings above 0 ppm. DEC Lakhani inspected the basement, individual floors, elevator shaft and sump pits. 03/19/19 - Lakhani DEC Lakhani and DEC Ajoku visited the gas station while the tightness tests were being performed. DEC Lakhani inspected 214 Green Street due to further odor complaints. PID readings in 214 Green Street did not exceed 0 ppm. Access was gained to 210 Green Street's basement today. 210 Green Street does not use fuel oil to heat the building. However, the highest PID reading observed was 7 ppm. Their basement is decrepit and used for storage. PID readings on the ground and above floors were less than 2 ppm. 03/20/19 - Lakhani Tightness tests were performed on all tanks at the gas station. Unofficial results of the tests reveal that the tanks are tight. DEC Lakhani returned to the site since tenants complained of the odors. None were detected upon DEC arrival. Spills staff also met with National Grid to inspect their vaults. Four (4) vaults were inspected near the intersection of McGuinness Blvd and Green Street. One vault was found with a sheen atop water and another with sheen on the mud. Samples were collected from the impacted vaults. National Grid is having their vaults cleaned by an environmental contractor. 03/21/19 - Lakhani Crompco submitted official results of the tank tests to DEC. Tanks, pipes, leak detectors and overfill passed. The monitoring well assessment remains to be completed at the gas station. 03/25/19 - Lakhani Owner information of 212 Green Street: 212/210 Green St BBL 3-2523-28 Owner 212 Green St LLC, Jac Ort, and his siblings - 516-286-3520 jmort516@aol.com 03/27/19 - Lakhani DEC Lakhani proceeded to investigate neighboring residential properties. DEC Lakhani was granted access to 212 Green Street and PID surveyed the building. PID readings in the occupied spaces ranged from 1.2 ppm to 2.5 ppm. The basement was surveyed and PID readings as high as 15 ppm were recorded. Olfactory odors were present. Coincidentally, the highest PID readings were observed at the sump pit. The pit was uncovered and PID readings soared to 45 ppm in the pit. Odors were emanating from the pit but no obvious petroleum product was visible in the water entering the pit. Upon speaking to the tenants, DEC Lakhani learned that a similar situation occurred two years earlier in the basement. However, odors quickly dissipated after the (pit) was flushed for 4 consecutive hours. DEC received a second odor complaint from a tenant at 211 Green Street (#1812673). 04/03/19 - Lakhani The DEC received additional complaints from Freeman Street, the street immediately north of Green Street. Multiple homes on both the north and south side of the street reported odors prevalent in the evenings between 4 PM and 6 PM. DEC Lakhani investigated the homes at Freeman Street during this time and detected sweet and sewage odors. The highest PID reading observed was 5 ppm in a shed behind 201 Freeman Street. It is possible that an individual may be dumping either a solvent or petroleum product in the sewer causing the odors in the homes. 04/05/19 - Lakhani DEC Lakhani met DEP Alex Castro on Freeman Street on 04/04/19. Sewers were inspected along Freeman Street and Green Street. PID readings were observed at manholes located at Freeman and McGuinness, a manhole on McGuinness between Freeman and Green, a manhole located at the intersection of Manhattan and Green, and another manhole located outside of 185 Green Street. PID readings in these manholes were greater than 13.5 ppm with the highest reading of 24 ppm at the manhole located on McGuinness. A light sheen was observed in the sewer at the manhole located at Freeman and McGuinness. DEP Castro will have DEP flush the sewers on Freeman Street. DEC and DEP also inspected 212 Freeman Street as tenants have complained about raw sewage and sewage impacting the building. The building's plumbing was not installed appropriately causing sewage to backflow and flood the backyard and the bathrooms of the ground floor apartments. There was standing raw sewage in the backyard during the inspection. The sewage odor penetrates the building and causes an odor issue in the apartments. The lack of fresh air vents causes the odor to linger. 210 Freeman Street was also inspected and faint odors were detected. The sewer trap is buried under sand in the pit. 212 Green Street was inspected and the sewer pit was inspected and odors were immediately detected once the cover was lifted off the pit. DEP Castro suggested that the odors are back flowing from the sewer through the open pipe in the pit. The pit will be flushed in attempt to mitigate the vapors. 04/08/19 - Lakhani DEP Sewer Maintenance met DEC Lakhani to inspect the sewer via the manhole located at Green Street and McGuinness Blvd. PID readings in the sewer were 7 ppm. There was good flow in the sewer. There was soapy sewage flowing unobstructed in the sewer. No petroleum odors were noted in the sewer. 04/11/19 - Lakhani DEC Lakhani visited Mary's apartment at 12:45 PM. DEC Lakhani observed olfactory odors. PID readings in the apartment were approx. 1.7 ppm. Readings in the basement increased to 2.4 ppm. The sewer trap/pit was opened and readings jumped to 4 ppm. PID readings where the pipe from the street enters the pit was approx. 9 ppm. Mary called FDNY who did not detect anything in the apartment using their meters. FDNY characterized the odors as sewage. Mary filed a complaint with DOB. DEC Lakhani then visited 212 Green Street after Jac Ort reportedly flushed the pit. PID readings in the basement were lower: approx. 2.5 ppm. The window was open allowing for ventilation. The window was closed and readings climbed to 4.5 ppm. PID readings in the sewer pit were as high as 60 ppm. The common wall between 212 and 214 Green Street has a few gaps. One gap is located on the common wall towards the front of the building. PID readings from this gap were approx. 14.2 ppm. 04/16/19 - Lakhani On 04/15/19, DEC Austin, DEC Lakhani and NYSDOH Walz visited both Green Street and Freeman Street. 214 Green Street was investigated first at 4:10 PM. PID readings were as follow: Hallway entrance: 190 ppb Gym ambient air: ~1000 ppb Outlet in gym on the wall shared with 212 Green: 3400 ppb. Jay's apt ambient air: 190 ppb Jay's closet: 1350 ppb Jay's apt second floor near outlet: 350 ppb Behind stove: 400 ppb Basement ambient air: 22 ppb Sump pits: 0 ppm (no odor; biological sheen) Elevator shaft: 11 ppb A SUMMA canister air sample was collected in the closet of Jay's apartment. 212 Green Street was investigated next at roughly 5:10 PM. PID readings were as follow: Basement ambient: 1300 ppb (pit closed) Basement ambient: 3400 ppb (pit open) Sump pit: 13000 ppb Floor drain adjacent to sump: 10000 ppb 212 Freeman Street was investigated next at roughly 5:35 PM. PID readings were as follow: Ambient air: 34 ppb Basement near sewer connections: 22 ppb Exterior sump pit, assumed rain water present: 0 ppb 201 Freeman Street was investigated next. No odors were present. Maximum readings of 22 ppb were observed in all areas of the home. 04/17/19 - Lakhani At 8:07 PM on 04/16/19, Mary reported smelling gasoline odors in the bottom floor of her apartment. She was instructed the ventilate her apartment from the bottom floor. The odors became apparent again at 5:37 AM on 04/17/19. DEC Lakhani responded at approx. 9:30 AM on 04/17/19 and found no odors. DEP was also on site during DEC inspection. No violations were written. 04/22/19 - Lakhani Mary, 212 Freeman Street, reported strong gasoline odors on the basement level entrance of her apartment at 10 AM today. Ziggy, 214 Green Street, also reported noticeable odors in the 4th floor hallway. 04/23/19 - Lakhani Mary contacted DEC Lakhani at 5:54 AM reporting strong gasoline odors in her home. DEC Lakhani

responded and arrived on scene to find a detectable olfactory odor that represented a combination of both sewage and petroleum product odors. PID readings in the home were 1.7 ppm. Upon opening the sewer trap, the highest PID observed was 16 ppm. The highest reading in the sewer trap was 24 ppm. DEC Lakhani set-up a SUMMA canister in the basement bedroom adjacent to the sewer trap and the downstairs entrance hallway. An 1.5 hour sample was collected. Manholes outside of 212 Freeman Street, 201 Freeman Street and at the intersection of Manhattan Ave and Freeman Street were inspected. PID readings were 37 ppm, 15.1 ppm, and 7.9 ppm, respectively. 04/29/19 - Lakhani 214 Green Street reported elevated odors on the first floor and at the entrance near the gym. Island Pump and Tank was retained as the PIN contractor to seal the sewer trap pits at 212 Freeman Street and 212 Green Street and provide ventilation to draw the vapors outside. A charcoal filter will be used at the 212 Freeman Street system to further mitigate the odors. 04/30/19 - Lakhani DEC Lakhani collected a SUMMA canister air sample at 212 Freeman Street at 6:18 AM today. 214 Green Street removed the street side caps on both their sewer and drain lines and detected a strong combined sewage and gasoline odor. Both DEC Austin and Lakhani witnessed these odors. Jason and the hired plumber discovered the pipe pumping water from the buildings sumps to the sewer is on the street side of the traps allowing gases to migrate from the main sewer into the building. The main traps would not stop these vapors. While these pipes have check valves, a second pipe connecting to the sump pipes does not. This second pipe is the potential conduit for the vapors that were found in Jay and Rachel's apartment. The sump pipes will be moved the building side of the trap to prevent any vapors from entering the building. This solution coupled with the sealed and ventilated sewer pit at 212 Green Street may address the odor complaint at 214 Green Street. 05/01/19 - Lakhani Mary from 212 Freeman Street noticed gasoline odors in her upstairs living room and bedroom. She reported less potent odors in the basement of her apartment. The sewers were inspected via six (6) manholes at Freeman, Green and Huron Streets along McGuinness Blvd. As each manhole was opened, observations and PID readings were recorded. Many of the manholes had accumulated debris/sediment which restricted flow in the sewer. DEP removed the debris from three (3) manholes at the corner of McGuinness Blvd and Freeman Street to restore flow. The sewer was then flushed using a pressurized water line. PID readings and observations prior to debris removal and flushing were as follows: • Freeman #1 (closer to Manhattan Ave): 6.2 ppm -Manhole contained debris. Sewage had a light sheen. Odors were present upon uncovering the manhole. • Freeman #2 (close to McGuinness Blvd): 4.2 ppm -Faint odors detected. Flow of sewage was good. • McGuinness #1 (between Freeman and Green): 4.7 ppm -Faint odor was detected. Flow was restricted by debris and bricks. • Green: 0 ppm -No odors detected. Flow is good. • McGuinness #2 (between Green and Huron): 1.2 ppm -No odors detected. Flow is good. • Huron: 2.6 ppm -No odors detected. Flow is good. After the debris was removed from the three (3) manholes, PID readings were as follows: • Freeman #1: 34.8 ppm • Freeman #2: 0.3 ppm • McGuinness #1: 0 ppm DEC Lakhani inspected Mary's apt after the debris removal and no odors were detected throughout her apt. After the sewer was flushed, PID readings at the three (3) manholes were as follows: • Freeman #1: 0 ppm -Flow was restored. No odors detected. • Freeman #2: 0 ppm -Flow was restored. No odors detected. • McGuinness #1: 0 ppm -Flow was restored. No odors detected. 05/03/19 - Lakhani DEC Lakhani went to Mary's apt this morning to check on the status of the ventilation. IPT installed the fan, however it caused odors to build in the vestibule. Odors were also present outside the building as the fan was running. PID readings in the vestibule when the fan was off were 2.4 ppm and 10.8 ppm when the fan was one. The odors in the vestibule were potent. PID readings in Mary's home where no more than 1.2 ppm on the first floor and no more than 3.6 ppm in the basement when the door to the vestibule was closed. These observations have allowed Mary to relocate for the weekend. Mary called DEP to inspect the apt since there was another sewage backup last night. Mary wanted DEP to issue an odor violation. While DEP did detect the odors, DEC Lakhani is unaware of any violations being issued. Due to the presence of the odors while the fan was on, Mary called 311 and made a complaint which prompted FDNY to visit the apt. FDNY did not find any issues and recommended to Mary that she move. The fan was not installed at 212 Green yet. IPT will return to install the fan and charcoal filter together. 05/06/19 - Lakhani 212 Freeman Street building manager, Mike Medovoy, informed that the sewer trap was flushed on 05/02/19. The plumbing was flushed from the rear of the building to the front again on 05/03/19 between 5 PM and 7 PM. Sediment was flushed out of the piping. According to Mike, odors were not strong compared to past odors. However, a hint of fuel odor was detected. 214 Green Street is having the mystery pipe relocated to the building side of the sewer trap. A check valve will be placed on the valve. The two (2) traps will then be flushed to the street. 05/07/19 - Lakhani Mike Medovoy emailed: I was able to go to the building last night around 6pm and this morning at 7:30am. The area by the trap had zero smell and definitely no fuel smells. Might you be able to go take reading as I think it maybe useful to record the changes since both the street and the building was flushed out. 05/08/19 - Lakhani DEC Lakhani visited Mary's apt at approx. 6 PM on 05/07/19 and observed PID readings of 1.3 ppm in the vestibule and 1.8 in the basement bedroom. No odors were detected during the visit. 05/15/19 - Lakhani The trend of diminishing odors has continued through the week. Nevertheless, Mary was relocated until the end of May. DEC has begun to actively address the new odors complaints made at the community meeting by performing field surveys and site visits. No odors have been detected in homes during visits to 186 India Street and 189 Freeman Street. The DEC has further engaged NYCDEP and requested they perform another thorough investigation of the sewers. DEP's Bureau of Water and Sewer Operations will be vactoring the following sewer segments: Freeman Street from McGuinness Blvd to Manhattan Avenue; Green Street from McGuinness Blvd to Manhattan Avenue; Manhattan Avenue from Eagle Street to Green Street; and McGuinness Blvd from Eagle Street to Huron Street. 05/17/19 - Lakhani DEP vactored and flushed the sewers in the area between 05/15/19 and 05/16/19. Below are the field screen results of the sewers as per DEP: 1. 4:06 pm, IFO 158 Freeman St, 0.0 ppm VOC'S, mh # 8502, manhole not pulled 2. 4:19 pm, IFO 201 Freeman St, 0.2 ppm VOC'S, mh # 8525, manhole not pulled 3. 4:24 pm, IFO 1031 Manhattan Ave, 0.2 ppm VOC'S, mh # 8325, only a trickle of flow, nearly bone dry 4. 4:36 pm, Freeman St && Manhattan Ave, 0.0 ppm VOC'S, mh # 9228, plenty of fluid 5. 4:43 pm, on Freeman St, 50 Ft E of Manhattan Ave, 0.0 ppm VOC'S , mh # 8522, medium volume, medium flow rate 6. 4:54 pm, Freeman St && McGuiness Blv, 1.7 ppm VOC'S, mh # 8480, large volume, low flow rate 7. 5:05 pm, Freeman St 30 feet W of McGuiness Blv, 12.5 ppm VOC'S, mh # 9179, medium volume, medium flow rate 8. 5:16 pm, OPPOSITE 344 McGuiness Blv, 54.8 ppm VOC'S, mh # 8481, high volume, low flow rate ERU repeats the high reading again 9. 5:21 pm, OPPOSITE 344 McGuiness Blv, 14.9 ppm VOC'S, with 5 minutes to vent, mh # 8481, High Volume, low flow rate 10. 5:29 pm, Huron St && McGuiness Blv, 10.4 ppm VOC'S, mh # 8690, medium volume, medium flow rate 11. 5:43 pm, Green St && Manhattan Ave, 0.9 ppm VOC'S, mh # 8541, small volume, low flow rate 12. 5:48 pm, IFO 183 Green St, 0.6 ppm VOC'S, mh #8493, small volume, medium flow rate 05/24/19 - Lakhani DEC Lakhani returned to Green and Freeman Streets on 05/22/19 and discovered PID readings in manholes between Freeman and Green Streets on McGuinness Blvd and at the corner of Freeman Street and McGuinness Blvd were no greater than 0.5 ppm. DEP found elevated readings in manholes on McGuinness Blvd near and on Huron Street. They are currently vactoring and flushing those manholes. 05/28/19 - Lakhani NYCDOH inspected Jay's apartment and observed PID readings below 1 ppm in their home. The DOH inspector gave verbal confirmation that the case can be closed. Upon hearing this Jay and Rachel have moved back into their apartment at 214 Green Street. However, Jay still indicated that there is some residual vapor odor that is intermittently noticeable (generally in the morning). DEP was vactoring the manholes on McGuinness Blvd near Huron Street on 05/24/19. However, the truck broke down. DEP returned today to vactor sewer lines on both sides of Manhattan Ave between Green and India Streets. DEP will have to retain a private contractor to vactor and flush the 84 line at Huron Street. Island Pump and Tank are working at 212 Freeman Street to completely seal the sump. The walls and bottom of the sump pit will be sealed with a mortar and the top sealed with a gasket. An AreaRAE will be placed on the first floor of Mary's apartment and will be left in place for the next two days (morning of 05/31/19). The manhole at the intersection of Freeman St and McGuinness Blvd and the manhole on McGuinness between Green and Freeman were field screened. PID readings were 27.8 ppm and 6.7 ppm respectively. 06/04/19 - Lakhani The mold abatement will be complete by COB on 06/04/19. The apartment will then be tested on 06/05/19 at 5 PM. Between 06/04/19 and 06/05/19, all equipment in the apartment will be turned off. 06/06/19 - Lakhani DEC Lakhani collected a SUMMA canister air sample on the first floor of Jay and Rachel's apartment at 214 Green Street on 06/05/19. PID readings throughout the house were 0.0 ppm. A SUMMA canister sample cannot be collected at 212 Freeman Street until the mold remediation work is complete.

The AreaRAE had reached capacity as the memory was full. IPT will retrieve the AreaRAE on 06/07/19 and extract the data. 6/6/19 - Austin - I did a PID survey of the catch basins and sewer manholes (through their sewer covers) on Freeman, McGuiness, Green, and Huron Streets, as described below: MH IFO 212 Freeman (Cinadr residence) - .1 ppm MH IFO 201 Freeman (Keller residence) - 0 CB southwest corner Freeman and McGuiness 0 212 Freeman- floor drain in front of alcove door - 2ppm ; door vent - 2 ppm (paint odor) McGuiness - All zeros Green St - All zeros Huron St - IFO 212 Huron- 6-9 ppm IFO 200 Huron 10 ppm IFO 186 Huron 3.5 ppm Huron and Manhattan- Nothing detected NYCDEP has indicated that they haven't cleaned the Huron St. interceptor, and had no plans to do so. We will discuss this with them further. - end 06/13/19 - Lakhani The AreaRAE data was extracted and revealed PID readings no greater than 0.1 ppm on 05/28/19 between approximately 2 PM and 10 PM. An air sample was collected at 214 Green Street on 06/05/19. Results were sent to NYSDOH for interpretation. NYSDOH indicated that the results of the air sampling fall within typical background concentrations. Results were communicated to Jay and Rachel. Air sampling at 212 Freeman Street will be postponed until the mold abatement work is complete. 07/01/19 - Lakhani DEC received the results of the SUMMA canisters collected at 212 Freeman Street. DEC Lakhani sent the results to NYSDOH for interpretation. All compounds with the exception of 1,4-dichlorobenze was below background concentrations. 07/02/19 - Lakhani DEC Lakhani collected a final SUMMA canister at Zigmund Kermish's apartment, located at 214 Green Street Apt. 4B. A 1.5 hour sample was collected in the apartment. PID readings in the home ranged between 0.3 ppm and 0.4 ppm. No olfactory odors were observed. DEC sent the sample to TestAmerica to be analyzed on 07/02/19 at 1:30 PM. 7/11/19 - Austin - Yesterday (7/10/19) at approximately 4:30 PM, I checked the three manholes along Huron St to se what the vapor levels were (through the sewer caps)while NYCDEP was cleaning this sewer interceptor (they were not on scene at the time of the monitoring): Results: IFO 212 Huron- 4-6 ppm IFO 200 Huron 0.2 ppm IFO 186 Huron 0 ppm Huron and Manhattan- Nothing detected We will need to monitor this sewer and re-check the other impacted sewers once DEP has completed their cleaning of the interceptor on Huron St. - end 07/24/19 - Lakhani DEC has also received and reviewed the FDNY list of response events in North Brooklyn for 6/1/18 – 12/31/18. However, no events during this time period seemed to have impacted the sewers either. Unfortunately, the source of the odors could not been determined despite cleanup and investigative efforts by NYSDEC, NYSDOH, NYCDOH, and NYCDEP. The spill has been closed. 10/18/19 - Austin - Lead DEC on this spill changed to Austin from Lakhani, due to Lakhani being on LWOP for school, to process any outstanding PIN project invoices. - end 10/29/19 - In conversation with Nate Walz of the NYSDOH, he indicated that the total cost for relocation of M. Cinadr was $11,546.85. - end"

Material Information

OP Unit ID:	1331741	***Med Ind Air:***	True
OU:	01	***Med GW:***	False
Material ID:	2340963	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	True
Quantity:	-1.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	JAY
Spiller Company:	UNKNOWN
Spiller Address:	321 MCGUINNESS BLVD
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	JAY
Contact Phone:	(917) 748-1021
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
54	1 of1	NW	0.09 / 451.74	11.68 / 0	ROADWAY FREEMAN & MCGUINESS ST BROOKLYN NY	NY SPILLS

Spill No:	0211776	***UST Trust:***	False
Site ID:	241027	***Spill Date:***	02/27/2003 04:00:00 PM
DER Facility ID:	198170	***Received Date:***	02/27/2003 04:26:00 PM
CID:	252	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	02/28/2003 12:00:00 AM
Water Body:		***Create Date:***	02/27/2003 12:00:00 AM
Class:	C3	***Update Date:***	03/03/2003 12:00:00 AM
Meets Std:	False	***DEC Region:***	2

Penalty:	False	**Lead DEC:**	MXTIPPLE
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Tank Truck		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"PETROLEUM TANK IS ENROUTE FOR CLEANUP."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 2/28/02 TIPPLE VISITED INTERSECTION, NO EVIDANCE OF PETROLEUM REMAINING ON ROADWAY"

Material Information

OP Unit ID:	865216	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	511559	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	25.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	BRIDGE TRANSPORTATION
Spiller Address:	176 27TH ST
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	RAY LARA
Contact Phone:	(718) 624-4842
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
55	1 of2	N	0.09 / 470.39	10.94 / -1	BAY CRANE SERVICE INC 255 FREEMAN ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID:	NYR000046383
Gen Status Universe:	No Report
Contact Name:	HENDERSON JACKMAN
Contact Address:	389 , NEW SOUTH RD , , HICKSVILLE , NY, 11801 , US
Contact Phone No and Ext:	516-937-1523
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20070101
Location Latitude:	40.734851
Location Longitude:	-73.950872

Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19971030
Handler Name: BAY CRANE SERVICE INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 1

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Date: 20060101
Handler Name: BAY CRANE SERVICE INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: BAY CRANE SERVICE INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: BAY CRANE SERVICE INC
Date Became Current:
Date Ended Current:
Phone: 516-937-1523
Source Type: Notification
Street No:
Street 1: 389 NEW SOUTH RD
Street 2:
City: HICKSVILLE
State: NY
Country:
Zip Code: 11801

Owner/Operator Ind: Current Owner
Type: Private
Name: BAY CRANE SERVICE INC
Date Became Current:
Date Ended Current:
Phone: 516-937-1523
Source Type: Implementer
Street No:
Street 1: 389 NEW SOUTH RD
Street 2:
City: HICKSVILLE
State: NY
Country: US
Zip Code: 11801

Owner/Operator Ind: Current Operator
Type: Private
Name: BAY CRANE SERVICE INC
Date Became Current:
Date Ended Current:
Phone: 516-937-1523
Source Type: Implementer
Street No:
Street 1: 389 NEW SOUTH RD
Street 2:
City: HICKSVILLE
State: NY
Country: US
Zip Code: 11801

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: BAY CRANE SERVICE INC

Receive Dt: 19971030
Generator Code Description: Very Small Quantity Generator
Handler Name: BAY CRANE SERVICE INC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
55	2 of2	N	0.09 / 470.39	10.94 / -1	BAY CRANE SERVICE INC 255 FREEMAN ST BROOKLYN NY	GEN MANIFEST

RCRA ID: NYR000046383
District Name: BAY CRANE SERVICE INC
Contact Name: HENDERSON THORMAN
Business Phone No: 5169371523
Mailing Street 1: 389 NEW SOUTH RD
Mailing Street 2:
Mailing City: HICKSVILLE
Mailing State: NY
Mailing ZIP: 11801
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

1998: 50 Gallons
1999: 85 Gallons
2000: 110 Gallons
2001: 75 Gallons

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
56	1 of2	SW	0.09 / 477.45	13.56 / 2	CON EDISON MANHOLE: 7527 184 INDIA ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID:	NYP004345583
Gen Status Universe:	No Report
Contact Name:	FREDERICK GRAZIANO
Contact Address:	
Contact Phone No and Ext:	718-666-4589
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20130914
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20130814
Handler Name: CON EDISON MANHOLE: 7527
Source Type: Emergency
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20130914
Handler Name: CON EDISON MANHOLE: 7527
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20130814
Generator Code Description: Very Small Quantity Generator
Handler Name: CON EDISON MANHOLE: 7527

---

56 | **2 of2** | **SW** | **0.09 / 477.45** | **13.56 / 2** | **CON EDISON**
184 INDIA ST SB 7527
BROOKLYN NY 11222 | **GEN MANIFEST**

RCRA ID: NYP004345583
District Name: CON EDISON
Contact Name: CON EDISON
Business Phone No: 2124603770
Mailing Street 1: 4 IRVING PL 15TH FL
Mailing Street 2:
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2013: 75 Gallons

---

57 | **1 of1** | **NNE** | **0.09 / 483.86** | **10.68 / -1** | **EN TECH CORP**
259 FREEMAN ST
BROOKLYN NY | **NY SPILLS**

Spill No: 1810898
Site ID: 581808
DER Facility ID: 534339
CID:
Program Type: ER
SWIS Code: 2401
Water Body:
Class: D3
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Housekeeping
Reported by: Other
UST Trust: False
Spill Date: 01/28/2019 09:54:00 AM
Received Date: 01/28/2019 09:54:00 AM
CAC Date:
Insp Date:
Close Date: 01/28/2019 12:00:00 AM
Create Date: 01/28/2019 09:56:00 AM
Update Date: 01/28/2019 01:36:43 PM
DEC Region: 2
Lead DEC: RMPIPER
After Hours: False

Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Who Did It: EN TECH CORP What Occurred: This company be putting diesel gas in their trucks and getting the gas and oil over the sidewalk and street! I walk my dog on the block and I be needing to wash his feet. The neighbors are tired of them When Did It Occur: EVERY DAM DAY County: New York Municipality: Brooklyn Location Or Address: 259 freeman st brooklyn ny How Did It Occur: Additional Details: they be hiding the trucking they shop Complainants Name: Abioye Nkrumah@gmail.com Complainants Phone: Complainants Email: abioyenkrumah@gmail.com Date of Submittal: 01/28/2019"

DEC Remark:

"DEC Piper drove by and saw nothing out of the ordinary. Spill closed."

Material Information

OP Unit ID:	1329497	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2338581	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	EN TECH CORP
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	N/A
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

58	***1 of1***	***SE***	***0.09 / 484.14***	***11.37 / -1***	***41-55 PROVOST CO 41-55 PROVOST ST 41 PROVOST ST Brooklyn NY 11222***	***UST***

Site ID:	11210	***Expiry:***	N/A
Site Status:	Unregulated/Closed	***County:***	Kings
Program No:	2-268704	***UTM X:***	588703.98744
Program Type Code:	PBS	***UTM Y:***	4509549.03799
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Other		

Tank Information

Prog No:	2-268704	***UDC Ind:***	1
Tank ID:	40502	***Red Tag Start Date:***	
Tank No:	003	***Red Tag End Date:***	
Tank Status:	6	***Tank Last Test:***	

Tank Status Desc:	Closed Prior to 03/1991	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:		**Next Test:**	
Close Date:		**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	275	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Tank Information

Prog No:	2-268704	***UDC Ind:***	1
Tank ID:	40500	***Red Tag Start Date:***	
Tank No:	001	***Red Tag End Date:***	
Tank Status:	6	***Tank Last Test:***	
Tank Status Desc:	Closed Prior to 03/1991	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:		***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: H00
Code Name: None

Type: Tank Leak Detection

Tank Information

Prog No:	2-268704	***UDC Ind:***	1
Tank ID:	40501	***Red Tag Start Date:***	
Tank No:	002	***Red Tag End Date:***	
Tank Status:	6	***Tank Last Test:***	
Tank Status Desc:	Closed Prior to 03/1991	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:		***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B00

Code Name: None
Type: Tank External Protection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Affiliation Information

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: 41-55 PROVOST CO C/O J A LEWIS
Contact Title:
Contact Name:
Address1: 1819 FLUSHING AVE
Address2:
City: FLUSHING
State: NY
Zip Code: 11385
Country Code: 001
Phone: (718) 386-3804
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: 41-55 PROVOST CO C/O J A LEWIS
Contact Title:
Contact Name:
Address1: 1819 FLUSHING AVE
Address2:
City: FLUSHING
State: NY
Zip Code: 11385
Country Code: 001
Phone: (718) 386-3804
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: 41-55 PROVOST CO C/O J A LEWIS
Contact Title:
Contact Name: VULCAP CORP
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-9130
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: 41-55 PROVOST CO
Contact Title:
Contact Name: VULCAP CORP
Address1:
Address2:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 386-3804
Phone Ext:
Email:
Fax:

59	1 of1	WNW	0.09 / 494.06	11.74 / 0	NUVITE CHEMICAL COMPOUNDS CORP BROOKLYN NY	PFAS IND

Status:	Active	**Fac Fips Code:**	36047
Fac Indian Cntry Flg:	No	**Compliance Status:**	No Violation Identified
Fac Derived Huc:	02030201	**EPA Programs:**	CAA; RCRA
Fac Derived Wbd:	020301010405	**Federal Facility:**	No
Fac Derived Cd113:	12	**Federal Agency:**	-
Fac Derived Cb2010:	360470575001002	**Fac Snc Flg:**	No
Fac Informal Count:	0	**AIR Flag:**	Yes
Last Informal Action:	-	**NPDES Flag:**	No
Formal Action Count:	0	**SDWIS Flag:**	No
Last Formal Action:	-	**RCRAFlag:**	Yes
Fac Total Penalties:	0	**TRI Flag:**	No
Fac Penalty Count:	-	**GHG Flag:**	No
Date Last Penalty:	-	**TRI IDs:**	-
Last Penalty Amt:	-	**TRI Releases Trnsfrs:**	-
Fac Qtrs With Nc:	0	**TRI on Site Releases:**	-
Programs With Snc:	0	**TRI off Site Trnsfrs:**	-
Fac Percent Minority:	46.042	**TRI Reporter:**	-
Fac Pop Den:	48953.63	**Fac Imp Water Flg:**	-
Count:	1	**Fac Major Flag:**	-
Fac County:	KINGS	**Fac Active Flag:**	Yes
State Other :		**Fac Inspection Count:**	0
Region:	02	**Date Last Inspection:**	-
Latitude:	40.73464	**Days Last Inspection:**	-
Longitude:	-73.95284		

Fac Derived Tribes: -
AIR IDs: NY0000002610101293
CAA Permit Types: Minor Emissions
CAA NAICS: 325612
CAA SICS: 2842
NPDES IDs: -
CWA Permit Types: -
CWA NAICS: -
CWA SICS: -
RCRA IDs: NYN008016354 NYR000154708
RCRA Permit Types: SQG, VSQG
RCRA NAICS: -
SDWA IDs: -
SDWA System Types: -
SDWA Compliance Status: -
SDWA Snc Flag: No
Fac Collection Meth: ADDRESS MATCHING-HOUSE NUMBER
EJSCREEN Flag Us: No
EJSCREEN Report: https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.95284,%22y%22:40.73464,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
ECHO Facility Report: https://echo.epa.gov/detailed-facility-report?fid=110011937039

Industry: Cleaning Product Mfg

60	1 of6	NW	0.10 / 527.09	11.79 / 0	NUVITE CHEMICAL COMPOUNDS CO 213 FREEMAN STREET BROOKLYN NY 11222	RCRA VSQG

EPA Handler ID:	NYN008016354
Gen Status Universe:	VSG
Contact Name:	CLIFFORD LESTER
Contact Address:	213 , FREEMAN STREET , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:	718-383-8351
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	
Receive Date:	20070514
Location Latitude:	40.734656
Location Longitude:	-73.95289
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Act W.O. Storage:	No

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20070513
Handler Name:	NUVITE CHEMICAL COMPOUNDS CO
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Implementer

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20070514
Handler Name:	NUVITE CHEMICAL COMPOUNDS CO
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Implementer

Historical Handler Details

Receive Dt:	20070513

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Generator Code Description:	Very Small Quantity Generator					
Handler Name:	NUVITE CHEMICAL COMPOUNDS CO					

60	2 of6	NW	0.10 / 527.09	11.79 / 0	**NUVITE CHEMICAL** **213 FREEMAN ST** **BROOKLYN NY 11222**	RCRA SQG

EPA Handler ID:	NYR000154708
Gen Status Universe:	Small Quantity Generator
Contact Name:	CLIFFORD LESTER
Contact Address:	213 , FREEMAN ST , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:	718-383-8351
Contact Email:	C.LESTER@NUVITECHEMICAL.COM
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20080214
Location Latitude:	40.734656
Location Longitude:	-73.95289
Recycler Activity(YES/NO)?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity W.O. Stor:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20080214
Handler Name:	NUVITE CHEMICAL
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator
Source Type:	Implementer

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20080215
Handler Name:	NUVITE CHEMICAL
Federal Waste Generator Code:	2

Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U132
Waste Code Description: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: FIFTYSIX BUILDING CO LLC
Date Became Current: 19560101
Date Ended Current:
Phone:
Source Type: Notification
Street No: 194
Street 1: FREEMAN ST
Street 2:
City: BROOKLYN
State: NY
Country: US
Zip Code: 11222

Owner/Operator Ind: Current Operator
Type: Private
Name: NUVITE CHEMICAL
Date Became Current: 19570101
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1:
Street 2:
City:
State:
Country:
Zip Code:

Historical Handler Details

Receive Dt: 20080215
Generator Code Description: Small Quantity Generator
Handler Name: NUVITE CHEMICAL

60	3 of6	NW	0.10 / 527.09	11.79 / 0	NUVITE CHEMICAL 213 FREEMAN ST	GEN MANIFEST

BROOKLYN NY 11222

RCRA ID:	NYR000154708	***Mailing State:***	NY
District Name:	NUVITE CHEMICAL	***Mailing ZIP:***	11222
Contact Name:	NUVITE CHEMICAL	***Mailing ZIP Ext:***	
Business Phone No:	7183838351	***Mailing Country:***	USA
Mailing Street 1:	213 FREEMAN ST	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	BROOKLYN	***Location County:***	KINGS

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2008: 65 Pounds; 500 Pounds; 350 Pounds; 160 Pounds; 300 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2008: 150 Pounds

Manifest Information

Waste Code(s):

D004: ARSENIC (Waste Code Description from EPA Hazardous Waste Identification)
D036: NITROBENZENE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2008: 150 Pounds

Manifest Information

Waste Code(s):

U163: (70-25-7) MNNG

Waste Amounts By Year:

2015: 440 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume)

of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2008: 100 Pounds; 350 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)

Waste Amounts By Year:

2008: 300 Pounds

Manifest Information

Waste Code(s):

D026: CRESOL (Waste Code Description from EPA Hazardous Waste Identification)
F001: (Generic) The following spent halogenated solvents used in degreasing: tetrachloroethylene, trichloroethylene, methylene chloride, 1,1, 1-trichloroethane, carbon tetrachloride, and chlorinated fluorocarbons; all spent solvent mixtures/blends used in degreasing containing, before use, total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those solvents listed in F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)
F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)
U080: (75-09-2) Methane, dichloro-

Waste Amounts By Year:

2008: 2000 Pounds

Manifest Information

Waste Code(s):

F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

2008: 65 Pounds; 100 Pounds

60	***4 of6***	***NW***	***0.10 / 527.09***	***11.79 / 0***	***NuVite Chemical Compounds Corp. 213 Freeman St. Brooklyn NY 11222*** ***NY***	***TIER 2***

Company Name:
DUN Bradstreet Cd:
County:
Latitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Longitude:						
Report Method:		Reported via Mail				

60	5 of6	NW	0.10 / 527.09	11.79 / 0	Nuvite Chemical Compounds Corp., 213 Freeman St., Brooklyn, NY 11222 NY	TIER 2

Company Name:
DUN Bradstreet Cd:
County:
Latitude:
Longitude:
Report Method: Reported via Mail

60	6 of6	NW	0.10 / 527.09	11.79 / 0	Nuvite Chemical Compounds, 213 Freeman St., Brooklyn, NY 11222 Kings NY	TIER 2

Company Name:
DUN Bradstreet Cd:
County:
Latitude:
Longitude:
Report Method: Reported via Mail

61	1 of1	WNW	0.10 / 528.53	12.81 / 1	200 FREEMAN ST 200 FREEMAN ST BROOKLYN NY 11222	AST

Site ID:	13041	**Expiry:**	12/28/2025
Site Status:	Active	**County:**	Kings
Program No:	2-289507	**UTM X:**	588376.84095
Program Type Code:	PBS	**UTM Y:**	4509812.31242
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Apartment Building/Office Building		

Tank Information

Prog No:	2-289507	**UDC Ind:**	0
Tank ID:	18883	**Red Tag Start Date:**	
Tank No:	001	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	01/01/1957	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	4000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: MOHSEN ZANDIEH

Tank Owner Address: 251-12 NORTHERN BLVD. LITTLE NECK, NY. 11362

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: H99
Code Name: Other
Type: Tank Leak Detection

Equipment: B00
Code Name: None
Type: Tank External Protection

Affiliation Information

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: ZAND RIDGE ASSOCIATES, LLC
Contact Title: PRES.
Contact Name: MOHSEN ZANDIEH
Address1: 251-12 NORTHERN BLVD.
Address2:
City: LITTLE NECK
State: NY
Zip Code: 11362
Country Code: 001
Phone: (718) 279-0300
Phone Ext:

Email:	MOHSEN@OLROUGHREALESTATE.COM
Fax:	

Affiliation Type:	04
Affiliation Name:	Facility Operator
Affiliation Sub Type:	NNN
Company:	200 FREEMAN ST
Contact Title:	
Contact Name:	UNITED METRO FUEL
Address1:	
Address2:	
City:	
State:	NN
Zip Code:	
Country Code:	001
Phone:	(718) 383-1400
Phone Ext:	
Email:	
Fax:	

Affiliation Type:	07
Affiliation Name:	Mail Contact
Affiliation Sub Type:	NNN
Company:	ZAND RIDGE ASSOCIATES, LLC
Contact Title:	PRES.
Contact Name:	MOHSEN ZANDIEH
Address1:	251-12 NORTHERN BLVD.
Address2:	
City:	LITTLE NECK
State:	NY
Zip Code:	11362
Country Code:	001
Phone:	(718) 279-0300
Phone Ext:	
Email:	MOHSEN@OLROUGHREALESTATE.COM
Fax:	

Affiliation Type:	11
Affiliation Name:	Emergency Contact
Affiliation Sub Type:	NNN
Company:	ZAND RIDGE ASSOCIATES, LLC
Contact Title:	
Contact Name:	MOHSEN ZANDIEH
Address1:	
Address2:	
City:	
State:	NN
Zip Code:	
Country Code:	999
Phone:	(718) 279-0300
Phone Ext:	
Email:	
Fax:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
62	1 of1	NNE	0.10 / 547.04	10.74 / -1	FORMER NEY SMELTING AND REFINING COMPANY 269-277 FREEMAN STREET / 230-242 EAGLE ST/ 105 PROVOST STREET BROOKLYN NY 11222	NY SPILLS

Spill No:	1006046	**UST Trust:**	
Site ID:	439383	**Spill Date:**	01/03/2005 12:00:00 PM
DER Facility ID:	394376	**Received Date:**	10/18/2006 12:00:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/05/2010 12:00:00 AM
Water Body:		**Create Date:**	09/01/2010 08:43:00 AM

Class:		**Update Date:**	11/17/2010 09:14:49 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	JBVOUGHT
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Housekeeping		
Reported by:	DEC		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"9/1/10-Vought-As per RTP Associates Phase I ESA dated 1/3/05 and received on 10/18/06: “An oil stain over cracked concrete was also discovered at 263 Freeman” and “there was still oil in the tank” in a fuel oil UST of unknown size at 269 Freeman; (and no PBS registration for Site); Oil stained floor was reported at 242 Eagle Street; Oil stain over cracked concrete reported at 257 Freeman; Oil staining under a truck in the Back Yard;"

DEC Remark:

"8/31/10-Vought-Spill added by Vought after discussion and approval by DEC OConnell due to oil spill on cracked concrete as per Phase I dated 1/3/05 (see below). File review by Vought: As per reports in file, multiple lots are listed under block 2506 including Lots: 19,23,27,30 & 139. As per nyc.gov website alternate address include: 105 Provost Street 269-277 Freeman Street 230-242 Eagle Street Vought searched PBS, CBS, Spills and E-Smart and no additional records found at these addresses. Property owner of 263-269 Freeman and 242 Eagle (Lots 27, 30, 36) as per ACRIS is: Greenpoint Group, LLC. 40 Ash Street Brooklyn, NY 11222 Address of Greenpoint Group as per NYS DOS Corporate Database is: Michael Kustanovich 242 Eagle Street Brooklyn, NY 11222 Current property owner of 238 Eagle (lot 23) is: 238 Eagle Realty Co., LLC 3006 Davis Place Oceanside, NY 11572 Current property owner of Back Yard and 257 Freeman (Lots 19 and 139) are: Sacks Montgomery, P.C 800 Third Avenue New York, NY 10022 Ph: (212) 355-4660 (from Google) Fax: (212) 593-7257 Current info as per Google of Ney Smelting (with same phone number as was registered to 269 Freeman) is: Ney Smelting and Refining 272 Georgia Avenue Brooklyn, NY 11207 Ph:(718)389-4900 Fax:(718)342-5123 email: info@neymetals.com Current info of Belmont Metals (company of Ron Mayer former owner of Ney) as per Google is: Belmont Metals Inc. 330 Belmont Avenue, Brooklyn, NY Ph:(718)342-4900 Fax:(718)342-0715 BCP Pre-App Info Sheet-9/11/06. Phase I Environmental Site Assessment (RTP Environmental Associates – Omar Minnicks-Steven Olivetti- Ph:732-968-9600)-1/3/05. Prepared for Ney Smelting and Refining Company and RTP hired by Verizon Wireless. Site has a parking lot in northwest corner (Back Yard) and a building on the rest of the site. “The building is a combination of five formerly separate buildings with past address of 257-269 Freeman Street and 238-242 Eagle Street. According to Ron Mayer, Ney Smelting took ownership of the property in 1982 and the previous owner was Reliable Machine Company. Nye Smelting's operations at the facility consisted of the smelting of lead, tin and zinc. The operations ceased in 2003. 1887 Sanborn shows that the northern portion of the site has a barrel storage facility and a 3 story building that is used for carpet cleaning and a process involving naptha. 1942 Sanborn shows paint spraying operations in the northern have of the Reliable Machine Company and the 1965 Sanborn shows that paint spraying operations were moved to the southern half of the facility. Report concludes that Recognized Environmental Conditions (REC) include naptha(Yard) and spray painting operations... , a 550 gallon UST under the building floor , oil staining over cracked concrete in two locations... , severly corroded sump surrounded by oil staining , oil staining on basement floor , and monitoring wells bordering the site . Report concludes that additional sampling needs to take place to address all potential RECS. Report recommends tightness testing of UST. 269 FREEMAN: Building contained offices, metal waste, welder, bags of solid sulfur, pallets of metal pipes, “a zinc smelter and two melting machines”. “Mr. Mayer informed RTP that an fuel oil underground storage tank (of unknown size) is located near the main office area” and that “there was still oil in the tank”. Report concludes this tank is 550-gallon UST 263 FREEMAN: Open warehouse with “a smelter in the middle of the area”, locker and break rooms, two 275-gallon ASTs, drums of metal tailings, drums of “head dross”, containers of enamel and oil, machines that handled melted metal. “An oil stain over cracked concrete was also discovered in the area of the Site. 242 EAGLE: Contains first floor and basement. First floor contained bags of ground ceramic with silicate, drums of metal on pallets, drums of hydraulic oil, holes in the floor , flammable storage cabinet with gasoline cans and a gasoline odor . Basement had air compressor, drain surrounded by what appears to be a sump or a berm and two tanks with pumps. In the area of one of the tanks is a sump that is surrounded by an oil stained floor. This sump is severly corroded with water in the drain of the sump 257 FREEMAN: Area contains durms of metal, bags of ground ceramic with silicate, pails of aluminum soldering flux, machines associated with the smelting process and an oil stain over cracked concrete 238 EAGLE:Open warehouse with shelving on eastern side and machinery on western side including a dust collector and grinder, rollers with associated pumps and additional machinery in the northeast corner. BACK YARD: Oil staining under a truck and the staining was on sand that was over a concrete pad that covered part of the site. Yard also contained machine axle, backhoe bucket, metal storage chest, sand piles, dumpster with construction debris. YARD: At the corner of Eagle and Provost. Several rusted drums and an iron pot along the western wall, metal containers in the north central portion and two monitoring wells in the sidewalk immediately northeast of the area. Fred Miller of Entech noted two additonal monitoring wells located immediately north of the Back Yard and he noted wells were installed by sewage treatment plant and that DEP noted to Miller that wells were clean . Phase II Environmental Site Assessment (RTP Associates)-4/28/05. Seven Areas of Concern (AOCs) identified in 1/3/05 Phase I. Seven AOCs included: paint spraying operations at 263 FREEMAN and 238 EAGLE, oil staining over cracked concrete in 257 FREEMAN and 263 FREEMAN, severely corroded sump with oil staining at 242 EAGLE, oil stained sand over concrete in BACK YARD, dumpster possibly used to deposit contaminated materials as well as leak contaminated water in the BACK YARD section of the subject property . (No mention of testing of 550-gallon UST as per Phase I).Site owners requetsed a sample be collected in every section of the building at the site and this sampling was performed in 12/04. Soil samples NS-1S, NS-6 and NS-7 and groundwater sample NS-1W were collected in the 263 FREEMAN Section (NS-1S at paint spraying operations, NS-6 at smelter, NS-7 in smelter pit). One soil sample each was collected from 238 EAGLE (NS-3), 242 EAGLE(corroded sump soil sample NS-4S and groundwater sample NS-4W), 257 FREEMAN(oil stained over cracked concrete soil sample NS-2) and 269 FREEMAN(NS-5) and three soil samples(NS-8, NS-9 and NS-10) collected in BACK YARD. Samples performed via Geoprobe and hand auger. Soil sample analyticals show maximum concentrations of: 71.6ppm Cd(NS-2),1.67ppm Hg(NS-2), 2080ppm Pb(NS-2), 18.6ppm As(NS-2), 50ppm Cr(NS-5), 1460ppm Zn(NS-2). Groundwater analyticals show up to: 531ppb CD(NS-4W)31ppb Hg(NS-4W), 17300ppb Pb(NS-4W), 351ppb As(NS-1W), 1350ppb Cr(NS-4W), 69700ppb Zn(NS-4W), 6ppb PCE(NS-4W). Report concludes that Both groundwater samples were very turbid. Since the soil has elevated concentrations of several heavy metals, then these heavy metals would be present in any groundwater sampling with turbid samples that would take place in the vicinity of these heavy metals. Report recommends well installation at the site, a deed notice as excavation is unfeasible and removal of petroleum stained soil with paving of entire site. Note laboratory methodology does NOT mention filtering of groundwater samples prior to analysis. Tank Removal and Groundwater Sampling Event (RTP Associates)-9/28/05. RTP retained by: Mr. Ron Mayer (former owner of Ney Smelting) Belmont Metals 330 Belmont Avenue

Brooklyn, NY 11207 website:belmontmetals.com Tank removal performed in 7/05. Oil water mixture was encountered in 550-gallon UST at 269 FREEMAN. Tank was excavated and was approximately 2'7 below grade and tank bottom was at 6'bg. Approximately 525 gallons of liquid was removed from the tank, which was then removed from the excavation, cut open and cleaned. Four holes were identified at the eastern end of the tank. One monitoring well installed in 238 EAGLE and samples collected in 4/05, 5/05 and 7/05. Five endpoint soil samples collected from UST excavation. ....no soil staining was observed... . Soil analyticals show minor PAHs attibutable to fill material and no VOCs. Groundwater samples show metal concentrations up to 118ppm in MW1 at 238 EAGLE. Groundwater Sampling Report (PW Grosser Frank Castellano 631-589-6353)-4/19/06. Additional groundwtaer sampling was performed as well as to serve to clarify the sampling locations performed as by RTP as part of their Phase II ESA . Based on written text of RTP Phase II ESA PWGC has estimated the locations of the groundwater as well as the soil samples from the RTP Phase II which are depicted in the attached figure . As depicted in the figure, the two groundwater samples collected by RTP were collected from the neighboring properties and not the subject property . (Note: RTP report was for all Ney Smelting and Refining Operations not just 269 Freeman Street). Report noted problem with assessing groundwater via collection of very turbid samples . PG Grosser collected five soil samples across Site. Depth to groundwater is 10'bg. Two groundwater samples collected from each boring (one to be filtered and second to be non-filtered . Filtering performed in lab and following groundwater samples are of filtered samples. Groundwater analyticals show same magnitude of metal contamination in non-filtered groundwater samples as RTP Phase II. Filtered groundwater samples show no TOGs 1.1.1 exceedences for metals except for manganese and sodium (expected due to close saltwater body). In summary, the elevated metal concentrations reported in the RTP Phase II ESA Report resulted from the presence of sediment particles in the groundwater samples and are not representative of a groundwater contamination issue . 9/2/10-Vought-Completed file review and sent email with Site plans and UIS notes to DEC Cozzy and O'Connell for P-Site status confirmation. E-doc'd entire file. DEC O'Connell also ntoed that EPA EnviroFacts sheet noted cadmium use and disposal on-site. DEC Cozzy agreed that site should be listed as P-Site and EPA info should be included as part of P-Site package. 9/7/10-Vought-Site visit by Vought and occupying 263-277 Freeman Street/242 Eagle and Yard is Aleta Group which manufactures air conditioning duct work and accessories. Phone number for Aleta Group is 718-349-0040. 238 Eagle Street is occupied by Abbott Paint & Varnish(Ph:718-349-2112) who distribute wood, display, faux, floor and theatrical coating supplies . Found following information via Google of current site occupant (Aleta Group, LLC.) The New York City Industrial Development Agency (the “Agency”) is empowered under the New York State Industrial Development Agency Act (constituting Title 1 of Article 18-A of the General Municipal Law), and Chapter 1082 of the 1974 Laws of New York, as amended, to issue nonrecourse revenue bonds to provide financing for qualified projects, and to enter into industrial and small industry incentive program transactions and other straight-lease transactions for the benefit of qualified projects, and thereby advance the job opportunities, general prosperity and economic welfare of the people of the State of New York (the “State”) and to improve their prosperity and standard of living. The Agency has been requested (i) to make available the proceeds of its bonds to be issued in the approximate aggregate dollar amounts, to be used by the persons, for the purposes, and at the addresses identified below, and (ii) to participate in industrial and small industry incentive program straight-lease transactions and other straight-lease transactions for the purposes and at the addresses also identified below. As used herein, “bonds” are bonds, the interest on which may be exempt from local and/or State and/or Federal income taxes; and the “City” shall mean The City of New York. As used herein with reference to bond amounts, “approximately” shall be deemed to mean up to such stated bond amount or a greater principal amount not to exceed 10 % of such stated bond amount. Straight-lease (Industrial Incentive Program) transaction for Greenpoint Group LLC, a real estate holding company, for the benefit of Aleta Industries Inc. and Aleta Group, Inc., a manufacturer and installer of air conditioning duct work and accessories, in connection with the acquisition, renovation and equipping of: (1) an approximately 7,400 square foot building located on an approximately 7,400 square foot parcel of land, located at 263-267 Freeman Street, Brooklyn, New York; (2) an approximately 8,000 square foot building located on an approximately 12,500 square foot parcel of land, located at 269-277 Freeman Street, Brooklyn, New York; and (3) an approximately 2,500 square foot building located on an approximately 10,000 square foot parcel of land, located at 242-252 Eagle Street, Brooklyn, New York. The financial assistance proposed to be conferred by the Agency will consist of payments in lieu of City real property taxes, exemption from City and State mortgage recording taxes and exemption from City and State sales and use taxes. 9/8/10-Vought-P-Site memo sent to DEC O'Connell, Nagi and NYDOH Bates. 9/14/10-Vought-Received call from current site rep of 242 Eagle: Mr. Michael Kustanovich Ph: 718-349-0040x101 email:aletaind@aol.com and discussed soil and groundwater analyticals and emailed him FOIL request. Vought told him that after discussion with supervision, that he may be calling Kust for more investigation and/or information. 9/17/10-Vought-Sent email request for site code to DEC Barrie including latitude, longitude and acreage of site. Vought received reply email from DEC Barrie that UIS Remediaton Site Code is 224144 and T&A Code is 65709. Vought to complete UIS Remediation database and administratively close this spill with referral to open Remediation Case. 10/5/10-Vought-This spill administratively closed by Vought and referred to open remediation case #224144. "

Material Information

OP Unit ID:	1190028	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2184995	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0577A		
Material Name:	heavy metals		

OP Unit ID:	1190028	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2184994	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	True
Units:	G	***Med Subway:***	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Recovered:
Med Soil: False
Med Air: False
Material Code: 0001A
Material Name: #2 fuel oil
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: NEY SMELTING AND REFINING COMPANY
Spiller Address: 269 FREEMAN STREET
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip: 11222
Spiller Country: 999
Contact Name: GREENPOINT GROUP LLC
Contact Phone:
Contact Ext:
Latitude:
Longitude:

63	1 of1	NNE	0.10 / 553.45	10.55 / -1	Former Ney Smelting and Refining Company 269 Freeman Street Greenpoint NY 11222	SHWS

Site Code: 439622
HW Code: 224144
Program: HW
Site Class: N
Site Name: Former Ney Smelting and Refining Company
Site Address: 269 Freeman Street
City: Greenpoint
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.735353847
Longitude: -73.950527001
SWIS: 2401
Acres: 1.200
Record Added: 2010-09-08 15:48:00
Record Update: 2013-10-31 16:07:00
Updated by: MJKOMORO
Site Code (Web): 224144
Program Type (Web): HW
Site Name (Web): Former Ney Smelting and Refining Company
Site Class (Web): N
Address1 (Web): 269 Freeman Street
Address2 (Web):
Locality (Web): Greenpoint
Zip Code (Web): 11222
County (Web): Kings
Longitude (Web): -73.950527001
Latitude (Web): 40.735353847
Site Code (GIS): 224144
Site Name (GIS): Former Ney Smelting and Refining Company
Program (GIS): HW
Site Class (GIS): N
Address1 (GIS): 269 Freeman Street
Address2 (GIS):
Locality (GIS): Greenpoint
Zip Code (GIS): 11222
County (GIS): Kings
Site Class Desc: No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does

not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Site Class Desc (Web): No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH:
Description:

Location: The Site is located across multiple addresses in the Greenpoint section of Brooklyn, NY. The addresses for the Site include 257, 259, 263, & 269 Freeman Street and 230, 238, 242 Eagle Street. 269 Freeman Street is also known as 105 Provost Street. The Newtown Creek Water Pollution Control Plant (WPCP) is located directly east of the Site. Site Features: The original Site encompassed five separate buildings and three yards that occupy seven separate lots. The buildings are no more than 2 stories in height. The entire Site is approximately 1.2 acres in size. There are manufacturing buildings to the north, south and west of the Site. Current Zoning/Uses: The area (and properties) is zoned M3-1 which includes heavy manufacturing and industrial uses along with certain commercial uses. Properties on the site are currently used for the manufacturing of air conditioning duct work, a distribution center for paint and varnish, parking, and staging of various contracting equipment. - 263-269 Freeman and 242 Eagle Street are currently used for the manufacturing of air conditioning duct work and accessories - 238 Eagle street is currently used for the distribution of paint and varnish. - The Yard portion east of 238 Eagle Street is currently an unused dirt yard. Historical Uses: In the early 1900?s the site was used as a cooperage for wooden barrel and cask production. From approximately 1942 to 1982, the property was occupied by Reliable Machine Company that had numerous paint spraying locations on the property. In 1982, Ney Smelting and Refining Company took ownership of the property in 1982 and renovated the buildings and used the property for smelting of lead, tin and zinc. Smelting operations ceased in 2003. Site Geology and Hydrogeology: Shallow boring logs indicate the Site overlies historic fill. The soil type below the fill is not known. Depth to groundwater is approximately 10 feet below grade and may be tidally influenced due to the close proximity to the Newtown Creek. Groundwater flow may also be affected by the adjacent Newtown Creek WPCP. Groundwater flow direction is estimated to be to the northeast Miscellaneous: There are no PBS, CBS records for the multiple addresses of the Site.

Assessment:

The site is covered with multiple buildings and parking facilities. One small area of the site contains a dirt construction yard that is largely underlain by a concrete slab. The shallow subsurface soil is comprised of historic fill that contains building debris such as brick and concrete, ash, and soil. This material contains elevated concentrations of inorganics that are generally below allowable concentrations at industrial sites. SVOCs are also present in the soil at the site but also do not exceed standards for industrial areas. No VOCs were detected at levels that cause concern. Data from TCLP analyses were all below hazardous waste thresholds. Groundwater is sporadically impacted by PCE and breakdown products. There is no continuous plume of impacted groundwater as would be observed if a source of PCE was present.

Owner Information

Owner Op:	01
Sub Type:	03
Owner Name:	Herb Lowenstein
Owner Company:	238 Eagle Realty Co. LLC.
Owner Street:	3006 Davis Pl

Owner Street 2:
Owner City: Oceanside
Owner State: NY
Owner Zip: 11572
Country: United States of America

Owner Op: 04
Sub Type: 09
Owner Name: Haim Boiangiu
Owner Company: Abbot Paint & Varnish
Owner Street: 238 Eagle St.
Owner Street 2:
Owner City: Green Point
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 01
Sub Type: 02
Owner Name: Greenpoint Group, LLC
Owner Company: Greenpoint Group, LLC
Owner Street: 269 Freeman Street
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 04
Sub Type: 03
Owner Name: Michael Kustanovich
Owner Company: Aleta Group, Inc.
Owner Street: 242 Eagle Street
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 01
Sub Type: 03
Owner Name: Geno Camali
Owner Company: 259 Freeman, LLC
Owner Street: 304 Harrington Ave
Owner Street 2:
Owner City: Closter
Owner State: NJ
Owner Zip: 07624
Country: United States of America

Projects Information

Project Code: 01
Project Desc: Site Caracterization
Project Refer Name:
End Date: 2013-04-11 00:00:00
End Status: ACT
Operable Unit ID: 1190257
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Site Characterization

Environmental Remediation

Operable Unit: 01
Contaminants: cadmium

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
64	1 of2	NNW	0.11 / 560.68	11.01 / -1	RESIDENTIAL 366 MCGUINNESS BLVD BROOKLYN NY	NY SPILLS

Spill No:	2305899	**UST Trust:**	False
Site ID:	657866	**Spill Date:**	10/09/2023 05:00:00 PM
DER Facility ID:	603407	**Received Date:**	10/09/2023 07:32:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/10/2023 12:00:00 AM
Water Body:		**Create Date:**	10/09/2023 07:36:00 PM
Class:		**Update Date:**	10/10/2023 09:37:12 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	RHLIN
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Traffic Accident		
Reported by:	Other		
Referred to:			
Source:	Passenger Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Car hit a fire hydrant, pieced the fuel tank / only affected roadway and catch basin / Cleanup pending"

DEC Remark:

"10/10/23-Lin-Duplicate spill. Refer to spill#2305894."

Material Information

OP Unit ID:	1404747	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2421841	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	10.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	ALEX ASTRO
Spiller Company:	UKNOWN
Spiller Address:	366 MCGUINNESS BLVD
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	ALEX ASTRO
Contact Phone:	(347) 865-1238
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
64	2 of2	NNW	0.11 / 560.68	11.01 / -1	ROADWAY 366 MCGUINNESS BLVD BROOKLYN NY	NY SPILLS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spill No:	2305891	**UST Trust:**	False
Site ID:	657858	**Spill Date:**	10/09/2023 02:00:00 PM
DER Facility ID:	603407	**Received Date:**	10/09/2023 03:52:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/31/2023 12:00:00 AM
Water Body:		**Create Date:**	10/09/2023 03:56:00 PM
Class:		**Update Date:**	10/31/2023 02:13:03 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	HSSEKHON
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Human Error		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Some entered the catch basin/roadway / Cleanup pending /"

DEC Remark:

"10/10/23-Lin-According to OEM, a truck hit a hydrant causing the saddle tank to leak 40 to 50 gallons of diesel onto the roadway and catch basin. DEP was notified and FD secured the leak. DEC Sekhon responded. 10/10/23 - Sekhon Site inspected on 10/9 (PM). Speedy dry observed onto affected area. A car was parked onto drain. Not able to see any oil into the catch basin. DEC Austin updated. 10/17/23 - Sekhon DEP Alex called and told that DEP found oil in the catch basin. DEP & DEC will Site visit on 10/23/23. 10/19/23 - Sekhon The Responsible company name is: Stone Express Inc. 99 Dell Glen Avenue Lodi, NJ 07644; (973)767-2454 Contact person: Jamie Pizza at jamie@stonextrucking.com Jamie told that spill cleaned up on 10/18 and she will email closure documents. Report provided. DECDOCS 10/31/23 -Sekhon Submitted report reviewed and accepted. Case closed."

Material Information

OP Unit ID:	1404739	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2421832	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	7.00	**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	MOSES
Spiller Company:	UNKOWN
Spiller Address:	366 MCGUINNESS BLVD
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	MOSES
Contact Phone:	(917) 612-5299
Contact Ext:	
Latitude:	
Longitude:	

65	1 of1	SW	0.11 / 562.14	13.68 / 2	203 JAVA ST. 203 JAVA ST BROOKLYN NY	LST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spill No:	9303193	**REM Phase:**	0
Site ID:	177715	**UST Trust:**	False
DER Facility ID:	149323	**Spill Date:**	06/10/1993 11:45:00 AM
CID:		**Rcvd Date:**	06/10/1993 12:07:00 PM
Program Type:	ER	**CAC Date:**	06/10/1993 12:00:00 AM
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Failure	**Close Date:**	06/10/1993 12:00:00 AM
Water Body:		**Create Date:**	06/11/1993 12:00:00 AM
Class:	D3	**Update Date:**	07/19/1993 12:00:00 AM
Meets Std:	True	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	KSTANG
County:	Kings	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Private Dwelling		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"SPILL ON DIRT FLOOR (CELLAR) - SORBENT APPLIED - TANK SIHING DIRECTLY ON DIRT."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG. "

Material Information

OP Unit ID:	981368	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	396785	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	1.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	WASHCYSHYN REC.
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.731857130
Longitude:	-73.952489960

66	*1 of2*	*N*	*0.11 / 569.08*	*10.99 / -1*	***CON EDISON SERVICE BOX: 7251 220 EAGLE ST BROOKLYN NY 11222***	***RCRA NON GEN***

EPA Handler ID:	NYP004395091
Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	

Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20131220
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20131120
Handler Name: CON EDISON SERVICE BOX: 7251
Source Type: Emergency
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20131220
Handler Name: CON EDISON SERVICE BOX: 7251
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20131120
Generator Code Description: Very Small Quantity Generator
Handler Name: CON EDISON SERVICE BOX: 7251

66	2 of2	N	0.11 / 569.08	10.99 / -1	CON EDISON 220 EAGLE ST SB7251	GEN MANIFEST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

BROOKLYN NY 11217

RCRA ID:	NYP004395091	**Mailing State:**	NY
District Name:	CON EDISON	**Mailing ZIP:**	10003
Contact Name:	CON EDISON	**Mailing ZIP Ext:**	
Business Phone No:		**Mailing Country:**	USA
Mailing Street 1:	4 IRVING PLACE	**Location ZIP Ext:**	
Mailing Street 2:	15TH FL	**Location Country:**	USA
Mailing City:	NEW YORK	**Location County:**	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2013: 40 Gallons

67	1 of1	NNW	0.11 / 569.30	10.80 / -1	PRIVATE RESIDENCE 214 EAGLE STREET NY	NY SPILLS

Spill No:	1213916	**UST Trust:**	
Site ID:	477133	**Spill Date:**	12/27/2012 11:23:00 AM
DER Facility ID:	432574	**Received Date:**	12/27/2012 11:23:00 AM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	12/27/2012 12:00:00 AM
Water Body:		**Create Date:**	12/27/2012 11:41:00 AM
Class:		**Update Date:**	12/28/2012 12:34:42 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	HRPATEL
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Affected Persons		
Referred to:			
Source:	Private Dwelling		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"During Newtown Creek meeting, Juan Falcon reported gas smell coming through his basement."

DEC Remark:

"12/27/12-Hiralkumar Patel. on 12/20/12, DEC Venetia received email from Wanda Ayala, Community Involvement Coordinator at EPA. Ms. Ayala mentioned that during the newtown creek meeting, Juan Falcon (who lives at 214 Eagle Street) reported gas smell in his basement. Mr. Falcon has called 311 on various occassions, but they have not been able to assist him because the smell is not constant (it dissipates) so it's difficult to pinpoint a source. due to ongoing oil spill remediation in greepoint area, EPA requested DEC to test the home. Wanda Ayala Community Involvement Coordinator Public Affairs Division Ph. (212) 637-3676 me and DEC Vought spoke with Mr. Falcon today. in past, he noted smell in his building similar to paint thinner and smell comes once a month or once a three month. currently, there is no smell in his house. he has gas heating sytem in building. recently, his basement was flooded with water during Sandy. he also mentioned that there is a paint shop on the same block, which used to make paint in past. Mr. Falcon requested a site inspection. scheduled a site inspection at 4 PM today. during search, found Abbott Paint & Varnish shop at 238 Eagle Street. Abbott Paint & Varnish 238 Eagle Street Brooklyn, NY Ph. (718) 349-2112 4:00 PM:- visited site. met Mr. Falcon. inspected building basement. noted strong sewer smell in basement upon arrival. no petroleum or chemical odors noted. basement was under renovation as was damaged during storm. Mr. Falcon mentioned that couple of year ago, he himself installed a flap in sewer line due to sewer backup problem. suggested him hire licensed plumber to inspect and correct any problems with sewer line as that may be the source of odors in basement. based on observations during the site visit and discussion with Mr. Falcon, case closed."

Material Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OP Unit ID:	1226943	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2224351	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	True		
Material Code:	0064A		
Material Name:	unknown material		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	
Spiller State:	
Spiller Zip:	
Spiller Country:	
Contact Name:	JUAN FALCON
Contact Phone:	(718) 349-3599
Contact Ext:	
Latitude:	40.735422000
Longitude:	-73.951562000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
68	1 of1	SSW	0.11 / 581.54	13.31 / 1	CON EDISON JAVA ST & MCGUINESS BLVD BROOKLYN NY 11234	RCRA NON GEN

EPA Handler ID:	NYP004791919
Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20150609
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150609
Handler Name: CON EDISON
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150609
Handler Name: CON EDISON
Source Type: Emergency
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Historical Handler Details

Receive Dt: 20150609
Generator Code Description: Large Quantity Generator
Handler Name: CON EDISON

69	1 of3	SE	0.11 / 603.40	11.29 / -1	Skanska/Picone JV II 252 Java St. Brooklyn, NY 11222 NY	TIER 2

Company Name:
DUN Bradstreet Cd:
County:
Latitude:
Longitude:
Report Method: Reported via Mail

69	2 of3	SE	0.11 / 603.40	11.29 / -1	Welsbach Electric Corp. 252 Java St. Brooklyn, NY 11222 NY	TIER 2

Company Name:
DUN Bradstreet Cd:
County:
Latitude:
Longitude:
Report Method: Reported via Mail

69	3 of3	SE	0.11 / 603.40	11.29 / -1	Welsbach Electrical Corp. 252 Java St., Brooklyn, NY 11222 (REVISION)	TIER 2

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					NY	

Company Name:
DUN Bradstreet Cd:
County:
Latitude:
Longitude:
Report Method: Reported via Mail

70	1 of2	SSE	0.12 / 621.01	12.24 / 0	CON EDISON 234 JAVA ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004847406
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20151002
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20151002
Handler Name: CON EDISON
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20151002
Handler Name: CON EDISON
Source Type: Emergency
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Historical Handler Details

Receive Dt: 20151002
Generator Code Description: Small Quantity Generator
Handler Name: CON EDISON

---

70 | ***2 of2*** | ***SSE*** | ***0.12 / 621.01*** | ***12.24 / 0*** | ***CON ED 234 JAVA ST SB 56190 BROOKLYN NY 11222*** | ***GEN MANIFEST***

RCRA ID: NYP004847406
District Name: CON ED
Contact Name: TOM TEELING
Business Phone No: 2124603770
Mailing Street 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Street 2:
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 100 Gallons

---

71 | ***1 of3*** | ***SSE*** | ***0.12 / 632.24*** | ***12.05 / 0*** | ***CON EDISON FRONT OF 238 JAVA ST SB56190 BROOKLYN NY 11222*** | ***GEN MANIFEST***

RCRA ID: NYP004602843
District Name: CON EDISON
Contact Name: CON EDISON
Business Phone No:
Mailing Street 1: 4 IRVING PL
Mailing Street 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2014: 50 Gallons

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
71	2 of3	SSE	0.12 / 632.24	12.05 / 0	CON EDISON 238 JAVA SB 56190 BROOKLYN NY	GEN MANIFEST

RCRA ID:	NYP004791919	**Mailing State:**	NY
District Name:	CON EDISON	**Mailing ZIP:**	10003
Contact Name:	DENNIS HUACON	**Mailing ZIP Ext:**	
Business Phone No:	2124603770	**Mailing Country:**	USA
Mailing Street 1:	4 IRVING PL 15TH FL	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	NEW YORK	**Location County:**	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 1000 Pounds

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
71	3 of3	SSE	0.12 / 632.24	12.05 / 0	CON EDISON 238 JAVA ST SB 56190 BROOKLYN NY	GEN MANIFEST

RCRA ID:	NYP004798773	**Mailing State:**	NY
District Name:	CON EDISON	**Mailing ZIP:**	10003
Contact Name:	DENNIS HUACON	**Mailing ZIP Ext:**	
Business Phone No:	2124603770	**Mailing Country:**	USA
Mailing Street 1:	4 IRVING PL 15TH FL	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	NEW YORK	**Location County:**	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 50 Gallons

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
72	1 of2	S	0.12 / 632.43	12.66 / 1	CON EDISON 230 JAVA ST & MCGUINESS BLVD BROOKLYN NY 11235	RCRA NON GEN

EPA Handler ID:	NYP004798765
Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20150624
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150624
Handler Name:	CON EDISON
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150624
Handler Name:	CON EDISON
Source Type:	Emergency
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Historical Handler Details

Receive Dt:	20150624
Generator Code Description:	Small Quantity Generator
Handler Name:	CON EDISON

72	*2 of2*	*S*	*0.12 / 632.43*	*12.66 / 1*	***CON EDISON 230 JAVA ST MH 8636 BROOKLYN NY***	***GEN MANIFEST***

RCRA ID:	NYP004798765	***Mailing State:***	NY
District Name:	CON EDISON	***Mailing ZIP:***	10003
Contact Name:	DENNIS HUACON	***Mailing ZIP Ext:***	
Business Phone No:	2124603770	***Mailing Country:***	USA
Mailing Street 1:	4 IRVING PL 15TH FL	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	NEW YORK	***Location County:***	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 150 Gallons

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
73	1 of1	S	0.12 / 637.65	13.28 / 1	GREENPOINT NATIONAL GARAGE INC 276 MC GUINNESS BLVD BROOKLYN NY 11222	UST

Site ID:	9389	***Expiry:***	N/A
Site Status:	Unregulated/Closed	***County:***	Kings
Program No:	2-243582	***UTM X:***	588527.66808
Program Type Code:	PBS	***UTM Y:***	4509498.73491
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Unknown		

Tank Information

Prog No:	2-243582	***UDC Ind:***	1
Tank ID:	10348	***Red Tag Start Date:***	
Tank No:	002	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	12/01/1932	***Next Test:***	
Close Date:	09/01/1993	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Material Information

Material Name:	gasoline
Percent:	100.00

Equipment Information

Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection

Equipment:	F00
Code Name:	None
Type:	Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Tank Information

Prog No:	2-243582	**UDC Ind:**	1
Tank ID:	10350	**Red Tag Start Date:**	
Tank No:	004	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1952	**Next Test:**	
Close Date:	09/01/1993	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	275	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: H00
Code Name: None

Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Tank Information

Prog No:	2-243582	***UDC Ind:***	1
Tank ID:	10349	***Red Tag Start Date:***	
Tank No:	003	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	12/01/1952	***Next Test:***	
Close Date:	09/01/1993	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Tank Information

Prog No:	2-243582	***UDC Ind:***	1
Tank ID:	10347	***Red Tag Start Date:***	
Tank No:	001	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	12/01/1952	***Next Test:***	
Close Date:	09/01/1993	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	1080	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Affiliation Information

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: GREENPOINT NATIONAL GARAGE INC
Contact Title:
Contact Name: LEON & DAVID YABOZ
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-1131
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: ZZZ
Company: LEON & DAVID YABOZ
Contact Title:
Contact Name:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Address1: 239 JAVA ST
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 389-1131
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: LEON & DAVID YABOZ
Contact Title:
Contact Name: LEON & DAVID YABOZ
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-1131
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: LEON & DAVID YABOZ
Contact Title:
Contact Name:
Address1: 239 JAVA ST
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 389-1131
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
74	1 of2	S	0.12 / 637.70	13.28 / 1	GREENPOINT NATIONAL GARAGE INC 276 MCGUINNESS BLVD BROOKLYN NY 11222-1811	RCRA NON GEN

EPA Handler ID: NY0000080176
Gen Status Universe: No Report
Contact Name:
Contact Address: 239 , JAVA ST , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 40.731546
Location Longitude: -73.951737
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date: 19980728
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19931217
Handler Name: GREENPOINT NATIONAL GARAGE INC
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990708
Handler Name: GREENPOINT NATIONAL GARAGE INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: GREENPOINT NATIONAL GARAGE INC
Source Type: Implementer

Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: GREENPOINT NATIONAL GARAGE INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: GREENPOINT NATIONAL GARAGE
Date Became Current:
Date Ended Current:
Phone: 718-389-1131
Source Type: Implementer
Street No:
Street 1: 239 JAVA ST
Street 2:
City: BROOKLYN
State: NY
Country: US
Zip Code: 11222

Owner/Operator Ind: Current Owner
Type: Private
Name: GREENPOINT NATIONAL GARAGE
Date Became Current:
Date Ended Current:
Phone: 718-389-1131
Source Type: Notification
Street No:
Street 1: 239 JAVA ST
Street 2:
City: BROOKLYN
State: NY
Country:
Zip Code: 11222

Owner/Operator Ind: Current Operator
Type: Private
Name: GREENPOINT NATIONAL GARAGE
Date Became Current:
Date Ended Current:
Phone: 718-389-1131
Source Type: Implementer
Street No:
Street 1: 239 JAVA ST
Street 2:
City: BROOKLYN
State: NY
Country: US
Zip Code: 11222

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: GREENPOINT NATIONAL GARAGE INC

Receive Dt: 19990708
Generator Code Description: Not a Generator, Verified
Handler Name: GREENPOINT NATIONAL GARAGE INC

Receive Dt: 19931217
Generator Code Description: Small Quantity Generator
Handler Name: GREENPOINT NATIONAL GARAGE INC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
74	2 of2	S	0.12 / 637.70	13.28 / 1	GREENPOINT NATIONAL GARAGE INC 276 MCGUINNESS BLVD BROOKLYN NY	GEN MANIFEST

RCRA ID: NY0000080176
District Name: GREENPOINT NATIONAL GARAGE INC
Contact Name: GREENPOINT NATIONAL GARAGE INC
Business Phone No: 7183891131
Mailing Street 1: 239 AVA STREET
Mailing Street 2:
Mailing City: BROOKLYN
Mailing State: NY
Mailing ZIP: 11222
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1993: 275 Gallons

75	1 of1	NNE	0.12 / 638.81	10.38 / -2	ABANDONED DRUMS 242 EAGLE ST BROOKLYN NY	NY SPILLS

Spill No:	0203069	***UST Trust:***	False
Site ID:	247407	***Spill Date:***	06/23/2002 11:50:00 AM
DER Facility ID:	203147	***Received Date:***	06/23/2002 12:55:00 PM
CID:	322	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	08/02/2002 12:00:00 AM
Water Body:		***Create Date:***	06/23/2002 12:00:00 AM
Class:	C3	***Update Date:***	08/31/2010 01:09:32 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	JBVOUGHT
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Abandoned Drums		
Reported by:	Local Agency		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"2 55 gal drums -moved out of the street and now sitting on the sidewalk - the drums are not leaking "

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT Drum Emptied 8/02/2002 REF#9930008 PIN#01036"

Material Information

OP Unit ID:	853906	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	520897	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	110.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	110.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		

Spiller Information

Spiller Name:	
Spiller Company:	UNK -
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.735392750
Longitude: -73.951972630

---

76 | **1 of1** | **W** | **0.12 / 649.70** | **13.30 / 1** | **CON EDISON**
FRONT OF 183 HURON ST SB7498
BROOKLYN NY 11222 | **GEN MANIFEST**

RCRA ID: NYP004717781
District Name: CON EDISON
Contact Name: CON EDISON
Business Phone No:
Mailing Street 1: 4 IRVING PL
Mailing Street 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 40 Gallons

---

77 | **1 of175** | **NE** | **0.12 / 649.95** | **9.75 / -2** | **CON EDISON - NEWTOWN CRK WTR POLL PLT**
329 GREENPOINT AVE ELECTRIC SERVICE AREA
BROOKLYN NY 11222-1901 | **RCRA NON GEN**

EPA Handler ID: NY0000228049
Gen Status Universe: No Report
Contact Name:
Contact Address: 4 , IRVING PL ROOM 300 , , NEW YORK , NY, 10003 , US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20070101
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date: 19990901
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19940419
Handler Name:	CON EDISON - NEWTOWN CRK WTR POLL PLT
Source Type:	Notification
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Waste Code Details

Hazardous Waste Code:	D003
Waste Code Description:	REACTIVE WASTE

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19990708
Handler Name:	CON EDISON - NEWTOWN CRK WTR POLL PLT
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20060101
Handler Name:	CON EDISON - NEWTOWN CRK WTR POLL PLT
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	3
Receive Date:	20070101
Handler Name:	CON EDISON - NEWTOWN CRK WTR POLL PLT
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	59-17 JUNCTION BLVD
Name:	NYC DEPT OF ENVIRON PROTECTION	***Street 2:***	
Date Became Current:		***City:***	CORONA
Date Ended Current:		***State:***	NY
Phone:	718-595-5043	***Country:***	
Source Type:	Notification	***Zip Code:***	11368

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	59-17 JUNCTION BLVD
Name:	NYC DEPT OF ENVIRON PROTECTION	***Street 2:***	
Date Became Current:		***City:***	CORONA
Date Ended Current:		***State:***	NY
Phone:	718-595-5043	***Country:***	US
Source Type:	Implementer	***Zip Code:***	11368

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	59-17 JUNCTION BLVD
Name:	NYC DEPT OF ENVIRON PROTECTION	***Street 2:***	
Date Became Current:		***City:***	CORONA
Date Ended Current:		***State:***	NY
Phone:	718-595-5043	***Country:***	US
Source Type:	Implementer	***Zip Code:***	11368

Historical Handler Details

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	CON EDISON - NEWTOWN CRK WTR POLL PLT

Receive Dt:	19990708
Generator Code Description:	Not a Generator, Verified
Handler Name:	CON EDISON - NEWTOWN CRK WTR POLL PLT

Receive Dt:	19940419
Generator Code Description:	Large Quantity Generator
Handler Name:	CON EDISON - NEWTOWN CRK WTR POLL PLT

77	***2 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***EXXON CO USA-BROOKLYN TERMINAL 320 FREEMAN ST BROOKLYN NY 11222-1213***	***RCRA NON GEN***

EPA Handler ID:	NYD063855746
Gen Status Universe:	No Report
Contact Name:	
Contact Address:	320 , FREEMAN ST , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:	
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	
Receive Date:	20070101
Location Latitude:	40.734704
Location Longitude:	-73.9482
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS;

Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date: 19980901
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19930409
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19851107
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19800818
Handler Name: EXXON CO USA-BROOKLYN TERMINAL
Source Type: Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 1

Receive Date: 19920218
Handler Name: EXXON CO USA
Source Type: Annual/Biennial Report
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990708
Handler Name: EXXON CO USA-BROOKLYN TERMINAL
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: EXXON CO USA-BROOKLYN TERMINAL
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: EXXON CO USA-BROOKLYN TERMINAL
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: EXXON COMPANY USA
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: EXXON COMPANY USA
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: EXXON COMPANY USA
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Notification
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country:
Zip Code: 99999

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified

Handler Name: EXXON CO USA-BROOKLYN TERMINAL

Receive Dt: 19990708
Generator Code Description: Not a Generator, Verified
Handler Name: EXXON CO USA-BROOKLYN TERMINAL

Receive Dt: 19920218
Generator Code Description: Large Quantity Generator
Handler Name: EXXON CO USA

Receive Dt: 19800818
Generator Code Description: Large Quantity Generator
Handler Name: EXXON CO USA-BROOKLYN TERMINAL

77	3 of175	NE	0.12 / 649.95	9.75 / -2	NYCDEP BWT NEWTOWN CREEK WPCP 329 GREENPOINT AVE BROOKLYN NY 11222	RCRA SQG

EPA Handler ID: NYD980779730
Gen Status Universe: Small Quantity Generator
Contact Name: ZAINOOL ALI
Contact Address: 329 , GREENPOINT AVE , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext: 718-389-2002
Contact Email: ZALI@DEP.NYC.GOV
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type: Municipal
Receive Date: 20140805
Location Latitude: 40.731077
Location Longitude: -73.947414
Recycler Activity(YES/NO)?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Oct, 2024.

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: TSD - General
Violation Type: 264.A
Violation Determined Date: 20101021
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20110223
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20101029
Enf Disposition Status: ACTION SATISFIED (CASE CLOSED)
Disposition Status Date: 20110304
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: TSD IS-General Facility Standards
Violation Type: 265.B
Violation Determined Date: 20101021
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20110223
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20101029
Enf Disposition Status: ACTION SATISFIED (CASE CLOSED)
Disposition Status Date: 20110304
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: TSD IS-Preparedness and Prevention
Violation Type: 265.C
Violation Determined Date: 20101021
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20110223
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20101029
Enf Disposition Status: ACTION SATISFIED (CASE CLOSED)
Disposition Status Date: 20110304
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: TSD IS-Contingency Plan and Emergency Procedures
Violation Type: 265.D
Violation Determined Date: 20101021
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20110223
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120

Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20101029
Enf Disposition Status: ACTION SATISFIED (CASE CLOSED)
Disposition Status Date: 20110304
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Universal Waste - Small Quantity Handlers
Violation Type: 273.B
Violation Determined Date: 20101021
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20101021
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20101029
Enf Disposition Status: ACTION SATISFIED (CASE CLOSED)
Disposition Status Date: 20110304
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Universal Waste - Small Quantity Handlers
Violation Type: 273.B
Violation Determined Date: 20101021
Scheduled Compliance Date:
Return to Compliance: Observed
Actual Return to Compl: 20101021
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20101029
Enf Disposition Status: ACTION SATISFIED (CASE CLOSED)
Disposition Status Date: 20110304
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation: SR - 373-3.2(g)(4),373-3.3(g)(1)
Violation Short Description: Generators - General
Violation Type: 262.A

Violation Determined Date: 20020923
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20021220
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20021007
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - Records/Reporting
Violation Type: 262.D
Violation Determined Date: 19980813
Scheduled Compliance Date:
Return to Compliance: Observed
Actual Return to Compl: 19981201
Violation Responsible Agency: EPA

Evaluation Details

Evaluation Start Date: 20101021
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description: TSD IS-General Facility Standards
Return to Compliance Date: 20110223
Evaluation Agency: State

Evaluation Start Date: 20101021
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description: TSD - General
Return to Compliance Date: 20110223
Evaluation Agency: State

Evaluation Start Date: 20101021
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description: TSD IS-Preparedness and Prevention
Return to Compliance Date: 20110223
Evaluation Agency: State

Evaluation Start Date: 20101021
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description: TSD IS-Contingency Plan and Emergency Procedures
Return to Compliance Date: 20110223
Evaluation Agency: State

Evaluation Start Date: 20101021
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description: Universal Waste - Small Quantity Handlers
Return to Compliance Date: 20101021
Evaluation Agency: State

Evaluation Start Date: 20020923
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description: Generators - General

Return to Compliance Date: 20021220
Evaluation Agency: State

Evaluation Start Date: 19990811
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description: Generators - Records/Reporting
Return to Compliance Date: 19981201
Evaluation Agency: EPA

Evaluation Start Date: 19980301
Evaluation Type Description: NON-FINANCIAL RECORD REVIEW
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19940121
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA Contractor/Grantee

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity W.O. Stor: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19841025
Handler Name: NEWTOWN CREEK WATER POLLUTION CONTROL
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: X002
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19981130
Handler Name: NYC DEPT OF ENVIRONMENTAL PROTECTION
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990729
Handler Name: NEWTOWN CREEK WATER POLLUTION CONTROL
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Implementer

Waste Code Details

Hazardous Waste Code: NONE
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20010101
Handler Name: NEWTOWN CREEK WPCP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20020417
Handler Name: NEWTOWN CREEK WPCP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20040305
Handler Name: NYCDEP BWT NEWTOWN CREEK WPCP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060223
Handler Name: NYCDEP BWT - NEWTOWN CREEK WPCP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20060224
Handler Name: NYCDEP BWT - NEWTOWN CREEK WPCP

Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: NYCDEP BWT - NEWTOWN CREEK WPCP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20080227
Handler Name: NYC DEP BWT NEWTOWN CREEK WPCP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: B007
Waste Code Description: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D040
Waste Code Description: TRICHLOROETHYLENE

Hazardous Waste Code: D043
Waste Code Description: VINYL CHLORIDE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20080821
Handler Name: NYCDEP BWT - NEWTOWN CREEK WPCP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20100302
Handler Name: NYC DEP BWT NEWTOWN CREEK WPCP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: B007
Waste Code Description: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20120125
Handler Name: NYC DEP BWT NEWTOWN CREEK WPCP
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: B007
Waste Code Description: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20120223
Handler Name: NYCDEP BWT NEWTOWN CREEK WWTP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20121022
Handler Name: NYCDEP BWT NEWTOWN CREEK WPCP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20140212
Handler Name: NYC DEP BWT NEWTOWN CREEK WWTP
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20140805
Handler Name: NYCDEP BWT NEWTOWN CREEK WPCP
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Municipal	***Street 1:***	
Name:	NYC DEPT. ENVIRONMENTAL PROTECTION	***Street 2:***	
Date Became Current:	19670101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	

Owner/Operator Ind: Current Operator ***Street No:***

Type:	Municipal	**Street 1:**	GREENPOINT AVE
Name:	NYCDEP BWT	**Street 2:**	
Date Became Current:	20030101	**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Implementer	**Zip Code:**	10990

Owner/Operator Ind:	Current Owner	**Street No:**	96
Type:	Municipal	**Street 1:**	-05 HORACE HARDING EXPY
Name:	NYC DEPT ENVIRONMENTAL PROTECTION	**Street 2:**	2ND FLOOR LOW RISE
Date Became Current:	19670101	**City:**	CORONA
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	11368

Owner/Operator Ind:	Current Owner	**Street No:**	9605
Type:	Municipal	**Street 1:**	HORACE HARDING EXPRESSWAY
Name:	NYC ENVIRONMENTAL PROTECTION	**Street 2:**	2ND FLOOR, LOW RISE
Date Became Current:	19670101	**City:**	CORONA
Date Ended Current:		**State:**	NY
Phone:	718-595-5272	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	11368

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	OWNERNAME	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	99999

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Municipal	**Street 1:**	
Name:	NYC ENVIRONMENTAL PROTECTION	**Street 2:**	
Date Became Current:	19370101	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Municipal	**Street 1:**	
Name:	NYC ENVIRONMENTAL PROTECTION	**Street 2:**	
Date Became Current:	19670101	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	

Owner/Operator Ind:	Current Owner	**Street No:**	96
Type:	Municipal	**Street 1:**	-05 HORACE HARDING EXPY,
Name:	NYC DEPT. ENVIRONMENTAL PROTECTION	**Street 2:**	2ND FLOOR LOW RISE
Date Became Current:	19670101	**City:**	CORONA
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	11368

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Municipal	**Street 1:**	GREENPOINT AVE
Name:	NYCDEP BWT	**Street 2:**	
Date Became Current:	20030101	**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	10990

Owner/Operator Ind:	Current Owner	**Street No:**	9605
Type:	Municipal	**Street 1:**	HORACE HARDING EXPRESSWAY
Name:	NYC ENVIRONMENTAL PROTECTION	**Street 2:**	2ND FLOOR, LOW RISE
Date Became Current:	19670101	**City:**	CORONA
Date Ended Current:		**State:**	NY

Phone:	718-595-5272	**Country:**	US
Source Type:	Notification	**Zip Code:**	11368
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Municipal	**Street 1:**	GREENPOINT AVE
Name:	NYCDEP BWT	**Street 2:**	
Date Became Current:	20030101	**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	10990
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Municipal	**Street 1:**	
Name:	NYC DEPT ENVIRONMENTAL PROTECTION	**Street 2:**	
Date Became Current:	19670101	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	
Source Type:	Notification	**Zip Code:**	
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Municipal	**Street 1:**	
Name:	NYC ENVIRONMENTAL PROTECTION	**Street 2:**	
Date Became Current:	19670101	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	
Owner/Operator Ind:	Current Operator	**Street No:**	9605
Type:	Municipal	**Street 1:**	HORACE HARDING EXPRESSWAY
Name:	NYC ENVIRONMENTAL PROTECTION	**Street 2:**	
Date Became Current:	19670101	**City:**	CORONA
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	11368
Owner/Operator Ind:	Current Owner	**Street No:**	9605
Type:	Municipal	**Street 1:**	HORACE HARDING EXPY.
Name:	NYC ENVIRONMENTAL PROTECTION	**Street 2:**	2ND FLOOR LOW RISE
Date Became Current:	19670101	**City:**	CORONA
Date Ended Current:		**State:**	NY
Phone:	718-595-5068	**Country:**	US
Source Type:	Notification	**Zip Code:**	11368
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Municipal	**Street 1:**	301 GREENPOINT AVE.
Name:	NYCDEP BWT	**Street 2:**	
Date Became Current:	19670501	**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	11222
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Municipal	**Street 1:**	
Name:	NYC ENVIRONMENTAL PROTECTION	**Street 2:**	
Date Became Current:	19670101	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	
Source Type:	Notification	**Zip Code:**	
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Municipal	**Street 1:**	
Name:	NYCDEP BWT	**Street 2:**	
Date Became Current:	19670501	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Municipal	**Street 1:**	

Name:	NYC DEPT ENVIRONMENTAL PROTECTION	**Street 2:**	
Date Became Current:	19670101	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Municipal	**Street 1:**	
Name:	NYC DEPT ENVIRONMENTAL PROTECTION	**Street 2:**	
Date Became Current:	19670101	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	
Source Type:	Notification	**Zip Code:**	
Owner/Operator Ind:	Current Owner	**Street No:**	96-05
Type:	Municipal	**Street 1:**	HORACE HARDING EXPWY
Name:	NYC ENVIRONMENTAL PROTECTION	**Street 2:**	2ND FL LOW RISE
Date Became Current:	19670101	**City:**	CORONA
Date Ended Current:		**State:**	NY
Phone:	718-595-5272	**Country:**	US
Source Type:	Notification	**Zip Code:**	11368
Owner/Operator Ind:	Current Owner	**Street No:**	9605
Type:	Municipal	**Street 1:**	HORACE HARDING EXPY.
Name:	NYC ENVIRONMENTAL PROTECTION	**Street 2:**	2ND FLOOR LOW RISE
Date Became Current:	19670101	**City:**	CORONA
Date Ended Current:		**State:**	NY
Phone:	718-595-5068	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	11368
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Municipal	**Street 1:**	301 GREENPOINT AVE.
Name:	NYCDEP BWT	**Street 2:**	
Date Became Current:	19670501	**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Implementer	**Zip Code:**	11222

Historical Handler Details

Receive Dt:	20140212
Generator Code Description:	Small Quantity Generator
Handler Name:	NYC DEP BWT NEWTOWN CREEK WWTP
Receive Dt:	20121022
Generator Code Description:	Large Quantity Generator
Handler Name:	NYCDEP BWT NEWTOWN CREEK WPCP
Receive Dt:	20120223
Generator Code Description:	Large Quantity Generator
Handler Name:	NYCDEP BWT NEWTOWN CREEK WWTP
Receive Dt:	20120125
Generator Code Description:	Small Quantity Generator
Handler Name:	NYC DEP BWT NEWTOWN CREEK WPCP
Receive Dt:	20100302
Generator Code Description:	Large Quantity Generator
Handler Name:	NYC DEP BWT NEWTOWN CREEK WPCP
Receive Dt:	20080821
Generator Code Description:	Large Quantity Generator
Handler Name:	NYCDEP BWT - NEWTOWN CREEK WPCP
Receive Dt:	20080227
Generator Code Description:	Large Quantity Generator
Handler Name:	NYC DEP BWT NEWTOWN CREEK WPCP

Receive Dt: 20070101
Generator Code Description: Large Quantity Generator
Handler Name: NYCDEP BWT - NEWTOWN CREEK WPCP

Receive Dt: 20060224
Generator Code Description: Large Quantity Generator
Handler Name: NYCDEP BWT - NEWTOWN CREEK WPCP

Receive Dt: 20060223
Generator Code Description: Large Quantity Generator
Handler Name: NYCDEP BWT - NEWTOWN CREEK WPCP

Receive Dt: 20040305
Generator Code Description: Large Quantity Generator
Handler Name: NYCDEP BWT NEWTOWN CREEK WPCP

Receive Dt: 20020417
Generator Code Description: Large Quantity Generator
Handler Name: NEWTOWN CREEK WPCP

Receive Dt: 20010101
Generator Code Description: Large Quantity Generator
Handler Name: NEWTOWN CREEK WPCP

Receive Dt: 19990729
Generator Code Description: Large Quantity Generator
Handler Name: NEWTOWN CREEK WATER POLLUTION CONTROL

Receive Dt: 19981130
Generator Code Description: Large Quantity Generator
Handler Name: NYC DEPT OF ENVIRONMENTAL PROTECTION

Receive Dt: 19841025
Generator Code Description: Large Quantity Generator
Handler Name: NEWTOWN CREEK WATER POLLUTION CONTROL

77	4 of175	NE	0.12 / 649.95	9.75 / -2	**EXXON COMPANY,USA** **320 FREEMAN STREET** **Brooklyn NY 11222**	AST

Site ID: 22853
Site Status: Inactive
Program No: 2-600882
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Other

Expiry: N/A
County: Kings
UTM X: 588829.49391
UTM Y: 4509838.67324

Tank Information

Prog No: 2-600882
Tank ID: 44246
Tank No: H1
Tank Status: 5
Tank Status Desc: Tank Converted to Non-Regulated Use
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 01/01/1929
Close Date: 04/01/1998
Tk Out of Serv Dt:
Capacity (Gal): 275
Registered: True
Tank Model:
Pipe Model:
Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Class A Operator:
Class B Operator:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: I05
Code Name: Vent Whistle
Type: Overfill

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Tank Information

Prog No: 2-600882
Tank ID: 44247
Tank No: H2
Tank Status: 5
Tank Status Desc: Tank Converted to Non-Regulated Use
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Line Last Test Due:

Install Date:	01/01/1929	**Next Line Test Due:**	
Close Date:	04/01/1998	**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	275	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I05
Code Name: Vent Whistle
Type: Overfill

Affiliation Information

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: EXXON COMPANY, USA
Contact Title:
Contact Name:
Address1: P O BOX 4415
Address2:
City: HOUSTON
State: TX
Zip Code: 77210-4415
Country Code: 001
Phone: (713) 656-9216
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: EXXON COMPANY, USA
Contact Title:
Contact Name: R A QUINN
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-0100
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: EXXON COMPANY, USA
Contact Title:
Contact Name: W SANDSJO
Address1: P.O. BOX 4386
Address2:
City: HOUSTON
State: TX
Zip Code: 77210-0531
Country Code: 001
Phone: (718) 389-4306
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: EXXON COMPANY, USA
Contact Title:
Contact Name: W SANDSJO
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-0100
Phone Ext:
Email:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Fax:						
77	5 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WWTP 329 GREENPOINT AVENUE BROOKLYN NY 11222	AST

Site ID: 20122
Site Status: Active
Program No: 2-456438
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)
Expiry: 11/20/2026
County: Kings
UTM X: 588945.64100
UTM Y: 4509414.56675

Tank Information

Prog No: 2-456438
Tank ID: 65294
Tank No: 1436
Tank Status: 1
Tank Status Desc: In Service
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 03/01/2003
Close Date:
Tk Out of Serv Dt:
Capacity (Gal): 1500
Registered: True
Tank Model:
Pipe Model:
UDC Ind: 0
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: -
Line Last Test Due:
Next Line Test Due:
Line Test Method: -
Class A Operator:
Class B Operator:
Modified by: KXLIU
Last Modified: 12/12/2023
Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: TERRENCE NOEL,P.E.
Tank Owner Address: 96-05 HORACE HARDING EXPWY, 2ND FL CORONA, NY. 11368

Material Information

Material Name: waste oil/used oil
Percent: 100.00

Equipment Information

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	67108	***Red Tag Start Date:***	
Tank No:	1446-98	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	10/06/1998	***Next Line Test Due:***	
Close Date:	10/24/2008	***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	5000	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: D01

Code Name:	Steel/Carbon Steel/Iron
Type:	Pipe Type
Equipment:	C01
Code Name:	Aboveground
Type:	Pipe Location
Equipment:	L00
Code Name:	None
Type:	Piping Leak Detection
Equipment:	I02
Code Name:	High Level Alarm
Type:	Overfill
Equipment:	H05
Code Name:	In-Tank System (ATG)
Type:	Tank Leak Detection
Equipment:	E00
Code Name:	None
Type:	Piping Secondary Containment
Equipment:	G04
Code Name:	Double-Walled (Underground)
Type:	Tank Secondary Containment
Equipment:	K00
Code Name:	None
Type:	Spill Prevention
Equipment:	J02
Code Name:	Suction Dispenser
Type:	Dispenser
Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection
Equipment:	B01
Code Name:	Painted/Asphalt Coating
Type:	Tank External Protection
Equipment:	F01
Code Name:	Painted/Asphalt Coating
Type:	Pipe External Protection

Tank Information

Prog No:	2-456438	***UDC Ind:***	0
Tank ID:	65295	***Red Tag Start Date:***	
Tank No:	1437	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	-
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	03/01/2003	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	-
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	275	***Class B Operator:***	
Registered:	True	***Modified by:***	KXLIU
Tank Model:		***Last Modified:***	12/12/2023
Pipe Model:			
Tank Location:	3		
Tank Location Desc:	Aboveground on saddles, legs, stilts, rack or cradle		
Category:	2		
Category Desc:	Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015		
Subpart:	4		

Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: TERRENCE NOEL,P.E.
Tank Owner Address: 96-05 HORACE HARDING EXPWY, 2ND FL CORONA, NY. 11368

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Tank Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Prog No:	2-456438	**UDC Ind:**	1
Tank ID:	67110	**Red Tag Start Date:**	
Tank No:	1448-98	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	10/06/1998	**Next Line Test Due:**	
Close Date:	10/26/2008	**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	1000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: L00
Code Name: None
Type: Piping Leak Detection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: E00

Code Name: None
Type: Piping Secondary Containment

Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Tank Information

Prog No:	2-456438	**UDC Ind:**	1
Tank ID:	36620	**Red Tag Start Date:**	
Tank No:	009	**Red Tag End Date:**	
Tank Status:	4	**Tank Last Test:**	
Tank Status Desc:	Closed - In Place	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:		**Next Line Test Due:**	
Close Date:	03/01/1996	**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	600	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: B00
Code Name: None

Type: Tank External Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: I00
Code Name: None
Type: Overfill

Equipment: J03
Code Name: Gravity
Type: Dispenser

Tank Information

Prog No: 2-456438
Tank ID: 36621
Tank No: 010
Tank Status: 4
Tank Status Desc: Closed - In Place
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date:
Close Date: 03/01/1996
Tk Out of Serv Dt:
Capacity (Gal): 600
Registered: True
Tank Model:
Pipe Model:
UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Class A Operator:
Class B Operator:
Modified by: MJGRIFFI
Last Modified: 05/09/2022
Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: I00
Code Name: None
Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: J03
Code Name: Gravity
Type: Dispenser

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: B00
Code Name: None
Type: Tank External Protection

Tank Information

Prog No:	2-456438	**UDC Ind:**	1
Tank ID:	51769	**Red Tag Start Date:**	
Tank No:	011	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	01/01/1929	**Next Line Test Due:**	
Close Date:	10/01/2002	**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	275	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I05
Code Name: Vent Whistle
Type: Overfill

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	51770	***Red Tag Start Date:***	
Tank No:	012	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	01/01/1929	***Next Line Test Due:***	
Close Date:	10/01/2002	***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	275	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: I05

Code Name: Vent Whistle
Type: Overfill

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Tank Information

Prog No:	2-456438	***UDC Ind:***	0
Tank ID:	65293	***Red Tag Start Date:***	
Tank No:	1421	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	-
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	03/01/2003	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	-
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	1500	***Class B Operator:***	
Registered:	True	***Modified by:***	KXLIU
Tank Model:		***Last Modified:***	12/12/2023
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4

Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: TERRENCE NOEL,P.E.
Tank Owner Address: 96-05 HORACE HARDING EXPWY, 2ND FL CORONA, NY. 11368

Material Information

Material Name: waste oil/used oil
Percent: 100.00

Equipment Information

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Tank Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Prog No:	2-456438	**UDC Ind:**	1
Tank ID:	67109	**Red Tag Start Date:**	
Tank No:	1447-98	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	10/06/1998	**Next Line Test Due:**	
Close Date:	10/24/2008	**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	1000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: L00

Code Name: None
Type: Piping Leak Detection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Tank Information

Prog No:	2-456438	**UDC Ind:**	1
Tank ID:	51771	**Red Tag Start Date:**	
Tank No:	013	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	12/01/1986	**Next Line Test Due:**	
Close Date:	08/01/2002	**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	4000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: lube oil
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: C00
Code Name: No Piping

Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Affiliation Information

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: NYC DEP
Contact Title:
Contact Name: WATCH ENGINEER
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 999
Phone: (718) 389-2002
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: NEWTOWN CREEK WWTP
Contact Title:
Contact Name: STEVEN CUBERO
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-2002
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: C01
Company: NYC DEP
Contact Title: CHIEF, BIOSOLIDS AND BUILDING MAINTENANCE CONTRACT
Contact Name: TERRENCE NOEL,P.E.
Address1: 96-05 HORACE HARDING EXPWY, 2ND FL
Address2:
City: CORONA
State: NY
Zip Code: 11368
Country Code: 001
Phone: (718) 595-4848
Phone Ext:
Email:
Fax:

Affiliation Type: 07

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: NYC DEP
Contact Title: CHIEF, BIOSOLIDS AND BUILDING MAINTENANCE CONTRACT
Contact Name: TERRENCE NOEL, P.E.
Address1: 96-05 HORACE HARDING EXPWY, 2ND FLOOR
Address2:
City: CORONA
State: NY
Zip Code: 11368
Country Code: 001
Phone: (718) 595-4848
Phone Ext:
Email: TNOEL@DEP.NYC.GOV
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	6 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WWTP 329 GREENPOINT AVENUE BROOKLYN NY 11222	UST

Site ID: 20122
Site Status: Active
Program No: 2-456438
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)
Expiry: 11/20/2026
County: Kings
UTM X: 588945.64100
UTM Y: 4509414.56675

Tank Information

Prog No: 2-456438
Tank ID: 65290
Tank No: 1433
Tank Status: 1
Tank Status Desc: In Service
Tank Type: 06
Tank Type Desc: Fiberglass Reinforced Plastic (FRP)
Install Date: 03/01/2003
Close Date:
Tk Out of Serv Dt:
Capacity (Gal): 20000
Registered: True
Tank Model:
Pipe Model:
UDC Ind: 0
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: -
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method: -
Modified by: KXLIU
Last Modified: 12/12/2023
Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: SHRINIVASAN SEWGOBIND
Class B Operator: STEVEN CUBERO
Tank Owner Name: TERRENCE NOEL,P.E.
Tank Owner Address: 96-05 HORACE HARDING EXPWY, 2ND FL CORONA, NY. 11368

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Tank Information

Prog No:	2-456438	***UDC Ind:***	0
Tank ID:	65289	***Red Tag Start Date:***	
Tank No:	1432	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	-
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:	03/01/2003	***Next Test:***	
Close Date:		***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	20000	***Line Test Method:***	-
Registered:	True	***Modified by:***	KXLIU
Tank Model:		***Last Modified:***	12/12/2023

Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: SHRINIVASAN SEWGOBIND
Class B Operator: STEVEN CUBERO
Tank Owner Name: TERRENCE NOEL,P.E.
Tank Owner Address: 96-05 HORACE HARDING EXPWY, 2ND FL CORONA, NY. 11368

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Tank Information

Prog No: 2-456438
Tank ID: 36615
Tank No: 004
Tank Status: 4
Tank Status Desc: Closed - In Place
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 01/01/1967
Close Date: 08/01/1999
Tk Out of Serv Dt:
Capacity (Gal): 50000
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: H00
Code Name: None

Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: I00
Code Name: None
Type: Overfill

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	63744	***Red Tag Start Date:***	
Tank No:	20	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	07/02/2002	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	3000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: empty
Percent: 100.00

Equipment Information

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: I00

Code Name: None
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: B00
Code Name: None
Type: Tank External Protection

Tank Information

Prog No:	2-456438	**UDC Ind:**	1
Tank ID:	36612	**Red Tag Start Date:**	
Tank No:	001	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1988	**Next Test:**	
Close Date:	10/01/2002	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Tank Information

Prog No:	2-456438	**UDC Ind:**	1
Tank ID:	36619	**Red Tag Start Date:**	
Tank No:	008	**Red Tag End Date:**	
Tank Status:	4	**Tank Last Test:**	02/01/1997
Tank Status Desc:	Closed - In Place	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	03
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	01/01/1967	**Next Test:**	
Close Date:	08/01/1999	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	8600	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: lube oil
Percent: 100.00

Equipment Information

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Tank Information

Prog No:	2-456438	***UDC Ind:***	0
Tank ID:	249260	***Red Tag Start Date:***	
Tank No:	NC-8502-12	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	-
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:	01/11/2010	***Next Test:***	
Close Date:		***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	6000	***Line Test Method:***	-
Registered:	True	***Modified by:***	KXLIU
Tank Model:		***Last Modified:***	12/12/2023
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: SHRINIVASAN SEWGOBIND
Class B Operator: STEVEN CUBERO
Tank Owner Name: TERRENCE NOEL,P.E.
Tank Owner Address: 96-05 HORACE HARDING EXPWY, 2ND FL CORONA, NY. 11368

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: L09
Code Name: Exempt Suction Piping

Type: Piping Leak Detection

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	173213	***Red Tag Start Date:***	
Tank No:	002-A	***Red Tag End Date:***	
Tank Status:	4	***Tank Last Test:***	
Tank Status Desc:	Closed - In Place	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	01/01/1967	***Next Test:***	
Close Date:	08/01/1999	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	50000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI

Tank Model: ***Last Modified:*** 05/09/2022
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: I00
Code Name: None
Type: Overfill

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Tank Information

Prog No: 2-456438
Tank ID: 63746
Tank No: 13
Tank Status: 3
Tank Status Desc: Closed - Removed
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test: 08/31/1999
Tank Next Test Due:
Test Method: 21
Date Tested:

Install Date:	12/01/1986	***Next Test:***	
Close Date:	07/02/2002	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: I00
Code Name: None
Type: Overfill

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Tank Information

Prog No:	2-456438	***UDC Ind:***	0
Tank ID:	249259	***Red Tag Start Date:***	

Tank No:	NC-8501-12	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	06	**Test Method:**	-
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	**Date Tested:**	
Install Date:	01/11/2010	**Next Test:**	
Close Date:		**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	12000	**Line Test Method:**	-
Registered:	True	**Modified by:**	KXLIU
Tank Model:		**Last Modified:**	12/12/2023
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: SHRINIVASAN SEWGOBIND
Class B Operator: STEVEN CUBERO
Tank Owner Name: TERRENCE NOEL,P.E.
Tank Owner Address: 96-05 HORACE HARDING EXPWY, 2ND FL CORONA, NY. 11368

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Tank Information

Prog No:	2-456438	**UDC Ind:**	0
Tank ID:	65288	**Red Tag Start Date:**	
Tank No:	1431	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	06	**Test Method:**	-
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	**Date Tested:**	
Install Date:	03/01/2003	**Next Test:**	
Close Date:		**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	20000	**Line Test Method:**	-
Registered:	True	**Modified by:**	KXLIU
Tank Model:		**Last Modified:**	12/12/2023
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: SHRINIVASAN SEWGOBIND
Class B Operator: STEVEN CUBERO
Tank Owner Name: TERRENCE NOEL,P.E.
Tank Owner Address: 96-05 HORACE HARDING EXPWY, 2ND FL CORONA, NY. 11368

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	60555	***Red Tag Start Date:***	
Tank No:	16	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	04/01/2001	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	10000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:

Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	62262	***Red Tag Start Date:***	
Tank No:	17	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	09/01/2001	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		

Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	36618	***Red Tag Start Date:***	
Tank No:	007	***Red Tag End Date:***	
Tank Status:	4	***Tank Last Test:***	02/01/1997
Tank Status Desc:	Closed - In Place	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	03
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	01/01/1967	***Next Test:***	
Close Date:	08/01/1999	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	8600	***Line Test Method:***	

Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Material Information

Material Name:	lube oil
Percent:	100.00

Equipment Information

Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection
Equipment:	B00
Code Name:	None
Type:	Tank External Protection
Equipment:	H00
Code Name:	None
Type:	Tank Leak Detection
Equipment:	J02
Code Name:	Suction Dispenser
Type:	Dispenser
Equipment:	I00
Code Name:	None
Type:	Overfill
Equipment:	G00
Code Name:	None
Type:	Tank Secondary Containment
Equipment:	C02
Code Name:	Underground/On-ground
Type:	Pipe Location
Equipment:	F00
Code Name:	None
Type:	Pipe External Protection
Equipment:	D01
Code Name:	Steel/Carbon Steel/Iron
Type:	Pipe Type

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	50947	***Red Tag Start Date:***	
Tank No:	001A	***Red Tag End Date:***	
Tank Status:	4	***Tank Last Test:***	
Tank Status Desc:	Closed - In Place	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN

Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1988	**Next Test:**	
Close Date:	03/01/1996	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: I00
Code Name: None
Type: Overfill

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Tank Information

Prog No: 2-456438 **UDC Ind:** 1

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tank ID:	51772	**Red Tag Start Date:**	
Tank No:	014	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:		**Next Test:**	
Close Date:	07/01/1996	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	1000	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: lube oil
Percent: 100.00

Equipment Information

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J03
Code Name: Gravity
Type: Dispenser

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	173202	***Red Tag Start Date:***	
Tank No:	002	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	ZZ	***Test Method:***	NN
Tank Type Desc:		***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	10/01/2002	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: invalid material - please fix
Percent: 100.00

Equipment Information

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Tank Information

Prog No: 2-456438
Tank ID: 64142
Tank No: 23
Tank Status: 3
Tank Status Desc: Closed - Removed
Tank Type: ZZ
Tank Type Desc:
Install Date:
Close Date: 09/01/2002
Tk Out of Serv Dt:
Capacity (Gal): 6000
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Material Information

Material Name: empty
Percent: 100.00

Equipment Information

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: F00
Code Name: None

Type: Pipe External Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	63745	***Red Tag Start Date:***	
Tank No:	21	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	07/01/2002	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	800	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: empty
Percent: 100.00

Equipment Information

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: I00
Code Name: None
Type: Overfill

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: A00

Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Tank Information

Prog No:	2-456438	**UDC Ind:**	0
Tank ID:	65291	**Red Tag Start Date:**	
Tank No:	1434	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	06	**Test Method:**	-
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	**Date Tested:**	
Install Date:	03/01/2003	**Next Test:**	
Close Date:		**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	20000	**Line Test Method:**	-
Registered:	True	**Modified by:**	KXLIU
Tank Model:		**Last Modified:**	12/12/2023
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: SHRINIVASAN SEWGOBIND
Class B Operator: STEVEN CUBERO
Tank Owner Name: TERRENCE NOEL,P.E.
Tank Owner Address: 96-05 HORACE HARDING EXPWY, 2ND FL CORONA, NY. 11368

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	66103	***Red Tag Start Date:***	
Tank No:	1439	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	ZZ	***Test Method:***	NN
Tank Type Desc:		***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	06/01/2003	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	200	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: empty
Percent: 100.00

Equipment Information

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: I00
Code Name: None
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	66107	***Red Tag Start Date:***	
Tank No:	1443	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	ZZ	***Test Method:***	NN
Tank Type Desc:		***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	06/01/2003	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	475	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:

Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: empty
Percent: 100.00

Equipment Information

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: I00
Code Name: None
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	66106	***Red Tag Start Date:***	
Tank No:	1442	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	ZZ	***Test Method:***	NN
Tank Type Desc:		***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	06/01/2003	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	475	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		

Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: empty
Percent: 100.00

Equipment Information

Equipment: I00
Code Name: None
Type: Overfill

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: F00
Code Name: None
Type: Pipe External Protection

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	36616	***Red Tag Start Date:***	
Tank No:	005	***Red Tag End Date:***	
Tank Status:	4	***Tank Last Test:***	
Tank Status Desc:	Closed - In Place	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	01/01/1967	***Next Test:***	
Close Date:	08/01/1999	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	50000	***Line Test Method:***	

Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Material Information

Material Name:	diesel
Percent:	100.00

Equipment Information

Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection
Equipment:	J02
Code Name:	Suction Dispenser
Type:	Dispenser
Equipment:	G00
Code Name:	None
Type:	Tank Secondary Containment
Equipment:	H00
Code Name:	None
Type:	Tank Leak Detection
Equipment:	F00
Code Name:	None
Type:	Pipe External Protection
Equipment:	D01
Code Name:	Steel/Carbon Steel/Iron
Type:	Pipe Type
Equipment:	B00
Code Name:	None
Type:	Tank External Protection
Equipment:	C02
Code Name:	Underground/On-ground
Type:	Pipe Location
Equipment:	I00
Code Name:	None
Type:	Overfill

Tank Information

Prog No:	2-456438	**UDC Ind:**	1
Tank ID:	64141	**Red Tag Start Date:**	
Tank No:	22	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	ZZ	**Test Method:**	NN

Tank Type Desc:		**Date Tested:**	
Install Date:		**Next Test:**	
Close Date:	09/01/2002	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	6000	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Material Information

Material Name:	empty
Percent:	100.00

Equipment Information

Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection
Equipment:	H00
Code Name:	None
Type:	Tank Leak Detection
Equipment:	J00
Code Name:	None
Type:	Dispenser
Equipment:	I00
Code Name:	None
Type:	Overfill
Equipment:	C00
Code Name:	No Piping
Type:	Pipe Location
Equipment:	G00
Code Name:	None
Type:	Tank Secondary Containment
Equipment:	D00
Code Name:	No Piping
Type:	Pipe Type
Equipment:	F00
Code Name:	None
Type:	Pipe External Protection
Equipment:	B00
Code Name:	None
Type:	Tank External Protection

Tank Information

Prog No:	2-456438	**UDC Ind:**	1

Tank ID:	60554	**Red Tag Start Date:**	
Tank No:	15	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:		**Next Test:**	
Close Date:	04/01/2001	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	2500	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	36614	***Red Tag Start Date:***	
Tank No:	003	***Red Tag End Date:***	
Tank Status:	4	***Tank Last Test:***	
Tank Status Desc:	Closed - In Place	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	01/01/1967	***Next Test:***	
Close Date:	08/01/1999	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	50000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: F00
Code Name: None
Type: Pipe External Protection

Tank Information

Prog No:	2-456438	**UDC Ind:**	1
Tank ID:	66105	**Red Tag Start Date:**	
Tank No:	1441	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	ZZ	**Test Method:**	NN
Tank Type Desc:		**Date Tested:**	
Install Date:		**Next Test:**	
Close Date:	06/01/2003	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	475	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: empty
Percent: 100.00

Equipment Information

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: F00
Code Name: None

Type: Pipe External Protection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	36617	***Red Tag Start Date:***	
Tank No:	006	***Red Tag End Date:***	
Tank Status:	4	***Tank Last Test:***	
Tank Status Desc:	Closed - In Place	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	01/01/1967	***Next Test:***	
Close Date:	08/01/1999	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	15500	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: I00
Code Name: None
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C02

Code Name: Underground/On-ground
Type: Pipe Location

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	66108	***Red Tag Start Date:***	
Tank No:	1444	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	ZZ	***Test Method:***	NN
Tank Type Desc:		***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	06/01/2003	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	200	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: empty
Percent: 100.00

Equipment Information

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: I00
Code Name: None
Type: Overfill

Tank Information

Prog No:	2-456438	**UDC Ind:**	0
Tank ID:	65292	**Red Tag Start Date:**	
Tank No:	1435	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	06	**Test Method:**	-
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	**Date Tested:**	
Install Date:	03/01/2003	**Next Test:**	
Close Date:		**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	5000	**Line Test Method:**	-
Registered:	True	**Modified by:**	KXLIU
Tank Model:		**Last Modified:**	12/12/2023
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: SHRINIVASAN SEWGOBIND
Class B Operator: STEVEN CUBERO
Tank Owner Name: TERRENCE NOEL,P.E.
Tank Owner Address: 96-05 HORACE HARDING EXPWY, 2ND FL CORONA, NY. 11368

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	66104	***Red Tag Start Date:***	
Tank No:	1440	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	ZZ	***Test Method:***	NN
Tank Type Desc:		***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	06/01/2003	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	475	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:

Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: empty
Percent: 100.00

Equipment Information

Equipment: I00
Code Name: None
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Tank Information

Prog No:	2-456438	***UDC Ind:***	1
Tank ID:	63743	***Red Tag Start Date:***	
Tank No:	19	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	07/01/2002	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	3000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		

Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: empty
Percent: 100.00

Equipment Information

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: I00
Code Name: None
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Tank Information

Prog No: 2-456438
Tank ID: 66102
Tank No: 1438
Tank Status: 3
Tank Status Desc: Closed - Removed
Tank Type: ZZ
Tank Type Desc:
Install Date:
Close Date: 06/01/2003
Tk Out of Serv Dt:
Capacity (Gal): 450

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:

Registered: True
Modified by: MJGRIFFI
Tank Model:
Last Modified: 05/09/2022
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: empty
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: I00
Code Name: None
Type: Overfill

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Affiliation Information

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: NYC DEP
Contact Title:
Contact Name: WATCH ENGINEER

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Address1:	
Address2:	
City:	
State:	NN
Zip Code:	
Country Code:	999
Phone:	(718) 389-2002
Phone Ext:	
Email:	
Fax:	

Affiliation Type:	07
Affiliation Name:	Mail Contact
Affiliation Sub Type:	NNN
Company:	NYC DEP
Contact Title:	CHIEF, BIOSOLIDS AND BUILDING MAINTENANCE CONTRACT
Contact Name:	TERRENCE NOEL, P.E.
Address1:	96-05 HORACE HARDING EXPWY, 2ND FLOOR
Address2:	
City:	CORONA
State:	NY
Zip Code:	11368
Country Code:	001
Phone:	(718) 595-4848
Phone Ext:	
Email:	TNOEL@DEP.NYC.GOV
Fax:	

Affiliation Type:	04
Affiliation Name:	Facility Operator
Affiliation Sub Type:	NNN
Company:	NEWTOWN CREEK WWTP
Contact Title:	
Contact Name:	STEVEN CUBERO
Address1:	
Address2:	
City:	
State:	NN
Zip Code:	
Country Code:	001
Phone:	(718) 389-2002
Phone Ext:	
Email:	
Fax:	

Affiliation Type:	01
Affiliation Name:	Facility Owner
Affiliation Sub Type:	C01
Company:	NYC DEP
Contact Title:	CHIEF, BIOSOLIDS AND BUILDING MAINTENANCE CONTRACT
Contact Name:	TERRENCE NOEL,P.E.
Address1:	96-05 HORACE HARDING EXPWY, 2ND FL
Address2:	
City:	CORONA
State:	NY
Zip Code:	11368
Country Code:	001
Phone:	(718) 595-4848
Phone Ext:	
Email:	
Fax:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	7 of175	NE	0.12 / 649.95	9.75 / -2	EXXON COMPANY,USA 320 FREEMAN STREET Brooklyn NY 11222	UST

Site ID:	22853	**Expiry:**	N/A
Site Status:	Inactive	**County:**	Kings

Program No:	2-600882	**UTM X:**	588829.49391
Program Type Code:	PBS	**UTM Y:**	4509838.67324
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Other		

Tank Information

Prog No:	2-600882	**UDC Ind:**	1
Tank ID:	44248	**Red Tag Start Date:**	
Tank No:	UG3	**Red Tag End Date:**	
Tank Status:	5	**Tank Last Test:**	
Tank Status Desc:	Tank Converted to Non-Regulated Use	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1986	**Next Test:**	
Close Date:	04/01/1998	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	4000	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	2		
Category Desc:	Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Material Information

Material Name:	#2 fuel oil (on-site consumption)
Percent:	100.00

Equipment Information

Equipment:	C02
Code Name:	Underground/On-ground
Type:	Pipe Location
Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection
Equipment:	D01
Code Name:	Steel/Carbon Steel/Iron
Type:	Pipe Type
Equipment:	G99
Code Name:	Other
Type:	Tank Secondary Containment
Equipment:	I00
Code Name:	None
Type:	Overfill
Equipment:	H00
Code Name:	None
Type:	Tank Leak Detection
Equipment:	F00
Code Name:	None

Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Affiliation Information

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: EXXON COMPANY, USA
Contact Title:
Contact Name: R A QUINN
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-0100
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: EXXON COMPANY, USA
Contact Title:
Contact Name:
Address1: P O BOX 4415
Address2:
City: HOUSTON
State: TX
Zip Code: 77210-4415
Country Code: 001
Phone: (713) 656-9216
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: EXXON COMPANY, USA
Contact Title:
Contact Name: W SANDSJO
Address1: P.O. BOX 4386
Address2:
City: HOUSTON
State: TX
Zip Code: 77210-0531
Country Code: 001
Phone: (718) 389-4306
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: EXXON COMPANY, USA
Contact Title:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Name: W SANDSJO
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-0100
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	8 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WWTP 329 GREENPOINT AVENUE BROOKLYN NY 11222	CBS

Site ID: 339175
Site Status: Active
Program No: 2-000233
Program Type Code: CBS
Program Type Desc: Chemical Bulk Storage
Expiration Date: 10/22/2025
DEC Region: 2
County: Kings
UTM X: 588982.64242
UTM Y: 4509507.97479
Georeference:
Tank Location:
Site Type: Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)
Details Url:
More Info:

Tank No:
Tank Status:
Tank Type:
Install Date:
Close Date:
Expiration Dt:
Expiration:
Capacity in Gallons:
Material Name:
Percent:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	9 of175	NE	0.12 / 649.95	9.75 / -2	NEWTON CREEK WPCP 329 GREENPOINT AVENUE BROOKLYN NY 11222	MOSF

Site ID: 344985
Site Status: Unregulated/Closed
Program No: 2-1300
Program Type Code: MOSF
Program Type Desc: Major Oil Storage Facility Program
Site Type: Other
More Info:

Expiration Date: N/A
DEC Region: 2
County: Kings
UTM X: 588982.77376
UTM Y: 4509507.09592

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	10 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK, STP 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 9411493
Site ID: 298541
DER Facility ID: 241520
CID:
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C4
Meets Std: True
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Unknown
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial

UST Trust: False
Spill Date: 11/29/1994 08:42:00 AM
Received Date: 11/29/1994 09:42:00 AM
CAC Date: 12/02/1994 12:00:00 AM
Insp Date:
Close Date: 12/02/1994 12:00:00 AM
Create Date: 01/12/1995 12:00:00 AM
Update Date: 07/10/2000 12:00:00 AM
DEC Region: 2
Lead DEC: GUTIERREZ
After Hours: False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"WILL INVESTIGATE -SPKE TO ANTHONY SIGONA. OIL COMING INTO PLANT. 12/02/94 ~340 SPOKE TO TOMMY THOMAS/DEP HE SAID IT LASTED FOR 1/2 HOUR INTERNAL PBLM INSIDE PLANT, ALL CLEANED UP."

DEC Remark:

""

Material Information

OP Unit ID:	1009382	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	373840	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	True
Quantity:	100.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	SAME
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.730794790
Longitude:	-73.948598750

77	11 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP DEP - DDC (JK) 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0000867	**UST Trust:**	False
Site ID:	148957	**Spill Date:**	04/14/2000 02:00:00 PM
DER Facility ID:	241520	**Received Date:**	04/21/2000 08:43:00 AM
CID:	398	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	
Water Body:		**Create Date:**	04/21/2000 12:00:00 AM
Class:	C4	**Update Date:**	09/18/2024 02:57:27 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	AXDORONO
REM Phase:	1	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Local Agency		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"DOING CONSTRUCTION ENCOUNTERED SPILL. 400 YARDS SOIL CONTAINED."

DEC Remark:

"7/22/05: Spill 9614108 was closed and will be cleaned up under this spill number Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 5/17/04 - AUSTIN - ORIGINALY CLOSED BY CLOSURE WORKGROUP IN 2/03; REOPENED FOR REVIEW BY DEC PROJ. MGR. - END 3/09/06: This spill transferred from I. Islam to Q. Abidi. 8/18/06 DEC lead transferred from Q. Abidi to J.A. Maisonave. - JAM 7/3/08 Sent email to Afsar Samani at DDC requesting info about 2 spills which occurred at Newtown Creek WPCP (spill nos. 9907560 & 0000867). Ms. Samani replied with following: DDC decided to have DEP continue to handle all the spills associated with this site. This site is undergoing some major construction by NYCDEP. The owner agency is funding and managing all aspect of the construction work which included some petroleum spill clean-up in the past. NYCDDC took the position that it is best for the owner agency NYCDEP to continue to handle all aspect of work at this site. DDC's consultant LiRo performed some non- motor vehicle tank closure at this site in the past. The NYCDEP needs to be contacted to address these two spill cases. - JAM 6/17/09 Sent email to Afsar Samani at NYCDDC requesting a contact at DEP who has been involved with construction activities mentioned in email dated July 3, 2008. She replied with contact: Ms. Shay McAdams @ (718) 595-4618 in Bureau of Water Supply EHS Office. - JAM 12/20/10: This spill case transferred from J. Maisonave to J. Kolleeny. - JK 01/16/20: I sent email to Mr. Mohammad Mahmud of NYCDEP, cc to Mr. Bill Yulinsky of DEP: Dear Mr. Mahmud, I am writing to inquire about two open petroleum spill cases that were reported years ago at above-referenced DEP facility [Newtown Creek WPCP], and which remain open and active in our database. Both of these spill cases seem to have involved discovery of contaminated soil during construction work at site. Spill No. 9907560 was reported by Abro Consulting; Spill No. 0000867 was reported by Bidwell Envt'l. I have attached copies of spill rpts for your convenience, altho they provide limited information. I am hoping that you may be able to provide addt'l information regarding these incidents that will either allow me to close out spill cases in our database, or point a way to further actions that will move these spill cases towards closure. Please confirm your receipt of this email and let me know if you can be of assistance in this matter. - JK 09/09/2024: In 12/2021, I was contacted by Ms. Menzy Woodis of DEP, told her I need 1 or 2 GW samples in area of USTs to close out two Newtown Creek WPCP spills. I provided a LiRo site plan to her. But she didn't follow up with me and attempts to contact her by email & phone in June & October 2022 went unanswered. Her contact info, email: try either mwoodis@dep.nyc.gov or mjeanbaptiste@dep.nyc.gov; phone: Office - (718) 595-4285; Cell - (646) 584-1837. Copied on her emails were David Anthony Olton (davidanthonyo@dep.nyc.gov) and Omid Khalpari (okhalpari@dep.nyc.gov). - J. Kolleeny 09/17/2024: This spill case was transferred to A. Doronova. AD"

Material Information

OP Unit ID:	822530	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	289102	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0064A		
Material Name:	unknown material		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	ELLEN METZGER
Contact Phone:	(914) 987-1755
Contact Ext:	
Latitude:	40.730794790
Longitude:	-73.948598750

77	***12 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***NEWTOWN CREEK WPCP DEP - DDC 301 GREENPOINT AVENUE BROOKLYN NY***	***NY SPILLS***

Spill No:	0001944	***UST Trust:***	False
Site ID:	148958	***Spill Date:***	05/15/2000 04:30:00 PM
DER Facility ID:	241520	***Received Date:***	05/16/2000 08:30:00 AM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CID:	397	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	05/05/2005 12:00:00 AM
Water Body:		**Create Date:**	05/16/2000 12:00:00 AM
Class:	C3	**Update Date:**	05/05/2005 11:54:56 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	AIIslam
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Local Agency		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"callers company was contracted to test underground tanks. compnay found contamination in the soil around tanks"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND No PBS SPILL CASE TRANFERRED TO KOLLEENY TO ISLAM 5/5/05- The site is having multiple open spills and is currently under remedial investigation by PMS Construction Mgt. and Shaw Envtl. As such, this spill is closed to consolidate with spill # 0000867. - II."

Material Information

OP Unit ID:	823609	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	550325	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	CALLER
Contact Phone:	
Contact Ext:	
Latitude:	40.730794790
Longitude:	-73.948598750

77	13 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP DEP - DDC 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	9408029	**UST Trust:**	False
Site ID:	148963	**Spill Date:**	09/16/1994 11:42:00 AM
DER Facility ID:	241520	**Received Date:**	09/16/1994 12:30:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	

SWIS Code:	2401	**Close Date:**	12/16/2002 12:00:00 AM
Water Body:		**Create Date:**	10/27/1994 12:00:00 AM
Class:	C3	**Update Date:**	12/28/2004 10:08:21 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	JAKOLLEE
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Local Agency		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"GETTING GASOLINE ODORS-IN EFFLUENT OF SEWAGE TREATMENT PLANT."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY AFTER CLOSURE OF GASOLINE TANKS, PMS CONSTRUCTION DID SITE INVESTIGATION, INSTALLED MONITORING WELLS. FOUND MODEST MTBE EXCEEDANCE. AFTER MONITORING WELLS FOR SOME TIME, GROUNDWATER IMPACTS DECLINED. OK TO CLOSE; SEE ALSO SPILL NO. 9602370."

Material Information

OP Unit ID:	1002195	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2096742	**Med SW:**	False
CAS No:	01634044	**Med DW:**	False
Material Family:	Hazardous Material	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	1213A		
Material Name:	MTBE (methyl-tert-butyl ether)		

OP Unit ID:	1002195	**Med Ind Air:**	False
OU:	01	**Med GW:**	True
Material ID:	377480	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	-1.00	**Med Surf:**	False
Units:	L	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.730794790
Longitude:	-73.948598750

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	14 of175	NE	0.12 / 649.95	9.75 / -2	EXXON TERMINAL 320 FREEMAN STREET BROOKLYN NY	NY SPILLS

Spill No:	8907186	**UST Trust:**	False
Site ID:	158187	**Spill Date:**	10/20/1989 08:30:00 PM
DER Facility ID:	133719	**Received Date:**	10/20/1989 09:13:00 PM
CID:		**CAC Date:**	10/20/1989 12:00:00 AM
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/20/1989 12:00:00 AM
Water Body:		**Create Date:**	12/07/1989 12:00:00 AM
Class:	B3	**Update Date:**	04/07/2004 12:00:00 AM
Meets Std:	True	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	TOMASELLO
REM Phase:	0	**After Hours:**	True

County: Kings
Contributing Factor: Equipment Failure
Reported by: Responsible Party
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"RECEIVING PIPELINE DELIVERY, VALVE WASN'T FULLY OPEN, GASKET RUPTURED & GAS ESCAPED, PIPELINE WAS SHUT DOWN, WILL REPLACE GASKET, DEC INVESTIGATED, CONTAMINATED SOIL TO BE STOCK PILED."

DEC Remark:

""

Material Information

OP Unit ID:	934883	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	443982	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	10.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		

Material Code: 0009
Material Name: gasoline

Spiller Information

Spiller Name:
Spiller Company: EXXON
Spiller Address:
Spiller City:
Spiller State: ZZ
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.734977870
Longitude: -73.948947390

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	15 of175	NE	0.12 / 649.95	9.75 / -2	EXXON TERMINAL 320 FREEMAN STREET BROOKLYN NY	NY SPILLS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spill No: 8912333
Site ID: 158189
DER Facility ID: 133719
CID:
Program Type: ER
SWIS Code: 2401
Water Body: NEWTOWN CREEK
Class: A3
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Federal Government
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 03/27/1990 10:30:00 AM
Received Date: 03/27/1990 03:32:00 PM
CAC Date:
Insp Date:
Close Date: 02/04/1998 12:00:00 AM
Create Date: 05/16/1990 12:00:00 AM
Update Date: 04/07/2004 12:00:00 AM
DEC Region: 2
Lead DEC: KSTANG
After Hours: False

Caller Remark:

"PATCHES ON WATER, USCG TEAM ON SITE."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG 03/27/90: DEC INVESTIGATED, OIL FOUND AT VARIOUS LOCATIONS AT FACILITY NEXT DOOR(99 PAIDGE AVE), BULKHEAD SOAKED WITH OIL,OIL IN TRENCHES BEING PUMPED OUTSIDE ON TOP OF BULKHEAD, TO ASSESS EXTENT OF CONTAMINAT. REFER TO 9101866. "

Material Information

OP Unit ID: 939133
OU: 01
Material ID: 567803
CAS No:
Material Family: Petroleum
Quantity: .00
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0022
Material Name: waste oil/used oil

Med Ind Air: False
Med GW: False
Med SW: True
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: PEREZ BORO ASPHALT
Spiller Address:
Spiller City:
Spiller State: ZZ
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.734977870
Longitude: -73.948947390

77	16 of175	NE	0.12 / 649.95	9.75 / -2	EXXON TERMINAL 320 FREEMAN STREET BROOKLYN NY	NY SPILLS

Spill No: 9012482
Site ID: 158191

UST Trust: True
Spill Date: 03/05/1991 05:00:00 PM

DER Facility ID:	133719	**Received Date:**	03/05/1991 06:16:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	02/11/2010 12:00:00 AM
Water Body:		**Create Date:**	03/07/1991 12:00:00 AM
Class:	B3	**Update Date:**	02/11/2010 02:16:05 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	exhampst
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"MONITORING WELL GETTING PRODUCT EAW-38,DEC TO INVESTIGATE,DEC CONTACTED JIM SCHULTZ OF EA ENGINEERING,PRODUCT PUMPED BUT RETURNED,15WELLS DRILLED IN AREA & SITE ASSESSMENT TO BE SUBMITED5/1/91"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 03/20/91: JIM SCHULTZ OF EA ENGINEERING CONTACTED. 0.9 FEET OF PRODUCT FOUND AFTER TWO ATTEMPTS TO PUMP WELL. PRODUCT WAS DESCRIBED AS BEING LIGHT, AND DARK IN COLOR. 12/23/2002, MILLER CLOSED OUT SPILL REPORT. THIS IS A REPORT OF SPILLAGE SUBSQUENTLY REMEDIATED BY EXXON AND IS NOW PART OF THE NEWTOWN CREEK WPCP EXPANSION. 06/09/03 Reassigned from Miller to Rommel. Ellen Metzger called. They have completed the sheeting around this property for the WPCP expansion. They have dug down to just above the watertable. The excavation work (Contract 35F) is planned for August. Due to the recent rain, oil is bubbling up through standing water and will be recovered. Rommel. 2/11/10. Reassigned to E. Hampston. Closing spill in conjunction with Miller note above and information below. See also spills 9106287, 9104730, 9101866, 9012950, 9005513. See also eDocs Greenpoint Terminal File for partial remediation file on this site: L:\DER\eDocs\Site-Specific\r2\kings\Greenpoint Terminal\Mobil Terminal - 400 Kingsland Avenue\S224088\Related Sites\Exxon Marketing Terminal NYCDEP assumed possession of property and has expanded Newtown Creek WPCP at this location. Exxon and NYCDEP combined efforts complete cleanup. NYCDEP records necessary to complete file. "

Material Information

OP Unit ID:	949662	**Med Ind Air:**	False
OU:	01	**Med GW:**	True
Material ID:	428955	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	EXXON
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.734977870
Longitude:	-73.948947390

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	17 of175	NE	0.12 / 649.95	9.75 / -2	301 GREENPOINT AVE 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	9302991	**UST Trust:**	False
Site ID:	213747	**Spill Date:**	06/05/1993 09:55:00 AM
DER Facility ID:	241520	**Received Date:**	06/05/1993 12:26:00 PM
CID:		**CAC Date:**	06/05/1993 12:00:00 AM
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	06/05/1993 12:00:00 AM
Water Body:		**Create Date:**	06/07/1993 12:00:00 AM
Class:	D4	**Update Date:**	09/11/2006 07:50:54 AM
Meets Std:	True	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	FIFOLT
REM Phase:	0	**After Hours:**	True

County: Kings
Contributing Factor: Unknown
Reported by: Local Agency
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"NO DETAILS - IT WAS TAKEN CARE OF - CALL BACK REQ."

DEC Remark:

""

Spiller Information

Spiller Name:
Spiller Company: NEW TOWN CRK
Spiller Address: SEWAGE PLANT
Spiller City:
Spiller State: ZZ
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.730794790
Longitude: -73.948598750

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	18 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK PLANT 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0600090	**UST Trust:**	False
Site ID:	362026	**Spill Date:**	04/03/2006 10:10:00 PM
DER Facility ID:	241520	**Received Date:**	04/03/2006 09:56:00 PM
CID:	64	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	04/04/2006 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	04/04/2006 02:07:00 AM
Class:	D4	**Update Date:**	04/04/2006 08:58:47 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SMSANGES
REM Phase:	0	**After Hours:**	True

County: Kings
Contributing Factor: Other
Reported by: Responsible Party
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Caller Remark:

"Suppose to pump 620 MGD however is unable to due to the overflow coming in. Unknown if there is a by-pass or not."

DEC Remark:

""

Material Information

OP Unit ID:	1120133	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2109625	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	PANAVILA ROY
Spiller Company:	
Spiller Address:	301 GREENPOINTAVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	PANAVILA ROY
Contact Phone:	(718) 389-2002
Contact Ext:	
Latitude:	40.731117000
Longitude:	-73.947406000

77	***19 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***NEWTOWN CREEK 301 GREENPOINT AVENUE BROOKLYN NY***	***NY SPILLS***

Spill No:	0514208	***UST Trust:***	
Site ID:	360868	***Spill Date:***	03/12/2006 12:00:00 PM
DER Facility ID:	241520	***Received Date:***	03/12/2006 01:53:00 PM
CID:	27	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	03/13/2006 12:00:00 AM
Water Body:	NEWTOWN CREEK	***Create Date:***	03/13/2006 09:13:00 AM
Class:	D4	***Update Date:***	03/13/2006 09:12:04 AM
Meets Std:	True	***DEC Region:***	2
Penalty:		***Lead DEC:***	rmpiper
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Caller reports facility can not keep up with rain. Spill is ongoing."

DEC Remark:

"forwarded to DEC Water group"

Material Information

OP Unit ID:	1117981	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2108496	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	
Spiller Company:	NEWTOWN CREEK
Spiller Address:	301 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.731117000
Longitude:	-73.947406000

77	***20 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***DEP FACILITY 329 GREENPOINT AVENUE BROOKLYN NY***	***NY SPILLS***

Spill No:	0514090	***UST Trust:***	
Site ID:	360727	***Spill Date:***	03/09/2006 10:00:00 AM
DER Facility ID:	159801	***Received Date:***	03/09/2006 10:57:00 AM
CID:	444	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	03/13/2006 12:00:00 AM
Water Body:		***Create Date:***	03/09/2006 11:08:00 AM
Class:	C4	***Update Date:***	03/13/2006 09:42:41 AM
Meets Std:	False	***DEC Region:***	2
Penalty:		***Lead DEC:***	SMSANGES
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"LEAK FROM A TRUCK ABOUT 1 QUART AND IS CLEANED UP"

DEC Remark:

"minor spill - all cleaned"

Material Information

OP Unit ID:	1117853	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2108357	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0015		
Material Name:	motor oil		

Spiller Information

Spiller Name:	BENJAMIN POTTS
Spiller Company:	JP PACON CONSTRUCTION
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	BENJAMIN POTTS
Contact Phone:	(718) 609-8797
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

77	***21 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***ON THE ROAD 329 GREENPOINT AVENUE BROOKLYN NY***	***NY SPILLS***

Spill No:	0514375	***UST Trust:***	False
Site ID:	361077	***Spill Date:***	03/16/2006 08:55:00 AM
DER Facility ID:	159801	***Received Date:***	03/16/2006 08:55:00 AM
CID:	408	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	03/16/2006 12:00:00 AM
Water Body:		***Create Date:***	03/16/2006 09:15:00 AM
Class:	C4	***Update Date:***	03/16/2006 12:37:12 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	HRPATEL
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"OIL SHEEN OBSERRVED IN A PUDDLE, ONE CUP OF PRODUCT, HAS BEEN CLEANE DUP"

DEC Remark:

"03/16/06-Hiralkumar Patel. Left message for Benjamin at Bidwell Environment. Spoke with Benjamin. they have found oil sheen and its all absorbed. all cleaned up. no further action required. case closed."

Material Information

OP Unit ID:	1118176	***Med Ind Air:***	False
OU:	01	***Med GW:***	False

Material ID:	2108693	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	1.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0015		
Material Name:	motor oil		

Spiller Information

Spiller Name:	BENJAMIN POTTS
Spiller Company:	JP PACON CONSTRUCTION
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	BENJAMIN POTTS
Contact Phone:	(718) 609-8797
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

77	**22 of175**	**NE**	**0.12 / 649.95**	**9.75 / -2**	**NEWTOWN CREEK WATER POLLU 301 GREENPOINT AVENUE BROOKLYN NY**	**NY SPILLS**

Spill No:	0511857	**UST Trust:**	False
Site ID:	358097	**Spill Date:**	01/04/2006 04:30:00 AM
DER Facility ID:	241520	**Received Date:**	01/14/2006 07:07:00 AM
CID:	72	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	01/17/2006 12:00:00 AM
Water Body:	WHALE CREEK	**Create Date:**	01/14/2006 07:20:00 AM
Class:	D4	**Update Date:**	01/17/2006 08:59:44 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SMSANGES
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Throttle engaged due to heavy rain. Duration from 0430 - 0630."

DEC Remark:

""

Material Information

OP Unit ID:	1115350	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2105411	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	
Spiller Company:	NYC DEP
Spiller Address:	301 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	JAMES DALY
Contact Phone:	(718) 372-8043
Contact Ext:	
Latitude:	40.731117000
Longitude:	-73.947406000

77	23 of175	NE	0.12 / 649.95	9.75 / -2	MINOR SPILL 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0512232	**UST Trust:**	False
Site ID:	358595	**Spill Date:**	01/03/2006 12:00:00 AM
DER Facility ID:	159801	**Received Date:**	01/23/2006 07:36:00 AM
CID:	73	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	01/27/2006 12:00:00 AM
Water Body:		**Create Date:**	01/24/2006 02:10:00 PM
Class:	C4	**Update Date:**	01/27/2006 11:30:13 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SFRAHMAN
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"OIL LEAK FROM MAN LIFT CAUSE SPILL OF 2 CUPS ONTO CONCRETE. ALL CLEANED UP. DEP ASKED THAT IT BE REPORTED TO DEC."

DEC Remark:

""

Material Information

OP Unit ID:	1115833	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2105942	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		

Material Name: diesel

Spiller Information

Spiller Name: PETER CHIODO
Spiller Company: SILVERITE CONSTRUCTION
Spiller Address: 329 GREENPOINT AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: BENJAMIN POTTS
Contact Phone: (718) 609-8797
Contact Ext:
Latitude: 40.731502000
Longitude: -73.946336000

---

77 | ***24 of175*** | ***NE*** | ***0.12 / 649.95*** | ***9.75 / -2*** | ***NEWTOWN CREEK 301 GREENPOINT AVENUE BROOKLYN NY*** | ***NY SPILLS***

Spill No: 0603406
Site ID: 366123
DER Facility ID: 241520
CID: 444
Program Type: ER
SWIS Code: 2401
Water Body:
Class: D4
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Unknown
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 06/28/2006 08:02:00 AM
Received Date: 06/28/2006 08:02:00 AM
CAC Date:
Insp Date:
Close Date: 06/28/2006 12:00:00 AM
Create Date: 06/28/2006 08:27:00 AM
Update Date: 06/28/2006 11:43:48 AM
DEC Region: 2
Lead DEC: SMSANGES
After Hours: True

Caller Remark:

"DUE TO HEAVY RAIN; CHANNELS OUT"

DEC Remark:

""

Material Information

OP Unit ID: 1124077
OU: 01
Material ID: 2113559
CAS No:
Material Family: Other
Quantity:
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0062A
Material Name: raw sewage

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: True
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Name: RICHARD DESFROSSE
Spiller Company: NEWTOWN CREEK
Spiller Address: 301 GREENPOINTAVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: RICHARD DESFROSSE
Contact Phone: (718) 372-7193
Contact Ext:
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	25 of175	NE	0.12 / 649.95	9.75 / -2	POLUTION CONTROL PLANT 329 GREENPOINT AVE BROOKLYNN NY	NY SPILLS

Spill No: 0711947
Site ID: 393494
DER Facility ID: 343107
CID: 81
Program Type: ER
SWIS Code: 2401
Water Body: EAST RIVER
Class:
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Local Agency
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 02/13/2008 02:30:00 AM
Received Date: 02/13/2008 02:57:00 AM
CAC Date:
Insp Date:
Close Date: 02/13/2008 12:00:00 AM
Create Date: 02/13/2008 03:08:00 AM
Update Date: 02/13/2008 10:06:45 AM
DEC Region: 2
Lead DEC: HRAHMED
After Hours: True

Caller Remark:

"Newtown creek, water polution control plant. #2 bar screen jammed up, cause leak. Repair in process."

DEC Remark:

"02/13/2008-Ahmed-Spill closed due to non-petroleum spill and reffered to DEC Water unit"

Material Information

OP Unit ID: 1150460
OU: 01
Material ID: 2141076
CAS No:
Material Family: Other
Quantity:
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0062A
Material Name: raw sewage

Med Ind Air: False
Med GW: True
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: ENGINEER CHIU
Spiller Company: POLUTION CONTROL PLANT
Spiller Address: 329 GREENPOINT AVE
Spiller City: BROOKLYNN
Spiller State: NY

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Zip:	11222
Spiller Country:	001
Contact Name:	ENGINEER CHIU
Contact Phone:	(718) 389-2002
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	26 of175	NE	0.12 / 649.95	9.75 / -2	NEWTON CREEK PLANT 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0611591	**UST Trust:**	False
Site ID:	376256	**Spill Date:**	01/18/2007 01:08:00 PM
DER Facility ID:	159801	**Received Date:**	01/18/2007 01:08:00 PM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	01/18/2007 12:00:00 AM
Water Body:		**Create Date:**	01/18/2007 01:25:00 PM
Class:	C4	**Update Date:**	01/18/2007 04:50:54 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SMSANGES
REM Phase:	0	**After Hours:**	False

County:	Kings
Contributing Factor:	Other
Reported by:	Local Agency
Referred to:	
Source:	Institutional, Educational, Gov., Other
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"SPILLED INTO SECONDARY CONTAINMENT DURING TRANSFER"

DEC Remark:

""

Material Information

OP Unit ID:	1133848	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2123677	**Med SW:**	False
CAS No:	07681529	**Med DW:**	False
Material Family:	Hazardous Material	**Med Sewer:**	False
Quantity:	3000.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		

Material Code:	0124A
Material Name:	sodium hypochlorite

Spiller Information

Spiller Name:	MR FISHER
Spiller Company:	NEWTON CREEK PLANT
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	JOE REDDINGTON
Contact Phone:	(212) 860-9364
Contact Ext:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Latitude:		40.731496000				
Longitude:		-73.946413000				

77	27 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WATER POLUTION CONTROL PLANT 329 GREEN POINT AVE BROOKLYN NY 11222	NY SPILLS

Spill No:	0908611	**UST Trust:**	False
Site ID:	421258	**Spill Date:**	10/30/2009 02:30:00 PM
DER Facility ID:	352614	**Received Date:**	10/30/2009 04:08:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	11/02/2009 12:00:00 AM
Water Body:		**Create Date:**	10/30/2009 04:09:00 PM
Class:		**Update Date:**	11/02/2009 09:33:18 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	hrpatel
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"10 gallons of hydrolic oil spilled into elevator shaft. Repairs and Clean up is being conducted at this time."

DEC Remark:

"11/02/09-Hiralkumar Patel. 9:28 AM:- spoke at Jerry at DEP. spill was inside concrete pit under elevator and was cleaned up. no soil/sewer affected. case closed."

Material Information

OP Unit ID:	1177151	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2169895	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	10.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	
Spiller Company:	ELEVATOR
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	SAME AS ABOVE
Contact Phone:	
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	28 of175	NE	0.12 / 649.95	9.75 / -2	DEP WASTEWATER 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0512132	**UST Trust:**	
Site ID:	358403	**Spill Date:**	01/06/2006 10:00:00 AM
DER Facility ID:	159801	**Received Date:**	01/20/2006 11:29:00 AM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	01/24/2006 12:00:00 AM
Water Body:		**Create Date:**	01/20/2006 11:51:00 AM
Class:	C4	**Update Date:**	01/24/2006 08:45:43 AM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	SMSANGES
REM Phase:	0	**After Hours:**	False

County: Kings
Contributing Factor: Other
Reported by: Other
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"1 CUP. AND IS CLEANED UP: CUTTING MACHINE LEAKED"

DEC Remark:

""

Material Information

OP Unit ID:	1115646	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2105733	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		

Material Code: 0001A
Material Name: #2 fuel oil

Spiller Information

Spiller Name: BENJAMIN POTTS
Spiller Company: DEP WASTEWATER
Spiller Address: 329 GREENPOINT AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: BENJAMIN POTTS
Contact Phone: (718) 609-8797
Contact Ext:
Latitude: 40.731502000
Longitude: -73.946336000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	29 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WATER POLLUTION CONTROL PLANT 329 GREEN POINT AVE BROOKLYN NY	NY SPILLS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spill No:	0810451	**UST Trust:**	False
Site ID:	407971	**Spill Date:**	12/17/2008 04:05:00 AM
DER Facility ID:	355035	**Received Date:**	12/17/2008 04:42:00 AM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	12/17/2008 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	12/17/2008 04:47:00 AM
Class:	D5	**Update Date:**	12/17/2008 04:44:59 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"ongoing discharge due to weather"

DEC Remark:

""

Material Information

OP Unit ID:	1164504	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2155883	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0060A		
Material Name:	wastewater		

Spiller Information

Spiller Name:	
Spiller Company:	NYCDEP
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	JIM DALY
Contact Phone:	
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

77	30 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0650058	**UST Trust:**	False
Site ID:	362519	**Spill Date:**	10/13/2005 12:00:00 PM
DER Facility ID:	159801	**Received Date:**	04/12/2006 02:44:00 PM
CID:		**CAC Date:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	04/13/2006 12:00:00 AM
Water Body:		**Create Date:**	04/13/2006 10:51:00 AM
Class:	C5	**Update Date:**	09/14/2006 07:49:15 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	JMKRIMGO
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Housekeeping		
Reported by:	Responsible Party		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Less then 10 oz (a small puddle)of oil was found by DEP inspector on soil by the disinfection building. All was cleaned up with absorbent pads on 11/07/05."

DEC Remark:

""

Material Information

OP Unit ID:	1120623	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2110112	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.10	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.10	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	False
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	DEP
Spiller Address:	
Spiller City:	***Update***
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	HELEN MAHONEY
Contact Phone:	(718) 595-6136
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	31 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WATER TREA 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0202662	**UST Trust:**	False
Site ID:	191594	**Spill Date:**	06/12/2002 01:00:00 PM
DER Facility ID:	159801	**Received Date:**	06/12/2002 03:15:00 PM
CID:	266	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	06/12/2002 12:00:00 AM
Water Body:	WHALE CREEK CANAL	**Create Date:**	06/12/2002 12:00:00 AM
Class:	C3	**Update Date:**	07/24/2002 12:00:00 AM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	JBVOUGHT
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Other		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"SPILLER WAS INSTALLING SOME CREOSOTE TIMBERS AS PART OF A NEW BULK HEAD. THERE IS SOME TYPE OF SHEEN COMING OFF OF THE TIMBERS. CALLER'S AGENCY IS THE ENVIRONMENTAL CONSULTANT ON THE SITE. AREA IS CONTAINED BY SOME DOCKS. SPILLER HAS BEEN DIRECTED TO PUT A BOOM IN PLACE. SPILLER TO MAKE ARRANGEMENTS FOR CLEAN UP. CALLER HAS BEEN WORKING WITH JENNIFER ROMMEL ON THE PROJECT AND ALREADY LEFT HER A MESSAGE AS WELL."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 6/12/2002-VOUGHT-Non-regulated material. Facility is permmitted for bulkhead construction as per NYSDEC Permits. Spill closed by Vought. 07/16/02 Picone was installing new timber fenders along the east side of Whale Creek using creosote treated fenders. The cresote from newly installed fenders bled for a time into the water, thereby causing a sheen on the water surface. DEC instructed Picone to install an oil boom along the fender and a second containment boom to the north of the work zone. The fender installation is now complete and a sheen is no longer visible. Picone is due to switch out the booms again this week. The work is complete and a sheen is no longer visible. jmr "

Material Information

OP Unit ID:	855765	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	520509	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	JOHN P PICONE CONSTRUCTIO
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	JIMMY PYNN
Contact Phone:	(718) 389-2002
Contact Ext:	
Latitude:	40.731275610
Longitude:	-73.946992490

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	32 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 329 GREENPOINT AVE RD E BROOKLYN NY	NY SPILLS

Spill No:	0706259	**UST Trust:**	False
Site ID:	386744	**Spill Date:**	08/31/2007 03:12:00 PM
DER Facility ID:	336055	**Received Date:**	09/04/2007 03:12:00 PM
CID:	408	**CAC Date:**	
Program Type:	ER	**Insp Date:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SWIS Code:	2401	**Close Date:**	09/05/2007 12:00:00 AM
Water Body:		**Create Date:**	09/04/2007 03:37:00 PM
Class:	D5	**Update Date:**	09/05/2007 10:51:23 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"ABOUT 1 QUART RELEASED; SMALL LEAK FROM BOON; ONTO PAVEMENT; HAS BEEN CLEANED;"

DEC Remark:

""

Material Information

OP Unit ID:	1143976	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2134259	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	JOANNA KOENIG
Spiller Company:	NEW TOWN CREEK
Spiller Address:	329 GREENPOINT AVE RD E
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	JOANNA KOENIG
Contact Phone:	(646) 739-3748
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	33 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WCPC 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0705272	**UST Trust:**	False
Site ID:	385563	**Spill Date:**	08/08/2007 07:00:00 AM
DER Facility ID:	241520	**Received Date:**	08/08/2007 07:39:00 AM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	08/08/2007 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	08/08/2007 08:02:00 AM
Class:		**Update Date:**	08/08/2007 09:59:23 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	jbvought

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

REM Phase: 0
After Hours: True
County: Kings
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Non Major Facility > 1,100 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"due to equipment failure and weather"

DEC Remark:

"08/08/07-Vought-Off hours responder. This spill closed and referred to DEC Water Unit."

Material Information

OP Unit ID: 1142830
OU: 01
Material ID: 2133076
CAS No:
Material Family: Other
Quantity: .00
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0062A
Material Name: raw sewage
Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: True
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: KEVIN GRANT
Spiller Company: NEWTOWN CREEK WCPC
Spiller Address: 301 GREENPOINTAVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: KEVIN GRANT
Contact Phone: (718) 372-7193
Contact Ext:
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	34 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WPCP 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 0701144
Site ID: 380636
DER Facility ID: 241520
CID: 79
Program Type: ER
SWIS Code: 2401
Water Body: EAST RIVER
Class: D5
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Responsible Party
Referred to:
UST Trust: False
Spill Date: 04/27/2007 04:40:00 AM
Received Date: 04/27/2007 06:40:00 AM
CAC Date:
Insp Date:
Close Date: 04/27/2007 12:00:00 AM
Create Date: 04/27/2007 02:11:00 PM
Update Date: 04/27/2007 03:31:22 PM
DEC Region: 2
Lead DEC: smsanges
After Hours: True

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"HEAVY RAIN CAUSED EQUIPMENT FAILURE - ONGOING"

DEC Remark:

""

Material Information

OP Unit ID:	1138114	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2128086	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0062A
Material Name: raw sewage

Spiller Information

Spiller Name: KEVIN GRANT
Spiller Company: NEW TOWN CREEK WPCP
Spiller Address: 301 GREENPOINT AVE.
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip: 11222
Spiller Country: 001
Contact Name: KEVIN GRANT
Contact Phone: (718) 372-7193
Contact Ext:
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	35 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP DEP - DDC 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	9911559	**UST Trust:**	False
Site ID:	148966	**Spill Date:**	01/04/2000 02:33:00 PM
DER Facility ID:	241520	**Received Date:**	01/04/2000 03:00:00 PM
CID:	281	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	02/26/2003 12:00:00 AM
Water Body:		**Create Date:**	01/04/2000 12:00:00 AM
Class:	C1	**Update Date:**	12/28/2004 10:06:47 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	TOMASELLO
REM Phase:	0	**After Hours:**	False

County: Kings
Contributing Factor: Abandoned Drums
Reported by: Local Agency
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"ABOVE MATERIAL DISCOVERED ABANDONED AND TAKEN TO ABOVE FACILITY. NO CALL BACK REQEUSTED."

DEC Remark:

""

Material Information

OP Unit ID:	1086174	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	297018	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	20.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	20.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	RICARDO FREYRE
Contact Phone:	(914) 987-1755
Contact Ext:	
Latitude:	40.730794790
Longitude:	-73.948598750

77	***36 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***NEWTOWN CREEK WCPC 329 GREEN POINT AVE BROOKLYN NY***	***NY SPILLS***

Spill No:	0809249	***UST Trust:***	False
Site ID:	406694	***Spill Date:***	11/15/2008 11:30:00 AM
DER Facility ID:	355035	***Received Date:***	11/15/2008 12:17:00 PM
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	11/17/2008 12:00:00 AM
Water Body:		***Create Date:***	11/15/2008 12:20:00 PM
Class:	E5	***Update Date:***	11/17/2008 10:42:21 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	RMPIPER
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"throttle gates"

DEC Remark:

"referred to dec water. closed"

Material Information

OP Unit ID:	1163273	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2154586	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		

Material Code: 9999
Material Name: other - wet weather bypass sewage rain

Spiller Information

Spiller Name:
Spiller Company: NEWTOWN CREEK WCPC
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: MR ROY
Contact Phone:
Contact Ext:
Latitude: 40.731496000
Longitude: -73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	37 of175	NE	0.12 / 649.95	9.75 / -2	POLLUTION PLANT 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0511797	***UST Trust:***	False
Site ID:	358031	***Spill Date:***	12/06/2005 10:00:00 AM
DER Facility ID:	159801	***Received Date:***	01/12/2006 02:25:00 PM
CID:	444	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	02/06/2006 12:00:00 AM
Water Body:		***Create Date:***	01/12/2006 02:45:00 PM
Class:		***Update Date:***	02/06/2006 09:00:38 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	JBVOUGHT
REM Phase:	0	***After Hours:***	False

County: Kings
Contributing Factor: Other
Reported by: Other
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"WHEN MOVIN A PIECE OF MACHINERY CAUSING SPILL IS CLEANED UP"

DEC Remark:

"1/12/06-Vought-Called Winnie Lanham and spill date was 12/06/05 and she will return call tomorrow with spill information. 1/30/06-Vought-Called Winnie Lanham and left message to return call to DEC. 2/1/06-Vought-Received message from Winnie to return call. 2/3/06-Vought-Returned call to Winnie (718-609-8715) and left message with requirements of method of cleanup, spill on concrete and if any sewers or drains were affected. 2/6/06-Vought-Received message from Winnie that spill was to stone and soil around generators spill was cleanup up via scraping of surface. Soil awaiting disposal. Removed soil was 1/4 of 55-gallon drum. No sewers or drains were affected. All contaminated was removed and spill closed due to minor spill

amount and non-continuous source. Spill closed by Vought."

Material Information

OP Unit ID:	1115283	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2105340	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	WINNIE LANHAM
Spiller Company:	POLLUTION PLANT
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	WINNIE LANHAM
Contact Phone:	(718) 389-2002
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

77	***38 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***NEWTOWN CREEK WATER POLUTION CONTROL 329 GREEN POINT AVE BROOKLYN NY***	***NY SPILLS***

Spill No:	0810194	***UST Trust:***	False
Site ID:	407709	***Spill Date:***	12/11/2008 05:20:00 PM
DER Facility ID:	355035	***Received Date:***	12/11/2008 06:16:00 PM
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	12/12/2008 12:00:00 AM
Water Body:	WHALE CREEK	***Create Date:***	12/11/2008 06:19:00 PM
Class:	D5	***Update Date:***	12/12/2008 11:07:14 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	smsanges
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"waste water bypass due to weathe, unk amoutn into whale creek, still ongoing."

DEC Remark:

""

Material Information

OP Unit ID:	1164246	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2155620	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0060A		
Material Name:	wastewater		

Spiller Information

Spiller Name:	
Spiller Company:	NYC DEP
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	JIM DALY
Contact Phone:	
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	39 of175	NE	0.12 / 649.95	9.75 / -2	DEP WASTE WATER TREATMENT 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0514457	***UST Trust:***	False
Site ID:	361187	***Spill Date:***	03/17/2006 01:50:00 PM
DER Facility ID:	159801	***Received Date:***	03/17/2006 02:26:00 PM
CID:	409	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	03/17/2006 12:00:00 AM
Water Body:		***Create Date:***	03/17/2006 02:44:00 PM
Class:		***Update Date:***	03/17/2006 03:12:00 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	JBVOUGHT
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Human Error		
Reported by:	Local Agency		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CLEAN UP IN PROCESS. LOCATED ON CONCRETE ROOF."

DEC Remark:

"3/17/06-Vought-Spill on roof of building and no impact to soil or groundwater. No sewers or drains affected. Spill closed by Vought."

Material Information

OP Unit ID:	1118268	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2108784	***Med SW:***	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	15.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0013		
Material Name:	lube oil		

Spiller Information

Spiller Name:	BENJAMIN POTTS
Spiller Company:	SILVER RITE CONSTRUCTION
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	BENJAMIN POTTS
Contact Phone:	(718) 609-8797
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

77	40 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WATER PLAN 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0307871	**UST Trust:**	False
Site ID:	310475	**Spill Date:**	10/26/2003 07:15:00 PM
DER Facility ID:	159801	**Received Date:**	10/26/2003 07:49:00 PM
CID:	211	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/27/2003 12:00:00 AM
Water Body:		**Create Date:**	10/26/2003 12:00:00 AM
Class:	B3	**Update Date:**	10/27/2003 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	TJDEMEO
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Local Agency		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"FITTING BROKE ON BOTTOM OF TANK - SPILL IS CONTAINED WITHIN INTERNAL SYSTEM AND WILL BE RECYCLED"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 10/27/03. Ref. to the Division of Water. YK."

Material Information

OP Unit ID:	874257	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	501398	**Med SW:**	False
CAS No:	07681529	**Med DW:**	False
Material Family:	Hazardous Material	**Med Sewer:**	False
Quantity:	5000.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Med Soil: True
Med Air: False
Material Code: 0124A
Material Name: sodium hypochlorite
Oxygenate:

Spiller Information

Spiller Name: JIM DALY
Spiller Company: NEW TOWN CREEK WATER PLAN
Spiller Address: 329 GREENPOINT AV
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: JIM DALY
Contact Phone: (718) 372-7193
Contact Ext:
Latitude: 40.731275610
Longitude: -73.946992490

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	41 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 0705172
Site ID: 385454
DER Facility ID: 159801
CID: 444
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C4
Meets Std: False
Penalty:
REM Phase: 0
County: Kings
Contributing Factor: Unknown
Reported by: Other
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 08/06/2007 09:30:00 AM
Received Date: 08/06/2007 01:01:00 PM
CAC Date:
Insp Date:
Close Date: 08/09/2007 12:00:00 AM
Create Date: 08/06/2007 01:25:00 PM
Update Date: 08/09/2007 09:32:51 AM
DEC Region: 2
Lead DEC: smsanges
After Hours:

Caller Remark:

"1 OUNCE ON TO SOIL AND IS ALL CLEANED UP"

DEC Remark:

""

Material Information

OP Unit ID: 1142724
OU: 01
Material ID: 2132966
CAS No:
Material Family: Petroleum
Quantity: .00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0008
Material Name: diesel

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Information

Spiller Name:	JOANNA KOENIG
Spiller Company:	NEWTOWN CREEK
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	JOANNA KOENIG
Contact Phone:	(718) 609-8783
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

77	42 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 329 GREENPOINT AVE RD E BROOKLYN NY	NY SPILLS

Spill No:	0706180	***UST Trust:***	False
Site ID:	386653	***Spill Date:***	08/31/2007 12:30:00 PM
DER Facility ID:	336055	***Received Date:***	08/31/2007 12:47:00 PM
CID:	410	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	08/31/2007 12:00:00 AM
Water Body:		***Create Date:***	08/31/2007 01:05:00 PM
Class:		***Update Date:***	08/31/2007 01:40:52 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	hrpatel
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Other		
Reported by:	Local Agency		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"ONE OUNCE OF MATERIAL TO SOIL: CLEANUP COMPELTE: SPILL DISCOVERED AT 12:30, TIME OF SPILL UNKNOWN:"

DEC Remark:

""

Material Information

OP Unit ID:	1143887	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2134159	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	JOANNA KOENIG
Spiller Company:	NEW TOWN CREEK

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Address: 329 GREENPOINT AVE RD E
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: JOANNA KOENIG
Contact Phone: (718) 609-8783
Contact Ext:
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	43 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP 329 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No: 0809701
Site ID: 407192
DER Facility ID: 335827
CID:
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C4
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Local Agency
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 11/30/2008 01:20:00 PM
Received Date: 11/30/2008 01:43:00 PM
CAC Date:
Insp Date:
Close Date: 12/02/2008 12:00:00 AM
Create Date: 11/30/2008 01:47:00 PM
Update Date: 12/02/2008 10:13:34 AM
DEC Region: 2
Lead DEC: smsanges
After Hours: True

Caller Remark:

"Wet Weather Bypass."

DEC Remark:

""

Material Information

OP Unit ID: 1163745
OU: 01
Material ID: 2155087
CAS No:
Material Family: Other
Quantity:
Units: G
Recovered:
Med Soil: False
Med Air: False
Material Code: 0062A
Material Name: raw sewage

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: EQUIPMENT FAILURE
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Name: PRINCE ANGUS
Contact Phone: (718) 389-2002
Contact Ext:
Latitude: 40.731496000
Longitude: -73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	44 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WPCP 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 0510055
Site ID: 355947
DER Facility ID: 241520
CID: 74
Program Type: ER
SWIS Code: 2401
Water Body: EAST RIVER
Class: D4
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 11/23/2005 01:05:00 AM
Received Date: 11/23/2005 02:28:00 AM
CAC Date:
Insp Date:
Close Date: 11/23/2005 12:00:00 AM
Create Date: 11/23/2005 02:41:00 AM
Update Date: 11/23/2005 09:23:01 AM
DEC Region: 2
Lead DEC: SMSANGES
After Hours: True

Caller Remark:

"1.36 million gallons of chlorine residual non compliance Due to control failure on chlorine pump End time 0115. "

DEC Remark:

"11/23/05-Vought-Off hours duty responder. Spill referred to DEC Water Unit Selvin Southwell."

Spiller Information

Spiller Name: MR. CHIU
Spiller Company: NEW TOWN CREEK WPCP
Spiller Address: 301 GREENPOINT AVE.
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: MR. CHIU
Contact Phone: (718) 389-2002
Contact Ext:
Latitude: 40.731117000
Longitude: -73.947406000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	45 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 0511191
Site ID: 357294
DER Facility ID: 241520
CID: 74
Program Type: ER
SWIS Code: 2401
Water Body: NEW TOWN CREEK
Class: C4
Meets Std: False
Penalty: False

UST Trust: False
Spill Date: 12/25/2005 11:00:00 AM
Received Date: 12/25/2005 12:44:00 PM
CAC Date:
Insp Date:
Close Date: 12/27/2005 12:00:00 AM
Create Date: 12/25/2005 12:58:00 PM
Update Date: 12/27/2005 09:41:23 AM
DEC Region: 2
Lead DEC: SMSANGES

REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"chlorine residual is below the required amount 0.03 Lost a primer on a pump Ended at 12:00pm "

DEC Remark:

""

Material Information

OP Unit ID:	1114571	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2104638	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	RICHARD DEFOSSE
Spiller Company:	NEW TOWN CREEK
Spiller Address:	301 GREENPOINTAVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	12222
Spiller Country:	001
Contact Name:	RICHARD DEFOSSE
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	40.731117000
Longitude:	-73.947406000

77	46 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WPCP 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0407841	**UST Trust:**	False
Site ID:	332418	**Spill Date:**	10/15/2004 07:00:00 AM
DER Facility ID:	159801	**Received Date:**	10/15/2004 08:12:00 AM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	01/28/2005 12:00:00 AM
Water Body:		**Create Date:**	10/18/2004 05:18:00 PM
Class:	C4	**Update Date:**	01/28/2005 02:18:22 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	CESAWYER
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Local Agency		
Referred to:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source: Commercial Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"PLANT UNDER CONSTRUCTION, WHILE EXCAVATING AND THE TRUCK WAS BACKING UP AND HIT SOMETHING AND PUNCTURED HIS TANK: CONTRACTOR CLEANING UP AT THIs TIME;"

DEC Remark:

"11/4/05 - Sawyer - Called Winnie Lanham at DEP and she assured me the spill was handled properly. She would also have the contractor forward the disposal manifest to the Department. 1/28/05 - Sawyer - Received the non-Hazardous Material Manifest from DEP Heavy Construction Manager Ernest Livingston. No further action required. Closed."

Material Information

OP Unit ID:	1094651	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	574774	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	60.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	WINNIE LANHAM
Spiller Company:	NEW TOWN CREEK WPCP
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	WINNIE LANHAM
Contact Phone:	(718) 389-2002
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	47 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WATER POLUTION PLANT 329 GREEN POINT AVE BROOKLYN NY 11222	NY SPILLS

Spill No:	0806368	**UST Trust:**	False
Site ID:	403650	**Spill Date:**	09/06/2008 05:20:00 PM
DER Facility ID:	352614	**Received Date:**	09/06/2008 05:18:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	09/08/2008 12:00:00 AM
Water Body:		**Create Date:**	09/06/2008 05:22:00 PM
Class:	D4	**Update Date:**	09/08/2008 09:29:48 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	RMPIPER
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Local Agency		
Referred to:			
Source:	Commercial/Industrial		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Complaint #4 in a series of 5 ongoing raw sewage bypasses."

DEC Remark:

"Due to heavy rains. closed and referreed to DEC water."

Material Information

OP Unit ID:	1160337	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2151504	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	1878A		
Material Name:	waste material		

Spiller Information

Spiller Name:	
Spiller Company:	NYCDEP
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	JIM DALY
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

77	48 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0600869	**UST Trust:**	False
Site ID:	362975	**Spill Date:**	04/22/2006 06:22:00 PM
DER Facility ID:	241520	**Received Date:**	04/22/2006 07:57:00 PM
CID:	64	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	04/24/2006 12:00:00 AM
Water Body:	NEWTOWN CREEK	**Create Date:**	04/23/2006 06:28:00 AM
Class:	C4	**Update Date:**	04/24/2006 08:42:29 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	HRPATEL
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"NON-COMPLIANCE STILL ONGOING DUE TO RAIN."

DEC Remark:

"Transferred to Water Division."

Material Information

OP Unit ID:	1121044	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2110529	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	JIM DALY
Spiller Company:	NEWTOWN CREEK
Spiller Address:	301 GREENPOINTAVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	JIM DALY
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	40.731117000
Longitude:	-73.947406000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	49 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP DEP - DDC 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0304007	***UST Trust:***	False
Site ID:	265775	***Spill Date:***	07/16/2003 01:30:00 PM
DER Facility ID:	241520	***Received Date:***	07/16/2003 02:42:00 PM
CID:	297	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	07/17/2003 12:00:00 AM
Water Body:		***Create Date:***	07/16/2003 12:00:00 AM
Class:	C4	***Update Date:***	12/28/2004 10:11:52 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	TJDEMEO
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Human Error		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"A WORKER FELL ONTO A VALVE AND RUPTURED THE SIGHT GLASS SPILLING THE ABOVE LIQUID INTO A CONTAINMENT PIT"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO Report forwarded to DEC Water group. Spill was contained in a pit at the

water treatment facility Update: Quantity spilled was actually 2985 gal "

Material Information

OP Unit ID:	872258	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	504866	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	1000.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	1703A		
Material Name:	sodium hydrochloride		

Spiller Information

Spiller Name:	MARK HAIMSON
Spiller Company:	NEW TOWN CREEK PLANT
Spiller Address:	301 GREENPOINT AV
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	MARK HAIMSON
Contact Phone:	(212) 860-9315
Contact Ext:	
Latitude:	40.730794790
Longitude:	-73.948598750

77	***50 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***EXXON TERMINAL 320 FREEMAN STREET BROOKLYN NY***	***NY SPILLS***

Spill No:	8909181	***UST Trust:***	False
Site ID:	158188	***Spill Date:***	12/19/1989 11:30:00 AM
DER Facility ID:	133719	***Received Date:***	12/19/1989 01:22:00 PM
CID:		***CAC Date:***	12/19/1989 12:00:00 AM
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	12/19/1989 12:00:00 AM
Water Body:	WHALE CREEK	***Create Date:***	01/03/1990 12:00:00 AM
Class:	C3	***Update Date:***	04/07/2004 12:00:00 AM
Meets Std:	True	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	FINGER
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Federal Government		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"USCG WILL SEND TEAM TO INVESTIGATE."

DEC Remark:

""

Material Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OP Unit ID:	936363	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	442356	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.734977870
Longitude:	-73.948947390

77	51 of175	NE	0.12 / 649.95	9.75 / -2	NEWTON CREEK PLANT 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0612936	**UST Trust:**	False
Site ID:	377889	**Spill Date:**	03/02/2007 01:30:00 AM
DER Facility ID:	241520	**Received Date:**	03/02/2007 02:07:00 AM
CID:	77	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	03/02/2007 12:00:00 AM
Water Body:	WHALE CREEK	**Create Date:**	03/02/2007 02:24:00 AM
Class:	C4	**Update Date:**	03/02/2007 10:41:31 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	sfrahman
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"non compliance due to weather."

DEC Remark:

"Referred to water division. "

Material Information

OP Unit ID:	1135406	**Med Ind Air:**	False
OU:	01	**Med GW:**	True
Material ID:	2125311	**Med SW:**	True
CAS No:		**Med DW:**	False

Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	
Spiller Company:	NYC DEP
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	-
Spiller Country:	001
Contact Name:	TIM DALY
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	52 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP DEP - DDC 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0013213	**UST Trust:**	False
Site ID:	148960	**Spill Date:**	03/17/2001 06:00:00 AM
DER Facility ID:	241520	**Received Date:**	03/17/2001 11:44:00 AM
CID:	398	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	04/05/2001 12:00:00 AM
Water Body:		**Create Date:**	03/17/2001 12:00:00 AM
Class:	C3	**Update Date:**	12/28/2004 10:05:37 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	MXTIPPLE
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"ELECTRICAL FIRE. NO CALL BACK REQUESTED. POSS CONTAINING PCB. CLEAN UP CREW ENROUTE."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE CLEAN HARBORS CONTAINED SAMPLED AND DISPOSED OF THE OIL/ NO PCB'S INVOLVED"

Material Information

OP Unit ID:	834710	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	539932	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	NYC DEP
Spiller Address:	5917 JUNCTION BLVD
Spiller City:	NEW YORK
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	ROBERT KEPICH
Contact Phone:	(718) 595-6777
Contact Ext:	
Latitude:	40.730794790
Longitude:	-73.948598750

77	53 of175	NE	0.12 / 649.95	9.75 / -2	NEWTON CREEK PLANT 301 GREENPOINT AVE. BROOKLYN NY	NY SPILLS

Spill No:	0802830	**UST Trust:**	
Site ID:	399003	**Spill Date:**	06/10/2008 10:30:00 PM
DER Facility ID:	337783	**Received Date:**	06/10/2008 11:17:00 PM
CID:	78	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	06/11/2008 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	06/11/2008 08:31:00 AM
Class:	D5	**Update Date:**	06/11/2008 09:17:15 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Spill is ongoing. Due to heavy rain. Going into East River."

DEC Remark:

""

Material Information

OP Unit ID:	1155870	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2146753	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Information

Spiller Name:
Spiller Company: NYC DEP
Spiller Address:
Spiller City:
Spiller State: ZZ
Spiller Zip: -
Spiller Country: 001
Contact Name: JIM DALY
Contact Phone: (718) 372-7193
Contact Ext:
Latitude:
Longitude:

77	54 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WATER POLLUTION CONTROL 329 GREEN POINT AVE BROOKLYN NY	NY SPILLS

Spill No: 0808966
Site ID: 406398
DER Facility ID: 355035
CID:
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C4
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Local Agency
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 11/08/2008 03:30:00 PM
Received Date: 11/08/2008 04:14:00 PM
CAC Date:
Insp Date:
Close Date: 11/10/2008 12:00:00 AM
Create Date: 11/08/2008 04:19:00 PM
Update Date: 11/10/2008 09:33:06 AM
DEC Region: 2
Lead DEC: SFRAHMAN
After Hours: True

Caller Remark:

"Ongoing at this time- Due to heavy rain."

DEC Remark:

"11/10/08-Referred to water division.(sr)"

Material Information

OP Unit ID: 1162987
OU: 01
Material ID: 2154285
CAS No:
Material Family: Other
Quantity:
Units:
Recovered:
Med Soil: False
Med Air: False
Material Code: 0060A
Material Name: wastewater

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Name:	
Spiller Company:	NYCDEP
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	JIM DALY
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	55 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEKWPCP DEP - DDC 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	9500431	**UST Trust:**	False
Site ID:	91496	**Spill Date:**	04/11/1995 12:00:00 PM
DER Facility ID:	241520	**Received Date:**	04/11/1995 02:59:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	05/05/2005 12:00:00 AM
Water Body:		**Create Date:**	05/09/1995 12:00:00 AM
Class:	C3	**Update Date:**	05/05/2005 11:32:48 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	AIIslam
REM Phase:	0	**After Hours:**	False

County:	Kings
Contributing Factor:	Human Error
Reported by:	Responsible Party
Referred to:	
Source:	Commercial/Industrial
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"FILL LINE FOUND WITH #2 OIL - STEVE SPOKE WITH RANDY, DEP WILL DIGOUT AREA AROUND FILL - 10'X 10' SECTION. CONTRACTOR WILL TAKE SOIL TO RECYCLING PLANT ON L.I."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY SPILL CASE TRANSFERRED FROM KOLLEENY TO ISLAM 5/5/05- The site is having multiple open spills and is currently under investigation by PMS Construction Mgt. and Shaw Envtl. Based on the information in the Caller Remarks area above,the existance of other open spills at the site and this spill being similar in nature, it is closed to consolidate with spill #9907560. -II."

Material Information

OP Unit ID:	1011197	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	369049	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	-1.00	**Med Surf:**	False
Units:	L	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		

Material Code:	0001A
Material Name:	#2 fuel oil

Spiller Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Name:
Spiller Company: NYCDEP
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.731117000
Longitude: -73.947406000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	56 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 0703835
Site ID: 383855
DER Facility ID: 241520
CID: 73
Program Type: ER
SWIS Code: 2401
Water Body: EAST RIVER
Class: C4
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 07/05/2007 02:00:00 AM
Received Date: 07/05/2007 05:13:00 AM
CAC Date:
Insp Date:
Close Date: 07/05/2007 12:00:00 AM
Create Date: 07/05/2007 05:28:00 AM
Update Date: 07/05/2007 09:30:55 AM
DEC Region: 2
Lead DEC: SFRAHMAN
After Hours: True

Caller Remark:

"SPILL IS ONGOING."

DEC Remark:

"Referred to water division.(SR)"

Material Information

OP Unit ID: 1141184
OU: 01
Material ID: 2131384
CAS No:
Material Family: Other
Quantity:
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0062A
Material Name: raw sewage

Med Ind Air: False
Med GW: False
Med SW: True
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company:
Spiller Address:
Spiller City:
Spiller State: ZZ

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Zip: -
Spiller Country: 001
Contact Name: CHIU
Contact Phone: (718) 389-2002
Contact Ext:
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	57 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 0610819
Site ID: 375328
DER Facility ID: 241520
CID: 73
Program Type: ER
SWIS Code: 2401
Water Body: EAST RIVER
Class:
Meets Std: False
Penalty:
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 12/25/2006 11:15:00 PM
Received Date: 12/26/2006 12:12:00 AM
CAC Date:
Insp Date:
Close Date: 12/26/2006 12:00:00 AM
Create Date: 12/26/2006 02:07:00 AM
Update Date: 12/26/2006 01:26:09 PM
DEC Region: 2
Lead DEC: HRPATEL
After Hours:

Caller Remark:

"NON-COMPLIANCE. SPILL IS ONGOING."

DEC Remark:

"referred to Water division."

Material Information

OP Unit ID: 1132969
OU: 01
Material ID: 2122762
CAS No:
Material Family: Other
Quantity:
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0062A
Material Name: raw sewage

Med Ind Air: False
Med GW: False
Med SW: True
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company:
Spiller Address:
Spiller City:
Spiller State: ZZ
Spiller Zip: -
Spiller Country: 001
Contact Name: PANAVILA ROY
Contact Phone: (718) 389-2002
Contact Ext:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Latitude:						
Longitude:						
77	58 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WPCP 301 GREEN POINT AVE BROOKLYN NY	NY SPILLS

Spill No:	0710149	**UST Trust:**	
Site ID:	391378	**Spill Date:**	12/23/2007 07:55:00 AM
DER Facility ID:	341012	**Received Date:**	12/23/2007 09:34:00 AM
CID:	41	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	12/24/2007 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	12/23/2007 09:58:00 AM
Class:	E5	**Update Date:**	12/24/2007 08:31:54 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	RMPIPER
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"due to hevy rains "

DEC Remark:

"Referred to DEC Water. closed."

Material Information

OP Unit ID:	1148436	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2138916	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	True
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	-
Spiller Country:	001
Contact Name:	ABOVE
Contact Phone:	
Contact Ext:	
Latitude:	40.731123000
Longitude:	-73.947445000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	59 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK CONT.PLANT 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0204403	**UST Trust:**	False
Site ID:	148961	**Spill Date:**	07/27/2002 09:05:00 AM
DER Facility ID:	241520	**Received Date:**	07/27/2002 11:53:00 AM
CID:	199	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	07/29/2002 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	07/27/2002 12:00:00 AM
Class:	C3	**Update Date:**	08/12/2002 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	JBVOUGHT
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CALLER STATES DUE TO A POWER FAILURE THERE WAS NO CLORINAZATION INTO THE EAST RIVER FROM THE WASTE WATER - POWER RESTORED BY 10:49 / WATER WAS TREATED BUT NOT CLORINATED"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 7/29/2002-VOUGHT-non regulated material. Spill referred to Selvin Southwell (NYSDEC water Unit). Spill closed by Vought."

Material Information

OP Unit ID:	857206	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	518655	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Hazardous Material	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0063A		
Material Name:	unknown hazardous material		

Spiller Information

Spiller Name:	
Spiller Company:	NEW YORK CITY DEP
Spiller Address:	6505 HORACE HARDING EXPWY
Spiller City:	ELMHURST
Spiller State:	NY
Spiller Zip:	11368-
Spiller Country:	001
Contact Name:	CALLER
Contact Phone:	
Contact Ext:	
Latitude:	40.730794790
Longitude:	-73.948598750

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	60 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP DEP - DDC 301 GREENPOINT AVENUE	NY SPILLS

BROOKLYN NY

Spill No:	9602370	***UST Trust:***	False
Site ID:	148964	***Spill Date:***	04/01/1996 12:00:00 AM
DER Facility ID:	241520	***Received Date:***	05/20/1996 10:19:00 AM
CID:	351	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	04/18/2001 12:00:00 AM
Water Body:		***Create Date:***	05/20/1996 12:00:00 AM
Class:	C4	***Update Date:***	12/28/2004 10:07:33 AM
Meets Std:	True	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	JAKOLLEE
REM Phase:	0	***After Hours:***	False

County: Kings
Contributing Factor: Unknown
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"caller received results from water samples indicating contamination"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY MTBE EXCEEDANCE (253 PPB) IN GROUNDWATER SAMPLE FROM ONE WELL. JK ASKED FOR ONE ADDITIONAL ROUND OF GROUNDWATER SAMPLING. ADDITIONAL ROUND OF GW SAMPLING SHOWED NO SIGNIFICANT GASOLINE-RELATED IMPACT TO GROUNDWATER, AND SINCE SITE IS UNDERGOING MAJOR RENOVATIONS INVOLVING LARGE AMOUNTS OF EARTH MOVING AND DEWATERING, SPILL CLOSURE IS APPROPRIATE."

Material Information

OP Unit ID:	1029840	***Med Ind Air:***	False
OU:	01	***Med GW:***	True
Material ID:	352192	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		

Material Code: 0009
Material Name: gasoline

OP Unit ID:	1029840	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2096807	***Med SW:***	False
CAS No:	01634044	***Med DW:***	False
Material Family:	Hazardous Material	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		

Material Code: 1213A
Material Name: MTBE (methyl-tert-butyl ether)

Spiller Information

Spiller Name: UNKNOWN
Spiller Company: Unknown
Spiller Address: UNKNOWN
Spiller City: UNKNOWN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: ANTHONY MARINO
Contact Phone: (212) 669-8286
Contact Ext:
Latitude: 40.730794790
Longitude: -73.948598750

---

77 | **61 of175** | **NE** | **0.12 / 649.95** | **9.75 / -2** | **Spill Number 9809941**
301 GREENPOINT AVENUE
BROOKLYN NY | **NY SPILLS**

Spill No: 9809941
Site ID: 265776
DER Facility ID: 241520
CID: 351
Program Type: ER
SWIS Code: 2401
Water Body:
Class: B2
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Other
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 11/06/1998 02:00:00 PM
Received Date: 11/06/1998 03:37:00 PM
CAC Date:
Insp Date:
Close Date: 02/13/2003 12:00:00 AM
Create Date: 11/06/1998 12:00:00 AM
Update Date: 02/13/2003 12:00:00 AM
DEC Region: 2
Lead DEC: MMMULQUE
After Hours: False

Caller Remark:

"WHILE REMOVING A TANK FARM AN UNKNOWN TYPE MATERIAL CAME OUT OF IT - IT IS BELIEVED IT MAY BE SOME TYPE OF PETROLEUM BASED DYE WHICH WAS INJECTED INTO THE PRODUCT - CALLER SPOKE WITH MIKE MULQUEEN IN REGION 2"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MULQUEEN 02/13/2003-Closed Due To The Nature / Extent Of The Spill Report."

Material Information

OP Unit ID: 1067212
OU: 01
Material ID: 313831
CAS No:
Material Family: Other
Quantity: .00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0064A
Material Name: unknown material

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: NYC DEP
Spiller Address:
Spiller City: ***Update***
Spiller State: ZZ
Spiller Zip:
Spiller Country: 001
Contact Name: ELLEN METZGER

Contact Phone: (914) 987-1755
Contact Ext:
Latitude: 40.730794790
Longitude: -73.948598750

---

77 | **62 of175** | **NE** | **0.12 / 649.95** | **9.75 / -2** | **NEW TOWN CREEK**
301 GREENPOINT AVENUE
BROOKLYN NY | **NY SPILLS**

Spill No: 0500990
Site ID: 344108
DER Facility ID: 241520
CID: 77
Program Type: ER
SWIS Code: 2401
Water Body: NEW TOWN CREEK
Class: D5
Meets Std: False
Penalty:
REM Phase: 0
County: Kings
Contributing Factor: Other
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 04/23/2005 11:30:00 PM
Received Date: 04/24/2005 01:20:00 AM
CAC Date:
Insp Date:
Close Date: 04/25/2005 12:00:00 AM
Create Date: 04/24/2005 02:09:00 AM
Update Date: 04/25/2005 08:46:02 AM
DEC Region: 2
Lead DEC: JBVOUGHT
After Hours: True

Caller Remark:

"raw sewege due to heavy rain, ongoing."

DEC Remark:

"4/25/05 //mt///referred to the water unit///nfa"

Material Information

OP Unit ID: 1102758
OU: 01
Material ID: 582981
CAS No:
Material Family: Other
Quantity:
Units: G
Recovered:
Med Soil: False
Med Air: False
Material Code: 0062A
Material Name: raw sewage

Med Ind Air: False
Med GW: True
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: NYC DEP
Spiller Address:
Spiller City: ***Update***
Spiller State: ZZ
Spiller Zip:
Spiller Country: 001
Contact Name: JAMES DALY
Contact Phone: (718) 372-7193
Contact Ext:
Latitude: 40.731117000
Longitude: -73.947406000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	63 of175	NE	0.12 / 649.95	9.75 / -2	EXXON TERMINAL 320 FREEMAN STREET BROOKLYN NY	NY SPILLS

Spill No:	9004386	**UST Trust:**	False
Site ID:	158190	**Spill Date:**	07/20/1990 11:15:00 AM
DER Facility ID:	133719	**Received Date:**	07/20/1990 11:37:00 AM
CID:		**CAC Date:**	06/20/1995 12:00:00 AM
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	06/20/1995 12:00:00 AM
Water Body:		**Create Date:**	07/25/1990 12:00:00 AM
Class:	C3	**Update Date:**	04/07/2004 12:00:00 AM
Meets Std:	True	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	JAMES
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CONTRACTOR DISCONNECTED WRONG PIPE, GASOLINE SPILLED OUT,EXXON WASHING GASOLINE INTO CONTAINMENT POND, TO VAC OUT PRODUCT, NRC#31777."

DEC Remark:

""

Material Information

OP Unit ID:	942192	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	435485	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	200.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	EXXON
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.734977870
Longitude:	-73.948947390

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	64 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0405275	**UST Trust:**	False
Site ID:	126574	**Spill Date:**	08/13/2004 07:00:00 AM
DER Facility ID:	159801	**Received Date:**	08/13/2004 11:29:00 AM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	04/20/2005 12:00:00 AM
Water Body:		**Create Date:**	08/13/2004 12:00:00 AM
Class:	C4	**Update Date:**	04/20/2005 03:47:24 PM
Meets Std:	True	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	JMKRIMGO
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Human Error		
Reported by:	Other		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"DURING HAMMERING SOMETHING, HIT SOMETHING TO CAUSE LEAK: CONTAINED IN A EXCAVATION: "

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 8/13/2004 Sangesland spoke with Ernest Livingston. He said as a pile was being hammered into place, they may have ruptured an old buried tank. Unknown what the material is, but it is green. Several years ago they had a similar Green Spill which turned out to be Hazardous. They shut down the work site and called a Haz Mat company to figure things out. No product is entering the creek. It is all contained in the excavation. Krimgold responded to the site. 8/18/04 - AUSTIN - RECD CALL FROM WINNIE LANHAM OF DEP HEALTH AND SAFETY FOR SITE(718-609-8715). SHE INDICATED THAT DEP HAD TAKEN SAMPLE OF NON-AQUEOUS GREEN LIQUID (ABOUT 50 GALS OF TOTAL 1000 GALS FLUID RECOVERD BY CLEAN VENTURES (THEIR CONTRACTOR)), AND WAS AWAITING PRIORITY POLLUTANT RESULTS. SHE WILL FAX LOCATION MAP SO THAT WE CAN FORWARD TO JENN ROMMEL FOR POSSIBLE DETERMINATION AS TO WHAT THIS MATERIAL MAY BE AS PART OF MOBIL GREENPOINT PLUME PROJECT. - END 9/7/04. J.Krimgold left message for Winnie Lanham. 9/8/04. J.Krimgold spoke to Ms. W. Lanham (DEP). They completed removal of contaminated soil in construction area. The material spilled appeared to be an antifreeze. Contaminated soil was disposed of as petroleum contaminated. Ms. Lonham will submit a report in a week. They will also perform soil delineation to assure no contamination left behind. 4/20/05. J.Krimgold revied the letter report submitted by DEP on April 20, 2005. No contaminants was found above TAGMs levels. NFA letter. "

Material Information

OP Unit ID:	888788	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	489375	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

OP Unit ID:	888788	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	489376	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	L	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Name:	ERNEST LIVINGSTON
Spiller Company:	NEW TOWN CREEK
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	ERNEST LIVINGSTON
Contact Phone:	(718) 609-8700
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	65 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WPCP 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	9614108	**UST Trust:**	False
Site ID:	213748	**Spill Date:**	03/04/1997 03:00:00 PM
DER Facility ID:	241520	**Received Date:**	03/04/1997 03:36:00 PM
CID:	282	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	07/22/2005 12:00:00 AM
Water Body:		**Create Date:**	03/04/1997 12:00:00 AM
Class:	B3	**Update Date:**	09/14/2006 07:53:56 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	JLDYBER
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"THEY WERE DOING EXCAVATION FOR A BUILDING PROJECT AND ENCOUTERED SOIL CONTAMINATION.MIKE MULQUEEN FROM DEC IS AWARE OF THE SPILL "

DEC Remark:

"7/22/05, Dyber: This spill will be cleaned up under spill 0000867. 7/8/05: Spoke with Jim Pynn. He will do research and get back to me. Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 03/29/04 Transferred from Mulqueen to Rommel"

Material Information

OP Unit ID:	1041669	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	339218	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	SAME
Spiller Company:	SAME

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip: 11222-
Spiller Country: 001
Contact Name: JIM PYNN
Contact Phone: (718) 389-2002
Contact Ext:
Latitude: 40.730794790
Longitude: -73.948598750

77	66 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 0509056
Site ID: 354774
DER Facility ID: 159801
CID: 444
Program Type: ER
SWIS Code: 2401
Water Body: NEWTOWN CREEK
Class: C4
Meets Std: False
Penalty:
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Local Agency
Referred to:
Source: Vessel
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 10/28/2005 11:45:00 AM
Received Date: 10/28/2005 12:04:00 PM
CAC Date:
Insp Date:
Close Date: 10/28/2005 12:00:00 AM
Create Date: 10/28/2005 12:23:00 PM
Update Date: 10/28/2005 03:03:48 PM
DEC Region: 2
Lead DEC: SMSANGES
After Hours: False

Caller Remark:

"A CRANE ON A BARGE LEAKED ABOUT 1 CUP INTO CREEK: BOOM WAS PLACED OUT : ALL CLEANED UP"

DEC Remark:

""

Material Information

OP Unit ID: 1112164
OU: 01
Material ID: 2102205
CAS No:
Material Family: Petroleum
Quantity: .00
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0013
Material Name: lube oil

Med Ind Air: False
Med GW: False
Med SW: True
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: JOHN CULKAN
Spiller Company: PICONE/MCCULLAGH
Spiller Address:
Spiller City:
Spiller State: ZZ
Spiller Zip:
Spiller Country: 001

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Name: WINNIE LANHAM
Contact Phone: (718) 389-2002
Contact Ext:
Latitude: 40.731502000
Longitude: -73.946336000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	67 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WATER POLL 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 0603250
Site ID: 365929
DER Facility ID: 241520
CID: 74
Program Type: ER
SWIS Code: 2401
Water Body: NEW TOWN CREEK
Class: E4
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 06/24/2006 01:40:00 AM
Received Date: 06/24/2006 02:18:00 AM
CAC Date:
Insp Date:
Close Date: 06/26/2006 12:00:00 AM
Create Date: 06/24/2006 02:33:00 AM
Update Date: 06/26/2006 09:07:30 AM
DEC Region: 2
Lead DEC: rmpiper
After Hours: True

Caller Remark:

"ongoing Heavy rain - unable to pump 2 times dry weather flow The plant is pumping 540 millions gallons per day - should be pumping 620 million gallons per day "

DEC Remark:

"Closed. Referrred to DEC water Division."

Material Information

OP Unit ID: 1123905
OU: 01
Material ID: 2113376
CAS No:
Material Family: Other
Quantity: .00
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0062A
Material Name: raw sewage

Med Ind Air: False
Med GW: True
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: JAMES DALY
Spiller Company: NEW TOWN CREEK WATER POLL
Spiller Address: 301 GREENPOINT AVE.
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: JAMES DALY
Contact Phone: (718) 372-8043
Contact Ext:
Latitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Longitude:						

77	68 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCC 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0603263	**UST Trust:**	False
Site ID:	365942	**Spill Date:**	06/24/2006 03:00:00 PM
DER Facility ID:	241520	**Received Date:**	06/24/2006 03:36:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	06/26/2006 12:00:00 AM
Water Body:	NEW TOWN CREEK	**Create Date:**	06/24/2006 03:48:00 PM
Class:	E5	**Update Date:**	06/26/2006 09:25:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	rmpiper
REM Phase:	0	**After Hours:**	True

County: Kings
Contributing Factor: Other
Reported by: Local Agency
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"WEATHER RELATED NONCOMPLIANCE"

DEC Remark:

"Closed. Referrred to DEC water Division."

Material Information

OP Unit ID:	1123918	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2113389	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0062A
Material Name: raw sewage

Spiller Information

Spiller Name: RICHARD DESFROSSE
Spiller Company: NEWTOWN CREEK WPCC
Spiller Address: 301 GREENPOINT AVE.
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip: 11222
Spiller Country: 001
Contact Name: RICHARD DESFROSSE
Contact Phone: (718) 372-7193
Contact Ext:
Latitude:
Longitude:

77	69 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 301 GREENPOINT AVENUE	NY SPILLS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					BROOKLYN NY	

Spill No:	0603280	**UST Trust:**	False
Site ID:	365959	**Spill Date:**	06/25/2006 01:00:00 PM
DER Facility ID:	241520	**Received Date:**	06/25/2006 01:34:00 PM
CID:	74	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	06/26/2006 12:00:00 AM
Water Body:	WHALE CREEK	**Create Date:**	06/25/2006 01:45:00 PM
Class:	E5	**Update Date:**	06/26/2006 09:31:46 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	rmpiper
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"PUMPING 532 MGD UNABLE TO PUMP TWO TIME WATER "

DEC Remark:

"Closed. Referrred to DEC water Division."

Material Information

OP Unit ID:	1123935	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2113406	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	JIM DALY
Spiller Company:	NEW TOWN CREEK
Spiller Address:	301 GREENPOINTAVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	JIM DALY
Contact Phone:	(718) 372-8043
Contact Ext:	
Latitude:	
Longitude:	

77	70 of175	NE	0.12 / 649.95	9.75 / -2	13TH ST PUMP STATION 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0508779	**UST Trust:**	
Site ID:	354500	**Spill Date:**	10/22/2005 08:45:00 AM
DER Facility ID:	241520	**Received Date:**	10/22/2005 11:48:00 AM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CID:	75	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/25/2005 12:00:00 AM
Water Body:	NEWTOWN CREEK	**Create Date:**	10/24/2005 02:34:00 PM
Class:	D4	**Update Date:**	10/25/2005 12:25:05 PM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	SMSANGES
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Local Agency		
Referred to:			
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"26 million gals raw sewage started today 0845 and endded 0945-spill from equipt failure-runnoff into Newtown Creek"

DEC Remark:

""

Material Information

OP Unit ID:	1111904	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2101949	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	26.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	TIMOTHY PREDDICE
Spiller Company:	13TH ST PUMP STATION
Spiller Address:	301 GREENPOINTAVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	TIMOTHY PREDDICE
Contact Phone:	(518) 773-7318
Contact Ext:	
Latitude:	40.731117000
Longitude:	-73.947406000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	71 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WATER POLLU 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0701075	**UST Trust:**	False
Site ID:	380529	**Spill Date:**	04/25/2007 11:10:00 PM
DER Facility ID:	241520	**Received Date:**	04/26/2007 01:22:00 AM
CID:	79	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	04/26/2007 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	04/26/2007 09:14:00 AM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Class:	E5	**Update Date:**	04/26/2007 10:05:17 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	rmpiper
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Local Agency		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"LOSS OF POWER TO INFLUENT GATES CAUSED GATES TO CLOSE AND SPILL TO EAST RIVER -"

DEC Remark:

"referred to decwater div. closed."

Material Information

OP Unit ID:	1138009	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2127973	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	JIM DALY
Spiller Company:	NYCDEP
Spiller Address:	301 GREEN POINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	JIM DALY
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	72 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0602385	**UST Trust:**	False
Site ID:	364835	**Spill Date:**	06/01/2006 08:47:00 PM
DER Facility ID:	241520	**Received Date:**	06/01/2006 09:30:00 PM
CID:	64	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	06/02/2006 12:00:00 AM
Water Body:	NEWTOWN CREEK	**Create Date:**	06/02/2006 02:07:00 AM
Class:		**Update Date:**	06/02/2006 08:42:52 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	JBVOUGHT
REM Phase:	0	**After Hours:**	True
County:	Kings		

Contributing Factor: Other
Reported by: Responsible Party
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"NON-COMPLIANCE."

DEC Remark:

"06/02/2006-Vought-Non-petroleum spill. Closed and referred to Water Unit."

Material Information

OP Unit ID:	1122855	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2112337	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0062A
Material Name: raw sewage

Spiller Information

Spiller Name: RICHARD DESFROSSE
Spiller Company: NEWTOWN CREEK
Spiller Address: 301 GREENPOINT AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip: 11222
Spiller Country: 001
Contact Name: RICHARD DESFROSSE
Contact Phone: (718) 372-7193
Contact Ext:
Latitude:
Longitude:

77	73 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WPCP 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0700138	**UST Trust:**	False
Site ID:	379422	**Spill Date:**	04/04/2007 01:15:00 PM
DER Facility ID:	241520	**Received Date:**	04/04/2007 05:50:00 PM
CID:	410	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	04/05/2007 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	04/05/2007 08:30:00 AM
Class:	D5	**Update Date:**	04/05/2007 10:08:23 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	False

County: Kings
Contributing Factor: Equipment Failure
Reported by: Local Agency
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Caller Remark:

"DUE TO HEAVY RAINS, END TIME WAS 5:30PM: IMPACTED SCREENS"

DEC Remark:

"04/05/07-Non Petroleum. transfer to Selvin Southwell Case closed"

Material Information

OP Unit ID:	1136903	***Med Ind Air:***	False
OU:	01	***Med GW:***	True
Material ID:	2126847	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	KEVIN GRANT
Spiller Company:	NEW TOWN CREEK WPCP
Spiller Address:	301 GREENPOINTAVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	KEVIN GRANT
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	74 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0700483	***UST Trust:***	False
Site ID:	379867	***Spill Date:***	04/15/2007 08:00:00 AM
DER Facility ID:	241520	***Received Date:***	04/15/2007 08:40:00 AM
CID:	75	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	04/16/2007 12:00:00 AM
Water Body:	EAST RIVER	***Create Date:***	04/16/2007 10:42:00 AM
Class:	C4	***Update Date:***	04/16/2007 12:21:17 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	smsanges
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Local Agency		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"wet weather bypass due to heavy screening-debros in water-uinto East River-oending weather conditions"

DEC Remark:

""

Material Information

OP Unit ID:	1137364	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2127315	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	100.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0060A		
Material Name:	wastewater		

Spiller Information

Spiller Name:	
Spiller Company:	NEWTOWN CREEK
Spiller Address:	301 GREENPOINT AVE.
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	75 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0700197	***UST Trust:***	
Site ID:	379499	***Spill Date:***	04/06/2007 10:15:00 AM
DER Facility ID:	159801	***Received Date:***	04/06/2007 12:07:00 PM
CID:	410	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	04/09/2007 12:00:00 AM
Water Body:		***Create Date:***	04/06/2007 12:24:00 PM
Class:	C4	***Update Date:***	04/09/2007 12:25:50 PM
Meets Std:	False	***DEC Region:***	2
Penalty:		***Lead DEC:***	smsanges
REM Phase:	0	***After Hours:***	
County:	Kings		
Contributing Factor:	Other		
Reported by:	Police Department		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CONTRACTOR ON SITE OVERFILLED A GENERATOR, MATERIAL SPILLED ON STONE AND SOIL, CLEANUP COMPLETE:"

DEC Remark:

""

Material Information

OP Unit ID:	1136979	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2126920	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	1.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	WINNIE LANHAM
Spiller Company:	SPMPJV CONTRACTING
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	WINNIE LANHAM
Contact Phone:	(718) 609-8700
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

77	***76 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***NEW TOWN CREEK 301 GREENPOINT AVENUE BROOKLYN NY***	***NY SPILLS***

Spill No:	0703363	***UST Trust:***	False
Site ID:	383284	***Spill Date:***	06/21/2007 09:50:00 PM
DER Facility ID:	241520	***Received Date:***	06/21/2007 10:37:00 PM
CID:	77	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	06/22/2007 12:00:00 AM
Water Body:	EAST RIVER	***Create Date:***	06/22/2007 12:19:00 PM
Class:		***Update Date:***	06/22/2007 12:34:55 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	jbvought
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"ONGOING BYPASS DUE TO HEAVY RAINS. 2ND CALL: REPORTING BYPASS ENDED AT 00:35 ON 6/22/07 "

DEC Remark:

"06/22/07-Vought-Off hours responder. Non petroleum spill. Spill closed and referred to DEC Water Unit (Rossan)."

Material Information

OP Unit ID:	1140647	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2130735	***Med SW:***	True

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	KEVIN GRANT
Spiller Company:	NEW TOWN CREEK
Spiller Address:	301 GREENPOINTAVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	KEVIN GRANT
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	77 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 329 GREENPOINT AVE RD E BROOKLYN NY	NY SPILLS

Spill No:	0706548	**UST Trust:**	
Site ID:	387084	**Spill Date:**	09/12/2007 10:16:00 AM
DER Facility ID:	336055	**Received Date:**	09/12/2007 10:16:00 AM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	09/12/2007 12:00:00 AM
Water Body:		**Create Date:**	09/12/2007 10:25:00 AM
Class:	C4	**Update Date:**	09/12/2007 02:28:33 PM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"BLOWN HOSE ON A DRILL RIG ABOUT 12 OUNCES AND IS ALL CLEANED"

DEC Remark:

"minor spill from equipment during construction on site. Cleaned by DEP"

Material Information

OP Unit ID:	1144304	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2134601	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Med Soil: True
Med Air: False
Material Code: 0010
Material Name: hydraulic oil
Oxygenate:

Spiller Information

Spiller Name: JOANNA KOENIG
Spiller Company: NEWTOWN CREEK
Spiller Address: 329 GREENPOINT AVE RD E
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: JOANNA KOENIG
Contact Phone: (646) 739-3748
Contact Ext:
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	78 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 329 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No: 0706001
Site ID: 386439
DER Facility ID: 335827
CID: 444
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C4
Meets Std: False
Penalty:
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Commercial Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 08/27/2007 11:30:00 AM
Received Date: 08/27/2007 11:59:00 AM
CAC Date:
Insp Date:
Close Date: 08/27/2007 12:00:00 AM
Create Date: 08/27/2007 12:08:00 PM
Update Date: 08/27/2007 01:46:08 PM
DEC Region: 2
Lead DEC: smsanges
After Hours:

Caller Remark:

"FROM AN UNDERPINNIG MACHINE AND WAS ABOUT 2 QUARTS AND IS ALL CLEANED UP"

DEC Remark:

""

Material Information

OP Unit ID: 1143677
OU: 01
Material ID: 2133947
CAS No:
Material Family: Petroleum
Quantity: .00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0010
Material Name: hydraulic oil

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Information

Spiller Name:	JOANNA KOENIG
Spiller Company:	NEWTOWN CREEK
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	JOANNA KOENIG
Contact Phone:	(718) 609-8783
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	79 of175	NE	0.12 / 649.95	9.75 / -2	AVENUE B PUMP STATION 329 GREENPOINT AVE RD E BROOKLYN NY	NY SPILLS

Spill No:	0708718	***UST Trust:***	
Site ID:	389669	***Spill Date:***	11/09/2007 09:00:00 PM
DER Facility ID:	336055	***Received Date:***	11/09/2007 09:07:00 PM
CID:	76	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	11/13/2007 12:00:00 AM
Water Body:	EAST RIVER	***Create Date:***	11/10/2007 02:08:00 AM
Class:		***Update Date:***	11/13/2007 09:10:07 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	hrpatel
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"caused by debris blocking screening to plant. 11/9 21:46 Subject called back. They are now in compliance."

DEC Remark:

""

Material Information

OP Unit ID:	1146802	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2137189	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	NEW TOWN CREEK WPCP
Spiller Company:	NEW TOWN CREEK WPCP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Address: 329 GREENPOINT AVE RD E
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: NEW TOWN CREEK WPCP
Contact Phone: (718) 389-2002
Contact Ext:
Latitude:
Longitude:

---

77 | **80 of175** | **NE** | **0.12 / 649.95** | **9.75 / -2** | **NEW TOWN CREEK 329 GREENPOINT AVENUE BROOKLYN NY** | **NY SPILLS**

Spill No: 0704882
Site ID: 385110
DER Facility ID: 159801
CID: 410
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C4
Meets Std: False
Penalty:
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Local Agency
Referred to:
Source: Commercial Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 07/30/2007 01:50:00 PM
Received Date: 07/30/2007 03:08:00 PM
CAC Date:
Insp Date:
Close Date: 08/01/2007 12:00:00 AM
Create Date: 07/30/2007 03:30:00 PM
Update Date: 08/01/2007 11:30:36 AM
DEC Region: 2
Lead DEC: smsanges
After Hours:

Caller Remark:

"SPILL AMOUNT WAS 1/2 GALLON ONTO SOIL AND PAVEMENT DUE TO BLOWN HYD HOSE ON BULLDOZER: CLEANUP COMPLETE:"

DEC Remark:

"Third minor spill today discovered at city sewage treatment plant construction site. all cleaned."

Material Information

OP Unit ID: 1142390
OU: 01
Material ID: 2132622
CAS No:
Material Family: Petroleum
Quantity:
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0010
Material Name: hydraulic oil

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: LARRY GILMORE
Spiller Company: CONTRACT 35G SPMP
Spiller Address: 540 KINGSTON AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Name: JOANNE KOENIG
Contact Phone: (646) 739-3748
Contact Ext:
Latitude: 40.731496000
Longitude: -73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	81 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 0704883
Site ID: 385111
DER Facility ID: 159801
CID: 410
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C4
Meets Std: False
Penalty:
REM Phase: 0
County: Kings
Contributing Factor: Unknown
Reported by: Local Agency
Referred to:
Source: Unknown
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 07/30/2007 02:00:00 PM
Received Date: 07/30/2007 03:12:00 PM
CAC Date:
Insp Date:
Close Date: 08/01/2007 12:00:00 AM
Create Date: 07/30/2007 03:30:00 PM
Update Date: 08/01/2007 11:29:31 AM
DEC Region: 2
Lead DEC: smsanges
After Hours:

Caller Remark:

"SPILL TO SOIL': CLEANUP COMPLETE:"

DEC Remark:

"City DEP construction site (sewage treatment plant) minor hydraulic oil leak to ground. All Cleaned"

Material Information

OP Unit ID: 1142391
OU: 01
Material ID: 2132623
CAS No:
Material Family: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0066A
Material Name: unknown petroleum

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: LARRY GILMORE
Spiller Company: CONTRACT 35G SPMP
Spiller Address: 540 KINGSLAND
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: JOANNE KOENIG
Contact Phone: (646) 739-3748
Contact Ext:
Latitude: 40.731496000
Longitude: -73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	82 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0704884	**UST Trust:**	
Site ID:	385112	**Spill Date:**	07/30/2007 02:15:00 PM
DER Facility ID:	159801	**Received Date:**	07/30/2007 03:15:00 PM
CID:	410	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	07/31/2007 12:00:00 AM
Water Body:		**Create Date:**	07/30/2007 03:30:00 PM
Class:	C4	**Update Date:**	07/31/2007 10:18:53 AM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Local Agency		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"BROKEN HOSE ON PILE DRIVER, SPILL TO SOIL: CLEANUP COMPLETE:"

DEC Remark:

"Sangesland spoke to rep on site. He said there was a break in a hydraulic line on a piece of equipment. The equipment is a new model that automatically seals off the hydraulic system when a break is found in the line. Therefore only a small amount of hydraulic oil actually spilled to the ground. Spill was excavated and prepared for transport as waste."

Material Information

OP Unit ID:	1142392	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2132624	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	2.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	JIM HARRIS
Spiller Company:	CONTRACT 30 G SILVER RI
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	JOANNE KOENIG
Contact Phone:	(646) 739-3748
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	83 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WATER PLAN 301 GREENPOINT AVE. BROOKLYN NY	NY SPILLS

Spill No:	0707573	**UST Trust:**	False
Site ID:	388286	**Spill Date:**	10/09/2007 10:30:00 PM
DER Facility ID:	337783	**Received Date:**	10/09/2007 10:58:00 PM
CID:	27	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/10/2007 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	10/10/2007 08:49:00 AM
Class:		**Update Date:**	10/10/2007 09:16:10 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	jbvought
REM Phase:	0	**After Hours:**	True

County: Kings
Contributing Factor: Other
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Spill due to heavy rain. Plant cant keep up with the flow."

DEC Remark:

"10/10/07-Vought-Off hours responder. Non-petroleum spill. Spill closed and referred to DEC Water Unit."

Material Information

OP Unit ID:	1145470	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2135803	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0062A
Material Name: raw sewage

Spiller Information

Spiller Name: JIM DALEY
Spiller Company: NEW TOWN CREEK WATER PLAN
Spiller Address: 301 GREENPOINT AVE.
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip: 11222
Spiller Country: 001
Contact Name: JIM DALEY
Contact Phone: (718) 372-7193
Contact Ext:
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	84 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 329 GREENPOINT AVE RD E BROOKLYN NY	NY SPILLS

Spill No:	0709349	**UST Trust:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site ID:	390410	**Spill Date:**	11/29/2007 09:00:00 AM
DER Facility ID:	336055	**Received Date:**	11/29/2007 09:13:00 AM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	11/29/2007 12:00:00 AM
Water Body:		**Create Date:**	11/29/2007 09:24:00 AM
Class:	C4	**Update Date:**	11/29/2007 04:55:31 PM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"BACKHOE LEAKED 1/2 GALLON OF BRAKE OIL; AND IS ALL CLEANED UP"

DEC Remark:

"minor spill in soil near water. All cleaned up."

Material Information

OP Unit ID:	1147515	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2137947	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	JOANNA KOENIG
Spiller Company:	NEWTOWN CREEK
Spiller Address:	329 GREENPOINT AVE RD E
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	JOANNA KOENIG
Contact Phone:	(646) 739-3748
Contact Ext:	
Latitude:	
Longitude:	

77	85 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 329 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No:	0804630	**UST Trust:**	
Site ID:	401572	**Spill Date:**	07/23/2008 06:15:00 AM
DER Facility ID:	335827	**Received Date:**	07/23/2008 07:54:00 AM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	07/28/2008 12:00:00 AM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Water Body:		**Create Date:**	07/23/2008 08:07:00 AM
Class:	D5	**Update Date:**	07/28/2008 01:38:04 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Local Agency		
Referred to:			
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"DUE TO HEAVY RAINS AND ONGOING"

DEC Remark:

""

Material Information

OP Unit ID:	1158359	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2149419	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	True
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	KEVIN GRANT
Spiller Company:	NEW TOWN CREEK
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	KEVIN GRANT
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	86 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 329 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No:	0804678	**UST Trust:**	
Site ID:	401624	**Spill Date:**	07/23/2003 10:45:00 PM
DER Facility ID:	335827	**Received Date:**	07/24/2008 12:12:00 AM
CID:	27	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	07/24/2008 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	07/24/2008 02:08:00 AM
Class:		**Update Date:**	07/24/2008 08:43:49 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	jbvought
REM Phase:	0	**After Hours:**	True

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County: Kings
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Plant cant' keep up with the rain. Spill is ongoing."

DEC Remark:

"07/24/08-Vought-Duty desk officer. Non petroleum spill. Spill closed and referred to DEC Water Unit."

Material Information

OP Unit ID: 1158411
OU: 01
Material ID: 2149484
CAS No:
Material Family: Other
Quantity:
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0062A
Material Name: raw sewage

Med Ind Air: False
Med GW: False
Med SW: True
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: KEVIN GRANT
Spiller Company: NEW TOWN CREEK
Spiller Address: 329 GREENPOINT AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: KEVIN GRANT
Contact Phone: (718) 372-7193
Contact Ext:
Latitude: 40.731496000
Longitude: -73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	87 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WATER PLAN 329 GREENPOINT AVE RD E BROOKLYN NY	NY SPILLS

Spill No: 0804109
Site ID: 400959
DER Facility ID: 336055
CID: 27
Program Type: ER
SWIS Code: 2401
Water Body: WHALE CREEK
Class: D5
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Other
Reported by: Other
Referred to:
Source: Major Facility (MOSF) > 400,000 gal

UST Trust:
Spill Date: 07/09/2008 09:10:00 PM
Received Date: 07/09/2008 09:41:00 PM
CAC Date:
Insp Date:
Close Date: 07/14/2008 12:00:00 AM
Create Date: 07/10/2008 02:07:00 AM
Update Date: 07/14/2008 03:17:35 PM
DEC Region: 2
Lead DEC: smsanges
After Hours: True

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Plant can't handle the rain. Climber screen is out of service also."

DEC Remark:

""

Material Information

OP Unit ID:	1157768	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2148802	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	JIM DALEY
Spiller Company:	NEW TOWN CREEK WATER PLAN
Spiller Address:	329 GREENPOINT AVE RD E
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	JIM DALEY
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	88 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 301 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No:	0802371	**UST Trust:**	
Site ID:	398490	**Spill Date:**	05/31/2008 01:50:00 PM
DER Facility ID:	347845	**Received Date:**	05/31/2008 02:57:00 PM
CID:	81	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	06/02/2008 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	05/31/2008 03:11:00 PM
Class:	D5	**Update Date:**	06/02/2008 11:54:22 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Local Agency		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"heavy rain is cause, wet weather bypass"

DEC Remark:

""

Material Information

OP Unit ID:	1155375	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2146243	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	KEVIN GRANT
Spiller Company:	NEW TOWN CREEK
Spiller Address:	301 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	KEVIN GRANT
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	89 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK TREATMENT PLANT 329 GREEN POINT AVE - BROOKLYN NY	NY SPILLS

Spill No:	0810724	***UST Trust:***	False
Site ID:	408264	***Spill Date:***	12/25/2008 02:10:00 AM
DER Facility ID:	357516	***Received Date:***	12/25/2008 02:31:00 AM
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	12/26/2008 12:00:00 AM
Water Body:		***Create Date:***	12/25/2008 02:37:00 AM
Class:	C4	***Update Date:***	12/26/2008 10:41:46 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	SFRAHMAN
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"raw sewage spill due to weather unknown amount at this time."

DEC Remark:

"Referred to water division.(sr)"

Material Information

OP Unit ID:	1164784	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2156168	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	
Spiller Company:	WEATHER RELATED
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	SAME
Contact Phone:	
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

77	***90 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***DEP CONSTRUCTION SITE 329 GREENPOINT AVE BROOKLYN NY***	***NY SPILLS***

Spill No:	0803882	***UST Trust:***	
Site ID:	400690	***Spill Date:***	07/03/2008 10:15:00 AM
DER Facility ID:	335827	***Received Date:***	07/03/2008 10:33:00 AM
CID:	408	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	07/17/2008 12:00:00 AM
Water Body:		***Create Date:***	07/03/2008 10:44:00 AM
Class:	C4	***Update Date:***	07/17/2008 04:11:20 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	HRAHMED
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Human Error		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CONSTRUCTION CREWS THOUGHT PIPE WAS EMPTY AND CUT THROUGH IT RELEASING THE MATERIAL; CLEAN UP IN PROGRESS;"

DEC Remark:

"DEC Hassan Ahmed made a site visit. 07/03/08-HRAHMED-Ahmed went for investigation. DEP John Rosso, James Pynn and Brian Alford from Bidwell Environmental were present at the site. As per DEP Pynn, during the Construction crews were cutting the pipe that ran between the abundant tank and the building, some resudual oil spilled on the excavation area due to gravity. The contractor immidiately pump the spilled oil into steel drums. Ahmed took some pictures, minor stain on the soil was observed. Ahmed told DEP Pynn that the contractor has to excavate more to take out all contaminated soil, atleast using a PID to determine the extent of excavation. DEP Pynn told he will send a report summerizing the excavation work along with some pictures which will be taken after the excavation. 07/17/08-HRAHMED-Ahmed received email from DEP John Russo and some pictures taken after the excavation work. As per John, a CM EH&S Inspector took PID readings in the excavation area after clean-up was performed. The readings were taken

at the north, south, east, and west side walls of the excavation using a MultiRAE multi-gas meter which includes a PID. The readings were all non-detect (zero) for VOCs. As per the picture the excavation looks clean. This case is closed. "

Material Information

OP Unit ID:	1157504	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2148525	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	155.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	
Spiller Company:	SILVESRITE CONSTRUCTION
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	BRIAN ALFORD
Contact Phone:	(646) 739-3749
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

77	***91 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***NEWTOWN CREEK PLANT 329 GREEN POINT AVE BROOKLYN NY***	***NY SPILLS***

Spill No:	1010132	***UST Trust:***	False
Site ID:	443722	***Spill Date:***	12/26/2010 07:35:00 PM
DER Facility ID:	355035	***Received Date:***	12/26/2010 10:18:00 PM
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	12/27/2010 12:00:00 AM
Water Body:		***Create Date:***	12/26/2010 10:21:00 PM
Class:	C4	***Update Date:***	12/27/2010 11:04:11 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	SFRAHMAN
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"hypo pump interruption - plant wide power dip - If this happens, they have to notify state - NO LEAK"

DEC Remark:

"Referred to Water Division.(sr)"

Material Information

OP Unit ID:	1194173	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2189895	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	1113A		
Material Name:	hypochloric acid		

Spiller Information

Spiller Name:	
Spiller Company:	NYC DEP
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	SHAWN SCAGLIONE
Contact Phone:	(718) 389-2002
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	92 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WATER POLL 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0603777	***UST Trust:***	False
Site ID:	366559	***Spill Date:***	07/06/2006 04:30:00 AM
DER Facility ID:	241520	***Received Date:***	07/06/2006 04:48:00 AM
CID:	74	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	07/06/2006 12:00:00 AM
Water Body:	WHALE CREEK	***Create Date:***	07/06/2006 05:00:00 AM
Class:		***Update Date:***	07/06/2006 10:22:53 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	SFRAHMAN
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"non compliance Unable to pump 2 x dry weather flow - due to heavy screenings Pumping 574mgd "

DEC Remark:

"07/06/06 Rahman-Referred to water division."

Material Information

OP Unit ID:	1124495	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2113993	***Med SW:***	True

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	JIM DALY
Spiller Company:	NEW TOWN CREEK WATER POLL
Spiller Address:	301 GREENPOINTAVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	JIM DALY
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	
Longitude:	

77	93 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WPCP 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0610972	**UST Trust:**	False
Site ID:	375514	**Spill Date:**	01/01/2007 07:00:00 AM
DER Facility ID:	241520	**Received Date:**	01/01/2007 07:32:00 AM
CID:	76	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	01/02/2007 12:00:00 AM
Water Body:		**Create Date:**	01/01/2007 07:57:00 AM
Class:	D5	**Update Date:**	01/02/2007 09:26:05 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SMSANGES
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CALLER REPORTS SPILL DUE TO HEAVY SCREENING AT 13TH STREET. AFFECTED AREA IS THE EAST RIVER. SPILL IS ONGOING."

DEC Remark:

""

Material Information

OP Unit ID:	1133148	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2122950	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	SEE RIZZO
Spiller Company:	NEW TOWN CREEK WPCP
Spiller Address:	301 GREENPOINTAVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	SEE RIZZO
Contact Phone:	(212) 982-8800
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	94 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0610780	**UST Trust:**	
Site ID:	375289	**Spill Date:**	12/22/2006 10:15:00 PM
DER Facility ID:	159801	**Received Date:**	12/22/2006 11:03:00 PM
CID:	62	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	12/26/2006 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	12/23/2006 02:07:00 AM
Class:		**Update Date:**	12/26/2006 01:22:29 PM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	HRPATEL
REM Phase:	0	**After Hours:**	
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Local Agency		
Referred to:			
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

""

DEC Remark:

"referred to Water division."

Material Information

OP Unit ID:	1132930	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2122722	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Information

Spiller Name:	RICHARD DESFOSSE
Spiller Company:	NEWTOWN CREEK
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	RICHARD DESFOSSE
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

77	95 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK DEP SITE 329 GREEN POINT AVE BROOKLYN NY 11222	NY SPILLS

Spill No:	1001677	***UST Trust:***	False
Site ID:	434751	***Spill Date:***	05/13/2010 09:25:00 AM
DER Facility ID:	352614	***Received Date:***	05/13/2010 09:41:00 AM
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	05/17/2010 12:00:00 AM
Water Body:		***Create Date:***	05/13/2010 09:44:00 AM
Class:	C4	***Update Date:***	05/17/2010 11:11:51 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	smsanges
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"hose failure caused leak. Clean up complete."

DEC Remark:

"After filling a fuel tank, delivery company rep turned off the nozzel and pulled out of the tank. Small amount of diesel still in nozzel spilled on the tank and ran down to the floor. Cleanup done with spill pads."

Material Information

OP Unit ID:	1185556	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2180284	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.25	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.25	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	RONNIE KELNER

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Company:	SILVERITE CONSTRUCTION
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	WINNIE LANHAM
Contact Phone:	(914) 618-0084
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	96 of175	NE	0.12 / 649.95	9.75 / -2	NYC DEP FACILITY 329 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No:	1001442	**UST Trust:**	False
Site ID:	434496	**Spill Date:**	05/06/2010 02:30:00 PM
DER Facility ID:	335827	**Received Date:**	05/06/2010 07:04:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	05/07/2010 12:00:00 AM
Water Body:		**Create Date:**	05/06/2010 07:07:00 PM
Class:		**Update Date:**	05/07/2010 11:06:17 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	hrpatel
REM Phase:	0	**After Hours:**	True

County:	Kings
Contributing Factor:	Equipment Failure
Reported by:	Other
Referred to:	
Source:	Commercial Vehicle
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Caller reporting a spill of 1 gallon of diesel to soil. Spill is contained and cleaned."

DEC Remark:

"05/07/10-Hiralkumar Patel. 11:04 AM:- spoke with Justin at NYC DEP. he mentioned that contractor's excavator tipped over into concrete trench with dirt on bottom. as excavator stuck in trench for some time, about 1 gal diesel spilled on dirt which was cleaned up immediately. case closed."

Material Information

OP Unit ID:	1185320	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2179638	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	1.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		

Material Code:	0008
Material Name:	diesel

Spiller Information

Spiller Name:	
Spiller Company:	TESTA/ SCAMSCA
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Zip:
Spiller Country: 999
Contact Name: JUSTIN MAURELIO
Contact Phone: (718) 717-5283
Contact Ext:
Latitude: 40.731496000
Longitude: -73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	97 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK PLANT DEP 329 GREEN POINT AVE BROOKLYN NY 11222	NY SPILLS

Spill No: 0806630
Site ID: 403919
DER Facility ID: 352614
CID:
Program Type: ER
SWIS Code: 2401
Water Body: EAST RIVER
Class:
Meets Std: False
Penalty: False
REM Phase: 0
UST Trust: False
Spill Date: 09/12/2008 05:15:00 PM
Received Date: 09/12/2008 05:51:00 PM
CAC Date:
Insp Date:
Close Date: 09/15/2008 12:00:00 AM
Create Date: 09/12/2008 06:00:00 PM
Update Date: 09/15/2008 10:06:33 AM
DEC Region: 2
Lead DEC: jbvought
After Hours: False
County: Kings
Contributing Factor: Deliberate
Reported by: Responsible Party
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Deliberate release due to heavy rain; 636 mgd released into East River 2157: John Napoli reports back in compliance as of 2125hrs"

DEC Remark:

"09/15/08-Vought-Off hours responder. Non petrolem spill and spill closed and referred to DEC Water Unit Ed Rossan."

Material Information

OP Unit ID: 1160602
OU: 01
Material ID: 2151777
CAS No:
Material Family: Other
Quantity:
Units:
Recovered:
Med Soil: False
Med Air: False
Material Code: 0060A
Material Name: wastewater
Med Ind Air: False
Med GW: False
Med SW: True
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: PANAVILA ROY
Spiller Company: NEWTOWN CREEK PLANT
Spiller Address: 329 GREEN POINT AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip: 11222
Spiller Country: 999
Contact Name: PANAVILA ROY
Contact Phone: (718) 389-2002
Contact Ext:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Latitude:		40.731496000				
Longitude:		-73.946413000				

77	98 of175	NE	0.12 / 649.95	9.75 / -2	Spill Number 0206432 329 GREENPORT AVE BROOKLYN NY	NY SPILLS

Spill No:	0206432	**UST Trust:**	False
Site ID:	265992	**Spill Date:**	09/20/2002 02:46:00 PM
DER Facility ID:	216754	**Received Date:**	09/20/2002 02:46:00 PM
CID:	207	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	12/08/2003 12:00:00 AM
Water Body:		**Create Date:**	09/20/2002 12:00:00 AM
Class:	C3	**Update Date:**	12/08/2003 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	TJDEMEO
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"contaminated soil historical spill"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO 12/8/03 TJD Unregulated substance. Spill closed."

Material Information

OP Unit ID:	857915	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	517039	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0048A		
Material Name:	dye		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	***Update***
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	ELLEN METZGER
Contact Phone:	(914) 987-1755
Contact Ext:	
Latitude:	40.731275610
Longitude:	-73.946992490

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	99 of175	NE	0.12 / 649.95	9.75 / -2	ELEVATION -1 IN MAIN BLD 329 GREEN POINT AVE BROOKLYN NY	NY SPILLS

Spill No:	0908307	**UST Trust:**	False
Site ID:	420902	**Spill Date:**	10/08/2009 08:00:00 AM
DER Facility ID:	355035	**Received Date:**	10/23/2009 03:24:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/26/2009 12:00:00 AM
Water Body:		**Create Date:**	10/23/2009 03:28:00 PM
Class:	C4	**Update Date:**	10/26/2009 04:21:26 PM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	False

County: Kings
Contributing Factor: Human Error
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"contained within the channel; caller states the material never entered the treatment process.clean up complete"

DEC Remark:

"spill contained - cleanup complete"

Material Information

OP Unit ID:	1176840	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2169543	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	5.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	5.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0021
Material Name: transmission fluid

Spiller Information

Spiller Name:
Spiller Company: SILVER RITE CONTRACTING
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: BERNARD VANCE
Contact Phone: (646) 235-7505
Contact Ext:
Latitude: 40.731496000
Longitude: -73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	100 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WATER POLLUTION CONTROL PLANT 329 GREEN POINT AVE BROOKLYN NY 11222	NY SPILLS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spill No:	0806127	**UST Trust:**	False
Site ID:	403388	**Spill Date:**	08/30/2008 04:15:00 AM
DER Facility ID:	352614	**Received Date:**	08/30/2008 05:09:00 AM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	09/02/2008 12:00:00 AM
Water Body:	WHALE CREEK	**Create Date:**	08/30/2008 05:13:00 AM
Class:	D5	**Update Date:**	09/02/2008 11:15:40 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Local Agency		
Referred to:			
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Ongoing raw sewage into Whale Creek; caused by rain. R2 Spills/Kumar Patel paged at 0515, notified at 0517."

DEC Remark:

""

Material Information

OP Unit ID:	1160091	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2151246	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	JIM DALY
Spiller Company:	NEWTOWN CREEK WATER POLLUTION CONTROL PLANT
Spiller Address:	329 GREEN POINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	999
Contact Name:	JIM DALY
Contact Phone:	
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

77	101 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 329 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No:	0708099	**UST Trust:**	
Site ID:	388936	**Spill Date:**	10/24/2007 10:00:00 AM
DER Facility ID:	335827	**Received Date:**	10/24/2007 12:05:00 PM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SWIS Code:	2401	**Close Date:**	10/26/2007 12:00:00 AM
Water Body:		**Create Date:**	10/24/2007 12:27:00 PM
Class:	D5	**Update Date:**	10/26/2007 11:04:32 AM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	
County:	Kings		
Contributing Factor:	Human Error		
Reported by:	Local Agency		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"OPERATER ERA: HOLDING IN SECONDARY CONTAINM,ENT AND IS PUMPING BACK AT THIS TIME"

DEC Remark:

"Copy forwarded to DEC Water Division"

Material Information

OP Unit ID:	1146089	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2136452	**Med SW:**	False
CAS No:	07681529	**Med DW:**	False
Material Family:	Hazardous Material	**Med Sewer:**	False
Quantity:	5800.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0124A		
Material Name:	sodium hypochlorite		

Spiller Information

Spiller Name:	RICH KENNEDY
Spiller Company:	NEWTOWN CREEK
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	RICH KENNEDY
Contact Phone:	(718) 389-2002
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	102 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 329 GREENPOINT AVE RD E BROOKLYN NY	NY SPILLS

Spill No:	0706475	**UST Trust:**	
Site ID:	386998	**Spill Date:**	09/10/2007 02:15:00 PM
DER Facility ID:	336055	**Received Date:**	09/10/2007 02:15:00 PM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/25/2007 12:00:00 AM
Water Body:		**Create Date:**	09/10/2007 02:34:00 PM
Class:	C4	**Update Date:**	10/25/2007 10:34:53 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	smsanges

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"AN OIL TANK WAS LEFT OUT AND THE RAIN CAUSED IT TOP OVERFLOW AND LEAK OUT ABOUT 1 CUP AND IS ALL CLEANED"

DEC Remark:

"minor spill - all cleaned"

Material Information

OP Unit ID:	1144222	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2134519	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	JOANNA KOENIG
Spiller Company:	NEWTOWN CREEK
Spiller Address:	329 GREENPOINT AVE RD E
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	JOANNA KOENIG
Contact Phone:	(646) 739-3748
Contact Ext:	
Latitude:	
Longitude:	

77	103 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK PLANT 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0609972	**UST Trust:**	False
Site ID:	374335	**Spill Date:**	12/01/2006 08:50:00 PM
DER Facility ID:	241520	**Received Date:**	12/01/2006 10:20:00 PM
CID:	64	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	12/04/2006 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	12/02/2006 02:08:00 AM
Class:		**Update Date:**	12/04/2006 11:24:49 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	JBVOUGHT
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

""

DEC Remark:

"12/4/06-Vought-Off hours spill responder. Non-petroleum spill. Spill closed and referred to DEC Water Unit."

Material Information

OP Unit ID:	1132012	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2121730	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	JIM DALY
Spiller Company:	NEW TOWN CREEK PLANT
Spiller Address:	301 GREENPOINTAVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	JIM DALY
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	104 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 329 GREENPOINT AV BROOKLYNN NY	NY SPILLS

Spill No:	0805108	**UST Trust:**	
Site ID:	402151	**Spill Date:**	08/02/2008 12:20:00 PM
DER Facility ID:	351361	**Received Date:**	08/02/2008 01:39:00 PM
CID:	81	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	08/05/2008 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	08/04/2008 08:23:00 AM
Class:	D5	**Update Date:**	08/05/2008 11:07:51 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Heavy rain and screenings. Flowing into east river. This is a non compliance"

DEC Remark:

""

Material Information

OP Unit ID:	1158917	***Med Ind Air:***	False
OU:	01	***Med GW:***	True
Material ID:	2150023	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	-
Spiller Country:	001
Contact Name:	KEVIN GRANT
Contact Phone:	(718) 372-3193
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

77	***105 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***NEWTOWN CREEK TREATMENT 329 GREENPOINT AVENUE BROOKLYN NY***	***NY SPILLS***

Spill No:	0307763	***UST Trust:***	False
Site ID:	310474	***Spill Date:***	10/22/2003 09:10:00 PM
DER Facility ID:	159801	***Received Date:***	10/22/2003 10:09:00 PM
CID:	195	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	10/23/2003 12:00:00 AM
Water Body:	WELLS CREEK	***Create Date:***	10/22/2003 12:00:00 AM
Class:	E5	***Update Date:***	10/23/2003 12:00:00 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	MXTIPPLE
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"PIPE RUPTURED SPILLING SLUDGE INTO STREET AND INTO SEWER. SEWER EMPTIES INTO WELLS CREEK."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE Ref. to the Division of Water. YK. "

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material Information

OP Unit ID:	874139	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	501290	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	200.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0058A		
Material Name:	sludge		

Spiller Information

Spiller Name:	DEAN SCARI
Spiller Company:	NYC DEP
Spiller Address:	59-17 JUNCTION BLVD
Spiller City:	FLUSHING
Spiller State:	NY
Spiller Zip:	-
Spiller Country:	001
Contact Name:	JIM DALY
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	40.731275610
Longitude:	-73.946992490

77	***106 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***NEW TOWN CREEK WP 329 GREENPOINT AVE RD E BROOKLIN NY***	***NY SPILLS***

Spill No:	0805503	***UST Trust:***	
Site ID:	402613	***Spill Date:***	08/12/2008 07:10:00 PM
DER Facility ID:	351818	***Received Date:***	08/12/2008 09:55:00 PM
CID:	62	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	08/13/2008 12:00:00 AM
Water Body:	EAST RIVER	***Create Date:***	08/13/2008 02:07:00 AM
Class:	D5	***Update Date:***	08/13/2008 10:58:35 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	smsanges
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"heavy rain and heavy screening"

DEC Remark:

""

Material Information

OP Unit ID:	1159367	***Med Ind Air:***	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OU:	01	**Med GW:**	False
Material ID:	2150480	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	KEVIN GRANT
Spiller Company:	NEW TOWN CREEK WP
Spiller Address:	329 GREENPOINT AVE RD E
Spiller City:	BROOKLIN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	KEVIN GRANT
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	107 of175	NE	0.12 / 649.95	9.75 / -2	Spill Number 0108649 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0108649	**UST Trust:**	False
Site ID:	310473	**Spill Date:**	11/28/2001 10:10:00 AM
DER Facility ID:	159801	**Received Date:**	11/28/2001 02:50:00 PM
CID:	211	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	11/29/2001 12:00:00 AM
Water Body:		**Create Date:**	11/28/2001 12:00:00 AM
Class:	C3	**Update Date:**	11/30/2001 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	JAKOLLEE
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Traffic Accident		
Reported by:	Other		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CONSTRUCTION SITE EQUIPMENT RAN OVER 2 5-GAL PAILS OF PRODUCT; SPILL CLEANED UP."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY KOLLEENY SPOKE TO ELLEN METZGER OF BIDWELL ENVIRONMENTAL ON 11/28/01 (DATE OF SPILL) AND FOLLOW-UP CALL ON 11/29/01 TO CONFIRM CLEANUP. MS. METZGER SAYS CONSTRUCTION SITE IS ON OLD EXXON TERMINAL, AND SPILL OCCURRED WITHIN AN AREA WHICH WILL BE THE FOOTPRINT OF A FUTURE BUILDING; AREA IS SURROUNDED BY SHEETING AND SOIL WILL BE EXCAVATED AND DISPOSED OF AS PETROLEUM-CONTAMINATED. NEVERTHELESS, SHE DIRECTED CONSTRUCTION CO. TO DIG UP THE SOIL IMPACTED BY THIS SPILL. THIS HAS BEEN DONE; THEY EXCAVATED ONE 55-GALLON DRUM OF MATERIAL, WHICH WILL BE PROPERLY DISPOSED OF."

Material Information

OP Unit ID:	846807	**Med Ind Air:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OU:	01	**Med GW:**	False
Material ID:	529891	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	10.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	10.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0015		
Material Name:	motor oil		

Spiller Information

Spiller Name:	
Spiller Company:	JOHN PICONE CONTRACTORS
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	ELLEN METZGER
Contact Phone:	(914) 987-1755
Contact Ext:	
Latitude:	40.731275610
Longitude:	-73.946992490

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	108 of175	NE	0.12 / 649.95	9.75 / -2	NEWTON CREEK PLANT 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0703611	**UST Trust:**	False
Site ID:	383585	**Spill Date:**	06/27/2007 10:30:00 PM
DER Facility ID:	241520	**Received Date:**	06/28/2007 12:03:00 AM
CID:	77	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	06/28/2007 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	06/28/2007 02:08:00 AM
Class:		**Update Date:**	06/28/2007 09:11:07 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	jbvought
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Wet weather bypass, ongoing."

DEC Remark:

"06/28/07-Vought-Non petroleum spill. This spill closed and referred to DEC Water Unit."

Material Information

OP Unit ID:	1140925	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2131036	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	
Spiller Company:	NYC DEP
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	-
Spiller Country:	001
Contact Name:	JIM DALY
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	
Longitude:	

77	109 of175	NE	0.12 / 649.95	9.75 / -2	NYC SEWAGE TREATMENT PLANT 329 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No:	0904709	**UST Trust:**	False
Site ID:	416915	**Spill Date:**	07/23/2009 08:30:00 AM
DER Facility ID:	335827	**Received Date:**	07/23/2009 09:58:00 AM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	07/24/2009 12:00:00 AM
Water Body:		**Create Date:**	07/23/2009 10:00:00 AM
Class:	C4	**Update Date:**	07/24/2009 04:26:56 PM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Local Agency		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"DUE TO A FAILED VALVE AN UNK AMOUNT OF PRODUCT HAS BEEN DISCHARGED INTO SECONDARY CONTAINMENT. CLEAN UP PENDING."

DEC Remark:

"spill was confined to the containment area in the plant. Spill material was redirected by drains into the head of the plant for processing. No release to the river."

Material Information

OP Unit ID:	1173174	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2165065	**Med SW:**	False
CAS No:	07681529	**Med DW:**	False
Material Family:	Hazardous Material	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Med Soil: False
Med Air: False
Material Code: 0124A
Material Name: sodium hypochlorite
Oxygenate:

Spiller Information

Spiller Name: JOE REDDINGTON
Spiller Company: NYC SEWAGE TREATMENT PLANT
Spiller Address: 329 GREENPOINT AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: JOE REDDINGTON
Contact Phone: (718) 389-2002
Contact Ext:
Latitude: 40.731496000
Longitude: -73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	110 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WATER POLLUTION CONTROL PLANT 329 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No: 0810614
Site ID: 408147
DER Facility ID: 335827
CID:
Program Type: ER
SWIS Code: 2401
Water Body: NEWTOWN CREEK
Class: D5
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Local Agency
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data
UST Trust: False
Spill Date: 12/21/2008 10:15:00 AM
Received Date: 12/21/2008 11:04:00 AM
CAC Date:
Insp Date:
Close Date: 12/22/2008 12:00:00 AM
Create Date: 12/21/2008 11:07:00 AM
Update Date: 12/22/2008 09:51:42 AM
DEC Region: 2
Lead DEC: smsanges
After Hours: True

Caller Remark:

"#2 climber screen is out of service."

DEC Remark:

""

Material Information

OP Unit ID: 1164667
OU: 01
Material ID: 2156054
CAS No:
Material Family: Other
Quantity:
Units:
Recovered:
Med Soil: False
Med Air: False
Material Code: 0062A
Material Name: raw sewage
Med Ind Air: False
Med GW: False
Med SW: True
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:	MONOHAN
Spiller Company:	NYC DEP
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	MONOHAN
Contact Phone:	
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

77	111 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 329 GREENPOINT AVE RD E BROOKLYN NY	NY SPILLS

Spill No:	0710497	***UST Trust:***	
Site ID:	391799	***Spill Date:***	01/04/2008 11:20:00 AM
DER Facility ID:	336055	***Received Date:***	01/04/2008 12:19:00 PM
CID:	444	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	01/07/2008 12:00:00 AM
Water Body:		***Create Date:***	01/04/2008 12:43:00 PM
Class:	D4	***Update Date:***	01/07/2008 01:33:56 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	RMPIPER
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"BATERY FROM A CRANE BURST AND LEAKED ACID: ABOUT 2 QUARTS: ALL CLEANED"

DEC Remark:

"small spill to waterway. cleaned. closed."

Material Information

OP Unit ID:	1148833	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2139329	***Med SW:***	False
CAS No:	07664939	***Med DW:***	False
Material Family:	Hazardous Material	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0039A		
Material Name:	sulfuric acid		

Spiller Information

Spiller Name:	JOANNA KOENIG

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Company:	NEWTOWN CREEK
Spiller Address:	329 GREENPOINT AVE RD E
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	JOANNA KOENIG
Contact Phone:	(646) 739-3748
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	112 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0606073	**UST Trust:**	False
Site ID:	369368	**Spill Date:**	08/26/2006 03:20:00 AM
DER Facility ID:	241520	**Received Date:**	08/26/2006 03:55:00 AM
CID:	64	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	08/28/2006 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	08/26/2006 04:03:00 AM
Class:	D4	**Update Date:**	08/28/2006 09:48:21 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SMSANGES
REM Phase:	0	**After Hours:**	True

County:	Kings
Contributing Factor:	Other
Reported by:	Responsible Party
Referred to:	
Source:	Major Facility (MOSF) > 400,000 gal
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"clogged screens due to rain."

DEC Remark:

""

Material Information

OP Unit ID:	1127205	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2116794	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code:	0062A
Material Name:	raw sewage

Spiller Information

Spiller Name:	
Spiller Company:	NEWTOWN CREEK
Spiller Address:	301 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222

Spiller Country: 001
Contact Name: JIM DALY
Contact Phone: (718) 372-7193
Contact Ext:
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	113 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WPCP 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 0510010
Site ID: 355895
DER Facility ID: 241520
CID: 41
Program Type: ER
SWIS Code: 2401
Water Body: EAST RIVER
Class: D4
Meets Std: False
Penalty: False
REM Phase: 0
UST Trust: False
Spill Date: 11/21/2005 08:30:00 PM
Received Date: 11/21/2005 09:21:00 PM
CAC Date:
Insp Date:
Close Date: 11/23/2005 12:00:00 AM
Create Date: 11/22/2005 09:04:00 AM
Update Date: 09/14/2006 07:49:52 AM
DEC Region: 2
Lead DEC: SMSANGES
After Hours: True
County: Kings
Contributing Factor: Other
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"471 million gallons per day - non-compliance - chlorine residual below 0.5 mg/l - hypo pump failure - ending time 2110 - went into East River"

DEC Remark:

""

Material Information

OP Unit ID: 1113226
OU: 01
Material ID: 2103292
CAS No:
Material Family: Other
Quantity: .00
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0062A
Material Name: raw sewage
Med Ind Air: False
Med GW: False
Med SW: True
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: SAME
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: MR R PIERRE
Contact Phone: (718) 389-2002
Contact Ext:
Latitude: 40.731117000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Longitude:		-73.947406000				

77	114 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0508162	**UST Trust:**	
Site ID:	353702	**Spill Date:**	10/08/2005 02:00:00 AM
DER Facility ID:	241520	**Received Date:**	10/08/2005 05:41:00 AM
CID:	73	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/11/2005 12:00:00 AM
Water Body:	WHEEL CREEK	**Create Date:**	10/08/2005 06:23:00 AM
Class:	D4	**Update Date:**	10/11/2005 10:24:41 AM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	SMSANGES
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"NON-COMPLIANCE. STOPPED AT 4:00 AM."

DEC Remark:

"forwarded to DEC Water"

Material Information

OP Unit ID:	1111151	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2101193	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	MR. CHIU
Spiller Company:	NEWTOWN CREEK
Spiller Address:	301 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	MR. CHIU
Contact Phone:	(718) 389-2002
Contact Ext:	
Latitude:	40.731117000
Longitude:	-73.947406000

77	115 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP DEP - DDC	NY SPILLS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

301 GREENPOINT AVENUE
BROOKLYN NY

Spill No:	9504909	***UST Trust:***	False
Site ID:	325034	***Spill Date:***	07/21/1995 10:00:00 AM
DER Facility ID:	241520	***Received Date:***	07/23/1995 09:10:00 AM
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	05/05/2005 12:00:00 AM
Water Body:		***Create Date:***	08/14/1995 12:00:00 AM
Class:	C4	***Update Date:***	07/07/2005 02:42:40 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	AIIslam
REM Phase:	0	***After Hours:***	True

County: Kings
Contributing Factor: Equipment Failure
Reported by: Responsible Party
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"BATTERY (NEW YORK HARBOR)"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY SPILL CASE IS TRANSFERRED TO I. ISLAM 5/5/05- According to the description, the spill was discharged in to the sewage system. Moreover, the site has multiple open spills and is currently under investigation by PMS Construction Mgt. and Shaw Envtl. for future remediation, As such, this spill is closed. - II. "

Material Information

OP Unit ID:	1015817	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	366434	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	3.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		

Material Code: 0066A
Material Name: unknown petroleum

OP Unit ID:	1015817	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	366435	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	L	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		

Material Code: 0062A
Material Name: raw sewage

Spiller Information

Spiller Name:
Spiller Company: NYCDEP NEWTOWN CREEK WPCP
Spiller Address:
Spiller City:
Spiller State: ZZ

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.731117000
Longitude: -73.947406000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	116 of175	NE	0.12 / 649.95	9.75 / -2	CONSTRUCTION SITE 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 0513125
Site ID: 359549
DER Facility ID: 159801
CID: 408
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C4
Meets Std: False
Penalty: False
REM Phase: 0
UST Trust: False
Spill Date: 01/04/2006 02:05:00 PM
Received Date: 02/14/2006 02:05:00 PM
CAC Date:
Insp Date:
Close Date: 02/17/2006 12:00:00 AM
Create Date: 02/14/2006 02:25:00 PM
Update Date: 02/17/2006 09:57:39 AM
DEC Region: 2
Lead DEC: HRPATEL
After Hours: False
County: Kings
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Commercial Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"DUE TO ALEAK FROM A MANLIFT, PRODUCT WAS 2 CUPS. HAS BEEN CLEANED UP"

DEC Remark:

"02/16/06-Hiralkumar Patel. Left message for Benjamin at Bidwell. 02/17/06-Hiralkumar Patel. Spoke with Benjamin. all cleaned up. environment unaffected. case closed."

Material Information

OP Unit ID: 1116755
OU: 01
Material ID: 2107204
CAS No:
Material Family: Petroleum
Quantity:
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0001A
Material Name: #2 fuel oil
Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: BENJAMIN POTTS
Spiller Company: SILVERITE CONSTRUCTION
Spiller Address: 329 GREENPOINT AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: BENJAMIN POTTS
Contact Phone: (718) 609-8797

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Ext:
Latitude: 40.731502000
Longitude: -73.946336000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	117 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP DEP - DDC 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 8602874
Site ID: 270074
DER Facility ID: 241520
CID:
Program Type: ER
SWIS Code: 2401
Water Body: EAST RIVER
Class:
Meets Std: True
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Responsible Party
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 08/31/1986 03:45:00 PM
Received Date: 07/31/1986 04:29:00 PM
CAC Date: 07/31/1986 12:00:00 AM
Insp Date:
Close Date: 07/31/1986 12:00:00 AM
Create Date: 09/11/1986 12:00:00 AM
Update Date: 07/07/2005 02:47:50 PM
DEC Region: 2
Lead DEC: UNASSIGNED
After Hours: False

Caller Remark:

"TRIPPED REGULATOR"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was "

Material Information

OP Unit ID: 900135
OU: 01
Material ID: 475731
CAS No:
Material Family: Other
Quantity: .00
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0630A
Material Name: nonene

Med Ind Air: False
Med GW: False
Med SW: True
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: NYCDEP
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.731117000
Longitude: -73.947406000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	118 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK PLANT 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 0502107
Site ID: 346401
DER Facility ID: 241520
CID: 62
Program Type: ER
SWIS Code: 2401
Water Body: NEW TOWN CREEK
Class: D4
Meets Std: True
Penalty:
REM Phase: 0
County: Kings
Contributing Factor: Other
Reported by: Local Agency
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 05/21/2005 08:05:00 PM
Received Date: 05/21/2005 08:54:00 PM
CAC Date:
Insp Date:
Close Date: 05/25/2005 12:00:00 AM
Create Date: 05/22/2005 12:09:00 PM
Update Date: 05/25/2005 12:45:31 PM
DEC Region: 2
Lead DEC: SMSANGES
After Hours: True

Caller Remark:

"Number 1 main sewer pump out of service for maintenance. Unable to pump 2 times dry weather flow."

DEC Remark:

""

Material Information

OP Unit ID: 1104172
OU: 01
Material ID: 584332
CAS No:
Material Family: Other
Quantity: .00
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0062A
Material Name: raw sewage

Med Ind Air: False
Med GW: False
Med SW: True
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: MR. PIERRE
Spiller Company: NEW TOWN CREEK PLANT
Spiller Address: 301 GREENPOINT AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip: 11222
Spiller Country: 001
Contact Name: MR. PIERRE
Contact Phone: (718) 372-7193
Contact Ext:
Latitude: 40.731117000
Longitude: -73.947406000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	119 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP DEP - DDC (JK) 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spill No:	9907560	**UST Trust:**	False
Site ID:	213750	**Spill Date:**	09/23/1999 09:47:00 AM
DER Facility ID:	241520	**Received Date:**	09/23/1999 09:47:00 AM
CID:	205	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	
Water Body:		**Create Date:**	09/23/1999 12:00:00 AM
Class:	B3	**Update Date:**	09/18/2024 02:58:20 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	AXDORONO
REM Phase:	1	**After Hours:**	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Responsible Party		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CALLER RECEIVED REPORT BACK ON SOIL TEST. SOIL CONTAMINATED."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY LIRO OVERSAW CLOSURE OF NON-MOTOR FUEL TANKS; PMS IS OVERALL REMEDIATION CONTRACTOR FOR SITE; THEY WILL NOW HANDLE INVESTIGATION/REMEDIATION OF THIS AND OTHER NON-MOTOR FUEL UST SPILLS. 8/22/06 DEC lead transferred from I. Islam to J.A. Maisonave. - JAM 7/3/08 Sent email to Afsar Samani at the DDC requesting information about two spills, which occurred at Newtown Creek WPCP (spill #'s 9907560 & 0000867). Ms. Samani replied with the following: DDC decided to have DEP continue to handle all the spills associated with this site. This site is undergoing some major construction by NYCDEP. The owner agency is funding and managing all aspect of the construction work which included some petroleum spill clean-up in the past. NYCDDC took the position that it is best for the owner agency NYCDEP to continue to handle all aspect of work at this site. DDC's consultant LiRo performed some non-motor vehicle tank closure at this site in the past. The NYCDEP needs to be contacted to address these two spill cases. - JAM 6/17/09 Sent email to Afsar Samani at NYCDDC requesting a contact at DEP who has been involved with construction activities mentioned in email dated July 3, 2008. She replied with contact: Ms. Shay McAdams @ (718) 595-4618 in Bureau of Water Supply EHS Office. - JAM 12/20/10: This spill case transferred from J. Maisonave to J. Kolleeny. - JK 01/16/20: I sent email to Mr. Mohammad Mahmud of NYCDEP, cc to Mr. Bill Yulinsky of DEP: Dear Mr. Mahmud, I am writing to inquire about two open petroleum spill cases that were reported years ago at above-referenced DEP facility [Newtown Creek WPCP], and which remain open and active in our database. Both of these spill cases seem to have involved discovery of contaminated soil during construction work at site. Spill No. 9907560 was reported by Abro Consulting; Spill No. 0000867 was reported by Bidwell Envt'l. I have attached copies of spill rpts for your convenience, altho they provide limited information. I am hoping that you may be able to provide addt'l information regarding these incidents that will either allow me to close out spill cases in our database, or point a way to further actions that will move these spill cases towards closure. Please confirm your receipt of this email and let me know if you can be of assistance in this matter. - JK 09/09/2024: In 12/2021, I was contacted by Ms. Menzy Woodis of DEP, told her I need 1 or 2 GW samples in area of USTs to close out two Newtown Creek WPCP spills. I provided a LiRo site plan to her. But she didn't follow up with me and attempts to contact her by email & phone in June & October 2022 went unanswered. Her contact info, email: try either mwoodis@dep.nyc.gov or mjeanbaptiste@dep.nyc.gov; phone: Office - (718) 595-4285; Cell - (646) 584-1837. Copied on her emails were David Anthony Olton (davidanthonyo@dep.nyc.gov) and Omid Khalpari (okhalpari@dep.nyc.gov). - J. Kolleeny 09/17/2024: This spill case was transferred to A. Doronova. AD"

Material Information

OP Unit ID:	1081839	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	300259	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	CALLER
Spiller Company:	NYC DEP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Address: 301 GREEN POINT AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip: -
Spiller Country: 001
Contact Name: CALLER
Contact Phone:
Contact Ext:
Latitude: 40.730794790
Longitude: -73.948598750

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	120 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WATER POLLUTION CONTROL PLANT 329 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No: 1007898
Site ID: 441347
DER Facility ID: 335827
CID:
Program Type: ER
SWIS Code: 2401
Water Body:
Class:
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 10/26/2010 07:13:00 AM
Received Date: 10/26/2010 10:51:00 AM
CAC Date:
Insp Date:
Close Date: 10/26/2010 12:00:00 AM
Create Date: 10/26/2010 10:55:00 AM
Update Date: 10/26/2010 01:48:05 PM
DEC Region: 2
Lead DEC: vszhune
After Hours: False

Caller Remark:

"Caller reporting a spill of 1100 Gallons of Ferric Cholride. Clean up is in progress."

DEC Remark:

"10/26/10-Zhune. responded to this site. Spoke to Richard Kennedy DEP-Environmental Health and Safety Engineer. He said at 7:13 am the computer detected low pressure and sensor stop. They shut the pump out at 7:19 am. The fedding sensor (located on the suction line) of one of the three ferric chloride tank broke. spill went into the grids then to the contaiment area and then back to the tank. Everything was recovered. Spill Closed "

Material Information

OP Unit ID: 1191913
OU: 01
Material ID: 2187117
CAS No: 07705080
Material Family: Hazardous Material
Quantity: 1100.00
Units: G
Recovered:
Med Soil: False
Med Air: False
Material Code: 0076A
Material Name: ferric chloride

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: RICH KENNEDY
Spiller Company: NYC DEP
Spiller Address: 329 GREENPOINT AVE
Spiller City: BROOKLYN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	JOE REDDINGTON
Contact Phone:	(347) 386-6609
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	121 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WATER POLL CONTROL 329 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No:	1308089	**UST Trust:**	False
Site ID:	488802	**Spill Date:**	11/07/2013 04:00:00 PM
DER Facility ID:	335827	**Received Date:**	11/07/2013 05:36:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	11/08/2013 12:00:00 AM
Water Body:		**Create Date:**	11/07/2013 05:40:00 PM
Class:		**Update Date:**	11/08/2013 12:55:22 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	HRAHMED
REM Phase:	0	**After Hours:**	False

County:	Kings
Contributing Factor:	Equipment Failure
Reported by:	Responsible Party
Referred to:	
Source:	Institutional, Educational, Gov., Other
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Spilled onto concrete and into containment area. Cleanup is underway."

DEC Remark:

"11/8/13- Ahmed - Non-petroleum spill on concrete, cleaned up. This spill is closed."

Material Information

OP Unit ID:	1238405	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2238326	**Med SW:**	False
CAS No:	07705080	**Med DW:**	False
Material Family:	Hazardous Material	**Med Sewer:**	False
Quantity:	1.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		

Material Code:	0076A
Material Name:	ferric chloride

Spiller Information

Spiller Name:	RIDDINGTON,JOE
Spiller Company:	NEW TOWN CREEK WATER POLL CONTROL
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	RIDDINGTON,JOE

Contact Phone: (347) 386-6609
Contact Ext:
Latitude: 40.731496000
Longitude: -73.946413000

---

77 | **122 of175** | **NE** | **0.12 / 649.95** | **9.75 / -2** | **NEWTOWN CREEK WWTP**
329 GREEN POINT AVE
BROOKLYN NY | **NY SPILLS**

Spill No: 1302071
Site ID: 482493
DER Facility ID: 355035
CID:
Program Type: ER
SWIS Code: 2401
Water Body:
Class:
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 05/22/2013 08:00:00 AM
Received Date: 05/29/2013 01:07:00 PM
CAC Date:
Insp Date:
Close Date: 06/03/2013 12:00:00 AM
Create Date: 05/29/2013 01:11:00 PM
Update Date: 06/03/2013 02:49:05 PM
DEC Region: 2
Lead DEC: SMSANGES
After Hours: False

Caller Remark:

"spill to containment/clean up complete"

DEC Remark:

"Bleach (Chlorine) is used in the treatment of sewage. The spill within the treatment plant was directed back to the entrance of the treatment stream and the total quantity of bleach spilled was processed through the system. The environment was not harmed. "

Material Information

OP Unit ID: 1232225
OU: 01
Material ID: 2231019
CAS No:
Material Family: Other
Quantity: 4200.00
Units: G
Recovered:
Med Soil: False
Med Air: False
Material Code: 0466A
Material Name: bleach

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: NEWTOWN CREEK WWTP
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: JOE REDDINGTON
Contact Phone:
Contact Ext:
Latitude: 40.731496000
Longitude: -73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	123 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0510252	**UST Trust:**	
Site ID:	356192	**Spill Date:**	11/29/2005 11:45:00 PM
DER Facility ID:	241520	**Received Date:**	11/30/2005 12:09:00 AM
CID:	73	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	11/30/2005 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	11/30/2005 08:03:00 AM
Class:	C4	**Update Date:**	11/30/2005 10:21:57 AM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	SMSANGES
REM Phase:	0	**After Hours:**	True

County: Kings
Contributing Factor: Equipment Failure
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"SPILL IS ON GOING."

DEC Remark:

""

Material Information

OP Unit ID:	1113506	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2103564	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0062A
Material Name: raw sewage

Spiller Information

Spiller Name:
Spiller Company:
Spiller Address:
Spiller City:
Spiller State: ZZ
Spiller Zip: -
Spiller Country: 001
Contact Name: MICHAEL KOWALSKI
Contact Phone: (718) 372-7193
Contact Ext:
Latitude: 40.731117000
Longitude: -73.947406000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	124 of175	NE	0.12 / 649.95	9.75 / -2	NYC DEP NEWTON CREEK WATER POLLUTION CONTROL PLANT	NY SPILLS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					329 GREEN POINT AVE BROOKLYN NY	

Spill No:	1105600	**UST Trust:**	False
Site ID:	453260	**Spill Date:**	08/17/2011 06:45:00 AM
DER Facility ID:	355035	**Received Date:**	08/17/2011 07:20:00 AM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	08/17/2011 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	08/17/2011 07:22:00 AM
Class:	D5	**Update Date:**	08/17/2011 09:46:36 AM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Caller reports Hypo Interuption."

DEC Remark:

"Treatment system failed.... untreated raw sewage was pumped out of the plant."

Material Information

OP Unit ID:	1203418	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2200064	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	SPEDES
Spiller Company:	NYC DEP NEWTON CREEK WATER POLLUTION CONTROL PLANT
Spiller Address:	329 GREEN POINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	LEONARD HARRIS
Contact Phone:	(718) 445-3915
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	125 of175	NE	0.12 / 649.95	9.75 / -2	WHALECREEK CANAL 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0510498	**UST Trust:**	
Site ID:	356486	**Spill Date:**	12/07/2005 09:00:00 AM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

DER Facility ID:	159801	**Received Date:**	12/07/2005 09:37:00 AM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	12/09/2005 12:00:00 AM
Water Body:	WHALECREEK CANAL	**Create Date:**	12/07/2005 10:01:00 AM
Class:	C4	**Update Date:**	12/09/2005 02:39:09 PM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	SMSANGES
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Local Agency		
Referred to:			
Source:	Vessel		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"ABOUT 1-2 QUARTS LEAKED, BOOMS WERE PLACED IN WATER"

DEC Remark:

""

Material Information

OP Unit ID:	1113791	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2103849	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	
Spiller Company:	JOHN CULKIN
Spiller Address:	CRANE CONTRACTOR
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	WINNIE LANHAM
Contact Phone:	(718) 389-2002
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	126 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK SEWER PLANT 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0700018	**UST Trust:**	False
Site ID:	379249	**Spill Date:**	04/02/2007 04:15:00 AM
DER Facility ID:	241520	**Received Date:**	04/02/2007 07:43:00 AM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	04/02/2007 12:00:00 AM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Water Body:	EAST RIVER	**Create Date:**	04/02/2007 09:16:00 AM
Class:		**Update Date:**	04/02/2007 02:30:36 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	vszhune
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Other		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"DUE TO WEATHER BY PASS DUE TO POWER FAILURE: POWER IS BACKON AT THIS TIME: NOT BEING CHLORINATED, RESET FEEDERS AND EVERYTHING IS BACK ON LINE BY 5:00 AM' DISCOVERED ROUTINELY:"

DEC Remark:

"Non Petroleum. Transferred to Selvin Southwell "

Material Information

OP Unit ID:	1136737	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2126688	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	True
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	KEVIN GRANT
Spiller Company:	NEWTOWN CREEK SEWER PLANT
Spiller Address:	301 GREENPOINTAVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	KEVIN GRANT
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	127 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK PLANT NEWTOWN CREEK PLANT NEW YORK CITY NY	NY SPILLS

Spill No:	8604496	**UST Trust:**	False
Site ID:	110654	**Spill Date:**	10/10/1986 11:30:00 PM
DER Facility ID:	96876	**Received Date:**	10/10/1986 02:48:00 PM
CID:		**CAC Date:**	10/11/1986 12:00:00 AM
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/11/1986 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	11/05/1986 12:00:00 AM
Class:		**Update Date:**	08/31/1987 12:00:00 AM
Meets Std:	True	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	UNASSIGNED

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

REM Phase: 0 **After Hours:** False
County: Kings
Contributing Factor: Other
Reported by: Responsible Party
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"CHLORINE FAILURE"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was 10/10/95: This is additional information about material spilled from the translation of the old spill file: SEWAGE"

Spiller Information

Spiller Name:
Spiller Company: NYCDEP
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.733461000
Longitude: -73.962324000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	128 of175	NE	0.12 / 649.95	9.75 / -2	ROAD C TUNNEL DEMO AREA 329 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No: 0902642 **UST Trust:** False
Site ID: 414699 **Spill Date:** 06/04/2009 09:30:00 AM
DER Facility ID: 335827 **Received Date:** 06/04/2009 12:53:00 PM
CID: **CAC Date:**
Program Type: ER **Insp Date:**
SWIS Code: 2401 **Close Date:** 06/04/2009 12:00:00 AM
Water Body: **Create Date:** 06/04/2009 12:55:00 PM
Class: C4 **Update Date:** 06/04/2009 02:18:26 PM
Meets Std: False **DEC Region:** 2
Penalty: **Lead DEC:** smsanges
REM Phase: 0 **After Hours:** False
County: Kings
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"DUE TO A LINE BREAK ABOUT 2.5 GALLONS SPILLED TO SOIL AND STANDING WATER. CLEAN UP WAS DONE."

DEC Remark:

"Private construction oversight contractor working for DEP. Hydraulic leak from large construction equipment. 2.5 gals leaked ground and rain water puddle. Cleaned with absorbant booms and disposed of into drums. Soil is already considered oil contaminated and will be dug out and disposed of as contaminated soil . Cleanup is complete."

Material Information

OP Unit ID:	1171078	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2162866	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	2.50	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	2.50	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	
Spiller Company:	SP2 CONTRACTOR
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	HOLLY KLUENDER
Contact Phone:	(917) 529-4310
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	129 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK TREATMENT PLANT 329 GREENPOINT AVE RD E BROOKLYN NY	NY SPILLS

Spill No:	0707652	**UST Trust:**	False
Site ID:	388384	**Spill Date:**	10/11/2007 10:00:00 AM
DER Facility ID:	336055	**Received Date:**	10/11/2007 02:04:00 PM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/11/2007 12:00:00 AM
Water Body:		**Create Date:**	10/11/2007 02:14:00 PM
Class:	C4	**Update Date:**	10/11/2007 02:26:29 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"IN AN ELEVATER SHAFT:"

DEC Remark:

"Sangesland spoke to Joanna Koenig at DEP Construction Site. Spill occurred in the elevator shaft of a building under construction on this property. Spill was contained in the elevator pit and was cleaned up. Hydraulic equipment is being repaired now."

Material Information

OP Unit ID:	1145559	**Med Ind Air:**	False
OU:	01	**Med GW:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material ID:	2135894	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	20.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	20.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	JOANNA KOENIG
Spiller Company:	NEWTOWN CREEK
Spiller Address:	329 GREENPOINT AVE RD E
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	JOANNA KOENIG
Contact Phone:	(646) 739-3748
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	130 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 329 GREENPOINT AVE RD E BROOKLYN NY	NY SPILLS

Spill No:	0804242	**UST Trust:**	
Site ID:	401117	**Spill Date:**	07/14/2008 06:30:00 AM
DER Facility ID:	336055	**Received Date:**	07/14/2008 07:52:00 AM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	07/14/2008 12:00:00 AM
Water Body:		**Create Date:**	07/14/2008 08:01:00 AM
Class:	D5	**Update Date:**	07/14/2008 02:21:49 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	smsanges
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"wet weather by due to heavy rain, ongoing"

DEC Remark:

""

Material Information

OP Unit ID:	1157920	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2148959	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	True
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	KEVIN GRANT
Spiller Company:	NEWTOWN CREEK
Spiller Address:	329 GREENPOINT AVE RD E
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	KEVIN GRANT
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	
Longitude:	

---

77 | ***131 of175*** | ***NE*** | ***0.12 / 649.95*** | ***9.75 / -2*** | ***CONSTRUCTION SITE 329 GREENPOINT AVENUE BROOKLYN NY*** | ***NY SPILLS***

Spill No:	0512289	**UST Trust:**	
Site ID:	358498	**Spill Date:**	01/24/2006 11:16:00 AM
DER Facility ID:	159801	**Received Date:**	01/24/2006 11:16:00 AM
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	01/27/2006 12:00:00 AM
Water Body:		**Create Date:**	01/24/2006 11:42:00 AM
Class:	C4	**Update Date:**	01/27/2006 04:18:38 PM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	SMSANGES
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Other		
Reported by:	Other		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"PROPER CONTAINMENT IS NOT BEING USED: ABOUT 2 CUPS: CLEAN UP PENDING ,TAKEN PLACE OF BY END OF DAY"

DEC Remark:

"DEP Wastewater facility Mr. Benjamin Potts works for DEP"

Material Information

OP Unit ID:	1115736	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2105839	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0013		
Material Name:	lube oil		

Spiller Information

Spiller Name:	BENJAMIN POTTS
Spiller Company:	CONSTRUCTION SITE
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	BENJAMIN POTTS
Contact Phone:	(718) 609-8797
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

77	132 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0607498	***UST Trust:***	False
Site ID:	371231	***Spill Date:***	10/01/2006 11:04:00 AM
DER Facility ID:	159801	***Received Date:***	10/01/2006 12:02:00 PM
CID:	41	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	01/04/2007 12:00:00 AM
Water Body:	EAST RIVER	***Create Date:***	10/01/2006 12:11:00 PM
Class:	D5	***Update Date:***	01/04/2007 02:42:00 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	SMSANGES
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"main sewer pump failure"

DEC Remark:

""

Material Information

OP Unit ID:	1129002	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2118653	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	ABOVE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Company:	NEWTOWN CREEK
Spiller Address:	329 GREEN POINT AV
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	UNK
Spiller Country:	001
Contact Name:	ABOVE
Contact Phone:	
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	133 of175	NE	0.12 / 649.95	9.75 / -2	TULLY CONSTRUCTION 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0513123	**UST Trust:**	False
Site ID:	359547	**Spill Date:**	01/18/2006 02:01:00 PM
DER Facility ID:	159801	**Received Date:**	02/14/2006 02:01:00 PM
CID:	408	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	02/17/2006 12:00:00 AM
Water Body:		**Create Date:**	02/14/2006 02:25:00 PM
Class:	C4	**Update Date:**	02/17/2006 09:56:35 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	HRPATEL
REM Phase:	0	**After Hours:**	False

County:	Kings
Contributing Factor:	Unknown
Reported by:	Other
Referred to:	
Source:	Unknown
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"2 QUARTS, HAS BEEN CLEANED UP, WAS FOUND ON SOIL"

DEC Remark:

"02/16/06-Hiralkumar Patel. Left message for Benjamin at Bidwell. 02/17/06-Hiralkumar Patel. Spoke with Benjamin. all cleaned up. environment unaffected. case closed."

Material Information

OP Unit ID:	1116753	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2107202	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		

Material Code:	0008
Material Name:	diesel

Spiller Information

Spiller Name:	BENJAMIN POTTS
Spiller Company:	PEGNO/TULLY JOINT VENTURE
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Zip:
Spiller Country: 001
Contact Name: BENJAMIN POTTS
Contact Phone: (718) 609-8797
Contact Ext:
Latitude: 40.731502000
Longitude: -73.946336000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	134 of175	NE	0.12 / 649.95	9.75 / -2	NYC DEP - WPCP 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No: 0106038
Site ID: 310472
DER Facility ID: 159801
CID: 390
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C3
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Unknown
Reported by: Local Agency
Referred to:
Source: Unknown
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 09/05/2001 06:00:00 PM
Received Date: 09/06/2001 11:35:00 AM
CAC Date:
Insp Date:
Close Date: 12/01/2003 12:00:00 AM
Create Date: 09/06/2001 12:00:00 AM
Update Date: 12/01/2003 12:00:00 AM
DEC Region: 2
Lead DEC: JMROMMEL
After Hours: False

Caller Remark:

"unk cause - belived to be waste oil contact - jennifer rommel - dec rep in area"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 9/17/02 The 5,000 gallon tank (approximately 20 feet west and perpendicular to the sheeting line in Whale Creek Canal) appears to have been damaged by the installation of sheeting. The Contractor has pumped out the contents of the tank, and is in the process of removing it. The contents of the tank appear to waste oil. A sample of the oil has been collecteed and test results should be back soon, including Full RCRA characterization. This is within the excavation area for Contract 32, and as such impacted soils will be excavated and disposed along with all the other contaminated soils at the site. We already have data that demonstrates that the surrounding soils are non-hazardous contaminated. 12/1/03 Analysis confirmed materlead not haz waste, oil and water mixture from excavation disposed at New York Oil Recovery, Inc. Tank removed and two soil endpoint samples and one groundwater (bottom) collected. Soil and water OK. spill closed. "

Material Information

OP Unit ID: 844455
OU: 01
Material ID: 530921
CAS No:
Material Family: Petroleum
Quantity: 800.00
Units: G
Recovered: 800.00
Med Soil: True
Med Air: False
Material Code: 0022
Material Name: waste oil/used oil

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: UNK
Spiller Address: UNK
Spiller City: UNK

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: JIM PYNN
Contact Phone: (718) 389-2002
Contact Ext:
Latitude: 40.731275610
Longitude: -73.946992490

---

77 | **135 of175** | **NE** | **0.12 / 649.95** | **9.75 / -2** | **NEWTON CREEK PLANT 329 GREENPOINT AVENUE BROOKLYN NY** | **NY SPILLS**

Spill No: 0601593
Site ID: 363866
DER Facility ID: 159801
CID: 77
Program Type: ER
SWIS Code: 2401
Water Body:
Class: C4
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Other
Reported by: Other
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 05/11/2006 02:35:00 AM
Received Date: 05/12/2006 03:10:00 AM
CAC Date:
Insp Date:
Close Date: 05/12/2006 12:00:00 AM
Create Date: 05/12/2006 03:23:00 AM
Update Date: 05/12/2006 08:52:30 AM
DEC Region: 2
Lead DEC: SMSANGES
After Hours: True

Caller Remark:

"bypass possibly ocurred due to rain. unkn if spill still investigating."

DEC Remark:

""

Material Information

OP Unit ID: 1121920
OU: 01
Material ID: 2111401
CAS No:
Material Family: Other
Quantity:
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0062A
Material Name: raw sewage

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: NYC DEPT. OF SANITATION
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: PANAVILA ROY
Contact Phone: (718) 389-2002

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Ext:
Latitude: 40.731502000
Longitude: -73.946336000

---

77 | **136 of175** | **NE** | **0.12 / 649.95** | **9.75 / -2** | **NEWTOWN CREEK 301 GREENPOINT AVENUE BROOKLYN NY** | **NY SPILLS**

Spill No: 0504567
Site ID: 349432
DER Facility ID: 241520
CID: 27
Program Type: ER
SWIS Code: 2401
Water Body: NEWTOWN CREEK
Class: C5
Meets Std: False
Penalty:
REM Phase: 0
County: Kings
Contributing Factor: Other
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 07/17/2005 08:15:00 AM
Received Date: 07/17/2005 09:45:00 AM
CAC Date:
Insp Date:
Close Date: 07/18/2005 12:00:00 AM
Create Date: 07/17/2005 10:11:00 AM
Update Date: 07/18/2005 08:34:51 AM
DEC Region: 2
Lead DEC: MXTIPPLE
After Hours: True

Caller Remark:

"Spill caused by loosing the climber screens and they throttled the gates causing two of the channels to close down."

DEC Remark:

"7/18/05 Tipple referred to the water unit"

Material Information

OP Unit ID: 1107032
OU: 01
Material ID: 2096349
CAS No:
Material Family: Other
Quantity:
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0062A
Material Name: raw sewage

Med Ind Air: False
Med GW: False
Med SW: True
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: NICK SCOTTO
Spiller Company: NEWTOWN CREEK
Spiller Address: 301 GREENPOINT AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip: 11222
Spiller Country: 001
Contact Name: NICK SCOTTO
Contact Phone: (718) 389-2002
Contact Ext:
Latitude: 40.731117000
Longitude: -73.947406000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	137 of175	NE	0.12 / 649.95	9.75 / -2	NEWTON CREEK PLANT 301 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0611175	**UST Trust:**	False
Site ID:	375762	**Spill Date:**	01/08/2007 01:55:00 AM
DER Facility ID:	241520	**Received Date:**	01/08/2007 02:17:00 AM
CID:	77	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	01/08/2007 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	01/08/2007 02:41:00 AM
Class:	D5	**Update Date:**	01/08/2007 09:21:21 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SMSANGES
REM Phase:	0	**After Hours:**	True

County: Kings
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"HEAVY RAIN."

DEC Remark:

""

Material Information

OP Unit ID:	1133384	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2123193	**Med SW:**	True
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0062A
Material Name: raw sewage

Spiller Information

Spiller Name:
Spiller Company: NYC DEP
Spiller Address:
Spiller City:
Spiller State: ZZ
Spiller Zip: -
Spiller Country: 001
Contact Name: RICHARD DESFROSSE
Contact Phone: (718) 372-7193
Contact Ext:
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	138 of175	NE	0.12 / 649.95	9.75 / -2	WATER POLLUTION CONTROL PLANT 329 GREEN POINT AVENUE BROOKLYN NY 11222	NY SPILLS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spill No:	0807189	**UST Trust:**	False
Site ID:	404518	**Spill Date:**	09/26/2008 03:00:00 AM
DER Facility ID:	353784	**Received Date:**	09/26/2008 03:36:00 AM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	09/26/2008 12:00:00 AM
Water Body:		**Create Date:**	09/26/2008 03:39:00 AM
Class:	C4	**Update Date:**	09/26/2008 09:07:44 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SFRAHMAN
REM Phase:	0	**After Hours:**	True

County: Kings
Contributing Factor: Other
Reported by: Responsible Party
Referred to:
Source: Gasoline Station or other PBS Facility
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"0340 Clean up will be conducted once the rain stops."

DEC Remark:

"Referred to water division."

Material Information

OP Unit ID:	1161173	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2152365	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0060A
Material Name: wastewater

Spiller Information

Spiller Name: JIM DALY
Spiller Company: WATER POLLUTION CONTROL PLANT
Spiller Address: 329 GREEN POINT AVENUE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip: 11222
Spiller Country: 999
Contact Name: JIM DALY
Contact Phone: (718) 372-7193
Contact Ext:
Latitude: 40.731496000
Longitude: -73.946413000

77	139 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK 301 GREEN POINT AVE BROOKLYN NY	NY SPILLS

Spill No:	0710837	**UST Trust:**	
Site ID:	392189	**Spill Date:**	01/13/2008 10:15:00 PM
DER Facility ID:	341012	**Received Date:**	01/13/2008 11:39:00 PM
CID:	79	**CAC Date:**	
Program Type:	ER	**Insp Date:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SWIS Code:	2401	**Close Date:**	01/13/2008 12:00:00 AM
Water Body:		**Create Date:**	01/14/2008 08:37:00 AM
Class:		**Update Date:**	01/14/2008 09:06:21 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	jbvought
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"SPILLING INTO WHALE CREEK. CURRENTLY ONGOING."

DEC Remark:

"01/14/08-Vought-Off hours responder. Non-petroleum spill. Spill closed and referred to DEC Water Unit."

Material Information

OP Unit ID:	1149215	**Med Ind Air:**	False
OU:	01	**Med GW:**	True
Material ID:	2139723	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	-
Spiller Country:	001
Contact Name:	JIM DALY
Contact Phone:	(718) 372-7192
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	140 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WPCP 329 GREEN POINT AVE BROOKLYN NY	NY SPILLS

Spill No:	0808381	**UST Trust:**	False
Site ID:	405773	**Spill Date:**	10/25/2008 09:00:00 PM
DER Facility ID:	355035	**Received Date:**	10/25/2008 10:37:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/27/2008 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	10/25/2008 10:41:00 PM
Class:	D5	**Update Date:**	10/27/2008 09:27:59 AM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	smsanges

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"HeavY screen"

DEC Remark:

"sewage bypass"

Material Information

OP Unit ID:	1162384	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2153639	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	True
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	
Spiller Company:	Anonymous
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	SEE ROY
Contact Phone:	(718) 389-2002
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

77	141 of175	NE	0.12 / 649.95	9.75 / -2	**Spill Number 9810145** **301 GREENPOINT AVENUE** **BROOKLYN NY**	NY SPILLS

Spill No:	9810145	**UST Trust:**	False
Site ID:	148965	**Spill Date:**	11/11/1998 01:45:00 PM
DER Facility ID:	241520	**Received Date:**	11/11/1998 02:47:00 PM
CID:	382	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/04/1999 12:00:00 AM
Water Body:		**Create Date:**	11/11/1998 12:00:00 AM
Class:	C4	**Update Date:**	10/04/1999 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	WOOLSEY
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source: Commercial Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"LINE OF A VEHICLE BROKE SPILLING THE MATERIAL ONTO THE DIRT. AREA IS UNDER CONSTRUCTION AND VEHICLE WAS ONE OF THE CONSTRUCTION VEHICLES. ALL CLEQAN ED UP WITH SPEEDY DRY."

DEC Remark:

""

Material Information

OP Unit ID:	1071063	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	314024	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	2.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	2.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	ELLEN METZGER
Spiller Company:	
Spiller Address:	301 GREENPOINT
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	ELLEN METZGER
Contact Phone:	(914) 987-1755
Contact Ext:	
Latitude:	40.730794790
Longitude:	-73.948598750

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	142 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 329 GREENPOINT AVENUE BROOKLYN NY	NY SPILLS

Spill No:	0502697	**UST Trust:**	False
Site ID:	347106	**Spill Date:**	06/06/2005 05:30:00 PM
DER Facility ID:	159801	**Received Date:**	06/06/2005 06:31:00 PM
CID:	407	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	10/18/2005 12:00:00 AM
Water Body:	NEW TOWN CREEK	**Create Date:**	06/06/2005 06:51:00 PM
Class:	D4	**Update Date:**	10/18/2005 02:29:09 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SMSANGES
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Other		
Reported by:	Local Agency		
Referred to:			
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Cause: main sewer pump out of service."

DEC Remark:

""

Material Information

OP Unit ID:	1104853	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	1262181	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	TIM CHRISTIANSON
Spiller Company:	NEW TOWN CREEK
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	TIM CHRISTIANSON
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	143 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK WWT PLANT 329 GREEN POINT AVE BROOKLYN NY	NY SPILLS

Spill No:	1002787	***UST Trust:***	False
Site ID:	435980	***Spill Date:***	06/10/2010 03:20:00 PM
DER Facility ID:	355035	***Received Date:***	06/10/2010 05:01:00 PM
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	06/14/2010 12:00:00 AM
Water Body:	EAST RIVER	***Create Date:***	06/10/2010 05:03:00 PM
Class:	E5	***Update Date:***	06/14/2010 09:46:37 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	RMPIPER
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CONTINUOUS BYPASS TO EAST RIVER AT THIS TIME. UPDATE 1901- BYPASS ENDED."

DEC Remark:

"referred to DEC Water Div. closed"

Material Information

OP Unit ID:	1186689	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2181495	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	
Spiller Company:	NEW TOWN CREEK WWT PLANT
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	DEAN BLAUSTIEN
Contact Phone:	
Contact Ext:	
Latitude:	40.731496000
Longitude:	-73.946413000

77	***144 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***PEGNO/TULLY JOINT VENTURE 329 GREENPOINT AVENUE BROOKLYN NY***	***NY SPILLS***

Spill No:	0513124	***UST Trust:***	False
Site ID:	359548	***Spill Date:***	01/19/2006 02:03:00 PM
DER Facility ID:	159801	***Received Date:***	02/14/2006 02:03:00 PM
CID:	408	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	02/17/2006 12:00:00 AM
Water Body:		***Create Date:***	02/14/2006 02:25:00 PM
Class:	C4	***Update Date:***	02/17/2006 09:57:03 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	HRPATEL
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"ONE QUART, HAS BEEN CLEANED UP."

DEC Remark:

"02/16/06-Hiralkumar Patel. Left message for Benjamin at Bidwell. 02/17/06-Hiralkumar Patel. Spoke with Benjamin. all cleaned up. environment unaffected. case closed."

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material Information

OP Unit ID:	1116754	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2107203	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	BENJAMIN POTTS
Spiller Company:	PEGNO/TULLY JOINT VENTURE
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	BENJAMIN POTTS
Contact Phone:	(718) 609-8797
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	145 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP DEP - DDC 301 GREENPOINT AVENUE BROOKLYN NY	LST

Spill No:	9211551	***REM Phase:***	0
Site ID:	148962	***UST Trust:***	False
DER Facility ID:	241520	***Spill Date:***	12/30/1992 12:00:00 PM
CID:		***Rcvd Date:***	01/07/1993 02:14:00 PM
Program Type:	ER	***CAC Date:***	01/08/1993 12:00:00 AM
SWIS Code:	2401	***Insp Date:***	
Contribute Factor:	Tank Failure	***Close Date:***	01/08/1993 12:00:00 AM
Water Body:		***Create Date:***	01/08/1993 12:00:00 AM
Class:	C4	***Update Date:***	12/28/2004 10:10:08 AM
Meets Std:	True	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	GUTIERREZ
County:	Kings	***After Hours:***	False
Referred to:			
Reported by:	Local Agency		
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CONTAMINATION DISCOVERED IN TREATMENT PLANT-DISCOVERED IT COMES FROM MOBIL SPILL-CHECKED MONITORING WELLS"

Dec Remark:

""

Material Information

OP Unit ID:	978528	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	404943	***Med SW:***	True

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	2004.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0012A		
Material Name:	kerosene		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	***Update***
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.730794790
Longitude:	-73.948598750

77	146 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WPCP DEP - DDC 301 GREENPOINT AVENUE BROOKLYN NY	LST

Spill No:	0003594	**REM Phase:**	0
Site ID:	148959	**UST Trust:**	False
DER Facility ID:	241520	**Spill Date:**	06/23/2000 11:00:00 AM
CID:	396	**Rcvd Date:**	06/23/2000 11:51:00 AM
Program Type:	ER	**CAC Date:**	
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Failure	**Close Date:**	05/05/2005 12:00:00 AM
Water Body:		**Create Date:**	06/23/2000 12:00:00 AM
Class:	C3	**Update Date:**	05/05/2005 11:21:34 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	AIIslam
County:	Kings	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"petrolium impacts noted to subsurface soil...samples taken and results will be forewarded when they are available."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL DEC Sigona received complaint referred to DEC Rommel. email to Brenda O'Shea - Malcolm Pirnie. >>> Jennifer Rommel 10/28/03 11:14AM >>> Hi Brenda. . . .I am looking at a spill reported on 06/23/00, (spill 0003594) by Charles Guder of Gannett Flemming regarding a #4 fuel oil tank. Caller remarks: petroleum impacts noted to subsurface soil. . . samples taken and results will be forwarded when available. Let me know if you can provide any info on this spill, or if I should contact Gannett Flemming. Thanks. >>> O'Shea, Brenda <boshea@NewtownCreek-cm.com> 10/28/03 11:52AM >>> Jennifer, I spoke with Ellen and Winnie about this, Winnie recollects that Gannett called in the spill and performed a satisfactory cleanup immediately. I would contact Gannett directly for all information. Regards, Brenda Brenda O'Shea, CPG Senior Project Scientist Malcolm Pirnie, Inc. boshea@newtowncreek-cm.com (718) 609-8782 (718) 383-8297 fax SPILL CASE TRANSFERRED TO KOLLEENY TO ISLAM 5/5/05- The spill site as a whole (multiple spills exist at the site)is under investigation by PMS Construction Mgt.and Shaw Envtl. Based on the information as mentioned above about the clean up of the site and existance of other open spills at the site, this spill is closed to consolidate with spill #9907560.- II "

Material Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OP Unit ID:	825999	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	551911	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0002A		
Material Name:	#4 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	NYCDEP NEWTOWN CREEK WPCP
Spiller Address:	301 GREENPOINT AVE
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	CALLER
Contact Phone:	
Contact Ext:	
Latitude:	40.730794790
Longitude:	-73.948598750

77	147 of175	NE	0.12 / 649.95	9.75 / -2	EXXON TERMINAL 320 FREEMAN STREET BROOKLYN NY	LST

Spill No:	9106287	**REM Phase:**	0
Site ID:	158195	**UST Trust:**	False
DER Facility ID:	133719	**Spill Date:**	09/11/1991 10:00:00 AM
CID:		**Rcvd Date:**	09/11/1991 10:32:00 AM
Program Type:	ER	**CAC Date:**	
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Failure	**Close Date:**	10/16/1997 12:00:00 AM
Water Body:		**Create Date:**	10/09/1991 12:00:00 AM
Class:	C3	**Update Date:**	04/07/2004 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	GELLER
County:	Kings	**After Hours:**	False
Referred to:			
Reported by:	Responsible Party		
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"TANK INVOLVED"

Dec Remark:

""

Material Information

OP Unit ID:	956766	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	422010	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	EXXON
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.734977870
Longitude:	-73.948947390

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	148 of175	NE	0.12 / 649.95	9.75 / -2	NYC NEWTON CREEK WPCP 320 FREEMAN STREET BROOKLYN NY	LST

Spill No:	9601620	**REM Phase:**	0
Site ID:	275304	**UST Trust:**	False
DER Facility ID:	133719	**Spill Date:**	05/01/1996 03:00:00 PM
CID:	252	**Rcvd Date:**	05/01/1996 03:42:00 PM
Program Type:	ER	**CAC Date:**	
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Failure	**Close Date:**	07/31/1997 12:00:00 AM
Water Body:		**Create Date:**	05/01/1996 12:00:00 AM
Class:	B3	**Update Date:**	04/07/2004 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	KSTANG
County:	Kings	**After Hours:**	False
Referred to:			
Reported by:	Responsible Party		
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Upon excavtion of soil tank was accidentally hit and pulled out of ground-soil cleaned up"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG AFTER CONSIDERING THE FACT THAT THE SPILL OCCURRED SO LONG AGO, AND THE REMARKS INDICATE THAT NO LONG-TERM FOLLOW-UP IS NEEDED; I DECIDED TO CLOSE THIS SPILL."

Material Information

OP Unit ID:	1033169	**Med in Air:**	False
OU:	01	**Med GW:**	True
Material ID:	351419	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code:	0022
Material Name:	waste oil/used oil

Spiller Information

Spiller Name:	
Spiller Company:	EXXON
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	STEVE SCHMALLER
Contact Phone:	(718) 595-4363
Contact Ext:	
Latitude:	40.734977870
Longitude:	-73.948947390

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	149 of175	NE	0.12 / 649.95	9.75 / -2	EXXON TERMINAL 320 FREEMAN STREET BROOKLYN NY	LST

Spill No:	9012950	**REM Phase:**	0
Site ID:	158192	**UST Trust:**	False
DER Facility ID:	133719	**Spill Date:**	03/19/1991 03:30:00 PM
CID:		**Rcvd Date:**	03/19/1991 03:54:00 PM
Program Type:	ER	**CAC Date:**	
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Overfill	**Close Date:**	12/27/2002 12:00:00 AM
Water Body:		**Create Date:**	04/02/1991 12:00:00 AM
Class:	C3	**Update Date:**	04/07/2004 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SJMILLER
County:	Kings	**After Hours:**	False
Referred to:			
Reported by:	Responsible Party		
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"ACCUMULATOR TANK SIZE 10FT DIAMETER BY 6FT LENGTH INSTALLED VERTICALLYPARTIALLY ABOVEGROUND,UPON TANK PULL, CONTAMINATED SOIL WAS DISCOVERED,WATER FROM WHALE CREEK SEEPED INTO EXCAVATION SITE."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MILLER 03/19/91: WHOLE PLANT TO BE DEMOLISHED,WILL INSTALL OBSERVATION WELL. 12/27/02, FACILITY WAS DEMOLISHED AND DEPT. APPROVED REMEDIATION PRECEDED EXPANSION OF GREENPOINT WPCP ONTO FORMER EXXON PROPERTY. "

Material Information

OP Unit ID:	952875	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	429397	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	EXXON
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.734977870
Longitude:	-73.948947390

77	***150 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***NEW TOWN CREEK WATER POLL 329 GREENPOINT AVENUE BROOKLYN NY***	***LST***

Spill No:	0407835	***REM Phase:***	0
Site ID:	332412	***UST Trust:***	False
DER Facility ID:	159801	***Spill Date:***	10/14/2004 08:20:00 PM
CID:	64	***Rcvd Date:***	10/14/2004 09:57:00 PM
Program Type:	ER	***CAC Date:***	
SWIS Code:	2401	***Insp Date:***	
Contribute Factor:	Tank Overfill	***Close Date:***	10/19/2004 12:00:00 AM
Water Body:	NEW TOWN CREEK	***Create Date:***	10/18/2004 05:18:00 PM
Class:	D6	***Update Date:***	10/19/2004 12:42:10 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	SMSANGES
County:	Kings	***After Hours:***	True
Referred to:			
Reported by:	Other		
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

""

Dec Remark:

""

Material Information

OP Unit ID:	1094645	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	574768	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	50.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	30.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0058A		
Material Name:	sludge		

Spiller Information

Spiller Name:	JIM DALY
Spiller Company:	NEW TOWN CREEK WATER POLL
Spiller Address:	329 GREENPOINT AVE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11224
Spiller Country:	001
Contact Name:	JIM DALY
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	151 of175	NE	0.12 / 649.95	9.75 / -2	MINOR SPILL 329 GREENPOINT AVENUE BROOKLYN NY	LST

Spill No:	0512231	**REM Phase:**	0
Site ID:	358594	**UST Trust:**	True
DER Facility ID:	159801	**Spill Date:**	01/04/2006 12:00:00 AM
CID:	73	**Rcvd Date:**	01/23/2006 07:32:00 AM
Program Type:	ER	**CAC Date:**	
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Failure	**Close Date:**	01/27/2006 12:00:00 AM
Water Body:		**Create Date:**	01/24/2006 02:10:00 PM
Class:	C4	**Update Date:**	01/27/2006 11:32:07 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SFRAHMAN
County:	Kings	**After Hours:**	True
Referred to:			
Reported by:	Responsible Party		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"3 CUPS OF DIESEL SPILLED ONTO SOIL DO TO OVER FILL OF A BARRELL. SPILL WAS ALL CLEANED UP. PER CALLER, DEP HAS ASKED THEM TO REPORT THIS."

Dec Remark:

"minor spill"

Material Information

OP Unit ID:	1115832	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2105941	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	PETER CHIODO
Spiller Company:	SILVERITE CONSTRUCTION
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	BENJAMIN POTTS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Phone: (718) 609-8797
Contact Ext:
Latitude: 40.731502000
Longitude: -73.946336000

---

77 | **152 of175** | **NE** | **0.12 / 649.95** | **9.75 / -2** | **NEWTOWN CREEK SEWER PLANT**
301 GREENPOINT AVENUE
BROOKLYN NY | **LST**

Spill No: 9700433
Site ID: 213749
DER Facility ID: 241520
CID: 257
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Failure
Water Body:
Class: C3
Meets Std: False
Penalty: False
County: Kings
Referred to:
Reported by: Local Agency
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: False
Spill Date: 04/09/1997 10:00:00 AM
Rcvd Date: 04/09/1997 10:56:00 AM
CAC Date:
Insp Date:
Close Date: 04/09/1997 12:00:00 AM
Create Date: 04/09/1997 12:00:00 AM
Update Date: 02/26/2008 04:06:20 PM
DEC Region: 2
Lead DEC: SMMARTIN
After Hours: False

Caller Remark:

"LEAK IN TANK SPILL IS CONTAINED "

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT DEP HAZMAT, ECS, FD, PD RESPONDED CONTRACTOR SNAPPED OFF FITTING ON BOTTOM OF TANK LEAKED INTO CONTAINMENT AREA. THEY STARTED PUMPING IT OUT TO OTHER TANKS-RESIDUAL IN CONTAINMENT WILL BE USED WITHIN PLANT WILL SCHEDULE CBS INSPECTION. 2/26/2008: Changed spilled material from sodium hydrochloride to sodium hypochlorite . (Zalewski) "

Material Information

OP Unit ID: 1046742
OU: 01
Material ID: 337028
CAS No: 07681529
Material Family: Hazardous Material
Quantity: 12000.00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0124A
Material Name: sodium hypochlorite

Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: BOB CONNAUGHTON
Spiller Company: NEWTOWN CREEK SEWER PLANT
Spiller Address: 329 GREEN POINT AVE
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: BOB CONNAUGHTON
Contact Phone: (718) 389-2000
Contact Ext:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Latitude:		40.730794790				
Longitude:		-73.948598750				

77	153 of175	NE	0.12 / 649.95	9.75 / -2	NEW TOWN CREEK 301 GREENPOINT AVENUE BROOKLYN NY	LST

Spill No:	0702645	**REM Phase:**	0
Site ID:	382401	**UST Trust:**	False
DER Facility ID:	241520	**Spill Date:**	06/03/2007 09:00:00 PM
CID:	79	**Rcvd Date:**	06/03/2007 09:13:00 PM
Program Type:	ER	**CAC Date:**	
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Overfill	**Close Date:**	06/04/2007 12:00:00 AM
Water Body:	EAST RIVER	**Create Date:**	06/04/2007 02:06:00 AM
Class:	C4	**Update Date:**	06/04/2007 09:53:05 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SFRAHMAN
County:	Kings	**After Hours:**	True
Referred to:			
Reported by:	Responsible Party		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"HAEVY RAIN AND SCREENINGS CAUSED RAIN GATES TO RATTLE AND WET WEATHER BY PASS IS ONGOING"

Dec Remark:

"Raw sewage- transferred to water division.Spill closed."

Material Information

OP Unit ID:	1139800	**Med in Air:**	False
OU:	01	**Med GW:**	True
Material ID:	2129843	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	KEVIN GRANT
Spiller Company:	NEW TOWN CREEK
Spiller Address:	301 GREEN POINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222
Spiller Country:	001
Contact Name:	KEVIN GRANT
Contact Phone:	(718) 372-7193
Contact Ext:	
Latitude:	
Longitude:	

77	154 of175	NE	0.12 / 649.95	9.75 / -2	DEPT OF CLEAN WATERS 329 GREENPOINT AVENUE	LST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					BROOKLYN NY	

Spill No:	9606892	**REM Phase:**	0
Site ID:	121045	**UST Trust:**	False
DER Facility ID:	159801	**Spill Date:**	08/29/1996 02:30:00 PM
CID:	323	**Rcvd Date:**	08/29/1996 03:03:00 PM
Program Type:	ER	**CAC Date:**	
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Overfill	**Close Date:**	08/29/1996 12:00:00 AM
Water Body:		**Create Date:**	08/29/1996 12:00:00 AM
Class:	C4	**Update Date:**	09/14/2006 07:52:49 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SMMARTIN
County:	Kings	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"DRIVER WAS INSTRUCTED TO FILL THE WRONG TANK. CLEAN UP CREW IS ENROUTE TO THE SCENE."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "

Material Information

OP Unit ID:	1034702	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	346161	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	15.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	DEPT OF CLEAN WATERS
Spiller Address:	329 GREEN POINT AVE
Spiller City:	BROOKLYN
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	(718) 389-2002
Contact Ext:	
Latitude:	40.731275610
Longitude:	-73.946992490

77	155 of175	NE	0.12 / 649.95	9.75 / -2	DEP WASTEWATER 329 GREENPOINT AVENUE BROOKLYN NY	LST

Spill No:	0512133	**REM Phase:**	0
Site ID:	358404	**UST Trust:**	
DER Facility ID:	159801	**Spill Date:**	12/08/2005 09:00:00 AM
CID:	444	**Rcvd Date:**	01/20/2006 11:32:00 AM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program Type:	ER	**CAC Date:**	
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Overfill	**Close Date:**	01/24/2006 12:00:00 AM
Water Body:		**Create Date:**	01/20/2006 11:51:00 AM
Class:	C4	**Update Date:**	01/24/2006 08:46:42 AM
Meets Std:	False	**DEC Region:**	2
Penalty:		**Lead DEC:**	SMSANGES
County:	Kings	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"OVERFILL OF A GAS TANK ON GENERATOR: 1 QUART: ALL CLEANED"

Dec Remark:

""

Material Information

OP Unit ID:	1115647	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2105734	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	BENJAMIN POTTS
Spiller Company:	DEP WASTEWATER
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	BENJAMIN POTTS
Contact Phone:	(718) 609-8797
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	156 of175	NE	0.12 / 649.95	9.75 / -2	EXXON TERMINAL 320 FREEMAN STREET BROOKLYN NY	LST

Spill No:	9104730	**REM Phase:**	0
Site ID:	158194	**UST Trust:**	False
DER Facility ID:	133719	**Spill Date:**	08/01/1991 10:35:00 AM
CID:		**Rcvd Date:**	08/01/1991 11:20:00 AM
Program Type:	ER	**CAC Date:**	03/30/1995 12:00:00 AM
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Failure	**Close Date:**	03/30/1995 12:00:00 AM
Water Body:		**Create Date:**	08/07/1991 12:00:00 AM
Class:	C3	**Update Date:**	04/07/2004 12:00:00 AM
Meets Std:	True	**DEC Region:**	2

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Penalty: False
County: Kings
Referred to:
Reported by: Responsible Party
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data
Lead DEC: KSTANG
After Hours: False

Caller Remark:

"TERMINAL BEING DISMANTLED,MANHOLE COVER HAS ONLY (2) BOLTS, TANK WAS PUMPED 2-3 MONTHS AGO,WASTE OIL IN EXCAVATION SITE."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "

Material Information

OP Unit ID: 955506
OU: 01
Material ID: 423791
CAS No:
Material Family: Petroleum
Quantity: 5.00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0022
Material Name: waste oil/used oil
Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: EXXON
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.734977870
Longitude: -73.948947390

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	157 of175	NE	0.12 / 649.95	9.75 / -2	EXXON TERMINAL 320 FREEMAN STREET BROOKLYN NY	LST

Spill No: 9101866
Site ID: 158193
DER Facility ID: 133719
CID:
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Failure
Water Body:
Class: C3
Meets Std: False
Penalty: False
County: Kings
Referred to:
Reported by: Responsible Party
Source: Major Facility (MOSF) > 400,000 gal
REM Phase: 0
UST Trust: False
Spill Date: 05/16/1991 11:00:00 AM
Rcvd Date: 05/16/1991 11:10:00 AM
CAC Date:
Insp Date:
Close Date: 12/23/2002 12:00:00 AM
Create Date: 05/23/1991 12:00:00 AM
Update Date: 04/07/2004 12:00:00 AM
DEC Region: 2
Lead DEC: SJMILLER
After Hours: False

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"OIL DISCOVERED WHILE EXCAVATING UNDERGROUND TANKS, DEC TO INVESTIGATE."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MILLER 12/23/02 MILLER CLOSED SPILL REPORT BECAUSE FORMER EXXON FACILITY WAS REMEDIATED UNDER DEC OVERSIGHT AND SUBSEQUENTLY REDEVELOPED AS NEWTOWN CREEK WPCP EXPANSION PROJECT."

Material Information

OP Unit ID:	952977	***Med in Air:***	False
OU:	01	***Med GW:***	True
Material ID:	424402	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	EXXON
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.734977870
Longitude:	-73.948947390

77	***158 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***DEP WASTEWATER 329 GREENPOINT AVENUE BROOKLYN NY***	***LST***

Spill No:	0512131	***REM Phase:***	0
Site ID:	358402	***UST Trust:***	
DER Facility ID:	159801	***Spill Date:***	12/20/2005 10:00:00 AM
CID:	444	***Rcvd Date:***	01/20/2006 11:26:00 AM
Program Type:	ER	***CAC Date:***	
SWIS Code:	2401	***Insp Date:***	
Contribute Factor:	Tank Overfill	***Close Date:***	01/24/2006 12:00:00 AM
Water Body:		***Create Date:***	01/20/2006 11:51:00 AM
Class:	C4	***Update Date:***	01/24/2006 08:44:42 AM
Meets Std:	False	***DEC Region:***	2
Penalty:		***Lead DEC:***	SMSANGES
County:	Kings	***After Hours:***	False
Referred to:			
Reported by:	Other		
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"OVERFILL OF CRANE: 1/2 QUART , ALL CLEANED UP:"

Dec Remark:

"minor spill - all cleaned"

Material Information

OP Unit ID:	1115645	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2105732	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	BENJAMIN POTTS
Spiller Company:	DEP WASTEWATER
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	BENJAMIN POTTS
Contact Phone:	(718) 609-8797
Contact Ext:	
Latitude:	40.731502000
Longitude:	-73.946336000

77	***159 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***EXXON COMPANY, U.S.A. 320 FREEMAN STREET Brooklyn NY 11222***	***UST***

Site ID:	340334	***Expiry:***	N/A
Site Status:	Unregulated/Closed	***County:***	Kings
Program No:	2-000218	***UTM X:***	588577.43901
Program Type Code:	CBS	***UTM Y:***	4509844.67839
Program Type Desc:	Chemical Bulk Storage		
Site Type:	Storage Terminal/Petroleum Distributor		

Tank Information

Prog No:	2-000218	***UDC Ind:***	1
Tank ID:	189192	***Red Tag Start Date:***	
Tank No:	AD1	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	04	***Test Method:***	NN
Tank Type Desc:	Fiberglass Coated Steel	***Date Tested:***	
Install Date:	01/01/1987	***Next Test:***	
Close Date:	03/01/1991	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			
Tank Location:	5		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Tank Information

Prog No:	2-000218	**UDC Ind:**	1
Tank ID:	189193	**Red Tag Start Date:**	
Tank No:	AD2	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	04	**Test Method:**	NN
Tank Type Desc:	Fiberglass Coated Steel	**Date Tested:**	
Install Date:	01/01/1987	**Next Test:**	
Close Date:	03/01/1991	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	4000	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	160 of175	NE	0.12 / 649.95	9.75 / -2	THE CITY OF NEW YORK/NYCDEP 329 GREENPOINT AVENUE 329 GREENPOINT AVENUE Brooklyn NY 11222	AST

Site ID: 341773
Site Status: Unregulated/Closed
Program No: 2-000261
Program Type Code: CBS
Program Type Desc: Chemical Bulk Storage
Site Type: Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)
Expiry: N/A
County: Kings
UTM X: 588982.64242
UTM Y: 4509507.97479

Tank Information

Prog No:	2-000261	**UDC Ind:**	1
Tank ID:	190545	**Red Tag Start Date:**	
Tank No:	F1191-15	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	99	**Test Method:**	NN
Tank Type Desc:	Other	**Line Last Test Due:**	
Install Date:	04/01/1993	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	6200	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 1

Tank Location Desc: Aboveground-contact w/ soil
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Tank Information

Prog No:	2-000261	**UDC Ind:**	1
Tank ID:	190546	**Red Tag Start Date:**	
Tank No:	F1191-16	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	99	**Test Method:**	NN
Tank Type Desc:	Other	**Line Last Test Due:**	
Install Date:	04/01/1993	**Next Line Test Due:**	
Close Date:	04/01/1996	**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	6200	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

77	161 of175	NE	0.12 / 649.95	9.75 / -2	FACILITY WASTE WATER TREATMENT PLANT 329 GREEN POINT AVE BROOKLYN NY	NY SPILLS

Spill No:	1504424	**UST Trust:**	False
Site ID:	510765	**Spill Date:**	07/26/2015 03:25:00 PM
DER Facility ID:	465339	**Received Date:**	07/26/2015 03:54:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	3101	**Close Date:**	07/27/2015 12:00:00 AM
Water Body:	WHALE CREEK	**Create Date:**	07/26/2015 03:58:00 PM
Class:		**Update Date:**	07/27/2015 09:47:09 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	HRPATEL
REM Phase:	0	**After Hours:**	True

County: New York
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"clean up in progress"

DEC Remark:

"case referred to water division."

Material Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OP Unit ID:	1260031	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2263389	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0058A		
Material Name:	sludge		

Spiller Information

Spiller Name:	DAVID JAWANDO
Spiller Company:	NEW FOUND CREEK PLANT
Spiller Address:	329 GREEN POINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	DAVID JAWANDO
Contact Phone:	(718) 349-4797
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	162 of175	NE	0.12 / 649.95	9.75 / -2	SEWAGE TREATMENT PLANT (NEW TOWN CREEK) 301 GREEN POINT AVE BROOKLYN NY	NY SPILLS

Spill No:	1805468	**UST Trust:**	False
Site ID:	576163	**Spill Date:**	08/18/2018 10:00:00 PM
DER Facility ID:	341012	**Received Date:**	08/18/2018 11:55:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	08/21/2018 12:00:00 AM
Water Body:		**Create Date:**	08/18/2018 11:58:00 PM
Class:	D4	**Update Date:**	08/21/2018 02:23:57 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	RMPIPER
REM Phase:	0	**After Hours:**	True
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"15% solution.contained"

DEC Remark:

"DEC piper spoke with Ed Wright. Spill from broken valve. Valve replaced. Liquid sent through treatment plant. Spill closed"

Material Information

OP Unit ID:	1323947	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2332344	**Med SW:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	100.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	1705A		
Material Name:	sodium hyperchloride		

Spiller Information

Spiller Name:	ED WRIGHT
Spiller Company:	WATER TREATMENT/DEP
Spiller Address:	301 GREEN POINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	ED WRIGHT
Contact Phone:	(646) 584-1844
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	163 of175	NE	0.12 / 649.95	9.75 / -2	NYCDEP - NEWTON CREEK WPCP 329 GREENPOINT AVENUE BROOKLYN NY 11222	GEN MANIFEST

RCRA ID:	NYD980779730	**Mailing State:**	NY
District Name:	NYCDEP - NEWTON CREEK WPCP	**Mailing ZIP:**	11368
Contact Name:	PAUL GOLDBERG	**Mailing ZIP Ext:**	
Business Phone No:	2123892002	**Mailing Country:**	USA
Mailing Street 1:	9605 HORACE HARDING	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	FLUSHING	**Location County:**	KINGS

Manifest Information

Waste Code(s):

F001: (Generic) The following spent halogenated solvents used in degreasing: tetrachloroethylene, trichloroethylene, methylene chloride, 1,1, 1-trichloroethane, carbon tetrachloride, and chlorinated fluorocarbons; all spent solvent mixtures/blends used in degreasing containing, before use, total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those solvents listed in F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

2001: 400 Pounds; 427 Pounds; 400 Pounds

Manifest Information

Waste Code(s):

F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

2001: 275 Gallons; 4800 Pounds

Manifest Information

Waste Code(s):

F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

1999: 43000 Pounds
2001: 405 Pounds

Manifest Information

Waste Code(s):

B006: (Wastes containing polychlorinated biphenyls (PCBs)) PCB transformers. PCB transformers means any transformer that contains 500 ppm PCB or greater.

Waste Amounts By Year:

1986: 44800 Pounds
1991: 6857 Kilograms

Manifest Information

Waste Code(s):

B007: (Wastes containing polychlorinated biphenyls (PCBs)) Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Waste Amounts By Year:

1991: 77 Kilograms
2002: 714 Kilograms; 25 Kilograms
2007: 1207 Kilograms
2008: 8618 Kilograms; 10063 Kilograms; 28000 Pounds; 11955 Kilograms; 10161 Kilograms; 14425 Kilograms; 10161 Kilograms; 13082 Kilograms; 13245 Kilograms; 10161 Kilograms; 7136 Kilograms; 12000 Kilograms; 6613 Kilograms; 4535 Kilograms; 2440 Kilograms; 10181 Kilograms; 3357 Kilograms; 13364 Kilograms; 2255 Kilograms
2009: 3191 Kilograms; 3600 Kilograms; 3200 Kilograms; 3400 Kilograms; 3191 Kilograms; 3472 Kilograms; 4104 Kilograms; 1909 Kilograms; 5987 Kilograms; 1315 Kilograms; 4136 Kilograms; 2000 Kilograms; 5209 Kilograms; 19957 Kilograms; 3200 Kilograms; 3400 Kilograms; 3518 Kilograms
2010: 136 Kilograms
2012: 19063 Kilograms; 13253 Kilograms; 18000 Kilograms; 6554 Kilograms; 11644 Kilograms

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 60 Pounds
2011: 60 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D019: CARBON TETRACHLORIDE (Waste Code Description from EPA Hazardous Waste Identification)
D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)
D043: VINYL CHLORIDE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2007: 400 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2014: 17 Pounds; 20 Pounds
2015: 64 Pounds; 15 Pounds
2016: 25 Pounds
2017: 20 Pounds; 110 Pounds; 7 Pounds
2018: 72 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2016: 25 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 28 Pounds; 28 Pounds
2011: 28 Pounds; 28 Pounds; 28 Pounds
2012: 25 Pounds; 25 Pounds; 25 Pounds; 25 Pounds; 25 Pounds; 25 Pounds
2013: 25 Pounds; 25 Pounds; 25 Pounds; 25 Pounds; 25 Pounds
2014: 25 Pounds; 25 Pounds; 25 Pounds
2015: 25 Pounds; 25 Pounds; 25 Pounds
2016: 25 Pounds; 25 Pounds; 25 Pounds
2017: 25 Pounds; 25 Pounds; 25 Pounds; 25 Pounds; 25 Pounds

2018: 25 Pounds; 25 Pounds; 25 Pounds

Manifest Information

Waste Code(s):

D004: ARSENIC (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1997: 40 Pounds
1998: 80 Pounds

Manifest Information

Waste Code(s):

D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1998: 30 Pounds
2001: 100 Pounds; 49960 Pounds
2002: 54220 Pounds
2004: 20 Tons

Manifest Information

Waste Code(s):

D006: CADMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2013: 22 Pounds
2015: 35 Pounds; 48 Pounds
2016: 26 Pounds
2017: 88 Pounds
2018: 65 Pounds

Manifest Information

Waste Code(s):

D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)
D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 25 Pounds

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1996: 30 Pounds
1997: 12000 Pounds
1998: 9300 Pounds; 5500 Gallons
1999: 300 Pounds; 3500 Pounds; 600 Pounds; 400 Pounds; 900 Pounds; 300 Pounds
2000: 10 Pounds
2001: 46520 Pounds; 300 Pounds; 500 Pounds; 47400 Pounds; 44560 Pounds; 41840 Pounds; 46880 Pounds; 50440 Pounds; 48600 Pounds; 51600 Pounds; 45620 Pounds; 20 Cubic yards; 44000 Pounds; 44140 Pounds; 40000 Pounds; 48000 Pounds; 46000 Pounds; 12 Cubic yards; 20 Cubic yards; 20 Cubic yards; 20 Cubic yards; 72000 Pounds; 44000 Pounds; 44000 Pounds; 44000 Pounds; 44000 Pounds; 20 Cubic yards; 20 Cubic yards; 20 Cubic yards; 48000 Pounds; 47000 Pounds; 43500 Pounds; 41680 Pounds; 42460 Pounds; 48060 Pounds; 47100 Pounds; 38800 Pounds; 44000 Pounds; 46000 Pounds; 44760 Pounds; 45620 Pounds; 42400 Pounds; 43740 Pounds; 48100 Pounds; 47300 Pounds; 47880 Pounds; 48600 Pounds; 23 Tons; 23 Tons; 30 Cubic yards; 45840 Pounds; 47420 Pounds; 46420 Pounds; 45520 Pounds; 44080 Pounds; 46220 Pounds; 44000 Pounds; 42240 Pounds; 34600 Pounds; 44040 Pounds; 51760 Pounds; 47280 Pounds; 50400 Pounds; 44880 Pounds; 48240 Pounds; 47600 Pounds; 43520 Pounds; 46260 Pounds; 37500 Pounds; 47420 Pounds; 45940 Pounds; 49580 Pounds; 42960 Pounds; 12 Cubic yards; 20 Cubic yards; 46840 Pounds; 48240 Pounds; 45160 Pounds; 20 Cubic yards; 59280 Pounds; 38000 Pounds; 44000 Pounds; 44000 Pounds; 44000 Pounds; 20 Cubic yards; 35000 Pounds; 44000 Pounds; 44000 Pounds; 44000 Pounds; 44000 Pounds; 44000 Pounds; 44000 Pounds; 42000 Pounds; 20 Cubic yards; 44000 Pounds; 25 Cubic yards; 25 Cubic yards; 25 Cubic yards; 50200 Pounds; 66200 Pounds; 39680 Pounds; 20 Cubic yards; 46880 Pounds; 48020 Pounds; 47100 Pounds; 48900 Pounds; 43660 Pounds; 46000 Pounds; 46000 Pounds; 48000 Pounds; 46000 Pounds; 46000 Pounds; 47000 Pounds; 49980 Pounds; 45900 Pounds; 48840 Pounds; 46800 Pounds; 46940 Pounds; 42980 Pounds; 44680 Pounds; 45480 Pounds; 45040 Pounds; 44420 Pounds; 44140 Pounds; 48180 Pounds; 43620 Pounds; 42080 Pounds; 44900 Pounds; 49300 Pounds; 44000 Pounds; 40000 Pounds; 20 Cubic yards; 20 Cubic yards; 44000 Pounds; 43000 Pounds; 45000 Pounds; 43260 Pounds; 58440 Pounds; 46380 Pounds; 4396 Pounds; 47760 Pounds; 10 Cubic yards; 46000 Pounds; 46000 Pounds; 46000 Pounds; 46000 Pounds; 30 Cubic yards; 30 Cubic yards; 51200 Pounds; 45200 Pounds; 46840 Pounds; 44140 Pounds; 44540 Pounds; 47160 Pounds; 47420 Pounds; 51160 Pounds; 47860 Pounds; 47880 Pounds; 44860 Pounds; 43460 Pounds; 46340 Pounds; 46220 Pounds; 39400 Pounds; 47000 Pounds; 27 Cubic yards; 24 Cubic yards; 20 Cubic yards; 23 Cubic yards; 44000 Pounds; 47000 Pounds; 46000 Pounds; 38000 Pounds; 44000 Pounds; 41200 Pounds; 47460 Pounds; 44860 Pounds; 47000 Pounds; 20 Cubic yards; 20 Cubic yards; 47980 Pounds; 46740 Pounds; 48520 Pounds; 45480 Pounds; 56020 Pounds; 46700 Pounds; 22 Tons; 46540 Pounds; 45600 Pounds; 45760 Pounds; 47880 Pounds; 53420 Pounds; 50740 Pounds; 44600 Pounds; 52520 Pounds; 48380 Pounds; 48480 Pounds; 42400 Pounds; 44500 Pounds; 46680 Pounds; 46280 Pounds; 49020 Pounds; 43500 Pounds; 45420 Pounds; 44400 Pounds; 47360 Pounds; 51060 Pounds; 49540 Pounds; 20 Cubic yards; 20 Cubic yards; 20 Cubic yards; 25 Cubic yards; 25 Cubic yards; 20 Cubic yards; 20 Cubic yards; 20 Cubic yards; 20 Cubic yards; 20 Cubic yards; 47640 Pounds; 22280 Pounds; 49800 Pounds; 44000 Pounds; 44000 Pounds; 40000 Pounds; 44000 Pounds; 46420 Pounds; 44280 Pounds; 46600 Pounds; 45600 Pounds; 44000 Pounds; 45180 Pounds; 45920 Pounds; 46660 Pounds; 43560 Pounds; 46480 Pounds; 47480 Pounds; 17240 Pounds; 45440 Pounds; 46060 Pounds; 46440 Pounds; 47600 Pounds; 46020 Pounds; 46760 Pounds; 45000 Pounds; 46380 Pounds; 22 Tons; 40580 Pounds; 44120 Pounds; 43280 Pounds; 46580 Pounds; 49500 Pounds; 47220 Pounds; 49160 Pounds; 45560 Pounds; 51920 Pounds; 47180 Pounds; 40860 Pounds; 48480 Pounds; 52600 Pounds; 48480 Pounds; 50740 Pounds; 48520 Pounds; 38000 Pounds; 42360 Pounds; 48000 Pounds; 48000 Pounds; 47000 Pounds; 44000 Pounds; 44000 Pounds; 44000 Pounds; 12 Cubic yards; 43720 Pounds; 47000 Pounds; 20 Cubic yards; 24 Cubic yards; 20 Cubic yards; 59520 Pounds; 46660 Pounds; 49800 Pounds; 52360 Pounds; 47090 Pounds; 12 Cubic yards; 20 Cubic yards; 41080 Pounds; 44420 Pounds; 46820 Pounds; 52280 Pounds; 22 Tons; 46060 Pounds; 47820 Pounds; 45360 Pounds; 47320 Pounds; 47880 Pounds; 46060 Pounds; 44920 Pounds; 45180 Pounds; 49640 Pounds; 47340 Pounds; 44560 Pounds; 42820 Pounds; 46380 Pounds; 39800 Pounds; 44660 Pounds; 43040 Pounds; 45820 Pounds; 50320 Pounds; 45800 Pounds; 39200 Pounds; 47140 Pounds; 46900 Pounds; 47220 Pounds; 47740 Pounds; 44000 Pounds
2002: 46420 Pounds; 47240 Pounds; 46840 Pounds; 40300 Pounds; 39740 Pounds; 43700 Pounds; 46140 Pounds; 52060 Pounds; 48680 Pounds; 48340 Pounds; 50220 Pounds; 49140 Pounds; 44120 Pounds; 55100 Pounds; 56160 Pounds; 60300 Pounds; 59000 Pounds; 61080 Pounds; 64180 Pounds; 43940 Pounds; 57920 Pounds; 59960 Pounds; 52160 Pounds; 53820 Pounds; 57360 Pounds; 56880 Pounds; 43740 Pounds; 50800 Pounds; 52620 Pounds; 43340 Pounds; 41780 Pounds; 47720 Pounds; 46560 Pounds; 43540 Pounds; 45220 Pounds; 38660 Pounds; 60460 Pounds; 50780 Pounds; 62300 Pounds; 66600 Pounds; 53160 Pounds; 56180 Pounds; 57180 Pounds; 50540 Pounds; 60960 Pounds; 61620 Pounds; 52740 Pounds; 60680 Pounds; 58580 Pounds; 62120 Pounds; 57600 Pounds; 60540 Pounds; 61820 Pounds; 50360 Pounds; 57620 Pounds; 52100 Pounds; 55840 Pounds; 56160 Pounds; 54400 Pounds; 52040 Pounds; 52240 Pounds; 50080 Pounds; 54040 Pounds; 51840 Pounds; 53780 Pounds; 49200 Pounds; 53640 Pounds; 53180 Pounds; 57240 Pounds; 56700 Pounds; 57780 Pounds; 54100 Pounds; 51460 Pounds; 51700 Pounds; 51640 Pounds; 20 Tons; 20 Tons; 20 Tons; 56420 Pounds; 49940 Pounds; 52180 Pounds; 55840 Pounds; 59840 Pounds; 58780 Pounds; 57480 Pounds; 54180 Pounds; 60420 Pounds; 44060 Pounds; 44740 Pounds; 39060 Pounds; 59300 Pounds; 52580 Pounds; 20 Tons; 58520 Pounds; 53720 Pounds; 48860 Pounds; 47020 Pounds; 44240 Pounds; 50340 Pounds; 46120 Pounds; 600 Pounds; 1200 Pounds; 31040 Pounds; 39800 Pounds; 53900 Pounds; 46740 Pounds; 51760 Pounds; 51220 Pounds; 46300 Pounds; 50440 Pounds; 48580 Pounds; 42820 Pounds; 55660 Pounds; 54140 Pounds; 59260 Pounds; 52920 Pounds; 57700 Pounds; 52940 Pounds; 58540 Pounds; 57860 Pounds; 61160 Pounds; 53020 Pounds; 55400 Pounds; 55640 Pounds; 50300 Pounds; 61000 Pounds; 56800 Pounds; 56800 Pounds; 46760 Pounds; 50740 Pounds; 54360 Pounds; 54620 Pounds; 50780 Pounds; 61400 Pounds; 56480 Pounds; 50840 Pounds; 50440 Pounds; 46480 Pounds; 46460 Pounds; 52240 Pounds; 56460 Pounds; 47420 Pounds; 29 Tons; 54840 Pounds; 20 Tons; 62080 Pounds; 49440 Pounds; 54100 Pounds; 58920 Pounds; 31 Tons; 29 Tons; 26 Tons; 29 Tons; 25 Tons; 20 Tons; 20 Tons; 20 Tons; 20 Tons; 20 Tons; 20 Tons; 20 Tons; 20 Tons; 20 Tons; 20 Tons; 20 Tons; 20 Tons; 45260 Pounds; 56620 Pounds; 58820 Pounds; 65260 Pounds; 58900 Pounds; 53200 Pounds; 56740 Pounds; 51560 Pounds; 56400 Pounds; 46640 Pounds; 50460 Pounds; 55960 Pounds; 47740 Pounds; 51400 Pounds; 53840 Pounds; 55880 Pounds; 52220 Pounds; 54880 Pounds; 52800 Pounds; 56540 Pounds; 53620 Pounds; 56420 Pounds; 20 Tons; 20 Tons; 20 Tons; 20 Tons; 20 Tons; 56380 Pounds; 20 Tons; 57700 Pounds; 55740 Pounds; 47820 Pounds; 54940 Pounds; 65440 Pounds; 49280 Pounds; 49160 Pounds; 46700 Pounds; 58420 Pounds; 54600 Pounds; 57800 Pounds; 45060 Pounds; 43360 Pounds; 46560 Pounds; 41460 Pounds; 45500 Pounds; 45160 Pounds; 39580 Pounds; 45020 Pounds; 40640 Pounds; 50340 Pounds; 47360 Pounds; 46620 Pounds; 41960 Pounds; 47420 Pounds; 21 Tons; 25 Tons; 24 Tons; 24 Tons; 23 Tons; 62920 Pounds; 60540 Pounds; 52520 Pounds; 30 Tons; 24 Tons; 49200 Pounds; 53660 Pounds; 54600 Pounds; 54880 Pounds; 50620 Pounds; 46860 Pounds; 51100 Pounds; 45140 Pounds; 49220 Pounds; 50940 Pounds; 52420 Pounds; 58160 Pounds; 58780 Pounds; 62860 Pounds; 56120 Pounds; 56160 Pounds; 56620 Pounds; 54140 Pounds; 52340 Pounds; 60180 Pounds; 52120 Pounds; 57020 Pounds; 55800 Pounds; 44400 Pounds; 51340 Pounds; 46700 Pounds; 59500 Pounds; 53640 Pounds; 50120 Pounds; 56040 Pounds; 56740 Pounds; 50580 Pounds; 57820 Pounds; 50660 Pounds; 23 Tons; 53240 Pounds; 49380 Pounds; 47520 Pounds; 43760 Pounds; 53820 Pounds; 47120 Pounds; 47860 Pounds; 49460 Pounds; 48500 Pounds; 59140 Pounds; 45840 Pounds; 44840 Pounds; 54340 Pounds; 49260 Pounds; 47960 Pounds; 46360 Pounds; 42100 Pounds; 57040 Pounds; 52060 Pounds; 48520 Pounds; 52740 Pounds; 50120 Pounds; 53960 Pounds; 47740 Pounds; 47140 Pounds; 49140 Pounds; 48400 Pounds; 48740 Pounds; 53760 Pounds; 50640 Pounds; 52520 Pounds; 20 Tons; 20 Tons; 52360 Pounds; 56800 Pounds; 52940 Pounds; 48380 Pounds; 51600 Pounds; 52100 Pounds; 49220 Pounds; 50160 Pounds; 55780 Pounds; 50080 Pounds; 57440 Pounds; 54280 Pounds;

56720 Pounds; 45540 Pounds; 51780 Pounds; 54380 Pounds; 51600 Pounds; 49640 Pounds; 46380 Pounds; 46180 Pounds; 51540 Pounds; 55420 Pounds; 49740 Pounds; 49300 Pounds; 50860 Pounds; 45240 Pounds; 46800 Pounds; 47700 Pounds; 49720 Pounds; 39500 Pounds; 45580 Pounds; 44400 Pounds; 53720 Pounds; 43940 Pounds; 43060 Pounds; 5 Gallons; 53060 Pounds; 52240 Pounds; 49200 Pounds; 58340 Pounds; 52660 Pounds; 53540 Pounds; 49700 Pounds; 52960 Pounds; 57780 Pounds; 54980 Pounds; 53020 Pounds; 53660 Pounds; 46880 Pounds; 53880 Pounds; 53160 Pounds; 56460 Pounds; 54400 Pounds; 56620 Pounds; 53260 Pounds; 56740 Pounds; 56160 Pounds; 56120 Pounds; 54660 Pounds; 52500 Pounds; 54720 Pounds; 43040 Pounds; 45300 Pounds; 42660 Pounds; 45260 Pounds; 46920 Pounds; 25 Tons; 31 Tons; 26 Tons; 28 Tons; 51600 Pounds; 46160 Pounds; 47780 Pounds; 41480 Pounds; 49440 Pounds; 53380 Pounds; 49440 Pounds; 41720 Pounds; 330 Pounds; 60360 Pounds; 57280 Pounds; 54960 Pounds; 52760 Pounds; 56800 Pounds; 52980 Pounds; 56740 Pounds; 58680 Pounds; 58660 Pounds; 7400 Pounds; 57340 Pounds; 58260 Pounds; 60120 Pounds; 58480 Pounds; 55520 Pounds; 56100 Pounds; 61700 Pounds; 62360 Pounds; 49480 Pounds; 55840 Pounds; 57060 Pounds; 52220 Pounds; 54120 Pounds; 64660 Pounds; 59320 Pounds; 47720 Pounds; 50240 Pounds; 51760 Pounds; 55600 Pounds; 50600 Pounds; 55800 Pounds; 45940 Pounds; 52620 Pounds; 51200 Pounds; 44600 Pounds; 48520 Pounds; 59120 Pounds; 54660 Pounds; 57200 Pounds; 55720 Pounds; 58220 Pounds; 54800 Pounds; 52300 Pounds; 55960 Pounds; 46640 Pounds; 56780 Pounds; 47700 Pounds; 55100 Pounds; 52280 Pounds; 49720 Pounds; 57720 Pounds; 47660 Pounds; 46480 Pounds; 53080 Pounds; 50720 Pounds; 40540 Pounds; 61320 Pounds; 56300 Pounds; 66560 Pounds; 57940 Pounds; 57340 Pounds; 60040 Pounds; 62200 Pounds; 55720 Pounds; 44500 Pounds; 50960 Pounds; 20 Tons; 52860 Pounds; 55100 Pounds; 58340 Pounds; 20 Tons; 53560 Pounds; 54440 Pounds; 20 Tons; 20 Tons; 56820 Pounds; 41240 Pounds; 55460 Pounds; 42420 Pounds; 55240 Pounds; 52020 Pounds; 48340 Pounds; 52120 Pounds; 54240 Pounds; 58920 Pounds; 55260 Pounds; 61540 Pounds; 58820 Pounds; 46880 Pounds; 54820 Pounds; 50440 Pounds; 50520 Pounds; 58340 Pounds; 51940 Pounds; 50240 Pounds; 48880 Pounds; 48040 Pounds; 50200 Pounds; 51900 Pounds; 57720 Pounds; 56540 Pounds; 54320 Pounds; 60240 Pounds; 32 Tons; 50340 Pounds; 43380 Pounds; 44080 Pounds; 56380 Pounds; 53140 Pounds; 54140 Pounds; 49780 Pounds; 52940 Pounds; 49880 Pounds; 41940 Pounds; 40800 Pounds; 44000 Pounds; 54520 Pounds; 51300 Pounds; 56700 Pounds; 38980 Pounds; 53840 Pounds; 58600 Pounds; 46980 Pounds; 64160 Pounds; 53060 Pounds; 50100 Pounds; 39820 Pounds; 44460 Pounds; 47140 Pounds; 20 Tons; 20 Tons; 54100 Pounds; 47760 Pounds; 47060 Pounds; 47960 Pounds; 53920 Pounds; 52880 Pounds; 57280 Pounds; 53440 Pounds; 65760 Pounds; 54140 Pounds; 57440 Pounds; 53960 Pounds; 56760 Pounds; 48720 Pounds; 51100 Pounds; 49000 Pounds; 50980 Pounds; 56560 Pounds; 50910 Pounds; 58740 Pounds; 62900 Pounds; 54700 Pounds; 52700 Pounds; 50720 Pounds; 49760 Pounds; 48820 Pounds; 52320 Pounds; 51800 Pounds; 50140 Pounds; 52860 Pounds; 49520 Pounds; 48580 Pounds; 55060 Pounds; 55080 Pounds; 45820 Pounds; 46960 Pounds; 46360 Pounds; 44800 Pounds; 45520 Pounds; 41460 Pounds; 43640 Pounds; 49820 Pounds; 63800 Pounds; 56480 Pounds; 21680 Pounds; 55600 Pounds; 59220 Pounds; 52440 Pounds; 45420 Pounds; 51720 Pounds; 51900 Pounds; 53920 Pounds; 53840 Pounds; 49200 Pounds; 50320 Pounds; 51820 Pounds; 54300 Pounds; 53760 Pounds; 55540 Pounds; 58520 Pounds; 56140 Pounds; 56440 Pounds

2003: 59020 Pounds; 64620 Pounds; 65080 Pounds; 67080 Pounds; 58380 Pounds; 61060 Pounds; 53020 Pounds; 57060 Pounds; 57520 Pounds; 62560 Pounds; 250 Pounds; 58460 Pounds; 63120 Pounds; 14 Cubic yards; 25680 Pounds; 52740 Pounds; 50700 Pounds; 56100 Pounds; 56120 Pounds; 65220 Pounds; 53020 Pounds; 60700 Pounds; 52920 Pounds; 20 Cubic yards; 50180 Pounds; 56020 Pounds; 60940 Pounds; 58760 Pounds; 53280 Pounds; 50620 Pounds; 50200 Pounds; 57040 Pounds; 54200 Pounds; 50720 Pounds; 54020 Pounds; 600 Pounds; 14 Cubic yards; 37820 Pounds; 23140 Pounds; 1780 Pounds; 59500 Pounds; 58820 Pounds; 65740 Pounds; 61780 Pounds; 57100 Pounds; 60060 Pounds; 62860 Pounds; 58340 Pounds; 55920 Pounds; 69680 Pounds; 56500 Pounds; 54020 Pounds; 53000 Pounds; 46960 Pounds; 50560 Pounds; 49540 Pounds; 39300 Pounds; 50520 Pounds; 49420 Pounds; 52120 Pounds; 46240 Pounds; 57860 Pounds; 52680 Pounds; 67520 Pounds; 56320 Pounds; 59860 Pounds; 25 Cubic yards; 25 Cubic yards; 59500 Pounds; 55860 Pounds; 54980 Pounds; 53820 Pounds; 54380 Pounds; 56840 Pounds; 57166 Pounds; 58120 Pounds; 46460 Pounds; 48960 Pounds; 51780 Pounds; 59380 Pounds; 61680 Pounds; 61100 Pounds; 58260 Pounds; 25 Cubic yards; 52760 Pounds; 54820 Pounds; 56280 Pounds; 51820 Pounds; 57580 Pounds; 20 Cubic yards; 39200 Pounds; 45360 Pounds; 41440 Pounds; 55460 Pounds; 61840 Pounds; 54740 Pounds; 46760 Pounds; 55640 Pounds; 52520 Pounds; 58360 Pounds; 56680 Pounds; 54140 Pounds; 53520 Pounds

2004: 57800 Pounds; 63100 Pounds; 52760 Pounds; 55600 Pounds; 50420 Pounds; 57860 Pounds; 57120 Pounds; 56100 Pounds; 57800 Pounds; 61460 Pounds; 54820 Pounds; 58200 Pounds; 62400 Pounds; 58460 Pounds; 54780 Pounds; 61520 Pounds; 48780 Pounds; 57080 Pounds; 59860 Pounds; 63400 Pounds; 59850 Pounds; 44900 Pounds; 59060 Pounds; 49040 Pounds; 56600 Pounds; 59000 Pounds; 56860 Pounds; 47960 Pounds; 48420 Pounds; 54000 Pounds; 57560 Pounds; 45560 Pounds; 59320 Pounds; 54880 Pounds; 54640 Pounds; 59600 Pounds; 63200 Pounds; 20 Cubic yards; 20 Cubic yards; 47420 Pounds; 47780 Pounds; 60040 Pounds; 61080 Pounds; 50200 Pounds; 62560 Pounds; 57560 Pounds; 61220 Pounds; 54940 Pounds; 56940 Pounds; 59000 Pounds; 59640 Pounds; 58520 Pounds; 58100 Pounds; 54360 Pounds; 56800 Pounds; 63720 Pounds; 20 Cubic yards; 20 Cubic yards; 40 Cubic yards; 44000 Pounds; 42000 Pounds; 20 Tons; 47280 Pounds; 19 Cubic yards; 45100 Pounds; 47000 Pounds; 40580 Pounds; 44640 Pounds; 45180 Pounds; 61800 Pounds; 53040 Pounds; 57380 Pounds; 59240 Pounds; 61020 Pounds; 65120 Pounds; 47300 Pounds; 33600 Pounds; 55600 Pounds; 53240 Pounds; 56480 Pounds; 61200 Pounds; 60560 Pounds; 20 Cubic yards; 20 Cubic yards; 52060 Pounds; 49600 Pounds; 47210 Pounds; 41980 Pounds; 36160 Pounds; 47180 Pounds; 56800 Pounds; 57460 Pounds; 57240 Pounds; 63080 Pounds; 59640 Pounds; 54840 Pounds; 65700 Pounds; 43820 Pounds; 20 Cubic yards; 20 Cubic yards; 53600 Pounds; 62500 Pounds; 22 Tons; 20 Cubic yards; 63740 Pounds; 52980 Pounds; 55680 Pounds; 57700 Pounds; 20 Cubic yards; 55280 Pounds; 40760 Pounds; 50360 Pounds; 27840 Pounds; 56660 Pounds; 20 Cubic yards; 45700 Pounds; 53020 Pounds; 54060 Pounds; 62640 Pounds; 64460 Pounds; 20 Cubic yards; 47660 Pounds; 57640 Pounds; 48420 Pounds; 43980 Pounds; 48560 Pounds; 56560 Pounds; 55340 Pounds; 50160 Pounds; 20 Cubic yards; 46700 Pounds; 44580 Pounds; 43740 Pounds; 15 Cubic yards; 20 Cubic yards; 50400 Pounds; 20 Cubic yards; 20 Cubic yards; 20 Cubic yards; 53200 Pounds; 54820 Pounds; 55820 Pounds; 56700 Pounds; 55780 Pounds; 54180 Pounds; 54800 Pounds; 58580 Pounds; 48880 Pounds; 60740 Pounds; 45740 Pounds; 47000 Pounds; 46580 Pounds; 42960 Pounds; 44380 Pounds; 33080 Pounds; 49680 Pounds; 50240 Pounds; 20 Cubic yards; 44280 Pounds; 41740 Pounds; 40300 Pounds; 20 Cubic yards; 20 Cubic yards; 20 Cubic yards; 20 Cubic yards; 20 Cubic yards; 48140 Pounds; 27940 Pounds; 52520 Pounds; 58560 Pounds; 66120 Pounds; 53080 Pounds; 600 Pounds; 150 Pounds; 45140 Pounds; 61620 Pounds; 20 Cubic yards; 20 Cubic yards; 68240 Pounds; 65020 Pounds; 58740 Pounds; 56940 Pounds; 52440 Pounds; 60300 Pounds; 42520 Pounds; 51300 Pounds; 52440 Pounds; 62520 Pounds; 65240 Pounds; 58380 Pounds; 61420 Pounds; 74420 Pounds; 74940 Pounds; 57140 Pounds; 65160 Pounds; 63900 Pounds; 63080 Pounds; 63820 Pounds; 62480 Pounds; 12260 Pounds; 20 Cubic yards; 60620 Pounds; 20 Cubic yards; 22 Tons; 64520 Pounds; 20 Cubic yards; 20 Tons; 20 Pounds; 20 Tons; 20 Cubic yards; 45420 Pounds; 44080 Pounds; 20 Cubic yards; 46560 Pounds; 64640 Pounds; 55080 Pounds; 58420 Pounds; 71620 Pounds; 63200 Pounds; 65400 Pounds; 20 Cubic yards; 47360 Pounds; 59360 Pounds; 45360 Pounds; 43940 Pounds; 44800 Pounds; 45920 Pounds; 46880 Pounds; 44340 Pounds; 20 Cubic yards; 20 Cubic yards; 45380 Pounds; 44060 Pounds; 47440 Pounds; 20 Cubic yards; 20 Cubic yards; 47020 Pounds; 40 Cubic yards; 44720 Pounds; 20 Cubic yards; 20 Cubic yards; 47460 Pounds; 55240 Pounds; 53040 Pounds; 20 Cubic yards; 20 Cubic yards; 58600 Pounds; 70940 Pounds; 55600 Pounds; 60560 Pounds; 45040 Pounds; 20 Cubic yards; 47100 Pounds; 54280 Pounds; 61200 Pounds; 59380 Pounds; 52320 Pounds; 59500 Pounds; 57460 Pounds; 56580 Pounds; 54860 Pounds; 60860 Pounds; 54960 Pounds; 63760 Pounds; 47000 Pounds; 48300 Pounds; 18 Cubic yards; 56180 Pounds; 58820 Pounds; 51060 Pounds; 51180 Pounds; 55 Cubic yards; 48420 Pounds; 46880 Pounds; 51600 Pounds; 57820 Pounds; 61320 Pounds; 20 Cubic yards; 63420 Pounds; 61960 Pounds; 20 Cubic yards; 20 Cubic yards; 64760 Pounds; 76200 Pounds; 67820 Pounds; 51500 Pounds; 73420 Pounds; 51540 Pounds; 63100 Pounds; 61600 Pounds; 18 Cubic yards; 51060 Pounds; 58760 Pounds; 45960 Pounds; 45660 Pounds; 20 Tons; 46240 Pounds; 20 Cubic yards; 54340 Pounds; 60060 Pounds; 61240 Pounds; 50360 Pounds; 59700 Pounds; 55040 Pounds; 20 Cubic yards; 58380 Pounds; 50780 Pounds; 57100 Pounds; 61300 Pounds; 35460 Pounds; 60380 Pounds; 55360 Pounds; 20 Cubic yards; 49620 Pounds; 45380

Pounds; 48100 Pounds; 47460 Pounds; 47000 Pounds; 48180 Pounds; 20 Cubic yards; 44000 Pounds; 47960 Pounds
2005: 54840 Pounds; 59960 Pounds; 41900 Pounds; 58140 Pounds; 49360 Pounds; 58840 Pounds; 48900 Pounds; 47420 Pounds; 20 Cubic yards; 40 Cubic yards; 61060 Pounds; 54320 Pounds; 64960 Pounds; 60920 Pounds; 65380 Pounds; 53320 Pounds; 60000 Pounds; 59160 Pounds; 62340 Pounds; 46780 Pounds; 46860 Pounds; 47080 Pounds; 46380 Pounds; 48820 Pounds; 20 Cubic yards; 55760 Pounds; 50900 Pounds; 59280 Pounds; 56160 Pounds; 52380 Pounds; 20 Cubic yards; 250 Pounds; 7000 Pounds; 45080 Pounds; 44400 Pounds; 43200 Pounds; 43620 Pounds; 47000 Pounds; 64720 Pounds; 57800 Pounds; 58260 Pounds; 20 Cubic yards; 53220 Pounds; 49760 Pounds; 56160 Pounds; 63620 Pounds; 10000 Pounds; 41900 Pounds; 8980 Pounds
2006: 54860 Pounds; 19920 Pounds; 46700 Pounds
2007: 900 Pounds; 10 Gallons; 55 Gallons
2008: 60140 Pounds; 59760 Pounds; 63100 Pounds; 400 Pounds; 48480 Pounds; 36520 Pounds; 51160 Pounds; 42920 Pounds; 55640 Pounds; 64360 Pounds; 62880 Pounds; 64420 Pounds; 42700 Pounds; 52300 Pounds; 60840 Pounds; 59160 Pounds; 64340 Pounds; 64920 Pounds; 20 Cubic yards; 58280 Pounds; 70 Pounds
2009: 61160 Pounds; 20 Cubic yards; 58120 Pounds; 64760 Pounds; 53560 Pounds; 20 Cubic yards; 70 Pounds; 49460 Pounds; 51280 Pounds; 60420 Pounds; 52480 Pounds; 20 Cubic yards; 25 Cubic yards; 20 Cubic yards; 70 Pounds; 5 Pounds; 50060 Pounds; 57480 Pounds; 53440 Pounds; 58900 Pounds; 54440 Pounds; 66520 Pounds; 20 Cubic yards; 20 Cubic yards; 48220 Pounds; 20 Cubic yards; 20 Cubic yards; 20 Cubic yards; 52620 Pounds; 58700 Pounds; 60740 Pounds; 56620 Pounds; 52080 Pounds; 49060 Pounds; 60080 Pounds; 68080 Pounds; 18 Cubic yards; 25 Cubic yards; 20 Cubic yards; 62340 Pounds; 64760 Pounds; 66720 Pounds; 64760 Pounds; 65820 Pounds; 65360 Pounds; 62540 Pounds; 59800 Pounds; 44060 Pounds; 67260 Pounds; 61080 Pounds; 70640 Pounds; 25 Cubic yards; 25 Cubic yards; 20 Cubic yards; 44540 Pounds; 30 Pounds; 140 Pounds; 200 Pounds; 51100 Pounds; 44560 Pounds; 44060 Pounds
2010: 18 Cubic yards; 18 Cubic yards; 20 Cubic yards; 64300 Pounds; 50500 Pounds; 56540 Pounds; 53100 Pounds; 55600 Pounds; 53760 Pounds; 55460 Pounds; 63760 Pounds; 57100 Pounds; 58200 Pounds; 54780 Pounds; 59620 Pounds; 18 Cubic yards; 75 Pounds; 100 Pounds; 20 Cubic yards; 200 Pounds; 56720 Pounds; 18 Cubic yards; 48960 Pounds; 55660 Pounds; 58620 Pounds; 650 Pounds
2011: 22.7 Tons; 28.2 Tons; 500 Pounds; 25.9 Tons; 29.1 Tons; 26.9 Tons; 26.7 Tons; 100 Pounds; 25.4 Tons; 200 Pounds; 250 Pounds; 23.8 Tons; 260 Pounds
2012: 225 Pounds; 225 Pounds; 300 Pounds; 6880 Pounds

Manifest Information

Waste Code(s):

B001: (Wastes containing polychlorinated biphenyls (PCBs)) PCB oil (concentrated) from transformers, capacitors, etc.

Waste Amounts By Year:

1991: 2762 Kilograms

Manifest Information

Waste Code(s):

B007: (Wastes containing polychlorinated biphenyls (PCBs)) Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.
F001: (Generic) The following spent halogenated solvents used in degreasing: tetrachloroethylene, trichloroethylene, methylene chloride, 1,1, 1-trichloroethane, carbon tetrachloride, and chlorinated fluorocarbons; all spent solvent mixtures/blends used in degreasing containing, before use, total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those solvents listed in F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

2009: 3200 Kilograms

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1996: 200 Pounds; 350 Pounds; 5 Gallons
1997: 40 Pounds
1998: 1 Gallons; 80 Pounds; 1 Pounds; 1 Gallons; 3500 Gallons
1999: 1 Gallons; 30 Pounds; 10 Pounds; 10 Pounds; 165 Gallons; 30 Pounds; 55 Gallons; 110 Gallons; 110 Gallons; 1 Pounds; 20 Pounds
2000: 5 Pounds
2001: 600 Pounds; 5 Pounds; 5 Pounds; 1400 Pounds

2002: 44120 Pounds; 52620 Pounds; 50800 Pounds; 245 Gallons; 56960 Pounds
2006: 165 Gallons; 55 Gallons; 60 Gallons; 55 Gallons; 10 Pounds; 55 Gallons; 5 Gallons; 55 Gallons
2009: 22 Gallons
2010: 10 Pounds
2015: 1 Pounds
2016: 344 Pounds
2017: 6 Pounds
2018: 13 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2009: 55 Gallons

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 10 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 20 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U154: (67-56-1) Methanol (I)

Waste Amounts By Year:

2018: 36 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1996: 20 Pounds
1997: 5 Pounds; 40 Pounds; 40 Pounds
1998: 80 Pounds; 1 Gallons; 405 Gallons; 8 Pounds; 1 Gallons
1999: 1 Pounds; 7 Pounds; 30 Gallons; 55 Gallons; 60 Gallons; 330 Gallons; 55 Gallons; 7 Pounds; 250 Pounds; 1000 Pounds; 55 Gallons; 10 Pounds; 165 Gallons
2000: 5 Gallons
2001: 100 Pounds; 100 Pounds
2005: 28 Pounds; 28 Pounds
2006: 55 Gallons; 28 Pounds; 5 Gallons; 55 Gallons; 110 Gallons
2010: 10 Pounds; 10 Pounds; 1 Pounds
2013: 1250 Gallons; 350 Gallons
2015: 2400 Pounds
2016: 39 Pounds
2017: 1800 Pounds
2018: 20 Pounds; 20 Pounds; 600 Pounds; 600 Pounds; 1 Pounds; 124 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 100 Pounds; 75 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1998: 80 Pounds; 80 Pounds
2001: 5 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
P030: Cyanides (soluble cyanide salts), not otherwise specified

Waste Amounts By Year:

2010: 1 Pounds; 5 Pounds
2015: .44 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
P105: (26628-22-8) Sodium azide

Waste Amounts By Year:

2010: 1 Pounds
2011: 60 Pounds

Manifest Information

Waste Code(s):

D006: CADMIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2009: 25 Pounds
2010: 20 Pounds
2013: 10 Pounds; 10 Pounds
2014: 60 Pounds; 10 Pounds
2015: 5 Pounds
2017: 3 Pounds; 20 Pounds
2018: 25 Pounds

Manifest Information

Waste Code(s):

D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2011: 60 Pounds; 30 Pounds; 80 Pounds
2012: 30 Pounds; 90 Pounds
2013: 22 Pounds; 20 Pounds; 40 Pounds
2014: 20 Pounds; 60 Pounds; 15 Pounds; 28 Pounds
2015: 30 Pounds
2017: 2 Pounds

Manifest Information

Waste Code(s):

D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1996: 20 Pounds
1998: 160 Pounds
1999: 200 Pounds; 900 Pounds; 300 Pounds; 150 Pounds; 20 Pounds
2001: 5 Pounds
2006: 10 Pounds; 260 Pounds; 5 Pounds; 85 Pounds
2008: 1 Pounds; 2 Pounds
2011: 2 Pounds
2012: 1 Pounds
2015: 20 Pounds
2016: 7 Pounds
2017: 40 Pounds
2018: 51 Pounds

Manifest Information

Waste Code(s):

D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2001: 5 Pounds
2015: 1 Pounds

Manifest Information

Waste Code(s):

D039: TETRACHLOROETHYLENE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2001: 54760 Pounds; 54040 Pounds; 50040 Pounds; 40320 Pounds; 47960 Pounds; 500 Pounds; 40220 Pounds; 50720 Pounds; 50940 Pounds; 51140 Pounds; 45160 Pounds

Manifest Information

Waste Code(s):

P105: (26628-22-8) Sodium azide

Waste Amounts By Year:

2001: 5 Pounds

Manifest Information

Waste Code(s):

U123: (64-18-6) Formic acid (C,T)

Waste Amounts By Year:

2001: 5 Pounds

Manifest Information

Waste Code(s):

U154: (67-56-1) Methanol (I)

Waste Amounts By Year:

2001: 100 Pounds
2002: 237 Gallons

Manifest Information

Waste Code(s):

U188: (108-95-2) Phenol

Waste Amounts By Year:

1999: 60 Pounds
2018: 5 Pounds

77	164 of175	NE	0.12 / 649.95	9.75 / -2	NYC DEP 329 GREENPOINT AVE BROOKLYN NY 11201	GEN MANIFEST

RCRA ID: NYP003661741 ***Mailing State:*** NY

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

District Name:	NYC DEP	**Mailing ZIP:**	11368
Contact Name:	PETER WILLIAMSEN	**Mailing ZIP Ext:**	
Business Phone No:	7185954814	**Mailing Country:**	USA
Mailing Street 1:	59 17 JUNCTION BLVD	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	CORONA	**Location County:**	KINGS

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2003: 20 Pounds

77	165 of175	NE	0.12 / 649.95	9.75 / -2	EXXON COMPANY USA 3020 320 FREEMAN ST BROOKLYN NY 11222	GEN MANIFEST

RCRA ID:	NYD063855746	**Mailing State:**	NY
District Name:	EXXON COMPANY USA 3020	**Mailing ZIP:**	11222
Contact Name:	WILLIAM K SANDSJO	**Mailing ZIP Ext:**	
Business Phone No:	2123890100	**Mailing Country:**	USA
Mailing Street 1:	320 FREEMAN STREET	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	BROOKLYN	**Location County:**	KINGS

Manifest Information

Waste Code(s):

F001: (Generic) The following spent halogenated solvents used in degreasing: tetrachloroethylene, trichloroethylene, methylene chloride, 1,1, 1-trichloroethane, carbon tetrachloride, and chlorinated fluorocarbons; all spent solvent mixtures/blends used in degreasing containing, before use, total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those solvents listed in F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

1991: 880 Gallons

Manifest Information

Waste Code(s):

F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

1984: 385 Gallons
1989: 45 Pounds
1990: 45 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1984: 3500 Gallons
1986: 45 Pounds; 45 Pounds; 4123 Gallons; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds
1987: 4200 Gallons; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 35 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 4425 Pounds; 45 Pounds; 45 Pounds; 45 Pounds
1988: 4200 Gallons; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 1760 Gallons; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 2145 Gallons; 45 Pounds; 1760 Gallons; 1760 Gallons; 45 Pounds; 45 Pounds; 4200 Gallons; 45 Pounds; 45 Pounds
1989: 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds; 45 Pounds
1990: 45 Pounds; 2340 Gallons; 45 Pounds; 45 Pounds; 45 Pounds
1991: 55 Gallons
1993: 17 Gallons; 14 Pounds; 16 Gallons; 14 Gallons; 16 Gallons; 15 Gallons; 50 Gallons; 17 Gallons
1994: 17 Gallons; 16 Gallons; 17 Gallons; 17 Gallons

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1987: 1050 Pounds

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1987: 240 Gallons
1988: 7803 Pounds
1992: 20750 Pounds; 16000 Pounds; 2751 Gallons

Manifest Information

Waste Code(s):

D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1990: 4160 Gallons
1991: 1650 Gallons; 3685 Gallons; 990 Gallons
1994: 55 Gallons

Manifest Information

Waste Code(s):

U080: (75-09-2) Methane, dichloro-

Waste Amounts By Year:

1990: 1600 Gallons; 2400 Gallons
1991: 55 Gallons

Manifest Information

Waste Code(s):

U226: (71-55-6) Methyl chloroform

Waste Amounts By Year:

1991: 880 Gallons

Manifest Information

Waste Code(s):

X722: Not Listed In 6 CRR-NY 371.4 or EPA Hazardous Waste Identification

Waste Amounts By Year:

1987: 2800 Pounds

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
77	166 of175	NE	0.12 / 649.95	9.75 / -2	NEWTOWN CREEK WASTEWATER RESOURCE RECOVERY FACILITY 329-69 GREENPOINT AVE BROOKLYN NY 11222	AIR PERMITS

Facility ID:
County:
Dec ID: 2610100025
Source: Air Permitted Facilities; Air Title V

Facility Details

Permit Type: ASF
Status: Expired
Renewal No: 0
Url Permit:
Modification No: 0
Issue Date:
Exp Date: 3/30/2016

Permit Type: ASF
Status: Expired
Renewal No: 0
Url Permit:
Modification No: 1
Issue Date: 3/30/2016
Exp Date:

Permit Type: ASF
Status: Expired
Renewal No: 0
Url Permit:
Modification No: 0
Issue Date: 8/5/2004
Exp Date: 3/30/2016

Title V Details

Permit Type: ATV
Status: Issued
Renewal No: 2
Url Permit: https://extapps.dec.ny.gov/data/dar/afs/issued_atv.html
Modification No: 0
Issue Date: 10/2/2019
Exp Date: 10/1/2024

Permit Type: ATV
Status: Expired
Renewal No: 1
Url Permit:
Modification No: 0
Issue Date: 1/7/2014
Exp Date: 1/6/2019

Permit Type: ATV
Status: Expired
Modification No: 0
Issue Date: 1/26/2005

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Renewal No: 0 **Exp Date:** 1/25/2010
Url Permit:

Permit Type: ATV **Modification No:** 1
Status: Expired **Issue Date:** 9/8/2005
Renewal No: 0 **Exp Date:** 1/25/2010
Url Permit:

Permit Type: ATV **Modification No:** 2
Status: Expired **Issue Date:** 10/4/2005
Renewal No: 0 **Exp Date:** 1/25/2010
Url Permit:

---

77 | **167 of175** | **NE** | **0.12 / 649.95** | **9.75 / -2** | **Nyc Dep Bwt Newtown Creek Wpcp**
329 Greenpoint Ave
Brooklyn NY 11222 | **TIER 2**

Company Name:
DUN Bradstreet Cd:
County: Kings County (Brooklyn)
Latitude:
Longitude:
Report Method: Reported via Mail

---

77 | **168 of175** | **NE** | **0.12 / 649.95** | **9.75 / -2** | **Nyc Dep Bwt Newtown Creek Wpcp**
329 Greenpoint Ave
Brooklyn NY | **TIER 2**

Company Name:
DUN Bradstreet Cd:
County: New York
Latitude:
Longitude:
Report Method: Reported via Mail

---

77 | **169 of175** | **NE** | **0.12 / 649.95** | **9.75 / -2** | **NYC DEP BWT Newtown Creek WPCP**
329 Greenpoint Ave
Brooklyn NY 11222 | **TIER 2**

Company Name:
DUN Bradstreet Cd:
County: Brooklyn
Latitude:
Longitude:
Report Method: Reported via Mail

---

77 | **170 of175** | **NE** | **0.12 / 649.95** | **9.75 / -2** | **NATIONAL GRID VEHICLE**
327 GREENPOINT AVE
BROOKLYN NY | **NY SPILLS**

Spill No: 2209274 **UST Trust:** False
Site ID: 648640 **Spill Date:** 02/17/2023 08:15:00 AM
DER Facility ID: 594730 **Received Date:** 02/17/2023 11:12:00 AM
CID: **CAC Date:**
Program Type: ER **Insp Date:**
SWIS Code: 2401 **Close Date:** 02/17/2023 12:00:00 AM
Water Body: **Create Date:** 02/17/2023 11:14:00 AM
Class: **Update Date:** 02/17/2023 11:41:14 AM
Meets Std: False **DEC Region:** 2
Penalty: False **Lead DEC:** HSSEKHON

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

REM Phase: 0 **After Hours:** False
County: Kings
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Commercial Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Fitting on a vehicle leaked less than a gallon to the vehicle. Contained, no resources impacted. Cleanup in progress"

DEC Remark:

"Due to equipment failure, less than 1 gallon of mineral oil spilled onto concrete floor. Spill contained, no drain affected. Spill cleaned up. Case closed."

Material Information

OP Unit ID: 1395592
OU: 01
Material ID: 2411329
CAS No:
Material Family: Petroleum
Quantity:
Units:
Recovered:
Med Soil: False
Med Air: False
Material Code: 2630
Material Name: mineral oil

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: NATIONAL GRID
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: NANCY WAGNER
Contact Phone: (516) 903-6287
Contact Ext:
Latitude:
Longitude:

77	171 of175	NE	0.12 / 649.95	9.75 / -2	COMMERICAL EQUIPEMNT 327 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No: 2209494
Site ID: 648872
DER Facility ID: 594730
CID:
Program Type: ER
SWIS Code: 2401
Water Body:
Class:
Meets Std: False
Penalty: False
REM Phase: 0
County: Kings
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:

UST Trust: False
Spill Date: 02/27/2023 08:00:00 AM
Received Date: 02/27/2023 08:16:00 AM
CAC Date:
Insp Date:
Close Date: 03/03/2023 12:00:00 AM
Create Date: 02/27/2023 08:18:00 AM
Update Date: 03/03/2023 02:04:42 PM
DEC Region: 2
Lead DEC: HSSEKHON
After Hours: True

Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Contained cleanup pending"

DEC Remark:

"2/27/23 - Sekhon Due to equipment failure 3 gallons of mineral oil spilled onto floor. No drain affected. Spill contained. 3/3/23 - Sekhon Notifier confirmed spill cleaned up, case closed."

Material Information

OP Unit ID:	1395819	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2411581	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	3.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	2630		
Material Name:	mineral oil		

Spiller Information

Spiller Name:	
Spiller Company:	NATIONAL GRID
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	NANCY WAGNER
Contact Phone:	(516) 903-6287
Contact Ext:	
Latitude:	
Longitude:	

77	***172 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***NEWTOWN CREEK WATER POLLUTION CONTROL PLANT*** ***BROOKLYN NY***	***PFAS IND***

Status:	Active	***Fac Fips Code:***	36047
Fac Indian Cntry Flg:	No	***Compliance Status:***	No Violation Identified
Fac Derived Huc:	02030201	***EPA Programs:***	CAA; CWA; RCRA
Fac Derived Wbd:	020301010405	***Federal Facility:***	No
Fac Derived Cd113:	12	***Federal Agency:***	-
Fac Derived Cb2010:	360470579002011	***Fac Snc Flg:***	No
Fac Informal Count:	4	***AIR Flag:***	Yes
Last Informal Action:	4/21/2021	***NPDES Flag:***	Yes
Formal Action Count:	9	***SDWIS Flag:***	No
Last Formal Action:	7/3/2024	***RCRAFlag:***	Yes
Fac Total Penalties:	450000	***TRI Flag:***	No
Fac Penalty Count:	2	***GHG Flag:***	No
Date Last Penalty:	6/8/2021	***TRI IDs:***	-
Last Penalty Amt:	300000	***TRI Releases Trnsfrs:***	-
Fac Qtrs With Nc:	2	***TRI on Site Releases:***	-
Programs With Snc:	0	***TRI off Site Trnsfrs:***	-
Fac Percent Minority:	48.058	***TRI Reporter:***	-
Fac Pop Den:	48299.96	***Fac Imp Water Flg:***	Yes

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Count:	1	**Fac Major Flag:**	Yes
Fac County:	KINGS	**Fac Active Flag:**	Yes
State Other :		**Fac Inspection Count:**	8
Region:	02	**Date Last Inspection:**	9/27/2023
Latitude:	40.73353	**Days Last Inspection:**	360
Longitude:	-73.948378		

Fac Derived Tribes:	-
AIR IDs:	NY0000002610100025
CAA Permit Types:	Major Emissions
CAA NAICS:	221320
CAA SICS:	4952
NPDES IDs:	NY0026204 NY0276570
CWA Permit Types:	Major, Non-M
CWA NAICS:	221320
CWA SICS:	1629 4952 1794
RCRA IDs:	NY0000228049 NYD980779730
RCRA Permit Types:	Other, SQG
RCRA NAICS:	22132
SDWA IDs:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA Snc Flag:	No
Fac Collection Meth:	INTERPOLATION-OTHER
EJSCREEN Flag Us:	No
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.948378,%22y%22:40.73353,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110000561268

Industry: Waste Management

77	173 of175	NE	0.12 / 649.95	9.75 / -2	YARD 329 GREENPOINT AVE BROOKLYN NY	NY SPILLS

Spill No:	2402362	**UST Trust:**	False
Site ID:	668746	**Spill Date:**	06/16/2024 02:00:00 PM
DER Facility ID:	335827	**Received Date:**	06/16/2024 02:23:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	09/13/2024 12:00:00 AM
Water Body:		**Create Date:**	06/16/2024 02:25:00 PM
Class:		**Update Date:**	09/13/2024 10:36:08 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	RHLIN
REM Phase:	0	**After Hours:**	True

County:	Kings
Contributing Factor:	Equipment Failure
Reported by:	Other
Referred to:	
Source:	Commercial/Industrial
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"caller reports appx 50 gals released to containment. clean up pending."

DEC Remark:

"06/17/24-Lin-According to Miller, a compressor leaked oil into a contaminant area at the Newtown Creek Treatment plant. They were hired to pump out the oil in the contaminant area. 9/13/24-Lin-Oil within the contaminant area was pumped out and properly disposed of. Case closed."

Material Information

OP Unit ID:	1415557	**Med Ind Air:**	False
OU:	01	**Med GW:**	False

Material ID:	2433583	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	50.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0015		
Material Name:	motor oil		

OP Unit ID:	1415557	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2433582	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	50.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0015		
Material Name:	motor oil		

Spiller Information

Spiller Name:	NANCY
Spiller Company:	NATIONAL GRID
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	NANCY
Contact Phone:	(516) 522-7857
Contact Ext:	
Latitude:	
Longitude:	

77	***174 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***CRACKED FITTING 329 GREENPOINT AVE BROOKLYN NY***	***NY SPILLS***

Spill No:	2402540	**UST Trust:**	False
Site ID:	668926	**Spill Date:**	06/20/2024 03:20:00 PM
DER Facility ID:	335827	**Received Date:**	06/20/2024 03:39:00 PM
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	2401	**Close Date:**	09/12/2024 12:00:00 AM
Water Body:		**Create Date:**	06/20/2024 03:42:00 PM
Class:		**Update Date:**	09/12/2024 09:43:10 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	HRPATEL
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"clean up - pending"

DEC Remark:

"06/20/24-Hiralkumar Patel. 3:52 PM:- left message for Nancy. 06/25/24-Hiralkumar Patel. 9:06 AM:- left message for Nancy. 09/12/24-Hiralkumar Patel. 9:27 AM:- received report from National Grid. approx. 5-10 gal of oil spilled from cracked fitting into concrete containment. cleanup completed. Rebecca Steffens Nationalgrid PH. (516) 790-3823 email: Rebecca.Steffens@nationalgrid.com case closed."

Material Information

OP Unit ID:	1415735	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2433776	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	10.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	NANCY
Spiller Company:	NATIONAL GRID
Spiller Address:	329 GREENPOINT AVE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	NANCY
Contact Phone:	(516) 532-7857
Contact Ext:	
Latitude:	
Longitude:	

77	***175 of175***	***NE***	***0.12 / 649.95***	***9.75 / -2***	***WASTE WATER TX FACILITY 327 GREENPOINT AVE BROOKLYN NY***	***NY SPILLS***

Spill No:	2404227	***UST Trust:***	False
Site ID:	670656	***Spill Date:***	08/07/2024 11:53:00 AM
DER Facility ID:	594730	***Received Date:***	08/07/2024 11:53:00 AM
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	08/22/2024 12:00:00 AM
Water Body:		***Create Date:***	08/07/2024 11:55:00 AM
Class:		***Update Date:***	09/04/2024 10:05:48 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	VSZHUNE
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"contained"

DEC Remark:

"8/7/24-Zhune spoke to Robert from National Grid. He said leak on equipment. Approximately 1 gallon of mineral oil. It's contained in the dike. Miller Environmental is going to clean de spill. 8/22/24-Robert Bettes from Miller Environmental emailed the report The report stated that oil leaked from valve and mixed with rain water. Spill was contained on the unit. Pads were put down to prevent spreading. Miller cleaned with soap and absorbent pads to

remove oil. All Waste was left onsite. One drum -55 gallon open top metal. Spill volume 2 gallons. Spill Closed. 9/4/24-Zhune-Rebeca Steffens emailed the following email The drum is being picked up by Veolia today and will transported to their facility in Flanders or Middlesex NJ for disposal. I will send you a copy of the manifest once I receive it."

Material Information

OP Unit ID:	1417445	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2435891	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	1.00	***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	2630		
Material Name:	mineral oil		

Spiller Information

Spiller Name:	
Spiller Company:	NAT GRID
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	ROBERT
Contact Phone:	(631) 831-5409
Contact Ext:	
Latitude:	
Longitude:	

78	***1 of4***	***SE***	***0.12 / 657.97***	***10.98 / -1***	***CON ED - MH 4308 JAVA ST & PROVOST ST BROOKLYN NY 11222-0000***	***RCRA NON GEN***

EPA Handler ID:	NYP004008553
Gen Status Universe:	No Report
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	CONSOLIDATED EDISON INC , , NEW YORK , NY, 10003-0000 , US
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	
Receive Date:	19980228
Location Latitude:	40.732078
Location Longitude:	-73.949449
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No

Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19980226
Handler Name:	CON ED - MH 4308
Source Type:	Annual/Biennial Report
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19980227
Handler Name:	CON ED - MH 4308
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	19980228
Handler Name:	CON ED - MH 4308
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Historical Handler Details

Receive Dt:	19980227
Generator Code Description:	Not a Generator, Verified
Handler Name:	CON ED - MH 4308
Receive Dt:	19980226
Generator Code Description:	Large Quantity Generator
Handler Name:	CON ED - MH 4308

78	*2 of4*	*SE*	*0.12 / 657.97*	*10.98 / -1*	***MANHOLE # TM2275 JAVA ST/PROVOST ST BROOKLYN NY***	***NY SPILLS***

Spill No:	0012337	***UST Trust:***	False
Site ID:	168430	***Spill Date:***	02/16/2001 12:00:00 PM
DER Facility ID:	141891	***Received Date:***	02/16/2001 01:18:00 PM
CID:	281	***CAC Date:***	
Program Type:	ER	***Insp Date:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SWIS Code:	2401	**Close Date:**	06/13/2003 12:00:00 AM
Water Body:		**Create Date:**	02/16/2001 12:00:00 AM
Class:	C4	**Update Date:**	06/16/2003 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	KMFOLEY
REM Phase:	0	**After Hours:**	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"ABOVE MATERIAL SPILLED AT ABOVE LOCATION DUE TO BUSHING FAILURE. TRANSFORMER TO BE REPLACED AND SAMPLE HAS BEEN TAKEN. CLEANUP IS PENDING TEST RESULTS. AMOUNT REPORTED AS 1 QUART. CON ED # 135566. NO CALL BACK REQUESTED."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY E2MIS 135566 2-16-01 12:15HRS M. ADAMO (NETWORK) REPORTS, ONE QUART OF TRANSFORMER OIL FOUND ON SLUDGE. NO SEWERS OR WATERWAYS WERE AFFECTED AND NO ACTIVE SMOKE OR FIRE IN STRUCTURE. SPILL WAS NOTICED WHILE REMOVING TRANSFORMER 2275. PRESSURE TESTED UNIT AND DID NOT HOLD PRESSURE. THERE IS A LEAK FROM PRIMARY BUSHING. HISTORICAL RECORDS INDICATE TO BE 10PPM FROM 1985. SEWER CONNECTION FOUND AND UPON CHECKING ENG RECORDS, WAS VERIFIED TO BE SEWERED. ALSO AT THIS TIME LEAK SEEMS TO BE CONTAINED. ENV. STOP TAG # 27979 WAS PLACED AND CAN NOT VERIFY AT THIS TIME IF THERE IS ANY SUMP IN STRUCTURE. NO PRIVATE PROPERTY INVOLVED. ONE LIQUID SAMPLE WAS TAKEN FROM TM 2275. CLEANUP PENDING SAMPLE RESULTS. S.PACE 49874. UPDATE********** 13:10HRS CIG WAS NOTIFIED. S.PACE 49874 Update - Date: Friday, 16 February 2001 8:35pm Lab Sequence Number: 01-01719 -001 SAMPLE TYPE: OIL None <1.00 PPM EQUIPMENT : NBV49730301 TM 2275 UPDATE********** 2-17-01 10:45HRS N. DREVITCH (ENV OPS) REPORTS, DOUBLE WASHED STRUCTURE, REMOVED TAG# 27979. SUMP WAS SEALED WITH CEMENT AND JOB 100%. S.PACE 49874. Update - 2/19/01 - 0745 hrs - Cleanup completed by double washing structure with slix. Solids were removed using diapers and coagulent. Incident is closed. H bertorelli # 54348. UPDATE 1/22/03 RECORDS SHOW TRANSFORMER REPLACED 2/17/01 EV"

Material Information

OP Unit ID:	834233	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	542609	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	1.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0020A		
Material Name:	transformer oil		

Spiller Information

Spiller Name:	
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller City:	NEW YORK
Spiller State:	NY
Spiller Zip:	10003
Spiller Country:	001
Contact Name:	BILL MURPHY
Contact Phone:	(212) 580-6763
Contact Ext:	
Latitude:	40.732093000
Longitude:	-73.949451000

78	3 of4	SE	0.12 / 657.97	10.98 / -1	CON EDISON - TRANSFORMER MANHOLE 2275	RCRA LQG

JAVA ST & PROVOST ST
NEW YORK NY 10017

EPA Handler ID:	NYP004869271
Gen Status Universe:	Large Quantity Generator
Contact Name:	THERESA BURKARD
Contact Address:	4 , IRVING PLACE, 15TH FL NE , , NEW YORK , NY, 10003 , US
Contact Phone No and Ext:	212-460-2262
Contact Email:	BURKARDT@CONED.COM
Contact Country:	US
County Name:	NEW YORK
EPA Region:	02
Land Type:	Private
Receive Date:	20160226
Location Latitude:	40.732083
Location Longitude:	-73.949459
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20160226
Handler Name:	CON EDISON - TRANSFORMER MANHOLE 2275
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator
Source Type:	Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	4
Type:	Private	***Street 1:***	IRVING PLACE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20151113	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003
Owner/Operator Ind:	Current Operator	**Street No:**	4
Type:	Private	**Street 1:**	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20151113	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003

78	4 of4	SE	0.12 / 657.97	10.98 / -1	**CON ED** **JAVA ST & PROVOST ST** **NEW YORK NY 10017**	NY MANIFEST

RCRA ID:	NYP004869271	**Mailing Street 1:**	4 IRVING PL 15TH FL NE
District Name:	CON ED	**Mailing Street 2:**	
Business Phone No:		**Mailing City:**	NEW YORK
Contact Name:	CON ED	**Mailing State:**	NY
Location ZIP Ext:		**Mailing ZIP:**	10003
Location County:	NEW YORK	**Mailing ZIP Ext:**	
Location Country:	USA	**Mailing Country:**	USA

79	1 of1	SE	0.14 / 716.58	11.27 / -1	**SKANSKA PICONE III JV** **252 JAVA ST AKA 259 KENT ST** **BROOKLYN NY 11222**	RCRA NON GEN

EPA Handler ID:	NYR000212837
Gen Status Universe:	No Report
Contact Name:	CHARLES R HEARL
Contact Address:	252 , JAVA ST , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:	718-513-5509
Contact Email:	CHARLES.HEARL@SKANSKA.COM
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20150409
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No

Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20140917
Handler Name:	SKANSKA PICONE III JV
Source Type:	Temporary
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Waste Code Details

Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE
Hazardous Waste Code:	D002
Waste Code Description:	CORROSIVE WASTE
Hazardous Waste Code:	D006
Waste Code Description:	CADMIUM
Hazardous Waste Code:	D007
Waste Code Description:	CHROMIUM
Hazardous Waste Code:	D008
Waste Code Description:	LEAD
Hazardous Waste Code:	D009
Waste Code Description:	MERCURY
Hazardous Waste Code:	F003
Waste Code Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Hazardous Waste Code:	F005
Waste Code Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150409
Handler Name:	SKANSKA PICONE III JV
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	239
Type:	Private	***Street 1:***	JAVA ST
Name:	YEHUDA YALOZ/STEVE GOLDMAN/JAVA ST LLC	***Street 2:***	
Date Became Current:	19990701	***City:***	BROOKLYN
Date Ended Current:		***State:***	NY
Phone:	718-389-1131	***Country:***	US
Source Type:	Implementer	***Zip Code:***	11222

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	SKANSKA PICONE III	***Street 2:***	
Date Became Current:	20090101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Implementer	***Zip Code:***	

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	SKANSKA PICONE III	***Street 2:***	
Date Became Current:	20090101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Temporary	***Zip Code:***	

Owner/Operator Ind:	Current Owner	***Street No:***	239
Type:	Private	***Street 1:***	JAVA ST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Name:	YEHUDA YALOZ/STEVE GOLDMAN/JAVA ST LLC	**Street 2:**	
Date Became Current:	19990701	**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:	718-389-1131	**Country:**	US
Source Type:	Temporary	**Zip Code:**	11222

Historical Handler Details

Receive Dt:	20140917
Generator Code Description:	Large Quantity Generator
Handler Name:	SKANSKA PICONE III JV

80	*1 of1*	*N*	*0.14 / 729.78*	*10.40 / -2*	***CON EDISON SERVICE BOX: 7252 227 EAGLE ST BROOKLYN NY 11222***	***RCRA NON GEN***

EPA Handler ID:	NYP004427720
Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20140228
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20140128
Handler Name:	CON EDISON SERVICE BOX: 7252

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source Type: Emergency
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20140228
Handler Name: CON EDISON SERVICE BOX: 7252
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20140128
Generator Code Description: Very Small Quantity Generator
Handler Name: CON EDISON SERVICE BOX: 7252

81	1 of1	SSE	0.14 / 734.14	12.03 / 0	CON EDISON SERVICE BOX: 8198 237 KENT ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004312948
Gen Status Universe: No Report
Contact Name: T`ARRI SOWELL
Contact Address:
Contact Phone No and Ext: 718-666-4506
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20130614
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without No

Storage:

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20130514
Handler Name:	CON EDISON SERVICE BOX: 8198
Source Type:	Emergency
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20130614
Handler Name:	CON EDISON SERVICE BOX: 8198
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Historical Handler Details

Receive Dt:	20130514
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CON EDISON SERVICE BOX: 8198

---

82 | ***1 of1*** | ***SE*** | ***0.14 / 741.58*** | ***10.82 / -1*** | ***FOX & LONDON INC.***
21 PROVOST ST
BROOKLYN NY 11222 | ***SEMS ARCHIVE***

Site ID:	0206649	***FIPS Code:***	36047
EPA ID:	NYN000206649	***Cong District:***	
Superfund Alte Agr:	No	***Region:***	02
Federal Facility:	No	***County:***	KINGS
FF Docket:	No		
NPL:	Not on the NPL		
Non NPL Status:	Referred to Removal - NFRAP		

Action Information

Operable Units:	00	***Qual:***	
Action Code:	DS	***SEQ:***	1
Action Name:	DISCVRY	***FF:***	No
Start Actual:	12/3/2012 5:00:00 AM	***FF Docket:***	No
Finish Actual:	12/3/2012 5:00:00 AM	***Region:***	02
Curr Action Lead:	EPA Perf		
NPL:			

Operable Units:	00	***Qual:***	
Action Code:	RS	***SEQ:***	1
Action Name:	RV ASSESS	***FF:***	No
Start Actual:	7/17/2014 4:00:00 AM	***FF Docket:***	No
Finish Actual:	7/17/2014 4:00:00 AM	***Region:***	02
Curr Action Lead:	EPA Perf		
NPL:			

Operable Units:	00	***Qual:***	
Action Code:	HX	***SEQ:***	1
Action Name:	PRE-CERC	***FF:***	No
Start Actual:		***FF Docket:***	No
Finish Actual:	12/3/2012 5:00:00 AM	***Region:***	02
Curr Action Lead:	EPA Perf		
NPL:			

Operable Units:	00	**Qual:**	N
Action Code:	PA	**SEQ:**	1
Action Name:	PA	**FF:**	No
Start Actual:	5/10/2013 5:00:00 AM	**FF Docket:**	No
Finish Actual:	6/26/2013 5:00:00 AM	**Region:**	02
Curr Action Lead:	EPA Perf		
NPL:			

83 *1 of2* *SE* *0.14 / 741.69* *10.82 / -1* ***FOX & LONDON INC.***
21 PROVOST ST
BROOKLYN NY 11222 ***CERCLIS***

Site ID:	0206649	**RNPL Status Code:**	N
Site EPA ID:	NYN000206649	**NPL Status:**	Not on the NPL
Site Street Address 2:		**RFED Facility Code:**	N
Site County Name:	KINGS	**RFED Facility Desc:**	Not a Federal Facility
Site FIPS Code:	36047	**USGS Hydro Unit No.:**	
Region Code:	02	**Site Cong. Dist. Code:**	
Site SMSA No.:		**ROT Desc:**	
Site Prim. Latitude:	+40.731461	**FR NPL Update No.:**	
Site Prim. Longitude:	-073.949372	**RFRA Code:**	
Lat Long Source:			

RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	EPA Fund
Act Code ID:	001	**Act Start Date:**	5/10/2013 00:00:00
RAT Code:	PA	**Act Complete Date:**	6/26/2013 00:00:00
RAT Short Name:	PA	**AGT Order No.:**	130
RAT Name:	PRELIMINARY ASSESSMENT	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	P	**SH Lead:**	
SPA Code:	13		

RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	EPA Fund
Act Code ID:	001	**Act Start Date:**	
RAT Code:	DS	**Act Complete Date:**	12/3/2012 00:00:00
RAT Short Name:	DISCVRY	**AGT Order No.:**	10
RAT Name:	DISCOVERY	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:		**SH Lead:**	
SPA Code:	13		

RAT Def: The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	
Act Code ID:		**Act Start Date:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RAT Code:		**Act Complete Date:**	
RAT Short Name:		**AGT Order No.:**	0
RAT Name:		**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:		**SH Seq:**	
RAT Level:		**SH Start Date:**	
RAT DEF OU:		**SH Complete Date:**	
RFBS Code:		**SH Lead:**	
SPA Code:			
RAT Def:			

Site Desc: No description available
.

Site Alias: No alias data available

83	2 of2	SE	0.14 / 741.69	10.82 / -1	FOX & LONDON INC 21 PROVOST AVE BROOKLYN NY 11222-1813	RCRA NON GEN

EPA Handler ID: NYN008010340
Gen Status Universe: No Report
Contact Name:
Contact Address: 21 , PROVOST AVE , , BROOKLYN , NY, 11222-1813 , US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20070101
Location Latitude: 40.731428
Location Longitude: -73.949367
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date: 20020430
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No

Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20020522
Handler Name: FOX & LONDON INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: FOX & LONDON INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: FOX & LONDON INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name:
Date Became Current:
Date Ended Current:
Phone:
Source Type: Implementer
Street No:
Street 1: 21 PROVOST AVE
Street 2:
City: BROOKLYN
State: NY
Country:
Zip Code: 11222-1813

Owner/Operator Ind: Current Operator
Type: Private
Name: NULL
Date Became Current: 20010101
Date Ended Current:
Phone:
Source Type: Implementer
Street No:
Street 1: 21 PROVOST AVE
Street 2:
City: BROOKLYN
State: NY
Country: US
Zip Code: 11222-1813

Owner/Operator Ind: Current Owner
Type: Private
Name: NULL
Date Became Current: 20010101
Date Ended Current:
Phone:
Source Type: Implementer
Street No:
Street 1: 21 PROVOST AVE
Street 2:
City: BROOKLYN
State: NY
Country: US
Zip Code: 11222-1813

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: FOX & LONDON INC

Receive Dt: 20020522

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Generator Code Description: Not a Generator, Verified
Handler Name: FOX & LONDON INC

---

84 | **1 of2** | **S** | **0.14 / 752.66** | **12.92 / 1** | **NORIS METALS**
231 KENT ST
Brooklyn NY 11222 | **UST**

Site ID: 472661
Site Status: Unregulated/Closed
Program No: 2-611917
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Other

Expiry: N/A
County: Kings
UTM X: 588569.31655
UTM Y: 4509460.51702

Tank Information

Prog No: 2-611917
Tank ID: 246211
Tank No: 001
Tank Status: 3
Tank Status Desc: Closed - Removed
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 01/01/1970
Close Date: 07/23/2012
Tk Out of Serv Dt:
Capacity (Gal): 550
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: L00
Code Name: None
Type: Piping Leak Detection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: K00

Code Name: None
Type: Spill Prevention

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Tank Information

Prog No:	2-611917	***UDC Ind:***	1
Tank ID:	246212	***Red Tag Start Date:***	
Tank No:	002	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	01/01/1970	***Next Test:***	
Close Date:	07/23/2012	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	1000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: I00
Code Name: None
Type: Overfill

Equipment: L00
Code Name: None
Type: Piping Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Affiliation Information

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: FRITZ LINDER
Contact Title: VP
Contact Name: FRITZ LINDER JR
Address1: 231 KENT ST
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 383-6478
Phone Ext:
Email:
Fax:

Affiliation Type: 07

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: NORIS METALS
Contact Title:
Contact Name: FRITZ LINDER JR
Address1: 231 KENT ST
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 383-6478
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: FRITZ LINDER
Contact Title:
Contact Name: FRITZ LINDER JR
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 383-6478
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: NORIS METALS
Contact Title:
Contact Name: FRITZ LINDER JR
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 383-6478
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
84	2 of2	S	0.14 / 752.66	12.92 / 1	NORIS METAL 231 KENT ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYR000194705
Gen Status Universe: No Report
Contact Name: FRITZ LINDER
Contact Address: 231 , KENT ST , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext: 718-383-6478
Contact Email: EWEINSTOCK@CARICHINC.COM
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20160610
Location Latitude:
Location Longitude:
Recycler Activity?: NO

Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date: 20130904
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20120620
Handler Name: NORIS METAL
Source Type: Temporary
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20160610
Handler Name: NORIS METAL
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	NORIS METALS	**Street 2:**	
Date Became Current:	19761015	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Implementer	**Zip Code:**	

Owner/Operator Ind:	Current Owner	**Street No:**	231
Type:	Private	**Street 1:**	KEN ST
Name:	NORIS METAL & DISPLAY CASE CO INC	**Street 2:**	
Date Became Current:	19761015	**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:	718-383-6478	**Country:**	US
Source Type:	Implementer	**Zip Code:**	11222

Owner/Operator Ind:	Current Owner	**Street No:**	231
Type:	Private	**Street 1:**	KEN ST
Name:	NORIS METAL & DISPLAY CASE CO INC	**Street 2:**	
Date Became Current:	19761015	**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:	718-383-6478	**Country:**	US
Source Type:	Temporary	**Zip Code:**	11222

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	NORIS METALS	**Street 2:**	
Date Became Current:	19761015	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Temporary	**Zip Code:**	

Historical Handler Details

Receive Dt: 20120620
Generator Code Description: Large Quantity Generator
Handler Name: NORIS METAL

---

85 | ***1 of1*** | ***S*** | ***0.15 / 765.88*** | ***13.32 / 1*** | ***WJZ AUTO REPAIR INC***
262-268 MCGUINNESS BLVD 262 MCGUINNESS BLVD
Brooklyn NY 11222 | ***UST***

Site ID:	14149	**Expiry:**	N/A
Site Status:	Unregulated/Closed	**County:**	Kings
Program No:	2-309931	**UTM X:**	588529.93319
Program Type Code:	PBS	**UTM Y:**	4509431.85376
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Unknown		

Tank Information

Prog No:	2-309931	**UDC Ind:**	1
Tank ID:	24334	**Red Tag Start Date:**	
Tank No:	001	**Red Tag End Date:**	
Tank Status:	4	**Tank Last Test:**	
Tank Status Desc:	Closed - In Place	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1960	**Next Test:**	

Close Date: 11/01/1989
Tk Out of Serv Dt:
Capacity (Gal): 550
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: B00
Code Name: None
Type: Tank External Protection

Tank Information

Prog No: 2-309931
Tank ID: 24335
Tank No: 002

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:

Tank Status:	4	**Tank Last Test:**	
Tank Status Desc:	Closed - In Place	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1960	**Next Test:**	
Close Date:	11/01/1989	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: F00
Code Name: None
Type: Pipe External Protection

Tank Information

Prog No:	2-309931	***UDC Ind:***	1
Tank ID:	24339	***Red Tag Start Date:***	
Tank No:	006	***Red Tag End Date:***	
Tank Status:	4	***Tank Last Test:***	
Tank Status Desc:	Closed - In Place	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	12/01/1960	***Next Test:***	
Close Date:	11/01/1992	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: I00
Code Name: None
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Tank Information

Prog No: 2-309931
Tank ID: 24338
Tank No: 005
Tank Status: 4
Tank Status Desc: Closed - In Place
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 12/01/1960
Close Date: 11/01/1989
Tk Out of Serv Dt:
Capacity (Gal): 550
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Tank Information

Prog No:	2-309931	**UDC Ind:**	1
Tank ID:	24336	**Red Tag Start Date:**	
Tank No:	003	**Red Tag End Date:**	
Tank Status:	4	**Tank Last Test:**	
Tank Status Desc:	Closed - In Place	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1960	**Next Test:**	
Close Date:	11/01/1989	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C00
Code Name: No Piping

Type: Pipe Location

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: I00
Code Name: None
Type: Overfill

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Tank Information

Prog No:	2-309931	***UDC Ind:***	1
Tank ID:	24337	***Red Tag Start Date:***	
Tank No:	004	***Red Tag End Date:***	
Tank Status:	4	***Tank Last Test:***	
Tank Status Desc:	Closed - In Place	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	12/01/1960	***Next Test:***	
Close Date:	11/01/1989	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I00

Code Name: None
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Affiliation Information

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: MARVIN J EDELSON
Contact Title:
Contact Name: MARVIN EDELSON
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 352-5751
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: ZZZ
Company: MARVIN J EDELSON
Contact Title:
Contact Name:
Address1: 163-43 19TH AVE
Address2:
City: WHITESTONE
State: NY
Zip Code: 11357
Country Code: 001
Phone: (718) 352-5751
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: WJZ AUTO REPAIR INC
Contact Title:
Contact Name: WALTER BIENI
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-5820

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: MARVIN J EDELSON
Contact Title:
Contact Name:
Address1: 163-43 19TH AVE
Address2:
City: WHITESTONE
State: NY
Zip Code: 11357
Country Code: 001
Phone: (718) 352-5751
Phone Ext:
Email:
Fax:

86	1 of4	N	0.15 / 786.45	10.03 / -2	WALLCOTE PAINT CO 208 DUPONT ST BROOKLYN NY 11222	RCRA LQG

EPA Handler ID: NYD001289131
Gen Status Universe: Large Quantity Generator
Contact Name: HERBERT WALLENSTEIN
Contact Address:
Contact Phone No and Ext: 718-389-3777
Contact Email: HARCOCOAT@AOL.COM
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20080212
Location Latitude: 40.736177
Location Longitude: -73.951818
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Oct, 2024.

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 20090602
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20090813
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20090618
Enf Disposition Status: ACTION SATISFIED (CASE CLOSED)
Disposition Status Date: 20090818

Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - Pre-transport
Violation Type: 262.C
Violation Determined Date: 20090602
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20090603
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20090618
Enf Disposition Status: ACTION SATISFIED (CASE CLOSED)
Disposition Status Date: 20090818
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: TSD IS-Preparedness and Prevention
Violation Type: 265.C
Violation Determined Date: 20090602
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20090813
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20090618
Enf Disposition Status: ACTION SATISFIED (CASE CLOSED)
Disposition Status Date: 20090818
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: LDR - General
Violation Type: 268.A
Violation Determined Date: 20090602
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20090813

Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20090618
Enf Disposition Status: ACTION SATISFIED (CASE CLOSED)
Disposition Status Date: 20090818
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: State Statute or Regulation
Violation Type: XXS
Violation Determined Date: 20090602
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20090603
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20090618
Enf Disposition Status: ACTION SATISFIED (CASE CLOSED)
Disposition Status Date: 20090818
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 20120222
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 20090602
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description: Generators - Pre-transport
Return to Compliance Date: 20090603
Evaluation Agency: State

Evaluation Start Date: 20090602
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description: LDR - General
Return to Compliance Date: 20090813
Evaluation Agency: State

Evaluation Start Date: 20090602
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description: TSD IS-Preparedness and Prevention
Return to Compliance Date: 20090813
Evaluation Agency: State

Evaluation Start Date: 20090602
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description: State Statute or Regulation
Return to Compliance Date: 20090603
Evaluation Agency: State

Evaluation Start Date: 20090602
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description: Generators - General
Return to Compliance Date: 20090813
Evaluation Agency: State

Evaluation Start Date: 19970709
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19890314
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19860610
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19800801
Handler Name: HARCO CHEMICAL COATING INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: K078
Waste Code Description: DESCRIPTION

Hazardous Waste Code: K079
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19970808
Handler Name: HARCO CHEMICAL COATING INC
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20051011
Handler Name: HARCO CHEMICAL COATING
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: HARCO CHEMICAL COATING
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: HARCO CHEMICAL COATING
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20080212
Handler Name: WALLCOTE PAINT CO
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	HARCO CHEMICAL COATINGS	**Street 2:**	
Dt Became Current:	19630901	**City:**	
Dt Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	

Owner/Operator Ind:	Current Owner	**Street No:**	208
Type:	Private	**Street 1:**	DUPONT STREET
Name:	EAGLE STREET REALTY CORPORATION	**Street 2:**	
Dt Became Current:	19730416	**City:**	BROOKLYN
Dt Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	11222

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	HARCO CHEMICAL COATINGS	**Street 2:**	
Dt Became Current:		**City:**	NOT REQUIRED
Dt Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	99999

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	
Name:	NO NAME FOUND	**Street 2:**	
Dt Became Current:	19630901	**City:**	
Dt Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Implementer	**Zip Code:**	

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	NO NAME FOUND	**Street 2:**	
Dt Became Current:	19630901	**City:**	
Dt Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Implementer	**Zip Code:**	

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	WALLCOTE PAINT COMPANY	**Street 2:**	
Dt Became Current:	20070626	**City:**	
Dt Ended Current:		**State:**	
Phone:		**Country:**	
Source Type:	Annual/Biennial Report	**Zip Code:**	

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	
Name:	EAGLE STREET REALTY	**Street 2:**	
Dt Became Current:	19630901	**City:**	
Dt Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	

Historical Handler Details

Receive Dt:	20070101
Generator Code Description:	Small Quantity Generator
Handler Name:	HARCO CHEMICAL COATING

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	HARCO CHEMICAL COATING

Receive Dt:	20051011
Generator Code Description:	Very Small Quantity Generator

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Handler Name: HARCO CHEMICAL COATING

Receive Dt: 19970808
Generator Code Description: Not a Generator, Verified
Handler Name: HARCO CHEMICAL COATING INC

Receive Dt: 19800801
Generator Code Description: Large Quantity Generator
Handler Name: HARCO CHEMICAL COATING INC

---

86 | **2 of4** | **N** | **0.15 / 786.45** | **10.03 / -2** | **HARCO CHEMICAL COATINGS**
208 DUPONT STREET
Brooklyn NY 11222 | **UST**

Site ID: 25581
Site Status: Unregulated/Closed
Program No: 2-603674
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Unknown

Expiry: N/A
County: Kings
UTM X: 588566.06593
UTM Y: 4509999.47159

Tank Information

Prog No: 2-603674
Tank ID: 55160
Tank No: 00004
Tank Status: 4
Tank Status Desc: Closed - In Place
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date:
Close Date: 10/01/1998
Tk Out of Serv Dt:
Capacity (Gal): 3000
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: I00
Code Name: None

Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Affiliation Information

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: HARCO CHEMICAL COATINGS
Contact Title:
Contact Name: HERBERT WALLENSTEIN
Address1: 208 DUPONT STREET
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 389-3777
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: HARCO CHEMICAL COATINGS
Contact Title:
Contact Name: HERBERT WALLENSTEIN
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-3777
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: HERCO CHEMICAL COATINGS
Contact Title:
Contact Name: HERBERT WALLENSTEIN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-3777
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: HERCO CHEMICAL COATINGS
Contact Title:
Contact Name:
Address1: 208 DUPONT STREET
Address2:
City: KINGS
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 389-3777
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
86	3 of4	N	0.15 / 786.45	10.03 / -2	HARCO CHEMICAL COATINGS 208 DUPONT ST Brooklyn NY 11222	UST

Site ID: 340012
Site Status: Unregulated/Closed
Program No: 2-000010
Program Type Code: CBS
Program Type Desc: Chemical Bulk Storage
Site Type: Manufacturing (Other than Chemical)/Processing

Expiry: N/A
County: Kings
UTM X: 588566.06593
UTM Y: 4509999.47159

Tank Information

Prog No: 2-000010
Tank ID: 182712
Tank No: 00001
Tank Status: 4
Tank Status Desc: Closed - In Place
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 12/01/1960
Close Date: 10/01/1998
Tk Out of Serv Dt:
Capacity (Gal): 5000
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
86	4 of4	N	0.15 / 786.45	10.03 / -2	HARCO CHEMICAL COATINGS 208 DUPONT ST Brooklyn NY 11222	AST

Site ID: 340012
Site Status: Unregulated/Closed
Program No: 2-000010
Program Type Code: CBS
Program Type Desc: Chemical Bulk Storage
Site Type: Manufacturing (Other than Chemical)/Processing
Expiry: N/A
County: Kings
UTM X: 588566.06593
UTM Y: 4509999.47159

Tank Information

Prog No: 2-000010
Tank ID: 191314
Tank No: 5
Tank Status: 5
Tank Status Desc: Tank Converted to Non-Regulated Use
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 09/01/1984
Close Date:
Tk Out of Serv Dt:
Capacity (Gal): 2500
Registered: True
Tank Model:
Pipe Model:
Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:
UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Class A Operator:
Class B Operator:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Tank Information

Prog No: 2-000010
Tank ID: 191315
Tank No: 6
Tank Status: 5
Tank Status Desc: Tank Converted to Non-Regulated Use
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 09/01/1984
Close Date:
Tk Out of Serv Dt:
Capacity (Gal): 2500
Registered: True
Tank Model:
Pipe Model:
Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:
UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Class A Operator:
Class B Operator:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
87	1 of1	SSW	0.15 / 804.84	15.68 / 4	CON EDISON 209 KENT ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004790705

Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20150605
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150605
Handler Name:	CON EDISON
Source Type:	Emergency
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150605
Handler Name:	CON EDISON
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Historical Handler Details

Receive Dt:	20150605
Generator Code Description:	Small Quantity Generator

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Handler Name:		CON EDISON				
88	1 of1	NW	0.15 / 806.77	9.66 / -2	CON EDISON 185 EAGLE ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004758488
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20150326
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150326
Handler Name: CON EDISON
Source Type: Emergency
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150326
Handler Name: CON EDISON
Source Type: Implementer

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20150326
Generator Code Description: Large Quantity Generator
Handler Name: CON EDISON

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
89	1 of2	W	0.15 / 812.54	13.99 / 2	996 MANHATTAN AVENUE 996 MANHATTAN AVENUE NEW YORK NY 11222	UST

Site ID: 612620
Site Status: Unregulated/Closed
Program No: 2-613197
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Auto Service/Repair (No Gasoline Sales)

Expiry: N/A
County: New York
UTM X:
UTM Y:

Tank Information

Prog No: 2-613197
Tank ID: 287736
Tank No: 001
Tank Status: 3
Tank Status Desc: Closed - Removed
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date:
Close Date: 01/14/2020
Tk Out of Serv Dt:
Capacity (Gal): 550
Registered: True
Tank Model:
Pipe Model:

UDC Ind: 0
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: -
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method: -
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 3
Subpart Desc: Subpart 3 contains requirements for USTs subject to just DEC requirements (primary example is tanks storing heating oil for on-premises consumption).
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: L00
Code Name: None
Type: Piping Leak Detection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Affiliation Information

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: BHLD 996 MANHATTAN AVENUE LLC
Contact Title:
Contact Name: LEE COHEN
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (917) 613-9411
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: 996 MANHATTAN AVENUE
Contact Title:
Contact Name: LEE COHEN
Address1:
Address2:
City:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

State: NN
Zip Code:
Country Code: 001
Phone:
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: BHLD 996 MANHATTAN AVENUE LLC
Contact Title: MANAGING MEMBER
Contact Name: LEE COHEN
Address1: C/0: BHLD CAPITAL, 81 PROSPECT PLACE, SUITE 9063
Address2:
City: NEW YORK
State: NY
Zip Code: 11217
Country Code: 001
Phone: (917) 61 3-9411
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: BHLD 996 MANHATTAN AVENUE LLC
Contact Title:
Contact Name: LEE COHEN
Address1: 81 PROSPECT PLACE, SUITE 9063
Address2:
City: BROOKLYN
State: NY
Zip Code: 11217
Country Code: 001
Phone: (917) 613-9411
Phone Ext:
Email: LEE@BHLDCAPITAL.COM
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
89	2 of2	W	0.15 / 812.54	13.99 / 2	996 Manhattan Avenue 996 Manhattan Avenue Brooklyn NY	OER CLEANUP

Class: Completed (C)
Phase: Completed
BIN: 3025230001
Postcode: 1
Community Board: 33
BBL: 3025230001
OER Program: VCP (Enrolled), E/RD (Review)
NTA: Greenpoint
Project Docs URL: https://a002-epic.nyc.gov/app/workspace/2404/docrepository

Council District: 575
Census Tract: 3064170
Latitude: 40.733139
Longitude: -73.954735

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
90	1 of1	NNE	0.15 / 814.69	9.71 / -2	POLYSTYRENE RECYCLING; INC. 220 DUPONT STREET Brooklyn NY 11222	SWF/LF

Activity Number: [24M83]
Facility Name (Act):
Location Addr (Act):
Location Addr2 (Act):
City (Act):
State (Act):

Facility Name (InAct): POLYSTYRENE RECYCLING; INC.
Location Addr (InAct): 220 DUPONT STREET
Loc Addr2(InAct):
City (InAct): Brooklyn
State (InAct): NY
Zip Code (InAct): 11222

Zip Code (Act):		***County (InAct):***	Kings
County (Act):		***East Coord (InAct):***	588600
East Coord (Act):		***North Coord (InAct):***	4509900
North Coord (Act):			
Facility Name:			
Location Addr:			
Location Addr2:			
City:			
State:			
Zip Code:			
County:			
East Coord:			
North Coord:			
Data Source:	SWMF - Inactive Facility Lists		

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		***Authorization No:***	2-6101-00024
Activity Desc:	RHRF - registration	***Authrzation Issue Dt:***	
Regulatory Status:	Permit	***Operator Type:***	
Active:	No	***Operator Name:***	
Dt of Last Inspection:		***Phone No:***	2125862717
Expiration Dt:		***Region:***	2
Owner Type:		***Contact Name:***	CHRIS MCGRATH
Owner Name:		***Contact Address:***	
Owner Address:		***Contact Address2:***	
Owner Address2:		***Contact City:***	
Owner City:		***Contact State:***	
Owner State:		***Contact Zip:***	
Owner Zip:		***Contact Phone:***	
Owner Phone:		***Contact Email:***	
Owner Email:			
Waste Types:			

---

91 | ***1 of1*** | ***SE*** | ***0.16 / 824.03*** | ***10.36 / -2*** | ***CONSOLIDATED SMELTING
25 PROVOST AVE
BROOKLYN NY 11222-1813*** | ***RCRA NON GEN***

EPA Handler ID:	NYN008010332
Gen Status Universe:	No Report
Contact Name:	
Contact Address:	25 , PROVOST AVE , , BROOKLYN , NY, 11222-1813 , US
Contact Phone No and Ext:	
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20070101
Location Latitude:	40.731565
Location Longitude:	-73.949389
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date:	20020430
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Violation Short Description:	
Return to Compliance Date:	

Evaluation Agency: EPA

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20020522
Handler Name:	CONSOLIDATED SMELTING
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20060101
Handler Name:	CONSOLIDATED SMELTING
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	3
Receive Date:	20070101
Handler Name:	CONSOLIDATED SMELTING
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	25 PROVOST AVE
Name:	CONSOLIDATED SMELTING	***Street 2:***	
Date Became Current:	20010101	***City:***	BROOKLYN
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Implementer	***Zip Code:***	11222-1813
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	25 PROVOST AVE
Name:	CONSOLIDATED SMELTING	***Street 2:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Date Became Current:		**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:		**Country:**	
Source Type:	Implementer	**Zip Code:**	11222-1813
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	25 PROVOST AVE
Name:	CONSOLIDATED SMELTING	**Street 2:**	
Date Became Current:	20010101	**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Implementer	**Zip Code:**	11222-1813

Historical Handler Details

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	CONSOLIDATED SMELTING
Receive Dt:	20020522
Generator Code Description:	Not a Generator, Verified
Handler Name:	CONSOLIDATED SMELTING

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
92	1 of1	WSW	0.16 / 832.22	17.02 / 5	982 MANHATTAN AVE 982 MANHATTAN AVENUE Brooklyn NY 11222	AST

Site ID:	30834	**Expiry:**	N/A
Site Status:	Unregulated/Closed	**County:**	Kings
Program No:	2-608987	**UTM X:**	588282.21204
Program Type Code:	PBS	**UTM Y:**	4509606.86766
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Apartment Building/Office Building		

Tank Information

Prog No:	2-608987	**UDC Ind:**	1
Tank ID:	66090	**Red Tag Start Date:**	
Tank No:	2	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	06/15/1975	**Next Line Test Due:**	
Close Date:	10/19/2009	**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	2000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	3		
Tank Location Desc:	Aboveground on saddles, legs, stilts, rack or cradle		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Tank Owner Name:			
Tank Owner Address:			

Material Information

Material Name:	#2 fuel oil (on-site consumption)
Percent:	100.00

Equipment Information

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: H06
Code Name: Impervious Barrier/Concrete Pad (A/G)
Type: Tank Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: F06
Code Name: Wrapped
Type: Pipe External Protection

Equipment: B05
Code Name: Jacketed
Type: Tank External Protection

Equipment: I05
Code Name: Vent Whistle
Type: Overfill

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Affiliation Information

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: HERCULES
Contact Title:
Contact Name: PETER KOSTAKOPOULOS
Address1: 900 MEEKER AVENUE
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 599-1717
Phone Ext:
Email: MAIN@HERCULESBOILERS.COM
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: PEETER KOSTAKOPOULOS
Contact Title:
Contact Name: PETER KOSTAKOPOULOS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 599-1717
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: 982 MANHATTAN AVE
Contact Title:
Contact Name: RICARDO OSVALDO
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 383-5434
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: PEETER KOSTAKOPOULOS
Contact Title: OWNER
Contact Name: PETER KOSTAKOPOULOS
Address1: 900 MEEKER AVE
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 599-1717
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
93	1 of1	NNW	0.16 / 839.56	8.53 / -3	CON EDISON SERVICE BOX: 8381 382 MCGUINESS BLVD BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004389508
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20131212
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20131112
Handler Name:	CON EDISON SERVICE BOX: 8381
Source Type:	Emergency
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20131212
Handler Name:	CON EDISON SERVICE BOX: 8381
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Historical Handler Details

Receive Dt:	20131112
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CON EDISON SERVICE BOX: 8381

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
94	1 of1	WNW	0.16 / 841.11	13.92 / 2	CON EDISON SERVICE BOX: 8461 183 FREEMAN ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID:	NYP004443081
Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20140316

Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20140216
Handler Name: CON EDISON SERVICE BOX: 8461
Source Type: Emergency
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20140316
Handler Name: CON EDISON SERVICE BOX: 8461
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20140216
Generator Code Description: Very Small Quantity Generator
Handler Name: CON EDISON SERVICE BOX: 8461

95	*1 of1*	*W*	*0.16 / 853.83*	*14.03 / 2*	***1026-1030 MANHATTAN AVENUE*** ***1026-1030 MANHATTAN AVENUE*** ***Brooklyn NY***	***OER CLEANUP***

Class: Active (A)
Phase: Closure
BIN: 3025130003
Council District: 575
Census Tract: 3064050
Latitude: 40.733982

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Postcode: 1 **Longitude:** -73.954871
Community Board: 33
BBL: 3025130004,3025130003,3025130002
OER Program: E/RD (Review)
NTA: Greenpoint
Project Docs URL: https://a002-epic.nyc.gov/app/workspace/4939/docrepository

---

96	1 of1	NW	0.16 / 854.90	11.26 / -1	CON EDISON 177 EAGLE ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004809731
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20150720
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150720
Handler Name: CON EDISON
Source Type: Emergency
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150720
Handler Name:	CON EDISON
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Historical Handler Details

Receive Dt:	20150720
Generator Code Description:	Small Quantity Generator
Handler Name:	CON EDISON

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
97	1 of1	W	0.16 / 856.30	14.04 / 2	1036 Manhattan Ave BCP Site 1032 and 1036-1038 Manhattan Avenue Brooklyn NY 11222	BROWNFIELDS

Site Code:	615119
HW Code:	C224315
Program:	BCP
Site Class:	A
Site Name:	1036 Manhattan Ave BCP Site
Site Address:	1032 and 1036-1038 Manhattan Avenue
City:	Brooklyn
Zip:	11222
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.734277778
Longitude:	-73.954597222
SWIS:	2401
Acres:	0.229
Record Added:	2020-12-18 15:13:00
Record Update:	2021-06-30 09:59:00
Updated by:	JHOCONNE
Site Code (Web):	C224315
Program Type (Web):	BCP
Site Name (Web):	1036 Manhattan Ave BCP Site
Site Class (Web):	A
Address1 (Web):	170 Freeman Street
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.954597222
Latitude (Web):	40.734277778
Site Code (GIS):	C224315
Site Name (GIS):	1036 Manhattan Ave BCP Site
Program (GIS):	BCP
Site Class (GIS):	A
Address1 (GIS):	1032 and 1036-1038 Manhattan Avenue
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Site Class Desc (Web):	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Assess DOH:	Information submitted with the BCP application regarding the conditions at the site are currently under review and

will be revised as additional information becomes available.

Description:

Location- The 1036 Manhattan Avenue BCP site is located in a commercial and residential area of the Greenpoint section of the Borough of Brooklyn. The site is bound to the north by Freeman Street and to the west by Manhattan Avenue, and by multi-family and mixed-use buildings to the east and south, respectively. Site Features- The site is currently vacant; site buildings have been demolished in preparation for redevelopment. The building foundations remain with building rubble occupying portions of the former building basements. The site is comprised of three complete tax parcels as noted above totaling 10,000 square feet. Current Zoning and Land Use- The site is currently zoned R7A (medium density residential apartments) with a C2-4 (commercial zone) overlay. The current land use at the site is as vacant properties. Surrounding properties along Manhattan Avenue are zoned with the same R7A/C2-4 designation of mixed-use commercial/residential. Surrounding properties to the east along Freeman Street and George Apen Street (also known as Green Street) are generally zoned as R6B residential. Past Use of the Site- The primary past use of the site that led to site contamination is a dry cleaner that operated from approximately 1965 to 1985. A portion of the site was labeled as "Paints" from 1951 to 2007 and may have additionally contributed to site contamination. The site was listed as an "E" designated site for hazardous materials and noise during the Greenpoint-Williamsburg Contextual Rezoning Action completed by New York City in July 2009 (CEQR No. 09CDP056K). Site Geology and Hydrogeology- The shallow subsurface of the site consists of a layer of dry silty sand with fill material from the surface to 12.5 feet below grade. Moist silty clay is then present from 12.5 to 14 feet below grade with wet fine-grained sand beneath 14 feet. Mapped native soils within the vicinity of the site are characterized as glacial till of variable texture and relatively impermeable. Bedrock was not encountered at the site in previous investigations. Groundwater at the site is located approximately 12.6 to 14.5 feet below grade. Groundwater flow is north-northeast towards Newtown Creek and the East River. No wetlands or surface water bodies are present at the site. The nearest surface water body is the Newtown Creek, located approximately 1,800 feet to the north.

Assessment:

Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), pesticides, poly-chlorinated biphenyls (PCBs), and metals. Soil vapor was analyzed for VOCs. Soil – Several SVOCs were detected in shallow soil 0-4 feet below grade surface (bgs) above the Protection of Groundwater soil cleanup objectives (PGSCO) and Restricted Residential SCO (RRSCO) on Lot 6 and Lot 8. Benzo(a)anthracene was detected at a maximum concentration of 20.6 parts per million, or ppm (RRSCO value of 1 ppm), benzo(a) fluoranthene was detected at a maximum concentration of 17.3 ppm (PGSCO value of 1.7 ppm and RRSCO value of 1 ppm), benzo(k)fluoranthene maximum concentration of 14.7 ppm (RRSCO value of 1 ppm and PGSCO value of 1.7 ppm), chrysene was detected at a maximum concentration of 19.1 ppm (RRSCO and PGSCO value of 1 ppm), and indeno(1,2,3-cd)pyrene maximum concentration of 10.5 ppm (RRSCO value of 0.5 ppm and PGSCO value of 8.2 ppm). Metals such as zinc was detected at a maximum concentration of 2,740 ppm (PGSCO value of 2,480 ppm and RRSCO value of 2,220 ppm), mercury was detected at a maximum concentration of 1.33 ppm (PGSCO value of 0.73 ppm and RRSCO value of 0.81 ppm), arsenic was detected at a maximum concentration of 16.4 ppm (PGSCO and RRSCO value of 16 ppm), and lead was detected at a maximum concentration of 734 ppm (PGSCO value of 450 ppm and RRSCO value of 400 ppm). Groundwater - Several chlorinated VOCs were detected in 4 monitoring wells. Trichloroethene (TCE) was detected at a maximum concentration of 13 parts per billion (ppb) exceeding Ambient Water Quality Standards (AWQS) of 5 ppb. Tetrachloroethene (PCE) was detected at a maximum concentration of 24 ppb (AWQS of 5 ppb). Cis-1,2-Dichloroethene (1,2- DCE) was detected at a maximum concentration of 8,000 ppb (AWQS of 5 ppb). Vinyl chloride was detected at a maximum concentration of 15 ppb (AWQS of 2 ppb). Several SVOCs were detected including benzo(a)anthracene and benzo(b)fluoranthene at a maximum concentration of 1.72 ppb and 1.76 ppb respectively (AWQS value of 0.002 ppb). Soil Vapor - Several chlorinated VOCs were detected in soil vapor and indoor air samples in Lot 8. Cis-1,2-Dichloroethene (1,2- DCE) was detected in sub-slab soil vapor samples at a maximum concentration of 150,000 micrograms per cubic meter (ug/m3) and in indoor air samples at a maximum concentration of 0.79 ug/m3. Vinyl chloride was detected in sub-slab soil vapor samples at a maximum concentration of 510 ug/m3.Trichloroethene (TCE) was detected in sub-slab soil vapor samples at a maximum concentration of 250 ug/m3 and in indoor air samples at a maximum concentration of 0.19 ug/m3. Tetrachloroethene (PCE) was detected in sub-slab soil vapor samples at a maximum concentration of 94 ug/m3 and in indoor air samples at a maximum concentration of 2.6 ug/m3. Carbon tetrachloride was detected at a concentration of 0.44 ug/m3 in one ambient air sample.

Owner Information

Owner Op:	01
Sub Type:	NNN
Owner Name:	Joshua Greenberg
Owner Company:	170 Freeman LLC
Owner Street:	4 Harbor Drive
Owner Street 2:	
Owner City:	Port Chester
Owner State:	NY
Owner Zip:	10573
Country:	United States of America

Owner Op:	19
Sub Type:	NNN
Owner Name:	
Owner Company:	Brooklyn Community Board No. 1
Owner Street:	435 Graham Avenue
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11211

Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Brooklyn Public Library - Greenpoint Branch
Owner Street: 107 Norman Avenue at Leonard Street
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 06
Sub Type: P02
Owner Name: Joshua Greenberg
Owner Company: 170 Freeman LLC
Owner Street: 228 Park Avenue South PMB 53318
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10003
Country: United States of America

Owner Op: 06
Sub Type: P02
Owner Name: Marshall Kesten
Owner Company: BK Corners LLC
Owner Street: 49 Box Street
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: GWBURKE
Record Added: 2021-03-22 11:34:00
Record Updated: 2021-03-22 11:34:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Projects Information

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2022-05-26 00:00:00
End Status: ACT
Operable Unit ID: 1378488
Operable Unit: 01A
Operable Unit Desc: IRM- On-site
Code Name: Remedial Design

Environmental Remediation

Operable Unit: 01
Contaminants:

Operable Unit: 00
Contaminants:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Operable Unit:		01A				
Contaminants:						

98	1 of1	WNW	0.16 / 862.19	14.01 / 2	**CON EDISON SERVICE BOX: 08458** **181 FREEMAN ST** **BROOKLYN NY 11222**	**RCRA NON GEN**

EPA Handler ID: NYP004443073
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20140316
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20140216
Handler Name: CON EDISON SERVICE BOX: 08458
Source Type: Emergency
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20140316

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Handler Name: CON EDISON SERVICE BOX: 08458
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20140216
Generator Code Description: Very Small Quantity Generator
Handler Name: CON EDISON SERVICE BOX: 08458

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
99	1 of1	W	0.16 / 864.41	14.00 / 2	KELLY CLEANERS 1036 MANHATTAN AVE BROOKLYN NY 11222-1316	RCRA NON GEN

EPA Handler ID: NYD049146186
Gen Status Universe: No Report
Contact Name:
Contact Address: 1036 , MANHATTAN AVE , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 40.734238
Location Longitude: -73.954898
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19850311
Handler Name: KELLY CLEANERS
Source Type: Notification

Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990708
Handler Name: KELLY CLEANERS
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: KELLY CLEANERS
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: KELLY CLEANERS
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: OWNERNAME
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: OWNERNAME
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: OWNERNAME
Date Became Current:
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	99999

Historical Handler Details

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	KELLY CLEANERS
Receive Dt:	19990708
Generator Code Description:	Not a Generator, Verified
Handler Name:	KELLY CLEANERS
Receive Dt:	19850311
Generator Code Description:	Large Quantity Generator
Handler Name:	KELLY CLEANERS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
100	1 of1	NNW	0.17 / 879.82	9.02 / -3	AMSCOR INC 188 DUPONT ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID:	NYD986909612
Gen Status Universe:	No Report
Contact Name:	SCOTT B SILBERGLIED
Contact Address:	PO BOX 262 , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:	718-383-4900
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	
Receive Date:	20070101
Location Latitude:	40.736145
Location Longitude:	-73.952182
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19900809
Handler Name: AMSCOR INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Code: F001
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20020222
Handler Name: AMSCOR INC
Source Type: Annual/Biennial Report
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060101
Handler Name: AMSCOR INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: AMSCOR INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: AMSCOR INC
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: AMSCOR INC
Date Became Current:
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED

Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	AMSCOR INC	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	99999

Historical Handler Details

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	AMSCOR INC
Receive Dt:	20020222
Generator Code Description:	Large Quantity Generator
Handler Name:	AMSCOR INC
Receive Dt:	19900809
Generator Code Description:	Very Small Quantity Generator
Handler Name:	AMSCOR INC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
101	1 of1	SSW	0.17 / 893.32	15.04 / 3	CON EDISON 210 KENT ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID:	NYP004798203
Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20150623
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No

Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150623
Handler Name:	CON EDISON
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150623
Handler Name:	CON EDISON
Source Type:	Emergency
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Historical Handler Details

Receive Dt:	20150623
Generator Code Description:	Small Quantity Generator
Handler Name:	CON EDISON

---

102 | ***1 of1*** | ***NNW*** | ***0.17 / 900.12*** | ***9.05 / -3*** | ***AMSCOR CORPORATION - 188 DUPONT STREET BROOKLYN NY*** | ***PFAS IND***

Status:	Active	**Fac Fips Code:**	36047
Fac Indian Cntry Flg:	No	**Compliance Status:**	No Violation Identified
Fac Derived Huc:	02030201	**EPA Programs:**	CAA; RCRA
Fac Derived Wbd:	020301010405	**Federal Facility:**	No
Fac Derived Cd113:	12	**Federal Agency:**	-
Fac Derived Cb2010:	360470579002012	**Fac Snc Flg:**	No
Fac Informal Count:	0	**AIR Flag:**	Yes
Last Informal Action:	5/13/1992	**NPDES Flag:**	No
Formal Action Count:	0	**SDWIS Flag:**	No
Last Formal Action:	-	**RCRAFlag:**	Yes
Fac Total Penalties:	0	**TRI Flag:**	No
Fac Penalty Count:	-	**GHG Flag:**	No
Date Last Penalty:	-	**TRI IDs:**	-
Last Penalty Amt:	-	**TRI Releases Trnsfrs:**	-
Fac Qtrs With Nc:	0	**TRI on Site Releases:**	-
Programs With Snc:	0	**TRI off Site Trnsfrs:**	-
Fac Percent Minority:	45.164	**TRI Reporter:**	-
Fac Pop Den:	49060.41	**Fac Imp Water Flg:**	-
Count:	1	**Fac Major Flag:**	-
Fac County:	KINGS	**Fac Active Flag:**	Yes
State Other :		**Fac Inspection Count:**	0
Region:	02	**Date Last Inspection:**	-
Latitude:	40.73616	**Days Last Inspection:**	-
Longitude:	-73.95187		
Fac Derived Tribes:	-		
AIR IDs:	NY0000002610100210		
CAA Permit Types:	Synthetic Minor Emissions		
CAA NAICS:	999999		
CAA SICS:	3479 3499		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

NPDES IDs:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDs:	NYD986909612
RCRA Permit Types:	Other
RCRA NAICS:	56291
SDWA IDs:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA Snc Flag:	No
Fac Collection Meth:	ADDRESS MATCHING-HOUSE NUMBER
EJSCREEN Flag Us:	Yes
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.95187,%22y%22:40.73616,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110012392295
Industry:	Metal Coating

103	1 of1	N	0.17 / 903.43	9.73 / -2	HARCO CHEMICAL COATINGS INC BROOKLYN NY	PFAS IND

Status:	Active	**Fac Fips Code:**	36047
Fac Indian Cntry Flg:	No	**Compliance Status:**	No Violation Identified
Fac Derived Huc:	02030201	**EPA Programs:**	RCRA
Fac Derived Wbd:	020301010405	**Federal Facility:**	No
Fac Derived Cd113:	12	**Federal Agency:**	-
Fac Derived Cb2010:	360470579002012	**Fac Snc Flg:**	No
Fac Informal Count:	0	**AIR Flag:**	No
Last Informal Action:	6/18/2009	**NPDES Flag:**	No
Formal Action Count:	0	**SDWIS Flag:**	No
Last Formal Action:	-	**RCRAFlag:**	Yes
Fac Total Penalties:	0	**TRI Flag:**	No
Fac Penalty Count:	-	**GHG Flag:**	No
Date Last Penalty:	-	**TRI IDs:**	11222HRLCH208DU
Last Penalty Amt:	-	**TRI Releases Trnsfrs:**	-
Fac Qtrs With Nc:	0	**TRI on Site Releases:**	-
Programs With Snc:	0	**TRI off Site Trnsfrs:**	-
Fac Percent Minority:	45.281	**TRI Reporter:**	-
Fac Pop Den:	48991.18	**Fac Imp Water Flg:**	-
Count:	1	**Fac Major Flag:**	-
Fac County:	KINGS	**Fac Active Flag:**	Yes
State Other :		**Fac Inspection Count:**	0
Region:	02	**Date Last Inspection:**	2/22/2012
Latitude:	40.73623	**Days Last Inspection:**	4595
Longitude:	-73.95111		

Fac Derived Tribes:	-
AIR IDs:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDs:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDs:	NYD001289131
RCRA Permit Types:	LQG
RCRA NAICS:	32551
SDWA IDs:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA Snc Flag:	No
Fac Collection Meth:	ADDRESS MATCHING-HOUSE NUMBER
EJSCREEN Flag Us:	Yes
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.95111,%22y%22:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

40.73623,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

ECHO Facility Report: https://echo.epa.gov/detailed-facility-report?fid=110000323374

Industry: Paints and Coatings

---

104 | ***1 of1*** | ***W*** | ***0.17 / 910.86*** | ***14.68 / 3*** | ***MTA NYCT GREEN STREET SUBSTATION***
GREEN ST & MANHATTAN AVE
BROOKLYN NY 11222 | ***RCRA LQG***

EPA Handler ID: NYR000076620
Gen Status Universe: Large Quantity Generator
Contact Name: HOWARD MATZA
Contact Address: 370 , JAY ST ROOM 819 , , BROOKLYN , NY, 11201 , US
Contact Phone No and Ext: 718-243-4581
Contact Email:
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 40.733724
Location Longitude: -73.954833
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990920
Handler Name: MTA NYCT GREEN STREET SUBSTATION
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060101
Handler Name: MTA NYCT GREEN STREET SUBSTATION
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: MTA NYCT GREEN STREET SUBSTATION
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Municipal
Name: MTA NEW YORK CITY TRANSIT
Dt Became Current:
Dt Ended Current:
Phone: 718-243-4581
Source Type: Notification
Street No:
Street 1: 370 JAY ST ROOM 819
Street 2:
City: BROOKLY
State: NY
Country:
Zip Code: 11201

Owner/Operator Ind: Current Owner
Type: Municipal
Name: MTA NEW YORK CITY TRANSIT
Dt Became Current:
Dt Ended Current:
Phone: 718-243-4581
Source Type: Implementer
Street No:
Street 1: 370 JAY ST ROOM 819
Street 2:
City: BROOKLY
State: NY
Country: US
Zip Code: 11201

Owner/Operator Ind: Current Operator
Type: Municipal
Name: MTA NEW YORK CITY TRANSIT
Dt Became Current:
Dt Ended Current:
Phone: 718-243-4581
Source Type: Implementer
Street No:
Street 1: 370 JAY ST ROOM 819
Street 2:
City: BROOKLY
State: NY
Country: US
Zip Code: 11201

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: MTA NYCT GREEN STREET SUBSTATION

Receive Dt: 19990920
Generator Code Description: Large Quantity Generator
Handler Name: MTA NYCT GREEN STREET SUBSTATION

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
105	1 of2	S	0.17 / 918.56	13.39 / 1	SHELL OIL CO 256 MCGUINNES BLVD BROOKLYN NY 11222-1809	RCRA NON GEN

EPA Handler ID: NYD987008166
Gen Status Universe: No Report
Contact Name:
Contact Address: ONE , JERICHO PLZ , , JERICHO , NY, 11753 , US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 40.730807
Location Longitude: -73.951569
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date: 19990714
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19920713
Handler Name: SHELL OIL CO
Source Type: Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990715
Handler Name: SHELL OIL CO
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: SHELL OIL CO
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: SHELL OIL CO
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: A JAY A NUSSBAUM
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: NY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: A JAY A NUSSBAUM
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Notification
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: NY
Country:
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: A JAY A NUSSBAUM
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: NY
Country: US
Zip Code: 99999

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: SHELL OIL CO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Dt: 19990715
Generator Code Description: Not a Generator, Verified
Handler Name: SHELL OIL CO

Receive Dt: 19920713
Generator Code Description: Large Quantity Generator
Handler Name: SHELL OIL CO

---

105 | **2 of2** | **S** | **0.17 / 918.56** | **13.39 / 1** | **MC GUINNESS & KENT SERVICE STATION INC.**
256 MCGUINNESS BOULEVARD
256 MCGUINNESS BLVD (KENT ST)
Brooklyn NY 11222 | **UST**

Site ID: 5932
Site Status: Active
Program No: 2-191035
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Retail Gasoline Sales

Expiry: 06/01/2027
County: Kings
UTM X: 588558.48676
UTM Y: 4509424.73587

Tank Information

Prog No: 2-191035
Tank ID: 7371
Tank No: 002
Tank Status: 3
Tank Status Desc: Closed - Removed
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 12/01/1971
Close Date: 04/01/1999
Tk Out of Serv Dt:
Capacity (Gal): 4000
Registered: True
Tank Model:
Pipe Model:

UDC Ind: 0
Red Tag Start Date:
Red Tag End Date:
Tank Last Test: 05/01/1993
Tank Next Test Due:
Test Method: 01
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method: -
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Tank Information

Prog No:	2-191035	**UDC Ind:**	0
Tank ID:	62789	**Red Tag Start Date:**	
Tank No:	2	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	06	**Test Method:**	-
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	**Date Tested:**	
Install Date:		**Next Test:**	
Close Date:	02/01/2002	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	12000	**Line Test Method:**	-
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: I02
Code Name: High Level Alarm

Type: Overfill

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: A03
Code Name: Fiberglass Liner (FRP)
Type: Tank Internal Protection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Tank Information

Prog No:	2-191035	***UDC Ind:***	0
Tank ID:	7372	***Red Tag Start Date:***	
Tank No:	003	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	05/01/1993
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	01
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	12/01/1971	***Next Test:***	
Close Date:	04/01/1999	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	-
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.

Class A Operator:
Class B Operator:
Tank Owner Name:

Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: I00
Code Name: None
Type: Overfill

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Tank Information

Prog No:	2-191035	***UDC Ind:***	0
Tank ID:	7370	***Red Tag Start Date:***	
Tank No:	001	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	05/01/1993
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	01
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	12/01/1971	***Next Test:***	
Close Date:	04/01/1999	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	-
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986

Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: I00
Code Name: None
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Tank Information

Prog No:	2-191035	***UDC Ind:***	0
Tank ID:	217706	***Red Tag Start Date:***	
Tank No:	0001	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	-
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:	06/01/2007	***Next Test:***	
Close Date:		***Line Last Test Due:***	08/21/2023
Tk Out of Serv Dt:		***Next Line Test Due:***	08/21/2024
Capacity (Gal):	12000	***Line Test Method:***	01
Registered:	True	***Modified by:***	TankSys
Tank Model:	104	***Last Modified:***	05/15/2024

Pipe Model: D
Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: FRANKLIN PIMENTEL
Class B Operator: FRANKLIN PIMENTEL
Tank Owner Name: FRANKLYN PIMENTEL
Tank Owner Address: 256 MC GUINNESS BLVD. BROOKLYN, NY. 11222

Material Information

Material Name: gasoline/ethanol
Percent: 10.00

Equipment Information

Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Equipment: A03
Code Name: Fiberglass Liner (FRP)
Type: Tank Internal Protection

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Tank Information

Prog No:	2-191035	**UDC Ind:**	0
Tank ID:	7374	**Red Tag Start Date:**	
Tank No:	005	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	-
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1959	**Next Test:**	
Close Date:	02/01/2002	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	-
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: D00
Code Name: No Piping

Type: Pipe Type

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: B00
Code Name: None
Type: Tank External Protection

Tank Information

Prog No:	2-191035	***UDC Ind:***	0
Tank ID:	7373	***Red Tag Start Date:***	
Tank No:	004	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	-
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	12/01/1959	***Next Test:***	
Close Date:	02/01/2002	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	-
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: I00
Code Name: None
Type: Overfill

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: F00

Code Name: None
Type: Pipe External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Tank Information

Prog No:	2-191035	**UDC Ind:**	0
Tank ID:	62788	**Red Tag Start Date:**	
Tank No:	1	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	06	**Test Method:**	-
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	**Date Tested:**	
Install Date:		**Next Test:**	
Close Date:	02/01/2002	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	12000	**Line Test Method:**	-
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: A03
Code Name: Fiberglass Liner (FRP)
Type: Tank Internal Protection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Tank Information

Prog No:	2-191035	***UDC Ind:***	0
Tank ID:	217707	***Red Tag Start Date:***	
Tank No:	0002	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	-
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:	06/01/2007	***Next Test:***	
Close Date:		***Line Last Test Due:***	08/21/2023
Tk Out of Serv Dt:		***Next Line Test Due:***	08/21/2024
Capacity (Gal):	12000	***Line Test Method:***	01
Registered:	True	***Modified by:***	TankSys
Tank Model:	104	***Last Modified:***	05/15/2024
Pipe Model:	D		

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: FRANKLIN PIMENTEL
Class B Operator: FRANKLIN PIMENTEL
Tank Owner Name: FRANKLYN PIMENTEL
Tank Owner Address: 256 MC GUINNESS BLVD. BROOKLYN, NY. 11222

Material Information

Material Name: gasoline/ethanol
Percent: 10.00

Equipment Information

Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: A03
Code Name: Fiberglass Liner (FRP)
Type: Tank Internal Protection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Affiliation Information

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: MC GUINNESS & KENT SERVICE STATION INC.
Contact Title:
Contact Name: FRANKLYN PIMENTAL
Address1:
Address2:
City:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

State:	NN
Zip Code:	
Country Code:	999
Phone:	(917) 776-3786
Phone Ext:	
Email:	
Fax:	

Affiliation Type:	04
Affiliation Name:	Facility Operator
Affiliation Sub Type:	NNN
Company:	MC GUINNESS & KENT SERVICE STATION INC.
Contact Title:	
Contact Name:	FRANKLIN PIMENTEL
Address1:	
Address2:	
City:	
State:	NN
Zip Code:	
Country Code:	001
Phone:	(718) 383-1131
Phone Ext:	
Email:	
Fax:	

Affiliation Type:	07
Affiliation Name:	Mail Contact
Affiliation Sub Type:	NNN
Company:	MC GUINNESS & KENT SERVICE STATION INC.
Contact Title:	PRESIDENT
Contact Name:	FRANKLYN PIMENTEL
Address1:	256 MC GUINNESS BLVD.
Address2:	
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 383-1131
Phone Ext:	
Email:	BPCOMPLETE@AOL.COM
Fax:	

Affiliation Type:	01
Affiliation Name:	Facility Owner
Affiliation Sub Type:	E
Company:	MC GUINNESS & KENT SERVICE STATION INC.
Contact Title:	PRESIDENT
Contact Name:	FRANKLYN PIMENTEL
Address1:	256 MC GUINNESS BLVD.
Address2:	
City:	BROOKLYN
State:	NY
Zip Code:	11222
Country Code:	001
Phone:	(718) 383-1131
Phone Ext:	
Email:	BPCOMPLETE@AOL.COM
Fax:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
106	1 of1	NW	0.17 / 920.87	10.41 / -2	J & N ASSOC 158 DUPONT ST (AKA 158A DUPONT STREET) Brooklyn NY 11222	AST

Site ID:	4631	**Expiry:**	N/A
Site Status:	Unregulated/Closed	**County:**	Kings
Program No:	2-150835	**UTM X:**	588366.56252
Program Type Code:	PBS	**UTM Y:**	4509971.59919

Program Type Desc: Petroleum Bulk Storage Program
Site Type: Unknown

Tank Information

Prog No:	2-150835	**UDC Ind:**	1
Tank ID:	40094	**Red Tag Start Date:**	
Tank No:	001	**Red Tag End Date:**	
Tank Status:	6	**Tank Last Test:**	
Tank Status Desc:	Closed Prior to 03/1991	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:		**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	3000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: I00
Code Name: None
Type: Overfill

Equipment: A00
Code Name: None

Type: Tank Internal Protection

Affiliation Information

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: J & N ASSOC
Contact Title:
Contact Name:
Address1: 32 COURT ST
Address2:
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 855-0740
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: ZZZ
Company: J & N ASSOC
Contact Title:
Contact Name:
Address1: 32 COURT ST
Address2:
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 855-0740
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: J & N ASSOC
Contact Title:
Contact Name: WM L HIGGINS
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 287-5500
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: J & N ASSOC
Contact Title:
Contact Name: R RADIBAN
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 855-0740

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					Phone Ext: **Email:** **Fax:**	
107	1 of1	WNW	0.18 / 932.41	14.19 / 2	1048 MANHATTAN AVENUE 1048 MANHATTAN AVENUE Brooklyn NY	OER CLEANUP

Class: Completed (C)
Phase: Site Management
BIN: 3025050002
Postcode: 1
Community Board: 33
Council District: 575
Census Tract: 3063951
Latitude: 40.734646
Longitude: -73.954979
BBL: 3025050002
OER Program: VCP (Enrolled), E/RD (Review)
NTA: Greenpoint
Project Docs URL: https://a002-epic.nyc.gov/app/workspace/4266/docrepository

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
108	1 of1	NW	0.18 / 947.45	8.82 / -3	CON EDISION - TM615 DUPONT ST. AND MCGUINESS BLVD. NEW YORK NY 10003	RCRA NON GEN

EPA Handler ID: NYP004082608
Gen Status Universe: No Report
Contact Name: ANTHONY DRUMMINGS
Contact Address: 4 , IRVING PLACE , , NEW YORK , NY, 10003 , US
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country: US
County Name: NEW YORK
EPA Region: 02
Land Type:
Receive Date: 20020602
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20020531
Handler Name:	CON EDISION - TM615
Source Type:	Annual/Biennial Report
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20020601
Handler Name:	CON EDISION - TM615
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20020602
Handler Name:	CON EDISION - TM615
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Historical Handler Details

Receive Dt:	20020601
Generator Code Description:	Not a Generator, Verified
Handler Name:	CON EDISION - TM615

Receive Dt:	20020531
Generator Code Description:	Large Quantity Generator
Handler Name:	CON EDISION - TM615

109	*1 of2*	*WSW*	*0.18 / 948.49*	*19.97 / 8*	***MTA NYCT - GREENPOINT TUBE*** ***INDIA ST & MANHATTAN AVE*** ***JACKSON AVE & 47TH RD*** ***BROOKLYN NY 11222***	***RCRA SQG***

EPA Handler ID:	NYR000208231
Gen Status Universe:	Small Quantity Generator
Contact Name:	GERALD LEZEAU
Contact Address:	2 , BROADWAY 5TH FL 503 , , NEW YORK , NY, 10004 , US
Contact Phone No and Ext:	646-252-3535
Contact Email:	GERALD.LEZEAU@NYCT.COM
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	State
Receive Date:	20140310
Location Latitude:	40.732308
Location Longitude:	-73.954611
Recycler Activity(YES/NO)?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity W.O. Stor:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20140310
Handler Name:	MTA NYCT - GREENPOINT TUBE
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator
Source Type:	Notification

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	State	***Street 1:***	
Name:	MTA NYCT	***Street 2:***	
Date Became Current:	19680301	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	
Owner/Operator Ind:	Current Owner	***Street No:***	2
Type:	State	***Street 1:***	BROADWAY 5TH FL 503
Name:	MTA NYCT	***Street 2:***	
Date Became Current:	19680301	***City:***	NEW YORK
Date Ended Current:		***State:***	NY
Phone:	646-252-3535	***Country:***	US
Source Type:	Notification	***Zip Code:***	10004

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
109	*2 of2*	*WSW*	*0.18 / 948.49*	*19.97 / 8*	***MTA NYCT - CROSSTOWN LINE I G LINE INDIA ST & MANHATTAN AVE TO CHURCH & MCDONALD AVES BROOKLYN NY 11218***	***RCRA SQG***

EPA Handler ID:	NYR000229195
Gen Status Universe:	Small Quantity Generator
Contact Name:	LUMINITA MARINESCU

Contact Address:	2 , BROADWAY 5TH FLOOR 503 , , NEW YORK , NY, 10004 , US
Contact Phone No and Ext:	646-252-3506
Contact Email:	LUMINITA.MARINESCU@NYCT.COM
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	State
Receive Date:	20161004
Location Latitude:	40.732308
Location Longitude:	-73.954611
Recycler Activity(YES/NO)?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity W.O. Stor:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20161004
Handler Name:	MTA NYCT - CROSSTOWN LINE I G LINE
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator
Source Type:	Notification

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	2
Type:	State	**Street 1:**	BROADWAY 5TH FLOOR 503
Name:	MTA NYCT	**Street 2:**	
Date Became Current:	19680301	**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	646-252-3506	**Country:**	US
Source Type:	Notification	**Zip Code:**	10004
Owner/Operator Ind:	Current Operator	**Street No:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type:	State	**Street 1:**	
Name:	MTA NYCT	**Street 2:**	
Date Became Current:	19680301	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	

110	1 of1	WSW	0.18 / 961.96	24.26 / 12	ALEKSANDRA CHODOWIEC 161 JAVA STREET AP. 1 BROOKLYN NY 11222	AST

Site ID:	30478	**Expiry:**	N/A
Site Status:	Unregulated/Closed	**County:**	Kings
Program No:	2-608626	**UTM X:**	588305.59799
Program Type Code:	PBS	**UTM Y:**	4509498.56492
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Apartment Building/Office Building		

Tank Information

Prog No:	2-608626	**UDC Ind:**	0
Tank ID:	65413	**Red Tag Start Date:**	
Tank No:	001	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:		**Next Line Test Due:**	
Close Date:	02/02/2009	**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	2000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location:	1
Tank Location Desc:	Aboveground-contact w/ soil
Category:	1
Category Desc:	Category 1 means a tank which was installed before December 27, 1986
Subpart:	
Subpart Desc:	
Tank Owner Name:	ALEKSANDRA CHODOWIEC
Tank Owner Address:	161 JAVA ST., APT. 1 BROOKLYN, NY. 11222

Material Information

Material Name:	#2 fuel oil (on-site consumption)
Percent:	100.00

Equipment Information

Equipment:	G00
Code Name:	None
Type:	Tank Secondary Containment
Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection
Equipment:	B00
Code Name:	None
Type:	Tank External Protection
Equipment:	C00
Code Name:	No Piping
Type:	Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: I00
Code Name: None
Type: Overfill

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Affiliation Information

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: A
Company: ALEKSANDRA CHODOWIEC
Contact Title: OWNER
Contact Name: ALEKSANDRA CHODOWIEC
Address1: 161 JAVA ST., APT. 1
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 389-5066
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company:
Contact Title:
Contact Name: EVA SZYMANIK
Address1: 2815 MT. ANTHONY RD.
Address2:
City: NORTH POWNAL
State: VT
Zip Code: 05260
Country Code: 001
Phone: (800) 277-0407
Phone Ext:
Email: ASZYMANIK@POLBOOK.COM
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: ALEKSANDRA CHODOWIEC
Contact Title:
Contact Name: ALEKSANDRA CHODOWIEC
Address1:
Address2:
City:
State: NN
Zip Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Country Code: 001
Phone: (718) 389-5066
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: ALEKSANDRA CHODOWIEC
Contact Title:
Contact Name: ALEKSANDRA CHODOWIEC
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 389-5066
Phone Ext:
Email:
Fax:

111	1 of1	SSE	0.18 / 964.07	9.75 / -2	CON EDISON - TRANSFORMER MANHOLE 753 253 GREENPOINT AVE BROOKLYN NY 11222	RCRA LQG

EPA Handler ID: NYP005133897
Gen Status Universe: Large Quantity Generator
Contact Name: ALYSSA SOTTO
Contact Address: 4 , IRVING PLACE, 15TH FL NE , , NEW YORK , NY, 10003 , US
Contact Phone No and Ext: 212-460-2757
Contact Email: SOTTOA@CONED.COM
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20180410
Location Latitude: 40.730602
Location Longitude: -73.95003
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20180410
Handler Name: CON EDISON - TRANSFORMER MANHOLE 753
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	4
Type:	Private	**Street 1:**	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20170830	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:	212-460-2757	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003

Owner/Operator Ind:	Current Owner	**Street No:**	4
Type:	Private	**Street 1:**	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20170830	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:	212-460-2757	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003

112	*1 of2*	*W*	*0.18 / 969.82*	*14.63 / 3*	***APHRODITE CLEANER 1019 MANHATTAN AVE BROOKLYN NY 11222***	***RCRA NON GEN***

EPA Handler ID: NYD987003795
Gen Status Universe: No Report
Contact Name: NICHOLAS NANAS
Contact Address: 1019 , MANHATTAN AVE , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 40.733752
Location Longitude: -73.954859
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19920522
Handler Name:	APHRODITE CLEANER
Source Type:	Notification
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code:	D000
Waste Code Description:	DESCRIPTION

Hazardous Waste Code:	F002
Waste Code Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20060101
Handler Name:	APHRODITE CLEANER
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20070101
Handler Name:	APHRODITE CLEANER
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	1019 MANHATTAN AVE
Name:	NICHOLAS NANAS	**Street 2:**	
Date Became Current:		**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:	718-389-1319	**Country:**	
Source Type:	Notification	**Zip Code:**	11222

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	1019 MANHATTAN AVE
Name:	NICHOLAS NANAS	**Street 2:**	
Date Became Current:		**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:	718-389-1319	**Country:**	US
Source Type:	Implementer	**Zip Code:**	11222

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	1019 MANHATTAN AVE
Name:	NICHOLAS NANAS	**Street 2:**	
Date Became Current:		**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:	718-389-1319	**Country:**	US
Source Type:	Implementer	**Zip Code:**	11222

Historical Handler Details

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	APHRODITE CLEANER

Receive Dt:	19920522
Generator Code Description:	Very Small Quantity Generator
Handler Name:	APHRODITE CLEANER

---

112 | ***2 of2*** | ***W*** | ***0.18 / 969.82*** | ***14.63 / 3*** | ***APHRODITE CLEANERS***
1019 MANHATTAN AVENUE
BROOKLYN NY 11222 | ***DELISTED DRYCLEANERS***

SR No:		**Shut Down:**	
DEC ID:	2-6101-00706	**Alt Solvent:**	
Zip Code 4:	1315	**Perchloroethylene:**	
Current Bus:		**Phone:**	718-389-1319
Latitude:		**Reg Effective Date:**	N/A
Longitude:		**Inspection Date:**	10/23/03
Record Date:	28-OCT-2019	**Drop Shop:**	Y
Original Source:	DRYC		

---

113 | ***1 of1*** | ***WNW*** | ***0.18 / 972.99*** | ***14.35 / 2*** | ***1050-1066 Manhattan Avenue***
1050 Manhattan Avenue
Brooklyn NY | ***OER CLEANUP***

Class:	Completed (C)	**Council District:**	575
Phase:	Site Management	**Census Tract:**	3000000
BIN:	3025050005	**Latitude:**	40.734693
Postcode:	1	**Longitude:**	-73.954986
Community Board:	33		
BBL:	3025050003,3025050004,3025050005,3025050006,3025050007,3025050008,3025050010		
OER Program:	VCP (Enrolled), E/RD (Review)		
NTA:	Greenpoint		
Project Docs URL:	https://a002-epic.nyc.gov/app/workspace/3312/docrepository		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
114	1 of1	W	0.19 / 982.29	15.21 / 3	APARTMENT HOUSE 168 HURON STREET BROOKLYN NY 11222	AST

Site ID: 16611
Site Status: Active
Program No: 2-342378
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Apartment Building/Office Building

Expiry: 02/03/2028
County: Kings
UTM X: 588242.70304
UTM Y: 4509635.13539

Tank Information

Prog No: 2-342378
Tank ID: 32062
Tank No: 001
Tank Status: 1
Tank Status Desc: In Service
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 01/01/1969
Close Date:
Tk Out of Serv Dt:
Capacity (Gal): 2000
Registered: True
Tank Model:
Pipe Model:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Class A Operator:
Class B Operator:
Modified by: JSMACRI
Last Modified: 12/01/2022

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: CHRIS PAPADOPOULOS
Tank Owner Address: 24-35 38TH STREET ASTORIA, NY. 11103

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: H99
Code Name: Other
Type: Tank Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Affiliation Information

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: HURON STREET REALTY CORPORATION
Contact Title: PRES
Contact Name: CHRIS PAPADOPOULOS
Address1: 24-35 38TH STREET
Address2:
City: ASTORIA
State: NY
Zip Code: 11103
Country Code: 001
Phone: (917) 509-7574
Phone Ext:
Email: CHRIS.PAPADOP@GMAIL.COM
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: APARTMENT HOUSE
Contact Title:
Contact Name: CHRIS PAPADOPOULUS
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 278-4437
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: HURON STREET REALTY CORPORATION
Contact Title: PRES
Contact Name: CHRIS PAPADOPOULOS
Address1: 24-35 38TH STREET
Address2:
City: ASTORIA
State: NY
Zip Code: 11103
Country Code: 001
Phone: (917) 509-7574
Phone Ext:
Email: CHRIS.PAPADOP@GMAIL.COM
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: HURON STREET REALTY CORPORATION
Contact Title:
Contact Name: G. PAPADOPOULOS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 999
Phone: (917) 733-6793
Phone Ext:
Email:
Fax:

---

115 | ***1 of1*** | ***W*** | ***0.19 / 987.93*** | ***14.68 / 3*** | ***158 GREEN INC***
158 GREEN ST AKA 107 MANHATTAN AVE
Brooklyn NY 11222 | ***AST***

Site ID:	460896	***Expiry:***	11/23/2026
Site Status:	Active	***County:***	Kings
Program No:	2-611752	***UTM X:***	588230.25213
Program Type Code:	PBS	***UTM Y:***	4509713.61847
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Apartment Building/Office Building		

Tank Information

Prog No:	2-611752	***UDC Ind:***	1
Tank ID:	242774	***Red Tag Start Date:***	
Tank No:	001	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	01/01/1950	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	2000	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: BIANCA CASABLANCA
Tank Owner Address: PO BOX 556 BRONX, NY. 10471

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: L09
Code Name: Exempt Suction Piping

Type: Piping Leak Detection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: J03
Code Name: Gravity
Type: Dispenser

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: H06
Code Name: Impervious Barrier/Concrete Pad (A/G)
Type: Tank Leak Detection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Affiliation Information

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: 158 GREEN, INC.
Contact Title:
Contact Name: JOSE VILLATORO
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (347) 432-6389
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: 158 GREEN, INC.
Contact Title: MANAGER
Contact Name: BIANCA CASABLANCA
Address1: PO BOX 556

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Address2:
City: BRONX
State: NY
Zip Code: 10471
Country Code: 001
Phone: (347) 202-9405
Phone Ext:
Email: BIANCA@CASABLANCAMGMT.COM
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: 158 GREEN, INC.
Contact Title:
Contact Name: EDGAR CASABLANCA
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (917) 681-8989
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: 158 GREEN, INC.
Contact Title: MANAGER
Contact Name: BIANCA CASABLANCA
Address1: PO BOX 556
Address2:
City: BRONX
State: NY
Zip Code: 10471
Country Code: 001
Phone: (347) 202-9405
Phone Ext:
Email: BIANCA@CASABLANCAMGMT.COM
Fax:

116	*1 of3*	*SSE*	*0.19 / 988.30*	*10.27 / -2*	***GREENSPAN & KUSHLIN ENGRAVING CORP 223 GREENPOINT AVE BROOKLYN NY 11222***	***RCRA NON GEN***

EPA Handler ID: NYR000097212
Gen Status Universe: No Report
Contact Name: SAMUEL GILBERT
Contact Address: 485 , MADISON AVE 20TH FLOOR , , NEW YORK , NY, 10022 , US
Contact Phone No and Ext: 212-935-0598
Contact Email:
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20070101
Location Latitude: 40.730588
Location Longitude: -73.950351
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date: 20070524
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20010524
Handler Name: GREENSPAN & KUSHLIN ENGRAVING CORP
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060101
Handler Name: GREENSPAN & KUSHLIN ENGRAVING CORP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101

Handler Name: GREENSPAN & KUSHLIN ENGRAVING CORP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	236 GREENPOINT AVE
Name:	GREENPOINT INDUSTRIAL	**Street 2:**	
Date Became Current:	20010101	**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:	718-349-0491	**Country:**	US
Source Type:	Implementer	**Zip Code:**	11222

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	236 GREENPOINT AVE
Name:	GREENPOINT INDUSTRIAL	**Street 2:**	
Date Became Current:	20010101	**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:	718-349-0491	**Country:**	US
Source Type:	Implementer	**Zip Code:**	11222

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	236 GREENPOINT AVE
Name:	GREENPOINT INDUSTRIAL	**Street 2:**	
Date Became Current:		**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:	718-349-0491	**Country:**	
Source Type:	Notification	**Zip Code:**	11222

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: GREENSPAN & KUSHLIN ENGRAVING CORP

Receive Dt: 20010524
Generator Code Description: Small Quantity Generator
Handler Name: GREENSPAN & KUSHLIN ENGRAVING CORP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
116	2 of3	SSE	0.19 / 988.30	10.27 / -2	CON EDISON SERVICE BOX: 08140 223 GREENPOINT AVE BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004575627
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20140725
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records

associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20140625
Handler Name:	CON EDISON
Source Type:	Emergency
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20140625
Handler Name:	CON EDISON
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20140725
Handler Name:	CON EDISON SERVICE BOX: 08140
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Historical Handler Details

Receive Dt:	20140625
Generator Code Description:	Small Quantity Generator
Handler Name:	CON EDISON

Receive Dt:	20140625
Generator Code Description:	Not a Generator, Verified
Handler Name:	CON EDISON

116	*3 of3*	*SSE*	*0.19 / 988.30*	*10.27 / -2*	*CON EDISON 223 GREEENPOINT AVE &*	*RCRA NON GEN*

MCGUINNESS BLVD
BROOKLYN NY 11222

EPA Handler ID:	NYP004183224
Gen Status Universe:	No Report
Contact Name:	CAROLINE ISKANDER
Contact Address:	US
Contact Phone No and Ext:	718-666-4714
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20160601
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20090714
Handler Name:	CON EDISON
Source Type:	Emergency
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20160601
Handler Name:	CON EDISON
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Historical Handler Details

Receive Dt:	20090714
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CON EDISON

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
117	1 of4	S	0.19 / 1,000.18	12.99 / 1	NYC FIRE DEPT ENGINE CO 238 205 GREENPOINT AVE BROOKLYN NY 11222-2407	RCRA NON GEN

EPA Handler ID:	NYR000040428
Gen Status Universe:	No Report
Contact Name:	
Contact Address:	205 , GREENPOINT AVE , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:	
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Municipal
Receive Date:	20070101
Location Latitude:	40.730516
Location Longitude:	-73.951074
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19970604
Handler Name:	NYC FIRE DEPT ENGINE CO 238
Source Type:	Notification
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: X003
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990708
Handler Name: NYC FIRE DEPT ENGINE CO 238
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: NYC FIRE DEPT ENGINE CO 238
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: NYC FIRE DEPT ENGINE CO 238
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Municipal
Name: NYC FIRE DEPT
Date Became Current:
Date Ended Current:
Phone: 718-965-8258
Source Type: Implementer
Street No:
Street 1: 205 GREENPOINT AVE
Street 2:
City: BROOKLYN
State: NY
Country: US
Zip Code: 11222

Owner/Operator Ind: Current Owner
Type: Municipal
Name: NYC FIRE DEPT
Date Became Current:
Date Ended Current:
Phone: 718-965-8258
Source Type: Notification
Street No:
Street 1: 205 GREENPOINT AVE
Street 2:
City: BROOKLYN
State: NY
Country:
Zip Code: 11222

Owner/Operator Ind: Current Owner
Type: Municipal
Name: NYC FIRE DEPT
Date Became Current:
Date Ended Current:
Phone: 718-965-8258
Source Type: Implementer
Street No:
Street 1: 205 GREENPOINT AVE
Street 2:
City: BROOKLYN
State: NY
Country: US
Zip Code: 11222

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified

Handler Name: NYC FIRE DEPT ENGINE CO 238

Receive Dt: 19990708
Generator Code Description: Not a Generator, Verified
Handler Name: NYC FIRE DEPT ENGINE CO 238

Receive Dt: 19970604
Generator Code Description: Small Quantity Generator
Handler Name: NYC FIRE DEPT ENGINE CO 238

---

117 | **2 of4** | **S** | **0.19 / 1,000.18** | **12.99 / 1** | **ENGINE COMPANY 238**
205 GREENPOINT AVENUE
Brooklyn NY 11222 | **AST**

Site ID: 22504
Site Status: Unregulated/Closed
Program No: 2-600523
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Other

Expiry: N/A
County: Kings
UTM X: 588573.21724
UTM Y: 4509384.63436

Tank Information

Prog No: 2-600523
Tank ID: 55976
Tank No: 007
Tank Status: 3
Tank Status Desc: Closed - Removed
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 09/01/1998
Close Date: 12/21/2021
Tk Out of Serv Dt:
Capacity (Gal): 550
Registered: True
Tank Model:
Pipe Model:

UDC Ind: 0
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: -
Line Last Test Due:
Next Line Test Due:
Line Test Method: -
Class A Operator:
Class B Operator:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: F05
Code Name: Jacketed
Type: Pipe External Protection

Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Tank Information

Prog No:	2-600523	***UDC Ind:***	1
Tank ID:	55978	***Red Tag Start Date:***	
Tank No:	008	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	09/01/1998	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	275	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Equipment: A00

Code Name: None
Type: Tank Internal Protection

Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: F05
Code Name: Jacketed
Type: Pipe External Protection

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Tank Information

Prog No:	2-600523	**UDC Ind:**	1
Tank ID:	42905	**Red Tag Start Date:**	
Tank No:	005	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:		**Next Line Test Due:**	
Close Date:	02/01/2001	**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	3000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I05
Code Name: Vent Whistle
Type: Overfill

Tank Information

Prog No:	2-600523	***UDC Ind:***	1
Tank ID:	295034	***Red Tag Start Date:***	
Tank No:	009	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	-
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	03/08/2022	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	-
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	550	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 3
Category Desc: Category 3 means a tank which was installed after October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: biodiesel (motor fuel)

Percent: .05

Equipment Information

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Equipment: A01
Code Name: Epoxy Liner
Type: Tank Internal Protection

Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Affiliation Information

Affiliation Type: 04

Affiliation Name:	Facility Operator
Affiliation Sub Type:	NNN
Company:	ENGINE COMPANY 238
Contact Title:	
Contact Name:	CASSANDRA RICHARD
Address1:	
Address2:	
City:	
State:	NN
Zip Code:	
Country Code:	001
Phone:	(718) 965-8238
Phone Ext:	
Email:	
Fax:	

Affiliation Type:	07
Affiliation Name:	Mail Contact
Affiliation Sub Type:	NNN
Company:	FIRE DEPARTMENT
Contact Title:	
Contact Name:	CASSANDRA RICHARD
Address1:	48-34 35TH STREET
Address2:	
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-6569
Phone Ext:	
Email:	CASSANDRA .RICHARD@FDNY.NYC.GOV
Fax:	

Affiliation Type:	01
Affiliation Name:	Facility Owner
Affiliation Sub Type:	C01
Company:	FIRE DEPARTMENT
Contact Title:	FACILITIES DEPUTY COMPLIANCE ADMINISTRATOR
Contact Name:	CASSANDRA RICHARD
Address1:	9 METROTECH
Address2:	
City:	BROOKLYN
State:	NY
Zip Code:	11201-3857
Country Code:	001
Phone:	(718) 999-2094
Phone Ext:	
Email:	
Fax:	

Affiliation Type:	11
Affiliation Name:	Emergency Contact
Affiliation Sub Type:	NNN
Company:	FIRE DEPARTMENT
Contact Title:	
Contact Name:	EOC/NOTIFICATION DESK
Address1:	
Address2:	
City:	
State:	NN
Zip Code:	
Country Code:	001
Phone:	(718) 999-2094
Phone Ext:	
Email:	
Fax:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
117	3 of4	S	0.19 / 1,000.18	12.99 / 1	ENGINE COMPANY 238 205 GREENPOINT AVENUE Brooklyn NY 11222	UST

Site ID: 22504
Site Status: Unregulated/Closed
Program No: 2-600523
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Other

Expiry: N/A
County: Kings
UTM X: 588573.21724
UTM Y: 4509384.63436

Tank Information

Prog No: 2-600523
Tank ID: 42904
Tank No: 004
Tank Status: 4
Tank Status Desc: Closed - In Place
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date:
Close Date: 09/01/1998
Tk Out of Serv Dt:
Capacity (Gal): 550
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: I05
Code Name: Vent Whistle
Type: Overfill

Equipment: H00

Code Name: None
Type: Tank Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Tank Information

Prog No:	2-600523	***UDC Ind:***	1
Tank ID:	54178	***Red Tag Start Date:***	
Tank No:	006	***Red Tag End Date:***	
Tank Status:	4	***Tank Last Test:***	
Tank Status Desc:	Closed - In Place	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	09/01/1998	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	1000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: I05
Code Name: Vent Whistle
Type: Overfill

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Tank Information

Prog No:	2-600523	**UDC Ind:**	1
Tank ID:	42901	**Red Tag Start Date:**	
Tank No:	001	**Red Tag End Date:**	
Tank Status:	4	**Tank Last Test:**	
Tank Status Desc:	Closed - In Place	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	05/01/1997	**Next Test:**	
Close Date:	05/01/1997	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: I05
Code Name: Vent Whistle
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Tank Information

Prog No:	2-600523	**UDC Ind:**	1
Tank ID:	42903	**Red Tag Start Date:**	
Tank No:	003	**Red Tag End Date:**	
Tank Status:	4	**Tank Last Test:**	
Tank Status Desc:	Closed - In Place	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:		**Next Test:**	
Close Date:	09/01/1998	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron

Type: Pipe Type

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I05
Code Name: Vent Whistle
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Tank Information

Prog No:	2-600523	***UDC Ind:***	1
Tank ID:	42902	***Red Tag Start Date:***	
Tank No:	002	***Red Tag End Date:***	
Tank Status:	4	***Tank Last Test:***	
Tank Status Desc:	Closed - In Place	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	05/01/1997	***Next Test:***	
Close Date:	05/01/1997	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: C01

Code Name: Aboveground
Type: Pipe Location

Equipment: I05
Code Name: Vent Whistle
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Affiliation Information

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: ENGINE COMPANY 238
Contact Title:
Contact Name: CASSANDRA RICHARD
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 965-8238
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: C01
Company: FIRE DEPARTMENT
Contact Title: FACILITIES DEPUTY COMPLIANCE ADMINISTRATOR
Contact Name: CASSANDRA RICHARD
Address1: 9 METROTECH
Address2:
City: BROOKLYN
State: NY
Zip Code: 11201-3857
Country Code: 001
Phone: (718) 999-2094
Phone Ext:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: FIRE DEPARTMENT
Contact Title:
Contact Name: CASSANDRA RICHARD
Address1: 48-34 35TH STREET
Address2:
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 784-6569
Phone Ext:
Email: CASSANDRA .RICHARD@FDNY.NYC.GOV
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: FIRE DEPARTMENT
Contact Title:
Contact Name: EOC/NOTIFICATION DESK
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 999-2094
Phone Ext:
Email:
Fax:

117	4 of4	S	0.19 / 1,000.18	12.99 / 1	CON EDISON SERVICE BOX: 8139 207 GREENPOINT AVE BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004434239
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20140305
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20140205
Handler Name:	CON EDISON SERVICE BOX: 8139
Source Type:	Emergency
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20140305
Handler Name:	CON EDISON SERVICE BOX: 8139
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Historical Handler Details

Receive Dt:	20140205
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CON EDISON SERVICE BOX: 8139

---

118 | ***1 of1*** | ***SW*** | ***0.19 / 1,010.27*** | ***26.10 / 14*** | ***946 Manhattan Avenue/160 Java Street***
946 Manhattan Avenue
Brooklyn NY | ***OER CLEANUP***

Class:	Completed (C)	**Council District:**	575
Phase:	Completed	**Census Tract:**	3064613
BIN:	3025510008	**Latitude:**	40.731511
Postcode:	1	**Longitude:**	-73.954465
Community Board:	33		
BBL:	3025510008		
OER Program:	E/RD (No Cleanup)		
NTA:	Greenpoint		
Project Docs URL:	https://a002-epic.nyc.gov/app/workspace/1340/docrepository		

---

119 | ***1 of1*** | ***WSW*** | ***0.19 / 1,016.23*** | ***19.26 / 7*** | ***975 Manhattan Avenue***
975 MANHATTAN AVENUE
Brooklyn NY | ***OER CLEANUP***

Class:	Completed (C)	**Council District:**	563
Phase:	Completed	**Census Tract:**	3064283
BIN:	3025320046	**Latitude:**	40.732519

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Postcode: 1 **Longitude:** -73.954652
Community Board: 33
BBL: 3025320046
OER Program: VCP (Enrolled), E/RD (Review)
NTA: Greenpoint
Project Docs URL: https://a002-epic.nyc.gov/app/workspace/5907/docrepository

---

120 | **1 of1** | **SSW** | **0.19 / 1,022.33** | **15.29 / 3** | **193 Greenpoint Avenue**
193 GREENPOINT AVENUE
Brooklyn NY | **OER CLEANUP**

Class: Completed (C) **Council District:** 575
Phase: Completed **Census Tract:** 3064770
BIN: 3025590037 **Latitude:** 40.730437
Postcode: 1 **Longitude:** -73.951810
Community Board: 33
BBL: 3025590037
OER Program: VCP (Terminated), E/RD (Review)
NTA: Greenpoint
Project Docs URL: https://a002-epic.nyc.gov/app/workspace/20198/docrepository

---

121 | **1 of1** | **WSW** | **0.19 / 1,024.41** | **18.28 / 6** | **977 Manhattan Avenue**
977 Manhattan Avenue
Brooklyn NY | **OER CLEANUP**

Class: Completed (C) **Council District:** 563
Phase: Site Management **Census Tract:** 3425610
BIN: 3025320045 **Latitude:** 40.732565
Postcode: 1 **Longitude:** -73.954659
Community Board: 33
BBL: 3025320045
OER Program: VCP (Enrolled), E/RD (Review)
NTA: Greenpoint
Project Docs URL: https://a002-epic.nyc.gov/app/workspace/2881/docrepository

---

122 | **1 of1** | **NW** | **0.20 / 1,038.67** | **9.41 / -3** | **INTERFLO TECHNOLOGIES**
393 MCGUINNESS BLVD
BROOKLYN NY 11222 | **RCRA NON GEN**

EPA Handler ID: NY0000441139
Gen Status Universe: No Report
Contact Name:
Contact Address: 19 , CLAY ST , , BROOKLYN , NY, 11222-1003 , US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20070101
Location Latitude: 40.736305
Location Longitude: -73.953027
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Oct, 2024.

Violation Details

Found Violation:	Yes
Citation:	
Violation Short Description:	Generators - General
Violation Type:	262.A
Violation Determined Date:	19940602
Scheduled Compliance Date:	19940805
Return to Compliance:	Observed
Actual Return to Compl:	19940725
Violation Responsible Agency:	EPA

Enforcement Details

Enforcement Type:	320
Enforcement Type Description:	FINAL IMMINENT HAZARD ORDER
Enforcement Action Date:	19940624
Enf Disposition Status:	
Disposition Status Date:	
Enforcement Lead Agency:	EPA
Proposed Penalty Amount:	
Final Amount:	
Paid Amount:	

Evaluation Details

Evaluation Start Date:	19940725
Evaluation Type Description:	NO LONGER A SIGNIFICANT NON-COMPLIER
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	EPA

Evaluation Start Date:	19940602
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Violation Short Description:	Generators - General
Return to Compliance Date:	19940725
Evaluation Agency:	EPA

Evaluation Start Date:	19940602
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	EPA

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19940707
Handler Name: INTERFLO TECHNOLOGIES
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F001
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U151
Waste Code Description: MERCURY

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19970520
Handler Name: INTERFLO TECHNOLOGIES
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: NONE
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: INTERFLO TECHNOLOGIES
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: INTERFLO TECHNOLOGIES

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	86-23 188TH ST
Name:	YALOS AVILA & ELIYAH	**Street 2:**	
Date Became Current:		**City:**	HOLLISWOOD
Date Ended Current:		**State:**	NY
Phone:	718-217-0801	**Country:**	US
Source Type:	Implementer	**Zip Code:**	11423

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	86-23 188TH ST
Name:	YALOS AVILA & ELIYAH	**Street 2:**	
Date Became Current:		**City:**	HOLLISWOOD
Date Ended Current:		**State:**	NY
Phone:	718-217-0801	**Country:**	US
Source Type:	Implementer	**Zip Code:**	11423

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	86-23 188TH ST
Name:	YALOS AVILA & ELIYAH	**Street 2:**	
Date Became Current:		**City:**	HOLLISWOOD
Date Ended Current:		**State:**	NY
Phone:	718-217-0801	**Country:**	
Source Type:	Notification	**Zip Code:**	11423

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: INTERFLO TECHNOLOGIES

Receive Dt: 19970520
Generator Code Description: Not a Generator, Verified
Handler Name: INTERFLO TECHNOLOGIES

Receive Dt: 19940707
Generator Code Description: Small Quantity Generator
Handler Name: INTERFLO TECHNOLOGIES

123	1 of1	WSW	0.20 / 1,059.19	26.07 / 14	CON EDISION - MH61605 MANHATTAN AVE NORTH OF JAVA MA NEW YORK NY 10003	RCRA NON GEN

EPA Handler ID: NYP004084406
Gen Status Universe: No Report
Contact Name: ANTHONY DRUMMINGS
Contact Address: 4 , IRVING PLACE , , NEW YORK , NY, 10003 , US
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country: US
County Name: NEW YORK
EPA Region: 02
Land Type:
Receive Date: 20020602
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20020531
Handler Name:	CON EDISION - MH61605
Source Type:	Annual/Biennial Report
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20020601
Handler Name:	CON EDISION - MH61605
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20020602
Handler Name:	CON EDISION - MH61605
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Historical Handler Details

Receive Dt:	20020601
Generator Code Description:	Not a Generator, Verified
Handler Name:	CON EDISION - MH61605

Receive Dt:	20020531
Generator Code Description:	Large Quantity Generator
Handler Name:	CON EDISION - MH61605

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
124	1 of1	NW	0.20 / 1,064.94	10.37 / -2	J & N ASSOC 159 DUPONT ST Brooklyn NY 11222	AST

Site ID: 4630
Site Status: Unregulated/Closed
Program No: 2-150827
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Unknown
Expiry: N/A
County: Kings
UTM X: 588370.93237
UTM Y: 4509994.36968

Tank Information

Prog No: 2-150827
Tank ID: 40093
Tank No: 001
Tank Status: 6
Tank Status Desc: Closed Prior to 03/1991
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date:
Close Date:
Tk Out of Serv Dt:
Capacity (Gal): 2000
Registered: True
Tank Model:
Pipe Model:
Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:
UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Class A Operator:
Class B Operator:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C00
Code Name: No Piping

Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Affiliation Information

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: ZZZ
Company: J & N ASSOC
Contact Title:
Contact Name:
Address1: 32 COURT ST
Address2:
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 855-0740
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: J & N ASSOC
Contact Title:
Contact Name: WM L HIGGINS
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 287-5500
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: J & N ASSOC
Contact Title:
Contact Name:
Address1: 32 COURT ST
Address2:
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 855-0740
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: J & N ASSOC
Contact Title:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Name: R RADIBAN
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 855-0740
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
125	1 of1	SSE	0.20 / 1,076.47	11.78 / 0	CON EDISON VAULT SUBMERSIBLE: 3826 NEWELL ST & GREEN POINT AVE 205 FEET S OF BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004431961
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20140302
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20140202
Handler Name: CON EDISON VAULT SUBMERSIBLE: 3826

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source Type: Emergency
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20140302
Handler Name: CON EDISON VAULT SUBMERSIBLE: 3826
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20140202
Generator Code Description: Very Small Quantity Generator
Handler Name: CON EDISON VAULT SUBMERSIBLE: 3826

126	1 of1	SSE	0.20 / 1,080.52	9.17 / -3	NYCDOT CONTRACT #HB107000GP & L & L PAINTING CO INC GREENPOINT AVE BR NEWTOWN CREEK BROOKLYN NY 11232	RCRA LQG

EPA Handler ID: NYR000199448
Gen Status Universe: Large Quantity Generator
Contact Name: JOHN KURRE
Contact Address: 55 , WATER ST , 5TH FL , NEW YORK , NY, 10041 , US
Contact Phone No and Ext: 212-788-2091
Contact Email: JKURRE@DOT.NYC.GOV
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type: Municipal
Receive Date: 20140304
Location Latitude: 40.730602
Location Longitude: -73.95003
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date: 20150616
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No

Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20130321
Handler Name:	NYCDOT CONTRACT #HB10700GP & L & L PAINTING CO INC
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator
Source Type:	Temporary

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20140304
Handler Name:	NYCDOT CONTRACT #HB107000GP & L & L PAINTING CO INC
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator
Source Type:	Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	55
Type:	Private	***Street 1:***	WATER ST
Name:	L & L PAINTING	***Street 2:***	
Dt Became Current:	19000101	***City:***	NEW YORK
Dt Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	10041
Owner/Operator Ind:	Current Owner	***Street No:***	55
Type:	Municipal	***Street 1:***	WATER ST 5TH FL
Name:	NYCDOT	***Street 2:***	
Dt Became Current:	19870101	***City:***	NEW YORK
Dt Ended Current:		***State:***	NY
Phone:	212-839-4040	***Country:***	US
Source Type:	Temporary	***Zip Code:***	10041
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	L&L PAINTING CO INC	***Street 2:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Dt Became Current:	20130401	**City:**	
Dt Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Temporary	**Zip Code:**	
Owner/Operator Ind:	Current Owner	**Street No:**	55
Type:	Municipal	**Street 1:**	WATER ST
Name:	NYCDOT	**Street 2:**	5TH FL
Dt Became Current:	19000101	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10041

Historical Handler Details

Receive Dt:	20130321
Generator Code Description:	Large Quantity Generator
Handler Name:	NYCDOT CONTRACT #HB10700GP & L & L PAINTING CO INC

---

127 | ***1 of1*** | ***W*** | ***0.21 / 1,087.13*** | ***14.48 / 2*** | ***153 GREEN STREET***
153 GREEN STREET
Brooklyn NY | ***OER CLEANUP***

Class:	Completed (C)	**Council District:**	563
Phase:	Completed	**Census Tract:**	3064040
BIN:	3025120052	**Latitude:**	40.733666
Postcode:	1	**Longitude:**	-73.955723
Community Board:	33		
BBL:	3025120052		
OER Program:	VCP (Enrolled), E/RD (Review)		
NTA:	Greenpoint		
Project Docs URL:	https://a002-epic.nyc.gov/app/workspace/4617/docrepository		

---

128 | ***1 of1*** | ***NNW*** | ***0.21 / 1,088.80*** | ***8.67 / -3*** | ***146 CLAY LLC***
400 MC GUINNESS BLVD
Brooklyn NY 11222 | ***AST***

Site ID:	15854	**Expiry:**	N/A
Site Status:	Unregulated/Closed	**County:**	Kings
Program No:	2-333824	**UTM X:**	588447.48967
Program Type Code:	PBS	**UTM Y:**	4510058.52533
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Other		

Tank Information

Prog No:	2-333824	**UDC Ind:**	1
Tank ID:	20817	**Red Tag Start Date:**	
Tank No:	001	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:		**Next Line Test Due:**	
Close Date:	10/25/2001	**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	3000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	1		
Tank Location Desc:	Aboveground-contact w/ soil		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		

Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: H04
Code Name: Groundwater Well
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: B00
Code Name: None
Type: Tank External Protection

Affiliation Information

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: 146 CLAY LLC
Contact Title:
Contact Name: ALEX GEORGLADIS
Address1:
Address2:
City:
State: NN
Zip Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Country Code: 001
Phone: (718) 534-0607
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: 146 CLAY LLC
Contact Title: AGENT
Contact Name: M. MICHAEL UNFLAT
Address1: 146 CLAY ST.
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 534-0607
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: 146 CLAY LLC
Contact Title:
Contact Name: ALEX GEORGLADIS
Address1: 146 CLAY ST.
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (718) 534-0607
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: 146 CLAY LLC
Contact Title:
Contact Name: EVAN AVDOULOUS
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 999
Phone: (917) 405-7654
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
129	1 of1	NE	0.21 / 1,088.91	8.63 / -3	CON EDISON 91 PAIDGE AVE & PROVOST ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004183273
Gen Status Universe: No Report
Contact Name: CAROLINE ISKANDER
Contact Address: US
Contact Phone No and Ext: 718-666-4714
Contact Email:
Contact Country: US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20160601
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20090714
Handler Name: CON EDISON
Source Type: Emergency
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20160601
Handler Name: CON EDISON
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20090714
Generator Code Description: Very Small Quantity Generator
Handler Name: CON EDISON

130	1 of1	NE	0.21 / 1,090.66	8.63 / -3	DIAMOND ASPHALT CORPORATION 91 Paidge Ave	AIR PERMITS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					Brooklyn NY 11222	

Facility ID:
County:
Dec ID: 2610101143
Source: Air Permitted Facilities

Facility Details

Permit Type: ASF
Status: Expired
Renewal No: 0
Url Permit:
Modification No: 0
Issue Date: 10/15/2004
Exp Date: 6/16/2011

Permit Type: ASF
Status: Expired
Renewal No: 0
Url Permit:
Modification No: 1
Issue Date: 6/16/2011
Exp Date:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
131	1 of1	SSW	0.21 / 1,092.93	21.84 / 10	175-177 GREENPOINT AVE 175-177 GREENPOINT AVE Brooklyn NY	OER CLEANUP

Class: Active (A)
Phase: Construction
BIN: 3025590046
Postcode: 1
Community Board: 33
Council District: 575
Census Tract: 3000000
Latitude: 40.730349
Longitude: -73.952720
BBL: 3025590046,3025590045
OER Program: E/RD (Review)
NTA: Greenpoint
Project Docs URL: https://a002-epic.nyc.gov/app/workspace/32679/docrepository

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
132	1 of1	NNE	0.21 / 1,096.86	8.15 / -4	CON EDISON MANHOLE: 55218 PAIDGE PL 300 FT S OF PROVOST ST E SIDE BROOKLYN NY 11201	RCRA NON GEN

EPA Handler ID: NYP004279113
Gen Status Universe: No Report
Contact Name: CELESTINO FERNANDEZ
Contact Address:
Contact Phone No and Ext: 718-666-4511
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20170728
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20121127
Handler Name:	CON EDISON MANHOLE: 55218
Source Type:	Emergency
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20170728
Handler Name:	CON EDISON MANHOLE: 55218
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Historical Handler Details

Receive Dt:	20121127
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CON EDISON MANHOLE: 55218

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
133	*1 of1*	*SSW*	*0.21 / 1,103.40*	*22.94 / 11*	***CON EDISON 173 GREENPOINT AVE BROOKLYN NY 11222***	***RCRA NON GEN***

EPA Handler ID:	NYP004788030
Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20150529
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150529
Handler Name:	CON EDISON
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150529
Handler Name:	CON EDISON
Source Type:	Emergency
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Historical Handler Details

Receive Dt:	20150529
Generator Code Description:	Small Quantity Generator
Handler Name:	CON EDISON

134	*1 of1*	*WSW*	*0.21 / 1,115.68*	*26.11 / 14*	***947 ASSOCIATES, LLC 151 JAVA ST BROOKLYN NY 11222***	***AST***

Site ID:	18276	**Expiry:**	N/A
Site Status:	Unregulated/Closed	**County:**	Kings
Program No:	2-361771	**UTM X:**	588256.99767
Program Type Code:	PBS	**UTM Y:**	4509496.96591
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Apartment Building/Office Building		

Tank Information

Prog No:	2-361771	**UDC Ind:**	0
Tank ID:	22155	**Red Tag Start Date:**	
Tank No:	001	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	-
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	09/01/1964	**Next Line Test Due:**	
Close Date:	09/18/2017	**Line Test Method:**	-
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	2000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: HENRY KIELMANOWICZ
Tank Owner Address: 53 PAPERMILL RD. MANHASSET, NY. 11030

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: I05
Code Name: Vent Whistle
Type: Overfill

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: B05
Code Name: Jacketed
Type: Tank External Protection

Equipment: E00

Code Name: None
Type: Piping Secondary Containment

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Affiliation Information

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: 947 ASSOCIATES, LLC
Contact Title:
Contact Name: HENRY KIELMANOWICZ
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 999
Phone: (917) 418-5080
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: A JOCHNOWITZ
Contact Title:
Contact Name: ROSE SANTA CRUZ
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 969-1268
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: 947 ASSOCIATES, LLC
Contact Title: MEMBER
Contact Name: HENRY KIELMANOWICZ
Address1: 53 PAPERMILL RD.
Address2:
City: MANHASSET
State: NY
Zip Code: 11030
Country Code: 001
Phone: (917) 418-5080
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Title:
Contact Name: HENRY KIELMANOWICZ
Address1: 146 INDIA STREET
Address2:
City: BROOKLYN
State: NY
Zip Code: 11222
Country Code: 001
Phone: (917) 418-5080
Phone Ext:
Email: TENATSHOTLINE@GMAIL.COM
Fax:

135	1 of1	W	0.21 / 1,120.22	13.99 / 2	148 GREEN STREET 148 GREEN STREET Brooklyn NY	OER CLEANUP

Class: Completed (C)
Phase: Completed
BIN: 3025220031
Postcode: 1
Community Board: 33
BBL: 3025220031
OER Program: E/RD (Review)
NTA: Greenpoint
Project Docs URL: https://a002-epic.nyc.gov/app/workspace/7493/docrepository
Council District: 563
Census Tract: 3064143
Latitude: 40.733633
Longitude: -73.955896

136	1 of1	E	0.21 / 1,121.54	4.98 / -7	NEWTOWN CREEK SOUTH END OF IVY HILL ROAD BROOKLYN, QUEENS NY 11222	NPL

EPA ID: NYN000206282
Data Source: U.S. EPA Superfund Program. Source: SEMS Superfund Public User Database. FOIA4 All Final NPL Sites. Retrieved on 25 Sept 2024; U.S. EPA Site Boundaries Shapefile Download; Superfund NPR Sites with Status Information

NPL (FOIA-004 All Final NPL Sites)

NPL Status Dt: 09/29/10
Federal Facility: No
SAA (Superfund Alt):
NAI: No
NA Entity (NAI Status):
Site Name: NEWTOWN CREEK
Address: SOUTH END OF IVY HILL ROAD
City: BROOKLYN, QUEENS
Zip: 11222
State: NY
Region: 02
County:
Latitude: +40.715192
Longitude: -073.930762

NPL (Superfund Sites List)

SEMS ID: 206282
SITS ID: 1813
Site Score: 50
Status: NPL Site
Proposed Date: 9/23/2009
Listing Date: 9/29/2010
NOID Date:
Deletion Date:
Site Name: Newtown Creek
City: Brooklyn, Queens
Site Listing Narrative: NYN000206282 (PDF)
Site Progress Profile: Newtown Creek
Partial Deletion: No
Constr Complete No:
Constr Complete Dt:
Region: 2
State: New York
County: Kings, Queens
Latitude: 40.715192
Longitude: -73.930762

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Proposed Fr Notice: 09/23/2009 (PDF)
Final Fr Notice: 09/29/2010 (PDF)
NOID Fr Notice:
Deletion Fr Notice:
Restoration Fr Notice:
Notice of Data Availability:

NPL (EPA Boundaries)

EPA Program:	Superfund Remedial	**GIS Area:**	170.65
Npl Status Code:	F	**Gis Area Units:**	Acres
Federal Facility Deter Code:	No	**Primary Telephone No:**	(212) 637-4275
Region Code:	2		

Site Contact Name: Caroline Kwan-Appelman
Site Contact Email: kwan.caroline@epa.gov
Feature Info Url: https://cumulis.epa.gov/supercpad/cursites/csitinfo.cfm?id=0206282
Feature Info Url Desc: Site Profile Page
Site Feature Class: 5
Site Feature Type: Total Site Polygon/OU Aggregation
Site Feature Name: Site Boundary
Site Feature Description: Newtown Creek is approximately 3.8 miles long creek with five tributaries that form part of the border between the boroughs of Brooklyn and Queens, New York City (NYC), New York.
Projection: R2_Contiguous_Albers_Equal_Area_Conic, SR-ORG:8974
Sf Geospatial Data Disclaimer: The Agency is providing this geospatial information as a public service and does not vouch for the accuracy, completeness, or currency of data. Data provided by external parties is not independently verified by EPA. This data is made available to the public strictly for informational purposes. Data does not represent EPA's official position, viewpoint, or opinion, express or implied. This information is not intended for use in establishing liability or calculating Cost Recovery Statutes of Limitations and cannot be relied upon to create any rights, substantive or procedural, enforceable by any party in litigation with the United States or third parties. EPA reserves the right to change these data at any time without public notice.
Addr Comment: South End of Ivy Hill Road
URL Alias Txt: https://www.epa.gov/superfund/newtown-creek

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
137	1 of1	SE	0.21 / 1,127.50	8.74 / -3	LEVITON MFG CO INC BROOKLYN NY	PFAS IND

Status:	Active	**Fac Fips Code:**	36047
Fac Indian Cntry Flg:	No	**Compliance Status:**	No Violation Identified
Fac Derived Huc:	02030201	**EPA Programs:**	CAA; RCRA
Fac Derived Wbd:	020301010405	**Federal Facility:**	No
Fac Derived Cd113:	12	**Federal Agency:**	-
Fac Derived Cb2010:	360470579002022	**Fac Snc Flg:**	No
Fac Informal Count:	0	**AIR Flag:**	Yes
Last Informal Action:	-	**NPDES Flag:**	No
Formal Action Count:	0	**SDWIS Flag:**	No
Last Formal Action:	5/31/1988	**RCRAFlag:**	Yes
Fac Total Penalties:	0	**TRI Flag:**	No
Fac Penalty Count:	-	**GHG Flag:**	No
Date Last Penalty:	-	**TRI IDs:**	11222LVTNM236GR
Last Penalty Amt:	-	**TRI Releases Trnsfrs:**	-
Fac Qtrs With Nc:	0	**TRI on Site Releases:**	-
Programs With Snc:	0	**TRI off Site Trnsfrs:**	-
Fac Percent Minority:	50.136	**TRI Reporter:**	-
Fac Pop Den:	47989.04	**Fac Imp Water Flg:**	-
Count:	1	**Fac Major Flag:**	-
Fac County:	KINGS	**Fac Active Flag:**	Yes
State Other :		**Fac Inspection Count:**	0
Region:	02	**Date Last Inspection:**	11/21/1989
Latitude:	40.73068	**Days Last Inspection:**	12723
Longitude:	-73.94924		

Fac Derived Tribes: -
AIR IDs: NY0000002610100008
CAA Permit Types: Minor Emissions
CAA NAICS: 335931

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CAA SICS:	3699
NPDES IDs:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDs:	NYD066075797
RCRA Permit Types:	Other
RCRA NAICS:	335931
SDWA IDs:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA Snc Flag:	No
Fac Collection Meth:	ADDRESS MATCHING-HOUSE NUMBER
EJSCREEN Flag Us:	Yes
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.94924,%22y%22:40.73068,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110001588540
Industry:	Electronics Industry

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
138	1 of1	SSW	0.22 / 1,137.28	24.69 / 13	CON EDISON 167 GREENPOINT AVE BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID:	NYP004807921
Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20150716
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150716
Handler Name:	CON EDISON
Source Type:	Emergency
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150716
Handler Name:	CON EDISON
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Historical Handler Details

Receive Dt:	20150716
Generator Code Description:	Small Quantity Generator
Handler Name:	CON EDISON

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
139	*1 of3*	*SE*	*0.22 / 1,175.86*	*8.73 / -3*	*VERIZON* *GREEN POINT AVE & JEWEL ST* *INTERSECTION OF* *BROOKLYN NY 11222*	*RCRA NON GEN*

EPA Handler ID:	NYP000965772
Gen Status Universe:	No Report
Contact Name:	BILL IRWIN
Contact Address:	2 , HAMPSHIRE ST 3RD FL , , LAWRENCE , MA, 01840 , US
Contact Phone No and Ext:	978-837-3604
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	
Receive Date:	20100108
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20100108
Handler Name:	VERIZON
Source Type:	Emergency
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
139	2 of3	SE	0.22 / 1,175.86	8.73 / -3	VERIZON GREENPOINT AVE & JEWEL ST INTERSECTION OF BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID:	NYP000965707
Gen Status Universe:	No Report
Contact Name:	BILL IRWIN
Contact Address:	2 , HAMPSHIRE ST 3RD FL , , LAWRENCE , MA, 01840 , US
Contact Phone No and Ext:	978-837-3604
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	
Receive Date:	20091229
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20091229
Handler Name:	VERIZON
Source Type:	Emergency
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

139	*3 of3*	*SE*	*0.22 / 1,175.86*	*8.73 / -3*	*CON EDISON GREENPOINT AVE & JEWEL ST BROOKLYN NY 11235*	*RCRA NON GEN*

EPA Handler ID:	NYP004792594
Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20150610
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150610
Handler Name:	CON EDISON
Source Type:	Emergency
Federal Waste Generator Code:	1

Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150610
Handler Name: CON EDISON
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20160205
Handler Name: CON EDISON - MANHOLE 8147
Source Type: Annual/Biennial Report update with Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Date Became Current: 20150610
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report update with Notification
Street No: 4
Street 1: IRVING PLACE
Street 2:
City: NEW YORK
State: NY
Country: US
Zip Code: 10003

Owner/Operator Ind: Current Owner
Type: Private
Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Date Became Current: 20150610
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report update with Notification
Street No: 4
Street 1: IRVING PLACE
Street 2:
City: NEW YORK
State: NY
Country: US
Zip Code: 10003

Historical Handler Details

Receive Dt: 20160205
Generator Code Description: Large Quantity Generator
Handler Name: CON EDISON - MANHOLE 8147

Receive Dt: 20150610
Generator Code Description: Large Quantity Generator
Handler Name: CON EDISON

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
140	1 of5	S	0.22 / 1,184.97	15.63 / 4	R & S STRAUSS 235 MCGUINESS BLVD BROOKLYN NY 11222-2305	RCRA NON GEN

EPA Handler ID: NYR000025619
Gen Status Universe: No Report
Contact Name:

Contact Address:	235 , MCGUINESS BLVD , , BROOKLYN , NY, 11222 , US
Contact Phone No and Ext:	
Contact Email:	
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20070101
Location Latitude:	40.730164
Location Longitude:	-73.951452
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19960617
Handler Name:	R & S STRAUSS
Source Type:	Notification
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Waste Code Details

Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE
Hazardous Waste Code:	D018
Waste Code Description:	BENZENE

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19990708
Handler Name:	R & S STRAUSS
Source Type:	Implementer
Federal Waste Generator Code:	N

Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: R & S STRAUSS
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: R & S STRAUSS
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: R & S STRAUSS ASSOCIATION
Date Became Current:
Date Ended Current:
Phone: 908-390-9000
Source Type: Notification
Street No:
Street 1: 9A BRICKPLANT RD
Street 2:
City: SOUTH RIVER
State: NJ
Country:
Zip Code: 08882

Owner/Operator Ind: Current Owner
Type: Private
Name: R & S STRAUSS ASSOCIATION
Date Became Current:
Date Ended Current:
Phone: 908-390-9000
Source Type: Implementer
Street No:
Street 1: 9A BRICKPLANT RD
Street 2:
City: SOUTH RIVER
State: NJ
Country: US
Zip Code: 08882

Owner/Operator Ind: Current Operator
Type: Private
Name: R & S STRAUSS ASSOCIATION
Date Became Current:
Date Ended Current:
Phone: 908-390-9000
Source Type: Implementer
Street No:
Street 1: 9A BRICKPLANT RD
Street 2:
City: SOUTH RIVER
State: NJ
Country: US
Zip Code: 08882

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: R & S STRAUSS

Receive Dt: 19990708
Generator Code Description: Not a Generator, Verified
Handler Name: R & S STRAUSS

Receive Dt: 19960617
Generator Code Description: Small Quantity Generator
Handler Name: R & S STRAUSS

140	2 of5	S	0.22 / 1,184.97	15.63 / 4	SPEEDWAY # 7821 210 GREENPOINT AVENUE BROOKLYN NY 11222	UST

Site ID: 13746
Site Status: Unregulated/Closed
Program No: 2-297550
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Retail Gasoline Sales

Expiry: N/A
County: Kings
UTM X: 588513.97442
UTM Y: 4509320.47047

Tank Information

Prog No: 2-297550
Tank ID: 46298
Tank No: 009
Tank Status: 3
Tank Status Desc: Closed - Removed
Tank Type: 06
Tank Type Desc: Fiberglass Reinforced Plastic (FRP)
Install Date: 07/01/1993
Close Date: 09/11/2023
Tk Out of Serv Dt:
Capacity (Gal): 4000
Registered: True
Tank Model:
Pipe Model:

UDC Ind: 0
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: -
Date Tested:
Next Test:
Line Last Test Due: 08/24/2021
Next Line Test Due:
Line Test Method: 12
Modified by: ACDANIEL
Last Modified: 04/16/2024

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name: Jacob Kohn
Tank Owner Address: 40 Oser Avenue, Suite 4 Hauppauge, NY. 11788

Material Information

Material Name: gasoline/ethanol
Percent: 10.00

Equipment Information

Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Tank Information

Prog No:	2-297550	***UDC Ind:***	0
Tank ID:	15758	***Red Tag Start Date:***	
Tank No:	004	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	02/01/1988
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	01
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	05/01/1972	***Next Test:***	
Close Date:	05/01/1993	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	-
Registered:	True	***Modified by:***	ACDANIEL
Tank Model:		***Last Modified:***	04/16/2024
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: I00
Code Name: None
Type: Overfill

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H99
Code Name: Other
Type: Tank Leak Detection

Tank Information

Prog No:	2-297550	***UDC Ind:***	0
Tank ID:	15760	***Red Tag Start Date:***	
Tank No:	006	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	02/01/1988
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	01
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	05/01/1972	***Next Test:***	
Close Date:	05/01/1993	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	-
Registered:	True	***Modified by:***	ACDANIEL
Tank Model:		***Last Modified:***	04/16/2024
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I00
Code Name: None
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: H99
Code Name: Other
Type: Tank Leak Detection

Tank Information

Prog No:	2-297550	***UDC Ind:***	0
Tank ID:	46299	***Red Tag Start Date:***	
Tank No:	010	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	-
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:	07/01/1993	***Next Test:***	
Close Date:	09/11/2023	***Line Last Test Due:***	08/24/2021
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	12
Registered:	True	***Modified by:***	ACDANIEL
Tank Model:		***Last Modified:***	04/16/2024
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.

Class A Operator:
Class B Operator:
Tank Owner Name: Jacob Kohn
Tank Owner Address: 40 Oser Avenue, Suite 4 Hauppauge, NY. 11788

Material Information

Material Name: gasoline/ethanol
Percent: 10.00

Equipment Information

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Tank Information

Prog No:	2-297550	***UDC Ind:***	0
Tank ID:	302423	***Red Tag Start Date:***	
Tank No:	014	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	-
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	03/16/2022	***Next Test:***	
Close Date:	09/14/2023	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	-
Registered:	True	***Modified by:***	ACDANIEL
Tank Model:		***Last Modified:***	04/16/2024
Pipe Model:			

Tank Location:	5
Tank Location Desc:	Underground
Category:	3
Category Desc:	Category 3 means a tank which was installed after October 11, 2015
Subpart:	2
Subpart Desc:	Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:	
Class B Operator:	
Tank Owner Name:	Jacob Kohn
Tank Owner Address:	40 Oser Avenue, Suite 4 Hauppauge, NY. 11788

Material Information

Material Name:	gasoline
Percent:	100.00

Equipment Information

Equipment:	B00
Code Name:	None
Type:	Tank External Protection
Equipment:	G00
Code Name:	None
Type:	Tank Secondary Containment
Equipment:	E00
Code Name:	None
Type:	Piping Secondary Containment
Equipment:	H00
Code Name:	None
Type:	Tank Leak Detection
Equipment:	J00
Code Name:	None
Type:	Dispenser
Equipment:	D00
Code Name:	No Piping
Type:	Pipe Type
Equipment:	F00
Code Name:	None
Type:	Pipe External Protection
Equipment:	K00
Code Name:	None

Type: Spill Prevention

Equipment: I00
Code Name: None
Type: Overfill

Equipment: L00
Code Name: None
Type: Piping Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Tank Information

Prog No:	2-297550	***UDC Ind:***	0
Tank ID:	15755	***Red Tag Start Date:***	
Tank No:	001	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	02/01/1988
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	01
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	05/01/1972	***Next Test:***	
Close Date:	05/01/1993	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	-
Registered:	True	***Modified by:***	ACDANIEL
Tank Model:		***Last Modified:***	04/16/2024

Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: H99

Code Name: Other
Type: Tank Leak Detection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: I00
Code Name: None
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Tank Information

Prog No:	2-297550	***UDC Ind:***	0
Tank ID:	46301	***Red Tag Start Date:***	
Tank No:	012	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	08/01/1997
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	20
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:	07/01/1993	***Next Test:***	
Close Date:	09/08/2023	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	-
Registered:	True	***Modified by:***	ACDANIEL
Tank Model:		***Last Modified:***	04/16/2024
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name: Jacob Kohn
Tank Owner Address: 40 Oser Avenue, Suite 4 Hauppauge, NY. 11788

Material Information

Material Name: gasoline/ethanol
Percent: 10.00

Equipment Information

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Tank Information

Prog No:	2-297550	***UDC Ind:***	0
Tank ID:	46297	***Red Tag Start Date:***	
Tank No:	008	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	08/01/1997
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	20
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:	07/01/1993	***Next Test:***	
Close Date:	09/13/2023	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	-
Registered:	True	***Modified by:***	ACDANIEL
Tank Model:		***Last Modified:***	04/16/2024
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	2		
Category Desc:	Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015		

Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name: Jacob Kohn
Tank Owner Address: 40 Oser Avenue, Suite 4 Hauppauge, NY. 11788

Material Information

Material Name: gasoline/ethanol
Percent: 10.00

Equipment Information

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Tank Information

Prog No:	2-297550	**UDC Ind:**	0
Tank ID:	15756	**Red Tag Start Date:**	
Tank No:	002	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	02/01/1988
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	01
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	05/01/1972	**Next Test:**	
Close Date:	05/01/1993	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	2000	**Line Test Method:**	-
Registered:	True	**Modified by:**	ACDANIEL
Tank Model:		**Last Modified:**	04/16/2024
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H99
Code Name: Other
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Tank Information

Prog No:	2-297550	**UDC Ind:**	0
Tank ID:	15759	**Red Tag Start Date:**	
Tank No:	005	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	02/01/1988
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	01
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	05/01/1972	**Next Test:**	
Close Date:	05/01/1993	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	2000	**Line Test Method:**	-
Registered:	True	**Modified by:**	ACDANIEL
Tank Model:		**Last Modified:**	04/16/2024
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: H99
Code Name: Other
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A00
Code Name: None

Type: Tank Internal Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Tank Information

Prog No:	2-297550	**UDC Ind:**	0
Tank ID:	15757	**Red Tag Start Date:**	
Tank No:	003	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	02/01/1988
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	01
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	05/01/1972	**Next Test:**	
Close Date:	05/01/1993	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	4000	**Line Test Method:**	-
Registered:	True	**Modified by:**	ACDANIEL
Tank Model:		**Last Modified:**	04/16/2024
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: F00

Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H99
Code Name: Other
Type: Tank Leak Detection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: I00
Code Name: None
Type: Overfill

Tank Information

Prog No:	2-297550	**UDC Ind:**	0
Tank ID:	15761	**Red Tag Start Date:**	
Tank No:	007	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	-
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	05/01/1972	**Next Test:**	
Close Date:	05/01/1993	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	-
Registered:	True	**Modified by:**	ACDANIEL
Tank Model:		**Last Modified:**	04/16/2024
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H99
Code Name: Other
Type: Tank Leak Detection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: I00
Code Name: None
Type: Overfill

Tank Information

Prog No:	2-297550	**UDC Ind:**	0
Tank ID:	46302	**Red Tag Start Date:**	
Tank No:	013	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	08/01/1997
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	06	**Test Method:**	20
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	**Date Tested:**	
Install Date:	07/01/1993	**Next Test:**	
Close Date:	09/08/2023	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	550	**Line Test Method:**	-
Registered:	True	**Modified by:**	ACDANIEL
Tank Model:		**Last Modified:**	04/16/2024
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator:
Class B Operator:
Tank Owner Name: Jacob Kohn
Tank Owner Address: 40 Oser Avenue, Suite 4 Hauppauge, NY. 11788

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: L00
Code Name: None
Type: Piping Leak Detection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Tank Information

Prog No:	2-297550	***UDC Ind:***	0
Tank ID:	46300	***Red Tag Start Date:***	
Tank No:	011	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	-
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:	07/01/1993	***Next Test:***	
Close Date:	09/08/2023	***Line Last Test Due:***	08/24/2021
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	4000	***Line Test Method:***	12
Registered:	True	***Modified by:***	ACDANIEL
Tank Model:		***Last Modified:***	04/16/2024
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.

Class A Operator:
Class B Operator:
Tank Owner Name: Jacob Kohn
Tank Owner Address: 40 Oser Avenue, Suite 4 Hauppauge, NY. 11788

Material Information

Material Name: gasoline/ethanol
Percent: 10.00

Equipment Information

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: L07
Code Name: Pressurized Piping Leak Detector
Type: Piping Leak Detection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: D06
Code Name: Fiberglass Reinforced Plastic (FRP)
Type: Pipe Type

Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Affiliation Information

Affiliation Type:	04
Affiliation Name:	Facility Operator
Affiliation Sub Type:	NNN
Company:	SPEEDWAY # 7821
Contact Title:	
Contact Name:	210 GREENPOINT REALTY LLC
Address1:	
Address2:	
City:	
State:	NN
Zip Code:	
Country Code:	001
Phone:	(917) 846-1115
Phone Ext:	
Email:	
Fax:	

Affiliation Type:	11
Affiliation Name:	Emergency Contact
Affiliation Sub Type:	NNN
Company:	210 GREENPOINT REALTY LLC
Contact Title:	
Contact Name:	JACOB KOHN
Address1:	
Address2:	
City:	
State:	NN
Zip Code:	
Country Code:	999
Phone:	(347) 578-3749
Phone Ext:	
Email:	
Fax:	

Affiliation Type:	07
Affiliation Name:	Mail Contact
Affiliation Sub Type:	NNN
Company:	210 GREENPOINT REALTY LLC
Contact Title:	AUTHORIZED SGNER
Contact Name:	JACOB KOHN
Address1:	40 OSER AVENUE
Address2:	SUITE 4
City:	HAUPPAUGE
State:	NY
Zip Code:	11788
Country Code:	001
Phone:	(917) 846-1115
Phone Ext:	
Email:	KOHNJACOB@GMAIL.COM
Fax:	

Affiliation Type:	01
Affiliation Name:	Facility Owner
Affiliation Sub Type:	E
Company:	210 Greenpoint Realty LLC
Contact Title:	AUTHORIZED SIGNER
Contact Name:	Jacob Kohn
Address1:	40 Oser Avenue, Suite 4
Address2:	
City:	Hauppauge
State:	NY
Zip Code:	11788
Country Code:	001
Phone:	(917) 846-1115
Phone Ext:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Email: Kohnjacob@gmail.com
Fax:

---

140 | **3 of5** | **S** | **0.22 / 1,184.97** | **15.63 / 4** | **MERIT S/S**
210 GREENPOINT AVENUE
BROOKLYN NY | **LST**

Spill No:	9303423	**REM Phase:**	0
Site ID:	174214	**UST Trust:**	True
DER Facility ID:	146554	**Spill Date:**	06/15/1993 03:00:00 PM
CID:		**Rcvd Date:**	06/15/1993 03:23:00 PM
Program Type:	ER	**CAC Date:**	
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Failure	**Close Date:**	10/28/2003 12:00:00 AM
Water Body:		**Create Date:**	06/16/1993 12:00:00 AM
Class:	B1	**Update Date:**	10/28/2003 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	SIGONA
County:	Kings	**After Hours:**	False
Referred to:			
Reported by:	Affected Persons		
Source:	Gasoline Station or other PBS Facility		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"ONGOING FOR DAYS/DEC RESPONDED TO SITE. TANKS REMOVED/REPLACED BY MERIT S/S. SOIL REMOVED REQUESTED ADDITIONAL TARPS TO CONTAIN VAPORS."

Dec Remark:

""

Material Information

OP Unit ID:	981755	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	396999	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	JANICE FLATERTY
Spiller Company:	AMERADA HESS CORP
Spiller Address:	1 HESS PLAZA
Spiller City:	WOODBRIDGE
Spiller State:	NJ
Spiller Zip:	07095-
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.730364820
Longitude:	-73.951838370

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
140	4 of5	S	0.22 / 1,184.97	15.63 / 4	SPEEDWAY 7821 210 GREENPOINT AVE BROOKLYN NY 11222-2304	RCRA VSQG

EPA Handler ID: NYD982185944
Gen Status Universe: VSG
Contact Name: CHARLES A BESSE
Contact Address: PO BOX 1500 , , SPRINGFIELD , OH, 45501-1500 , US
Contact Phone No and Ext: 937-863-6272
Contact Email: CABESSE@SPEEDWAY.COM
Contact Country: US
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20160921
Location Latitude: 40.730408
Location Longitude: -73.951819
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date: 19990722
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Act W.O. Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19870511
Handler Name: MERIT OIL CORP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990708
Handler Name: MERIT OIL CORP
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: MERIT OIL CORP
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: MERIT OIL CORP
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20160921
Handler Name: SPEEDWAY 7821
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: SPEEDWAY LLC
Date Became Current: 20141001
Date Ended Current:
Phone: 937-864-3000
Source Type: Notification
Street No:
Street 1: PO BOX 1500
Street 2:
City: SPRINGFIELD
State: OH
Country: US
Zip Code: 45501-1500

Owner/Operator Ind: Current Operator
Type: Private
Name: MERIT OIL CORP
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Street No:
Street 1: NOT REQUIRED

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Name:	MERIT OIL CORP	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	SPEEDWAY LLC	**Street 2:**	
Date Became Current:	20141001	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	MERIT OIL CORP	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	99999

Historical Handler Details

Receive Dt:	20070101
Generator Code Description:	Not a Generator, Verified
Handler Name:	MERIT OIL CORP
Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	MERIT OIL CORP
Receive Dt:	19990708
Generator Code Description:	Not a Generator, Verified
Handler Name:	MERIT OIL CORP
Receive Dt:	19870511
Generator Code Description:	Large Quantity Generator
Handler Name:	MERIT OIL CORP

140	5 of5	S	0.22 / 1,184.97	15.63 / 4	**237 McGuinness Boulevard** **210 Greenpoint Avenue** **Brooklyn NY**	**OER CLEANUP**

Class:	Active (A)	**Council District:**	575
Phase:	Construction	**Census Tract:**	3065200
BIN:	3025760007	**Latitude:**	40.730415
Postcode:	1	**Longitude:**	-73.951868
Community Board:	33		
BBL:	3025760007		
OER Program:	E/RD (Review), State BCP		
NTA:	Greenpoint		
Project Docs URL:	https://a002-epic.nyc.gov/app/workspace/32253/docrepository		

141	1 of2	S	0.23 / 1,189.03	15.63 / 4	**210 Greenpoint Avenue Redevelopment** **210 GREENPOINT AVENUE** **BROOKLYN NY 11222**	**BROWNFIELDS**

Site Code:	628709
HW Code:	C224348
Program:	BCP
Site Class:	A
Site Name:	210 Greenpoint Avenue Redevelopment
Site Address:	210 GREENPOINT AVENUE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

City:	BROOKLYN
Zip:	11222
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.730200000
Longitude:	-73.951669444
SWIS:	2401
Acres:	0.310
Record Added:	2021-11-23 08:52:00
Record Update:	2024-04-11 21:13:00
Updated by:	SMQUANDT
Site Code (Web):	C224348
Program Type (Web):	BCP
Site Name (Web):	210 Greenpoint Avenue Redevelopment
Site Class (Web):	A
Address1 (Web):	210 GREENPOINT AVENUE
Address2 (Web):	
Locality (Web):	BROOKLYN
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.951669444
Latitude (Web):	40.730200000
Site Code (GIS):	C224348
Site Name (GIS):	210 Greenpoint Avenue Redevelopment
Program (GIS):	BCP
Site Class (GIS):	A
Address1 (GIS):	210 GREENPOINT AVENUE
Address2 (GIS):	
Locality (GIS):	BROOKLYN
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Site Class Desc (Web):	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Assess DOH:	Access to the site is restricted by a fence. The site is covered by concrete foundation slabs and pavement so people are not expected to come in contact with site contaminants in soil. However, persons who enter the site could contact contaminants in the soil by digging below the surface/site cover or otherwise disturbing the soil. Contaminated groundwater is not used for drinking and the site and surrounding areas are served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because the site is vacant, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for any future on-site development. Environmental sampling indicates soil vapor intrusion from site contamination is not a concern for off-site buildings.

Description:

Site Location: The Site's address is 210 Greenpoint Avenue, Brooklyn, NY 11222. The Site is located in Kings County, New York and is identified as Block 2576 Lot 7. The Site is located in a mixed-use residential and commercial section of the Greenpoint neighborhood of Brooklyn, NY on the south side of Greenpoint Avenue between McGuinness Boulevard and Eckford Street. The Site is located approximately 0.5 miles west of Newtown Creek. The Site is bounded by Greenpoint Avenue followed by mixed-use commercial and residential buildings to the north, McGuinness Boulevard followed by a commercial building, "Key Foods Grocery Store", to the east, a mixed-use commercial and residential building to the south, and a residential apartment building to the west. The Site is 13,675 square feet (0.31 acres) in size. Site Features: The Site is improved with two one-story buildings; one of which is utilized for storage, and the other as a retail building/office space. The buildings do not include cellar levels. There are five 4,000-gallon gasoline/ethanol gasoline USTs and one 550-gallon tank classified as "other" currently in use at the Site. Current Zoning and Land Use: The Site is currently occupied by an active retail petroleum station and is zoned R7-A and R6-B for residential use with a commercial C2-4 overlay. The surrounding properties are currently used for commercial and residential purposes. The nearest residential buildings are directly adjoining to the south and west of the Site. The proposed development of this property is consistent with the current zoning. As a result of the CEQR process, Block 2576 Lot 7 was assigned an environmental E-Designation (E-287) – 209-231 McGuinness Boulevard Rezoning Action, for hazardous materials, noise (window wall attenuation & alternate means of ventilation), and air (HVAC fuel limited to natural gas & exhaust stack location limitations) resulting from a CEQR effective 10 December 2012 (CEQR 10DCP024K). Satisfaction of the E-Designation requirements is subject to review and approval by the NYCOER to obtain a NTP or NNO prior to obtaining building permits. Past Land Use: The Site was developed in the late 1800s and was occupied by commercial, residential, and vacant properties until the early 1940s, from the early 1940s to the late 1970s the Site operated as several auto-related facilities, from the late 1970s through the present the Site has operated as a gasoline filling station. Site Geology and Hydrogeology: The stratigraphy of the Site, from

the surface down, consists primarily of urban fill extending to approximately 5.5 ft bgs (terminus of each soil boring). Groundwater was not encountered during the November 2021 investigation; however, it is anticipated at approximately 7 to 10 ft bgs. Groundwater flow is anticipated toward the northeast.

Assessment:

Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substances (PFAS), and pesticides. Soil vapor was analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern include VOCs, SVOCs (primarily PAHs), and metals. Soil: Exceedances of the Unrestricted Use Soil Cleanup Objectives (UUSCOs) and in some cases Protection of Groundwater Soil Cleanup Objective (PGWSCOs) were primarily found in the historic fill layer which extends from 9 - 13 ft. across the site. In general, the highest concentrations were detected in the upper 10 ft. of site soils. However, elevated concentrations of VOCs and metals did extend into deeper soils (28 - 30 ft.) at SB-1 in the western portion of the site. VOCs detected at levels exceeding UUSCOs and PGWSCOs include: acetone up to 0.09 mg/kg (UUSCO of 0.05 mg/kg), benzene up to 1.4 mg/kg (UUSCO and PGWSCO of 0.6 mg/kg), ethylbenzene up to 74 mg/kg (UUSCO of 1 mg/kg, PGWSCO of 5.5 mg/kg, and RRSCO of 41 mg/kg), isopropyl benzene up to 16 mg/kg (PGWSCO of 2.3 mg/kg), naphthalene up to 69 mg/kg (PGWSCO of 13 mg/kg), n-butylbenzene up to 13 mg/kg (PGWSCO of 12 mg/kg), n-propyl benzene up to 40 mg/kg (PGWSCO of 3.7 mg/kg), toluene up to 12 mg/kg (PGWSCO of 1.5 mg/kg), 1,3,5-trimethylbenzene up to 140 mg/kg (PGWSCO of 3.3 mg/kg), 1,2,4-trimethylbenze up to 340 mg/kg (PGWSCO of 13 mg/kg), and xylenes up to 320 mg/kg (PGWSCO of 1.2 mg/kg). SVOCs detected at levels exceeding UUSCOs and PGWSCOs from 0 - 10 ft. bgs. include: benzo(a) anthracene up to 7.5 mg/kg (PGWSCO of 3 mg/kg), benzo(a)pyrene up to 6.2 mg/kg (PGWSCO 1.1 mg/kg), benzo(b)fluoranthene up to 6.3 mg/kg (PGWSCO of 1.1 mg/kg), benzo(k)fluoranthene up to 1.6 mg/kg (PGWSCO of 1.1 mg/kg), chrysene up to 5.8 mg/kg (PGWSCO of 0.4 mg/kg), dibenzo (a,h)anthracene up to 0.76 mg/kg (UUSCO of 0.33 mg/kg), indeno(1,2,3-cd)pyrene up to 3.8 mg/kg (PGWSCO of 3.2 mg/kg), and naphthalene up to 21 mg/kg (PGWSCO of 13 mg/kg). Metals detected at levels exceeding UUSCOs include: arsenic at a concentration of 13.2 mg/kg (UUSCO of 13 mg/kg), copper up to 77.2 mg/kg (UUSCO of 50 mg/kg), lead up to 590 mg/kg (UUSCO of 63 mg/kg), mercury up to 2.67 mg/kg (UUSCO of 0.18 mg/kg), zinc up to 1,230 mg/kg (UUSCO of 109 mg/kg). The PFAS compounds perfluorooctanoic acid (PFOA) was detected in soil at concentrations above the respective unrestricted use guidance value of 0.66 parts per billion (ppb) at a concentration of 0.695 ppb. Data does not indicate any off-site impacts in soil related to this site. Groundwater: VOCs detected above Class GA Ambient Water Quality Standards (AWQS) include: benzene up to 240 parts per billion (ppb) with an AWQS value of 1 ppb, ethylbenzene up to 5,100 ppb, isopropyl benzene up to 320 ppb, naphthalene up to 660 ppb, n-propyl benzene in one sample at 540 ppb, o-xylene up to 6,800 ppb, p/m-xylene up to 18,000 ppb, sec-butylbenzene up to 11 ppb, tert-butylbenzene up to 6.3 ppb, toluene up to 9,100 ppb, 1.2.4-Tetramethylbenzene in one sample at 140 ppb, 1,2,4-Trimethylbenzene up to 3,3300 ppb, and 1,3,5-Trimethylbenzene in one sample at 790 ppb, all with an AWQS value of 5 ppb. SVOCs detected above AWQS include: acenaphthene with one sample at 110 ppb (AWQS of 20 ppb), naphthalene up to 470 ppb (AWQS of 10 ppb), benzo(a)anthracene up to 0.27 benzo(a)anthracene, benzo(a)pyrene up to 0.13 benzo(a)pyrene, benzo(b)fluoranthene up to 0.19 ppb benzo(k)fluoranthene up to 0.06 ppb, chrysene up to 0.15 ppb, and indeno(1,2,3-c,d) pyrene up to 0.09 ppb, all with an AWQS of 0.002 ppb. Excluding naturally occurring minerals, no metals were detected above their respective AWQS. No pesticides or PCBs were detected above their AWQS either. For PFAS compounds, PFOA and PFOS were reported at concentrations up to 92.2 parts per trillion (ppt) and 55 ppt respectively, exceeding the Maximum Contaminant Levels (MCLs)(drinking water standard) of 10 ppt each in groundwater. The compound 1,4- dioxane was not detected above the MCL of 1 ppb. There are no public water supply wells within a half a mile and there is a municipal prohibition for use of groundwater at the site. Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor: The total cumulative maximum concentrations for benzene, toluene, ethylbenzene, and xylenes (BTEX) compounds was 190.7 micrograms per cubic meter (ug/m3). Multiple VOCs were detected in soil vapor samples collected throughout the site. The most elevated concentrations detected were collected from SG-1 near the former USTs on the west side of the site. This includes: n-hexane, benzene, cyclohexane, 2,2,4-trimethylpentane, and heptane which were detected with maximum concentrations of 356,000 ug/m3, 45,400 ug/m3, 328,000 ug/m3, 2,120,000 ug/m3, and 107,000 ug/m3 respectively. Data does not indicate any off-site impacts in soil vapor related to this site.

Materials Information

Waste Name: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: naphthalene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: toluene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: perfluorooctanoic acid
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: lead
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: chrysene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 19
Sub Type: NNN
Owner Name: Rebecca Crowley
Owner Company: Greenpoint Library
Owner Street: 107 Norman Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 01
Sub Type: E
Owner Name: Jacob Kohn
Owner Company: 210 Greenpoint Realty LLC
Owner Street: 40 Oser Avenue, Suite 4
Owner Street 2:
Owner City: Hauppauge
Owner State: NY
Owner Zip: 11788
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name: Dealice fuller
Owner Company: Brooklyn Commuinty Board 1

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Street: 435 Graham Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11211
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Jacob Kohn
Owner Company: 210 Greenpoint Realty LLC
Owner Street: 40 Oser Avenue, Suite 4
Owner Street 2:
Owner City: Hauppauge
Owner State: NY
Owner Zip: 11788
Country: United States of America

HW Extra Information

Dump:	False	**Record Added:**	2022-03-18 13:24:00
Structure:	False	**Record Updated:**	2023-09-25 19:55:00
Lagoon:	False	**Disposal Start:**	
Landfill:	False	**Disposal Terminate:**	
Pond:	False	**Latitude:**	
Dell:		**Longitude:**	
Updated By:	SMQUANDT		

Projects Information

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2023-02-15 00:00:00
End Status: ACT
Operable Unit ID: 1375824
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Environmental Remediation

Operable Unit: 00
Contaminants: 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, benzene, benzo(a)anthracene, benzo(b)fluoranthene, chrysene, ethylbenzene, indeno(1,2,3-cd)pyrene, isopropylbenzene, lead, mercury, n-propylbenzene, naphthalene, perfluorooctanoic acid, toluene, xylene (mixed)

Operable Unit: 01
Contaminants: 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, benzene, benzo(a)anthracene, benzo(b)fluoranthene, chrysene, ethylbenzene, indeno(1,2,3-cd)pyrene, isopropylbenzene, lead, mercury, n-propylbenzene, naphthalene, perfluorooctanoic acid, toluene, xylene (mixed)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
141	2 of2	S	0.23 / 1,189.03	15.63 / 4	210 Greenpoint Avenue Redevelopment 210 GREENPOINT AVENUE BROOKLYN NY 11222	PFAS CONTAM

Site Code: 628709
HW Code: C224348
Program: BCP
Site Class: A
Site Name: 210 Greenpoint Avenue Redevelopment
Site Address: 210 GREENPOINT AVENUE
City: BROOKLYN
Zip: 11222

County:	Kings
Region:	2
Town:	New York City
Latitude:	40.730200000
Longitude:	-73.951669444
SWIS:	2401
Acres:	0.310
Record Added:	2021-11-23 08:52:00
Record Update:	2024-04-11 21:13:00
Updated by:	SMQUANDT
Site Code (Web):	C224348
Program Type (Web):	BCP
Site Name (Web):	210 Greenpoint Avenue Redevelopment
Site Class (Web):	A
Address1 (Web):	210 GREENPOINT AVENUE
Address2 (Web):	
Locality (Web):	BROOKLYN
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.951669444
Latitude (Web):	40.730200000
Site Code (GIS):	C224348
Site Name (GIS):	210 Greenpoint Avenue Redevelopment
Program (GIS):	BCP
Site Class (GIS):	A
Address1 (GIS):	210 GREENPOINT AVENUE
Address2 (GIS):	
Locality (GIS):	BROOKLYN
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Site Class Desc (Web):	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Assess DOH:	Access to the site is restricted by a fence. The site is covered by concrete foundation slabs and pavement so people are not expected to come in contact with site contaminants in soil. However, persons who enter the site could contact contaminants in the soil by digging below the surface/site cover or otherwise disturbing the soil. Contaminated groundwater is not used for drinking and the site and surrounding areas are served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because the site is vacant, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for any future on-site development. Environmental sampling indicates soil vapor intrusion from site contamination is not a concern for off-site buildings.

Assessment:

Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substances (PFAS), and pesticides. Soil vapor was analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern include VOCs, SVOCs (primarily PAHs), and metals. Soil: Exceedances of the Unrestricted Use Soil Cleanup Objectives (UUSCOs) and in some cases Protection of Groundwater Soil Cleanup Objective (PGWSCOs) were primarily found in the historic fill layer which extends from 9 - 13 ft. across the site. In general, the highest concentrations were detected in the upper 10 ft. of site soils. However, elevated concentrations of VOCs and metals did extend into deeper soils (28 - 30 ft.) at SB-1 in the western portion of the site. VOCs detected at levels exceeding UUSCOs and PGWSCOs include: acetone up to 0.09 mg/kg (UUSCO of 0.05 mg/kg), benzene up to 1.4 mg/kg (UUSCO and PGWSCO of 0.6 mg/kg), ethylbenzene up to 74 mg/kg (UUSCO of 1 mg/kg, PGWSCO of 5.5 mg/kg, and RRSCO of 41 mg/kg), isopropyl benzene up to 16 mg/kg (PGWSCO of 2.3 mg/kg), naphthalene up to 69 mg/kg (PGWSCO of 13 mg/kg), n-butylbenzene up to 13 mg/kg (PGWSCO of 12 mg/kg), n-propyl benzene up to 40 mg/kg (PGWSCO of 3.7 mg/kg), toluene up to 12 mg/kg (PGWSCO of 1.5 mg/kg), 1,3,5-trimethylbenzene up to 140 mg/kg (PGWSCO of 3.3 mg/kg), 1,2,4-trimethylbenze up to 340 mg/kg (PGWSCO of 13 mg/kg), and xylenes up to 320 mg/kg (PGWSCO of 1.2 mg/kg). SVOCs detected at levels exceeding UUSCOs and PGWSCOs from 0 - 10 ft. bgs. include: benzo(a) anthracene up to 7.5 mg/kg (PGWSCO of 3 mg/kg), benzo(a)pyrene up to 6.2 mg/kg (PGWSCO 1.1 mg/kg), benzo(b)fluoranthene up to 6.3 mg/kg (PGWSCO of 1.1 mg/kg), benzo(k)fluoranthene up to 1.6 mg/kg (PGWSCO of 1.1 mg/kg), chrysene up to 5.8 mg/kg (PGWSCO of 0.4 mg/kg), dibenzo (a,h)anthracene up to 0.76 mg/kg (UUSCO of 0.33 mg/kg), indeno(1,2,3-cd)pyrene up to 3.8 mg/kg (PGWSCO of 3.2 mg/kg), and naphthalene up to 21 mg/kg (PGWSCO of 13 mg/kg). Metals detected at levels exceeding UUSCOs include: arsenic at a concentration of 13.2 mg/kg (UUSCO of 13 mg/kg), copper up to 77.2 mg/kg (UUSCO of 50 mg/kg), lead up to 590 mg/kg (UUSCO of 63 mg/kg), mercury up to 2.67 mg/kg (UUSCO of 0.18 mg/kg), zinc up to 1,230 mg/kg (UUSCO of 109 mg/kg). The PFAS compounds perfluorooctanoic acid (PFOA) was detected in soil at concentrations above the respective unrestricted use guidance value of 0.66 parts per billion (ppb) at a concentration of 0.695 ppb. Data does not indicate any off-site impacts in

soil related to this site. Groundwater: VOCs detected above Class GA Ambient Water Quality Standards (AWQS) include: benzene up to 240 parts per billion (ppb) with an AWQS value of 1 ppb, ethylbenzene up to 5,100 ppb, isopropyl benzene up to 320 ppb, naphthalene up to 660 ppb, n-propyl benzene in one sample at 540 ppb, o-xylene up to 6,800 ppb, p/m-xylene up to 18,000 ppb, sec-butylbenzene up to 11 ppb, tert-butylbenzene up to 6.3 ppb, toluene up to 9,100 ppb, 1.2.4-Tetramethylbenzene in one sample at 140 ppb, 1,2,4-Trimethylbenzene up to 3,3300 ppb, and 1,3,5-Trimethylbenzene in one sample at 790 ppb, all with an AWQS value of 5 ppb. SVOCs detected above AWQS include: acenaphthene with one sample at 110 ppb (AWQS of 20 ppb), naphthalene up to 470 ppb (AWQS of 10 ppb), benzo(a)anthracene up to 0.27 benzo(a)anthracene, benzo(a)pyrene up to 0.13 benzo(a)pyrene, benzo(b)fluoranthene up to 0.19 ppb benzo(k)fluoranthene up to 0.06 ppb, chrysene up to 0.15 ppb, and indeno(1,2,3-c,d) pyrene up to 0.09 ppb, all with an AWQS of 0.002 ppb. Excluding naturally occurring minerals, no metals were detected above their respective AWQS. No pesticides or PCBs were detected above their AWQS either. For PFAS compounds, PFOA and PFOS were reported at concentrations up to 92.2 parts per trillion (ppt) and 55 ppt respectively, exceeding the Maximum Contaminant Levels (MCLs)(drinking water standard) of 10 ppt each in groundwater. The compound 1,4- dioxane was not detected above the MCL of 1 ppb. There are no public water supply wells within a half a mile and there is a municipal prohibition for use of groundwater at the site. Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor: The total cumulative maximum concentrations for benzene, toluene, ethylbenzene, and xylenes (BTEX) compounds was 190.7 micrograms per cubic meter (ug/m3). Multiple VOCs were detected in soil vapor samples collected throughout the site. The most elevated concentrations detected were collected from SG-1 near the former USTs on the west side of the site. This includes: n-hexane, benzene, cyclohexane, 2,2,4-trimethylpentane, and heptane which were detected with maximum concentrations of 356,000 ug/m3, 45,400 ug/m3, 328,000 ug/m3, 2,120,000 ug/m3, and 107,000 ug/m3 respectively. Data does not indicate any off-site impacts in soil vapor related to this site.

Description:

Site Location: The Site's address is 210 Greenpoint Avenue, Brooklyn, NY 11222. The Site is located in Kings County, New York and is identified as Block 2576 Lot 7. The Site is located in a mixed-use residential and commercial section of the Greenpoint neighborhood of Brooklyn, NY on the south side of Greenpoint Avenue between McGuinness Boulevard and Eckford Street. The Site is located approximately 0.5 miles west of Newtown Creek. The Site is bounded by Greenpoint Avenue followed by mixed-use commercial and residential buildings to the north, McGuinness Boulevard followed by a commercial building, "Key Foods Grocery Store", to the east, a mixed-use commercial and residential building to the south, and a residential apartment building to the west. The Site is 13,675 square feet (0.31 acres) in size. Site Features: The Site is improved with two one-story buildings; one of which is utilized for storage, and the other as a retail building/office space. The buildings do not include cellar levels. There are five 4,000-gallon gasoline/ethanol gasoline USTs and one 550-gallon tank classified as "other" currently in use at the Site. Current Zoning and Land Use: The Site is currently occupied by an active retail petroleum station and is zoned R7-A and R6-B for residential use with a commercial C2-4 overlay. The surrounding properties are currently used for commercial and residential purposes. The nearest residential buildings are directly adjoining to the south and west of the Site. The proposed development of this property is consistent with the current zoning. As a result of the CEQR process, Block 2576 Lot 7 was assigned an environmental E-Designation (E-287) – 209-231 McGuinness Boulevard Rezoning Action, for hazardous materials, noise (window wall attenuation & alternate means of ventilation), and air (HVAC fuel limited to natural gas & exhaust stack location limitations) resulting from a CEQR effective 10 December 2012 (CEQR 10DCP024K). Satisfaction of the E-Designation requirements is subject to review and approval by the NYCOER to obtain a NTP or NNO prior to obtaining building permits. Past Land Use: The Site was developed in the late 1800s and was occupied by commercial, residential, and vacant properties until the early 1940s, from the early 1940s to the late 1970s the Site operated as several auto-related facilities, from the late 1970s through the present the Site has operated as a gasoline filling station. Site Geology and Hydrogeology: The stratigraphy of the Site, from the surface down, consists primarily of urban fill extending to approximately 5.5 ft bgs (terminus of each soil boring). Groundwater was not encountered during the November 2021 investigation; however, it is anticipated at approximately 7 to 10 ft bgs. Groundwater flow is anticipated toward the northeast.

Materials Information

Waste Name: perfluorooctanoic acid
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: naphthalene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: toluene
Waste Quantity: UNKNOWN

Waste Code:

Waste Name: benzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: lead
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: chrysene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 01
Sub Type: E
Owner Name: Jacob Kohn
Owner Company: 210 Greenpoint Realty LLC
Owner Street: 40 Oser Avenue, Suite 4
Owner Street 2:
Owner City: Hauppauge
Owner State: NY
Owner Zip: 11788
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name: Rebecca Crowley
Owner Company: Greenpoint Library
Owner Street: 107 Norman Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Jacob Kohn
Owner Company: 210 Greenpoint Realty LLC
Owner Street: 40 Oser Avenue, Suite 4
Owner Street 2:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner City: Hauppauge
Owner State: NY
Owner Zip: 11788
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name: Dealice fuller
Owner Company: Brooklyn Commuinty Board 1
Owner Street: 435 Graham Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11211
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: SMQUANDT

Record Added: 2022-03-18 13:24:00
Record Updated: 2023-09-25 19:55:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Projects Information

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2023-02-15 00:00:00
End Status: ACT
Operable Unit ID: 1375824
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Environmental Remediation

Operable Unit: 01
Contaminants: 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, benzene, benzo(a)anthracene, benzo(b)fluoranthene, chrysene, ethylbenzene, indeno(1,2,3-cd)pyrene, isopropylbenzene, lead, mercury, n-propylbenzene, naphthalene, perfluorooctanoic acid, toluene, xylene (mixed)

Operable Unit: 00
Contaminants: 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, benzene, benzo(a)anthracene, benzo(b)fluoranthene, chrysene, ethylbenzene, indeno(1,2,3-cd)pyrene, isopropylbenzene, lead, mercury, n-propylbenzene, naphthalene, perfluorooctanoic acid, toluene, xylene (mixed)

142	1 of1	WSW	0.23 / 1,191.50	27.09 / 15	CON EDISON SERVICE BOX: 8624 143 JAVA ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004311346
Gen Status Universe: No Report
Contact Name: ANTHONY SIGNORE
Contact Address:
Contact Phone No and Ext: 718-666-4714
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20130613

Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20130513
Handler Name: CON EDISON SERVICE BOX: 8624
Source Type: Emergency
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20130613
Handler Name: CON EDISON SERVICE BOX: 8624
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20130513
Generator Code Description: Very Small Quantity Generator
Handler Name: CON EDISON SERVICE BOX: 8624

143	*1 of1*	*WNW*	*0.23 / 1,195.38*	*14.85 / 3*	***CON EDISON - TRANSFORMER MANHOLE 658*** ***120 DUPONT ST & MANHATTAN AVE*** ***BROOKLYN NY 11222***	***RCRA LQG***

EPA Handler ID: NYP004871584

Gen Status Universe:	Large Quantity Generator
Contact Name:	THERESA BURKARD
Contact Address:	4 , IRVING PLACE, 15TH FL NE , , NEW YORK , NY, 10003 , US
Contact Phone No and Ext:	212-460-2262
Contact Email:	BURKARDT@CONED.COM
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20160226
Location Latitude:	40.735863
Location Longitude:	-73.955178
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20160226
Handler Name:	CON EDISON - TRANSFORMER MANHOLE 658
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator
Source Type:	Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	4
Type:	Private	**Street 1:**	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20151119	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY

Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003
Owner/Operator Ind:	Current Operator	**Street No:**	4
Type:	Private	**Street 1:**	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	**Street 2:**	
Dt Became Current:	20151119	**City:**	NEW YORK
Dt Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	10003

144 **1 of1** **SE** **0.23 / 1,202.31** **8.95 / -3**

CON EDISON MANHOLE: 8172
213 JEWEL ST
BROOKLYN NY 11222

RCRA NON GEN

EPA Handler ID:	NYP004289914
Gen Status Universe:	No Report
Contact Name:	ANTHONY SIGNORE
Contact Address:	
Contact Phone No and Ext:	718-802-3008
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20130328
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20130228
Handler Name:	CON EDISON MANHOLE: 8172
Source Type:	Emergency
Federal Waste Generator Code:	3

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Generator Code Description: Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20130328
Handler Name: CON EDISON MANHOLE: 8172
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20130228
Generator Code Description: Very Small Quantity Generator
Handler Name: CON EDISON MANHOLE: 8172

145	1 of1	SW	0.23 / 1,203.56	28.13 / 16	CON EDISON SERVICE BOX: 08133 157 GREENPOINT AVE BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004441994
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20140314
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20140214
Handler Name:	CON EDISON SERVICE BOX: 08133
Source Type:	Emergency
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20140314
Handler Name:	CON EDISON SERVICE BOX: 08133
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Historical Handler Details

Receive Dt:	20140214
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CON EDISON SERVICE BOX: 08133

146	*1 of1*	*SW*	*0.23 / 1,209.65*	*30.01 / 18*	***CON EDISON 916 MANHATTAN AVE BROOKLYN NY 11222***	***RCRA NON GEN***

EPA Handler ID:	NYP004736971
Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20150224
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No

Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150224
Handler Name:	CON EDISON
Source Type:	Emergency
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150224
Handler Name:	CON EDISON
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Historical Handler Details

Receive Dt:	20150224
Generator Code Description:	Small Quantity Generator
Handler Name:	CON EDISON

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
147	1 of1	SW	0.23 / 1,230.05	31.38 / 19	CON EDISON - MANHOLE 4328 MANHATTAN AVE & KENT ST INT BROOKLYN NY 11222	RCRA LQG

EPA Handler ID:	NYP005151725
Gen Status Universe:	Large Quantity Generator
Contact Name:	ALYSSA SOTTO
Contact Address:	4 , IRVING PLACE, 15TH FL NE , , NEW YORK , NY, 10003 , US
Contact Phone No and Ext:	212-460-2757
Contact Email:	SOTTOA@CONED.COM
Contact Country:	US
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20180410
Location Latitude:	40.730904
Location Longitude:	-73.954341
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No

Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20180410
Handler Name:	CON EDISON - MANHOLE 4328
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator
Source Type:	Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	4
Type:	Private	***Street 1:***	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	***Street 2:***	
Dt Became Current:	20180118	***City:***	NEW YORK
Dt Ended Current:		***State:***	NY
Phone:	212-460-2757	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	10003

Owner/Operator Ind:	Current Operator	***Street No:***	4
Type:	Private	***Street 1:***	IRVING PLACE
Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.	***Street 2:***	
Dt Became Current:	20180118	***City:***	NEW YORK
Dt Ended Current:		***State:***	NY
Phone:	212-460-2757	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	10003

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
148	1 of1	W	0.23 / 1,231.45	13.76 / 2	132-140 GREEN STREET 132-140 GREEN STREET NEW YORK CITY NY	LST

Spill No:	0011967	***REM Phase:***	0
Site ID:	91808	***UST Trust:***	False
DER Facility ID:	82488	***Spill Date:***	02/03/2001 01:00:00 PM
CID:	389	***Rcvd Date:***	02/06/2001 05:08:00 PM
Program Type:	ER	***CAC Date:***	
SWIS Code:	3101	***Insp Date:***	
Contribute Factor:	Tank Overfill	***Close Date:***	04/11/2003 12:00:00 AM
Water Body:		***Create Date:***	02/06/2001 12:00:00 AM
Class:	C4	***Update Date:***	04/11/2003 12:00:00 AM
Meets Std:	False	***DEC Region:***	2

Penalty:	False	**Lead DEC:**	MCTIBBE
County:	New York	**After Hours:**	True
Referred to:			
Reported by:	Affected Persons		
Source:	Private Dwelling		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"SPILL INSIDE AND OUTSIDE A RESIDENCE UNK QUANTITY PETROLEUM TANK CLEANERS RESPONDED AND ACCESSED THE SITUATION AND WILL BE BACK TOMORROW FOR CLEAN UP. NO CALLBACK NECESSARY"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE PTC INVESTIGATED. PRESSURED WASH TOMORROW. ALLIED TRANSPORTATION DELIVERED FOR HESS. HE WAS NOTIFIED TODAY AT 1200HRS. CLEANED BY HESS."

Material Information

OP Unit ID:	833328	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	542254	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0002A		
Material Name:	#4 fuel oil		

Spiller Information

Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller City:	UNKNOWN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	RAYMOND
Contact Phone:	(917) 523-3075
Contact Ext:	
Latitude:	40.725127410
Longitude:	-73.999142650

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
149	1 of1	N	0.24 / 1,244.06	8.55 / -3	SUNOCO MIDSTREAM LLC BROOKLYN NY	BULK TERMINAL

PADD:	1	**Crude Oil:**	
FID:		**Jetfuel:**	
Term ID:		**Gasoline:**	
Site:	BROOKLYN	**Distillate:**	
Facility Type:		**Avgas:**	
Station Type:		**Period:**	June 2023
Status:		**Truck In:**	
Handling:		**Truck Out:**	
Telephone:		**Pipe In:**	
Population:		**Pipe Out:**	
Source Date:		**Marine In:**	
Val Method:		**Marine Out:**	
Val Date:		**Rail In:**	
Exstars I:		**Rail Out:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Posrel:		**County Fips:**	
Capacity:		**County:**	
Asphalt:		**Zip:**	
Chemicals:		**Zip4:**	
Propane:		**Country:**	
Butane:		**Latitude:**	40.737141
Refined:		**Longitude:**	-73.951564
Ethanol:		**X:**	-8232250.4478
Biodiesel:		**Y:**	4973646.9932
Owner:			
Operator:			
Address:			
Commodity:			
NAICS Code:			
NAICS Desc:			
Source:	Form EIA-815, Monthly Terminal Blenders Report		
Website:			
Data Source:	U.S. Energy Information Administration (EIA) Petroleum Product Terminals (GIS)		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
150	1 of 1	N	0.24 / 1,254.22	8.15 / -4	BROOKLYN TERMINAL - SUNOCO LLC BROOKLYN NY	PFAS IND

Status:	Active	**Fac Fips Code:**	36047
Fac Indian Cntry Flg:	No	**Compliance Status:**	No Violation Identified
Fac Derived Huc:	02030201	**EPA Programs:**	CAA; CWA; RCRA
Fac Derived Wbd:	020301010405	**Federal Facility:**	No
Fac Derived Cd113:	12	**Federal Agency:**	-
Fac Derived Cb2010:	360470579002003	**Fac Snc Flg:**	No
Fac Informal Count:	1	**AIR Flag:**	Yes
Last Informal Action:	9/21/2023	**NPDES Flag:**	Yes
Formal Action Count:	0	**SDWIS Flag:**	No
Last Formal Action:	-	**RCRAFlag:**	Yes
Fac Total Penalties:	0	**TRI Flag:**	No
Fac Penalty Count:	-	**GHG Flag:**	No
Date Last Penalty:	-	**TRI IDs:**	11222MTVNT25PAI
Last Penalty Amt:	-	**TRI Releases Trnsfrs:**	-
Fac Qtrs With Nc:	1	**TRI on Site Releases:**	-
Programs With Snc:	0	**TRI off Site Trnsfrs:**	-
Fac Percent Minority:	44.514	**TRI Reporter:**	-
Fac Pop Den:	49065.77	**Fac Imp Water Flg:**	Yes
Count:	1	**Fac Major Flag:**	Yes
Fac County:	KINGS	**Fac Active Flag:**	Yes
State Other :		**Fac Inspection Count:**	6
Region:	02	**Date Last Inspection:**	5/2/2024
Latitude:	40.73716	**Days Last Inspection:**	142
Longitude:	-73.95166		
Fac Derived Tribes:	-		
AIR IDs:	NY0000002610100105		
CAA Permit Types:	Major Emissions		
CAA NAICS:	424710 454311		
CAA SICS:	4226		
NPDES IDs:	NY0006131		
CWA Permit Types:	Non-M		
CWA NAICS:	-		
CWA SICS:	5171		
RCRA IDs:	NY0000998849 NYD000632141		
RCRA Permit Types:	Other, VSQG		
RCRA NAICS:	493110		
SDWA IDs:	-		
SDWA System Types:	-		
SDWA Compliance Status:	-		
SDWA Snc Flag:	No		
Fac Collection Meth:	ADDRESS MATCHING-HOUSE NUMBER		
EJSCREEN Flag Us:	Yes		
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.95166,%22y%22:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

40.73716,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

ECHO Facility Report: https://echo.epa.gov/detailed-facility-report?fid=110000323436

Industry: Petroleum

---

151 | ***1 of1*** | ***NW*** | ***0.24 / 1,259.50*** | ***14.65 / 3*** | ***DUPONT ASSOC***
127 DUPONT ST
Brooklyn NY 11222 | ***AST***

Site ID:	4632	***Expiry:***	N/A
Site Status:	Unregulated/Closed	***County:***	Kings
Program No:	2-150843	***UTM X:***	588260.00111
Program Type Code:	PBS	***UTM Y:***	4509978.78354
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Unknown		

Tank Information

Prog No:	2-150843	***UDC Ind:***	1
Tank ID:	40095	***Red Tag Start Date:***	
Tank No:	001	***Red Tag End Date:***	
Tank Status:	6	***Tank Last Test:***	
Tank Status Desc:	Closed Prior to 03/1991	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:		***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	4000	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: I00
Code Name: None
Type: Overfill

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Affiliation Information

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: ZZZ
Company: DUPONT ASSOC
Contact Title:
Contact Name:
Address1: 32 COURT ST
Address2:
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 855-0740
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: DUPONT ASSOC
Contact Title:
Contact Name:
Address1: 32 COURT ST
Address2:
City: BROOKLYN
State: NY
Zip Code: 11201
Country Code: 001
Phone: (718) 855-0740
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: DUPONT ASSOC
Contact Title:
Contact Name: WM L HIGGINS
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 287-5500
Phone Ext:
Email:
Fax:

Affiliation Type:	04
Affiliation Name:	Facility Operator
Affiliation Sub Type:	NNN
Company:	DUPONT ASSOC
Contact Title:	
Contact Name:	CARMAN
Address1:	
Address2:	
City:	
State:	NN
Zip Code:	
Country Code:	001
Phone:	(718) 855-0740
Phone Ext:	
Email:	
Fax:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
152	1 of1	SSW	0.24 / 1,272.25	28.25 / 16	CON EDISON 178 GREENPOINT AVE BROOKLYN NY 11235	RCRA NON GEN

EPA Handler ID:	NYP004802682
Gen Status Universe:	No Report
Contact Name:	THOMAS TEELING
Contact Address:	
Contact Phone No and Ext:	212-460-3770
Contact Email:	
Contact Country:	
County Name:	KINGS
EPA Region:	02
Land Type:	Private
Receive Date:	20150706
Location Latitude:	
Location Longitude:	
Recycler Activity?:	NO
Recycler Activity Note:	This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No
Recycler Activity:	No
Recycler Activity Without Storage:	No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150706
Handler Name: CON EDISON
Source Type: Emergency
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150706
Handler Name: CON EDISON
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20160205
Handler Name: CON EDISON - SERVICE BOX 8136
Source Type: Annual/Biennial Report update with Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Date Became Current: 20150706
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report update with Notification
Street No: 4
Street 1: IRVING PLACE
Street 2:
City: NEW YORK
State: NY
Country: US
Zip Code: 10003

Owner/Operator Ind: Current Operator
Type: Private
Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Date Became Current: 20150706
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report update with Notification
Street No: 4
Street 1: IRVING PLACE
Street 2:
City: NEW YORK
State: NY
Country: US
Zip Code: 10003

Historical Handler Details

Receive Dt: 20160205
Generator Code Description: Large Quantity Generator
Handler Name: CON EDISON - SERVICE BOX 8136

Receive Dt: 20150706
Generator Code Description: Small Quantity Generator
Handler Name: CON EDISON

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
153	1 of1	WNW	0.24 / 1,280.75	14.97 / 3	CON EDISON 131 EAGLE ST BROOKLYN NY 11222	RCRA NON GEN

EPA Handler ID: NYP004884124
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20151228
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20151228
Handler Name: CON EDISON
Source Type: Emergency
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20151228
Handler Name: CON EDISON
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Historical Handler Details

Receive Dt: 20151228
Generator Code Description: Small Quantity Generator
Handler Name: CON EDISON

---

154 | ***1 of1*** | ***SSW*** | ***0.24 / 1,288.27*** | ***27.82 / 16*** | ***186 Greenpoint Avenue 186 Greenpoint Avenue Brooklyn NY*** | ***OER CLEANUP***

Class: Completed (C)
Phase: Completed
BIN: 3025750005
Postcode: 1
Community Board: 33
Council District: 575
Census Tract: 3065149
Latitude: 40.730311
Longitude: -73.952950
BBL: 3025750005
OER Program: VCP (Enrolled), E/RD (Review)
NTA: Greenpoint
Project Docs URL: https://a002-epic.nyc.gov/app/workspace/1749/docrepository

---

155 | ***1 of1*** | ***W*** | ***0.25 / 1,310.09*** | ***14.74 / 3*** | ***CON EDISON 132 HURON ST BROOKLYN NY 11222*** | ***RCRA NON GEN***

EPA Handler ID: NYP004813750
Gen Status Universe: No Report
Contact Name: THOMAS TEELING
Contact Address:
Contact Phone No and Ext: 212-460-3770
Contact Email:
Contact Country:
County Name: KINGS
EPA Region: 02
Land Type: Private
Receive Date: 20150929
Location Latitude:
Location Longitude:
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Violation/Evaluation Summary

Note: NO RECORDS: As of Oct 2024, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity: No
Recycler Activity Without No

Storage:

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150929
Handler Name: CON EDISON
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150929
Handler Name: CON EDISON
Source Type: Emergency
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Historical Handler Details

Receive Dt: 20150929
Generator Code Description: Small Quantity Generator
Handler Name: CON EDISON

---

156 | ***1 of1*** | ***WSW*** | ***0.25 / 1,313.93*** | ***30.84 / 19*** | ***ST. ELIAS GREEK RITE ROMAN CATH. CHURCH***
147 KENT STREET
BROOKLYN NY 11222 | ***AST***

Site ID: 28224
Site Status: Active
Program No: 2-606361
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Other
Expiry: 10/10/2027
County: Kings
UTM X: 588276.28462
UTM Y: 4509370.88018

Tank Information

Prog No: 2-606361
Tank ID: 61310
Tank No: 001
Tank Status: 1
Tank Status Desc: In Service
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 06/01/1953
Close Date:
Tk Out of Serv Dt:
Capacity (Gal): 1500
Registered: True
Tank Model:
Pipe Model:
UDC Ind: 0
Red Tag Start Date:
Red Tag End Date:
Tank Last Test: 05/08/2006
Tank Next Test Due:
Test Method: 21
Line Last Test Due:
Next Line Test Due:
Line Test Method: -
Class A Operator:
Class B Operator:
Modified by: JSMACRI
Last Modified: 12/06/2022
Tank Location: 6
Tank Location Desc: Aboveground in Subterranean Vault w/ access for inspections
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: KSENIA MOLLER
Tank Owner Address: 30 WEST 69TH STREET NEW YORK, NY. 10023

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: I05
Code Name: Vent Whistle
Type: Overfill

Affiliation Information

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: HWH KENT, LLC
Contact Title: PROPERTY MANAGER
Contact Name: KSENIA MOLLER
Address1: 30 WEST 69TH STREET
Address2:
City: NEW YORK
State: NY
Zip Code: 10023
Country Code: 001
Phone: (347) 672-7321

Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: HERBERT W. HIRSCH ENTERPRISES, INC.
Contact Title:
Contact Name: HERBERT HIRSCH
Address1: 30 WEST 69TH STREET
Address2:
City: NEW YORK
State: NY
Zip Code: 10023
Country Code: 001
Phone: (347) 672-7321
Phone Ext:
Email: HWH@HIRSCHENTINC.COM
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: HWH KENT, LLC
Contact Title:
Contact Name: HURBERT HIRSCH
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 999
Phone: (347) 672-7321
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: ST. ELIAS GREEK RITE ROMAN CATH. CHURCH
Contact Title:
Contact Name: H. HIRSCH
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (718) 767-8936
Phone Ext:
Email:
Fax:

157	***1 of1***	***NE***	***0.26 / 1,371.75***	***3.49 / -9***	***Perez Interboro Asphalt C 99 Paidge Avenue Brooklyn NY 0***	***SWF/LF***

Activity Number: [24W08]
Facility Name (Act):
Location Addr (Act):
Location Addr2 (Act):
City (Act):
State (Act):
Zip Code (Act):
County (Act):
East Coord (Act):

Facility Name (InAct): Perez Interboro Asphalt C
Location Addr (InAct): 99 Paidge Avenue
Loc Addr2(InAct):
City (InAct): Brooklyn
State (InAct): NY
Zip Code (InAct): 0
County (InAct): Kings
East Coord (InAct): 0
North Coord (InAct): 0

North Coord (Act):
Facility Name:
Location Addr:
Location Addr2:
City:
State:
Zip Code:
County:
East Coord:
North Coord:
Data Source: SWMF - Inactive Facility Lists

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		***Authorization No:***	0
Activity Desc:	C&D processing - registration	***Authrzation Issue Dt:***	
Regulatory Status:	Registration	***Operator Type:***	
Active:	No	***Operator Name:***	
Dt of Last Inspection:		***Phone No:***	7183834100
Expiration Dt:		***Region:***	2
Owner Type:	Private	***Contact Name:***	
Owner Name:	Perez Interboro Asphalt Co.; I	***Contact Address:***	
Owner Address:	99 Paidge Avenue	***Contact Address2:***	
Owner Address2:		***Contact City:***	
Owner City:	Brooklyn	***Contact State:***	
Owner State:	NY	***Contact Zip:***	
Owner Zip:	11222	***Contact Phone:***	
Owner Phone:	7183834100	***Contact Email:***	
Owner Email:			
Waste Types:			

---

158 ***1 of4*** ***N*** ***0.26 / 1,398.14*** ***6.19 / -6*** ***BROOKLYN - SUNOCO LLC***
25 PAIDGE AVENUE
BROOKLYN NY 11222 ***MOSF***

Site ID:	344636	***Expiration Date:***	03/31/2025
Site Status:	Active	***DEC Region:***	2
Program No:	2-1540	***County:***	Kings
Program Type Code:	MOSF	***UTM X:***	588490.39702
Program Type Desc:	Major Oil Storage Facility Program	***UTM Y:***	4510139.38787
Site Type:	Storage Terminal/Petroleum Distributor		
More Info:	http://www.dec.ny.gov/chemical/287.html		

---

158 ***2 of4*** ***N*** ***0.26 / 1,398.14*** ***6.19 / -6*** ***MOTIVA***
25 PAIDGE AVENUE
BROOKLYN NY ***LST***

Spill No:	9413568	***REM Phase:***	0
Site ID:	264923	***UST Trust:***	False
DER Facility ID:	215870	***Spill Date:***	01/11/1995 12:01:00 AM
CID:		***Rcvd Date:***	01/11/1995 04:30:00 PM
Program Type:	ER	***CAC Date:***	
SWIS Code:	2401	***Insp Date:***	
Contribute Factor:	Tank Failure	***Close Date:***	10/28/2003 12:00:00 AM
Water Body:		***Create Date:***	02/02/1995 12:00:00 AM
Class:	B3	***Update Date:***	03/22/2004 12:00:00 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	SIGONA
County:	Kings	***After Hours:***	False
Referred to:			
Reported by:	Responsible Party		
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"FOUND CONTAMINATION IN MONITOR WELLs 15 & 16 -EXCAVATION DONE -SOIL CONTAMINATED FURTHER INVESTIGATION BEING DONE."

Dec Remark:

""

Material Information

OP Unit ID:	1011128	***Med in Air:***	False
OU:	01	***Med GW:***	True
Material ID:	372312	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	MARIO D'ANTONIO
Spiller Company:	MOTIVA
Spiller Address:	1100 LOUISIANA STREET
Spiller City:	HOUSTON
Spiller State:	TX
Spiller Zip:	77002-
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.737209180
Longitude:	-73.951612510

158	***3 of4***	***N***	***0.26 / 1,398.14***	***6.19 / -6***	***MOTIVA 25 PAIDGE AVENUE BROOKLYN NY***	***LST***

Spill No:	8703522	***REM Phase:***	0
Site ID:	264920	***UST Trust:***	False
DER Facility ID:	215870	***Spill Date:***	07/25/1987 02:00:00 AM
CID:		***Rcvd Date:***	07/30/1987 11:30:00 AM
Program Type:	ER	***CAC Date:***	07/30/1987 12:00:00 AM
SWIS Code:	2401	***Insp Date:***	
Contribute Factor:	Tank Overfill	***Close Date:***	07/30/1987 12:00:00 AM
Water Body:		***Create Date:***	07/31/1987 12:00:00 AM
Class:	B3	***Update Date:***	10/28/2003 12:00:00 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	SIGONA
County:	Kings	***After Hours:***	False
Referred to:			
Reported by:	Responsible Party		
Source:	Tank Truck		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"TANK TRUCKER OVERFILLED HIS VEHICLE. SPILL WENT THROUGH DRAIN ON PLATFORM TO THE OIL SEPARATOR. CLEANED-UP."

Dec Remark:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

""

Material Information

OP Unit ID:	907408	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	469754	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	ISLAND TRANSPORTATION
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.737209180
Longitude:	-73.951612510

158	*4 of4*	*N*	*0.26 / 1,398.14*	*6.19 / -6*	***Arc Terminals New York Holdings, LLC 25 Paidge Ave Brooklyn NY***	***PFAS***

Facility ID:	BSF0347	***County:***	Kings
Survey Complete:	YES		
Survey:	Class B Fire Suppression Foam Usage Survey - New York State Bulk Storage Facilities		
Q. 6:	YES		
Q. 7:	YES		
Q. 8:	unknown		
Q. 9:	unknown		
Q. 10:	unknown		
Q. 11:	unknown		
Q. 12:			
Q. 13:			

Reference:

If a respondent indicated that the facility used/stored/disposed PFOA/PFOS substances, it does not necessarily mean that there is an environmental/public health concern associated with that facility. Also, if a respondent indicated that they currently/formerly used, stored, disposed of, or released Class B firefighting foam it does not necessarily mean that the foam contains/contained PFOA/PFOS since many Class B foams do not contain these substances. DEC is in the process of reviewing/evaluating the returned surveys to determine if additional follow-up or study is needed.
Return rate: 91 surveys were sent to facilities; 90 were returned completed as of June 1, 2017.
Questions 1 & 2 relate to name and address; questions 3-5 relate to facility ownership.
Q. 6: Is any Class B fire suppression foam currently stored and/or used at the facility?
Q. 7: Has any Class B fire suppression foam ever been stored and/or used at the facility?
Q. 8: Has Class B fire suppression foam ever been used for training purposes at the facility?
Q. 9: Has Class B fire suppression foam ever been used for firefighting or other emergency response purposes at the facility?
Q. 10: Has the facility ever experienced a spill or leak of Class B fire suppression foam?
Q. 11: Has your facility ever been responsible for the use of Class B fire suppression foam at a location other than the facility (i.e. offsite training, emergency response, or spill)?

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
159	1 of2	SE	0.27 / 1,403.94	9.02 / -3	Greenpoint Scrap Metal 304 Greenpoint Avenue Brooklyn NY 11222	SWF/LF

Activity Number:	[24M00]	**Facility Name (InAct):**	
Facility Name (Act):	Greenpoint Scrap Metal	**Location Addr (InAct):**	
Location Addr (Act):	304 Greenpoint Avenue	**Loc Addr2(InAct):**	
Location Addr2 (Act):		**City (InAct):**	
City (Act):	Brooklyn	**State (InAct):**	
State (Act):	NY	**Zip Code (InAct):**	
Zip Code (Act):	11222	**County (InAct):**	
County (Act):	Kings	**East Coord (InAct):**	
East Coord (Act):	588653;588875;589120	**North Coord (InAct):**	
North Coord (Act):	4509421;4509644;4509887		
Facility Name:	Greenpoint Scrap Metal		
Location Addr:	304 Greenpoint Avenue		
Location Addr2:			
City:	Brooklyn		
State:	NY		
Zip Code:	11222		
County:	Kings		
East Coord:	588653;588875;589120		
North Coord:	4509421;4509644;4509887		
Data Source:	SWMF - Active Facility Lists; SWMF - Active Solid Waste Management Facilities as of 08-17-2023		

SWMF - Active Facility Lists Details(Act)

Accuracy Code:		**Authorization No:**	
Activity Desc:	RHRF - exempt (non-VDF)	**Authrzation Issue Dt:**	
Regulatory Status:	Exempt	**Operator Type:**	
Active:	Yes	**Operator Name:**	Allocco Recycling Ltd.
Dt of Last Inspection:	2/14/2019	**Phone No:**	7183493094
Expiration Dt:		**Region:**	2
Owner Type:	Private	**Contact Name:**	Michael Allocco Jr
Owner Name:	Michael Allocco	**Contact Address:**	
Owner Address:	540 Kingsland Avenue	**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:	Brooklyn	**Contact State:**	
Owner State:	NY	**Contact Zip:**	
Owner Zip:	11222	**Contact Phone:**	7183493094
Owner Phone:	7183493094	**Contact Email:**	mike@alloccorecycling.com
Owner Email:			
Waste Types:			

SWMF - Active Facility Lists Details(Act)

Accuracy Code:		**Authorization No:**	
Activity Desc:	RHRF - exempt (non-VDF)	**Authrzation Issue Dt:**	
Regulatory Status:	None	**Operator Type:**	
Active:	Yes	**Operator Name:**	
Dt of Last Inspection:		**Phone No:**	7183893000
Expiration Dt:		**Region:**	2
Owner Type:	Private	**Contact Name:**	
Owner Name:	The Fortune Group	**Contact Address:**	
Owner Address:	239 India Street	**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:	Brooklyn	**Contact State:**	
Owner State:	NY	**Contact Zip:**	
Owner Zip:	11222	**Contact Phone:**	
Owner Phone:	7183893000	**Contact Email:**	
Owner Email:			
Waste Types:			

SWMF - Active Facility Lists Details(Act)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Regulatory Status: Exempt
Active: Yes
Dt of Last Inspection:
Expiration Dt:
Owner Type: Private
Owner Name: Alan Friedman
Owner Address: 203 Vineland Avenue
Owner Address2:
Owner City: Staten Island
Owner State: NY
Owner Zip: 10312
Owner Phone:
Owner Email: ibyscrap@aol.com
Waste Types:

Authorization No:
Authrzation Issue Dt:
Operator Type:
Operator Name:
Phone No: 7183893200
Region: 2
Contact Name:
Contact Address:
Contact Address2:
Contact City:
Contact State:
Contact Zip:
Contact Phone:
Contact Email:

Active Solid Waste Management Facilities Details as of 08-17-2023

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Active: Yes
Expiration Dt:
Geo Reference: 540 Kingsland Avenue
Brooklyn, NY 11222
(40.735029397, -73.944583868)
Region: 2
Waste Types:

Authorization No:
Authrzation Issue Dt:
Owner Type: Private
Owner Name: Michael Allocco
Phone No: 7183493094

Active Solid Waste Management Facilities Details as of 08-17-2023

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Active: Yes
Expiration Dt:
Geo Reference: 304 Greenpoint Avenue
Brooklyn, NY 11222
(40.730872811, -73.947550894)
Region: 2
Waste Types:

Authorization No:
Authrzation Issue Dt:
Owner Type: Private
Owner Name: Alan Friedman
Phone No: 7183893200

Active Solid Waste Management Facilities Details as of 08-17-2023

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Active: Yes
Expiration Dt:
Geo Reference: 239 India Street
Brooklyn, NY 11222
(40.732846582, -73.950204269)
Region: 2
Waste Types:

Authorization No:
Authrzation Issue Dt:
Owner Type: Private
Owner Name: The Fortune Group
Phone No: 7183893000

159	2 of2	SE	0.27 / 1,403.94	9.02 / -3	**Greenpoint Scrap Metal** **304 Greenpoint Avenue** **Brooklyn NY 11222**	RECYCLING

East Coordinate: 588875
North Coordinate: 4509421
County: Kings
Location Address2:

Details

Activity No: [24M00]
Authorization No:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Active: Yes
Activity Desc: RHRF - exempt (non-VDF)
Region: 2
Phone No: 7183893200
Accuracy Code:
Waste Types:
Georeference: 304 Greenpoint Avenue
Brooklyn, NY 11222
(40.730872811, -73.947550894)

Auth Issue Date:
Expiration DT:
Owner Type: Private
Owner Name: Alan Friedman

---

160 | **1 of1** | **NW** | **0.27 / 1,438.63** | **10.57 / -1** | **Spill Number 0010491**
64 BOX ST
BROOKLYN NY | **LST**

Spill No: 0010491
Site ID: 319948
DER Facility ID: 257785
CID: 233
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Overfill
Water Body:
Class: C3
Meets Std: False
Penalty: False
County: Kings
Referred to:
Reported by: Affected Persons
Source: Tank Truck
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: False
Spill Date: 12/18/2000 04:00:00 PM
Rcvd Date: 12/18/2000 04:45:00 PM
CAC Date:
Insp Date:
Close Date: 06/13/2003 12:00:00 AM
Create Date: 12/18/2000 12:00:00 AM
Update Date: 06/13/2003 12:00:00 AM
DEC Region: 2
Lead DEC: MXTIPPLE
After Hours: True

Caller Remark:

"building owner ordered too much oil spill went to sidewalk clean up is being completeed by oil man on scene now "

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE "

Material Information

OP Unit ID: 831629
OU: 01
Material ID: 544389
CAS No:
Material Family: Petroleum
Quantity: 10.00
Units: G
Recovered: 10.00
Med Soil: True
Med Air: False
Material Code: 0001A
Material Name: #2 fuel oil

Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: MR CHATENARNIE
Spiller Company:
Spiller Address: 64 BOX ST
Spiller City: BROOKLYN
Spiller State: ZZ
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Contact Ext:						
Latitude:		40.737324390				
Longitude:		-73.954382010				
161	1 of1	NW	0.29 / 1,537.99	10.87 / -1	**Box Street GW** **Box Street btw Manhattan Ave and McGuinness Blvd** **Brooklyn NY 11222**	SHWS

Site Code: 488734
HW Code: 224184
Program: HW
Site Class: P
Site Name: Box Street GW
Site Address: Box Street btw Manhattan Ave and McGuinness Blvd
City: Brooklyn
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.737373000
Longitude: -73.954609000
SWIS: 2401
Acres:
Record Added: 2013-11-06 09:59:00
Record Update: 2021-01-07 08:34:00
Updated by: JCGRATHW
Site Code (Web): 224184
Program Type (Web): HW
Site Name (Web): Box Street GW
Site Class (Web): P
Address1 (Web): Box Street btw Manhattan Ave and McGuinness Blvd
Address2 (Web):
Locality (Web): Brooklyn
Zip Code (Web): 11222
County (Web): Kings
Longitude (Web): -73.954609000
Latitude (Web): 40.737373000
Site Code (GIS): 224184
Site Name (GIS): Box Street GW
Program (GIS): HW
Site Class (GIS): P
Address1 (GIS): Box Street btw Manhattan Ave and McGuinness Blvd
Address2 (GIS):
Locality (GIS): Brooklyn
Zip Code (GIS): 11222
County (GIS): Kings
Site Class Desc: Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Site Class Desc (Web): Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Assess DOH: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.
Description:

Location The Box Street GW Site is located in an urban area between Manhattan Ave and McGuinness Blvd. Site Features The exact site location has not been established. Currnet Zoning/Uses(s) When the site location is established the current zoning can be determined. The surrounding parcels are currently used for a combination of commercial, light industrial and residential. Historical Use(s) When the site location is determined the use will be updated. Site Geology and Hydrogeology Geology is unknow at this time. Depth to groundwater is approximately 9' bgs. Flow is to the north-northeast towards Newtown Creek.

Assessment:

Nature and Extent of Contamination Groundwater: May-July 2013 - 7 groundwater samples collected. Chlorinated VOCs above GQS include: cis-1,2-DCE (max 17,000 ppb), 1,1-DCA (max 1600 ppb), 1,1-DCE (max 640 ppb), methylene chloride (max 95 ppb), trans-1,2-DCE (52 ppb), TCE (max 100 ppb), and vinyl chloride (max 1600 ppb). September 2013 – 3 groundwater samples and 1 duplicate sample collected. Chlorinated VOCs above GQS include: cis-1,2-DCE (max 51,000 ppb), 1,1-DCA (max 2800 ppb), 1,1-DCE (max 2100 ppb), TCE (max 80 ppb), and vinyl chloride (max 21,000 ppb).

Owner Information

Owner Op:	01
Sub Type:	03
Owner Name:	
Owner Company:	56 Box Street LLC
Owner Street:	199 Lee Avenue
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11211-8919
Country:	United States of America

Environmental Remediation

Operable Unit:	01
Contaminants:	

162 ***1 of3*** ***ENE*** ***0.31 / 1,640.16*** ***1.00 / -11*** ***DEPT OF SANITATION 459 N HENRY ST BROOKLYN NY*** ***LST***

Spill No:	0012519	***REM Phase:***	0
Site ID:	197038	***UST Trust:***	False
DER Facility ID:	164013	***Spill Date:***	02/22/2001 02:00:00 PM
CID:	211	***Rcvd Date:***	02/22/2001 02:09:00 PM
Program Type:	ER	***CAC Date:***	
SWIS Code:	2401	***Insp Date:***	
Contribute Factor:	Tank Test Failure	***Close Date:***	04/23/2012 12:00:00 AM
Water Body:		***Create Date:***	02/22/2001 12:00:00 AM
Class:	B3	***Update Date:***	06/04/2012 03:29:48 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	adzhitom
County:	Kings	***After Hours:***	False
Referred to:	NFA		
Reported by:	Tank Tester		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"UNCOVER ISOLATE AND RETEST"

Dec Remark:

"6/18/08. J. Krimgold reviewed the letter-report submitted by ROUX Associate inc. dated June 2, 2008 with request to close the spill case. The letter-report contains no new info besides what the Department has already in its files. The 12 pages attached to the letter is nothing but printouts from our website or copies of documents (application, failed test reports, etc.) that was already submitted to the Department. Nothing in the letter-report points to the investigation of the cause of the test failure or removal of the release. Request for the spill case closure was denied. JMK. 12-27-2011 This spill was assigned to Leszek Zielinski on 06/28/10. Then this spill was reassigned from V. Brevdo to Alex Zhitomirsky on 12-27-2011, as per V. Brevdo instructions. Emailed LiRo and received the following response by S. Frank: We will pull together whatever information we have and forward it to you. AZ 2-7-2012 Site demolition and construction completed at site by May 2011. On 7/22/11 LiRo met with the site personnel and gathered additional information relevant to spill 0012519. LiRo prepared a letter to address DEC concerns from the July 2008 spill closure denial and submitted to DEC on

January 23, 2012. Received and filed e-copies from LiRo. AZ 4-19-2012 Received on January 26, 2012, and reviewed Tank Closure Sample Results and Spill Closure Request dated January 23, 2012. The report stated that in August 2005, EMTEQUE Corp. oversaw Safeway Environmental perform closure and removal of tank#001. Approximately 15 cubic yards and four 55-gallon drums of soil were removed during excavation of the UST. No visible discoloration within the excavation was noted. No petroleum odors or elevated PID readings were recorded. EMTEQUE collected a total of five soil samples from the excavation pit. No VOCs were reported in any sample. SVOCs were reported above TAGM Levels in all five samples. The SVOCs reported were mainly polycyclic aromatic hydrocarbons (PAH)typically indicative of urban fill material. The site layout has changed significantly due to demolition and construction activities. Because of this, the former tank location is unknown. Based on this information, LiRo requested closure of spill#0012519. This spill was closed and a letter was sent to S. Frank/F. Ashkan/V. brevod: Dear Steve, I have reviewed tank closure sample results and spill closure request for the above spill number submitted to DEC on January 26, 2012. A tank test failure of the tank#1 was recorded at this site. As a result, a spill #0012519 was issued. EMTEQUE Corp. oversaw Safeway Environmental perform closure and removal of tank#001 in August 2005. Approximately 15 cubic yards and four 55-gallon drums of soil were removed during excavation of the UST. No visible discoloration within the excavation was noted. No petroleum odors or elevated PID readings were recorded. EMTEQUE collected a total of five soil samples from the excavation pit. No VOCs were reported in any sample. SVOCs were reported above TAGM levels in all five samples. The SVOCs reported were mainly polycyclic aromatic hydrocarbons (PAH) typically indicative of urban fill material. Based on this information, this spill number is closed. All wells associated with this spill should be properly abandoned. The Department hereby reserves all of its rights concerning, and such forbearance shall not extend to, any further investigation or remedial action the Department deems necessary due to: I. The off-site migration of petroleum contaminants that was not addressed by this evaluation. II. Environmental conditions related to the Site which were unknown to the Department at the time of this approval. III. Information received, in whole or in part, after the Department's spill case closure, which indicates that the corrective action was not sufficiently protective of human health for the reasonably anticipated use(s) of the site; or IV. Fraud in obtaining this approval for inactivation. Please be advised that you should maintain a permanent file of all documentation and correspondence regarding this case for future use. The Department's files regarding this release may not be maintained indefinitely. Sincerely, Alex Zhitomirsky "

Material Information

OP Unit ID:	834047	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	542783	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	ROBERT JOHNSON
Spiller Company:	DEPT OF SANITATION
Spiller Address:	
Spiller City:	ASTORIA
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	ROBERT JOHNSON
Contact Phone:	(718) 768-5795
Contact Ext:	
Latitude:	40.735273970
Longitude:	-73.944868790

Tank Test Information

Spill Tank ID:	1526111	***Source:***	
Tank No:	1	***Leak Rate:***	.00
Tank SIze:	5000	***Gross Fail:***	F
Material:	0001	***Modified by:***	Spills
EPA UST:		***Last Modified:***	2004-10-01 04:00:45.140000000
UST:		***Test Method:***	03
Cause:			
Alt Test Method:	Horner EZ Check I or II		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
162	2 of3	ENE	0.31 / 1,640.16	1.00 / -11	DSNY Greenpoint Household Drop-Off 459 NORTH HENRY ST. (NEWTOWN CREEK IN GREENPOINT) Brooklyn NY 11222	SWF/LF

Activity Number:	[24T02]	**Facility Name (InAct):**	DSNY Greenpoint Household Drop-Off
Facility Name (Act):		**Location Addr (InAct):**	459 NORTH HENRY ST. (NEWTOWN CREEK IN GREENPOINT)
Location Addr (Act):		**Loc Addr2(InAct):**	
Location Addr2 (Act):		**City (InAct):**	Brooklyn
City (Act):		**State (InAct):**	NY
State (Act):		**Zip Code (InAct):**	11222
Zip Code (Act):		**County (InAct):**	Kings
County (Act):		**East Coord (InAct):**	589077
East Coord (Act):		**North Coord (InAct):**	4509896
North Coord (Act):			
Facility Name:			
Location Addr:			
Location Addr2:			
City:			
State:			
Zip Code:			
County:			
East Coord:			
North Coord:			
Data Source:	SWMF - Inactive Facility Lists		

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		**Authorization No:**	2-6101-00022/00001
Activity Desc:	Transfer station - permit	**Authrzation Issue Dt:**	12/8/1995
Regulatory Status:	None	**Operator Type:**	
Active:	No	**Operator Name:**	
Dt of Last Inspection:		**Phone No:**	2128378030
Expiration Dt:	12/31/2005	**Region:**	2
Owner Type:	Municipal	**Contact Name:**	Pablo Lacayo
Owner Name:	NYC Department of Sanitation	**Contact Address:**	44 Beaver Street
Owner Address:	44 Beaver Street	**Contact Address2:**	
Owner Address2:		**Contact City:**	New York
Owner City:	New York	**Contact State:**	NY
Owner State:	NY	**Contact Zip:**	10004
Owner Zip:	10004	**Contact Phone:**	2124374657
Owner Phone:	2124374668	**Contact Email:**	placayo@dsny.nyc.gov
Owner Email:	tfuller@dsny.nyc.gov		
Waste Types:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
162	3 of3	ENE	0.31 / 1,640.16	1.00 / -11	DSNY Greenpoint Household Drop-Off 459 NORTH HENRY ST. (NEWTOWN CREEK IN GREENPOINT) Brooklyn NY 11222	SWF/LF

Activity Number:	[24W02]	**Facility Name (InAct):**	DSNY Greenpoint Household Drop-Off
Facility Name (Act):		**Location Addr (InAct):**	459 NORTH HENRY ST. (NEWTOWN CREEK IN GREENPOINT)
Location Addr (Act):		**Loc Addr2(InAct):**	
Location Addr2 (Act):		**City (InAct):**	Brooklyn
City (Act):		**State (InAct):**	NY
State (Act):		**Zip Code (InAct):**	11222;11234
Zip Code (Act):		**County (InAct):**	Kings
County (Act):		**East Coord (InAct):**	588853;591136
East Coord (Act):		**North Coord (InAct):**	4499272;4509974
North Coord (Act):			
Facility Name:			

Location Addr:
Location Addr2:
City:
State:
Zip Code:
County:
East Coord:
North Coord:
Data Source: SWMF - Inactive Facility Lists

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		**Authorization No:**	0
Activity Desc:	C&D processing - registration	**Authrzation Issue Dt:**	
Regulatory Status:	Registration	**Operator Type:**	
Active:	No	**Operator Name:**	
Dt of Last Inspection:		**Phone No:**	7182513400
Expiration Dt:		**Region:**	2
Owner Type:	Private	**Contact Name:**	
Owner Name:	RALPH AND JAMIE SERPICO	**Contact Address:**	
Owner Address:	5710 PRESTON COURT	**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:	BROOKLYN	**Contact State:**	
Owner State:	NY	**Contact Zip:**	
Owner Zip:	11234	**Contact Phone:**	
Owner Phone:	7182513400	**Contact Email:**	
Owner Email:			
Waste Types:			

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		**Authorization No:**	2-6101-00022/00001
Activity Desc:	C&D processing - registration	**Authrzation Issue Dt:**	3/17/2006
Regulatory Status:	Permit	**Operator Type:**	
Active:	No	**Operator Name:**	
Dt of Last Inspection:		**Phone No:**	2128378030
Expiration Dt:	3/31/2008	**Region:**	2
Owner Type:	Municipal	**Contact Name:**	Pablo Lacayo
Owner Name:	NYC Department of Sanitation	**Contact Address:**	44 Beaver Street
Owner Address:	44 Beaver Street	**Contact Address2:**	
Owner Address2:		**Contact City:**	New York
Owner City:	New York	**Contact State:**	NY
Owner State:	NY	**Contact Zip:**	10004
Owner Zip:	10004	**Contact Phone:**	2124374657
Owner Phone:	2124374668	**Contact Email:**	placayo@dsny.nyc.gov
Owner Email:	tfuller@dsny.nyc.gov		
Waste Types:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
163	1 of1	ENE	0.31 / 1,649.02	0.00 / -12	NYC-DOS GREENPOINT MTS BROOKLYN NY	PFAS IND

Status:	Active	**Fac Fips Code:**	36047
Fac Indian Cntry Flg:	No	**Compliance Status:**	No Violation Identified
Fac Derived Huc:	02030201	**EPA Programs:**	CAA
Fac Derived Wbd:	020301010405	**Federal Facility:**	No
Fac Derived Cd113:	12	**Federal Agency:**	-
Fac Derived Cb2010:	360470579002000	**Fac Snc Flg:**	No
Fac Informal Count:	0	**AIR Flag:**	Yes
Last Informal Action:	-	**NPDES Flag:**	No
Formal Action Count:	0	**SDWIS Flag:**	No
Last Formal Action:	10/12/1990	**RCRAFlag:**	No
Fac Total Penalties:	0	**TRI Flag:**	No
Fac Penalty Count:	-	**GHG Flag:**	No
Date Last Penalty:	10/12/1990	**TRI IDs:**	-
Last Penalty Amt:	75000	**TRI Releases Trnsfrs:**	-

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fac Qtrs With Nc:	0	**TRI on Site Releases:**	-
Programs With Snc:	0	**TRI off Site Trnsfrs:**	-
Fac Percent Minority:	46.759	**TRI Reporter:**	-
Fac Pop Den:	47820.98	**Fac Imp Water Flg:**	-
Count:	1	**Fac Major Flag:**	-
Fac County:	KINGS	**Fac Active Flag:**	Yes
State Other :		**Fac Inspection Count:**	0
Region:	02	**Date Last Inspection:**	-
Latitude:	40.736131	**Days Last Inspection:**	-
Longitude:	-73.945957		
Fac Derived Tribes:	-		
AIR IDs:	NY0000002610100022		
CAA Permit Types:	Minor Emissions		
CAA NAICS:	562211		
CAA SICS:	4953		
NPDES IDs:	-		
CWA Permit Types:	-		
CWA NAICS:	-		
CWA SICS:	-		
RCRA IDs:	-		
RCRA Permit Types:	-		
RCRA NAICS:	-		
SDWA IDs:	-		
SDWA System Types:	-		
SDWA Compliance Status:	-		
SDWA Snc Flag:	No		
Fac Collection Meth:	INTERPOLATION-OTHER		
EJSCREEN Flag Us:	No		
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.945957,%22y%22:40.736131,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1		
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110019834376		
Industry:	Waste Management		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
164	1 of1	SSE	0.32 / 1,671.83	12.29 / 0	LOVE MONKEY BROOKLYN NY	PFAS IND

Status:	Active	**Fac Fips Code:**	36047
Fac Indian Cntry Flg:	No	**Compliance Status:**	No Violation Identified
Fac Derived Huc:	02030201	**EPA Programs:**	RCRA
Fac Derived Wbd:	020301010405	**Federal Facility:**	No
Fac Derived Cd113:	12	**Federal Agency:**	-
Fac Derived Cb2010:	360470573001003	**Fac Snc Flg:**	No
Fac Informal Count:	0	**AIR Flag:**	No
Last Informal Action:	-	**NPDES Flag:**	No
Formal Action Count:	0	**SDWIS Flag:**	No
Last Formal Action:	-	**RCRAFlag:**	Yes
Fac Total Penalties:	0	**TRI Flag:**	No
Fac Penalty Count:	-	**GHG Flag:**	No
Date Last Penalty:	-	**TRI IDs:**	11222BRKLY196DI
Last Penalty Amt:	-	**TRI Releases Trnsfrs:**	-
Fac Qtrs With Nc:	0	**TRI on Site Releases:**	-
Programs With Snc:	0	**TRI off Site Trnsfrs:**	-
Fac Percent Minority:	51.457	**TRI Reporter:**	-
Fac Pop Den:	47474.94	**Fac Imp Water Flg:**	-
Count:	1	**Fac Major Flag:**	-
Fac County:	KINGS	**Fac Active Flag:**	Yes
State Other :		**Fac Inspection Count:**	0
Region:	02	**Date Last Inspection:**	12/18/1992
Latitude:	40.72917	**Days Last Inspection:**	11600
Longitude:	-73.9489		
Fac Derived Tribes:	-		
AIR IDs:	-		
CAA Permit Types:	-		
CAA NAICS:	-		
CAA SICS:	-		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

NPDES IDs:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDs:	NYD078166824
RCRA Permit Types:	VSQG
RCRA NAICS:	51211
SDWA IDs:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA Snc Flag:	No
Fac Collection Meth:	ADDRESS MATCHING-HOUSE NUMBER
EJSCREEN Flag Us:	Yes
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.9489,%22y%22:40.72917,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110009468487
Industry:	Metal Machinery Mfg
Industry:	Metal Coating

165	1 of1	ESE	0.32 / 1,684.11	9.68 / -2	**Rapid Processing (Humboldt Ave Brooklyn)** **860 Humboldt Street** **Brooklyn NY 11222**	SWF/LF

Activity Number:	[24MC6]	**Facility Name (InAct):**	Rapid Processing (Humboldt Ave Brooklyn)
Facility Name (Act):		**Location Addr (InAct):**	860 Humboldt Street
Location Addr (Act):		**Loc Addr2(InAct):**	
Location Addr2 (Act):		**City (InAct):**	Brooklyn
City (Act):		**State (InAct):**	NY
State (Act):		**Zip Code (InAct):**	11222
Zip Code (Act):		**County (InAct):**	Kings
County (Act):		**East Coord (InAct):**	588996
East Coord (Act):		**North Coord (InAct):**	4509385
North Coord (Act):			
Facility Name:			
Location Addr:			
Location Addr2:			
City:			
State:			
Zip Code:			
County:			
East Coord:			
North Coord:			
Data Source:	SWMF - Inactive Facility Lists		

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:	4.3 - Utilization of Digital Orthophoto Quads	**Authorization No:**	24MC6
Activity Desc:	RHRF - registration	**Authrzation Issue Dt:**	
Regulatory Status:	Registration	**Operator Type:**	
Active:	No	**Operator Name:**	
Dt of Last Inspection:		**Phone No:**	7183490500
Expiration Dt:		**Region:**	2
Owner Type:	Private	**Contact Name:**	Jose Ortiz
Owner Name:	Anthony Tristani	**Contact Address:**	
Owner Address:	860 Humboldt Street	**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:	Brooklyn	**Contact State:**	
Owner State:	NY	**Contact Zip:**	
Owner Zip:	11222	**Contact Phone:**	7183490500
Owner Phone:	7183490500	**Contact Email:**	jose@rapidprocessingllc.com
Owner Email:			
Waste Types:	Commingled Paper;Paper / Cardboard;Newspaper;Office Paper		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
166	1 of1	E	0.32 / 1,684.26	9.07 / -3	GREENPOINT INCINERATOR NEW YORK CITY DEPARTMENT OF SANITATION NYCDOS BROOKLYN NY	PFAS IND

Status:	Active	**Fac Fips Code:**	36047
Fac Indian Cntry Flg:	No	**Compliance Status:**	No Violation Identified
Fac Derived Huc:	02030201	**EPA Programs:**	RCRA
Fac Derived Wbd:	020301010405	**Federal Facility:**	No
Fac Derived Cd113:	12	**Federal Agency:**	-
Fac Derived Cb2010:	360470579002011	**Fac Snc Flg:**	No
Fac Informal Count:	0	**AIR Flag:**	No
Last Informal Action:	-	**NPDES Flag:**	No
Formal Action Count:	0	**SDWIS Flag:**	No
Last Formal Action:	9/30/2002	**RCRAFlag:**	Yes
Fac Total Penalties:	0	**TRI Flag:**	No
Fac Penalty Count:	-	**GHG Flag:**	No
Date Last Penalty:	-	**TRI IDs:**	-
Last Penalty Amt:	-	**TRI Releases Trnsfrs:**	-
Fac Qtrs With Nc:	0	**TRI on Site Releases:**	-
Programs With Snc:	0	**TRI off Site Trnsfrs:**	-
Fac Percent Minority:	48.948	**TRI Reporter:**	-
Fac Pop Den:	47090.31	**Fac Imp Water Flg:**	-
Count:	1	**Fac Major Flag:**	-
Fac County:	KINGS	**Fac Active Flag:**	Yes
State Other :		**Fac Inspection Count:**	0
Region:	02	**Date Last Inspection:**	10/31/2006
Latitude:	40.733579	**Days Last Inspection:**	6535
Longitude:	-73.944897		
Fac Derived Tribes:	-		
AIR IDs:	-		
CAA Permit Types:	-		
CAA NAICS:	-		
CAA SICS:	-		
NPDES IDs:	-		
CWA Permit Types:	-		
CWA NAICS:	-		
CWA SICS:	-		
RCRA IDs:	NYD986972008		
RCRA Permit Types:	SQG		
RCRA NAICS:	562211		
SDWA IDs:	-		
SDWA System Types:	-		
SDWA Compliance Status:	-		
SDWA Snc Flag:	No		
Fac Collection Meth:	ADDRESS MATCHING-HOUSE NUMBER		
EJSCREEN Flag Us:	No		
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.944897,%22y%22:40.733579,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1		
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110010434155		
Industry:	Waste Management		

167	1 of1	NW	0.32 / 1,689.97	12.98 / 1	Former BRT Railroad Car Barn 1121-1137 Manhattan Avenue/18 Box St. Brooklyn NY 11222	BROWNFIELDS

Site Code:	455846
HW Code:	C224153
Program:	BCP
Site Class:	C
Site Name:	Former BRT Railroad Car Barn
Site Address:	1121-1137 Manhattan Avenue/18 Box St.
City:	Brooklyn

Zip:	11222
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.736900000
Longitude:	-73.956094444
SWIS:	2401
Acres:	1.147
Record Added:	2011-09-26 11:59:00
Record Update:	2013-12-18 16:05:00
Updated by:	HRAHMED
Site Code (Web):	C224153
Program Type (Web):	BCP
Site Name (Web):	Former BRT Railroad Car Barn
Site Class (Web):	C
Address1 (Web):	1121-1137 Manhattan Avenue/18 Box St.
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.956094444
Latitude (Web):	40.736900000
Site Code (GIS):	C224153
Site Name (GIS):	Former BRT Railroad Car Barn
Program (GIS):	BCP
Site Class (GIS):	C
Address1 (GIS):	1121-1137 Manhattan Avenue/18 Box St.
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Site Class Desc (Web):	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH:	Remedial activities undertaken at the site have effectively reduced the potential for exposure to site-related contaminants. Therefore, this site no longer poses a public health concern.

Description:

Location: The Former BRT Railroad Car Barn site is located in an urban area in the Greenpoint section of Brooklyn, and is known as 18 Box Street and 1121-1137 Manhattan Avenue. It is comprised of one tax parcels known as Block 2482 Lot 26. Site Features: The site is being redeveloped for residential use. Current Zoning and Land Use(s): Lot 26 is zoned M1-2/R6A. The M1 district is often a buffer between M2 or M3 districts (manufacturing/industrial) and adjacent residential or commercial districts. The site is currently being redeveloped for residential use. Past Use of the Site: The site was developed prior to 1887 with multiple 3-story buildings that were utilized by the Brooklyn Crosstown Rail Road. By 1916, the site was utilized by the Brooklyn Rapid Transit (BRT) as a rail road car barn for the Cross Town Division. The northwest corner of the building was utilized as a repair shop and two boilers were housed within the repair shop. Other companies that conducted similar operations within the building in the 1940s and early 1950s include the Brooklyn and Queens Transit Corporation and the New York City Transit System. In 1953, the site was redeveloped again with the two adjacent buildings that currently occupy the subject site lots. The building was utilized as a hardware warehouse in the 1960s and 1970s and was utilized by M. Hiller & Son, Inc. as a rags and used clothing distributor/warehouse since the company purchased the property in 1977. Site Geology and Hydrogeology: Subsurface soils at the site are primarily made up of urban fill material to an approximate depth of 1 to 5 feet below slab grade, followed by fine sand, silt and sandy clay to 15 feet below slab grade. It should be noted that slab grade of the buildings is 3 to 4 feet above street level along Box street and Manhattan Avenue. According to the USGS topographic map for the area, the elevation of the property is approximately 14 feet above mean sea level. The topography within the immediate area slopes gradually from southeast to northwest. Groundwater at the site exists at approximately 8 feet below grade and flows in a northwest direction. Certificate of Completion issued, 12/18/2013.

Assessment:

Nature and Extent of Contamination: Prior to Remediation: Petroleum contamination associated with the underground storage tank (UST) was identified,

including non-aqueous phase liquid (NAPL). Elevated levels of SVOCs, as well as lead and copper, are present in soil beneath the site at concentrations which exceed unrestricted use soil cleanup objectives (SCOs). These contaminants have been detected in soil between 0 to 10 feet below grade. These include benzo(a)anthracene (up to 62 ppm), benzo(a)pyrene (up to 51 ppm), benzo(b)fluoranthene (up to 71 ppm), benzo(k)fluoranthene (up to 21 ppm), chrysene (up to 56 ppm), dibenzo(a,h)anthracene (up to 3.6 ppm), fluoranthene (up to 160 ppm), indeno(1,2,3-cd)pyrene (up to 12 ppm), phenanthrene (up to 140 ppm), pyrene (up to 140 ppm), arsenic (up to 17.6 ppm), chromium (up to 54.9 ppm), copper (up to 151 ppm), mercury (up to 2.95 ppm), manganese (up to 2880 ppm), lead (up to 472 ppm), nickel (up to 34.9 ppm), zinc (up to 476 ppm). Elevated levels of VOCs and SVOCs have been detected in groundwater at concentrations exceeding the TOGS 1.1.1 Class GA standards. These include 1,2,4-trimethylbenzene (up to 280 ppb), 1,3,5-trimethylbenzene (up to 86 ppb), benzene (up to 3.5 ppb), ethylbenzene (up to 74 ppb), isopropylbenzene (up to 18 ppb), m/p-xylenes (up to 130 ppb), n-butylbenzene (up to 7.6 ppb), n-propylbenzene (up to 34 ppb), o-xylene (up to 130 ppb), toluene (up to 11 ppb), naphthalene (up to 22,000 ppb), benzo(a)anthracene (up to 6.1 ppb), benzo(b)fluoranthene (up to 8.1 ppb), benzo(k)fluoranthene (up to 3.3 ppb), chrysene (up to 5.4 ppb), fluoranthene (up to 540 ppb), indeno(1,2,3-cd)pyrene (up to 2.5 ppb), phenanthrene (up to 13,000 ppb), pyrene (up to 1300 ppb). After Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were naphthalene, benz(a)anthracene, benzo(a)pyrene, benzo(b) fluoranthene, benzo[k]fluoranthene, chrysene, dibenz[a,h]anthracene, fluoranthene, fluorene, indeno(1,2,3-cd)pyrene, phenanthrene, pyrene, lead, copper, o-xylene, p-xylene, 1,2,4-trimethylbenzene, chromium, benzene, ethylbenzene, toluene, arsenic, barium, zinc, nickel, manganese in soil and groundwater and cadmium in Little Creek sediments. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use. Significant Threat: This site does not pose a significant threat to human health or the environment.

Materials Information

Waste Name: FLUORENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,2,4-TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: Chrysene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: COPPER
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: P-XYLENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: TOLUENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: ZINC
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: NICKEL
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: BARIUM
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: BENZENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: O-XYLENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: PYRENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: MANGANESE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: ARSENIC
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: LEAD
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 01
Sub Type: 06
Owner Name: Jeffrey Hiller
Owner Company: M. Hiller and Son, Inc.
Owner Street: 1133 Manhattan Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Brooklyn Public Library
Owner Street: Greenpoint Branch
Owner Street 2: 107 Norman Ave.
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Matt Schwartz
Owner Company: 1133 Manhattan Avenue LLC
Owner Street: 11 Park Place, Suite 1705
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10007
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: HRAHMED
Record Added: 2011-09-26 16:24:00
Record Updated: 2013-12-05 16:17:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Projects Information

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 2013-12-18 00:00:00
End Status: ACT
Operable Unit ID: 1205994
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Action

Project Code: 25
Project Desc:
Project Refer Name:
End Date: 2013-12-18 00:00:00
End Status: ACT
Operable Unit ID: 1239609
Operable Unit: 00
Operable Unit Desc: Site Management
Code Name: Certificate of Completion

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2012-08-24 00:00:00
End Status: ACT
Operable Unit ID: 1205994
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Project Code: 04
Project Desc: Remedial Design

Project Refer Name:
End Date: 2012-08-24 00:00:00
End Status: ACT
Operable Unit ID: 1205994
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Design

Environmental Remediation

Operable Unit: 01
Contaminants: 1,2,4-trimethylbenzene, arsenic, barium, benzene, benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chromium, chrysene, copper, dibenz[a,h]anthracene, ethylbenzene, fluoranthene, fluorene, indeno(1,2,3-cd)pyrene, lead, manganese, naphthalene, nickel, o-xylene, p-xylene, phenanthrene, pyrene, toluene, zinc

Operable Unit: 00
Contaminants: 1,2,4-trimethylbenzene, arsenic, barium, benzene, benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chromium, chrysene, copper, dibenz[a,h]anthracene, ethylbenzene, fluoranthene, fluorene, indeno(1,2,3-cd)pyrene, lead, manganese, naphthalene, nickel, o-xylene, p-xylene, phenanthrene, pyrene, toluene, zinc

---

168 | ***1 of1*** | ***SSE*** | ***0.32 / 1,702.24*** | ***15.53 / 4*** | ***176 MCGUINNES AVE/GAS STA - TTF***
176 MCGUINNESS BOULEVARD
Brooklyn NY 11222 | ***LST***

Spill No:	9108332	***REM Phase:***	0
Site ID:	228776	***UST Trust:***	True
DER Facility ID:	4291	***Spill Date:***	11/04/1991 07:00:00 PM
CID:		***Rcvd Date:***	11/04/1991 11:31:00 AM
Program Type:	ER	***CAC Date:***	
SWIS Code:	2401	***Insp Date:***	
Contribute Factor:	Tank Test Failure	***Close Date:***	10/27/2014 12:00:00 AM
Water Body:		***Create Date:***	11/12/1991 12:00:00 AM
Class:	C4	***Update Date:***	11/18/2014 12:21:08 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	TJDEMEO
County:	Kings	***After Hours:***	False
Referred to:			
Reported by:	Tank Tester		
Source:	Gasoline Station or other PBS Facility		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"WILL E I & R"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 4/12/04-Vouight-Spill transferred from Sullivan to Rommel as per Rommel. Contacted present owner. Manny Shurka (212) 832-9100. He has no info on followup tank test. He bought site in 1997. All tanks closed in 1999. If tanks were operated for two years after tank test failure, then tanks can be assumed to have been OK in 1997. Tanks were not suction dispensers. They used submersible pumps. So, depending on where the tank test failure leak was, there could have been a release. Check with Manny if he did an environmental assessment when he bought the property or if Getty did one when they sold the property. 8/17/12 Spill re-assigned to T. Demeo as per RSE. bf 10/09/14-Hiralkumar Patel. reviewed available documents for DEC DeMeo. alternate address: 190 McGuiness Blvd. PBS #s: 2-146994, 2-610594 PBS # 2-146994 for 176 McGuiness Blvd. as per PBS record, site has/had following tanks: - twelve (12) 550 gal gasoline USTs, closed-in-place in Feb. 1999 - one (1) 4,000 gal gasoline UST, closed-in-place in Feb. 1999 - two (2) 4,000 gal gasoline UST, in-service, installed in Feb. 1999 - one (1) 4,000 gal diesel UST, in-service, installed in Feb. 1999 PBS #: 2-610594 for 190 McGuiness Blvd. as per PBS record, the site has on 250 gal waste oil AST on legs, installed in Apr. 2007. other spill # 0204172 was reported on 07/22/2002 due to gasoline odors during delivery to the station. case closed. found tank test report dated 06/25/1997 on PBC edoc. as per the document, twelve (12) 550 gal gasoline tanks and one (1) 4,000 gal diesel tanks were fount tight. there is no document available to confirm source of tank test failure in 1991 (subject spill) and any petroleum release associated with it. Helf Enterprises LLC. **property owner** 10/27/14 TJD File review - determinations are based upon research into historical case file by Patel. Current owner took possession of propert 1997, followed by the closure of (12) UST's in 1999 and a (4K) UST's also closed in place in 1999. In February 1999 a total of (2) new 4K UST's were installed on site and remain in operation. All (12) 550's and (1) 4K gasoline UST's passed a tighntess test in 1997 - no record of repair or remedial action in file. Passing tank tightness reports for all tanks performed in 1997 have been uploaded to DECDOCS. Due to the lack of available history at this property and the fact the tighness test failure was reported in excess of 20 years ago, the suspect tanks were abandonned in place in 1999, the site has new owner's and no additional information is currently available - no further action is required at this time - spill is

administratively closed. "

Material Information

OP Unit ID:	962462	***Med in Air:***	False
OU:	01	***Med GW:***	True
Material ID:	420485	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	-1.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	***Update***
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.728430690
Longitude:	-73.950151690

Tank Test Information

Spill Tank ID:	1539268	***Source:***	
Tank No:		***Leak Rate:***	.00
Tank SIze:	0	***Gross Fail:***	
Material:	0009	***Modified by:***	Spills
EPA UST:		***Last Modified:***	2004-10-01 04:00:45.140000000
UST:		***Test Method:***	00
Cause:			
Alt Test Method:	Unknown		

169	***1 of1***	***SE***	***0.33 / 1,759.40***	***10.77 / -1***	***120 JEWEL ST/BKLYN 120 JEWEL ST NEW YORK CITY NY***	***LST***

Spill No:	8708714	***REM Phase:***	0
Site ID:	108855	***UST Trust:***	False
DER Facility ID:	95648	***Spill Date:***	01/12/1988 03:00:00 PM
CID:		***Rcvd Date:***	01/13/1988 10:05:00 AM
Program Type:	ER	***CAC Date:***	09/30/1992 12:00:00 AM
SWIS Code:	2401	***Insp Date:***	
Contribute Factor:	Tank Test Failure	***Close Date:***	09/30/1992 12:00:00 AM
Water Body:		***Create Date:***	01/26/1988 12:00:00 AM
Class:	B3	***Update Date:***	05/12/1994 12:00:00 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	BATTISTA
County:	Kings	***After Hours:***	False
Referred to:			
Reported by:	Tank Tester		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Caller Remark:

"2K TANK SYSTEM FAILED HORNER EZY CHECK WITH AN UNKNOWN LEAK RATE, WILL EXCAVATE, ISOLATE AND RETEST."

Dec Remark:

""

Material Information

OP Unit ID:	913383	***Med in Air:***	False
OU:	01	***Med GW:***	True
Material ID:	464087	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	-1.00	***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	CERTIFIED INTERN'NAL CORP
Spiller Address:	120 JEWEL ST
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.729159000
Longitude:	-73.947796000

Tank Test Information

Spill Tank ID:	1532986	***Source:***	
Tank No:		***Leak Rate:***	.00
Tank SIze:	0	***Gross Fail:***	
Material:	0001	***Modified by:***	Spills
EPA UST:		***Last Modified:***	2004-10-01 04:00:45.140000000
UST:		***Test Method:***	00
Cause:			
Alt Test Method:	Unknown		

170	1 of1	WNW	0.34 / 1,770.42	14.33 / 2	CANDLELIGHT CIRCLE BLDG# 15 CLAY NY	LST

Spill No:	9400007	***REM Phase:***	0
Site ID:	86546	***UST Trust:***	False
DER Facility ID:	79377	***Spill Date:***	04/01/1994 08:39:00 AM
CID:		***Rcvd Date:***	04/01/1994 09:50:00 AM
Program Type:	ER	***CAC Date:***	04/01/1994 12:00:00 AM
SWIS Code:	3424	***Insp Date:***	04/01/1994 12:00:00 AM
Contribute Factor:	Tank Failure	***Close Date:***	04/29/1994 12:00:00 AM
Water Body:		***Create Date:***	04/29/1994 12:00:00 AM
Class:	D4	***Update Date:***	08/19/1994 12:00:00 AM
Meets Std:	True	***DEC Region:***	7
Penalty:	False	***Lead DEC:***	HDWARNER

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County: Onondaga **After Hours:** False
Referred to:
Reported by: Police Department
Source: Passenger Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"CAR LEAKED GASOLINE ONTO PARKING AREA FIRE DEPT APPLIED ABSORBANTS."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HW 04/29/94: NO FURTHER ACTION. "

Material Information

OP Unit ID: 993723
OU: 01
Material ID: 387336
CAS No:
Material Family: Petroleum
Quantity: 6.00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0009
Material Name: gasoline

Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: UNK
Spiller Address:
Spiller City: ***UPDATE***
Spiller State: ZZ
Spiller Zip:
Spiller Country: 999
Contact Name:
Contact Phone:
Contact Ext:
Latitude:
Longitude:

---

171 | **1 of2** | **NNW** | **0.34 / 1,803.85** | **6.22 / -6** | **29 ASH ST/BKLYN/UNIVERSAL**
29 ASH ST
BROOKLYN NY | **LST**

Spill No: 8708297
Site ID: 119834
DER Facility ID: 104081
CID:
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Test Failure
Water Body:
Class: C4
Meets Std: False
Penalty: False
County: Kings
Referred to:
Reported by: Tank Tester
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: False
Spill Date: 12/24/1987 11:00:00 AM
Rcvd Date: 12/24/1987 01:30:00 PM
CAC Date:
Insp Date:
Close Date: 07/18/2003 12:00:00 AM
Create Date: 01/14/1988 12:00:00 AM
Update Date: 09/30/2003 12:00:00 AM
DEC Region: 2
Lead DEC: SMSANGES
After Hours: False

Caller Remark:

"5K TANK SYSTEM FAILURE, LEAK RATE OVER 10 GAL/HR. CONTACT: ART ECKSTEIN (718) 389-2929."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND / / : ACTION UNKNOWN. 02/09/01 Reassigned from Battista to Sangesland. See also 9709313 Closed - Refer to 9709313"

Material Information

OP Unit ID:	912922	***Med in Air:***	False
OU:	01	***Med GW:***	True
Material ID:	463690	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	-1.00	***Med Surf:***	False
Units:	L	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	UNIVERSAL CHILDREN
Spiller Address:	29 ASH ST
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.738177170
Longitude:	-73.954048890

Tank Test Information

Spill Tank ID:	1532814	***Source:***	
Tank No:		***Leak Rate:***	.00
Tank Size:	0	***Gross Fail:***	
Material:	0001	***Modified by:***	Spills
EPA UST:		***Last Modified:***	2004-10-01 04:00:45.140000000
UST:		***Test Method:***	00
Cause:			
Alt Test Method:	Unknown		

---

171 ***2 of2*** ***NNW*** ***0.34 / 1,803.85*** ***6.22 / -6*** ***29 ASH ST 29 ASH ST BROOKLYN NY*** ***LST***

Spill No:	9709313	***REM Phase:***	0
Site ID:	119835	***UST Trust:***	False
DER Facility ID:	104081	***Spill Date:***	11/10/1997 06:30:00 PM
CID:	211	***Rcvd Date:***	11/10/1997 06:39:00 PM
Program Type:	ER	***CAC Date:***	
SWIS Code:	2401	***Insp Date:***	
Contribute Factor:	Tank Test Failure	***Close Date:***	04/03/2003 12:00:00 AM
Water Body:		***Create Date:***	11/10/1997 12:00:00 AM
Class:	C4	***Update Date:***	04/03/2003 12:00:00 AM
Meets Std:	False	***DEC Region:***	2

Penalty:	False	**Lead DEC:**	SMSANGES
County:	Kings	**After Hours:**	True
Referred to:			
Reported by:	Tank Tester		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

""

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 02/09/01 Reassigned from Tibbe to Sangesland. See also 8708297. 2/20/2001 Bob Olsen at Enviro-Comp submitted a report showing boring work and water samples which show high levels of volitiles. Mr. Olsen says that the problem is due to Mobil and not from his site. 2/21/2001 - Sangesland spoke to Mark Tibbe about the site. He said the site is NOT within the product plume of Mobil Greenpoint however it MAY be in the dissolved phase plume. Mark said that he told Mr. Olsen to prove the groundwater flow by installing wells on his site and prove that the groundwater flow was in that direction. There also seems to be a problem with the data, because the concentrations are not consistant in all the borings at each depth. If the problem was from Mobil, there would not be such a wide range of values on a single site. Sangesland spoke to Mr. Olsen and asked him to prove his point that the problem is from Mobil by way of hydrogeology. Sangesland told Mr. Olsen to install 3 wells and identify flow direction. 5/16/2001 - Sangesland (along with Rommel and DEC attorney) met at the DEC offices with Steven Gurewitsch (Star Candle), Bob Olsen (Enviro-Comp), James Periconi (attorney). This meeting went over a series of technical options open to Star Candle to resolve the problems at the site. Problem is contaminated soil under the slab of the garage floor. Groundwater is approx. 5 ft deep. DEC suggested that the slab be opened, bad soil be excavated and the area back filled and repaved. Sidewall endpoint samples were discussed. DEC thought we had an understanding that this would be done, however 2 hours after the meeting Mr. Steven Gurewitsch called to say they would not do the work we discussed. Issue remains open. 11/27/2002 - Sangesland reviewed a submittal from Bob Olsen of Enviro-Comp (631-727-8445) concerning this site. Mr. Olsen states Pursuant to and in accordance with our discussions of 2001, Star Candle Company treated the bore holes ..... This effort was not discussed with the DEC. Apparently Mr. Olsen hired Regenisis to pour ORC down 4 boring holes several times over the course of several months. A soil sample was then taken from the bottom of each of these boring holes (just above the groundwater line). These samples came back clean. This procedure probably created 4 small clean pockets on the site. No type of confirmation boring was taken in an area around the prior borings which could confirm that the whole area was clean. 11/27/2002 - Sangesland spoke with Bob Olsen to ask why this work was done without discussions with the DEC. After review of what work was done: a) Biological treatment with retesting b) The fact that the entire subject site is fairly small (loading bay of the garage) c) The groundwater is very shallow, and non potable in an industrial area of Greenpoint. d) The problem was caused by a prior property owner. Sangesland requested confirmation of certain atributes of the Biological product used. 4/3/2003 Sangesland reviewed a submittal from Bob Olsen of Enviro-Comp which included a statement from Regenesis (biological product). After review of this information, the DEC believes that some levels of contamination continue to exist, but they are minor levels and in a limited area. Based on the qualifying statements above, this spill has been closed out. ********** Spill Closed ********** ****QUALIFIER**** If the loading dock area is ever excavated, the property owner is responsible for the preparation of a Human Health & Safety Plan for the construction/excavation people working at the site"

Material Information

OP Unit ID:	1052384	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	327665	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	MARGARET TAVARES
Spiller Company:	
Spiller Address:	29 ASH ST
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	MARGARET TAVARES
Contact Phone:	(212) 363-3775
Contact Ext:	
Latitude:	40.738177170

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Longitude: -73.954048890

Tank Test Information

Spill Tank ID:	1545452	**Source:**	
Tank No:	1	**Leak Rate:**	.00
Tank SIze:	5000	**Gross Fail:**	
Material:	0001	**Modified by:**	Spills
EPA UST:		**Last Modified:**	2004-10-01 04:00:45.140000000
UST:		**Test Method:**	03
Cause:			
Alt Test Method:	Horner EZ Check I or II		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
172	1 of1	WNW	0.34 / 1,811.42	14.24 / 2	29 Clay Property 29 Clay Street Brooklyn NY 11222	BROWNFIELDS

Site Code: 663677
HW Code: C224408
Program: BCP
Site Class: A
Site Name: 29 Clay Property
Site Address: 29 Clay Street
City: Brooklyn
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.736652902
Longitude: -73.956832199
SWIS: 2401
Acres: 0.220
Record Added: 2024-03-06 09:45:00
Record Update: 2024-08-02 11:57:00
Updated by: AAOBLIGA
Site Code (Web): C224408
Program Type (Web): BCP
Site Name (Web): 29 Clay Property
Site Class (Web): A
Address1 (Web): 29 Clay Street
Address2 (Web):
Locality (Web): Brooklyn
Zip Code (Web): 11222
County (Web): Kings
Longitude (Web): -73.956832199
Latitude (Web): 40.736652902
Site Code (GIS): C224408
Site Name (GIS): 29 Clay Property
Program (GIS): BCP
Site Class (GIS): A
Address1 (GIS): 29 Clay Street
Address2 (GIS):
Locality (GIS): Brooklyn
Zip Code (GIS): 11222
County (GIS): Kings
Site Class Desc: Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Site Class Desc (Web): Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Assess DOH: Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Description:

Location: The Clay Properties LLC site is inclusive of 29 Clay Street, Brooklyn, NY 11222. The site is comprised of one New York City Tax Lot (County: Brooklyn; Block 2482; Lot 53). The total area of the site is 9,415.9. Site Features: The site is currently vacant. Remnants of the slab of the former building remain on-site. The site is gated to avoid any trespassers entering the premises. Current Zoning and Land Use: The site is currently inactive and the current zoning designation is M1/2-R6 in Special Use District MX-8. The Site is located within a densely developed mixed-use area. The following summarizes the surrounding land uses: North: Commercial Street followed by a NYC Transit facility (65 Commercial Street), a new development at 56 Commercial Street. South: Clay Street two development sites, Site Code 224136 (State Superfund Program) and Site Code C224287 (NYS Brownfield Program). East: An industrial building (6 Box Street) and a 7-story mixed-use (retail residential) building (1133 Manhattan Avenue, followed by two mixed-use buildings and Manhattan Avenue. West: A construction site; NYS Brownfield Site Code C224278, with the intersection of Clay and Commercial Streets beyond. Past Use of the Site: The site was utilized for various industrial and manufacturing operations including an iron works, a tin can storage facility, a cotton batting company, a paper storage warehouse, and "non-specific manufacturing use". Interflo Technologies operated at 19 Clay Street (Lot 9) as a Registered Resource Conservation and Recovery Act (RCRA) small quantity hazardous waste generator from at least July 1994 to January 1997. Interflo Technologies generated ignitable, halogenated, non-halogenated solvents and mercury waste under USEPA ID No. NY0000374314. Multiple RCRA violations were identified for the site; however, all were addressed to the satisfaction of USEPA. Sanborn History: 1887-1905: The Site is developed with multiple structures identified as the Logan Iron Works, including a blacksmith shop, a flange shop, and a boiler shop. Commercial Street and additional portions of the iron works are to the north, followed by a sugar refinery. 1916: The Site is developed consistent with the 1905 map depictions; however, the buildings are now identified as a tin can storage facility. 1942-1951: The Site has been redeveloped with a commercial/industrial building along Clay Street. The structure is labeled as a partial 2-story structure identified as a paper storage warehouse. This structure is consistent with the most recent building. 1965: The building is identified as occupied by non-specific manufacturing use. Site Geology and Hydrogeology: Estimated depth to groundwater and groundwater flow direction typically varies due to seasonal fluctuations in precipitation, local usage demands, hydrogeology, underground structures, or de watering operations (if any). According to the recent Phase II Investigation the depth to groundwater in the vicinity of the Site is approximately 6-8 feet below grade surface. Based upon data provided on the above-referenced groundwater elevation map, regional groundwater flow direction in the vicinity of the Site is anticipated to flow west-northwest.

Assessment:

Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available.

Owner Information

Owner Op:	19
Sub Type:	NNN
Owner Name:	Acacia Thompson
Owner Company:	Brooklyn Public Library-Greenpoint Branch
Owner Street:	107 Norman Avenue
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11211
Country:	United States of America

Owner Op:	19
Sub Type:	NNN
Owner Name:	
Owner Company:	Brooklyn Community Board District 1
Owner Street:	435 Graham Avenue
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11221
Country:	United States of America

Owner Op:	01
Sub Type:	P03
Owner Name:	Idan Shitrit
Owner Company:	Clay Properties LLC
Owner Street:	134 North 4th Street
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11249
Country:	United States of America

Owner Op:	06
Sub Type:	P03
Owner Name:	Idan Shitrit
Owner Company:	Clay Properties LLC
Owner Street:	134 North 4th Street

Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11249
Country: United States of America

Environmental Remediation

Operable Unit: 01
Contaminants:

---

173 | ***1 of1*** | ***ESE*** | ***0.34 / 1,812.49*** | ***10.26 / -2*** | ***330 CALYER ST. 330 CALYER STREET BROOKLYN NY*** | ***LST***

Spill No: 9401962
Site ID: 260458
DER Facility ID: 109689
CID:
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Test Failure
Water Body:
Class: C3
Meets Std: False
Penalty: False
County: Kings
Referred to:
Reported by: Tank Tester
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: False
Spill Date: 05/10/1994 12:15:00 PM
Rcvd Date: 05/10/1994 12:15:00 PM
CAC Date:
Insp Date:
Close Date: 04/30/1998 12:00:00 AM
Create Date: 05/13/1994 12:00:00 AM
Update Date: 04/16/2002 12:00:00 AM
DEC Region: 2
Lead DEC: KSTANG
After Hours: False

Caller Remark:

""

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "

Material Information

OP Unit ID: 995644
OU: 01
Material ID: 385700
CAS No:
Material Family: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0001A
Material Name: #2 fuel oil

Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company:
Spiller Address:
Spiller City: ***Update***
Spiller State: ZZ
Spiller Zip:
Spiller Country: 001

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.730448070
Longitude: -73.946141070

Tank Test Information

Spill Tank ID:	1542692	**Source:**	
Tank No:		**Leak Rate:**	.00
Tank Size:	0	**Gross Fail:**	
Material:	0001	**Modified by:**	Spills
EPA UST:		**Last Modified:**	2004-10-01 04:00:45.140000000
UST:		**Test Method:**	00
Cause:			
Alt Test Method:	Unknown		

174	1 of1	ESE	0.35 / 1,843.12	10.39 / -2	**Carbona Products** **330 CALYER STREET** **BROOKLYN NY 11222**	SHWS

Site Code: 338763
HW Code: 224023
Program: HW
Site Class: N
Site Name: Carbona Products
Site Address: 330 CALYER STREET
City: BROOKLYN
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.730397656
Longitude: -73.946162737
SWIS: 2401
Acres:
Record Added: 1999-11-18 12:00:00
Record Update: 2003-12-16 00:00:00
Updated by: kstang
Site Code (Web): 224023
Program Type (Web): HW
Site Name (Web): Carbona Products
Site Class (Web): N
Address1 (Web): 330 CALYER STREET
Address2 (Web):
Locality (Web): Brooklyn
Zip Code (Web): 11222
County (Web): Kings
Longitude (Web): -73.946162737
Latitude (Web): 40.730397656
Site Code (GIS): 224023
Site Name (GIS): Carbona Products
Program (GIS): HW
Site Class (GIS): N
Address1 (GIS): 330 CALYER STREET
Address2 (GIS):
Locality (GIS): BROOKLYN
Zip Code (GIS): 11222
County (GIS): Kings
Site Class Desc: No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the

work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Site Class Desc (Web): No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH:
Description:

The site did not qualify for addition to the Registry of Inactive Hazardous Waste Sites.

Assessment:

Projects Information

Project Code: 01
Project Desc: Site Caracterization
Project Refer Name:
End Date: 2000-03-21 00:00:00
End Status: ACT
Operable Unit ID: 1100673
Operable Unit: 01
Operable Unit Desc: CARBONA PRODUCTS
Code Name: Site Characterization

Environmental Remediation

Operable Unit: 01
Contaminants:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
175	1 of 1	E	0.35 / 1,872.27	9.44 / -3	FORMER MOBIL GREENPOINT TERMINAL 403 GREENPOINT AVENUE BROOKLYN NY 11222	MOSF

Site ID: 345008
Site Status: Unregulated/Closed
Program No: 2-2720
Program Type Code: MOSF
Program Type Desc: Major Oil Storage Facility Program
Site Type: Storage Terminal/Petroleum Distributor
More Info:
Expiration Date: N/A
DEC Region: 2
County: Kings
UTM X: 589257.26524
UTM Y: 4509623.43416

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
176	1 of2	NNW	0.36 / 1,878.18	7.54 / -4	ECONOMY CONTAINER SERVICE 23 ASH ST Brooklyn NY 11222	SWF/LF

Activity Number:	[24T14]	**Facility Name (InAct):**	ECONOMY CONTAINER SERVICE
Facility Name (Act):		**Location Addr (InAct):**	23 ASH ST
Location Addr (Act):		**Loc Addr2(InAct):**	
Location Addr2 (Act):		**City (InAct):**	Brooklyn
City (Act):		**State (InAct):**	NY
State (Act):		**Zip Code (InAct):**	11222
Zip Code (Act):		**County (InAct):**	Kings
County (Act):		**East Coord (InAct):**	588200
East Coord (Act):		**North Coord (InAct):**	4510200
North Coord (Act):			
Facility Name:			
Location Addr:			
Location Addr2:			
City:			
State:			
Zip Code:			
County:			
East Coord:			
North Coord:			
Data Source:	SWMF - Inactive Facility Lists		

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		**Authorization No:**	2-6101-00085
Activity Desc:	Transfer station - permit	**Authrzation Issue Dt:**	
Regulatory Status:		**Operator Type:**	
Active:	No	**Operator Name:**	
Dt of Last Inspection:		**Phone No:**	
Expiration Dt:		**Region:**	2
Owner Type:		**Contact Name:**	JULIAN FILLIAPONO; MANAGER
Owner Name:		**Contact Address:**	
Owner Address:		**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:		**Contact State:**	
Owner State:		**Contact Zip:**	
Owner Zip:		**Contact Phone:**	
Owner Phone:		**Contact Email:**	
Owner Email:			
Waste Types:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
176	2 of2	NNW	0.36 / 1,878.18	7.54 / -4	F & P Resources LLC 23 Ash Street Brooklyn NY 11221	SWF/LF

Activity Number:	[24M00]	**Facility Name (InAct):**	F & P Resources LLC
Facility Name (Act):		**Location Addr (InAct):**	23 Ash Street
Location Addr (Act):		**Loc Addr2(InAct):**	
Location Addr2 (Act):		**City (InAct):**	Brooklyn
City (Act):		**State (InAct):**	NY
State (Act):		**Zip Code (InAct):**	11211;11214;11215;11221;11222;11231
Zip Code (Act):		**County (InAct):**	Kings
County (Act):		**East Coord (InAct):**	584652;585300;585806;588568;590321;590770
East Coord (Act):		**North Coord (InAct):**	4492844;4502974;4503057;4507777;4508030;4509702
North Coord (Act):			
Facility Name:			
Location Addr:			
Location Addr2:			
City:			
State:			
Zip Code:			

County:
East Coord:
North Coord:
Data Source: SWMF - Inactive Facility Lists

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		***Authorization No:***	
Activity Desc:	RHRF - exempt (non-VDF)	***Authrzation Issue Dt:***	
Regulatory Status:		***Operator Type:***	
Active:	No	***Operator Name:***	Benson Metal Corp.
Dt of Last Inspection:		***Phone No:***	7187227754
Expiration Dt:		***Region:***	2
Owner Type:		***Contact Name:***	Robert Lopinto
Owner Name:	Benson Metal Corp.	***Contact Address:***	
Owner Address:	543 Smith Street	***Contact Address2:***	
Owner Address2:		***Contact City:***	
Owner City:	Brooklyn	***Contact State:***	
Owner State:	NY	***Contact Zip:***	
Owner Zip:	11231	***Contact Phone:***	5167912300
Owner Phone:	7187227754	***Contact Email:***	sharpiroengineers@att.net
Owner Email:	tpetrosino@cropseymetals.com		
Waste Types:			

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		***Authorization No:***	
Activity Desc:	RHRF - exempt (non-VDF)	***Authrzation Issue Dt:***	
Regulatory Status:	None	***Operator Type:***	
Active:	No	***Operator Name:***	
Dt of Last Inspection:		***Phone No:***	7183838820
Expiration Dt:		***Region:***	2
Owner Type:	Private	***Contact Name:***	Joel Lehrman
Owner Name:	R&Z Metal Recycling Corp	***Contact Address:***	
Owner Address:	247 Huron Street	***Contact Address2:***	
Owner Address2:		***Contact City:***	
Owner City:	Brooklyn	***Contact State:***	
Owner State:	NY	***Contact Zip:***	
Owner Zip:	11222	***Contact Phone:***	7183838820
Owner Phone:	7183838820	***Contact Email:***	RZMetal@aol.com
Owner Email:	RZMetal@aol.com		
Waste Types:			

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		***Authorization No:***	
Activity Desc:	RHRF - exempt (non-VDF)	***Authrzation Issue Dt:***	
Regulatory Status:		***Operator Type:***	
Active:	No	***Operator Name:***	
Dt of Last Inspection:		***Phone No:***	7184971950
Expiration Dt:		***Region:***	2
Owner Type:		***Contact Name:***	Wayne KIng
Owner Name:	Charles J King Inc	***Contact Address:***	
Owner Address:	1301 Grand Street	***Contact Address2:***	
Owner Address2:		***Contact City:***	
Owner City:	Brooklyn	***Contact State:***	
Owner State:	NY	***Contact Zip:***	
Owner Zip:	11211	***Contact Phone:***	7184971950
Owner Phone:	7184971950	***Contact Email:***	wdking@att;net
Owner Email:	wdking@att.net		
Waste Types:			

SWMF - Inactive Facility Lists Details (InAct)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Accuracy Code:		**Authorization No:**	
Activity Desc:	RHRF - exempt (non-VDF)	**Authrzation Issue Dt:**	
Regulatory Status:		**Operator Type:**	
Active:	No	**Operator Name:**	
Dt of Last Inspection:		**Phone No:**	7183664017
Expiration Dt:		**Region:**	2
Owner Type:		**Contact Name:**	Timothy Fulton
Owner Name:	F & P Resources LLC	**Contact Address:**	340 Maspeth Avenue
Owner Address:	340 Maspeth Avenue	**Contact Address2:**	
Owner Address2:		**Contact City:**	Brooklyn
Owner City:	Brooklyn	**Contact State:**	NY
Owner State:	NY	**Contact Zip:**	11221
Owner Zip:	11221	**Contact Phone:**	7183664017
Owner Phone:	7183664017	**Contact Email:**	barbara@tntscrap.com
Owner Email:			
Waste Types:			

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		**Authorization No:**	
Activity Desc:	RHRF - exempt (non-VDF)	**Authrzation Issue Dt:**	
Regulatory Status:		**Operator Type:**	
Active:	No	**Operator Name:**	Cropsey Scrap Iron & Metal Corp.
Dt of Last Inspection:		**Phone No:**	5167912300
Expiration Dt:		**Region:**	2
Owner Type:		**Contact Name:**	Robert Lopinto
Owner Name:	Cropsey Scrap Iron & Metal Corp.	**Contact Address:**	same
Owner Address:	2994 Cropsey Avenue	**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:	Brooklyn	**Contact State:**	
Owner State:	NY	**Contact Zip:**	
Owner Zip:	11214	**Contact Phone:**	5167912300
Owner Phone:		**Contact Email:**	shapiroengineers@att.net
Owner Email:			
Waste Types:			

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		**Authorization No:**	
Activity Desc:	RHRF - exempt (non-VDF)	**Authrzation Issue Dt:**	
Regulatory Status:		**Operator Type:**	
Active:	No	**Operator Name:**	
Dt of Last Inspection:		**Phone No:**	7182223133
Expiration Dt:		**Region:**	2
Owner Type:		**Contact Name:**	Anthony DeConcillis
Owner Name:	Sixth Street Iron and Metal	**Contact Address:**	same
Owner Address:	163 6th Street	**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:	Brooklyn	**Contact State:**	
Owner State:	NY	**Contact Zip:**	
Owner Zip:	11215	**Contact Phone:**	7182223133
Owner Phone:		**Contact Email:**	anthony@dorannresources.com
Owner Email:			
Waste Types:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
177	1 of2	WNW	0.36 / 1,893.31	13.44 / 1	Former NuHart Plastic Manufacturing 65 DUPONT STREET BROOKLYN NY 11222	SHWS

Site Code:	416038
HW Code:	224136
Program:	HW
Site Class:	02
Site Name:	Former NuHart Plastic Manufacturing
Site Address:	65 DUPONT STREET

City:	BROOKLYN
Zip:	11222
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.735950293
Longitude:	-73.958054247
SWIS:	2401
Acres:	1.180
Record Added:	2009-07-03 14:23:00
Record Update:	2024-07-23 13:20:00
Updated by:	AAOBLIGA
Site Code (Web):	224136
Program Type (Web):	HW
Site Name (Web):	Former NuHart Plastic Manufacturing
Site Class (Web):	02
Address1 (Web):	65 DUPONT STREET
Address2 (Web):	
Locality (Web):	BROOKLYN
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.958054247
Latitude (Web):	40.735950293
Site Code (GIS):	224136
Site Name (GIS):	Former NuHart Plastic Manufacturing
Program (GIS):	HW
Site Class (GIS):	02
Address1 (GIS):	65 DUPONT STREET
Address2 (GIS):	
Locality (GIS):	BROOKLYN
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	This classification is assigned to a site at which: a. the disposal of hazardous waste has been confirmed and the presence of such hazardous waste or its components or breakdown products represents a significant threat to public health or the environment: or b. hazardous waste disposal has not been confirmed, but the site has been listed on the Federal National Priorities List (NPL).
Site Class Desc (Web):	This classification is assigned to a site at which: a. the disposal of hazardous waste has been confirmed and the presence of such hazardous waste or its components or breakdown products represents a significant threat to public health or the environment: or b. hazardous waste disposal has not been confirmed, but the site has been listed on the Federal National Priorities List (NPL).
Assess DOH:	Access is restricted by a fence and the site is vacant. People who enter may come into contact with contaminants in soil by walking on the site, digging or otherwise disturbing the soil. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. As the site is vacant, soil vapor intrusion is not a current concern, however the potential exists for soil vapor intrusion in future buildings on-site. Environmental sampling indicates soil vapor intrusion from site contamination is not a concern for off-site buildings.

Description:

Location: The site is located at 65 Dupont Street in the Greenpoint section of Brooklyn, Kings County, NY. The approximately 1.13-acre site is identified on the tax map as Block 2487, part of Lot 17. The site is bordered immediately to the north by Clay Street followed by commercial/industrial buildings, to the east by Brownfield Cleanup Program (BCP) Site Former NuHart East (ID: C224287), to the south by Dupont Street followed by multi-family residential structures, and to the west by Franklin Street followed by a New York City playground. Site Features: The dimensions of the site are approximately 50 feet by 200 feet. The site is currently under construction. Current Zoning and Land Use: The site is zoned M1-2/R6, which designates the site as manufacturing with a residential overlay. The site is currently being redeveloped into a residential building. Future use of the site is consistent with current zoning. Past Use of the Site: The site has been in use for various manufacturing and commercial purposes since 1887. It has been used for manufacturing, as an office, for storage, and for shipping and receiving. Prior to the late 1940s, the site and the surrounding lots were used as a boiler shop for Logan Ironworks, two stables, a gas and light fixture factory, a sheet metal works, a soap factory, a waterproofing factory, and a scrap metal facility. The subject property was developed for plastic manufacturing purposes in the late 1940s to early 1950s and has remained relatively unchanged since that time. From 1983 to 2004, NuHart and Company made vinyl siding and sheeting at the site. After 2004, NuHart vacated the on-site buildings. A total of 12 underground storage tanks (USTs) were located at the site prior to demolition of the on-site building. According to records, these tanks were emptied and closed. There were also two large aboveground silos on site. The Petroleum Bulk Storage (PBS) facility number is 2-608875, and the Chemical Bulk Storage (CBS)facility number is 2-000444 both of which are closed. Liquid plasticizers stored included bis(2-ethylhexyl)phthalate, bis(2-ethylhexyl)adipate, and palatinol 711P phthalate. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a

remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable unit 1 (OU1) is the on-site source area and associated contamination. OU2 consists of the off-site groundwater and soil vapor plumes. Site Geology and Hydrogeology: Soil at the site consists of a layer of urban fill extending from the surface to about 8 feet below the original onsite slab, underlain by sand, silty sand and/or sandy silt. Groundwater is encountered at a depth of approximately 10 to 15 feet below grade surface and flows generally westerly to northwesterly towards the East River.

Assessment:

Nature and Extent of Contamination prior to remediation: Soil and groundwater samples from both on-site and off-site were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), PCBs, pesticides and metals. Based upon investigation conducted to date, the primary contaminants of concern for both OU1 and OU2 include phthalates (specifically bis(2-ethylhexyl) phthalate and di-n-octyl phthalate) and VOCs (specifically trichloroethylene and its decomposition products). Soil - VOCs in soil are found both on and off-site at levels above unrestricted use soil cleanup objectives (UUSCOs) in a limited area in the northeast portion of the site and extending off-site beneath the sidewalk on the south side of Clay Street. The highest soil contamination concentration of trichloroethylene (TCE) was reported at 14 parts per million (ppm) compared to the UUSCO of 0.47 ppm. Other VOCs detected above the UUSCOs include: cis-1,2-dicholoretheylene (DCE) with maximum concentration of 2.4 ppm (UUSCO is 0.25 ppm). SVOCs in soil were identified both onsite and off-site above UUSCOs, including bis(2-ethylhexyl) phthalate (DEHP) at a concentration of 59,200 ppm (UUSCO is 50 ppm) and di-n-octyl phthalate (DOP) at a concentration of 3,010 ppm (UUSCO is 100 ppm). The following site-specific chemicals were identified in soil exceeding the restricted residential SCOs: bis(2-ethylhexyl) phthalate, di-n-octyl phthalate, cis-1,2-dichloroethene, and TCE. Groundwater - Phthalates are present as an LNAPL plume floating on the groundwater surface beneath most of the site and extending off-site to the west and southwest. Dissolved-phase phthalates were detected above NYSDEC groundwater standards in several wells generally located on the periphery of the LNAPL plume. The maximum concentration of DEHP was reported at 1,750 parts per billion or ppb (compared to the groundwater standard of 5 ppb) and DOP at 87.1 ppb (compared to the groundwater standard of 50 ppb). Dissolved-phase TCE and its associated breakdown product DCE were found in the northeast portion of the site and extending a short distance off-site to the northwest at concentrations exceeding the groundwater standards of 5 ppb. The maximum concentrations of TCE was reported at 33,000 ppb, and DCE at 2,700 ppb. Soil Vapor - VOCs were detected in on-site sub-slab soil vapor beneath the northeastern portion of the site building with the greatest impacts coinciding with the chlorinated VOC-impacted groundwater in this area. Sub-slab vapor contaminant concentrations were detected up to a maximum of 43,000 micrograms per cubic meter (ug/m3) for TCE, 2,500 ug/m3 for PCE, and 3,700 ug/m3 for DCE.

Materials Information

Waste Name: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: BIS(2-ETHYLHEXYL)PHTHALATE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: DIOCTYL PHTHALATE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: Chrysene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: FLUORENE
Waste Quantity: UNKNOWN

Waste Code:

Waste Name: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: North Brooklyn Development Corporation
Owner Street: 148-150 Huron Street
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 01
Sub Type: E
Owner Name: David Speiser
Owner Company: Dupont Street Owner LLC
Owner Street: 520 Madison Avenue, Suite 3501
Owner Street 2:
Owner City: New YoRk
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name: Jennifer gonzalez
Owner Company: NYSDEC Region 2 Headquarters
Owner Street: 47-40 21st Street
Owner Street 2:
Owner City: Long Island City
Owner State: NY
Owner Zip: 11101
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Brooklyn Community Board No. 1
Owner Street: 435 Graham Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11211
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: YYWONG

Record Added: 2009-08-04 08:09:00
Record Updated: 2014-03-25 13:10:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Projects Information

Project Code: 02

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2019-03-28 00:00:00
End Status: ACT
Operable Unit ID: 1172355
Operable Unit: 01
Operable Unit Desc: For OU 01 Remedial Program
Code Name: Remedial Investigation

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2023-05-16 00:00:00
End Status: ACT
Operable Unit ID: 1238386
Operable Unit: 02
Operable Unit Desc: Off-site
Code Name: Remedial Design

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2019-03-28 00:00:00
End Status: ACT
Operable Unit ID: 1238386
Operable Unit: 02
Operable Unit Desc: Off-site
Code Name: Remedial Investigation

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2023-05-16 00:00:00
End Status: ACT
Operable Unit ID: 1172355
Operable Unit: 01
Operable Unit Desc: For OU 01 Remedial Program
Code Name: Remedial Design

Environmental Remediation

Operable Unit: 02
Contaminants: bis(2-ethylhexyl)phthalate, dichloroethene (cis-1,2-), dioctyl phthalate, trichloroethene (TCE), vinyl chloride

Operable Unit: 01A
Contaminants: bis(2-ethylhexyl)phthalate, dichloroethene (cis-1,2-), dioctyl phthalate, trichloroethene (TCE), vinyl chloride

Operable Unit: 01
Contaminants: bis(2-ethylhexyl)phthalate, dichloroethene (cis-1,2-), dioctyl phthalate, trichloroethene (TCE), vinyl chloride

Operable Unit: 00
Contaminants: bis(2-ethylhexyl)phthalate, dichloroethene (cis-1,2-), dioctyl phthalate, trichloroethene (TCE), vinyl chloride

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
177	2 of2	WNW	0.36 / 1,893.31	13.44 / 1	Former NuHart East 65 Dupont Street and 75 Dupont Street Brooklyn NY 11222	BROWNFIELDS

Site Code: 578905
HW Code: C224287
Program: BCP
Site Class: C
Site Name: Former NuHart East
Site Address: 65 Dupont Street and 75 Dupont Street
City: Brooklyn
Zip: 11222
County: Kings

Region:	2
Town:	New York City
Latitude:	40.736055556
Longitude:	-73.957216667
SWIS:	2401
Acres:	1.120
Record Added:	2018-10-30 09:48:00
Record Update:	2023-12-27 13:16:00
Updated by:	AMSERVIS
Site Code (Web):	C224287
Program Type (Web):	BCP
Site Name (Web):	Former NuHart East
Site Class (Web):	C
Address1 (Web):	65 Dupont Street and 75 Dupont Street
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.957216667
Latitude (Web):	40.736055556
Site Code (GIS):	C224287
Site Name (GIS):	Former NuHart East
Program (GIS):	BCP
Site Class (GIS):	C
Address1 (GIS):	65 Dupont Street and 75 Dupont Street
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Site Class Desc (Web):	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH:	Remedial actions are complete, the site was cleaned up to meet unrestricted use, and all known exposure pathways were addressed by the remedy for the site.

Description:

Site Location: The site is located in an urban area at 65 Dupont Street and 75 Dupont Street in the Greenpoint neighborhood of Brooklyn, NY. The approximately 1.12-acre site is identified on the New York City tax map as block 2487, Lot 18 (formerly lots 17, 18, 20, 21, and 57) and a portion of new Lot 17. The site is bounded by Clay Street followed by industrial and manufacturing buildings to the north, residential apartment buildings to the east, Dupont Street followed by residential apartment buildings and a senior living facility to the south, and the Former NuHart Plastic Manufacturing site, an inactive hazardous waste site, to the west. Site Features: Construction for the new development is currently ongoing. Current Zoning and Land Use: All five lots are within an MX-8 Special Mixed-Use District and currently zoned M1-2/R6A (manufacturing with a residential overlay). Surrounding land uses include commercial and industrial properties to the north, the Former NuHart Site (site no. 224136) to the west, and residential properties (single and multi-family) to the south. There are no schools or daycare facilities identified within 1,000 feet of the project site. There were no nursing homes or hospitals identified within 1,000 feet of the site. The Dupont Street Senior housing complex is located just south of the site at 80 Dupont Street. Past Use of the Site: The site was developed since at least 1887 and was used for metalworking, manufacture of light fixtures, soap, and water-proofing materials through 1950. From 1950 until 2004 the site and associated manufacturing buildings to the west were used by the NuHart Company for the production, storage, and shipping of plastic and vinyl products. Operations ceased in 2004 and the site buildings have been vacant since that time. Site Geology and Hydrogeology: The site is underlain by a layer of urban fill consisting of mainly brown silty sand with asphalt, concrete, and brick fragments. Fill extends to a depth of approximately 5 feet below grade surface. Brown silty sands, fine to medium sands, and clay layers underlay the urban fill layer. Groundwater was encountered at approximately 5 to 10 feet below grade surface, and groundwater flow beneath the site is generally to the west-northwest towards the East River.

Assessment:

Remediation at the site is complete. Prior to remediation the primary contaminants of concern were petroleum products in soil and groundwater associated with the underground storage tanks in the northeast portion of the site; SVOCs and metals in soil related to urban fill throughout the site.

Remedial action has successfully achieved soil cleanup objectives for unrestricted use. Prior to remediation: Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substances (PFAS), and pesticides. Soil vapor was analyzed for VOCs. Based upon the investigations conducted to date, the primary contaminants of concern at the site are petroleum products in soil and groundwater associated with the underground storage tanks (USTs) in the northeast portion of the site, SVOCs and metals associated with urban fill in shallow soil throughout the site, and VOCs in soil vapor in the northwest portion of the site associated with the adjacent Former NuHart Plastic Manufacturing site. Soil - VOCs exceeding unrestricted use soil cleanup objective (UUSCOs) were detected in soil in northern portion of the site near the closed in place underground storage area. VOCs identified at the site include acetone at 11 parts per million (ppm) (UUSCO is 0.05 ppm), 1,2,4-trimethylbenzene at 11 ppm (UUSCO is 3.6 ppm), naphthalene at 14 ppm (UUSCO is 12 ppm), and xylenes at 3 ppm (UUSCO is 0.26 ppm). SVOCs detected at levels exceeding UUSCOs in soil throughout the site include benzo(a)anthracene up to 9.2 ppm (UUSCO is 1 ppm), benzo(a)pyrene up to 8.4 ppm (UUSCO is 1 ppm), benzo(b)fluoranthene up to 11 ppm (UUSCO is 1 ppm), and chrysene up to 9.8 ppm (UUSCO is 1 ppm). Metals detected at levels exceeding UUSCOs include lead up to 2500 ppm (UUSCO is 63 ppm), mercury up to 1.27 ppm (UUSCO is 0.18 ppm), arsenic up to 22.9 ppm (UUSCO is 13 ppm), and barium up to 490 ppm (UUSCO is 350 ppm). The PFAS compound perfluorooctanoic acid (PFOA) was detected at 0.293 parts per billion (ppb), below its unrestricted use guidance value of 0.66 ppb. Perfluorooctanesulfonic acid (PFOS) was detected in soil at concentrations up to 0.293 ppb, below its unrestricted use guidance value of 0.88 ppb. Data does not indicate any off-site impacts in soil related to this site. Groundwater - Separate phase petroleum products are present in the north portion of the site near the closed-in-place fuel oil USTs. VOCs were detected in groundwater at concentrations exceeding the ambient water quality standards (AWQS), including trichloroethene (TCE) up to 7400 ppb (AWQS of 5 ppb), ethylbenzene up to 11 ppb (AWQS of 5 ppb), xylene up to 11 ppb (AWQS of 5 ppb), and naphthalene up to 110 ppb (AWQS of 5 ppb). The TCE is associated with the adjacent Former NuHart Plastic Manufacturing site. SVOCs were detected at concentrations exceeding the AWQS including benzo(a)anthracene up to 0.12 ppb, benzo(b)fluoranthene up to 0.16 ppb, and chrysene up to 0.14 ppb (each has AWQS of 0.002 ppb), and bis(2-ethylhexyl) phthalate up to 61 ppb (AWQS of 5 ppb). Dissolved metals were detected at concentrations exceeding the AWQS include sodium, manganese and magnesium, all of which are naturally occurring and are related to the site's proximity to saline surface water. For PFAS compounds, PFOS and PFOA were reported at concentrations up to 15.8 parts per trillion (ppt) and 393 ppt respectively, exceeding the maximum contaminant levels (MCLs) (drinking water standard) of 10 ppt each in groundwater. The compound 1,4-dioxane was detected up to 1.74 ppb (MCL of 1 ppb). Data does not include any off-site impacts in groundwater related to this site. Soil Vapor - The total cumulative maximum concentration for the petroleum-related VOCs benzene, toluene, ethylbenzene, and xylenes (BTEX) compounds was 1,980 micrograms per cubic meter (ug/m3). In addition, TCE was found up to 14,000 ug/m3, tetrachloroethene (PCE) up to 850 ug/m3, 1,1,1-trichloroethane up to 11,200 ug/m3. Data does not indicate any off-site impacts in soil vapor related to this site.

Materials Information

Waste Name: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: barium
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: arsenic
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,1,1-trichloroethane
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: chrysene
Waste Quantity: UNKNOWN

Waste Code:

Waste Name: naphthalene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: lead
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: petroleum products
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: acetone
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Brooklyn Public Library - Williamsburg Branch
Owner Street: 240 Division Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11207
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: David Speiser
Owner Company: Dupont Street 1 LLC
Owner Street: 520 Madison Avenue, Suite 3501
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 01
Sub Type: NNN
Owner Name: zachary Kadden
Owner Company: Dupont Street Owner LLC
Owner Street: 520 Madison Avenue, Suite 3501
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 01
Sub Type: P03
Owner Name: David Speiser
Owner Company: Dupont Street Owner 2 LLC
Owner Street: 520 Madison Avenue, Suite 3501
Owner Street 2:
Owner City: New York

Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: David Speiser
Owner Company: Dupont Street Owner 2 LLC
Owner Street: 520 Madison Avenue, Suite 3501
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: zachary Kadden
Owner Company: Dupont Street Owner LLC
Owner Street: 520 Madison Avenue, Suite 3501
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Brooklyn Public Library - Greenpoint Branch
Owner Street: 107 Norman Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Brooklyn Community Board 1
Owner Street: 435 Graham Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11211
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: JHOCONNE

Record Added: 2019-01-17 09:19:00
Record Updated: 2023-12-12 08:49:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Projects Information

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 2023-12-27 00:00:00
End Status: ACT
Operable Unit ID: 1326638
Operable Unit: 01

Operable Unit Desc: Remedial Program
Code Name: Remedial Action

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2022-09-06 00:00:00
End Status: ACT
Operable Unit ID: 1326638
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2022-09-06 00:00:00
End Status: ACT
Operable Unit ID: 1326638
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Design

Project Code: 25
Project Desc:
Project Refer Name:
End Date: 2023-12-27 00:00:00
End Status: ACT
Operable Unit ID: 1403985
Operable Unit: 00
Operable Unit Desc: Site Management
Code Name: Certificate of Completion

Environmental Remediation

Operable Unit: 01
Contaminants: 1,1,1-trichloroethane, 1,2,4-trimethylbenzene, acetone, arsenic, barium, benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, bis(2-ethylhexyl)phthalate, chrysene, lead, mercury, naphthalene, petroleum products, tetrachloroethene (PCE), trichloroethene (TCE)

Operable Unit: 00
Contaminants: 1,1,1-trichloroethane, 1,2,4-trimethylbenzene, acetone, arsenic, barium, benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, bis(2-ethylhexyl)phthalate, chrysene, lead, mercury, naphthalene, petroleum products, tetrachloroethene (PCE), trichloroethene (TCE)

178	1 of1	WNW	0.36 / 1,893.59	13.91 / 2	**Clay Properties LLC** **19-27 Clay Street and 60-62 Commercial Street** **Brooklyn NY 11222**	BROWNFIELDS

Site Code: 652671
HW Code: C224390
Program: BCP
Site Class: A
Site Name: Clay Properties LLC
Site Address: 19-27 Clay Street and 60-62 Commercial Street
City: Brooklyn
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.736536111
Longitude: -73.957169444
SWIS: 2401
Acres: 0.237
Record Added: 2023-06-05 14:30:00
Record Update: 2024-08-02 11:55:00

Updated by:	AAOBLIGA
Site Code (Web):	C224390
Program Type (Web):	BCP
Site Name (Web):	Clay Properties LLC
Site Class (Web):	A
Address1 (Web):	19-27 Clay Street and 60-62 Commercial Street
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.957169444
Latitude (Web):	40.736536111
Site Code (GIS):	C224390
Site Name (GIS):	Clay Properties LLC
Program (GIS):	BCP
Site Class (GIS):	A
Address1 (GIS):	19-27 Clay Street and 60-62 Commercial Street
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Site Class Desc (Web):	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Assess DOH:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.

Description:

Location: The approximate 0.237-acre site is located at 19-27 Clay Street and 60-62 Commercial Street in Greenpoint section of Brooklyn, New York and is identified as Block 2482 lots 9 and (tentative) 10 on the New York City tax map. The site is bounded by Commercial Street to the north, Clay Street to the south, a construction site and vacant lot to the east, and the Brownfield Cleanup Program (BCP) 50 commercial Street development site, No. C224278, to the west. Site Features: There is 1) a two-story unoccupied warehouse located at 19-27 Clay Street (Lot 9) and 2) a vacant yard area located at 60-62 Commercial Street (Lot 10). The site is gated to avoid any trespassers entering the premises. The yard is currently in use as a construction staging and delivery area for the adjacent construction site at 68 Commercial Street (not a part of the BCP site) Current Zoning and Land Use: The site is currently unoccupied and the current zoning designation is M1-2-R6. The Site is located within a densely developed mixed-use area. Adjoining and surrounding land uses are as follows: North: Commercial Street and a 4-story residential building (74 Commercial Street), followed by a NYC Transit facility (65 Commercial Street), an undeveloped lot (33-35 Commercial Street) and a high-rise building under construction (1-3 Bell Slip). South: Clay Street, followed by BCP ID C224287, Former NuHart East Site with a residential building currently under construction (65 Dupont Street), four 1- and 2-familiy residences (38-46 Clay Street) and a mixed-use (residential (48 Clay Street). East: Vacant Lot (29 Clay Street), construction site (68 Commercial Street) and a 7-story mixed-use (retail-residential) building (1133 Manhattan Avenue), followed by two mixed-use buildings and Manhattan Avenue. West: BCP ID C224278 50 Commercial Street Development (50 Commercial Street) is currently being remediated and redeveloped. Past Use of the Site: The site was utilized for various industrial and manufacturing operations including an iron works, a tin can storage facility, a cotton batting company, a paper storage warehouse, and "non-specific manufacturing use". Interflo Technologies operated at 19 Clay Street (Lot 9) as a Registered Resource Conservation and Recovery Act (RCRA) small quantity hazardous waste generator from at least July 1994 to January 1997. Interflo Technologies generated ignitable, halogenated, non?halogenated solvents and mercury waste under USEPA ID No. NY0000374314. Multiple RCRA violations were identified for the site; however, all were addressed to the satisfaction of USEPA. Sanborn History: 1887-1905: The Site is developed with multiple structures identified as the Logan Iron Works, including a blacksmith shop, a flange shop. Commercial Street and additional portions of the iron works are to the north, followed by a sugar refinery. 1916: The Site is developed consistent with the 1905 map depictions; however, the buildings are now identified as a tin can storage facility. 1942-1951: The Site is now a 2-story structure occupied by a cotton batting manufacturer along Clay and the northern portion of the property are undeveloped. This is consistent with the existing building. 1965: The building is identified as occupied by non-specific manufacturing uses. The northern portion of the property is identified as a lumber storage yard. Site Geology and Hydrogeology: According to the recent Phase II Investigation (dated March 2023) the depth to groundwater in the vicinity of the Site is approximately 6-8 feet below grade surface. Based upon data provided on the above-referenced groundwater elevation map, regional groundwater flow direction in the vicinity of the Site is anticipated to flow west-northwest.

Assessment:

Nature and Extent of Contamination: soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Soil vapor was analyzed for VOC. Based on investigations conducted to date at the subject property, the primary contaminants of concern for the site are Chlorinated solvents, (include PCE, TCE and its degradation products) were detected in soil, groundwater and soil vapor above applicable standards and guidance values. Soil – Trichloroethylene (TCE) was detected in soil 0-2 feet below grade surface (bgs) above the Protection of Groundwater soil cleanup objectives (PGSCO) and Restricted Residential SCO (RRSCO) with a max concentration of 21 parts per million (ppm). The following semi-volatile organic compounds were detected in soil exceeding the RRSCO: benzo(a) anthracene (max 15 ppm); benzo(a) pyrene (max. 13.1 ppm); benzo(b)fluoranthene (max. 12 ppm), benzo(k)fluoranthene (max. 10.9 ppm); chrysene (Max. 13.9 ppm); dibenzo(a,h)fluoranthene (max 3.270 ppm) and indeno(1,2,3-cd)pyrene (max. 8.73 ppm). The following metals were detected in soil

exceeding the RRSCO: Arsenic (Max 23.2 ppm); mercury (max 4.28 ppm), barium (max. 513 ppm); cadmium (max. 6.14 ppm); copper (max. 303 ppm); lead (max. 6870 ppm); and manganese (max. 3260 ppm). No pesticides were detected in soil above restricted residential use SCOs. PCBs was detected above the RRSCO with a max concentration of 7.9 ppm. No PFAS or 1, 4-dioxane detection above unrestricted use SCO. Groundwater – VOCs detected in groundwater above class GA standards includes the following: PCE with maximum concentration of 6.2 parts per billion (ppb), TCE with maximum concentration of 6,370 ppb, cis-1,2-dichloroethene with maximum concentration of 1340 ppb, vinyl chloride with maximum concentration of 60.4 ppb,. No SVOCs, pesticides, PCBs or metals were detected above the Class GA Standards. Three dissolved metals (lead, manganese and sodium) were reported at concentration exceeding the Groundwater standard. Soil Vapor – PCE was detected in soil vapor sample with max concentration of 4500 micro gram per cubic meter (ug/m3); TCE with max concentration of 740,000 ug/m3; Cis-1,2-dichloroethylene with max. concentration of 120 ug/m3.

Owner Information

Owner Op:	06
Sub Type:	P03
Owner Name:	Idan Shitrit
Owner Company:	Clay Properties LLC
Owner Street:	134 North 4th Street
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11249
Country:	United States of America

Owner Op:	19
Sub Type:	NNN
Owner Name:	
Owner Company:	Brooklyn Public Library - Greenpoint Branch
Owner Street:	107 Norman Avenue
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11222
Country:	United States of America

Owner Op:	01
Sub Type:	P03
Owner Name:	Idan Shitrit
Owner Company:	Clay Properties LLC
Owner Street:	134 North 4th Street
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11249
Country:	United States of America

Owner Op:	19
Sub Type:	NNN
Owner Name:	
Owner Company:	Brooklyn Community District 1
Owner Street:	435 Graham Avenue
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11221
Country:	United States of America

Environmental Remediation

Operable Unit:	01
Contaminants:	

179	*1 of2*	*NW*	*0.36 / 1,899.59*	*9.96 / -2*	***MANHATTAN AVE. RECYCLING CORP.*** ***1166 MANHATTAN AVE.*** ***Brooklyn NY 11222***	***SWF/LF***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Activity Number: [24T54]
Facility Name (Act):
Location Addr (Act):
Location Addr2 (Act):
City (Act):
State (Act):
Zip Code (Act):
County (Act):
East Coord (Act):
North Coord (Act):
Facility Name:
Location Addr:
Location Addr2:
City:
State:
Zip Code:
County:
East Coord:
North Coord:
Data Source: SWMF - Inactive Facility Lists

Facility Name (InAct): MANHATTAN AVE. RECYCLING CORP.
Location Addr (InAct): 1166 MANHATTAN AVE.
Loc Addr2(InAct):
City (InAct): Brooklyn
State (InAct): NY
Zip Code (InAct): 11222
County (InAct): Kings
East Coord (InAct): 588200
North Coord (InAct): 4510200

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:
Activity Desc: Transfer station - permit
Regulatory Status:
Active: No
Dt of Last Inspection:
Expiration Dt:
Owner Type:
Owner Name:
Owner Address:
Owner Address2:
Owner City:
Owner State:
Owner Zip:
Owner Phone:
Owner Email:
Waste Types:

Authorization No: 2-6101-00069
Authrzation Issue Dt:
Operator Type:
Operator Name:
Phone No:
Region: 2
Contact Name: JULIAN FILIPONE; PRESIDENT
Contact Address:
Contact Address2:
Contact City:
Contact State:
Contact Zip:
Contact Phone:
Contact Email:

179	2 of2	NW	0.36 / 1,899.59	9.96 / -2	NEW YORK RECYCLERS; INC. (Manhattan Ave) 1166-68 MANHATTAN AVENUE Brooklyn NY 11222	SWF/LF

Activity Number: [24WE7]
Facility Name (Act):
Location Addr (Act):
Location Addr2 (Act):
City (Act):
State (Act):
Zip Code (Act):
County (Act):
East Coord (Act):
North Coord (Act):
Facility Name:
Location Addr:
Location Addr2:
City:
State:
Zip Code:
County:
East Coord:
North Coord:
Data Source: SWMF - Inactive Facility Lists

Facility Name (InAct): NEW YORK RECYCLERS; INC.(Manhattan Ave)
Location Addr (InAct): 1166-68 MANHATTAN AVENUE
Loc Addr2(InAct):
City (InAct): Brooklyn
State (InAct): NY
Zip Code (InAct): 11222
County (InAct): Kings
East Coord (InAct): 588210
North Coord (InAct): 4510151

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		***Authorization No:***	
Activity Desc:	C&D processing - registration	***Authrzation Issue Dt:***	
Regulatory Status:		***Operator Type:***	
Active:	No	***Operator Name:***	
Dt of Last Inspection:		***Phone No:***	7183492540
Expiration Dt:		***Region:***	2
Owner Type:		***Contact Name:***	TIMOTHY FULTON
Owner Name:		***Contact Address:***	
Owner Address:		***Contact Address2:***	
Owner Address2:		***Contact City:***	
Owner City:		***Contact State:***	
Owner State:		***Contact Zip:***	
Owner Zip:		***Contact Phone:***	
Owner Phone:		***Contact Email:***	
Owner Email:			
Waste Types:			

180	*1 of1*	*NW*	*0.37 / 1,945.91*	*11.06 / -1*	***PENSATO INDUSTRIES*** ***BROOKLYN NY***	***PFAS IND***

Status:	Active	***Fac Fips Code:***	36047
Fac Indian Cntry Flg:	No	***Compliance Status:***	No Violation Identified
Fac Derived Huc:	02030201	***EPA Programs:***	CAA; RCRA
Fac Derived Wbd:	020301010405	***Federal Facility:***	No
Fac Derived Cd113:	12	***Federal Agency:***	-
Fac Derived Cb2010:	360470563001001	***Fac Snc Flg:***	No
Fac Informal Count:	0	***AIR Flag:***	Yes
Last Informal Action:	-	***NPDES Flag:***	No
Formal Action Count:	0	***SDWIS Flag:***	No
Last Formal Action:	-	***RCRAFlag:***	Yes
Fac Total Penalties:	0	***TRI Flag:***	No
Fac Penalty Count:	-	***GHG Flag:***	No
Date Last Penalty:	-	***TRI IDs:***	-
Last Penalty Amt:	-	***TRI Releases Trnsfrs:***	-
Fac Qtrs With Nc:	0	***TRI on Site Releases:***	-
Programs With Snc:	0	***TRI off Site Trnsfrs:***	-
Fac Percent Minority:	42.941	***TRI Reporter:***	-
Fac Pop Den:	49047.77	***Fac Imp Water Flg:***	-
Count:	1	***Fac Major Flag:***	-
Fac County:	KINGS	***Fac Active Flag:***	Yes
State Other :		***Fac Inspection Count:***	0
Region:	02	***Date Last Inspection:***	-
Latitude:	40.73813	***Days Last Inspection:***	-
Longitude:	-73.95548		
Fac Derived Tribes:	-		
AIR IDs:	NY0000002610100241		
CAA Permit Types:	Minor Emissions		
CAA NAICS:	999999		
CAA SICS:	2499		
NPDES IDs:	-		
CWA Permit Types:	-		
CWA NAICS:	-		
CWA SICS:	-		
RCRA IDs:	NYD987023132		
RCRA Permit Types:	Other		
RCRA NAICS:	314999		
SDWA IDs:	-		
SDWA System Types:	-		
SDWA Compliance Status:	-		
SDWA Snc Flag:	No		
Fac Collection Meth:	ADDRESS MATCHING-HOUSE NUMBER		
EJSCREEN Flag Us:	Yes		
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.95548,%22y%22:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

40.73813,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

ECHO Facility Report: https://echo.epa.gov/detailed-facility-report?fid=110009206689

Industry: Textiles and Leather

---

181 | ***1 of1*** | ***WNW*** | ***0.37 / 1,958.11*** | ***13.02 / 1*** | ***49 Dupont Street 49 Dupont Street Greenpoint NY 11222*** | ***BROWNFIELDS***

Site Code: 420821
HW Code: C224136
Program: BCP
Site Class: N
Site Name: 49 Dupont Street
Site Address: 49 Dupont Street
City: Greenpoint
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.735698199
Longitude: -73.958229607
SWIS: 2401
Acres: 2.810
Record Added: 2009-10-22 10:30:00
Record Update: 2010-08-24 09:45:00
Updated by: YYWONG
Site Code (Web): C224136
Program Type (Web): BCP
Site Name (Web): 49 Dupont Street
Site Class (Web): N
Address1 (Web): 49 Dupont Street
Address2 (Web):
Locality (Web): Greenpoint
Zip Code (Web): 11222
County (Web): Kings
Longitude (Web): -73.958229607
Latitude (Web): 40.735698199
Site Code (GIS): C224136
Site Name (GIS): 49 Dupont Street
Program (GIS): BCP
Site Class (GIS): N
Address1 (GIS): 49 Dupont Street
Address2 (GIS):
Locality (GIS): Greenpoint
Zip Code (GIS): 11222
County (GIS): Kings
Site Class Desc: No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Site Class Desc (Web): No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does

not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH:
Description:

The site is located in the Greenpoint section of Brooklyn in a mixed industrial/commercial/ residential area. The building consists of a number of smaller buildings that have been joined together. The dimensions of the footprint of the one large building are approximately 400 feet by 200 feet. A line of row houses is situated across the street to the south. Commercial buildings are situated directly across the street to the north. To the west is a park and to the northwest is a paved lot which is used for truck storage. The site has been in existence since 1887. It has been used for manufacturing, as an office, as storage, and for shipping and receiving. Prior to 1950, the site was used as a boiler shop for Logan Ironworks, two stables, a gas and light fixture factory, a sheet metal works, a soap factory, a waterproofing factory, and a scrap metal facility. From 1983 to 2004, NuHart & Company made vinyl siding and sheeting at the site. After 2004, NuHart & Company removed all of their equipment and offices. The site is now used for the storage of plastic wrapping and many large (36 cu. ft.) fabric bags containing pellets of resin. There are 17 underground storage tanks located on the site and two large silos above ground at the west end of the building. The Petroleum Bulk Storage (PBS)number is 2-608875 (for 13 registered tanks). The site is a former Chemical Bulk Storage (CBS) facility #2-000444 with 5 plasticizer tanks. Liquid plasticizers stored included bis(2-ethylhexyl)tertphthalate, bis(2-ethylhexyl)adipate, and palatinol 711P phthalate. The requestor withdrew the application, and the site was listed on the Registry of Inactive Hazardous Waste disposal site as of June 2010 (see site no. 224136).

Assessment:

The plasticizers bis(2-ethylhexyl)phthalate anddi-n-octylphthalate, as well as #4 fuel oil have been found in groundwater (both as non-aqueous phase liquid and in the dissolved phase) and in soil. From 1983 to 2004 NuHart & Company (the tenant) manufactured vinyl siding and sheeting at the factory. After manufacturing ceased in 2004, environmental investigations were performed. The investigations identified soil and groundwater contamination consisting of liquid plasticizers and petroleum. The amount of each material that was released is unknown. Soil concentrations as high as 20,000,000 ppb of bis(2-ethylhexyl)phthalate were detected in soil boring SB-44. Non-aqueous phase liquid (NAPL) was found at thicknesses of up to 5 feet in one well. A large plume of plasticizer NAPL was identified under the western end of the factory where the plasticizer USTs were located. This plume had migrated off-site in a northwesterly direction. A small plume of mostly #4 oil NAPL was identified under the northeast corner of the factory and had migrated a shorty distance off site. The environmental remediation which followed involved cleaning the floors of the factory, cleaning out the underground storage tanks, cleaning all sumps and pipe gallery wells, installing monitoring wells, and installing NAPL collection wells and equipment. The NAPL plumes have now been reduced in size and consist of three separate plumes. All of the plumes are contained under the sidewalks bounding the factory and under the footprint of the building. The smallest plume is under the northeast corner of the site. The former large plume under the western end of the factory is now two separate plumes (according to the November 26, 2008 gauging event) and consist solely of plasticizers. The thickness of the NAPL ranges from 0.16 feet to 1.38 feet. Product collection from these two plumes is continuing and, as of December 2008, has recovered a total of 8,356 gallons of NAPL.

Owner Information

Owner Op:	01
Sub Type:	01
Owner Name:	JOSEPH FOLKMAN
Owner Company:	49 DUPONT REALTY CORP.
Owner Street:	49 DUPONT STREET
Owner Street 2:	
Owner City:	BROOKLYN
Owner State:	NY
Owner Zip:	11222
Country:	United States of America

Owner Op:	06
Sub Type:	P02
Owner Name:	JOSEPH FOLKMAN
Owner Company:	49 DUPONT REALTY CORP.
Owner Street:	49 DUPONT STREET
Owner Street 2:	
Owner City:	BROOKLYN

Owner State: NY
Owner Zip: 11222
Country: United States of America

Environmental Remediation

Operable Unit: 01
Contaminants:

---

182 | **1 of2** | **SW** | **0.37 / 1,960.32** | **23.47 / 11** | **111 MILTON ST/BKLYN**
111 MILTON STREET
NEW YORK CITY NY | **LST**

Spill No: 8911087
Site ID: 219108
DER Facility ID: 181207
CID:
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Overfill
Water Body:
Class:
Meets Std: True
Penalty: False
County: Kings
Referred to:
Reported by: Responsible Party
Source: Tank Truck
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: False
Spill Date: 02/21/1990 02:00:00 PM
Rcvd Date: 02/21/1990 02:44:00 PM
CAC Date: 02/22/1990 12:00:00 AM
Insp Date:
Close Date: 02/22/1990 12:00:00 AM
Create Date: 05/11/1990 12:00:00 AM
Update Date: 09/30/2004 09:28:29 PM
DEC Region: 2
Lead DEC: WILSON
After Hours: False

Caller Remark:

"AIR BUBBLE DEVELOPED IN FILL PIPE WHEN NOZZLE DISENGAGED, SPILL ON CONCRETE, SORBENT PADS USED & DISPOSED OF."

Dec Remark:

""

Material Information

OP Unit ID: 938074
OU: 01
Material ID: 440629
CAS No:
Material Family: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0001A
Material Name: #2 fuel oil

Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: BAERENKLAU
Spiller Address:
Spiller City:
Spiller State: ZZ
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Contact Ext:						
Latitude:		40.709425000				
Longitude:		-74.010184000				

182	2 of2	SW	0.37 / 1,960.32	23.47 / 11	111 MILTON STREET 111 MILTON STREET BROOKLYN NY	LST

Spill No:	9312646	**REM Phase:**	0
Site ID:	219109	**UST Trust:**	False
DER Facility ID:	279871	**Spill Date:**	01/27/1994 01:30:00 PM
CID:		**Rcvd Date:**	01/27/1994 02:05:00 PM
Program Type:	ER	**CAC Date:**	01/27/1994 12:00:00 AM
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Overfill	**Close Date:**	01/27/1994 12:00:00 AM
Water Body:		**Create Date:**	01/28/1994 12:00:00 AM
Class:	C4	**Update Date:**	09/30/2004 09:28:29 PM
Meets Std:	True	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	KSTANG
County:	Kings	**After Hours:**	False
Referred to:			
Reported by:	Responsible Party		
Source:	Private Dwelling		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"PUT DOWN SPEEDY DRY - WILL CLEAN"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "

Material Information

OP Unit ID:	991300	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	388066	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	1.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	BAERENKLAU OIL CO.
Spiller Address:	740 JAMAICA AVENUE
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.729323990
Longitude:	-73.956271690

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
183	1 of1	SE	0.37 / 1,974.30	11.04 / -1	DEPT CONSUMER AFFAIRS 245 MESEROLE AVE GREENPOINT BROOKLYN NY	LST

Spill No:	0305945	**REM Phase:**	0
Site ID:	122817	**UST Trust:**	False
DER Facility ID:	106460	**Spill Date:**	09/03/2003 09:00:00 AM
CID:	211	**Rcvd Date:**	09/04/2003 08:14:00 PM
Program Type:	ER	**CAC Date:**	
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Overfill	**Close Date:**	09/05/2003 12:00:00 AM
Water Body:		**Create Date:**	09/04/2003 12:00:00 AM
Class:	C4	**Update Date:**	09/24/2003 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	JMKRIMGO
County:	Kings	**After Hours:**	True
Referred to:			
Reported by:	Citizen		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"sewer system also affected - caller states a tank was overfilled yesterday and crews from business have improperly cleaned it up they have bagged up residual product and dump it into dumpster"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD 9/4/03. J.Krimgold @ site. No access to the inside parking area. No evidence of spill outside the building. 9/5/03. J. Krimgold @ the site. During tanker-truck tank calibration, due to a human error, it was overfilled. According to the DCA manager about 20-30 gallons of diesel was spilled. Spill was contained by the spedee-dry on the paved area of the parking lot. JK ordered to pick up contaminated debris and powerwash pavement in front of the calibration area. No catch basins or sewers were affected by this release. NFA."

Material Information

OP Unit ID:	872530	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	503180	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	100.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0002A		
Material Name:	#4 fuel oil		

Spiller Information

Spiller Name:	ROBERT BODGAS
Spiller Company:	DEPT CONSUMER AFFAIRS
Spiller Address:	245 MESEROLE AV
Spiller City:	GREEN POINT (BROOKLYN)
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
184	1 of3	ENE	0.37 / 1,978.14	2.19 / -10	Allocco Recycling Ltd (Kingsland Ave) 540 Kingsland Avenue Brooklyn NY 11222	SWF/LF

Activity Number: [24M00]
Facility Name (Act): Allocco Recycling Ltd (Kingsland Ave)
Location Addr (Act): 540 Kingsland Avenue
Location Addr2 (Act):
City (Act): Brooklyn
State (Act): NY
Zip Code (Act): 11222
County (Act): Kings
East Coord (Act): 588653;588875;589120
North Coord (Act): 4509421;4509644;4509887
Facility Name (InAct):
Location Addr (InAct):
Loc Addr2(InAct):
City (InAct):
State (InAct):
Zip Code (InAct):
County (InAct):
East Coord (InAct):
North Coord (InAct):
Facility Name: Allocco Recycling Ltd (Kingsland Ave)
Location Addr: 540 Kingsland Avenue
Location Addr2:
City: Brooklyn
State: NY
Zip Code: 11222
County: Kings
East Coord: 588653;588875;589120
North Coord: 4509421;4509644;4509887
Data Source: SWMF - Active Facility Lists; SWMF - Active Solid Waste Management Facilities as of 08-17-2023

SWMF - Active Facility Lists Details(Act)

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Regulatory Status: Exempt
Active: Yes
Dt of Last Inspection:
Expiration Dt:
Owner Type: Private
Owner Name: Alan Friedman
Owner Address: 203 Vineland Avenue
Owner Address2:
Owner City: Staten Island
Owner State: NY
Owner Zip: 10312
Owner Phone:
Owner Email: ibyscrap@aol.com
Waste Types:
Authorization No:
Authrzation Issue Dt:
Operator Type:
Operator Name:
Phone No: 7183893200
Region: 2
Contact Name:
Contact Address:
Contact Address2:
Contact City:
Contact State:
Contact Zip:
Contact Phone:
Contact Email:

SWMF - Active Facility Lists Details(Act)

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Regulatory Status: Exempt
Active: Yes
Dt of Last Inspection: 2/14/2019
Expiration Dt:
Owner Type: Private
Owner Name: Michael Allocco
Owner Address: 540 Kingsland Avenue
Owner Address2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Owner Phone: 7183493094
Owner Email:
Waste Types:
Authorization No:
Authrzation Issue Dt:
Operator Type:
Operator Name: Allocco Recycling Ltd.
Phone No: 7183493094
Region: 2
Contact Name: Michael Allocco Jr
Contact Address:
Contact Address2:
Contact City:
Contact State:
Contact Zip:
Contact Phone: 7183493094
Contact Email: mike@alloccorecycling.com

SWMF - Active Facility Lists Details(Act)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Regulatory Status: None
Active: Yes
Dt of Last Inspection:
Expiration Dt:
Owner Type: Private
Owner Name: The Fortune Group
Owner Address: 239 India Street
Owner Address2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Owner Phone: 7183893000
Owner Email:
Waste Types:

Authorization No:
Authrzation Issue Dt:
Operator Type:
Operator Name:
Phone No: 7183893000
Region: 2
Contact Name:
Contact Address:
Contact Address2:
Contact City:
Contact State:
Contact Zip:
Contact Phone:
Contact Email:

Active Solid Waste Management Facilities Details as of 08-17-2023

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Active: Yes
Expiration Dt:
Geo Reference: 540 Kingsland Avenue
Brooklyn, NY 11222
(40.735029397, -73.944583868)
Region: 2
Waste Types:

Authorization No:
Authrzation Issue Dt:
Owner Type: Private
Owner Name: Michael Allocco
Phone No: 7183493094

Active Solid Waste Management Facilities Details as of 08-17-2023

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Active: Yes
Expiration Dt:
Geo Reference: 239 India Street
Brooklyn, NY 11222
(40.732846582, -73.950204269)
Region: 2
Waste Types:

Authorization No:
Authrzation Issue Dt:
Owner Type: Private
Owner Name: The Fortune Group
Phone No: 7183893000

Active Solid Waste Management Facilities Details as of 08-17-2023

Accuracy Code:
Activity Desc: RHRF - exempt (non-VDF)
Active: Yes
Expiration Dt:
Geo Reference: 304 Greenpoint Avenue
Brooklyn, NY 11222
(40.730872811, -73.947550894)
Region: 2
Waste Types:

Authorization No:
Authrzation Issue Dt:
Owner Type: Private
Owner Name: Alan Friedman
Phone No: 7183893200

184	2 of3	ENE	0.37 / 1,978.14	2.19 / -10	**Allocco Recycling Ltd (Kingsland Ave)** **540 Kingsland Avenue** **Brooklyn NY 11222**	SWF/LF

Activity Number: [24WA3]
Facility Name (Act): Allocco Recycling Ltd (Kingsland Ave)
Location Addr (Act): 540 Kingsland Avenue
Location Addr2 (Act):
City (Act): Brooklyn
State (Act): NY
Zip Code (Act): 11222

Facility Name (InAct):
Location Addr (InAct):
Loc Addr2(InAct):
City (InAct):
State (InAct):
Zip Code (InAct):
County (InAct):

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County (Act):	Kings	**East Coord (InAct):**	
East Coord (Act):	589120	**North Coord (InAct):**	
North Coord (Act):	4509887		
Facility Name:	Allocco Recycling Ltd (Kingsland Ave)		
Location Addr:	540 Kingsland Avenue		
Location Addr2:			
City:	Brooklyn		
State:	NY		
Zip Code:	11222		
County:	Kings		
East Coord:	589120		
North Coord:	4509887		
Data Source:	SWMF - Active Facility Lists; SWMF - Active Solid Waste Management Facilities as of 08-17-2023		

SWMF - Active Facility Lists Details(Act)

Accuracy Code:	2.1 - NYSDEC 100 m grid collection	**Authorization No:**	24WA3
Activity Desc:	C&D processing - registration	**Authrzation Issue Dt:**	
Regulatory Status:	Registration	**Operator Type:**	
Active:	Yes	**Operator Name:**	Allocco Recycling Ltd.
Dt of Last Inspection:	10/19/2021	**Phone No:**	7183493094
Expiration Dt:		**Region:**	2
Owner Type:	Private	**Contact Name:**	Michael Allocco Jr
Owner Name:	Michael Allocco	**Contact Address:**	
Owner Address:	540 Kingsland Avenue	**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:	Brooklyn	**Contact State:**	
Owner State:	NY	**Contact Zip:**	
Owner Zip:	11222	**Contact Phone:**	7183493094
Owner Phone:	7183493094	**Contact Email:**	mike@alloccorecycling.com
Owner Email:			
Waste Types:	Asphalt;Concrete;Metals (Ferrous);Metals (Non-Ferrous);Rock;Sand;Soil (Clean);Commingled Paper;Brick; Magazines;Newspaper;Office Paper		

Active Solid Waste Management Facilities Details as of 08-17-2023

Accuracy Code:	2.1 - NYSDEC 100 m grid collection	**Authorization No:**	24WA3
Activity Desc:	C&D processing - registration	**Authrzation Issue Dt:**	
Active:	Yes	**Owner Type:**	Private
Expiration Dt:		**Owner Name:**	Michael Allocco
Geo Reference:	540 Kingsland Avenue Brooklyn, NY 11222 (40.735029397, -73.944583868)	**Phone No:**	7183493094
Region:	2		
Waste Types:	Asphalt;Concrete;Metals (Ferrous);Metals (Non-Ferrous);Rock;Sand;Soil (Clean);Commingled Paper;Brick; Magazines;Newspaper;Office Paper		

184	*3 of3*	*ENE*	*0.37 / 1,978.14*	*2.19 / -10*	***Allocco Recycling Ltd (Kingsland Ave)*** ***540 Kingsland Avenue*** ***Brooklyn NY 11222***	***RECYCLING***

East Coordinate:	589120	**County:**	Kings
North Coordinate:	4509887	**Location Address2:**	

Details

Activity No:	[24M00]	**Authorization No:**	
Active:	Yes	**Auth Issue Date:**	
Activity Desc:	RHRF - exempt (non-VDF)	**Expiration DT:**	
Region:	2	**Owner Type:**	Private
Phone No:	7183493094	**Owner Name:**	Michael Allocco
Accuracy Code:			
Waste Types:			
Georeference:	540 Kingsland Avenue		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					Brooklyn, NY 11222 (40.735029397, -73.944583868)	
185	1 of1	WNW	0.38 / 1,997.25	12.68 / 1	40-56 Commercial Street 40-56 Commercial Street Brooklyn NY 11222	SHWS

Site Code:	571781
HW Code:	224278
Program:	HW
Site Class:	N
Site Name:	40-56 Commercial Street
Site Address:	40-56 Commercial Street
City:	Brooklyn
Zip:	11222
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.736489789
Longitude:	-73.957722976
SWIS:	2401
Acres:	0.282
Record Added:	2018-06-21 11:52:00
Record Update:	2024-03-28 09:36:00
Updated by:	AMSERVIS
Site Code (Web):	224278
Program Type (Web):	HW
Site Name (Web):	40-56 Commercial Street
Site Class (Web):	N
Address1 (Web):	40-56 Commercial Street
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.957722976
Latitude (Web):	40.736489789
Site Code (GIS):	224278
Site Name (GIS):	40-56 Commercial Street
Program (GIS):	HW
Site Class (GIS):	N
Address1 (GIS):	40-56 Commercial Street
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced; c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.
Site Class Desc (Web):	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not

completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Description:

Location: The approximate 0.282-acre site is located at 40-56 Commercial Street in the Greenpoint section of Brooklyn, Kings County, New York, and is identified as block 2482, Lots 1,7 and 8 on the New York City tax map. The site is bounded by Commercial Street to the north, Clay Street followed by the NuHart Plastics State Superfund site to the south, a 1 to 2 -story industrial building and a undeveloped storage yard to the east, and the intersection of Commercial Street and Clay Street followed by the Greenpoint Playground to the west. Site Features: The Site is developed with two one-story warehouse and garage on the eastern portion of the property, which is currently used for commercial hardware supply storge, and a vacant lot on the western portion. Current Zoning and Land Use: The site is currently zoned as M1-2 for manufacturing/industrial use with an R6 residential overlay. The surrounding area consists of commercial and residential buildings, open space/outdoor recreation, and asphalt parking lots Past Use of the Site: The western portion of the Site is currently occupied by a vacant lot primary use for truck parking. Historical use for the western portion of the site include gasoline filing station, auto repair operation and vehicle/equipment storage. The eastern portion of the site is used for commercial hardware supply storage. Site Geology and Hydrogeology: Soil borings completed at the site identified urban fill materials consisting of silty sand and construction debris from ground surface to 10 feet below grade. Groundwater is present at a depth of approximately 8 to 10 feet below grade.

Assessment:

The site enter into the BCP program please refer to Site no. C224278 for more information. Nature and Extent of Contamination: soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Soil vapor was analyzed for VOC. Based on investigations conducted to date at the subject property, the primary contaminants of concern for the site are tetrachloroethylene (PCE) and its breakdown product trichloroethylene (TCE). Chlorinated solvents, include PCE and TCE were detected in soil, groundwater and soil vapor above applicable standards and guidance values. Soil – VOCs exceeding unrestricted use soil cleanup objective (UUSCOS). VOCs identified at the site included TCE with maximum concentration at 5.1 parts per million (ppm) (UUSCOs is 0.47 ppm), which also exceeds the applicable protection of groundwater soil cleanup objectives (pGSCO) of 2 ppm; n-propylbenzene with 11 ppm (UUSCO is 3.9 ppm); ethylbenzene with 2ppm (UUSCO is 1ppm); 1,2,4-trimethylbenzene with 34 ppm(UUSCO is 3.6 ppm) 1,3,5-trimethylbenzene with 11 ppm (UUSCO is 8.4 ppm); and xylenes with 13 ppm(UUSCO is 0.26 ppm). The following semi-volatile organic compounds were detected in soil exceeding the restricted residential use SCOs: benzo(a)anthracene (max 8.3 ppm); benzo(a) pyrene (max. 7.48 ppm); benzo(b)fluoranthene (max. 7.15 ppm), benzo(k) fluoranthene (max. 7.02 ppm); chrysene (Max. 8.58 ppm) dibenzo(a,h)fluoranthene (max 0.764 ppm) and indeno(1,2,3-cd)pyrene (max. 1.92 ppm). The following metals were detected in soil exceeding the unrestricted use SCOs: mercury (max 1.28 ppm), barium (max. 1390 ppm); cadmium (max. 4.06 ppm); copper (max. 220 ppm); lead (max. 2700 ppm); nickel (max. 40.9 ppm) and zinc (max. 991 ppm). The following pesticides were detected in soil above unrestricted use SCOs: 4,4-DDT (max 0.00531 ppm), and 4,4'-DDD (0.0568 ppm). No PCBs was detected above the unrestricted use SCOs. Groundwater – VOCs detected in groundwater includes the following: PCE with maximum concentration of 24 parts per billion (ppb), TCE with maximum concentration of 130,000 ppb, cis-1,2-dichloroethene with maximum concentration of 1700 ppb, vinyl chloride with maximum concentration of 81 ppb, 1,1-dichloroethene with maximum concentration of 12 ppb, trans-1,2-dichloroethene with maximum concentration of 22 ppb, toluene with maximum concentration of 8 ppb, isopropylbenzene with maximum concentration of 63 ppb, and p-isopropyltoluene with maximum concertation of 11 ppb. No SVOCs, pesticides, PCBs or metals were detected above the Class GA Standards. Soil Vapor – TCE was detected at up to 1410 micrograms per cubic meter (ug/m3), and petroleum-related VOCs ranged from 21 ug/m3 to 1220 ug/m3.

Owner Information

Owner Op:	01
Sub Type:	E
Owner Name:	Nicholas Manetta
Owner Company:	Rimani Realty LLC
Owner Street:	101 Malba Drive
Owner Street 2:	
Owner City:	Malba
Owner State:	NY
Owner Zip:	11357
Country:	United States of America

Environmental Remediation

Operable Unit:	01

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Contaminants:		dichloroethene (cis-1,2-), tetrachloroethene (PCE), trichloroethene (TCE)				
186	1 of1	NW	0.39 / 2,085.08	11.20 / -1	Greenpoint Manuf. and Design Ctr. 1155 Manhattan Avenue Brooklyn NY 11222	SHWS

Site Code:	421914
HW Code:	224138
Program:	HW
Site Class:	N
Site Name:	Greenpoint Manuf. and Design Ctr.
Site Address:	1155 Manhattan Avenue
City:	Brooklyn
Zip:	11222
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.738503000
Longitude:	-73.955954000
SWIS:	2401
Acres:	3.865
Record Added:	2009-11-17 16:10:00
Record Update:	2011-08-26 14:02:00
Updated by:	MJKOMORO
Site Code (Web):	224138
Program Type (Web):	HW
Site Name (Web):	Greenpoint Manuf. and Design Ctr.
Site Class (Web):	N
Address1 (Web):	1155 Manhattan Avenue
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.955954000
Latitude (Web):	40.738503000
Site Code (GIS):	224138
Site Name (GIS):	Greenpoint Manuf. and Design Ctr.
Program (GIS):	HW
Site Class (GIS):	N
Address1 (GIS):	1155 Manhattan Avenue
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced; c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.
Site Class Desc (Web):	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a

volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH:
Description:

LOCATION: The Greenpoint Manufacturing and Design Center (GMDC) property is located at 1155-1205 Manhattan Avenue which is an urban area of Brooklyn (Kings County) in New York City. SITE FEATURES: The property is nearly entirely covered by structures, with only one small area covered with other impervious material located along the northern edge of the property along Newtown Creek. There are eight contiguous four to six-story building on the property. The property borders Newtown Creek on the north side. CURRENT ZONING/USE: This property is currently in use for many separate commercial uses, primarily by small businesses and artisans. The surrounding uses are varied - the property adjacent to the west is indicated as having residential and commercial use but appears commercial; the properties to the east across Manhattan Avenue are indicated as being factory/industrial uses, but appear to be commercial with residential above. HISTORICAL USE(s): The property has a long industrial/commercial history, but went through an extensive remedial effort overseen by local agencies in the 1990's. The property owners have done significant renovations on the buildings and have conducted at least two recent investigations which identified limited groundwater contamination, but did not identify any significant soil contamination.

Assessment:

NATURE AND EXTENT OF CONTAMINATION: Only two (of ten) temporary groundwater sampling wells located in the basement of the structure at 1155 Manhattan Avenue showed evidence of contamination. Each contained one chlorinated VOC slightly above standards. Tetrachloroethylene was identified at 21ppb; chloroform was identified at 12 ppb. Groundwater standards are 5 ppb and 7 ppb respectively. Soil samples from these borings were below unrestricted standards for the same compounds. Samples taken from permanent wells did not identify any VOC contamination. Based on professional judgment, the slight exceedances of groundwater standards, adjacent to the Newtown Creek Superfund Site, do not constitute a significant threat to the environment. No further investigations are warranted at this time. Site designation was changed from "P" to "N."

Owner Information

Owner Op:	01
Sub Type:	01
Owner Name:	Manhattan Avenue Holding Corp.
Owner Company:	Manhattan Avenue Holding Corp.
Owner Street:	1155 Manhattan Avenue
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11222
Country:	United States of America

Owner Op:	04
Sub Type:	NNN
Owner Name:	Paul Parkhill
Owner Company:	Greenpoint Manufacturing & Design Center
Owner Street:	1155 Manhattan Avenue
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11222
Country:	United States of America

Projects Information

Project Code:	01
Project Desc:	Site Caracterization
Project Refer Name:	
End Date:	2011-03-23 00:00:00
End Status:	ACT
Operable Unit ID:	1177785
Operable Unit:	01

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Operable Unit Desc: Remedial Program
Code Name: Site Characterization

Environmental Remediation

Operable Unit: 01
Contaminants: cis-1,2-dichloroethene, tetrachloroethene (PCE), toluene

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
187	1 of1	WNW	0.41 / 2,142.54	11.76 / 0	50 Commercial Street Development 50 and 56 Commercial Street and 15-17 Clay Street Brooklyn NY 11222	BROWNFIELDS

Site Code: 650002
HW Code: C224278
Program: BCP
Site Class: A
Site Name: 50 Commercial Street Development
Site Address: 50 and 56 Commercial Street and 15-17 Clay Street
City: Brooklyn
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.736586000
Longitude: -73.957523000
SWIS: 2401
Acres: 0.283
Record Added: 2023-04-11 10:20:00
Record Update: 2024-03-26 08:05:00
Updated by: AAOBLIGA
Site Code (Web): C224278
Program Type (Web): BCP
Site Name (Web): 50 Commercial Street Development
Site Class (Web): A
Address1 (Web): 50 and 56 Commercial Street and 15-17 Clay Street
Address2 (Web):
Locality (Web): Brooklyn
Zip Code (Web): 11222
County (Web): Kings
Longitude (Web): -73.957523000
Latitude (Web): 40.736586000
Site Code (GIS): C224278
Site Name (GIS): 50 Commercial Street Development
Program (GIS): BCP
Site Class (GIS): A
Address1 (GIS): 50 and 56 Commercial Street and 15-17 Clay Street
Address2 (GIS):
Locality (GIS): Brooklyn
Zip Code (GIS): 11222
County (GIS): Kings
Site Class Desc: Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Site Class Desc (Web): Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Assess DOH: Access is restricted by a fence. People who enter the site may come into contact with site-related soil and groundwater contamination if they dig below the surface. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of site contaminants in indoor air via soil vapor intrusion is not a current concern. However, the potential exists for inhalation of site contaminants for any future on-

site development. In addition, environmental sampling indicates soil vapor intrusion from site contamination is not likely a concern for off-site buildings.

Description:

Location: The approximate 0.283-acre site is located at 50 Commercial Street in the Greenpoint section of Brooklyn, Kings County, New York, and is identified as Block 2482 Lots 1, 7 and 8 on the New York City tax map. The site is bounded by Commercial Street to the north, Clay Street to the south followed by Former NuHart East Site (NYS BCP Site #C224287) and Former NuHart Plastic Manufacturing (NYSDEC Superfund Site #224136), an industrial warehouse (Clay Properties LLC Site, NYS BCP Site ID #C224390) and residential buildings to the east, and the intersection of Commercial and Clay Street to the west. Site Features: The Site is developed with a one-story industrial warehouse on Lot 7, a small shed and vacant land on Lot 8, and an asphalt-paved storage yard at Lot 1. The site is currently vacant. Current Zoning and Land Use: The site is currently zoned as M1-2/R6 for industrial and manufacturing use. The site is currently vacant. The surrounding parcels are currently used for a combination of residential, commercial, and light industrial. There two playgrounds located within a 0.125-mile radius of the subject property. the two playgrounds are identified as Greenpoint Playground and Newtown Barge Playground. Past Use of the Site: The western portion of the site (Lot 1) is currently occupied by a vacant lot use for truck parking, historically this portion of the site was operating as a gasoline filling station, auto repair and junk storage. Historical use for the eastern portion (Lot 7 and 8) of the site includes iron and steel work operations, lumber and building material warehouse. Site Geology and Hydrogeology: Soil borings completed at the site identified urban fill materials consisting of brown silty-sand matrix from ground surface to about 2 feet below grade surface (bgs), underlain by native soil consist of brown silty sand. Groundwater is present at a depth of approximately 8 feet bgs and generally flows in a westerly direction.

Assessment:

Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), pesticides and per- and polyfluoroalkyl substances (PFAS). Soil vapor was analyzed for VOCs. Based on investigations conducted to date at the subject property, the primary contaminants of concern for the site are trichloroethylene (TCE) and petroleum VOCs in soil, groundwater and soil vapor; and metals and SVOCs in soil. Soil - VOCs detected at concentrations exceeding the protection of groundwater soil cleanup objectives (PGSCOs) include TCE at a maximum concentration of 5.1 parts per million (ppm) compared to the PGSCO of 0.47 ppm, 1,2,4-trimethylbenzene at a maximum concentration of 4.2 ppm (PGSCO of 3.6 ppm), and xylenes at a maximum concentration of 13 ppm (PGSCO of 1.6 ppm). Several SVOCS were detected in soil exceeding the restricted residential use soil cleanup objectives (RRSCOs), including benzo (a)anthracene at a maximum concentration of 8.3 ppm; benzo(a)pyrene with a maximum concentration of 7.48 ppm; benzo(b)fluoranthene with a maximum concentration of 7.15 ppm. The RRSCO for these compounds is 1 ppm. The following metals were detected in soil exceeding the RRSCOs: mercury at a maximum concentration of 1.28 ppm (RRSCO is 0.81), barium at a maximum concentration of 1,390 ppm (RRSCO is 400 ppm); and lead at a maximum concentration of 2,750 ppm (RRSCO is 400 ppm). No PCBs or pesticides was detected above the RRSCOs. No per- or polyfluoroalkyl substances (PFAS) were detected in soil above restricted residential guidance values. Data does not indicate any off-site impacts in soil related to the site. Groundwater - Groundwater sample results were compared to the NYS Ambient Water Quality Standards and Guidance Values (AWQSGVs). VOCs detected in groundwater include TCE at a maximum concentration of 130,000 parts per billion (ppb), cis-1,2-dichloroethene at a maximum concentration of 1700 ppb, vinyl chloride at a maximum concentration of 81 ppb, 1,1-dichloroethene at a maximum concentration of 12 ppb, trans-1,2-dichloroethene at a maximum concentration of 6,500 ppb, toluene at a maximum concentration of 8 ppb, isopropylbenzene at a maximum concentration of 63 ppb, and p-isopropyltoluene at a maximum concertation of 11 ppb. The AWQSGV for each of these compounds is 5 ppb with the exception of vinyl chloride (AWQSGV of 2 ppb). Perfluorooctanoic acid (PFOA) was detected at a maximum concentration of 927 parts per trillion (ppt) compared to the AWQSGV of 6.7 ppt, and perfluorooctanesulfonic acid (PFOS) was detected at a maximum concentration of 92.4 ppt (AWQSGV is 2.7 ppt). No SVOCs, pesticides, PCBs or metals were detected above the AWQS. Data does not indicate any off-site impacts in groundwater related to the site. Soil Vapor - TCE was detected at up to 1410 micrograms per cubic meter (ug/m3), 1,2,4-trimethylbenzene was detected at up to ug/m3, cis-1,2-dichloroethene was detected at up to 35 ug/m3, toluene was detected at up to 120 ug/m3 and total xylenes were detected at up to 740 ug/3. Data does not indicate any off-site impacts in soil vapor related to the site.

Materials Information

Waste Name: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: barium
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: trans-1,2-dichloroethene

Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: toluene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: lead
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 01
Sub Type: E
Owner Name: NICHOLAS MANETTA
Owner Company: RIMANI REALTY LLC
Owner Street: 270 MCGUINNESS BOULEVARD
Owner Street 2:
Owner City: BROOKLYN
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Brooklyn Public Library
Owner Street: Greenpoint Library Env. Education Center
Owner Street 2: 107 Norman Avenue
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Brooklyn Community Board 1
Owner Street: 435 Graham Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222

Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: NICHOLAS MANETTA
Owner Company: RIMANI REALTY LLC
Owner Street: 270 MCGUINNESS BOULEVARD
Owner Street 2:
Owner City: BROOKLYN
Owner State: NY
Owner Zip: 11222
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: JHOCONNE

Record Added: 2023-09-28 10:22:00
Record Updated: 2024-01-31 16:26:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Projects Information

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2024-02-08 00:00:00
End Status: ACT
Operable Unit ID: 1396962
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2024-02-08 00:00:00
End Status: ACT
Operable Unit ID: 1396962
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Design

Environmental Remediation

Operable Unit: 01
Contaminants: 1,2,4-trimethylbenzene, barium, benzo(a)anthracene, benzo(a)pyrene, benzo(k)fluoranthene, cis-1,2-dichloroethene, lead, mercury, toluene, trans-1,2-dichloroethene, trichloroethene (TCE), vinyl chloride, xylene (mixed)

Operable Unit: 00
Contaminants: 1,2,4-trimethylbenzene, barium, benzo(a)anthracene, benzo(a)pyrene, benzo(k)fluoranthene, cis-1,2-dichloroethene, lead, mercury, toluene, trans-1,2-dichloroethene, trichloroethene (TCE), vinyl chloride, xylene (mixed)

188	1 of1	WNW	0.41 / 2,170.84	9.66 / -2	CROSSTOWN ANNEX 65 COMMERCIAL STREET BROOKLYN NY	LST

Spill No: 9011113
Site ID: 208696
DER Facility ID: 173146
CID:

REM Phase: 0
UST Trust: True
Spill Date: 01/18/1991 03:00:00 PM
Rcvd Date: 01/18/1991 04:25:00 PM

Program Type:	ER	**CAC Date:**	
SWIS Code:	2401	**Insp Date:**	
Contribute Factor:	Tank Failure	**Close Date:**	01/30/2004 12:00:00 AM
Water Body:		**Create Date:**	02/01/1991 12:00:00 AM
Class:	C3	**Update Date:**	01/30/2004 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	MCTIBBE
County:	Kings	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"(3) 5K DIESEL TANKS IN (1) UNDERGROUND CONCRETE VAULT, 25 INCHES OF WATER & OIL DISCOVERED (2 INCHES OF OIL ON WATER), 2ND VAULT CONTAINED LUBE OIL,1120 GAL TANK,(2) 550 GAL WASTE OIL,SAME CONDITION."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 01/18/91: WILL PUMP OUT OIL. 11/16/94: REASSIGNED FROM SIGONA TO ZHITOMIRSKY ON 11/16/94. transfered from Hale to Tibbe on 12/27/00. tanks repaired/replaced/upgraded. investigation ongoing. See file."

Material Information

OP Unit ID:	951320	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	431206	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	L	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0013		
Material Name:	lube oil		

OP Unit ID:	951320	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	431204	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	-1.00	**Med Surf:**	False
Units:	L	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	
Spiller Company:	NYCTA
Spiller Address:	90-25 161ST STREET
Spiller City:	JAMAICA
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.737008150
Longitude:	-73.957264850

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
189	1 of3	WNW	0.41 / 2,175.38	10.69 / -1	45 Commercial Street 45 Commercial Street Brooklyn NY 11222	BROWNFIELDS

Site Code: 598914
HW Code: C224304
Program: BCP
Site Class: C
Site Name: 45 Commercial Street
Site Address: 45 Commercial Street
City: Brooklyn
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.736972222
Longitude: -73.957944444
SWIS: 2401
Acres: 1.020
Record Added: 2019-12-03 15:09:00
Record Update: 2024-08-29 11:01:00
Updated by: DKMACNEA
Site Code (Web): C224304
Program Type (Web): BCP
Site Name (Web): 45 Commercial Street
Site Class (Web): C
Address1 (Web): 45 Commercial Street
Address2 (Web):
Locality (Web): Brooklyn
Zip Code (Web): 11222
County (Web): Kings
Longitude (Web): -73.957944444
Latitude (Web): 40.736972222
Site Code (GIS): C224304
Site Name (GIS): 45 Commercial Street
Program (GIS): BCP
Site Class (GIS): C
Address1 (GIS): 45 Commercial Street
Address2 (GIS):
Locality (GIS): Brooklyn
Zip Code (GIS): 11222
County (GIS): Kings
Site Class Desc: Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Site Class Desc (Web): Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH: Remedial actions are complete and measures are in place to prevent people from coming in contact with residual site contamination.
Description:

Location: The site is located at 45 Commercial Street in the Greenpoint neighborhood of Brooklyn (Tax Block 2472, Lot 70). There is a parcel under construction to the north, followed by Newtown Creek, a parking lot to the east, Commercial Street to the south, and multi-story commercial/ residential building to the west. Site Features: The site is approximately 44,600 square feet, flat, and is paved with concrete and asphalt. Current Zoning and Land Use: The site is located in an R6/R8/C2-4 mixed-use residential and commercial district. The site is currently vacant. Past Use of the Site: Coal and lumber storage were the primary uses of the property from the late 1800s until about 1980. Since then, the site has been used for parking and equipment & material storage. Site Geology and Hydrogeology: The site consists of a surficial layer of historic fill material overlying native fine- to coarse-grained sandy soil and silty soil. The historic fill is composed of varying amounts of sand and silt from surface grade to depths of 10 to 15 feet

below grade surface (bgs) (terminus of deepest boring). Bedrock was not encountered during any environmental investigations performed at the site. Groundwater was encountered at 8-10 feet bgs. Groundwater flow was found towards the west during the investigation, toward the confluence of the East River and Newtown Creek, rather than the expected direction towards the north.

Assessment:

Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were lead, arsenic and SVOCs in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Remediation: Nature and Extent of Contamination: Various investigations have included the site since 2001. The most recent investigation results from 2019 and 2020 are described below: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), pesticides and the emerging contaminants per- and polyfluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor was analyzed for VOCs. Soil- The primary contaminants in soil at this site are metals and SVOCs. Arsenic, copper, and lead, with lesser amounts of barium and mercury exceed the applicable restricted residential soil cleanup objectives (RRSCOs). Arsenic was found at a maximum concentration of up to 60 parts per million (ppm) compared to the RRSCO of 16 ppm, though later samples showed a range from 8- 16 ppm sitewide. Copper was found at 599 ppm (RRSCO is 270 ppm). Lead in soil ranges up to 10900 ppm (RRSCO is 400 ppm). Individual SVOCs, such as benzo(a)anthracene, benzo(a)pyrene, and chrysene, were found throughout the site above the RRSCOs. In one location, the SVOCs totaled 789 ppm which exceeds the 500 ppm total for cleanup. For emerging contaminants, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were detected. PFOS was measured in two soil samples below the guidance value for unrestricted use of 0.88 ppb. PFOA was detected in one soil sample at 1.7 ppb, exceeding the unrestricted use and the protection of groundwater guidance values of 0.66 ppb and 1.1 ppb respectively, but below the restricted residential standard of 33 ppb. Data does not indicate any off-site soil impacts related to this site. Groundwater- Groundwater exceeds ambient water quality standards (AWQS) for the naturally-occurring metals iron, sodium, magnesium and manganese, and the VOC 1,2-dichloroethane (1,2-DCA) which was detected at 1 part per billion (ppb), slightly exceeding the standard of 0.6 ppb. 1,2-DCA may be related to a historic petroleum release. Perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 170 and 25 parts per trillion (ppt), respectively, exceeding the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater. 1,4-dioxane was reported at concentrations of up to 0.1 parts per billion (ppb), below the Maximum Contaminant Level (drinking water standard) of 1 ppb in groundwater. Data does not indicate any off-site groundwater impacts related to this site. Soil Vapor - Five soil vapor samples were obtained in 2020. The primary contaminants in soil vapor are volatile organic compounds such as acetone 860 ug/m3 (micrograms per cubic meter), n-pentane (180 u/gm3) and n-hexane (470 ug/m3). One of the five samples contained PCE at 1.8 ug/m3 which is just above the detection level. Other chlorinated compounds were detected in the soil vapor, such as dichlorodifluoromethane (R-12) (3 ug/m3) and trichlorofluoromethane (R-11) (2.2 ug/m3). Data does not indicate any off-site impacts in soil vapor related to this site.

Materials Information

Waste Name: chrysene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: arsenic
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: copper
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: lead
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: barium
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op:	06
Sub Type:	P03
Owner Name:	Guy Morton
Owner Company:	H Owner LLC
Owner Street:	535 Madison Avenue
Owner Street 2:	
Owner City:	New York
Owner State:	NY
Owner Zip:	10022
Country:	United States of America

Owner Op:	06
Sub Type:	P03
Owner Name:	Guy Morton
Owner Company:	Greenpoint Landing Developers LLC
Owner Street:	535 Madison Avenue
Owner Street 2:	
Owner City:	New York
Owner State:	NY
Owner Zip:	10022
Country:	United States of America

Owner Op:	06
Sub Type:	P03
Owner Name:	Guy Morton
Owner Company:	Greenpoint Landing Associates, L.L.C.
Owner Street:	535 Madison Avenue
Owner Street 2:	
Owner City:	New York
Owner State:	NY
Owner Zip:	10022
Country:	United States of America

Owner Op:	06
Sub Type:	P03
Owner Name:	anne carson blair
Owner Company:	H1H2 Owner LLC
Owner Street:	535 Madison Avenue
Owner Street 2:	
Owner City:	new york
Owner State:	NY
Owner Zip:	10022
Country:	United States of America

Owner Op:	19
Sub Type:	NNN
Owner Name:	
Owner Company:	Leonard Library
Owner Street:	81 Devoe Street at Leonard Street
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11211
Country:	United States of America

Owner Op:	01
Sub Type:	P03
Owner Name:	Anne Carson Blair
Owner Company:	H1H2 Owner LLC
Owner Street:	535 Madison Avenue
Owner Street 2:	
Owner City:	New York
Owner State:	NY
Owner Zip:	10022
Country:	United States of America

Owner Op:	06
Sub Type:	P03
Owner Name:	Guy Morton

Owner Company:	Greenpoint Storage Terminal LLC
Owner Street:	535 Madison Avenue
Owner Street 2:	
Owner City:	New York
Owner State:	NY
Owner Zip:	10022
Country:	United States of America
Owner Op:	06
Sub Type:	P03
Owner Name:	anne carson blair
Owner Company:	H1H2 Retail LLC
Owner Street:	535 Madison Avenue
Owner Street 2:	
Owner City:	new york
Owner State:	NY
Owner Zip:	10022
Country:	United States of America
Owner Op:	06
Sub Type:	P03
Owner Name:	Anne Carson Blair
Owner Company:	H1H2 GPL Owner LLC
Owner Street:	535 Madison Avenue
Owner Street 2:	
Owner City:	new york
Owner State:	NY
Owner Zip:	10022
Country:	United States of America
Owner Op:	06
Sub Type:	P03
Owner Name:	Guy Morton
Owner Company:	GPL Development LLC
Owner Street:	535 Madison Avenue
Owner Street 2:	
Owner City:	New York
Owner State:	NY
Owner Zip:	10022
Country:	United States of America
Owner Op:	19
Sub Type:	NNN
Owner Name:	Dealice Fuller
Owner Company:	Brooklyn Community Board 1
Owner Street:	435 Graham Avenue
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11211
Country:	United States of America
Owner Op:	01
Sub Type:	P03
Owner Name:	
Owner Company:	HP H1H2 Housing Development Fund Company, Inc.
Owner Street:	c/o NYC Partnership HDFC, Inc.
Owner Street 2:	253 West 35th Street, 3rd Floor
Owner City:	New York
Owner State:	NY
Owner Zip:	10001
Country:	United States of America

HW Extra Information

Dump:	False	***Record Added:***	2020-03-23 15:30:00
Structure:	False	***Record Updated:***	2022-11-15 09:28:00
Lagoon:	False	***Disposal Start:***	

Landfill:	False	**Disposal Terminate:**	
Pond:	False	**Latitude:**	
Dell:		**Longitude:**	
Updated By:	RECURLEY		

Projects Information

Project Code:	25
Project Desc:	
Project Refer Name:	
End Date:	2022-12-15 00:00:00
End Status:	ACT
Operable Unit ID:	1377633
Operable Unit:	00
Operable Unit Desc:	Site Management
Code Name:	Certificate of Completion
Project Code:	05
Project Desc:	Remedial Action
Project Refer Name:	Excavation, SMDS
End Date:	2022-12-15 00:00:00
End Status:	ACT
Operable Unit ID:	1346407
Operable Unit:	01
Operable Unit Desc:	Remedial Program
Code Name:	Remedial Action
Project Code:	02
Project Desc:	Remedial Investigation
Project Refer Name:	
End Date:	2021-04-13 00:00:00
End Status:	ACT
Operable Unit ID:	1346407
Operable Unit:	01
Operable Unit Desc:	Remedial Program
Code Name:	Remedial Investigation

Environmental Remediation

Operable Unit:	01
Contaminants:	arsenic, barium, benzo(a)anthracene, benzo(a)pyrene, chrysene, copper, lead, mercury
Operable Unit:	00
Contaminants:	arsenic, barium, benzo(a)anthracene, benzo(a)pyrene, chrysene, copper, lead, mercury

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
189	2 of3	WNW	0.41 / 2,175.38	10.69 / -1	45 Commercial Street 45 Commercial Street Brooklyn NY 11222	ENG

Site Code:	598914
HW Code:	C224304
Control Type:	ENG
Program:	BCP
Site Class:	C
Site Name:	45 Commercial Street
Site Address:	45 Commercial Street
City:	Brooklyn
Zip:	11222
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.736972222
Longitude:	-73.957944444
SWIS:	2401
Acres:	1.020
Record Added:	2019-12-03 15:09:00

Record Updated:	2024-08-29 11:01:00
Updated By:	DKMACNEA
Site Code (Web):	C224304
Program Type (Web):	BCP
Site Class (Web):	C
Site Name (Web):	45 Commercial Street
Address1 (Web):	45 Commercial Street
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.957944444
Latitude (Web):	40.736972222
Site Code (GIS):	C224304
Program (GIS):	BCP
Site Class (GIS):	C
Site Name (GIS):	45 Commercial Street
Address 1 (GIS):	45 Commercial Street
Address 2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Latitude (GIS):	
Longitude (GIS):	
Site Class Desc:	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Site Class Desc (Web):	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH:	Remedial actions are complete and measures are in place to prevent people from coming in contact with residual site contamination.

Description:

Location: The site is located at 45 Commercial Street in the Greenpoint neighborhood of Brooklyn (Tax Block 2472, Lot 70). There is a parcel under construction to the north, followed by Newtown Creek, a parking lot to the east, Commercial Street to the south, and multi-story commercial/ residential building to the west. Site Features: The site is approximately 44,600 square feet, flat, and is paved with concrete and asphalt. Current Zoning and Land Use: The site is located in an R6/R8/C2-4 mixed-use residential and commercial district. The site is currently vacant. Past Use of the Site: Coal and lumber storage were the primary uses of the property from the late 1800s until about 1980. Since then, the site has been used for parking and equipment & material storage. Site Geology and Hydrogeology: The site consists of a surficial layer of historic fill material overlying native fine- to coarse-grained sandy soil and silty soil. The historic fill is composed of varying amounts of sand and silt from surface grade to depths of 10 to 15 feet below grade surface (bgs) (terminus of deepest boring). Bedrock was not encountered during any environmental investigations performed at the site. Groundwater was encountered at 8-10 feet bgs. Groundwater flow was found towards the west during the investigation, toward the confluence of the East River and Newtown Creek, rather than the expected direction towards the north.

Assessment:

Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were lead, arsenic and SVOCs in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Remediation: Nature and Extent of Contamination: Various investigations have included the site since 2001. The most recent investigation results from 2019 and 2020 are described below: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), pesticides and the emerging contaminants per- and polyfluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor was analyzed for VOCs. Soil- The primary contaminants in soil at this site are metals and SVOCs. Arsenic, copper, and lead, with lesser amounts of barium and mercury exceed the applicable restricted residential soil cleanup objectives (RRSCOs). Arsenic was found at a maximum concentration of up to 60 parts per million (ppm) compared to the RRSCO of 16 ppm, though later samples showed a range from 8- 16 ppm sitewide. Copper was found at 599 ppm (RRSCO is 270 ppm). Lead in soil ranges up to 10900 ppm (RRSCO is 400 ppm). Individual SVOCs, such as benzo(a)anthracene, benzo(a)pyrene, and chrysene, were found throughout the site above the RRSCOs. In one location, the SVOCs totaled 789 ppm which exceeds the 500 ppm total for cleanup. For emerging contaminants, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were detected. PFOS was measured in two soil samples below the guidance value for unrestricted use of 0.88 ppb. PFOA was detected in one soil sample at 1.7 ppb, exceeding the unrestricted use and the protection of groundwater guidance values of

0.66 ppb and 1.1 ppb respectively, but below the restricted residential standard of 33 ppb. Data does not indicate any off-site soil impacts related to this site. Groundwater- Groundwater exceeds ambient water quality standards (AWQS) for the naturally-occurring metals iron, sodium, magnesium and manganese, and the VOC 1,2-dichloroethane (1,2-DCA) which was detected at 1 part per billion (ppb), slightly exceeding the standard of 0.6 ppb. 1,2-DCA may be related to a historic petroleum release. Perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 170 and 25 parts per trillion (ppt), respectively, exceeding the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater. 1,4-dioxane was reported at concentrations of up to 0.1 parts per billion (ppb), below the Maximum Contaminant Level (drinking water standard) of 1 ppb in groundwater. Data does not indicate any off-site groundwater impacts related to this site. Soil Vapor - Five soil vapor samples were obtained in 2020. The primary contaminants in soil vapor are volatile organic compounds such as acetone 860 ug/m3 (micrograms per cubic meter), n-pentane (180 u/gm3) and n-hexane (470 ug/m3). One of the five samples contained PCE at 1.8 ug/m3 which is just above the detection level. Other chlorinated compounds were detected in the soil vapor, such as dichlorodifluoromethane (R-12) (3 ug/m3) and trichlorofluoromethane (R-11) (2.2 ug/m3). Data does not indicate any off-site impacts in soil vapor related to this site.

Controls Information

Control Code: 15
Control Name: Cover System
Control Type: ENG
Updated By: EWJACKSO
Record Added Date: 2022-10-24 16:35:02.243000000
Record Updated Dt: 2024-10-24 08:50:10.933000000
In Place Date: 2022-10-18 00:00:00

Control Code: 13
Control Name: Vapor Mitigation
Control Type: ENG
Updated By: EWJACKSO
Record Added Date: 2022-10-24 16:35:02.243000000
Record Updated Dt: 2024-10-24 08:50:10.933000000
In Place Date: 2022-10-18 00:00:00

Materials Information

Waste Name: copper
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: chrysene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: lead
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: barium
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: arsenic
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 06
Sub Type: P03
Owner Name: Guy Morton
Owner Company: Greenpoint Landing Associates, L.L.C.
Owner Street: 535 Madison Avenue

Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Guy Morton
Owner Company: Greenpoint Landing Developers LLC
Owner Street: 535 Madison Avenue
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Guy Morton
Owner Company: Greenpoint Storage Terminal LLC
Owner Street: 535 Madison Avenue
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: anne carson blair
Owner Company: H1H2 Owner LLC
Owner Street: 535 Madison Avenue
Owner Street 2:
Owner City: new york
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Anne Carson Blair
Owner Company: H1H2 GPL Owner LLC
Owner Street: 535 Madison Avenue
Owner Street 2:
Owner City: new york
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Guy Morton
Owner Company: H Owner LLC
Owner Street: 535 Madison Avenue
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Leonard Library
Owner Street: 81 Devoe Street at Leonard Street
Owner Street 2:
Owner City: Brooklyn
Owner State: NY

Owner Zip: 11211
Country: United States of America

Owner Op: 01
Sub Type: P03
Owner Name: Anne Carson Blair
Owner Company: H1H2 Owner LLC
Owner Street: 535 Madison Avenue
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Guy Morton
Owner Company: GPL Development LLC
Owner Street: 535 Madison Avenue
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 01
Sub Type: P03
Owner Name:
Owner Company: HP H1H2 Housing Development Fund Company, Inc.
Owner Street: c/o NYC Partnership HDFC, Inc.
Owner Street 2: 253 West 35th Street, 3rd Floor
Owner City: New York
Owner State: NY
Owner Zip: 10001
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name: Dealice Fuller
Owner Company: Brooklyn Community Board 1
Owner Street: 435 Graham Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11211
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: anne carson blair
Owner Company: H1H2 Retail LLC
Owner Street: 535 Madison Avenue
Owner Street 2:
Owner City: new york
Owner State: NY
Owner Zip: 10022
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disposal Start:
Disposal Terminate:

Dell:
Updated By: RECURLEY
Record Added: 2020-03-23 15:30:00
Record Updated: 2022-11-15 09:28:00
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Projects Information

Project Code: 05
Project Desc: Remedial Action
Project Refer Name: Excavation, SMDS
End Date: 2022-12-15 00:00:00
End Status: ACT
Operable Unit ID: 1346407
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Action

Project Code: 25
Project Desc:
Project Refer Name:
End Date: 2022-12-15 00:00:00
End Status: ACT
Operable Unit ID: 1377633
Operable Unit: 00
Operable Unit Desc: Site Management
Code Name: Certificate of Completion

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2021-04-13 00:00:00
End Status: ACT
Operable Unit ID: 1346407
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Environmental Remediation

Operable Unit: 00
Contaminants: arsenic, barium, benzo(a)anthracene, benzo(a)pyrene, chrysene, copper, lead, mercury

Operable Unit: 01
Contaminants: arsenic, barium, benzo(a)anthracene, benzo(a)pyrene, chrysene, copper, lead, mercury

189	3 of3	WNW	0.41 / 2,175.38	10.69 / -1	45 Commercial Street 45 Commercial Street Brooklyn NY 11222	INST

Site Code: 598914
HW Code: C224304
Control Type: INST
Program: BCP
Site Class: C
Site Name: 45 Commercial Street
Site Address: 45 Commercial Street
City: Brooklyn
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.736972222
Longitude: -73.957944444
SWIS: 2401
Acres: 1.020
Record Added: 2019-12-03 15:09:00
Record Updated: 2024-08-29 11:01:00
Updated By: DKMACNEA
Site Code (Web): C224304
Program Type (Web): BCP
Site Class (Web): C

Site Name (Web):	45 Commercial Street
Address1 (Web):	45 Commercial Street
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.957944444
Latitude (Web):	40.736972222
Site Code (GIS):	C224304
Program (GIS):	BCP
Site Class (GIS):	C
Site Name (GIS):	45 Commercial Street
Address 1 (GIS):	45 Commercial Street
Address 2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Latitude (GIS):	
Longitude (GIS):	
Site Class Desc:	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Site Class Desc (Web):	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH:	Remedial actions are complete and measures are in place to prevent people from coming in contact with residual site contamination.

Description:

Location: The site is located at 45 Commercial Street in the Greenpoint neighborhood of Brooklyn (Tax Block 2472, Lot 70). There is a parcel under construction to the north, followed by Newtown Creek, a parking lot to the east, Commercial Street to the south, and multi-story commercial/ residential building to the west. Site Features: The site is approximately 44,600 square feet, flat, and is paved with concrete and asphalt. Current Zoning and Land Use: The site is located in an R6/R8/C2-4 mixed-use residential and commercial district. The site is currently vacant. Past Use of the Site: Coal and lumber storage were the primary uses of the property from the late 1800s until about 1980. Since then, the site has been used for parking and equipment & material storage. Site Geology and Hydrogeology: The site consists of a surficial layer of historic fill material overlying native fine- to coarse-grained sandy soil and silty soil. The historic fill is composed of varying amounts of sand and silt from surface grade to depths of 10 to 15 feet below grade surface (bgs) (terminus of deepest boring). Bedrock was not encountered during any environmental investigations performed at the site. Groundwater was encountered at 8-10 feet bgs. Groundwater flow was found towards the west during the investigation, toward the confluence of the East River and Newtown Creek, rather than the expected direction towards the north.

Assessment:

Post-Remediation: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were lead, arsenic and SVOCs in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. Prior to Remediation: Nature and Extent of Contamination: Various investigations have included the site since 2001. The most recent investigation results from 2019 and 2020 are described below: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), pesticides and the emerging contaminants per- and polyfluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor was analyzed for VOCs. Soil- The primary contaminants in soil at this site are metals and SVOCs. Arsenic, copper, and lead, with lesser amounts of barium and mercury exceed the applicable restricted residential soil cleanup objectives (RRSCOs). Arsenic was found at a maximum concentration of up to 60 parts per million (ppm) compared to the RRSCO of 16 ppm, though later samples showed a range from 8- 16 ppm sitewide. Copper was found at 599 ppm (RRSCO is 270 ppm). Lead in soil ranges up to 10900 ppm (RRSCO is 400 ppm). Individual SVOCs, such as benzo(a)anthracene, benzo(a)pyrene, and chrysene, were found throughout the site above the RRSCOs. In one location, the SVOCs totaled 789 ppm which exceeds the 500 ppm total for cleanup. For emerging contaminants, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were detected. PFOS was measured in two soil samples below the guidance value for unrestricted use of 0.88 ppb. PFOA was detected in one soil sample at 1.7 ppb, exceeding the unrestricted use and the protection of groundwater guidance values of 0.66 ppb and 1.1 ppb respectively, but below the restricted residential standard of 33 ppb. Data does not indicate any off-site soil impacts related to this site. Groundwater- Groundwater exceeds ambient water quality standards (AWQS) for the naturally-occurring metals iron, sodium, magnesium and manganese, and the VOC 1,2-dichloroethane (1,2-DCA) which was detected at 1 part per billion (ppb), slightly exceeding the standard of 0.6 ppb. 1,2-DCA may be related to a historic petroleum release. Perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 170 and 25 parts per trillion (ppt), respectively, exceeding the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater. 1,4-dioxane was reported at concentrations of up to 0.1 parts per billion (ppb), below the Maximum Contaminant Level (drinking water

standard) of 1 ppb in groundwater. Data does not indicate any off-site groundwater impacts related to this site. Soil Vapor - Five soil vapor samples were obtained in 2020. The primary contaminants in soil vapor are volatile organic compounds such as acetone 860 ug/m3 (micrograms per cubic meter), n-pentane (180 u/gm3) and n-hexane (470 ug/m3). One of the five samples contained PCE at 1.8 ug/m3 which is just above the detection level. Other chlorinated compounds were detected in the soil vapor, such as dichlorodifluoromethane (R-12) (3 ug/m3) and trichlorofluoromethane (R-11) (2.2 ug/m3). Data does not indicate any off-site impacts in soil vapor related to this site.

Controls Information

Control Code: 34
Control Name: IC/EC Plan
Control Type: INST
Updated By: EWJACKSO
Record Added Date: 2022-10-24 16:35:02.243000000
Record Updated Dt: 2024-10-24 08:50:10.933000000
In Place Date: 2022-10-18 00:00:00

Control Code: 32
Control Name: Site Management Plan
Control Type: INST
Updated By: EWJACKSO
Record Added Date: 2022-10-24 16:35:02.243000000
Record Updated Dt: 2024-10-24 08:50:10.933000000
In Place Date: 2022-10-18 00:00:00

Control Code: 08
Control Name: Ground Water Use Restriction
Control Type: INST
Updated By: EWJACKSO
Record Added Date: 2022-10-24 16:35:02.243000000
Record Updated Dt: 2024-10-24 08:50:10.933000000
In Place Date: 2022-10-18 00:00:00

Control Code: J
Control Name: Environmental Easement
Control Type: INST
Updated By: EWJACKSO
Record Added Date: 2022-10-24 16:35:02.243000000
Record Updated Dt: 2024-10-24 08:50:10.933000000
In Place Date: 2022-10-18 00:00:00

Materials Information

Waste Name: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: copper
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: barium
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: lead
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: chrysene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: arsenic
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 19

Sub Type: NNN
Owner Name:
Owner Company: Leonard Library
Owner Street: 81 Devoe Street at Leonard Street
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11211
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Anne Carson Blair
Owner Company: H1H2 GPL Owner LLC
Owner Street: 535 Madison Avenue
Owner Street 2:
Owner City: new york
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: anne carson blair
Owner Company: H1H2 Owner LLC
Owner Street: 535 Madison Avenue
Owner Street 2:
Owner City: new york
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Guy Morton
Owner Company: Greenpoint Landing Developers LLC
Owner Street: 535 Madison Avenue
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 01
Sub Type: P03
Owner Name: Anne Carson Blair
Owner Company: H1H2 Owner LLC
Owner Street: 535 Madison Avenue
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Guy Morton
Owner Company: Greenpoint Landing Associates, L.L.C.
Owner Street: 535 Madison Avenue
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Guy Morton
Owner Company: Greenpoint Storage Terminal LLC

Owner Street:	535 Madison Avenue
Owner Street 2:	
Owner City:	New York
Owner State:	NY
Owner Zip:	10022
Country:	United States of America

Owner Op:	06
Sub Type:	P03
Owner Name:	Guy Morton
Owner Company:	H Owner LLC
Owner Street:	535 Madison Avenue
Owner Street 2:	
Owner City:	New York
Owner State:	NY
Owner Zip:	10022
Country:	United States of America

Owner Op:	06
Sub Type:	P03
Owner Name:	anne carson blair
Owner Company:	H1H2 Retail LLC
Owner Street:	535 Madison Avenue
Owner Street 2:	
Owner City:	new york
Owner State:	NY
Owner Zip:	10022
Country:	United States of America

Owner Op:	01
Sub Type:	P03
Owner Name:	
Owner Company:	HP H1H2 Housing Development Fund Company, Inc.
Owner Street:	c/o NYC Partnership HDFC, Inc.
Owner Street 2:	253 West 35th Street, 3rd Floor
Owner City:	New York
Owner State:	NY
Owner Zip:	10001
Country:	United States of America

Owner Op:	19
Sub Type:	NNN
Owner Name:	Dealice Fuller
Owner Company:	Brooklyn Community Board 1
Owner Street:	435 Graham Avenue
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11211
Country:	United States of America

Owner Op:	06
Sub Type:	P03
Owner Name:	Guy Morton
Owner Company:	GPL Development LLC
Owner Street:	535 Madison Avenue
Owner Street 2:	
Owner City:	New York
Owner State:	NY
Owner Zip:	10022
Country:	United States of America

HW Extra Information

Dump:	False	***Dell:***	
Structure:	False	***Updated By:***	RECURLEY
Lagoon:	False	***Record Added:***	2020-03-23 15:30:00
Landfill:	False	***Record Updated:***	2022-11-15 09:28:00

Pond: False
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Projects Information

Project Code: 25
Project Desc:
Project Refer Name:
End Date: 2022-12-15 00:00:00
End Status: ACT
Operable Unit ID: 1377633
Operable Unit: 00
Operable Unit Desc: Site Management
Code Name: Certificate of Completion

Project Code: 05
Project Desc: Remedial Action
Project Refer Name: Excavation, SMDS
End Date: 2022-12-15 00:00:00
End Status: ACT
Operable Unit ID: 1346407
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Action

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2021-04-13 00:00:00
End Status: ACT
Operable Unit ID: 1346407
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Environmental Remediation

Operable Unit: 01
Contaminants: arsenic, barium, benzo(a)anthracene, benzo(a)pyrene, chrysene, copper, lead, mercury

Operable Unit: 00
Contaminants: arsenic, barium, benzo(a)anthracene, benzo(a)pyrene, chrysene, copper, lead, mercury

---

190 | **1 of1** | **NW** | **0.41 / 2,188.61** | **10.37 / -2** | **BULOVA CORPORATION**
77 COMMERCIAL STREET
BROOKLYN NY | **LST**

Spill No: 0211097
Site ID: 137163
DER Facility ID: 117348
CID: 204
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Test Failure
Water Body:
Class: C3
Meets Std: False
Penalty: False
County: Kings
Referred to:
Reported by: Tank Tester
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: False
Spill Date: 02/05/2003 10:30:00 AM
Rcvd Date: 02/05/2003 11:03:00 AM
CAC Date:
Insp Date:
Close Date: 04/09/2003 12:00:00 AM
Create Date: 02/05/2003 12:00:00 AM
Update Date: 01/07/2004 12:00:00 AM
DEC Region: 2
Lead DEC: JBVOUGHT
After Hours: False

Caller Remark:

"TANK TEST FAILURE"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT arakhan 2/5/03 TTF Letter sent. 3/4/2003-Vought-Spoke with Bob Weber (718-204-3277) who is vice president of operations. Initial test failure was due to open vent line. Vent line was sealed and tank passed system test. Tank will be abandoned in place. NYSDEC requires copy of passing test and work invoice. Tank is a 15000 gallon UST. Mr. Weber will send in PBS notification of abandonment to PBS Unit and copies of test and invoice to Vought. 4/9/2003-Vought-Recieved passing system test results and work invoice. Spill closed by Vought."

Material Information

OP Unit ID:	862135	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	514458	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	BOB WEBER
Spiller Company:	BULOVA CORPORATION
Spiller Address:	77 COMMERCIAL STREET
Spiller City:	BROOKLYN
Spiller State:	NY
Spiller Zip:	11222-
Spiller Country:	001
Contact Name:	PHIL FAZIN
Contact Phone:	(516) 375-5890
Contact Ext:	
Latitude:	40.737300570
Longitude:	-73.956727340

Tank Test Information

Spill Tank ID:	1528007	***Source:***	
Tank No:	1	***Leak Rate:***	.00
Tank SIze:	15000	***Gross Fail:***	
Material:	0001	***Modified by:***	Spills
EPA UST:		***Last Modified:***	2004-10-01 04:00:45.140000000
UST:		***Test Method:***	03
Cause:			
Alt Test Method:	Horner EZ Check I or II		

191	***1 of1***	***E***	***0.42 / 2,213.55***	***7.07 / -5***	***UNITED METRO ENERGY - BROOKLYN TERMINAL*** ***BROOKLYN NY***	***PFAS IND***

Status:	Active	***Fac Fips Code:***	36047
Fac Indian Cntry Flg:	No	***Compliance Status:***	No Violation Identified
Fac Derived Huc:	02030201	***EPA Programs:***	CAA; CWA; RCRA
Fac Derived Wbd:	020301010405	***Federal Facility:***	No
Fac Derived Cd113:	12	***Federal Agency:***	-
Fac Derived Cb2010:	360470579002011	***Fac Snc Flg:***	No
Fac Informal Count:	1	***AIR Flag:***	Yes

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Last Informal Action:	5/18/2020	**NPDES Flag:**	Yes
Formal Action Count:	0	**SDWIS Flag:**	No
Last Formal Action:	11/18/2005	**RCRAFlag:**	Yes
Fac Total Penalties:	0	**TRI Flag:**	Yes
Fac Penalty Count:	-	**GHG Flag:**	No
Date Last Penalty:	11/18/2005	**TRI IDs:**	11222MTRTR498KI
Last Penalty Amt:	2500	**TRI Releases Trnsfrs:**	2961
Fac Qtrs With Nc:	0	**TRI on Site Releases:**	2961
Programs With Snc:	0	**TRI off Site Trnsfrs:**	0
Fac Percent Minority:	49.385	**TRI Reporter:**	Yes
Fac Pop Den:	46486.66	**Fac Imp Water Flg:**	Yes
Count:	1	**Fac Major Flag:**	-
Fac County:	KINGS	**Fac Active Flag:**	Yes
State Other :		**Fac Inspection Count:**	2
Region:	02	**Date Last Inspection:**	9/8/2022
Latitude:	40.73385	**Days Last Inspection:**	744
Longitude:	-73.943		

Fac Derived Tribes:	-
AIR IDs:	NY0000002610100093
CAA Permit Types:	80% Synthetic Minor Emissions
CAA NAICS:	424710
CAA SICS:	5171
NPDES IDs:	NY0007676
CWA Permit Types:	Non-M
CWA NAICS:	-
CWA SICS:	5171
RCRA IDs:	NYD040796211
RCRA Permit Types:	Other
RCRA NAICS:	32411 42271
SDWA IDs:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA Snc Flag:	No
Fac Collection Meth:	ADDRESS MATCHING-HOUSE NUMBER
EJSCREEN Flag Us:	No
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.943,%22y%22:40.73385,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110000323427
Industry:	Petroleum

192	1 of1	SE	0.42 / 2,227.52	11.69 / 0	METAL SPECIALTIES-775-797 HUMBOLDT ST BROOKLYN NY	PFAS IND

Status:	Active	**Fac Fips Code:**	36047
Fac Indian Cntry Flg:	No	**Compliance Status:**	No Violation Identified
Fac Derived Huc:	02030201	**EPA Programs:**	CAA; RCRA
Fac Derived Wbd:	020301010405	**Federal Facility:**	No
Fac Derived Cd113:	12	**Federal Agency:**	-
Fac Derived Cb2010:	360470573001006	**Fac Snc Flg:**	No
Fac Informal Count:	0	**AIR Flag:**	Yes
Last Informal Action:	-	**NPDES Flag:**	No
Formal Action Count:	0	**SDWIS Flag:**	No
Last Formal Action:	-	**RCRAFlag:**	Yes
Fac Total Penalties:	0	**TRI Flag:**	No
Fac Penalty Count:	-	**GHG Flag:**	No
Date Last Penalty:	-	**TRI IDs:**	-
Last Penalty Amt:	-	**TRI Releases Trnsfrs:**	-
Fac Qtrs With Nc:	0	**TRI on Site Releases:**	-
Programs With Snc:	0	**TRI off Site Trnsfrs:**	-
Fac Percent Minority:	52.828	**TRI Reporter:**	-
Fac Pop Den:	46582.5	**Fac Imp Water Flg:**	-
Count:	1	**Fac Major Flag:**	-
Fac County:	KINGS	**Fac Active Flag:**	Yes
State Other :		**Fac Inspection Count:**	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Region:	02	**Date Last Inspection:**	12/17/1992
Latitude:	40.7287	**Days Last Inspection:**	11601
Longitude:	-73.94596		
Fac Derived Tribes:	-		
AIR IDs:	NY0000002610100148		
CAA Permit Types:	Minor Emissions		
CAA NAICS:	423490		
CAA SICS:	3479 3499		
NPDES IDs:	-		
CWA Permit Types:	-		
CWA NAICS:	-		
CWA SICS:	-		
RCRA IDs:	NYD147385744		
RCRA Permit Types:	Other		
RCRA NAICS:	-		
SDWA IDs:	-		
SDWA System Types:	-		
SDWA Compliance Status:	-		
SDWA Snc Flag:	No		
Fac Collection Meth:	ADDRESS MATCHING-HOUSE NUMBER		
EJSCREEN Flag Us:	Yes		
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.94596,%22y%22:40.7287,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1		
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110019396296		
Industry:	Metal Coating		

193	1 of4	ENE	0.42 / 2,233.84	2.05 / -10	SIMS METAL MANAGEMENT 30-27 GREENPOINT AVE LONG ISLAND CITY NY	LST

Spill No:	1200318	**REM Phase:**	1
Site ID:	462940	**UST Trust:**	False
DER Facility ID:	87815	**Spill Date:**	04/11/2012 05:00:00 PM
CID:		**Rcvd Date:**	04/11/2012 05:05:00 PM
Program Type:	ER	**CAC Date:**	
SWIS Code:	4101	**Insp Date:**	
Contribute Factor:	Tank Test Failure	**Close Date:**	
Water Body:		**Create Date:**	04/11/2012 05:07:00 PM
Class:	C3	**Update Date:**	07/22/2024 01:22:51 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	MEDELUKE
County:	Queens	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Line test failure."

Dec Remark:

"Spoke with Bill.Underground line failed test.Investigation required.(sr) 06/25/12 Rec'd Work Plan to investigate the horizontal and vertical extent of subsurface petroleum impacts.(sr) 08/07/12 LNAPL delineation work completed, summary report will be sent to DEC shortly.(sr) 02/06/13 Remedial Investigation Report in edocs.The site is an active scrap metal recyling facility located at the confluence of Dutch Kills and Newtown Creek.The Dutch Kills is located to the west of the site.Newtown Creek is located to the south of the site, property to the north is rail road track operated by LIRR.The adjoining properties to the east of the site are utilized by others for commercial and or industrial operations.Spill was identified when the pressure test of the underground line failed(AST 150,000 gallon).Leak was identified.Franklin Company disconnected the feed and return line.Integral Engineering performed remedial investigation.Twenty five soil borings and twenty one monitoring wells were installed through out the site.Monitoring wells were installed in soil borings with significant impacts and visible LNAPL at the groundwater interface.Five permanent monitoring wells were installed in phase I.Petroleum impacted soil/fill was observed in SB-6/MW-2 at 7-10 ft bgs in the northern corner of the Site, adjacent to the rip-rap bulkhead along the Dutch Kills Basin. Three separate plumes of LNAPL are present at the site.Plume A consists of weathered and biodegraded diesel fuel, located to the northwest of AST and west of the underground pipeline trench in the vicinity of MW-1(3.81ft), MW-2(2.28ft), MW-9(0.11 ft), MW-10(0.37 ft), MW-11(0.38 ft) and MW-13(2.62ft). Plume A is believed to be downgradient of the source of the diesel fuel release. Plume B consists of weathered and biodegraded diesel fuel, concentrated in the former pipeline trench, in the vicinity of MW-19(0.12 ft) and MW-20(0.28 ft).Plume B is also appears to be result of an additional segments of corroded and impaired pipings.There are no active sources for Plume A and Plume B as the underground pipelines were

removed. Plume C consists of a more viscous and highly weathered unidentified LNAPL in the vicinity of MW-15(0.50 ft) and MW-16(0.43 ft). The following wells are identified with no LNAPL and are being used to illustrate the outer limits of Plume A, B and C:MW-3, MW-4, MW-5, MW-6, MW-7, MW-8, MW-12, MW-14, MW-17, MW-18, MW-21. Ground water was encountered at depth of 5 ft bgs throughout the site. Recovery effort was performed on Plume A to remove product and monitor for product recharge to evaluate the optimal locations for long term recovery efforts. Plume area A appears to be the greatest available volume of recoverable LNAPL. The proposed IRM includes installation of recovery wells and electric belt skimmers. Three recovery wells(RW-1, RW-2 and RW-3)were installed in Plume A. Additional recovery wells/belt skimmers setups are anticipated for plume B and C as part of the IRM. 03/01/13 Rec'd email from Kevin Mccarthy(212-962-439x314) regarding Offsite investigation on LIRR proerty.They are checking the issue with their attorney.(sr) 3/12/14-Vought-DEC Rahman received email from DEC Ian Beilby dated 3/11/14 that Hi Sharif, Any new progress on this investigation? I checked edocs but it looks like there has been no activity in the past year. DEC Rahman forwarded email to Vought and Vought spoke to DEC Demeo and spill to be assigned to DEC Mahat. 4/2/14-Vought-Sent email to DEC Beilby with cc to DEC Mahat that Ian, The case has been reassigned to Santosh Mahat (cc'd above) and you may also reach him at 718-482-4038. Thanks. Spill reassigned from Rahman to Mahat. 9/3/14: Mahat DEC Mahat contacted Mr. Kevin McCarty @ 212-962-4303 inquiring more information about the current status of the remediation actions. Mr. McCarty mentioned that the remediation is still going on and he is recovering free products from couple of recovery wells. He is using belt skimmer to collect free products. A report is due from November 2012-present day. 9/25/14 TJD Spill #1405728 associated with housekeeping was identified during inspection of facility as part of Newtown Creek/Dutch Kills sheen trackdown investigation on 8/26/14. Spill of waste oil was observed following the acceptance and dumping of debris reported to have been brought to the facility by NYC Housing Authority. The spill was cleaned immediately by facility personnel. Above spill note is for reference only as surface spill is not directly related to reported AST tightness test failure and subsequent removal of AST and installation of monitoring well network and recovery system. DEC REQUIRE : 1. Need all laboratory data from monitoring well even with no product well. 2. Measure Groundflow dirrection 3. Dissolved GW sampling at plume edge wells 4. Monitoring recovery wells by dispenser line - Deleniation. 5/20/15: Mahat DEC Mahat received an email uopdate from James L'Esperance (Integral). Santosh, Sims has just informed me that they plan on commencing work on the stormwater basin at their Queens facility tomorrow. This work will involve excavating soil from the area of Spill #12-00318, as discussed during our site meeting and in the Remedial Action Letter submitted in April. Sims intends on starting the work tomorrow. I'm anticipating that the work will last 2-4 weeks. Integral will have a geologist on-site during all excavation activities. Please feel free to give me a call to discuss if you have any questions. Thanks, James James L'Esperance Integral Consulting Inc. - www.integral-corp.com 61 Broadway, Suite 1601 - New York, NY 10007 Tel: 212.440.6708 - Cell: 646.285.4808 - Fax: 212.962.4302 8/6/15: Mahat DEC Mahat received an email from the contractor regarding the backfill material: Email: Santosh, Here's the information on the imported recycled concrete fill that we discussed. Allocco Recycling is a NYSDEC registered C&D facility. This material will be used as backfill beneath pavement. Let me know if there's anything else you need. Thanks! James L'Esperance The backfill documents has been uploaded on D2 for reference. 8/13/15: Mahat Site Visit: DEC Mahat and DEC Omar visited the site during the side wall sample collection. All collected sampled will be analyzed for the EPA 8260 and EPA 8270. A complete report will be forwarded to the Department one the results is published. 8/18/15: Mahat DEC Mahat request Mr. L'Esperance to provide a weekly report on the site: Here an update: Weekly Progress Report for SIMS Metal Management (Queens) August 18, 2015 30-27 Greenpoint Avenue, LIC, NY Spill # 12-00318 In May 2015, SIMS Metal Management (SMM) began excavating the area of open spill #12-00318 down to approximately 5 ft bgs as part of their plans to install a storm water retention basin. Due to space restrictions on-site, the excavation is being performed in several stages. Two soil stockpiles (COMP-1 and COMP-2) were generated and separated based on the degree of contamination from visual and olfactory inspection, as well as measuring volatiles with a PID. Soil from COMP-2 was significantly more impacted than soil from COMP-1. Waste characterization samples were collected in mid-June, and the soil was removed from the Site upon approval from Clean Earth New Jersey (CENJ). Material from COMP-1 (approximately 30 cubic yards) was transported to CENJ of Carteret in mid July. Material from COMP-2 (approximately 240 cubic yards) was transported to the same facility from July 29-31. On August 5, SMM's contractor (NOVA) began installing supports and sheathing within the excavation. On August 13, Integral (James L'Esperance and Stacey Ng) collected a total of ten sidewall endpoint samples outside of the sheathing, representing the material to be left in place. All soil samples will be analyzed for CP-51 list VOCs (via USEPA Method 8260C) and SVOCs (via USEPA Method 8270D), in accordance with the Remedial Action Letter, dated April 16, 2015. A groundwater bottom sample will be collected once all of the sheathing is installed and all material is removed from the excavation. This week, the remaining material will be excavated, sampled, and characterized for disposal as another pile (COMP-3). Please let me know if you have any questions. Thanks, James 8/24/15: Mahat Weekly Update: Weekly Progress Report for SIMS Metal Management (Queens) August 24, 2015 30-27 Greenpoint Avenue, LIC, NY Spill # 12-00318 Last week, the contractor (NOVA) completed the installation of sheathing around the extents of the excavation. This week, the remaining material will be excavated, sampled, and characterized for disposal as another pile (COMP-3). The water bottom sample is tentatively scheduled for Monday, August 31. Please let me know if you have any questions. Thanks, James 8/28/15: Mahat DEC Mahat received an email informing the water bottom sample will be taken on August 31, 2015. Result of the samples will be forwarded to the Department for review. 9/1/15: Mahat DEC Mahat received another update on the case: Update: Last week, SMM's contractor (NOVA), began excavating the remaining material left in the footprint of the future retention basin. From Aug. 24-27, NOVA removed approximately 1,000-1,300 cubic yards of material and stockpiled the soil to the southwest of the excavation. Large wood debris and impacted boulders/concrete were taken to an approved facility for proper disposal. On Friday, Aug. 28, NOVA completed removing all required material, at which point, Integral collected waste characterization samples according to the sampling protocol for Clean Earth of New Jersey (CENJ). This stockpile is referred to as COMP-3 and will remain covered on-site until approval from CENJ. Upon receipt of the results from the lab analysis, CENJ will provide trucks to begin hauling material off-site to its facility in Carteret, NJ. This is expected to begin sometime during the week of September 7, 2015. Yesterday, Aug. 31, Integral returned to site to collect the "bottom" endpoint groundwater sample. We anticipate receiving analytical results next week. 9/4/15: Mahat DEC Mahat received endpoint sample those were collected from the side walls and bottom of the excavation. All laboratory result has been uploaded on D2 for reference. All collected wall samples are Below CP 51 guidance value. GW water sample was below TOGS standards with exception of Naphthalene, Benzo(b) fluranthene, Cherysene and Indeno are slightly above TOGS Standard.Based on the laboratory result, no further remedial action is warranted on the excavated area. However, there are 6 1" monitoring well that needed GW samples. James will collect water sample from those MW and analyzed for EPA 8260 and EPA 8270 for the confirmation. More remediation plan will be drafted once the result is out. DEC is waiting for sample report. 9/15/15: Mahat DEC Mahat sent an email to Mr. L'Esperance: Email: James, I have reviewed the site map and soil samples submitted on 9/4/15. Almost all soil samples are below CP 51 guidance values. There is nothing to discuss on this portion of the site for further remediation unless GW sample is opposite. The Department is also interested to know the current status of the former underground pipeline that runs behind the building. Feel free to contact me if you have any questions or concerns. Ps. we can conduct a conference call once GW result is out. 10/07/15: Mahat DEC Mahat received an email from Mr. L'Esperance: Email: Santosh, I've just received the groundwater results for the trench wells at the site (see attached). MW-19 was not sampled because its cap and casing are damaged beyond repair. MW-21 was not sampled because it was dry at the time of sampling. Please let me know when you'd like to discuss the results. Thanks, James 10/8/15: Mahat DEC Mahat sent an email to Mr. L'Espernace confirming further remediation on the site is not warranted by the Department. Email: James, Thank you for the info and update. The Department is satisfied with all the lab results. Please prepare a standard report for the closure of the spill case. Let me know if you have any questions or concerns. Santosh Mahat - Environmental Engineer DEC Mahat is waiting for a complete closure report for review. 2/9/16: Mahat DEC Mahat contacted Mr. L'Espernace inquiring about the status of the closure report. The report has been submitted to SIMS for a review. Once the report is done reviewing by SIMS rep. it will be forwarded to the

Department. 4/12/16: Mahat DEC Mahat uploaded the closure report submitted to the Department. Based on the report, the Department does not warrant any further action on the site. Spill case is closed on NYSDEC Spill database. 4/25/16: Mahat e/c: A spill closure letter has been sent and uploaded on D2 for reference. 8/10/16: Mahat e/c: DEC Mahat received an email update from the consultant via email. He notified the Department that the free product has been detected MW-16. Email: Hi Jeff and Santosh,As discussed on Friday, 0.17 feet (about 2 inches) of separate-phase product was discovered in MW-16, which is a 1" well located in the former pipeline trench northeast of where the excavation occurred. The product was bailed out and the well re-gauged; no product was immediately detected. As discussed, Sims and Integral will bail the well every two days, and also gauge the well on a regular basis for the next two months. I'll keep both of you updated with the results of this exercise. Thanks, James Based on the email, the spill case has been re-opened and further investigation/action is required. As per the email, the consultant will be gauging the MW for another two months and bail MW every two days. 10/21/16 - Austin - Transferred from Santosh Mahat (transferred out of Spills unit)to Jeff Vought for continuance of the work - end 1/17/17-Vought-Received email from DEC Ian Bielby that Jeff, Sorry to bother you on this spill but I see this spill is reopened due to some reappearance of NAPL. I'm trying to determine if there are potential impacts to newtown creek as a result of this information. Can you tell me whether there are any wells close to Newtown creek that have NAPL? Vought performed full D2 file review and produced Non-FOIL summary site plans. Vought noted that reports describe three LNAPL plumes (Plumes A, B, C) and Plume A was addressed via excavation of the entire plum to 5' below the water table. Plume B and C were addressed reportedly via hand bailing. Vought noted however that Plumes B and C were never delineated and also documentation does not specify how these plumes were remediated. 1/18/17-Vought-Sent letter to Simsmetal East LLC, approving of email proposal dated 8/10/16 and requiring submission of a RIWP including: 1)Product recovery data for well MW16 as per 8/10/16 Email from Integral 2)Delineation of soil and groundwater contamination of Plume C at MW-16 3)Submission of Historical IRM data for Plume C 4)quarterly sampling of wells surrounding Plume C. CC'd on letter were Intergral(L'Esperance), OGC Urda and DEC Bielby. Vought also added letter to D2. Vought sent email reply to DEC Bielby that Ian, You never need to apologize as you are never a "bother" lol. In response to your email query below, and as I recently took over this project from Santosh (who has departed Spills), I have reviewed all available files in D2 and drafted up my usual technicolor Non-FOIL summary site plans which are attached above. To answer your question on "potential impacts to Newtown Creek" there were historical impacts to the Creek with a documented " sheen" in 2012 from what the reports call LNAPL "Plume A". Furthermore data from this time also showed up to .5' of LNAPL in well MW-2 which was immediately adjacent to the Creek. In 2016, Plume A was entirely excavated to 5 feet below the water table as part of the installation of a new storm water retention basin. Endpoint samples from the Plume A excavation only showed minor detections of VOCs above Unrestricted SCOs and a bottom groundwater sample from the excavation only showed 85ppb benzene and 30ppb naphthalene. There were also two additional LNAPL plumes at the site (Plumes B and C) which were remediated via bailing of wells. Note that Plumes B and C are separated from the Creek by the remedial excavation of Plume A so it is unlikely that these plumes are currently impacting the Creek. Due to the disappearance of LNAPL from the site as well as minimal dissolved groundwater concentrations, the spill was closed on 4/25/16. On 8/10/16, we received an email from the consultant that .17' of LNAPL was observed in MW-16 which was identified as part of Plume C. In this email the consultant proposed manual bailing of the well and submission of a report. At that point the Department re-opened the Spill. As I have just reviewed the entire file, I am sending out a letter (attached above) to the consultant via separate email today (with a copy to you) requiring submission of a RIWP including: 1) Product recovery data for well MW16 (Plume C) 2) Delineation of soil and groundwater contamination of Plume C 3) Submission of Historical IRM LNAPL recovery data for Plume C 4) Quarterly sampling of wells surrounding Plume C. Hope this this helps and as always let me know if you need anything else, Thanks! 1/18/17-Vought-Sent email to Integral (L'Esperance) with cc to OGC Urda and DEC Beilby that James, I have taken over the above referenced spill from Santosh Mahat as he is no longer with the Spills Unit and as such I have reviewed all available reports for the site that are in our document system. I have attached the Department's spill reopening and requirement letter above and look forward to the submission of an RIWP that includes the requirements on the letter. An original of the letter is in the US mail to SIMS Metal East. Thanks. 1/19/17-Vought-Received email from Integral (Keith Brodock) with cc to OGC Urda, DEC Bielby, Integral (Corso/McCarty) that Hi Jeff, Katie Corso has taken over the SIMS project on our end, with support from Kevin McCarty (both copied here). (James L'Esperance left Integral for a job at Northrup Grumman in California.) I will forward your email to Katie and Kevin, and one of them will be in touch. Please give me a ring if you need anything in the interim. Contact for Integral is: Kathryn Corso email: kcorso@integral-corp.com Ph: (212)440-6702 Cell:646-895-3325 Vought sent reply to Brodock with cc to all that Keith, Thanks for the quick reply and the new contact information for Integral. If Katie and Kevin have any questions and/or would like to discuss the Department's requirements, they can certainly call me. DEC Requires as per Consent Order, Resubmission of RIWP including: 1)Approval of proposal for IRM Product recovery from Plume B as per 8/10/16 email from Integral pending inclusion of 2)Delineation of Plumes B 3)Submission of IRM Reports showing recovery for Plume C. Installation of 4 recovery well at location. 4) Quarterly groundwater monitoring of surrounding wells 5)cc to Integral (Brodock/ Katie Corso), DEC Bielby, OGC Urda 12/12/17 - Austin - Assigned from Vought to Patel - end 07/09/18-Hiralkumar Patel. alternate address: none PBS #: 2-095354. as per PBS record, the site had/has following tanks: - one (1) 275 gal #2 fuel oil AST, closed prior to Mar. 1991 - one (1) 275 gal lube oil AST, closed prior to Mar. 1991 - two (2) 275 gal waste oil AST, closed prior to Mar. 1991 - one (1) 990 gal diesel oil AST, closed prior to Mar. 1991 - two (2) 1,000 gal #2 oil ASTs, closed prior to Mar. 1991 - one (1) 2,000 gal diesel UST, closed prior to Mar. 1991 - one (1) 1,100 gal gasoline UST, closed prior to Mar. 1991 - one (1) 2,000 gal #2 oil AST, closed prior to Mar. 1991 - one (1) 2,000 gal #2 oil UST, closed prior to Mar. 1991 - one (1) 500 gal waste oil AST, closed prior to Mar. 1991 - one (1) 100 gal lube oil AST, removed in May 2012 - one (1) 150,000 gal diesel AST, removed in May 2014 - one (1) 4,000 gal diesel AST, in-service, installed in Sep. 2017 - one (1) 1,000 gal diesel AST, in-service, installed in Nov. 2013 - one (1) 275 gal motor oil AST, in-service, installed in Feb. 2012 - one (1) 660 gal diesel AST, in-service, installed in Jan. 2008 - one (1) 275 gal lube oil AST, in-service, installed in Nov. 2006 - one (1) 550 gal diesel AST, in-service, installed in Nov. 2006 - one (1) 275 gal hydraulic oil AST, in-service, installed in Nov. 2006 - one (1) 275 gal hydraulic oil AST, in-service, installed in Jan. 2007 - one (1) 275 gal motor oil AST, in-service, installed in Jan. 2007 - one (1) 275 gal waste oil AST, in-service, installed in Jan. 2007 other spills #: 9805015, 0613037, 1405728 spill #: 9805015 was reported on 07/22/1998 as 15 gal #2 fuel oil spilled due to failed line on truck. spill closed. spill #: 0613037 was reported on 03/05/2007 as scarp metal barge sunk in water. case closed. spill #: 1405728 was reported on 08/26/2014 as 2 gal waste oil spilled from scrap brought into yard. spill closed. summary of spill closure report dated 02/10/16: - total of 21 permanent and temporary groundwater monitoring wells and piezometers were installed in the area of the AST and its associated feed and return lines - in mid-2012, product thickness in the area of the tank ranged from 0 to 0.48 ft in 2-in wells, and 0.50 to 3.91 ft in 1-in wells - product thicknesses in the area of the feed and return lines (the pipe trench area) ranged from 0 to 0.29 inches - in Dec. 2012, three (3) 4-in recovery wells and the belt skimmer were installed immediately north of the decommissioned diesel tank - skimmer begun removal operations after the freeze risk was over in Mar. 2013 - product thicknesses dropped drastically across the site immediately following the skimmer start-up, with the last measurable product thickness being recorded on 07/07/2014 (this was before product noted again in Aug. 2016) - DEC sent email on 05/20/15 approving plan for installation of a stormwater retention basin that required excavation of material from the area of the former diesel AST - excavation extended to 5 ft bg, which was slightly below the average water table depth in the area (about 4.5 ft bg) - a slight sheen was noted on the water table within the excavation - no sheen noted in Dutch Kills located adjacent to excavation area - approx. 1,000 cu. yd. of soil was removed - collected total of nine (9) endpoint sidewall soil samples and one bottom groundwater sample (as excavation extended below water table) - groundwater samples were also collected from the seven former pipeline trench wells - no contamination was noted in soil or groundwater samples the subject spill case was reported due to tightness test failure of underground lines of 150,000 gal diesel AST at the site. during further investigation, the underground supply/return lines were found corroded. the faulty lines and the tank were removed from the site. multiple soil borings and groundwater monitoring wells were installed during subsurface investigation/remediation. three separate LNAPL plumes (A, B and C)

were identified: - Plume A consists of weathered and biodegraded diesel fuel, located in the area to the north of and adjacent to the AST. this plume was remediated via product recovery using skimmers and excavation for installation of stormwater retention basin. - Plume B consists of weathered and biodegraded diesel fuel, concentrated in the former pipeline trench in the vicinity of wells MW-19 and MW-20 (near northeast corner of on-site building which is first building to the east of the former tank) - Plume C consists of a more viscous and highly weathered unidentified LNAPL, concentrated in the vicinity of the former pipeline trench in the vicinity of wells MW-15 and MW-16 (near northwest corner of on-site building which is second building to the east of the former tank) the spill case was closed on 04/25/2016 based on review of Spill Closure Report dated 02/10/16 (summarized above), but re-opened in Aug. 2016 as product was noted again in existing well MW-16 (Plume C). on 01/18/2017, DEC Vought sent letter requiring delineation of Plume C, IRM data for Plume C and quarterly sampling of well around Plume C. 10:35 AM:- left message for Keith at Integral. 10:56 AM:- received call from Keith and Katie from Integral. Keith mentioned that no work has been conducted since case re-opening. asked Keith to send copy of IRM Report dated 06/10/13 (as incomplete report in file), Remedial Action Letter dated 04/16/15 (which is missing) and email dated 08/10/16 (if available). 12:02 PM:- left message for Mr. Cunningham. Prolerized Schiabo-Neu Company **property owner as per NYC ACRIS** (partnership of Hugo Neu & Sons, Inc., Proler International Corp. and Schiavone-Bonomo Corp.) Simsmetal East LLC. **owner listed on PBS record** One Linden Avenue East Jersey City, NJ 07305 Attn.: Craig Cunningham Ph. (201) 577-3200 / 3158 (201) 725-8515 email: craig.cunningham@simsmm.com 12:20 PM:- sent email to Mr. Cunningham including copy of letter dated 01/18/2017. asked him to immediately submit required information/documents. email copied to Keith and Katie. 12:25 PM:- received call from Mr. Cunningham and inquired him about required documents as per letter dated 01/18/17. he mentioned that Integral is doing groundwater monitoring. informed him about discussion with Keith/Kathryn (who mentioned that no remedial activities conducted by Integral at the site since case reopening) earlier today. asked Mr. Cunningham to schedule a site inspection and well gauging. 12:33 PM:- sent email to Mr. Cunningham and asked him to schedule a site inspection. informed him that all well locations should be clear for inspection/gauging. email copied to Keith and Katie. 1:50 PM:- received email from Katie including IRM Report and Remedial Action Letter. remedial action letter included proposed work for installation of stormwater retention basin. the IRM report is missing Appendix A (Well Gauging Data). 07/11/18-Hiralkumar Patel. 11:44 AM:- received email from Katie. she mentioned that their IT department look through James L'Esperance's email archives, but did not find the email from August 10, 2016. also, she did not find the actual attachment A to the IRM report, but submitted the well gauging data from 2012-2014. reviewed well gauging data in IRM report. area of Plume A was remediated via excavation to install a stormwater retention basin. wells MW-19 and MW-20 were located in area of Plume B. during well monitoring between Aug. 2012 and Oct. 2014, product was not found in well MW-19 after Nov. 2013; and in well MW-20 after Nov. 2012. wells MW-15 and MW-16 were located in area of Plume C. during well monitoring between Aug. 2012 and Oct. 2014, product was not found in well MW-15 after Sept. 2013 (except 2.5 in. in Nov. 2013); and in well MW-16 after Nov. 2013. 1:30 PM:- sent email to Katie and asked her to schedule a site inspection to gauge all existing wells. email copied to Keith. 07/26/18-Hiralkumar Patel. received email from Katie (at 1:57 PM on 07/25/18) including copy of email dated 08/10/16 (from James to DEC Vought/Mahat). Katie also confirmed site inspection at 10 AM on 08/02/18. 08/02/18-Hiralkumar Patel. 10:00 AM:- visited site with DEC Sekhon. met Keith (Integral), Katie (Integral), Eric Knorr (facility manager) and Mr. Cunningham. Mr. Cunningham mentioned that only one well MW-16 is left at the site and all other wells were either closed or destroyed. free phase product was noted outside a bailer previously placed in the 1-inch well. Katie mentioned that the well MW-16 has been gauged multiple times since detection of product in Aug. 2016. she also stated that product sample was collected from the well recently for fingerprint analysis. mixture of degraded diesel fuel and lubricating oil is found in the well. well MW-16 was gauged. groundwater was found at 5.5 ft bg, with 4 inches of product on top. a previously used utility vault was noted approx. five ft east of well MW-16 location. Mr. Cunningham mentioned that the concrete vault was taken out-of-service when they removed generator from the site. the concrete vault is approx. 6 ft deep. informed Mr. Cunningham/Keith that the Department requires further remediation at the site either by 1) replacing 1-in well with larger diameter well/adding more wells to the east (as there were no well to the east of MW-16 in past) and installation of belt skimmer, or 2) using existing vault for product recovery by drilling holes in vault's walls/floor to allow product accumulation, or 3) excavation/removal of contaminated material in the area of MW-16. Mr. Cunningham will discuss remedial options with property owner and will send a work plan. Eric Knorr Facility Manager PH. (718) 786-6031 (646) 531-0822 (C) email: eric.knorr@simsmm.com 12:03 PM:- received call from Keith. he mentioned that property owner has planned to use existing concrete vault for product recovery. he will submit plans for that. 2:14 PM:- received email from Katie including well gauging data and fingerprint analysis result. product sample was collected on 07/13/18 and results show that the sample contained a mixture of both diesel fuel oil (#2 fuel oil) and a lubricating, motor or waste oil. well MW-16 was gauged multiple times between July 2016 and Oct. 2017 and noted product between 0.03 ft and 0.55 ft (max. on 08/31/17). 09/20/18-Hiralkumar Patel. 9:49 AM:- received email from Katie. she mentioned that ConEd will inspect the vault and confirm it is abandoned. she is waiting for drawings for the oil recovery system. 10/12/18-Hiralkumar Patel. 12:44 AM:- sent email to Katie inquiring updates. 12:51 PM:- received email from Katie. she mentioned that ConEd has visited the site once, but they are due back again on 10/24. after this second site visit, SIMS hopes to get an answer from ConEd on whether they can use the manhole for oil recovery. 07/18/19-Hiralkumar Patel. 1:12 PM:- sent email to Keith/Katie inquiring updates. email copied to Mr. Cunningham and Mr. Knorr. 10/22/19-Hiralkumar Patel. 3:05 PM:- sent email to Keith, Katie, Mr. Cunningham and Mr. Knorr inquiring updates. 10/24/19-Hiralkumar Patel. 2:22 PM:- received email from Katie including a site photograph and rough diagram of oil recovery system. she spoke with Glenn Cavanaugh at SIMS. Glenn has been working on building an oil recovery system at the site to pull groundwater from an old ConEd manhole near the trench well (MW-16) and pump it to an oil water separator onsite. holes have been cut into the manhole to allow groundwater to flow in. SIMS has installed the discharge piping, a pump controller and float levels. currently the system is approximately 75% complete and SIMS expects to have it complete in 30 days. the pipe installation from the holding tank to the oil water separator and from the oil water separator to the detention pond needs to be completed before the system can be energized. SIMS is also working on obtaining final schematics and an operation manual from their contractor EXVAC and are planning to install a run time meter. 11/27/19-Hiralkumar Patel. received email from Katie (at 4:02 PM on 11/26/19). she mentioned that work on oil recovery system should be completed end of next week or week after dependent upon the weather. 12/30/19-Hiralkumar Patel. received email from Katie (at 5:35 PM on 12/27/19). she mentioned that installation of the oil recovery system is complete. property owner is working on adjusting the pump before it will be switched on. Katie is planning to visit the site in the morning on 01/06/20 to take product measurements in well MW-16. 05/28/20-Hiralkumar Patel. 11:59 AM:- sent email to Katie inquiring update. email copied to Keith, Mr. Cunningham, Mr. Knorr and Glenn Cavanaugh (Glenn.Cavanaugh@simsmm.com). 06/16/20-Hiralkumar Patel. received email from Katie (at 5:27 PM on 06/15/20) including gauging record for well MW-16 collected on 01/06/20 and 06/07/20. 1.5 ft of product was noted in well MW-16 on 01/06/20. the oil recovery system has been running since 1/3/2020. Katie visited the site on 06/07/20 and measured 0.05 ft of product in well MW-16. the MW-16 was not bailed for months before the January measurement (while the oil recovery system was being installed) and the well was also not bailed between the January and June measurements. Katie will collect and report monthly measurements from MW-16 (next site visit set for mid-July). 07/09/20-Hiralkumar Patel. received email from Katie (at 3:51 PM on 07/08/20) including gauging record for well MW-16 collected today. no product was noted in well MW-16. 10:22 AM:- sent email to Katie inquiring about amount of oil recovered using the recovery system. 07/22/20-Hiralkumar Patel. 2:41 PM:- received email from Katie. she mentioned that Integral will draft a monitoring plan for MW-16 and the oil recovery system, which will include a plan for monitoring the amount of oil recovered from the system. the plan will be submitted for review in the next few weeks. 08/12/20-Hiralkumar Patel. received email from Katie (at 9:29 PM on 08/11/20) including an interim remedial measure monitoring plan. summary: - SIMS completed construction of IRM oil recovery system in Dec. 2019 and begun operation in Jan. 2020 - will gauge well MW-16 on monthly basis - will collect sample from manhole or pump discharge pipe on monthly basis for TPH analysis ------ - once decided, the oil recovery system will be turned off for a week for a rebound test. well MW-16 will be gauged after a week to check for any product accumulates -

will submit monthly reports 08/18/20-Hiralkumar Patel. 9:16 AM:- sent email to Katie and asked her to submit complete design of oil recovery system. email copied to Keith, Mr. Knorr, Mr. Cunningham and Kevin Roche (Kevin.Roche@simsmm.com). 10:15 AM:- received email from Katie including a line drawing of oil recovery system. 10/15/20-Hiralkumar Patel. received email from Katie (at 4:52 PM on 10/14/20) including results from September monitoring. during the September site visit (on 09/03/20), Integral gauged MW-16 (0.09 ft product noted) and collected a water sample from the manhole (location of the oil recovery system sump pump). the sample was analyzed for diesel range (C10-C28) and extended range (C28-C44) organics. the sample data was used to estimate the mass of DRO and ORO (C10-C44) removed by the system from January to September 2020. Katie mentioned that Integral will continue monitoring the oil recovery system per the proposed monitoring plan emailed on August 11th and will provide updated tables and figures. 12/31/20-Hiralkumar Patel. 11:40 AM:- sent email to Katie and asked her to submit monthly reports, as proposed (in plan submitted on 08/11/20), including complete lab report, overall site map with location of MW-16 and oil recovery system, and disposal manifests. email copied to Keith, Mr. Knorr, Mr. Cunningham and Mr. Roche. 01/19/21-Hiralkumar Patel. received email from Katie (at 8:41 PM on 01/15/21) including monitoring data for Oct. 2020. Integral gauged MW-16 and collected a water sample from the manhole (location of the oil recovery system sump pump) on 10/23/2020. 0.60 ft of product was measured in well MW-16. all product was bailed from the well. the sample was analyzed for diesel range (C10-C28) and extended range (C28-C44) organics. the sample data was used to estimate the mass of DRO and ORO (C10-C44) removed by the system from January to October 2020. Katie stated that the onsite oil water separator gets cleaned once a year and was cleaned out on 7/10/2020. the on-site OWS is not dedicated to the oil recovery system and also services the site's storm water system. 02/08/21-Hiralkumar Patel. 12:10 PM:- sent email to Mr. Knorr/Katie. asked them to submit a site map including location of wells/oil-water separator system and monthly reports since Oct. 2020. also asked them to submit future report in timely manner (monthly as proposed in the plan). email copied to Keith, Mr. Cunningham and Mr. Roche. 02/09/21-Hiralkumar Patel. received email from Katie (at 8:58 PM on 02/08/21) including monthly report for Dec. 2020 and laboratory results of the manhole sample. she mentioned that they do not have a monthly report for November. she will submit the monthly report for January once sample results received. she will also work on getting an overall site map with the locations of MW-16 and the oil recovery system. on 12/28/2020, 1.6 ft of product was noted in well MW-16. 03/11/21-Hiralkumar Patel. 10:28 AM:- received email from Katie including monthly report for Jan. 2021 and laboratory results of the manhole sample. on 01/28/2021, 0.8 ft of product was noted in well MW-16. she mentioned that they changed the calculation for the cumulative DRO and ORO removed by the system. in previous reports they used the total run time for the system to calculate the monthly estimated product removed by the system. this equation was changed to use the run time since the last site visit, plus the estimated cumulative product removed during the last site visit, which is a more accurate estimated than what presented in previous report. 03/30/21-Hiralkumar Patel. 3:22 PM:- received email from Katie including monthly report for Feb. 2021 and laboratory results of the manhole sample. on 02/23/2021, 0.2 ft of product was noted in well MW-16. 04/05/21-Hiralkumar Patel. 3:45 PM:- received email from Katie including monthly report for Mar. 2021 and laboratory results of the manhole sample. on 03/24/2021, 0.04 ft of product was noted in well MW-16. 05/24/21-Hiralkumar Patel. 9:42 AM:- received email from Katie Cowan from Integral including monthly report for Apr. 2021 and laboratory results of the manhole sample. on 04/27/2021, 0.8 ft of product was noted in well MW-16. Kathryn Cowan Ph. (212) 440-6701 email: kcowan@integral-corp.com 07/02/21-Hiralkumar Patel. received email from Katie (at 3:36 PM on 07/01/21) including monthly report for May 2021 and laboratory results of the manhole sample. on 05/27/2021, 0.55 ft of product was noted in well MW-16. 07/08/21-Hiralkumar Patel. 10:40 AM:- received email from Katie including monthly report for June 2021 and laboratory results of the manhole sample. on 06/24/2021, 0.42 ft of product was noted in well MW-16. 07/27/21-Hiralkumar Patel. 10:30 AM:- spoke with Katie and inquired her about design and discharge of water treatment system. she mentioned that the water from the treatment system is being discharged into on-site storm drain system. asked Katie to provide details about the treatment system (just separator or any filtration system) and permit details for water discharge. 08/04/21-Hiralkumar Patel. 9:24 AM:- received email from Katie including specifications for the OWS. she mentioned that water is being pumped from the manhole (concrete vault adjacent to MW-16) to the onsite OWS. in the OWS free-floating oils and floatable oil-coated solids accumulate until they are pumped out. the clearer water beneath the separated waste flows downward and is transferred to the clearwell chamber through PVC riser pipes. the OWS uses a sludge hopper with drain for sludge removal and coalescers to accelerate the separation process. treated water then flows into the onsite storm water retention basin, where further treatment (e.g., silt removal) occurs, as needed, prior to discharge. 9:28 AM:- sent email to Katie and inquired her about water discharge point: city sewer or outfall. 10:45 AM:- received email from Katie stating that the final discharge to an outfall on the Dutch Kills. 08/13/21-Hiralkumar Patel. 9:52 AM:- sent email to DEC Mike Haggerty including response (with attachments) from Katie on 08/04/21 regarding oil/water separator design and outfall details. email copied to DEC Austin. 10:19 AM:- received email from DEC Haggerty inquiring about SPDES permit under which the water is being discharged at the outfall. 10:26 PM:- sent email to Katie and asked her about SPDES permit number under which the water is being discharged at the outfall. email copied to Craig Cunningham (Craig.Cunningham@simsmm.com), Keith and Kevin Roche (Kevin.Roche@simsmm.com). 08/16/21-Hiralkumar Patel. 10:43 AM:- received email from Katie including SPDES permit # NYR00C577 for outfall discharge. 08/17/21-Hiralkumar Patel. 12:07 PM:- received email from Katie including monthly report for July 2021 and laboratory results of the manhole sample. on 07/22/2021, 0.78 ft of product was noted in well MW-16. 09/22/21-Hiralkumar Patel. received email from Katie (at 6:02 PM on 09/20/21) including monthly report for Aug. 2021 and laboratory results of the manhole sample. on 08/19/2021, 0.10 ft of product was noted in well MW-16. 09/28/21-Hiralkumar Patel. after discussing with DEC Austin and DEC Michael Haggerty, case transferred to DEC Haggerty who is coordinating cleanup efforts of the Newtown Creek along with USEPA under a superfund project. case assigned to DEC Haggerty. - sent email to Mr. Cunningham and informed him about case transfer. email copied to DEC Haggerty, Mr. Roche, Mr. Knorr, Katie and Keith. 10/4/21: Haggerty - SIMS shutdown NAPL recovery system and will delineate observed NAPL. 1/19/22: Haggerty - PM approved Subsurface Investigation Work Plan to delineate NAPL observed in MW-16. 1/13/23: Haggerty - PM approved Suburface Investigation Report. 2/8/23: Haggerty - Spill 2209022 called in at the property when NAPL was observed in soil during a subsurface investigation conducted by EPA. 5/8/23: Haggerty - Spills 1200318 and 2209022 will be investigated together under an amended consent order. Refer to Spill 2209022."

Material Information

OP Unit ID:	1213047	***Med in Air:***	False
OU:	01	***Med GW:***	True
Material ID:	2210953	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		

Material Code: 0008
Material Name: diesel

Spiller Information

Spiller Name:
Spiller Company: SIMS METAL MANAGEMENT
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: WILLIAM KLEIN
Contact Phone: (718) 762-5200
Contact Ext:
Latitude: 40.734094222
Longitude: -73.939104916

---

193 | **2 of4** | **ENE** | **0.42 / 2,233.84** | **2.05 / -10** | **Sims Metal Management LIC**
30-27 Greenpoint Avenue
Long Island City NY 11101 | **SWF/LF**

Activity Number: [41MA6]
Facility Name (Act): Sims Metal Management LIC
Location Addr (Act): 30-27 Greenpoint Avenue
Location Addr2 (Act):
City (Act): Long Island City
State (Act): NY
Zip Code (Act): 11101
County (Act): Queens
East Coord (Act): 589598
North Coord (Act): 4509798
Facility Name (InAct):
Location Addr (InAct):
Loc Addr2(InAct):
City (InAct):
State (InAct):
Zip Code (InAct):
County (InAct):
East Coord (InAct):
North Coord (InAct):
Facility Name: Sims Metal Management LLC
Location Addr: 30-27 Greenpoint Avenue
Location Addr2:
City: Long Island City
State: NY
Zip Code: 11101
County: Queens
East Coord: 589598
North Coord: 4509798
Data Source: SWMF - Active Facility Lists; SWMF - Active Solid Waste Management Facilities as of 08-17-2023

SWMF - Active Facility Lists Details(Act)

Accuracy Code: 4.3 - Utilization of Digital Orthophoto Quads
Activity Desc: RHRF - registration
Regulatory Status: Registration
Active: Yes
Dt of Last Inspection: 10/7/2016
Expiration Dt:
Owner Type: Private
Owner Name: Sims Metal Management East
Owner Address: One Linden Ave East
Owner Address2:
Owner City: Jersey City
Owner State: NJ
Owner Zip: 7305
Owner Phone: 2013334300
Owner Email:
Authorization No: 41MA6
Authrzation Issue Dt:
Operator Type: Private
Operator Name: Sims Municipal Recycling
Phone No: 7187866031
Region: 2
Contact Name: Jack Bernardino
Contact Address:
Contact Address2:
Contact City:
Contact State:
Contact Zip:
Contact Phone: 2014485458
Contact Email: jack.bernardino@simsmm.com
Waste Types: Metals (Aluminum);Metals (Ferrous);Metals (Non-Ferrous);Commingled Paper;Source Separated Recyclables (Metal/Glass/Paper/Plastic)

Active Solid Waste Management Facilities Details as of 08-17-2023

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Accuracy Code: 4.3 - Utilization of Digital Orthophoto Quads
Activity Desc: RHRF - registration
Active: Yes
Expiration Dt:
Geo Reference: 30-27 Greenpoint Avenue
Long Island City, NY 11101
(40.737288404, -73.943055428)
Region: 2
Waste Types: Metals (Aluminum);Metals (Ferrous);Metals (Non-Ferrous);Commingled Paper;Source Separated Recyclables (Metal/Glass/Paper/Plastic)

Authorization No: 41MA6
Authrzation Issue Dt:
Owner Type: Private
Owner Name: Sims Metal Management East
Phone No: 7187866031

---

193 | **3 of4** | **ENE** | **0.42 / 2,233.84** | **2.05 / -10** | **Sims Metal Management LLC**
30-27 Greenpoint Avenue
Long Island City NY 11101 | **RECYCLING**

East Coordinate: 589598
North Coordinate: 4509798

County: Queens
Location Address2:

Details

Activity No: [41MA6]
Active: Yes
Activity Desc: RHRF - registration
Region: 2
Phone No: 7187866031
Accuracy Code: 4.3 - Utilization of Digital Orthophoto Quads
Waste Types: Metals (Aluminum);Metals (Ferrous);Metals (Non-Ferrous);Commingled Paper;Source Separated Recyclables (Metal/Glass/Paper/Plastic)
Georeference: 30-27 Greenpoint Avenue
Long Island City, NY 11101
(40.737288404, -73.943055428)

Authorization No: 41MA6
Auth Issue Date:
Expiration DT:
Owner Type: Private
Owner Name: Sims Metal Management East

---

193 | **4 of4** | **ENE** | **0.42 / 2,233.84** | **2.05 / -10** | **Sims Metal Management LLC**
30-27 Greenpoint Avenue
Long Island City NY 11101 | **SWF/LF**

Activity Number: [41V30106]
Facility Name (Act):
Location Addr (Act):
Location Addr2 (Act):
City (Act):
State (Act):
Zip Code (Act):
County (Act):
East Coord (Act):
North Coord (Act):
Facility Name: Sims Metal Management LLC
Location Addr: 30-27 Greenpoint Avenue
Location Addr2:
City: Long Island City
State: NY
Zip Code: 11101
County: Queens
East Coord: 589598
North Coord: 4509798
Data Source: SWMF - Active Solid Waste Management Facilities as of 08-17-2023

Facility Name (InAct):
Location Addr (InAct):
Loc Addr2(InAct):
City (InAct):
State (InAct):
Zip Code (InAct):
County (InAct):
East Coord (InAct):
North Coord (InAct):

Active Solid Waste Management Facilities Details as of 08-17-2023

Accuracy Code: 1 - No accuracy stated
Activity Desc: Scrap metal processor - registration
Active: Yes
Expiration Dt: 03/16/2028
Geo Reference: 30-27 Greenpoint Avenue
Long Island City, NY 11101

Authorization No: 41V3106
Authrzation Issue Dt: 03/17/2023
Owner Type: Private
Owner Name: Sims Metal Management East
Phone No: 7187866031

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

(40.737288404, -73.943055428)
Region: 2
Waste Types: Decommissioned ELVs (Section 2A smp);Scrap Metal - Ferrous ;Scrap Metal - Non-ferrous

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
194	1 of1	SE	0.43 / 2,247.21	11.84 / 0	37-41 MOULTRIE ST 37-41 MOULTRIE ST BROOKLYN NY	LST

Spill No: 0308536
Site ID: 322770
DER Facility ID: 260013
CID: 205
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Test Failure
Water Body:
Class: C4
Meets Std: False
Penalty: False
County: Kings
Referred to:
Reported by: Responsible Party
Source: Private Dwelling
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: False
Spill Date: 11/12/2003 01:00:00 PM
Rcvd Date: 11/12/2003 01:32:00 PM
CAC Date:
Insp Date:
Close Date: 05/06/2005 12:00:00 AM
Create Date: 11/12/2003 12:00:00 AM
Update Date: 05/06/2005 03:40:41 PM
DEC Region: 2
Lead DEC: SMSANGES
After Hours: False

Caller Remark:

""

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND sent TTF letter 11/17/2003 retest passed, consultant will send in paperwork soon"

Material Information

OP Unit ID: 874781
OU: 01
Material ID: 502025
CAS No:
Material Family: Petroleum
Quantity: .00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0001A
Material Name: #2 fuel oil

Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: MR LIN
Spiller Company: LIN RES.
Spiller Address: 37-41 MOULTRIE ST
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: CALLER
Contact Phone:
Contact Ext:
Latitude: 40.728144400
Longitude: -73.946414250

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tank Test Information

Spill Tank ID:	1528803	***Source:***	
Tank No:	1	***Leak Rate:***	.00
Tank SIze:	5000	***Gross Fail:***	
Material:	0001	***Modified by:***	Spills
EPA UST:		***Last Modified:***	2004-10-01 04:00:45.140000000
UST:		***Test Method:***	03
Cause:			
Alt Test Method:	Horner EZ Check I or II		

195	*1 of3*	*NNE*	*0.43 / 2,281.90*	*5.16 / -7*	***23-30 Borden Avenue Development*** ***23-30 BORDEN AVENUE*** ***Long Island City NY 11101***	***BROWNFIELDS***

Site Code:	591540
HW Code:	C241238
Program:	BCP
Site Class:	A
Site Name:	23-30 Borden Avenue Development
Site Address:	23-30 BORDEN AVENUE
City:	Long Island City
Zip:	11101
County:	Queens
Region:	2
Town:	New York City
Latitude:	40.739380556
Longitude:	-73.947402778
SWIS:	4101
Acres:	4.670
Record Added:	2019-07-09 08:18:00
Record Update:	2023-04-18 08:28:00
Updated by:	WBBENNET
Site Code (Web):	C241238
Program Type (Web):	BCP
Site Name (Web):	23-30 Borden Avenue Development
Site Class (Web):	A
Address1 (Web):	23-30 BORDEN AVENUE
Address2 (Web):	
Locality (Web):	Long Island City
Zip Code (Web):	11101
County (Web):	Queens
Longitude (Web):	-73.947402778
Latitude (Web):	40.739380556
Site Code (GIS):	C241238
Site Name (GIS):	23-30 Borden Avenue Development
Program (GIS):	BCP
Site Class (GIS):	A
Address1 (GIS):	23-30 BORDEN AVENUE
Address2 (GIS):	
Locality (GIS):	Long Island City
Zip Code (GIS):	11101
County (GIS):	Queens
Site Class Desc:	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Site Class Desc (Web):	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Assess DOH:	Access is restricted by a fence. People who enter the site may come into contact with site-related soil and groundwater contamination if they dig below the surface. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into structures and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of structures, is referred to as soil vapor intrusion. Because there is no on-site structure, inhalation of site contaminants in indoor air

due to soil vapor intrusion does not represent a concern for the site in its current condition. Environmental sampling indicates that soil vapor intrusion may present a concern for off-site structures.

Description:

Location: The site is located at 23-30 Borden Avenue in Long Island City, Queens, NY, and is identified as Block 68 and Lot 38 on the New York City Tax Map. Site Features: The site consists of approximately 4.67 acres. The site previously contained a two-story warehouse building with one mezzanine level, and an asphalt paved parking lot, located between Borden Avenue and the central setback portion of the site building. The building was demolished between 2020 and 2021. Since that time, the site has remained vacant. The proposed site redevelopment will include six-story building with loading docks, structured parking landing and storage. The Site is currently an active construction site and there are no site occupants. Current Zoning and Land Use: The site is located in a M3-2 manufacturing district. The site is within the Long Island City Industrial Business Zone. The property is designated for warehouse use (E1). The adjoining parcels and surrounding area are used for industrial, public facilities and institutions, and transportation utility facilities. Past Use of the Site: Historical operations at the site include an LIRR switch yard between the years 1898 and 1950. Additionally, coal gas associated structures, including a gasometer, a purifier house and gas holders, were identified on the northern portion of the site between the years 1898 and 1928. The site has been used for warehouse purposes since 1970. Site Geology and Hydrogeology: The subsurface strata beneath the site consists of historic fill generally consisting of fine to coarse sand with varying amounts of gravel, silt, clay, brick, concrete, asphalt, wood fragments, and miscellaneous debris to depths that ranged from depths of approximately 5.5 to 16-feet below ground surface (bgs). The fill layer is underlain by either a native sand or clay layer. The clay layer was observed to continue to 34-feet bgs in some borings. In borings where sand was encountered beneath the fill material, it was observed to continue to the soil boring termination depth. Bedrock was encountered at depths that ranged from 30 to 34-feet bgs. Groundwater was encountered at depths ranging from about 6.5 to 10.5-feet bgs. Based on the proximity of the site to the Newtown Creek, groundwater is inferred to flow to the south-southwest towards Newtown Creek.

Assessment:

Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), pesticides, and per- and polyfluoroalkyl substances (PFAS). Soil vapor was analyzed for VOCs. The primary contaminants of concern at the site include metals, SVOCs and VOCs in the soil, groundwater and/or soil vapor. Soil: Data results from soils sampling reported several metals, petroleum VOCs, and SVOCs (primarily polycyclic aromatic hydrocarbon, or PAHs). The PAHs and most metals contamination in soils are likely related to the presence of historic fill or historical operations at the site. Petroleum-related VOCs impacts are attributed to historical operations at the site. Maximum detections in comparison to applicable protection of groundwater or commercial use soil cleanup objectives (PGSCO/CSCO) are as follows: lead at 3,810 parts per million (ppm) compared to the PGSCO of 450 ppm and the CSCO of 1,000 ppm, benzo(a) anthracene at 171 ppm (PGSCO of 1.0 ppm, CSCO of 5.6 ppm), benzo(a)pyrene at 226 ppm (PGSCO of 22 ppm, CSCO of 1 ppm), benzo(b) fluoranthene at 66.5 ppm (PGSCO of 1.7 ppm, CSCO of 5.6 ppm), benzo(k)fluoranthene at 82.8 ppm (PGSCO of 1.7 ppm, CSCO of 56 ppm), chrysene at 152 ppm (PGSCO of 1.0 ppm, CSCO of 56 ppm), 1,2,4-trimethylbenzene at 170 ppm (PGSCO of 3.6 ppm, CSCO of 190 ppm), benzene at 11 ppm (PGSCO of 0.06 ppm, CSCO of 44 ppm), ethylbenzene at 1,300 ppm (PGSCO of 1.0 ppm, CSCO of 390 ppm), o-xylene at 210 ppm (PGSCO of 1.6 ppm, CSCO of 500 ppm), and toluene at 10 ppm (PGSCO of 0.7 ppm, CSCO of 500 ppm). PFAS were detected in one of thirty-five soil samples analyzed for the compounds, with perfluorooctane sulfonic acid (PFOS) detected at 6.6 parts per billion (ppb), which is below the commercial use guidance value of 440 ppb and above the protection of groundwater guidance value of 3.7 ppb. Data does not indicate any off-site impacts in soil related to this site. Groundwater: Groundwater sampling found metals, VOCs, SVOCs (PAHs) contamination above Class GA Ambient Water Quality Standards (AWQS). Some metals were found at relatively low levels in groundwater and are likely related to the presence of historic fill. Maximum detections are as follows: 1,1,1-trichloroethane 82.7 ppb (AWQS is 5 ppb), tetrachloroethene (PCE) at 12.3 ppb (AWQS is 5 ppb), trichloroethene (TCE) at 13.9 ppb (AWQS is 5 ppb), vinyl chloride at 524 ppb (AWQS is 2 ppb), cis-1,2-dichloroethylene at 318 ppb (AWQS is 5 ppb), 1,2,4-trimethylbenzene at 95.8 ppb (AWQS is 5 ppb), benzene at 308 ppb (AWQS is 1 ppb), ethylbenzene at 1,370 ppb (AWQS is 5 ppb), o-xylene at 254 ppb (AWQS is 5 ppb), and toluene at 17 ppb (AWQS is 5 ppb). PFOS and perfluorooctanoic acid (PFOA) were reported at concentrations of up to 313 and 552 parts per trillion (ppt), respectively, exceeding the Maximum Contaminant Level (drinking water standard, or MCL) of 10 ppt for each. 1,4-dioxane was reported at concentrations up to 6.2 ppb (MCL of 1 ppb). Based on the soil data, there is no apparent on-site source for 1,4-Dioxane in site groundwater. Petroleum impacts including observations of non-aqueous phase liquids (NAPL) were predominantly encountered in native material in the northwestern portion of the site and the southern central portion of the site. Additional sampling is needed to determine is there any off-site impacts in groundwater-related to this site. Soil Vapor: VOCs were detected in soil vapor during the remedial investigation. The maximum concentrations of 1,1,1-trichloroethane, tetrachloroethene, trichloroethene and carbon tetrachloride in soil vapor were detected primarily in the south-central portion of the site at the respective concentrations of 8,500 micrograms per cubic meter (ug/m3), 4,800 ug/m3, 1,200 ug/m3 and 60 ug/m3. Data indicated there is potential for off-site migration of VOCs in soil vapor. Additional sampling is needed to determine whether actions are needed to address soil vapor intrusion off-site.

Materials Information

Waste Name: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: lead
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: petroleum products
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: vinyl chloride
Waste Quantity: UNKNOWN

Waste Code:

Waste Name: nickel
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,1,1-Trichloroethane(TCA)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: zinc
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 01
Sub Type: E
Owner Name: Anderw Chung
Owner Company: 23-30 Borden Owner LLC
Owner Street: 1350 Avenue of the Americas, 17th Floor
Owner Street 2: c/o Innovo Property Group
Owner City: New York
Owner State: NY
Owner Zip: 10019
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name: Denise Keehan-Smith
Owner Company: Queens Community Board 2
Owner Street: 43-22 50th Street, Room 2B
Owner Street 2:
Owner City: Queens
Owner State: NY
Owner Zip: 11377
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Andrew Chung
Owner Company: 23-30 Borden Owner LLC
Owner Street: 1350 Avenue of the Americas, 17th Floor
Owner Street 2: c/o Innovo Property Group
Owner City: New York
Owner State: NY
Owner Zip: 10019
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Queens Library at Court Square
Owner Street: 25-01 Jackson Avenue
Owner Street 2:
Owner City: Queens
Owner State: NY
Owner Zip: 11101
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: JXPEREZM
Record Added: 2019-09-23 09:39:00
Record Updated: 2022-05-17 13:37:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Projects Information

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2020-04-06 00:00:00
End Status: ACT
Operable Unit ID: 1348358
Operable Unit: 01A
Operable Unit Desc: Slab & Foundation Removal, and Surface Stabilization
Code Name: Remedial Design

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2021-11-09 00:00:00
End Status: ACT
Operable Unit ID: 1339156
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Design

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2021-11-09 00:00:00
End Status: ACT
Operable Unit ID: 1339156
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Environmental Remediation

Operable Unit: 00
Contaminants: 1,1,1-Trichloroethane(TCA), 1,2,4-trimethylbenzene, benzene, toluene, ethylbenzene and xylenes (BTEX), cis-1,2-dichloroethene, lead, nickel, petroleum products, polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride, zinc

Operable Unit: 01
Contaminants: 1,1,1-Trichloroethane(TCA), 1,2,4-trimethylbenzene, benzene, toluene, ethylbenzene and xylenes (BTEX), cis-1,2-dichloroethene, lead, nickel, petroleum products, polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride, zinc

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Operable Unit: 01A
Contaminants: 1,1,1-Trichloroethane(TCA), 1,2,4-trimethylbenzene, benzene, toluene, ethylbenzene and xylenes (BTEX), cis-1,2-dichloroethene, lead, nickel, petroleum products, polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride, zinc

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
195	2 of3	NNE	0.43 / 2,281.90	5.16 / -7	23-30 Borden Avenue Development 23-30 BORDEN AVENUE Long Island City NY 11101	ENG

Site Code: 591540
HW Code: C241238
Control Type: ENG
Program: BCP
Site Class: A
Site Name: 23-30 Borden Avenue Development
Site Address: 23-30 BORDEN AVENUE
City: Long Island City
Zip: 11101
County: Queens
Region: 2
Town: New York City
Latitude: 40.739380556
Longitude: -73.947402778
SWIS: 4101
Acres: 4.670
Record Added: 2019-07-09 08:18:00
Record Updated: 2023-04-18 08:28:00
Updated By: WBBENNET
Site Code (Web): C241238
Program Type (Web): BCP
Site Class (Web): A
Site Name (Web): 23-30 Borden Avenue Development
Address1 (Web): 23-30 BORDEN AVENUE
Address2 (Web):
Locality (Web): Long Island City
Zip Code (Web): 11101
County (Web): Queens
Longitude (Web): -73.947402778
Latitude (Web): 40.739380556
Site Code (GIS): C241238
Program (GIS): BCP
Site Class (GIS): A
Site Name (GIS): 23-30 Borden Avenue Development
Address 1 (GIS): 23-30 BORDEN AVENUE
Address 2 (GIS):
Locality (GIS): Long Island City
Zip Code (GIS): 11101
County (GIS): Queens
Latitude (GIS):
Longitude (GIS):
Site Class Desc: Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Site Class Desc (Web): Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Assess DOH: Access is restricted by a fence. People who enter the site may come into contact with site-related soil and groundwater contamination if they dig below the surface. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into structures and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of structures, is referred to as soil vapor intrusion. Because there is no on-site structure, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. Environmental sampling indicates that soil vapor intrusion may present a concern for off-site structures.
Description:

Location: The site is located at 23-30 Borden Avenue in Long Island City, Queens, NY, and is identified as Block 68 and Lot 38 on the New York City Tax Map. Site Features: The site consists of approximately 4.67 acres. The site previously contained a two-story warehouse building with one mezzanine level, and an asphalt paved parking lot, located between Borden Avenue and the central setback portion of the site building. The building was demolished between 2020 and 2021. Since that time, the site has remained vacant. The proposed site redevelopment will include six-story building with loading docks, structured parking landing and storage. The Site is currently an active construction site and there are no site occupants. Current Zoning and Land Use: The site is located in a M3-2 manufacturing district. The site is within the Long Island City Industrial Business Zone. The property is designated for warehouse use (E1). The adjoining parcels and surrounding area are used for industrial, public facilities and institutions, and transportation utility facilities. Past Use of the Site: Historical operations at the site include an LIRR switch yard between the years 1898 and 1950. Additionally, coal gas associated structures, including a gasometer, a purifier house and gas holders, were identified on the northern portion of the site between the years 1898 and 1928. The site has been used for warehouse purposes since 1970. Site Geology and Hydrogeology: The subsurface strata beneath the site consists of historic fill generally consisting of fine to coarse sand with varying amounts of gravel, silt, clay, brick, concrete, asphalt, wood fragments, and miscellaneous debris to depths that ranged from depths of approximately 5.5 to 16-feet below ground surface (bgs). The fill layer is underlain by either a native sand or clay layer. The clay layer was observed to continue to 34-feet bgs in some borings. In borings where sand was encountered beneath the fill material, it was observed to continue to the soil boring termination depth. Bedrock was encountered at depths that ranged from 30 to 34-feet bgs. Groundwater was encountered at depths ranging from about 6.5 to 10.5-feet bgs. Based on the proximity of the site to the Newtown Creek, groundwater is inferred to flow to the south-southwest towards Newtown Creek.

Assessment:

Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), pesticides, and per- and polyfluoroalkyl substances (PFAS). Soil vapor was analyzed for VOCs. The primary contaminants of concern at the site include metals, SVOCs and VOCs in the soil, groundwater and/or soil vapor. Soil: Data results from soils sampling reported several metals, petroleum VOCs, and SVOCs (primarily polycyclic aromatic hydrocarbon, or PAHs). The PAHs and most metals contamination in soils are likely related to the presence of historic fill or historical operations at the site. Petroleum-related VOCs impacts are attributed to historical operations at the site. Maximum detections in comparison to applicable protection of groundwater or commercial use soil cleanup objectives (PGSCO/CSCO) are as follows: lead at 3,810 parts per million (ppm) compared to the PGSCO of 450 ppm and the CSCO of 1,000 ppm, benzo(a) anthracene at 171 ppm (PGSCO of 1.0 ppm, CSCO of 5.6 ppm), benzo(a)pyrene at 226 ppm (PGSCO of 22 ppm, CSCO of 1 ppm), benzo(b) fluoranthene at 66.5 ppm (PGSCO of 1.7 ppm, CSCO of 5.6 ppm), benzo(k)fluoranthene at 82.8 ppm (PGSCO of 1.7 ppm, CSCO of 56 ppm), chrysene at 152 ppm (PGSCO of 1.0 ppm, CSCO of 56 ppm), 1,2,4-trimethylbenzene at 170 ppm (PGSCO of 3.6 ppm, CSCO of 190 ppm), benzene at 11 ppm (PGSCO of 0.06 ppm, CSCO of 44 ppm), ethylbenzene at 1,300 ppm (PGSCO of 1.0 ppm, CSCO of 390 ppm), o-xylene at 210 ppm (PGSCO of 1.6 ppm, CSCO of 500 ppm), and toluene at 10 ppm (PGSCO of 0.7 ppm, CSCO of 500 ppm). PFAS were detected in one of thirty-five soil samples analyzed for the compounds, with perfluorooctane sulfonic acid (PFOS) detected at 6.6 parts per billion (ppb), which is below the commercial use guidance value of 440 ppb and above the protection of groundwater guidance value of 3.7 ppb. Data does not indicate any off-site impacts in soil related to this site. Groundwater: Groundwater sampling found metals, VOCs, SVOCs (PAHs) contamination above Class GA Ambient Water Quality Standards (AWQS). Some metals were found at relatively low levels in groundwater and are likely related to the presence of historic fill. Maximum detections are as follows: 1,1,1-trichloroethane 82.7 ppb (AWQS is 5 ppb), tetrachloroethene (PCE) at 12.3 ppb (AWQS is 5 ppb), trichloroethene (TCE) at 13.9 ppb (AWQS is 5 ppb), vinyl chloride at 524 ppb (AWQS is 2 ppb), cis-1,2-dichloroethylene at 318 ppb (AWQS is 5 ppb), 1,2,4-trimethylbenzene at 95.8 ppb (AWQS is 5 ppb), benzene at 308 ppb (AWQS is 1 ppb), ethylbenzene at 1,370 ppb (AWQS is 5 ppb), o-xylene at 254 ppb (AWQS is 5 ppb), and toluene at 17 ppb (AWQS is 5 ppb). PFOS and perfluorooctanoic acid (PFOA) were reported at concentrations of up to 313 and 552 parts per trillion (ppt), respectively, exceeding the Maximum Contaminant Level (drinking water standard, or MCL) of 10 ppt for each. 1,4-dioxane was reported at concentrations up to 6.2 ppb (MCL of 1 ppb). Based on the soil data, there is no apparent on-site source for 1,4-Dioxane in site groundwater. Petroleum impacts including observations of non-aqueous phase liquids (NAPL) were predominantly encountered in native material in the northwestern portion of the site and the southern central portion of the site. Additional sampling is needed to determine is there any off-site impacts in groundwater-related to this site. Soil Vapor: VOCs were detected in soil vapor during the remedial investigation. The maximum concentrations of 1,1,1-trichloroethane, tetrachloroethene, trichloroethene and carbon tetrachloride in soil vapor were detected primarily in the south-central portion of the site at the respective concentrations of 8,500 micrograms per cubic meter (ug/m3), 4,800 ug/m3, 1,200 ug/m3 and 60 ug/m3. Data indicated there is potential for off-site migration of VOCs in soil vapor. Additional sampling is needed to determine whether actions are needed to address soil vapor intrusion off-site.

Controls Information

Control Code:	15	***Record Added Date:***	2024-09-26 11:25:02.143000000
Control Name:	Cover System	***Record Updated Dt:***	2024-09-26 11:25:02.177000000
Control Type:	ENG	***In Place Date:***	2024-08-12 00:00:00
Updated By:	JXPEREZM		

Control Code:	36	***Record Added Date:***	2024-09-26 11:25:02.143000000
Control Name:	Monitoring Wells	***Record Updated Dt:***	2024-09-26 11:25:02.177000000
Control Type:	ENG	***In Place Date:***	2024-08-12 00:00:00
Updated By:	JXPEREZM		

Materials Information

Waste Name:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name:	benzene, toluene, ethylbenzene and xylenes (BTEX)

Waste Quantity: UNKNOWN
Waste Code:

Waste Name: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: lead
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,1,1-Trichloroethane(TCA)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: petroleum products
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: nickel
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: zinc
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 19
Sub Type: NNN
Owner Name: Denise Keehan-Smith
Owner Company: Queens Community Board 2
Owner Street: 43-22 50th Street, Room 2B
Owner Street 2:
Owner City: Queens
Owner State: NY
Owner Zip: 11377
Country: United States of America

Owner Op: 01
Sub Type: E
Owner Name: Anderw Chung
Owner Company: 23-30 Borden Owner LLC
Owner Street: 1350 Avenue of the Americas, 17th Floor
Owner Street 2: c/o Innovo Property Group
Owner City: New York
Owner State: NY
Owner Zip: 10019
Country: United States of America

Owner Op: 19

Sub Type: NNN
Owner Name:
Owner Company: Queens Library at Court Square
Owner Street: 25-01 Jackson Avenue
Owner Street 2:
Owner City: Queens
Owner State: NY
Owner Zip: 11101
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Andrew Chung
Owner Company: 23-30 Borden Owner LLC
Owner Street: 1350 Avenue of the Americas, 17th Floor
Owner Street 2: c/o Innovo Property Group
Owner City: New York
Owner State: NY
Owner Zip: 10019
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disposal Start:
Disposal Terminate:
Dell:
Updated By: JXPEREZM
Record Added: 2019-09-23 09:39:00
Record Updated: 2022-05-17 13:37:00
Latitude:
Longitude:

Projects Information

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2021-11-09 00:00:00
End Status: ACT
Operable Unit ID: 1339156
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Design

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2021-11-09 00:00:00
End Status: ACT
Operable Unit ID: 1339156
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2020-04-06 00:00:00
End Status: ACT
Operable Unit ID: 1348358
Operable Unit: 01A
Operable Unit Desc: Slab & Foundation Removal, and Surface Stabilization
Code Name: Remedial Design

Environmental Remediation

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Operable Unit: 00
Contaminants: 1,1,1-Trichloroethane(TCA), 1,2,4-trimethylbenzene, benzene, toluene, ethylbenzene and xylenes (BTEX), cis-1,2-dichloroethene, lead, nickel, petroleum products, polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride, zinc

Operable Unit: 01A
Contaminants: 1,1,1-Trichloroethane(TCA), 1,2,4-trimethylbenzene, benzene, toluene, ethylbenzene and xylenes (BTEX), cis-1,2-dichloroethene, lead, nickel, petroleum products, polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride, zinc

Operable Unit: 01
Contaminants: 1,1,1-Trichloroethane(TCA), 1,2,4-trimethylbenzene, benzene, toluene, ethylbenzene and xylenes (BTEX), cis-1,2-dichloroethene, lead, nickel, petroleum products, polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride, zinc

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
195	3 of3	NNE	0.43 / 2,281.90	5.16 / -7	23-30 Borden Avenue Development 23-30 BORDEN AVENUE Long Island City NY 11101	INST

Site Code: 591540
HW Code: C241238
Control Type: INST
Program: BCP
Site Class: A
Site Name: 23-30 Borden Avenue Development
Site Address: 23-30 BORDEN AVENUE
City: Long Island City
Zip: 11101
County: Queens
Region: 2
Town: New York City
Latitude: 40.739380556
Longitude: -73.947402778
SWIS: 4101
Acres: 4.670
Record Added: 2019-07-09 08:18:00
Record Updated: 2023-04-18 08:28:00
Updated By: WBBENNET
Site Code (Web): C241238
Program Type (Web): BCP
Site Class (Web): A
Site Name (Web): 23-30 Borden Avenue Development
Address1 (Web): 23-30 BORDEN AVENUE
Address2 (Web):
Locality (Web): Long Island City
Zip Code (Web): 11101
County (Web): Queens
Longitude (Web): -73.947402778
Latitude (Web): 40.739380556
Site Code (GIS): C241238
Program (GIS): BCP
Site Class (GIS): A
Site Name (GIS): 23-30 Borden Avenue Development
Address 1 (GIS): 23-30 BORDEN AVENUE
Address 2 (GIS):
Locality (GIS): Long Island City
Zip Code (GIS): 11101
County (GIS): Queens
Latitude (GIS):
Longitude (GIS):
Site Class Desc: Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Site Class Desc (Web): Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.

Assess DOH: Access is restricted by a fence. People who enter the site may come into contact with site-related soil and groundwater contamination if they dig below the surface. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into structures and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of structures, is referred to as soil vapor intrusion. Because there is no on-site structure, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. Environmental sampling indicates that soil vapor intrusion may present a concern for off-site structures.

Description:

Location: The site is located at 23-30 Borden Avenue in Long Island City, Queens, NY, and is identified as Block 68 and Lot 38 on the New York City Tax Map. Site Features: The site consists of approximately 4.67 acres. The site previously contained a two-story warehouse building with one mezzanine level, and an asphalt paved parking lot, located between Borden Avenue and the central setback portion of the site building. The building was demolished between 2020 and 2021. Since that time, the site has remained vacant. The proposed site redevelopment will include six-story building with loading docks, structured parking landing and storage. The Site is currently an active construction site and there are no site occupants. Current Zoning and Land Use: The site is located in a M3-2 manufacturing district. The site is within the Long Island City Industrial Business Zone. The property is designated for warehouse use (E1). The adjoining parcels and surrounding area are used for industrial, public facilities and institutions, and transportation utility facilities. Past Use of the Site: Historical operations at the site include an LIRR switch yard between the years 1898 and 1950. Additionally, coal gas associated structures, including a gasometer, a purifier house and gas holders, were identified on the northern portion of the site between the years 1898 and 1928. The site has been used for warehouse purposes since 1970. Site Geology and Hydrogeology: The subsurface strata beneath the site consists of historic fill generally consisting of fine to coarse sand with varying amounts of gravel, silt, clay, brick, concrete, asphalt, wood fragments, and miscellaneous debris to depths that ranged from depths of approximately 5.5 to 16-feet below ground surface (bgs). The fill layer is underlain by either a native sand or clay layer. The clay layer was observed to continue to 34-feet bgs in some borings. In borings where sand was encountered beneath the fill material, it was observed to continue to the soil boring termination depth. Bedrock was encountered at depths that ranged from 30 to 34-feet bgs. Groundwater was encountered at depths ranging from about 6.5 to 10.5-feet bgs. Based on the proximity of the site to the Newtown Creek, groundwater is inferred to flow to the south-southwest towards Newtown Creek.

Assessment:

Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), pesticides, and per- and polyfluoroalkyl substances (PFAS). Soil vapor was analyzed for VOCs. The primary contaminants of concern at the site include metals, SVOCs and VOCs in the soil, groundwater and/or soil vapor. Soil: Data results from soils sampling reported several metals, petroleum VOCs, and SVOCs (primarily polycyclic aromatic hydrocarbon, or PAHs). The PAHs and most metals contamination in soils are likely related to the presence of historic fill or historical operations at the site. Petroleum-related VOCs impacts are attributed to historical operations at the site. Maximum detections in comparison to applicable protection of groundwater or commercial use soil cleanup objectives (PGSCO/CSCO) are as follows: lead at 3,810 parts per million (ppm) compared to the PGSCO of 450 ppm and the CSCO of 1,000 ppm, benzo(a) anthracene at 171 ppm (PGSCO of 1.0 ppm, CSCO of 5.6 ppm), benzo(a)pyrene at 226 ppm (PGSCO of 22 ppm, CSCO of 1 ppm), benzo(b) fluoranthene at 66.5 ppm (PGSCO of 1.7 ppm, CSCO of 5.6 ppm), benzo(k)fluoranthene at 82.8 ppm (PGSCO of 1.7 ppm, CSCO of 56 ppm), chrysene at 152 ppm (PGSCO of 1.0 ppm, CSCO of 56 ppm), 1,2,4-trimethylbenzene at 170 ppm (PGSCO of 3.6 ppm, CSCO of 190 ppm), benzene at 11 ppm (PGSCO of 0.06 ppm, CSCO of 44 ppm), ethylbenzene at 1,300 ppm (PGSCO of 1.0 ppm, CSCO of 390 ppm), o-xylene at 210 ppm (PGSCO of 1.6 ppm, CSCO of 500 ppm), and toluene at 10 ppm (PGSCO of 0.7 ppm, CSCO of 500 ppm). PFAS were detected in one of thirty-five soil samples analyzed for the compounds, with perfluorooctane sulfonic acid (PFOS) detected at 6.6 parts per billion (ppb), which is below the commercial use guidance value of 440 ppb and above the protection of groundwater guidance value of 3.7 ppb. Data does not indicate any off-site impacts in soil related to this site. Groundwater: Groundwater sampling found metals, VOCs, SVOCs (PAHs) contamination above Class GA Ambient Water Quality Standards (AWQS). Some metals were found at relatively low levels in groundwater and are likely related to the presence of historic fill. Maximum detections are as follows: 1,1,1-trichloroethane 82.7 ppb (AWQS is 5 ppb), tetrachloroethene (PCE) at 12.3 ppb (AWQS is 5 ppb), trichloroethene (TCE) at 13.9 ppb (AWQS is 5 ppb), vinyl chloride at 524 ppb (AWQS is 2 ppb), cis-1,2-dichloroethylene at 318 ppb (AWQS is 5 ppb), 1,2,4-trimethylbenzene at 95.8 ppb (AWQS is 5 ppb), benzene at 308 ppb (AWQS is 1 ppb), ethylbenzene at 1,370 ppb (AWQS is 5 ppb), o-xylene at 254 ppb (AWQS is 5 ppb), and toluene at 17 ppb (AWQS is 5 ppb). PFOS and perfluorooctanoic acid (PFOA) were reported at concentrations of up to 313 and 552 parts per trillion (ppt), respectively, exceeding the Maximum Contaminant Level (drinking water standard, or MCL) of 10 ppt for each. 1,4-dioxane was reported at concentrations up to 6.2 ppb (MCL of 1 ppb). Based on the soil data, there is no apparent on-site source for 1,4-Dioxane in site groundwater. Petroleum impacts including observations of non-aqueous phase liquids (NAPL) were predominantly encountered in native material in the northwestern portion of the site and the southern central portion of the site. Additional sampling is needed to determine is there any off-site impacts in groundwater-related to this site. Soil Vapor: VOCs were detected in soil vapor during the remedial investigation. The maximum concentrations of 1,1,1-trichloroethane, tetrachloroethene, trichloroethene and carbon tetrachloride in soil vapor were detected primarily in the south-central portion of the site at the respective concentrations of 8,500 micrograms per cubic meter (ug/m3), 4,800 ug/m3, 1,200 ug/m3 and 60 ug/m3. Data indicated there is potential for off-site migration of VOCs in soil vapor. Additional sampling is needed to determine whether actions are needed to address soil vapor intrusion off-site.

Controls Information

Control Code:	34	***Record Added Date:***	2024-09-26 11:25:02.143000000
Control Name:	IC/EC Plan	***Record Updated Dt:***	2024-09-26 11:25:02.177000000
Control Type:	INST	***In Place Date:***	2024-08-12 00:00:00
Updated By:	JXPEREZM		

Control Code:	J	***Record Added Date:***	2024-09-26 11:25:02.143000000
Control Name:	Environmental Easement	***Record Updated Dt:***	2024-09-26 11:25:02.177000000
Control Type:	INST	***In Place Date:***	2024-08-12 00:00:00
Updated By:	JXPEREZM		

Control Code:	14	**Record Added Date:**	2024-09-26 11:25:02.143000000
Control Name:	Soil Management Plan	**Record Updated Dt:**	2024-09-26 11:25:02.177000000
Control Type:	INST	**In Place Date:**	2024-08-12 00:00:00
Updated By:	JXPEREZM		

Control Code:	08	**Record Added Date:**	2024-09-26 11:25:02.143000000
Control Name:	Ground Water Use Restriction	**Record Updated Dt:**	2024-09-26 11:25:02.177000000
Control Type:	INST	**In Place Date:**	2024-08-12 00:00:00
Updated By:	JXPEREZM		

Control Code:	25	**Record Added Date:**	2024-09-26 11:25:02.143000000
Control Name:	Landuse Restriction	**Record Updated Dt:**	2024-09-26 11:25:02.177000000
Control Type:	INST	**In Place Date:**	2024-08-12 00:00:00
Updated By:	JXPEREZM		

Control Code:	31	**Record Added Date:**	2024-09-26 11:25:02.143000000
Control Name:	Monitoring Plan	**Record Updated Dt:**	2024-09-26 11:25:02.177000000
Control Type:	INST	**In Place Date:**	2024-08-12 00:00:00
Updated By:	JXPEREZM		

Control Code:	32	**Record Added Date:**	2024-09-26 11:25:02.143000000
Control Name:	Site Management Plan	**Record Updated Dt:**	2024-09-26 11:25:02.177000000
Control Type:	INST	**In Place Date:**	2024-08-12 00:00:00
Updated By:	JXPEREZM		

Materials Information

Waste Name:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name:	zinc
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name:	benzene, toluene, ethylbenzene and xylenes (BTEX)
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name:	1,1,1-Trichloroethane(TCA)
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name:	nickel
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name:	lead
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: petroleum products
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 01
Sub Type: E
Owner Name: Anderw Chung
Owner Company: 23-30 Borden Owner LLC
Owner Street: 1350 Avenue of the Americas, 17th Floor
Owner Street 2: c/o Innovo Property Group
Owner City: New York
Owner State: NY
Owner Zip: 10019
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Andrew Chung
Owner Company: 23-30 Borden Owner LLC
Owner Street: 1350 Avenue of the Americas, 17th Floor
Owner Street 2: c/o Innovo Property Group
Owner City: New York
Owner State: NY
Owner Zip: 10019
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name: Denise Keehan-Smith
Owner Company: Queens Community Board 2
Owner Street: 43-22 50th Street, Room 2B
Owner Street 2:
Owner City: Queens
Owner State: NY
Owner Zip: 11377
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Queens Library at Court Square
Owner Street: 25-01 Jackson Avenue
Owner Street 2:
Owner City: Queens
Owner State: NY
Owner Zip: 11101
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disposal Start:
Disposal Terminate:

Dell:
Updated By: JXPEREZM
Record Added: 2019-09-23 09:39:00
Record Updated: 2022-05-17 13:37:00
Latitude:
Longitude:

Projects Information

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2021-11-09 00:00:00
End Status: ACT
Operable Unit ID: 1339156
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Design

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2021-11-09 00:00:00
End Status: ACT
Operable Unit ID: 1339156
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2020-04-06 00:00:00
End Status: ACT
Operable Unit ID: 1348358
Operable Unit: 01A
Operable Unit Desc: Slab & Foundation Removal, and Surface Stabilization
Code Name: Remedial Design

Environmental Remediation

Operable Unit: 01
Contaminants: 1,1,1-Trichloroethane(TCA), 1,2,4-trimethylbenzene, benzene, toluene, ethylbenzene and xylenes (BTEX), cis-1,2-dichloroethene, lead, nickel, petroleum products, polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride, zinc

Operable Unit: 00
Contaminants: 1,1,1-Trichloroethane(TCA), 1,2,4-trimethylbenzene, benzene, toluene, ethylbenzene and xylenes (BTEX), cis-1,2-dichloroethene, lead, nickel, petroleum products, polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride, zinc

Operable Unit: 01A
Contaminants: 1,1,1-Trichloroethane(TCA), 1,2,4-trimethylbenzene, benzene, toluene, ethylbenzene and xylenes (BTEX), cis-1,2-dichloroethene, lead, nickel, petroleum products, polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride, zinc

196	1 of2	N	0.44 / 2,317.12	3.49 / -9	NYC WATER TREATMENT PLANT NEWTOWN CREEK BROOKLYN NY	LST

Spill No: 9904793
Site ID: 236837
DER Facility ID: 281121
CID: 390
Program Type: ER
SWIS Code: 4101
Contribute Factor: Tank Test Failure
Water Body:
Class: B3
Meets Std: False
Penalty: False
County: Queens
Referred to:
Reported by: Responsible Party
Source: Commercial/Industrial

REM Phase: 0
UST Trust: False
Spill Date: 07/22/1999 11:00:00 AM
Rcvd Date: 07/22/1999 11:17:00 AM
CAC Date:
Insp Date:
Close Date: 07/23/2003 12:00:00 AM
Create Date: 07/22/1999 12:00:00 AM
Update Date: 07/23/2003 12:00:00 AM
DEC Region: 2
Lead DEC: SMSANGES
After Hours: False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"tank failed - poss from vent pipe - tank had 2700 gals of oil in it"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND COPY TO DEC WATER."

Material Information

OP Unit ID:	1079236	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	560673	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	UNKNOWN
Spiller Company:	NYC WATER TREATMENT PLANT
Spiller Address:	NEWTOWN CREEK
Spiller City:	BROOKLYN
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	UNKNOWN
Contact Phone:	
Contact Ext:	
Latitude:	40.736309000
Longitude:	-73.942548000

Tank Test Information

Spill Tank ID:	1547398	**Source:**	
Tank No:	13	**Leak Rate:**	.00
Tank SIze:	4000	**Gross Fail:**	
Material:	0001	**Modified by:**	Spills
EPA UST:		**Last Modified:**	2004-10-01 04:00:45.140000000
UST:		**Test Method:**	03
Cause:			
Alt Test Method:	Horner EZ Check I or II		

196	***2 of2***	***N***	***0.44 / 2,317.12***	***3.49 / -9***	***NEWTOWN CREEK SOLVENT DRUM NEWTOWN CREEK QUEENS NY 11428***	***SEMS ARCHIVE***

Site ID:	0203745	**FIPS Code:**	36081
EPA ID:	NYD987015245	**Cong District:**	06
Superfund Alte Agr:	No	**Region:**	02
Federal Facility:	Yes	**County:**	QUEENS
FF Docket:	No		
NPL:	Not on the NPL		
Non NPL Status:	Removal Only Site (No Site Assessment Work Needed)		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Action Information

Operable Units:	00	***Qual:***	
Action Code:	VS	***SEQ:***	1
Action Name:	ARCH SITE	***FF:***	Yes
Start Actual:		***FF Docket:***	No
Finish Actual:	9/30/2001 4:00:00 AM	***Region:***	02
Curr Action Lead:	EPA Perf In-Hse		
NPL:			

Operable Units:	00	***Qual:***	C
Action Code:	RV	***SEQ:***	1
Action Name:	RMVL	***FF:***	Yes
Start Actual:	8/5/1992 4:00:00 AM	***FF Docket:***	No
Finish Actual:	9/28/1992 4:00:00 AM	***Region:***	02
Curr Action Lead:	USCG		
NPL:			

197	1 of1	W	0.44 / 2,326.89	8.84 / -3	***COURIER PACKAGING CO INC*** ***BROOKLYN NY***	***PFAS IND***

Status:	Active	***Fac Fips Code:***	36047
Fac Indian Cntry Flg:	No	***Compliance Status:***	No Violation Identified
Fac Derived Huc:	02030201	***EPA Programs:***	CAA
Fac Derived Wbd:	020301010405	***Federal Facility:***	No
Fac Derived Cd113:	12	***Federal Agency:***	-
Fac Derived Cb2010:	360470563001004	***Fac Snc Flg:***	No
Fac Informal Count:	0	***AIR Flag:***	Yes
Last Informal Action:	-	***NPDES Flag:***	No
Formal Action Count:	0	***SDWIS Flag:***	No
Last Formal Action:	-	***RCRAFlag:***	No
Fac Total Penalties:	0	***TRI Flag:***	No
Fac Penalty Count:	-	***GHG Flag:***	No
Date Last Penalty:	-	***TRI IDs:***	-
Last Penalty Amt:	-	***TRI Releases Trnsfrs:***	-
Fac Qtrs With Nc:	0	***TRI on Site Releases:***	-
Programs With Snc:	0	***TRI off Site Trnsfrs:***	-
Fac Percent Minority:	44.275	***TRI Reporter:***	-
Fac Pop Den:	47908.24	***Fac Imp Water Flg:***	-
Count:	1	***Fac Major Flag:***	-
Fac County:	KINGS	***Fac Active Flag:***	Yes
State Other :		***Fac Inspection Count:***	0
Region:	02	***Date Last Inspection:***	-
Latitude:	40.734038	***Days Last Inspection:***	-
Longitude:	-73.959942		

Fac Derived Tribes:	-
AIR IDs:	NY0000002610100033
CAA Permit Types:	Synthetic Minor Emissions
CAA NAICS:	326121
CAA SICS:	3082
NPDES IDs:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDs:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDs:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA Snc Flag:	No
Fac Collection Meth:	ADDRESS MATCHING-HOUSE NUMBER
EJSCREEN Flag Us:	Yes
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.959942,%22y%22:40.734038,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

ECHO Facility Report: https://echo.epa.gov/detailed-facility-report?fid=110064222700

Industry: Plastics and Resins

---

198 | **1 of1** | **E** | **0.45 / 2,368.87** | **5.66 / -6** | **United Metro Energy Corp**
500 Kingsland Ave
Brooklyn NY | **PFAS**

Facility ID: BSF0415 **County:** Kings
Survey Complete: YES
Survey: Class B Fire Suppression Foam Usage Survey - New York State Bulk Storage Facilities
Q. 6: YES
Q. 7: YES
Q. 8: YES
Q. 9: NO
Q. 10: NO
Q. 11: NO
Q. 12:
Q. 13:
Reference: If a respondent indicated that the facility used/stored/disposed PFOA/PFOS substances, it does not necessarily mean that there is an environmental/public health concern associated with that facility. Also, if a respondent indicated that they currently/formerly used, stored, disposed of, or released Class B firefighting foam it does not necessarily mean that the foam contains/contained PFOA/PFOS since many Class B foams do not contain these substances. DEC is in the process of reviewing/evaluating the returned surveys to determine if additional follow-up or study is needed.
Return rate: 91 surveys were sent to facilities; 90 were returned completed as of June 1, 2017.
Questions 1 & 2 relate to name and address; questions 3-5 relate to facility ownership.
Q. 6: Is any Class B fire suppression foam currently stored and/or used at the facility?
Q. 7: Has any Class B fire suppression foam ever been stored and/or used at the facility?
Q. 8: Has Class B fire suppression foam ever been used for training purposes at the facility?
Q. 9: Has Class B fire suppression foam ever been used for firefighting or other emergency response purposes at the facility?
Q. 10: Has the facility ever experienced a spill or leak of Class B fire suppression foam?
Q. 11: Has your facility ever been responsible for the use of Class B fire suppression foam at a location other than the facility (i.e. offsite training, emergency response, or spill)?

---

199 | **1 of2** | **E** | **0.45 / 2,389.83** | **6.24 / -6** | **Manhattan Adhesives**
425-459 Green Point Avenue
Brooklyn 11222
NY | **HSWDS**

Reg Site ID: 224009
Site No: HS2035
EPA ID: NYD980780811
Is Site Active?: No
Registry: D
Years of Operation: 1970 to 1972
RCRA: Unknown
HRS Score: 10.1
HRS Date: 05/26/83
Acres: 0.00
Site Code: 1
Site Code Desc: Industrial Site
Owner: P
Owner Name: Frank Castiglione
Owner Address: 32-02 College Pt. Blvd.
Flushing
Owner Telephone: (212)886-1117
Operator: P
Operator Name: U
Operator Address: U
Operator Telephone: U
Completed Investigation: Phase 1
Samples Collected: None
Threat to Env/Public Health?: E/P
Surface Water Contamination?: Unknown
Groundwater Contamination?: Unknown

VOCs: No
Semi VOCs: No
PCBs: Yes
Pesticides: Yes
Metals: No
Asbestos: No
County: Kings
Region: 2
Latitude: 40 43 56 N
Longitude: 73 56 42 W
Quadrangle: Brooklyn

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Drinking Water Contam?:	Unknown
Surface Water Class:	U
Groundwater Class:	U
Active Drinking Water Supply?:	Unknown
Hazard Substance Exposed?:	Unknown
Controlled Site Access?:	Unknown
Ambient Air Contamination?:	U
Threat of Direct Contact?:	Unknown
Doc Fish/Wildlife Mortality?:	Unknown
Impact on Special Status?:	Unknown
TCLP:	
Surface Water:	nearest surface water: 400 ft, northwest
Groundwater:	
Drinking Water:	
Fish or Wildlife Mortality:	
Fish or Wildlife Resource:	
Building:	
Hazard Substance Disposed:	Aroclor 1221, Aroclor 1221B, Aroclor 5460, PCB/PCT mixture
Air:	
Surface Water:	
Surface Soil:	
Waste:	
EP Toxicity:	
Groundwater:	
Sediment:	
Subsurface Soil:	
Leachate:	
Regulatory Agencies Involved:	
Preparer:	Julia Slack(pb) Env. Engineering Tech June 14, 1994
Nominated by:	
Describe the Site:	Records obtained from Mansanto Indusrtial Chemical Co. (of St. Louis Missouri) indicate that from 1970 to 1972, Manhattan Adhesives bought the following PCB products. Aroclor 1221 (9880 lbs), Aroclor 1221B (2080 lbs), Aroclor 5460 (306,6000 lbs), and PCB/PCT mixture (42,000 lbs). Court testimony given in 1982 revealed that about 400,000 gallons of waste oils and PCB's were dumped down a manhole on-site. It is unknown where the manhole leads. The waste material reportedly came from a chemical spill in New Jersey.
Describe the Threat:	

Allegations exist to the fact that Manhattan Adhesives poured about 400,000 lbs of PCB contaminated wastes into the sewers. If PCB's entered the eco-system there would be a potential for bio-accumulation and associated impacts to the flora and fauna of Newton Creek and the East River.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
199	2 of2	E	0.45 / 2,389.83	6.24 / -6	***Manhattan Adhesives*** ***425-459 Green Point Avenue*** ***Brooklyn*** ***NY***	HSWDS

Reg Site ID:	224009	***VOCs:***	No
Site No:		***Semi VOCs:***	No
EPA ID:	NYD980780811	***PCBs:***	Yes
Is Site Active?:	No	***Pesticides:***	Yes
Registry:	D	***Metals:***	No
Years of Operation:	1970 to 1972	***Asbestos:***	No
RCRA:	Unknown	***County:***	Kings
HRS Score:	10.1	***Region:***	2
HRS Date:	05/26/83	***Latitude:***	40 43 56 N
Acres:	0.00	***Longitude:***	73 56 42 W
Site Code:	1	***Quadrangle:***	Brooklyn
Site Code Desc:	Industrial Site		
Owner:	P		
Owner Name:	Frank Castiglione		
Owner Address:	32-02 College Pt. Blvd. Flushing		
Owner Telephone:	(212)886-1117		
Operator:	P		
Operator Name:	U		
Operator Address:	U		

Operator Telephone:	U
Completed Investigation:	Phase 1
Samples Collected:	None
Threat to Env/Public Health?:	E/P
Surface Water Contamination?:	Unknown
Groundwater Contamination?:	Unknown
Drinking Water Contam?:	Unknown
Surface Water Class:	U
Groundwater Class:	U
Active Drinking Water Supply?:	Unknown
Hazard Substance Exposed?:	Unknown
Controlled Site Access?:	Unknown
Ambient Air Contamination?:	U
Threat of Direct Contact?:	Unknown
Doc Fish/Wildlife Mortality?:	Unknown
Impact on Special Status?:	Unknown
TCLP:	
Surface Water:	nearest surface water: 400 ft, northwest
Groundwater:	
Drinking Water:	
Fish or Wildlife Mortality:	
Fish or Wildlife Resource:	
Building:	
Hazard Substance Disposed:	Aroclor 1221, Aroclor 1221B, Aroclor 5460, PCB/PCT mixture
Air:	
Surface Water:	
Surface Soil:	
Waste:	
EP Toxicity:	
Groundwater:	
Sediment:	
Subsurface Soil:	
Leachate:	
Regulatory Agencies Involved:	
Preparer:	Julia Slack(pb) Env. Engineering Tech June 14, 1994
Nominated by:	
Describe the Site:	Records obtained from Mansanto Indusrtial Chemical Co. (of St. Louis Missouri) indicate that from 1970 to 1972, Manhattan Adhesives bought the following PCB products. Aroclor 1221 (9880 lbs), Aroclor 1221B (2080 lbs), Aroclor 5460 (306,6000 lbs), and PCB/PCT mixture (42,000 lbs). Court testimony given in 1982 revealed that about 400,000 gallons of waste oils and PCB's were dumped down a manhole on-site. It is unknown where the manhole leads. The waste material reportedly came from a chemical spill in New Jersey.
Describe the Threat:	

Allegations exist to the fact that Manhattan Adhesives poured about 400,000 lbs of PCB contaminated wastes into the sewers. If PCB's entered the eco-system there would be a potential for bio-accumulation and associated impacts to the flora and fauna of Newton Creek and the East River.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
200	1 of7	ESE	0.45 / 2,391.25	12.51 / 0	**BROOKLYN TERM /MOBIL OIL CORP** **300 NORTH HENRY ST** **BROOKLYN NY 11222**	CERCLIS

Site ID:	0201304	**RNPL Status Code:**	N
Site EPA ID:	NYD000824540	**NPL Status:**	Not on the NPL
Site Street Address 2:		**RFED Facility Code:**	N
Site County Name:	KINGS	**RFED Facility Desc:**	Not a Federal Facility
Site FIPS Code:	36047	**USGS Hydro Unit No.:**	02030201
Region Code:	02	**Site Cong. Dist. Code:**	12
Site SMSA No.:	5600	**ROT Desc:**	Other
Site Prim. Latitude:	+40.731790	**FR NPL Update No.:**	
Site Prim. Longitude:	-073.943470	**RFRA Code:**	
Lat Long Source:			
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	EPA In-House
Act Code ID:	001	***Act Start Date:***	
RAT Code:	VS	***Act Complete Date:***	9/22/1987 00:00:00
RAT Short Name:	ARCH SITE	***AGT Order No.:***	1500
RAT Name:	ARCHIVE SITE	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:		***SH Lead:***	
SPA Code:	13		
RAT Def:	The decision is made that no further activity is planned at the site.		
Site Desc:			
Site Alias:			

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	EPA Fund
Act Code ID:	001	***Act Start Date:***	
RAT Code:	PA	***Act Complete Date:***	9/22/1987 00:00:00
RAT Short Name:	PA	***AGT Order No.:***	130
RAT Name:	PRELIMINARY ASSESSMENT	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	P	***SH Lead:***	
SPA Code:	13		
RAT Def:	Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.		
Site Desc:			
Site Alias:			

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	
Act Code ID:		***Act Start Date:***	
RAT Code:		***Act Complete Date:***	
RAT Short Name:		***AGT Order No.:***	0
RAT Name:		***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:		***SH Seq:***	
RAT Level:		***SH Start Date:***	
RAT DEF OU:		***SH Complete Date:***	
RFBS Code:		***SH Lead:***	
SPA Code:			
RAT Def:			
Site Desc:	No description available .		
Site Alias:	NORTH HENRY ST TERMINAL,,,NY,;		

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	EPA Fund
Act Code ID:	001	***Act Start Date:***	
RAT Code:	DS	***Act Complete Date:***	6/1/1981 00:00:00
RAT Short Name:	DISCVRY	***AGT Order No.:***	10
RAT Name:	DISCOVERY	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:		***SH Lead:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SPA Code: 13
RAT Def: The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.
Site Desc:
Site Alias:

---

200 | **2 of7** | **ESE** | **0.45 / 2,391.25** | **12.51 / 0** | **BROOKLYN TERM /MOBIL OIL CORP**
300 NORTH HENRY ST
BROOKLYN NY 11222 | **CERCLIS NFRAP**

Site ID: 201304
Site EPA ID: NYD000824540
Site Parent ID:
Site County Name: KINGS
Parent Site Name:
Site FIPS Code: 36047
Region Code: 2
Site Cong. Dist. Code: 12
Federal Facility:

CERCLIS-NFRAP Assess History

OU ID: 0
Act Code ID: 1
RAT Code: PA
RAT Short Name: PA
RAT Name: PRELIMINARY ASSESSMENT
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code: P
SPA Code: 13
RALT Short Name: EPA Fund
RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.
RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information
Act Start Date:
Act Complete Date: 9/22/1987
AGT Order No.: 130
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:
SH Qual:
RAQ Act. Qual Short: NFRAP
RNPL Status Code: N

CERCLIS-NFRAP Assess History

OU ID: 0
Act Code ID: 1
RAT Code: VS
RAT Short Name: ARCH SITE
RAT Name: ARCHIVE SITE
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code:
SPA Code: 13
RALT Short Name: EPA In-House
RAT Def: The decision is made that no further activity is planned at the site.
RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information
Act Start Date:
Act Complete Date: 9/22/1987
AGT Order No.: 1500
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:
SH Qual:
RAQ Act. Qual Short:
RNPL Status Code: N

CERCLIS-NFRAP Assess History

OU ID: 0
Act Code ID: 1
RAT Code: DS
RAT Short Name: DISCVRY
RAT Name: DISCOVERY
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code:
SPA Code: 13
Act Start Date:
Act Complete Date: 6/1/1981
AGT Order No.: 10
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:
SH Qual:
RAQ Act. Qual Short:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RALT Short Name: EPA Fund
RNPL Status Code: N
RAT Def: The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.
RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

---

200 | **3 of7** | **ESE** | **0.45 / 2,391.25** | **12.51 / 0** | **EXXON MOBIL OIL CORPORATION BROOKLYN TERMINAL**
300 NORTH HENRY STREET
Brooklyn NY 11222 | **MOSF**

Site ID: 344640
Site Status: Unregulated/Closed
Program No: 2-1420
Program Type Code: MOSF
Program Type Desc: Major Oil Storage Facility Program
Site Type: Storage Terminal/Petroleum Distributor
More Info:

Expiration Date: N/A
DEC Region: 2
County: Kings
UTM X: 589161.51103
UTM Y: 4509278.91358

---

200 | **4 of7** | **ESE** | **0.45 / 2,391.25** | **12.51 / 0** | **MOBIL**
300 NORTH HENRY STREET
BROOKLYN NY | **LST**

Spill No: 8910558
Site ID: 59222
DER Facility ID: 55361
CID:
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Failure
Water Body:
Class: C3
Meets Std: False
Penalty: False
County: Kings
Referred to:
Reported by: Responsible Party
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: False
Spill Date: 02/03/1990 10:00:00 AM
Rcvd Date: 02/05/1990 12:48:00 PM
CAC Date:
Insp Date:
Close Date: 12/03/2003 12:00:00 AM
Create Date: 02/05/1990 12:00:00 AM
Update Date: 04/07/2004 12:00:00 AM
DEC Region: 2
Lead DEC: TOMASELLO
After Hours: False

Caller Remark:

"CONTAINED IN TANK FARM AREA, 2FT BASE OF WATER ADDED, TRANSFER OIL TO BARGE."

Dec Remark:

""

Material Information

OP Unit ID: 935928
OU: 01
Material ID: 440128
CAS No:
Material Family: Petroleum
Quantity: 80.00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0012A
Material Name: kerosene

Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Information

Spiller Name:
Spiller Company: EXXONMOBIL
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.728788960
Longitude: -73.944000220

---

200 | ***5 of7*** | ***ESE*** | ***0.45 / 2,391.25*** | ***12.51 / 0*** | ***MOBIL GREENPOINT 300 NORTH HENRY STREET BROOKLYN NY*** | ***LST***

Spill No:	8800842	***REM Phase:***	0
Site ID:	59220	***UST Trust:***	False
DER Facility ID:	55361	***Spill Date:***	04/27/1988 02:00:00 PM
CID:		***Rcvd Date:***	04/27/1988 02:58:00 PM
Program Type:	ER	***CAC Date:***	
SWIS Code:	2401	***Insp Date:***	
Contribute Factor:	Tank Test Failure	***Close Date:***	04/23/2003 12:00:00 AM
Water Body:		***Create Date:***	04/29/1988 12:00:00 AM
Class:	c3	***Update Date:***	04/07/2004 12:00:00 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	JMROMMEL
County:	Kings	***After Hours:***	False
Referred to:			
Reported by:	Responsible Party		
Source:	Major Facility (MOSF) > 400,000 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"THE LINE HAS BEEN ISOLATED.THE PRODUCT IS TO BE REMOVED AND EXCAVATIONTO BE DONE. THE LINE WILL BE REPLACED SINCE IT DOES NOT HOLD THE PRES-SURE TEST."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL Closed and cross-referenced to spill #8800244 Rommel"

Material Information

OP Unit ID:	916331	***Med in Air:***	False
OU:	01	***Med GW:***	True
Material ID:	460013	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0012A		
Material Name:	kerosene		

Spiller Information

Spiller Name:
Spiller Company: EXXONMOBIL
Spiller Address:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller City:
Spiller State: ZZ
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.728788960
Longitude: -73.944000220

Tank Test Information

Spill Tank ID: 1533766
Tank No:
Tank SIze: 0
Material: 0012
EPA UST:
UST:
Cause:
Alt Test Method: Unknown
Source:
Leak Rate: .00
Gross Fail:
Modified by: Spills
Last Modified: 2004-10-01 04:00:45.140000000
Test Method: 00

---

200 | ***6 of7*** | ***ESE*** | ***0.45 / 2,391.25*** | ***12.51 / 0*** | ***MOBIL GREENPOINT 300 NORTH HENRY STREET BROOKLYN NY*** | ***LST***

Spill No: 8808149
Site ID: 59221
DER Facility ID: 55361
CID:
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Test Failure
Water Body:
Class: A3
Meets Std: False
Penalty: False
County: Kings
Referred to:
Reported by: Responsible Party
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data
REM Phase: 0
UST Trust: True
Spill Date: 01/12/1989 11:30:00 AM
Rcvd Date: 01/12/1989 12:20:00 PM
CAC Date:
Insp Date:
Close Date: 09/24/2003 12:00:00 AM
Create Date: 01/19/1989 12:00:00 AM
Update Date: 04/07/2004 12:00:00 AM
DEC Region: 2
Lead DEC: JMROMMEL
After Hours: False

Caller Remark:

"(2) TANKS FAILED PETRO TITE, 1ST WAS UNLEADED GAS 2K TANK FAILED AT 1GPH, 2ND WAS DIESEL, 4K TANK FAILED AT 1GPH, 3RD WAS A 4K TANK WHICH HOLDS AN ADDITIVE & FAILED AIR PRESSURE TEST,LEAK IN PIPING"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 01/12/89: MOBIL HAS GIVEN GASERVICE PERMISSION TO EXCAVATE. Formerly assigned to Sullivan. Closed and cross referenced to 8800244"

Material Information

OP Unit ID: 924554
OU: 01
Material ID: 452914
CAS No:
Material Family: Petroleum
Quantity: .00
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0009
Med in Air: False
Med GW: True
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Material Name: gasoline

Spiller Information

Spiller Name:
Spiller Company: EXXONMOBIL
Spiller Address: NORTH HENRY STREET
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.728788960
Longitude: -73.944000220

Tank Test Information

Spill Tank ID: 1535079
Tank No:
Tank Size: 0
Material: 0009
EPA UST:
UST:
Cause:
Alt Test Method: Unknown
Source:
Leak Rate: .00
Gross Fail:
Modified by: Spills
Last Modified: 2004-10-01 04:00:45.140000000
Test Method: 00

---

200 ***7 of7*** ***ESE*** ***0.45 / 2,391.25*** ***12.51 / 0*** ***MOBIL GREENPOINT 300 NORTH HENRY STREET BROOKLYN NY*** ***LST***

Spill No: 9312129
Site ID: 59225
DER Facility ID: 55361
CID:
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Failure
Water Body:
Class: B3
Meets Std: True
Penalty: False
County: Kings
Referred to:
Reported by: Responsible Party
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data
REM Phase: 0
UST Trust: False
Spill Date: 01/14/1994 12:01:00 PM
Rcvd Date: 01/14/1994 02:53:00 PM
CAC Date:
Insp Date:
Close Date: 10/16/2002 12:00:00 AM
Create Date: 01/18/1994 12:00:00 AM
Update Date: 04/07/2004 12:00:00 AM
DEC Region: 2
Lead DEC: SJMILLER
After Hours: False

Caller Remark:

"550 GAL. A/G TANK - WATER IN TANK FROZE & SPLIT SAME - OIL LEAKED TO ICE-COVERED GROUND - CONTAM. ICE P/U & DRUMMED. WILL DISPOSE - STEVE MILLER NOTIFIED AT 12:15."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MILLER 10/10/95: This is additional information about material spilled from the translation of the old spill file: MIXED OILS-RECO.SYST."

Material Information

OP Unit ID: 994142
OU: 01
Material ID: 391125
Med in Air: False
Med GW: False
Med SW: False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0006		
Material Name:	crude oil		

Spiller Information

Spiller Name:	
Spiller Company:	EXXONMOBIL
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.728788960
Longitude:	-73.944000220

201	*1 of4*	*E*	*0.45 / 2,401.39*	*5.30 / -7*	***MANHATTAN ADHESIVES PLANT 425-459 GREENPOINT AVENUE BROOKLYN NY 11222***	***CERCLIS***

Site ID:	0202271	**RNPL Status Code:**	N
Site EPA ID:	NYD980780811	**NPL Status:**	Not on the NPL
Site Street Address 2:		**RFED Facility Code:**	N
Site County Name:	KINGS	**RFED Facility Desc:**	Not a Federal Facility
Site FIPS Code:	36047	**USGS Hydro Unit No.:**	02030201
Region Code:	02	**Site Cong. Dist. Code:**	13
Site SMSA No.:	5600	**ROT Desc:**	Other
Site Prim. Latitude:	+40.736891	**FR NPL Update No.:**	
Site Prim. Longitude:	-073.66	**RFRA Code:**	
Lat Long Source:			
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	
Act Code ID:		**Act Start Date:**	
RAT Code:		**Act Complete Date:**	
RAT Short Name:		**AGT Order No.:**	0
RAT Name:		**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:		**SH Seq:**	
RAT Level:		**SH Start Date:**	
RAT DEF OU:		**SH Complete Date:**	
RFBS Code:		**SH Lead:**	
SPA Code:			
RAT Def:			
Site Desc:	No description available .		
Site Alias:	No alias data available		

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	State (Fund)
Act Code ID:	001	**Act Start Date:**	
RAT Code:	DS	**Act Complete Date:**	9/1/1984 00:00:00
RAT Short Name:	DISCVRY	**AGT Order No.:**	10

RAT Name:	DISCOVERY	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:		**SH Lead:**	
SPA Code:	13		

RAT Def: The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	State (Fund)
Act Code ID:	001	**Act Start Date:**	7/1/1985 00:00:00
RAT Code:	SI	**Act Complete Date:**	8/31/1985 00:00:00
RAT Short Name:	SI	**AGT Order No.:**	160
RAT Name:	SITE INSPECTION	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	P	**SH Lead:**	
SPA Code:	13		

RAT Def: The process of collecting site data and samples to characterize the severity of the hazard for the hazard ranking score and/or enforcement support.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	State (Fund)
Act Code ID:	001	**Act Start Date:**	9/1/1984 00:00:00
RAT Code:	PA	**Act Complete Date:**	10/31/1984 00:00:00
RAT Short Name:	PA	**AGT Order No.:**	130
RAT Name:	PRELIMINARY ASSESSMENT	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	P	**SH Lead:**	
SPA Code:	13		

RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	EPA In-House
Act Code ID:	001	**Act Start Date:**	
RAT Code:	VS	**Act Complete Date:**	8/31/1985 00:00:00
RAT Short Name:	ARCH SITE	**AGT Order No.:**	1500
RAT Name:	ARCHIVE SITE	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:		**SH Lead:**	
SPA Code:	13		

RAT Def: The decision is made that no further activity is planned at the site.

Site Desc:
Site Alias:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
201	2 of4	E	0.45 / 2,401.39	5.30 / -7	MANHATTAN ADHESIVES PLANT 425-459 GREENPOINT AVENUE BROOKLYN NY 11222	CERCLIS NFRAP

Site ID: 202271
Site EPA ID: NYD980780811
Site Parent ID:
Site County Name: KINGS
Parent Site Name:
Site FIPS Code: 36047
Region Code: 2
Site Cong. Dist. Code: 13
Federal Facility:

CERCLIS-NFRAP Assess History

OU ID: 0
Act Code ID: 1
RAT Code: VS
RAT Short Name: ARCH SITE
RAT Name: ARCHIVE SITE
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code:
SPA Code: 13
RALT Short Name: EPA In-House
RAT Def: The decision is made that no further activity is planned at the site.
RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information
Act Start Date:
Act Complete Date: 8/31/1985
AGT Order No.: 1500
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:
SH Qual:
RAQ Act. Qual Short:
RNPL Status Code: N

CERCLIS-NFRAP Assess History

OU ID: 0
Act Code ID: 1
RAT Code: DS
RAT Short Name: DISCVRY
RAT Name: DISCOVERY
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code:
SPA Code: 13
RALT Short Name: State (Fund)
RAT Def: The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.
RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information
Act Start Date:
Act Complete Date: 9/1/1984
AGT Order No.: 10
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:
SH Qual:
RAQ Act. Qual Short:
RNPL Status Code: N

CERCLIS-NFRAP Assess History

OU ID: 0
Act Code ID: 1
RAT Code: PA
RAT Short Name: PA
RAT Name: PRELIMINARY ASSESSMENT
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code: P
SPA Code: 13
RALT Short Name: State (Fund)
RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.
RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information
Act Start Date: 9/1/1984
Act Complete Date: 10/31/1984
AGT Order No.: 130
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:
SH Qual:
RAQ Act. Qual Short: NFRAP
RNPL Status Code: N

CERCLIS-NFRAP Assess History

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OU ID:	0	**Act Start Date:**	7/1/1985
Act Code ID:	1	**Act Complete Date:**	8/31/1985
RAT Code:	SI	**AGT Order No.:**	160
RAT Short Name:	SI	**SH OU:**	
RAT Name:	SITE INSPECTION	**SH Code:**	
RAT Hist. Only Flag:		**SH Seq:**	
RAT NSI Indicator:	B	**SH Start Date:**	
RAT Level:	1	**SH Complete Date:**	
RAT DEF OU:	00	**SH Lead:**	
RFBS Code:	P	**SH Qual:**	
SPA Code:	13	**RAQ Act. Qual Short:**	NFRAP
RALT Short Name:	State (Fund)	**RNPL Status Code:**	N

RAT Def: The process of collecting site data and samples to characterize the severity of the hazard for the hazard ranking score and/or enforcement support.

RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

---

201	3 of4	E	0.45 / 2,401.39	5.30 / -7	**Former Manhattan Adhesives Plant** **425-459 Greenpoint Avenue** **Brooklyn NY**	SHWS

Site Code:	58916
HW Code:	224009
Program:	HW
Site Class:	N
Site Name:	Former Manhattan Adhesives Plant
Site Address:	425-459 Greenpoint Avenue
City:	Brooklyn
Zip:	
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.732192984
Longitude:	-73.944858258
SWIS:	2401
Acres:	
Record Added:	1999-11-18 12:00:00
Record Update:	2003-12-16 00:00:00
Updated by:	kstang
Site Code (Web):	224009
Program Type (Web):	HW
Site Name (Web):	Former Manhattan Adhesives Plant
Site Class (Web):	N
Address1 (Web):	425-459 Greenpoint Avenue
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	
County (Web):	Kings
Longitude (Web):	-73.944858258
Latitude (Web):	40.732192984
Site Code (GIS):	224009
Site Name (GIS):	Former Manhattan Adhesives Plant
Program (GIS):	HW
Site Class (GIS):	N
Address1 (GIS):	425-459 Greenpoint Avenue
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	
County (GIS):	Kings

Site Class Desc: No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement

on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Site Class Desc (Web): No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH:

Description:

The site did not qualify for addition to the Registry of Inactive Hazardous Disposal Sites. Manhattan Adhesives is currently an empty factory building that is located at the foot of the Greenpoint Ave., Bridge in Brooklyn. Besides the Manhattan Adhesives factory, about 10 feet from the northeast wall is a manhole (not a sewer or drain) into which liquid waste was allegedly discharged. This waste came from a condemned oil storage site located at the intersection of Rt. 280, and the NJ Turnpike in NJ. The manhole is suspected of being the opening to an underground tank; however, the quantity of the waste allegedly dumped exceeds the capacity of most tanks. This information was obtained from the State Senate Committee on Crime and the Brooklyn District Attorney's office. Phase I State Superfund has been completed. A partial phase II investigation was completed during 1985 and recommended no further action. The Responsible Party has agreed to undertake an investigation in 1986. An investigation has not found hazardous waste on-site.

Assessment:

Owner Information

Owner Op: 01
Sub Type: NNN
Owner Name:
Owner Company: Frank Castiglione
Owner Street: 32-02 College Point Boulevard
Owner Street 2:
Owner City: Flushing
Owner State: NY
Owner Zip: 11354
Country: United States of America

Owner Op: 01
Sub Type: E
Owner Name:
Owner Company: FRANK CASTIGLIONE
Owner Street: 32-02 COLLEGE POINT BLVD.
Owner Street 2:
Owner City: FLUSHING
Owner State: NY
Owner Zip: 11354
Country: United States of America

Projects Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Project Code: 01
Project Desc: Site Caracterization
Project Refer Name:
End Date: 1985-07-01 00:00:00
End Status: ACT
Operable Unit ID: 576
Operable Unit: 01
Operable Unit Desc: FORMER MANHATTAN ADHESIVES
Code Name: Site Characterization

Environmental Remediation

Operable Unit: 01
Contaminants:

---

201 | ***4 of4*** | ***E*** | ***0.45 / 2,401.39*** | ***5.30 / -7*** | ***MANHATTAN ADHESIVES PLANT 425-459 GREENPOINT AVENUE BROOKLYN NY 11222*** | ***SEMS ARCHIVE***

Site ID: 0202271
EPA ID: NYD980780811
Superfund Alte Agr: No
Federal Facility: No
FF Docket: No
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

FIPS Code: 36047
Cong District: 13
Region: 02
County: KINGS

Action Information

Operable Units: 00
Action Code: SI
Action Name: SI
Start Actual: 7/1/1985 5:00:00 AM
Finish Actual: 8/31/1985 5:00:00 AM
Curr Action Lead: St Perf
NPL:

Qual: N
SEQ: 1
FF: No
FF Docket: No
Region: 02

Operable Units: 00
Action Code: PA
Action Name: PA
Start Actual: 9/1/1984 5:00:00 AM
Finish Actual: 10/31/1984 6:00:00 AM
Curr Action Lead: St Perf
NPL:

Qual: N
SEQ: 1
FF: No
FF Docket: No
Region: 02

Operable Units: 00
Action Code: VS
Action Name: ARCH SITE
Start Actual:
Finish Actual: 8/31/1985 5:00:00 AM
Curr Action Lead: EPA Perf In-Hse
NPL:

Qual:
SEQ: 1
FF: No
FF Docket: No
Region: 02

Operable Units: 00
Action Code: DS
Action Name: DISCVRY
Start Actual: 9/1/1984 5:00:00 AM
Finish Actual: 9/1/1984 5:00:00 AM
Curr Action Lead: St Perf
NPL:

Qual:
SEQ: 1
FF: No
FF Docket: No
Region: 02

---

202 | ***1 of2*** | ***ESE*** | ***0.46 / 2,403.01*** | ***12.48 / 0*** | ***Mobil Oil Brooklyn Terminal 300 NORTH HENRY STREET BROOKLYN NY*** | ***SHWS***

Site Code:	58693
HW Code:	224013
Program:	HW
Site Class:	N
Site Name:	Mobil Oil Brooklyn Terminal
Site Address:	300 NORTH HENRY STREET
City:	BROOKLYN
Zip:	
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.729622813
Longitude:	-73.944100946
SWIS:	2401
Acres:	15.000
Record Added:	1999-11-18 12:00:00
Record Update:	2003-12-16 00:00:00
Updated by:	kstang
Site Code (Web):	224013
Program Type (Web):	HW
Site Name (Web):	Mobil Oil Brooklyn Terminal
Site Class (Web):	N
Address1 (Web):	300 North Henry Street
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	10013
County (Web):	Kings
Longitude (Web):	-73.944100946
Latitude (Web):	40.729622813
Site Code (GIS):	224013
Site Name (GIS):	Mobil Oil Brooklyn Terminal
Program (GIS):	HW
Site Class (GIS):	N
Address1 (GIS):	300 NORTH HENRY STREET
Address2 (GIS):	
Locality (GIS):	BROOKLYN
Zip Code (GIS):	
County (GIS):	Kings
Site Class Desc:	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced; c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.
Site Class Desc (Web):	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced; c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work

was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH:
Description:

See project S224150

Assessment:

Owner Information

Owner Op: 03
Sub Type: NNN
Owner Name:
Owner Company: MOBIL OIL
Owner Street:
Owner Street 2:
Owner City:
Owner State: NY
Owner Zip:
Country: Unknown

Environmental Remediation

Operable Unit: 01
Contaminants:

---

202 | ***2 of2*** | ***ESE*** | ***0.46 / 2,403.01*** | ***12.48 / 0*** | ***BROOKLYN TERM /MOBIL OIL CORP***
300 NORTH HENRY ST
BROOKLYN NY 11222 | ***SEMS ARCHIVE***

Site ID: 0201304
EPA ID: NYD000824540
Superfund Alte Agr: No
Federal Facility: No
FF Docket: No
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

FIPS Code: 36047
Cong District: 12
Region: 02
County: KINGS

Action Information

Operable Units: 00
Action Code: VS
Action Name: ARCH SITE
Start Actual:
Finish Actual: 9/22/1987 4:00:00 AM
Curr Action Lead: EPA Perf In-Hse
NPL:

Qual:
SEQ: 1
FF: No
FF Docket: No
Region: 02

Operable Units: 00
Action Code: PA
Action Name: PA
Start Actual:
Finish Actual: 9/22/1987 4:00:00 AM
Curr Action Lead: EPA Perf
NPL:

Qual: N
SEQ: 1
FF: No
FF Docket: No
Region: 02

Operable Units: 00
Action Code: DS
Action Name: DISCVRY
Start Actual: 6/1/1981 4:00:00 AM

Qual:
SEQ: 1
FF: No
FF Docket: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Finish Actual: 6/1/1981 4:00:00 AM
Region: 02
Curr Action Lead: EPA Perf
NPL:

---

203 *1 of1* | *NNW* | *0.46 / 2,403.46* | *4.51 / -8* | *DITMAS OIL-LONG ISLAND CITY*
53-02 11TH ST
LONG ISLAND CITY NY 11101
MOSF

Site ID: 345056
Site Status: Inactive
Program No: 2-2020
Program Type Code: MOSF
Program Type Desc: Major Oil Storage Facility Program
Site Type: Storage Terminal/Petroleum Distributor
More Info:
Expiration Date: N/A
DEC Region: 2
County: Queens
UTM X: 588440.78695
UTM Y: 4510466.39436

---

204 *1 of2* | *W* | *0.46 / 2,411.32* | *9.59 / -2* | *145 WEST STREET*
145 WEST STREET
BROOKLYN NY
LST

Spill No: 9408283
Site ID: 176036
DER Facility ID: 147953
CID:
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Test Failure
Water Body:
Class: C3
Meets Std: True
Penalty: False
County: Kings
Referred to:
Reported by: Tank Tester
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data
REM Phase: 0
UST Trust: False
Spill Date: 09/21/1994 12:00:00 PM
Rcvd Date: 09/22/1994 08:16:00 AM
CAC Date: 12/02/1994 12:00:00 AM
Insp Date:
Close Date: 12/02/1994 12:00:00 AM
Create Date: 10/31/1994 12:00:00 AM
Update Date: 03/03/2000 12:00:00 AM
DEC Region: 2
Lead DEC: SMMARTIN
After Hours: True

Caller Remark:

"TTF- WILL RECOMMEND REPAIRS"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT 12/02/94: CLOSED OUT 20K TANK, TOOK SOIL SAMPLES, BELOW STARS. SEE O'DOWD'S FILES: 9408663 "

Material Information

OP Unit ID: 1005855
OU: 01
Material ID: 377721
CAS No:
Material Family: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0001A
Material Name: #2 fuel oil
Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: UNKNOWN
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.731949160
Longitude: -73.959676760

Tank Test Information

Spill Tank ID: 1543162
Tank No:
Tank SIze: 0
Material: 0001
EPA UST:
UST:
Cause:
Alt Test Method: Unknown
Source:
Leak Rate: .00
Gross Fail:
Modified by: Spills
Last Modified: 2004-10-01 04:00:45.140000000
Test Method: 00

---

204 ***2 of2*** ***W*** ***0.46 / 2,411.32*** ***9.59 / -2*** ***145 WEST STREET 145 WEST STREET BROOKLYN NY*** ***LST***

Spill No: 9408663
Site ID: 176037
DER Facility ID: 147953
CID:
Program Type: ER
SWIS Code: 2401
Contribute Factor: Tank Test Failure
Water Body:
Class: C3
Meets Std: True
Penalty: False
County: Kings
Referred to:
Reported by: Tank Tester
Source: Private Dwelling
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data
REM Phase: 0
UST Trust: False
Spill Date: 09/29/1994 10:30:00 AM
Rcvd Date: 09/29/1994 11:53:00 AM
CAC Date: 12/02/1994 12:00:00 AM
Insp Date:
Close Date: 12/02/1994 12:00:00 AM
Create Date: 11/01/1994 12:00:00 AM
Update Date: 12/02/1994 12:00:00 AM
DEC Region: 2
Lead DEC: O'DOWD
After Hours: False

Caller Remark:

"TO PUMP TANK OUT VIA NOTIFIER"

Dec Remark:

""

Material Information

OP Unit ID: 1002784
OU: 01
Material ID: 378091
CAS No:
Material Family: Petroleum
Quantity: -1.00
Units:
Recovered: .00
Med Soil: True
Med Air: False
Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Material Code: 0001A
Material Name: #2 fuel oil

Spiller Information

Spiller Name:
Spiller Company: COMMERCIAL BLDG COOP APTS
Spiller Address: 145 WEST STREET
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.731949160
Longitude: -73.959676760

Tank Test Information

Spill Tank ID: 1543192
Tank No:
Tank SIze: 0
Material: 0001
EPA UST:
UST:
Cause:
Alt Test Method: Unknown
Source:
Leak Rate: .00
Gross Fail:
Modified by: Spills
Last Modified: 2004-10-01 04:00:45.140000000
Test Method: 00

205	1 of1	E	0.46 / 2,415.05	5.30 / -7	F.E.S. RECYCLING; INC. (SUMMIT CARTING) 425 GREENPOINT AVE Brooklyn NY 11222	SWF/LF

Activity Number: [24W77]
Facility Name (Act):
Location Addr (Act):
Location Addr2 (Act):
City (Act):
State (Act):
Zip Code (Act):
County (Act):
East Coord (Act):
North Coord (Act):
Facility Name:
Location Addr:
Location Addr2:
City:
State:
Zip Code:
County:
East Coord:
North Coord:
Data Source: SWMF - Inactive Facility Lists
Facility Name (InAct): F.E.S. RECYCLING; INC. (SUMMIT CARTING)
Location Addr (InAct): 425 GREENPOINT AVE
Loc Addr2(InAct):
City (InAct): Brooklyn
State (InAct): NY
Zip Code (InAct): 11222
County (InAct): Kings
East Coord (InAct): 589400
North Coord (InAct): 4509700

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:
Activity Desc: C&D processing - registration
Regulatory Status: Permit
Active: No
Dt of Last Inspection:
Expiration Dt: 11/6/2001
Owner Type:
Owner Name:
Authorization No: 2-6101-00011
Authrzation Issue Dt: 11/6/1996
Operator Type:
Operator Name:
Phone No: 7183926858
Region: 2
Contact Name: PENTELIS FAKIRIS; PRESIDENT
Contact Address:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Address:		**Contact Address2:**	
Owner Address2:		**Contact City:**	
Owner City:		**Contact State:**	
Owner State:		**Contact Zip:**	
Owner Zip:		**Contact Phone:**	
Owner Phone:		**Contact Email:**	
Owner Email:			
Waste Types:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
206	1 of1	E	0.46 / 2,417.00	5.96 / -6	UNITED BIOFUELS INC - 435 GREENPOINT AVE BROOKLYN NY	PFAS IND

Status:	Inactive	**Fac Fips Code:**	36047
Fac Indian Cntry Flg:	No	**Compliance Status:**	No Violation Identified
Fac Derived Huc:	02030201	**EPA Programs:**	CAA
Fac Derived Wbd:	020301010405	**Federal Facility:**	No
Fac Derived Cd113:	12	**Federal Agency:**	-
Fac Derived Cb2010:	360470579002010	**Fac Snc Flg:**	No
Fac Informal Count:	0	**AIR Flag:**	Yes
Last Informal Action:	-	**NPDES Flag:**	No
Formal Action Count:	0	**SDWIS Flag:**	No
Last Formal Action:	-	**RCRAFlag:**	No
Fac Total Penalties:	0	**TRI Flag:**	No
Fac Penalty Count:	-	**GHG Flag:**	No
Date Last Penalty:	-	**TRI IDs:**	-
Last Penalty Amt:	-	**TRI Releases Trnsfrs:**	-
Fac Qtrs With Nc:	0	**TRI on Site Releases:**	-
Programs With Snc:	0	**TRI off Site Trnsfrs:**	-
Fac Percent Minority:	50.256	**TRI Reporter:**	-
Fac Pop Den:	46147.88	**Fac Imp Water Flg:**	-
Count:	1	**Fac Major Flag:**	-
Fac County:	KINGS	**Fac Active Flag:**	Yes
State Other :		**Fac Inspection Count:**	2
Region:	02	**Date Last Inspection:**	12/14/2021
Latitude:	40.732958	**Days Last Inspection:**	1012
Longitude:	-73.942278		
Fac Derived Tribes:	-		
AIR IDs:	NY0000002610101278		
CAA Permit Types:	80% Synthetic Minor Emissions		
CAA NAICS:	327123 324110		
CAA SICS:	2911		
NPDES IDs:	-		
CWA Permit Types:	-		
CWA NAICS:	-		
CWA SICS:	-		
RCRA IDs:	-		
RCRA Permit Types:	-		
RCRA NAICS:	-		
SDWA IDs:	-		
SDWA System Types:	-		
SDWA Compliance Status:	-		
SDWA Snc Flag:	No		
Fac Collection Meth:	ADDRESS MATCHING-HOUSE NUMBER		
EJSCREEN Flag Us:	No		
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.942278,%22y%22:40.732958,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1		
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110055277445		
Industry:	Petroleum		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
207	1 of1	NE	0.46 / 2,419.10	4.69 / -7	STAGING SCAFFOLDING 25-20 BORDEN AVE LONG ISLAND CITY NY	LST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spill No:	0109751	**REM Phase:**	0
Site ID:	316328	**UST Trust:**	False
DER Facility ID:	189762	**Spill Date:**	12/18/2001 12:00:00 PM
CID:	365	**Rcvd Date:**	01/08/2002 03:07:00 PM
Program Type:	ER	**CAC Date:**	
SWIS Code:	4101	**Insp Date:**	
Contribute Factor:	Tank Failure	**Close Date:**	07/29/2002 12:00:00 AM
Water Body:		**Create Date:**	01/08/2002 12:00:00 AM
Class:	B3	**Update Date:**	06/13/2006 08:54:22 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	MXTIPPLE
County:	Queens	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"THEY ARE PULLING THE TANK OUT THURSDAY - 550 GALLON TANK - THE CONTAMINATED SOIL WAS FOUND BACK IN DECEMBER - A DEC REP IS SUPPOSED TO BE ON SITE TOMORROW"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE "

Material Information

OP Unit ID:	848113	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	527401	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	JOHN PANTONELLI
Spiller Company:	STAGING SCAFOLDING
Spiller Address:	2520 BORDEN AV
Spiller City:	LONG ISLAND CITY
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	JOHN PANTONELLI
Contact Phone:	(718) 361-2861
Contact Ext:	
Latitude:	40.738026750
Longitude:	-73.938560180

208	***1 of1***	***N***	***0.46 / 2,428.34***	***6.31 / -6***	***BUSINESS 11-40 BORDEN AVE QUEENS NY***	***LST***

Spill No:	0709037	**REM Phase:**	0
Site ID:	390051	**UST Trust:**	
DER Facility ID:	339641	**Spill Date:**	11/19/2007 12:30:00 PM
CID:	408	**Rcvd Date:**	11/19/2007 03:03:00 PM
Program Type:	ER	**CAC Date:**	

SWIS Code:	4101	**Insp Date:**	
Contribute Factor:	Tank Test Failure	**Close Date:**	07/24/2008 12:00:00 AM
Water Body:		**Create Date:**	11/19/2007 03:31:00 PM
Class:	C4	**Update Date:**	07/24/2008 12:16:20 PM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	bkfalvey
County:	Queens	**After Hours:**	False
Referred to:			
Reported by:	Tank Tester		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"DRY PORTION LEAK;"

Dec Remark:

"11/27/07 bf: Spoke to Nancy Galasso. She plans on repairing the tank and is waiting for proposal from Petroleum Tank Cleaners. Confirmed mailing address and sent ttf letter to: Nancy Galasso Wickersham Realty 79 Wheatley Road Old Westbury, NY 11568 1/2/08 On 12/27/07, received 12/11/07 passing tightness test for tank only. Included was a note requesting a response. 1/3/08 Called Nancy Galasso (516)626-3487. She told me tank failure was due to pipes. PTC is handling. Called M. Salamack of PTC. Tank emptied. Running on temp tank. No contamination found so far. Piping is both aboveground and underground. Company leasing building is giving PTC hard time. They were sent away when trying to make repairs. Lessee wants to remove tank and install AST. Owner wants to keep UST. PTC caught in middle and has to call lessee prior to doing work at the site (as per lessee). Mark will call lessee today. bf 5/22/2008 Sangesland sent a TTF 2nd Notice letter to: Nancy Galasso Wickersham Realty 79 Wheatley Road Old Westbury, NY 11568 5/23/08 Received message from N. Galasso Wickershaw (516)626-3487. She said tank was closed, which according to DEC records was closed in 2008. I told her to close the spill case a letter/report is required. bf 5/28/08 Yesterday, M. Salamack left message stating no contamination found. Piping fittings were loose. He will send report to me by the end of the week. bf 7/24/08 received letter from Mark Salamack on 7/16/08. Suction line Cuase of failure was exposed pipe inside the building. Buried prtion of pie examioned and no sign of cantamination. Old tank abandoned and new 1080 gallon AST installed. Passing tightness test for tank included. Review of PBS file shows that tank was closed. NFA. bf"

Material Information

OP Unit ID:	1147167	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2137567	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	MARLIN JOSEPH
Spiller Company:	BUSINESS
Spiller Address:	11-40 BORDEN AVE
Spiller City:	QUEENS
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	MARLIN JOSEPH
Contact Phone:	(718) 624-4842
Contact Ext:	112
Latitude:	40.740561000
Longitude:	-73.950856000

Tank Test Information

Spill Tank ID:	2365790	**Source:**	01
Tank No:		**Leak Rate:**	.00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tank Size:	3000	**Gross Fail:**	
Material:	0001	**Modified by:**	Watchdog
EPA UST:		**Last Modified:**	2007-11-19 15:30:59
UST:	True	**Test Method:**	03
Cause:	99		
Alt Test Method:	Horner EZ Check I or II		

209	1 of1	E	0.46 / 2,441.00	2.28 / -10	UNITED METRO ENERGY CORP. 498 KINGSLAND AVENUE BROOKLYN NY 11222	MOSF

Site ID:	344649	**Expiration Date:**	03/31/2026
Site Status:	Active	**DEC Region:**	2
Program No:	2-1380	**County:**	Kings
Program Type Code:	MOSF	**UTM X:**	589327.92900
Program Type Desc:	Major Oil Storage Facility Program	**UTM Y:**	4509831.79267
Site Type:	Storage Terminal/Petroleum Distributor		
More Info:	http://www.dec.ny.gov/chemical/287.html		

210	1 of1	WSW	0.47 / 2,457.49	13.94 / 2	58 Greenpoint Ave.-OER 58 Greenpoint Ave. Brooklyn NY 11222	SHWS

Site Code:	533500
HW Code:	224246
Program:	HW
Site Class:	P
Site Name:	58 Greenpoint Ave.-OER
Site Address:	58 Greenpoint Ave.
City:	Brooklyn
Zip:	11222
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.729512000
Longitude:	-73.958674000
SWIS:	2401
Acres:	0.090
Record Added:	2016-10-12 16:00:00
Record Update:	2024-02-14 10:39:00
Updated by:	HMDUDEK
Site Code (Web):	224246
Program Type (Web):	HW
Site Name (Web):	58 Greenpoint Ave.-OER
Site Class (Web):	P
Address1 (Web):	58 Greenpoint Ave.
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.958674000
Latitude (Web):	40.729512000
Site Code (GIS):	224246
Site Name (GIS):	58 Greenpoint Ave.-OER
Program (GIS):	HW
Site Class (GIS):	P
Address1 (GIS):	58 Greenpoint Ave.
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was

disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.

Site Class Desc (Web): Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.

Assess DOH: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Description:

This is an OER site not managed by NYSDEC

Assessment:

Environmental Remediation

Operable Unit: 01
Contaminants:

---

211 | ***1 of1*** | ***WSW*** | ***0.47 / 2,497.74*** | ***12.93 / 1*** | ***KB PROJECTS***
BROOKLYN NY | ***PFAS IND***

Status:	Inactive	***Fac Fips Code:***	36047
Fac Indian Cntry Flg:	No	***Compliance Status:***	No Violation Identified
Fac Derived Huc:	02030201	***EPA Programs:***	CAA
Fac Derived Wbd:	020301010405	***Federal Facility:***	No
Fac Derived Cd113:	12	***Federal Agency:***	-
Fac Derived Cb2010:	360470565001007	***Fac Snc Flg:***	No
Fac Informal Count:	0	***AIR Flag:***	Yes
Last Informal Action:	-	***NPDES Flag:***	No
Formal Action Count:	0	***SDWIS Flag:***	No
Last Formal Action:	-	***RCRAFlag:***	No
Fac Total Penalties:	0	***TRI Flag:***	No
Fac Penalty Count:	-	***GHG Flag:***	No
Date Last Penalty:	-	***TRI IDs:***	-
Last Penalty Amt:	-	***TRI Releases Trnsfrs:***	-
Fac Qtrs With Nc:	0	***TRI on Site Releases:***	-
Programs With Snc:	0	***TRI off Site Trnsfrs:***	-
Fac Percent Minority:	47.215	***TRI Reporter:***	-
Fac Pop Den:	47324.67	***Fac Imp Water Flg:***	-
Count:	1	***Fac Major Flag:***	-
Fac County:	KINGS	***Fac Active Flag:***	-
State Other :		***Fac Inspection Count:***	0
Region:	02	***Date Last Inspection:***	-
Latitude:	40.72973	***Days Last Inspection:***	-
Longitude:	-73.9591		
Fac Derived Tribes:	-		
AIR IDs:	NY0000002610101090		
CAA Permit Types:	Minor Emissions		
CAA NAICS:	999999		
CAA SICS:	3089		
NPDES IDs:	-		
CWA Permit Types:	-		
CWA NAICS:	-		
CWA SICS:	-		
RCRA IDs:	-		
RCRA Permit Types:	-		
RCRA NAICS:	-		
SDWA IDs:	-		

SDWA System Types:	-
SDWA Compliance Status:	-
SDWA Snc Flag:	No
Fac Collection Meth:	ADDRESS MATCHING-HOUSE NUMBER
EJSCREEN Flag Us:	No
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.9591,%22y%22:40.72973,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110019327414
Industry:	Plastics and Resins

212	1 of1	NNE	0.47 / 2,506.56	6.41 / -6	21-07 BORDEN AVE 21-07 BORDEN AVE QUEENS NY	LST

Spill No:	9614479	**REM Phase:**	0
Site ID:	104312	**UST Trust:**	False
DER Facility ID:	92184	**Spill Date:**	03/15/1997 12:15:00 PM
CID:	199	**Rcvd Date:**	03/15/1997 12:30:00 PM
Program Type:	ER	**CAC Date:**	
SWIS Code:	4101	**Insp Date:**	
Contribute Factor:	Tank Overfill	**Close Date:**	02/25/2003 12:00:00 AM
Water Body:		**Create Date:**	03/15/1997 12:00:00 AM
Class:	C4	**Update Date:**	02/25/2003 12:00:00 AM
Meets Std:	False	**DEC Region:**	2
Penalty:	False	**Lead DEC:**	TOMASELLO
County:	Queens	**After Hours:**	True
Referred to:			
Reported by:	Responsible Party		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"TANK OVERFILL BY DRIVER - MATERAL SPILLED ONTO SIDEWALK - OIL CLEANED UP BY DRIVER"

Dec Remark:

""

Material Information

OP Unit ID:	1042165	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	339587	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	10.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	10.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	JOHN GOODWIN
Spiller Company:	MYSTIC TRANSPORT
Spiller Address:	1901 STEINWAY ST
Spiller City:	ASTORIA
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Name: JOHN GOODWIN
Contact Phone: (800) 635-3835
Contact Ext:
Latitude: 42.852158860
Longitude: -78.708566650

---

213 | **1 of1** | **SE** | **0.48 / 2,514.91** | **12.97 / 1** | **AFFIRMATIVE PIPE CLEANING**
275 NORTH HENRY Street
?? NY 0 | **SWF/LF**

Activity Number: [24T94]
Facility Name (Act):
Location Addr (Act):
Location Addr2 (Act):
City (Act):
State (Act):
Zip Code (Act):
County (Act):
East Coord (Act):
North Coord (Act):
Facility Name:
Location Addr:
Location Addr2:
City:
State:
Zip Code:
County:
East Coord:
North Coord:
Data Source: SWMF - Inactive Facility Lists

Facility Name (InAct): AFFIRMATIVE PIPE CLEANING
Location Addr (InAct): 275 NORTH HENRY Street
Loc Addr2(InAct):
City (InAct): ??
State (InAct): NY
Zip Code (InAct): 0
County (InAct): Kings
East Coord (InAct): 589100
North Coord (InAct): 4509800

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:
Activity Desc: Transfer station - permit
Regulatory Status:
Active: No
Dt of Last Inspection:
Expiration Dt:
Owner Type:
Owner Name:
Owner Address:
Owner Address2:
Owner City:
Owner State:
Owner Zip:
Owner Phone:
Owner Email:
Waste Types:

Authorization No: 2-6101-00136
Authrzation Issue Dt:
Operator Type:
Operator Name:
Phone No: 7180000000
Region: 2
Contact Name: EUGENE CAMALI; OWNER
Contact Address:
Contact Address2:
Contact City:
Contact State:
Contact Zip:
Contact Phone:
Contact Email:

---

214 | **1 of1** | **WSW** | **0.48 / 2,532.43** | **12.36 / 0** | **101-105 West Street**
101-105 West Street, Brooklyn
Brooklyn NY 11222 | **VCP**

Site Code: 57559
HW Code: V00231
Program: VCP
Site Class: C
Site Name: 101-105 West Street
Site Address: 101-105 West Street, Brooklyn
City: Brooklyn
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.730189621

Longitude:	-73.959590406
SWIS:	2401
Acres:	0.200
Record Added:	2000-11-30 16:06:00
Record Update:	2007-05-11 16:18:00
Updated by:	mobarrie
Site Code (Web):	V00231
Program Type (Web):	VCP
Site Name (Web):	101-105 West Street
Site Class (Web):	C
Address1 (Web):	101-105 West Street
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.959590406
Latitude (Web):	40.730189621
Site Code (GIS):	V00231
Site Name (GIS):	101-105 West Street
Program (GIS):	VCP
Site Class (GIS):	C
Address1 (GIS):	101-105 West Street, Brooklyn
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Site Class Desc (Web):	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH:	Soils contaminated with metals and semi-volatile organic compounds were identified at this site. Contaminated soils have either been excavated and disposed of offsite or are covered by a concrete slab or the onsite building, thereby minimizing the potential for direct contact exposures. Groundwater has not been impacted, therefore there is no potential for ingestion exposures. Volatile organic compounds were not detected at this site therefore, inhalation via soil vapor intrusion is not a potential exposure pathway .

Description:

101-105 West Street is located in the Greenpoint area of Brooklyn, NY 10310, Block 2556, Lot 58. The site is a 0.2-acre parcel used as a construction material storage yard. It is located between Kent Street and Java Street, on the west side of West Street. A commercial property borders the site to the east. The intended use of the site remains to be a construction material storage yard. The surrounding uses are mainly residential with some commercial divisions. Contamination at the site was predominantly in the soil and represented by Semi Volatile Organic Compounds and metals, and resulted from historic fill and uncontrolled dumping of oil and oil-related products from trucks loading construction materials. The Remedial Investigation work plan was approved in 1999 and the RI was completed in 2000. The groundwater is 8-10 feet below ground. The soil is sandy and it is covered with 3-4 feet of fill material. The Remedial Work Plan was approved in 2001 and the field remedial work was completed in 2002. The remedy involved excavation of the entire site and off site disposal. Clean backfill material has been placed in the former excavation. Remedial work at the site is completed.

Assessment:

The contaminants of concern in soil at the site were Semi Volatile Organic Compounds (SVOCs)and heavy metals. The groundwater has not been impacted by the contaminants. In 1998, the Pase I and Phase II Environmental Site Aassessment have revealed that the contaminants of concern in soil were above TAGM 4046 RSCO. The SVOCs had excedences ranging from non detected to Benzo(a)anthracene 43ppm, benzo(a)fluoranthene 1500ppm, benzo(b)fluoranthene 41ppm, benzo(k)fluoranthene 26ppm, benzo(a)pyrene 41ppm, Chrysene 38ppm,Dibenzofuran 12ppm. Some of the havy metal excedences were Arsenic 52ppm, Selenium 5.6ppm, Chromium 49ppm, Cadmium 12.5ppm, Lead 1930ppm,Zinc 1490ppm, Mercury 3.5 ppm. The source was presumed to be in the fill material and also produced by uncontrolled dumping. During the remedial phase, the site has been excavated and the end point samples showed that the concentrations of the contaminats levels were very close to TAGM 4046 RSCO. The excavation has been backfilled with clean soil. The remediation was completed in 2002.

Materials Information

Waste Name: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: LEAD
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 04
Sub Type: ZZZ
Owner Name:
Owner Company: SAFEWAY CONSTRUCTION ENTERPRISES INC
Owner Street: 105-107 WEST STREET
Owner Street 2:
Owner City: BROOKLYN
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 01
Sub Type: ZZZ
Owner Name:
Owner Company: LAUREL HILL REALTY CORP
Owner Street: 10 LINDEN STREET
Owner Street 2:
Owner City: NEW HYDE PARK
Owner State: NY
Owner Zip: 11040
Country: United States of America

Owner Op: 06
Sub Type: ZZZ
Owner Name:
Owner Company: Laurel Hill Realty Co.
Owner Street: 10 LINDEN STREET
Owner Street 2:
Owner City: NEW HYDE PARK
Owner State: NY
Owner Zip: 11040
Country: United States of America

Projects Information

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2002-07-31 00:00:00
End Status: ACT
Operable Unit ID: 3954
Operable Unit: 01
Operable Unit Desc: D2-0023-00-05
Code Name: Remedial Investigation

Environmental Remediation

Operable Unit: 01
Contaminants: anthracene, benzo(a)pyrene, lead

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
215	1 of1	ESE	0.48 / 2,556.23	13.63 / 2	MEEKER AVENUE PLUME Meeker Avenue BROOKLYN NY 11222	NPL

EPA ID: NYN000203407
Data Source: U.S. EPA Superfund Program. Source: SEMS Superfund Public User Database. FOIA4 All Final NPL Sites. Retrieved on 25 Sept 2024; U.S. EPA Site Boundaries Shapefile Download; Superfund NPR Sites with Status Information

NPL (FOIA-004 All Final NPL Sites)

NPL Status Dt: 03/16/22
Federal Facility: No
SAA (Superfund Alt):
NAI: No
NA Entity (NAI Status):
Site Name: MEEKER AVENUE PLUME
Address: Meeker Avenue
City: BROOKLYN
Zip: 11222
State: NY
Region: 02
County: KINGS
Latitude: +40.725409
Longitude: -73.935904

NPL (Superfund Sites List)

SEMS ID: 203407
SITS ID: 1969
Site Score: 50
Status: NPL Site
Proposed Date: 9/9/2021
Listing Date: 3/16/2022
NOID Date:
Deletion Date:
Site Name: Meeker Avenue Plume
City: Brooklyn
Site Listing Narrative: NYN000203407 (PDF)
Site Progress Profile: Meeker Avenue Plume
Proposed Fr Notice: 09/09/2021 (PDF)
Final Fr Notice: 03/16/2022 (PDF)
NOID Fr Notice:
Deletion Fr Notice:
Restoration Fr Notice:
Notice of Data Availability:
Partial Deletion: No
Constr Complete No:
Constr Complete Dt:
Region: 2
State: New York
County: Kings
Latitude: 40.725409
Longitude: -73.935904

NPL (EPA Boundaries)

EPA Program: Superfund Remedial
Npl Status Code: F
Federal Facility Deter Code: No
Region Code: 2
Site Contact Name: John Brennan
Site Contact Email: brennan.john.f@epa.gov
Feature Info Url: https://cumulis.epa.gov/supercpad/cursites/csitinfo.cfm?id=0203407
Feature Info Url Desc: Site profile page
Site Feature Class: 5
Site Feature Type: Total Site Polygon/OU Aggregation
Site Feature Name: Meeker Avenue Plume Site Site Boundary
Site Feature Description: The Meeker Avenue Plume site is in the Greenpoint/East Williamsburg area of Brooklyn.
Projection: R2_Contiguous_Albers_Equal_Area_Conic, SR-ORG:8974
Sf Geospatial Data Disclaimer: The Agency is providing this geospatial information as a public service and does not vouch for the accuracy, completeness, or currency of data. Data provided by external parties is not independently verified by EPA. This
GIS Area: 217.59480991
Gis Area Units: Acres
Primary Telephone No: (212) 637-3881

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

data is made available to the public strictly for informational purposes. Data does not represent EPA's official position, viewpoint, or opinion, express or implied. This information is not intended for use in establishing liability or calculating Cost Recovery Statutes of Limitations and cannot be relied upon to create any rights, substantive or procedural, enforceable by any party in litigation with the United States or third parties. EPA reserves the right to change these data at any time without public notice.

Addr Comment:
URL Alias Txt: https://www.epa.gov/superfund/Meeker-Avenue-Plume

---

216 | ***1 of1*** | ***E*** | ***0.48 / 2,556.34*** | ***2.38 / -10*** | ***SUMMIT CARTING CORP***
427 Greenpoint Ave
Brooklyn NY 11222 | ***SWF/LF***

Activity Number:	[24W]	***Facility Name (InAct):***	SUMMIT CARTING CORP
Facility Name (Act):		***Location Addr (InAct):***	427 Greenpoint Ave
Location Addr (Act):		***Loc Addr2(InAct):***	
Location Addr2 (Act):		***City (InAct):***	Brooklyn
City (Act):		***State (InAct):***	NY
State (Act):		***Zip Code (InAct):***	11222
Zip Code (Act):		***County (InAct):***	Kings
County (Act):		***East Coord (InAct):***	589173
East Coord (Act):		***North Coord (InAct):***	4509596
North Coord (Act):			
Facility Name:			
Location Addr:			
Location Addr2:			
City:			
State:			
Zip Code:			
County:			
East Coord:			
North Coord:			
Data Source:	SWMF - Inactive Facility Lists		

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		***Authorization No:***	0
Activity Desc:	C&D processing - registration	***Authrzation Issue Dt:***	
Regulatory Status:	Permit	***Operator Type:***	
Active:	No	***Operator Name:***	
Dt of Last Inspection:		***Phone No:***	
Expiration Dt:		***Region:***	2
Owner Type:	Private	***Contact Name:***	
Owner Name:	SUMMIT CARTING CORP	***Contact Address:***	
Owner Address:	425 GREENPORT AVE.	***Contact Address2:***	
Owner Address2:		***Contact City:***	
Owner City:	BROOKLYN	***Contact State:***	
Owner State:	NY	***Contact Zip:***	
Owner Zip:		***Contact Phone:***	
Owner Phone:	7183926858	***Contact Email:***	
Owner Email:			
Waste Types:			

---

217 | ***1 of1*** | ***N*** | ***0.49 / 2,589.47*** | ***7.73 / -4*** | ***51-02 21ST ST***
51-02 21ST ST
LONG ISLAND CITY NY | ***LST***

Spill No:	8806127	***REM Phase:***	0
Site ID:	189954	***UST Trust:***	False
DER Facility ID:	158514	***Spill Date:***	10/20/1988 10:00:00 AM
CID:		***Rcvd Date:***	10/20/1988 10:17:00 AM
Program Type:	ER	***CAC Date:***	
SWIS Code:	4101	***Insp Date:***	
Contribute Factor:	Tank Test Failure	***Close Date:***	07/19/2004 12:00:00 AM
Water Body:		***Create Date:***	10/31/1988 12:00:00 AM
Class:	C4	***Update Date:***	08/02/2004 12:00:00 AM
Meets Std:	False	***DEC Region:***	2

Penalty:	False	**Lead DEC:**	SMSANGES
County:	Queens	**After Hours:**	False
Referred to:			
Reported by:	Tank Tester		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"10K TK SYS FAILED PETRO, WOULDN'T MAINTAIN LEVEL IN STAND PIPE."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND AUSTIN - SPILL ORIG. ASSIGNED TO BATTISTA 11/04/93: MID COUNTY MECH. PERMANENTLY TOOK TANK OUT OF SERVICE 12/88 AND INSTALLED A NEW TANK 6/89. 12/19/2001 Sangesland spoke with Stephine Davis from FPM Group (631-737-6200 ext228). She called asking what can be done to close out this spill report. Apparently FPM Group started working on the site in 1993. At that time the Free Product plume (from a buried heating oil tank) was defined. Property is approx 1 acre and is a picture framing company in a 5 story building Two belt skimmer wells were installed in 1993 and have been operating ever since. Product was skimmed off, separated, water has been drummed and removed from the site and product piped back into the heating oil tank to be used in the building burner. The building owner has been operating the system and now says there is very little product in the skimmers. Sangesland told Ms. Davis to submit a report (with as much DEC correspondance as possible in the appendix). The report should include a write up (1-2 page) of what the original problem was, what investigation/delineation was done and how the system has operated for the last 8 years. Sangesland said the area needs to once again be delineated to confirm the plume is gone. Suggested geo-probe in the area of the plume. Finally the environmental consultant will need to define how the dissolved product will be addressed from now on. 11/19/2003 Sangesland reviewed a report by Gregory Scott of Roux Associates (631-232-2600) The report outlines the work done on the site between 1988 and 2002. Belt skimmers were installed in 2 wells and pulled out 150 gallons of oil over a period of years. These skimmers were shut down in 2002 and this letter was requesting formal approval to shut them down. Since the floating product was removed, Roux would like the DEC to close out the case..... NO. DEC is requesting GW samples from each of the existing wells tested to method 8270 and 8021. Depending on the concentration levels, additional remedial work may be required. 2/10/2004 Roux Associates Inc submitted a report dated 1/29/04. This report stated that slight traces of measurable floating product is present in the onsite wells . This statement requires the DEC to maintain this as an open case. 3/4/2004 Roux Associates stated that they will do another round of sampling of the wells and submit the results soon . 3/23/2004 Roux submitted a letter dated 3/22/2004 which states no measurable floating product is present in the onsite wells. Though monitoring well MW-4 contained an absorbent sock with minimal product staining No testing of these groundwater samples was done. June 2004 - Sangesland and Austin made a site visit and concluded the spill should be closed out. DEC requested a final report with certain information documented. 7/19/2004 - Sangesland reviewed a report from Roux associates. All of the requested information was included. Based on this report, the former problem at the site has been remediated and now the site has very minor trace hits which may or may not be related to the original problem or from off site locations. Based on the industrial nature of the site and the fact that there are no impacts to human contact the DEC has closed out this case. "

Material Information

OP Unit ID:	922957	**Med in Air:**	False
OU:	01	**Med GW:**	True
Material ID:	454482	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	-1.00	**Med Surf:**	False
Units:	L	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	AMJ REALTY CO
Spiller Address:	SAME
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.741057200
Longitude:	-73.949787350

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tank Test Information

Spill Tank ID:	1534786	***Source:***	
Tank No:		***Leak Rate:***	.00
Tank SIze:	0	***Gross Fail:***	
Material:	0001	***Modified by:***	Spills
EPA UST:		***Last Modified:***	2004-10-01 04:00:45.140000000
UST:		***Test Method:***	00
Cause:			
Alt Test Method:	Unknown		

---

218 | ***1 of1*** | ***ENE*** | ***0.50 / 2,622.32*** | ***4.70 / -7*** | ***LEXUS TRANSFER AND RECYCLING INC.***
3200 RAILROAD AVENUE
Long Island city NY 11101 | ***SWF/LF***

Activity Number:	[41W82]	***Facility Name (InAct):***	LEXUS TRANSFER AND RECYCLING INC.
Facility Name (Act):		***Location Addr (InAct):***	3200 RAILROAD AVENUE
Location Addr (Act):		***Loc Addr2(InAct):***	
Location Addr2 (Act):		***City (InAct):***	Long Island city
City (Act):		***State (InAct):***	NY
State (Act):		***Zip Code (InAct):***	11101
Zip Code (Act):		***County (InAct):***	Queens
County (Act):		***East Coord (InAct):***	589500
East Coord (Act):		***North Coord (InAct):***	4509900
North Coord (Act):			
Facility Name:			
Location Addr:			
Location Addr2:			
City:			
State:			
Zip Code:			
County:			
East Coord:			
North Coord:			
Data Source:	SWMF - Inactive Facility Lists		

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		***Authorization No:***	
Activity Desc:	C&D processing - registration	***Authrzation Issue Dt:***	
Regulatory Status:		***Operator Type:***	
Active:	No	***Operator Name:***	
Dt of Last Inspection:		***Phone No:***	7187842929
Expiration Dt:		***Region:***	2
Owner Type:		***Contact Name:***	PETER EVANLELISTA
Owner Name:		***Contact Address:***	
Owner Address:		***Contact Address2:***	
Owner Address2:		***Contact City:***	
Owner City:		***Contact State:***	
Owner State:		***Contact Zip:***	
Owner Zip:		***Contact Phone:***	
Owner Phone:		***Contact Email:***	
Owner Email:			
Waste Types:			

---

219 | ***1 of1*** | ***E*** | ***0.51 / 2,672.69*** | ***3.42 / -9*** | ***460 Kingsland Avenue***
460 Kingsland Avenue
Brooklyn NY 11222 | ***SHWS***

Site Code:	415641
HW Code:	224135
Program:	HW
Site Class:	P
Site Name:	460 Kingsland Avenue

Site Address:	460 Kingsland Avenue
City:	Brooklyn
Zip:	11222
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.732500000
Longitude:	-73.941388889
SWIS:	2401
Acres:	3.500
Record Added:	2009-06-25 10:07:00
Record Update:	2023-05-11 12:44:00
Updated by:	HMDUDEK
Site Code (Web):	224135
Program Type (Web):	HW
Site Name (Web):	460 Kingsland Avenue
Site Class (Web):	P
Address1 (Web):	460 Kingsland Avenue
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.941388889
Latitude (Web):	40.732500000
Site Code (GIS):	224135
Site Name (GIS):	460 Kingsland Avenue
Program (GIS):	HW
Site Class (GIS):	P
Address1 (GIS):	460 Kingsland Avenue
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Site Class Desc (Web):	Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Assess DOH:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Description:

Location: The site is located at 460 Kingsland Avenue in the Greenpoint section of Brooklyn, New York (Figure 1). 460 Kingsland Avenue is located within a commercial/industrial area and is bordered by Newtown Creek to the east (which has served as an industrial water way for nearly 140 years), Kingsland Avenue to the west, Greenpoint Avenue (John Jay Byrne) Bridge to the north, and OU-4 to the south. To the east, Newtown Creek has been designated a Federal Superfund Site and is under the jurisdiction of the United States Environmental Protection Agency (USEPA). Site Features: The property is composed of an approximate 3.55-acre parcel, identified as Block 2612 Lot 20 on the Brooklyn tax map. Land surface elevations are approximately 7 feet above mean sea level (AMSL) within the southeastern portion of and gradually rise to approximately 11 feet (AMSL) within the northwestern portion of the site. Currently, the site contains two abutting one-story buildings. Current Zoning and Land Use: The property is zoned M3-1 for heavy manufacturing and industrial use. Exterior areas are paved and used for parking and storage. The site is subleased to numerous third parties for parking, storage, and for use as office space. Past Use of the Site: Historical maps indicate the site and surrounding areas were undeveloped marshlands until the late 1800s when the land was filled for industrial development. The northern portion of the site was operated by the Columbus Distilling Company and the Chris Cunningham Boiler Works from approximately 1892 to 1919. The southern portion of the site was operated by ExxonMobil's predecessors as part of a petroleum refinery operation from approximately 1892 to 1920. By approximately 1920, refinery operations had expanded to include the entirety of 460 Kingsland Avenue. The refinery operations within the site continued until 1966. Under ExxonMobil's former operations, 460 Kingsland Avenue also served as a petroleum bulk storage yard. An oil water separator (OWS) was located along southern site boundary. Based on a review of historic aerial photographs, the OWS appears to have been filled sometime between 1961 and 1966. In 1967,

ExxonMobil's predecessors sold the property to a freight company and a trucking terminal was built, which currently remains on-site. On or about August 29, 1981, a former site owner reported that the bulkhead had collapsed into Newtown Creek, along with considerable amounts of fill/soil, asphalt parking lot and concrete curb stop. The bulkhead collapse was repaired with fill and a new steel sheet pile bulkhead was installed along the property. As documented in the Updated PCB Source Evaluation Report (September 7, 2012), PCB contamination in this area appears to be attributable to PCB-laden fill materials associated with the bulkhead reconstruction. Site Geology and Hydrogeology: The stratigraphic units underlying the site form three distinct hydrogeologic units; the shallow aquifer, the shallow confining unit, and, the regional aquifer. The shallow aquifer is primarily comprised of the saturated fill materials deposited above the historical creek and marsh sediments. The depth to groundwater in the shallow aquifer varies from approximately 1.5 to 8.5 feet below land surface (ft/bls) within the site and the saturated thickness of the shallow aquifer within the site is typically less than 10 feet. The shallow confining unit is made up of deposits from the historical creek and marsh sediments. Historically, marsh land and open water covered the entirety of 460 Kingsland Avenue. The shallow confining unit ranges in thickness from approximately 5 to 20 feet across the site. The shallow confining unit has very low groundwater movement rates such that, it isolates the shallow aquifer from the underlying regional aquifer. This causes confined or semi-confined conditions within the regional aquifer. The geology of the shallow confining unit is identified as a clay or peat material with varying levels of silt. The regional aquifer is found throughout the site below the shallow aquifer and shallow confining unit. It is made up of fine to medium grained sands, with varying amounts of silt and coarser materials and was found to be at least 10 to 15 feet in thickness. Groundwater movement is consistent in the regional aquifer compared to the shallow aquifer, due to the sand and silty sand material that comprise this layer.

Assessment:

Soil sampling indicates that hazardous waste disposal has occurred at the site. Groundwater sampling at the site indicates that PCBs may be present in the shallow groundwater at levels above the NYSAWQS. Additional site characterization is necessary to examine complete nature and extent in groundwater and soil and to determine if a significant amount of waste is present. Petroleum impacts are present in site in shallow and deeper soils, and in groundwater from former refining operations on and near the site.

Owner Information

Owner Op:	01
Sub Type:	NNN
Owner Name:	SALVATORE TROVATO
Owner Company:	REVEAL KINGSLAND LLC
Owner Street:	X
Owner Street 2:	
Owner City:	X
Owner State:	NY
Owner Zip:	11222
Country:	United States of America

Owner Op:	01
Sub Type:	NNN
Owner Name:	FRANK GALASSO
Owner Company:	NEWSAG LLC
Owner Street:	X
Owner Street 2:	
Owner City:	X
Owner State:	NY
Owner Zip:	11222
Country:	United States of America

Owner Op:	01
Sub Type:	02
Owner Name:	
Owner Company:	NEW SAG LLC
Owner Street:	2 GALASSO PLACE
Owner Street 2:	
Owner City:	MASPETH
Owner State:	NY
Owner Zip:	11378
Country:	United States of America

Projects Information

Project Code:	01
Project Desc:	Site Caracterization
Project Refer Name:	Supplemental Site Characterization
End Date:	2010-01-22 00:00:00
End Status:	ACT
Operable Unit ID:	1171973
Operable Unit:	01

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Operable Unit Desc: Remedial Program
Code Name: Site Characterization

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2019-02-27 00:00:00
End Status: ACT
Operable Unit ID: 1330175
Operable Unit: 01A
Operable Unit Desc: PCB IRM
Code Name: Remedial Design

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name: Source Area Evaluation
End Date: 2016-10-31 00:00:00
End Status: ACT
Operable Unit ID: 1330175
Operable Unit: 01A
Operable Unit Desc: PCB IRM
Code Name: Remedial Investigation

Environmental Remediation

Operable Unit: 01A
Contaminants: 1,2,4-trichlorobenzene, 1,3,5-trimethylbenzene, PCB aroclor 1248, PCB aroclor 1254, PCB aroclor 1260, acetone, arsenic, benzene, benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chromium, chrysene, copper, dibenz[a,h]anthracene, ethylbenzene, indeno(1,2,3-cd)pyrene, lead, mercury, toluene, xylene (mixed)

Operable Unit: 01
Contaminants: 1,2,4-trichlorobenzene, 1,3,5-trimethylbenzene, PCB aroclor 1248, PCB aroclor 1254, PCB aroclor 1260, acetone, arsenic, benzene, benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chromium, chrysene, copper, dibenz[a,h]anthracene, ethylbenzene, indeno(1,2,3-cd)pyrene, lead, mercury, toluene, xylene (mixed)

Operable Unit: 00
Contaminants: 1,2,4-trichlorobenzene, 1,3,5-trimethylbenzene, PCB aroclor 1248, PCB aroclor 1254, PCB aroclor 1260, acetone, arsenic, benzene, benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chromium, chrysene, copper, dibenz[a,h]anthracene, ethylbenzene, indeno(1,2,3-cd)pyrene, lead, mercury, toluene, xylene (mixed)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
220	1 of1	SE	0.62 / 3,266.18	19.21 / 7	**Former Spic and Span Cleaners and Dyers Inc.** **315 Kingsland Avenue** **Brooklyn NY 11222**	SHWS

Site Code: 405850
HW Code: 224129
Program: HW
Site Class: 02
Site Name: Former Spic and Span Cleaners and Dyers Inc.
Site Address: 315 Kingsland Avenue
City: Brooklyn
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.727586000
Longitude: -73.942222000
SWIS: 2401
Acres: 0.510
Record Added: 2008-10-28 09:49:00
Record Update: 2024-04-25 15:58:00
Updated by: HMDUDEK
Site Code (Web): 224129

Program Type (Web):	HW
Site Name (Web):	Former Spic and Span Cleaners and Dyers Inc.
Site Class (Web):	02
Address1 (Web):	315 Kingsland Avenue
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.942222000
Latitude (Web):	40.727586000
Site Code (GIS):	224129
Site Name (GIS):	Former Spic and Span Cleaners and Dyers Inc.
Program (GIS):	HW
Site Class (GIS):	02
Address1 (GIS):	315 Kingsland Avenue
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	This classification is assigned to a site at which: a. the disposal of hazardous waste has been confirmed and the presence of such hazardous waste or its components or breakdown products represents a significant threat to public health or the environment: or b. hazardous waste disposal has not been confirmed, but the site has been listed on the Federal National Priorities List (NPL).
Site Class Desc (Web):	This classification is assigned to a site at which: a. the disposal of hazardous waste has been confirmed and the presence of such hazardous waste or its components or breakdown products represents a significant threat to public health or the environment: or b. hazardous waste disposal has not been confirmed, but the site has been listed on the Federal National Priorities List (NPL).
Assess DOH:	Exposure to site-related contamination in drinking water and soil is unlikely since area homes and businesses are supplied with public water and contaminants are below the ground surface. Since the possibility exists for vapors from site-related chemicals to migrate into nearby homes and businesses, soil vapor intrusion sampling will continue in the area and data evaluated as they become available.

Description:

Location: The 0.51 acre site is located at 313-315 Kingsland Avenue in the Greenpoint section of Kings County (Borough of Brooklyn, New York City). The site is located on the southwest corner of the intersection of Kingsland and Norman Avenues. Site Features: The site is completely covered by multiple buildings of varying construction and height. Numerous other commercial and industrial properties are located to the north, east, and west of the site. A large residential area is located immediately south of the site, and extends south along both Kingsland Avenue and Monitor Street. A large sewage treatment plant is located approximately 1/2 mile north of the site. Current Zoning/Use(s): The site is zoned for both residential and light manufacturing. The site is partially occupied, and is utilized for a variety of purposes (residential, warehousing, etc.). Historical Use(s): The Department began a Site Characterization in this area during the Spring of 2007 as part of a plume trackdown investigation (Meeker Avenue Plume Trackdown, DEC Site ID No. 224121). This particular location was specifically targeted for investigation based on Sanborn fire insurance map data indicating that the site was operated by Spic and Span Cleaners and Dyers, Inc. (a.k.a. Eastern District Dye Works) from the early 1900's until the mid-1960's. The Meeker Avenue Plume Trackdown Site Characterization in the area of this site was conducted in several phases, and was completed in the Summer of 2009. Operable Units: The site was divided up into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. Operable Unit 1 (OU-01) consists of the on-site source area which includes the sidewalk adjacent to 315 Kingsland Avenue. All remaining off-site contamination will be investigated and remediated separately as Operable Unit 2 (OU-02). 300 Kingsland Avenue is suspected to be part of the former Spic and Span operation and will be addressed as part of OU-02.. Site Geology and Hydrogeology: The site is underlain by a fill unit (0.5-10' thick), a stratified sand unit with some to no fines (over 120' thick), a discontinuous glacial till unit within the sand unit (0.5-50' thick), a discontinuous clayey silt unit within the sand unit (0.5-25' thick), and the Raritan Formation (approximately 138.5' below ground surface). Groundwater is approximately 11-25' below ground surface in the vicinity of the site. Groundwater flows north to northeast toward Newtown Creek, which lies approximately 1,300' northeast of the site.

Assessment:

Nature and Extent of Contamination: - Groundwater The primary contaminant of concern at the site is tetrachloroethene (PCE). PCE has been found in shallow groundwater at concentrations up to 39,000 ppb, and in deep groundwater at concentrations up to 170,000 ppb, exceeding the Part 703.5 class GA standard of 5 ppb. PCE DNAPL has also been found on-site at concentrations up to 1,000,000 ppm (100%) in deep monitoring wells. Trichloroethene (up to 5,000 ppb), cis-1,2-dichloroethene (up to 14,000 ppb), and vinyl chloride (up to 3,200 ppb) have also been found in shallow groundwater at concentrations above their respective Part 703.5 class GA standards (5 ppb each). - Soil PCE has been found in soil up to 290,000 ppm, well above the soil cleanup objective for unrestricted use (1.3 ppm). -Soil Vapor and Indoor Air Concentrations of PCE in soil vapor have been found up to 8,200,000 ug/m^3, and in indoor air up to 170 ug/m^3. Concentrations of TCE in soil vapor have been found up to 32,000 ug/m^3, and in indoor air up to 12 ug/m^3. Significant Threat: The site poses a significant threat to public health and the environment.

Materials Information

Waste Name: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 19
Sub Type: C01
Owner Name:
Owner Company: Brooklyn Community Board #1
Owner Street: 435 Graham Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 01
Sub Type: 05
Owner Name: FRANK CHAN
Owner Company: DOUBLE STAR REALESTATE, INC.
Owner Street: 307 KINGSLAND AVENUE
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 01
Sub Type: 05
Owner Name: Sam Gee
Owner Company: Delta Property Associates
Owner Street: 276 Grand Street
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10002
Country: United States of America

Owner Op: 01
Sub Type: 05
Owner Name: Jean Chau
Owner Company: DOUBLE STAR REALESTATE, INC.
Owner Street: 307 KINGSLAND AVENUE
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 19
Sub Type: C04
Owner Name: David Camara
Owner Company: Brooklyn Public Library - Leonard Branch
Owner Street: 81 Devoe Street
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11211
Country: United States of America

Owner Op: 01
Sub Type: 01
Owner Name:
Owner Company: DELTA PROPERTY ASSOCIATES
Owner Street: 260 NORMAN AVENUE
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

HW Extra Information

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: ldennist
Record Added: 2008-10-28 12:22:00
Record Updated: 2013-09-20 14:09:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Projects Information

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2015-05-18 00:00:00
End Status: ACT
Operable Unit ID: 1255371
Operable Unit: 01B
Operable Unit Desc: PCE DNAPL recovery
Code Name: Remedial Design

Project Code: 05
Project Desc: Remedial Action
Project Refer Name: SVI Mitigation
End Date: 2013-03-04 00:00:00
End Status: ACT
Operable Unit ID: 1182668
Operable Unit: 01A
Operable Unit Desc: IRM SVI mitigation
Code Name: Remedial Action

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2017-10-25 00:00:00
End Status: ACT
Operable Unit ID: 1290229
Operable Unit: 01C
Operable Unit Desc: soil contamination at 300 Kingsland Avenue
Code Name: Remedial Design

Environmental Remediation

Operable Unit: 01A
Contaminants: tetrachloroethene (PCE)

Operable Unit: 01
Contaminants: tetrachloroethene (PCE)

Operable Unit: 02
Contaminants: tetrachloroethene (PCE)

Operable Unit: 01C

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants: tetrachloroethene (PCE)

Operable Unit: 01B
Contaminants: tetrachloroethene (PCE)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
221	1 of1	WNW	0.63 / 3,352.04	0.00 / -12	NEWTOWN CREEK SOUTH END OF IVY HILL ROAD BROOKLYN, QUEENS NY 1122	SUPERFUND ROD

EPA ID: NYN000206282
Site ID: 0206282
NPL Status: Final
Non NPL Status:
Region: 02
EPA ID (SFDB): NYN000206282
Site Name (SFDB): NEWTOWN CREEK
State (SFDB): NY
Region (SFDB): 02
Data Source(s): SEMS Superfund Public User Database; Searchable Superfund Decision Documents Database (SFDB)

Superfund Decision Documents Details (SFDB)

Doc ID: 609882
Date: 04/12/2021
Pub No:
Description:
PDF Link: https://semspub.epa.gov/src/document/02/609882
Title: RECORD OF DECISION FOR OU2 FOR THE NEWTOWN CREEK SITE

Completed RODs, ROD Amendments and ESDs (FOIA 2) Details

Seq ID: 3
Actual Comp Date: 04/12/21
Action Name: Record of Decision (ROD)
Operable Unit Name: CSO DISCHARGES

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
222	1 of1	SSW	0.65 / 3,412.97	8.07 / -4	Former Presto Electroplating 9 North 15th Street Brooklyn NY 11222	SHWS

Site Code: 651928
HW Code: 224397
Program: HW
Site Class: P
Site Name: Former Presto Electroplating
Site Address: 9 North 15th Street
City: Brooklyn
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.725005782
Longitude: -73.956919367
SWIS: 2401
Acres: 0.145
Record Added: 2023-05-11 08:06:00
Record Update: 2023-07-05 13:32:00
Updated by: WBBENNET
Site Code (Web): 224397
Program Type (Web): HW
Site Name (Web): Former Presto Electroplating
Site Class (Web): P
Address1 (Web): 9 North 15th Street
Address2 (Web):
Locality (Web): Brooklyn

Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.956919367
Latitude (Web):	40.725005782
Site Code (GIS):	224397
Site Name (GIS):	Former Presto Electroplating
Program (GIS):	HW
Site Class (GIS):	P
Address1 (GIS):	9 North 15th Street
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Site Class Desc (Web):	Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Assess DOH:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Description:

Site Location: The proposed site is located at 9 North 15th Street in Kings County, and is identified as Block 2614, Lot 16 on the New York City Tax Map. Site Features: The site is a 0.145-acre lot including one-story warehouse building. Current Zoning and Land Use: The site is zoned M102 (manufacturing district) and is currently unoccupied. The site was used by Linaire Sheet Metal Corp. between 1994 to 2021. The surrounding parcels are currently used for a combination of light manufacturing, commercial uses, and parking. Past Uses: The existing building was constructed in early 1930's. Previous industrial uses include manufacturing, a construction company, a garage, and a sheet metal facility. From 1976 to 1995, the site was listed as a RCRA generator (EPA ID no. NYD001486885) of corrosive wastes, chromium, and electroplating treatment sludges. The facility operated as V E 2 Plating and as Presto Electro Plating Corp. Historically the electroplating operations extended onto the adjacent BCP site, 12 Franklin Street (C224286). Site Geology and Hydrogeology: The depth to groundwater is approximately five to nine feet below grade, based on groundwater elevations at sites in the surrounding area. Groundwater flows to the west/southwest through the site toward Bushwick Inlet but may be tidally influenced.

Assessment:

Soil, groundwater, soil vapor, and indoor air samples were collected at the site under an investigation overseen by NYC Office of Environmental Remediation between February and April of 2022. Nineteen soil borings were installed. Elevated levels of tetrachloroethene (PCE) and trichloroethene (TCE) were detected, with maximum concentrations of 100 parts per million (ppm) and 400 ppm respectively compared to their respective protection of groundwater soil cleanup objectives (POGSCOs) of 1.3 ppm and 0.47 ppm. Several semi-volatile organic compounds (SVOCs) and metals were detected above their respective unrestricted use SCOs (UUSCOs). One emerging contaminant, perfluorooctanesufonic acid (PFOS) (max. 9.6 ppb), was found above its protection of groundwater guidance value. Six permanent monitoring wells and three temporary monitoring wells were installed at the site. Groundwater flows west/southwest towards Bushwick Inlet, which is located approximately 250 feet from the site. Chlorinated Volatile Organic Compounds (CVOCs) were detected at concentrations exceeding ambient water quality standards including PCE (max. 570 parts per billion, or ppb), TCE (max. 65 ppb), cis-1,2-dichloroethene (max. 60 ppb), and vinyl chloride (max 55 ppb). Multiple PFAS compounds were also detected at concentrations exceeding guidance values. Two temporary soil vapor points were installed with co-located indoor air (IA) and sub-slab soil vapor (SV) samples taken at each location. Chlorinated VOCs were detected in both soil vapor and indoor air, including PCE (max. 32,000 micrograms per cubic meter, or ?g/m3 in soil vapor, max. 2.9 ?g/m3 in indoor air), TCE (max. 190,000 ?g/m3 SV, max. 4.2 ?g/m3 IA), cis-1,2-dichloroethene, or DCE (max. 1500 ?g/m3 SV, max. 0.1 ?g/m3 IA), and vinyl chloride (9.0 ?g/m3 SV, max. 0.1 ?g/m3 IA). According to NYSDOH decision matrices, the concentrations of PCE, TCE, and cis-1,2-DCE require mitigation.

Owner Information

Owner Op:	01
Sub Type:	03
Owner Name:	Mitchell Wieder
Owner Company:	Haplin Realty Corp.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Street: 57 Fox Lane
Owner Street 2:
Owner City: Dix Hils
Owner State: NY
Owner Zip: 11746
Country: United States of America

Owner Op: 04
Sub Type: 03
Owner Name: LINAIRE SHEET METAL INC.
Owner Company:
Owner Street: 3 N 15TH STREET
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

Environmental Remediation

Operable Unit: 01
Contaminants: tetrachloroethane, trichloroethene (TCE)

223	1 of1	E	0.67 / 3,518.37	17.96 / 6	36-04 Review Avenue 36-04 Review Avenue Long Island City NY 11101	SHWS

Site Code: 571316
HW Code: 241218
Program: HW
Site Class: N
Site Name: 36-04 Review Avenue
Site Address: 36-04 Review Avenue
City: Long Island City
Zip: 11101
County: Queens
Region: 2
Town: New York City
Latitude: 40.733861111
Longitude: -73.938388889
SWIS: 4101
Acres: 0.340
Record Added: 2018-06-08 15:53:00
Record Update: 2020-10-28 08:33:00
Updated by: SMQUANDT
Site Code (Web): 241218
Program Type (Web): HW
Site Name (Web): 36-04 Review Avenue
Site Class (Web): N
Address1 (Web): 36-04 Review Avenue
Address2 (Web):
Locality (Web): Long Island City
Zip Code (Web): 11101
County (Web): Queens
Longitude (Web): -73.938388889
Latitude (Web): 40.733861111
Site Code (GIS): 241218
Site Name (GIS): 36-04 Review Avenue
Program (GIS): HW
Site Class (GIS): N
Address1 (GIS): 36-04 Review Avenue
Address2 (GIS):
Locality (GIS): Long Island City
Zip Code (GIS): 11101
County (GIS): Queens
Site Class Desc: No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Site Class Desc (Web): No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Description:

This site entered into the Brownfield Cleanup Program on August 6, 2019. Please refer to site C241218.

Assessment:

This site entered into the Brownfield Cleanup Program on August 6, 2019. Please refer to site C241218.

Owner Information

Owner Op:	04
Sub Type:	E
Owner Name:	
Owner Company:	Allied Extruders
Owner Street:	36-08 Review Avenue
Owner Street 2:	
Owner City:	Long Island City
Owner State:	NY
Owner Zip:	11101
Country:	United States of America

Environmental Remediation

Operable Unit:	01
Contaminants:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
224	1 of1	NE	0.69 / 3,624.51	13.16 / 1	27-10 49th Avenue-OER 27-10 49th Avenue Long Island City NY 11101	SHWS

Site Code:	571772
HW Code:	241219
Program:	HW
Site Class:	N
Site Name:	27-10 49th Avenue-OER
Site Address:	27-10 49th Avenue
City:	Long Island City
Zip:	11101
County:	Queens
Region:	2
Town:	New York City
Latitude:	40.741115000
Longitude:	-73.942090000
SWIS:	4101
Acres:	0.880
Record Added:	2018-06-21 10:25:00
Record Update:	2020-10-28 08:17:00
Updated by:	CHPOST
Site Code (Web):	241219
Program Type (Web):	HW
Site Name (Web):	27-10 49th Avenue-OER
Site Class (Web):	N
Address1 (Web):	27-10 49th Avenue
Address2 (Web):	
Locality (Web):	Long Island City
Zip Code (Web):	11101
County (Web):	Queens
Longitude (Web):	-73.942090000
Latitude (Web):	40.741115000
Site Code (GIS):	241219
Site Name (GIS):	27-10 49th Avenue-OER
Program (GIS):	HW
Site Class (GIS):	N
Address1 (GIS):	27-10 49th Avenue
Address2 (GIS):	
Locality (GIS):	Long Island City
Zip Code (GIS):	11101
County (GIS):	Queens
Site Class Desc:	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced; c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.
Site Class Desc (Web):	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced; c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work

was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Description:

This site entered into the Brownfield Cleanup Program on August 6, 2019. Please refer to site C241218.

Assessment:

This site entered into the Brownfield Cleanup Program on August 6, 2019. Please refer to site C241218.

Owner Information

Owner Op: 01
Sub Type: E
Owner Name: Zach McHugh
Owner Company: Hunters Point SG, LLC
Owner Street: 10 West Forest Avenue
Owner Street 2:
Owner City: Engelwood
Owner State: NJ
Owner Zip: 07613
Country: United States of America

Owner Op: 04
Sub Type: E
Owner Name:
Owner Company: Carey Limousine
Owner Street: 27-10 49th Avenue
Owner Street 2:
Owner City: Long Island City
Owner State: NY
Owner Zip: 11101
Country: United States of America

Environmental Remediation

Operable Unit: 00
Contaminants:

Operable Unit: 01
Contaminants:

225	1 of1	NNW	0.71 / 3,732.29	15.23 / 3	KOSAN INDUSTRIAL CORP 5-49 49TH AVE LONG ISLAND CITY NY 11101-5610	RCRA CORRACTS

EPA Handler ID: NYD061949228
Gen Status Universe: No Report
Contact Name:
Contact Address: 5-49 , 49TH AVE , , LONG ISLAND CITY , NY, 11101 , US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: QUEENS
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 40.743827
Location Longitude: -73.95471
Recycler Activity?: NO

Recycler Activity Note: This facility has no indication of Recycling Activity.

Event/Area Details

Area Name: SITEWIDE
Event Code: CA075LO
Corrective Action Event Descri: CA PRIORITIZATION-LOW CA PRIORITY
Actual Date of Event: 20040113
Orig Sched Event Date:
New Sched Event Date:
Best Date: 20040113
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA210OT
Corrective Action Event Descri: REFERRED TO A NON-RCRA AUTHORITY-OTHER
Actual Date of Event: 19950425
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19950425
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA225NF
Corrective Action Event Descri: STABILIZATION MEASURES EVALUATION-NOT AMENABLE TO STABILIZATION (NOT FEASIBLE)
Actual Date of Event: 19950228
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19950228
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA075HI
Corrective Action Event Descri: CA PRIORITIZATION-HIGH CA PRIORITY
Actual Date of Event: 19930908
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19930908
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA050
Corrective Action Event Descri: RFA COMPLETED
Actual Date of Event: 19950425
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19950425
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA070NO
Corrective Action Event Descri: DETERMINATION OF NEED FOR AN INVESTIGATION-INVESTIGATION IS NOT NECESSARY
Actual Date of Event: 19950425
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19950425
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date: 19850513
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner: No
Smelting, Melting and Refining: No
Underground Injection Control: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19800818
Handler Name: KOSAN INDUSTRIAL CORP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: K078
Waste Code Description: DESCRIPTION

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: U031
Waste Code Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Hazardous Waste Code: U107
Waste Code Description: 1,2-BENZENEDICARBOXYLIC ACID, DIOCTYL ESTER (OR) DI-N-OCTYL PHTHALATE

Hazardous Waste Code: U112
Waste Code Description: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Hazardous Waste Code: U140
Waste Code Description: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U159
Waste Code Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Hazardous Waste Code: U161
Waste Code Description: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Code: U239
Waste Code Description: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19801119
Handler Name: KOSAN INDUSTRIAL CORP
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Part A

Waste Code Details

Hazardous Waste Code: U002

Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: U031
Waste Code Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Hazardous Waste Code: U107
Waste Code Description: 1,2-BENZENEDICARBOXYLIC ACID, DIOCTYL ESTER (OR) DI-N-OCTYL PHTHALATE

Hazardous Waste Code: U112
Waste Code Description: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Hazardous Waste Code: U140
Waste Code Description: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U159
Waste Code Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Hazardous Waste Code: U161
Waste Code Description: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Code: U239
Waste Code Description: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990708
Handler Name: KOSAN INDUSTRIAL CORP
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: KOSAN INDUSTRIAL CORP
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: KOSAN INDUSTRIAL CORP
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: STEPHEN GALGANO
Date Became Current:
Date Ended Current:
Phone: 212-277-3333
Street No:
Street 1: 465 LOGAN ST
Street 2:
City: OPERCITY
State: NY
Country:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source Type:	Part A	**Zip Code:**	99999
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	465 LOGAN ST
Name:	STEPHEN GALGANO	**Street 2:**	
Date Became Current:		**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:	212-277-3333	**Country:**	US
Source Type:	Implementer	**Zip Code:**	11208
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	465 LOGAN ST
Name:	STEPHEN GALGANO	**Street 2:**	
Date Became Current:		**City:**	OPERCITY
Date Ended Current:		**State:**	NY
Phone:	212-277-3333	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	465 LOGAN ST
Name:	STEPHEN GALGANO	**Street 2:**	
Date Became Current:		**City:**	BROOKLYN
Date Ended Current:		**State:**	NY
Phone:	212-277-3333	**Country:**	
Source Type:	Notification	**Zip Code:**	11208

Historical Handler Details

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	KOSAN INDUSTRIAL CORP
Receive Dt:	19990708
Generator Code Description:	Not a Generator, Verified
Handler Name:	KOSAN INDUSTRIAL CORP
Receive Dt:	19801119
Generator Code Description:	Not a Generator, Verified
Handler Name:	KOSAN INDUSTRIAL CORP
Receive Dt:	19800818
Generator Code Description:	Large Quantity Generator
Handler Name:	KOSAN INDUSTRIAL CORP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
226	1 of1	SW	0.76 / 4,003.90	8.28 / -4	Williamsburg – Former Pratt Refinery 26 N 12th St. Brooklyn NY 11211	SHWS

Site Code:	533192
HW Code:	224055A
Program:	HW
Site Class:	P
Site Name:	Williamsburg – Former Pratt Refinery
Site Address:	26 N 12th St.
City:	Brooklyn
Zip:	11211
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.724219499
Longitude:	-73.959631363
SWIS:	2401
Acres:	7.000
Record Added:	2016-10-03 15:06:00
Record Update:	2022-06-06 07:26:00
Updated by:	KATHOMPS

Site Code (Web):	224055A
Program Type (Web):	HW
Site Name (Web):	Williamsburg Former Pratt Refinery
Site Class (Web):	P
Address1 (Web):	26 N 12th St.
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11211
County (Web):	Kings
Longitude (Web):	-73.959631363
Latitude (Web):	40.724219499
Site Code (GIS):	224055A
Site Name (GIS):	Williamsburg – Former Pratt Refinery
Program (GIS):	HW
Site Class (GIS):	P
Address1 (GIS):	26 N 12th St.
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11211
County (GIS):	Kings
Site Class Desc:	Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Site Class Desc (Web):	Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Assess DOH:	The site is completely fenced, which restricts public access. However, persons who enter the site could contact contaminants in the soil by walking on the site, digging or otherwise disturbing the soil. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because there is no on-site building, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. However, the potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site development. Sampling indicates soil vapor intrusion is a potential concern for off-site buildings, however this may be attributable to contamination from an off-site source.

Description:

Location: The Williamsburg-Pratt Refinery site is located in a commercial/industrial area in the Williamsburg section of Brooklyn. The site comprises a single real estate parcel, Block 2277 Lot 1, at 26 N 12th St. It is approximately 7 acres in size and is located between Kent Ave. and the East River and between N 12th St. and Bushwick Inlet. Site Features: The site formerly included above ground petroleum bulk storage tanks, a 3 story office building, a one story cinder block garage, a fuel dispenser island, and a large asphalt paved area. All above ground structures, buildings and storage tanks, were dismantled and removed during the summer of 2019. Current Zoning and Land Use: Currently the site is vacant covered by concrete slabs and asphalt. The Block and Lot are zoned commercial and future use is anticipated as parkland. The land use in the surrounding area is currently a mix of industrial, commercial, residential, and parkland use. The nearest residential property is located approximately 2 blocks to the south. Past Use of the Site: A petroleum refinery operated on the site from circa 1870 into the early 1900s. Subsequently, the property was utilized as a major petroleum bulk storage facility until the early 2000s. Site Geology and Hydrogeology: The site is underlain by urban fill and varied glacial sediments consisting of outwash sand and gravel, till and lenticular clay more than 100 feet in thickness. The fluvial marsh silty clay to clay is encountered from approximately 5 to 25 feet below ground surface across the site. The groundwater table is approximately 6 feet below ground surface. Groundwater flows to the north northwest, toward Bushwick Inlet and the East River.

Assessment:

Soil sediment and groundwater samples were analyzed for volatile organic compounds (VOCs), semi volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), pesticides, metals, and the emerging contaminants per and polyfluorinated substances (PFAS) and 1,4 dioxane. Based on investigations conducted, the primary contaminants of concern include VOCs and SVOCs, and total metals in soil and groundwater. PFAS was found in groundwater samples. Nature and Extent Soil: Sampling results indicated that VOCs, SVOCs, pesticides, PCBs, metals and mercury were

detected above the applicable restricted residential use soil cleanup objectives (RRSCOs) or protection of groundwater soi cleanup objectives (PGWSCOs) in soil samples. VOCs: Petroleum VOCs consisting of benzene, toluene, ethylbenzene, total xylenes (collectively BTEX), isopropylbenzene, n propylbenzene, 1, 3, 5 trimethylbenzene, 1, 2, 4 trimethylbenzene, sec butylbenzene, 4 isopropyltoluene, and naphthalene were detected in many samples site wide. The soil boring logs indicate that the petroleum contamination extends from the surface to a depth of approximately 30 ft below ground surface (bgs). Petroleum VOC detections and concentrations increased with depth, a majority of them occurring in the area of the former bulk storage tanks. The highest number of samples containing petroleum VOCs occurred at the water table interface. The highest concentrations occurred at or below the water table (1 to 6 feet bgs) to approximately 25 30 ft below grade. Some samples containing BTEX were found at greater depths, which were associated with coal tar, as noted below. 1,2,4 Trimethylbenzene, naphthalene and BTEX (benzene, toluene, ethylbenzene and xylenes) were found most often and had the highest concentrations exceeding RRSCOs and PGWSOCs. 1,2,4 Trimethylbenzene concentrations ranged from 4.4 to 790 parts per million (ppm), exceeding the PGWSCO of 3.6 ppm. Naphthalene concentrations ranged from 17 to 2,500 ppm, exceeding the PGWSCO of 12 ppm. Benzene concentrations ranged from 0.7 to 19 ppm, exceeding the PGWSCO of 0.7 ppm; toluene concentrations ranged from 0.88 to 59 ppm, exceeding the PGWSCO of 0.7 ppm; ethylbenzene concentrations ranged from 1 to 120 ppm, exceeding the PGWSCO of 1 ppm; total xylenes concentrations ranged from 0.28 to 460 ppm, exceeding the PGWSCO of 0.26 ppm. The petroleum contamination is more prevalent along the southern boundary along 12th Street and around the former bulk storage tanks. This suggests that the site has been impacted by the former petroleum storage and fueling operations. SVOCs: SVOCs, primarily polycyclic aromatic hydrocarbons (PAHs), were detected in a majority of the soil borings site wide, primarily within the shallow soil samples associated with the historic fill (5 to 10 ft below grade), although some occurred at greater depths and were associated with coal tar. PAHs, specifically benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, chrysene, dibenz(a,h)anthracene, and indeno(1,2,3 c,d)pyrene, accounted for the highest percentage of SVOC samples exceeding RRSCOs or PGWSCOs, as applicable. Concentrations of benzo(a)anthracene (1.1 ppm to 230 ppm) and benzo(a)pyrene (1.1 to 76 ppm) found on site significantly exceed their RRSCO of 1 ppm. Concentrations of benzo(b)fluoranthene (1.1 ppm to 75 ppm) and chrysene (1.1 to 160 ppm) found on site exceed their RRSCO of 3.9 ppm. Concentrations of dibenz(a,h)anthracene (0.36 ppm to 11 ppm) found on site exceed the RRSCO of 0.33 ppm. Concentrations of indeno(1,2,3 c,d) pyrene (0.53 ppm to 34 ppm) found on site exceed the RRSCO of 0.5 ppm. The highest SVOC sample concentrations were phenanthrene, fluorene, fluoranthene, and naphthalene and found within the historic fill. Concentrations of phenanthrene (120 to 3,600 ppm), fluorene (120 to 1,500 ppm), naphthalene (200 to 2,500 ppm) and fluoranthene (160 to 1,600 ppm) found on site significantly exceed their RRSCO of 100 ppm. Coal Tar: The PAH and VOC (BTEX, noted above) analytical results indicate that coal tar was encountered in two borings from 20 to 50 feet, bgs. Coal tar was also identified in the field based upon photoionization detector(PID) readings, olfactory observations, and visual identification. The location of these borings is generally in the southeast and central portion of the site. Metals: Metals consisting of arsenic, barium, cadmium, total chromium, iron, cobalt, copper, lead, mercury, nickel, selenium and zinc were detected above RRSCOs. Metals exceeding the RRSCOs are found primarily within the shallow soils (5 to 10 feet, bgs) site wide within the historic fill. Arsenic, lead, and mercury accounted for the highest percentage of metal exceedances of RRSCOs. Concentrations of arsenic (16.3 to 1,110 ppm) found on the site exceed the RRSCO of 16 ppm. Concentrations of lead (448 to 12,100 ppm) found onsite exceed the RRSCO of 400 ppm. Concentrations of mercury (0.856 to 8.43 ppm) found onsite exceed the RRSCO of 0.81 ppm. While many of the metal values were within the range of their typical background concentrations for urban fill, some were well above these values are likely attributable to the petroleum and coal tar releases previously identified. PCBs and Pesticides: PCBs were detected at 8.9 ppm in one shallow soil boring exceeding the RRSCO of 1 ppm. Pesticides were detected in samples, although no pesticides were detected above RRSCOs. Site-related VOC, SVOC, pesticides and metals were found in Bushwick Inlet and/or East River sediments adjacent to the site. Coal tar DNAPL was observed in one sample in the East River. Petroleum LNAPL, sheen and odors were observed in three samples in the East River and four samples collected in the Bushwick Inlet. This suggests that site contamination has likely migrated off-site into the Bushwick Inlet. Groundwater: Sampling results indicated that VOCs, SVOCs, and metals were detected above the 6NYCRR Part 703 Ambient Water Quality Standards and Guidance Values (AWQSGVs) in groundwater. VOCs: VOCs, including 1,2,4 trimethylbenzene, 1, 3, 5 trimethylbenzene, benzene, chlorobenzene, isopropylbenzene, naphthalene, n propylbenzene, sec butylbenzene, MTBE, and total xylenes were detected at concentrations exceeding AWQSGVs The following VOCs were the highest: naphthalene at 2,100 part per billion (ppb) which exceeds the AWQSGV of 10 ppb; benzene at 160 ppb which exceeds the AWQSGV of 1 ppb; 1,2,4 trimethylbenzene at 260 which exceeds the AWQSGV of 5 ppb; total xylenes at 1,140 ppb which exceeds the AWQSGV of 5 ppb. SVOCs: SVOCs, including acenaphthene, benzo(a) anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, indeno(1,2,3 c,d)pyrene, and phenol were detected at concentrations exceeding NYSDEC AWQSGVs. The following are the maximum concentrations of SVOC found on site in groundwater: acenaphthene at 52 ppb, which exceeds the AWQSGV of 20 ppb; benzo(a)pyrene at 4 ppb, which exceeds the AWQSGV (non detect); benzo(b)fluoranthene at 3 ppb, benzo(k)fluoranthene at 2 ppb, chrysene at 5 ppb and indeno(1,2,3 c,d)pyrene at 2 ppb, which exceed their AWQSGV of 0.002 ppb; and phenol at 2 ppb which exceeds the AWQSGV of 1 ppb. 1,4-Dioxane was not detected above the laboratory reporting limit in any groundwater sample. The elevated concentration of VOCs is likely a reflection of the petroleum contamination as most exceedances occurred in the former petroleum storage and fueling operations. The SVOC contamination is in part the result of the historic fill as most exceedances occurred in the western half of the site. SVOC contamination was also found in borings with observed coal tar in the southeast area of the site along 12th street, suggesting some SVOC groundwater contamination could be attributed to the MGP. Metals: The metals arsenic, barium, beryllium, cadmium, chromium, copper, iron, magnesium, lead, manganese, and sodium were detected at concentrations exceeding AWQSGVs in unfiltered samples. Filtered samples show only iron, magnesium, and sodium exceeding AWQSGVs, which is likely from compounds associated with the East River, which have a hydrogeological connection to groundwater at the Site. The source of the other metals in the unfiltered samples is likely due to the presence of suspended sediments in the sample. PCBs and Pesticides: PCBs and pesticides were not detected above the laboratory reporting limit in any groundwater sample. PFAS Perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 160 parts per trillion (ppt) and 17 ppt, respectively, exceeding the Maximum Contaminant Level (MCL, drinking water standard) of 10 ppt in groundwater. The maximum concentration of total PFAS in one sample was 706 ppt. The source of these compounds is thought to be from the on site fire suppression system as the compounds were found in samples taken in the immediate vicinity of the foam house. Non Aqueous Phase Liquid-NAPL NAPL was found in both soil and groundwater samples sitewide. Both LNAPL and DNAPL were found in soil borings below the water table and in groundwater wells. Most groundwater observations were non measurable sheens or blebs. However, some had measurable LNAPL,up to 1.5 feet thick. Sediment: Site-related VOC, SVOC, and metals were found in Bushwick Inlet and/or East River sediments adjacent to the site. Coal tar and petroleum was observed in one sample in the East River. Petroleum sheen and odors were observed in three samples in the East River and four samples collected in the Bushwick Inlet. contamination has migrated off-site. The VOC most often detected in samples and with the highest concentrations was 1,2,4-Trimethylbenzene, concentrations of which ranged from 0.1 to 10 ppm. The SVOC most often detected in samples and with the highest concentrations was Naphthalene, concentrations of which ranged from 3 to 48 ppm. The source of these VOC and SVOC compounds are associated with the site. Unfiltered metals samples show compounds associated with the East River. The source of the other metals in the unfiltered samples is likely due to the presence of suspended sediments in the sample. Sediment gathered show observed coal tar and petroleum contamination in the East River and Bushwick Inlet sediment. Coal tar DNAPL was observed in one sample in the East River adjacent to the site. Petroleum LNAPL, sheen and odors were observed in three samples in the East River and four samples collected in the Bushwick inlet. Based on sediment data below and the tidal influence, contaminated groundwater and LNAPL/DNAPL appear to have migrated off-site into the adjacent waterway.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Information

Owner Op:	01
Sub Type:	C01
Owner Name:	Kay Zias
Owner Company:	City of New York Parks & Recreation, Capital Projects Divisi
Owner Street:	117-02 Roosevelt Avenue
Owner Street 2:	Flushing Meadows Corona Park
Owner City:	Flushing
Owner State:	NY
Owner Zip:	11368
Country:	United States of America

Projects Information

Project Code:	01
Project Desc:	Site Caracterization
Project Refer Name:	Exxon Mobile / NYC Parks Site Characterization
End Date:	2021-04-22 00:00:00
End Status:	ACT
Operable Unit ID:	1281917
Operable Unit:	01
Operable Unit Desc:	Remedial Program
Code Name:	Site Characterization

Environmental Remediation

Operable Unit:	01
Contaminants:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
227	1 of3	E	0.76 / 4,006.10	23.01 / 11	***Quanta Resources 37-80 Review Avenue Long Island City NY 10111***	***VAPOR***

Site Code:	241005	***UTM X:***	589794.36154
Vapor Ins Eval Stat:	Complete	***UTM Y:***	4509552.90982
Program:	State Superfund Program	***Point X:***	-73.9366145436898
Site Class:	02	***Point Y:***	40.73201742517192
Town:	New York City	***Method:***	4.3
County:	Queens	***Accuracy:***	
GIS Flag:	1	***Accuracy Unit:***	
Brown URL:	https://www.dec.ny.gov/chemical/brownfields.html		
Detail URL:	https://extapps.dec.ny.gov/cfmx/extapps/derexternal/haz/details.cfm?ProgNo=241005		
Doc URL:	https://extapps.dec.ny.gov/data/DecDocs/241005		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
227	2 of3	E	0.76 / 4,006.10	23.01 / 11	***REVIEW AVENUE DEVELOPMENT II 37-80 REVIEW AVE LONG ISLAND CITY NY 11101***	***RCRA CORRACTS***

EPA Handler ID:	NYD980592562
Gen Status Universe:	Small Quantity Generator
Contact Name:	DAVID M KUSHNER
Contact Address:	380 , LEXINGTON AVE ROOM 2020 , , NEW YORK , NY, 10168 , US
Contact Phone No and Ext:	212-661-0858
Contact Email:	KUSH@PARADIGMCF.COM
Contact Country:	US
County Name:	QUEENS
EPA Region:	02
Land Type:	Private
Receive Date:	20080325

Location Latitude: 40.735553
Location Longitude: -73.940157
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Event/Area Details

Area Name: SITEWIDE
Event Code: CA750YE
Corrective Action Event Descri: RELEASE TO GW CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE
Actual Date of Event: 20160331
Orig Sched Event Date:
New Sched Event Date:
Best Date: 20160331
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: S

Area Name: SITEWIDE
Event Code: CA800YE
Corrective Action Event Descri: READY FOR ANTICIPATED USE DETERMINATION - READY FOR ANTICIPATED USE
Actual Date of Event: 20210108
Orig Sched Event Date:
New Sched Event Date:
Best Date: 20210108
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: S

Area Name: SITEWIDE
Event Code: CA400
Corrective Action Event Descri: REMEDY DECISION
Actual Date of Event: 20070209
Orig Sched Event Date:
New Sched Event Date:
Best Date: 20070209
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: S

Area Name: SITEWIDE
Event Code: CA075ME
Corrective Action Event Descri: CA PRIORITIZATION-MEDIUM CA PRIORITY
Actual Date of Event: 20040811
Orig Sched Event Date:
New Sched Event Date:
Best Date: 20040811
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA225NF
Corrective Action Event Descri: STABILIZATION MEASURES EVALUATION-NOT AMENABLE TO STABILIZATION (NOT FEASIBLE)
Actual Date of Event: 19950207
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19950207
Groundwater Release Indicator:
Soil Release Indicator:

Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA050
Corrective Action Event Descri: RFA COMPLETED
Actual Date of Event: 19940920
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19940920
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA070YE
Corrective Action Event Descri: DETERMINATION OF NEED FOR AN INVESTIGATION-INVESTIGATION IS NECESSARY
Actual Date of Event: 19940920
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19940920
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA725YE
Corrective Action Event Descri: HUMAN EXPOSURES CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE
Actual Date of Event: 20150929
Orig Sched Event Date:
New Sched Event Date:
Best Date: 20150929
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: S

Area Name: SITEWIDE
Event Code: CA075HI
Corrective Action Event Descri: CA PRIORITIZATION-HIGH CA PRIORITY
Actual Date of Event: 19930908
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19930908
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA550RC
Corrective Action Event Descri: REMEDY CONSTRUCTION-REMEDY CONSTRUCTED
Actual Date of Event: 20160908
Orig Sched Event Date:
New Sched Event Date:
Best Date: 20160908
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: S

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Oct, 2024.

Evaluation Details

Evaluation Start Date: 20091007
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19870420
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner: No
Smelting, Melting and Refining: No
Underground Injection Control: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19791231
Handler Name: QUANTA RESOURCES CORP
Federal Waste Generator Code:
Generator Code Description:
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19801024
Handler Name: QUANTA RESOURCES CORP
Federal Waste Generator Code:
Generator Code Description:
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19801119
Handler Name: QUANTA RESOURCES CORP
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Part A

Waste Code Details

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060301
Handler Name: QUANTA RESOURCES CORP.
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: B007
Waste Code Description: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D027
Waste Code Description: 1,4-DICHLOROBENZENE

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D040
Waste Code Description: TRICHLOROETHYLENE

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20061025
Handler Name: REVIEW AVENUE DEVELOPMENT II
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20061026

Handler Name: REVIEW AVENUE DEVELOPMENT II
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: B007
Waste Code Description: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D027
Waste Code Description: 1,4-DICHLOROBENZENE

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D040
Waste Code Description: TRICHLOROETHYLENE

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20080325
Handler Name: REVIEW AVENUE DEVELOPMENT II
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20080326
Handler Name: REVIEW AVENUE DEVELOPMENT II
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: B007
Waste Code Description: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D018

Waste Code Description: BENZENE

Hazardous Waste Code: D027
Waste Code Description: 1,4-DICHLOROBENZENE

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D040
Waste Code Description: TRICHLOROETHYLENE

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: QUANTA RESOURCES CORP
Date Became Current:
Date Ended Current:
Phone: 201-941-2020
Source Type: Part A
Street No:
Street 1: 1 RIVER ROAD
Street 2:
City: OPERCITY
State: NJ
Country:
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: 37-80 REVIEW, LLC
Date Became Current: 20050628
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report
Street No:
Street 1: 380 LEXINGON AVENUE SUITE 2020
Street 2:
City: NEW YORK
State: NY
Country: US
Zip Code: 10168

Owner/Operator Ind: Current Operator
Type: Private
Name: QUANTA RESOURCES CORP. (LAST KNOWN OPER)
Date Became Current: 19800801
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report
Street No:
Street 1:
Street 2:
City:
State:
Country: US
Zip Code:

Owner/Operator Ind: Current Owner
Type: Private
Name: 37-80 REVIEW LLC
Date Became Current: 20050628
Date Ended Current:
Phone:
Source Type: Notification
Street No: 380
Street 1: LEXINGTON AVE SUITE 2020
Street 2:
City: NEW YORK
State: NY
Country: US
Zip Code: 10168

Owner/Operator Ind: Current Owner
Type: Private
Name: QUANTA RESOURCES CORP
Date Became Current:
Date Ended Current:
Phone: 201-941-2020
Source Type: Notification
Street No:
Street 1: 1 RIVER RD
Street 2:
City: EDGEWATER
State: NJ
Country:
Zip Code: 07020

Owner/Operator Ind: Current Operator
Type: Private
Name: QUANTA RESOURCES CORP
Date Became Current: 19800801
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1:
Street 2:
City:
State:
Country:
Zip Code:

Historical Handler Details

Receive Dt: 20080326
Generator Code Description: Small Quantity Generator
Handler Name: REVIEW AVENUE DEVELOPMENT II

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Dt: 20061026
Generator Code Description: Large Quantity Generator
Handler Name: REVIEW AVENUE DEVELOPMENT II

Receive Dt: 20061025
Generator Code Description: Small Quantity Generator
Handler Name: REVIEW AVENUE DEVELOPMENT II

Receive Dt: 20060301
Generator Code Description: Large Quantity Generator
Handler Name: QUANTA RESOURCES CORP.

Receive Dt: 19801119
Generator Code Description: Not a Generator, Verified
Handler Name: QUANTA RESOURCES CORP

Receive Dt: 19801024
Generator Code Description:
Handler Name: QUANTA RESOURCES CORP

Receive Dt: 19791231
Generator Code Description:
Handler Name: QUANTA RESOURCES CORP

227	3 of3	E	0.76 / 4,006.10	23.01 / 11	Quanta Resources 37-80 Review Avenue Long Island City NY 10111	SHWS

Site Code: 58532
HW Code: 241005
Program: HW
Site Class: 02
Site Name: Quanta Resources
Site Address: 37-80 Review Avenue
City: Long Island City
Zip: 10111
County: Queens
Region: 2
Town: New York City
Latitude: 40.731205070
Longitude: -73.935376500
SWIS: 4101
Acres: 1.696
Record Added: 1999-11-18 12:00:00
Record Update: 2024-09-25 09:16:00
Updated by: SMQUANDT
Site Code (Web): 241005
Program Type (Web): HW
Site Name (Web): Quanta Resources
Site Class (Web): 02
Address1 (Web): 37-80 Review Avenue
Address2 (Web):
Locality (Web): Long Island City
Zip Code (Web): 10111
County (Web): Queens
Longitude (Web): -73.935376500
Latitude (Web): 40.731205070
Site Code (GIS): 241005
Site Name (GIS): Quanta Resources
Program (GIS): HW
Site Class (GIS): 02
Address1 (GIS): 37-80 Review Avenue
Address2 (GIS):
Locality (GIS): Long Island City
Zip Code (GIS): 10111
County (GIS): Queens
Site Class Desc: This classification is assigned to a site at which:

a. the disposal of hazardous waste has been confirmed and the presence of such hazardous waste or its components or breakdown products represents a significant threat to public health or the environment: or
b. hazardous waste disposal has not been confirmed, but the site has been listed on the Federal National Priorities List (NPL).

Site Class Desc (Web): This classification is assigned to a site at which:

a. the disposal of hazardous waste has been confirmed and the presence of such hazardous waste or its components or breakdown products represents a significant threat to public health or the environment: or
b. hazardous waste disposal has not been confirmed, but the site has been listed on the Federal National Priorities List (NPL).

Assess DOH: Waste oil previously stored on-site has caused widespread contamination of groundwater and soils. Approximately 500,000 gallons of contaminated waste oil remains at the site, floating on the water table. The aquifer of concern is not used as a source for drinking water. Groundwater wells in this area of Queens are used only for commercial and industrial purposes. A fence surrounds the site restricting access and minimizing the potential for direct contact exposures to on-site contaminates. The potential exists for the floating oil plume to migrate into the nearby Newtown Creek which empties into the East River. Further investigation is required.

Description:

Location: The Quanta Resources Site is an approximately 2 acre parcel located at 37-80 Review Avenue. The site is bounded on the northeast by Review Avenue and on the southwest by the Southern Line of the Long Island Rail Road (LIRR). On the northwest it is bounded by an alley (Preston Street) that runs from Review Avenue to the LIRR tracks. On the southeast it is bounded by the property currently owned by Phoenix Beverages (an imported beer distributor). Farther to the northeast, across Review Avenue, is Calvary Cemetery. Farther to the northwest, across the alley, is the "North Capasso" property, also referred to as Review Avenue Development I (RADI). Farther to the southwest, across the LIRR tracks, is the "South Capasso" property. Newtown Creek lies beyond the South Capasso property farther to the southeast approximately 450 feet from the site. Fencing bounds the property on all sides. Current Zoning and Land Use: The site is located within a highly industrialized area of Long Island City, Queens, New York. Zoning in this area is designated as heavy manufacturing. Site Features: The site has been inactive since being abandoned in November 1981. Tanks and several buildings remain on site. Past Uses of the Site: The Quanta Resources property and surrounding properties have been used for a variety of industrial purposes since the late 19th century. A Sanborn Fire Insurance Map from 1898 indicates that the site was partially occupied by vacant and dilapidated brick wrecks of an oil refinery. Available information indicates the earliest recorded actual owner of the property was American Agricultural Chemical Company. In 1931 the property was transferred to Triplex Oil. Triplex Oil used the property for refining of used crank case oil for approximately 40 years. From 1972 until 1980 the facility was operated by several different owners including Pentalic Corporation, Sea Lion Corporation, Ag-met Oil Service, Inc., Hudson Oil Refining Corp., and Portland Holding Corp. In 1980 Quanta Resources acquired the property, and used the property for the re-refining of used crankcase oil and other liquid recycling before filing for bankruptcy on October 6, 1981. A Consent Order was signed with numerous PRPs in May 2002 for the undertaking of investigation and remediation activities. An RI/FS was completed. Soil and groundwater contamination has been confirmed. The primary contaminants of concern include petroleum hydrocarbons, chlorinated solvents, PCBs, heavy metals and PAHs. Measurable LNAPL was found in 24 of 29 onsite and offsite monitoring wells. The Site was accepted into BCP. The BCA agreement was executed on 12/2/05 (see C241005). A PRAP was issued in June 2006. A PRAP Public Meeting was held on June 28, 2006 and the ROD was signed 2/9/07 requiring a $15,560,000 remedy which includes an LNAPL recovery system. Remedial Design is underway. A number of potential LNAPL source areas existed on the Quanta Resources Site throughout its operational history, however, the primary suspected source area is the tank farm area located in the northeastern portion of the site. A New York City emergency remedial action removed approximately 640,000 gallons of waste oil from the property. Some of the waste oil contained tetrachloroethene, methyl chloride, 1,1,1-trichloroethane and trichloroethene. Sludge, waste oil, and diesel fuel, all contaminated with PCBs, were also removed from badly deteriorated leaking tanks and drums. As part of NYSDEC's Phase II Investigation, three on-site groundwater monitoring wells were installed. During installation it was discovered that there was a seven foot layer of oil (also known as Light Non-Aqueous Phase Liquid - LNAPL) lying above the groundwater table. An LNAPL recovery system was installed at the site in 2016. This system continues to operate and is effective in remediating the site. See Site Code C241005 and C241089 for post ROD updates.

Assessment:

The site presents a significant threat due to the soil and groundwater contamination, free product LNAPL plume and close proximity to Newtown Creek. An RI/FS was completed. Soil and groundwater contamination has been confirmed. The primary contaminants of concern include petroleum hydrocarbons, chlorinated solvents,heavy metals and PAHs. Measurable LNAPL was found in 24 of 29 onsite and offsite monitoring wells. ROD signed 2/07. Site has transitioned into the Brownfield program. Site is now tracked as Review Avenue Development II - Site # C241089

Materials Information

Waste Name: 1,1,1-TRICHLOROETHANE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: BENZENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,1,1 TCA
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: METHYL CHLORIDE
Waste Quantity: UNKNOWN

Waste Code:

Waste Name: TOLUENE 2,4-DIISOCYANATE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,1,1-TCA
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: TETRACHLOROETHENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: TRICHLOROETHENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,1,1-Trichloroethane(TCA)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: TOLUENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: HYDROCARBONS HEAVY METALS.
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 04
Sub Type: E
Owner Name:
Owner Company: QUANTA RESOURCES
Owner Street: 299 S. STATE STREET
Owner Street 2:
Owner City: DOVER
Owner State: DE
Owner Zip: 19901
Country: United States of America

Owner Op: 03
Sub Type: NNN
Owner Name:
Owner Company: Quanta Resources
Owner Street:
Owner Street 2:
Owner City:
Owner State: ZZ
Owner Zip:
Country: United States of America

Owner Op: 01
Sub Type: E
Owner Name:
Owner Company: QUANTA RESOURCES
Owner Street: 299 S. STATE ST.
Owner Street 2:
Owner City: DOVER
Owner State: DE
Owner Zip: 19901
Country: United States of America

Owner Op: 01
Sub Type: NNN
Owner Name:

Owner Company: Quanta Resources
Owner Street: 299 South State Street
Owner Street 2:
Owner City: Dover
Owner State: DE
Owner Zip: 19901
Country: United States of America

Owner Op: 04
Sub Type: NNN
Owner Name:
Owner Company: Quanta Resources
Owner Street: 299 South State Street
Owner Street 2:
Owner City: Dover
Owner State: DE
Owner Zip: 19901
Country: United States of America

HW Extra Information

Dump: True
Structure: True
Lagoon: False
Landfill: False
Pond: False
Dell: False
Updated By: INITIAL
Record Added: 1999-11-18 12:00:00
Record Updated: 1999-11-18 12:00:00
Disposal Start: 1960
Disposal Terminate: 1981
Latitude: 40:43:52:0
Longitude: 73:56:09:0

Projects Information

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2007-02-09 00:00:00
End Status: ACT
Operable Unit ID: 626
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM
Code Name: Remedial Investigation

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 1982-12-01 00:00:00
End Status: ACT
Operable Unit ID: 627
Operable Unit: 01A
Operable Unit Desc: IRM - Removal Action
Code Name: Remedial Action

Project Code: 01
Project Desc: Site Caracterization
Project Refer Name:
End Date: 1990-06-01 00:00:00
End Status: ACT
Operable Unit ID: 626
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM
Code Name: Site Characterization

Environmental Remediation

Operable Unit: 01A
Contaminants: 1,1,1-Trichloroethane(TCA), 1,1,1-trichloroethane, benzene, methyl chloride, tetrachloroethene, toluene, toluene 2,4-diisocyanate

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Operable Unit: 02
Contaminants: 1,1,1-Trichloroethane(TCA), 1,1,1-trichloroethane, benzene, methyl chloride, tetrachloroethene, toluene, toluene 2,4-diisocyanate

Operable Unit: 01
Contaminants: 1,1,1-Trichloroethane(TCA), 1,1,1-trichloroethane, benzene, methyl chloride, tetrachloroethene, toluene, toluene 2,4-diisocyanate

228	1 of1	ENE	0.77 / 4,069.36	19.48 / 7	ACTIVE STEEL DRUM CO INC 52-30 34TH ST LONG ISLAND CITY NY 11101-3202	RCRA CORRACTS

EPA Handler ID: NYD003933355
Gen Status Universe: No Report
Contact Name:
Contact Address: 52-30 , 34TH ST , , LONG ISLAND CITY , NY, 11101 , US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: QUEENS
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 40.736663
Location Longitude: -73.936103
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Event/Area Details

Area Name: SITEWIDE
Event Code: CA225NR
Corrective Action Event Descri: STABILIZATION MEASURES EVALUATION-FACILITY NOT AMENABLE TO STABILIZATION
Actual Date of Event: 19950919
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19950919
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA075HI
Corrective Action Event Descri: CA PRIORITIZATION-HIGH CA PRIORITY
Actual Date of Event: 19930908
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19930908
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA075LO
Corrective Action Event Descri: CA PRIORITIZATION-LOW CA PRIORITY
Actual Date of Event: 20040113
Orig Sched Event Date:
New Sched Event Date:
Best Date: 20040113
Groundwater Release Indicator:
Soil Release Indicator:

Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA050
Corrective Action Event Descri: RFA COMPLETED
Actual Date of Event: 19950928
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19950928
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA070NO
Corrective Action Event Descri: DETERMINATION OF NEED FOR AN INVESTIGATION-INVESTIGATION IS NOT NECESSARY
Actual Date of Event: 19950928
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19950928
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Oct, 2024.

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19841113
Scheduled Compliance Date:
Return to Compliance: Observed
Actual Return to Compl: 19870513
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 19870922
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 19870427
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:

Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19841113
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description: Generators - General
Return to Compliance Date: 19870513
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner: No
Smelting, Melting and Refining: No
Underground Injection Control: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19800818
Handler Name: ACTIVE STEEL DRUM CO INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: F001
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F004
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F017
Waste Code Description: DESCRIPTION

Hazardous Waste Code: U159
Waste Code Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19801119
Handler Name: ACTIVE STEEL DRUM CO INC
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Part A

Waste Code Details

Hazardous Waste Code: F017
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990708
Handler Name: ACTIVE STEEL DRUM CO INC
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: ACTIVE STEEL DRUM CO INC
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: ACTIVE STEEL DRUM CO INC
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: BARRY K. FINE
Date Became Current:
Date Ended Current:
Phone: 516-665-4375
Source Type: Part A
Street No:
Street 1: 27 LAWRANCE LANE
Street 2:
City: OPERCITY
State: NY
Country:
Zip Code: 99999

Owner/Operator Ind: Current Operator
Type: Private
Name: BARRY K. FINE
Date Became Current:
Date Ended Current:
Phone: 516-665-4375
Source Type: Implementer
Street No:
Street 1: 27 LAWRANCE LANE
Street 2:
City: OPERCITY
State: NY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: BARRY K FINE
Date Became Current:
Date Ended Current:
Phone: 516-665-4375
Source Type: Implementer
Street No:
Street 1: 27 LAWRANCE LANE
Street 2:
City: BAY SHORE
State: NY
Country: US
Zip Code: 11706

Owner/Operator Ind: Current Owner
Type: Private
Name: BARRY K FINE
Date Became Current:
Date Ended Current:
Phone: 516-665-4375
Source Type: Notification
Street No:
Street 1: 27 LAWRANCE LANE
Street 2:
City: BAY SHORE
State: NY
Country:
Zip Code: 11706

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: ACTIVE STEEL DRUM CO INC

Receive Dt: 19990708
Generator Code Description: Not a Generator, Verified
Handler Name: ACTIVE STEEL DRUM CO INC

Receive Dt: 19801119
Generator Code Description: Not a Generator, Verified
Handler Name: ACTIVE STEEL DRUM CO INC

Receive Dt: 19800818
Generator Code Description: Large Quantity Generator
Handler Name: ACTIVE STEEL DRUM CO INC

229	1 of1	NNE	0.78 /	12.42 /	Arch Street Yards (LIRR)	SHWS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
			4,101.06	0	Arch Street and Jackson Avenue Long Island City NY 11101	

Site Code: 571989
HW Code: 241222
Program: HW
Site Class: A
Site Name: Arch Street Yards (LIRR)
Site Address: Arch Street and Jackson Avenue
City: Long Island City
Zip: 11101
County: Queens
Region: 2
Town: New York City
Latitude: 40.743611111
Longitude: -73.947222222
SWIS: 4101
Acres: 0.300
Record Added: 2018-06-27 09:30:00
Record Update: 2022-08-01 16:33:00
Updated by: JHOCONNE
Site Code (Web): 241222
Program Type (Web): HW
Site Name (Web): Arch Street Yards (LIRR)
Site Class (Web): A
Address1 (Web): Arch Street and Jackson Avenue
Address2 (Web):
Locality (Web): Long Island City
Zip Code (Web): 11101
County (Web): Queens
Longitude (Web): -73.947222222
Latitude (Web): 40.743611111
Site Code (GIS): 241222
Site Name (GIS): Arch Street Yards (LIRR)
Program (GIS): HW
Site Class (GIS): A
Address1 (GIS): Arch Street and Jackson Avenue
Address2 (GIS):
Locality (GIS): Long Island City
Zip Code (GIS): 11101
County (GIS): Queens
Site Class Desc: Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Site Class Desc (Web): Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Assess DOH:
Description:

Location: The Arch Street Yard Site is located in an urban area of Long Island City, Queens County, NY. The site is approximately 0.3 acre in size. This property is owned by the Long Island Rail Road (LIRR). The site is located north of 49th Avenue, under the 21st St. bridge. Jackson Ave. borders the site to the west and the Arch St. to the east. Site Features: The site currently houses a train repair facility. In addition, several sets of train tracks traverse the site. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) with an R7X (residential) overlay. The surrounding parcels are currently used for a combination of residential, commercial, light industrial and utility/transportation rights-of-way. Past Use of the Site: The site has historically been used as a rail road yard. Site Geology and Hydrogeology: Soil boring logs from a 2005 investigation identified urban fill consisting of fine sand and silt with some gravel, wood and railroad ties in the upper 5 to 8 feet below grade (bg). Beneath that, to a depth of approximately 12 feet bgs, the borings identified wet organic silt with plant fibers. Groundwater occurs at approximately 3-5 feet bgs and flows west towards the East River.

Assessment:

Nature and Extent of Contamination: Soil - a subsurface soil sample exhibited tetrachloroethylene (PCE) at a concentration of 1,160 parts per million (ppm), which exceeds both the protection of groundwater soil cleanup objective (SCO) of 1.3 ppm and the industrial use SCO of 300 ppm. SVOCs were not detected at concentrations exceeding the industrial SCOs, with the exception of benzo(a)pyrene at 2.9 ppm (industrial SCO is 1.1 ppm). No metals, PCBs or pesticides were detected above the industrial SCOs. Groundwater - Groundwater samples collected from a boring location exhibited PCE at a maximum individual concentration of 17,600 parts per billion (ppb), above the ambient water quality standard of 5 ppb. Soil Vapor - PCE and trichloroethene (TCE) detected at concentrations of 881 micrograms per cubic meter (ug/m3) and 859 ug/m3, respectively. The sub-slab soil vapor sample collected from the Engineering Support Building in August 2016 exhibited TCE at a concentration of 5 ug/m3.

Materials Information

Waste Name: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 04
Sub Type: NNN
Owner Name: KATHLEEN GREEN
Owner Company: Long Island Rail road
Owner Street: Corporate Safety Department
Owner Street 2: 144-41 94th Ave, Mail Code 1944, 4th Fl
Owner City: Jamaica
Owner State: NY
Owner Zip: 11435
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: HRAHMED

Record Added: 2021-06-04 13:16:00
Record Updated: 2021-06-04 13:16:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Environmental Remediation

Operable Unit: 00
Contaminants: dichloroethene (cis-1,2-), tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride

Operable Unit: 01
Contaminants: dichloroethene (cis-1,2-), tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
230	1 of1	ESE	0.79 / 4,150.43	31.57 / 20	83 Apollo Street OER 83 Apollo Street Brooklyn NY 11222	SHWS

Site Code: 617384
HW Code: 224323
Program: HW
Site Class: P
Site Name: 83 Apollo Street OER
Site Address: 83 Apollo Street
City: Brooklyn
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.727052489
Longitude: -73.938343816

SWIS:	2401
Acres:	0.230
Record Added:	2021-03-24 10:08:00
Record Update:	2024-01-18 10:52:00
Updated by:	HMDUDEK
Site Code (Web):	224323
Program Type (Web):	HW
Site Name (Web):	83 Apollo Street OER
Site Class (Web):	P
Address1 (Web):	83 Apollo Street
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.938343816
Latitude (Web):	40.727052489
Site Code (GIS):	224323
Site Name (GIS):	83 Apollo Street OER
Program (GIS):	HW
Site Class (GIS):	P
Address1 (GIS):	83 Apollo Street
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Site Class Desc (Web):	Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Assess DOH:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Assessment:

Nature and extent of contamination based on the initial site characterization: Soil – Semi-volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), and metals contamination were detected in shallow soil. For example, the SVOC - benzo(a)anthracene was detected at 1.5 parts per million or ppm (compared to the restricted-residential Soil Cleanup Objective [SCO] of 1 ppm), the metal – mercury was detected at 2.01 ppm (compared at the restricted-residential SCO of 0.81 ppm, and total PCBs was detected at 1.2 ppm (compared to the restricted-residential SCO of 1 ppm. Groundwater – Elevated petroleum concentrations were encountered in groundwater. For example, benzene was detected at 2,200 parts per billion or ppb (compared to the groundwater standard of 1 ppb). Dissolved-phase petroleum contamination may be related to NYSDEC Site No. S224150: ExxonMobil Greenpoint Petroleum Remediation Project. Soil Vapor – Elevated chlorinated solvent concentrations were encountered in soil vapor. For example, trichloroethene (TCE) was detected up to 31,300 micrograms per cubic meter.

Description:

Location: The property is a 0.23 acre property located on the east side of Apollo Street between Nassau Avenue and Norman Avenue. The site is surrounded by commercial and manufacturing properties. Site Features: A one-story commercial building is present on the property. Current Zoning and Land Use: The site is zoned M1-2 (commercial and light manufacturing). The site is currently vacant. Past Use of the Site: A Phase I Environmental Site Assessment identified previous on-site commercial/industrial uses including an adhesives manufacturer. Site Geology and Hydrogeology: On-site geology information is limited. Borings installed in the adjacent sidewalk revealed urban fill in the upper 5ft underlain primarily by fine sand with stratified layers of silt and gravel to groundwater interface at approximately 30ft below grade. Groundwater flow is the area in controlled by large-scale dewatering from the ExxonMobil Greenpoint Petroleum Remediation Project (NYSDEC Site No. S224150).

Environmental Remediation

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Operable Unit:		01				
Contaminants:						

231	1 of1	SW	0.80 / 4,200.66	5.81 / -6	**Former Pratt Refinery** **26 N. 12th Street** **Brooklyn NY 11249**	SHWS

Site Code:	658785
HW Code:	224402
Program:	HW
Site Class:	P
Site Name:	Former Pratt Refinery
Site Address:	26 N. 12th Street
City:	Brooklyn
Zip:	11249
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.726003668
Longitude:	-73.959686466
SWIS:	2401
Acres:	7.300
Record Added:	2023-11-10 11:40:00
Record Update:	2024-02-02 15:37:00
Updated by:	WBBENNET
Site Code (Web):	224402
Program Type (Web):	HW
Site Name (Web):	Former Pratt Refinery
Site Class (Web):	P
Address1 (Web):	26 N. 12th Street
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11249
County (Web):	Kings
Longitude (Web):	-73.959686466
Latitude (Web):	40.726003668
Site Code (GIS):	224402
Site Name (GIS):	Former Pratt Refinery
Program (GIS):	HW
Site Class (GIS):	P
Address1 (GIS):	26 N. 12th Street
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11249
County (GIS):	Kings
Site Class Desc:	Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Site Class Desc (Web):	Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Assess DOH:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Description:

Location: The Pratt Refinery site is located in a commercial/industrial area in the Williamsburg section of Brooklyn. The site comprises a single real estate parcel, Block 2277 Lot 1, at 26 N 12th St. It is approximately 7.3-acres in size and is located between Kent Avenue and the East River and

between N 12th St. and Bushwick Inlet. Site Features: The site formerly included above ground petroleum bulk storage tanks, a 3-story office building, a one-story cinder block garage, a fuel dispenser island, and a large asphalt paved area. All above ground structures, buildings and storage tanks, were dismantled and removed during the summer of 2019. Current Zoning and Land Use: Currently the site is vacant and covered by concrete slabs and asphalt. The Block and Lot are zoned commercial and future use is anticipated as parkland. The land use in the surrounding area is currently a mix of industrial, commercial, residential, and parkland use. The nearest residential property is located approximately 2 blocks to the south. Past Use of the Site: A petroleum refinery operated on the site from circa 1870 into the early 1900s. Subsequently, the property was utilized as a major petroleum bulk storage facility until the early 2000s. Site Geology and Hydrogeology: The site is underlain by urban fill and varied glacial sediments consisting of outwash sand and gravel, till and lenticular clay more than 100 feet in thickness. The fluvial marsh silty clay to clay is encountered from approximately 5 to 25 feet below ground surface across the site. The groundwater table is approximately 6 feet below ground surface. Groundwater flows to the north northwest, toward Bushwick Inlet and the East River.

Assessment:

Soil and groundwater samples were analyzed for volatile organic compounds (VOCs), semi volatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), pesticides, metals, and the emerging contaminants per and polyfluorinated substances (PFAS) and 1,4 dioxane. Based on investigations conducted, the primary contaminants of concern include VOCs and SVOCs, and metals in soil and groundwater. Both Light Non-Aqueous Phase Liquid (LNAPL) and Dense Non-Aqueous Phase Liquid (DNAPL) were encountered in soil borings below the water table and in groundwater wells.

Owner Information

Owner Op:	01
Sub Type:	C01
Owner Name:	
Owner Company:	City of New York
Owner Street:	100 Church Street
Owner Street 2:	NYC LAW DEPARTMENT, ENVIRONMENTAL DIVISION
Owner City:	New York
Owner State:	NY
Owner Zip:	10007
Country:	United States of America

Environmental Remediation

Operable Unit:	01
Contaminants:	isopropylbenzene, n-propylbenzene, naphthalene, sec-butylbenzene, tert-butylbenzene

232	***1 of7***	***SW***	***0.81 / 4,269.27***	***11.28 / -1***	***K - Williamsburg Works Kent Ave & 12th Street Brooklyn NY 11211-***	***SHWS***

Site Code:	372653
HW Code:	224055
Program:	HW
Site Class:	A
Site Name:	K - Williamsburg Works
Site Address:	Kent Ave & 12th Street
City:	Brooklyn
Zip:	11211-
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.723611111
Longitude:	-73.960555556
SWIS:	2401
Acres:	5.800
Record Added:	2006-10-27 17:50:00
Record Update:	2022-11-23 12:58:00
Updated by:	WBBENNET
Site Code (Web):	224055
Program Type (Web):	HW
Site Name (Web):	K - Williamsburg Works
Site Class (Web):	A
Address1 (Web):	Kent Ave & 12th Street
Address2 (Web):	
Locality (Web):	Brooklyn

Zip Code (Web):	11211-
County (Web):	Kings
Longitude (Web):	-73.960555556
Latitude (Web):	40.723611111
Site Code (GIS):	224055
Site Name (GIS):	K - Williamsburg Works
Program (GIS):	HW
Site Class (GIS):	A
Address1 (GIS):	Kent Ave & 12th Street
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11211-
County (GIS):	Kings
Site Class Desc:	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Site Class Desc (Web):	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Assess DOH:	The NYSDOH will evaluate the potential for impacts to public health from exposure to site contaminants once sufficient information from the investigation of the site becomes available for review.

Description:

Location: The Williamsburg Works Manufactured Gas Plant (MGP) site is located in a commercial/industrial area in the Williamsburg section of Brooklyn, New York. The site is approximately six acres in size and is composed of four parcels of land located on the east bank of the East River between North 11th and North 12th Streets on the west and east sides of Kent Avenue. Site features: Site features include a vacant asphalt paved lot and the foundation slab for the recently demolished document storage warehouse on the west side of Kent Avenue and a two -story commercial building on the east side of Kent Avenue. Current zoning and land use: The land uses in the area surrounding the MGP site are currently a mix of industrial, commercial, residential, and parkland uses. The privately-owned document storage warehouse was in active use until it was destroyed in a fire on January 31, 2015 and subsequently demolished. The former building's slab remains and is surrounded by a lockable chain link fence. The vacant lot at 50 Kent Ave. is owned by the NYC Department of Parks and Recreation and used as an outdoor music venue, flea market and skate park and surrounded by a chain link fence. The two-story commercial building on the east side of Kent Avenue is privately owned and in active use. The nearest residential properties are located to the east and south approximately 1 block from the site. Past use of the site: A manufactured gas plant operated on the site from circa 1850 until approximately 1930. Following the decommissioning of the MGP, the lot was occupied by a NYC Department of Sanitation Garage that was demolished around 2000. Site Geology and Hydrogeology: The site is underlain by urban fill and varied glacial sediments consisting of outwash sand and gravel, till, and lenticular clay more than 100 feet in thickness. The groundwater table is approximately 5 feet below ground surface. Groundwater flows to the west, toward the East River.

Assessment:

The Remedial Investigation of the site has not been fully completed, since large portions of the site are occupied by buildings. However, the work that has been completed has identified significant coal tar contamination in the subsurface. Soils beneath the vacant lot at 50 Kent Avenue are heavily impacted. Design work is currently under way for an excavation IRM on this parcel during the 2015 field season, and tar collection wells have been completed around the perimeter of this property. Tar removal from these wells is taking place on a continuing basis. Tar contamination has moved off site to the north but does not appear to have reached the shoreline in that area. A large portion of the former plant footprint lies beneath the former document storage warehouse. Test borings around the perimeter of this building confirm the presence of MGP tars in the area, and off site migration of this tar has taken place, leading to contamination of sediments beneath adjacent areas of the East River.

Materials Information

Waste Name:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	

Owner Information

Owner Op:	19
Sub Type:	C01
Owner Name:	Williamsburg Branch
Owner Company:	Brooklyn Public Library
Owner Street:	240 Division St., at Marcy Ave.
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11211

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Country: United States of America

Owner Op: 01
Sub Type: C01
Owner Name: kAY zIAS
Owner Company: City of New York Parks & Recreation, Capital Projects Divisi
Owner Street: 117-02 Roosevelt Avenue
Owner Street 2: Flushing Meadows Corona Park
Owner City: FLUSHING
Owner State: NY
Owner Zip: 11368
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: ldennist

Record Added: 2013-09-20 14:19:00
Record Updated: 2013-09-20 14:19:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Projects Information

Project Code: 04
Project Desc: Remedial Design
Project Refer Name: 50 Kent Ave IRM design
End Date: 2015-06-30 00:00:00
End Status: ACT
Operable Unit ID: 1237856
Operable Unit: 01A
Operable Unit Desc: 50 Kent Avenue IRM
Code Name: Remedial Design

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 2018-03-27 00:00:00
End Status: ACT
Operable Unit ID: 1237856
Operable Unit: 01A
Operable Unit Desc: 50 Kent Avenue IRM
Code Name: Remedial Action

Environmental Remediation

Operable Unit: 00
Contaminants: coal tar

Operable Unit: 01A
Contaminants: coal tar

Operable Unit: 01
Contaminants: coal tar

Operable Unit: 02
Contaminants: coal tar

232	2 of7	SW	0.81 / 4,269.27	11.28 / -1	BUG, Williamsburg Works Kent Avenue, North 12th Street Brooklyn 11211 NY	HSWDS

Reg Site ID: U
VOCs: No

Site No:		**Semi VOCs:**	No
EPA ID:	NYD980532030	**PCBs:**	No
Is Site Active?:	No	**Pesticides:**	No
Registry:	N	**Metals:**	No
Years of Operation:	1850 to 1936	**Asbestos:**	No
RCRA:	Unknown	**County:**	Kings
HRS Score:	U	**Region:**	2
HRS Date:	U	**Latitude:**	40 43 25 N
Acres:	0.00	**Longitude:**	73 57 30 W
Site Code:	2A	**Quadrangle:**	U

Site Code Desc: Coal Gasification Plant
Owner: U
Owner Name: (formerly) Brooklyn Union Gas
Owner Address: 195 Montague Street
Brooklyn
Owner Telephone: (718)403-3053
Operator: Same
Operator Name: U
Operator Address: U
Operator Telephone: U
Completed Investigation: PA
Samples Collected: None
Threat to Env/Public Health?: E
Surface Water Contamination?: Unknown
Groundwater Contamination?: Unknown
Drinking Water Contam?: Unknown
Surface Water Class: U
Groundwater Class: U
Active Drinking Water Supply?: Unknown
Hazard Substance Exposed?: Unknown
Controlled Site Access?: Unknown
Ambient Air Contamination?: U
Threat of Direct Contact?: Unknown
Doc Fish/Wildlife Mortality?: Unknown
Impact on Special Status?: Unknown
TCLP:
Surface Water:
Groundwater:
Drinking Water:
Fish or Wildlife Mortality:
Fish or Wildlife Resource:
Building:
Hazard Substance Disposed: Suspected coal/tar
Air:
Surface Water:
Surface Soil:
Waste:
EP Toxicity:
Groundwater:
Sediment:
Subsurface Soil:
Leachate:
Regulatory Agencies Involved: Cercla 103c
USEPA
NYSDEC
Preparer: Julia Slack
Engineering Aide
NYSDEC
May 25, 1994
Nominated by:
Describe the Site: This was formerly the site of a coal-gasification plant, purchased by Brooklyn Union at the turn of the century. One of the by-products produced was a
hydrocarbon tar which was temporarily stored on-site. Ownership and use of the property since 1936 is unknown.
Describe the Threat:

The soil was possibly contaminated with trace amounts of hydrocarbon tar; impact was probably reduced by time and excavation of soils.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
232	3 of7	SW	0.81 / 4,269.27	11.28 / -1	BUG, Williamsburg Works Kent Avenue, North 12th Street Brooklyn 11211 NY	HSWDS

Reg Site ID: U
Site No: HS2017
EPA ID: NYD980532030
Is Site Active?:
Registry: N
Years of Operation:
RCRA:
HRS Score:
HRS Date:
Acres:
Site Code: 2A
Site Code Desc: Coal Gasification Plant
Owner: (formerly) Brooklyn Union Gas
Owner Name:
Owner Address:
Owner Telephone:
Operator: U
Operator Name:
Operator Address:
Operator Telephone:
Completed Investigation:
Samples Collected:
Threat to Env/Public Health?:
Surface Water Contamination?:
Groundwater Contamination?:
Drinking Water Contam?:
Surface Water Class:
Groundwater Class:
Active Drinking Water Supply?:
Hazard Substance Exposed?:
Controlled Site Access?:
Ambient Air Contamination?:
Threat of Direct Contact?:
Doc Fish/Wildlife Mortality?:
Impact on Special Status?:
TCLP:
Surface Water:
Groundwater:
Drinking Water:
Fish or Wildlife Mortality:
Fish or Wildlife Resource:
Building:
Hazard Substance Disposed: Suspected coal/tar
Air:
Surface Water:
Surface Soil:
Waste:
EP Toxicity:
Groundwater:
Sediment:
Subsurface Soil:
Leachate:
Regulatory Agencies Involved:
Preparer:
Nominated by:
Describe the Site: This was formerly the site of a coal-gasification plant, purchased by Brooklyn Union at the turn of the century. One of the by-products produced was a hydrocarbon tar which was temporarily stored on-site. Ownership and use of the propetiy since 1936 is unknown.
Describe the Threat:

VOCs:
Semi VOCs:
PCBs:
Pesticides:
Metals:
Asbestos:
County: Kings
Region: 2
Latitude:
Longitude:
Quadrangle:

The soil was possibly contaminated with trace amounts of hydrocarbon tar; impact was probably reduced by time and excavation of soils.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
232	4 of7	SW	0.81 / 4,269.27	11.28 / -1	BUG, Williamsburg Works Kent Avenue, North 12th Street Brooklyn 11211 NY	HSWDS

Reg Site ID:	U	**VOCs:**	No
Site No:	HS2017	**Semi VOCs:**	No
EPA ID:	NYD980532030	**PCBs:**	No
Is Site Active?:	No	**Pesticides:**	No
Registry:	N	**Metals:**	No
Years of Operation:	1850 to 1936	**Asbestos:**	No
RCRA:	Unknown	**County:**	Kings
HRS Score:	U	**Region:**	2
HRS Date:	U	**Latitude:**	40 43 25 N
Acres:	0.00	**Longitude:**	73 57 30 W
Site Code:	2A	**Quadrangle:**	U

Site Code Desc: Coal Gasification Plant
Owner: U
Owner Name: (formerly) Brooklyn Union Gas
Owner Address: 195 Montague Street
Brooklyn
Owner Telephone: (718)403-3053
Operator: Same
Operator Name: U
Operator Address: U
Operator Telephone: U
Completed Investigation: PA
Samples Collected: None
Threat to Env/Public Health?: E
Surface Water Contamination?: Unknown
Groundwater Contamination?: Unknown
Drinking Water Contam?: Unknown
Surface Water Class: U
Groundwater Class: U
Active Drinking Water Supply?: Unknown
Hazard Substance Exposed?: Unknown
Controlled Site Access?: Unknown
Ambient Air Contamination?: U
Threat of Direct Contact?: Unknown
Doc Fish/Wildlife Mortality?: Unknown
Impact on Special Status?: Unknown
TCLP:
Surface Water:
Groundwater:
Drinking Water:
Fish or Wildlife Mortality:
Fish or Wildlife Resource:
Building:
Hazard Substance Disposed: Suspected coal/tar
Air:
Surface Water:
Surface Soil:
Waste:
EP Toxicity:
Groundwater:
Sediment:
Subsurface Soil:
Leachate:
Regulatory Agencies Involved: Cercla 103c
USEPA
NYSDEC
Preparer: Julia Slack
Engineering Aide
NYSDEC
May 25, 1994
Nominated by:
Describe the Site: This was formerly the site of a coal-gasification plant, purchased by Brooklyn Union at the turn of the century. One of the by-products produced was a hydrocarbon tar which was temporarily stored on-site. Ownership and use of

the property since 1936 is unknown.

Describe the Threat:

The soil was possibly contaminated with trace amounts of hydrocarbon tar; impact was probably reduced by time and excavation of soils.

---

232 | ***5 of7*** | ***SW*** | ***0.81 / 4,269.27*** | ***11.28 / -1*** | ***BUG, Williamsburg Works***
Kent Avenue, North 12th Street
Brooklyn 11211
NY | ***HSWDS***

Reg Site ID:	U	***VOCs:***	No
Site No:	HS2017	***Semi VOCs:***	No
EPA ID:	NYD980532030	***PCBs:***	No
Is Site Active?:	No	***Pesticides:***	No
Registry:	N	***Metals:***	No
Years of Operation:	1850 to 1936	***Asbestos:***	No
RCRA:	Unknown	***County:***	Kings
HRS Score:	U	***Region:***	2
HRS Date:	U	***Latitude:***	40 43 25 N
Acres:	0.00	***Longitude:***	73 57 30 W
Site Code:	2A	***Quadrangle:***	U

Site Code Desc:	Coal Gasification Plant
Owner:	U
Owner Name:	(formerly) Brooklyn Union Gas
Owner Address:	195 Montague Street Brooklyn
Owner Telephone:	(718)403-3053
Operator:	Same
Operator Name:	U
Operator Address:	U
Operator Telephone:	U
Completed Investigation:	PA
Samples Collected:	None
Threat to Env/Public Health?:	E
Surface Water Contamination?:	Unknown
Groundwater Contamination?:	Unknown
Drinking Water Contam?:	Unknown
Surface Water Class:	U
Groundwater Class:	U
Active Drinking Water Supply?:	Unknown
Hazard Substance Exposed?:	Unknown
Controlled Site Access?:	Unknown
Ambient Air Contamination?:	U
Threat of Direct Contact?:	Unknown
Doc Fish/Wildlife Mortality?:	Unknown
Impact on Special Status?:	Unknown
TCLP:	
Surface Water:	
Groundwater:	
Drinking Water:	
Fish or Wildlife Mortality:	
Fish or Wildlife Resource:	
Building:	
Hazard Substance Disposed:	Suspected coal/tar
Air:	
Surface Water:	
Surface Soil:	
Waste:	
EP Toxicity:	
Groundwater:	
Sediment:	
Subsurface Soil:	
Leachate:	
Regulatory Agencies Involved:	Cercla 103c USEPA NYSDEC

Preparer: Julia Slack
Engineering Aide
NYSDEC
May 25, 1994

Nominated by:

Describe the Site: This was formerly the site of a coal-gasification plant, purchased by Brooklyn Union at the turn of the century. One of the by-products produced was a
hydrocarbon tar which was temporarily stored on-site. Ownership and use of the property since 1936 is unknown.

Describe the Threat:

The soil was possibly contaminated with trace amounts of hydrocarbon tar; impact was probably reduced by time and excavation of soils.

232	6 of7	SW	0.81 / 4,269.27	11.28 / -1	BUG. Williamsburg Works Kent Avenue. North 12th Street Brooklyn 11211 NY	HSWDS

Reg Site ID:	U	**VOCs:**	No
Site No:	HS2017	**Semi VOCs:**	No
EPA ID:	NYD980532030	**PCBs:**	No
Is Site Active?:	No	**Pesticides:**	No
Registry:	N	**Metals:**	No
Years of Operation:	1850 to 1936	**Asbestos:**	No
RCRA:	Unknown	**County:**	Kings
HRS Score:	U	**Region:**	2
HRS Date:	U	**Latitude:**	40 43 25 N
Acres:	0.00	**Longitude:**	73 57 30 W
Site Code:	2A	**Quadrangle:**	U

Site Code Desc: Coal Gasification Plant
Owner: U
Owner Name: (formerly) Brooklyn Union Gas
Owner Address: 195 Montague
Street Brooklyn
Owner Telephone: (718)403-3053
Operator: Same
Operator Name: U
Operator Address: U
Operator Telephone: U
Completed Investigation: PA
Samples Collected: None
Threat to Env/Public Health?: E
Surface Water Contamination?: Unknown
Groundwater Contamination?: Unknown
Drinking Water Contam?: Unknown
Surface Water Class: U
Groundwater Class: U
Active Drinking Water Supply?: Unknown
Hazard Substance Exposed?: Unknown
Controlled Site Access?: Unknown
Ambient Air Contamination?: U
Threat of Direct Contact?: Unknown
Doc Fish/Wildlife Mortality?: Unknown
Impact on Special Status?: Unknown
TCLP:
Surface Water:
Groundwater:
Drinking Water:
Fish or Wildlife Mortality:
Fish or Wildlife Resource:
Building:
Hazard Substance Disposed: Suspected coal/tar
Air:
Surface Water:
Surface Soil:
Waste:
EP Toxicity:
Groundwater:

Sediment:
Subsurface Soil:
Leachate:
Regulatory Agencies Involved: Cercla 103c
USEPA
NYSDEC
Preparer: Julia Slack
Engineering Aide
NYSDEC
May 25, 1994
Nominated by:
Describe the Site: This was formerly the site of a coal-gasification plant. purchased by Brooklyn Union at the turn of the century. One of the by-products
produced was a hydrocarbon tar which was temporarily stored on-site. Ownership and use of the property since 1936 is unknown.
Describe the Threat:

The soil was possibly contaminated with trace amounts of hydrocarbon tar; impact was probably reduced by time and excavation of soils.

232	7 of7	SW	0.81 / 4,269.27	11.28 / -1	K - Williamsburg Works Kent Ave & 12th Street Brooklyn NY 11211-	MGP

Site Code:	224055	***Acres:***	5.8
SWIS Code:	2401	***Region:***	2
Class:	A	***Town:***	New York City
Disp Start:		***County:***	Kings
Disp Term:		***Latitude:***	40.723611111
Allowable Uses:	Industrial	***Longitude:***	-73.960555556

Detail(s)

Description:

Location: The Williamsburg Works Manufactured Gas Plant (MGP) site is located in a commercial/industrial area in the Williamsburg section of Brooklyn, New York. The site is approximately six acres in size and is composed of four parcels of land located on the east bank of the East River between North 11th and North 12th Streets on the west and east sides of Kent Avenue. Site features: Site features include a vacant asphalt paved lot and the foundation slab for the recently demolished document storage warehouse on the west side of Kent Avenue and a two -story commercial building on the east side of Kent Avenue. Current zoning and land use: The land uses in the area surrounding the MGP site are currently a mix of industrial, commercial, residential, and parkland uses. The privately-owned document storage warehouse was in active use until it was destroyed in a fire on January 31, 2015 and subsequently demolished. The former building's slab remains and is surrounded by a lockable chain link fence. The vacant lot at 50 Kent Ave. is owned by the NYC Department of Parks and Recreation and used as an outdoor music venue, flea market and skate park and surrounded by a chain link fence. The two-story commercial building on the east side of Kent Avenue is privately owned and in active use. The nearest residential properties are located to the east and south approximately 1 block from the site. Past use of the site: A manufactured gas plant operated on the site from circa 1850 until approximately 1930. Following the decommissioning of the MGP, the lot was occupied by a NYC Department of Sanitation Garage that was demolished around 2000. Site Geology and Hydrogeology: The site is underlain by urban fill and varied glacial sediments consisting of outwash sand and gravel, till, and lenticular clay more than 100 feet in thickness. The groundwater table is approximately 5 feet below ground surface. Groundwater flows to the west, toward the East River.

Assess ENV:

The Remedial Investigation of the site has not been fully completed, since large portions of the site are occupied by buildings. However, the work that has been completed has identified significant coal tar contamination in the subsurface. Soils beneath the vacant lot at 50 Kent Avenue are heavily impacted. Design work is currently under way for an excavation IRM on this parcel during the 2015 field season, and tar collection wells have been completed around the perimeter of this property. Tar removal from these wells is taking place on a continuing basis. Tar contamination has moved off site to the north but does not appear to have reached the shoreline in that area. A large portion of the former plant footprint lies beneath the former document storage warehouse. Test borings around the perimeter of this building confirm the presence of MGP tars in the area, and off site migration of this tar has taken place, leading to contamination of sediments beneath adjacent areas of the East River.

Assess DOH:

The NYSDOH will evaluate the potential for impacts to public health from exposure to site contaminants once sufficient information from the investigation of the site becomes available for review.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
233	1 of1	NNW	0.81 / 4,292.69	5.01 / -7	Queens West - South Center Blvd, 47th Rd, 48th Ave NY 11101	SHWS

Site Code: 57706
HW Code: 241011A
Program: HW
Site Class: N
Site Name: Queens West - South
Site Address: Center Blvd, 47th Rd, 48th Ave
City:
Zip: 11101
County: Queens
Region: 2
Town: New York City
Latitude: 40.744559984
Longitude: -73.957573299
SWIS: 4101
Acres:
Record Added: 2000-01-07 09:49:00
Record Update: 2006-07-28 14:55:00
Updated by: mobarrie
Site Code (Web): 241011A
Program Type (Web): HW
Site Name (Web): Queens West - South
Site Class (Web): N
Address1 (Web): Center Blvd, 47th Rd, 48th Ave
Address2 (Web):
Locality (Web):
Zip Code (Web): 11101
County (Web): Queens
Longitude (Web): -73.957573299
Latitude (Web): 40.744559984
Site Code (GIS): 241011A
Site Name (GIS): Queens West - South
Program (GIS): HW
Site Class (GIS): N
Address1 (GIS): Center Blvd, 47th Rd, 48th Ave
Address2 (GIS):
Locality (GIS):
Zip Code (GIS): 11101
County (GIS): Queens
Site Class Desc: No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Site Class Desc (Web): No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH:
Description:

See site no. V00194.

Assessment:

Environmental Remediation

Operable Unit:
Contaminants:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
234	1 of1	SSE	0.82 / 4,318.72	16.29 / 4	Former Berkman Bros Site 55 Eckford Street Brooklyn NY 11222	SHWS

Site Code: 470590
HW Code: 224168
Program: HW
Site Class: N
Site Name: Former Berkman Bros Site
Site Address: 55 Eckford Street
City: Brooklyn
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.721794775
Longitude: -73.948291650
SWIS: 2401
Acres: 0.234
Record Added: 2012-10-30 10:38:00
Record Update: 2018-10-31 10:43:00
Updated by: MJCRUDEN
Site Code (Web): 224168
Program Type (Web): HW
Site Name (Web): Former Berkman Bros Site
Site Class (Web): N
Address1 (Web): 55 Eckford Street
Address2 (Web):
Locality (Web): Brooklyn
Zip Code (Web): 11222
County (Web): Kings
Longitude (Web): -73.948291650
Latitude (Web): 40.721794775
Site Code (GIS): 224168
Site Name (GIS): Former Berkman Bros Site
Program (GIS): HW
Site Class (GIS): N
Address1 (GIS): 55 Eckford Street
Address2 (GIS):
Locality (GIS): Brooklyn
Zip Code (GIS): 11222
County (GIS): Kings
Site Class Desc: No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Site Class Desc (Web): No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Description:

The site has transferred to the BCP and is being tracking under site #C224168.

Assessment:

Additional investigation will be needed in order to define the nature and extent of the contamination.

Owner Information

Owner Op:	01
Sub Type:	E
Owner Name:	
Owner Company:	Eckford - Greenpoint LLC
Owner Street:	55 Eckford Street
Owner Street 2:	
Owner City:	Brooklyn
Owner State:	NY
Owner Zip:	11222
Country:	United States of America

Environmental Remediation

Operable Unit:	01
Contaminants:	

235	*1 of1*	*E*	*0.82 / 4,325.38*	*32.77 / 21*	***Roehr Chemicals, Inc.*** ***52-28 37th Street*** ***Long Island City NY 11101***	***SHWS***

Site Code:	55924
HW Code:	241014
Program:	HW

Site Class:	C
Site Name:	Roehr Chemicals, Inc.
Site Address:	52-28 37th Street
City:	Long Island City
Zip:	11101
County:	Queens
Region:	2
Town:	New York City
Latitude:	40.734802290
Longitude:	-73.935686280
SWIS:	4101
Acres:	0.500
Record Added:	1999-11-18 12:00:00
Record Update:	2018-02-27 14:46:00
Updated by:	JHOCONNE
Site Code (Web):	241014
Program Type (Web):	HW
Site Name (Web):	Roehr Chemicals, Inc.
Site Class (Web):	C
Address1 (Web):	52-28 37th Street
Address2 (Web):	
Locality (Web):	Long Island City
Zip Code (Web):	11101
County (Web):	Queens
Longitude (Web):	-73.935686280
Latitude (Web):	40.734802290
Site Code (GIS):	241014
Site Name (GIS):	Roehr Chemicals, Inc.
Program (GIS):	HW
Site Class (GIS):	C
Address1 (GIS):	52-28 37th Street
Address2 (GIS):	
Locality (GIS):	Long Island City
Zip Code (GIS):	11101
County (GIS):	Queens
Site Class Desc:	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Site Class Desc (Web):	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH:	People are not expected to contact contaminated soil because buildings and pavement cover most of the site. People may contact contaminated soils if they dig below surface materials. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply system that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Environmental sampling indicates that actions are not needed to address the potential for soil vapor intrusion in on or off-site structures.

Description:

Location: The former Roehr Chemicals facility is located in an urban area at 52-20 37th Street, Long Island City, Queens, at the corner of Starr Avenue. Roehr Chemicals operated four buildings on five lots described as Queens County Tax Map Block 310, Lots 1, 8, 23, 24 and 28. The Site is identified as Block 310, Lot 28. Current Zoning and Land Use: The site is located in a mixed-use area with industrial, commercial and residential uses. The Long Island Expressway (Interstate 495) is located about 1200 feet north of the site. Calvary Cemetery is located immediately east of the site across 37th Street, and Newtown Creek is located approximately 1750 feet southwest of the site. Site Features: The site consists of a one story building on a 100 feet x 100 feet property. The building is presently used as a warehouse for storing packing boxes, and the adjacent partial yard is used for storage and parking. Past Uses of the Site: On this site bulk pharmaceuticals and pharmaceutical intermediates were manufactured from 1957 to 1991. Several VOCs, such as xylene, benzene and diethyl-ketone, were used in the production of these items. During site operations involving the removal of spent xylene, a containment system failed, leaking xylene to the surrounding soil. Lot 28 contained the main building and has been the focus of the

investigation and remediation. Other lots that were part of Roehr Chemical (Block 310, Lots 1, 8, 23, & 24) were investigated and closed in August 1992 under RCRA closure. Geology and Hydrogeology: Groundwater flows to the southwest, toward Cavalry Cemetery and eventually toward Newtown Creek. Groundwater is approximately 25-30 feet below ground surface.

Assessment:

Nature and Extent of Contamination: Prior to Remediation, the Remedial Investigation/Feasibility Study (RI/FS) found groundwater contaminated with xylene and acetone. The RI showed an elongate and narrow xylene plume leaving the site and entering the Calvary Cemetery. An off-site investigation was conducted in October 2000 to determine the impact of on-site contamination on the groundwater quality downgradient of the Calvary Cemetery. A series of geoprobe borings and four monitoring wells were installed along Review Avenue. Total xylenes in many of these wells were found to be at a maximum concentration of 19 ppb. Post-Remediation - The remedial actions taken to date have adequately addressed the significant threat posed to the environment by the contamination. The remedial actions included the operation of a soil vapor extraction and air sparging system with groundwater monitoring. With the operation of a AS/SVE system, the groundwater concentrations of site related contaminants were reduced to non-detect levels in most wells. The AS part of the remedial system has been pulsed and the SVE was shut off in June 2013. It was determined that a significant reduction in groundwater concentrations of xylene and ethylbenzene have been achieved. The concentration of xylene has been reduced from a maximum of 105,000 ppb to 63 ppb in the most recent sampling round.

Materials Information

Waste Name: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: ACETONE
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 04
Sub Type: 02
Owner Name:
Owner Company: Roehr Chemicals, Inc.
Owner Street: 52-28 37th Street
Owner Street 2:
Owner City: Long Island City
Owner State: NY
Owner Zip: 11101
Country: United States of America

Owner Op: 01
Sub Type: E
Owner Name: Donald Lau
Owner Company: Wonton Food Inc.
Owner Street: 220-222 Moore Street
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11206
Country: United States of America

Owner Op: 03
Sub Type: E
Owner Name:
Owner Company: ACETO CORPORATION
Owner Street: ONE HOLLOW LANE
Owner Street 2:
Owner City: LAKE SUCCESS
Owner State: NY
Owner Zip: 110421215
Country: United States of America

Owner Op: 04
Sub Type: E
Owner Name:
Owner Company: Wonton Foods Inc
Owner Street: 52-28 37th Street
Owner Street 2:
Owner City: Long Island City
Owner State: NY
Owner Zip: 11101
Country: United States of America

HW Extra Information

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Dell: False
Updated By: SMMARTIN
Record Added: 1999-11-18 12:00:00
Record Updated: 2014-01-30 10:45:00
Disposal Start: 1991
Disposal Terminate: unknown
Latitude: 40:44:05:0
Longitude: 73:56:10:0

Projects Information

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2001-03-29 00:00:00
End Status: ANF
Operable Unit ID: 644
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM
Code Name: Remedial Investigation

Project Code: 01
Project Desc: Site Caracterization
Project Refer Name:
End Date: 1995-10-01 00:00:00
End Status: ACT
Operable Unit ID: 644
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM
Code Name: Site Characterization

Project Code: 07
Project Desc: Site Management (formerly OM&M)
Project Refer Name:
End Date: 2014-09-04 00:00:00
End Status: ACT
Operable Unit ID: 1118887
Operable Unit: 00
Operable Unit Desc: Site Management
Code Name: Site Management

Environmental Remediation

Operable Unit: 00
Contaminants: acetone, ethylbenzene, xylene (mixed)

Operable Unit: 01A
Contaminants: acetone, ethylbenzene, xylene (mixed)

Operable Unit: 01
Contaminants: acetone, ethylbenzene, xylene (mixed)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
236	1 of2	SSW	0.82 / 4,347.68	15.93 / 4	K - Wythe Ave. Station Wythe Ave., Berry St., N 12th & 13th St Brooklyn NY 11211	SHWS

Site Code: 378992
HW Code: 224069
Program: HW
Site Class: A
Site Name: K - Wythe Ave. Station
Site Address: Wythe Ave., Berry St., N 12th & 13th St
City: Brooklyn
Zip: 11211
County: Kings
Region: 2
Town: New York City
Latitude: 40.722222222
Longitude: -73.956388889
SWIS: 2401
Acres: 2.000
Record Added: 2007-03-27 14:30:00
Record Update: 2024-04-25 08:06:00
Updated by: GHPRATT
Site Code (Web): 224069
Program Type (Web): HW
Site Name (Web): K - Wythe Ave. Station
Site Class (Web): A
Address1 (Web): Wythe Ave., Berry St., N 12th & 13th St
Address2 (Web):
Locality (Web): Brooklyn
Zip Code (Web): 11211
County (Web): Kings
Longitude (Web): -73.956388889
Latitude (Web): 40.722222222
Site Code (GIS): 224069
Site Name (GIS): K - Wythe Ave. Station
Program (GIS): HW
Site Class (GIS): A
Address1 (GIS): Wythe Ave., Berry St., N 12th & 13th St
Address2 (GIS):
Locality (GIS): Brooklyn
Zip Code (GIS): 11211
County (GIS): Kings
Site Class Desc: Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Site Class Desc (Web): Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Assess DOH: Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining in Operable Unit 1. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Direct contact with contaminants in the soil is unlikely because the site is covered with pavement and buildings. Volatile organic compounds in the contaminated soil or contamination groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying structures and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion for any future on-site redevelopment of Operable Unit 2. Environmental sampling indicates that soil vapor intrusion is not a concern for off-site buildings.

Assessment:

Prior to Completion of Remediation For OU 1: Lot 1 Parcel Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Based upon investigations conducted, the primary contaminants of concern for OU 1 were BTEX and naphthalene (VOCs), and polycyclic aromatic hydrocarbons (PAHs) (SVOCs). Prior to the IRM, the subsurface soil showed exceedances of the unrestricted soil cleanup objectives (SCOs) for benzene, toluene, ethylbenzene and xylene (BTEX), various PAH constituents, and several metals. Benzene was found as high as 70 parts per million (ppm), compared to an SCO of 0.06 ppm. Toluene was found as high as 550 ppm (0.7 SCO), ethylbenzene as high as 270 ppm (1 ppm SCO), and total xylenes as high as 610 ppm (0.26 ppm SCO). Naphthalene was detected as high as 9,400 ppm, compared to an SCO of 12 ppm. Several PAH compounds were detected as high as 96 ppm, with most having an

SCO of 1 ppm. The metal constituents that exceeded the unrestricted SCOs were as follows: lead as high as 1400 ppm (63 ppm SCO); mercury as high as 18 ppm (0.18 ppm SCO); and arsenic as high as 40 ppm (13 ppm SCO). Subsurface soil offsite had minor exceedances of only the unrestricted SCOs. Groundwater - Groundwater was only sampled at one on-site location during the investigation due to existing buildings, and was found to be impacted by SVOCs and lead. Lead was detected at a concentration of 254 ppb (25 ppb standard); and the four PAHs detected (benz(a)anthracene, benz(a)pyrene, benzo(b)fluoranthene, and chrysene) had a maximum concentration of 0.08 ppb, with a standard of 0.002 ppb. Groundwater sampled at two offsite locations was found to be impacted by VOCs and SVOCs. Soil Vapor - There were no soil vapor samples collected at OU-1. Post-remediation (OU1 only): An IRM was performed at OU1 in 2014 that removed approximately 68,000 tons of impacted material to depths ranging from 15 to 30 feet below ground surface. Prior to remediation, the primary contaminants of concern were BTEX and naphthalene (VOCs), and PAHs (SVOCs). Of the 28 confirmatory samples taken, 25 met the site remedial action SCOs for restricted residential use. The three samples which did not meet the SCOs, and which exceeded only for metals and PAHs, were found at depths greater than 15 feet below ground surface. Groundwater samples collected post-IRM indicated a decrease in concentrations of detected constituents. Prior to Completion of Remediation For OU2 Parcel: Mihata Corporation Properties Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Based upon investigations conducted, the primary contaminants of concern for OU2 were BTEX and naphthalene (VOCs), and polycyclic aromatic hydrocarbons (PAHs) (SVOCs). a full investigation of these media could not be performed due to the presence of existing buildings. The subsurface soil showed exceedances of the unrestricted soil cleanup objectives (SCOs) for benzene, toluene, ethylbenzene and xylene (BTEX), various PAH constituents, and several metals. Benzene was found as high as 330 pats per million (ppm), compared to an SCO of 0.06 ppm. Toluene was found as high as 840 ppm (0.7 SCO), ethylbenzene as high as 1,200 ppm (1 ppm SCO), and total xylenes as high as 1,600 ppm (0.26 ppm SCO). Naphthalene was detected as high as 1,300 ppm, compared to an SCO of 12 ppm. Several PAH compounds were detected as high as 13 ppm, with most having an SCO of 1 ppm. The metal constituents that exceeded the unrestricted SCOs were as follows: lead as high as 1,600 ppm (63 ppm SCO); mercury as high as 2.3 ppm (0.18 ppm SCO); and arsenic as high as 77 ppm (13 ppm SCO). Subsurface soil offsite had minor exceedances of only the unrestricted SCOs. Groundwater - Groundwater was sampled at two on-site locations during the investigation due to existing buildings, with one location within the holder footprint, and the other at the site boundary. The location within the holder was impacted by SVOCs and lead, while the boundary location had impacts from VOCs and one SVOC. Lead was detected at a concentration of 35 parts per billion (ppb) (25 ppb standard); and the four PAHs detected (benz(a)anthracene, benz(a)pyrene, benzo(b)fluoranthene, and chrysene) had a maximum concentration of 0.25 ppb, with a standard of 0.002 ppb. The VOCs found to exceed standards were benzene at 2,200 ppb (1 ppb standard), toluene at 1,200 ppb (5 ppb standard), ethylbenzene at 600 ppb (5 ppb standard), xylene at 2,480 ppb (standard of 5 ppb), isopropyl benzene at 30 ppb (5 ppb standard), naphthalene at 1,200 ppb (guidance value of 10 ppb), n-propylbenzene at 42 ppb (5 ppb standard), styrene at 690 ppb (5 ppb standard), 1,2,4-trimethylbenzene at 600 ppb (5 ppb standard), and 1,3,5-trimethylbenzene at 160 ppb (5 ppb standard). Naphthalene was the SVOC which was found at 1,100 ppb (guidance value of 10 ppb). Groundwater sampled at one offsite location was found to be impacted by VOCs and SVOCs. Soil Vapor- There were three soil vapor samples collected at OU2 during the investigation. The sub-slab vapor samples contained compounds, including BTEX and trimethylbenzenes, which may be associated with gas holder operations and which are common petroleum products. One compound, TCE, was detected at 11 micrograms per cubic meter. This compound is a chlorinated solvent, which is not associated with former gas holder operations. In 2018, several monitoring wells were sampled for PFAS and 1,4-diaxane as part of the Department's Emerging Contaminants initiative. Perfluorooctanoic acid (PFOA) and perfluorooctanesulfanoic acid (PFOS) were reported at concentrations of up to 66 and 15 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. Individual PFAS exceeding the 100 ppt screening level included perfluorohexanoic acid (PFHxA) at a concentration of 272 ppt. Total PFAS, including PFOA and PFOS, were reported at concentrations of up to 679 ppt, which is above the 500 ppt screening level for total PFAS in groundwater. The residual contamination in soil and groundwater is being managed under an Interim Site Management Plan.

Description:

Location: The former Wythe Avenue Station is located in the Williamsburg neighborhood of Brooklyn, New York, Kings County. The site occupies nine parcels, and is bounded by North 13th Street to the north, North 12th Street to the south, Berry Street to the east and Wythe Avenue to the west. These nine parcels are identified as Block 2283, Lots 1, 25, 28, 31, 33, 35, 38, 41 and 43, and comprise approximately 2.07 acres. Site Features: The site is comprised of commercial and industrial properties, and site topography is nearly flat. Lot 1 (OU1) contains a newly constructed twenty-one story hotel and retail stores, the remaining eight lots (OU2) comprise several one-story warehouse buildings on the east half of the site which are currently occupied by the Mirtex Trading Corporation. Current Zoning and Land Use: The area is zoned M1-1 and M1-2, which allow for light industrial and commercial uses. The site is surrounded by mixed use parcels, including light industrial, commercial and residential. The nearest residential area is within 100 feet to the southwest. Past Use of the Site: The site was operated as a Manufactured Gas Plant (MGP) holder station by Brooklyn Union Gas Co. from approximately 1903 to 1965. The station operated solely for gas distribution, and no gas production facilities were present at the site. Over the life of facility, manufactured gas, and possibly natural gas, based on the years of operation, was stored at the facility. In 1965 the holders and all associated MGP buildings were dismantled when the property was sold. Subsequent development of the site included two one-story buildings on the western two parcels, used for manufacturing and warehousing, in 1968. The eastern portion of the site was redeveloped with several warehouse buildings between 1985 and 1991. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of a release or exposure pathway resulting from the site contamination. Operable Unit 1 (OU1) consists of the parcel (Lot 1) owned by Wythe Berry LLC on the western half of the site (approximate size of 1.15 acres). Operable unit 2 (OU2) consists of the remaining eight parcels owned by Mihata Corporation on the eastern half of the site (approximate size of 0.92 acres). Geology and Hydrogeology: The site is underlain by up to 12 feet of urban fill material, then various layers of gravelly sands, silts and clays. Bedrock is approximately 100 feet below the ground surface. Groundwater is encountered at depths of 7 to 10 feet beneath the site, and generally flows to the north in the western portion of the site, and to the east in the eastern portion of the site.

Materials Information

Waste Name: chrysene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: toluene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: lead
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,2,4-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo[k]fluoranthene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: ethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: n-propylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: butylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: biphenyl
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: arsenic
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: COAL TAR
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: methylene chloride
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,3,5-trimethylbenzene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: styrene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: naphthalene
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 19
Sub Type: C05
Owner Name: Gerald A. Esposito
Owner Company: Brooklyn Community Board 1
Owner Street: 435 Graham Avenue
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11211
Country: United States of America

Owner Op: 01
Sub Type: E
Owner Name: Tom Burns
Owner Company: William Vale Owner llc
Owner Street: 444 Madison Ave, Fl 14
Owner Street 2:
Owner City: New York
Owner State: NY
Owner Zip: 10022
Country: United States of America

Owner Op: 19
Sub Type: E
Owner Name:
Owner Company: Brooklyn Public Library
Owner Street: Greenpoint Branch
Owner Street 2: 107 Norman Avenue at Leonard Street
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11222
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Record Added: 2013-09-20 14:19:00
Record Updated: 2018-09-18 11:37:00

Lagoon:	False	***Disposal Start:***	
Landfill:	False	***Disposal Terminate:***	
Pond:	False	***Latitude:***	
Dell:		***Longitude:***	
Updated By:	SXDEYETT		

Projects Information

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2019-02-08 00:00:00
End Status: ACT
Operable Unit ID: 1255245
Operable Unit: 02
Operable Unit Desc: Mihata Corporation Properties
Code Name: Remedial Investigation

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2017-03-31 00:00:00
End Status: ACT
Operable Unit ID: 1136491
Operable Unit: 01
Operable Unit Desc: Wythe Berry LLC Properties
Code Name: Remedial Investigation

Project Code: 01
Project Desc: Site Caracterization
Project Refer Name:
End Date: 2013-08-14 00:00:00
End Status: ACT
Operable Unit ID: 1136491
Operable Unit: 01
Operable Unit Desc: Wythe Berry LLC Properties
Code Name: Site Characterization

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 2014-05-30 00:00:00
End Status: ACT
Operable Unit ID: 1247727
Operable Unit: 01A
Operable Unit Desc: Lot 1 Wythe Berry LLC
Code Name: Remedial Design

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 2015-06-22 00:00:00
End Status: ACT
Operable Unit ID: 1247727
Operable Unit: 01A
Operable Unit Desc: Lot 1 Wythe Berry LLC
Code Name: Remedial Action

Environmental Remediation

Operable Unit: 02
Contaminants: 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, arsenic, benzene, benzo(a)anthracene, benzo(a)pyrene, benzo(b) fluoranthene, benzo(k)fluoranthene, butylbenzene, chrysene, dibenz[a,h]anthracene, ethylbenzene, indeno(1,2,3-cd)pyrene, isopropylbenzene, lead, mercury, n-propylbenzene, naphthalene, styrene, toluene, trichloroethene (TCE), xylene (mixed)

Operable Unit: 00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contaminants: 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, arsenic, benzene, benzo(a)anthracene, benzo(a)pyrene, benzo(b) fluoranthene, benzo(k)fluoranthene, butylbenzene, chrysene, dibenz[a,h]anthracene, ethylbenzene, indeno(1,2,3-cd)pyrene, isopropylbenzene, lead, mercury, n-propylbenzene, naphthalene, styrene, toluene, trichloroethene (TCE), xylene (mixed)

Operable Unit: 01A
Contaminants: 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, arsenic, benzene, benzo(a)anthracene, benzo(a)pyrene, benzo(b) fluoranthene, benzo(k)fluoranthene, butylbenzene, chrysene, dibenz[a,h]anthracene, ethylbenzene, indeno(1,2,3-cd)pyrene, isopropylbenzene, lead, mercury, n-propylbenzene, naphthalene, styrene, toluene, trichloroethene (TCE), xylene (mixed)

Operable Unit: 01
Contaminants: 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, arsenic, benzene, benzo(a)anthracene, benzo(a)pyrene, benzo(b) fluoranthene, benzo(k)fluoranthene, butylbenzene, chrysene, dibenz[a,h]anthracene, ethylbenzene, indeno(1,2,3-cd)pyrene, isopropylbenzene, lead, mercury, n-propylbenzene, naphthalene, styrene, toluene, trichloroethene (TCE), xylene (mixed)

236	2 of2	SSW	0.82 / 4,347.68	15.93 / 4	**K - Wythe Ave. Station** **Wythe Ave., Berry St., N 12th & 13th St** **Brooklyn NY 11211**	MGP

Site Code:	224069	**Acres:**	2
SWIS Code:	2401	**Region:**	2
Class:	A	**Town:**	New York City
Disp Start:		**County:**	Kings
Disp Term:		**Latitude:**	40.722222222
Allowable Uses:	Restricted-Residential	**Longitude:**	-73.956388889

Detail(s)

Description:

Location: The former Wythe Avenue Station is located in the Williamsburg neighborhood of Brooklyn, New York, Kings County. The site occupies nine parcels, and is bounded by North 13th Street to the north, North 12th Street to the south, Berry Street to the east and Wythe Avenue to the west. These nine parcels are identified as Block 2283, Lots 1, 25, 28, 31, 33, 35, 38, 41 and 43, and comprise approximately 2.07 acres. Site Features: The site is comprised of commercial and industrial properties, and site topography is nearly flat. Lot 1 (OU1) contains a newly constructed twenty-one story hotel and retail stores, the remaining eight lots (OU2) comprise several one-story warehouse buildings on the east half of the site which are currently occupied by the Mirtex Trading Corporation. Current Zoning and Land Use: The area is zoned M1-1 and M1-2, which allow for light industrial and commercial uses. The site is surrounded by mixed use parcels, including light industrial, commercial and residential. The nearest residential area is within 100 feet to the southwest. Past Use of the Site: The site was operated as a Manufactured Gas Plant (MGP) holder station by Brooklyn Union Gas Co. from approximately 1903 to 1965. The station operated solely for gas distribution, and no gas production facilities were present at the site. Over the life of facility, manufactured gas, and possibly natural gas, based on the years of operation, was stored at the facility. In 1965 the holders and all associated MGP buildings were dismantled when the property was sold. Subsequent development of the site included two one-story buildings on the western two parcels, used for manufacturing and warehousing, in 1968. The eastern portion of the site was redeveloped with several warehouse buildings between 1985 and 1991. Operable Units: The site was divided into two operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of a release or exposure pathway resulting from the site contamination. Operable Unit 1 (OU1) consists of the parcel (Lot 1) owned by Wythe Berry LLC on the western half of the site (approximate size of 1.15 acres). Operable unit 2 (OU2) consists of the remaining eight parcels owned by Mihata Corporation on the eastern half of the site (approximate size of 0.92 acres). Geology and Hydrogeology: The site is underlain by up to 12 feet of urban fill material, then various layers of gravelly sands, silts and clays. Bedrock is approximately 100 feet below the ground surface. Groundwater is encountered at depths of 7 to 10 feet beneath the site, and generally flows to the north in the western portion of the site, and to the east in the eastern portion of the site.

Assess ENV:

Prior to Completion of Remediation For OU 1: Lot 1 Parcel Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Based upon investigations conducted, the primary contaminants of concern for OU 1 were BTEX and naphthalene (VOCs), and polycyclic aromatic hydrocarbons (PAHs) (SVOCs). Prior to the IRM, the subsurface soil showed exceedances of the unrestricted soil cleanup objectives (SCOs) for benzene, toluene, ethylbenzene and xylene (BTEX), various PAH constituents, and several metals. Benzene was found as high as 70 parts per million (ppm), compared to an SCO of 0.06 ppm. Toluene was found as high as 550 ppm (0.7 SCO), ethylbenzene as high as 270 ppm (1 ppm SCO), and total xylenes as high as 610 ppm (0.26 ppm SCO). Naphthalene was detected as high as 9,400 ppm, compared to an SCO of 12 ppm. Several PAH compounds were detected as high as 96 ppm, with most having an SCO of 1 ppm. The metal constituents that exceeded the unrestricted SCOs were as follows: lead as high as 1400 ppm (63 ppm SCO); mercury as high as 18 ppm (0.18 ppm SCO); and arsenic as high as 40 ppm (13 ppm SCO). Subsurface soil offsite had minor exceedances of only the unrestricted SCOs. Groundwater - Groundwater was only sampled at one on-site location during the investigation due to existing buildings, and was found to be impacted by SVOCs and lead. Lead was detected at a concentration of 254 ppb (25 ppb standard); and the four PAHs detected (benz(a)anthracene, benz(a)pyrene, benzo(b)fluoranthene, and chrysene) had a maximum concentration of 0.08 ppb, with a standard of 0.002 ppb. Groundwater sampled at two offsite locations was found to be impacted by VOCs and SVOCs. Soil Vapor - There were no soil vapor samples collected at OU-1. Post-remediation

(OU1 only): An IRM was performed at OU1 in 2014 that removed approximately 68,000 tons of impacted material to depths ranging from 15 to 30 feet below ground surface. Prior to remediation, the primary contaminants of concern were BTEX and naphthalene (VOCs), and PAHs (SVOCs). Of the 28 confirmatory samples taken, 25 met the site remedial action SCOs for restricted residential use. The three samples which did not meet the SCOs, and which exceeded only for metals and PAHs, were found at depths greater than 15 feet below ground surface. Groundwater samples collected post-IRM indicated a decrease in concentrations of detected constituents. Prior to Completion of Remediation For OU2 Parcel: Mihata Corporation Properties Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Based upon investigations conducted, the primary contaminants of concern for OU2 were BTEX and naphthalene (VOCs), and polycyclic aromatic hydrocarbons (PAHs) (SVOCs). a full investigation of these media could not be performed due to the presence of existing buildings. The subsurface soil showed exceedances of the unrestricted soil cleanup objectives (SCOs) for benzene, toluene, ethylbenzene and xylene (BTEX), various PAH constituents, and several metals. Benzene was found as high as 330 pats per million (ppm), compared to an SCO of 0.06 ppm. Toluene was found as high as 840 ppm (0.7 SCO), ethylbenzene as high as 1,200 ppm (1 ppm SCO), and total xylenes as high as 1,600 ppm (0.26 ppm SCO). Naphthalene was detected as high as 1,300 ppm, compared to an SCO of 12 ppm. Several PAH compounds were detected as high as 13 ppm, with most having an SCO of 1 ppm. The metal constituents that exceeded the unrestricted SCOs were as follows: lead as high as 1,600 ppm (63 ppm SCO); mercury as high as 2.3 ppm (0.18 ppm SCO); and arsenic as high as 77 ppm (13 ppm SCO). Subsurface soil offsite had minor exceedances of only the unrestricted SCOs. Groundwater - Groundwater was sampled at two on-site locations during the investigation due to existing buildings, with one location within the holder footprint, and the other at the site boundary. The location within the holder was impacted by SVOCs and lead, while the boundary location had impacts from VOCs and one SVOC. Lead was detected at a concentration of 35 parts per billion (ppb) (25 ppb standard); and the four PAHs detected (benz(a)anthracene, benz(a)pyrene, benzo(b)fluoranthene, and chrysene) had a maximum concentration of 0.25 ppb, with a standard of 0.002 ppb. The VOCs found to exceed standards were benzene at 2,200 ppb (1 ppb standard), toluene at 1,200 ppb (5 ppb standard), ethylbenzene at 600 ppb (5 ppb standard), xylene at 2,480 ppb (standard of 5 ppb), isopropyl benzene at 30 ppb (5 ppb standard), naphthalene at 1,200 ppb (guidance value of 10 ppb), n-propylbenzene at 42 ppb (5 ppb standard), styrene at 690 ppb (5 ppb standard), 1,2,4-trimethylbenzene at 600 ppb (5 ppb standard), and 1,3,5-trimethylbenzene at 160 ppb (5 ppb standard). Naphthalene was the SVOC which was found at 1,100 ppb (guidance value of 10 ppb). Groundwater sampled at one offsite location was found to be impacted by VOCs and SVOCs. Soil Vapor- There were three soil vapor samples collected at OU2 during the investigation. The sub-slab vapor samples contained compounds, including BTEX and trimethylbenzenes, which may be associated with gas holder operations and which are common petroleum products. One compound, TCE, was detected at 11 micrograms per cubic meter. This compound is a chlorinated solvent, which is not associated with former gas holder operations. In 2018, several monitoring wells were sampled for PFAS and 1,4-diaxane as part of the Department's Emerging Contaminants initiative. Perfluorooctanoic acid (PFOA) and perfluorooctanesulfanoic acid (PFOS) were reported at concentrations of up to 66 and 15 parts per trillion (ppt), respectively, exceeding the 10 ppt screening levels for groundwater for each. Individual PFAS exceeding the 100 ppt screening level included perfluorohexanoic acid (PFHxA) at a concentration of 272 ppt. Total PFAS, including PFOA and PFOS, were reported at concentrations of up to 679 ppt, which is above the 500 ppt screening level for total PFAS in groundwater. The residual contamination in soil and groundwater is being managed under an Interim Site Management Plan.

Assess DOH:

Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining in Operable Unit 1. Contaminated groundwater at the site is not used for drinking or other purposes and the area is served by a public water supply that is not affected by this contamination. Direct contact with contaminants in the soil is unlikely because the site is covered with pavement and buildings. Volatile organic compounds in the contaminated soil or contamination groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying structures and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion for any future on-site redevelopment of Operable Unit 2. Environmental sampling indicates that soil vapor intrusion is not a concern for off-site buildings.

237	1 of1	SW	0.83 / 4,359.31	8.86 / -3	**Brooklyn North 1 Garage** **50 Kent Avenue** **Brooklyn NY 11211**	SHWS

Site Code:	338766
HW Code:	224028
Program:	HW
Site Class:	N
Site Name:	Brooklyn North 1 Garage
Site Address:	50 Kent Avenue
City:	Brooklyn
Zip:	11211
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.711443540
Longitude:	-73.928806481
SWIS:	2401
Acres:	
Record Added:	1999-11-18 12:00:00
Record Update:	2009-11-20 15:30:00
Updated by:	MOBARRIE
Site Code (Web):	224028
Program Type (Web):	HW
Site Name (Web):	Brooklyn North 1 Garage
Site Class (Web):	N

Address1 (Web):	50 Kent Avenue
Address2 (Web):	
Locality (Web):	Brooklyn
Zip Code (Web):	11211
County (Web):	Kings
Longitude (Web):	-73.928806481
Latitude (Web):	40.711443540
Site Code (GIS):	224028
Site Name (GIS):	Brooklyn North 1 Garage
Program (GIS):	HW
Site Class (GIS):	N
Address1 (GIS):	50 Kent Avenue
Address2 (GIS):	
Locality (GIS):	Brooklyn
Zip Code (GIS):	11211
County (GIS):	Kings
Site Class Desc:	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced; c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.
Site Class Desc (Web):	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced; c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.
Assess DOH:	
Description:	

The site is being addressed under site no. 224055 (Williamsburg Works MGP).

Assessment:

Projects Information

Project Code:	01
Project Desc:	Site Caracterization
Project Refer Name:	
End Date:	2000-10-16 00:00:00
End Status:	ACT
Operable Unit ID:	1100676
Operable Unit:	01

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Operable Unit Desc: BROOKLYN NORTH GARAGE
Code Name: Site Characterization

Environmental Remediation

Operable Unit: 01
Contaminants:

---

238 | **1 of1** | **ENE** | **0.85 / 4,477.54** | **11.33 / -1** | **Former Prestone Press**
47-50 30TH STREET
Long Island City NY 11101 | **SHWS**

Site Code: 648810
HW Code: 241264
Program: HW
Site Class: P
Site Name: Former Prestone Press
Site Address: 47-50 30TH STREET
City: Long Island City
Zip: 11101
County: Queens
Region: 2
Town: New York City
Latitude: 40.741376292
Longitude: -73.938388491
SWIS: 4101
Acres: 1.300
Record Added: 2023-02-23 14:01:00
Record Update: 2023-02-27 15:18:00
Updated by: HMDUDEK
Site Code (Web): 241264
Program Type (Web): HW
Site Name (Web): Former Prestone Press
Site Class (Web): N
Address1 (Web): 47-50 30TH STREET
Address2 (Web):
Locality (Web): Long Island City
Zip Code (Web): 11101
County (Web): Queens
Longitude (Web): -73.938388491
Latitude (Web): 40.741376292
Site Code (GIS): 241264
Site Name (GIS): Former Prestone Press
Program (GIS): HW
Site Class (GIS): P
Address1 (GIS): 47-50 30TH STREET
Address2 (GIS):
Locality (GIS): Long Island City
Zip Code (GIS): 11101
County (GIS): Queens
Site Class Desc: Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Site Class Desc (Web): No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the

work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Description:

Location: The Former Prestone Press Site is located in an urban area at 47-50 30th Street in the Long Island City section of Queens, New York. The site is approximately 1.3 acres and is bounded by an unnamed alley to the north, 29th Street to the west, a Metropolitan Transportation Authority right-or-way previously used as a parking area for the building to the south, and 30th Street to the east. The Dutch Kills is located 300 feet west of the site and the Amtrak Sunnyside Yard is 0.25-miles north of the site. Site Features: The main site feature includes a 52,500 square-foot single story building, which extends nearly to the boundaries of the lot. Current Zoning and Land Use: The zoning for the site is M3-2, an industrial and manufacturing designation intended for heavy industry. The site is currently not in use and the printing equipment used by the last occupant has been removed from the building. The surrounding properties include an unnamed alley and dry cleaner to the north, 29th Street to the west, a construction material recycler to the southwest, a movie studio to the east and northeast, a shipping warehouse to the south, and a 3D printing company to the east. Past Use of the Site: According to available information, the site was vacant undeveloped land until as early as 1898 and as late as 1915. By 1936, the northern portion of the site operated as a lumber yard under East River Mill and Lumber Company; the southern portion was occupied by Acme Shellac Products. In 1947, the original portion of the Site's current building was constructed, and building additions were completed by 1950 and by 1970. The 1947 Sanborn fire insurance map depicts the current building as a refrigerator warehouse, and maps from 1950 through 1970 depict it as a liquor warehouse operated by Standard Wine and Liquor Company. The building was used as an office and warehouse for Philip A. Hunt Chemical Corporation from approximately 1977 until 1983. Milton Paper Company occupied the site and utilized the building for paper storage and offices from when acquired the Site in 1985 until when Prestone Press commenced operations in 2006. Prestone Press ceased operations and ARE acquired the property in 2019. The building has been unused since that time. Phase I and Phase II property investigations were conducted between 2005 and 2019; these investigations were not part of a remedial program. Based on a Phase II investigation in 2018, sealing of walls, joints, and floor seams was completed. No other interim remedial actions have been required or conducted. Site Geology and Hydrogeology: Phase II investigation data indicate that the site is underlain by approximately 8 to 10 feet of urban fill above native silty sands and organic peaty soils which are characteristic of a formerly intertidal estuarine ecology (Dutch Kills and the East River). Groundwater is present beneath the site at approximately 10 feet below ground surface (bgs), and approximately 14 to 15 feet below the building floor slab. Groundwater is believed to flow towards Dutch Kills, but this has not yet been confirmed. Historic fill material, typically containing elevated concentrations of PAHs and metals, appears to underlay the entire site. This historic fill material is characteristic of urban fill in New York City, particularly in areas of former tidal estuary ecologies, such as the Dutch Kill and East River, that have been historically filled for industrial and commercial development purposes. Bedrock at properties surrounding the site has been documented between 45-60 feet bgs.

Assessment:

Soil, groundwater, and soil gas samples have been collected under various environmental investigations. The chlorinated volatile organic compound (CVOC) tetrachloroethene (PCE) has been detected in soil, groundwater, and soil vapor samples at the site. PCE was detected in soil above the protection of groundwater soil cleanup objective (PGSCO) at a maximum concentration of 18 parts per million (ppm) (PGSCO: 1.3 ppm) in the vadose zone. PCE has been detected in groundwater above the Ambient Water Quality Standards (AWQS) at a maximum concentration of 170 parts per billion, or ppb (AWQS: 5 ppb). PCE was detected at a maximum concentration of 280,000 micrograms per cubic meter (ug/m3) in soil vapor and 1,700 ug/m3 in indoor air. TCE was detected at a maximum concentration of 100 ug/m3 in soil vapor and 3.8 ug/m3 in indoor air. Other CVOCs detected in soil vapor include cis-1,2-Dichloroethene at 11 ug/m3, carbon tetrachloride at 0.51 ug/m3, and methylene chloride at 7.89 ug/m3. Based on the soil vapor data, the NYSDOH Decision Matrices recommendations suggest mitigation.

Owner Information

Owner Op:	01
Sub Type:	NNN
Owner Name:	Richard Suarez
Owner Company:	ARE-NY Region No. 3 Holding, LLC
Owner Street:	430 East 29th Street, Suite 100
Owner Street 2:	
Owner City:	New York
Owner State:	NY
Owner Zip:	10016
Country:	United States of America

Environmental Remediation

Operable Unit:	01
Contaminants:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
239	1 of1	E	0.88 / 4,647.34	28.01 / 16	Peerless Property 3850 Review Ave. Long Island City 11101 NY	HSWDS

Reg Site ID:	N	**VOCs:**	Yes
Site No:		**Semi VOCs:**	No
EPA ID:	NYD980641138	**PCBs:**	No
Is Site Active?:	Unknown	**Pesticides:**	No
Registry:	N	**Metals:**	No
Years of Operation:	U to U	**Asbestos:**	No
RCRA:	Unknown	**County:**	Queens
HRS Score:	U	**Region:**	2
HRS Date:	U	**Latitude:**	40 44'30"N
Acres:	5.00	**Longitude:**	73 57'30"W
Site Code:	1	**Quadrangle:**	U

Site Code Desc: Industrial Site
Owner: P
Owner Name: Charter International Oil Co.
Owner Address: 8938 Manchester Ave.
PO Box 5008, Tx, 77012
Owner Telephone: (713)923-3300
Operator: P
Operator Name: H.D. Sherman Co., Inc.
Operator Address: 3850 Review Ave.
Long Island City, NY 11101
Operator Telephone: U
Completed Investigation: PA
Samples Collected: None
Threat to Env/Public Health?: E/P
Surface Water Contamination?: Unknown
Groundwater Contamination?: Unknown
Drinking Water Contam?: No
Surface Water Class: U
Groundwater Class: U
Active Drinking Water Supply?: Unknown
Hazard Substance Exposed?: Unknown
Controlled Site Access?: No
Ambient Air Contamination?: U
Threat of Direct Contact?: Unknown
Doc Fish/Wildlife Mortality?: Unknown
Impact on Special Status?: No
TCLP:
Surface Water: Nearest surface water is 100 yards from the site in a southwest direction.
Groundwater:
Drinking Water:
Fish or Wildlife Mortality:
Fish or Wildlife Resource:
Building:
Hazard Substance Disposed: Xylene 1330-20-7
Toluene 108-88-3
other solvents unknown
Air:
Surface Water:
Surface Soil:
Waste:
EP Toxicity:
Groundwater:
Sediment:
Subsurface Soil:
Leachate:
Regulatory Agencies Involved: NYSDEC
Preparer: Julie L. Welch
NYSDEC, Intern, RPI
Env. Eng. Tech. 1
February 10, 1994
Nominated by:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Describe the Site: Before 1972, unknown amounts of Xylene and Toluene were handled and stored at this facility. Accidental leaks or spills may have occurred.

Describe the Threat:

A hazard exists to the Newton Creek which runs behind the site. If the sovents spill or leak, they may contaminate the waterway.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
240	1 of1	NNW	0.88 / 4,647.64	10.34 / -2	OCONNER CAPITAL PARTNERS 5-36 46TH ROAD QUEENS NY 11101	RCRA CORRACTS

EPA Handler ID: NYD001264191
Gen Status Universe: Large Quantity Generator
Contact Name: BRENT CARRIER
Contact Address:
Contact Phone No and Ext: 212-546-0832
Contact Email:
Contact Country:
County Name: QUEENS
EPA Region: 02
Land Type: Private
Receive Date: 20100707
Location Latitude: 40.746592
Location Longitude: -73.955085
Recycler Activity?: NO
Recycler Activity Note: This facility has no indication of Recycling Activity.

Event/Area Details

Area Name: IGNITABLES STORAGE
Event Code:
Corrective Action Event Descri:
Actual Date of Event:
Orig Sched Event Date:
New Sched Event Date:
Best Date:
Groundwater Release Indicator: Yes
Soil Release Indicator: Yes
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency:

Area Name: CYANIDE DRUM STORAGE
Event Code:
Corrective Action Event Descri:
Actual Date of Event:
Orig Sched Event Date:
New Sched Event Date:
Best Date:
Groundwater Release Indicator: Yes
Soil Release Indicator: Yes
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency:

Area Name: SITEWIDE
Event Code: CA050
Corrective Action Event Descri: RFA COMPLETED
Actual Date of Event: 19910315
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19910315
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:

Event Responsible Agency: E

Area Name: SUMPS & TRENCHES
Event Code:
Corrective Action Event Descri:
Actual Date of Event:
Orig Sched Event Date:
New Sched Event Date:
Best Date:
Groundwater Release Indicator: Yes
Soil Release Indicator: Yes
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency:

Area Name: SITEWIDE
Event Code: CA075ME
Corrective Action Event Descri: CA PRIORITIZATION-MEDIUM CA PRIORITY
Actual Date of Event: 19921117
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19921117
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA070NO
Corrective Action Event Descri: DETERMINATION OF NEED FOR AN INVESTIGATION-INVESTIGATION IS NOT NECESSARY
Actual Date of Event: 19910524
Orig Sched Event Date:
New Sched Event Date:
Best Date: 19910524
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Oct, 2024.

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19910523
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 19910524
Violation Responsible Agency: EPA

Enforcement Details

Enforcement Type: 320
Enforcement Type Description: FINAL IMMINENT HAZARD ORDER
Enforcement Action Date: 19910524
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: EPA

Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 20000210
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19910913
Evaluation Type Description: CORRECTIVE ACTION COMPLIANCE EVALUATION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19910826
Evaluation Type Description: CORRECTIVE ACTION COMPLIANCE EVALUATION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19910624
Evaluation Type Description: CORRECTIVE ACTION COMPLIANCE EVALUATION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19910613
Evaluation Type Description: FOCUSED COMPLIANCE INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19910531
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19910528
Evaluation Type Description: CASE DEVELOPMENT INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19910524
Evaluation Type Description: NO LONGER A SIGNIFICANT NON-COMPLIER
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19910523
Evaluation Type Description: FOCUSED COMPLIANCE INSPECTION
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19910523
Evaluation Type Description: SIGNIFICANT NON-COMPLIER
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19910520
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION

Violation Short Description: Generators - General
Return to Compliance Date: 19910524
Evaluation Agency: EPA

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner: No
Smelting, Melting and Refining: No
Underground Injection Control: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Recycler Activity Without Storage: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19910731
Handler Name: ACCURATE ASSOCIATES
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: F007
Waste Code Description: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

Hazardous Waste Code: F008
Waste Code Description: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Hazardous Waste Code: X003
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990708
Handler Name: ACCURATE ASSOCIATES
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: ACCURATE ASSOCIATES
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: ACCURATE ASSOCIATES
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20080617
Handler Name: O C A LONG ISLAND CITY LLC
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: P106
Waste Code Description: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Hazardous Waste Code: P121
Waste Code Description: ZINC CYANIDE (OR) ZINC CYANIDE ZN(CN)2

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20100707
Handler Name: OCONNER CAPITAL PARTNERS
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20110822
Handler Name: OCONNER CAPITAL PARTNERS
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: ACCURATE ASSOC
Date Became Current:
Date Ended Current:
Phone: 718-729-2957
Source Type: Implementer
Street No:
Street 1: 5-20 46TH RD
Street 2:
City: LONG ISLAND CITY
State: NY
Country: US
Zip Code: 11101

Owner/Operator Ind: Current Owner
Type: Private
Name: ACCURATE ASSOCIATES
Date Became Current:
Date Ended Current:
Phone: 718-729-2957
Source Type: Notification
Street No:
Street 1: 5-20 46TH RD
Street 2:
City: LONG ISLAND CITY
State: NY
Country:
Zip Code: 11101

Owner/Operator Ind: Current Owner
Type: Private
Name: OCA LONG ISLAND CITY LLC
Date Became Current: 20061201
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1:
Street 2:
City:
State:
Country:
Zip Code:

Owner/Operator Ind: Previous Owner
Type: Private
Name: OCA LONG ISLAND CITY LLC
Date Became Current: 20061222
Date Ended Current: 20110822
Phone:
Source Type: Implementer
Street No: 535
Street 1: MADISON AVE
Street 2:
City: NEW YORK
State: NY
Country: US
Zip Code: 10022

Owner/Operator Ind: Current Owner
Type: Private
Name: OCA LONG ISLAND CITY LLC
Date Became Current: 20061222
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report update with Notification
Street No: 535
Street 1: MADISON AVE
Street 2:
City: NEW YORK
State: NY
Country: US
Zip Code: 10022

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	5-20 46TH RD
Name:	ACCURATE ASSOCIATES	***Street 2:***	
Date Became Current:		***City:***	LONG ISLAND CITY
Date Ended Current:		***State:***	NY
Phone:	718-729-2957	***Country:***	US
Source Type:	Implementer	***Zip Code:***	11101

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	O'CONNOR CAPITAL PARTNERS	***Street 2:***	
Date Became Current:	20061222	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	5-20 46TH RD
Name:	ACCURATE ASSOC	***Street 2:***	
Date Became Current:		***City:***	LONG ISLAND CITY
Date Ended Current:		***State:***	NY
Phone:	718-729-2957	***Country:***	
Source Type:	Implementer	***Zip Code:***	11101

Owner/Operator Ind:	Previous Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	O'CONNOR CAPITAL PARTNERS	***Street 2:***	
Date Became Current:	20061222	***City:***	
Date Ended Current:	20110822	***State:***	
Phone:		***Country:***	US
Source Type:	Implementer	***Zip Code:***	

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	BRENT CARRIER	***Street 2:***	
Date Became Current:	20061201	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	
Source Type:	Notification	***Zip Code:***	

Historical Handler Details

Receive Dt:	20110822
Generator Code Description:	Not a Generator, Verified
Handler Name:	OCONNER CAPITAL PARTNERS

Receive Dt:	20080617
Generator Code Description:	Small Quantity Generator
Handler Name:	O C A LONG ISLAND CITY LLC

Receive Dt:	20070101
Generator Code Description:	Not a Generator, Verified
Handler Name:	ACCURATE ASSOCIATES

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	ACCURATE ASSOCIATES

Receive Dt:	19990708
Generator Code Description:	Not a Generator, Verified
Handler Name:	ACCURATE ASSOCIATES

Receive Dt:	19910731
Generator Code Description:	Large Quantity Generator
Handler Name:	ACCURATE ASSOCIATES

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
241	1 of1	ENE	0.88 / 4,657.31	10.85 / -1	Former Green and White Cleaners 47-46 30th Street Long Island City NY 11101	SHWS

Site Code:	648812
HW Code:	241272
Program:	HW
Site Class:	P
Site Name:	Former Green and White Cleaners
Site Address:	47-46 30th Street
City:	Long Island City
Zip:	11101
County:	Queens
Region:	2
Town:	New York City
Latitude:	40.742077647
Longitude:	-73.938247054
SWIS:	4101
Acres:	0.440
Record Added:	2023-02-23 14:07:00
Record Update:	2023-02-27 15:36:00
Updated by:	HMDUDEK
Site Code (Web):	241272
Program Type (Web):	HW
Site Name (Web):	Former Green and White Cleaners
Site Class (Web):	P
Address1 (Web):	47-46 30th Street
Address2 (Web):	
Locality (Web):	Long Island City
Zip Code (Web):	11101
County (Web):	Queens
Longitude (Web):	-73.938247054
Latitude (Web):	40.742077647
Site Code (GIS):	241272
Site Name (GIS):	Former Green and White Cleaners
Program (GIS):	HW
Site Class (GIS):	P
Address1 (GIS):	47-46 30th Street
Address2 (GIS):	
Locality (GIS):	Long Island City
Zip Code (GIS):	11101
County (GIS):	Queens
Site Class Desc:	Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Site Class Desc (Web):	Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.
Assess DOH:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Description:

Site Location: The proposed site is located at 47-46 30th Street just east of the Dutch Kills in the Long Island City section of Queens, New York. The proposed site is 0.44-acres in Queens County. The site has a history of being used as a commercial dry cleaner (Green & White Cleaners) and on October 18, 2022, the on-site building was severely damaged in a fire that resulted in a NYC DOB violation to demolish the unsafe structure. Site Features: The main site feature includes a 19,200 square-foot lot with a building that extends nearly to the boundaries of the property. Current Zoning and Land Use: The property is located in an area zoned for industrial and manufacturing designation intended for heavy industrial use. Past Use of the Site: The site has historically been used as a commercial dry cleaner. The most recent operator was Green & White Cleaners which has an active air

facility permit under DEC ID 2-6304-01682 for the operation of a Firbimatic perchloroethylene machine used for dry cleaning operations. Site Geology and Hydrogeology: Site soils have not been investigated but are thought to consist of urban fill underlain by native silty-sands and organic peaty soils, characteristic of former intertidal estuarine ecology. Bedrock in the surrounding area has been found at depths between 45-60 feet below grade. Depth to groundwater is unknown and is thought to flow towards Dutch Kills.

Assessment:

Environmental Assessment: There has been no environmental sampling performed at the site. Based on environmental data for the neighboring 47-50 30th Street property (Former Prestone Press Site No. 241264) the Department believes further investigation of this property is warranted. A summary of the environmental investigation from the Former Prestone Press site as it pertains to Former Green & White Cleaners is provided below: Soil Vapor & Indoor Air – Sub-slab soil vapor and indoor air sampling conducted at the neighboring Former Prestone Press site found tetrachloroethene (PCE) and degradation product trichloroethene (TCE) in soil vapor at concentrations exceeding the NYSDOH decision matrix standards along the northern border of the site nearest the 47-46 30th Street property. PCE has been detected at a maximum concentration of 280,000 micrograms per cubic meter (ug/m3) in soil vapor and 1,700 ug/m3 in indoor air. TCE has been detected at a maximum concentration of 100 ug/m3 in soil vapor and 3.8 ug/m3 in indoor air.

Owner Information

Owner Op:	04
Sub Type:	NNN
Owner Name:	INSUN YUN
Owner Company:	Green and White dry cleaners
Owner Street:	47-46 30th Street
Owner Street 2:	
Owner City:	QUEENS
Owner State:	NY
Owner Zip:	11101
Country:	United States of America

Owner Op:	01
Sub Type:	NNN
Owner Name:	Insun yun
Owner Company:	NY Tex Care Inc.
Owner Street:	47-46B 30th Street
Owner Street 2:	
Owner City:	long island city
Owner State:	NY
Owner Zip:	11101-3404
Country:	United States of America

Environmental Remediation

Operable Unit:	01
Contaminants:	

242	*1 of4*	*SW*	*0.89 / 4,673.65*	*14.88 / 3*	***BUG, Peoples Works Kent Ave. Brooklyn 11211 NY***	***HSWDS***

Reg Site ID:	N	***VOCs:***	No
Site No:	HS2016	***Semi VOCs:***	Unknown
EPA ID:	NYD980532105	***PCBs:***	No
Is Site Active?:	Unknown	***Pesticides:***	No
Registry:	N	***Metals:***	No
Years of Operation:	1871 to 1895	***Asbestos:***	No
RCRA:	Unknown	***County:***	Kings
HRS Score:	U	***Region:***	2
HRS Date:	U	***Latitude:***	40 43'20"N
Acres:	0.00	***Longitude:***	73 57'35"W
Site Code:	2A	***Quadrangle:***	U
Site Code Desc:	Coal Gasification Plant		
Owner:	Publ Utily		
Owner Name:	Formerly BUG Company		
Owner Address:	195 Montague Street Brooklyn NY 11201		
Owner Telephone:	(718)403-3053		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Operator:	U
Operator Name:	U
Operator Address:	U
Operator Telephone:	U
Completed Investigation:	PA
Samples Collected:	None
Threat to Env/Public Health?:	E
Surface Water Contamination?:	Unknown
Groundwater Contamination?:	Unknown
Drinking Water Contam?:	Unknown
Surface Water Class:	U
Groundwater Class:	U
Active Drinking Water Supply?:	No
Hazard Substance Exposed?:	Unknown
Controlled Site Access?:	Unknown
Ambient Air Contamination?:	U
Threat of Direct Contact?:	Unknown
Doc Fish/Wildlife Mortality?:	Unknown
Impact on Special Status?:	Unknown
TCLP:	
Surface Water:	
Groundwater:	
Drinking Water:	
Fish or Wildlife Mortality:	
Fish or Wildlife Resource:	
Building:	
Hazard Substance Disposed:	Suspected hydrocarbon tars (benzene, pyridene, cresols, toluene, naphthalene, hydrogen sulfide, phenol)
Air:	
Surface Water:	
Surface Soil:	
Waste:	
EP Toxicity:	
Groundwater:	
Sediment:	
Subsurface Soil:	
Leachate:	
Regulatory Agencies Involved:	NYSDEC, CERCLA 103c
Preparer:	Julie Welch EnvEngrTech1 May 27, 1994
Nominated by:	
Describe the Site:	A former coal-gasification plant was purchased by BUG Co. During the operations as a CG plant, a hydrocarbon tar was produced and stored on site until sold for use in roofing or road surfacing. The plant was decommissioned in 1895, all remaining tars were reportedly removed and the facility was razed. Ownership and use of the property since 1895 is unknown.
Describe the Threat:	

The soil is possibly contaminated with trace amounts of hydrocarbon tar. (impact probably reduced due to time and excavation of soils) Leachate into groundwater is not a major concern because area groundwater is not a potable supply.

242	2 of4	SW	0.89 / 4,673.65	14.88 / 3	**BUG, Peoples Works** **Kent Ave. Brooklyn 11211** **NY**	HSWDS

Reg Site ID:	N	**VOCs:**	No
Site No:		**Semi VOCs:**	Unknown
EPA ID:	NYD980532105	**PCBs:**	No
Is Site Active?:	Unknown	**Pesticides:**	No
Registry:	N	**Metals:**	No
Years of Operation:	1871 to 1895	**Asbestos:**	No
RCRA:	Unknown	**County:**	Kings
HRS Score:	U	**Region:**	2
HRS Date:	U	**Latitude:**	40 43'20"N
Acres:	0.00	**Longitude:**	73 57'35"W
Site Code:	2A	**Quadrangle:**	U
Site Code Desc:	Coal Gasification Plant		
Owner:	Publ Utily		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Name:	Formerly BUG Company
Owner Address:	195 Montague Street Brooklyn NY 11201
Owner Telephone:	(718)403-3053
Operator:	U
Operator Name:	U
Operator Address:	U
Operator Telephone:	U
Completed Investigation:	PA
Samples Collected:	None
Threat to Env/Public Health?:	E
Surface Water Contamination?:	Unknown
Groundwater Contamination?:	Unknown
Drinking Water Contam?:	Unknown
Surface Water Class:	U
Groundwater Class:	U
Active Drinking Water Supply?:	No
Hazard Substance Exposed?:	Unknown
Controlled Site Access?:	Unknown
Ambient Air Contamination?:	U
Threat of Direct Contact?:	Unknown
Doc Fish/Wildlife Mortality?:	Unknown
Impact on Special Status?:	Unknown
TCLP:	
Surface Water:	
Groundwater:	
Drinking Water:	
Fish or Wildlife Mortality:	
Fish or Wildlife Resource:	
Building:	
Hazard Substance Disposed:	Suspected hydrocarbon tars (benzene, pyridene, cresols, toluene, naphthalene, hydrogen sulfide, phenol)
Air:	
Surface Water:	
Surface Soil:	
Waste:	
EP Toxicity:	
Groundwater:	
Sediment:	
Subsurface Soil:	
Leachate:	
Regulatory Agencies Involved:	NYSDEC, CERCLA 103c
Preparer:	Julie Welch EnvEngrTech1 May 27, 1994
Nominated by:	
Describe the Site:	A former coal-gasification plant was purchased by BUG Co. During the operations as a CG plant, a hydrocarbon tar was produced and stored on site until sold for use in roofing or road surfacing. The plant was decommissioned in 1895, all remaining tars were reportedly removed and the facility was razed. Ownership and use of the property since 1895 is unknown.
Describe the Threat:	

The soil is possibly contaminated with trace amounts of hydrocarbon tar. (impact probably reduced due to time and excavation of soils) Leachate into groundwater is not a major concern because area groundwater is not a potable supply.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
242	3 of4	SW	0.89 / 4,673.65	14.88 / 3	BUG, Peoples Works Kent Ave. Brooklyn 11211 NY	HSWDS

Reg Site ID:	N	**VOCs:**	No
Site No:	HS2016	**Semi VOCs:**	Unknown
EPA ID:	NYD980532105	**PCBs:**	No
Is Site Active?:	Unknown	**Pesticides:**	No
Registry:	N	**Metals:**	No
Years of Operation:	1871 to 1895	**Asbestos:**	No
RCRA:	Unknown	**County:**	Kings
HRS Score:	U	**Region:**	2

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

HRS Date:	U	**Latitude:**	40 43'20"N
Acres:	0.00	**Longitude:**	73 57'35"W
Site Code:	2A	**Quadrangle:**	U
Site Code Desc:	Coal Gasification Plant		
Owner:	Publ Utily		
Owner Name:	Formerly BUG Company		
Owner Address:	195 Montague Street Brooklyn NY 11201		
Owner Telephone:	(718)403-3053		
Operator:	U		
Operator Name:	U		
Operator Address:	U		
Operator Telephone:	U		
Completed Investigation:	PA		
Samples Collected:	None		
Threat to Env/Public Health?:	E		
Surface Water Contamination?:	Unknown		
Groundwater Contamination?:	Unknown		
Drinking Water Contam?:	Unknown		
Surface Water Class:	U		
Groundwater Class:	U		
Active Drinking Water Supply?:	No		
Hazard Substance Exposed?:	Unknown		
Controlled Site Access?:	Unknown		
Ambient Air Contamination?:	U		
Threat of Direct Contact?:	Unknown		
Doc Fish/Wildlife Mortality?:	Unknown		
Impact on Special Status?:	Unknown		
TCLP:			
Surface Water:			
Groundwater:			
Drinking Water:			
Fish or Wildlife Mortality:			
Fish or Wildlife Resource:			
Building:			
Hazard Substance Disposed:	Suspected hydrocarbon tars (benzene, pyridene, cresols, toluene, naphthalene, hydrogen sulfide, phenol)		
Air:			
Surface Water:			
Surface Soil:			
Waste:			
EP Toxicity:			
Groundwater:			
Sediment:			
Subsurface Soil:			
Leachate:			
Regulatory Agencies Involved:	NYSDEC, CERCLA 103c		
Preparer:	Julie Welch EnvEngrTech1 May 27, 1994		
Nominated by:			
Describe the Site:	A former coal-gasification plant was purchased by BUG Co. During the operations as a CG plant, a hydrocarbon tar was produced and stored on site until sold for use in roofing or road surfacing. The plant was decommissioned in 1895, all remaining tars were reportedly removed and the facility was razed. Ownership and use of the property since 1895 is unknown.		
Describe the Threat:			

The soil is possibly contaminated with trace amounts of hydrocarbon tar. (impact probably reduced due to time and excavation of soils) Leachate into groundwater is not a major concern because area groundwater is not a potable supply.

242	4 of4	SW	0.89 / 4,673.65	14.88 / 3	BUG, Peoples Works Kent Ave. Brooklyn 11211 NY	HSWDS

Reg Site ID:	N	**VOCs:**	No
Site No:	HS2016	**Semi VOCs:**	Unknown
EPA ID:	NYD980532105	**PCBs:**	No
Is Site Active?:	Unknown	**Pesticides:**	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Registry:	N	**Metals:**	No
Years of Operation:	1871 to 1895	**Asbestos:**	No
RCRA:	Unknown	**County:**	Kings
HRS Score:	U	**Region:**	2
HRS Date:	U	**Latitude:**	40 43'20"N
Acres:	0.00	**Longitude:**	73 57'35"W
Site Code:	2A	**Quadrangle:**	U

Site Code Desc: Coal Gasification Plant
Owner: Publ Utily
Owner Name: Formerly BUG Company
Owner Address: 195 Montague Street
Brooklyn NY 11201
Owner Telephone: (718)403-3053
Operator: U
Operator Name: U
Operator Address: U
Operator Telephone: U
Completed Investigation: PA
Samples Collected: None
Threat to Env/Public Health?: E
Surface Water Contamination?: Unknown
Groundwater Contamination?: Unknown
Drinking Water Contam?: Unknown
Surface Water Class: U
Groundwater Class: U
Active Drinking Water Supply?: No
Hazard Substance Exposed?: Unknown
Controlled Site Access?: Unknown
Ambient Air Contamination?: U
Threat of Direct Contact?: Unknown
Doc Fish/Wildlife Mortality?: Unknown
Impact on Special Status?: Unknown
TCLP:
Surface Water:
Groundwater:
Drinking Water:
Fish or Wildlife Mortality:
Fish or Wildlife Resource:
Building:
Hazard Substance Disposed: Suspected hydrocarbon tars (benzene, pyridene, cresols, toluene, naphthalene, hydrogen sulfide, phenol)
Air:
Surface Water:
Surface Soil:
Waste:
EP Toxicity:
Groundwater:
Sediment:
Subsurface Soil:
Leachate:
Regulatory Agencies Involved: NYSDEC, CERCLA 103c
Preparer: Julie Welch
EnvEngrTech1
May 27, 1994
Nominated by:
Describe the Site: A former coal-gasification plant was purchased by BUG Co. During the operations as a CG plant, a hydrocarbon tar was produced and stored on site until
sold for use in roofing or road surfacing. The plant was decommissioned in 1895, all remaining tars were reportedly removed and the facility was razed.
Ownership and use of the property since 1895 is unknown.
Describe the Threat:

The soil is possibly contaminated with trace amounts of hydrocarbon tar. (impact probably reduced due to time and excavation of soils) Leachate into groundwater is not a major concern because area groundwater is not a potable supply.

243	1 of1	SSW	0.90 / 4,775.99	24.73 / 13	NAVY FIRE FIGHTING SCH	FUDS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					NO CITY NY	

FUDS Property No: C02NY1088
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map?id=54552
FUDS INST ID: NY29799F954900
Status: Properties without projects
SDS ID:
NPL Status Code:
Eligibility: Eligible
Site Eligib:
Current Owner: PRIV: PRIVATE
Has Project: No
DOD FUDS Pro: C02NY1088
Project Required: No
No Further Action:
Congressional District: 07
Congressional Dist 117: 12
Media ID:
Metadata ID:
Feature Desc:
EPA Region: 02
County: KINGS
Latitude: 40.72138889
Longitude: -73.95833333
Fiscal year: 2021
USACE Division: NAD
USACE District: New England District (NAE)
Centroid Lat:
Centroid Long:
Se Anno Cad Data:
Shape Length:
Shape Area:
Shape Len:
X: -73.958312988
Y: 40.7214355470001
Data Source: U.S. Army Corps of Engineers Geospatial Open Data
Property History:

Feature Description:

The site was used by the Department of the Navy as a training facility to instruct Naval personnel to fight ship-board fires.

244	1 of1	SW	0.91 / 4,786.58	15.36 / 3	K - Peoples Works Kent Ave. S. 10th St., S. 11th St. Brooklyn NY 11211	MGP

Site Code: 224053
SWIS Code: 2401
Class: A
Disp Start:
Disp Term:
Allowable Uses: Not Identified
Acres: 0.9
Region: 2
Town: New York City
County: Kings
Latitude: 40.707966212
Longitude: -73.969042621

Detail(s)

Description:

Location: The site is located in Williamsburg area of Brooklyn, Kings County and is at the northwest corner of Kent Avenue and Division Street in the South Williamsburg area of Brooklyn. The western boundary of the site is the Wallabout Channel along the East River. Site Features: The site consists of portions of two parcels identified as a Block 2134, Lots 1 and 150. A portion of Lot 150 is underwater. A bulkhead exists along the length lot 150. The site relief slopes towards the river. The site is currently in redevelopment. The site is enclosed by lockable fencing and is monitored by security personel. Multi-unit residential housing (condominiums) are present north of the Site; Kent Avenue, multi-unit residential housing, and commercial properties are located east; commercial properties are located south; and the East River and Wallabout Channel are located west of the Site. Current Zoning/Uses: The site has an approved zoning amendment with Special Permit modifications for residential (R7-3) zoning designation from the current manufacturing designation (M3-1) with a 100 foot commercial (C2-4) overlay. Most recently the site was used as a lumberyard and retail home center. In 2021 the

buildings were demolished and redevelopment is ongoing. Past Use of the Site: A manufactured gas plant (MGP) formerly Peoples Works (224053), operated on the northern portion of the site prior to 1868 and ceased operations between 1893 and 1896. Other past uses include a lumber yard, stave yard, molasses storage, sugar refining, warehouse storage, and a brewing company. In 1999, LILCO and Brooklyn Union Gas merged to form KeySpan. National Grid acquired KeySpan in 2008 and currently maintains ownership of the site. Site Geology and Hydrogeology: Site is covered with up to 5 feet of fill. This material is typical urban fill, characterized by bricks and gravel. Below the fill materials are sands and silts. Near the river, a wedge of silts and clays was noted, underlain by a peat layer. This lithology reflects palustrine deposits along the East River channel, likely overlain by glacial sands and fill during development of the East River waterfront. Bedrock beneath the Site is the Ravenswood Formation gneiss, and is estimated to be approximately 100 feet bgs. OU1 is the former MGP footprint. Located on a portion of Block 2134 Lot 1 and Lot 150. OU2 includes areas outside the former MGP footprint. Specifically, OU2 includes a parcel north of the former MGP owned by NYC Parks. The parcel included a former embayment now filled in. It is predominantly covered with concrete pavers and asphalt pavement aside from a landscaped area covered with grass and shrubs on a portion of the parcel. OU2 includes the East River adjacent to the MGP footprint and former embayment identified by sediment borings exhibiting observed MGP related impacts.

Assess ENV:

The Site is a Former MGP and it was subject to a Phase II (AKRF) and Site Characterization (Tetratech 2018) and a Site Investigation (Tenen 2014) for BCP site C224053. The primary contaminant of concern for the site is coal tar. Materials such as coal tar are commonly encountered as Non-Aqueous Phase Liquids (NAPL). Coal tar contains both volatile and semi-volatile organic compounds. Specific volatile organic compounds (VOCs) of concern are benzene, toluene, ethylbenzene and xylenes (BTEX). Specific semi-volatile organic compounds of concern are the polycyclic aromatic hydrocarbons (PAHs). Subslab vapor samples indicate other contaminants exist on site related to post MGP operations. Soil: Limited potentially visual or olfactory impacts were identified during this SC investigation. These impacts were noted primarily in the northwest corner of the Site.The MGP-related impacts were also observed located north of the former MGP facility, in the area of a former embayment. BTEX was detected at concentrations that were above their respective NYSDEC Restricted-Residential and Commercial SCOs. Total PAHs ranged from not detect to 6,708.7 mg/kg. PCB's was detected at low concentrations (0.03 mg/kg and below). All pesticides, herbicides, and PCBs were detected at concentrations below their respective NYSDEC Restricted-Residential and Commercial SCOs. Mercury was detected exceeding the Restricted-Residential SCO in one sample (1.42 mg/kg) and exceeded the Commercial SCO in two samples (2.99 and 1.44 mg/kg). Free cyanide was detected but did not exceed applicable SCOs. Groundwater: Benzene was detected at concentrations exceeding the applicable Ambient Water Quality Standards (AWQS) in the groundwater. Ethyl benzene, toluene and total xylenes exceeded applicable AWQS. Tetrachloroethene (PCE), were detected at concentrations exceeding the applicable AWQS. One PAH, naphthalene, was detected in this sample at a concentration exceeding the AWQS. Herbicides, pesticides, and PCBs were not detected in groundwater samples. SVOCs were detected at concentrations exceeding the applicable AWQS Iron, magnesium, manganese and sodium, detected above AWQS, are indicators of groundwater geochemistry. Total BTEX, exceeding 1,000 ug/l, was detected. Total PAHs were detected ranging from 70 to 80 ug/l. Sediment: Potential MGP-related olfactory impacts were identified in sediment borings. Petroleum-like odors were also noted at borings, visual impacts, consisting of NAPL blebs, observed in one sediment. Soil Vapor and Indoor Air Subslab samples detected TCE at a concentration of 881 ug/m3. Subslab detections of petroleum-related compounds were also detected. Alcohol-related compounds above ambient air concentrations, including isopropanol at a concentration of 784 ug/m3 were detected. Soil vapor points detected petroleum-related VOCs at low concentrations, chlorinated solvents were detected: 1,1,1-trichloroethane was detected at a concentration of 1.64 ug/m3; PCE was detected concentration of 14 ug/m3; and, TCE was detected at a concentration of 2.41 ug/m3. Ambient air samples detected low concentrations of: dichlorodifluoromethane, chloromethane, ethanol, acetone, methylene chloride, carbon tetrachloride and toluene.

Assess DOH:

Since the site is fenced and covered by asphalt or concrete, people will not come into contact with site-related soil and groundwater contamination unless they dig below the surface. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion in the current building and any future on-site building development and occupancy.

245	1 of1	ESE	0.92 / 4,846.60	27.21 / 15	**Empire Varnish Company, Inc.** **38 VARICK STREET** **BROOKLYN NY 11222**	SHWS

Site Code:	378382
HW Code:	224123
Program:	HW
Site Class:	C
Site Name:	Empire Varnish Company, Inc.
Site Address:	38 VARICK STREET
City:	BROOKLYN
Zip:	11222
County:	Kings
Region:	2
Town:	New York City
Latitude:	40.726944444
Longitude:	-73.935833333
SWIS:	2401
Acres:	
Record Added:	2007-03-13 12:51:00
Record Update:	2018-02-21 09:32:00

Updated by:	GWBURKE
Site Code (Web):	224123
Program Type (Web):	HW
Site Name (Web):	Empire Varnish Company, Inc.
Site Class (Web):	C
Address1 (Web):	38 VARICK STREET
Address2 (Web):	
Locality (Web):	BROOKLYN
Zip Code (Web):	11222
County (Web):	Kings
Longitude (Web):	-73.935833333
Latitude (Web):	40.726944444
Site Code (GIS):	224123
Site Name (GIS):	Empire Varnish Company, Inc.
Program (GIS):	HW
Site Class (GIS):	C
Address1 (GIS):	38 VARICK STREET
Address2 (GIS):	
Locality (GIS):	BROOKLYN
Zip Code (GIS):	11222
County (GIS):	Kings
Site Class Desc:	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Site Class Desc (Web):	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH:	
Description:	

Empire State Varnish Company, Inc. is located at 38 Varick Street, Brooklyn, NY. The Property is situated along the east side of Varick Street approximately 200 feet from the corner of Bridgewater Street in the Greenpoint section of Brooklyn. The irregular shaped Property also fronts on Bridgewater Street. The Property is zoned M3-1 and consists of an approx. 30,000 sq. ft. lot improved with several small buildings utilized for the production of varnish and paint. Empire has been producing paint and varnish on-site since the 1930's. The production process involves heating and mixing natural or synthetic resins with a vegetable oil. This mixture is then cooled and blended with a volatile solvent in large kettles. The oils primarily used by Empire are soybean and linseed oils. The volatile solvent commonly used by Empire is mineral spirits. The mineral spirits were stored on-site in underground storage tanks until the early 1980's. The facility currently uses only aboveground tanks or 55-gallon drums to store raw materials or finished product on-site. A consent order was completed to close the site under RCRA. Since this site is located across from Exxon site (Greenpoint), Exxon showed interest in acquiring this property to extract the free product in groundwater migrating from their site. RCRA agreed to transfer the Empire site to DER to close the site under the remediation program. Consent order has been amended to transfer the responsibility to DER. Empire has submitted a closure plan and ROUX Associates has submitted a report with the details of their investigation. Closure activities begun in August 2007. All the undergound and above ground tanks were removed along with the drums, containers, cehmical equipments and other misc. items and disposed off-site. The soils excavated during the removal of USTs were sampled and properly disposed. The closure activites were completed in December 2007. The final closure report was submitted in February and was approved. The No Further Action letter was sent to the owner on February 29, 2008.

Assessment:

Other than physical hazards at the site there are no significant environemntal hazards from this site. The groundwater at the site is contaminated but the contamination was contributed from the Exxon Mobil (Greenpoint) spill. Recent investigation results indicate the presence of free product in groundwater at the site. Closure activities begun in August 2007. All the undergound and above ground tanks were removed along with the drums, containers, chemical equipments and other misc. items and disposed off-site. The soils excavated during the removal of USTs were sampled and properly disposed. The closure activites were completed in December 2007. The final closure report was submitted in February and was approved. The No Further Action letter was sent to the owner on February 29, 2008. Now the ownership of the property is transferred to Exxon. The consultant for Exxon is installing extraction wells to remove the free product in the groundwater.

Owner Information

Owner Op:	01

Sub Type: NNN
Owner Name: EMPIRE VARNISH COMPANY, INC.
Owner Company: EMPIRE VARNISH COMPANY, INC.
Owner Street: 38 VARICK STREET
Owner Street 2:
Owner City: BROOKLYN
Owner State: NY
Owner Zip: 11222
Country: United States of America

Owner Op: 04
Sub Type: NNN
Owner Name: EMPIRE VARNISH COMPANY, INC.
Owner Company: EMPIRE VARNISH COMPANY, INC.
Owner Street: 38 VARICK STREET
Owner Street 2:
Owner City: BROOKLYN
Owner State: NY
Owner Zip: 11222
Country: United States of America

Projects Information

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 2008-02-29 00:00:00
End Status: ACT
Operable Unit ID: 1149888
Operable Unit: 01B
Operable Unit Desc: Order on consent:Closure - Soil Removal IRM
Code Name: Remedial Action

Project Code: 04
Project Desc: Remedial Design
Project Refer Name: IRM Soil Removal RD
End Date: 2007-09-30 00:00:00
End Status: ACT
Operable Unit ID: 1149888
Operable Unit: 01B
Operable Unit Desc: Order on consent:Closure - Soil Removal IRM
Code Name: Remedial Design

Project Code: 04
Project Desc: Remedial Design
Project Refer Name: IRM Drum removal RD
End Date: 2007-09-30 00:00:00
End Status: ACT
Operable Unit ID: 1149887
Operable Unit: 01A
Operable Unit Desc: Order on consent:Closure - Drum Removal IRM
Code Name: Remedial Design

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 2008-02-29 00:00:00
End Status: ACT
Operable Unit ID: 1149887
Operable Unit: 01A
Operable Unit Desc: Order on consent:Closure - Drum Removal IRM
Code Name: Remedial Action

Project Code: 01
Project Desc: Site Caracterization
Project Refer Name: Phase I/II Site Investigation
End Date: 2007-04-30 00:00:00
End Status: ACT

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Operable Unit ID: 1135889
Operable Unit: 01
Operable Unit Desc: Order on Consent: Closure
Code Name: Site Characterization

Environmental Remediation

Operable Unit: 01
Contaminants:

Operable Unit: 01B
Contaminants:

Operable Unit: 01A
Contaminants:

---

246 | **1 of1** | **ESE** | **0.92 / 4,871.97** | **36.18 / 24** | **Meeker Avenue Plume Trackdown**
Meeker Avenue
Brooklyn NY 11222 | **SHWS**

Site Code: 375861
HW Code: 224121
Program: HW
Site Class: P
Site Name: Meeker Avenue Plume Trackdown
Site Address: Meeker Avenue
City: Brooklyn
Zip: 11222
County: Kings
Region: 2
Town: New York City
Latitude: 40.726148297
Longitude: -73.936267858
SWIS: 2401
Acres:
Record Added: 2007-01-09 14:37:00
Record Update: 2024-01-17 07:12:00
Updated by: HMDUDEK
Site Code (Web): 224121
Program Type (Web): HW
Site Name (Web): Meeker Avenue Plume Trackdown
Site Class (Web): P
Address1 (Web): Meeker Avenue
Address2 (Web):
Locality (Web): Brooklyn
Zip Code (Web): 11222
County (Web): Kings
Longitude (Web): -73.936267858
Latitude (Web): 40.726148297
Site Code (GIS): 224121
Site Name (GIS): Meeker Avenue Plume Trackdown
Program (GIS): HW
Site Class (GIS): P
Address1 (GIS): Meeker Avenue
Address2 (GIS):
Locality (GIS): Brooklyn
Zip Code (GIS): 11222
County (GIS): Kings
Site Class Desc: Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.

Site Class Desc (Web): Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.

Assess DOH: The site encompasses several city blocks occupied by a dense mixture of residential and manufacturing buildings, including commercial and industrial facilities. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion for any existing buildings or any future development and occupancy. Sub-slab depressurization systems (systems that ventilate/remove the air beneath the building) have been installed in several buildings within the site boundary to prevent the indoor air from being affected by the contamination in soil vapor beneath the buildings. However, additional evaluations of the potential for soil vapor intrusion to occur are needed so that all site related exposure routes are identified.

Description:

Location: The Site is located in the Greenpoint and East Williamsburg sections of Brooklyn. The area currently being investigated is bounded by the former Mobil Brooklyn Refinery/current British Petroleum (BP) Terminal to the north along Norman Avenue and Bridgewater Street, Newtown Creek to the east, Lombardy and Withers Streets to the south, and Kingsland (aka Grandparents) Avenue to the west. Site Features: The elevated Brooklyn-Queens Expressway (I-278) bisects the Site. Current Zoning and Land Use: Primarily, the Meeker area is zoned for commercial and industrial uses; however, the area also includes a residential component. Buildings where mixed use exists generally have commercial space on the 1st floor, and residential space above. Past Use of the Site: This section of Brooklyn has a long industrial history. Investigations conducted by the Exxon Mobil Corporation and the New York State DOT between 2005 and 2006 indicated the presence of chlorinated volatile organic compounds (CVOCs) (primarily tetrachloroethene and trichloroethene) in soil, soil gas, and groundwater at several different locations throughout the study area immediately adjacent to the Exxon Mobil petroleum plume. Based on this information, the Department began investigations in 2007 in order to determine the source(s) of this contamination. To date, six (6) distinct sources of contamination have been identified - Former Spic and Span Cleaners and Dyers (DEC ID No. 224129), Former Klink Cosmo Cleaners (DEC ID No. 224130), ACME Steel/Metal Works (DEC ID No. 224131), ACME Steel/Brass Foundry (DEC ID No. 224132), Former Lombardy Street Lacquer and Soap Mfg. (DEC ID No. 224182), and Former Goodman Brothers Steel Drum Co. (DEC ID No. 224211). All six (6) locations have been listed in the Registry of Inactive Hazardous Waste Disposal Sites as Class 2 sites. Meeker Avenue Plume added to the Federal Register as a National Priorities List site in March 2022. Site Geology and Hydrogeology: The Site is underlain by a fill unit (0.5-11' thick); below the fill unit, in descending order, are the following geologic units, with varying thicknesses throughout the Site - a sandy unit or a silty sand unit (depending on the location), a discontinuous clayey silt unit or a discontinuous glacial till unit (depending on the location), a sand and gravel unit, and the Raritan Formation (located 108-138' below ground surface). Groundwater generally flows towards the northeast, in the direction of Newtown Creek. Depth to water ranges from 11 - 55' below ground surface.

Assessment:

Nature and Extent of Contamination: -Groundwater Concentrations of tetrachloroethene (PCE), trichloroethene (TCE), cis-1,2-dichloroethene (DCE), and vinyl chloride (VC) have been found well above Part 703.5 class GA standards. Specifically, PCE was found at concentrations up to 120,000 ppb (5 ppb standard), TCE was found at concentrations up to 70,000 ppb (5 ppb standard), DCE was found at concentrations up to 95,000 ppb (5 ppb standard), and VC was found at concentrations up to 3,200 ppb (2 ppb standard). -Soil Concentrations of PCE have been found in soil up to 290,000 ppm, well above the soil cleanup objective for unrestricted use (1.3 ppm). -Soil Vapor and Indoor Air Concentrations of PCE in soil vapor have been found up to 48,200,000 ug/m^3, and in indoor air up to 170 ug/m^3. Concentrations of TCE have been found in soil vapor up to 230,000 ug/m^3, and in indoor air up to 13 ug/m^3.

Owner Information

Owner Op: 19
Sub Type: C04
Owner Name: David Camara
Owner Company: Brooklyn Public Library - Leonard Branch
Owner Street: 81 Devoe Street
Owner Street 2:
Owner City: Brooklyn
Owner State: NY
Owner Zip: 11211
Country: United States of America

Owner Op: 19
Sub Type: C05
Owner Name:
Owner Company: BROOKLYN COMMUNITY BOARD #1

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Street: 435 GRAHAM AVENUE
Owner Street 2:
Owner City: BROOKLYN
Owner State: NY
Owner Zip: 11222
Country: United States of America

Environmental Remediation

Operable Unit: 01
Contaminants: tetrachloroethene (PCE), trichloroethene (TCE)

Operable Unit: 00
Contaminants: tetrachloroethene (PCE), trichloroethene (TCE)

247	1 of1	SW	0.98 / 5,172.53	10.81 / -1	**Kent Terminal** **Kent Ave. between 5th-11th St.** **Brooklyn NY 11211**	SHWS

Site Code: 338767
HW Code: 224029
Program: HW
Site Class: N
Site Name: Kent Terminal
Site Address: Kent Ave. between 5th-11th St.
City: Brooklyn
Zip: 11211
County: Kings
Region: 2
Town: New York City
Latitude: 40.721489791
Longitude: -73.961615694
SWIS: 2401
Acres:
Record Added: 1999-11-18 12:00:00
Record Update: 2009-03-30 14:20:00
Updated by: BRWOLOSE
Site Code (Web): 224029
Program Type (Web): HW
Site Name (Web): Kent Terminal
Site Class (Web): N
Address1 (Web): Kent Ave. between 5th-11th St.
Address2 (Web):
Locality (Web): Brooklyn
Zip Code (Web): 11211
County (Web): Kings
Longitude (Web): -73.961615694
Latitude (Web): 40.721489791
Site Code (GIS): 224029
Site Name (GIS): Kent Terminal
Program (GIS): HW
Site Class (GIS): N
Address1 (GIS): Kent Ave. between 5th-11th St.
Address2 (GIS):
Locality (GIS): Brooklyn
Zip Code (GIS): 11211
County (GIS): Kings
Site Class Desc: No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to

Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Site Class Desc (Web): No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH:
Description:

The site did not qualify for addition to the Registry of Inactive Hazardous Disposal Sites

Assessment:

Projects Information

Project Code: 01
Project Desc: Site Caracterization
Project Refer Name:
End Date: 1997-02-01 00:00:00
End Status: ACT
Operable Unit ID: 1100677
Operable Unit: 01
Operable Unit Desc: KENT TERMINAL SITE
Code Name: Site Characterization

Environmental Remediation

Operable Unit: 01
Contaminants:

---

248 | ***1 of1*** | ***NNW*** | ***0.99 / 5,225.90*** | ***4.74 / -7*** | ***Queens West - North 46-00 FIFTH STREET LONG ISLAND CITY NY 11101*** | ***SHWS***

Site Code: 55923
HW Code: 241011
Program: HW
Site Class: N
Site Name: Queens West - North
Site Address: 46-00 FIFTH STREET
City: LONG ISLAND CITY
Zip: 11101
County: Queens
Region: 2
Town: New York City
Latitude: 40.747587610

Longitude:	-73.956448830
SWIS:	4101
Acres:	
Record Added:	1999-11-18 12:00:00
Record Update:	2006-07-28 15:22:00
Updated by:	mobarrie
Site Code (Web):	241011
Program Type (Web):	HW
Site Name (Web):	Queens West - North
Site Class (Web):	N
Address1 (Web):	46-00 Fifth Street
Address2 (Web):	
Locality (Web):	Long Island City
Zip Code (Web):	11101
County (Web):	Queens
Longitude (Web):	-73.956448830
Latitude (Web):	40.747587610
Site Code (GIS):	241011
Site Name (GIS):	Queens West - North
Program (GIS):	HW
Site Class (GIS):	N
Address1 (GIS):	46-00 FIFTH STREET
Address2 (GIS):	
Locality (GIS):	LONG ISLAND CITY
Zip Code (GIS):	11101
County (GIS):	Queens
Site Class Desc:	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced; c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.
Site Class Desc (Web):	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced; c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.
Assess DOH:	
Description:	

See site no. V00505A, V00505B, 00505C and V00505D.

Assessment:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Environmental Remediation

Operable Unit: 01
Contaminants:

Unplottable Summary

Total: 20 Unplottable sites

DB	Company Name/Site Name	Address	City	Zip	ERIS ID
ERNS		INDIA ST WEST ST ***NRC Report No:*** 1030166	BROOKLYN NY		806807203
GEN MANIFEST	NYNEX	JAVA ST	BROOKLYN NY		874641041
GEN MANIFEST	CON EDISON	SEC MCGUINESS BLVD SB12440	BROOKLYN NY	11201	874649079
GEN MANIFEST	CONSOLIDATED EDISON	INDIA ST & DEAD END - MH 70123	BROOKLYN NY	11201	874611813
GEN MANIFEST	CON EDISON	PROVOST ST	BROOKLYN NY	11222	874711124
GEN MANIFEST	CONSOLIDATED EDISON	MH 4308 - JAVA ST	QUEENS NY		874655229
GEN MANIFEST	CONSOLIDATED EDISON CO	MCGUINISS & INDIA	NY		874614831
HSWDS	BUG, Peoples Works	Kent Ave. Brooklyn 11211	NY		863415272
LST	CONTINENTAL WAREHOUSE	23RD STREET ***Spill No	Close Date:*** 9515551 | 03/04/1996 12:00:00 AM	BROOKLYN NY		814016928
LST	1621 EAST KENT STREET	1621 EAST KENT STREET ***Spill No	Close Date:*** 9209000 | 11/04/1992 12:00:00 AM	BROOKLYN NY		814040909
LST	MCCARREN COMFORT STSTION	LORIMER ST ***Spill No	Close Date:*** 1703018 | 10/11/2017 12:00:00 AM	BROOKLYN NY		861941530
NY SPILLS	FRANKLIN STREET	HURON STREET	BROOKLYN NY		813966544

Spill No* | *Close Date: 9604494 | 06/09/2006 12:00:00 AM

NY SPILLS	NEWTOWN CREEK	MCGUINESS BLVD	BROOKLYN NY		813634508
		***Spill No*	*Close Date:*** 1302307	06/04/2013 12:00:00 AM	
NY SPILLS	NEWTOWN CREEK WPCP DEP -DDC	301 GREEN POINT AVENUE	QUEENS NY		813642614
		***Spill No*	*Close Date:*** 9504303	04/29/2004 12:00:00 AM	
NY SPILLS	MCGUINNSS BLVD/BKLYN	MCGUINNESS BLVD	BROOKLYN NY		813652690
		***Spill No*	*Close Date:*** 8906523	10/03/1989 12:00:00 AM	
NY SPILLS	249	HURON ST	BROOKLYN NY		813752969
		***Spill No*	*Close Date:*** 0001313	05/04/2000 12:00:00 AM	
NY SPILLS	BY BULASKI BRIDGE	MCGUINESS AVE	BROOKLYN NY		895590982
		***Spill No*	*Close Date:*** 2108757	12/31/2021 12:00:00 AM	
NY SPILLS	NEWTOWN CREEK SEWER PLANT	301 GREEN POINT AV	QUEENS NY		813847164
		***Spill No*	*Close Date:*** 9710321	04/08/1998 12:00:00 AM	
NY SPILLS	MAN HOLE # 64501	GREEN AVE	BROOKLYN NY		813782116
		***Spill No*	*Close Date:*** 0211422	04/03/2003 12:00:00 AM	
SWF/LF	GREENPOINT INCINERATOR (NYCDOS)	N. HENRY STREET	Brooklyn NY	11222	881498645

Unplottable Report

Site:

INDIA ST WEST ST BROOKLYN NY

ERNS

NRC Report No:	1030166	***Latitude Degrees:***	
Type of Incident:	FIXED	***Latitude Minutes:***	
Incident Cause:	UNKNOWN	***Latitude Seconds:***	
Incident Date:	09-Nov-2012 15:00:00	***Longitude Degrees:***	
Incident Location:		***Longitude Minutes:***	
Incident Dtg:	DISCOVERED	***Longitude Seconds:***	
Distance from City:		***Lat Quad:***	
Distance Units:		***Long Quad:***	
Direction from City:		***Location Section:***	
Location County:	KINGS(BROOKLYN)	***Location Township:***	
Potential Flag:	No	***Location Range:***	
Year:	Year 2012 Reports		

Description of Incident: DIELECTRIC FLUID WAS FOUND IN A VAULT. THE CAUSE AND SOURCE ARE UNKNOWN.

Material Spill Information

Chris Code:	OTH	***Unit of Measure:***	GALLON(S)
CAS No:	000000-00-0	***If Reached Water:***	UNKNOWN
UN No:		***Amount in Water:***	0
Name of Material:	DIELECTRIC FLUID	***Unit Reach Water:***	UNKNOWN AMOUNT
Amount of Material:	100		

Calls Information

Date Time Received:	09-Nov-2012 15:33:05	***Responsible City:***	NEW YORK
Date Time Complete:	09-Nov-2012 15:39:23	***Responsible State:***	NY
Call Type:	INC	***Responsible Zip:***	10003
Resp Company:	CONSOLIDATED EDISON COMPANY OF NEW YORK	***Source:***	TELEPHONE
Resp Org Type:	PUBLIC UTILITY		

Incident Information

Tank ID:		***Building ID:***	
Tank Regulated:	U	***Location Area ID:***	
Tank Regulated By:		***Location Block ID:***	
Capacity of Tank:		***OCSG No:***	
Capacity Tank Units:		***OCSP No:***	
Description of Tank:		***State Lease No:***	
Actual Amount:		***Pier Dock No:***	
Actual Amount Units:		***Berth Slip No:***	
Tank Above Ground:	ABOVE	***Brake Failure:***	U
NPDES:		***Airbag Deployed:***	U
NPDES Compliance:	U	***Transport Contain:***	U
Init Contin Rel No:		***Location Subdiv:***	
Contin Rel Permit:		***Platform Rig Name:***	
Contin Release Type:		***Platform Letter:***	
Aircraft ID:		***Allision:***	U
Aircraft Runway No:		***Type of Structure:***	
Aircraft Spot No:		***Structure Name:***	
Aircraft Type:		***Structure Oper:***	U
Aircraft Model:		***Transit Bus Flag:***	
Aircraft Fuel Cap:		***Date Time Norm Serv:***	
Aircraft Fuel Cap U:		***Serv Disrupt Time:***	
Aircraft Fuel on Brd:		***Serv Disrupt Units:***	
Aircraft Fuel OB U:		***CR Begin Date:***	

Aircraft Hanger:		***CR End Date:***	
Road Mile Marker:		***CR Change Date:***	
Power Gen Facility:	N	***FBI Contact:***	
Generating Capacity:		***FBI Contact Dt Tm:***	
Type of Fixed Obj:	UNKNOWN	***Passenger Handling:***	
Type of Fuel:		***Passenger Route:***	XXX
DOT Crossing No:		***Passenger Delay:***	XXX
DOT Regulated:	U	***Sub Part C Test Req:***	XXX
Pipeline Type:		***Conductor Test:***	
Pipeline Abv Ground:	ABOVE	***Engineer Test:***	
Pipeline Covered:	U	***Trainman Test:***	
Exposed Underwater:	N	***Yard Foreman Test:***	
Railroad Hotline:		***RCL Operator Test:***	
Railroad Milepost:		***Brakeman Test:***	
Grade Crossing:	U	***Train Dispat Test:***	
Crossing Device Ty:		***Signalman Test:***	
Ty Vehicle Involved:		***Oth Employee Test:***	
Device Operational:	U	***Unknown Test:***	

Incident Details Information

Release Secured:	U	***State Agen Report No:***	
Release Rate:		***State Agen on Scene:***	
Release Rate Unit:		***State Agen Notified:***	
Release Rate Rate:		***Fed Agency Notified:***	
Est Duration of Rel:		***Oth Agency Notified:***	
Desc Remedial Act:		***Body of Water:***	
Fire Involved:	N	***Tributary of:***	
Fire Extinguished:	U	***Near River Mile Make:***	
Any Evacuations:	N	***Near River Mile Mark:***	
No Evacuated:		***Offshore:***	N
Who Evacuated:		***Weather Conditions:***	PARTLY CLOUDY
Radius of Evac:		***Air Temperature:***	53
Any Injuries:	N	***Wind Direction:***	NW
No. Injured:		***Wind Speed:***	14
No. Hospitalized:		***Wind Speed Unit:***	MPH
No. Fatalities:		***Water Supp Contam:***	U
Any Fatalities:	N	***Water Temperature:***	
Any Damages:	N	***Wave Condition:***	
Damage Amount:		***Current Speed:***	
Air Corridor Closed:	N	***Current Direction:***	
Air Corridor Desc:		***Current Speed Unit:***	
Air Closure Time:		***EMPL Fatality:***	
Waterway Closed:	N	***Pass Fatality:***	
Waterway Desc:		***Community Impact:***	
Waterway Close Time:		***Passengers Transfer:***	NO
Road Closed:	N	***Passenger Injuries:***	
Road Desc:		***Employee Injuries:***	
Road Closure Time:		***Occupant Fatality:***	
Road Closure Units:		***Sheen Size:***	
Closure Direction:		***Sheen Size Units:***	
Major Artery:	No	***Sheen Size Length:***	
Track Closed:	N	***Sheen Size Length U:***	
Track Desc:		***Sheen Size Width:***	
Track Closure Time:		***Sheen Size Width U:***	
Track Closure Units:		***Sheen Color:***	
Track Close Dir:		***Dir of Sheen Travel:***	
Media Interest:	NONE	***Sheen Odor Desc:***	
Medium Desc:	SUBSURFACE	***Duration Unit:***	
Addl Medium Info:	ELECTRICAL VAULT	***Additional Info:***	CALLER INTENDS TO NOTIFY THE STATE AND CITY.

Site: ***NYNEX***
JAVA ST BROOKLYN NY

GEN MANIFEST

RCRA ID:	NYP000932111	***Mailing State:***	NY
District Name:	NYNEX	***Mailing ZIP:***	10016
Contact Name:	V ORCHIER	***Mailing ZIP Ext:***	
Business Phone No:	2123387126	***Mailing Country:***	USA

Mailing Street 1:	221 EAST 37TH STREET	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	NEW YORK	***Location County:***	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1996: 1600 Pounds

Site: ***CON EDISON***
SEC MCGUINESS BLVD SB12440 BROOKLYN NY 11201

GEN MANIFEST

RCRA ID:	NYP004752093	***Mailing State:***	NY
District Name:	CON EDISON	***Mailing ZIP:***	10003
Contact Name:	CON EDISON	***Mailing ZIP Ext:***	
Business Phone No:		***Mailing Country:***	USA
Mailing Street 1:	4 IRVING PL	***Location ZIP Ext:***	
Mailing Street 2:	15TH FL	***Location Country:***	USA
Mailing City:	NEW YORK	***Location County:***	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 1000 Pounds

Site: ***CONSOLIDATED EDISON***
INDIA ST & DEAD END - MH 70123 BROOKLYN NY 11201

GEN MANIFEST

RCRA ID:	NYP004183463	***Mailing State:***	NY
District Name:	CONSOLIDATED EDISON	***Mailing ZIP:***	10003
Contact Name:	FRANKLYN MURRAY	***Mailing ZIP Ext:***	
Business Phone No:	2124602808	***Mailing Country:***	USA
Mailing Street 1:	4 IRVING PLACE RM 828	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	NEW YORK	***Location County:***	KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2009: 200 Gallons

Site: ***CON EDISON***
PROVOST ST BROOKLYN NY 11222

GEN MANIFEST

RCRA ID:	NYP004290326	***Mailing State:***	NY
District Name:	CON EDISON	***Mailing ZIP:***	10003
Contact Name:	TOM TEELING	***Mailing ZIP Ext:***	
Business Phone No:	2124603770	***Mailing Country:***	USA
Mailing Street 1:	4 IRVING PLACE 15TH FLOOR	***Location ZIP Ext:***	

Mailing Street 2:
Mailing City: NEW YORK
Location Country: USA
Location County: KINGS

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2013: 300 Gallons

Site: ***CONSOLIDATED EDISON***
MH 4308 - JAVA ST QUEENS NY

GEN MANIFEST

RCRA ID: NYP004008553
District Name: CONSOLIDATED EDISON
Contact Name: FRANKLIN MURRAY
Business Phone No: 2124602808
Mailing Street 1: 4 IRVING PLACE RM 828
Mailing Street 2:
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: QUEENS

Manifest Information

Waste Code(s):

B003: (Wastes containing polychlorinated biphenyls (PCBs)) Petroleum oil or other liquid containing 500 ppm or greater of PCBs.

Waste Amounts By Year:

1997: 3236 Kilograms

Manifest Information

Waste Code(s):

B007: (Wastes containing polychlorinated biphenyls (PCBs)) Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Waste Amounts By Year:

1997: 1 Cubic yards; 1 Cubic yards

Site: ***CONSOLIDATED EDISON CO***
MCGUINISS & INDIA NY

GEN MANIFEST

RCRA ID: NYP004024030
District Name: CONSOLIDATED EDISON CO
Contact Name: FRANKLIN MURRAY
Business Phone No: 2124602808
Mailing Street 1: 4 IRVING PLACE RM 828
Mailing Street 2:
Mailing City: NEW YORK
Mailing State: NY
Mailing ZIP: 10003
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: QUEENS

Manifest Information

Waste Code(s):

B007: (Wastes containing polychlorinated biphenyls (PCBs)) Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Waste Amounts By Year:

1998: 227 Kilograms

Site: ***BUG, Peoples Works***
Kent Ave. Brooklyn 11211 NY

HSWDS

Reg Site ID:	N	***VOCs:***	
Site No:	HS2016	***Semi VOCs:***	
EPA ID:	NYD980532105	***PCBs:***	
Is Site Active?:		***Pesticides:***	
Registry:	N	***Metals:***	
Years of Operation:		***Asbestos:***	
RCRA:		***County:***	Kings
HRS Score:		***Region:***	2
HRS Date:		***Latitude:***	
Acres:		***Longitude:***	
Site Code:	2A	***Quadrangle:***	
Site Code Desc:	Coal Gasification Plant		
Owner:	Formerly BUG Company		
Owner Name:			
Owner Address:			
Owner Telephone:			
Operator:	U		
Operator Name:			
Operator Address:			
Operator Telephone:			
Completed Investigation:			
Samples Collected:			
Threat to Env/Public Health?:			
Surface Water Contamination?:			
Groundwater Contamination?:			
Drinking Water Contam?:			
Surface Water Class:			
Groundwater Class:			
Active Drinking Water Supply?:			
Hazard Substance Exposed?:			
Controlled Site Access?:			
Ambient Air Contamination?:			
Threat of Direct Contact?:			
Doc Fish/Wildlife Mortality?:			
Impact on Special Status?:			
TCLP:			
Surface Water:			
Groundwater:			
Drinking Water:			
Fish or Wildlife Mortality:			
Fish or Wildlife Resource:			
Building:			
Hazard Substance Disposed:	Suspected hydrocarbon tars (benzene, pyridene, cresols, toluene, naphthalene, hydrogen sulfide, phenol)		
Air:			
Surface Water:			
Surface Soil:			
Waste:			
EP Toxicity:			
Groundwater:			
Sediment:			
Subsurface Soil:			
Leachate:			
Regulatory Agencies Involved:			
Preparer:			
Nominated by:			
Describe the Site:	A former coal-gasification plant was purchased by BUG Co. During the operations as a CG plant, a hydrocarbon tar was produced and stored on site until sold for use in roofing or road surfacing. The plant was decommissioned in 1895, all remaining tars were reportedly removed and the facility was razed. Ownership and use of the property since 1895 is unknown.		
Describe the Threat:			

The soil is possibly contaminated with trace amounts of hydrocarbon tar. (impact probably reduced due to time and excavation of soils) Leachate into groundwater is not a major concern because area groundwater is not a potable supply.

Site: ***CONTINENTAL WAREHOUSE***
23RD STREET BROOKLYN NY

LST

Spill No:	9515551	***REM Phase:***	0
Site ID:	299931	***UST Trust:***	False
DER Facility ID:	242638	***Spill Date:***	03/04/1996 10:10:00 AM
CID:	275	***Rcvd Date:***	03/04/1996 11:16:00 AM
Program Type:	ER	***CAC Date:***	
SWIS Code:	2401	***Insp Date:***	
Contribute Factor:	Tank Failure	***Close Date:***	03/04/1996 12:00:00 AM
Water Body:		***Create Date:***	03/04/1996 12:00:00 AM
Class:	C4	***Update Date:***	03/26/1996 12:00:00 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	KSTANG
County:	Kings	***After Hours:***	False
Referred to:			
Reported by:	Responsible Party		
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"foreign object punctured saddle tank - spill has been contained - firedept is on scene at this time - 150 gallon tank"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG SPOKE TO OPERATOR @ WAREHOUSE, SAID ONLY 6 GALLONS OF OIL IN GROUND, CLEANED UP - NYFD PUMPPED OUT TANK, WILL RECYCLE OIL - FAX CONTRACTOR LIST TO WAREHOUSE FOR PROPER DISPOSAL OF DRUMED WASTE."

Material Information

OP Unit ID:	1030207	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	355673	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	150.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	MARYBETH ACKERS
Spiller Company:	NEWPORT TRANSPORT
Spiller Address:	1397 PROGRESS RD
Spiller City:	SUFFOLK
Spiller State:	VA
Spiller Zip:	23434-
Spiller Country:	001
Contact Name:	
Contact Phone:	(718) 499-6300
Contact Ext:	
Latitude:	40.666729994
Longitude:	-73.982980000

Site: ***1621 EAST KENT STREET***
1621 EAST KENT STREET BROOKLYN NY

LST

Spill No:	9209000	***REM Phase:***	0
Site ID:	66535	***UST Trust:***	False

DER Facility ID:	63691	***Spill Date:***	11/04/1992 11:10:00 AM
CID:		***Rcvd Date:***	11/04/1992 11:40:00 AM
Program Type:	ER	***CAC Date:***	11/04/1992 12:00:00 AM
SWIS Code:	2401	***Insp Date:***	
Contribute Factor:	Tank Failure	***Close Date:***	11/04/1992 12:00:00 AM
Water Body:		***Create Date:***	11/04/1992 12:00:00 AM
Class:	C4	***Update Date:***	09/30/2004 09:28:29 PM
Meets Std:	True	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	O'DOWD
County:	Kings	***After Hours:***	False
Referred to:			
Reported by:	Other		
Source:	Private Dwelling		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"TANK CORRODED CONTAINED ON CONCRETE FLOOR-TANK TO BE REPAIRED BEFORE ANY FUTURE OIL DELIVERY/SORBENT PAD NOW UNDER TANK"

Dec Remark:

""

Material Information

OP Unit ID:	972533	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	564630	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	1.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	***Update***
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

Site: ***MCCARREN COMFORT STSTION***
LORIMER ST BROOKLYN NY

LST

Spill No:	1703018	***REM Phase:***	0
Site ID:	553173	***UST Trust:***	False
DER Facility ID:	231932	***Spill Date:***	06/27/2017 11:25:00 AM
CID:		***Rcvd Date:***	06/27/2017 11:25:00 AM
Program Type:	ER	***CAC Date:***	
SWIS Code:	2401	***Insp Date:***	
Contribute Factor:	Tank Test Failure	***Close Date:***	10/11/2017 12:00:00 AM
Water Body:		***Create Date:***	06/27/2017 11:27:00 AM
Class:	D4	***Update Date:***	10/11/2017 10:59:09 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	TJDEMEO

County:	Kings	***After Hours:***	False
Referred to:			
Reported by:	Other		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"1080 gal ust"

Dec Remark:

"06/27/17 - Lakhani A 1080 gallon UST failed a tank tightness test due to a dry leak. A bad return line was found to be an issue and it appeared to have been disconnected between the building and the tank. The tank stores #2 fuel oil. The tank belongs to NYC Parks Department. Parks Compliance Dept contact is Justin Bauer (Justin.bauer@parks.nyc.gov, 212-360-3433). TTF sent to Justin. Uploaded to D2. 10/5/17 TJD Sent email to Justin Bauer at NYC Parks requesting update including the submission of all documentation associated with the investigation, repairs and testing with the involved UST. Awaiting requested documentation. 10/11/17 TJD File review. Closure documentation received from NYC Parks. As per report, initial tank test failure was reported as a dry leak. Repair work was conducted on July 5th, 2017 by AARCO Environmental - the return line was discovered to be improperly connected to the vent pipe - repair was made and system was retested with passing results. No discharge to environment from reported tank test failure. All documentation has been uploaded to DECDOCS. Spill closed."

Material Information

OP Unit ID:	1301257	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2307633	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	MCCARREN COMFORT STSTION
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	JUSTIN
Contact Phone:	(212) 360-3433
Contact Ext:	
Latitude:	
Longitude:	

Site: ***FRANKLIN STREET***
HURON STREET BROOKLYN NY

NY SPILLS

Spill No:	9604494	***UST Trust:***	False
Site ID:	192977	***Spill Date:***	07/05/1996 09:15:00 AM
DER Facility ID:	160912	***Received Date:***	07/05/1996 09:59:00 AM
CID:	205	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	06/09/2006 12:00:00 AM
Water Body:		***Create Date:***	07/05/1996 12:00:00 AM
Class:	C4	***Update Date:***	06/09/2006 02:48:22 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	JHOCONNE
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		

Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"con ed's no.7 fuel oil line leaking under ground."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL 2 BLOCKS. NO SEWERS. LINE SHUTDOWN. MEG FOR CLEANUP. 7/6/96 - Update from Steve Romano, Con Ed CIG: as of 00:05 hrs, they have excavated 25' of pipe. Removed 1200 gallons oil, 80 yds soil. <2 gallons in sewer - contained with pigs and pads. (CAE) 7/7/96, 9:10 AM - update from Lisa Primeggia, CIG: located leak at 0800 rhs. 2 or 3 pinhole leaks. 2000 gallons oil recovered. (CAE) 7/22/96: memo from Mike Mulqueen to Randy Austin detailing his and Chris Engelhardt's oversight of the clean up efforts. Mark Tibbe made initial response on 7/5. Mulqueen and Engelhardt made subsequent site visits and inspections on 7/9 and 7/16. 7/23/96, 2:00 PM: Katz met at site with Eddy Louie (Env. Affairs), John Mitchell and Carmine Sabatasso (Underground Transmissions). Con Ed has made the permanent repair to the pipeline. Underground Transmissions wasnts to backfill the existing excavation so that they can continue west into Franklin Avenue and north as well to invetsigate pipe offset. They must remove pre-existing and current sheeting, backfill the hole and cap with concrete. They will set a well in the excavation prior to backfilling and one in additional excavation as well (total of 2 wells). (GHK) 8/5/96: Inspected north of offset of continuing excavation (plan to excavate another 8 feet and install well as per Carmine Sabatasso). They are in process of installing sheeting. Will excavate to ground water. They need to move north 8 feet to the end of the offset so that they can inspect the offset welds. (GHK) 11/1/96, 10:00 AM: Katz on site with Sabatasso, Eddy Louie. Approved backfilling of excavation upon visual inspection. Carmine will contact Katz when he reaches contamination along the west side of Franklin Ave. Cannot collect sidewall or bottom samples because of shoring and ground water conditions. Will submit all manifests on soil removeal and disposal sampling. However, 2 wells were installed in the excavation so far. More contamination may be found on the west side of Franklin Ave. Some oil is coming in through shoring. (GHK) 11/5/96: e-mail from Eddy Louie to Glen Katz: Glen, I am writing to follow up on our brief meeting on 11/1 with Carmine Sabatasso at the above-referenced spill site along our Pipeline No. 7. Based on a visual inspection of the excavation on the northeast corner of Franklin and Huron, you agreed that the excavation is sufficiently clean for Con Edison to backfill it. This would allow Con Edison to proceed with an additional excavation on the other side of the sheeting (i.e., west of the old excavation). The Company's section-by-sectionexcavation/cleanup procedure minimizes disruption to traffic. We have checked the two sections closed to date and you agree that they both appear to be visibly clean. ...As we discussed, Con Edison will provide DEC with detailed information regarding the quantities of soil and water removed during the entire clean up operation when this project has been completed. Any analytical data and the groundwater monitoring information will also be included in the report. Currently, Con Edison has installed two wells at the site. 1/15/97, 10:30 AM: Katz met with Eddy Louie and John Mitchell. * Took photographs of excavation. Shows 24 gas main, Con Ed fuel oil pipeline to the right of shored (300 psi main). * Approved Con Ed to backfill and continue south to the last area. * Observed Brooklyn Union Gas inspecting 300 psi gas main. They indicated that the main was in good shape and that no damage had occurred as a result of the release. * Asked Eddy Louie to have the wells checked in my presence. The well located in the northbound lane of Franklin and middle of Huron St. had substantial #6 oil in the well. * Also had Con Ed pull some vault lids in the vicinity - OK. * Told Eddy that this will require more than monthly monitoring as he suggested. (GHK) 1/16/97: letter from Katz to Eddy Louie: ...As a result of the release and its impact to soil and groundwater DEC requires the submission of a SiteSpecific Work Plan (WP) within 60 days of receipt of thi sletter. The WP should include but not be limited to the survey and upgrade of existing groundwater monitoring wells; a scaled site map; and proposed additional boring and well locations for horizontal and vertical delineation of the plume. In the interim, Con Ed shall implement free product recovery from the existing impacted monitoring wells on a daily basis through the duration of the pipeline inspection and weekly thereafter. 2/13/97, 10:00 AM: Chritine Kovari, Con Ed EA - * will survey existing mws for groundwater flow; * continue to evacuate well with product weekly until further notice; * will monitor & bail for 10 week period; * will generate letter w/ gw flow map, proposed boring and well locations. (GHK) 6/26/97: C. Kovari faxes groundwater monitoring and product bailing data. For period 1/24/97 through 5/30/97 approximatley 20.75 gallons of oil and 1280 gallons of water were recovered from the two wells utilizing a vac truck. Con Ed requests to scaled back monitoring & bailing to monthly. According to records, trace amounts of product continue to be found in all 4 wells. 1/98: C. Kovari - consultant is preparing report for submittal - to request closure. 2 new wells installed, no free product found. 3/10/99: Con Ed submits Subsurface Investigation at: Franklin and Huron, Brooklyn, NY , prepared by Miller Environmental Group. 2/3/03: e-mail from Rich Perusse (Con Ed Remediation) to O'Connell: Jane, As I mentioned in an earlier email, we (Remediation) plan to support Steam/Central Engineering during the integrity testing of the next section of Pipeline 7. We will also concurrently address Appendix B Site 25 and capture a couple of other spills during the work. These include N14th/Franklin, N12th manhole, and possibly others identified prior to or during the work (perhaps during FOIL review of DEC files). I understand that we had a spill (DEC #9604494) at the corner of Huron and Franklin in 1996 and subsequently conducted an investigation/remediation. A report and closure request were submitted to Chris Engelhardt on March 10, 1999. There is nothing in my files to indicate that DEC responded to the report and closure request. Is this spill still open? Is further work needed to close this spill? Please let me know. If the spill is still open, I may roll it into the Site 25. O'Connell replied: Hey Rich: I looked through the file for this spill and found the closure report. Doesn't look like Chris looked at it before he left. I can take a quick look at it, but to be on the safe side I'd say to add it to site 25 for now. I'll let you know if it looks like it can be closed. 2/4/03: Spoke with Rich Perusse after briefly reviewing the report. All of the wells are of questionable design (the original wells were never drilled, only placed in excvation, new wells appear to be screened to surface, etc). Also, no soil of groundwater samples were collected from the source area. I told Rich Perusse to find out if the original wells were still in place (the report indicates that at least one of the wells was paved over before the report was finalized. We may be able re-install them, or install boring/well in source area as part of site 25 investigation. (JHO) APPENDIX B SITE 25/45. TRANSFERED FROM ENGELHARDT TO O'CONNELL. Update 6/9/06 Spill closed based on final site investigation report located in eDocs App. B Site 25. (SKA) "

Material Information

OP Unit ID:	1035527	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	347256	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False

Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0003A		
Material Name:	#6 fuel oil		

Spiller Information

Spiller Name:	LISA PRIMEGGIA
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller City:	MANHATTAN
Spiller State:	NY
Spiller Zip:	10003
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.733269994
Longitude:	-73.952125000

Site: ***NEWTOWN CREEK***
MCGUINESS BLVD BROOKLYN NY

NY SPILLS

Spill No:	1302307	***UST Trust:***	False
Site ID:	482734	***Spill Date:***	06/03/2013 04:30:00 PM
DER Facility ID:	437967	***Received Date:***	06/03/2013 05:29:00 PM
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	06/04/2013 12:00:00 AM
Water Body:	NEWTOWN CREEK	***Create Date:***	06/03/2013 05:32:00 PM
Class:	C4	***Update Date:***	06/04/2013 10:02:56 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	RWAUSTIN
REM Phase:	0	***After Hours:***	False
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Citizen		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Citizen reporting a heavy sheen on the water."

DEC Remark:

"6/3/13 - Austin - I responded out to Newtown Creek from the office, upon receiving this spill report. It was just starting to rain, so since an hour had lapsed between the caller's observation and the report time, I first went to the west of Mcguiness Blvd to inspect Newtown Creek (dock at foot of Manhattan Ave.). No sheen observed, and tide was at approx. high slack tide. I then went to Nature Walk Park (foot of Paige Ave.) and by then the rainfall was considerable. No sheen observed there, as well. I contacted Mr. Rassmussen, who indicated he saw a 30 foot long sheen ath the foot of the supports for the Pulaski Bridge, on the Brooklyn side. He sent a pic via e-mal, which showed a weathred sheen with small debris, indicative of a sewer sheen (there was a rainfall event previously that day). I wrote back Mr. Rasmussen and informed himn of that, and requested notification if he saw a persistant problem in the area. Pic in eDocs - end"

Material Information

OP Unit ID:	1232469	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2231277	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		

Material Code: 0064A
Material Name: unknown material

Spiller Information

Spiller Name:
Spiller Company: UNKNOWN
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: JENS RASMUSSEN
Contact Phone: (917) 720-7022
Contact Ext:
Latitude: 40.735126000
Longitude: -73.952636000

Site: ***NEWTOWN CREEK WPCP DEP -DDC***
301 GREEN POINT AVENUE QUEENS NY

NY SPILLS

Spill No: 9504303
Site ID: 236835
DER Facility ID: 272519
CID:
Program Type: ER
SWIS Code: 4101
Water Body: NEWTOWN CREEK
Class: C3
Meets Std: False
Penalty: False
REM Phase: 0
UST Trust: False
Spill Date: 07/10/1995 05:18:00 PM
Received Date: 07/10/1995 06:28:00 PM
CAC Date:
Insp Date:
Close Date: 04/29/2004 12:00:00 AM
Create Date: 08/03/1995 12:00:00 AM
Update Date: 02/07/2005 11:40:46 AM
DEC Region: 2
Lead DEC: ADZHITOM
After Hours: True
County: Queens
Contributing Factor: Unknown
Reported by: Federal Government
Referred to:
Source: Unknown
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"SHEEN IS ON THE SURFACE. CG SENDING A TEAM OUT - UPDATE - SPILL WAS INVESTIGATED BY USCG - SHEEN WAS COMING FROM GREENPOINT PLUME"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ZHITOMIRSKY 04/29/2004: Closed by Rashid Ahmed."

Material Information

OP Unit ID: 1015351
OU: 01
Material ID: 365812
CAS No:
Material Family: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Med Ind Air: False
Med GW: False
Med SW: True
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:
Material Code: 0066A
Material Name: unknown petroleum

Spiller Information

Spiller Name:
Spiller Company: UNKNOWN

Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name:
Contact Phone:
Contact Ext:
Latitude:
Longitude:

Site: ***MCGUINNSS BLVD/BKLYN***
MCGUINNESS BLVD BROOKLYN NY

NY SPILLS

Spill No:	8906523	***UST Trust:***	False
Site ID:	269760	***Spill Date:***	10/04/1989 12:00:00 PM
DER Facility ID:	219701	***Received Date:***	10/03/1989 01:34:00 PM
CID:		***CAC Date:***	10/03/1989 12:00:00 AM
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	10/03/1989 12:00:00 AM
Water Body:	EAST RIVER/NEWTOWN	***Create Date:***	10/17/1989 12:00:00 AM
Class:		***Update Date:***	03/23/2004 12:00:00 AM
Meets Std:	True	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	RWAUSTIN
REM Phase:	0	***After Hours:***	False

County: Kings
Contributing Factor: Unknown
Reported by: Local Agency
Referred to:
Source: Major Facility (MOSF) > 400,000 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"PETROLEUM PLUME DISCOVERED BENEATH GREENPOINT, REPORT OF SITUATION HASBEEN DONE IN PART BY E.BASCO."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN "

Material Information

OP Unit ID:	934307	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	446936	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	-1.00	***Med Surf:***	False
Units:	L	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		

Material Code: 0009
Material Name: gasoline

Spiller Information

Spiller Name:
Spiller Company:
Spiller Address:
Spiller City:
Spiller State: ZZ
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 40.739044994

Longitude: -73.952585000

Site: ***249 HURON ST BROOKLYN NY***

NY SPILLS

Spill No:	0001313	***UST Trust:***	False
Site ID:	257091	***Spill Date:***	05/02/2000 04:20:00 PM
DER Facility ID:	210511	***Received Date:***	05/02/2000 05:25:00 PM
CID:	196	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	05/04/2000 12:00:00 AM
Water Body:		***Create Date:***	05/02/2000 12:00:00 AM
Class:	C3	***Update Date:***	05/08/2000 12:00:00 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	MXTIPPLE
REM Phase:	0	***After Hours:***	True

County: Kings
Contributing Factor: Human Error
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"CALLER STATES A 55 GALLON DRUM THAT WAS HALF FULL - SPILLED ABOUT 25 GALLONS WHEN THE DRUM WAS KNOCKED OVER BY ACCIDENT. THE PRODUCT METHYLENE - DIPHENYLDISOCYANATE. SPILL IS CONTAINED. CHRISTOPHER HAAS FROM DEP WAS ON THE SCENE. SPILL TO BE CLEANED UP."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 05/0/2000 INITIAL CONTAINMENT IN SAND FILLED DUMPSTER/ REMOVAL AND DISPOSAL BY RADIAC ENVIRONMENTAL"

Material Information

OP Unit ID:	823229	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	289532	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	25.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		

Material Code: 9999
Material Name: other -

Spiller Information

Spiller Name: VINCENT GROSSO
Spiller Company: J&J BRONZ CASTINGS
Spiller Address: 249 HURON ST
Spiller City: BROOKLYN
Spiller State: NY
Spiller Zip: 11222-
Spiller Country: 001
Contact Name: VINCENT GROSSO
Contact Phone: (718) 383-2111
Contact Ext:
Latitude: 40.733269994
Longitude: -73.952125000

Site: ***BY BULASKI BRIDGE MCGUINESS AVE BROOKLYN NY***

NY SPILLS

Spill No:	2108757	***UST Trust:***	False
Site ID:	630719	***Spill Date:***	12/31/2021 02:45:00 PM
DER Facility ID:	577744	***Received Date:***	12/31/2021 03:18:00 PM
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	12/31/2021 12:00:00 AM
Water Body:	NEW TOWN CREEIK	***Create Date:***	12/31/2021 03:20:00 PM
Class:		***Update Date:***	12/31/2021 03:34:14 PM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	RJFENG
REM Phase:	0	***After Hours:***	False

County: Kings
Contributing Factor: Unknown
Reported by: Other
Referred to:
Source: Unknown
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

""rainbow colors on water" -"

DEC Remark:

"12/31/2021 - Feng - Desk Duty. Spoke to Mr. Constatinos and he will send photos to Kumar Patel's cell phone. Duplicate spill and consolidated under 2108754. Spill is closed."

Material Information

OP Unit ID:	1377824	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2391442	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		

Material Code: 0064A
Material Name: unknown material

Spiller Information

Spiller Name:
Spiller Company: SHEEN ON WATER
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: CONSTANTINOS
Contact Phone: (929) 400-0865
Contact Ext:
Latitude:
Longitude:

Site: ***NEWTOWN CREEK SEWER PLANT***
301 GREEN POINT AV QUEENS NY

NY SPILLS

Spill No:	9710321	***UST Trust:***	False
Site ID:	220771	***Spill Date:***	12/08/1997 09:00:00 AM
DER Facility ID:	182604	***Received Date:***	12/09/1997 10:04:00 AM
CID:	297	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	4101	***Close Date:***	04/08/1998 12:00:00 AM
Water Body:	NEWTOWN CREEK	***Create Date:***	12/09/1997 12:00:00 AM
Class:	C3	***Update Date:***	04/08/1998 12:00:00 AM

Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	O'DOWD
REM Phase:	0	***After Hours:***	False
County:	Queens		
Contributing Factor:	Unknown		
Reported by:	Affected Persons		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"#6 FUEL OIL FLOWED INTO THE TREATMENT PLANT FOR 5-6 HOURS"

DEC Remark:

""

Material Information

OP Unit ID:	1053354	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	328627	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0003A		
Material Name:	#6 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	RONALD LOCHAN
Contact Phone:	(718) 595-4724
Contact Ext:	
Latitude:	
Longitude:	

Site: ***MAN HOLE # 64501***
GREEN AVE BROOKLYN NY

NY SPILLS

Spill No:	0211422	***UST Trust:***	False
Site ID:	126407	***Spill Date:***	02/15/2003 08:10:00 AM
DER Facility ID:	109278	***Received Date:***	02/15/2003 07:39:00 PM
CID:	233	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	2401	***Close Date:***	04/03/2003 12:00:00 AM
Water Body:		***Create Date:***	02/15/2003 12:00:00 AM
Class:	C4	***Update Date:***	04/03/2003 12:00:00 AM
Meets Std:	False	***DEC Region:***	2
Penalty:	False	***Lead DEC:***	JHOCONNE
REM Phase:	0	***After Hours:***	True
County:	Kings		
Contributing Factor:	Unknown		
Reported by:	Affected Persons		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CON ED # 147190 MATERIAL IS ON 200 GALLONS OF WATER IN MAN HOLE MATERIAL IS CONFINED IN THE MAN HOLE CLEAN UP IS UNDERWAY AN EARTHEN SUMP WAS LOCATED "

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis no. 147-190: 2/15/03 - 0810HRS FOUND APPROX 1-QUART OF UNKNOWN OIL ON 200 GALLONS OF WATER IN MH-64501.IT APPEARS TO BE CONTAINED AT THIS TIME NO SEWERS OR WATERWAYS EFFECTED. 1-SAMPLE TAKEN. UPDATE 15-FEB-2003 1739 HRS LSN# 03-01355-001, SAMPLE TYPE: OIL, AROCLOR: 1260, RESULT: < 1.0 PPM. UPDATE: 5-FEB-2003 FOUND EATHERN SUMP IN STRUCTURE. UPDATE - 15-FEB-2003 17:39 HRS.. LSN# 03-01355-001 , SAMPLE TYPE: OIL, AROCLOR: 1260, RESULT: < 1. PPM. UPDATE: 15-FEB-2003 1930 JONES ENVIROMENTAL OPS REPORTS FOUND EATHERN SUMP IN STRUCTURE. WILL TAKE OFF 24 HOUR CLOCK. CALLED CIG COSTA @ 1937HRS UPDATE: 15-FEB-2003 2018HRS JONES REPORTS DOUBLE WASHED STRUCTURE WITH BIO GEN 760 REMOVED ALL LIQUIDS. CEMENTED SUMP REMOVED TAG # 36405 CLEAN UP 100%"

Material Information

OP Unit ID:	862588	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	511211	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller City:	UNKNOWN
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	40.688646000
Longitude:	-73.949020000

Site: ***GREENPOINT INCINERATOR (NYCDOS)***
N. HENRY STREET Brooklyn NY 11222

SWF/LF

Activity Number:	[24IC2]	***Facility Name (InAct):***	GREENPOINT INCINERATOR (NYCDOS)
Facility Name (Act):		***Location Addr (InAct):***	N. HENRY STREET
Location Addr (Act):		***Loc Addr2(InAct):***	
Location Addr2 (Act):		***City (InAct):***	Brooklyn
City (Act):		***State (InAct):***	NY
State (Act):		***Zip Code (InAct):***	11222
Zip Code (Act):		***County (InAct):***	Kings
County (Act):		***East Coord (InAct):***	589000
East Coord (Act):		***North Coord (InAct):***	4510000
North Coord (Act):			
Facility Name:			
Location Addr:			
Location Addr2:			
City:			
State:			
Zip Code:			
County:			
East Coord:			
North Coord:			

Data Source: SWMF - Inactive Facility Lists

SWMF - Inactive Facility Lists Details (InAct)

Accuracy Code:		***Authorization No:***	
Activity Desc:	Waste combustion - no energy recovery	***Authrzation Issue Dt:***	
Regulatory Status:	None	***Operator Type:***	
Active:	No	***Operator Name:***	
Dt of Last Inspection:		***Phone No:***	7180000000
Expiration Dt:		***Region:***	2
Owner Type:		***Contact Name:***	ANTHONY ZARILLO
Owner Name:		***Contact Address:***	
Owner Address:		***Contact Address2:***	
Owner Address2:		***Contact City:***	
Owner City:		***Contact State:***	
Owner State:		***Contact Zip:***	
Owner Zip:		***Contact Phone:***	
Owner Phone:		***Contact Email:***	
Owner Email:			
Waste Types:			

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13 and E1527-21, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

National Priority List: NPL

The U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL) includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program, based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action. This data includes NPL sites represented as polygons, where available, that can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. As site investigation and remediation progress, OUs may be added, modified or refined. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 25, 2024

National Priority List - Proposed: PROPOSED NPL

Sites proposed by the U.S. Environmental Protection Agency (EPA), the state agency, or concerned citizens for addition to the National Priorities List (NPL) due to contamination by hazardous waste and identified by the EPA as a candidate for cleanup because it poses a risk to human health and/or the environment. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 25, 2024

Deleted NPL: DELETED NPL

Sites deleted from the U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL). The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 25, 2024

SEMS List 8R Active Site Inventory: SEMS

The U.S. Environmental Protection Agency's (EPA) Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted. This data includes SEMS sites from the List 8R Active file as well as applicable sites from the EPA's Facility Registry Service map tool.

Government Publication Date: Oct 24, 2024

Inventory of Open Dumps, June 1985: ODI

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

SEMS List 8R Archive Sites: SEMS ARCHIVE

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. This data includes sites from the List 8R Archived site file.

Government Publication Date: Oct 24, 2024

Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS: CERCLIS

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

EPA Report on the Status of Open Dumps on Indian Lands: IODI

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (AI/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

CERCLIS - No Further Remedial Action Planned: CERCLIS NFRAP

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS Liens: CERCLIS LIENS

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA). This database was provided by the United States Environmental Protection Agency (EPA). Refer to SEMS LIEN as the current data source for Superfund Liens.

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action: RCRA CORRACTS

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Oct 21, 2024

RCRA non-CORRACTS TSD Facilities: RCRA TSD

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites that have indicated engagement in the treatment, storage, or disposal of hazardous waste which requires a RCRA hazardous waste permit.

Government Publication Date: Oct 21, 2024

RCRA Generator List: RCRA LQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste.

Government Publication Date: Oct 21, 2024

RCRA Small Quantity Generators List: RCRA SQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month.

Government Publication Date: Oct 21, 2024

RCRA Very Small Quantity Generators List: RCRA VSQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Oct 21, 2024

RCRA Non-Generators: RCRA NON GEN

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Oct 21, 2024

RCRA Sites with Controls: RCRA CONTROLS

List of Resource Conservation and Recovery Act (RCRA) facilities with institutional controls in place. RCRA gives the U.S. Environmental Protection Agency (EPA) the authority to control hazardous waste from the "cradle-to-grave." This includes the generation, transportation, treatment, storage, and disposal of hazardous waste. RCRA also set forth a framework for the management of non-hazardous solid wastes. The 1986 amendments to RCRA enabled EPA to address environmental problems that could result from underground tanks storing petroleum and other hazardous substances.

Government Publication Date: Oct 21, 2024

Federal Engineering Controls-ECs: FED ENG

List of Engineering controls (ECs) made availabe by the United States Environmental Protection Agency (EPA). ECs encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. The EC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Nov 20, 2024

Federal Institutional Controls- ICs: FED INST

List of Institutional controls (ICs) made available by the United States Environmental Protection Agency (EPA). ICs are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site. The IC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Nov 20, 2024

Land Use Control Information System: LUCIS

The LUCIS database is maintained by the U.S. Department of the Navy and contains information for former Base Realignment and Closure (BRAC) properties across the United States.

Government Publication Date: Sep 1, 2006

Institutional Control Boundaries at NPL sites: NPL IC

These boundaries of Institutional Control areas at sites on the U.S. Environmental Protection Agency's (EPA) National Priorities List (NPL), or as Proposed or Deleted, are sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). The EPA's NPL includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. Institutional controls are non-engineered instruments such as administrative and legal controls that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes.

Government Publication Date: Sep 25, 2024

Emergency Response Notification System: ERNS 1982 TO 1986

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System: ERNS 1987 TO 1989

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System: ERNS

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Oct 15, 2024

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database: FED BROWNFIELDS

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This data is provided by the United States Environmental Protection Agency (EPA) and includes Brownfield sites from the Cleanups in My Community (CIMC) web application.

Government Publication Date: Feb 7, 2024

FEMA Underground Storage Tank Listing: FEMA UST

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks.

Government Publication Date: Dec 31, 2017

Facility Response Plan: FRP

This listing contains facilities that have submitted Facility Response Plans (FRPs) to the U.S. Environmental Protection Agency (EPA). Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit FRPs. Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments. This listing includes FRP facilities from an applicable EPA FOIA file and Homeland Infrastructure Foundation-Level Data (HIFLD) data file.

Government Publication Date: Jan 9, 2024

Delisted Facility Response Plans: DELISTED FRP

Facilities that once appeared in - and have since been removed from - the list of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Jan 9, 2024

Historical Gas Stations: HIST GAS STATIONS

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries: REFN

This list of petroleum refineries is sourced from the U.S. Energy Information Administration (EIA), Refinery Capacity Report. The listing includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year. The geographic area the report covers is the 50 States, the District of Columbia, Puerto Rico, the U.S. Virgin Islands, Guam, and other U.S. possessions. Per the EIA, the facility location data represents the approximate location based on research of publicly available information from sources such as Federal agencies, company websites, and satellite images on public websites.

Government Publication Date: Jun 6, 2024

Petroleum Product and Crude Oil Rail Terminals: BULK TERMINAL

A list of petroleum product and crude oil rail terminals from the U.S. Energy Information Administration (EIA), as well as petroleum terminals sourced from the Federal Communications Commission Data hosted by the Homeland Infrastructure Foundation-Level Database. Data includes operable bulk petroleum product terminals with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil with activity between 2017 and 2018. EIA petroleum product terminal data comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings.

Government Publication Date: Jun 6, 2024

LIEN on Property: SEMS LIEN

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) provides Lien details on applicable properties, such as the Superfund lien on property activity, the lien property information, and the parties associated with the lien.

Government Publication Date: Oct 24, 2024

Superfund Decision Documents: SUPERFUND ROD

This database contains a list of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include completed Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD) for active and archived sites stored in the Superfund Enterprise Management System (SEMS), along with other associated memos and files. This information is maintained and made available by the U.S. Environmental Protection Agency.

Government Publication Date: Oct 24, 2024

Formerly Utilized Sites Remedial Action Program: DOE FUSRAP

The U.S. Department of Energy (DOE) established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from the Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations. The DOE Office of Legacy Management (LM) established long-term surveillance and maintenance (LTS&M) requirements for remediated FUSRAP sites. DOE evaluates the final site conditions of a remediated site on the basis of risk for different future uses. DOE then confirms that LTS&M requirements will maintain protectiveness.

Government Publication Date: Mar 4, 2017

State

Registry of Inactive Hazardous Waste Disposal Sites in New York State: SHWS

State-and tribal- equivalent CERCLIS. State Superfund Program (Inactive Hazardous Waste Disposal Site Remedial Program) (IHWDS) - Oversees the identification, investigation and cleanup of sites where consequential amounts of hazardous waste exist. These sites go through a process of investigation, evaluation, cleanup and monitoring that has several distinct stages. This list is made available by New York State Department of Environmental Conservation's State Superfund Program.

Government Publication Date: Nov 5, 2024

Delisted Registry of Inactive Hazardous Waste Disposal Sites in New York: DELISTED SHWS

This database contains a Registry of Inactive Hazardous Waste Disposal sites which have been removed from New York Department of Environmental Conservation's Environmental Site Remediation database.

Government Publication Date: Nov 5, 2024

Hazardous Substance Waste Disposal Sites: HSWDS

A list of sites included in Hazardous Substance Waste Disposal Site Study reports made available by the New York Department of Environmental Conservation Division of Hazardous Waste Remediation. Provides information regarding the evolving status of hazardous substance waste disposal sites in New York.

Government Publication Date: Oct 24, 2003

Vapor Intrusion Legacy Site List: VAPOR

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion. This list is made available by Department of Environmental Conservation's Vapor Intrusion Legacy Site List. This database serves a purpose similar to that of the federal Superfund Enterprise Management System (SEMS), functioning as a state-level counterpart for tracking potential hazardous substance release sites.

Government Publication Date: Jul 18, 2024

Solid Waste Facilities and Landfills: SWF/LF

Solid Waste Information Management System (SWIMS) is an inventory containing active and inactive facilities throughout the state. This list is made available by Department of Environmental Conservation's Solid Waste Information Management System (SWIMS).

Government Publication Date: Aug 17, 2023

Inactive Landfill Facilities: LANDFILL INACTIVE

List of inactive landfills in the State of New York. This data is made available by the New York State Department of Environmental Conservation (DEC). DEC notes that these are preliminary data and should not be regarded as a complete inventory of all landfills in the State, and also that site locations and attributes are preliminary and should not be relied upon without independent verification.

Government Publication Date: May 16, 2024

Waste Tire Facilities: WASTE TIRE

This list of active Waste Tire Facilities is maintained by the New York State Department of Environmental Conservation. Waste tire storage facilities (WTSF) store waste tires or portions of waste tires. Most of these facilities require Part 360 permits, but under certain conditions a registration maybe available.

Government Publication Date: Dec 9, 2024

NYC OER Cleanup Sites: OER CLEANUP

Properties remediated under oversight of the New York City (NYC) Mayor's Office of Environmental Remediation (OER), both in the E-Designation program and the NYC Voluntary Cleanup Program. Includes sites completed and in progress.

Government Publication Date: Oct 22, 2024

Recycling Facilities: RECYCLING

The Department of Environmental Conservation (DEC), Division of Materials Management (DMM), Bureau of Permitting and Planning regulates solid waste management facilities in accordance with 6 NYCRR Part 360. Information pertaining to those facilities is maintained with the Division's Solid Waste Information Management System (SWIMS) database. The Facility List is a dataset related to solid waste management facilities operating in the state, and includes such information as facility location, contact names and associated information, waste types managed, and regulatory information.

Government Publication Date: May 21, 2024

Leaking Storage Tanks: LST

This database contains records of chemical and petroleum spill incidents. They include leaking aboveground storage tanks or leaking underground storage tanks, with incidents of tank test failures, tank failures and tank overfill. This list is made available by New York State Department of Environmental Conservation's Spill Response Program.

Government Publication Date: Oct 21, 2024

Delisted Leaking Storage Tanks: DELISTED LST

List of Leaking Storage Tank sites which has been removed from New York Department of Environmental Conservation's Spill Response Program

Government Publication Date: Oct 21, 2024

Underground Storage Tanks- UST-Petroleum Bulk Storage (PBS): UST

This list of facilities within the Petroleum Bulk Storage (PBS) Program that have underground storage tanks onsite is made available by the New York State Department of Environmental Conservation's Environmental Site Database Search. The listing includes underground petroleum storage facilities with a combined storage capacity of over eleven hundred (1,100) gallons.

Government Publication Date: Nov 13, 2024

The Bulk Storage Program Database - AST: AST

Facilities within the Petroleum Bulk Storage (PBS) that have aboveground storage tanks. Aboveground petroleum storage facilities with a combined storage capacity over eleven hundred (1,100) gallons. This list is made available by New York State Department of Environmental conservation's Petroleum Bulk Storage (PBS) program.

Government Publication Date: Nov 13, 2024

Petroleum Bulk Storage: TANKS

The Bulk Storage Program Database maintains the registrations of active and inactive bulk storage sites statewide. This database includes Petroleum Bulk Storage (PBS) tanks where no information is available on whether they are ASTs or USTs. This list is made available by the New York State Department of Environmental Conservation's PBS Program.

Government Publication Date: Nov 13, 2024

Major Oil Storage Facilities (MOSF): MOSF

In 1977, the New York State Legislature passed the "Oil Spill Prevention, Control and Compensation Act" (Article 12 of the Navigation Law). This law regulates all oil terminals and transport vessels operating in the waters of the State which have a storage capacity of 400,000 gallons or more. (Terminals and vessels with a capacity of 400,000 gallons or more are commonly referred to as major oil storage facilities or MOSFs). This list is made available by the New York State Department of Environmental Conservation's Major Oil Storage Facility (MOSF) Program.

Government Publication Date: Nov 13, 2024

Chemical Bulk Storage (CBS): CBS

This list of facilities that store regulated hazardous substances in aboveground or underground tanks is made available by the New York State Department of Environmental Conservation's Chemical Bulk Storage (CBS) Program. "Hazardous substance" means any substance listed as hazardous or acutely hazardous in 6 NYCRR Part 597 or a mixture thereof.

Government Publication Date: Nov 13, 2024

Delisted Storage Tanks: DELISTED TANKS

List of Storage Tank sites which has been removed from New York Department of Environmental Conservation's Environmental Site Database.

Government Publication Date: Nov 13, 2024

Delisted County Records: DELISTED COUNTY

Records removed from county databases. Records may be removed from the county lists made available by the respective county departments because they are inactive, or because they have been deemed to be below reportable thresholds.

Government Publication Date: Jul 31, 2024

Registry of Engineering Controls in New York State: ENG

Registry of Engineering Controls in New York State taken from the New York State Department of Conservation Environmental Site Remediation Database.

Government Publication Date: Nov 5, 2024

Registry of Institutional Controls in New York State: INST

Registry of Institutional Controls in New York State taken from the New York State Department of Conservation Environmental Site Remediation Database.

Government Publication Date: Nov 5, 2024

Voluntary Cleanup Agreements: VCP

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The VCP was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites. This VCP list is made available by the New York State Department of Environmental Conservation.

Government Publication Date: Nov 5, 2024

Environmental Restoration Program Listing: ERP

The Environmental Restoration Program (ERP) provides municipalities with financial assistance for site investigation and remediation at eligible brownfield sites. To spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (Bond Act). Under the ERP, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. This ERP list is made available by the New York State Department of Environmental Conservation.

Government Publication Date: Nov 5, 2024

Brownfields Site List (Subset of Site Remediation): BROWNFIELDS

The Brownfield Cleanup Program (BCP) was developed to enhance private-sector cleanups of brownfields and to reduce development pressure on "Greenfields". A Brownfield site is real property, the redevelopment or reuse of which may be complicated by the presence or potential presence of a contaminant. Contaminants include hazardous waste and/or petroleum. This BCP list is made available by the New York State Department of Environmental Conservation.

Government Publication Date: Nov 5, 2024

Tribal

Leaking Underground Storage Tanks (LUSTs) on Tribal/Indian Lands: INDIAN LUST

This list of leaking underground storage tanks (LUSTs) on Tribal/Indian Lands in Region 2, which includes New York, is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Jan 28, 2016

Underground Storage Tanks (USTs) on Indian Lands: INDIAN UST

This list of underground storage tanks (USTs) on Tribal/Indian Lands in Region 2, which includes New York, is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Apr 04, 2016

Delisted Tribal Leaking Storage Tanks: DELISTED INDIAN LST

Leaking Underground Storage Tank (LUST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian LUST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: May 7, 2024

Delisted Tribal Underground Storage Tanks: DELISTED INDIAN UST

Underground Storage Tank (UST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian UST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: May 7, 2024

County

No County databases were selected to be included in the search.

Additional Environmental Record Sources

Federal

PFAS Greenhouse Gas Emissions Data: PFAS GHG

The U.S. Environmental Protection Agency's Greenhouse Gas Reporting Program (GHGRP) collects Greenhouse Gas (GHG) data from large emitting facilities (25,000 metric tons of carbon dioxide equivalent (CO2e) per year), and suppliers of fossil fuels and industrial gases that results in GHG emissions when used. Includes GHG emissions data for facilities that emit or have emitted since 2010 chemicals identified in EPA's CompTox Chemicals Dashboard list of PFAS without explicit structures and list of PFAS structures by DSSTox. PFAS emissions data has been identified for facilities engaged in the following industrial processes: Aluminum Production (GHGRP Subpart F), HCFC-22 Production and HFC-23 Destruction (Subpart O), Electronics Manufacturing (Subpart I), Fluorinated Gas Production (Subpart L), Magnesium Production (Subpart T), Electrical Transmission and Distribution Equipment Use (Subpart DD), and Manufacture of Electric Transmission and Distribution Equipment (Subpart SS). Over time, other industrial processes with required GHGRP reporting may include PFAS emissions data and the list of reportable gases may change over time.

Government Publication Date: Aug 5, 2024

On-Scene Coordinator Response Sites: OSC RESPONSE

This list of On-Scene Coordinator (OSC) Response Sites is provided by the U.S. Environmental Protection Agency (EPA). OSCs are the federal officials responsible for monitoring or directing responses to all oil spills and hazardous substance releases reported to the federal government. OSCs coordinate all federal efforts with, and provide support and information to local, state, and regional response communities. An OSC is an agent of either EPA or the U.S. Coast Guard (USCG), depending on where the incident occurs. EPA's OSCs have primary responsibility for spills and releases to inland areas and waters. USCG OSCs have responsibility for coastal waters and the Great Lakes. In general, an OSC has the following key responsibilities during and after a response: Assessment, Monitoring, Response Assistance, and Evaluation.

Government Publication Date: Apr 4, 2024

Facility Registry Service/Facility Index: FINDS/FRS

The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Aug 1, 2024

Toxics Release Inventory (TRI) Program: TRIS

The U.S. Environmental Protection Agency's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of toxic chemicals from U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. There are currently 770 individually listed chemicals and 33 chemical categories covered by the TRI Program. Facilities that manufacture, process or otherwise use these chemicals in amounts above established levels must submit annual reporting forms for each chemical. Note that the TRI chemical list does not include all toxic chemicals used in the U.S. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment. This database includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFOA/PFOS Contaminated Sites: PFAS NPL

This list of Superfund Sites with Per- and Polyfluoroalkyl Substances (PFAS) detections is made available by the U.S. Environmental Protection Agency (EPA) in their PFAS Analytic Tools data, previously the list was obtained by EPA FOIA requests. EPA's Office of Land and Emergency Management and EPA Regional Offices maintain what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment. Limitations: Detections of PFAS at National Priorities List (NPL) sites do not mean that people are at risk from PFAS, are exposed to PFAS, or that the site is the source of the PFAS. The information in the Superfund NPL and Superfund Alternative Agreement (SAA) PFAS detection site list is years old and may not be accurate today. Site information such as site name, site ID, and location has been confirmed for accuracy; however, PFAS-related information such as media sampled, drinking water being above the health advisory, or mitigation efforts has not been verified. For Federal Facilities data, the other Federal agencies (OFA) are the lead agency for their data and provided them to EPA.

Government Publication Date: Dec 17, 2024

Federal Agency Locations with Known or Suspected PFAS Detections: PFAS FED SITES

List of Federal agency locations with known or suspected detections of Per- and Polyfluoroalkyl Substances (PFAS), made available by the U.S. Environmental Protection Agency (EPA) in their PFAS Analytic Tools data. EPA outlines that these data are gathered from several federal entities, such as the Federal Superfund program, Department of Defense (DOD), National Aeronautics and Space Administration, Department of Transportation, and Department of Energy. The dates this data was extracted for the PFAS Analytic Tools range from 2022 to 2024. Sites on this list do not necessarily reflect the source/s of PFAS contamination and detections do not indicate level of risk or human exposure at the site. Agricultural notifications in this data are limited to DOD sites only. At this time, the EPA is aware that this list is not comprehensive of all Federal agencies.

Government Publication Date: Jul 22, 2024

SSEHRI PFAS Contamination Sites: PFAS SSEHRI

This PFAS Contamination Site Tracker database is compiled by the PFAS Project Lab, part of the Social Science Environmental Health Research Institute (SSEHRI) at Northeastern University. According to the SSEHRI, the database records qualitative and quantitative data from each known site of PFAS contamination, including timeline of discovery, sources, levels, health impacts, community response, and government response. The goal of this database is to compile information and support public understanding of the rapidly unfolding issue of PFAS contamination. All data presented was extracted from government websites, news articles, or publicly available documents. Locations for the Known PFAS Contamination Sites are sourced from the PFAS Sites and Community Resources Map by the PFAS-REACH team, credited to PFAS Project Lab, Silent Spring Institute, and PFAS Exchange. Disclaimer: The source conveys the data undergoes regular updates as new information becomes available, some sites may be missing and/or contain information that is incorrect or outdated, as well as their information represents all contamination sites SSEHRI is aware of, not all possible contamination sites. This data is not intended to be used for legal purposes. Access the following source link for the most current information: https://pfasproject.com/pfas-sites-and-community-resources/

Government Publication Date: Jun 27, 2024

National Response Center PFAS Spills: PFAS ERNS

This Per- and Poly-Fluoroalkyl Substances (PFAS) Spills dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The National Response Center (NRC), operated by the U.S. Coast Guard, is the designated federal point of contact for reporting all oil, chemical, and other discharges into the environment, for the United States and its territories. This dataset contains NRC spill information from 1990 to the present that is restricted to records associated with PFAS and PFAS-containing materials. Incidents are filtered to include only records with a "Material Involved" or "Incident Description" related to Aqueous Film Forming Foam (AFFF). The keywords used to filter the data included "AFFF," "Fire Fighting Foam," "Aqueous Film Forming Foam," "Fire Suppressant Foam, "PFAS," "PERFL," "PFOA," "PFOS," and "Genx." Limitations: The data from the NRC website contains initial incident data that has not been validated or investigated by a federal/state response agency. Keyword searches may misidentify some incident reports that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS spills/release incidents.

Government Publication Date: Dec 9, 2024

PFAS NPDES Discharge Monitoring: PFAS NPDES

This list of National Pollutant Discharge Elimination System (NPDES) permitted facilities with required monitoring for Per- and Polyfluoroalkyl (PFAS) Substances is made available via the U.S. Environmental Protection Agency (EPA)'s PFAS Analytic Tools. Any point-source wastewater discharger to waters of the United States must have a NPDES permit, which defines a set of parameters for pollutants and monitoring to ensure that the discharge does not degrade water quality or impair human health. This list includes NPDES permitted facilities associated with permits that monitor for Per- and Polyfluoroalkyl Substances (PFAS), limited to the years 2007 - present. EPA further advises the following regarding these data: currently, fewer than half of states have required PFAS monitoring for at least one of their permittees, and fewer states have established PFAS effluent limits for permittees. For states that may have required monitoring, some reporting and data transfer issues may exist on a state-by-state basis.

Government Publication Date: Dec 16, 2024

Perfluorinated Alkyl Substances (PFAS) from Toxic Release Inventory: PFAS TRI

List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a per- or polyfluoroalkyl (PFAS) substance included in the U.S. Environmental Protection Agency's (EPA) consolidated PFAS Master List of PFAS Substances. Encompasses Toxics Release Inventory records included in the EPA PFAS Analytic Tools. The EPA's TRI database currently tracks information on disposal or releases of 770 individually listed toxic chemicals and 33 chemical categories from thousands of U.S. facilities and details about how facilities manage those chemicals through recycling, energy recovery, and treatment. This listing includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFAS Water Quality Portal Sampling Data: PFAS WATER

This Per- and Poly-Fluoroalkyl Substances (PFAS) Environmental Media Sampling Data is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The Water Quality Portal (WQP), as a cooperative service sponsored by the United States Geological Survey, the EPA, and the National Water Quality Monitoring Council, is part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations, and individuals submit project details and sampling results to this public repository. Limitations: EPA did not carry out the sampling or testing of a majority of the data in the WQP PFAS dataset. EPA can only speak to the accuracy and completeness of the data from projects like the National Aquatic Resource Surveys for which EPA is the data owner/organization. Data may exist within the file on Quality Assurance Project Plans (QAPPs) and the approving agency of the QAPP, if a QAPP is entered.

Government Publication Date: Jul 22, 2024

PFAS TSCA Manufacture and Import Facilities: PFAS TSCA

The U.S. Environmental Protection Agency (EPA) issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. This list is specific only to TSCA Manufacture and Import Facilities with reported per- and poly-fluoroalkyl (PFAS) substances. Data file is sourced from EPA's PFAS Analytic Tools TSCA dataset which includes CDR/Inventory Update Reporting data from 1998 up to 2020. Disclaimer: This data file includes production and importation data for chemicals identified in EPA's CompTox Chemicals Dashboard list of PFAS without explicit structures and list of PFAS structures in DSSTox. Note that some regulations have specific chemical structure requirements that define PFAS differently than the lists in EPA's CompTox Chemicals Dashboard. Reporting information on manufactured or imported chemical substance amounts should not be compared between facilities, as some companies claim Chemical Data Reporting Rule data fields for PFAS information as Confidential Business Information.

Government Publication Date: Jan 5, 2023

PFAS Waste Transfers from RCRA e-Manifest : PFAS E-MANIFEST

This Per- and Poly-Fluoroalkyl Substances (PFAS) Waste Transfers dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. Every shipment of hazardous waste in the U.S. must be accompanied by a shipment manifest, which is a critical component of the cradle-to-grave tracking of wastes mandated by the Resource Conservation and Recovery Act (RCRA). According to the EPA, currently no Federal Waste Code exists for any PFAS compounds. To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: • PFAS • PFOA • PFOS • PERFL • AFFF • GENX • GEN-X (plus the Vermont state-specific waste codes). Limitations: Amount or concentration of PFAS being transferred cannot be determined from the manifest information. Keyword searches may misidentify some manifest records that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS waste transfers.

Government Publication Date: Dec 15, 2024

PFAS Industry Sectors: PFAS IND

This Per- and Poly-Fluoroalkyl Substances (PFAS) Industry Sectors dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The EPA developed the dataset from various sources that show which industries may be handling PFAS including: EPA's Enforcement and Compliance History Online (ECHO) records restricted to potential PFAS-handling industry sectors; ECHO records for Fire Training Sites identified where fire-fighting foam may have been used in training exercises; and 14 CFR Part 139 Airports compiled from historic and current records from the FAA Airport Data and Information Portal. Since July 2006, all certificated Part 139 Airports are required to have fire-fighting foam onsite that meet certain military specifications, which to date have been fluorinated (Aqueous Film Forming Foam). Limitations: Inclusion in this dataset does not indicate that PFAS are being manufactured, processed, used, or released by the facility. Listed facilities potentially handle PFAS based on their industrial profile, but are unconfirmed by the EPA. Keyword searches in ECHO for Fire Training sites may misidentify some facilities and should not be considered to be an exhaustive list of fire training facilities in the U.S.

Government Publication Date: Sep 23, 2024

Hazardous Materials Information Reporting System: HMIRS

The Hazardous Materials Incident Reporting System (HMIRS) database contains unintentional hazardous materials release information reported to the U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration.

Government Publication Date: May 29, 2024

National Clandestine Drug Labs: NCDL

The U.S. Department of Justice ("the Department"), Drug Enforcement Administration (DEA), provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.

Government Publication Date: Nov 30, 2023

Toxic Substances Control Act: TSCA

The U.S. Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule. The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI). EPA CDR collections occur approximately every four years and reporting requirements change per collection.

Government Publication Date: May 12, 2022

Hist TSCA: HIST TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.
The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.
Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing: FTTS ADMIN
An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.
Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing: FTTS INSP
An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.
Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List: PRP
Early in the site cleanup process, the U.S. Environmental Protection Agency (EPA) conducts a search to find the Potentially Responsible Parties (PRPs). The EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site. This listing contains PRPs, Noticed Parties, at sites in the EPA's Superfund Enterprise Management System (SEMS).
Government Publication Date: Jul 24, 2024

State Coalition for Remediation of Drycleaners Listing: SCRD DRYCLEANER
The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin. Since 2017, the SCRD no longer maintains this data, refer to applicable state source data where available.
Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS): ICIS
The Integrated Compliance Information System (ICIS) database contains integrated enforcement and compliance information across most of U.S. Environmental Protection Agency's (EPA) programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained by the EPA Headquarters and at the Regional offices. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.
Government Publication Date: Apr 13, 2024

Drycleaner Facilities: FED DRYCLEANERS
A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) data as made available by the U.S. Environmental Protection Agency (EPA), sourced from the ECHO Exporter file. The EPA tracks facilities that possess NAIC and SIC codes that classify businesses as drycleaner establishments.
Government Publication Date: May 5, 2024

Delisted Drycleaner Facilities: DELISTED FED DRY
List of sites removed from the list of Drycleaner Facilities (sites in the EPA's Integrated Compliance Information System (ICIS) with NAIC or SIC codes identifying the business as a drycleaner establishment).
Government Publication Date: May 5, 2024

Formerly Used Defense Sites: FUDS
Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DOD) is responsible for an environmental restoration. The FUDS Annual Report to Congress (ARC) is published by the U.S. Army Corps of Engineers (USACE). This data is compiled from the USACE's Geospatial FUDS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) FUDS dataset which applies to the Fiscal Year 2021 FUDS Inventory.

Government Publication Date: May 15, 2023

FUDS Munitions Response Sites: FUDS MRS

Boundaries of Munitions Response Sites (MRS), published with the Formerly Used Defense Sites (FUDS) Annual Report to Congress (ARC) by the U.S. Army Corps of Engineers (USACE). An MRS is a discrete location within a Munitions response area (MRA) that is known to require a munitions response. An MRA means any area on a defense site that is known or suspected to contain unexploded ordnance (UXO), discarded military munitions (DMM), or munitions constituents (MC). This data is compiled from the USACE's Geospatial MRS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) MRS dataset.

Government Publication Date: May 15, 2023

Former Military Nike Missile Sites: FORMER NIKE

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 2, 1984

PHMSA Pipeline Safety Flagged Incidents: PIPELINE INCIDENT

This list of flagged pipeline incidents is made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types. Accidents reported on hazardous liquid gravity lines (§195.13) and reporting-regulated-only hazardous liquid gathering lines (§195.15) and incidents reported on Type R gas gathering (§192.8(c)) are not included in the flagged incident file data.

Government Publication Date: May 6, 2024

Material Licensing Tracking System (MLTS): MLTS

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: May 11, 2021

Historic Material Licensing Tracking System (MLTS) sites: HIST MLTS

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File: MINES

The Master Index File (MIF) is provided by the United States Department of Labor, Mine Safety and Health Administration (MSHA). This file, which was originally created in the 1970's, contained many Mine-IDs that were invalid. MSHA removes invalid IDs from the MIF upon discovery. MSHA applicable data includes the following: all Coal and Metal/Non-Metal mines under MSHA's jurisdiction since 1/1/1970; mine addresses for all mines in the database except for Abandoned mines prior to 1998 from MSHA's legacy system (addresses may or may not correspond with the physical location of the mine itself); violations that have been assessed penalties as a result of MSHA inspections beginning on 1/1/2000; and violations issued as a result of MSHA inspections conducted beginning on 1/1/2000.

Government Publication Date: Feb 5, 2024

Surface Mining Control and Reclamation Act Sites: SMCRA

This inventory of land and water impacted by past mining (primarily legacy coal mining operations) is maintained by the U.S. Department of the Interior's Office of Surface Mining Reclamation and Enforcement (OSMRE), as it provides information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). This inventory contains information on the type and extent of Abandoned Mine Land (AML) Problems, as well as information on the cost associated with the reclamation of those problems. The data is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed. Disclaimer: Per the OSMRE, States and tribes who enter their data into e-AMLIS (AML Inventory System) may truncate their latitude and longitude so the precise location of usually dangerous AMLs is not revealed in an effort to protect the public from searching for these AMLs, most of which are on private property. If more precise location information is needed, please contact the applicable state/tribe of interest.

Government Publication Date: May 20, 2024

Mineral Resource Data System: MRDS

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2016

DOE Legacy Management Sites: LM SITES

The U.S. Department of Energy (DOE) Office of Legacy Management (LM) currently manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The LM manages sites with diverse regulatory drivers (statutes or programs that direct cleanup and management requirements at DOE sites) or as part of internal DOE or congressionally-recognized programs, such as but not limited to: Formerly Utilized Sites Remedial Action Program (FUSRAP), Uranium Mill Tailings Radiation Control Act (UMTRCA Title I, Tile II), Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), Resource Conservation and Recovery Act (RCRA), Decontamination and Decommissioning (D&D), Nuclear Waste Policy Act (NWPA). This site listing includes data exported from the DOE Office of LM's Geospatial Environmental Mapping System (GEMS). GEMS Data disclaimer: The DOE Office of LM makes no representation or warranty, expressed or implied, regarding the use, accuracy, availability, or completeness of the data presented herein.

Government Publication Date: Dec 12, 2023

Alternative Fueling Stations: ALT FUELS

This list of alternative fueling stations is sourced from the Alternative Fuels Data Center (AFDC). The U.S. Department of Energy's Office of Energy Efficiency & Renewable Energy launched the AFDC in 1991 as a repository for alternative fuel vehicle performance data, which provides a wealth of information and data on alternative and renewable fuels, advanced vehicles, fuel-saving strategies, and emerging transportation technologies. The data includes Biodiesel (B20 and above), Compressed Natural Gas (CNG), Electric, Ethanol (E85), Hydrogen, Liquefied Natural Gas (LNG), Propane (LPG), and Renewable Diesel (R20 and above) fuel type locations.

Government Publication Date: Aug 29, 2024

Superfunds Consent Decrees: CONSENT DECREES

This list of Superfund consent decrees is provided by the Department of Justice, Environment & Natural Resources Division (ENRD) through a Freedom of Information Act (FOIA) applicable file. This listing includes Cases filed since 2010 limited to the following: Consent Decrees for CERCLA or Superfund Sites filed and/or as proposed within the ENRD's Case Management System (CMS); and applicable ENRD's Environmental Defense Section (EDS) CERCLA Cases with "Consent" in History Note. CMS may not reflect the latest developments in a case, nor can the agency guarantee the accuracy of the data. ENRD Disclaimer: Congress excluded three discrete categories of law enforcement and national security records from the requirements of the FOIA; response is limited to those records that are subject to the requirements of the FOIA; however, this should not be taken as an indication that excluded records do, or do not, exist.

Government Publication Date: Jun 26, 2024

Air Facility System: AFS

This EPA retired Air Facility System (AFS) dataset contains emissions, compliance, and enforcement data on stationary sources of air pollution. Regulated sources cover a wide spectrum; from large industrial facilities to relatively small operations such as dry cleaners. AFS does not contain data on facilities that are solely asbestos demolition and/or renovation contractors, or landfills. ECHO Clean Air Act data from AFS are frozen and reflect data as of October 17, 2014; the EPA retired this system for Clean Air Act stationary sources and transitioned to ICIS-Air.

Government Publication Date: Oct 17, 2014

Registered Pesticide Establishments: SSTS

This national list of active EPA-registered foreign and domestic pesticide and/or device-producing establishments is based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that each producing establishment must place its EPA establishment number on the label or immediate container of each pesticide, active ingredient or device produced. An EPA establishment number on a pesticide product label identifies the EPA registered location where the product was produced. The list of establishments is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Feb 29, 2024

Polychlorinated Biphenyl (PCB) Transformers: PCBT

Locations of Transformers Containing Polychlorinated Biphenyls (PCBs) registered with the United States Environmental Protection Agency. PCB transformer owners must register their transformer(s) with EPA. Although not required, PCB transformer owners who have removed and properly disposed of a registered PCB transformer may notify EPA to have their PCB transformer de-registered. Data made available by EPA.

Government Publication Date: Oct 15, 2019

Polychlorinated Biphenyl (PCB) Notifiers: PCB

Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.

Government Publication Date: May 23, 2024

Power Plants: POWER PLANTS

This list of power plants is provided by the U.S. Energy Information Administration (EIA). The listing includes operable electric generating plants in the United States by energy source, originating from the EIA-860, Annual Electric Generator Report; EIA-860M, Monthly Update to the Annual Electric Generator Report; and EIA-923, Power Plant Operations Report. It includes all operable plants by energy source with a combined nameplate capacity of 1 megawatt or more that are operating, are on standby, or out of service for short- or long-term.

Government Publication Date: Apr 15, 2024

State

Underground Injection Control Wells: UIC

List of Brine Disposal Wells in the New York State Department of Environmental Conservation (NYSDEC) online Wells Data Search. Brine disposal wells are considered Underground Injection Control (UIC) Class II wells. Brine disposal wells deeper than 500 feet require a permit from the NYSDEC Division of Mineral Resources for any operation to drill, deepen, plug back, convert, or plug and abandon a well. Regardless of well depth, the NYSDEC Division of Water must be contacted for a determination of whether a State Pollution Discharge Elimination System (SPDES) permit is necessary to operate any brine disposal well.

Government Publication Date: Sep 16, 2024

New York City Cooling Tower Registrations: COOLING TOWERS NYC

This dataset contains cooling tower systems currently registered in the New York City Cooling Tower Registration Portal and Legionella water test dates as reported by a building's qualified person. Data is provided by the New York City Department of Health and Mental Hygiene. Decommissioned cooling tower systems are excluded from the dataset.

Government Publication Date: Sep 13, 2024

Manufactured Gas Plants: MGP

A list of former Manufactured Gas Plants (MGP) made available by the New York Department of Environmental Conservation (NYSDEC). From the late 1800's to the mid 1900's, hundreds of manufactured gas plants across New York State supplied homes and industry with fuel. Former MGP structures such as gas holders, tar separators, wells, and tanks were often susceptible to spills and leaks. As a result, these structures were a significant source of contamination from the release of tar and other toxic by-products.

Government Publication Date: Aug 20, 2024

Spill Incidents Database: NY SPILLS

This Spill Incident Database is made available by the New York State Department of Environmental Conservation (DEC). The DEC's Spill Response Program receives, and compiles reports of hazardous material spills occurring anywhere in New York State. These reports are submitted through the spill hotline and other mechanisms, and then DEC spill response staff enters the reported spill incidents into the state's official database. The database contains records of chemical and petroleum spill incidents dating back to 1978.

Government Publication Date: Oct 21, 2024

PFAS Remedial Sites: PFAS CONTAM

List of sites being addressed under one of the New York State Department of Environmental Conservation (DEC) Division of Environmental Remediation (DER)'s remedial programs, where the waste or contaminant of concern is a Per- or polyfluorinated alkyl substance (PFAS) included in the PFAS Structure List and/or PFAS Chemicals Without Explicit Structure List made available by the United States Environmental Protection Agency (US EPA).

Government Publication Date: Nov 5, 2024

Per- and Polyfluoroalkyl Substances (PFAS): PFAS

A list of sites surveyed by the New York Department of Environmental Conservation to determine locations that manufacture, use, store, or release into the environment materials containing Per- and Polyfluoroalkyl Substances (PFAS). Per- and Polyfluoroalkyl Substances (PFAS) are a group of chemicals used to make fluoropolymer coatings and products that resist heat, oil, stains, grease, and water. Some PFAS are difficult to break down and persist in the environment that may cause harm to the public. This list is made available by the Department of Environmental Conservation of New York State.

Government Publication Date: Jan 16, 2019

Landfill Investigations PFAS Sampling Results: PFAS LANDFILL

A list of inactive landfill sites that have been investigated for Per- and Polyfluoroalkyl Substances (PFAS) in the state of New York made available by the New York State Department of Environmental Conservation.

Government Publication Date: May 16, 2024

Registed Dry Cleaner Facilities: DRYCLEANERS

The Division of Air Resources of the New York State Department of Environmental Conservation (DEC) tracks all registered dry cleaner facilities. Drycleaning drop off locations (i.e., drop off locations not performing drycleaning on-site) do not require registration and are not included in DEC listings of registered drycleaners.

Government Publication Date: Sep 26, 2024

Delisted Dry Cleaner Facilities: DELISTED DRYCLEANERS

Sites removed from the list of dry cleaner facilities registered with the Department of Environmental Conservation (DEC)'s Division of Air Resources.

Government Publication Date: Sep 26, 2024

Hazardous Waste Manifest - Facilities: NY MANIFEST

List of facilities located in New York that are included in the Hazardous Waste Manifest Data Downloads Location Address data file made available by the New York Department of Environmental Conservation (DEC), with which no manifests are associated. The Hazardous Waste Manifest Data made available by the NY DEC is compiled from hazardous waste manifest shipments to, from, or within New York State. The Bureau of Program Management, in the Division of Environmental Remediation, is responsible for maintaining hazardous waste manifest records.

Government Publication Date: Jun 24, 2024

Receivers from Hazardous Waste Manifests: REC MANIFEST

List of receiver facilities located in New York that are included in the Hazardous Waste Manifest Data Downloads Location Address data file made available by the New York Department of Environmental Conservation (DEC), which are identified as a receiver in associated manifests. The Hazardous Waste Manifest Data made available by the NY DEC is compiled from hazardous waste manifest shipments to, from, or within New York State. The Bureau of Program Management, in the Division of Environmental Remediation, is responsible for maintaining hazardous waste manifest records. Hazardous Waste Code Descriptions are from NY Part 371.4 (6 CRR-NY 371.4) Identification and Listings of Hazardous Waste, unless otherwise noted.

Government Publication Date: Jun 24, 2024

Generators from Hazardous Waste Manifests: GEN MANIFEST

List of generator facilities located in New York that are included in the Hazardous Waste Manifest Data Downloads Location Address data file made available by the New York Department of Environmental Conservation (DEC), which are identified as a generator in associated manifests. The Hazardous Waste Manifest Data made available by the NY DEC is compiled from hazardous waste manifest shipments to, from, or within New York State. The Bureau of Program Management, in the Division of Environmental Remediation, is responsible for maintaining hazardous waste manifest records. Hazardous Waste Code Descriptions are from NY Part 371.4 (6 CRR-NY 371.4) Identification and Listings of Hazardous Waste, unless otherwise noted.

Government Publication Date: Jun 24, 2024

New York City E-Designated Sites: E DESIGNATION

A list of sites with an (E) Designation, described as a New York City (NYC) zoning map designation that indicates the presence of an environmental requirement pertaining to potential hazardous materials contamination, window/wall noise attenuation, or air quality impacts on a particular tax lot. The NYC Office of Environmental Remediation administers the E-Designation Environmental Review Program to avoid significant adverse impacts to human health or the environment through exposure to these hazards. The data is provided by the NYC Department of City Planning (DCP).

Government Publication Date: May 3, 2024

Registered Cooling Towers: COOLING TOWERS

This dataset contains location, legionella sampling results and operational status information for currently operating cooling towers, as well as information on towers that previously operated, in New York State and New York City. The data is self-reported by the cooling tower operator according to Public Health Law, Section 225(5)(a) Subpart 4-1 – Cooling Towers. Data provided by New York State Department of Health.

Government Publication Date: Aug 27, 2024

Tier 2 Report: TIER 2

A list of Tier 2 facilities in the state of New York. This is a list of facilities which have reported hazardous substances provided by Homeland Security and Emergency Services.

Government Publication Date: Sep 28, 2022

NY DEC Projects of Interest: PROJECTS

A list of permits for notable projects - permit applications that have received a lot of public attention - made available by the New York Department of Environmental Conservation (DEC).

Government Publication Date: Jan 3, 2022

Air Permitted Facilities: AIR PERMITS

This list of issued state facility air permits is maintained by the New York State Department of Environmental Conservation (NYDEC). The listing includes Air State Facility Permits (ASF) and Air Title V Facility Permits (ATV). ASF permits may be required by medium-sized commercial or industrial facilities or larger facilities that have agreed to limit emissions. ATV permits may be required at the largest facilities statewide, or at facilities located in those areas where state implementation plans are in place to improve air quality. Please note: An Issued permit is valid for a stated period of time. Modifications may be made to an issued permit for the remainder of the active permit.

Government Publication Date: Jan 31, 2024

Liens Listing: LIEN

The New York Environmental Protection and Spill Compensation Fund (Oil Spill Fund) places liens on properties that are sites of oil spills when the owners are responsible parties and fail to pay for cleanup. The Office of the New York State Comptroller provides this listing of liens information from the Oil Spill Fund.

Government Publication Date: Sep 20, 2024

Tribal

No Tribal additional environmental record sources available for this State.

County

No County additional environmental record sources available for this State.

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.


'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

Appendix 6 Regulatory Records Documentation



249 HURON STREET, 11222

Brooklyn (Borough 3) | Block 2524 | Lot 46

+ Add Another Tax Lot for Comparison

TAX LOT | BBL 3025240046

Zoning District: M1-1

INTERSECTING MAP LAYERS :

- FRESH Zone
- Coastal Zone
- Flood Zone Preliminary Flood Insurance Rate Maps 2015
- Appendix I
- Appendix J Designated M District

ZONING DETAILS:

- Digital Tax Map
- Zoning Map: 13a (PDF)
- Historical Zoning Maps (PDF)

Owner	DALE NY LLC
Land Use	Industrial & Manufacturing
Lot Area	15,000 sq ft
Lot Frontage	150 ft
Lot Depth	100 ft
Year Built	1920
Year Altered	1968
Building Class	Factory and Industrial Buildings - Light Manufacturing (F5)
Number of Buildings	1
Number of Floors	1
Gross Floor Area	15,000 sq ft
Total # of Units	1
Building Info	BISWEB
Property Records	View ACRIS
Housing Info	View HPD's Building, Registration & Violation Records
Community District	Brooklyn Community District 1
City Council District	Council District 33
School District	14
Police Precinct	94
Fire Company	E238
Sanitation Borough	3
Sanitation District	01
Sanitation Subsection	1B

Printable page

249 HURON STREET

Borough: BROOKLYN
Block: 2524 Lot: 46

2025 - 2026 Final Assessment

Final Assessment Roll for	2025-2026 | City of New York
Taxable Status Date	January 5, 2025
	EXPLANATION OF ASSESSMENT ROLL
Owner Name	DALE NY LLC
Property Address	249 HURON STREET # 11222
Billing Name and Address	DALE NY LLC C/O: JAY LAU, ESQ. 40 CUTTERMILL RD. STE 504 GREAT NECK NY 11021-3213
Tax Class	4
Building Class	F5 - FACTORY; LIGHT MANUFACTURING

Property Owner(s)

DALE NY LLC

Land Information

Lot Size	
Frontage (feet)	150.00
Depth (feet)	100.00
Land Area (sqft)	15,000
Regular / Irregular	Regular
Corner	
Number of Buildings	1
Building Size	
Frontage (feet)	100.00
Depth (feet)	100.00
Stories	1
Extension	E

Assessment Information

Description	Land	Total
ESTIMATED MARKET VALUE	338,000	1,682,000
MARKET AV	152,100	756,900
MARKET EX		0
TRANS AV	152,100	658,530
TRANS EX		0

Taxable/Billable Assessed Value

	Assessed Value
Subject To Adjustments, Your 2025/26 Taxes Will Be Based On	658,530

Market Value History

Tax Year	Market Value
2025 - 2026	1,682,000
2024 - 2025	1,610,000
2023 - 2024	1,519,000
2022 - 2023	1,388,000
2021 - 2022	1,118,000

Note

For more information about how your property taxes are calculated, visit http://nyc.gov/assessments.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

235 HURON STREET | **BROOKLYN 11222** | **BIN# 3064225**

HURON STREET 235 - 249

Health Area	: 300	**Tax Block**	: 2524
Census Tract	: 579.01	**Tax Lot**	: 46
Community Board	: 301	**Condo**	: NO
Buildings on Lot	: 1	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	MCGUINNESS BOULEVARD, PROVOST STREET		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	NO

Additional BINs for Building: NONE
Additional Designation(s): IBZ - INDUSTRIAL BUSINESS ZONE

HPD Multiple Dwelling: No

Special District: UNKNOWN

This property is located in an area that may be affected by the following:

Tidal Wetlands Map Check:	No
Freshwater Wetlands Map Check:	No
Coastal Erosion Hazard Area Map Check:	No
Special Flood Hazard Area Check:	Yes

Click here for more information

Department of Finance Building Classification: F5-FACTORY/INDSTRIAL

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	6	0
Violations-DOB	4	0
Violations-OATH/ECB	5	0
Jobs/Filings	3	
ARA / LAA Jobs	1	
Total Jobs	4	
Actions	56	

OR Enter Action Type:
OR Select from List: Select...
AND Show Actions

- Elevator Records
- Electrical Applications
- Permits In-Process / Issued
- Illuminated Signs Annual Permits
- Plumbing Inspections
- Open Plumbing Jobs / Work Types
- Facades
- Marquee Annual Permits
- Boiler Records
- DEP Boiler Information
- Crane Information
- After Hours Variance Permits

DUPLICATE

№ 17093

OFFICE OF THE PRESIDENT OF THE BOROUGH OF BROOKLYN

BUREAU OF BUILDINGS

CERTIFICATE OF OCCUPANCY

(ISSUED PURSUANT TO ARTICLE 1, SECTION, 5 BUILDING CODE)

BROOKLYN, N.Y. [illegible] 27 192 7

This is to certify that the NEW BUILDING

Located at [illegible] Fourth Ave. 190 Prospect St

Has been COMPLETED substantially according to the approved plans and specifications and the requirements of the BUILDING CODE, and PERMISSION is hereby granted for the OCCUPANCY of said building for the following purposes:

Flats

Permit No. E 1400 27

108-2114-21C WORK COMPLETED

Per [illegible]

Superintendent of Buildings

Form 54-79M-7015(1-59) 114

DEPARTMENT OF BUILDINGS

BOROUGH OF Brooklyn, THE CITY OF NEW YORK

No. 1722754

Date OCT 20 1960

CERTIFICATE OF OCCUPANCY

(Standard ~~form~~ adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No. 107752

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~ altered ~~existing~~ building—premises located at

251-257 Huron Street, north side 225' West of Provost Street

Block 2524 Lot 42

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~New~~ or Alt. No.— 3316-1957 Construction classification— non-fireproof

Occupancy classification— AS STATED BELOW . Height 1 & 3 stories, 35 feet

Date of completion— Const. 10-17-1960 . Located in unrestricted Use District

Plumb. 10-17-1960

0 Area . Height Zone at time of issuance of permit

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar	on ground	-	-	-	storage and boiler room
First	120	30	2	32	factory
Second	120 & 50	15	15	30	factory and offices
Third	120	15	-	15	factory

TOTAL - AS STATED ABOVE

FIRE DEPARTMENT APPROVAL DATED AUGUST 11, 1960 - (Sprinkler System)

Borough Superintendent

CERTIFICATE WILL BE NULL AND VOID IF ALTERED IN ANY MANNER OR ADDITIONS ARE MADE THERETO.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 54-155M-705777(60) 114

DEPARTMENT OF BUILDINGS

BOROUGH OF Brooklyn, THE CITY OF NEW YORK

ok

No. [illegible]

Date MAR 9 - 1961

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C.26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~ altered ~~existing~~ building—premises located at

237 to 239 Huron Street, north side 125' east of Oakland Street

Block 2524 Lot 50 & 51

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~N.B.~~ or Alt. No.— 2357-1960 Construction classification— Vacant land

Occupancy classification— Parking Lot . Height - - - stories, - - - feet.

Date of completion— const. 3-6-61 . Located in unrestricted Use District.

C Area plumb. 3-1-61 . Height Zone at time of issuance of permit

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
On ground		-	-	-	parking lot for more than five (5) motor ~~vehicles including overnight parking.~~
					TOTAL:- PARKING LOT

Borough Superintendent

CERTIFICATE WILL BE NULL AND VOID IF ALTERED IN ANY MANNER OR ADDITIONS ARE MADE THERETO.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there be any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the discretionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachments into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance; that there are no notices of violations or orders pending in the Department of Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§ 646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 55-2530-7/041 153

DEPARTMENT OF HOUSING AND BUILDINGS

BOROUGH OF BROOKLYN , CITY OF NEW YORK

RBC

No. 107752

Date Jan. 11, 1943

CERTIFICATE OF OCCUPANCY

(Standard form adopted by the Board of Standards and Appeals and issued pursuant to Section 646 of the New York Charter, and Sections C26-181.0 to C26-187.0 inclusive Administrative Code 2.1.3.1. to 2.1.3.7. Building Code.)

This certificate supersedes C. O. No.

To the owner or owners of the building or premises:

THIS CERTIFIES that the ~~new~~ altered ~~former~~ building—premises located at

251/257 Huron Street, North Side, 225' West of Provost St.

Block 2524 Lot 42

, conforms substantially to the approved plans and specifications, and to the requirements of the building code and all other laws and ordinances, and of the rules and regulations of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646F of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~Alteration~~ Alt. 2667/42 Construction classification—Non-fireproof

Occupancy classification—Foundry, Etc. Height 1 & 3 stories, 17 & 35 feet.

Date of completion—Const. 1/8/43 Pl. 1/6/43 Located in Unrestricted Use District.

--- Area --- Height Zone at time of issuance of permit

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED MALE	FEMALE	TOTAL	USE
Cellar	Ground	5	-	5	Boiler Room and Storage
First	120	30	2	32	Foundry, Shipping and Office
Second	120	15	-	15	Machine Shop
Third	120	15	-	15	Pattern Shop

TOTAL: Foundry, Shipping, Office, Machine Shop and Pattern Shop

(Page 1)

Borough Superintendent.

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

Unless an approval for the same has been obtained from the Borough Superintendent, no change or rearrangement in the structural parts of the building, or affecting the light and ventilation of any part thereof, or in the exit facilities, shall be made; no enlargement, whether by extending on any side or by increasing in height shall be made; nor shall the building be moved from one location or position to another; nor shall there by any reduction or diminution of the area of the lot or plot on which the building is located.

The building or any part thereof shall not be used for any purpose other than that for which it is certified.

The superimposed, uniformly distributed loads, or concentrated loads producing the same stresses in the construction in any story shall not exceed the live loads specified on reverse side; the number of persons of either sex in any story shall not exceed that specified when sex is indicated, nor shall the aggregate number of persons in any story exceed the specified total; and the use to which any story may be put shall be restricted to that fixed by this certificate except as specifically stated.

This certificate does not in any way relieve the owner or owners or any other person or persons in possession or control of the building, or any part thereof from obtaining such other permits, licenses or approvals as may be prescribed by law for the uses or purposes for which the building is designed or intended; nor from obtaining the special certificates required for the use and operation of elevators; nor from the installation of fire alarm systems where required by law; nor from complying with any lawful order for additional fire extinguishing appliances under the directionary powers of the fire commissioner; nor from complying with any lawful order issued with the object of maintaining the building in a safe or lawful condition; nor from complying with any authorized direction to remove encroachment into a public highway or other public place, whether attached to or part of the building or not.

If this certificate is marked "Temporary", it is applicable only to those parts of the building indicated on its face, and certifies to the legal use and occupancy of only such parts of the building; it is subject to all the provisions and conditions applying to a final or permanent certificate; it is not applicable to any building under the jurisdiction of the Housing Division unless it is also approved and endorsed by them, and it must be replaced by a full certificate at the date of expiration.

If this certificate is for an existing building, erected prior to March 14, 1916, it has been duly inspected and it has been found to have been occupied or arranged to be occupied prior to March 14, 1916, as noted on the reverse side, and that on information and belief, since that date there has been no alteration or conversion to a use that changed its classification as defined in the Building Code, or that would necessitate compliance with some special requirement or with the State Labor Law or any other law or ordinance, that there are no notices of violations or orders pending in the Department of Housing and Buildings at this time; that Section 646F of the New York City Charter has been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent, and that, so long as the building is not altered, except by permission of the Borough Superintendent, the existing use and occupancy may be continued.

"§.646 F. No certificate of occupancy shall be issued for any building, structure, enclosure, place or premises wherein containers for combustibles, chemicals, explosives, inflammables and other dangerous substances, articles, compounds or mixtures are stored, or wherein automatic or other fire alarm systems or fire extinguishing equipment are required by law to be or are installed, until the fire commissioner has tested and inspected and has certified his approval in writing of the installation of such containers, systems or equipment to the Borough Superintendent of the borough in which the installation has been made. Such approval shall be recorded on the certificate of occupancy."

Additional copies of this certificate will be furnished to persons having an interest in the building or premises, upon payment of a fee of fifty cents per copy.

Form 54-C (Rev. 7/64)–15M-701340(66) 114

DEPARTMENT OF BUILDINGS

ek BOROUGH OF Brooklyn , THE CITY OF NEW YORK

Date JAN - 4 1966 No. 198652

CERTIFICATE OF OCCUPANCY

NO CHANGES OF USE OR OCCUPANCY NOT CONSISTENT WITH THIS CERTIFICATE SHALL BE MADE UNLESS FIRST APPROVED BY THE BOROUGH SUPERINTENDENT

This certificate supersedes C. O. No. 132629

THIS CERTIFIES that the ~~new~~ altered ~~existing~~ building—premises located at 241-7 Huron Street Block 2524 Lot 50, 46

That the zoning lot and premises above referred to are situated, bounded and described as follows:

BEGINNING at a point on the north side of Huron Street distant 125 feet east from the corner formed by the intersection of Huron Street and Nehalmass Boulevard

running thence north 100 feet; thence east 150 feet;

thence south 100 feet; thence west 150 feet;

running thence ____ feet; thence ____ feet;

to the point or place of beginning, conforms substantially to the approved plans and specifications, and to the requirements of the Building Code, the Zoning Resolution and all other laws and ordinances, and of the rules of the Board of Standards and Appeals, applicable to a building of its class and kind at the time the permit was issued; and

CERTIFIES FURTHER that, any provisions of Section 646e of the New York Charter have been complied with as certified by a report of the Fire Commissioner to the Borough Superintendent.

~~New~~ No.— Alt. 1593-1966 Construction classification—class 3 & class 1

Occupancy classification— metal sorting & shipping(Use Group 17) Height 1 stories, 20' & 23 feet

Date of completion— at time of issuance of permit. const. 12-28-67- plumb. 12-27-67 Located in M 1 - 1 Zoning District.

This certificate is issued subject to the limitations hereinafter specified and to the following resolutions of the Board of Standards and Appeals: and The City Planning Commission: (Calendar numbers to be inserted here)

PERMISSIBLE USE AND OCCUPANCY

Off-Street Parking Spaces ____

Off-Street Loading Berths ____

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE
Cellar	on ground	-	boiler room
First	on ground	6	metals sorting and shipping (Use group 17)

TOTAL:- AS STATED ABOVE

Sewage Disposal:
Sanitary Drainage ____ (DOES) (DOES NOT) Discharge Into Either Sanitary or Combined Sewer

Storm Drainage ____ (DOES) (DOES NOT) Discharge Into Either Storm or Combined Sewer

Samuel Pinaker
Borough Superintendent

OFFICE COPY—DEPARTMENT OF BUILDINGS

PERMISSIBLE USE AND OCCUPANCY (continued)

STORY	LIVE LOADS Lbs. per Sq. Ft.	PERSONS ACCOMMODATED	USE

Borough Superintendent

Appendix 7 Interview Documentation

Owner/Representative Questionnaire

1) Current owner of the Site?_____

2) Number of years owned?_____

3) Year of Building Construction?_____

4) Current Usage of the Site?_____

5) Current Occupants?_____

6) Previous Owner?_____

7) Previous Usage of the Site?_____

8) Previous Occupants?_____

9) Any knowledge of Environmental Issues regarding the Site?_____

_____

10) Any knowledge of Environmental Issues regarding the Adjacent Properties?_____

_____

11) Any previous Environmental Investigations performed at the Site?_ _____

If so, describe the investigation and provide documents_____

_____

12) Any Environmental Liens associated with the Site?_____

This form was completed by:

Signature_____Date:_____

Print Name/Title _____ Phone #:_____

Number of years associated with the Subject Property:_____

Appendix 8 Qualifications of Environmental Professionals

CURRICULUM VITAE

PAUL P. STEWART
ADVANCED CLEANUP TECHNOLOGIES, INC.
110 MAIN STREET, SUITE 103
PORT WASHINGTON, NY 11050
BUSINESS: (516)-441-5800 x103

EDUCATION:

Professor	Polytechnic Institute, (NY) Environmental Law and Regulations	1996- 1999
J.D.	Vermont Law School, (VT) Environmental Law	1982
M.S.	Tufts University, (MA) Environmental Health Engineering	1979
B.S.	Boston University, (MA) Environmental Science	1978

PROFESSIONAL HISTORY:

PRESIDENT, ADVANCED CLEANUP TECHNOLOGIES, INC.

Joined the firm in February, 1989 with extensive expertise in the investigation of environmental contamination incidents. Has been employed by industrial facilities, retail petroleum distributors, insurance companies and financial institutions to investigate past and present chemical handling practices and conditions at subject locations.

Mr. Stewart has developed a Forensics department which directs all investigations into the occurrence of contamination and sources of its release. These services are geared towards identifying the nature, extent and causes of environmental contamination. He is also affiliated with Polytechic Institute of New York where he is engaged in joint research into groundwater flow, chemical transport modeling and remediation as applied to major chemical releases.

PROFESSIONAL HISTORY (Continued)

ASSOCIATE ATTORNEY	RIVKIN, RADLER, DUNNE & BAYH EAB Plaza, Uniondale, NY 11556	1985- 1989

A member of the Science/Causation Team and Environmental Practice Group with extensive experience in groundwater investigations and major environmental litigation. He coordinated the development of major scientific and technical issues involved in complex hazardous waste and toxic tort law suits including Agent Orange, Shell and many others.

His responsibilities included the allocation of liabilities and costs for the release of chemicals into the environment and developing appropriate levels of remedial action. He was also responsible for researching and evaluating evidence of property damage and environmental exposure in conjunction with the Real Estate Department, where he developed environmental due diligence procedures for commercial real estate transactions.

His additional responsibilities included investigating companies' chemical handling, transport and disposal practices and impacts on their regulatory requirements. This work involved surveying industrial activities and chemical release incidents at numerous facilities including literature research, public agency records review and the coordination of appropriate soil, soil vapor and ground water investigations. He also made appearances before federal, state and local regulatory agencies and successfully negotiated the resolution of regulatory compliance issues under numerous statutory frameworks.

ASSOCIATE ATTORNEY	ESCHEN & ESCHEN North Broadway, Hicksville, NY	1983- 1985

Responsible for personal injury and property damage trials and depositions. Successfully perfected numerous appellate briefs and issues including negligence, contract and insurance law. Appearance before regulatory and penal tribunals. Applications of land use development and management law.

INTERN EXAMINER	U.S. PATENT & TRADEMARK OFFICE Washington, D.C.	1981

Screened applications for statutory compliance. Prepared legal memoranda in support of official determinations in pending actions.

AFFILIATIONS:
American Chemical Society

American Society of Testing and Materials

CERTIFICATIONS AND LICENSES:

New Jersey Certification in Subsurface Evaluations
Approved ASTM Instructor on Environmental Site Assessments
New York State Restricted Handler Class II
Portable Gas Chromatography Chemist
Licensed to practice law in New York and Florida

SELECT PRESENTATIONS:

The Scene of the Accident: Forensic Engineering in Hazardous Waste Litigation, Purdue University Industrial Waste Symposium, in Indiana, May 10, 1988.

A Case Study of Petroleum Contamination, Environmental Claim Seminar, St. Paul, Minnesota, May 14, 1990.

PUBLICATIONS:

Numerous technical reports and articles on environmental health engineering and science including the following:

Evaluation of an Ecological Habitat in an Urban New England Environment, 1978.

Environmental Impact Analysis, Construction of the Kennedy Memorial Library, 1978.

Pretreatment of Chromium Waste Sludge from Metal Plating Facility, 1979.

Environmental Impact Analysis, Expansion of the Block Island Sewage Treatment Plant, 1979.

Environmental Report, 11th Annual ALI-ABA Conference on Environmental Law, Vermont Law School Forum, 1981.

Official Comments, Final Environmental Impact Statement, Proposed Runaway Extension and Industrial Park Development, Lebanon Municipal Airport, Lebano, New Hamsphire, 1982.

Laboratory Scale Design, Treatment of Wastewater from Soda Manufacturing, 1985.

Development of a Groundwater Evaluation Program, Hazardous Waste and Toxic Torts Law and Strategy, 1985.

The scene of the Accident: Forensic Engineering in Hazardous Waste Litigation, Journal of the Industrial Waste Symposium, Prudue University, 1988.

History of Commercial use of Methyl tert-Butyl Ether in gasoline products, 1990.

PUBLICATIONS (Continued)

A Case Study of Petroleum Contamination, April 16, 1990.

Effect of Bentonite Diversion Wall on the Migration of Wastes at a Hazardous Waste Landfill, Sato, C., A. Protopapas, P. Stewart, June, 1991.

RELATED PROJECT EXPERIENCE:

Beekman, New York

Performance of an environmental services audit of on-going groundwater remediation project.

Bellmore, New York

The investigation of soil and groundwater contamination associated with retail gasoline distribution facilities.

Brockton, Massachusetts

Performance of a soil, soil vapor and groundwater investigation associated with a retail dry cleaning facilities.

Falls Village, Connecticut

The investigation and remediation of soil and groundwater contamination associated with the release of fuel oil from an underground storage tank.

Garden City, New York

The investigation and remediation of chlorinated solvent contamination associated with printing industry wastes.

Pineola, North Carolina

The investigation of soil and groundwater contamination associated with the release of petroleum from a retail gasoline and bulk petroleum distribution facility.

Ridgefield, Connecticut

The investigation and remediation of soil and groundwater contamination associated with the release of fuel oil from an above ground petroleum storage facility.